Available from

NRC/GPO Sales Program

Superintendent of Documents Government Printing Office Washington, D. C. 20402

A year's subscription consists of 12 issues for this publication.

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

Microfiche of single copies are available from NRC/GPO Sales Program Washington, D. C. 20555

Title List of Documents Made Publicly Available

March 1-31, 1984

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



		, ,

CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket Items by Facility Name	χV
Docketed Items	1
Low Level Radwaste Disposal Sites — Docket 27	1
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	8
Domestic Licensing of Special Nuclear Material — Docket 70	418
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions — Docket 71	422
Nondocketed Items	425
10 CFR — Commission Meeting Records	425
ACRS — Advisory Committee on Reactor Safeguards	425
ADVCM — NRC Advisory Committees	428
COMMISSION NRC Commissioners	428
CONTRACT — NRC Contracts and Modifications	430
FOIA — Freedom of Information Act Requests and Releases	434
GEN TECH IS — Generic Technical Issues	463
I&E — Inspection and Enforcement	465
MISC — Public Document Room Miscellaneous	468
NUREG — NUREG Reports and Related Correspondence	469
ORG — Correspondence with Other Organizations	485
PR — Proposed Rule	488
PRM — Petition for Rulemaking	490
PROJ — Projects - Predocket Licensing	490
PT21 — Noncompliance Reports and Related Correspondence	490
QA999 — Quality Assurance Inspections	493
REGGD — Regulatory Guides	498
RES — Research and Technical Assistance Reports	499
REVIEW GROUP — NRC Research Review Groups	499
SECY — Position Papers Before the Commission	500
STATE PROG — State Programs	501
TOPREP — Vendor Reports and Related Correspondence	502
WASH — Regulatory Publications - Pre-Nureg Series	508
WASTE MGT — Nuclear Waste Management	508
XPORTLIC — Export and Import Licenses	511
Personal Author Index	517
Corporate Source Index ,	549
Report Number Index	579
Cross Reference of Enclosures to Principal Documents	581
Appendix A — Definitions of Docket 50 Categories	A-1
Appendix B — Definitions of Nondocketed Categories	B-1

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC) This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:


- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
 - O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
 - P. Operating license stage documents and correspondence
 - Q. Inspection reports, IE Bulletins and correspondence
 - R. Periodic operating reports and related correspondence
 - S. Reportable occurrences. LERs and related correspondence
 - T. Hearing transcripts on non-antitrust matters
 - U. Congressional/executive correspondence
 - V. Licensing operators and related correspondence

- W Decommissioning stage documents and correspondence
- V Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report

The principal elements of the entries in the list are

P Operating license stage documents & correspondence



- 1 NRC/PDR Document category (see Appendix A)
- 2 NRC Accession Number (year, month, day, and sequence number of item).
- 3 Description of information contained in the document.
- 4 Personal author(s) An asterisk in this position indicates that there is no personal author
- 5 Corporate, agency or nonindividual source
- 6. Date of document described
- 7 Recipient of document and NRC or corporate affiliation
- 8 Pages in this document
- 9 The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files
- 10 This three-digit portion of this entry is the number of the frame on which this document starts.
- The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
- 12 If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale, "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are

IOCFR — Commission Meeting Records

ACRS — Advisory Committee on Reactor Safeguards

COMMISSION — NRC Commissioners

CONTRACT — NRC Contracts and Modifications

DISC LOSURE — Financial Disclosure Information

FOIA — Freedom of Information Act Requests and Releases

GEN TECH IS — Generic Technical Issues

I&E - Inspection and Enforcement

MISC — Public Document Room Miscellaneous

NUREG - NUREG Reports and Related Correspondence

ORG — Correspondence with Other Organizations

PR — Proposed Rule

PRM — Petition for Rulemaking

PROJ — Projects—Predocket Licensing

PT21 - Noncomphance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD -- Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP -- NRC Research Review Groups

RM - Rulemakings

SECY — Position Papers Before the Commission

STATE PROG — State Programs

TOPREP -- Vendor Reports and Related Correspondence


WASH - Regulatory Publications-Pre-NUREG Series

WASTE MGT - Nuclear Waste Management

XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



- 1. Nondocketed category
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 6. Corporate, agency or other nonindividual source.
- 7. Contract or financial (FiN) number (if any). If the document has a secondary report number, it will appear following this entry.
- 8. Secondary report number assigned by originator.
- 9. Date of document described.
- 10. NRC organizational recipient.
- 11. Pages in document.
- 12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
- 13. Price for which NRC sells the document.

- 14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files
- 15. This three-digit portion of this entry is the number of the frame on which this document starts

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping inaterials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Rad	lwaste Disposal Sites — Docket 27		40-8585	Wyoming Mineral Corp , Lakewood, CO	6
27-039	Sheffield, IL, US Ecology, Inc	1	40-8586	Kerr-McGee Nuclear Corp , Oklahoma City, OK	6
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc	1	40-8602	Silver King Mines, Inc., Casper, WY	6
27-048	Richland, WA, US Ecology, Inc	1		·	
Domestic Licen	ising of Source Material - Docket 40		40-8647	Kerr-McGee Nuclear Corp , Oklahoma City, OK	6
40-0299	Union Carbide Corp , Grand Junction, CO	1	40-8663	Nuclear Dynamics, Inc , Phoenix, AZ	6
40-0481	American Bearing Co., Indianapolis, IN	2	40-8674	Plateau Resources, Ltd., Grand Junction, CO	6
40-0672	Nuclear Metals, Inc., Concord, MA	2	40-8681	Energy Fuels Nuclear, Inc., Denver, CO	6
40-1162	Western Nuclear, Inc., Jeffrey City, WY	2	40-8684	Western Nuclear, Inc., Lakewood, CO	6
40-1341	Tennessee Valley Authority, Chattanooga, TN	2	40-8698	Plateau Resources, Ltd., Grand Junction, CO	6
40-1478	Spencer Chemical Co., Kansas City, MO	2	40-8727	Kerr-McGee Nuclear Corp , Oklahoma City, OK	7
40-2061	Kerr-McGee Chemical Corp, Oklahoma City, OK	2	40-8745	Ogle Petroleum, Inc., Casper, WY	7
40-2259	Pathfinder Mines Corp., Riverton, WY	3	40-8760	Ediow International Co , Washington, DC	7
40-3392	Allied Chemical Corp , Morristown, NJ	3	40-8768	Kerr-McGee Nuclear Corp , Oklahoma City, OK	7
40-3453	Atlas Minerals, Inc., Denver, CO	3	10.0001		2
40-4492	Federal-American Partners, Riverton, WY	4	40-8781	Teton Exploration Drilling Co, Inc., Casper, WY	7
40-6329	Catholic Univ. of America, Washington, DC	4	40-8783	Uranerz USA, Inc , Casper, WY	7
40-6622	Pathfinder Mines Corp , Shirley Basin, WY	4	40-8786	Uranium Resources, Inc., Richardson, TX	7
40-6659	Getty Oil CoPetrotomics Co., Shirley Basin, WY	4	40-8820	AMAX Environmental Services, Inc., Golden, CO	7
40-6920	Automation Industires, Inc., Phoenixville, PA	4	40-8824	Target Research, Inc., Wharton, NJ	7
40-6940	Kawecki Berylco Industries, Inc.,	5	40-8829	Wyoming Fuel Co., Lakewood, CO	7
10 5155	Boyertown, PA	e	40-8830	Honeywell, Inc , Hopkins, MN	8
40-7455	Whittaker Metals, Los Angeles, CA	5		nsing of Production and Utilization Facilities—	
40-8027	Keri-McGee Nuclear Corp , Oklahoma City, OK	5	Docket 50	Main of Minking Personsh Persons	8
40-8084	Rio Algom Corp., Moab, UT	5	50-2	Univ. of Michigan Research Reactor	8
40-8102	Exxon Co., USA, Houston, TX	5	50-3	Indian Point Station, Unit 1	9
40-8107	Army, Dept. of, Sacramento, CA	5	50-5	Pennsylvania State Univ. Research Reactor	
40-8452	Bear Creek Uranium Co., Casper, WY	5	50-10	Dresden Nuclear Power Station, Unit 1	9
40-8502	Wyoming Mineral Corp., Lakewood, CO	5	50-13	Babcock & Wilcox Co. Critical Facility	10
40-8584	Minerals Exploration Co., Los Angeles, CA	6	50-18	Vallecitos Boiling Water Reactor	10

Docket	Name	Page	Docket	Name	Page
50-20	Massachusetts Institute of Technology Research Reactor	10	50-249	Dresden Nuclear Power Station, Unit 3	36
50-29	Yankee-Rowe Nuclear Power Station	10	50-250	Turkey Point Plant, Unit 3	39
50-30		11	50-251	Turkey Point Plant, Unit 4	41
50-54	Plum Brook Research Reactor Facility Union Carbide Research Reactor	11	50-254	Quad-Cities Station, Unit 1	44
		12	50-255	Palisades Nuclear Plant	46
50-62 50-70	Univ of Virginia Research Reactor General Electric Test Reactor	12	50-259	Browns Ferry Nuclear Power Station, Unit 1	47
50-70	Univ of Utah Research Reactor	12	50-260	Browns Ferry Nuclear Power Station, Unit 2	52
50-72	General Electric Nuclear Test Reactor	12	50-261	H. B. Robinson Plant, Unit 2	55
		12	50-262	Brigham Young Univ. Research Reactor	57
50-83	Univ of Florida Training Reactor		50-263	Monticello Nuclear Generating Plant	58
50-113	Univ. of Arizona Research Reactor	12	50-264	Dow Chemical Co	59
50-123	Univ of Missouri Research Reactor	13	50-265	Quad-Cities Station, Unit 2	59
50-133	Humboldt Bay Power Plant, Unit 3	13	50-266	Point Beach Nuclear Plant, Unit 1	61
50-139 50-142	Univ of Washington Research Reactor	14	50-267	Fort St Vrain Nuclear Generating Station	64
	UCLA Training Reactor	14	50-269	Oconee Nuclear Station, Unit 1	67
50-146 50-155	Saxton Nuclear Experimental Facility	15	50-270	Oconee Nuclear Station, Unit 2	69
	Big Rock Point Nuclear Plant	15	50-271	Vermont Yankee Nuclear Power Station	70
50-156 50-166	Univ of Wisconsin Research Reactor	17	50-272	Salem Nuclear Generating Station, Unit 1	72
50-170	Univ of Maryland Research Reactor	17	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	74
50-170	National Naval Medical Center	17	50-277	Peach Bottom Atomic Power Station, Unit 2	81
	Peach Bottom Atonic Power Station, Unit 1	17	50-278	Peach Bottom Atomic Power Station, Unit 3	83
50-182	Purdue Univ Research Reactor	17	50-280	Surry Power Station, Unit 1	85
50-185	Plum Brook Reactor—Mock-up	17	50-281	Surry Power Station, Unit 2	88
50-201	West Valley Reprocessing Plant	17	50-282	Prairie Island Nuclear Station, Unit 1	91
50-206	San Onofre Nuclear Station, Unit 1	18	50-285	Fort Calhoun Station, Unit 1	93
50-213 50-219	Haddam Neck Plant	21	50-286	Indian Point Station, Unit 3	94
50-219	Oyster Creek Nuclear Power Plant	23	50-287	Oconee Nuclear Station, Unit 3	97
	Nine Mile Point Nuclear Station, Unit 1	26	50-28 9	Three Mile Island Nuclear Station, Unit 1	99
50-223	Univ. of Lowell Research Reactor	28	50-293	Pilgrim Nuclear Power Station, Unit 1	105
50-224	Univ. of California Research Reactor	28	50-295	Zion Nuclear Power Station, Unit 1	108
50-225	RPI Critical Experiment	28	50-296	Browns Ferry Nuclear Power Station, Unit 3	110
50-237	Dresden Nuclear Power Station, Unit 2	28	50-298	Cooper Nuclear Station	114
50-238	Nuclear Ship Savannah	31	50-301	Point Beach Nuclear Plant, Unit 2	116
50-244	Robert Emmet Ginna Nuclear Plant, Unit I	31	50-302	Crystal River Nuclear Plant, Unit 3	118
50-245	Millstone Nuclear Power Station, Unit 1	32	50-304	Zion Nuclear Power Station, Unit 2	120
50-247	Indian Point Station, Unit 2	34		·	

D	ocket	Name	Page	Docket	Name	Page
	50-305	Kewaunee Nuclear Power Plant	123	50-358	William H. Zimmer Nuclear Station, Unit 1	235
	50-306	Prairie Island Nuclear Station, Unit 2	125	50-361	San Onofre Nuclear Station, Unit 2	236
	50-309	Maine Yankee Atomic Power Plant	126	50-362	San Onofre Nuclear Station, Unit 3	239
	50-311	Salem Nuclear Generating Station, Unit 2	128	50-364	Joseph M Farley Nuclear Plant, Unit 2	242
	50-312	Rancho Seco Nuclear Generating Station	130	50-366	Edwin I Hatch Nuclear Plant, Unit 2	245
	50-313	Arkansas Nuclear One, Unit 1	133	50-368	Arkansas Nuclear One, Unit 2	248
	50-315	Donald C. Cook Nuclear Power Plant, Unit 1	136	50-369	William B. McGuire Nuclear Station, Unit 1	251
	50-316	Donald C Cook Nuclear Power Plant, Unit 2	139	50-370	William B. McGuire Nuclear Station, Unit 2	253
	50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	142	50-373	LaSalle County Station, Unit 1	255
	50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	144	50-374	LaSalle County Station, Unit 2	258
	50-320	Three Mile Island Nuclear Station, Unit 2	147	50-382	Waterford Generating Station, Unit 3	261
	50-321	Edwin I. Hatch Nuclear Plant, Unit 1	151	50-383	Waterford Generating Station, Unit 4	266
	50-322	Shoreham Nuclear Power Station	153	50-387	Susquehanna Steam Electric Station, Unit 1	266
	50-323	Diablo Canyon Nuclear Power Plant, Unit 2	164	50-388	Susquehanna Steam Electric Station, Unit 2	269
	50-324	Brunswick Steam Electric Plant, Unit 2	169	50-389	St. Lucie Plant, Unit 2	272
	50-325	Brunswick Steam Electric Plant, Unit 1	172	50-390	Watts Bar Nuclear Plant, Unit 1	275
	50-327	Sequoyah Nuclear Plant, Unit 1	175	50-391	Watts Bar Nuclear Plant, Unit 2	278
	50-328	Sequoyah Nuclear Plant, Unit 2	177	50-395	Virgil C. Summer Nuclear Station, Unit 1	281
	50-329	Midland Plant, Unit 1	179	50-396	Univ. of Virginia Cavalier Reactor	283
	50-330	Midland Plant, Unit 2	186	50-397	WPPSS Nuclear Project, Unit 2	283
	50-331	Duane Arnold Energy Center	193	50-400	Shearon Harris Nuclear Power Plant, Unit I	286
	50-333	James A. Fitzpatrick Nuclear Power Plant	195	50-401	Shearon Harris Nuclear Power Plant, Unit 2	294
	50-334	Beaver Valley Power Station, Unit 1	197	50-402	Shearon Harris Nuclear Power Plant, Unit 3	299
	50-335	St Lucie Plant, Unit 1	199	50-403	Shearon Harris Nuclear Power Plant, Unit 4	300
	50-336	Millstone Nuclear Power Station, Unit 2	202	50-407	Univ. of Utah Research Reactor	300
	50-338	North Anna Power Station, Unit 1	204	50-409	La Crosse Boiling Water Reactor	300
	50-339	North Anna Power Station, Unit 2	207	50-410	Nine Mile Point Nuclear Station, Unit 2	302
	50-341	Enrico Fermi Atomic Power Plant, Unit 2	210	50-412	Beaver Valley Power Station, Unit 2	303
	50-344	Trojan Nuclear Plant	212	50-413	Catawba Nuclear Station, Unit 1	305
	50-346	Davis-Besse Nuclear Power Station, Unit 1	214	50-414	Catawba Nuclear Station, Unit 2	312
	50-348	Joseph M. Farley Nuclear Plant, Unit 1	217	50-416	Grand Gulf Nuclear Station, Unit !	317
	50-352	Limerick Generating Station, Unit 1	221	50-417	Grand Gulf Nuclear Station, Unit 2	323
	50-353	Limerick Generating Station, Unit 2	227	50-423	Millstone Nuclear Power Station, Unit 3	326
	50-354	Hope Creek Nuclear Station, Unit 1	232	50-424	Vogtle Electric Generating Plant	328
	50-355	Hope Creek Nuclear Station, Unit 2	234	50-425	Vogtle Electric Generating Plant	331

Docket	Name	Page	Docket	Name	Page
STN-50-437	Floating Nuclear Plant	333	STN-50-498	South Texas Project, Unit 1	393
50-438	Bellefonte Nuclear Plant, Unit 1	333	STN-50-499	South Texas Project, Unit 2	394
50-439	Beilefonte Nuclear Plant, Unit 2	336	50-500	Davis-Besse Nuclear Power Station, Unit 2	395
50-440	Perry Nuclear Power Plant, Unit 1	338	50-501	Davis-Besse Nuclear Power Station, Unit 3	395
50-441	Perry Nuclear Power Plant, Unit 2	342	STN-50-508	WPPSS Nuclear Project, Unit 3	395
50-443	Seabrook Nuclear Station, Unit 1	346	STN-50-509	WPPSS Nuclear Project, Unit 5	399
50-444	Seabrook Nuclear Station, Unit 2	349	50-513	WPPSS Nuclear Project, Unit 4	401
50-445	Comanche Peak Steam Electric Station, Unit 1	351	50-514	Pebble Springs Nuclear Plant, Unit 1	403
50-446	Comanche Peak Steam Electric Station,	356	50-515	Pebble Springs Nuclear Plant, Unit 2	403
30 440	Unit 2		STN-50-518	Hartsville Nuclear Plant, Unit 1	404
STN-50-447	GESSAR-238	361	STN-50-519	Hartsville Nuclear Plant, Unit 2	404
STN-50-454	Byron Station, Unit 1	361	STN-50-520	Hartsville Nuclear Plant, Unit 3	404
STN-50-455	Byron Station, Unit 2	365	STN-50-521	Hartsville Nuclear Plant, Unit 4	404
STN-50-456	Braidwood Station, Unit 1	368	50-522	Skagit Nuclear Power Project, Unit 1	404
STN-50-457	Braidwood Station, Unit 2	370	50-523	Skagit Nuclear Power Project, Unit 2	405
50-458	River Bend Station, Unit 1	373	STN-50-528	Palo Verde Nuclear Station, Unit 1	406
50-459	River Bend Station, Unit 2	376	STN-50-529	Palo Verde Nuclear Station, Unit 2	409
50-460	WPPSS Nuclear Project, Unit 1	378	STN-50-530	Palo Verde Nuclear Station, Unit 3	412
50-461	Clinton Power Station, Unit 1	381	50-537	Clinch River Breeder Reactor	415
50-462	Clinton Power Station, Unit 2	383	50-538	Memphis State Univ. Research Reactor	415
50-463	Fulton Generating Station, Unit 1	383	STN-50-546	Marble Hill Nuclear Station, Unit I	415
50-464	Fulton Generating Station, Unit 2	384	STN-50-547	Marble Hill Nuclear Station, Unit 2	416
50-466	Allens Creek Nuclear Station, Unit 1	384	STN-50-553	Phipps Bend Nuclear Station, Unit 1	417
50-467	Allens Creek Nuclear Station, Unit 2	384	STN-50-554	Phipps Bend Nuclear Station, Unit 2	417
STN-50-470	CESSAR System 80	384	STN-50-556	Bluck Fox Station, Unit 1	417
50-471	Pilgrim Nuclear Power Station, Unit 2	384	STN-50-557	Black Fox Station, Unit 2	417
STN-50-482	Wolf Creek Generating Station	384	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	417
STN-50-483	Callaway Plant, Unit I	388	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	418
STN-50-486	Callaway Plant, Unit 2	392	Donaestic Licen	sing of Special Nuclear Material — Docket 70	
STN-50-488	Perkins Nuclear Station, Unit 1	392	70-0027	Babcock & Wilcox Co., Lynchburg, VA	418
STN-50-489	Perkins Nuclear Station, Unit 2	392	70-0036	Combustion Engineering, Inc., Windsor, CT	418
STN-50-490	Perkins Nuclear Station, Unit 3	392	70-0143	Nuclear Fuel Services, Inc , Erwin, TN	418
STN-50-493	Cherokee Nuclear Station, Unit 3	392	70-0152	Purdue Univ., West Lafayette, IN	419
50-496	Montague Nuclear Power Station, Unit 1	392	70-0190	Catholic Univ. of America, Washington, DC	419
50-497	Montague Nuclear Power Station, Unit 2	392	70-0371	UNC Naval Products, Inc., Uncasville, CT	419

Docket	Name	Page	Docket	Name	Page
70-0378	Army, Dept of, Adelphi, MD	419		Radioactive Material for Transport and	
70-0398	Commerce, Dept of, Washington, DC	419		ion of Radioactive Material Under Certain — Docket 71	
70-0474	Upsala College, East Orange, NJ	419	71-0511	Deltak Corp	422
70-0553	Army, Dept of, Sacramento, CA	420	71-0513	Edlow International Co	422
70-0687	Union Carbide Corp , Tuxedo, NY	420	71-0514	North American Inspection	422
70-0712	Kerr-McGee Nuclear Corp, Oklahoma City, OK	420	71-5450	Model RCC -1, -2, -3, -4, Westinghouse Electric Corp	422
70-0734	GA Technologies, Inc., San Diego, CA	420	71-6206	Model B, Babcock & Wilcox Co	422
70-0824	Babcock & Wilcox Co , Lynchburg, VA	420	71-6406	Model None, Energy, Dept of	422
70-0920	Rensselaer Polytechnic Institute, Troy, NY	420	71-6601	Model, CNS 8-120, Chem-Nuclear	422
70-0925	Kerr-McGee Nuclear Corp., Oklahoma City, OK	420	71-9001	Systems, Inc. Model IF-300, General Electric Co	422
70-0984	Battelle Memorial Institute, Richland, WA	420	71-9009	Model: FL 10-1, General Electric Co.	423
70-1100	Combustion Engineering, Inc , Windsor, CT	420	71-9027	Model 741 & 741E, Technical Operations,	423
70-1113	General Electric Co , Wilmington, NC	421	m. 0044	Inc.	100
70-1143	Westinghouse Electric Corp , Pittsburgh, PA	421	71-9036	Model: C-1, Source Production & Equipment Co, Inc.	423
70-1151	Westinghouse Electric Corp., Pittsburgh, PA	421	71-9071	Model: AP-101, ANEFCO, Inc	423
70-1193	Kerr-McGee Nuclear Corp., Oklahoma City, OK	421	71-9079	Model: HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp	423
70-1201	Babcock & Wilcox Co., Lynchburg, VA	421	71-9080	Model: HN-600, NUPAC 7-100 & CNS	423
70-1257	Exxon Nuclear Co , Inc., Richland, WA	421		7-100, Hittman Nuclear & Development Corp	
70-1311	Air Force, Dept of, USAF, Academy, CO	421	71-9108	Model CNS 6-75, Chem-Nuclear Systems,	423
70-1359	IRT Corp., San Diego, CA	421	71-9134	Inc Model ETR, Exxon Nuclear Idaho Co	423
70-1621	Duquesne Light Co , Pittsburgh, PA	421		•	
70-1717	Norwalk Hospital, Norwalk, CT	422	71-9160	Model: 20-VS & 40-VS, Gulf Nuclear, Inc	423 423
70-2199	Veterans Administration Medical Center,	422	71-9161	Model R, Gulf Nuclear, Inc. Model, GNM-20, Gulf Nuclear, Inc.	423
	Washington, DC	100	71-9162	,	
70-2946	Louisiana Power & Light Co, New Orleans, LA	422	71-9175	Model CNS6-80B Nuclear Packaging, Inc	423
70-2955	Edlow International Co., Washington, DC	422	71-9190	Model: CASTOR V, Gesellschaft Fuer Nuklear Service, MBH	423
70-2988	Philadelphia Electric Co , Philadelphia, PA	422			

,
•
1
!
:
1
1

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites — Docket 27			Minerals Exploration Co, Los Angeles, CA	40-8584	6
Barnwell, SC, Chem-Nuclear Systems, Inc	27-047	1	Nuclear Dynamics, Inc., Phoenix, AZ	40-8663	6
Richland, WA, US Ecology, Inc	27-048	1	Nuclear Metals, Inc., Concord, MA	40-0672	2
Sheffield, IL, U.S Ecology, Inc	27-039	1	Ogle Petroleum, Inc , Casper, WY	40-8745	7
Domestic Licensing of Source Material — Dock	set 40		Pathfinder Mines Corp , Riverton, WY	40-2259	3
Allied Chemical Corp , Morristown, NJ	40-3392	3	Pathfinder Mines Corp , Shirley Basin, WY	40-6622	4
AMAX Environmental Services, Inc., Golden, CO	40-8820	7	Plateau Resources, Ltd , Grand Junction, CO	40-8674	6
American Bearing Co, Indianapolis, IN	40-0481	2	Plateau Resources, Ltd.,	40-8698	6
Army, Dept. of, Sacramento, CA	40-8107	5	Grand Junction, CO	10,0001	
Atlas Minerals, Inc., Denver, CO	40-3453	3	Rio Algom Corp., Moab, UT	40-8084	5
Automation Industries, Inc., Phoenixville, PA	40-6920	4	Silver King Mines, Inc., Casper, WY	40-8602	6
Bear Creek Uranium Co., Casper, WY	40-8452	5	Spencer Chemical Co., Kansas City, MO	40-1478	2
Catholic Univ. of America, Washington, DC	40-6329	4	Target Research, Inc , Wharton, NJ	40-8824	7
Edlow International Co., Washington, DC	40-8760	7	Tennessee Valley Authority, Chattanooga, TN	40-1341	2
Energy Fuels Nuclear, Inc., Denver, CO	40-8681	6	Teton Exploration Drilling Co., Inc., Casper, WY	40-8781	7
Exxon Co., USA, Houston, TX	40-8102	5	Union Carbide Corp , Grand Junction, CO	40-0299	1
Federal-American Partners, Riverton, WY	40-4492	4	Uranerz USA, Inc., Casper, WY	40-8783	7
Getty Oil CoPetrotomics Co , Shirley Basin, WY	40-6659	4	Uranium Resources, Inc., Richardson, TX	40-8786	7
Honeywell, Inc., Hopkins, MN	40-8830	8	Western Nuclear, Inc., Jeffrey City, WY	40-1162	2
Kawecki Berylco Industries, Inc.,	40-6940	5	Western Nuclear, Inc., Lakewood, CO	40-8684	6
Boyertown, PA			Whittaker Metals, Los Angeles, CA	40-7455	5
Kerr-McGee Chemical Corp., Oklahoma City, OK	40-2061	2	Wyoming Fuel Co., Lakewood, CO	40-8829	7
Kerr-McGee Nuclear Corp.,	40-8027	5	Wyoming Mineral Corp , Lakewood, CO	40-8502	5
Oklahoma City, OK	10.0027		Wyoming Mineral Corp., Lakewood, CO	40-8585	6
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8586	6	Domestic Licensing of Production and Utilizati Docket 50	ion Facilities —	
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8647	6	Allens Creek Nuclear Station, Unit 1	50-466	384
Kerr-McGee Nuclear Corp.,	40-8727	7	Allens Creek Nuclear Station, Unit 2	50-467	384
Oklahoma City, OK	70-0141	,	Arkansas Nuclear One, Unit 1	50-313	133
Kerr-McGee Nuclear Corp , Oklahoma City, OK	40-8768	7	Arkansas Nuclear One, Unit 2	50-368	248

Name	Docket	Page	Name	Docket	Page
Babcock & Wilcox Co., Critical Facility	50-13	10	Davis-Besse Nuclear Power Station, Unit 2	50-500	395
Beaver Valley Power Station, Unit 1	50-334	197	Davis-Besse Nuclear Power Station, Unit 3	50-501	395
Beaver Valley Power Station, Unit 2	50-412	303	Diablo Canyon Nuclear Power Plant, Unit 1	50-275	74
Bellefonte Nuclear Plant, Unit 1	50-438	333	Diablo Canyon Nuclear Power Plant, Unit 2	50-323	164
Bellefonte Nuclear Plant, Unit 2	50-439	336	Donald C Cook Nuclear Power Plant, Unit 1	50-315	136
Big Rock Point Nuclear Plant	50-155	15	Donald C. Cook Nuclear Power Plant, Unit 2	5 0-316	139
Black Fox Station, Unit 1	STN-50-556	417	Dow Chemical Co.	50-264	59
Black Fox Station, Unit 2	STN-50-557	417	Dresden Nuclear Power Station, Unit 1	50-10	9
Braidwood Station, Unit 1	STN-50-456	368	Dresden Nuclear Power Station, Unit 2	50-237	28
Braidwood Station, Unit 2	STN-50-457	370	Dresden Nuclear Power Station, Unit 3	50-249	36
Brigham Young Univ. Research Reactor	50-262	57	Duane Arnold Energy Center	50-331	193
Browns Ferry Nuclear Power Station, Unit 1	50-259	47	Edwin I Hatch Nuclear Plant, Unit 1	50-321	151
Browns Ferry Nuclear Power Station, Unit 2	50-260	52	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	245
Browns Ferry Nuclear Power Station, Unit 3	50-296	110	Enrico Fermi Atomic Power Plant, Unit 2	50-341	210
Brunswick Steam Electric Plant, Unit 1	50-325	172	Floating Nuclear Plant	STN-50-437	333
Brunswick Steam Electric Plant, Unit 2	50-324	169	Fort Calhoun Station, Unit 1	50-285	93
Byron Station, Unit 1	STN-50-454	361	Fort St. Vrain Nuclear Generating Station	50-267	64
Byron Station, Unit 2	STN-50-455	365	Fulton Generating Station, Unit 1	50-463	383
Callaway Plant, Unit 1	STN-50-483	388	Fulton Generating Station, Unit 2	50-464	384
Callaway Plant, Unit 2	STN-50-486	392	General Electric Nuclear Test Reactor	50-73	12
Calvert Cliffs Nuclear Power Plant, Unit I	50-317	142	General Electric Test Reactor	50-70	12
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	144	GESSAR-238	STN-50-447	361
Catawba Nuclear Station, Unit 1	50-413	305	Grand Gulf Nuclear Station, Unit 1	50-416	317
Catawba Nuclear Station, Unit 2	50-414	312	Grand Gulf Nuclear Station, Unit 2	50-417	323
CESSAR System 80	STN-50-470	384	H. B. Robinson Plant, Unit 2	50-261	55
Cherokee Nuclear Station, Unit 3	STN-50-493	392	Haddam Neck Plant	50-213	21
Clinch River Breeder Reactor	50-537	415	Hartsville Nuclear Plant, Unit 1	STN-50-518	404
Clinton Power Station, Unit 1	50-461	381	Hartsville Nuclear Plant, Unit 2	STN-50-519	404
Clinton Power Station, Unit 2	50-462	383	Hartsville Nuclear Plant, Unit 3	STN-50-520	404
Comanche Peak Steam Electric Station, Unit 1	50-445	351	Hartsville Nuclear Plant, Unit 4	STN-50-521	404
Comanche Penk Steam Electric Station,	50-446	356	Hope Creek Nuclear Station, Unit 1	50-354	232
Unit 2			Hope Creek Nuclear Station, Unit 2	50-355	234
Cooper Nuclear Station	50-298	114	Humboldt Bay Power Plant, Unit 3	50-133	13
Crystal River Nuclear Plant, Unit 3	50-302	118	Indian Point Station, Unit 1	50-3	8
Davis-Besse Nuclear Power Station, Unit 1	50-346	214	Indian Point Station, Unit 2	50-247	34

Name	Docket	Page	Name	Docket	Page
Indian Point Station, Unit 3	50-286	94	Palo Verde Nuclear Station, Unit 2	STN-50-529	409
James A Fitzpatrick Nuclear Power Plant	50-333	195	Palo Verde Nuclear Station, Unit 3	STN-50-530	412
Joseph M. Farley Nuclear Plant, Unit 1	50-348	217	Peach Bottom Atomic Power Station, Unit 1	50-171	17
Joseph M. Farley Nuclear Plant, Unit 2	50-364	242	Peach Bottom Atomic Power Station, Unit 2	50-277	81
Kewaunee Nuclear Power Plant	50-305	123	Peach Bottom Atomic Power Station, Unit 3	50-278	83
La Crosse Boiling Water Reactor	50-409	300	Pebble Springs Nuclear Plant, Unit 1	50-514	403
LaSalle County Station, Unit 1	50-373	255	Pebble Springs Nuclear Plant, Unit 2	50-515	403
LaSalle County Station, Unit 2	50-374	258	Pennsylvania State Univ. Research Reactor	50-5	9
Limerick Generating Station, Unit 1	50-352	221	Perkins Nuclear Station, Unit 1	STN-50-488	392
Limerick Generating Station, Unit 2	50-353	227	Perkins Nuclear Station, Unit 2	STN-50-489	392
Maine Yankee Atomic Power Plant	50-309	126	Perkins Nuclear Station, Unit 3	STN-50-490	392
Marble Hill Nuclear Station, Unit 1	STN-50-546	415	Perry Nuclear Power Plant, Unit 1	50-440	338
Marble Hill Nuclear Station, Unit 2	STN-50-547	416	Perry Nuclear Power Plant, Unit 2	50-441	342
Massachusetts Institute of Technology Research Reactor	50-20	10	Phipps Bend Nuclear Station, Unit 1	STN-50-553	417
Memphis State Univ. Research Reactor	50-538	415	Phipps Bend Nuclear Station, Unit 2	STN-50-554	417
Midland Plant, Unit 1	50-329	179	Pilgrim Nuclear Power Station, Unit I	50-293	105
Midland Plant, Unit 2	50-330	186	Pilgrim Nuclear Power Station, Unit 2	50-471	384
Millstone Nuclear Power Station, Unit 1	50-245	32	Plum Brook Reactor-Mock-Up	50-185	17
Millstone Nuclear Power Station, Unit 2	50-336	202	Plum Brook Research Reactor Facility	50-30	11
Millstone Nuclear Power Station, Unit 3	50-423	326	Point Beach Nuclear Plant, Unit 1	50-266	61
Montague Nuclear Power Station, Unit 1	50-496	392	Point Beach Nuclear Plant, Unit 2	50-301	116
Montague Nuclear Power Station, Unit 2	50-497	392	Prairie Island Nuclear Station, Unit 1	50-282	91
Monticello Nuclear Generating Plant	50-263	58	Prairie Island Nuclear Station, Unit 2	50-306	125
National Naval Medical Center	50-170	17	Purdue Univ. Research Reactor	50-182	17
Nine Mile Point Nuclear Station, Unit 1	50-220	26	Quad-Cities Station, Unit 1	50-254	44
Nine Mile Point Nuclear Station, Unit 2	50-410	302	Quad-Cities Station, Unit 2	50-265	59
North Anna Power Station, Unit 1	50-338	204	Rancho Seco Nuclear Generating Station	50-312	130
North Anna Power Station, Unit 2	50-339	207	River Bend Station, Unit 1	50-458	373
Nuclear Ship Savannah	50-238	31	River Bend Station, Unit 2	50-459	376
Oconee Nuclear Station, Unit 1	50-269	67	Robert Eminet Ginna Nuclear Plant, Unit 1	50-244	31
Oconee Nuclear Station, Unit 2	50-270	69	RPI Critical Experiment	50-225	28
Oconee Nuclear Station, Unit 3	50-287	97	Salem Nuclear Generating Station, Unit 1	50-272	72
Oyster Creek Nuclear Power Plant	50-219	23	Salem Nuclear Generating Station, Unit 2	50-311	128
Palisades Nuclear Plant	50-255	46	San Onofre Nuclear Station, Unit 1	50-206	18
Palo Verde Nuclear Station, Unit 1	STN-50-528	406	San Onofre Nuclear Station, Unit 2	50-361	236

Name	Docket	Page	Name	Docket	Page
San Onotre Nuclear Station, Unit 3	50-362	239	Univ of Utah Research Reactor	50-407	300
Saxton Nuclear Experimental Facility	50-146	15	Univ of Utah Research Reactor	50-72	12
Seabrook Nuclear Station, Unit 1	50-443	346	Univ of Virginia Cavalier Reactor	50-396	283
Seabrook Nuclear Station, Unit 2	50-444	349	Univ of Virginia Research Reactor	50-62	12
Sequoyah Nuclear Plant, Unit 1	50-327	175	Univ of Washington Research Reactor	50-139	14
Sequoyah Nuclear Plant, Unit 2	50-328	177	Univ. of Wisconsin Research Reactor	50-156	17
Shearon Harris Nuclear Power Plant, Unit 1	50-400	286	Vallecitos Boiling Water Reactor	50-18	10
Shearon Harrts Nuclear Power Plant, Unit 2	50-401	294	Vermont Yankee Nuclear Power Station	50-271	70
Shearon Harris Nuclear Power Plant, Unit 3	50-402	299	Virgil C Summer Nuclear Station, Unit 1	50-395	281
Shearon Harris Nuclear Power Plant, Unit 4	50-403	300	Vogtle Electric Generating Plant	50-424	328
Shoreham Nuclear Power Station	50-322	153	Vogtle Electric Generating Plant	50-425	331
Skagit Nuclear Power Project, Unit 1	50-522	404	Waterford Generating Station, Unit 3	50-382	261
Skagit Nuclear Power Project, Unit 2	50-523	405	Waterford Generating Station, Unit 4	50-383	266
South Texas Project, Unit 1	STN-50-498	393	Watts Bar Nuclear Plant, Unit 1	50-390	275
South Texas Project, Unit 2	STN-50-499	394	Watts Bar Nuclear Plant, Unit 2	50-391	278
St Lucie Plant, Umt 1	50-335	199	West Valley Reprocessing Plant	50-201	17
St Lucie Plant, Unit 2	50-389	272	William B. McGuire Nuclear Station, Unit 1	50-369	251
Surry Power Station, Unit 1	50-280	85	William B McGuire Nuclear Station, Unit 2	50-370	253
Surry Power Station, Unit 2	50-281	88	William H. Zimmer Nuclear Station, Unit 1	50-358	235
Susquehanna Steam Electric Station, Unit 1	50-387	266	Wolf Creek Generating Station	STN-50-482	384
Susquehanna Steam Electric Station, Unit 2	50-388	269	WPPSS Nuclear Project, Unit 1	50-460	378
Three Mile Island Nuclear Station, Unit 1	50-289	99	WPPSS Nuclear Project, Unit 2	50-397	283
Three Mile Island Nuclear Station, Unit 2	50-320	147	WPPSS Nuclear Project, Unit 3	STN-50-508	395
Trojan Nuclear Plant	50-344	212	WPPSS Nuclear Project, Unit 4	50-513	401
Turkey Point Plant, Unit 3	50-250	39	WPPSS Nuclear Project, Unit 5	STN-50-509	399
Turkey Point Plant, Unit 4	50-251	41	Yankee-Rowe Nuclear Power Station	50-29	10
UCLA Training Reactor	50-142	14	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	417
Union Carbide Research Reactor	50-54	11	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	418
Univ. of Arizona Research Reactor	50-113	12	Zion Nuclear Power Station, Unit 1	50-295	108
Univ of California Research Reactor	50-224	28	Zion Nuclear Power Station, Unit 2	50-304	120
Univ of Florida Training Reactor	50-83	12	Domestic Licensing of Special Nuclear Materi	al - Docket 70	
Univ. of Lowell Research Reactor	50-223	28	Air Force, Dept. of, USAF Academy, CO	70-1311	421
Univ of Maryland Research Reactor	50-166	17	Army, Dept of, Adelphi, MD	70-0378	419
Umv. of Michigan Research Reactor	50-2	8	Army, Dept. of, Sacramento, CA	70-0553	420
Univ of Missouri Research Reactor	50-123	13	Babcock & Wilcox Co., Lynchburg, VA	70-1201	421

Name	Docket	Page	Name	Docket	Page
Babcock & Wilcox Co , Lynchburg, VA	70-0027	418	Westinghouse Electric Corp , Pittsburgh, PA	70-1151	421
Babcock & Wilcox Co , Lynchburg, VA	70-0824	420	Packaging of Radioactive Material for Transpo		
Battelle Memorial Institute, Richland, WA	70-0984	420	Transportation of Radioactive Material Und Conditions — Docket 71	er Certain	
Catholic Univ of America, Washington, DC	70-0190	419	Deltak Corp	71-0511	_422
Combustion Engineering, Inc., Windsor, CT	70-0036	418	Edlow International Co	71-0513	422
Combustion Engineering, Inc., Windsor, CT	70-1100	420	Model. 20-VS & 40-VS, Gulf Nuclear, Inc	71-9160	423
Commerce, Dept of, Washington, DC	70-0398	419	Model 741 & 741E, Technical Operations, Inc.	71-9027	423
Duquesne Light Co, Pittsburgh, PA	70-1621	421	Model: AP-101, ANEFCO, Inc	71-9071	423 422
Edlow International Co., Washington, DC	70-2955	422		71-6206	
Exxon Nuclear Co, Inc, Richland, WA	70-1257	421	Model B, Babcock & Wilcox Co.		
GA Technologies, Inc., San Diego, CA	70-0734	420	Model: C-1, Source Production & Equipment Co, Inc	71-9036	423
General Electric Co, Wilmington, NC	70-1113	421	Model. CASTOR V, Gesellschaft Fuer Nuklear Service, MBH	71-9190	423
IRT Corp., San Diego, CA	70-1359	421	Model CNS 6-75, Chem-Nuclear Systems,	71-9108	423
Kerr-McGee Nuclear Corp , Oklahoma City, OK	70-1193	421	Inc		
Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-0712	420	Model. CNS 8-120, Chem-Nuclear Systems, Inc	71-6601	422
Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-0925	420	Model CNS6-80B, Nuclear Packaging, Inc Model ETR, Exxon Nuclear Idaho Co.	71-9175 71-9134	423 423
Louisiana Power & Light Co.,	70-2946	422	Model. FL 10-1, General Electric Co	71-9009	423
New Orleans, LA			Model GNM-20, Gulf Nuclear, Inc.	71-9162	423
Norwalk Hospital, Norwalk, CT	70-1717	422	Model HN-100, Series 2 & 2A, Hittman	71-9079	423
Nuclear Fuel Services, Inc., Erwin, TN	70-0143	418	Nuclear & Development Corp.		
Philadelphia Electric Co., Philadelphia, PA	70-2988	422	Model: HN-600, NUPAC 7-100 & CNS 7-100, Hutman Nuclear & Development	71-9080	423
Purdue Univ., West Lafayette, IN	70-0152	419	Corp		
Rensselaer Polytechnic Institute, Troy, NY	70-0920	420	Model: IF-300, General Electric Co	71-9001	422
UNC Naval Products, Inc., Uncasville, CT	70-0371	419	Model: None, Energy, Dept. of	71-6406	422
Union Carbide Corp., Tuxedo, NY	70-0687	420	Model:R, Gulf Nuclear, Inc	71-9161	423
Upsala College, East Orange, NJ	70-0474	419	Model. RCC -1, -2, -3, -4, Westinghouse	71-5450	422
Veterans Administration Medical Center, Washington, DC	70-2199	422	Electric Corp North American Inspection	71-0514	422
Westinghouse Electric Corp., Pittsburgh, PA	70-1143	421			

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, U B ECDLOGY, INC

- B403010344 Requests correction in distribution list to reflect J8 Goodie as assistant atty general GDODIE.J 8 Illinois. State of 84/02/10 Division of Waste Management. 1p 22449 353
- 8403160077 Trip rept of attendence at Sheffield Tritium Migration Study Steering Committee 840119 meeting re fiscal errangements, groundwater tracer study temp surveys & addl data needs GDDDE.D. Geotechnical Branch (Post 831001) BHAFFNER, J A Low-Level Waste & Uranium Recovery Projects Branch 84/02/21 HIGOINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch KNAPP.M. R Geotechnical Branch (Post 831001) 2pp 22662 284
- B403200317 Forwards agenda for 840228-29 technical meetings at Bpringfield. IL to review existing monitoring programs & possible monitoring program after site closure LASH, T R Illinois, State of 84/02/21 Illinois, State of 3pp. 22709-164.
- 8403070380 Notification of contract execution, Mod 5, to "Evaluation of Locations & Rates of Groundwater Discharge from Sheffield Low level Waste Disposal Facility " Contractor USOS PAGE: M Technical Assistance Contracts Branch NRC-02-80-069 84/03/01. DAVIS, J Office of Nuclear Material Bafety & Safeguards, Director GOODE, D J NRC No Detailed Affiliation Given 1p 22567,041
- --8403070383 Mod 3.changing name of project officer, to "Evaluation of Locations & Rates of Groundwater Discharge from Sheffield Low Level Maste Disposal Facility " " Interior, Dept of Geological Burvey SMITH, P Division of Contracts NRC-02-80-069, 84/03/01, 1p 22567 042.
- 8403220218 Informs of establishment of task working group to formulate alternative strategies for transfer of Bhaffield low level waste disposal facility to DDE Response requested by 840308 as to assignment of staff representatives.

 BROWNING, R. E. Division of Waste Management 84/03/09 KNAPP, M Geotychnical Branch (Post 831001) RUNTING, J Division of Waste Management. HIOGINBOTHAM.L. Low-Level Waste & Uranium Recovery Projects Branch 2pp 22721,357

DOCKET 27-047 BARNWELL, BC, CHEM-NUCLEAR SYSTEMS, INC.

8403130316 Forwids summary, in grams, of SNM disposed of at site during CVB3 under License 12-13536-01 BNM amounted to 175,104 37 g BTILL, J. Chem-Nuclear Bystems, Inc 84/02/28 Division of Waste Management. 2pp. 22649:307.

DOCKET 27-040 RICHLAND, HA, U. B. ECOLOGY, INC

- 8403020377 Forwards summary of technical update meeting on 840119 in USQB ofcs in Urbana, IL re tritium migration investigation at Sheffield low level waste disposal site.

 @AYNOR, R. U. B. Ecology, Inc. (formerly Nuclear Engineering, Inc.)

 84/02/13 U. B. Ecology, Inc. (formerly Nuclear Engineering, Inc.).

 3pp. 22492.187
- 8403010341 Forwards monthly BNM receipt & burial rept for Jan 1984 & rept of isotopic activity as required by State of MA W/o encis.

 WRIGHT, B. V. U. B Ecology, Inc. (formerly Nuclear Engineering, Inc.)
 84/02/14. BRDWNINO, B. Low Level Wasta Licensing Branch ip 22449:304.

- 8403010349 Requests specific approval for one-time disposal of 5 Ci Pu-238 neutron source Info re source described in attached 831011 ltr WALLER:W K U S Ecology, Inc (formerly Nuclear Engineering, Inc.) 84702714 SCHAFFNER, J NRC - No Detailed Affiliation Given 4pp 20449 388
- 8403150317 Forwards FR notice of issuance & negative declaration on license amend re SNM disposal for FR publication H1001NB0THAM.L Low-Level Waste & Uranium Recovery Projects Branch 84/02/24 FELTON.J M Division of Rules and Records App 22649 303
- 8403150283 Forwards Amend 4 to License 16-19204-01 Amend authorizes receipt & disposal of BNM at US Ecology. Inc low level radwaste burial facility in Hanford. HA HIGGINBOTHAM. L. Low Level Waste Licensing Branch 84/02/27. SCOVILLE, J. J. U. S. Ecology, Inc. (formerly Nuclear Engineering, Inc.) 2pp 22662 001
- --8403130201 Amend 4 to Matl/Byproduct License 16-19204-01, reflecting wasts manifest, waste form & classification requirements contained in 10CFR61 & 20 311 HIGGINEOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch 84/02/16 25pp 22662 003
- 8403i60094 Advises that App A of SNM license unchanged in order to maintain consistency w/App A of State of WA license, per Dec 1983 telcon re inconsistent sole-use vehicle limits & removable contamination limits
 SHAFFNER, J A Low-Level Waste & Uranium Recovery Projects Branch 84/02/27 THOMAS, B Region 5, Office of Director Ip. 22662 27
- B403220235 Responds to B40214 1tr requesting one-time approval of disposal of 5 Ci Pu-238 neutron source NRC needs data necessary to make independent determination of no significant environ impact due to disposal of package BHAFFNER.J A Lou-Level Waste & Uranium Recovery Projects Branch B4/03/05 WALLER.K U S Ecology, Inc (formerly Nuclear Engineering, Inc.) 2pp 22719 357

DOMESTIC LICENSING OF SOURCE MATERIAL

- DOCKET 40~0299 UNION CARBIDE CORP . GRAND JUNCTION, CO
- 8403010012 Requests reconsideration of classification of 830810 submittal to License SUA-648 re testing clay cap & cover math for inactive tailings area as minor amend Submittal not request for amend LYONS, J. Union Carbide Corp 83/08/16 PETTINGILL, H.A. Uranium Recovery Field Office ip 82479 340
- 8403:50284 Water level evaluation rept for Jan 1984 Production from pumphack well improved compared to Dec.but remains below vol required for reversal of hydraulic gradient W/84013: ltr LYONS.J L Union Carbide Corp 84/01/31 PETTINGILL.H Uranium Recovery Field Office 17pp 22448 227
- B403i30210 Advises that review of expansion application & periodic revs temporarily suspended pending successful resolution of A-9 sespage problem ERICKBONJ Wyoning, State of 84/02/11 LYONS,P J Union Carbide Corp 2pp 22649.050
- 8403070266 Forwards payment for Enforcement Action 83-108 dtd 840210 NRC findings disputed SHORTRIDGE,E W. Union Carbide Corp 84/02/28. Director's Office. Office of Inspection and Enforcement 2pp 22547:316

- DUCKET 40-0481 AMERICAN BEARING CO . INDIANAPOLIS. IN
- 8403060490 Forwards Oak Ridge Associated Univs final rept on NUSCOURT FORWARDS USE RINGS RASSOCIATED ONLYS FINDS FEP decontamination of American Bearing Corp facilities in Indianapolis. IN M/o encl CROM-W T Uranium Fuel Licensing Branch 84/02/27 Licensing Branch 1p 22552 209 Uranium Fuel
- DOCKET 40-0672 NUCLEAR METALS. INC . CONCORD. MA
- 8403030136 Ack receipt of 840115 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-0672/83-08 MARTIN T T Division of Engineering & Technical Programs 64/02/24 VUNDACO,F J Nuclear Metals, Inc 1p 22488 iii
- --8403050144 Responds to NRC 830805 ltr re ltem 7 listed in Confirmatory Action Ltr 83-08 Descriptions of listed programs submitted for NRC review Addl info forwarded to Mati Licensing Branch, Div of Fuel Cycle & Matl Safety VUMBACD.F J Nuclear Metals, Inc 84/01/15 MARTIN.T T Division of Engineering & Jechnical Programs 2pp 22488 i12
- --8403050150 Forwards, for review, info for inclusion into renewal application for License SMB-179 based on request from Region 1 & documented in 830805 Confirmatory Action Ltr 83-08 VUMSACO,F J Nuclear Metals. Inc 8401715 WANG,J C Division of Fuel Cycle & Material Safety 55pp 22488 114
- --8403050156 "Rept of In Vivo Counting for Nuclear Metals, Inc " Work parformed on GEO/18-22 GUEHRING, J S Helgeson Nuclear Services, Inc 83/10/05 53pp
- 8403220090 Ack receipt of 840217 ltr informing NRC of steps taken to correct violations noted in IE insp MARIIN.T T Division of Engineering & Technical Programs 84/03/09 TUFFIN.N B Nuclear Netais. Inc \$p 22716 298
- --8403220092 Responds to NRC 840117 itr re violations noted in 1E insp Corrective actions radiological work audit program & format VUMBACO,F J Nuclear Metals, Inc 84/02/17 MARTIN,T T Division of Engineering & Tachnical Programs 12pp 22716 299
- DOCKET 40-1162 WESTERN NUCLEAR, INC , JEFFREY CITY, WY
- 8403200343 Submits review of First Second & Third Quarter 1983 water quality sampling monitoring for Eglit Rock Mill Movement of contaminated waters datected KDNHINSHI, & R. FETTENGILL. H J Uranium Recovery Field Office 84/02/09 Uranium Recovery Field Office 5pp 22709 114
- POCKET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANOGGA, IN
- 8403220220 Forwards revised, "Edgemont Mill Decommissioning Project Health Physics Manual" in response to E Hawkins concerns
 Revised info provided as clarification & elaboration of
 statements made in original manual
 MILLS: M Tennessee Valley Authority 84/01/16 SMIT
 Uranium Recovery Field Office 2pp 22721 236 84/01/16 SMITH-R D
- --8403220224 Rev | to "Edgemont Mill Decommissioning Health Physics Tennessee Valley Authority 84/01/31 110pp 22721 241
- 8403[50237 Forwards rept for Nov 1783 on status of projects active under FIN A-9350 KELLY,M J Dak Ridge National Laboratory FIN A-9350 83/12/14 HAWKINS,E F Uranium Recovery Field Office 4pp 22649 012
- 8403130229 Provides add1 info in response to concerns raised during NRC review of proposed Pond iO mods Mods include const of new isolated elevated pand Weckiy visual insp will be conducted for all Pond IO dikes
 MILLS,L N Tennessee Valley Authority 84/01/04 SMITH, R D
 Uranium Recovery Field Office 3pp 22649 027
- 8403150230 Forwards status rept for Dec 1983 on projects active under FIN A-7350 KELLY, H J Oak Ridge National Laboratory FIN A-9350 84/01/18 HAWKING, E F Uranium Recovery Field Office App 22649 023

- 8403260102 Forwards IE Insp Rept 40-1341/84-01 on 840123 No violations HALL.R E Region 4. Office of Director 84 Tennesses Valley Authority 2pp 22758 245 84/02/22 DONOVAN, T K Tennessee Valley Authority
- --8403260107 iE Insp Rept 40-1341/84-01 on 840123 No violations or deviations identified Major areas inspected organization & administration.radiation protection.respiratory protection & independent measurements
 SPITIBERG.D B , JIERREE.C C , EVERETT,R R Region 4, Office of Director 84/02/21 4pp 22758 247
- 8403200333 Amends Condition 31 to License SUA-816 Amend approves radiological safety plan & procedures in health physics manual as basis for implementing radiation safety programs SMITHAR D Uranium Recovery Field Office 84/02/27 Tenner Valley Authority 2pp 22709 124
- --8403200335 Safety evaluation re review of health physics manual for decommissioning Edgement Hill Manual acceptable HAMKINS: E F., JIERREE.C C Uranium Recovery Field Office 84/02/23 App 22709 126
- DOCKET 40-1478 SPENCER CHEMICAL CO , KANSAB CITY, MO
- B403260116 FDIA request for five categories of documents re facilities BARNES,C Affiliation Not Assigned 83/12/02 FELTON,J M Division of Rules and Records 1p 22763:333
- 8403260123 Partial response to FOIA request for five categories of documents re Kerr-McGee Oil Industries, Inc Forwards documents listed on app Review of addl documents subj to documents tasted on app narral request continuing FELTON, J M Division of Rules and Records 84/03/02 BARNES, C Affiliation Not Assigned 2pp 22763 334
- --8403260127 Repts 660207 explosion due to accumulation of hydrogen gas, killing operator & injuring two other employees Operation of thorium process line terminated WULLER.9 E Kerr-McGee Corp 66/03/03 PRICE.E π Atomic Energy Commission 2pp 22763 336
- --R403260136 Forwards investigation rept re 660207 explosion at facility
 Licensee evaluation of hazards involved in processing source
 mati should be reviewed H/o stated encls
 DUBINSKIL Atomic Energy Commission 66/08/02 PAGE, R G
 Atomic Energy Commission 4pp 22763 340
- --BA03260141 Confirms that Enforcement Branch will not communicate w/licensee re compliance investigation rept concerning explosion on 660207 No items of noncompliance noted during investigation PAGE:R O At PAGE:R O Atomic Energy Commission 66/08/17 Commission 1p 22763 344 Atomic Energy
- ~~B403260148 Forwards Region IV 660729 memo re results of survey of licensee facility at Cushing.OK Licensee measurements, as reported in 660609 ltr, substantiated by Region IV findings ROY.M Atomic Energy Commission 66/08/08 NUSSBAUMER, D A Atomic Energy Commission 1p 22763 345
- --B403260153 Discusses certification of 660426 rept re disposition of SNM, per Q Waller 660602 telcon Rept should indicate that contamination limits met in order for Commission to authorize transfer of facility
 NUSSBAUMER, D.A. Atomic Energy Commission 66/Q6/10 LAMBERTUS, H. Kerr-McGee Corp. 2pp. 22763 348
- --8403250158 Confirms 560207 chemical explosion at Cushing.OK thorium processing plant.per 660207 telcon Investigation complete.

 LAMBERTUS, H Kerr∼McGee Corp 66/02/08 WALKER, N I Atomic Energy Commission 3pp 22763 352
- DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP , DKLAHOMA CITY, OK
- 8403020130 Motion to change status of Chamber of Commerce of City of West Chicago to that of limited appearance Certificate of Syc entl FAMELL.T.W West Chicago, IL 84/02/2 Licensing Board Panel 4pp 22442 151 Atomic Safetu and
- 8403130101 Forwards IE Insp Rept 40-2061/84-01 on 831011, i7, 1109, 18, 1212, 21, 840116, 18, 20, 27, 0202-03 & 07 No noncompliance identified adentified
 PAPERIELLO,C J Region 3, Office of Director 84/02/27
 RAINEY,J L Kerr-McGee Chemical Corp (Subs of Kerr-McGee Corp) RAINEY, J L Kwi 2pp 22614 261

- --8403130117 IE Insp Rept 40-2061/84-01 on 831011.17.1107.18.1212.21. 840116.18.20.27.0202-03 & 07 No noncompliance noted Major areas inspected incinerator installation.testing & readiness for operation
 JANUSIA.4 O . SCHUMACHER.M C Region 3. Office of Director 84/02/27 5pp 22614 263
- 8403060118 People of State of IL revised statement of interest from 830707 petition for hearing & for leave to intervene HARRIGAN.N F Illinois, State of 84/02/29 Atomic Safety and Licensing Board Panel ip 22516 317
- --8403060124 People of State of IL revised Contention 2(a) Revincorporates deleted Contention 2(c) Certificate of Svc encl
 RAPKIN.A Illinois, State of 84/02/27 Atomic Safety and
 Licensing Board Panel Spp 22516 319
- B403070027 Requests leave to revise statement of interest included in B30707 petition for hearing & for leave to intervene HARTIGAN,N F Illinois, State of 84/02/29 2pp 22541 200
- --8403070030 People of State of IL agreed revised contentions Proof of Byc encl RAPKIN.A Illinois, State of 84/02/29 Atomic Safety and Licensing Board Panel 8pp 22541 202
- 8403090079 Order granting West Chicago Chamber of Commerce motion to make written limited appearance in proceeding FRYE.J H Atomic Safety and Licensing Board Panel 84/03/07 ip 22575 296
- B403090i19 Memorandum & order admitting revised Contentions 2(a),(1), (n),(p) & (q) Contentions will be governed by B40224 prehearing conference order discovery schedule FRYE.J H Atomic Bafety and Licensing Board Panel 84/03/07 ip 22574 067
- 8403200327 Bummary of 840301 meeting w/Dupont to discuss source matl licensing PAOE:R O Uranium Fuel Licensing Branch 84/03/08 DAVIS.J Q Office of Nuclear Material Bafety & Bafeguards.Director 3pp 22709 140
- 8403200083 Motion for leave to file instanter revised Contentions 2(k).
 (u) & (w) Kerr-McGee & staff do not object to late filing of revised contantions Revised contentions encl RAPKIN.A Illinois, Btate of 84/03/14 Atomic Safety and Licensing Board Fanel 1p 22685 288
- --8403200089 Revised Contentions 2(k), (u) & (w) Applicant chose West Chicago site solely for reasons of short-term economic convenience & benefit including avoidance of expenditures for transportation & land acquisition Proof of Bvc enci RAPKIN.A Illinois. State of 84/03/14 Atomic Safety and Licensing Board Panel 5pp 22685 289
- B403210019 Notice of appearance in proceeding Certificate of Byc encl HEDGLON,M Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) B4/03/19 7pp 22706.350
- 8403280028 Bubmits address change for Nuclear Licensing & Regulation Dept, JC Stauter will serve as primary addressee for encl list of itensees SHELLEY, W J Kerr-McGee Corp 84/03/21. SCHAEFFER, C NRC No Detailed Affiliation Given 3pp 22777 060.
- B403290385 Notice of withdrawal of appearance in proceeding Certificate of Evc encl
 CHARNOFF, G Shaw, Pittman, Potts & Trowbridge DBB 189 84/03/27
 3pp 22814 251
- --8403290389 Response to State of IL Atty General 840314 proposed revised Contentions 2(k), 2(v) & 2(v) Revised Contention 2(k) w/o merit & licensee objects to admission of revised Contention 2(v) & 2(w) as repetitive. W/Certificate of 8vc HEDGLON, M Kerr-McQee Corp. 84/03/27 Commissioners 5pp 22814:254.
- B40330025B Motion for extension of time until B40417 to submit briefs in response to ABLB 840224 order Certificate of 8vc encl RAPKIN, A Illinois, State of DBB 216, 84/03/30 Commissioners 4pp 22824:074.

- DOCKET 40-2259 PATHFINDER MINES CORP . RIVERTON, WY
- 8403150342 "Semiannual Efficient Monitoring Rept.Jul-Dec 1983 "
 Documentation required by License Condition 25 Amend 16
 encl W/840228 ltr
 HARDGROVE.T W Pathfinder Mines Corp 83/12/31 WODLSEY.R T
 Uranium Recovery Field Office 16pp 22649 247
- 8403:90443 Submits review of first 1983 semiannual rept of environ data & 1983 land use survey rept Site performance within acceptable limits w/exception of certain groundwater results
 WOOLSEY.R T , PETTENGILL.H J Uranium Recovery Field Office 84/02/09 Uranium Recovery Field Office 5pp 22679 357
- 8403120251 Requests accelerated approval to quarterly schedule for stack effluent monitoring Approval will allow quarterly schedule to be instituted prior to final approval of entire license renewal application
 NUGENT, E L Pathfinder Mines Corp 84/02/17 PETTENGILL, H
 Uranium Recovery Field Office ip 22619 207
- DOCKET 40-3392 ALLIED CHEMICAL CORP . MORRISTOWN, NJ
- 8403130083 Forwards IE Insp Rept 40-3372/84-01 on 840131-0202 No violations or deviations identified PAPERIELLO.C J Region 3, Office of Director 84/02/23 CIPOLLA.A J Allied Chemical Corp 2pp 22578 335
- --B403130074 IE Insp Rept 40-3392/84-01 on B40131-0202 No violations or deviations identified Major areas inspected radiation protection solid radwaste mgt. environ monitoring safety committees & conduct of operations
 MILLER,D E , FRANCE,G M , GREGER,L R Region 3, Office of Director B4/02/22 6pp 22598 337
- 8403230097 Forwards corrected "Facility Effluent Rept.830701-840101" CIPOLLA:A J Allied Chemical Corp 84/02/29 Region 3, Office of Director 1p 22730 122
- ~-8403230100 Corrected "Facility Effluent Rept.830701-840101 " * Ailied Chemical Corp 84/01/01 2pp 22730 123
- DOCKET 40-3453 ATLAS MINERALS, INC , DENVER, CO
- 8401120171 Forwards annual audit rept of Moab Mill radiation protection program Followup rept addressing action taken or to be taken for each item in audit encl BLUBAUGH.R E Atlas Minerals. Inc 83/07/16 WEAVER.R R Atlas Minerals. Inc 2pp 21805 020
- --8401120180 "ALARA Audit Rept of Atlas Minerals Corp Environ & Radiological Monitoring Program," executive summary SAVIGNAC,N Atlas Minerals, Inc. 83/09/30 379p 21805 022
- 8403150264 "Bampling & Analysis Results of Environ Monitoring Program. Bacond Half 1783" per License Condition 42 & 43 W/840223 ltr EDWARDS.D L Atlas Minerals, Inc 83/12/31 SMITH.R D Uranium Recovery Field Office 125pp 22648 037
- B403040465 Issues Amend 14 to License SUA-917, adding Conditions 19(E) & 36 re potential impact of past disposal of metal drums containing vanadium wastes & disposal of wastes in tailings pond or beach respectively OARGIA, P.J., PETTENGILL, H.J. Uranium Recovery Field Office 4pp 22549 327
- 8403070367 Issues Amend 14 to License 8UA-917, prohibiting disposal of wastes other than mill process or liquid sanitary wastes in tailings pond unless specifically authorized by NRC BMITH:R D Uranium Recovery Field Office 84/01/18 Atias Minsrals: Inc Rpp 22564 143
- 8403150280 Forwards clarification of storage/seepaga terms in "Water Balance Study,U Mill Tailings Impoundment," in response to 840118 request BLUBAUGH.R E Atlas Minerals, Inc. 84/02/14 PETTENOILL,H J Uranium Recovery Field Office 3pp 28646 359
- 8403200399 Bubmits review of technical evaluation performed by Dames & Moore of embankment performance for Moab Mill Embankment in excellent condition & functioning as designed QARCIA:P J. PETTENDILL.H J. Uranium Recovery Field Office 84/02/14 Uranium Recovery Field Office 2pp 22707 337

- 8403230267 Advises that License SUA-917 will be renewed & reduced monitoring program submitted in anticipation of increased sales market for U-308 concentrate BLUBAUGHAR E Atlas Minerals, Inc. 84/02/16 SMITHAR D Uranium Recovery Field Office ip 22741 356
- 8403i50242 Informs of annual survey of land use within 2-mile area of mill Summary of differences in land use provided EDHARDS, D.L. Atlas Minerals, inc. 84/02/24 SMITH.D Uranium Racovery field Office 2pp 22649 010
- 8403190431 Notifies of issuance of Amend 14 License SUA-917 Amend requires evaluation of possible impacts from waste other than mill tailings disposed in tailings pond or removal of wastes
 GARCIALP J. PETTENOILL.H J. Uranium Recovery Field Office 84/03/01 HILLER.H O. License Fee Management Branch 1p 22681 326
- DOCKET 40-4492 FEDERAL-AMERICAN PARTNERS, RIVERTON, WY
- 8403200374 "Semiannual Rept on Radioactive Effluent Per 10CFR40 65, Jul-Dec 1983 " One oversize map encl Aperture card is available in PDR W/American Nuclear Corp 840227 ltr. * Federal American Partners 83/12/31 40pp 22707 285
- 8403190414 Ack receipt of 840203 request for approval of in-place reclamation of ail existing tailings generated by Federal American Partners in Gas Hills area Review under way SMITH.R D. Uranium Recovery Field Office 84/02/14 ANDRUS.N J American Nuclear Corp. ip 22681 350
- 8403200323 Forwards pertinent sections of draft DES re in-place reclamation of tailings pond Requests review of American Nuclear Corp request & comments re concept of in-place reclamation of Tailings Pond i PETTENGILL.H Uranium Recovery Field Office 84/02/23 RANDEN.L Hyoming, State of 2pp 22709 149
- --8403200323 Discusses status of preparing final reclamation plan for Tailings Pond 2 Requests assurance that Region IV approves concept of in-place reclamation for tailings existing at mill.

 ANDRUS, N J American Nuclear Corp 84/02/03 SMITH.R D Uranium Recovery Field Office ip 22709 151
- --8403200328 Responds to 840203 request for NRC approval of in-place reclamation of existing tailings generated at mill operated in Gas Hill area of State of HY Situation currently under review
 SHITH.R D Uranium Recovery Field Office 84/02/14 ANDRUS, N J Amarican Nuclear Corp 1p 22709 132
- 8403220045 Forwards Federal-American Partners, "Semiannual Rept on Radioactive Efficent-Per 100FR40 65.Jul-Dec 1983 " ANDRUS.N J American Nuclear Corp 84/02/27. Region 4, Office of Director 2pp 22715 122
- ---8403220054 "Semiannual Rept on Radioective Effluent.Per 10CFR40.65, Jul-Dec 1983 " W/one oversize figure Aperture card is available in PDR + Federal American Partners 83/12/31 38pp 22715 124
- DECKET 40-6329 CATHOLIC UNIV OF AMERICA, WASHINGTON, DC
- B403i3042P Discusses IE insp of Licenses SNM-i64.8UD-137 & 08-02075-03 on B40126-27 & forwards notice of violation MARTIN.T T Division of Engineering & Technical Programs B4/03/08 MURPHY.JJ Catholic Univ of America, Washington, DC 2pp
- --8403130433 Notice of violation from insp on 840126-27 Violations noted survey maters not calibr at proper intervals # Division of Engineering & Technical Programs 84/03/08 1p 22613 142
- DOCKET 40-4622 PATHFINDER HINES CORP , SHIRLEY BASIN, WY
- 8403190416 Reviews 830314 submittal of parameters for radiological assessment Parameters requiring clarification listed Response requested by 840301 PETTENOILL: J Uranium Recovery Field Office 84/02/09 RUSSELL: J E Pathfinder Mines Corp 3pp 22681 347

- 8403200397 Reviews application for renewal of License SUA-442 Beveral areas identified needing add1 info Bpecific data requirements & appropriate section of renewal summerized PETTENGILL, H J Uranium Recovery Field Office 84/02/10 RUSSELL, J E Pathfinder Mines Corp 2pp 22707 361
- DOCKET 40-6659 GETTY OIL CO PETROTOMICS CO , SHIRLEY BASIN, WY
- 8403260242 Radionuclide liquid effluent rept for Jul-Dec 1983 List of particulates in form of stack gases released to unrestricted areas submitted.

 PRAFF,8 J Getty/Petrotomics Co 84/01/24 Region 4, Office of Director ip 22754 326
- B403200377 Forwards review of First & Becond Quarter 1983 environ monitoring data for Petrotomics Mill Levels of chlorides & suiphates decreasing KONNINSKI,O R. PETTENGILL.H J Uranium Recovery Field Office 84/02/22 Uranium Recovery Field Office 5pp 22708 337
- DOCKET 40-6920 AUTOMATION INDUSTRIES, INC , PHOENIXVILLE, PA
- 8403010472 Discusses IE Insp Repts 40~6920/83-01 & 30~05998/83-01 on 830315.0607 & 0804 b IE Insp Repts 40~6920/83-02 b 30~05998/83-02 on 831017-18 & i102-03 & forwards notice of violation MURLEY, T E Region i, Office of Director 84/02/16 DHIGHT, J. Automation Industries, Inc. 4pp 22438 290,
- --8403010483 Notice of violation & proposed imposition of civil penalty in amount of 45.625 Violations noted. Failure to apply correction factor to meter readings previously identified during NRC insp & radioactive matis not suitably packaged MURLEY.T E Region i. Office of Director 84/02/16 App. 22438 294
- 8403020331 Confirms 840227 teicon understanding of listed actions based on results of 840228 insp MARTIN.T T Division of Engineering & Technical Programs 84/02/29 MORELAND.F Automation Industries, Inc. 2pp 22439 213
- 8403120234 Forwards order to show cause & order temporarily suspending Licenses 37-00611-09 & 808-868 DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/02 DMIGHT.J Automation Industries, Inc 2pp 22619 241
- --B403120242 Order to show cause & order temporarily suspending Licenses SUB-B6B & 37-00611-09 re apparent excess radiation exposure to thumb & fingernails of two radiation technicians working in restricted area

 DEYDUNO,R C Director's Office, Office of Inspection and Enforcement 84/03/02 Automation Industries, Inc 10pp 22319 243
- 8403210001 Responds to notice of violation & proposed imposition of civil penalties Third party being located to take over activities at Phoenizviiie, PA nuclear encapsulation factiity

 BOWHAN, D C Automation Industries, Inc 84/03/14, Director's Office, Office of Inspection and Enforcement 3pp. 22707 052
- --8403210005 Responds to NRC 831227 ltr re violations noted in IE enforcement conference rept & insp of License 37-00611-09 Drawings for extension tubes used w/Model B source changer revised MORELAND, P.E. Automation Industries, Inc. 84/02/03 HARTIN, T.T. Division of Engineering & Technical Programs 7pp. 22707:055
- --8403210010 Forwards add1 technical info re discussions during 830928 enforcement conference concerning fractured secondary encapsulation on Co-60 source & evaluation of source connector. No disconnects observed during 12,000 cycles. HORELAND.P E Automation Industries. Inc 84/01/30, ALLEN,J & Region i, Office of Director 17pp 22707.062.
- B40330000B Responds to B40302 order to show cause & order temporarily suspending Licenses 37-00611-09 & BUB-86B Certain facts in Paragraphs II & III of order contested. Hearing requested BOHMAN, D. C. Automation Industries, Inc. 84/03/26. Director's Office, Office of Inspection and Enforcement 2pp 22821 165

- DOCKET 40-6940 KAWECKI BERYLCO IND , INC , BOYERTOWN, PA
- 8403070317 Forwards submittals from Kawecki Berylco Industries re cause & extent of fluoride contamination in monitoring well 4 & background radiological parameters in West Swamp Creek WYNGARDEN, 8 D Uranium Fuel Licensing Branch 84/02/27 Uranium Fuel Licensing Branch 6pp 22564 321
- DOCKET 40-7455 WHITTAKER METALE, LOS ANGELES, CA
- B4D3190310 Discusses IE insp of License SMA-1018 on 831101~02 No violations observed insp limited to review of Whittaker Metals site in Greenville.PA MARTIN.T T Division of Engineering & Technical Programs 84/03/08 COLLINS.T J Desco Marine 1p 22673 274
- 8403200327 Summary of 840301 meeting w/Dupont to discuss source matl licensing PAGE.R G Uranium Fuel Licensing Branch 84/03/08 DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director 3pp 22709:140
- DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP . OKLAHOMA CITY, OK
- 8403140215 Advises of issuance of Amend 24 to License SUB-1010 changing name of company to Sequoyah Fuels Corp. Review encl
 - enci PAGE:R O Uranium Fuel Licensing Branch 83/12/16 SHELLEY,W J Sequoyah Fuels Corp 1p 28637 331
- --8403140217 Review of 831021 application to amend License SUB-1010 changing company name to Bequoyah Fuels Corp Amend should be issued KOBLA, B M , CROW. W T Uranium Fuel Licensing Branch 83/12/16 2pp 22637 332
- 8403010307 Issues Amend 26 to License SUB-1010, amending Conditions 5,6 & 7 re quantitative analyses for metals & specified Isotopes, existing monitoring wells & surface water samples PAGE.8 O Uranium Fuel Licensing Branch 84/02/16 SHELLEY, W J Kerr-McGee Corp 5pp 22438,310
- --8403010513 SER supporting Issuance of Amend 26 to License BUB-1010.
 amending Conditions 5,6 & 7 re quantitative analyses for
 metals & specified isotopes, existing monitoring wells &
 surface water samples
 RHODES, M. CROW-W T Uranium Fuel Licensing Branch 84/02/16 22438 315
- 8403280028 Submits address change for Nuclear Licensing & Regulation Dept JC Stauter will serve as primary addressee for enci list of licensees SHELLEY, W. J. Kenr-McGee Corp. 84/03/21, SCHAEFFER, C. NRC No Detailed Affiliation Given. 3pp. 22777 060
- DOCKET 40-8084 RIO ALGOM CORP , MOAB, UT
- 8403150208 "Bemlannual Environ Monitoring Rept for Jul-Dec 1983 " LAWTON, M D. Rio Algom, Ltd 83/12/31 34pp 22648 246
- 8403150274 Provides add) info re annual yellowcake production before final assay adjustment from existing carbonate leach at Lisbon mill, PATTIEDON:R 8 RID Algom, Ltd. 84/02/09. EMITH:R D Uranium Recovery Field Office 2pp 22648 285
- 8403190413 Forwards request for addl info re principal parameters for radiological assessment Info needed to complete review of application to renew Source Matl License SUA-1117 Response requested by 840316
 PETTENGILL,H J. Uranium Recovery Field Office 84/02/15
 LANTON,M D Rio Algom, Ltd 1p. 22481 351
- DOCKET 40-8102 EXXON CO., USA, HOUSTON, TX
- B403260138 Ack receipt of 831109 ltr informing NRC of steps taken to Corract violations noted in IE insp of License SUA-1139 on 830905-0B Addi info required re site security HALLIR.E. Region 4, Office of Director 84/01/18 SHANNON, J B Exxon Corp. 1p. 22759:138

- ~-8403260142 Responds to NRC 831014 ltr re violations noted in 1E insp of License 8UA-1137 on 830906-08 Corrective action Section 3 4 of license renewal application modified to reflect current security practices
 SHANNON.J B Exxon Corp 83/11/09 HALL.R E Region 4, Office
 of Director 3pp 22758 159
- 8402140325 Ack receipt of 831109 & 840125 ltrs informing NRC of steps taken to correct violations noted in IE insp of License 8UA-1139 on 830906-08 HALLIR E Region 4. Office of Director 84/02/08 SHANNON, J B Exxon Corp 1p 22228 237
- --8402140327 Responds to NRC 831014 ltr re violations noted in IE insp of License 8UA-1139 on 830906-08 Corrective actions product storage warehouse secured, limiting access to authorized personnel & continuous site security provided BHANNON, J B Exxon Corp 84/01/25 HALL, R E Region 4, Office of Director Rpp 22228 238
- 8403200380 Forwards summary of 840213 meeting between representatives of Exxon Minerals & U Recovery Field Oft to discuss comments on Exxon proposed decommissioning plans for Highland U operations PANGBURN. O C , PETTENGILL, H J Uranium Recovery Field Office 84/02/22 Uranium Recovery Field Office 5pp 22708 332
- DOCKET 40-8107 ARMY, DEPT DF, BACRAMENTO, CA
- 8403200107 IE Insp Findings & Licensee Ack dtd 840207 of License STB-1101 Insp findings no violations observed SKOV.D D Region 5. Office of Director 84/02/07 ip 2268 84/02/07 ip 22685 353
- DOCKET 40-8452 BEAR CREEK URANIUM CO , CASPER, MY
- 8403150935 Forwards 1983 reclamation bond calculations, including performance bond calculation & cost detail for mill site dismanting, decommissioning & reclamation activities MEDLOCK, R L Bearfoot Corp 83/09/20 SMITH, D, GARCIA, P Uranium Recovery Field Office 7pp 22649 016
- 8403150102 "Bear Creek U Co Bemiannual Rept to NRC, Jul-Dec 1983, Environ Sampling " W/840307 ltr BLOSSOM, J N Bear Creek Uranium Co 83/12/31 21pp 22641 169
- B403150226 Hater quality data for monitor wells & static levels for monitor well for Fourth Guarter 1983 per Condition 91(a) of Litense BUA-1310 W/840222 itr BLOSSOM, J N Bearfoot Corp 83/12/31 3pp 22647 032
- 8403190436 "Tailings Disposal Area 1983 Technical Evaluation " W/840131 itr MEDLOCK.R L. Bear Creek Uranium Co 83/12/31 SMITH.D. Uranium Recovery Field Office 40pp 22681 072
- 8403150245 Forwards design review of PMF channel per License Condition 511.Amend 22 to Source Mati License SUA-1310 MEDLOCK.R L Bearfoot Corp 84/01/31 SMITH.D Uranium Recovery Field Office 3pp 22648 357
- 8403200350 Forwards review of monitoring data required by License Condition 51(a) of Source Matl License SUA-1310 PANGBURN, O C , PETTENGILL, H J Uranium Recovery Field Office 84/02/29 Uranium Recovery Field Office 3pp 22709 104
- DOCKET 40-8502 WYDMING MINERAL CORP , LAKEWOOD, CO
- 8403220182 Advises that review of proposed program for demonstrating restoration of alternative lixiviant test area at irigaray Mine site will be completed by 840315 All well fields must be restored. HAHKINB,E F Uranium Recovery Field Office 84/02/22 DEASON,C W Malapai Resources Co ip 22723 282
- 8403220196 Advises that review of proposed program for demonstrating restoration of alternative lixiviant test area at Irigaray Mine site will be completed by 840315 All well fields must be restored be restored HAMKINB,E F Uranium Recovery Field Office 84/02/22 RUTLEDGE,C Wastinghouse Electric Corp. 1p. 22723 279

- DOCKET 40-8584 MINERALS EXPLORATION CO , LOS ANGELES, CA
- 8403150228 Submits responses to questions re Sept 1982 application for amend to Source Hatl License SUA-1330 KLEIM T J Minerals Exploration Co (subs of Union Oil Co of California) 83/08/02 PETTENGILL.H Uranium Recovery Field Office 2pp 22649 030
- 8403280039 Notifies that U processing suspended equipment decontaminated for suspension period & monitoring reduced Suspension will extend through & possibly beyond 5 yrs HILLS C Union Minerals 83/12/13 PETTENDILL, H Uranium Recovery Field Office 2pp 22812 343
- 840322006B Forwards summary of environ monitoring & meteorological conditions for Jul-Dec 1983, per License Conditions
 34, 43 & 48 Environ monitoring, as modified by Amend 12, implemented w/exception of addl air monitor downwind KLEIN-T J Union 76 Hinerals Exploration Co 84/02/28 Region 4, Office of Director ip 22712 218
- --8403220071 Summary of environ monitoring & meteorological conditions for Jul-Dec 1983 * Union 76 Minerals Exploration Co 83/12/31 74pp 22712 219
- 8403220117 Forwards summary of environ monitoring & meteorological conditions.per License BUA-1350 Section 5 & Conditions 34, 43 & 48 Station will be operable in First Quarter 1984 KLEIN T J Union Minerals 84/02/28 Region 4, Office of Director 1p 22718 116
- --8403220124 Summary of environ monitoring & meteorological conditions for Third & Fourth Quarters 1983 * Union Minerals 83/12/31 75pp 22718:117
- DOCKET 40-8585 WYOHING MINERAL CORP . LAKEWOOD, CO
- 8403260213 "Bemiannual Effluent Manitoring Rept, Jul-Dec 1983 " W/840227 ltr BERGOR E Wastinghouse Electric Corp 83/12/31 2op 22756 162
- DOCKET 40-8585 KERR-MCGEE NUCLEAR CORP . GKLAHGMA CITY, DK
- 8403150332 Forwards rapt re abandonment & plugging procedures for water well & monitor hold

 8HBLLEY,W J Kerr-HtGee Corp 83/10/05 PETTENOILL,H Uranium Recovery Field Office 3pp 22647 271
- 8403280099 Forwards completed NRC Form 314 for license License will not be renewed at present LANDAGDRA,M Kerr-McGee Corp 83/11/21 Division of Fuel Cycle & Material Bafety 1p. 22811 361
- --8403280103 Certificate of disposition of matls no matls procured by licenses under License SUA-1330, SHELLEY,H J. Kerr-HcGee Corp B3/11/21 ip 22811 362
- DOCKET 40-8602 BILVER KING MINES, INC., CASPER, MY
- 8403200370 "Annual Land Use Burvey Project Area Five Mile Radius, 1783 " N/B40228 ltr One oversize map enc? Aperture card is available in FDR # 551ver King Mines, Inc 83/12/91 PETTENOILL.H J Uranium Recovery Field Office 12pp 22708 273
- 8403220210 Responds to 831122 request to extend license & defer further preoperational environ monitoring Approval of request would not be in keeping wintent of NRC regulations License ranswal application should be submitted PETTENGILLH J Uranium Recovery Field Office 84/02/23 WOLFF, C E Silver King Mines, Inc. ip. 22723 265
- DOCKET 40-8647 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK
- 8403280028 Submits address change for Nuclear Licensing & Regulation Dapk JC Stauter will serve as primery addresses for encl list of licensees EMELLEY, W.J. Kerr-HcOes Corp. 84/03/21, SCHAEFFER, C. NRC No Datailed Affiliation Given. 3pp. 22777.060.

- DOCKET 40-8663 NUCLEAR DYNAMICS, INC , PHOENIX, AZ
- 8403150Ri2 Submits analysis of Ra-226 level in water immediately prior to discharge, supplementing 831107 request for permission to discherge water in evaporation ponds Application to amend License SUA-1331 under NRC consideration FRITZ D M Western Water Consultants, Inc 84/01/13 WAGNER, J Hyaming, State of 4pp 22647,046
- DOCKET 40-8674 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO
- 8403220191 "E4fluent Monitoring Rept. Jul-Dec 1983 " W/840227 1tr * Plateau Resources. Ltd 83/12/31 10pp 22717 036
- DUCKET 40-8681 ENERGY FUELS NUCLEAR, INC , DENVER, CO
- B403190424 Forwards rept of B30830 ALARA audit Rept provides data & trends which enabled audit committee to make recommendations to reduce worker exposures & environ effluents Next rept scheduled for B40229 SMITH.D E Energy Fuels Nuclear, Inc 83/11/28 VINCELETTE, D Energy Fuels Nuclear, Inc 43pp 22700 179
- 8403260187 Lists corrective actions to be taken, per 840112 telcon re 831127 incident & measures to prevent recurrence of violations noted in IE insp on 840104-05 COLLINS, J T Region 4, Office of Director 84/01/13 SPARLING, D K Energy Fuels Nuclear, Inc 1p 22756 121
- 8403200360 Forwards review of semiannual ALARA rept for Energy Fuels Nucleer White Sand Mill for period ending 830630 Future repts should contain more detailed discussion of audit committee findings HILDENBRAND, P., HAWKINS, E.F. Uranium Recovery Field Office 84/02/15 Uranium Recovery Field Office 7pp 22709 003
- 8403200389 Requests assistance in reviewing Union Carbide application for self-bonding SMITM;R D. Uranium Recovery Field Office 84/02/16 BROWNING;R E Division of Waste Management 2pp 22708 313
- --B403200394 Forwards proposed reclamation surety agreement, organizational chart & specific employee qualification for White Mesa U Mill near Blanding.UT DEMOLLANDER, G Union Carbide Corp 84/02/10 HILDENBRAND,P Uranium Recovery Field Office 17pp 22709 315
- 8403200363 Summary of 840209 meeting_w/Union Carbide & Energy Fuels
 Nuclear in Denver.Co re submittal in support of Energy Fuels
 request to transfer Source Matl License 8UA-1338 to Union
 Carbide
 HILDENBRAND, P. HAKKINS, E. F. Uranium Recovery Field Office
 84/02/21 Uranium Recovery Field Office 3pp 22708 336
- 8403190335 FN-84-014 on 840316.notice of violation & proposed imposition of civil penalty in amount of \$6,000 issued to licensee Action based on violations involving radiological occurrence w/potential for radiation exposures FLACK.E. AXELRAD. J Director's Office. Office of Inspection and Enforcement. 84/03/13 2pp 22675 027
- DOCKET 40-8684 WESTERN NUCLEAR, INC , LAKEHOOD, CO
- 8403150215 Forwards results of expanded study by In-Bitu, Inc of pump test specifically addressing issue of leakage from aquifers adjacent to production aquifer through confining layers.
 BOODEN.6 Hestern Nuclear, Inc (subs of Phelps Dodge Corp)
 B4/01/26 HILDEBRAND, P Uranium Recovery Field Office Bpp 22649 035
- DOCKET 40-8698 PLATEAU REBOURCES, LTD , GRAND JUNCTION, CO
- B403:502:3 Confirms telcon re resignation of RJ Carr, effective B40:31 JH Davis will assume RJ Carr duties, effective B40:201 Resume of JN Davis encl GERDENN.F W Plateau Resources, Ltd. B4/01/16. SMITH.R.D Uranium Recovery Field Office. 3pp 22649:043
- 8403150249 Forwards resume of N Savignac per E Hawkins request Savignac will conduct GC audits
 GERDEMAN.F W Plateau Resources, Ltd 84/02/02 SMITH.R.D.
 Uranium Recovery Field Office 6pp 22648.351.

- J403220183 Forwards "Effluent Monitoring Rept, Jul-Dec 1983 " Results of Pb-210 analyses for fourth quarter high vol air samples will be available by 840305 GERDEMAN, F W Plateau Resources, Ltd 84/02/27 Region 4, Offs of Director ip 22909 200 Renian 4. Desire
- -8403220187 "Effluent Monitoring Rept.Jul-Dec 1983" * Plateau Resources. Ltd 83/12/31 39pp 229 3700 22709 201
- DICKET 40-8727 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, DK
- 403280028 Submits address change for Nuclear Licensing & Regulation
 Dept JC Stauter will serve as primary addresses for encl
 list of licensess sees Kerr-McOes Corp 84/03/21 BCHAEFFER,C NRC - No Listion Given 3pp 22777 060 Detailed Affiliation Given

DICKET 40-8745 DOLE PETROLEUM, INC , CASPER, WY

- 403230136 Notifies of amend to License SUA-1396, deleting License Condition Bi to indicate radiation safety officer satisfactorily completed formalized intensive health physics training program SMITH.R D Uranium Recovery Field Office, 84/02/27 Petroleum, Inc. 1p. 82743.354
- -8403230157 Notifies that Ogis Petroleum, Inc fulfilled requirements of License Condition 13 re radiation safety officer satisfactorily completing formalized intensive health Physics training program

 Physics training program

 WASTLER, B L , HAWKINS, E F Uranium Recovery Field Office

 84/02/22, Uranium Recovery Field Office ip 22743: 19 22743 355

ICKET 40-8760 EDLOW INTERNATIONAL CO . WASHINGTON, DC

- .03270086 Ack receipt of 840306 ltr informing NRC of steps taken to ACS2700B6 Ack receipt of B40306 for informing NRG of steps taken correct violations noted in IE insp of Licenses BMC-5377 Requests evaluation to determine whether train accident could affect eafe storage of natural UP6 HIND. A Division of Rediciogical & Materials Bafety Programs 84/03/22 EDLOW. J Ediow International Co 3pp 22770 026
- 8403270094 Responds to NRC telcom w/J Edlow re violation noted in IE imap of License BMC-1377 Corrective actions UF6 will not be stored inside warshouse before license issued POIDHURST, B W Edlow International Co 84/03/06 ALEXSON, W L Region 3. Office of Director 1p 22770 028

CKET 40-9768 KERR-MCGEE NUCLEAR CORP , OKLAHDMA CITY, OK

- O3010071 Forwards inforest to State of MY Dept of Environ Quality to be inserted into D-Sand in situ project application. FREEMAN.M D Sequoyah Fuels Corp 84/01/25 HILDENBRAND,P R, LINEHAN.J J Uvanium Recovery Field Office. 16pp 22480 008
- D3200355 Discusses detection of excessive U concentration in urine mnatysis at Kerr McGee Q-Sand Project Vendor actions Batisfactory.

 HILDENBRAND, P., HAWKINS, E. F., Uranium Recovery Field Office
 B4/02/09 Uranium Recovery Field Office 2pp 22708 359
- 33280127 Informs of issuance of amend to License SUA-1387 designating
- Sequoush Fusis Corp as whoily owned subsidiary of Carr-McOse
 SAITH-RD Uranium Recovery Field Office 84/02/09 SHELLEY, W J
 Carr-McOse Corp 2pp 22811 080,
- 13200375 Bummary of 840221 meeting w/Western Nuclear Inc in Denver CO 'e concerns about Willow Creek R&D project discovered during wakage analysis of pump test data. ILLDENBRAND, P., HAMKINS, E., Upanium Recovery Field Office 14/02/23. Upanium Recovery Field Office 2pp 22708 342
- 13280028 Submits address change for Nuclear Licensing & Regulation Papt JC Stauter will serve as primary addresses for encl
 1st of licenses.
 HELLEY, W. J. Karr-McGee Corp. 84/03/21 8CHAEFFER.C NRC - No
 letailed Affiliation Given 3pp 22777.060

- DOCKET 40-8781 TETON EXPLORATION DRILLING CD . INC . CASPER, MY
- 8403150205 Comments on encl quarterly rept for Oct-Dec 1983 Listed Staup, W P Oak Ridge National Laboratory & Idaho, Univ of, Moscow, ID 2pp 22646 228 84/01/16 WILLIAMS, R E
- --8403150207 "Teton Exploration Drifting Co Levenberger Project. Quarterly Rept for Oct-Dec 1983 " * Idaho: Univ of, Moscow, ID 83/12/31 33pp 22646 230

DOCKET 40-8783 URANERZ USA, INC , CASPER, WY

- 8403190412 "Quarterly Operating Rept for Third Quarter 1983 " 4/831101 ltr SOMERVILLE:K G Uraner: USA, Inc 83/09/30 LINGHAN, J J Uranium Recovery Field Office 100pp 22681 106
- 8403170411 "Quarterly Operating Rept for Second Guarter 1983 " W/ 830901 ltr SOMERVILLE.K 0 Uranerz USA, Inc 83/0; Recovery Field Office 99pp 22681 212 63/06/30 LINEHAN, J.J. Uranium

DOCKET 40-8786 URANIUM RESOURCES. INC. RICHARDSON. TX

- 8403150272 Informe of contamination of DJ Kindis urine sample 14-11 NG3150272 Informs of contamination of DJ Kindis uring sample 14-11 taken on B31124 Source of contamination could not be identified Bioassay samples wiil be piaced in locked, tamper proof receptacie to prevent contamination FREEMAN, M D. SIME, G J Kerr-McGee Corp 84/01/04 SMITH, R D Uranium Recovery Field Office 3pp 22648 280
- 8403150283 Comments on adequacy of pump test Teet will yield most info requested Bome data may require reanalysis MULLER, K. Wyoming, State of 84/01/26 Wyoming, State of 3pp 22648-348
- B403150260 Comments on Kerr-McGee responses to previous comments, excluding pump test comments Adequacy or remaining issue noted as appropriate MULLER, K. Wyoming, State of 84/01/26 Hyoming, State of 22648 346
- 8403130294 Forwards info sent to State of WY Dept of Environ Quality to be inserted in O Sand in-situ project application FREEMAN, M D Kerr-McGee Corp 84/01/31 LINEHAN, J Uranium Recovery Field Office 16pp 22649 317

DOCKET 40-8820 AMAX ENVIRONMENTAL SERVICES, INC. GOLDEN, CO.

8403070348 Issues Amend 1 to License BMB-1418, Adding Condition 17 stating that rept required by Condition 17 must be submitted PAGE,R G Uranium Fuel Licensing Branch 84/02/27 KERRIGAN.J E AMAX Environmental Services, Inc. (subs. of AMAX, Inc.) 1p

DOCKET 40-8824 TARGET RESEARCH, INC., WHARTON, NJ

- B403220170 Ack receipt of 840213 ltr informing NRC of steps taken to correct violations noted in IE insp of License 808-1421 MARTIN: T Division of Engineering & Technical Programs 84/03/16 GUADAONO: V Target Research: Inc. ip 22909 176 84/03/15
- --8403220173 Responde to NRC 1tr re violations noted in IE insp of License SUB-1421 Corrective actions license amended to allow transport of mati to licensed recipient & to modify detection requirements

 GUADADONO,V Target Research, Inc 84/02/13 FRIEDMAN.L F
 Regian 1. Dffice of Director 2pp 22707, 197

DOCKET 40-8829 HYDMING FUEL CO . LAKEHDOD, CD

8403150317 Forwards responses to NRC questions re-solar evaporation pond design & State of NE questions re-Crow Butte U Project. W/four oversize maps Aperture cards are available in PDR. 8TOUT.D H Wyoming Fuel Co 83/10/21. LINEHAN.J Uranium Recovery Field Office 136pp. 22677.113

- --8403150340 "Soils Engineering Rept. Hyoming Fuel Co Crow Butte Project Pilot Test Pand Area " FISHER.R. HARDEN, K.C. Fisher, Harden & Fisher 82/12/31 52pp 22677 197
- 8403150286 Comments on Hypming Fuel Co response to request for add1 info & on "Guidelines for Groundwater Monitoring at In Bitu U Solution Mines " Ltr to EPA 4t6 831205 outlining procedures for exempting aquifer enc! HOFFIAN. T E Wastern Nebreska Resources Council 84/01/06 HAWKING.E F Uranium Recovery Field Office 7pp 22648 335
- 8403190415 Forwards draft rept of review of hydrology for Wyoming Fuel Co proposed Crow Butte R&D project Rept will be basis for hydrology section of EIA HAMKINGLE F Uranium Recovery Field Office 84/02/09 HABERMAN.C Nebraska, State of 32pp 22700 147
- 8403200372 Forwards review of waste storage ponds which should be included in environ assessment Pond & liner designs meet applicable criteria GILLEN.D.N. JOHNSON.T.L. Engineering Branch (Post 831001) 84002/15 WASTLER.S.L. Uranium Recovery Field Office 5pp 22708 345
- 8403190418 Forwards EIAs & licenses for Kerr-McGee & Uraner: R&D projects.per request W/o enc! HAHKINS.E F Uranium Recovery Field Office 84/02/17 HABERMAN.C Nebrasta. State of 1p 22681 346
- B403200320 Responds to comments & requests for addI info on groundwater restoration & potential for increased energy costs at U in situ leach project No impact evident on present rete payer or environ due to project HAHKINSE Unanium Recovery Field Office 84/02/22 HDFFMAN,T Western Nebraska Resources Council 2pp 22709 162
- 8403220190 Forwards description of pump test by Myoming Fuel Co for proposed Grow Wutte project & subsequent enalyses of pump test data M/o encl
 HAMMINS.E.F. Urenium Recovery Field Office 84/02/22 REILLY,F. Interior, Dept. of, Geological Survey Ip 22723 281

DOCKET 40-8930 HONEYWELL, INC , HOPKINS, MN

- 8403060201 Forwards IE Insp Repts 40-8830/84-01 & 30-20529/84-01 on 840207-08 No noncompliance noted WIEDEMAN,D Q Region 3, Office of Director 84/03/01 FRAKES,J Honeywell, Inc. 1p 22517 176
- --8403060210 IE lass Repts 40-8830/84-01 & 30-20527/84-01 on 840207-08 No noncomplience noted Major areas inspected organization. Licenses audits training, retraining & instructions to workers, radiological protection procedures & matts HADERA, J R. DBERG, C. T. WIEDEMAN, D. G. Region 3, Office of Director 84/02/29 ipp. 22517 177

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR

F Becurity, medical, emergency & fire protection plans

8403280205 Forwards sanitized version of updated Feb 1984 route survey for shipment from Ann Arbor. MI to Bavanneh River. EC to replace Aug 1983 version, per locfR73 21 Portions of 830825 ltr remain unchanged SHERR. T S Haterial Transfer Safeguards Licensing Branch 84/03/12 KERR. W Michigen, Univ of, Ann Arbor, MI. 14pp 22808, 214 24% Fiche 30-002:84703/12.8402280205

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8403070288 Public version of page changes to Book I personnel procedures & Book II emergency procedures, including Procedure IP-1007 re determination of magnitude of release & exposure rate M/831213 itr & JM Felton release memo O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/12/02 MURLEY T E Region I. Office of Director 80pp 22592 220 RAX Fiche 50-003,83/12/02,8403090288

- 8403190243 Notification of 840418 workshop in King of Prussia,PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl MRLEY,T E Region i. Defice of Director 84/03/09 0'100LE,J D Consolidated Edison Co of New York, Inc HEIDER,L H Yankse Atomic Electric Co COUNSIL,W G. Connecticut Yenkee Atomic Power Co 35pp 22672 062 24X Fiche 50-000.84/03/09,8403190243
- 8403190069 Provides preliminary estimete of cost to upgrade present primary emergency operations fecility to provide radiation protection factor of five O'TOOLE.JD Consolidated Edison Co of New York, Inc 84/03/14 EIBENHUT.D O Division of Licensing 2pp 22666 132 24X Fiche 50-003.84/03/14.8403190069
- B403290291 Advises that B31014 rev to physical security plan consistent w/provisions of IOCFR50 54(p) & acceptable MARTIN.T T Division of Engineering & Technical Programs 84/03/21 O'TOOLE.J D Consolidated Edison Co of New York, Inc. App 22800 001 24x Fiche 50-003.84/03/21,8403290291

G Inspection reports. IE Bulietins & correspondence

- 8401190072 IE Info Notice 84-13, "Potentiel Deficiency in Motor depreted Valve Control Circuits & Annunciation " 8vc list enc!

 JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22709 239 24X Fiche 50-000,84/02/28,8401170072
- 8402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACELJ N Division of GA, Safeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pg 22552 329 24X Fiche 50-000.84/03/02,8402090007
- B402090008 IE Info Notice BA-I6, "Feilure of Autometic Sprinkler Sys Valves to Operate " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098. 24X Fiche 50-000.84/03/02,8402090008.
- 8402090009 IE Info Notice 84-I5, "Reporting of Radiological Releases" 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche, 50-000, 84/03/02, 8402090009
- B402070011 IE Info Notice B4-I7, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/05 Consolidated Edison Co. of New York, Inc I17pp 22553 336 24X Fiche, 50-000, 84/03/05, 8402070011
- 8402090024 IE Info Notice 84-09.Rev I, "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co. of New York, Inc 118pp 22635:049 24X Fiche 50-000.84/03/07,8402090024
- B40207002B IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Svc list encl.

 JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22584-186 24X Fiche. 50-000, 84/03/07, 8402070028
- B402090031 IE Bulletin B4-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys." Syc list encl
 DEYOUNG.R.C. Director's Office, Office of Inspection and
 Enforcement. B4/03/12 Consolidated Edison Co of New York, Inc
 134pp 67245 275 24X Fiche: 50-000, 84/03/12, 8402090031.
- 8402070043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PHR Reactor Cavities." 8vc list encl.

 JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229. 24% Fichs: 50-000,84/03/21,8402070043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related 8us " Svc list encl JURDANA: L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001, 24X Fiche: 50-000, 84/03/21, 8402070044
- R Periodic operating reports & related correspondence
- 8403230135 "Personnel Whole Body Exposure for CY83." W/840301 ltr D'TDOLE.J.D Consolidated Edison Co. of New York, Inc. 83/12/31. MURLEY.T E Region 1, Office of Director. 3pp 22730:137. 24X Fiche: 50-003, 83/12/31, 8403230135.

DOCKETED ITEMS

- 8403260120 "Effluent & Waste Disposal Semiannual Rept for Jul-Dec 1983 " W/840301 ltr D'TOOLE.J D Consolidated Edison Co of New York, Inc 83/12/31 MURLEY, T E Region 1, Office of Director 46pp 22758 086 24X Fichs 50-003,83/12/31,8403260120
- B. Reportable occurrences, LERs & related correspondence
- 8403R60233 Forwards summary list of deficiencies identified per IOCFRSO 55(e), Part 21 & potential generic ltr repts for comments
 - ETAROBTECKI.R Division of Project & Resident Programs 84/02/28 Region 1. Office of Director 7pp 22735 063 24X Fichs 30-000.84/02/28.8403260233
- DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR
- F. Becurity, medical, emergency & fire protection plans
- E403070360 Requests add1 info identified in encl NRC emergency plan review by E40430 Plan submitted on B2i027 dose not meet requirements or guidelines in Rev 1 to Reg Guide 2 6 & ANBI/ANS-15 i6-i782.

 THOMAS.C 0 Etandardization & Special Projects Branch 84/02/27 CUNNINGHAM.R Q. Pennsylvania State Univ , University Park, PA 2pp 22564, 138 24% Fiche 50-005, 64/02/27, 8403070360
- ---B403070362 Evaluation of Penneylvania State Univ research reactor emergency preparedness plan

 * Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/29 3pp 22564 i40 24X Fiche 50-005.B4/02/27, B403070360
- DOCKET 50-10 DREEDEN NUCLEAR POWER STATION, UNIT 1
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list
 - Anci. JDRDAN,E L Division of Emergency Preparedness & Engineering Reapones (Poet 830103) 84/02/28 Consolidated Edison Co of New York, Inc. i15pp. 22707 237 24X Fiche 50-000.84/02/28.8401170072
- F. Becurity, medical, emergency & fire protection plane
- 8403120053 Advises of 840323 regional workshop in Rosemont, IL w/ail Region III licensess to discuss fire protection safe shutdown requirements of 100FR50, App R Agenda enci SPESBARD, R L Division of Emergency Preparedness & Operational Support 84/03/06 REED, C Commonwealth Edison Co 3pp 22585-222 24X Fichs. 50-019, 84/03/06, 8493120053
- O. Adjudicatory correspondence
- 8402220157 Order extending time until 840228 for Commission to act to revisw Director's Decision DD-83-14 CHILK, 8, J Office of the Secretary of the Commission 84/02/21 Commissioners 1p 22337 362 24X Fiche 50-000, 84/02/21, 8402220157
- 8403010238 Order extending time until 840305 for Commission to act to review Director's Decision DD-83-14 & 831029 decision denying request of Environ Policy Inet. CHILK.8 J Office of the Secretary of the Commission 84/02/28 Commissioners ip. 82434-210. 24X Fiche 50-000,84/02/28. 8403010238
- 8403070069 Informs that Commission unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expired. Decision became final agency action on 840305 CHILK, 8. J. Office of the Secretary of the Commission 64/03/08 CELEBREIZE, A J. Ohio. State of. Rpp 22575-350 24% Fiche: 50-000, 84/03/08, 8403070069
- B403070074 Informs that Commission unanimously declined to review Director's Decision DD-83-14. Time provided by NRC regulations within which Commission may act to review expired. Decision became final agency action on 840305 CHILK, B. J. Diffice of the Secretary of the Commission 84/03/08 MILLAR, F. Environmental Policy Institute, ip. 22575 292 24X Fiche: 50-000, 84/03/08, 8403070074.
- BA03090113 Informs of Commission decision not to review Director's Decision DD-B3-14. Time for Commission to act expired on BA0305. W/o encl
 CHILK.B.J. Office of the Secretary of the Commission B4/03/08 REBNIKUFF.H. Bierra Club 1p. 22574.079 24X
 Fiche: 50-000: 84/03/08; 8403090113.

- P Operating license stage documents & correspondence
- 8403020037 Notification of contract execution "Dresden & Perry Simulator Leasing," awarded to 0E JESEUP, B Technical Assistance Contracts Branch FIN B-8713 84702/17 HAVINS, O H Director's Dffice, Dffice of Inspection and Enforcement 1p 22491 045 24X Fiche 50-000.84/02/17,8403020037
- ---B403020043 Contract "Dresden & Perry Simulator Leasing," awarded to GE
 PIERCE,R L General Electric Co MDRTON, K V Division of Contracts FIN B-8713 84/02/17 38pp 22491 046 24X
 Fiche 50-000,84/02/17,8403020037
- B403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc list enc1 EIBENHUT, D G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000.84/03/14,8403150275
- Q Inspection reports: IE Bulletins & correspondence
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan" Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance
 THOMAB.B Commonwealth Edison Co 84/02/24 KEPPLER, J & Region G, Office of Director 3pp 22470 137 24X Fiche 50-000,84/02/24.
- --8403050046 Rev O to "Corporate Regulatory Performance Improvement Plan" Commonwealth Edieon Co 84/02/27 22pp 22490 142 24X Fiche 50-000,84/02/24,8403050043
- 8402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.JN Division of QA, Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000,84/03/02.8402070007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sye Valves to Operate " Syc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 82553 078 24X Fiche 50-000.84/03/02.8402070008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releasee" Eve list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fichs 50-000.84/03/02, 8402070009
- B402070011 IE Info Notice B4-17, "Probleme W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN E L Division of Emergency Preparednese & Engineering Response (Post B30103) B4/03/05 Consolidated Edison Co of New York, Inc i17pp 22553 336 24X Fiche 50-000,84/03/05,8402070011
- B402070024 IE Info Notice 84-09. Rev i, "Lessone Learned From Insps of Fire Protection Safe Shutdown Sye " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Poet 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402070028 IE Info Notice 84-18, "Strees Corroeion Cracking in PWR Sys." Svc liet and JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche. 50-000.84/03/07, 8402090028
- 8402070031 IE Bullatin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Syc list encl DEYOUNG.R C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 67245 275 24X Fiche 50-000.84/03/12,8402070031.
- B4032300BB Ack receipt of regulatory performance improvement plan
 Periodic meetings requested to discuse progress on program
 & provide feedback.
 KEPPLER.J G Region 3. Office of Director. B4/03/20 THOMAS.B
 Commonwealth Edison Co ip 22730 161 24X Fiche:50-000,84/03/20,
 B4032300BB
- --B403230107 Forwards corporate regulatory performance improvement plan THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER.J Q. Region 3, Office of Director 3pp. 22730 162. 24X Fiche 50-000. B4/03/20.8403230088

- --8403230126 Rev O to "Gorporate Regulatory Performance Improvement Plan For Dresden.Guad Citles.Zion & LaSalle Operating Nuclear Stations & Eyron & Braidwood Project Operating Stations & Byron & Braidwood Project Operating
 Organizations "

 Commonwealth Edison Co 84/02/29 22pp 22730 145 24X
 Fiche 50-000, 84/03/20, 8403230089
- 840E090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Syc list encl JORDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/03/21 Consolifated Edison Co. of New York, Inc. 123pp 22823-227 24X Fichs 50-000.84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related 102090044 IE Info Notice dames.

 Sys " Eve list encl
 JORDAN,E L Division of Emergency Proparedness & Engineering
 Response (Post 830103) 84/03/21. Consolidated Edison Co of New
 York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044

R Periodic operating reports & related correspondence

- 8403060099 "Rept of Radioactive Efficents, Jul-Det 1983 " H/840215 ltr SCOTT.D J Commonwealth Edison Co 83/12/31 KEFPLER.J G Region 3. Office of Director 17pp 22506 245 24X Fiche 50-010.83/12/31. 8403060099
- 8403080197 "Rept of Occupational Personnel Radiation Doses, 1983 " W/840227 1tm
- W/840227 ltr 8COTT.J S Commonwealth Edison Co 83/12/31 CASE,E G Off Nuclear Reactor Regulation. Director 13pp 22359 099 24X Ficha 50-000,83/12/31,8403080197
- 8403220120 Annual whole body external exposures for 1983 W/840316 ltr RYEAX, B Commonwealth Edison Co 83/12/31 7pp. 22716 007 24X Fiche 50-000,83/12/31,8403220120.

DOCKET 50-13 BABCOCK & WILCOX CO CRITICAL FACILITY

- P Operating license stage documents & correspondence
- 8403020162 Responds to 831122 request for waiver on use of qualified reactor operators for fuel handling operations during period between time of CV-10 facility final shutdown & completion of fuel shipments Request denied THOMAS,C O Standardization & Special Projects Granch 84/02/17 (B.6EN.A F Babcock & Wilcox Co 3pp 22491 138 24X Fiche 50-013.84/02/17.8403020162

DOCKET 50-18 VALLECITOS BOILING MATER REACTOR

- R Periodic operating reports & related correspondence
- 8403200244 "Annual Operating Rept 19 for Vallecitos BLR (Deactivated) " 403200244 "Annual Operating Rept 19 for Vallacitos BHR (Deactivated M/840312 ltr * General Electric Co 83/12/31 DENTON, HR Office of Nuclear Reactor Regulation, Director 5pp 22691, 115 24X Fiche 30-018,03/12/31.8403200244
- DOCKET 50-20 MASSACHUSETTS INST OF TECH RES. REACTOR F. Security, medical, emergency & fire protection plans
- B402120347 Forwards Rev 30 to SAR for research reactor HITR-11. affecting physical security plan Rev withheld (ref 10CFR73 21). CLARK.L Massachusetts Institute of Technology, Cambridge, MA. 84/02/07 THOMAS.C O Standardization & Special Projects Branch 1p 22203 299 24X Fiche 50-020,84/02/07,8402130347
- 8403220034 Advises that Region I appraisal/insp of emergency preparadness program scheduled to begin 840403

 MARTIN.T T Division of Engineering & Technical Programs 84/03/13 CLARK.L Massachusetts Institute of Technology. Cambridge. NA ip 22717 182 24X Fiche 50-020,84/03/13,8403220034
- O Inspection reports. IE Sulletins & correspondence
- 8403220034 Advises that Region I appraisal/insp of emergency preparedness program scheduled to begin 840403 HARTIN, T T Division of Engineering & Technical Programs 84/03/13 CLARK, L Massachusetts Institute of Technology, Cambridge, MA ip 22717 182 24X Fiche, 50-020, 84/03/13, 8403220034

- DOCKET BO-28 YANKEE-ROWE NUCLEAR POWER STATION F Security, medical, emergency & fire protection plans
- 8403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection gafe shutdown insp & topics described in IE Info Notice gafe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl MURLEY.TE Region 1. Office of Director 84/03/09 D'TOOLE.J D Consolidated Edison Co of New York, Inc HEIDER.L H Yanks Atom Electric Co COUNSIL.W Q Connecticut Yanks Atomic Power Co 33pp 22672 062 24X Fiche 30-000.84/03/09.8403190243 Vankes Atomie

J Insurance & indemnity information

- 8403140033 Forwards Endorsement 40 to MAELU Policy MF-26 & Endorsements 103140003 Forwards Endorsement 40 to make Policy MP-26 & Endorsemen 108 & 109 to NELIA Policy NF-26 BINISIJ M Marsh & McLennan, Inc 84/03/05 SALTZMAN, J D Assistant Director for State & Licensee Relations 4pp 22634 155 24X Fichs 50-029,84/03/05.8403140033
- 8403270215 Submits info re nuclear property insurance coverage as of 103270215 Bubmits info to nuclear property insurance co 840401 Coverage carried W/American Nuclear Insurance & Mutual Atomic Enargy Reinsurance Pool KAY.J A Yankee Atomic Electric Co 84/03/22 CRUTC Operating Reactors Branch 5 ip 22772 087 24X Fiche 50-029,84/03/22,8403270216 CRUTCHFIELD, D
- P Operating license stage documents & correspondence
- 8403080007 Forwards YAEC-1378, "Main Steam Line Break Analysis Addition of Boron Transport Model " Post-processor to RETRAN code developed to predict Yankee Nuclear Power Station transient begron contentrations
 KAY.J A Yankee Atomic Electric Co 84/03/02 CRUTCHFIELD, D Operating Reactors Branch 5 19 22357 155 24X
 Fiche 50-029.84/03/02.8403080007
- --8403080009 "Yankee Nuclear Power Station Main Steam Line Break Analysis AUJUSUUUP "Yankee Nuclear Power Station Main Steam Line Break And Addition of Boron Transport Kodel " KENDALL.J M , FUJITA.N , CHANDOLA.V Yankee Atomic Electric Co YAEC-1398 84/02/29 115pp 22537 157 24X Fiche 50-029.84/03/02.8403080007
- 8403120123 Forwards proposed resolution of specific equipment soviron qualification deficiencies identified in Franklin Research Ctr Technical Evaluation Rept TER-C5257-463

 KAY, J A Yankee Atomic Electric Co 84/03/05 EISENKUT, D 0

 Division of Licensing 35pp 22589 229 24X Fiche 50-029,84/03/05, 8403120123
- 8403130287 Requests exemption from 10CFR30 44(c)(11)(B), specifying requirements for containment penetrations disignated for use as post-accident hydrogen recombiner, by 840405 KAY, JA Yankse Atomic Electric Co 84/03/06 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 22614 146 24X Fichs 50-029,84/03/06,8403130287
- 8403190267 Notifies of assignment of EC Heinzinger as Chief, Reactor Projects Section iA. Div of Project & Resident Programs, effective immediately STAROSTECKI.? Division of Project & Resident Programs 84/03/12 HEIDER, L. H. Yanke Atomic Electric Co. 2pp. 22671, 299 24X Fiche 50-029, 84/03/12, 8403190267
- B403200284 Requests YAEC-1399P, "Determination of Decay Heat for LHR LOCA Analysis." be withheld (ref 10CFR2 790)
 KAY.J A Yankee Atomic Electric Co 84/03/19 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 22696 246 24X
 Fiche 50-029.84/03/19.8403200284
- --8400200288 Requests exemption from 10CFR30. App K requirement re use of 1971 ANS std on decay heat for inifinite reactor operation w/120% uncertainty factor in alternative, proposes use of 1979 ANS std KAY, J. A Ya LAVI ANS SEC KAY, J. A. Yankse Atomic Electric Co. 84/03/09 Office of Nuclear Reactor Regulation, Director 3pp 22696 249, 24X Fiche 50-029,84/03/19,8403200284
- ---B403200290 "Executive Summary Rept on Justification of Modified Decay Heat Model for Yankee Nuclear Power Station " HARVEY, R C , HUSAIN, A Yankee Atomic Electric Co 84/03/09. 27pp 22696 232 24X Fiche 50-029, 84/03/19, 8403200284
- 8403270007 Responds to open item identified in util integrated assessment (NUREO-0823). Topic III-10 A Util established criterion per Rey Quide I 106 for thermal overload protection for motor operated valves KAY, J A Yankse Atomic Electric Go 84/03/22 CRUTCHFIELD, Operating Reactors Branch 5 3pp 22769 350 24X Fichs 50-029, 84/03/22, 8403270007 CRUTCHFIELD, D

DOCKETED ITEMS

- B403270003 Responds to open item identified in util integrated assessment (NUREO-0825), SEP Topic III-5 A Analysis performed per ANBI/ANB 3B 2 to determine force imparted on electrical penetration Blister 12E from break on Steam Generator 2 KAY, J A Yankee Atomic Electric Co 84/03/23 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 22767 346 24X
- 8403300192 Forwards draft Rev 5 to Procedure DP-3838 re low voltage on Emergency Bus 1 or 6-3 480-volt bus draft Rev 5 to OP-3844 re low voltage on Emergency Bus 2 or 4-1 480-volt bus & draft Rev 5 to OP-3845 per BEP Topic VIII-1 a KAY, J A Yankee Atomic Electric Co 84/03/28 CRUTCHFIELD, D Operating Reactors Branch 5 12pp 22819 251 24X Fiche 50-029,84/03/28,8403300192
- @ Inspection reports, IE Bulletins & correspondence
- E401190072 lE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Syc list encl.

 JORDAN,E t. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York Inc 115pp 22707 239 24X Fiche 50-000.84/02/28.8401190072
- B403010331 Advises that plan for exam of primary nozzles described in B40112 ltr satisfies conditions of B40103 relief requests from inservice insp requirements GRUTCHFIELD,D Operating Reactors Branch 5 84/02/29 KAY, J A Yankee Atomic Electric Co 2pp 22432 076 24X Fiche 50-029, 84/02/29, 8403010331
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enci ORACE, J N Division of GA, Bafeguards & Inspection Programs (Post 830103), 84/03/02 Consolidated Edison Co of New York, Inc 130pp. 22532 329 24X Fiche 50-000.84/03/02.8402090007
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 22553 098 24X Fiche 50-000.84/03/02.8402070008
- 8402090009 lE Info Notice 84-i5, "Reporting of Radiological Releases" 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- B402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Coaling Components Below Nil Ductility Tamp "Svc list encl JDRDAN, EL Division of Emergency Preparedness & Engineering Responss (Post 830103) 84/03/05 Consolidated Edison Co of New York, Int 117pp 22553 336 24% Fiche 50-000,84/03/05,8402070011
- B402070024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc 11st encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402070024
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Bys." Byc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 196 24X Fiche 50-000.84/03/07.8402090028
- B402070031 IE Bulletin 84-02, "Failures of OE Type HFA Relays in Use in Class IE Bafety Sys " Svc list encl DEYOUNG.R.C Director's Office of Inspection and Enforcement. 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823-094 24X Fiche 50-000,84/03/12,8402090031
- 8403270286 Forwards IE Insp Rept 50-027/84-02 on 840126-27 No violations noted MARTIN,T.T. Division of Engineering & Technical Programs 84/03/13 HEIDER,L H Yankee Atomic Electric Co 2pp 22800 031 24X Fiche 50-029,84/03/13,8403270286
- --8403290292 IE Insp Rept 50-029/84-02 on 840126-27 No violations noted Major areas inspected failure analysis & activities to replace 3/4-diameter, Schedule 80 vant line on steam generator Loop i GRAY, E. H., DURR, J. P. Region i, Office of Director 84/02/21 3pp. 22800.033 24X Fiche 50-029.84/03/13.8403290286
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp. 22823 229. 24X Fiche 50-000.84/03/21,8402090043

- 8402090044 IE Info Notice B4-20, "Svc Life of Relays in Sefety-Related Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403020292 Personnel & man-rem by work & duty function rept, 1983 W/ B40224 ltr ST LAURENT,N, HEIDER,L H Yankee Atomic Electric Co 83/12/31 HAYNES R C Region 1, Office of Director 4pp 22440 229 Q4X Fiche 50-029.83/12/31.8403020292
- B403120181 "Bemiannual Effluent Release Rept for Jul-Dec 1983 "
 W/840301 1tr
 KAY.JO 1 Yankee Atomic Electric Co 83/12/31 MURLEY.T E Region
 1. Office of Director 16pp 22587 135 24X Fiche 50-027.83/12/31.
 8403120181
- 8403210068 "1983 Annuel Rept " W/840301 ltr HEIDER.L H Yankee Atomic Electric Co 83/12/31 MURLEY.T E Region 1. Office of Director 9pp 22705 043 24X Fiche 30-027.83/12/31.8403210068
- B403020072 Monthly operating rept for Jan 1984 W/840206 ltr WHIPPLE, 8 , HEIDER, L H Yankee Atomic Electric Co 84/01/31 App 22441 337 24X Fiche 50-029,84/01/31,8403020072
- 8403300083 Monthly operating rept for Feb 1984 W/B40305 ltr WHIPPLE, 8 · HEIDER, L H Yankee Atomic Electric Co 84/02/29 6pp 22821 181 24% Fiche 50-029,84/02/29,8403300083
- B Reportable occurrences, LERs & related correspondence
- 9211110598 Discusses failure of Westinghouse Type SC-1 1876-072 relays No further review should be conducted based on review of info ABHE.F Reactor Operations Analysis Branch 82/10/21 SEYFRIT, K V Reactor Operations Analysis Branch 3pp 22/775 235 24X Fiche 50-027,82/10/21,8211110598
- B403090175 Forwards LER 84-001-00 ST LAURENT: N N Yankee Atomic Electric Co 84/02/23 MURLEY: T E Region 1. Dffice of Director 1p 22573 263 24X Fiche 50-029,84/02/23.8403090175
- 8403200215 LER 84-002-00 on 840214, during review for SEP Topic IV-10 A, surveillance procedure inadequacy discovered Tech Spec changes did not contain time requirement Procedure changed W/840315 ltr
 DRAMBRIDOE, B L , ST LAURENT, N N Yankee Atomic Electric Co
 84/03/15 3pp 22699 320 24% Fiche 50-029,84/03/15,8403200215
- DDCKET 50-30 PLUM BROOK RESEARCH REACTOR FACILITY

 R Periodic operating reports & related correspondence
- 8403060405 Forwards "Annual Status Rept for 1983," per 810516 dismantling order RICHLEY, E A. BOITEL, E C National Aeronautics & Space Admin 84/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director Rpp 22518 292 24X Fiche 50-030,84/03/01,8403060405
- --8403060410 "Annual Status Rept for 1983 "

 * National Assonautics & Bpace Admin 84/Q2/06 8pp 22518 294 24X Fiche 50-030, 84/03/01, 8403060405
- W Decommissioning Stage Documents & Correspondence
- 8403150214 EVALUATION OF NUCLEAR FACILITY DECOMMISSIONING PROJECTS SUmmary Report Plum Brook Reactor Facility DERORE, D H, MILLER, R L United Nuclear Corp FIN B-7568 NUREO/CR-3605 B4/02/29 Division of Engineering Technology 34pp Available at NRC 44 29 22649 052 24X Fiche 50-030.84/02/29.8403150214
- DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR
 I Financial information
- 8403220043 Bubmits financial info re operation of facility, per 840302 request Cost estimate for decommissioning encl Annual Financial Rept. 1982 forwarded MCGGVERN, J. J. Union Carbide Corp. 84/03/15 THOMAS, C. O. Standardization & Special Projects Branch. Spp. 22712 146 24X Fiche 50-054,84/03/15,8403220043

P Operating license stage documents & correspondence

- 8403130045 Application for amend to License R-81 adding one additionance to Tech Specs we experiment review & approval to more fully describe extent of nuclear safeguards committee responsibility RUZICKA, HO Union Carbide Corp 84/03/01 THOMAS, C D Standardization & Special Projects Branch 1p 22598 361 241 Fiche 30-054.84/03/01.8403130045
- --8403130052 Proposed Tech Spec change request re experiment review & approval

 Union Carbide Corp 64/03/01 ip 22598 362 24X Fiche 50-054,84703/01,8403130045
- 8403120294 Requests add) info re May 1980 application for license renewal re detailed estimates of total annual operating & decommissioning costs & detailed explanation of sources of funds to cover costs info should be submitted by 840324 THOMAS.C O Standardization & Special Projects Branch 84/03/02 MCGBURRNJ Union Carbide Corp 2pp 22596 361 24X Fiche 50-054,84/03/02,8403120294
- 8403130178 Requests Geosciences Branch review geology & seismology sections of encl Union Carbide reactor SER for Union Carbide subsidiary company license renewal application THOMAS.C O Standardization & Special Projects Branch 84/03/05 JACKSUN.R Geosciences Branch 31pp 22646 281 24X Fiche 50-054,84/03/05.8403150178
- 0 Inspection reports, IE Bulletins & correspondence
- 8403020278 Forwards IE Insp Rept 50-054/84-01 on 840104-06 No violations noted STARUSTECKI.R Division of Project & Resident Programs 84/02/16 MCGUVERN.J J Union Carbide Corp 2pp 22440 052 24X Fiche 50-054,84/02/16,8403020278
- --8403020305 IE Insp Rept 30-054/84-01 on 840104-06 No violations or deviations noted Major aras inspected licensee action on previous insp findings, facility reviews & audits, operator requalification training & surveillance activities XINNEY.H W . RUBERTSON.J A Region i. Office of Director ELSASSER.T C Division of Project & Resident Programs B4/02/03 10pp 22440 054 24X Fiche 50-054.84/02/16.8403020278
- R Periodic operating reports & related correspondence
- 8403270198 "Annual Rept for 1783" W/840320 ltr STRACK:R A Union Carbide Corp 83/12/31 STAROSTECKI:R Division of Project & Resident Programs 7pp 22772 014 24X Fiche 50-054.83/12/31.8403270198
- DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR
- F Security, medical, emergency & fire protection plans
- 8403290328 Forwards updated spent nuclear fuel route from Univ of Virginia to Savannah River,8C SHERR.T S Material Transfer Bafeguards Licensing Branch 84/03/12 BENNECHE,F E Virginia. Univ of, Charlottesville, VA 9pp 22822 229 24x Fichs 50-062,84/03/12,8403290328
- R Pariodic operating reports & related correspondence
- 8403010397 Annual operating rept for 1983 FARRAR, J P Virginia, Univ of, Charlottesville, VA 84/02/16 Division of Licensing 10pp 22433 093 24X Fiche 50-062,84/02/16, 8403010397
- DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR
- R Periodic operating reports & related correspondence
- 8403200242 "GE Test Reactor Annual Rept.Number 25 " H/840312 ltr CUNNINGHAN, G E General Electric Co 83/12/36 DENTGN.H R Office of Nuclear Reactor Regulation. Director 7pp 22690 157 24X Fiche 30-070,83/12/31,8403200242

- DOCKET 80-72 UNIV OF UTAH RESEARCH REACTOR
- F Security, medical, emergency & fire protection plans
- 8403200281 Forwards revised emergency plan, addl financial info & 1983 financial statement for univ SANDQUIST.O M Utah, Univ of, Balt Lake City, UY 84/03/14 THOMAS.C O Standardization & Special Projects Branch 1p 22496 281 24x Fiche 50-072,84/03/14,8403200281
- ---8403200293 Revised "Univ of Utah Emergency Plan for Training & Research Reactors " BANDGUIST.0 M Utah, Univ of, Salt Lake City, UT UTEC ME 84-0205 84/03/14 28pp 22696 282 24X Fiche 50-072,84/03/14, 8403200281
- --8403200296 Univ of Utah operating budget 1983-84 * Utah, Univ of, Salt Lake City, UT 84/03/14 37pp 22696 310 24X Fiche: 50-072,84/03/14,8403200281
- I Financial information
- 8403200281 Forwards revised emergency plan, addl financial info & 1983 financial statement for univ SANDQUIST.G M Utah. Univ of. Salt Lake City. UT 84/03/14 THOMAS,C O Standardization & Special Projects Branch 19 22696 281 24X Fiche 50~072,84/03/14,8403200281
- --8403200276 Univ of Utah operating budget 1983-84 * Utah, Univ of Salt Lake City, UT 84/03/14 37pp 22676 310 24% Fiche 50-072,84/03/14,8403200281
- DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

 R Periodic operating reports & related correspondence
- 8403150072 Annual Rept 24 of operation changes tests & experiments for QE nuclear test reactor H/840305 ltr REED.L L . CUNNINGHAM G E General Electric Co 83/12/3i DENTGN.H R Office of Nuclear Reactor Regulation, Director 7pp 22641 042 24X Fiche 50-073,83/12/31.8403150072
- DOCKET 50-83 UNIV OF FLORIDA TRAINING REACTOR
- F Security, medical, emergency & fire protection plans
- 8403010247 Ack receipt of 831122 & 840201 ltrs transmitting Rev 7 to physical security plan Changes consistent w/provisions of 10CFR30 54(p) & acceptable for inclusion into plan LEHIS.R C Division of Project & Resident Programs 84/02/24 DIAZ.N J Florida, Univ of, Gainesville, FL 2pp 22432 010 24X Fiche 50-083.84/02/24.8403010247
- P Operating license stage documents & correspondence
- 8403280065 Forwards Amend 14 to License R-56 & safety evaluation Amend adds new Section 6 6 3. "Other Special Repts," to Tech Specs covering Level 1, 2 or 3 personnel changes & changes in transient or accident analyses
 THOMAS.C O Standardization & Special Projects Branch 84/03/06
 DIAZ,N J Florida, Univ of, Gainesville, FL 2pp 22812 318 24X
 Fiche 50-083,84/03/06.8403280065
- --8403280068 Amend 14 to License R-56, adding new Section 6 & 3, "Other Special Repts," to Tech Specs covering Level 1,2 or 3 personnel changes & changes in transient or accident analyses
 THOMAS, C O Standardization & Special Projects Branch 55p 22812 220 24% Fiche 50-083,84/03/06.8402280065
- --8403280071 Safety evaluation supporting Amend 14 to License R-56 * Office of Nuclear Reactor Regulation, Director 84/03/06 [p 22812 325 24X Fiche 50-083,84/03/06,8403280065
- DDCKET 50-113 UNIV OF ARIZONA RESEARCH REACTOR
- G Inspection reports, IE Bulletins & correspondence
- 8403060165 Forwards IE Insp Rept 50-113/84-01 on 840109-10 No noncompliance identified. HENSLAMBKI.F A Region 5, Office of Director 84/02/03 GALLAOHER.R Arizona Univ of, Tucson, AZ 2pp 22517 004 24X Fiche 30-113,84/02/03,8403060165

--8403060172 IE Insp Rept 50-113/84-01 on 840109-10 No noncompliance identified Major areas inspected radiation control program, including posting & labeling, surveys & personnel radiation dosimetry SHERMAN, C I, WENSLAMBK I, F A Region 5, Office of Director 84/02/02 7pp 22517 006 24X Fiche 50-113,84/02/03,8403060165

DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR

G Inspection reports. IE Bulletins & correspondence

- 8403170085 Ack receipt of 840305 ltr informing NRC of schedule to revise & update radiation protection procedures per IE Insp Rapt 50-123/84-01
 NORELIUB.C E Division of Project & Resident Programs 84/03/14
 WARNER,D Missouri, Univ of, Rolla, MD ip 22669 325 24X
 Fiche 50-123,84/03/14,8403190085
- --8403190088 Responds to NRC 840216 ltr re violations noted in IE Insp Rept 50-123/84-01 Corrective actions procedure changes to prevent detector from being left disconnected implemented & radiation procedures rewritten BOLON.A E Missouri, Univ of Rolla, MD 84/03/05 NORGLIUB, C E Division of Project & Resident Programs ip 28657-326 24X Fiche 50-123,84/03/14,8403190085
- --8403190094 Forwards IE Insp Rept 50-123/84-01 on 840125 W/o App A describing noncompliance NORELIUB.C E Division of Project & Resident Programs 84/02/16 WARNER, D Missouri, Univ of, Rolls, MO 2pp 22669 327 24X Fichs 50-123,84/03/14,8403190085
- --8403190076 IE Insp Rept 50-123/84-01 on 840125 Noncompliance noted incomplete procedures re radiation protection RIDGWAY,K R, TAMBLING,T N Region 3, Office of Director 84/02/06 6pp 22667,327 24X Fiche 30-123,84/03/14,840319085

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

- 8402230176 Forwards revised Btats of CA nuclear power plant emergency response plan MEDFORD, M O Southern Callfornia Edison Co 84/02/16 EISENHUT. D Q Division of Licensing 2903pp 22353 OOI 24X Fichs 50-000,84/02/16,8402230176
- --8403020117 Revised State of CA nuclear power plant emergency response plan. * Celifornia: State of B3/04/30. 2901pp 22353 003 24X Fiche 50-000,84/02/i6.8402230176
- 8403270205 Discusses Southern California Edison submittal of 1983 revised State of CA emergency response plan on behalf of all State of CA plents, incorporating plan into Diablo Campon Addl planning info will not be developed for Humboldt Bay BCHUYLER, J D Pacific Gas & Electric Co 84/03/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22772, 137 24X Fiche 50-000,84/03/22,8403270205

G Adjudicatory correspondence

- B403270004 Discusses State of CA emergency response plan Plan Incorporated Into Diablo Canyon plan Addl planning will not be performed for Humboldt Bay per 1980 legislation Related correspondence BCHUYLER, J. 0, Pacific Oss & Electric Co DSD 117 B4/03/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1 22769: 349. 24X Fiche. 50-000. 84/03/22, 8403270004
- E403270037 Responds to IE Bulletin 83-07 re apparently fraudulent products sold by Ray Miller, Inc No subj matls incorporated in any safety-related eys. Related correspondence SCHUYLER, J O Pacific Gas & Electric Co DSB 116 84/03/22 MARTIN, J B Reglon 5, Office of Director 2pp 22769 322 24x Fiche 80-133,84/03/22,8403270037

I Financial information

B403280051 Annual Financial Rept 1783 W/B40326 ltr MIELKE, F. W. , BHACKELFORD, B , CRANE, P A Pacific Gas & Electric Co B3/12/31 50pp 22776 23Q. 24X Fiche 50-000, B3/12/31, B403280051

J Insurance & indemnity information

- 8403060178 Forwards Endorsements 101 & 102 to NELIA Policy NF-133 CRANE,P A Pacific Oas & Electric Co 84/02/28 SALTZMAN.J D Assistant Director for State & Licensee Relations 3pp 22518 345 24X Fiche 50-133.84/02/28.8403040178
- P Operating license stage documents & correspondence
- 8403150275 Generic Ltr 84-07 to all licenses of BWRs re procedural guidance for pips replacement at BWRs Svc list encl EISENHUT.D G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000.84/03/14.8403150275
- @ Inspection reports, IE Bulletins & correspondence
- 8401190072 IE Info Notice 84-i3, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22709 239 24X Fiche 50-000,84/02/28,8401170072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOY & NRC " Svc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York. Inc 130pp 22552 329 24X Fiche 50-000.84/03/02,8402090007
- 8402090008 IE Info Notice BA-16. "Failure of Automatic SprinkIer Bys Valves to Operate " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York. Inc. 122pp 2253 098 24X Fiche 50-000.84/03/02, 8402090008
- 8402090009 IE Info Notice 84-15. "Reporting of Rediological Releases" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- B40R090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Bvc list encl JGRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class 1E Safety Bys " Svc list enc!
 DEYOUNG:R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 227 24X Fiche: 50-000, 84/03/21, 8402090043
- B402090044 IE Info Notice 84-20, "Bvc Life of Relays in Safety-Related Bys " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp. 22933 001 24X Fiche 50-000,84/03/21,8402090044
- 8403270037 Responds to IE Bulletin 83-07 re apparently fraudulent products sold by Ray Miller, Inc. No subj matis incorporated in any safety-related sys Related correspondence SCHUYLER, J D Pacific Gas & Electric Co DSB 116 84/03/22 MARTIN, J B Region 5, Office of Director 2pp 22769, 322 24X Fiche, 50-133,84/03/22,8403270037

R. Periodic operating reports & related correspondence

- 8403020006 Monthly operating rept for Jan 1984 H/840203 ltr DERKB.P 6 , WEEKB.E D Pacific Gas & Electric Co 84/01/31 5pp 22442 210 24X Fiche,50-133,84/01/31,8403020006
- B403300075 Monthly operating rept for Feb 1984 W/B40305 ltr DERKB,P S , WEEKB,E D Pacific Gas & Electric Co 84/02/29 5p 22821 302 24X Fiche 50-133,84/02/29,8403300075

DOCKET 50-139 UNIV OF MASHINGTON RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8403240340 Advises that smergency plan submitted on 82i104, does not meet requirements of App E to 10CFR50 or guidance criteria in Rev 1 to Reg Guide 2 & Addi Info identified in Enclemergency plan review should be provided by 840430 THOMAS: C O Standardization & Special Projects Branch 84/03/09 ROBKIN M A Washington Univ of Seattle. WA 5pp 22775 258 24X Fiche 50-139,84/03/09,8403240340

DOCKET 50-142 UCLA TRAINING REACTOR

- F Security, medical, emergency & fire protection plans
- B403170010 Response opposing ABL9 B40224 allegations of misrepresentation re Part 73 issues Representations accurate & no action per 10CFR2 713 should be taken HODDHEAD.C P Hearing Branch 4 84/03/09 Atomic Bafety and Licensing Beard Panel 14pp 22665 133 24X Fiche 50-142.84/03/09, 8403170010
- --8403170015 Affidavit of CP Woodhead in response to ASLB 840224 memorandum & under re missepresentation WOODHEAD.CP Hearing Branch 4 84/03/09 33pp 22665 236 24X Fiche 50-142.84/03/09.8403170010
- --B403190022 Affidavit of JR Gray re CP Woodhead 830B15 filing Certificate of Svc encl GRAY.J R Rearing Branch 4 84/03/09 5pp 22665 26B 24X Fiche 50-142.B4/03/09, B403190010

O Adjudicatory correspondence

- 8403010248 Response to board 831223 order to respond to Committee to Bridge the Gap allegations of mati false statements Record evidence contradicts ellegations MCODHEAD.C P Hearing Branch 4 84/01/10 26pp 22432 124 24x Fiche 50-142.84/01/10.8403010248
- --8403010253 Affidavit of JR Miller in response to Committee to Bridge the Cap allegation that verification that reactor radiation was 100 rem/h at 3-ft.unshie3ded.was untrue HILLER.JR Operating Reactors Branch 3 84/01/09 3pp 22432 150 24X Fiche 50-142.84/01/10.8403010248
- --8403010255 Affidavit of RE Carter verifying that JR Miller & author performed calculations in early 1981 to assess radiation level of reactor core CARTER.R E Standardization & Special Projects Branch 6pp 22432 153 24X Fiche 50-142,84/01/10.8403010248
- --B403010260 Affidavit of DM Carlson showing that statement in 1979 meeting did not contradict truth of 810407 affidavit re necessity of sabotage protection at nonpower reactors CARLSON, D M NRC No Detailed Affiliation Given B4/01/10 Bpp 22432 159. 24% Fiche 50-142-B4/01/10, B403010248
- ---8403010265 Affidavit of DM Carlson re areas requiring controlled access to comply w/iOCFR73 Security sys sufficient to comply w/IOCFR73 67 & no requirement exists for guard,metal or explosive detectors Centificate of Svc encl.
 CARLSON,D M Physical Security Licensing Dranch 81/04/17 18pp 22432 167 24X Fiche 50-142.84/01/10.8403010248
- ---8403010266 Affidavit of GB Nelson re 830628 physical inventory of SNM NELSON, O B Region 5, Office of Director 84/01/09 20pp 22432 186 24X Fiche 50-142,84/01/10,8403010248
- 8403140044 Forwards entire record of safeguards insp repts for 1975-1983 provided by Region V M/o encl.
 MODDHEAD,C Hearing Branch 4 B4/03/09 FRYE,J H. BRIGHT,Q Q .
 LEUBKE,R A Atomic Safety and Licensing Board Panel 1p 22633-084 24X Fichs.50-142.84/03/09.8403140064
- 8403140089 Response to ASLB 840224 order indicating concerns on security plan & security insp repts re sabotage matters raised by Contention XX & directing univ & staff to respond by 840309 Certificate of Svc enci.
 CORNIER.W H California. Univ of: Los Angeles. CA 84/03/09 Atomic Safety and Licensing Board Panel 130pp. 22523 175 24: Fiche 50-142-84/03/09.8403140089

- 8403190010 Response opposing ASLS 840224 allegations of misrepresentation re Part 73 issues Representations accurate & no action per 10CFR2 713 should be taken MDUDMEAD, CP Hearing Branch 4 84703/09 Atomic Safety and Licensing Board Panel 14pp 22665 133 24X Fiche 50-142:84/03/09-8403190010
- --B403190014 Affidavit of DM Carlson in response to ASLB 840224 memorandum & order CARLEON D M Division of Bafeguards 84/03/09 100pp 22665 147 24X Fiche 50-142.84/03/09.8403190010
- --B403190015 Affidavit of CP Woodhead in response to ABLB 840224 memorandum & order re misrepresentation WOODHEAD, CP Hearing Branch 4 84/03/07 33pp. 22665 236 24% Fiche 50-142,84/03/09,8403190010
- ~~8403190022 Affidavit of JR Gray re CP Woodhead 830815 filing Certificate of 5vc encl GRAY. J R Hearing Branch 4 84/03/09 5pp 22665 268 24X Fiche: 50-142, 84/03/09, 8403190010
- 8403190197 Forwards 1E ltr sent to licensee re proposed renewal of OL M/o enci
 MDODHEAD,C P Hearing Branch 4 84/03/14 HIRSCH,D Affiliation
 Not Assigned ip 22668 354 24% Fiche 50-142,84/03/14,8403190157
- 8403200021 Summarizes 840309 press conference where CE Young announced that UCLA reactor shut down for repairs & would remain shut down through Digmpics & possibly thereafter BAY.J H. Committee to Bridge the Sap BAY.J H. Nuclear Law Center B4/03/14 FRYE.J H. BRIGHT.G D . LUEBKE.E A Atomic Safety and Licensing Board Panel 3pp 22698 355 24X Fiche 50~142.84/03/14, 840320002i
- B403190177 Requests notification of accuracy of Washington Post (140310 article indicating that reactor will close during Summer Olympics to avoid possibility of terrorist attack Article enci
 FRYE.J.H. Atomic Safety and Licensing Board Panel B4/03/15
 CORNIER.H.H. California, Univ. of, Los Angeles, CA 2pp
 22671 145 24X Fiche 50-142.84/03/15,8403190177
- 8403210027 Notifies of appraisal of DPc of IE re protection against sabotage & IE Insp Rept 50-124/83-01 for Virginia Polytechnic Inst re insp for radiological sabotage Related correspondence MOUDHEAD, C P Hearing Branch 4 84/03/16 FRYE, J H , ERICHT, C O . LUEBKE, E A Atomic Safety and Licensing Board Panel. 1p 22706 357 24% Fiche 50-142.84/03/16.8403210027
- B403260380 Responds to 840315 inquiry re info reported in 840310 Washington Post article Reactor will remain shut down until after Olympic Games Barricades & armed guards planned Related correspondence CORMIER.W H California, Univ of. Los Angeles. CA. DBB 085 84/03/20 FRYE, J H, LUERKE, E A, BRIGHT. G II Atomic Befety and Licensing Board Panel 2pp 22760,140 24X Fiche: 50-142,84/03/20.84003260380
- B\$03260003 Memorandum & order ruling on Committee to Bridge the Qap objections to rebuttal tastimony Berved on 840323 LUESKE, E A. BRICHT.O O. FRYE, J H. Atomic Sefety and Licensing Board Panel DSB 062 84/03/22 Committee to Bridge the Oap 31pp 2274B 315. 24X Fiche 50-142,84/03/22,8403260003.
- 8403260365 Requests that review of SECY-83-500 re staff proposal to eliminate sabotage protection requirements for research reactors await completion of Ofc of Inspector & Auditor investigation W/o encls Related correspondence HIRSCH.D Government Accountability Project. DSB 105 84/03/23 PALLADING, GILINEKY, ROBERTB Commissioners 2pp. 22760 077 24x Fichs 50-142,84/03/23,8403260365
- P Operating license stage documents & correspondence
- 8403070412 Forwards chronology of licensee activities. Indicating relicensing, intervenor & hearing highlights
 BERNARD, H Standardization & Special Projects Branch. 84/03/01.
 THOMAS, C 0 Standardization & Special Projects Branch. 7pp.
 22567 Oig 24X Fiche 50-142,84/03/01,8403070412

DOCKET 50-146 BAXTON NUCLEAR EXPERIMENTAL FACILITY

J Insurance & indemnity information

8403280064 Forwards Endorsement 91 to Policy NF-164, Endorsements 71 & 74 to NELIA Policy NF-220, Endorsement 61 to MAELU Policy MF-73 & Endorsements 82 & 83 to NELIA Policy NF-107 HDFFMAN, J Marsh & McLennan, Inc 84/03/22 DINITZ, I Assistant Director for 8ts & Licensee Relations 7pp 22776 337 24X Fiche 50-146,84/03/22,8403280064

DUCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

- F Security, medical, emergency & fire protection plans
- B403090229 Rev 42 to emergency plen implementing procedures, Vol 9A * Consumers Power Co 84/02/28 4pp 22571 240 24X Fichs 50-155.84/02/28,8403090229
- B40309021B Forwards evaluation rept of offsite radiological emergency preparedness exercise conducted on B30726 Deficiencies observed did not detract from overall demonstrated cepability to protect public KRIMM.R W Federal Emergency Menagement Agency B4/03/06 JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 7pp 22571 142 24X Fiche 50-155,84/03/06,840309021B
- --8403090221 Evaluation of State of MI.Charlevoix & Emmet Counties offsite radiological emergency preparedness exercise for Big Rock Point Nuclear Power Station * Faderal Emergency Menagement Agency 83/07/26 43pp 22571 147 24X Fiche 50-155.84/03/06.8403090218
- B403120097 Extends invitation to ettend B40323 regional workshop in Rosemont, IL re 10CFR50, App R safe shutdown requirements.

 Horkshop will cover subjs described in IE Info Notice 84-09 & provide addl guidence in safe shutdown analyses SPESBARD, R L. Division of Engineering B4/03/06 DEWITT, R B Consumers Power Co 3pp 22588, 160 24X Fichs 50-155, 84/03/06, 8403120097
- B403220021 Forwards examption from requirements of Section III 0 3 of App R to 10CFR50 re fire detection & fixed fire suppression sys in areas for which alternate shutdown capability provided, in response to util B31020 ltr.
 CRUTCHFIELD.D. Operating Reactors Brench 5. 84/03/20 VANDEWALLE.D.J. Consumers Power Co 3pp 22713.345 24X Fiche 30-155,84/03/20.8403220021
- ---8403220023 Exemption from requirements of Section III @ 3 of App R to iOCFR50 re fire detection & fixed fire suppression sys in areas for which elternate shutdown capability provided EISENHUT, D @ Division of Liceneing. 84/03/20 Consumers Power Co 4pp 22713 348 24X Fiche 50-155,84/03/20,8403220021

Q Adjudicatory correspondence

- B403010203 Forwards licensee 840120 & 24 ltrs on Christa-Maria Bubcontention 9(6) which questions adherence to guidance of NUREG-0737 re radiation monitoring sys. Releted correspondence, OALLG, J Isham, Lincoln & Beale GALLG, J Consumers Power Co 84/02/27 BLOCH, P.B., PARIB, D.H., SHON, F.J Atomic Bafety and Licensing Board Panel 4pp 22435, 283 24X Fiche 50-155, 84/02/27, 8403010203
- B403060188 Forwards replies to J O'Neill 840207 & 07 proposed findings on Contention II-D & issues other than aircraft contention FURSE, M.C. Isham, Lincoln & Beele FURSE, M.C. Consumers Power Co 84/03/01 BLOCH, F.B., PARIS, D.H., SHON, F.J. Atomic Safety and Licensing Board Panel, 1p. 22515 118 24X Fiche 50-155, 84/03/01, 8403060188.
- --8403060192 Reply opposing J D'Neill 840207 proposed findings of fact on D'Neill Contention II-D re aircraft hazards QALLO, J. COPELAND, V. Consumers Power Co. QALLO, J. Isham, Lincoln & Beale, 84003/01. 21pp 22515 117 24X Fiche. 50-155, 84/03/01, 8403060188.
- ---B403060202 Reply opposing J O'Neill proposed findings of fact on 'issues other than aircraft contention Findings lack merit & have no basis in record Certificate of Buc encl
 GALLO, J, FURBE, M C Consumers Power Co GALLO, J Isham, Lincoln & Beale B4/03/01 22pp 22515 140 24X Fiche.50-155,84/03/01,840300188

- 8403140076 Forwards NRC response to intervenor J O'Neill proposed findings of fact on Contention IID re aircraft crashes, seismic crane & pool concrete integrity OUDDARD, R J Hearing Branch 3 84/03/01 BLOCK, P B , PARIS, O H , SHON, F J Atomic Safety end Licensing Board Panel 3pp 22621 338 24X Fiche 50-155,84/03/01,8403140096
- --8403140099 Response to Intervenor J O'Neill proposed findings of fact on pool concrete integrity, saismic crans & aircraft hazards contentions Proposed findings unfounded based on sample size & analysis completeness
 BACHMANN.R O Hearing Branch 1 GDDDARD.R J Hearing Branch 3
 84/03/01 12pp 22621 341 24X Fiche 50-155,84/03/01,8403140096
- 8403120035 Notice of appearance in proceeding Certificate of Svc encl FURBE, H C Consumers Power Co 84/03/05 3pp 22589 267 24X Fiche 50-i55,64/03/05,8403120035
- 8403080ii0 Memorandum & order reopening record on B-52 bomber crash probability Staff review of 1980 USAF analysis shall be filed by 840405
 BLOCH, P. B., FARIS, D. H., SHON, F. J. Atomic Safety and Licensing Board Panel 84/03/06 Office of the Executive Legal Director App 22559 267 24X Fiche 50-155,84/03/06,8403080i10
- 8403090i32 Memorendum clerifying ABLE 840306 order (LDP 84-12A) respending record on B-52 bumber crash probability Probability of crash on Bayshore Renge or overflight of facility need not be calculated BLOCH, P B , PARIS, D H , SHDN, F J Atomic Befety and Licensing Board Panel 84/03/08 3pp 22575 125 24X Fiche 50-155,84/03/08,8403090i32
- 8403190004 Forwards HMM Assoc, Inc revised rept, "Evacuation Time Estimates for Areas Near Big Rock Point " Related correspondence GALLO, J Isham, Lincoln & Beele GALLO, J Consumers Power Co 84/03/13 BLOCH.P B , PARIB.O M , BHON.F J Atomic Bafety end Licensing Board Panel 130pp 22665 001 24X Fiche 50-155, 84/03/13,8403190004
- B403200130 Patition to reconsider & vacate 840306 & 07 orders & find Betourne testimony re 1980 risk analysis to be relieble & probative evidence Certificate of Svc enc:

 GALLO, J Consumers Power Co GALLO, J Ishem, Lincoln & Beale, B4/03/16 9pp. 22699 164 24X Fiche 50-155,84/03/16.8403200130
- B403260360 Response opposing licensee B40301 introduction & motion to strike Reasonable emount of time to supply more transcript citations requested if B40209 filing found deficient Related correspondence
 D'NEILL, J D'Neill, J DBB 084 84/03/16 Atomic Befety and Licensing Board Penel 2pp 22760 262 24X Fiche 50-155,84/03/16.
- 8403280355 Response to licenses 840316 petition for reconsideration of ABLB unpublished 840306 memorandum & order respening hearing record on U'Neill Contention II-D Notice of appearance & Certificate of Svc encl PATTERBON.W F Hearing Branch 3 D88 i55 84/03/23 6pp 22787 204 24% Fiche, 50-155, 84/03/23, 8403280355

I Financial information

8403190071 Annual Financial Rept for 1983 W/840312 1tr SELBY, J D., FOLAHEE, J B., PERRY, P. A. Consumers Power Co. 83/12/31 01AMBUSBO, A. Division of Licensing 34pp 22666, 136 24X Fiche, 50-000, 83/12/31,8403190071

P Operating license stage documents & correspondence

- B403050005 Forwards notice of consideration of issuance of emend to License DPR-6 re radioactive iodine coolent concentration limits. CRUTCHFIELO, D. Operating Reactors Branch 5, 84/02/22 VANDEWALLE, D. J. Consumers Power Co. 4pp. 22490 065 24X Fiche 50-155,84/02/22,8403050005
- --B403050006 Notice of consideration of issuance of amend to License DPR-6 & proposed NBHC determination & apportunity for hearing based on B31216 request re radioactive iodine coolant concentration limits CRUTCHFIELD, D. Operating Reactors Branch 5 84/02/22 7pp 22490 069 24X Fiche, 50-155,84/02/22,8403050005
- 8403050121 Forwards notice of consideration of issuance of amend to License DPR-6, based on 811215 & revised 831216 applications Amend changes Tech Specs re stack gas monitoring sys CRUTCHFIELD, D. Operating Reactors Branch 5 84/02/22 VANDEMALLE, D.J. Consumers Fower Co. 4pp. 22488 032 24X Fiche 50-155,84/02/22,8403050121

- 8403050039 Board Notification 84-041 forwards util 840202 updated proposed resolutions & commitments per integrated assessment of plant Several issues under litigation before ASLB reproposed expansion of spent fuel pool storage expacity MIRAGLIA:F J Assistant Director for Safety Assessment 84/02/24 BLOCH-P B PARIS.O H SHON.F J Atomic Safety and Licensing Board Panel 5pp 22548 283 24X Fiche 50-155,84/02/24,8403060039
- B403060356 Advises that justification of unlimited or limited use of purge sys during normal operations will not be pursued Bys will only be operated during cold shotdown condition Info requested in NRC 840126 ltr no longer required JOHNSON.8 D Consumers Power Co 84/03/01 CRUTCH-FIELD, D Operating Reactors Branch 5 ip 22519 206 24X Fiche 50-135,84/03/01,8403060356
- 8403060321 Forwards request for add1 info re updated inservice testing program for pumps & valves.described in 830121 ltr Conference call to discuss items requested CRUICHFIELD.D Operating Reactors Branch 5 84/03/02 VANDEWALLE.D J Consumers Power Co App 22513 ii6 24X Fiche 50-155.84/03/02.8403060321
- B403090210 Advises that util B40220 proposed variance for high-range stark gas monitors unacceptable Sys should be modified to meet display guidance of NUREG-0737. Item II F i(1). "Addl Accident Monitoring Instrumentation CRUTCHFIELD.D Operating Reactors Branch 5 84/03/07 VANDEWALLE.D J Consumers Power Co 5pp 22574 358 24X Fiche 50-000.84/03/07.8403090210
- B403i60122 Summary of 840222 meeting w/util in Bethesda, MD re 840202 submittal updating integrated assessment Conclusions on listed items provided EMCH.R L Operating Reactors Branch 5 84/03/13 Operating Reactors Branch 5 4pp 22652 020 24X Fiche 50-155,84/03/13,8403i60122
- 8403150275 Generic Ltr 84-07 to all licenses of BWRs re procedural guidance for pipe replacement at BWRs Svc list encl EISEMMUT.D G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000,84/03/14,8403150275
- B40330030B Board Notification 84-054 forwards NRC evaluation & conclusion re util variance from NUREG-0737 guidance concerning high range stack gas monitor (TMI Item II F 1 I)
 HIRAGLIA:F J Assistant Director for Safety Assessment 84/03/14
 BLOCH:P B : PARIB:O H : SHON:F J Atomic Safety and Licensing Board Panel 7pp 22844 282 24X Fiche 50-155,84/03/14.8403300308
- 8403190178 Forwards safety evaluation approving util response to NUREO-0737. Item 11 K 3 44. "Evaluation of Anticipated Transients W/Single Failure to Verify No Fuel Failure " Issue resolved CRUTCHFIELD, D Operating Reactors Branch 5 84/03/15 VANDEWALLE, D J Consumers Power Co 6pp 22671 167 24% Fiche 50-155,84/03/15,8403190178
- B403200177 Forwards comparison of proposed radiological affluent Tech Space (RETS) w/model BMR RETS & comparison of proposed offsite dose calculation manual w/NRC generic guidelines & NUREO-0133
 CRUTCHFJELD D Operating Reactors Branch 5 B4/03/15
 VANDEWALLE, D J Consumers Power Co 137pp 22697 206 24X
 Fiche 30-155,86/03/15.8403200177
- B403230143 Forwards corrected safety evaluation re NUREG-0737. Item II K 3 44, "Evaluation of Anticipated Transients of Manager Failure to Verify No Fuel Failure " Item resolved for facility CRUTCHFIELD.D Operating Reactors Branch 5 84/03/22 VANDEMALLE.D J Consumers Power Co 5pp 22730 142 24X Fiche 50-155.84/03/22.8403230143
- 8403270104 Forwards SER for SEP outstanding hydrologic issues identified during review of integrated plant safety assessment rept (NUREG-0828) Issues include local plant flooding from PMP & flood emergency plan CAUTCHFIELD D Operating Reactors Branch 5 84/03/22 VANDEMALLE, D J Consumers Power Co 3pp 22774 032 24X Fiche 50-155.84/03/22.8403270106
- --B403270113 SER re SEP outstanding hydrologic issues PMP flooding would not cause failures of sys required for safe shutdown + Office of Nuclear Reactor Regulation, Director 84/03/22 6pp 22774 PMP - The SO-155, 84/03/22, 8403270106

- 8403280034 Summary of 840314 meeting w/util & INEL in Bethesda. MD reserviron equipment qualification (EEQ) for facility Util will submit analyses respected by refile them spike & addl info concerning EEG by 840304 Viewgraphs encl EMCH.R L. Operating Reactors Branch 5 84/03/26 Operating Reactors Branch 5 84/03/26 Operating Reactors Branch 5 21pp 22777 023 24% Fiche 50-155.84/03/26, 8403280034
- 8403290187 Responds to NRC request for graphic representation of info on revised Table 4-i. "Hydrostatic Yest Pressure/Temp Limits, Heatup Pressure Temp Limits & Cooldown/Temp Limits." per 831024 Tech 9per Change request Graphs encl KRICH, R M Consumers Power Co 84/03/26 CRUTCHFIELD.D Operating Reactors Branch 5 4pp 22801 024 24X Fiche 50~105,84/03/26,84/03/26
- 8403290249 Submits add1 info re containment water level & pressure monitoring sys.per 840312 request Power supply voltage variations effect negligible on overall sys accuracy KRICH, R M Consumers Power Co 84/03/26 CRUTCHFIELD.D Operating Reactors Branch 5 1p. 22800 042 24% Fiche 50-155,84/03/26, accuracy
- @ Inspection reports. IE Bulletina & correspondence
- 840i190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche. 50-000.84/02/28, 8401190072
- 8403120131 Responds to IE Bulietin 83-07. "Apparently Fraudulent Products Bold by Ray Miller, Inc " Purchase order records for 1975-79 reviewed & 14 suspect purchase orders found No matis supplied on orders purchased from Ray Miller, Inc JOHNBON, B D Consumers Power Co 84/03/01 KEPPLER, J Q Region 3, DFfice of Director 2pp 22588 238 24% Fiche 50-000.84/03/01, 8403120131
- 8402090007 IE Info Notice 84-i4. "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE.J N Division of QA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 078 24X Fiche 50-000,84/03/02.8402090008
- B402070009 IE Info Notice B4-i5, "Reporting of Radiological Releases"
 Eve list enel
 JURDANAE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. i19pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below NiI Ductility Temp " Svc list encl URBAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8402070024 IE Info Notice 84-07. Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JURDAN. E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07.8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list ent! JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 840207003) JE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 84/03/12 Consolidated Edison Co of New York
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Set list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229, 24% Fiche 50-000,84/03/21,8402090043

- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related
 - #U20Y0044 IE Info Notice 84-20. Tays thre of Relays in Garety-Related Bys "Syz List encl JORDAN.E L Division of Emergency Preparedness & Engineering Rasponse (Post 890103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000.84/03/21.8402070044
- R Periodic operating reports & related correspondence
- 8403080131 "Semiannual Radioactive Efficent Release Rept. Jul-Dec 1983 " NO3000131 "Semiannual Redioactive Efficient Release Rept, Jul-Dec 19: W/B40227 ltr KRICH.R M Consumers Power Co 83/12/31 KEPPLER, J G Region : Office of Director 12pp 22559 166 24X Fiche 50-155.83/12/31 8403080131 Region 3.
- 8403080141 "Annual Operating Rept Occupational Exposure, 1983 " W/840229 KRICH,R M Consumers Power Co 83/12/31 KEPPLER,J G Region Office of Director 4pp 22559 223 24X Fiche 50-155,83/12/31,8403080141 Region 3.
- 840302008B Monthly operating rept for Jan 1984 H/840203 ltr BALCH.L L . HOFFMAN.D P Consumers Power Co 84/01/31 7pp 22442 292 24X Fiche 50-155,84/01/31.8403020088
- 8403300152 Corrected monthly operating rept for Feb 1984 W/840307 itr BALCH.L., HDFFMAN.D P Consumers Power Co 84/02/29 2pp 22819 350 24X Fiche 50-155,84/02/29,8403300152
- B Reportable occurrences, LERs & related correspondence
- 8403080249 Confirmatory action ltr re problems w/Anchor-Darling valves used in reactor depressurization sys Caused by increased closing air pressure to i30 psig resulting in binding Addl testing required

 J.J. C. Region 3, Office of Director 84/03/02 REYNOLDS, J.W.

 Rers Power Co. 2pp. 22556 291 24X Fiche 50-155,84/03/02. KEPPLER, J C Region : Consumers Power Co 8403080249
- 8403120078 Updated PNO-III-84-020A three reactor depressurization sys 9031200/8 Opdated PNO-111-69-020A three reactor depressor: valves failed Caused by binding of disc in seat resulting from increase in closing air pressure Reactor restarted & in site testing conducted DEFAYETTER R Region 3, Office of Director 84/03/06 1 22386 305 24X Fiche 50-135,84/03/06,8403120078
- 8403270066 LER 84-001-00 on 840228, three of four reactor depressurization sys isolation valves failed to operate in open position Caused by increased air supply pressure to gate valve Air pressure reduced W/840322 ltr CASTIOLIONE, L. KRICH, R M Consumers Power Co 84/03/22 22766, 255 24X Fiche 50-155, 84/03/22, 8403270066

DOCKET 50-156 UNIV OF WIBCONSIN RESEARCH REACTOR

H General correspondence

- 8403200020 Informs that JA Franzen & GC Penn removed from appointments As reactor operators at facility MATUBENIC, B M Wisconsin, Univ of, Madison, WI 84/03/15 Standardization & Special Projects Branch 1p 22698 354 24X Fiche 50-156, 84/03/15,840320020
- DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR
- P. Operating license stage documents & correspondence
- B403210124 Application for renewal of License R-70 All future correspondence re license should be addressed to F Kerr. TOLL J B Maryland, Univ of, Coilege Park, MD B4/03/15 THOMAS, C Blandardization & Special Projects Branch 1p. 22707·185 R4X Fiche. 50-166, B4/03/15, B403210124
- --8403210126 Tech Specs for Univ of Maryland training reactor * Maryland, Univ of. College Park, MD 84/03/15 42pp 22707 186. 24X Fiche 50-166,84/03/15,8403210124.

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

Q Adjudicatory correspondence

8403190182 Order granting joint motion for approval of stipulation & withdrawal of intervenor, licensee & NRC motions for summary disposition Adjudicatory proceedings dismissed HOYT,H F. Atomic Bafety and Licensing Board Panel, 84/03/15 Office of the Executive Legal Director 3pp 22670 320 24X Ficha: 50-170,84/03/15,8403190182

- DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1 R Periodic operating reports & related correspondence
- B403230012 "Annual Decommission Rept.1983 " W/840320 ltr FLEISCHMANN.R Philadelphia Electric Co 83/12/31 STOLZ, J F Operating Reactors Brench 4 2pp 22727 357 24X Fiche 30-171.83/12/31.8403230012
- W Decommissioning Stage Documents & Correspondence
- B403230012 "Annual Decommission Rept.1983 " W/840320 ltr FLEISCHMANN,R. Philadelphia Electric Co 83/12/31 t Operating Reactors Branch 4 pp 22727 357 24X Fiche 50-171:83/12/31:8403230012 STOLZ, J F
- DOCKET 50-182 PURDUE UNIV RESEARCH REACTOR
- F Security, medical, emergency & fire protection plans
- 8403190211 Forwards IE Safeguards Insp Repts 30-182/84-01 & 70-0152/84-01 on 840216-17 No noncompliance identified AXELSON, W. L. Region 3, Office of Director 84/03/14 LYKOUDIS, P Purdue Univ , Nest Lafagetts, IN 2pp 22671 109 24X Fichs 50-182,84/03/14,8403190211
- Q Inspection reports. IE Bulletins & correspondence
- 8403190211 Forwards IE Safeguards Insp Repts 50-182/84-01 & 70-0132/84-01 on 840216-17 No noncompliance identified AXELEGIN, W.L. Region 3, Office of Director 84/03/14 LYKGUDIS, P. Purdue Univ., Nest Lafayette, IN 2pp 22671 109 24X Fiche 50-182,84/03/14,8403170211
- DOCKET 50-185 PLUM BROOK REACTOR MOCK-UP
- R Periodic operating reports & related correspondence
- 8403060405 Forwards "Annual Status Rept for 1983," per 810516
- --8403060410 "Annual Status Rept for 1983 "

 * National Aeronautics & Space Admin 84/02/06 8pp 22518 294
 24X Fiche 50-030.84/03/01.8403060405

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

- Q Adjudicatory correspondence
- 8402220157 Order extending time until 840228 for Commission to act to review Director's Decision DD-83-14 CHILK.8 J Office of the Secretary of the Commission 84/02/21 Commissioners 1p 22337 362 24X Fiche 50-000,84/02/21, 8402220157
- 8403010238 Order extending time until 840305 for Commission to act to review Director's Decision DD-83-i4 & 831027 decision denying request of Environ Policy Inst CHICK, B J Office of the Secretary of the Commission 84/02/28 Commissioners ip 22434 210 24X Fiche 50-000,84/02/28. 840301023B
- 8403090069 Informs that Commission unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expired Decision became final agency action on 840305 CHILK,8 J Office of the Secretary of the Commission 84/03/06 CELEBREZZE,A J Chio. State of 2pp 22575 350 24X Ficha 50-000,84/03/08,8403090069 84/03/08
- 8403090074 Informs that Commission unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expired Decision became final agency action on 840305 CHILK, B J Office of the Secretary of the Commission 84/03/08 MILLAR, E Environmental Policy Institute ip 22575 292 24X Fichs 50-000,84/03/08.8403090074

- 8403090113 informs of Commission decision not to review Director's Decision DD-83-14 Time for Commission to act expired on 840305 W/o encl
 CHILKE J Defice of the Secretary of the Commission 84/03/08 RESNIKOFF, H Sierra Club 1p 22576 079 24X Fiche 50-000, 84/03/08, 8403090113
- DOCKET 30-206 BAN UNDERE NUCLEAR STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- 8402030338 Forwards revised "Emergency Plan Implementing Procedures. San Onefre Nuclear Generating Station.Units 1.2 & 3 "CRDY.P A Southern Celifornia Edison Co 84/01/27 NRC No Detailed Affiliation Civen ip 22064 013 24X Fiche 50-206.84/01/27.8402030338
- --8402030344 Revised "Emergency Plan Implementing Procedures, San Onofre Nuclear Contrating Station, Units 1,2 & 3 " ANDERSON, C K , PATRISEL O A Southern California Edison Co 84/01/27 525pp 22064 015 24X Fiche 50-206, 84/01/27, 8402030338
- 840305D148 Forwards "Evaplation of Southern California Edison
 Site-Specific Offsite Radiological Emergency Preparadness
 Prompt Alert & Notification Sys Evaluation " Sys adequate to
 alert & notify public in event of accident
 SPECK.B W Federal Emergency Management Agency 84/01/31
 DIRCKB.W J Office of the Executive Director for Operations 1p
 22487 314 24X Fiche 50-206.84/01/31.8403050148
- --8403030172 "Evaluation of Bouthern Celifornia Edison Site-Specific Offsite Radiological Emergency Preparadness Prompt Alert & Notification Sys "
 * Faderal Emergency Management Agency 84/01/05 Aipp 22487 315 24% Fiche 50-206.84/01/31.8403050148
- 8403130031 Ravs to emergency plan implementing procedures, including EPIP S0123-VIII-0 202, "Assignment of Emergency Response Personnel" & S023-VIII-1, "Recognition & Classification of Emergencies" W/B40227 itr
 UENNETT, D D. PEACOR, D H. CROY, P A. Southern Caiifornia Edison Co. 84/02/15 68pp. 22643 207 24X Fiche 50-206.84/02/15.8403150031
- 8402230176 Forwards revised State of CA nuclear power plant emergency response plan
 MEDFORD, M O Southern California Edison Co 84/02/16
 EISENHUT, D 9 Division of Licensing 383pp 22393 001 24X
 Fichs 50-000.84/02/16.8402230176
- --8403020117 Revised State of CA nuclear power plant emergency response plan

 * Callfornia, State of 83/04/30 2901pp 22353 003 24%
 Fiche 50~000,84/02/16,8402230176
- 8403050127 Forwards exemption from 10CFR50. App E. Bection IV F 1 re requirement for state & local participation in annual emergency plan exercise scheduled for 840227 EISENHUT, D 0 Division of Licensing 84/02/29 BASKIN, K P BosENHUT, D 0 Division of G 3pp 22489-165 24X Fiche 50-206.84/02/27,8403050127
- --8403050132 Exemption from IOCFR30, App E. Section IV F t re requirement for state & local participation in annual emergency plan exercise scheduled for 840229 MIRAGLIA.F J Division of Licensing 84/02/29 Southern California Edison Co 3pp 22489 Id8 24X Fiche 50-206.84/02/29, 8403050127
- 8403270256 Forwards Rev 12 to physical security plan Rev withheld (ref 100FR73 21)
 HAYNES, J O. Southern California Edison Co. 84/03/07 MARTIN, J B
 Replan 5. Diffice of Director Rep. 22772 031 24X
 Fiche 50-206.84/03/07.8403270256
- 8403200097 Informs that emergancy operations facility HVAC control logic mod & procedures necessary to implement HVAC isolation completed prior to 840229 commitment date MEDFORD, M 0. Bouthern California Edison Co 84/03/14 EIBENHUT, D 0 Division of Licensing ip 22679 075 24X Fiche 50-208.84/03/14.8403200097.
- 8403220018 Forwards "Updated Fire Hazards Anelysis, Vols 1-4, "
 BABKIN, K.P. Southern California Edison Co. 84/03/19 DENTON, H.R.
 OPFice of Nuclear Reactor Regulation, Director 10pp 22735 238
 24X Fithe 50-206/84/03/19, 8403220018

- --B403220024 "Tests for Fire Protection for Complete Fire Engulfment of Cable Trays & Conduits Containing Grouped Electrical Conductors, Test Rept on Kaowool " CHAILLE,C E Bouthern California Edison Co 78/10/24 7pp 22735 248 24X Fiche 50-206.84/03/19.8403220018
- --8403220027 "Updated Fire Harards Analysis, Vols i-4 "
 # Southern California Edison Co 84/03/19 1178pp 22735 341 24% Fire 50-206, 84/03/19, 8403220018
- 8403270203 Discusses Southern Californie Edison submittal of 1983 revised Stete of CA emergency response pien on behalf of all State of CA plants, incorporating pien into Diablo Canyon Addi planning info will not be developed for Humboldt Bay SCHUYLERJ O Pacific Gas & Electric Co 84/03/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22772 137 24X Fiche 50-000,84/03/22,8403270205
- B403280030 Responds to NRC fire protection review of instelled mods & two areas of nonconformance Corrective actions eddl fire stop installation expected to be complete prior to startup from present outage & pressure verification retested MEDFORD.M D Southern California Edison Co 84/03/26 CRUTCHFIELD.D Operating Reactors Brench 5. 2pp 22777 046 24X Fiche 50-206.84/03/26.8403280030
- 8403290122 Forwards examples of deta output from technical support ctr accident monitoring sys computer supplementing 831110 ltr re containment pressure, water level & hydrogen monitor instrumentation, per NRC request MEDFORD.M O Southern Callfornia Edison Co 84/03/27 CRUTCHFIELD.D Operating Reactors Branch 5 5pp 22806 357 24X Fiche 50-206.84/03/27.8403290122
- H General correspondence
- B40312003B Requests notification whether util committed in writing or orally to counter proposals or mods to integrated living schedule contained in Denton 840208 itr to Baskin BRONSKI,D, MCDDNALD,J E Sierra Club 84/03/05 CRUTCHFIELD,D DFfice of Nuclear Reactor Regulation, Director ip 22590 317 24X Fiche 50-206,84/03/05.8403120038
- B403140063 Requests that HB Stochr be removed from distribution list & that L Bernath be added HULSEY.9 A San Diego Oas & Electric Co 84/03/12 £18ENHUT.D 0 Division of Licensing ip 22655 OB3 24X Fiche 50-206.84/03/12.8403160063
- J Insurance & indemnity information
- B403040395 Forwards Endorsements 100 & 88 to NELIA Policy NF-146 & MAELU Policy MF-38, respectively RDCCO.J Southern California Edison Co 84/02/29 DINITZ.1 Office of Nuclear Reactor Regulation, Director 3pp 22518 152 24X Fiche 50-206, B4/02/29, B403060395
- P Operating license stage documents & correspondence
- 8403020222 Notifies that Class III fee rether than Class II fee appropriate for review of Amend 72 to License DPR-13, since review involved consideration of single safety Issue Remittance of add1 sum requested DIGGS:R M License Fee Management Branch 84/02/27 RAY,H B Bouthern California Edison Co ip 22494 323 24X Fiche 50-206.84/02/27,8403020222
- B40316007B Bummary of B4020B & 09 meetings w/utll.Woodward/Clyde Consultants & Bachtel at site & in Los Angeles.CA, respectively.re BEP Topics II-4 F. "Bettlement of Foundations & Buried Equipment" & III-6 CHENG.T M Systematic Evaluation Program Branch 84/02/27 GRIMES.C i Systematic Evaluation Program Branch 7pp 22662 26B 24X Fichs 50-206.84/02/27.8403160098
- 8403060156 Notification of 840308 meeting w/util in Bethesda, MD to discuss ilcenses 840227 revised integrated living schedule MCKENNA.E Operating Reactors Branch 5 84703702 CRUTCHFIELD, D Operating Reectors Branch 5. 2pp 22513 355 24X Fiche 50-206,84/03/02,8403060156
- 8403070254 Notifies that info re BEP integrated assessment originally scheduled to be submitted by 840305 will not be provided until 840330 due to necessity of further review KRIEGER,R W Southern California Edison Co 84/03/02 CRUTCHFIELD.D Deprating Reactors Branch 5 1p 22547 294 24X Fiche 50-206.84/03/02.8403070254

- 8403090195 Discusses seismic evaluation of structural elements, per 84020B ltr Yiwld displacement of steel beams should be used to calculate ductifity factors instead of calculated plastic moment capacity of beams MIRAGLIA, F J Assistant Director for Safety Assessment 84/03/07 BASKIN, K Southern California Edison Co 4pp 22575 145 24X Fiche 50-206,84/03/07,8403090195
- B403130216 Forwards request for addl info re Proposed Changes 76 & 126 to Tech Specs Info requested within 30 days of ltr date CRUTCHFIELD.D. Operating Reactors Branch 5 B4/03/09 BASKIN, K P Bouthern California Edison Co
- 8403160013 Forwards "Evaluation of Natural Circulation Cooldown Test
 Performed at San Gnofre Nuclear Generating Station "Rept
 provides evaluation of applicability of results to St Lucie
 Unit 2
 WILLIAMS.J W Fiorida Power & Light Co 84/03/13 EISENHUT.D Q
 Division of Licensing Ip 22652 179 24X Fiche 50-000,84/03/13,8403160013
- B40327035B Requests appropriate Class III fee for review of Proposed Change 123 to License DPR-13 dtd B30707 re purging & venting of containment MILLER.W O License Fee Management Branch B4/03/13 MEDFORD.M O Bouthern California Edison Co 2pp 22787 346 24% Fiche 50-206.84/03/13.8403270358
- 8403160251 Notifies that addl time required to process proposed Tech Spec changes re RCB heatup & cooldown curves Submittal expected by 840525 KRIEGER,R W Southern California Edison Co 84/03/14 GRUTCHFIELD,D Operating Reactors Branch 5 ip 22660 123 24X Fiche 50-206,84/03/14,8403160251
- B403220001 Bummary of B40308 meeting w/utils in Bethesda, MD re licensee revised proposal for integrated living schedule submitted by B40227 ltr List of attendees & agenda encl MCKENNA.E Operating Reactors Branch 5 B4/03/20 Operating Reactors Branch 5 B4/03/20, B4/03/20, B4/03/2001
- 840322012; Forwards revised pages to 83:213 submittat of rediclogical effluent Tech Spaces per 840:31 taicon Summary of changes listed MEDFORD.M O Bouthern Celifornia Edison Co 84/03/20 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 22716 217 24X Fiche 50-206.84/03/20.6403220121
- --B403220125 Rsvised pages to radiological effluent Tech Bpecs rs radioactive paseous effluent monitoring instrumentation * Bouthern California Edison Co B4/03/20 5pp 22716 221 24X Fiche: 50-206, B4/03/20, B403220121
- 8403230070 Notification of 840328 meeting w/util in Bethesda, MD to discuss util proposed integrated living schedule MCKENNA, E M Operating Reactors Branch 5 84/03/20 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 22726 328 24X Fiche 30-206.84/03/20,8403230070
- 8403270182 Responds to 840216 ltr re operability of 6-inch butterfly valves used for containment venting Valves do not have to be closed when reactor not in cold shutdown or refueiing mode MEDFORD.M O Bouthern California Edison Co 84/03/27 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 22803 326, 24X Fiche 50-206,84/03/27,8403270182
- 8403290295 Provides justification why limiting uss of Aminch containment vent sys considered unnecessary Bassd on info provided, vent sys demonstrated capable of performing intended isolation function under transient conditions MEDFORD, M O Southern California Edison Co B4/03/27 CRUTCHFIELD, D Operating Reactors Branch 5 5pp 22800.037 24X Fiche, 50-206, 84/03/27, 8403270275
- G. Inspection reports, IE Bulletins & correspondence
- B403080408 FOIA request for repts of insp carried out under Condition 2 of Nuclear Energy Liability policies for facilities CALSOYAB, C D Affiliation Not Assigned B4/02/07 Region 5, Office of Director, App 22567 341 24X Fiche: 50-000, 84/02/07, 8403080408
- 8403060025 Forwards IE Insp Repts 50-206/83-28,50-361/83-43 & 50-362/83-42 on 831210-840121 No noncompliance noted BIBHDP.T W Division of Resident Reactor Project & Engineering Programs 84/02/09 BASKIN.K P Southern Callfornia Edison Co Rpp 22516.285 24X Fiche 50-206,84/02/09.8403060025

- --8403060027 IE Insp Rspts 50-206/83-28,50-361/83-43 & 50-362/83-42 on 831210-840121 Na noncompilance or deviations noted Major areas inspected operational safety verification, power ascension transient testing & maint activities CHAFFEE, A E , STEWART, J P , D'ANGELO, A Region 5, Offics of Director 84/02/07 13pp 22516 287 24X Fiche 50-206,84/02/07,8403060025
- 8403060008 Forwards IE insp Repts 30-206/84-02.50-361/84-02 & 50-362/84-02 on 840115-20 No noncompliance noted WENSLAWERI, F A Region 5. Office of Director 84/02/16 BASKIN, K B Southern California Edison Co 2pp 22516 268 24X Fiche 50-206,84/02/16,8403040008
- --8403040019 IE Insp Repts 50-206/84-02.50-361/84-02 & 50-362/84-02 on 840115-20 No nuncompliance or deviations noted Major areas inspected radiation protection programm health physics & chemistry training & general employee training SHERMAN, C I . WENSLAMSKI, F A Region 5. Office of Director 84/02/15 i5pp 22516 270 24X Fiche 50-206.84/02/16.8403060008
- 8403080417 Responds to FDIA request for rapts of inspicarriad out under Condition 2 to Nuclear Energy Liability policiss for facilities NRC does not have repts FELTON.J M Division of Rules and Records 84/02/22 CALSOYAS, C D Affiliation Not Assigned 1p 22567 345 24X Fiche 50-000.84/02/22,8403080419
- 8401190072 IE info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enci JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401170072
- 8403190367 Forwards IE Insp Repts 50-206/84-04.50-361/84-05 k 50-362/84-05 on 840123-27 No noncompliance noted WENSLAMSKI.F A Region 5. Office of Director 84/03/01 8ASKIN.K B Southern California Edison Co 2pp 22675 220 24X Fiche 50-206.84/03/01.8403190367
- ---8403190373 IE Insp Rspts 50-206/84-04,50-361/84-05 & 50-362/84-05 on 840123-27 No noncompliance noted Major areas inspected, radiological environ monitoring program & followup on licensee action as previous insp findings YUHAS. O F. WENSLAWSKI, F. A. Region 5, Office of Director 84/03/01 & App. 22675 222 24X Fiche. 50-206.84/03/01.8403190367
- 8402090007 IE Info Natice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of GA. Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000.84/03/02,8402090007.
- 8402070008 IE info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Opsrate " Svc list enci JURDAN,E L. Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 078 24X Fiche 50-000,84/03/02,8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Rediological Releases" 8vc list encl JURDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductifity Temp " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402070011
- B402090024 IE Info Notice 84-09,Rsv i, "Lassons Learned From Insps of Fire Protection Bafs Shutdown Sys " Svc list encl, JURDAN,E L Division of Emergancy Preparadnsss & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR 8ys " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. (1889) 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8402070031 IE Bullstin 84-02, "Failures of GE Type HFA Rslays in Use in Class IE Bafety Bys " 8vc list encl DEYQUNO,R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823,074 24X Fiche 50-000,84/03/12,8402070031

- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries anto PWR Reactor Covities " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24% Fiche 50-000,84/03/21,8402090043
- 8402090044 IE into Notice 84-20, "Svc Life of Releys in Safety-Related Sys" Bvc list enc!
 JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24% Fiche 50-000.84/03/21.8402090044

R Periodic operating reports & related correspondence

- 8403060438 "Annual Personnel Monitoring Rept, 1983 " W/840229 ltr HAYNES, J G Southern California Edison Co 83/12/31 4pg 22511 189 24X Fiche 50-206, 83/12/31, 8403060438
- 8403020218 Monthly operating rept for Jan 1784 W/840215 ltr MDRRIS.C A . HAYNES.J G Bouthern California Edison Co App 22440 263 24X Fiche 50-206.84/01/31.8403020218 R4/01/31
- 8403300003 Monthly operating rept for Feb i984 W/840312 ltr MDRRIS.C A . HAYNES, J 0 Southern Callfornia Etison Co B4/02/29 App 22822 i19 24X Fiche 50-204.84/02/29.8403300003
- S Reportable occurrences, LERs & related correspondence
- 84030:045: Informs Commission of problems w/emercentu diesel generators mfg by Transamerica Delaval.inc
 DIRCKS.N J Office of the Executive Director for Operations
 SECY-B3-034 84/01/25 4pp 22438 347 24% Fiche 50-000.84/01/25. B403010451
- 8403010207 Forwards "Investigation of Types AF & AE Piston Stirts." per 403010207 Forwards "Investigation of Types AF & AE Piston Skirts."
 Transamerica Dejaval.inc Duners Group program commitments
 Rept evaluates cracks in AF piston skirts in Shoreham &
 Grand Qu)f Nuclear Power Stations
 MUSELER.W J TDI (Transamerica Dejaval. Inc.) Cumers Group
 MUSELER.W J Long Island Lighting Co 84/02/27 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 3pp 22434 090
 24X Fiche 50-000,84/02/27,8403010207
- 8403140203 Forwards "Operating History Overview for Diesel Cenerators in Nuclear Svc." comparing Transamerica Delavai.inc generators w/generators mfg by other vendors HEBDON.F J Program Technology Branch 84/02/27 BERLINGER.C H NRC No Detalied Affiliation Given 1p 22638 319 24X Fiche 30-000.84/02/27.8403140203
- --8403140205 "Operating History Overview for Diesei Generators in Nuclear Svr " ** Director's Dffice 84/02/29 65pp 22638 320 24X Fishe 50-000, 84/02/27, 8403140203
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Deiaval.Inc omergency diesel generators MUSELER.W J TDI (Transamerica Delaval. Inc.) Owners Group MUSELER.W J Long Island Laghting Co 84/02/28 DENTON, H F Uffice of Nuclear Reactor Regulation, Director 42pp 2243: 24X Fiche 30-000,84/02/28,8403010218 22435 177
- 8403060194 RD on B40118. during 4-month fire detector surveillance. Zone A detector failed to actuate deluge sys in hydrogen seal oil unit area Caused by sticking deluge sys in hydrogen seal oil unit area Caused by sticking deluge solenoid valve Fire watch established & valve repaired HAYNES, J G Southern California Edison Co 84/02/28 MART: Region 5. Office of Director ip 82517 354 24X Fiche 50-206.84/02/28.8403060174 84/02/28 MARTIN, J B
- 6403020275 Responds to reliability survey questions re diesel generator startup & operation Responses to NRC request for addl info re Transamerica Belaval emergency diesel generators will be re transamente ustavus emergenty submitted by B40801 MEDFORD, M G Southern California Edison Co 84/02/27 CRUTCHETTEIN 7 0-1 22440 074 24X

int Evaluation," ablish

76 24X

- B403060399 Provides addl info re reactor coolant gas vent sys.per NUREO-0737. Item II B 1 Sys used to purge nitrogen accumulated in reactor vessel head on B31118 RCS will be vented periodically to reduce nitrogen pressure MEDFORD. H O Bouthern California Edison Co B4/03/02 CRUTCHFIELD. D Operating Reactors Branch 5 3pp 22518 271 24X Fiche 50-206.84/03/02.8403060399
- 8403140048 Forwards "Grand Gulf Component Tracking Sys." "Shoreham Component Tracking Sys" & "Transamerico Delaval Inc Diesel Generators Owners Group Program Plan." to resolve concerns w/emergency diesel generators MUSELER, W J Long Island Lighting Co B4/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22626 (24X Fiche 30-000, 84/03/02, 8403140048 22626 062
- --8403140095 "Transamerica Delaval, Inc Diesel Generators Owners Group ## TDI (Transamerica Delaval, Inc.) Owners Group 84/03/02 261pp 22628 223 24X Fiche 50-000,84/03/02,8403140048
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Owners Group Distribution list encl EISENHUT.D G Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22708 001 24X Fiche 50-000,84/03/12,
- ---8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Owners Group in Bethesda, MD re problems w/emergency
 diesei generators
 CARUSO.R Licensing Branch 2 84/02/27 D'REILLY, J P NRC No
 Detailed Affiliation Given App 22708 004 24X
 Fiche 50-000,84/03/12,8402090037
- --B403060554 Transcript of 840210 meeting w/Transamerica Delaval.Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fich# 50-000,84/03/12,8402090039
- --B403070409 Summary of B40216 meeting W/Transamerica Deiaval, Inc Owners Oroup in Wading River,NY re program plan to establish reliability of diesel generators Agenda.meeting transcript & attendance list enci HILLER,M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24x Fiche 50-000,84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Deiavai, Inc. diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708.169 24X Fiche 50-000,84/03/12,8402090039
- B403140050 Forwards "Design Review of Connecting Hod Bearing Shells for Transamerica Delavai Enterprise Engines" for Shoreham & Grand Guif diesei generators MUSELER, W J Long Island Lighting Co 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22632 074 24% Fiche 50-000, 84/03/12, 8403140050
- B403i50i33 Forwards "Transamerica Delavai, Inc Diesei Generator Rocker Arm Capacrew Btress Analysis Rept " Capacrew design adequate for applicable engines & svc conditions MUSELER: W J TDI (Transamerica Delavai, inc.) Owners Group MUSELER: W J Long Island Lighting Co B4/03/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000, B4/03/13, B403150133
- --8403150154 "Emergency Diesel Generator Rocker Arm Capscrow Stress Analysis," prepared for Transamerica Delavai,inc Owners * Stone & Webster, Inc 84/03/31 27pp 22639 272 24X Fiche 30-000,84/03/13,8403150133
- 8403170376 PNS-V-84-004 on 840314, licenses notified that results of NUMBER OF THE PROPERTY OF THE
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started MATHEWS.C S. Transamerica Delaval, Inc. 84/03/16 EISENHUT.D.O Division of Licensing 20pp 22691 177 24X Fiche 50-000.84/03/16. 8403200222

- 8403210065 LER 84-001-00 on 840215, tear gas drifted onto site Piant & personnel precautions taken Cause unknown Investigation conducted by Marine Corps to determine whether gas came from training exercises at Camp Pendiston W/840316 ltr HAYNES, J G Southern California Edison Co 84/03/16 3pp 22704 357 24X Fiche 50-206.84/03/16.8403210065
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV. 500-750 MVA. 5 kV 350-3,000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL, D D Brown Boveri Corp (subs of Brown Boveri & Ca , Ltd) 84/03/19 Record Services Brench (Document Control Desk) 5pp 22772 114 24X Fiche 50-000,84/03/19.8403270219
- 8403270132 Forwards "Emergency Diesel Generator Air Start Vaive Capscrew Dimension & Stress Analysis," prepared by S&W for Transamsrica Delavai, Inc (TD1) Diesel Generator Guners Oroup MUSELER, W J TDI (Transamerica Delavai, Inc.) Gwners Group MUSELER, W J Long Island Lighting Co. 84/03/23 DENTON, H R Defice of Nuclear Reactor Regulation, Director 2pp 22774 001 DAY Etche 50-000,84/03/23,8403270132
- B403270134 Requests meeting on B4041B to discuss short-term & iong-term corrective actions & investigations re Transamerica Delayal dissel generators List of suggested meeting topics encl
 MCGAUGHY, J P TDI (Transamsrica Delayal, Inc.) Owners Group MCGAUGHY, J P Mississippi Power & Light Co B4/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 22769 133 24X Fichs 90-000, 84/03/23, 8403270134

T Hearing transcripts on non-antitrust matters

- B402090039 Board Notification B4-052 forwards meeting summaries containing transcripts of B40210 & 16 meetings between NRC & Transamerica Deiaval, inc (TD1) Owners Group Distribution list encl.
 EISENHUT, D G Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 R4X Ficha 50-000, 84/03/12, 8402090039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Dslaval, Inc Owners Group in Bethesda, MD re problems w/emsrgency dissel generators CARUBO, R Licensing Branch 2 84/02/27 D'REILLY, J P NRC No Dstailed Affiliation Given App 22708 004 24X Fiche 50-000,84/03/12,8402090039
- ---8403060554 Transcript of 840210 meeting w/Transamerica Delaval.Inc Owners Group in Bethesda.MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 OOB. 24X Fiche 50-000.84/03/12.8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Dwners Group in Wading River, NY re program plan to establish reliability of diesei generators Agenda, meeting transcript & attendance list encl MILLER, d A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24% Fiche 50-000.84/03/12,8402070039
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc diesei generators Pp 1-82 * Commissioners 84/02/16 84pp 22708·169 24X Fiche 50-000, 84/03/12, 8402090039

X Onsite Storage of Low Level Waste

8403060363 Forwards program description for waste classification & form to be used to implement 10cFR61 & 10cFRR0 311 requirements re land disposal of radwaste & stds for protection from radiation
MEDFORD, M O Southern California Edison Co 84/03/02
EISENHUT, D 9 Division of Licensing Bpp 22518 207 24X
Fiche. 30-206,84/03/02,8403060363

DOCKET 30-213 HADDAM NECK PLANT

- F. Security, medical, emergency & fire protection plans
- 8403070289 Public version of Rev 12 to emergency plan. W/receipt form & JM Felton 840307 release memb DUNDFRID, M Connecticut Yankee Atomic Power Co. 83/12/15 EISENHUT, D NRC No Detailed Affiliation Given 209pp 22596 134 24X Fiche 50-213, 83/12/15, 8403070289.

- B403260143 Forwards general position statement on Reg Quide 1 97.Rev 2 re justification of significant general deviations.per NURGO-0737.Suppl 1 COUNSIL.W G. SEARS.C F Northsest Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G. Connecticut Yantes Atomic Power Co B4/02/29 MILLER.J R Operating Reactors Branch 3 CRUTCHFIELD,D Operating Reactors Branch 3 Services 50-000.B4/02/29.B403260143
- --8403260151 General position statement on Reg Quide 1 97,Rev 2 re instrumentation for assessing plant & environ conditions during & following accidents * Northeast Nuclear Energy Co (subs of Northeast Utilities) & Connecticut Yankee Atomic Power Co * Northeast Utilities 84/02/29 69pp 22758 165 24X Fiche 30-000,84/02/29,8403260143
- 8403190243 Notification of 840418 workshop in King of Prussia, PA to discuss issues learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop enc!

 MURLEY, T.E. Region i. Office of Director 84/03/09 D'TOOLE, J D Gonsolidated Edison Co. of New York, Inc. HEIDER, L.H. Yankes Atomic Electric Co. COUNSIL, N. O. Connecticut Yankes Atomic Power Co. 35pp. 22672 062 24X Ficher 50-000, 84/03/09, 8403190243
- 8403260146 Forwards revised procedures for corporate organization for nuclear incidents procedure manual, including Procedure CONI re table of contents & CONI i 05 re corporate emergency operations ctr operations H/o sncl COUNBIL, W Q , SEARB, C F Connecticut Yankee Atomic Power Co COUNBIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) B4/03/07 EISENHUT, D Q Division of Licensing 2pp 22750 330 24X Fiche 50-000,84/03/09,8403260146
- B40327006B Revised smargency plan implementing procedures, including Rev 2! to EPIP 1 5-2 re notification & communication.Rev 3 to EPIP 1 5-43 re parsonnel accountability & Rev 1 to EPIP 1 5-41 rs core damage estimate procedure. W/840309 itr COUNBIL.W 0, SEARS.C F Connecticut Yankee Atomic Power Co B4/03/07 EISENBUT.D 0, Division of Licensing 65pp 22766 262 24X Fichs 50-213,84/03/09,8403270068
- 8403190151 Ack receipt of 840216 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/83-28 MARTIN, T T Division of Engineering & Technical Programs. 84/03/13 COUNBILL W O Connecticut Yanke Atomic Power Co 2pp. 22668 329 R4X Fichs 50-213.84/03/13,8403190151
- --8403170155 Responds to NRC 840120 itr re violations noted in IE Insp Rept 50-213/83-28 Corrective actions two employees who have not received proper training removed from emergency on-call schedule & will not be reassigned until trained CDUNSIL.W Q Connecticut Yankse Atemic Power Co 84/02/16 MARTIN.T T Division of Engineering & Technical Programs 3pp, 22668 331 24X Fiche 50-213,84/03/13,8403190151
- B403270008 Informs that util will provide info re planned deviations from Buppl i to NUREO-0737 by B40501 Pelay has no effect on achedules for implementation of Suppl i to NUREO-0737 COUNSIL.H 0 . BEARR.C F Connecticut Yankes Atomic Power Co COUNSIL.H 0 . Northeast Nuclear Energy Co (subs of Northeast Utilities) B4703/16 EIBENHUTD 0 Division of Licensing 2pp 22770 011 24X Fiche 50-000,84/03/16,8403270008

J Insurance & indemnity information

- 8403140092 Forwards Endorsements 1,2 & 3 to NELIA Certificate N-11 & Endorsements 1,2 & 3 to MAELU Certificate N-11 SIMIBI, J M Marsh & McLennan, Inc. 84/03/05 SALTZMAN, J D. Assistant Director for State & Licensee Relations 25pp 22623;306 24X Fichs 50-213,84/03/05,8403140092.
- 8403140116 Forwards Endorsement 70 to MAELU Policy MF-39 & Endorsements 79 & 80 to NELIA Policy NF-151
 81NIBI, JM Connecticut Yankee Atomic Power Co 84/03/05.
 8ALTZMAN, J D Assistant Director for State & Licenese Relations
 4pp. 22620 334 24% Fiche 50-213,84/03/05,8403140116
- P Operating license stage documents & correspondence
- 8403010340 Corrects incorrect statement re problem associated w/drawing containment air sample using post-accident sampling sys per TMI Itam II B 3, Vaive is motor operated three-way vaive COUNBIL.W.O Connecticut Yankee Atomic Power Co. 83/11/10. MURLEY.T E. Region I. Office of Director. ip 22432 327. 24X Fiche: 50-213,83/11/10,8403010340.
- B403010391 Bummarizes findings from audit of TMI action items during wt of B31024 Item II B 3: "Post-Accident Bempling Sys (PASS): "findings are of most concern Corrective actions listed CDUNBIL, H O: OPEKAJ F Connecticut Yankee Atomic Power Co. B3/11/23 MURLEY, T E Region 1: Office of Director. App 22434 068 24X Fiche 50-213,83/11/23.8403010391

- 8403060325 Forwards MCAP-10433, "Determination of Copper Content of Longitudinal Meld Seams in Intermediate Shell Region of Haddam Neck Reactor Vessel." confirming past estimates of copper content & through-wall distribution COUNSIL.W G Connecticut Yankee Atomic Power Co 84/02/17 CRUTCHFIELD.D Operating Reactors Branch 5 ip 22513 320 24X Fichs 50-213.84/02/17.8403060325
- --8403060326 "Determination of Copper Content of Longitudinal Weld Seams in Intermediate Shell Region of Haddam Neck Reactor Vessel "
 BBOOS: R S . YANICHKO. S E Westinghouse Electric Corp MCAP-10433
 B3/11/30 11pp 22513 321 24X Fiche 50-213, 84/02/17,
 8403060325
- 8403050105 Advises that operability testing of RCS vent valves will be performed per requirements of ASME. Section X1, Subsection IMV-3410, for Category B valves.per NUREG-0737.1tem II B 1 COUNSIL.W G Connecticut Yanise Atomic Power Co COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities B4/02/21 MILLER.J R Operating Reactors Branch 3 CRUTCHFIELD. D Derating Reactors Branch 5 2pp 22488 043 24X Fiche 50-000, 84/02/21, 8403050105
- B403070003 Requests, within 15 days, fee for 831024 application for amend to Tech Specs re operator staffing DIGOS,R M License Fee Management Branch B4/02/24 CDUNSIL, W G Connecticut Yankee Atomic Power Co 1p 22562 352 24X Fiche 50-213,84/02/24,8403070003
- 8403010384 Forwards SER for SEP Topic II-3 C, "UHS " Issue adequately resolved based on review of 831114 ltr Resolution will be incorporated in suppl to integrated plant safety assessment rept (NUREO-0826) CRUTCHFIELD.D Operating Reactors Branch 5 84/02/28 COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 6pp 22434 061 24X Fichs 50-213.84/02/28.8403010384
- 8403140014 Discusses review of post-TMI periodic testing program including containment atmosphere sampling portion of past-accident sampling sys.normal containment gas sampling sys in integrated test unnecessary CDUNSIL.W G. SEARS.C F. Connecticut Vankee Atomic Power Co 84/02/29 CRUTCHFIELD.D. Operating Reactors Branch 5 2pp 22693 288 24X Fiche 50-213,84/02/29.8403140014
- 8403:30027 Informs that Amends 54,92 & 87 to Licenses DPR-61,DPR-21 & DPR-65, respectively, inadvertently eliminated reporting requirements for exceeding radiological limiting conditions for operation Corrective actions identified COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W G Connecticut Vankee Atomic Power Co COUNSIL,W G Northeast Utilities 84/03/01 MILLER, J R Operating Reactors Branch 3 CRUTCHFIELD,D Operating Reactors Branch 5 4pp 22615 107 247 Fiche 50-000,84/03/01,B403130027
- 8403150350 Notification of 840327 meeting w/util in Bethesda.MD to discuss integrated living schedule MINER.S Operating Reactors Branch 4 84/03/07 STOLZ.J F Operating Reactors Branch 4 2pp 22647 IOB 24X Fiche 50-213.84/03/07.8403150350
- 8403260162 Application to amend License DPR-61 based on granting relief from ASME Code volumetric requirements & visual inap of welds & internal surfaces of reactor coolant pumps Class III license amend fee encl
 COUNSIL, M.G. Connecticut Yantee Atomic Power Co. 84/03/12
 CRUTCHFIELD.D. Operating Reactors Branch 5. 4pp. 22750 349 24X
 Fiche 50-213,84/03/12,8403260162
- 8403260200 Comments on Issue 3 of NUREG-0885, "NRC Policy & Planning Guidance, 1984" Seven themes identified represent important objectives for industry COUNSIL.N @ Northeast Utilities 84/03/12 DIRCKS, N U Defice of the Executive Director for Operations 4pp 22756 204 24K Fichs 50-000,84/03/12,8403260200
- 8403260252 Maintains position that changes in Amend 57 to License DPR-51 re transmission rights-of-way, ministerial in nature, required as matter of law & therefore require no license amend fee COUNSIL.W G Connecticut Yanker Atomic Power Co 84/03/12 HILLERAW D License Fee Management Branch 2pp 22754 311 24X Fichs 50-213,84/03/12,8403260252
- 140329027B Responds to SEP Topic VIII-3 B re dc power sys bus voltage monitoring & annunciation Commitment to provide battery current indication in control room during 1984 refueling outage retracted COUNSIL.W 6 Connecticut Yankee Atomic Power Co 84/03/22 CRUTCHFIELD.D Operating Reactors Brench 5 2pp 22601 330 24X Fiche 50-213,84/03/22,840329027B

- G Inspection reports. IE Bulletins & correspondence
- 8403010399 Forwards IE Insp Rept 50-213/84-02 on 840103-31 No violations observed STAROBIECKI,R Division of Project & Resident Programs 84/02/16 CDUNGIL,W 9 Connecticut Yankee Atomic Power Co 2pp 22434 029 24X Fiche 50-213.84/02/16.8403010399
- --B403010404 IE Insp Rept 50-213/B4-02 on 840103-31 No violations identified Major areas inspected control room, turbine bldg, primary auxiliary bldg & auxiliary feed pump room, plant operations & surveillance testing program SMETLAND.P D Region i, Office of Director ELSASSER.T C Division of Project & Resident Programs 84/02/16 15pp 22434 031 24X Fiche 50-213.84/02/16.8403010379
- 8401170072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22707 237 24X Fiche 50-000,84/02/28,8401170072
- 8403070137 Informs that util does not intend to perform mechanical snubber functional testing referenced in ASME Code as part of inservice insplaying refueling outage Testing will be performed upon equipment delivery COUNSIL.W 9 . DPEKA.J F Connecticut Yankee Atomic Power Co 84/02/28 CRUTCHFIELD.D Dperating Reactors Branch 5 2pp 22375 060 24X Fiche 50-213.84/02/28.8403070137
- B402090007 IE Inpo Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Dlvision of GA, Safeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329. 24X Fiche 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list and J JURDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp. 22553 098 24X Fiche 50-000-84/03/02,8402070008
- 8402070009 IE Info Notice 84-15. "Reporting of Radiological Releases"
 8vc list encl
 JORDANA, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24% Fichs 50-000.84/03/02.8402070009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below N11 Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402070024 IE Info Nutice 84-07, Rev 1, "Lessons Learned From Insps of Fire Protection Bafe Shutdown Bys " Svc 11st encl JORDAN,E L Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- B40209002B IE Info Notice 84-1B, "Stress Carrosion Cracking in PWR
 Sys " Svc list enc!
 JORDANIE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co of New
 York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403230136 Amends 830510 response to IE Bulletin 82-02.Listed commitments.Including visual exam of RCPB threaded fasteners, deleted due to overly-conservative interpretation of bulletin Future exams will be per ABME Section XI COUNSIL.W 0 . SEARB.C F Connecticut Yankee Atomic Power Co 84/03/07 MRLEY.T E Region i. Office of Director 2pp 22730 140 24X Fiche 50-213.84/03/09.8403230136
- B402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Glass IE Safety Bys " Bvc list encl DEYOUNG, R C Director's Office. Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12,8402090031
- 8403260162 Application to amend License DPR-61 based on granting relief from ABME Code volumetric requirements & visual insport welds & internal surfaces of reactor coolant pumps Class III license amend fee encl COUNBIL.W G Connecticut Yankee Atomic Power Co 84/03/12. CRUTCHFIELD, D Deraking Reactors Branch 5 4pp 22750 349 24X Fiche: 50-213,84/03/12,8403260162

- 8403170151 Ack receipt of 840216 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/83-28
 MARTIN T T Division of Engineering & Technical Programs 84/03/13
 CDUNSIL W O Connecticut Yenkee Atomic Power Co 2pp 28668 329
 24X Fiche 50-213.84/03/13.8403170151
- --8403190155 Responds to NRC 840120 ltr re violations noted in IE Insp
 Rept 50-213/83-28 Corrective actions two employees who have
 not received proper training removed from emergency on-call
 schedule & will not be reassigned until trained
 CDUMBIL.W 0 Connecticut Yankee Atomic Power Co 84/02/16
 MARTIN.T T Division of Englneering & Technical Programs 3pp
 22668 331 24X Fichs 50-213,84/03/13,8403190151
- B403220136 Provides results of reevaluation of performance assessment, per util 831219 itr addressing topics discussed at 831129 SALP mpt meeting Category 1 rating will be assigned to refueling area for Millstone 2 Explains Category 2 ratings MURLEY.T E Region 1. Office of Director 84/03/16 CDUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 22716 047 24X Fichs 50-000.84/03/16.8403220136
- 8402090043 IE Info Notice 84-i9, "Two Evente involving Unauthorized Entries into PMR Reactor Cavities" Svc 11st encl
 JORDAN,E L Division of Emergency Preparedness & Englneering
 Response (Post 830103) 84/03/21 Consolidate Edison Co of New
 York, Inc 123pp 22823 227 24X Fiche 50-000.84/03/21.8402070043
- B402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc lifet encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York,
- E403300144 Responds to IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoitage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Haddam Neck facility uses 31 Westinghouse-type DB breakers CDUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) CDUNSIL.W O CONNECTION OF CO
- 8403300161 Ack receipt of 840301 itr informing NRC of steps taken to correct violations noted in IE insp Rept 50-213/83-26
 MARTIN.T T Division of Engineering & Technical Programs 84/03/23
 COUNSELL, W O Connecticut Yankee Atomic Power Co 2pp 22820 054
 24X Fichs 50-213,84/03/23,8403300161
- --8403300i66 Responds to NRC 840i3i itr re violations noted in IE insp Rept 50-213/83-26 Corrective actions Procedure CHDR i 8 ravised on 840224 to document alternative method of performing filtration & counting of filtration papers COUNSIL.W 0 , BEARS.C F Connecticut Yankes Atomic Power Co 84/03/01 MARTIN.T T Division of Engineering & Technicai Programs 2pp 22820 036 24X Fichs 50-213,84/03/23,8409300161
- R. Periodic operating reports & related correspondence
- B403230022 "Haddam Neck Plant & Milletone Station Units 1 & 2 Annual Rept.1783 " W/840301 itr COUNSIL.W 0, EEARGE, C F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL.W C. Connecticut Yankes Atomic Power Co. B3/12/31 MURLEY, T E. Region 1, Dffice of Director. 348pp 22727 001 24X Fichs 50-000, B3/12/31, 8403230022
- 8403020093 Monthly operating rept for Jan 1984 W/840215 itr UNIKEWICZ,8 , GRAVES,R H Connecticut Yankee Atomic Power Co 84/01/31, 10pp 22442,321 24X Fiche 50-213,84/01/31,8403020093
- 8403300176 Monthly operating rept for Feb 1984 H/B40315 ltr GRAVEB,R H Connecticut Yankes Atomic Power Co 84/02/29 10pp 22820 321, 24% Fiche. 50-213, 84/02/29, 8403300176
- B403130283 Forwards "Semiannual Radioactive Efficient Release Rept. JulDec 1983 "Due to new computerized data base mgt eye,
 calculations of meteorological joint frequency distributions
 & offeits dose estimates delayed until 840430
 GOUNSIL.W 0 , BEARS, C F, Connecticut Yankes Atomic Power Co
 84/03/01 MURLEY, T E Region i Office of Director ip
 67207:324 24X Fiche. 50-213. 84/03/01. 8403130283
- --8403130289 "Bemiannual Radioactive Effluents Release Rept. Jul-Dec 1983 " * Connecticut Yankee Atomic Power Co 83/12/3i 15pp. 22608 002, 24X Fiche: 50-213.84/03/01.8403130283

- S Reportable occurrences. LERs & related correspondence
- 840302023B PND-II-84-020 labor contract w/Intl Brotherhood of Electrical Workes expires at midnight on 840227 Possibility exists that workers will reject contract & not rept to work on 840302 Supervisory personnel will continue operations GREENMAN, E. Region 2. Office of Director LIPINSKI, D. Region 1. Office of Director B4/02/27, 1p. 22440 093 24X Fiche 50-213.84/02/27, 840302023B
- DOCKET 50-219 DYSTER CREEK NUCLEAR POWER PLANT
- F Security, medical, emergency & fire protection plans
- B403:30269 Forwards IE Insp. Rept. 50-2:19/83-26 on 831107-:231 & notice of violation
 STARDSTECKI.R Division of Project & Resident Programs 84/02/27
 FIEDLER,P B General Public Utilities GPU Service Corp. 2pp. 22605 181 24X Fiche 50-219,84/02/27,8403130269
- --8403130272 Notice of violation from inep on 831107-1231 * Region 1, Office of Director 84/02/27 lp 22605 183 24X flche 50-219,84/02/27,8403130269
- --8403130280 IE Insp Rept 50-219/83-26 on B31107-1231 Violation noted failure of Surveillance Procedure 645 6 012. "Fire Pump Functional Test" to incorparate Tech Spec change COMP(IL.C., CONNERS L. Region I, Office of Director B4/02/15 11pp 22605 184 24X Fiche 50-219.84/02/27.8403130269
- B403190243 Notification of B40418 workshop in King of Prussia.PA to discuss issues learned from recent App R fire protection safe shutdown insp & topice described in IE info Notice 84-07 Agenda for workshop enc!

 MURLEY.T E Region 1. Office of Director B4/03/09 O'TDQLE.J D Consolidated Edison Co of New York, Inc KUBER.R W Rochester Gas & Electric Corp KEMPER.J S Philadeiphia Electric Co 35pp 22672 062 24X Fiche 50-000.84/03/09.8403190243
- 8403190063 Forwards 46 oversize drewings submitted in conjunction w/831216 submittal re fire hazards analysis rept & iOCFR50, App R. Section III 6. "Bafety Shutdown Evaluation " Aperture cards are available in POR FIEDLER.P B General Public Utilities QPU Service Corp 84/03/12 CRUTCHFIELD.D Deprating Reactors Branch 5 ip 22673 080 24% Fiche 50-217,84/03/12.8403190063

H General correspondence

- 8403060231 Forwards ordinance prohibiting import of spent nuclear fuel or radwasts for storage within township & regulating storage of spent nuclear fuel & radwasts at facility NRC radwasts at facility NRC radwasts at facility NRC DELO, H A Lacey Township to discuss problem DELO, H A Lacey Township, NJ 84/03/01 DENYON, H R Dffice of Nuclear Reactor Regulation, Director 4pp 22514.161 24X Fiche 50-217,84/03/01,8403060231
- 8403270015 Requests that R Arnold be removed from NRC correspondence distribution list & PR Clark be added as president of OPU J Knubs! should be deleted from "cc" listing as manager of BWR licensing Unity titles should be used in future THORPE, J R General Public Utilities GPU Service Corp. 84/03/26 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp 22806, 205 24X Fiche 50-217,84/03/26,8403270015
- P Operating license stage documents & correspondence
- 8403140340 Summary of 831215 meeting w/GE & Mark I Owners Group in Bethesds.MD re Mark I containment wetwell-dryweil vacuum breaker deelgn methodology SIEOSL.B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 5ipp 22635 198 24X Fichs 50-000.84/02/21. 8403140340
- 8403050070 Forwards Class III fee for Amend 70 to License DFR-i4, per 840210 request THORRE, J.R. General Public Utilities - GPU Service Corp. 84/02/27 DIGGS,R.M. License Fee Management Branch 2pp. 22490 185 24X Fiche 50-219.84/02/27,8403050070
- 8403010290 Notlification of 840307 meeting w/utll in Bethesda.MD to discuss detailed control room design & review process LOMBARDO, J Operating Reactors Branch 5 84/02/29 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 22434-261 24X Fiche 50-219.84/02/29.8403010290

- 27 Forwards corrected Page 3 1-8 (Table 3 1 1) of Amend 71 to pDR-16 Replacement corrects error in Table 3 1 1, ctive Instrumentation Requirements "
- FIELD.D Operating Reactors Branch 5 84/03/05 FIEDLER,P B 41 Public Utilities 0PU Service Corp 3pp 22516 006 24x 50-219.04/03/05.8403060327 IFIELD, D.
- 50328 Corrected Page 3 1-8 (Table 3 1 1) of Amend 71 to License -16.correcting error in Table 3 1 i. "Protective rumentation Requirements"

 IRC No Detailed Affiliation Given 84/03/05 1p 22316 008
- : Fiche 50-219,84/03/05,8403040327
- 99 Forwards info in response to NRC B20630 ltr re NUREO-0737. II B 3. "Post-Accident Bampling Bys " W/three oversite sas Aperture cards are available in PDR R.P B Oeneral Public Utilities OPU Service Corp 84/03/06 HFIELD.D Operating Reactors Branch 5 35pp 22608 246 247 50-219.84/03/06.8403130199
- 194 Forwards request for addl info re full-term DL conversion nn revisus Response requested by 840331 to be consistent version schedule One day site visit tentativaly used for first bk in Apr 1984 HFIELD, D Operating Reactors Branch 5 84/03/07 FIEDLER, P B ral Public Utilities GPU Service Corp 5pp 22559 218 24X 50-219,84/03/07.8403080094

- 297 Approves proposed disposal methods for contaminated ste Evaluation complete HFIELD, D. Operating Reactors Branch 5 84/03/08 FIEDLER.P B ral Public Utilities OPU Service Corp 2pp 22572 204 24X 50-219.84/03/08.8403090297
- OB3 Forwards Rav I to expanded safety parameter display sys) schedule Planned Cycle II refueling outage will rt completion of basic BPDB in 1988 Remaining liation work to be completed during Cycle II refueling ER.P II General Public Utilities OPU Service Corp. 84/03.NHUT, D 0 Division of Licensing 3pp 22642 392 24X 50-217,84/03/07,8403150083 64/03/09
-)203 Forwards ravised page of Tech Spec Change Request 103, parating 878 definition of hot shutdown condition into ing condition for operation action statement (RT,M H General Public Utilities OPU Bervice Corp 84/CHFIELD.D Operating Reactors Branch 5 to 22655 242 50-219.84/03/12.8403160203 64/03/12
- 160204 Revised Tech Specs incorporating STS definition of hot stdown condition into limiting condition for operation tion statement General Public Utilities GPU Service Corp 84/03/12 ip 355 243 24X Fiche 50-219.84/03/12.8403160703
- 0002 Forwards "Ogster Creek Nuclear Generating Station Generic sis of 4160-Voit Buitchgear & 460-Voit Unit Bubstation nets." in response to SEP Topic III-6, "Beismic Design Identical"
- iderations LER.P.D General Public Utilities - OPU Bervice Corp. 84/ TCHFIELD,D Operating Reactors Branch 5 2pp. 22713.001 a 50-219.84/03/13.8403220002 84/03/13
- 220004 "Ogster Creek Nuclear Obserating Station Seismic Analysis 4460-Volt Buitchgear & 460-Volt Unit Substation binets " binets
- 83/11/30 9600 22713 003 MPR Associator, Inc. MPR-794 x Fiche, 50-217, 84/03/13, 8403220002
- 0152 Forward: "Turbine Bldg Tornado Evaluation.SEP Topic III-2 & Yornado Loadings," par request
 N.ER.P B Osneral Public Utilities GPU Bervice Corp 84/03/1
 IYCHFIELD, D. Operating Reactors Branch 5 1p 22714 001 24)
 s 50-219.84/03/13.8403220152 84/03/13
- 1220155 "Turbing Bidg Tornado Evaluation, SEP Topic III-2 Wind & rinadd Loadings "
 General Public Utilities - GPU Service Corp 84/01/31 140pp
 2714 002, 24% Fiche 50-219,84/03/13,8403220152
- 50275 Generic Ltr 84-07 to all licensess of BWRs re procedural isnce for pipe replacement at BWRs Bvc list encl NHUT, D O Bivision of Licensing 84/03/14. Commonwealth on Co 20pp 22823:354, 24X Fiche: 50-000,84/03/14.8403150275
 - 'fies that Class III fee rather than Class IV fee withdrawal of BiOSiS application for Tech core sgray chargers & piping, Refund
 - cense Fee Management Branch 84/03/15 FIEDL Utilities QPU Bervice Corp 1p 22844.306 /03/15.8403300304. FIEDLER, P B

- 8403220012 Forwards responses to listed 831207 requests for info re environ qualification of electrical equipment, including resolution of deficiencies & TMI action plan items (NURED-0737) to be installed at end of Cycle 10 outage FIEDLER.P B General Public Utilities OPU Service Corp 84/03/16 CRUTCHFIELD.D Operating Reactors Branch 5 18pp 22712 343 24: Fichs 30-219.84/03/16.8403220012
- 8403270165 Informs that provisions of Code Cases N-341 & N-356 re
 NDE personnel qualification will be adopted Time period
 for requalification increased to 5 yrs
 FIEDLER,P B General Public Utilities OPU Service Corp 84/03/21
 EISENHUT,D G Division of Licensing ip 22774 146 24X
 Fiche 50-219,84/03/21,8403270165
- 8403280011 Forwards request for add1 info re spent fuel pool expansion Response requested within 15 days CRUTCHFIELD:D Operating Reactors Branch 5 84/03/26 FIEDLER.P B General Public Utilities GPU Service Corp 3pp 22777 079 24x Fiche 50-219.84/03/26.8403280011
- O Inspection reports, IE Builetins & torrespondence
- 8403130269 Forwards 1E Insp Rept 50-219/83-26 on 831107-1231 & notice OBISOMERY FORWARDS IE 1889 Nept to Committee the Committee of Violation
 STAROBTECKL,R Division of Project & Resident Programs 84/02/27
 FIEDLER,P B General Public Utilities - GPU Service Corp 2pp.
 22605 181 24X Fiche 50-219,84/02/27,8403130269
- --8403130272 Notice of violation from insp on 831107-1231 * Region i, Office of Director 84/02/27 ip 22805 183 24X Fiche 30-219.84/02/27,8403130229
- --8403130280 IE Insp Rept 50-219/83-26 on 831107-1231.Violation noted failure of Survillance Procedure 645 6 012, "Fire Pump Functional Test" to incorporate Tech Spec change. CCMB(IL.C. COMNER.E. L. Region 1. Defice of Director 84/02/15 11pp 22605 184 24% Fiche 50-219.84/02/27.8403130869
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Vaive Control Circuits & Annunciation " Byc list UNIONAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239 24X Fiche 50-000:84/02/28,8401190072
- 8403150012 Forwards IE Insp Rept 50-219/84-02 on 840116-20 No violations observed
 MARTIN.T T Division of Engineering & Technical Programs. B4/03/01
 FIEDLER.P B General Public Utilities - GPU Service Corp 2pp
 22641 251 24X Fiche 50-219.84/03/01.8403150012
- ~-B403150017 IE insp Rept 50-219/84-02 on 840116-20 No violations identified Major areas inspected radiation protection program, including personnel selection qualification & training & radiological control technician qualification DRAGDUN.T , BICEHOUSE, H , SHANBAWY, M Region 1, Office of Director B4/02/28 9pp 22641 253 24X Fichs 50-219,84/03/01,8403150012
- B4020900D7 IR Info Natice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list enci ORACE, J N Division of OA: Bafeguards & Inspection Programs (Post B30103) B4703/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000;84/03/02,8402090007
- B402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 078 24X Fiche 50-000,84/03/02.8402070008
- 8402070009 IE Info Notice 84-15, "Reporting of Radiological Releases "
- 840207001i IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E L. Division of Energency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553-336 24X Fiche 50-000,84/03/05,8402070011
- B403090070 Ack receipt of B40127 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-219/B3-25, BELLAMY, R R. Division of Engineering & Technical Programs. B4/03/05 FIEDLER, P.B. General Public Utilities QPU Bervice Corp. 19 22575 289 24% Fiche 50-219.84/03/05.8403090070

- --8403070073 Responds to NRC 831228 ltr re violations noted in IE Insp. Rept 50-219/83-25 Corrective actions chemistry surveillance test program revised to ensure that chemistry surveillances listed & completed as scheduled FIEDLER.P B General Public Utilities OPU Service Corp. 84/01/27 MARTIN.T T Division of Engineering & Technical Programs 2pp 22575 290 24X Fiche 50-219.84/03/05.8403090070
- 8402090024 IE Info Notice 84~09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Cangolideted Edison Co of Naw York, Inc 118pp 22635 047 24X Fiche 50~000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Bys " Byc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22384.186 24X Fiche 30-000,84/03/07,8402090028
- 8403160205 Ack receipt of 840224 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-219/83-27
 MARTIN,T.T Division of Engineering & Technical Programs 84/03/07
 FIEDLER.P B General Public Utilities OPU Bervice Corp 2pp
 22655 216 24X Fichs 50-219,84/03/07.8403160205
- --8403160208 Responds to NRC 840117 itr re violations noted in IE insp Rept 50-219/83-27 Corrective actions supervisors instructed to verify drain plug integrity Temporary rev to Procedure 351 32 submitted for review FIEDLER,P B General Public Utilities - GPU Service Corp 84/02/24 MARTIN.T T Division of Engineering & Technical Programs 3pp 22655 218 24X Fiche 50-219,84/03/07,8403160203
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety 8ys." Svc list encl DEYOUNG,R C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fichs 50-000,84/03/12,8402090031
- 8403290099 Forwards IE insp Rept 50-219/84-04 on 840207-10 No violations observed MARTIN,T T pivision of Engineering & Technical Programs 84/03/13 FIEDLER,P B General Public Utilities GPU Service Corp 2pp 22806 350 24% Fiche 50-219,84/03/13,8403290099
- --8403270104 IE Insp Rept 50-219/84-04 on 840207-10 No viplations identified Major areas inspected inservice insp program GRAYS H., DURR.J., Region 1, Office of Director. 84/03/07 4pp 22804 352 24X Fiche 30-219.84/03/13.8403270079
- 8403200056 Forwards Ray O to "Masonry Wall Failure Consequence Analysis" & "Dyster Creek Generating Station Containment Spray 8ys Assessment re Postulated Collapse of Reactor Bldg Southeast Stairwall Masonry Walls," per IE Bulletin 80-11 FIEDLER,P.B General Public Utilities - GPU Service Corp 84/03/14 CRUTCHFIELD, D Operating Reactors Branch 5 1p 22687 001 24X Fiche 50-219,84/03/14,8403200056.
- --8403200062 Rev O to "Masonry Hall Failure Consequence Analysis"
 BALLARD, M F Impell Corp 02-0370-1132 ROO 83/08/31 116ps
 22687 003 24X Fiche 50-219.84/03/14.8403200056
- ~-8403200067 Rsv O to "Oyster Craek Nuclear Generating Station Containment Spray Sys Assessment re Postulated Collapse of Reactor Bidg Southeast Stairwell Masonry Walls " DE GRASSI.0, MARANTER J Impell Corp 02-0370-1137 ROO 83/10/31 49pp 22687 ii9 24X Fiche 50-219,84/03/14,8403200056
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list and JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp. 22823,229 24X Fiche 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84-20, "Byc Life of Relays in Bafety-Related Bys." Byc list ancl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp. 22733 001 24X Fiche 50-000,84/03/21,8402070044
- 8403280005 Forwards evaluation rept re defarment of masonry wall mode (IE Bulletin 80-ii) Evaluation eddresses only request for defarment of mode to certain walls, not ongoing staff review of IE Bulletin 80-ii responses CRUTCHFIELD.D. Operating Reactors Branch 5 84/03/27 FIEDLER, P. B. General Public Utilities OPU Service Corp. 12pp. 22777 159, 24: Fichs. 50-219, 84/03/27, 8403280005

- R Periodic operating reports & related correspondence
- 8403240074 "Semiannual Effluent Relwate Rept for June-Dec 1983 "
 W/840229 1tr
 FIEDLER P B Qeneral Public Utilities GPU Barvice Corp
 170pp 22749 202 24% Fiche 50-219.83/12/31.8403260074
- 8403020128 Monthly operating rept for Jan 1984 4/840210 ltr BARAN,R , FIEDLER,P B General Public Utilities ~ GPU Bervice Corp 84/01/31 8pp 22442 088 24X Fiche 50-219, 84/01/31, 8403020128
- B403010254 NPDEB noncompliance notification on B40123, discharge—intake temp difference of augment offgas-new radwaste sys cooling water exceeded permit limiting condition of 27 F Svc water pump & HX repaired FIEDLER:P B . DOUGLAS.H General Public Utilities GPU Service Corp 84/02/24 GASTON, J New Jersey, State of 5pp 22432 265 24X Fiche 50-219, 84/02/24, 8403010256
- --8403010261 "NPDES Discharge Monitoring Rept for Jan 1984 "
 FIEDLER,P B General Public Utilities GPU Service Corp
 84/01/31 5pp 22432 270 24X Fiche 50-219.84/02/24.8403010256
- 8403070203 Forwards summary rept of Woodborer Study Program from June 1975 through 1983, per 831108 agreement HEWARD, R W General Public Utilities GPU Service Corp 84/02/28 LOMBARDD, J J NRC No Detailed Affiliation Given 5pp 22538 354 24X Fichs 50-219, 84/02/28, 8403070203
- 8403160057 "NPDES Discharge Monitoring Rept.Feb 1784 " W/840307 ltr FIEDLER.P General Public Utilities - OPU Service Corp 84/02/27 QASTON.J New Jersey, State of 8pp 22652:315 24X Fiche 30-217.84/02/27,8403160057
- B403230119 Forwards 1983 ecological studies rept for 1983 & results of fish kill monitoring program FIEDLER.P B General Public Utilities OPU Service Corp 84/02/29 MURLEY.T E Region i. Office of Director. 1p 22731 001 24X Fiche 50-219.84/02/29.8403230119
- ---8403230123 "Ecological Studies Progress Rept, Sept 1982 Aug 1983 "
 * Ecological Analysts, Inc 83/08/31 50pp 22731 022 24X Fichs 50-219, 84/02/29, 8403230119
- 6403300001 Monthly operating rept for Feb 1984 W/840315 ltr BARAN,R , FIEDLER,P B General Public Utilities - GPU Service Corp 84/02/29 8pp 22822 111 24X Fiche 50-219,84/02/29,8403300001
- 8403230110 Forwards "Study of Woodborer Populations Re Oyster Creek Ownerating Station, 831021-840131," progress rept for 35th quartor FIEDLER, P B General Public Utilities - GPU Service Corp 84/03/16 MURLEY, T E Region 1, Office of Director 1p 22731 072 24X Fiche 50-217, 84/03/16, 8403230110
- --8403230112 "Study of Moodborer Populations Re Dyster Creek Generating Station,831021-840131," progress rept for 35th querter HILLMAN.R E., BELHORE.C I Battelle Memorial Institute, Pacific Northwest Laboratories 84/01/31 24pp 22731 074 24X Ficha 50-219,84/03/16.8403230110
- S Reportable occurrences, LERs & related correspondence
- B305200133 Forwards Technical Review Rept AEOD/T312, "Failure of 5-kV Cable Terminations" Failure probably caused by nick in cable insulation
 CHIRAMAL.M Reactor Operations Analysis Branch B3/05/09
 BEYFRIT.K V Reactor Operations Analysis Branch ip 22789 315
 24X Fiche 50-219-83/05/09-8305200133.
- B4030102% NPDES poncompliance notification temp difference of augment offgaw-new radw water exceeded permit limiting condition r pump & HX repaired FIEDLER, P B . DOUGLAS, M General Public Corp B4702/24 QASTON, J New Jersey, 24X Fiche, 50-219, 84/02/24, 84030102%
- --8403010261 "NPDE8 Discharge M FIEDLER,P B General Publi 84/01/31 %pp 22432 27C

- 403070235 Fallowup Part 21 rept re defective mechanical shubber capstan springs supplied by Pacific Scientific Affected utils listed Purchasers have been notified & advised to work directly w/Pacific Scientific in disposition HOVI.L NPS Industries. Inc 84/02/24 DEYGUNO, R C Director's 07*1cs. Office of Inspection and Enfercement 2pg 22335 279 24X Fichs 50-000.84/02/24,8403070236
- 40313020B PNO-1-84-023 on 840306.worker repairing lights in turbine bldg sustained radioactive contamination on waist & head Incident investigated & critiqued Corrective actions being reviewed by specialist NIMITE, R L . SHANBAKY, M . BELLAMY, R Region 1. Office of Director 84/03/07 1p 22603 056 24% Fiche 50-217.84/03/07.8403130208
- 140327000B PNO-I-84-027 on 840323, through-wall crack discovered on weld on condensate return line from south isolation condenser No repair or replacement plans formulated Facility corrently shut down for refueling & mod TRIPP.L. KEINIO.R Region 1. Office of Director 84/03/23 ip 22803 282 24X Fiche 50-219,84/03/23.8403290008
- 3403300074 PNE-I-84-003 on 840324, male phoned Jersey Central Power & Light Customer Svc Ctr & notified that FFA will start domolishing plants Dyster Creek inplemented emergency contingency plan & TMI increased security awareness MADDEN, W. JOYNER J. Region 1. Office of Director 84/03/26 ip 22822 088 24X Fiche 50-000, 84/03/26, 8403300074

' Operator Examinations

- i40J08023i Submits projected requests for site visits to conduct operator licensing exams through FV87.per 83i22i request & Generic Ltr 83-40
 FIEDLER.P B General Public Utilities GPU Service Corp 84/03/01
 EISENHUT.D 0 Division of Licensing 2pp 22361:032. 24X
 Fiche 50-219.84/03/01,8403080231.
- 1403270165 Informs that provisions of Code Cases N-341 & N-356 re
 NDE personnel qualification will be adopted Time period
 for requalification increased to 5 yrs.
 FIEDLER,P B General Public Utilities GPU Service Corp. 84/03/21
 EIEENIUT.D 0 Division of Licensing ip 22774 146 24X
 Fiche 30-219.84/03/21.8403270165
- DOCKET \$0-220 NINE HILE POINT NUCLEAR STATION, UNIT 1
 . Security, madical, emergency & fire protection plans
- 8403060036 Advises that NRC will not revisu emergency plans to delete private or proprietary info unless specifically requested by licensee.per BIO709 Generic Ltr Bi-27 W/o request.sntire plan will be placed in PDR VASSALLO.D B Operating Reactors Branch 2 84/02/10 RHODE.9 K Niagara Mohawk Power Corp. 2pp 22528 327 24X Fiche 50-220.84/02/10.8403060036
- 8403:30496 Forwards comments on 830930 detailed control room design review program pion per Suppl 1 to NWREG-0737 Specific areas of pion not described in enough detail to ensure that plan will meet requirements, in-progress audit suggested VASSALLO, D D Operating Reactors Branch 2 84702/22 RHDDE, Q K Niagara Mohawk Power Corp 13pp 22617, 348, 24X Fiche 50-220,84/02/22,8403130476
- B403130006 Forwards IE Insp Rept 50-220/83-30 on 831217-840131 No violations observed STAROBIECKI.R Division of Project & Resident Programs. 84/02/27 RHUDE, 0 K Nisgara Mohauk Power Corp 2pp 22615 169 24X Fiche 50-220:84/02/27,8403130006
- --8403130021 IE Insp Rept 50-220/83-30 on B31219-840131 No violations identified Hajor areas inspected licenses action on previous insp findings, operational safety verification, physical security, plant tours & surveillance testing HUDSON-B D , CCLLINS, S J Region S, Office of Director 84/02/22 12pp 22615 171 24X Fiche 50-220.84/02/27,8403130006
- 8403050439 Forwards marked-up procedures generation package for implementing symptom-based emergency operating procedures, per Suppl 1 to NUREO-0737. For comment LEMPOES. TE Niagara Mohawk Power Corp 84/03/01. VASSALLO, D B. Operating Reactors Branch 2 122pp 22508 143 24X
 - tted page rays to Issue 2.Rev O to security & plans. Pages withheld
 - awk Power Corp 84/03/01. MARTIN:T T t Technical Programs ip 22575:354 24X 3090063.

- B403130366 Forwards response to B40112 request for add1 info re NUMEG-0737. Item II B 3, "Post-Accident Sampling Sys " Emergency Procedure EPP-9, "Determination of Core Damage Under Accident Conditions" also enci MANOAN, C V Miagara Mohawk Power Corp B4/03/08 VASSALLO, D G Operating Reactors Branch 2 15pp 22605 010 24X Fiche 50-220, 84/03/08, 8403130386
- --8403130391 Rev 0 to Emergency Procedure EPP-9, "Determination of Core Damage Under Accident Conditions" LEACH,E W. ROMAN, T. W. Miagera Mohauk Power Corp 84/03/31 27pp 22405 025 24X Fiche 50-220,84/03/08,8403130386
- 8403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl MURLEY, T E Region 1. Uffice of Director 84/03/09 0/10DLE, J D Consolidated Edison Co of New York, Inc. KUBER, R W Rochester Oss & Eisectric Corp KEMPER, J S Philadelphia Electric Co 35pp 22672 062 24X fiche 50-000, 84/03/09, 8403190243
- 8403230iià Discusses calculated dose rates due to shine from reactor bldg atmosphere to control room & security bldg following design basis LDCA, per IE Inep Rept 50-220/83-15 Doses not expected to exceed 5 rem during first 8 h following DBA MANGAN, C V Niagara Hohawk Power Corp 84/03/19 VASSALLO, D B Operating Reactors Branch 2 2pg 22730 333 24X Fiche: 50-220, 84/03/19, 8403230116
- 1 Financial information
- 8403290177 Annual Financial Rept 1783 W/840322 ltr HAEHL.J 0 . DGNLON.W J . LEMPGES.T E Niagera Mohawk Power Corp 83/12/31, 41pp 22800 319. 24X Fiche.50-220.83/12/31.8403290177
- J Insurance & indemnity information
- 8403280036 Forwards Endorsement 71 to MAELU Policy MF-46 RUBHMORE J W Niagara Mohawk Power Corp 84/03/22 SALTZMAN, J Assistant Director for Btate & Licensee Relations 2pp 22777 021 24X Fiche 50-220,84/03/22,8403280036
- 8403280047 Forwards Endorsoments 85 & 86 to NELIA Policy NF-161 RUBHMORE, J W. Niagara Mohawk Power Corp. 84/03/22 BALTIMAN, J Assistant Director for State & Licensee Relations 3pp. 22776-359 24X Fiche: 50-220, 84/03/22, 8403280047
- P. Operating license stage documents & correspondence
- 8403140340 Summary of 831215 meeting w/GE & Mark I Owners Group in Bethesds. ND re Mark I conteinment wetwell-drywell vacuum breaker design methodology SIEGEL, B L. Operating Reactors Branch 2 84/02/21 Operating Reactors Iranch 2 3ipp 22635 198 24X Fiche: 50-000, 84/02/21, 8403140340
- 8403060247 Forwards status.plans & schedules per Generic Ltr B3-28, "Required Actions Based on Generic Implications of Balem ATMS Events" ATMS Events "MANOAN, C V Niagara Mohawk Power Corp 84/02/29 VASSALLO, D B Operating Reactors Branch 2 App 22515 195 24X Fiche 50-220,84/02/29,8403060247.
- 8403090040 Remits fee for Tech Spec amend application dtd 840109, per 840125 request MANGAN, CV Niagara Mohawk Power Corp 84/02/29 DIGGS,R M License Fee Management Branch 2pp 22576 005 24X Fiche 50-220,84/02/29,8403090040
- 8403040221 Forwards supplemental clarifying info re spent fuel pool mod, based on review of encls to NRC 840201 ltr providing Amend 54 to License DPR-63 Dose tracking sys will be implemented to maintain control of worker exposures MANGAN, C V Niegara Mohawk Power Corp 84/03/01 VASSALLO, D. B Operating Reactors Branch 2 5pp 22515 172. 24x Fiche, 50-220. 84/03/01, 8403060221
- 8403060446 Advises that offsite dose calculation manual will be submitted by 840307 MANGAN.C V Niegara Mohawk Power Corp 84/03/01 VASSALLO,D,B Operating Reactors Branch 2. 1p 22518.130 24X Fichs.50-220.84/03/01.8403060446.
- 8403120224 Notification of 840315 meeting w/util in Bethesda MD to discuss environ qualification of equipment HERMANN.R A. Operating Reactors Branch 2 84/03/03 VABALLO,D B. Operating Reactors Branch 2 1p 22615.360 24X Fiche 50-220,84/03/03.8403120224.

 Γ_{-1}

- 8403090146 Withdraws 770116 & 0715 applications for amend to License DPR-63 Revised Tech Specs re diesel instrument sutpoint logic & relief valves will be submitted by 840401 MANGAN.C V Niagara Mohawk Power Corp 84/03/05 VASSALLO, D B Operating Reactors Branch 2 lp 22075 048 24X Fiche 50-220, 84/03/05, 8403090146
- 8403120059 Forwards results of safety evaluation of NUREQ-0737, Item II K 3 18 concluding that eliminating high dryweil pressure permissive could increase severity of loss of feedwater transient by actuating automatic depressurization sys MANGAN, C V Niagara Mohawk Power Corp 84/03/06 VASBALLO, D B Operating Reactors Branch 2 Spp 22586 285 24X Fiche 50-220,84/03/06,8403120059
- B403090240 Summary of B40216 meeting w/Northeast Nuclear Energy Co.

 Boston Edison Co.Vermont Yankee Nuclear Power Co & Teledyns
 Engineering Sycs in Waltham. MA re eddl Mark I torus
 structural analysis List of attendees encl

 BMEA.J. J. Operating Reactors Branch 5 SIEGEL. B. Operating
 Reactors Branch 2 8403/07 CRUTCHFIELD. D. Operating Reactors
 Branch 5 4pp 22572 298 24X Fiche 50-000.84/03/07.8403090240
- 8403:30340 Forwards offsite dose calculation manual, per proposed radiological effluent Tech Spec dtd 840201 Response to Frankiin Research Ctr comments re 830301 offsite dose calculation manual also enci LEMPGEB.TE Niagara Mohewk Power Corp 84/03/07 VASSALLO, D 8 Operating Reactors Branch 2 6pp 22607.154 24x Fiche 30-220,84/03/07.8403130340
- --8403130347 "Definite Dose Calculation Manual"
 # Niagara Mohawk Power Corp 84/03/01 B3pp 22607 i60 24X Fiche.50-220,84/03/07,8403130340.
- 8403130386 Forwards response to 840112 request for addi info re NUREQ-0737, Item II B 3, "Post-Accident Eampling Bys " Emergency Procadure EFP-9, "Determination of Core Damage Under Accident Conditions" aiso encl MANGAN.C V Niagara Mohawk Power Corp 84/03/08 VABBALLQ, D B Operating Reactors Branch 2 iJpp. 22605 010 24X Fiche 50-220,84/03/08,8403130386
- --8403130391 Rev O to Emergency Procedure EPP-9. "Determination of Core Damage Under Accident Conditions" LEACH: E W. ROMAN.T W Niagara Mohawk Power Corp 84/03/31 29pp 22605 025 24X Fiche 50-220.84/03/08.8403130386
- 8403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs. 8vc list enci EIBENHUT.D O Division of Licensing B4/03/14 Commonwealth Edison Co 20pp 22823 354, 24% Fiche 50-000.84/03/14.8403150275
- 8403200002 Forwards list of items under review needed to support refueling outage & items not yet submitted by util MANGAN.C V Niagara Mohawk Power Corp 84/03/15 VASEALLD, D D Operating Reactors Branch 2 2pp 22683 361 24X Ficha 50-220,84/03/15,8403200002.
- 8403220129 Forwards Rev i to control room habitability summary rept, per 840131 ltr & TMI Action Plan Item III D 3 4 Main steam line break source term revised to correspond to Tech Bec concentration limit of 25 uCi total iodine per 9 of water LEMP0ES.T E. Niagara Hohawk Power Corp 84/03/19 VABSALLO,D,B Operating Reactors Branch 2 6pp 22716 001 24x Fiche.50-220,84/03/19,8403220129.
- 8403220177 Responds to NRC request to explain operator ection given draft emergency condenser Tech Spec change Operators will take into account plant condition & other indications, besides high radiation signal, before manually isolating sys. MANGAN, CV Niagara Mohawk Power Corp. 84/03/19 VASSALLD, D B Operating Reactors Branch 2 2pp 22717.022 24X Fiche. 50-220,84/03/19,8403220177
- 8403300241 Requests remittance of fee for review of 840113 proposed Tech Spec changes re installation of protective relaying on outside of reactor protection & reactor trip bus motor generator set.

 DIGGS:R M Licanse Fee Management Branch 84/03/19 RHODE, C K Niagera Mohawk Power Corp 1p. 22840 361 24X
 Fiche: 50-220, 84/03/19, 8403300241
- 8403230078 Provides addi info re Type C testing of emergency cooling & reactor cleanup inboard isolation valves & method for extrapolation of leakage test results from reduced pressure to accident pressure.per 83101 Tech Spac amend application MANGAN, C V Niagera Mohawk Power Corp 84/03/20 VASBALLO, D B Operating Reactors Branch 2 2pp 22726 333, 24X Fiche 50-220,84/03/20,8403230078

- 8403270176 Advises that final status rept re equipment qualification arogram to be supplied to Commission by 840601.per 830520 aubmittal HANRAN.C V Niagara Mohawk Power Corp 84/03/20 VASSALLO, D E Opporating Reactors Branch 2 ip 22771 [32 24X Fiche 50-220.84/03/20,8403270176
- 8403300058 Forwards proposed mod to existing logic for automatic initiation of diesei generators upon loss of voltage & degraded voltage Proposed mod involves physicai changes to undervoltage relaying circuits for Powerboards 102 & 103 MANGAN.C V Niagara Mohawk Power Corp 84/03/27 VASSALLO.D D Operating Reactors Branch 2 9pp 22821 103 24X Fiche 50-220,84/03/27,8403300058
- a Inspection reports: IE Bulletins & correspondence
- B403i30006 Forwards iE Insp Rept 50-220/83-30 on 831219-840i3i No violations observed STARDSTECKI.R Division of Project & Resident Programs 84/02/2: RHODE, G K Niagera Mohawk Power Corp 2pp 22615,169 24X Fiche 50-220.84/02/27,8403i30006
- --840313002i IE Insp Rept 50-220/83-30 on 83i219-84013i No violations identified Major areas inspected licensee action on previous insp findings.operational safety verification.physical security.plant tours & surveiliance testing HUDSON.8 D . COLLING.8 J Region i. Office of Director 84/02/22 i2pp 22615 17i 24X Fiche 50-220.84/02/27.8403130006
- 840ii90072 iE Info Notice 84-i3, "Potential Deficiency in Hotor Operated Valve Control Circuits & Annunclation " Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,840ii90072
- 8403260270 Responds to IE Bulletin 83-08 Westinghouse Type DB or DS breakers & GE Type AK-2 breakers, w/undervoltage trip attachments, not in use at facility LEMPGES, TE Niagara Mohawk Power Corp 84/03/01 DEYGUNG, R C Director's Office, Dffice of Inspection and Enforcement ip 22754 282 24X Fiche 50-220,84/03/01,8403260270
- 8402090007 IE Info Notice 84-i4, "Highlights of Recent Transport Regulatory Revs by DOY & NRC " Svc list encl QRACE.J N Division of QA, Sařeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co. of New York, Inc 130pp 22552 329 24X Fiche S0-000,84/03/02.8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list enci
 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 078 24X Fiche 50-000.84/03/02.8402070008
- 8402090009 IE Info Notice 84-i5, "Reporting of Radiological Releases"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Rosponse (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 119pp. 22553 217 24X Ficha 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Reiow Nii Ductility Temp " Bvc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York Inc. 1179p 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8402090024 IE Info Notice 84-09.Rev i. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York Inc 1188p 22635 049 24X Fichs 30-000.84/03/07.8402090024
- 840207002B IE Info Notice 84-iB, "Stress Corresion Cracking in PWR Bys " Bvc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000.84/03/07.8402090028
- 8403120044 Forwards revised inservice insp program Program will incorporate portions of 1980 edition through Minter 1981 addends of Section XI of ABME Boiler & Pressure Vessel Code Personnel qualification per proposed Tech Space encl LEMPGES, T E Niagara Mohawk Power Corp. 84/03/07 VASBALLO, D B Operating Reactors Branch 2 ip 22590 289. 24% Fiche 50-220.84/03/07,8403120044
- --8403120050 Revised "Inservice Insp Program"

 * Nisgara Mohawk Power Corp 84/03/31 4pp 22590 290 24X
 Fiche 50-220.84/03/07.8403120044.

2070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in lass IE Safety Sys " Svc list enc! EYDUNG.R C Director's Dffice. Office of Inspection and nforcement B4/03/12 Conspitated Edison Co. of New York, Inc 34pp 22823 094 24x Fiche 50-000.84/03/12.8402090031

3300295 Requests remittance of fee for final review of 800502 ubmittal & 820730 rev re inservice insp program & requested alief from ASME Code insp requirements
1095.R M License Fee Management Branch 84/03/15 RHODE.0 K lagara Mohawk Power Corp 1p 22844 318 24X iche-50-220.84/03/15.8403300295

3230116 Discusses calculated dose rates due to shine from reactor ldg atmosphere to control room & security bidg following esign basis LOCA,per IE Insp Rept 50-220/83-15 Doses not spected to exceed 5 rem during first 8 h following DBA IANGAN.C V Niegara Mohawk Power Corp 84/03/17 VASSALLO,D 8 perating Reactors Branch 2 2pp 22730 333 24X 1che 50-220,84/03/19,8403230114

2070043 IE Info Notice 84-19, "Two Events Involving Unauthorized otries into PWR Reactor Cavities" Svc list encl
IDRDAN, E L Division of Emergency Preparedness & Engineering
esponse (Post B30103), 84/03/21 Consolidated Edison Co of New
ork, Inc. 123pp. 22823 229 24X Fiche 50-000,84/03/21,8402090043

2090044 IE Info Notice 84-20, "Svc Life of Relays in Sefety-Related ys " Svc list encl ORDAN, E L Division of Emergency Preparedness & Engineering esponse (Post 830103) 84/03/21 Consolidated Edison Co of New ork, Inc. 135pp 22933 001, 24X Fiche 50-000,84/03/21,8402090044

3300151 Responds to IE Bulletin 83-07 re falsification of matlertifications by Ray Miller, Inc Util received no matls rightating from Ray Miller, Inc through any intermediaries isted in IE Bulletin 83-07. Suppl I.
EMPGES.T E Niagara Mchawk Power Corp 84/03/23 MURLEY, T E agion 1. Office of Director 2pp 22820 030. 24X icks 50-220.84/03/23.8403300151

Periodic operating reports & related correspondence

3070194 "Radioactive Effluent Release Semiannual Rept, Jul-Dec 933 " 4/840301 ltr EMPGES,T E Niagara Mohawk Power Corp 83/12/31 MURLEY,T E agion i. Office of Director 52pp 22538 162 24X icha 50-220.83/12/31.8403070194

Reportable occurrences. LERs & related correspondence

3210043 Nonroutine radiological environ operating rept on 840217, horeline sediment samples collected in Nov 1983 indicated oncentrations of Cs-137 & Sr-90 exceeding control sample aires Caused by effluent discharges W/840313 Itm EMPGEB.T E Niagara Mohawk Power Corp 84/02/17 MURLEY.T E egion 1, Dffice of Director. 3pp 22707.039 24X 1che 50-220.84/02/17.8403210043

3140122 Part 21 rept re status update concerning abnormal wear on inear converters Test program underway Results of nysstigation indicate excessive wear caused by hunting of ontrol circuitry GDBON.J P Pacific Air Products Co 84/03/09 Director's ffice. Office of Inspection and Enforcement 7pp 22624.068 24X iche 30-000.84/03/09.8403/40182

3190135 PNS-I-84-002 on 840312, bomb threat received from nidentified caller Site emergency & safeguards contingency lan requirements implemented Public areas & site protected rea searched w/negative findings ADDEN.B , JOYNER.J Region 1, Office of Director 84/03/12 lp 2674-352 24x Fiche 50-220,84/03/12,8403190135.

3220075 EN-84-015 on B40320, notice of violation & proposed mposition of civil penalties in amount of \$180,000 will be ssued to licensee Action based on failure to maintain ontainment integrity & failure to conduct surveillance RAIO.J. AXEERAD.J. Director's Office, Office of Inspection and nforcement 84/03/15 2pp 22712 308. 24% Fiche 50-220,84/03/15,403220075

DOCKET 50-223 UNIV. OF LOWELL RESEARCH REACTOR

G Inspection reports: IE Bulletins & correspondence

B403300165 Act receipt of B40307 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-223/83-02.
STAROSTECKIR Division of Project & Resident Programs. 84/03/26
BEGHIAN:L E Lowell. Univ of Lowell, MA ip 22820 050 24X
Fiche: 50-223,84/03/26.8403300165

--8403300169 Responds to NRC 840209 ltr re violations noted in IE Insp Rept 50-223/83-02 Corrective actions automatic notification issued to committee members & tickler sys installed to measure control & regulating valve intervals BEOHIAN, L. Lowell: Univ of. Lowell: NA. 84/03/07 BTAROSTECKI, R. Division of Project & Resident Programs 2pp 22820 051 24X Fiche 50-223,84/03/26,8403300165

DOCKET 50-224 UNIV OF CALIFORNIA RESEARCH REACTOR

R Pariodic operating reports & related correspondence

B403150115 "Berkeley Research Reactor Annual Rept of Operations, 1983 "
W/840309 ltr
LIM.T H Galifornia, Univ. of, Berkeley, CA 83/12/31, MILLER, J A
Standardization & Special Projects Branch 11pp 22640 048, 24X
Fiche, 50-224,83/12/31,8403150115

DOCKET 50-225 RPI CRITICAL EXPERIMENT

F Security, medical, emergency & fire protection plans

8403060204 Proposed emergency plan for License CX-22 W/840206 itr HICKS,F, HARRIS,D. Rensselaer Polytechnic Institute, Troy, NY 84/02/27 THOMAS.C O Standardization & Special Projects Branch 22pp 22517 154 24X Ficher 30-225.84/02/29,8403060204.

R Periodic operating reports & related correspondence

8403200229 "Annual Rept of Tests & Experiments, Mar 1982 - Feb 1983 " WICKS, F., HARRIS, D. R. Rensselmer Polytechnic Institute, Troy, NY 83/02/28 2pp 22690 164. 24X Fiche 50-225,83/02/28,8403200229

8403260156 "Annual Operating Rept.Mar 1783 - Mar 1784 " WICKS.F., HARRIS.D R Rensselaer Polytechnic Institute, Troy, NY 84/03/01 Region 1, Office of Director. App 22750 339 24X Fithe 50-225.84/03/01.8403260156

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8403050004 Forwards FEMA 840206 ltr & final exercise evaluations on 830914 offsite emergency preparedness exercise. Recommendations from rept do not affect approval of plan PAPERIELLO.C J Region 3, Office of Director 84/02/29 REED.C Commonwealth Edison Co 2pp 22490 240 24X Fiche, 50-237, 84/02/29, 8403030004

8403120053 Advises of 840323 regional workshop in Rosemont, IL w/all Region III licensees to discuss fire protection safe shutdown requirements of 10CFR50. App R Agenda encl. BPESSARD, R L. Division of Emergency Preparedness & Operational Support 84/03/06 REED.C Commonwealth Edison Co 3pp. 22585 222 24X Fiche 50-010,84/03/06,8403120053.

8403150092 Forwards results of improgress audit of detailed control room design review Util pursuing course of review which NRC believes will satisfy requirements of Suppl 1 to NUREO-0737. CRUTCHFIELD, D Operating Reactors Branch 5 84/03/14 FARRAR, D & Commonwealth Edison Co lipp 22643 002, 24X Fiche. 50-237, 84/03/14, 8403150092

Q Adjudicatory correspondence

8402220157 Order extending time until 840228 for Commission to act to review Director's Decision DD-83-14 CHILK: 8 J Office of the Secretary of the Commission 84/02/21. Commissioners ip. 22337.362. 24X Fiche 80-000.84/02/21. 8402220157

- 840301023B Order extending time until 840305 for Commission to act to review Director's Decision DD-B3-14 & B31027 decision denying request of Environ Policy Inst CHILK, B J Dffice of the Secretary of the Commission 84/02/28 Commissioners ip 22434 210 24X Fiche 50-000,84/02/28, 840301023B
- 8403090069 Informs that Commission unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expired Decision became final agency action on 840305 CHILK'S J Office of the Secretary of the Commission 84/03/08 CELEBREZZE, A J Chio, State of 2pp 22575 350 24X Fichs 50-000.84/03/08.8403090069
- 8403090074 Informs that Commission unanimously declined to review Director's Decision DD-B3-14 Time provided by NRC regulations within which Commission may act to review expired Decision became final agency action on 840305 CHILK.B J Office of the Secretary of the Commission 84/03/08 MILLAR, F. Environmental Policy Institute ip 22575 272 24X Fithe 50-000,84/03/08,8403090074
- 8403090113 Informs of Commission decision not to review Director's Decision DD-83-14 Time for Commission to act expired on 840305 W/a encl CHILK, B. J. Office of the Becretary of the Commission 84/03/08 RESNIKOFF, M. Sierra Club ip 22576 079 24X Fiche: 50-000.84/03/08.8403090113
- P Operating license stage documents & correspondence
- 8403090185 Resubmits response to SEP Topic VII-1 A. "Isolation of Reactor Protection Sys from Nonsafety Sys, Including Qualification of Isolation Devices" Page 2 omitted from original response RYSAK, B. Commonwealth Edison Co. 84/02/15 CHERY, D. Division of Licensing ip 22368 319 24X Fiche 50-237, B4/02/15, 8403090185
- ---8403090191 Responds to SEP Topic VII-1 A. "Isolation of Reactor Protection 8ys from Nonsafety Sys.Including Quailfication of Isolation Devices" APRM inputs will have Class IE isolators rated at i meg-ohm w/separate power supplies RYBAK.B Commonwealth Edison Co 1378A 83/08/03 OILBERT.R Operating Reactors Brench 5 4pp 22548 320 24X Fiche 50-237.84/02/15.8403090185
- --8403090194 Forwards info re BEP Topic VII-1 A, "Isolation of Reactor Protection Sys from Nonsafety Sys. Including Qualification of Isolation Devices," in response to 801022 request JANECEK, R F Commonwealth Edison Co 81/01/21 LAINAS, G C Assistant Director for Safety Assessment. 22pp 22548, 324 24X Fiche 50-237, 84/02/15, 8403090185
- 8403020037 Notification of contract execution "Dresden & Perry Bimulator Leasing," Awarded to GE
 JESBUP, B Technical Assistance Contracts Branch FIN 8-8713
 84/02/17 HAVINS,O H. Director's Office, Office of Inspection and Enforcement 1p. 22491 045 R4X Fiche 50-000,84/02/17,8403020037
- --8403020043 Contract "Dresden & Perry Simulator Leasing." awarded to QE PIERCE,R L. General Electric Co. MORTON,K V. Division of Contracts FIN 8-8713 84/02/17 38pp 22491 046 24X Fiche 50-000,84/02/17,8403020037
- 8403140340 Bummary of 831215 meeting w/GE & Mark I Owners Group in Bethesde, MD re Mark I containment wetweil-dryweli vacuum breaker design methodology. SIEGEL, B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2, 5ipp. 22635 198 24X Fiche 50-000,84/02/21, 8403140340
- 84030501i9 Forwards supplemental response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Balem ATHS Events"

 PARNES, F. L. Commonwealth Edison Co. 84/02/29 DENTON, H. R. Defice of Nuclear Reactor Regulation, Director 26pp 22488 084 24X Fiche: 50-000, 84/02/29, 8403035019.
- 8403130070 Forwards proposed resolution of environ qualification BER & Franklin Research Ctr technical evaluation rept open item deficiencies Final BER should be issued to indicate resolution of progrem deficiencies.

 RYBAK, B Commonwealth Edison Co 84/02/29, DENTON, H R, Office of Nuclear Reactor Regulation, Director, 44pp 22402'123 24X Fiche, 50-237, 84/02/29, 8403130070

- 8403130400 Forwards 840210 responses to Generic Ltr 83-35 clarifying TMI Itam II K 3 31 Util concurs w/NRC position Item should be closed RYBAK.B Commonwealth Edison Co 84/03/02 EISENBUT, D Q Division of Licensing 2pp 22613 143 24X Fiche 50-000, 84/03/02, 2403130400
- 8403i30410 Application for amend to Licenses DPR-i9 & DPR-25, revising Tech Spec Table 3 7 i to require min addition of four LPCI & two torus spray suction valves RYBAK.B Commonwealth Edison Co 84/03/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 226i6 05i 24X Fiche 50-237,84/03/05,8403i304i0
- ---8403130418 Proposed changes to Tech Spec Yabie 3 7 1 to require min addition of Four LPCI & two torus spray suction valves * Commonwealth Edison Co 84/03/05 10pp 22616 053 24X Fichs 50-237, 84/03/05, 8403130410
- B403190040 Forwards request for add1 info to support conclusions recurrent design codes & criteria & load combinations in B20802 ltr per integrated plant safety assessment rept (NUREO-0823)
 CRUTCHFIELD.D Operating Reactors Branch 5 84/03/09 FARRAR.D L Commonwealth Edison Co 8pp 22643 084 24X Fiche 50-237.84/03/09.8403180040
- --8403150045 "Review of Licensee Response to Design Codes, Design Criteria & Loading Combinations, Dresden Nuclear Power Statton Unit 2," draft supplemental technical evaluation rept STILHELL, T C , DARWISH, M , WALLO, E W Franklin Institute/Franklin Rassarch Center NRC-03-81-130 TER-C5506-425 83/11/15 PERBINKO, D NRC No Datailed Afficiation Given 36pp 22643 092 24x Fiche 50-237.84/03/09.8403150040
- 8403130275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs 8vc list encl EISENHUT, D. O Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000,84/03/14,8403150275
- 8403220153 Application to amend Licenses DPR-19 & DPR-25, revising Tech Specs to update snubber tables to reflect additions, deletions & other changes RYBAK.B Commonwealth Edison Co 84/03/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 22715 338 24X Ficha 50-237,84/03/15,8403220153
- --B403220158 Proposed Tech Specs updating snubber tables to reflect additions.deletions & other changes * Commonwealth Edison Co B4/03/15 20pp 22715 341 24X Fiche.50-237.84/03/15,8403220153
- B403270130 Application for amend to License DPR-25, changing Tech Spect to extend certain MAPLHGR curves to 40,000 MWd/ST.

 RYBAK.B Commonwealth Edison Co 84/03/19 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 22774 129 24X Fiche 50-000,84/03/19,8403270130
- --B403270136 Errata & Addenda Bheet 9, replacing Page 4-14 to "LOCA Analysis Rept Por Dresden Units 2 & 3 & Guad Cities i & 2 Nuclear Power Stations "

 * General Electric Co NEOD-24146A ERR 09 83/01/31 2pp 22774 135 24X Fiche, 50-000, 84/03/19, 8403270130
- 8403220047 Forwards corrected Page 45 to Amends 81 & 73 to Licenses DPR-19 & DPR-25, respectively, which failed to include Footnote it re verification of time delay setting between 3 & 9 s
 CRUTCHFIELD, D Operating Reactors Branch 5 84/03/20 FARRAR, D L Commonwealth Edison Co 4pp 22712 197 24X Fichs 50-237, 84/03/20
- Q Inspection reports, IE Bulletins & correspondence
- B403120134 Forwards IE Insp Repts 50-237/84-01, 50-249/84-01, 50-254/84-01, 50-255/84-01, 50-259/84-01 & 50-304/84-01 on B40203-14 No noncompliance identified BHAFER; W D Region 3, Office of Director 84/02/23 REED, C. Commonwealth Edison Co 2pp 22590 090 24X Fiche 50-000, 84/02/23. B403120134
- --8403120137 IE Insp Repts 50-237/84-01,50-249/84-01,50-254/84-01, 50-265/84-01,50-275/84-01 & 50-304/84-01 on 840203-14 No noncompitance or deviations identified Major areas inspected allegations of improper operation CHRISGOTINOS,N, TONGUE,T, HOLZMER,M Region 3, Office of Director 84/02/21 4pp 22570 072 24X Fiche 50-000,84/02/23,8403120134

- 8403050043 Forwards Rev O to Corporate Regulatory Performance Improvement Plan " Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance
 THOMAS. 8 Commonwealth Edison Co 84/02/24 KEPPLER. J G Region 3. Office of Director 3pp 22470 139 24x Fiche 50-000,84/02/24,8403050043
- --8403050044 Rev O to "Corporate Regulatory Performance Improvement Plan" * Commonwealth Edison Co 84/02/29 22pp 22490 142 24X Fiche 50-000, 84/02/24, 8403050043
- 8403120070 Forwards 1E Insp Rept 50-237/84-02 on 840110-26 & notice of violation of Violation of Project & Resident Programs 84/02/24 REED.C Communumenth Edison Co 2pp 22591 133 24X Fiche 50-237.84/02/24.8403120070
- --8403120073 Notice of violation from lnsp on 840110-26 NORELIUS.C E Division of Project & Resident Programs 2pp 22591 133 24% Fiche 50-237.84/02/24.8403120070
- --8403120079 IE Insp Rept 50-237/84-02 on 840110-26 Noncompliance noted failure to follow control rod sequence procedure & out-of-svc procedure resulting in skipping 20 steps TONGUE, T M. 6TASEK.S. WALKER.R D. Region 3. Office of Director 84/02/22 8pp 22591 137 24X Fiche 50-237.84/02/24.8403120070
- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc 11st encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22707 237 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc 11st encl GRACE, J N Division of GA, Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24% Fiche 50-000,84/03/02,8402090007
- 8402090000 IR Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases" Svc list encl JORDAN.E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consultdated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02, 8402090009
- 8402090011 [E Info Notice 84-17, "Problems W/Llquid Nitragen Cooling Components Below NI! Ductility Temp " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24% Fiche 50-000, 84/03/05, 8402090011
- 8402090024 IE info Natice 84-09.Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list encl JORDAN, Et. Davision of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consultdated Edison Co of New York, Inc (18pp 22584 186 24X Fiche 50-000, 84/03/07, 8402090028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys "Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24X Fiche 50-000,84/03/12,8402070031
- 8403230088 Ack receipt of regulatory performance improvement plan Periodic meetings requested to discuss progress on program & provide feedback KEPPLER, J G Region J, Office of Director 84/03/20 THQMAS, B Commonwealth Edison Co ip 2273D 161 24X Fiche. 50-000, 84/03/20, 8403230088
- --B403230107 Forwards corporate regulatory performance improvement plan THOMAS, B. Commonwealth Edison Co. B4/02/24 KEPPLER, J. G. Region G. Office of Director. 3pp. 22730 162. 24X Fiche 50-000, B4/03/20.840323008B

11

- --8403230124 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden, Guad Cities, Zion & LaBaile Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations "
 + Commonwealth Edison Co 84/02/29 22pp 22730 165 24X Fiche 50-000,84/03/20,8403230088
- 8403260196 Forwards responses to IE Bulletin 83-07. "Apparently Fraudulent Products Sold by Ray Miller. Inc " Guad Cities supplied w/p/ping metls from Ray Miller. Inc during const Evaluation encl Concerns of IE Bulletin 83-06 satisfied BARNES, P. L. Commonwealth Edison Co. 84/03/20 KEPPLER, J. O. Region 3, Office of Director 19pp 22756 185 24X Fiche 50-000, 84/03/20, 840320.0196
- 8402090043 IE lnfo Notice 84~19, "Two Events Involving Unauthorized Entries Into PWR Reactor Cavities" Svc list encl
 JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 829 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84~20, "Svc Life of Relays in Safety-Related Bys " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24% Fiche 50-000,84/03/21,8402090044
- 8403270114 EN-83-076A on 840323, order imposing civil monetary penelties in amount of \$50,000 Action based on failure to classify torus-to-drywell vacuum breaker actuation arm shaft seals under App B hitigation of 831115 penalty underranted KLINGLER,0 , AXELRAD,J Director's Office, Office of Inspection and Enforcement 84/03/23 ip 22774 051 24X Fichs 50-237,84/03/23,8403270114.
- R Periodic operating reports & related correspondence
- 8403060099 "Rept of Radioactive Effluents, Jul-Dec 1983 " W/B40215 itr SCDTT,D J Gommonwealth Edison Co 83/12/31 KEPPLER, J G Region 3, Office of Director 17pp 22506 245 24x Fiche 50~010,83/12/31, 8403060099
- B4030B0197 "Rept of Occupational Personnel Radiation Doses,1983 "
 W/B40227 ltr
 SCOTT, J S Commonwealth Edison Co 83/12/31 CASE,E G Office of
 Nuclear Reactor Regulation, Director 13pp 22559 099 24X
 Fichs 50-000,83/12/31,8403080197.
- B403220120 Annual whole body external exposures for 1983 W/B40316 ltr RYBAK.B. Commonwealth Edison Co B3/12/31 7pp 22716 007 24X Fiche 50-000.B3/12/31,B403220120
- B403130015 Monthly operating repts for Feb 1984 W/840301 1tr SCHROEDER, B A , SCOTT, D J Commonwealth Edison Co 84/02/29 17pp 22614 344 24x Fichs 50-237,84/02/29,8403130015
- S Reportable occurrences. LERs & related correspondence
- 8403270089 Supplemental LER 83-080/03X-1 on 831124, offgas log rad monitor 2-1705-A delivered offgas high elarm & high alarm spiked & drifted downscale Caused by burned out resistor Power supply installed & monitor calibr. WHA0307 itr WOUTULENICZ, T. SCOTT, D. J. Commonwealth Edison Co. 83/12/20 KEPPLERJ G. Region 3. Offsice of Director 3pp. 22766-252, 24x Fiche 50-237,83/12/20,8403270089.
- 8403230076 Updated LER 83-012/01x-1 on 830210, while conducting routine mechanical snubber test main steam line mechanical snubbers 44.46.30.51 & 53 found inoperable Thorough investigation revealed no cause Enubbers replaced W/840302 ltr SCHROEDER, D. MIRDCHNA, R., SCOTT, D. J. Commonwealth Edison Co 84/03/02 KEPPLER, J. G. Region 3, Office of Director App. 22730 125 24X Fiche, 50-237, 84/03/02, 8403230076
- 8403270056 Updated LER 83-084/03X-1 on 831230, during normal operation, primary containment oxygen sample from torus alarmed on low level sample flow Caused by sample line moisture Line drained & leads reconnected W/840314 tr.

 BERGAN, G W , SCOTT, D. J Commonwealth Edison Co 84/03/14, KEPPLER, J Q Region 3, Office of Director 3pp. 22766:136 24X Fiche 50-237,84/03/14,8403270056
- 8403240240 LER 84-003-00 on 840221, core spray valve M02-1402-25A failed to operate from control room Caused by cracked bearing race & gear housing Work requests written to modify existing circuitry W/840319 ltr COYLE, L., SCOTT, D. J. Commonwealth Edison Co. 84/03/19 4pp 22754 359, 24X Fiche 50-237,84/03/19,8403240260

8403260223 LER 84-004-00 on 840222, during Core Spray Vaive Operability Test DOS 1400-2, core spray suction vaive MD-2-1402-3A failed to close from control room Caused by faulty auxiliary breaker contact Contacts replaced W/840320 ltr COYLEL, 860TT,D J Commonwealth Edison Co 84/03/20 4pp 22736 086 24% Fiche 50-237,84/03/20,8403260223

DOCKET BO-238 NUCLEAR SHIP BAVANNAH

- R Periodic operating reports & related correspondence
- 8403050111 Forwards "Semiannual Survey Rept TLD Monitoring Rept, Direct Radiation Survey & Containment Survey Results & Environ Bample Analysis Rept.820916-831031 "

 QUERRY, J E Commerce, Dept of, Maritime Administration 84/02/29 NRC No Detailed Affiliation Olven 2pp 22487 271 24X

 Fiche 50-239.84/02/29,8403050111
- --8403050i13 "Semiannual Survey Rept'TLD Monitoring Rept, Direct Radiation Survey & Containment Survey Results & Environ Sample Analysis Rept, 820916-831031 " * Bouth Carolina, State of 83/10/31 27pp 22487 273 24X Fichs 50-238, 84/02/29, 8403050111

DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT i

F Security, medical, emergency & fire protection plans

- 8403060290 Summary of 840222 meeting w/util & Bechtel re proposed App R exemption requests & alternative shutdown sys Meeting agenda & list of attendees enci DICK, OF Diperating Reactors Branch 5 84/02/27. Operating Reactors Branch 5 5pp 22519 163 24x Fiche 50-244:84/02/27, 84040160390
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss Issabns learned from recent App R fire protection safe shuddown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl MURLEY.TE Region 1. Office of Director 84/03/09 O'TOOLE, J D Consolidated Edison Co of New York. Inc POLLOCK, M S Long Island Lighting Co UDERITY Public Service Electric & Qas Co of New Jersey 35pp 22672 062 24X Fiche 50-000,84/03/09,8403190243
- 8403240243 Revised emergency plan implementing procedures, including Procedure SC-410 re insp of emergency equipment Procedure SC-422 re maining emergency survey ctr & Procedure SC-312 re maining operation support ctr W/840320 Itr # Rochester Gas & Electric Corp 84/03/20 MURLEY, T E Region i. Office of Director 27pp 22754 327 24X Fichs 50-244.84/03/20.8403240243
- J Insurance & indemnity information
- B403140078 Forwards Endorsement 79 to MAELU Policy MF-47 & Endorsements 93 & 94 to NELIA Policy NF-170, SINISI.J K Marsh & McLennan, Inc. 84/03/05 SALTZMAN, J D Assistant Director for State & Licensee Relations 4pp 22634
- D Advisory Committee on Reactor Bafeguards reports & correspondence
- B403280335 Summary of ACRE Subcommittee on RE Qinna B31116 meeting w/ utils.Qilbert Assoc, Westinghouse, KMC, Inc., Taylor Assoc & LeBoeuf, Lamb, Leiby & MacRae in Washington, DC re application to convert provisional DL to full-term QL ACRE Advisory Committee on Reactor Safeguards, B4/02/10 ACRE Advisory Committee on Reactor Bafeguards 20pp 22807, 239 24X Ficher 50-244, B4/02/10, B403280335
- P Operating license stage documents & correspondence
- 8403060115 Forwards add1 info in support of 831110 Tech 8pec change request re use of technical support ctr battery in place of one Class IE battery for brief period KOBER, R W Rochester Cas & Electric Corp 84/02/29 CRUTCHFIELD, D Operating Reactors Branch 5 2pp. 22518 086 24X Fiche 50-244,84/02/29,840306015
- --8403060126 Rev 2 to Procedure EWR 3378, "Design Criteria Ginna Station Technical Support Ctr Battery Vital Battery Intertie "W/two oversize drawings. Aperture cards are available in PDR SHITH, J H. ANDERBON, C R. DANIELS. C. W. Rochester Cas & Electric Corp 62/11/11. 11pp 22518, 088 24X Fiche 50-244, 84/02/27, 8403060115

- 8403160158 Notification of 840315 meeting w/util. Applied Research Assoc & Q11bert Assoc in Bethesda. MD to discuss site-specific tornado parameters & structural upgrade program PERSINKO. D Systematic Evaluation Program Branch 84/03/07 ORIMES. C I Bystematic Evaluation Program Branch ip 22662 266 24X Fiche 50-244.84/03/07.8403160158
- 8403280122 Summary of \$40224 meeting w/Westinghouse Owners Group in Bathasda,MD re proposed Westinghouse steam generator tube rupture generic program Attendee 11st & agenda encl NERSES,V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp 22811 131 24X Fiche 50-000,84/03/07,8403280122
- 8403130225 Advises of plan for resolving upper plenum injection issue involving ECCB models by Westinghouse & Erron for calculating ECCB performance of Westinghouse two-loop plants Response to upcoming SER due 70 days after issuance CRUTCHFIELD, D. Operating Reactors Branch 5 84/03/07 KOBER, R W Rochester Gas & Electric Corp. 3pp 22606 060 24X Fiche 90-244,84/03/09,8403130225
- 8403210135 Forwards notice of consideration of issuance of amend to License DPR~18 & proposed NSHC determination & opportunity for hearing on 831220 request for Tech Spec change re fuel design CRUTCHFIELD, D. Operating Reactors Branch 5 84/03/19 KOBER, R W. Rochester Oas & Electric Corp. 2pp. 22707 238 24X Fiche 30-244, 84/03/19, 8409210135
- --8403210143 Notice of consideration of issuance of amend to License DPR-18 & proposed NSHC determination & opportunity for hearing re-proposed fuel design change CRUTCHFIELD, D. Operating Reactors Granch 5 84/03/15 lipp 22707 240 24X Fiche 50-244.84/03/19.8403210135
- 840326019B Forwards proprietary responses to MRC questions re util application for amend to Tech Specs dtd Dec 1983 & application for withholding info Info withheld (ref 10CFR2 790)
 KDEER: R W Rochester Gas & Electric Corp 84/03/19 CRUTCHFIELD, D Operating Reactors Branch 5 ip 22754 099 24X
 Fiche. 30-244:84/03/19:8403260198
- --8403260201 Application for withholding proprietory responses to questions re applications for amend to Tech Specs dtd Dec 1983 HIBBEHANN,R A Westinghouse Electric Corp 84/03/16 PENTON.H R Office of Nuclear Reactor Regulation, Director 11pp 22756 100 24X Fiche 50-244.84/03/19.8403260198
- 8403280069 Discusses installation & NDE of steam generator tubesheet sleeves Approval to install 10 addi sleeves based on inspresults requested.

 KDBER, R Rochester Gas & Electric Corp. 84/03/23 CRUTCHFIELD, R Operating Reactors Branch 5 5pp. 22776 344 24X Fiche 50-244,84/03/23.8403280069
- 8403270185 Forwards "Containment Vessel Tendons" & "Containment Vessel Tendons Stress Relaxation " completing response to Comments 8 & 11a.per NRC 830308 ltr Response to Comment 10 expected by 840401 KOBER.R W Rochester Gas & Electric Corp 84/03/24 CRUTCHFIELD, D Dpersting Reactors Branch 5 2pp 22801 028 24X Fichs 50-244,84/03/26,8403270185
- --8403270189 "Containment Vessel Tendons Stress Relaxation Properties of Retensioned Wires " FULTON, J F, HBIEH, S 8, HERR, J, C Q(1bert Associator, Inc QAI 2497 83/12/31 120pp 22801 127 24% Fiche 50-244,84/03/26, 8403270185
- Q. Inspection reports, iE Bulletins & correspondence
- 8401190072 iE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl. JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22709 239 24% Fiche 50-000.84/02/28, 8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " 8vc list encl. GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Compsidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000.84/03/02,8402090007

- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Oporate" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24% Fiche 50-000.84/03/02.8402070008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases" Svt fist encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Rusponse (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 117pp 22553 217 24X Fiche 50-000.84/03/02.8402090009
- B402070011 IE Info Nutice 84-17, "Problems W/Liquid Nitrogen Goaling Components Below Nil Ductility Temp " Svc list encl JGRDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05, 8402070011
- B4020700R4 IE Info Notice B4-09, Rev 1, "Lessons Learned From insps of Fire Protection Safe Shutdown Sys " Svt list enc! JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07, 8402090024
- B402090028 IE Info Notice B4-18. "Stress Corresion Cracking in PWR
 Bys " Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co. of New
 York, Inc. 118pp 22584 i86 24% Fiche 50-000.84/03/07, B402090028
- B402070031 IE Duietin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Bys " Svc list encl DEYOUNG.R C Director's Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24x Fiche 50-000,84/03/12,8402090031
- 8403270150 Rosponds to IE Bulletin 83-08 re electrical circuit breakers u/undervoitage trip feature in use in safety-related applications other than reactor trip sys No subj circuit breakers in use at facility KDBER.R N Rochester Gas & Electric Corp 84/03/12 MURLEY.T E Region 1. Office of Director ip 22769 150 24X Fiche 50-244.84/03/12.8403270150
- 8402090043 IR Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Syc list encl JORBAN, E L Division of Emergency Preparedness & Engineering Response (Rost 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24% Fiche 50-000,84/03/21.8402090043
- 8402090044 IE info Notice 84-20, "Svt Life of Relays in Safety-Related Bys " Svt list entl JORDAN," L Division of Emorgancy Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22931 OD1 24X Fiche 50-000,84/03/21,8402070044
- 8403270152 Responds to IE Bulletin 83-07 re apparently fraudulent products sold by Ray Millor. Inc. Matls never received directly from Ray Miller & equipment never received from suppliers using Ray Miller matls

 KOBER.R W Rochester Oas & Electric Corp. 84/03/21 MURLEY, T. E. Region I. Office of Director ip. 22769 149 24X

 Fiche 50-244, 84/03/21, 8403270152
- 8403280069 Discusses installation & NDE of steam generator tubesheet sleeves Approval to install 10 add1 sleeves, based on inspresults, requested KODER, R. Rochester Cas & Electric Corp. 84/03/23 CRUTCHFIELD, R. Operating Reactors Branch 5. 3pp. 22776-344. 24X Fichs 30-244,84/03/23,8403280069
- 8403300189 Ack receipt of 840127 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Rept 30-244/83-23 STAROBIECKI: R Division of Project & Resident Programs 84/03/23 KODER, R W Rochester Ges & Electric Corp 2pp 22819 284 24X Fiche 80-244.84/03/23.8403300189
- --8403300171 Responds to NRC 831228 ltr re violations noted in iE lnsp Rept 50-244/83-23 Corrective actions Procedure 8H-2606 5D approved for use on 821203 Training accomplished for all liaison engineers in plant administrative procedures MAIER. J E Rochester Gas & Electric Corp 84/01/27 MURLEY. T E Region 1. Office of Director 6pp 22819 286 24X Fiche 30-244,94/03/23.8403300189
- R Periodic operating reports & related correspondence
- 8403020202 Monthly operating rept for Jan 1984 W/840210 1tr MCNAMARA.A E , SNOW, B A Rochester Gas & Electric Corp B4/01/31 5pp 22440 231 24% Fiche 50-244 84/01/31 8403020202

- B403300081 Monthly operating rept for Feb 1984 W/840310 ltr DDDDE,R E , SNOW, B A Rochester Cas & Electric Corp 84/02/29 4pp 22822 078 24% Fiche 50-244.84/02/29.8403300081
- 8403i30132 Forwards "Effluent & Waste Disposal Semiannual Rept, Jui-Dec 1983," "8td Rept of Personnel Whole Body Exposure (Rem) by Exposure Groups, 1983" & "8td Rept of Personnel & Man-Rem by Work & Job Function, 1983 "
 KOSER, R W Rochester Gas & Electric Corp 84/03/02 MURLEY, T E Region i. Dffice of Director 1p 22600 033 24X
 Fiche 50-244,84/03/02,8403130132
- --8403130142 "Effluent & Waste Disposel Semiannual Rept, Jul-Dec 1983 "

 » Duke Power Co 83/12/31 £2pp 22600 034 24X

 Fiche 30-244,84/03/02,8403130132
- ---B403130149 "Std Rept of Personnel Whole Body Exposure (Rem) by Exposure Oroups: 1983 " * Duke Power Cq 83/12/31 ip 22600 046 24X Fiche 30-244,84/03/02,8403130132
- --8403130137 "Std Rept of Personnel & Man-Rem by Work & Job Function for 1983 "
 - * Duke Pawer Co 83/12/31 1p 22600 047 24X Fiche 30-244,84/03/02,8403130132
- 9 Reportable occurrences. LERs & related correspondence
- 8403260233 Forwards summary list of deficiencies identified per 10CFR50 591e). Part 21 & potential generic ltr repts for comments BTAROSTECKI, R Division of Project & Resident Programs 84/02/28 Rogion 1, Office of Director 7pp 22756; 065 24X Ficho 50~000: 84/02/28.8403260233.

V Operator Examinations

- B403190425 Notification of Bignificant Licenses Meeting B4-23 on 840315 w/util in King of Prussia:PA to discuss Region I evaluation of icensed operator requalification program COLLING:B J Assistant Director for Operating Reactors B4/03/08 DIRCKS:W Dffice of the Executive Director for Operations DEYOUNO:R Director's Office. Office of Inspection and Enforcement EISENHUT,D Division of Licensing ip 22681 331 24X Ficho 50-244.84/03/08.8403190425
- DOCKET 50-245 MillStone NUCLEAR POWER STATION, UNIT 1
 F Security, medical, emergency & fire protection plans
- B403260175 Rev 41 to emergency plan implementing procedure index & Rev i to Procedure EPIP 4305A, "Meteorological Tower Emergency Operations Facility Computer Terminal Operation " W/B40309 itr COUNBIL: 40 , SEARB, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNBIL: 40 Northeast Utilities \$4/02/15 EISENHUT, D.G. Division of Licensing 14pp 22756:171 24X Fiche 50-245,84/02/15,8403260195
- B403260143 Forwards general position statement on Reg Guide I 97.Rev 2 re justification of significant generic deviations:per NUREO-0737. Suppl i CDUNSIL.W 0 . SEARB.C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 0 Connecticut Yankee Atomic Fower Co 84/02/29 MILLER, J R Operating Reactors Branch 3. CRUICHFIELD.D Operating Reactors Branch 5. 3pp 22758 162 24X Fiche 30-000.84/02/29.8403260143
- --B403260151 General position statement on Reg Quide 1 97.Rev 2 re instrumentation for assessing plant & environ conditions during & following accidents # Northeast Nuclear Energy Co (subs. of Northeast Utilities). # Connecticut Yankee Atomic Power Co # Northeast Utilities B4/02/29 67pp 22758 165 24X Fiche 30-000.B4/02/R9.B403260143
- 8403190243 Notification of 840418 workshop in King of Prussie, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-07 Agenda for workshop encl MURLEY, TE Region 1, Office of Director. 84/03/09, O'TDOLE, J D Consolidated Edison Co of New York, Inc FOLLOCKIM B Long Island Lighting Co UDERITZ Public Service Electric & Gas Co. of New Jersey 33pp 22672:062, 24X Fiche. 50-000, 84/03/09, 8403190243
- 8403230029 Forwards response to request for add1 info concerning Suppl 1 to NUREO-0737 re procedures generation package & Rev 1 to emergency procedures guidelines CDUNBILL G 0 SEARB. C F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNBILL G. Northeast Utilities 84/03/09 CRUTCHFIELD. D Operating Reactors Branch 5 44pp. 22728 210 24x Fiche 50-245,84/03/09.8403230029

- --8403230034 Rev 1 to. "Millstone Nuclear Power Station Unit 1, Emergency Procedures Guidelines "

 * Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/03/31 56pp 22728 256 24% Fiche 50-245.84/03/09,8403230029
- 8403260146 Forwards revised procedures for corporate organization for nuclear incidents procedure menual including Procedure CONI re table of contents & CONI 1 05 re corporate emergency operations ctr operations M/o encl COUNSIL, W O . SEARS, C F Connecticut Yankee Atomic Power Co COUNSIL, W O . Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/03/09 EIGENHUT, D O Division of Licensing 2pp 22750 330 24% Fiche 50-000,84/03/09,8403260146
- 8403220136 Provides results of reevaluation of performance assessment, per util 83i217 ltr addressing topics discussed at 83i127 8ALP mgt meeting Category I rating uill be assigned to refueling area for Millstone 2 Explains Category 2 ratings MURLEY, T E Region 1. Office of Director 84/03/16, COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 22716 047 24X Fichs 50-000,84/03/16,8403220136
- 8403270008 Informs that util wiil provide info re planned deviations from Suppl 1 to NUREO-0737 by 840501 Delay has no effect on schedules for implementation of Suppl 1 to NUREO-0737 COUNDELL W 0 SEARB, C F Connecticut Yankee Atomic Power Co COUNDELL W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 84003/16, EJSENHUT, D 0 Division of Licensing 2pp 22770 011 24X Fiche 50-000, 84/03/16, 8403270008
- 8403300084 Advises that 83:214 Rev 18 to security plan & 840:10 Rev 2 to training & qualification plan consistent w/provisions of 10GFR50 54(p) & acceptable MARTIN:T T Division of Engineering & Technical Programs 84/03/26 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 22822 014 24X Fiche 50-245:84/03/26:8403300084
- J Insurance & indemnity information
- 8403140031 Forwards Endorsement 92 to NELIA Policy NF-173 SINISI.J M Harsh & McLennan, Inc. 84/03/05 BALTZMAN,J D Assistant Director for State & Licensee Relations 2pp 22633 017 24X Fiche 50-245.84/03/05.8403140031
- P Operating license stage documents & correspondence
- 8403200271 Affidavit of Q Sherwood requesting NEDE-20592-6F, "STR Bundle Submittal.Millstons-1 Segmented Test Rod Bundle.Suppl 6," dtd Jul 1982.be withheld from public disclosure BHERWOOD, Q Q General Electric Co 83/06/02 3pp 22696 i71 24X Fichs 50-245.83/06/02.8403200271.
- 8403060454 Forwards Amends 95 & 92 to Licenses DPR-21 & DPR-65, respectively Amends change Tech Specs to comply w/final rule on licensed operator staffing.
 CRUTCHFIELD.D Dperating Reactors Branch 5. 84/02/16 CQUNBIL,W 6 Northeast Nuclear Energy Co (subs of Northeast Utilities). 3pp 22511,193 24X Ficher 50-245.84/02/16:8403060454
- --8403060459 Amends 95 & 92 to Licenses DPR-2: & DPR-65, respectively, changing Tech Specs to comply w/final rule on licensed operator staffing CRUTCHFIELD, D Operating Reactors Branch 5 84/02/16 14pp 22511 196, 24X Fiche 50-245,84/02/16,8403060454
- 8403140340 Bummary of 831215 meeting w/OE & Mark I Owners Oroup in Bethesda, MD re Mark I containment wetwell-drywell vacuum breaker design methodology. SIEGEL, B. L. Operating Reactors Branch 2, 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fiche 50-000,84/02/21, 8803140340
- 8403070304 Provides responses to three open items from NRC/BNL Yankee Atomic Electric Co & consultants Mark I containment program plant-unique enalysis rept 840216 review meeting CELIA,N S. Teledyne Engineering Services 84/02/28 8IEGEL,B NRC No Detailed Affiliation Given 4pp 22546,171 24X Fiche,50-000,84/02/28,8403070304.
- B403130027 Informs that Amends 54,92 & B7 to Licenses DPR-61,DPR-21 & DPR-65, respectively, inadvertently eliminated reporting requirements for exceeding radiological limiting conditions for operation, Corrective actions identified, CDUNBIL, H O Northeast Nuclear Energy Co (subs. of Northeast Utilities) CDUNBIL, W O Connecticut Yankee Atomic Power Co CDUNBIL, H, O Northeast Utilities B4/03/01, MILLER, JR Operating Reactors Branch 3, CRUTCHFIELD, D. Operating Reactors Branch 5 4pp 22615 107, 24X Fichs 50-000, 84/03/01, 8403130027

- 8403190048 Informs that util postponed ultrasonic test/insp of safe~ end.no.zle bore & blend regions of feedwater mozile per NUREC-0619.due to installation of low flow feedwater controller COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O Northeast Utilities 84/03/05 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 22666 251 24X Fiche 50-245.84/03/05.8403190048
- B403090240 Bummary of 840216 meeting w/Northeast Nuclear Energy Co.
 Boston Edison Co.Vermont Yankes Nuclear Power Co & Teledyne
 Engineering Svcs in Waltham. Mare addl Mark I torus
 structural analysis List of attendees encl
 SHEA.J J Operating Reactors Branch 5 SIEGEL. D Operating
 Reactors Branch 2 84/03/07 CRUTCHFIELD. D Operating Reactors
 Branch 5 4pp 22572 298 24X Fiche 50-000.84/03/07.8403090240
- 8403260200 Comments on Issue 3 of NUREG-0885, "NRC Policy & Planning Outdance.1984 " Seven themes identified represent important objectives for industry COUNSIL.W 0 Northeast Utilities 84/03/12 DIRCKS.W J Office of the Executive Director for Operations 4pp 22756 204 24X Fiche 50-000.84/03/12,8403260200
- 8403150275 Generic Ltr 84-07 to ail licensees of BMRs re procedural guidance for pipe replacement at BMRs Svc list encl EISENHUT, D Q Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 334 24% Fiche 80-000.84/03/14.8403150275
- 8403190383 Notification of 840412 meeting w/util in Bethesda.MD to review addl justification for exemption from primary reactor containment leakage testing requirements re transversing in-core probe SHEA.J J Operating Reactors Branch 5 84/03/14 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 22675 205 24X Fiche 50-245.84/03/14.8403190383
- 8403210070 Forwards Amends 96 & 93 to Licenses DPR-21 & DPR-65, respectively Amends consist of changes to Section 6 of Tech Specs re nuclear review board reorganization & 8TS CRUTCHFIELD; D Operating Reactors Branch 5 84/03/19 COUNSIL, W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 6pp 22705 087 24X Fichs 50-245,84/03/19,8403210070
- --B403210079 Amends 96 & 93 to Licenses DPR-21 & DPR-65, respectively, consisting of changes to Section 6 of Tech Specs re nuclear review board, reorganization & 815 CRUTCHFIELD, D. Operating Reactors Branch 5 84/03/19 23pp 22705 095 24X Fiche, 50-245, 84/03/19, 8403210070
- 84032300B5 Forwards safety evaluation of BWR Clumers Group generic response to NUREG-0737. Item II K 3 45 re depressurization w/other than automatic depressurization sys (ADB) No mods to plant design & operation required CRUTCHFIELD, D Operating Reactors Branch 5 84/03/20 COUNSIL, W © Northeast Nuclear Energy Co (subs of Northeast Utilities) App 22726,335 24X Fichs 50-245,84/03/20,8403230085
- O Inspection reports, IE Bulletins & correspondence
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Metor Operated Vaive Control Circuits & Annunciation " Svc list and URBDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000.84/02/28, 8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Bvc list encl ORACE, J N Division of OA, Bafeguards & Inspection Programs (Post 830103), B4/03/02 Consolidated Edison Co. of New York, Inc 130pp. 22552 329 R4X Fichs 50-000,84/03/02,8402070007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate" Svc list encl JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 2255.098 24X Fiche 50-000.84/03/02.8402090008
- 8402090007 IE Info Notice 84-i5, "Reporting of Radiological Releases" 8vc list encl. JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York: Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011

- 8402070024 IE Info Notice B4-09. Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York. Inc 118pp 22635 049 24% Fiche 50-000. 84/03/07. 8402090024
- B40209002B IE info Notice B4-18, "Stress Corrosion Cracking in PWR Bys " Svc list and J JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24x Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bujietin 84-02, "Failures of GE Type HFA Relays in Use in Class JE Safety Bys " Svc list encl DEYQUNG.R C Director's Dffice. Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York. Inc 134pp 22923 094 24% Fiche 50-000.84/03/12.8402090031
- 8403190045 Notification of 840323 meeting w/util in Bethesda. MD to discuss BWR primary coolant recirculation piping insp & possible use of pipe clamps if cracks identified SHEA. J Operating Reactors Branch 5 B4/03/14 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 22666 i75 24X Fiche 50-245,84/03/14,8403190045
- 8403220136 Provides results of reevaluation of performance assessment, per util 83:219 ltr addressing topics discussed at 83:129 BALP mgt meeting Category 1 rating will be assigned to refueling area for Millstone 2 Explains Category 2 ratings MURLEY, T E Region 1. Office of Director 84/03/16 CCUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 22716 047 24x Fiche 50-000,84/03/16,8403220136
- 8402090043 IE lnfo Notice 84-19, "Two Events Involving Unauthorized Entries anto PWR Reactor Cavities" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22623 229 24% Fiche 50-000.84/03/21.8402090043
- 8402070044 JE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys" Svc list encl
 JURDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000.84/03/21, 8402070044
- G403300144 Responds to IE Bulletin G3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys "Haddam Nock facility uses 31 Hestinghouse-type DB breakers COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O Connecticut Yankee Atomic Power Co COUNSIL.W O Northeast Utilities B4/03/21 MURLEY.T E Region 1. Office of Director 4pp 22020 068 24X Fiche 50-000.64/03/21. G403300144
- 8403300086 Ack receipt of 840224 ltr informing NRC of steps taken to correct violations noted in JE Insp Repts 50-245/83-20 & 50-336/83-28
 - MARTIN, T T Division of Engineering & Technical Programs B4/03/23 COUNSIL, W J Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22822 017 24X Fiche 30-249,84/03/23,8403300086
- --8403300092 Responds to NRC 840125 ltr re violations noted in IE Insp Repts 50-245/83-20 & 50-336/83-28 Corrective actions Procedure CP 809A rewritten to include method of determining hi & hi-hi alarm setpoints COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities 84/02/24 MURCEY.T E Region 1. Office of Director 2pp 22822 019 24X Fiche 50-245,84/03/23,8403300086
- R Periodic operating reports & related correspondence
- 8403230022 "Haddam Neck Plant & Millstone Station Units 1 & 2 Annual Rept.1983 " H/840301 ltr CDUNSIL.W G. SEARS, C F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL.W G. Connecticut Yankee Atomic Power Co. 83/12/31 MURLEY, T E. Region 1, Office of Director. 348pp R2727 001 24% Fiche 50-000.83/12/31.8403230022
- B403020055 Honthly operating rept for Jan 1784 H/B40213 ltr HARRAN, G., MRDCZKA, E.J., MRDCZKA, E.J., Northeast Nuclear Energy Co (subs of Northeast Utilities), B4/01/31 5pp 22442 254 24X Fiche 50-245, 84/01/31, 8403020055
- 8403120135 Forwards "Semiannual Radioactive Effluents Release Rept.
 Jul-Dec 1983 " Offsite dose estimates not included due to
 estimate delays Complate rept will be resubmitted by 840400
 COUNSIL.W 0 . OPEKA.J F Northeast Nuclear Energy Co (subs of
 Northeast Utilities) COUNSIL.W 0 Northeast Utilities 84/02/28
 MUNIEY, T E Region 1. Office of Director ip 22590 096 24X
 Fiche 50-245.84/02/28.8403120135

- --840312013B "Semiannual Radioactive Effluents Release Rept, Jul-Dec 1983 " * Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/12/31 42pp 22590 097 24% Fiche 50-245,84/02/28,8403120135
- 8403300135 Monthly operating rept for Feb 1984 W/840313 ltr HARRAN, 0 , MRGCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MRGCZKA, E J Northeast Utilities 84/02/29 7pp 22820 023 24X Fichs 50-245,84/02/29,8403300135
- 5 Reportable occurrences. LERs & related correspondence
- 8403260233 Forwards summary list of deficiencies identified per iOCFR30 55(e).Part 21 & potential generic ltr repts for comments

 8TAROSTECKI.R Division of Project & Resident Programs 84/02/28 Region 1, Office of Director 7pp 22756 065 24X Fichs 50-000.84/02/28.8403260233
- 8403260284 LER 84-003-00 on 840213.gamma scan performed on two oysters indicated presence of Ag-110M w/concentration exceeding control station average activity No operational corrective actions necessary W/840316 ltr KANOLEY, JP., MROCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 84/03/16 4pp 22754 278 24X Fiche 30-245.84/03/16,8403260284
- DOCKET 50-247 INDIAN POINT STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8403090288 Public version of page changes to Book I personnel procedures & Book II emergency procedures, including Procedure IP-1007 re determination of magnitude of release & exposure rate W/831213 ltr & JM Felton release memo O'TODLE, J D Consolidated Edison Co of New York, Inc 83/12/02 MURLEY, T E Region i. Office of Director 80pp 22592 220 24X Fiche 30~003,83/12/02,8403090288
- 8403020341 Forwards IE Insp Rept 50-247/84-01 on 840109-11 No violations noted MARTINIT Division of Engineering & Technical Programs 84/02/17 O'TOGLE, J D Consolidated Edison Co of New York, Inc 2pp 22439 296 24X Fiche 50-247,84/02/17,8403020341
- --8403020342 IE Insp Rept 50-247/84-01 on 840109-11 No violations noted Major areas inspected public prompt notification sys HOUNAS, E J. CROCKER, H W Region 1, Office of Director 84/02/14 5pp 22439 298 24X Fichs 50-247,84/02/17,8403020341
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D G Division of Licensing 84/02/23 PALLADINO, 61LINSKY, ROBERTS Commissioners ip 22576 203, 24X Fiche 50-000,84/02/23,8402090006
- --84030803i6 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRR Ofc Ltr 19.dtd 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT.D 0 Division of Licensing 10pp 22576 204 24X Fiche 50-000,84/02/23,8402070006
- B403190243 Notification of B40418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09, Agenda for workshop encl MURLEY, TE Region 1. Office of Director 84/03/09 D'YOULE, J D Consolidated Edison Co of New York, Inc LUNDVALL, A E. Baltimore Gas & Electric Co RANDAZZA, J B. Maine Yankee Atomic Power Cd 35pp 22672 062 24X Fiche 50-000, 84/03/09, 8403190243
- 8403190355 Forwards revised schedule re-safety assessment sys/safety parameter display sys per Suppl 1 to NUREG-0737 Assessment indicates contractor capable of completing job 0'YOOLE, J D Consolidated Edison Co of New York, Inc 84/03/12. EIBENHUT.D G Division of Licensing 4pp 22675 176 24X Fiche 50-247,84/03/12.8403190355
- 8403190049 Provides preliminary estimate of cost to upgrade present primary emergency operations facility to provide radiation protection factor of five O'TODLE.J D Consolidated Edison Co of New York, Inc 84/03/14. EISENHUT.D C Division of Licensing 2pp 22666 132 24% Fiche 50-003,84/03/14.8403190069

B403290251 Advises that B31014 rev to physical security plan consistent U/provisions of 10CFR50 54(p) & acceptable MARTIN, T Division of Engineering & Technical Programs B4/03/21 O'TOOLE, J D Consolidated Edison Co of New York, Inc 4pp 22800 001 24X Fiche 50-003,84/03/21,8403290251

H General correspondence

- 8403010170 Forwards Resolution 76 authorizing County participation in four-county radiological planning task force & authorizing use of County employees for radiological emergency response preparedness implementation requested W/Certificate of Svc BEIGERMAN, V K Rockland County, NY 84/02/15 PALLADINO, N Commissioners 3pp 22435 307 24X Fiche 50-247,84/02/15, example 177
- P Operating license stage documents & correspondence
- 8403010262 Further response to FOIA request for documents re Sandia Contract A-1123 & bibliography used by R Bernero Forwards App A documents FELTON, J M Division of Rules and Records FIN A-1123 83/12/20 RUTLEDGE.P Carolina Environmental Study Group 2pp 22444 069 24X Fiche 50-000,83/12/20,8403010262
- --B403010268 Forwards preliminary draft documents re Bandia Labs work in area of siting criteria development Repts represent work being done in expanding use of probabilistic analysis in regulatory work W/o encls
 DIRCKB, W J Office of the Executive Director for Operations
 82/04/26 GILINSKY Commissioners 5pp 22444,071 24X
 Fiche 50-000.83/12/20,8403010262
- B403270002 Final response to FQ1A request for four categories of documents tests, studies & analyses referencing or pertaining to NURED-0103, "BTS for B&W PMR" App A documents encl FELTON, J M Division of Rules and Records 84/01/13 MADDEN, T J Kaye, Scholer, Fierman, Hays & Hendler App 22816 127 24X Fichs 50-000:84/01/13.8403270002
- --B403270004 Speech entitled "RCPB Leakage Detection Bys "
 POMEROY, D.L. Atomic Energy Commission, Directorate of Regulatory
 Operations 84/01/13 5pp 22817 003 24X Fiche 50-000,
 84/01/13,8403270002
- 8403010186 Forwards Amend 86 to License DPR-26 & safety evaluation Amend changes Tech Specs to require that no movement of reactor fuel be made unless reactor subcritical for at least 131 h
 PEDERSEN, R L Operating Reactors Branch i 84/02/2; O'TODLE, J D Consolidated Edison Co of New York, Inc 2pp 22479:199 24X
 Fiche: 50-247, 84/02/21, 8403010186
- ---8403010194 Amend 86 to License DPR-R6, changing Tech Specs to require that no movement of reactor fuel be made unless reactor subcritical for at least 131 h VAR6A,8 A Operating Reactors Branch i 84/02/21 4pp 22479 201 24X Fiche 50-247,84/02/21,8403010186
- --8403010199 Bafety evaluation supporting Amend 86 to License DPR-26 * Office of Nuclear Reactor Regulation, Director 84/02/21 3pt 22479 206 24X Fiche 50-247,84/02/21,8403010186
- 840302017B Requests add1 info re Task Action Plan F 1 (f)(3) Forwards list of questions needed to complete review Responses expected within 30 days of 1tr receipt VAROA:8 A Operating Reactors Branch 1 84/02/22 0'TOOLE, J D Consolidated Edison Co of New York, Inc 4pp 22491 086 24X Fiche. 50-247, 84/02/22, 8403020178
- 8403090095 Forwards application to amend License DPR-26 consisting of proposed Tech Bpec changes, incorporating requirements of Item II B 1 of NURED-0737, "Reactor Coolant Vent Bys "D'TODLE,J D Consolidated Edison Co of New York, Inc 84/02/28 VARGA,S,A Dpsyating Reactors Branch 1 2pp 22576 007 24X Fiche: 50-247,84/02/28,8403090095
- --8403090098 Application for amend to License DPR-26, revising Tech Specs to incorporate requirements for reactor coolant vent sys O'1001E, J D. Consolidated Edison Co. of New York. Inc 84/02/28 2pp 22576.009 24X Fiche 50-247,84/02/28,8403090095
- --8403090101 Proposed Tech Spec re RCS vents per NUREO-0737, Item II B i * Consolidated Edison Co. of New York, Inc 84/02/29 Spp 22576:011 24% Fiche 50-247,84/02/28,8403090095,

- 8403070394 Forwards Amend 87 to License DPR-26 & safety evaluation Amend modifies Tech Specs to require min of 23 ft of water above reactor vessel flange during fuel handling operations PEDERSEN.R L Operating Reactors Branch I 84/02/29 0'TOOLE.J D Consolidated Edison Co of New York, Inc 3pp 22567 023 24X Fiche 30-247,84/02/29,8403070394
- --B403070398 Amend B7 to License DPR-26 modifying Tech Specs to require min of 23 ft of water above reactor vessel flange during fuel handling operations
 VARQA:S A Operating Reactors Branch 1 84/02/29 4pp
 22567 026 24X Fiche 50-247,84/02/29.8403070394
- --8403070402 Safety evaluation supporting Amend 87 to License DPR-26 * Office of Nuclear Reactor Regulation. Director 84/02/29 2pp 22567 030 24X Fiche 50-247.84/02/29.8403070394
- --8403210200 Amend 88 to License DPR-26,mod1fying Tech Specs by relocating requirements of reactor vessel surveillance program from miscellaneous insp Section 4 2 to RCS limiting conditions for operation in Section 3 i B VARGA.S A Operating Reactors Branch 1 84/03/07 8pp 22709 i84 24X Fiche 50-247,84/03/07,8403210197
- 8403300231 Advises that goal for completion of technical reviews & implementation of all NURGO-0737 items, excluding Suppl 1, is 8 sept 1984 Requests to be advised of potential problems within 30 days VARGA-S A Operating Reactors Branch 1 84/03/13 D'TDOLE, J D Consolidated Edison Co of New York, Inc 2pp 22844 358 24X Fiche 50-247,84/03/13,8403300231
- 840209004i Board Notification 84-050 provides Commission policy statement 5 proposed rulemaking on environ qualifications EISENHUT.D 9 Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 22716 338 24X Fiche 50-000.84/03/14.840209004i
- 8403200124 Advises that schedule for submittal of detailed control room design review summary rept will be provided by 840731, per 830831 ltr
 O'YOOLE, J D Consolidated Edison Co of New York, Inc 84/03/14 EIBENHUT, D G Olvision of Licensing ip 22685 352 24X
 Fiche 50-247,84/03/14.8403200124
- 8403290170 Forwards review status of remaining Generic Ltr 83-28 items re required actions based on generic implication of Salem ATMB events Westinghouse conducting life-cycle testing of shunt & undervoltage trip attachments O'TODLE, J D Consoltdated Edison Co of New York, Inc 84/03/15 E18ENHUT, D C Division of Licensing 7pp 22003 081 24X Fiche 50-247,84/03/15.8403290170
- 8403270193 Notifies that util will provide addl info re performance testing of relief & safety valves.per Item II D i of NUREG-0737.by 840615.per 840308 agreement D'TOOLE.J D Consolidated Edison Co of New York. Inc 84/03/i6 VARGA:S A Operating Reactors Branch i 1p 22771 i02 24X Fiche 50-247.84/03/i6.8403270193
- G inspection reports: IE Bulletins & correspondence
- B403020341 Forwards IE Insp Rept 50-247/B4-01 on 840109-11 No violations noted MARTIN,T T Division of Engineering & Technical Programs 84/02/17 D'TODLE,J D Consolidated Edison Co of New York, Inc 2pp 22437 276 24X Fiche 50-247,84/02/17,8403020341
- --8403020342 IE Insp Rept 50-247/84-01 on 840109-11 No violations noted Major areas inspected public prompt notification sys WOJNAB,E J , CROCKER,H W Region i, Office of Director 84/02/14 Spp R2439 298 24% Fiche 50-247,84/02/17,8403020341
- 8403050014 Ack receipt of 840127 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/83-22 MARTIN, T T Division of Engineering & Technical Programs 0'TOOLE, J D Consolidated Edison Co of New York, Inc 22490 133 24x Fiche 50-247,84/02/24.8403050014

- --840305C015 Responds to NRC 831229 ltm re violations noted in IE Insp. Rept 50-247/83-22 Corrective actions detailed evaluation of documentation & insp. records of 40 maint work packages conducted Withdrawal of violation requested O'TOOLE.J D. Consolidated Edison Co. of New York. Inc. 84/01/27 MARTIN.T T. Division of Engineering & Technical Programs. 3pp. 22490 135 24X Fiche 50-247.84/02/24.8403050014
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enci JORDAN.E L Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22709 239 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Rays by DDT & NRC " Svc list anc) GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Ficha 50-000.84/03/02.8402090007
- 8402070008 IE Info Notice 84-i6, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list enc! JCRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc i22pp 22553 098 24% Fiche 50-000.84/03/02.8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24K Fiche 50-000,84/03/02,8402090009
- 84D2090011 IE info Notice 84-17, "Problems H/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000;84/03/05,8402090013
- 8402090024 IE Info Notice 84-09, Rev i. "Lessons Learned From Insps of fire Protection Bafe Shutdown Bys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corresion Cracking in PWR Sys " Syc list enci JURDAN.EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 84032i0197 Forwards Amend BB to License DPR-26 Amend modifies Tech Specs by relocating requirements of reactor vessel surveillance program from miscetianeous insp Section 4 2 to RCS limiting conditions for operation in Section 3 1 B VARGA.9 A Operating Reactors Branch i 84/03/07 O'TDDLE, J D Consolidated Edison Co of New York, Inc 6pp 22709 178 24X Fiche 50-247,84/03/07,8403210197
- --8403210200 Amend 88 to License DPR-26 modifying Tech Specs by relocating requirements of reactor vessel surveillance program from misceillaneous insp Section 4 2 to RCS limiting conditions for operation in Section 3 1 B VARGA,S A Operating Reactors Branch i 84/03/07 8pp 22709 184 24X Fiche 50-247,84/03/07,8403210197
- 8403150029 Forwards request for schedular relief from ASME Boiler & Pressure Vessel Code Settion XI. IMD-2410 (b) re implementation of sys pressure testing as part of inservice insp program, until Cycle 7/8 refueling outage complete C+TOOLE-J D Consolidated Edison Co of New York, Inc 84/03/08 VARGA, 8 A Operating Reactors Branch 1 Spp 22641 001 24X Fiche 50-247,84/03/08,8403150029
- 8402070D31 IE Bulletin 84-02. "Failures of OE Type HFA Relays in Use in Class IE Bafety Sys " Syc list enc!
 DEYUUN9.R C Director's Office. Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fichs 50-000.84/03/12,8402090031
- B403270172 Forwards summary of analysis assuming failure of fast acting main feedwater regulating valve to close on demand in response to IE Bulletin 80-04 Containment pressure & core reactivity response within FSAR acceptance criteria.
 O'TODE.J D Consoludated Edison Co of New York, Inc 84/03/15 VARGALS A Operating Reactors Branch 1 App 22803 355 24% Ficher 30-247.84/03/15,8403290172
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list end JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp. 22823 229 24X Fiche 50-000,84/03/21,8402070043

- 8402090044 IE Info Notice 84-20. "Svt Life of Relays in Safety-Related Sys" Svc list encl JORDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24% Fiche 50-000.84/03/21.8402090044
- 8403270268 Forwards response to IE Bulletin B3-07. "Apparently Fraudulent Products Sold by Ray Miller, Inc " No subj matis received for use at facilities Evaluation of other matis received from vendor enci G'TGOLE, J D Consolidated Edison Co of New York, Inc 84/03/22 DEYQUNG.R C Director's Office Office of Inspection and Enforcement 9pp 22800 0il 24% Fiche 50-247.84/03/22,8403290268
- R Periodic operating reports & related correspondence
- 8403230135 "Personnal Whole Nody Exposure for CY83 " U/840301 ltr D'IDDLE.J D Consolidated Edison Co of New York, Inc 83/12/3i MURLEY.T E Region 1, Office of Director 3pp 22730.i37 24X Fichs.50-003.83/12/31.8403230135
- B403260120 "Effluent & Waste Disposal Semiannual Rept for Jul-Dec 1983 " W/B40301 ltr O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/12/31 MURLEY, T E Region 1, Office of Director 46pp 22758 086 24X Fich 50-003.83/12/31.8403260120
- 8403020195 Monthly operating rept for Jan 1984 W/840215 ltr BLATT.M , O'TOOLE.J D Consolidated Edison Co of New York, Inc B4/01/31 MCDONALD.H O Office of Resource Management, Director, 6pp 22442 028 24% Fiche 50-247.84/01/31.8403020155
- 8403270186 Monthly operating rept for Feb 1984 W/840315 ltr BLATT,M . G'TOBLE. J D Consolidated Edison Co of New York, Inc 84/02/29 MCDOMALD,H Q Distribution Services Branch 7pp 22771 324 24X Fichs 50-247.84/02/29,8403270186
- S Reportable occurrences, LERs & related correspondence
- B403210194 LER 84-001-00 on 840104, low pressure alarm on weld channel & containment penetration prossurization sys sounded in central control room Caused by Isakage past one or both containment purge axhaust valves W/840227 ltr BLATT, M. 0'TOOLE, J. D. Consolidated Edison Co. of New York, Inc 84/02/03 MURLEY, T. E. Region 1, Office of Director 4pp 22707 098 24X Fiche 50-247,84/02/03,8403210154
- 8403:30405 LER 84-002-00 on 840:05, two of four MSIVs did not fully close within 5 s Tach Spec requirement Caused by dried out valve shaft lubrication Shaft & packing lubricated W/840827 ltr
 BLATT.M , UTUOLE, J D Consolidated Edison Co of New York, Inc 84/02/04 MURLEY.T E Region 1, Office of Director 3pp 226:3 147 24% Fiche 50-247,84/02/04,8403:30405
- 8403150093 EN-84-012 on 840313, notice of violation & proposed imposition of civil penalty in amount of \$40,000 will be issued to license Action based on violation of Tech Spacs re containment spray sys inoperability CRAIG. J. AXELRAD. J. Director's Office, Office of Inspection and Enforcement 84/03/08 ip 22641 248 24X Fiche 50-247,84/03/08, 240315083
- 8403270204 LER 84-003-00 on 840205, unit brought to hot shutdown due to RPI channel drift Caused by uncalibr analog-signal due to movement in voltage adjustment potentiometer on RPI power supply sola transformer W/840322 ltr O'TODLE, J D Consolidated Edison Co of New York, Inc. 84/03/22. 4pp 22770 284 24X Fichs 50-247,84/03/22,8403270204
- T Hearing transcripts on non-antitrust matters
- 8403160004 Transcript of ACRS Subcommittees on Reliability & PRA & Indian Point Units 2 & 3 840314 meeting in Washington, DC Pp 1-60. Supporting documentation encl # ACRS Advisory Committee on Reactor Safeguards 84/03/14 61pp 22653.289 24X Fichs 50-247.84/03/14.8403160004
- DUCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- B903050004 Forwards FEMA B40206 ltr & final exercise evaluations on B30914 offsite emergency preparedness exercise. Recommendations from rept do not affect approval of plan. PAPERIELLO, C. J. Region 3, Offsice of Director 84/02/29. REED, C. Commonwealth Edison Co. 2pp. 22470 240 24X Ficha 50-237, B4/02/29, B403050004

- 8403120053 Advises of 840323 regional workshop in Rosemont, IL w/all Region III licenses to discuss fire protection safe shutdown requirements of iOCFR50, App R Agenda encl SPESSARD, R L Division of Emergency Preparedness & Operational Support 84/03/06 REED, C Commonwealth Edison Co 3pp 22585 222 24X Fiche 50-010, 84/03/06, 8403120059
- 8403150092 Forwards results of in-progress audit of detailed control room design review Util pursuing course of review which NRC believes will satisfy requirements of Suppl I to NVREG-0737 CRUTCHFIELD.D Operating Reactors Branch 5 84/03/14 FARRAR.D L Commonwealth Edison Co lipp 22643 002 24X Fiche 50~237, 84/03/14,8403150092

9 Adjudicatory correspondence

- 8402220137 Order extending time until 840228 for Commission to act to review Director's Decision DD-B3-14
 CHILK, B J Office of the Secretary of the Commission 84/02/21
 Commissioners ip 22337 362 24X Fiche 50-000,84/02/21,
- 8403010238 Order extending time until 840305 for Commission to act to review Director's Decision DD-83-14 & 831029 decision denying request of Environ Policy Inst CHILK: B J Office of the Secretary of the Commission 84/02/28 Commissioners ip 22434-210 24X Fiche 50-000,84/02/28,8403010238
- B403070067 Informs that Commission unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expired Dacision became final agency action on 840305 CHILK, B J Office of the Secretary of the Commission 84/03/08 CELEBREZZE, A J Dhio, State of 2pp 22575 350 24X Fiche 50-000.84/03/08.8403070069
- 8403090074 Informs that Commission unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expired. Decision became final agency action on 840305 CHILK.B J Diffice of the Secretary of the Commission 84/03/08 MILLAR: Environmental Policy Institute ip 22575 292 24X Fichs' 50-000.84/03/08.8403090074
- B403090ii3 Informs of Commission decision not to review Director's Decision DD-83-44 Time for Commission to act expired on B40305 W/o encl.

 GHILK.B J Office of the Secretary of the Commission 84/03/08 REBNIKOFF,M. Bierra Club ip 22576 079 24X Fiche 50-000.84/03/08.8403090ii3

P. Operating license stage documents & correspondence

- B403020037 Notification of contract execution "Dresden & Perry
 Bimulator Leasing," awarded to GE
 JEBUP, B Technical Assistance Contracts Branch FIN B-8713
 B402/17 HAVINS, O H Director's Diffice, Office of inspection and
 Enforcement ip 22491 045 24X Fiche 50-000, 84/02/17, 8403020037
- ---B403020043 Contract "Dresden & Perry Simulator Leasing," awarded to QE PIERCE,R,L General Electric Co. FIN B-8713 84/02/17 38pp 22491.046 24X Fiche:50-000,84/02/17:8403020037
- 8403140340 Summary of 831215 meeting W/GE & Hark I Duners Group in Bethesda, MD re Mark I containment wetwell-drywell vacuum breaker design methodology 81EGEL, B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 5ipp 22635 178 24X Fiche, 50-000, 64/02/21.
- 8403050119 Forwards supplemental response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Basem ATMS Events."

 BARNES, P. L. Commonwealth Edison Co. 84/02/29 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 26pp 22488 084 24X Fiche. 50-000, 84/02/29, 8403050119
- 8403130070 Forwards proposed resolution of environ qualification SER & Franklin Research Ctr technical evaluation rept open item deficiencies Final SER should be issued to indicate resolution of program deficiencies RYBAK, B. Commonwealth Edison Co 84/02/27 DENTON, H R. Office of Nuclear Reactor Regulation, Director 46pp 22602 123 24X Fiche 50-237,84/02/29,8403130070

- 8403130400 Forwards 840210 responses to Generic Ltr 83-35 clarifying TMI Item il K 3 31 Util concurs w/NRC position Item should be closed RYBAK, B Commonwealth Edison Co 84/03/02 EISENHUT, D 0 Division of Licensing 2pp 22613 143 24X Fiche 50-000, 84/03/02, 840310400
- 8403i30410 Application for amend to Licenses DPR-19 & DPR-25 revising Tech Spec Table 3 7 1 to require min addition of four LPCI & two torus spray suction valves RYBAK, B Commonwealth Edison Co 84/03/05 DENTGN, H R Office of Nuclear Reactor Regulation, Director 2pp 22616 031 24X Fiche 50-237,84/03/05,8403130410
- --8403i304i8 Proposed changes to Tech Spec Table 3 7 1 to require min addition of four LPC1 & two torus spray suction valves * Commonwealth Edison Co 84/03/05 10pp 22616 033 24X Fiche 50-237, B4/03/05, B403i30410
- 8403140133 Forwards Amend 74 to License DPR-23 & safety evaluation. Amend changes Tech Specs to support Cycle 9 operation w/reload fuel supplied by & associated analyses performed by Exxon CRUTCHFIELD, D. Operating Reactors Branch 5 84/03/09 FARRAR, D. L. Commonwealth Edison Co. 4pp. 22620 189 24X Fiche 50-249,84/03/09.8403140133
- --8403140143 Amend 74 to License DPR-25 changing Tech Specs to support Cycle 9 operation w/reload fuel supplied by & associated analyses performed by Exxon CRUTCHFIELD.D Operating Reactors Branch 5 84/03/09 10pp 22620 193 24X Fiche 50-249.84/03/09.8403140133
- --8403140188 Safety evaluation supporting Amend 74 to License DFR-25 * Office of Nuclear Reactor Regulation, Director 84/03/09 12pp 22620 203 24x Fiche 50-249.84/03/09.8403140133
- B403:50275 Generic Ltr B4-07 to all licensees of BHRs re procedural guidance for pipe replacement at BHRs Svc list encl EISENHUT.D G Division of Licensing 84/03/14 Commonwealth Ediann Co 20pp 22823 354 24X Fiche 50-000.B4/03/14.8403:50275
- 8403220153 Application to amend Licenses DPR-19 & DPR-25, revising Tech Specs to update snubber tables to reflect additions, deletions & other changes RYBAK, II Commonwealth Edison Co 84/03/15 DENTUN.H R Office of Nuclear Reactor Regulation, Director 3pp 22715 338 24X Fiche 50~237,84/03/15,8403220153
- --8403220158 Proposed Tech Specs updating snubber tables to reflect additions deletions & other changes * Commonwealth Edison Co 84/03/15 20pp 22715 341 24X Fiche 50-237, 84/03/15.8403220153
- B403270130 Application for amend to License DPR-25, changing Tech Specs to extend certain MAPLHGR curves to 40,000 MMd/ST RYBAK,B Commonwealth Edison Co B4/03/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22774 129 24X Fiche 50-000,84/03/19,8403270130
- --8403270136 Errata & Addenda Sheet 9, replacing Page 4-14 to "LQCA Analysis Rept for Dresden Units 2 & 3 & Guad Cities 1 & 2 Nuclear Power Stations " # General Electric Co NEDG-24146A ERR 09 B3/01/31 2pp 22774 135 24X Fiche 50-000,84/03/19,8403270130
- --B403270144 Proposed Tech Specs re extension of certain MAPLHOR curves to 40.000 MHd/8T * Commonwealth Edison Co 84/03/19 3pp 22774 137 24X Fiche 50-000,84/03/19,8403270130
- 8403220047 Forwards corrected Page 45 to Amends 81 & 73 to Licenses DPR-19 & DPR-25, respectively, which failed to include Footnote is reverification of time delay setting between 3 & 9 & GRUTCHFIELD, D Operating Reactors Branch 5 84/03/20 FARRAR, D L Commonwealth Edison Co 4pp 22712 i97 24X Fiche 50-237.84/03/20, 8403220047
- G Inspection reports, iE Bulletins & correspondence
- B403120134 Forwards IE Insp Repts 30-237/84-01, 50-249/84-01, 50-254/84-01, 50-254/84-01, 50-254/84-01, 50-254/84-01 & 50-304/84-01 an 840203-14 No noncompliance identified BHAFER! N D Region 3, Office of Director Commanuealth Edison Co 2pp 22590 090 24X Fiche 50-000-84/02/23, B403120134

- --8403120137 IE insp Repts 50-237/84-01.50-249/84-01.50-254/84-01.50-2
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan" Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THOMAS, B Commonwealth Edison Co 84/02/24 KEPPLER, J G Region 3, Office of Director 3pp 22470 137 24X Fiche 50-000,84/02/24, 24/325042
- --8403050046 Rev O to "Corporate Regulatory Performance Improvement Plan" + Commonwealth Edison Co 84/02/29 22pp 82490 142 24X Fiche 50-000.84/02/24.8403050043
- B401i90072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enci
 JCRDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22707 238. 24X Fiche 50-000.84/02/28.8401170072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of QA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24% Fiche: 50-000.84/03/02,8402090007
- 8402090008 IE Info Notice 84-14. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 22553 098 24X Fiche 30-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-i5, "Reporting of Radiological Releases" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 84020900ii IE Info Notice 84-17, "Problems H/Liquid Nitrogen Coaling Components Below Nii Ductility Temp " Svc list enc) JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc i17pp 22553 336 24X Fichs 50-000,84/03/05,84020900ii
- 8403130370 Forwards summary of ultrasonic insp & resultant repairs on stainless steel webds covered by 830826 order Summary lists overall insp scopp, welds not examined & table of peids w/indications of intergranular stress corrosion cracking RYBAK.8 Commonwealth Edison Co 84/03/05 DENTON, H R DPfice of Nuclear Reactor Regulation, Director 5ipp 22614 334 24X Fiche 50-249,84/03/05,8403130370
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown 89% " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 184 24X Fiche 50-000,84/03/07,8402090028
- 8403190001 Commits to submit plans for insp.corrective actions &/or mods, including potential replacement of recirculation or other piping, at least 90 days prior to next refueling outage scheduled for Apr 1985
 SCHROEDER, CW Commonwealth Edison Co 84/03/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22664 324 24% Fiche 50-249,84/03/09,8403190001
- 8402070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class JE Safety Sys " Svc list enc!
 DEYDUND, R C Director's Office. Office of Inspection and Enforcement 84/03/12 Constillated Edison Co of New York, Inc 134pp 22823 094 24X Fiche: 50-000.84/03/12.8402070031
- 8403200196 Responds to 840307 telon re mid-cycle inspresults of sweepplet welds 22A-4 & 228-8 on recirculation symptoms printing RYBAK.8 Commonwealth Edison Co 84/03/12 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 22677 116 24X Fiche.50-249,84/03/12.8403200196

- 8403190074 Forwards order re intergranular stress corrosion cracking insp & repair at facility & SER CRUTCHFIELD.D Operating Reactors Branch 5 84/03/15 FARRAR.D L Commonwealth Edison Co 2pp 22669 335 24X Fiche 50-249.84/03/15.8403/90074
- ~-8403190077 Order confirming util commitments re intergranular stress correston cracking insp PURPLE.R A Division of Licensing 84/03/15 Commonwealth Edison Co 6pp 22669 337 24% Fiche 90-249.84/03/15.8403190074
- --8403190082 Safety evaluation re intergranular stress corrosion cracking insp & repair Plans for insp & mod of recirculation & other RCPB piping sys should be submitted for review 3 months before refueling outage # Office of Nuclear Reactor Regulation, Director 84/03/15 13pp 22669 343 24X Fichs 50-249,84/03/15,8403190074
- 8403190107 Forwards safety evaluation supporting util 831209 plan for insp & repair of remaining welds covered in NRC 830826 intergranular stress corrosion cracking insp order confirming shutdown Plant may return to power operation DENTON, H R Office of Nuclear Reactor Regulation. Director 84/03/15 FARRAR, D L. Commonwealth Edison Co 3pp 22669 200 24X Fiche 50-249, 84/03/15 8403190107
- --8403190113 Safety evaluation supporting util 831209 plan for insp & repair of remaining welds covered in NRC 830826 intergranular stress corrosion cracking insp order confirming shutdown Fuil power operation acceptable # Office of Nuclear Reactor Regulation. Director 84/03/15 ippp 22669 203 24% Fichs 90-249.84/03/15.8403190107
- 8403230088 Ack receipt of regulatory performance improvement plan
 Periodic meetings requested to discuss progress on program
 & provide feedback
 KEPPLER, J Q Region 3, Office of Director 84/03/20 THOMAS, B
 Commonwealth Edison Co 1p 22730 161 24X Fiche 50-000, 84/03/20,
 840323088
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAB.8 Commonwealth Edison Co 84/02/24 REPPLER.J Q Region 3. Office of Director 3pp 22730 162 24X Fiche 50-000, 84/03/20.8403230088
- --8403230124 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden, Quad Cities, Zion & LaBaile Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations" a Commonwealth Edison Co 84/02/27 22pp 22730 165 24X Fiche 30-000, 84/03/20, 8403230088
- 8403260196 Forwards responses to IE Bulletin 83-07, "Apparently Fraudulent Products Bold by Ray Miller. In: " Quad Cities supplied Wylping matis from Ray Miller. In: during const Evaluation enc.) Concerns of IE Bulletin 83-06 satisfied BARNES, P. L. Commonwealth Edison Co. 84/03/20 KEPPLER. J. 9 Region 3, Office of Director 19pp 22756 185 24X Fiche 30-000,84/03/20,84/03/20,84/03/260196
- B402090043 iE Info Notice B4-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities" Svc Iist encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys" 8vc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fithe 50-000,84/03/21,8402090044
- A Periodic operating reports & related correspondence
- 8403060099 "Rept of Radioactive Effluents.Jui-Dec 1983 " W/840215 ltr SCOTT.D J Commonwealth Edison Co 83/12/31 KEPPLER,J G. Region 3, Office of Director 17pp 22506 245 24X Fiche 30-010.83/12/31, 8403060099
- 8403080197 "Rept of Occupational Personnel Radiation Doses,1983." W/840227 ltr SCOTT.J S Commonwealth Edison Co 83/12/31 CASE,E G Office of Nuclear Reactor Regulation, Director 13pp 22559 099 24X Fichs 50-000,83/12/31,8403080197
- 8403220120 Annual whole body external exposures for 1983 W/840316 ltr RVDAK.B Commonwealth Edison Co 83/12/31 7pp 22716 007 24X Fiche 50-000:83/12/31:8403220120

8403130015 Monthly operating repts for Feb 1784 H/840301 ltr 8CHRCEDER, B A , SCOTT, D J Commonwealth Edison Co 84/02/29 17pp 22614 344 24X Fiche 50-237,84/02/29,8403130015

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

- F Security, medical, emergency & fire protection plans
- 8403280110 Public version of Emergency Pien Implementing Procedures 20103, "Classification of Emergencies" & 20104, "Emergency Roster" W/840123 ltr & JM Felton 840322 release memo BAKER.C. HILLIAMS.J W Fiorids Power & Light Co 84/01/17 O'REILLY.J P Region 2. Office of Director 31pp 22811 327 24X Fiche 80-250.84/01/17.8403280110
- 8403020204 Forwards IE Insp Repts 50-250/83-43 & 50-251/83-42 on 831216 & notice of violation Notice of violation withheld (ref 100FRZ 790(d) & 100FRZ 21) LEWIS,R C Division of Project & Resident Programs 84/01/25 WILLIAMS,J W Florida Power & Light Co 2pp 22440 094 24X Fiche 30-250,84/01/25,8403020204
- --8403020241 IE Insp Repts 50-250/83-43 & 50-251/83-42 on 831216
 Noncompliance noted employee circumvented security access
 control sys Details withheld (ref 100FR2 790 & 100FR73 21)
 TILLMAN, A. BREWER, R. Region 2. Office of Director MCGUIRE, D. R.
 Division of Emergency Preparedness & Materials Safety 84/01/20
 1p 22440 096 24X Fiche 50-250,84/01/25,8403020204
- 8403060086 Approves state & local plans & preparedness for electing & protecting public in event of radiological emergency Approval conditional on verification of alert & notification sys per criteria of App 3 of NMREO-06534/FRMA-REP-1, Rev i EPECK.S W Federal Emergency Management Agency 84/02/15 DIRCKS, W J Office of the Executive Director for Operations ip 22516 300 24% Fiche 50~250,84/02/15,8403060086
- 8403010173 Forwards order confirming licensee commitments to implement post-THI related items per Buppi i to NUREQ-0737 Bchedular commitments reasonable achievable & will provide timely upgrading of emergency response capability VARQA.8 A Operating Reactors Branch i 84/02/23 WILLIAMS, J J Florida Power & Light Co 4pp 22479 207 24X Fiche.50-250.84/02/23.8403010173
- --8403010180 Order confirming licensee commitments to upgrade emergency response capability, per Buppl 1 to NUREQ-0737 (Generic Ltr 82-33) EIBENHUT, D Q Division of Licensing 84/02/23 Fiorida Power & Light Co & pp 22479 213 24X Fiche 50-250.84/02/23,8403010173
- B403020285 Ack receipt of 840215 ltr informing NRC of steps taken to correct violations noted in 1E Safeguards Insp Repts 50-280/83-42 LEWIB.R C Division of Project & Resident Programs B4/02/27 WILLIAMB.J W Florida Power & Light Co lp 22440 067 24X Fiche 50-250.84/02/278 B4903020285
- --8403020288 Responds to NRC 840125 ltr re violations noted in IE Safeguards Insp Repts 50-250/83-43 & 50-251/83-42 Corrective actions withheld (ref 10cFR2 770 & 73 21) HILLIAMS, J. W. Floride Power & Light Co 84/02/15 D'REILLY, J. P. Region 2, Office of Director 1p 22440 070 24X Fiche 50-250,84/02/29,8403020285
- 8403160254 Notifies of 840316 workshop to discuss 10CFR30.App R requirements & inspiresults to resolve misunderstandings refire protection Attendess should be limited to six due to size of conference room LEWIS.R C Division of Project & Resident Programs 84/03/02 WILLIAMS.J W Florida Power & Light Co 1p 22660 255 24X Fichs 50-000.84/03/02.8403160254
- 8403190429 Forwards regulatory effectiveness review (RER) rept, possible solutions to RER concerns & observations & vital areas definition rept. Encls withheld (ref 10CFR73 21) VAROA: 8 A Operating Reactors Branch 1 84/03/06 WILLIAMS, J W Florida Power & Light Co. 1p 22681 327 24% Fiche 50-250, 84/03/06,8403190429

Q Adjudicatory correspondence

8403070135 Brief on conflict posed by legal requirement of timeliness & equitable considerations ASLB should issue ruling allowing patitioners contentions that address new fuel core design, changes in Tech Specs & reduction in safety margins HODDER, M H Center for Nuclear Responsibility 84/03/03 llpp 22538 R65 24X Fiche 50~250,84/03/03,8403070135

- --8403070139 Motion for leave to file brief on conflict pased by legal requirements of timeliness & equitable considerations on 840303 Instead of 840302 Certificate of Svc encl HODDER, M H Center for Nuclear Responsibility 84/03/03 Atomic 8afety and Licensing Board Punel 2pp 22538 276 24X Fiche 50-250,84/03/03,8403070135
- --8403070143 Forwards applicant 830325 ltr w/encl re util pressurized thermal shock & flux reduction program per 840228 request Wa ltr HODDER,M H Hodder, M H HODDER,M H Center for Nuclear Responsibility 84/03/03 Atomic Safety and Licensing Board Panel 7pp 22538 278 248 Fiche 30-230,84/03/03.8403070135
- 8403i400i7 Response to NRC & util responses to amended petition to intervene NRC guilty of conducting business lawlessky via repeated UL amends w/NSHC determination Certificate of Svc enc!
 HODDER: M H Center for Nuclear Responsibility HODDER: M H HODDER: M H BA/O3/O7 Atomic Safety and Licensing Board Panel 20pp 22632 144 24x Fiche 50-250,84/03/07.8403140017
- --8403140023 Motion for leave to file late, due to delays in typing & reproduction
 HODDER, M H Center for Nuclear Responsibility HODDER, M H
 Hodder, M H B4/03/07 Atomic Safety and Licensing Board Panel
 Jpp 22632 164 24X Fiche 50-250.84/03/07.8403140017
- 8403130034 Order granting licensee motion for extension of time to 840314 for filing response to petitioner 840303 brief re consolidating consideration of two sets of license amends issued last yr LAZO,R M Atomic Safety and Licensing Board Panel 84/03/09 Ip 22614 307 24X Fiche 50-250.84/03/07.8403130034
- 8403190062 Response to Ctr for Nuclear Responsibility & J Lorion 840303 brief on conflict posed by legal requirements of timeliness & equitable considerations ASLB should exclude any & all issues re 831209 Amends 92 & 98 Certificate of Svc enci MODDHEAD.C P Hearing Branch 4 84/03/14 12pp 22666 200 24x Fiche 50-250.84/03/14.8403190062
- 8403170171 Response to petitioners 840303 brief re consolidating two sets of license amends issued in late 1983 in support of new fuel assemblies ABLB should confine proceeding to 841007 amends
 841007 amends
 8AUSER.M A Florida Power & Light Co BAUSER.M A Newman & Holtringer 84/03/14 Abomic 8afety and Licensing Board Panel 15pp 22670 265 24X Fiche.50-250.84/03/14,8403190171
- --B403190179 Affidavit of DC Poteraiski on petitioners B40303 briaf re conflict posed by legal requirement of timeliness & equitable considerations Util B30720 amends not part of pressurized thermal shock program W/Certificate of Svc POTERALBKI.D C Florida Power & Light Co B4/03/09 17pp 22670 280 24X Fiche 50-250.84/03/14.8403190171
- 8403290299 Forwards WL Guthrie 840228 ltr to be served on parties Copy should be placed in PDR LAZO,R M Atomic Safety and Licensing Board Panel DSD 178 84/03/27 CLEMENTS,W L Record Services Branch (Document Control Desk) ip 22801 336 24X Fiche 50-250,84/03/27,8403290299
- --B403290304 Forwards file presented to Dade County Citizens Review Committee objecting to DL issuance GUTHRIE.W L Affiliation Not Assigned 84/02/28 Atomic Safety and Licensing Board Panel 57pp R2801 337 24X Fiche 50-250

H General correspondence

- 8403280149 Responds to 840208 itr requesting assistance in responding to J Paskavitch itr requesting latest EIB on concentrations of Sn-90.Cs-137 & 1-131 near plants Two annual repts encl H/o repts
 DIRCKS:W J Office of the Executive Director for Operations 84/03/07 CHILLEG.L Benate 4pp 22807 316 24X
 Fiche 50-000.84/03/07.8403280149
- --8403280156 Forwards constituent J Paskavitch itr requesting latest E18 on concentrations of Br-90.Cs-137 & I-131 near plants.

 Comments & views requested,

 CHILES, L Benate 84/02/08 KAMMERER, C. Office of Congressional Affairs 8pp 82809 320 24X Fiche 50-000.84/03/07.8403280149

J Insurance & indemnity information

8403060332 Forwards Endorsement 70 to NELIA Policy NF-185 DUCK.J R Harsh & McLennan. Inc 84/02/28 SALTZMAN.J Assistant Director for State & Licensee Relations 2pp 22516 011 24X Fiche 50-250.84/02/28.8403060332

- P Operating license stage documents & correspondence
- 8403010160 Forwards Amends 101 & 75 to Licenses DPR-31 & DPR-41, respectively & safety evaluation Amends revise Tech Specs to add motor apenated valves 863-A & 963-B to existing valves required to have power removed MCDDNALD, D O Operating Reactors Branch 1 84/02/22 WILLIAMS, J W Fiorida Power & Light Co 3pp 22479 232 24X Fiche 50-250,84/02/22,8403010160
- --8403010171 Amends 101 & 95 to Licenses DPR-31 & DPR-41, respectively. revising Tech Specs to add motor operated valves 863-A & 863-B to existing valves required to have power removed VAR6A.5 A Operating Reactors Branch 1 B4/02/22 7pp 22479 235 24X Fiche 50-250.84/02/22.8403010160
- --B4030i0177 Safety evaluation supporting Amends 101 & 95 to Licenses DPR-31 & DPR-41.respectively uffice of Nuclear Reactor Regulation. Director 84/02/22 7pp 22479 242 24X Fichs 50-250.84/02/22.8403010160
- 8403020184 Requests identification of any potential problems or items that cannot be met within time frame required to meet Sept 1984 goal for completion of NURGE-0737 items
 VARGA-8 A Operating Reactors Branch i 84/02/22 WILLIAMS, J
 Florida Power & Light Co 2pp 22495 005 24X
 Fiche 50-230,84/02/22.8403020184
- 8403040168 Notifies that administrative program & procedures now in effect will be reviewed to confirm implementation of recommended guidelines in NUTAC rept.per Generic Ltr 83-28 WILLTAMS.J C Florida Power & Light Co 84/03/01 EISENHUT.D O Davision of Licensing ip 22518 336 24X Flice 50-000,84/03/01.8403000168
- 8403080020 Forwards Integral neutron source data for evaluating & verifying flux reduction per 84117 request Data for Cycle 9 core octant time averaged relative power density.critical weld peaking factor & peripheral assembly pin power encl HILLIAMS.J W Florida Power & Light Co 84/03/01 VAROA.B A Operating Reactors Branch 1. 10pp 22559 229 24X Flohe 50~250.84/03/01.8403080020
- 8403190150 Notifies of 840402-06 meeting & preimplementation audit at Turkey Point to discuss confirmatory items identified in safety evaluation of detailed control room design reviews for facilities
 VARQA: S A Operating Reactors Branch 1. 84/03/07 HILLIAM. J W Florida Power & Light Co Opp 22691 311 24X
 Fiche 50-000.84/03/07.8403190150
- 8403200264 Application to amend Licenses DPR-31 & DPR-41, changing Tech Speca to expand spent fuel storage facilities to accommodate expected increase in inventory of spent fuel assemblies above capacity of existing storage facility WILLIAMS. J W Florida Power & Light Co 84/03/14 EISENHUT, D Q Division of Licensing 3pp 22687 263 24X Fiche 50-250,84/03/14,8403200264
- --8403200266 Proposed Tech Specs, expanding spent fuel storage facilities * Florida Power & Light Co 84/03/14 17pp 22687 266 24X Fiche 50-230, 84/03/14, 8403200264
- --8403200270 "Spent Fuel Storage Facility Mod. SAR" # Florida Power & Light Co 84/03/14 106pp 22687 283 24X Ficha 50-250, 84/03/14, 8403200264
- 8403300288 Requests remittance of fee for review of 840210 rept summarizing available reactor vessel matte data in response to pressurized thermal shock concerns DIGGS.R M. License Fee Management Branch 84/03/15 UHRIG.R.E Florida Power & Light Co. Ip 22844 327 24X Fiche 50-250. 84/03/15.8403300288
- B403260203 Advises that proposed license amend re spent fuel storage expansion submitted on B40314 forwarded to state designee for State of FL.in accordance w/iOCFR50 71(b)(1)
 HILLIAMS.J W Florida Power & Light Co B4/03/16 EISENHUT.D 0
 Division of Licensing ip 22756 207 24X Fiche 50-250, B4/03/16.
- a Inspection reports, IE Bulietins & correspondence
- 8403020204 Forwards IE Insp Repts 30-250/83-43 & 50-251/83-42 on 831216 & notice of violation Notice of violation withhelf (ref 100FR2 79/d) & 100FR2 79/1 LEWIS,R C Division of Project & Resident Programs 84/01/25. WILLIAMS,J W. Fiorida Power & Light Co Rep 22440 094 24X Fichs 50-230.84/01/25,8403020204.

- --B40302024: IE Insp Repts 50-250/83-43 & 50-251/83-42 on B31216 Noncompliance noted employee circumvented security access control sys betails withheld (ref 100FR2 770 & 100FR73 21) TILLHAN.A. BREMER.R Region 2. Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Bafety 84/01/20 1p 22440 076 24% Fiche 30-250.84/01/25.8403020204
- 8403160306 Forwards IE Insp Repts 50-250/84-02 & 50-251/84-02 on B40121-31 No violations or deviations noted DANCE.H C Division of Project & Resident Programs 84/02/21 WILLIAMS.J W Florida Power & Light Co 2pp 22660 145 24X Fiche 50-250.84/02/21.8403160306
- --8403160316 IE insp Repts 50-250/84-02 & 50-251/84-02 on 840121-31 No violations or deviations noted Major areas inspected plant operations, surveillance testing & plant tours KRU0.H E Region 2. Office of Director JAPE.F Division of Engineering & Operational Programs 84/02/14 8pp 22660 147 24% Fiche 50-250,84/02/21,8403160306
- 8401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York. Inc 115pp 22709 237 24X Fiche 50-000.84/02/28, 8401190072
- 8403020285 Ack receipt of 840215 itr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-280/89-49 & 50-281/83-42 LEWIS.R C Division of Project & Resident Programs 84/02/29 WILLIAMS, J W Fiorida Power & Light Co ip 22440 069 24X Fiche 50-250.84702/29.8403020285
- --8403020288 Responds to NRC 840125 ltr re violations noted in IE Safeguards Insp Repts 50-250/83-43 & 50-251/83-42 Corrective actions withheld (ref 10CFR2 790 & 73 21) WILLIAMS, J W Fiorida Power & Light Co. 84/02/15 O'REILLY, J P Region 2, Office of Director 1p 22440 070 24x Fiche 50-250,84/02/29,8403020285
- E403040291 Requests 1-month exemption from 10CFR50 55a(g)(5)(ii) schedular requirements re inservice insp Due to recent revs to code boundary drawings, addl time to review & incorporate changes required
 WILLIAMS.J W Florida Power & Light Co 84/03/01 EISENHUT, D G Division of Licensing 2pp 22519 086 24X Fiche 50-250,84/03/01,8403040291
- 8403140300 Discusses util request to update requirements for syspressure tests & extend existing 10-year inspiniterval due to lengthy steam generator repair outages Extension unacceptable Update of test requirements acceptable VARGA.B.A Operating Reactors Branch 1 84/03/01, WILLIAMS, J. R Florida Power & Light Co Spp 22635 318 24X Fische 50-250,84/03/01,8403140300
- --8403140306 Exemption from requirements of pressure test to 1980 Edition through Winter 1981 ASME Code, Section XI Requests to extend Insp Intervals to 840901 unacceptable EIBENIUT, D G Division of Licensing 84/03/01 Fibrida Power & Light Co 4pp 22635 323 24X Fiche 50-250,84/03/01,8403140300
- B402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Evc list encl ORACE, J N Division of QA, Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc 11st enci. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830183) 84/03/02. Consolidated Edison Co. of New York, Inc. 122pp 2253 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list enci
 JORDAN,E L. Division of Emergency Preparadness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 119pp 22553 217 24X Fiche 30-000,84/03/02,8402090009
- B402090011 IE lnfo Notice B4-17, "Problems H/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). B4/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000.84/03/05, 8402090011
- 8402070024 iE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Bys." Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co. of New York, Inc. 118pp 22635:049 24X Fiche 50-000,84/03/07,8402070024

- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403290123 Forwards response to Action Item 4 requested by IE Bulletin 82-02 re maint procedures for threaded fasteners in RCPB Response to Action Item 3 previously provided in 820802 ltr WILLIAMS, J W Floride Power & Light Co 84/03/09 O'REILLY, J P Region 2, Office of Director 3pp 22807 189 24X Fiche 50-250,84/03/09.8403290123
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24x Fichs 50-000.84/03/12,8402090031
- 8403270315 Summarizes 840307 meeting w/util to discuss performance enhancement program current evants & outstanding regulatory issues Maeting beneficial & provided better understanding of util plans
 O'REILLY.J P Region 2, Office of Director 84/03/16
 HUDIBURO, J J Florida Power & Light Co ip 22802 075 24X
 Fiche 50-230.84/03/16.8403270315
- 8403290097 Summarizes 840315 meeting w/util at Region II ofc reparformence enhancement program.current events & outstanding regulatory issues
 O'REILLY.J P Region 2, Office of Director 84/03/19 ADDMAT,E A Florida Power & Light Co ip 22806 349 24X Fiche 50-250, 84/03/19,8403290097
- 8403290192 Confirms lE mgt meeting on 840322 in Region II ofc to discuss proposed revs to plant performance enhancement program, per 840313 telcon LEWIS.R C Division of Project & Resident Programs 84/03/20 WILLIAMS.J W Florida Power & Light Co ip 22803 313 24% Fiche 50-250.84/03/20,8403290192
- 8402090043 IE Info Notice 84-17, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc 11st encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 227 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp. 22933 001 24X Fiche 50-000,84/03/21,8402090044

R Periodic operating reports & related correspondence

- 8403020033 Monthly operating repts for Jan 1984 W/840215 itr GRANT, N W., WILLIAMS, J. W. Fiorlda Power & Light Co 84/01/31 19pp 22442 235 24X Fiche 50-000, 84/01/31, 8403020033
- 8403300173 Forwards monthly operating repts for Feb 1984 & corrected Fage 1 of Bt Lucie Unit 2 monthly operating rept for Jan 1984 WILLIAMS, J W Florida Power & Light Co 84/03/15 Office of Resource Management, Director 1p 22819 263, 24X Fiche 50-000,84/03/15,8403300173
- --8403300185 Monthly operating repts for Feb 1984 GRANT,N,W Florida Power & Light Co 84/03/15 16pp 22819 264 24X Fiche 50-000,84/03/15,8403300173
- --8403300193 Corrected Page 1 of monthly operating rept for Jan 1984 GRANT, N W. Florida Power & Light Co 84/02/15 ip 22819 280 24X Fiche 50-000,84/03/15,8403300173

8, Reportable occurrences, LERs & related correspondence

- 8402270125 LER 84-004-00 on 840104, auxiliary feedwater sys periodic test initiated & pump A failed to develop required flow. Caused by Misposition of Manual governor speed control knob Knob reset to max position, W/840222 ltr.
 ARIAS, J., WILLIAMB, J. W Floride Power & Light Co 84/02/22 4pp 22389, 243 24x Fichs 50-250, 84/02/22, 8402270125
- 8403020248 PNO-II-84-018 on 840227, units shut down following failure of Bismens-Allis breaker to trip during functional test of 4-kV electrical breakers for nonsafety-related electrical bus 3C. Insp & repair underway DANCE M. C., LEWIS, R. C. Region 2, Office of Director. 84/02/28, 2pp. 22440-101 24X Fiche 50-250,84/02/28,8403020248

- 8403160058 LER 84-006-00 on 840212, reactor tripped Caused by electrical relay malfunction resulting in loss of power to nonsefety-related 4160-valt bus Design review & complete testing of automatic turbine governor initiated M/840313 ltr ROACH,P A , MILLIAMS,J W Florida Power & Light Ca 84/03/13 3pp 22652 323 24X Fiche 50-250,84/03/13,8403160058
- 8403220104 LER 84-007-00 on 840216.while at steady operation.dual unit trip occurred from 100X power, resulting in loss of 4,160-volt buses 30 & 40 Caused by bolt in breaker 4AC01 cubicle door travel Doors checked for proper clearance W/840319 1tr AR1A8.J, HILLIAMS.J W Florida Power & Light Co 84/03/19 6pp 22715 279 24X Fiche 50-250.84/03/19.8403220104

T Hearing transcripts on non-antitrust matters

B403020249 Transcript of 840228 prehearing conference in Homestead,Ft. Pp 1-84

* Atomic Safety and Licensing Board Panel 84/02/28 86pp 22440 107 24% Fiche 50-250,84/02/28.8403020249

V Operator Examinations

- B40302027B Forwards list of requested dates for NRC site visits to conduct operator licensing exams as requested in Generic Ltr B3-40 WILLIAMS, J W Fiorida Power & Light Co B4/02/29 EISENHUT, D O Division of Licensing 3pp 22440 071 24X Fiche 50-250,84/02/29,
- DOCKET 50-251 TURKEY POINT PLANT, UNIT 4
- F Security, medical, emergency & fire protection plans
- B4032B01i0 Public version of Emergency Plan Implementing Procedures 20103, "Classification of Emergencies" & 20104, "Emergency Roster" W/840123 ltr & UM Feiton B40322 release mean BAKER.C., WILLIAMS, J. W. Florida Power & Light Co. B4/01/17 O'REILLY, J. P. Region 2, Office of Director Sipp 22811 329 24X Fiche 30-250.84/01/17.84032B0110
- 8403020204 Forwards IE Insp Repts 50-250/83-43 & 50-251/83-42 on B31216 & notice of violation Notice of violation withheld (ref 10CFR2 790(d) & 10CFR73 21)
 LEWIS, R C Division of Project & Resident Programs 84/01/25
 WILLIAMS. J W Fiorida Power & Light Co 2pp 22440 094 24X
 Fichs 50-250.84/01/25.8403020204
- ---B403020241 iE Insp Repts 50-250/83-43 & 50-251/83-42 on B31216
 Noncompliance noted employee circumvented security access
 control sys Details withheld (ref iOCFR2 790 & 1OCFR73 21)
 TILLMAN.A Region 2, Office of Director B4/01/20 ip
 22440 096 24X Fiche 50-250/84/01/25/8403020204
- B403060086 Approves state & local plans & preparedness for electing by protecting public in event of radiological emergency Approval conditional on verification of elect & notification sys per criteria of App 3 of NUREG-0554/EMA-REP-1; Nev 1.

 SPECK, S W Federal Emergency Management Agency B4/02/15
 DIRCKS, W J Office of the Executive Director for Operations 1p
 22516 300 24X Fiche 50-250,84/02/15,8403060086
- B403010173 Forwards order confirming licensee commitments to implement post-TMI related items per Suppl i to NUREO-0737 Schedular commitments reasonable, achievable & wiil provide timely upgrading of emergency response capability VAROA, S.A. Operating Reactors Branch i 84/02/23, WILLIAMS, J.J. Florida Power & Light Co. 4pp. 22479 209 24% Fiche 50-250.84/02/23,8403010173.
- ~-B403010180 Order confirming licensee commitments to upgrade emergency response capability, per Suppl 1 to NUREO-0737 (Generic Ltr B2-33).
 EIBENHUT.D @ Division of Licensing B4/02/23 Florida Power & Light Co 6pp 22477 213 24% Fiche 50-250.84/02/23.8403010173
- 8403020285 Ack receipt of 840215 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-230/83-43 & 50-251/83-42 LEMBER C Division of Project & Resident Programs 84/02/29 WILLIAMS, J W Florida Power & Light Co ip 22440 049, 24X Fichs 50-250,84/02/29,8403020285
- --B403020288 Responds to NRC 840125 ltr re violations noted in IE Safeguards Insp Repts 50-250/83-43 & 50-251/83-42 Corrective actions withheld (ref 10CFR2, 790 & 73 21) WILLIAMS, J W Florida Power & Light Co 84/02/15 O'REILLY, J P Region 2, Office of Director Ip 22440 070 24X Fichs 50-250, 84/02/27, 8403020285

- 8403160254 Notifies of 840316 workshop to discuss 10CFR50.App R requirements & inspresults to resolve misunderstandings refire protection Attenders should be limited to six due to size of conference room LEWIGHR C Division of Project & Resident Programs 84/03/02 WILLIAMS.J W Florids Power & Light Co ip 22660 255 24X Fiche 50-000.84/03/02.8403160254
- 8403190429 Forwards regulatory effectiveness review (RER) rept, possible solutions to RER concerns & observations & vital areas definition rept Encls withheld (ref 100FR73 21) VAROA:S A Operating Reactors Branch 1 84/03/06 WILLIAMS, J W Fiorida Power & Light Co 1p 22681 327 24X Fiche 50~250, 84/03/06,8403190429

G Adjudicatory correspondence

- 8403070135 Brief on conflict posed by legal requirement of timeliness & equitable considerations ASLB should issue ruling allowing patitioners contentions that address new fuel core design: changes in Tech Specs & reduction in safety margins. HDDDER: M H Center for Nuclear Responsibility 84/03/03 11pp 22538 265 24X Fiche 50-250.84/03/03.8403070135
- --8403070139 Motion for leave to file brief on conflict posed by legal requirements of timeliness & equitable considerations on 840303 Instead of 840302 Certificate of Svc encl HODDER.N H Center for Nuclear Responsibility 84/03/03 Atomic Safety and Licensing Board Penel 2pp 22538 276 24X Fiche 50-250.84/03/03.8402370139
- --8403070143 Forwards applicant 630325 ltr w/encl re util pressurized thermal shock & flux reduction program per 640226 request W/o ltr HODDER,M H Hodder, M H HODDER,M H Center for Nuclear Responsibility 84/03/03 Atomic Safety and Licensing Board Panel 70p 22538 278 248 Fiche 50-250,84/03/03,8403070133
- 8403140017 Response to NRC & utll responses to amended petition to intervene NRC guilty of conducting business lawlessly via repeated OL amends w/NSHC determination Certificate of Svc encl HUDDER.M H Center for Nuclear Responsibility HODDER.M H Hodde M H B4/03/07 Atomic Safety and Licensing Board Panel 20pp 22632 144 24x Fichs 50-250,84/03/07,8403140017
- --B40314D023 Motion for leave to file late, due to delays in typing & reproduction
 MODDER, M H Center for Nuclear Responsibility HopDer, M H
 Hodder, N H B4/03/07 Atomic Safety and Licensing Board Pane)
 3pp 22632 164 24X Fiche 50-250,84/03/07,8403140017
- 8403130034 Order granting licenses motion for extension of time to 840314 for filling response to petitioner 840303 brief reconsolidating consideration of two sets of license amends issued last yr
 LAZO.R M Atomic Bafety and Licensing Board Panel 84/03/09 ip 22614 307 24X Fiche 30-250,84/03/09.8403130034
- 8403170062 Response to Ctr for Nuclea: Responsibility & J Lorion 840303 brise on conflict posed by legal requirements of timeliness & equitable considerations ASLB should exclude any & all issues re 831209 Amends 92 & 98 Certificate of Svc encl WDODHEAD.C P Hearing Branch 4 84/03/14 i2pp 22666 200 24X Fiche 30-280.84703/14.8403170062
- 8403190171 Response to petitioners 840303 brief re consolidating two sets of license amends 1ssued in late 1983 in support of now fuel assemblies ASLB should confine proceeding to 841007 amends
 BAUSER, M A Fiorida Power & Light Co BAUSER, M A Newman & Holtzinger 84/03/14 Atomic 8afety and Licensing Board Panel 15pp 82670 265 84X Fiche 50-250.84/03/14.840319017
- --8403190179 Affidavit of DC Poteralski on petitioners 840303 brief re conflict posed by legal requirement of timeliness & equitable considerations Util 830720 amends not part of pressurised thermal shock program W/Certificate of 8vc #OTERALSKI.D C Fiorida Power & Light Co 84/03/09 17pp 22670 280 24% Fiche 50-250,84/03/14,8403190171
- 8403270277 Forwards WL Quthrie 840228 ltr to be served on parties
 Capy should be placed in PDR
 LAZO,R M Atomic Safety and Licensing Board Panel BSB 178
 B4/03/27 CLEMENTS.H L Record Services Branch (Document Control
 DBBK) ip 22801:336 24X Fichs, 50-250, 89/03/27, 8403270297
- ~-8403270304 Forwards file presented to Dade County Citizens Review Committee objecting to OL issuance GUTHRIE.W L Affiliation Not Assigned 84/02/28 Atomic Safety and Litensing Board Panet 57pp 22801 337 24X Fichs 50-250,84/03/27,8403290299

H General correspondence

- 8403280149 Responds to 840208 ltr requesting assistance in responding to J Paskavitch itr requesting latest EIS on concentrations of Sr-90.Cs-137 & I-i31 near plants Two annual repts encl W/o repts
 DIRCKS.H J Office of the Executive Director for Operations 84/03/07 CHILES.L Senate 4pp 22807 316 24X
 Fiche 50-000.84/03/07.8403280149
- --8403280156 Forwards constituent J Paskevitch itr requesting latest EIS on concentrations of Sr-90, Cs-137 & 1-i31 near plants
 Comments & views requested
 CHILES,L Senate 84/02/08 KAMMERER,C Office of Congressional
 Affalrs 8pp 22809 320 24X Fiche 50-000,84/03/07,8403280149

J Insurance & indemnity Information

- B403060332 Forwards Endorsement 70 to NELIA Policy NF-185 DUCK.J R Marsh & McLennan, Inc 84/02/28 SALTZMAN,J Assistant Director for State & Licensee Relations 2pp 22516 011 24X Fiche 50-250.84/02/28.8403360332
- P Operating license stage documents & correspondence
- 8403010160 Forwards Amends 101 & 95 to Licenses DPR-31 & DPR-41, respectively & safety evaluation Amends revise Tech Specs to add motor operated valves 863-A & 863-B to existing valves required to have power removed HCDONALD, D © Operating Reactors Branch 1 84/02/22 WILLIAMS, J W Florida Fower & Light Co 3pp 22477 232 24X Fiche 50-250.84/02/22.8403010160
- --B403010171 Amends 101 & 95 to Licenses DPR-31 & DPR-41, respectively, revising Tech Specs to add motor operated valves 863-A & 863-B to existing valves required to have power removed VARGA,S A Operating Reactors Branch 1 84/02/22 7pp 22479 235 24X Fiche 50-250.84/02/22.8403010160
- --8403010177 Safety evaluation supporting Amends 101 & 95 to Licenses DPR-31 & DPR-41, respectively * Office of Nuclear Reactor Regulation, Director 84/02/22 7pp 22479 242 24X Fiche 30-250,84/02/22,8403010160
- 8403020184 Requests identification of any potential problems or items that cannot be met within time frame required to meet Sept 1984 goal for completion of NUREG-0737 items VARGA.S A Operating Reactors Branch 1 84/02/22 WILLIAMS, J Florida Power & Light Go 2pp 22495 005 24X Fiche 50-250.84/02/22.8403020184
- B40306016B Notifles that administrative program & procedures now in effect will be reviewed to confirm implementation of recommended guidelines in NUTAC rept.per Generic Ltr 83-28 WILLIAMS, J C Florida Power & Light Co 84/03/01 EISENHUT, D O Division of Licensing 1p 22518 336 24X Fiche 50-000, 84/03/01, 8403060168
- 8403080020 Forwards integral neutron source data for evaluating & vorifying flux reduction per 84517 request Data for Cycle 9 core octant time averaged relative power donsity.critical weld peaking factor & peripheral assembly pin power encl HILLIAMS.J W Florida Power & Light Co 84/03/01 VARQA.S A Operating Reactors Branch 1 10pp 22559 229 24X Fiche 50-250.84/03/01.8403080020
- B403170150 Notlfies of B40402-06 meeting & preimplementation audit at Turkey Point to discuss confirmatory items identified in safety evaluation of detailed control room design reviews for facilities
 VARGA.B A. Operating Reactors Branch 1 84/03/07 WILLIAM.J W Florida Power & Light Co 6pp 22681 311 24X Fishe 50-000.84/03/07.8403190150
- 8403200264 Application to amend Licenses DPR-31 & DPR-41 changing Tech Specs to expand spent fuel storage facilities to accommodate expected increase in inventory of spent fuel assemblies above capacity of existing storage facility WILLIAMS. J W Florida Power & Light Co 84/03/14 EISENHUT, D O Division of Licensing Spp 22687 263 24% Fiche 50-250,84/03/14,8403200264
- --8403200266 Proposed Tech Specs, expanding spent fuel storage facilities * Florida Power & Light Co 84/03/14 17pp 22687-266 24X Fiche 50-250,84/03/14,8403200264
- --BA03200270 "Spent Fuel Storage Facility Mod.SAR" a Florida Pawer & Light Co B4/03/14 106pp 22687 283 24X Fithe 50-250,84/03/14,8403200264

- 8403300288 Requests remittance of fee for review of 840210 rept summarizing available reactor vessel matis data in response to pressurized thermal shock concerns DIGGS,R M License Fee Management Branch 84/03/i5 UHRIG.R E Florida Power & Light Co ip 22844 327 24X Fiche 50-250, RA/03/15.RA03300288
- B403260203 Advises that proposed license amend re spent fuel storage expansion submitted on 840314 forwarded to state designee for State of FL.in accordance w/10CFR50 91(b)(1) WILLIAMS, J W Florida Power & Light Co 84/03/16 EISENHUT, D C Division of Licensing 1p 22796 209 24X Fiche 50-250, 84/03/16, 8403260203
- Q Inspection reports, IE Bulletins & Correspondence
- 8403020204 Forwards IE Insp Repts 50-250/83-43 & 50-251/83-42 on 831216 & notice of violation Notice of violation withheld (ref 10CFR2 790(d) & 10CFR3 21)
 LEWIB.R C Division of Project & Resident Programs 84/01/25
 WILLIAMS.J W Florida Power & Light Co 2pp 22440 074 24X
 Fiche 50-250,84/01/25,8403020204
- --8403020241 IE Insp Repts 50-250/83-43 & 50-251/83-42 on 831216
 Noncompliance noted employee circumvented security access
 control sys Details withheld (ref 10CFR2 790 & 10CFR73 21)
 TILLMAN, A. BREWER, R. Region 2. Office of Director MCGUIRE, D. R. Britan of Emergency Preparedness & Materials Safety 84/01/20
 1p 22440 096 24X Fiche 50-250.84/01/25.8403020204
- 8403160306 Forwards IE Insp Repts 50-250/84-02 & 50-251/84-02 on B40121-31 No violations or deviations noted DANCE.H C Division of Project & Resident Programs B4/02/21 HILLIAMS.J W Florida Power & Light Co 2pp 22660 145 24X Fichs 50-250,84/02/21,8403160306
- --8403160316 IE Insp Repts 50-250/84-02 & 50-251/84-02 on 840121-31 No violations or deviations noted Major areas inspected plant operations, surveillance testing & plant tours KRUG, H E Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 84/02/14 8pp 22660 147 24X Fiche 50-250,84/02/21,8403160306
- 840ii90072 IE Info Notice 84-i3, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc Iist encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830i03) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp. 22709 239 24X Fiche 50~000,84/02/28,840ii70072
- 8403020285 Ack receipt of 840215 ltr informing NRC of steps taken to correct violations noted in IE Bafeguards Insp Repts 30-250/83-43 & 50-291/83-42 LENIS.R C. Division of Project & Resident Programs 84/02/29 WILLIAMB.J W Florida Power & Light Co ip 22440 069 24X Fiche 50-250.84/02/29.8403020285
- --8403020288 Responds to NRC 840125 ltr re violations noted in IE Safaguards Insp Repts 50-250/63-43 & 50-251/83-42 Corrective actions withheld (ref 100FR2 790 & 73 21) WILLIAMS, J W Florida Power & Light Co 84/02/15 O'REILLY, J P Region 2, Office of Director in 2440 070 24X Fiche 50-250,84/02/27,8403020285
- 8403060291 Requests i-month exemption from iOCFR30 35a(g)(5)(ii) schedular requirements re inservice insp Due to recent revs to code boundary drawings, addI time to review & incorporate changes required HILLIAMS.J W Florida Power & Light Co 84/03/01 EISENHUT.D G Division of Licensing 2pp 22519.086 24X Fiche 50-250.84/03/01.8403060291
- 8403140300 Discusses util request to update requirements for syspressure tests & extend existing 10-year insp interval due to lengthy steam generator repair outages Extension unacceptable Update of test requirements acceptable VARGA, S A Operating Reactors Branch 1 84/03/01 WILLIAMS, J W Fiorida Power & Light Co 5pp 22635 318 24X Fiche 50-250,84/03/01,8403140300
- --8403140306 Exemption from requirements of pressure test to 1980 Edition through Winter 1981 ASME Code Bection XI Requests to extend insp intervals to 840901 unacceptable. EIBENNUT.D.G Division of Licensing 84/03/01 Florida Power & Light Co 4pp 22635 323 24X Fiche 50-250,84/03/01,8403140300
- B402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Bvc list encl GRACE,J N. Division of QA, Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007.

- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JCRDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JORDAN, E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 82553 217 24X Fiche 50-000.84/03/02.8402090009
- B402090011 IE Info Notice B4-i7, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 8030103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8402090024 IE Info Notice 84-09.Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 30-000.84/03/07.8402090024
- 8402070028 IE Infa Notice 84-i8, "Stress Corrosion Cracking in PWR Bys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24% Fiche 50-000.84/03/07.8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Bvc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000,84/03/12,8402090031
- 8403290315 Summarizes 840309 meeting w/util to discuss performance enhancement program current events & outstanding regulatory issues Meeting beneficial & provided better understanding of util plans
 O'REILLY, J P Region 2, Office of Director 84/03/16
 HUDIINRO, J J Fibrida Power & Light Co ip 22802 095 249
 Fiche 50-250,84/03/16,8403290315
- B403290097 Summarizes 840315 meeting w/util at Region II ofc re performance enhancement program, current events & outstanding regulatory issues O'REILLY, JP Region 2, Office of Director 84/03/19 ADDMAT, E A Florida Power & Light Co ip 22806 349 24% Fiche 50-250. 84/03/19.8403290097
- B403290192 Confirms IE mgt meeting on 840322 in Region II oft to discuss proposed revs to plant performance enhancement program.per B40313 telcon
 LEWIS.R C Division of Project & Resident Programs 84/03/20
 WILLIAMS.J W Florida Power & Light Co ip 22803 313 24X
 Fiche 30-250.84/03/20.8403290192
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list enc! JORDAN.E L. Division of Emergency Preparedness & Engineering Rosponse (Post 800103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Bys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000.84/03/21.8402090044
- R Periodic operating reports & related correspondence
- 8403020033 Monthly operating repts for Jan 1984 W/840215 1tr GRANT,N W , WILLIAMS,J W Florida Power & Light Co 84/01/31 19pp 22442 235 24X Fiche 50-000,84/01/31,8403020033
- B403300173 Forwards monthly operating repts for Feb 1984 & corrected Page 1 of St Lucie Unit 2 monthly operating rept for Jan 1984
 HILLIAMS, J W Florida Power & Light Co 84/03/15 Office of Resource Management, Director ip 22819 263 24X
 Fiche 50-000.84/03/15.8403300173
- --8403300185 Monthly operating repts for Feb 1984 GRANT.N W Florida Power & Light Co 84/03/15 16pp 22819 264 24X Fiche 50-000,84/03/15.8403300173

5 Reportable occurrences, LERs & related correspondence

- 8403020248 PND-[1-84-018 on 840227, units shut down following failure of Siamens-Aiiis breaker to trip during functional test of 4-kV electrical breakers for monsafety-related electrical bus 3C Insp & repair underway

 DANCE. H C . LEWIS. R C Region 2. Office of Director 84/02/28

 2pp 22440 iol 24X Fiche 50-250.84/02/28,8403020248
- 8403160038 LER 84-001-00 on 840212, reactor tripped Caused by electrical synchronism-check relay malfunction Design reviewed & automatic turbine governor runback logic circuitry tested satisfactorily W/840313 itr RDACH.P A . WILLIAMS.J W F)prida Power & Light Co 84/03/13 3pp 22635 136 24X Fiche 50-251.84/03/13.8403160038
- 8403160069 LER B4-002-00 on 940212 reactor trip occurred due to steam flow greater than feed flow coincident Caused by high steam flow reading on steam generator 4A Calibr check performed H/640313 ltr ARIAS,J, HILLIAMS,J W Florida Power & Light Co 84/03/13 3pp 22695 086 24X Fiche 50-251,84/03/13,8403160069
- T Hoaring transcripts on non-antitrust matters
- 8403020249 Transcript of 840228 prehearing conference in Homestead.FL Pp 1-84 * Atomic Bafety and Licensing Board Panei 84/02/28 86pp 22440 107 24X Fiche 50-250,84/02/28.8403020249

V Operator Examinations

8403020278 Forwards ilst of requested dates for NRC site visits to conduct operator licensing exams as requested in Generic Ltr 63-40 MILLIAMS, J W Florida Power & Light Co 84/02/29 EISENHUT, D G Division of Licensing 3pp 22440 071 24X Fiche 50-250,84/02/27,8403020278

DOCKET 30-254 QUAD CITIES STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8403090294 Public version of revised emergency plan implementing procedures, including Procedures GEP i10-0 re station director & GEP i10-2 re acting station directory (shift ongineer) W/JM Felton release memo KOVAK, T.J., TIEFZ,G., GERNER,L. Communumenth Edison Co. 89/11/03 43pp 22592 017 24X Fithe 50-254.83/11/03,8403090294
- B4030A00A3 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per B10709 Generic Etr B1-27 W/o request, entire plan will be placed in PDR VASSALLO.D B Operating Reactors Branch 2 84/02/10 FARRAR D L Commonwealth Edison Co 2pp 22528 303 24X Fiche 50-254.84/02/10.84030A0063
- 8403130135 Advises that state & iocal plans & preparedness for radiological emergencies adequate Approval conditional on FEMA verification of adequacy of algreing & notification sys.per App 3 of Nev 1 to NUREO-0554/FEMA-REP-1 SPECK.8 W Federal Emergency Hamagement Agency 84/03/02 DIRCKS W J Office of the Executive Director for Operations 2pp 22608 227 24X Fiche 30-234.84/03/02.8403130155
- 8403120149 Notifies of 840323 regional workshop in Rosemont, IL w/all Region III licensees to discuss fire protection safe shutdown requirements Workshop will provide addl guidance re iOCFR30, App R requirements Agenda enci SPESSARD.R L. Division of Emergency Preparedness & Operational Support 84/03/06 REED.C Commonwealth Edison Co 3pp 22386 i82 24% Fithe 50-254,84/03/06,8403120149
- P Operating license stage documents & correspondence
- G403010037 Application to amend License DPR-29, changing Tech Specs re MAPLHOR curves for certain fuel types
 RYGAM. B Commonwealth Edison co. 84/02/21 DENTON, H. R. Office of Nuclear Repation Purector 2pp 22436 078 24X
 Fiche 50-254.84/02/21,8403010087
- --8403010073 Proposed changes to Tech Spec Figure 3 5-1, revising MAPLHGR curves
 ** Commonwealth Edition Co 84/02/21 18pp 22436 080 24X
 Fiche 50-254,84/02/21,8403010089

- B403140340 Summary of 831215 meeting w/GE & Mark I Dwners Group in Bethesda: MD re Mark I containment wetwell-dryweil vacuum breaker design methodology SIEGEL: D. L. Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fiche 50-000, 84/02/21, 8403140340
- 8403060273 Application for amend to Litense DPR-29, changing Tech Spec Pages 3 1/4 1-8, -9, -i0, -i2, -i3, -i4, -2, -2a, -3, -7, 3 2/4 2-i4 & 3 3/4 3-3 re scram discharge vol sys mode Class III fee encl RVBAK.8 Commonwealth Edison Co 84/02/28 DENTON, H R Office of Nuclear Reaction Regulation, Director 2pp 22517 050 24X Fiche 50-254, 84/02/28, 8403060273
- --8403060279 Proposed changes to Tech Spec Pages 3 1/4 i-8,-9,-10,-12,-13,-14,-2,-2a,-3,-7,3 2/4 2-14 & 3 3/4 3-3 rp scram discharge vol sys mode a Commonwealth Edison Co 84/02/28 14pp 22517 052 24X Fiche 50-254,84/02/28,8403060273
- B403050119 Forwards supplemental response to Generic Ltr B3-2B,
 "Required Actions Dased on Generic Implications of Salem
 ATMS Events"

 BARNES,P L Commonwealth Edison Co 84/02/27 DENTON.H R Office
 of Nuclear Reactor Regulation, Director 26pp 22488 OB4 24X
 Fisho 50-000.84/02/29, 840305017
- 8403130353 Documents present resolution of SER open items & deficiencies noted in Franklin Research Ctr technical evaluation rept re environ qualification of safety-related electrical equipment

 RYBAKIE Commonwealth Edison Co 84/02/29 DENTON, HR Office of Nuclear Reactar Regulation, Director 40pp R2617 080 24X

 Fiche 50-254,84/02/29,8403130353
- B403130400 Forwards B40210 responses to Generic Ltr B3-35 ciarifying TMI Item II K 3 31 Util concurs w/NRC position Item should be closed RYBAK.B Commonwealth Edison Co 84/03/02 RISENHUT, D 9 Division of Licensing 2pp 22613 143 24X Fiche 50-000,84/03/02,
- B403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc list encl EIBENHUT.D Q Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24% Fitche 50-000,84/03/14,8403150275
- B403270130 Application for amend to License DPR-25, changing Tech Specs to extend certain MAPLHGR curves to 40,000 MHd/8T RYBAK.D Commonwealth Edison Co. 84/03/19 DENTON, H R Office of Nuclear Reacting Regulation, Director 2pp 22774 129 24x Ficha 50-000,84/03/19,8403270130
- --8403270136 Errata & Addenda Shert 7.replacing Page 4-i4 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Guad Cities 1 & 2 Nuclear Power Stations"

 * General Electric Co NEDU-24146A ERR 09 83/01/31 2pp 22774 135 24X Fiche 30-000.84/03/19.8403270130
- 9 Inspection reports, 1E Builetins & correspondence
- B403120134 Forwards IE Insp Repts 50-237/84-01,50-249/84-01, 50-254/84-01,50-245/84-01,50-295/84-01 & 50-304/84-01 on 840203-14 No noncompliance identified SHAFER, N D Region 3, Office of Director 84/02/23 REED.C Commonwealth Edison Co 2pp 22590 090 24X Fiche 50-000,84/02/23,8403120134
- --8403120137 IE Insp Repts 50-237/84-01.50-249/84-01.50-254/84-01.
 50-265/84-01.50-295/84-01 & 50-304/84-01 on 840203-i4.No noncompliance or deviations identified Major areas inspected allegations of improper operation CHRISBOTIMOS.N. TONGUE, T. HOLZMER, M. Region 3, Office of Director 84/02/21 4pp 22590 092 24X Fiche 50-000,84/02/23,8403120134
- 8403030002 Submits brief outline of regulatory improvement program Program implements basic changes in practices & structure of operation Summary of corrective actions taken in response to control rod insertion error encl
 THOMAS, B. Commonwealth Edison Co. 84/02/24 KEPPLER, J. G. Region
 3, Office of Director lipp 22470 226 24X Fiche 50-254,84/02/24.8403050002
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan" Plan designed to Aeighten employes awareness & strengthen corporate ability to improve regulatory performance
 THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER, J G Region 3. Office of Director 3pp 22470 137 24X Fiche 50-000,84/02/24,8403050043

- --8403050046 Rev O to "Corporate Regulatory Performance Improvement
 - Flan "
 * Commonwealth Edison Co 84/00
 Fiche 90-000,84/02/24,8403050043 84/02/27 22pp 22490 142 24X
- 8401190072 iE lnfo Notice 84-13, "Potential Deficiency in Mator Operated Valve Control Circuits & Annunciation " Svc list
 - encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22709 237 24X Fiche 50-000.84/02/28.8401190072
- 8403050072 Forwards addendum to iE Insp Repts 50-254/83-21 & 50-265/83-19, comparing beta analyses of liquid sample split & gross beta results of spiked liquid sample Info will close Open Items 50-254/83-21-02 & 50-265/83-19-01 PAPERIELLO, C J Region 3, Office of Director 84/02/29 REED, C Commonwealth Edison Co ip 22490 014 24X Fiche 50-254.84/02/29.
- --8403050074 Addendum to IE Insp Repts 50-254/83-21 & 50-245/83-19 re comparative beta analysis results of liquid sample split & grass beta results of spiked liquid sample * Region 3, Office of Director 84/02/29 ip 22470 015 24X Fiche 50-254,84/02/29,8403050072
- 8403190207 Forwards IE Insp Repts 50-254/83-24 & 50-265/83-23 on 830804-840202, No noncompliance identified LITTLE: H 8 Region 3, Office of Director 84/03/01 REED.C Commonwealth Edison Co 2pp 22671 072 24X Fiche 50-254.84/03/01.
- --840317020B IE Insp Repts 50-254/63-24 & 50-255/63-23 on 630804-840202 No noncompliance or deviations identified Major areas inspected review of inservice inspreactor water cleanup sys piping. IE bullatins & LERs CILIMBERO,R L , DANIELSON,D H , WARD,K D Region 3, Office of Director 84/03/01 25pp 22571 074 24X Fiche 50-254,84/03/01. 8403190207
- 8402070007 IE Info Notice 84-i4, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE.J N Division of GA. Bařegvards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402070007
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkier Bys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402070008
- 8402070007 IE info Notice 84-15, "Reporting of Radiological Releases" Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24% Fiche 50-000,84/03/02,8402070007
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nii Ductility Temp " Evc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8402090024 IE info Notice 84-09. Rev 1. "Lessons Learned From insps of Fire Protection Safe Shutdown Bys" Svc iist encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000,84/03/07,8402090024
- 840207002B IE Info Notice 84-18, "Stress Corrosion Cracking in PWR NOZOYOUZH IE INFO NOTICE 84-18. "Stress Corrosion Cracking in PMM Bys " 8vc list encl. JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000:84/03/07.8402090028
- B403190075 Requests B01002 & B10107 confirmatory orders on IE Builetin B0-17 re scram discharge mods be rescinded & actions no longer applicable be removed &/or deleted RYBAK: B Commonwealth Edison Co 84/03/07 DENTON, H R Of Nuclear Reactor Regulation, Director Spp 22669 358 24X Fiche 30-254,84/03/07,8403190075 Office of
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list enc!
 DEYCKNOG.R C Director's Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24X Fiche 50-000.84/03/12.8402090031

- B403270175 Submits plan for insp & repair of intergranular stress corrosion cracking indications in stainless steel piping in drywell during refueling outage initiated on B40306 RYBAK, B Commonwealth Edison Co B4/03/19 DENTON, H R Offic Nuclear Reactor Regulation, Director 4pp 22771 193 24X Fiche 50-254,84/03/19,8403270175
- 8403230088 Ack receipt of regulatory performance improvement plan Periodic meetings requested to discuss progress on program & provide feedback KEPPLER, J G Region 3, Office of Director 84/03/20 TH MEPPLER J G Region 3. Office of Director 84/03/20 THOMAS, B Commonwealth Edison Co ip 22730 i61 24X Fiche 50-000, 84/03/20, 8403230088
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAS.B Commonwealth Edison Co. 84/02/24 KEPPLER.J G Region 3. Office of Director 3pp 22730 142 24X Fiche 50-000. 84/03/20.8403230088
- --8403230126 Rev O to "Corporate Regulatory Performance Improvement Pian For Dresden, Quad Cities, Zion & LaSalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations " ### Stations & Byron & Miscoland | Bright | Brig
- 8403260196 Forwards responses to IE Builetin 83-07. "Apparently Frauduient Products Soid by Ray Miller. Inc." Qued Cities supplied w/piping matls from Ray Miller. Inc during const Evaiuation enci Concerns of IE Bulletin 83-06 satisfied BARNES.FL Commonwealth Edison Co. 84/03/20 KEPPLER.J.O. Region 3, Office of Director 19pp. 22796 185 24X Fiche 50-000.84/03/20.8403260196
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related 102099044 IE Info Notice 5. m...
 Sys " Svc list enci
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/21 Consolidated Edison Co of New
 York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403080197 "Rept of Occupational Personnel Radiation Doses, 1983 " M/40027 itr SCOTT.J B Commonwealth Edison Co 83/12/31 13pp 22539 099 24X Fiche 50-000.83/12/31.8403080197
- 8403220120 Annual whole body external exposures for 1983 W/840316 ltr RYBAK, B Commonwealth Edison Co 83/12/31 7pp 22716 007 24X Fiche 50-000,83/12/31,8403220120
- 8403060113 Forwards Rev 1 to "Effluent & Waste Disposal Semiannual Rept Jul-Dec 1982 " Errata for "Liquid Alpha Radioactivity, Jan-Jul 1983" & "Bolid Radwaste Summary, Jul-Dec 1983, " aiso Fig. 3. Part nausants Summary of the Tropy and Commonwealth Edison Co. 84/02/07 KEPPLER, J. 9. Region 3. Office of Director 1p. 225/8 252 24X Fiche 50-254, 84/02/07, 8403040113
- --8403060117 Rev 1 to "Efficent & Waste Discosal Semiannual Rept Jul-Dec Commonwealth Edison Co 83/05/31 7pp 22518 253 24x Fiche 50-254,84/02/07,8403060113
- --8403060121 Errata for "Liquid Alpha Radioactivity Jan-Juna 1983 "
 * Commonwealth Edison Co 83/06/30 ip 22518 260 24X
 Ficha 50-254,84/02/07,8403060113
- --8403060127 "Solid Radwaste Summary, Jul-Dec 1983 "
 * Commonwealth Edison Co 83/12/31 App 22518 261 24x Fiche 50-254, 84/02/07, 8403040113
- 8403130382 Monthly operating repts for Feb 1784 W/B40308 ltr MISAK.A . KALIVIANAKIS.N Commonwealth Edison Co B4/02/29 24pp 22616 275 24X Fiche 50-254.84/02/29.8403130382
- 8403150019 Listing of changes, tests & experiments Completed during Feb 1984 Summary of safety evaluation reported per IOCFR50 59 encl W/840308 ltr KALIVIANAKIS.N Commonwealth Edison Co 84/02/29 CASE.E & Office of Nuclear Reactor Regulation. Director 3pp 22644 360 24X Fiche 50-254,84/02/29,8403150019

S Reportable occurrences, LERs & related correspondence

- 8403070256 Followup Part 2) rept re defective mechanical snubber capatan springs supplied by Pacific Scientific Affected utils listed Purchasers have been notified & advised to work directly w/Pacific Scientific in disposition HOVI.L. NP5 Industries. Inc. 84/02/24 DEYOUNG.R.C. Director's Office Office of Inspection and Enforcement 2pp 22536 279 24X Fiche 50-000.84/02/24,8403070256
- 8403080011 Forwards response to Commissioner Gilinsky request for info on frequency of personnel errors at selected operating plants Summary of tabulated events re operator errors, personnel errors or procedural errors provided for CY83 DIRCKS.H J Office of the Executive Director for Operations 84/02/24 PALLADINO, GILINSKY, ROBERTS Commissioners 17pp 22584 142 24X Fiche 50-000,84/02/24,8403080011.
- 8403130235 PNO-111-84-023 on 840305 HPCI sys declared inoperable when surveillance test revealed accessive leakage on main pump outboard bearing During test of automatic degressurization sys, electromatic relief valve E failed to open CHRIGSOTIMBS.N. SHAFER.W Region 3. Diffice of Director 84/03/06 ip 22617 278 24x Fiche 50-854,84/03/06,8403130235

DOCKET 50-255 PALIBADES NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

- 8403010351 Summary of 840209 meeting w/util.Stiente Applications, Inc. MPR Assoc & MIT re NRC comments on detailed control room design review program plan, per requirements of Suppl 1 to NUREG-0737 Viewgraphs enci
 PAULSON.W A Operating Reactors Branch 5 84/02/29 Operating Reactors Branch 5 34pp 22432 329 24X Fiche 50-255.84/02/29, 8403010351
- 8403120115 Notifies of 840323 workshop on fire protection safe shutsown requirements of 10CFR50.App R in Rosemont.IL to discuss IE Info Notice 84-09 & provide add1 shutdown analyses 8/or mod guidance Agenda enti
 SPESSARD.R L Division of Emergency Preparedness & Operational Support 84/03/06 DEMITT.R S Consumers Power Co 3pp 22588 235 24% Fiche 50-255.84/03/06.8403120115

I Financial information

- 8403190071 Annual Financial Rept for 1983 W/840312 ltr SELBY, J D. FOLAHER, J B. PERRY, P A Consumers Power Co 83/12/31 01AMBUSSO. A Division of Licensing 34pp 22666 136 24X Fiche 50-000, 83/12/31,8403190071
- P Operating license stage documents & correspondence
- 8403010368 Forwards Amend 79 to License BPR-20 & safety evaluation Amend deletes capsule A-60 from reactor vessel surveillance capsule program & modifies coupon removal schedule PAULEON,W A Operating Reactors Branch 5 84/02/28 VANDEWALLE,D J Consumers Power Co 2pp 22403 080 24X Fiche 50-255,84/02/28,8403010368
- --8403010372 Amend 79 to License DPR-20, deleting capsule A-60 from reactor vessel surveillance capsule program & modifying coupon removal schedule to provide option of removing equivalent capsule instead of primary capsule CRUTCHFIELD, D Derating Reactors Branch 5 84/02/28 4pp 22433 082 24X Fiche 50-255,84/02/28.8403010368
- --8403010373 Safety evaluation supporting Amend 79 to License DPR-20 * Office of Nuclear Reactor Regulation, Director 84/02/28 3pt 22433 086 24X Fiche 50-255,84/02/28,8403010368
- 8403220078 Advises that issue of justifying unlimited or limited use of purge sys during normal operations will not be pursued Sys will operate only during told shutdown Tech Spec mod expected by 840420 Resubmitted due to error in original JCHNSDN, B D Consumers Power Co 84/03/01 CRUTCHTELD, D. Operating Reactors Branch 5 ip 22712 313 24% Fiche 30-255,84/03/01,8403220078
- E403050232 Summary of 840307 meeting w/util,NDE Technology, Westinghouse, Bechtel.C-E. Engineering Planning & Mgt & Newman & Holtzinger in Bethesda, MD re NDE program for steam generator tubes
 PAULSON.W A Operating Reactors Branch \$ 84/03/07 Operating Reactors Branch \$ 116pp 22561 034 R4X Fiche 50-255.84/03/07.8403090232

- 8403090210 Advises that util 840220 proposed varience for high-range stack gas monitors unacceptable 8ys should be modified to meet display guidance of NUREG-0737. Item If F 1(1), "Addl Accident Monitoring Instrumentation "CRUTCHFIELD.D Operating Reactors Branch 5 84/03/07 VANDEMALLE.D J Consumers Power Co 5pp 22574 358 24X Fichs 50~000.84/03/07.8403090210
- 8403150145 Ack receipt of NRC 840123 request for info re post-accident sampling sys (TMI Item II B 3) Plant-specific core damage estimete procedure & info demonstrating equipment operability & operator training will be provided by 840515 JUNNBON.N D Consumers Power Co 84/03/12 CRUTCHFIELD.D Departing Reactors Branch 5 1p 22639 362 24X Fiche 50-255.84/03/12.8403150145
- 8403230093 Application for Thend to License DPR-20, consisting of proposed Tech Epec change request to revise accident & transient analyses due to steam generator tube plugging Class III amend fee enci Heatup scheduled for 840308 JOHNSON-8 D Consumers Power Co 84/03/16 CRUTCHFIELD, D Operating Reactors Branch 5 18pp 22731 099 24X Fichs 50-255,84/03/16,8403230093
- --8403230078 Proposed pages to Tech Spec change request, revising accident & transient analyses due to steam generator tube plugging # Consumers Power Co 84/03/16 3ipp 22731 ii7 24X Fiche 50-253,84/03/16,8403230093
- --8403230102 "Palisades Cycle & Setpoint Verification W/50% Steam Cenerator Tube Piugging " LINDGUIST, T.R., NUTT, W.T. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) XN-NF-04-14 84/03/09 43pp 22731 158 24X Fiche 50-255,84/03/16,8403230093
- --B403230106 "Plant Transient Analysis for Palisedes Nuclear Power Plant W/50X Steam Generator Plugging"

 LINDGUIST.TR. NUTTH T Exxon Nuclear Co., inc. (subs. of Exxon Corp.) XN-NF-84-18 84/03/07 150pp 22731 202 24X
 Fiche. 50-255, 84/03/16. 8403230093
- --B403230111 "Palisades LOCA-ECCB Analysis for 2125 MMt Operation & 50% Steam Generator Tube Plugging."

 TAHVILI.T Exxon Nuclear Co , Inc (subs of Exxon Corp)

 XN-NF-B4-24 84/03/09, 54pp 22731 383 24X

 Fiche 50-255,84/03/16:8403230093
- 8403260113 Requests extension to respond to Generic Ltr 83-28 to reflect extension of current refueling outage Work necessary to address remaining issues will commence 60 days after end of current refueling outage VANDEWALLE.D J Consumers Power Co 84/03/22 EISENHUT.D G Division of Licensing 2pp 22750 361, 24X Fiche 50-255,84/03/22,8403260115
- B403270166 Notification of B40405-06 meetings w/util in Van Buren County, MI to discuss proposed radiological affluent Tech Bpecs PAULSON: WA Operating Reactors Branch 5 B4/03/23 CRUTCHFIELD, D Operating Reactors Branch 5 Spp 22774 147, 24X Fiche 50-255. B4/03/23. B400270166
- 8403300064 Notification of 840410 meeting w/util in Bethes6a,MD to discuss steam generator repair PAUL8DN.W A Operating Reactors Branch 5 84/03/28 CRUTCHFIELD,D Operating Reactors Branch 5 4pp 22822 106 24X Fiche, 50-255,84/03/28,840330064

Q Inspection reports, IE Bulletins & correspondence

- 8403050223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RC8 leakage Forwards App C documents Search continuing FELTON.J M Division of Rules and Records 84/02/07, MADDEN.T J. Kays. 8choler, Fierman. Hays & Handler 3pp 22496-234 24X Fiche 50-000,84/02/07.8403050223.
- --B403050236 Notlifies that independent measurements of identified & unidentified RCB leak rates for all PWRs in Region III performed per Procedures 617278 & 617288 Insp findings summarized.

 NORELIUS: C E Division of Engineering 02/03/08 JORDAN, E L Division of Engineering & Guality Assurance (Pre 030103) 2pp 22494 270 24X Fiche 50-000.04/02/07.0403050223
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " 8vc list encl UDROAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22909 239 24X Fiche 50-000,84/02/28,8401190072

- 8403120131 Responds to IE Bulletin 83-07. "Apparently Fraudulent Products Sold by Ray Miller, Inc " Purchase order records for 1975-79 reviewed & 14 suspect purchase orders found No matis supplied on orders purchased from Ray Miller, Inc JOHNSON, B D Consumers Power Co 84/03/01 KEPPLER, J G Region 3, Office of Director 2pp 22388 238 24X Fiche 50-000, 84/03/01, 8403120131
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACELJ N Division of GA. Gaféguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fichs 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16, "Falture of Automatic Sprinkler Bys Valves to Operate " Bvc list ancl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 2253 098 24X Fichs 50-000,84/03/02,8402090008
- B402070007 IE Info Notice 84-i5. "Reporting of Radiological Releases " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 117pp 22553 217 24X Fiche 50-000,84/03/02,8402070009
- 8402090011 IE Info Notice 84-17. "Problems W.Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidate Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8403070300 Responds to IE Bulietin 83-08. "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Subj circuit breakers not installed in safety-related sys VANDEWALLE, D J Consumers Power Co 84/03/03 KEPPLER, J Q Region 3, Office of Director 2pp 22346 360 24X Fiche 50-235.84/03/05, 8403070300
- 8402090024 IE Info Notice 84-07, Rev i, "Leasons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JDRDAN, E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/03/07 Consolidated Edison Co of New York, Inc i18pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 840207002B IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Sys." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 840209003i IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Svc list encl DEYDUNG, R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York
- 8402070043 IE Info Notice 84-i9, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 227 24X Fiche 50-000,84/03/21,8402070043
- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Bys." Bvc list encl JURDAN, E L Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000.84/03/21.8402090044
- R Periodic operating reports & related correspondence
- 8403080184 "1983 Annual Operating Rept Occupational Exposure " W/ 840229 ltr JOHNSON, B D Consumers Power Co 83/12/31 KEPPLER, J Q Region 3, Office of Director 4pp 22539 202 24X Fiche 50-235,83/12/31, 8403080184
- 8403080206 "Radioactive Effluent & Waste Disposal Semiannual Rept Jul-Dac 1983 " W/840229 ltr JUHNSON, B D Consumers Power Co 83/12/31 KEPPLER, J O Region 3, Office of Director ilpp 22560.008 24X Fiche 50-255,83/12/31, 8403080206
- 8403120041 "1983 10CFR50 49 Annual Rept " W/840227 ltr JUNNSON, B D Consumers Power Co 83/12/31 KEPPLER. J G Region 3. Office of Director 5pp 22587 274 24% Fiche 50-255,83/12/31, 8403120041

- 8403120140 Monthly operating rept for Feb 1984 W/840307 Ltr CAVADAS,K J , VANDENBERG,D Consumers Power Co 84/02/29 5pp 22585 245 24X Fiche 50-255.84/02/29,8403120140
- 8 Reportable occurrences, LERs & related correspondence
- 8302020109 Forwards technical review rept. "Diesel Generator Load Sequencer Design Oeficiency - LER 82-025/01T " CHIRAMALIM Reactor Operations Analysis Branch 83/01/19 SEYFRITIK V Reactor Operations Analysis Branch 1p 22808 306 24X Fiche 50-255.83/01/19.8302020109
- --B403270350 "Diesel Generator Load Sequencer Design Deficiency LER 82-025/017." technical review rept * Reactor Operations Analysis Branch 83/01/19 3pp 22808 307 24X Fichs 50-255,83/01/19.8302020109
- 8403170101 Part 21 rept re apparent design deficiency in Siemens Allis Model MA-2058 stored energy circuit breaker. Breaker insp & hold down device orientation will be complete by 840401 Determination of permanent fix & implementation by 840601 JOHNSON, B D. VANDEWALLE, D J. Consumers Power Co. 84/02/27 KEPPLER, J G. Region 3, Office of Director 5pp 22669 305 24X Fiche 50-235,84/02/27,8403190101
- 8403i90091 PNO-iiI-84-026 on 8403i3.during insp to verify support plate integrity after tube-puiling activities.damage observed to auxiliary feedwater sparger piping in both steam generators Damage may delay May 1984 startup DEFAVETTE.R. BQYD.D Region 3. Office of Director 84/03/i3 ip 22669 227 24X Fiche 50-255.84/03/i3.8403i9009i
- B403230023 PND-III-84-027 on 840318 diver working on fuel assembly upender received radiation dose to right thigh of 4 5 rems Caused by licensee failure to identify localized high radiation field near upender GREGERL R , PAPERIELLO. C Region 3. Defice of Director 84/03/19 ip 22726 318 24X Fich 50-255.84/03/19.8403230023
- DOCKET SO-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8403060238 Emergency pian implementing procedures, including iP-2 re notification of unusual event. IP-3 re alert. iP-4 re site emergency & IP-6 re radiological emergency pian. activation at support ctr W/840228 ltr & list of effective pages MILLS.L M Tennessee Valley Authority 84/02/10 O'REILLY.J P Region 2. Office of Director 52pp 22516 078 24X Fiche 50-259.84/02/10.8403060238
- 8403060571 Advises that NRC will not review emergency glans to delete privacy or proprietary info unless specifically requested by licensee, per Bi0709 Generic Ltr Bi-27 M/o request, entire plan will be placed in PDR VASBALLO, D B Operating Reactors Branch 2 84/02/10 PARRIB, H G Tennessee Valley Authority 2pp 22552 261 24% Fiche 50-259.84/02/10.8403060571
- 8403050235 Rev 5 to Procedure iP-9, "Muscle Shoals Emergency Ctr Implementing Procedures Document " W/840213 ltr MAXWELL.R., SLIGER, E.K. Tennessee Valley Authority 84/02/13 63pp 22518 023 24X Fithe 50-000,84/02/13,8403060235
- 84030&0147 Forwards revised effective pages to Knoxviile Emergency Ctr. Central Emergency Control Ctr.Div of Nuclear Power Emergency Ctr & Muscie Shoais Emergency Control Ctr emergency plan implementing procedures W/o Muscle Shoals pages MILLS.L M Tennessee Vailey Authority 84/02/28 0'REILLY.J P Region 2. Office of Director 1p 22516 165 24x Fiche 50-000.84/02/28.8403060147
- --8403060163 Revised list of affective pages to Knoxville Emargency Ctr emargency plan implementing procedures # Tannessee Valley Authority 84/02/06 8pp 22516 166 24X Ficha 50-000.84/02/28.8403060147
- --B403060189 Revised list of effective pages to Central Emergency Control Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 8pp 22516 174 24X Fiche 50-000,84/02/28.8403060147
- --8403060206 Revised list of effective pages to Div of Nuclear Power Emergency Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 4pp 22516 182 24X Fiche 50-000,84/02/28.8403060147

- 8403160162 Act receipt of 840222 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-259/83-57, 50-260/83-57 to 50-260/83-57 to 50-260/83-57 lewis, R C pivision of Project & Resident Programs 84/02/29 PARRIS, H C Jennessee Valley Authority ip 22655 273 24x Fiche 50-259,84/02/29,8403160162
- --8403160171 Responds to NRC 840123 itr re violations noted in IE Insp Repts SO-259/83-57,50-260/83-57 % 50-296/83-57 Corrective actions policy statement issued to health physics technicians re high radiation area doors MILLS,L M Tennessee Valley Authority 84/02/22 O'REILLY, J P Region 2, Office of Director 5pp 22655 274 24X Fiche 5G-239,84/02/29,8403160162
- --8403160181 Notice of violation from insp on 831126-1225
 ** Region 2, Office of Director 84/01/23 2pp 22655 281 24X
 Fiche SO-259.84/02/29.8403160162
- --8403160186 IE lnsp Repts 50-259/83-57.50-260/83-57 & 50-296/83-57 on B31126-1225 Violations noted failure to lock high radiation area.to follow special work permit & to have adequate fire protection maint procedure PAULK.G & Ragion 2. Office of Director 84/01/21 App 22655 283 24% Fiche 50-259.84/02/29.8403160162
- 840316021B Act receipt of 840209 itr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-259/83-40, 50-260/83-40
 LENIS,R C. Division of Project & Resident Programs 84/03/01
 PARRIS.H G Tennessee Valley Authority 1p 22661 098 24%
 Fiche 50-239,84/03/01.8403160218
- --8403160223 Responds to NRC 840111 ltr re violations noted in 1E Insp Repts 30-239/83-40.50-260/83-40 & 50-296/83-40 Corrective actions radiological emergency planning program reviewed & areas requiring rev identified MiLLS.L M Tennessee Valley Authority 84/02/09 D'REILLY, J P Region 2. Office of Director 6pp 22661 099 24X Fiche 50-259.84/03/01.8403160218
- --840316023D Forwards 1E Insp Repts 50-259/83-40,50-260/83-40 & 50-296/83-40 on 83(017-2) & 1122 & notice of violation LEMIS.R C Division of Project & Resident Programs 84/01/11 PARRIS.H O Tennessee Valley Authority 2pp 2266; 105 24X Fiche 50-259,84/03/01.8403160218
- --8403160239 Notice of violation from insp on 831017-21 & 1122 * Region 2. Office of Director 84/01/11 3pp 22661 107 24X Fiche 50-259,84/03/01.8403160218
- --8403160249 1E Insp Repts 50-259/83-40,50-260/83-40 & 50-296/83-40 on 831017-21 & 1122 Noncompliance noted failure to control documents.properly thain energency personnel in protective action requirements & incorporate protective action DECKER. T.R. Region 2. Office of Director 84/01/06 9pp 22661 110 24X Fiche 50-259,84/03/01.8403160218
- 8403160345 Extends invitation to attend region 840316 workshop at regional oft to discuss 10CFR50. App R requirements & recent results of insp to help resolve misunderstandings associated w/requirements

 LEMIS.R C Division of Project & Resident Programs 84/03/02

 PARRIS.H G Tennessee Valley Authority 2pp 22660 083 24x

 Fiche 50-000.84/03/02.8403160345
- 8403130485 Ack receipt of 840119 ltr transmitting Rev 7 to security personnel training & qualification plan Rev consistent W/provisions of 100FR30 54(p) & acceptable LEHIS.R C Division of Project & Rosident Programs 84/03/08 PARRIS.H G Tennessee Valley Authority 2pp 22613 210 24X Fiche 50-257.84/03/08.8403130485
- 8403130484 Ack receipt of 840130 ltr transmitting rev to physical security plan Rev consistent w/provisions of iOCFR50 54(p) & acceptable LEMIS.R C Division of Project & Resident Programs 84/03/09 PARRIS.H G Tennessee Valley Authority 2pp 28613 197 24x Fiche 30-259.84/03/09.8403130484
- 8403160025 Advises that 840116 rev to physical security personnel training & qualification plan consistent u/provisions of 10CFR30 54(p) & acceptable LEWIB.R C Division of Project & Resident Programs 84/03/13 PARRIS.H G Tennessee Valley Authority 2pp 22650 358 24X Fiche 50-259.84/03/13.8403160025

- 8403170136 Ack receipt of 840221 & 0312 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 Responses meet 10CFR2 201 requirements LEWIG.R C Division of Project & Resident Programs 84/03/14 PARRIS.H 0 Tennessee Valley Authority ip 22670 314 24X Fiche 50-259, 84/03/14, 8403190136
- --8403190149 Supple response to NRC 840120 ltr re violations noted in 1E Insp Repts 50-299/83-59:80-260/83-59 & 50-296/83-59 Responses withheld (nef 1006R73 21) MILLS:L M Tennessee Valley Authority 84/03/12 O'REILLY, J P. Region 2: Office of Director 1p 22670 315 24X Fiche 50-259:84/03/14,8403190136
- --8403170161 Responds to NRC 840120 ltr re violations noted in IE Insp Repts 30-257/83-59, 50-260/83-59 & 50-276/83-57 Responses withheld (ref 10CFR73 21) MILLB-L M Tennessee Valley Authority 84/02/21 O'REILLY, J P Region 2. Office of Director ip 22670 316 24X Fiche 30-259, 84/03/14,8403190126
- --8403170172 Forwards IE lnsp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 on 831216 & notice of violation Notice of violation withheld (ref 100FR2 790 & 73 21)
 LEHIS,R C Division of Project & Resident Programs 84/01/20
 PARRIS,H G Tennesser Valley Authority 2pp 22670 317 24X
 Ficho 50-259,84/03/14,8403190136
- --8403190188 IE insp Repts 50-259/83-59.50-260/83-59 & 50-296/83-39 on 831216 Noncompliance noted security force member failed to control access to area Details withheld (ref 10CFR73 21 & 2.70)
 TILLMAN A Region 2. Office of Director 84/01/19 ip 22670 319 24X Fiche 50-259.84/03/14.8403190136
- B403290117 Forwards FEMA final rept for B31015-16 emergency exercise VERRELLI.D M Division of Project & Resident Programs 84/03/20 PARRIS.H G Tennessee Valley Authority 1p 22807 027 24X Fiche 50-259,84/03/20,8403290117
- O Adjudicatory correspondence
- 8403200059 Submits addl info on util initiatives in PRA, per response to B40227 itr Effort to reduce number of violations & risks maintained FREEMAN, S D Tennessee Valley Authority 84/03/12 MARKEY, E J House of Rop . Interior & Insular Affairs 2pp 22685 033 24X Ficho 50-259, 84/03/12, 8403200059
- J insurance & indemnity information
- 8403060334 Forwards Endorsoment 73 to NELIA Policy NF-198 DUCK.JR Marsh & McLenman. Inc. 84/02/28 SALTZMAN.J Assistant Director for State & Licensee Relations 2pp 22516 009 24X Fiche 50-259.84/02/28.8403060334
- P Operating license stage documents & correspondence
- 8403060076 Forwards request for add1 info re inservice testing of pumps & valves, in order to complete review of 820831 & 830406 submittals Response requested within 45 days of itr receipt VASSALLO, D B Operating Reactors Branch 2 84/02/10 PARRIS, H O Tennessee Valley Authority 4pp 22528 288 24X Fiche, 50-257, 84/02/10, 8403060076
- B403140340 Summary of B31215 meeting w/GE & Mark I Owners Group in Bethesda.MD re Mark I containment wetwell-drywell vacuum breaker design methodology BIE0EL.B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fiche 50-000, 84/02/21, 8403140340
- B403010306 Application for amend to Licenses DPR-33.DPR-52 & DPR-48. changing Tech Specs to lower Group 1 isolation setpoint for reactor lower water level W/proprietary NEDE-30012, " MSIV Water Level "Rept withheld (ref iOCFR2.790) HILLS.L M Tennessee Valley Authority 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22433 042 24% Fiche 50-259, 84/02/22, 8403010306
- --B403010313 Proposed changes to Tech Specs lowering Group 1 isolation setpoint for reactor lower water level W/affidavit + Tennesses Valley Authority B4/02/22 29pp 22433 045 24X Fichs 50-259,84/02/22,8403010304

;

Ţ

DOCKETED ITEMS

- 8403150323 Forwards info re BNL dose reduction project plant visit info allows BNL personnel to better prepare for station visit, espedite paperwork & minimize impact on plant personnel VASSALLO, D B Operating Reactors Branch 2 84/02/28 PARRIS, H G Tennessee Vailey Authority 46pp 22662 040 24X Fiche 50-259,84/02/28,8403150323
- 8403:30007 Forwards response to Generic Ltr 83-36 re MyREG-0737 Tech Specs MILLS,L M Tennessee Valley Authority 84/03/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 3PP 22613 349 24X Fiche 50-259,84/03/07,8403130007
- 8403130025 Informs that addi info requested on 831012 re reactor protection sys power monitoring sys design mods will be submitted by 840702 MILLS.L M Tennessee Valiny Authority 84/03/07 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 22614 362 24x Fiche 50-259.84/03/07.8403130025
- 8403160247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rev 7 to topical QA program per 840302 telcon LEWIS, R C Region 2. Office of Director 84/03/08 PARRIB, H G Tennessee Valley Authority 1p 22660 361 24X Fiche 50-000.84/03/08.8403i60247
- B403160373 Notifies of use of ABME Nuclear Components Code Case N32-4 for hydrostatic testing of Class 3 embedded piping NRC position re use of Code Case N32-4 requested MILLB.L M Tennessee Vailey Authority 84/03/12 DENTON,H R. Office of Nuclear Reactor Regulation, Director ip 22660 014 24X Fiche 30-000.84/03/12.8403160373
- 8403130275 Centric Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe repiacement at BWRs Svc list enci EIBENHUT.D 0 Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 82823 354 24X Fiche 50-000.84/03/14.8403150275
- 6403200170 Forwards response to Item 4 5 of Deneric Ltr 83-28,
 "Required Actions Based on Generic implications of Baiem
 ATMS Events" re reactor trip sys reliability Control rod
 tests check rod insertion times & hydraulic scram valves
 MILLG.L M Tennessee Valley Authority 84/03/15 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 10pp 22700 024
 24X Fiche 50-257,84/03/15,8403200170
- B403260229 Forwards addl info re test configuration & results of verification testing, per B40106 request re adequacy of station electric distribution sys voltages Test results indicated no unexpected voltage leveis MILLGL M Tennessee Vality Authority B4/03/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 26pp 22756 124 24X Fiche 50~259, 84/03/19, 8403260229

O Inspection reports, IE Builetins & correspondence

- B403070034 Responds to NRC 1tr re violations noted in iE Insp Repts 50-259/83-09.50-260/83-09 & 50-295/83-09 List of identified deficiencies & implementation schedule provided to senior NRC inspector on B3090i MILLS.L M Tennessee Valley Authority B3/09/15 D'REILLY, J P Region 2. Office of Director ip 22547 261 24X Fichs 50-259,83/09/15,8403070054
- 8403070237 Updates 830715 response to NRC 830616 itr re violations noted in IE Insp Repts 50-259/83-19,50-260/83-19 & 50-276/83-19 Operating instructions revised & Units 2 & 3 PBC charping sys operational MILLS.L M Tennessee Valley Authority 83/09/30, 0'REILLY, J P Region 2. Office of Director ip 22541 361 24X Fiche 50-259,83/09/30,8403070237
- 8403070271 Supple 830830 response to NRC ltr re violations noted in iE Insp Repts 50-259/83-23,50-260/83-23 & 50-276/83-23 Boral test specimen installation will be delayed until 831028 due to late receipt of matis per 831012 telcon KAMMER, D S Tennessee Valiey Authority 83/10/21 0'REILLY, J P Region 2, D#fice of Director 1p. 22546 356 24X Fiche 50-259,83/10/21,8403070271
- 8403070023 Responds to NRC ltr re violations noted in IE Insp Repts 50-259/83-27.50-260/83-27 & 50-296/83-27 Corrective actions compliance w/instructions will be achieved & corrective actions will be completed before Cycie & operation MILLG.L M Tennessee Vailey Authority 83/10/27 O'REILLY, J P Region 2. Office of Director ip 22541 262 24X Ficher 50-259,83/10/27,8403070023

- B403070067 Forwards iE Insp Repts 50-259/83-50, 50-260/83-50 & 50-296/83-50 on B30912-16 & 26-30 Unresolved item re possible high radiation doses measured by personnel dosimeters, discussed on B31028, considered closed O'REILLY, J P Region 2. Office of Director 84/01/11 PARRIS, H & Tennessee Vailey Authority 2pp 22545 341 24X Fiche 50-259, 84/01/11, 8403070067
- --8403070072 iE Insp Repts 50-259/83-50.50-260/83-50 & 50-296/83-50 on 831028 No violations or deviations noted Major grees inspected TLD & multiple badging DEBs T Region 2. Office of Director 83/12/05 5pp 22545 343 24X Fiche 50-259.84/01/11.8403070067
- 8403160232 Forwards IE Insp Repts 50-259/84-04.50-260/84-04 & 50-296/84-04 on 840123-27 No violations or deviations noted VERRELLI.D M Division of Froject & Resident Programs 84/02/16 PARRIES M G Tennessee Valley Authority 2pp 22661 029 24X Fiche 50-259.84/02/16.8403160232
- --8403160238 iE Insp Repts 50-259/84-04.50-260/84-04 & 50-296/84-04 on 840123-27 No violations or deviations noted Major areas inspected startup testing, new fuel receipt, plant tours & MBIV repair status DAVENPORT, K E Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 84/02/14 5pp 22661 031 24X Fiche 50-259,84/02/16,8403160232
- 8401190072 iE infa Notice 84-13, "Potential Deficiency in Mator Operated Valve Control Circuits & Annunciation " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/28 Consolidated Edison Co of New York, Inc 113pp 22909 239 24X Fiche 50-000.84/02/28,8401190072
- B403i60162 Ack receipt of 840222 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/B3-57, 50-260/B3-57 & 50-296/B3-57 LEWIB.R C Division of Project & Resident Programs 84/02/29 PARRIS.H O Tennessee Valley Authority ip 22655 273 24X Fiche 50-259,84/02/29,8403160162
- --8403160171 Responds to NRC 840123 ltr re violations noted in IE insp Repts 50-259/83-57, 50-260/83-57 & 50-296/83-57 Corrective actions policy statement issued to health physics technicians re high radiation area doors MILLS.L M Tennesse Valley Authority 84/02/22 O'REILLY, J P Region 2. Office of Director 5pp 22655 274 24X Fiche 50-259,84/02/29,8403160162
- --8403160178 Forwards 12 Insp Repts 50-259/83-57.50-260/83-57 & 50-294/83-57 on 831126-1225 & notice of violation LEWIG.R C Division of Project & Resident Programs 84/01/23 PARRIS,H G Tennessee Valley Authority 2pp 22655 279 24x Fiche 50-259,84/02/29,8403160162
- --8403160181 Notice of violation from insp on 831126-1225 * Region 2, Office of Director 84/01/23 2pp 22655 281 24x Fiche 50-259,84/02/29,8403160162
- --B403160186 IE Insp Repts 50-259/83-57.50-260/83-57 & 50-296/83-57 on B31126-1225 Violations noted failure to lock high radiation area, to follow special work permit & to have adequate fire protection maint procedure PAULK.0 L Region 2. Office of Director CANTRELL,F B Division of Project & Resident Programs 84/01/21 6pp 22655 283 24X Fiche 50-259,84/02/29,8403160162
- 8403160218 Ack receipt of 840207 ltr informing NRC of steps taken to correct violations noted in iE insp Repts 50-259/83-40, 50-260/83-40 & 50-296/83-40 & Froject & Resident Programs 84/03/01 PARRIS, H G Tennessee Vailey Authority ip, 22661 078 24X Fiche 50-257,84/03/01,8403160218
- --8403160223 Responds to NRC 840111 itr re violations noted in IE insp Repts 50-259/83-40, 50-260/83-40 & 50-294/83-40 Corrective actions radiological emergency pianning program reviewed & areas requiring revidentified MiLLS.L M Tennessee Vailey Authority 84/02/09 0'REILLY.J P Region 2. Office of Director App 22661 099 24X Fiche 50-259,84/03/01.8403160218
- --8403160230 Forwards IE insp Repts 50-259/83-40, 50-260/83-40 & 50-276/83-40 on 831017-21 & 1122 & notice of violation LEWIB.R C Division of Project & Resident Programs 84/01/11 PARRIS,H G Tennessee Valley Authority 2pp 22661 105 24X Fiche 50-259,84/03/01.8403160218
- --8403160239 Notice of violation from insp on 831017-21 & 1122 * Region 2, Office of Director 84/01/11 3pp 22661 107 2 Fiche 50-259,84/03/01,8403160218

- --8403160244 IE Insp Repts 50-259/83-40,50-260/83-40 & 50-296/83-40 on 831017-21 & 1122 Noncompliance noted failure to control documents.properly train emergency personnel in protective action requirements & incorporate protective action DECKER, T.R. STODDART, P.G. Region 2, Office of Director JENKINS, G.R. Division of Emergency Preparedness & Materials Safety 84/01/06 9pp 22661 110 24% Fiche 50-239,84/03/01,8403160218
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE,J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24% Fiche 50-000.84/03/02.8402090007
- 8402090008 IE into Notice 84-16. "Failure of Automatic Sprinkler Sys-Valvas to Operate " Svc 11st encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Cansolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 JE Info Notice 84-15, "Reporting of Radiological Releases"

 Evc list enci.

 JURDAN, E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/03/02 Consolidated Edison Co of New

 York, Inc ii9pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8403080213 EN-84-007. on B40307. notice of violation & proposed imposition of civil penalties in amount of \$40,000 to be issued Action based on failure to control access into vital area due to guard leaving post ROSAND.R. AXELRAD.J Director's Office. Office of Inspection and Enforcement 84/03/02 1p 22560.021 24X Fiche.50-259,84/03/02.8403080213
- 84020900ii IE info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidate Edison Co of New York, Inc i17pp 22553 336 24X Fiche 50-000,84/03/05,84020900ii
- 84031&0308 Act receipt of 840217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-259/83-56 LEWIS-R C Division of Project & Resident Programs 84/03/05 PARRIS, H G Tennessee Veiley Authority 1p 22660 085 24X Fiche 50-259.84/03/05.8403160308
- --8403160318 Responds to NRC 840117 ltr re violations noted in 15 Insp Rapts 50-259/83-56, 50-260/83-56 & 50-296/83-56 Corrective actions 10% retest sample calculation made for all snubbers within Category/Group 3 Mill.S.L.M Tennessee Valley Authority 84/02/17 D'REILLY, J.P. Ragion 2, Office of Director 2pp 22660 086 24X Fiche 50-259, 84/03/05, 8403160308
- --8403160328 Forwards iE Insp Repts 30-257/83-56.50-260/83-56 & 50-2576/83-56 on 831213-16 & notice of violation LEWISLR C Division of Project & Resident Programs 84/01/17 PARRISH 0 Tennessee Valley Authority 2pp 22660 088 24% Fiche 50-259.84/03/05.8403160308
- --8403160332 Notice of violation from insp on 831213-16 * Region 2. Office of Director 84/01/17 ip 22660 090 24x Fiche 50-259.84/03/05.8403160308
- --8403160339 IE Insp Repts 50-259/B3-56,50-260/B3-56 & 50-296/B3-56 on B31213-16 Vibiation noted failure to test addi iOX sample for each shubber that failed functional test WHITENER, H. Repion 2, Office of Director JAPE, F. Division of Engineering & Operational Programs B4/01/10 Bpp 22660 091 24X Fiche 50-239,84/03/05,8403160308
- 1403290237 Forwards IE Insp Repts 50-259/84-05.50-260/84-05 & 50-296/84-05 en 840130-0201 No violations or deviations identified VERRELLI, D M Division of Project & Resident Programs 84/03/05 PARRIS, H G Tennessee Valley Authority 2pp 22800 229 24X Fiche 50-259.84/03/05.8403290237
- --8403290239 IE Insp Repts 30-259/84-03, 50-260/84-03 & 50-296/84-03 on B40130-0201. No violations or deviations identified Major areas inspected following of IE Subjetin 81-03. review of LERs re Builetin & procedures for flow reverification tests. CUNNINOHAM: A L Region 2. Office of Director MONTOOMERY, D H Division of Engineering & Operational Programs 84/03/02 Spp 22803 231 24X Fiche 50-259.84/03/03,8403290237
- 8402090024 IE Info Notice 84-09. Rev i, "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc iist encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24% Fiche 50-000,84/03/07. B402090024

- B402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR
 Bys " Sys " Sist and I
 UDRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co of New
 York Inc 118pp 22584 186 24x Fiche 50-000.64/03/07.8402090028
- B403160273 Forwards IE Enforcement Conference Repts 50-259/84-06, 50-240/84-06 & 50-276/84-06 on 840224 O'REILLY, J P Region 2, Office of Director 84/03/08 PARRIS, H Q Tennessee Valley Authority 2pp Fichs 50-259,84/03/08
- --B403160282 IE Enforcement Conference Repts 50-259/84-06. 50-260/84-06 & 50-296/84-06 on 840224 Major items discussed bypassing rod sequence control sys while shutting down & isolation of drywell to pool pressure instrument
 BUTCHER.R C Region 2. Office of Director CANTRELL.F 8
 Division of Project & Resident Programs B4/02/27 4pp
 22661 006 24X Fiche 50-259.84/03/08.8403160273
- 8402070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " 8vc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12.8402090031
- 8403:90136 Ack receipt of 840221 & 0312 ltrs informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-259/83-59, 50-260/83-59 & 50-259/83-59 Responses meet 10CFR2 201 requirements LEWIS, R C Division of Project & Resident Programs 84/03/14 PARRIS, H G Tennessee Valley Authority 1p 22670 314 24X Fiche. 50-259, 84/03/14.8403190136
- --8403190149 Suppis response to NRC 840120 ltr re violations noted in IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 Responses withheld (ref 100FR73 21) MILLS, L M Tennessee Valley Authority 84/03/12 O'REILLY, J P Region 2, Office of Director 1p 22670 315 24X Fiche 50-259,84/03/14,8403190136
- --8403190161 Responds to NRC 840120 itr re violations noted in IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 Responses withheld (ref 10CFR73 21) MILLS,L M Tennessee Valley Authority 84/02/21 O'REILLY, J P Region 2. Office of Director ip 22670 316 24X Ficho 50-259,84/03/14,8403190136
- --8403190172 Forwards IE Insp Repts 50-259/83-59.50-260/83-59 & 50-296/83-59 on 831216 & notice of violation Notice of violation withheld (ref 100FR2 790 & 73 21)
 LEMIS.R C Division of Project & Resident Programs 84/01/20
 PARRIB.H G Tennessee Valley Authority 2pp 22670 317 24X
 Fiche 50-259.84/03/14.8403190136
- --B4031901B8 1E Insp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 on 831216 Noncompliance noted security force member failed to control access to area Details withheid (ref iOCFR73 21 & 2 790)
 TILLMAN, A., PATTERBON, C. Region 2, Office of Director MCGUIRE, D.R. Division of Emergency Preparedness & Materials Bafety 84/01/19 1p 22670 319 24X Fiche 50-259, 84/03/14, 8403190136
- 8403290047 Summarizes 840312 meeting in Region II ofc re planned util organizational changes & regulatory performance improvement program for facility

 B'REILLY, J.P. Region 2, Office of Director 84/03/15 PARRIS, H. O. Tennessee Valley Authority ip 22806/271 24X
 Fiche 50-239,84/03/15,8403290047
- 8403290178 Ack receipt of 840217 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-259/83-38, 50-260/83-88 & 50-278/83-38

 LEMIS.R C Division of Project & Resident Programs 84/03/20

 PARRIS.H G Tennessee Vailey Authority ip 22800 278, 24X

 Fiche 50-259,84/03/20,8403290178
- --8403290183 Supply response to NRC 840119 ltr re violations noted in 1E Insp Repts 50-259/83-38, 50-260/83-38 & 50-296/83-38 Corrective actions distribution of insp rept to health physics personnel initiated HILLS.L M Tennessee Valley Authority 84/02/17 O'REILLY, J P Region 2. Office of Director 2pp 22800 279 24X Fiche 50-259,84/03/20,8403290178
- --B403290190 Ack receipt of 831209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-3B, 50-260/83-38 & 50-296/83-38 O'REILLY.J P Region 2, Office of Director 84/01/19 PARRIS.H O Tennessee Valley Authority 2pp 22800.281 24X Fiche 50-259,84/03/20,8403290178

- --8403270203 Ack recript of B31209 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50~237/83-38, 50~294/83-38 LEWIS.R C Division of Project & Resident Programs 83/12/21 PARRIE.H 0 Tennessee Valley Authority ip 22800 283 24X Ficha 50~259, 84/03/20, 8403290178
- --8403290207 Responds to NRC B31109 ltr re violations noted in IE Insp Repts 50-259/83-38,50-260/83-38 & 50-296/83-38 Corrective actions insp rept distributed to health physics personnel & RCI-5 revised to incorporate loCFR49 changes MILLB,L M Tennessee Valley Authority B3/12/09 U'REILLY,JP Region 2, Optice of Director 5pp 22800 284 24X Fiche 50-259,84/03/20,8403290178
- --8403290211 Forwards IE Insp Repts 50-259/83-38, 50-260/83-38 & 50-296/83-38 on 830912-16 & notice of violation LENIB,R C Division of Project & Resident Programs 83/11/09 PARRIS,H G Tennessee Valley Authority 2pp 22800 289 24X Fiche 50-259,84/03/20,8403290178
- --8403290214 Notice of violetian from insp on 830912-16 * Region 2, Office of Director 83/11/09 2pp 22800 291 24X Fiche 50-259,84/03/20,8403290178
- --8403290220 IE Insp Repts 50-259/83-38, 50-260/83-38 & 50-296/83-38 on 830912-16 Violations noted 55-gallon drum reading 30 to 65 millirem per hour observed uniabeled & radiation control procedures not prepared or adhered to DEBB, B T Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/11/03 6pp 22800 293 24X Fiche 50-259, 84/03/20, 8403290178
- B402090043 IE Info Notice B4-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc ilst encl
 JORDAN, E L Division of Emergency Preparedness & Englneering
 Response (Post B30103) B4/03/21 Consolidated Edison Go of New
 York, Inc i23pp. 22823 229 24X Fiche 50-000,84/03/21,8402090043
- B402090044 IE Info Notice 8A-20, "Byc Life of Relays in Safety-Related Bys " Byc list and JURDAN, E L Division of Emergency Preparednoss & Englneering Response (Post 830103), 84/03/21 Consolidated Edison Co of New York, Inc. 135pp. 22933 001 24X Fiche 50-000,84/03/2i,8402090044

R Periodic operating reports & related correspondence

- 84030R0103 Monthly operating repts for Jan 1984 W/840210 itr CHAPMAN,M , THOM,T., JONES.O T. Tennessee Valley Authority 84/01/31. 41pp 22443 166 24X Fiche 50-257,84/01/31.8403020103
- 8403300133 Forwards monthly operating repts for Feb 1984 & corrected Jan 1984 monthly operating rept for Unit 1 JONES: 0 T Tennessee Valley Authority 84/03/09 Office of Recourse Management. Director. 1p 22820 203 24X Fiche 50-259.84/03/09.8403300133
- --B403300134 Monthiu operating repts for Feb 1984
 THOM.T Tennessee Vailey Authority 84/02/29 37pp 22820 204
 24X Fiche 50-259,84/03/09,8403300133
- --8403300137 Corrected monthly operating rept for Jan 1784 CHAPMAN, M Tennesses Volley Authority B4/01/31 2pp 28220 243 24X Fiche 30-237, 84/03/09, 8403300133

8. Reportable occurrences, LERs & related correspondence

- 8403010226 Updated LER 83-016/03X-1 on 830309; offsite analysis of charcoal sample from control room emergency wantilation sys showed methyl iddide removal efficiency less than required Caused by degradation of stored charcoal W/840215 ltr CLARX.JR., JONES, O T Tennesse Valley Authority 84/02/15 O'REILLY,J,P Region 2, Diffice of Director. 5pp 22435, 238 24X Fiche, 50-259, 84/02/15, 8403010226.
- 8403020325 Updated LER 83-029/03L-1 on 830604, during standby gas treatment sys operability test, train B found inoperable Causad by erratic McDonnel & Miller Model AF-i flow switches Damper 0-65-503 adjusted. W/840221 ltr CARTER. S. D. JCHES, O T Tennessee Valley Authority 84/02/2i 0'REILLY, J P Region 2, Office of Director 3pp. 22439, 312 24X Fiche 50-259, 84/02/21, 8403020325
- 8403010371 LER 84-008-00 on 840129, during normal operation, one or more pressure differential transmitter instrumentation 1-25A through D failed in downscale direction causing trouble alerm, Cause unknown, Instruments recalibr, WF40223 1tr MARKIN, K M , JONES, G T Tennesse Valley Authority 84/02/23. 4pp 22433:089 24X Fiche 50-259, 84/02/23, 8403010371

- 8403060244 LER 84-010-00 on 840203 operator observed hydrogen-oxygen analyzer B isolated Caused by faulty Group 6 isolation relay signal Signal reset & h; & low relays replaced W/840228 ltr MORKIN, K M; JONES, G T Tennesse Valley Authority 84/02/28 3pt 22515 178 24X Fiche 50-259,84/02/28,8403060244
- 8403260233 Forwards summary list of deficiencies identified per 10CFR30 55(e).Part 21 & potential generic itr repts for comments
 STAROSTECKI.R Division of Project & Resident Programs 84/02/28 Region 1. Office of Director 7pp 22736 063 24X
 Fiche 50-000.84/02/28.8403260233
- B403090085 LER 84-011-00 on 840209, during routine surveillance testing, automatic scram initiated Caused by failure of MSIV dc solenold Failure considered random event Solenoid coils checked weekly for operability W/B40229 itr
 BMITH, D L , JONES, O T Tennessee Vailey Authority 84/02/29 3pp 22575 317 24X Fiche 50-259, 84/02/29, 8403090085
- 8403090245 Followup LER 84-007-01 on 840127, operator observed decreasing pressure on control atmospheric dilution tanks Caused by two isolation valves being in closed position Operating instructions revised W/840302 itr
 WALKER, J B , JONES, O T Tennessee Valley Authority 84/03/02 3pp 22573 253 24X Fiche 50-259,84/03/02.8403090245
- B403090253 LER B4-0i3-00 on B40213; air & Vacuum release vaives found underrated for surge check vaive svc application Caused by misapplication of valve New vaives: w/proper design & pressure rating, installed W/40302 ltr HALKER, J B , JONEB, O T Tennessee Vailey Authority B4/03/02 3pp 22573 254 24X Fiche 50-259, B4/03/02; B403090253
- B403130205 LER B4-012-00 on B40214.RHR valve FCV-i-74-4B failed to open making normal method cold shutdown impossible to achieve Possibly caused by failure of Phase B motor winding Next rept will be submitted by 840901 W/840306 ltr ROZEAR.C J. JUNES,0 T Tennessee Vailey Authority B4/03/06 3pp 22617 292 24X Fiche 50-259, 84/03/06.B403130205
- 840317037i LER 84-015-00 on 840221, during ongoing design review of plant sys, discovered that emergency squipment cooling water vacuum priming vaive on notth header underdesigned for sys pressure Cause not stated Valve isolated W/840309 itr BHITH.D L. JONES.O T Tennessee Valley Authority 84/03/09 3pp 22675 304 24% Fiche 50-295,84/03/09,840319037i
- B4032002i3 Updated LER 83-066/03x-1 on B3iti2, interiock that prevents bridge travel over core w/one rod withfraum & fuel grappie extended failed to operate, resulting in loss of rod block function Caused by improper adjustment W/840309 itr HOLDER: E T , JONEB, O T Tennessee Valley Authority B4/03/09 O'REILLY, J P Region 2, Office of Director 6pp 22699 314 24X Fiche 50-259,84/03/09,8403200213
- 8403190125 LER 84-014-00 on 840222, reactor scramped when turbing high pressure first stage pressure exceeded 142 psig w/ turbing stop valves closed Caused by procedural error Operating instruction will be revised W/840313 ltr ROZEAR, CJ J. UDMEB, O T Tennesse Valley Authority 84/03/13 3pp 22668 248 24X Fiche 50-259,84/03/13.8403190125
- B403220046 Updated LER 84-014-01 on 840222 reactor scrammed when turbine high pressure first stage pressure exceeded 142 psig w/turbine stop vaives closed Caused by procedural error.

 Operating instruction revised W/840316 ltr
 RDZEARC J , JDMES.6 T Tennesses Vaiisy Authority B4/03/13 3pp 22712 194. 24X Fiche 50-259,84/03/13.8403220046

V Operator Examinations

- 8403160227 Confirms 840302 meeting in Atlanta, 0A re 840319 operator requalification exam, per 840229 telcon
 LEMIS,R C Division of Project & Resident Programs 84/03/01
 PARRIS,H O Tennessee Vailey Authority 1p 22660 328 24X
 Fiche 50-259,84/03/01.8403160227
- 8403290322 Discusses 840117 ltr confirming arrangements for administration of requalification exams Random selection process used to determine identify of examines for written & oral exams List of examiness encl LEMIS.R C Division of Project & Resident Programs 84/03/13 PARRIS.H O Tennessee Valley Autority 3pp 22802 049 24X Fiche. 50-259.84/03/13.8403290322
- 8403270213 Summarizes 840302 meeting w/util re 840323 requalification exam of licensed operator & senior operator personnel at facilities. Meeting provided better understanding of operator requalification training & exam programs
 LEMIS, R C Division of Project & Resident Programs 84/03/15
 PARRIS, H 0, Tennessee Valley Authority 3pp 22800 360 24X
 Fiche 50-257,84/03/15,8403270213

- DOCKET 50-260 BROWNS FERRY NUCLEAR FOHER STATION, UNIT 2

 F. Security, medical, emergency & fire protection plans
- 8403040238 Emergency plan implementing procedures, including IP-2 re notification of unusual event, IP-3 re alert, IP-4 re site emergency plan, activation at support ctr W/840228 ltr & list of effective pages MILLS.L M Tennessee Valley Authority 84/02/10 D'REILLY, J P Region 2. Office of Director 52pp 22516 098 24X Fiche 50-259,84/02/10,8403060238
- 8403040371 Advises that NRC will not review emergency plans to delete privaty or proprietary info unless specifically requested by licensee.per 810707 Ceneric Ltr 81-27 M/o request.entire plan will be placed in PDR VASSALLO.D B Operating Reactors Branch 2 84/02/10 PARRIS.H G Tennessee Valley Authority. 2pp 22552 261 24X Fiche 50-257.84/02/10.8403040571
- 8403060235 Rev 5 to Procedure IP-9, "Muscle Shoals Emergency Ctr Implementing Procedures Document " W/840213 ltr MAXMELL,R. SLIGER,E K Tennessee Valley Authority B4/02/13 ADpp 22518 023 24% Fiche 50-000.84/02/13.8403060235
- 8403060147 Forwards revised effective pages to Knozville Emergency Ctr. Central Emergency Control Ctr.Div of Nuclear Power Emergency Ctr. & Muscle Shoals Emergency Control Ctr smergency plan implementing pracedures W/o Muscle Shoals pages MILLS.t. M. Tennesses Valley Authority 84/02/28 0'REILLY.J.P. Region 2. Office of Director 10. 22516-165 24X Fiche 50-000.84/02/28.8403060147
- --8403060163 Revised list of effective pages to Knoxville Emergency Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 8pp 22516 166 24X Fiche 50-000,84/02/28,8403060147
- --8403050189 Revised list of effective pages to Centr41 Emergency Control Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 8pp 22516 174 24X Fiche 50-000,64/02/28.8403060147
- --8403050206 Revised list of effective pages to Div of Nuclear Power Emergency Ctr emergency plan implementing procedures * Tennessee Valiey Authority 84/02/06 4pp 22516 182 24X Fiche 50-000, 84/02/28.8403060147
- 84031&0162 Ack receipt of B40222 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-259/83-57, S0-260/83-57 & 50-259/83-57
 LEWIS.R C Division of Project & Resident Programs 84/02/29 PARTIS.H G Tennessee Valley Authority in 22655 273 24x Fiche 50-259, 84/02/29, 8403160162
- --B403160171 Responds to NRC 840123 itr re violations noted in IE Insp Repts 50-259/83-57, 50-260/83-57 & 50-296/83-57 Corrective actions policy statement issued to health physics technicians re high radiation area doors MILLS.L.M Tennessee Valley Authority B4/02/22 O'REILLY, J.P. Region 2, Office of Director Spp 22655 274 24x Fiche 50-259,84/02/29,8403160162
- --8403160181 Notice of violation from insp on 831126-1225 • Region 2, Office of Director 84/01/23 2pp. 22655 281 24X Fiche 50-259,84/02/29.8403160162
- --8403160186 IE [nsp Repts 50-259/83-57, 50-260/83-57 & 50-296/83-57 on 831126-1225 Violations noted failure to lock high radiation areas to follow special work permit & to have adequate fire protection maint procedure.

 PAULK, G L. Region 2, Office of Director 84/01/21 App 22555 283 24X Fiche 50-259,84/02/29,8403160162
- 8403160218 Ack receipt of 840209 ltr informing NRC of steps taken to correct violetions noted in IE Insp Repts 50-239/83-40, 50-280/83-40 & 50-296/83-40 EBHS,R C Division of Project & Resident Programs 84/03/01 PARRIS.H 0 Tennessee Valley Authority ip 22661 098 24X Fiche 50-259,84/03/01,8403160218
- --8403160223 Responds to NRC 840111 ltr re violations noted in 1E Insp Repts 50-259/83-40, 50-260/83-40 & 50-296/83-40 Corrective actions radiological emergency planning program reviewed & areas requiring rev identified MILLS,L.M Tennessee Veiley Authority 84/02/09, D'REILLY, J P Region 2, Office of Director 6pp 22661 099 24x Fiche 50-257,84/03/01,8403160218

- --8403160230 Forwards IE Insp Repts 50-259/83-40, 50-260/83-40 & 50-296/83-40 on 831017-21 & 1122 & notice of violation LEWIS:R C Division of Project & Resident Programs 84/01/11 PARRIS:H 0 Tennessee Valley Authority 2pp 22661 105 24) Fichs 50-259:84/03/01,840316021B
- --8403160239 Natice of violation from insp on 831017-21 & 1122 * Region 2. Office of Director 84/01/11 3pp 22661 107 24X Fiche 50-259,84/03/01.8403160218
- --8403160244 IE Insp Repts 50-259/83-40, 50-260/83-40 & 50-296/83-40 on 831017-21 & 1122 Noncompliance noted failure to control documents, properly train emergency personnel in protective action requirements & incorporate protective action BECKER.TR Region 2, Office of Director 84/01/04 9pp 22661 110 24X Fichs 50-259,84/03/01.8403160218
- 8403160345 Extends invitation to attend region 840316 workshop at regional ofc to discuss 10CFR50. App R requirements & recent results of insp to help resolve misunderstandings associated W/raquirements

 LEWISHR C Division of Project & Resident Programs 84/03/02 PARTIS, H G Tennessee Valley Authority 2pp 22660 083, 24X Fiche 50-000, 84/03/02,8403160345
- B403:30485 Ack receipt of B401:9 itr transmitting Rev 7 to security personnel training & qualification plan Rev consistent w/provisions of 100FR50 54(p) & acceptable LEWIG.R C Division of Project & Resident Programs B4/03/08 PARRIB,H 0 Tennessee Valley Authority 2pp 22613 210 24X Fiche 50-259.84/03/08,8403130485
- B4031304B4 Att receipt of B40130 ltr transmitting rev to physical security plan Rev consistent w/provisions of iOCFR50 54(p) & acceptable LEWIB,R C Division of Project & Resident Programs 84/03/09 PARRIS,H 0 Tennessee Valley Authority 2pp 22613 197. 24X Fiche 50-239, 84/03/09, 8403130484
- 8403160025 Advises that 840116 rev to physical security personnel training & qualification plan consistent w/provisions of 100FRS0 54(p) & acceptable
 LEWIS.R C Division of Project & Resident Programs 84/03/13
 PARRIB.H G Tennessee Valley Authority 2pp 22653 358 24X
 Fiche 50-259,84/03/13,8403160025
- 8403190136 Ack receipt of 840221 & 0312 ltrs informing NRC of steps taken to turrect violations noted in IE lnsp Repts 50-257/83-59, 50-260/83-59 & 50-296/83-59 Responses meet 10CFR2 201 requirements LEWIS,R C Division of Project & Resident Programs 84/03/14 PARRIS.H G Tennessee Vailey Authority 1p 22670 314 24X Fiche 50-259.84/03/14,8403190136
- --8403170149 Supple response to NRC 840120 ltm re violations noted in IE Insp Repts 50-257/83-59, 50-260/83-59 & 50-296/83-59 Responses withheld (ref 100FR73 21). MILLS, L M Tennesse Valley Authority 84/03/12, 0'REILLY, J P Region 2, Office of Director ip. 22670 315 24X Fichs 50-259,84/03/14,8403190136
- --8403190161 Responds to NRC 840120 itr re violations noted in 1E Insp Repts 50-259/83-59, 50-260/83-59 & 50-294/83-59 Responses withheld (ref 10CFR73 21) MILLS, L M Tennessee Vailey Authority 84/02/21 D'REILLY, J P Region 2, Office of Director 1p 22670 316 24X Fichs 50-259,84/03/14,8403190136
- --8403190172 Forwards IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-276/83-59 on 831216 & notice of violation Notice of violation withheld (ref 100FR2 790 & 73 21)

 LEWIS.R C Division of Project & Resident Programs 84/01/20

 PARRIS.H G Tennessee Valley Authority 2pp 22670 317 24X

 Fiche 50-259,84/03/14,8403190136
- --8403190188 IE Insp Repts 50-259/83-59, 50-240/83-59 & 50-296/83-59 on 831214 Noncompliance noted security force member failed to control eccess to area Details withheld (ref 10CFR73 21 & 2 790)
 TILLMAN,A Region 2, Office of Director 84/01/19, 1p. 22470, 319 24X Fiche 50-259, 84/03/14, 8403190134.
- 8403270117 Forwards FEMA final rept for 831015-16 emergency exercise, VERRELLI,D M Division of Project & Resident Programs 84/03/20 PARRIB,H.O Tennessee Valley Authority 1p 22807,027 24X Fichs 50-257.84/03/20,8403270117.

Adjudicatory correspondence

B403200059 Submits add1 info on util initiatives in PRA.per response to B40227 Itr Effort to reduce number of violations & risks maintained FREEMAN.8 D Tennessee Valley Authority B4/03/12 MARKEY.E J House of Rep , Interior & Insular Affairs 2pp 22685 033 24X Fishs 50-239.84/03/12.8403200059

J. Insurance & indemnity information

- B403060334 Forwards Endorsement 73 to NELIA Policy NF-198 DUCK, J R Harsh & McLennan, Inc 84/02/28 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 22516 009 24X Fiche 50-259, 84/02/20, 8403060334
- P Operating license stage documents & correspondence
- 840306076 Forwards request for add1 info re inservice testing of pumps & valves, in order to complete review of 820831 & 830405 submittals Response requested within 45 days of 1tr receipt VABSALLQ, D. B. Operating Reactors Branch 2 84/02/10 PARRIS.H Q Tennesses Valley Authority 4pp 22528 288 24X Ficher 50-259.84/02/10.8403060076
- 8403140340 Summary of B31215 meeting w/GE & Mark I Owners Group in Bethesda, MD rs Mark I containment wetweii-drywell vacuum breaker design methodology BEEGEL, B L Operating Reactors Brench 2 B4/02/21 Operating Reactors Brench 2 5ipp. 22635 178 24x Fiche 50-000,84/02/21, B403140340.
- 8403010306 Application for amend to Licenses DPR-33 DPR-52 & DPR-68, changing Tech Specs to lower Group 1 isolation setpoint for reactor lower water level M/proprietary NEDE-30012, " .MSIV Water Level. "Rept withheld (ref 100FR2 790) MILLS.L M Tennessee Valley Authority 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22433 042 24X Fiche 50-259,84/02/22,8403010306
- --8403010313 Proposed changes to Tech Specs lowering Group 1 isolation setpoint for reactor lower water level W/affidavit * Tehnessee Vailey Authority 84/02/22 29pp 22433,045 24X Fiche 50-259.84/02/22.8403010306
- B403150323 Forwards info re BNL dose reduction project plant visit info allows BNL personnel to better prepare for station visit, expedite paperwork & minimize impact on plant personnel VASBALLO, D B Operating Reactors Branch 2 B4/02/28 PARRIS, H O Tennessee Valley Authority 46pp 22662 040 24x Fiche 50-259, 84/02/28, 8403150323
- B403130007 Forwards response to Generic Ltr B3-36 to NUREG-0737 Tech Bpecs MILLSL.M. Tennessee Vailey Authority B4/03/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 3PP 22613 349 24X Fiche 50-259,84/03/07,8403130007
- 8403130028 Informs that add1 info requested on 831012 re reactor protection sys power monitoring sys design mods will be submitted by 840702 MILLS,L M Tennestee Valley Authority, 84/03/07 DENTON,H R Office of Nuclear Reactor Regulation, Director ip 22614 362 24x Fiche 50-259,84/03/07,8403130025,
- B40B160247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rev 7 to topical GA program per 640302 telcon

 LEWISIR C Region 2. Office of Director 84/03/08 PARRIS, H G Tennessee Valley Authority ip 22660 361. 24X

 Fiche. 50-000, 84/03/08. 8403160247
- B403160373 Notifies of use of ABME Nuclear Components Code Case N32-4 for hydrostatic testing of Class 3 embedded piping NRC position re use of Code Case N32-4 requested MILLB.L. M Tennessee Valley Authority B4/03/12, DENTON, H R, Office of Nuclear Reactor Regulation, Director. ip 22660.014 24% Fiche: 50-000.84/03/12,8403160373
- 8403130275 Generic Ltr 84-07 to all licensess of BWRs re procedural guidance for pipe replacement at BWRs. Bvc list encl EISENHUT, D. O Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823, 354. 24% Fiche: 50-000.84/03/14.8403150275
- 8403200170 Forwards response to Item 4 5 of Generic Ltr 83-28,

 "Required Actions Based on Generic Implications of Balem
 ATHS Events" re reactor trip sys reliability Control rod
 tests check rod insertion times & hydravlic screm valves

 MILLS.L M Tennesse Valley Authority 84/03/15 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 10pp 22700 024
 24X Fiche. 50-259, 84/03/15, 8403200170

- 8403240229 Forwards add1 info me test configuration & results of verification testing, per 840106 request re adequacy of station electric distribution sys voltages Test results indicated no unexpected voltage levels
 MILLS.L M Tennessee Valley Authority 84/03/19 DENTON, H R
 Office of Nuclear Reactor Regulation. Director 26pp 22796 124
 24X Fiche 50-259.84/03/19.8403260229
- O Inspection reports, 1E Bulletins & Correspondence
- 8403070054 Responds to NRC ltr re violations noted in 1E Insp Repts 50-259/83-09, 50-260/83-09 & 50-294/83-09 List of identified deficiencies & implementation schedule provided to senior NRC inspector on 830901 MILLS.L M Tennessee Valley Authority 83/09/15 0'REILLY, J P Region 2. Office of Director ip 22547 261 24X Fiche 50-259, 83/09/15, 8403070054
- 8403070237 Updates 830715 response to NRC 830614 ltr re violations noted in 1E lnsp Repts 50-239/83-19.50-240/83-19 & 50-274/83-19 Operating instructions revised & Units 2 & 3 PBC charging sys operational MILLS.L M Tennessee Valley Authority 83/09/30 0'REILLY, J P Region 2. Office of Director. 1p 22541 361 24X Fiche 50-259,83/09/30,8403070237
- 8403070271 Supple 830830 response to NRC ltr re violations noted in IE Insp Repts 50-259/83-23,50-260/83-23 & 50-296/83-23 Boral test specimen installation will be delayed until 831028 due to late receipt of matls per 831012 telcon KAMMER. D 8 Tennessee Valley Authority 83/10/21 O'REILLY, J P Region 2, Office of Director in 22546 336 24x Fiche 50-259,83/10/21,840307027i
- 8403070023 Responds to NRC itr re violations noted in IE Insp Repts 50~259/83-27.50~260/83-27 & 50~296/83-27 Corrective actions compliance w/instructions will be achieved & corrective actions will be completed before Cycle & operation MILLS.L M Tennesse Valley Authority 83/10/27 G'REILLY, J P Region 2. Office of Director 1p 22541 262 24% Fiche 50-259,83/10/27,8403070023
- 8403070067 Forwards IR Insp Repts 50-259/83-50.50-260/83-50 & 50-276/83-50 on 830912-16 & 26-30 Unresolved item repositble high radiation doses measured by personnel dosimeters, discussed on 831028, considered closed O'REILLY, J P Region 2, Office of Director 84/01/11 PARRIS, H O Tennessee Valley Authority 2pp 22545 341 24X Fiche 50-259,84/01/11,8403070067
- --8403070072 IE Insp Repts 50-259/83-50.50-240/83-50 & 50-294/83-50 en 831028 No violations or deviations noted Major areas inspected TLD & multiple badging DEBS.B T Region 2. Office of Director 83/12/05 5pp 82545 343 24X Fiche 50-289.84/01/11.8403070047
- 8403160232 Forwards I% Insp Repts 50-259/84-04, 50-260/84-04 & 50-296/84-04 on 840123-27 No violations or deviations noted VERRELLI,D M Division of Project & Resident Programs 84/02/16 PARRES,H 0 Tennessee Valley Authority 2pp 22661 029 24% Fithe 50-259,84/02/16,8403160232
- --8403160238 IE Insp Repts 50-259/84-04, 50-260/84-04 & 50-276/84-04 on 840123-27 No violations or deviations noted Major areas inspected startup testing new fuel receipt plant tours & MBIV repair status

 DAVENPORT.K E Region 2, Office of Director JAPE.F Division of Engineering & Operational Programs 84/02/14 Spp 22661 031 24X Fiche 50-259,84/02/16,8403160232.
- 8401190072 IR Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enti JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24% Fiche 50-000.84/02/28,8401190072
- 8403140162 Ack receipt of 840222 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-57, 50-260/83-57 & 50-296/83-57 LEWIG, R C. Division of Project & Resident Programs, 84/02/29 PARRIS
- --B403160171 Responds to NRC 840123 ltr re violations noted in IE Insp Repts 50-259/83-57,50-260/83-57 & 50-296/83-57 Corrective actions policy statement issued to health physics technicians re high radiation area doors MILLS.L M Tennessee Valley Authority 84/02/22 G'REILLY, J P Region 2, Office of Director 5pp 22655 274 24X Fiche 50-259,84/02/29,8403160162

- --B403160178 Forwards IE Insp Repts 50-259/B3-57,50-260/B3-57 & 50-296/B3-57 on B31126-1225 & notice of violation LEHIS:R C Division of Project & Resident Programs B4/01/23 PARRIS:H G Tennessee Valley Authority 2pp 22655 279 24X Fichs 50-259,84/02/29,8403160162
- --8403160181 Notice of Vialation from insp on 831126-1225 * Region 2. Office of Director 84/01/23 2pp 22655 281 24X Fiche 50-259,84/02/29,8403160162
- --8403160186 IE Insp Repts 50-259/83-57.50-260/83-57 & 30-296/83-57 on B31126-1225 Violations noted failure to lock high radiation area, to follow special work permit & to have adequate fire protection maint procedure PAULK, G L Region 2. Office of Director CANTRELL, F 8 Division of Project & Resident Programs 84/01/21 6pp 22655 283 24X Fiche 50-259,84/02/29,8403160162
- 8403160218 Ack receipt of 840209 itr informing NRC of steps taten to correct violations noted in IE Insp Repts 50-259/83-40, 50-260/83-40 & 50-296/83-40 EBHSR C Division of Project & Resident Programs 84/03/01 PARRIS.H G Tennessee Valley Authority ip 22661 078 24X Fichs: 50-259.84/03/01,8403160218
- --8403160223 Responds to NRC 840111 ltr re violations noted in iE insp Repts 30-259/83-40,50-260/83-40 & 50-276/83-40 Corrective actions radiological emergency planning program reviewed & ereas requiring rev identified HILLS.L M Tennessee Valley Authority 84/02/09 O'REILLY, J P Region 2, Office of Director. App. 22661 099 24X Fiche 50-259,84/03/01,8403160218
- --8403160237 Notice of violation from insp on 831017-21 & ii22 * Region 2. Office of Director 84/01/ii 3pp 22661 107 24X Ficha 50-257,84/03/01,8403160218
- --8403160244 iE Insp Repts 50-257/83-40.50-260/83-40 & 50-296/83-40 on 831017-21 & 1122 Noncompliancs noted failure to control documents property train emergency personnel in protective action requirements & incorporate protective action DECKER.TR. STODDART.P.G. Region 2. Office of Director JENKINS.G.R. Division of Emergency Preparadness & Materiais Safety 84/01/06 9pp 22661 110 24X Fiche 50-239,84/03/01.8403160218
- 8402090007 IE Info Notice 84-(4, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE. J N Division of OA, Bafeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24% Fiche 50-000,84/03/02,8402090007
- 8402090008 iE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list enci JURDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22353 098 24X Fiche 30-000.84/03/02.8402090008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Rsisases." Byc 11st encl JURDAN, E L. Division of Emergency Preparedness & Enginesring Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 117pp 22353 217 24X Fiche 50-000,84/03/02,8402070009
- 8403080213 EN-84-007 on 840307, notice of violation & proposed imposition of civil penalties in amount of \$40,000 to be issued Action based on failure to control access into vital area due to guard leaving post ROSANO.R . AXELRAD, J Director's Office. Office of Inspection and Enforcement 84/03/02 ip 22560 021 24X Fiche 50-257,84/03/02,8403800213
- B4020700il IE Info Notice B4-17, "Problems W/Liquid Nitrogen Cooling Components Below Mil Ductility Temp " Svc list encl JURDAN, EL Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24% Fich. 50-000,84/03/05,8402070011
- 8403i60308 Ack receipt of 8402i7 1tr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-239/83-56 LEWIS, R C Division of Project & Resident Programs 84/03/05 PARRIS, H G Tennessee Valley Authority 1p 22660 085 24X Fiche: 50-259, 84/03/05, 8403160308

- --8403160318 Responds to NRC 840117 Itr re violations noted in IE Insp flepts 50-259/83-56.30-260/83-36 & 50-296/83-56 Corrective actions 10% retest sample calculation made for all snubbers within Category/Group 3 MILLS.L M Tennessee Valley Authority 84/02/17 D'REILLY, J P Region 2, Office of Director 2pp 22660 084 24% Fiche 30-259,84/03/05.8403160308
- --8403160328 Forwards IE Insp Repts 50-259/83-56, 50-260/83-56 & 50-296/83-56 on B31213-16 & notice of violation LEWIG.R C Division of Project & Resident Programs 84/01/17 PARRIG.H G Tennessee Vailey Authority 2pp 22660 088 24X Ficha 50-259,84/03/05.8403160308
- --8403160339 IE Insp Repts 30-259/83-56, 50-260/83-56 & 50-276/83-56 on B31213-16 Violation noted failure to test add1 10% sample for each snubber that failed functional test HHITENER.H L. Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 84/01/10 8pp 22660 091 24% Ficha 50-239,84/03/05,8403160308
- 8403290237 Forwards IE lnsp Repts 50-259/84-05.50-260/84-05 & 50-275/94-05 on 840130-0201 No violations or deviations identified.

 VERRELLID.M Division of Project & Resident Programs. 84/03/05 PARRIB.H 0 Tennessee Valley Authority 2pp 22800 227 24X Fiche 50-259.84/03/05.8403290237
- --8403270237 IE Insp Repts 50-259/84-05, 50-260/84-05 & 50-276/84-05 on 840130-020i No violations or deviations identified Major areas inspected following of IE Bullatin 81-03 revising of LERs re builetin & procedures for flow reverification tasts CUNNINOHAN,A L Region 2, Office of Director. MONTODMERY,D M Division of Engineering & Operational Programs 84/03/02 5pp 22800 23i 24X Fiche 50-259,84/03/05,8403270237
- 8402090024 iE info Notice 84-09. Rev i: "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc i18pp 22635 049. 24X Fiche. 50-000.84/03/07. 8402090024
- 8402090028 IE Info Notice 84-i8, "Stress Corrosion Cracking in PWR 8ys " Svc list enci JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of Naw York, Inc. i18pp 22584,i86 24X Fiche 50-000,84/03/07,8402090028
- B403160273 Forwards iE Enforcement Conference Rapts 50-259/84-06, 50-260/84-06 & 50-276/84-06 on 840224 UREILLY.U.P Region 2. Office of Director 84/03/08 PARRIS.H 9 Tannessee Valley Authority. 2pp 22661 004 24X Fichs 50-259.84/03/08.8403160273
- --8403i60282 IE Enforcement Conference Repts 50-259/84-06, 50-260/84-06 & 50-296/84-06 on 840824 Major itsms discussed bypassing rod sequence control sys while shutting down k isolation of drywell to pool pressure instrument BUTCHER.R C Region 2, Office of Director CANTRELL.F 8 Division of Project & Resident Programs 84/02/29 App 22661 006 24X Fiche:50-259,84/03/08,8403160273
- 8402070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823, 094 24% Ficher 50-000, 84/03/12, 8402090031
- 8403190136 Ack receipt of 840221 & 0312 ltrs informing NRC of steps taken to correct violations noted in iE insp Repts 50-239/83-59,50-260/83-59 & 50-276/83-59 Responses meet 10CFR2 201 requirements

 LEMIS R C Division of Project & Resident Programs 84/03/14 PARRISH 0 Tennessee Vailey Authority 1p 22670 314 24X Fiche 50-259,84/03/14,8403190136.
- --8403190147 Supple response to NRC 840120 itr re violations noted in IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 Responses withheld (ref 100FR73 21), MILLS, L M Tennessee Valley Authority 84/03/12 0'REILLY, J P. Region 2. Office of Director ip 22670 315 24% Fiche 50-259,84/03/14,8403190136
- --8403190161 Responds to NRC 840120 itr re violations noted in IE Insp Repts 50-259/83-59, 30-260/83-59 & 30-296/83-59 Responses withheld (ref 10CFR73 21) MILLS,L M Tennessee Valley Authority 84/02/21 O'REILLY, J P Region 2, Defice of Director 19, 22670 316 24X Fiche 30-259,84/03/14,8403190136

- --8403190172 Forwards IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 on 831216 & notice of violation Notice of violation withheld (ref 100FR2 790 & 73 21)

 LEMIB.R C Division of Project & Resident Programs 84/01/20 PARRIS,N O Tennesses Valley Authority 2pp 22670 317 24% Fiche 50-259,84/03/14,8403190136
- --8403190188 IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 on B31216 Noncompliance noted security force member failed to control access to area Details withheld (ref 100FR73 21 & 2 790)
 TILLMAN, A. PATYERSON, C. Region 2, Office of Director MCQUIRE, D.R. Division of Emergency Preparedness & Materials Bafety 84/01/19 1p 22670 319 24% Fiche 50-259, 84/03/14, 8403190136
- 8403290047 Summarizes 840312 meeting in Region II ofc re planned util organizational changes & regulatory performance improvement program for facility UREILLY.JP Region 2. Office of Director 84/03/15 PARRIS.H G Tennessee Vailey Authority 1p 22806.271 24X Fiche 50-209.84/03/15.8403290047
- 8403290178 Ack receipt of 840217 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-239/83-38. 50-240/83-38 & 50-296/83-38
 LEWIS.R C Division of Project & Resident Programs 84/03/20
 PARRIB.H Q Tennessee Vailey Authority ip 22800 278 24X
 Fiche' 50-259,84/03/20.8403290178
- --B4D3290183 Suppls response to NRC B40119 ltr re violations notad in IE Insp Repts 50-259/B3-3B.50-260/B3-3B & 50-296/B3-3B Corrective actions distribution of insp rept to health physics personnel initiated MILLB.L M Tennessee Valley Authority B4/02/17 O'REILLY, J P Region 2, Office of Director 2pp 22800 279 24X Fiche 50-259.84/03/20.8403290178
- ---8403270170 Ack receipt of 831207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-257/83-38, 50-250/83-38 & 50-256/83-38 B O'REILLY, J P Region 2, Office of Director 84/01/17 PARRIS, H O, Tennessee Valiey Authority 2pp 22800 281 24X Fisha 50-259, 84/03/20, 8403270178
- --8403290203 Ack receipt of 83:209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-38, 50-276/83-38 LEWIB.R C Division of Project & Resident Programs 83/i2/2i PARRIB.H O Tennesses Vaiiey Authority ip 22800 283 24X Fiche.50-259,84/03/20,8403290178
- ---B403270207 Responds to NRC B31107 ltr re violations noted in IE Insp Repts 50-259/83-38,50-260/83-38 & 50-296/83-38 Corrective actions insp rept distributed to health physics personnel & RCI-5 revised to incorporate iOCFR49 changes MILLS.L M Tennessee Valley Authority B3/12/09 O'REILLY, J P Region 2, Office of Director 5pp 22800 284 24X Fiche. 50-259, 84/03/20, 8403270178
- --840329D2ii Forwards IE Insp Repts 50-259/83-38,50-260/83-38 & 50-276/83-38 on 8309i2-i6 & notice of violation LEMIS.R C Division of Project & Resident Programs 83/i1/09 PARTS.H Q Tennessee Vailey Authority 2pp 22800.289 24% Fiche 50-259,84/03/20,8403290i78
- ---8403270214 Notice of violation from insp on 830712-16 * Region 2, Office of Director 83/11/09 2pp 22800 291 24) Fiche. 30-257, 84/03/20, 8403270178
- --8403290220 IE Insp Repts 50-259/83-38,50-260/83-38 & 50-296/83-38 on 830912-16 Violations noted 55-gallon drum reading 30 to 65 millirem per hour observed unlabeled & radiation control procedures not prepared or adhered to DEBS,B T, Region 2, Office of Director BARR.K P Division of Engineering & Operational Programs 83/11/03 6pp. 22800 273 24X Fiche 50-259,84/03/20,8403290178
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, El. Division of Emergency Preperedness & Engineering Response (Post 830103) 84/03/21 Consolidate Edizon Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21.8402090043
- B402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000, B4/03/21, 8402090044

- R Periodic operating reports & related correspondence
- 8403020103 Monthly operating repts for Jan 1984 H/B40210 ltr CHAPMAN.M., THOM.T., JONES.O.Y. Tennessee Valley Authority 84/01/31 41pp 22443 166 24X Fiche 50-259.84/01/31.8403020103
- 8403300133 Forwards monthly operating repts for Feb 1984 & corrected Jan 1984 monthly operating rept for Unit i JUNES.G T Tennessee Valley Authority 84/03/09 Office of Resource Management, Director ip 22820 203 24X Fiche 50-259.84/03/09.8403300133
- --8403300136 Monthly operating repts for Feb 1984 THDM,T Tennessee Valley Authority 84/02/29 37pp 22820 204 24% Fiche 50-259,84/03/09,8403300133
- B Reportable occurrences, LERs & related correspondence
- 8403260233 Forwards summary list of deficiencies identified per iOCFRSD 55(e).Part 21 & potential generic itr repts for comments STARGSTECKI.R Division of Project & Resident Programs 64/02/28 Region 1. Office of Director 7pp 22756 065 24X Fiche 50-000.84/02/28.8403260233
- B403i30lBi LER B4-003-00 on B402i2, routine survailiance testing stopped because operator unable to bring HPCI turbine speed down to required 2,400 rpm Caused by erratic ramp generator/signal converter box adjustment W/840306 ltr SMITH.D L . JONES.G T Tennesses Valley Authority B4/03/06 3pp 226i7 324 24X Fiche 50-260,84/03/06,840313018i
- 840320017i Foilowup LER 82-028/03X-3 on 81092i, turbine reactor bldg
 Doors 237 & 238 opened simultaneously, breaching secondary
 containment Caused by failed Folger Adams interlock sys due
 to loose door latch screws Procedures revised W/840309 ltr
 CARTER, 8. JONES, 0 T Tennesse Vailey Authority 84/03/09
 O'REILLY, J P Region 2, Office of Director 3pp 22699 353 24X
 Fiche 50-260,84/03/09,840320017i
- 8403220159 LER 64-004-00 on 840222 during startup reactor scrammed Caused by high flux spike on channels C & F of intermediate range monitors Plant written procedures & nuclear engineer qualification program revised W/840315 ltr MORKIN, M . JONES O T Tennessee Valley Authority 84/03/15 Jpg 22715 331 24X Fiche 50-260,84/03/15,8403220159
- V Operator Examinations
- 8403i60227 Confirms 840302 meeting in Atianta, OA re 8403i9 operator requalification exam.per 840229 teicon
 LEWIB.R C Division of Project & Resident Programs 84/03/0i
 PARRIS.H O Tennessee Valley Authority Ip 22660 328 24X
 Fiche 30-259.84/03/0i,8403i60827
- B403290322 Discusses B40Ji7 ltr confirming arrangements for administration of requalification exams. Random selection process used to determine identify of examinees for written & oral exams list of examinees encl
 LEWIG.R C Division of Project & Resident Programs B4/03/i3 PARRIS, H O Tennessee Valley Authority 3pp 22802 047 24X Fiche 50-259.84/03/i3,8403270322
- 8403270213 Summarizes 840302 meeting w/util re 840323 requalification exam of licensed operator & senior operator personnel at facilities Meeting provided better understanding of operator requalification training & exam programs

 LEWIS.R C Division of Project & Resident Programs 84/03/15

 PARRIS.H G Tennessee Valley Authority 3pp 22800,360 24X

 Fiche: 50-259,84/03/15,8403270213
- DOCKET 30-261 H B ROBINSON PLANT, UNIT 2
- F. Becurity, medical, emergency & fire protection plans
- 8403160385 IE Insp Rept 50-241/84-02 on 840111-0210 No violations or deviations identified Major areas inspected Tech Spec compliance, plant tour, operations performance, ROs. housekeeping, site security, surveillance & maint activities WEISE.S. MYERG.D Region 2. Office of Director BEMIS.P R Division of Project & Resident Programs 84/02/16 12pp 22660.002 24X Fiche 50-261,84/02/17,8403160382
- 8403160382 Forwards IE Insp Rept 50-261/84-02 on 840111-0210 No violations or deviations identified VERRELLI,D M Division of Project & Resident Programs 84/02/17 UTLEY,E E Carolina Power & Light Co 1p 22660 001 24X Fichs 50-261,84/02/17,8403160382

- 8403050508 Forwards order confirming util commitments to implement requirements of Suppl 1 to NUREC-0737 Order based on commitments contained in util 840415 & 830824 responses to 821217 Generic Ltr 82-33 VARGA-S A Operating Rosctors Branch 1 84/02/21 UTLEY-E Carolina Power & Light Co 3pp 22552 165 24X Fiche \$0-261.84/02/21.8403040508
- 8403160249 Ack receipt of 840217 itr informing NRC of steps taken to correct violations noted in IE Insg Rept 50-261/83-35 Implementation of corrective actions will be examined during future insps
 LEWIS.R C Division of Project & Resident Programs 84/02/29 UTLEY.E E Carolina Fower & Light Co 1p 22660 299 24X Fiche 50-261.84/02/29.8403160249
- --B403160262 Responds to NRC 840118 ltr re violations noted in 1E insp Rept 50-261/B3-35 Corrective actions Emergency Procedure PEP-105 will be revised to implement recommendations of IE Info Natice 83-28 & NUREG-0654 HORGAN.R E Carolina Power & Light Co 84/02/17 G'REILLY, J P Region 2. Office of Director 3pp 22660 300 24x Fiche 50-261,84/02/29,8403160249
- --B403160300 IE Insp Rept 50-261/B3-35 on B31205-09 Violation noted IE Info Notice 83-28 guidance not incorporated into Emergency Procedure PEP-105, "Emergency Control General Emergency " STODDART.P g Ragion 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Bafety 84/01/11 7pp. 22660 305 24X Fiche 50-261.84/02/29,8403160249
- 8403200245 Revised energency implementing procedures, including Rev 1 to Procedure PEP-503, "Administration of Radioprotective Drugt" & Rev 1 to Procedure PEP-653. "Performance of Training. Exercises & Drills " WAR40316 ltr MORGAN.R E Carolina Power & Light Co 84/02/27 C'REILLY, J P Region 2. Office of Director 15pp 22691 120 24X Fiche 50-261.84/02/29.8403200245
- 8403160283 Advises of 840316 meeting in Region II ofc to discuss App R requirements & results of recent App R insps Attendance should be limited to six util employees LEMIS.R C Division of Project & Resident Programs 84/03/02 UTLEY,E E Carolina Power & Light Co ip 22660 109 24X Fithe 50-000.84/03/02.8403160283
- 8403070074 Suppls 831025 request for exemption from requirements of 10CFR73 35 for portion of steam generator repair program Encl withheld (ref 10CFR73 21)

 UTLEY.E E Carolina Power & Light Co 84/03/05 VARGA.8 A Operating Reactors Branch | 2pp 22571 | 14 24x Fiche 30-261.84/03/05,8403090074
- 1403230127 Revs 0 & 4 to Emergency Plan Implementing Procedure PEP-105 "Emergency Control - General Emergency " W/B40320 ltr MORGAN R E Carolina Power & Light Co 84/03/20 O'REILLY, J P Region 2. Office of Director 14pp 22730 193 24X Fiche 50-261.84/03/20.8403230127
- P Operating license stage documents & correspondence
- 8403060470 Discusses negotiations w/licensee on NUREQ-0797 Items reservency operating procedures.per 830601 % 0712 memos REQUA. 0 Operating Reactors Brench i 83/09709 EISCNHUT, D 0 Division of Licensing ip 22949 326 24% Fiche 50-261,83/09/09,8403060470
- 8403010230 Notification of 840228 meeting w/util in Bethesda.MD to discuss multi-plant actions.TMI action items & specific open items REQUA.O Operating Reactors Branch 1 84/02/21 VARGA.B A Operating Reactors Branch 1 2pp 22479 195 24X Fiche 30-261.84/02/21.8403010200
- 8403050005 Forwards Amend 77 to License DPR-23, ABLB order dismissing proceeding & notice of issuance Amend approves Steam generator repair program & provides licensing conditions re repair operation W/o ABLB order REQUA, 0 Operating Reactors Brench i 84/02/28 UTLEY, E Carolina Power & Light Co 3pp 22528 354, 24X Fiche 50-261.84/02/28,8403060005
- --8403050009 Amend 77 to License DPR-23 approving steam generator repair program & providing licensing conditions re repair operation ETSENHUT. D 0 Division of Licensing 84/02/28 3pp 22528 357 24X Fiche 50-251,84/02/28

- --8403060012 Notice of issuance & availability of Amend 77 to License DPR-23 VAROA:S A Operating Reactors Branch 1 84/02/28 3pp 22528 360 24% Fiche 50-261.84/02/28.8403060005
- 8403050217 Forwards request for add1 info re TMI Item II D 3 4, "Control Room Habitability " Response requested within 45 days of receipt of itr VARGA.8 A Operating Reactors Branch 1 84/02/27 UTLEY.E E Carolina Power & Light to 4pp 22528 137 24X Fichs 50-261.84/02/29.8403050217
- 8403130093 Forwards util resolution of generic environ qualification of safety-related electrical equipment deficiencies discussed in 830105 8ER CUTIER, A B Carolina Power & Light Co 84/03/02 VARQA, 8 A Operating Reactors Branch i 46pp 22614 215 24X Fiche \$0-261.84/03/02,8403130093
- B403130161 Application to amend License DPR-23, requesting blanket approval to transfer slightly contaminated sediment from settling ponds to facility ash ponds using either hydrovacuum truck or direct piping/sluicing method UTLEY.E E Carolina Power & Light Co 84/03/09, VAROA.8 A Operating Reactors Branch i 3pp. 22640 039 24X Fiche 50-261.84/03/09.8403150161
- --8403i50163 "Transfer of Slightly Contaminated Bediment to Ash Pond via Ash Bluice Sys." SAR * Carolina Power & Light Co 83/01/19 27pp 22640 062 24X Fichs 50-261,84/03/07,8403150161
- 8403210093 Provides addl info re adequacy of electrical distribution voltage system 840119 request Criteria used in selecting undervoltage & overvoltage alarm setpoints for 110-kV grid voltage discussed.

 CUTTER, A D Carolina Power & Light Co. 84/03/09 VARQA, 8 A Operating Reactors Branch i 18pp 22705 339 24X

 Fiche 50-261.84/03/09.8403210093
- 8403210116 Forwards additinfo re power distributions as part of pressurized thermal shock program to effect flux reduction, per 830930 submittal, in response to 840301 telton ZIMMERMAN, BR Carolina Power & Light Co 84/03/12 VARQA, 8 A Operating Reactors Branch 1 3pp 22705 064 24X Fichs 50-261,84/03/12,8403210116
- B403300225 Requests remittance of Class V fee for 820701 application for steam generator repair program EI8 prepared to assess major environ impact of occupational radiation exposures associated w/groposed repair of steam generator MILLER, W O License Fee Management Branch B4/03/14 JUNES, J. A Carolina Power & Light Co 2pp 22845 Q37 24X Fiche 50-261,84/03/14,8403300225.
- 8403270235 Application for amend to License DPR-23 revising Tech Specs re immediate notification requirements for LER sys CUTTER, A B Carolina Power & Light Co 84/03/21 VARQA, S A Dearsting Reactors Branch 1 2pp 22772, 033 24X Fiche 50-261,84/03/21,8403270235
- --8403270239 Proposed Tech Specs re immediate notification requirements of LER sys & Caroline Power & Light Co 84/03/21 30pp 22772 035 24X Fichs 50-261,84/03/21,8403270235
- A Inspection reports, IE Bulletins & correspondence
- B402140189 Forwards IE Insp Rept 50-261/83-37 on 831215-16 No violations or deviations noted VERRELLI,D M Division of Project & Resident Programs 84/01/10 UTLEY,E E Carolina Power & Light Co 2pp 22228 355. 24X Fiche: 50-261/84/01/10/8402140189
- --B402140193 IE Insp Rept 50-261/83-37 on 831215-16 No violations or deviations noted Major areas inspected RCS leak rate measurement
 BURNETT: P T Region 2, Office of Director JAPE: F Division of Engineering & Operational Programs. 84/01/10 5pp. 22228:357
 24X Fiche: 50-261: 84/01/10, 8402140189
- 8403160382 Forwards IE Insp Rept 50-261/84-02 on 840111-0210. No violations or deviations identified.
 VERRELLI, D. M. Division of Project & Resident Programs 84/02/17 UTLEY, E. E. Garglina Power & Light Co. 1p. 22660-001. 24X Fiche. 50-261/84/02/17/8403160382

- --8403160385 IE Insp Rept 50-261/84-02 on 840111-D210 No violations or deviations identified Major areas inspected Tech Spec compliance, plant tour, operations performance, ROs, housekeeping, eite security, surveillance & maint activities HEISE, 8 . MYERS, D. Region 2. Office of Director BEMIS, P. R. Division of Project & Resident Programs 84/02/16 12pp 22660 002 24X Fiche 50-261,84/02/17,8403160382
- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering

enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401170072

- 8403160249 Ack receipt of 840217 ltr informing NRC of steps taken to correct violations noted in iE lnsp Rept 50-261/83-35 Implementation of corrective actions will be examined during future ineps
 LEMIS,R C. Divieion of Project & Resident Programs 84/02/27 UTLEY,E E Carolina Power & Light Co ip 22660 299 24% Fiche 50-261,84/02/29,8403160247
- --8403160262 Reeponds to NRC 840118 itr re violations nated in IE lnsp Rept 50-261/83-35 Corrective actions Emergency Procedure PEP-103 will be revised to implement recommendations of IE Info Notice 83-28 & NNREO-0654 MOROAN.R E Carolina Power & Light Co 84/02/17 D'REILLY, J P Repion 2. Office of Director 3pp 22660 300 24x Fiche 50-261.84/02/29.8403160249
- --B403160275 Forwards lE lnsp Rept 50-261/83-35 on 831205-07 & notice of violation W/o notice of violation LEWIB:R C Division of Project & Resident Programs 84/01/18 UTLEY:E E Carolina Power & Light Co 2pp 22660 303 24x Fiche 50-261:84/02/29,8403160249
- --8403160300 IE Insp Rept 50-261/83-35 on 831205-09 Violation noted IE Info Notice 83-28 guidance not incorporated into Emergency Procedure PEP-105, "Emergency Control Qeneral Emergency " STODDART, P Q Region 2, Office of Director JENKINS, Q R Division of Emergency Preparedness & Materials Safety 84/01/11 7pp 22660 305 24% Fiche 50-261,84/02/29,8403160249
- B402090007 IE lnfo Notice 84-14, "Highlights of Recent Transport Regulatory Reve by DOT & NRC " Svc list encl GRACE, J N Division of GA, Bareguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552,327 24X Fiche 50-000.84/03/02.8402090007
- 8402090008 IE lnfo Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Responee (Poet 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- B402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Byc liet encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fichs 50-000, B4/03/02, B402090009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Camponents Below Nil Ductility Temp " Evc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Poet 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- B402090024 lE lnfo Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sye " Syc iist encl JORDAN, E L Division of Emergency Preparedness & Engineering Reeponee (Ppet 830103) B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 lE lnfo Notice 84-18, "Streee Corrosion Cracking in PWR Sys." Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584:186 24X Fichs 50-000,84/03/07,8402090028
- 8403160267 Forwards IE Enforcement Conference Repts 50-261/84-08 & 50-400/84-08 on 840223 O'REILLY, J.P. Region 2, Office of Director 84/03/09 UTLEY, E.E. Carolina Power & Light Co. 2pp. 22660 275 24X Fichs 50-000, 84/03/09, 8403160267
- --B403160274 IE Enforcement Conference Repts 50-261/84-08 & 50-400/84-08 on 840223 Major areas discussed unauthorized entry into facility reactor cavity & GA programs re procurement of svcs & matls
 VERRELLI, D. M. Division of Project & Resident Programs 3pp 22660:277 24X Fiche 50-000,84/03/09,8403160267

- 8402090031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list enci DEYOUNG,R C Director's Office. Office of inspection and Enforcement 84/03/12 Consolidated Edison Co of New York. Inc 134pp 22823 094 24x Fiche 50-000.84/03/12.8402090031
- B403300324 Discusses iE insp on B40221 & forwards notice of violation & proposed imposition of civil penalty O'REILLY, J P Region 2, Office of Director 84/03/13 UTLEY, E Carolina Power & Light Co 2pp 22842 312 24X Fiche 50-261.84/03/13.8403300324
- --8403300327 Notice of violation & proposed imposition of civil penalty in amount of \$30.000 Violation noted health physics technician failed to perform adequate surveys for licensed operator when entry made into reactor keyway sump 0'REILLY, JP Region 2, Office of Director 84/03/13 4pp 22842 315 24X Fiche 50~261,84/03/13,8403300324
- 8402090043 IE info Notice 84-i9, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JURDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York. Inc 123pp 22823 229 24X Fiche 50-000.84/03/21.8402090043
- 8402070044 IE info Notice 84-20: "Svc Life of Relays in Bafety-Related Sys " Svc list enci JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York Inc 135pp 22733 001 24X Fiche 50-000.84/03/21.8402070044
- R Periodic operating reports & related correspondence
- 8403080135 Monthly operating rept for Jan 1984 W/B40302 ltr SCOTT.A E : NORRIS:H R : MORGAN:R E Carolina Power & Light Co 84/01/31 DEYQUNG:R C Director's Office. Office of Inspection and Enforcement 4pp 22559 279 24X Fiche 50-261;84/01/31.8403080135
- 8403080258 Monthly operating rept for Feb 1984 W/840302 ltr NCRRIS.H R. SCOTT.A E. MCROAN.R E. Carolina Power & Light Co 84/02/27 DEYOUNG.R C. Director's Office. Office of Inspection and Enforcement 4pp 22557 ii7 24X Fiche 50-261.84/02/29.8403080258
- 8 Reportable occurrences, LERs & related correspondence
- 8403150098 Special rept on 840131, six hose stations, seven non-Tech Spechose stations & two hydrents inoperable due to isolation of water loop for bidg const Addi support for rerouted fire water piping provided MORGAN.R E Carolina Power & Light Co 84/03/06 O'REILLY, J P Region 2, Office of Director ip 22640 362 24X Fiche 50-261,84/03/06,8403150098
- 8403130445 EN-84-009 on 840312, notice of violation & proposed imposition of civil penalty in amount of \$30,000 will be issued based on failure of Tech Specs procedures re entry into locked high radiation area FLACK, E. AXELRAD. J Director's Office, Office of inspection and Enforcement 84/03/07 2pp 22613 138 24X Fiche 50-261,84/03/07.8403130449
- DOCKET 50-262 BRIGHAM YOUNG UNIV RESEARCH REACTOR

 O Inspection reports, 1E Bulletins & correspondence
- 8401190072 IE info Notice 8A-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list BRCI JORDAN, E L Division of Emorgency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239 24X Fiche 50-000.84/02/28.8401190072
- B402090007 IE info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA, Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 30-000,84/03/02,8402090007
- B40209000B 1E Info Notice B4-16, "Failure of Automatic Sprinkler Sys Vaives to Operats " Svc liet encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 09B 24X Fiche 50-000,84/03/02,8402090008
- 8402070007 IE Info Notice 84-i5, "Reporting of Radiological Releases"
 Svc list encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc ii7pp 22553 217 24X Fiche 50-000,84/03/02,8402070007

- 8402090011 IE Info Natice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nii Ductility Temp " Svc list enc! JORBAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24% Fiche 50-000.84/03/05.8402090011
- 8402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Fische 50-000, 84/03/07, 8402090024
- 8402090028 IE info Notice 84-iB. "Stress Corrosion Cracking in FWR Sys " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolldated Edison Co. of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 6402090031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE 8afety Sys " Svc list encl DEYOUNG: R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Go of New York
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24% Fiche 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84-20, "Evo Life of Relays in Safety-Related 8ys " Svo list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044

DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

- F Security, medical, emergency & fire protection plans
- 8403060041 Advises that NRC will not review emergency plans to delete privacy or proprietory info unless specifically requested by licensee, per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR VASSALLO. D B Operating Reactors Branch 2 84/02/10 MUSOLF. D M Northern States Power Co 2pp 22528 325 24X Fiche 50-263.84/02/10.8403060041
- 8403060283 Rev 5 to Emergency Plan Implementing Procedure A 2-106, "Activation of Technical Support Ctr" W/840301 ltr & list of current pages BRURG,R L , SCHEINERT,R L , FEY,F L Northern States Power Co 84/02/28 8pp 22519 207 24% Fiche 50-263,84/02/28,8403060265
- 8403060185 Ack receipt of 840207 ltr transmitting Rev 14 to security plan Rev consistent w/provisions of 10CFR50 54(p) & acceptable AXELSON.W L Region 3, Office of Director 84/03/01 MUSOLF.D M Northern States Power Co 2pp 28518 359 24X Fiche 50-263.84/03/01.8403060185
- 8403080238 Forwards "Monticello Nuclear Power Plant Site-Specific Offsite Radiological Emergency Preparedness Evaluation" & "Monticello Nuclear Power Plant Full-Scale Joint Emergency Eiercise on 830223, " final rept KRIMI, R W Federal Emergency Management Agency 84/03/05 Faderal Emergency Management Agency 3pp 22560 127 24X Fiche 50-263,84/03/05,8403080238
- --8403080242 "Monticello Nuclear Power Plant Site-Specific Officite Radiological Emergency Preparedness, State of MN & Sherburne & Wright Counties, " regional directors evaluation » Federal Emergency Nanagement Agency 84/01/26 32pp 22540 130 24X Fiche 50-263,84/03/05,8403080238
- ~-8403080244 "Monticello Nuclear Power Plant Full-Scale Joint Emergency Exercise on 830223," final rept * Federal Emergency Management Agency 84/03/05 110pp 22560 255 24% Fiche 30-263,84/03/05,8403080238
- 8403130198 Forwards evaluation of State of MN & Shelburne & Wright Counties emergency preparedness plan for 830283 full-scale exercise identified deficiencies corrected KRIMMR W Federal Emergency Hanagement Agency 84/03/05 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 7pp 22613 256 24X Fiche 50-263.84/03/05,8403103198

- --8403130207 Evaluation of State of MN & Shelburne & Wright Counties emergency preparedness plan for 830223 full-scale exercise # Federal Emergency Management Agency 84/03/05 63pp 22613 263 24X Fiche 50-263,84/03/05,8403130178
- 8403120060 Extends invitation to attend regional workshop on fire protection safe shutdown requirements of 10CFR50.App R & IE Info Notice 84-09 on 840323 in Rosemont, IL Proposed agonda suci for review SPESSARD.R L. Division of Engineering 84/03/06 LARSON.C E Northern States Power Co 3pp 22570 286 24X Fiche 30-263.89/03/06.8403120060

I Financial information

- B403270115 Suppl to Annual Financial Rept 1983, consisting of financial & statistical info W/840326 ltr BRUSVEN.A D Northern States Power Co 83/12/31 23pp 22806 182 24X Fiche 80-000.83/12/31,8403270115
- P Operating license stage documents & correspondence
- B403140340 Summary of B31215 meeting w/GE & Mark I Dwners Group in Betheeda. MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL, B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 178 24X Fiche 50-000, 84/02/21, 8403140340
- B403140185 Forwards SER on NUREG-0737, Item II D 1 rs performance testing of BMR relief & safety valves Item satisfactorlly resolved VASSALLO, D B Operating Reactors Branch 2 84/02/24 MUSOLF, D M Northern States Power Co 17pp 22638 004 24X Fiche 50-263.84/02/24,8403140185
- B403130079 Forwards "Effluent & Waste Disposal Semiannual Rept.Jul-Dec 1983," "Offsite Radiation Dose Assessment,1983" & Rev 4 to "Offsite Dose Calculation Manual " FEY.F.L. Northern States Power Co. 84/03/01 Region 3, Office of Director 1p 22617 327 24X Fiche 50-263,84/03/01.8403130079
- --8403130103 Rev 4 to "Offsite Dose Calculation Manual "
 * Northern States Power Co 84/02/23 12pp 22617 347 24X Fiche 50-263,84/03/01,8403130079
- 8403150275 Generic Ltr 84~07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc list encl EISENHUT, D G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24% Fiche 50-000, 84/03/14; 8403150275
- 840330323 Notifies that Class III fee appropriate for review of 800515 application to amend License DPR-22 re definition of term operable DI088.R M License Fee Management Branch 84/03/15 MUSQLF, D W Northern States Power Co 1p 22842 319 24X Fishe 50-263, 84/03/15, 8403300323
- 8403270049 Provides info to aid NRC in review & approval of alternate shutdown sys dealgn (ABBD) Drawings showing physical location of ABBD control & relay panels & P&IDs for RHR & reactor water cleanup sys will be provided MUSDLF,D Northern States Power Co 84/03/19 Office of Nuclear Reactor Regulation, Director 2pp 22769 344, 24X Fiche 50-263,84/03/19,8403270049
- @ Inspection reports, IE Bulletins & correspondence
- 8403120141 Forwards IE Insp Rept 50-263/84-01 on 840111-0201 No noncompliance Identified 8HAFER, W ID Region 3. Office of Director 84/02/23 LARSON, C, E Northern States Power Co 23pp 22585 234 24X Fiche 50-263, 84/02/23, 8403120141
- --B403120145 IE Insp Rept 50-263/84-01 on 840111-0201 No noncompliance or deviations identified Major areas inspected operational safety, LERs, IE bulistins & circulars, preparation for refueling, onsite review committee & procedures BROWN, C H , OROBE, J A , EVANS, C D Region 3, Office of Director 84/02/21 8pp 22585 236 24% Fiche 50-263, 84/02/23, 8403120141

1

B403200287 Forwards IE insp Rept 50-263/84-02 on B40206-10 No noncompliances identified PAPERIELLO,C J. Region 3, Office of Director B4/03/06, LARSON,C E. Northern Btates Power Co. ip 22696 342 24% Fiche 50-263, B4/03/06, B403200287

- --B403200271 IE Insp Rept 50-263/84-02 on B40206-10 No noncompliance or deviation identified Major areas inspected organization & mgt control.audits, advance planning & preparation, training & qualifications & exposure control GRANT.W B. GREGERIL R Region 3. Office of Director B4/03/05 7pp 22696 343 24X Fiche 50-263.B4/03/06,B403200287
- B403190064 Informs that investigation of vendor purchase orders indicated that facility received no fraudulent products sold by Ray Milier, Inc.per IE Builtein B3-07 review LARSON, C E Northern States Power Co 84/03/12 DEYOUNG, R C Director's Office of Inspection and Enforcement 2pp 22664 322 24X Fiche 50-263:84/03/12.8403190064
- A Periodic operating reports & related correspondence
- 8403020177 Monthly operating rept for Jan 1984 W/840210 ltr MYRABO,A L . MUSOLF.D Northern States Power Co 84/01/31 5pp 22440 237 24X Fiche 50-263,84/01/31,8403020197
- 8403300087 Monthly operating rept for Feb 1984 W/840306 itr MYRABO,A L , MUSOLF,D Northern States Power Co 84/02/29 5pp R2822 021 24X Fiche 50-263,84/02/29,8403300087
- 8403130079 Forwards "Efficient & Waste Disposal Semiannual Rept. Jul-Dec 1983: "Offsite Radiation Dose Assessment, 1983" & Ray 4 to "Offsite Dose Calculation Hanual" FEY.F. L. Northern States Power Co. 84/03/01 Region 3, Office of Director 1p 22617 327 24X Fiche 50-263, 84/03/01, 8403130079
- --8403130087 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1983 "
 * Northern States Power Co 83/12/31 15pp 22617 328, 24X
 Fiche 50-263,84/03/01,8403130079
- --8403130096 "Offsite Radiation Dose Assessment, 1983 "
 * Northern States Power Co 83/12/31 4pp 22617 343 24X
 Fiche 50-263,84/03/01,8403130079
- --8403130103 Rev 4 to "Offsite Dose Calculation Hanual"

 ** Northern States Power Co 84/02/23 12pp 22617 347 24x
 Fiche 50-263,84/03/01,8403130079
- 5 Reportable occurrences, LERs & related correspondence
- 8403010316 LER 84-006-00 on 840119, reactor bldg isolation & initiation of standby gas treatment occurred when radiation therk source brought too close to refuel floor spent fuel pool monitor Area radiation monitor relocated H/840324 itr
 HILLER, M L . MUSDLF, D Northern States Power Co 84/02/24 3pp
 22432.098 24X Fiche 50-263.84/02/24.8403310316
- B403080233 PND-III-B4-017A several cracks discovered in stainless steel paping sections in LPCI sys & jet pump instrument seal Stainless steel sections & jet pump instrument seal lines uill be replaced DEFAYETTE, R, CHRISGOTIMOB, N, SHAFER, W Region 3, Office of Director. B4/03/01 ip 22540 125. 24X Fiche 50-263,84/03/01, 8403080233
- 8403120088 LER 84-007-00 on 840206, reactor recirculation motor generator set drive motor breaker failed to open remotely Gaused by binding of rollers Rollers cleaned & repacked w/vendor approved jubricant W/840306 ltr PUDLICK, L., MUSCLF, D. Northern States Power Co. 84/03/05 3pp. 22588.243 24X Ficher 50-263,84/03/05,8403120088.
- 8403120033 LER 84-008-00, on 840207, operating recirculation pump (P) shutdown & associated pump set generator field breaker did not trip Caused by faulty field breaker Maint frequency increased & all bearings & rollers cleaned H/840307 ltr KELLER, H. MUSOLF, D. Northern States Power Co. 84/03/06, 4pp 22585 225 24X Fiche 50-263,84/03/06,8403120033
- 8403130365 LER 84-009-00 on 840207.EFT sys (control room HVAC) transferred to emergency mode due to toxic chemical datector tape break Caused by excessive friction between optics block & tape Spring tension reduced & block replaced H/H840308 ltr HAMMER, H F, MUSCLF.D Northern States Power CO 84/03/08 3pp R2616 270 24X Fiche: 50-263, 84/03/08, 8403130365
- 8403130423 PNO-III-84-0178 on 840308, during visual insp, four J nozzles on feedwater spargers of reactor vessel found cracked Decision on repair & replacement pending more detailed exam State of MN notified DEFAYETTE.R, WALKER,R, SHAFER.W Region 3, Office of Director 84/03/08 ip 22613 090 24X Fiche 50-263,84/03/08,8403130423

- 8403200255 LER 84-010-00 on 840217.emergency filtration train syscontrol room HVAC transferred to toxic chemical emergency mode Caused by release of chlorine into chlorine tank storage room M/840316 itr IVERBON.O N , MUSCLFID Northern States Power Co 84/03/16 3pg 22691 108 24% Fiche 50-263,84/03/16.8403200255
- 8403220003 LER 84-011-00 on 840218 & 23.crack indications detected on loop jet pump 8 instrument seal & on loops A & B of RHR LPGI lines Caused by intergranular stress corrosion cracking Affected matis replaced W/840319 ltr KELLER. M. MUSDLF, D. Northern States Power Co. 84/03/19 3pp 22713 342 24X Fiche 50-243.84/03/19.8403220003
- DOCKET 50-264 DOW CHEMICAL CO
- F Security, medical, emergency & fire protection plans
- 8401260161 Releases public version of request for 2-month extension for completion of revs to emergency plan FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch ip 21759 337 24X Fiche 30-264,84/01/18,8401240141
- --8401260167 Submits public version of request for 2-month extension for completion of revs to emergency plan from 840103-0302 Extension period will be used to modify plan per final ANSI 15 11 (1982) std KOCHER.C W Daw Chemical Co 83/12/23 THOMAS,C G Standard Lattion & Special Projects Branch 1p 21757 358 24X Fiche 50-264,84/01/18,8401260161
- B403050012 Forwards revised emergency plan KDCHER, C W Dow Chemical Co B4/03/01 THOMAS, C O Btanderdization & Special Projects Branch ip 22490 077. 24X Fiche 50-264, 84/03/01, 8403050012
- --8403030013 Revised emergency plan * Dow Chemical Co 84/02/23 559p 22490 078 24X Fiche 50-264,84/03/01,8403050012
- DOCKET 50-265 QUAD CITIES STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8403090294 Public version of revised emergency plan implementing procedures including Procedures GEP 110-0 re station director & GEP 110-2 re acting station directory (shift engineer) WJM Feiton release memo KOVAK, T J , TIETZ, 0 , GERNER, L Commonwealth Edison Co 83/11/03 43pp 22592 017 24X Fiche 50-254,83/11/03.8403090294
- B403060063 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by itcensee.per Bi0709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR VABBALLO.D B Operating Reactors Branch 2 B4/02/10 FARRAR.D L Commonwealth Edison Co. 2pp 22528 303 24X Fiche 50-254.84/02/10.84030.0063
- B403i30i55 Advises that state & iocal plans & preparedness for radiological emergencies adequate Approval conditional on FEMA verification of adequacy of alerting & notification sys.per App 3 of Rev i to NUREO-0654/FEMA-REP-1 BPECK, S W Faderal Emergency Management Agency 84/03/02 DIRCKB, W J Office of the Executive Director for Operations 2pp 22608 229 24X Fiche 50-254,84/03/02.8403130155.
- 8403120149 Notifies of 840323 regional workshop in Rosemont, IL w/all Region III licensees to discuss fire protection safe shutdown requirements Horkshop will provide addi guidance re 10CFR50.App R requirements Agenda encl SPESBARD, R L. Division of Emergency Preparedness & Operational Support 84/03/06 REED.C Commonwealth Edison Co 3pp 22586 182 24X Fiche 50-254,84/03/06,8403120149
- P Operating license stage documents & correspondence
- 8403050337 Forwards order confirming util commitment re intergranular streas corrosion cracking insp & repair Order being filed w/Ofc of FR for publication Safety evaluation also enc1 VABSALLO.D B Operating Reactors Branch 2 84/02/15 FARRAR.D L Commonwealth Edison Co 2pp 22501 344 24X Piche 50-265.84/02/15.8403050337

- --8403050341 Order confirming util commitment re intergranular stress corresson cracking these repair RCS leakage will be Iimited to 2 gpm increase in unidentified leakage within any 24 h pariod EISENHUT.D o Division of Licensing 84/02/15 Communumenth Edison Co. 6pp. 22501 346 24X Fiche 50-265.84/02/15.8403050337
- --840303030345 Safety evaluation re intergranular stress corrosion cracking Insp & mod plans must be submitted to NRC at least 3 months prior to start of nert refueling outage # Office of Nuclear Reactor Regulation. Director 84/02/15 11pp 22501 352 24% Fiche 50-265.84/02/15.8403050337
- 8403060059 Forwards safety evaluation re util response to 830904 intergranular stress corrosion cracking insp order confirming shutdown to inspect recirculation. RHR. core spray & reactor water cleanup sys Required actions satisfactory DENTON. H R Office of Nuclear Reactor Regulation. Director 84/02/15 FARRAS. D L Commonwealth Edison Co 2pp 22528 222 24X Fiche 50-265.84/02/15.8403060059
- B403140340 Summary of 831215 meeting w/GE & Hark i Dwners Group in BethesdarMD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL, B L. Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2. Sipp 22635 198 24X Fiche 50-000.84/02/21. 8403140340
- 8403130102 Submits info re Cycle 7 shutdown margin demonstration.per 840224 request Reloaded core in compliance w/Tech Specs & startup allowed to proceed RYBAK.B Commonwealth Edison Co 84/02/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 12pp 22602 212 24X Fiche 50-265,84/02/27,8403130102
- 8403050119 Forwards supplemental response to Generic Ltr 83-28,
 "Required Actions Based on Oeneric Implications of Salem
 ATME Events "
 BARNES, P L Commonwealth Edison Co 84/02/29. DENTON, H R Office
 of Nuclear Reactor Regulation, Director 26pp. 22488 084 24X
 Fiche 50-000,84/02/29,8403050119
- 8403130353 Documents present resolution of SER open items & deficiencies noted in Franklin Research Ctr technical evaluation rept re environ qualification of safety-related electrical equipment RYBAK, B Commonwealth Edison Co 84/02/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 40pp 22617 080 24X Fiche 50-254,84/02/29,8403130353
- 8403130400 Forwards 840210 responses to Generic Ltr 83-33 clarifying TMI Item II K 3 31 Util concurs w/NRC position Item should be clased HYBAK, B Commonwealth Edison Co 84/03/02 EISENRUT, D 9 Division of Licensing 2pp 22613 143 24X Fiche 50-000, 84/03/02, 8403130400
- 8403150275 Generic Ltr 84-07 to all licensess of BWRs re procedural guidance for pipe replacement at UWRs Svc list encl EISENHUT.B G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000.84/03/14.8403150275
- 3403270130 Application for amend to License DPR-25, changing Tech Specs to extend certain MAPLHOR curves to 40,000 MWd/ST RYBAK.B Commonwealth Edison Co 84/03/19 DENYON, H R Office of Nuclear Reactor Regulation. Director 2pp 22774 129 24X Fiche 50-000.89/03/19.8403270130
- --8403270136 Errata & Addenda Sheet 9, replacing Page 4-14 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Quad Cities 1 & 2 Nuclear Power Stations" ** General Electric Co NEDO-24146A ERR 09 83/01/31 2pp 22774.135 24X Fiche 50-000.84/03/19.8403270130
- O Inspection reports, IE Bulbetins & correspondence
- 8403090337 Forwards order confirming util commitment re intergranular stress corrosion Cracking insp & repair Order being filed w/Ofc of FR for publication Safety evaluation also encl VASSALLO,D 0 Operating Fractors Branch 2 84/02/15 FARRAR,D L Commonwealth Edison Co 2pp 22501 344 24X Fiche 50-265,84/02/15,840305037
- --8403050341 Order confirming util commitment re intergranular stress correction cracking insp & repair RCS leakage will be limited to 2 gpm increase in unidentified leakage within any 24 h period EISENHUT, D G. Division of Licensing 84/02/15 Commonwealth Edison Co. Opp. 22501 346. 24X Fiche-50-265.84/02/19.8403050397

- --8403050345 Safety evaluation re intergranular stress corrosion cracking Insp & mod plans must be submitted to NRC at least 3 months prior to start of next refueling outage 4 Office of Nuclear Reactor Regulation, Director 84/02/15 11pp 22501 352 24X Fiche 90-265.84/02/15.8403050337
- B403060059 Forwards safety evaluation re util response to B30904 intergranular stress corresion cracking insporder confirming shutdown to inspect recirculation.RHR, core spray & reactor water cleanup sys Required actions satisfactory DENTON.H R Dffice of Nuciear Reactor Regulation, Director B4/02/15 FARRR.D L Commonwealth Edison Co 2pp 22528 222 24X Fiche 50-265.84/02/15.8403060059
- 8403120134 Forwards lE Insp Repts 50-237/84-01.50-249/84-01. 50-234/84-01.50-265/84-01.50-295/84-01 & 50-304/84-01 on 840203-14 No noncompliance identified 84/02/23 REED, C Commonwealth Edison Co 2pp 22590 090 24X Fiche 50-000,84/02/23,
- --8403120137 IE Insp Repts 50-237/84-01.50-249/84-01.50-254/84-01.
 50-265/84-01.50-275/84-01 & 50-304/84-01 on 840203-14 No noncompliance or deviations identified Major areas inspected allegations of improper operation CKRISBOTINOS, N. WALKER, R.D. Region 3, Office of Director 84/02/21 4pp 22590 092 24X Fiche 50-000.84/02/23.8403120134
- 8403050002 Submits brief outline of regulatory improvement program Program implements basic changes in practices & structure of operation Summary of corrective actions taken in response to control rod insertion error encl
 THOMAB, B Commonwealth Edison Co 84/02/24 KEPPLER, J O Region 3, Office of Director lipp 22490 226 24X Fichs, 50-254, 84/02/24, 8403050002
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Pian " Pian designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THOMAS, B Commonwealth Edison Co 84/02/24 KEPPLER, J Q Region 3, Office of Director 3pp 22490 139 24X Fichs 50-000,84/02/24,8403050043
- --B403050046 Rev O to "Corporate Regulatory Performance Improvement Fian" * Commonwealth Edison Co 84/02/29 22pp 22490 142 24X Ficho 50-000, 84/02/24, 8403050043
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operatod Valve Control Circuits & Amunciation " Svc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22709 237 24X Fiche 30-000.84/02/28,8401170072
- B403030072 Forwards addendum to IE Insp Repts 30-254/83-21 & 50-265/83-i9, comparing beta analyses of liquid sample split & gross beta results of spixed liquid sample Info will close Open Items 50-254/83-21-02 & 50-265/83-19-0i PAPERIELLO.C J Region 3, Office of Director B4/02/29 REED, C Commonwealth Edison Co 1p 22470 014 24X Fiche 50-254, 84/02/29, 8403050072
- --B403050074 Addendum to IE Insp Repts 50-254/63-21 & 50-265/63-19 re comparative beta analysis results of liquid sample split & gross beta results of spiked liquid sample # Region 3, Office of Director # B4/02/29 ip. 22490 015 24% Fiche 50-254,84/02/29,8403050072
- 8403190207 Forwards IE Insp Repts 50-254/83-24 & 50-265/83-23 on 830804-840202 No noncompliance identified LITEL.W 8 Region 3, Office of Director 84/03/01, REED.C Commonwealth Edison Co 2pp 22671 072 24X Fichs 50-254.84/03/01, 8403190207
- --8403190208 it Insp Repts 50-254/83-24 & 50-265/83-23 on 830804-840202
 No noncompliance or deviations identified Major areas
 inspected review of inservice inspireactor water cleanup sys
 piping, IE bulletins & LERs
 CILIMBERG,R L , DANIELSON,D H , WARD,K D Region 3, Defice of
 Director 84/03/01 Ropp 22671 074 24X Fiche,50-254,84/03/01,8403190207
- B402070007 IE Info Notice B4-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Bvc list encl GRACE, J N Division of QA, Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22532 327 24X Fiche 50-000.84/03/02.8402070007

- 8402070008 lE info Notice 84~16, "Failure of Automatic Sprinkier Sys Valves to Operate " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-i3, "Reporting of Radiological Releases 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fishe 50-000,84/03/02,8402090009
- B402090011 IE 1nfo Notice 84-i7, "Problems W/Liquid Nitrogen Cooling Components Below Nii Ductility Temp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402070024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys" Byc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. i18pp 22635 049, 24% Fiche 30-000,84/03/07,8402090024
- B40209002B IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Sys " Svc list enc!

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 i86 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYDONO, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24x Fiche 50-000,84/03/12,8402070031
- B40323008B Ack receipt of regulatory performance improvement plan Perlodic meetings requested to discuss progress on program & provide feedback KEPPLER.J G Region 3, Office of Director B4/03/20 THOMAS.B Commonwealth Edison Co ip 22730 161 24X Fiche 30-000.B4/03/20.B4032300BB
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER.J & Region 3. Diffice of Director 3pp 22730 142 24X Fiche 50-000. 84/03/20.840323008B
- --8403230126 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden, Guad Cities, Zlon & LeSalie Operating Nuclear Stations & Byron & Braldwood Project Operating Organizations " * Commonwealth Edison Co 84/02/29 22pp 22730 165 24X Fiche 50-000, 84/03/20, 8403230088
- B403260196 Forwards responses to IE Builetin 83-07, "Apparently Fraudulent Products Bold by Ray Miller, Inc " Quad Cities supplied w/piping matis from Ray Miller, Inc during const Evaluation encl Concerns of IE Builetin 83-06 satisfied BARNES, Pt. Commonwealth Edison Co 84/03/20 KEPPLER, J G Region 3, Office of Director, 19pp 22756 185 24X Fiche 50-000, 84/03/20, 8403260196
- B402090043 IE Info Notice B4-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc llst encl JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24% Fiche 50-000.84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Evc Life of Relays in Befety-Related 8ys " Svc list encl JURDANNE, L. Davision of Emergency Preparedness & Englneering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc i35pp. 22933 001, 24% Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403080197 "Rept of Occupational Personnel Radiation Doses,1983 " W/B40227 ltr BCOTT.J B Commonwealth Edison Co 83/12/31 i3pp. 22559 099 24X Fiche 50-000,83/12/31,8403080197
- 8403220120 Annual whole body external exposures for 1983 W/840316 itr RYBAK.8 Commonwealth Edison Co 83/12/31 7pp 22714 007 24X Fiche: 50-000, 83/12/31, 8403220120

- 8403060ii3 Forwards Rev i to "Effluent & Waste Disposal Semiannual Rept Jul-Dec 1982" Errata for "Liquid Alpha Radioactivity, Jen-Jul 1983" & "Solid Radwaste Summary, Jul-Dec 1983," also encl KALIVIANAKIS,N Commonwealth Edison Co 84/02/07 KEPPLER. J G Region 3, Office of Director ip 2258 252 24X Fiche 50-254,84/02/07.8403060113
- --8403060i17 Rev 1 to "Effluent & Waste Disposal Semiannual Rept Jul-Dec 1982 "
 - * Commonwealth Edison Co 83/05/31 7pp 22518 253 24X Fiche 50-254,84/02/07,8403060113
- --8403060121 Errata for "Liquid Alpha Radioactivity Jan-June 1983 " * Commonwealth Edison Co 83/06/30 ip 22518 260 24X Fiche 50-254,84/02/07,8403060113
- ---8403060127 "Bolid Radwaste Summary.Jul-Dec 1983 "

 * Commonwealth Edison Co 83/12/31 App 22518 261 24X
 Fiche 50-254,84/02/07,840306013
- 8403130382 Monthly operating repts for Feb 1984 W/840308 1tr MISAK, A.: KALIVIANAKIS, N. Commonwealth Edison Co. 84/02/29 24pp 22616 275 24x Fichs 50-234,84/02/29,8403130382
- 8403150019 Listing of changes, tests & experiments completed during Feb 1784 Summary of safety evaluation reported per 10CFR50 59 encl H/840308 itr KALIVIANAKIS,N Commonwealth Edison Co 84/02/27 CASE, E 9 Office of Nuclear Reactor Regulation. Director 3pp 22644 360 24X Fiche 50-254,84/02/27,8403150019
- S Reportable occurrences. LERs & related correspondence
- 8403120107 Revised LER 83-020/017-3 on 831027.11 welds identified as having crack indications Caused by intergranular stress corrosion cracking Repair employed weld overlay or Induction heat stress improvement W/840221 itr CLARK.D. KALIVIANAKIB.N. Commonwealth Edison Co. 84/02/21 KEPPLER.J. Region 3. Office of Director 7pp. 22588 172 24X Fiche 50-265.84/02/21.8403120107
- 8403070256 Foilowup Part 21 rept re defective mechanical snubber capstan springs supplied by Pacific Scientific Affected utils listed Purchasers have been notified & advised to work directly w/Facific Scientific in disposition HDVI.L NPS Industries. Inc 84/02/24 DEYOUNG.R C Director's Office Office of Inspection and Enforcement 2pp 22536 279 24X Fichs 50-000.84/02/24.8403070256
- 84030800il Forwards response to Commissioner Gilinsky request for info on frequency of personnei errors at selected operating plants Summany of tabulated events re operator errors, personnei errors or procedural errors provided for CY83 DIRCKS,W J Office of the Executive Director for Operations 84/02/24 PALLADING, OILINSKY, ROBERTS Commissioners 17pp 22584 142 24X Fiche 50-000.84/02/24,8403080011
- 8403200106 Revised LER 83-021/01T-5 on 831028.ultrasonic exams of large bore stainless steel pipe welds identified 11 welds w/crack indications Caused by intergranular stress corrosion cracking Weld overlay performed W/840228 itr CLARK.D. KALIVIANAKIS.N. Commonwealth Edison Co. 84/02/28 KEPPLER.J. Region 3. Office of Director 7pp 22685 318 24X Fichs 50-265.84/02/28.8403200106
- B403160027 LER 84-003-00 on 840211 main feed breaker to 480-voit essential svc bus 27 tripped Caused by overcurrent condition through crosstie Loads iimited W/840308 ltr CLARK, D 0 , KALIVIANAKIB, N Commonwealth Edison Co 84/03/08 3pp 22655 165 24X Fiche 50-265, 84/03/08, 8403160027
- B4032001BB LER B4-004-00 on B40215.full scram received while reactor shut down Caused by faulty 10% closure limit switch on MBIV AD R-203-2A Limit switch replaced W/840313 ltr KALIVIANAKIS,N Commonwealth Edison Co 84/03/13 2pp 22698 284 24X Fichs 50-265.B4/03/13,84032001BB
- DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- B40305020B Advises that NRC wiil not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per Bi0709 Generic Ltr B1-27 W/o request.entire plan will be placed in PDR MILLER.J R Operating Reactore Branch 3 84/02/16 FAY, C W Hisconsin Electric Power Co 2pp 22528 152 24X Fiche 50-266.84/02/16.8403050208

- 403120045 Notifies of 840323 workshop on fire protection safe shutdown requirements of 10CFR30. App R in Rusemont. IL to discuss IE Info Notice 84-09 % provide add1 shutdown analyses &/or mod guidance Apenda enci SPEBSARD. R L Division of Emergency Preparedness & Operational Support 84/03/06 BURSTEIN. R Wisconsin Electric Power Co 3pp 22370 294 24X Fiche 50-266. 84/03/06. 8403120045
- 403160080 Submits addl info on Generic Ltr 82-33 sthedule requirements for Smergency response capabilities Vendor of new computer sys requested 1-yr delay to June 1785 for delivery. **sfetting scheduler commitments made to NRC FAV.C W Hisconsin Electric Power Co 84/03/08 DENTON, H R GIFfice of Nuclear Reaction Regulation. Director 4pp 2252 327 24X Fiche 50-266,84/03/08,8403160080
- 403220093 Ack receipt of 840306 ltr informing NRC of corrective actions re deviation from commitment & resolution of revised emergency plan 58R clarification items noted in IE Insp. Repts 50-266/83-25 & 50-301/83-25 PAPERIELLO.C J. Region 3. Office of Director 84/03/19 BURSTEIN.S Wisconsin Electric Power Co. ip 22716-324 24X Fiche 50-266.84/03/19.8403220093
- -8403220099 Responds to NRC B40202 ltr forwarding revised emergency plan SER & request for clarification of listed items & deviation from commitment Corrective actions Procedure EP 5 0.
 "Organizational Control of Emergencies." revised FAY.C W Wisconsin Electric Power Co B4/03/06 KEPPLER.J 0.
 PAPERIELLO.C J Region 3. Office of Director 9pp 22716 325 24X Fiche 50-266.84/03/19.8403220093

Adjudicatory correspondence

- 3402220157 Order extending time until 840228 for Commission to act to review Director's Decision DD-83-i4 CHILK.8 J Office of the Secretary of the Commission B4/02/21 Commissioners 1p 22337 362 24X Fiche 50-000, 84/02/21. 8402220157
- 8403010238 Order extending time until 840305 for Commission to act to review Director's Decision DD-83-14 & 831029 decision denying request of Environ Policy Inst CHILM.8 J Office of the Secretary of the Commission 84/02/28 Commissioners ip 22434 210 24X Fiche 50-000,84/02/28,84030.0231
- B403090069 Informs that Commission unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expired Decision became final agency action on B40305 CHILK, S J Office of the Secretary of the Commission B4/03/08 CELEBREZIE, A J Ohio, State of 2pp 22575 350 24% Fiche 50-000,84/03/08.8403090069
- 8403090074 Informs that Commission unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expired Decision became final agency action on 840305 CHILK, 9 J Office of the Serretary of the Commission 84/03/08 MILLAR. F Environmental Policy Institute ip 22575 272 24X Fichs 50-000,84/03/08.84030990074
- 8403090113 Informs of Commission decision not to review Director's Decision DD-83-14 Time for Commission to act expired on 840305 W/o encl
 CHILK.8 J Office of the Secretary of the Commission 84/03/08 RESNIKOFF.M Bierra Club ip 22376 079 24X
 Fichs 30-000.84/03/08.8403090113
- P Operating license stage documents & correspondence
- 8403290002 Final response to FOIA request for four categories of documents, tests, studies & analyses referencing or pertaining to NUREO-0103, "STB for NAW PHR" App A documents encl FELTON. J Division of Rules and Records B4/01/13 MADDEN, T J Kaye, Scholer, Fierman, Hays & Handler. 6pp 22816 127 24% Fiche 50-000,84/01/13,8403270002
- --8403290045 Discusses G Reed 730301 ltr to G Arlotto re RCPB leakage detection sys Method for detecting slow departure from normal indications of leakage detection sys provided in util manitoring charts
 PORSE, L. Atomic Energy Commission Directorate of Regulatory Blandards 73/03/09 HICHMANIK Atomic Energy Commission 2pp 22816 303 24K Fiche 50-000,84/01/13,8403290002
- --B403290049 Forwards info describing RCB leakage monitoring Related info ancl REED: 0 A Wisconsin Electric Power Co 73/03/01 ARLOTTO, 0 Atomic Energy Commission - Directorate of Regulatory Standards 40pp 22817 330 24X Fiche 50-000 B4/01/13 8403290002

- B403070255 Application for amend to Licenses DPR-24 & DPR-27 Amend incorporates changes to Teth Specs re accident monitoring instrumentation to be installed per NUREG-0737 requirement FAV.C W Wisconsin Electric Power Co 84/02/29 DENTION, H.R Office of Nuclear Reactor Regulation, Director MILLER, J.R. Operating Reactors Branch 5 4pp 22536.179. 24X Fiche 50-266.84/02/29,8403070255
- --8403070237 Proposed Tech Specs incorporating changes re-accident monitoring instrumentation to be installed per NUREG-0737 requirement # Wisconsin Electric Power Co 84/02/27 10pg 22536:183 24X Fiche 50-266.84/02/27.8403070255
- B403060373 Informs that encl notice of consideration of issuance of amend to Licenses DPR-24 & DPR-27 & proposed NSHC determination & opportunity for hearing sent to DFc of FR for publication Amend concerns leak surveillance. W/o encl COLIURN, T G Operating Reactors Branch 3 B4/03/01 FAY, C. W Hisconsin Electric Power Co ip 22532-255 24% Fiche 50-266.84/03/01.8403060375.
- 8403120237 Requests remittal of addl fee for review of 820527 application re-steam generator replacement in response to util 831205 denial that Class V fee applicable MILLER, W D License Fee Management Branch 84/03/01 FAY, C M. Misconsin Electric Power Co 3pp 22619 238 24X Fichs 50-266,84/03/01,8403120237
- 8403220254 Forwards FR notice of consideration of issuance of amend to Licenses DRR-24 & DRR-27 & proposed NBHC & opportunity for hearing re 831223 application to revise surveillance interval for post-accident recovery sys outside containment COLBURN.T G. Operating Reactors Branch 3 84/03/01 FAY.C W Misconsin Electric Power Co. 2pp 22723 325 24X Fichs 50-266.84/03/01.8403220254
- --8403220239 FR notice of consideration of issuance of amend to Licenses DFR-24 & DFR-27 & proposed NSHC & opportunity for hearing re 83123 application to revise surveillance interval for post-accident recovery sys outside containment MILLER.JR Operating Reactors Branch 3. 84/02/09. 8pp 22723 327 24X Fiche 50-266.84/03/01,8403220254
- B403120157 Advises that, due to delays in delivery & installation of auxiliary safety instrumentation panels (ASIPs), installation of six accident monitors addressed in NUREG-0737, Items II F i 1 through II F i 6 will not be completed by 840630. FAY, C W Wisconsin Electric Power Co 84/03/05. DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 3pp 22586: 250 24X Fichs 50-266,84/03/05,8403120157
- 8403130005 Informs of plans to Cycle 12 reload core Startup of Cycle 12 streeted in mid-Mar 1984 following steam generator replacement
 FAY.C W Wisconsin Electric Power Co 84/03/05 DENTON, H R
 Office of Nuclear Reactor Regulation, Director, MILLER, J R
 Operating Reactors Branch 3 Spp 28615 195 24X
 Fichs 50-286, 84/03/05,8403130005
- 8403170417 Comments on 840207 ltr modifying 851025 request for amenda to Tech Specs re changes in conduct of containment integrated leak test rates No significant hazards consideration discussion required MILLER, J.R. Operating Reactors Branch 3 84/03/06 FAY, C.W. Hisconsin Electric Power Co. 2pp. 22681 344 24X Fiche 50-266,84/03/06,8403190419
- 8403160054 Submits evaluation procedure for reactor vessel outlet nozzle-to-shell weld indication, per IMB-3122 4 of ASME Section XI Flaws acceptable Continued svc warranted based on avaluation results FAY.C W. Misconsin Electric Power Co. 84/03/12 DENTON, H.R. Optics of Nuclear Reactor Regulation, Director MILLER, J.R. Operating Reactors Branch 3. 3pp. 22654 360 24X Fichs 30-266.84/03/12.8403160054
- 8403210077 Responds to Generic Ltr 84-01 re use of terms important to safety & safety-related Widespread use of terms in NRC regulations considered unrasolved Notification of meeting requested FAY.C W Wisconsin Electric Power Co 84/03/15. EISENHUT,D Q. Division of Licensing. TAYLOR.J M Director's Office. Office of Inspection and Enforcement 1p 22705 165. 24X Fiche 30-266:84/03/15,8403210077
- B403220162 Application to amend Licenses DPR~24 & DPR~27, changing Tech Specs to add add1 restrictions on heavy loads over spent fuel pool & making additions & deletions re safety-related snubbers, per IE Bulletin 79-14 & Item II D 1 FAY.C W Misconsin Electric Power Co. 84/03/16. DENYDN, H R. Office of Nuclear Reactor Regulation, Director MILLER, T R Operating Reactors Branch 3. 4pp \$22718.057 24X Fiche 50-266,84/03/16,8403320162

- --8403220167 Proposed Tech Specs, adding additestrictions on heavy loads over spent fuel pool, making additions & deletions to list of safety-related snubbers & revising position titles within administrative specs

 * Wisconsin Electric Power Co 84/03/16 29pp 22718 061 24X
 Fiche 50-264, 84/03/16, 8403220162
- 8403270125 Submits balance of payment for Class V fee for license amend approval resteam generator replacement FAV.C W Wisconsin Electric Power Co 84/03/16 MILLER.W O License Fee Management Branch ip 22774 ii4 24X Fiche 50-266.84/03/16.8403270125
- 8403270098 Responds to request for Tech Spec change to limit amount of overtime worked by plant staff members performing safety—related functions Amend to Tech Specs delayed pending adoption of Commission proposed rule
 FAY.C W Wisconsin Electric Power Co 84/03/19 DENTON, H R
 Office of Nuclear Reactor Regulation, Director MILLER, J R
 Operating Reactors Branch 3 2pp 22766 339 24X
 Fiche 50-266.84/03/19.8403270098
- 8403270237 Discusses reactor vessel outlet nozzle-to-shell weld flaw indication evaluation Requirements of ABME Section XI safisfied & reactor vessel confirmed for continued operation FAY.C.W Wisconsin Electric Power Co 84/03/23 DENTON.H R. Office of Nuclear Reactor Regulation, Director MILLER.J R Operating Reactors Branch 3, 6pp. 22771 348 24X Fiche 30-266,84/03/23,8403270237
- Q Inspection reports, IE Bulletins & correspondence
- B403050223 Further response to FOIA request for records of named individuals.including repts, analyses, studies, test calculations, procedures & practices for measurement of RCS leakage Forwards App C documents Search continuing FELTON.J M Division of Rules and Records 84/02/07 MADDEN.T J Raye, Scholer, Flernan, Hays & Handler 3pp 22476 234 24X Fiche: 50-000, 84/02/07, 8403050223
- --8403050256 Notifies that independent measurements of identified & unidentified RCS leak rates for all PMRs in Region III performed per Procedures 617278 & 617288 Insp. findings summarized NGRELIUS, C.E. Division of Engineering 82/03/08 JORDAN, E.L. Division of Engineering & Guality Assurance (Pre 830103) 2pp 22496-270 24X Fiche 50-000,84/02/07,8403050223
- 8403060131 Forwards IE Insp Repts 50-266/83-21 & 50-301/83-20 on 831011-840111 & mpt meeting on 840104 & notice of violation REESBARDR L. Region 3, Office of Director 84/02/21 BURSTEIN,S Wisconsin Electric Power Co 3pp 22506 182 24X Fiche 50-266,84/02/21,8403060151
- --8403060162 Notice of violation from insp on 831011-840111 SPESBARD,R L Region 3, Office of Director 84/02/21 6pp 22506,185 24X Fiche 50-266.84/02/21,8403060151
- --8403060176 IE Insp Repts 50-266/83-2i & 50-301/83-20 on 831011-84011i & mgt meeting on 840104 Violation noted failure to maintain cleaniiness control, provide & follow procedures, control documents & properly store recards
 HASSE,R A . CHOULES,N C . JORDAN,M J Region 3, Office of Director 84/02/13 54pp 22506 171 24X Fiche 50-266.84/02/2i, 8403060151
- B403130002 Forwards IE Insp Repts 50-264/83-26 & 50-301/83-24 on B31201-840131 & notice of yiolation BMAFER: W D Region 3, Office of Director 84/02/22, BURSTEIN, S Wisconsin Electric Power Co 2pp 22615, 267 24X Fichs. 50-266: 84/02/22, 8403130002
- --8403130011 Notice of violation from inep on 831201-840131 BHAFER: H D Region 3, Office of Director 84/02/22 2pg 22415 269 24% Fiche 50-266,84/02/22,840313004
- --8403130023 IE Insp Repts 50-266/83-26 & 50-301/83-24 on 831201-840131 Noncompliance noted fire in containment resulted when welding slag landed on acetylene hose attached to acetylene bottle not in use & not moved to safer location HAGUE, R L , FITZPATRICK, B , JACKIW, I N Region 3, Office of Director 84/02/21 9pp 22615 271 24X Fiche 50-266,84/02/22,8403130002
- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909-239 24X Fiche 50-000,84/02/28,8401190072

- 8402070007 IE Info Notice 84-i4, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enci GRACE, J M. Divysion of GA. Safeguerds & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22952 329 24X Fiche 50-000,84/03/02,8402070007
- B402090008 IE Info Notice B4-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list enc? JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below N11 Ductility Temp " Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403190240 Forwards IE Insp Rept 50-266/83-20 on 831213-16 & 840110-13 & notice of violation LITTLE.W S Region 3. Office of Director 84/03/05 BURSTEIN.S Wisconsin Electric Power Co 2pp 22672 037 24X Fichw 50-266.84/03/05.8403190240
- --8403190244 Notice of violation from insp on 831213-16 & 840110-13 LITTLE.W S Region 3. Office of Director 84/03/02 2pp 22672 039 24X Fiche 50-266.84/03/05.8403190240
- --8403190247 IE Insp Rept 50-266/83-20 on 831213-16 & 840110-13
 Nancompliance noted failure to follow steam generator
 replacement project procedures
 KLEINSORGE,W P Region 2. Office of Director BLAKE.J J
 Division of Engineering & Operational Programs 84/02/23 17pp
 22672 041 24X Fiche 50-266.84/03/05.8403190240
- 8402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Eafe Shutdown Sys " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. iiBpp 22635 049 24X Fiche 50-000,84/03/07,8402070024
- 8402090028 IE Info Notice 84-18, "Stress Corresion Cracking in PWR Sys " Syc list enci JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Svc list encl DEYOUNG.R C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24X Fichs 50-000.84/03/12,8402070031
- 8403220093 Ack receipt of 840306 1tr informing NRC of corrective actions re deviation from commitment & resolution of revised emergency pian SER clarification items nated in IE Insp. Repts 50-266/83-25 & 50-301/83-25
 PAPERIELLO, C J Region 3, Office of Director 84/03/19
 BURSTEIN, S Wisconsin Electric Power Co ip 22716 324 24X
 Fiche 50-266,84/03/19,8403220093
- --8403220099 Responds to NRC 840202 ltr forwarding revised emergency plan SER & request for clarification of listed items & deviation from commitment Corrective actions Procedure EP 5 0, "Organizational Control of Emergencies," revised FAY.C W Wisconsin Electric Power Co 84/03/06 KEPPLER.J 0, PAPERIELLO, C.J. Region 3, Office of Director 9pp 22716 325 24X Fiche 50-266,84/03/19,8403220093
- 8402090043 IE info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Byc Life of Relays in Safety-Related Bys " Syc list enc] JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044

- R Periodic operating reports & related correspondence
- 8403060358 "Semiannual Honitoring Rept. Jul-Dec 1983 " H/840229 itr FAV.C W Wiscomein Electric Power Co 83/12/31 DENTON: H R Dffice of Nuclear Reactor Regulation. Director 18pp 22817 026 24X Fiche 50-266:83/12/31:8403060358
- 8403120066 "Annual Results & Data Rept.1983 " W/840301 ltr FAY.C W Wisconsin Elettric Power Co 83/12/31 KEPPLER.J O Region 3. Office of Director 59pp 22591 070 24X Fiche 50-266.83/12/31.8403120066
- 8403140139 Monthly operating repts for Feb 1984 W/840308 ltr FAY.C W Wisconsin Electric Power Co 84/02/29 lipp 22620 252 24X Ficha 50-266,84/02/29,8403140139
- S Reportable occurrences, LERs & related correspondence
- B403130379 PND-III-B4-022 in response to IE Info Notice 82-29, exam identified 67 of 74 control rod drive support pins withack indications Licensee & Westinghouse evaluating exam findings to determine required action
 JDRDAN.M. JACKIM.I. STAFER.N. Region 3. Office of Director B4/03/02 ip 22616 092 24x Fichy 50-266.84/03/02.8403130379
- 9403260072 Forwards safety evaluation of damaged control rod guide tube support plns UI indictions on shank-to-collar not safety concern FAYs W Hisconsin Electric Power Co 84/03/19 DENION H R Office of Nuclear Reactor Regulation. Director HILLER, J R Operating Reactors Branch 3 17pp 22746 323 24% Fiche 50-266-84/03/19,8403260072
- ~-8403260073 "Westinghouse Safety Evaluation.Cracked Control Rpd Ouide Tube Support Pins " " Westinghouse Electric Corp 84/03/03 28pp 22746 340 24X Fiche 50-265.64/03/19.8403260072
- DOCKET 90-267 FORT BT VRAIN NUCLEAR GENERATING STATION
 F Security, medical, emergency & fire protection plans
- 8403240161 Forwards IE Insp Rept 50-267/83-32 on 83:203-09 No violations or deviations identified JUHNSUNE H Region 4. Office of Director 84/02/03 LEE.DR Public Service Co of Colorado 4pp 22750 345 24x Fiche 30-267.84/02/03.8403260161
- ~-8403260167 IE insp Rept 50~267/83~32 on 831205~09 No violations or deviations identified Major areas inspected security systematic physical barriers-protected areas & vital area testing & maint & alarm stations Details withheld (ref 100FR73 21) CALDKELL.R A , KELLY.J A F , HUNNICUTT.D M Region 4, Defice of Director 84/02/01 2pp 22750 347 24% Fiche 50~267, 84/02/03.
- 8403240100 Forwards IF Insp Rept 50-267/84-03 on 840116-20 No violations of deviations noted JOHKSON.E H Region 4. Office of Director 84/02/14 LEE.OR Public Service Co of Colorado 2pp 22738 231 24X Fiche 30-267.84/02/14.8403260100
- --B403260107 IE Insp Rept 50-267/B4-03 on B40116-20 No violations or deviations noted Major areas inspected raduaste program, including organization & mgt controls training & qualifications & solid raduaste processing WILQURN.L. MURRAY, B. HUNNICUTT, D. M. Region 4. Office of Director B4/02/13 iOpp 22758 253 24X Fiche 50-267, 84/02/14, 8403260100
- 8403130435 Requests exemption from requirements of Sections ill Q.J.L & D to 10CFR30.App R Fire protections provisions believed adequate to protect health & safety of public in event of accidents involving fires Affidavit enci LEE.D R Public Service Co of Colorado 84/03/02 COLLINS, J T Region 4. Office of Director 9pp 22613 163 24X Fichs 50-267.84/03/02.8403130435
- 840322013B Forwards revised schedule for supplying info re emergency response capabilities requested by Generic Ltr 82-33,per 840223 telcon Reg Guide i 97 rept will be completed by 85022B BREY. H L Public Service Co of Colorado 84/03/09 COLLINS. J F Region 4. Office of Director 3pp 22714 285 24% Fiche 50~267.84/03/09.8403220138

1 Financial information

- 8403270192 Annual Financial Rept 1983 M/840323 ltr PERSON,R T , WALKER,R F , WAREHDDURO,D Public Service Co of Colorado 83/12/31 BDYD,R S Office of Nuclear Reactor Regulation, Director 57pp 22770 073 24X Fiche 50-267,83/12/31, 8403270192
- P Operating license stage documents & correspondence
- B403020014 Partial response to FOIA request for seven categories of documents re NRC regionalization program App A documents in PDR Review of remaining documents incomplete FELTON.J M. Division of Rules and Records B3/12/16 LOWENTHAL.J Nuclear Information & Resource Service 3pp 22492 248 24x Fiche 50-000.03/12/16.8403020014
- --B212080692 Forwards FR notice amending iOCFR30 4 informing public that communications & applications should be sent to Region 4 Ltr to Congressional Committees enci DENTON-HR Office of Nuclear Reactor Regulation, Director 82/12/01 FELION-J H Division of Rules and Records 2pg 22493 309 24% Fiche 50-000,83/12/16,84030220014
- --D212GBO693 "Regional Licensing Program Fort Bt Vrain Contrating Station," 10CFR50 final rule Amend delegates responsibility for implementing licensing program to regional administrator Draft Congressional itrs encl DRCKB.W J Office of the Executive Director for Operations, 02/12/01 5pp 22493 311 24% Fiche 50-000, 93/12/16, 8403020014
- --B2(2130052 Summary of B21116 meeting w/util onsite re delegation of licensing functions to Region 4 Uniqueness of Factifity & need to treat aspects differently from other LURs discussed. Draft delegation of authority memo and for signature. DENTON, H.R. Defrice of Nuclear Reactor Regulation, Director B2/11/29 DERCKS, W.J. Defrice of the Executive Director for Operations Spp. 22493 286 24X Fiche 50-000,83/12/16.
- --8212160039 Forwards FR notice & amend to iOCFR50, reflecting delegation & assignment of certain licensing actions to Region 4 administrator BENTON, H.R. OFFICE OF Nuclear Reactor Regulation, Director 02/11/30 DIRCKS, W.J. Office of the Executive Director for Operations /pp 22493 302 24X Fiche 30-000, 83/12/16.
- --030ii40406 Describes selected approach for tronsfer & maint of facility official docket files & supporting documentation to flegion 4 Region 4 will assume routine document distribution on 82ii01

 FUNCHCB.V L Pianning & Program Analysis Staff 82/10/10, EIECHBUT.B O Division of Licensing 2pp 22492 353 24X Fiche 50-000, 03/12/16-0403020014
- --8301149490 Advises that Region 4 assumes responsibility for receipt & distribution of all facility documentation effective 821101 800TF.R.8 Detument Management Branch, 82/10/20 Document Hanagement Branch ip 22492 355 24X Fiche 50-000, 83/12/16, 8403DR0014
- --B301140494 Advises that Region 4 assumes responsibility for receipt & dissemination of incoming licenses communications for facility effective B2:101
 SCOTT. B Detument Management Branch B2/10/27 QAQLIARDO.J E Division of Resident, Reactor Project & Engineering Programs 1p 24492 336 24X Fiche 50-000, B3/12/16,8403020014.
- --B304260013 Forwards functional transfer checklist used to coordinate administrative aspects of transfers of NRC headquarters functions to regions Subjs to prepare checklists for listed STELLO, V. Regional Operations & Ceneric Requirements B3/04/19 DENTON. H. Office of Nuclear Reactor Regulation. Director DEYDUNO, R. Director's Office, Office of Inspection and Enforcement DAVIS. J. Diffice of Nuclear Haterial Bafety & Bafeguards, Director Spp. 22493 337 24% Fiche'50-000.83/12/16, 8403070014
- --U403020029 Discusses delegation & masignment to Region IV of certain licensing functions for facility DIRCKS.W J Office of the Executive Director for Operations DENTON.H R Office of Nuclear Reactor Regulation. Director 92/11/29 COLLING.J T Region 4, Office of Director 928 22493 289 24X Fichs 50-000,83/12/16.8403020014
- --B403020032 Bunmary of 820701 initial planning meeting w/NRR.OELD.EDD.
 Region IV & OPC of Administration relicensing transfer from
 NRR to Region IV Details encl Next meeting scheduled for
 B20915
 HEBSHAN, R Assistant Director for Safety Assessment B2/09/03.
 IPPOLITO, T A Assistant Director for Safety Assessment 27pp
 22492 267 24X Fiche 50-000.B3/12/16.8403020014

- --8403020041 Informs of forthcoming FR publication of encl amend to Commission rules in 10CFR50 re implementation of facility regionalization program Amend issued as final rule effective on 821201 W/o encl
 DENTON, HR Office of Nuclear Reactor Regulation, Director 83/12/16 UDALL, MK House of Rep., Interior & Insular Affairs ip 22473 316 24X Fliche 50-000, 83/12/16, 8403020014
- --8403020045 Informs of forthcoming FR publication of encl amend to Commission rules in 10CFR50 re implementation of facility regionalization program Amend issued as final rule effective on 821201 Wo encl
 DENTON.H R Office of Nuclear Reactor Regulation, Director 83/12/16 MOFFETT.Y House of Rep. Government Operations 1, 22493 317 24% Fiche 50-000,83/12/16,8403020014
- --8403020044 Informs of forthcoming FR publication of encl amend to Commission rules in 100FR50 re implementation of facility regionalization program Amend issued as final rule effective on 821201 Wo encl
 DENTON.H R Office of Nuclear Reactor Regulation, Director B3/12/16 OTTINGER.R.L House of Rep., Energy & Commerce 1p 22493:318 24X Fiche 50-000,83/12/16,8403020014
- --B40302004B Informs of forthcoming FR publication of encl amend to Commission rules in 10CFR50 re implementation of facility regionalization program Amend issued as final rule effective on 621201 My o encl
 DENTON.H.R. Office of Nuclear Reactor Regulation, Director B3/12/16 SIMPEON.A Benate, Environment & Public Works ip 22493 319 24X Fiche 50-000,83/12/16,8403020014
- 8401250468 Forwards engineering evaluation rept, "Temporary Loss of All AC Power due to Relay Failures in Diesel Generator Load Bhedding Circuitry "Practice of running emergency power sources in parallel w/offsite power sys may be prevalent HELTEMES, C. J. Director's Offsice 84/01/06 DENTON.H R. Offsice of Nuclear Reactor Regulation, Director 3pp 22437 349 24X Fiche: 50-267,84/02/21,8402270004
- --8401250456 Revisus 831215 schedule for NRC 840125 drill in preparation for 840306-08 federal field exercise Executive team mambers should be available for entire time DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 84/01/10 PALLADING.N Commissioners 2pp 67130 048 24X Fiche 50-267,84/02/21,8402290004
- --B401250476 Forwards Engineering Evaluation E401. "Temporary Loss of All ac Power Due to Relay Failures in Dissel Generator Load Shedding Circuitry " Failures occurred while generator 1B operated in parallel w/plant distribution sys CHIRAMAL.M Director's Office B4/01/04 BEYFRIT, K V Reactor Uperations Analysis Branch ip 22437 350 24X Fichs: 50-267,84/02/21.8402270004
- --B401250510 "Temporary Loss of All ac Power due to Relay Failures in Diesel Generator Load Bhedding Circuitry (LER 83-8) "
 CHIRAMAL,M Director's Office 84/01/04 7pp 22497.351 24X Fichs.30-267,84/02/21.8402270004
- 8403010101 Responds to request for add1 info re proposed amend to Limiting Condition for Operation 4 1 9 re average core temp during shutdown HAREMBOURG, D. W. Public Service Co. of Colorado. 84/02/24, JOHNSON, E. H. Region 4, Diffice of Director. 3pp. 22436 038 24X Ficher 50-267,84/02/24,8403010101
- 8403130177 Advises that util will be utilizing respiratory protective equipment under provisions of 10CFR20 103, effective 840401, per 840228 telcon BORBT, F. J. Public Service Co. of Colorado 84/02/28 COLLINS, J. T. Region 4, Office of Director, ip 22615 305 24X Fiche 50-267, 84/02/28, 8403130177
- 8403160303 Provides radiological ET8 clarifications & changes based on Item 267/8403-01 in IE Insp Rept 50-267/84-03
 WAREMBOURD, D. M. Public Bervice Co of Colorado 84/02/29
 COLLING, J. T. Region 4, Office of Director 2pp. 22660 347 24X
 Fiche. 50-267,84/02/29,8403160303
- 8403130231 Requests FR publication of Amend 40 to License DPR-34, revising design feature Tech Specs to describe type of fuel elements to be utilized in upcoming & future reloads JOHNSON, E H Region 4, Office of Director 84/03/02 MILLER, J R Operating Reactors Branch 3 2pp 22617 268 24X Fiche: 50-267, 84/03/02, 8403130231
- 8403130231 Forwards Amend 40 to License DPR-34 & safety evaluation Amend revises Tech Spec design features to indicate approval for Type H-451 & H-327 graphite in future reload fuel elsments
 HAGNER, F C Region 4, Office of Director 84/03/02 LEE, O R Public Service Co. of Colorado ip 22617 237 24X Fiche 30-267, 84/03/02, 8403130251

- ---8403130257 Amend 40 to License DPR-34, revising Tech Spec design features to indicate approval for Type H-451 & H-327 graphite in future reload fuel elements
 JOHNSON,E H Region 4. Office of Director 84/03/02 5pp
 22617 240 24X Fiche 50-267,84/03/02,8403130251
- ---8403130263 Safety evaluation supporting Amend 40 to License DFR-34 * Region 4, Office of Director 84/03/02 10pp 22617 245 24X Fiche 50-267,84/03/02,8403130251
- 8403120081 Forwards safety evaluation re Sections 5 1 1 & 5 3 of NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants " Guidelines satisfied Phase I acceptable JUHNBON,E H Region 4, Office of Director 84/03/06 LEE,O R Public Service Co of Colorado 2pp 22590 168 24X Fiche 50-267,84/03/06,8403120081
- --8403120086 Safety evaluation re NUREO-0612, "Control of Heavy Loads," Phase i Guidelines satisfied + NRC - No Detailed Affiliation Given 84/03/06 2pp 22390 170 24X Fiche 50-267.84/03/06.8403120081
- --8402280725 "Control of Heavy Loads at Nuclear Power Plants:Fort St Vrain Nuclear Generating Station:Phase I." technical evaluation rept STICKLEY.T H EGG. Inc FIN A-6457 EGG-HS-6274 RO3 84/01/3) NRC - No Detailed Affiliation Given 27pp 22570 172 24X Fiche 30-227,84/03/06.8403120081
- 8403i70350 Forwards application for amend to License DPR-34, ciarifying Tech Bpec changes by revising reporting requirements of Bections 50 72 & 50 73 No license amend fee required per Generic Ltr 83-43

 LEE, O R Public Bervice Co of Colorado 84/03/06 COLLINS, J T Region 4. Office of Director 2pp 226/3 295 24X Fiche 50-267.84/03/04.8403190350
- --B403190357 Application to amend License DPR-34, clarifying Tech Spec changes by revising reporting requirements of Sections 50 72 & 50 73 LEE, D & Public Service Co of Colorado 84/03/06 2pp 22673 297 24X Fiche 50-267,84/03/06,8403190350
- ~~B403i90359 Proposed Tech Specs revising reporting requirements of Sections 50 72 & 50 73 * Public Service Co of Colorado 84/03/06 10pp 22673 299 24% Fichs 50-267,84/03/06,8803190350
- 8403130234 Disagrees w/util 840209 itr concluding that no Tech Spec revs required to finalize NUREO-0737 items presented in Generic Ltrs 83-36 & 83-37 Changes needed for conformance to NUREO-0737 encl Commitments requested within 20 days JOHNSON,E H Region 4, Office of Director 84/03/08 LEE, D R Public Service Co of Colorado 3pp 22617 265 24X Fiche 50-267,84/03/08,8403130234
- 84031900B3 Forwards Amend 41 to License DPR-34 & safety evaluation Amend allows receipt, possession & use of radioactive instrument calibr sources containing up to 300 Cl Cs-137 HAGNER, P C Region 4, Office of Director 84/03/08 LEE, O R Public Bervice Co of Colorado 3pp 22674 213 24X Fiche 50-267,84/03/08,8403190083
- --8403190087 Amend 41 to License DPR-34, allowing receipt, possession & use of radioactive instrument calibr sources containing up to 300 Gi Cs-137 & 200 uCi Kr-85
 JOHNSON, E H Region 4, Office of Director 84/03/08 2pp 22674 216 24X Fichs 50-267,84/03/08,8403190083
- --8403190093 Safety evaluation supporting Amend 41 to License DPR-34 * Office of Nuclear Reactor Regulation, Director 84/03/08 2pp 22674 218 24% Fiche 50-267,84/03/08,8403190083
- 8403190320 Requests FR publication of notice of issuance of Amend 4i to License DPR-34 Amend allows possession & use of larger sized radioactive Cs-137 & Kr-85 instrumentation calibr sources
 JOHNSON, E H Region 4, Office of Director 84/03/08 MILLER, J R Operating Reactors Branch 3 2pp 22673 278 24X Fichs 50-267,84/03/08,8403190220
- 8403i60229 Forwards Rev A to Work Spec WS-93-0004. "Reevaluation of Plant Protection Sys Setpoints." as result of 831027 agreement to revise previous application for amend to Tech Specs MAREMSOURG, D Public Service Co of Colorado 84/03/09, COLLINS.J T Region 4, Office of Director 2pp 22661:045 24X Fichs 50-267.84/03/09,6403160229

- --B403160223 Rev A to Work Spec MS-93-0004, "Recvaluation of Plant Protection Sys Setpoints" FLOWERIM Public Service Co of Colorado B4/02/17 17pp 22661 047 24x Fichs 50-267.84/03/09.B403160229
- 8403270189 Forwards application to amend License DPR-34, changing Tech Specs re limiting conditions for instrumentation & control sys.control room temp & area radiation monitoring LEE.DR Public Service Co of Colorado 84/03/14 COLLINS, J T Region 4, Office of Director 4pp 22771 iO3 24X Fiche 50-267,84/03/14,8403270189
- --840327019i Application for amend to License DPR-34. revising Tech Speck re limiting conditions for operation of instrumentation & control sys.control room temp & area radiation monitoring * Public Service Co of Colorado 84/03/14 3pp 22771 107 24X Fiche 50-267.84/03/14.8403270189
- ---8403270194 Proposed Tech Specs re limiting conditions for operation of instrumentation & control systematical room temp & area radiation monitoring

 > Public Service Co of Colorado 84/03/14 14pp 22771 110 24X Fiche 50-267.84/03/14.8403270189
- 0 Inspection reports, IE Bulletins & correspondence
- 8403130122 Forwards IE Insp Rept 50-267/83-28 on 831128-1202 & notice of deviation
 JDHNSON,E H Region 4. Office of Director 84/01/25 LEE.O R
 Public Service Co of Colorado 2pp 22602 198 24X
 Fiche 50-267.84/01/25.8403130122
- ~-8403i30135 Notice of deviation from insp on B31128-i202 * Region 4, Office of Director 84/01/25 2pp 22602 200 24X Fiche 50-267,84/01/25,8403130122
- --8403130148 IE lnap Rept 50-267/83-28 on 831128-1202 Deviation noted Inadequate designation of person responsible for low level waste transportation & lack of suitable plan for training & retraining re waste transportation CHANEY.H D , MURRAY.B , HUNNICUTT.D M Region 4, Dffice of Director 84/01/18 10pp 22602 202 24X Fiche 50-267.84/01/25.8403130122
- 8403260161 Forwards IE Insp Rept 50-267/83-32 on 831205-09 No violations or deviations identified JOHNSON, E R Region 4. Office of Director 84/02/03 LEE, D R Public Service Co of Colorado 4pp 22750 345 24X Fiche 50-267,84/02/03.8403260161
- --8403260167 IE Insp Rept 50-267/83-32 on 831205-09 No violations or deviations identified Major areas inspected security sysaudit, physical barriers-protected areas & vital areas testing & maint & alarm stations Details withheld (ref 10CFR73 21) CALDMELL.R A . KELLY, J A F . HUNNICUTT, D M Region 4. Office of Director 84/02/01 2pp 22750 347 24X Fiche 50-267,84/02/03. 3403260161
- 8403260100 Forwards IE Insp Rept 30-267/84-03 on 840116-20 No violations or deviations noted
 JOHNSON.E H Region 4. Office of Director 84/02/14 LEE.O R
 Public Service Co of Calorado 2pp 22758 251 24X
 Fiche 50-267.84/02/14.8403260100
- --8403260107 IE Insp Rept 50-267/84-03 on 840116-20 No violations or deviations noted Major areas inspected radwaste program, including organization & mgt controls, training & qualifications & solid radwaste processing WILBORN, L. MURRAY, B., HUNNICUTT, D.M. Region 4, Office of Director 84/02/13 10pp 22758 253 24X Fiche 50-267,84/02/14,8403260100
- B403010107 Submits schedule & program description for Segment 3 fuel element insps, per 840210 telcon Program will be performed upon request Euel element cracks have no effect on fuel particle integrity
 WAREMBOURG.O W Public Service Co of Colorado 84/02/13
 COLLINS.J T Region 4, Office of Director App 22436 037 24X
 Fiche 50-267.84/02/15.8403010107
- 8403010304 Responds to IE Sulletin 79~14 re review of selemic piping redocumentation status Util will finalize design work in upcoming months & remaining mod will be completed prior to startup after fourth refueling outage UREY, H L Public Service Co of Colorado 84/02/17 COLLINS, J T Region 4, Office of Director 2pp 22432 122 24X Fiche 50-267.84/02/17.8403010304

- 8403050112 Responds to NRC 840125 itr re deviations noted in IE Insp Rept 50-267/83-28 Corrective actions Radiation Protection Administrative Procedure RFAP-4 will be revised to include administrative control section MAREMBOURG, D.W. Public Service Co. of Colorado. 84/02/22 COLLINS.J T. Region 4, Office of Director. 3pp. 22487 303—24X Fiche 50-267,84/02/22,8403050112
- 8403050153 Ack receipt of 831128 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-267/83-26 No add1 response required to NRNGA certificate as error not germane to corrective action
 JOHNSON.E H Region 4. Diffice of Director 84/02/23 LEE.O R
 Public Service Co of Colorado ip 22485 060 24X
 Fiche 50-267.84/02/23.8403050153
- 8401i90072 IE info Natice 84-13. "Potential Deficiency in Mator Operated Valve Control Circuits & Annunciation " Svc list encl JCRDAN.& L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York. Inc. 118pp 22909 239 24% Fiche: 50-000.84/02/28.8401170072
- B403160303 Provides radiological ETS clarifications & changes based on Item 267/8403-01 in IE Insp Rept 50-267/84-03 HAREMBOURG, D. W. Public Service Co. of Colorado B4/02/29 COLLINS, J. T. Region 4, Office of Director 2pp 22660 347 24X Fiche 50-267,84/02/29,8403160303
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl ORACE.J N Division of GA: Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000.84/03/02.8402090007
- B402090008 IE Info Notice B4~i6, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDÁN: E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/02 Consolidated Edison Co. of New York, Inc 122pp 22553 098 24X Fiche 50~000, 84/03/02, 8402090008
- B402090009 IE Info Notice 84~15, "Reporting of Radiological Releases"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000, B4/03/02, B402070009
- 8402090D11 IE lnfo Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc Iist encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc i17pp 22553 336 24X Fiche 50-000,84/03/05,840209001i
- 8403260205 Forwards IE Insp Rept 50-267/84-04 on 840206-10 & notice of violation JOHNSON.E H. Region 4. Office of Director 84/03/05 LEC.O R Public Service Co. of Colorado. 2pp. 22756 210 24X Fiche 50-267.84/03/05.8403260205
- --8403260209 Notice of violation from insp on 840206-i0 * Region 4, Dffice of Director 84/03/05 ip 22756 212 24X Fiche 30-267,84/03/05,8403260205
- --84032602ti IE Insp Rept 50-267/84-04 on 840206-10 Violation noted maint worker proceeded toward work area w/anticontamination clothing surveyed indicating 400 counts per minute & clothes not stored for decay it rewashing WILBORN.L . MURRAY.B . HUNNICUTT.D M Region 4. Office of Director 84/03/05 10pp 22756 213 24X Fiche 50-267,84/03/05,8403260205
- B403160326 Documents B40305 talcon which advised NRC that photographs committed to in fuel element insp program underexposed Preparations to remove all Region 18 fuel elements from fuel storage usil to permit photographs of elements begun MAREMBOURO, D SI Public Service Co of Colorado 84/03/06 COLLINS, J T Region 4, Office of Director 2pp 22660,039, 24X Fiche 30-267,84/03/06.8403160326
- 8402070024 IE Info Notice 84-07, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JDRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc 118pp 22635 047. 24X Ficha 50-000,84/03/07,8402070024
- 8402070028 IE Info Notice 84-i8, "Btress Corrosion Cracking in PWR Bys " Svc Iist encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Int 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028

- 8403260174 Forwards IE Insp Rept 50-267/84-07 on 840213-16 No violations or deviations identified JOHNSON, E.H. Region 4, Office of Director 84/03/08 LEE, O.R. Public Service Co. of Colorado 2pp 22757 343 24X Fiche 50-267
- --B403260177 IE Insp Rept 50-267/84-07 on 840213-16 No violations or deviations identified Major areas inspected QA procedures for installation of safety-related electrical equipment & qualification of QC electrical personnel BESS, J E , JAUDON, J P , HUNNICUTT, D H Region 4, Office of Director B4/03/08 7pp 22757 345 24X Fiche 50-267, 84/03/08, 8403260174
- B402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety 8ys " 8vc list encl DEYDUND, R C Director's Office. Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list and JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- B402090044 IE Info Notice B4-20, "Svc Life of Relays in Bafety-Related Bys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp. 22733 001 24X Fiche 50-000.84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403060309 "Semiannual Effluent Rept. Jul-Dec 1983 " W/840202 itr BCRST.F J Public Service Co of Colonado 83/12/31 COLLINS, J Region 4. Office of Director 17pp 22515 338 24X Fiche 50-267, 83/12/31,8403060309
- 8403130376 "Environ Radiation Surveillance Program Summary Rept for Third & Fourth Quarters 1983 " W/840227 ltr JOHNSON, J E Colorado State Univ. Ft Collins, CO BREY, H L Public Service Co of Colorado 83/12/31 COLLINS, J T Region 4, Office of Director 143pp 22604 207 24X Fiche 50-267, 83/12/31, 8403130394.
- 84030i0liB "Annual Occupational Exposure Rapt 1783 " BORBT.F J Public Service Co of Colorado 84/02/21 COLLING, J T Region 4. Defice of Director 1p 22436 034 24X Fichs.50-247,84/02/21,8403010118
- 8403190344 Monthly operating rept for Feb 1984 W/840313 ltr FULLER, C . WAREMBOURG, D Public Service Co of Colorado 84/02/29 9pp 22673 156 24% Fiche 50-267,84/02/29,8403190344
- B. Reportable occurrences, LERs & related correspondence
- B403010134 Forwards LERs 80~030/03X-2 & B1-068/03X-1 MAREMBURGO, D Public Service Co of Colorado 84/02/16, COLLINS, J T Region 4, Office of Director ip 22435 347 24X Fiche 30~267,84/02/16,8403010134
- ---8403010135 LER 80-030/03X-2 on 800604, steam generator penetration leakage appeared to be greater than 400 lb per day Caused by purified helium leakage internal to loop 2 penetration & occurring between interspace & cold reheat steam plying NOVACHEK,F., FRYE,D L., MCBRIDE,L M Public Service Co. of Coloredo 84/02/16 7pp 22435 350 24X Fiche 50-267,84/02/16,8403010134
- --B403010167 LER B1-068/03X-i on B11024, loop 2 steam generator interspace leakage exceeded limits Caused by helium leakage internal to penetration interspace & occurring between interspace & cold reheat steam piping NOVACHEK, F., FRYE, D.L., MCBRIDE, L.M. Public Service Co. of Coloredo B4/02/16 4pp 22435 357 24X Fiche 50-267, 84/02/16, 8403010134.
- 8403010116 LER 84-002-00 on 840123, during surveillance test, one of three bearing water pressure differential suitches found inoperable Cause unknown Switch replaced & calibr to instrument operating requirements W/840222 ltr.
 NOVACHEK, F. WAREMBOURO, D. Public Service Co. of Colorado 84/02/22 COLINS, J. T. Region 4. Office of Director Opp 22436 028 24X Fiche 50-267,84/02/22,8403010116

- 8403120071 Requests initiation of new task interface agreement for review of licensee 840120 submittal re steam generator tube leak Acceptable steam generator tube surveillance program should be established DENISE.R P Division of Resident, Reactor Project & Engineering Programs 84/03/06 EIGENNUT, D 0 Division of Licensing 2pp 22589 302 24X Fiche 50-267.84/03/06.8403120071
- B403220063 LER B4-003-00 on B40212, automatic plant protective sys reactor scram initiated by one of two logic trips involving nuclear startup channel 11 Caused by insertion of fuel block containing neutron startup source W/B40313 ltr NOVACHEK, F. MAREMBOURG, D. Public Service Co of Colorado 84/03/13 COLLING, J. T. Region 4. Office at Director 7pp 22717 173 24X Fiche 50-267,84/03/13,8403220063
- DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8403090254 Public version of revised crisis mgt plan implementing procedures; including Procedures 5 3 4 re scheduling/planning support group, 5 3 6 re radialogical support group & 5 3 7 re technical support group W/831107 ltr & Mt Felton memo TUCKER, H B Duke Power Co 83/10/31 DENTON, H R Office of Nuclear Reaculation, Director 271pp 22575 055 24% Fiche 50-000.83/10/31,8403090254
- 8403040225 Rev il to crisis mgt plan W/840224 ltr & public info pamphlet VAVOHN.T E . TUCKER.H B Duke Power Co B4/02/02 DENTON.H R Office of Nuclear Reactor Regulation. Director 66pp 22516 185 24x Fichs 50-000.84/02/02.8403060225
- 8403160134 Forwards 1E Insp Repts 50-269/84-04.50-270/84-04 & 50-287/84-04 on 840201-02 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/16 TUCKER.H B Duke Power Co 2pp 22655 336 24X Fiche 50-269, 84/02/16.8403160134
- --B403160141 IE Insp Repts 50-269/84-04, 50-270/84-04 & 50-287/84-04 on B40201-02 No violations identified Major areas inspected emergency preparedness areas of protective action decisionmaking CLINE, W E Region 2, Office of Director 84/02/15 4pp 22655 338 24X Fiche 50-269, 84/02/16, 8403160134
- B403090222 Forwards Rev 3 to training & qualification plan Rev withheld (ref 10CFR73 21)
 TUCKER, H B Duke Power Co B4/02/29 O'REILLY, J P Region 2,
 Defice of Director 1p 22575 149 24X Fiche 50-269,84/02/29,
- B403160278 Extends invitation to attend 840316 workshop to discuss IOCFR30. App R requirements & results of recent insp to help resolve misunderstanding associated w/requirements LEWIS.R C Division of Project & Resident Programs 84/03/02 TUCKER.H B Duke Power Co 1p 22660 274 24% Fiche 30-000.84/03/02.8403160278
- B403160245 Forwards summary of 840228 meeting w/util in Atlanta, GA re iOCFR50 4B & IOCFR50, App R fire protection application Attendance list also encl LEWIS:R C Division of Project & Resident Programs 84/03/07 TUCKER:H B Duke Power Co 3pp 22640 312 24X Fiche 50-269, 84/03/07, 8403160245
- 8403120119 Advises that 840116 Rev 11 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable LEWIS,R C Division of Project & Resident Programs 84/03/08 TUCKER,H B Duke Power Co 2pp 27589 219 24X Fiche 50-269,84/03/08,8403120119
- 8403390069 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/83-36.
 50-270/83-37 & 50-287/83-36 Implementation of corrective actions will be examined during future insp DANCE.H C Division of Project & Resident Programs 84/03/20 TUCKER, H B Duke Power Co ip 22807 011 24X Fiche 50-269, 84/03/20, 8403290069
- --8403270108 IE Insp Repts 50-269/83-36.50-270/83-37 & 50-287/83-36 on 83111-1210 Violation nated failure to follow Maint Procedure 270/83-37-01 re quality performed on Reactor Coolant Pump 202 REYANT, Region 2, Office of Director 84/01/09 10pp 22807 017 24X Fiche 50-269.84/03/20.8403270069

- 8403270209 Forwards Rev 4 to util response to NUREG-0737, Suppl 1. including control room review implementation priority
- P Operating license stage documents & correspondence
- 8403060292 Submits response to NRC request for schedular info re SER of 103060272 Submits response to NRC request for schedular info re SER of proposed inadequate core cooling instrumentation Final design description will be submitted by B50701
 TUCKER, H B Duke Power Co 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director STDL2, J F Operating Reactors Branch 4 2pp 22518 124 24X Fiche 50-249,84/02/28,8403060292
- 8403150328 Forwards Amends 127, 127 & 124 to Licenses DPR-38, DPR-47 & 103150328 Forwards Amends 127, 127 & 124 to Licenses DRR-3B DRR-4: DRR-5B respectively & safety evaluation Amends revise Tech Specs to implement limiting conditions for operation in event one startup transformer out of svc STOLZ. J F Operating Reactors Branch 4 84/03/02 YUCKER. H B Duke Power Co 2pp 22649 274 24X Fiche 50-269, 84/03/02. 8403150328
- --8403150335 Amends 127.127 & 124 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs to implement limiting conditions for operation in event one startup transformer BTOLZ, J.F. Operating Reactors Branch 4 84/03/ 22649 276 24X Fiche 50-269,84/03/02,8403150328 84/03/02 2104
- --8403150344 Safety evaluation supporting Amends 127,127 & 124 to Licenses DPR-48, DPR-47 & DPR-55, respectively * Dffice of Nuclear Reactor Regulation, Director 84/03/02 22649 297 24X Fiche 30-269,84/03/02,8403150328 84/03/02 2pp
- Q Inspection reports. IF Bulletins & correspondence
- 8403070364 Forwards IE Insp Repts 50-269/83-11,50-270/83-11 & 50-287/83-11 on 830317-28 Enforcement action addressed in NRC 830602 ltr LEMIS.R C Division of Project & Resident Programs 83/06/02 TUCKER.H B Duke Power Co 2pp 22546 025 24X Fiche 30-269,83/06/02.84603070264
- --8403070369 IE insp Repts 50-269/83-11.50-270/83-11 & 50-287/83-11 on B30317-28 Violations noted ioss of containment integrity on B30317 & 21 & failure to meet requirements of confirmatory order dtd 810710 re independent verification BRYANT.J. FALCONER, D. Region 2. Office of Director IONATONIS, A Division of Project & Resident Programs 83/06/02 10pp 22546 027 24X Fiche 50-269.83/06/02.8403070364
- 8403160134 Forwards IE lnsp Repts 50-269/84-04.50-270/84-04 & 50-287/84-04 on 840201-02 No violations or deviations JO-20/704-00 60 60201-02 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/16 TUCKER.H B Duke Power Co 2pp 22655 336 24X Fithe 50-269.84/02/16.8403160134
- ~-8403160141 IE Insp Repts 50-269/84-04.50-270/84-04 & 50-287/84-04 on 840201-02 No violations identified Major areas inspected emergency preparedness areas of protective action emergency preparations description decisionmaking decisionmaking CLINE.W E Region 2, Office of Director JENKIN of Emergency Preparedness & Materials Safety 6/22655 338 24X Fiche 50-269,84/02/16,8403160134 KINS, C R Division 84/02/15 4pp JENKINS, O R
- B40301030B Forwards addi info re B30B15 request for relief from inservice insp requirements (Hydrostatic) of Section XI of ABME Boiler & Pressure Vessel Code Valve 2LPBW-133 cannot be closed due to sheared along pins TUCKER, H B Dute Power Co B4/02/23 DENTON, H R Office of Nuclear Reactor Regulation. Director STOLZ, J F Operating Reactors Branch 4 2pp 22432 102 24X Fiche 50-269,84/02/23,840301030B
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Syc list Anc.]
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/02/28 Consolidated Edison Co of New
 York, Inc. 115pp 22707 237 24X Fiche 50-000.84/02/28,8401170072
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of OA. Safeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.B4/03/02,8402090007

- 8402070008 lE Info Notice 84-16. "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000-84/03/02.8402070008
- 8402070007 IE Info Notice 84-15. "Reporting of Radiological Releases
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Relow Nil Ductility Temp " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09. Rev i, "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corresion Cracking in PWR Sys "Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of QE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403270069 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-249/83-34, 50-270/83-37 & 50-287/83-36 implementation of corrective actions will be examined during future insp DANCE, H C Division of Project & Resident Programs 84/03/20 TUCKER, H B Duke Power Co 1p 22807 0ii 24X Fiche 50-269,84/03/20,8403270069
- --8403290082 Responds to NRC 840109 itr re violations noted in 1E Insp. Repts 50-269/83-36,50-270/83-37 & 50-287/83-36 Corrective actions Unit 2 staging coil locations corrected & seal packages on Reactor Coolant Pump 202 replaced TUCKER.H D Duke Power Co. 84/02/08 O'REILLY, J. P. Region 2, Office of Director 2pp 22807.012 24X Fiche 50-269,84/03/20,8407390nAg 8403270069
- --B403270090 Forwards IE Insp Repts 50-269/83-36.50-270/83-37 & 30-287/83-36 on 83i111-i210 & notice of violation DANCE: H C Division of Project & Resident Programs 84/01/TUCKER.H B Duke Power Co 2p 22807 014 24X Fiche 50-269.84/03/20.8403290069 84/01/09
- --8403290095 Notice of violation from insp on 831111-1210 * Ragion 2, Office of Director 84/01/09 ip 22807 016 24X Ficha 50-269,84/03/20,8403290069
- -8403290108 IE Inap Repts 50-269/83-36,50-270/83-37 & 50-287/83-36 on 831111-1210 Violation noted, failure to foilow Maint Procedure 270/83-37-01 re quality performed on Reactor B4/01/09
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities " 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21. Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl. JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402070044
- R Periodic operating reports & related correspondence
- 8403200010 Monthly operating repts for Feb 1984 W/840315 ltr. REAVIS. J A . TUCKER. H B. Duke Power Co 84/02/29 17pp. 22685 185 24X Fiche 50-269,84/02/29,8403200010

V Operator Examinations

8403080237 Forwards operator licensing exam schedule through CYBB, in response to Generic Ltr 83-40
TUCKER, H B Duke Power Co 84/02/27 EISENHUT, D G Division of Licensing 2pp 22561 023 24X Fiche 50-269, 84/02/29, 8403080239

DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

- 8403090254 Public version of revised crisis mgt plan implementing procedures, including Procedures 5 3 4 re scheduling/planning support group 5 3 6 re redicitogical support group & 5 3 7 re technical support group W/831107 ltr & JM Felton memo TUCKER, H B Duke Power Co 83/10/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 271pp 2295 055 24% Fiche 50-000,83/10/31.8403090254
- 8403060225 Rev 11 to crisis mgt plan W/840224 ltr & public info pamphlet VAUQHN.T E. TUCKER.H B Duke Power Co 84/02/02 DENTON.H R Dfffice of Nuclear Reactor Regulation. Director 46pp 22516 189 24X Fiche 50-000.84/02/02.8403060225
- 8403160134 Forwards IE Insp Repts 50-269/84-04.50-270/84-04 & 50-287/84-04 on 840201-02 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/16 TUCKER.H B Duke Power Co 2pp 22655
- --8403160141 1E Insp Repts 50-269/84-04.50-270/84-04 & 50-287/84-04 on 840201-02 Np violations identified Major areas inspected emergency preparedness areas of protective action decisionmaking CLINE, W E Region 2, Office of Director 84/02/15 4pp 22655 338 24X Fiche 50-269.84/02/16.8403160134
- 8403090222 Forwards Rev 3 to training & qualification plan Rev withheld (ref 10CFR73 21) TUCKER. H B Duke Power Co 84/02/29 O'REILLY, J.P. Region 2, Dffice of Director 1p 22575 149 24x Fiche 50-269, 84/02/29, 8403090222
- B403160278 Extends invitation to attend 840316 workshop to discuss 10CFR50. App R requirements & results of recent insp to help resolve misunderstanding associated w/requirements LEWIG.R C Division of Project & Resident Programs 84/03/02 TUCKER.H B Duke Power Co ip 22660 274 24X Fiche 50-000.84/03/02.8403160278
- 8403160245 Forwards summary of 840228 meeting w/util in Atlanta, GA re 10CFR50 48 & 10CFR50. App R fire protection application Attendance list also encl LEWIS.R C Division of Project & Resident Programs 84/03/07 TUCKER.H B Duke Power Co 3pp 22660 312 24X Fiche 50-269,84/03/07,8403160245
- 8403120119 Advises that 840116 Rev 11 to physical security plan consistent w/provisions of iOCFR50 54(p) & acceptable LEWIS.R C Division of Project & Resident Programs 84/03/08 TUCKER.H B Duke Power Co 2pp. 22589 219 24X Fiche 50-269,84/03/08.8403i20119
- 8403290069 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-269/83-36. 50-270/83-37 & 30-287/83-36 Implementation of corrective actions will be examined during future insp DANCE:H C Division of Project & Resident Programs 84/03/20 TUCKER,H B Duke Power Co ip 22807 Oli 24X Fiche 50-269,84/03/20,8403290069
- --8403270108 IE Insp Repts 50-269/83-36:50-270/83-37 & 50-287/83-36 on B3111-1210 Violation noted failure to follow Maint Procedure 270/83-37-01 re quality performed on Reactor Coolant Pump 282.

 BYYANT, J Region 2. Office of Director 84/01/09 10pp 22807 017 24X Fiche 50-269,84/03/20,8403270069
- B403270209 Forwards Rev 4 to util response to NUREG-0737, Suppl i, including control room review implementation priority schedule TUCKER. H B Duke Power Co 84/03/23 DENTON, H R Defice of Nuclear Reactor Regulation, Director STGLZ. J F Operating Reactors Branch 4 9pp 22772 OBB 24X Fiche 50-269, 84/03/23, 8403270209

- P Operating license stage documents & correspondence
- 8403040292 Submits response to NRC request for schedular info re SER of proposed inadequate core cooling instrumentation Final design description will be submitted by 850701
 TUCKER, H B Duke Power Co 84/02/28 DENTON: H R Office of Nuclear Reactor Regulation. Director STOLZ, J F Operating Reactors Branch 4 2pp 22518 124 24% Fiche 50-269,84/02/28,8403040292
- 8403130328 Forwards Amends 127,127 & 124 to Licenses DPR-38,DPR-47 & DPR-55,respectively & safety evaluation Amends revise Tech Specs to implement limiting conditions for operation in event one startup transformer out of svc STOLZ.J F Operating Reactors Branch 4 84/03/02 TUCKER.H B Dute Power Co 2pp 22649 274 24X Fiche 50-269.84/03/02.8403150328
- --8403150335 Amends 127,127 & 124 to Licenses DPR-3B, DPR-47 & DPR-55, respectively, revising Tech Specs to implement limiting conditions for operation in event one startup transformer out of svc STOLZ, JF Operating Reactors Branch 4 84/03/02 2ipp 22649 276 24X Fiche 50~269,84/03/02.8403150328
- --8403150344 Safety evaluation supporting Amends 127,127 & 124 to Licenses DPR-3B, DPR-47 & DPR-55, respectively * Office of Nuclear Reactor Regulation, Director 84/03/02 2pp 22647 297 24X Fiche 50-269,84/03/02,8403150328
- 8403290314 "Oconee 2 Cycle 7 Startup Testing Rept " W/840326 ltr ELDER, M L , FARSONS, C H Duke Power Co 84/03/26 DENTON, H, R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 23pp 22802 070 24X Fiche, 50-270, 84/03/26, 8403290314
- Q Inspection reports, IE Bulletins & correspondence
- 8403070364 Forwards IE Insp Repts 50-267/83-11.50-270/83-11 & 50-287/83-11 on 830317-28 Enforcement action addressed in NRC 830602 ltr LEWIS.R C Division of Project & Resident Programs 83/06/0. TUCKER.H B Duke Power Co 2pp 22546 025 24X Fiche 50-269.83/06/02.8403070364
- --8403070369 IE Insp Repts 50-269/B3-i1,50-270/B3-i1 & 50-287/B3-i1 on B30317-28 Violations noted loss of containment integrity on B30317 & 21 & failure to meet requirements of confirmatory order dtd B10710 re independent verification BRYANT, J. FALCONER, D. Region 2, Office of Director IONATONIS, A Division of Project & Resident Programs B3/06/02 iOpp 22546 027 24X Fiche 50-269,83/06/02.8403070364
- 8403i60i34 Forwards IE Insp Repts 30-269/84-04, 50-270/84-04 & 50-267/84-04 on 84020i-02 No violations or deviations identified DANCE, H C Division of Project & Resident Programs 84/02/16 TUCKER, H B Duke Power Co 2pp 22655 336 24X Fichs 50-269, 84/02/16, 8403160134
- --8403160141 IE Insp Repts 50-269/84-04.50-270/84-04 & 50-287/84-04 on 840201-02 No violations identified Major areas inspected emergency preparedness areas of protective action decisionmaking GLINE,W E Region 2, Office of Director JENKINB,O R Division of Emergency Preparedness & Materials Safety 84/02/15 App 22655 338 24% Fiche 50-269,84/02/16,8403160134
- B40301030B Forwards addl info re B30B15 request for relief from inservice insp requirements (Hydrostatic) of Section XI of ABME B011er & Pressure Vessel Code Valve 2LPBM-133 cannot be closed due to sheared hinge pins TUCKER.H B Duke Power Co B4/02/23 DENTON.H A Office of Nuclear Reactor Regulation. Director STGL7.J F Operating Reactors Branch 4 2pp 22432 102 24X Fiche 50-267.84/02/23,8403010308
- 8401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Gircuits & Annunciation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22709 237 24X Fiche 50-000.84/02/28,8401170072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOY & NRC " 8vc list encl GRACE. J N Division of OA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Go of New York. Inc i30pp 22552 329 24X Fiche 50-000.84/03/02.8402090007

- 840207000B IE Info Notice B4-16. "Failure of Automatic Sprinkler Sys
 - Valves to Operate " Syr list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 2253 098 24X Fithe 50-000.84/03/02.8402090006
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 - SVC list encl JORDAN E (D: Response (Post Division of Emergency Preparedness & Engineering to the State of S
- 8402090011 IE Info Notice 84-17. "Problems H/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svr list encl URBAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/05 Consolidated Edison Co of Nyork, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,840207003 22553 336 24X Fiche 50~000, 84/03/05, 8402070011
- 8402070024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Evolist enci JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24% Ficha 50-000,84/03/07,8402070024 110pp
- 8402090028 IE Impo Notice 84-18, "Stress Corrosion Cracking in PWR 102070022 IE INTO NOVEL S. S. Sys " Svc list encl JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of 0E Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidates Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- B403290069 Ack receipt of B40208 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-267/83-36, 50-270/83-37 & 50-287/83-36 Implementation of corrective actions will be examined during future insp DANCE-H C Division of Project & Resident Programs 84/03/20 TUCKER, H B Duke Power Co ip 22807 0ii 24% Fiche 50-269, 84/03/20,8403290069
- --8403290082 Responds to NRC 840109 ltr re violations noted in IE Insp Repts 50-269/83-36.50-270/83-37 & 50-287/83-36 Corrective actions Unit 2 staging coil locations corrected & seal packages on Reactor Coolant Pump 282 replaced TUCKER.H B Duke Power Co 84/02/08 O'REILLY, J P Region 2, Office of Director 2pp 22807 012 24X Fithe 50-269,84/03/20, 8403290069
- --8403290090 Forwards IE Insp Repts 50-269/83-36, 50-270/83-37 & 50-287/83-36 on 831111-1210 & notice of violation DANCE.H C Division of Project & Resident Programs 84/01/TUCKER.H B Duke Power Co 2pp 22807 014 24X Fiche 50-269,84/03/20,8403290069 84/01/09
- --8403270075 Notice of violation from insp on 831111-1210 m Region 2, Office of Director 84/01/07 lp 228 Fiche 50-269.84/03/20.8403290069 22807 016 24X
- --8403290108 IE Insp Repts 50-269/83-36,50-270/83-37 & 50-287/83-36 on 831111-1210 Violation noted failure to follow Maint Procedure 270/83-37-01 re quality performed on Reactor Collant Pump 282 BRYANT.J., FALCDNER, D. Regian 2. Office of Director BROWNLEE, V.L. Division of Project & Resident Programs 84/01/09 10pp 22807 017, 24X Fiche 50-269.84/03/20.8403290069
- 8402090043 IE Info Notice 84-i9. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22883 229 24X Fiche 50-000.84/03/21.8402090043
- 8402090044 JE Info Notice 84-20, "Svc Life of Relays in Safety-Related 102070044 15 Anto Movies 5. dec. Sys " Svc list enci JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp. 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403200010 Monthly operating repts for Feb 1984 W/840315 ltr REAVIB.J A. TUCKER, H B Duke Power Co 84/02/29 17pp. 22685 185 24% Fiche 50-269,84/02/29,8403200010

- V Operator Examinations
- 8403080239 Forwards operator licensing exam schedule through CY88.in response to Generic Ltr 83-40 TUCKER.H B Duke Power Co 84/02/27 EISENHUT.D G Division of Licensing 2pp 22561 023 24X Fiche 50-267.84/02/27.8403080239
- DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION Security, medical, emergency & fire protection plans
- 8403060022 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR VASSALLO, D B Operating Reactors Branch 2 84/02/21 8INCLAIR, J C Vermont Yankee Nuclear Power Corp 2pp 22528 336 24X Fiche 50-271,84/02/21.8403060022 BINCLAIR, J B
- 8403140285 Informs that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737. Item III A 2 i Reasonable assurance exists that prompt protective measures will be taken to protect public VASSALLO,D 8 Operating Reactors Branch 2 84/02/22 BINCL/ Vernont Yankee Nuclear Power Corp 3pp. 22636:320 24X Fiche 50-271.84/02/22,8403140285 BINCLAIR, J B
- 8403140270 Approves 831116 request to establish emergency operations facility (EGF) 8 75 miles from plant w/o providing backup EOF EUF EISENHUT, D 0 Division of Licensing 84/02/27 MC Vermont Vankes Nuclear Power Corp 2pp 22636 318 Fichs 50-271,64/02/27.6403140290 84/02/27 MURPHY, M. P.
- B403190243 Notification of B40418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice B4-07 Agenda for workshop ent!

 MURLEY.TE Region i, Office of Director B4/03/07 0/TOOLE.J D Consolidated Edison Co of New York, Inc. LUNDVALL.A E Baltimore Gas & Electric Co RANDAZZA.JB Maine Yankee Atomic Power Co 35pp 22672 062 24X Fiche D0-000.B4/03/07.B403190243 Baltimore
- B403290064 Forwards IE Enforcement Conference Rept 50-271/83-26 on B40110 Util has not provided NRC w/required fire protection features for certain equipment in reactor bidg to achieve & maintain safe shutdown MARTIN, T T Division of Engineering & Technical Programs, B4/03/13 MURRHY, W P Vermont Yankee Nuclear Power Corp 2pp 22806 283 24% Fiche 50-271,84/03/13,8409270064
- --8403290071 IE Enforcement Conference Rept 50-271/83-26 on 840110 Major areas discussed potential violation of iOCFR50.App R refailure to provide fire protection for redundant safe shutdown aquipment iocated primarily in reactor bidg PULLANT, S V. ANDERSON.C J. Region I. Office of Director 84/03/06 7pp 22806 285. 24% Fiche 50-271.84/03/13.8403290064
- 8403230063 Requests eight exemptions from IQCFR30. App R requirements re fire protection of safe shutdown capability Exemption request approval will negate need to provide alternate shutdown capability.per Section III G of App R MURPHY.W P Vermont Yankee Nuclear Power Corp 84/03/14 DENTON.H R Office of Nuclear Reactor Regulation, Director 20pp 22735 022 24X Fiche 50-271,84/03/14,8403230063
- 8403200166 Forwards FEMA 820609 final post-exercise assessment for 103200166 Forwards FEMA 820609 final post-exercise assessment for 820218 joint radiological emergency preparedness exercise Rept for 830921 exercise will be issued shortly MARTIN, T.T. Division of Engineering & Technical Programs 84/03, MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 3pp. 22698 041 24% Fishe 50-271,84/03/15,8403200166
- P Operating license stage documents & correspondence
- B403140340 Summary of B31215 meeting w/OE & Mark I Gwners Group in Bethesda: MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL: B L Operating Reactors Branch 2 B4/02/21 Operating Reactors Branch 2 Sipp 22635 198 24X Fiche 50-000.84/02/21, 8403140340
- B403020247 Informs of completion of addl analysis for frequency response of associated hydraulic control units (HCU) for scram mys HCU supports should be modified Installation of mods aspected by end of yr MURHY, W P Vermont Yankee Nuclear Power Corp 84/02/28 VASSALLO, D B Operating Reactors Branch 2 1p 22440 100, 24X Fiche 50-271, 24/02/28, 8403020247

- 8403070304 Provides responses to three open Items from NRC/BNL Yankee Atomic Electric Co & consultants Mark I containment program plant-unique analysis rept 840216 review meeting CELIA,N S Teledyne Engineering Services 84/02/28 SIEGEL,B NRC No Detailed Affiliation Given 4pp 22546 171 24X Fiche 30-000,84/02/28,8403070304
- 8403120003 Forwards Rev O to "Vermont Yankee Nuclear Power Station Offsite Dose Calculation Manual" used to implement provisions of radiological effluent Tech Specs SINCLAIR.J B Vermont Yankee Nuclear Power Corp 84/03/05 VABSALLO,D B Operating Reactors Branch 2 5pp 22589 304 24X Fiche 50-271,84/03/05,8403120003
- --B403120005 Rev O to. "Vermont Yankee Nuclear Power Station Offsite Dose Calculation Manual" * Vermont Yankee Nuclear Power Corp 84/03/05 108pp 22889 309 24X Fiche 50-271.84/03/05.8403120003
- 8403090240 Summary of 840216 meeting w/Northeast Nuclear Energy Co. Boston Edison Co.Vermont Yankee Nuclear Power Co & Teledyne Engineering Svcs in Waltham MA re addl Mark I torus structural analysis List of attendees encl SHEA.J J Operating Reactors Branch 5 SIEOEL, B Operating Reactors Branch 2 8403/07 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 22572 298 24X Fiche 50-000.84/03/07.8403090240
- 8403300268 Forwards request for add1 info re operation of purge & vent valves Response requested within 60 days
 VASBALLO,D B Operating Reactors Branch 2 84/03/12 SINCLAIR, J B
 Vermont Yankse Nuclear Power Corp 3pp 22844 331 24X
 Fiche 50-271,84/03/12.8403300268
- 8403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc iist encl EIBENHUT, D 0 Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000,84/03/14,8403150275
- 8403270190 Forwards supplemental info in response to Generic Ltr 83-28 re required actions based on generic implications of Salem ATWS events
 HURPHY,N P Vermont Yankee Nuclear Power Corp 84/03/23
 VABBALLO,D B Operating Reactors Branch 2 10pp 22772 171 24X
 Fichs 50-271.84703/23.8403270190
- Q Inspection reports, IE Bulistins & correspondence
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22707 237 24X Fiche 50-000.84/02/28,840117007P
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " 8vc list encl GRACE.J N Division of GA. Bafeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- B40209000B IE Info Notice 84-i6. "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 09B 24X Fiche 50-000,84/03/02,8402090008
- B402070009 IE Info Notice 84-i5, "Reporting of Radiological Releases"
 Svc list enci
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02;8402070009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Balow Nil Ductiiity Temp " Svc list encl JURDAN, E L Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/03/05, Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- B402090024 IE Info Notice B4-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/07 Consolidated Edison Co of New York, Int 118pp 22635 049 24X Fiche 50-000, B4/03/07. B402090024
- B40209002B IE Info Notice B4-iB, "Stress Corrosion Cracking in PWR Bys." Byc list enc! JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/07 Consolidated Edison Co of New York, Inc 11Bpp 22584 186 24X Fiche 50-000 B4/03/07, B40209002B

- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IC Safety Sys " Svc list enc! DEYOUNG:R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24% Fich# 50-000,84/03/12.8402090031
- 8403200274 Forwards "Recirculation & RHR Weld Joint Insp Program ~ 1984 Refueling Outage " Refueling scheduled to commence 840616 BINCLAIR. J B Vermont Yankee Nuclear Power Corp 84/03/13 VASSALLO, D B Operating Reactors Branch 2 2pp 22676 126 24X Fiche 50-271.84/03/13.8403200274
- --B403200277 "Recirculation & RHR Weld Joint Insp Program 1984 Refueling Outage " • Vermont Yankse Nuclear Power Corp 84/03/13 43pp 22694 128 24X Fiche 50-271,84/03/13,8403200274
- B403290064 Forwards IE Enforcement Conference Rept 50-271/83-26 on 840110 Util has not provided NRC w/required fire protection features for certain equipment in reactor bldg to achieve & maintain safe shutdown
 MARTIN.T T Division of Engineering & Technical Programs 84/03/13
 MURPHY.H P Vermont Yankee Nuclear Power Corp 2pp 22806 283
 24X Fishe 50-271-84/03/13-8403290064
- ---B40329007i IE Enforcement Conference Rept 50-271/83-26 on 8401iO Major areas discussed potential violation of 10CFR50. App R refailure to provide fire protection for redundant safe shutdown equipment located primarily in reactor bldg PULLANI.S V, ANDERSON.C J Region 1. Office of Director 84/03/06 7pp 22806 R85 24X Fiche 50-271.84/03/13.8403290064
- 8403200156 Responds to IE Bulletin 80-ii, "Masonry Wall Design "
 Reanalysis of 10 masonry walls completed Addl time required
 to verify results Reanalysis program will be completed by
 June 1784
 MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 84/03/15
 VASSALLO, D.B. Operating Reactors Branch 2 ip. 22696 362 24X
 Fiche 30-271.84/03/15.8403200156
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 227 24X Fiche 50-000.84/03/21,8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000.84/03/21,8402070044
- 8403300153 Responds to 1E Builetin 83-07 re apparently fraudulent products sold by Ray Miller. Inc No evidence found that subj math supplied directly or indirectly by Ray Miller. Inc for use at factility MURPHY.W P Vermont Yankee Nuclear Power Corp 84/03/22 MURLEY.T E Region 1. Office of Director 2pp 22821 014 24X Fiche 50-271,84/03/22,8403300153
- B403300065 Ack recript of 840302 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-271/83-33 MARTINITY Division of Engineering & Technical Programs 84/03/23 MURPHY.W P Vermont Yankee Nuclear Power Corp 2pp 22821 291 24X Fiche 50-271:84/03/23:8403300065
- --840330007i Responds to NRC 840131 ltr re violations noted in IE Insp Rept 50-271/83-33 Corrective actions Procedure OP 0533. "Body Burden Counting," will be revised MURPHY, W P Vermont Yankse Nuclear Power Corp 84/03/02 MARTIN, T T Division of Engineering & Technical Programs 2pp 22821 293 24X Fiche, 50-271, 84/03/23, 8403300065
- 8403300142 Ack receipt of 840302 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-271/83-30 MARTIN T T Division of Engineering & Technical Programs 84/03/23 MURPHY.W P Varmont Yankee Nuclear Power Corp 1p 22820 358 24X Fiche 50-271.84/03/23.8403300142
- --B403300146 Responds to NRC B40201 itr re violations noted in IE Insp Rept 50-271/63-30 Corrective actions radiation surveys will be made using both Eberlins RD-2 & E-520 instrumentation Health physics mgt approval will be required MURHMY.W P Vermont Yankee Nuclear Power Corp B4/03/02 MURLEY.T E Region 1. Office of Director 4pp 22821 359 24X Fiche 50-271.84/03/23.8403300142

- R Periodic operating reports & related correspondence
- 8403130481 "Annual Operating Rept for 1983 " W/840305 ltr SINCLAIR. J B Vermont Vantee Nuclear Power Corp 83/12/31 MURLEY. T E Regian 1. Office of Director 10pp 22613 199 24X Fiche. 50-271, 83/12/31.8403130481
- 8403230140 Personnel exposure annual rept for 1983 W/840312 itr SINCLAIR.J. I Vermont Yankee Nuclear Power Corp 83/12/31 MURLEY.T E Region 1. Office of Director 3pp 22730 231 24X Fiche 50-271.83/12/31.8403230140
- 840319086 Monthly operating rept for Feb 1984 W/840309 itr BURGER:F J , MURPHY,W P Vermont Yankee Nuclear Power Corp 84/02/29 7pp 22669 220 24% Fiche 50-271,84/02/29,8403190086
- 8 Reportable occurrences, LERs & related correspondence
- 8403050223 Further response to FDIA request for records of named individuals including repts, analyses, studies, test calculations, procedures & practices for measurement of RGS leakage Forwards App C documents Search continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN, T J. Kaye, Scholer, Fierman, Hays & Handler 3pp 22496 234 24X Fiche 30-000,84/02/07,8403050223
- --8403050241 Forwards potentially generic (asue data sheet on 800611 event re failure of BWR drywell leakage detection sys to identify significant leakage BRUNNER.E.J. Region 1. Philadelphia, Office of the Director 80/07/10 JORDAN.E.L. Region 1. Philadelphia, Office of the Director LENIS.R.C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch HEISHMAN.R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 2. Pranch 22476 257 24X Fichm 50-900,84/02/07,8403050223
- 8403020322 Forwards LERs 84-001-01 & 84-002-00 PELLETIER, J P Vermont Vanice Nuclear Power Corp 84/02/27 Record Services Branch (Document Control Desk) ip 22439 307 24X Fiche 50-271, 84/02/27, 8403020322
- --8403020326 LER 84-001-01 on 840105, pressure translent generated, resulting in reactor trip Caused by instability in turbine controls sys Instruments which provide trip checked & one channel recalibr
 PELLETIER, J P. Vermont Yankee Nuclear Power Corp 84/02/27 2pp 22439 308 24X Fiche. 50-271, 84/02/27, 8403020322
- --8403020328 LER 84-002-00 on 840202, torus-reactor bldg vacuum breaker sys found out of calibr Caused by setpoint drift Switch setpoints readjusted to Tech Spec requirements PELLETIER, Jp Vermont Yankee Nuclear Power Corp 84/02/27 2pp 22439 310 24X Fiche 50-271,84/02/27,8403020322
- ODCKET 50-272 BALEM NUCLEAR GENERATING STATION, UNIT 1
- F Becurity, medical, emergency & fire protection plans
- 8403160132 Forwards IE Insp Rept 50-272/83-37 on 831205-06 & 840116-20 Full compliance w/fire protection features for safe shutdown apparently not achieved MARTIN.T T Division of Engineering & Technical Programs 84/03/02 UDERITZ.R A Public Service Electric & Gas Ca of New Jersey 3pp 22635:291 24X Fische 50-272.84/03/02.8403160152
- --8403160157 lE Insp Rept 50-272/83-37 on 831205-06 & 840116-20 Noncompliance noted failure to provide fire protection features required by App R. Section III 0 for safe shutdown in five areas of plant PULLANI.8. ANDERSON.C Region i. Office of Director 84/03/01 235p 22655 294 24X Fiche 50-272,84/03/02,8403160152
- 8403190433 Responds to 821205 & 830718 itrs re emergency operations facility (EOF) Request to establish primary EOF 7 5 miles from facility w/o providing backup EOF acceptable EISENHUT.D Q Division of Licensing 84/03/05 LIDEN,E A Public Service Electric & Gas Co of New Jersey. 1p 22681 325. 24X Fichm 50-272.84/03/05.8403190433
- 8403130171 Forwards FEMA post-exercise assessment for 831024 joint exercise of State of DE & iocal radiological amergency preparedness plans for facility MARTIN.T T Division of Engineering & Technical Programs 84/03/0 UDERITZ.R A Public Service Electric & Gas Co of New Jersey Op 22597 223 24X Fiche 50-272,84/03/07.8403130171
- --840313017B Evaluation of 831024 joint exercise of State of DE & local padiological emergency preparedness plans for facility.

 * Federal Emergency Management Agency 83/11/25 72pp
 22597 226 24X Fiche 50-272,84/03/07-8403130171.

- 8403220006 Forwards IE Insp Repts 30-272/84-06 & 90-311/84-06 on 840206-10 No violations observed MARTIN, T T Division of Engineering & Technical Programs 84/03/08 UDERITZ.R A Public Service Electric & Oas Co of New Jersey 2pp 22716 174 24% Fiche 50-272.84/03/08.8403220006
- --B403220010 IE Insp Repts 50-272/B4-06 & 50-311/B4-06 on B40206-10 No violations noted Major areas inspected security organization, security program audit testing & maint, physical barriers, security sys power supply & assessment aids MADDEN, M J, BAILEY, R J, JOYNER, J H, Ragion 1, Office of Director B4/03/06 4pp 22716 176 24X Fiche 50-272, B4/03/08, B403220006
- B403190243 Notification of B40418 workshop in King of Prussla, PA to discuss lessons learned from recent App R fire protection safe shuddown insp & topics described in IE Info Notice B4-09 Agenda for workshop sntl HURLEY, T E Region I. Office of Director Consolidated Edison Co of New York, Inc Power Authority of the State of New York 50pp 22672-062 24X Fiche 50-000-84/03/09,8403190243
- J Insurance & Indemnity information
- 8403260197 Forwards Endorsement 48 to NELIA Policy NF-236, Endorsements 69 & 72 to NELIA Policy NF-208, Endorsement 59 to MAELU Policy NF-77 & Endorsement 67 to NELIA Policy NF-230, GULDEN, M.P. Harsh & McLennan, Inc. 84/03/12 8ALTZMAN, J. Assistant Director for State & Licensee Relations, 6pp 22751 033 24% Fiche 50-000,84/03/12.8403260197
- B4032B005B Forwards Endorsements 68 & 69 to NELIA Policy NF-230 & Endorsements 54 & 55 to MAELU Policy MF-90 GOLDEN, M P Harsh & McLennan, Inc. 84/03/21 SALTZMAN, J. Assistant Director for State & Licensee Relations. 5pp. 22776-354 24X Fiche 50-272, B4/03/21, B40328005B
- P Operating license stage documents & correspondence
- 8403070047 Submits details of vendor manual review program in response to 830506 order modifying licenses Commitment to incorporate all vandor manuals for safety-related equipment into document control sys completed in 10EN, E.A. Public Service Electric & Gas Co. of New Jersey, 84/02/22 KISTER, H.B. Division of Project & Resident Programs 3pp 22575.345 24X Fiche, 50-272,84/02/22,8403090049
- 8403030119 Forwards supplemental response to Generic Ltr 83-28,
 "Required Actions Based on Generic Implications of Balem
 ATMS Events"
 BARNES, P. L. Commonwealth Edison Co. 84/02/29 DENTON, H. R. Dffice
 of Nuclear Reactor Regulation, Director 26pp. 22488 084 24X
 Fiche 50-000,84/02/29,8403050119
- 8403:30017 Requests extension for updating inadequate core cooling instrumentation & reactor vessel level instrumentation sys status repts per TMI Item II F 2 & providing Mestinghouse proprietary info until 840402 LIDEN,E A Public Service Electric & Oas Co of New Jersey 84/03/02 VARQA,E A Dyparating Reactors Branch 1 ip 22614 361 24X Fiche 50-272,84/03/02,8403130017
- 8403260050 Requests Identification of any potential problems or items re completion of NUREO-0737 items by Sept 1984 Response requested within 30 days of itr receipt VAROA, 8 A Operating Reactors Branch 1 84/03/02 UDERITZ, R A Public Service Electric & Oas Co of New Jersey. 3pp 22763 281 24X Fichs 50-272.84/03/02.8403260050
- B403140113 Forwards "Salem Generating Station 316(b) Demonstration," per 830623 request for add1 info re review of OL application for Hope Creek
 MITTLIR L Public Service Electric & Qas Co of New Jersey
 B4/03/05 SCHHENCER,A Licensing Branch 2 ip. 22629 124 24X
 Fiche. 30-000.84/03/05.8403140113
- --8403140117 "Balem Generating Station 316(b) Demonstration "
 # Public Service Electric & Gas Co. of New Jersey 84/02/29,
 647pp 22629,125 24X Fiche 50-000.84/03/05:8403140113.
- B4032702Bi Forwards plant-specific info on reactor protection sys shunt trip mods, in response to NRC B30810 ltr & Generic Ltr B3-2B Shunt trip mechanism will be installed during refusing outage. W/14 oversize drawings Aperture cards in PDR LIDEN.E A Public Service Electric & Gas Co of New Jersey B4/03/14 VARQALB A Operating Reactors Branch 1 14pp. 22800 200 24X Fiche 50-272.84/03/14.8403290281

- 8403300085 Requests extension to Jul 1984 for completion of post-maint operability testing of safety-related equipment based on revised interpretation of scope identified through discussion w/Region 1 personnel LIDEN, E A Public Service Electric & Gas Co of New Jersey 84/03/23 VAROA, S A Operating Reactors Branch 1 3pp 22822 073 24X Fiche 50-272,84/03/23,8403300085
- Q Inspection reports. IE Bulletins & correspondence
- 8401190072 IE Info Notice 8A-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl UORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000.84/02/28.8401190072
- 8403070080 Submits supplemental response to IE Builetin 83-06 re nonconforming maths supplied by Tube-Line Corp Remaining four suppliers confirmed that no subj meths supplied to Hope Cresk Colt Industries info under review MARTIN.T J Public Service Electric & Gas Co of New Jarsey 84/02/28 MURLEY.T E Region 1. Office of Director 2pp 22575 297 24X Fiche 50-000,84/02/28,8403070080
- 8403150068 Forwards IE Insp Repts 50~272/84~02 & 50-311/84-02 on 840116-19 No violations observed MARTIN.T T Division of Engineering & Technical Programs 84/02/28 UNDERITI,R A Public Service Electric & Gas Co. of New Jersey 2pp 22643 177 24X Fiche 50-272,84/02/28,8403150068
- --B403150078 IE lnsp Repts 50-272/B4-02 & 50-311/B4-02 on 840116-19 No violations observed Major areas inspected nonradiological chemical measurements. GC program of analytical measurements & procedures & training ZIBULSKY, H, KITTAN, JJ, PASCIAK, WJ, Region 1, Dffice of Director B4/02/27 3pp 22643 179 24X Fiche 50-272.84/02/28, B403150068
- 8402090007 IE info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Evc list enc! ORACE, J N Division of GA, Bareguerds & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24x Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparodness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE info Notice 84-15, "Reporting of Radiological Releases"

 8vc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8403160152 Forwards IE Insp Rept 50-272/83-37 on 831205-06 & 840116-20 Full compilance w/fire protection features for safe shutdown apparently not achieved MARTIN T T Division of Engineering & Technical Programs 84/03/02 UDERITZ.R A Public Bervice Electric & Gas Co of New Jersey 3pp 22655 291 24X Fiche 50-272, 84/03/02.8403160152
- --8403160157 1E Insp Rept 50-272/83-37 on B31205-06 & 840116-20 Noncompliance noted failure to provide fire protection features required by App R.Bection III 0 for safe shutdown in five areas of plant PULLANI,8, ANDERSON,C Region 1. Office of Director B4/03/01 23pp 22655 274 24X Fiche 50-272,84/03/02,8403160152
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp. 22553 336 24% Fiche 50-000,84/03/05.8402090011,
- 8403220105 Forwards IE Insp Repts 50-272/84-04 & 50-311/84-04 on 840111-0206 No violations observed STAROSTECKIR Division of Project & Resident Programs 84/03/06 UDERITY: A Public Service Electric & Qas Co of New Jersey 2pt 22715 285 24X Fiche 50-272,84/03/06,8403220105
- --8403220113 IE Insp Repts 50-272/84-04 & 50-311/84-04 on 840111-0206 No violations identified Major areas inspected status of previous insp items.revisus of periodic & special repts, LER review & operational safety verification LINVILLE, J C , SUMMERS, R J Region i, Office of Director NURRHOLM, L J Division of Project & Resident Programs 84/02/27 17pp 22715 287 24X Fichs 50-272,84/03/06,8403220105

- 8402090024 IE Info Notice 84-09, Rev 1, 'Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list enc!
 JCRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York Inc 118pp 22635 049 24% Fiche \$0-000.84/03/07.8402090024
- 8402070028 iE info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " Syx list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Editor Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8403220006 Forwards IE Insp Repts 50-272/84-06 & 50-311/84-06 on 840306-10 No violations observed MARTIN.T T Division of Engineering & Technical Programs 84/03/08 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 2pp 22716 174 24X Fiche 50-272.84/03/08.8403220006
- --8403220010 lE Insp Repts 50-272/84-06 & 50-311/84-06 on 840206-10 No violations noted Major areas inspected security organization, security program audititesting & maintiphysical barriers, security sys power supply & assessment aids MADDEN.W J , BAILEY.R J , JOYNER.J H Region 1, Office of Director 84/03/06 4pp 22716 176 24X Fiche 50-272,84/03/08.8403220006
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12.8402090031
- 8403220036 Responds to IE Bulletin 83-07, "Apparently Fraudulent Products Sold By Ray Miller. Inc "Companies supplying matls or sucs to facilities listed No mati purchased from Ray Miller. Inc LIDEN,E A Public Service Electric & Gas Co of New Jersey 84/03/14 HURLEY,T E Region 1. Office of Director App 22865 166 24% Fiche 50-272.84/03/14.8403220036
- B403270206 Forwards IE Mgt Meeting Repts 50-272/84-11 & 50-311/84-11 on 840201 Corrective actions taken for ALARA program deficiencies noted in IE Insp Repts 50-272/83-22 & 50-311/83-22 adequate MARTIN,T T Division of Engineering & Technical Programs 84/03/15 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 2pp 22803 288 24X Fiche 50-272.84/03/15.8403270206
- --8403270210 1E Mgt Meeting Repts 50-272/84-11 & 50-311/84-11 on 840201
 Major areas discussed planned improvements in program to
 reduce personnel occupational radiation exposure to ALARA
 Corrective action acceptable
 NIMITZ.R L , SHANDAKY.M M Region 1, Office of Director
 84/03/06 3pp 22803 270 24X Fiche 50-272,84/03/15,8403290206
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 227 24X Fichs 50-000.84/03/21,8402090043
- 8402070044 IR Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list enc: JORDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fichs 50-000,84/03/21,8402070044
- B403270135 Forwards IE Mgt Meeting Repts 50-272/84-12 & 50-311/84-12 on B40306 to discuss util action plan for improving nuclear dept operations
 BTAROBIECKI, R Division of Project & Resident Programs B4/03/22
 UDERITZ, R Public Service Electric & Gas Co of New Jersey 2pp 82807 107 24% Fiche 50-272,84/03/22,8403270135
- --8403270137 IE Mgt Moeting Repts 50-272/84-12 & 50-311/84-12 on 840306 Areas discussed overview of status of action plan to improve nuclear dept operations LINVILLE, J C , NORRHOLM, L J Region 1, Office of Director 84/03/12 70pp 22807 107 24X Fiche. 50-272,84/03/22,8403270135
- 8403300171 Ack receipt of 831128 & 840304 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-27/283-27 & 50-311/813-30 STAROBIECKI, R Division of Project & Resident Programs 84/03/23 UDERITZ, R A Public Service Electric & Gas Cq of New Jersey ip 22820,032 24x Fiche 50-272:84/03/23.8403300171

- *B403300177 Suppls B31128 response to NRC B31026 itr re violations noted in RE insp Repts 50-272/B3-27 & 50-311/B3-30

 Corrective actions emergency instruction action requirement, re reactor coolant pump shaft, revised LIDEN, E A Public Service Electric & Oas Co of New Jersey B4/03/06 STAROSTECKI, R Division of Project & Resident Programs 4pp 28820 033 24% Fishe 50-272, B4/03/23, B400300171
- -8403300183 Responds to NRC 831026 ltr re violations noted in IE Insp Repts 50-272/83-27 & 50-311/83-30 Corrective actions emergency instruction revised to increase limits for vibration & decision made to remove action requirements LIDEN.E A Public Service Electric & Oas Co of New Jersey 83/11/28 STROSTECKIR Division of Project & Resident Programs 3pp 22820 037 24X Fiche 50-272.84/03/23.8403300171

Periodic operating reports & related correspondence

- O3070305 Personnel exposure rept for 1983 W/840223 itr MIDURA/H J Public Service Electric & Oas Co of New Jersey 83/12/3i MURLEY,T E Region I. Office of Director 7pp 22546 335 24x Fiche 50-272,83/12/3i,8403070305
- 03070260 Forwards "Salem Nuclear Generating Station Semiannual Radioactive Effluent Release Rept. Jui-Dec 1983." Interim rept Effluent data for Fourth Guarter 1983 incomplete Revised rept expected by 840415 tillen.E A Public Service Electric & Gas Co of New Jersey 84/03/29 MURLEY.T Region 1. Office of Director 2pp 22546 232 24X Fiche 50-272.84/02/29.8403070240
- 8403070261 "Salem Nuclear Generating Station Semiannual Radioactive Effluent Release Rept. Jul-Dec 1983." Interim rept * Public Service Electric & Gas Co of New Jersey RERR-151 83/12/31 48pp 22546 234 24X Fiche 50-272.84/02/29.8403070260
- 23220174 Monthly operating rept for Feb 1984 W/840310 1tr MILLER.1. K. ZUPKO.J M Public Service Electric & Gas Co of New Jersey 84/02/29 13pp 22718 103 24X Fichs 50-272,84/02/29, 8403220174

Reportable occurrences. LERs & related correspondence

- ill50076 Discusses events involving loss of electrical inverters including attendant inverters to vital instrument buses Recommendations provided by Nuclear Safety Analysis Ctr are excellent in helping to reduce instrument failures ASHE.F Reactor Operations Analysis Branch 82/10/21 SEYFRIT.K V Reactor Operations Analysis Branch 8pp 22775 223 24X Fiche 50-000.82/10/21.8211150076
- D2100176 LER 84-002-00 on 840107, inlet valve 13CN27 closed due to spurious high level in feedwater heater 15C Caused by heater typess ICN47 falling to open Bypass differential setpoint lowered & signal summator module replaced W/840206 tr RUEP, J. L. ZUPKD, J. M. Public Service Electric & Gas Co. of New Jersey 84/02/06 5pp. 22313 001 24X Fiche 50-272,84/02/06, 3402100176
- 03080013 Supplemental LER 81-059/01X-01 on 810616, during initial esting, auxiliary feedwater pump 23 turbine steam supply theck vaives 21M946 & 23M846 found damaged internally Caused by steam flow sys oscillations W/840224 ltr lupko, J M Public Service Electric & Gas Co of New Jersey 84/02/24 4pp 22559 239 24X Fiche 50-272,84/02/24,8403080013
-)3080246 Supplemental LER 03-062/99X-1 on 831122.during testing on seismic instrumentation.triarial time history accelograph is not respond as required Caused by detector failure iccelerometer replaced H/840224 ltr UPP. J. ZUPKO. J M. Public Service Electric & Cas Co. of New Jersey 84/02/24 4pp 22561 009 24X Fiche 50-272.84/02/24,8403080246
- 13080252 Supplemental LER 79-068/03X-i on 791018, safety injection ump motor i2 tripped on overcurrent Caused by impeller acknots improperly secured at mfg facility Pumps eassembled using Locktite compound W/840224 ltr IUPP. J. ZUPKO, J. B. Public Service Electric & Gas Co. of New Jersey 84/02/24 4pp 22557 i00 24X Fiche 50-272,84/02/24,8403080252
- 3270244 LER 84-005-00 on 840224 reactor trip occurred from 100% ower Caused by turbine generator tripping on generator evertal ground protection investigation into extent & cause f damage in progress W/840323 itr
 UPPAJ L. 7UPKOJ M Public Service Electric & Gas Co of New lersey 84/03/23 4pp 2277) 312 24X Fithe 50-272,84/03/23

U Congressional/Executive Correspondence

- B403150336 Responds to B40131 request for explanation of recent facility annual review Personnel mgt & organization attitudes affected low rating If performance unacceptable, immediate enforcement action will be taken DIRCKS,W J Office of the Executive Director for Operations 84/03/04 ROTH,W V Senate 2pp 22649 265 24X Fiche 50-272,84/03/06,8403150336
- --8403150341 Requests explanation of implications of rating of unsatisfactory in area of plant operations ROTH.W V Senate 84/01/31 PALLADINO,N J Commissioners 3pp 22649 268 24X Fiche 50-272,84/03/06.8403150336

V Operator Examinations

- 8403060312 Responds to 840124 ltr re iicensed operator requallfication program Quities used to determine weaknesses & need for emphasis on subjs Licensed operator training program Training Procedure TP-305 revised LIDENSE A Fublic Service Electric & Oas Co of New Jersey 84/02/28 VARCAS A Assistant Director for Operating Reactors 2pp 22515 333 24X Fiche 50-272.84/02/28.8403060312
- DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

 E NRC Safaty Evaluation Report (SER), supple & correspondence
- 8403080085 FDIA request for SER & SSER 21 (NUREG-0675) re operation of facilities GARDE, B P Government Accountability Project 84/01/09 Office of Administration 2pp 22584 074 24X Fiche 50-275,84/01/09,840308085
- B403080076 Partial response to FOIA request for SER re operation of facilities Forwards documents listed on app Documents also placed in PDR Review of remaining documents continuing FELTON. J M Division of Rules and Records 84/01/23 GARDE, B P Government Accountability Project 2pp 22584 076 24X Fiche 50-275,84/01/23,8403080075
- --8403080103 Allegations 51 & 52 re NRC concern that plant personnel reluctant to come forward w/safety concerns since candor endangers jubs ** NRC No Detailed Affiliation Given 84/01/23 2pp 22584 089 24X Fiche 50-275.64/01/23.8403080096
- B403150147 Supple B40217 response to SSER Items 61 & 102 re design control process Design control process adequately controlled & const completed as specified SCHUYLER.J D Pacific Gas & Electric Co 84/02/25 MARTIN.J B Region 3. Office of Director 11pp 22639 351 24X Fichs 50-275.84/02/25,8403150147
- 8403060564 Forwards SSER 17 re util application for QLs, Suppl addresses NRC evaluation re breakwater & superstrut issues M/o encl KNIGHTON, G W Litensing Branch 3 84/02/27 BCHUYLER, J D Pacific Gas & Electric Co 4pp 22552 265 24X Fiche 50-275, 84/02/27, B403060364
- 8409070104 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-275 And 50-323 (Pacific Gas And Electric Company)

 * Division of Licensing NUREO-0675 S17 84/02/29 22pp
 Available at NRC 43 00 22561 214 24X Fichs 50-275,84/02/27,8403070104
- 8402090030 Board Notification 84-035 updates allegation listed in SSER 21 & Board Notification 84-003 Public allegations not previously forwarded & characterizations of allegations from confidential sources encl EISENHUT. D & Division of Licensing 84/03/02 PALLADING, 01LINSKY, ROBERTS Commissioners iipp 22556 O6i 24X Fiche 50-275,84/03/02,8402090030
- --8312140347 Forwards Nuclear Svc Corp 1977 audit of Pullman Power Products work scope at facility, in response to 831004 ltr to Chairman Palladino Attention called to ASLAB 831024 denial of Joint intervenor 831020 motion to reopen record DIRCKS, W J Office of the Executive Director for Operations 83/11/18 THOMAG, W M House of Rep 4pp 22556 080 24X Fiche 50-275,84/03/02,8402090030
- --8312140351 Forwards JR Reynolds 830721 itr expressing concern,on behalf of Joint Intervenors re deficient design & const of factility Nuclear 8vc Corp 1977 audit enci
 THOMAS, W H House of Rep 83/10/04 PALLADING, N Commissioners
 4pp 22556 081 24X Fiche 50-275,84/03/02,8402070030

- --8403080281 "Audit Rept Pullman Power Products Hork Scope at Diablo Canyon Site 770822-0920 " HEBER.J., LARSEN.G J., NEHMAN.T C Pacific Gas & Electric Co 77/09/20 42pp 22556 090 24X Fiche 50-275.84/03/02.8402090030
- --8312280099 Responds to 831021 itr re rept of 1977 audit of Pullman Pawor Products Corp Motlon filed before NRC for revocation or in alternative, continuation of Suspension of low power OL for facility Matter referred to NRC DIRCKS.W J Office of the Executive Director for Operations 83/11/18 PANETTAL E House of Rep 4pp 22596, 132 24X Fiche 80-275, 84/03/02.8402090030
- --B312280102 Requests response to allegations made in Nuclear Svcs Colpenciaudit rept re Pullman Power Products Corp const QA afforts
 PANETTA, L. E. House of Rep. B3/10/21 PALLADINO, N. Commissioners ip 24% Fiche 50~275, 84/03/02,8402090030
- --8312280107 "Proposal for Independent Internal Audit of Pullman-Kellogy Efforts at Diablo Canyon " * Nuclear Services Corp 77/07/28 21pp 22556 134 24X Fiche 50-275,84/03/02,8402090030
- --8401040010 Forwards all ltrs which appeared in San Luis Obispo Talegram-Tribune between 831019-31 re emergency planning response plan for facility Lack of public confidence in response plan discussod KRANZDORF,R Affiliation Not Assigned 83/11/04 PALLADINO,N Commissioners 17pp 22556 175 24X Fiche 50-275,84/03/02, 8402090030
- 8403080405 Further response to FOIA request for documents re SER related to operation of facilities Forwards App 8 documents App A & B documents available in PDR Review of remaining documents subj to request in progress FELTON, J M Division of Rules and Records 84/03/02 GARDE, B f Oovernment Accountability Project 4pp 22583 073 24X Fiche 50-275,84/03/02,8403080405
- --8403080431 Forwards SSER input re Allegation 68 Programmatic breakdown in Pullman Power Products GA program not indicated Installed hardware safety concerns not identified LIEBERMAN.J Office of the Executive Legal Director 83/12/27 EISENHUT, D Division of Licensing 4pp 22583 i63 24X Fiche 50-275,84/03/02.8403080405
- B403220172 Forwards update of closeout status of SBER 20 Open Item 2 & followup Items 1 & 9 re Hertz cutoff emorgency, auxiliary feedwater sys runout control sys test & overspeed setpoint change, respectively SCHUYLER, J O Pacific Gas & Electric Co B4/03/19 KNIGHTON, G W Licensing Branch 3 2pp 22717 020 24X Fiche 50-275, 84/03/19, B403220172
- 8403300078 Responds to 840315 request for info on Item 28 of SSER 2i re annulus structure reverification Visual insps of piping performed insp identified need for support mods Mods reinspected at operating temps 8CHUYLER, J O Pacific Ons & Electric Co 84/03/23 KNIGHTON, G W Licensing Branch 3 ip 22822 087 24X Fiche 30-275, 84/03/23, 840330078
- 8403300148 Suppls util 840215 ltr providing justification for exclusion of auxiliary feedwater level control valve activators from severe environ exposure list per SSER 27 followup Item 5 SCHUYLER.J C Pacific Oas & Electric Co 84/03/23 KNIGHTON.G W Licensing Branch 3 ip 22820 344 24x Fiche 50-275,84/03/23,8403300148
- 8403300300 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, Units I AND 2 Docket Nos 50-275 And 50-323 (Pacific Ras and Electric Company)

 ** Division of Licensing NUREG-0675 S22 84/03/31 400pp Available at NRC, \$11 00 22843 001 24% Fiche 50-275,84/03/31,8403300300
- F Security, medical, emergency & fire protection plans
- B403280114 Public version of revised emergency plan implementing procedures, including Procedures EP OP-9 re loss of reactor coolant pump w/o reactor trip & EP G-2 re ostablishment of organization W/840103 & 0322 memos
 THOMBERG.R C , SCHUYLER.J O Pacific Gas & Electric Co 84/01/05 MARTIN.J B Region 5, Office of Director 33pp 22811 236 24X Fiche 50~275,84/01/05,8403280114

- 8403070355 Public version of emergency plan implementing procedures, lineluding Procedure EP 0-4 personnel accountability & assembly & EP RB-12 re mid & high-range plant vent radiation monitors W/840208 ltr & JM Felton 840302 release memo THOMBERG.R C , SCHWYLER.J O Pacific Oas & Eloctric Co 84/01/23 MARTIN.J B Region 5. Office of Director 120pp 22565 187 24X Fiche 50-275.84/01/23.8403070395
- B4030&013B Forwards IE Insp Repts 50-275/83-39 & 30-323/83-27 on B31205-22 & notice of violation B15HOP.T W Division of Resident, Reactor Project & Engineering Programs 84/02/03 SCHUVLER, J O Pacific Qas & Electric Co 2pp 22506 334 24% Fiche 50-275,84/02/03,840306013B
- --8403060142 Notice of violation from insp on 831205-22 CANTER, H L Region 5, Office of Director 84/02/03 2pp 22506 336 24X fiche 50-275,84/02/03,8403060138
- --8403060146 IE Insp Repts 50-275/83-39 & 50-323/83-27 on 831205-22 Noncompliance noted failure to properly implement fire loss prevention procedures & suppls 9COMN.K : POLICH:T : CANTER.H L Region 5: Office of Directur 84/01/24 18pp 22506 338 24X Fiche 50-275:84/02/03:8403060138
- 8403090172 Forwards Rev 11 to physical security plan Rev withheld (ref 10CFR73 21)
 SCHUYLER, J O Pecific Oas & Electric Co 84/02/06 MARTIN, J B Region 5. Office of Director ip 22575 049 24x
 Fiche 50-275,84/02/06,8403090172
- 8402230176 Forwards revised State of CA nuclear power plant emergency response plan MEDFORD, M O Southern California Edison Co 84/02/16 EISENHUT, D O Division of Licensing 363pp 22353 001 24X Fiche 50-000, 84/02/16, 8402230176
- --8403020117 Revised State of CA nuclear power plant emergency response plan

 * California, State of 83/04/30 290ipp 22353 003 24X

 Ficha 50-000.84/02/14.8402230176
- 8402090006 Board Notification 84-034 forwards R Voltmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT.D 0 Division of Licensing 84/02/23 PALLADING Commissioners ip 22576 203 24X Fiche 50-000, 84/02/23, 8402090006
- --8403080314 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NRR Ofc Ltr 19, dtd 82100; Further evaluation of test data required VOLLMER, R H Division of Engineering 84/02/06 EISENHUT, D Q Division of Licensing 10pp 22376 204 24X Fiche 50-000, 84/02/23, 8402070006
- 8403080405 Further response to FOIA request for documents of SER rolated to operation of facilities Forwards App B documents App A & B documents available in PDR Review of remaining documents subj to request in progress FELIGN.J M Division of Rules and Records 84/03/02 GARDE.B P Government Accountability Project 4pp 22593 073 24X Fiche 50-275.84/03/02.8403080405
- --8403080411 Forwards response to Allegation RV-83-A-0034.per GW Knighton 831122 hote Temporarily exempting liconsee from maintaining physical security & safeguards contingency plans dld not increase risk of redialogical sabotage MCCORNLE, OW Power Reactor Safeguards Licensing Branch 83/12/01 THOMAS.C D Standardization & Special Projects Branch 4pp 22583 077 24X Fiche 50-275.84/03/02.8403080405
- --8403080417 Resubmits response to Allegation RV-83-A-0034, per GW
 Knighton 831103 memo Temporarily exempting licensee from
 maintaining physical security & safeguards contingency plans
 did not increase risk of radiological sabotage
 MCCORKLE, GW Power Reactor Safeguards Licensing Branch
 83/12/05 THOMAS, C D Standardization & Special Projects Branch
 3pp 22583 081 24X Fiche 50-275.84/03/02,8403080405
- --8403080420 Forwards response to Allegation RV-83-A-0034, per OH Knighton 821122 note Temporarily exempting licensee from maintaining physical security & safeguards contingency plans did not increase risk of radiological sabotage DURNETT.R F Division of Safeguards 83/12/08 EISENHUT.D O Division of Licensing 3pp 22983 084 24X Fiche 50-275, 84/03/02.8403080403

- 403150082 Responds to NRC 840203 ltr re violations noted in IE Insp Rept 50-275/83-39 Corrective actions area permits for welding posted to identify generic requirements on area basis & util inspector assigned to assist fire marshall SCHUYLER.J C Pacific Gas & Electric Co 84/03/05 MARTIN.J B Region 5. Office of Director 6pp 22646 013 24% Fiche 50-275.84/03/05.8403150092
- |403280001 Forwards safeguards info re changes to Rev !! to security plan Info withheld (ref 1005873 2!)
 SCHUYLERIJO Pacific Gas & Electric Co 84/03/19 MARTIN, J B Region 5. Office of Director ip 22777 151 24X
 Fiche 50-275,84/03/19.8403280001
- 1403270205 Discusses Southern California Edison submittal of 1983 revised State of CA emergency response plan on behaif of ail State of CA plants, incorporating plan into Diablo Canyon Addi planning info will not be developed for Humboldt Bay SCHUYLER, J O Pacific Oas & Electric Co 84/03/22 DENTON.H R Office of Nuticar Reactor Regulation. Director 1p 22772 137 24X Fiche 50-000.84/03/22,8403270205
- 1403290264 Advises that 840111 rev to physical security pian & drawings consistent w/provisions of 10CFR50 54(p) & acceptable SCHUSTER: M D Region 5, Office of Director 84/03/23 SCHUYLER, J D Pacific Gas & Ejectric Co 1p 22800 010 24X Fichs 50-275.84/03/23,8403290264

Adjudicatory correspondence

- 3402090D12 Board Notification 84-045 forwards 840202 petition to defer decision re low power OL, made by Govt Accountability Project (GAP) on tehaif of San Luis Obispo Mothers for Peace Distribution list & app encl EISENHUT.D 0 Division of Licensing 84/02/29 MOORE.T G. JOHNBON.W R. RUCK.J H. Atomic Safety and Licensing Appeal Panel 5pp 67218 074 24% Fichs 30-275.84/02/29.8402090012
- --8403060303 Petition to defer decision re issuance of low power OL until listed actions complete
 DEVINE.T M . CLEWETT. J Government Accountability Project
 DEVINE.T M . San Luis Obispo Mothers for Peace 84/02/02
 Commissioners 94ipp 22508 273 24X Fiche 50-275,84/02/29,
- 403070044 Motion for extension until B40317 to file response to Joint Intervenors B40222 motion to respon record on const GA Certificate of Svc encl NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French B4702/29 Atomic Safety and Licensing Appeal Panel Spp 22541 250 24X Fiche 50-275, B4/02/29, B403070044
- 3403140071 Forwards expurgated transcript of 840125 meeting between staff & C Stokes,per ASLAB 840223 order W/o encl RUTBERG, J Hearing Branch 2 84/02/29 MODRE,T S , BUCK,J H , JOHNBON-W R Atomic Safety and Licensing Appeal Panel 2pp 22434 184 R4X Fiche 50-275,84/02/27,8403140071
- i403060260 Response of Governor Deukmejian to util 840229 motion for extension of time to respond to Joint Intervenor 840222 motion to reopen & motion of Deukmejian for like extension of time to reply Certificate of Svc encl STRUMHASSER. C California, State of 84/03/01 Atomic Safety and Licensing Appeal Panel 9pp 22517 i32 24X Fiche 50-275.84/03/01.
- 3403080118 Suppl) to 840214 motion to augment or, in alternative, to reopen record Provides add) explanantion of allegations redesign & design GA deficiencies from transcript of 840125 meeting Certificate of Bvc encl
 REYNDLDS, J R Joint Intervenors Diable Canyon REYNDLDS, J R
 Center for Law in the Public Interest 84/03/01 Atomic Safety and Licensing Appeal Panei 15pp 22057 182 24X
 Fiche 50-275.84/03/01.8403080118
- 1403060179 Order granting applicant 840229 motion for extension of time to 840319 to respond to Joint Intervenors 840222 motion to reopen record on const 94 TOMPKINS.B A Atomic Safety and Licensing Appeal Panel 84/03/02 2pp 22518 248 24X Fiche 50-275,84/03/02,8403060179
- 403070128 Suppl to 840222 motion to reopen record on issues of const GA & licensee character & competence Serious doubts re util competence to manage project raised M/Certificate of Bvc REYNOLDS, J.R. Affiliation Not Assigned REYNOLDS, J.R. Center for Law in the Public Interest 84/03/02 Atomic Safety and Licensing Board Panel 23pp 22538 231 24X Fiche 50-275,84/03/02,8600070128

- 8403140179 Request for extension of time to 840315 to file response to Joint Intervenor motion to augment or reopen record Certificate of Svc encl RUTBERG-J Hearing Branch 2 84/03/02 Atomic Safety and Licensing Appeal Panel 4pp 22624 100 24X Fiche 50-275,84/03/02,8403140179
- 8403070188 Order requiring governor response to Joint Intervenor 840214 motion to reopen record on issue of design QA by 840308 SHCEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 84/03/06 California, State of ip 2254i 362 24X Fiche 50-275.84/03/06. 8403070188
- 8403120006 Answer opposing Joint Intervenors 840214 motion to augment or reopen record on design GA Motion should be denied in entirety Certificate of Svc encl NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burka, Berry & French 84/03/06 Atomic Safety and Licensing Appeal Panel 23pp 22936 189 24X Fiche 50-275,84/03/06,8403120006
- --B403120010 Affidavit of FC Breismeister DJ Curtis MJ Jacobson ME Leppke, GH Moore, RG Oman LE Shipley & WH White re design GA BREISMEISTER, F, CURTIS DJ , JACOBSON MJ Pacific Gas & Electric Co 84/03/05 10ipp 22586 331 24X Fiche 50-275, 84/03/06,
- --BA03120012 Affidavit of M Tresler,R Oman & M Leppke re history of onsite angineering small bore piping program description TREBLER,M , DMAN,R , LEPPKE,M Pacific Gas & Electric Co B4/03/05 5Bpp 22587 070 24% Fiche: 50-275,84/03/06.8403120006
- --B403120015 Affidavit of LB Mangoba re design verification & const of small bore pipe support sys
 MANGOBA,L B Bechtel Corp B4/03/04 App 22587 i28, 24X
 Fiche. 50-275, 84/03/04, 8403120006
- --B403120017 Affidavit of A Shusterman re design QA & coverup of hanger recalculation SHUETERMAN, A Bechtei Corp 84/03/04 4pp 22587 134 24X Fiche 50-275, 84/03/06, 8403120006
- --8403120018 Affidavit of RD Etzier re design QA & QC inspector qualifications ETZLER,R D Pacific Qas & Electric Co 84/03/06 4pp 22587 138 24% Fiche 50-275.84/03/06.8403120006
- --8403120022 Affidavit of HB Friend re design QA & util/Bechtel contract FRIEND,H B Pacific Oas & Electric Co 84/03/05 2pp 22587 142 24X Fiche 50-275,84/03/06.8403120006
- --B403120023 Affidavit of DJ Curtis re design GA & small bore pipe support group drawing CURTIS,D J Bechtel Curp 84/03/05 2pp 22587 144 24X Fichs 50-275,84/03/06,8403120006
- --8403120029 Affidavit of JD Bhiffer.R Patterson.JM Gisclon.KC Doss. JB Moch.RC Thornberry.RD Etzier.RK Rhodes & EM Burns re J Cooper B40123 affidavit & Joint Intervenor 840214 motion on design GA SHIFFER.J D., PATTERSON.R., GILBCLON.J M. Pacific Gas & Electric Co. 84/03/05 234pp 22587 146 24X Fiche 50-275,84/03/06, 8403120006
- 8403130010 Summarises fears that Commission will discard terms of 1981 order & will surrender normal requirements of Atomic Energy Act by permitting facility to go critical in quality indeterminate state CLEWETT, J Government Accountability Project DEVINE, T., CLEWETT, J Ban Luis Ubisso Mothers for Peace 84/03/13 PALLADINO, N J, OILINBKY, V., ROBERTS, T Commissioners 22642, 326 24X Fiche 50-275, 84/03/13, 8403150010
- 8403160014 Order extending time until 840413 for Commission to act to review ALAB-756
 CHILK, 8 J Office of the Becretary of the Commission 84/03/13 Commissioners ip 22652 362 24X Fiche 50-275,84/03/13. 8403160014
- B403190011 Motion for leave to file reply to util answer in opposition to motion to reppen record Certificats of Svc encl REYNOLDS, J. R. Joint Intervenors Diablo Canyon REYNOLDS, J. R. Canter for Law in the Public Interest B4/03/15 Atomic Safety and Licensing Appeal Panel 5pp 22665 273 24X Fiche 50-275.84/03/15,8403190011

- --8403190016 Reply to util answer in opposition to 840214 motion to augment or, in alternative, to reopen record Contentions in opposition cannot withstend scrutiny Certificate of Svc
 - REYNOLDS, J. R. Joint Intervenors Diabio Canyon REYNOLDS, J. R. Center for Law in the Public Interest 84/03/15 Atomic Safety and Licensing Appeal Panel 26pp 22665 278 24X Fiche 50-275, 84/03/15, 8403190011
- --8403170021 Statement of C Stokes rebutting util defenses of seismic design review STOKEB, C Joint Intervenors Diablo Canyon 84/03/14 26pp 22645 307 24X Fichs 50~275,84/03/15,8403170011
- 8403190100 Answer opposing Joint Intervenor 840214 motion to augment or, in alternative, to reopen record on design GA issues Motion Falled to Justify either augmentation or reopening record Certificate of Sev enci RUTBERO, J. CHANDLER, L. J. Hearing Branch 2 MCGURREN, H. J. Hearing Branch 1 8403/15 Atomic Safety and Licensing Appeal Panel 29pp 22667 215 24X Fiche 50-275.84/03/15.8403190100
- --8403170102 Affidavit of JP Knight re Joint Intervenors motion to augment or, in alternative, to reopen record KNIGHT, JP Division of Engineering 84/03/15 Atomic Safety and Licensing Appeal Panel 16pp 22667 244 24X Fiche 50-275.84/03/15,8403190100
- --8403190106 Affidavit of M Hartzman re Joint Intervenors motion to augment or, in alternative, to reopen record HARTZMAN, M Division of Engineering 84/03/15 22pp 22667 260 24X Ficha 50-275,84/03/15,8403190100
- --8403190110 Affidavit of SD Reynolds re Joint Intervenors 840214 motion to augment or, in alternative, to reopen record REYNOLDS, SD Region 1, Office of Director 84/03/15 Spp 22667 282 24X Fiche 50-275,84/03/15,8403190100
- --8403190114 Affidavit of TW Bishop re Joint Intervenors 840214 motion to augment or, in alternative, to reopen record BIBHOP, TW Region 5. Office of Director 84/03/08 4pp 22667 290 24X Fiche 50-275.84/03/15.8403190100
- --B403190116 Affidavit of JR Fair re Joint Intervenors 840214 motion to augment or, in alternative, to reopen record FAIR, J R Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/08 6pp 22667, 294 24X Fiche 50-275, 84/03/15, 8403190100
- --8403190119 Affidavit of CY Liang re deficiencies in RHR sys design LIANG, C Y Division of Systems Integration (post 811005) 84/03/15 30pp 22667 300 24X Fiche 50-275.84/03/15.8403190100
- --8403190122 Affidavit of F Rosa re RHR sys RDBA,F Division of Systems Integration (post B11005) 84/03/15 17pp. 22667 330 24X Fiche 50-275,84/03/15,8403190100
- --8403190126 Affidavit of JL Crews re Joint Intervenors 840214 motion to augment or, in alternative, to reopen record CREWB. J L Region 5, Office of Director 84/03/14 5pp 22667 347 24X Fiche 50-275,84/03/15.8403190100
- --B403170130 Supplemental affidavit of JL Crews on add1 info re Joint Intervenors motion on GA deficiencies CREMS.JL Region 5, Office of Director B4/03/15 ip 2267.352 24X Fiche. 30-275,84/03/15.8403170100
- --8403190134 Affidavit of H Bchierling re Joint Intervenors 840214 motion to augment or, in alternative, to reopen record Unexecuted affidavit of PJ Horriii encl SCHIERLINO; H Licensing Branch 3 84/03/15, 3pp 22667 353 24X Fiche 50-275,84/03/15,8403190100
- 8403210033 Request for extension of time until 840403 to file response to Joint Intervenors motion to reopen record on const GA Certificate of Svc encl CHANDLER, L J Hearing Branch 2 84/03/16 Atomic Safety and Licensing Appeal Panel 4pp 22704,330 24X Fiche 50-275,84/03/16,8403210033
- 8403210114 Forwards PJ Morrill signed & corrected affidavit as addendum to NRC 840315 response to Joint Intervenors motion to augment or respen design of a record Related correspondence CHANDLER.L J Hearing Branch 2 84/03/16 MOORE.T.8 BUCK, J H Atomic Safety and Licensing Appeal Panel JOHNSON, W R Atomic Bafety and Licensing Board Panel. 2pp 22707 126 24X Fiche 50-275,84/03/16.8403210114

- --B403210119 Affidavit of PJ Horriil as addendum to NRC B40315 response to Joint intervenors motion to augment or reopen design QA record Prof qualifications of JV Knight also enci MORRILL.P J Division of Resident Reactor Project & Engineering Programs B4/03/15 Atomic Safety and Licensing Board Panel Upp 22707 128 24X Fiche 50-275,84/03/16.8403210114
- 8403200133 Discusses dispute between plant workers & util re slander suit Identification of relevant issues, establishing accountability for inaccurate util statements & fixing hardware from 64 breakdown not yet possible DEVINE, T Government Accountability Project DEVINE, T San Luis Obispo Nothers for Peace 81/03/19 PALLADINO, N J , GILINSKY, V , ROBERTS. T Commissioners 20pp 22699 047 24x Fichs 50-275,84/03/19,8403200133
- 8403210159 Decision ALAB-763 affirming LBP-82-70 granting authorization to operate facility.w/listed conditions SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel DSB 021 84/03/20 122pp 22710 144 24X Fiche 50-275.84/03/20.8403210159
- 8403220106 Forwards renewal of application for stay to permit completion of administrative review & opportunity for court review of Joint Intervenors emergency motion REYNOLOB, J R Center for Law in the Public Interest REYNOLOB, J R Joint Intervenors Diablo Canyon DSB 044 84/03/20 PALLADINO, N . GILINGKY, V . ROBERTS, T Commissioners 2pp 22715 304 24% Ficha 50-275,84/03/20,8403220106
- --8403220110 Renewal of application for stay to permit review of Joint Intervenors emergency motion Unexecuted affidevit of M Kaku & Certificate of Svc enci REYNOLDS.J R Joint Intervenors - Diablo Canyon REYNOLDS.J R Center for Law in the Public Interest 84/03/20 Atomic Safety and Licensing Appeal Panel 25pp 22715 304 24x Fiche 50-275.84/03/20.8403220104
- 8403270063 Informs that plant scheduled to be ready for initial criticality on 840329 & for operation above 5% rated power on 840427 CRANE.P A Pacific Gas & Electric Co DSG 113 84/03/21 MODRE.T S Atomic Bafety and Licensing Appeal Panel ip 22766 105 24% Fiche 50-275.84/03/21.8403270063
- 8403270298 Comments on request for meeting to discuss issues raised by C Stokes on submission by util & staff re design GA Related correspondence CHANDLER, L J Hearing Branch 2 DSB 139 84/03/21 DEVINE, T Government Accountability Project 2pp. 22789 035 24X Fiche 50-275,84/03/21,8403270298
- 8403230191 Forwards Nekton, Inc. paper. "Post-Miocene Compressional Tectonics Along Central State of CA Margin " Conclusion of paper will reviewed SCHUYLER, J.O. Pacific Gas & Electric Co. DSB 074 84/03/22 PALLADINO, N.J. ASSELBTINE, J.K., BERNTHAL, F.M. Commissioners 20pp 22743, 072 24X Fiche 50-275, 84/03/22, 8403230191
- 8403260007 Order ruling on 840320 renewal of application for stay Commission currently considering lifting OL suspension Guestion of stay already before Commission Served on 840323 SHDEMAKER, C. J. Atomic Enfety and Licensing Appeal Panel DSB 08184/03/22 Joint Intervenors Diablo Canyon Spp 22747 388 24X Fiche 50-275,84/03/22,8403260007
- 8403260368 Forwards executed signature page for affidavit of M Kaku submitted as attachment to Joint Intervanors 840320 renewal of application for stay REYNOLOS, JR Center for Law in the Public Interest REYNOLOS, JR Joint Intervenors Diablo Canyon DS8 100 84/03/22 PALLADINO, N. GILINSKY, V. RODERTS, T. Commissioners 2pp 22760 133 24X Fiche 50-275,84/03/22,8403260368
- --8403260367 Executed signature page of affidavit of M Kaku in support of 840320 renewal of application for stay KAKU.M Joint Intervenors Diablo Canyon 84/03/21 ip 22760 135 24X Fiche 50-275.84/03/22.8403260368
- 8403270004 Discusses State of CA emergency response plan Plan incorporated into Diablo Camyon plan Addl planning will not be performed for Humboldt Bay per 1980 legislation Related correspondence SCHUYLER, J O Pacific Gas & Electric Co DBB 117 84/03/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 1, 22769, 349 24% Fiche 50-000, 84/03/22, 8403270004
- 8403260005 Requests that low power test license not be granted Discussion before licensing vote requested LEVY,B , SHARPE,C Affiliation Not Assigned DSB 079 84/03/23 PALLADINO,N , ASSELSTINE,J K , BERNTHAL.F J Commissioners ip 22747 356 24X Fiche 50-275,84/03/23,8403260005

- B4032A0364 Forwards 12 addl affidavits in support of B40301 petition to defer any futher licensing decisions until completion of comprehensive reinsp.mgt audit & audit of design verification M/o enc!

 DEVINE.T. CLEWETT.J Opvernment Accountability Project DEVINE.T San tuis Dbispo Mothers for Peace DSB 101 B4/03/23 PALLADING.N J. OILINSMY.V. ROBERTS.T Commissioners 9pp 22760 065 24% Fiche 50-275.84/03/23.8403260364
- 8403270006 Informs that 12 add1 affidavits in support of Mothers for Peace 840301 petition to defer licensing submitted to Region V Related correspondence
 * Government Accountability Project DSB 115 84/03/23
 PALLADINO, N J Commissioners ip 22770 009 24X
 Fithe 50-275,84/03/23,8403270005
- 8400270347 Telecopy ltr expressing view that no low power license should be granted until all safety questions & allegations resolved G'CONNELL, J California, State of DSB 142 84/03/23 PALLADINO, N Commissioners ip 22789 005 24% Fithe 50-275.84/03/23,8403270347
- 8403270352 Telecopy itr orging assurance that alleged safety hexards checked & thoroughly evaluated before granting license SRONZAN.B California, State of DSB 140 B4/03/23 PALLADINO.N Commissioners ip 22789 004 24% Fiche 50-275,84/03/23,840370392
- 8403260375 Requests opportunity to discuss OL issuance Commission should not vote on low power testing LEVY, B. SHARRE, C. Affiliation Not Assigned DSB 093 84/03/26 PALLADING, N. OLILINSKY, V. ROBERTS, T. M. Commissioners 1p 22760.138 24X Fiche 50-275.84/03/26.8403260375
- 8403260378 Requests that Commission not vote & authorization to operate not de given to facility LEVY.O. SHARPE, C. Affiliation Not Assigned DSB 092 84/03/26 ASSELBTINE-U S. DERNTHALF J. Commissioners 1p 22760 136 24X Fiche 50-275.84/03/26,8403260378

H Ceneral correspondence

- 8403010525 Responds to 840112 request that NRC deny FQ&E any type of OLfor plant Validity of allegations re design & const being evaluated Commission will not recommend that low power license be fully reinstated until evaluation complete DENTON, HR Office of Nuclear Reactor Regulation, Director 84/02/15 KNYTEON, JA Affiliation Not Assigned 3pp 22443 282 24X Flohe 50-275, 84/02/15, 8403010525
- --B403010532 Expresses concern that plant potes grave danger to environ & public health of State of CA & urges NRC to deny util any type of OL due to continuing design flaus KNUTSON-J A AFFILIAtion Not Assigned B4/01/12, DIRCKB,W NRC No Detailed Affiliation Given Ip 22443 285 24% Fiche 50-278,84/02/15.8403010525

1 Pinancial information

- 8403280051 Annual Financial Rept 1983 W/840326 ltr MIELKE,F W . SHACKELFORD.B . CRANE.P A Pacific Gas & Electric Co 83/12/31 50pp 22776 230 24X Flthe 50~000.83/12/31,8403280051
- J Insurance & Indemnity information
- 8400280033 Forwards Endorsement 40 to NELIA Policy NF-228.
 CRANEJP A Pacific Qas & Electric Co 84/03/21 BALTZMAN.J D
 Assistant Director for State & Licensee Relations 2pp 22777 044
 24X Fiche 50-225.64/03/21,8403260033
- D Advisory Committee on Reactor Bafeguards reports & correspondence
- 8403280307 Summary of ACRS Subcommittee on Extreme External Phenomena 831012 meeting w/wtil. Westinghouse, TERA & Univ of Illinois in Mashington, DC re use of tan effect methodology in seismic design analysis at Diablo Canyon Agenda encl # ACRS Advisory Committee on Reactor Bafeguards 83/11/25 ACRS Advisory Committee on Reactor Bafeguards 16pp 22808 040 24X Fiche 50-275, 83/11/25, 8400280307
- 8403290381 Notice of ACRS 840405-07 meetings in Washington, DC Agenda enci CHILK, S. J. Office of the Secretary of the Commission DSB 198 84/03/28 6pp 22814 081 24% Fiche 50-275,84/03/28,8403290381

- P Operating license stage documents & correspondence
- 8403070027 FD1A request for records re 1977 Nuclear Svcs Corp audit of Pullman Power Products
 REYNOLDS.J. Center for Law in the Public Interest 84/01/20
 Office of Administration 2pp 22592 329 24X
 Fiche 50-275,84/01/20.8403090027
- 8403010301 Forwards Board Notification 84-022 which provides in camera transcript of NRC 840125 meeting w/recipient & C Stokes Requests specific identification of names & sections in rept to be withheld from public disclosure. W/o encl EISENHUT, D O Division of Licensing 84/02/14 DEVINE, T Government Accountability Project ip 22438 335 24X Fiche 50-275,84/02/14,8403010501
- 8402090004 Board Notification 84-037 forwards Chairman Palladino 840109
 1tr transmitting rept on matters re GA Case Study C for
 plant Rept encls compare draft & final version of case study
 & include comments on draft version
 E18ENHUT.D C Division of Licensing 84/02/24 BUCK, J H ,
 MOURE, T S , JOHNSTON, W R Atomic Safety and Licensing Appeal Panel
 3pp 22549 036 24X Fichs 50-275,84/02/24,8402090004
- 8402090017 Board Notification 84-038 forwards RJ Mattson 840123 mamo to DO Eisenhut providing status update of NRC actions re Hestinghouse ECCS actuation logic EISENHUT.D O Division of Licensing 84/02/27 PALLADINO, GILINS
- --B40201050B Provides updated status of rev to Hestinghouse designed PHR ECCS actuation logic Westinghouse plans completion of evaluation for submittal by mid-Mar 1984 MATHON:R J Division of Bystems Integration (post 811005) 84/01/23 EISENHUT.D Division of Licensing 2pp 22546.007 24X Fiche 50-000,84/02/27,8402090017.
- B403150165 Requests add1 info explicitly addressing specific steps in 36CFRB00 4(b),(c),or (d) re determination of effect of operation & maint activities on SLO-2 archaeological site XNIGHTUN, Q W Licensing Branch 3 B4/02/27 BCRUYLER, J O Pacific Oas & Electric Co 4pp 22646 345 24X Fiche 50-275,84/02/27, B403150165
- 8403070075 Forwards application to amend License DPR-76, changing Tech Specs re testing requirements for HEPA filters & charcoal adsorbers, per Generic Ltr 83-13 SCHUYLER, J O Pacific Qas & Electric Co 84/02/29 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 22541 220 24X Fiche 50-275, 84/02/29, 8403070075
- --8403070079 Application to amend License DPR~76, changing Tech Specs re testing requirements for HEPA filters & charcoal adsorbers, per Generic Ltr 83-13 Justification encl. SCHUYLER, J D Pacific Oss & Electric Co 84/02/29 App 22541 221 24X Fiche 50~275,84/02/29,8403070075
- --8403070083 Proposed Tech Specs re testing requirements for HEPA filters & charcoal adsorbers, per Generic Ltr 83-13

 * Pacific Gas & Electric Co 84/02/29 10pp 22541 225 24X
 Fichu 50-275.84/02/29.8403070075
- 8403070284 Forwards application to amend License DPR-76, consisting of Amend Request 84-02, changing Tech Specs to allow entry into Mode 3 for required surveillance testing of pressurizer code safety valves
 SCHUYLER, J O Pacific Gas & Electric Co 84/02/29 DENTON, H R. Office of Nuclear Reactor Regulation, Director ip 22547.071 24X Fiche 80-275, 84/02/29, 8403070284
- --8403070288 Application to amend License DPR-76, consisting of Amend Request 84-02, revising Tech Specs to allow entry into Mode 3 for required surveillance testing of pressurizer code safety valves SCHUYLER, J. D. Pacific CM's & Electric Co. 84/02/29, 2pp 22347 072 24X Fiche 30-275,84/02/29,8403070284
- --8403070292 Proposed Tech Specs re surveillance testing of pressurizer code safety valves.

 + Pacific Gas & Electric Co 84/02/29 ip 22547 074. 24X Fiche 50-275,84/02/29.8403070284
- 8403080413 Forwards License Amend Request 84-04 to License DPR-76, changing Tech Spect to update frequency of auxiliary feedbater pump surveillance to latest ABME std value.

 86HUYLER-J.O Pacific Oas & Electric Co 84/02/27 DENTON, H R Dffice of Nuclear Reactor Republication. Director 1p 22556:242 24X Fiche 50-275:84/02/29,8403080413

- --8403080414 License Amend Request 84-04 to License DPR-76.changing Tech Spec Section 4 7 1 2 to base auxiliary feedwater pump surveillance on Tech Spec 4 0 5 8CHUYLER, J D Pacific Oas & Electric Co 84/02/29 1p 22556 243 24X Fiche 50-275.84/02/29.8403080413
- --8403080415 Proposed Tech Specs re auxiliary feedwater sys surveillance requirements

 # Pacific Gas & Electric Co 84/02/27 3pp 22556 244 24X

 Fiche 50-275,84/02/29,84030804i3
- 8403070028 Partial response to FOIA request for records re 1977 Nuclear Svcs Corp audit of Puiman Power Products Documents entirely withheld (ref FOIA Exemption 5) Review of remaining documents subj to request in progress FELTON, J M Division of Rules and Records 84/03/01 REYNOLDS, J Center for Law in the Public Interest 2pp 22572 331 24X Fiche 50-275,84/03/01,8403070028
- 8403080405 Further response to FDIA request for documents re BER related to operation of facilities Forwards App B documents App A & B documents available in PDR Review of remaining documents subj. to request in progress
 FELTON.J M Division of Rules and Records 84/03/02 QARDE, B P Government Accountability Project 4pp 22583 073 24X
 Fiche 50-275.84/03/02.8403080405
- --8312230236 Forwards responses to Allegations 7.9 & 48.per 831130 SPEIB.T P Division of Safety Technology 83/12/09 KNIOHTON.O Office of Nuclear Reactor Regulation, Director 12pp 22583 iii 24X Fiche 50-275,84/03/02,8403080405
- --8403080422 Forwards Input on Allegations 51 & 52 Fuel loading addressed In 831108 Memorandum & Order CLI-83-27 No significant safety concerns matl to fuel loading & precriticality testing warrant continuation or suspension of activities BURNS.8 Office of the Executive Legal Director 83/12/07 KNIGHTON.0 Defice of the Executive Regulation, Director 3pp 22583.108 24X Fichs 50-275,84/03/02.8403080405
- --8403080426 Forwards safety evaluations for Allegations 8.10, 11, 14, 15, 16, 17, 27, 28, 29, 31, 32, 33, 35, 36, 85, 85 & 86 Licensee approach for determining containment stability against tilting VOLLMER,R H Division of Engineering 83/12/07 EISENHUT,D 0 Division of Licensing 31pp 22583 132 24X Fiche 50-275,84/03/02,8403080405
- 8403220076 Forwards San Luis Obispo Mothers for Peace 840202 10CFR2 206 petition requesting Commission defer decision re reinstatement of low power license Written response eddressing issues requested by 840327 W/o encl DENTON/H R Office of Nuclear Reactor Regulation, Director 84/03/02 SCHUYLER.J O Pacific Oas & Electric Co 3pp 22723 298 24X Fiche 50-275,84/03/02,8403220076
- 8403150011 Forwards summary of mods, repairs or equipment changes resulting from review of allegations performed since Sept 1983, per 830304 request ECHUYLER, J D Pacific Oas & Electric Co 84/03/06 MARTIN, J B Region 5, Office of Director 2pp 22641 249 24% Fiche, 50-275, 84/03/06, 8403150011
- B403120129 Forwards policy directive for protection & retention of records re design.const & operation activities for facility Policy supersedes instructions contained in 840215 itr BCHUYLER.J O Pactfic Gas & Electric Co 84/03/08 EISENHUT, D O Office of Nuclear Reactor Regulation, Director 2pp 22590 087 24X Fiche 30-275,84/03/08,8403120129
- 8403200218 Forwards Rev 2 to Procedure EP OP-17, "Malfunction of RHR Sys," requested by ACR8 Bubcommittee on Dieblo Cenyon during 840210 meeting SCHUYLER, J.O Pacific Gas & Electric Co 84/03/12 KNIGHTON, G W Licensing Branch 3. ip 22699 337. 24x Fiche 50-275, 84/03/12, 8403200218
- --8403200220 Rev 2 to Procedure EP OP-17, "Malfunction of RHR Sys + Pacific Oas & Electric Co 82/02/19, 3pp 22699,338 24 * Pacific Gas & Electric Co 82 Fiche: 50-275, 84/03/12, 8403200218.
- 8402070041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications. EISENNUT.D @ Division of Licensing 84/03/14 Atomic Safety and Licensing Board Penei. 10pp 24X Fiche 50-000,84/03/14,8402070041
- B403220035 Forwards tables providing detailed operating experience for licensed operating personnel & licensed & nonlicensed shift technical advisors

 SCHUYLER, J O Pacific Cas & Electric Co B4/03/16 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 5pp 2271B 20B 24X Fiche: 50-275, B4/03/16, B403220035

- 8403270093 Forwards corrected page to proposed Tech Spec Page 3/4 7-17 from B40229 License Amend Request 84-03 re testing requirements for HEPA filters & charcoal absorbers SCHUYLER, J O Pacific Gas & Electric Co 84/03/21 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 22769 312 24) Fiche 50-275,84/03/21,8403270053
- --8403270057 Corrected Page 3/4 7-17 to proposed Tech Specs revising & clarifying testing requirements for HEPA fliters & charcoal absorbers # Pacific Gas & Electric Co 84/03/21 ip 22769 313 24% Fiche 50-275, 84/03/21, 8403270053
- 8403260176 Informs of plans to have shift advisors w/qualifications & training recommended by Near-Term OL Util Group on staff prior to exceeding 5% power Advisors will be subj to final exam following training SCHUYLER-J O Pacific Qas & Electric Co 84/03/23 KNIOHTON, Q W Licensing Branch 3 lp 22758 234 24% Fiche 50-275, 84/03/23, 8403260176
- 8403270366 Requests that license not be granted until allegations by employees of plant resolved MAYDEN, T California, State of 84/03/23 PALLADINO, N Commissioners 1p 22789 001 24X Fiche 50-275,84/03/29, 8403270366
- @ Inspection reports, IE Builetins & correspondence
- 8403040138 Forwards IE Insp Repts 50-275/83-39 & 50-323/83-27 on 831205-22 & notice of violation BISHDP.T W Division of Resident, Reactor Project & Engineering Programs 84/02/03 SCHUYLER, J O Pacific Cas & Electric Co 2pp 22506 334 24X Fiche 50-275.84/02/03.8403060138
- --8403060142 Notice of violation from insp on 831205-22 GANTER.H L Region 5, Office of Director 84/02/03 22306 336 24X Fiche 50-275,84/02/03,8403060138
- --8403040144 IE Insp Repts 50-275/83-37 & 50-323/83-27 on 831205-22 Noncompliance noted failure to properly implement fire loss prevention procedures & suppls SCOMN. K. POLICH. T. CANYER. H L. Region 5. Office of Oirector 84/01/24 18pp 22506 338 24X Fiche 50-275,84/02/03,8403040138
- 8403040207 Forwards IE Insp Repts 50-275/84-01 & 50-323/84-01 on NGGGGEV FORWARDS IE INSP REPTS 50-2/3/84-01 & 50-323/84-01 on B40103-05 & notice of violation B16NCP.T W Division of Restient, Reactor Project & Engineering Programs 84/02/17 SCHUYLER.J O Pacific Gas & Electric Co 22517 145 24X Fiche 50-275,84/02/17,8403060207
- --8403060214 Notice of violation from insp on 840103-06 KIRBCH.D F Region 5, Office of Director 84/02/17 22517 147 24X Fiche 50-275,84/02/17,8403060807 84/02/17 2pp
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list URDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50~000;84/02/28,8401190072
- 8403040131 Forwards IE Insp Repts 50-275/83-37 & 50-323/83-25 on 90300131 Forwards IE Insp Repts 50-273/83-37 & 50-323/83-25 on B3114-16 & 1128-1209
 BIGHOP-T W Division of Resident Reactor Project & Engineering Progrems 84/02/27 BCHUYLER, J D Pacific Oas & Electric Co 22506:273 24% Fiche 50-275,84/02/27,8403060131
- --8403060143 Natice of violation from insp on 831114-18 & 1128-1209 CANTER, H L Region 5, Office of Director 84/02/29 2pp 22506 275 24% Fiche 50-275,84/02/29,8403060131
- --8403060149 IE Insp Repts 50-275/83-37 & 30-323/83-25 on 831114-18 & 1128-1209 Noncompliance noted failure to assure that welding inspectors qualified & certified per procedural inspectors qualified & certified per procedural requirements
 HERNANDEZ, G H , ROBS, T M , KIRSCH, D F Region 5, Office of Director 84/02/29 49pp 22506 277 24X Fiche 50-275, 84/02/29, 8403060131
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enci ORACE, J N Division of OA, Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007 130pp
- B40209000B JE Info Notice B4-i6, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl, JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/02 Consolidated Edison Co. of New York, Inc. 122pp 2255 09B 24X Fiche 50-000.84/03/02.8402090008

- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases 102090007 to him house here by list encl Division of Emergency Preparedness & Engineering JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24% Fiche 50-000.84/03/02, 8402070009
- 84D2090011 IE Infa Notice 84-i7. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090022 Board Notification 84-043 submits info re exams & measurements by Parameter. Inc of radiographs & field welds & delta ferrite measurements of spiected welds under Contract NRC-03-82-249 EISENHUT, D. G. Division of Licensing NRC-05-82-249 B4/03/ PALLADING, GILINSKY. ROBERTS Commissioners 3pp 22586 247 B4/03/05 Ficha 50-275,84/03/05,8402090022
- ---8403080193 Forwards "Project Quality Plan for Providing Assistance & Svcs to Support NRC/IE Region IV Personnel in NDE & Review of Radiographs," per Task Order 56 of Contract NRC-05-82-249 NRC-05-82-249 LOFY, R A Parameter, Inc NRC-05-82-249 B3/11/23 XIRSCH, D Region 5. Office of Director 19 22556 250 24X Fiche 50-275, B4/03/05, B402090022
- ~-B403080197 "Project Buality Plan for Providing Assistance & Svcs to Support NRC/1E Region IV Personnel in NDE & Review of Radiographs at Diablo Canyon,Units 1 & 2 "FQLEY,W J , LDFY,R A Parameter, Inc NRC-05-82-249, PQP-124 83/11/22 NRC No Detailed Affiliation Given 25pp 22556 251 24X Fichs 50-275,84/03/05,84020900022
- 8403180082 Responds to NRC 840203 itr re violations noted in IE Insp Rept 50-275/83-39 Corrective actions area permits for welding posted to identify generic requirements on area basis & util inspector assigned to assist fire marshaii SCHUYLER.J O Pacific Cas & Electric Co 84/03/05 MARTIN.J B Region 5. Office of Director &pp 22446 013 24X Fiche 50-275.84/03/05.8403150082
- B403130006 Forwards description of program implemented to verify clearance between piping & penetrations in response to IE Guiletin 79-14
 SCHUYLER.JP Pacific Gas & Electric Co 84/03/QA MARTIN, J B Region 5. Office of Director 3pp 22640 324 24X
 Fiche 50-275.84/03/06/8403150006
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list enci JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 10209002B IE Info Motile Br. Sys " Sys list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Svc list encl DEYDUNG: R C Director's Office of Inspection and Enforcement B4703/12 Consolidated Edison Co of New York. Inc 134pp 22823 094 24X Fiche 30-000.84/03/12.8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthornies Entries into PWR Reactor Cavities" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fiche 50-000.84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list enci JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- 8403140244 Board Notification 84-066 forwards SECY-84-104 re NRC insp of Nuclear Syzs Corp audit of Pullman Power Products at site including draft 16 Insp Rept 50-275/83-37 & 840229 site.including draft is inspired to account top to the final rept
 EISENHUT, D.G. Division of Licensing 84/03/28 BUCK, J.H.,
 MOGRE, T.S., JOHNSON, W.R. Atomic Safety and Licensing Appeal Panel
 Dpp 22747 070 24X Piche 50-275

- -8403200301 Provides info to Commissioners re circumstances surrounding documentation of NRC insp of 1977 Nuclear Svcs Corp audit of Pullman Power Products Co
 DIRCKS.W J Office of the Executive Director for Operations
 B4/03/02 124pp 22747 073 24X Fiche 30-275,84/03/28.
 B4/03/02 124pp 2747 073 24X Fiche 30-275,84/03/28.
- R Periodic operating reports & related correspondence
- 8403020004 Monthly operating rept for Jan 1984 W/840203 1th KELLY,W J., THORNBERRY,R C Pacific Cas & Electric Co 5pp 28442 196 24x Ficha 50-275.84/01/31.8403020004
- 8403020443 Forwards monthly status rept of offsite emergency greparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency pianning issues
 DIRCKB, W.J. Office of the Executive Director for Operations
 84/02/21 PALLADINO Commissioners 9pp 22492 083 24X
 Ficha 50-000.84/02/21.8403020443
- B403230139 Forwards "Environ Investigations at Diablo Canyon, 1782 " WARRICK, J W Pacific Gas & Electric Co 84/02/20 Record Services Branch (Document Control Desk) ip 22732 341, 24x Fiche 50-275, 84/02/28, 8403230139
- --8403230141 "Environ Investigations at Diablo Canyon,1782 " CAYOT,R F , BEHRENS,D W Pacific Gas & Electric Co 83. 760pp 22732 342 24% Fiche 50~275,84/02/28,8403230137 B3/04/30
- 8403300141 Monthly operating rept for Feb 1984 W/840302 ltr KELLY, W J. THORNBERRY, R C Pacific Gas & Electric Co 84/02/29 6pp 22820 352 24X Fiche 50-275,84/02/29,8403300141
- 5 Reportable occurrences. LERs & related correspondence
- 8403150025 Special Rept 84-02 on 840123, fire water pump i declared NULLIANCES EPECIAL REPT EM-O2 ON EMPLIKES FIRE Water pump i declared inoperable after pump motor circuit breaker tripped Caused by frequent motor starts in short time period Surveillance test conducted & pump returned to svc SHIFFER.J D Pacific Gas & Electric Co 84/02/29 MARTIN.J B Region 5. Office of Director 1p 22639 023 24x Fiche 50-275,84/02/29,8403150029
- 8403080405 Further response to FDIA request for documents re SER related to operation of facilities Forwards App B documents App A & B documents available in PDR Review of remaining documents subj to request in progress
 FELTON.J M Division of Rules and Records 84/03/02 OARDE, B P.
 Government Accountability Project 4pp 22583 073 24X
 Fiche 50-275,84/03/02,8403080405
- --B403080421 Requests assistance in addressing improper design activities re use of U-bolts & code break (code boundary) design, per affidavit re allegations
 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/11/29 EISENHUT, D G Division of Licensing 15pp 22563 093 24X fiche 50-275,84/03/02,8403080405
- 8403:5012: FNO-V-84-013 on 840307: Bechtel laborer suffered heart NOSIDURE PRO-V-84-013 on BAUSS/) Because laborer suffered heart attack while working in auxiliary bldg Medical attention provided to individual at site Individual pronounced dead upon arrival at Sierra Vista Hose DDDPS-R T Region 5. Office of Director 84/03/07 ip 22640 218 24X Fiche 50-275,84/03/07,8403150121
- 8403220066 LER 84-006-00 on 840217, four 4 i6 kV circuit breakers failed to remain closed Caused by excessive wear in Teflon coated fibergiass sleeve bearings used in mechanical actuator Breakers repaired W/840319 itr KES
- T Hearing transcripts on non-antitrust matters
- 8402090032 Board Notification 84-048 forwards transcript of 840125 NOZOYOUSZ BOORG NOTIFICATION BA-048 forwards transcript of 840 meeting re allegations concerning small bore piping Review & evaluation of allegations continuing EISENHUT, D 0 Division of Licensing 84/03/13 PALLADINO, GILINSKY, ROBERTS Commissioners 3pp 67217 046 24X Fiche 50-275,84/03/13,8402090032
- --8403150136 Forwards transcript of 840125 meeting re allegations concerning small bore piping Info excised to protect confidentiality of NRC sources & preciude compromising ongoing insps BISHOP, T W Region 5, Office of Director 84/02/23 STRUMWASSER, M California, State of Fiche 50-275,84/03/13,8402070032

- --B403150144 Forwards transcript of B40125 meeting re allegations concerning small bore piping info excised to protect confidentiality of NRC sources & preclude compromising angoing insps
 BIBHOP.T W Region 5, Office of Director 84/02/23 REYNOLDS, J Center for Law in the Public Interest ip 22645 005 24X Fishs 50-275,84/03/13,8402070032
- ~~8403150152 Forwards transcript of 840125 meeting re allegations concerning small bore piping Info excised to protect confidentiality of NRC sources & preclude compromising ongoing insps
 BIBHOP, T W Region 5, Oppice of Director B4/02/23 CRANE, P A Pacific Oas & Electric Co 1p 22645 006 24X
 Fiche 50-273, 84/03/13, 84020970032
- --8403150159 Forwards transcript of 840125 meeting re allegations concerning small bore piping Info excised to protect confidentiality of NRC sources & preclude compromising angoing insps
 BISHOP.T W Region 5, Defice of Director 84/02/23 NORTON Norton, Burke, Berry & French ip 22645 007 24% Fichs 50-275,84/03/13,8402090032
- --B403150162 Excised transcript of B40125 closed meeting W/C Stokes re allegations concerning small bore piping Pp 1-220 * NRC - No Detailed Affillation Given 84/01/25 319pp 22445 008 24X Fiche 50-275.84/03/13,8402090032
- U Congressional/Executive Correspondence
- 8403260106 Provides current status of facility licensing process in response to 840126 ltr Bince B40124 hearings.NRC has continued investigation. Insp & evaluation of allegations, which will be resolved prior to low power authorization DENTON.H R Office of Nuclear Reactor Regulation, Director B4/03/09 MCCARTHY.L T California, State of 4pp 22761356, 24X Fiche 50-275,84/03/09,8403260106
- --84032&0111 Expresses concern re possibility that facility will be licensed w/o meeting safety stds MCCARTHY,L T California, State of 84/01/26 PALLADINO,N Commissioners ip 22761 359 24X Fiche 50-275,84/03/09,84032A010A
- 8403270367 Telecopy itr expressing concerns re lifting of suspended low power license Commission should carefully weigh ABLAB conclusions & fulfill responsibility to require safe plant operation THOMAS.W M House of Rep DSB 143 84/03/26 PALLADIND.N Commissioners 2pp 22787 002 24X Fiche 50-275.84/03/26.8403270367

V Operator Examinations

- B403220035 Forwards tables providing detailed operating experience for licensed operating personnel & licensed & nonlicensed shift technical advisors

 BCHUYLER.J O Pacific Ges & Electric Co 84/03/16 DENTON.H R Office of Nuclear Reactor Regulation, Director 5pp 22718 208 24X Fiche 50-275.84/03/16.8403220035
- 8403260176 informs of plans to have shift advisors w/qualifications & training recommended by Near-Term OL Util Oroup on staff prior to exceeding 3% power Advisors will be subj to final gram following training SCHUYLER.J O Pacific Gas & Electric Go 84/03/23 KN10HTON.Q W Licensing Branch 3 19 22758 234 24% Fiche 50-275, 84/03/23, 8403260176
- DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2
 F Security, medical, emergency & fire protection plans
- 8403090285 Public version of revised emergency plan implementing procedures, including Procedure EP-101 re classification of emergencies, EP-207C re first aid & EP-103 re alert response W/840210 ltr & JM Felton 840307 release meno COUNEY, M J Philadelphia Electric Co 84/01/10 MURLEY, T E Region 1, Office of Director 93pp, 22593 228 24X Fiche 50-277, 84/01/10, 8403090285
- 8403010310 Forwards IE Insp Repts 50-277/83-37 & 50-278/83-35 on 831214-840112 & notice of violation BTARDSTECKI.R Division of Project & Resident Programs 84/02/16 DALTROFF.B L Philadelphia Electric Co 2pp 22432 078 24X Fiche 50-277.84/02/16,8403010310

- --8403010322 IE Insp Repts 50-277/83-37 & 50-278/83-35 on 831214-840112 Violation noted requirements for requalification lecture attendance & supplementary training not met & adequacy of secondary containment door indicator maint unresolved DLOUGH.A R , WILLIAMS.J H , TRIPP.L E Region 1, Office of Director 84/01/19 17pp 22432 OBi 24X Fichs 50-277.84/02/16, 8403010310
- 8403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp 5 topics described in IE Info Natice 84-09 Agenda for workshop ent!

 MURLEY, T E Region 1. Office of Director Consolidated Edison Co of New York, Inc 8RONS, J C , MCNEILL, C A Power Authority of the State of New York 35pp 22672 062 24X Fiche 50-000.84/03/09.8403190243
- 8403200371 Forwards list of applications submitted & applicable fees for fire protection reviews & approvals
 MILLER, W O License Fee Management Branch 84/03/09 BAUER, E G
 Philadelphia Electric Co 3pp 22708 310 24X
 Fiche 30-277,84/03/09,8403200391
- 8403220083 Notifies of error in numbering of second insp rept encl in 840127 ltr Number should be 30-278/83-29 instead of 83-19 Corrected version encl MARTIN.T T Division of Engineering & Technical Programs 84/03/12 DALTROFF, B.L. Philadelphia Electric Co 1p 22716 268 24X Fiche 50-277,84/03/12,8403220083
- --8403220085 Forwards corrected IE Insp Repts 50-277/83-31 & 50-278/83-29 on 831114-18 & notice of violation MARTIN.7 T Division of Engineering & Technical Programs 84/01/27 DALTROFF,8 L Philadelphia Electric Co 2pp 22716 269, 24X Fiche 50-277,84/03/12,8403220083
- --8403220087 Corrected notice of violation from insp on B3J114-18 * Region I, Office of Director 84/01/27 ip 22716 271 24x Fiche 50-277,84/03/12,8403220083
- --8403220091 Corrected IE Insp Repts 50-277/83-31 & 50-278/83-29 on 831114-18 Noncompliance noted failure to meet fire brigade training requirements PULLANI.S V . ANDERSON, C J Region 1, Office of Director 84/01/03 10pp 22716 272 24X Fiche 50-277,84/03/12,6403220083
- 8403210045 Forwards application for amend to Licenses DPR-44 & DPR-56 re fire protection to reflect improvements in fire detection sys & to conform to STB BRADLEY,E J Philadelphia Electric Co 84/03/16 DENTON,H R Dffice of Nuclear Reactor Regulation, Director ip 22707 042 24X Fiche 50-277.84/03/16.8403210045
- --8403210055 Application for amend to Licenses DPR-44 & DPR-56 modifying limiting condition for operation action statement for fire barriers to reflect guidance in STS for GE BURS # Philadelphia Electric Co 84/03/16 6pp 22707 043 24X Fiche 50-277,84/03/16,8403210045
- --B403210063 Proposed Tech Specs modifying limiting condition for operation action statement for fire barriers to reflect guidance provided in STS for GE BHRs # Philadelphia Electric Co B4/03/16 3pp 22707 049 24X Fichs 50-277,84/03/16,8403210045
- B403270104 Requests extension until Oct 1984 for annual emergency preparedness exercise Extension would allow inclusion of offsite plans & use of proposed alternate emergency facility location DALTROFF, B L. Philadelphia Electric Co B4/03/20 EISENHUT, D G Division of Licensing 6pp 22769 217 24x Fiche 50-277,84/03/20. B403270104
- J Insurance & indemnity information
- 8403260054 Forwards Endorsements 106 & 107 to NELIA Policy NF-140 & Endorsement 59 to MAELU Policy MF-67
 BRADLEY, E. J. Philadelphia Electric Co. 84/03/16 BALTZMAN, J. Assistant Director for State & Licensee Relations 4pp 22750 232 24X Fiche 50-277,84/03/16,8403260054
- P Operating license stage documents & correspondence
- 8403140340 Summary of 831215 meeting w/GE & Mark I Owners Group in Bethesda.MD re Hark I containment wetwell-drywell vacuum breaker design methodology SIEGEL.B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 Sipp 22635:198 24X Fiche 50-000,84/02/21, 8403140340

- 8403070137 Forwards Amends 92 & 94 to Licenses DPR-44 & DPR-56, respectively & EIA Amends delete certain ETS re noise monitoring requirements & nonradialogical water quality-related requirements STOL7. J F Operating Reactors Branch 4 B4/02/24 DAUER.E G Philadelphia Blettric Co 3pp 22565 160 24X Fiche 50-277.84/02/24,8403070137
- --8403070141 Amends 92 & 94 to Licenses DPR-44 & DPR-56, respectively, deleting certain ETS re-noise monitoring requirements & nonradiological water quality-related requirements BTOLZ-J F Operating Reactors Branch 4 84/02/24 15pp 22565 163 24X Fiche 50-277.84/02/24.8403070137
- --8403070144 EIA supporting Amends 92 & 94 to Licenses DPR-44 & DPR-96, respectively * Office of Nuclear Reactor Regulation, Director 84/02/24 10pp 22365 179 24X Fiche 50-277.84/02/24.8403070137
- 8403150013 Forwards response to request for add1 info re Class IE electrical receway supports Design supports have sufficient margin to assure that loss of single support will not cause loss of safety function
 SCHUYLER.J O Pacific Gas & Electric Co 84/03/07 MARTIN.J B Region 5. Office of Director 3pp 22640 327 24X
 Fishe 50-277.84/03/07.8403150013
- 8403150137 Forwards application to amend Licenses DPR-44 & DPR-56, revising Tech Specs to incorporate 10CFR50, App I requirements for radialogical effluents DALTROFF.S L Philadelphia Electric Co 84/03/07 STOLZ.J F Operating Reactors Branch 4 2pp 22646 022 24X Fiche 50-277.84/03/07.8403150137
- ---8403150140 Application for amend to Licenses DPR-44 & DPR-56, revising Tech Specs to incorporate radiological effluent requirements of iOCFR50, App I BAUER, E G. BRADLEY, E J. Philadelphia Electric Co. 84/03/07 12pp 22646 024 24x Firne 50-277, 84/03/07, 8403130137
- --8403150143 Proposed Tech Spec changes, incorporating radiological affluent requirements of 10CFR50. App I * Philadelphia Electric Co 84/03/07 82pp 22646.036 24X Fiche 50-277,84/03/07,8403150137
- 8403150005 "Radiation Protection Program for Recirculatio Piping Replacement" W/840308 ltr DALTROFF.S L Philadelphia Electric Co 84/03/08 STOLZ, J F Operating Reactors Branch 4 lipp 22641 339 24X Fiche 50-277.84/03/08.8403150005
- 8403270064 Forwards revised "Diffsite Dose Calculation Manual," per NRC 830929 request re radiological effluent Tech Specs ULLRICH.W T Philadelphia Electric Co 84/03/08 PANDEY.S Franklin Institute/Franklin Research Center ip 22766 i06 24) Fiche 80-277.84/03/08.8403270064
- --8403270067 Revised 'Offsite Dose Calculation Manual "
 * Philadelphia Electric Co 84/03/08 41pp 22766 107 24X
 Fiche 50-277,84/03/08,8403270064
- 8403150275 Generic Ltr 84-07 to all litersess of BWRs re procedural guidance for pape replacement at 8WRs Svc list encl EISENNUT.D G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24% Fiche 50-000,84/03/14,8403150275
- B403210043 Forwards application for amend to Licenses DPR-44 & DPR-56 re fire protection to reflect improvements in fire detection sus a to conform to ST8
 BRADLEY, E J Philadelphia Electric Co 84/03/16 DENTON, H R
 Office of Nuclear Reactor Regulation. Director ip 22707 042 24X
 Fithe 50-277.84/03/16.8403210005
- --8403210035 Application for amend to Licenses DPR-44 & DPR-36 modifying limiting condition for operation action statement for fire barriers to reflect guidance in STS for GE BHRs * Philadelphia Electric Co 64/03/16 App 22707 043 24X Fiche 50-277,84/03/16,8403210045
- --BA03210063 Proposed Tech Specs modifying limiting condition for operation action statement for fire barriers to reflect guidance provided in STB for QC BNRs # Philadelphis Electric Co 84/03/16 3pp 22707 049 24X Fichs 50-277.84/03/16.8403210045

- G Inspection reports, 1E Bulletins & correspondence
- B403010310 Forwards IE lnsp Repts 50-277/83-37 & 50-278/83-35 on B31214-840112 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 84/02/16 DALTROFF,S L Philadelphia Electric Co 2pp 22432 078 24X Fichs 50-277.84/02/16.8403010310
- --8403010315 Notice of violation from insp on 831214-840112 * Region L. Office of Director 84/02/16 lp 22432 080 24X Fiche 50-277,84/02/16,8403010310
- ~-8403010322 IE Insp Repts 50-277/83-37 & 50-278/83-35 on 831214*840112 Violation noted requirements for requalification lecture attendance & supplementary training not met & adequacy of secondary containment door indicator maint unresolved BLOUGH.A R . WILLIAMS. J H . TRIPP.L E Region I. Office of Director 84/01/19 17pp 22432 081 24X Fiche 30-277.84/02/16.8403010310
- 8403020306 Forwards IE Insp Repts 50-277/84-05 & 50-278/84-05 on 840130 No violations nated MARTIN, T T Division of Engineering & Technical Programs 84/02/17 DALTROFF, S L Philadelphia Electric Co 2pp 22440 035 24X Fiche 50-277.84/02/17.8403020304
- ---B403020309 IE lnsp Repts 50-277/B4-05 & 50-278/B4-05 on B40130 No violations noted Major areas inspected Eastern Testing & Insp. Inc radiographs & licensee reinterpretation reader sheets

 MERCH.HW Region i, Office of Director DURR, J P Division of Engineering & Technical Programs B4/02/16 3pp 22440 037 24) Fichs 50-277,84/02/17,8403020306
- 8403090081 Forwards Suppl 4 to response to IE Bulletin 83-02, consisting of rept, "Recirculation, RHR Shutdown Cooling, Head Spray Line Reactor Info (Rev 2) "
 DALTROFF, 8 L Philadelphia Electric Co 84/02/21 MURLEY, T E Region i, Office of Director 3pp 22575 153 24X
 Fiche 50-277,84/02/21,8403090081
- --B403090089 "Retirculation RHR Shutdown Cooling.Head Spray Line.Reactor Water Cleanup Line & Core Spray Line Piping Weld Info (Rev 2)" Philadelphia Electric Co B4/02/27 61pp 2257\$ 156 24X Fiche 50-277.B4/02/21.B4030900Bi
- 8403070320 Forwards IE insp Repts 50-277/84-04 & 50-278/84-04 on B40125-27 No violations noted MARTIN,T T Division of Engineering & Technical Programs 84/02/22 DALTROFF,8 L Philadelphia Electric Co 2pp 22546 330 24X Fiche 50-277,84/02/22,8403070320
- --8403070322 IE Insp Rept 50-277/84-04 & 50-278/84-04 on 840125-27 No violations noted Major areas inspected licensee actions in response to torus med requirements & IE Bulletin 78-11 NARRUN.L. DURR.J P Region 1 Office of Director 84/02/07 3pp 22546 332 24X Fiche 50-277.84/02/22.8403070320
- 8401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp. 22909 239 24X Fiche 50-000.84/02/28,8401190072
- 8403150054 Forwards IE lnsp Repts 50-277/84-01 & 50-278/84-01 on 840105-20 Enforcement conference planned to discuss problem w/internal review process for identifying & evaluating potential unreviewed safety questions STAROSTECKI.R Division of Project & Resident Programs 84/02/27 DALTROFF.5 L Philadelphia Electric Co 2pp 22642 298 24X Fiche: 50-277.84/02/29.8403150054
- --8403150063 IE Insp Repts 50-277/84-01 & 50-278/84-01 on 840105-20. Approval of individual rod scram procedures in apparent violation of 10CFR30 59 Three examples of inadequate procedures noted BLOUGH.A R , WILLIAMS, J H , TRIPP, L E Region 1, Office of Director. 84/02/28 12pp 22642 300 24X Fiche.50-277,84/02/29,8403150054
- B402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Eve list encl ORACE.J N Division of GA. Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc. 130pp 22552:329 24% Ficha 50-000.84/03/02.8402090007

- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22503 098 24% Fiche 50-000.84/03/02, 8402090008
- 8402070007 1E Info Notice 84-15, "Reporting of Radiological Releases" 8vc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 28553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Llquid Nitrogen Cooling Components Below Nil Ductillty Temp " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403070131 Forwards description of plans for recirculation & RHR syspiping replacement during upcoming Unit 2 refuel outage per IE Builetin 83-02 Mod/refueling outage work should be completed within 32 ubs Two oversize drawings encl DALTROFF, 8 L Philadelphia Electric Co 84/03/04 STOLZ, J F Operating Reacture Branch 4 21pp 22548 275 24X Fiche. 30-277,84/03/06.8403070131
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys." Svc list and JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consoildated Edison Co of New York, Inc isop 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Byc list enc! JURDAN,E L Division of Emergency Preparedness & Englneering Response (Post 830103) 84/03/07 Consoildated Edison Co of New York, Inc 118pp 22584 186 24X Flche 50-000,84/03/07,8402090028
- 840209003i IE Bulletin 84-02. "Fallures of OE Type HFA Relays in Use in Class IE Bafety Sys " Svc list encl DEYOUNG, R C Director's Defice, Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc i34pp. 22823 094 24% Fiche 50-000.84/03/12,8402090031
- 8403220083 Notifies of error in numbering of second inspirely encl in 840i27 ltr Number should be 50-278/83-29 instead of 83-i9 Corrected version encl MARTIN.T T Division of Engineering & Technical Programs 84/03/12 DALTROFF,S L Philadelphia Electric Co ip 22716 268 24X Fichs 50-277,84/03/12,8403220083.
- --8403220085 Forwards corrected IE Insp Repts 50-277/83-31 & 50-278/83-29 on 83i14-18 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 84/01/27 DALTROFF.8 L Philadelphia Electric Co 2pp 22716:269 24X Fiche 50-277,84/03/12,8403220083
- --8403220087 Corrected notice of vibiation from insp on 831114-i8 * Region i, Office of Director 84/01/27 ip. 22716 271 24X Fiche 50-277,84/03/12,8403220083
- --8403220091 Corrected lE Insp Repts 50-277/83-31 & 50-278/83-29 on B3il14-i8 Noncompliance noted failure to meet fire brigade training requirements PULSANI,8 V , ANDERSON.C J Region i. Office of Director B4/01/03, 10pp 22716-272 24X Fiche 50-277,84/03/12,8403220083
- 8402090043 IE Info Notice 84-19, "Two Eyents Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURDAN/E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21. Consolidate Edison Co of New York, Inc 123pp 22823 229, 24X Fichs 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice B4~20, "Syc Life of Relays in Safety-Related Bys." Syc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/21 Consolidated Edison Co. of New York: Inc. 135pp 22933 001 24X Fiche 50-000.84/03/21.8402090044
- 8403270250 Forwards response to 840207 request for add1 info re IE Bulletin 80-ii, "Masonry Wall Design." Min reinforcement for all block walls exceeds requirements.

 DALTROFF, S.L. Philadelphia Electric Co. B4/03/21. STOLZ. J F Operating Reactors Branch 4. Spp. 22772, 097. 24X Fichs. 50-277, 84/03/21, 8403270250

- R Periodic operating reports & related correspondence
- 8403050i17 "Semiannual Effluent Releases Rept 16.Jul-Dec 1983" W/ 840229 ltr ALDEN,W M Philadelphia Electric Co 83/12/31 MVRLEY.T E Region 1. Defice of Director 19pp 22488 016 24X Fiche 50-277.83/12/31. 8403050117
- 8403190198 Monthly operating repts for Feb 1984 W/840313 ltr ALDEN,W M , ULLRICH,W T Philadelphia Electric Co 84/02/29 10pp 22671 132 24X Fiche 50~277,84/02/29,8403190198
- 8 Reportable occurrences, LERs & related correspondence
- 8403010358 LER 84-001-00 on 840117, during surveillance testing of RHR B injection valve MO 2-101548, valve failed to reopen Caused by warping of Bakelite coll & core housing within motor control ctr Thermal overload device replaced W/840927 ltr CLARK.8 L , LOQUE.R H Philadeiphia Electric Co 84/02/27 4pp 22433 009 24K Fiche 50-277,84/02/27,8403010358
- 8403i20085 LER 84-003-00 on 84013i operator failed to taks corrective action rapidity enough to contain reactor coolant temp, ailowing heatup rate to reach 120 F Caused by personnel error Operator disciplined W/840301 ltr CLARK, 8 L , ULRICH.W T Philadelphia Electric Co 84/03/01 4pp 22588 179 24X Fiche 50-277,84/03/01,8403i20080
- B403200019 LER B4-004-00 on B40213 during local leak rate tests on RHR sys B valves, packing leak discovered on test iine isolation valve MD2-10-34B Caused by loose packing Packing tightened & valve stroke tested W/B40314 ltr CLARK, B L , ULLRICH, W T Philadelphia Electric Co B4/03/14 4pp 2269B 350 24X Fiche 50-277, 84/03/14, 8403200019
- BOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8403090285 Public version of revised emergency plan implementing procedures, including Procedure EP-101 re classification of emergencies, EP-207C re first ald \$ EP-103 re alert response W/B402i0 ltr & /M Felton B40307 release memo COUNEY, M J Philadelphia Electric Co B4/01/10 NURLEY, T E Region i, Office of Director 93pp 22593 228 24X Fiche 50-277,84/01/10,8403090285
- 8403010310 Forwards IE Insp Repts 50-277/83-37 & 50-278/83-35 on 831214-840112 & notics of violation STAROBIECKI.R Division of Project & Resident Programs 84/02/16 DALTROFF.8 L Phisadelphia Electric Co 2pp 22432 078 24X Fiche 50-277.84/02/16.8403010310
- --B403010322 IE Insp Repts 50-277/83-37 & 50-278/83-35 on 83:214-840i12 Violation noted requirements for requalification letture attendance & supplementary training not met & adequacy of secondary containment door indicator maint unresolved BLOUGH. A R Region 1. Office of Director B4/0i/19 i7pp 22432 081 24% Fiche 50-277.84/02/16.8403010310
- 8403190243 Notification of 840418 workshop in King of Prussla, PA to discuss lassons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop enci MURLEY, T & Region 1, Office of Director 84/03/09 O'TOOLE, J D Consolidate Edison Co of New York, Inc CAREY, J J Duquesne Light Co MARTIN, T J Public Service Electric & Gas Co of New Jersey 35pp. 22472 042 24X Fiche 50-000.84/03/09,8403190243
- B403200391 Forwards list of appilcations submitted & appilcabls fees for fire protection reviews & approvais
 MILLER.W O License Fee Management Branch 84/03/09 DAUER.E & Philadelphia Electric Co 3pp 22708 310 24X
 Flchs 50~277,84/03/09.8403200391
- 8403220083 Natifles of error in numbering of second insp rspt encl in 840127 ltr Number should be 50-278/83-29 instead of 83-19 Corrected version encl.

 MARTIN.T T Division of Enginsering & Technical Programs B4/03/12 DALTROFF,S L Philadelphia Electric Co lp 22716 268 24% Fiche 50-277,84/03/12,8403220083
- --B4032200B5 Forwards corrected 1E Insp Repts 50-277/B3-31 & 50-278/B3-29 on B31114-1B & notice of violation MARTIN:T T Division of Engineering & Technical Programs B4/01/27 DALTROFF.8 L Philadelphia Electric Co 2pp 22716 269 24X Fichs 50-277.B4/03/12,84032200B3

- --8403220087 Corrected notice of violation from insp on 831114-i8 * Region i, Office of Director 84/01/27 ip 22716 271 24K Fiche 50-277,84/03/12,8403220083
- --8403220091 Corrected IE Insp Repts 50~277/83-31 & 50-278/83-29 on B311(4-18 Noncompliance noted failure to meet fire brigade training requirements PULLANI,S V Region I. Office of Director 84/0i/03 10pp 22716 272 24X Fichs 50-277,84/03/12,8403220083
- 8403210045 Forwards application for amend to Licenses DPR-44 & DPR-56 re fire protection to reflect improvements in fire detection sys & to conform to STS BRADLEY, E. J. Philadelphia Electric Co. 84/03/14 DENTON. H.R. Office of Nuclear Reactor Regulation, Director 1p 22707 042 24X Fiche 50-277.84/03/16.8403210045
- --B403210055 Application for amend to Licenses DPR-44 & DPR-56 modifying limiting condition for operation action statement for fire barriers to reflect guidance in STS for OE BHRs * Philadelphia Electric Co B4/03/16 6pp 22707 043 24X Fiche 50-277,84/03/16,8403210045
- --8403210063 Proposed Tech Specs modifying limiting conditions for operation action statement for fire barriers to reflect guidance provided in STB for GE BWRs w Philadelphia Electric Co 84/03/16 3pp 22707 049 24X Fiche 50-277,84/03/16.8403210045
- 8403270104 Requests extension until Oct 1984 for annual emergency preparedness exercise Extension would allow inclusion of offsite plans & use of proposed alternate emergency facility location DALTROFF. S.L. Philadelphia Electric Co. 84/03/20 EISENHUT. D. G. Division of Licensing. 6pp. 22749 217. 24X Fiche: 50-277.84/03/20.8403270104
- J. Insurance & indemnity information
- B403260054 Forwards Endorsements 106 & 107 to NELIA Policy NF-140 & Endorsement 39 to MAELU Policy MF-67 RADLEY,E J Philadelphia Electric Co 84/03/16 BALT2MAN,J Assistant Director for State & Licensee Relations 4pp 22750 232 24% Fiche 50-277,84/03/16.8403260054
- P Operating license stage documents & correspondence
- 8403140340 Summary of B31215 meeting w/OE & Mark I Owners Group in Bethesda.MD re Mark I containment wetwell-drywell vacuum breaker design methodology BIEGEL.B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fiche 50-000.84/02/21, 8403140340
- 8403070137 Forwards Amends 72 & 74 to Licenses DPR-44 & DPR-36, respectively & EIA Amends delete certain ETS re noise monitoring requirements & nonradiological water quality-related requirements
 STDLZ, J F Operating Reactors Branch 4 84/02/24 BAUER, E 0 Philadelphia Electric Co 3pp 22565 160 24X
 Fiche 50-277 84/02/24,8403070137
- --8403070141 Amends 92 & 94 to Licenses DPR-44 & DPR-36, respectively, deleting certain ETS re-noise monitoring requirements & nonradiological water quality-related requirements BTOLZ-J F Operating Reactors Branch 4 84/02/24 15gp 22365 163 24X Fiche 50-277,84/02/24,8403070137
- --B403070144 EIA supporting Amends 92 & 94 to Licenses DPR-44 & DPR-56, respectively # Office of Nuclear Reactor Regulation. Director 84/02/24 10pp 22565 179 24X Fiche 50-277.84/02/24.8403070137
- 8403i50i37 Forwards application to amend Licenses DPR-44 & DPR-56, revising Tech Specs to incorporate 10CFR50, App I requirements for radiological effluents
 DALTROFF, S. Philadelphia Electric Co. 84/03/07 STDLZ, J. F. Operating Reactors Branch 4. 2pp. 22646:022 24X
 Fiche 50-277, 84/03/07, 8403i50i37
- --8403150140 Application for amend to Licenses DPR-44 & DPR-56, revising Tech Specs to incorporate radiological effluent requirements of IOCFR50. App 1.

 BAUER, E G. BRADLEY, E J. Philadelphia Electric Co. 84/03/07 12pp 22646 024 24% Fiche 50-277.84/03/07.8403150137.
- --8403150143 Proposed Tech Spec changes, incorporating radiological effluent requirements of IOCFR30.App I * Philadelphia Electric Co. 84/03/07 82pp 22646 036 24X Fichs 50-277.84/03/07.8403150137

- B403270064 Forwards revised "Offsite Dose Calculation Manual," per NRC B30929 request re radiological effluent Tech Specs ULLRICH.W T Philadelphia Electric Co 84/03/08 PANDEY.B Franklin Institute/Franklin Research Center ip 22766 106 24X Fiche 50-277.84/03/08.8403270064
- 8403150275 Ceneric Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc list encl EIBENNUT.D G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22223 354 24X Fiche 50-000.84/03/14.8403150275
- 8403210045 Forwards application for amend to Licenses DPR-44 & DPR-56 re fire protection to reflect improvements in fire detection sys & to conform to 8T8 BRADLEY.E J Philadelphia Electric Co 84/03/16 DENTON,H R Office of Nuclear Reactor Regulation, Director ip 22707.042 24X Fiche 50-277,84/03/16.8403210045.
- --84032i0055 Application for amend to Licenses DPR-44 & DPR-56 modifying limiting condition for operation action statement for fire barriers to reflect guidance in 878 for 0E BNRs * Philadelphia Electric Co 84/03/16 App 22707 043 24X Fiche 50-277,84/03/16.84032i0045
- --8403210063 Proposed Tech Specs modifying limiting condition for operation action statement for fire barriers to reflect guidance provided in STS for OE DNRs * Philadelphia Electric Co 84/03/16 3pp 22707 049 24X Fichs 50-277.84/03/16.8403210045
- Q Inspection reports, IE Bulletins & correspondence
- 8403010310 Forwards LE Insp Repts 50-277/83-37 & 50-278/83-35 on B31214-840112 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 84/02/16 DALTROFF, S L Philadelphia Elsectric Co 2pp 22432 078 24X Fichs 50-277,84/02/16,8403010310
- --8403010315 Notice of violation from insp on 831214-840112 * Region i, Office of Director 84/02/16 ip 22432 080 24X Fiche 50-277.84/02/16.8403010310
- ---B403010322 IE lnsp Repts 50-277/83-37 & 50-278/83-35 on 83:214-840:12
 Violation noted requirements for requalification lecture
 attendance & supplementary training not met & adequacy of
 secondary containment door indicator maint unresolved
 BLOUGH, A R , WILLIAMS, J H , TRIPP, L E Region 1. Office of
 Director 84/01/19 17pp 22432 OB1 24X Fiche 50-277,84/02/16,8403010310
- 8403020306 Forwards IE Insp Repts 50-277/84-05 & 50-278/84-05 on B40130 No violations noted MARTIN,T T Division of Engineering & Technical Programs. 84/02/17 DALTROFF,S L Philadelphia Electric Co 2pp 22440 035 24X Fiche 50-277.84/02/17.8403020306
- --8403020309 IE Insp Repts 50-277/84-03 & 50-278/84-05 on 840130 No violations noted Major areas inspected Eastern Testing & Insp. Inc radiographs & licensee reinterpretation reader sheets

 KERCH. H W Region i, Office of Director DURR, J P Division of Engineering & Technical Programs 84/02/16 3pp 22440 037 24X Fiche 50-277,84/02/17,8403020306
- 8403070320 Forwards IE Insp Repts 50-277/84-04 & 50-278/84-04 on 840125-27 No violations noted MARTIN.T T Division of Engineering & Technical Frograms. 84/02/22 DALTROFF,8 L Philadelphia Electric Co 2pp 22546 330 24X Fiche.50-277.84/02/22.8403070320
- --8403070322 IE Insp Rept 50-277/84-04 & 50-278/84-04 on 840125-27 No violations noted Major areas inspected licensee actions in response to torus mod requirements & IE Bulletin 78-11 NARROM, L., DURR, J. P. Region 1. Office of Director 84/02/07 3pp 22545 332 24X Fiche, 50-277, 84/02/22, 8403070320.
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valva Control Circuits & Annunciation " Svc list ent!

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072

- B403130054 Forwards IE Insp Repts 30-277/84-01 & 50-278/84-01 on 840105-20 Enforcement conference planned to discuss problem w/internal review process for identifying & evaluating potential unreviewed safety questions STAROBTECKIR Division of Project & Resident Programs 84/02/29 DALTROFF, S L Philadelphia Electric Co 2pp 22642 298 24x Fichs 50-277,84/02/29,8403150054
- --B403150063 IE Insp Repts 50-277/84-01 & 50-278/84-01 on 840105-20 Approval of individual rod scram procedures in apparent violation of IOCFR50 57 Three examples of inadequate procedures noted BLOUGH.AR., HILLIAMS.J.H., TRIPP.L.E. Region I. Office of Director 84/02/28 12pp 22642 300 R4X Fiche 50-277.84/02/29.8403150054
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE.J N Division of GA. Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- E402090009 IE Info Notice 84-15. "Reporting of Radiological Releases"

 Bvc list entl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co. of New
 York, Inc 117pp 22553 217 24X Fichs 50-000, 84/03/02, 8402090009
- B402090011 IE Info Notice 84-17, "Problems H/Llquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/05 Consolidate Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche 50-000, 84/03/05, 8402090011
- 8402090024 IE Info Notice 84-09, Rev 1: "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp. 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Btress Corrosion Cracking in PWR Sys." Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24% Fichs 50-000,84/03/07,8402070028
- 8402090031 IE Bulletin 84-0R, "Failures of GE Type HFA Relays in Use in Clars IE Safety Sys " Syc list encl DEYQUNG: R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 194pp 22823:094 24X Fiche 50-000:84/03/12:8402090031
- 84032R0083 Notifies of error in numbering of second insp rept encl in 840127 ltr Number should be 50-278/83-29 instead of 83-19 Corrected version encl MARTIN, T.T. Division of Engineering & Technical Programs B4/03/12 DALTROFF, B L. Philadelphia Electric Co. ip 22716 268 24X Fiche, 50-277, 84/03/12, 8403220083
- ---8403220085 Forwards corrected 1E Insp Repts 50-277/83-31 & 50-278/83-29 on 831114-18 & notice of violation MARTIN:T T Division of Engineering & Technical Programs 84/01/27. DALTROFF:8 L Philadelphia Electric Co 2pp 22716.269 24X Fiche 50-277.84/03/12:8403220083.
- --8403220087 Corrected notice of violation from insp on 831114-18 * Region 1. Office of Director 84/01/27 lp. 22716.271 24X Fiche 50-277.84/03/12.8403220083
- --E403220091 Corrected IE Insp Repts 50-277/83-31 & 50-278/83-29 on B31114-18 Noncompliance noted failure to meet fire brigade training requirements.
 PULLANI, S V . ANDERSON, C J Region 1, Office of Director B4/01/03 10pp 22716-272 24X Fiche 50-277, 84/03/12, 8403220083
- B402070043 IE Info Notice B4-19, "Twp Events Involving Unauthorized Entries into PWR Reactor Cavities." Syc list encl.
 JURDAN, EL Division of Remergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229, 24X Fiche 50-000,84/03/21.8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Bafety-Related 8ys," Svc list encl. JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp. 22933 001 24X Fiche 50-000,84/03/21,8402070044

- 8403270250 Forwards response to 840207 request for add1 info re IE Bulletin 80-11, "Masonry Wall Design " Min reinforcement for all block walls exceeds requirements
 DALTROFF.B L Philadelphia Electric Co 84/03/21 STOLZ, J F Operating Reactors Branch 4 8pp 22772 097 24X Fiche 50-277.84/03/21.8403270250
- R Periodic operating reports & related correspondence
- 8403050117 "Semiannual Effluent Releases Rept 16, Jul-Dec 1983 " W/ 840229 Itm ALDEN.W M Philadelphia Electric Co 83/12/31 MURLEY.T E Region 1. Office of Director 12pp 22488 016 24X Fiche 50-277, 83/12/31,
- 8403190198 Monthly operating repts for Feb 1984 W/840313 1tm ALDEN.W H : ULLRICH.W T Philadelphia Electric Co 84/02/29 10pp 22671 132 24X Fichs 50-277.84/02/29.8403190198
- 8 Reportable occurrences. LERs & related correspondence
- B403120175 LER B4-002-00 on B40124, during unit startup, calculational error resulted in reactor heatup rate of iil F/h Caused by personnel error Heatup rate immediately reduced W/B40223 ltr
 CLARK, B L , ULLRICH, W T Philadelphia Electric Co 84/02/23 4pp 22570 197 24% Fiche 50-278, 84/02/23, 8403120175
- B403120019 LER B4-004-00 on B40125 reactor coolant temp dropped below 120 F when feedwater inadvertently pumped into reactor vessel Caused by operator error Level restored to normal & main steam line drains opened H/B40301 ltr CLARK, B L . ULLRICH, M T Philadelphia Electric Co 84/03/01 4pp 22586 264 28x Fiche 50-278, B4/03/01, B403120019
- 8403130158 LER 84-005-00 on 840209; reactor auto scram on high neutron flux occurred due to runback & subsequent relay failure in main turbine electrohydraulic control sys Caused by faulty relay contact Relay replaced W/840307 ltr CLARK, B L , ULLRICH, W T Philadelphia Electric Co 84/03/07 4pp 22599 152 24% Fiche 50-278, 84/03/07, 8403130158
- DOCKET 50-280 SURRY POWER STATION, UNIT 1

 F Becurity, medical, emergency & fire protection plans
- 8403070239 Forwards 8ALP Repts 50-280/83-33,50-281/83-35,50-338/83-33 & 50-337/83-33 for Oct 1782 Aug 1983 Evaluation will be discussed at 831208 meeting at North Anna site LEWIS.R C Division of Project & Resident Programs 83/11/25 STEWART.W L Virginia Electric & Power Ca 2pp 22536 227 24X Fiche 50-000.83/11/25.8403070239
- --8403070246 BALP Repts 50-280/83-33.50-281/83-35.50-338/83-33 & 50-339/83-33 for Oct 1982 Aug 1983 Reliable performance w/improvement in most previously noted areas of weakness demonstrated * Region 2, Office of Director 83/11/25 42pp 22536 229 24x Fiche 50-000,83/11/25,8403070239
- 840ii30314 Supplemental info to 80i028 application to amend Licenses DRR-31 & DRR-37 re fire pump flow testing Justification for capability of fire pumps to provide adequate fire protection provided STEWART.W L. Virginia Electric & Power Co. 84/01/09 DENTON, H.R. Office of Nuclear Reactor Regulation, Director VARGA, S.A. Operating Reactors Branch i 2pp 21798 313 24X Fichs 50-280,84/01/09,8401130314
- 8403280125 Public version of Rev 9 to Emergency Plan Implementing Procedure EPIP-1 OI. "Emergency Manager Controlling Procedure " W/940123 Itr & JM Folton 840322 release memo. WILSON.J. GRADY.D. STEWART.W L. Virginia Electric & Power Co 64/01/13 O'REILLY.J P Region 2. Office of Director 5pp 22811 082 24X Fiche. 50-280.84/01/13.8403280125
- 8403070250 Forwards IE lnsp Repts 50-280/83-37 & 50-281/83-39 on 831201-31 No violations or deviations identified DANGE, H C Division of Project & Resident Programs 84/02/10 STEMART, H L Virpinia Electric & Power Co 2pp 22546 016 24X Fiche 50-280,84/02/10,8403070250
- --8403070253 IE Insp Repts 50-280/83-37 k 50-281/83-39 on 83:201-31 No violations or deviations identified Major areas inspected operations:plant security, followup of events k LERs, performance appraisal insp findings & surveillance review BURKE:D J . DAVIS; M J Region 2. Office of Director ELROD; 8 Division of Project & Resident Programs 84/02/07 7pp 22546 018 24X Fichs 50-280.84/02/10,8403070250

- 8403070242 Rev 4 to Emergency Plan Implementing Procedure EPIP-4 23, "Post-Accident Bampling of Reactor Coolant" W/840302 ith SIEWART.W L Virginia Electric & Power Co 84/02/16 O'RESLLY.J P Region 2. Office of Director 22pp 22573 228 24X Fiche 30-260.84/02/16.8403090242
- 8403200114 Forwards changes to sacurity personnel training qualification program Changes withheld (ref 10CFR73 21) STEWART, W L. Virginia Electric & Power Co. 84/02/17 D'REILLY, J P. Region 2, Office of Director. p. 22685 335 24X Fiche 50-280.84/02/17.8403200116
- 8403190263 Rev 1 to corporate emergency response plan W/840315 ltr STEWART, W L. Virginia Electric & Power Co. 84/02/24 O'REILLY, J P Region 2. Office of Director 105pp 22670 135 24X Fiche 50-000.84/02/24.8403190263
- 8403060377 Forwards correction to B30217 ltr re revised pages to amergency plan implementing procedures W/o enci SALYERS:E M Virginia Electric & Fower Co 84/02/29 NRC No Detailed Affiliation Given 1p 22518 133 24X Fiche 50-280.84/02/29.8403060397
- 8403080264 Forwards "Control Room Design Review Program Plan for North Anna & Surry Power Stations," In response to Suppl 1 to NUREO-0737 Review expected to be completed by 850830 STEMART.W L. Virginia Electric & Power Co. 84/03/01 DENTON:H R Office of Nuclear Reactor Regulation. Director EISENHUT.D G Division of Licensing 2pp 22557 275 24X Fiche 50-000,84/03/01. B403080264
- --84030B0269 "Control Room Design Review Program Plan for North Anna & Surry Power Stations." in response to Suppl 1 to NAREO-0737 e Virginia Electric & Power Co 84/03/01 11ipp 22557 299 244 Fiche 50-000.84/03/01.8402080264
- 8403210117 Rev 11 to Emergency Plan Implementing Procedure EPIP-1 01, "Emergency Manager Controlling Procedure" & Rev 6 to Procedure EPIP-2 01, "Notification of State & Local Govts " #/840316 ltr # Virginia Electric & Power Co 84/03/01 D'REILLY, J P Region & Office of Director Opp 22703 067 24X Fiche 30-280,84/03/01, 8403210117
- 840308009: Submits add1 info in order to conduct detailed review of emergency response procedures generation package.psr 840125 request items : & 2 will be addressed by 840530 Item 3 should be addressed by Westinghouse Dwners Oroup STEWART, W. L. Virginia Electric & Power Co. 84/03/02 DENTON, W. R. Office of Nuclear Reactor Regulation, Director EISENHUT, D. O. Division of Licensing 2pp 22559 199 24X Fiche 50-000.84/03/02.84036009:
- 8403090151 Revised emergency plan implementing procedures, including Rev ii to EPIP-i OI, "Emergency Manager Controlling Procedure" 5 Rev 6 to EPIP-2 OI, "Notification of State & Local Govts " H/840302 Itr SALYERS,E N Virginia Electric & Power Co 84/03/02 69p 22575 046 24X Fiche 50-280,84/03/02,8403090151
- 8403160276 Extends invitation to attend 840316 workshop at regional off to discuss 10CFR50. App R requirements & results of insps to help resolve misunderstandings associated w/requirements LEMIS.R C Division of Project & Resident Programs 84/03/02 STEMART.U L Virginia Electric & Power Co 1p 22660 080 24X Fiche 50-000.84/03/02.6403160276
- 8403150077 Forwards IE Safeguards Insp Repts 50-280/84-06 & 50-281/84-06 on 840227-0302 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/03/07 STEMART.W L Virginia Electric & Power Co 2pp 22639 300 24% Fiche 50-280.84/03/09.8403150097
- --8403150107 IE Saftguards insp Repts 50-280/84-06 & 50-281/84-06 on 840327-0302 No noncompliance noted Major areas inspected security organization/mgt.personnel response.records & repts & testing Details withheld (ref iOCFR73 21 & 2 790) ENNIS.U D. HCGUIRE.D R. Region 2. Office of Director 84/03/09 ip 22639 302 24X Fiche 50-280,84/03/09.8403150099
- 8403190052 Informs that local emergency operations facilities at North Anna & Surry Power Stations will be functional, except for data communications & display, by 850731, per NUREO-0737, Suppl 1
 STEHART, W. L. Virginia Electric & Power Co. 84/03/14 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. 0
 Division of Licensing 2pp 22866 173 24% Fiche 50-000, 84/03/14, 8403190032

- B403230146 Rev 7 to Emergency Plan Implementing Procedure EPIP-2 01. "Notification of State & Local Govts " W/840316 ltr BALYERB.E M Virginia Electric & Power Co 84/03/16 3pp 22730 228 24% Fiche 30-280,84/03/16,8403230146
- J Insurance & indemnity information
- 8403140065 Endorsement 55 to MAELU Policy MF-57 * Mutual Atomic Energy Liability Underwriters 83/12/14 ip 22634 183 244 Fiche 50-280.83/12/14.8403140065
- 8403140067 Endorsement 72 to NELIA Policy NF-186

 * Nuclear Energy Liability Insurance Association 83/12/14 lp 22633 083 24x Fiche 50-280,83/12/14,8403140067
- 8403140034 Endorsement 35 to NELIA Policy N8-314

 * Nuclear Energy Liability Insurance Association 84/03/01 ip 22633 064 24% Fiche 50-280,84/03/01,8403140054
- 8403140059 Endorsement 74 to NELIA Policy NF-185

 * Nuclear Energy Liability Insurance Association 84/03/01 1p
 22634 182 24% Fiche 50-280,84/03/01,8403140059
- P. Operating license stage documents & correspondence
- 8401130314 Supplemental info to 801028 application to amend Licenses DRR-31 & DRR-37 re firs pump flow testing Justification for capability of fire pumps to provide adequate fire protection provided STEMART, W.L. Virginia Electric & Pawer Co. 84/01/09 DENTON, H.R. Office of Nuclear Reactor Regulation, Director VARGA, S.A. Operating Reactors Branch 1 2pp 21798 313, 24X Fiche SD-280.84/01/09.8401130314
- B403050230 "Radionuclide Release Under Specific LHR Accident Conditions: "Vol V. "PWR-Large, Dry Containment (Surry Recalculations)" ("OIESEKE, J A. CYBULEKIB, P. DENNING, R. B. Battelle Memorial Institute, Columbus Laboratories 8403050230 84/01/12 Office of Nuclear Regulatory Research, Director 212pp 22502.001 24X Fiche 30-280.84/01/12,8403050230
- 8403080339 Final response to FOIA request for documents re NRC investigation of industrial accident involving burst steam pipe at facility "VEPCO Investigative Board Preliminary Rept" on accident placed in PDR FELTON, J M Division of Rules and Records 84/01/20 CARDE, B P Government Accountability Project ip 22076 214 24X Ficha 50-280,84/01/20,8403080339
- B403160269 Confirms B40208 telcon re functional testing of snubbers Add1 functional testing of Unit i snubbers per Tech Spec 4 17 C 6 will be completed during feb 1984 maint outage Unit 2 testing to be completed during Mar 1984 maint outage LEMIS.R C Division of Project & Resident Programs 84/02/13 STEMART.W 1 Urigina Electric & Power Co 1p 22660.334 24X Fiche 50-200.84/02/13.8403160269
- B403020054 Forwards Amends 95 & 94 to Licenses DPR-32 & DPR-37, respectively & safety evaluation Amends revise Tech Specs to change min boron injection tank boron concentration from 11 5% to 0% NEIGHBORS, J D. Operating Reactors Branch 1 84/02/24 BTEWART, W. L. Virginia Electric & Power Co. 2pp. 22491 018 24% Fiche 50-280, 64/02/24, 8403020054
- --B403020058 Amends 95 & 94 to Licenses DPR-32 & DPR-37.respectively, revising Tech Bpecs to change min boron injection tank boron concentration from 11 5% to 0% & changing boric acid sys boron concentration from 11 5% to 7% VAROA,8 A Operating Reactors Brench 1 84/02/24 18pp 22491 020 24% Fiche 50-280,84/02/24,8403020054
- --840302006i Safety evaluation supporting Amends 95 & 94 to Licenses DPR-32 & DPR-37.respectively 4 Office of Nuclear Reactor Regulation, Director 84/02/24, 7pp 22491 038 24X Fichs 50-280,84/02/24,8403020054.
- B403020195 Forwards addi info to complete review of Topical Rept VEP-FRD-41, "VEPCO Reactor Sys Transient Analysis Using RETRAN Computer Gode." in response to NRC Nov 1982 informal request STEHART, W.L. Virginia Electric & Power Co. 84/02/27. DENTON, H.R. Office of Nuclear Reactor Regulation, Director EISENHUT, D.O. Division of Licensing lapp 22443 257 24X Fiche 50-000,84/02/27. B403020495

- 8403050229 Submits review of post-accident sampling sys, Item II B 3 Ten of 11 Criteria met Remaining criterion re procedure for estimating extent of core damage based on radionuclide evaluation.acceptable on interim basis
 MILLER, J R Derating Reactors Branch 3 84/02/27 STEWART, W L
 Virginia Electric & Power Co 6pp 22528 001 24X
 Fiche 50-000,84/02/27,8403050229
- 8403260105 Supplemental application for amend to Licenses DPR-32 & DPR-37 Suppl reflects change in title of fire marshal to loss prevention supervisor & deletes NDE supervisor STEMART. U. Virginia Electric & Power Co. 84/03/22 DENTON, H.R. Defice of Nuclear Reactor Regulation, Oirector VAROA, 8 A Operating Reactors Branch 1 5pp 22758 238 24X Fiche 50-280,84/03/22,8403260105
- --8403260iiO Proposed Tech Spec, changing organization title of fire marehal to lose prevention supervisor & deleting NDE supervisor position * Virginia Electric & Power Co 84/03/22 2pp 22758 243 24X Ficha 50-280,84/03/22
- Q Inepection reporte, IE Bulletine & correspondence
- 8403070237 Forwards SALP Repts 50-280/83-33,50-281/83-35,50-338/83-33 & 50-337/83-33 for Oct 1982 Aug 1983 Evaluation will be discussed at 831200 meeting at North Anna site LEWIS.R C Division of Project & Resident Programs 83/11/25 STEWART,W L Virginia Electric & Power Co 2pp 22534 227 24x Fiche: 50-000,83/11/25,8403070239
- --8403070246 SALP Repts 50-280/83-33.50-281/83-35.50-338/83-33 & 50-337/83-33 for Oct 1982 -- Aug 1983 Reliable performance w/improvement in most previouely noted areas of weakness demonstrated ** Region 2. Office of Director 83/11/25 42pp 22536 229 24X Fiche 30-000,83/11/25,8403070239
- 8403080339 Final response to FOIA request for documents re NRC investigation of industrial accident involving burst steam pipe at facility "VEPCO Investigative Board Preliminary Rapt" on accident placed in PDR FELTON.J M Division of Ruiss and Records 84/0i/20 GARDE, B P Government Accountability Project ip 22576 214 24X Fiche 50~280,84/0i/20,8403080339
- --840308034i "VEPCO Investigative Board Preliminary Rept " W/o cover sheat * Virginia Electric & Power Co 84/0i/20 29pp 22576,2i5 24x Fiche 30-280,84/0i/20,8403080339
- 8403070250 Forwarde IE inep Repte 50-280/83-37 & 50-281/83-39 on B31201-31 No violations or deviations identified DANCE,H.C Division of Project & Resident Programs 84/02/10 BTEMARTW L Virginia Electric & Power Co 2pp 22546 016 24% Fiche.50-280,84/02/10,8403070250
- --B403070253 IE Insp Repts 50-280/83-37 & 50-281/83-39 on B3:201-31.No violations or deviations identified Major areae inspected operations.plant excurity, followup of events & LERA performance appraisai insp findinge & surveillance review BURKE,D J., DAVISM J Region 2. Office of Director ELROD, B Division of Project & Resident Programs B4/02/09, 7pp 22546 Q18 24X Fichs 50-280,84/02/10,8403070250
- B403070279 Discusses SALP evaluation issuance of SALP rept approved No major weaknesses identified during assessment period at North Anna One major weakness identified in area of radiological controls at Surry O'REILLY.J P Region 2, Office of Director B4/02/i6 SYEWART.W L Virginia Electric & Power Co 2pp 22541 286 24X Fiche 50-000,84/02/16,8403070279
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuite & Annunciation " Bvc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. i15pp 22709:239 24X Fichs. 50-000; 84/02/28, 8401190072
- 8403140199 Forwards FR notice & safety evaluations of granting of ralief from ABME Section XI intervice requirements.per 790517 & 0928, 801215, 820325 & 0525, 830107, 0307, 0407 & 1227 requests

 VAROA, S A Operating Reactors Branch 1. 84/02/28 BTEWART, W L, Virginia Electric & Power Co 4pp 22638, 073, 24X Fichs. 50-280, 84/02/28, 8403140199
- --8403140200 Notice of granting of relief from ASME Section XI inservice insp requirements.
 VAR9A: BA Deprating Reactors Branch 1 84/02/28 2pp 22638 077 24X Fiche: 50-280,84/02/28,8403140199

- --8403140202 Safety evaluation accepting licenses 801215,820325 & 0525 requests for relief from ASME inservice insp requirements * Office of Nuclear Reactor Regulation. Director 84/02/28 16pp 22638 079 24X Fiche 50-280.84/02/28.8403140199
- ~-8403140204 Safety evaluation accepting licensee 830107,0307.0414 & 1227 requests for relief from ASME inservice insp requiremente # Office of Nuclear Reactor Regulation, Director #4/02/28 1809 22638 095 24% Fiche 50-280.84/02/28.8403140199
- --8207030161 "Inservice Insp Program," technical evaluation rept * Science Applications, Inc. NRC-03-82-076 SAI-186-028-20 82/08/27 NRC - No Detailed Affiliation Given 44pp 22638 113 24X Fiche 50-280,84/02/28.8403140179
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Responee (Post 830103) 84/03/02 Consolidated Edison Co. of New York: Inc. 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- B402090009 IE info Notice 84-i5. "Reporting of Radiological Releases" Svc list encl
 JORDAN,E L. Division of Emergency Preparednese & Engineering Response (Post 830i03) 84/03/02 Consolidated Edison Co of New York, Inc ii9pp 22553 2i7 24X Fiche 30-000,84/03/02,8402090009
- B403i60i54 Responds to IE Builetin 83-08 re eiectricai circuit breakers w/undervoitage trip feature in use in safety-related applications other than trip sys Only reactor trip breakers contain subj trip attachments
 BTEWARTIW L Virginia Electric & Power Co 84/03/02 O'REILLY, J P
 Region 2, Office of Director 2pp 22806 008 24X
 Fiche 50-000,84/03/02,8403i60i54
- 84020900ii iE info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Campanents Below Nii Ductiirty Temp " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE into Notice 84-07. Rev i. "Lessons Learned From Ineps of Fire Protection Safe Shutdown Sys " Svc iist enci JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc ii8pp 22635 049 24X Fiche 50-000,84/03/07.8402090024
- 8402090028 iE info Notice 84-iB, "Strese Corresion Cracking in PWR Sys " Svc list enc! JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc iiBpp 22584 i86. 24X Fiche 50-000.84/03/07.8402090028
- 8403150099 Forwards IC Safeguarde Insp Repts 50-280/84-06 & 50-281/84-06 on 840227-0302 No violations or deviations identified DANCE. H C Division of Project & Resident Programs 84/03/09 STEMART, W L Virginia Electric & Power Co 2pp 22639 300 24X Fiche 50-280,84/03/09,8403150099
- --B403i30i09 IE Bafeguards Insp Repts 50-280/B4-04 & 50-28i/B4-06 on 840227-0302 No noncompliance noted Major areas inspected excurity organization/mgt.personnel response records & repts & testing Details withheld (ref iOCFR73 21 & 2 790) ENNIB.J D. MCGUIRE, D.R. Region 2. Office of Director 84/03/09 ip 22639 302 24X Fichs 50-280,84/03/09.8403i50099
- 8402090031 IE Bulletin 84-02, "Failuree of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYDUNG:R C Director's Office: Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24X Fiche 50-000;84/03/12,8402090031
- 8403270274 Discusses 840210 meeting re util plans; current events; present organizational changes & outstanding regulatory issues. Meeting beneficial 1 provided better understanding of plans
 O'RETLLY, J.P. Region 2. Office of Director 84/03/19
 FERGUSON, J.H. Virginia Electric & Power Co. ip. 22814-079 24X
 Fiche: 50-280, 84/03/19, 8403290274
- B402070043 IE Info Notice B4-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities " Bvc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402070043

- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related
- Sys "Svc list encl JDRPAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- 8403270021 Informs that due to add1 review required re mat1 supplied by Ray Miller.Inc.util unable to respond to IE Bulletin 83-07 until 840406

 STEMART.W. L. Virginia Electric & Power Ca 84/03/22 DEYOUNO.R C Director's Office. Office of Inspection and Enforcement Ip 22770 068 24X Fishe 50-000:84/03/22.8403270021
- 8403290197 Resubmits 840302 response to IE Bulletin 83-08, "Electrical Circuit Breaters M/Undervoltage Trip Feature in Use in Safety-Related Applications ... " Affirmation inadvertently unitted from 840302 it encl STEWART.W L. Virginia Electric & Power Co 84/03/29 O'REILLY, J P Region 2. Office of Director 2pp 22806 006 24X Fiche 50-000-84/03/29,8403290157

R Periodic operating reports & related correspondence

- 8403020053 Forwards operating repts for Jan 1784 & corrected pages of bealth physics repts for Jul-Dec 1983 STEMART.W L Virginia Electric & Power Co 84/02/14 HALLER.N M NRC * No Detailed Affiliation Given 1p 22447 127 24X Fiche 50-280.84/02/14.8403020053
- 84/01/31
- --8403020063 Corrected page to health physics rept for monthly operating repts for Nov 1983

 * Virginia Electric & Power Co B3/11/30 ip. 22447 170 24X
 Fiche 50-280.84/02/14.8403020053
- --8403020066 Corrected page to health physics rept for monthly operating repts for Dec 1983

 ** Virginia Electric & Power Co 83/12/31 1p 22447, 171 24X
 Fiche 50-280, 84/02/14: 8403020053
- --8403020071 Corrected page to health physics rept for monthly operating repts for Jul 1983 * Virginia Electric & Power Co 83/07/31 1p 22447 172 24X Fiche 30-280,84/02/14,8403020053
- --8403020076 Corrected page to health physics rept for monthly operating repts for Aug 1983 * Virginia Electric & Power Co 83/08/31 ip 22447-173 24X Fichs 50-280.84/02/14,8403020053
- --8403020085 Corrected page to health physics rept for monthly operating repts for Sept 1983

 * Virginia Electric & Power Co 83/09/30 ip 22447 174, 24x Fiche 50-280.84/02/14,8403020053
- -8403020090 Corrected page to health physics rept for monthly operating repts for Oct 1983 .

 * Virginia Electric & Power Co 83/10/31 1p. 22447:175 24x Fiche 50-280.84/02/14.8403020033
- 8403300060 Monthly operating repts for Feb 1984. W/840315 ltr WILSON, J. STEWART. W. Virginia Electric & Power Co 84/02/29 HALLER, N M Office of Resource Management, Director 44pp. 22821 113 24X Fithe 50-280:84/02/29,8403300065

S Reportable occurrences, LERs & related correspondence

- 8403090223 RD SPR-84-2 on 840118, specific activity sample of reactor conlant showed peak dose equivalent I-131 level of 1 87 uCi.exceeding Tech Spec limit Caused by fuel element defects in reactor core Dose level monitored.

 WILSON, J L Virginia Electric & Power Co 84/02/17 O'REII Region 2. Office of Director 2pp 22575 150 24X Fiche: 50-280,84/02/17.8803090223 84/02/17 O'REILLY, J P
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 T&T valve, to close Encl ltr (td 840203 sent to listed utils GE notified of affected units in BMR
- THERDUX, R R Terry Corp 84/02/22 WDODRUFF, R W Director's Office, Office of Inspection and Enforcement App. 22706 327 24X Fiche 50-000, 84/02/22, 8403210032

- 8403090280 RO SPR-84-003 on 840204. following trip from 100% power, specific activity sample of reactor coolant showed peak dose equivalent I-131 limit of less than or equal to 1 0 uCi Caused by fuel slement defects in reactor core GILBON. J L Virginia Electric & Power Co 84/02/24 D'REILLY, Region 2. Office of Director 3pp 22372 141 24% Fiche 50-280.84/02/24.8403090250 D'REILLY, J P
- 8403130424 LER 84-003-00 on 840206.reactor tripped due to low steam generator level w/steam flow/feed flow mismatch in steam generator A Caused by tripped feedwater breaker closing Breaker replaced M/840306 itr WILSON, J W Virginia Electric & Power Co 84/03/06 O'REILLY, J P Region 2. Office of Director & Opp 22613 131 24X Fichs 50-280.84/03/06.8403130424
- B403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program underway Results of Investigation indicate excessive wear caused by hunting of control circuitry

 DOBBON.J P Pacific Air Products Co 84/03/09 Director's

 Office, Office of Inspection and Enforcement 7pp 22624 068 24X

 Fichs 50-000.84/03/07.8403140122
- DOCKET 50-28; SURRY POWER STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8403070239 Forwards SALP Repts 50-280/83-33, 50-281/83-35, 50-338/83-33 & 50-339/83-33 for Oct 1982 Aug 1983 Evaluation will be discussed at 831208 meeting at North Anna site LEWIS, R C Division of Project & Resident Programs 83/11/25 STEMART. W L Virginia Eigetric & Power Co 2pp 22536 227, 24x Fiche 50-000,83/11/25,8403070239
- --B403070246 SALP Repts 50-280/83-33, 50-281/83-35, 50-338/83-33 k 50-339/83-33 for Oct 1982 Aug 1983 Reliable performance w/improvement in most previously noted areas of weakness demonstrated # Region 2, Office of Director 83/11/25 42pp 22536; 229, 24X Fiche 50-000, 83/11/25, 8403070239
- 8401130314 Supplemental info to 801028 application to amend Licenses DPR-31 & DPR-37 re fire pump flow testing Justification for capability of fire pumps to provide adequate fire protection provided STEWART, W.L. GFFICE OF Nuclear Reactor Regulation, Director 2pp 21798 313 24X Fiche 50-280,84/01/09,8401130314
- 8403280125 Public version of Rev 9 to Emergency Plan Implementing Public version of Rev 7 to Emergency Plan Implementing Procedure EPIP-1 01, "Emergency Manager Controlling Procedure" #/840123 ltr & JM Felton 840322 release memo WILBON. J. GRADY. D. BTEWART. W. L. Virginia Electric & Power Co 84/01/13 0'RELLY. J P. Region 2. Office of Director Spp 22811 082 24X Fiche 50-280, 84/01/13,8403280125
- 8403070250 Forwards IE Imap Repts 50-280/83-37 & 50-281/83-39 on NGG/0220 reparts I has negt 50-280/63-37 and 83/201-31 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/10 STEWART.W L Virginia Electric & Power Co 2pp 22546 016 24X Fiche 50-280.84/02/10.8403070250
- --B403070253 IE Insp Repts 50-280/B3-37 & 50-281/B3-39 on B31201-31 No violations or deviations identified Major areas inspected operations; plant security, followup of events & LERs, performance appraisal insp findings & surveillance review BURKE: D J Region 2. Office of Director B4/02/09 7pp 22546 018 24X Fiche 50-280,84/02/10.8403070250
- 8403090242 Rev 4 to Emergency Plan Implementing Procedure EPIP-4 23, "Post-Accident Sampling of Reactor Coolant " W/840302 ltr STEWART: N L Virginia Electric & Power Co 84/02/16 O'REILLY, J P Region 2, Office of Director 22pp 22573 228 24X Fiche 50-280,84/02/16,8403090242
- 8403200116 Forwards changes to security personnel training qualification program Changes withheld (ref 10CFR73 21). SYEWART:N L. Virginia Electric & Power Co 84/02/17 (Region 2, Office of Director. 1p 22685 335 24X Fiche 50-280:84/02/17:8403200116 O'REILLY, J P
- 8403190263 Rev 1 to corporate emergency response plan W/840315 ltr STEMART, W L. Virginia Electric & Power Co. 84/02/24 O'REILLY, J P Region 2. Office of Director. 105pp. 22670'135 24X Fiche 50-000.84/02/24.8403190263.
- 8403060397 Forwards correction to 830217 ltr re revised pages to amergency plan implementing procedures. M/o encl SALYERS,E M Virginia Electric & Power Co. 84/02/29 NRC Detailed Affiliation Given ip 22518 133, 24X Fiche 50-280.84/02/29.8403060397 NRC - No

- 8403080264 Forwards "Control Room Design Review Program Plan for North Anna & Surry Power Stations," in response to Suppl 1 to NUREO-0737 Review expected to be completed by 850830 STEMARTH L Virginia Electric & Power Co 84/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D G Division of Licensing 2pp 22557 275 24% Fiche 50-000, 84/03/01, 8403080264
- --8403080269 "Control Room Design Review Program Plan for North Anna & Burry Power Stations," in response to Suppl 1 to NUREO-0737 * Virginia Electric & Power Co 84/03/01 illpp 22557 299 24% Fiche 30-000,84/03/01,8403080264
- 8403210ii7 Rev ii to Emergency Plan Implementing Procedure EPIP-1 01, "Emergency Manager Controlling Procedure" & Rev 6 to Procedure EPIP-2 01, "Notification of State & Local Govts " #/840316 itr « Virginia Electric & Pawer Co 84/03/01 O'REILLY, J P Region 2, Office of Director Spp 22705:067 24% Fiche 50-280,84/03/01, 840820117
- B403080091 Submits addl info in order to conduct detailed review of emergency response procedures generation package.per 840125 request Items 1 & 2 will be addressed by 840530 Item 3 should be addressed by Westinghouse Owners Group STEWART, W L. Virginia Electric & Power Co. 84/03/02 DENTON, H R Diffice of Nuclear Reactor Regulation, Director EIBENHUT, D Q Division of Licensing 2pp 22559 199 24X Fiche 50-000,84/03/02,8403080091
- 8403070151 Revised emergency plan implementing procedures, including Rev 11 to EPIP-1 Oi, "Emergency Manager Controlling Procedure" & Rev 6 to EPIP-2 Oi, "Notification of State & Local Govts " W/840302 1tr SALYERB.E M Virginia Electric & Power Co 84/03/02 6pp 22575 066. 24X Fiche 50-280,84/03/02,8403090151
- B403160276 Extends invitation to attend 840316 workshop at regional ofc to discuse 10CFR50, App R requirements & results of insps to help resolve misunderstandings associated w/requirements LEWIS, R C Division of Project & Resident Programs B4/03/02 BTEMART. W L. Virginia Electric & Power Co 1p 22660 080 24X Fichs: 50-000, 84/03/02, 8403160276.
- 8403150099 Forwards IE Safeguards Insp Repts 50-280/84-06 & 50-281/84-06 on 840227-0302 No violations or deviations identified DANCE, H C Division of Project & Resident Programs 84/03/09 STEMART, W L Virginia Electric & Power Co 2pp 22639 300 24X Fiche 50-280, 84/03/09-0803150099
- 8403190052 Informs that local emergency operations facilities at North Anna & Surry Power Stations will be functional, except for data communications & display, by 850731, per NUREO-0737, Buppl 1 BTEWART, W.L. Virginia Electric & Power Co 84/03/14 DENTON, H.R. Office of Nuclear Reactor Regulation, Director EISENHUT, D. Q. Division of Licensing 2pp 22666 173 24X Fiche 50-000,84/03/14,
- B403190052

 8403230146 Rev 7 to Emergency Plan Implementing Procedure EP1P-2 01.
 "Notification of State & Local Govts " W/840316 1tr
 BALYER8 E M Virginia Electric & Power Co 84/03/16 3pp
 22730 228 24x Fichs 50-280.84/03/16,8403230146.
- P. Operating license stage documents & correspondence
- 840:1303:14 Supplemental info to 80:1028 application to amend Licenses DRR-31 & DRR-37 re fire pump flow testing Justification for capability of fire pumps to provide adequate fire protection provided.

 STEHART: W. L. Virginia Electric & Power Co. 84/01/09. DENYON, H.R. Office of Nuclear Reactor Regulation, Director VARGA, S.A. Operating Reactors Branch i 2pp 21798-313 24X Fiche. 50-280, 84/01/09, 840:130314
- B403050230 "Radionuclide Release Under Specific LWR Accident Conditions," Vol V. "PWR-Large, Dry Containment (Surry Recalculations) "
 OIEBEKE, J. A. CYBULSKIS, P. DENNING, R. B. Battelle Memorial Institute, Columbus Laboratories B403050230 B4/01/12 Office of Nuclear Regulatory Research, Director 212pp. 22502 001 24X Ficher 50-280, 84/01/12, 8403050230

- 84030B0339 Final response to FOIA request for documents re NRC investigation of industrial accident involving burst steam pipe at facility "VEPCO investigative Board Preliminary Rept" on accident placed in PDR FELTON, J M Division of Rules and Records 84/01/20 GARDE, B P Government Accountability Project ip 22576 214 24X Fiche 50-280,84/01/20,8403080339
- 8403160269 Confirms 840208 telcon re functional testing of snubbers Addl functional testing of Unit 1 snubbers per Tech Spec 4 17 C 6 will be completed during Feb 1984 maint outage Unit 2 testing to be completed during Mar 1984 maint outage LEMIS.R C Division of Project & Resident Programs 84/02/13 STELART.W L Virginia Electric & Power Co 1p 22660 334 24X Fichs 50-280.84/02/13.8403160269
- 8403020034 Forwards Amends 95 & 94 to Licenses DPR-32 & DPR-37, respectively & safety evaluation Amends revise Tech Specs to change min boron injection tank boron concentration from 11 5% to 0%

 NEIOHBORS, J D Operating Reactors Branch 1 B4/02/24 STEWART, W L Virginia Electric & Power Co 2pp 22491 018 24%

 Fiche 50-280,84/02/24,8403020054
- --B403020058 Amends 95 & 94 to Licenses DPR-32 & DPR-37, respectively, revising Tech Specs to change min boron injection tank boron concentration from 11 5% to 0% & changing boric acid sysboron concentration from 11 5% to 7% VARGA, S A Operating Reactors Branch 1 84/02/24 18pp 22491 020 24% Fiche 50-280,84/02/24,8403020054
- --8403020061 Safety evaluation supporting Amends 95 & 94 to Licenses DPR-32 & DPR-37, respectively * Office of Nuclear Reactor Regulation, Director 84/02/24 7pp 22491 038 24% Fiche 30-280,84/02/24,8403020054
- 8403020195 Forwards add1 info to complete review of Topical Rept VEP-FRD-41, "VEPCO Reactor Sys Transient Analysis Using RETRAN Computer Code," in response to NRC Nov 1982 informal request STEWART, W L Virginia Electric & Power Co 84/02/27 DENTON, H R Defice of Nuclear Reactor Regulation, Director EISENHUT, D O Division of Licensing 16pp 22443 237 24% Fiche 50-000,84/02/27,040301058
- 8403050229 Submits review of post-accident sampling sys, item II B 3 Ten of 11 criteria met Remaining criterion to procedure for estimating extent of core damage based on radionuclide evaluation. acceptable on interim basis
 MiLLER.J R Operating Reactors Branch 3 84/02/27 STEWART.W L Virginia Electric & Power Co 6pp 22528 001 24X
 Fichs 50-000.84/02/27.8403050229
- 8403260105 Supplemental application for amend to Licenses DPR-32 & DPR-37 Suppl reflects change in title of fire marshal to loss prevention supervisor & deletes NDE supervisor STEMART, W L Virginia Electric & Power Co 94/03/22 DENTON, H R DFfice of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch i 5pp 22758 238 24X Fiche 50-280,84/03/22,8403260105
- --B4032601i0 Proposed Tech Spec.changing organization titls of fire marshal to loss prevention supervisor & deleting NDE supervisor position

 * Virginia Electric & Power Co 84/03/22 2pp 22758 243 24X Fiche 50-280,84/03/22
- @ Inspection reports: IE Bulletins & correspondence
- 8403070237 Forwards BALP Repts 50~280/83-33,50~281/83-35,50-338/83-33 & 50~337/83-33 for Oct 1982 Aug 1983 Evaluation will be discussed at 831208 meeting at North Anna site LEMIS:R C Division of Project & Resident Programs 83/11/25 BTEWART.W L Virginia Electric & Power Co. 2pp 22536 227 24X Fiche 50~000.83/11/25,8403070237
- --8403070246 SALP Repts 50-280/83-33,50-281/83-35,50-338/83-33 & 50-339/83-33 for Oct 1982 Aug 1983 Reliable performance w/Improvement in most previously noted areas of weakness demonstrated # Region 2, Office of Director 83/11/25 42pp. 22336,229 24X Fiche 50-000,83/11/25,8403070239
- 8403080339 Final response to FOIA request for documents re NRC investigation of industrial accident involving burst steam pipe at facility "VEPCO Investigative Board Preliminary Rept" on accident placed in PDR FELTON.J M Division of Rules and Records 84/01/20 GARDE: B POWERTMENT ACCOUNTABLE PROPERTY PROPERTY

- 8403070250 Forwards IE Insp Repts 50-280/83-37 & 50-281/83-39 on 831201-31 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/10 STEWART.W L Virginia Electric & Power Co 2pp 22546 016 247 Fichs 50-280.84/02/10.8403070250
- --B403070233 IE Insp Repts 50-280/B3-37 & 50-281/B3-39 on B31201-31 No violations or deviations identified Major areas inspected operations.plant security, followup of events & LEAs, performance appraisal insp findings & surveillance review BWRKE.D J. DAVIS.M J. Region 2. Office of Director ELROD, S Division of Project & Resident Programs B4/02/09 7pp 22546 018 24X Fiche 50-280,84/02/10,8403070250
- 8403070279 Discusses SALP evaluation Issuance of SALP rept approved No major weaknesses identified during assessment period at North Anna One major weakness identified in area of radiological controls at Surry O'REILLY.JP Region 2. Office of Director 84/02/16 STEWART.W L Virginia Electric & Power Co. 2pp 22541 286 24X Fiche 50-000.84/02/16.8403070279
- 8403140197 Forwards FR notice & safety evaluations of granting of relief from ASME Section XI inservice requirements.per 790517 & 0928, 801215, 820325 & 0525,830107,0307,0407 & 1227 requests
 VAROA.S A Operating Reactors Branch 1 84/02/28 STEWART.W L Virginia Electric & Power Co 4pp 22638 073 24X Fichs 50-280,84/02/28,8403140199
- --8403140200 Notice of granting of relief from ASME Section X1 inservice insp requirements WARGA.S A Operating Reactors Branch 1 84/02/28 2pp 22638 077 24X Fiche 50-280.84/02/20.8403140199.
- --8403140202 Safety evaluation accepting licensee 801215,820325 & 0525 requests for relief from ABME inservice insp requirements * Office of Nuclear Reactor Regulation, Director 84/02/28 14pp 22638 077 24% Fichs 50-280.84/02/28.8403140197
- --8403140204 Safety evaluation accepting licensee 830107,0307,0414 & 1227 requests for relief from ASME Inservice insp requirements a Office of Nuclear Reactor Regulation, Director 84/02/28 llpp 22638 095 24X Fiche 50-280.84/02/28.8403140199
- --B209030161 "Inservice Insp Program." technical evaluation rept * Science Applications. Inc. NRC-03-B2-096 BAI-186-028-20 B2/08/27 NRC - No Detailed Affiliation Given 44pp 22636 L13 24X Fiche 50-260.84/02/28.3403140199
- B402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of OA: Safeguards & Inspection Programs (Post 830103) B4/03/02 Consollidated Edison Co of New York. Inc 130pp 22552 329 24X Fiche 50-000:84/03/02.8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, Et. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list encl
 JURRANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22593 217 24X Fiche 50-000, 84/03/02, 8402090009
- 8403160154 Responds to IE Bulletin 83-08 re electrical circuit breakers M/undervoltage trip feature in use in safety-related applications other than trip sys Only reactor trip breakers contain subj trip attachments SIEMARI.W L Virginia Electric & Power Co 84/03/02 D'REILLY, J P Region 2. Office of Director 2pp 22806 008 24X Fiche 50-000.84/03/02.8403160154
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Caoling Components Below Nil Ductility Temp " Byo list enci JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/05. Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05,8402090011
- 8402090024 IE Info Notice 84-09.Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 820103) 84/03/07 Consolidated Edison Co of New York, Inc 188pp 22635 049 24X Fiche 50-000,84/03/07,8402090024

- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Svc list enc! JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- B403150099 Forwards IE Safeguards Insp Repts 50-280/84-06 & 50-281/84-06 on B40227-0302 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/03/09 STEMART.W L Virginia Electric & Power Co 2pp 22639 300 24% Fiche 50-280.84/03/09.8403150099
- --8403150107 IE Bafeguards Insp Repts 50-280/84-06 & 50-281/84-06 on 840227-0302 No noncompliance noted Major areas inspected security organization/mgt.personnel response.records & repts & testing Details withheld (ref iOCFR73 21 & 2 770) ENNIS, J D. MCOUIRE, D R. Region 2, Office of Director 84/03/09 tp 22637 302 24X Fiche 50-280.84/03/07.8403150097
- 8402070031 IE Bulletin 84-02, "Failures of CE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24% Fiche 50-000.84/03/12.8402090031
- B403270274 Discusses B40210 meeting re util plans, current events, present organizational changes & outstanding regulatory issues Meeting beneficial & provided better understanding of plans O'REILLY, JP Region 2, Office of Director B4/03/19 FERGUSON, JH Virginia Electric & Power Co 1p 22814 079 24X Fiche 50-280,84/03/19,8403290274
- 8402090043 IE Info Notice B4-19. "Two Events Involving Uneuthorized Entries into PHR Reactor Cavities " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York. Inc 123pp 22823 229 24% Fiche 50-000.84/03/21,8402090043
- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Sys " Svc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24X Fiche 30-000,84/03/21,8402090044
- 8403270021 Informs that due to add1 review required re mat1 supplied by Rag Miller, inc. util unable to respond to IE Bulletin B3-07 until 1840404
 STEWART. W.L. Virginia Electric & Power Co. 84/03/22 DEYOUNG. R.C. Director's Office. Office of Inspection and Enforcement ip 22770 068 24X Fiche 80-000.84/03/22,8403270021
- 8403290137 Resubmits 840302 response to 1E Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications "Affirmation inadvertently anitted from 840302 ltr encl STEWART.W L Virginia Electric & Power Co 84/03/29 O'REILLY, J P Region 2, Office of Director 2pp 22806 006, 24X Fiche 50-000.84/03/29,8403290157
- R Periodic operating reports & related correspondence
- B403020053 Forwards operating repts for Jan 1984 & corrected pages of health physics repts for Jul-Dec 1983 STEMART.W L. Virginia Electric & Power Co. 84/02/14 HALLER,N M NRC - NO Detailed Affiliation Given ip. 22447 129 24X Ficha 50-280.84/02/14.8403020053
- --8403020059 Monthly operating repts for Jan 1984 WILSON, J., JONES, V. H. Virginia Electric & Power Co., 84/01/31 38pp 22447 130 24X Fiche 50-280,84/02/14,8403020053
- --8403020063 Corrected page to health physics rept for monthly operating repts for Nov 1983 * Virginia Electric & Power Co 83/11/30 lp 22447 170 24X Ficher 30-280, 84/02/14,8403020053
- --8403020066 Corrected page to health physics rept for monthly operating repts for Dec 1983

 * Virginia Electric & Power Co. 83/12/31, 1p 22447-171 24X
 Fichs. 50-280, 84/02/14, 8403020053
- --8403020071 Corrected page to health physics rept for monthly operating repts for Jul 1983

 * Virginia Electric & Power Co 83/07/31. 1p 22447 172 24X
 Fichs. 50-280. 84/02/14, 8403020053

- --8403020074 Corrected page to health physics rept for monthly operating repts for Aug 1983 Wirginia Electric & Power Co 83/08/31 1p 22447 173 24X Fiche 50-280,84/02/14,8403020053
- ---B403020085 Corrected page to health physics rept for monthly operating repts for Bept 1983 * Virginia Electric & Power Co 83/09/30 1p 22447 174 24X Fichs 50-280, 84/02/14, 8403020053
- --8403020090 Corrected page to health physics rept for monthly operating repts for Oct 1983

 * Virginia Electric & Power Co 83/10/31 ip 22447 175 24X
 Fichs 50-280,84/02/14,8403020053
- B403300060 Monthly operating repts for Feb 1984 W/840315 1tr WILBON, J. SIEWART.W.L. Virginia Electric & Power Co. B4/02/29 HALLER, N. M. Deffice of Resource Management, Director 49pp 22821 113 24% Fiche 30-280.84/02/29,8403300060
- 8 Reportable occurrences, LERs & related correspondence
- 8305160260 Forwards technical review of rod control urgent failurs on B20625 Caused by blown fuse & failed phase control card in 2 ac power cabinet No generic implications identified TREHAN, N K Reactor Operations Analysis Branch 83/05/05 SEYFRIT.K V Reactor Operations Analysis Branch 2pp 22809 285 24X Fiche 50-281,83/05/05,8305160260
- --8403280121 "Rod Control Urgent Failure on 830625 at Burry Unit 2." technical review rept TREHAN.N Director's Office 83/05/05 ip 22809 286 24X Fiche. 50-281.83/05/05.8305160260
- B403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpel NPS-4 T&T valve, to close Enci ltr dtd B40203 sent to listed utils GE notified of affected units in BWR plants
 THEROUX, R Terry Corp 84/02/22 WOODRUFF, R W Director's Office, Office of Inspection and Enforcement 6pp 22706 327 2-Fiche 50-000.84/02/22, B403210032
- B403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry.

 DDBSDN.J P Pacific Air Products Co 84/03/07 Director's Office. Office of Inspection and Enforcement 7pp 22624 068 24X Fiche 50-000.84/03/07.8403140122
- DUCKET 50-282 PRAIRIE IBLAND NUCLEAR STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8403090270 Public version of revised emergency response plan implementing procedures, including Procedure F3-2 re classification of emergenciee F3-5 re emergency notification & F3-10 re personnel accountability W/831219 ltr & memo MENDELE DJ. JONNSON, JM Northern States Power Co 83/10/28 168pp 22595 326 24X Fiche 50-282,83/10/28,8403090270.
- B403070207 Revised emergency implementing procedures, including Rev 25 to Procedure F3, "Table of Contents" & Rev 3 to Procedure F3-8. "Recommendations for Offsite Protective Actions " 4//840302 ltr FEY.F.L. Northern States Power Co. 84/02/24 28pp 22574 328 24% Fiche 50-282,84/02/24,8403090207
- 8403190020 Forwards IE Insp Repts 50-282/83-24 & 50-304/83-24 on 831211-840210, No noncompliance identified BHAFER, W D Region 3. Office of Director, 84/03/01 LARSON, C. E Northern States Power Co 2pp 22666, 053 24X Fiche 50-282, 84/03/01, 8403190020
- --8403190042 IE Insp Repts 50-282/83-24 & 50-306/83-24 on 831211-840210 No noncompliance or deviations identified, Major areas inspected, maint, LERs, emergency planning & surveillance, meetings w/state & local officials & IE bulletins HARD. J E , FETERABEND, C D , HARTMANN, P L Region 3, Office of Director, 84/02/29 12pp, 22666 055 24X Fiche 50-282,84/03/01,8403190020
- B403130163 Forwards final rept re small-scale offsite radiological emergency preparedness exercise on 821014 No deficiencies notad KRIMM-R W Federal Emergency Management Agency 84/03/05 JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 6pp 22579 307. 24X Fiche 50-282-84/03/05-284/130163

- ---8403130172 Final rapt of small-scale joint emergency exercise on 821014 # Federal Emergency Management Agency 82/12/17 82pp 22597 313 24X Fiche 50-282.84/03/05.8403130163
- 8403120106 Notifies of 840323 workshop on fire protection safe shutdown requirements of 10CFR50.App R in Rosemont IL to discuss IE Info Notice 84-09 & provide addl shutdown analyses %/or mod guidance Agenda encl SPESSARD.R L Division of Emergency Preparedness & Operational Support 84/03/06 LARSON.C E Northern States Power Co 3pp 22588 169 24% Fiche 50-282:84/03/06.8403120106
- 8403300130 Revised emergency plan implementing procedures, including Procedure F3 re table of contents & F3-13 re offsite dose calculation W/840320 transmittal ltr WATTLE FEY.F1. Northern States Power Co. 84/03/09 34pp 22820 255 24X Fiche 50-282, 84/03/09, 8403300130
- I Financial information
- 8403290115 Suppl to Annual Financial Rept 1983, consisting of financial & statistical into W/840326 ltr
 BRUSYEN, A D Northern States Power Co 83/12/31 23pp 22806 182 24X Fiche 50-000, 83/12/31, 8403290115
- P Operating license stage documents & correspondence
- 8403050238 Forwards Amends &8 & 62 to Licenses DPR-42 & DPR-60, respectively & safety evaluation Amends revise Tech Specs re emergency air treatment sys & ebsctric hydrogen recombiners DITANNI,D C Operating Reactors Branch 3 84/02/21 MUSGLF,D M Northern States Power Co 2pp 22527 188 24X Fiche 50-282.84/02/21.8403050238
- --8403050243 Amends 48 & 42 to Licenses DPR-42 & DPR-40, respectively, revising Tech Specs re emergency air treatment sys & electric hydrogen recombiners
 MILLER, J.R. Operating Reactors Branch 3 84/02/21 18pp
 22527 190 24X Fiche 50-282,84/02/21,8403050238
- --8403050249 Safety evaluation supporting Amends 68 & 62 to Licenses DPR-42 & DPR-60 respectively * Office of Nuclear Reactor Regulation, Director 84/02/21 7pp 22527 208 24% Fiche 50-282.84/02/21,8403050238
- 8403040425 Submits fees requested for \$20630 exemption request, in response to NRC 840213 itr MUSDLF.D Northern States Power Co 84/02/27 MILLER, W O License Fee Management Branch 2pp 22518 200 24X Fiche 50-282,84/02/29,8403060425
- 8403130245 Forwards "Effluent & Waste Disposal Semiannual Rept. Jul-Dec 1983." "Offsite Radiation Dose Assessment, 1983" & Rev 4 to "Offsite Dose Calculation Manual" FEY,F.L. Northern States Power Co. 84/03/01 Region 3, Office of Director 1p 22410 143 24X Fiche 50-282, 84/03/01, 8403130245
- --8403130278 Rev 4 to "Offsite Dose Calculation Manual" BORENSON, J. Northern States Power Co. 84/11/14 11pp 22610 157 24X Fiche 50-282,84/03/01.8403130245
- 8403150270 Forwards safety evaluation re error in COURA HITC/MIT computer code, previously accepted by NRC 830217 & 0324 ltrs, for use in analyzing fuel reloads Error does not create any substantial safety hazard MILLER, J R Operating Reactors Branch 3 84/03/06 MUSOLF, D M Northern States Power Co ip 22647 333 24X Fiche 50-282, 84/03/06,8403150270
- --8403150293 Bafety evaluation re error in COBRA IIIC/MIT computer code reload methodology rept NSPNAD-8102 Error has not affected initial findings or conclusions re acceptability of use of COBRA IIIC/MIT code

 * NRC No Detailed Affiliation Given 84/03/06. 2pp 22649 334 24X Fiche 50-282,84/03/06.8403150270
- B403190397 Provides updated info re mods required by NUREG-0737.ltem II D i 2 re safety & relief valve performance.Unit i piping & supports will be installed during next refueling outage scheduled for 850105
 MUSDLF.D Northern States Power Co 84/03/14 Office of Nuclear Reactor Regulation, Director 1p 22675 192 24X
 Fiche 30-282.84/03/14.8403190397

- 8403230031 Submits status of mods to improve adequacy of station distribution sys voltages, per util 860717 itr & NRC 821029 SER All mods completed, w/exception of changes to station air compresser starting circuit.

 MUSDLF.D Northern States Power Co 84/03/16 Office of Nuclear Reactor Regulation, Director 2pp 22724 346 24X Ei-bo-80-909. 94/03/16. 8403230051
- G Inspection reports. IE Bulletins & correspondence
- 8403050223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, pracedures & practices for measurement of RCB leakage Forwards App C documents Bearch continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN, T J Raye, Scholer, Fierman, Hays & Handler 3pp 22476 234 24X Fichs 50-000,84/02/07.8403050223
- --8403050256 Notifies that independent measurements of identified & unidentified RCS leak rates for all PMRs in Region III performed per Procedures 617278 & 617288 Insp findings summarized NORELIUS, C E Division of Engineering 82/03/08 JORDAN, E L Division of Engineering & Quality Assurance (Pre 830103) 2pp 22496:270 24X Fiche 50-000.84/02/07,8403050283.
- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/28 Gonsolidated Edison Co of New York Inc i15pp 22907 237 24X Fiche 50-000.84/02/28,8401190072
- 8403190020 Forwards IE Insp Repts 50-282/83-24 & 50-306/83-24 on B31211-840210 No noncompliance identified SHAFER: W D Region 3. Dffice of Director. B4/03/01 LARBON: C E Northern States Power Co 2pp 22666 053 24X Fiche 50-282.84/03/01.8403190020
- --8403190042 IE Insp Repts 50-282/83-24 & 50-306/83-24 on B31211-B40210
 No noncompliance or deviations identified Major areas
 inspected maint. LERs. emergency planning & survsiliance,
 meetings w/state & local officials & IE builetins
 HARD. J E . FEIERABEND. C D . HARTMANN.P L Region G, Office of
 Director 84/02/29 12pp 22666 055 24X Fiche 50-282,84/03/01,
 8403190020
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list enci GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fische, 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinklar Sys Vaives to Operate " Syr list encl JORDAN,E L Division of Emargency Preparednass & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Flche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiologics! Releases" Svc list enci
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fichs 50-000,84/03/02,8402090009
- 840209001i IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nii Ductility Temp " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc i17pp, 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402070024 IE Info Notice 84-09. Rsv 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000, 84/03/07, 8402070024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " Syc list enci, JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8403190388 Forwards summary of status of requests for relief from requirements of Section XI of ASME Boiler & Pressurg Vessel Code for inservice (hep program & clarification of items that require add) review MUSGLF.D Northern States Power Co 84/03/09 Office of Nuclear Reactor Regulation, Director 9pp 22675.295 24X Fiche 50-282.84/03/09.8403190388

- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYGUNG:R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24% Fiche 50-000:84/03/12.8402070031
- 8403190200 Rssponds to IE Bulletin 83-07 re products supplied by Ray Miller. Inc Neither unit received products from Ray Miller. Inc & vendor not en approved util vendor 11st LARSON.C E Northern States Power Co 84/03/12 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 4pp 22671 105 24% Fiche 50-282,84/03/12,8403190200
- B403300036 Forwards IE Insp Repts 50-282/84-02 & 50-306/84-02 on B40213-17 No noncompliance noted PAPERIELLO.C J. Region 3. Office of Director 84/03/15 LARSON.C E Northern States Power Co 2pp. 22821 320 24X Fiche 50-282
- --8403300040 IE Insp Rspts 50-282/84-02 & 50-306/84-02 on 840215-17. No violations or deviations identified Major areas inspected, implementation of iOCFR20 & 60 requirements for disposal of low levsi redwastss, including mgt controls & 60 ROZAKS 9. DESTMANN.M J. BCHUMACHER.M C Region 3, Office of Director 84/03/15 5pp. 22821.322 24X Fiche 50-282,84/03/15,8403300036
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" 8vc llst encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Bafety-Related Bys " Svc list encl JORDAN.E.L Division of Emergency Prsparedness & Englneering Response (Post 830103) B4/03/2i Consolidated Edison Co of Nsw York, Inc 135pp 22933 001. 24X Fiche 50-000,84/03/2i,8402090044
- B403270170 Forwards "Inservice Insp Exam Summary,831204-23 " Rept idsntifies components examined, exam methods used, exam number & summarizes results Results Indicated that integrity of sys maintained MUSCLF, D. Northern Btates Power Co. B4/03/23 Dffice of Nuclear Reactor Regulation, Director 2pp 22771 144 24X Fiche 50-282,84/03/23,8403270170
- --8403270181 "Inservice Insp Exam Summary.831204-23 "
 ANDERSON.H T , KROMPOS.P J Northern States Power Co. 84/03/15
 150pp 22771 146 24X Fiche.50-282.84/03/23,8403270170
- R Psrlodic operating reports & related correspondence
- 8403300095 Monthly operating repts for Feb i984 W/840306 ltr DUGSTAD: D . MUSCLF. D Northern States Power Co 84/02/29 9pp 24047.060 24X Fichs 50-282.84/02/29.8403300095
- 8403130245 Forwards "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1983," "Offsite Radiation Dose Assessment, 1983" & Rev 4 to "Offsite Doss Calculation Manual" FEY.F.L. Northern States Power Co 84/03/01 Region 3, Office of Director 1p 22610 143 24X Fiche 50-282,84/03/01,8403130245
- --8403130258 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1983"

 * Northern Statss Power Co 83/12/31 9pp 22610, 144, 24X
 Fiche 50-282, 84/03/01, 8403130245
- --B403130270 "Offsite Radiation Dose Assessment,1983," * Northern States Power Co 83/12/31 App 22610 153 24X Fichs 50-282,84/03/01,8403130245.
- --8403130278 Rsv 4 to "Offsite Doss Calculation Manual " BORENSON, J Northsrn States Power Co B4/11/14, 11pp, 22610 157. 24X Fiche 50-282, 84/03/01, 8403130245
- S Reportable occurrences, LERs & related correspondence
- 8211220027 Discusses problems associated w/disset generator surveillance tests, as demonstrated in 820827 testing of diesel gensrator D=2 Hispositioning of auto/manual switch could render sys unable to perform design function CHIRAMAL, H. Reactor Operations Analysis Branch 82/11/17, 82YPRITK V. Reactor Operations Analysis Branch, 2pp. 22775 165 24X Fiche 50-282,82/11/17,8211220027

1

- DOCKET 50-285 FORT CALHOUN STATION, UNIT 1
- F Becurity, medical, emergency & fire protection plans
- B403050099 Requests that transmittal sheets confirming receipt of revised emergency pian implementing procedures be returned within 5 days of receipt United W C Daham Public Power District B3/06/02 COLLINS, J T Region 4. Defice of Director 1p 22485 241 24x Fichs 50-285, 83/06/02, 8403050099
- B4032BD165 Forwards public version of revised emergency plan implementing procedures W/o procedures W/JM Felton 840322 release memo
 JONES, W C Omaha Public Power District 84/01/10 COLLINS, J T Region 4, Office of Director 2pp 22807 270 24X Fichs 50~285,84/01/10,8403280165
- 8403280193 Forwards public version of changes to radiological emergency response plan W/o changes W/JM Felton 840322 release memo JONEB.W C Omaha Public Power District 84/01/10 COLLING.J T Region 4. Office of Director 2pp 22789:340 24X Fiche 50-285,84/01/10,8403280193
- 8403050138 Submits scenario for providing emergency preparedness info, per NRC 820114 ltr & revised amergency preparedness rule published 800819 COLLINS.J.T. Region 4, Office of Director 84/02/09 JONES, W.C. Omaha Public Power District 2pp 22490 001 24X Fiche 50-285, 84/02/09, 8403050138
- B403050512 Forwards order confirming util commitments on emergency response capability, per Generic Ltr S2-33 Order based on commitment contained in util 830415 ltr W/o enci MILLER, J R Operating Reactors Branch 3 84/02/22 JONES, W C Omsha Public Power District ip 22552 164 24X Ficha 50-285, 84/02/22, 8403060512
- 8403120062 Revs to emergency plan implementing procedures, including OBC-6. "General Emergency Actions," OBC-12, "Accidental Actuation of Early Warning Siren Sys" & OBC-14, "Emergency Duty Actions " W/840301 transmittal & receipt form # Umaha Public Power District 84/03/01 39pp 22591 031 24X Fiche 50-285,84/03/01.8403120062
- 8403170154 Forwards changes to emergency plan implementing procedures H/o encl
 JONES, W C. Omahm Public Power District 84/03/05 COLLINS, J T
 Region 4, Office of Director ip 22668 345 24X
 Fiche 50-285, 84/03/05, 8403190154
- B403090234 Revised radiological emergency response plan procedures, including Procedures R5, "Notification Methods & Procedures" & R2, "Radiological Exposure Control " W/B40306 itr JONES, W C Omaha Public Power District B4/03/06 COLLINS, J T Region 4, Office of Director 59pp 22572 227 24x Fiche 50-285, B4/03/06, B403090234
- P Operating license stage documents & correspondence
- 8402170136 Forwards application for amend to License DPR-40, changing Tech Bpec Sections 1 i,i 3.2 1 i,2 i 2,2 3,2,i0 2 & Tables 1-1,2-2,3-1 & 3-5, to eliminate requirement to inspect fuel 1-1:2-26:3-1 & 3-3, to similate requirement to inspect run.
 slements removed from vessel sach refueling
 s LaBosuf, Lamb, Leiby & MacRae * Omaha Public Power District
 84/02/14, DENTON, H Office of Nuclear Reactor Regulation, Director
 3pp. 22299:146 24X Fiche 50-285,84/02/14,8402170156
- --8402170166 Application for amend to License DPR-40, changing Tech Spec Sections 1 i.i.3, 2 i.i.2, i.2, 2 3, 2 i0 2 & 2 i0 4 & Tables i-1,2-2,3-1 & 3-5 to eliminate requirements to inspect fuel elements removed from vessel each refueling JONES W. C Omaha Public Power District 84/02/07 2pp 22299:149 24X Fiche 50-285,84/02/14,8402170136
- --8402170176 Proposed Tech Specs i 1.1 3,2.1.1.2 i,2,2 3,2 10 2 & Tables 1-1,2-2,3-1 & 3-5, eliminating requirement to inspect fuel elements removed from vessel each refueling # Omaha Public Power District 84/02/09 i40pp 22299 i5i 24X Fiche 50-285.84/02/i4,8402170156
- B40GD10312 Forwards proprietary & nonproprietary add1 info restatistical combination of uncertainties rept.per B40213 request.Application for withholding & C-E affidavit encl Proprietary info withhold (ref 100FR2 790)
 JONES, W. C. Omaha Public Power District 84/02/24 MILLER, J. R. Operating Reactors Branch 3 20pp. 22432 283 24X Fiche. 50-285, 84/02/24,8403010312

- B403060396 Responds to Generic Ltr 84-01 re use of terms important to safety & safety-related Steering Committee of Util Safety Classification Group will represent util in further Classification of the discussions
 JONES, W C Omaha Public Power District 84/02/29 TAYLOR, J M
 Director's Office, Office of Inspection and Enforcement ip
 22518 132 24X Fiche 50-285, 84/02/29, 8403040396
- 8403120183 Forwards application for amend to License DPR-40, revising Tech Specs to add limiting conditions for operation, surveillance requirements & administrative requirements, per
 - REG-0737 LeBoouf, Lamb, Leiby & MacRae * Omaha Public Power District /03/09 DENTON.H Office of Nuclear Reactor Regulation, Director pp 22585 200 24X Fiche 50-285,84/03/09,8403120183 84/03/09
- --B403120192 Application for amend to License DPR-40, revising Yech Specs to add limiting conditions for operation, surveillance requirements & administrative requirements, per NUREG-0737 JONES W C Dmaha Public Power District B4/03/08 2pp 22585 203 24% Fiche 50-285.84/03/09,8403120183
- -8403120195 Proposed Tech Speca re limiting conditions for operation, surveillance requirements & administrative requirements # Omaha Public Power District 84/03/09 14pp 22585 205 24x Fiche 50-285,84/03/09.8403120183
- 8403130458 Forwards schedule for addi submittal of radiological effluent Tech Specs based on results of 790330 assessment & manpower requirements for 1984 refueling outage Next submittal will resolve remaining issues
 JONES.W C Omaha Public Power District 84/03/09 MILLER.J R Operating Reactors Branch 3 3pp 22613 352 24X
 Fichs 50-265.84/03/09.8403130458
- 8403280183 Forwards request for add1 info re 840214 request concerning Cycle 9 operation Response requested within 30 days of itr receipt in order to maintain review schedule W/o encl MILLER, J R Operating Reactors Branch 3 84/03/12 JONES, W C Omaha Public Power District ip 22809 289 24X Fiche 50-285,84/03/12,8403280183
- O Inspection reports, IE Builetins & correspondence
- 8403240148 Forwards IE Insp Rept 50-285/83-34 on 831212-14 No violations or deviations noted GAGLIARDD, J E Region 4, Office of Director 84/01/19 JONES,W C Omaha Public Power District 2pp 22757 336 24X Fiche 50-285,84/01/19,8403260168
- --8403260172 lE Insp Rept 50-285/83-36 on 831212-14 No violetions or deviations noted Major areas inspected transportation & soild radwaste program including mpt controls, selection of packages, delivery of packages & records & repts HOLLEY,W L , MURRAY,B , JOHNSON,W D Region 4, Office of Director 84/01/12 5pp 22757 338 24X Fiche 50-285,84/01/17,8403260168
- 8402210338 Forwards SALP Rept 50-285/83-28 for Sept 1982 Aug 1983 Overall performance satisfactory
 COLLING.J T Region 4, Office of Director 84/02/10 JONES.W C
 Omaha Public Power District 2pp 22346 238 24X
 Fichs 50-285.84/02/10,8402210338
- --8402210343 Forwards SALP Rept 50-285/83-28 for Sept 1982 Avg 1983 GAGLIARDD, J E Rejon 4, Office of Director 83/12/14 JONES, W C Omaha Public Power District 4pp 22346 24X Fiche 50-285, 84/02/10, 8402210338
- --B40221034B BALP Rept 50-285/83-28 for Sept 1982 Aug 1983 No noncompliance noted Major areas inspected mgt involvement in assuring quality, approach to resolution of technical issues & responsiveness to NRC initiatives

 JOHNSON, W D , GAOLIARDO, J E Region 4, Office of Director B3/12/13 42pp 22346 244 24X Fiche 50-285.84/02/10,8402210338
- --8310040317 Forwards evaluation of LERs for Sept 1982 Aug 1983 Util LERs among best reviewed BEYRRIT.K V Reactor Operations Analysis Branch 83/09/28 SEIDLE.W C Division of Resident, Reactor Project & Engineering Programs 4pp 22346,286 24X Fiche 50-285.84/02/10/8402210338
- --8402210357 Forwards responses to SALP Rept 50-285/83-28 ALARA program under review to improve affectiveness Radwaste coordinator position will be created Internal audit program strangthened
 JONES, W C Omaha Public Power District 84/01/10 GA
 Region 4, Office of Director 12pp 22346 270 24X
 Fiche 30-285:84/02/10:8402210338 GAGLIARDO, J E

- 8402170136 Forwards application for amend to License DPR-40, changing Tech Spec Sections 1 1.1 3.2 1 1.2 1 2.2 3.2.10 2 % Tables 1-1.2-2.3-1 % 3-5, to eliminate requirement to inspect fuel elements removed from vestel sech refueling * LeBosuf, Lamb. Leiby & MacRae * Dmaha Public Power District 84/02/14 DENTON, H Dffice of Muclear Reactor Regulation, Director 3pp 22299 146 24X Fiche 50-285.84/02/14,8402170156
- --8402170166 Application for amend to License DPR-40 changing Tech Spec Sections 1 1.1 3.2 1 1.2 1 2.2 3.2 10 2 & 2 10 4 & Yables 1-1.2-2.3-1 & 3-5 to eliminate requirements to inspect fuel elements removed from vessel each refueling JONES. W C Omaha Public Power District 84/02/07 2pp. 22279 147 24X Fiche 50-285,84/02/14.8402170156
- --8402i70176 Proposed Tech Specs i 1.1 3.2 1 1.2 1 2.2 3.2 10 2 & Tables 1-1.2-2.3-1 & 3-5. eliminating requirement to inspect fuel elements removed from vessel each refueling *Omaha Public Pouer District 84/02/09 140pp 22279 i51. 24X Fiche 50-285.84/02/14.8402170156
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Mator Operated Valve Control Circuits & Annunciation " Svc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Cansolidated Edison Co of New York, Inc. 113pp 22707 237 24X Fichs 50-000.84/02/28,8401170072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Fransport Regulatory Revs by DDT & NRC." Svc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830603) 8403/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fithe 50-000,84/03/02.8402090007.
- 8402090009 IE Info Notice 84-16, "Fatiure of Automatic Sprinkler Sys Valves to Operate " Svc iist encl. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York. Inc. 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- B402090009 IE Info Notice B4-15. "Reporting of Radiological Releases" Svc list enci
 JORDAN.6 L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. i19ρp 22553 217 24X Fiche 50-000.84/03/02.8402090009
- 840209001i IE info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc iist encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York Inc ii7pp 22553 336 24X Fiche 50-000,84/03/05,840209001i
- 8403120147 Submits tabulation of comparative analysis results of unknown liquid sample Results will appear in next confirmatory measurements inspired Criteria for comparing analytical measurements encl GAGLIARDO, J E Region 4, Office of Director 84/03/06 JONES, W C Omaha Public Power District 3pp 22585 254 24X Fiche 50-285,04/03/06,0403120147
- 8402090024 lE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc iist encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc i18pp. 22635 049, 24X Fiche 50-000, 84/03/07, 8402090024
- 840209002B IE Jnfo Notice 84-18. "Stress Corrosion Cracking in PWR Bys " Byc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403190057 Ack receipt of B40203 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-285/83-31 Implementation of corrective actions will be reviewed during future insp GAGLIARDO. J E Region 4, Office of Director 84/03/08 JONES, W C Omaha Public Power District ip 22666 128 24% Fiche 50-285,84/03/08,8403170057
- --840319006i Responds to NRC 840105 ltr re violations noted in IE Insp Rept 50-285/83-31.Corrective actions weekly review of radiation work permits discontinued in favor of deily, weekly, monthly & special surveys of radiological conditions JONES: W C Dmaha Public Power District 84/02/03 DENISE, R P Division of Resident, Reactor Project & Engineering Programs 3pp 22666 129 24X Fiche 50-285,84/03/08,8403190057

- 8403130200 Forwards response to 1E Builetin 80~11, "Masonry Wall Design," per 840200 request Damping values of 2% for DBE & 4% SSE used for unreinforced masonry walls JDNES.W C Omaha Public Power District 84/03/09 MILLER, J R Operating Reactors Branch 3 7pp 22613 079 24X Fiche 50~285.84/03/09,8403130200
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fichs 50-000.84/03/12,8402090031
- 8403190279 Ack receipt of 840214 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/83-30 OA0LIARDOJE Region 4, Office of Director 84/03/13 JONES,W C Omaha Public Power District 1p 22672 029 24X Ficha 50-285,84/03/13,8403190279
- --840319028i Responds to 840123 telcon re violations noted in IE Insp. Rept 50-285/83-30 Corrective actions. Engineering Evaluation/ Assistance Request FC-84-08 initiated on 8401i6 to upgrade decontamination facility including shower, stail & plumbing JONES W C Omaha Public Power District 84/02/14 DENISE, R P Division of Resident, Reactor Project & Engineering Programs 2pp 22672 030 24X Fiche 50-285,84/03/13,8403190279
- E403270249 Forwards replacement Pages i.7.8.23.29 & 50 to 1983-1993 inservice insp program plan dtd 830926 Reasons & justification for changes & exemptions listed JONES.W C Omaha Public Power District 84/03/19 MILLER.J R Operating Reactors Granch 3 2pp 22772 105 24X Fiche 50-285.84/03/19.8403270249
- 8402070043 iE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of Naw York, Inc 123pp 22823 227 24X Fichs 50-000,84/03/21,8402070043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys "Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403050i35 "Annual Rept for Tech Spec Section 5 9 1 0,1983" & "Bemiannual Rept for Tech Spec Section 5 9 4.Jul-Dec 1983." W/840301 ltr JDNES.W C Omaha Public Power District 83/12/31 200pp 22489 172 24% Fiche 50-285.83/12/31.8403050135
- B403200176 Monthly operating rept for Feb 1984 W/840313 itr MATHEWR.TP , JONES W C Omaha Public Power District 84/02/29 DEYOUNGR C Director's Office Office of Inspection and Enforcement 10pp 22699 327 24X Fiche 50-285,84/02/29, 8403200176
- 8 Reportable occurrences, LERs & related correspondence
- 8403030124 LER 84-001-00 on 840122, crans supervisor left spant fuel pool area while key still in interlock bypass switch in bypassed position, contrary to Tech Spec 2 11(2) Caused by personnel error Event discussed w/Individual W/840222 ltr RICHARD, A W. JONES, W. C. Omaha Public Power District 84/02/22, 3pp 22489 162 24X Fichs 50-285, 84/02/22, 8403050124
- DOCKET 50-284 INDIAN POINT STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- B40302017i Forwards order confirming util commitments to implement requirements of Suppl 1 to NUREG-0737 Order based on B30418 & 0823 ltrs in response to Generic Ltr 82-33 VARGA, B A Operating Reactors Branch 1 84/02/21 BAYNE, J P Power Authority of the State of New York 4pp 22491 091 24X Fiche 50-286.84/02/21,840302017i
- --8403020175 Order confirming licensee 830418 & 0823 commitments on emergency response capability, per requirements of Suppl 1 to NUREO-0737 & Generic Ltr 83-33 EISENHUT, D G Division of Licensing 84/02/21 Pawer Authority of the State of New York 6pp 22491 095 24X Fiche 50-286,84/02/21,8403020171

- 8403020352 Advises that NRC wiii not review emergency plans to delete privacy or propriatary info unless specifically requested by licansee.per 810709 Genaric Ltr 81-27 W/o request, entire plan will be placed in PDR POLK.P J Operating Reactors Branch i 84/02/21 BAYNE, J P Power Authority of the State of New York 3pp 22492 222 24X Fichs 50-286,84/02/21,8403020352
- 8403020333 Forwards IE Insp Rept 50-286/84-01 on 840109-ii No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/02/21 BRONS, J C. Powar Authority of the Stata of New York 2pp 22439 023 24X Ficha 50-286/84/02/21/8403020353
- --8403020357 IE Insp Rapt 50-286/84-01 on 840109-11 No violations noted Major areas inspacted public prompt notification sys WOUNAS,E J , CROCKER,H W Region 1, D4fica of Director 84/02/17 3pp. 22439 025 24X Ficha 50-286
- B402070006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisanhut re fire research results concerning firas in alactrical cabinats in control room EIBENHUT.D.O Division of Licensing 84/02/23 PALLADING Commissioners ip 22576 203 24% Ficha 50-000,84/02/23, 8800000004
- --8403080316 Racommends that info re fire research results concarning fires in electrical cabinats in control room be submitted for board notification.per NRR Ofc Ltr 19, dtd 821001 Further avaluation of test data raquired VOLLMER.R H Division of Engineering 84/02/06 EISENHUT, D 0 Division of Licensing 10pp 22576 204 24X Fiche 50-000,84/02/23,8402090006
- 84030902il Ravised emargency plan procedures, including Procedures IP-1011 re offsite monitoring, IP-1021 re radiological medical emergency & IP-1063 ra vahicie/equipment radiological check & decontamination W/840308 ltr * Powar Authority of the State of Naw York 84/03/05 43pp 22575:001 24% Ficha 50-286, 84/03/05, 8403090211
- 8403130162 Forwards remaining fee for review of Rev 8 to physical sacurity plan.per 10CFR170 22 Review interpreted as Class II fee Remittance paid under protest pending final detarmination of legality of fee schedule RAYNE, J.P. Power Authority of the State of New York 84/03/05 B10698 R M Licanse Fee Management Branch 2pp 22615 214 24% Fiche 30-286.84/03/05.8403130162
- B403190243 Notification of B40418 workshop in King of Prussia.PA to discuss lassons learned from recent App R fira protection safe shutdown insp & topics described in IE Info Notice B4-07 Agenda for workshop ancl.

 HURLEY, T. E. Region i, Office of Director B4/03/07 D'TOOLE, J D Cansolidated Edison Co of New York. Inc CAREY, J J Duquesne Light Co. MARTIN.T J Public Bervica Electric & Oas Co of New Jersay 35pp 22672 062 24X Ficher 50-000, B4/03/09, B403190243.
- 8403190258 Ack racaipt of 840214 ltr informing NRC of steps taken to correct violations noted in 16 Emergency Preparednass Appraisal Rept 50-286/81-05 MARTIN.T T. Division of Engineering & Technical Programs 84/03/13 BRONS.J C Power Authority of the State of New York 2pp 22672 221 24X Fiche 50-286.84/03/13.8403190258
- --8403170265 Responds to NRC Billi19 ltr re violations noted in IE
 Emergancy Praparadness Appraisal Rept 50-286/81-05
 Corractive actions post-accident instrumentation & sampling
 requirements per NUREO-0737 & Reg Guida i, 97 implamentad
 BRONB, J C Powar Authority of the State of New York 84/02/14
 MARTIN, T T Division of Enginaering & Technical Programs 2pp
 22672 223, 24X Fiche, 50-286, 84/03/13, 8403190258
- 6403190276 Responds to 840208 request for info re emergency operations facility (EOF), spacifically praliminary cost estimate for upgrade to everall radiation protection factor of five Existing EOF meats Suppl 1 to NUREG-0737 requirements BAYNE.J P Consolidated Edison Co of Naw York, Inc 84/03/14 VARGA.8. Operating Reactors Branch 1 2pp 22674 354 24X Ficha 50-286,84/03/14,8403190276

H General correspondance

84030i0170 Forwards Resolution 76 authorizing County participation in four-county radiological planning task force & authorizing use of County employees for radiological emergency responsa pregaradness Implamentation requested W/Certificate of Svc SEIGERMAN.V K Rockland County, NY 84/02/15 PALLADING.N Commissioners 3pp 22435 307 24% Fichs 50-247,84/02/15.

J Insurance & indemnity information

- 8403260197 Forwards Endorsament 4B to NELIA Policy NF-236, Endorsaments 69 & 72 to NELIA Policy NF-20B, Endorsement 39 to MAELU Policy MF-77 & Endorsement 67 to NELIA Policy NF-230 GOLDEN.M P Marsh & McLennan. Inc B4/03/12 SALTZMAN.J Assistant Director for Stata & Licensee Relations 6pp 22751 033 24X Fiche 50-000.84/03/12.8403260197
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 8403050020 Responds to FDIA request for documents re PASNY submittal on sys interactions, repts evaluating submittal & list of repts/analyses from LLL evaluating PASNY sys interaction program Forwards App A documents
 FELTON.J M Division of Rules and Records 83/12/07 SHOLLY, 8 Union of Concerned Scientists 6pp 22525 098 24x
 Fiche 50-000.83/12/07.8403080020
- --7912030323 Requests commants on 791012 ACRS ltr re sys interaction
 Plans inhouse meeting for 791115
 SCHWENCER, A Operating Reactors Branch i (Pre 800428) 79/11/09
 HANAUER, S Assistant Director for Plant Systems ZECH, O
 Division of Operating Reactors GAMMILL, W Assistant Director for
 Operating Reactor Projects (Pre 791030) 1p 22527 146 24X
 Fiche 50-000,83/12/07,8403050020
- --B208070297 Provides status rept on NRC evaluation of iicansee sys interaction study Initial guidance delayed pending furthar cost/banefit analysis Generic program review planned for Fall 1982
 GOODWIN,E F Technical Support Branch B2/07/30 FRALEY,R FACRS Advisory Committee on Reactor Safeguards 2pp 22526 265 24% Fiche 50-000, 83/12/07, 8403050020
- --8403050034 Discusses 771113 meeting re ACRS ltr on Indian Point 3 sys interactions 8CHWENCER: A Operating Reactors Branch i (Pre 800428) 77/12/05 EISENHUT: D G Division of Operating Reactors 2pp 22527 147 24X Fichs 50-000:83/12/07.8403050020
- P Operating license stage documents & correspondence
- 8403050017 FOIA requast for SECY-78-549.UCID-19310, "Review of PASNY Bys Interaction Study" & records of NRC staff & consultant review of PASNY sys interaction study on Indian Point Unit 3 SHOLLY, S C Union of Concerned Scientists 83/10/20 FELTON, J M Division of Rules and Records ip 22525 097 24X Fiche 50-286.83/10/20,8403050017
- B403050020 Responds to FOIA request for documents re PASNY submittal on sys interactions.repts evaluating submittal & list of repts/analyses from LLL avaluating PASNY sys interaction program Forwards App A documents FELTON.J M Division of Rulas and Records 83/12/07 SHOLLY.8 Union of Concerned Scienvists App 22525 098 24X Fiche, 50-000.83/12/07.8403050020
- --8103040048 Discussas NRC requests for licensee sys interaction studies Forwards draft ltr to util documenting past advise & requesting meeting date when util ran provide definition & realistic schedule for sys interaction program RUBENSTEIN,L S Assistant Director for Core & Containment Systems 81/02/10 NOWAK,T M Assistant Director for Operating Raactors 5pp 22527 175 24X Fiche 50-000.83/12/07.8403050020
- --8104220881 Summary of 810402 meeting w/vtil.Ebasco.LLL & BNL re status of sys interaction study ROSS,W J Derating Reactors Branch i 81/04/09 Operating Reactors Dranch 1 4pp 22526 192 24X Fichs 50-000.83/12/07.
- --8303080290 "Preliminary Investigation of Interconnacted Bys Interactions for Safety Injection Bys of Indian Point 3 " ALESBO.H P Lawrence Livermore Laboratory 83/03/04 NRC - No Detailed Affiliation Given 33pp 22526 139 24X Fiche 50-000.83/12/07.8403050020
- --8303230119 Notification of 830311 meeting w/BNL & LLL in Bathesda.MD to discuss details of contract scope for application of sys interactions analysis methods to Indian Point 3 GOFFMAN.F NRC No Detailed Affiliation 91
- --8307290506 Notification of 830809 follow-up meeting w/util in Bethesda.MD to discuss sys interaction at facility POLK.P J Operating Reactors Branch i 83/07/22 VARGA.S A Operating Reactors Branch i 83/07/22 VARGA.S A Fiche 50-000.83/12/07.8403050020

- --8308040003 Forwards proposed test for ltr to PASNY requesting info for sys interaction methodology studies Timing for receipt of documents critical to plan for resolving Unresolved Safety Issue A-17 Expedited transmittal requested THADANSIA C Reliability & Risk Assessment Branch 83/06/14 VARCA.S A Operating Reactors Branch i ip 22525 198 24% Fiche 80-000,83/12/07,8403050020
- --B310170712 Identifies info required by ELL from util for contract re sys interaction study covering off normal operating procedures & check-off procedures & lists MORRIS.C Reliabli(ty & Risk Assessment Branch FIN A-0445 83/09/29 PDLK.P J NRC - No Detailed Affiliation Given 28pp 22525 327 24X Fiche 50-000,83/12/07.8403050020
- ---B403050023 "Diagraph-Matrix Application on Indian Point 3 for Sys Interactions," statement of work Related info encl • NRC - No Detailed Affiliation Olven FIN A-0445 B3/12/07 35pp 22525 111 24X Fiche 50-000. B3/12/07, B403050020
- --8403050024 Draft "Evaluation of Indian Point 3 Sys Interaction Analysis Program" * NRC - No Detailed Affiliation Olven 82/02/20 7pp 22525 104 24X Fiche 50-000,83/12/07,8403030020
- --8403050025 Informs that listed individuals will visit site during wk of 831017 Sycs requested & schedule provided Related info encl MORRIS.C Division of Systems Integration (past 811005) FIN A-0455 83/10/04 COFFMAN.F D Division of Systems Integration (post 811005) 21pp 22526 034 24X fiche 50-000,83/12/07,8403050020
- --8403050027 Notification of 831121-23 site visit to obtain info re sys interaction methodology study POLK.P J Operating Reactors Branch i 83/10/31 VARGA.B A Operating Reactors Branch i 2pp 22526 055 24X Fiche 50-000,83/12/07.8403050020
- --8403030029 SYSTEMS INTERACTION EVALUATION PROCEDURE FOR APPLICATION TO INDIAN POINT-3
 LIM, J , ALESSO, H P , RICE, T R Laurence Livermore Laboratory
 FIN A-0405 NUREG/CR-2050 81/04/30 NRC No Detailed
 Affiliation Given 50pp 22526 089 24% Fiche 50-000.83/12/07,
 8403030020
- --8403050035 "Review of PASNY Sys interaction Study "
 ALESSO H P Lawrence Livermore Laboratory KELLY, J E Science
 Applications, Inc Bi/06/15 9pp 22526 196 24x
 Fiche 50-000.83/12/07.8403050020
- --8403050037 Discusses effect of control sys failures on plant safety STOLZ, J F Systems Interaction Branch 80/12/18 Systems Interaction Branch 60/12/18 Systems Interaction Branch ip 22527 158 24X Fiche 50-000,83/12/07,8403050020
- --8403050038 "Review of PASNY Sys Interaction Study "
 ALESSO, H P Lawrence Livermore Laboratory UCID-19130 82/03/01
 7pp 22526 256 24% Fiche 50-000,83/12/07,8403050020
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entireig withheid (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S i Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 30-000,84/02/13,8403080179
- 8403020064 Notification of 840425 meeting w/util in Bethesda.MD to discuss resolution of outstanding issues re electrical equipment environ qualification POLK.P J Operating Reactors Branch 1 84/02/24 VARGA.S A Operating Reactors Branch 1 2pp 22491 194 24X Fiche 50-286.84/02/24.8403020064
- 8403030041 Notification of 840308 meeting w/util in Bethesda.MD to discuss sys interaction study submittal POLK.P J Operating Reactors Branch i 84/02/24 VAROA.S A Operating Reactors Branch i 84/02/24 VAROA.S A Fiche 50-286.84/02/24.8403050041
- 8403050298 Notification of 840327-29 meetings w/util in Buchana,NY to discuss sys interaction study POLK-P J Operating Reactors Branch 1 84/02/24 VAROA,8 A Operating Reactors Branch 1 3pp 22501 264. 24X Fiche 50-286,84/02/24,8403050298
- 8403050044 Forwards SER for NUREQ-0737. Item II B 2 2 re plant shielding Actions taken or planned for post-accident vital area access satisfy requirements of MUREQ-0737 VARGA.S A Operating Reactors Branch 1 94/02/28 BAYNE, J P Power Authority of the State of New York 6pp R252B 318 24X Fiche: 50-286,84/02/28,8403060044

- 8403090267 Forwards updated info re sys interaction study, per util B3i130 ltr Central control room review concerns resolved Twenty connected & 417 of 620 unconnected interactions closed Specific summary/status tables encl BAYNE, J P Power Authority of the State of New York 84/03/06 VARGA. S A Operating Reactors Branch 1 47pp 22572 149 24x Fiche 50-286,84/03/06,8403090267
- 8403i60009 Forwards application for amend to License DPR-64, changing Tech Spec Sections 3 13.4 ii & 6 10 re snubber surveillance BAYNE, J P Power Authority of the State of New York 84/03/12 VARGA, 8 A Operating Reactors Branch 1 4pp 22654 325 24X Fichs 50-286.84/03/12,8403160009
- --B403160017 Application for amend to License DPR-64, changing Tech Spsc Section 3 19,4 11 & 6 10 re snubber surveillance BAYNE, J.P. Pawar Authority of the State of New York B4/03/12 1p. 22654 329 24X Fichs 50-286,84/03/12,8403160009
- --8403160021 Proposed Tech Spec Sections 3 13,4 11 & 6 10 re snubber surveillance Safety evaluation encl * Pawer Authority of the State of New York 84/03/12 16pp 22654 330 24X Fiche 50-286,84/03/12.8403160009
- B402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EIBENNUT.D 0 Division of Licensing. 84/03/14 Atomic Safety and Licensing Board Panel 10pp 22716 338 24X Fiche 50-000,84/03/14,8402090041
- 8403290100 informs that util expects to complete commitment on NUREO-0737, item II B 3 re post-accident sampling sys by June 1985 BAYNE.J P Power Authority of the State of New York 84/03/23 VARGA.8 A Operating Reactors Branch I IP 22806 356 24X Fichs 50-286,84/03/23,8403290100
- 8403290152 Bubmits paragraph inadvertently omitted from 831230 ltr providing status rept on makeup water resin retention filters BAYNE, J P Power Authority of the State of New York 84/03/23 VAROA, 8 A Dperating Reactors Branch 1 ip 22803 321 24X Fiche 50-286,84/03/23,8403290152
- O Inspection reports. IE Bulletins & correspondence
- 8403020353 Forwards IE insp Rept 50-286/84-01 on 840109-11 No violations noted MARTIN: T Division of Engineering & Technical Programs 84/02/21 BRONS, J C Power Authority of the State of New York 2pp 22439 023 24X Fithe 50-286,84/02/21,8403020353
- --8403020357 IE Insp Rept 50-286/84-01 on 840109-11 No violations noted Major areas inspected public prompt notification sys MOJNA9.E J. CROCKER.H W Region 1. Office of Director 84/02/17 5pp 22439 025 24% Fichs 50-286.84/02/21.8403020353.
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN,E L. Division of Emergency Preparedness & Engineering Reaponse (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22707 237 24X Fiche 50-000.84/02/28, 8401179072
- 8403150146 Forwards IE Insp Rept 50-286/84-02 on 840116-0215 & notice of violation
 BTAROSTECKI,R Division of Project & Resident Programs 84/03/01
 BRONS.J C Power Authority of the State of New York 2pp
 22643 027 24x Fiche 50-286.84/03/01.8403150146
- --8403150149 Notice of violation from insp on 840116-0215 * Region i, Office of Director 84/03/01 tp 22643 027 24X Fiche 50-286,84/03/01,8403150146
- --B403150166 iE Insp Rept 50-286/B4-02 on B40116-0215 Violation noted RM sys changes not delineated on sys print or sys checkoff list & safety evaluation not performed KENNY.T J. ROBSBACH.L W. Region 1. Office of Director NORRHOLH; L. Division of Engineering & Technical Programs, 84/02/22 i3pp 22643 030 24X Fiche 50-286.84/03/01,8403150146
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Reys by DOT & NRC " Svc list encl ORACE, J N Division of GA: Safeguards & Inspection Programs (Post 830103) 84/03/02, Consolidated Edison Co of New York; Inc 130pp 22552:329 24X Fiche:50-000.84/03/02,8402090007.

- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list enc! JBRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24% Fiche 50-000,84/03/02,8402090008
- B402090009 IE Info Notice 84-15, "Reporting of Radiological Reieases"

 Bvc list enc!

 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc i19pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nii Durtility Temp " 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05.8402090011
- 8402070024 IE Info Notice 84-07. Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 047 24X Fiche 50-000.84/03/07,8402070024
- 8402090028 IE Info Notice 84-i8, "Stress Corrosion Cracking in PWR 8ye." Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc i18pp 22584 186 24X Fiche 50-000.84/03/07.8402090028
- 8402070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Bafety 8ys " Svc list enc1
 DEYOUNG:R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823-074. 24X Fichs 50-000.84/03/12,8402070031
- 8403190258 Ack receipt of 840214 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Rept 50-286/81-05 MARTIN, T T Division of Engineering & Technical Programs 84/03/i3 BRONS, J C Power Authority of the State of New York 2pp 22672 221 24X Fiche 50-286,84/03/13,8403190258
- --8403190265 Responds to NRC Billi9 itr re violations noted in IE
 Emergency Preparedness Appraisal Rept 50-286/81-05
 Corrective actions post-accident instrumentation & sampling requirements per NUREO-0737 & Reg Oulde 1 97 implemented BRONS, J C Power Authority of the State of New York 84/02/14
 MARTIN.T T Division of Engineering & Technical Programs 2pp 22672 223 24X Fiche 50-286,84/03/13.8403190258
- 8402090043 IE Info Notice 84-i9, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Bvc list encl JDRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co of New York, Inc 123pp. 22823:229 24X Fiche 50-000,84/03/21,8402090043
- B402070044 IE Info Notice 84-20, "Bvc Life of Relays in Bafety-Related Bys " Bvc list and JDRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York, Inc 135pp 22733:001 24X Fiche 50-000,84/03/21,8402070044
- 8403300175 Forwards response to IE Builetin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " No subj matls provided or used at facility BRONB, J C Power Authority of the State of New York, 84/03/21 MURLEY, T E Region 1, Office of Director 2pp 22820 045 24: Fiche 50-286,84/03/21,8403300175

R Periodic operating reports & related correspondence

- 8403210113 "Summary Rept of Personnel Radiation Exposure by Work & Job Function,1983 " W/840227 ltr BRONS.J.C Power Authority of the State of New York 83/12/3i MURLEY,T.E Region 1, Office of Director 2pp 22705 062, 24X Fiche' 50-286,83/12/31,8403210113
- 8403130256 Forwards "Radioactive Efficient & Waste Disposal, Semiennual Rept. Jul-Dec 1983" BRDN9.J. C Power Authority of the State of New York 84/02/29 MURLEY.T.E Region 1. Office of Director 1p 22616 094 24X Fiche: 50-286.84/02/29,8403130256
- --B403130412 "Radioactive Effluent & Waste Disposal Semiannual Rept. Jul-Dec 1983 " * Power Authority of the State of New York B3/12/31 54pp 22416:095 24% Fiche 50-286, B4/02/29, B403130256

- 8403300159 Monthly operating rept for Feb 1984 W/840315 ltr KELLY,L . BRONS,J C Power Authority of the State of New York 84/02/29 7pp 22821 075 24X Fiche 50-286,84/02/29,8403300159
- S Reportable occurrences, LERs & related correspondence
- B403150047 LER 84-00i-00 on 840125, w/reactor in hot shutdown.code safety valve MS-45 an main steam header 34 opened momentarily Caused by high differential pressure lifting valve Valve reset & tested W/840224 ltr
 GUMBLE.F W BRONS.J C Power Authority of the State of New York 84/02/24 MURLEY.T E Region 1. Office of Director 3pp 22643 13B 24X Fiche 50-286.84/02/24.8403150047
- 8403150050 LER 84-003-00 on 840128, automatic safety injection signal actuated on high differential steam line pressure Caused by code safety valve MS-45 on main header 34 lifting momentarily Valve reset W/840224 itr GUMBLE,F W. BRONS,J C Power Authority of the State of New York 84/02/24 MURLEY,T E Region 1, Office of Director 3pp 22643 143 24X Fiche 50-286,84/02/24.8403150050
- 8403210049 LER 84-002-00 on 840128, w/reactor critical at zero power, trip initiated by intermediate range nuclear instrumentation Caused by blown power supply fuse for Channel 32 Fuse replaced W/B40224 itr GUMBLE.F W. BRONS, J. C. Power Authority of the Btate of New York 84/02/24 MURLEY, T. E. Region 1, Office of Director Jpp 22705 311 24X Fiche 50-286, 84/02/24, 8403210049
- 8403260233 Forwards summary list of deficiencies identified per IOCFR50 55(e),Part 21 & potential generic itr repts for comments STAROBTECK1,R Division of Project & Resident Programs 84/02/28 Region 1. Office of Director 7pp 22736 065 24X Fiche 50-000.84/02/28.8403260233
- B403120152 LER 84-004-00 on B40209.reactor trip actuated on steam flow/feed flow mismatch for steam generator 32 Caused by ioss of both heater drain pumps Associated instrument air iines blown down removing condensation W/840307 ltr GUMBLE.F W . DRONS.J C Power Authority of the State of New York 84/03/07 3pp 22586 178 24X Fiche 50-286.84/03/07.8403120/152
- B40326007i LER B4-005-00 on B40220, reactor trip initiated on steam flow/feed flow mismatch on steam generator 32 Caused by closure of main feed regulating valve due to failed trip solenoid Leads replaced W/B40320 ltr ANDERBON. J J. BRONS. J C Power Authority of the Btate of New York B4/03/20 3pp 22747 341 24X Fiche 50-286. B4/03/20. 8403260091
- 8403260257 LER 84-006-00 on 840309, during monthly reactor protection sys testing, turbine tripped Caused by inadvertent closure of ceil switch associated w/reactor trip bypass breaker 52/BVB Catch realigned W/840320 itr ANDERBON, J J , BRONS, J C Power Authority of the State of New York 84/03/20 3pp 22755 142 24X Fiche 50-286,84/03/20,8403260257

T Hearing transcripts on non-antitrust matters

- 8403160004 Transcript of ACRS Subcommittees on Reliability & PRA & Indian Point Units 2 & 3 840314 meeting in Washington.DC Pp 1-60 Bupporting documentation enci
 * ACRS Advisory Committee on Reactor Safeguards, 84/03/14 61pp 22653 289 24X Fiche 50-247.84/03/14.8403160004
- V Operator Examinations
- B40i200078 Forwards operator licensing exam schedule for FY84-B7.in response to Generic Ltr 83-40 NRC will be informed of changes BAYNE, J P Pawer Authority of the State of New York B4/01/16 EIBENHUT, D G Division of Licensing, 4pp 21862 357 24X Fiche 50-286.84/01/16.8401200078
- DOCKET 50-287 OCONER NUCLEAR STATION, UNIT 3
- F Becurity, medical, emergency & fire protection plans
- 8403090254 Public version of revised crisis mgt plan implementing procedures, including Procedures 5 3 4 re scheduling/planning support group, 5 3 6 re radiological support group & 5 3 7 re technical support group W/831107 ltr & JM Felton memo TUCKER, H B Duke Power Co 83/10/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 271pp 22595 055 24% Fiche 50-000, 83/10/31, 8403090254

- B403060225 Rev \$1 to crisis mgt plan W/B40224 itr & public info pamphlet VAUGEN.T E , TUCKER.H B Duke Power Co 84/02/02 DENTON.H R Office of Nuclear Reactor Regulation. Director 66pp 22516 189 24X Fiche 50-000.84/02/02.8403050225
- 8403160134 Forwards IE Insp Repts 50-269/84-04, 50-270/84-04 & 50-287/84-04 on 840201-02 No violations or deviations identified DANCE, H C Division of Project & Resident Programs 84/02/16 TUCKER, H B Duke Power Co 2pp 22655 336 24X Fiche 30-269,84/02/16,8403160134
- --8403160141 1E Insp Repts 50-269/84-04,50-270/84-04 & 50-287/84-04 on 840201-02 No violations identified Major areas inspected emergency preparedness areas of protective action decisionaking CLINE,W E Region 2, Office of Director 84/02/15 4pp 22655 338 24X Fiche 50-269,84/02/16,8403160134
- 8403090222 Forwards Rev 3 to training & qualification plan Rev withheld (ref 10CFR73 21) TUCKER,H B Duke Power Co 84/02/29 O'REILLY, J P Region 2, Office of Director 1p 22575 149 24X Fiche 50-269, 84/02/29, 8403090222
- 8403160278 Extends invitation to attend 840316 workshop to discuss IOCFR50. App R requirements & results of recent insp to help resolve misunderstanding associated whrequirements LEWIS.R C Division of Project & Resident Programs 84/03/02 TUCKER.H B Duke Power Co ip 22660 274 24X Fiche 50-000.84/03/02.8403160278
- 8403160245 Forwards summary of 840228 meeting w/util in Atlanta, GA re 10CFR50 48 & 10CFR50. App R fire protection application Attendance list also encl LEWIS, R C Division of Project & Resident Programs 84/03/07 TUCKER, H B Duke Power Co 3pp 22660 312 24X Fiche 50-269, 84/03/07.8403160245
- 8403120119 Advises that 840114 Rev 11 to physical security planconsistent w/provisions of 10CFR50 54(p) & acceptable LEWIS,R C Division of Project & Resident Programs 84/03/08 TUCKER,H B Duke Power Co 2pp. 22587 217 24X Fiche 50-269,84/03/08.8403120119
- 8403290069 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-269/83-36. 50-270/83-37 & 50-287/83-36 implementation of corrective actions will be examined during future insp DANCE: H C Division of Project & Resident Programs 84/03/20 TUCKER: H D Duke Power Co ip 22807 011 24% Fiche 50-269,84/03/20,8403290069
- --8403290108 IE Insp Repts 50-269/83-36:50-270/83-37 & 50-287/83-36 on 831111-1210 Violation noted failure to follow Maint Procedure 270/83-37-01 re quality performed on Reactor Comiant Pump 282
 BRYANT. J Region 2. Office of Director 84/01/09 10pp 22807 017 24x Fiche 50-269,84/03/20.8403270069
- 8403270209 Forwards Rev 4 to util response to NUREO-0737, Suppl 1.
 Including control room review implementation priority
 schedule
 TUCKER, M B Duke Power Co 84/03/23 DENTON, H R Office of
 Nuclear Reactor Regulation, Director STULZ, J F Operating Reactors
 Branch 4 9pp 22772 088 24X Fiche 50-269, 84/03/23, 8403270209
- P Operating license stage documents & correspondence
- 8403060272 Submits response to NRC request for schedular info re SER of proposed inadequate core cooling instrumentation Final design description will be submitted by 850701
 TUCKER.H D Duke Power Co 84/02/28 DENTON.H R Office of Nuclear Reactors Regulation. Director 87012.J F Operating Reactors Branch 4 2pp 22518 124 24X Fiche 50-269,84/02/28,8403060272
- 8403150328 Forwards Amends 127,127 & 124 to Licenses DPR-3B, DPR-47 & DPR-55, respectively & safety evaluation Amends revise Teck Specs to implement limiting conditions for operation in event one startup transformer out of syc STDLZ.J F Operating Reactors Branch 4 84/03/02 TUCKER, H B Duke Power Co 2pp 22649 274 24% Fiche 50-269,84/03/02, 8403150328
- --8403150335 Amends 127.127 & 124 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs to implement limiting conditions for operation in event one startup transformer out of svc SIDLZ.JF Operating Reactors Branch 4 84/03/02 21pp 22649 276 24X Fiche 50-269, 84/03/02.8403150328

- --B403150344 Safety evaluation supporting Amends 127,127 & 124 to Licenses DPR-36,DPR-47 & DPR-55,respectively * Office of Nuclear Reactor Regulation, Director B4/03/02 2pp 22649 297 24X Fichs 50-269,84/03/02,8403150328
- O Inspection reports. IE Bulletine & correspondence
- 8403070364 Forwards IE Insp Repts 50-269/83-11.50-270/83-11 & 50-287/83-11 on 830317-28 Enforcement action addressed in NRC 830402 Itr LEMIS.R C Division of Project & Resident Programs 83/06/02 TUCKER.H B Duke Power Co 2pp 22546 025 24X Fithe 50-269, 83/06/02.8403070364
- --8403070369 IE Insp Repts 50-269/83-11.50-270/83-11 & 50-287/83-11 on 830317-28 Violations noted loss of containment integrity on 830317 & 21 & failure to mest requirements of confirmatory order dtd 810710 re independent verification BRYANT, J. FALCONER, D. Region 2. Office of Director IGNATONIS, A Division of Project & Resident Programs 83/06/02 10pp 22346 027 24X Fiche 50-269.83/06/02,8403070364
- B403160134 Forwards IE insp Repts 50-269/84-04.50-270/84-04 & 50-287/84-04 on 840201-02 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/16 TUCKER.H B Duko Power Co 2pp 22655 336 24X Fiche 50-269.84/02/16.8403160134
- --8403160141 IE Insp Regts 50-269/84-04.50-270/84-04 & 50-287/84-04 on 840201-02 No violations identified Major areas inspected emergency preparedness areas of protective action decisionmaking CLINE.W E Region 2. Office of Director JENKINB.G R Division of Emergency Preparedness & Materials Safety 84/02/15 4pp 22655 338 24X Fiche 50-269.84/02/16.8403160134
- 8403010308 Forwards add1 info re 830815 request for relief from inservice insp requirements (Hydrostatic) of 8ection XI of ABME Boiler & Pressure Vesse) Code Valve 2LPSM-133 cannot be closed due to sheared hinge pins TUCKER.H B Duke Fower Co 84/02/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 8TOL7.J F Operating Reactors Branch 4 2pp 22432 102 24X Fiche 50-269,84/02/23,8403010308
- 8401190072 IE info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, inc. 115pp 22709 237 24X Fiche 50-000,84/02/28,8401190072
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list enci GRACE, J N Division of OA, Bafeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc L30pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402090000 IE Info Notice 84-16. "Failure of Automatic Sprinkler 8ys Valves to Operate " Svc list enc! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 lE info Notice 84-15. "Reporting of Radiological Releases" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02, 8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below NI1 Ductility Temp " Bvc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York. Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402090011
- B40R090024 IE Info Notice B4-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B301031, 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22435.049 24X Fiche 50-000,84/03/07,8402090024
- B40207002B IE Info Natice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list and JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028

- 8402090031 IE Bulietin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list enci DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, inc 124pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- B403290069 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/83-36, 50-270/83-37 & 50-227/83-36 implementation of corrective actions will be examined during future insp DANCE.H C Division of Project & Resident Programs 84/03/20 TUCKER.H B DUR Power Co 1p 22807 011 24X Fishe 50-269, 84/03/20, 8403290067
- --84032900B2 Responds to NRC 840109 ltr re violations noted in IE Insp. Repts 50-269/83-36,50-270/83-37 & 30-287/83-36 Corrective actions Unit 2 staging coil locations corrected & seal packages on Reactor Coolant Pump 282 replaced TUCKER.H B Duke Power Co 84/02/08 O'REILLY.J P Region 2, Office of Director 2pp 22807 012 24X Fiche 50-269,84/03/20. 8803290069
- --8403290090 Forwards IE Insp Repts 50-269/83-36, 50-270/83-37 & 50-287/83-36 on 831111-1210 & notice of violation DANCE.H C Division of Project & Resident Programs 84/01/07 TUCKER.H B Duke Power Co 2pp 22807 014 24X Fiche 50-269, 84/03/20, 8403270067
- --B40327010B IE Insp Repts 50-269/B3-36,50-270/B3-37 & 50-287/B3-36 on B3111-1210 Violation noted failure to follow Maint Procedure 270/B3-37-01 re quality performed on Reactor Coolant Pump 2B2
 BRYANT, J. FALCONER, D. Region 2, Office of Director BROWNLEE, V.L. Division of Project & Resident Programs B4/01/09 10pp 22B07 017 24X Fiche 50-269,84/03/20,B403270069
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21.8402090043
- B402090044 IE Info Nutice B4-20, "Syc Life of Relays in Safety-Related Bys " Syc list anc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/21 Consolidated Edison Co. of New York, Inc. 135pp. 22933 Q01 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403200010 Monthly operating repts for Feb 1984 W/B40315 ltr REAVIS.J A., TUCKER,H B Duke Power Co B4/02/29 17pp 22685 185 24X Fiche 50~269,B4/02/29,B403200010
- V Operator Examinations
- 8403080237 Forwards operator licensing exam schedule through CYBB, in response to Generic Ltr 83-40
 TUCKER, H B Duke Power Co 84/02/27 EISENHUT, D Q Division of Licensing 2pp 2256 023 24X Fiche 50-269,84/02/29,8403080239
- DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- B403140088 Public Version of temporary change notices to amergency plan implementing procedures, including Procedure 1004 B recallout of onsite & offsite duty roster personnel H/ JM Felton 840312 release memb BRADY, J A. PAULEB, J, GRANGE, O J General Public Utilities GPU BBFV1ce Corp. B31(0/27 35pp. 22637 142 24X Fiche, 50-289, 83/10/27, 8403140088
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D Q Division of Licensing 84/02/23 PALLADING, QILINSKY, ROBERTS Commissioners 1p 22576 203 24X Fiche 50-000,84/02/23,8402090006
- --84030B0316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NRR Dfc Ltr 19, dtd 821001 Further evaluation of test data required VOLLMER, R H Division of Engineering 84/02/06 EISENHUT, D 9 Division of Licensing 10pp 22576 204 24X Fiche 50-000, B4/02/23, 8402090006

- 8403010347 Forwards status & justification for nine listed NUREG-0737 * Reg Quide 1 97 items, per 840222 request Analysis of safety parameter display sys will be submitted by 840430 HUKILL.H D General Public Utilities GPU Service Corp 84/02/27 EISENHUT.D Q Division of Licensing 2ipp 22433 018 24X Fiche 90-289,84/02/27.8403010347
- 8403050097 Revised emergency plan implementing procedures, including Procedure 1004 8 re callout of onsite & offsite duty roster personnel & Procedure 1004 21 re emergency repair/ operations

 * Ceneral Public Utilities CPU Service Corp 84/02/28 17pp 22488 047 24% Fiche 50-289,84/02/288,8403050097
- 8403060133 Forwards Rev 19 to security plan Rev restores portions of plan wording re TMI-2 security features modified in Revs 17 & 18 Rev withheld (ref 10CFR73 21)
 HUKILL: B D General Public Utilities OPU Service Corp 84/02/29
 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22506 332 24% Fiche 50-289,84/02/29,8403060133
- 8403120166 Revised emergency plan implementing procedures, including Procedure 1004 36 re warehouse muster.Procedure 1004 4 re general emergency & Procedure 1004 3 re site emergency * General Public Utilities ~ GPU Service Corp 84/03/01 85pp 22590 319 24% Fiche 50~289,84/03/01,8403120166
- 8403120004 Reevaluates response to NUREQ-0737. Item III D 3 4, "Control Roam Habitability," based on PRA technique for ensite & offsite sources App R mods will assure adequate smoke detection in control roam HUKILL.H D General Public Utilities GPU Service Corp 84/03/02 BTOLZ.J F Operating Reactors Branch 4 2pp 22586 306 24X Fiche 50-287.84/03/02.8403120004
- B403220141 Rev 9 to Procedure 1004 6. "Add1 Assistance & Notification " * General Public Utilities - GPU Service Corp B4/03/06 21pp 22714 288 24X Fiche 50-289,84/03/06,8403220141
- 8403130286 Informs that annual emergency exercise scheduled for 841003, per 10CPR50. App E requirements Limited participation planned by Commonwealth of PA, five risk counties & local municipalities

 HUKILL-H D General Public Utilities GPU Service Corp 84/03/08

 Office of Nuclear Reactor Regulation, Director 1p 22605 180

 24X Fiche 50-289, 84/03/08, 8403130286
- 8403190243 Notification of B40418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice B4-09 Agenda for workshop enci MRLEY, TE Ragion 1. Office of Director B4/03/09 D'TDOLE, J o Consolidated Edison Co of New York, Inc CDUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) RHODE, G K Niagara Mohawk Power Corp 35pp 22472 042 24X Fichs 50-000.84/03/09.8403190243
- 8403270315 Advises that emergency plan documented in NUREO-0746, "Emergency Preparedness Evaluation for TMI-1" & Suppl 1, NUREO-0737, Item III A 2 1, complete for facility STOLZ, J F Operating Reactors Branch 4 BA/03/09 HUKILL, H D General Public Utilities OPU Service Corp 5pp 22789 241 24X Fiche 50-289,84/03/09.8403270315
- 8403270232 Revised emergency plan implementing procedures, including Rev 10 to Procedure 1004 6, "Addl Assistance & Notification" & Rev 4 to Procedure 1004 6, "Offsite Emergency Response Directory "
 OIANOI, O J General Public Utilities OPU Service Corp 84/03/20 220p 22771 354 24% Fiche 50-289,84/03/20,8403270232
- 8403300303 Notification of 840327 meeting w/util in Bethesda.MD to discuss detailed control room design review items relative to requirements of NUREO-0737. Suppl 1 SILVER.H Operating Reactors Assessment Branch, 84/03/20 STOLZ.J F Operating Reactors Branch 4 2pp 22844 307 24X Fichs 50-289.84/03/20.8403300303
- B403290005 Inquires as to whether NRC plans to take any action to correct deficiencies in emergency preparedness for facility identified by FEMA Details of NRC position requested WEISS.E R Harmon & Weiss 84/03/22 STQLZ.J F Operating Reactors Branch 4 lp 22803 281 24X Fiche 50~289,84/03/22,8403290005

Q Adjudicatory correspondence

- B403010009 Requests substitution of Attachment I to 840206 filing w/ ancl & corrects statement re insp or licensee produced documents Driginal Attachment I should be returned GHURCHILL.B W Shau, Pittman, Potts & Troubridge CHURCHILL.B W Hetropolitan Edison Co. 84/02/13 WOLFE.S J. METRICK, D.L., LAMB.J.C. Atomic Safety and Licensing Board Panel 6pp. 22435-221-24X Fiche 50-259.84/02/13,8403010009
- BAD306D0B4 Forwards listed unespurgated ref documents & Topical Rept OO3, Rev 3 W/o entl W/svc list Related correspondence CHURCHILLB W Shaw, Fittman, Potts & Troubridge CHURCHILL, B W Metropolitan Edison Co BA/03/01 DOROSHOW, J. BRADFORD, L. Three Mile Island Alert 2pp 22516 359 24X Fiche 50-287,84/03/01.
- 8403040182 Memorandum & order denying TMI Alert B40123 motion for order compelling discovery & granting licensee 840206 motion for protective order MCLFE,S J Atomit Safety and Licensing Board Panel 84/03/02 Three Mile 1stand Alert 8pp 22518 350 24% Fiche 50-289, 84/03/02.8403506182
- 8403060243 Protective order that licensee shall not be compelled to respond to intervenor. TMI Alert Document Request 22 set forth in 831230 request for production of documents WDLFE.8 J Atomic Safety and Licensing Board Panel 84/03/02 Mitropolitan Edison Co 9pp 22515 181 24X Fiche 50-289,84/03/02.8403060243
- 8403070025 Notice forwarding info re recent resolution of proceeding in which Met Ed was charged w/criminal activity re primary coolant leak rate testing Certificate of Syz encl Related correspondence
 BLAKE.E L Metropolitan Edison Co BLAKE.E L Shaw, Pittman, Potts 5 Trowbridge 84/03/02 63pp 22548 043 24X
 Fiche 50-229,84/03/02,8403070025
- 8403070233 Informs parties that Commissioner Bernthal will tour facility on 840309 Notification of representatives of parties wishing to attend must be made no later than 840308 * Commissioners 84/03/06 pp. 22541 308 24X Fiche 50-289.84/03/06.8403070232
- 8403080105 Errata for licenses motion for summary disposition of each of TMT Alert & Joint Intervenor contention Certificate of Svc encl
 TROWSRIDGE.0 F Metropolitan Edison Co TROWSRIDGE.0 F Shaw,
 Pittaan, Potts & Troubridge 84/03/06 Atomic Safety and
 Licensing Board Panel App 22559 178 24X Fiche 50-289,84/03/05.
- 8403070129 Notice forwarding transcript of 840228 & 29 proceedings & 840301 order by US District Court for Middle District of State of PA re resolution of leak rate test Related correspondence BLAKE.E L Metropolitan Edison Co 84/03/07 Atomic Safety and Licensing Board Panel 89pp 22576 089 24X Fiele 50-289.84/03/07.8403070129
- B403130013 Motion for reconsideration of ALAB-697 in view of new infore emergency planning for farmers ASLAB grossly erred in considering matter of emergency planning for farmers resolved Certificate of Svc encl AAMODT, N O · AAMODT, M M Aamodts 84/03/07 Atomic Safety and Licensing Appeal Panel 33pp 22615 128 24x Fiche 50-289, 84/03/07.8403130013
- 8403140111 Ack receipt of Joint Intervenors 840227 motion to file response to licensee second set of interrogatories out of time Motion viewed discovery between Joint Intervenors & licensee Staff does not intend to file orief on merits MAGNER.M E Hearing Branch 4 84/03/07 WOLFE.S J. LAMB.J C. HETRICK.D L. Atomic Safety and Licensing Board Panel Ip 22623 337 24% Fiche 50-289.84/03/07.8403140111
- 8403130443 Forwards supplemental affidavit of FS Gracobbe clarifying B40223 affidavit Related correspondence CHURCHILL.B W Shaw, Pittman, Potts & Trowbridge CHURCHILL.B W Metropolitan Edison Co 84/03/08 WOLFE, S J , LAMB, J G , HETRICK, D L Atomic Safety and Licensing Board Panel 1p 22613 172 24X Fichs 50-285,84/03/08,8403130443
- --B403130451 Supplemental affidavit of FS Giacobbe, clarifying misleading statement in 840223 affidavib GIACOBBE.F S Metropolitan Edison Co 84/03/07 3pp 22613 173 24% Fiche 50-259,84/03/08,8403130443

- 8403130065 Hotion for extention of time until 840330 to respond to licensee & NRC motions for summery disposition Certificate of Svc encl Related correspondence DERESHOW. J Three Mile Island Alert 84/03/10 Atomic Safety and Licensing Board Panel 50p 22602 ii8 24X Fiche 50-289.84/03/10, 8403130085
- 8403160015 Responds to RC DeYoung 840306 ltr re emergency info pamphlst on farm evacuation plans Suggestion that author initiate & negotiate plans w/Commonwealth of PA unacceptable LEE, J' Affiliation Not Assigned 84/03/12 PALLADING, GILINGKY, ASSELSTINE Commissioners 3pp 22652 359 24X Fiche 30-289,84/03/12.8403160012
- 8403210137 Comments on need to resolve mgt integrity issue prior to MRC restart decision GODDLING. B House of Rep. 84/03/12 UDALL.M K House of Rep. Interior & Insular Affairs 2pp. 22707 251 24x Fiche 50~289.84/03/12,8403210137
- B403200055 Forwards W Washington 840313 memo detailing contacts w/
 Bradford on 840217 W Washington conscientious efforts to
 arrange to obtain documents promised & ordered by ABLB did
 not amount to harassment Related correspondence
 TRCMBRIDGE, G F Shaw, Pittman, Potts & Trowbridge TRCMBRIDGE, G F
 Metrogolitan Edison Co 84/03/14 DROSHOW, J Three Mile Island
 Alert 11pp 22698 296 24X Fiche 50-289,84/03/14.8403200055
- 8403i60007 Second supplemental answer to TMI Alert first set of interrogatories & request for production of documents Computer printput list of documents requested encl Staff objects to Production Request 2 Certificate of Svc encl MAGNER, M E Hearing Branch 4 84/03/15 23pp 22655,174 24x Fiche, 50-289,84/03/15,8403160007
- 8403i60032 Responds to 83i206 ltr re Commission consideration of applicant request for Commission approval of restart Final decision will be made in near future PALLADINO.N J Commissioners 84/03/15 UDALL.M K House of Rep . Interior & Insular Affairs 2pp 22655 141 24x Fiche 80-287.84/03/15.8403160032
- 8403190187 Forwards supplemental affidavit of CE McCracken & CS Wu re clarification to 840224 affidavit in support of staff motion for summary disposition of TMI Alert Contention 1 d HAGNER, ME Hearing Branch 4 84/03/15 HOLFE, B J, LAMB, J C, HETRICK, D L. Atomic Safety and Licensing Board Fanel 1p 22670 357 24X Fiche 50-289,84/03/15,8403190(87
- ---8403190189 Supplemental affidavit of CE McCracken & PC Wu clarifying Paragraph 9 of 840224 affidavit in support of staff motion for summary disposition of TMI Alert Contention 1 d MCCRACKEN.C E. MU.P.C. Division of Engineering 84/03/14 2pp 22670 358 24X Fiche 50-289,84/03/15.8403190187
- 8403200066 Forwards licensee status rept on required actions from Feb 1983 BETA rept, interofc memo re shift monitor program & press release announcing change in Nuclear Safety & Compliance Committee BAUSER. D. B. Shaw. Pittman. Potts & Troubridge BAUSER. D. B. Metropolitan Edison Co. 84/03/15 EDLES, Q. J. BUCK. J. H., KOML. C. N. Atomic Safety and Licensing Appeal Panel. 61pp. 22685-035-24X Fiche 50-289,84/03/15,8403200066
- 8403200120 Response supporting TMI Alert motion for extension of time Until BA0330 for filing response to licenses & NRC motions for summary disposition Certificate of Bvc encl Related Correspondence TRCHBRIDGE OF Metropolitan Edison Co TRCHBRIDGE, O F. Bhaw, Pittman, Potts & Trombridge 84/03/15 Atomic Bafety and Licensing Board Panel 5pp 22699 176 24X Fiche 50-289.84/03/15, 840320120
- 8403200191 Responds to 831208 & 18 ltrs repossibility of restart decision prior to further evidentiary hearings on mgt competence & integrity ASLAB decision will be considered by Commission upon issuance PALLADINO,N J Commissioners 84/03/19 SPECTER, A Senate 2pp 22598,003 24x Fiche 30-289,84/03/19.8403200191
- --B403200195 Forwards revised add1 views of Commissioner Bernthal per Commission 840127 memorandum re tentative views & plans for resolution of mgt integrity issues prior to restart CLEMENTS, W.L. Office of the Secretary of the Commission 84/02/13 Office of the Executive Legal Director. 4pp 22698 020 24X Fiche 50-289,84/03/19,8403200191

- --8403200198 Responds to 840124 ltr & 831216 position statement re funding of cleanup prerequisite for restart Commission does not have legal authority to condition restart of TMI-1 on funding solution for cleanup of TMI-2 PALLADIND.N.J Commissioners 84703/19 THORNDURCH, R Pennsylvania, Commonwealth of, 3pp 22698 024 24X Fichs 30-289,84703/19,8403200191
- --8403200200 Comments on rept that Commission recommended authorization to operate at 25% power w/commencement as early as Jan 1984 Authorization contradicts previous Commission assurances Evidentiary hearings recommended EPECTER.A Banate 83/12/0B PALLADINO.N J Commissioners 1p 22698.027 24% Fiche 50-289,84/03/19,8403200191
- --B403200205 Responds to B31117 ltr re resolution of mgt competence & integrity issues prior to restart Questions about competence & integrity will be adequately resolved prior to restart decision
 PLAINE: HH. Office of the General Course! B3/11/23 SPECTER.A
 Banate. 2pp 22498 028 24X Fiche 50-289.84/03/19.8403200191
- --8403200211 Advises Commission to hold necessary hearings to resolve outstanding issues discussed at 831216 hearing SPECTER.A Senate 83/12/18 PALLADIND, N Commissioners 2pp 22698-030. 24X Fiche 50-289,84/03/19.8403200191
- 8403210014 UCB brief on Commission 840127 review of Issues decided in ALAB-729 & ALAB-744 History of proceeding shows successive marrowing of Issues until all unresolvable issues excluded M/Cartificate of 8vc HRIBB.E.R. Union of Concerned Scientists 84/03/19 44pp 22706:283. 24X Fiche 50-289.84/03/19.8403210014
- B403210024 Brief re Commission review of specific design issues in ALAB-729, Certificate of Bvc encl
 QQLDBERG, J R Hearing Branch 2 RAWBON, R J Hearing Branch 4
 B4/03/19, Commissioners 47pp 22706 00B 24K
 Fiche: 50-289, 84/03/19,8403210024
- B403210193 Brief on review of ALAB-729 & ALAB-744 Commission review Areas should be affirmed
 BAXTER, T. A Metropolitan Edison Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge D88 020 84/03/19 Commissioners 68pp 22710.001. 24X Fiche 50-289,84/03/19,8403210193
- 8403220242 Response to both licenses & staff motion for summary disposition of Joint Intervenors contentions & motion to stay hearing. Certificate of Svc encl AMODT: N O Aemodts LEE, J Joint Petitioners TMI 84/03/19 Atomic Safety and Licensing Board Panel 9pp, 22719 040, 24X Fiche, 50-289, 64/03/19.8403220242
- 8403210169 Response supporting licenses 840224 motion for summary disposition of each of TM1 Alert & Joint Intervenors contentions. Motion establishes that no genuine issues of fact be litigated.

 MADMER: M E. Hearing Branch 4 DBB 015 84/03/20. Atomic Safety and Licensing Board Panel Opp 22710 348, 24X Fiche, 80-289, 84/03/20.8403210169
- ---B403210173 Affidavit of CE McGracken & PC Wu in response to license motion for summary disposition of Joint Intervenors Contention 5. Certificate of Box encl MCGRACKEN.C E., Wup C Division of Engineering 84/03/14 9pp 22710:354 24X Fiche:50-289,84/03/20.8403210169
- 8403210175 Forwards HD Hukill 840222 & 27 ltrs re emergency feedwater sign flow instrumentation & NUREO-0737 selective item status, respectively, 8vc list encl BAXTER, T.A. Shaw, Pittman. Potts & Trowbridge BAXTER, T A Metropolitan Edison Co DSB 005 84/03/20 CHILK, S.J. Office of the Becretary of the Commission. 27pp. 22710 104 24X Fiche: 50-287, 84/03/20, 8403210175
- BACG210187 Forwards H Hukill 840307 ltr to UF Stolz re reviews of teaching performance, ability & attitude of DD in 1983 & RR Clark 840228 ltr to RC Degoing responding to 840203 notice of violation Certificate of Svc enci.

 BAUSER, D. B. Shaw, Pittman, Potts & Trowbridge BAUSER, D. B. Metropolitan Edison Co. DBB 004 84/03/20 EDLER, D. J. BUCK, J. H. KOM-C. N. Atomic Safety and Licensing Appeal Panel 35pp.
 22710:289 24X Fiche:50-289,84/03/20,8403210187
- 8403260382 Inquires re intendes plan to take action on FEMA identified deficiencies in emergency preparedness.
 WEISBLE.R Harmon & Weiss WEISBLE.R. Three Mile Island Alert 1988 097 84/03/22 870LZ.J F. Operating Reactors Branch 4 ip 22760:142. 24X Fiche 50~289.84/03/22.8403260382

- 8403270300 Informs that staff does not intend to respond to Aamodt B40307 motion for reconsideration of ALAB-697 unless requested by ABLAB ABLAB ABLAB SALAB ABLAB SALAB SALAB
- 8403270304 Response to TMT Alert 840310 motion for extensions of time until 840330 to respond to licensee & staff motions for summary disposition Staff does not object to motion Certificate of Svc enc1 Related correspondence WAGNER, M E Hearing Branch 4 DBB 136 84/03/22 Atomic Safety and Licensing Board Panyl 3pp 22789 029 24x Fiche 50-289.84/03/22,8403270304
- 8403260332 Order grenting Joint Intervenors 840227 motion to file out of time response to licensee second set of interrogatories Served on 840326 WOLFE.S J. Atomic Safety and Licensing Doard Panel DSB 089 84/03/23 Joint Petitioners THI ip 22760 161 24X Fiche 50-289.84/03/23.8403260332
- 8403260337 Order granting extension of time until 840330 to respond to licensee & staff motions for summery disposition Served on 840326 MOLFERS J Atomic Safety and Licensing Board Panel DSB 088 84/03/23 Three Mile Island Alart ip 22760 169 24X Fiche 50-289, 88/03/23. 8403260337
- 8403260345 Response opposing Aamodt 840308 motion for reconsideration of ALAB-697 Motion advances no anguments not previously presented Certificate of Svc encl
 ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Troubridge DSD 095 84/03/23 Atomic Safety and Licensing Appeal Panel 6pp 22760 184 24% Fiche 50-289,84/03/23,8403260345
- 8403290386 Amended response to UCS 840120 petition to show cause re emergency feedwater sys Amend necessary to reflect factual devalopments which have occurred since 840224 re licensee response Certificate of Svc encl
 BAXTER.T A General Public Utilities OPU Service Corp BAXTER.T A Shaw, Pittman, Potts & Trowbridge DSB 195 84/03/26
 Dffice of Nuclear Reactor Regulation, Director 24pp 22814 257 24X Fiche 50-289,84/03/26,8403270386
- 8403280343 Memorandum & Order CLI-84-3 on relevance of Board Notification 63-47 issues in proceeding Issues do not warrant reopening record Separate views of Commissioner Ollinsky uncl CHILK.8 J Office of the Secretary of the Commission DSB 181 84/03/28 15pp 22787 101 24x Fiche 50-289.84/03/28.8403280343
- 8403280352 Notifies that Commissioner Bernthal will tour plant on 840406 Served on 840328 * Commissioners DSB 159 84/03/28 ip 22787 172 24X Fiche 50-289,84/03/28.8403280352
- 8403300259 Notice of change in svc list Certificate of Syc encl WEI85.E R Harmon & Weiss DSD 211 84/03/30 3pp 22924-071 24X Fiche 50-289,84/03/30,8403300259

H General correspondence

- 8403160291 Expresses appreciation for receipt of missing page from Board Notification 84-002A E Blake admission of telling clients not to rept significant employment test rev to NRC is important item to investigate as part of mgt competency. LEWIS.M I Lewis. M 84/02/12 STOLZ.J F NRC No Detailed Affiliation Given 2pp 22660 143, 24X Fiche 50-287,84/02/12.8403160291.
- 8403060220 Unges NRC to grant immediate approval for restert of Undamaged reactor IMLERIR. Affiliation Not Assigned 84/02/29 NRC No Detailed Affiliation Given 1p 22515 177 24X Fichs 50-289,84/02/29,8403060220
- B40313002B Urges NRC to put facility back in operation BHANCEY:R E Affiliation Not Assigned B4/03/05 NRC No Detailed Affiliation Given 2pp 22615 303 24X Fiche 50-287, 84/03/05, 8403130028
- 8403210141 Requests deletion of RC Arnold, former president of General Public Utils, from NRC mailings & General Public Utilities - GPU Service Corp 84/03/16 NRC -No Detailed Affiliation Oliven 2pp 22707 280 24X Fichs 50-289,84/03/16,8403210141

- B403230001 Submits rev to distribution list & forwards personnel & title changes made to mailing labels
 HUKILL,H D General Public Utilities GPU Service Corp 84/03/20
 DENTON,H R Office of Nuclear Reactor Regulation, Director 5pp
 22726 350 24X Fiche 50-289,84/03/20,8403230001
- 8403270146 Requests Label 217057007114 for CW Smyth, licensing manager, be changed on NRC distribution of documents & correspondence Rev to entilists, marked to reflect personnel & title changes for util amployees, also requested HUKILLH D General Public Utilities OPU Service Corp 84/03/20 SCHAEFFER.C NRC No Detailed Affiliation Given 6pp 22770 013 24% Fiche 50-287,84/03/20,8403270146
- J Insurance & indemnity information
- B403280010 Forwards Endorsements 72 & 73 to NELIA Policy NF-220 & Endorsements 62 & 63 to MAELU Policy MF-73 OFFICE Corp. B4/03/22 OFFICE CARP. B4/03/22 SALTIMAN. J. Defice of Nuclear Reactor Regulation, Director Spp. 22777 074 24% Fiche 50-289.84/03/22,8403280010
- P Operating license stage documents & correspondence
- B403010010 F01A request for documents re TMI-1 Restart Issues Task Force to be placed in PDR SHQLLY.B C Union of Concerned Scientists 83/12/12 FELTON.J M Division of Rules and Records 1p. 22446 056 24X Fiche 50-289.83/12/12.8403010010
- 8403010014 Partial response to FDIA request for documents re TMI-1 Restart Issues Task Force Forwards documents listed on app Info also available in PDR FELTON,J M Division of Rules and Records 84/01/03 SHDLLY,6 C Union of Concerned Scientists 2p 22446 057 24X Fichs 50-287,84/01/03,8403010014
- --8305110054 Informs that reevaluation of Cycle 5 reload application, has identified two issues re nonconservative cladding swelling & rupture models & TAFY/TACO penalty proposed by B&H that shoud be resolved prior to restart RUBENSTEIN.L S Assistant Director for Core & Plant Systems 83/05/02 LAINAS.G C Assistant Director for Operating Reactors 3pp 22446 212 24X Fishe 50-289,84/01/03,8403010014
- --B403010020 Assigns recipients to TMI-1 Restert issues Takk Force to verify that NRC requirements for restart torrectly identified & facility treated similar to eil operating plants for other NRC requirements
 EIBENHUTLD Q Division of Licensing STAROSTECKI,R Division of Project & Resident Programs 83/04/15 JACOBS,R Region 1.
 Office of Director VAN VLIET,J, DIIANNI,D Division of Licensing 1p 22446 057 24X Fichs 50~289,84/01/03.8403010014
- --8403010023 Responds to 830415 memo & forwards "Rept of TMI-1 Restart Issues Task Force Members" Meeting requested to respond to questions
 HILLIAMS:M H TMI-1 Restart Issues Task Force 83/04/29
 EISENHUT:D 0 Division of Licensing STARGSTECKI:R Division of Project & Resident Programs | p 22446 060 24X
 Fiche 50-289:84/01/03;8403010014
- --8403010030 "Rept of TMI-1 Restart issues Task Force Members "
 WILLIAMS, M., VAN VLIET, J., YOUNG, F. TMI-1 Restart Issues Task
 Force 83/04/29 150pp 22446 061 24X Fiche 50-289, 84/01/03.
- --8403010036 List of generic itrs from 1978-1983 Related info encl * NRC - No Detailed Affiliation Given 84/01/03 27pp. 22446 247 24% Fiche 50-289,84/01/03.8403010014
- --B403010043 Forwards input to B30429 TMI-1 Restart Issues Tesk Force rept Info derived from ASLB partial initial decisions in restart proceedings Related info encl GOLDBERG. J R Dffice of the Executive Legal Director B4/01/03 WILLIAMS. M Division of Licensing 19pp 22446 274 24X Fiche: 50-289,84/01/03.8403010014
- 8403020392 FDIA request for Chilk 821019 memo to Dircks re postaccident sampling sys (NUREO-0737, Item II B 3) to be placed in PDR PEDRO, J NUS Corp 84/01/26 Division of Rules and Records 19 22491 285 24X Fiche 50-289, 84/01/26, 8403020392
- 8403080393 Forwards DL Jensen 830517 1tr to N Palladino Te DOJ investigation of TM1 Document subj to Voigt 830526 FOIA request & 830919 appeal Document should be placed in PDR SHEENEY.M Office of the General Counsel 84/01/27 PODL, M J NRC - No Detailed Affiliation Given ip 22567 354 24X Ficher 50-289,84/01/27,8403080393

- --8403080425 Responds to 8304ii ltr re TMI-i restart & DOJ investigation into allegations re mgt competence investigation being pursued diligently but will not be completed by requested date

 JENSEN.D L. Justice, Dept of 83/05/17 PALLADINO, N J
 Commissioners 4pp 22567 355 24X Fiche 50-269,84/01/27, 840:2080393
- 8403070053 Responds to 831214 itr suggesting Commission refuse to restart Unit i until funding for Unit 2 cleanup in place Commission does not believe that Unit 1 restart & Unit 2 cleanup should be tied together PALLADING.N J Commissioners 84/02/08 MORRIS.A E Advisory Council for Decontamination of TMI Unit 2 ip 22563 198 24X Fichs 50-289.84/02/08,8403070053
- 8403020169 Forwards table indicating review & insp status of TMI-1 restart certification items Current schedule calls for completion of all items not requiring hot functional testing by June 1984
 STOLZ, J F Operating Reactors Branch 4 84/02/15 HUKILL, H D General Public Utilities 0PU Bervice Corp 33pp 22491 101 24X Fiche 30-289, 84/02/15, 8403020169
- 8403020395 Responds to FOIA request for Chilk 821019 memo to Dircks re SECY-82-384 concerning status of TMI-1 NUREQ-0737 Items Forwards document Document also available in PDR FELTON, J M Division of Rules and Records 84/02/15 PEDRO, J NUS Corp 1p 22491 286 24X Fiche 50-289,84/02/15,8403020395
- 8403040222 Forwards application for amend to License DPR-50, changing Tech Specs to incorporate functional test program for reactor conlant pump snubbers to develop small replacement program for hydraulic snubbers HUKILLH D General Public Utilities GPU Service Corp 84/02/17 STGUZ.JF Operating Reactors Branch 4 1p 22516 064 24% Fichs 50-289, 84/02/17,8403060222
- --8403060227 Application for amend to License DPR-50, changing Tech Specs to incorporate functional test program for reactor coolant pump snubbers & to develop seal replacement program for hydraulic snubbers Certificate of Svc encl HUKILL.H D Ceneral Public Utilities GPU Service Corp 84/02/17 2pp 22516 065 24% Fiche 50-289,84/02/17.8403060222
- --8403060236 Proposed Tech Spec changes re functional test program for reactor comiant pump snubbers & seal replacement program for hydraulic snubbers # General Public Utilities ~ GPU Service Corp 84/02/17 14pp 22516 086 24X Fiche 50-289,84/02/17,8403060222
- B403040476 Requests expected response date for each TMI action item listed in encl within 10 days EISENHUT, D © Division of Licensing B4/02/21 HCMILL, H D General Public Utilities OPU Service Corp 5pp 22552 320 24X Fiche 50-287, 84/02/21, 8403040476
- 8403010516 Summary of 840130-31 meetings w/util at site in Dauphin County, PA re status, schedule & scope of implementation of selected NUREO-0737 action items Agenda & viewgraphs encl
 VAN VLIET, J Operating Reactors Branch 4 84/02/22 Operating Reactors Branch 4 130pp 22443 303 24X Fiche, 50-289, 84/02/22, 8403010516
- 8403040473 Requests expected completion dates for NUREG-0737 items & justification for proposed schedule for items that will hot be completed by June 1984 by 840227
 EIBENHUT, D 0 Division of Licensing 84/02/22 HUMILL, H D
 General Public Utilities OPU Service Corp 4pp 22552, 325 24X
 Fiche 50-289,84/02/22,8403060473
- 8403120310 Forwards, for review, revised draft package of conditions from TMI-1 restart proceedings for incorporation into OL Meeting proposed for Mar 1984 at TMI-1 site to receive required add1 info & discuss comments on license conditions.

 STGLZ,J F Operating Reactors Branch 4 84/02/22 HUKILL,H D General Public Utilities ~ GPU Service Corp 14pp 22615 306 24X Fiche 50-289,84/02/22,8403120310
- B4030204iB Notification of 840309 meeting w/util in Middletown, PA to distuse draft package of license conditions assembled by NRC from TMI-i restart proceeding decisions & forwarded to Util by 84022R ltr
 VAN VLIET, J Operating Reactors Branch 4 84/02/24 STOLZ, JF. Operating Reactors Granch 4 3pp 22491 276 24% Fiche. 50-289, 84/02/24, 8403020418

1

- 8403050472 Notification of 840308 meeting w/util in Bethesda,MD to discuss resolution of environ qualification deficiencies noted in Franklin Research Ctr technical evaluation rept & compilance w/10CFR30 40 VAN VLIET V Operating Reactors Branch 4 84/02/28 STOLZ,J F Operating Reactors Branch 4 2pp 22549 321 24X Fichs 50-289:84/02/28.8403050472
- B403060160 Forwards results of chemical analysis techniques performed on std test matrix solution as required by NUREO-0737. Action Item II B 3.per util B31122 itr Response to Criterion 10 of draff EBER complete
 HUKILL. H D General Public Utilities OPU Service Corp B4/02/29
 BTCL.7. J F Operating Reactors Branch 4 5pp 22516 263 24X
 Fichs 50-289.84/02/29.8403060160
- B403060139 Forwards check to satisfy cost of 840126 OL Change Request 133 KUKILL, H D General Public Utilities ~ GPU Service Corp 84/03/01 STOL7.J F Office of Nuclear Reactor Regulation, Director 1p R2516 361 24X Fiche 50~289,84/03/01,8403060159
- 8403060233 Forwards design info, instrument accuracy & response times to assist in post-implementation review of containment water level monitoring (NUREG-0737, Item II F i), per 8307i9 request HUKILL, H D General Public Utilities GPU Service Corp 84/03/01 SIOLZ, J F Operating Reactors Branch 4 opp 22517 317 24X Fiche 50-289, 84/03/01, 8403060233
- 8403080037 Lists planned submittal dates for eight action items.per 840221 request HUMILL.H D General Public Utilitles - GPU Service Corp 84/03/02 EIBENHUT.D D Division of Licensing 2pp 22559 197 24X Fiche 50-289.84/03/02.8403080039
- 8403120004 Reevaluates response to NUREO-0737, item III D 3 4, "Control Roum Habitability." based on PRA technique for onsite & offsite sources App R mods will assure adequate smoke datection in control room HUMILL, H D General Public Utilities GPU Service Corp 84/03/02 STGLIZ.J F Operating Reactors Branch 4 2pp 22586 306 24% Fich # 50-289, 84/03/02, 84/03/0004
- B403070125 Forwards list of draft license conditions considered complete.per 840222 request Conditions should be deleted Draft License Condition D 4 should specify Leval I PRA & should be submitted by 840630
 HUXILL, H D General Public Utilities GPU Service Corp. 84/03/05
 BTOLTZ.JF Operating Reactors Branch 4 2pp 22576 061 24X
 Fiche 50-289,84/03/05,8403090125
- B403220107 Forwards safety evaluation re TM1 ltem II K 2 17,
 "Potential for Voiding in RCS During Transients " Safety
 evaluation documenting completion of Item encl
 STOLZ.J F Operating Reactors Branch 4 B4/03/05 HUKILL.H D
 Deneral Public Utilities GPU Service Corp 4pp 22723.288 24X
 Fiche 50-289.84/03/05.8403220107
- 8403120036 Advises that 840305 ltr re draft license conditions contained incorrect data Correct completion data for Level 1 PRA is 860630, HUKILL, H D General Public Utilities GPU Service Corp 84/03/06 BTDL7.J F Operating Reactors Branch 4 1p. 22586 281, 24X Fichs 50-289,84/03/06,8403120056
- 8403160006 Forwards summary of revised RM-A5 & RM-025 elarm setpoints to determine if setpoints could be lowered HUMILL, H D. General Public Utilities OPU Service Corp 84/03/12 GERUSKY, T Pennsylvania, Commonwealth of, 2pp. 22654 320 24X Fiche 50-289,84/03/12,8403160006
- ---B403160022 Forwards summary of condensor offges radiation monitor responses to once-through steam generator leakage HUKILL-H D Cameral Public Utilities OPU Service Corp B4/03/12 B70L7.J F Operating Reactors Branch 4 3pp 22654.322 24X Fiche.50-287.84/03/12,8403160006
- 8403160024 Forwards summary of condensor offgas radiation monitor responses to once-through steam generator leakage HUMILL, H D General Public Utilities GPU Service Corp 84/03/12 8TOLE, J F Operating Reactors Branch 4 3pp. 22653 355 24X Fiche 50-289,84/03/12,8403160024
- B40R070D41 Board Notification B4-050: provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT,D @ Division of Licensing, 84/03/14. Atomic Bafety and Licensing Board Fanel 10pp 24X Fiche 50-000,84/03/14,8402090041

- 8403200099 Forwards schedule for implementation of activities for control of heavy loads, per NRC requests re NUREG-0612 Cask plt gate listing lugs will be modified by 841015 . HUKILL, H D General Public Utilities - OPU Service Corp B4/03/15 EIBENHUT, D Q Division of Licensing 3pp 22685 313 24X Fiche 50-289,84/03/15.8403200099
- 8403210014 UCS brief on Commission 840127 review of issues decided in ALAB-729 & ALAB-744 History of proceeding shows successive narrowing of Issues until all unresolvable Issues excluded W/Cortificate of 8vc WEISS, E.R. Union of Concerned Scientists 84/03/19 44pp 22706 283 24x Fiche 50-289, 84/03/19, 8403210014
- 8403230040 Responds to NUREG-0737, Item II D i re relief & safety valve testing.per 840215 Itr Facility adequately represented by ERRI valve tests Precaution of 1.000 psig overly conservative HUXILL.H D General Public Utilities GPU Service Corp 84/03/20 870L7.J F Operating Reactors Branch 4 ip 22724 331 24X Fiche. 50-289, 84/03/20, 8403230040
- 8403230053 Notifies of assurances obtained from Design Data Labs re independent training auditor Lab meets requirements for independent auditor HUKILL: HD General Public Utilities GPU Service Corp 84/03/20 STOLZ: JF Operating Reactors Branch 4 2pp 22724 340 24X Fiche 50-289.84/03/20.8403230053
- Q Inspection reports, IE Bulletins & correspondence
- B4030B040B FOIA request for repts of inspicarried out under Condition 2 of Nuclear Energy Liability policies for facilities CALBOYAS,C D Affiliation Not Assigned 84/02/07 Region 5, Office of Director 4pp 22567 341 24X Fiche 90-000,84/02/07, B4030B040B
- 8403020169 Forwards table indicating review & insp status of TMI-1 restart certification items Current schedule calls for completion of all Items not requiring hot functional testing by June 1984
 8TOLZ.J F Operating Reactors Branch 4 84/02/15 HUKILL.H D Ceneral Public Utilities GPU Service Corp 33pp 22491 101 24X Fiche 50-289,84/02/15.8403020169
- B4030702B2 Forwards IE Insp Rept 50-289/83-32 on B31i01-B40112 No violations noted BTAROBTECKI,R Division of Project & Resident Programs. B4/02/21 HUKILL H D General Public Utilities OPU Service Corp 4pp 22547 079 24X Fiche 50-289,84/02/21,84030702B2
- --B403070287 IE lnsp Rept 50-289/B3-32 on 83ii01-B401i2 No violations noted Major areas inspected actions on previous lnsp findings.plant operations (long-term shutdown). Tech Spec surveillance test program & update to NUREO-0680, Suppl 4 YOUNG,F, BAUNACK,W, CONTER Region 1. Office of Director 84/02/06 15pp 22547 083 24X Fiche 30-289, 84/02/21,8403070282
- B403080419 Responds to FOIA request for repts of insp carried out under Condition 2 to Nuclear Energy Liability policies for facilities NRC does not have repts
 FELTON, J M Division of Rules and Records B4/02/22 GALSOYAB, C D
 Affiliation Not Assigned 1p 22567 345 24X
 Fiche 50-000, B4/02/22, B403080419
- 8403010363 EN-84-005 on 840227, notice of violation & proposed imposition of civil penalties to be issued in amount of 440,000 Action based on five violations re open containment isolation valves
 CRAIO, J. AXELRAD, J. Director's Office, Office of Inspection and Enforcement 84/02/24 2pp 22433 013 24X Fiche 50-289,84/02/24.
- 8403090244 Responds to IE Bulletin 83~08, "Electrical Circuit Breakers W/Undervoitage Trip Faature in Use in Sefety-Related Applications Other Than Reactor Trip Sys " No safety-related applications of breakers identified at facility HUKILL,H D General Public Utilities GPU Service Corp. 84/02/27 MURLEY.T E Region i. Office of Director ip 22572:226 24X Fiche 50-289,84/02/27,8403090244
- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circults & Annunciation." Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22909 239 24X Fiche 50-000.84/02/28,8401190072
- 8403080403 Discusses iE insp on 830824-1003 & forwards notice of violation & proposed imposition of civil penalty MURLEY. T R Region i, Office of Director 84/02/27 CLARK. PR general Public Utilities GPU Service Corp 4pp 22581 332 R4X Fiche 50-289.84/02/27.8403080403

- --B403080407 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Violations noted written safety procedures not properly implemented & unidentified primary sys leaknate not classified as unusual event MURLEY,TE Region 1, Office of Director 84/02/27 6pp 22381 336 24% Fiche 50-289,84/02/29,8403080403
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc iist enc.]
 ORACE.J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24x Fiche 50-000:84/03/02,8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22593 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"

 Svc list encl

 JDRDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New

 York, Inc. 1179p 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24% Fiche 50-000.84/03/05, B402090011
- 8402090024 IE Info Nutice 84-07, Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys" Svc list encl JORDAN, E. L. Odvision of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York: Inc. 118pp 22635 049 24X Fiche 50-000.84/03/07.8402070024
- 8402090028 IE Info Natice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc IIst enc! JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84703707 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84703707,8402090028
- 8402090031 IE Bulletin B4~02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list onc! DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403290186 Forwards IE Insp Rept 50-289/83-34 on 831212-30 Noviolations observed
 MARTIN.T T Division of Engineering & Technical Programs 84/03/13
 HUKILL.H D General Public Utilities OPU Service Corp 2pp
 22803 305 24X Fiche 50-289.84/03/13.8403290186
- ---8403290191 IE Insp Rept 50-289/83-34 on 831212-30 No violations identified Major areas inspected open items in areas of once-through steam generator repair, RCS requalification, PDRV.LERs & test procedure review GRAY, E. H. VITO. D., NEN, P. Region 1, Office of Director 84/02/16 60pp 22803 307 24% Fiche 50-289,84/03/13,8403290186
- 8403210187 Forwards H Hukill 840307 ltr to UF Stolz re reviews of teaching performance, ability & attitude of UD in 1983 & RR Clark 840228 ltr to RC Degung responding to 840203 natice of violation Contificate of Svc encl BAUSER, D B Shaw, Pittman, Potts & Troubridge BAUSER, D B Metropolitan Edison Co DSB 004 8403/20 EDLES, C J , BUCK, J H , KOML, C N Atomic Safety and Licensing Appeal Panel 35pp 22710 289 24X Fiche 50-289, 84/03/20, 8403210187
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities" Syc list encl URBANKE L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21. Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24% Fiche 50-000,84/03/21,8402070043
- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Bys " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 84/03/21 Consulidated Edison Co. of New York, Inc. i35pp 22933 001 24X Fiche 50-000,84/03/21,8402070044

sports & related correspondence

nnnel exposure data, aircraft movement rport, leak reduction program safety valve challenges for

- 8403200068 Monthly operating rept for Feb 1984 W/840315 itr SMYTH.C W. HUKILL.H D. General Public Utilities - OPU Service Corp 84/02/29 MCDUNALD.W C. Office of Resource Management. Director 6pp 22685 096 24X Fiche 50-289,84/02/29,8403200068
- 8403210076 Forwards "Number of Personnel & Man Rems by Work & Job Function:0783" & "Aircraft Movements at Harrisburg Intl Airport:0783" HUNILL: H.D General Public Utilities - GPU Service Corp 84/03/01 MUNILLY.T E Region i. Office of Director 2pp 22705 077 24X Fiche 50-289:84/03/01.8403210076
- --8403210082 "Number of Personnel & Man Rems by Work & Job Function. CY83 "

 * General Public Utilities - GPU Service Corp 83/12/31 2pp 22705 079 24X Fichs 50-289,84/03/01.8403210076
- --8403210088 "Aircraft Movements at Harrisburg Intl Airport, CYB3 "
 * General Public Utilities GPU Service Corp 83/12/31 5pp
 22705 081 24% Fiche 50-289,84/03/01.8403210076
- B403210138 Forwards personnel exposure rept for 1983, including total count of personnel monitored & number of personnel in each whole body esposure range HUKILL, H D General Public Utilities GPU Service Corp 84/03/01 MURLEY, T E Region 1, Office of Director ip 22707 088 24X Fiche 50-289,84/03/01,8403210138
- ~-8403210146 Personnel exposure rept for 1983 * General Public Utilities - OPU Service Corp 83/12/31 2pg 22707 089 24X Fiche 50-289.84/03/01.8403210138
- 8. Reportable occurrences, LEAs & related correspondence
- 8403300074 PNS-I-84-003 on 840324, maie phoned Jersey Central Power & Light Customer Svc Ctr & notified that FFA will start demolishing plants Gyster Creek implemented emergency contingency plan & TMI increased security awareness MADDEN, W. JUYNER, J. Region 1, Office of Director 84/03/26 ip 22822 088 24% Fiche 50-000, 84/03/26, 8403300074
- T Hearing transcripts on non-antitrust matters
- 8403150349 Transcript of 840215 public meeting in Middletown.PA to receive comments on draft suppl to programmatic E18 Pp 1-101 * Commissioners 84/02/15 102pp 22649 110 24X Fiche 50~289.84/02/15, 8403150349
- 8403050073 Transcript of 840301 telephone conference in Bethesde.MD restam generator repair Pp 180-195

 * Atomic Bafety and Licensing Board Panel 84/03/01 19pp
 22490 045 24X Fiche 50-289.84/03/01.8403050073
- 8403280153 Forwards documents for inclusion in Chairman 840223 testimony before Senate Subcommittee on Nuclear Regulation. Committee on Environ & Public Warks

 * Office of Congressional Affairs 84/03/08 Record Services Branch (Document Control Desk) 1p 22809.274 24X
 Fiche 80-287.84/03/08.8403280153
- --8403280160 Statement of JK Asselstine on 840223 re Commission authority to issue temporary CL, review of NRC NBHC determination pertaining to steam generator repairs at TMI-1 & licensing reform legislation
 ABBELBTINE.J K Commissioners 84/02/23 8pp 22809 308 24X Fiche 50-289,84/03/08,8403280153
- B403270335 Transcript of Commission B40323 affirmation/discussion & vote in Washington, DC re request for denial of renewal of Beabrook Unit 2 CP & SECY-84-48 concerning review of ALAB-724 in matter of Met Ed Pp 1-3 s Commissioners B4/03/23 App 22787-356 24X Fiche 50-000:84/03/23,8403270335
- U Congressional/Executive Correspondence
- 8402220291 Responds to 831209 ltr in opposition to restart until all outstanding issues resolved PALLADIND, N J Commissioners 84/01/31 HEINZ, J Senate 1p 22384 306 24X Fiche 50-289, 84/01/31, 8402220291.
- --8403090003 Responds to 831212 ltr expressing contern re-protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 and W/o end!
 PALLADINO, N J Commissioners 84/01/31 KOLTER, J P. House of Rep. 1p. 22584 305 24X Fiche 50-289,84/01/31,8402220291

- --8403070004 Responds to 831212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 encl W/a encl PALLADINO, N J Commissioners 84/01/31 MURPHY, A J House of Rep 1p 22584 307 24X Fiche 50-289, 84/01/31, 8402220271
- --B403090005 Responds to B31212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 encl W/a encl PALLADINO, N J Commissioners B4/01/31 MURTHA, J P House of Rep 1p 22584 308 24X Fiche 50-289,84/01/31,8402220291
- --8403090007 Responds to 831212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 encl W/o encl PALLADINN, N J Commissioners 84/01/31 CLINGER, W F House of Rep 1p 22584 309 24X Fiche 50-289,84/01/31,8402220291
- --8403090008 Responds to 831212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 encl W/o encl PALLADINO, N J Commissioners 84/01/31 0AYD09, J M. House of Rep 1p 22584 310 24X Fiche 50-289,84/01/31,8402220291
- --8403070007 Responds to 831212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 encl M/o encl PALLADINO, N J Commissioners 84/01/31 RITTER, D House of Rep ip. 22584 311 24X Fiche 50-289,84/01/31,8402220271
- --8403090010 Responds to 831212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 encl W/o encl PALLADINO, N J Commissioners 84/01/31 HARRISON, F House of Rep. 1p 22384 312 24% Fiche 50-289,84/01/31,8402220291
- --B403090013 Expresses concern re protracted time period for resolution of issues surrounding TM1-1 restart Commission should place primary emphasis on ability of util mgt to operate plant safely GAYDGS,J M, KOLTER,J P, MURPHY,A J House of Rep. 83/12/12 PALLADIND,N, GILLINSKY,V, ROBERTS,T Commissioners. 2pp. 22584 331 24X Fiche 50-289,84/01/31,8402220291
- --B403090011 Expresses concern re protracted time period for resolution of issues surrounding TMI-1 restart Commission should place primary emphasis on ability of util mgt to operate plant safely HARRIBON,F House of Rep B3/12/13 PALLADINO,N, GILINGKY,V ROBERTS.T Commissioners. 2pp 22584 329 24% Fichs 30-289,84/01/31.8402220291
- 8403070053 Responds to 831214 ltr suggesting Commission refuse to restart Unit 1 until funding for Unit 2 cleanup in place Commission does not believe that Unit 1 restart & Unit 2 cleanup should be tied together PALLADINO, N J Commissioners. 84/02/08 MDRRIS, A E Advisory Council for Decontamination of TMI Unit 2. 1p 22563 178 24) Fichs. 50-289, 84/02/08, 8403070053
- --8403070050 Responds to B31213 ltr re criminal indictment of Met Ed & cleanup of Unit 2 Commission does not believe delaying restart would accelerate Unit 2 cleanup Unit 1 restart & Unit 2 cleanup should not be tied together PALLADING.N J Commissioners 84/02/08 MORRIB, A E. House of Rep. 1p 22563, 199 24X Fiche 50-289,84/02/08,8403070053
- --B403070069 Responds to B31207 ltr urging Commission not to authorize restart of Unit I Commission views on restart set forth in encl 840127 notice to parties Commission does not believe Unit I restart & Unit 2 cleanup related PALLADINO,N J Commissioners B4/02/08 GEKAS,O W House of Rep ip 22563 200 24% Fiche 50-289, B4/02/08, B403070053
- --8403070073 Urges Commission not to accept recommendation to restart Unit 1 in light of mpt integrity review & criminal proceedings & slow pace of Unit 2 cleanup GEKAB.0 W. House of Rep B3/12/07. PALLADING.N.J Commissioners ip 22563 217 24X Fiche 50-289,84/02/08.8403070053.
- --8403070076 Advises of convictions re Unit 1 restart. Due to criminal indictments & belief that Unit 1 revenue should go directly toward Unit 2 cleanup. recommends against restart WALKER, R. 9 House of Rep. 83/12/13 PALLADING, N , ASSELSTINE, J BERNTHAL.F. Commissioners ip 2256/2 218 24% Fiche: 50-289, 84/02/08, 8403070053
- 8402220288 Ack receipt of 840131 reaffirmation of Commission 840127 decision re restart Further elaboration of decision basis requested.
 HEINZJ Senate. 84/02/14 PALLADING.N J Commissioners ip 22034:360. 24X Fiche 50-289,84/02/14,8402220288

- --8402220303 Submits opposition to further consideration of restart until all outstanding issues resolved HEINZ.J Senate 83/12/09 PALLADINO.N Commissioners 1p 22336 362 24% Fiche 50-289,84/02/14,8402220288
- 8403200191 Responds to 831208 & 18 itrs re possibility of restart decision prior to further evidentiary hearings on mgt competence & integrity ASLAB decision will be considered by Commission upon lasuance PALLADIND.N J Commissioners 84/03/19 SPECTER.A Senate 2pp 22698 003 24% Fiche 50-289,84/03/19,8403200191
- --8403200200 Comments on rept that Commission recommended authorization to operate at 25% power w/commencement as early as Jan 1984 Authorization contradicts previous Commission assurances Evidentiany hearings recommended SPECTER.A Benate 83/12/08 PALLADINO.N J Commissioners 1p 22698 027 24% Fiche 50-289.84/03/19.8403200191
- --8403200205 Responds to 831117 ltr re resolution of mgt competence & integrity issues prior to restart Questions about competence & integrity will be adequately resolved prior to restart decision
 PLAINE.H Office of the General Counsel 83/11/23 SPECTER,A
 Senate 2pp 22698 028 24X Fiche 50-289,84/03/19,8403200191
- --8403200211 Advises Commission to hold necessary hearings to resolve outstanding issues discussed at 831216 hearing SPECTER: A Senate 83/12/18 PALLADINO.N Commissioners 2pp 22698 030 24% Fiche 50-289,88/03/19,8803200191

V Operator Examinations

8403120016 Submits list of dates on which individual DD teaching ability, attitude & willingness to cooperate monitored DD no longer licensed operator & no longer training licensed operators or trainees
HUKILL.H D General Public Utilities - GPU Service Corp 84/03/07
BTOLZ.JF Operating Reactors Branch 4 ip 22586 263 24X
Fiche 50-289,84/03/07.8403120016

DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT i

F Security, medical, emergency & fire protection plans

- 8403060034 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR VASSALLO.D B Operating Reactors Branch 2 84/02/10 HARRINGTON, WD Boston Edison Co 2pp 22528 331 24X Fichs 50-293,84/02/10.8403060034
- 8403120305 Responds to B30720 petition requesting that NRC take immediate action to remedy alleged serious deficiencies in offsite emergency response plans Request denied in part, based on encl interim Director's Decision 84-05 DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 84/02/27 ERNST.M D Massachusetts Public Interest Research Group 2pp 22619 101 24X Fiche 50-293,84/02/27,8403120305
- --8403120308 Interim Director's Decision DD-84-5 denying in part, Massachusetts PIRG 830730 2 206 petition, requesting NRC action to remedy allegations re deficiencies in offsite emergency response plans DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/02/27 31pp 22617 103 24X Fiche 50-293,84/02/27,8403120305
- --8403120311 Notice of issuance of Director's Decision DD-84-5 re 630720 2 206 petition re deficient emergency response plans DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 84/02/27 2pp 32619 134 24X Fiche 50-293,84/02/27,8403120305
- --8402020093 Requests further review of issue re evacuation time estimate, per NRC/FEMA B01104 MDU Evaluation of potential bottlenecks to avacuation of plume emergency planning zone identified in BER (NUREO-0022 Buppl 5), requested UDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/20 KRIMM,R W Federal Emergency Management Agency 2pp 22619 136 24% Fiche 50-293,84/02/27,8403120305
- 8403i40248 Responds to 8401i2 ltr submitting current status of facility safeguards info protection says 84s in accordance w/provisions of 10CFR3 21 & acceptable VASBALLO.D B Operating Reactors Branch 2 84/02/27 HARRINGTON.W D Boston Edison Co 3pp 22636 340 24X Fithe 50-273.84/02/27.8403140248

- 8403090147 Clarifies NRC 831102 safety evaluation for 10CFR50.App R. Items III 0 3 & III L re number of fuses to be removed if fire accurs in cable spreading room of control room Correct number of fuses is 12, not six HARRINGTON.W D Boston Edison CO 84/03/05 VASSALLO.D B Dperating Reactors Branch 2 ip 22575 128 24X Fiche 50-293.84/03/05,8403090147
- B403130255 Forwards Rev 6 to security force training & qualification plan re consolidation of similar crucial tasks, changes in conformance to physical changes to facility & verbiage mods Rev withheld (ref 10CFR2 790 & 73 21) HARRINGTON.W D Boston Edison Co B4/03/05 MURLEY, T E Region I. Office of Director 1p 22607 137 24X Fiche 50-293,84/03/05,840310255
- 8403300232 Forwards staff comments on detailed control room design review program plan.per NUREO-0737. Suppl 1 Some areas of plan require further description VASSALLD.D B Operating Reactors Branch 2 84/03/06 HARRINOTON.W D Boston Edison Co 18pp 22844 264 24x Fiche 50-293.84/03/06.8403300232
- E403150018 Informs that FEMA will transmit on or before 840402, proposal refurther review of issues concerning evacuation time estimates for population, including work propram estimate of resources & schedule for completion of major components KRIMMR W Federal Emergency Management Agency 84403/07 JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) ip 22640 330 24% Fiche 50-293,84/03/09,8403150018
- 8403150177 Forwards Rev 1 pages to 820625 App R response, containing fire protection analyses & recommendations for facility W/six oversize drawings Aperture cards are available in PDR HARRINGTON, W D Boston Edison Co 84/03/09 VASSALLO, D B Departing Reactors Dranch 2 62pp 22643 279 24X Fiche 90-293,84/03/09,8403i50177
- 8403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-07 Agenda for workshop enci MRLEY. TE Region 1. Office of Director 84/03/07 D'TOOLE, J D Consolldated Edson Co of New York. Inc COUNSIL. W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) RHDDE, O K Niagara Mohawk Power Corp 35p 22672 062 24x Fiche 50-000,84/03/09,8403190243
- 8403200098 Forwards final exercise rept prepared by FEMA for 830629 joint exercise of state & local radiological emergency preparedness plans MARTINIT T Division of Engineering & Technical Programs 84/03/15 HARRINOTONIW D Boston Edison Ca 3pp 22699 099 24X Fiche 50-293,84/03/15,8403200098

G Adjudicatory correspondence

- 8403260001 Order extending time until 840329 For Commission to act to review Director's Decision DD-84-5 Served on 840323 CHILK:S J Office of the Secretary of the Commission DSB 080 84/03/23 Commissioners ip 22748 357 24X Fiche 50-293.84/03/23.8403260001
- 8403300002 Order extensing time util 840405 for Commission to act to review Director's Decision DD-84-5 Served on 840329 CHILLS J Office of the Secretary of the Commission DSB 207 84/03/29 Commissioners lp 22822 105 24X Fiche 50-293.84/03/29,8403300002
- J Insurance & indemnity Information
- 0403140029 Forwards Endorsement 65 to MAELU Policy MF-58 & Endorsements 81 & 86 to NELIA Policy NF-168 SINISI.J M Marsh & McLennan. Inc. 84/03/05 SALTZMAN, J D Assistant Director for State & Licensee Relations 4pp 22633 015 24X Fiche 50-293,84/03/05,8403140029
- P Operating license stage documents & correspondence
- 840315000B Informs of actions taken re coordination of drywell activities for dunation of Refueling Outage 6 & recirculation piping replacement project HARRINGTON, T E Boston Edison Co 84/02/08 MURLEY, T E Region 1. Office of Director 2pp 22643 297 24X Fiche 50-293, 84/02/08. 840315000B

- 8403140340 Summary of 831215 meeting w/OE & Mark I Owners Group in Bethesda. MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL. B L Operating Reactors Dranch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fichs 50-000.84/02/21, 8403140340
- 8403140272 Forwards corrected Page 22 for 830405 Amend 73 to License DPR-35 Change adds equal or less than symbols inadvertently left off 1.085 psig limiting safety sys setting for Tech Spec Section 2 2A

 LEECH.P H Operating Reactors Branch 2 84/02/22 HARRINGTON, W D Boston Edison Co 2pp 22636 327 24X Fiche 50-293,84/02/22.
- --B403140279 Corrected Page 22 to 830405 Amend 73 re 1,085 psig limiting safety sys setting for Yech Spec Section 2 2A e Boston Edison Co 83/04/05 1p 22636 331 24X Fiche 50-293,84/02/22.8403140272
- 8403010324 Forwards updated Rev 1 to "Inservice Testing Program," w/boundary coordinate info provided for locating valves & pumps on insp drawlings
 HARRINGTON: W D Boston Edison Co 84/02/27 VASSALLO, D B Operating Reactors Branch 2 2pp 22432 014 24X
 Fiche 50-293,84/02/27,8403010324
- ---B403010327 Updated Rev 1 to "Inservice Testing Program " * Boston Edison Co B4/02/27 40pp 22432 016 24X Fiche 50-293,84/02/27,8403010324
- B403090152 Forwards GE B40304 ltr supporting proposed change to control rod drive weekly surveillance Tech Specs.per P Leech 840203 telcon request HARRINGTON.W D Boston Edlson Co B4/03/05 VASSALLO.D B Operating Reactors Dranch 2 4pp 22575 129 24X Fiche 30-273.84/03/05.8403090152
- B403090240 Summary of B40216 meeting w/Northeast Nuclear Energy Co. Boston Edison Co. Vermont Yankee Nuclear Power Co & Teledyne Engineering Svcs In Waltham MA re addl Mark I torus structural analysis List of attendees encl SHEA. J Deparating Reactors Branch 5 84/03/07 CRUTCHFIELD, D Operating Reactors Branch 5 49p 22372 298 24X Fiche 50-000.84/03/07.8403090240
- 8403140107 Forwards results of secundary containment leak rate Test B 7 3 performed on 831213 to verify integrity of containment at Refueling Dutage & prior to refuel Results satisfactory HARRINGTON.W D Boston Edison Co 84/03/07 Office of Nuclear Reactor Regulation, Director 4pp 22620 358 24X Fiche 50-293,84/03/07.8403140107
- B403130111 Responds to B31230 request that Section V(A) of NRC order issued to util on B2011B be terminated Based on Improvements in organizational structure & methods of communicating status of safety-related activities, requirement terminated MURLEY.T E Region 1. Office of Director 84/03/09 HARRINGTON.WD Baston Edison Co 2pp 22A40 214 24X Fiche 50-293,84/03/09.8403150111
- --8403150117 Requests that NRC 820118 order requiring that corporate onsite representative position be established to provided daily audit of plant operations be terminated Organizational changes have reduced need for onsite representative HARRINOTON, W D Boston Edison Co 83/12/30 MURLEY, T E Region 1, Office of Director 2pp 22640 216 24X Fiche 50-293, 84/03/09,8403150111
- 8403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc list encl EISENHUT, D Q Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000,84/03/14,8403150275
- B403270010 Application for amend to License DPR-35, consisting of Proposed Tech Spec Change B4-02 allowing increased core flow HARRINGTON, H D Boston Edison Co B4/03/20 VASSALLO, D B Derating Reactors Branch 2 3pp 22769 165 24X Fiche 50-293, B4/03/20, B403270010
- --9403270015 Proposed Tech Spec Change 84-02, ellowing increased core flow * Boston Edison Co 84/03/20 2pp 22769 168 24X Fiche 50-293, 84/03/20, 8403270010
- --8403270022 "Safety Review of Pilgrim Nuclear Power Station, Unit 1 at Core Flow Conditions Above Rated Flow Throughout Cycle 6 " FISCHER, D L., GRIDLEY, R L. General Electric Co. NEDD-30242 83/08/31 34pp 22769 170 24X Fichs 50-273,84/03/20,8403270010

- --8403270024 Suppl 1 to "Safety Review of Pilgrim Nuclear Power Station Unit 1 at Core Flow Conditions Above Rated Flow for End~of-Cycle 6 "FISCHER, D L , GRIDLEY, K L General Electric Co NEDD-30242 S01 B3/07/30 15pp 22767 201 24X Fiche 50-293.84/03/20,8403270010
- 8403270055 Application to amend License DPR-35, consisting of Proposed Change 84-Dichanging Tech Specs to remove details of Section XI inservice insp program HARRINGTON, W D Boston Edison Co 84/O3/20 VASSALLO, D B Operating Reactors Branch 2 4pp 22774 i15 24X Fiche 50-293,84/O3/20,8403270055
- --8403270143 Proposed Tech Spac changes, removing details of Section XI inservice insp program
 * Boston Edison Co 84/03/20 10pp 22774 119 24X Fiche 50-293,84/03/20,8403270055
- @ Inspection reports, IE Bulletins & correspondence
- 8403020262 Forwards IE Insp Rept 50-293/83-26 on 831212-16 No Violations identified

 MARTIN, T T. Region 1. Office of Director 84/02/07

 HARRINOTON. W D Boston Edison Co 2pp 22440 081 24X

 Fiche. 30-293, 84/02/09, 8403020262
- -8403020272 IE Insp Rept 50-293/83-26 on 831212-16 No violations digntified Major areas inspected procedural & personnel qualifications for ultrasonic exam of recirculation piping weld intergranular stress corrosion cracking NARROW.L. REPRESENTATION AND CONTROL OF BUTTON BY 22440 OBS 24X Fiche 50-273,84/02/09,8403020262
- 8403020315 Forwards IE Insp Rept 50-293/84-02 on 840103-05 & 09-13 No MARTIN.T T Division of Engineering & Technical Programs HARRINOTON, W D Boston Edison Co 2pp 22437:007 24x Ficha 50-273,84/02/17,8403020315
- --8403020399 IE lnsp Rept 50-293/84-02 on 840103-05 & 09-13 No violations dentified Major areas inspected recirculation piping replacement program, including welding activities, plant maint program & ultrasonic test program & ultrasonic test program & Region 1, Office of Director GRAVE H & MCREARTY, R , SHAUB, T Region 1, Office of Director G4/02/09 lipp 22439 009 24X Fiche 50-293,84/02/17,8403020315
- 8403010324 Forwards updated Rev 1 to "Inservice Testing Program." w/boundary coordinate info provided for locating velves & pumps on insp drawings HARRINGTON.W D Boston Edison Co 84/02/27 VABBALLO.D B Operating Reactors Branch 2 2pp 22432:014 24X Fithe 50-293.84/02/27,8403010324
- 8403090047 R#sponds to 1E Bulletin 83-07, "Apparently Fraudulent Products Bold by Ray Miller, Inc." Suspect matl not supplied or used at facility HARRINGTON, W.D. Boston Edison Co. 84/02/27 MURLEY, T.E. Regio Office of Director. 2pp. 22576 002 24x Fiche 50-293, 84/02/27, 8403090047
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. i15pp 82709 237 24X Fiche 50-000,84/02/28,8401170072
- B403070330 Ack receipt of 840215 ltr informing NRC of steps taken to correct violations noted in 16 Insp Rept 50-293/83-23.
 BTARDSTECKI,R Division of Project & Resident Programs 84/02/28 HARRINGTON W D Boston Edison Co ip 22546 354 24X Fiche: 50-293,84/02/28,8403070330
- --8403070341 Responds to NRC 831208 ltr re violations noted in IE Insp. Rept 50-293/83-23 Corrective actions NDP raised mgt policy issues re-procurements which have taken longer than expected to resolve Completion expected by 840402 HARRINOTON-H D Boston Edison Co 84/02/15 STAROSTECKI, R Division of Project & Resident Progrems. 1p 22544 355 24X Fiche. 50-293,84/02/28,8403070330
- 84031500A7 Forwards IE Insp Rept 50-293/84-01 on 840101-0206 No violations noted Concern identified re program for feedback of operating experiences
 8TARGETECHIR Division of Project & Resident Programs 84/03/01
 MARRINGTON:W D Boston Edison Co 2pp 22641 025 24X
 Fithe: 50-293.84/03/01.8403150067

- --B403150073 IE Insp Rept 50-293/84-0; on B4010;-0206 No violations noted Major areas inspected operational safety verification, plant event followop, surveillance & maint activity review & followop on insps required by IE Dulletin 84-01 JOHNSON, J. MCGRIDE, M., BORCHARDT, Region i, Office of Director B4/02/23 i5pp 22641 027 24% Fiche 50-273,84/03/0i,8403150067
- 8402090007 IE Info Notice 84-i4, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enci ORACE.V N Division of GA, Bafeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,84020900007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valvas to Operate " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 1E Info Notice 84-15. "Reporting of Radiological Releases" Horosophic Amplication of Figure Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 119pp 22553 217 24% Fiche 50-000-84/03/02.8402090009
- 8402090011 IE Info Notice 84-i7, "Problems W/Liquid Nitragen Cooling Components Belaw Nil Ductility Tamp " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Ca of New York, Inc ii7pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- B402070024 1E Info Notice B4-07, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JURDAN:E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Editon Co of New York: Inc i1Bpp 22635 049 24X Fiche 50-000, 84/03/07, 8402070024
- 8402090028 IE info Notice 84-18, "Stress Corrosion Cracking in PMR 402070028 IE info Notice 89-18, others corposion ordering in Bys " Svc list encl JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 30-000,84/03/07,8402070028
- 8403130212 Informs of recent plant developments MH McBride appointed resident inspector, effective 831211 Ultrasonic insps of stainless steel piping sections reported indications of cracking GE contacted to assist in managing pipe repairs. MURLEY, T E Region 1. Office of Director 84/03/08 Plymouth, MA 2pp 22605 063 24X Fiche 50-273,84/03/08,8403130212
- 8402070031 lE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in O2070031 IE BOISETR 04-02. Partones of GE Tope Fra Relays IN 938 / Class IE Bafety Sys "Syc list encl
 DEYQUNO, R C Director's Office. Office of Inspection and
 Enforcement 84/03/12 Consolidated Edison Co of New York, Inc
 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8403260313 Ack receipt of 840301 ltr informing NRC of corrective & preventive actions taken re violations noted in IE Insp Rept 50-273/83-24 REPL 30-233-244
 BTAROBTECKI.R Division of Project & Resident Programs
 HARRINOTON.W D Boston Edison Co ip 22753 i55 24
 Fiche 50-293.84/03/20.84032603i3
- --8403260317 Responds to NRC 840207 ltr re violations noted in IE Insp Rept 50-293/83-24 Corrective actions personnel advised of importance of adherence to procedure re logging of temp during reactor heatups & cooldowns HARRINGTUN, W D Boston Edison Co 84/03/01 BTARDSTECKI, R Division of Project & Resident Programs 2pp 22753 136 Fiche 50-293,84/03/20,8403260313
- 8403270055 Application to amend License DPR-35, consisting of Proposed Change 84-01, changing Tech Specs to remove details of Section XI inservice insp. program HARINOTON, W.D. Boston Edison Co. 84/03/20 VASSALLO, D.D. D
- --8403270143 Proposed Tech Spec changes, removing details of Section XI Inservice insp program
 * Boston Edition Co 84/03/20 10pp 22774 119 24X
 Fichs 50-293,84/03/20,8403270055
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21,8402090043

- B402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list entl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22953 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403120027 "Radioactive Effluent & Waste Disposal Rept Including Radiological Impact on Humans, Jul-Dec 1983 " W/840301 ltr BOWMAN.C E Boston Edison Co 83/12/31 MURLEY, T & Region 1, Office of Director 74pp 22588 047 24% Fiche 50-293.83/12/31. 8403120027
- 8403200164 Monthly operating rept for Feb 1984 W/840313 ltr. HAMILTON, P., HARRINGTON, W.D. Boston Edison Co. 84/02/29. 7pp 22697 137 24X Fiche 30-293,84/02/29,8403200164
- S Reportable occurrences. LERs & related correspondence
- 8305040149 Forwards, "Condensate Demineralizer Resin Migretion Through Plant Vent & Standby Gas Treatment Sys," technical review rept No addl involvement necessary PELLET, J L Reactor Operations Analysis Branch. 83/04/19 SEYFRIT, K V Reactor Operations Analysis Branch ip 22789 300 24X Fiche 50-293,83/04/19,8303040149
- --8305040155 "Condensate Demineralizer Resin Migration Through Plant Vent & Standby Gas Freatment 8ys." technical review rept * Director's Office 83/04/19 3pp 22789 301 24X Fiche 50-293.83/04/19.8305040149
- 8403260233 Forwards summary list of deficiencies identified per iOCFR30 55(e),Part 2: & potential generic ltr repts for comments
 STAROSTECKI:R Division of Project Resident Programs 84/02/28
 Region 1. Office of Director 7pp. 22756.065 24X
 Fiche 50-000.84/02/28.8403260233
- 8403070283 PND-1-84-021 on 840301 radiographer working at field site could not fully retract 24 1 Ci Ir-192 to safe shielded position Gaused by improperly connecting pigtail to guidetube Whole body dose read 40 mrem.
 ROWE. C. GLENN. J. Region 1. Office of Director 84/03/02 ip 82546 359 24X Fiche 50-293.84/03/02.8403070283
- DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1
 F Security, medical, emergency & fire protection plans
- 8403140082 Public version of Rev 12 to Emergency Plan Implementing Procedure EPIP 700-1, "Emergency Phone List " W/831021 receipt form & JM Felton 840312 release memo NYKIRK. J W. PLIML.O Commonwealth Edison Co. 83/10/26
- 8403280117 Public version of Rev 7 to Emergency Plan Implementing Procedure EPIP 440-1, "Emergency Communications Sys & Operational Tests " W/840110 procedure change request form & JM Felton 840322 release memo PLIML-9 Commonwealth Edison Co 84/01/04 DENTIN, H R NRC No Detailed Affiliation Given 21pp 22811 167 24X Fiche 50-295.84/01/04.8403280119
- 8403020003 Revised emergency implementing procedures, including Rev i to Procedure EPIP 100-i. "Acting Station Director" W/840301 ltr # Commonwealth Edison Co 84/02/21 8pp 22442 187 24X Fiche, 50-295, 84/02/21, 8403020003
- 8403120326 Notification of 840308 meeting w/util in Bethesda,MD to discuss status of implementation of fire protection mod & proposed interim compensatory measures NORRIG. J A Operating Reactors Branch 1 B4/03/01 VARQA,S A Operating Reactors Branch 1, 2pp 22596 353 24X Fichs 50-295,84/03/01,8403120326
- 8403170314 Forwards IE Insp Repts 50-275/83-27 t 50-304/83-28 on 831122-1228 t 840202 t notice of violation Concerns re mgt control inadequacies, per TMI Action Plan Item II F [i, "Noble Gas Effluent Monitor," sypressed MIND, 3 A Division of Radiologica) t Materials Safety Programs 84/03/01 REED, C Commonwealth Edison Co 2pp 22673 196 24 Fiche 50-275,84/03/01,8403190314
- --8403190321 Notice of violation from insp on B31122-840202 HIND, J A Division of Radiological & Materials Safety Programs B4/03/01 3pp 22673 198 24X Fithe 30-295.84/03/01.8403190314

- --8403190334 IE Insp Repts 50-275/83-27 & 50-304/83-28 on 831122-840202 Violation noted failure to follow plant procedures resource handling, to evaluate radiological hazards & to control access to high radiation area LOVENDALE,P C , NICHOLSON, N , OREGER, L R Region 3, Diffice of Director 84/02/27 i4pp 22673 201 24X Fichs 50-275,84/03/01.' 8403190314
- 8403130185 Discusses evaluation of State of IL & local plans & preparedness for facilities Plans adequate to protect health & safety of public Approval of public alert notification sys conditional on verification of criteria of NUREG-0654 SPECKIS W Federal Emergency Management Agency 84/03/02 DIRCKSW J Diffice of the Executive Director for Operations ip 22613 316 24X Fiche 50-295, 84/03/02, 8403130185
- B403120051 Notifies of 840323 workshop on fire protection safe shutdown requirements of 10CFR30, App R in Rosemont, IL to discuss IE info Notice 84-09 & provide add1 shutdown analyses &/or mod guidance Agenda enci
 SPEBSARD.R L Division of Emergency Preparedness & Operational Bupport 84/03/06 REED.C Commonwealth Edison Co 3pp 22590 297 24X Fiche 50-295, 84/03/06.8403120051
- B403210089 Revised Page 3 to Emergency Plan Implementing Procedure EPIP-180-1, "Rad/Chem Director" W/840320 transmittal & receipt form PLIML, O Commonweelth Edison Co 94/03/07 2pp 22705 320 24X Fiche: 50-293.84/03/07, 8403210089
- B403190195 Revised pages to Emergency Plan Implementing Procedures EPIP-180-1.adding rad/chem ofc to habitability checks W/840309 transmittal & receipt form.

 * Commonwealth Edison Co. 84/03/09 5pp 22671 100 24X Fiche 50-299.84/03/09.8403190195
- 8403230124 Rev 4 to Emergency Plan Implementing Procedure EPIP-330-1, "Classification of GSEP Conditions " W/840322 transmittel ltv PLIML, G Commonwealth Edison Co 84/03/22 App 22730 187 24X Fiche 50-295,84/03/22,8403230124
- G Adjudicatory correspondence
- 8403020134 Forwards util 840228 ltr to Denton requesting permission to withdraw application for license amends re containment leakage tests criteria Hotion will be filed upon request. Certificate of Bvc enci BIEPTOE:P.P Isham. Lincoln & Beals BIEPTOE:P.P Commonwealth Edison Co 84/02/28 LAZO,R M Atomic Safety and Licensing Board Panel 6pp 22441 345 24x Fiche 50-295.84/02/28,8403020134
- B403D2014D Notice of appearance in proceeding Certificate of Svc encl BTEPTOE.P P Commonwealth Edison Co STEPTOE.P P Isham: Lincoln & Beals 84/02/28 ip 22443 253 24x Fiche 50-275, 84/02/28, 8403020140
- --8403020146 Notice of appearance in proceeding Certificate of Svc encl GILOMEN.B R Commonwealth Edison Co GILOMEN.B R, Isham. Lincoln & Beale 84/02/28 3pp 22443 254 24X Fiche, 50-295, 84/02/28, 8403020140
- 8403i40134 Response to Citizens Against Nuclear Power (CANP) 8402i3 petition to intervene & request for hearing Request should be held in absyance pending action on util request to ulthdraw application Certificate of Svc encl PERLIS.R 9 Rearing Branch 3 84/03/05 Atomic Safety and Licensing Board Panel. 7pp 22624 205 24X Fiche 50-295,84/03/05,8403140134
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8403050020 Responds to FOIA request for documents re PABNY submittal on sys interactions; repts evaluating submittal & list of repts/analyses from LLL evaluating FABNY sys interaction program Forwards app A documents
 FELTON, J M Division of Rules and Records 83/12/07. SHULLY, 8. Union of Concerned Scientists & App 22525.098 24X
 Fiche 50-000,83/12/07,8403050020
- --8403050028 Discusses licensee proposed review plans addressing ACRS recommendations re sys interaction study GOLLERIK R Assistant Director for Operating Reactor Projects (Fre 791030) 77/10/21 BENDERIM ACRS Advisory Committee on Reactor Safeguards 2pp 22525 144 24X Fiche 50-000, 83/12/07, 8403030020

P Operating license etage documents & correspondence

- 8403020131 Withdraws B30808 application for amend to Licenses DPR-39 & DPR-48, chenging acceptance criteria for containment leak rate tests Evidentiary hearing in 1984 would dietract technical & legel resources from higher priority tasks FARRAR, D Commonwealth Edison Co 84/02/28 DENYON, H R Office of Nuclear Reactor Regulation, Director 2pp 22443 243 24X Fichs. 50-295, 84/02/28, 8403020131
- 8403050117 Forwards supplemental response to Generic Ltr 83-28,
 "Required Actions Based on Generic Implications of Selem
 ATHS Evente"

 BARNES:P L Commonweelth Edison Co 84/02/29 DENTON, H R Office
 of Nuclear Reector Reguletion. Director 26pp 22488 084 24X
 Fiche 50-000,84/02/29;8403050119
- 8403070145 Requests submittel of documentation re NUREQ-0737 items within 30 days to complete technical reviews & implementation, excluding Suppl 1:by Sept 1784. VAROA: B A Operating Reactors Brench 1 84/03/02 FARRAR: D L Commonwealth Edison Co 2pp 22592 307 24X Fiche 50-295,84/03/02,843390145
- 8403280090 Forwards Amends 84 & 74 to Licenses DPR-39 & DPR-48, respectively, sefety evaluation & notice of issuance & availability Amends allow performence of extensive preventive maint on shered diseal generator NORRIB. J. Operating Reactors Branch 1 84/03/12 FARRAR.D L Cammonweelth Edison Co. 3pp. 22812 293 24X Fiche 50-295.84/03/12, 840328090
- ----B403280101 Amends 84 & 74 to Licenses DPR-39 & 48, respectively, allowing performance of extensive preventive meint on chared diesel generator VARQA, B A Operating Reactors Branch 1 84/03/12 App 22812 296 24X Fiche 50-295,84/03/12,8403280090
- --8403280106 Bafety evaluation supporting Amends 84 & 74 to Licensee DPR-37 & DPR-48, respectively.

 + Office of Nuclear Reactor Regulation, Director 84/03/12 9pp 22812.302 24% Fichs 50-275.84/03/12,8403280090
- ---B403280108 Notice of issuance & availability of Amands 84 & 74 to Licenses DPR-39 & DPR-48, respectively VARQA/S.A. Operating Reactors Branch 1 84/03/12 3pp 22812.31t 24X Fiche.50-295.84/03/12.8403280090
- 8403260182 Clerifies NUREQ-0737. Item 11 K 3 3i, in response to Generic Ltr 83-35 Hestinghouse Ownere Group authorized program to demonstrate conservation of WFLASH small breek LOCA enalyses, per Item 11 K 3 30

 BARNES, P. L. Commonweelth Edison Co. 84/03/21 EISENHUT, D. 0

 Division of Licensing 1p 22756 170 24X Fiche 50-000, 84/03/21.

 8403260182,
- G Inspection reports: 1E Bulletins & correspondence
- 8403050223 Further rasponse to FQIA request for records of named individuals; including repte, analyses, studies, test calculations, procedures & prectices for messurement of RCB laskage Forwards App C documents, Search continuing FELTON, J. M Division of Rules and Records. 84/02/07, MADDEN, T J Kaye, Bchoier, Flerman, Hays & Hendler 3pp 22496-234. 24X Fiche: 50-000,84/02/07,8403050223
- --B403050256 Notifies that independent measurements of identified & unidentified RCB leek rates for all PMRs in Region III performed per Procedures 617278 & 61728B Inep findings summarized NORELIUS, C E Division of Engineering 82/03/08 JORDAN, E. L Division of Engineering & Quality Assurance (Pre 830103), 2pp 22496:270. 24X Fiche 50-000, 84/02/07, 8403050223
- 8403120134 Forwards IE Insp Repte 50-237/84-01, 50-249/84-01, 50-254/84-
- --8403120137 IE Insp Repts 50-237/84-01, 50-249/84-01, 50-254/84-01, 50-254/84-01, 50-254/84-01 & 50-304/84-01 on 840203-14 No noncompliance or deviations identified Mejor areas inspected; allegations of improper operation CHRISBOTIMOS N, WALKER, R D. Region 3, Office of Director 84/02/21, 4pp. 22590 092, 24X Fiche 50-000,84/02/23,8403120134

- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan" Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THDMAS, B Commonwealth Edison Co 84/02/24 KEPPLER, J 9 Region 3, Office of Director 3pp 22470 139 24X Fiche 50-000,84/02/24,8403050043
- ---8403050046 Rev O to "Corporate Regulatory Performance Improvement Flam" * Commonwealth Edison Co 84/02/29 22pp 22490 142 24X Fichs 30-000.84/02/24.8403050043
- 8401190072 iE info Notice 84-13, "Potential Deficiency in Motor Operated Velve Control Circuits & Annonclation " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- B403170314 Forwards IE Inep Repts 50-295/83-27 & 50-304/83-28 on B3(122-1228 & 840202 & notice of violation Concerns re mgt control inadequacise.per TMI Action Plen Item 1I F 1 1. "Noble Gas Effluent Monitor," syressed HIND, J A Division of Radiological & Meteriels Sefety Programe B4/03/01 REED, C Commonwesith Edieon Co 2pp 22673 176 24X Fichs 50-295.84/03/01,8403190314
- --8403190321 Notice of violation from insp on 831122-840202 HIND, J A Division of Radiological & Materiels Safety Programs 84/03/01 3pp 22673 198 24X Fiche 50-295.84/03/01.8403190314
- --8403170321 Notice of violation from insp on 831122-840202, HIND, J A Division of Rediologicei & Materiale Safety Programs 84/03/01 3pp 22673 198 24X Fiche 50-275,84/03/01,8403190314
- --8403/90334 iE Insp Repts 50-295/83-27 & 50-304/83-28 on 83i122-840202 Vipistion noted failure to foliow plant procedures resource handling; to evaluate radiological hazerds & to control access to high radiation area LOVENDALE.P C , NICHOLSON, N , OREGER, L R Region 3, Office of Director 84/02/29 i4pp 22673 20i 24X Fiche 50-295.84/03/01, 8403i90314
- 8402090007 IE Info Notice 84-14, "Highlighte of Recent Transport Reguletory Revs by DOT & NRC " Svc list enci GRACE.JN Division of QA. Safaguards & Inspection Progrems (Post B30103). 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552,329 24X Fiche 50-000,84/03/02.8402090007
- 8402070008 iE lnfo Notice 84-i6, "Failure of Automatic Sprinkier 8ys Valves to Operate " Svc iist anci JORDAN.E L. Division of Emergency Preparadness & Engineering Response (Post E00103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releasee "
 Svc list encl
 JURDAN,E L. Division of Emergency Preparednese & Engineering
 Response (Poet 830103) 84/03/02 Consolideted Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02.8402090009
- B4020900ii IE Info Notice 84-i7, "Problems W/Liquid Nitrogen Cooling Components Below Nii Ductility Temp " Svc list enci JURDAN:E L. Division of Emergency Preparedneee & Engineering Response (Poet B30103) 84/03/05 Consolidated Edison Co. of New York, Inc 117pp 22553 336 24X Fiche: 50-000, 84/03/05, 8402090011
- B402090024 IE Info Notice 84-09.Rev I. "Lessons Learned From Insps of Fire fratection Safe Shutdown Sys " Syc list enci JORDAN E L Division of Emergency Preperedness & Engineering Response (Poet B30103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche. 50-000, 84/03/07.8402070024
- 8402090028 IE Info Notice 84-18, "Strees Corrosion Crecking in PWR 8ys." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edieon Co of New York, Inc. (18pp. 22584 186 24% Fiche 50-000,84/03/07,8402090028
- 8403220161 Forwards 1E Insp Repts 50-295/83-26 & 50-304/83-27 on 831221-840209 & notice of violation W/o notice of violation SHAFER, W D Region 3. Office of Director 84/03/07 REED.C Commonwealth Edison Co 2pp 22717 188 24X Fichs 50-295.84/03/07, 8403220161

- --8403220165 IE Insp Repts 50-295/83-26 & 50-304/83-27 on B31221-840209 Noncompliance noted failure to comply w/approved written procedures.Paragraphs 5.6, 11 & 14.resulting in reactor trips & LERs
 HOLZMER, M M , DUNAHAY, F R , BDYD, D C Region 3, Dffice of Director 84/03/06 12pp 22717 190 24X Fiche 50-295.84/03/07, 8403220161
- 840209003i IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list enc!
 DEYDUNO, R C Director's Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000,84/03/12,8402090031
- 8403230088 Ack receipt of regulatory performance improvement plan Periodic meetings requested to discuss progress on program by provide feedback KEPPLER, J O Region 3. Office of Director 84/03/20 THOMAS; B Commonwealth Edison Co ip 22730 161 24X Fiche 50-000; 84/03/20, 8409270068
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLEN.J 9 Region 3. Office of Director 3pp 22730 162 24X Fiche 50-000. 84/03/20.8403230088
- --8403230126 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresdem.Quad Cities, Zion & LaGalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations " * Commonwealth Edison Co 84/02/27 22pg 22730 165 24% Fithe 50-000,84/03/20,8403230088
- 8403250196 Forwards responses to IE Bulletin 83-07. "Apparently Fraudulent Products Sold by Ray Miller. Inc " Quad Cities supplied w/piping matls from Ray Miller. Inc during const. Evaluation encl Concerns of IE Bulletin 83-05 satisfied BARNES.P L. Commonwealth Edison Co. 84/03/20 KEPPLER.J Q. Region G. Office of Director 19pp 22754 185 24X Fiche 50-000.84/03/20.84/03260196
- 8402090043 IE Info Nutice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fichs 50-000,84/03/21,8402090043
- 8402090044 iE Info Notice 84-20, "See Life of Relays in Safety-Related Sys " See list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22433 001 24X Fiche 50-000,84/03/21,8402040044
- R Periodic operating reports & related correspondence
- 8403060217 "Effluent & Waste Disposal Semiannual Rept.Jul-Dec 1983 Oaseous Effluents, Summation of all Releases " W/840210 ltr GRAESSER.K L Commonwealth Edison to 83/12/31 KEPPLER.J Q Region 3, Office of Director 27pp 22511,159 24X Fichs 50-295.83/12/31.8403060217
- 8403080197 "Rept of Occupational Personnel Radiation Doses,1983 "
 W/840227 ltr
 SCOTT,J S Commonwealth Edison Co 83/12/31 13pp 22559 099
 24% Fiche 50-000,83/12/31,8403090197
- 8403220120 Annual whole body external exposures for 1983 W/840316 itr RYBAK.B Commonwealth Edison Co 83/12/31 7pp 22716 007 24X Fiche 50-000.83/12/31.8403220120
- 8403170156 Monthly operating repts for Feb 1984 W/840309 ltr. AUSTIN, G , GRAESBER, K L Commonwealth Edison Co 84/02/29 13pp 22669 163 24X Fichs 50-295,84/02/29,8403190156
- S. Reportable occurrences, LERs & related correspondence
- B211150076 Discusses events involving loss of electrical inverters including attendant inverters to vital instrument buses.

 Recommendations provided by Nuclear Bafety Analysis Ctr are excellent in helping to reduce instrument failures.

 ASHE: F Reactor Operations Analysis Branch B2/10/21 SEYFRIT, K V Reactor Operations Analysis Branch Bp 22775 223 24X Fishe 30-000. B2/10/21, B211150076
- 8403060249 LER 84-006-00 on 840203.RCS increased above 200 f on computer CRT display before energizing safeguards sys Caused by operator error Operators reminded to complete all necessary prerequisites before starting action W/840302 ltr CAMPBELL,E J. GRAESEER,K L. Commonwealth Edison Co. 84/03/02 3pp 22517 076 24X Fiche 50-275.84/03/02.8403060249

- 8403070164 LER 83-055/03L-0 on 830613 containment purge radiation monitor 1RT-PR07C recorder found out of tolerance low Cause undetermined Recorder recalibr to within tolerance Preventive maint program implemented W/840305 ltr KASSNER.0 . GRAESSER.K L Commonwealth Edison Co 84/03/05 KEPPLER.J O Region 3, Office of Director 2pp 22575.135 24X Fiche 30-275.84/03/05.8403090164
- 8403270035 LER 84-007-00 on 840222, annunciators for steam generator feed flow mismatch, level deviation & lo-lo level alarmed & reactor tripped Cause of trip could not be determined Unit brought back on line on 840223 W/840322 ltr RATHSAM.R. GRAESSER.K L Commonwealth Edison Co 84/03/22 3pp 22767 324 24% Fichs 30-295.84/03/22.8403270035
- BA03270109 LER B4-D10-00 on 840224, fredwater pump C decreased to min speed, causing steam generator D low level coincident w/ steam flow-feed flow mismatch & reactor trip Caused by location of self-bleeding moisture trap W/840323 ltr BEINECKE, P J, GRAESSER, K L Commonwealth Edison Co 84/03/23 app 22774 026 24X Fiche, 50-295, 84/03/23, 8403270109
- B403270203 LER B4-007-00 on B40223, during unit startup, control rod urgent failure received during rod withdrawal, preventing rod motion Operator tripped reactor manually Alarm spurious Cause not determined #/B40323 ltr
 CHIN.R Y. GRAESERIK L Commonwealth Edison Co 84/03/23 3pp 22771 319 24X Fiche 50-295,84/03/23,8403270203
- 8403270265 LER 84-008-00 on 840223, loop D regulating valve failed to open & level in steam generator D feil Caused by supervisor inadvertently leaving instrument air supply valve closed while performing step 32(b) W/840323 itr BEINECKE, P J , GRAESSER, K L Commonwealth Edison Co 84/03/23 3pp 22771 316 24X Fiche 50-295,84/03/23,8403270265
- DOCKET 50-294 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

 F. Security, medical, emergency & fire protection plans
- 8403060238 Emergency plan implementing procedures, including IP-2 renotification of unusual event, IP-3 realert, IP-4 resite emergency & IP-4 readiological amergency plan, activation at support ctr WI640228 itr & list of effective pages MILLG.L M Tennessee Vailey Authority 84/02/10 D'REILLY, J P Region 2. Iffice of Director \$20p\$ 22516 078 24X Fiche 50-257,84/02/10,8403060238
- 8403060571 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810709 Generic Ltm 81-27 W/o request entire plan will be placed in PDR VABSALLO.D B Operating Reactors Branch 2 84/02/10 PARRIS.H 0 Tennessee Valley Authority 2pp 22552 261 24X Fiche 50-259,84/02/10,8403060571
- 8403040235 Rev 5 to Procedure IP-9. "Muscle Shoals Emergency Ctr Implementing Procedures Document" W/840213 ltr MAXMELL, R. SLIGER, E. K. Tennesses Valley Authority 84/02/13 63pp 22518 023 24% Fiche 50-000,84/02/13,8403040235.
- 8403040147 Forwards revised effective pages to Knoxville Emergency Ctr. Central Emergency Control Ctr. Div of Nuclear Power Emergency Ctr & Muscle Bhoals Emergency Control Ctr emergency plan implementing procedures W/o Muscle Shoals pages
 MILLS.L. M Tennessee Valley Authority 84/02/28 0'REILLY.J P
 Region 2. Office of Director 1p 22516 165 24X
 Fiche 80-000.84/02/28,8403060147
- --B403060163 Revised first of effective pages to Knoxville Emergency Ct emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 8pp 22516:166 24X Fiche 50-000, 84/02/28.840366147
- --8403060187 Revised list of effective pages to Central Emergency Control Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 8pp 22516.174 24X Fiche 30-000,84/02/28.8403060147
- --8403060204 Revised list of effective pages to Div of Nuclear Power Emergency Ctr amergency plan implementing procedures * Tennessee Valley Authority 84/02/06 4pp. 22516:182 24X Fiche 50-000,84/02/28.8403060147
- 8403140162 Ack receipt of 840222 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-259/83-57, 80-260/83-57 & 50-296/83-57
 LEHIS:R C Division of Project & Resident Programs. 84/02/27 PARRIS:H G Tennessee Valley Authority 1p 22655 273 24X Fiche 50-259.84/02/29.8403160162

- ~-8403160171 Responds to NRC 840123 ltr re violations noted in [E Insp Repts 50~259/83-57,50~260/83-57 & 50~296/83-57 Corrective actions policy statement issued to health physics technicians re high radiation area doors MILLS,L M Tennessee Valley Authority 84/02/22 0'REILLY, J P Region 2: Office of Director 5pp 22655 274 24X Fiche 50~259,84/02/29,8403160162
- >-04031601B1 Netice of violation from insp on 031126-1225 # Region 2. Office of Director 84/01/23 2pp 22655 201 24X Fiche 50-259.84/02/29.0403160162
- --8403160186 IE Insp Repts 50-259/83-57,50-260/83-57 & 50-296/83-57 on 831126-1225 Violations noted failure to lock high radiation area, to follow special work permit & to have adequate fire protection maint procedure PAULK, G L. Region 2, Office of Director 84/01/21 App 22655 283 24X Fiche 50-259,84/02/27,8403160162
- g403160218 Ack receipt of 840209 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-239/83-40, 30-250/83-40 & 50-296/83-40 LEWIS, R C Division of Project & Resident Programs 84/03/01 PARRIS
- --8403160223 Responds to NRC 840111 ltr re violations noted in 1E Insp Repts 50-259/83-40, 50-260/83-40 & 50-276/83-40 Corrective actions radiological emergency pianning program reviewed & areas requiring rev identified MILLS-L M Tennessee Valley Authority 84/02/09 O'REILLY, J P Region 2, Office of Director 6pp 22661 099 24X Fiche 50-259, 84/03/01, 8403160218
- --8403140230 Forwards IE Insp Repts 50-259/83-40, 50-260/83-40 & 50-296/83-40 on 831017-21 & 1122 & notice of violation LEWIB, R C Division of Project & Resident Programs 84/01/11 PARRES, H G Tennessee Valley Authority 2pp 22641 105 24X Fiche 50-259, 84/03/01, 8403140218
- --8403160237 Notice of violation from insp on 831017-21 & 1122 * Region 2, Office of Director 84/01/11 3pp 22661 107 24X Fiche:50-259,84/03/01,8403160218
- --8403160244 IE Insp Repts 30-259/83-40, 30-260/83-40 & 50-296/83-40 on 831017-21 & 1122 Noncompliance noted failure to control documents, properly train emergency personnel in protective action requirements & incorporate protective action DECKER.TR Region 2, Office of Director 84/01/06 9pp 22661 110 24X Fichs 50-259,84/03/01,8403160218
- 3403160345 Extends invitation to attend region 840316 workshop at regional ofc to discuss 10CFR50. App R requirements & recent results of imap to help resolve misunderstandings associated w/requirements

 LEHISLR.C Division of Project & Resident Programs 84/03/02 PARRISLH OF Tennessee Valley Authority 2pp 22660 083 24X Fiche 30-000,84/03/02,8403160345
- 1403130485 Ack receipt of 840119 itr transmitting Rev 7 to security personnel training & qualification plan Rev consistent w/provisions of 10CFR50 54(p) & acceptable LENIS.R C Division of Project & Resident Programs 84/03/08 PARRIS,H, O Tennesse Valley Authority 2pp 22613 210 24x Fiche 50-259,84/03/08,8403130485
- 403130484 Ack receipt of 840130 itr transmitting rev to physical security plan Rev consistent w/provisions of 10CFR30 54(p) & acceptable LEHIS.R.C. Division of Project & Resident Programs 84/03/09 PARRIS.H G Tennesses Valley Authority. 2pp 22613 197. 24X Fiche 50-259.84/03/09.8403130484
- 403160025 Advises that 840116 rev to physical security personnel training & qualification plan consistent w/provisions of 100FR50.54(e) & acceptable LEHIB-R C Division of Project & Resident Programs 84/03/13 PARRIGH G Tennesses Valley Authority 2pp 22653 358 24x Fiche 50-259,64/03/13,8403160025
- **QG190136 At ** receipt of 840221 & 0312 ltre informing NRC of steps taken to correct violations noted in IE Insp Repts 30-259/83-39, 30-260/83-39 & 50-296/83-39 Responses meet 10CFR2 201 requirements.

 LENIS,R C Division of Project & Resident Programs. 84/03/14 PARRIS,H Q Tennesses Velley Authority, ip 22670 314 24X Piche: 30-259,84/03/14,8403190136

- --B403190149 Supply response to NRC B40120 ltm re violetions noted in IE Insp Repts 30-239/83-59, 30-240/83-39 % 50-294/83-59 Responses withheld (ref 10CFR73 21) MILLS, L M Tennesses Valley Authority 84/03/12 O'REILLY, J P Region 2, Office of Director ip 22670 315 24X Fiche 50-259,84/03/14,8403190134
- --B403190161 Responds to NRC 840120 Itr re violations noted in IE Insp Repts 50-259/83-59,50-260/83-59 & 50-296/83-59 Responses withheld (ref 10CRR73 21) MILLS,L M Tennessee Valley Authority 84/02/21 D'REILLY,J P Region 2, Office of Director 1p 82670 316 24X Fiche 50-259,84/03/14,8403190136
- --8403190172 Forwards IE lnsp Repts 50-239/83-59, 50-260/83-59 & 30-296/83-59 on 831216 & notice of violation Notice of violation withheld (ref 100FR2 790 & 73 21)
 LEWIS.R C Division of Project & Resident Programs 84/01/20 PARRIS.H G Tennessee Valley Authority 2pp 22670 317 24X Fiche 50-259, 84/03/14, 8403190136
- --8403190188 IE Insp Repts 50-259/83-59,50-260/83-59 & 50-296/83-59 on 831216 Noncompliance noted security force member failed to control access to area Details withheld (ref [OCFR73 21 & 2 790)

 TILLMAN,A Region 2. Office of Director 84/01/19 lp 22670 319 24% Fiche 50-259,84/03/14.8403190136
- 8403270117 Forwards FEMA final rept for 831015-16 emergency exercise VERRELLI,D M Division of Project & Resident Programs 84/03/20 PARRISH 0 Tennessee Valley Authority ip 22807 027 24X Fiche 50-297.84/03/20.8403270117
- 9 Adjudicatory correspondence
- 8403200059 Submits addl info on util initiatives in PRA, per response to 840227 ltr Effort to reduce number of violations & risks maintained FREEMAN.S D Tennessee Valley Authority 64/03/12 MARKEY, E J House of Rep. Interior & Insular Affairs 2pp 22685 033 24X Fiche 50-259.84/03/12.8403200059
- J Insurance & indemnity information
- 8403060334 Forwards Endorsement 73 to NELIA Policy NF-198 DUCK J R Marsh & McLennan, Inc 84/02/28 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 22516 009 24X Fiche 50-259.84/02/28.8403060334
- P Operating license stage documents & correspondence
- 8403060076 Forwards request for addi info re inservice testing of pumps & vaives, in order to complete review of 820831 & 830406 aubmittals Response requested within 45 days of itr receipt VASSALLO, D B Operating Reactors Branch 2 84/02/10 PARRIS. H G Tennesses Valley Authority 4pp 22328 289 24% Fiche 50-259.84/02/10.8403060076
- 8403140340 Summary of 831215 meeting w/GE & Mark I Dwners Group in Bathesda,MD re Mark I containment wetwell-drywell vacuum breaker design methodology BIEGEL,B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fiche 50-000,84/02/21.
- B403010306 Application for amend to Licenses DPR-33 DPR-52 & DPR-68 changing Tech Space to lower Group i isolation setpoint for reactor lower water level M/proprietary NEDE-30012, " MSIV Water Levei "Rept withheld (ref 10CFR2 790) MILLS, L M Tennessee Valley Authority B4/02/22 DENYON, H R Office of Nuclear Reactor Regulation, Director 3pp 22433 042 24% Fiche 50-259, 84/02/22, 8403010306
- --8403010313 Proposed changes to Tech Specs lowering Group I isolation setpoint for reactor lower water level Waffidavit

 * Tennessee Valley Authority 84/02/22 29pp 22433 045 24K Fiche 50-259,84/02/22,8403010306
- 8403;40276 Requests 840307 meeting w/TVA in Chattanooga, TN to discuss design of analog trip sys for Unit 3 in light of failure of analog transmitters experienced in Unit 1, per util 840123 request for license amend VASSALLG, D 8 Operating Reactors Branch 2 84/02/28 PARRIS, H 6 Tennessee Valley Authority 2pp 22636 327 24X Fiche 50-294, 84/02/28, 8403140274

- 8403150323 Forwards info re BNL dose reduction project plant visit info ailous BNL personnel to better prepare for station visit. expedite paperwork & minimize impact on plant personnel VASSALLO, D B Operating Reactors Branch 2 84/02/28 PARRIS.H O Tennessee Valley Authority 46p 22662 040 24X Fithe 50-259.84/02/28.8403150323
- 8403130007 Forwards response to Generic Ltr 83-36 re NUREG-0737 Tech Specs MILLS.L M Tennessee Valley Authority 84/03/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 3PP 22613 349 24X Fiche 50-259,84/03/07.8403130007
- 8403130025 Informs that addi info requested on 831012 re reactor protection sys power monitoring sys design mods will be submitted by 840702 MILLS.L M Tennessee Valing Authority 84/03/07 DENYON, H R Office of Nuclear Reactor Regulation, Director ip 22614 362 24X Fiche 50-259,84/03/07,8403130025
- 8403160247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rev 7 to topical QA program.per 840302 telcon
 LENIBAR C Region 2. Office of Director 84/03/08 PARRIS,H 0 Tennessee Valley Authority ip 22660 361 24X
 Fiche 50-000.84/03/08.8403160247
- 8403160373 Notifies of use of ASME Nuclear Components Code Case N32-4 for hydrostatic testing of Class 3 embedded piping NRC position re use of Code Case N32-4 requested MILLS:L M Tennessee Valley Authority 84/03/12 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 22660 014 24% Fiche 50-000.84/03/12.8403160373
- 8403150275 Ceneric Ltr 84-07 to all licensees of BMRs re procedural guidance for pipe replacement at BMRs 8vc list encl EISENHUT, D C Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 394 24% Fiche 50-000, 84/03/14,8403150275
- 8403200170 Forwards response to Item 4 5 of Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATMB Events" re reactor trup sys reliability Control rod tests check rod insertion times & hydraulic screw valves HILLS,L H Tennessee Valley Authority 84/03/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 22700 024 24X Fiche 50-259.84/03/15.8403200170
- 8403260229 Forwards add1 info re test configuration & results of verification testing.per 840106 request re adequacy of station electric distribution sys voltages Test results indicated no unexpected voltage levels
 MILLS.L. M Tennessee Valley Authority 84/03/19 DENTON, H R
 Defice of Nuclear Reactor Regulation. Director 26pp 22796 12
 24X Fiche 50-259.84/03/19.8403260229

Q Inspection reports. It Bulletins & correspondence

- B403070054 Responds to NRC Itr re violations noted in IE Insp Repta 50-259/83-09, 50-260/83-09 & 50-296/83-09 List of identified deficiencies & implementation schedule provided to senior NRC inspector on B30901 MILLS.L H Tennessee Valley Authority 83/09/15 O'REILLY, J P Region 2, Office of Director in 22547 261 24X Fiche 50-259,83/09/15,8403070054
- 8403070237 Updates 830715 response to NRC 830616 ltr re violations noted in IE Insp Repts 50~259/83-19.50~250/83-19 & 50~259/83-19 perating instructions revised & Units 2 & 3 PEC charging sys operational MILLS.L M Tennessee Valley Authority 83/09/30 0'REILLY, J P Region 2. Office of Director 1p 22541 361 24X Fiche 50~259,83/09/30.8403070237
- 8403070271 Supple 830830 response to NRC ltr re violations noted in IE Insp Repts 50-257/83-23, 50-260/83-23 & 50-276/83-23 Borel test specimen installation will be delayed until E31028 due to late receipt of matls per 831012 telcon KAMMER, D S Tennessee Vailey Authority 83/10/21 G'REILLY, J P Region 2, Dffice of Director ip 22546 355 24% Fiche 50-259,83/10/21,8403070271
- 8403070023 Responds to NRC ltr reviolations noted in IE Insp Repts 50-259/83-27,50-260/83-27 & 50-296/83-27 Corrective actions compitance w/instructions will be achieved & corrective actions will be completed before Cycle & operation MILLS.L.M Tennessee Valley Authority 83/10/27 O'REILLY.J P Region 2. Office of Director ip 22541 262 24X Fiche 50-259,83/10/27,8403070023

- 8403070067 Forwards IE Insp Repts 50-259/83-50.50-260/83-50 & 50-276/83-50 on 830912-16 & 26-30 Unresolved item repossible high radiation doses measured by personnel dosimeters discussed on 831028, considered closed G'REILLY.J P. Region 2. Office of Director 84/01/11 PARRIE, H & Tennassee Valiey Authority 2pp 22545 341 24X Fiche 50-259, 84/01/11, 8403070067
- --8403070072 IE Insp Repts 50-259/83-50,50-260/83-50 & 50-296/83-50 on 831028 No violations or deviations noted Major areas inspected TLD & multiple badging DEBS,8 T Region 2, Office of Director B3/12/05 5pp 22545 343 24X Fiche 50-259.84/01/11.8403070067
- 8403160232 Forwards 1E Insp Repts 50-259/84-04, 30-260/84-04 & 50-276/84-04 on 840123-27 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/02/16 PARRIB.H 0 Tennesses Valiey Authority 2pp 22661 029 24% Fichs 50-259,84/02/16,6403160232
- ---B40316023B iE Insp Repts 50-259/B4-04, 50-260/B4-04 & 50-296/B4-04 on B40123-27 No violations or deviations noted. Major areas inspected startup testing, new fuel receipt plant tours & MSIV repair status
 DAVENPORT, K E Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs B4/02/14 5pp 22661 031 24% Fiche 50-259, 84/02/16, 8403160232
- B401190072 IE Info Notice B4-13. "Potential Deficiency in Motor Operated Valve Control Circults & Annunciation " Svc list ancl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 94/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000/84/02/28.8401190072
- 8403160162 Ack receipt of 840222 ltr informing NRC of steps taken to carrect violations noted in IE Insp Repts 50-259/83-57, 30-260/83-57 & 50-289/83-57

 LEHIS,R C Division of Project & Resident Programs 84/02/29 PARIS,H O Tennessee Valley Authority 1p 22655 273 24X Fiche 50-259-84/02/29,8403160162
- ---8403160171 Responds to NRC 840123 itr re violations noted in IE Insp Repts 50-259/83-57,50-260/83-57 & 50-296/83-57 Carrective actions policy statement issued to health physics technicians re high radiation area doors MILLB, L M Tennesses Valley Authority 84/02/22 G'REILLY, J P Region 2, Office of Director 3pp 22655-274 24X Fichs 50-259,84/02/29,8403160162
- --8403160178 Forwards IE Insp Repts 50-259/83-57, 50-260/83-57 & 50-296/83-57 on 831126-1225 & notice of violation LEWIS.R C Division of Project & Resident Programs 84/01/23 PARRIS.H 0 Tennesses Valley Authority 2pp 22655 279 24) Fiche 50-259,84/02/29,8403160162
- ~-8403160181 Notice of violation from insp on 831126-1225 * Region 2, Office of Director 84/01/23 2pp 22655 281 24X Ficha 90-259,84/02/29.8403160162
- --8403160186 1E Insp Repts 5D-259/83-57, 50-260/83-57 & 30-296/83-57 on 831126-1225 Violations noted failure to lock high radiation area, to follow special work permit & to have adequate fire protection maint procedure PAULK.O L. Region 2. Office of Director CANTRELL.F 8 Division of Project & Resident Programs 84/01/21 6pp 22655 283 24X Fiche 50-259,84/02/29,8403160162
- 8403160218 Ack receipt of 840209 ltr informing NRC of steps taken to correct violations noted in 1E Inap Repts 50-259/83-40, 50-260/83-40 & 50-296/83-40 LEMIS.R C Division of Project & Resident Programs 84/03/01 PARRIS.H O Tennessee Valley Authority ip 22661 078 24X Fiche 50-259.84/03/01.8403160218
- ---8403160223 Responds to NRC 840111 itr re violations noted in IE Insp Repts 50-259/83-40,50-260/83-40 & 50-296/83-40 Corrective actions radiological emergency pianning program reviewed & areas requiring rev identified MILL9.L M Tennessee Valley Authority 84/02/09 D'REILLY, J P. Region 2. Office of Director App 22661;099 24X Fiche 50-259,84/03/01.8403160218
- --8403160230 Forwards IE Insp Repts 50-259/83-40, 50-260/83-40 & 50-276/83-40 on 831017-21 & 1122 & notice of violation. LEWIS.R C Division of Project & Resident Programs 84/01/11 PARRIS.H 0 Tennessee Valley Authority 2pp. 22661,105 24X Fiche 50-259,84/03/01,8403160218
- --8403160239 Notice of violation from Insp on 831017-21 & 1122.

 ** Region 2, Office of Director. 84/01/11 3pp 22661 107 24%
 Fiche 50-259,84/03/01,8403160218

- --8403160244 IE Insp Repts 30-259/83-40, 50-260/83-40 & 50-296/83-40 on 831017-21 & 1122 Noncompliance noted failure to control documents, properly train emergency personnel in protective action requirements & incorporate protective action DECKER, TR. STODDART, P. G. Region 2, Office of Director JENKINS, G. R. Division of Emergency Preparedness & Moterials Safety 84/01/06 9pp 28661 110 24X Fiche 50-259,84/03/01, 8403160218
- B402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl ORACE.J N Division of GA, Bafeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X fiche 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 94-i6. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fichs 50-000.84/03/02,8402090008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases "
 8Vc liet enc!
 JORDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402070009
- 8403080213 EN-84-007 on 840307 hotice of violation & proposed imposition of civil penalties in amount of \$40,000 to be issued Action based on Failure to control access into vital area dus to guard leaving post ROSANO, R Director's Office, Office of Inspection and Enforcement 84/03/02 1p 22560 021 24X Fiche 50-259.84/03/02.8403080213
- B402090011 IE Info Notice 84-i7, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/05 Consolidate Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403160308 Ack receipt of 840217 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-259/83-56 LEWIS,R C Division of Project & Resident Programs 84/03/05 PARRIB,H G Tennessee Valley Authority ip 22660 085, 24X Fiche 50-259.84/03/05.8403160308
- --8403160318 Responds to NRC 840117 itr re violations noted in IE insp Repts 50-239/83-56,50-260/83-36 t 50-296/83-36 Corrective actions 10% retest sample calculation made for all snubbers within Category/Oroup 3 MILLE, L M Tennessee Valley Authority 84/02/17 O'REILLY, J P Region 2, Office of Director 2pp 22660 086 24X Fiche 50-239,84/03/05,8403160308
- --8403160328 Forwards 1E Insp Repts 50-239/83-56.50-260/83-56 & 50-296/83-56 on 831213-16 & notice of violation LEWIS.R.C Division of Project & Resident Programs 84/01/17 PARRIB.H Q Tennesses Valley Authority 2pp 22660 088 24X Fiche 50-259,84/03/05,8403160308
- --8403160339 IE Insp Repts 50-259/83-56, 50-260/83-56 & 50-296/83-56 on 831213-16 Violation noted failure to test add1 10% sample for each snubber that failed functional test HHITENER, H. L. Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 84/01/10 8pp 22660 091 24X Fiche, 50-259, 84/03/05, 8403160308
- B403290237 Forwards IE Insp Repts 50-259/84-05, 50-260/84-05 & 50-296/84-05 on B40130-0201 No violations or deviations identified VERRELLI, D M Division of Project & Resident Programs 84/03/05 PARRIS, H. Q Tennessee Valley Authority 2pp 22800-227 24X Fiche: 50-259, 84/03/05, 8403290237
- --8403290239 IE Inap Repts 50-259/84-05, 50-260/84-05 & 50-296/84-05 on 840130-0201, No violations or deviations identified Major areas inspected followup of 1E Bolletin Bi-03, review of LERs re bulletin & procedures for flow reverification tests CUNNINOHAM, A L Region 2, Office of Director MONTGOMERY, D M Division of Engineering & Operational Programs 84/03/02 5pp 20800 231 24X Fiche 50-259,84/03/05,8403290237
- B402070024 IE Info Notice B4-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Bvc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07. Consolidated Edison Co of New York, Inc. 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402070024
- B40207002B IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys." Svc list ancl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103), 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028

- 8403160273 Forwards IE Enforcement Conference Repts 50-259/84-06, 50-260/84-06 & 50-296/84-06 on 840224 .
 D'REILLY, J P Region 2, Office of Director 84/03/08 PARRIS, H & Tennesses Valley Authority 2pp 22661 004 24X Fiche 50-259, 84/03/08, 8403160273
- --84031602B2 IE Enforcement Conference Repts 50-259/84-06.50-260/84-06 & 50-296/84-06 on B40224 Major items discussed bypassing rod sequence control sys while shutting down & isolation of drywell to peal pressure instrument
 BUTCHER, R C Region 2, Office of Director CANTRELL, F S
 Division of Project & Resident Programs 84/02/29 4pp
 28661 006 24X Fiche 50-259.84/03/08.8403160273
- B402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYDUNG.R C Director's Office, Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8403190136 Ack receipt of 840221 & 0312 itre informing NRC of steps taken to correct violations noted in IE insp Repts 50-289/83-59, 50-260/83-59 & 50-296/83-59 Responses meet 10CFR2 201 requirements

 LEWIG.R C Division of Project & Resident Programs 84/03/14 PARRIS, H 0 Tennessee Valley Authority 1p 22670 314 24X Fiche 30-259,84/03/14,8403190136
- --8403190149 Supple response to NRC 840120 itr re violations noted in IE
 Insp Repts 80-259/83-59.50-260/83-59 & 50-296/83-59
 Responses withheld (ref 10CFR73 21)
 MILLS, L M Tennessee Valley Authority 84/03/12 D'REILLY, J P
 Region 2. Office of Director 1p 22670 315 24X
 Fichs 50-259,84/03/14,8403190136
- --8403170161 Responds to NRC 840120 itr re violations noted in IE Insp Repts 30-257/83-59, 50-240/83-59 & 50-296/83-59 Responses withhold (ref 10CFR73 21) MILLS, L M Tennessee Valley Authority 84/02/21 Q'REILLY, J P Region 2, Office of Director 1p 22670 316 24X Fiche 50-259, 84/03/14, 8403190136
- --8403190172 Forwards IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-276/83-59 on 831216 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 73 21) LEWIS, R C Division of Project & Resident Programs 84/01/20 PARRIS, H G Tennessee Valley Authority 2pp 22670 317 24) Fiche 50-259, 84/03/14, 8403190136
- --8403190188 IE Insp Repts 50-289/83-59, 50-260/83-59 & 50-296/83-59 on 631216 Noncompliance noted security force member failed to control access to area Details withheld (ref 10CFR73 21 & 2 793)
 TILLMAN,A . PATTERSON,C Region 2, Office of Director MCQUIRE,D R Division of Emergency Preparadness & Materials Safety 84/01/19 ip 22670 319 24X Fiche 50-259,84/03/14,8403190136
- 8403290047 Summarizes B40312 meeting in Region II ofc to planned util organizational changes & regulatory performance improvement program for facility O'REILLY, JP Region 2. Office of Director 84/03/15 PARRIB, H G Tannessee Valley Authority ip 22806 271 24X Fiche 50-259,84/03/15,8403290047
- --8403290183 Suppls response to NRC 840117 ltr re violations noted in IE insp Repts 50-297/83-38, 50-260/83-38 & 50-296/83-38 & 50-296/83-38 Corrective actions distribution of insp rept to health physics personnel initiated MILLS.L M Tennessee Valley Authority 84/02/17 0'REILLY.J PRegion 2, Office of Director 2pp 22800 279 24X Fichs 50-259,84/03/20,8403290178
- --8403270170 Ack receipt of 831207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-257/83-38, 50-260/83-38 & 50-276/83-38 O'REILLY, J P Region 2, Office of Director 84/01/19 PARRIE, H 0 Tennessee Valley Authority 2pp 22800 281 24X Fiche 50-257,84/03/20,8403270178
- --8403290203 Ack receipt of 831209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-259/83-38, 50-296/83-38
 LEWIS,R C Division of Project & Resident Programs 83/12/21
 PARRIS.H O Tennessee Valley Authority 1p 22600 283 24x
 Fiche 50-259,84/03/20,8403290178

- --8403270207 Responds to NRC 831107)tr re violations noted in IE Insp Repts 50-259/83-38, 50-260/83-38 & 50-296/83-38 Corrective actions ansp rept distributed to health physics personne) & RCI-5 revised to incorporate 10CFR47 changes MILLS.L M Tennessee Valley Authority 83/12/07 D'REILLY.J P Region 2, Office of Director 5pp 22800 284 24X Fishe 50-259,84/03/20,8403290178
- --8403270211 Forwards IE Insp Repts 50-259/83-38.50-260/83-38 & 50-276/83-38 on 830912-16 & notice of violation LEWIS.R C Division of Project & Resident Programs 83/11/07 PARRIS.H O Tennessee Valley Authority 2pp 22800 289 24X Fiche 50-239.84/03/20.8403270178
- --8403290214 Notice of violation from insp on 830912-16 * Region 2, Office of Director 83/11/09 2pp 22800 291 24X Fiche 50-259,84/03/20,8403290178
- --8403290220 IE Insp Repts 50-259/B3-38, 50-260/B3-38 & 50-296/B3-38 on B3D912-16 Violations noted 55-gallon drum reading 30 to 65 millires per hour observed unlabeled & radiation control procedures not prepared or adhered to DEBS.B T Region 2. Office of Director BARR.K P Division of Engineering & Operational Programs B3/11/03 6pp 22800 293 24X Fiche 50-259.84/03/20.8403290178
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, R. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fichs 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svr List ent! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402070044
- R Periodic operating reports & related correspondence
- 8403020103 Monthly operating repts for Jan 1984 W/840210 ltr CHAPMAN.M., THOM.T., JONES.O.T. Tennessee Valley Authority 84/01/31 41pp 22443 166 24% Fiche 50-259.84/01/31.8403020103
- 8403300133 Forwards monthly operating repts for Feb 1984 & corrected Jan 1984 monthly operating rept for Unit 1
 JONES G T Tennessee Valley Authority 84/03/09 Office of Resource Management, Director 1p 22820 203 24X
 Fiche 30-259.84/03/09.8403300133
- --8403300136 Monthly operating repts for Feb 1984 THOM, T Tennessee Valley Authority 84/02/29 37pp 22820 204 24X Fiche 50-259,84/03/09,8403300133
- S Reportable occurrences, LERs & related correspondence
- B403050051 Notification of 840307 meeting w/util in Chattanoga,TN to discuss design of analog trip sys in light of transmitter failures in Unit i
 CLARK.R J Operating Reactors Branch 2 84/02/28 VASSALLO,D E
 Operating Reactors Branch 2 1p 22527 31B 24x
 Fiche 50-276.84/02/28.8403050051
- 8403260293 Forwards summary list of deficiencies identified per 10CFR50 55(e),Part 21 & potential generic ltr repts for comments

 BYAROSTECKI.R Division of Project & Resident Programs Region 1. Office of Director 7pp 22756 065 24X

 Fiche 50-000.84/02/28.8403260233
- B403200087 LER B4-004-00 on B40228,RHR outboard Loop II isolation valve steam found broten Probably caused by overstress or extreme load Limitorque.Limitorque switches & valve discs investigated W/B40314 ltr Followup rept by 840615 HALKER, J B JONES, C T Tennessee Valley Authority B4/03/14 2pp 22697 092 24X Fishe 50-296.84/03/14.8403200087
- V Operator Examinations
- 8403160227 Confirms 840302 meeting in Atlanta, GA re 840317 operator requalification exam.per 840227 telcon
 LEWIG.R C Division of Project & Resident Programs 84/03/01
 PARRIS.H G Tennessee Valley Authority 1p 22660 328 24X
 Fiche 50-257,84/03/01.8403160227

- B403290322 Discusses B40117 itr confirming arrangements for administration of requalification exams Random selection process used to determine identify uf examinees for written & oral exams List of examinees encl
 LEWIS.R C Division of Project & Resident Programs 84/03/13
 PARRIS.H G Tennessee Valley Authority 3pp 22802 049 24X
 Fichs 50-259.84/03/13.8403290322
- 8403290213 Summarizes 840302 meeting w/util re 840323 requalification exam of licensed operator & senior operator personnel at facilities Meeting provided better understanding of operator requalification training & exam programs

 LEMIS.R C Division of Project & Resident Programs 84/03/15

 PARRIS.H O Tennessee Valley Authority 3pp 22800 340 24X

 Fiche 50-259.84/03/15.8403290213
- DOCKET 50-298 COOPER NUCLEAR STATION
- F Security, medical, emergency & fire protection plans
- 8403050141 Provides scenario for submittal of proposed emergency preparedness info,per NRC 820114 ltr & 800817 revised emergency planning rule COLLINS,J T Region 4. Office of Director 84/02/09 PILANT,J M Nebraska Public Power District 2pp 22487 306 24X Fiche 30-278.84/02/09.8403050141
- 8403060471 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per B10709 Generic Ltr B1-27, W/o request.entire plan will be placed in FDR VASSALLO.D B Operating Reactors Branch 2 84/02/10 FILANT.J M Nebraska Public Power District 2pp 22549 324 24X Fiche 50-298.84/02/10.8403060471
- 8403060346 Forwards emergency plan implementing procedures, including Rev 2 to 5 7 5, "General Emergency Implementing Procedure," Rev 3 to 5 7 13, "Personnel Monitoring & Decontamination" & Rev 3 to 5 7 13, "Rescue & Reentry " M/o enc! PILANT, J M Nebraska Public Power District 84/02/13 COLLING, J T Region 4, Office of Director 1 22518 223 24X Fiche 50-298,84/02/13,8403060346
- B403260235 Forwards 1E Insp Rept 50-298/83-28 on B31018-21 & notice of violation JOHNBON.E H Region 4, Office of Director 84/02/17 PILANT, J M Nabraska Public Power District 2pp 22755 158 24X Fiche 50-298.84/02/17.8403260235
- --8403260238 Notice of violation from insp on 831018-21 * Region 4, Office of Director 84/02/17 2pp 22755 160 24X Fiche 50-298,84/02/17,8403260235
- --B403260240 IE Imap Rept 50-298/83-28 on 831018-21 Violation noted licensee presented no evidence that physician assistant trained to identify aberrant behavior Details withheld (ref 10CFR73 21)
 CALDWELL:R A , KELLY, J A F , HUNNICUTT, D M Region 4, Defice of Director 84/02/17 1p 22755 162 24X Fiche 50-298,84/02/17,8403260235
- 8403060239 Forwards Rev 3 to Emergency Plan Implementing Procedures 5 7 3, "Alert Implementing Procedure," 5 7 8. "Activation of OSCs" & 5 7 12, "Emergency Rediation Exposure Control " W/o encis PILANT, J M Nebraske Public Power District 84/02/21 COLLINS, J T Region 4, Office of Director 1p 22517 313 24X Fichs 50-298/84/02/21.8403060239
- 8403140252 Forwards order confirming licensee 830415,0711 & 28 & 1230 commitments to comply w/Bupp1 1 to NUREG-0737 re emergency response capability VASSALLO,D D Operating Reactors Branch 2 84/02/22 PILANT, J M Nebraska Public Power District 2pp 22636 332 24X Fichs 50-298,84/02/22,8403140252
- --B403140255 Order confirming licensue commitments to comply w/Buppl 1 to NUREO-0737 (Genetic Ltr B2-33) re emergency response capability EIBENHUT.D o Division of Licensing 84/02/22 Nebraska Public Power District 6pp. 22636;334. 24X Fiche 50-298.84/02/22, 8403140252
- B403090100 Application for amend to License DPR-16.changing Tech Specs re fire detection instruments to comply w/NUREQ-0737 (Generic Ltr 83-36).Items II 8 i.IJ B 3.II F 1 & II D 3.4 KUNCL.L 0 Nebraska Public Power District 84/02/29 VASSALLO, D B Operating Reactors Branch 2 6pp 22571 116, 24X Fiche 50-298.84/02/27.8403090100

- --8403070116 Proposed radiplogical Tech Specs per NUREG-0737 (Generic Ltr 83-36) re fire detection instrumentation
 **Nebraska Public Power District 84/02/29 16pp 22571 122
 24X Fiche 50-278.84/02/29,8403070100
- 8403170087 Revised emergency plan implementing procedures, including Procedure 5 7 16 re release rate determination 5 7 17 re dose assessment 5 7 19 re onsite radiological monitoring W/840314 1tr
 THOMASON, P V , PILANT, J M Nebraska Public Power District 84/02/27 COLLINS, J T. Region 4, Office of Director 72pp 2266 227 24X Fiche 50~278.84/02/27,8403170087
- 8403060264 Forwards "Program Pian for Detailed Control Room Design Review." including proposed schedule for implementation, per NUREG-0737, Buppi I requirements PILANT, J M Nebraska Public Power District B4/03/01 EIBENHUT. D O Division of Licensing 1p 22515 225 24X Fiche 30-298, 84/03/01.8403060264
- --8403060274 "Program Plan for Detailed Control Room Design Review "
 * Nebraska Public Power District 84/02/29 65pp 22515 226
 24X Fiche 50-298,84/03/01.8403060264
- 8403060354 Forwards descriptions of Reg Quide 1 97 requirements & schedule for implementation of emergency response capability, per NUREO-0737, Buppl 1
 PILANT, J. M. Nebraska Public Power District 84/03/01
 EIBENHUT. D. Q Division of Licensing 19pp 82515 311 24X
 Fiche, 50-298.84/03/01,8403060354
- 8403080265 Forwards three repts re facility safety parameter display sys (8PDS), per requirements of Euppl 1 to NUREG-0737 BPDS will be installed during upcoming recirculation piping replacement outage PILANT, J M Nebraska Public Power District 84/03/01 EISENHUT. D. O Division of Licensing 2pp 22558 050 24X Fiche 50-298, 84/03/01, 8403080265
- --8403080268 "Bafety Parameter Display Bys Bafety Analysis "
 LOBNER, P 8cience Applications, Inc 503-8500000-76 84/03/01
 72pp. 22558-052 24X Fiche 50-298.84/03/01.8403080265
- --8403080273 Procedure 503-8500000-51, "Verification & Validation Plan"
 THOMAS, N Science Applications, Inc 84/03/01 67pp 22558 i25
 24X Fiche 50-298,84/03/01,8403080265
- --8403080306 Procedure 503-8500000-27, "Safety Parameter Display Sys Implementation Flan" LUBNER,P Science Applications, Inc 84/03/01 30pp 22558 193 24X Fiche, 50-278, 84/03/01, 8403080265
- 8403200167 Forwards Rev 5 to safeguards plan Rev withheld (ref 10CFR73 21 & 2 790) PILANT, J M Nebraska Public Power District 84/03/14 Record Services Branch (Document Control Desk). 1p 22696 354 24X Fiche, 50-298, 84/03/14, 8403200167
- 8403220055 Forwards revs to emergency plan implementing procedures, including Rev 5 to Procedure 5 7 id re release rate determination. Rev 5 to 5 7 i7 re dose assessment. Rev 0 to 5 7.17 & Rev 3 to 5 7 i9 re monitoring W/o encl PILANT, J M Nebraska Public Power District 84703/14 COLLINS, J T Region 4, Office of Director 1p 22713 358 24X Fiche, 50-278, 84/03/14, 8403220055
- 8403270013 Revised Emergency Plan Implementing Procedures EPIP 5 7 6, "Notification," EPIP 5, 7, 20, "Protective Action Guides" & EPIP 5, 7, 21, "Emergency Equipment Inventory " W/840322 ltr WHITMAN,D., WINDHAM,R., PILANT,J.M Nebraska Public Power District 84/03/15, COLLING,J.T Region 4, Office of Director 60pp 22766:028 24% Fiche 50-298,84/03/15,8403270013.
- 8403220031 Ack receipt of 831205 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-278/83-27 JOHNSON, E. H. Region 4. Office of Director 84/03/19 PILANT, J M Nebraska Public Power District 1p 22712 321 24X Ficha. 50-298, 84/03/19, 8403220031.
- --B403220042 Responds to NRC B3110B ltr re violations noted in IE Insp Rept 50-298/B3-27. Corrective actions adequacy of interfaces W/state & local govts on emergency preparedness will receive add1 attention PILANT, J M Nebraska Public Power District. 83/12/05 JOHNBON, E H. Region 4. Office of Director 3pp. 22712 322 24X Ficher 50-298, 84/03/17, 8403220031

- P Operating license stage documents & correspondence
- 8403140340 Summary of 831215 meeting w/GE & Mark I Dwners Group in Bethesda.MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL.B L Operating Reactors Branch 2 84/02/21 Operating Reactors Br
- 8403090100 Application for amend to License DPR-16, changing Tech Specs re fire detection instruments to comply w/NUREG-0737 (Generic Ltr 83-36). Items II B 1. II B 3, II F 1 & II D 3 4 KUNCL, L G Nebraska Public Power District 84/02/29 VASSALLO.D B Operating Reactors Branch 2 &pp 22571 116 24X Fiche 50-298,84/02/29.8403090100
- --8403070iió Proposed radiological Tech Specs per NUREG-0737 (Generic Ltr 83-36) re fire detection instrumentation * Nebraska Public Power District 84/02/27 16pp 22371 i22 24% Fichs 30-298.84/02/29.8403090i00
- 8403120270 Requests remittal of addl fee for review of 840118 application for Tech Spec change re standby gas treatment & auxiliary electric sys, core & containment cooling sys & torus temp monitoring sys
 DIGOS.R M License Fee Management Branch 84/03/01 PILANT, J M Nebraska Public Power District ip 22615 362 24X
 Fichs.50-278.84/03/01.8403120290
- 8403i50168 Application for amend to License DPR-46, consisting of Proposed Change 7 to radiological efficient Tech Specs W/
 "Offsite Dose Assessment Manual for Assessment of Gaseous & Liquid Efficients" No fee required PILANT, J M Nebraska Public Power District 84/03/07 VASSALLO, D B Operating Reactors Branch 2 ip 22642 074 24X Fiche 50-298, 84/03/07, 8403i50168
- --8403150171 Proposed Change 7 to radiological effluent Tech Bpecs * Nebraska Public Power District B4/03/07 72pp 22642 075 24X Fiche 50-278,84/03/07,8403150168
- --B403150173 "Offsite Dose Assessment Manual for Assessment of Oaseous & Liquid Effluents "

 * Nebraska Public Power District 84/01/31 125pp 22642 166 24X Ficha 50-298,84/03/07,8403150168
- 8403200254 Forwards Class IV fee per 840301 ltr PILANT, J M Nebraska Public Power District 84/03/13 DI00S, R M License Fee Management Branch ip 22691 107 24X Fiche 50-298, 84/03/13, 8403200254
- 8403:50275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc list encl EISENHUT, D & Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 334 24X Fiche 50-000.84/03/14.8403i50275
- O Inspection reports. IE Bulletins & correspondence
- 8403260235 Forwards lE Insp Rept 50-298/83-28 on 831018-21 & notice of violation JOHN80N.E H Region 4, Office of Director 84/02/17 PILANT, J M Nebraska Public Power District 2pp 22755 158 24X Fiche 50-298,84/02/17,8403260235
- --8403260238 Naticm of violation from insp on 831018-21 * Region 4, Office of Director 84/02/17 2pp 22755 160 24X Fiche 50-298,84/02/17,8403260235
- --8403260240 IE insp Rept 50-298/83-28 on 831018-21 Violation noted licensee presented no evidence that physician assistant trained to identify aberrant behavior Details withheld (ref 100FR79 21).

 CALDHELLAR A, KELLY, J A F, HUNNICUTT, D H Region 4, Diffice of Director 84/02/17 ip 22755 162 24X Fiche 50-278, 84/02/17, 8403260235
- 8403030091 Ack receipt of 840110 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-278/83-25 JDHN80N.E H Region 4, Office of Director. 84/02/24 PILANT, J M Nebraska Public Power District. 1p 22488 059 24X Fiche. 50-278.84/02/24.8403050091
- --B403050095 Responds to NRC B3120B ltr re violations noted in IE Insp Rept 50-298/83-25 Corrective actions responsibilities for transcribing & forwarding safety review & audit board minutes transferred to individual w/ewer duties PILANT.J M Nebraska Public Power District B4/01/10 JOHNBON,E H Region 4, Office of Director 5pp 2248B 060 24X Fiche 50-278,84/02/24,8403050091

- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl
 - enci JORDAN,E L Division of Emergency Preparedness & Enginesring Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp. 22709 239 24X Fiche 50-000,84/02/28,8401190072
- B403060392 Forwards "Inservice Insp Plan for ASME Class 1,2 & 3 Components," per B31216 commitment PILANT, J M Nebraska Public Power District 84/03/01 VASBALCO, D.B Operating Reactors Branch 2 ip. 22518 134. 24X Fiche 50-298,84/03/01,8403060392
- --8403060373 "Inservice Insp Pian for ASME Class 1,2 & 3 Components "

 * General Electric Co 84/03/01 15pp 22518 135 24X
 Fishe 50-278,84/03/01,8403060392
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02,8402090007
- 8402090008 iE Info Notice 84-ib. "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list and JORDAN E L Division of Emergency Preparedness & Engineering Reponse (Post 830103) 84/03/02 Consolidated Edison Co of New York Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8403090009 iE Info Notice 84-15, "Reporting of Radiological Releases "
 Svc list enct
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidates Edison Co of New
 York, Inc. (19pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 84020900ii iE Info Notics 84-17, "Problems W/Liquid Nitrogen Coaling Components Below Nil Ductility Temp " Svc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York Inc 117pp 22553 336 24X Fiche: 50-000.84/03/05.8402090011
- 8403130307 Provides results of comparative analysis of liquid upknown sample performed by Radiological & Environ Sciences Lab in connection w/NRC confirmatory measurements insp in Oct 1983 JOHNSON, E. H. Region 4, Office of Director 84/03/06 PILANT, J. M. Nabraska Public Power District 3pp 22608 036 24x Fiche 50-298.84/03/06.8403130307
- 8402090024 IE Info Notice 84-09. Rev i, "Lessons Learnsd From ineps of Firs Protection Safe Shutdown 83s " Svc list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 047 24X Fiche 50-000,84/03/07,8402070024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consultated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000.84/03/07.8402090028
- 8402090031 IE Bulletin 84-02. "Failures of CE Typs HFA Relays in Use in Class IE Safety Sys " Svc list enc!

 DEYOUND.R C Director's Office, Office of Inspection and Enforcement #4703/12 Consolidated Edison Co of New York, inc 134pp 22823 094 24% Fiche 50-000.84/03/12.8402090031
- 8403160255 Ack receipt of 840118 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-298/83-31 JOHNSON,E H Region 4, Office of Director 84/03/12 PILANT, J M Nebraska Public Power District ip 22660 327 24X Fiche 50-298,84/03/12,8403160255
- --8403160260 Responds to NRC 831223 ltr re violations noted in IE Insp Rspt 50-2781/83-31 Corrective actions operations supervisor required to meet every wk w/crew in training to discuss reactor operation PILANT.J M Nebraska Public Power District 84/01/18 JOHNSON, E Region 4. Office of Director 4pp 22660:330 24X Ficha 30-298,84/03/12,8403160255
- 8403220031 Ack receipt of 831205 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-298/83-27 JOHNBON, E H Region 4, Office of Director 84/03/19 PILANT, J M Nebreska Public Power District 1p. 22712 321 24X Fiche 50-298,84/03/19,8403220031

- --B403220042 Responds to NRC 831108 ltr re violations noted in IE Insp Rept 50-298/83-27 Corrective actions adequacy of interfaces w/state & local govts on emergency preparadness will receive add1 attention PILANT.J M Nebrasta Public Power District 83/12/05 JOHNSON,E H Region 4, Office of Director 3pp 22712 322 24X Fichs 50-298,84/03/19,8403220031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavitiss" Svc list enci JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/03/21 Consolidated Edison Co of Naw York, Inc 123pp 22823 229 24% Fiche 50-000,64/03/21,8402090043
- B402070044 IE info Notice 84-20. "Bvc Life of Relays in Safety-Related Bys " Bvc list snc1 JURDANAE L Division of Emsrgency Preparedness & Engineering Response (Post 630103) 84/03/21 Consolidated Edison Co of New York, inc 135pb 22733 001 24X Fiche 50-000.84/03/21,8402070044
- R Psriodic operating reports & related correspondence
- 8403020083 Monthly operating rept for Jan 1984 W/840207 ltm BALLINGER.P L . THOMASON,P V Nebrasta Public Power District 84/01/31 5pp 22441 211 24X Fichs 50-298,84/01/31.84030R0083
- B Reportable occurrences, LERs & related correspondence
- B310280186 Forwards Safety Engineering Evaluation AEOD/E319, "Loss of Drywell-Torus Pressure Differential During RHR Pump Fiow Tasting at Cooper Nuclear Station "Licensee corrective actions adsquate RUBIN-8 D Reactor Operations Analysis Branch 83/09/08 SEYFRIT.K V Reactor Operations Analysis Branch ip 22775 205 24X Fiche 50-278.83/09/08,8310280186
- --8310280188 "Lose of Drywell-Torus Pressure Differential During RHR Pump Flow Testing of Cooper Nuclear Btation " RUBIN.8 Director's Office 83/09/08 17pp 22775 206 24X Fichs 50-278,83/09/08,8310280186
- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2
- B401190072 IE Info Notics 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/28 Consolidated Edison Co. of New York. Inc. 113pp. 22909 239 24X Fiche 30-000-84/02/28, 8401190072.
- F Security, medical, emergency & fire protection plans
- 8403050208 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licenser, per 810709 Generic Ltr 81-27 W/o request entire plan will be placed in PRR MILLER, J R Operating Reactors Branch 3 84/02/16, FAY, C W Wisconsin Electric Power Co 2pp 22528 152 24X Fiche 50-266,84/02/16,8403050208
- B403120045 Notifies of B40323 workshop on fire protection safe shutdown requirements of iOCFR50. App R in Rosemont, IL to discuss IE Info Notice 84-09 & provide add shutdown analyses &/or mad guidance Agenda enci EFEBBARD. R i. Division of Emergency Preparedness & Operational Support B4/03/06 BURSTEIN/S Wisconsin Electric Power Co Spp 22570 294 24X Fiche 50-266,84/03/06,8403120045
- 840316080 Submits addl info on Generic Ltr 82-33 schedule requirements for emergency response capabilities Vandor of new computer sys requested 1-yr delay to June 1985 for delivery, affecting schedular commitments made to NRC FAY.C W Hisconsin Electric Power Co 84/03/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp. 22652 327. 24X Fiche 50-266,84/03/08,8403160080
- 8403220093 Ack receipt of 840306 ltr informing NRC of corrective actions re deviation from commitment & resolution of revised emergency plan SER clarification items noted in IE Insp Repts 50-266/63-22 & 50-301/63-25 PAPERIELLO.C J Region 3, Office of Director 84/03/19. BURSTEIN.S Misconsin Electric Power Co. 1p. 22716-324, 24X Ficha 50-266.84/03/19.8403220093

--B403220099 Responds to NRC 840202 itr forwarding revised emergency plan SER & request for clarification of listed items & deviation from commitment Corrective actions Procedure EP 5 0.
"Organizational Control of Emergencies," revised FAV.C W Wisconein Electric Power Co 84/03/06 KEPPLER.J 0 Region 3. Office of Director 7pp 22716 325 24X Fiche 50-266.84/03/19.8403220093

O. Adjudicatory correspondence

- B402220157 Order extending time until 840228 for Commission to act to review Director's Decision DD-83-14 CHILK.8 J Office of the Secretary of the Commission 84/02/21 Commissioners ip 22337 362 24X Fiche 50-000.84/02/21.
- 8403010238 Order extending time until 840305 for Commission to act to review Director's Decision DD-83-14 & 831029 decision denying request of Environ Policy Inst CHILK, 8 J Office of the Secretary of the Commission 84/02/28 Commissioners ip 22434 210 24X Fiche 50-000,84/02/28,8403010238
- 8403070069 Informs that Commission Unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review sxpired Decision became final agency action on 840305 CHILK, B J Office of the Secretary of the Commission 84/03/08 CELEBREZIE, A J Chio, State of Exp 22575, 350 24x Fiche 50-000, 84/03/08, 8403070069
- 8403090074 Informs that Commission Unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expired Decision became final agency action on 840305 GMILK.8 J Office of the Secretary of the Commission 84/03/08 MILLAR, F Environmental Policy Institute 1p 22575 272 24X Fichs 50-000.84/03/08.8403090074
- 8403090113 Informs of Commission decision not to review Director's Decieion DD-83-14 Time for Commission to act expired on 840305 W/a encl CHILK, B. J. Office of the Secretary of the Commission 84/03/08 RESNIXOFF, M. Sierra Club. ip 22575 079 24X Fiche: 50-000, 84/03/08, 8403090113

P. Operating license stage documents & correspondence

- 8403270002 Final response to FDIA request for four categories of documents, tests, studies & analyses referencing or pertaining to NUREO-0103, "STS for B&W PWR " App A documents encl FELTON, J M Division of Rules and Records 84/01/13 MADDEN.T J Kayer Scholer, Fierman, Hays & Handler 6pp 22816 127 24X Fichs, 50-000, 84/01/13, 8403270002
- --8403270045 Discusses O Reed 730301 ltr to G Arlotto re RCPB leakage detection sys Method for detecting slow departure from normal indications of leakage detection sys provided in util monitoring charts
 PORSELL. Atomic Energy Commission Directorate of Regulatory Standards 73/03/07 WICHHAN-K Atomic Energy Commission 2pp 22816.303 24X Fiche 50-000,84/01/13.8403270002
- --8403270047 Forwards info describing RCS leakage monitoring Related info encl REED, 0 A Wisconsin Electric Power Co 73/03/01 ARLOTTO. 0 Atomic Energy Commission - Directorate of Regulatory Standards 40pp 22817:330, 24% Fiche:50-000,84/01/13.8403270002
- 8403070255 Application for amend to Licenses DPR-24 th DFR-27. Amend incorporates changes to Tech Specs re accident monitoring instrumentation to be installed per NUREO-0797 requirement FAY.C. W. Hisconsin Electric Power Go. 84/02/29 DENTON. H.R. Office of Nuclear Reactor Regulation, Director. MILLER, J.R. Operating Reactors Branch 5 App. 22536:179. 24X Fiche: 50-266, 84/02/29, 8403070255
- ---8403070257 Proposed Tach Specs incorporating changes in accident monitoring instrumentation to be installed per NUREO-0737 requirement # Hisconsin Electric Power Co 84/02/27. 10pp 22536 183 24X Fiche 50-266,84/02/27,8403070255
- 8403060575 Informs that encl notice of consideration of issuance of amend to Litenses DPR-24 & DPR-27 & proposed NBHC datermination & opportunity for hearing sent to Ofc of FR for publication, Amend concerns leak surveillance W/o and COLBURN.T.9 Operating Reactors Branch 3 84/03/01 FAY.C W Wisconsin Electric Power Co. 1p 22552:255 24X Fiche: 50-266,84/03/01,8403040575

- 8403220254 Forwards FR notice of consideration of issuance of amend to Licenses DPR-24 & DPR-27 & proposed NSHC & apportunity for hearing re 831223 application to revise surveillance interval for post-accident recovery sys outside containment COLBURN.T O Operating Reactors Branch 3 84/03/01 FAY.C W Hisconsin Electric Power Co 2pp 22723 325 24X Fiche 50-266.84/03/01.8403220254
- --8403220259 FR notice of consideration of issuance of amend to Licenses DPR-24 & DPR-27 & proposed NSHC & opportunity for hearing re B31223 application to revise surveillance interval for post-accident recovery sys outside containment MILLER, J.R. Operating Reactors Branch 3 84/02/07 8pp 22723 327 24X Fiche 50-246.84/03/01.8403220254
- 8403120137 Advises that due to delays in delivery & installation of auxiliary safety instrumentation panels (ASIPs), installation of six accident monitors addressed in NUREO-0737. Items II F i i through II F I 6 will not be completed by 840630 FAY.C W Wisconsin Electric Power Co 84/03/05 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 Spp 22586 250 24X Fiche 50-266,84/03/05.8403120157
- B403170419 Comments on B40207 ltr modifying B31025 request for amends to Tech Specs re changes in conduct of containment integrated leak test rates No significant hazards consideration discussion required MILLER, J R Operating Reactors Branch 3 84/03/06 FAY, C W Wisconsin Electric Power Co 2pp 22681 344 24X Fiche 50-266,84/03/06,8403190419
- B403210077 Responds to Generic Ltr 84-01 re use of terms important to safety & safety-related Widespread use of terms in NRC regulations considered unresolved Notification of meeting requested FAY.C W Hisconsin Electric Power Co 84/03/15 EISENHUT, D O Division of Licensing TAYLOR, J M Director's Office, Office of Inspection and Enforcement ip 82705 165 24X Fiche, 50-266.84/03/15,8402210077
- 8403220162 Application to amend Licenses DPR-24 & DPR-27, changing Tech Specs to add addi restrictions on heavy loads over spent full pool & making additions & deletions as safety-related snubbars, per IE Bulletin 79-14 & Item II D i FAY.C W Wisconsin Electric Power Co 84/03/16 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, T R. Operating Reactors Branch 3 4pp 22718 057 24X Fiche 50-266,84/03/16.6403220162
- --8403220167 Proposed Tech Specs, adding additions on heavy loads over spont fuel pool, making additions & deletions to list of safety-related snubbers & revising position titles within administrative specs # Wisconsin Electric Power Co 84/03/16, 29pp. 22718 061 24x Fiche 50-266,84/03/16,8403220162
- 8403270078 Responds to request for Tech Spec change to limit amount of overtime worked by plant staff members performing safety—related functions Amend to Tech Specs delayed pending adoption of Commission preposed rule
 FAY.C.W Wisconsin Electric Power Co 84/03/19 DENTON, H.R. Office of Nuclear Reactor Regulation, Director MILLER, J.R. Operating Reactors Branch 3 2pp 22766 339 24X
 Fiche 50-266,84/03/19.8403270098
- Q Inspection reports. IE Bulletins & correspondence
- 8403050223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCS leakage Forwards App C documents Search continuing FELTON, J M Division of Rules and Records 84/02/07 HADDEN, T. J Kaye, Scholer, Fierman, Hays & Handler 3pp 22476 234 24X Fichs 50-000,84/02/07,8403050223
- --B403050256 Notifies that independent measurements of identified & unidentified RCB leak rates for all FWRs in Region III performed per Procedures 617278 & 617288 Insp findings summarized NORELIUS.C E Division of Engineering B2/03/08, JORDAN,E L Division of Engineering & Quality Assurance (Pre 830103) 2ρμ 22476 270 24X Fiche. 30-000, B4/02/07, B403050223
- 8403040151 Forwards JE Insp Repts 50-266/83-21 & 50-301/83-20 on B31011-840111 & mgt meeting on 840104 & notice of violation BPESBARD,R. L. Region 3. Office of Director. 84/02/21, SURETEIN,S Misconsin Electric Power Co. Spp. 22904 182 24X Fiche 50-266/84/02/21,8403040151
- --8403060162 Notice of violation from insp on 831011-840111 SPEBEARD,R L Region 3, Office of Director 84/02/21. App 22306 185 24X Fiche 30-266,84/02/21.8403060151

- --8403060176 IE Insp Repts 30-256/83-21 & 50-301/83-20 on 831011-840111 & mgt meeting on 840104 Viplation noted failure to maintain cleanliness control, provide & follow procedures, control documents & property store records HASSE, R A. CHOULES, N C. JORDAN, M J. Region 3. Office of Director 84/02/13 54pp 22506 191 24X Fiche 30-266.84/02/21. 8403060151
- B403130002 Forwards IE Insp Repts 50-266/83-26 & 50-301/83-24 on 831201-840131 & notice of violation SHAPER: W D Region 3. Office of Director 84/02/22 BURSTEIN: 9 Wisconsin Electric Power Co 2pp 22615 267 24X Fiche 50-266.84/02/22.8403130002
- --8403130011 Notice of violation from insp on 831201-840131 SHAFER.W D Region 3. Office of Director 84/09/22 2pp 22615 269 24X Fiche 50-266.84/02/22,8403130002
- --8403130023 IE Insp Repts 50-266/83-26 & 50-301/83-24 on 831201-840431 Noncompliance noted fire in containment resulted when welding slag lended on acetylene hose attached to acetylene bottle not in use & not moved to safer location HAGUE,R L , FITZPATRICK,B , JACKIN I N Region 3, Office of Director 84/02/21 9pp 22615 271 24X Fiche 50-266.84/02/22, 8403130002
- 8402070007 IE Info Natice 84-i4, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enci ORACE.J N Division of 8A. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York. Inc. 130pp 22552 329 24X Fiche 50-000.84/03/02.8402090007
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Vaives to Operate " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York: Inc 122pp 22553 078 24X Fiche.50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-i3, "Reporting of Radiological Releases" 5vc list enci JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc. ii9pp 22353 217 24X Fiche 50-000,84/03/02,8402090009
- 840209001; IE Info Notice B4-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York. Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8402070024 IR Info Notice B4-09.Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/7 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR
 Sys " Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co of New
 York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Svc list encl DEYOUNO, R C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York
- 8403220093 Act receipt of 840306 itr informing NRC of corrective actions re deviation from commitment & resolution of revised emergency plan SER clarification items noted in IE Insp. Repts 50-266/83-25 & 50-301/83-25
 PAPERIELLO.C J. Region 3, Office of Director 84/03/19
 BURSTEIN.S. Hisconsin Electric Power Co. ip 22716 324 24X
 Fichs 50-266.84/03/19.8403220093
- --8403220099 Responds to NRC 840202 ltr forwarding revised emergency plan SER & request for clarification of listed items & deviation from commitment Corrective actions Procedure EP 5 0, "Organizational Control of Emergencies:" revised, FAY,C W Wisconsin Electric Power Co 84/03/06 KEPPLER,J Q, PAPERIELLO,C J Region 3, Office of Director 9pp 22716,325 24% Fiche 50-266,84/03/19,8403220093
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into FUR Reactor Cavities " Svc list ancl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). B4/03/21 Consolidated Edison Co of Naw York Inc 123pp 22823 229 24% Fiche 30~000,84/03/21,8402090043

- 8402070044 IE info Notice 84-20, "Byc Life of Relays in Safety-Related Sys " 8vc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- R Pariodic operating reports & related correspondence
- 8403060338 "Bemiannual Monitoring Rept.Jui-Dec 1983" W/840229 1tr FAY, C W Misconsin Electric Power Co 83/12/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 18pp 22517 026 24% Fiche 30-264, 83/12/31, 8403060358
- B4031200&6 "Annual Results & Data Rept.1983 " W/840301 ltr FAY,C W Misconsin Electric Power Co B3/12/31 KEPPLER.J G Region 3, Office of Director 59pp 22591 070 24X Fiche 50-266.83/12/31.8403120066
- B403140139 Monthly operating repts for Feb 1984 W/840308 ltr FAY,C W Misconsin Electric Power Co 84/02/27 lipp 22620,252 24X Fiths 50-266,84/02/29,8403140139
- 8 Reportable occurrences. LERs & related correspondence
- 8403230068 LER B4-001-00 on B40223;pipe snubber ID 2HS-M75 removed for NUREO-0737 mod prior to obtaining Tech Spec change allowing removal Snubber reinstatiod within 72 h Tech Spec change to delete snubber initiated W/B40315 ltr FAY.C W Wisconsin Electric Power Co B4/03/15. KEPPLER: J Q. Region 3. Office of Director. 3pp 22726 324 24X Fiche 50-301.84/03/15.8403230068
- DOCKET 50-302 CRYBTAL RIVER NUCLEAR PLANT, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8403120354 Forwards order confirming licenses commitments to implement post-TMI-related items set forth in Suppl i to NUREO-0737. "Requirements for Emergency Response Cepability " Order based on util responses to 821213 Generic Ltm 82-33 STOLZ.J F Operating Reactors Branch 4 84/02/21 HILGUB, # 8 Florida Power Corp 3pp 22615 329 24X Fiche 50-302,84/02/21, 8403120354
- --8403120359 Order confirming licenses commitments on emergency response capability.per Suppl 1 to NUREO-0737 EIBENHUT, D 0 Division of Licensing 84/02/21 Florida Power Corp 6pp 22615 332 24X Fiche 50-302.84/02/21,8403120354
- B403Di0072 Forwards modified amended security plansRev 4 Rev withheld (ref 10CFR73 21)
 WEBTAFER, G R Florida Power Corp B4/02/23 DENTON, H R Office of Nuclear Reactor Regulation. Director 3pp 22436 iii 24x
 Ficho. 50-302
- 8403290262 Forwards IE Insp Rept 50-302/64-04 on 840206-07 No violations or deviations noted DANCE, H C Division of Project & Resident Programs, 84/03/0 HILOUS, W S Florids Power Corp Rpp 22800 169 24X Fiche 50-302,84/03/01,8403290262
- --8403270266 IE Insp Rept 50-302/84-04 on 840206-07. No violations or deviations noted Major areas inspected amergency preparedness protective action recommundations HUFFHAN.O N Region 2. Diffice of Director JENKINB.O.R Division of Emergency Preparedness & Materials Bafety 64/02/27 App 22800 i71 24X Fiche 50-302,84/03/01,8403290262
- B403160285 Notifies of B40316 workshop to discuss 10CFR50, App R requirements & results of insps to resolve misunderstandings re fire protection, Attendees should be limited to six due to conference room size

 LEWIS, RC Division of Project & Resident Programs 84/03/02 WILGUS, W B Florida Power Corp ip 22660 272 24x

 Fichs 50-302.84/03/02.8403160285
- 8403160334 Ack receipt of 840209 ltr re emergency exercise scheduled during Apr 1984
 DANCE, H C Division of Project & Resident Progrems 84/03/02 WILCUS N 8 Florida Power Corp 2pp 22660,027 24X
 Ficha 50-302,84/03/02,8403160334
- 8403160335 Forwards IE Safeguards Insp Rept 50-302/84-05 on 840213-17 & notice of violation Notice of violation withheld (ref 100FR2, 790)
 LEWIS, R C Division of Project & Resident Programs 84/03/08
 Fiorida Power Corp. 2pp 22659 162 24X Fiche: 50-302, 84/03/08, 8403160335

- --8403160388 IE Bafeguards Insp Rept 50-302/84-05 on 840213-17 Violations noted Details withheld (ref 10CFR2 790 & 73 21)
 HALL, B L Region 2, Office of Director MCGUIRE, D R Division of Emergency Preparadness & Materials Safety 84/03/02 ip 22659 164 24X Fiche 50-302,84/03/08,8403160335
- 8403130033 Ack receipt of 840123 ltr forwarding Rev 2 to physical security plan Changes consistent w/provisions of 10CFR50 54(p) & acceptable LEWIS.R.C Division of Project & Resident Programs 84/03/09 WILQUS.W B Florida Power Corp 3pp 22614 324 24X Fiche 50-302.84/03/09.8403130033

H General correspondence

- 8403280149 Responds to 840208 ltr requesting assistance in responding to J Paskavitch ltr requesting latest EI8 on concentrations of Sr-90.0s-137 & I-131 near plants Two annual repts encl W/o repts
 DIRCKS.W J. Office of the Executive Director for Operations
 84/03/07 CHILES.L Senate 4pp 22809 316 24X
 Fiche 50-000.84/03/07.8403280149
- --8403280136 Forwards constituent J Paskavitch ltr requesting latest EIS on concentrations of Sr-90,Cs-137 & I-131 near plants Comments & views requested CHILEGIL Senate 84/02/08 KAMMERER,C Office of Congressional Affairs 8pp 22809 320 24X Fiche 50-000,84/03/07,8403280149

J Insurance & indemnity information

8403040353 Forwards Endorsement 63 to NELIA Policy NF-175 DUCK-J.R. Marsh & McLennan, Inc 84/02/28 SALTZMAN,J Assistant Director for State & Licensee Relations 2pp 22519 071 24X Fiche 50-302,84/02/28,8403060353

P Operating license stage documents & correspondence

- B402060419 Application for amend to License DPR-72 consisting of Tech Bpec Change Request ii2 revising restrictions on steam generator operating level to be based on inventory instead of operating level alone MESTAFER, O.R. Florida Power Corp. 84/01/30 DENTON, H.R. Dffice of Nuclear Reactor Regulation, Director 5pp. 22085 141 24X Fiche: 50-302.84/01/30.8402060419
- --8402060421 Proposed Tech Specs re steam generator operating levels # Florida Power Corp 84/01/30 14pp 22085 146 24X Fiche 50-302,84/01/30,8402060419
- B403040359 Application for amend to License DPR-72.changing Tech Specs to allow increase in enrichment of fuel assemblies from 3 3 weight percent to 3 5 weight percent U-235 WESTAFER, O. R. Fiorida Power Corp. B4/02/24 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 5pp 225i1, 208 24X Fiche: 50-302, 84/02/24, 8403040359
- --8403060362 Proposed Tech Specs allowing increase in enrichment of fuel assemblies from 3 3 weight percent to 3.5 weight percent U-235 NBHC determination enci # Florida Power Corp. 84/02/24 3pp 22511 2i3 24X Fiche 50-302
- ---B403060366 "Criticality Bafaty Analysis of Crystal River Spent Fuel Storage Rack " TURNER, S. E., QURLEY, M.K., Florida Power Corp. 88-152 83/12/31 19pp 22511:216 24X Fiche:50-302,84/02/24,8403060359
- 8403060364 Revised application for amend to License DPR-72, changing Tach Specs to reflect addition of two independent, in-place hydrogen monitors. Certificate of Bvc encl. WESTAFER, O.R. Florida Power Corp 84/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director App 22511 297 24X Fiche: 50-302, 84/02/24, 8403060364
- --B403060368 Proposed Tech Specs reflecting addition of two independent, in-place hydrogen monitors, in response to NUREO-0737, Item II F 1.

 * Florida Power Corp. B4/02/24 Ppp 22511 303 24X Fiche 50-302.84/02/24,8403060364
- 8403040343 Submits add1 info re emergency feedwater sys program Gilbert Assoc hired to investigate emergency feedwater turbine concern. Detailed rept will be available by 840430 WESTAFER, G R Florida Power Corp 84/02/29 BTOLZ, J F Operating Reactors Branch 4 2pp 22519 080 24% Fiche 50-302, 84/02/29, 8403040343

- B403i60231 Summarizes 8402i4 mgt meeting w/util in Atlanta, GA re mgt activities & future plans Meeting beneficial Attendance list encl LEMIG.R C Division of Project & Resident Programs 84/02/29 WILQUS.W S Florida Power Corp 3pg 22660 325 24X Fiche 50-302,84/02/29,840316023i
- 8403120130 Comments on NUREO-0737. Item II II 1, "RC8 Vents " 8ix listed items completed, per 830903 SER RC8 vent sus solenoid valves not susceptible to common mode failure No corrective action necessary
 WESTAFER, 0 R Finrida Power Corp 84/03/07 STCLZ, JF Operating Reactors Branch 4 Opp 22588 202 24X Fiche 50-302,84/03/07,8403120130
- B403190427 Notification of B40405 meeting w/util & General Physics Corp in Bethesda.MD to discuss NRC B40207 comments on control room design review program plan Agenda wncl HERNAN.R Operating Reactors Branch 4 84/03/09 STOLZ, J F Operating Reactors Branch 4 3pp 22681 32B 24X Fiche 30-302,84/03/09,8403190427
- 8403160315 Application to amend License DPR-42, proposing supply power to circuit from R30 kV offsite transmission network through either CR-1 or CR-2 distribution sys in order to avoid ehutdown during maint outage WESTAFER, G R Florida Power Corp 84/03/12 STQLZ, J F Operating Reactors Branch 4 2pp 22660 099 24X Fichs 50-302, 84/03/12, 8403160315
- --8403160320 Proposed Tech Spec depicting alternate paths for offsite power sources during maint outage
 * Florida Power Corp 84/03/12 ip 22660 i01 24X
 Fiche 50-302,84/03/12,8403160315
- 8403200038 Application for amend to License DPR-72, changing Tech Epecs reclassifying accessibility on snubbers & requesting relief from requirement for visual insp MESTATER, 9 R Florida Power Corp 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation. Director 9pp 22698 327 24X Fiche 50-302, 84/03/12, 8403200030
- ---B403200044 Proposed Tech Specs, changing accessibility on snubbers & requesting relief from visual insp requirements # Florida Power Corp 84/03/12 7pp 22678 336 24X Fiche 50-302.84/03/12.8403200038
- 8403200265 Submits notes of conference from second quarterly progress meeting on 840202 re 316 Study.per NPDES permit reporting requirements
 WESTAFER.Q R Florida Power Corp 84/03/15 DENTON.H R Office of Nuclear Reactor Regulation, Director 9pp 22697 013 24X
 Fiche 50-302.84/03/15.8403200265
- 8403230014 Confirms info given in 840316 telcon re administrative controls during paralleling 4160-volt busses while supplying facility cable from Unit 2 step-up transformer WEBTAFER, Q R Florida Power & Light Co 84/03/19 STOLZ, J F Operating Reactors Branch 4 2pp 22726 361 24X Fichs 50-302,84/03/19,8403230014
- 8403230062 Application to amend License DPR-72, consisting of Suppl 1 to Tech Spec Change Request 1i2, to provide greater assurance that operation w/flooded aspirating ports strictly prohibited Certificate of Svc encl WESTAFER, O R Florida Power Corp 84/03/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 22726 319, 24X Fichs 50-302,84/03/20,8403230062
- --8403230067 Proposed Tech Spec Figure 3 4-5, "Max Allowable Steam Generator Level" * Florida Power Corp 84/03/20 ip 22726-323 24X Fichs 50-302,84/03/20,8403230062
- 8403270157 Application to amend License DPR-72, consisting of Tech Spac Change Request 34, Suppl 3 extending implementation of radiological affluent Tech Space to permit installation of oxygen & hydrogen analyzers Certificate of Svc enci HESTAFER, GR Florida Power Corp 84/03/22 DENTON, HR Clefice of Nuclear Reactor Regulation, Director 5pp 22806 063 24X Fiche 50-302,84/03/22,8403290159
- --8403290162 Proposed Tech Spec changes re radioactive gaseous effluent monitoring instrumentation surveillance requirements # Floride Power Corp 84/03/22 10pp 22806 068, 24X Fichs 50-302, 84/03/22, 8403290159

- O Inspection reports. IE Bulletins & carrespondence
- 8403290231 Forwards IE Insp Rept 50-307/84-01 on 840130-0203 No violations or deviations noted DANCE.H C Division of Project & Resident Programs 84/02/27 WILGUB.W 6 Florida Power Corp 2pp 22800 186. 24X Fiche: 50-302,84/02/27,8403290231
- --8403270234 IE Insp Rept 50-302/84-01 on 840130-0203 No violations or deviations noted Major areas inspected QA, training, posting & labeling, external exposure control, radiation insp. plant tours & outage preplanning.
 FRANKLIN.L A . BARR.K Region 2, Office of Director 84/02/23 5pp 22800 188 24X Fiche 50-302,84/02/27,8403270231
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Syc list Encl
- JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 113pp 22707 237 24X Fiche 50-000,84/02/28,8401190072
- 8403060402 Forwards Rev 0 to 04-5079-204, "Masonry Wall Reevaluation Program Including Response to NRC Questions," in response to S31129 request for add1 info re IE Bulletim 80-11 WESTAFER, G R Florida Power Corp 84/02/29 BTDLZ, J F Operating Reactors Branch 4 2pp 22511 235 24X Fiche 50-302, 84/02/29, 8403060402
- --8403060414 Rev O to 04-5079-204, "Masonry Wall Reevaluation Program Including Response to NRC Questions"
 # Oilbert Associates, Inc. 04-5079-204 ROO 84/02/10 40pp 22311 237 24X Fiche 50-302,84/02/29,8403060402
- 8403290262 Forwards IE Insp Rept 50-302/84-04 on 840206-07 No Violations or deviations noted DANCE-H C Division of Project & Resident Programs 84/03/0 HILOUS, W S Florida Power Corp 2pp 22800 169 24X Fiche 30-302.84/03/01.8403290262
- -8403290266 IE Insp Rept 50-302/84-04 on 840206-07 No violations or deviations noted. Major areas inspected emergency preparedness protective action recommendations HUFFMAN, G N Region 2. Office of Director JENKINS, G R Divisio of Emergency Preparedness & Materials Safety 84/02/27 App 22800 171 24K Fiche 50-302.84/03/01.8403270262
- 1402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 2252 327 24x Fiche 50-000.84/03/02.8402090007
- '402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02,8402090008
- 402070009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Swc list encl
 JORDAN, E.L. Division of Emergency Preparadness & Engineering
 Response (Post 830103) 84/03/02 Consulidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02,8402090009
- 402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp" Svc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post E00103) B4/03/05 Consolidated Edison Co of New York, Inc. 117pp. 22553 336, 24X Fiche 50-000.84/03/05,8402090011
- 102090024 IE Info Notice 84-09.Rev I. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys." Svc list encl.

 JORDAN E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Fiche: 50-000.84/03/07.8402090024
- 102090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys." Svc 11st encl JORDANNE 1. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co of New York, Inc. 118pp 22584:186 24X Fiche 50-000,84/03/07.8402090028
- Q3140335 Forwards IE Bafeguards Insp Rept 50-302/84-05 on 840213-17 % notice of violation Notice of violation withheld (ref 100FR2 790)
 LEWIS,R C. Division of Project & Resident Programs 84/03/08
 Florida Power Corp 2pp 22659 162 24X Fiche 50-302,84/03/08,8403160335

- --8403160388 IE Safeguards Insp Rept 50-302/84-05 on 840213-17 Violations noted Details withheld (ref 10CFR2 790 & 73 21) HALL,B L Region 2. Office of Director MCOUIRE,D R Division of Emergency Preparedness & Materials Safety 84/03/02 1p 22659 164 24X Fiche 50-302,84/03/08,8403160335
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl.
 DEVOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031.
- 8403200038 Application for amend to License DPR-72, changing Tech Specs reclassifying accessibility on snubbers & requesting relief from requirement for visual insp.
 WESTAFER, Q.R. Florida Power Corp. 84/03/12 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 9pp. 22698-327, 24X Fiche. 50-302, 84/03/12, 8403200038
- --B403200044 Proposed Tech Specs, changing accessibility on snubbers & requesting relief from visual insp requirements.
 # Florida Power Corp 84/03/12 7pp. 22698:336 24X
 Fiche 50-302,84/03/12,8403200038
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities " Svc list encl JDRDANIE.L Division of Energency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sqs " Svc list encl DERDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403060283 Monthly operating rept for Jan 1984.W/840207 ltr GRAHAM.D., FIELDS.D., WESTAFER.Q R Florida Power Corp 84/01/31 DEYQUNG,R C Office of International Programs, Director. 5pp 22517 021 24X Fiche 80-302.84/01/31,8403060283
- 8403160036 Menthly operating rept for Feb 1784 W/840312 ltr CULVER.M M.. ORAHAM.D , WEBTAFER.G R Florida Fower Corp. 84/02/29 DEYDUND.R C Director's Office. Office of Inspection and Enforcement 5pp. 22655.001 24X Fiche 50-302.84/02/29.8403160036
- S Reportable occurrences. LERs & related correspondence
- 8403020235 PND-II-84-019 on 840228, trip occurred, interrupting electric svc Caused by lightening arrestor failing on 230-kV line due to voltage transient wensed by reactor coolant pump power monitors 8vc restored within 30 minutes ROGGE, J F , PANCIERA: V Region 2, Office of Director 84/02/28 2pp. 22440 079. 24x Fiche 50-302.84/02/28,8403020235
- 8403090193 NPDES noncompliance notification forwards two ltrs in response to EPA 840206 ltr concerning exceeding temp limits & notification of antifouling paint use on cooling water inlet pipes & pitm, respectively
 WESTAFER, G R Florida Power Corp. 84/03/06 DENTON, H R Office of Nuclear Reactor Regulation. Director. 6pp 22975 030 24X
 Fichs 50-302.84/03/06,8403090193
- 8403300111 Forwards EPA 840302 ltr informing of NPDES noncompliance natification Util failed to rept heavy metal concentrations for south ash pend discharge Berial Number 009 for Oct 1983 MESTAFER.0 R Florida Power Corp. 84/03/26 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 2pp 22821 225, 24X Fiche 50-302,84/03/26,8403300111
- --8403300115 NPDES noncompliance notification Advises that util failed to rept heavy metal concentrations for Discharge 009 as result of inadequate sampling procedures Sampling procedures modified HANCOCK, J. A. Florida Power Corp. 84/03/19 MCGARRY, P. T. Environmental Protection Agency Spp. 22821:227 24X Fishe 50-302,84/03/26,8403300111

٠ ,

1

- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- B4031400B2 Public version of Rev 12 to Emergency Plan Implementing Procedure EPIP 700-1: "Emergency Phone List " W/831021 receipt form & JM Felton 840312 release memo. NYKIRK: J W. PLIML: Q Commonwealth Edison Co 83/10/26. 16pp 22646 119 24X Fiche 30-275,83/10/26.8403140082.

- 8403280119 Public version of Rev 7 to Emergency Plan Implementing Procedure EPIP 440-1. "Emergency Communications Sys & Operational Tests " M/840110 procedure change request form & JM Felton 840322 release memo PLIML.0 Commonwealth Edison Co 84/01/04 DENTON.H R NRC No Detailed Affiliation Given 21pp Fichs 50-275.84/01/04.8403280119
- 8403020003 Revised emergency implementing procedures including Rev 1 to Procedure EPIP 100-1, "Acting Station Director" W/840301 ltr + Commonwealth Edison Co 84/02/21 8pp 22442 187 24X Fiche 50-275.84/02/21.8403020003
- 8403120326 Notification of 840308 meeting w/util in Bethesda.MD to discuss status of implementation of fire protection mod & proposed interim compensatory measures
 NORRIS.J A Operating Reactors Branch 1 84/03/01 VAROA.S A Operating Reactors Branch 1 2pp 22596 353 24X
 Fiche 50-295,84/03/01,8403120326
- 8403170314 Forwards 1E Insp Repts 50-275/83-27 & 50-304/83-28 on 831122-1228 & 840202 & notice of violation Concerns re mgt control inadequacies, per TMI Action Plan Item II F 1 1, "Noble Gas Effluent Monitor: "expressed HIND, J A Division of Radiological & Materials Sefety Programs 84/03/01 REED.C Commonwealth Edison Co 2pp 22673 176 24X Fiche 50-275.84/03/01.8403170314
- --8403190321 Notice of violation from insp on 831122-840202 HIND, J. A Division of Radiological & Materials Safety Programs 84/03/01, 3pp 22673 198 24X Fiche 50-295,84/03/01,8403190314
- --8403190334 IE Insp Repts 50-295/83-27 & 50-304/83-28 on 831122-840202 Violation noted, failure to follow plant procedures re source handling, to evaluate radiological hazards & to control access to high radiation area LOVENDALE, P C Region 3, Office of Director 84/02/29 14pp 22673, 201, 24X Fiche 50-295,84/03/01.8403190314
- 8403130185 Discusses evaluation of State of IL & iocal pians & preparedness for facilities Plans adequate to protect health & sefety of public Approval of public alert netification sys conditional on verification of criteria of NUREG-0654 SPECK, B W Federal Emergency Management Agency 84/03/02 DIRCKS, W J Defice of the Executive Director for Operations ip 22613:316 24X Fiche 50-295.84/03/02.8403130185
- 8403120051 Notifies of 840323 workshop on fire protection safe shutdown requirements of 100FR50. App R in Rosemont, IL to discuss IE lnfo Notice 84-09 & provide addl shutdown analyses &/or mod guidance Agenda encl SPESSARD, R L Division of Emergency Preparedness & Operational Support 84/03/06 REED, C Commonwealth Edison Co 3pp 22570: 277. 24X Fiche' 50-295, 84/03/06, 8403120051
- 8403210089 Revised Page 3 to Emergency Plan Implementing Procedure EPIP-180-1, "Rad/Chem Director" W/640320 transmittal & receipt form PLIML.9 Commonwealth Edison Co 84/03/07 2pp 22705 320 24X Fiche 50-295.84/03/07,8403210089
- 8403190195 Revised pages to Emergency Plan Implementing Procedures EPIP-180-1.adding rad/chem ofc to habitability checks W/840309 transmittal & receipt form * Commonwealth Edison Co 84/03/09 5pp 22671 100 24X Fiche: 50-295, 84/03/09, 8403190195
- B403230124 Rev 4 to Emergency Pian Implementing Procedure EPIP-330-1, "Classification of GBEP Conditions " W/B40322 transmittal 1tr. PLIML, O Commonweelth Edison Co B4/03/22 App 22730 187 24X Fiche, 50-295, 84/03/22, 8403230124

9. Adjudicatory correspondence

- 8403020134 Forwards will 840228 ltr to Denton requesting permission to withdraw application for license amends re containment leakage tests criteria Motion will be filed upon request Certificate of Svc encl STEPTOE, P P Isham, Lincoin & Beale, STEPTOE, P P Commonwealth Edison Co 84/02/28 LAZD, R M Atomic Safety and Licensing Board Panel, App 22441 345 24X Fichs. 50-295, 84/02/28,8403020134
- 8403020140 Natice of appearance in proceeding Certificate of Svc encl STEPTOE, P. P. Commonwealth Edison Co STEPTOE, P. P. Isham, Lincoln & Beale 84/02/28 ip. 22443 253 24X Fiche 50-275, 84/02/28, B403020140

- --8403020146 Notice of appearance in proceeding Certificate of Svc encl OlloMEN, D R Commonwealth Edison Co CILOMEN, B R Isham, Lincoln & Beals 84/02/28 3pp 22443 254 24x Fiche 50-295,84/02/28. 8403020140
- 8403140134 Response to Citizens Against Nuclear Power (CANP) 840213 petition to intervene & request for hearing Request should be held in abegance pending action on util request to withdraw application Certificate of Svc enc! PERLIS.R O Hearing Branch 3 84/03/05 Atomic Safety and Licensing Board Penel 7pp 22624 205 24X Fiche 50-295.84/03/05.8403140134
- O Advisory Committee on Reactor Safoguards reports & correspondence
- 8403050020 Responds to FOIA request for documents re PASNY submittal on sys interactions, repts evaluating submittal & list of repts/analyses from LLL evaluating PASNY sys interaction program Forwards App A documents
 FELTON, J M Division of Rules and Records 83/12/07 SHOLLY, S Union of Concerned Scientists 6pp 22525 078 24X
 Fichs 30-000,83/12/07,8403050020
- --8403050028 Discusses licensee proposed review plans addressing ACR8 recommendations re sys interaction study GULLER, K R Assistant Director for Operating Reactor Projects (Pre 791030) 77/10/21 BENDER, M ACR8 Advisory Committee on Reactor Safaguards 2pg 22525 146 24X Fiche 50-000, 83/12/07, 8403050020
- P Operating license stage documents & correspondence
- 8403020131 Withdraws 830808 application for amend to Licenses PPR-39 & DPR-48, changing acceptance criteria for containment leak rate tests Evidentiary hearing in 1984 would distract tochnical & legal resources from higher priority tasks FARRAR.D Commonwealth Edison Co 84/02/28 DENTOLIN Office of Nuclear Reactor Regulation. Director 2pp 22443 243 24X Fiche 50-295,84/02/28,8403020131
- 8403050119 Forwards supplemental response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATWS Events"

 BARNES,P L Commonwealth Edison Co 84/02/29 DENTON.H R Office of Nuclear Reactor Regulation, Director 26pp 22488 084 24X Fiche 50-000.84/02/29.8403050117
- B403090145 Requests submittal of documentation re NUREO-0737 items within 30 days to complete technical reviews & implementation, excluding Suppi i.by Sept 1984 VAROA.S A Operating Reactors Branch i 84/03/02 FARRAR.D L Commonwealth Edison Co 2pp 22592 309 24X Fichs 50-295.04/03/02.8403090145
- 8403280070 Forwards Amends 84 & 74 to Licenses DPR-37 & DPR-48, respectively, safety evaluation & notice of issuance & availability Amends allow performance of extensive preventive maint on shared diesel generator NORRIB, J Operating Reactors Branch 1 84/03/12 FARRAR, D L Commonwealth Edison Co 3pp 22812 273 24X Fiche 50-275,84/03/12,8403280070
- --8403280101 Amends B4 & 74 to Licenses DPR-39 & 48, respectively, allowing performance of extensive preventive maint on shared diesel generator VARGA.8 A Operating Reactors Dranch 1 84/03/12 App 22812 296 24X Fiche 50-295,84/03/12,8403280090
- --8403280106 Safety evaluation supporting Amends 84 & 74 to Licenses DPR-39 & DPR-48 respectively * Office of Nuclear Reactor Regulation, Director 84/03/12 9pp 22812 302 24% Fiche 50-295,84/03/12,8403280090
- 8403260182 Clarifies NVREQ-0737, Item II K 3 3i. In response to Generic Ltr 83-35 Westinghouse Owners Group authorized program to demonstrate conservation of WFLASH small break LOCA analyses, per Item II K 3 30 IARNES, P L Commonwealth Edison Co 84/03/21 EISENHUT, D 0 Division of Licensing 1p 22756 170 24% Fiche 50-000, 84/03/21, 8403260182

Inspection reports. IE Bulletins & correspondence

- 3403030223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCS leakage Forwards App C documents Search continuing FELTON, J H Division of Rules and Records 84/02/07 MADDEN, T J Kaye, Scholer, Fierman, Hays & Handler 3pp 22496 234 24X Fichs 50-000,84/02/07,8403050223
- --B403030256 Notifies that independent measurements of identified & unidentified RCS leak rates for all PWRs in Region III performed per Procedures 617278 & 617280 Insp findings summarized NORELIUS.C E Division of Engineering 82/03/09 JORDAN:E L Division of Engineering & Quality Assurance (Pre 830103) 2pp 22494 270 24X Fithe 50-000,84/02/07.8403050223
- 3403080174 informs of inservice insplactivities from 840329-0501 Activities will include volumetric surface & visual insplot ASME Class 1.2 & 3 components Detailed insplayoram will be available for review by second who of Mar 1734 ORAESSER.K L. Commonwealth Edison Co. 84/02/23 KEPPLER.J G Region 3. Office of Director 1p. 22537 143 24X Fiche 50-304.84/02/23,8403080174
- 3403120134 Forwards IE Insp Repts 50-R37/B4-01.50-249/B4-01. 50-254/B4-01.50-245/B4-01.50-295/B4-01 & 50-304/B4-01 on 840203-14 No moncompliance identified SHAFER.W D Region J. Office of Director 84/02/23 REED.C Commonwealth Edison Co 2pp 22570 090 24X Fiche 50-000.84/02/23. 8403120134
- --B403120137 IE insp Repts 50-237/84-01.50-249/84-01.50-254/84-01. 50-265/84-01.50-295/84-01 & 50-304/84-01 on 840203-14 No moncompliance or deviations identified Major areas inspected ailegations of improper operation CHRISSOTINUS, N. Region 3. Office of Director 84/02/21 App 22370 092 24X Fiche 50-000,84/02/23.8403120134
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan" Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER, J G Region 3. Office of Director 3pp 22490 139 24X Fichs 50-000.84/02/24,8403050043
- --8403050046 Rev 0 to "Corporate Regulatory Parformance Improvement Plan " * Commonwealth Edison Co 84/02/27 22pp 22490 142 24X Fiche 30-000,64/02/24.8403050043
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering
- JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22909 237 24X Fiche 50-000,84/02/28,8401190072
- 840319D314 Forwards IE Insp Repts 50-299/83-27 & 50-304/83-28 on 831122-1228 & 860202 & notice of violation Concerns re mgt central inadequaties, per TMI Action Plan Item II F I I.

 "Noble Gas Effluent Monitor." expressed HIND-JA Division of Radiological & Materiais Bafety Programs 84/03/01 REED, C Commonwealth Edison Co 2pp 22673 196 24% Fiche 50-295,84/03/01,8403190314
- --8403190321 Notice of violation from insp on 831122-840202 HIND, J A Division of Radiological & Materials Safety Programs 84/03/01 3pp 22873 198 24X Fiche 50-295,84/03/01,8403190314
- --8403190334 IE Insp Repts 50-295/B3-27 & 50-304/B3-28 on B31122-B40202 Violation noted failure to foliow plant procedures re source handling to evaluate radiological hazards & to control access to high radiation area LOVENDALE.P C , NICHOLSON.N , OREOER, L R Region 3, Office of Director B4/02/27 14pp 22673 201 24X Fiche 50-293.84/03/01. B403190314
- B402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Syc list encl ORACE.J N Division of GA. Safeguards & Inspection Programs (Fost B30103) B4/03/02 Compolidated Edison Co of New York, Inc 130pp 22552 327 24x Fiche 50-000, B4/03/02, 8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 28553 098 24X Fiche 30-000,84/03/02,8402090008

- B402070007 IE Info Notice 84-15, "Reporting of Radiological Releases"

 Bvc list encl

 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co. of New
 York, Inc. 119pp 22553 217 24X fiche 50-000,84/03/02,8402070009
- 8402090011 iE Info Notice 84-17, "Problems W/Liquid Nitragen Coaling Components Below Nil Ductility Temp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402070024 IE info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown 8ys " Svc list encl URDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402070024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fichs 50-000,84/03/07,8402090028
- 8403220161 Forwards IE Insp Repts 50-295/83-26 & 50-304/83-27 on 831221-840209 & notice of violation W/o notice of violation SMAFER, W D Region 3. Office of Director 84/03/07 REED. C Commonwealth Edison Co 2pp 22717 188 24X Fiche 50-295.84/03/07.8403220161
- --8403#20165 IE insp Repts 50-295/83-24 & 50-304/83-27 on 831221-840209 Noncompliance noted failure to comply w/approved written procedures Paragraphs 5.6.11 & 14. resulting in reactor trips & LERs
 HOLZMER, M M , DUNAHAY, F R , BDYB, D C Region 3, Office of Director 84/03/04 12pp 22717 190 24X Fichs 50-295.84/03/07, 840320161
- 8402070031 IE Bulietin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Svc list enc!

 DEYOUND, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- B403230088 Ack receipt of regulatory performance improvement pian Periodic meetings requested to discuss progress on program & provide feedback KEPPLER, J G Region 3, Office of Director 84/03/20 THOMAS, B Commonwealth Edison Co 1p 22730 161 24x Fiche 30-000,84/03/20, 8403230088
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER.J Q Region 3. Office of Director 3pp 22730 162 24% Fiche 50-000. 84/03/20.8403230088
- --B403230126 Rev 0 to "Corporate Regulatory Performance Improvement Plan For Dresden, Quad Cities, Zion & LaSalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations" * Commonwealth Edison Co B4/02/29 22pp 22730 165 24X Fiche 50-000, 84/03/20, 8403230088
- 8403260176 Forwards responses to iE Bulletin 83-07, "Apparently Fraudulent Products Boid by Ray Miller, Inc " Guad Cities supplied w/piping matls from Ray Miller, inc during Const Evaluation Encl Concerns of IE Bulletin 83-06 satisfied BARNES,P L Commonwealth Edison Co 84/03/20 KEPPLER,J Q Ragion 3, Office of Director 17pp, 22756 185 24X Fiche 50-000,84/03/20,8403260176
- 8402070043 IE info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pg 22823 227 24% Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Evc Life of Relays in Safety-Related Sys "Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24% Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403060217 "Efficient & Waste Disposal Semiannual Rept.Jul-Dec 1983, Gaseous Effluents. Summation of all Releases " W/840210 ltr GRAESEER. K. L. Commonwealth Edison Co. 33/12/31 KEPPLER. J. G. Region 3, Office of Director 27pp 22511 159 24X Fichs 50-295.83/12/31,8403060217

- 8403080197 "Rept of Occupational Personnel Radiation Doses, 1783" W/B40227 ltr BCOTT, J 5 Commonwealth Edison Co 83/12/31 13pp 22559 099 24X Fiche 50-000, 83/12/31, 8403080197
- 8403220120 Annual whole body external exposures for 1983 W/840316 ltr RYBAK.B Commonwealth Edison Co 83/12/31 7pp 22716 007 24X Fiche 50-000.83/12/31,8403220120
- 8403190156 Monthly operating repts for Feb 1984 W/840309 itr AUBTIN.0 . GRAESER, K L Commonwealth Edison Co 84/02/29 13pp 22669 163 24X Fiche 50-295.84/02/29.8403190156

B Reportable occurrences, LERs & related correspondence

- 8211150076 Discusses events involving loss of electrical inverters including attendent inverters to vital instrument buses Recommendations provided by Nuclear Safety Analysis Ctr are excellent in helping to reduce instrument failures ASHE.F Reactor Operations Analysis Brench 82/10/21 SEYFRIT.K v Reactor Operations Analysis Brench 82/10/21 SEYFRIT.K v Fiche. 50-000, 82/10/21, 8211150076
- 8403090174 LER 83-037/03X-i on 830915, during instrument mechanic surveillance testing of passive gas failure monitor 2 RT-PRIS, no flow observed Caused by defective circuit breaker Breaker replaced W/840305 ltr KUBCHLE: CW , GRAESER, K L. Commonwealth Edison Co 84/03/05 KEPPLER, J Region 3, Office of Director 2pp 22575 143 24X Fichs 50-304,84/03/05,8403070174
- 8403200173 LER 84-005-00 on 840215 during maint, instrument five valve test manifold for containment differential pressure transmitter found w/equalizing valve open Mod proposed to replace manifold w/single valve W/840312 ltr KELLY.T. GRAEBERN L. Commonwealth Edison Co. 84/03/12 3pp 22697.124, 244 Fiche 50-304.84/03/12.8403200173

DOCKET 30-305 KEWAUNEE NUCLEAR POWER PLANT

- F Security, medical, emergency & fire protection plans
- 8403050125 Ack receipt of FEMA 840130 ltr & associated final exercise walvations of 831101 emergency preparedness exercise No deficienciss affecting public health & safety identified based on performance of offsite agencies PAPERIELLO, C J Region 3, Office of Director, 84/02/27 QIESLER, C, W Wisconsin Public Service Corp 2pp 22487 109 24x Fichs. 50-305.84/02/27,8403050125
- 8403150343 Forwards exemption from schedular requirements for alternative shutdown sys per 10CFR50 48(c)(4) & SER Exemption being forwarded to Dfc of FR for publication EISENHUT, D Q Division of Licensing 84/02/27 OIESLER.C W Wisconsin Public Service Corp 2pp 22647 215 24X Fiche: 50-305, 84/02/27, 8403150343
- --8403150345 Examption from schedular requirements for alternative shutdown sys per 10CFR50 48(c)(4)
 DENTON,H R Office of Nuclear Reactor Regulation, Director 84/02/29 Wisconsin Public Service Corp lipp 22649 217 24X Fiche 50-305,84/02/29,8403150343
- --B403150347 Bafety evaluation supporting specific exemption from 10CFR50, 48(c)(4) re App R alternate shutdown schedule # Uffice of Nuclear Reactor Regulation, Director 84/02/29 19pp. 22649 228, 24X Fiche 50-305,84/02/29,8403150343
- 8403080089 Ack receipt of 840207 ltr transmitting changes to industrial security manual & security force training & qualification manual. Changes consistent w/provisions of 10GFR50 54(p) & acceptable
 AXELSON.M.L. Region 3, Office of Director 84/03/02 GIESLER, C W Hisconsin Public Service Corp 2pp 22557 263 24X Fiche 50-305,84/03/02,8403080088
- 8403120048 Advises of 840323 regional workshop in Rosemont, IL w/all Region III licensees to discuss fire protection safe shutdown requirements of 100FR50. App R Agenda encl SPEBBARD, R.L. Division of Emergency Preparedness & Operational Support 84/03/06 01ESLER.C W Wisconsin Public Service Corp 3pp. 22589 289 24X Fiche 50-305.84/03/06.8403120048

J Insurance & indemnity information

- B403160298 Forwards Endorsement 65 to NELIA Policy NF-204, Endorsement 14 to NELIA Policy NF-384 & Endorsement 8 to NELIA Master Policy 1 GIESLER.C W Hisconsin Public Service Corp B4/03/13 DINITZ, 1 Office of Nuclear Res
- P Operating license stage documents & correspondence
- 8403050223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCG leakage Forwards App C documents Search continuing FELTON, J M Division of Rules and Records 84/02/0/ MADDEN, T J Kaye, Scholer, Fierman, Hays & Handler 3pp 22496 234 24X Ficha 50-000,84/02/07,8403050223
- --8403050235 Advises that certain aspects of facility Tech Spec requirements governing RCS leakage appear to be inconsistent w/std nuclear industry practice Licenses should be requested to modify Tech Specs Related info encl NORELIUS.C E Region 3. Office of Director 82/03/10 EISENHUT.D 6 Division of Engineering lipp 22496 248 Fiche 50-000,84/02/07.8403030223
- 8403010066 Forwards safety evaluation re 821223 response to Oeneric Ltr 82-16 concerning NUREQ-0737 Tech 8pecs Two Items closed Items I A I 1 3 b II E 4 i under consideration Response acceptable VARQA, S A Operating Reactors Branch 1 84/02/10 GIFSLER, C W Wisconsin Public Service Corp 7pp 22480 OO1 24X Fichs 50-305,84/02/10,8403010066
- 8402170104 Forwards "Reload Safety Evaluation Cycle X." Feb 1984 Cycle X reload design assumes approval of proposed Amend 54 to Tech Specs OIEBLER, C.W. Wisconsin Public Service Corp. 84/02/14 VARGA, S.A. Operating Reactors Branch 1 2pp 22301 009 24X Fiche 50-305.84/02/14,8402170104
- --8402170107 "Reload Safety Evaluation Cycle X." Feb 1984 HDLLY, J T. ROPSON.D J., WOZNIAK.S F. Hisconsin Public Service Corp. 84/02/06 66pp. 22301 011 24X Fiche 50-305,84/02/14, 8402170104
- 8403070321 Forwards corrected Tech Spec Page 6-26 to Amend 52 to License DPR-43 deleting Paragraph 6 14. "Environ qualification" VARQA.S A Operating Reactors Branch 1 84/02/23 GIESLER.C W Wisconsin Public Service Corp 3pp 22564 317 24X Fiche 50-305.84/02/23.8403070321
- ~-8403070323 Corrected Tech Spec Page 4-26 deleting Paragraph 6 i4,
 "Environ Qualification"

 * Office of Nuclear Reactor Regulation, Director 84/02/23 ip
 22544 320 24% Fiche 30-305,84/02/23,8403070321
- 8403060504 Discusses site visit on 840228-29 & 0301-02 w/BNL representative to collect data on high radiation exposure jobs & dose reduction mods for studies being performed by NRC.per 840223 conference call VARQA, 8 A Operating Reactors Branch 1 84/02/24 GIESLER, C W Wisconsin Public Service Corp. 3pp 22552 174 24X Ficha, 50-305, 84/02/24, 8403060504
- 8403020295 Notifies that proposed Tech Spec for certain NUREG-0737 items per Generic Ltr 83-37 will be submitted by 840401 GIESLER.C W Wisconsin Public Service Corp. 84/02/28 EIBENHUT, D G Division of Licensing 2pp 22440 066 24X Fiche 50-305,84/02/28,8403020295
- B403140225 Notifies of plan for resolving upper plenum injection (UPI) issue Issue involves ECCS models by Westinghouse & Exxon for calculating ECCS performance of Westinghouse & uo-loop plants Retention of interim penalty propose & UAROA.S A Operating Reactors Branch 1 84/03/06 QIEBLER, C Wilsonsin Public Service Corp. Spp 22637.323 24X Fiche 50-305,84/03/06.8403140225
- 8403i30i88 Provides info to support review of proposed Amend 58 to License DPR-43 Attached table provides comparison of calculated voltages Agreement shown between calculated & measured voltages & currents OIESLERIC W Wisconsin Public Service Corp B4/03/08 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 22406 126 24X Fichs 50-305.84/03/08.8403i30i88

- 8403160327 Forwards revised Page 4 2 1 of proposed Amend 57 to Tech Specs re inservice insp & testing GIESLER.C W Hisconsin Public Bervice Corp 84/03/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 22660 155 24X Fiche 50-305.84/03/13.8403160327
- --8403160331 Revised Page 4 2 1 of proposed Amend 57 to Tech Specs reinservice insp & testing
 * Wisconsin Public Service Corp 84/03/13 ip 22660 156 24X
 Fitche 50-305,84/03/13,8403160327
- 8403200134 Requests permanent exemption from requirements of App J to 10CFR50 ref air lock testing following periods during which containment integrity maintained GIESLER, C W Wisconsin Public Service Corp 84/03/15 DENTON, H R Office of Noclear Reactor Regulation, Director 2pp 22686 36I 24% Fiche 50-305,84/03/15,8403200154
- 8403270030 Discusses 840120 meeting re resolution of SER deficisncies, mathodology of master list development all DBAs considered & Justification for continued operation Environ qualification plan encl OIESLER.C W Wisconsin Public Servics Corp 84/03/16 VARQA,S A Operating Reactors Branch I 9pp 22768 031 24X Fiche 50-305,84/03/16,8403270030
- --8403270032 "Resolution of SER for Environ Qualification of Electrical Equipment Important to Bafety at Kswaunee Nuclear Power Plant "

 * Wisconsin Public Bervice Corp 84/03/16 79pp 22768 040 24X Fichs 50-305, 84/03/16, 8403270030
- --8403270038 "Kewaunee Nuclear Power Plant Environ Qualification Plan" # Wisconsin Public Service Corp 84/03/16 358pp 22768 124 24X Fiche 50-305,84/03/16,8403270030
- 8403280048 Forwards response to B31205 request for addI info re NUREO-0737 Item II D 1. "Performance Testing of Relief & Safety Valves "Microfiche of RELAPS/ADLPIPE computer analysis enci OIESLER.C W Wisconsin Public Service Corp 84/03/23 VARQA, 8 A Operating Reactors Branch 1 Sopp 22776 282 24X Fichs: 50-305, 84/03/23, 8403280048
- @ Inspection reports, IE Bulletins & correspondence
- B403050223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCB isakage Forwards App C documents Search continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN, T J Kayes, Scholer, Fierman, Hays & Handler 3pp 22496 234 24X Fiche 50-000,84/02/07,8403050223
- --B403050256 Notifies that independent measurements of identified & unidentified RCS leak rates for all PMRs in Region ill performed per Procedures 61727B & 61728B Insp finding summarized NORELIUS: C E Division of Engineering B2/03/08 JORDAN.E L Division of Engineering & Guality Assurance (Pre 830103) 2pp 22476 270 24X Fiche 50-000.84/02/07.8403050223
- 8403190379 Forwards IE Insp Rept 50-305/83-17 on 831216-840215 No noncompliants noted SHAFER.W D Region 3. Office of Director 84/02/27 GIESLER, C W Wisconsin Public Service Corp 2pp 22675 209 24X Fiche 50-305/84/02/27,8403190379
- --8403190384 iE Insp Rept 50-305/83-17 on 831219-840215 No noncompliance noted Major areas inspected maint surveillance, independent inspiregional requests & operational safety NELBON.R L , JACKIN.I N Region 3, Office of Director 84/02/24 5pp. 22675 211 24x Ficher 50-305/84/02/27,8403190379
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28, Consolidated Edison Co. of New York, Inc. 115pp 22707 237 24X Fiche; 50-000, 84/02/28, 8401170072
- 8402090007 IE Info Notice 84-i4, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list sncI GRACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-i6, "Failure of Automatic Sprinklar Bys Vaives to Operate." Svc list encl JDRAN.E L Division of Emergency Proparadness & Engineering Response (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc. 122pp 22553 098 24% Fiche 50-000,84/03/02,8402090008

- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases "
 Svc list sncl
 JORDAN, E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 117pp 22553 217 24X Fiche 50-000,84/03/02,8402070009
- 8402090011 IE 1nfo Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Bslow Nil Ductility Temp " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-07, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc 118pp 22635 049 24% Fithe 50-000, 84/03/07, 8402090024
- B402090028 IE Info Notice B4-18, "Stress Corrosion Cracking in FWR Bys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403220134 Forwards IE Insp Rept 50-305/84-01 on 840206-10. No noncompliance noted PAPERIELLO.C J Region 3, Office of Director 84/03/08, GIESLER,C W Hisconsin Public Service Corp 2pp, 22716.037. 24X Fiche.50-305.84/03/08.8403220134.
- --B403R20140 lE Insp Rspt 50-305/84-01 on 840R06-10 No noncompliance noted Major areas inspected confirmatory measurements, including sampling, lab GC & comparison of itensee analyses w/Rspion III mobils lab.

 JANUBKA: A 0 , SLAHINSKI: N J , SCHUMACHER, M. G. Region J, Office of Director 84/03/08 8pp 22716 039 24X Fiche 50-305,84/03/08,8403220134
- 8402090031 IE Dulletin 84-02. "Failures of GE Tupe HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG.R C. Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000-84/03/12,8402090031.
- 8403200016 Responds to IE Bulletin 83-08 re electrical circuit breakers w/undervoltage trip feature No circuit breakers w/mechanical trip attachments similar to DB-50 breaker used in safety-related applications
 01ESLER.C W Wisconsin Public Service Corp. 84/03/12 KEPPLER, J. Q
 Region 3, Office of Director. ip 22699, 181. 24X
 Fiche 50-305,84/03/12,8403200016
- B403i60327 Forwards revised Page 4 2 I of proposed Amend 57 to Tech Specs re inservice insp & testing OIEGLER.C W Wisconsin Public Service Corp 84/03/I3 DENTON.H R Defice of Nuclear Reactor Regulation, Director. 1p 22660 155 24X Fiche 50-305.84/03/I3.8403I60327
- --8403160331 Revised Page 4 2 I of proposed Amend 57 to Tech Specs re inservice insp & testing * Hisconsin Public Service Corp 84/03/13 ip 22660 156 24X Fiche 50-305,84/03/13.8403160327
- 8402090043 IE Info Notice 84-i9, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/21 Consolidated Edison Co of New
 York, Inc 123pp. 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notics 84-20, "Svc Life of Relays in Bafety-Related Sys " Svc list enc! JURDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403060408 "Semiannual Effluent Release Rept, Jul-Dec 1983 " W/840229 ltr OIEBLER, C W Wisconsin Public Service Corp 83/12/31 KEPPLER, J Q Region 3, Office of Director 32pp. 22518 155 24X Fiche 50-305, 83/12/31, 8403040408
- 8403070169 "Kewaunse Nuclear Powsr Plant Annual Operating Rept 1983." W/840301 ltr
 * Misconsin Public Service Corp 83/12/31 110pp 22539.001. 24X Fiche 50-305.83/12/31.8403070169
- 8403130147 Monthly operating rept for Feb 1984 W/840309 ltr. RUITER, G H , DIESLER, C W. Wisconsin Public Service Corp. 84/02/29 5pp 22608-220 24X Fiche 50-305,84/02/27,8403130147

- 8 Reportable occurrences, LERs & related correspondence
- 8403230178 Forwards Technical Review Rept AEOD/T313, "Capped Containment Pressure Sensing Lines," & proposed IE info notice Issue adequately resolved RUBIN,8 D Reactor Operations Analysis Branch 83/05/11 BEYFRIT.K V Reactor Operations Analysis Branch 1p 22757 286 24X Fiche 50-000,83/05/11.8403230178
- --8403230181 "Capped Containment Pressure Sensing Lines." technical review rept Condition caused by procedural inadequacy RUBIN,5 D Director's Office 83/05/11 App 22757 287 24X Fichs 50-000,83/05/11,8403230178
- V Operator Examinations
- 8403130351 Requests encl ref matl for requalification program evaluation scheduled for uk of 840521 Matl required by 840316 BTREETER.JF Region 3, Office of Director 84/03/05 GlESLER,C W Wisconsin Public Bervice Corp 3pp 22618 354 24X Fiche 30-305,84/03/05.8403130351
- DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8403070270 Public version of revised emergency response plan implementing procedures, including Procedure F3-2 reclassification of emergencies, F3-5 re emergency notification & F3-10 re personnel accountability W/831219 ltr & memo MENDELE, D. J. JOHNSON, J. M. Northern States Power Co. 83/10/28 148pp 22595 326 24X Fiche 50-282,83/10/28,8403070270
- 8403070207 Revised emergency implementing procedures, including Rev 25 to Procedure F3, "Table of Contents" & Rev 3 to Procedure F3-8, "Recommendations for Offsite Protective Actions " W/840302 ltr FEY,F L. Northern States Power Co 84/02/24 28pp 22574 328 24% Fichs 50-282, 84/02/24, 8403070207
- 8403190020 Forwards IE Insp Repts 50-282/83-24 & 50-306/83-24 on 831211-840210 No noncompliance identified 8HAFER, N D Region 3. Office of Director 84/03/01 LARSON, C E Northern States Power Co 2pp 22666 053 24X Fiche, 50-282, 84/03/01, 8403190020
- --8403190042 IE lnsp Repts 50-282/83-24 & 50-306/83-24 on 831211-840210 No noncompliance or deviations identified Major areas inspected, maint. LERs, energency planning & surveillance, meetings w/state & local officials & IE bulletins HARD, J E : JACKIW, I N Region 3. Office of Director 84/02/29 12pp 22666,055 24X Fiche 50-282,84/03/01.8403190020
- 8403130163 Forwards final rept re small-scale offsite radiological amergency preparedness exercise on 821014 No deficiencies noted.

 KRIMM, R W Federal Emergency Menagement Agency 84/03/05

 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) App 22599 307 24X Fiche 50-282,84/03/05,8403130163
- --8403130172 Final rept of small-scale joint emergency exercise on 821014 # Federal Emergency Management Agency 82/12/17 92pp 22599 313 24% Fiche 50-282,84/03/05,8403130163
- 8403120106 Notifies of 840323 workshop on fire protection safe shutdown requirements of 100FR30. App R in Rosemont. IL to discuss IE Info Notice 84-09 & provide add! shutdown analyses &/or mod guidance. Agenda enc!

 EPE88ARD. R. L. Division of Emergency Preparedness & Operational Support 84/03/06 LARBON. C. E. Northern States Power Co. 3pp 22388 169 24X Fiche 50-282, 84/03/06.8403120106
- 8403300130 Revised emergency plan implementing procedures, including Procedure F3 re table of contents & F3-13 re offsite dose calculation W/840320 transmittel ltr WATT.E, FEY.F L Northern States Power Co 84/03/09 36pp 22820 255 24X Fiche 50-282,84/03/09,8403300130
- I. Financial information
- E403270115 Suppl to Annual Financial Rept 1983.consisting of financial & statistical info W/840326 ltr ERUSVEN,A.D. Northern States Power Co 83/12/31 23pp 22806 182 24X Fiche 30-000,83/12/31,8403290115

- P Operating license stage documents & correspondence
- 8403050238 Forwards Amends 68 & 62 to Licenses DPR-42 & DPR-60, respectively & safety evaluation Amends revise Tech Specs resemengency air treatment sys & electric hydrogen recombiners DIIANNI. P C Operating Reactors Branch 3 84/02/21 MUSQLF, D M Northern States Power Co 2pp 22527 188 24X Fichs 50-282.84/02/21.8403050238
- --8403050243 Amends 68 & 62 to Licenses DPR-42 & DPR-60, respectively, revising Tech Specs re omergency air treatment sys & electric hydrogen recombiners MILLER.J R Operating Reactors Branch 3 84/02/21 18pp 22527 190 24X Fiche 50-282,84/02/21,8403050238
- --8403050249 Safety evaluation supporting Amends &B & &2 to Licenses DPR-42 & DPR-60, respectively * Office of Nuclear Reactor Regulation. Director 84/02/21 7pp 22327 208 24% Fiche 50-282,84/02/21,8403050238
- 8403060425 Submits fees requested for 820630 exemption request, in response to NRC 840213 ltr MUSQLF, D. Northern States Power Co. 84/02/29 MILLER, W.O. License Fee Management Branch 2pp 22518 200 24X Fiche 50-282,84/02/29,8403060425
- 8403130245 Forwards "Efficent & Waste Disposal Semiennual Rept.Jul-Dec 1983," "Offsite Radiation Dose Assessment, 1983" & Rev 4 to "Offsite Dose Calculation Manual" FEY.F L Northern States Power Co 84/03/01 Region 3, Office of Director Ip 22610 143 24X Fiche 50-282, 84/03/01, 8403130245
- --8403130278 Rev 4 to "Offsite Dose Calculation Manuel " SORENSON, J Northern States Power Co 84/11/14 11pp 22610 157 24X Fiche 50-282,84/03/01,8403130245
- B403150290 Forwards safety evaluation re error in CDGRA IIIC/MIT computer code, previously accepted by NRC 830217 & 0324 ltrs. for use in analyzing fuel reloads Error does not create any substantial safety haird MILLER, J R. Operating Reactors Branch 3 84/03/06 MUSOLF, D M Northern States Power Co 1p 22647 333 24X Fiche 50-282, 84/03/06,8403150290
- --8403150293 Sefety evaluation re error in COBRA lilC/MIT computer code reload methodology rept NSPNAD-diOZ Error has not effected initial findings or conclusions re acceptability of use of COBRA IIIC/MIT code. * NRC - No Datelled Affiliation Given 84/03/06 2pp 22649 334 244 Fiche 50-282,84/03/06.8403150290
- 8403190397 Provides updated info re mods required by NUREO-0737. Item
 II D 1 2 re safety & relief valve performance Unit i piping
 & supports will be installed during next refueling outage
 scheduled for 850105
 MUSQLF, D Northern States Power Co 84/03/14 Office of Nuclear
 Reactor Regulation, Director 1p 22675 192 24X
 Fiche 50-282.84/03/14.8403190397
- 8403230051 Submits status of mods to improve adequacy of station distribution sys voltages, per util 810717 ltr & NRC 821029 SER All mods completed w/exception of changes to station air compresser starting circuit MUBCLF.D Northern States Power Co 84/03/16 Office of Nuclear Reactor Regulation, Director 2pp 22724 346 24X Fiche 50-282.84/03/16.8403230051
- @ Inspection reports. IE Bulletins & correspondence
- 8403050223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCB leakage Forwards App C documents Sparch continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN, T J Rayes, Scholer, Fireman, Hays & Handler 3pp 22496 234 24X Fiche 50-000.84/02/07,8403050223
- --B403050256 Notifies that independent measurements of identified & unidentified RCS leak rates for all PWRs in Region III performed per Procedures 617278 & 617288 Insp findings summarized NORELIUS.C E Division of Engineering 82/03/08 JURDAN.E L Division of Engineering & Quality Assurance (Fre 830103) 2pp 22476 270 24% Fiche 50-000.84/02/07.8403050223
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Bvc list enc!

 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239 24X Fiche. 50-000.84/02/28,8401190072

- 8403190020 Forwards IE Insp Repts 50-282/83-24 & 50-306/83-24 on B31211-840210 No noncompliance identified SHAFER.W D Region 3 Office of Director 84/03/01 LARSON.C E Northern States Pouer Co 2pp 2266 053 24X Fiche 50-282
- --8403190042 IE Insp Repts 50-282/83-24 & 50-306/83-24 on 831211-840210 No noncompliance or deviations identified Major areas inspected maint.LERs, emergency planning & surveillance, meetings w/state & local officials & IE bulietins HARD. J E. FEIERADEND. C D., HARTMANN.P L. Region 3, Office of Director 84/02/29 12pp 22666 055 24X Fiche 50-282,84/03/01.8403190020
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACELJ N Division of QA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, inc 130pp 22552 327 24X Fiche 50-000.84/03/02.8402090007
- 840209000B IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84703/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000,84703/02,8402090008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases " Svc iist encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. ii9pp 22593 217 24% Fiche 50-000.84/03/02, 8402090009
- 84020900i1 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Coaling Components Delow Nil Ductility Temp " Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24% Fiche 90-000,84/03/05,84020900ii
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York. Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 i86 24X Fiche 50-000,84/03/07,8402090028
- 8403190388 Forwards summary of status of requests for relief from requirements of Section XI of ASME Boiler & Pressure Vessel Code for inservice insp program & clarification of items that require addireview MUSQLF.D Northern States Power Co 84/03/09 Office of Nuclear Reactor Regulation. Director 9pp 22675 295 24X Fiche 50-282.84/03/09.8403190388
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list enc! BEYDUNG,R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc i34pp 22823 074 24X Fiche 50-000,84/03/12,8402090031
- 8403190200 Responds to [E Bulletin 83-07 re products supplied by Ray Miller. Inc Neither unit received products from Ray Miller. Inc & vendor not on approved util vendor list LARSON.C E Northern States Power Co 84/03/12 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 4pp 22471 105 24X Fiche 50-282,84/03/12,8403190200
- 8403300036 Forwards IE Insp Repts 50-282/84-02 & 50-306/84-02 on 840215-i7 No nuncompliance noted PAPERIELLO.C J Region 3. Office of Director 84/03/15 LARSON.C E Northern States Power Co 2pp 22821 320 24% Fiche 50-282,84/03/15,8403300036
- --8403300040 IE Insp Repts 50-282/84-02 & 50-304/84-02 on 840215-17 No violations or deviations identified Major areas inspected implementation of ICCFR20 & 60 requirements for disposal of low level radwastes.including mgt controls & QC RDZAK.S: DESTMANN.M.J., SCHUMACHER.M.C. Region 3, Office of Director 84/03/15 5pp 22821 322 24X Fiche 50-282.84/03/15, 8403300034
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURBAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24% Fiche 50-000,84/03/21,8402090043

- B402090044 JE Info Notice 84-20, "Svc Life of Relays in Bafety-Related Sys " Svc list enc! JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24% Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403300095 Monthly operating repts for Feb 1984 W/840306 ltr BU06TAD.D. HUSDLF,D Northern States Power Co 84/02/29 9p 24047 060 24X Fiche 30-282.84/02/29.8403300095
- 8403130245 Forwards "Effluent & Waste Disposal Semiannual Rept.Jul-Dec 1983," "Offsite Radiation Dose Assessment.1983" & Rev 4 to "Offsite Dose Calculation Manual" FEY,F L Northern States Power Co 84/03/01 Region 3, Office of Director 1p 22610 143 24x Fiche 50-282.84/03/01,8403130245
- ---8403i30258 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1983 "
 * Northern States Fower Co 83/12/31 9pp 22610 144 24X
 Fiche 50-282,84/03/01.8403130245
- DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT
- F Security, medical, emergency & fire protection plans
- 8403070278 Responds to 8309i3 itr re changes to physical security plan Rev Inconsistent w/provisions of 10CFR50 54(p) & unacceptable for reasons stated in encl Encl withheld (ref 10CFR73 21) MARTIN.T T Division of Engineering & Technical Programs 84/02/29 RANDAZZA.J B Maine Yankee Atomic Power Co 3pp 22347 098 24X Fiche 50-309.84/02/29.8803070278
- E403220095 Forwards IE Insp Rept 30-309/83-20 on 831101-1231 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 84/03/07 RANDAZZAJ B Maine Yankee Atomic Power Co 2pp 22715 163 24X Fiche 50-309.84/03/07.8403220095
- --B403220103 IE insp Rept 50-309/B3-20 on B3i101-1231 Violation identified plant shift superintendent did not check tags on Tagging Order 2137-B3 HOLDEN.C . ARCHITZEL.R . SWETLAND.P Region i. Office of Director 84/03/06 13pp 22715 166 24X Fiche 50-309.84/03/07.8403220095
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encil HURLEY, T E Region 1. Office of Director 84/03/09 D'TOOLE, J D Consolidated Edison Co of New York. Inc KENYON, B D Pennsylvania Power & Light Co HARRISON, R J Public Service Co of New Hampshire 35pp 22672 062 24X Fiche 50-000,84/03/09,8403190243
- Q Adjudicatory correspondence
- 8403130262 Order granting Sensible Maine Power & State of ME motions to withdraw contentions, granting util motion to withdraw portion of application & authorizing issuance of amend of OL LAZO,R M Atomic Safety and Licensing Doard Panel 84/03/09 4pp 22606 050 24X Fiche 50-309,84/03/09,8403130262
- H General correspondence
- 840322011? Expresses concern re inexperienced & unskilled labor at facility Repair contract awarded to contractor w/little or no repair experience OP Conley 840215 ltr encl COSSAR.A G Affiliation Not Assigned 84/03/17 DEYDUNG.R Director's Office, Office of Inspection and Enforcement 2pp 22716 216 24X Fiche 50~309,84/03/17,8403220119
- P Operating license stage documents & correspondence
- 8403020283 Forwards safety evaluation based on review of 830912,22 & 1102 responses re feedwater trip sys Feedwater trip sys design satisfies single fallure requirements Requests completion of listed confirmatory items within 120 days MILLER, J R Operating Reactors Branch 3 84/02/14 GARRITY, J H Maine Yantee Atomic Power Co 10pp 22475 016 24X Fiche 50-309,84/02/14,8403020283

- 8403050380 Forwards request for add1 info re Cycle 8 reload to continue review of 840127 submittal MILLER.JR Operating Reactors Branch 3 84/02/17 GARRITY, J H Maine Yankee Atomic Power Co 3pp 22527 253 24X Fiche 50-309,84/02/17.8403050380
- 8403050355 Responds to 840106 itr re radiological effluent Tech Specs (RET6) Program provides accountable sys to assure protection of public health & safety Schedule for submittal of proposed RET8 & offsite dose calculation manual requested MILLER, J R Operating Reactors Branch 3 84/02/27 GARRITY, J H Maine Yankee Atomic Pouer Co 2pp 22501 335 24X Fiche 50-309,84/02/27,8403050355
- B403060094 Forwards Class III amend fee,per NRC 840116 itr re Proposed Changes 81 8-72 concerning snubber surveifiance & reactor protective sys channet & ESF actuation sys WHITTIER, 0 D Maine Yankee Atomic Power Co 84/02/27 DIGGS,R M License Fee Management Dranch 1p 22516 362 24X Fiche 50-309,84/02/29,8403060094
- 8403150333 Requests info re analysis of high energy steam line break Info needed to complete review of 820713 submittel reenviron conditions for equipment outside containment Info requested within 30 days
 MILLER, J. R. Operating Reactors Branch 3 84/03/02 RANDAZZA, J.B. Maine Vankee Atomic Power Co. 2pp. 22647 269 24X
 Fiche 50-309,84/03/02,8403150333
- 8403150105 Informs of recent assignment of EC Wenzinger as Chief, Reactor Projects Section iA, effective immediately Responsibilities cover Maine Yankee, Yankee Rowe & Calvert Cliffs Nuclear Power Stations BTAROBTECKI, R Region 1, Office of Director 84/03/08 RANDAZAJ B Maine Yankee Atomic Power Co 2pp 22640 140 24x Fiche 50-309,84/03/08.8403150105
- 8403230036 Withdraws 81050: commitment to instail addi pressurizer sensor Contribution of purge sys isolation valves to radialogical consequences to DBA LOCA would be minimal WHITTIER.0 D Maine Yankee Atomic Power Co 84/03/16 MILLER.JR Operating Reactors Branch 3 1p 22724 332 24X Fiche 50-309,84/03/16.8403230036
- B403220192 Forwards "Control of Heavy Loads, Phase iI " Rept result of review of crane operation design & maint including analysis of load drop risk to safety-related equipment beneath travel paths Confirms defense-in depth, per NUREQ-0612 WHITTIER: O Maine Yankee Atomic Power Co 84/03/19 MILLER, J R Operating Reactors Branch 3 2pp 22717 048 24X Fiche 50-309,84/03/19,8403220192
- ---8403220199 "Control of Heavy Loads, Phase II "
 # Maine Yankee Atomic Power Co 84/03/19 124pp 22717 050
 24X Fiche 50-309, 84/03/19, 8403220192
- B403230042 Informs that supplied inservice testing program will be submitted by B40601 Inservice testing procedures specific to control & implementation of testing activities will be completed no ister than 840515

 WHITTIER: O D Maine Yankee Atomic Power Co 84/03/20 MILLER, J R Operating Reactors Branch 3 ip 22728 354 24X

 Fiche 50-309,84/03/20,8403230042
- B403270138 Forwards revised Page 3 of Maine Yankee penetration test requirements enci w/containment leak testing rept Isolation Valve PD-233 added to list of containment sump discharge valves inside containment
 HHITTIER, 0 D Maine Yankee Atomic Power Co 84/03/21 MILLER, J R
 Operating Reactors Branch 3 2pp 22769 141 24X
 Fiche. 50-309, 84/03/21, 8403270138
- G Inspection reports, IE Bulietins & correspondence
- B403210R08 Corrected notification of B40313 meeting w/util in Bethesda, MD to discuss insp program for thermal shield in Cycle 7/8 outage. Time of meeting changed HEITNER, K L Operating Reactors Branch 3 B4/02/21 MILLER, J R Operating Reactors Branch 3 ip 22709 206 24X Fiche 50-309.84/02/21.8403210208
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Vaive Control Circuits & Annunciation " Syc list encl.
 JURDAN, & L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22709-239, 24X Fiche 50-000,84/02/28,8401170072
- B402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl QRACE. N. Division of QA, Bafeguards & Inspection Programs (Fost B30103) B4/03/02. Consolidated Edison Co of New York, Inc 130pp. 22552 329 24X Fiche 50-000, B4/03/02, B402090007

- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 22553 098 24X Fiche 30-000.84/03/02.8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list enc! JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 119pp 22553 217 24X Fiche 50-000, 84/03/02, 8402090009
- 8402070024 IE Info Notice 84-09. Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. i18pp 22635 049 24% Fiche 50-000. B4/03/07. B402070024
- 8402070028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR 8ys " Svt list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 30-000,84/03/07,8402070028
- 8403220056 Forwards IE Insp Rept 50-309/84-03 on 840207-10 No violations noted MARTIN T T Division of Engineering & Technical Programs 84/03/07 RANDAZZAJ B Maine Yankee Atomic Power Co 2pp 22714 339 24X Fiche 50-309.84/03/07.8403220056
- --B403220062 IE Insp Rept 50-309/B4-03 on 840207-10 No violations noted Major areas inspected inservice insp program, including GA function & control of exam equipment MCBREARTY, R A , DURR , J P Region 1, Office of Director 84/03/05 5pp 22714 341 24% Fiche 50-309,84/03/07,8403220056
- 8403220095 Forwards IE Insp Rept 50-309/83-20 on 831101-1231 & notice of violation STAROBTECKI, R Division of Project & Resident Programs 84/03/07 RANDAZA.J 8 Hains Yankee Atomic Power Co 2pp 22715 163 24X Fichs 50-309,84/03/07.8403220095
- --8403220078 Notice of violation from insp on 831101-1231 * Region i, Office of Director 84/03/07 ip 22715 i65 24X Fiche 50-309,84/03/07,8403220075
- --8403220103 IE Insp Rept 50-309/83-20 on 831101-1231 Violation identified plant shift superintendent did not check tags on Tagging Order 2137-83 HOLDEN,C., ARCHITZEL,R., SWETLAND,P Region 1, Office of Director 84/03/06 13pp 22715 166 24X Fiche 50-309,84/03/07,8403220095
- 8402090031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use an Class IE Safety Sys " Svc list enc!
 DEYOUNG:R C Director's Office: Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000:84/03/12,8402090031
- B402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000, B4/03/21, B402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list enci JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- 8403300160 Responds to FE Bulietin 83-07 re apparently frauduient products sold by Ray Miller, Inc Ray Miller, Inc flanges received from RECO industries installed in safety-related sys Flanges will remain installed FRIZZLE, C D Maine Yankee Atomic Power Co 84/03/22 MURLEY, T E Region 1, Office of Director 4pp 22021 082 24X Fichs 50-309,84/03/22,8403300160
- R Periodic operating reports & related correspondence
- 8403130047 "Efficient & Haste Disposal Semiannual Rept. Jui-Dec 1983 "
 W/840302 Itr
 WHITTIER.G D Maine Yankee Atomic Power Co 83/12/31 MURLEY.T E
 Region i, Office of Director lipp 22608 083 24X
 Fiche 50-309:83/12/31.8403130047
- 8403290254 "Annual Personnel Exposure Rept CY83 " W/B40320 ltr WHITTIER: 0 D Maine Vantee Atomic Power Ca 83/12/31 MURLEY, T E Region i, Office of Director 3pp 22800 075 24X Fiche 50-309, 83/12/31, 8402290256

- 8403020065 Monthly operating rept for Jan 1984 W/840208 itr BIENTLUER, 9 , NCCWIBER, J T Maine Yankee Atomic Power Co 84/0 MARTFIELD, R A Management Information Branch 5pp 22442 287 24X Fiche 50-309,84/01/31,8403020065 84/01/31
- 8403300162 Monthly operating rept for Feb 1984 W/840308 itr. SIEMILLER, 8 A., MCCUMBER, J. T. Maine Yankee Atomic Power Co B4/02/29 5pp 22821 086 24X Fishe 30-309, 84/02/29, 8403300162
- S Reportable occurrences, LERs & related correspondence
- 8403130496 PNO-1-84-024 on 840306, during resin replacement operation, unplanned release of gaseous radioactivity occured Beveral workers elightly contaminated w/Rb-BB No activity detected State of ME informed BICEHDUSE, H. SHANBAKY, H. BELLANY, R. Region i. Office of Director 84/03/07 ip 22613 329 24X fiche 50-309, 84/03/07, 8403130436
- DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2 Security, medical, emergency & fire protection plans
- 8403190433 Responds to 821206 & 830718 ltrs to emergency operations facility (EOF) Request to establish primary EOF 7 5 miles from facility w/o providing backup EOF acceptable EIEENHUT, D 0 Division of Licensing 84/03/05 LIDEN,E A Published Electric & Gas Go of New Jersey lp 22681 325 24% Fichs 50-272.84/03/05,8403190433
- 8403220006 Forwards IE Insp Repts 30-272/84-06 & 50-311/84-06 on 840206-10 No violations observed MARTIN T Division of Engineering & Technical Programs 84/03/08 UDERITZ-R A Public Service Electric & Gas Co of New Jersey 2pp 22716-174 24X Fiche 50-272.84/03/08.8403220006
- --8403220010 IE Insp Ropts 50-272/84-06 & 90-311/84-06 on 840206-10 No violations noted Major areas inspected security organization, security program audit, testing & maint, physical barriers, security sys power supply & assessment aids MADDEN.W J Region 1, Office of Director 84/03/06 App 22716 176 24% Fiche 50-272,84/03/08,8403220006
- 8403190243 Notification of 840118 workshop in King of Prussia:PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice safe shutdown insp & topics described in IE Info Notice B4-09 Agenda for workshop encl MURLEY.T C Region I, Office of Director 84/03/09 O'TODLE.J D Consolidated Edison Co. of New York. Inc. KENYON.B D Pennsylvania Power & Light Co. HARRISON.R J Public Service Co. of New Hampshire J5pp 22672 062 24X Fiche 50-000.84/03/09.8403190243
- P Operating license stage documents & currespondence
- 8403090049 Submits details of vendor manual review program in response to 830504 order modifying licenses Commitment to incorporate all vendor manuals for safety-related equipment into dacument control sys completed
 LIDEN.E A Public Service Electric % Cas Co of New Jersey
 84/02/22 RISTER.H B Division of Project & Resident Programs
 App 22575 345 24X Fiche 50-272.84/02/22.8403090049
- 8403030)19 Forwards supplemental response to Generic Ltr 63-28, "Required Actions Dased on Generic implications of Salem
- ATMS Events "BARNES MAYOR OF SCHOOLS TERRITORIS OF SALEM BARNES P L Commonwealth Edison Co 84/02/27 DENTON, M R Off of Nuclear Reactor Regulation, Director 26pp 22488 084, 24X Fiche 30-000, 84/02/29, 8403050119
- 8403:30017 Requests extension for updating inadequate core cooling instrumentation & reactor vessel level instrumentation sys status repts per TMi Item II F 2 & providing Westinghouse proprietary info until 840402 LIDEN.E A Public Service Electric & Gas Co of New Jersey 84/03/02 VARGA,8 A Operating Reactors Branch 1 Ip. 22614 361 24X Fiche 50-272,84/03/02,8403130017
- 8403:30108 Requests 4-month extension until June 1984 for submittal of technical rept on reactor vessel surveillance Capsule T LIDENE A Public Service Electric & Gas Co of New Jersey 84/03/02 VARGA: B A Operating Reactors Branch 1. 2pp 22600 257 24X Fiche 50-311.84/03/02.8403130108
- B403260030 Requests identification of any potential problems or items re-completion of NUREG-0737 items by Sept 1984 Response requested within 30 days of 1tr receipt VAROA.6 A Operating Reactore Branch 1 B4/03/02 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 3pp 22763 2Ft 24X Fiche 50-272.84/03/08.8403260050

- E403i40113 Forwards "Salem Generating Station 3i6(b) Demonstration," per 830623 request for add1 info re review of OL application for Hope Creet
 MITTL: R L Public Service Electric & Gas Co of New Jersey
 84/03/05 SCHWENCER: A Licensing Branch 2 ip 22627 124 24X
 Fiche 50-000.84/03/05.8403140113
- --8403140117 "Salem Generating Station 316(b) Demonstration "
 * Public Service Electric & Gas Co of New Jersey 84/0
 647pp 22627 125 24X Fiche 50-000.84/03/05.8403140113 84/02/29
- 8403290281 Forwards plant-specific info on reactor protection sys shunt trip mods, in response to NRC 830810 ltr & Generic Ltr 83-28 Shunt trip mechanism wiil be installed during refueling outage W/14 oversize drawings Aperture cards in FDR LIDEN.E A Public Service Electric & Gas Co of New Jersey 84/03/14 VRQA.5 A Operating Reactors Branch i 14pp 22800 200 24X Fiche 50-272.84/03/14.8403290281
- 8403300085 Requests extension to Jul 1984 for completion of post-maint 103300005 Requests extension to JUL 1984 for completion of post-maint operability testing of sefety-related equipment based on revised interpretation of scope identified through discussion w/Region I personnel LIDEN,E A Public Service Electric & Qas Co of New Jersey 84/03/23 VARQA,B A Operating Reactors Branch 1 3pp 22822 073 24X Fichs 30-272,84/03/23,8403300085
- O Inspection reports, IE Bulletins & correspondence
- 8401190072 iE Info Notice 84-13. "Potential Deficiency in Mator Operated Valve Control Circuits & Annunciation " Svc list URDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22707 237 24X Fiche 50-000.84/02/28,8401170072
- 8403070080 Submits supplemental response to iE Builetin 83-06 re nonconforming matls supplied by Tube-Line Corp Remaining four suppliers confirmed that no subj matls supplied to Hope Creek Colt Industries info under review MARTIN.T J Public Service Electric & Oas Co of New Jersey 84/02/28 MURLEY.T E Region 1. Office of Director 2pp 22575 297 R4X Fiche 30-000,84/02/28,8403070080
- 840315006B Forwards IE Insp Repts 50-272/84-02 & 50-311/84-02 on 840116-19 No violations observed MARTIN.T T Division of Engineering & Technical Programs 84. UNDERIT7.R A Public Service Electric & Oas Co of New Jerset 2pp 22643 177 24X Fiche 50-272.84/02/28.840315006B 84/02/28
- --8403150078 IE Insp Repts 50-272/84-02 & 50-311/84-02 on 840116-19 No violations observed Major areas inspected nonradiological chemical measurements, GC program of analytical measurements & procedures & training ZIBULSKY,H , KITTAN J J , PABCIAK,W J Region 1. Dffice of Director B4/02/27 3pp 22643 179 24X Fiche 50-272,84/02/28, 8403150068
- B402070007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list and! GRACE, J N Division of GA. Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidate Edison Co of New York, Inc i30pp 22552 329 24X Fichs 30-000.84/03/02,8402090007
- 8402070008 IE info Notice 84-16, "Failure of Automatic Sprinkier Sys Valves to Operate " Svc list encl JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24% Ficha 50-000,84/03/02,8402070008
- 8402070009 IE Info Notice 84-15, "Reporting of Radiological Releases" 102070009 IE Info Notice Ba-10. The purching of Naviological National Sec list enci
 JORDAN.E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 Yark, Inc. 119pp 22553 217 24X Fiche 30-000,84/03/02,8402090009
- 8403220105 Forwards 1E Insp Repts 50-272/84-04 & 50-311/84-04 on 840111-0206 No violations observed BTAR081ECKL: R Division of Project & Resident Programs 84/03 UDERITY: R A Public Service Electric & Gas Co of New Jersey 22715, 285 24X Fiche 50-272, 84/03/06, 8403220105 84/03/06
- --8403220113 iE Insp Repts 50-272/84-04 & 50-311/84-04 on 840111-0206 No violations identified Major areas inspected status of previous insp items: review of periodic & special repts. LER review & operational safety verification LINVILLE, J C , 8UMMERS, R J Region i. Office of Director NORRHOLM, L J Division of Project & Resident Programs. 84/02/27 i7pp 22715, 287 24X Fiche 50-272, 84/03/06, 8403220105

- B402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown 8ys " Svc list enc1
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 840209002B IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403220006 Forwards IE Insp Repts 50-272/84-06 & 50-311/84-06 on 840206-10 No violations observed MARTIN.T T Division of Engineering & Technical Programs 84/03/08 UDERITZ,R A Public Bervice Electric & Gas Co of New Jersey 2pp 22716 174 24X Fichs 50-272,84/03/08,8403220006
- --B403220010 IE lnsp Repts 50-272/B4-06 & 50-311/B4-06 on B40206-10 No violations noted Major areas inspected security organization, security program audit testing & maint, physical barriers, security spower supply & assessment aids MADDEN, W. J. BAILEY, R. J. JOYNER, J. H. Region I. Office of Director B4/03/06 App 22716 176 24X Fiche 50-272, B4/03/08, B403220006
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUND, R C Director's Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12.8402090031
- 8403220036 Responds to IE Bulletin 83-07. "Apparently Fraudulent Products Bold By Ray Miller, Inc." Companies supplying matls or sves to facilities listed No matl purchased from Ray Miller, Inc.
 LIDEN.E A Public Service Electric & Oas Co of New Jersey 84/03/14 MURLEY, TE Region 1, Office of Director 4pp 22065, 166 24X Fiche 50-272, 84/03/14, 8403220036
- 8403290206 Forwards IE Mgt Meeting Repts 50-272/84-11 & 30-311/84-11 on 840201 Corrective actions taken for ALARA program deficiencies noted in IE Insp Repts 50-272/83-22 & 50-311/83-22 adequate MARTIN, T T Division of Engineering & Technical Programs 84/03/15 UDERITZ:R A Public Bervice Electric & Qas Co of New Jersey 2pp 22803-288 24X Fiche-50-272,84/03/15,8403290206
- --8403270210 IE Mgt Meeting Repts 50-272/84-i1 & 50-3i1/84-i1 on 84020i Major areas discussed planned improvements in program to reduce personnel occupational radiation exposure to ALARA Corrective action acceptable NIMITZ.R L . SHANBAKY.M M Region 1, Office of Director 84/03/06 3pp 22803 270 24X Fiche, 50-272,84/03/15,8403290206
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402070043
- B402090044 IE Info Notice B4-20, "Svc Life of Relays in Bafety-Related Bys " Svc list encl. JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York: Inc 135pp 22733 001 24X Fiche 50-000.84/03/21,8402090044
- 8403290135 Forwards IE Mgt Mesting Repts 50-272/84-12 & 50-311/84-12 on 840306 to discuss util action plan for improving nuclear dept operations.

 BTAROSTECKI, R Division of Project & Resident Programs 84/03/22.

 UDERITZ, R Public Bervics Electric & Oas Co of New Jersey 2pp 22807,107 24X Fichs. 50-272,84/03/22,8403290135.
- --B403290139 IE Mgt Meeting Repts 50-272/84-12 & 50-311/84-12 on B40306 Areae discussed overview of status of action plan to improve nuclear dept operations. LINVILLE, J C., NORRHOLM, L. J Region 1, Office of Director. B4/03/12 70pp 22807:109. 24X Fiche 50-272,84/03/22,8403270135.
- 8403300171 Ack receipt of 831128 & 840306 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/80-27 & 50-311/82-30 BTAROBTECKI.R. Division of Project & Resident Programs 84/03/23 UDERITZ.R.A. Public Service Electric & Oas Co of New Jersey 1p 22820:032. 24x Fichs 50-272.84/03/23.8403300171

- --8403300177 Suppls B31128 response to NRC B31026 ltr re violations noted in IE Insp Repts 50-272/83-27 & 50-311/83-30 Corrective actions emergency instruction action requirement, re reactor coolant pump shaft revised LIDEN,E A Public Service Electric & Gas Co of New Jersey 84/03/04 STAROBIECKI,R Division of Project & Resident Programs 4pp 22820 033 24X Fiche 50-272,84/03/23,8403300171
- --8403300183 Responds to NRC 831026 ltr re violations noted in IE insp Repts 50-272/83-27 & 50-311/83-30 Corrective actions emergency instruction revised to increase limits for vibration & decision made to remove action requirements LIDEN.E A Public Service Electric & Cas Co of New Jersey 83/11/28 STAROSTECKIR Division of Project & Resident Programs 3pp 22820 037 24X Fiche 50-272.84/03/23.8403300171
- 8403300180 Ack receipt of 831026 & 840306 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-311/83-18
 STARRSTECKI Division of Project & Resident Programs 84/03/23
 - 50-311/83-18
 BTAROSTECKI Division of Project & Resident Programs. 84/03/23
 UDERITZ,R A public Service Electric & Gas Co of New Jersey 1p
 22819 331 24X Fiche 50-311.84/03/23.8403300180
- --8403300186 Responds to NRC 830926 ltr re violations noted in IE Insp Rept 90-311/83-18 Corrective actions shift supervisor counseled re actions Maint supervisors reinsturucted on keeping operating shift informed of plant status LIDEN.E A Public Service Electric & Cas Co of New Jersey 84/03/06 MURLEY.T & Region 1, Office of Director 3pp 22819 332 24X Fiche 50-311,84/03/23,8403300180
- ---8403300170 Responds to NRC 830726 ltr re violations noted in IE Insp Rept 50-311/83-18 Corrective actions shift supervisor counseled re actions Maint supervisors reinsturucted on keeping operating shift informed of plant status UDERITZ.R A Public Service Electric & Gas Co of New Jersey 83/10/26 MURLEY.T E Region I Office of Director 3pp 22819 335 24X Fiche 50-311.84/03/23.8403300180
- R Periodic operating reports & related correspondence
- 8403070305 Personnel exposure rept for 1783 W/840223 ltr MIDURA,H J Public Service Electric & Gas Co of New Jersey 83/12/31 MURLEY,T E Region i, Office of Director 7pp 22546 335 24X Fiche 50-272,83/12/31,8403070303
- 8403070260 Forwards "Salem Nuclear Generating Station Semiannual Radioactive Effluent Release Rept.Jul-Dec 1983," interim rept Effluent data for Fourth Guarter 1983 incomplete Revised rept expected by 840415 LIDEN.E A Public Service Electric & Oas Co of New Jersey 84/02/29 HURLEY.T Region 1, Office of Director 2pp 22546 232 24X Fiche 50-272.84/02/29,8403070260
- ---8403070261 "Salem Nuclear Generating Station Semiannual Radioactive Effluent Release Rept, Jul-Dec 1983." Interim rept * Public Service Electric & Gas Co of New Jersey RERR-151 83/12/31 48pp 22546 234 24X Fiche 50-272,84/02/29,8403070260
- 8403220142 Monthly operating rept for Feb 1784 W/840310 ltr MILLER.L K., ZUPKO, J M. Public Service Electric & Gas Co. of New Jersey 84/02/29 8pp 22714 309 24X Fiche 50-311,84/02/29, 8403220142
- 8 Reportable occurrences, LERs & related correspondence
- 8211120256 Discusses 820307 & 0718 events re loss of vital bus 2A Design change request issued to install noise suppression circuitry in safeguard equipment control sys during Jan 1983 refueling outage CHIRAMAL,M Director's Office 82/11/09 SEYFRIT,K V Reactor Operations Analysis Branch 5pp 22775-247 24% Fiche 50-311.82/11/09.8211120256
- B309240515 Forwards "Load Reduction Transient at Salem Nuclear Power Plant,Unit 2 on B20114," engineering evaluation Event was significant operacing experience which should be included in forthcoming issue of Fower Reactor Events TREHAN,N.K. Reactor Operations Analysis Branch B3/09/08 BEYFRIT.K.V. Reactor Operations Analysis Branch ip 22743.001 24X Fithe 50-311,83/09/08.8309260515
- --8309260510 "Load Reduction Transient at Salem Nuclear Power Plant. Unit 2 on 820114," engineering evaluation, TREHANN K. Reactor Operations Analysis Branch 83/09/30 23pp 22743 002 24X Fiche 50-311.83/09/08.8309260515

- 103130384 LER 84-002-00 on 840209. RHR common suction valve 2RH1 inadvertently shut, resulting in loss of RHR flow through RCB Caused by briel covers not removed to reflect release of breaker tags WA640309 ltr RUPP, J L , ZUPKD, J M Public Service Electric & Gas Co of New Jersey 84/03/09 5pp 22604 357 24X fiche 50-311,84/03/09,8403103384
- 103220039 LER 84-003-00 on 840215, pressurizer overpressure protection systematical due to induced pressure transient Caused by starting reactor coolant pump Operating Procedure GPII-1 3 4 amended W/840315 1tr RUPP, J L , ZUPKD, J M Public Service Electric & Gas Co of New Jersey 84/03/15 4pp 22712 140 24X Fiche 50-311, 84/03/15, 8403220039
- IO322015i LER 84-004-00 on 840214, diesel generator 28 failed to start Caused by fuel vil supply valves being shut on 840212 due to fuel oil leak developing on one cylinder Procedures revised M/840315 tr RUPP.J L . ZUPKO.J M Public Service Electric & Gas Co of New Jersey 84/03/15 4pp 22714 331 24% Fiche 50-311,84/03/15,8403238191
- O3270099 LER 84-005-00 on 840222 generator output breaker tripped on overcurrent Caused by overcurrent relay not fully resetting following reactor coolent pump start Survelllance test run satisfactorily performed W/840323 ltm RUPP.J L , ZUPKG.J M Public Service Electric & Gas Co of New Jersey 84/03/23 Spp 22766 351 24x Fiche 50-311,84/03/23,8403270099

Congressional/Executive Correspondence

- O3150336 Responds to 840131 request for explanation of recent facility annual review Personnelingt & organization attitudes affected low rating If performance unacceptable, immediate enforcement action will be taken DIRCKS: M J Defice of the Executive Director for Operations 84/03/06 R0IM, W V Senate 2pp 22449 265 24X Fiche 50-272.84/03/06.8403150336
- 8403130341 Requests explanation of implications of rating of unsatisfactory in area of plant operations ROTH.H V Senate 84/01/31 PALLADIND.N J Commissioners 3p; 22649 268 24% Fiche 50-272, 84/03/06.8403150336

Operator Examinations

- O3040312 Responds to B40124 ltr re licensed operator requalification program Quizzes used to determine weaknesses & need for emphasis on subjs Licensed operator training program training Procedure TP-305 revised
 LIDENLE A Public Service Electric & Gas Co of New Jersey B4/02/28 VARGALS A Assistant Director for Operating Reactors 2pp 22515 333 24X Fiche 50-272.84/02/28.8403060312
- CKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION
 Security, medical, emergency & fire protection plans
- 3403020117 Revised State of CA nuclear power plant emergency response plan # California, State of 83/04/30 2901pp 22353 003 24X Fiche 50-000,84/02/16,8402230176
-)3120339 Forwards order confirming util commitments to implement tost-TMI-related items set forth in Suppl 1 to NUREO-0737. 'Requirements for Emergency Response Capability " Order lased on util 821217 response to Generic Ltr 82-33 TOLZ.J F Operating Reactors Branch 4 84/02/21 RODRIGUEZ.R J lacramento Municipal Utility District Spp 22615 320 24X Tiche. 50-312.84/02/21.8403120339
- -403120342 Order confirming licensee commitments on emergency response capability per Suppl 1 to NUREQ-0737
 EISENRUT.D G Division of Licensing 84/02/21 Sacramento Municipal Utility District App 22415 323 24X
 Fiche 50-312,84/02/21,8403120339

- 8403040387 Informs that matis on order to support 1984 refueling outage to perform alternative shutdown panel mod Generic Ltr 84-09 factored into reevaluation efforts re App R campliance ROBRIGUEZ, R J Sacramento Municipal Utility District 84/02/29 STGLZ, J F Operating Reactors Branch 4 2pp 22511 352 24X Fiche 50-312.84702729.8403040387
- J Insurance & indomnity information
- 84030å0i41 Forwards Endorsements 66 & 67 to NELIA Policy NF-212, Endorsement 4 to NELIA Policy N-49.Endorsements 56 & 57 to MAELU Policy MF-75 & Endorsement 4 to MAELU Policy M-49 LATHAM. W K Sacramenta Municipal Utility District 84/02/28 SALTZMAN. J B NRC - No Detailed Affiliation Given 7pp 22506 356 24X Fiche 50-312.84/02/28.84030&0141
- B403260124 Forwards Endorsements 38 & 68 to MAELU Policy MF-75 & NELIA Policy NF-212, respectively MATTIMOE, J J Bacramento Municipal Utility District 84/03/08 SALTIMON, J B NRC No Detailed Affiliation Given 3pp 22758
- P Operating license stage documents & correspondence
- B4030i0117 FOLA request for studies performed by USGS & State of CA Div of Mines & Geology re facility seismic design CALSOYAS.C D Affiliation Not Assigned B3/11/14 NRC No Detailed Affiliation Given 4pp 22444 345, 24x Fichs 50-312.83/11/14.8403010117
- B403010123 Responds to FDIA request for studies performed by USOB L State of CA Div of Mines & Quology re facility seismic design Forwards App A documents Info also available in PDR FELTON, J M Division of Rules and Records 83/12/20 CALSOYAS, C D Affiliation Not Assigned 3pp 22444 349 24X Fiche 50-312,83/12/20.8403010123
- --7906140545 Summary of telcon to provide response to 790413 ltr requesting info re selsmic analysis GARNEGID Operating Reactors Branch 4 (Pre 790625) 79/04/25 REID: R W Operating Reactors Branch 4 (Pre 790625) lp 22444 352 24X Fiche 50-312,63/12/20.8403010123
- --790614054B Discusses review of plant earthquake design criteria & requests info re selsmic analysis
 DAVIS, J F California, Btate of 79/04/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22444 353 24X Fiche 50-312, 83/12/20, 8403010123
- --7910260122 Summarizes view of recent fault data.NRC requirements & fact that FBAR considered only three faults active Recommends that new info on fault sys be assessed MINOGUE.R 3 Office of Standards Development. Director 79/10/01 DENTON; HR Office of Nuclear Reactor Regulation, Director 4pp 22444 338 24X Fiche 50-312.83/12/20,8403010123
- --79i11203i7 Forwards RB Minogue 79i00l memo to HR Denton & evaluation of relevancy to proceedings before ASLB EISENHUT.D 0 Division of Operating Reactors 79/10/19 SCOTT,S Distribution Services Branch 3pp 22444 355 24X Fiche 50-312,83/12/20,8403010123
- --7911120366 Forwards solsmicity rept re Sacramento County, CR & portions of 680816 CA application & 730608 safety evaluation TISDN, J C Commerce, Dept of. 68/07/05 PRICE, H L Atomic Energy Commission, Directorate of Regulatory Operations ip 22445 085 24X Fiche 50-312,83/12/20.8403010123
- --7911120370 Requests add1 info to complete review of initial site examination info data form DEYOUNG,R C Atomic Energy Commission, Directorate of Licensing 74/12/13 DAVIS,E K Sacramento Municipal Utility District 2pp 22445 028 24X Fiche 50-312,83/12/20,8403010123
- --79ii120413 Responds to 760115 ltr re DL Kelleker 751217 concern about nuclear plant in Orville, CA vicinity No plant planned for area Discussed DBE re plant design DIRCKB, W J NRC No Detailed Affiliation Given 76/02/04 CRANBTON, A Senate 3pp 22445 041 24X Fiche 50-312,83/12/20,8403010123
- --B00127031i Forwards response to 77100i memo re geologic & seismic reassessment of facility No immediate hazard at site Licensee should undertake program to assemble & assess new info re geology & seismology of site region JACKBGN: E Goosciences Branch 77/12/21 GAMMILL. W P Assistant Director for Standard & Advanced Reactors 70p 22445 050 24X Fiche 50-312,83/12/20.8403010123

- --80092:0342 Recommends meeting w/util to review progress of selsmic assessment study
 JACKBON, R E Geosciences Branch 80/09/12 REID, R W Operating
 Reactors Branch 4 ip 22445-057 24X Fiche 50-312.83/12/20.
 8403010123
- --B009250345 Discusses util response to NRC request for seismic reassessment Seven listed areas of info should be directed to util to avoid delay in reviewing rept ALTERMAN.I B Geosciences Branch 80/09/12 JACKSON,R E Geosciences Branch 3pp 22445 058 24X Fiche 50-312,83/12/20,8403010123
- --8403010150 Forwards evaluation of Unit 2 initial site exam info data review Site safety members participating in review listed DENTON-H R Atomic Energy Commission, Directorate of Licensing 74/10/10 DEYOUNG/R C Atomic Energy Commission, Directorate of Licensing 4pp 22445 046 24X Fiche 50-312.83/12/20.8403010123
- 8403010117 Partial response to FOIA request for documents by named individuals re repts, analyses, studies, procedures & sys for measurement of RCS leakage App B documents placed in PDR App A documents already available in PDR Search continuing FELTON.J M Division of Rules and Records 84/01/25 MADDEN.T J Kaye. Scholer, Fierman, Hays & Handler 7pp 22480 026 24X Fiths 50-000,84/01/25,8403010117
- --B3111504Bi Forwards results of review of RCS leak rate test procedures & calculational methods used in 1978 at two randomly selected BWR plants.per 830920 request Deficiencies discovered during trial use period corrected DEYOUND.R C Director's Office. Office of Inspection and Enforcement B3/11/07 DIRCKS,W J Office of the Executive Director for Operations 22pp 22482 020 24x Fiche 50-000,84/01/25,8403010117
- --8403010233 Discusses RC6 leak rate calculations.per 820504 telcon Mods to RCSLK7 computer program permit leak rate calculations for pressures between 1,900 & 2,100 psig w/temp between 260 F & 270 F Plant data encl MORRILL.P J Region 5, Office of Director 82/05/05 WOODRUFF,R W Reactor Engineering Branch 17pp 22481 362 24X Fiche 50-000,84/01/25,8403010117
- 8403050223 Further response to FOIA request for records of named individuals including repts, analyses studies, test calculations, procedures & practices for measurement of RCS leakage Forwards App C documents Search continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN, T J Kaye, Scholer, Fierman, Hays & Handler 3pp 22476 234 24% Fiche 50-000,84/02/07,8403050223
- --B403050250 Forwards plant-specific date cards for facilities re reactor coolant leakage calculations.per 810902 request Add1 date cards for remaining plants will be sent shortly CREWB.J L. Division of Resident, Reactor Projects & Engineering Inspection B1/09/16 BAER.R L Division of Resident & Regional Reactor Inspection 2pp 22496 248 24X Fiche 30-000.B4/02/07.B4/03050223
- 8403010494 Forwards request for add1 lnfo re Vol 1 to Cycle 7 reload rept Schedule for response requested within 14 days of itr receipt STOLZ,J F Operating Reactors Branch 4 84/02/15 RODRIGUEZ,R Bacramento Municipal Utility District 3pp 22438 306 24X Fiche 30-312:84/02/15,8403010494
- 8403010388 Responds to Generic Ltr 83-41 re fast cold starts of diesel generators Diesel generators A & B fast started 15 times between 830201 & 840215 for surveillance testing Diesel vendor recommends idle start over fast-start & load RODRIGUEZ,R J Sacramento Municipal Utility District 84/02/21 E18ENHUT,D 9 Division of Licensing 1p 22434 047 24X Fiche 50-312,84/02/21,8403010388
- B403010374 Forwards Amend 53 to License DPR-54 & safety evaluation Amend implements requirements of App I to 10CFR50. establishes new limiting conditions for quarterly & annual release rates & revises environ monitoring program MINER.B Operating Reactors Branch 4 84/02/22 RODRIGUEZ.R J Bacramento Municipal Utility District 2pp 22449 011 24x Fichs 50-312.84/02/22,8403010374
- --8403010377 Amend 33 to License DPR-54, implementing requirements of App I to 10CFR50, establishing new limiting conditions for quarterly & annual release rates & revising environ monitoring program GTULZ, JF Operating Reactors Branch 4 84/02/22 101pp 22449 013 24X Fiche 50-312,84/02/22,8403010374
- --8403010378 Safety evaluation supporting Amend 33 to License DPR-54 * Office of Nuclear Reactor Regulation, Director 84/02/22 23pp 22449 114 24X Fiche 50-312,84/02/22,8403010374

- 8403020350 Responds to Generic Ltr 84-0; re use of terms important to safety & safety-related Accepts opportunity to discuss subj further Participation in discussion will be through steering committee of Util Safety Classification Group RODRIGUEZ.R J Sacramonto Municipal Utility District 84/02/28 TAYLOR, JM Director's Office Office of Inspection and Enforcement ip 22439 022 24% Fiche 50-312,84/02/28,8403020350
- B403050007 Application for Proposed Amend 103 to License DPR-54, changing quarterly calibr requirements for area monitors R-15023, R-15026 & R-15027
 LATHAM.W Sacramento Municipal Utility District 84/02/28
 EISENHUT, D G Division of Licensing 4pp 22470 190 24X
 fiche 30-312,84/02/28,8403050007
- --8403050008 Proposed Tech Spec re change to quarterly callbr requirements for area monitors R-19025,R-15026 & R-15027 * Sacramento Municipal Utility District 84/02/28 ip 22490 194 24X Fiche 50-312,84/02/28,8403050007
- --8403050010 "Safety Evaluation to Support Changing Guarterly Calibr Requirement for Area Monitors R-15025.R-15026 & R-15027 " * TERA Corp 82/01/26 3pp 22490 195 24X Fiche 50-312.84/02/28.8403050007
- 8403120302 Requests remittal of Class III fee for review of 840123 application for Tech Spec changes re NUREQ-0737 requirements
 DIGGS,R M License Fee Management Branch 84/03/01 RODRIQUEZ.R Sacramento Municipal Utility District ip 22596 360 24X
 Fiche 30-312.84/03/01,8403120302
- 8403130125 Forwards add1 info re Cycle 7 reload rept, Vol 1.per 840215 ltr Structural characteristics of racking & crushing failure modes illustrated RODRIGUEZ, R J Sacramento Municipal Utility District 84/03/06 STOLZ, J F Operating Reactors Branch 4 3pp 22601 334 24x Fiche 50-312, 84/03/06,8403130125
- 8403200001 Forwards fee payment to cover 840228 proposed Amend 103 to License DPR-54 CQLOMBO,R W Sacramento Municipal Utility District 84/03/14 MILLER, W O License Fee Management Branch 1p 22685 211 24X F1che 50-312-84/03/14.8403200001
- 8403260215 Forwards Class III fee for proposed Amend 100 to License DPR-54, per 840123 ltr. in response to NRC 840301 request RODRIGUEZ, R J Sacramento Municipal Utility District 84/03/21 MILLER, W O License Fee Management Branch 1p 22756 161 24X Fiche 50-312-84/03/21,8403260215
- G Inspection reports, IE Bulletins & correspondence
- B4030B040B FD1A request for repts of insp carried out under Condition 2 of Nuclear Energy Liability policies for facilities CALBOYAS,C D Affiliation Not Assigned 84/02/07 Region 5, Office of Director 4pp 22567 341 24X Fiche 50~000,84/02/07, 8403080408
- B403060401 Forwards IE Insp Rept 50-312/83-37 on B31227-29 Insp performed re allegations concerning processing electrical cable pull cards B16HDP.T W Region 5. Office of Director 84/02/17 RODRIGUEZ, R J Bacramento Municipal Utility District 2pp 22518 276 24X Fiche 50-312,84/02/17,8403060401
- --8403060406 IE Insp Rept 50-312/83-37 on 831227-29 Major areas inspected allegations re electrical cable pull card inadequacies Allegations substantiated BURDDIN, J F. KIRSCH. D F. Region 5, Office of Director 84/02/15 5pp 22518 278 24X Fiche 50-312,84/02/17,8403040401
- 8403130498 Forwards IF Performance Appraisal Rept 50-312/83-35 on 831107-18 & 28-1201 Requests response within 60 days reactions taken to improve mgt controls in areas of GA audits & plant operations PARTLOW, J 0 Division of GA. Safeguards & Inspection Programs (Post 830103) 84/02/17 RODRIGUEZ/R Sacramento Municipal Utility District 6pp 22634 353 24X Fichs 50-312,84/02/17,8403130498
- --B403130479 IE Performance Appraisal Rept 50-312/83-35 on 831(07-18 & 28-1201 Major areas inspected licenses mgt controls over selected licenses activities HINCKLEY.D Q , WOESSNER.J D , FOSTER.L E Division of GA, Safeguards & Inspection Programs (Post 830103) 84/01/27 52pp 22634 359 24X Fiche 50-312,84/02/17.8403130498
- 8403080061 Forwards IE Insp Rept 50-312/84-01 on 840116-20 & 26 & telcons on 840131,0202 & 20 No noncompliance noted WENNLAWSKI,F A Region 5, Office of Director 84/02/21 RODRIGUEZ,R J Secremento Municipal Utility District 1p 22559 246 24X Fiche 50-312,84/02/21,8403080061

- --B403080075 IE lasp Rept 50-312/B4-01 on 840116-20 & 26 & telcons on 840131.0202 & 20 No noncompliance or deviations noted Major areas inspected items of noncompliance & radwaste audit of solid-liquid & gaseous radwaste processing NORTH-H S · WENSLAWBKI.F A Region 5. Office of Director 84/02/21 10pp 22559 247. 24% Fiche 50-312.84/02/21.8403080061
- 3403080419 Responds to FOIA request for repts of insp carried dut under Condition 2 to Nuclear Energy Liability policies for facilities NRC does not have repts FELTON. J M Division of Rules and Records 84/02/22 CALSDYAS. C D Affiliation Not Assigned. 1p 22567 345 24x Fiche 50-000.84/02/22.8403080419
- 1403080274 Forwards IE Insp Rept 50-312/83-36 on 831205-840110 & notice of violation BISHOP.T W Region 5. Office of Director 84/02/23 RODRIGUEZ.R Sacramento Municipal Utility District 2pp 22557 277 24X Fiche 50-312.84/02/23.8403080274
- --8403080274 Notice of violation from lnsp on 831205-840110 YOUNG,T Region 5, Office of Director 84/02/23 2pp 22557 279 24% Fiche 50-312.84/02/23,8403080274
- --8403080279 IE Insp Rept 50-312/83-36 on B31205-B40110 Noncompliances noted failure to follow temporary change procedure & failure to comply w/surveillance procedure spec for operability of pressurizer level instruments

 CANTER.H L PEREZ.O P . YOUNG.T Region 5. Office of Director B4/02/22 13pp 22357 2B1 24X Fiche 50-312. B4/02/23. 2403080274
- B401190072 IE Info Notice B4-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunclation " Svc 11st encl
 JORDAN, E L Division of Emergancy Preparedness & Engineering
- JORDAN.E L Division of Emergancy Preparedness & Engineering Response (Post B30103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- B402090007 IE Info Notice B4-14. "Highlights of Recent Transport Regulatory Revs by DDT & NRC." Svc list encl GRACE.J N Division of GA: Safeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York: Inc 130pp 22552 329 24% Fiche 50-000.84/03/02.8402090007
- 3402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 22553 098 24% Fiche 50-000,84/03/02,8402090008
- 3402090007 IE Info Notice 84-15. "Reporting of Radiological Releases " Svc 11st encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 117pp 22553 217 24X Fiche 50-000.84/03/02,8402090007
- 3402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Capling Components Below NiI Ductility Temp " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553.336 24X Fiche 50-000,84/03/05,8402070011
- 3402090024 IE Info Notice 84-09.Rev 1. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svr list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24x Fiche 50-000.84/03/07,8402090024
- 3402090028 IE Info Notice 84-iB, "Stress Corrosion Cracking in PWR Sys " Bvc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22384 186 24X Fiche 30-000,84/03/07,8402090028
- 1403130343 Confirms 840323 meeting in Walnut Creek.CA to discuss SALP rupt for Oct 1982 Nov 1983 Agenda encl BISHOP.T W Region 5. Office of Director 84/03/09. HATTIMDE,J J Bacramento Monicipal Utility District. 2pp 92617 196 24X Fiche 50-312.84/03/09.8403130343
- --8403130352 Notification of significant licenses meeting on 840323 in Walnut Creek.CA to discuss SALP rept for Oct 1982 - Nov
 - * Region 5, Office of Director 84/03/09, Region 5, Office of Director ip. 22617 198. 24X Fiche 50-312,84/03/09,8403130343
 - nv 1983 1/01/18 34pp 22617:199 24X

- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Gys " Svc list encl DEVOUNO.R C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fichs 50-000.84/03/12,8402090031
- 8403190275 Forwards "Anticipated Performance Behavior of Auxiliary Faedwater Pumps Under Extreme Conditions W/Main Steam Line Break W/Both Nuclear Steam Generators at Atmospheric Pressure." per response to IE Bulletin 80-04 RDDRIGUEZ.R J Sacramento Municipal Utility District 84/03/17 STOLZ.J F Operating Reactors Branch 4 ip 22672 287 24X Fichs 50-312-84/03/19,8403190275
- --8403190282 "Anticipated Performance Behavior of Auxiliary Feedwater Pumps Under Extreme Conditions W/Main Steam Line Break W/ Both Nuclear Steam Generators at Atmospheric Pressure " MAKAY.E Energy Research & Consultants Corp ERCO-693 84/02/16 27pp 22672 288 24X Fiche 50-312,84/03/19,8403190275
- 8402090043 IE Info Natice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavitles " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24% Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list enc! JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- R Periodle operating reports & related correspondence
- 8403200045 Monthly operating rept for Feb 1984 W/840304 ltr COLOMBO.R , RODRIGUEZ.R J Sacramento Municipal Utility District B4/02/29 7pp 22685 138 24% Fiche 50-312.84/02/29,8403200045
- B Reportable occurrences, LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval. Inc DIRCKS.W J Office of the Executive Director for Operations SECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000.84/01/25.8403010451
- 8403230056 Part 21 rept re Westinghouse mechanically Interlocked full voltage reversing starters not maintaining required relative positions Caused by assemblurs incorrectly removing backing plates RODRIGUEZ, R J Sacramento Municipal Utility District 84/02/15, MARTIN, J D Region 5. Office of Director 5pp 22726 345 24% Fiche 50-312-84/02/15,8403230056
- 8403210032 Part 2: rept re failure of auxiliary feedwater pump drive turbines, Gimpel NPS-4 T&T valve to close Encl ltr dtd 840203 sent to listed utils GE notlfied of affected units in BWR plants
 THEROUX, R R Terry Corp 84/02/22 WOODRUFF, R W Director's Office, Office of Inspection and Enforcement App 22706 327 24X Fichs 50-000,84/02/22,8403210032
- B403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval, inc Owners Group program commitments. Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations MUSELER, W J DI (Transamerica Delaval, Inc.) Owners Group B4/02/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22434 090. 24% Fiche 50-000,84/02/27,8403010207
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval, inc emergency diesel generators MUSELER.W J TDI (Transamerica Delaval, Inc.) Owners Group 84/02/28 DENTON.H R Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Fiche 50-000.84/02/28,8403010218
- 8403260233 Forwards summary list of deficiencies identified per IOCFRSD 35(e).Part 21 & potential generic itr repts for comments

 STAROSIECKI,R Division of Project & Resident Programs, 84/02/28, Region 1, Office of Director. 7pp 22756.065 24X Fichs 30-000.84/02/28.8403260230
- 8403050452 LER 84-004-00 on 840124, power supply for meteorological tower instrumentation failed Caused by temporary overhead feeder experiencing severe spikes & switching transients Power supply repaired M/840301 ltr COLOMBO,R W . MATTIMOE, J J Sacramento Municipal Utility District. 84/03/02 MATTIM, J B Region 5. Office of Director 3pp 22511 341 24X Fiche 50-312,84/03/02,8403040452

- 8403060467 LER 84-006-00 on 840131.plant mgt notified that for calendar training yr 1983.23 operators & 16 security personnel did not attend quarterly class training session Caused by schaduling problems W/840301 itr COLUMBG.R W. MATTIMOS.J J Bacramento Municipal Utility District 84/03/02 MARTIN.J B Region 9. Office of Director 3pp 22007 001 24X Fiche 50-312.84/03/02.8403060467
- 840314004B Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Bys" & "Transamerica Delavai, Inc.
 Dizzel Generators Comers Group Program Plan," to resolve concerns W/emergency dissel generators
 MUERLER, W.J. Long Island Lighting Co. 84/03/02 DENTON, H.R.
 Office of Nuclear Reactor Regulation, Oirector 2pp 22626 062
 24X Fichs 30-000,84/03/02,8403140048
- --8403140095 "Transamerica Delaval. Inc Diesel Generators Dwners Group Program Fian " * TDI (Transamerica Delaval, Inc) Owners Group 84/03/02 261pp 22628-223 24X Fichs 50-000.84/03/02.8403140048
- 8403130112 Forwards tentative schedule for responding to NRC questions re Transamerica Delaval diesel generators, per 840131 ltr Delays or changes in owners group qualification program could change schedule RODRIGUEZ, R J Sacramento Municipal Utility District 84/03/05 BTGL7.J F Operating Reactors Brench 4 3pp 22613 292 24X Fiche 30-312,84/03/05,8403130112
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Owners Group Distribution list encl.

 EIBENHUT, D. Q. Division of Licensing 84/03/12 PALLADIND Commissioners 5pp 22708 001 24X Fiche 50-000,84/03/12,8402090039.
- --B403060536 Forwards summary of B40210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency dissel generators CARUSO, R Licensing Branch 2 84/02/27 D'REILLY, J P NRC No Datailed Affiliation Given 6pp 22708 006, 24X Fiche 50-000, 84/03/12, 8402090039
- --8403060554 Transcript of 840210 maeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency dissel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 OOB 24X Fiche 50-000,84/03/12,8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica belaval, Inc Owners Oroup in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl
 MILLER, H A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 50-000,84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval,Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche: 50-000,84/03/12,8402090039
- 8403140050 Forwards "Design Revisw of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Orand Gulf diesel generators

 MUBELER, W. J. Long Island Lighting Co. 84/03/12 DENTON, H.R.

 Office of Nuclear Reactor Regulation: Director 2pp R2632 074

 24X Fiche 50-000,84/03/12,8403140050
- 8403150133 Porwards "Transamerica Delaval, Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept." Capscrew design adequate for applicable engines & svc conditions MUSELER: W J TDI (Transamerica Delaval, Inc.) Owners Group MUSELER: W J. Long Island Lighting Co 84/03/13 DENTON. H R Office of Nuclear Reactor Regulation, Director 2pp. 22437-270 24X Ficha 50-000,84/03/13,8403150133.
- B403200184 Forwards procurement spec to which Transamerica Delaval standby diesel generators ordered in response to NRC 840131 request RODRIGUEZ, R. J. Bacramento Municipal Utility District 84/03/15 BTOLZ, J. F. Operating Reactors Branch 4 337pp 22886 001 24 Fiche. 50~312.84/03/15.8403200184
- B403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series angines List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started encl.

 MATHEWS: C B. Transamerica Delaval, Inc 84/03/16 EISENHUT, D G Division of Licensing 20pp. 22671 177 24X Fiche 50-000,84/03/16,8403200222

- 8403230117 PND-V-84-016 on 840319 hydrogen explosion occurred in main generator Caused by circuit breaker trip shutting down hydrogen seal oil pump. resulting in hydrogen leak Manual safety injection to seal oil tank initiated NARBUT, P. ECKHARDT, J. Region 3, Office of Director 84/03/20 ip 22730 335 24X Fiche 50-312,84/03/20.8403230[17]
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by S&W for Transamerica Delaval, Inc (TDI) Diesel Generator Owners Oroup MUBELER, W J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/23 DENYON, H R Office of Nuclear Reactor Regulation, Director 2pp 22774 001 24% Fische 30-000, 84/03/23, 8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica
 Delaval diesel generators List of suggested meeting topics encl
 MCGAUGHY, J P TD1 (Transamerica Oslaval, Inc.) Clumers Group
 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 4pp 22769 i33 24X Fiche 50-000,84/03/23,8403270134

T Hearing transcripts on non-antitrust matters

- 8402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Owners Group Distribution list encl
 EISENHUT, D 0 Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22708 001 24X Fiche \$0-000,84/03/12,840207039
- --8403060336 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Owners Oraup in Bethesda-MD re problems w/emergency
 diesel generators
 CARUSO.R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No
 Detailed Affiliation Olven 6pp 22708 006 24X
 Fiche 50-000.84/03/12.8402090037
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Betheida, MD re problems w/emergency diesel generators * NRC - No Oetailed Affiliation Olven 84/02/10 147pp 67201 008 24X Fiche 50-000.84/03/12,8402090039
- ~-8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River.NY re program plan to establish reliability of diesel generators Agenda.meeting transcript & attendance list encl
 HTLLER.M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 30-000.84/03/12,8402090039.
- ~-8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval. Inc. diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000.84/03/12.8402070037

DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

F Security, medical, emergency & fire protection plans

- 8403130437 Documents results of activities conducted during 831031-1104 IE insp to review open items re emergency planning Commitment status to resolve items provided Expeditious actions by NRC to remove items requested MARSHALL.JR Arkansas Power & Light Co 83/12/09 COLLINS.JT Region 4. Dffice of Director 15pp 22613 233 24X Fiche 50-313.83/12/09.8403130437
- 8403090301 Public version of Rev 11 to Emergency Plan Implementing Procedure 1903 10, "Emergency Action Level Response " W/ 831220 transmittal form & JM Felton release memo LEVINE, J M Arkansas Power & Light Co 83/12/17 4pp 22384 346 24X Fiche 30-313-83/12/17,8403090301
- 8403120011 Forwards Amend 10 to emergency plan W/o encl MARSHALL.J R Arkansas Power & Light Co 84/01/20 COLLINS.J T Region 4: Office of Director 1p 22585 221 24X Fiche 50-313.84/01/20.8403120011
- B403280074 Public version of Amend 10 to emergency plan W/840120 ltr & JM Felton B40322 release memo MARSHALL.J R Arkansas Power & Light Co B4/01/20 COLLINS.J T Ragion 4. Office of Director 5pp 22812 288 24% Fiche 50-313,84/01/20,8403280094

- 8403130473 Submits response to Hakney request for addlinfo re emergency plan training for non-util employees Vendors & contractors w/unescorted access within protected area receive training commensurate w/job assignments MARSHALL.JR Arkansas Power & Light Co 84/01/24 GAGLJARDO,J E Division of Resident, Reactor Project & Engineering Programs ip 22613 330 24% Fiche 50-313,84/01/24,8403130473
- 8403200174 Amend 11 to emergency plan W/B40314 ltr MARSHALL,J R Arkansas Power & Light Co 84/02/06 EISENHUT,D 0 Defice of Nuclear Reactor Regulation, Director Spp 22689 312 24x Fiche 50-313.84/02/06.8403200174
- B403030142 Notifies that NRC will provide inspectors to observe onsite aspects of periodic exercises for emergency preparedness Scenerio for submission of info listed CDLLNS, JT Region 4. Office of Director 84/02/09 GRIFFIN, J M Alabama Power Co 2pp 22487 308 24X Fiche 50-313,84/02/09. B403030142
- 8403130395 Forwards IE Insp Repts 50-313/84-05 & 50-368/84-05 on 840126 No violations or deviations identified BAOLIARDO.JE Region 4. Defice of Director 84/02/16 GRIFFIN.J M Arkansas Power & Light Co 2pp 22616 323 24X Fiche 50-313.84/02/16.8403130395
- --B403130402 IE Insp. Repts 50-313/84-05 & 50-368/B4-05 on B40126 No violations or deviations identified Major areas inspected status of REX-B4 exercise scenario development HACKNEY.C A , BAIRD J B , JOHNBON W D Region 4. Office of Director B4/02/16 3pp 22616 327 24X fiche 50-313.B4/02/16.B403130395
- 0403060350 Requests approval of mod to health physics network & emergency notification sys phones from handset to headset to alleviate fatigue during continuous open-line communications maintained in emergencies

 MARBHALL.JR Arkansas Power & Light Co 04/02/17 DENISE,R P
 Division of Resident, Reactor Project & Engineering Programs 1, 22319 085 24% Fiche 50-313.84/02/17,8403060350
- 8403060430 Provides preliminary estimates for emergency operations facility mods to raise radiation protection factor to greater than or equal to five, per NUREG-0696. In response to NRC 840214 request Util will not implement mods MARSHALLJR Arkansas Power & Light Co 84/02/29 STOLZ.JF Operating Reactors Branch 4 MILLER.JR Operating Reactors Branch 3 2pp 28518 192 24X Fiche 50-313.84/02/29.8403060430
- 8403060324 Forwards proprietary Rev 12 to Procedure 1703 10, "Emergency Action Level Response" & proprietary Procedure 1904 series (1704 01.02.03.06.07 & 08), "Offsite Dose Projections" Froprietary procedures withheld # Ankansas Power & Light Co. 84/03/01 NRC No Detailed Affiliation Given 2pp 22513 333 24X Fiche 50-313.84/03/01, 8403060324
- 840307035B Public version of Rev 12 to Emergency Plan Implementing Procedure 1903 10, "Emergency Action Level Response" W/ 840209 transmitta) form & JM Felton 840302 release memo LEVINE, J & Pennsylvania Power & Light Co 8403/01 68pp 22564 227 24x Fiche 50-313,8403/01.840307035B
- 8403260090 Forwards 1E Insp Repts 50-313/84-04 & 50-368/84-04 on 840124-26 No violations or deviations identified GAGLIARDOJ E Region 4. Office of Director 84/03/05 GRIFFIN.J M Arkantas Power & Light Co 2pp 22758 271 24X Fiche 50-313.84/03/05,8403280090
- --8402260097 IF Insp Repts 50-313/84-04 to 50-368/84-04 on 840124-26 No violations or deviations identified Hajor areas inspected security organization personnel per alleged compromise of safeguards info Details withheld (ref [OCFR73 21) KELLY, JA. HALL, R. E., JUNNSCN, W.D. Region 4. Office of Director 84/03/02 ip 22758 273 24X Fichs 50-313,84/03/05,8403260090
- 8403230238 Advises that based on review of 831125 submittal of detailed control room design, specific areas of program plan do not meet requirements of Buppl i to NUREG-0737 Meeting requested to resolve deficiencies
 BTOLZ.J F Operating Reactors Branch 4 B4/03/06 GRIFFIN, J M Apkansas Flower & Light Co 2pp 22759 278 24X
 Fische 50-313.84/03/06.8403230238
- 8403190277 Notifies of error in 840216 itr transmitting IE Insp Repts 50-313/84-03 & 50-368/84-03 Ltr indicated rept numbers 30-313/83-03 & 50-368/83-03 Records should be changed accordingly GAGLIARDD. J E Region 4. Office of Director 84/03/08 GRIFFIN. J M Arkansas Power & Light Co 10 22673 190 24X Fiche 50-313.84/03/08.8403190227

- --8403190283 Forwards IE Insp Repts 50-313/84-03 & 50-368/84-03 on 840125 No violations or deviations noted GAOLIARDD. J. E. Region 4. Defice of Director 84/02/16 GRIFFIN. J. H. Arransas Power & Light Co. 2pp. 22673 191 24X Fiche 50-313.84/03/08.8403190277
- ---8403170288 IE Insp Repts 50-313/84-03 & 50-368/84-03 on 840125 No violations or deviations noted Major areas inspected actions taken as result of discrepancy between public info brochure & Jan 1984 telephone directory for emergency planning zone HACKNEY, C A . BAIRD, J B . JD;NSDN, H D . Region 4, Dffice of Director 84/02/16 3pp 22673 173 24X Fiche 50-313,84/03/08,8403170277
- 8403150113 Forwards exercise repts of 820519 & 830316 joint exercises of offsite radiological emergency preparadiess plans for Arkansas Nuclear One Power Station Deficiencies observed at both exercises Approval under FEMA Rule 44GFR330 in effect KRIMM.R W Federal Emergency Management Agency 84/03/09 JORDAN, E L Division of Emergency Preparadiess & Engineering Response (Post 830103) 2pp 22640 001 24X Fiche 50-313.84/03/09, 8403150113
- --8403150119 Exercise repts of 820519 & 830316 joint exercises of offsite radiological emergency preparedness plan for Arkansas Nuclear One Power Station KRIMM.R W Federal Emergency Management Agency 84/03/09 45pp 22640 003 24X Fiche 50-313,84/03/09.8403150113
- 8403200246 Forwards Amend 4 to nuclear contingency plan, Rev 4 to
 Nuclear Contingency Plan Procedures 1,2,3,7 & 9, Rev 3 to
 Procedures 5,6,8 & 11.Rev 2 to Procedures 4 & 13 & Rev 1 to
 Procedure 15
 MARSHALL,JR Arkansas Power & Light Co 84/03/14 EISENHUT, D 0
 Office of Nuclear Reactor Regulation, Director 1p 22688 027 24X
 Fiche 50-313,84/03/14.8403200246
- ---8403200251 Rev 4 to nuclear contingency plan * Arkansas Power & Light Co 84/02/06 49pp 22688 020 24% Fiche 50-313,84/03/14,8403200246
- --8403200258 Revs 4,3,2 & 1 to Nuclear Contingency Plan Implementing Procedures 1,2,7 & 9,5,4,8 & 11.4 & 13 & 15, respectively, reassignment of personnel to emergency response organization, notification & command & control # Arlansas Power & Light Co 84/03/15 143pp 22688 077 24X Fichs 50-313,84/03/14,8403200246
- 8403200179 Forwards Amend 11 to emergency plan & Amend 4 to nuclear contingency plan MARGHALL,J R Arkansas Power & Light Co 84/03/15 GULLINS,J T Region 4. Office of Director 1p 22689 120 24X Fichs 50-313,84/03/15,8403200179
- --84032001B0 Amend 11 to emergency plan & Amend 4 to nuclear contingency plan * Arkansas Power & Light Co 84/02/06 57pp 22689 121 24X Fishe 50-313,84/03/15,8403200179
- --8403200181 Rev 4 to Nuclear Contingency Plan Implementing Procedure 1.
 "Assignment of Personnel to Emergency Response
 Dryantization "
 * Arkansas Power & Light Co 84/02/04 137pp 22489 177 24X
 Fiche 50-313,84/03/15,8403200179
- 8403220185 Responds to 840217 request for relocation of HPN telephone in emergency control ctr & for approval to add headsets Request forwarded to Telecommunications Branch Headset mod approved GAOLIARDO, J E Region 4. Office of Director 84/03/19 ORIFFIN.J M Arkansas Power & Light Co 1p 82717,035 24X Fichs 50-313,84/03/19,8403220185
- P Operating license stage documents & correspondence
- B403050179 Application for amend to License DPR-51, updating Figures 3 1 2-1,3 1 2-2 & 3 1 2-3 of Tech Spec Section 3 1 2 7 prior to reaching 6 EFPY of operation GRIFFIN.J M Arkansas Power & Light Co. 84/02/27 STDLZ, J F Operating Reactors Branch 4 App 22515 162 24X Fiche 50-313,84/02/27,8403060199
- --8403060205 Proposed Tech Spec changes, updating Figures 3.1 2-1.3 1.2-2 & 3.1 2-3 of Tech Spec Section 3 i 2 7, prior to reaching 6 EFPY of operation
 ** Arkansas Power & Light Co 84/02/27 6pp 22515.165. 24X Fiche 50-313,84/02/27.8403060199

- 8403050158 Comments on SER in NRC 831219 ltr re degraded grid voltage Requested Tech Spec changes would preclude compliance w/10CFR50.App A GDC 17 MARSHALL.JR Arkansas Power & Light Co 84/02/28 STOLZ.JF Operating Reactors Branch 4 App 22489 055 24X Fiche 50-313,84/02/28.8403050158
- 8403070368 Comments on util interpretation of Tech Spec 3 7 2 re failure of single cell in one bank of batteries to meet surveillance procedure criteria Tech Specs should be amended for Clarity EISENHUT.D 0 Division of Licensing 84/02/28 DENJSE,R P Division of Resident, Reactor Project & Engineering Programs 2pp 22567 202 24X Fiche 50-313.84/02/28.8403070368
- 8403150037 Application for amend to License DPR-51, revising Tech Specs ra low temp overpressure protection sys, per NRC 830826 & 1104 requests
 ORIFFIN.J M Arkenses Power & Light Co 84/02/29 STOLZ, J F Operating Reactors Branch 4 4pp 22643 013 24x
 Fiche: 50-313,84/02/29,8403150037
- --8403150041 Proposed Tech Specs re low temp overpressure protection sys

 * Arkanses Power & Light Co 84/02/29 3pp 22643 017 24X Fiche' 50-313,84/02/29,8403150037
- 8403230133 REVIEW OF THE ARKANSAS NUCLEAR ONE GENERATING STATION UNIT NO 1 EMERGENCY FEEDWATER SYSTEM RELIABILITY ANALYSIS YOUNGBLOOD, R., PAPAZOGLOU, I A Brookhaven National Laboratory NUREC/CR-3529 84/02/29 Division of Safety Technology 102pp 22739 130 24% Fichs 50-313,84/02/29,8403230133
- B403140299 Forwards request for add1 info re control of heavy loads Response requested within 60 days MILLER, J R Operating Reactors Branch 3 B4/03/06 GRIFFIN, J M Arkansas Power & Light Co 2pp 22635 327 24X Fiche 50-313, 84/03/06, 8403140299
- 8403090179 Forwards supplemental info re core exit thermocouples (CET) for inadequate core cooling interim operation.per 840210 telcon CET sys complies w/most NUREG-0737.Item II F 2 requirements MARBHALL.J R Arkansas Power & Light Co 84/03/07 STOLZ.J F Operating Reactors Branch 4 5pp 22573 267 24X Fiche 50-313.84/03/07.8403090179
- B403230091 Responds to B40125 request for add1 info on seismic qualification of emergency fradwater sys (EFW) re vent & drain lines, per Generic Ltr B1-14 EFW trains could not be disabled by open vent or drain MARSHALL.JR Arkansas Power & Light Co B4/03/16 BT0LZ, JF Operating Reactors Branch 4 2pp 22724 343 24X Fiche 50-313,84/03/16.8403830091
- 8403260051 Application to amend Licenses DPR-51 & NFF-6, changing Tech Bpacs re RCS vents, post-accident sampling, long-term auxiliary feedwater sys evaluation; noble gas monitor & iddine particulate sampling, per NURGO-0737 items GRIFFIN, J M Arkansas Power & Light Co 84/03/16 STOLZ, J F Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch 3 9pp 22750-273 24X Fichs 50-313,84/03/16,8403260051
- --8403260157 Proposed Tech Spec changes re RCS vent post-accident sampling: long-term auxiliary feedwater sys evaluation; noble gas monitors; iodine particulate sampling & containment water level monitor

 # Arkanas Power & Light Co 84/03/16 27pp 22750 302 24X Fiche 50-319,84/03/16,8403260051
- G Inspection reports. IE Bulletins & correspondence
- 8403130437 Documents results of activities conducted during 831031-1104 IE insp to review open items re emergency planning Commitment status to resolve items provided Expeditious actions by NRC to remove items requested MARSHALL, J.R. Arkansas Power & Light Co. 83/12/09 COLLINS, J.T. Region 4, UPFice of Director 15pp. 22613 233 24X Fiche 50-313,83/12/09,8403130437
- 8403300046 Forwards IE Insp Repts 50-313/83-36 & 50-368/83-36 on 831219-21. No violations or deviations identified GAQLIARDO, J E Region 4, Office of Director 84/01/31 GRIFFIN J.M. Arkansas Power & Light Co 2pp 22821 240 24X Fiche 50-313,84/01/31,8403300046
- --B403300050 IE Insp Repts 50-313/83-36 & 50-368/83-36 on 831219-21 No violations or deviations identified Major areas inspected QA plans, instructions & procedures for low level radwaste storage facility MILBORN, L. MURRAY, 8 , JOHNSON, W.D. Region 4, Office of Director 84/01/27 10pp 22821 242 24X Fiche 50-313,84/01/31;8403300046

- 8403130395 Forwards IE Insp Repts 50-313/84-05 & 50-368/84-05 on 840126 No violations or deviations identified GAGLIARDO, J E Region 4. Office of Director 84/02/16 GRIFFIN.J M Arkansas Power & Light Co 2pp 22616 325 24X Fichs 50-313.84/02/16.8403130395
- --8403130402 lE Insp Repts 50-313/84-05 & 50-348/84-05 on 840126 No violations or deviations identified Major areas inspected status of REX-84 exercise scenario development HACKNEY, C A , BAIRD, J B , JOHNBON, W D Region 4, Office of Director 84/02/16 3pp 22416 327 24X Fiche 50-313,84/02/16,8403130395
- 840ii90072 IE Info Notice 84~13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consulidated Edison Co of New York, Inc 115pp 22907 237 24X Fiche 50-000,84/02/28,8401190072
- 8403060198 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-25 & 50-38/83-25 BAOLIARDO.J E Region 4, Office of Director 84/02/29 ORIFFIN.J M Arkansas Power & Light Co 1p 22517 226 24X Fiche 50-313.84/02/29.8403060198
- --8403060203 Responds to NRC 831024 ltr re violations noted in IE Insp Repts 50-313/83-25 & 50-368/83-25 Corrective actions fire watch posted at Doors 267 & 340 until mods to eliminate excessive air gaps under doors completed MAREHALL.JR Arkansas Power & Light Co 84/02/03 DENISE, R P Division of Resident, Reactor Project & Engineering Programs 3pp 22517 227 24X Fiche 50-313,84/02/29,8403060198
- 8403060122 Notification of significant licensee enforcement conference on 840309 w/util in Arlington.TX * Region 4. Office of Director 84/03/01 Region 4. Office of Director 1p 22516 328 24X Fiche 50-313,84/03/01,8403060122
- B402090007 IE Info Notice B4-i4, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of QA. Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 2252 329 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84703/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- B40209009 IE Info Notice B4~15, "Reporting of Radiological Releases"

 Svc list encl

 JORDÁN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02.8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JCRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/03/05 Consolidated Edison Co. of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403260090 Forwards IE Insp Repts 50-313/84-04 & 50-368/84-04 on 840124-26 No violations or deviations identified GAOLIARDO, J E Region 4, Office of Director 84/03/05 GRIFFIN, J M Arkansas Power & Light Co 2pp 22758 271 24X Fichs 50-313,84/03/05,8403260090
- --8403260099 IE Insp Repts 50-313/84-04 & 50-368/84-04 on 840124-26 No violations or deviations identified Major areas inspected security organization personnal per alleged compromise of safeguards info Details withheld (ref IOCFR73 21)
 KELLYJ A . HALL,R E . JOHNBON W D Region 4, Office of Director 84/03/02 1p 22758 273 24X Fiche 50-313,84/03/05,8403260090
- 8402090024 IE Info Notice 84-09.Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- B402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PHR Bys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028

- 8403130120 Informs that IE Insp Repts 50-313/83-12,50-368/83-12, 50-313/83-33 & 50-368/83-33 cancelled No insp repts will be issued for subj numbers OAGLIARDD, J E Region 4, Office of Director 84/03/08 GRIFFIN.J M Arkansas Pawer & Light Co 1p 22602 197 24X Fichs 50-313,84/03/08,8403130120
- 8403190277 Notifies of error in 840216 ltr transmitting IE Insp Repts 50-313/84-03 & 50-368/84-03 Ltr indicated rept numbers 50-313/83-03 & 50-368/83-03 Records should be changed accordingly GAGLIARDO. J E Region 4, Office of Director 84/03/08 GRIFFIN.J M. Arkansas Power & Light Co. ip 22673 190 24X Fiche 50-313,84/03/08.8403190227
- --8403190283 Feruards IE Insp Repts 50-313/84-03 & 50-368/84-03 on 840125 No violations or deviations noted GACLIARDOLJ E Region 4. Office of Director 84/02/16 GRIFFIN.J M Arkansas Power & Light Co 2pp 22673 191 24X Fiche 50-313,84/03/08,8403190277
- --8403190288 IE Insp Repts 50-313/84-03 & 50-368/84-03 on 840125 No violations or deviations noted Hajor areas inspected actions taken as result of discrepancy between public info brochure & Jan 1984 telephone directory for emergency planning zone HACKNEY.C A , BAIRD.J B , JUHNSON.W D Region 4. Diffice of Director 84/02/16 3pp 22673 193 24X Fiche 50-313,84/03/08,8403190277
- 8403260230 Forwards IE insp Repts 30-313/84-06 & 50-368/84-06 on 840221-24 No violations or deviations noted GAGLIARDO, J E Region 4, Office of Director 84/03/08 ORIFFINJ M Arkansas Power & Light Co 2pp 22755 151 24) Fiche 50-313,84/03/08,8403260230
- --8403260232 IE insp Repts 50-313/84-06 & 50-369/84-06 on 840221-24 No violations or deviations noted Major areas inspected maint program BOARDMAN.J R . JCHNSON.W D . CROSSMAN.W A Region 4. Office of Director 84/03/08 5pp 22755 153 24X Fiche 50-313,84/03/08.8403260230
- 8402090031 iE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list enci DEYBUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Comsolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8403200169 Forwards QA Program Insp Rept 97900784/83-02 Significance of reported findings should be evaluated to determine acceptability of product or svc provided by vendor M/o encl QAGLIARDD. J E Region 4. Office of Director 84/03/16 ORIFFIN. J M Arkansas Power & Light Co 1p 22676/353 24X Fixhs 50-313,84/03/16,403200169
- 8402090043 iE Info Notice 84-19, "Two Events involving Unauthorized Entries into PHR Reactor Cavities" Svc list enci JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York Inc 123pp 22823 227 24X Fiche 50-000.84/03/21.8402090043
- 8402090044 iE Info Notice 84-20. "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN.E L Davision of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 133pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- R Periodic operating reports & related correspondence
- 840306030B "Annual Radiation Exposure Rept, 1983 " W/840229 ltr MARSHALL.J R Arkansas Power & Light Co 83/12/31 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 22517 047 24x Fichs 50-313, 83/12/31, 84033060308
- 8403020075 Monthly operating rept for Jan 1984 W/B40215 ltr MORTON, K L . MARSHALL, J R Arkansas Power & Light Co 84/01/31 7pp 22441 331 24X Fiche 50-313,84/01/31,8403020075
- B403300069 Monthly operating rept for Feb 1984 W/B40315 ltr MDRTON.K L : MARSHALL.J R Arkansas Power & Light Co B4/02/29 BASSETT.H S Office of Resource Management, Director 7pp 22821 295 24X Fithe 50-313.84/02/29,8403300068
- S Reportable occurrences. LERs & related correspondence
- 840323017B Forwards Technical Review Rept AEOD/T313, "Capped Containment Pressure Sensing Lines." 5 proposed IE info notice Issue adequately resolved RUBIN-S D Reactor Operations Analysis Branch 83/05/11 SEYFRIT.K V Reactor Operations Analysis Branch 1p 22757 286 24X Fichs 50-000.83/05/11.840323017B

- --8403230181 "Capped Containment Pressure Sensing Lines," technical review rept Condition caused by procedurel inadequacy RUBIN. 8 D Director's Office 83/05/11 6pp 22759 287 24X Fithe 50-000.83/05/11.8403230178
- 8403280113 "Analysis of 800407 Loss of Dffsite Power Transient at Artansas Nuclear One Unit 1 " DAVIS: C B EG&O, Inc FIN A-6270 EGG-BAAM-6381 83/08/31 NRC - No Detailed Affiliation Given 61pp 22811 269 24X Fichs 90-313.83/08/31.8403280113
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpel NPS-4 T&T vaive, to close Enc) ltr dtd 840203 sent to listed utils GE notified of affected units in BWR plants
 THEROUX, R R Terry Corp 84/02/RR WOODRUFF, R W Director's Office, Office of Inspection and Enfortement 6pp 22706 327 24X Fichs 50-000.84/02/22:8403210032
- DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1
 F Security, medical, emergency & fire protection plans
- B403090281 Public version of reissue of Rev 9 to emergency plan procedures App A. "Telephone Numbers for Key Plant Personnei " H/83i110 transmittal form & JM Felton B30307 release memo * Indiana & Michigan Power Co 83/ii/03 17pp 22594 303 24X Fichs. 80-315.83/ii/03.8403090281
- 8403070268 Public version of Rev 9 to emergency plan implementing procedures App A: "Telephone Numbers for Key Plant Personnel " W/831109 transmittal form & JM Felton release memo * Indiana & Michigan Electric Co 83/11/09, 18pp 22592.346 24X F(che 50-315,83/11/09,8403090268
- B403120021 Notifies of 840323 regional workshop in Rosemont, IL w/all Region 1II licensees to discuss fire protection safe shutdown requirements Workshop will provide addl guidance re 10CFR50. App R requirements Agenda enci BPEBSARD. R L Division of Emergency Preparedness & Operational Support B4/03/06 DDLAN. J E American Electric Power Bervice Corp DDLAN. J C Indiana & Michigan Electric Co 3pp 22586-272 24X Fiche 90-315.84/03/06.8403120021
- B403130202 Explains & justifies items in nonoutage work schedule which cannot be complated by B40620 Requests schedular exemption from iOCFR50.App R.Bections III G R. iII O B & III J extending compliance date to B41231

 ALEXICH.M P Indiana & Michigan Electric Co B4/03/08 DENTON.H R Office of Nuclear Reactor Regulation, Director Bpp 22617 312

 24X Fiche 50-315.84/03/08.8403130202.
- 8403130121 Rev 5 to Emergency Plan implementing Procedure PMP ROBO EPP 008, "initiating Manning of Emergency Response Facilities & Caliling Off-Duty Plant Personnel" RRAUBELD & Gallon A & MITH, W M indiana & Michigan Electric Co. 84/03/09 14pp 22601.320, 24X Fiche 50-315.84/03/09.8403130121
- 8403130200 Forwards draft final exercise rept for 840125 joint radiological emergency preparedness exercise 8tate of MI & Berrien County demonstrated capability to protect public in event of radiological emergency (RIIM), R W Federal Emergency Management Agency, 84/03/07 JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) Rpp 22642 001 24X Fiche 50-315,84/03/09,8403180200
- --8403150203 Draft evaluation of util. State of MI & Berrien County 840125 joint exercise # Federal Emergency Management Agency 84/02/22, 42pp 22642 003 24X Fiche, 50-315, 84/03/09, 8403150200
- B403300233 Forwards comments on detailed control room design review. Plan demonstrates commitment to meet requirements of Suppl 1 to NUREO-0737, however, addi info required Meeting should be held in Apr or Hay 1984 to discuss comments VARQA: A Operating Reactors Branch 1 B4/03/13 DOLAN, J Indiana & Michigan Electric Co 12pp 22842; 350, 24% Fichs 30-315,84/03/13,8403300233.
- 8403300042 Forwards IE Insp Repts 50-315/84-Q5 & 50-316/84-05 on 840213-17 & notice of violation PAPERIELLO, C.J. Region 3, Office of Director 84/03/14 DOLAN, J.E. American Electric Power Bervice Corp DOLAN, J.E. Indiana & Michigan Electric Co., 2pp. 22821 343 R4X Fiche. 50-315, 84/03/14, 8403300042
- --8403300047 Notice of violation from insp on 840213-17 PAPERIELLO,C.J. Region 3, Office of Director. 84/03/14 2pp 22821 345 24% Fiche 50-315,84/03/14,8403300042,

- --8403300051 IE Insp Repts 50-315/84-05 & 50-316/84-05 on 840213-17 Noncompliance identified failure to meet schedular emergency plan & procedure requirements ENELL.H 0 , PHILLIPS,M P Region 3, Office of Director 84/03/12 12pp 22821 348 24X Fichs 50-315,84/03/14,8403300042
- 8403260178 Submits addl info re daily App R fire insp program per 840314 request Procedure detailing listed items will be
- written ALEXICH.M P Indiana & Michigan Electric Co 84/03/16 DENTON.H F Office of Nuclear Reactor Regulation, Director 2pp 22756 122 24X Fiche 50-315.84/03/16.8403260178
- 8403220050 Atk receipt of 840308 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-315/84-01 & 50-316/84-01
 - DU-316/84-01
 PAPERIELLO.C J Region 3, Office of Director 84/03/19 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co ip 22714 351 24X Fiche 50-315, 84/03/19, 8403220050
- --8403220060 Responds to NRC 840210 ltr re violations noted in IE Insp. Repts 50-315/84-01 & 50-316/84-01 Corrective actions control room functional responsibilities transfer formalized in procedures & emergency plan implementing procedures revised ALEXICH.M P Indiana & Michigan Electric Co 84/03/08 KEPPLER.J O Region 3, Office of Director 2pp 22714 352 24X Fiche 50-315,84/03/19,8403220050
- 8403290271 Emergency Plan Implementing Procedure PMP 2081 EPP 001. "Plant Manager Procedures Index " Procedure PMP 2081, EPP 007 cancelled due to error WELCH, 8 E Indiana & Michigan Electric Co 84/03/28 4pp 22800 024 24X Fiche 50-315,84/03/28,8403290271
- P Operating license stage documents & correspondence
- B403020190 Requests status of replacement, schedule for completion & copy of Acton Leb rept re DA Mercoid switches being replaced by DAH type
 VARGA, B A Operating Reactors Branch i 84/02/21 DDLAN, J Indiana & Michigan Electric Co DDLAN, J American Electric Power Bsrvice Corp 2pp 22475 001 24X Fiche 50-315,84/02/21, B403020190
- 8403060195 Forwards "Status Summary Rept on Adequacy of Distributed Ignition Bys for Hydrogen Control." in response to NRC 820429 ltr & commitments made during NRC 830913 meeting in Bethesda. HD.

 ALEXICH.M P Indiana & Michigan Electric Co 84/03/01 DENTON.H R
 Office of Nuclear Reactor Regulation, Director 2pp 22517 188
 24X Fiche 30-315.84/03/01.8403060195
- --B403060200 "Status Summary Rept on Adequacy of Distributed Ignition Sys for Hydrogen Control " * Indiana & Michigen Electric Co B4/03/01 36pp 22517 190 24% Ficha 50-315.84/03/01.8403060195
- 8403190450 Forwards "SER.Pump & Valve Inservice Testing Program.DC Cook Nuclear Plant.Units i & 2." identifying deficiencies requiring resolution Meeting to discuss deficiencies requested VARQA.B.A Operating Reactors Branch 1 84/03/05 DOLAN.J Indiana & Michigan "Electric Co DOLAN.J American Eisctric Power Service Corp 2pp 22480 340 24X Fiche 50-315,84/03/05,84/03/055
- --B403070390 Requests mesting w/util in Mar 1984 to resolve deficiencies in pump & valve inservice testing program Contractor rept ancl BOSNAK, R. J Machanical Engineering Branch B4/03/01 VARQA, B A Operating Reactors Branch i p 22680 342 24X Fiche: 50-315, 84/03/05, B403190450
- ---8403070395 "BER.Pump & Vaive Inservice Testing Program, DC Cook Nuclear Plant, Units 1 & 2 "
 COOK, T L , ROCKHOLD, H C, EQ&G, Inc. FIN A-6265 EQD-EA-6413
 83/10/91 NRC No Detailed Affiliation Given 22680 343, 24X Fiche, 50-315,84/03/05,8403190450
- 8403140224 Interprets current Tech Specs as allowing control rod movement described in util 840130 ltm. Tech Specs require 23 ft of water over top of reactor vessel flange during movement of fuel assemblies or control rods.

 VARQA: 8 A Operating Reactors Branch 1 84/03/07 DOLAN.J.

 Indiana & Michigan Electric Co. DOLAN.J American Electric Power Service Corp 4pp. 22637 326 24% Fiche 50-315,84/03/07.

- 8403300296 Advises that goal for completion of technical reviews & implementation of all NUREG-0737 items.excluding Suppl 1.is
 Sept 1984 Requests to be advised of potential problems
 within 30 days
 VARGA.S A Operating Reactors Branch 1 84/03/13 DOLAN.J
 Indiana & Michigan Electric Co DOLAN.J American Electric Power
 Service Corp 2pp 22844 316 24X Fiche 50-315.84/03/13.
- --8403200228 Revised proposed Tech Specs for reactor coolant Vent symper TMI Item II B 1
 * Indiana & Michigan Electric Co 84/03/15 7pp 22690 192
 24% Fiche 50-315,84/03/15,8403200283
- 8403300R47 Notification of 840327 & 28 meetings w/util in Stevensylle.MI to discuss current preliminary review of inservice testing program for pumps & valves & forthcoming iO-yr program WIGGINTON,D Operating Reactors Branch 1 84/03/15 VARGA,S A Operating Reactors Branch 1 2pp 22826 361 24X Fiche 50-315.84/03/15,8403300247
- B403260002 Requests approval for use of encl new peaking factor limit rept for Cycle 8 Rept presumes target band of greater than or equal to 5% target axial flux difference Rept withheld ALEXICH, M P Indiana & Michigan Electric Co 84/03/20 DENTON, H f Office of Nuclear Reactor Regulation, Director 2pp 22747 361 24X Fiche 50-315, 84/03/20, 8403260002
- O Inspection reports, IE Bulletins & correspondence
- 8403050223 Further response to FOIA roquest for records of named individuals. Including repts, analyses, studies, test calculations, procedures & practices for measurement of RCB leakage Forwards App C documents Search continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN, T J Raye, Scholer, Fierman, Hays & Handler 3pp 22496 234 24X Fiche 50-000,84/02/07,8403050223
- --8403050256 Notifies that independent measurements of identified & unidentified RCS leak rates for all PMRs in Region III performed per Procedures 617270 & 617280 Insp findings summarized NORELIUB.C E Division of Engineering 82/03/08 JORDAN.E L Division of Engineering & Quality Assurance (Pre 630103) 2pp 22496 270 24X Fichs 50-000.84/02/07.8403050223
- B403080277 Forwards IE Insp Repts 50-315/84-04 & 50-316/84-04 on B40207 No noncompliance identified LITTLE, W B Region 3, Office of Director 84/02/24 DOLAN. J E American Electric Fouer Service Corp DOLAN. J E Indiana & Michigan Electric Co 2pp 22557 272 24X Fiche 50-315,84/02/24,8403080297
- --B4030B0302 1E Insp Repts 50-315/84-04 & 50-316/84-04 on B40207 No noncompliance or deviations identified Major areas inspected documentation & walk-downs re equipment discussed in IE info Ltr B1-14 KEATING, D E, MUFFETT, J, DANIELSON, D H, Region 3, Office of Director 84/02/25 3pp 22557 274 24X Fiche 50-315.84/02/24, 8403080299
- 8403120116 Forwards IE Mgt Meeting Repts 50-315/84-03 & 50-316/84-03 on 840131 KEPPLER, J O Region 3, Office of Director 84/02/24 DOLAN, J.E American Electric Power Service Corp DDLAN, J E Indiana & Michigan Electric Co 2pp 22389 209 24X Fiche 50-315.84/02/24,8403120116
- --B403120124 IE Mgt Meeting Repts 50-315/84-03 & 50-316/84-03 on B40131 Major areas discussed progress & status of licensee regulatory performance improvement program BHAFER, W D , NORELIUS, C E Region 3, Office of Director 84/02/21 3pp 22589 211 24X Fiche 50-315/84/02/24.8403120116
- 8401190072 1E Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 30-000.84/02/28, 8401170072

- 8403060305 Ack receipt of 8402:0 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-315/83-22 & 50-316/83-23 PAPERIELLO:C J Region 3. Office of Director 84/03/01 DDLAN.J
 - PAPERIELLO, C.J. Region 3. Diffice of Director 84/03/01 DDLAN, J.E. American Electric Power Service Corp. DDLAN, J.E. Indiana & Michigan Electric Co. 1p. 22515-357 24X Fiche 50-315, 84/03/01, 8403040305
- --B4030&0315 Responds to NRC B40111 itr re violations noted in iE Insp Repts 50-315/83-22 & 50-316/83-23 Corrective actions lab personnel resinstructed in properly logging analysis results ALEXICH-M P Indiana & Michigan Electric Co B4/02/10 KEPPLER.J G Region 3. Office of Director 4pp 22515 358 24X Fiche 50-315.84/03/01.8403060305
- 8402090007 lE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOY & NRC " Svc list enc! GRACE, J N Division of OA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svr list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fithe 50-000,84/03/02,8402090008
- 8402090009 IE info Notice 84-15. "Reporting of Radiological Releases" Svc list enci
 JDROAN.E L. Division of Emergency Preparedness & Engineering
 Response (Past 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 119pp 22533 217 24X Fiche 50-000,84/03/02,8402090009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Companents Below Nil Ductility Temp " Svc list enci JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24% Fiche 50-000,84/03/05,8402070011
- 8403080208 Ack receipt of 840214 itr providing additinfore Section D 2 C, "Review of Tests or Experiments," of 840120 submittal in response to 83117 confirmatory action itr Subj will be examined during subsequent insp KEPPLER, J G Region 3, Office of Director 84/03/05 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co Ip 22040 019 24X Fiche 50-315,84/03/05,8403080208
- --8403080214 Submits add1 info to 840120 itr, in response to 831117 confirmatory action ltr, Section B 2 C, "Review of Tests or Experiments " Term "nonroutine tests or experiments" clarified ALEXICH.M P Indiana & Michigan Electric Co 84/02/14 KEPPLER.J G Region 3, Office of Director lp 22560 020 24X Fiche 30-315.84/03/05.8403080209
- B402070024 IE Info Notice B4-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JDROAN, E L. Bivision of Emergency Preparedness & Engineering Response (Post B30103) B4/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24% Fiche 50-000, 84/03/07, 8402070024
- 8402070028 IE info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50~000,84/03/07,8402090028
- 8403160034 Requests relief from provisions of ASME Section XI 1974, Table IMB-2500 exam Categories B-L-1 & B-L-2 for reactor coolant pump ALEXICH. M P Indiana & Michigan Electric Co 84/03/08 DENTON:H R Office of Nuclear Reactor Regulation. Director 3pp 22654 357 24X Fichs 50-315.84/03/08.8403160034
- 8402090031 IE Bulietin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sgs " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403300042 Forwards IE Insp Repts 50-315/84-05 & 50-314/84-05 on 840213-17 & notice of violation PAPERIELLO,C J Region 3, Office of Director 84/03/14 DDLAN,J E American Electric Power Service Corp DDLAN,J E Indiana & Michigan Electric Co 2pp 22921 343 24X Fiche, 50-315, 84/03/14, 840330042
 - Notice of violation from insp on 840213-17 _G.C.J. Region 3. Office of Director 84/03/14, 2pp 5 24% Fiche 50-315,84/03/14,8403300042

- --8403300051 IE Insp Repts 50-315/84-05 & 50-316/84-05 on 840213-17
 Noncompliance identified failure to meet scheduler emergency
 plan & procedure requirements
 SNELL, W C. PHILLIPS, W P. Region 3, Office of Director 84/03/12
 12pp 22821 348 24X Fiche 50-315.84/03/14.8403300042
- 8403200202 Requests relief from 10CFR30 55a(g) provisions to allow both facilities to begin second 10-ur insp intervel on same date. Same start date would allow more efficient & Uniform use of personnel HERINGIR F Indiana & Michigan Electric Co. 84/03/13 DENTON, HR Office of Nuclear Reactor Regulation. Director 3pp 22686 347 24X Fiche 30-315,84/03/15.8403200202
- B403220030 Ack receipt of B40308 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/84-01 & 30-316/84-01 PAPERIELLO,C J Region 3, Office of Director 84/03/19 DOLAN,J E American Electric Power Service Corp DOLAN,J E Indiana & Michigan Electric Co ip 22714 351 24X Fiche 50-315,84/03/19,840320030
- --B403220060 Responds to NRC B40210 ltr re violations noted in IE Insp Repts 50-315/B4-01 & 50-316/B4-01 Corrective actions, control room functional responsibilities transfer formalized in procedures & emergency plan implementing procedures revised ALEXICH.M P Indiana & Michigan Electric Co B4/03/08, KEPPLER, J G Region J. Office of Director 2pp 22714.352 24X Fiche.50-315,84/03/19.8403220050
- B403230137 Ack receipt of B40210 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-315/83-19 Confirms understanding that functional logic diagrams under review & revived diagrams will be avaitable by mid-Apr NORELIUS.C E Division of Project & Resident Programs 84/03/19 DOLAN.J E American Electric Power Service Corp DOLAN.J E Indiana & Michigan Electric Co 1p 22730 147 24x Fiche 80-315.84/03/19.8403230137
- --B40323013B Responds to NRC B3122B ir re violetions noted in IE Insp Repts 50-315/83-19 & 50-316/83-20 Corrective actions valve restored to proper position upon discovery of error Sample gump restored to svc ALEXICH M P Indiana & Michigan Electric Co 84/02/10 KEPPLER, J G Region 3, Office of Director 5pp. 22730.148 24X Fiche 50-315,84/03/19.8403230137
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York Inc 123pp 22823 229 24% Fichs 50-000,84/03/21,8402090043
- 8402070044 IE info Notice 84-20, "Svc Life of Relays in Bafety-Related Bys " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- 8403270047 Responds to IE Bulistin 83-07. "Apparently Fraudulant Products Sold by Ray Miller: Inc " Nuclear grade matis not purchased directly from Ray Miller: Inc Review of matis supplied by subvendors continuing ALEXICH.NP Indiana & Michigan Electric Co 84/03/22 DEYOUNG.R C Director's Office: Office of Inspection and Enforcement 10pp 22769 299 24X Fiche 50-315,84/03/22,8403270047
- R Periodic operating reports & related correspondence
- 8403130259 "Annual Operating Rept.1983" W/840229 ltr. STIETZEL.J F., SRENSSON.B A., SHITH.W G. Indiana & Michigan Electric Co. 83/12/31 KEPPLER.J G. Region 3. Office of Director 31pp 22606 017 24X Fiche 50-315,83/12/31,8403130259
- 8403020044 Monthly operating rept for Jan 1984 W/840213 ltr. OILLET, W T , SMITH, W G Indiana & Michigan Electric Co, 84/01/31 11pp 22441 188 24X Fiche 50-315,84/01/31.8403020044
- 8403300157 Monthly operating rept for Fab 1984 W/840308 ltr. OILLETT.W T . SHITH.W G Indiana & Michigan Electric Co. 84/02/29 10pp 22820 058 24X Fiche 50-315.84/02/29,8403300157
- 8403080169 Forwards "Radioactive Effluent Release Rept.Jul-Dec 1983," ALEXICH.M P indiana & Michigan Electric Co 84/03/01 KEPPLER.J O Region 3. Office of Director ip 22618 001 24X Fiche 50-315.84/03/01.8403080169
- --B403:30420 "Semiannual Radioactive Effluent Release Rept. Jul-Dec 1983 "
 # Indiana & Michigan Electric Co B3/12/31 352pp 22618:002,
 24X Fiche 50-015,84/03/01.8403080169.

- S Reportable occurrences, LERs & related correspondence
- B303170014 Forwards AEOD/T303, "Seat Degradation in Henry Pratt Butterfly Valves " Info appears to represent potential generic problem IE info notice or circular recommended BROWN:E J Reactor Operations Analysis Branch 83/03/02 SEYFRIT, K V Reactor Operations Analysis Branch ip 22775 167 24X Fiche 30-313,83/03/02,8303170014
- --8303170017 "Beat Degradation in Henry Pratt Butterfly Valves," technical review rept BROWN, E J Director's Office 83/02/24 App 22775 168 R4X Fiche 50-315, 83/03/02, 8303170014
- B403200216 NPDEB noncompliance notification on B40216.blowdown sample collected during heating boiler startup indicated 9 4 ppm iron. Caused by boiler inactivity W/B40313 ltr MENGE.R C Indiana & Michigan Electric Co B4/02/17 ZUGGER.P D Michigan, State of KEPPLER.J O Region 3, Office of Director 2pp 22699 323 24X Fiche 50-315,84/02/17,8403200216
- 8403200283 Updated LER 82-061/03X-1 on 820726, discovered that alarm/ trip setpoint values in newly installed containment air gazeous & particulate monitors higher than Tech Specs Caused by parsonnel error Procedure revised W/840313 itr DRAPER, D.M., SMITH, W.G. Indiana & Michigan Electric Co. 84/03/13 KEPPLER, J. G. Region 3, Office of Director. 3pp. 22677 100 24X Fiche 50-315,84/03/13,8403200283
- DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2
 P Sacurity, medical, emergency & fire protection plans
- B403070281 Public version of reissue of Rev 7 to emergency plan procedures App A: "Telephone Numbers for Key Plant Personnel" #V831i10 transmittal form & JM Felton 830307 release memo #Indiane & Michigan Power Co. 83/11/03 17pp 22594 303, 24X Fichs. 50-315, 83/11/03, 8403070281
- 8403090268 Public version of Rev 9 to Emergency plan implementing procedures App A: "Telephone Numbers for Key Plant Personnel" H/831109 transmittal form & JM Felton release memo * Indiana & Michigan Electric Co 83/11/09 18pp 22592 346 24X Fichs. 50-315.83/11/09,8403090268
- 8403120021 Notifies of 840323 regional workshop in Rosemont, IL w/all Region III licensees to discuss fire protection safe abutdown requirements Workshop will provide add1 guidance resiOCFR50.App R requirements Agenda encl SPESSARD, R L Division of Emergency Preparedness & Operational Support 84/03/06 DOLANJ, J E American Electric Power Service Corp DOLANJ, E Indiana & Michigan Electric Co 3pp 22586-272 24X Fiche 50-315,84/03/06,8403120021
- 8403130202 Explains & justifies items in nonoutage work schedule which cannot be tompleted by 840620 Requests schedular exemption from 10GFR50. App R. Bections III 0 2.111 0 3 & III J extending compliance date to 841231 ALEXICH. M P Indiana & Michigan Electric Co. 84/03/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 22617 312 24X Fiche. 50-315, 84/03/08, 8403130202
- 8403130121 Rev 5 to Emergency Plan Implementing Procedure PMP 2080 EPP 008, "Initiating Manning of Emergency Response Facilities & Calling Off-Duty Plant Personnel" KRAUSELD, BLIND, A.A., SMITH, W.M. Indiana & Michigan Electric Co 84/03/09 14pp 22601 320 24X Fiche 50-315,84/03/09,8403130121
- B403150200 Forwards draft final exercise rept for 840125 joint radiological emergency preparedness exercise State of MI & Berrien County demonstrated capability to protect public in event of radiological emergency MR1MM.R.W. Federal Emergency Management Agency 84/03/09 JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22642 001 24x Fiche 50-315,84/03/09,8403150200
- --8403150203 Draft evaluation of util. State of M1 & Berrien County 840125 joint exercise * Federal Emergency Management Agency 84/02/22 42pp 22642*003. 24X Fiche, 50-315.84/03/09.8403150200
- 8403300233 Forwards comments on detailed control room design review Plan demonstrates commitment to meet requirements of Suppl 1 to NUREQ-0737, however, add1 info required Meeting should be hald in Apr or May 1984 to discuss comments VARQA, S. A Operating Reactors Branch 1 84/03/13 DDLAN, J Indiana & Michigan Electric Co 12pp 22842 350 24X Fiche 50-315,84/03/13,8403300233

- 8403300042 Forwards IE Insp Repts 50-315/84-05 & 50-316/84-05 on 840213-17 & notice of violation PAPERIELLO.C J Region 3. Office of Director 84/03/14 DDLAN, J E American Electric Power Service Corp 2pp 22821 343 24X Fiche 50-315,84/03/14,8403300042
- --8403300047 Notice of violation from lnsp on B40213-17 PAPERIELLO,C J Region 3, Office of Director B4/03/14 2pp 22821 345 24X Fiche 50-315,84/03/14,8403300042
- --8403300051 lE insp Repts 50-315/84-05 & 50-316/84-05 on 840213-17 Noncompliance identified failure to meet schedular emergency plan & procedure requirements SNELL, W O Region 3. Office of Director 84/03/12 12pp 22821 348 24X Fiche 50-315,84/03/14,8403300042
- 8403260178 Submits addl info re deily App R fire insp program per 840314 request Procedure detailing listed items will be written
 ALEXICH.M P indiana & Michigan Electric Co 84/03/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22754 122 24X Fiche 50-315.84/03/16.8403260178
- 8403220050 Ack receipt of 840308 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-315/84-01 & 50-316/84-01 PAPERIELLO,C J Region 3, Office of Director 84/03/19 DOLAN, J E American Electric Power Service Corp ip 22714 351 24X Fiche 50-315.84/03/19.8403220050
- --8403220060 Responds to NRC 840210 ltr re violations noted in IE insp Repts 50-315/84-01 & 50-316/84-01 Corrective actions control room functional responsibilities transfer formalized in procedures & emergency plan implementing procedures revised ALEXICH.M P Indiana & Michigan Electric Co 84/03/08 KEPPLER.J G Region 3. Office of Director 2pp 22714 352 24X Fiche 50-315,84/03/19,8403220050
- 8403270271 Emergency Plan Implementing Procedure PMP 2081 EPP 001, "Plant Manager Procedures Index " Procedure PMP 2081 EPP 007 cancelled due to error HELCH'S E Indiana & Michigan Electric Co 84/03/28 4pp 22800 024 24X Fiche 50-315,84/03/28,8403270271
- P Operating license stage documents & correspondence
- B403020190 Requests status of replacement, schedule for completion & copy of Acton Lab rept re DA Mercold switches being replaced by DAW type VAROA, S A Operating Reactors Branch 1 84/02/21 DOLAN, J Indiana & Michigan Electric Co DOLAN, J American Electric Power Service Corp 2pp 22495 001 24X Fiche 50-315,84/02/21, B403020190
- 8403060191 Application for amend to License DPR-74.revising Tech Specs rs Cycle 5 reload ALEXICH, M P Indiana & Michigan Electric Co 84/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 22518 001 24X Fiche 50-316.84/03/01.8403060191
- --B40306D197 Proposed Tech Spec changes re Cycle 5 reload * Indiana & Michigan Electric Co 84/03/01 15pp 22518 008 24X Fiche 50-316, 84/03/01, 8403060191
- 8403060175 Forwards "Status Summary Rept on Adequacy of Distributed Ignition 8ys for Hydrogen Control." in response to NRC 820427 itr & commitments made during NRC 830913 meeting in Bethesda, MD ALEXICH, M P Indiana & Michigan Electric Co 84/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22517 188 24X Fiche 50-315,84/03/01,8403060195
- --8403060200 "Status Summary Rept on Adequacy of Distributed Ignition Sys for Hydrogen Control " * Indiana & Michigan Electric Co 84/03/01 36pp 22517 190 24X Fichs 50-315,84/03/01,8403060195
- B4030B0205 Forwards proprietary & nonproprietary info supporting application for Tech Spec changes for Cycle 5 reload Proprietary repts withheld CHANDLER, J C Exxon Nuclear Co . Inc (subs of Exxon Corp) B4/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 22558 224 24% Fiche 50-316,84/03/02,8403080205
- ---8403080210 Suppl 1 to "DC Cook Unit 2.Cycle 5 9AR "
 COPELAND,R A, STOUT,R B, WILLIAMSON.H E Exxon Nuclear Co., inc
 (subs of Exxon Corp.) XN-NF-83-85 801 84/02/23 15pp
 22589 227 24X Fiche 50-316,84/03/02.8403088205

B403190450

- --B4030B0216 Nonproprietary "DC Cook Unit 2 Cycle 5 5% Steam Generator Tube Plugging Limiting Break LOCA/ECCS Analysis " ADES,M J. BRAUN.D J. FAUST.N F Exion Nuclear Co. Inc. (subs of Exion Corp.) XN-NF-B4-21 (NP) B4/03/01 65pp 22558 244 24X Fiche 50-316.84/03/02,84030B0205
- --B4030B0220 "DC Cook Unit 2.Cycle 5 SAR "
 WIMPY.P D , SKD9EN.F B , WILLIAMSON.H E Exton Nuclear Co , Inc
 (subs of Exton Corp) XN-NF-B3-B5 83/10/24 34pp 22558 310
 24X Fiche 50-316.84/03/02,8403080205
- --8403080223 Nonproprietary Rev 2 to "Plant Transient Analysis for DC Cook Unit 2 Reactor at 3,425 MMT Operation W/5% Steam Generator Tube Plugging "
 ADAMS.F T , KAYSER.H V , CHANDLER.J C Exxon Nuclear Co , inc (subs of Exion Corp) XN-WF-62-32 (NP) RO2 84/03/03 114pp 22558 345 24% Fiche 50-316.84/03/02.8403080205
- 8403190450 Forwards "SER. Pump & Valve Inservice Testing Program, DC Cook Nuclear Plant, Units 1 & 2." identifying deficiencies requiring resolution Meeting to discuss deficiencies requested VAROALS A Operating Reactors Branch 1 84/03/05 DULAN, J Indiana & Mithgan Electric Co DULAN, J American Electric Power Service Corp 2pp 22680 340 24X Fache 50-315,84/03/05,8403/05,8403/05
- --8403070390 Requests meeting w/util in Mar 1984 to resolve deficiencies in pump & valve inservice testing program Contractor rept BOSNAK.R J Mechanical Engineering Branch 84/03/01 VAROA.S A Operating Reactors Branch 1 1p 22680 342 24% Fiche 50-315.84/03/05.8403190450
- --8403070395 "SER. Pump & Valve Inservice Testing Program, DC Cook Nuclear Plant. Units 1 & 2"
 COOM. T L . ROCKHOLD. H C EO&G. Inc Fin A-6265 ±69-EA-6413
 83/10/31 NRC No Detailed Affiliation Given 23pp
 22680 343 24% Fiche 50-315.84/03/05.8403170450
- 8403140224 interprets current Tech Specs as allowing control rod movement described in util 840130 itr Tech Specs require 23 ft of water over top of reactor vessel flange during movement of fuel assemblies or control rods VARGA.8 A Operating Reactors Branch i 84/03/07 DOLAN.J Indiana & Michigan Eiectric Co DOLAN.J American Eiectric Power Service Corp 4pp 22637 326 24% Fiche 30-315,84/03/07,8403140224
- B403150097 Forwards nonproprietary version of XN-NF-82-90(NP), Suppl 1: "Potential Radiological Consequences of incidents Involving High Exposure Fuel." which supports application for Tech Spec changes for Cycle 3 reload CHANDLER.J C Exxon Nuclear Co. Inc (subs of Exxon Corg) 84/03/13 DENTON, HR Office of Nuclear Reactor Regulation, Director 6pp 22639 024 24X Fiche 50-316,84/03/13,8403150097
- --8403150104 "Potential Radiological Consequences of Incidents Involving High Exposure Fuel.DC Cook.Unit 2 "
 COPELAND.R A. KAYSER.W V. STOUT.R B Exxon Nuclear Co. Inc.
 (subs of Exion Corp.) XN-NF-92-90 (NP) 801 84/03/31 24pp
 22639 030 24% Fiche 50-316.84/03/13.8403150097
- 8403300296 Advises that goal for completion of technical reviews & implementation of all NUREO-0737 items.excluding Suppl 1.is
 Sept 1984 Requests to be advised of potential problems within 30 days VARGA,S A Operating Reactors Branch 1 84/03/13 DOLAN, J Indiana & Michigan Electric Co DOLAN, J American Electric Power Service Corp 2pp 22844 316 24X Fiche 50-315,84/03/13, 8407300294
- 8403200210 Application to amend License DPR-74.revising Tech Specs re flowrate for flow balance tost of safety injection pumps ALEXICH.M P Indiana & Michigan Electric Co B4/03/15 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 7pp 22697 293 24X Fiche 50-316.84/03/15,8403200210
- --8403200214 Proposed Tech Specs re flowrate for flow balance test of
- 8403200223 Application for amend to Licenses DPR-38 & DPR-74, revising Tech Specs re reactor coolant vent sys per TM1 Item II B i Justification for NSHC provided in 840120 ltr still applicable
 ALEXICH, M P Indiana & Michigan Electric Co
 - Office of Nuclear Reactor Regulation, Director 2pp 22690.190 DENTON, R R

- --8403200228 Revised proposed Tech Specs for reactor coolant vent sys per TMI Item II 8 1 # Indiana & Michigan Electric Co 84/03/15 7pp 22690 192 24% Fiche 50-315,84/03/15,8403200223
- 8403300247 Notification of 840327 & 28 meetings w/util in Stevensville.MI to discuss current preliminary review of inservice testing program for pumps & valves & forthcoming HIGHT Program
 WIGGINTON,D Coperating Reactors Branch 1 84/03/15
 Operating Reactors Branch 1 2pp 22826 361 24X
 Fichs 50-315,84/03/15,8403300247 84/03/15 VARQA,8 A
- 8403200100 Forwards Rev 1 to XN-NF-83-85, Suppl 1. "DC Cook Unit 2, Cycle 5 8AR"
 CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp)
 84/03/16 DENTON H R Office of Nuclear Reactor Regulation,
 Director 1p 22699 186 24X Fichs 50-316,84/03/16,8403200100
- --8403200101 Rev 1.Suppl i.to "DC Cook Unit 2.Cycle 5 SAR "
 COPELANDR A . WILLIAMSON.H E . STOUT.R B Exxon Nuclear Co , Inc
 (subs of Exxon Corp) XN-NF-83-85 R01 S01 84/03/15 12pp
 22697 187 24X Fiche 50-316,84/03/16,8403200100
- B403270110 Forwards responses to NRC questions re proposed B40301 & 15 Tech Spec change requests to flow rate for safety injection pump flow balance test info constitutes supplemental info for changes to Cycle 5 reioad

 ALEXICH.M P Indiana & Mithigan Electric Co B4/03/23 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 7pp 22774 041 24X Fiche 50-316,84/03/23,8403270110
- G Inspection reports, iE Bulletins & correspondence
- 8403050223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCS leakage Forwards app C documents Search continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN, T J Kaye, Scholer, Fierman, Hays & Handler 3pp 22496 234 24X Ficha 50-000,84/02/07,8403050223
- --8403050256 Notifies that independent measurements of identified & unidentified RCS leak rates for all PWRs in Region III performed per Procedures 617278 & 61728B insp findings summarized summarized
 NGRELIUS,C E Division of Engineering 82/03/08 JORD/
 Division of Engineering & Quality Assurance (Pre 830103)
 22496 270 24X Fiche 50-000.84/02/07.8403030223 JORDAN, E. L.
- 8403080299 Forwards IE insp Repts 50-315/84-04 & 50-316/84-04 on 840207 No noncompliance identified LITILE W S Region 3, Office of Director 84/02/24 DDLAN, J E American Electric Power Service Corp DDLAN, J E Indiana & Michigan Electric Co 2pp 22557 272 24X Fiche 50-315,84/02/24,8403080299
- --8403080302 IE Insp Repts 50-315/84-04 & 50-314/84-04 on 840207 No noncompliance or deviations identified Major areas inspected documentation & walk-downs re equipment discussed in IE Info Ltr 81-14 THE THROUGH STATES AND ANIELSON, D. H. Region 3, Office of Director 84/02/25 3pp 22557 274 24X Fiche 50-315,84/02/24,8403080297
- 8403120116 Forwards IE Mgt Meeting Repts 50-315/84-03 & 50-316/84-03 on 840131 KEPPLER, J O Region 3, Office of Director, 84/02/24 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 22587 209 24% Fiche 50-315,84/02/24,8403120116
- --8403120124 IE Mgt Meeting Repts 50-315/84-03 & 50-316/84-03 on 840131 Major areas discussed progress & status of licensee regulatory performance improvement program SHAFER, W D. NORELIUS. C E. Region 3. Office of Director 84/02/21 3pp 22589 211 24X Fiche 50-315,84/02/24,8403120116
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list UNDOAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24% Fiche: 50-000,84/02/28,8401190072
- 8403040305 Ack receipt of 840210 ltr informing NRC of steps taken to correct violations noted in 1E insp Repts 50-315/83-22 & DD-316/83-23
 PAPERIELLO, C J Region 3, Office of Director 84/03/01 DDLAN, J American Electric Power Service Corp DDLAN, J E. Indiana & Hichigan Electric Co ip 22515:357 24X Fiche 50-315.84/03/01, DOLAN, J. E. 8403060305

- --8403060315 Responds to NRC 840111 ltr re violations noted in IE Insp. Repts 50-315/83-22 & 50-316/83-23 Corrective actions leb personnel reinstructed in properly logging analysis results ALEXICH, M.P. Indiana & Michigan Electric Co. 84/02/10 KEPPLER, J. Q. Region 3, Office of Director 4pp. 22515 338 24x Fiche 50-315,84/03/01,8403040305
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enci GRACE.J N Division of GA, Sereguards & Inspection Progrems (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02.8402070007
- 8402090008 IE Info Notice 84-16, "Feilure of Automatic Sprinkler Bys Velves to Operate " Svc list enc! JURDAN, E L. Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090007 IE Info Notice 84-15, "Reporting of Radiological Releases" Byo list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 119pp 22583 217 24X Fiche 50-000,84/03/02,8402090009
- B402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Evc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche. 50-000,84/03/05,8402090011
- B4030B020B Ack receipt of B402i4 Itr providing add1 info re Section B 2.C, "Review of Tests or Experiments," of B40120 submittal in response to B31i17 confirmatory action 1tr Bub; will be examined during subsequent insp KEPPLER, J Q Region 3, Office of Director B4/03/05 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co ip 22540 019 24X Fiche 50-315,84/03/05,84030B020B
- ---8403080214 Submits add1 info to 840120 ltr, in response to 831117 confirmatory action ltr.8ection B 2 C. "Review of Tests or Experiments" Term "nonroutine tests or experiments" clarified.

 ALEXICH.M P Indiens & Michigen Electric Co 84/02/14 KEPPLER.J G. Region 3, Office of Director ip 22560 020 24X Fiche 50-315,84/03/05,8403080208
- B402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Bafe Bhutdown Bys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635;049 24X Fiche. 50-000, 84/03/07, 8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys." Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584-186 24X Fiche, 30-000, 84/03/07, 8402090028
- B403160034 Requests relief from provisions of ASME Section XI 1974, Table IMB-2500 exam Categories B-L-1 & B-L-2 for reactor coolent pump ALEXICH.M P Indiana & Michigan Electric Ca 84/03/08 DENTON,H R Dffice of Nuclear Reactor Regulation, Director 3pp 22654 357 24X Fichs 50-315,84/03/08,8403160034
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Releys in Use in Class IE Sefety Sys " Syc list encl DEYOUNG.R.C. Director's Office, Office of Inspection and Enforcement 84/03/12. Consolidated Edison Co of New York, Inc 134pp. 22823.094. 24X Fiche 50-000.84/03/12.8402090031
- 8403300042 Forwards IE Insp Repts 50-315/84-05 & 50-316/84-05 on 840213-17 & notice of violation PAPERIELLO.C.J. Region 3, Office of Director 84/03/14. DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 22821 343. 24X Fiche 50-315,84/03/14, 8403300042.
- --8403300047 Notice of violation from insp on 840213-17 PAPERIELLD,C J Region 3, Office of Director 84/03/14 2pp 22821.345. 24% Fiche: 50-315,84/03/14,8403300042,

- 8403200202 Requests relief from 10CFR50 55a(g) provisions to allow both facilities to begin second 10-yr insp interval on same date Same start date would allow more efficient & uniform use of personnel
 HERINO.R F Indiana & Michigan Electric Co 84/03/15 DENTON.H R
 Deffice of Nuclear Reactor Regulation, Director 3pp 22686 347
 24X Fiche 50-315,84/03/15,8403200202
- 8403220050 Ack receipt of 840308 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/84-01 & 50-316/84-01 PAPERIELLO, C J Region 3, Office of Director 84/03/19 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigen Electric Co ip 22714 351 24X Fiche 50-315/84/03/19, 840322050
- --B403220060 Responds to NRC B40210 ltr re violations noted in IE Insp Repts 50-315/84-01 & 50-316/84-01 Corrective actions control room functional responsibilities transfer formalized in procedures & emergency plan implementing procedures revised ALEXICH.M P Indians & Michigan Electric Co B4/03/08 KEPPLER.J 9 Region 3, Office of Director 2pp 22714 352 24X Fichs 50-315,84/03/19,8403220050
- 8403230137 Ack receipt of 840210 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-315/83-19 Confirms understending that functionel logic diagrams under review & revived diagrams will be available by mid-Apr NORELIUS,C E Division of Project & Resident Programs 84/03/19 DOLAN,J E American Electric Power Service Corp DOLAN,J E Indiana & Michigan Electric Co Ip 22730 147 24X Fiche 50-315,84/03/19.8403230137
- --8403230138 Responds to NRC 835228 Ir re violations noted in IE Insp Repts 50-315/83-17 & 50-316/83-20 Corrective actions velve restored to proper position upon discovery of error Sample pump restored to svc ALEXICH.M P Indiana & Michigen Electric Co 84/02/10 KEPPLER.J G Region 3, Office of Director App 22730 148 24X Fiche 50-315,84/03/19,8403230137
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc iist encl URDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- B402090044 IE Info Notice 84-20. "Svc Life of Relays in Bafety-Related Bys " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24% Fiche 50-000.84/03/21,8402090044
- 8403270047 Responds to IE Bulletim 83-07, "Apparently Fraudulent Products Sold by Ray Milier. Inc " Nuclear grade matis not purchased directly from Ray Milier. Inc Review of matis supplied by subvendors continuing ALEXIEN, MP Indiane & Michigan Electric Co 84/03/22 DEYOUNG.R C Director's Office Office of Inspection and Enforcement 10pp 22769 299 24X Fiche 50-315.84/03/22. B403270047
- R Periodic operating reports & related correspondence
- 8403130259 "Annual Operating Rapt: 1983 " W/840229 ltr STIETZEL, J F , SRENSSON, B A , SMITH, H O indiana & Michigan Electric Co 83/12/31 KEPPLER, J G Ragion 3, Office of Director 31pp 22606 017 24X Ficha 50-315.89/12/31
- 8403020007 Monthly operating rept for Jan 1984 W/840213 ltr OILLET.W T . PEAK.G J., SVENBEON.B A Indiana & Michigan Electric Co 84/01/31 Bpp 22442 215 24X Fiche 50-316,84/01/31, 8403020007
- B403080169 Forwards "Radioactive Effluent Release Rept.Jul-Dec 1983 "
 ALEXICH.M P Indiana & Michigam Electric Co 84/03/0i
 KEPPLER.J O Region 3, Office of Director ip 22618 001 24X
 Fiche 50-315.84/03/01.8403080169
- --8403130420 "Semiannual Radioactive Effluent Release Rept.Jul-Dec 1983 "
 * Indiana & Michigan Electric Co 83/12/31 352pp 22618 002
 24X Fiche 50-315,84/03/01,8403080169

- S Reportable occurrences. LERs & related correspondence
- B303170014 Forwards ACOD/T303, "Seat Degradation in Henry Pratt Butterfly Valves " Info appears to represent potential generic problem IE info notice or circular recommended BROHNLE J Reactor Operations Analysis Branch B3/03/02 SEYFRIT.K V Reactor Operations Analysis Branch ip 22775 167 24X Fiche B0-315,83/02/02,8303170014
- --8303170017 "Seat Degradation in Henry Pratt Butterfly Valves," technical review rept BROWN,E J Director's Office 03/02/24 4pp 22775 168 24X Fichs 50-315,63/03/02,8303170014
- 8403200217 LER 84-002-00 on 840218 turbine/reactor trip occurred from full power while placing moisture separator reheater steam coils in svc Caused by operator falling to close main steam supply valves Procedure modified W/840316 ltr
 BAKER, K R . SMITH, W G Indiana & Michigan Electric Co 84/03/16
 3pp 22699 341 24X Fiche 50-316,84/03/16,8403200217
- DOCKEF 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8403140228 Public version of Rev 2 to Emergency Plan Implementing Procedure ERPIP A 2. "Review/Approval." M/831214 1tr & JM Felton 840312 release memo RUSBELL, B J. USI.V Baltimore Gas & Electric Co 83/12/14 5pp 22637 317 24X Fiche 50-317.83/12/14.8403140228
- 8403150091 Forwards safeguards Info Info withheld (ref 10CFR73 21) JOLLEY, J. R. Baltimore Gas & Electric Co. 84/02/10 CLARK, R. A. Operating Reactors Branch 3 ip 22643 001 24x Fiche 50-317,84/02/10.8403150091.
- 8403020300 Rev 9 to emergency plan implementing Procedure ERPIP-5 0, "Preparation & Control of Emergency Response " W/840227 ltr UBI.V , RUSSELL.L D Baitimore Gas & Electric Co 84/02/14 10pj 22440 042 24X Fiche 50-317.84/02/14.8403020300
- 8403010301 Responds to util 831024 request for changes to Rev 12 to security plan & Rev 2 to training & qualification plan Changes consistent w/provisions of 10CFR50 B4(p) & acceptable MARTIN, T T Division of Engineering & Technical Programs 84/02/B0HMAKER.N J Baltimore Oas & Electric Co. 4pp 22432 118 24 Fiche 50-317.84/02/23.8403010301
- 8403150155 Forwards Rev 9 to Emergency Response Plan Implementing Procedure ERPIP-5 O, "Preparation & Control of Emergency Response"

 USI.V Baitimore Gas & Electric Co 84/02/27 Director's Office. Defice of Inspection and Enforcement 1p 22642 288 24X Fiche 80-317.84/02/27.8403150155
- 8403020343 Forwards SALP rept for Oct 1982 Sept 1983 Maint of low personnel error rate merits continued attention.
 MURLEY, T E Region 1, Office of Director 84/02/29 LUNDVALL, A E Baltimore Gas & Electric Co 3pp 22439 217 24X
 Fiche 50-317.84/02/29.8403020343
- --8403020345 8ALP rept for Oct 1982 Sept 1983 * Region 1, Office of Director 83/12/12 57pp 22439:220 24X Fiche 50-317,84/02/29,8403020343
- --8403020347 Forwards SALP rept for discussion & review at 831220 meeting in Baltimore. MD Recent performance during 830914 emergency preparedness exercise & two Category III areas will be discussed STAROSTECKI.R Division of Project & Resident Programs 83/12/14 LUNDVALL. A E Baltimore Oas & Electric Co ip 22439 287 24X Fichs 50-317.84/02/29,8403020343
- 8403130110 Rev 9 to Radiological Emergency Plan Implementing Procedure ERPIP-5 2. "Emergency Planning Unit Records " W/840306 itr. USI.V Baltimore Qes & Electric Co 84/03/04 5pp. 22640 209 24% Fiche 50-317,84/03/06,8403130110
- 8403190243 Notification of 840418 workshop in King of Prussla.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop enci MRRLEY.T E Region 1, Office of Director 84/03/09 0'TODLE, J D Consolidated Edison Co op New York, Inc. HARRINOTON, W D Boston Edison Co MURPHY, N P. Vermont Yankee Nuclear Power Corp 35pp. 22672-062 24X Fiche 50-000,84/03/09,8403190249

- 8403210006 Forwards IE Insp Repts 50-317/83-35 & 50-318/83-35 on 831212-16 No violetions observed MARTIN.T T Division of Engineering & Technical Programs 84/03/07 LUNDVALL, A E Baitimore Gas & Electric Co 2pp 22704 334 24X Fiche 50-317/84/03/07/8403210006
- ---8403210016 IE Insp Repts 50-317/83-35 & 50-318/83-35 on 631212-16 No violations identified Major areas inspected emergency preparedness activities outlined in IE insp procedures & review of emergency response plan COHEN. I. HAWXHURST. J., CROCKER. H. W. Region i. Office of Director 84/02/17 App 22704 336 24X Fiche 50-317,84/03/09,8403210006
- 8403190018 Forwards Caivert Cliffs Instruction CC1-310, "Emergency Operating Procedure Writers Guide." implementation schedule, validation verification plan & training plan per Suppl 1 to NURG-0737
 LUNDVALL.A E Baltimore Gas & Electric Co 84/03/14 MILLER, J. R Operating Reactors Branch 3 5pp 22666 001 24X
 Fiche 30-317,84/03/14.8403190018
- --8403190023 Calvert Cliffs Instruction CCI-310, "Emergency Operating Procedure Hrlters Ouide" Emergency operating plan validation/verification plan & training plan encl * Baltimore Gas & Electric Co 84/03/14 46pp 22666.006 24X Fiche 50-317,84/03/14.8403190018
- 8403220032 Requests exemption from specific requirements of Section III 0 2 of 10CFR30. App R & approval of equivalent separation within Fire Areas 39. 40.42 & 43 LUNDVALL.A E Baltimore Oas & Electric Co 84/03/14 MILLER.J R. Operating Reactors Branch 3 4pp 22714 335 24X Fiche 50-317.84/03/14.8403220052
- B403200029 Forwards FEMA evaluation of Town of Lusby, Calvert County, MD post-exercise radiological emergency preparedness plans for facilities Echedule for corrective actions re offsite emergency preparedness deficiencies requested MARTIN, T T Division of Engineering & Technical Programs 84/03/15, LUNDVALL, A E Baltimore Gas & Electric Co 3pp 22699 234 24X Fiche 50-317,84/03/15,8403200029
- --B403200035 Evaluation of Town of Lusby, Calvert County, MD post-exercise radiological emergency preparedness plans for facilities * Federal Emergency Management Agency B3/10/13 36pp 22699 237 24K Fiche 30-317, 84/03/15, 8403200029
- B403220080 Forwards list of local news media available for public broadcasting/notification List used in lieu of FR for exigent or emergency license amends
 LATHAN, D W Baltimore Gas & Electric Co 84/03/15 JAFFE, D H. Operating Reactors Branch 3 2pp 22716 263 24X
 Fiche 50-317,84/03/15,8403220080
- B4033001B2 Forwards safeguards info Info withheld (ref 10CFR73 21)
 JBLLEY, J R Baltimore Gas & Electric Go 84/03/21 MARTIN:T T
 Division of Engineering & Technical Progrems 1p 22820 044 24%
 Fiche 30-317,84/03/21,8403300182
- J Insurance & indemnity information
- 8403140036 Forwards Endorsements 56 & 57 to NELIA Policy NF-216, Endorsement 45 to MAELU Policy MF-76 & Endorsement 23 to NELIA Policy NS-348 GAMMIE, 0 B Baltimore Oas & Electric Co 84/03/07 DINITZ, I. Office of State Programs, Director 5pp 22633 124 24X Fiche, 50-317, 84/03/07, 8403140036
- P Operating license stage documents & correspondence
- 8403010117 Partial response to FOIA request for documents by named individuals re repts, analyses, studies, procedures & sys for measurement of RCB leakage App B documents placed in FDR. App A documents already available in FDR Search continuing FELTON, J M Division of Rules and Records 84/01/25 MADDEN, T J Kaye, Scholer, Fierman, Hays & Handler 7pp 22480 026, 24% Fiche 50-000,84/01/25,8403010117
- --B011070522 Bummarizes results of independent evaluations of primary sys leak rate & some considered extensions Extension of specific evaluations to all PWR facilities recommended Draft procedure re evaluations will be submitted by B00915 JORDAN.E. L. Division of Reactor Operations Inspections B0/08/21 MDSELEY.N.C. Division of Reactor Operations Inspections, lipp 22480 266 24X Fiche 50-000, B4/01/25, B403010117

- 8403050305 Notification of 840316 merting w/util & INEL in Bethesda.MD to discuss & resolve outstanding issues re qualification of electric equipment

 JAFFE.D H Operating Reactors Branch 3 84/02/27 MILLER.J R
- electric squipment JAFFE,D H Operating Reactors Branch 3 84/02/27 MILLER,J R Operating Reactors Branch 3 2pp 22501 247 24X Fiche 50-317,84/02/27,8403050305
- 8403260236 Forwards "Summary of Startup Testing for Cycle 7 "
 LUNDVALL.A E Baltimore Gas & Electric Co 84/02/27 MURLEY,T E
 Region 1, Office of Director 1p 22754 317 24X
 Fichs 50-317.84/02/27,8403260236
- --8403260248 "Summary of Startup Testing for Cycle 7 "

 * Baltimore Gas & Electric Co 84/02/27 8pp 22754 318 24x
 Fiche 50-317,84/02/27,8403260236
- 8403060263 Suppls response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATMS Event " Tabular assessment of status & scheduled date for completion of specific items encl LUNDVALL, A E Baltimore Oas & Electric Co 84/02/27 EISENHUT, D 0 Division of Licensing 32pp 22517 323 24x Fiche 50-317, 84/02/27,8403060263
- 84030&0400 Requests mod of 8303i& order requiring instaliation of noble gas steam sffluent monitor by 84030i Mod reflects commitment to install acceptable replacement for existing sys prior to 84123i, in lieu of schedule proposed in util 840203 ltr LUNDVALL:A E Baltimore Gas & Electric Co 84/03/01 MILLER, J R Operating Reactors Branch 3 2pp 225i8 274 24X Fiche. 50-317.84/03/01,84030&0400
- B4030800B3 Forwards order modifying implementation date for TMI Action Item II F 1 1. "Noble Cas Steam Effluent Monitor." per NUREO-0737 Order provides new completion date of 841231 W/a encl MILLER, J R Operating Reactors Branch 3 84/03/02 LUNDVALL, A E Beltimore Cas & Electric Co 4pp 22584 075 24x Fichs 30-317,84/03/02,8403080083
- 8403160040 Advises that work required to resolve concerns in Generic Ltr 81-i4, "Seismic Qualification of Auxiliary Feedwater Bys," completed, per 820106 request Valves successfully qualified by analysis w/o need for mod LUNDVALL.A E Baitimore Qas & Electric Co 84/03/14 MILLER, J R Operating Reactors Branch 3 2pp 22655 i32 24X Fiche 50-317.84/03/14,8403160040
- 8403220014 Informs of recent assignment of EC Wenzinger at chief, Reactor Projects Bection iA, effective immediately STAROSIECKI, R Division of Project & Resident Programs 84/03/15 LUNDVALL, A E Baitimore Gas & Electric Co 2pp 22712 341 24X Fiche 50-317,84/03/15,8403220014
- B403300070 Responds to request for voluntary participation requestions raised in Generic Ltr 83-41 List of type of diesel generator starts & frequency of starting cycles, based on surveillance testing & corrective maint activities, anci
 LUNDVALL, A. E. Baltimore Gas & Electric Co 84/03/20 EISENHUT, D G
 Division of Licensing 6pp 22822 099 24X Fiche 50-317, 84/03/20, 8403300070
- G Inspection reports, 1E Bulletins & correspondence
- 8403030203 Forwards Structural & Qeotechnical Engineering Brench request for addl info for completion of review of IE Bulietin 80-11, "Masonry Wall Design " Response requested within 60 days of receipt of 1tr MILLER.J R Operating Reactors Branch 3 84/02/24, LUNDVALL.A E Baltimore Gas & Electric Co 7pp 22528 155 24X Fiche. 50-317.84/02/24,8403050203
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enci.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22709-239 24X Fiche 50-000.84/02/28.8401190072
- 8403020343 Forwards BALP rept for Oct 1982 Bept 1983 Maint of low personnel error rate merits continued attention MURLEY.7 E Region 1, Office of Director 84/02/29 LUNDVALL, A E Baltimare Qas & Electric Co 3pp. 22439 217 24X Fiche 50-317.84/02/29,8403020343
- --8403020345 8ALP rept for Oct 1982 Bept 1983. * Region 1, Office of Director 83/12/12 57pp 22439,220 24X Fiche, 50-317,84/02/29,8403020343

- --8403020346 Forwards AE Lundvall 830916 & 1202 itrs listing corrective actions retwo Category III areas on valve lineups & fuel oil day tank level addressed in SALP rept
 LUNDVALL.A E Haltimore Gas & Electric Co 84/01/06 MURLEY.T E Region 1. Office of Director ip 22439 277 24X
 Fiche 50-317,84/02/29,8403020343
- --B403020347 Forwards SALP rept for discussion & review at B31220 meeting in Baitmore, MD Recent performance during B30914 emergency preparedness exercise & two Category III areas wiil be discussed BTAROSTECKI, R Division of Project & Resident Programs B3/12/14 LUNDVALL.A E Baitimore 9as & Electric Co ip 22439 287 24X Fiche 30-317,84/02/29.8403020343
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enc! ORACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edition Co of New York. inc 130pp 22552 329 24X Fiche 50-000.84/03/02.8402070007
- 8402090008 IE Info Notice 84-14, "Failure of Automatic Sprinkler Sys Valves to Operate" Svc list enci JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of Naw York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090007 iE Info Notice 84-i5, "Reporting of Radiological Releases "
 Svc list encl
 JURDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE info Notice 84-17. "Problems W/Liquid Nitragen Cooling Components Below Nii Ductility Temp " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 800103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24% Fiche 50-000,84/03/05,8402090011
- 8403150049 Proposes to extend Unit 1 inservice insp interval end date to 870401 to coincide w/Unit 2 to insure both programs updated to same yr & addenda of ASME Code.Section XI Exemption requested Class III amend fee remitted LUMDVALL.A E Baltimore Oau & Electric Co 84/03/06 MILLER.J R Operating Reactors Branch 1 2pp 22643 141 24X Fiche 50-317.84/03/06.8403150049
- B40319040B Forwards "Calvert Cliffs Unit i, Insp of Steam Generators 11 & 12," final rept LUNDVALL, A E Baltimore Gas & Electric Co 84/03/06 MURLEY, T E Region 1, Office of Director 2pp 22673 316 24X Fichs 50-317, 84/03/06, 840319040B
- --8403190409 "Calvert Ciiffs Unit 1, Insp of Steam Generators 1: & 12, "final rept EMERY.R S Zetec, Inc 83/10/31 127pp 22673 318 24X Fiche 50-317.84/03/06.8403190408
- 8402090024 IE Info Notice 84-09, Rev i, "Løssons Løarned from Insps of Fire Protection Safe Shutdown Sys " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/7 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000.84/03/07,8402090024
- 8402090028 iE info Notice 84-18, "Stress Corrosion Cracking in PMR Bys " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403210006 Forwards IE Insp Repts 50-317/83-35 & 50-318/83-35 on B31212-16 No violations observed MARTIN, T. T. Division of Engineering & Technical Programs 84/03/09 LUNDVALL,A E Baltimore Qas & Electric Co 2pp 22704 334 24X Fiche 50-317.84/03/09.8403210006
- --B403210D16 iE Insp Repts 50-317/B3-35 & 50-318/B3-35 on B31212-16 No Violations identified Major areas inspected emergency preparedness activities outlined in IE insp procedures & review of emergency response plan COHEN. I . HAWKHURST. J J . CROCKER. H W Region 1. Office of Director B4/02/17 6pp 22704 336 24% Fiche 50-317, B4/03/09, B403210006
- 840209003i IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYGUNO.R C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24X Ficha 50-000.84/03/12.840207003i

- 8403250104 Ack receipt of 831201 request for NRC to reconsider issuance of noncompliance per IE insp Repts 50-317/83-23 & 50-318/83-23 Violations withdrawn Records will be adjusted attordingly MARTIN, T T Division of Engineering & Technical Programs 84/03/15 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 22737 353 24X Fiche 50-317,86/03/15,8403260104
- --8403260112 Responds to NRC 831103 ltr re vibiations noted in IE Insp Repts 50-317/83-23 & 50-318/83-23 Requests that NRC reconsider issuance of noncompliance Relevant info not discussed w/NRC during exit interview LUNDVALL.A E Baltimore Gas & Electric Co 83/12/01 MARYIN.T T Division of Engineering & Technical Programs 2pp 22757 355 24X Fithe 50-317,84/03/15.8403260104
- B402090043 IE Info Notice 84-j9, "Two Events involving Unauthorized Entries into FMR Reactor Cavities" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consoitdated Edison Co of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Bafety-Related Bys " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post #30103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 COI 24X Fiche 50-000.84/03/21.8402090044
- R Periodic operating reports & related correspondence
- 8403200003 Monthly operating repts for Feb 1984 W/840315 itr HEWLEY, E K Baltimore Qas & Electric Co 84/02/29 15pp 22485 273 24X Fiche 50-317,84/02/29,8403200003
- 8403i30305 Forwards "Semiannual Effluent Release Rept," for Becond Half 1983 & meteorological data for Jul-Sept 1983 & Oct-Dac 1983 LUNDVALL, A E Daitimore Gas & Electric Co B4/03/01 MURLEY, T E Region I, Office of Director 1p 22607 276 24X Fiche 50-317.84/03/01,8403130305
- --8403130314 "Semiannuai Effiuent Release Rept," Second Haif 1983 # Baltimore Gas & Electric Co B3/12/31 17pp 22607 277 24X Fiche 50-317,84/03/01,8403130305
- --8403130322 "Meteorological Data-Jul-Sept 1983 " * Baltimore Qas & Electric Co 83/09/30 66pp 22607 294 24X Fiche 50-317,84/03/01,8403130305
- --8403130334 "Meteorological Data, Dct-Dec 1983 "
 * Daltimore Qas & Electric Co 83/12/31 33pp 22607 327 24%
 Fiche 50-3(7,84/03/0),8403130305
- 5 Reportable occurrences, LERs & related correspondence
- 8403230125 Forwards Technical Review Rept AEOD/T315, "Events Involving Loss of or Perturbations in Single 120-Volt AC Vital Power Supply Inverter & Attendant Distribution Dus Which Resulted in Inadvertent Actuations of Safety Sys "
 ASHE.F Reactor Operations Analysis Branch 83/05/24 SEYFRIT.K V Reactor Operations Analysis Branch ip 22741 347 24X
 Fiche 50-317.83/05/24,8403230125
- --8403230128 "Events Invoiving Loss of or Perturbations in Bingle 120" Volt AC Vital Power Supply Inverter & Attendant Distribution Bus Which Resulted in Inadvertent Actuation of Bafety Eys," technical review rept Rept should be provided to MRR ASHE,F Reactor Operations Analysis Branch 83/05/24 Bpp 22741 348 24% Fiche 50-317,83/05/24,8403230125
- 8403230171 Forwards Technical Review Rept AEOD/T314. "improper Size of Inlet Piping to Primary Safety Valves "
 IMBRO.E Reactor Operations Analysis Granch 83/05/24
 SEYFRITA V Reactor Operations Analysis Branch ip, 22759 297
 24X Fiche 50-000,83/05/24.8403230171
- --8403230175 "Improper Size of Inlet Piping to Primary Safety Valves." technical review rept. Reduced diameter inlet piping does not represent safety concern IMBROLE V Director's Office 83/05/24 2pp 22759, 278 24X Fiche 50
- 8403130355 LER 84-002-01 on 840127, reactor tripped & all eight reactor trip breakers opened simultaneously Root cause unknown independent sys failure evaluation will be performed W/B40215 ltr SALYARDB.L E , RUSSELL.L B Baltimore Gas & Electric Co 84/02/15 MCRLEY.T.E Region 1. Office of Director 4pp 22616 254 24X Fiche 50-317.84/02/15.8403130356

- 8403130277 LER 84-003-00 on 840123 technicians violated Tech Specs by opening containment isolation valves i-8V-6840-0 & i-8V-6807-0 during operational maint check New procedure written & Tech Spec amend submitted W/840222 ltr ESHELMAN.E M , RUSSELL.L D Baltimore Gas & Electric Co 84/02/22 MURLEY.T E Region 1, Office of Director 4pp 22614 178 24X Fichs 50-317,84/02/22,8403130297
- 8403020343 Forwards SALP rept for Oct 1982 Sept 1983 Maint of low personnel error rate merits continued attention.
 MURLEY, T E Region i, Office of Director 84/02/29 LUNDVALL: A E Baltimore Oas & Electric Co 3pp 22439 217 24X
 Fiche 30-317.84/02/29.8403020343
- --8403020345 8ALP rept for Oct 1982 Sept 1983 * Region i, Office of Director 83/12/12 57pp 22439 220 24X Fiche 50-317,84/02/29,8403020343
- 8403130078 Updated LER 82-066/03X-i on 821026.reactor protective systhame: I trip units for high power, thermal margin/low pressure & axia; shape index bypassed Caused by two oscillators producing noise W/840305 ltr
 8YDNOR.R B . RUBSELL.L B Baltimore Oas & Elsctric Co 84/03/05
 3pp 22614 271. 24X Fiche 50-317.84/03/05.8403130098
- 8403i30252 Updated LER 8i-032/03X-i on 8i0420, reactor protective sys channel D bi power thermal margin/low pressure & axial shape index trip units bypassed for maint Caused by oscillator noise in transmitter W/840305 ltr SYDNOR, R D , RUSSELL-L D Baitmore Oas & Eisctric Co 84/03/05 2pp 22614 195. 24X Fiche 50-317.84/03/05.8403i30252
- 8403130279 Updated LER 83-037/03X-i on 830718, response time of trip circuit breakers 3 & 4 undervoltage trip devices slower than Tech Spec limits Caused by setpoint drift, Setpoints adjusted M/840305 itr SyDNOR, R B . RUSSELL. B Baitimore Gas & Eisctric Co 84/03/05 2pp 22614 138 24X Fiche 50-317,84/03/05,8403130279
- 8403130424 Updated LER 83-049/03X-1 on 830818, auxiliary feedwater pump it found inoperable Caused by stage & shaft piece-balance being bound up Parts replaced W/840305 itr FARELL, E V. RUSSELL, B. Baltimore Gas & Electric Co. 84/03/05 2pp 22618 357 24X Fiche 50-317,84/03/05.8403130426
- 8403130295 Updated LER 83-034/03X-1 on 830525,ECC8 pump room cooler 12 taken out of svc Cause unknown Supply piping & strainers disassembled, inspected & cleaned New mechanical preventive maint procedures implemented H/840306 itr.

 BRANT, K T , RUSSELL, L B Baltimore Gas & Electric Co 84/03/06 2pp 22606 048 24X Fiche 50-317,84/03/06,8403130275
- 8403300100 LER 84-004-00 on 840228 charging pumps 12 & 13 removed from svc due to excessive packing leakage Caused by defective packing Evaluation of alternative packing matts underway H/840328 1tr
 JENNINOS, R T, NAPIER, J J, RUSSELL, L B Baitimore Oas & Electric Co 84/03/28 3pp 22822 OOi 24X Fiche 50-317,84/03/28, 8403300100
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- B403140228 Public version of Rev 2 to Emergency Plan Implementing Procedure ERPIP A 2, "Review/Approval" M/831214 its & JM Felton 840312 release memo RUSEELL, L B , UBI, V Baltimore Gas & Electric Co 83/12/14, 5pp 22637 317 24% Fich # 50-317, 83/12/14, 8403140228
- 8403130091 Forwards safeguards info Info withheld (ref 10CFR79 21)
 JOLLEY, J R Baitlmore Gas & Electric Co B4/02/10 CLARK, R. A.
 Operating Reactors Branch 3 10 22643 001 24X
 Fithe 50-317, 84/02/10, 8403150091
- B403020300 Rev 9 to amergency plan implementing Procedure ERPIP-5 O. "Preparation & Control of Emergency Response " W/840227 ltr USIV , RUSSELL.L B Baltimore Oas & Electric Co 84/02/14. 10pp 22440 042 24X Fiche 30-317,84/02/14.8403020300
- 8403010301 Responds to util 831024 request for changes to Rev 12 to security plan & Rev 2 to training & qualification plan Changes consistent w/provisions of 10CFR50 54(p) & acceptable NARTIN.T T Division of Engineering & Technical Programs 84/02/23 BOMMAKER.N J Ealtimore Gas & Electric Co 4pp. 22432;118 24X Fiche 50-317,84/02/23,8403010301

- 8403150155 Forwards Rev 9 to Emergency Response Plan Implementing Procedure ERPIP-5 0, "Preparation & Control of Emergency Response"

 USI.V Baltimore Gas & Electric Co B4/02/27 Director's Office of Inspection and Enforcement ip 22642 288 24X Fiche 50-317,84/02/27.8403150155
- B403020343 Forwards SALP rept for Oct 1982 Bept 1983 Maint of low personnel arror rate merits continued attention MURLEY.T E Region 1: Office of Director B4/02/29 LUNDVALL,A Baltimore Oas & Electric Co 3pp 22439 217 24X Fiche 30-317,284/02/29,8403020343 LUNDVALL, A E
- --8403020345 8ALP rept for Oct 1982 Sept 1983 * Region i, Office of Director 83/12/12 Fiche 50-317,84/02/27,8403020343 57pp 22439 220 24X
- --8403020347 Forwards SALP rept for discussion & review at 831220 meeting in Baltimore, MD Recent performance during 830914 emergency preparedness axercise & two Category III areas will be discussed discussed
 STARDSYECKI,R. Division of Project & Resident Programs 83/
 LUNDVALL,A E Baltimore Cas & Electric Co ip 22439 287
 Fichs 50-317,84/02/29,8403020343
- 8403150110 Rev 9 to Radiological Emergency Plan Implementing Procedure ERPIP-5 2, "Emergency Planning Unit Records " W/840306 ltr UBI,V Baltimore Oas & Electric Co 84/03/06 5pp 22640 209 24X Fiche 50-317,84/03/06,8403150110
- 8403210006 Forwards IE Insp Repts 50-317/83-35 & 50-318/83-35 on B31212-16.No violations observed MARTIN, T Division of Engineering & Technical Programs 84. LUNDVALL, A E Baltimore Gas & Electric Co 2pp 22704 334 Fiche 50-317,84/03/09,8403210006 84/03/09
- --8403210016 IE Insp Repts 50-317/83-35 & 50-318/83-35 on 831212-16 No violations identified Major areas inspected emergency preparedness activities outlined in IE insp procedures & review of emergency response plan CDHEN, 1 Region i. Office of Director. 84/02/1; 22704 336 24% Fiche 50-317.84/03/07.8403210006
- 8403i900iB Forwards Calvert Cliffs Instruction CCI-3i0. "Emergency Deersting Procedure Writers Guide." implementation schedule validation verification plan & training plan per Suppl i to NUREG-0737 OURPL 1 TO NOREG-U/3/ LUNDVALLIA E Baitimore Qas & Electric Co 84/03/14 MILLER, J R Operating Reactors Branch 3 5pp 22666 001 24X Fiche 50-317.84/03/14.8403190018
- --B403i90023 Calvert Cliffs Instruction CCl-3iO, "Emergency Operating Procedure Writers Guide "Emergency operating plan validation/verification plan & training plan encl # Baltimore Gas & Electric CO B4/03/14 46pp 22666 006 24X Fiche 50-317,84/03/14,8403190018
- 8403220052 Requests exemption from specific requirements of Section III 9 2 of 10CFR50, App R & approval of equivalent separation within Fire Areas 39, 40, 42 & 43 LUNDVALL, A E Baitimore Gas & Electric Co 84/03/14 MILLER, J R Operating Reactors Branch 3 4pp 22714 335 24X Fiche: 50-317,84/03/14,8403220052
- 8403200029 Forwards FEMA evaluation of Town of Lusby, Calvert County, MD post-exercise radiological emergency preparedness plans for facilities Schedule for corrective actions re offsite amargency preparedness deficiencies requested MARTIN, T T Division of Engineering & Technical Programs, 84 LUNDYALL, A E Baltimore Oas & Electric Co 3pp 22699:234 Fiche: 50-317,84/03/13,8403200029 84/03/15
- --8403200035 Evaluation of Town of Lusby, Calvert County, MD post-exercise radiological emergency preparedness plans for facilities # Federal Emergency Management Agency 83/10/13 56pp 22697, 237 24X Fiche 50-317, 84/03/15
- 8403220080 Forwards list of local news media available for public 003220080 Forwards list of local news media available for public broadcasting/notification. List used in lieu of FR for exigent or emergency license amends LATHAM, D W Baltimor's Cas & Electric Co B4/03/15 JAFFE, D H Operating Reactors Branch 3, 2pp 22716, 263, 24X Fiche: 50-317: 84/03/15, 8403220080
- B403300182 Forwards safeguards info Info withheld (ref 10CFR73 21) JOLLEY, J R. Baltimore Gas & Electric Co B4/03/21 MARTIN.T T. Division of Engineering & Technical Programs, ip 22820, 044 24X Fiche 50-317,84/03/21,8403300182

J Insurance & indemnity information

- 8403140036 Forwards Endorsements 56 & 57 to NELIA Policy NF-216, Endorsement 45 to MAELU Policy MF-76 & Endorsement 23 to NELIA Policy NS-348 84/03/07 DINITZ, I 22633 124 24X Baltimore Gas & Electric Co CAMMIF. C R Office of State Programs, Director Spp Fiche 50-317,84/03/07,8403140036
- P Operating license stage documents & correspondence
- B4030i0117 Partial response to FOIA request for documents by named individuals re repts analyses, studies, procedures & sys for measurement of RCB leakage App B documents placed in PDR App A documents aiready available in PDR Search continuing FELTON, J M Division of Rules and Records B4/01/25 MADDEN, T Rays, Scholer, Fierman, Hays & Handler 7pp 22480 026 24% Fiche 50-000,84/01/25,8403010117
- --8011070522 Summarizes results of independent evaluations of primary sys leak rate & some considered extensions Extension of specific evaluations to all PMR facilities recommended Draft procedure re evaluations will be submitted by 800715 UORDAN, E L Division of Reactor Operations Inspections 80/08/21 HDBELEY, N C Division of Reactor Operations Inspections iipp 22480 266 24X Fiche 50-000,84/01/25,8403010117
- 8403050305 Notification of 840316 meeting w/util & INEL in Bethesda.MD to discuss & resolve outstanding issues re qualification of conscious & results of electric equipment
 JAFFE, D H Operating Reactors Branch 3 84/02/27 MILLER, J R
 Operating Reactors Branch 3 2pp 22501 267 24X
 Fiche 90-317,84/02/27,8403050309
- 8403050078 Forwards "Rept on Task 05088, Pressurizer Relief Valve Discharge Piping Gualification for Calvert Ciiffs, Unit 2." per TMI Item II D i LUNDVALL, A E Baltimore Gas & Electric Co 84/02/29 MILLER Operating Reactors Branch 3 3pp 22484 167 24X Fiche 50-318,84/02/27,8403050098
- --8403050100 "Rept on Task 05088, Pressurizer Relief Valve Discharge Piping Qualification for Calvert Cliffs, Unit 2 " Approx nine of 84 existing pipe supports may experience stress PATEL, R B Bechtel Corp 84/02/14 1602p 22484 170 24X Fiche 50-318,84/02/29,8403050098
- --8403050103 Rev 2 to "Pressurizer Safety Valve Operability Rept 4 Combustion Engineering. Inc. CEN-248(8) R02 84/01/31 22484 332 24X Fiche 50-318.84/02/27.8403050078
- 8403060263 Suppls response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Balem ATMS Event " Tabular assessment of status & scheduled date for completion of specific items enci LUNDVALL, A E Baltimore Oas & Electric Co 84/02/29 EISE Division of Licensing 32pp 22517 323 24% Fiche 50-317 84/02/29.8403060263 FISENHUT, D Q
- 8403060400 Requests mod of 830316 order requiring installation of noble gas steam efficient monitor by 840301 Mod reflects commitment to install acceptable replacement for existing sys prior to 841231, in lieu of schedule proposed in util 840203 itr LUNDVALL.A E Baltimore Gas & Electric Co 84/03/01 MILLER.J R Operating Reactors Brench 3 2pp 22518 274 24X Fiche 50-317.84/03/01.8403060460
- 8403080083 Forwards order modifying implementation date for TMI Action Item II F 1 i, "Noble Gas Bteam Effluent Monitor," per NUREG-0737 Order provides new completion date of 841231 W/o enci MILLER, J. R. Operating Reactors Branch 3 84/03/02 LUNDVALL, A E Baltimore Gas & Electric Co 4pp 22584 095 24X Fiche 50-317.84/03/02,8403080083
- B403i&0040 Advises that work required to resolve concerns in Generic Ltr 81-14, "Seismic Gualification of Auxiliary Feedwater Sys," completed, per 820106 request Valves successfully qualified by analysis w/o need for mod LUNDVALL.A E Baltimore Gas & Electric Co 84/03/14 HILLER.J R Operating Reactors Branch 3 2pp 82655, 132 24X Fiche 50-317,84/03/14,8403160040
- 8403220014 Informs of recent assignment of EC Wenzinger as chief, Reactor Projects Section 1A. effective immediately BTAROSTECKI, R Division of Project & Resident Programs 84/03/15 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 22712 341 24X Fiche 50-317,84/03/15,8403220014

- B40330070 Responds to request for voluntary participation requestions raised in Generic Ltr 83-41 List of type of diesel generator starts & frequency of starting cycles, based on surveillance testing & corrective maint activities, encl LUNDVALL, A E Baltimore Gas & Electric Co 84/03/20 EIBENHUT, D Q Division of Licensing 6pp 22822 099 24X Fiche 50-317, 84/03/20, 840330070
- Q Inspection reports, IE Builetins & correspondence
- 8403050203 Forwards Structural & Geotechnical Engineering Branch request for add1 info for completion of review of IE Bulletin 80-11. "Masonnry Wall Design " Response requested within 60 days of receipt of 1tr MILLER, J R Deprating Reactors Branch 3 84/02/24 LUNDVALL, A E Daltimore Gas & Electric Co 7pp 22528 155 24X Fiche 50-317,84/02/24.8403050203
- 8401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enct JURDAN, E L. Division of Emorgency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239 24X Fiche 30-000.84/02/28.8401190072
- 8403020343 Forwards SALP rept for Oct 1982 Sept 1983 Maint of low personnel error rate merits continued attention MURLEY.7 E Region 1. Office of Director 84/02/27 LUNDVALL.A E Baltimore Gas & Electric Co 3pp 22439 217 24X Fiche 50-317.64/02/29:8403020343
- --8403020345 SALP rept for Oct 1982 Sept 1983 * Region 1, OPFice of Director 83/12/12 57pp 22439 220 24X Fiche 50-317,84/02/29,8403020343
- --B403020346 Forwards AE Lundvail 930916 & 1202 ltrs listing corrective actions retwo Category III areas on valve lineups & fuel oil day tank isval addressed in EALP rept LUNDVALL.A E Baltimore Gas & Electric Co B4/01/06 MURLEY.T E Region 1. Office of Director 1p 22439 277 24X Fiche 50-317.84/02/29.8403020343
- ---8403020347 Forwards SALP rept for discussion & review at 831220 meeting in Baltimore, MD Recent performance during 830914 emergency preparedness exercise & two Category III areas will be discussed
 8TAROSTECKI, R Division of Project & Resident Programs 83/12/14
 1UNDVALL, A E Baltimore Gas & Electric Co ip 22439 287 24X
 Fiche 50-317,84/02/29,8403020343
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE. J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York. Inc 130pp 22552 327 24X Fiche 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate" Svr list enti JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolifated Edison Co of New York, Inc. 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice B4-15, "Reporting of Radiological Releases"
 Byo list enci
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84703/02 Consolidated Edison Co of New
 York, Inc. 117pp 22553 217 24X Fiche 50-000,84/03/02,8402070009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403150049 Proposes to extend Unit 1 inservice insplinterval and date to 870401 to coincide w/Unit 2 to insure both programs updated to same yr & addenda of ASHE Code, Section XI Exemption requested Class III amend fee remitted LUNDVALL, A E Baltimore Gas & Electric Co. 84/03/06 MILLER, J R Operating Reactors Brench 3 2pp 22643 141 24X Fiche 50-317,84/03/06.8403150049
- 8402090024 IE Info Notice 84-09, Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024

- 8402070028 IE Info Notice 84-18. "Stress Corrosion Cracking in FHR 8ys " Svc list ench JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 18
- 8403210006 Forwards IE Insp Repts 50-317/83-35 & 50-318/83-35 on 831212-16 No violations observed MARTIN, T T Division of Engineering & Technical Programs 84/03/09 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 22704 334 24X Fiche 50-317,84/03/09,8403210006
- --B4032i0016 IE Insp Repts 50-3i7/B3-35 & 50-3i8/B3-35 on B31212-16 No violations identified Major areas inspected emergency preparedness activities outlined in IE insp procedures & review of emergency response plan COHEN, I , HAMXRURST, J J , CROCKER, H W Region I Office of Director B4/02/17 App 22704 336 24X Fiche 50-3i7,84/03/09, B403210006
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list enci BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co. of New York, Inc i34pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- 8403260104 Ack receipt of 831201 request for NRC to reconsider issuance of noncompliance per IE Insp Repts 50-317/83-23 & 50-318/83-23 Violations withdrawn Records will be adjusted accordingly MARTIN,T T Division of Engineering & Technical Programs 84/03/15 LUNDVALL,A.E Baltimore Gas & Electric Co 2pp 22757 353 24X Fiche 80-317,84/03/15.8403260104
- --8403240112 Responds to NRC 831103 ltr re violations noted in IE Insp Repts 50-317/83-23 & 50-318/83-23 Requests that NRC reconsider issuance of noncompliance Relevant info not discussed w/NRC during srit interview LUNDVALLA E Baltimore Cas & Electric Co 83/12/01 MARTIN.T Y Division of Engineering & Technical Programs 2pp 22757 355 24X Fiche 50-317, 84/03/15,8403240104
- 8402090043 IE info Nutice 84-19, "Two Events involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co of Naw York, Inc. 123pp 22823 227 24X Fiche 50-000.84/03/21,8402090043
- 8402090044 IE info Notice 84-20. "Svc Life of Relays in Sefety-Related Sys " Svc list encl UDROBANE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000.84/03/21.8402090044
- R Periodic operating reports & related correspondence
- 8403200003 Monthly operating repts for Feb 1984 W/840315 1tr BEMLEY, E K Baltimore Gas & Electric Co 84/02/29, 15pp 22685 273 24X Fiche 50-317,84/02/29,8403200003
- 8403130305 Forwards "Semiannual Effluent Release Rept," for Second Half 1983 & meteorological data for Jul-Bept 1983 & Oct-Dec 1983 LUNDVALL.A E Baltimore Gas & Electric Co 84/03/01 MURLEY,T E Region 1. Office of Director 1p 22607,276 24X Fiche 50-317,84/03/01,8403130305.
- --8403130314 "Semiannual Effluent Release Rept." Second Half 1983 * Baltimore Cas & Electric Co 83/12/31 17pp 22607 277 24X Fiche 50-317, 84/03/01.8403130305.
- --8403130322 "Meteorological Data, Jul-Sept 1983 "
 # Baltimore Cas & Electric Co 83/09/30 66pp 22607:294 24X
 Fiche 50-317,84/03/01,8403130305
- --8403i30334 "Mateorological Data, Oct-Dec 1783 "
 * Baltimore Qas & Electric Co 83/12/31 33pp 22607,327 24X
 Fiche 50-317,84/03/01,8403130305
- B Reportable occurrences, LERs & related correspondence
- 8403230125 Forwards Technical Review Rept AEOB/T315, "Events Involving Loss of or Perturbations in Single 120-Volt AC Vital Power Supply Inverter & Attendant Distribution Bus Which Resulted in Inadvertent Actuations of Safety Sys "
 ASHE, F. Reactor Operations Analysis Branch, 83/05/24 BEYFRIT, K. V. Reactor Operations Analysis Branch ip 22741, 347 24X Fiche 50-017, 83/05/24, 84003230125

- --B403230128 "Events Involving Loss of or Perturbations in Single 120-Volt AC Vital Power Supply Inverter & Attendent Distribution Bus Which Resulted in Inadvertent Actuation of Safety Sys," technical review rept Rept should be provided to NRR ASME,F Reactor Operations Analysis Branch 83/05/24 Bpp 22741 348 24X Fiche 50-317.83/05/24.8403230125
- 8403230171 Forwards Technical Review Rept AEOD/T314. "Improper Size of Inlet Piping to Primary Safety Valves "
 IMBRO,E Reactor Operations Analysis Branch 83/05/24
 SEYFRIT,K V Reactor Operations Analysis Branch 1p 22759 297
 24X Fichs 50-000.83/05/24,8403230171
- ---8403230175 "Improper Size of Iniet Piping to Primary Safety Valves," technical review rept Reduced diameter inlet piping does not represent safety concern IMBRO,E V Director's Office 83/05/24 2pp 22759 298 24x Fiche 50
- 8311020249 Forwards engineering evaluation rept re PORV actuation resulting in sefety injection actuation IMBRO.E V Reactor Operations Analysis Branch 83/07/08 SEYFRITK V. Reactor Operations Analysis Branch ip 22789 318 24X Fiche 30-318,83/09/08,8311020249
- ---8311020253 "PORV Actuation Resulting in Safety Injection Actuation "
 IMBRO,E V Reactor Operations Analysis Branch 83/09/08, 7pp
 22789 319 24X Fiche 50-318,83/09/08,8311020249
- 8403020343 Forwards SALP rapt for Oct 1982 Sapt 1983 Maint of low personnel error rate marits continued attention MURLEY, T E. Region 1. Office of Director 84/02/29 LUNDVALL, A 8 Baltimore Gas & Electric Co 3pp 22439 217 24X Fiche 50-317.84/02/29.8403020343
- --8403020345 SALP rept for Oct 1982 Sept 1983 * Region 1. Office of Director 83/12/12 57pp 22439 220 24X Fiche 50-317.84/02/29,8403020343
- 8403060109 LER 84-001-00 on 831005,1220 & 840203,ECC8 pump room ventilation sys exhaust fan discharge damper 21 would not open Caused by air supply to exhaust fan discharge damper isoleted Air restored & sys returned to syc W/840301 ltr JUNGE,M , RUBSELL,L B Baltimore Gas & Electric Co 84/03/01 5pp 22518:305 24% Fiche 50-318,84/03/01.8403060109
- 8403130039 Updated LER 82-054/03X-1 on 821124, power lost to 24 4-kV bus, resulting in loss of saltwater pump 22 & low pressure safety injection pump 22 Caused by cracked printed circuit board No corrective ections planned W/840303 ltr BASBO, L. F., RUSBELL, L. B. Baltimore Gas & Electric Co. 84/03/05 2pp 22608.081 24X Fiche 50-318.84/03/03, 8403130039
- B403130081 Updated LER 81-025/03X-1 on B10430 & 0514 reactor protective sys Channel B trip units 1,3,7.8 & 10 bypassed to investigate problem w/T-hot Channel B Caused by failure of two oscillators in transmitter circuitry, W/840305 ltr BYDNOR, R B , RUSBELL, B Beltimore Gas & Electric Co 84/03/05, 2pp 22614 302 24X Fiche 50-318,84/03/05,8403130081
- 8403130413 Updated LER 83-036/03X-1 on 830719, response time for reactor trip circuit breakers 4 & 7 undervoitage devices indicated alower than Tech Spèc limits Caused by setpoint drift & worn front frame assembly mechanisms W/840305 ltr 8YDNOR, R B , RUSSELL, L B Baitimore Gas & Electric Co 84/03/05 2pp. 22613 088 24X Fiche, 50-318,84/03/05,8403130413
- B403130450 Updated LER 81-030/03X-1 on B10305, discovered temp trensmitter 122HB out of tolerance in nonconservative direction, Caused two oscillators producing noise on transmitter output Transmitter replaced W/840305 ltr BYDNOR, R. B., RUSSELL, L. B. Baltimore Oes & Electric Co. 84/03/05, 2pp. 22613 231 24X Fiche. 50-31B.84/03/05,8803130450
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2 F. Security, medical, emergency & fire protection plans
- B403070264 Public version of Rev 1-00 to Emergency Plan 4000-PLN-1300.01. W/JM Felton 840307 release memo BARTON, J M., CLARK, P R General Public Utilities - OPU Service Corp B4/02/01. 300pp 22074 005 24X Fiche 50-320,84/02/01,8403070264
- 8403130467 Forwards IE Insp Rept 50-320/84-02 on 840109-0213 No violations observed.

 BARRETT, L. H. Thi Program Office. 84/02/27 KANGA, 8 K General Public Utilities GPU Service Corp 3pp 22613-219 24X Fiche. 50-320, 84/02/27, 8403130467

- --8403130471 IE Insp Rept 50-320/84-02 on 840109-0213 No violations identified Major areas inspected LERs previous insp findings radioactive matl shipments health physics & environ review & reactor bidg entries MEHE.J. MOBLAK.T. BELL.J. TMI Program Office 84/02/22 7pp 22613 221 24X Fiche 50-320.84/02/27.8403130467
- 8403050151 Revised emergency implementing procedures, including Procedure 1054 1 re unusual syent, Procedure 1054 2 re alert, Procedure 1054 3 re site emergency & Procedure 1054 4 re general emergency BRADY, J A General Public Utilities OPU Service Corp 84/02/28 113pp 22484 054 24% Fiche 50-020.84/02/28,8403050151
- B4030B017B Rev 5 to Emergency Pian Implementing Procedure 1054 3.
 "Bite Emergency"
 BRADY, J A. MILLER, A Ceneral Public Utilities OPU Service Corp
 B4/02/2B 29pp 22559 114 24X Fiche 50-320.84/02/28.84030B017B
- 8403060133 Forwards Rev 19 to security plan Rev restores portions of plan wording re TMI-2 security features modified in Revs 17 & 18 Rev withheld (ref 10CFR73 21) HUKILL, H D General Public Utilities GPU Service Corp 84/02/29 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 2pg 22506 332 24X Fiche 50-289,84/02/29,8403040133
- 8403130286 Informs that annual emergency exercise scheduled for 841003, per 10CFR50, App E requirements Limited participation plenned by Commonwealth of PA, five risk counties & local municipalities
 HUKILL.H D General Public Utilities GPU Service Corp 84/03/08
 Office of Nuclear Reactor Regulation, Director 1p 22605 160
 24X Fiche 50~289,84/03/08,8403130286
- 8403150118 Revs to Emergency Preparedness Administrative Procedure 1056. "Administration of TMI-2 Onsite & Offsite Emergency Duty Roster"

 REAVER. J R , ORANGE. G J General Public Utilities OPU Service Corp 84/03/08 27pp 22639 305 24X Fiche 50-320,84/03/08,8403150118
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection and shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl MURLEY.TE Region 1. Office of Director 84/03/09 O'TOQLE.J D Consolidated Edison Co of New York. Inc. HARRINGTON.W D Boston Edison Co MURPHY.W P Vermont Yanke Nuclear Power Corp 35pp 22672 Q62 24X Fiche 50-000.84/03/09.8403190243
- 8403210047 Forwards IE Insp Rept 50-320/84-01 on 840109-12 & 17-20 No violations noted
 MARTIN.T T Division of Engineering & Technical Programs
 KANDA, B K General Public Utilities - GPU Service Corp
 22705 305 24X Fiche 50-320.84/03/09.8403210047
- --8403210054 IE Insp Rept 50-320/84-01 on 840109-12 & 17-20 No violations noted Major areas inspected IE Insp Procedures 82203, 82205, 82210 & 82211 re notifications & communications, shift staffing, audits & emergency work protection, respectively TERC.N M . MOLYNER.E . GORDON.C Z Region i. Office of Director 84/02/16 4pp 22705 307 24X Ficher 50-320,84/03/09,8403210047
- 8403280243 Forwards list of mods to fire protection sys, based on review of 820415 fire hazards analysis Schedule for corrective actions for items not yet addressed requested within 30 days
 8NYDER, B. J. TMI Program Office 84/03/13 KANOA, B.K. Gensrel Public Utilities GPU Service Corp. 4pp. 22808 202 24X
 Fichs 50-320,84/03/13,8403280243
- B403290202 Forwards IE Safeguards Insp Rept 50-320/84-03 on 840213-17
 No violations noted
 MARTIN.T T Division of Engineering & Yechnical Programs 84/03/13
 KANRA, B K General Public Utilities CPU Service Corp 2pp
 22801 001 24X Fiche 50-320.84/03/15.8403290202
- --8403270205 IE Befeguards Insp Rept 50-320/84-03 on 840213-17 No violations noted Major arees inspected security organization, security program audity testing & meint, physical barriers, detection aids & communications
 DUNLAP, J H , JUYNER, J H Region 1, Office of Director. 84/03/15
 5pp 22801 003 24X Fiche. 50-320,84/03/15,8403290202
- 8403270073 Rev i to Emergency Plen Implementing Procedure 1054 21, "Emergency Repeir/Operations" BRADY, J A , KOVACH, D , GRANGE, O General Public Utilities GPU BBFVICE Corp 84/03/20 4pp 22766 id6 24X Fiche 50-320, 84/03/20.8403270073

O Adjudicatory correspondence

- 6403070370 Commission determination statement withholding transcript of closed 530921 meeting re-motion to quash Hartman subpoenas CHILX.S J Office of the Secretary of the Commission 84/02/27 Public Document Branch ip 22567 201 24X Fiche 50-320,84/02/27.8403070370
- 8403160005 Advises that time for Commission to review Director's Decision DD-B4-4 expired Commission declined review Decision became final agency action on 840313 CHILK, S.J. Office of the Secretary of the Commission 84/03/14 LEWIS, M. Lewis, M. 1p. 22655 197 24X Fiche 50-320, 84/03/14, 8403160005
- 8403200191 Responds to 831208 & 18 ltrs re possibility of restart decision prior to further evidentiary hearings on mpt compatence & integrity ASLAB decision will be considered by Commission upon issuance PALLADING,N J Commissioners 84/03/19 SPECTER, A Senate 2pp 22698 003 24% Fiche 50-289,84/03/19,8403200191
- --8403200198 Respands to 840124 ltr & 831216 position statement refunding of cleanup prerequisite for restart Commission does not have legal authority to condition restart of TMI-1 on funding solution for cleanup of TMI-2 PALLADINO, N J Commissioners 84/03/19 THORNBURCH, R Pennsylvania, Commanuealth of, 3pp 22698.024 24X Fiche 50-289,84/03/19,8403200191

H General correspondence

- 8403060083 Requests that D Kennedy replace D Hess on mailing list for TMI matls
 KENNEDY.D Pennsylvania, Commonwealth of, B4/03/01 SNYDER, B J
 TMI Program Office ip 22517 014 24X Fiche: 50-320, 84/03/01, 840395083
- 8403190056 Responds to constituent RE Burks 840123 request for info re accident Forwards "Population Dose & Health Impact of Accident at TM1 Station," (NUREG-0538) W/o enci DIRCKS,W J Office of the Executive Director for Operations 84/03/05 HEFLIN.H Senate 3pp 22681 317 24X Fiche 50-320,84/03/05,8403190056
- --8403190060 Requests comments on encl constituent RE Burks 840123 request for NRC rept on TMI accident HEFLIN.H Senate 84/02/10 KAHMERER,C Office of Congressional Affairs 3pp 22681 320 24X Fiche 50-320.84/03/08,8403190054
- B403210141 Requests deletion of RC Arnold, former president of Ganeral Public Utils, from NRC mailings # General Public Utilities - CPU Service Corp 84/03/16 NRC -No Detailed Affiliation Given 2pp 22707.280 24X Fiche 50-289,84/03/16.8403210141

J Insurance & indemnity information

- G4032B0010 Forwards Endorsements 72 & 73 to NELIA Policy NF-220 & Endorsements 62 & 63 to HAELU Policy MF-73 GERETY.H F General Public Utilities GPU Service Corp 84/03/22 SALTIAN.J Office of Nuclear Reactor Regulation. Director Spp 22777 074 24X Fiche 50-289,84/03/22,8403280010
- P Operating license stage documents & correspondence
- 8403200304 Forwards N Myers 820111 memo re statements made at 811221 meeting on info flow during TM1 accident DIRCKS,W J Office of the Executive Director for Operations 82/01/13 PALLADIND, 011LINSKY, BRADFORD Commissioners Opp 22709 170 24X Fiche 50-320.82/01/13.8403200304
- 8403200341 Forwards H Meyer 830308 memo rs possibility of intentionally or willfully withholding info during accident NRC statements inconsistent DIRCKS, W J Office of the Executive Director for Operations 82/03/ii PALLADINO, GIL INSKY, BRADFORD Commissioners 5pp. 22709 ii9 24X Fiche 50-320,82/03/ii.8403R00341.
- 8403080393 Forwards DL Jensen 830517 1tr to N Palladino re DOJ investigation of TMI Document subj to Voigt 830526 FOIA request & 830919 appeal Document should be placed in PDR SMEENEY, M Office of the General Counsel 84/01/27 PDGL, M J NRC NO Detailed Affiliation Given 1p 22367:354 24X Fiche: 50-289: 84/01/27: 8403080393

- --8403080425 Responds to 830411 itr re TMI-1 restert & DDJ investigation into allegations re mgt competence Investigation being pursued diligently but will not be completed by requested date

 JENSEN.D L Justice. Dept of 83/05/17 PALLADINO.N J Commissioners 4pp 22367 355 24X Fiche 50-289,84/01/27, 8403080393
- 8403070053 Responds to 831214 ltr suggesting Commission refuse to restart Unit 1 until funding for Unit 2 cleanup in place Commission does not believe that Unit 1 restart & Unit 2 cleanup should be tied together PALLADING.N J Commissioners 84/02/08 MURRIS,A E Advisory Council for Decontamination of TMI Unit 2 ip 22563 178 24X Fiche 50-289.84/02/08.8403070053
- 8403020318 Forwards annual update to "Recovery Program Sys Description, Auxiliary Bidg Emergency Liquid Cleanup Sys (EPICOR-11) "Chemical addition section no longer utilized in EPICOR II Sys KANQA.B K General Public Utilities OPU Service Corp 84/02/24 SNYDER.B J TMI Program Office ip 22439 315 24X Fiche 50-320,84/02/24,8403020318
- --8403020323 "Recovery Program Sys Description, Auxiliary Bidg Emergency Liquid Cleanup Sys (EPICOR-II) " * Oeneral Public Utilities - QPU Service Corp 84/02/29 81pp 22437 316 24% Fiche 50-320,84/02/24,8403020318
- 8403130159 Comments on EIB draft suppline occupational radiation dose at TM1-2 Alternatives 1 & 2 unacceptable Alternative 3 acceptable based on reducing occupational seposure w/o delaying fuel removal HAGER:0 W Maryland, State of B4/02/29 SNYDER:8 J TMI Program Office 17pp 22608 147 24x Fiche 50-320.84/02/29.8403130159
- 8403020277 Submits comment on review of draft suppl to programmatic EIS re decontamination & disposal of radwaste resulting from 790328 accident at facility BLANCHARD.0 Interior, Dept of 84/03/01 SNYDER, B J TMI Program Office ip 22440 040 24X Fiche 50-320, 84/03/01, 8403020277
- 8403080410 Responds to 840214 request for 30-day extension to comment on draft suppl to programmatic EIS Due date for comments extended to 840402
 DENTON, H R Office of Nuclear Reactor Regulation, Director 84/03/01 MORRIS, A E Lancaster, PA 2pp 22581 328 24X
 Fiche: 50-320,84/03/01,8403080410
- --B403080412 Requests 30-day extension to comment on programmatic EI8 update
 MORRIS, A E Advisory Council for Decontamination of TMI Unit 2
 B4/02/14 PALLADINO.N J Commissioners 2pp 22581 329 24X
 Fiche 50-320.84/03/01.8403080410
- 8403120261 Grants 840214 request for 30-day extension to submit comments on draft suppl to preliminary EIS Comments now required by 840402 Announcement of extension will be published in FR
 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 84/03/01 MORRIS, A E Advisory Council for Decontamination of TMI Unit 2 3pp 22619 140 24X Fiche 50-320,84/03/01,8403120261
- 8403080267 Forwards updated major milestone schedule for TMI-2 cleanup for 1984, in response to 840131 request KANGA.B K General Public Utilities - GPU Service Corp 84/03/02 SRYDER.B J TMI Propyman Office 7pp 22557 093 24X Fiche 50-320,84/03/02,8403080267
- 8403160041 Comments on NRC review of pyrophoric reactions of zirconium Experiments described in HR Denton 840R17 itr may lead to uninformed or false conclusions GULBRANSEN.E A Pittsburgh, Univ of, Pittsburgh, PA 84/03/02 LEMIS.M Lewis, M ip. 22655 128 24% Fiche 50-320,84/03/02, 8403160041
- --B403160047 Submits petition for appeal of NRR Director's Decision DD-B4-4 on 840217 denying request to postpone headlift Decision ignores obvious dangers LEWIB.M I Lewis. M B4/03/11 PALLADINO, OILINSKY, ROBERTS Commissioners. 3pp 22455 127 24X Fiche 50-320, 84/03/02, 8402140041.
- 8403150311 Comments on 831230 ltr providing plan & schedule for recovering Tech Spec required sys & components Plan acceptable Requests notice on quarterly basis of status of propress in reinstating Tech Baec surveillance requirements SNYDER.B J THI Program Office 84/03/07, KANOA.B K General Public Utilities OPU Service Corp 2pp 22649 314 24% Fiche 50-320.84/03/07,8403150311

- 8403130428 Forwards Rev 3 to "SER for Removal of TMI-2 Reactor Vessel Head" for review & approval KANGA.B K General Public Utilities GPU Bervice Corp 84/03/09 ENYDER, D J THI Program Office 2pp 22608 303 24X Fiche 50-320
- ---8403i30439 Rev 5 to "SER for Removal of THI-2 Reactor Vessel Head" * General Public Utilities - OPU Service Corp 15737-2-007-102 R05 84/02/29 181pp 22608 305 24X Fiche 50-320,84/03/09, 8403i30428
- 8403220195 Responds to 840201 request for info re sources of internal QPU funds available for facility cleanup in 1984 Financial forecast for 1984-86 re spending plans & cash generation will be provided GRAHAM, J O General Public Utilities GPU Service Corp 84/03/09 BALTZMAN, J Office of State Programs, Director 3pp 22717 046 24X Fiche 50-320,84/03/09,8403220195
- 8403230240 Advises that since facility has average coolant temp of less than 200 F & is at zero power; cold shutdown requirements of final rule on licensed operating staffing applicable ENYODER, B J TMI Program Office 84/03/09 KANGA, B K General Public Utilities GPU Service Corp 3pp 22759 275 24X Fiche 50-320,84/03/09,8403230240
- B403280221 Requests response to author 840201 ltr re sources of funding in 1984 for cleanup of facility Svc list anc!
 BALTZMAN, J Assistant Director for State & Licensee Relations 84/03/12 QRAMAN, J O General Public Utilities GPU Service Corp 2pp. 22789-344 24X Fiche 50-320.84/03/12.8403280221
- 8403200201 Forwards annual update to sys description for solid waste staging facility Primary mod deletes ref to completed EPICOR-11 venting & shipping program Remaining changes reflect current plant status KANGALB K General Public Utilities OPU Service Corp 84/03/15 SNYDER, B J TM1 Program Office ip 22698 263 24X Fiche: 50-320,84/03/15,8403200201
- --B403200208 Annual update to "Recovery Program Bolid Weste Staying Facility Sys Description " * General Public Utilities - GPU Service Corp 84/03/15 20pp 22698.244 24X Fiche 50-320.84/03/15.8403200201
- B403270123 Forwards application for amend to License DPR-73, consisting of Tech Spec Change Request 45, increasing max allowable boron concentration in RCB to 3, 000 ppm KINTER, E E General Public Utilities GPU Service Corp 84/03/22 SNYDER, B J TMI Program Office ip 22774 140 24X Fiche. 50-320, 84/03/22, 8403270123
- --B403270127 Application for amend to License DPR-73, consisting of Tech Spec Change Request 45 increasing max allowable boron concentration in RCS to 6,000 ppm # General Public Utilities GPU Service Corp 84/03/22 4pp 22774 141 24X Fiche 50-320,84/03/22,8403270123
- --8403270127 Proposed Tech Specs increasing max allowable boron concentration in RCB to 6,000 ppm
 % General Public Utilities QPU Service Corp 84/03/22 ip 22774.145 24X Fiche 50-320,84/03/22,8403270123
- 8403270210 Application to amend License DPR-73, revising Tech Specs re boron concentration upper limit KANGA.B K General Public Utilities - GPU Service Corp 84/03/22 BARRETT,L.H TMI Program Office 2pp 22770.277 24X Fichs: 50-320,84/03/22,8403270210
- ---8403270212 Proposed Tech Spec changes re boron concentration upper limit. = General Public Utilities -- GPU Service Corp. 84/03/22, 3pp 22770 279. 24X Fiche 50-320,84/03/22,8403270210
- 8403300031 Forwards general & specific comments on Buppl 1 to programmatic E18 Statement should be added to Table 2 ; "Licenses Goals for Dose Rate Reduction" to Indicate goals are for target values only.

 KANDA: H. K. Oeneral Public Utilities QPU Service Corp 84/03/26 BNYDER, B. J TMI Program Office. 12pp. 22821 327 24X Fiche: 50-320: 84/03/26.8403300031.
- Q Inspection reports, IE Bulletins & correspondence
- 8403080408 FOIA request for repts of insp carried out under Condition 2 of Nuclear Energy Liebility policies for facilities CALBDYAS, G. D. Affiliation Not Assigned 84/02/07 Region 3, Office of Director. 4pp. 22567:341 24X Fiche 30-000.84/02/07, 8403080408.

- B403080419 Responds to FOIA request for repts of insp tarried out under Condition 2 to Nuclear Energy Liability policies for facilities NRC does not have repts
 FELTON, J M Division of Rules and Records B4/02/22 CALSOVAS, C D Affiliation Not Assigned ip 22567 345 24X
 Fichs 50-000, B4/02/22, B403080419
- 8403090036 Responds to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " Companies supplying matls or sycs to facility listed Ray Miller matl not installed in safety-related sys at facility KANGA.B K General Public Utilities OPU Service Corp 84/02/23 MURLEY.T E Region 1, Office of Director lipp 22576 038 24X Fiche 50-320,84/02/23,8403090038
- 8403130467 Forwards 1E Insp Rept 50-320/84-02 on 840109-0213 No vialations observed BARRETY, L H THI Program Office 84/02/27 KANGA, B K General Public Utilities + GPU Service Corp 3pp 22613 217 24X Fiche 50-320,84/02/27,8403130467
- --8403130471 IE Insp Rept 50-320/84-02 on 840109-0213 No violations identified Major areas inspected LERs, previous insp findings, radioactive mat) shipments, health physics & environ review & reactor bidg entries
 WIEHE, J., MOSLAK, T., DELL, J. TM1 Program Office 84/02/22 7pp 22613 221 24X Fiche 50-320,84/02/27,8403130467
- 8401190072 IE Info Notice 84-i3, "Potential Deficiency in Motor Operated Valve Control Circults & Annunclation " Svc 11st encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York. Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- B403150125 Discusses IE insp on 831220-21 & forwards notice of violation
 MARTIN.T T Division of Engineering & Technical Programs B4/02/28
 EIBENBUD.M New York Univ Medical Center, New York, NY 2pp
 22640 317 24X Fiche 50-320.84/02/28,8403150125
- --8403150132 Notice of violation from Insp on 831220-21 Violation noted 5 B mCi Ce-144 source transported to & passessed at facility not authorized by specific or general license * Region i. Office of Director 84/02/28 ip 22640 319 24X Fiche 50-320,84/02/28,8403150125
- --B403190139 Discusses B31219 unauthorized use of 5 B mC1 Ce-144 source to aid in calibr of facility phoswitch datector Util personnel unaware of mati until after source unloaded THONUS, L THI Program Office 93/12/23 GLENN, J NRC No Detailed Affiliation Given ip 22640 320 24X Fiche 50-320,84/02/28,8403150125
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA, Bafeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02.8402090007
- B402090008 IE Info Notice B4-16, "Failure of Automatic Sprinkler Sys Vaives to Operate " Syc list enci JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consulidated Edison Co of New York, Inc 122pp 22553 098, 24X Fiche 50-000,84/03/02,8402090008
- B402090009 IE Info Notice B4-15, "Reporting of Radiological Releases "
 Bvc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co. of New
 York, Inc. 119pp 22553 217 24X Fiche 50-000.84/03/02,8402090009
- 8403120101 Ack receipt of 840201 ltr informing NRC of results of analyses of split sample of submerged demineralizer sys effluents per IE Insp Rept 50-320/83-18
 MARTIN,T, T Division of Engineering & Technical Programs. 84/03/02 KANOA, B K General Public Utilities GPU Bervice Corp 2pp 22588, 226 24X Fiche 50-320,84/03/02,8403120101
- --8403120102 Responds to NRC 831229 ltr & forwards results of analyses of split semple of submerged demineralizer sys, per IE Insp Rapt 50-320/83-18 Table encl KANGA, B K General Public Utilities GPU Service Corp. 84/02/01 MURLEY, T E, Region i. Office of Director 3pp 22588 228 24X Fiche 50-320,84/03/02,8403120101
- 8402070011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp." Svc list encl JORDAN, Et. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Egison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000,04/03/05,8402070011

- 8402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York Inc 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 8402070028 IE Info Notice 84-18. "Stress Corrosion Cracking in PHR Bys "Svc list encl JONDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York Inc 118pp 22584 186 24X Fiche 50-000.84/03/07. 8402070028
- B403210047 Forwards IE Insp Rept 50-320/84-01 on 840109-12 & 17-20 No violations noted MARTIN. T T Division of Engineering & Technical Programs 84/03/07 KANOA, B K Oeneral Public Utilities GPU Service Corp 29p 22705 305 24X Fiche 50-320.84/03/09.8403210047
- --B403210034 IE Insp Rept 50-320/84-01 on 840109-12 & 17-20 No violations noted Major areas inspected IE Insp Procedures 82203, 82205, 82210 & 82211 re notifications & communications, shift staffling audits & emergency work protection, respectively TERC, N H. HULTNER, E. GORBONC Z. Region i. Office of Director. B4/02/16 4pp 22705 307 24X Fiche 50-320, 84/03/09, 8403210047
- 8402070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety 8ys " Svc list encl
 DEYOUND.R C Director's Office. Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co. of New York
- B403190213 Ack receipt of 840223 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-320/83-14
 MARTIN.T T Division of Engineering & Technical Programs. 84/03/13
 KANOA, B K General Public Utilities 0PU Service Corp 1p
 22671 120 24X Fiche 50-320.84/03/13.8403190215
- --8403190217 Responds to NRC 840125 itr re violations noted in IE Insp Rept 50-320/83-14 Corrective actions effort made to ensure that lead engineer performing design work will not perform verification & procedure modified KANOA: B K General Public Utilities - GPU Service Corp 84/02/23 MURLEY, T E Region 1. Office of Director 2pp. 22671 121 24X Fiche 50-320,84/03/13,8403190215
- B403290202 Forwards IE Safeguards Insp Rept 50-320/84-03 on 840213-17 No violations noted MARTIN.T T Division of Engineering & Technical Programs B4/03/15 KANOA, B K Cemeral Public Utilities - GPU Service Corp 2pp 22801-001 24X Fiche 50-320.84/03/15.8403290202
- --8403290205 IE Bafeguards Insp Rept 50-320/84-03 on 840213-17 No violations noted Major areas inspected security organization: security program audit; testing & maint, physical barriers, detection aids & communications DUMLAFIJ M. JOYNERJJ, H. Region 1. Diffice of Director 84/03/15 5pp 22801 003 24X Fiche 50-320.84/03/15.8403290202
- 8402090043 IE info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities " Byo list enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000.84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related 8ys " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp. 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Pariodic operating reports & related correspondence
- B403120334 Forwards TMI Program Oft weekly status rept for wk of B4021B-25
 BARRETT, L H TMI Program Office B4/02/27 DENTON, H R Office of Nuclear Reactor Regulation, Director BNYDER, B. J. TMI Program Office iOpp 22596 343, 24x Fiche 50-320, 84/02/27,8403120334.
- 8403210059 Forwards "Aircraft Movements at Harrisburg Intl Airgort, 1983" & "Number of Personnel & Man Rems by Work & Job Function, 1983 "
 KANGA, B K Qaneral Public Utilities OPU Bervice Corp 84/02/28 MRLEY, T E Region 1, Office of Director 2pp 22704:350 24X Fiche 50-320,84/02/28,8403210059
- --8403210064 "Aircraft Hovements at Harrisburg Intl Airport, 1983 "

 ** General Public Utilities OPU Bervice Corp 83/12/31 ip.
 22704: 352 24% Fiche 50-320, 84/02/28, 8403210059

- --B40321007; "Number of Personnel & Man Rems by Work & Job Function, 1983 "

 * General Public Utilities - GPU Service Corp B4/02/16 ip 22704 353 24X Fiche 50-320,84/02/28,8403210059
- B403130475 Forwards "Quarterly Dose Assessment Rept, Fourth Quarter 1983" & "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1983"
 KANGA.B K General Public Utilities GPU Service Corp 84/02/29
 MURLEY.T E Region 1, Office of Director 2pp 22614 064 24X
 Fiche 50-320.84/02/29,8403130475
- --8403130483 "Quarterly Dose Assessment Rept.Fourth Quarter 1983 "
 # General Public Utilities QPU Service Corp 83/12/31 4pp 22614 066 24X Fiche 50-320,84/02/27,8403130475
- --8403130489 "Semiannual Radioactive Effluent Release Rept.Jul-Dec 1983 "
 # General Public Utilities GPU Service Corp 83/12/31 25pp,
 22614 070 24X Fiche 50-320,84/02/29,8403130475
- 8403210138 Forwards personnel exposure rept for 1983, including total count of personnel monitored & number of personnel in each whole body exposure range HUKILL, H D General Public Utilities QPU Service Corp 84/03/01 MURLEY, T E Region 1. Office of Director 1p 22707 088 24X Ficha 50-287,84/03/01,8403210138
- --8403210146 Personnel exposure rept for 1983 * General Public Utilities - GPU Service Corp 83/12/31 2pp 22707 089 24X Fiche 50-289,84/03/01.8403210138
- 8403120233 Forwards TMI Program Ofc weekly status rept for wk of 840226-0303 BARRETY,L W TMI Program Office 84/03/05 DENTON,H R Office of Nuclear Reactor Regulation, Director SNYDER,B J TMI Program Office 12pp 22615 342 24X Fiche 50-320,84/03/05,8403120253
- S Reportable occurrences, LERs & related correspondence
- 8403060426 Forwards Figures 8-8 & 8-9 inadvertently omitted from 840208 response to NRC 840104-06 audit questions re auxiliary bldg underpinning MCONEY, J A Consumers Power Co 84/02/27 HARRIBON, J J Region 3, Office of Director 6pp 22518 194 24X Fiche 50-320,84/02/27, 8403060426
- 8403260233 Forwards summary list of deficiencies identified per iOCFR50 55(e).Part 21 & potential generic ltr repts for comments
 BTAROSTECKI.R Division of Project & Resident Programs 84/02/28 Region i. Office of Director 7pp 22756 065 24X Fiche 50-000.84/02/28.8403260233
- B403060103 PND-TMI-84-002 licensee pleaded guilty to one count of using incorrect procedure to determine RCS water inventory & noic contenders on six of remaining 10 counts, subj to final acceptance by court on 840229 FABANCIA, JARRETT, L TMI Program Office 84/02/29 ip 22517 018 24% Fiche 50-320,84/02/29,8403060103
- B403060110 PND-TMI-B4-003 on B40229, load test of reactor bldg polar crane scheduled Load test will qualify crane to lift 170 ton reactor vessel head NRC plans to continue monitoring events
 MOSLAK, T., QASANO, A., BARRETT, L. THI Program Office, 84/02/29 ip
 22518 310 24X Fiche 50-320,84/02/29;8403060110
- 8403060144 PNO-THI-84-002A on 840229, court accepted licensee plea of guilty to one count of using incorrect procedure to determine RCS water inventory & plea of nolo contendere on six of remaining 10 counts.
 FASANO, A. BARRETT, L. TMI Program Office 84/02/29 ip 22513 350. 24X Fiche 50-320,84/02/29,8403060144
- 8403060435 PNO-TMI-84-003A on 840227, qualification load test of reactor bldg polar crans completed Load test qualified crans to lift 170 ton reactor vessel head scheduled for summer MOSLAK, T., FABANO, A., BARREIT, L. TMI Program Office 84/03/01 1p 22511 362. 24X Fichs 50-320,84/03/01,8403060435.
- 8403280006 LER 84-002-00 on 840216, determined that load test for polar crane procedure failed to incorporate adequate isolation requirements for nonborated water sources Tests from 840213-16 conducted in unanalyzed condition W/840314 ltr. GOULD.T.L. KANOA.B K General Public Utilities GPU Service Corp. 84/03/14 MRLEY,TE Region 1 Office of Director. 2pp. 22777:171 24X Fiche 50-320,84/03/14.84032800006

- B403300074 PNS-I-B4-003 on B40324, male phoned Jersey Central Power & Light Customer Svc Ctr & notified that FFA will start demolishing plants Oyster Creek implemented emergency contingency plan & TMI increased security awareness MADDEN, W Region 1. Office of Director 84/03/26 ip 22822 OBS 24X Fiche 50-000, 84/03/26, 8403300074
- U Congressional/Executive Correspondence
- B403070053 Responds to 931214 1tr suggesting Commission refuse to restart Unit 1 until funding for Unit 2 cleanup in place Commission does not believe that Unit 1 restart & Unit 2 cleanup should be tied together PALLADING.N J Commissioners B4/02/08 MORRIS.A E Advisory Council for Decontamination of TMI Unit 2 1p 22563 178 24x Fiche.50-289.84/02/08.8403070053
- ---8403070060 Responds to 831213 ltr re criminal indictment of Met Ed & cleanup of Unit 2 Commission does not believe delaying rastert would accelerate Unit 2 cleanup Unit 1 restart & Unit 2 cleanup should not be tied together PALLADINO.N J Commissioners 84/02/08 MORRIS, A E House of Rep 1p 22563:199 24X Fiche 50-289,84/02/08,8403070053
- --B403070069 Responds to B31207 1tr urging Commission not to authorize restart of Unit 1 Commission views on restart set forth in enci B40127 notice to parties Commission does not believe Unit 1 restart & Unit 2 cleanup related PALLADINO,N J Commissioners B4/02/08 GEKAB,O W House of Rep 1p 22563,200 24X Fiche 50-289,84/02/08,8403070053
- --8403070073 Urges Commission not to accept recommendation to restart Unit 1 in light of mpt integrity review & criminal proceedings & slow pace of Unit 2 cleanup OEKAB,O W House of Rep 83/12/07 PALLADING,N J Commissioners, 1p 22563 217 24X Fiche 30-289,84/02/08,8403070053
- --8403070076 Advises of convictions re Unit 1 restart Due to criminal indictments & belief that Unit 1 revenue should go directly toward Unit 2 cleanup.recommends against restart HALKER.R 8 House of Rep 83/12/13 PALLADINO,N, ASSELSTINE,J, BERNTHAL,F Gommissioners ip 22563 218, 24X Fichs 30-289,84702/08.8403070033
- DOGKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- B403070282 Public version of Rev O to Emergency Plan Implementing Procedure HNP-8161, "Eberline Model PCM-1 Portal Monitor" & Rev 17 to HNP-B008, "Rediation Work Permit" W/84018 1tr & JM Felton 830307 release memo. BURRELLIE C, NIX.H.C. Georgia Power Co 84/01/18 46pp 28393 321 24X Fiche.50-321,84/01/18.8403070282
- 8403300339 Public version of transmittal & title pages of deleted Emergency Plan Implementing Procedures HNP-8017, "Insp of Bteel Radwaste Shipping Drums" & HNP-8422, "Handling & Loading of Chem-Nuclear Cask " H/840119 ltr & 840322 memo BDRRELL,E C , NIX.H C Georgia Power Co 84/01/25 App 22842 306 24X Fiche 50-321,84/01/25,8403300339
- 8403260261 Forwards order confirming licensee commitment to implement post-TMI-related itmes in NUREG-0737, Suppl 1 (Generic Ltr 82-33), "Requirements for Emergency Response Capability," STOLZ, J. F. Operating Reactors Branch 4, 84/02/21 BECKHAM, J T Georgia Power Co. 3pp 22763 179, 24% Fiche, 50-321, 84/02/21, 8403260261
- ---B403260265 Order confirming licensee commitments on emergency response capability requirements set forth in NUREQ-0737, Suppl 1 (Qeneric Ltr 82-33), EISENHUT, D. O., Division of Licensing 84/02/21 Qeorgia Power Co., 6pp. 22763:182 24X Fiche 50-321.84/02/21.8403260261.
- 8403070067 Forwards rev to physical security plan Rev withheld (ref 10CFR2.790 & 73 21). Transmittal ack encl BECKMAN.J.T. Georgia Power Co. 84/02/27 O'REILLY, J. P. Region 2. Diffice of Director. 2pp 22575 351 24X Fiche: 50-321, 84/02/27, 8403070067
- 8403130165 Revs 6 & 7 to Emergency Plan Implementing Procedures HNP-8006, Rev 9 to HNP-8007 & Rev 0 to HNP-8043 re decontamination & Rev 8 to HNP-4860. HP-4867, 4868 & 4869 re reveiw & rev to emergency plan W/840306 ltr SORRELL, E C Georgia Power Co. 84/03/02 124pp 22600, 132 24X Fiche: 50-321, 84/03/02, 8403130165

- B403130346 Advises that next annual emergency exercise scheduled for B40B02 State of GA & local govts do not plan to fully participate Exemption to 100FR50.App E necessary to proceed w/exercise Reply requested if date & exercise acceptable BECKHAM.JT Georgia Power Co B4/03/02 DENTGN.HR Office of Nuclear Reactor Regulation, Director 1p 22607 149 24X Fiche 50-321.84/03/02.8403130346
- 8403160150 Notifies of 840316 workshop meeting to discuss 10CFR50, App R requirements & associated inspiresults to resolve fire protection misunderstandings Number of attendees should be limited to six due to conference room size

 LEWIS, R C Region 2. Office of Director 84/03/02 KELLY, R J Georgia Power Co 1p 22655 317 24X Fiche 50-321,84/03/02, 880346030
- 8403130004 Transmittal & title pages of deleted emergency plan implementing procedures, including HNP-1-4205 re turbine lube oil reservoir oil fire & HNP-1-4206 re turbine lube oli conditioner & storage fire #/840306 itr
 SURRELL, E C Georgia Power Co 84/03/06 i2pp 22615 i83 24X Fiche 50-321,84/03/06,8403130004
- B403260150 Revised emergency plan implementing procedures, including Procedure HNP-8033 re quantitative fit testing, Procedure HNP-4526 re alert emergency rally point leader & Procedure HNP-8010 re use & care of respirators W/840320 ltr SORRELL-E C Georgia Power Co 84/03/20 114pp 22758 270 24X Fiche 50-321,84/03/20,8403260150
- 8403300143 Rev & to Emergency Plan Implementing Procedures HNP 4726 & 4626 & Rev 8 to Procedure HNP-8012 re general & site area emergency relip point leaders & radiation & contamination surveys W/840326 ltr 80RELL,E C Georgia Power Co 84/03/26 l19pp 22820 083 24X Fiche 50-321,84/03/26,8403300143
- J Insurance & indemnity information
- 8403060281 Forwards Endorsement 85 to NECIA Policy NF-215 BUCK.JR Marsh & McLennan, Inc 84/02/28 SALTZMAN.J Assistant Director for State & Licenses Relations 2pp 22518-187 24X Fichs 50-321.84/02/28.8403060281
- B40328003B Forwards Endorsements 86 & 87 to NELIA Policy NF-2:5 & Endorsements 70 & 71 to MAELU Policy MF-78 DUCK.JR Marsh & McLennan. Inc 84/03/2: SALTZMAN.J Assistant Director for State & Licensee Relations 5pp 22777.010 24X Fiche 50-32!.84/03/2!080038
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8402270263 Responds to FOIA request for JC Mark 801204 memo to ACRB re hydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards App A documents App B documents in FDR FELTON, J M Division of Ruies and Records 84/01/30 HIATT, 8 L Ohio Citizens for Responsible Energy 7pp 22412.051 24X Fiche 50-000,84/01/30.8408270263
- --8402270314 Forwards summary of investigations re hydrogen recombiners & relay failures in HPCI sys
 ZUKOR.D J ACRB Advisory Committee on Reactor Safeguards
 80/10/30 MOELLER.D W ACRB Advisory Committee on Reactor
 Safeguards 4pp 22412 086 24X Fiche 50-000.84/01/30,
 8402270263
- P Operating license stage documents & correspondence
- B401120456 Notlfication of B40214 meeting w/GPU.Bechtel & Southern Svcs Co in Bethesda,MD to discuss equipment qualification RIVENBARK.0 W Operating Reactors Branch 4 84/01/09 STOLZ,J F Operating Reactors Branch 4 2pp 21804,101 24X Fiche 50-321.84/01/09,8401120456
- 8403090187 Appilcation for amend to Licenses DPR-57 & NPF-5, revising Tach Specs re listed TMI Action Plan Items, per Generic Ltr 83-36
 BECKHAM, J T Georgia Power Co 84/02/06 STOLZ, J F Operating Reactors Branch 4 Spp. 22573 276 24X Flohe 50-321,84/02/06,8403090187
- --8403090196 Proposed Tech Specs re instrumentation providing surveillance info.post-accident sampling & analysis & post-accident monitoring instrumentation * Georgia Power Co. 84/02/06 | 18pp | 22573 284 24X Fiche 50-321

- 8403160226 Reviews 840112 meeting to discuss responses to 831004 request for add1 info needed to review QA program description List of meeting attendees ent1 LEMIS.R C Division of Project & Resident Programs 84/02/07 KELLY.R J Georgia Power Co 3pp 22661 064 24X Fishe 50-321.84/02/09.8403160226
- 8403050085 Discusses analyses on 22 safety relief valve (SRV) discharge lines per B21227 request to address questions re SRV test program per TMI Item II D I Analyses indicate supports & piping geometry adequate GUCHALL T Georgia Fower Co 84/02/10 BTOLZ, J F Operating Reactors Branch 4 2pp 22470 007 24X Fiche 50-321,84/02/10,8403050085
- 8403060436 Forwards notice of consideration of issuance of Amenda 97 & 34 to Licenses DPR-57 & NPF-5, respectively & proposed NSHC determination & opportunity for hearing retime requirements for scram discharge vol vent & drain valves RIVENBARK, Q Uperating Reactors Branch 4 84/02/21 BECKMAN, J T Georgia Power Co 3pp 22049 344 24X Fichs 50-321,84/02/21.
- --8403060440 Natice of consideration of issuance of Amenés 97 % 34 to Licenses DPR-97 & NPF-5, respectively & proposed NSHC determination & opportunity for hearing STOLZ.J F Operating Reactors Branch 4 84/02/21 8pp 22549 347 24X Fiche 50-321.84/02/21,8403060436
- 8403140340 Summary of B31215 meeting w/GE & Mark | Cuners Group in Bethesda: MD re Mark | containment wetwell-drywell vacuum breaker design methodology SIEGEL. D. Derating Reactors Dranch 2 84/02/21 Operating Reactors Branch 2 Sipp 22635 19B 24X Fiche 50-000,84/02/21, 8403140340
- 8403010110 Forwards Amends 98 & 25 to Licenses DPR-57 & NPF-5, respectively & safety evaluation Amends revise Tech Specs to extend time alloyed to restore thermal power scram & control rod block trip setpoints within Tech Spec limits RIVENBARK, G Operating Reactors Branch 4 84/02/22 BECKHAM, J T Georgia Power Co 2pp 22477 281 24X Fiche 50-321, 84/02/22, 8403010110
- --B403010124 Amends 9B & 35 to Licenses DPR-07 & NPF-5, respectively, ravising Tech Specs to extend time allowed to restore thermal power scram & control rod block trip setpoints within Tech Specs limits
 SIOLZ_JF Operating Reactors Branch 4 B4/02/22 15pp 22479 283 24% Fische 50-521,84/02/22,8403010110
- --8403010128 Safety evaluation supporting Amends 98 & 35 to Litenses DPR-57 % NPF-5 respectively * Office of Nuclear Reactor Regulation, Director 84/02/22 3pp 22479 298 24% Fiche 50-321.84/02/22,8403010110
- 8403070337 Forwards request for additinfo to complete review of proposed programs for inservice testing of pumps & values submitted in 830812 ltr Info requested within 30 days STOL7.J F Operating Reactors Branch 4 84/02/23 BECKHAM.J T Georgia Power Co 4pp 22564 134 24% Fiche 50-321.84/02/23.8403070337
- 8403070251 Forwards update on facilities conformance & info re glans & schedules for any needed improvements & rept re vendor equipment technical info program by Nuclear Util Task Action Committee on Generic Ltr 83-28. Section 2 2 2 GUCWALL T Georgia Power Co 84/02/29 BTOLZ, JF Operating Reactors Branch 4 24pp 22536 069 24X Fiche 50-321.84/02/29, 8403070251
- --8403070252 "Vendor Equipment Technical Info Program," per Generic Ltr 83-28, Section 2 2 2.final draft * Nuclear Utility Task Action Committee 84/02/29 63pp 22536 112 24X Fiche 50-321,84/02/29,8403070251
- 8403260045 Forwards Amend 99 to License DPR-57 Amend changes Tech Spacs to delete drywell-to-torus differential pressure sys STOLI.J F Operating Reactors Branch 4 G4/03/06, BECKHAM, J T Georgia Power Co 3pp 22763 284 24X Fiche 50-321,84/03/06, 8403260045
- --8403260048 Amend 77 to License DPR-57, changing Tech Specs to delete drywell-to-torus differential pressure sys STOLZ.J F Operating Reactors Branch 4 84/03/06 7pp 22743 287 24X Fiche 50-321,84/03/06,8403260045
- B403200005 Responds to B40229 request for add1 action to verify aspects of overhead crane design at facility.per NUREG-0612 guidelines Crane safety & reliability satisfactory OUCMALT Georgia Power Co B4/03/12 STOLZ.JF Operating Reactors Branch 4 2pp 92685 209 24X Fiche 50-321.84/03/12, B403200005

- 8403150275 Generic Ltr 84-07 to all licensees of BHRs re procedural guidance for pipe replacement at BHRs Svc list encl EISENHUT, D G Division of Licensing 84/03/14 Commonwealth Edison to 20pp 22823 354 24X Fiche 50-000.84/03/14,8403150275
- G Inspection reports, 1E Bulletins & correspondence
- 8403160196 Forwards IE Insp Repts 50-321/84-04 & 50-366/84-04 on 840204-07 No violations or deviations identified DANCE: HC Division of Project & Resident Programs 84/02/24 KELLY: R T Georgia Power Co 2pp 22655 351 24X Fichs 50-321,84/02/24,8403160196
- --8403160198 IE Insp Repts 30-321/84-04 & 50-366/84-04 on 840204-07 No violations or deviations identified Major areas inspected torus vent header cracking feedwater line ultrasonic indication & recirculation piping replacement CROWLEY, B R , BLAME, J J Region 2, Office of Director, 84/02/23 dpp 22655 353 24X Fich# 50-321,84/02/24,8403160196.
- B401190072 (E Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Evc list encl QRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24x Fiche 50-000,84/03/02,8402090007
- B40207000B IE Info Notice B4-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list entl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402070008
- 8402070009 [E Info Notice 84-15, "Reporting of Radiological Releases"

 Byc list enci

 JORDAN-E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 117pp. 22553 217 24X Fiche 50-000.84/03/02.8402090009
- 8402090011 IE Info Notice 84-17, "Problems H/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05,8402090011
- 8402090024 IE Info Notice 84-09. Rev 1, "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl, JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000,84/03/07,8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list encl, JORDAN, El Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fichs 50-000,84/03/07,8402070028
- 8403160338 Ack receipt of 840206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-32 & 50-326/83-34
 DANCE, H C Division of Project & Resident Programs. 84/03/09
 XELLYR J Georgia Power Co. 1p 22660 015 24X
 Fiche 50-321,84/03/09,8403160338
- --B403i40349 Responds to NRC 840104 ltr re violations noted in IE Insp Repts 50-321/83-32 & 50-364/83-34 Corrective actions: proceedure revs drafted & undergoing review & approval process QUCHA.L T Georgia Power Co 84/02/06 D'REILLY, J. P. Region 2, Dffice of Director 2pp 22660 016 24X Fiche 50-321, 84/03/09, 8403160338
- --8403160357 Forwards 1E Insp Repts 50-321/83-32 & 50-366/83-34 on B31114-18 & notice of deviation DANCE, H C Division of Project & Resident Programs, 84/01/06. KELLY, R. J Georgia Pawer Co Zpp 22660;018 24X Fiche 50-321,84/03/09,8403160338
- --B403160365 Notice of deviation from insp on 831114-18 * Region 2, Office of Director 84/01/06 1p 22660-020, 24X Fiche 30-321,84/03/09,8403160338

- --8403i60372 IE Inep Repte 50-32i/83-32 & 50-366/83-34 on B3lilq-18 Deviation noted failure to electronically callbr high range drywall radiation monitors, per NUREO-0737. Item II F I WRAY, J R Region 2, Office of Director BARR K P Division of Engineering & Operational Programs 84/01/04 7pp 22660, 021 24X Fiche 50-321, 84/03/09, 8403160338
- 840209003i IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Bafsty Bys " Syc list encl DEYOUNG, R C Director's Office of Inspection and Enforcement 84/03/12 Consolidated Edieon Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8403290193 Ack receipt of 840301 itr informing NRC of etepe taken to correct violations noted in IE Insp Rept 50-366/83-26 LEWIS.R C. Division of Project & Resident Programe 84/03/15 KELLY.R J. Georgia Pawer Co ip 22801 008 24X F1che.50-366.84/03/15,8403290193
- --8403270i74 Rssponds to NRC 84020i ltr re violations noted in IE Insp Repts 50-321/83-25 & 50-366/83-26 on 83072i-0820 Corrective actions administrative controls to strsse indspendent verification upgraded BECKHAN, J T Gsorgia Power Co 84/03/01 D'REILLY, J P Region 2, Office of Director App 2280i 009 24X Fichs 50-366, 84/03/15.8403270i73
- --8403270175 Forwards IE Insp Rspts 50-321/83-25 & 50-366/83-26 on 830721-0820 & notice of violation LEMIB-R.C Division of Project & Resident Programs 84/02/01 XELLY,R J Gsorgia Powsr Co 2pp 22801 015 24X Fichs.50-366.84/03/15.8403270173
- --8403290197 IE Insp Repts 50-321/83-25 & 50-366/83-26 on 830721-0820 Violations noted safety-related equipment & sys not aligned & limiting condition for operation for main etem isolation leakage control eys not established CRLENJAKIR V., HOLMES-RAY,P , PANCIERA,V W Region 2, Office of Director 84/01/28 Spp 22801 018 24X Fiche 50-366,84/03/15,8403290193
- 8403270208 Ack rsceipt of 840301 itr informing NRC of steps taken to correct violations noted in IE Inep Rept 50-321/84-03 DANGE:H C Division of Project & Resident Programs, 84/03/19 KELLYR J. Georgia Power Co ip 22800 302 24X Fiche 50-321,84/03/19,8403270208
- --8403270212 Rssponds to NRC 840210 ltr re violations noted in lE Inep Repts 50-321/84-03 & 50-366/84-09 Corrective actions NDE personnel reminded of importance of proper & complete data recording.

 QUCHA, L. T Quorgia Power Co 84/03/01 O'REILLY, J P Region 2: Office of Director. 2pp 22800 303 24X Fiche 50-321, 84/03/19, 8403290208
- --8403290215 Forwards iE Insp Rspts 50-321/84-03 & 50-366/84-03 on 840124-27 & notics of violation DANCE,H.C. Division of Project & Resident Programs 84/02/10 KELLY,R J. Georgia Powsr Co. 2pp 22800 305 24X Fichs 50-321,84/03/19,8403290208
- ---8403290216 Notice of viplation from insp on 840124-27 * Region 2. Office of Director 84/02/10 ip 22800 307 24X Fichs.50-321,84/02/17,8403290208
- ---B403290219 IE Inep Rspte 50-321/84-03 & 50-366/84-03 on 840124-27 Violation noted ultrasonic insp rscords for Fall 1982 insp of reactor vessel flange to Sheli Wald C-I did not show extent or location of area CROMLEY.B.R Region 2. Office of Director BLAKE.J J Division of Emergancy Preparedness & Materials Eafety 84/02/09 11pp 22800 308. 24X Fiche 50-321.84/03/19.8403290208
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unguthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Poet 830103), 84/03/21. Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fichs 50-000,84/03/21,8402070043
- 8402070044 IE Info Notics 84~20, "Syc Life of Relays in Safety-Related 8ys." Syc list enr!

 JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp. 22933 Ooi 24X Fiche 50-000.84/03/21.8402070044
- R. Periodic operating reports & related correspondence
- 8403130071 Monthly operating repts for Feb 1984 W/840310 1tr RAFEEDIE.D P . NIX.H C Georgia Power Co 84/02/29 12pp 22443:191 24X Fiche 50-321.84/02/29.8403150071

- 8 Reportable occurrences, LERs & related correspondence
- 8403090228 Supplemental narrative summary to LER 50-321/1979-021.Rev 5 providing updated data re tritium levels in groundwater samples during Third Quarter 1983 presented in enci Table i W/840208 ltr NIX.H C Georgia Power Co 84/01/31 O'REILLY.J P Region 2. Office of Director 3pp 22571 237 24X Fiche 50-321.84/01/31.8403090228
- 8403010330 Forwards supplemental narrative summary to LER 50-321/79-021, Rev 5 Groundwater problems reviewed w/Region II personnel on 831219 Problems not environ concern in regulatory sense Rept closes LER NIX.H C Georgia Power Co 84/02/08 O'REILLY, J P Region 2. Office of Director 3pp 22432 073 24X Fiche 50-321,84/02/08,8403010330
- 8403160044 LER 84-001-00 on 840211.reactor scram followed high vibration turbine trip Caused by bucket & fingsr damage to both 13th stages of low pressure turbine A Stage 13 will be replaced at later date W/840309 ltr
 TIPPS.6 B . NIX.H C Georgia Power Co 84/03/09 4pp 22655.120 24X Fiche 50-321.84/03/09.8403160044
- 8403300104 Advisss that program of periodic manual operation of safety relief valves will be discontinued, based on results of BMR Owners Group investigation Safety relief valve cycling caused valvee to lask prematurely GUCHALL T Georgia Power Co 84/03/26 STOLZ, J F Operating Reactors Branch 4. 2pp 22821 216 24X Ficks 50-321,84/03/26,8403300104
- DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION
- A Application/construction stage documents & correspondence
- 8403080363 FOIA request for documents re BWR Intergranular Stress Corrosion Cracking Dunsse Graup meeting on or about 811028 HAFNER, B Suffolk Nuclear Study Oroup 83/11/26 Office of Administration ip 22583 007 24X Fiche 50-322,83/11/26, 8403080363
- B403020i39 Provides justification for deletion of station blackout tast & completion of program for training during iow power testing.per TMT Item i G is in response to Generic Ltr B3-24 MCCAFFREY.B R Long Island Lighting Co 84/02/i6 DENTON.H R Office of Nuclear Reactor Regulation. Director Bpp 22443 245 24X Fiche 50-322:84/02/i6.8403020i39
- 8403080367 Responds to FOIA request for documents re EWR Integranular Stress Corrosion Cracking Dwners Group meeting on or about 811028 Forwards App A documents Records also in PDR FELTON, J M Division of Rules and Records 84/02/28 HAFNER, B Suffolk Nuclear Study Group 2pp 22583 008 24X Fiche 30-000,84/02/28,8403080367
- --8309210434 Requests evaluation of Grand Gulf & Bhoreham 830817 & 23 responses, reepectively re intergranular strsss corrosion cracking in BHR piping Response requested by 830916 W/o enci
 EIBENHUT, D O Division of Licsnsing 83/09/06 VOLLMER, R
 Division of Enginssring ip. 22583 010 24X
 Fiche 50-000,84/02/28,8403080367
- 840309001B Responds to FOIA request for documents re BNL background radiation survey DDE preparing Shoreham & BNL site repts When printed Shoreham rept will be available from NRC & BNL rept will be available from DOE FELTON.J M. Division of Rules and Rscords 84/03/02 QROSSMAN.K Island Closeup Naws Service. Eag Harbor, NY 1p 22372 344 24X Fiche 50-322.84/03/02.8403090018
- B403i400i9 Clarifies Bept 1983 draft technical evaluation rspt of Phase II submittal of control of heavy loads, per 840i09 telcon Bafe load paths for rsactor bldg closed loap cooling water pumps revised MCCAFFREY, B R Long Island Lighting Co 84/03/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 22633 218 24X Fiche 30-322,84/03/05,8403i40019
- 8403140126 Forwards NRC Region I morning repts rs facility emergency diesel generatore for 840215-0301 GODDARD.R J Hearing Branch 3 84/03/05 BRENNER.L, FERGURGN.G A. MORRIS.P. A Atomic Safety and Licensing Board Panel 13pp 22620 341 24X Fiche 50-322,84/03/05,8403140126

- 8403200302 Forwards response to Generic Ltr B3-28. "Required Actions Based on Generic Implications of Salem ATHS Events " Encl addresses each NRC position & describes actions taten by util in response MCCAFFREV.B B Long Island Lighting Co 84/03/09 DENTON.H R Office of Nuclear Reactor Regulation. Director 50pp 22696 177 24X Fiche 50-322.84/03/09.8403200302
- 8403200227 Responds to Generic Ltr 84-01 providing description of NRC position on regulatory jurisdiction involving terms important to safety & safety-related Util wishes to discuss subj further MCCAFFREY.B R Long Island Lighting Co 84/03/13 DENTON.H Office of Nuclear Reactor Regulation. Director 2pp 22690 188 24X Fiche 50-322.84/03/13.8403200227
- 840209004) Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EJSENNUT.D O Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000.84/03/14.8402090041
- 8403270116 Forwards supplemental nuclear power plant experience tables for operating shiff positions Expected QL date is 840515.in response to add questions in DF Schnell.Union Electric Co. ltr. NOTARO, J. A. Long Island Lighting Co. 84/03/22 DENTON.H R. Office of Nuclear Reactor Regulation, Director Spp. 22775 157 24% Fiche 50-322.84/03/22.8403270114
- 8403290248 Requests that Suffolk County, NY be notified in advance of any discussions or meetings w/util & be invited to participate County requests copies of documents re review of util 840320 supplemental motion for low power OL LANPHER, L C Kirkpotrick, Lockhart, Hill, Christopher & Phillips LANPHER, L C Buffolk County, NY 84/03/23 DENION, H R Office of Nuclear Reactor Regulation, Director 2pp 22800 215 24X Fiche 50-322,84/03/23.8403290248
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403020287 Forwards "Rept on Special Lifting Devices," per 831111 response to SER Open Item 59 Rept covers design, fabrication & Initial acceptance testing of six special lifting devices listed in Table 3 of 810717 ltr MCCAFFREY, B R Long Faland Lighting Co 84/02/21 DENTON. H R Office of Nuclear Reactor Regulation, Director 3pp 22441 268 24X Fiche 50-322.84/02/21,8403020287
- ~-8403020290 "Rept on Special Lifting Devices" * Stone & Webster Engineering Corp 11600 02 84/02/10 47pp 22441 271 24X Fiche 50-322.84/02/21,8403020287
- 8403270119 Forwards monthly status "List of Active Safety-Related Equipment at Qualification Level." per SER Issue 9 redynamic qualification
 MCCAFFREY, B R long Island Lighting Co 84/03/15 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 22774 062 24X Fiche 50-322,84/03/15,8403270119
- ~-8403270122 "Control Bldg Category | Equipment Balance-of-Plant Qualification Level," monthly status rept * Etone & Nebster Engineering Corp 84/02/27 50pp 22774 064 24X Fiche 50-322,84/03/15.8403270119
- F Security, medical, emergency & fire protection plans
- 8403290160 Forwards Rev 3 to local offsite radiological emergency response plan
 SHITH.J Long Island Lighting Co 83/12/21 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 22804 001 24X
 Fiche 50-322,63/12/21,8403290160
- --8403290165 Rev 3 to local offsite radiological emergency response plan W/17 oversize Figures * Long Island Lighting Co 83/12/21 700pp 22804 021 24X Fiche 50-322,83/12/21,8403290160
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in slectrical cabinets in control room EISENHUT.D 0 Division of Licensing 84/02/23 PALLADING Commissioners ip 28574 203 24% Fiche 50-000-84/02/23, 840209000A
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRR OFC Ltr 19.4td 821001 Further svaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT.D O Division of Licensing 10pp 22976 204 24X Fiche 50-000.84/02/23,8402090006

- B403170243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown inep & topics described in IE Info Notice 34-09 Agende for workshop encl MURLEY.7 E Region I. Office of Director 84/03/09 O'TOOLE, U D Consolidated Edison Co. of New York. Inc. DALTROFF, B L. Philadelphia Electric Co. HUKILL, H D. General Public Utilities GPU Service Corp. 35pp. 22672 062 24X Fiche 50-000, 84/03/09, 8403190243
- 84D3270245 Forwards revised safeguard license condition resulting from review of Rev 2 to guard training & qualification plan Rev 2 changes acceptable MIRAGLIA.F J Assistant Director for Safety Assessment 84/03/09 NOVAK, T M Assistant Director for Licensing 3pp 22789 272 24X Fiche 50-322.84/03/09,6403270245
- 8403190363 Forwards evaluation of LILCO transition plan per NURE9-0654/ FEMA-REP-1, Rev 1 Deficiencies noted SPECK, 9 W Federal Emergency Management Agency 84/03/15 DIRCKB, W J Office of the Executive Director for Operations 71pp 22673 081 24X Fiche 50-322,84/03/15,8403190363
- B403260113 Forwards FEMA review of Rev 3 to util transition plan for offsite emergency preparedness, per NUREO-0654
 MARTIN, T T Division of Engineering & Technical Programs B4/03/20
 FOLLOCK, M S Long Island Lighting Co 3pp 22758 001 24X
 Fiche 50-322.84/03/20.840326013
- --B403260117 Review of Rev 3 to util transition plan for offsite emergency preparadness, per NUREO-0654 * Federal Emergency Management Agency 84/02/10 66pp 22758 004 24X Fichs 50-322,84/03/20.8403260113
- 8403280029 Forwards Rev 7 to amended security plan Rev withheld (ref 10CFR73 21) MCCAFFREY,B R Long Island Lighting Co 84/03/22 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 22777 048 24X Fishe 50-322,84/03/22,8403280029
- O Adjudicatory correspondence
- 8403280063 Vtil Bafety Classification Group brief amicus curiae objecting to ASLB distinction between regulatory terms important to safety & safety-related EARLEY, A F Utility Safety Classification Group 83/12/23 Atomic Safety and Licensing Appeal Panel 38pp 22813 001 24X Fiche 50-322.83/12/23.8403280063
- 8403010220 Revises svc list, adding BR McCaffrey & deleting JL Smith Certificate of Svc encl BRITT.L F Long Island Lighting Co 84/02/24 BRENNER, L J , FERGUSDN, G A , MORRIS, P A Atomic Safety and Licensing Board Panel 3pp 22435 235 24X Fiche 50-322.84/02/24,8403010220
- 8403010183 Motion opposing Suffolk County motion for extension of time to respond to DDE summary disposition motions Request untimely & unsupported by good cause Certificate of Svc sent? Related correspondence
 MCCLESKEY.K E Long Island Lighting Co MCCLESKEY.K E Hunton & Williams 6402/27 Atomic Sefety and Licensing Board Panel 5pp 22435 302 24% Fiche 50-322.84/02/27.8403010183
- B403010195 Motion for leave to file surrebuttal testimony on Contention 23 re shadow phenomenon in interest of allowing ASLB to hear clash among experts, testimony should be allowed Certificate of Svc encl Related correspondence CHRISTMAN.J N Long Island Lighting Co CHRISTMAN.J N Hunton & Williams B402/27 Atomic Safety and Licensing Board Panel. 7pp 22435 291 24X Fiche 50-322,84/02/27,8403010195
- 8403010234 Motion for extension of time until 840306 to respond to LILCO summary disposition motions on Contentions 24 8,33,45,46 & 49 Related correspondence LETSCHE,K J Suffalk County, NY LETSCHE,K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/02/27 Atomic Safety and Licensing Board Panek 4pp 22434 184 24X Fiche 50-322,84/02/27,8403010234
- B403010237 Motion for leave to file modified Contentions 16 & 18 reutil public educ brochure Motion should be granted Denial would constitute improper refusal to deal w/important issues raised by brochure

 LETSCHE, K J Suffolk County, NY LETSCHE, K J Kirkpatrick,
 Lockhart, Hill, Christopher & Phillips B4/02/27 Atomic Safety
 and Licensing Board Panel 19pp 22434;191 24x

 Fiche 50-322,84/02/27,8403010237

1

- B403010242 Interrogetories to Suffolk County & State of NY re identification of expert witnesses at trial concerning diesel generator contentions Certificate of Svc encl Related correspondence ELLIS,TS Long Island Lighting Co ELLIS,TS Hunton & Williams B4/02/27 Suffolk County, NY Spp 22434 214 24X Fiche 50-322.84/02/27,8403010242
- 84D3D10249 Notice of TA Moore, A Bakshi, GD Eley, H Avery, R Anderson, P Meulangracht, B Christensen, M Ooldsmith & R Hubbard depositions on 840307, OB, O9, 12, 13, 14, 15, 16 & 19, respectively Certificate of Evc encl Related correspondence ELLIS, T B. Long Island Lighting Co ELLIS, T S. Hunton & Williams 84/02/27 8pp 22432 275 24X Fiche 50-322, 84/02/27, 8403010249
- B403020123 Statement of Governor Cuomo in support of Buffolk County B40213 motion for leave to file new contentions re util offsite emergency preparedness training program Certificate of Svc encl CUOMD, M. ZAHNLEUTER, R. J. New York, State of B4/02/27 4pp 22442 10B 24X Fiche 50-322.84/02/27.8403020123
- B403020233 Affidavit of D Axelrod opposing util motion to compel expedited production of documents by Btate fo NY Documents subj to executive privilege W/Certificate of Svc Related correspondence AXELROD, D. New York, Btate of 84/02/27 App 22440 269 24X Fichs 50-322.84/02/27,8403020233
- 84030i0174 Order granting Buffolk County 840227 motion for 6-day extension of time within which to respond to LILCO summary disposition motions
 LAURENON, J A Atomic Bafety and Licensing Board Panel 84/02/28
 4pp 22435-227 24X Fiche 50-322,84/02/28,8403010174
- B403010215 Memorandum & order denying Suffolk County B4020B motion for leave to file reply to LILCO answer opposing Suffolk County motion for leave to file rebuttal testimony on Contention 23 LAURENSON, J A Atomic Safety and Licansing Board Panel B4/02/28 Buffolk County, NY 10pp 22436 009 24X Fiche, 50-322, 84/02/28, 8403010215
- 8403010225 Drder granting in part LILCO 840206 motion to compel expedited production of documents by State of NY & denying LILCO 840206 motion to reply to State of NY LAURENBON, J A Atomic Safety and Licensing Board Panel 84/02/28 Long Island Lighting Co 10pp 22435 243 24X Fiche 50-322,84/02/28,8403010225
- 8403010232 Order ruling on Suffolk County 840209 objections to 840203 memorandum & order ruling on intervenors proposed modified emergency planning contentions LAVRENSON, J A Atomic Befety and Licensing Board Panel 84/02/28 8pp 22434 176 24% Fiche 50-322,84/02/28,8403010232
- B403010269 Order granting util 840210 motion to compel expedited production of State of NY emergency preparedness plan State of NY directed to act expeditiously in complying w/order LAURENSON, J A Atomic Bafety and Licensing Board Panel 84/02/26 5pp 22432 253 24X Fiche 50-322,84/02/28,8403010269
- B403020143 Notice of appearance in proceeding Certificate of Svc encl ROLFE,R,M Long Island Lighting Co ROLFE,R M Hunton & Williams 84/02/28 3pp 22441 360 24X Flche 50-322,84/02/28,8403020143
- 8403020168 Motion for leave to make & suppl replies to State of NY 840223 & 27 discovery papers Certificate of Svc encl Related correspondence IRNIN, D P Long Island Lighting Co 84/02/28 Atomic Safety and Licensing Board Panel 18pp 22443 207 24X Fiche 50-322.84/02/28.
- 8403140100 Forwards GH Cunningham 840228 memos re Transamerica Delavai emergency dissel generator contentions advanced by Suffolk Gounty, Memos submitted per 840222 conference of counsel BORDENICK, B M, Hearing Branch 3 84/02/28 BRENNER, L, FERQUEON, O A, MORRIS, P A Atomic Safety and Licensing Board Panel 5pp 22621 353 24X Fiche 50-322,84/02/28,8403140100
- B403i40136 Response supporting util motions for summary disposition of Contentions 24, B.33.45, 46 & 47 No genuine facts to be litigated & applicant entitled to summary disposition of contentions. W/Certificate of Svc BORDENICK, D. M Hearing Branch 3 84/02/28 Atomic Safety and Licensing Board Panel 17pp 22620 169 24X Fiche 50-322,84/02/28, 8403140136

- 8403i40i41 Requests assistance in responding to ASLB inquiries re Transamerica Delaval amergency diesel generator contentions advanced by Suffolk County Summary of ASLB inquiry outlined CUNNINGHAM, O H Office of the Executive Legal Director 84/02/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22620 339 24x Fiche 50-322,84/02/28,8403140141
- B403i4016i Response supporting Suffolk County 8402i3 motion for leave to file new contentions on offsite emergency preparedness training program Certificate of Syc encl BORDENICK, B.M. Hearing Branch 3 84/02/28 Atomic Safety and Licensing Board Panel 11pp 22620 264 24% Fiche 50-322,84/02/28,8403140161
- 8403140182 Discusses inquiry at 840224 conference of counsel re Buffolk County Transamerica Delaval emergency diesal generator contentions Assistance requested for preparation of appropriate rept, CUNNINGHAM 0 H Office of the Executive Legal Director 84/02/28 HAYES, B B Office of Investigation 1p 22620 i88 24X fiche 50-322.84/02/28.8403140182
- 8403140155 Responds to proposal circulated at 840222 conference of counsel re possibility & feasibility of transmitting info electronically to & from displaymriters Proposal generally approved BORDENICK, B. H. Hearing Branch 3 84/02/29 BRENNER, L., FERCUSON, G. A., MORRIS, P. A. Atomic Bafety and Licensing Board Panel 3pp 22621 358 24% Fiche 50-322, 84/02/29, 8403140155
- 8403060105 Forwards requests for production of documents, superseding 840217 requests Related correspondence ROLFE, R M Runton & Williams ROLFE, R M Long Island Lighting Co 84/03/01 DYNNER, A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips PALAMIND, F o New York, State of 1p 22506 104 24X Fiche 50-322,84/03/01,8403060105
- --8403060107 Request for production of listed documents re Contentions I,
 11 & lil Certificate of Svc encl Related correspondence
 ROLFE.R M Long Island Lighting Co ROLFE.R M Hunton &
 Williams 84/03/01 DYNNER.A R Suffolk County, NY DYNNER.A R
 Kirkpatrick, Lockhart, Hill, Christopher & Phillips 44pp
 22506 105 24X Fiche 50-322.84/03/01,8403060105
- 8403060265 Answer to Suffolk County 840227 motion to file modified public educ brochure contentions & objections to contentions Contentions clearly inadmissible & motion should be denied Certificate of Svc enci CHRISTMAN.J N Long Island Lighting Co 84/03/01 Atomic Bafety and Licensing Board Panel 17pp 22517 112 24X Fiche 50-322.84/03/01.8403060265
- 8403040114 Order confirming schedule Changes for Ordup II issues LAURENSION.J A Atomic Safety and Licensing Board Panel 84/03/02 Long Island Lighting Co 5pp 22516 327 24X Fichs 50-322,84/03/02,8403040114
- 8403060208 Objects to ASLB 840301 conference call involving counsel for util & State of NY re-ruling on discovery dispute concerning util request for production of certain state documents
 Related correspondence
 LANPHER, L.C. Kirkpatrick, Lockhart, Hill, Christopher & Phillips
 LANPHER, L.C. Suffolk County, NY 84/03/02 LAURENSON, J.A.,
 KLINE, J.R., BHON, F.J. Atomic Safety and Licensing Board Panel 2pp
 22016 086 24X Fiche 50-322,84/03/02,8403060208
- 8403060268 Brief in response to util B31223 brief on appeal from ASLB imposition of OL condition re term important to safety as pertaining to class of structures, sys & components Certificate of Swc encil LANPHER, L C Suffolk County, NY LANPHER, L C Kirkpetrick, Lockhart, Hill, Christopher & Phillips 84/03/02 18pp. 22515 207 24% Fiche 50-322.84/03/02,8403060268
- B403130129 Reply brief re Contentions 7B on classification & sys interactions & 12-i5 on GA/GC Certificate of Svc enci REVELEY, W T Long Island Lighting Co REVELEY, W T Hunton & Williams 84/03/02 Atomic Safety and Licensing Appeal Panel 137pp 22601 337 24X Fiche 50-322.84/03/02.8403130129
- B403140081 Forwards Board Notification BN-84-33 re staff sys Interactions program W/o encl RAMSON,R J Hearing Branch 4, 84/03/02 ROSENTHAL,A S . EDLES,G J , WILBER, H A Atomic Safety and Licensing Appeal Panei 2pp 22633:249 24X Fiche 50-322,84/03/02,84/03140081
- 840314015B Advises that NRC staff will not respond to util motion for leave to make & suppi replies & reply & suppiemental reply to State of NY 840223 & 27 discovery papers NRC not involved in dispute between parties
 BORDENICK.B M Hearing Branch 3 84/03/04 LAURENSON.J A , SHON.F J , KLINE.J R Atomic Safety and Licensing Board Panel 200 22620 235 24X Fiche 50-322,84/03/04.8403140158

- 8403130027 Memorandum opposing util summary disposition motions on Contentions 24 B.33,35.45.45 t 49 Statements of matifacts as to which there exist gonuine issues to be heard encl M/Certificate of Svc Related correspondence LETSCHE.K J Suffolk County, NY LETSCHE,K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/03/05 Atomic Safety and Licensing Board Paphel 83pp 22615 023 24x Fiche 80-322,84/03/05,8403130029
- 8403140039 Forwards GW McCorkle 840228 memo re Rev 2 to guard training & qualification plan, for info
 BURDENICK,B M Hearing Branch 3 84/03/05 IRHIN,D P Hunton & Williams Miller,M Kirkpatrick, Lockhart, Hill, Christopher & Phillips 3pp 22633 046 24% Fiche 50-322,84/03/05,8403140039
- 8403140125 Forwards NRC Region I morning repts re facility emergency diesel generators for 840215-0301 GDODARD:R J Hearing Branch 3 84/03/05 BRENNER,L, FERGUSON.O A, MORRIS,P A Atomic Safety and Licensing Board Panel 13pp 22620 341 24x Fiche 50-322.84/03/05,8403140126
- B403090093 Order ruling on util motions to compel production of ducuments & objections of Governor Cuomo LAURENSON, J. A. Atomic Bafety and Licensing Board Panel B4/03/06 14pp 22575 303 24% Fiche 50-322, B4/03/06, B4030900B3
- 8403130146 Reply to util response to Suffolk County motion to file new contentions re offsite emergency preparedness training program & util objections to proposed training contentions Certificate of Svc encl
 LANPHER.L C Suffolk County, NY LANPHER.L C Kirkpatrick,
 Lockhart Hill, Christopher & Phillips 84/03/07 Atomic Safety and Licensing Board Panel 47pp 22608 173 24%
 Fiche 50-322.84/03/07.8403130146
- B403140342 Advises that NRC has no objection to util B40227 motion for leave to file surrebuttal testimony on emergency planning Contention 23 REFKA,D A Hearing Branch 3 B4/03/07 LAURENSON. J A , SHON, F J , KLINE, J R Atomic Safety and Licensing Board Panel 2pp 22633 049 24% Fiche 50-322, B4/03/07. 8403140042
- 8403140165 Response to Suffolk County 840227 motion for leave to fila modified Contentions 16 & 18 re public info brochure Contentions 16 L.16 M & 16 N should be denied Certificate of Svc encl
 REPKA, D A Hearing Blanch 3 84/03/07 Atomic Safety and Licensing Board Panel 7pp 22620 237 24X Fiche 50-322,84/03/07,8403140165
- 8403070059 Advises oral arguments on panding appeals will be heard on 840327 in Bethesda, MD Board will issue order confirming hearing & detailing hearing time allotments SHDEMAKER: C.J. Atomic Safety and Licensing Appeal Panel 84/03/08 BORDENICK. B.M. Office of the Executive Logal Director BROWN, H. Kirkpatrick. Lockhart, Hill. Christopher & Phillips REVELEY, W.T. Hunton & Williams ip 22575 349 24X Fiche 50-322, 84/03/08. 8403070059
- 8403130083 Motion of Governor Cuomo to file rebuttal testimony on Contention 65 re evacuation time estimates Related correspondence JAHNLEUTER, R. J. New York. State of 84/03/08 Atomic Safety and Licensing Board Panel 7pp 22614 274 24X Fiche 50-322.84/03/08, 8403130885
- --B403130091 Rebuttal testimony of DT Hartgen & FJ Bench re emergency planning Contention AS on evacuation time estimates Certificate of Svc encl HARTGEN.D T , BEACH, F J New York, State of 84/03/08 20pp 22614 281 24X Fiche 50-322,84/03/08 B403130085
- 8403130003 Motion to strike testimony of JR Sears on behalf of NRC staff re emergency preparedness Contentions 26 A, 26 C & 26 D Testimony contains personal views Certificate of Svc encl Related correspondence
 LETSCHE, K J Suffolk County, NY LETSCHE, K J Kirkpatrick, Lockhart, Nill, Christopher & Phillips 84/03/09 Atomic Safety and Licensing Board Panel App 22615 198 24X
 Fische 30-322,84/03/09,8403130003
- 8403130012 Forwards listed motions to strike testimony Related corpespondence FALZONE, R R Long [sland Lighting FALZONE, R R Long [sland Lighting Co 84703709 LAURENSEN. J A. KLINE, J R. BHON, F J Atomic Safety and Licensing Board Fanel 2pp 22600 048 24X Fiche 50-322,84703709,8403130012
- --8403130018 Motion to strike portions of PB Herr direct testimony on Contention 22 D re emergency planning rone Testimony unduly repetitious, cumulative & irrelevant Related correspondence MDNAGHAN. J A Long Island Lighting Co MDNAGHAN. J A Hunton & Williams 84/03/09 Atomic Safety and Licensing Board Panel 7pp 22500 050 24% Fiche 50-322,84/03/09,8403130012

- --8403130030 Motion to strike portions of D Harris & M Mayer testimony on Contentions 24 0 (agreements of ambulances) & 75 (capacity of relocation ctrs) Testimony does not address issues Related correspondence MCCLEBKEY, K E Long Island Lighting Co MCCLESKEY, K E Hunton & Williams 84/03/09 Atomic Bafety and Licensing Board Panel 7pp 22600 057 24x Fiche 50-322,84/03/09,8403130012
- --8403130041 Motion to strike portions of deputy chief inspector RC Roberts, et al direct testimony on Contentions 24 T & 59 re notification to public by US Coast Guard Objectionable portions are Phase I issues Related correspondence MONAGHAN.J A Long Island Lighting Co MONAGHAN.J A Hunton & Hilliams 84/03/07 Atomic Safety and Licensing Board Panel. 5pp 22600 064 24X Fiche 50-322,84/03/09,8403130012
- --8403130053 Motion to strike direct testimony on Suffolk County behalf re amergency planning Contention 26 Testimony predicated on sproneous assumptions, beyond scope of contention & w/o sufficient foundation Related correspondence MONAGHAN, J A Long Island Lighting Co MONAGHAN, J A Hunton & Williams 84073/09 Atomic Bafety and Licensing Board Panel 11pp 22600 069 24X Fiche 50-322,84/03/09.8403130012
- --8403130063 Hotion to strike portions of direct testimony on Suffolk County behalf re emergency planning Contentions 28-32 & 34
 Testimony generally w/o factual basis & irrelevant Related correspondence
 MONAGHAN, J A Long Island Lighting Co MONAGHAN, J A Hunton & Williams 84/03/09 Atomic Safety and Licensing Board Panel 17pp 22600 080 24X Fiche 50-322,84/03/09,8403130012
- --B403130073 Motion to strike portions of direct tastimony on Buffolk County behalf re emergency planning Contentions 55-58 Majority of testimony outside scope of contentions Related correspondence MONAGHAN, J. A. Hunton & Williams B4/03/09 Atomic Bafety and Licensing Board Panel Bpp 82600 097 24X Fiche 50-322.84/03/09,8403130012
- --8403130082 Motion to strike portions of assistant chief inspector JL Monteith, et al testimony on emergency planning Contention & Testimony unduly repetitious, outside scope of contention & trrelevant Related correspondence ZEUOIN.L B Long Island Lighting Co ZEUOIN.L B Hunton & Williams 84/03/09 Atomic Bafety and Licensing Board Panel 4pp 22600,105 24X Fiche 50-322.84/03/09.8403130012
- --B403130090 Motion to strike portions of TB Gibbons direct testimony on amergency planning Contentions 66 D & 97 B re agreements for snow removal & evacuation during deep snow Testimony outside scope of contention Related correspondence CHRISTMAN.J N Long Island Lighting Co CHRISTMAN.J N Hunton & Williams B4703/09 Atomic Safety and Licensing Board Panel 6pp 22600 109 24X Fiche 50-322.84/03/09.8403130012
- --B403130099 Motion to strike portions of WJ Acquario, et al testimony on emergency planning Contention 67 re evacuation of persons w/o access to automobiles Testimony outside scope of contention & irrelevant Related Correspondence ZEUGIN, L B Long Island Lighting Co ZEUGIN, L B Hunton & Williams B4/03/09 Atomic Bafety and Licensing Board Panel 3pp 22600 115 24X Fichs 50-322,84/03/09,8403130012
- --8403130107 Motion to strike portions of MJ Aquario.RD Albertin & RC Knighton direct testimony on emergency planning Contention 73 re evacuation of handicapped persons not in special facilities Related correspondence FALZONE, R Long Island Lighting Co FALZONE, R Hunton & Williams 8403/07 Atomic Bafety and Licensing Board Panel. 6pp 22600 118 24X Fiche 50-322.84/03/07.8403130012,
- --8403130117 Motion to strike portions of 8 Sargent testimony on Suffolk County behalf on emergency planning Contention 73 A re evacuation of homebound Testimony argumentative repetitious & irrelevant W/Certificate of Svc Related correspondence CHRISTMAN.J N Long Island Lighting Co. CHRISTMAN.J.N Hunton & Williams 84/03/07 Atomic Safety and Licensing Board Panel 8pp 22400 124 24% Fiche 50-322,84/03/07,8403130012.
- 8403130022 Provides schedule of clustering & order for litigation of remaining Group I & all Group II-A issues in hearings scheduled to resume on 840320 for ASLB approval Certificate of Svc encl.Related correspondence IRWIN.D P Hunton & Williams IRWIN.D P Long Island Lighting Co 84/03/09, LAURENSON.J A, KLINE.J R. SHON.F J Atomic Barety and Licensing Board Fanel Spp 22615 123 24X Fiche 50-322,84/03/09, BOOKED STATES AND ACCOUNTS A

- B403130043 Motion of Oovernor Coumo to strike portions of MC Cordard & JA Waismantle testimony re Phase II emergency planning Contantion 92 & statement supporting Suffolk County motion Certificate of Svc encl Related correspondence ZAHNLEUTER, R J New York, State of B4/03/09 Atomic Safety and Licensing Board Panei 9pp 22598 346 24X Fiche 50-322,84/03/09,8403130043
- E403130097 Order granting util E40227 motion for leave to file surrebuttal testimony on Contention 23 LAURENSON.J A Atomic Safety and Licensing Board Panel 84/03/09 2pp 22614 268 24% Fiche 50-322.84/03/09.8403130097
- B403130107 Memorandum & order ruling on Suffolk County B40227 motion to file modified Contentions 16 & 18 re util public education brachure Contentions 16 J.16 K.16 L & 16 M allowed Contentions 16 N & 18 denied LAURENSIN, J A Atomic Safety and Licensing Board Panel 84/03/09 7pp. 22615 281 24X Fiche 50-322, B4/03/07, B403130107
- B403i30174 Motion to strike portions of util Oroup II-A testimony Testimony neither probative nor matl & unrollable Cartificate of Svc encl Related correspondence MILLER, M S Suffoik County, NY MILLER, M S Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/03/09 Atomic Safety and Licensing Board Panel 3Bpp 22599 136 24X Fiche 30-322,84/03/09,8403130174
- 8403170124 Brief in opposition to Suffolk County brief in support of appeal of ASLS partial initial decision & LILCO brief on appeal Certificate of Svc enci BORDENICK, B M , REPKA-D A , Hearing Branch 3 RAWSON, R J Hearing Branch 4 84/03/09 Atomic Safety and Licensing Appeal Panei 145pp 22669,001 24X Fiche 50-322.84/03/09,8403190124
- 8403190127 Interim deficiency rept re failure of turbocharger on emergency standby diesel generator Temporary bypass vaive around turbocharger prelube drip line orifice installed M/Certificate of Svc Related correspondence MCCAFFREY, B R Long Island Lighting Co 84/03/09 MURLEY, T E Region 1, Office of Director 4pp 22668 252 24X Fiche 50-322.84/03/09,8403190127
- B403i40004 Order establishing schedule for oral argument on ASLB 830921 partial initial decision Arguments will be heard on 840327 in Bethesda: MD BHOEMAKER.C J Atomic Bafety and Licensing Appeal Panel 84/03/12 Office of the Executive Legal Director 3pp 22633 264 24X Fiches 30-322.84/03/12.8403140004
- 8403140005 Order scheduling order of contentions at 840320 hearing re Group I & Group II-A issues Cross-examination plans on first two clusters of Group II-A due 840316 LANRENBON, J A Atomic Safety and Licensing Board Panei 84/03/12 Office of the Executive Legal Director 3pp 22633 229 24X Fiche 50-322,84/03/12,8403140005
- 8403150004 Opposition to Governor Guomo 840308 motion for loave to file rebuttal testimony on Contention 65 re evacuation time estimates Notion fails to establish good cause for filing of rebuttal Related correspondence
 ZEUGIN,L 8. Long Island Lighting Co ZEUGIN,L B Hunton & Milliams 84/03/12 Atomic 8afety and Licensing Board Panei 15pp 22641 324 24X Fiche 50-322,84/03/12,8403150004
- B403150026 Response to LILCO & staff objections to Suffoik County motion for leave to file modified public education brochure contentions Motion to file modifying Contentions 16 & 18 should be granted M/Certificate of Svc MCMURRAY, C M. Buffolk County, NY MCMURRAY, C M. Kirkpatrick, Lockhart, Hill. Christopher & Phillips 84/03/12 Atomic Safety and Licensing Board Panel 27pp 22640 332 24x Fichs.50-322.84/03/12.8403150026
- B403190092 Recommends admittance of Hartgen & Beach rebuttal testimony accompanying State of NY 840309 motion re Contention 45 on evacuation time estimates if testimony found to be unique & important to complete record REPKA.D.A Hearing Branch 3 R4/03/15 LAURENSON.J.A . SHON.F.J. KLINE.J.R Atomic Safety and Licensing Board Panel 2pp 22669 300 24x Fiche 30-322:84/03/15,8403190092
- B403190131 Discusses findings & determinations on LILCO transition plan. Key to Regional Assistance Committee (RAC) 840210 review & consolidated RAC review and BPECK, S. W. Federal Emergency Management Agency 84/03/15 DIRCKB, W.J. Office of the Executive Director for Operations 70pp 22668; 258 24% Fiche 50-322, 84/03/15, 8403190131

- 8403190169 Advises that EJ Reis & BM Bordenick will present staff oral arguments on appeals taken from ABLB 830921 Partial Initial Decision LDP-83-57 in proceeding BORDENICK, B M Hearing Branch 3 84/03/15 SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 1p 22668 251 24X Fiche 50-322,84/03/15,8403190169
- B403200004 Informs of joint agreement w/Suffoik County to defer filing date for testimony on Contention i5 which will result in deferral of testimony on Contention ii Deferred schedule proposed Related correspondence

 LANPHER, L. C. Kirkpatrick, Lockhart, Hill, Christopher & Phillips (LANPHER, L. C. Long Island Lighting Co. 84/03/15 LAURENSON, J. A. KLINE, J. R. 980N, F. J. Atomic Safety and Licensing Board Panel 2pp 22685 i36. 24% Fiche 50-322,84/03/15,84032000004
- 8403200069 Opposition to Suffolk County 840314 request for delay in ASLB ruling on Contention 45. "Rebuttal " Requests either feckless or disingenous Certificate of Svc enc! IRMIN D P Long Island Lighting Co IRMIN D P Hunton & Williams 84/03/15 Atomic Safety and Licensing Board Panei 4pp 22683 102 24% Fiche 50-322.84/03/15,8403200069
- B40320012B Forwards Complaint B4-4615 filed by Suffolk County for declaratory Judgment concerning implementation of offsite emergency plan Related correspondence LANPHER.L C Kirkpatrick, Lockhapt, Hill, Christopher & Phillips LANPHER.L C Buffolk County, NY B4/03/15 LAURENSON, JA, KLINE, JR, SHON, FJ Atomic Safety and Licensing Board Fanel 14pp 22679 078 24x Fiche 50-322.84/03/15.840320012B
- 8403200031 Response opposing Suffork County & State of NY 840309 motions to strike portions of util Group II-A testimony Related correspondence CHRISTMAN.J N Long Island Lighting Co CHRISTMAN.J N Hunton Williams 84/03/16 Atomic Safety and Licensing Board Panel 71pp 22684 001 24x Fiche 30-322.84/03/16.8403200031
- --8403200037 Answer opposing Suffeik County motion to strike testimony of JR Bears Motion has no basis in NRC regulations or case law Certificate of Svc enci CHRIBTMAN.J N Long Island Lighting Co CHRISTMAN.J N Hunton & Williams 84/03/16 Atomic Safety and Licensing Board Panel Spp 22684 073 24% Fiche 50-322.84/03/16.8403200031
- 8403200075 Order excluding Contentions II &15 from Group li-B & amending 840302 order confirming schedule changes to reflect listed dates LAURENSON, J A Atomic Safety and Licensing Board Panel 84/03/16 Suffeix County, NY 2pp 22685 311 24% Fiche 50-322,84/03/16,8403200095
- 8403200131 Response opposing LILCO 840309 motion to strike portions of direct testimony of PG Herr on Contention 22 D re inadequacy of LILCO emergency planning zone Related correspondence MCMURRAY. C M Suffolk County, NY MCMURRAY. C M Kirkpatrick. Lockbart. Hill, Christopher & Phillips 84/03/16 Atomic Safety and Licensing Board Panel 5pp 22698 127 24% Fiche 50-322,84/03/16.8403200131
- --8403200134 Response opposing LILCO 840309 motion to strike direct testimony of RC Roberts, et al.on Contentions 24 T & 59 re ability of Coast Guard to notify public Related correspondence MCMURRAY.C M Suffoik County. NY MCMURRAY.C M Kirkpatrick, Lackhart. Hill, Christopher & Phillips 84/03/16 Atomic Safety and Licensing Board Panol 7pp 22698 132 24x Fiche 50~322,84/03/16,8403200131
- --8403200136 Memorandum in opposition to LILCO 840309 motion to strike portions of testimony of D Harris & M Mayer on Contentions 24 0 & 75 Related correspondence LETSCHE, K J Suffoik County, NY LETSCHE, K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/03/16 Atomic Safety and Licensing Board Panel 11pp 226/98 139 24% Fiche 50-322,84/03/16,8403200131
- ---8403200140 Response opposing LILCO 840307 motion to strike portions of direct testimony re emergency planning Contention 26 Related correspondence HILLER,M S Suffolk County, NY MILLER,M S Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/03/16 Atomic Safety and Licensing Board Panel 34pp 22678 150 24X Fiche 50-322,84/03/16,8403200131
- --8403200143 Response opposing LILCO 840309 motion to strike portions of direct testimony re emergency planning Contentions 28,29,30, 31,32 & 34 Related correspondence MILLER,M 8 Suffolk County, NY MILLER,M 9 Kirkpatrick, Lockhert, Hill. Christopher & Phillips 84/03/16 Atomic Safety and Licensing Board Panel 36pp 22698 184 24X Fiche 50-322,84/03/16,8403200131

- --8403200146 Response opposing LILCO 840309 motion to strike portions of direct testimony re emergency planning Contentions 55-58 Related correspondence MILLER, MS Suffolk County, NY MILLER, M. S. Kirkpatrick, Lockhart, Hill. Christopher & Phillips 84/03/16 Atomic Safety and Licensing Board Panel 26pp 22698 220 24X Fiche 50-322,84/03/16,8403200131
- --B403200131 Response opposing LILCO 840309 motion to strike portions of Suffolk County Police Dept witnesses testimony on emergency planning Contention 64 Related correspondence MCMURRAY.C M Suffolk County, NY MCMURRAY.C.M Kirkpatrick, Lockhart, Hill: Christopher & Phillips 84/03/16 Atomic Safety and Licensing Board Panel 6pp 22698 246 24X Fiche 50-322,84/03/16,8403200131
- --B403200155 Response opposing LILCO B40309 motion to strike portions of State of NY testimony on Contentions &6 D.67.73 & 97 B Related correspondence HCMURRAY.C M Suffolk County, NY MCMURRAY.C M Kirkpatrick, Lockhart, Hiil. Christopher & Phillips B4/03/16 Atomic Safety and Licensing Board Panel 2pp 22898 252 24x Fiche 50-322,84/03/16,8403200131
- --8403200159 Memorandum in apposition to LILCO 840309 motion to strike portions of testimony of S Saegert on Contention 73 A Certificate of Svc encl Related correspondence LETSCHE.K Suffolk County, NY LETSCHE.K Kirkpatrick, Lockhart. HIII. Christopher & Phillips 84/03/16 9pp 22498 254 24X Fiche 50-322,84/03/16,8403200131
- B403210098 Forwards NRC Region I morning repts for 840302-16 re emergency diesel generators Related correspondence G00DARD:R J Hearing Branch 3 84/03/16 BRENNER.L MORRIB.P A , FERGUSDN.Q A Atomic Safety and Licensing Board Panel 36pp 22706 054 24X Fiche 50-322.84/03/16.8403210098
- 8403210100 Responses to applicant, Suffoix County & State of NY 840309 motions to strike portions of Group II-A testimony Certificate of Svc enci Related correspondence BORDENICK, B M , REPKA, D A Hearing Branch 3 84/03/16 Atomic SaFety and Licensing Board Panel 17pp 22706 100 24x Fiche 50-322,84/03/16,8403210100
- B403210104 Response denying Suffolk County 840309 motion to strike testimony of JR Sears re emergency preparadness Contentions 26 A, 26 C & 26 D Certificate of Svc encl Related correspondence REPKA.D A Hearing Branch 3 84/03/16 Atomic Gafety and Licensing Board Panel 7pp 22706 128 24X Fiche 30-322,84/03/16,8403210104
- 8403210150 Memorandum & order denying State of NY B40309 motion for leave to file rebuttal testimony on Contention 65 re avacuation time estimates LAURENBON, J & Atomic Safety and Licensing Board Panel 84/03/16 7pp 22707 091 24% Fische 50-322,84/03/16,8403210150
- 8403210179 Response of Governor Cuomo in opposition to util 840309 motion to strike portions of TD Gibbons direct testimony on Contentions CG D & 97 D Certificate of Svc encl Related correspondence
 ZAHNLEUTER.R J New York, Stats of DGB 00B 84/03/16 Atomic Safety and Licensing Board Panel 7pp 22710 091 24X
 Fiche 50-322,84/03/16,8403210179
- 8403210188 Response in opposition to LILCO 840309 motion to strike portions of direct testimony of MJ Aquanio.80 Albertin & RO Knighton re Contention 73 Certificate of Svc encl Related correspondence
 ZAMNLEUTER.R. J. New York, State of DSB 007 84/03/14, Atomic Safety and Licensing Opera Panel 7pp 22710 084 24X
 Fiche 50-322,84/03/14,8403210188
- 8403210201 Response in opposition to util 840307 motion to strike portions of MJ Acquario, et al testimony on amergency glanning Contention 67 M/Certificate of 8vc Related correspondence ZAHNLEUTER, R J New York, State of DSD 007 84/03/16 Atomic Safety and Licensing Board Panel 7pg 22710 072 24X Fiche 50-322,84/03/16.8403210201
- 8403210083 Order ruling on Suffolk County 840213 motion for leave to file new contentions or LiLCO offsite emergency preparedness training program LAURENSON.J A Atomic Safety and Licensing Board Panel 84/03/19 Suffolk County, NY 20pp 22705 166 24X Fichs 50-322,84/03/19,8403210083

- B403210186 Informs that LC Lonpher will present oral argument at B40327 appeal hearing KJ Letsche may also appear on behalf of Suffolk County Related correspondence LANPHER.L C Kirkpatrick. Lockhart. Hill. Christopher & Phillips LANPHER.L C Suffolk County. NY D88 022 B4/03/19 SHOEMAKER.C J Atomic Safety and Licensing Appeal Panol ip 22718 226 24X Fiche 50-322.84/03/19.8403210186
- 84032i0177 Forwards supplemental motion for low power OL & supporting unercruted affidavits EARLEY.A F Hunton & Hilliams EARLEY.A F Long Island Lighting Co 84/03/20 BRENNER.L , MORRIS.P A , FERGUSON,O A Atomic Safety and Licensing Board Panel 1p 22709 240 24X Fiche 50-322,84/03/20,8403210177
- --B403210181 Supplemental motion for low power OL Unexecuted affidavits of JA Notaro, WG Schiffmacher, GG Sherwood, AS Rao & EC Eckert encl Certificate of Svc also encl REVELEY, W T Long island Lighting Co REVELEY, W T Hunton & Williams B4/03/20 Atomic Bafety and Licensing Board Panel 108pp 22709 241 24X Fiche 50-322, 84/03/20, 8403210177
- 8403220250 Response opposing LILCO 840301 request for production of documentation Certificate of Svc encl Related correspondence DYNNER, A R Suffolk County, NY DYNNER, A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 050 84/03/20 Atomic Safety and Licensing Board Panel 13pp 22719 097 24X Fiche 50-322,84/03/20,8403220250
- B403230010 Forwards concerns raised in HH Brown B40301 ltr re design review/quality revalidation now under de facto control & direction of LILCO Design review should be stopped & genuinely independent review instituted PALOMINO,F O New York, State of 84/03/21 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22730 131 24X Fiche 50-322,84/03/21,8403230010
- B403230013 Forwards Certificate of Svc for listed testimony on emergency planning contentions Related correspondence NCCLEBKEV.K E Hunton & Williams MCCLEBKEV.K E Long Island Lighting Co DSB 061 04/03/21 LAURENSON.J A . KLINE.J R . SHON.F J Atomic Safety and Licensing Board Panel 5pp 22727 352 24X Fiche \$0-322.84/03/21.8403230013
- B403270074 Response to request for production of documents Certificate of Svc encl Related correspondence RDLFE: R M Long Island Lighting Co DSD 106 B4/03/21 Suffolk County, NY 54pp 22766 170 24X Fiche 50-322,84/03/21,8403270074
- 8403270197 Forwards supplemental motion for low power QL MCCAFFREY.D R Long Island Lighting Co 84/03/21 DENTON, H R Office of Nuclear Reactor Regulation. Director 1p 22770, 293 24X Fichs 50-322.84/03/21, 0400270197
- 8403280356 Notifies that proposed rulemaking re "Applicability of App A to App B" will be deleted from regulatory agenda Related correspondence REIS.E J Hearing Branch 3 DSB 154 B4/03/22 ROBENTHAL, A B, EDLES. Q J. WILLIER, H A Atomic Bafety and Licensing Appeal Panel 3pp 22787 210 24% Fiche 50-322,84/03/22,8403280356
- 8403280340 Advises that staff may rely on ALAB-763 as corroborating certain NRC positions set forth in 840309 brief Relevant portions of brief to be further discussed at oral argument are Part II A & B & Part IV Related correspondence BORDENICK: B M Hearing Branch 3 088 153 84/03/23 SHOEMAKER: C J Atomic Bafety and Licansing Appeal Panel 1p 22787 099 24X Fiche 50-322,84/03/23,8403280340
- B403280362 Advises that possibility of ASLB proposal to electronically transmit info & selected documents within context of proceeding to diosel generators still under consideration Related correspondence
 BIORDENICK, B M Hearing Branch 3 OSB 152 84/03/23 BRENNER, L, FERGUSON, G A, MORRIS, P A Atomic Safety and Licensing Board Panel ip 22787 234 24% Fiche 50-322, 84/03/23, 8403280362.
- 8403270272 Motion to strike direct testimony of CV Failla on behalf of NY State re Contention 24 F 2 Agreement re notice of & discovery on intended testimony not complied with Gertificate of Stvc encl Related correspondence IRWIN.DP Long Island Lighting Co IRWIN.DP Hunton & Williams DBB 127 84/03/24 Atomic Safety and Licensing Board Panel 13pp 22789 036 24X Fiche 50-022.84/03/24.8403270292
- 8403270275 Forwards BR McCaffrey 840313 itr to HR Denton & TS Ellis 840312 ltr to Dircks re meaning of term important to safety in NRC regulations Related correspondence REIS,E J Hearing Branch 3 DSB 128 84/03/26 ROSENTHAL,A B . EDLES, 6 J . WILBER:H A Atomic Safety and Licensing Appeal Panel 7pp 22787 047 24X Fiche, 50-322,84/03/26,8403270275

- B403280346 Motion to establish regular daily hearing schedule Hearing day from 7am to 3pm reasonable & sufficiently long Certificate of Svc encl LETSCHE, K J Suffolk County, NY LETSCHE, K J Kirkpatrick, Lockhart, Hili, Christopher & Phillips BSB 163 84/03/26 Atomic Bafety and Licensing Board Panel 5pp 22787 122 24X Fiche 50-322,84/03/26,8403280346
- 8403280357 Forwards Suffork County cross-examination plans for Cluster 3 & Cluster 4 M/o encl Related correspondence LETSCHE, K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips LETSCHE, K J Buffork County, NY DSB 156 84/03/26 LAURENSON, J A, KLINE, J R, SHON, F J Atomic Safety and Licensing Board Fanel 1p 22787 213 24X Fiche 50-322,84/03/26,8403280357
- 8403280358 Preliminary views on scheduling re util 840320 supplemental motion for low power OL Motion entirely new & seeks to circumvent litigation on adequacy of emergency diesel generators Certificate of Svc encl
 SCHEIDT,D J Suffolk County, NY SCHEIDT,D J Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 164 84/03/26 15pp 22787 214 24X Fiche 50-322.84/03/26.8403280338
- 8403290179 Forwards LILCD plan for cross-examination of KJ Regensburg. RA Snow & VR Stile on Contentions 34 & 28-32 re communications among emergency response personnel M/o plan M/Certificate of Evc Related correspondence

 918K,K D Hunton & Williams SISK,K D Long Island Lighting Co DBB 179 84/03/26 LAURENBON,J A. KLINE,JR, SHON,F J Atomic Bafety and Licensing Board Panel 4pp 22803 322 24X Fiche 50-322,84/03/26,8403290179
- 8403280350 Order approving settiement of portion of Suffolk County Contention if re passive mechanical valve failure Berved on 840327 BRENNER, L Atomic Safety and Licensing Board Panel DSU 149 84/03/27 Suffolk County, NY 2pp 22787 146 24X Fichs. 50-322,84/03/27.0403280350
- 8403290377 Suppiemental memorandum opposing util summary disposition mutions on Contentions 24 B.33.45.46 & 49 Certificate of Svc snci Related correspondence LETSCHE,K J Suffolk County, NY LETSCHE,K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips DBB 196 B4/03/27 Atomic Bafety and Licensing Board Panel 19pp 22814 123 24X Fiche 50~322.84/03/27.8403270377
- 8403290390 Motion to remove Contention 77 from Cluster 3 & to reinsert Contention 77 into hearing schadule at later date Certificate of Syc encl
 LETBCHE.K Suffolk County, NY LETSCHE.K Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSD 197 84/03/27 Atomic Safety and Licensing Board Panel 10pp 22814 312 24X Fiche. 50-322,84/03/27,8403290390
- B403300256 Motion to strike portions of Group II-B testimony of Buffoik County Certificate of Svc enci Related correspondence CHRISTMAN, J N Long Island Lighting Co CHRISTMAN, J N Hunton & Williems DSB 214 84/03/27 Atomic Safety and Licensing Board Panel 38pp 22824 078 24X Fiche 50-322,84/03/27,8403300256
- B403300277 Suppl to motion for summary disposition of Contentions 24 B,33,45,46 & 49 No genuine issue of mati fact exists & util entitied to favorable decision W/Certificate of Svc Related correspondence MCCLEEKEY, K E Long Island Lighting Co MCCLEEKEY, K E Hunton & Hilliams DSB 224, 84/03/27 Atomic Safety and Licensing Board Panel 11pp 22824 020 24x Fiche 30-322, 84/03/27,8403300277
- 8403290373 Order confirming schedule for staff answer to LILCO 840320 supplemented motion for low power OL Courtesy notification and I.

 BERNNER, L. Atomic Safety and Licensing Board Fanel DBB (B5 84/03/28 GFfice of the Executive Legal Director 4pp 22814.087 24X Fiche 50-322.84/03/28,8403290373
- B403270383 Motion to strike portions of util Group II-B testimony as intelevant, nonprobative & incompetent Certificate of Svc encl. Related correspondence
 LETSCHE, K. J. Buffolk County, NY LETSCHE, K. J. Kirkpatrick,
 Lackhart, Hill, Christopher & Phillips DSS 188 84/03/28
 Atomic Sefety and Licensing Board Panel 76pp. 22814 164 24X
 Fiche 50-322,84/03/28,8403290383
- J. Insurance & indemnity information
- 8403140003 Forwards Endorsements 11 & 12 to NELIA Policy NF-269 ROBBING, J Ø Marsh & McLennan, Inc 84/03/05 DINITZ, I Assistant Director for State & Licensee Relations 3pp 22633 232 24X Fiths 50-222.84/03/05,6403140003

- G Inspection reports, IE Builetins & correspondence
- 8403010381 Forwards IE Insp Rept 50-322/84-01 on 840102-13 & natice of violation STAROSTECKI.R Division of Project & Resident Programs 84/02/16 POLLUCK.M S Long Island Lighting Co 2pp 22434 072 24X Fiche 50-322.84/02/16.8403010381
- --84030i0382 Notice of violation from 1nsp on 840102-i3 * Region 1, Office of Director 84/02/i6 ip 22434 074 24X Fiche 50-322.84/02/i6.84030i038i
- --8403010390 iE Insp Rept 50-322/84-01 on 840102-13 Violation noted reassembly of emergency diesel generator 101 not prescribed by & accomplished in accordance w/appropriate procedure PETRONE.C Region 1. Office of Director MCGABE.E C Division of Project & Resident Programs 84/01/16 App 22434 075 24X Fiche 50-322.84/02/16.8403010381
- 840ii90072 IE info Notice 84-i3, "Potential Deficiency in Mator Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22709 239 24X Fiche 50-000.84/02/28.8401190072
- 8402090007 IE info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enci GRACE, J N Division of GA. Safeguards & inspection Programs (Post 830103) 84/03/02 Consolidated Edizon Co of New York, Inc 130pp 22552 329 24% Fiche 50-000.84/03/02.8402090007
- 8402090008 iE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc i 1st enci JORDAN E L Division of Emergenty Preparedness & Engineering Response (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc i22pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 iE Info Notice 84-i5, "Reporting of Radiological Reiwases" Svc iist encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 94/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02.8402090009
- 8402090Qii IE info Notice 84-i7, "Probiems W/Liquid Nitrogen Coaling Components Beiaw Nil Ductility Temp " Svc iist enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 930103) 84/03/05 Consolidated Edison Co of New York, Inc ii7pp 22553 336 24X Fiche 50-000.84/03/05.8402070011
- 8403220143 Forwards iE Insp Rept 50-322/84-02 on 840i23-0226 No vigiations found STARDSTECKIR Division of Project & Resident Programs 84/03/06 POLLOCK,M S Long Island Lighting Co 2pp 227i4 3i7 24X Fiche 50-322.84/03/06.8403220i43
- --8403220160 iE Insp Rept 50-322/84-02 on 840123-0226 No violations found Major areas inspected, iE Bulletin 80-07 (Detail 3).TMI action items, review of emergency diesel generator testing & previously identified insp findings PETRONE, C. SHEDLOSKY, T. MCCABE. E. C. Region i. Office of Director 84/02/28 10pp 22714 319 24X Fiche 50-322.84/03/06, 8403220143
- 8402090024 IE info Notice 84-09, Rev i, "Lessons Learned From Insps of Fire Protection 8afe Shutdown Bys " Svc list enci JDRDAN,E L Division of Emergency Preparedness & Enginearing Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc i18pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-i8, "Stress Corresion Cracking in PWR 8ys " 8vc list encl JURDAN,E L Davision of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulietin 84~02, "Failures of CE Type HFA Relays in Use in Class IE Safety Bys " Svc list enci
 DEYOUND, R C Director's Office, Office of Inspection and
 Enforcement B4/03/12 Consolidated Edison Co of New York, Inc
 134pp 22823 094 24X Fiche 50-000,84/03/12,840209003i
- 8403290387 Forwards Tech Spec-related SALP input for Feb 1983 Feb 1984.in response to R Caruso 840305 memo Bafeguards-related input will be sent directly to R Caruso by Bafeguards Licensing Branch Category 2 assigned for mpt involvement. THOMAS, C 0 Standardization & Special Projects Branch 84/03/13 SCKMENCER.A Licensing Branch 2 4pp 22823 090 24X Fiche 50-322.84/03/13,8403270387

- 8403300072 Forwards IE (nsp Rept 50-322/84-03 on 840118-20 & 0209-11 No
- violations noted

 MARTIN T T Division of Engineering & Technical Programs 84/03/16

 POLLOCK.M S Long Island Lighting Co 2pp 22822 092 24X

 Fichs 50-322.84/03/16.8403300072
- --B403300076 IE (nsp Rept 50-322/84-03 on 84018-20 & 0209-11 No violations noted Major areas inspected licensee preliminary site activities in preparation for const of new emergency diesel generator bldg VARELA,A A. DURR.J P Region 1. Office of Director B4/03/07 3pp 22822 094 24% Fiche 50-322.84/03/16.8403300072
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list enti JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 227 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice B4-20. "Svc Life of Relays in Safety-Related Sys " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York inc 135pp 22933 001 24X Fiche 50-000.84/03/21.8402090044
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS.W J Office of the Executive Director for Operations 84/02/21 PALLADINO Commissioners 9pp 22492 083 24% Fiche 90-000.84/02/21.8403020443
- 8403270ii9 Forwards monthly status "List of Active Safety-Related Equipment at Qualification Level." per SER Issue 9 re dynamic qualification MCCAFFREY. B R Long Island Lighting Co B4/03/15 DENTON. H R Office of Nuclear Reactor Regulation. Director 2pp 22774 060 24X Fichs 50-322.84/03/15.8403270119
- --8403270122 "Control Bidg Category 1 Equipment Balance-of-Piant Qualification Level." monthly status rept • Stone & Webster Engineering Curp 84/02/27 50pp 22774 064 24% Fiche 50-322,84/03/15.8403270119
- S Repartable occurrences. LERs & related correspondence
- B403010451 Informs Commission of problems w/emergency diesei generators mfg by Transamerica Delaval. Inc
 DIRCKS.W.J. Office of the Executive Director for Operations
 SECY-93-034 84/01/25 4pp 22438 347 24X Fiche 30-000.84/01/25.
 B40301045i
- 8403010207 Forwards "Investigation of Types AF & AE Piston Bkirts," per Transamerica Belaval. Inc Duners Group program commitments Rept evaluates cracks in AF piston skirts in Ghoreham & Grand Gulf Nuclear Power Stations MUSELER. H J TDI (Transamerica Delavai, Inc.) Duners Group MUSELER. H J Long Island Lighting Co 84/02/27 DENYON, H R Dffice of Nuclear Reactor Regulation. Director 3pp 22434 070 24X Fiche 30-000,84/02/27.8403010207
- --8403010446 "Investigation of Types AF & AE Piston Skirts "
 * Failure Analysis Associates FAAA-84-2-14 84/02/27 83pp
 22434 093 24X Fiche 50-000.84/02/27.8403010207
- 840207002i Board Notification B4-037 discusses NRC 840210 & 16 meetings w/Transamerica Delaval, Inc Emergency Diesel Generators Gumers Group Meeting scheduled on 840208 for finalization of generic program plan prior to NRC review ETSENNUT, D 0 Division of Licensing 84/02/28 PALLADING, GLLIRSKY, ROBERTS Commissioners 5pp 22346 003 24X Fiche 50-000.84/02/28,8402070021
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval. Inc swargancy diesel generators MUSELER, H J TDI (Transamerica Delaval. Inc.) Owners Group 84/02/280 DENYON.H R Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Fiche 50-000,84/02/28.8403010218
- 8403260233 Forwards summary list of deficiencies identified per 10CFRSO 55(e), Part 21 & patential generic ltr repts for comments 8TARDSTECKIR Division of Project & Resident Programs 84/0
 - comments STARDSTECKI.R Division of Project & Resident Programs 84/02/28 Region 1. Office of Director 7pp 22736 C65 24x Fiche 50-000.84/02/28.8403260233

- B402090020 Board Notification B4-044 forwards Part 21 rept re Transamerica Delaval, Inc. turbocharger thrust bearing lubrication defect resulting in engine nonavailability EIEENHUT, D 0 Division of Licensing 84/02/29 PALLADING, 01LINSKY, RODERTS Commissioners 4pp 22541 263 24X Fiche 50-000.84/02/29.8402090020
- 840306033B Advises of problem compromising integrity of design review/
 quality revalidation of emergency diesel generators mfg by
 Transamerica Delaval Inc Util involvement in review
 represents conflict of interest
 BROWN.H H Kirkpatrick, Lockhart, Hill, Christopher & Phillips
 BROWN,H H Suffolk County, NY 84/03/01 DENTON.H R Defice of
 Nuclear Reactor Repulation, Director opp 22519 088 24X
 Fiche 50-322,84/03/01.840306038
- B403i40048 Forwards "Grand Oulf Component Tracking Bys," "Ehoreham Component Tracking Sys" & "Transamerica Delavai: Inc Diesel Generators Owners Group Program Plan." to resolve concerns w/emergency diesel generators MUSELER. H J Long Island Lighting Co 84/03/02, DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22626-062-24X Fiche 50-000.84/03/02, 8403140048
- --B403140080 "Grand Oulf Component Tracking Sys "
 + Long Island Lighting Co. 84/02/29 879pp 22626 064 24X
 Fiche 50-000,84/03/02,8403140048
- --8403140091 "Shoreham Component Tracking Sys "

 * Long Island Lighting Co 84/02/29, 516pp 22627, 069 24X
 Fithe 50-000, 84/03/02, 8403140048
- --8403140095 "Transamerica Delavai. Inc Diesei Generators Owners Group Program Plan " * TDI (Transamerica Delaval. Inc) Owners Group 84/03/02 261pp 22628 223 24X Fiche 50-000.84/03/02.8403140048
- 8402090033 Board Notification 84-047 forwards Transamerica Delavai. Inc Owners Group piston stirt rept & task descriptions EISENHUT, D.G. Division of Licensing 84703/07 PALLADINO, GILINGKY, ROBERTS Commissioners 4pp 22674 221 24X Fiche 50-000,84/03/07,8402090033
- 8403170127 Interim deficiency rept re failure of turbocharger on emergency standby diesei generator Temporary bypass valve around turbocharger preiube drip time orifice instailed W/Certificate of Bvc Related correspondence MCCAFFREY. B R Long Island Lighting Co 84/03/09 MURLEY, T E Region I, Office of Director 4pp 22669 252 24X Fiche 50-322.84/03/09.8403190127
- 8402090035 Board Notification 84-053 forwards "Emergency Disset Ownerator Component Tracking Bys." facility component data base for design review & quality revailedation effort of Transamerica Deiavai Duners Group program plan CISENNUT.D 0 Division of Licensing 84/03/12 PALLADIND, GILINEKY, ROBERTS Commissioners 4pp 67218 079 24% Fiche 50-322.84/03/12.8402090035
- --8403190385 "Emergency Diesel Generator Component Tracking Sys "
 * TDI (Transamerica Deiaval, Inc.) Gwners Group 84/02/29, 515pp 22475 322 24X Fichs 50-322.84/03/12.8402090035
- 8402090038 Board Notification 84-051 forwards "Trensamerica Delaval.inc (TDI) Diesel Generators Gwners Group Program Plan "EISENHUT:D 9 Division of Licensing 84/03/12 PALLADIND, GILINGHY, ROBERTS Commissioners 5pp 22688 214 24X Fiche 50-000.84/03/12,8402090038
- --8403200143 "Transamerica Delaval (TDI) Diesel Generators Owners Group Program Plan " * TDI (Transamerica Delaval, Inc.) Owners Group 84/03/12 261pp 22688 219 24% Fiche 50-322,84/03/12,8402090038.
- 8402070037 Board Notification B4-032 forwards meeting summaries containing transcripts of B40210 & 16 meetings between NRC & Transamerica Delayal.inc (TDI) Owners Group Distribution 1st encl
 EISENHUI, D O Division of Licensing 84/03/12 PALLADING, GILINEKY, ROBERTS Commissioners 5pp 22708 001 24% Fiche 50-000.84/03/12,8402090039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Owners Group in Bethesda.MD re problems w/emergency
 diesel generators
 CARUSO,R Licensing Branch 2 84/02/27 O'REILLY, J.P. NRC No
 Detailed Affiliation Glyen Gpp 22708 006 24X
 Fiche 50-000,84/03/12,8402090039

- --8403060554 Transcript of 840210 meeting w/Transamerica Deiaval. Inc Owners Group in Bathesda. MD re problems w/emergency diesel generators + NRC - No Detailed Affiliation Given 84/02/10 147pp 22708 012 24X Fiche 50-000.84/03/12.8402070039
- --B403070409 Summary of B40216 meeting w/Transamerica Delaval, inc Owners Group in Wading River, NY re program plan to establish reliability of diesal generators Agenda, meeting transcript & attendance list encl
 MILLER, HA Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Ficha 50-000.84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delavai. Inc diesei generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fichs 50-000,84/03/12,8402070039
- B403140050 Forwards "Design Review of Connecting Rod Bearing Shelis for Transamerica Delawal Enterprise Engines" for Shoreham & Grand Gulf diesel generators MUBELER, W. J. Long Island Lighting Co. B4/03/12 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 22632 074 24X Fiche 30-000:84/03/12, B403140050
- --8403140086 "Design Review of Connecting Rod Bearing Shells for Transamerica Delavai Enterprise Engines " Failure Analysis Associates PAO 7396, 84/03/12 51pp 22632 076 24X Fiche 50-000,84/03/12,8403140050
- B403150133 Forwards "Transamerica Delavai, Inc Diesel Generator Rocker Ann Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & svc conditions MUBELER, W J TDI (Transamerica Delaval, Inc.) Dwners Group MUBELER, W J Long Island Lighting Co B4/03/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000,84/03/13,8403150133
- --B403150154 "Emergency Diesel Generator Rocker Arm Capscrew Stress Analysis," prapared for Transamerica Delayal, Inc Owners Group
 * Stone & Webster, Inc 84/03/31 27pp 22637 272 24X
 Fiche 50-000,84/03/13,8403150133
- 8403190285 PNO-I-84-025 on 840313 licensee found crack in emergency diesel generator 103 engine block between cylinders 4 & 5 Crack being investigated through use of eddy current inspitechniques PETRONE.C., ESELOROTH, P. Region i. Office of Director 84/03/14 ip 22472 278 24X Fiche 50-322,84/03/14,8403190285
- B403200222 Responds to B40214 Requests for Info 1 & 2 re R-4 series engines Liet indicating engine number model & svc number. customer name & address, rating, date shipped & date sterted encl MATHEMB, C B Transamerica Delaval, Inc. B4/03/16 EISENHUT, D C Division of Liceneing 20pp 22691 179 24X Fiche 50-000, B4/03/16, B403200222.
- B403230094 PND-I-84-026 on B40313, crack discovered in emergency diesel generator engine. Ultrasonic & eddy current exam indicated crack depth of i inch & length of 2 inches State of NY informed PETRONE: C. ESELOROTH.P Region 1. Office of Director B4/03/20 ip 22724,345 24X Fiche 50-322,84/03/20. B403230094
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis." prepared by S&W for Transamerica Delaval, Inc (TDI) Diesel Generator Owners Group MUSELER: W J TDI (Transamerica Delaval, Inc.) Owners Group MUSELER: W J Long Island Lighting Co. 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 22774 001 24X Fiche 50-000, 84/03/23, 8403270132
- --8403270187 "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared for Transamerica Delaval. Inc (TDI) Diesel Generator Owners Group * Stope & Webster Engineering Corp 84/03/31 23pp 22774 003 24X Fiche 50-000.84/03/23,8403270132
- B403270134 Requeste meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica
 Delayal diesel gamerators List of suggested meeting topics
 ancl
 MCGAUGHY, J P TDI (Transamerica Deiayal, Inc.) Guners Group
 MCGAUGHY, J P Mississippi Power & Light Co 84/03/23 DENTON, H R
 Office of Nuclear Reactor Regulation, Director App 227A9, 133.
 24X Fiche 50-000, 84/03/23, 8403270134

- B403300170 Requests that Transamerica Delaval, Inc diesei review program be stopped promptly due to improper role of util in directing review New independent review should be established, in consultation w/Suffolk County UONES, F. F. Suffolk County, NY B4/03/23 DENTON, H.R. Defice of Nuclear Reactor Regulation. Director 20p 22820 047 24X Fiche 50-322,84/03/23,8403300170
- T Hearing transcripts on non-antitrust matters
- 8403010244 Surrebuttal testimony of DS Mileti & JH Borensen on Contention 23 re shadow phenomenon Related correspondence MILETI.D S . SORENSON, J H Suffolk County, NY 84/02/27 38pp 22434 219 24X Fiche 50-322.84/02/27,8403010244
- 8403060212 Forwards testimony on behalf on Governor Cuomo re Contentions 66 D.67.73 & 97 B Related correspondence ZAHNLEUTER.R.J. New York. State of 84/03/01 LAURENSON.J.A., KLINE.J.R., SHON.F.J. Atomic Safety and Licensing Board Panel 1p 22517 231 24X Fiche 50-322.84/03/01.8403060212
- --8403060226 Testimony of WJ Acquario.RD Albertin & RG Knighton re emergency planning Contention 67, "Evacuation of Persons W/o Access to Automobiles" Related correspondence ACGUARIO.W J. ALBERTIN.R D. KNIGHTON.R O. New York, Btate of 84/03/01 50pp 22517 232 24X Fiche 50-322.84/03/01.8403060212
- --B403060246 Testimony of MJ Acquario.RD Albertin & RO Knighton re emergency planning Contention 73: "Evacuation of Handicapped Persons Not in Special Facilities " Related correspondence ACQUARIO.M J. ALBERTIN.R D., XNICHTON.R O. New York, State of B4/03/01 13pp 22517 285 24X Fiche 50-322.84/03/01,8403060212
- ~-8403060252 Testimony of TD Gibbons re emergency planning Contention 66 D. "Agreements for Snow Removal" & emergency planning Contention 97 B. "Evacuation During Deep Snow " Certificate of Bvc encl Related correspondence GIBBONS, T D New York. State of 84/03/01 14pp 92517 298 24X Fiche 50-322.84/03/01.8403060212
- 8403060254 Forwards Suffolk County testimony on listed Group II contentions Remaining contentions will be addressed by cross-examination Contention 51 withdrawn Related correspondence LETECHE.K J Kirkpatrick, Luckhart, Hill, Christopher & Phillips LETECHE.K J Suffolk County, NY 84/03/02 LAURENSON.J A. KLINE.J R., SHON.F J Atomic Bafety and Licensing Board Panel ip 22514 001 24% Fiche 50-322.84/03/02.8403040254
- ---8403040259 Direct testimony of PD Herr on emergency planning Contention 22 D re inadequacy of LILCO emergency planning zone Related correspondence
 HERR.P B Suffolk County, NY 84/03/02 21pp 22514 002 24X
 Fiche 50-322,84/03/02.8403060254
- ---B403040266 Direct testimony of KJ Regensburg, RA Snow & VR Stile on emergency planning Contentions 20 & 55-58 re notification of public Related correspondence REGENBOURG, KJ, SNOW, RA, STILE, VR Suffolk County, NY B4/03/02 28pp 22514 023 24X Fiche 50-322, B4/03/02, B403060254
- --8403060270 Direct testimony of KJ Regensburg.RA Snow & VR Stile on emergency planning Contention 26 re notification of emergency response personnel Related correspondence REGENBURG.K J. BNAM.R A. BTILE.V R. Suffolk County, NY 84/03/02 76pp 22514 051 24X Fiche 50-322.84/03/02.8403060254
- --8403060278 Direct testimony of KJ Regensburg, RA Bnow & VR Stile on emergency planning Contentions 28, 29, 30, 31, 32 & 34 re communications among emergency response personnel Related correspondence RECENSBURG, K J. SNOW, R A , STILE, V R Suffalk County, NY 84/03/02 45pp 22514 127 24X Fiche 50-322,84/03/02,8403060254
- --8403060287 Direct testimony of JL Monteith.RC Roberts,P McGuire, MJ Turano.EJ Michel & PB Herr on emergency planning Contention 27 re-mobilization of emergency response personnel Related correspondence MONTEITH.JL., ROBERTS,R C., MCGUIRE.P Suffolk County, NY 84/03/02 144pp 22514 172 24X Fiche 50-322.84/03/02, 8403060254
- --8403060295 Direct testimony of JL Monteith.RC Roberts,P McOuire,
 MJ Turano & EJ Michel on emergency glanning Contention && re
 removal of obstacles from roadway & provisions for fuel
 Related correspondence
 MONTEITH.J L , ROBERTS,R C , MCGUIRE,F Suffolk County, NY
 84/03/02 32pp 22514 318 24% Fiche 50-322,84/03/02,8403060254

- ---B403060301 Direct testimony of RC Roberts DA Hoffman & JJ Read on smergency planning Contentions 24 T & 59 re notification to public by US Coast Guard Related correspondence ROBERTS,R C , HOFFMAN,D A , READ,J J Suffolk County, NY B4/03/02 | 15pp | 22514 350 | 24% Fiche 50-322.84/03/02 | 8403060254
- ---8403040307 Direct testimony of PB Herr & EJ Michel on Contentions 67 & 24 I re evacuation of persons w/o access to automobiles & lack of agreements w/transfer point owners Related correspondence
 HERR,P B . MICHEL E J . HERR,P B Suffolk County, NY 84/03/02 47pg \$2515 004 24x Fiche 50-322,84/03/02,8403060254
- --8403060310 Direct testimony of D Harris & M Mayer re Contentions 24 G. 24 K.24 P.73 & 75 Related correspondence HARRIS, D : MAYER, M Suffolk County, NY 84/03/02 33pp 22315 053 24X Fiche 50-322,84/03/02,8403060254
- --8403060314 Direct testimony of S Sampert on emergency planning Contention 73 A re evacuation of homebound Related correspondence SAEGERT, S Suffolk County, NY SAEGERT, S New York Univ. New York, NY 84/03/02 9pp 22515 086 24X Fiche 50-322,84/03/02,8403060234
- --8403060318 Direct testimony of RT Kreiling on Contention 24 O Related correspondence HREILING.R T Suffolk County, NY 84/03/02 3pp 22515 095 24% Fiche 50-322.84/03/02.8403050254
- --8403060319 Direct teatimony of RC Roberts on emergency planning Contention 74 re inappropriate proximity of proposed relocation ctrs Related correspondence RDEERTS.R C Suffolk County, NY 84/03/02 App. 22515 098 24X Fache 50-322,84/03/02,8403060254
- --B403060322 Direct testimony of PF Cosgrove & JL Fakler on emergency planning Contention 24 S re lack of agreements on emergency response training of non-LILCO personnel Certificate of Bvc encl Relates correspondence COSGROVE.P F , FAKLER.J L Suffolk County, NY 84/03/02 16pp 22515 102 24X flohe 50-322.84/03/02.8403060254
- 8403070147 Forwards listed testimonles on emergency planning issues
 Related correspondence
 MCCLESKEY, K E Harmon & Welss MCCLESKEY, K E Long Island Lighting
 Co 84/03/02 LAURENSON, J A , SHON, F J , KLINE, J R Atomic Safety
 and Licensing Board Panel 3pp 22542 001 24X
 Fichs 50-322,84/03/02,8403070147
- --8403070154 Testimony of CA Clawson MC Cordaro & CA Daverio on Phase II emergency planning Contentions 21 & 21 C re Spanish translation of public info CLAMSON, C A . CORDARON C . DAVERID, C A . Long Island Lighting Co 84/03/02 45pp 22542 056 24X Fiche 50-322,84/03/02,8403070147
- --8403070158 Testimony of MC Cordaro, CA Daverio, E8 Lieberman & JA Weismantle on Phase 11 emergency planning Contention 22 re expansion of emergency planning tone boundary CCRDARO, M C , DAVERIO, C A , LIEBERMAN, E B Long Island Lighting Co 84/03/02 60pp 22542 103 24X Fiche 50-322, 84/03/02, 8403070147
- --8403070160 Testimony of MC Cordato, JA Weismanthe & ED Robinson on Phase II emergency planning Contentions 24 F.G. I. K.L. D.P.R. B & T re itrs of agreement CORDARD, M C , WEISMANTLE, J A , ROBINSON, E D. Long Island Lighting Co 84/03/02 385pp 22542 175 24X Fiche 50-322,84/03/02,84
- ---8403070165 Testimony of MC Cordaro, CA Daverio, NA Hobbs, WF Renz & MG Schiffmacher on Phase II emergency planning Contentions 26A-C, 0 & E CORDARO, M C , DAVERIO, C A , HOBBS, N A Long Island Lighting Co 84/03/02 58pp 22543 200 24X Fiche 50-322,84/03/02,8403070147
- ~~8403070171 Testimony of MC Cordaro, JA Weismantle, E8 Liebermen & RA Variey on Phase II emergency planning Contention 27, CORDARO, M C . WEISMANTLE, J A , LIEBERMAN, E 8 Long Island Lighting Ca. 84/03/02 28pp 22943 256 24X Fiche. 50-322, 84/03/02, 8403070147
- --840307017B Testimony of MC Cordaro, CA Daverio, NA Hobbs & WF Ren: on Phase II emergency planning Contentions 28-32 & 34. CCRDARO, M C. DAVERIO, C A . HOBBS, N A Long Island Lighting Co 84/03/02 50pp 22543 286 24X Fiche 50-322,84/03/02,8403070147

- --B403070183 Testimony of MC Cordaro, CA Daverio & ML Miele on Phase II emergency planning Contention 31 re preselected dose sampling points CORDARO, M C. DAVERIO, C A , MIELE, M L Long Island Lighting Co 84/03/02 2ipp 22543 337 24X Fiche 50-322,84/03/02,8403070147
- --8403070190 Testimony of MC Cordaro, NA Hobbs, WF Renz, NO Schiffmecker & JA Weismantle on Phase II emergency planning Contentions 55, 56, 57 & 59 CORDARO, MC C. HOBBS, N A , RENZ, W F Long Island Lighting Co 84/03/02 37pp 22543 360 24X Fiche 50-322,84/03/02,8403070147
- --B403070195 Testimony of MC Cordero, ED Robinson & JA Weismantle on Phase II emergency planning Contention 38 re notification to special facilities & hearing impalred persons at home CORDARO, M C , ROBINGON, E D , HEISMANTLE, JA Long Island Lighting Co B4/03/02 70pp 22544 037 24X Fiche 50-322,84/03/02,8403070147
- --8403070198 Testimony of MC Cordaro, JA Welsmantle & EB Lieberman on Phase II emergency planning Contention & CORDARO, M C . WEISMANTLE, J A . LIESERMAN, E B Long Island Lighting Co 84/03/02 28pp 22544 112 24X Fiche 50-322.84/03/02.84/03/04.7
- --B403070201 Testimony of MC Cordano. JA Welsmantle & EB Lieberman on Phase II emergency planning Contention 67 CDRDARD. M C . WEISMANTLE. J A . LIEBERMAN. E. B Long Island Lighting Co B4/03/02 2Bpp 22544 142 24X Fiche 50-322. 84/03/02. 8403070147
- --B403070204 Testimony of CA Clawson, ED Robinson & JA Weismantle on Phase II emergency planning Contention 73 A re preregistration of handicapped CLAMBON.C A. CORDARO, M.C., ROBINSON, E.D. Long Island Lighting Co B4/03/02 33pp 22544 171 24X Fiche 50-322, 84/03/02, B403070147
- --8403070207 Testimony of MC Cordaro, EB Lieberman, ED Robinson & JA Weismantle on Phase II emergency planning Contention 73 B re notification & evacuation of handicapped at home CORDARO, M C., LIEBERMAN, E.B., ROBINSON, E.D. Long Island Lighting Co. 84/03/02 33pp 22544 206 24X Fichs 50-322,84/03/02,840370147
- --8403070211 Testimony of MC Cordaro, JA Welsmantle & ED Robinson on Phase II emergency planning Contention 74 re location of relocation ctrs CORDARO, M. C., WEISMANYLE, J. A., ROBINSON, E. D. Long Island Lighting Co. 84/03/02 71pp 22544 241 24X Fiche 50-322,84/03/02, 8403070147
- --B403070214 Testimony of MC Cordaro, JA Welsmantle & ED Robinson on Phase II emergency planning Contentions 75 re capacity of relocation ctrs and CORDARO, M C., WEISMANTLE, J A. ROBINSON, E.D. Long Island Lighting Co. B4/03/02 50pp 22544 302 24X Fiche 50-322,84/03/02. B403070147
- --8403070217 Testimony of MC Cordaro.CA Daverio & ML Miele on Phase II emergency planning Contention 77 re thyroid contamination equipment at relocation ctrs CCRDARO.M C. DAVERIO.C A. MIELE,M L Long Island Lighting Co 84/03/02 25pp 22544 341 24X Fichs 50-322.84/03/02.8403070147
- ---B403070220 Testimony of MC Cordaro & JA Weismantls on Phase II
 emergency planning Contention 92 re state emergency plan
 CORDARO,M C, WEISMANTLE, JA Long Island Lighting Co 64/03/02
 100pp 22545 006 24X Fiche 30-322.84
- --B403070222 Testimony of MC Cordard, NA Hobbs, WF Renz, WO Schiffmacher & JA Weismantle on Phase II emergency planning Contentions 93, 94 & 95 CORDARD, M C , HOBBS, N A , RENZ, W F Long Island Lighting Co 84/03/02 32pp 22545 119. 24X Fiche 50-322,84/03/02,8403070147
- --8403070227 Testimony of MC Cordato.ED Robinson & JA Weismantls on Phase II emergency planning Contentions 96 A & 96 C re loss of offsite power CORDARO.M C . ROBINSON.E D . WEISMANTLE.J A Long Island Lighting Co 84/03/02 15pp 22545 153 24X Fiche 50-322.84/03/02.8403070147
- --8403070231 Testimony of MC Cordaro, ML Miele & JA Weismantle on Phase II emergency planning Contention 97 B re evacuation in severe snowstorm Prof qualifications of LILCO witnesses & Certificate of Svc encl CORDARD, MC, MIELE, ML, WEISMANTLE, J Long Island Lighting Go. 84/03/02 160pp 22545 169 24X Fiche 50-322, 84/03/02, 8403070147

- B403140045 Forwards testimony of JR Sears on behalf of NRC staff re emergency preparedness Contentions 26 A, 26 C & 26 D REPRAD A Hearing Branch 3 B4/03/02 LAURENSON.J A , SHON,F J , KLINEAJ R Atomic Safety and Licensing Board Panel 13pp 22633 051 24X Fiche 50-322,84/03/02,8403140045
- B403130085 Motion of Governor Coomo to file rebuttal testimony on Contention 55 re evacuation time estimates Related correspondence ZAHNLEUTER, R J New York, State of 84/03/08 Atomic Safety and Licensing Board Panei 7pp 22614 274 24X Fiche 50-322,84/03/08,840313088
- --8403130091 Rebuttal testimony of DT Hartgen & FJ Bench re emergency planning Contention 65 on evacuation time estimates Certificate of 8vc encl HARTGEN.D T, BEACH,F J New York, State of 84/03/08 20pp 22614 281 24X Fiche 50-322,84/03/08,8403130085
- B402090039 Board Notification 84-092 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transemerica Delavai. Inc (TDI) Duners Group Distribution list and EISENHUT, D 0 Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fiche 50-000, 84/03/12.
- --8403060536 Forwards summary of 8402i0 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators GARUSO.R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No Detailed Affiliation Given 6pp 22708 006 24X Fiche 50-000,84/03/12,8402090039
- ---B403060554 Transcript of B40210 meeting w/Transamerica Delaval, Inc Gwners Group in Bethesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201.008 24X Fiche 50-000, 84/03/12,8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delavai, Inc Owners Oroup in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list enci
 HILLER: M A Licensing Branch 4 84/02/27 Licensing Branch 4
 8pp 22708 161 24% Fiche 50-000, 84/03/12, 8402090039
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp. 22708 169 24X Ficha 50-000,84/03/12,8402090039
- 8403260224 Transcript of B40320 hearing in Hauppauge.NY re emergency planning proceeding Pp 3.890-4.069 Supporting documentation encl
 # Atomic Bafety and Licensing Board Panel, 84/03/20 440pp 22756-236 24X Fiche 50-322.84/03/20.8403260224
- 8403220288 Forwards testimony on Oroup II B Contentions 24 E.24 F 2 & F 3,24 J.24 N.60.61,63.69.70.71.72.85 & 88 Testimony for Contentions ii & 15 will be filed on 84030 Related correspondence
 LETSCHE,K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips
 LETSCHE,K J Suffolk County, NY DSD 055 84/03/21
 LAURENBON,J A, KLINE,J R, SHON,F J Atomic Safety and Licensing
 Board Panel ip 22719.137 24X Fiche 50-322.84/03/21.8403220288
- --8403220292 Testimony of OJ Jeffers & AR Rossi re Contentions 24 E. 24 F.61, C.69, 70 & 71 Related correspondence JEFFERB, OJ, ROSSI, AR Suffolk County, NY 84/03/21 16pp 22719 158 24X Fiche 50-322,84/03/21,8403220288
- --8403220297 Testimony of RW Petrilak re Contentions 24 E, 24 N.61 C.69, 70 & 71 Related correspondence PETRILAK,R W Suffolk County, NY 84/03/21, 26pp 22719 174 24X Fichs.30-322,84/03/21,8403220288
- --8403220302 Testimony of NJ Muto & JT Smith re Contentions 24 E,24 F. 24, N,61,C,69,70 & 71 Related correspondence MUTO.N J. BMITH.J T Suffolk County, NY 84/03/21 i3pp 22717,200 24X Fiche 50-322,84/03/21,8403220288
- --8403220305 Testimony of FC Finlayson.OC Minor & EP Radford re Contention 61 Related correspondence FINLAYSON.F C, MINOR.O C, RADFORD.E P Suffolk County, NY 84/03/21 33pp. 22717 213 24X Fiche 50-322.84/03/21,8403220288
- --8403220310 Testimony of D Harris & M Mayer re Contentions 24 J, 24 N, 60, 63 & 72 Related correspondence
 HARRIB, D. MAYER, M. Suffolk County, NY 84/03/21 43pp
 22719 246 24X Fiche 50-322,84/03/21,8403220288

- --8403220313 Testimony of GC Minar re Contentions 85 & 88 Certificate of Svc encl Related correspondence
 MINDR. G Suffolk County, NY 84/03/21 17pp 22719 289 24X
 Fiche 50-322,84/03/21.8403220288
- B40323000B Testimony of RR Doremus on Contentions 24 E.24 F 2,24 F 3, 24 M.61 C & 69-71 re school emergency plans DOREMUS, R R Long Island Lighting Co DSD 062 84/03/21 31pp 2272B 312 24% Fiche 30-322.84/03/21.8403230008
- B403230016 Testimony of MC Cordaro, CA Daverio, ML Miele & RJ Watts on Contention BB re dose criteria & cost-benefit analysis for reentry Related correspondence CORDARD.M C. DAVERID.C A. MIELE, M L. Long Island Lighting Co. DSB 069 B4/03/21 43pp 22728 Q01 24X Fiche 50-322.84/03/21,
- 8403230020 festimony of MC Cordaro EB Lieberman.ML Miele.ED Robinson & JA Weismantte re Contentions 24 E.24 F 2.24 F 3.24 M.61 C & 68-71 re schools Related correspondence CORDARO,M C. MIELE,M L. Long Island Lighting Co LIFBERMAN,E B KLD Associates. Inc BSD 063 84/03/21 400pp 22725 001 24X Fiche 50-322.84/03/21,8403230020
- B403230032 Testimony of MC Cordaro.CA Daverio.ML Mieie.D9 Mileti & RJ Watts re Contentions 60.61,63 & 64 on protective action recommendations Related correspondence CORDARO.M C . DAVERIO.C A . MIELE.M L. Long Island Lighting Co OS B4703/21 197pp 22735 041 24X Fiche 50-322.84/03/21.8403230032
- 8403230038 Testimony of MC Cordaro D Glaser ML Mieie ED Robinson.

 JA Weismantie & J Yedvab on Contention 24 J.N.72 C.D & 96 B
 re planning for spocial facilities Related correspondence
 CORDARO M C . GLASSER D . MIELE, M L Long Island Lighting Co DSB
 044 84/03/21 294pp 22732 047 24X Fiche 30-322.84/03/21.
 8403230038
- 8403230048 Testimony of MC Cordaro, CA Daverio, ML Miele, SN Porter on Contention 81 re ingestion pathway Related correspondence CORDARO, M C. DAVERIO, C A. MIELE, M L. Long Island Lighting Co DSB 067 84/03/21 200pp 22724 131 24X Fiche 50-322, 84/03/21 8403230048
- B403230066 Testimony of MC Cordaro. JA Weismatie & Ep Lieberman on Contentions 72 A & E re adequate evacuation time estimates Related correspondence CORDARO.M C. WEISMANTLE. J A. LIEBERMAN, E D. Long (s) and Lighting Co. DSB 066 B4/03/21 iBpp 22726 257 247 Fishe 50~322,84/03/21,8403230066
- 8403230073 Testimony of MC Cordaro.CA Daverio.ML Miele & RJ Watts on Contention 85 re recovery & reentry Related correspondence CORDARO.M C . DAVERIO.C A . MIELE.M L Long island Lighting Co DS8 048 84/03/21 44pp 22726 230 24X Fiche 30-322.84/03/21, 8402230073
- 8403260012 Transcript of 840321 hearing in Hauppauge, NY re emergency planning proceeding Pp 4.070-4.268
 * Atomic Safety and Licensing Board Panel 84/03/21 200pp 22747 001 24% Fiche 50-322,84/03/21.8403260012
- 8403260338 Forwards direct testimony of CV Failla re Contention 24 F 2 Rolated correspondence ZAHNLEUTER,R J New York, State of D8B 097 84/03/21 LAURENSON,J A, KLINE,J R, SHDN.F J Atomic Safety and Licensing Board Panei ip 22760 165 24X Fiche 50-322.84/03/21.8403260338
- --8403260342 Direct testimony of CV Failla re Contention 24 F 2 on agreements w/bus companies in event of radiologica; accident FAILAAC V New York, State of 84/03/21 13pp 22760 166 24X Fiche 50-322.84/03/21.8403260338
- 8403260377 Forwards util testimony on Contention 18 re adequacy of zone & route info Related correspondence FALZONE, R Hunton & Williams FALZONE, R Long Island Lighting Ca D88 096 84/03/22 LAURENGON. J A. KLINE, J R., SHON, F J Atomic Bafety and Licensing Board Panel 1p 22760 001 24X Fiche 50-322, 84/03/22. 8403260377
- ---8403260379 Testimony of CA Clawson, MC Cordaro & CA Daverio on Contention 18 re adequacy of zone & route info Certificate of 8vc entl CLAMBON, C A , CORDARO, M C , DAVERIO, C A Long Island Lighting Co 84/03/22 55pp 22760 002 24X Fiche 50-322,84/03/22,8403260377
- 8403270176 Transcript of 840322 hearing in Hauppaugs.NY re emergency planning proceeding Pp 4,269-4,511 * Atomic Bafety and Licensing Board Panel 84/03/22 328pp 22772 182 24X Fichs 50-322,84/03/22,8403270196.

- 8403290001 Transcript of 840327 oral argument in Bethesda.MD Pp 1-192 * Atomic Safety and Licensing Appeal Panel 84/03/27 193pp 22803 088 24X Fiche 50-322.84/03/27.8403270001
- V Operator Examinations
- 8403270116 Forwards supplemental nuclear power plant experience tables for operating shift positions Espected QL date is 840518, in response to add questions in DF Schmell, Union Electric Co. ltr NOTARO, J A Long Island Lighting Co 84/03/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 22775 137 24X Fishe 50-322,86/03/22.840327016
- DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8403090027 FOld request for records re 1977 Nuclear Svcs Corp audit of Pullman Power Products
 REYNOLDS.J. Center for Law in the Public Interest 84/01/20
 Gffice of Administration 2pp 82592 329 24X
 Fiche 50-275,84/01/20.8403090027
- 8403010501 Forwards Board Notification 84-022 which provides in camera transcript of NRC 840125 meeting w/recipient & C 8tokes Requests specific identification of names & sections in rept to be withheld from public disclosure W/o entl EISEMHUT.D © Division of Licensing 84/02/14 DEVING.T Government Accountability Project 1p 22438 335 24X Fiche 50-275,84/02/14.8403010501
- 8402070004 Board Notification 84-037 forwards Chairman Palladino 840107 ltr transmitting rept on matters to GA Case Study C for plant Rept encls compare draft & final version of case study & include comments on draft version
 EISENHAUT, D © Division of Licensing 84/02/24 BUCK, J H ,
 MODRE, T S , JOHNSTON, W R Atomic Safety and Licensing Appeal Panel
 3pp 22547 036 24X Fiche 50-275,84/02/24,8402070004
- 8402090D17 Board Notification 84-038 forwards RJ Mattson 840123 mamo to D6 Elsenhut providing status update of NRC actions re Westinghouse ECGS actuation logic EISENHUT.D @ Division of Licensing 84/02/27 PALLADINO, OILINSKY, ROBERTS Commissioners 7pp 22546 007 24X Fiche 50-000.84/02/27.8402090017
- B403190165 Requests add1 info explicitly addressing specific steps in 36(FRB00 4(b),(c),or (d) re determination of effect of operation & maint activities on SLO-2 archaeological site

 KNIGHTDN,G W Licensing Branch 3 B4/02/27 BCHUYLER,J D Pacific Oas & Electric Cq 4pp 22646 345 24% Fiche 50-275, B4/02/27, B403150165
- 8403090028 Partial response to FDIA request for records re 1977 Nuclear Byes Corp audit of Pullman Power Products Documents entirely withheld (ref FOIA Exemption 5) Review of remaining documents subj to request in progress FELTON.J M Division of Rules and Records 84/03/01 REYNOLDS.J Center for Law in the Public Interest 2pp 22592 331 24% Fichs 50-275,84/03/01.8403090028
- 8403080405 Further response to FDIA request for documents re BER related to operation of facilities Forwards App B documents App A B documents available in PDR Review of remaining documents subj to request in progress FELTON. J M Division of Rules and Records 84/03/02 CARDE, B P Government Accountability Project 4pp 22583 073 24X Fiche 50-275,84/03/02,8403080405
- --B312230256 Forwards responses to Allegations 7,9 & 48,per 831130 request BFEIS.T P Division of Safety Technology 83/12/09 KNIGHTON,0 Office of Nuclear Reactor Regulation, Director 12pp 22883 111 24X Fiche 50-275,84/03/02,8403080405
- --8403080422 Forwards input on Allegations 51 & 52 Fuel loading addressed in 831108 Memorandum & Order CLI-83-27 No significant safety concerns matl to fuel loading & precriticality testing warrant continuation or suspension of activities BURNELS Office of the Executive Legal Director 83/12/09 KNIGHTON & Office of Nuclear Reactor Regulation, Director 3pp 22583.108 24X Fiche 50-275,84/03/02,8403080405
- --8403080426 Forwards safety evaluations for Allegations 8,10,11,14,15, i6,17,27,28,27,31,32,33,35,35,55,85 & 86 ticensee approach for determining containment stability against tilting acceptable VOLLMER,R H, Division of Engineering 83/12/09 CISENHUT,D Q, Division of Licensing 31pp 22583 132 24X Fiche 30-275,84/03/02,8403080405

- 8403150013 Forwards response to request for add1 info re Class IE electrical raceway supports Design supports have sufficient margin to assure that loss of single support will not cause loss of safety function SCHUYLER.J D Pacific Oas & Electric Co 84/03/07 MARTIN.J B. Region 5. Office of Director. 3pp 22640 327 24X Fichs 50-277.84/03/07.8403150013
- 8403200218 Forwards Rev 2 to Procedure EP OP-17. "Malfunction of RHR Sys." requested by ACRS Subcommittee on Diabio Canyon during 840210 meeting BCHUYLER.J D Pacific Oax & Electric Co 84/03/12 KNIGHTON.O W. Licensing Branch 3 lp 22699 337 24X Fiche 50-275,84/03/12,8403200218
- --B403200220 Rev 2 to Procedure EP OP-17, "Malfunction of RHR Bys"

 * Pacific Gas & Electric Co 82/02/19 3pp 22499 338 24X
 Fiche 50-275,84/03/12,8403200218
- 8402070041 Board Notification 84~050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT.D C Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000,84/03/14/8402090041
- 8403220035 Forwards tables providing detailed operating experience for licensed operating personnel & licensed & nonlicensed shift technical advisors BCHUYLER, J B Pacific Oas & Electric Co 84/03/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 22718 208 24X Fichs 50-275,84/03/16,8403220035
- B403260176 Informs of plans to have shift advisors w/qualifications & training recommended by Near-Term OL, Util Group on staff prior to exceeding 5% power Advisors will be subj to final eram following training

 SCHUYLER, J O Pacific Gas & Electric Co 84/03/23, KNIGHTON, Q W. Licensing Branch 3 lp 22758 234 24% Fiche 50-275, 84/03/23, 8403260176
- B403270366 Requests that license not be granted until allegations by employees of plant resolved MAYDEN. T California. State of 84/03/23 PALLADING, N Commissioners ip 22789 001 24X Fichs 50-275, 84/03/23, 8403270366
- E NRC Safety Evaluation Report (BER), supple & correspondence
- B403080085 F01A request for SER & BBER 21 (NUREQ-0675) re operation of facilities
 OARDE-B.P Government Accountability Project 84/01/09. Office of Administration 2pp 22584 074 24X Fiche 50-275,84/01/09. 8403080085
- 8403080096 Partial response to FOIA request for BER reaperation of facilities forwards documents listed on app Documents also placed in PDR. Review of remaining documents continuing FELYDN.J M Division of Rules and Records 84/01/23 GARDE, B P. Obvernment Accountability Project 2pp 22584 076 24X Fiche 50-275,84/01/23,8403080094
- --8403080103 Allegations 51 % 52 re NRC concern that plant personnel reluctant to come forward w/safety concerns since candor andangers Jobs * NRC No Detailed Affiliation Given. 84/01/23 2pp 22584'089 24X Fiche 50-275,84/01/23.8403080096
- B403060564 Forwards SBER 17 re util application for OLs Suppl addresses NRC evaluation re breakwater & superstrut issues W/o encl KNIOHTON: 0 R Licensing Branch 3 84/02/27 8CHUYLER: J O Pacific Gas & Electric Co 4pp 22552 265 24x Ficha 50-275; 84/02/27; B403060564
- 8403070104 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-275 And 50-323 (Facific Gas And Electric Company) bivision of Licensing NUREG-0675 817, 84/02/29 22pp, Available at NRC. \$3 00. 22561 214 24X Fiche 50-275,84/02/29, 8403070104.
- B402070030 Board Notification B4-035 updates allegation listed in SGER 21 & Board Notification 84-003 Public allegations not previously forwarded & characteritations of allegations from confidential sources encl EIBENHUT, D 0 Division of Licansing 84/03/02 PALLADING, QILINGKY, ROBERTS Commissioners 11pp. 22536,061 24X Fiche 50-275,84/03/02,8402070030

- --B312140347 Forwards Nuclear Byc Corp 1977 audit of Pullman Power Products work scape at facility, in response to B31004 ltr to Chairman Palladino Attention called to ASLAB B31024 denial of Joint Intervenor B31020 motion to reopen record DIRCKB, M J. Office of the Executive Director for Operatione B3/11/18 THOMAS, W M House of Rep 4pp 22556 080 24X Fiche 50-275, 84/03/02,8402070030
- --B312140351 Forwards JR Reynolds B30921 ltr expressing concern, on behalf of Joint Intervenors re deficient design & const of facility Nuclear Svc Corp 1977 audit encl
 THOMAS, W M House of Rep B3/10/04 PALLADINO, N Commissioners
 4pp 22556 081 24X Fiche 50-R75, B4/03/02, B402090030
- --8403080281 "Audit Rept Pullman Power Products Work Scope at Diabla Canyon Site 770822-0920 " WEBER, J , LARSEN, O J , NEWMAN. T C Pacific Gas & Electric Co 77/09/20 42pp 22556 090 24% Fithe 50-275.84/03/02.8402090030
- --8312280097 Responds to 831021 ltr re rept of 1977 audit of Pullman Pawer Producte Corp Motion filed before NRC for revocation or in alternative continuation of suspension of low power CL for facility Matter referred to NRC DIRCKB,W J Office of the Executive Director for Operatione 83/11/18 PANETTA,L E House of Rep 4pp 22554 132 24X Fiche 50-275,84/03/02.8402090030
- ---B312280107 "Proposal for Independent Internal Audit of Pullman-Kellogg Efforts at Diablo Canyon " * Nuclear Services Corp 77/07/28 21pp 22556 134 24X Fiche 50-275,64/03/02.8402090030
- --8401040010 Forwards all ltrs which appeared in Ben Luis Obispo Telegram-Tribune between 831019-31 re emergency planning response plan for facility Lack of public confidence in response plan discussed KRANZDORF.R Affiliation Not Assigned 83/11/04 PALLADINO, N Commissioners 17pp 22556.175 24X Fiche 50-275,84/03/02,
- B4030B0405 Further response to FGIA request for documents re BER related to operation of facilities Forwards App B documents App A & B documents evailable in PDR Review of remaining documents subj. to request in progrees
 FELTON, J.M. Division of Rules and Records 84/09/02, GARDE, B P Government Accountability Project. 4pp 22589 079 24X
 Fiche: 50-275, 84/09/02, 8403080405
- --B4030B043i Forwards SBER input re Allegation 68 Programmatic breakdown in Pullman Power Products GA program not indicated Installed hardware safety concerns not identified.

 LIEBERMAN, J Office of the Executive Legal Director B3/12/27 EIBERNHUT, D Division of Licensing 4pp 22383 i63 24X Fiche 50-275, 84/03/02,8403080405
- B403300300 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, Units 1 AND 2 Docket Nos 50-275 And 50-323. (Pacific Gas and Electric Company)

 # Division of Licensing NUREG-0675 822 84/03/31 400pp Available at NRC. \$11 00 22843 001 24X Fichs 50-275,84/03/31, 8403300300
- F Becurity, medical, emergency & fire protection plans
- 8403280114 Public version of revised emergency plan implementing procedures including Procedures EP OP-7 re loss of reactor coolant pump w/o reactor trip & EP G-2 re establishment of organization W/840105 & 0322 memos
 THOMBERGOR C., SCHUYLER, J D Pacific Oas & Electric Co 84/01/05
 MARTIN.J.S Region 5, Office of Director 33pp 22811 236 24X
 Fiche 50-275,84/01/05,8403280114
- 8403070355 Public vereion of emergency plan implementing procedures, including Procedure EP G-4 personnel accountability & assembly & EP RB-12 re mid & high-renge plant vent radiation magnitors W/840208 ltr & JM Felton 840302 release memo THOMBERGOR, C , SCHUYLER, J O, Pacific Gas & Electric Co 84/01/23 MARTIN, J S Region 5, Office of Director 120pp 22565 189 24X Ficher 50-275,84/01/23,8403070355
- B403070172 Forwards Rev 11 to physical security plan Rev Withheld (ref 10CFR73.21), BCHUYLER, J O. Pacific Qas & Electric Co B4/02/06 MARTIN, J B Region 5, Office of Director 1p. 22575 049 24X Fiche: 50-275, 84/02/06, 8403070172
- B402230176 Forwards revised State of CA nuclear power plant emergency response plan MEDFORD, M O Southern California Edison Co. 84/02/16 EISENHUT, D O, Division of Licensing 383pp 22333 001, 24X Fiche: 50-000, 84/02/16, 8402230176

- --B403020117 Revised State of CA nuclear power plant emergency response
 plan

 * California: State of B3/04/30 2901pp 22353 003 24X
 Fiche 50-000, B4/02/16: B402230176
- 8402070006 Board Notification 84-034 forwards R Volimer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D 0 Division of Licensing 84/02/23 PALLADIND Commissioners 1p 22576 203 24X Fiche 50-000.84/02/23, 8402070006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.psr NRR Off. Ltr 17, dtd 821001 Further swalluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT.D O Division of Licensing 10pp 22076 204 24X Fiche 50-000,84/02/23,8402090006
- 8403080405 Further response to FOIA request for documents re BER related to operation of facilities Forwards App B documents App A & B documents available in PDR Review of remaining documents subj. to request in progress FELTON. J M Division of Rulee and Records 84/03/02 GARDE. B P Government Accountability Project 4pp 22583 073 24X Fiche 50-275,84/03/02.8403080405
- --84030804ii Forwards response to Allegation RV-83-A-0034.per GW
 Knighton 83ii22 note Temporarily exempting licensee from
 maintaining physical security & safeguards contingency
 plans did not increase risk of radiological sabotage
 MCCORKLE.G W Power Reactor Bafeguards Licensing Branch
 83/12/01 THOMAS.C O Standardization & Special Projects Branch
 4pp 22583 077 24X Fiche 50-275.84/03/02.8403080405
- --B4030B0417 Resubmits response to Allegation RV-83-A-0034, per GW Knighton 83:103 memo Temporarily exempting licenses from maintaining physical security & safeguards contingency plans did not increase risk of radiological sabotage MCCORKLE.0 H Power Reactor Safeguards Licensing Branch 83/12/05 TMUMAB.C O Standardization & Special Projects Branch 3pp 22583 081 24X Fiche 50-275.64/03/02.8403080405
- --B4030B0420 Forwards response to Allegation RV-83-A-0034.per GW Knighton B21122 note Temporarily exempting licensee from maintaining physical security & safeguards contingency plans did not increase risk of radiological sabotage BURNETT.R F Division of Safeguards 83/12/08 EISENHUT.D G Division of Licensing 3pp 22583 084 24X Fiche 50-275, B4/03/02.8403B0405
- B4032B0001 Forwards safeguards info re changes to Rev ii to security plan Info withheld (ref 10CFR73 21)
 BCHUYLER, J D Pacific Oas & Electric Co B4/03/19 MARTIN, J B
 Region 5, Defice of Director 1p 22777.151 24X
 Fiche 50-275,84/03/19,84032B0001
- 8403270205 Discusses Southern Celifornia Edison submittal of 1983 revised State of CA emergency response plan on behalf of all State of CA plante, incorporating plan into Diablo Campon Addl planning info will not be developed for Humboldt Day SCHUYLER, J D Pacific Gas & Electric Co 84/03/22 DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p 22772 137 24% Fiche 50-000,84/03/22,8403270205
- 8403290264 Advises that 840111 rev to physical security plan & drewings consistent w/provisions of 10CFR50 54(p) & acceptable BCHUSTER; M D Region 5. Office of Director 84/03/23 BCHUYLER; J D Pacific Oas & Electric Co. ip 22800 010 24X Fiche, 50-275,84/03/23,8403290264
- O. Adjudicatory correspondence
- 8402070012 Board Notification 84-045 forwards 840202 petition to defer decision re low power OL, made by Govt Accountability Project (QAP) on behalf of San Luis Obispo Mothers for Peace Distribution list t app encl EISEN-NUT, D Q Division of Licensing 84/02/27 MOORE, T S, JOHNSON, W R, BUCK, J H Atomic Safety and Licensing Appeal Panel 5pp 67218 074 24% Fiche 50-275,84/02/29,8402090012
- 8403070044 Motion for extension until 840319 to file response to Joint Intervenors 840222 motion to reopen record on const 8A Certificate of 8vc encl NORTON, 8 Pacific Gas & Electric Co NORTON, 8 Norton, Burke, Barry & French 84/02/27 Atomic Safety and Licensing Appeal Panel 5pp 22541 250 24X Fiche 50-275, 84/02/27, 8403070044.

- 8403140071 Forwards expurgated transcript of 840125 meeting between staff & C Stokes, per ASLAB 840223 order W/o encl RUTBERG, J Hearing Branch 2 84/02/29 HORRE, T S. BUCK, J H. JOHNSON, W R Atomic Safety and Licensing Appeal Panel 2pp 22634 184 24X Fiche 50-275,84/02/29,8403140071
- 8403050260 Response of Governor Beukmejian to util 840227 motion for extension of time to respond to Joint Intervenor 840222 motion to reopen & motion of Beukmejian for like extension of time to reply Certificate of Svc entl
 STRUMMASSER,N California, State of 84703/01 Atomic Safety and Licensing Appeal Panel 9pp 22517 132 24x Fiche 50-275,84703/01,8403060260
- 8403080118 Supp)) to 840214 motion to augment or, in alternative, to reopen record Provides addi explanantion of allegations redesign & design 9A deficiencies from transcript of 840125 meeting Certificate of Svc and REYNOLDS. J R Joint Intervenors Diablo Canyon REYNOLDS. J R Joint Intervenors Diablo Canyon REYNOLDS. J R Center for Law in the Public Interest 84/03/01 Atomic Safety and Licensing Appeal Penel 15pp 22559 182 24X Fiche 50-275.84/03/01.8403080118
- 8403060179 Order granting applicant 840229 motion for extension of time to 840319 to respond to Joint Intervenors 840222 motion to reopen record on const GA TOMPKINS.B A Atomic Safety and Licensing Appeal Panel 84/03/02 2pp 22518 348 24% Fiche 50-275,84/03/02,8403060179
- 8403070128 Suppl to 840222 motion to reapen record on issues of const GA & licensee character & competence Serious doubts re util competence to manage project raised W/Certificate of Syc REYNDLDS, J R Affiliation Not Assigned REYNDLDS, J R Center for Law in the Public Interest 84/03/02 Atomic Safety and Licensing Board Panel 23pp 22538 231 24X Fiche 50-27b,84/03/02,8403070128
- 8403140179 Request for estension of time to 840315 to file response to Joint Intervenor motion to augment or repper record Certificate of Svc encl RUTBERG. J. Hearing Branch 2 84/03/02 Atomic Safety and Licensing Appeal Panel App. 22624 100 24X Fiche 50-275,84/03/02,8403140179
- 8403070188 Order requiring governor response to Joint Intervenor 840214 motion to reopen record on issue of design QA by 840308 SHOEMAKER.C J Atomic Safety and Litersing Appeal Panel 84/03/06 California, State of 1p 22541 362 24% Fiche 50-275,84/03/06,8403370188
- 8403120006 Answer opposing Joint Intervenors 840214 motion to augment or reopen record on design 0A Hotion should be denied in entirety Certificate of Svc encl
 NORTON.8 Pacific Cas & Electric Co NORTON.0 Norton, Burke,
 Berry & French 84/03/06 Atomic Safety and Licensing Appeal
 Panel 23pp 22956 189 24X Fiche 30-275.84/03/06.8403120006
- --8403120010 Affidayit of FC Breismeister, DJ Curtis, HJ Jacobson, ME Leppke, OH Moore, RO Oman, LE Shipley & WH White re design QA BREISMEISTER, F. CURTIS, D. J. JACOBSON, M. J. Pacific Oas & Eisctric Ca 84/03/05 101pp 22586 331 24X Fiche 50-275, 84/03/06, 8403120006
- --8403120015 Affidavit of LB Mangoba re design verification & const of small bore pips support sys
 MANGOBAL B Bechtel Corp 84/03/04 App 22587 128, 24X
 Fichs 50-275,84/03/04,8403120006
- --8403120017 Affidavit of A Shusterman re design QA & coverup of hanger recalculation SHUSTERMANA Bechtel Corp 84/03/04 4pp 22587 134 24X Fiche 50-275,84/03/06.8403120006
- --8403120018 Affidavit of RD Etzler re design GA & QC inspector qualifications ETZLERR D Pacific Gas & Electric Co 84/03/06 4pp 22587 138 24X Fiche 50-275.84/03/06,8403120006
- --8403120022 Affidavit of HB Friend re design GA & util/Bechtel contract FRIEND, H B Pacific Gas & Electric Co 84/03/05 2pp 22587 142 24% Fiche 50-275,84/03/06,8403120006
- --8403120023 Affidavit of DJ Curtis re design GA & small bore pipe support group drawing CURTIS,D J Berthel Corp 84/03/05 2pp 22587 144 24X Fichs 50-275,84/03/06.8403120006

- --B403120029 Affidavit of JD Shiffer, R Patterson, JM Gisclon, KC Doss, JB Hoch, RC Thornberry, RD Etzler, RK Rhodes & EM Burns re J Copper B40123 affidavit & Joint Intervenor 840214 motion on design 0A BHIFFER, JD., PATTERSON, R., GILSCLON, JM Pacific Cas & Electric Co B4/03/05 234pp 22587 146 24X Fiche 50-275, 84/03/06, B403120006
- 8403150010 Summarizes fears that Commission will discard terms of 1981 order & will surrender normal requirements of Atomic Energy Act by permitting, facility to go critical in quality indeterminate state CLEWETT. J Government Accountability Project DEVINE, T. CLEWETT. J Ban Luis Obispo Mothers for Peace 84/03/13 PALLADINO, N J, OILINGKY, V. ROMBERTS, T Commissioners 22642 326 24X Fiche 50-275,84/03/13,8403150010
- 8403160014 Order extending time until 840413 for Commission to act to review ALAB-756 CHILM.9 J Office of the Secretary of the Commission 84/03/13 Commissioners ip 22652:362 24X Fiche 50-275,84/03/13,8403360014
- 8403190011 Motion for leave to file reply to util answer in opposition to motion to reopen record Certificate of Svc encl REYNOLDS, J. R. Joint Intervenors Diablo Canyon REYNOLDS, J. R. Center for Law in the Public Interest 84/03/15 Atomic Safety and Licensing Appeal Panel 5pp 2265 273 24X Fiche 50-275,84/03/15,8403190011
- --B403190016 Reply to util answer in opposition to B40214 motion to augment or, in alternative, to reopen record Contentions in opposition cannot withstand scruting Certificate of BVc encl REYNOLDS, J. R. Joint Intervenors Diablo Canyon REYNOLDS, J. R. Center for Law in the Public Interest B4/03/15. Atomic Bafety and Licensing Appeal Panel. 26pp 22665 278. 24X Fiche 50-275, B4/03/15,8403190011
- ---8403190021 Statement of C Stokes rebutting util defenses of seismic design review STOKES:C Joint Intervenors - Diablo Canyon 84/03/14 24pp. 22665 309 24X Fiche 50-275,84/03/15,8403190011
- B403190100 Answer apposing Joint Intervenor B40214 motion to augment or in alternative to reopen record on design GA issues Hotion failed to justify either augmentation or reopening record Certificate of Svc encl
 RUTBERG. J. CHANDLER. L. J. Hearing Branch 2 MCGURREN, H. J. Hearing Branch 1 B4/03/15 Atomic Safety and Licensing Appeal Panel 29pp 22667 213 24X Fiche 50-275.84/03/15.8403190100
- --8403190102 Affidavit of JP Knight re Joint intervenors motion to augment or, in alternative, to reopen record KNIGHT, JP Division of Engineering 84/03/15 Atomic Safety and Litensing Appeal Panel 16pp 22667 244 24X Fiche 50-275,84/03/15,8403190100
- --840319Di06 Affidavit of M Hartzman re Joint Intervenors motion to augment or, in alternative, to respen record HARTZMAN, M Division of Engineering 84/03/15 22pp 22667 260 24X Fiche 50-275,84/03/15,8403190100
- --8403190110 Affidavit of SD Reynolds re Joint Intervenors 840214 motion to augment or, in alternative to respen record REYNOLDS, B. Region 1. Office of Director 84/03/15 8pp 22667 282 24X Fiche 50-275,84/03/15,8403190100
- --8403170114 Affidavit of TW Bishop re Joint Intervenors 840214 motion to augment or in alternative, to reopen record BISHOP.T W Region 5, Office of Director 84/03/08 4pp 22667 290 24X Fiche: 50-275,84/03/15,8403190100
- --B403190116 Affidavit of JR Fair re Joint Intervenors 840214 motion to augment or, in alternative, to reopen record FAIR, J R Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/08. 6pp 22667, 294 24X F1ths 50-275, 84/03/15, 8403190100
- --B403190119 Affidavit of CY Liang re deficiencies in RHR sys design LIANG.C.Y Division of Systems Integration (post 811005) 84/03/15 30pp 22667:300 24X Fiche 50-275,84/03/15,8403190100
- --8403190122 Affidavit of F Rosa re RHR sys RGBA, F Division of Systems Integration (post 811005). 84/03/15 17pp 22647 330 247 Fiche 50-275.84/03/15.8403190100
- --8403190126 Affidavit of JL Crews re Joint Intervenors 840214 motion to augment or in alternative to reopen record CREHS.J L Region 5. Office of Director 84/03/14 5pp 22667 347 24% Fiche 50-275,84/03/15,8403190100

- --B403190i30 Supplemental affidavit of JL Creus on addl info re Joint Intervenors motion on GA deficiencies CREMS, J L Region 5, Office of Director 84/03/15 ip 22667 352 24X Fiche 30-275,84/03/15,8403190100
- --8403190134 Affidavit of H Schierling re Joint Intervenors 840214 motion to augment or, in alternative, to respen record Unexecuted affidavit of PJ Morrill enci SCHIERLING, H Literaing Branch 3 84/03/15 3pp 22667 353 24X Fiche 50-275,84/03/15,8403190100
- 8403210033 Request for extension of time until 840403 to file response to Joint Intervenors motion to reopen record on const QA Certificate of 8vc encl
 CHANDLER, L. J. Hearing Branch 2 84/03/16 Atomic Safety and Licensing Appeal Panel 4pp 22704 330 24X Fiche 50-275,84/03/16,8403210033
- 8403210114 Forwards PJ Morrill signed & corrected affidavit as addendum to NRC 840315 response to Joint Intervenors motion to augment or reopen design GA record Related correspondence CHANDLER, L.J. Hearing Branch 2 84/03/16 MORRE, T.S., BUCK, J.H. Atomic Bafety and Licensing Appeal Panel JOHNSON, W.R. Atomic Bafety and Licensing Board Panel 2pp 22707 126 24% Fichs. 50-275, 84/03/16, 8403210114
- --8403210119 Affidavit of PJ Morrill as addendum to NRC 840315 response to Joint Intervenors motion to augment or reopen design QA record. Prof qualifications of JP Knight also encl MCRRILL.P J. Division of Resident Reactor Project & Engineering Programs 8403315 Atomic Bafety and Licensing Board Panei 15pp. 22707 128 24X Fiche 50-275.84/03/16.8403210114
- B403200133 Discusses dispute between plant workers & util re slander suit Identification of relevant issues, establishing accountability for inaccurate util statements & fixing hardware from GA breakdown not yet possible DEVINE, T Government Accountability Project DEVINE, T. San Luis Chispo Mothers for Peace B4/03/19 PALLADIND, N J , GILINSKY, V , ROBERTS, T. Commissioners 20pp 22699 047 24X Fiche: 50-275, 84/03/19, 8403200133
- B403210157 Decision ALAB-763 affirming LBP-B2-70 granting authorization to operate facility, w/listed conditions
 BHOEMAKER, C J Atomic Safety and Licensing Appeal Panel DBB 021
 B4/03/20 122pp 22710 144 24X Fiche 50-275.84/03/20.8403210159
- 8403220106 Forwards renewal of application for stay to permit completion of administrative review & opportunity for court review of Joint Intervenors emergency motion REYNOLDS, J.R. Center for Law in the Public Interest REYNOLDS, J.R. Jaint Intervenors Diable Canyon DSB 044 84/03/20 PALLADINO, N. GILINSKY, V. ROBERTB, T. Commissioners 2pp. 22715 304 24X Fiche 50-275,84/03/20,8403220106
- --8403220110 Renewal of application for stay to permit review of Joint Intervenors emergency motion Unexecuted affidavit of M Kaku & Centificate of Bvc encl
 REYNOLDS, J.R Joint Intervenors Diablo Canyon REYNOLDS, J R
 Center for Law in the Public Interest 84/03/20 Atomic Safety and Licensing Appeal Panel 25pp. 22715 306 24X
 Fiche 50-275,84/03/20,8403220106
- B403270298 Comments on request for meeting to discuss issues raised by C Stokes on submission by util & staff re design GA Related correspondence CHANDLER.L.J Hearing Branch 2 DBB 139 84/03/21 DEVINE, T Government Accountability Project 2pp 22789 035 24X Fiche 50-275,84/03/21,8403270298
- 8403270004 Discusses State of CA emergency response plan Plan incorporated into Diablo Canyon plan Addl planning will not be performed for Humboldt Bay per 1980 legislation Related correspondence SCHUYLER, J D. Pacific Cas & Electric Co. DSB 117 84/03/22 DENTON: R Office of Nuclear Reactor Regulation, Director 1p. 22769: 349 24X Ficher 50-000, 84/03/22, 8403270004
- 8403260005 Requests that low power test license not be granted.
 Discussion before licensing vote requested
 LEVY.B., SHARPE,C Affiliation Not Assigned DSB 077 84/03/23
 PALLADING,N, ABSELBTINE,JK, BERNITHALF,J Commissioners, 1p
 22747:356 24X Fiche 50-275,84/03/23,8403260005
- 8403260364 Forwards 12 add1 affidavits in support of 840301 petition to defer any futher licensing decisions until completion of comprehensive reinspragt audit & audit of design verification. W/o encl.

 BEVINE.T., CLEWETT.J. Government Accountability Project.
 BEN Luis Obispo Mothers for Peace DSB 101 84/03/23 PALLADINO.N.J. GLINSKY, V. ROBERTS.T. Commissioners 7pp 22740:065. 24% Fiche: 50-275, 84/03/23, 8403260364

- 8403270006 Informs that 12 add1 affidavits in support of Nothers for Peace 840301 petition to defer licensing submitted to Region V Related correspondence * Government Accountability Project DSB 115 B4/03/23 PALLADINO,N J Commissioners ip 22770 009 24X Fichs 50-275,84/03/23,8403270006
- 8403270347 Telecopy ltr expressing view that no low power license should be granted until all safety questions & allegations resolved O'CONNELL.J California, State of DSS 142 84/03/23 PALLADIND,N Commissioners 1p 22789 005 24X Fiche 50-275.84/03/23.8403270347
- 8403270352 Telecopy itr urging assurance that alleged safety hazards checked & thoroughly evaluated before granting license BRONZAN,B California, State of DEG i40 84/03/23 PALLADINO,N Cammissioners ip 22789 004 24X Fiche 50-275,84/03/23,8403270332
- B403240375 Requests opportunity to discuss OL issuance Commission should not vote on low power testing LEVY, B. GHARPE.C. Affiliation Not Assigned DSB 093 84/03/26 PALLADINO, N. GILINGKY, V. ROBERTS.T M Commissioners 1p 22740 138 24X Fiche 50-275,84/03/26,8403260375
- 8403260378 Requests that Commission not vote & authorization to operate not be given to facility LEVY,B., SHARPE,C. Affiliation Not Assigned. DSB 092 84/03/26 ABSELBTINE,J K., BERNTHAL,F J. Commissioners ip 22760 136 24X Fiche 50-275,84/03/26,8403260378
- H Ceneral correspondence
- 8403010525 Responds to 840112 request that NRC deny POLE any type of OLfor plant Validity of allegations re design & const being evaluated Commission will not recommend that low power license be fully reinstated until evaluation complete DENTON.H R Office of Nuclear Reactor Regulation, Director 84/02/15 KNUTBON.J A Affiliation Not Assigned 3pp 22443 282 24X Fiche 50-275,84/02/15,8403010525
- --8403010532 Expresses concern that plant poses grave danger to environ & public health of State of CA & urges NRC to deny util any type of DL due to continuing design flaus KNUTBON. J A Affiliation Not Assigned 84/01/12 DIRCKS, W NRC No Detailed Affiliation Given ip 22443 285 24X Fiche 50-275,84/02/15,8403010525
- I Financial information
- 840328005i Annual Financial Rept 1983 W/840326 ltr MIELKE,F W , GHACKELFORD,B , CRANE,P A Pacific Gas & Electric Co 83/12/31 50pp 22776 230 24X Fiche 50-000,83/12/31,8403280051
- J Insurance & indemnity information
- 8403280033 Forwards Endorsement 40 to NELIA Policy NF-228 CRANE,P A Pacific Cas & Electric Co 84/03/21 SALTZMAN,J D Assistant Director for State & Licensee Relations 2pp 22777 044 24X Fiche: 50-275.84/03/21,8403280033
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 8403280307 Summary of ACRS Subcommittee on Extreme External Phenomena B31012 meeting w/util.Westinghouse.TERA & Univ of Iilinois in Mashington, DC re use of tan effect methodology in seismic design analysis at Diablo Canyon Agenda sncl # ACRS Advisory Committee on Reactor Safeguards 83/11/25 ACRS Advisory Committee on Reactor Safeguards 16pp. 22808 040 24X Fiche: 50-275,83/11/25,8403280307
- 8403290381 Notice of ACRS 840405-07 meetings in Washington DC Agenda encl CHILK, 8 J Office of the Secretary of the Commission DSB 198 84/03/28 App 22814 QB; 24% Fiche 50-275,84/03/28,8403290381
- G Inspection reports, IE Bulletins & correspondence
- 8403060138 Forwards IE Insp Repts 50-275/83-39 & 50-323/83-27 on 831205-22 & notice of violation BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/02/03 SCHUYLER, J D Pacific Qas & Electric Co 2p 22506 334 24X Fiche 50-275, 84/02/03, 8403060138

- --8403060146 IE Insp Repts 50-275/83-37 & 50-323/83-27 on 831205-22 Noncompliance noted failure to properly implement fire loss prevention procedures & suppls SCDMN,K : POLICH, (. CANTER, H L Region 5, Office of Director 84/01/24 18pp 22506 338 24X Fiche 50-275,84/02/03,8403060138
- 8403060207 Forwards IE Insp Repts 50-275/84-01 & 50-323/84-01 on 840103-06 & notice of violation BESHDP.T W Division of Resident.Reactor Project & Engineering Programs 84/02/17 SCHUYLER.J O Pacific Gas & Electric Co 2pp 22517 145 24X Fiche 50-275,84/02/17,8403060207
- --B403060223 IE Insp Repts 50-275/84-01 & 50-323/84-01 on 840103-06 Noncompliance noted failure to perform safety-related welding activities in area of structural steel welding activities BURDOIN.J F, KIRSCH.D F Region 5. Office of Director 84/02/17 4pp 22517 149 24X Fiche 50-323,84/02/17.8403040207
- B401190072 IE Info Notice B4-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annonciation " Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B300103) B4/02/2B Consolidated Edison Co of New Yorks Inc 115pp 22709 239 24X fiche 50-000.84/02/2B, B401190072
- B403060131 Forwards IE Insp Repts 50-275/83-37 & 50-323/83-25 on 831114-18 & 1128-1209 BISHOP,T W Division of Resident, Reactor Project & Engineering Programs B4/02/29 SCHUYLER,J D Pacific Gas & Electric Co 201 22306
- --8403060143 Natice of violation from insp on 831114-18 & 1128-1209 CANTER.H L Region 5. Office of Director 84/02/29 2pp 22506 275 24X Fiche 50-275.84/02/29.8403060131
- --8403060149 IE Insp Repts 50-275/83-37 & 50-323/83-25 on 831114-18 & 1128-1209 Noncompliance noted failure to assure that welding inspectors qualified & certified per procedural requirements
 HERNANDEZ.O # , ROSS.T M , KIRBCH.D F Region 5. Office of Director 84/02/29 49pp 22504 277 24X Fiche 50-275.84/02/29, 8403060131
- 8402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list enci GRACE, J N Division of GA: Gafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York. Inc 130pp 22552 329 24X Fiche 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JDRDANLE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02,8402090008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases" 5vc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc. 117pp 22553 217 24X Fiche 50-000.84/03/02,8402070007
- B402090011 IE Info Notice B4-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp "Eve list enci JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4703705 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50~000.84/03/05. B40209001i
- 8402090022 Board Notification 84-043 submits info re stams & measurements by Parameter, Inc of radiographs & field welds & delta ferrite measurements of selected welds under Contract NRC-05-82-249
 EISENHUT, D 0 Division of Licensing NRC-05-82-249 84/03/05 PALLADINO, GILINSKY, ROBERTS Commissioners 3pp 22556 247 24X Fichs 50-275,84/03/05,8402090022
- --8403080193 Forwards "Project Quality Plan for Providing Assistance & Sves to Support NRC/IE Region IV Personnel in NDE & Review of Radlographs," per Task Order 55 of Contract NRC-05-82-249

 LOFY.R A Parameter, Inc. NRC-05-82-249 83/11/23 KIRSCH, D Region 5, Office of Director 1p 22556 250 24X

 Fiche 50-275,84/03/05,8402090022
- --8403080197 "Project Quality Pien for Providing Assistance & Svcs to Support NRC/IE Region IV Personnel in NDE & Review of Radingraphs at Diable Cangon.Units 1 & 2 "FDLEY,H J. LOFY,R A Parameter, Inc NRC-05-82-247 PQP-124 BJ/11/22 NRC No Detailed Affiliation Given 25pp 22556 251 24% Fichs 50-275,84/03/05.8402090022

- B402090024 IE Info Notice B4-09, Rev 1, "Lessons Learned From Insps of Fire Protection Bafe Shutdown Bys " Bvc list encl URBAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24x Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PHR Bys " Byc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolldated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- B402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYQUNO.R C Director's Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- B402090043 IE Info Notice B4-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JURDAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/21 Consolidated Edison Co of New York, Inc 123pp. 22823 229 24X Fiche 50-000,84/03/21.8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Bafety-Releted Sys " Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402079044
- 8403140244 Board Notification 84-066 forwards SECY-84-104 re NRC insp of Nuclear Sycs Corp audit of Pullman Power Products at site, including draft IE Imsp Rept 50-275/83-37 & 840229 final rept EISENHUT.D O Division of Licensing 84/03/28 BUCK.J H , MODRE.T 8 , JOHNSON.W R Atomic Bafety and Licensing Appeal Penel. 3pp 22947 070 24% Fiche 50-275/84/03/28/8403140244
- --8403200301 Provides info to Commissioners re circumstences surrounding documentation of NRC insp of 1977 Nuclear Svcs Corp audit of Pullman Power Products Co DIRCKS.W J Office of the Executive Director for Operations 84
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for DL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 BIRCKS.W J Office of the Executive Director for Operations.
 84/02/21 PALLADINO Commissioners 9pp 22492.083 24X Fiche 50-000.84/02/21.8403020443
- 8403230139 Forwards "Environ Investigations et Diablo Cengon,1982." MARRICK.J W. Pacific Gas & Electric Co. 84/02/28. Record Services Branch (Document Control Desk). 1p. 22732-341, 24X Fiche 50-275.84/02/28.8403230139
- --8403230141 "Environ Investigations at Diable Cenyon,1982 "
 CAYOTAR F. BEHRENS,D W Pacific Gas & Electric Co 83/06/30
 760pp 22732 342 24X Fiche: 50-275,84/02/28,8403230139
- S Reporteble occurrences, LERs & related correspondence
- 8403260233 Forwards summary list of deficiencies identified per iOCFR50 55(e).Part 21 & potential generic ltr repts for comments
 STARGSTECKI.R Division of Project & Resident Programs 84/02/28, Region i. Office of Director 7pp 22756:065 24X
 Fiche 50-000.84/02/28.8403260233
- 8403150048 Final deficiency rept re melfunction of valve operator mfg by Limitorque Initially reported on 830627 Existing screws will be replaced on affected valves prior to fuel load, Meint procedures modified BCMUYLER.J D Pacific Gas & Electric Co 84/03/01 MARTIN, J B. Region 5. Office of Director. 1p 22641 014 24X Fiche 50~323,84/03/01.8403150048
- B403080405 Further response to FOIA request for documents re BER related to operation of facilities Forwards App B documents. App A & B documents available in PDR Review of remaining documents subj to request in progress FELTON, J M Division of Rules and Records 84/03/02 QARDE, B P Government Accountability Project 4pp 22583:073 24X Fiche.50-275,84/03/02,8403080405

- --B4030B042i Requests assistance in addressing improper design activities re use of U-bolts & code break (code boundary) design.per affidavit re allegations
 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs B3/11/29 EISENHUT.D O Division of Licensing image 22883 093 24% Fiche 50-275.64/03/02.84030B0405
- 8403130121 PNO-V-84-013 on 840307. Bechtel laborer suffered heart attack while working in auxiliary bldg Medical attention provided to individual at site Individual pronounced dead upon arrival at Sierra Vista Hosp DOUDB.R T Region 5. Office of Director 84/03/07 ip 22640 218 24X Ficha 30-275,84/03/07.8403150121

T. Hearing transcripts on non-antitrust matters

- E402070032 Board Notification E4-04B forwards transcript of E40125 aseting re allegations concerning small bore piping Review & swaluation of allegations continuing EIBENHUT.D G Division of Licensing 84/03/13 PALLADING, OILINSKY, ROBERTH Commissioners 3pp 67217 046. 24x Fiche 50-275,84/03/13,8402070032
- --8403150136 Forwards transcript of 840125 meeting re allegations concerning small bore piping Info excised to protect confidentiality of NRC sources & preclude compromising angoing insps
 BISHOP,T W Region 5, Office of Director 84/02/23
 BTRUMHABSER,M California, State of ip 22645 004 24X
 Fiche 50-278,84/03/13,8402090032
- --B403150144 Forwards transcript of 840125 meeting re allegations concerning small bore piping Info excised to protect confidentiality of NRC sources & preclude compromising ongoing insps
 BISHOP.T W Region 5. Office of Director 84/02/23 REYNOLDS, J Center for Law in the Public Interest 1p 22645 005 24% Fiche 50-275, B4/03/13, B402090032
- ---B403130132 Forwards transcript of B40125 meeting re allegations concerning small bore piping Info excised to protect confidentiality of NRC sources & preclude compromising ongoing insps
 BISHOP, T W Region 5, Office of Director, 84/02/23 CRANE, P A Pacific Gas & Electric Co ip 22645 006 24X
 Fiche 50-275,84/03/13,8402090032
- --8403150157 Forwards transcript of 840125 meeting re allegations concerning small bore piping Info excised to protect confidentiality of NRC sources & preclude compromising ongoing insp.
 816HOP, T W Region 5, Office of Director 84/02/23 NORTON Norton, Burke, Berry & French 1p 22645 007 24X Fichs. 50-275,84/03/13,8402090032
- --8403150162 Excised transcript of 840125 closed meeting w/C Stokes re allegations concerning small bore piping Pp 1-220 # NRC - No Detailed Affiliation Olven 84/01/25 319pp 22645 008 24X Fiche 50-275,84/03/18,8402090032

U. Congressional/Executive Correspondence

- 8403260106 Provides current status of facility licensing process in response to 840126 ltm. Since 840124 hearings. NRC has continued investigation, insp & evaluation of allegations, which will be resolved prior to low power authorization. DENTON, H R Dffice of Nuclear Reactor Regulation. Director 84/03/09 MCCARTHY, L T California, Btate of 4pp. 22761 356 24X Fiche 50-275,84/03/09,8403260106.
- --8403260111 Expresses concern re possibility that facility will be licensed w/o meeting sefety stds MCGARTHY,L T. California, Statz of 84/01/26 PALLADING,N Commissioners ip 22761 357 24X Fiche. 50-275,84/03/09, 8403260106
- B403270367 Telecopy itr expressing concerns re lifting of suspended low power license. Commission should carefully weigh ABLAB conclusions & fulfill responsibility to require safe plant operation.
 THOMAG.W M. House of Rep. DSB 143, 84/03/26 PALLADINO, N Commissioners, 2pp 22789,002 24X Fiche 50-275,84/03/26,8403270367.

V. Operator Examinations

8403220035 Forwards tables providing detailed operating experience for licensed operating personnel & licensed & nonlicensed shift technical advisors SCHUYLER, J.O. Pacific Oas & Electric Co 84/03/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 22718 208, 24X Fiche; 50-275, 84/03/16, 8403220035

8403260176 Informs of plans to have shift advisors w/qualifications & training recommended by Near-Term DL Util Group on staff prior to exceeding 5% power Advisors will be subj to final exam following training SCHUYLER. J D Pacific Gas & Electric Co 84/03/23 KNIOHTON, O W Licensing Branch 3 Ip 22738 234 24% Fiche 50-275, 84/03/23, 8403260176

DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

- 8403060567 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per B10709 Generic Ltr Bi-27 W/o request.sntire plan will be placed in PDR VASBALLO.D B Operating Reactors Branch 2 84/02/10 UTLEY.E E Carolina Power & Light Co 2pp 22552 263 24X Fiche 50-324.84/02/10.8403060567
- B403020118 Summary of 840202 meeting w/util in Bethesda, MD re exemptions from 10CFR50. App R requirements & plans concerning atternate shutdown capability to constitute acceptable level of fire protection MACKAY. B Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 3pp 22491 174 24X Fiche 50-324, 84/02/21.
- 8403020159 Notification of 840315 meeting w/util in Bethesda.MD to discuss progress rept on fire protection, alternate shutdown sys.iOCFR.App R exemptions & overall completion schedule MACKAY.S D Operating Reactors Branch 2 84/02/22 VASSALLO,D B Operating Reactors Branch 2 2pp 22471 141 24X Fiche 50-324.84/02/22,8403020159
- 8403090066 Forwards order confirming licenses commitments re emergency response capability Order based on 830415 % 1014 responses committing to specified action W/o encl VASSALLO, D B Operating Reactors Branch 2 84/02/22 UTLEY, E E Carolina Power & Light Co ip 22575 353 24X Fiche: 50-324, 84/02/22, 8403090066
- 8403i40236 Forwards order confirming licensee commitments on Emergency response capability VASSALLO.D B Operating Reactors Branch 2 84/02/22 UTLEY, E E Carolina Power & Light Co 2pp 22636 353 24% Fiche 50~324.84/02/22,8403i40236
- --8403140239 Order confirming licensee commitment on emergency response capability per Generic Ltr 82-33 (Suppl i to NUREG-0737) EIBENNUT.D Q Division of Licensing 84/02/22 Carolina Power & Light Co Spp 22636 355 24X Fiche 50-324.84/02/22.
- 8403060140 Forwards payment of Class III & Class I amend fees for 821213 & 830502 applications re radiological effluent Tech Specs & App R exemption requests, respectively CUTTER, A B Carolina Power & Light Co 84/02/29 MILLER, W O License Fee Management Branch ip 22513 349 24X Fiche: 50-324, 84/02/29, 8403060140
- B4032600B9 Summary of B40216 meeting w/util in Bethesda.MD re util progress on alternate shuddown capability assessment & mods required by 10CFR50.App R Agenda encl MACKAY.B Operating Reactors Branch 2 84/03/01 Operating Reactors Branch 2 84/03/01 B4032608B9 22763 228 24X Fiche 50-324,84/03/01.
- 8403160283 Advises of 840316 meeting in Region II ofc to discuss App R requirements & results of recent App R insps Attendance should be limited to six util amployees LEWIE.R C Division of Project & Resident Programs 84/03/02 UTLEV.E E Carolina Power & Light Co 1p 22660 107 24X Fiche 50-000,84/03/02,8403160283
- 8403290086 Forwards IE Insp Repts 50-324/84-04 & 50-325/84-04 on 840115-0215 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/03/07 UTLEY.E E Carolina Power & Light Co 2pp 22806 328 24X Fiche 50-324.84/03/07.8403290086
- --8403270092 IE Insp Repts 50-324/84-04 & 50-325/84-04 on 840115-0215 No violations or deviations identified Major areas inspected: surveillance:maintroperational safety verification. EBF Eye walkdown, in-office LER reviews & fire protection MYERG, D D: OARNER, L W: PATTERSON, C: Region 2, Office of Director 84/03/06 lipp 22806 330 24X Fiche 50-324,84/03/07,8403290086

- 8403200033 Rav 13 to emergency response plan, Vol XIII, Book 1 M/840315 transmittal form BUYER, L Carolina Power & Light Co 84/03/14 18pp 22685 167 24X Fiche 50-324,84/03/14,8403200033
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8402270263 Responds to FOIA request for JC Mark 801204 memo to ACRB re hydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards App A documents App B documents in PDR FELTON, J M Division of Rules and Records 84/01/30 HIATT, B L Ohio Citizens for Responsible Energy 7pp 22412 051 24X Fiche 50-000.84/01/30.8402270263
- --B402270314 Forwards summary of investigations re hydrogen recombiners & relay failures in HPC1 sys
 ZUKOR.D J ACRS Advisory Committee on Reactor Bafeguards
 BO/10/30 MDELLER.D W ACRS Advisory Committee on Reactor
 Safeguards 4pp 22412 OBA 24X Fiche 50-000.84/01/30.
- P Operating license stage documents & correspondence
- 8403060053 Forwards corrected Tech Spec Pages 3/4 3-42 & 3/4 6-2 to Amend 59 to License DPR-71 & Amends 65 & 91 to Licenses DPR-71 & DPR-62, respectively VASSALLO, D & Operating Reactors Branch 2 84/02/10 UTLEY, E E Carolina Power & Light Co 2pp 22528 305 24X Fiche 50-324.84/02/10, 8403060053
- --8403060056 Corrected Tach Spec Pages 3/4 3-42 & 3/4 6-2 to Amend 59 to License DPR-71 & Amends 65 & 91 to Licenses DPR-71 & DPR-62, respectively **NRC No Detailed Affillation Given 84/02/10 3pp 22528 307 24% Fiche 50-324,84/02/10 8403060053
- 8403060067 Forwards request for add1 info re util 820907 request for ifcense amend to reflect miscellaneous Tech Spec revs Response requested within 60 days of 1tr receipt VASSALLO,D B Operating Reactors Branch 2 84/02/10 UTLEY,E E Carolina Power & Light Co 4pp 22528 299 24X Fichs 50-324.84/02/10.8403060067
- 8403060069 Forwards request for add1 info re inservice testing of pumps & valves, in order to complete review of 831012 submittal Response requested within 45 days of 1tr receipt VASSALLO,D B Operating Reactors Branch 2 84/02/10 UTLEY,E E Carolina Power & Light Co 3pp 22528 296 24X Fiche 50-324,84/02/10,8403060069
- 840:305:0073 Forwards request for add1 info re util 83:12: request for approval to dispose of waste lubricating oils containing trace amounts of licensed radioactive matl by onsite combustion Response requested within 60 days VASSALLO. B Operating Reactors Branch 2 84/02/15 UTLEY.E E Carqiina Power & Light Co 3pp 22528 273 24X Fische 30-324.84/02/15.8403060073
- 8403140340 Summary of 831215 meeting w/GE & Mark I Owners Group in Bethesda.HD re Mark I containment wetweil-drywell vacuum breaker design methodology SIEGEL.B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fiche 50-000,84/02/21, 8403140340
- 8403150124 Summary of 840202 meeting w/wti), INEL, Bechtel & Southern Svcs Co in Bethesda, MD re equipment environ qualifications Proposed schedule for implementation will be submitted by 840322 Agenda & attendance list encl GROTENHUIS, M Operating Reactors Branch 2 84/02/22 Operating Reactors Branch 2 5pp 22646 354 24x Fiche 50-324, 84/02/22, 8403150124
- 8403060300 Application for amend to Licenses DPR-71 & DPR-62, revising Tech Spec 4 i 2 s to clarify when reactivity anomaly surveillance performed Revs supplement & supersede changes in 831229 ltr
 HOME: P W Carolina Power & Light Co 84/02/28 VASBALLO.D B Operating Reactors Branch 2 Jpp 22516 001 24%
 Fiche 50-324,84/02/28.8403060300
- --8403060302 Proposed changes to Tech Spec 4 i 2 a to clarify when reactivity anomaly surveillance performed = Carolina Power & Light Co 84/02/28 2pp 22516 004 24X Fiche 50-324,64/02/28,8403060300

- 8403070137 Application supplementing 820316,830623 & 0906 requests for amend to Licenses DPR-62 & DPR-71, consisting of Tech Spec changes for Item 9 re isolation of HPCI & RCIC mod (NUREQ-0737, Action Item II K 3 15) & Generic Ltr 83-02 HOME.P W Carolina Powor & Light Co 84/02/28 VASSALLO.D B Operating Reactors Branch 2 2pp 22538 316 24X Fichs 50-324,84/02/28,8403070157
- --8403070162 Proposed Tach Spec changes for Item 9 re isolation of HPC1 & RCIC mod (NUREG-0737, Action Item II K 3 15) & Generic Ltr 83-02
 -- Carolina Power & Light Co 84/02/28 31pp 22538 318, 24% Fiche 50-324,84/02/28,8403070157
- B403060140 Forwards payment of Ciess III & Class I amend fees for 821213 & 830302 applications re-radiological effluent Tech 8pecs & App R exemption requests respectively CUTTER.A B Carolina Power & Light Co 84/02/29 MILLER.W O, License Fee Management Branch 1p 22513 349 24X Fiche 80-324,84/02/29,8403060140
- 8403040167 Advises that NUREO-0737. Action Items II K 3 30 & II K 3. 31 considered complete, based on 840104 telcon between NRC & GE Licensee need only identify to NRC ref on docket to GE Topical Rept NEDO-20566 or NEDO-20566P ZIMMERMAN, B R Carolina Power & Light Co 84/02/29 VABBALLO, D. E. Operating Reactors Branch 2 2pp 22518 334. 24X Fiche 50-324,84/02/29,8403060167
- 8403060276 Forwards POBI-BEAL Intl.Inc. "LOCA & Beismic Analysis. Brunswick Steam Electric Plant," to demonstrate valve operability. (n respanse to NRC 831201 request HOME.P W Carolina Power & Light Co 84/02/27 VARGA, 8 A Operating Reactors Branch i 5pp 22512 001 24X Fiche 80-324,84/02/27,8403060276
- --8403060304 "LDCA & Seismic Analysis Brunswick Steam Electric Plant" * Posi-Beal Valves International 3R5R58L-001 84/02/15, 470pp 22512 006 24X Fiche 50-324,84/02/27,8403060276
- B403140287 Forwards evaluation of revised operator requalifications program Rev meets requirements specified in 10CFR50 55.App A & acceptable VABSALLO.D B Operating Reactors Branch 2 84/02/29 UTLEY.E E Caralina Power & Light Co 3pp 22635 360 24X Fiche 50-324.84/02/29.8403140287
- 8403090252 Application to amend Licenses DPR-71 & DPR-62, revising Tech Spaces re accident monitoring instrumentation per NUREQ-0737 & Generic Ltr 83-36 HDME, P W Carolina Power & Light Co 84/03/02 VASSALLO, D B Operating Reactors Branch 2 7pp 28371 172 24X Fiche, 50-324, 84/03/02, 8403070252.
- --8403090240 Proposed Tech Specs re limiting conditions for operation & surveillance requirements for accident monitoring instrumentation per NUREG-0737 & Generic Ltr 83-36 * Carolina Power & Light Co 84/03/02 21pp 22571 199 24% Fiche 30-324,84/03/02,8403090252
- B4032i006i Forwards response to 840202 request for addl info re NUREG-0737. Items II F 1 4, "Containment Pressure Monitor Bys." II F 1 5. "Containment Mater Level Monitor Bys." & II F 1 5. "Containment Hydrogen Monitor Bys." & TIMMERNAN, S R Carolina Power & Light Co. 84/03/07 VASBALLO, D, B Operating Reactors Branch 2 20pp 22705 001 24% Fiche 50-324,84/03/09,8403210061
- B400210129 Responds to B40202 request re TMi Action Item II, K 3 1B concerning automatic depressurization sys (ADB) logic mods. High drywell pressure permissive eliminated & manual inhibit switches to ADS logic added HOME.P W Carolina Power & Light Co 84/03/09 VABBALLO.D.B Operating Reactors Branch 2 ip 22707 235 24X Fiche 50-324.84/03/09.8403210129
- B403:50275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pips replacement at BWRs 8vc list encl EIBENHUT.D 0 Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 334 24X Fichs 50-000:84/03/14.8403150275
- 8403300254 Notification of 840321 meeting w/util in Bethesda,MD to discuss status of battery review study OROTENHUIS,M Operating Reactors Branch 2 84/03/14 VASEALLO,D & Operating Reactors Dranch 2 1p 22844 352 24X Fiche 50-324,84/03/14,8403300254

- 8403210075 Forwards add1 info re BHR steady-state analysis methods, per NRC 840117 request Answers provided to 12 of 15 questions raised by NRC GE uill provide input to Guestions 4.8 % 13 Add1 responses uill be submitted by 840521
 ZIMMERMAN,S R Carolina Power & Light Co 84/03/15 VASSALLO,D 8 Uperating Reactors Branch 2 2pp 22705 122 24X
 Fiche 50-324,84/03/15,8403210075
- --8403210080 Amend 1 to "Verification of Carolina Power & Light Ref BWR
 Thermal-Hydraulic Methods Using FIBHR Code "
 KUNITA,R X Carolina Power & Light Ca NF-1583 04-1 A01
 84/03/31 41pp 22705 124 24% Fiche 50-324,84/03/15
- B403300299 Notifies that Class III & Class I fees for review of B30929 application re feedwater & main turbine trip/bypass sysbeing refunded due to withdrawai of application MILLER.W O License Fee Management Branch B4/03/15 JONES.J A Carolina Power & Light Co 2pp R2B44 309 24X Fiche 50-324.84/03/15.8403300299
- 8403290083 Responds to 840221 request for add1 info re control of heavy loads Initial load testing performed for head strongback, dryer separator sling & spent fuel cask yoke ZIMMERMAN, B R Carolina Power & Light Co 84/03/20 VABSALLO, D B Operating Reactors Branch 2 2pp 22806 325 24X Fiche. 50-324, 84/03/20, 8403270083
- Q Inspection reports, IE Bulletins & correspondence
- 8403070307 Forwards IE Insp Repts 50-324/83-42 & 50-325/83-42 on 831215-840115 No violations or deviations noted VERRELLI,D M Division of Project & Resident Programs 84/02/06 UTLEY,E E Carolina Power & Light Co 2pp 22846 175 24X Fiche 50-324,84/02/06,8403070307
- --8403070310 IE Insp Repts 50-324/83-42 & 50-325/83-42 on 83 1215-840115 No violations or deviations noted Major areas inspected surveillance.maint, operational safety verification, ESF sys waikdown, LEF review, independent insp & plant transients MYERB, D D . QARNER, L W. Region 2. Office of Director BEMIS, P R Division of Project & Resident Programs 84/02/03 Bpp 22546 177 24X Fiche 50-324,84/02/06,8403070307
- B403140291 Forwards request for add1 info on IE Builetin B0-li re masonry wall design Response requested in 60 days VABBALLO.D B Operating Reactors Branch 2 84/02/21 UTLEY.E E Carolina Power & Light Co 13pp 22635 336 24X Fiche 50-324.84/02/21.8403140291
- 8403070200 Informs that start date for mid-cycle insp in response to NRC concerns re intergranular stress corrosion cracking should be changed to 841102 HOWE.P.W Carolina Power & Light Co 84/02/27 DENTON.H R Office of Nuclear Reactor Regulation. Director ip 22538 353 24X Fiche.50-324.84/02/27,8403070200
- 84Dii90072 IE Info Notice 84-i3, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl.

 JORDAN, E L. Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 113pp 22707 237 24X Fiche. 50-000.84/02/28.8401170072
- B402090007 IE lnfo Notice B4-i4, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl QRACE, N Division of QA, Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-i6, "Failure of Automatic Sprinkler Bys Valves to Operate," Syc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp. 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Byc list encl
 JORDANIE L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp. 22553 217 24X Fiche 50-000,84/03/02.8402090009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24% Fiche 50-000,84/03/05,8402070011
- 8402070024 IE Info Notice 84-09, Rev i, "Leasons Learned From Insps of Fire Protection Bafe Shutdown Bys" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/07 Consolidated Edison Co of New York, Inc 118pp 28635 049 24X Fiche 50-000,84/03/07,8402090024

- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Svc list encl JORDAN, E. Division of Emergency Preparedness" & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403290086 Forwards IE Insp Repts 50-324/84-04 & 50-325/84-04 on 840i15-0215 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/03/07 UTLEY, E E Carolina Power & Light Co 2pp 22806 328 24X Fiche 50-324,84/03/07,8403290086
- --8403290092 iE Insp Repts 50-324/84-04 & 50-325/84-04 on 840115-0215 No violations or deviations identified Major areas inspected surveillance, maintroperational safety verification, EBF sys walkdown, in-office LER reviews & fire protection MYER9.D O , GARNER,L W , PATTERSON,C Region 2, Office of Director 84/03/06 ilpp 22806 330 24X Fiche 50-324,84/03/07,8403290086
- 840209003i IE Bulletin 84-02, "Failures of QE Tupe HFA Relays in Use in Class IE Safety Sys " Syc list enci DEYOUNG.R C Director's Office. Office of inspection and Enforcement B4/03/12 Consolidated Edison Co of New York. Inc 134pp 22823 074 24X Fiche 50-000.84/03/12.8402070031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 iE Inf. Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000.84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403130333 Henthiy operating repts for Feb 1984 W/840305 ltr HARRISON,F , DIETZ.C R Carolina Power & Light Co 84/02/29 DEYDUNG,R C Director's Office, Office of Inspection and Enforcement 18pp 22614 197 24X Fiche 50-324.84/02/29, 8403130333
- S Reportable occurrences, LERs & related correspondence
- 8305060337 Forwards technical rept "Air in Reactor Water Cleanup Sys Instrument Sensing Lines," detailing 821216 transmitter maifunction Engineering evaluation should be performed 8ALAH,8 Reactor Operations Analysis Branch 83/04/25 8EYFRIT.H V Reactor Operations Analysis Branch 1p 22789 304 24X Fiche 50-324,83/04/25,8305060337
- --8305060342 "Air in Reactor Water Cleanup Sys instrument Sensing Lines." describing 821216 transmitter maifunction
 * Reactor Operations Analysis Branch 83/04/25 4pp 22789 305 24X Fiche 50-324,83/04/25,835060337
- B4030i0i35 Updated LER 80-ii3/03L-i on B012li,primary containment atmospheric control inerting inlet isolation vaive 2-CAC-V48 discovered w/dual open-ciose position indication Caused by defective limit switch W/840222 ltr
 ALLEN.M. T., DIETZ. C.R. Carolina Power & Light Co. B4/02/22 D'REILLY, J.P. Region 2, Office of Director 3pp. 22436 00i 24X Fiche 50-324,84/02/22.84030i0135
- 8403010299 Updated LER 82-123/03L-4 on 821010, loss of 4, ido-voit smergency bus E-3 occurred Caused by startup output & dissel generator output breakers failing to close when unit auxiliary transformer opened W/840222 ltr POULK, R M , DIETZ, C R Carolina Power & Light Co 84/02/22 O'REILLY, J P Region 2, Office of Director 4pp 22432 ii3 24X Fichs 30-324,84/02/22,8403010299
- 8403090235 RO 2-83-1 on 840124,ECCS actuation instrument E41-L8-NOO3 found inoperable Caused by instrument venting line problem investigation & evaluation incomplate Next rept will be submitted by 840316
 DIETZ, C R Carolina Power & Light Co 84/02/22 O'REILLY, J P Region 2. Office of Director ip 22572 292 24X
 Fiche 50-324,84/02/22.8403090235
- B403010395 RO 2-5R-84-3 on 840110.Co-60 concentration in bottom sediment sample exceeded Tech Spec limit Surface water samples in intake & discharge canals & ocean showed no Co-60 activity Sample frequency increased DIET7.C R Carolina Power & Light Co 84/02/24 O'REILLY.J P Region 2. Office of Director 2pp 22434 048 24x Fiche 50-324.84/02/24.8403010393

- 8403070023 RO 2-84-2 on 840127, while placing equipment clearance on emergency diesel generator 4. emergency ac bus E-4 inadvertently rendered inoperable Review of event incomplete Next rept uill be submitted by 840307 DIETZ.C R Carolina Fower & Light Co 84/02/28 O'REILLY, J P Region 2. Office of Director 10 22575 355 24X Fiche 50-324, 84/02/28. 8403070023
- 840313030i Follows, RD 2-SR-B4-2 in Sept 1982.Co-60 detected in battom sediments collected in stilling basin Increase in redicactivity probably caused by increased releases of Co-60 due to general decontamination effort DIETZ.C R Carolina Power & Light Co 84/02/29 B'REILLY, J P Region 2. Office of Director 9pp 22608 047 24X Fiche 50-324.84/02/29.840313030i
- 8403130152 LER 84-002-CO on 840129 diesel generator output breaker 125volt de normal control power breaker inadvertently deenergized Caused by auxiliary operator not adhering to procedures Breaker properly labeled W/840302 itr PASTVALM J. DIETZ.C.8. Carolina Power & Light Co. 84/03/02 0'REILLU.J.P. Region 2. Office of Director 4pp 22608 225 24X Fiche 50-324,84/03/02.8403130152
- 8403200324 Discusses failure of Battery 2A2 to pass required capacity test in Dec 1983 incident may lead to further changes in Tech Specs, procedure rev or mode of battery electrical sys LAINAS. G.C. Assistant Director for Operating Reactors 84/03/05 RUBENSTEIN.L.S. Division of Engineering 2pp 22709 146 24X Fichs 50-324.89703/05.8403200324
- 8403150179 Forwards updated LER 82-123/03L-4 DIETZ.C R Carolina Power & Light Co 84/03/07 O'REILLY, J P Region 2. Office of Director |p 22642 09D 24x Fiche 90-324.88/03/07.8403150179
- 8403150186 Forwards updated LER 80-113/03L-1 DIETZ.C R Carolina Power & Light Co 84/03/07 D'REILLY, J P Region 2. Office of Director 2pp 22642 285 24X Fiche 50-324,84/03/07,8403150186
- 8403130078 RD 2-84-01 re E41-LS-NO03 vent ilns problem investigation & evaluation completed & event determined not reportable per 1007R50 73
 DIETZ.C R Carolina Power & Light Co 84/03/09 O'REILLY, J P Region 2, Office of Director ip 22614 304 24X
 Fichs 50-324/84/03/09,8403130078
- 8403130406 Special Rept 2-SR-84-4 on 840204, fire barrier limiting conditions for operation initiated to permit repair of inoperable Fire Boor 108 Distortion of door upper hings prevented door from latching properly Boor returned to svc DIETZ.C R Cardina Power & Light Co 84/03/09 D'REILLY.J P Region 2, Office of Director 1p 22616 049 24% Fiche 50-324,84/03/09.8403130406
- 8403150090 NPDES noncompliance notification on 84022i, discovered one cooling water pump bay w/o screens Caused by regair work to damaged bearing on pump screen 2D & problems w/starting pump Outage scheduled for 840310 to replace gump FURR, B J Carolina Power & Light Co 84/03/12 WAKILD, C North Carolina, State of 1p 22640 361 24% Fiche 50-324,84/03/12,8403150090
- 8403210123 Updated LER 83-018/03L-1 on 830930, traverse in-core probe (TiP) detector C would not fully retract from core, rendering TIP C guide tube primary containment isolation ball valve inoperable Caused by damaged connector W/830314 ltr PASTVAM J. DIETI, C R Carolina Power & Light Co 84/03/14. D'REILLY, J P Region 2, Office of Director Rpp 22707 183 24x Fiche 50-324,84/03/14,8403210123
- 8403200273 LER 84-003-00 on 840214 normal power supply feeder emergency bus E-4 automatically opened due to bus undervoltage condition sensed by bus degraded voltage relay 27DV. Cause unknown W/B0315 ltr FASTVA. M J . DIETZ. C R Carolina Power & Light Co 84/03/15 3pp 22676 123 24X Fiche 50-324.84/03/15.8403200273
- 8403200207 Forwards preliminary findings of investigation re LER 2-83-95 Failurs to recognize or correct mechanical seal genetration fire rating deficiency & summary of deficiencies discussed DIETZ, C R Carolina Power & Light Co 84/03/16 Record Services Branch (Document Control Dest) App. 22700, 001 24X Fishe 50-324,84/03/16,8403200207
- 8403270266 LER 84-004-00 on 840222. while testing primary containment isolation sys of reactor low water level.logic channel NO254A-IMBIV 821-F028D closed-resulting in reactor scram Causes by ack dc solenoid valves deenergized W/840323 ltr PASTVA.M J. DIETZ.C R Carolina Power & Light CO 84/03/23 4pp 22772 023 24X Fiche 50-324.84/03/23,8403270266

- DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- B403060567 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licenses, per 810709 Generic Ltr Bi-27 M/o request, entire plan will be placed in PDR VASSALLO, D B Operating Reactors Branch 2 B4/02/10 UTLEY, E E Carolina Power & Light Co 2pp 22552 263 24X Fichs 50-324.84/02/10.8403060567
- 8403020118 Summary of 840202 meeting w/util in Bethesda, MD re exemptions from 10CFR30. App R requirements & plans cuncerning alternate shutdown capability to constitute acceptable level of fire protection MACKAY. 8 Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 3pp 22491 174 24X Fiche 30-324,84/02/21.
- 8403020159 Notification of 840315 meeting w/util in Bethesda, MD to discuss progress rept on fire protection alternate shutdown sys. 10CFR. App R exemptions & overall completion schedule MACKAY. S D Operating Reactors Branch 2 84/02/22 VASSALLO. D B Operating Reactors Branch 2 2pp 22491 i41 24X Fiche 50-324.84/02/22,8403020159
- 8403090066 Forwards order confirming licenses commitments re emergency response capability Order based on 830415 & 1014 responses committing to specified action W/o encl VASSALLO D B Operating Reactors Branch 2 84/02/22 UTLEY, E Carolina Power & Light Co ip 22575 353 24X Fiche 50-324,84/02/22,8403090066
- 8403140236 Forwards order confirming licensee commitments on emergency response capability
 VASBALLO,D B Operating Reactors Branch 2 84/02/22 UTLEY, E E Carolina Power & Light Co 2pp 22636 353 24X
 Fiche 50-324,84/02/22,8403140236
- --8403140239 Order confirming licensee commitment on emergency response capability per Generic Ltr 82-33 (Suppl i to NUREC-0737) EISENHUT.D G Division of Licensing 84/02/22 Carolina Power & Light Co 5pp 22434 355 24X Fiche 50-324,84/02/22,8403140234
- 8403060140 Forwards payment of Class III & Class I amend fees for 821213 & 830502 applications re radiological effluent Tech Specs & App R exemption requests respectively CUTTER A B Carolina Power & Light Co 84/02/29 MILLER, W D. License Fee Management Branch 19 22513 349 24X Fiche 50-324.84/02/29,8403040140
- 8403260089 Summary of 840216 meeting w/util in Bethesda, MD re util progress on aiternate shutdown capability assessment & mods required by 10CFR50. App R Agenda encl MACKAY. S Operating Reactors Branch 2 84/03/01 Operating Reactors Branch 2 4pp 22763 228 24X Fiche 50-324.84/03/01.8403240889
- B4031602B3 Advises of B40316 meeting in Region II ofc to discuss App R requirements & results of recent App R insps Attendance should be limited to six util employees LEHIS.R C Division of Project & Resident Programs B4/03/02 UTLEY.E E Carolina Power & Light Co ip 22660 109 24X Fiche 50-000.84/03/02,84031602B3
- B403270086 Forwards IE insp Repts 50-324/84-04 & 50-325/84-04 on 840115-0215 No violations or deviations identified VERRELLI, D M Division of Project & Resident Programs 84/03/07 UTLEY, E Carolina Power & Light Co 2pp 22806-328 24X Fiche 50-324,84/03/07,8403270086
- --8403290092 IE Insp Repts 50-324/84-04 & 50-325/84-04 on 840115-0215 No violations or deviations identified Major areas inspected, surveillance, maint, operational safety verification, ESF syswalkdown, in-office LER reviews & fire protection, MYERS.D O Ragion 2. Office of Director BEMIS,P R Division of Project & Resident Programs 84/03/06 iipp 22806:330 24x Fiche 50-324,84/03/07,840329086
- 8403200033 Rev 13 to emergency response plan. Vol XIII, Book 1 W/840315 transmittal form BOYER. L Carolina Power & Light Co 84/03/14 18pp 22685: 167. 24X Fiche 50-324.84/03/14,8403200033

- D. Advisory Committee on Reactor Safeguards reports & correspondence
- 8402270263 Responds to FDIA request for JC Hark 801204 memo to ACRS re hydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards App A documents App B documents in PDR FELTON-J M Division of Rules and Records 84/01/30 HIATT, S L Dhio Citizens for Responsible Energy 7pp 22412 051 24X Fichs 50-000,84/01/30,8402270263
- --8402270314 Forwards summery of investigations of hydrogen recombiners & relay failures in HPCI sys
 ZUKOR, D. J. ACRE Advisory Committee on Reactor Safeguards
 80/10/30 MDELLER, D.W. ACRE Advisory Committee on Reactor
 82428904748 4PP 22412 086 24X Fiche 50-000,84/01/30,
 8402270263
- P. Operating license stage documents & correspondence
- 8403230049 Application for emend to License DPR~71, changing Tech Spec description of reactor core fuel assemblies. HDME, P. H Carolina Power & Light Co 84/01/31 VASSALLO, D B, Operating Reactors Branch 2 2pp 22724 348 24X Fiche: 50-325,84/01/31,8403230049
- --8403230054 Proposed Tech Spec change re description of reactor core fuel assemblies e Carolina Power & Light Co. 84/01/31, 3pp. 22724,350 24X Fiche:50-325,84/01/31,8403230049
- 8403060053 Forwards corrected Tech Spec Pages 3/4 3-42 & 3/4 6-2 to Amend 59 to Licenses DPR-71 & Amends 65 & 91 to Licenses DPR-61 & DPR-62, respectively YASSALLO, D B Operating Reactors Branch 2. 84/02/10 UTLEY, E Caroline Power & Light Co 2pp. 22528 305 24% Fiche. 50-324, 84/02/10, 8403060053
- --8403060056 Corrected Tech Spec Pages 3/4 3-42 & 3/4 6-2 to Amend 59 to License DPR-71 & Amends 65 & 91 to Licenses DPR-71 & DPR-62, respectively * NRC No Detailed Affiliation Given. 84/02/10 3pp 22528:307 24X Fiche 50-324.84/02/10.8403060053
- 8403060067 Forwards request for addl info re util 820907 request for lissues amend to reflect miscellaneous Tech 8pec revs Response requested within 60 days of itr receipt VASSALLO, D. B. Operating Reactors Branch 2 84/02/10 UTLEY, E. Caroline Power & Light Co. 4pp. 22528 297. 24X Fische 30-324,84/02/10,8403060067
- 8403060069 Forwards request for add1 info re inservice testing of pumps & valves:in order to complete review of 831012 submittal Response requested within 45 days of ltr receipt.

 VASSALLO,D B Operating Reactors Branch 2 84/02/10 UTLEY,E E Capolina Power & Light Co. 3pp 22528.296 24% Fiche: 50-324,84/02/10,8403060069
- B403040073 Forwards request for add1 info re util B31121 request for approval to dispose of wasta lubricating oils containing trace amounts of licensed radioactive metl by onsite combustion Response requested within 60 days.

 VASSALLO,D B Operating Reactors Branch 2 B4/02/15 UTLEY,E E. Carolina Power & Light Co. 3pp 22528:293 24X

 Fiche, 50-324, 84/02/15, 8403040073.
- 8403140340 Summary of 831215 meeting w/GE & Merk I Owners Group in Bathesda.HD re Mark I containment wetwell-dryweil vacuum breaker design methodology. BIEOEL. B. L. Opereting Reactors Branch 2 84/02/21 Operating Reactors Branch 2, 51pp 22635,178 24X Fiche: 50-000,84/02/21, 8403140340
- 8403150124 Summary of 84020R meeting w/util, INEL, Bechtel & Bouthern Bycs Co in Bethesda, MD re equipment environ qualifications Proposed schedule for implementation will be submitted by 840322. Agenda & attendance list encl. GROTENHUIS, M Operating Reactors Branch 2 84/02/22 Operating Reactors Branch 2, 5pp. 22646,354 24X Fiche 50-324,84/02/22, 8403150124.
- 8403060300 Application for amend to Licenses DPR-71 & DPR-62, revising Tech Spec 4 1 2 a to clarify when reactivity anomaly surveillance performed Revs supplement & supersede changes in 831229 itr.

 HOWE, P. W. Carolina Power & Light Co. 84/02/28 VASSALLO, D.B. Operating Reactors Branch 2, 3pp 22514 001 24X Fiche, 50-324, 84/02/28, 8403040300
- ---B403060302 Proposed changes to Tech Spec 4 1,2 a to clarify when practivity anomaly surveillance performed * Carolina Power & Light Co. 84/02/20 2pp. 22516.004 24X Fiche: 30-324,84/02/20,8403060300.

- --8403070162 Proposed Tach Spec changes for Item 9 re isolation of HPCI & RCIC mod (NUREQ-0737. Action Item II K 3 15) & Ganeric Ltr 83-02 * Cerolina Power & Light Co 84/02/28 31pp 22538 318 24X Fiche 50-324.84/02/28.8403070157
- 8403060140 Forwards payment of Class III & Class I amend fees for 821213 & 830502 applications re radiological effluent Tech Specs & App R szemption requests: respectively CUTTER.A B Carolina Power & Light Co 84/02/29 MILLER.W O License Fee Management Branch 1p 22513 349 24X Fiche; 50-324.84/02/29, 8403060140
- 8403060167 Advises that NUREO-0737, Action Items II K 3 30 & II K 3 31 considered compists, based on B40104 telcon between NRC & OE Licensee need only identify to NRC ref on dockst to GE Topical Rept NEDO-20366 or NEDD-203667
 ZIMMERMAN, S. R. Carolina Power & Light Co B4/02/29 VASSALLO, D B Operating Reectors Branch 2 2pp. 22518 334. 24X Fiche 50-324,84/02/29,8403060167
- 8403060276 Forwards POSI-SEAL Inti.Inc. "LOCA & Seismic Analysis, Brunswick Steem Electric Plant." to demonstrate valve operability. In response to NRC 831201 request HOME, P W Carolina Power & Light Co 84/02/29 VARGA, S A Operating Reactors Brench 1 5pp 22512 001 24X Fiche: 50-324, 84/02/29, 8403060276
- --8403060304 "LOCA & Seismic Anelysis, Brunswick Steam Electric Plant" * Posi-Seal Valves International 325258L-001 84/02/15 470pp 22512 006 24X Fiche 50-324,84/02/29,8403060296
- 8403130452 Application to amend License DPR-71 revising Tech Spec Section 5 3 1 re fuel assemblies, changing 3 00 weight parcent number to 2 97 weight percent to reflect enrichment level used in relocal analysis HOME:P W Cerolina Power & Light Co 84/02/29 VASSALLO, D B Operating Resctors Branch 2 ip 22613 331 24X Fichs 50-325-84/02/29,8403130452
- --B403130465 Revised Tech Spec Bection 5 3 1, Pegss 5-1 & 5-4 changing 3 00 weight percent to 2 99 weight percent to reflect enrichment level used in reload analysis * Cerolina Power & Light Co 84/02/29 2pp 22613 332 24X Fiche 50-325,84/02/29,8403130452
- 8403140287 Forwards evaluation of revised operator requalifications program Rev meets requirements specified in 10CFR50 55, App A & accepteble VABSALLO, D. D. Operating Reactors Branch 2 84/02/29 UTLEY, E E Caroline Power & Light Co. 3pp 22635, 360 24% Fiche 50-324, 84/02/29, 8403140287
- 8403090252 Application to amend Licenses DPR-71 & DPR-62, revising Tech Bpecs re accident monitoring instrumentation per NUREG-0737 & Gensric Ltr 63-35 HOHE, P H Caroline Power & Light Co 84/03/02 VASSALLO, D B Operating Reactors Brench 2 7pp 22571 192 24X Fiche 50-324,84/03/02,8403090252.
- --8403090260 Proposed Tsch Specs re limiting conditions for operation & surveillence requirements for eccident monitoring instrumentation per NUREG-0737 & Generic Ltr 83-36 & Cerolina Power & Light Co. 84/03/02 Zipp 22571 199. 24X Fiche 50-324,84/03/02.8403090252.
- 8403210061 Forwards response to 840202 request for additinfore NUREG-0737. Items II Fit 4, "Containment Pressure Monitor Bys." II Fit. 5, "Containment Water Level Monitor Bys." & II, Fit 6, "Containment Hydrogen Light Co. 84/03/09 VABBALLO, D B Operating Reactors Branch 2 20pp 22705:001 24X Fichs 50-324, 84/03/09, 8403210061
- B403210127 Responds to B40202 request re TMI Action Item II K 3,18 concerning automatic depressurization sys (ADS) logic mods High drywell pressure permissive eliminated k menual inhibit switches to ADS logic edded HOME,P W Caroline Power & Light Co E4/03/07 VASSALLO,D 8 Operating Reactors Branch 2 1p. 22707 235, 24X Fiche:50-324,84/03/07,8403210129

- 8403150275 Generic Ltr 84-07 to 411 licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc list encl EISENHUT, D G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000,84/03/14,8403150275
- 8403300254 Notification of 840321 meeting w/util in Bethesda.MD to discuss status of battery review study OROTENHUIS.M Operating Reactors Branch 2 84/03/14 VASSALLO.D B Operating Reactors Branch 2 1p 22844 352 24X Fiche 50-324.84/03/14.8403300254
- 8403210075 Forwards addi info re BWR steady-state analysis methods.per NRC 840117 request Answers provided to 12 of 15 questions raised by NRC 85 will provide input to Questions 4,8 & 13 Addl responses will be submitted by 84052; ZIMPERMANS R Carolina Power & Light Co. 84/03/15 VASSALLO, D B Operating Reactors Branch 2 2pp 22705 122 24X Fiche 50-324,84/03/15,8403210075
- ---8403210080 Amend i to "Verification of Carolina Power & Light Ref BHR
 Thermal-Hydraulic Methods Using FIBHR Code "
 KUNITA.R K Carolina Power & Light Co NF-1583 C4-1 AOI
 84/03/31 41pp 22705 124 24X Fiche, 50-324,84/03/15,8403210075
- B403300299 Notifies that Class III & Class I fees for review of 830929 application re feedwater & main turbine trip/bypass sysbeing refunded due to withdrawal of application MILLER.W O License Fee Management Branch 84/03/15 JONES J A Carolina Power & Light Co 2pp 22844 309 24X Fiche 50-324,84/03/15,8403300299
- 8403290083 Responds to 840221 request for add1 info rs control of heavy loads Initial load testing performed for head strongback, dryer separator wiing & spant fuel cask yoke ZIMMERMAN, S.R. Carolina Power & Light Co. 84/03/20 VASGALLO, D.B. Operating Reactors Branch 2. 2pp. 22806 325 24X Fiche 50-324,84/03/20,8403270083

Q Inspection reports. IE Bulletins & correspondence

- B403070307 Forwards lE insp Repts 50-324/83-42 & 50-329/83-42 on B31213-B40115 No violations or deviations noted VERRELLI.D.M Division of Project & Resident Programs 84/02/06 VERTELLI.D.M Carolina Power & Light Co Rep 22546 i75 24X Fiche 50-324.84/02/06.8403070307
- --8403070310 IE Insp Repts 50-324/83-42 & 50-325/83-42 on 831215-840115
 No violations or deviations noted Major areas inspected
 surveillance,maint, operational safety verification.ESF sys
 walkdown.LER review.independent insp & plant transients
 MYERB.D O , OARNER.L W Region 2, Office of Director BEMIS.P R
 Division of Project & Resident Programs 84/02/03 Bpp
 22546 177 24X Fiche 50-324.84/02/06.8403070307
- 8403140291 Forwards request for add1 info on IE Bulletin 80-11 re masonry wall design Response requested in 60 days VASSALLO,D B Operating Reactors Branch 2 84/02/21 UTLEY,E E Carolina Power & Light Co 15pp 22635 336 24K Fiche 50-324,84/02/21.8403140291
- 8403070200 Informs that start date for mid-cycle insp in reeponse to NRC concerns re intergranular stress corresion cracking should be changed to 841102 HOME, PW Carolina Power & Light Co 84/02/27 DENION, HR Office of Nuclear Reactor Regulation, Director 1p 22538 353, 24x Fiche 50-324,84/02/27.8403070200
- 8403070315 Forwards Rev O to "Design Rept for Recirculation 89% Weld Overlay Repairs at Brunswick Steam Electric Plant Unit 1:" in pesponse to concerns raised by NRC re Oct 1983 intergranular stress corrosion cracking insp HOME, P W Carolina Power & Light Co 84/02/27 DENTON, H R Office of Nuclear Reactor Regulation, Director, Jpp 22547:001 24X Fiche 50-325,84/02/27,8403070315
- --8403070318 Rev O to "Design Rept for Recirculation Sys Weld Overlay Repairs at Brunswick Steam Electric Plant Unit 1 "
 CHARNLEY, J E , SUND.H J , WENNER, T J , NUTECH Engineers, Inc CPL-13-103 ROO 83/11/04 50pp 22547:004. 24X
 Fighs 50-325,84/02/27,8403070315
- 8401190072 TE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Svc list encl JORDAN, E. L. Division of Emergency Praparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. i15pp. 22709 239 24X Fiche 50-000,84/02/28,8401190072

- 8402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of GA, Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 130pp 22552 329 24X Fichs 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JDRDAN,E L Division of Empreency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of Nsw York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402070009 IE Info Notice 84~15. "Reporting of Radiological Releases"

 Svc list encl

 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, inc 119pp 22553 217 24% Ficha 50-000,84/03/02,8402090009
- 8402090Dii IE Infa Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Respanse (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22853 336 24% Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp. 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402070028 IE Info Notice B4-18, "Stress Corrosion Cracking in FWR Bys " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of Naw York, inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- B403290086 Forwards IE Insp Repts 50-324/84-04 & 50-325/84-04 on B40115-0215 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/03/07, UTLEY, E E Carolina Power & Light Co 2pp 22806 328 24X Fichs 50-324.84/03/07.8403290086
- --8403290092 IE Insp Repts 50-324/84-04 & 50-325/84-04 on 840115-0215 № violations or deviations identified Major areas inspected surveillance.maint. operational safety verification.EBF syswalkdown.in-affice LER reviews & fire protection MYERS.D 0 . GARNER.L W . PATTERSON.C Region 2. Office of Director 84/03/06 itpp 22806 330 24% Fiche 50-324.84/03/07.8403270086
- 8402090031 IE Bulietin 84-02, "Failures of GE Type HFA Releys in Uss in Class IE Safaty Sys " Syc list encl DEVDUNG.R C Director's Office of Properties of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12.8402090031
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of Nsw York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21.8402090043
- 8402070044 IE Info Notice 84-20, "Syc Life of Relays in Safety-Related Sys." Syc list entl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24% Fichs 50-000,84/03/21,8402070044
- R Persodic operating reports & related correspondence
- 8403130333 Monthly operating repts for Feb 1784 M/840305 ltr MARRIBON, F. DIETZ, C.R. Carolina Power & Light Co. 84/02/29, DEYQUNO, R.C. Director's Offics, Office of Inspection and Enforcement 18pp 22614 197 24X Ficha: 50-324,84/02/29, 8403130333
- B Reportable occurrences. LERs & related correspondence
- 8403240411 Forwards Technical Revisw Rept AEOD/T304, "Cause of Containment Isolation Valve F042A to Close"

 SALAH.B Reactor Operations Analysis Branch. 83/03/23
 SEYFRIT,K V Reactor Operations Analysis Branch. 1p. 22775 309.
 24X Fiche 50-325.83/03/23.8403260411
- --B403260414 "Cause of Containment Isolation Valve F042A to Close," AEDD/T304-0010 technical revisw rept * Reactor Operations Analysis Branch 83/03/23 App 22775:310 24X Fiche 50-325,83/03/23,8403240411

- B403010133 Updated LER 83-057/03L-1 on B31117.during unit power performance.temp recorder TR-1258 printed erratically Caused by dirty electrical contacts in control board timing relay Contacts cleaned & returned to svc W/840222 ltr PABTVAM J. DIETZ.C R Carolina Power & Light Co 84/02/22 O'REILLY.J P Region 2, Office of Director 2pp 22435 340 24X Fiche: 50-325.84/02/22.8403010133
- 8403010202 Updated LER 83-063/03L-1 on 831203, reactor water cleanup sys (RWCS) differential flow indicator 1-031-R615 showed erroneous indication On 831207, spurious RWCS alarm annunciated Caused by air in sensing lines W/840222 ltr PASTVA, M J. DIETZ, C R Carolina Power & Light Co 84/02/22 U*REILLY, J P Region 2, Office of Director 3pp 22435 288 24X Fiche 50-325,8402/22,8403010202
- 8403150035 Updated LER 83-063/03L-i on 831203, during unit power operation, reactor water cleanup sys differential flow indicator i-031-R615 showed erroneous indication Causad by entrapped air in sensing line Air removed W/840307 ltr PABTVA.M J. DIETZ.C R Carolina Power & Light Co 84/02/22 O'REILLY.J P. Region 2. Office of Director 3pp 22643 287 24X Fiche 50-325.84/02/22,8403150035
- 8403010375 RO 2-BR-84-3 on 840110.Co-60 concentration in bottom sediment sample exceeded Tech Spec limit Surface water samples in intake & discharge canals & ocean showed no Co-60 activity. Sample frequency increased DIETZ.C R Carolina Power & Light Co 84/02/24 D'REILLY, J P Region 2. Office of Director 2pp 22434 048 24X Fichm 50-324,84/02/24,8403010395
- B403090R05 Special Rept i-BR-84-1 during replacement of equipment hatch, fire barrier limiting condition for operation 7-day time frame exceeded Fire watches will be maintained until work completed DIETZ.G R Carolina Power & Light Co 84/02/Z7 D'REILLY, J P Region 2. Office of Director ip 22574 325 24X Fiche 50-325,84/02/27,8403090205
- 8403130301 Followup RO 2-SR-84-2 in Sept 1982, Co-60 detected in bottom sediments collected in stilling basin Increase in radioactivity probably caused by increased releases of Co-60 due to general decontamination effort DIETZ, C R Carolina Power & Light Co 84/02/29 O'REILLY, J P Region 2. Office of Director 9pp 22608 047 24X Fiche 50-324,84/02/29,8403130301
- 8403130323 LER 84-002-00 on 840203, reactor scram occurred due to high reactor vessel pressure Caused by loss of electrohydraulic control sys fluid actuation supply pressure to valves closing main turbine bypass valves W/840302 ltr
 PABTVA.M J. DIETZ.C R Carolina Power & Light Co 84/03/02 G*REILLY.J P Region 2, Office of Director 4pp 22614 126 24X Fiche 50-325,84/03/02,8403130323
- 8403130049 LER 84-001-00 on 840119, during attempt to initiate suppression pool cooling using Loop A of RHR svc water sys. loop pumps A & C tripped on low suction pressure lockout Caused by air in header Air vented W/840309 ltr PASTVA. M J. DIETZ. C R Carolina Power & Light Co B4/03/09 3pp 22598-355 24X Fiche. 50-325, 84/03/09, 8403130049
- B403170302 LER B4-003-00 on B40217, speed control of HPCI turbine very erratic Caused by malfunction of electronic speed controller Controller unit replaced & HPCI sus satisfactorily tested & returned to svc W/B40314 ltr PASTVA.M J. DIETZ.C R. Carolina Power & Light Co B4/03/14 Zpp 22673-263 24X Fiche 50-325,84/03/14,8403170302
- 8403210137 Updated LER 82-119/03L-1 on 821120, during steady state plant operation, APRM F declared inoperable due to erratic output signal from input LPRN 28-21C, Caused by loose connector Connector corrected, W/840314 ltr ALLEN, M T., DIETZ, C.R. Carolina Power & Light Co. 84/03/14 D'RETLLY, J P., Region 2, Defice of Director, 2pp. 22707 274 24X Fiche: 50-325,84/03/14,8403210139.
- DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1
- F. Becurity, medical, emergency & fire protection plans
- 8403040235 Rev 5 to Procedure 1P-9, "Muscle Shoals Emergency Ctr Implementing Procedures Document " W/B40213 ltr MAXWELL.R Tennessee Valley Authority, 84/02/13 63pp 22518 023 24X Fiche 50-000,84/02/13,8403060235
- 8403060391 Rev 7 to radiological amergency plan, W/840229 ltr MILLS, L M Tennessee Valley Authority 84/02/24, 0'REILLY, J P Region 2, Office of Director, 3pp 22511 336 24X Fiche 50-327,84/02/24,8403060391

- B4030i0154 Ack receipt of B40210 & B31103 ltrs re changes to physical security plan Changes consistent w/provisions of . 10CFR50 54(p) & acceptable LEWIB.R C Division of Project & Resident Programs 84/02/27 PARRIS.H G Tennessee Valley Authority 2pp 22435 310 24X Fiche 30-327,84/02/27,8403010154
- 8403060147 Forwards revised effective pages to Knoxville Emergency Ctr. Central Emergency Control Ctr.Div of Nuclear Power Emergency Ctr & Muscle Shoals Emergency Control Ctr emergency plan implementing procedures W/o Muscle Shoals pages MILLS.L M Tennessee Valley Authority 84/02/28 O'REILLY.J P Region 2. Dffice of Director 19 22516 165 24X Fiche 50-000.84/02/28.8403060147
- --8403060163 Revised list of effective pages to Knoxville Emergency Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 8pg 22516 166 24X Fiche 50-000,84/02/28,8403060147
- --8403060189 Revised list of effective pages to Central Emergency Control Ctr emergency plan implementing procedures * Tennesses Valley Authority 84/02/06 Bpp 22516 174 24X Fache 50-000.84/02/28.8403060147
- --8403060206 Revised list of effective pages to Div of Nuclear Power Emergency Ctr emergency plan implementing procedures * Tannessee Valley Authority 84/02/06 App 22516 162 24X Fiche 50-000,84/02/28.8403080147
- 8403160345 Extends invitation to attend region 840316 workshop at regional ofe to discuss 10CFR50.App R requirements & recent results of insp to help resolve misunderstandings associated w/requirements

 LEMIS.R C Division of Project & Resident Programs 84/03/02

 PARRIES.H G Tennessee Valley Authority 2pp 22660 083 24X

 Fiche 50-000.84/03/02.8403160345
- 8403190370 Rev 8 to radiological emergency plan, updating DOE agreement ltr in App E W/840315 ltr MlLL8.4. M Tennessee Valley Authority 84/03/07 O'REILLY, J P Region 2. Office of Director App 22674 207 24X Fiche 50-327.84/03/07.8403190370
- B403i30377 Ack receipt of B40ii9 ltr transmitting Rev 7 to security personnel training & qualiffication plan Changes consistent W/provisions of iOCFR50 54(p) & acceptable for inclusion in plan
 LEWIG.R C Division of Project & Resident Programs B4/03/08 PARRIB.H G Tennesses Valley Authority ip 22616 293 24X Fiche 50-327,84/03/08,8403i30377
- 8403160035 Advises that 840116 rev to physical security plan consistent w/provisions of iOCFR50 54(p) & acceptable LEWIG.R C Division of Project & Resident Programs 84/03/13 PARRIS.H O Tennessee Valley Authority 2pp 22655 139 24X Fiche 50-327.84/03/13.8403160035
- 8403160139 Advises that B40101 rev to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable LEWIS.R C Division of Project & Resident Programs B4/03/i3 PARRIS.H G Tennessee Valley Authority 2pp 22655 331 24X Fiche 50-327.84/03/i3.8403160139
- B403260277 Revised Emergency Plan Implementing Procedures SQN-IPD "Implementing Procedures Index" & SQN IP-5 "General Emergency " W/840320 Itr Emergency " W/8403216 L CREATER OF THE MILLS, L M Tennessee Valley Authority B4/03/16 D'REILLY, J P Region 2, Office of Director App 22753, 028 24% Fiche 50-327, 84/03/16, 8403260277
- J Insurance & indemnity information
- 8403060224 Forwards Endorsement 40 to NELIA Policy NF-247
 DUCK.J R Marsh & McLennan. Inc 84/02/28 SALTZMAN.J Assistant
 Director for State & Licensee Relations 2pp 22516 062 24X
 Fiche 50-327.84/02/28.8403060224
- 8403070175 Forwards Endorsement 34 to MAELU Policy MF-102.correcting policy number on Endorsement 33 from MF-77 to MF-102 DUCK.JR Marsh & McLennan, Inc. 84/03/01 SALTZMAN, J Assistant Director for State & Licensee Relations 19 22538 351 24X Fiche 50-327,84/03/01,8403070175

P Operating license stage documents & correspondence

- 8403020313 Forwards add1 comments to Guidelines 5a.7a & 7b of technical evaluation rept in response to NRC 820630 ltr re control of heavy loads.per Generic Ltr 81-07 MILLS.L M Tennessee Valley Authority 84/02/28 ADENSAM.E Licensing Branch 4 11pp 22439 190 24X Fiche 50-327.84/02/28, decon2033
- 8403160247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rev 7 to topical GA program.per 840302 telcon LEMIB.# C Region 2. Office of Director 84/03/08 PARRIS.H G Tennessee Valley Authority 1p 22660 361 24X Fiche 50-000.84/03/08.8403160247
- 8403290026 Forwards listing of Category IV components not to be replaced or relocated by end of second refueling cycle.per 10CFR50 49(h) & util 831114 ltr Requeste extension of completion date to June 1985 for disposition of 164 items HILLS,L M Tennessee Valley Authority 84/03/23 ADENSAN,E Licensing Branch 4 App 22806 218 24% Fiche 50-327,84/03/23,8403290026
- 8403290038 Forwards revised responses to B31123 & 840109 itrs reapproval of proposed license amend repost-accident sampling for facilities. THI I tem II B 3 MILLS.L M Tennessee Valley Authority 84/03/23 ADENSAM.E Licensing Branch 4 9pp 22806-237 24X Fiche 50-327.84/03/23, 8403290038

O Inspection reports. IE Bulletins & correspondence

- 8403160217 Forwards IE Insp Repts 50-327/84-03 & 50-328/84-03 on 840106-0205 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/02/15 PARRIS.H G Tennessee Valtey Authority 2pp 22661 091, 24X Fiche 50-327,84/02/15,8403160217
- --8403160225 IE Insp Repts 30-327/84-03 & 50-328/84-03 on B40106-0205 No violations or deviations noted Major areas Inspected operation safety verification. LER review & Independent inspected the street of the section plan FORD.E J. BUTLER.S D. Region 2. Office of Director JULIAN.C A Division of Project & Resident Programs 84/02/15 5pp 22661 093 24X Fiche 50-327,84/02/15.8403160217
- 8403060223 IE Insp Repts 50-275/64-01 & 50-323/84-04 on 840103-06 Noncompliance noted failure to perform safety-related origing activities in area of structural steel welding activities BURDDIN.JF. KIRBCH.DF Region 5, Office of Director 84/02/17 App. 22517 149. 24X Fighr 50-223/84/02/17,8403360207
- 8403070191 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-327/83-27 & 50-328/83-29 O'REILLY, J.P. Region 2. Defice of Director 84/02/27 PARRIE, H Q Tennessee Value Authority 19 22538 298 24X Fiche 50-327,84/02/27,8403070151
- --B403070135 Responds to NRC B40110 itr re violations noted in IE Insp Repts 50-327/83-27 & 50-328/83-27 Corrective actions Work Plan 10260 reworked per critical sys, structures & components requirements HILLS-L M Tennessee Valley Authority B4/02/08 O'REILLY, J P Region 2. Office of Director 6pp 22538 277 24X Fiche 50-327, B4/02/27, B403070151
- --8403070156 Forwards IE Insp Repts 50-327/B3-29 & 50-328/B3-29 on B31106-1205 & notice of violation O'REILLY, J.P. Region 2, Office of Director. B4/01/10 PARRIS.H 9 Tennessee Valley Authority 2pp 22538 305 24X Fiche 50-327,84/02/27,8403070151
- --8403070159 Notice of violation from insp on 631106-1205 • Region 2, Office of Director 84/01/10 3pp 22538 307 24% Fiche 50-327,84/02/27.8403070151
- --8403070163 IE Insp Repts 50-327/83-29 & 50-328/83-29 on 83:106-1205 Violations noted failure to follow Sys Operating Instruction 14 3 for high crud tank B release & failure to inspect work per M&AI-12 requirements
 FORD

- B401190072 IE Info Natice B4-13, "Potential Deficiency in Hotor Operated Valve Control Circuits & Annunclation " Svc list encl JORBAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22709 239 24X Fichs 30-000.84/02/28 B801190072
- 8402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Bvc list encl GRACE.J N Division of GA. Bareguards & Inspection Programs (Pest 830103) 84/03/02 Consolidated Edison Co of New York, Inc 8308p 22532 329 24X Fiche 50-000,84/03/02,8402070007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinler Bys Valves to Operate " 8vc list enc! JORDAN E L. Bivision of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of Rey York, Inc. 122pp 22553 098 24% Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Byo list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 94/03/02 \ Consolidated Edison Co. of His York, Inc. 119pp. 22553 217 24X Fiche 30-000,84/03/02,8402090002.
- 8403090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Evo list enct.

 JURDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24% Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09. Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl. JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635,049 24X Fithe 50-000.84/03/07.8402090026
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in fMR Bys." Bvc list and J JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 64/03/07 Consolidated Edison Co of Kre York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8403130088 Forwards Rev 1 to "Inservice Insp Program"
 HILLS.L.M Tennessee Valley Authority 84/03/07 ADENBAH.E
 Licensing Branch 4 ip 22597 001 24X Fiche 50-327.84/03/07.
 8403130088
- --8403130100 Rev 1 to Procedure BL-114 1. "Inservice Insp Program"
 LEHBERGER.N Tennesse Valley Authority 84701/04, 425pp
 22597 002. 24X Fichs: 50-327.84/03/07.8403130088
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys." Svc list encl
 DEYOUNG: R C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co. of New York inc
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unautheriss Entries into PWR Reactor Cavities" Bvc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/21 Consolidated Edison Co 45 Nov
 York, Inc 123pp 22823 229 24X Fiche: 50-000, 84/03/21, 8402090913
- 8402070044 IE Info Notice 84~20. "Bvc Life of Relays in Bafsty-Related Bys." Byc 11st enc! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21. Consolidated Edison Co. of Nie York, Inc. 135pp 22933-001 24X Fiche.50~000,84/03/21,8402070918
- R Periodic operating reports & related correspondence
- B403020002 Monthly operating repts for Jan 1984, W/840215 ltr MABON:C C Tempesse Valley Authority 84/01/31 30pp 22442 117 24X Fishe 50-327, 84/01/31, 8403020002
- 8403070275 "NPDES Discharge Monitoring Rept. Nov 1983 Jan 1984 "
 * Tennessee Valley Authority 84/01/31, 79pp 22545:092 24x
 Fiche 50-327,84/01/31,8403070295
- 8403300154 Montyly operating repts for Feb 1984, W/840315 1tr EDDINOB, M O , MASON, C C Tennessee Valley Authority 84/07/29 51pp RRSR1 016 RAX Fiche 50-327, 84/07/29, 8403300154.

- S Reportable occurrences, LERs & related correspondence
- 8403080011 Forwards response to Commissioner Gilinsky request for info on frequency of personnel errors at selected operating plants Summary of tabulated events re operator errors, personnel errors or pracedural errors provided for CVB3 DIRCKB, WJ Diffice of the Executive Director for Operations 84/02/24 PALLADING, GOLINSKY, ROBERTS Commissioners 17pp 22584 142 24X Fiche 50-000,84/02/24,8403080011
- 8403020147 LER 84-010-00 on 840128, high radiation alarm actuated, causing auxiliary bidg isolation to occur Caused by electromagnetic interference High radiation alarm reset & manitor returned to svc W/840227 ltr DUQQIN.0. MABON.C C Tennessee Vailey Authority 84/02/27 3pp 22441 357 24X Fiche 50-327,84/02/27,8403020147
- 8403050080 LER 84-009-00 on 840i28, high radiation alarm actuated, causing containment ventilation isolation to occur Caused by root valve on pressurizer leaking through packing Valve bactseated M/840227 ltr
 DUGUN, O . MASON, C C Tennesses Valley Authority 84/02/27 3pp 22490 016 24% Fiche 50-327,84/02/27,8403030080
- 8403i40203 Forwards "Operating History Overview for Diesel Generators in Nuclear Gvc." comparing Transamerica Delaval.lnc generators w/generators mfg by other vendors HEBDON.F J Program Technology Branch 84/02/27 BERLINGER.C H NRC No Datailed Affiliation Given Ip 22638.317 24X Fiche 50-000.84/02/27.8403i40203
- --8403140205 "Operating History Overview for Diesel Generators in Nuclear Byc " * Director's Office 84/02/27 65pp, 22638 320 24X Fiche 50-000,84/02/27,8403140203
- 8403020244 LER 84-013-00 on 840130 turbine trip followed by reactor trip occurred Caused by high-high level in steam generator 4. Unit stabilized at 547 F W/840228 ltr KIRK. 9 B E . MASON. C C Tennessee Valley Authority 84/02/28 3pp 22440.097 24X Fiche 50-327,84/02/28,8403020244
- 8403i50lBi Forwards "Fallures in Upper Head Injection Sys " Licensees taking action to resolve setpoint drift on Barton level transmitters No AEOD action recommended ZUKDR,D J Reactor Operations Analysis Branch 84/02/28 SEYFRIT.K V Reactor Operations Analysis Branch 1p 22646 272 24X Fiche 50-000,84/02/28.8403i50lBi
- ---8403150183 "Failures in Upper Head Injection Sys," AEOD engineering evaluation rept
 ZUKDR, A Director's Office 84/02/28 8pp 22646 273 24X
 Fiche. 50-000, 84/02/28, 8403150181
- 8403060276 LER 84-012-00 on 84020i, high radiation alarm actuated, causing containment ventilation isolation to occur. Caused by voltage spike as result of electromagnetic interference Alarm reset & monitor returned to svc W/84030i ltr DU001N, 0, MASON, C C Tennessee Valley Authority 84/03/0i 4pp 22519:066 24% Fiche 50-327,84/03/0i,8403060276
- 8403i30079 LER 84-0i4-00.on 8402i4.high radiation alarm actuated, causing containment ventitation isolation to occur Caused by voltage spike resulting in electromagnetic interference. Alarm reset & monitor returned to svc W/840309 ltr. DUGOIN, 0, MASON, C C Tennessee Vaiiey Authority 84/03/09 4pp 22643:203. 24% Fiche 30-327.84/03/09.8403i30079
- 8403190121 LER 84-016-00, on 840225, high radiation alarm actuated, causing auxiliary bidg isolation to occur Gaused by contaminated vacuum cleaner removed from fuel transfer canal to radwaste area W/840316 ltr
 DUG01N, 0, MASON.C C Tennessee Valley Authority. 84/03/16 3pp 22668:245 24X Fiche 50-327,84/03/16,8403190121
- 8403190365 LER 84-015-00, on 840220, high radiation alarm actuated, causing auxiliary bldg isolation Caused by voltage spike due to electromagnetic interference breaker actuation Independent high radiation alarm reset. W/B40316 ltr DU001N, 0, MASON, C C Tennessee Valley Authority 84/03/16 3pp 22675, 231 24X Fiche 50-327, 84/03/16, 8403190365.
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV.500-750 MVA:5 kV 350-3,000 & all HKV circuit breakers. Initially reported on 830223 Addends to installation & maint procedures sent to affected units DUVALLO D Brown Boveri Corp. (subs of Brown Boveri & Co., Ltd.) 84/03/19 Record Services Branch (Document Control Desk.) 5pp 22772:114. 24X Fiche 50-000.84/03/19,8403270219

- 8403260164 LER 84-018-00 on 840221, fire protection deludge valve found isolated w/o continuous fire watch in place Caused by spurious signal Shift groups reinstructed to establish fire watches W/840320 ltr
 KIRK.0 B , MASON.C C Tennessee Velley Authority 84/03/20 3pp 22730 353 24X Fire 50-327.84/03/20.8403260164
- 8403300073 LER 84-017-00 on 840227, high radiation elarm actuated, causing containment ventilation isolation to occur Caused by small quantity of airborne radiation escaping Radiation monitor reset W/840327 ltr
 DUGGIN G . MASON.C C Tennessee Valley Authority 84/03/27 3pt 22822 089 24X Fiche 50-327,84/03/27,8403300073
- 8305230539 Forwards technical review rept, "Flow Diockage in Essential Raw Cooling Water Sys Due to Asiatic Clam Intrusion "
 IMBRO.E Reactor Operations Analysis Branch 83/03/28
 SEYFRIT. K V Reactor Operations Analysis Branch 1p 22787 281
 24X Fiche 50-327,84/03/28,8305230539
- 8305230546 "Flow Blockage in Essential Raw Cooling Water Bys due to Asiatic Clam Intrusion," technical review rept Bignificant infestations of aquatic organisms can remain undetected in svc water sys & cause flow blockages at inopportune times.

 * Reactor Operations Analysis Branch 83/03/28 3pp 22789 282 24X Fiche 50-327,84/03/28,8405230539
- DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

 F Security, medical, smergency & fire protection plans
- 8403040235 Rev 5 to Procedure 1P-9. "Muscle Shoats Emergency Ctr Implementing Procedures Document " W/840213 1tr MAXHELL.R Tennessee Valley Authority 84/02/13 63pp 22518 023 24X Fiche 50-000.84/02/13.8403060235
- 8403060391 Rev 7 to radiological emergency plan W/B40229 ltr MILLS,L M Tennesse Valley Authority B4/02/24 O'REILLY,J P Region 2. Office of Director 3pp 22511 336 24x Fiche 50-327,64/02/24,8403060391
- 8403010154 Ack receipt of 840210 & 83ii03 ltrs to changes to physical security plan Changes consistent w/provisions of 10CFR50 54(p) & acceptable LEMIS.R C Division of Project & Resident Programs 84/02/27 PARRIS.H G Tennessee Valley Authority 2pp 22435 3i0 24X Fiche 50-327,84/02/27.8403010154
- 8403060147 Forwards revised effective pages to Knoxville Emergency Ctr. Central Emergency Control Ctr.Div of Nuclear Power Emergency Ctr & Muscle Shoals Emergency Control Ctr emergency plan implementing procedures W/o Muscle Shoals pages MILLG.L M Tennessee Vallay Authority 84/02/28 O'REILLY, J P Region 2. Office of Director ip 22516 165 24X Fichs 50-000.84/02/28.8403060147
- --8403060i63 Revised list of effective pages to Knoxville Emergency Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 8pp 22516 i66 24X Fiche 50-000.84/02/28,8403060147
- --8403060189 Revised list of effective pages to Central Emergency Control Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 8pp 22516 174 24X Fiche 50-000.84/02/28-8403060147
- --B403060206 Revised list of effective pages to Div of Nuclear Power Emergency Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 4pp 22516 182 24X Fiche 50-000,84/02/28,8403060147
- 8403160345 Extends invitation to attend region 840316 workshop at regional ofc to discuss 10GFR30. App R requirements & recent results of insp to help resolve misunderstandings associated w/requirements

 LEMIS.R C Division of Project & Resident Programs 84/03/02

 PARRIS.H 0 Tennessee Valley Authority 2pp 22660 083 24X

 Fiche 50-000,84/03/02.8403160345
- 8403190370 Rev 8 to radiological emergency plan.updating DDE agreement ltr in App E W/840315 ltr HILLB,L.M Tennessee Valley Authority 84/03/07 O'REILLY,J P Region 2. Office of Director. App 22674 207 24X Fiche 50-327.84/03/07.8403190370

- 8403130377 Ack receipt of 840119 ltr transmitting Rev 7 to security personnel training & qualification plan Changes consistent w/previsions of 10CFR50 54(p) & acceptable for inclusion in plan
 - plan LEMIB.R C Division of Project & Resident Programs 84/03/08 PARRIB.H G Tennessee Valley Authority 19 22616 293 24X Fiche 50-327.84/03/08.8403130377
- 8403160035 Advises that 840116 rev to physical security plan consistent u/provisions of 10CFR50 54(p) & acceptable LEWIS.R C Division of Project & Resident Programs 84/03/13 PARRIS.H 6 Temmessee Valley Authority 2pp 22655
- 8403160139 Advises that 840101 rev to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable LEWIS.R C Division of Project & Resident Programs 84/03/13 PARRIS,H O Tennessee Valley Authority 2pp 22655 331 24X Fiche 50-327.84/03/13.8403160839
- 8403260277 Revised Emergency Pian Implementing Procedures SQN-1PD "Implementing Procedures Index" & SQN IF-5 "General Emergency " W/840320 Itr NOBLES, L M . CRAMLEY, D E , MILLS, L K Tennessee Vailey Authority 84/03/16 D'REILLY, J F Region 2, Office of Director App 22753 028 24% Fiche 50-327.84/03/16.8403260877
- J Insurance & indemnity information
- 8403060224 Forwards Endorsement 40 to NELIA Policy NF-247 BUCK-JR Mørsh & McLennan, Inc. 84/02/28 SALTZMAN, J. Assistant Director for State & Licensee Relations 2pp 22516 062 24X Fiche 50-327,84/02/28.8403060224
- 8403070175 Forwards Endorsement 34 to MAELU Policy MF-102, correcting policy number on Endorsement 33 from MF-77 to MF-102 BUCK-J R Marsh & McLennan, Int 84/03/01 SALTZMAN, J Assistant Director for State & Licensee Relations ip 22538 351 24X Fiche 50-327.84/03/01.8403070175
- P Operating license stage documents & correspondence
- 8403020313 Forwards add1 comments to Guidelines 5a,7a & 7b of technical evaluation rept in response to NRC 820630 ltr re control of heavy loads.per Generic Ltr 81-07 HILLS.L M Tennessee Valley Authority 84/02/28 ADENSAM.E Licensing Branch 4 lipp 22437 190 24X Fiche 30-327,84/02/28,880330313
- 8403140247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rey 7 to topical QA program.per 840302 teleon
 LEMIS.R C Region 2. Office of Director 84/03/08 PARRIS.H G Tannassee Vailey Authority 1p 22660 361 24x
 Fiche 50-000.84/03/08.8403160247
- 8403290038 Forwards revised responses to 831123 & 840109 itrs re approval of proposed license amend re post-accident sampling for facilities: TM1 Item II 8 3 MELS:L M Tennesses Vailey Authority 84/03/23 ADENSAM.E Licensing Branch 4 9pp 22806 237 24X Fishe 50-327,84/03/23, 8403290038
- O Inspection reports. i£ Bulletins & correspondence
- 8403160217 Forwards IE insp Repts 50-327/84-03 & 50-328/84-03 on 840106-0205 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/02/15 PARRISH Ø Tennessee Valiey Authority 2pp 22661 091 24X Fiche 50-327.84/02/15.8403160217
- 8403070151 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-29 & 50-329/83-29 O'REILLY, J P Region 2. Office of Director 84/02/27 PARRIS, H G Tennessee Valley Authority ip 22538 298 24X Fiche 50-327,84/02/27,8403070151

- --8403070155 Responds to NRC 840110 ltr re violations noted in IE lass Repts 50-327/03-29 & 50-328/83-29 Corrective actions Work Plan 10260 reworked per critical sys, structures & components requirements MILLS.L K Tennessee Valley Authority 84/02/08 0'REILLY, J P Region 2, Office of Director App 22538 299 24x Fiche 50-327.84/02/27,8403070151
- --8403070196 Forwards IE Insp Repts 50-327/83-29 & 50-328/83-29 on B31104-1205 & notice of violation O'REILLY, J P Region 2. Office of Director 84/01/10 PARTS, H O Tennessee Valley Authority, 2pp 22338 305 24X Fiche 50-327,84/02/27,8403070151
- --8403070159 Natice of violation from insp on 831106-1205 * Region 2, Office of Director 84/01/10 3pp, 22538.307 24x Fichs 50-327.84/02/27.8403070151
- --8403070163 IE Insp Repts 50-327/83-29 & 50-328/83-29 on 831106-1205
 Violations noted failure to foliow Sys Operating Instruction
 14 3 for high crud tank B release & failure to inspect work
 per M&Al-12 requirements
 FORD
- B401190072 IE Info Notice 94-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Bvc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York. Inc 115pp 22909 239 24X Fiche 50-000.84/02/28,8401190072
- 8402070007 IF Info Natice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC," Svc list encl. GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 840209000B if Info Notice 84-16. "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc i22pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svt list encl JCROBAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 117pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- B402070011 lE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 80103) B4/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05.8402070011
- 8402090024 IE Info Notice 84-07. Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list anci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Fost B30103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402070028 IE info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syx list end JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24% Fiche 50-000.84/03/07.8402070028
- B402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class 1E Safety Sys " Byc list encl DEYOUNG: R C Director's Office. Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24% Fiche; 50-000.84/03/12,8402070031.
- 8402070043 iE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list and UNRDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84~20, "Svc Life of Relays in Safety-Related Sys " Svc list and JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc 135pp 22733 001 24% Fiche 50-000,84/03/21,8402070044

- R Periodic operating reports & related correspondence
- 8403020002 Monthly operating repts for Jan 1984 W/840215 ltr MASON:C C Tennesse Valiley Authority 84/01/31 30pp 22442 157 24X Fichs 50-327:84/01/31.8403020002
- 8403070295 "NPDES Discharge Monitoring Rept.Nov 1983 Jan 1984 " * Tennessee Valley Authority 84/01/31 79pp 22546 092 24% Fiche 50-327,84/01/31,8403070295
- 8403300154 Montyly operating repts for Feb 1984 W/840315 ltr EDDINGS,M G , MASON,C C Tennessee Valley Authority 84/02/29 51pp 22821 016 24X Fiche 50-327.84/02/29,8403300154
- 8 Reportable occurrences, LERs & related correspondence
- B40308001i Forwards response to Commissioner Gilinsky request for info on frequency of personnel errors at selected operating plants Summary of tabulated events re operator errors, personnel errors or procedural errors provided for CVB3 DIRCKB.W J Office of the Executive Director for Operations B4/02/24 PALLADINO Commissioners 17pp 22584 142 24X Fiche. 50-000.84/02/24.8403080011
- 8403130181 Forwards "Failures in Upper Head Injection Sys " Licensees taking action to resolve setpoint drift on Barton level transmitters No AEOD action recommended ZUKOR, DJ Reactor Operations Analysis Branch 84/02/28 SEYFRIT.K V Reector Operations Analysis Branch ip 22646 272 24X Fiche 50-000.84/02/28.8403150181
- --8403150183 "Failures in Upper Head Injection Sys." AEOD engineering avaluation rept ZUKOR.A Director's Office 84/02/28 8pp 22646 273 24x Fiche 50-000,84/02/28,8403150181
- 84032702i9 Pert 2i rept re broken contact carrier in control device of 7 3 kV-15 kV. 500-750 MVA, 5 kV 350-3,000 & ail HKV circuit braekers Initiality reported on 830223 Addenda to installation & meint procedures sent to affected units DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24X Fiche 50-000.84/03/19,8403270219
- 8403300204 LER 84-003-00 on 840227, vital inverter failed Caused by blown fuse due to incarrect connection which caused containment ventilation isolation Containment ventilation isolation reset & inventer returned to svc W/840327 itr DUGOIN, 0. MASON, C.C. Tennessee Vailey Authority 84/03/27, 3pp 22819 324 24X Fiche 50-328,84/03/27,8403300204

DOCKET 50-329 MIDLAND PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8403010192 FOIA request for records relevent to or generated in connection w/831021 "Rept on Review of Diesel Generator Bidg at Midlend"

 GARDEL® P Government Accountability Project 83/11/26 Office of Administration 2pp 22445 092 24X Fiche 50-329,83/11/26.
 8403010192
- 84030i0178 Responds to FOIA request for records relevant to or generated in connection w/831021 "Rept on Review of Diesel Generator Bidg at Midland " Forwards App B documents App A documents evaitable in FDR FELTON, J M Division of Rules and Records 83/12/14 GARDE, B P Government Accountability Project 4pp 22445 092 24X Fiche: 50-329, 83/12/14, 8403010198
- --B310310471 Forwards tesk group rept. "Rept on Review of Diesei
 Omberator Bldg at Midiand," Oct 1983 Large addl settlements
 not anticipated More accurate program to monitor cracks
 needed,
 KUO.P. Structurel & Geotechnical Engineering Branch 83/10/21
 KNIGHT.J P. Assistant Director for Comp & Structures Engineering
 (Fost 830201) 2pp 22445 152 24X Fiche. 50-329, 83/12/14,
 8403010198
- --8310310475 "Rept on Review of Diesel Cenerator Bidg at Midland"
 TAN.C P Structural & Gentechnical Engineering Branch 83/10/35
 96pp 22445 154. 24X Fiche: 50-329, 83/12/14, 8403010178
- --B3:2010004 Forwards corrected Pages 9,17,20 & 4 to App 11 to rept on review of diasel generator bldg. KUD-P Structurel & Geotechnical Engineering Branch 83/11/14 KNIOHT.J P Assistant Director for Comp & Structures Engineering (Post 830201), 5pp 22445 256, 24X Fiche 50-329,63/12/14, 8403010178

- --0312050628 Requests rept re adequacy of diesel generator bldg on expedited basis as input to Congress re Landsman concerns EISENHUT.D G Division of Licensing 83/11/18 VOLLMER,R Division of Engineering 1p 22445 263 24X Fiche 50-329.03/12/14,8403010198
- --8312070022 Forwards Structural & Geotechnical Engineering Branch
 assessment of "Rept of Roview of Diesel Generator Didg at
 Midland." dtd 831021 par E Adensam & M Paton requests
 Meeting & Possible reopening of hearing recommended
 LEAR.O Structural & Geotechnical Engineering Branch
 VOLLMER.R H Division of Engineering 2pp 22445 268 24x
 Fiche 30-329,83/12/14,8403010198
- ~-B312070298 Discusses recommendation for suppl to Board Notifications B3-165 & 83-153 re diesel generator bldg Comments & recommendations of J Kane & F Rinaid: on task group rept & reopening of hearing provided HOOD, D & Licensing Branch 4 B3/11/22 EISENHUT, D 0 Division of Licensing 4pp 22445 264 24X Fiche 50-329.83/12/14, 8403010188
- --B312080134 Recommends PT Kuo B31114 memo containing four corrected pages to rept re structural adequacy of diesel generator bldg be forwarded to Doard as supplemental notification to BN 83-165 HOOD, D Licensing Branch 4 83/11/17 EISENHUT, D Assistant Director for Licensing ip 22445 261 24X Fiche 50-329, 83/12/14,8403010198
- --B403010204 Advises that info re plan to address Landsman concerns should be issued as Board Notification 83-109
 EIBENHUTD G Division of Licensing 83/07/27 NOVAK, T
 Assistant Director for Licensing 1p 22445 098 24X
 Fiche 50-329,83/12/14,8403010198
- --B4030i02i1 Advises that attached correspondence re new schedule for review of Landsman concerns should be issued as Board Notification 183-142 M/o enci EIBENHUT.D Q Division of Licensing 83/09/20 NDVAK.T Assistant Director for Licensing Ip 22445 099 24X Fiche 50-329,83/12/14,8403010198
- --8403040217 Draft rept, "Review of Diesel Generator Bldg at Midland Plant " MILLER,C A , COSTANTINO.C J Brookhaven National Laboratory 83/09/23 25pp 22445 100 24X Fiche 50-329,83/12/14,8403040198
- ---8403010223 Advises that enci JP Knight 830923 memo to RH Volimer should be issued as Board Notification 83-153 W/o encl EIBENHUT; D 9 Division of Licensing 83/10/05 NDVAK, Y Assistant Director for Licensing ip 22445 125 24X Fiche 50-329, 83/12/14, 8403010198
- --8403010227 Forwards "Review of Diesel Generator Bldg at Midiand Plant " REICH,M Brookhayen National Laboratory 83/10/17 KUD.P T Structural & Geotechnical Engineering Branch 1p 22445 126 24X Fiche 50-329.83/12/14,8403010198
- --B403D10231 "Review of Diesel Generator Didg at Midland Plant "
 MILLER, C A , COSTANTINO, C J Brookhaven National Laboratory
 B3/10/17 25pp 22445 127 24X Fiche 50-329, 83/12/14, 8403010198
- --8403010243 Requests that enci rept on review of diesel generator bidg & util analysis requested during review be issued as Board Notification 83-165 EISENNUT.D Q Division of Licensing 63/10/26 NOVAK.T Assistant Director for Licensing 69P 22443 250 24X Ficha 50-327.83/12/14.8403010198
- --B403010273 Advises that supplemental info provided in PT Kuo 831114 memo to JP Knight will be transmitted to Nidland Board as suppi to Board Notification 83-165 Issue will be incorporated as Board Notification 83-165A W/a enci ETBENKUT. D © Division of Licensing 83/11/16 NDVAX. T Assistant Director for Licensing ip 22445 262 24X Fiche 50-327.83/12/14.8403010198
- --8403010282 Forwards guidance for use in deciding whether to recommend that hearing be reopened Hearing should be reopened based on listed reasons VOLLMER.R H Division of Engineering 83/11/25 EISENHUT.D G Division of Licensing 3pp 22445 270 24X Fiche 50-327, 83/12/14,8403010198
- --8403010285 Advises that Vollmer recommended reopening Midland hearing on diesel generator bidg structural adequacy issue, based on task group rept Vollmer memo enci M/o encl ADENSAM, E NRC No Detailed Affiliation Civen 63/11/25 EISENHUT, D NRC No Detailed Affiliation Given 1p 22445 273 24X Fiche 30-039, 83/12/14:8403010198

- 8403010488 Appeals denial of FOIA request for T Novak notes generated by or during visit to Glen Elium. IL to discuss Ofc of Special Cases findings re facilities from Sept 1982 to Dec
 - 1983 GARDE, B.P. Government Accountability Project 84/01/17 FELTON, J.M. Division of Rules and Records 19 22443 274 24X Fiche 50-329, 84/01/17, 8403010488
- 8403040486 Further response to FOIA request for documents re evaluation or seview of design, const. scheduling.cost & licensing of facilities from 1977 to present Rept unavailable for Categories 1 & 2 Panel records on evaluations placed in PDR FELTON, J H Division of Ruies and Records 84/01/24 ZACK, A M Barris. Sott. Denn & Driter 2pp 22552 232 24X Fiche 30-329,84/01/24,8403060486
- 0403060370 Notifies of independent design & const verification program 840313 meeting w/NRC & util in Bethesda.MD to discuss details of completion of IDVP LEVIN.H A TERA Corp 84/02/24 EISENHUT.D 0 Division of Licensing KEPPLER.J 0 Region J. Office of Director COOK.J.H Consumers Power Co 3pp 22511 312 24X Fiche 50-329.84/02/24, 8403060370
- 8403010276 Authorizes util to proceed w/remedial soils work activities scheduled for Mar 1984, per 840214 request for Work Authorization Procedure 102750125 HARRISON, J. Region 3, Office of Director 84/02/28 QUAMME, D. L. Consumers Power Co. 2pp. 22432 104 24% Fiche 50-327, 84/02/28, 8403010276
- 8403080230 Lists unresolved items & audit finding repts, including MSA-B3-10-03U & MSA-B3-25-07F, respectively 4 Consumers fower Co 84/02/28 Stone & Webster, Inc. ip 23560 126 24% Fiche 30-329,84/02/28,8403080230
- 8403080241 Forwards 84022/ list of Dechtel personnel trained to accomplish status assessment Consumers Power Co 84/02/28 Stone & Webster, Inc 3pp 22561 013 24% Fiche 50-329,84/02/28.8403080241
- 840308024B Forwards proposed list of remedial soils work for Mar 1984 & supplemental work activity list for Apr 1984 Review.comments & authorization requested QUA/ME.D.L. Consumers Power Co. 84/02/28 HARRISON, J.J. Region 3. Office of Director [3pp. 22556 276. 24x Fithe 50-329.84/02/28, RA01080248
- 8403080260 Forwards summary of sixth meeting on confirmed items & findings on 84020t at Bechtel Ann Arbor.MI ofc re items identified in independent design & const verification program monthly status rept dtd 840133 LEVIN.H A TERR Corp 84/02/28 KEPPLER, J 0 Region 3, Office of Director COOM, J W Consumers Power Co EISENHUT.D 0 Division of Licensing 14pp 22557 078 24X Fiche 50-329,84/02/28,8403080260
- 8403;3026; Notifies that GR Fotiades placed on controlled distribution of training plan manual.per 840224 request QUAMME.D L Consumers Power Co 84/02/28 BARANOW, S Stone & Webster, Inc ip 226;7 134 24% Fiche 50-329; 84/02/28, 8403;3026;
- 8403220179 Forwards 840307 memo providing documentation to 5%N for const implementation overview
 * Consumers Power Co 84/02/28 Stone & Webster, Inc 4pp 22717 024 24X Fiche 50-329,84/02/28,8403220179
- 8403080262 Forwards waskly NSSS subcontract status rept for wit ending 840217 M/o encl 4 Consumers Power Co 84/02/29 Stone & Mebster, Inc ip 22557 112 24X Fiche 30-329.84/02/29.8403080262
- 8403130189 Provides list of documents sent to SSW on 840227 * Consumers Power Co 84/03/01 Stone & Webster, Inc is 22617 323 24X Fiche 50-329,84/03/01,8403130189
- 8403140021 Forwards Vol X to "Spismic Margin Review, Miscellaneous Subsystems & Components "COCK, J W Consumers Power Co 84/03/01 DENTON, H R Division of Licensing 3pp 22622 167 24% Fitche 50-327, 84/03/01, 8403140021

- --8403140026 "Seismic Margin Review Miscellaneous Subsystems & Components "
 WESLEY, D A , NARVER, R B Structural Mechanics Associates BMA 13701 05R003 VIO 84/02/29 200pp 22632 171 24X
 Fiche 50-329,84/03/01.8403140021
- B403130470 Discusses sampling insps of const training records for personnel noted in Correspondence CSC-7382 Personnel listed cleared to perform status assessment encl W/o encl KARR.J E Stone & Webster. Inc. B4/03/02 GUAMME.D L Consumers Power Co 1p 22613 209 24X Fiche 50-327,84/03/02.8403130470
- 8403150003 Forwards svc water pump structure crack survey rept NRC concurrence of mods to crack mapping program requested Saven oversize drawings encl Aperture cards are available in PDR MDDNEY, J. A. Consumers Power Co. 84/03/05 HARRISEN, J. J. Region 3, Office of Director. 30pp. 22824 i16. 24X Fiche 50-329,84/03/05. 8403150003
- 8403130388 Forwards signed affidavit & resume for RE Horine assigned to const implementation staff at plant KARR.JE Stone & Hebster, Inc. 84/03/06. HARRISON,JJ Region 3, Diffice of Director 9pp 22605 001 24X Fiche 50~327,84/03/06, page 23020
- 8403130482 Advises that listed remedial soils work activities presently scheduled for Apr 1984 identified as critical work activities Appropriate details of listed activities requested to assist NRC in review HARRISON.J J Region S. Office of Director 84/03/06 QUAMME, D. L. Consumers Power Ca 4pp 22613 193 24X Fiche 50-329.84/03/06. B403130482
- B403i90098 Advises that PBACK eliminated from weekly distribution of summary of inspector training & personnel form printouts QUAMME.D L Consumers Power Co 84/03/06 BARANDM.8 Stone & Webster Inc 2pp 22669 302 24X Fiche. 50-329, 84/03/06. 8403i90098
- B403230114 Provides add1 info on scope of work required to support turbine roll test milestone as part of const completion program implementation QUANNE. D L Consumers Power Co 84/03/06 HARRISON, J J Region 3. Office of Director 7pp 22730 337 24X Fiche 50-329,84/03/06,8403230114
- 8403140032 Forwards "Pian to Conduct Independent Mgt Appraisal of Midland Nuclear Project." by Cresap, McCormick & Paget Appraisal will examine util approach for completing plant Certificate of 5 vc encl Related correspondence COOK, J W Consumers Power Co 84/03/07 KEPPLER, J O Region 3, Office of Director 4pp 22633 129 24x Fiche 50-327,84/03/07,84/0314032
- --840314003B "Pian to Conduct Independent Mgt Appraisal of Midland Nuclear Project " * Cresap, McCormick & Paget 84/03/07 73pp 22633:133 24X Fiche 50-329,84/03/07.8403140032
- 8403130153 Authorizes util to proceed w/Phase i const completion activities for listed plant modules.psr 840215 & 0306 requests Partial sys approved for Phase I activities located in module area also listed HARRISON, J. J. Region 3, Office of Director 84/03/08 QUAMME, D.C. Consumers Power Co. 3pp. 22601 262 24X Fiche 50-329,84/03/08,8403130153
- --8403130168 Submits addl info on scope of work required to support turbine roll test milestone, per 840215 ltr. Further definition of scape for seven Q-listed sys & description of const completion program process provided QUAMME.D L Consumers Power Co 84/03/06 HARRISON.J J Region 3, Gffice of Director 9pp 22601 267 24X Fiche 50-327, 84/03/08, 8403130153
- 8403200027 Requests authorization to proceed per work authorization procedures to excavate Lag Zones Y3 & Z3, install brace struts E10, E11, H10 & H11, install temporary support bracket at E1 & W1 & remove unacceptable backfill & casing. MODNEY, J A Consumers Power Co 84/03/08 HARRIBON, J. J. Region 3, Diffice of Director. ip 22699, 233 24X Fiche 50-329, 84/03/08, 240320027
- B403170180 Ack receipt of B40207 ltr indicating desire to discuss itsely operation date Cost, generating capacity & extent to which costs attributable to reasons beyond control of itemsee discussed KEPPLER. J & Region 3. Office of Director 84/03/09. BARAK. A J Hichigan. State of. 2pp 22671 144 24X Fiche. 50-329, 84/03/09, 8403190180

- --8403170186 Discusses 831028 ltr recommending deferring further Caseload Forecast Panel meetings Earliest completion date for Unit 2 not expected until months after Second Guarter 1986 & Unit 1 expected 6-7 months thereafter NOVAK.T M Assistant Director for Licensing 83/12/20 CODK.J W Consumers Power Co 4pp 22671 146 24X Fiche 50-327,84/03/09,840190180
- ---8403170192 Notifies that util seeking ratemaking treatment for plant Engineering consultants hired to prepare testimony re operation date.cost & generating capacity BARAK.A J Michigan. State of 84/02/07 KEPPLER.J G Region 3. Office of Director 2pp 22471 150 24X Fiche 50-329.84/03/09, 8403190180
- 8403200039 Requests authorization to proceed w/excavation & repair of frozen piping & excavation & installation load of redesigned E-17 HOCKEY. J A Consumers Power Co 84/03/09 HARRISON, J J Region 3, Office of Director. ip 22698 315 24X Fiche 50-329, 84/03/09, 8403200039
- 8403220025 Forwards 840305 memo re Unresolved Questions 47 & 48 from Memo DEB 330-83 for PGCI C-i 60.Rev 7
 BEAUDDIN.D E Consumers Power Co 84/03/12 FOTIADES.O R Stone & Mabater, Inc 2pp 22717 180 24X Fiche 50-327,84/03/12,
- 8402070041 Board Notification 84-050 provides Commission policy statement & proposed rolemaking on environ qualifications EISENHUT, D Q Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000,84/03/14,8402090041
- 8403200084 Authorites listed critical remedial soils work activities for Mar 1984 HARRISON J J Region 3, Office of Director 84/03/14 QUAMME, D L Consumers Power Co. 2pp 22685 274 24X Fiche 50~327,84/03/14, 840220084
- 8403220082 Authorizes listed remedial soils work activity for Mar 1984 HARRIBON-J Region 3. Office of Director 84/03/15 GUAMME, D L Consumers Power Co 2pp. 22716 265 24X Fiche 50-329, 84/03/15, 8403220082
- 8403220113 Forwards summary of independent design & const verification program 840313 meeting w/util & Govt Accountability Project in Betheeda. MD LEVIN.H A. TERA Corp 84/03/15 KEPPLER.J G Region 3, Office of Director COOK.J.H. Consumers Power Co EISENHUT.D O. Division of Licensing 37pp 22716 226 24X Fiche 50-327,84/03/15,8403220113
- 8403270009 Forwards listing of GA mpt audits for tracked info Item
 052

 # Consumers Power Co. 84403/15 | Stone & Webster, Inc. 200
- 4 Consumers Power Co 84/03/15 Stone & Webster, Inc 2pp 22769:353, 24X Fiche 50-329,84/03/15,8403270009
- 8403270014 Forwards summary of quality verification program mgt review 830601 meeting PALMER.8. Consumers Power Co. 84/03/19 Stone & Webster, Inc 14pp. 22770-029 24X Fiche 50-329.84/03/19.8403270014
- 840322010Q Notifies of eighth independent design & const verification program 840328 meeting w/util Isham.Lincoln & Beale.Govt Accountability Project & Midland Daily News to discuss status of confirmed items & findings LEVIN.H A TERR Corp 84/03/20 KEPPLER, J W Region 3. Dffice of Director EIBENHUT, D Q Division of Licensing COOK. J W Goneumers Power Co. Spp 22715-179 24X Fiche 50-329,84/03/20,8403220100
- 8403270157 Notifies of eighth OCR status review meeting on 840328 w/ util, BRW & StW in Ann Arbor, MI to discuss confirmed items & findings of independent design const verification program Agenda encl.

 LEVIN, H. A. TERA Corp 84/03/20, EISENHUT, D. O Division of Licensing KEPPLER, J. O. Region 3, Office of Director COOK, J W Consumers Power Co., Spp. 22769 157 24X Ficha 50-329, 84/03/20, 8403270159
- 8403300070 Forwards minutes of mgt raview for const completion plan quality verification program 830427 meeting Agenda & supporting documentation encl FALNER, B. Consumers Pawer Co 84/03/20 Stone & Webster, Inc 46pp. 22822

- 8403220007 Requests authorization to proceed w/work authorization Procedure 202550205, "Excavate Around Manhole 10 " GUAMME, D L Consumers Power Co 84/03/22 HARRISON, J J Region 3, Office of Director Ip 22713 362 24X Fiche 50-329, 84/03/22, 8403220007
- F Security, medical, emergency & fire protection plans
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Elsenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D G Division of Licensing 84/02/23 PALLADING Commissioners ip 22576 203 24X Fiche 50-000,84/02/23,8402090006
- --B4030803ió Recommends that info re fire research results concerning fires in electrical cabinets in Control room be submitted for board notification, per NRR Bfc Ltr 19, dtd B21001 Further evaluation of test data required.

 VOLLMER, R H Division of Engineering 84/02/06 EIBENHUT, D 0 Division of Licensing 10pp 22576 204 24X Fiche 50-000, 84/02/23, 8402090006
- 8403120103 Notifies of 840323 workshop on fire protection safe shutdown requirements of iOCFR30, App R in Rosemont; IL to discuss IE Info Notice 84-09 & provide addl shutdown analyses &/or mod guidance Agenda encl SPESSARD, R L Division of Emergency Preparedness & Operational Support 84/03/06 CODK, J W Consumers Power Co 3pp 22588 223 24X Fiche 50-329, 84/03/06, 8403120103
- O Adjudicatory correspondence
- 8403060073 Forwards list of audit repts dtd 840130-0202 Certificate of Svc encl Related correspondence BRUNNER, J E Consumers Power Co 84/02/29 BECHOEFER, C, HARBOUR, J : COMAN, F P Atomic Safety and Licensing Board Panel 4pp 22516 334 24X Fiche 30-327,84/02/29,8403060093
- 8403140119 Contention on Transamerica Delaval diesel generators re Model DSRV 12 Model cannot be relied upon to perform requisite safety function 8TAMIRIS. B Stamiris, B 84/03/04 Atomic Safety and Licensing Board Panel 3pp 22624 201 24X Fiche 50-329.84/03/04.8403140119
- 8403140075 Forwards DG Eisenhut 830810 ltr to BP Garde, per 830921 commitment W/o encl HABSELL, DF Hearing Branch 1 84/03/05 BECHHOEFER, C. COWAN, FP. HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 22633 081 24% Fiche 50-329, 84/03/05, 8403140075
- 8403140154 Forwards summaries of B20202-05 meeting & audit re auxiliary building underpinning.820316-i9 meeting & audit re soils remedial action & 831004-07 audit & meeting re HVAC sys HTLCOVE.M N Hearing Branch 2 84/03/05 BERNAGEI, L Government Accountability Project 2pp 22621 361 24X Fiche 50-329.84/03/05,8403140154
- B403150003 Forwards svc water pump structure crack survey rept Concurrence on mods to crack mapping program requested Details will be discussed at B400404 meeting Certificate of Svc enci Related correspondence MODNEY, J A Consumers Power Co 84/03/05 HARRISON, J J Region 3, Office of Director 30pp, 22824 116 24X Fiche 50-329,84/03/05, B403150003
- 8403120039 Advises that entire fireline excavation backfilled after physical connections made to restore fire svc to portions of site 8vc list encl Related correspondence BRUNNER.J E Carolina Power & Light Co 84/03/07 BECHHOEFER.C., COWAN.F F., HARBOUR.J Atomic Safety and Licensing Board Panel 3pp. 22389 271 24X Fiche.50-327.84/03/07.8403120039
- 8403130114 Order revising schedules for submittal of proposed findings & conclusions on GA/mgt attitude issues ASLB may issue separate partial initial decision on certain issues not encompassed by proposed findings on issues BECHHOEFER.C. Atomic Safety and Licensing Board Panel 84/03/i2 2pp 22615 295 24X Fiche 50-329.84/03/i2,84031301i4.
- 8403190166 Forwards Bechtel quality action rept supporting D Lewis testimony re buried control room pressurination pipe Corrosion caused by stray walding Currents not item of concern Svc list encl Related correspondence BRUNNER, J E Consumers Power Co 84/03/12 BECHHDEFER.C. HARBOUR.J. CURAN.FP Atomic Safety and Licensing Board Panel 7pp 22669 184 24X Fiche 50-329,84/03/12,8403190166

- 8403230031 Requests approval for release of insplactivity per NRC report disposition regardless of position of module action item Related correspondence GUARME. D. L. Consumers Power Co. DSB 072 84/03/13 HARRISON. J. J. Region 3. Office of Director 3pp 22724 335 24X Fiche 50-329 84/03/13.8403230031
- 8403200011 Proposes to defer response to Stamiris OL contention re Transamerica Delaval diesel generators until after receiving Stamiris ltr in support of timeliness of contention Proof of Svc enci GLOMEN B R Isham, Lincoln & Beale GILOMEN, B R Consumers Power Co B4/03/15 BECHHOEFER.C Atomic Safety and Licensing Board Fanel 3pp 22663 338 24x Fiche 50~329, 84/03/15,8403200011
- B403200139 Addendum to Stamiris contention on Transamerica Delaval.inc diesel generators addressing late filing factors of 10CFR2 714 STAMIRIS B Stamiris, B 84/03/15 Commissioners 2pp 22699 136 24X Fiche 50-329, E4/03/15, E403200137
- B403270020 Proposes to defer response to Staminis 840304 contention re Transamerica Delavai diesel generators Proof of Svr encl GILCHEM.B R Jeham. Lincoln & Beale O'LLOMEN.B R Consumers Power Co DSB 110 84703/15 BECHMOEFER.C Atomic Safety and Licensing Board Panel 3pp 22766 360 24X Fichs 50-329.84/03/15.8403270020
- 8403220246 Order setting time for responses to 8 Stamiris 840304 motion as if 840313 addendum was original filing date Served on 840322 BECHOEFER.C Atomic Safety and Licensing Board Panel DSB 059 84/03/21 Office of the Escutive Legal Director 2pp. 22719 049 24% Fishe 50-329.84/03/21.8403220244
- 8403280348 Order extending time until 840425 for Commission to act to review Director's Decisions DD-83-16 & DD-84-2 Served on 840328 CHILKS J Office of the Secretary of the Commission USB 158 84/03/27 Commissioners lp 22787 143 24X Fiche 50-327,84/03/27,0403280348

I Financial information

- 8403190071 Annual Financial Rept for 1983 W/840312 ltr SELBY. J D. FOLMEE. J B. PERRY.P. A. Consumers Power Co. 83/12/31 OIAMBUSSD. A. Division of Licensing 34pp 22666 136 24X Fiche 50-000.83/12/31.8403190071
- G Inspection reports. IE Bulletins & correspondence
- 8401230630 Partial response to FOIA request for IE 800103 rept re review of mati false statement at facilities associated to supporting records to rept to repts prepared in response Forwards App A documents Review of addl records in progress FELTON. J M Division of Rules and Records 83/11/01 HINSLOW.R Wall Street Journel 2pp 21905 337 24X Fiche 50-329,83/11/01.8401230630
- 8403070229 Partial response to FDIA request for repts re NRC investigation of failure of reactor vessel holddown studs on Unit I reactor vessel Forwards App A & B Gocuments FELTON, J M Division of Rules and Records 84/02/23 PLATO, E D Kohl, Secrest, Wardle, Lynch, Clark & Hampton 6pp 22564 149 24X Fiche 50-329,84/02/23,8403070229
- --8403070343 Forwards IE insp Repts 50-329/80-12 & 50-330/80-13 on 800301-31 No noncompliance noted Major areas inspected eram of procedures & representative records.observations & intervieus w/personnel W/o encl FIORELLI, G Region 3. Chicago, Office of the Director 80/05/19 HOMELLI, B H Comsumers Power Co 2pp 22564 170 24x Fiche 50-329, 84/02/23, 8403070229
- --8403070351 Responds to 830901 itr & forwards IE Investigation Repts 30-329/80-13 & 50-330/80-14 H/o encl LEMIS.5 H Region 3. Office of Director 83/09/20. MYERS, T F Garan, Lucow, Hiller, Seward, Cooper & Becker 1p 22544 263 24% Fiche 50-329.84/02/23,8403070229
- 8401170072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl.
 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22709 237 24X Fiche 50-000,84/02/28,8401170072
- BA03130297 Advises that const implementation overview performed sampling insp of const training records for personnel Results satisfactory KARRJ E Gtons & Hebster, Inc 84/02/29 GVAMME, D L Consumers Power Co 19 22417 233 24X Fiche 50-329, 84/02/29, 8403130297

- E4030A0385 Forwards IE Monthly Meeting Ropts 50-329/64-05 & 50-329/64-05 on 840209 MARNICK.R F Region 3, Office of Director 84/03/01 COOK, J W Consumers Power Co 2pp 22507 004 24X Fiche 50-329,84/03/01,8403060385
- --8403060398 IE Monthly Meeting Repts 50-327/84-05 & 50-330/84-05 on 840209 Major topics discussed crack mapping EPA jacking toads & US Testing audit corrective action status GARDNER, R N, HARRISON, J J Region 3, Office of Director 84/02/29 Spg 22507 006 24% Fiche 50-327,84/03/01.8403060385
- --B403060407 Forwards minutes of Feb 1984 monthly third-party assessment meeting re underpinning & remedial soils work LUCKGLAS Brane & Webster, Inc. B4/02/21, HARRISON, J J Region 3, Office of Director 21pp 22507 011, 24X Fiche 50-329,84/03/01.8403060385.
- --8403060415 Forwards Independent Assessment of Underpinning Weskiy Rept 68 for 840101-07 LUCKS:A 8 Stone & Hebster: Inc 84/02/12 COOK:R NRC - No Detailed Affiliation Given 11pp 22507 032. 24X Fiche 50-329.84/03/01.8403060385
- --8403060420 Forwards Independent Assessment of Underpinning Weekly Rept 69 for 840108-14 LUCKS.A S Stone & Webster. Inc. 84/01/17 COOK.R NRC - No Detailed Affiliation Olven 13pp 22307 043 24X Fiche 50-329,84/03/01.8403060383
- --8403060423 Forwards Independent Assessment of Underpinning Weekly Rept 70 for 840115-21 LUCKS:A S Stone & Webster: Inc 84/01/25 COUK.R NRC - No Detailed Affiliation Civen 14pp 22307 038 24X Fiche 50-329,84/03/01,8403060383
- --8403060428 Forwards Independent Assessment of Underpinning Waskly Rept 71 for 840122-28 LUCKS.A S Stone & Webster, Inc. 84/02/02 COOK.R NRC - No Detailed Affiliation Given 16pp 22507 072 24X Fichs 50-329.84/03/01.8403040385
- --B403060442 Forwards Const Implementation Overview Weekly Rept 31 for 840109-13 KARRJE Stone & Webster, Inc. 84/01/18 KEPPLER, J.G. Region 3. Office of Director 17pp 22507 100 24X Fichs 50-329,84/03/01,8403060385
- --8403060444 Forwards Const Implementation Overview Weekly Rept 32 for 840116-20 KARR: J E Stone & Webster, Inc 84/01/27 KEPPLER, J O Region 3, Office of Director 20pp 22507 117 24X Fiche 50-329,84/03/01,8403060385
- --8403060445 Forwards Const implementation Overview Weekly Rept 33 for 840123-27 KARR-JE Stone & Webster, Inc 84/02/01 KEPPLER, J G Region 3. Office of Director, 17pp 22507 137 24X Fiche 50-329.84/03/01/8403060385
- B402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Evc list encl CRACE, J N Division of GA. Safeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24x Fiche 50-000,84/03/02,8402090007
- B402090000 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate." Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 2253 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 64-15, "Reporting of Radiological Releases "
 Svc list encl
 JORDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp. 22553 217 24X Fiche 50-000,84/03/02,8402090009.
- B403060288 Authorizes util to Jack Piers CTI & CTI2 as long as auxiliary bldg differential movement controlled according to 840104 agreement documented in IE Insp Repts 50-329/84-01 & 50-320/84-01 HARRISON J Region 3, Office of Director 84/03/02 QUANTE, D. Consumers Power Co ip 22519 168 24X Fiche 50-329, 84/03/02, 8403060288
- 8403130254 Forwards RC Sember 840223 memo re MPGAD insp evaluation & Overinsp Audit MSA-84-5 Overinsp Audit MSA-84-5 VGKAL.D J Consumers Power Co 84/03/02 Stone & Webster, Inc Rpp 22606 054 24% Fiche 50-329,84/03/02,8403130254

- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below N11 Ductility Yemp "Suc list encl JORDAN E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05,8402090011
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc 11st encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07.8402070024
- B40209002B IE Info Notice 84-1B, "Stress Corrosion Cracking in PWR Bys " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000.84/03/07,8402090028
- B40207003i IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety 80s " Svc list enc!
 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823 094 24% Fiche 50-000,84/03/12,8402070031
- B403220016 Submits summary of Bechtel investigation & corrective actions to resolve Issue of nonconforming matl supplied by Tube-Line Corp. in response to IE Bulletin 83-06 Final response expected by 840615 CDDK.J W Consumers Power Co 84/03/12 KEPPLER.J O Region 3: 0Ffice of Director 2pp 22712 339 24X Fiche 50-329.84/03/12.8403220016
- 8403270199 Submits resolutions to concerns addressed in 840110 ltr re hanger reinesp program Computer listing of hangers evaluated against commodity list to determine base number of hangers in program submitted QUAMME.D L. Consumers Power Co. 84/03/15 KARR, J.E. Stone & Webster. Inc. 2pp. 22770 291 24X Fiche 50-329,84/03/15,8403270199
- 8402090043 IE Info Notice 84-19, "Two Events Invoiving Unauthorized Entries into PWR Reactor Cavities " Svc ilst encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- B4D2090044 IE Info Notice 84-20, "Svc Life of Relays in Sefety-Related Bys " Svc List and JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche, 50-000, 84/03/21, 8402090044
- R. Periodic operating reports & related correspondence
- B403070008 Forwards monthly rept for Jan 1984, per ALAB-106, including Bechtel honconformance rept, Bechtel FSO nonconformance rept, Bechtel guality action requests, Bechtel mgt corrective action repts & Bechtel GA findings COOK, J W Consumers Fower Co 84/02/25 DEYQUNO, R C Director's Office, Office of Inspection and Enforcement 2530pp 22527 010 24X Fiche 50-329, 84/02/25, 8403070008
- 8403220013 Forwards monthly status rept for Fab 1984 Monthly OCR/finding status review meeting scheduled for 840328 in Ann Arbor, Al LEVIN.H A TERA Corp 84/03/16 EISENHUT, D 0 Division of Licensing. KEPPLER, J 0 Region 3, Office of Director COCK, J W Consumers Power Co 3pp. 22713 285 24X Fichs 50-329,84/03/16,8403220013.
- --8403220022 "Midland Independent Design & Const Verification Program Monthly Status Rept Number 10 for Feb 1984 " DOUGHERTY: F A TERA Corp 84/03/16 54pp 22713 288 24X Fichs: 50-329,84/03/16,8403220013
- B403270062 Forwards "Const Implementation Overview (CIO)," Weekly Rept 39 for 840305-09 KARRIJE Stone & Webster, Inc. 84/03/16 KEPPLER, J. G. Region 3. Dffice of Director. 17pp 22766 088 24X Fiche 50-329,84/03/16, 8403270062.
- B403230043 Forwards menthly status rept for Midland project for Feb 1984. WARNICK.R. F. Region 3, Office of Director 84/03/19 KEPPLER, J 0 Region 3, Office of Director ip 22728, 351 24X Fiche, 50-329, 84/03/19, 8403230043.
- --8403230046 Forwards monthly status rept for Midland project for Feb 1784. COUK,R J Region 3, Office of Director 84/03/15 WARNICK,R F Region 3, Office of Director 2pp 22728 352 24X Fiche: 50-329,84/03/19,8403230043

- S Reportable occurrences. LERs & related correspondence
- 8401230430 Partial response to FOIA request for IE 800103 rept re review of mati false statement at facilities, associated & supporting records to rept & repts prepared in response Forwards App A documents Review of addi records in progress FELTON.J M Division of Rules and Records 83/11/01 WINSLOW, R Wall Street Journal 2pp 21505 337 24x Fiche 50-329,83/11/01,8401230630
- --8401230660 PNO-79-039 on 790305, investigation concluded that QA program for obtaining proper soil compaction of facility deficient excessive settlement observed widlesel generator bldg & incorrect info re soil foundation contained in FSAR SHEWMAKER, R E , HENDERSON, J B , THORNDURG, H D Office of Inspection & Enforcement, Office of the Director 79/03/06 2pp 21905 352 24X Fiche 50-329,63/11/01,8404230630
- 8403070226 FOIA request for repts re results of investigation of failed reactor vessel bolddown studs on Unit 1 reactor vessel PLATO.E D Kohl, Secrest, Mardle, Lynch, Clark & Hampton 84/01/23 KEPPLER.J O Region 3, Office of Director 2pp 22564 147 24X Fichs 50-329,84/01/23,8403070226
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval, Inc DIRCKS W J Office of the Executive Director for Operations 8ECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000, 84/01/25, 8403010451
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 T&T valve, to close Enci itr d&d 840203 sent to listed utils GE notified of affected units in DWR plants
 THEROUX.R R Terry Corp 84/02/22 WDODRUFF.R W Director's Office, Office of Inspection and Enforcement 6pp 22706-327 24X Fiche 30-000.84/02/22.8403210032
- 8403060269 Interim deficiency rept re nonconservative design of embedments in concrete using shear lugs located in tension rones Next rept expected by 840601 CODK.J W Consumers Power Co 84/02/24 KEPFLER.J O Region 3. Office of Director App 22515 201 24X Fiche 50-329.84/02/23. 8403060269
- 8403070229 Partial response to FOIA request for repts re NRC investigation of Failure of reactor vessel holddown stude on Unit 1 reactor vessel Forwards App A & B documents FELTON, J M Division of Rules and Records 84/02/23 PLATO, E D Kohl. Becrest, Wardle, Lynch, Clark & Hampton 6pp 22564 149 24X Fiche 30-329,84/02/23,8403070229
- --B403070340 Ack receipt of 771214 interim rept re broken anchor boit in reactor vessel support skirt flange.
 FIDRELLI,0 Region 3, Chicago, Dffice of the Director 79/12/26 HOMELL,6 H Consumers Power Co 10pp 22564 158 24% Fiche 50-329,84/02/23,8403070229
- --8403070345 Recommends order be issued to util requiring action to correct unacceptable anchor bolts at facility Draft ltr & order enc! KEPPLER.J 0 Region 3. Chicago, Office of the Director 80/06/27 THOMPSON.D Executive Officer for Operations Support 36pp 22364 172 24X Fiche 50-329,84/02/23,8403070329
- --8403070349 Forwards depositions re preservice failure of reactor vessel studs utilized at Unit 1 Related Info enc1
 LEWIS.5 H Region 3. Office of Director 84/01/06
 BERKOUTT2.D M Office of the General Counsel 52pp 22564 264
 24X Fiche 50-329,84/02/23,8403070229
- B403Q40104 Interim deficiency rept to B&W steam generator auxiliary feadwater header dasign change Unit 2 changes should be completed by 840229 Work on Unit 1 suspended due to delays in startup dates
 COOK, J W Consumers Power Co 84/02/24 KEPPLER, J G Region 3, Office of Director 3pp 22517 015, 24X Fiche 50-329,84/02/24,8403040104
- 8403060272 Interim deficiency rept re nonconforming electrical raceway sys. Adverse effect of deficiencies on safety of plant operation unlikely Rechtel revised final Rept MCAR 70 encl Next rept will be submitted by 840608 CDDK, J.W. Consumers Power Co. 84/02/24. KEPPLER, J.G. Region 3, Office of Director 7pp. 22917-066 24X Fiche. 50-329, 84/02/24, 8403060272
- 8403060411 Forwards signed afficavit & resume of Z Ziiak assigned to const implementation overview staff KARR, J E Stone & Webster, Inc 84/02/24 HARRISON, J J Region 3, Office of Director Spp 22511.347 R4X Fiche 50-327,84/02/24, 8403060411

- 8403080026 Forwards rept on 840210 exit meeting w/Bechtel & NRC re indiscriminate cable substitutions • Consumers Power Co 84/02/24 Stone & Webster Engineering Corp 3pp 22557 243 24X Fiche 50-327,84/02/24 8403080026
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval. Inc Dumers Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations MUSELER. H. J. TDI (Transamerica Dulaval, Inc.) Dumers Group 84/02/27 DENTON.H R. Office of Nuclear Reactor Regulation. Director 3pp 22434 090 24X Fiche 80-000.84/02/27.8403010207
- 8403080245 Confirms that listing of open nonconformance repts, sorted by issue date given to D Brown on 840221 GUANNED L Consumers Power Co. 84/02/27 BARANGH. S Stone & Hebster, Inc. 3pp 22561 006 24% Fiche 50-329,84/02/27,
- 8403130074 Forwards closed Monconformance Identification Rept NIR-018 re training record discrepancies not in tompliance w/requirements of FPO-2 ODO/Rev 7, "Training of Const Personnel"

 KARR, J.E. Stone & Webster, Inc. 84/02/27 QUAMME, D.L. Consumers Power Co. 3pp. 22615 219 24X Fiche 50-329,84/02/27,8403130074
- B402090021 Board Notification B4-039 discusses NRC 840210 & 16 meetings w/Transamerica Delayal, inc Emergency Diesel Ganerators Owners Group Meeting scheduled on B40308 for finalization of generic program plan prior to NRC review EISEMBUT, D.G. Division of Licensing 84/02/28 PALLADIND, GILINBKY, ROBERTS Commissioners 5pp 22946 003 24X Fiche 50-000, 84/02/28, 8402090021
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval. Inc emergency diesel generators MUSELER. W. J. TDI (Transamerica Delaval. Inc.) Owners Group 84/02/28 DENTON. H. R. Office of Nuclear Reactor Regulation. Director 42pp 22435 177 24X Fiche 50-000.84/02/28.8403010218
- 8403080171 Forwards requested list of items determined to be ready for review & closure by NRC Items marked by asterist reviewed by Region III inspectors & will be removed from list when closed in insprept CODK. J W Consumers Power Co 84/02/28 KEPPLER. J C Region 3. Office of Director 16pp 22559 278 24X Fiche 50-329.84/02/28. 8403080171
- B403080187 Forwards response to Tracked Info Item 054 requesting MTC GA manual quality plan program manual procedures & target list utilized at 61te & walkdown summaries 14suse to date # Consumers Power Co 84/02/28 Stone & Mebster, Inc 2pp 22559 112 24X Fiche 50-329.84/02/28.8403080187
- 8403080192 Advises that sampling insps of tonet training records of personnel complete Results of Insp satisfactory & NIR-018 closed Personnel listed on encis cleared to perform status assessment W/o enci KARR. J E Stone & Webster, Inc 84/02/28 QUAMME, D L Consumers Power Co 1p 22537 201 24% Fiche 30-329,84/02/28.8403080192
- 8403080235 Lists audit finding repts.Including MSA-83-7-04F,01F & M01-603-03-02

 * Consumers Power Co 84/02/28 Stone & Webster, Inc 1p 22360 124 24% Fiche 50-329,84/02/28,8403080235
- 8403130173 Forwards closed const implementation overview. Item 035 re dielectric isolation spacers for galvanic protection of copper pipe to galvanized steel pipe supports missing in some dreas
- some areas KARR.J E Stone & Webster, Inc 64/02/28 QUAMME.D L Consumers Power Co 29pp 22599 194 24x Fiche 50-329,84/02/28,8403130173
- B402090020 Board Notification B4-044 forwards Part 21 rept re Transamerica Delaval.Inc turbocharger thrust bearing Lubrication defect resulting in engine nonavallability EISENHUT, D 0 Division of Licensing 84/02/29 PALLADIND Commissioners 4pp 22541 243 24X Fithe 50-000, 84/02/29, 8402090020
- B403080221 Forwards Nunconformance Identification Rept 019 On 840222, field deviation disposition list not revised to reflect changes for Specs M-1A & C-304 MARR.J & Stone & Webster, Inc. 84/02/29 GUANME, D L. Consumers Power Co. 2pp 22560 022 24% Fiche 50-329,84/02/29.8403080221
- 8403080247 Forwards complete response to Const Implementation Overview Item 056 re inconsistencies noted during evaluation of training for PCCI C-1 50 e Consumers Power Co 84/02/29 Stone & Webster, Inc 4pp 22561 019 24X Fiche 50-327,84/02/29,84030300247

ı `\

- 8403080250 Forwards closed Const Implementation Overview Itam 054 re Mark Technologies Corp GA & quality program plan manuals, procedures & target list MARR.J E Stone & Webster, Inc 84/02/29 QUAMME.D L Consumers Fower Co 3pp 22561 016 24X Fiche 50-329,84/02/29,8403080250
- 8403080259 Forwards complete response to Const Implementation Overview Item 037 re trainer evaluation ** Consumers Power Co 84/02/29 Stone & Webster, Inc 4pp 22557 its 24X Fiche 50-329.84/02/29.8403080259
- 8403130210 Forwards closed QAR RT-00021 which provides complete response to Nonconformance Identification Rept NIR-008 retraining matrix

 * Consumers Power Co 84/02/29 Stone & Mebster, Inc 6pp 22605.057 24X Fiche 50-329,84/02/29,8403130210
- 8403060385 Forwards IE Monthly Meeting Repts 50-329/84-05 & 50-330/84-05 on 840207 WARNICK, F. F. Region 3. Office of Director 84/03/01 COCK, J. W. Consumers Power Co. 2pp. 22507 004 24X Fiche 50-329, 84/03/01, 840300385
- --8403060407 Forwards minutes of Fab 1984 monthly third-party assassment mesting to underpinning & remedial soils work LUCKS:A S Stone & Webster: Inc 84/02/21 HARRISON, J Region 3. Office of Director 21pp 22507 011 24X Fichs 50-329,84/03/01,8403060385
- --8403060415 Forwards Independent Assessment of Underpinning Weekly Rept 68 for 840101-07 LUCKB:A 8 Stone & Webster, Inc. 84/02/12 CDOK,R NRC - No Detailed Affiliation Given 11pp 22507 032 24X Fiche 50-329.84/03/01.8403060385
- --8403060420 Forwards Independent Assessment of Underpinning Weskly Rept 67 for 840108-14 LUCKB.A S S Stone & Webster, Inc. 84/01/17 CDOK.R NRC - No Detailed Affiliation Given 15pp 22507 043 24X Fiche 30-329,84/03/01.8403060385
- --8403060423 Forwards Independent Assessment of Underpinning Weekly Rept 70 for 840115-21 LUCKBA 8 Stone & Webster, Inc 84/01/25 COOK, R NRC - No Detailed Affiliation Olven 14pp 22507 058 24X Fiche 50-329)84/03/01.8403060385
- --8403060428 Forwards Independent Assessment of Underpinning Weskly Rept 71 for 840122-28 LUCKB.A S Stane & Webster. Inc 84/02/02 COOK.R NRC - No Detailed Affiliation Oiven 16pp 22507 072 24X Fiche 50-329,84/03/01.8403060385
- --8403060442 Forwards Const Implementation Overview Washly Rept 31 for 840109-13 KARR,J E Stone & Wabster, Inc. 84/01/18 KEPPLER,J G Ragion 3. Office of Director 17pp 22507 100 24X Fichs 50-329,84/03/01.8403060385
- --8403060444 Forwards Const Implementation Overview Weekly Rept 32 for 840116-20 KARR, J E Stone & Webster, Inc 84/01/27 KEPPLER, J Q Region 3, Office of Director 20pp 22507 117 24X Fiche 50-329, 84/03/01, 8403040385
- --8403060445 Forwards Const implementation Overview Weekiy Rept 33 for 840123-27 KARR, J. E. Stone & Webster, Inc. 84/02/01 KEPPLER, J. O. Region 3. Office of Director 17pp 22507 137 24X Fiche 30-329,84/03/01.8403060385
- B403130195 Forwards closed const implementation overview Item 037 retraining classes KARR.J E Stone & Hebster, Inc 84/03/01 QUAMME.D L. Consumers Power Co 5pp 22617 307 24X Fiche 50-329.84/03/01.8403130195
- B403080222 Interim deficiency rept re coordination of engineering holds & restrictions resulting in installation of unqualified Essex cables Cables will be replaced Interim or final rept expected by 940504 CODK, J & Consumers Power Co 84/03/02 KEPPLER, J C, Region 3, Office of Director &pp 22541 025 R4X Fiche. 50-329, 84/03/02, 8403080222
- 8403130050 Forwards closed Audit Finding Repts MSA-83-25-02F, MSA-83-25-10F & MSA-83-25-03F & closed Unresolved Item Repts MSA-83-25-09U & MSA-83-25-07U VORAL.D J Consumers Power Co 84/03/02 Stone & Webster, Inc 12pp 22608.094 24X Fiche 50-329,84/03/02,8403130050.

- 8403130184 Forwards Nonconformance Identification Rept 020 re unsigned
 - Change request forms

 KARR.J.E Stone & Webster, Inc 84/03/02 QUAMME.D L Consumer

 Power Co 2pp 22617 234 24X Fiche 50-329,84/03/02,8403130184 Consumers
- 8403130292 Forwards Audit Rept MSA-83-39 W/o encl VOXAL,D J Consumers Power Co 84/03/02 Stone & Webster, Inc 1p 22614 149 24X Fiche 50-329.84/03/02.8403130292
- 8403130321 Forwards Const Implementation Overvisw Hold Point Notification Itsm OdI re subcontract document control for action. Recommands form be revised to provide signature & dets space for recipient

 KARR, J E Stone & Webster, Inc 84/03/02 GUAMME, D L Consums

 Power Co 2pp 22614 130 24X Fiche 50-327, 84/03/02, 8403130321 Consumers
- 8403140049 Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval. Inc Diesel Cenerators Comers Group Program Plan," to resolve concerns w/smergency diesel generators MUSELER.W J Long Island Lighting Co 84/03/02 DENTON, H R Dffice of Nuclear Reactor Regulation. Director 2pp 22626 062 24X Fiche 50-000,84/03/02,8403140048
- --8403140095 "Transamerica Deiaval, Inc Diesei Generators Owners Group Program Plan " * TDI (Transamerica Delavai, Inc.) Owners Group 84/03/02 261pp 22628 223 24X Fiche.50-000,84/03/02,8403140048
- 8403130161 Forwards, for info.closed Quality Action Request GAR-RT-00020 used to track const implementation overview Nonconformance Identification Rept NIR-007

 **Consumers Power Co. 84/03/05 Stone & Webster, Inc. 10pp. 22599'298 24% Fiche 50-329.84/03/05.8403130161
- 8403130362 Forwards partial response to Tracked Action Item 043, consisting of pre- & post-stop work order activities. DDR implementation, site-wide distribution plan implementation schedule & corrective action plan W/o encis REICHEL,N I Consumers Power Co. 84/03/05, Stone & Webster, Inc 1p. 22616 269 24X Fiche 50-329,84/03/05,8403130362
- 8403130479 Forwards Const Implementation Overview, Item 048 re inconsistency between spec requirements on spacing between anchor bolts of different diameters Bechtel preparing spec change notice. KARR, J. E. Stone & Webster, Inc. 84/09/05 KEPPLER, J. Q. NRC - N. Detailed Affiliation Given. QUAMME, D. L., REICHEL, N. I. Consumers. Power Co. 3pp. 22613, 228. 24X Fiche 50-329, 84/03/05, 8403130479. NRC - No
- B40313023B Forwards Const Implementation Overview Item 062 re training classes Btatus assessment performed on pipe supports by personnel w/incomplate required training KARR.J.E Stope & Webster, Inc. B4/03/06. KEPPLER,J.9 Region 3, Diffice of Director 3pp 22606 057 24X Fiche 50-329,84/03/06, RA0310328
- 8403130354 Forwards completed response to Tracked Action Item 048 consisting of Spec Change Notice 14001 to Spec C-306 re grouted anchor bolts
 REIGHEL, N I Consumers Power Co 84/03/04 PA---LIN I Consumers Power Co 84/03/06 Stons & Webster, inc 22616 330 24% Fiche 50-329,84/03/06,8403130354
- 8403130491 Requests extension to 840309 for responding to Tracked Info Items 058 & 059 & Tracked Recommendation Item 060 REICHEL,M.I. Consumers Power Co 84/03/06 Stone & Wabster, Inc ip 22613 180, 24X Fiche 50-329, 84/03/06,8403130491
- 8402090033 Board Notification 84-047 forwards Transamerica Delaval, Inc ODVOYDOOS Board Notification 84-047 forwards Transamerica Del Dwises Group piston skirt rept & task descriptions EIEENHUT, D. O Division of Licensing 84/03/07 PALLADING, OILINGKY, ROBERTB Commissioners 4pp 22674, 221 24X Fiche: 50-000, 84/03/07, 8402070033
- 8403130271 Informs that response to Nonconformance Insp Rept 008 satisfactory Const implementation overview will continue to monitor training commitments w/emphasis on listed areas. KARR, J. E. Stone & Webster, Inc. 84/03/07 0404MME,D L. Consum: Power Co 1p 22614-175 24X Fiche: 50-329, 84/03/07, 8403130271
- 8403140122 Part 21 rept re status update concerning abnormal wear on linear converters. Test program underway Results of investigation indicate excessive wear caused by hunting of investigation indicate excessive wear caused becoming interpolicy.
 DOBBON, J.P. Pacific Air Products Co. 84/03/0
 Office, Office of Inspection and Enforcement
 Fiche 30-000,84/03/09,8403140122 Director's
 7pp 22454 84/03/09 22624'068 24X

- 8403220072 Forwards listed documentation re post-weld heat treat thermocouples Bechtel in contact w/suppliers to obtain replacements W/o encl
 * Consumers Fower Co 84/03/09 SMITH, A Stone & Webster, Inc ip 22712 310 24X Fiche 50-329,84/03/09,8403220072
- 8402090038 Board Notification 84-051 forwards "Transamerica Dalayai, Inc (TDI) Diesei Generators Owners Group Program Plan " EISENHUT,D O Division of Licensing 84/03/12 PALLADING, GILINSKY, ROBERTS Commissioners Jpp 22688 214 24X Fiche 50-000 84/03/12,8402090038
- B402090037 Board Notification B4-032 forwards meeting summaries containing transcripts of B40210 & 16 meetings between NRC & Transamerica Delaval.Inc (TDI) Owners Group Distribution list encl EISENHUT D G Division of Licensing 84/03/12 PALLADI GILINSKY, ROBERTS Commissioners 5pp 22708 001 24X Fichs 50-000,84/03/12,8402090039
- --BA03060536 Forwards summary of 840210 meeting w/Transamerica Dejaval. Inc Owners Group in Bethesda.MD re-problems w/emergancy dissel generators
 CARUSD.R Licensing Branch 2 84/02/27 O'REILL)
 Detailed Affiliation Given opp 22708 006 24X
 Fiche 50-000,84/03/12,8402090037 O'REILLY, J P NRC - No
- --8403060354 Transcript of 840210 meeting w/Transamerica Dilavai.Inc Owners Group in Bethesda.MD re probisms w/emergency diesel generators # NRC - No Detailed Affiliation Given 84/02/10 147pp 22708 012 24X Fiche 50-000,84/03/12,8402070037
- --8403070407 Summary of 840216 meeting w/Transamerica Delaval, inc Owners
 Group in Wading River, NY re program plan to establish
 reliability of diesel generators Agenda, meeting transcript &
 attendance list snci
 MILLER, M A Licensing Branch 4 84/02/27 Licensing Branch 4
 8pp 22708-161 24X Fiche 50-000.84/03/12,8402090039
- -8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval, Inc diesel generatore Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000,84/03/12,8402090039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Sheiis for Transamerica Deiavai Enterpriss Engines" for Shoreham & Orand Gulf diesel generators MUSELER, W. J. Long island Lighting Co. 84/03/12 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 22632 074 24X Fiche 50-000,84/03/12,8403140050
- B403180133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept." Capscrew design adequate for applicable engines & svc conditions MUSELER,W J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000,84/03/13,8403150133
- 8403270169 Forwards, for info, Quality Action Requests (GARs) RA-00134 & RA-00135 to assign action & track const implementation overview (GIO) NIRs 019 & 020 on MPGAD GUAIL, sys CIO will evaluate satisfactorily closed out QARs to close out NIRs * Consumers Power Co 64/03/14 Stone & Webster, Inc App 22771 138 24X Fiche 50-329.84/03/14.8403270169
- 8403270023 Informs that ail G redline drawings incorporated.per Hold Point OOL.Rept 6 * Consumers Power Co 84/03/15 Stone & Webster, inc 2pp 22770 067 24% Fichs 50-329.84/03/15.8403270023
- 8403270029 Forwards response to Tracked Info Item 055 re training matrix status assessment requirements # Consumers Power Co 84/03/15 Stone & Hebster, Inc 11pp 22769 328 24% Fichs 50-329.84/03/15,8403270029
- 8403270227 Forwards open Const Implementation Overview Itsm 063 restatus assessment in Moduls 120D on 840313 using unmarked FSK prints

 KARR, J E Stone & Wasster, Inc 84/03/15 KEPPLER, J G NRC Notatied Affiliation Given REICHEL, N I , WELLS, R A Consumers Power Co 3pp 22772 081 24X Fichs 50-329, 84/03/15, 8403270227 NRC - No
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series angines List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started MATHEMB, C B Transamerica Delavai, Inc 84/03/16, EISENHUT, D Q Division of Licensing 20pp 22691 179 24X Fiche 50-000,84/03/16,8403200222

- B403220067 Interim deficiency rept ro low alloy quenched & tempered bolting 1 5-inches & greater in support of safety-related sys Current status of Bechtel matl evaluation encl Next rept will be sent by B40727 COOK.J W Consumers Power Co B4/03/i6 KEPPLER.J O Region 3. Defice of Director 10pp 22716 150 24X Fiche 50-329,84/03/16. B4003290647
- 8403220108 Interim deficiency rept to defective capstan springs in mechanical shock arrestors supplied by Pacific Scientific Arrestors being evaluated & tested Nert rept by 840504 CDDK.J W Consumers Power Co 84/03/16 KEPPLER.J C Region 3. Office of Director 17pp 22716 180 24X Fiche 50-327.84/03/16. 8403220108
- B403270062 Forwards "Const implementation Overview (CIO)," Weekly Rept 39 for 840305-07 KARR.J E Stone % Webster, Inc. 84/03/16 KEPPLER.J G Region 3. Office of Director 17pp 22766 086 24X Fiche 50-329.84/03/16. B403270062
- 8403270076 Forwards const implementation overview for Items 064.065 & O&6 re CW-1 00, "E-Series" PDCI's.Zack Procedure MB-FF-7C & Zack Procedure MB-FF-18 Welding insp requirements deleted & spec change notice recommended KARR, JE Stone & Webster, inc 84/03/16 KEPPLER, J @ NRC No Detailed Affiliation Given REICHEL, N I Consumers Power Co QUAMME, D L Stone & Webster, Inc 4pp 22766 356 24X Fiche 50-327.84/03/16,8403270076
- 8403270093 Forwards Closed Const implementation Overview item 056/Hold Point Notification re Checklist MP-MIS-008E-0001 Review of items re impact on training requested KARR.JE Stone & Webster, Inc. 84/03/19 KEPPLER.J O NRC No Detailed Affiliation Given REICHEL.N 1 . GUAMME.D L. Consumers Power Co Spp 22769 358 24% Fiche 50-329.84/03/19.8403270093
- 8403270236 Forwards DF Ronk B40315 memo to JT Christy & attachments showing planned weekly menhour allocations for PGCI & areas for wks of 640323.30 & 0406 W/o encl RONK, DF Consumers Pawer Co. 844/03/19 BAUMGARINER, T Stone & Webster, Inc. 1p 22771 347 Z4X Fiche 50-329.84/03/19.8403270236
- 8403300006 Forwards Closed Const Implementation Overview Item 052 re Criterion XVIII site auditing KARR: J E Stone & Webster, Inc 84/03/20 KEPPLER: J G NRC - No Detailed Affiliation Given GUMME: D L . REICHEL: N 1 Consumers Power Co 3pp 22822 126 24X Fiche 50-329:84/03/20.8403300006
- 8403300035 Forwards proposed project records classification code list b mgt policy for review KARR.J E Stone & Webster Engineering Corp 84/03/20 GUAMME.D L. Consumers Power Co 8pp 22821 312 24X Fiche 50-327,84/03/20,8403300035
- 8403270132 Forwards "Emergency Diesel Generator Alr Btart Valve Capacrew Dimension & Stress Analysis," prepared by 55W for Transamerica Delaval Inc (TDI) Diesel Generator Owners Group MUSELER.H J TDI (Transamerica Delaval, Inc.) Dwners Group B4/03/23 DENTON.H R Gffice of Nuclear Reactor Regulation, Director 2pp 22774 001 24% Fiche 50-000.84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica
 Delaval dissel generators List of suggested meeting topics
 enci
 MCGAUGHY, J P IDI (Transamerica Delaval, Inc.) Owners Group
 84/03/23 DENION.H R Office of Nuclear Reactor Regulation,
 Director 4pp 22769 133 24X Fiche 50-000,84/03/23,8403270134
- T Hearing transcripts on non-antitrust matters
- B402098039 Board Notification 84-052 forwards meeting symmarles containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval.Inc (TD1) Guners Group Distribution list encl
 EISENHUT.D G Division of Licensing 84/03/12 PALLADIND Commissioners 5pp 22708 001 24% Fiche 50-000,64/03/12.
- --8403060336 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, HD re problems w/mmergency diesel generators CARUSO, R Licensing Branch 2 84/02/27 G'REILLY, J P NRC No Detailed Affiliation Given App 22708 006 24X Fiche 50-000, 84/03/12, 8402090039
- --B403060554 Transcript of 840210 meeting w/Transamerica Delavalinc Owners Group in Bethesda, MD re problems w/emergency diesel generators

 * NRC No Detailed Affillation Given 84/02/10 147pp 67201 008 24X Fiche 50-000, 84/03/12-8402090037

- --B403070407 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Croup in Wading River, NY re program plan to establish reliability of dissel generators Agenda, meeting transcript & attendance list enci MILLER.M A Licensing Branch 4 84/02/27 Licensing Branch 4 Bpp 22708 161 24X Fiche 50-000,84/03/12,8402090039
- --B403070423 Transcript of B40216 conference in Wading River, NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners B4/02/16 B4pp 22708 167 24X Fiche 50-000, B4/03/12, B402070037

DOCKET 50-330 MIDLAND PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- B403010192 FOIA request for records relevant to or generated in connection w/831021 "Rept on Review of Diesel Generator Bidg at Midland"

 GARDE, B P Government Accountability Project B3/11/26 Office of Administration 2pp 22445 092 24X Fiche 50-329, B3/11/26, B803010192
- 840301019B Responds to FOIA request for records relevant to or gonerated in connection w/831021 "Rept on Review of Diesel Generator Bldg at Midland " Forwards App B documents App A documents available in PDR FELTON, J M Division of Rules and Records 83/12/14 GARDE, D P Government Accountability Project App 22445 092 24X Fiche 50-329,83/12/14,8403010198
- --8310310471 Forwards task group rept, "Rept on Review of Diesel Generator Bldg at Midland." Oct 1983 Large addl settlements not anticipated More accurate program to monitor cracks needed KVO.P Structural & Gentechnical Engineering Branch 83/10/21 KNIOHT.J P Assistant Director for Comp & Structures Engineering (Post 830201) 2pp 22445 152 24X Fiche 50-329,83/12/14. 8403010198
- --8310310475 "Rept on Review of Diesel Generator Bldg at Midland "
 TAN.C P Structural & Geotechnical Engineering Branch 83/10/31
 9app 22445 154 24X Fiche 50-329,83/12/14,8403010198
- --B312010004 Forwards corrected Pages 9.17.20 & 4 to App 11 to rept on raview of diesel generator bldg MUG.P Structural & Geotechnical Engineering Branch B3/11/14 MNIGHT.J P Assistant Director for Comp & Structures Engineering (Post B30201) 5pp 22445 296 24X Fiche 50-329,83/12/14. 84030(0198
- --8312030628 Requests rept re adequacy of diesel generator bldg on expedited basis as input to Congress re Landsman concerns EISENHUT.D G Division of Licensing 83/11/18 VOLLMER.R Division of Engineering 1p 22445 263 24X Fiche 50-329.83/12/14.8403010198
- --B312070022 Forwards Structural & Geotechnical Engineering Branch assessment of "Rept of Review of Diesel Generator Bidg at Midland." dtd 831021 per E Adensam & W Paton requests Heeting & possible reopening of hearing recommended LEAR.0 Structural & Geotechnical Engineering Branch 83/11/22 VOLLMER.R H Division of Engineering 2pp 22445 268 24X Fiche 50-329,83/12/14,8403010198
- --B312070298 Discusses recommendation for suppl to Board Notifications 83-165 & 83-153 re diesel generator bldg Comments & recommendations of J Kane & F Rinaldi on task group rept & reopening of hearling provided HODD, D S Licensing Granch 4 83/11/22 EISENHUT, D Q Division of Licensing App 22445 264 24X Fiche 50-329.83/12/14. 8403010198
- --8312080134 Recommends PT Kuo 831114 memo containing four corrected pages to rept re structural adequacy of diesel generator bldg be forwarded to Board as supplemental notification to BN 83-165
 HOOD, D Licensing Branch 4 83/11/17 EISENHUT, D Assistant Director for Licensing 1p 22445 261 24X Fiche 30-329, 83/12/14,8403010198
- --8403010204 Advises that info re plan to address Landsman concerns should be issued as Board Notification 83-107 EISENHUT, D. G. Division of Licensing 83/07/27 NOVAK, T Assistant Director for Licensing ip 22445 098 24X Fiche 50-329, 83/12/14,8403010198

- --840301021i Advises that attached correspondence re new schedule for review of Landsman concerns should be issued as Board Notification 83-142 W/o encl EISENHUT.D G Division of Licensing 83/09/20 NOVAK.T Assietant Director for Licensing ip 22445 099 24X Fiche 50-329.83/12/14.8403010198
- --B403010217 Draft rept. "Review of Diesel Generator Bldg at Midland Plant" MILLER.C A , COSTANTINO.C J Brookhaven National Laboratory B3/09/23 25pp 22445 100 24x Fiche 50-329.B3/12/14.B40301019B
- --B403010223 Advises that enci JP Knight B30723 memo to RH Vollmer should be issued as Board Notification B3-i53 W/o encl EIBENHUT.D G Division of Licensing 83/10/05 NDVAK, T Assistant Director for Licensing 1p 22445 125 24X Fichs 50-329, B3/12/14, 840301019B
- --8403010227 Forwards "Review of Diesel Generator Bldg at Midland Plant "
 REICH, M Brookhaven National Laboratory B3/10/17 KUD, P T
 Btructural & Geotechnical Engineering Branch ip 22445 126 24X
 Fishs 50-329, 83/12/14, 8403010198
- --8403010231 "Review of Diesel Generator Bldg at Midland Plant" MILLER: C A , COSTANTIND.C J Brookhaven National Laboratory 83/10/17 25pp 22445 127 24X Fiche 50-329.83/12/14.8403010198
- --B403010245 Requests that encl rept on roview of diesel generator bldg & util analysis requested during review be issued as Board Notification 83-165
 E1SENHUT, D Ø Division of Licensing 83/10/26 NOVAK, T Assistant Director for Licensing 6pp 22445 250 24X Ficher 30-327, 83/12/14, 8403010198
- --B403010273 Advises that supplemental info provided in PT Kuo B31114 memo to JP Knight will be transmitted to Midland Board as suppl to Board Notification B3-165 Issue will be incorporated as Board Notification B3-165A W/o encl EISENIUT, D 0 Division of Licensing B3/11/16 NOVAK, T Assistant Director for Licensing ip 22445 262 24X Fiche 50-329, 83/12/14, 8403010198
- --B4030102BR Forwards guidance for use in deciding whether to recommend that hearing be reopened Hearing should be reopened based on listed reasons VOLLMER.R H Division of Engineering 83/11/25 EISENHUT, D G Division of Licensing 3pp 22445 270 24X Fiche 80-329, 83/12/14/8403010198
- --B4D3010285 Advises that Vollmer recommended reopening Midland hearing on diesel generator bldg structural adequacy issue, based on task group rept Vollmer memo enc! W/o enc!

 ADENBAM, E NRC No Detailed Affiliation Given B3/11/25
 EIBENHUT, D NRC No Detailed Affiliation Given ip 22445 273
 24X Fiche 50-327, 83/12/14, 8403010198
- B40301048B Appeals denial of FDIA request for T Novak notes generated by or during visit to Olen Ellyn. IL to discuss Dfc of Bpecial Cases findings re facilities from Sept 1982 to Dec 1983 OARDE, B. P. Government Accountability Project 84/01/17 FELTON. J. M. Division of Rules and Records 1p 22443 274 24X Fiche 50-329, 84/01/17, 840301048B
- B4030604B6 Further response to FDIA request for documents re evaluation or review of design.const.scheduling.cost & licensing of facilities from 1977 to present Rept unavailable for Categories 1 & 2 Panel records on evaluations placed in PDR FELTON, J M Division of Rules and Records B4/01/24 ZACK.A M Barris. Bott. Denn & Driker 2pp 22552 252 24X Fiche 50-329.84/01/24,84030604B6
- B403060370 Notifies of independent design & const verification program B40313 meeting w/NRC & util in Bethesda.MD to discuss details of completion of IDVP LEVIN.H A TERA Corp B4/02/24 EISENHUT, D Q Division of Licensing KEPPLERJ O Region 3. Office of Director COOK, J W Consumers Power Co 3pp 22511 312 24X Fiche 50-327, 84/02/24, 8403060370
- B403010296 Authorizes util to proceed w/remedial soils work activities scheduled for Mar 1984,per B40214 request for Work Authorization Procedure 102795125 HARRISON, J Region 3, Office of Director 84/02/28 GUAMME, D L Consumers Power Co 2pp 22432 104 24% Fiche 50-329, 84/02/28, 8403010296,

- 8403010497 Responds to appeal re denial of FDIA request for records in possession of T Novak on visit to Olen Eliyan it to discuss findings of Ofc of Special Cases re facilities NRC has no records subj to request DIRCKS.W J Office of the Executive Director for Operations 84/02/2B GARDE.B P Government Accountability Project ip 22443 273 24X Fiche 50-329,84/02/2B.8403010497
- 8403080230 Lists unresoived items & audit finding repts, including MSA-83-10-030 & MSA-83-25-07F, respectively * Consumers Power Co 84/02/28 Stane & Hebster, Inc ip 22560 126 24X Fiche 50-329, 84/02/28, 8403080230
- 840308024i Forwards 840227 list of Bethtel personnel trained to accompitable status assessment

 * Consumers Power Co. 84/02/28 Stone & Webster, inc. 3pp. 22561 013 24x Fiche 50-327,84/02/28.8403080241
- 8403080248 Forwards proposed list of remedial solis work for Mar 1984 * supplemental work activity list for Apr 1984 Review.comments & authorization requested QUAMME.D L Consumers Power Co 84/02/28 HARRISON.J J Region 3, Defice of Director 13pp 22556 276 24X Fiche 50-329,84/02/28,8403080248
- 8403080260 Forwards summary of sixth meeting on confirmed items & findings on 840201 at Bechtel Ann Arbor.NI ofc re items identified in independent design & tonst verification program monthly status rept dtd 840113
 LEVIN.H A TERA Corp 84/02/28 KEPPLER, J G Region 3, Office of Director COOK, J W Consumers Power Co Elsenhut, D G Division of Licensing 14pp 22557 078 24% Fichs 50-327,84/02/28.8403080260
- 8403;30261 Notifies that GR Fotiades placed on controlled distribution of training plan manual, per 840224 request QUAMME, D L Consumers Power Co 84/02/28 BARANDW, S Btone & Webster, Inc 1p 22617 134 24X Fiche 50-329,84/02/28,8403130261
- 8403220179 Forwards 840307 memo providing documentation to S&W for const implementation overview

 * Consumers Power Co 84/02/28 Stone & Webster, Inc App 22717 024 24X Fiche 50-329,84/02/28,8403220179
- 8403080262 Forwards weekly NSSS subcontract status rept for wk ending 840217 W/o encl * Consumers Power Co 84/02/29 Stone & Webster, Inc 1p 22557 112 24X Fiche 50-329,84/02/29,8403080262
- 8403330189 Provides list of documents sent to S&W on 840229

 * Consumers Power Co 84/03/01 Stone & Webster, Inc 1;
 22617 323 24% Fiche 50-329,84/03/01,8403130189
- 8403140021 Forwards Vol X to "Seismic Margin Review, Miscellaneous Subsystems & Components " COOK, J W Consumers Powel Co 84/03/01 DENTON, H R Division of Licensing 3pp 22632 167 24X fiche 50-329, 84/03/01, 8403140021
- --8403140026 "Seismic Margin Review, Miscellaneous Subsystems & Components "
 WESLEY, D A , NARVER, R B Structural Mechanics Associates SMA 13701 058003 V10 84/02/27 200pp 22432 171 24X
 Fiche 50-329,84/03/01,8403140021
- 8403130470 Discusses sampling insps of const training records for personnel noted in Correspondence CSC-7382 Personnel listed cleared to perform status assessment encl M/o enci KARR, J E Stone & Webster, Inc. 84/03/02 QUANNE, D L Consumers Power Co 1p 22613 209 24% Fiche 50-327,84/03/02.8403i30470
- B403:30003 Forwards svc water pump structure crack survey rept
 NRC concurrence of mods to crack mapping program requested
 Seven oversize drawings enci Aperture cards are available in
 PDR
 MOONEY, J A Consumers Power Co 84/03/05 HARRISON, J Region 3,
 Office of Director 30pp 22824 116 24X Fiche 50-329,84/03/05,
- 8403130388 Forwards signed affidavit & resume for RE Horine assigned to const implementation staff at plant
 KARR.JE Stone & Webster, Inc 84/03/06 HARRISON, J J Region 3.
 Defice of Director 7pp 22805 001 24% Fiche 50-329,84/03/06, 1800310388
- B403i304B2 Advises that iisted remedial soils work activities presently scheduled for Apr 1984 identified as critical work activities Appropriate details of listed activities requested to assist NRC in review HARRISON. J J Region 3. Office of Director 84/03/06 GUAMME.D L; Consumers Power Co 4pp 22613 193 24X Fiche 50-329.84 03/06. B4031304B2

- 8403190078 Advises that PBACK eliminated from weekly distribution of summary of inspector training & personnel form printouts QUAMME.D L Consumers Power Co 84703/06 BARANOW.S Stone & Webster. Inc 2pp 22669 302 24X Fiche 30-327.84/03/06.
- 8403230114 Provides addl info on scope of work required to support turbine roll test milestone as part of const completion program implementation QUAMME. D.L. Consumers Power Co. 84/03/06 HARRISON, J. Region 3. Office of Director 9pp 22730 337 24% Fiche 50-329, 84/03/06. 8403230114
- 8403140032 Forwards "Plan to Conduct Independent Mgt Appraisal of Midland Nuclear Project," by Cresap, McCormick & Paget Appraisal will examine util approach for completing plant Certificate of Syc enci Related correspondence CODK, J.W. Consumers Power Co. 84/03/07 KEPPLER, J.G. Region 3, Office of Director App. 22603 129 24X Fiche 50-329,84/03/07,8403140032
- --840314003B "Plan to Conduct Independent Mgt Appraisal of Midland Nuclear Project" • Cresap, HcCormick & Paget 84/03/07 73pp 22633 133 24X Fiche 50-329, 84/03/07,8403140032
- 8403130133 Authorizes otil to proceed w/Phase I const completion activities for listed plant modules, per 840215 & 0305 requests Partial sys approved for Phase I activities located in module areas also listed MARRISON, J J Region 3, Office of Director 84/03/08 QUAPME, p L Consumers Power Co 3pp 22601 262 24% Fiche 50-329,84/03/08,
- --B403130168 Submits addl info on scope of work required to support turbing roll test milestone, per 840215 ltr Further definition of scope for seven Q-listed sys & description of const completion program process provided QUAHME.D L Gonsumers Power Co B4/03/06 HARRISON, J. J Region 3, Office of Director. 9pp 22601 267 24X Fiche 50-329, 84/03/08,8403130153
- 8403200027 Requests authorization to proceed per work authorization procedures to excavate Lag Zones Y3 & Z3. install brace struts Eto.Eij.NiO & Wil.install temporary support bracket at Ei & VI & remove unacceptable backetil & casing MDONEY, J A Consumers Power Co 84/03/08 HARRISON, J J Region : 04fice of Director 1p 22697 233 24X Ficha 50-329,84/03/08,840320027
- 8403190180 Ack receipt of 840207 ltr indicating desire to discuss likely operation date Cost.generating capacity & extent to which costs attributable to reasons beyond control of licensee discussed KEPPLER.J G Region 3, Dffice of Director 84/03/09 BARAK, A J Michigan. State of 2pp 22671 144 24X Fiche 50-329, 84/03/09, 8403190180
- --840319018A Discusses 831028 ltr recommending deferring further Caseload Forecast Panel meetings Earliest completion date for Unit 2 not expected until months after Second Quarter 1986 & Unit 1 expected 6-9 months thereafter NOVAK,7 M Assistant Director for Licensing 83/12/20 COOK, J W Consumers Power Co 4pp 22471 146 24x Fiche 50-329,8403/09,8403190180
- --8403190192 Notifies that ut;1 seeking ratemeking treatment for plant Engineering consultants hired to prepare testimony reoperation date.cost & generating capacity BARAK.A J Hichigan, State of 84/02/07 KEPPLER, J G Region 3, Office of Director 2pp 22671 150 24X Fiche 50-329,84/03/09,8403190180
- B403200039 Requests authorization to proceed w/excavation & repair of frozen piping & excavation & installation load of redesigned E-17 MOUNEY. J A Consumers Power Co 84/03/09 HARRISON, J J Region 3, Uffice of Director 1p 22698 315 24X Fiche 50-329,84/03/09, 840320039
- 8403220025 Forwards 840303 memo re Unresolved Questions 47 & 48 from Hemo DEB 330-63 for PGCI C-1 &0.Rev 7 PEAUDOIN.D E Consumers Power Co 84/03/12 FOT[ADES.G.R Btone & Wabster, Inc 2pp 22717 [80 24X Fiche. 50-327, 84/03/12, 8403220025
- 8402070041 Board Notification 84-050 provides Commission policy statement & proposed relemaking on environ qualifications EISENHUT.D G Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24% Fiche 50-000,84/03/14,8402070041

- B403200084 Authorizes listed critical remedial soils work activities for Mar 1984
 HARRISON, J. J. Region 3. Office of Director 84/03/14 QUAME, D. L. Consumers Power Co. 2pp 22685 294 24X Fiche 50-329, 84/03/14, 8403200084
- 8403220202 Forwards complete responses to tracked info Items 03B,039 & tracked recommendation Item 060 re site auditing = Consumers Power Co 84/03/14 Stone & Webster, Inc 11pp 22788 090 24x Fiche 50-329,84/03/14,8403220202
- 8403220082 Authorizes listed remedial soils work activity for Nar 1984 HARRISON: J J Region 3: Office of Director 84/03/15 QUANTE: D L Consumers Power Co 2pp 22716 265 24% Fiche 50-327,84/03/15, 34013200000
- 8403220113 Forwards summary of independent design & const verification program 840313 meeting w/util & Govt Accountability Project in Bethesda MD LEVIN.H A TERA Corp 84/03/15 KEPPLER.J & Region 3. Office of Director COOK.J H Consumers Power Co EISENHUT.D 9. Division of Licensing 37pp 22716 226 24X Fiche 50~329.84/03/15.840322013
- 8403270009 Forwards listing of QA mgt audits for tracked info Item 052 # Consumers Power Co 84/03/15 Stone & Webster, Inc 2pp 22769 353 24X Fichm 50-329.84/03/15,8403270009
- 8403270014 Forwards summary of quality verification program mgt review 830401 meeting.
 PALMER, B. Consumers Power Co. 84/03/19 Stone & Webster, Inc. 14pp 22770 029 24X Fiche 50-329,84/03/19,8403270014.
- 8403220100 Notifies of eighth independent design & const verification program 840328 meeting w/util.Isham.Lincoln & Beale.Govt Accountability Project & Midland Daily News to discuss status of confirmed items & Findings

 LEVIN.H A TERA Corp 84/03/20 KEPPLER, J W Region 3, Office of Director EISENHUT, D G Division of Licensing COOK, J W, Consumers Power Co 5pp 22715 179 24X Fiche 50-329,84/03/20, 8403220100
- B403270159 Notifies of eighth OCR status review meeting on 840320 w/ util BAW & SAW in Ann Arbor, MI to discuss confirmed items & findings of independent design const verification program Agenda encl
 LEVIN: H A TERA Corp B4/03/20 EISENHUT. D @ Division of Licensing KEPPLER, J G Region 3, Office of Director, COOK, J N Consumers Power Co Spp. 22769 157 24X Fiche 50-329,84/03/20, 0407370149
- B403300070 Forwards minutes of mgt review for const completion plan quality verification program B30429 meeting Agenda & supporting documentation encl PALMER: IL Consumers Fower Co 84/03/20 Stone & Hebster, Inc. 46pp 22822 026 24X Fiche 50-329,84/03/20.8403300090
- 8403220007 Requests authorization to proceed w/work authorization Procedure 202550205. "Excavate Around Manhole 10 " GUAMME.D L. Consumers Power Co. 84/03/22 HARRISON, J.J. Region 3. Office of Director 1p 22713 362 24X Fiche 50-329.84/03/22. 8403220007
- F Security, medical, emergency & fire protection plans
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 mess to D Eisenhut re fire research results contenning fires in electrical cabinets in control room EISENHUT, D G Division of Licensing, 84/02/23 FALLADING Commissioners Ip 22576 203 24X Fichs 50-000,84/02/23,8402090004
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRN Ofc Ltr 19, dtd 821001 Further evaluation of tast data required VGLLMER,R H Division of Engineering 84/02/06 EISENHUT,D 9 Division of Licensing 10pp 22376 204 24X Fiche 30-000.84/02/23,8402090006
- 8403120103 Natifies of 840323 workshop on fire protection safe shutdown requirements of 10CFR50. App R in Rosemont, IL to discuss IE Info Notice 84-09 & provide addl shutdown analyses &/or mod quidance. Agenda and I SPESSARD. R L Division of Emergency Preparedness & Operational Support 84/03/06 COOK. J H. Consumers Power Co. 3pp 22388 223 24% Fiche 50-329, 84/03/06.8403120103

@ Adjudicatory correspondence

- 8403060093 Forwards list of audit repts dtd 840130-0202 Certificate of Svc encl Related correspondence BRUNNER.J E Consumers Power Co 84/02/29 BECHDEFER.C., HARBDUR.J., COMAN.F P. Atomic Safety and Licensing Board Panel 4pp 22516 334 24X Fiche 50-329.84/02/29.8403060093
- 8403140119 Contention on Transamerica Delayel diesel generators re Model DSRV 12 Model cannot be relied upon to perform requisite safety function STAMIRIS, B Stamiris, B 84/03/04 Atomic Safety and Licensing Board Panei 3pp 22624 201 24X Fishe 50-329,84/03/04,8403140119
- 8403140075 Forwards DG Eisenhut 830810 ltr to BP Garde,per 830921 commitment W/o encl HASSELL,D F Hearing Branch 1 84/03/05 BECHHOEFER,C . COMAN,FP , HARBOUR,J Atomic Bafety and Licensing Board Panei 2pp 22633 081 24X Fiche 50~327,84/03/05,8403140075
- B403140154 Forwards summaries of B20202-05 meeting & audit re auxiliary building underpinning. B20316-19 meeting & audit re soils remedial action & B31004-07 audit & meeting re HVAC sys WILCOVE, N Hearing Branch 2 B4/03/05 BERNABEI, L Government Accountability Project 2pp 22621 361 24X Fiche 50-329, 84/03/05, 8403140154
- 8403150003 Forwards evc water pump structure crack survey rept Concurrence on mods to crack mapping program requested Details will be discussed at 840404 meeting Certificate of 8vc encl Related correspondence HODNEY, J.A. Consumers Power Co. 84/03/05 HARRISON, J.J. Region 3 Office of Director. 30pp. 22824 116 24x Fiche 50-329,84/03/05, 8403150003
- 8403120039 Advises that entire fireline excavation backfilled after physical connections made to restore fire svc to portions of site Svc list enci Related correspondence BRUNNER, J E Carolina Power & Light Co 84/03/07 BECHHOEFER, C. CONAN, F.P., HARBOUR, J. Atomic Safety and Licensing Board Panel 3pp 22587 271 24X Fiche 50-327,84/03/07,8403120039
- 8403i30i14 Order revising schedules for submittal of proposed findings & conclusions on GA/mgt attitude issues ASLB may issue separate partial initial decision on certain issues not encompassed by proposed findings on issues
 BECHHOEFER.C Atomic Safety and Licensing Board Panel B4/03/12
 2pp 226i5 295 24X Fiche 50-329,84/03/12,8403i30i14
- 8403190166 Forwards Bechtel quality action rept supporting D Lewis testimony re buried control room pressurization pipe Corrosion caused by stray weiding currents not item of concern. Svc list encl Related correspondence BRUNNER, J E Consumers Power Co 84/03/12 BECHHOEFER, C, HARBOUR, J, COMAN. F P Atomic Safety and Licensing Board Panei 7pp 22669 184 24X Fiche 50-329,84/03/12,8403190166
- 8403230031 Requests approval for release of insplactivity per NRC rework disposition regerdless of position of module action item Related correspondence guamme. D L Consumers Power Co DSB 072 84/03/13 HARRISON, J J Region 3, Office of Director 3pp 22724 335 24X Fichs 50-329,84/03/13,8403230031
- 8403200011 Proposes to defer response to Stamiris DL contention re Transamerica Deiaval diesel generators until after receiving Stamirls ltr in support of timeliness of contention Proof of Svc enci OILQMEN, B R Isham, Lincoln & Beale GILDMEN, B R Consumers Power Co 84/03/15 BECHHOEFER, C Atomic Safety and Licensing Board Panel 3pp 22683 358 24x Fiche 50-329, 84/03/15, 840320001i
- 8403200139 Addendum to Stamiris contention on Transamerica Delaval, Inc diesel generators addressing late filing factors of 10CFR2 714. BTAMIRIB, B Stamiris, B 84/03/15 Commissioners 2pp 22699:156 24X Fiche 50-329,84/03/15,8403200139
- B403270020 Proposes to defer response to Stamiris 840304 contention re Transemerica Deiavai diesel generators Proof of Bvc encl OLLOHEN.B R Isham, Lincoln & Baals QLOMEN, B R Consumers Power Co DSB iio 84703/15 BECHHOEFER.C Atomic Befety and Licensing Board Panel. 3pp 22766 360 24X Ficha 50-329,84/03/15,8403270020
- 8403220246 Order setting time for responses to 8 Stambris 840304 motion as if 840315 addendum was original filing data Served on 840322.

 BECHHDEFER, C. Atomic Safety and Licensing Board Panel DSB 039 84703/21. Office of the Executive Legal Director 2pp 22719 049. 24X Fichs 50-329,84/03/21,8403220246

- 8403280348 Order extending time until 840425 for Commission to act to review Director's Decisions DD-83-16 & DD-84-2 Served on 840328 GHILK 5 J Office of the Secretary of the Commission DSB 158 84/03/27 Commissioners ip 22787 143 24X Fiche 50-329.04/03/27, 8403280348
- I Financial information
- 8403190071 Annual Financial Rept for 1983 W/840312 ltr SELBY. J D Consumers Power Co 83/12/31 34pp 22666 i36 24X Fiche 50-000.83/12/31.8403190071
- O Inspection reports. IE Bulletins & correspondence
- 8401230630 Partial response to FOIA request for IE 800103 rept re review of mat) false statement at facilities, associated & supporting records to rept & repts prepared in response. Forwards App A documents Review of addi records in progress FELTON, J M Division of Rules and Records 83/11/01 WINSLOW, R Wall Street Journal 2pp 21705 337 24X Fiche 50-329, 83/11/01, 8401230630
- B403070229 Partial response to FQIA request for repts to NRC investigation of failure of reactor vessel holddown studs on Unit 1 reactor vessel Forwards App A & B documents FELTON.J M Division of Rules and Records 84/02/23 PLATO.E D Kohl, Secrest, Wardle, Lynch, Clark & Hampton & Dp 22544 149 24X Fiche 80~327,84/02/23,8403070229
- --8403070343 Forwards 1E Insp Repts 50-329/80-12 & 50-330/80-13 on B00301-31 No noncompliance noted Najor areas inspected exam of procedures & representative records observations & interviews w/personnel W/o encl FIORELLI.9 Region 3. Chicago. Office of the Director 80/05/19 HOWELL.9 H Consumers Power Co 2pp 22564 170 24X Fiche 50-329, 84/02/23, 8403070229
- ~~840307035i Responds to 830901 ltr & forwards iE Investigation Repts 50-329/80-13 & 50-330/80-14 M/o encl LEWIS.8 H Region 3, Office of Director 83/09/20 MYERB.T F Garan. Lucow, Milier, Seward, Cooper & Becker ip 22544 263 24X Fiche 50-329.84/02/23.8403070229
- 8401190072 IE info Notice 84-13, "Povential Deficiency in Motor Operated Voive Control Circuits & Annunciation " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22907 239 24X Fiche 50-000.84/02/28,8401190072
- 8403130297 Advises that const implementation overview performed sampling insp of const training records for personnei Results satisfactory KARR, J E Stone & Webster, Inc 84/02/29 GUAMME.D L Consumers Power Co ip 22617 233 24X Fiche 50-329,84/02/29,8403130297
- 8403060385 Forwards IE Monthly Meeting Repts 50-327/84-05 & 50-330/84-05 on 840209 WARNICK, R. F. Region 3, Office of Director 84/03/01 COOK, J W Cansumers Power Co 2pp 22507 004 24X Fiche 50-327,84/03/01,8403060385
- --B403060398 IE Monthly Meeting Repts 50-329/84-05 & 50-330/84-05 on B40209 Major topics discussed crack mapping EPA jacking loads & UB Testing audit corrective action status GARDNBR,R N. HARRISON, J. J. Region 3. Office of Director 84/02/29 5pp 22507 006 24X Fiche 50-329.84/03/01.8403060365
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Syc list enci GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24% Fiche 50-000,84/03/02,8408090007
- B40209000B IE Info Notice 84-16, "Failure of Automatlc Sprinkler Sys Valves to Operate " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc. 122pp 22553 098 24X Fiche 50-000.84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"

 Byc list encl

 JORDAN: E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/03/02 Consolidated Edison Co of New

 York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02.8402090009

- 8403060288 Authorizes util to jack Piers CTI & CTI2 as long as auxiliary bidg differential movement controlled according to 840104 agreement documented in 1E insp Repts 30-329/84-01 & 50-329/84-01 WARRISON, J.J. Region 3, Office of Director 84/03/02 QUAMME, D.L. Consumers Power Co. ip 22519 169 24% Fiche 30-329,84/03/02,8403006288
- B403130254 Forwards RC Sember B40223 memo re MPOAD insp evaluation & Overinsp Audit MSA-84-6 VOKAL.O J Consumers Power Co 84/03/02 Stone & Webster, Inc 2pp 22606 054 24% Fiche 50-329,84/03/02.8403130254
- 8402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Delow Nil Ductility Tamp " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/03 Consolidated Edison Ca of New York, Inc 117pp 22551 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09. Rev I. "Lassona Learned From Imaps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emorgency Preparedness & Engineering Response (Post 830103) 84/03/07 Consultated Edison Co of New York, Inc. 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Builetin 84-02, "Fallures of GE Type MFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG:R C Director's Office, Office of inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403220016 Submits summary of Bechtel investigation & corrective actions to resolve issue of nonconforming mat1 supplied by Tubo-Line Corp. in response to IE Builetin 83-06 Final response expected by 840615 CDOK.J W Consumers Power Co 84/03/12 KEPPLER.J O Region 3. Office of Director 2pp 22712 339 24X Fiche 50-329,84/03/12,840320016
- 8403270179 Submits resolutions to concerns addressed in 840110 ltr re hanger reinsp program Computer listing of hangers evaluated against commodity list to determine base number of hangers in program submitted GUAMME. D L Consumers Power Co 84/03/15 KARR, J E Stone & Webster, Inc 2pp 22770 291 24X Fiche 50-327, 84/03/15, 8403270197
- 8402090043 IE lnfo Natice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list enci JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 227 24% Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Byc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24% Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403020443 Ferwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS, W J Offsice of the Executive Director for Operations
 84/02/21 PALLADINO Commissioners 7pp 22492 083 24X
 Fiche 90-000.84/02/21.8403020443
- 8403070008 Forwards monthly rept for Jan 1784, per ALAB-106, including Bechtel nonconformance rept. Bechtel FSO nonconformance rept. Bechtel quality action requests, Bechtel mgt corrective action repts & Bechtel Additions of the corrective action repts & Bechtel Additions of the corrective action repts & Bechtel Additions of the corrective action repts & Bechtel Additional Development Additional Communication of the correction and Enforcement 2530pp 22529 D10 24X Fichs 50-327,84/02/25,8403070008
- B403220013 Forwards monthly status rept for Feb 1984 Monthly OCR/finding status review meeting scheduled for B40328 in Ann Arbor.MI LEVIN.H A TERA Corp B4/03/16 EIGENHUT, D G Division of Licensing KEPPLER.J G Region 3. Office of Director COOK, J H Consumers Power Co 3pp 22713 285 24X Fiche 50-329, 84/03/16. B403220013

- --B403220022 "Midland Independent Design & Const Verification Program Honthly Status Rept Number 10 for Feb 1984 " DQUGHERTY.F A TERA Corp 84/03/16 54pp 22713 288 24X Fiche 50-327,84/03/16.8403220013
- 8403270062 Forwards "Const Implementation Overview (CIO)," Washly Rept 39 for 840305-09 KARR: J E Stone & Webster. Inc 84/03/16 KEPPLER: J O Region 3. Office of Director 17pp 22766 088 24X Fiche 50-329.84/03/16. 8403270062
- 8403230043 Forwards monthly status rept for Midland project for Feb 1984 WARNICK.R F Region 3, Office of Director 84/03/19 KEPPLER.J Q Region 3, Office of Director 1p 22728 351 24X Fiche 50-329.84/03/19.8403230043
- --8403230046 Forwards monthly status rept for Midland project for Feb 1984 COOK.R J Region 3. Office of Director 84/03/15 WARNICK.R F Region 3. Office of Director 2pp 22728 352 24X Fiche 50-329,84/03/19.8403230043
- 5 Reportable occurrences, LERs & related correspondence
- 8401230630 Partial response to FDIA request for 1E 800103 rept re review of mail false statement at facilities associated & supporting records to rept & repts prepared in response Forwards App A documents Review of addl records in progress FELTON. J M Division of Rules and Records 83/11/01 HINSLOH,R. Wall Street Journal 2pp 21905 337 24X Fiche 50-329,83/11/01. B401230630
- --8401230660 PNO-79-039 on 790305 invostigation concluded that QA gregras for obtaining proper soil compaction of facility deficient excessive settlement observed w/diesel generator bldg & incorrect info re soil foundation contained in FSAR CHEMMAKER, R E. HENDERSON. J D. THORNDURG, H D. Office of Inspection & Enforcement. Office of the Director 79/03/06 2pp 21905 352 24X Fichs 50-329,83/11/01,8401230630
- B403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamortica Delavai, Inc DIRCKS, W.J. Office of the Executive Director for Operations SECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000,84/01/25,8403010451
- 8403210032 Part 21 rept re failure of auxiliary foedwator pump drive turbines.04mpal NPS-4 T&T valve to close Enci ltr dtd 840203 sent to insted utils GE notified of affected units in BWR plants
 THEROUX.R R Terry Corp 84/02/22 WOODRUFF.R W Director's Office, Office of Inspection and Enforcement 5pp 22705 327 24% Fiche 50-000.84/02/22.8403210032
- 8403060269 interim deficiency rept re nonconservativo design of embedments in concrete using shear lugs located in tension zones Next rept expected by 840601 COOK.JW Consumers Power Co 84/02/24 KEPPLER.J Q Region 3. Office of Director App 22515 201 24X Fiche 50-329.84/02/23.8403060269
- 8403070229 Partial response to FOIA request for repts re NRC investigation of failure of reactor vessel holddown studs on Unit I reactor vessel Forwards App A & B documents FELTON, J M Division of Rules and Records 84/02/23 PLATO, E D Kohi, Becrest, Wardle, Lynch, Clark & Hampton 6pp 22564, 149 241 Fiche 50-329, 84/02/23, 8403070229
- --B403070343 Recommends order be issued to util requiring action to correct unacceptable anchor bolts at facility Draft ltr & order ench
 KEPPLER.J O Region 3. Chicago, Office of the Director 60/06/27
 THOMPSON.D Executive Officer for Operations Support. 36pp
 22544 172 24X Fishe 50-329,84/02/23,8403070229
- 8403060104 Interim deficiency rept re USW steam generator auxiliary feedwater header design change Unit 2 changes should be completed by 840229 Work on Unit 1 suspended due to delays in startup dates
 COOK.J W Consumers Power Co 84/02/24 KEPPLER.J O Region 3.
 OFFice of Director 3pp 22517 015 24% Fichs 50-329.84/02/24, 8403060104
- BA03060272 Interim deficiency rept re nonconforming electrical racewiy sys Adverse effect of deficiencies on safety of plant aperation unlikely Becatel revised final Rept MGAR 70 encl Next rept will be submitted by 840608 CDOK. J W Consumers Power Co B4/02/24 KEPPLER. J O Region 9, Defice of Director 7pp 22517 066 24X Fiche 50-329,84/02/24, B403060272

- 84030604i1 Forwards signed affidavit & resume of Z Zirak assigned to const implementation overview staff
 KARR.JE Stone & Webster. Inc 84/02/24 HARRISON, J J Region 3. Office of Director 5pp 225i1 347 24X Fiche 50-329,84/02/24,84030604i1
- B403080026 Forwards rept on 840210 exit meeting w/Bechtel & NRC re indiscriminate cable substitutions & Consumers Power Co 84/02/24 Stone & Webster Engineering Corp 3pp 22559 243 24X Fiche 50-329,84/02/24,8403080026
- B403010207 Forwards "Investigation of Tupes AF & AE Piston Skirts," per Transamerica Delaval Inc Owners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations MUSELER, W. J. TDI (Transamerica Delaval, Inc.) Owners Group B4702/27 DENTON. H.R. Office of Nuclear Reactor Regulation, Director 3pp 22434 090 24% Fiche 50-000.84/02/27,8403010207
- B403060426 Forwards Figures 8-8 & 8-7 inedvertently omitted from 840208 response to NRC 840104-06 audit questions re auxiliary hldg underpinning MOONEY. J A Consumers Power Co 84/02/27 HARRISON, J Region 3. Office of Director 6pp 22518 174 24X Fiche 50-320.84/02/27, 8403060426
- 8403080245 Confirms that listing of open nonconformance repts sorted by issue date given to D Brown on 840221 GLANKE, D L. Consumers Power Co 84/02/27 BARANOW, S Stone & Webster, Inc 3pp 22561 006 24X Fiche 50-327.84/02/27, 8401090245
- B403130074 Forwards closed Nonconformance Identification Rept NIR-018 rs training record discrepancies not in compliance w/requirements of FPG-2 000/Rev 7, "Training of Const Personnel" KARR.J E Stone & Webster, Inc B4/02/27 QUAMME, D L Consumers Power Co 3pp 22615 219 24X Fiche 50-329, 84/02/27, 8403130074
- B402090021 Board Notification B4-039 discusses NRC B40210 & 16 mestings w/Transamsrica Delayel, Inc Emergency Diesel Generators Duners Group Meeting scheduled on B40308 for finalization of generic program plan prior to NRC review EIBENHUT, D @ Division of Licensing B4/02/28 PALLADINO, OILINEXY, ROBERTS Commissioners 5pp 22546 003 24X Ficha 50-000 84/02/28,8402090021
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delavai, Inc. emergency diesei generators MUBELER, W. J. TDI (Transamerica Delaval, Inc.) Owners Group 84/02/28 DETOIN, H. R. Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Fiche 50-000,84/02/28,8403010218
- B403080171 Forwards requested list of items determined to be ready for review & closure by NRC Items marked by asterisk reviewed by Region III inspectors & will be removed from list when closed in insprept CODK.J W. Consumers Power Co. 84/02/28 KEPPLER.J G. Region 3, Office of Director 16pp. 22559 298 24X Fiche 50-329,84/02/28, E403080171
- 840308D187 Forwards response to Tracked Info Item 054 requesting MTC QA manual, quality pian program manual, procedures & target list utilized at site & walkdown summaries issued to date * Consumers Power Co 84/02/28 Stone & Webster, Inc 2pp 22559-112 24X Fiche 50-329,84/02/28,8403080187
- 8403080192 Advises that sempling insps of const training records of personnel complete Results of insp satisfactory & NIR-018 closed. Personnel listed on encis cleared to perform status assessment W/o encl Btone & Hoster, Inc 84/02/28 GUAMME, D.L. Consumer-Pauer Co 1p 22539 201 24X Fiche 30-329, 84/02/28.8403080192
- B4000B0235 Lists audit finding repts, including MSA-83-7-04F, OIF & MOI-603-03-02
 + Consumers Power Co 84/02/28 Stone & Webster, Inc Ip 22560 124 24% Fichs, 50-329, 84/02/28, 8403080235
- 8403130173 Forwards closed const implementation overview, Item 035 rediclectric isolation spacers for galvanic protection of copper pipe to galvanized steel pipe supports missing in some areas

 KARR.J E Stone & Webster, Inc 84/02/28 QUAMME.D L Consumers
 Power Co 27pp, 22377 174 24X Fiche 50-327,84/02/28,8403130173
- 8402090020 Board Notification 84-044 forwards Part 21 rept re Transamerica Delaval. Inc turbocharger thrust bearing lubrication defect resulting in angine nonavailability EISENHUT.D o Division of Licensing 84/02/29 PALLADINO Commissioners 4pp 22541 265 24X Fiche 50-000,84/02/29. 8402090020

- 8403080221 Forwards Nonconformance Identification Rept 019 On \$40222, field deviation disposition list not revised to reflect changes for Specs M-1A & C-304 KARR, J E Stone & Webster. Inc 84/02/29 QUAMME, D L Consumers Power Co 2pp 22560 022 24X Fiche 50-329 84/02/29,8403080221
- 8403080247 Forwards complete response to Const Implementation Overview Item 056 re inconsistencies noted during evaluation of training for PGCI C-1 50 ** Consumers Fower Ca 84/02/29 Stone & Webster, Inc 4pp 22561 017 24X Fiche 50-329.84/02/29.8403080247
- 8403080250 Forwards closed Const Implementation Overview Item 054 re Mark Technologies Corp GA & quality program plan maxwels, procedures & target list KARR.J E Stone & Webster, Inc 84/02/29 GUAMME.D t. Consumers Power Co 3pp 22561 016 24X Fiche 50-329,84/02/29,8403080250
- 8403D80259 Forwards complete response to Const Implementation Overview Item 057 re trainer evaluation # Consumers Power Co 84/02/27 Stone & Webster, Inc 4pp 22557 ii3 24% Fichs 50-329,84/02/29,8403080259
- 8403130210 Forwards closed GAR RT-00021 which provides complete response to Nonconformance Identification Rept NIR-008 retraining matrix * Consumers Power Co 84/02/29 Stone & Webster, Inc App 22605 007 24X Fiche 50-329,84/02/29,8403130210
- 8403060385 Forwards IE Monthly Meeting Repts 50-329/84-05 & 50-330/84-05 on 840209 WARNICK.R F Region 3, Office of Director 84/03/01 CODK, J W Consumers Power Co 2pp 22507 004 24% Fiche 50-329,84/03/01,8403060385
- --B403060407 Forwards minutes of Feb 1984 monthly third-party assessment meeting re underpinning & remedial soils work LUCKB.A S Stone & Webster, Inc. B4/02/21 HARRISON, J J Region 3, Office of Director 21pp 22507 011 24X Ficha 50-329, 84/03/01, 8403040385
- --8403060415 Forwards independent Assessment of Underpinning Weekly Rept 48 for 840101-07 LUCKB.A S Stone & Webster, Inc 84/02/32 COOM,R NRC - No Detailed Affiliation Olven lipp 22507 032 24X Fiche 50-329,84/03/01,8403060385
- --8403060420 Forwards Independent Assessment of Underginning Weekly Rept 69 for 840108-14 LUCKS.A 8 stone & Webster, Inc 84/01/17 CDDK, R NRC - No Detailed Affiliation Given 15pp 22507 043 24X Fiche 50-329,84/03/01.8403060385
- --8403060423 Forwards Independent Assessment of Underpinning Weekly Rept 70 for 840115-21 LUCKB.A S Stone & Webster, inc 84/01/25 COOK.R NRC - No Detailed Affiliation Given 14pp 22507 058 24X Fiche 50-329,84/03/01.8403060385
- --8403060428 Forwards Independent Assessment of Underpinning Weekly Rept 71 for 840122-28 LUCKS.A 8 Stone & Webster, Inc 84/02/02 CDOK,R NRC - No Detailed Affiliation Given 16pp 22507 072 24x Fiche 50-329,84/03/01.8403060385
- --8403060442 Forwards Const Implementation Overview Weekly Rept 31 for 840109-13
 KARR, J E Stone & Webster, Inc 84/01/18 KEPPLCR, J G Region 3, Office of Director 17pp 22307 100 24%
 Fiche 50-329,84/03/01,8403040385
- --8403060444 Forwards Const implementation Overview Weekly Rept 32 for 840116-20 KARR, J.E. Stone & Webster, Inc. 84/01/27 KEPPLER, J.G. Region 3, Office of Director 20pp 22507 117 24X Fiche 50-329,84/03/01,8403060385
- --8403060445 Forwards Const Implementation Overview Weekly Rept 33 for 840123-27 KARR, J E Stone & Webster, Inc 84/02/01, KEPPLER, J G Region 3, Office of Director 17pp 22507 137 24X Ficher 50-329,84/03/01.8403060385
- 8403130195 Forwards closed const implementation over training classes KARR.J E Stone & Webster, Inc. 84/03/01 QUAMME. Power Co. Spp. 22617 307 24% Fiche 50-329.84/03

- iOBO222 Interim deficiency rept be coordination of engineering holds restrictions resulting in installation of unqualified sex cables Caples will be replaced Interim or final rept spected by 840504
 DR.J W Consumers Power Co. 84/03/02 REPPLEA.J G Region 3.
 #fice of Director App. 22561 025 24% Fiche 30-329,84/03/02.
- 3130050 Forwards closed Audit Finding Repts MSA-83-25-02F, SA-83-25-10F & MSA-83-25-03F & closed Unresolved Item Repts SA-83-25-07U MSA-83-25-07U 84/03/02) J Consumers Power Co 84/03/02 Stone & W 22508 094 24x Fiche 50-329,84/03/02,8403130050 Stone & Webster, Inc.
- 3130184 Forwards Nonconformance Identification Rept 020 re unsigned hange request forms
 ARR.J E Stone & Hebster, Inc. 84/03/02 GUAMME.D L Consumers ower CO 2pp. 22617 234 24X Fische 50-329,84/03/02.8403130184
- 3130292 Forwards Audit Rept MSA-83-37 W/o encl /OKAL,D J Consumers Power Co 84/03/02 Stone & Webster, Inc p 22644 149 24X Fiche 50-929,84/03/02,8403130292
- 33130321 Forwards Const Implementation Overview Hold Point Joi 100221 Forwards Const Implementation Overview mula Point Joi 170221 Forwards Const Implementated document control for action Recommends form by revised to provide signature & date space for recipient (ARR.) E Stone & Webster Inc 84/03/02 QUAMMED & Consume Fower Co 2pp 22414 130 24X Fiche, 50-329, 84/03/02, 8403130321
- 03i4004B Forwards "Grand Oulf Component Tracking Sys." "Shoreham Component Tracking Sys." & "Transamerica Delaval.inc Diesel Oeperators Unners Group Program Plan." to Tesolve concerns w/emergency diesel generators MUSELER.W J Long Island Lighting Co 84/03/02 DENTON.H R Office of Nuclear Reactor Regulation. Director Spp 22626 062 24X Fiche 50-000.84/03/02.8403140048
- 8403140095 "Transamerica Delaval, Int Diesel Generators Duners Group
- 103130161 Forwards, for info.closed Guality Action Request GAR-RY-00020 used to track const implementation overview Nonconformance Identification Rept MIR-007

 **Conswmars Power Co 84/03/05 Stone & Webster, Inc 10pp 22579 278 24X Fiche 50-327,84/03/05,8403130161
- 403130362 Forwards partial response to Tracked Action Item 043, consisting of pre- & post-stop work order activities.DDR implementation, site-wide distribution plan implementation site-wide distribution plan implementation schedule & corrective action plan H/o encis REICHEL,N I Consumers Power Co. 84/03/05 Stone & Hebster, Inc. 19 22616 269 24% Fiche 50-329,84/03/05,8403130362
- 403130479 Forwards Const Implementation Overview: Item 048 re inconsistency between sper requirements on spacing between anchor buits of different diameters Bechtel preparing sper
- change notice KARR, J E Sto change notice
 MARR, J E Stone & Webster, Inc 84/03/05 KEPPLER, J O NRC - |
 Detailed Affiliation Given GUAMME, D L , REICHEL, N I Consumers
 Paper Co 3pp 22613 228 24% Fishe 50-329, 84/03/05, 8403130479
- 3403130238 Forwards Const implementation Overview Item 062 re training classes Status assessment performed on pipe supports by personnel wincompiete required training XARR.J E Stone & Webster, Inc. 64/03/06 KEPPLER.J 0 Region 3, Office of Director 3pp 22606 057 24X Fiche 50-329.84/03/06. 8403130238
- 8403130354 Forwards completed response to Tracked Action Item 048 consisting of Spec Change Notice 14001 to Spec C-306 re grouted anchor balts
 REICHELN I Consumers Power Co 84/03/06 Stone & Webster, Inc 4pp 22616 330 24% Fische 50-329,84/03/06,8403130354
- 8403130491 Requests extension to 840309 for responding to Tracked Infa Items 058 & 059 & Tracked Recommendation Item 0ad REICHEL, N I Consumers Power Co 84/03/06 Stome & Webster, Inc 1p 22613 180 24% Fiche 50-329.84/03/06,8403130491
- 8402070033 Board Notification B4-047 forwards Transamerica Delayal, Inc Dwners Group piston skirt rept & task descriptions EISEMBUT, D 0 Divition of Licensing 84/03/07, PALLADING, 01LINSKY, ROBERTS Commissioners 4pp 22674 221 24X Fiche 50-000,84/03/07,8402070033

- 8403130271 Informs that response to Nunconformance Insp Rept 008 satisfactory Const Implementation overview will continue to munitor training commitments w/emphasis on listed areas KARR. J E Stone & Webster: Inc 84/03/07 804MHs.D L Consum Power Co ip 22614 175 24X Ficha 50-329, 84/03/07. 8403130271 Consumers
- Q403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program Underway Results of investigation indicate excessive wear caused by hunting of control circuitry

 DDDSON, J P Pacific Air Products Co 84/03/09 DODSON, J.P. Pacific Air Products to 24/03/0 Office, Office of Inspection and Enforcement Fiche 50-000,84/03/09,8403140122 7 Director's 7po 22624 068 24x
- B403220072 Forwards listed documentation re-post-weld heat treat thermacouples Bechtel in contact w/suppliers to obtain replacements M/o encl # Consumars Power Co B4/03/09 BMITH.A Btone & Webster, Inc ip 22712 310 24% Fiche 50-329, B4/03/09, 8403220072
- 8402070038 Roard Notification 84-051 forwards "Transamerica Delaval, Inc (TDI) Diesel Generators Owners Group Program Plan " EIBENHUIT DG Division of Licensing 84/03/12 PALLADIND, GILINSKY, ROBERTS Commissioners Spp 22688 214. 24X Fichs, 50-000, 84/03/12, 8402090038
- 8402090039 Board Notification 84-082 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delayal, Inc (TDI) Owners Group Distribution GISENHUT.D G Division of Licensing 84/03/12 PALLADING, GILINSKY, ROBERTS Commissioners 5pp 22708 001 24x Fiche 50-000.84/03/12.8402090039.
- ~~8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc. Duners Group in Bethasda.MD re problems w/emergency Inc Duners Graup in decisions.

 diesel generators

 CARUSO R Licensing Branch 2 84/02/27 O'REILLY, J P. NRC - No
 Detailed Affiliation glven 6pp 22708 006 24X

 Fiche 50-000,84/03/12,8402090037
- ~-BAD30A0394 Transcript of 840210 meeting w/Transamerica Delayel, Inc Owners Group in Betheada, MD re problems w/smergency diesel generators * NRC ~ No Detailed Affiliation Given 64/02/10 147pp 22708 012 24X Fiche 80~000,84/03/12,8402090039
- ~-B403070409 Bummary of B40216 meeting w/Transamerica Delaval, Inc Dwners Group in Wading River,NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl
 MILLER,H A Licensing Branch 4 84/02/27 Licensing Branch 4 Bpp 22708 161 24X Fiche 50~000.84/03/12,8402090039.
- ~-8403070423 Transcript of 840216 conference in Wading River, Ny re Transamerica Belaval, Inc diesel generators, Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fichs 50-000, 84/03/12, 8402090039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators
 MUSELER, W. J. Long Island Lighting Co. 84/03/12 DENTON, H.R. Office of Nutlear Reactor Regulation, Director 2pp 22602;074
 24X Fiche 50-000,84/03/12.8403140050
- 8403150133 Forwards "Transamerica Delavol,inc Diesel Generator Rocker Arm Capstrew Stress Analysis Rept " Capstrew design adequate for applicable engines & svc conditions MUSELER, W J TDI (Transamerica Delaval, Inc.) Gwners Oroup 64/03/13 DENTON,H R Diffice of Nuclear Reactor Regulation, Director 2pp 2263y 270 24% Fiche 50-000,84/03/13,8403150133
- 8403270169 Forwards, for info, Quality Action Requests (GARs) RA-00134 & RA-00135 to assign action & track const implementation overview (CIO) NIRs 019 & 020 on MPGAD GUAIL sys CIO will evaluate satisfactorily closed out OARs to close out NIRs * Consumers Power Co 84/03/14. Stone & Webster, Inc 6pp 22771 138 24X Fiche 30-329, 84/03/14, 8403270169
- 8403270023 Informs that all 0 redline drawings incorporated, per Hold Point OD: Rept 6.
 * Consumers Power Co 84/03/15 Stone & Webs 22770 069 24% Fiche 50-329,84/03/15,8403270023. Stone & Webster, Inc 2pp
- 8403270029 Forwards response to Tracked Info Item 055 re training matrix status assessment requirements # Consumers Power Co 84/03/15 Stone & Webster, Inc 11pg 22769.328 24X Fiche 50-327,84/03/15,8403270027.

- 8403270227 Forwards open Const Implementation Overview Item 063 re status assessment in Module 120D on 840313 using unmarked FSK prints KARR, JE Stone & Webster, Inc 84/03/15 KEPPLER, J G NRC No Detailed Affiliation Givan REICHEL, N 1 . WELLS, R A Consumers Power Co 3pp 22772 081 24X Fiche 50-329, 84/03/15, 8403270227
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started MATHEMS, C S Transamerica Delaval, Inc 84/03/16 EISENHUT, D 0 Division of Licensing 20pp 22691 179 24X Fiche 50-000,84/03/16, 8403200222
- 8409220067 Interim deficiency rept re low alloy quenched & tempered bolting 1 5-inches & greater in support of safety-related sys Current status of Dechtel matl evaluation encl Next rept will be sent by 840727 CODM.J W Consumers Power Co 84/03/16 KEPPLER, J G Region 3, Office of Director 10pp 22716 150 24X Fiche 50-329,84/03/16,8403220067
- B40322010B Interim deficiency rept re defective capstan springs in mechanical shock arrestors supplied by Pacific Scientific Arrestors being evaluated & tested Next rept by 840504 CODK, J. W Consumers Power Co B4/03/16 KEPPLER, J G. Region Services of Services Ser Office of Director 17pp 22716 180 24X Fiche 50-329,84/03/16,
- 8403270062 Forwards "Const Implementation Overview (CIO)." Weekly Rept Region 3.
- 8403270096 Forwards const implementation overview for Items 064.065 & 066 re CW-1 00. "E-Beries" POCI's, Zack Procedure MB-FP-7C & Zack Procedure MB-FP-1B Welding insp requirements deleted & spec change notice recommended KARR.J E. Stone & Webster, Inc. 84/03/16 KEPPLER,J O NRC - No Detailed Affiliation Given REICHEL.N I Consumers Power Co GUAHME.D L. Stone & Webster, Inc. 4pp 22766 356 24X Fiche 50-327,84/03/16.8403270076
- 8403270093 Forwards Closed Const Implementation Overview Item 056/Hold Point Notification re Checklist MP-MIS-008E-0001 Review of items re impact on training requested KARR.J E Stone & Webster, Inc 84/03/19 KEPPLER.J Q NRC No Detailed Affiliation Olven REICHEL.N I . GUAMME.D i. Consumers Power Co 5pp 22769 358 24X Fiche 50-327,84/03/19,8403270093
- 8403270236 Forwards DF Ronk 840315 memo to JT Christy & attachments showing planned weekly manhour allocations for PGC1 & areas for wks of 840323.30 & 0406 W/o encl RDNKD F Consumers Power Co 84/03/19 BAUMGARTNER, T Stone & Wabster, Inc. 1p 22771.347 24X Fichs 50-329.84/03/19.8403270236
- 8403300006 Forwards Closed Const Implementation Overview Item 052 ra Criterion XVIII site auditing
 KARRJ E Stone & Webster, Inc 84/03/20 KEPPLER, J 0 NRC - No
 Detailed Affiliation Glven QUAMME, D L. REIGHEL, N I Consumers
 Power Co 3pp 22822 126 24X Fichs 50-329, 84/03/20, 8403300006
- 8403300035 Forwards proposed project records classification code list & mgt policy for review.

 KARR, J E Stone & Webster Engineering Corp 54/03/20 GUAMME, D

 Consumers Power Co 8pp. 28821 312 24X Fiche 50-329, 84/03/20. 8403300033
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capecrew Dimension & Stress Analysis," prepared by S&W for Transamerica Delaval, Inc (TDI) Diesel Generator Owners Oroup. MUSELER, W J MUBELER, W J TDI (Transamerica Delaval, Inc.) Owners Group, 84/03/23. DENTON, H R Office of Nuclear Reactor Regulation, Director, 2pp 22774 001 24X Fiche 50-000, 84/03/23, 8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delayal disset generators List of suggested meeting topics enci MCOAUOHY, J.P. TDI (Transamerica Delayal, Inc.) Owners Group 84/03/23 DENTON, H.R. Office of Nuclear Reactor Regulation, Director App 22769 133 24X Fiche 50-000, 84/03/23, 8403270134

T Hearing transcripts on non-antitrust matters

- B402090039 Board Notification B4-032 forwards meeting summaries containing transcripts of B40210 & 16 meetings between NRC & Transamerica Delaval, Inc. (TDI) Owners Group Distribution
- DOCKET 50-331 DUANE ARNOLD ENERGY CENTER F Security, medical, emergency & fire protection plans
- 8403200121 Revised emergency plan implementing procedures, including Rev 1 to EPIP 2 4. "Activation & Operation of Offsite Relocation & Assembly Area" & Rev 23 to rev control sheet W/840126 itr & transmittal/ack memo dtd 840125 YOUNG K . WILSON D L Iows Electric Light & Power Ca 83/11/17 DENTON.H Office of Nuclear Reactor Regulation. Director 13pp 22697 023 24X Fiche 50-331,83/11/17,8403200121
- 840320005i Revised emergency plan implementing procedures, including Rev 6 to EPIP 2 2 re technical support ctr activation, Rev 2 to 6 to EFIP 2 2 re technical support tr activation Rev 2 to EPIP EPIP 6 i re maint of smergency preparedness & Rev 2 to EPIP 7 i re coordinator duties W/840125 ltr WILSON.D. L. Idwa Electric Light & Power Co. 84/01/10 DENTON.H Office of Nuclear Reactor Regulation, Director 93pp 226B3 25i 24X Fiche 50-33i.84/01/10.840320005i DENTON, H R
- 8403200047 Revised emergency plan implementing procedures, including Rev 4 to EPIP 1 1 re emergency action level determination & Rev 6 to EPIP i R re-notification of emergency response 6 to EPIP 1 & re noutricesson organization W/840126 ltr WILSON, D L Iowa Electric Light & Power Co 84/01/16 DENTON, H WILSON, D L Iowa Electric Light & Power Co 84/01/16 DENTON, H Office of Nuclear Reactor Regulation, Director 60pp 24X Fiche 50-331.84/01/16.8403200047
- B403200183 Revised emergency implementing procedures, including Rev 1 to Procedure EPIP 2 5. "Cantrol Room Emergency Response Operation" & Rev 3 to Procedure EPIP 3 Js., "Manual Dose Injections " W/840312 ltr WILEGON, D. L. Iowa Electric Light & Power Co. 84/02/08 DENTON, H. Office of Nuclear Reactor Regulation. Director & Bpp. 22697 144 24X Fiche 50-331.84/02/08,8403200183
- 8403060550 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR VASBALLO, D B Operating R VASSALLO,D 0 Operating Reactors Branch 2 84/02/10 LIV.L Inwa Electric Light & Power Co 2pp 22552 293 24X Fiche 50-331,84/02/10,8403060550
- 8403060136 Forwards changes to security plan Changes withheld (ref 10CFR73 21) MCGAUGHY, R W 10wa Electric Light & Power Co 84/02/27 KEPPLER, J G Region 3, Office of Director 1p 22516 Fiche 50-331,84/02/27,8403040134 2251A 085 24X
- 8403120057 Extends invitation to attend regional workshop on fire protection safe shutdown requirements of 10CFR50.App R & IE Info Notice 84-09 on 840323 in Rosemont, IL Proposed agenda encl for review SPESSARD,R L Division of Engineering 84/0 Electric Light & Power Co 3pp 22588 044 Fiche 50-331,84/03/04,8403120057 84/03/06 LIU,L
- 8403130145 Ack receipt of 840227 itr transmitting changes to security plan Changes consistent w/provisions of locfR50 54(p) & acceptable AXELBON, W L Region 3, Office of Director 84/03/08 LIU, L lowe Electric Light & Power Co 2pp 22408 171 24X Fiche 50-331,84/03/08,8403130145
- 8403130478 Ack receipt of 840222 itr re procedure distribution for radiation protection procedures Controlled distribution of emergency plan & implementing procedures acceptable PAPERIELLO.C J. Region 3, Office of Director 84/03/08 MINECK.D L. Jowa Electric Light & Power Co. ip 22613 252 2: Fiche 50-331,84/03/08.8403130478
- --8403130488 Discusses revised procedures to simplify distribution of NOSISNABL Discusses revised procedures to simplify distribution radiation protection procedures from controlled copy to uncontrolled copy for info only MINECK.D.L. Tawa Electric Light & Power Co 84/02/22 KEPPLER.J & Region 3. Office of Director 1p 22613 253 Fichs 50-331,84/03/08,8403130478

- 8403190236 Forwards IE Safeguards Insp Rept 50-331/83-19 on 831220-B40119 & notice of violation & proposed imposition of civil penalty Notice withhold (ref iOCFR73 21) KEPPLER. J O Region 3, Office of Director 84/03/13 LIU.L lowa Electric Light & Power Co 4pp 22672 281 24X Fiche 50-331.84/03/13,8403190236
- --B403190237 IE Bafeguards Insp Rept 50-331/83-19 on 831220-840119
 Noncompliance noted failure to provide adequate vital area
 barrier & security plan criteria not met for vital
 equipment Details withheld (ref 10CFR73 21)
 PIRTLE, G L . MADEDA, T J . CREED, J R Region 3, Office of Director
 84/02/01 2pp 22672 285 24X Fiche 50-331,84/03/13,8403190236

J Insurance & indemnity information

- 8403260062 Forwards Endorsements 62 & 63 to NELIA Policy NF-214 & Endorsements 51 & 52 to MAELU Policy MF-72 SHEALK H Newman & Holtringer 84/03/14 SALTZMAN, J D Assistant Director for State & Licensee Relations 5pp 22750 240 24X Fiche 50-331,84/03/14,8403260062
- P Operating license stage documents & correspondence
- B403200192 "Offsite Dase Assessment Manual for Gasaous & Liquid Effluents " W/840315 ltr MCGAUGHY.R W lowe Clectric Light & Power Co 83/03/31 DENTON,H Office of Nuclear Reactor Regulation, Director 112pp 22700 034 24X Fiche 50-331,83/03/31,8403200192
- B402140527 Forwards exemption from leakage test requirements of 10CFR50.App J. Bection 50 54(a).per util 780829 request Exemption for core spray isolation valves & RCIC & HPCI condensate return isolation valves denied EER also encl EISENHUT.D 0 Division of Licensing 84/01/17 L1U.L Iows Electric Light & Power Co 2pp 22262 234 24X Fiche 50-331.84/01/17,8402140527
- B403060050 Forwards request for additinfore Mark 1 containment long-term program, plant-unique enalysis rept loads evaluation. Response requested within 45 days of itr receipt Meeting or conference call recommended no later then B40221

 VASBALLO.D B Operating Reactors Branch 2 B4/02/07 LIU.L Iowa Electric Light & Power Co. App. 22528 310 24X

 Fiche 50-331.84/02/07.8403060050
- 8403140340 Summary of 831213 meeting w/GE & Hark I Qwners Oroup in Bethosdo.MD re Mark I containment wetweil-dryweil vacuum breaker design methodology SIEGEL.D L. Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fiche 50-000,84/02/21, 8403140340
- B403:40313 Responds to B40:23 itr concurring w/NRC determination of NSHC for amend request RTS-155 Add1 amend requests received from licensee after 830506 published in FR include RTS-154.RTS-153 & RTS-74
 VASSALLO, D B Operating Reactors Branch 2 B4/02/23 HOUVENAGLE, T IDMS. State of 5pp 22635 303 24X Fiche 50-331,84/02/23, 8403140313
- 840302010B Application for amend to License DPR-49.correcting typographical errors.clarifying existing text & updating old refs MCOAUGHY,R W Iowa Electric Light & Power Co 84/02/27 DENTON.H Office of Nuclear Reactor Regulation, Director 2pp 22442 335 24X Fiche 50-331.84/02/27.8403020108
- --8403020111 Proposed Tach Specs correcting typographical errors, clarifying existing test & updating old refe a lowa Electric Light & Power Co 84/02/27 75pp 22442 337 24X Fiche 50-331.84/02/27.8403020108
- 8403050233 Notifies that Class IV rather than Class III fee appropriate for review of 840127 application for amend to License DPR-49, changing Tech Specs re NUREO-0737 & min staffing requirements.

 DIGGS-R M License Fee Management Branch 84/02/29 ARNDLD, D lowa Ejectric Light & Power Co ip 22527-337 24X

 Ficha 50-331,24/02/29,8403050233.

-1 13° N

- 8403090262 Forwards supplemental response to Generic Ltr 83-28,
 "Required Actions Based on Generic Implications of Salem
 ATMS Events " Activities may be rescheduled during next
 update of integrated plan for mods
 MCGAUGHY, R W Iowa Electric Light & Power Co 84/02/29 DENTON, H
 Office of Nuclear Reactor Regulation, Director 284pp 22572 304
 24X Fiche 50-331.84/02/29,8403090262
- --8403090277 Rev O to Procedure 1410 8, "Post-Scram Review"

 SEDLACK.M 8 [111inois Power Co 84/02/23 App 22573 222 24X
 Fiche 50-331,84/02/29,8403090262
- 8403130144 Forwards response to NRC 840207 request for add1 info re plant-unique analysis rept for Mark I torus mads NCGAUGHY, R W lowa Electric Light & Power Co 84/03/02 DENTON, H Office of Nuclear Reactor Regulation, Director 24pp 22601 276 24X Fiche 50-331.84/03/02.8403130144
- B4030900BB Application to amend License DPR-49.changing Tech Specs to incorporate add1 MAPLHOR limits MCGAUGHY.R W Iowa Electric Light & Power Co 84/03/05 DENTON.H R Optice of Nuclear Reactor Regulation. Director 2pp 22575 327 24% Fiche 50-331.84/03/05.84030900BB
- --8403090092 Proposed Tech Spec changes extending MAPLHGR limits * Inwa Electric Light & Power Co 84/03/05 11pp 22575 329 24X Fiche 50-331.84/03/05.8403090088
- 8403150087 Forwards draft summary of status of equipment qualification program, including response summary of technical evaluation rept.accident description & equipment identification summary & qualification rept MCGAUCHY.R W Iowa Electric Light & Power Co 84/03/08 DENTON.H R Defice of Nuclear Reactor Regulation. Director 106pp 22641 034 24X Fiche 50-331.84/03/08.8403150087
- 8403190300 Forwards revised Page 3 2-23. Table 3 2-0 of 840214 Amend 93 to Liconse DPR-49, making administrative changes to Tach Spoce MCGAUGHY, R W Iowa Ejectric Light & Power Co 84/03/12 DENTON, H Office of Nuclear Reactor Regulation. Director 1p 28673 166 24) Ficho 30-331-84/03/12, 8403190300
- ---B403190306 Revised Page 3 2-23 to Tech Specs, reflecting edministrative changes

 * lowa Electric Light & Power Co 84/03/12 ip 22673 167 24X Fiche 50-331,84/03/12,8403190300
- 8403:30275 Oeneric Ltr 84-07 to all licenseds of BHRs re procedural guidance for pipe replacement at BHRs Svc list enci EIGENHUT.D 0 Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000.84/03/14:8403150275
- 8403300279 Requests remittance of fee for action on 780829 application re exemption from certain App J test requirements MILLER, W O Licenso Fee Hanagement Branch 84/03/15 ARNOLD, D Towa Electric Light & Power Co ip 22844 330 24X Fiche 50-331.84/03/15.8403300279
- 8403230004 Application for rev to License DPR-46, changing Tech Specs re primary containment leakage test requirements MCGAUGHY, R W Towa Electric Light & Power Co 84/03/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 22728 088 24X Fiche 50-331:84/03/16,8403230004
- ~-B403230007 Proposed Tech Spec Change RTS-112B, changing primary containment leakage test requirements ** lowa Electric Light & Power Co B4/03/16 19pp 22728.092 24X Fiche SD-331,84/03/16,8403230004
- 8403260208 Corrects erroneous statement from B30425 response to Generic Ltr 83-02, "NUREO-0737 Tech Specs." re Action Item II.E 4.1, "Dedicated Hydrogen Penetration "Purpe/repressurization sysused as backup for combustible gas control. MCGAUGHY.R H Towa Eisctric Light & Power Co. 84/03/20 DENTON, H Office of Nuclear Reactor Regulation, Director 1p. 22756:164 24X Fiche 50-331:84/03/20.8403260208
- Q, Inspection reports, IE Bulletins & correspondence
- 8403140319 Forwards request for add1 info identified by Franklin Research Ctr re IE Bulletin 80-11 concerning masonry wall design, in response to licensee 821010 submittal VASSALLO, D B Operating Reactors Branch 2 84/02/22. LIU, L. Iowa Electric Light & Power Co App 22635 283 24X Fiche 50-331,84/02/22,8403140319

- 8403120120 Forwards IE Insp Rept 50-331/84-02 on 840103-31 & notice of violation NORELIUS, C & Region 3, Office of Director 84/02/23 LIU, L Iowa Electric Light & Power Co 2pp 22588 206 24X Ficha 50-331.84/02/23.8403120120
- --B403120125 Notice of violation from insp on B40103-31 NORELIUS C E Region 3. Office of Director B4/02/23 ip 22888 208 24% Fiche 50-331.84/02/23.8403120120
- --B403120133 IE Insp Rept 50-331/B4-02 on 840103-31 Noncompliance noted failure to follow procedures re connecting volt ohmmeter at step 4 I instead of step 4 7, causing PS 4544 to Jumper closed & PSV-4401 to open CLARDY, L S. WALKER, R D. Region 3, Office of Director 84/02/2 7pp 22588 207 24X Fiche 50-331,84/D2/23,8403120120
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Bvc list encl. JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22709 239 24X Fiche 50-000,84/02/28,8401190072
- B4020900D7 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Evc list enci GRACE.J N Division of GA, Bafeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02,8402090007.
- B402070008 IE Info Notice 84-i6. "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York Inc i22pp. 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Reisases"

 Bvc list encl

 JORDAN, E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/03/02, Consolidated Edison Co of New

 York, Inc 119pp. 22553 217 24X Fiche 50-000-84/03/02.8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. i17pp 22553 334 24X Fiche 50-000.84/03/05,8402090011
- 8402070024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown 84s" 8vc list encl.

 JORDAN.E. L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/07 Consolidated Edison Co of New York, Inc 188p 22635 049 24X Fiche 50-000.84/03/07.8402070024
- 8402090028 IE Info Notice 84-i8, "Stress Corrosion Cracking in PWR 8ys " 8vc list encl JURDAN,E,L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402070031 IE Bylletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Svc list encl DEVOUNG,R. C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823,094 24X Fiche 50-000,84/03/12,8402090031
- 8403170236 Forwards IE Bafeguards Insp Rept 50-331/83-17 on 831220-840119 & notice of violation & proposed imposition of civil penalty Notice withheld (ref 100FR73 21)
 KEPPLER, J. G. Region 3, Office of Director 84/03/13 LIU, L. Iowa Electric Light & Power Co. 4pp. 22672-281 24X
 Fiche. 50-331, 84/03/13, 8403190236
- --B403190239 IE Bafeguards Insp Rept 50-331/83-19 on B31220-840119.
 Noncompliance noted fallure to provide adequate vital area barrier & security plan criteria not met for vital equipment Details withheld (ref IOCFR73 21)
 PIRTLE, O.L., MADEDA, T.J., CREED, J. R. Region 3, Office of Director 84/02/01, 2pp 22672 285, 24X Fiche 30-331,84/03/13,8403190236
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unsuthorized Entries into PHR Reactor Cavities" Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp. 22823 229 24X Fiche 50-000,84/03/21,8402090043

- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN.E. Djvision of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 2293 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403120042 "Annual Rept of Facility Changes.Tests.Experiments & Bafety & Relief Valve Failures & Challenges.1983 " W/840301 itr MINECK,D.L. Iowa Electric Light & Power Co. 83/12/31 KEPPLER,J G Region 3. Office of Director 73pp. 22591 145 24X Fiche 50-331.83/12/31.8403120042
- 8403220017 Monthly operating rept for Feb 1984 W/840315 itr PUTNAM.K 8 , MINECK.D L Iowa Electric Light & Power Co 84/02/29 7pp 22712 332 24X Fiche 50-331.84/02/27.8403220017
- S Reportable occurrences, LERs & related correspondence
- 8403060145 LER 84-009-00 on 840131 during performance of LPCI surveillance test.RHR sys discharge piping pressure dropped to 0 psig Caused by equipment maladjustment Position indication on two vaives in question adjusted W/840301 ltr KEITH.W R, MINECK,D L lowa Electric Light & Power Co 84/03/01 3pp 22513 346 24X Fiche 50-331.84/03/01.8403060145
- 8403120091 LER 84-010-00 on B40204.steam leak detection high differential temp. HPC1 isolation trip signal annunciators alarmed & inboard HPC1 steam supply isolation valve cycled closed Caused by electrical spike in HPC1 W/840305 itr BMITH, J C . MINECK, D L lowa Electric Light & Power Co 84/03/05
- 8403;20139 LER 84-011-00 on 840205, auto-isolation of control bldg ventilation & initiation of intake standby filter unit 8 occured dus to low inlet air temp Caused by inadequate circulation through nonsafety-related coils W/840306 ltr HAMEL.D B. MINECK,D L. Iowa Electric Light & Power Co. 84/03/06 3pp. 22590 139 24X Fiche 50-331.84/03/06.8403120139
- 8403160091 EN-84-011 notice of violation & proposed imposition of civil penalty in amount of \$20,000 to be issued Action based on failure to control access to vital area RUSAND.R., AXELRAD.J. Director's Office. Office of Inspection and Enforcement 84/03/08 1p 22652 019 24X Fiche 50-331,84/03/08. 8403160051
- DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT
 F Security, medical, emergency & fire protection plans
- B403060045 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per B10709 Generic Ltr B1-27 W/o request, entire plan will be placed in PDR VABBALLO.D B Operating Reactors Branch 2 B4/02/10 BAYNE.J P Pawer Authority of the State of New York 2pp 22528 316 24X Fichs 50~333,84/02/10,8403060045
- 8403140246 Forwards comments on detailed control room design review program plan per Suppl i to NUREO-0737 Specific areas of plan not described in enough detail to provide assurance that applicable requirements wiil be met VABBALLO.D B Operating Reactors Branch 2 84/02/22 BAYNE.J.P. Power Authority of the State of New York 10pp 22636 343 24X Fiche 50-333.84/02/22.8403140246
- B403070312 Forwards IE Insp Rept 50-333/84-01 on 840101-31 No violations observed MCNETECKI,R Division of Project & Resident Programs 84/02/23 MCNETLL,C A Power Authority of the State of New York 2pp 22546 185 24X Fiche 50-333,84/02/23,8403070312
- --B403070316 IE Insp Rept 50-333/84-01 on 840101-31 No violations noted Major areas inspected licenses action on previous insp findings,LER review,operational safety verification, surveillance observations & fire protection program DOERFLEIN.L T Region i. Office of Director COLLINS.B J Division of Project & Resident Programs B4/02/21 lipp 22546 187 24X Fichs 50-333,84/02/23,8403070312
- 8403020327 Requests that completion date of emergency operations facility be extended from B50201 to B5042B, par B30415 & 0824 ltrs & NNRCG-0737, Suppl 1 Completion date does not cover safety parameter display sys installation BAYNE, J.P. Power Authority of the State of New York 84/02/29 VABSALO, D.B. Operating Reactors Branch 2 2pp 22439, 205 24X Fiche 50-333,84/02/29,8403020327

- 8403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop enc; MURLEY. T E Region 1. Office of Director 84/03/09 O'TOOLE. J D Consolidated Edison Co of New York, Inc DALTROFF, B L Philadelphia Electric Co HURILL, H D General Public Utilities OPU Service Corp 33pp 22672 062 24x Fichs 50-000, 84/03/09, 8403190243
- 8403270185 Requests extension to 840831 for completion of third annual emergency preparedness exercise based on Interpretation of Section IV F.App E to 10CFR50 BAYNE.J P Power Authority of the State of New York 84/03/21 VASSALLO.D B Operating Reactors Branch 2 2pp 22771 121 24) Fichs 50-333.84/03/21.8403270185
- P Operating license stage documents & correspondence
- 8403120024 Submits progress rept for drawing update program, including schedule for balance of update work & description of program for continued maint of as-built drawings, per 830408 request BAYKE, J.P. Power Authority of the State of New York 84/02/10 Region 1, Office of Director 4pp 22586 279 24X Fiche 50-333,84/02/10,8403120024
- 8403140304 Informs that add1 info necessary to review 830513 request for amend to License DPR-39, changing Tech Specs re process piping penetrating primary containment info should be submitted within 60 days of itr receipt VASSALLO.D B Operating Reactors Branch 2 84/02/21 BAYNE, J P Power Authority of the State of New York 2pp 22635 315 24X Fiche 50-333,84/02/21,8403140304
- 8403140340 Summary of 831215 meeting w/GE & Mark I dumers Group in Bethesda.MD re Mark I containment wetwell-drywell vacuum breakor design methodology
 SIEGEL.O L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 31pp 22633 178 24X Fiche 50-000.84/02/21, 8403140340
- 8403020031 Advises that util will continue to operate vent & purge valves for Inspecting RCPB, in response to NRC B40113 ltr Vent & purge valve data and B40113 ltr Vent & purge valve data and B40113 ltr Vent & purge valve data and B40113 ltr VASSALLO.D B Operating Reactors Branch 2 4pp 22439 030 24% Fichs 50-333,8402224,840302035;
- 8403090240 Summary of 840216 meeting w/Northeast Nuclear Energy Co. Boston Edison Co. Vermont Yankee Nuclear Power Co & Teledyne Engineering Svcs In Waltham MA re addl Mark I torus structural analysis List of attendess encl SHEA. J J Operating Reactors Branch 5 84/03/07 CRUTCHFIELD. D Operating Reactors Branch 5 40 22572 278 24X Fiche 50-000.84/03/07.8403090240
- 8403300266 Informs of review of data & evaluations re crack in heat affected zone of recirculation sys weld Continued operation acceptable VASSALLQ.D B Operating Reactors Branch 2 84/03/12 BAYNE.J P Power Authority of the State of New York 2pp 22844 334 24X Fiche 50-333.84/03/12.8403300266
- B403150275 Generic Ltr 84-07 to all licensoes of BMRs re procedural guidance for pipe replacement at BMRs Svc list encl EISENHUT.D O Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22623 354 24X Fiche 50-000,84/03/14,8403150275
- 8403300250 Notification of 840330 meeting w/util in Bethesda,MD to discuss environ qualification of equipment ABELSON.H J Operating Reactors Branch 2 84/03/14 VASSALLO,D D Operating Reactors Branch 2 2pp 22844 354 24X Fiche 50-333,84/03/14,8403300250
- 8403300252 Notification of B40322 meeting w/utli in Dethesda, MD to discuss licensee exemption request re staffing rule ADEL90N:H I Operating Reactors Branch 2 84/03/14 VASBALLO, D 8 Operating Reactors Dranch 2 1p 22844 356 24% Fiche 50-333,84/03/14,8403300252
- B403200094 Forwards response to request for info re licensed matidisposal procedures, per 10CFR20 302 & util 830808 itr Oil burn rate & stack volumetric flow rate for mar & average boiler operation presented in Table i
 BAYNE, J P Power Authority of the State of New York 84/03/15
 VASSALLO, D B Dernating Reactors Branch 2 4pp 22685 301 24/Fiche 50-333,84/03/15,8403200094
- --8403200096 Revised "Proposed Disposal Procedures for Radioactively Contaminated Fuel Oil" * Power Authority of the State of New York 84/02/29 6pp 22685 305 24X Fiche 50-333.84/03/15.8403200094

- B40326017i Withdraws B305i3 application to amend License DPR-59, changing Tech Spec Table 3 7-1 re process piping penetrating primary containment: as complete update of Table 3 7-1 will be submitted by 840627
 BAYNE.J P Power Authority of the State of New York 84/03/20 VASSALO.D B Operating Reactors Branch 2 2pp 22750 359 24X Fiche 50-333,84/03/20,840326017i
- Q Inspection reports, 1E Bulletins & correspondence
- B403070312 Forwards IE Insp Rept 50-333/84-01 on 840101-31 No violations observed STARDSTECKI, R Division of Project & Resident Programs B4/02/23 MCNETLL, C A Power Authority of the State of New York 2pp 22546 185 24% Fichs 50-333.84/02/23.8403070312
- --8403070316 IE Insp Rept 50-333/84-01 on 840101-31 No violations noted Major areas inspected licensee action on previous insp findings. LER review. operational safety verification, surveillance observations & fire protection program DOERFLEINL T Region i. Office of Director COLLINS. B J Division of Project & Resident Programs 84/02/21 11pp 22546 187 24X Fiche 50-333.84/02/23.8403070312
- 8403020351 Advises that utll will continue to operate vent & purge valves for inspecting RCPB, in response to NRC 840113 ltr Vent & purge valve data encl BAYNE.J P Power Authority of the State of New York 84/02/24 VASSAL
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Bvc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22907 239 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of GA: Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02.8402090007
- B402090008 IE Info Notice 84-16, "Fallure of Automatic Sprinkler Bys Valves to Operate " Svc 11st encl
 JORDAN,E L Division of Emergency Preparedness & Engineering Responso (Post 830103) B4703/02 Consolidated Edison Co of New York, Inc. 122pp 22553 098 24X Fiche 50-000,84703/02,8402090008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases" Byc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02.8402090009
- 8402090011 IE Info Notice B4-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 334 24X Fiche 50-000,84/03/05,8402090011
- B402090024 IE Info Notice B4-09, Rev 1, "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IR Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403130466 Advises that during preinduction heating stress improvement uitrasonic insp,flaw identified in heat affected zone of one weld in reclirculation pump suction line Evaluation concluded flaw acceptable for one fuel cycle w/o repair BAYNE.J P Power Authority of the State of New York 84/03/09. VASSALO.D D Operating Reactors Brench 2 2pp 22613 234 24% Fiche 50-333,84/03/09.8403130466
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12,8402090031

- B403220079 Ack receipt of B40228 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50~333/83-28
 STARDSTECKI.R Division of Project & Resident Programs MCNEILL.C A Power Authority of the State of New York 1p
 22716 334 24X Fiche 50~333,84/03/15,8403220079
- --84032200Bi Responds to NRC 840i17 ltr re violations noted in IE Insp Rept 50-333/83-28 Corrective actions review of safetyrelated work for period of time from start of commercial operation to 780131 will be completed by 840909 MCNEILL.C A Power Authority of the State of New York 8TAROSTECKI.R Division of Project & Resident Programs 22716 335 24X Fiche 50-333.84/03/15.8403220079
- B402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24% Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related 8ys " 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044

R Periodic operating reports & related correspondence

- B403010413 "Personnel Radiation Monitoring Rept for 1983 " W/B40201 ltr MCNEILL.C A Power Authority of the State of New York 83/12/3i COLLING.D Radiological Assessment Branch 2pp 22434 024 24X Fiche 50-333,83/12/31,8403010413
- 8403010420 "Personnel Radiation Exposure Bummary for 1983 " W/840201 ltr MCNEILL.C A Power Authority of the State of New York 83/12/31 HAYNES.R C Region 1. Office of Director 7pp 22434 050 24X Fiche 50-333.83/12/31.8403010420
- B403130137 "Effluent & Waste Disposal Somiannual Rept Jul-Dac 1983 "
 W/B40227 Itr
 MCNEILL,C A Power Authority of the Btate of New York B3/12/31
 MURLEY,T E Region i. Office of Director 55pp 22601 062 24X
 Fiche 50-333,83/12/31,8403130137
- 8403130350 Monthly operating rept for Feb 1984 W/840308 ltr CODK.J., MCNEILL.C A Power Authority of the State of New York 84/02/29 lipp 22616 258 24X Fiche 50-333.84/02/29.8403130350

8. Reportable occurrences, LERs & related correspondence

- B403010365 LER 84-001-00, on B4011B, during surveillance testing for inoperative B side suppression pool cooling & spray isolation valve. RHR svc water pump C failed Gaused by worn impaller collet Valve repaired W/B40202 ltr.
 LIBEND.R. MCNEILL.C A Power Authority of the State of New York B4/02/02 MURLEY, T Region 1. Dffice of Director 3pp. 22433 015 24X Fiche 50-333,84/02/02,8403010365
- 8403010241 Updated LER 83-060/03X-1 on 831130, incorrect motor actuator installed on RHR suppression pool outboard isolation valve during maint activities Cause not stated Replacement actuator installed on 840119 W/840203 ltr
 8AKER, R. MCNEILL. C. A. Power Authority of the State of New York 84/02/03 MRLEY, T. E. Ragion 1, Office of Director 3pp 22434:211 24X Fiche 50-333,84/02/03,8403010241
- B403260233 Forwards summary list of deficiencies identified per iOCFR50 55(e),Part 21 & potential generic ltr repts for comments
 STAROBTECKI.R Division of Project & Resident Programs 84/02/28
 Region 1, Office of Director, 7pp 22756 065 24X
 Fiche: 50-000.84/02/28.8403260233
- B403060193 LER 84-004-00 on 840210, dc ground occurred on station battery A. During ground isolation procedure, dc control power to RCIC inverter momentarily interrupted Caused by procedure not stating manual reset required. W/840229 1tr
 LINDBEY, D. J. MCNEILL, C. A. Power Authority of the State of New York 84/02/29, 2pp, 22517-357 24X Fiche. 50-333, 84/02/29, 8403060193
- 8403090025 LER 84-003-00 on 840207, while HPCI intentionally out of svc for maint & mod, RCIC sys declared inoperable Caused by personnel error Personnel counseled & training program implemented W/840305 ltr
 KEITH.H N , MCNEILL.C A Power Authority of the State of New York 84/03/05 5pp 22576 181 24X Fiche 50-333,84/03/05,8403090025

- 8403200231 LER 84-006-00 on 840213, reactor water indicating switch found out of Tech Spec limits Caused by excessive internal mechanical friction Surveillance of equipment will be performed & manufacturer contacted W/840314 ltr KEITH,H N . MCNEILL,C A Power Authority of the State of New York 84/03/14 4pp 22676 117 24% Fische 50-333,84/03/14,8403200231
- 8403290246 LER 84-005-00 on 840225 primary containment atmosphere monitoring instrumentation analyzers A & 9 out of svc for 5 h Caused by zero point calibr & sample flow vacuum pump problems Sys mods implemented H/840326 itr KEITH.H N . MCNEILL.C A Power Authority of the State of New York 84/03/26 3pp 22800 195 24X Fiche 50-333,84/03/26,8403270246
- DOCKET 50-334 BEAVER VALLEY POHER STATION, UNIT !

 F Security, medical, emergency & fire protection plans
- 8403200040 Emergency Preparedness Plan EPP/IP 1 2.Attachments 6 & 7 MILLER: D J Duquesne Light Co 84/03/02 6pp 22698 316 24X Fiche 50-334:84/03/02.8403200040
- 8403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agends for workshop encl MURLEY, TE Region I. Office of Director 84/03/09 O'TOGLE, J D Consolidated Edison Co of New York, Inc MANA, B K General Public Utilities GPU Service Corp WODLEYER, E J Duquesne Light Co 35pp 22672 062 24X Fiche 50-000, 84/03/09, 8403190243
- B403200233 Revised emergency plan implementing procedures, including Procedure EPP/IP 3 2 re personnel accountability.Procedure EPP/IP 3 4 re emergency respiratory protection & Procedure EPP/IP 3 5 re traffic & access control W/840227 ltr SIEBER.J D Duquesne Light Co 84/03/09 241pp 22690 208 24X Fiche 50-334.84/03/09.8403200233
- 8403210097 Forwards IE Insp Rept 50-334/84-03 on 840131-0203 No violations noted MARTIN.TT Division of Engineering & Technical Programs 84/03/09 CAREYJJ Duquesne Light Co 2pp 22705 357 24X Fiche 50-334.84/03/09.8403210097
- ---8403210105 IE Insp Rept 50-334/84-03 on 840131-0203 No violations noted Major areas inspected emergency preparedness of areas described in IE Insp Procedures 8203,8204,8205,82205,82206,82207,8210 & 68221 |
 SMITH.R H , MOLTMER.E Region 1. Office of Director CROCKER,H W Division of Engineering & Technical Programs 84/03/08 App 22705 359 24X Fiche 50-334,84/03/09,8403210097
- 8403260166 Forwards IE Insp Rept 50-334/84-04 on 840201-29 No violations found STARDBTECKI,R Division of Project & Resident Programs 84/03/12 CAREY,J J Duquesne Light Co 2pp 22757 320 24X Fiche 50-334,84/03/12,8403260166
- --8403260173 IE Insp Rept 50-334/84-04 on 840201-27 No significant safety issues identified Major areas inspected plant operations, housekeeping, fire protection, radiological controls, physical security & surveillance program

 TRDSKOSKI, W M., JOHNSON, D., TRIFF.L. Region 1, Office of Director 84/03/12 14pp 22757 322 24X Fiche 50-334, 84/03/12, 8402860166
- 8403270215 Provides followup to 840228 telcon re Suppl 1 to NUREO-0737.
 "Development of Emergency Operating Procedures." from generic Westinghouse emergency response guidelines
 Development will continue as described.
 CAREY.J J Duquesne Light Co 84/03/14 VARGA.S A Operating
 Reactors Branch 1 3pp 22770 270 24X Fiche 50-334.84/03/14.
 8403270215
- B4032B0017 Forwards Rev i to physical security plan.Part I, "Base Plan " Rev withheld (ref 10CFR73 21 & 2 790) CAREY, J J Duquesne Light Co 84/03/15 MURLEY, T E Region 1, Office of Director 2pp 22777 082 24X Fiche 50-334,84/03/15, 84032B0017
- P Operating license stage documents & correspondence
- 8403070387 Forwards Amend 76 to License DPR-66 & safety evaluation Amend changes Tach Specs by adding six hydraulic snubbers to surveillance list.Table 3 7-4a TAM.P Operating Reactors Branch i 84/02/27 CAREY, J J Duquesnu Light Co 3pp 22567 032 24X Fiche 50-334.84/02/27,8403070387.

- --840307038? Amend 76 to License DPR-66, changing Tech Specs by adding six hydraulic snubbers to surveillance list Table 3 7-4a VARGA.8 A Operating Reactors Branch 1 84/02/27 4pp 22567 035 24% Fiche 50-334,84/02/27,8403070387
- --B403070391 Safety evaluation supporting Amend 76 to License DPR-66 * Office of Nuclear Reactor Regulation, Director 84/02/27 2: 22567 037 24X Fichs 50-324.04/02/27.8403070387
- 8403090153 Notifies that goal for completion of technical reviews & implementation of NUREG-0737 items.excluding Suppl 1.is Sept 1984 All required documents must be provided & Tech Specs in place to meet goal VAROA.S A Operating Reactors Dranch i 84/03/02 CAREY.J J Duquesne Light Co 3pp 22584 358 24x Fiche 50-334.84/03/02.
 - 8403090153
- 340316006i Summary of B40301 meeting w/util re upgrading core exit thermocouples (TMI Action Item II F 2) List of attendees Reactors Drenating Reactors Branch 1 84/03/07 Operating Reactors Drench 1 App 22662 310 24X Fiche 50-334,84/03/07. 8403160061
- 3403260294 Forwards request for add1 info re 821221 request for relief from ASME Code, Section XI inservice testing requirements for pumps & valves Response requested within 45 days of ltr VARGA.S A Operating Reactors Branch 1 84/03/08 CAREY.J J Duquesne Light Co 6pp 22761 337 24X Fiche 50-334.84/03/08.
- 8403260274
- 1403280325 Forwards comments on proposed Tech Spec changes per 830714 & 0922 itrs Addl info on bypasses to block trip instruments requested VAROALSA Operating Reactors Branch 1 84/03/13 CAREY, J. J. Duquesne Light Co 17pp 22807 305 24X Fiche 50-334,84/03/13.8403280325
- Inspection reports, IE Bulletins & correspondence
- 401i90072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list
- JURDAN. EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22709 239 24X Fiche 50-000.84/02/28.8401190072
- 103070342 Ack recript of 840214 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-334/83-27 STAROSTECKI.R Division of Project & Resident Programs 84/02/28 CAREY, J D Duquesne Light Co 1p 22546, 288 24X Fiche 50-334,84/02/28,8403070342
- -8403070344 Responds to NRC 840116 ltr re violations noted in 1E insp Rept 50-334/83-29 Corrective actions.valves TV-CC-107A,8 & C added to valve table for stroke testing & procedures for testing & calibr of relays revised CAREY,J J Duquesne Light Co 84/02/14 STARQBTECKI,R Division of Project & Resident Programs 4pp 22546 289 24X Fiche 50-334,84/02/28,8403070342 STARGSTECKI.R Division
- 102090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE.U.N Division of OA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 30-000.84/03/02,8402090007
- KO209000B IE Info Notice 84-14. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122gp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 02090009 IE Info Notice 84-15. "Reporting of Radiological Releases " Sec list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post B30103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02.8402070009
- 02090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Selow Nil Ductility Temp " Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 820103). 84/03/05 Consolidated Edison Co of New
 York, Inc 117pp 22553 334 24X Fiche 50-000.84/03/05.8402070011
- 03120170 Ack receipt of 840204 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-334/83-19 & 50-334/83-23 & IE Enforcement Conference Rept 50-334/83-27 BTARDSTECKI.R Division of Project & Resident Programs 84/03/05 CAREV.J J Duquesne Light Cn 2pp 22590-160 24X Tiche 50-334,84/03/05,8403120170

- --8403:20172 Responds to NRC 840105 ltr re violations noted in IE Enforcement Conference Rept 50-334/83-27 Corrective actions operations personnel responsibility review program instituted CAREY.J J Duquesne Light Co 84/02/06 MURLEY.T E Region 1, Ceffice of Director 6pp 22590 162 24x Fiche 50-334,84/03/05. 8403120170
- 8402090024 IE Info Notice 84-09.Rev i, "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22435 049 24X Fiche, 50-000, 84/03/07, 8402070024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 102070028 IE Info Notice 67-5-. Sys " Svc list encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co of New
 York, Inc 118pp 22384 186 24x Fiche 50-000,84/03/07,8402070028
- 8403210097 Forwards 1E lnsp Rept 50-334/84-03 on 840131-0203 No Violations noted

 MARTIN.T T Division of Engineering & Technical Programs 84/03/09
 CAREY.J Duqueene Light Co 2pp 22705 357 24X
 Fiche: 50-334, 84/03/09, 8403210097
- --8403210105 1E Insp Rept 50-334/84-03 on 840131-0203 No violations noted Major areas inspected emergency preparedness of areas described in IE Insp Procedures 82203,82204,82205,82206, 82209.82210 & 8221i SMITH,R H , MOLTNER: E Region 1. Office of Director GROCKER. Division of Engineering & Technical Programs. 84/03/08. 4pp 22705.359 24% Fiche: 50-334.84/03/09.8403210097. CROCKER, H W
- 840209003i IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafoty Sys " Svc list encl DEYOUNG:R C Director's Office. Office of Inspection and Enforcement 84/03/12 Conscilidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8403260166 Forwards IE Insp Rept 50-334/84-04 on 840201-29 No violations found
 STARDSTECKI,R Division of Project & Resident Programs. 84/03/12
 CAREY,J J Duquesne Light Co 2pp 22757-320 24X
 Fiche 50-334-84/03/12.8403240164
- -8403260173 IE Insp Rept 50-334/84-04 on 840201-29 No significant safety HOSZOVIA LE IREP REP 30-34-74-04 of ADVOI-24 No significant sare issues identified Major areas inspected plant operations, housekeeping, fire protection, radiological controls, physical security & surveillance program TROSKOSKI, W M . JOHNSON, D . TRIPP, L Region 1, Office of Director 84/03/12 | 14pp | 22757 322, 24X Fiche 50-334,84/03/12, 8403260166
- 8403270053 Forwards IE Insp Rept 50-334/84-02 on 840116-20 & notice of Violation

 MARTIN.TT Division of Engineering & Technical Programs 84/03/13

 CAREY.J J Duquesne Light Co 2pp 22806-272 24X

 Fiche 50-334.84/03/13.8403290033
- --B403270037 Notice of violation from insp on 840116-20 + Region 1, Office of Director 84/03/13 1p 22806 274, 24X Fich 50-334,84/03/13,8403270053.
- --8403270062 IE Insp Rept 50-334/84-02 on 840116-20 Violation noted.
 iO-yr inservice insp plan in use not distributed in
 controlled manner or reviewed or approved by authorized personnel GRAY.E H , MCBREARTY,R A , DURR.J P Region 1. Office of Director B4/02/28 5pp. 22806 275 24X Fiche 30-334,84/03/13,8403290053
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities" Byc list encl.
 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of Parks, Inc. 123pp 22823 229 24% Fiche 50-000,84/03/21,8402090 24X Fiche: 50-000, 84/03/21, 8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys "Syc list encl
 JORPAN, E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/03/21 Consolidated Edison Co. of New
 York, Inc 135pp 22933 001 24X Fiche.50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403260160 Annual rept of challenges to pressurizer safety & PORVs No challenges occured during 1983 M/840223 ltr CAREY,J J Duquesne Light Co 83/12/31, HURLEY,T E Region 1, Office of Director 2pp 22750-343 24X Fiche: 50-334, 83/12/31, 8403260160

- 8403010126 NPDES discharge monitoring rept for Jan 1984 W/840224 ltr FEITKNECHT.C Duquesne Light Co 84/01/31 REID.R W Operating Reactors Branch 4 16pp 22435 324 24X Fiche 50-334.84/01/31,
- B403020084 Monthly operating rept for Jan 1984 W/840209 ltr HOLTZ:JJ: CAREY:JJ Duquesne Light Co 84/01/31 12pp 22441 199 24X Fiche 50-334.84/01/31.8403020086
- 8403070259 Forwards annual rept of personnel receiving greater than 100 mrem & associated mrem exposure by work function for CY83.

 CAREYJ J Duquesne Light Co 84/02/15 MURLEY, T E Region 1, Office of Director ip 2254i 272 24X Fiche 50-334, 84/02/15, 8403070269
- --B403070366 Annual rept of personnel receiving greater than 100 mrem & associated mrem exposure by work function for CYE3

 # Duquesne Light Co 83/12/31 ip 22541 273 24X
 Fiche 50-334, B4/02/15, B403070269
- 8403070243 Forwards "Effluent & Haste Disposal Bemiannual Rept. Jul-Dec 1983 " Ventilation vent radiation monitor RM-V8-101A/B declared inaperable on B31130 CAREY.J J Duquesne Light Co 84/02/22 Region 1, Office of Director 2pp 22536 020 24X Fiche 50-334,84/02/22,8403070243.
- --8403070244 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1983 " * Duquesne Light Co 83/12/31 59pp 22536 022 24X Fiche 50-334,84/02/22,8403070243
- 8403300181 Monthly operating rept for Feb 1984 W/840308 ltr HDLTZ,J L , CAREY,J J Duquesne Light Co 84/02/29 5pp 22820.333 24X Fithe 50-334,84/02/29,8403300181
- B403190276 Forwards corrected forwarding 1tr dtd 840222 & page to "Bemiannual Efficient Rept.Second Half 1983," due to typographical errors CAREY, J J Duquesne Light Co 84/03/05 Region 1, Office of Director, ip 22673 240 24X Fiche.50-334,84/03/05.8403190276
- --8403190319 Corrected ltr forwarding "Semiannual Effluent Rept, Becond Half 1983 "
 CAREY, J J Duquesne Light Co 84/02/22 Region 1, Office of Director ip 22673-242 24X Fiche 50-334,84/03/05.8403190276
- --8403190324 Corrected "Effluent & Waste Disposel Semiannual Rept, Second Half 1983" * Duquesne Light Co 83/12/31 ip 22673 243 24X Fiche 50-334,84/03/05,8403190276
- 8. Reportable occurrences, LERs & related correspondence
- B403260013 Discusses ioss of RHR for approx 5 h on 800521 Caused by weld in ataching line to common header of RHR pumps
 Safety significance minimal No further AEOD action planned.
 LANNINO,W D Director's Office 80/08/04 Director's Office
 1p. 22763 331 24X Fiche. 50-334. 80/08/04, 8403260013
- 8403010016 Further response to FDIA request for 16 categories of documents. Forwards MJ Dircks 811219 ltr re 810606 sabotage event & special rept to Commonwealth of PA Info partially withheld (ref FDIA Exemption 3)
 FELTON, J. M. Division of Rules and Records 84/01/04 SHOLLY, 8 C Union of Concerned Scientists 2pp 22479 076 24X
 Fiche 50-334, 84/01/04, 8403010016
- --8403010032 Responds to 811021 & 1104 requests for info re 810606 sabotage event at facility, Details withheld (ref 10CFR73, 21)
 DIRCKS, W.J. Office of the Executive Director for Operations 81/12/19, TAYLOR, F. R. Pennsylvania, Commonwealth of, 2pp 22479.080, 24X Fiche 50-334.84/01/04.8403010016
- --B403010061 "Response to Apparent Act of Sabotage at Beaver Valley, Unit 1, " Info partially deleted (ref iOCFR2 790(d) & IOCFR73, 21)

 * NRC No Detailed Affiliation Clven 84/01/04 App 22479: 112 24X Fiche 30~334,84/01/04,8403010016
- 84030A0134 RO on 840215, high radiation alarms w/normal activity present received constantly for Channels 7 & 9 of special particulate indine, noble gas monitor Cause could not be determined Vendor Will assist in investigation LACEY.W. S. Duquesne Light Co 84/02/27 Record Services Branch (Document Control Desk). 2pp 22517.002 24X Fiche: 50-334, 84/02/27, 8403040134

8403270219 Part 21 rept re broken contact carrier in control dev 7 5 kV-15 kV.500-750 MVA.5 kV 350-3.000 & all HKV circuit breaters Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL,D D Brown Bover: Corp (subs of Brown Bover; & Co. 84/03/19 Record Services Branch (Document Control Desk) 22772 114 24X Fiche 50-000,84/03/19,8403270219

V Operator Examinations

8403060297 Lists concerns re operator license exam review process Proper security measures can be taken to prevent dissemination of questions to license applicants during exam Requests NRC reconsider new guidance.per NUREO-1021 CAREV.J J Duquesne Light Co 84/02/24 DENTON.H R Office Nuclear Reactar Regulation. Director 2pp 22511 134 24X Fiche 50-334,84/02/24,8403060297

DOCKET 50-335 ST LUCIE PLANT, UNIT 1

- F Security, medical, emergency & fire protection plans
- B403090280 Public version of Rev 13 to radiological emergency pla B40124 ltr & JM Felton B40307 release memo WILLIAMS, J W Florida Power & Light Co B4/01/04 O'REILLY, C Region 2. Defice of Director 227pp 22593 001 24X Fiche 50-335,84/01/04,8403090280
- 8403040340 Revised emergency implementing pian procedures, includi Procedures 2-0030140 re blackout operation,2-0030143 re total loss of ac power,2-0120042 re LOCA & 2-1010030 re loss of instrument air W/840229 ltr SAGER,D A , WETHY, C N Florida Power & Light Co 84/01/23 / 22519 094 24X Fiche 50-335,84/01/23,8403040340
- 8403070140 Forwards IE Insp Repts 50-335/84-03 & 50-389/84-04 on 840118-20 No violations or deviations noted DANCE.H C Division of Project & Resident Programs 84/02/13, WILLIAMS, J W Florida Power & Light Co 2pp 22538 285 24X Fichs 50-335,84/02/13,8403070140
- --B403070145 IE insp Repts 50-335/84-03 & 50-389/84-04 αn B40118violations or deviations noted Major areas inspected emergency preparedness to assess on-shift prompt emergency classification & protective action recommendations DECKER.T R Region 2, Office of Director JENKINS, C R Div of Emergency Preparedness & Materials Safety B4/02/10 4pp 22538 287 24X Fiche 50-335,84/02/13,8403070140
- 8403190386 Rev 12 to Emergency Plan Implementing Procedure 310002 "Natural Emergencies " W/840307 ltr WILLIAMB, J W Florida Power & Light Co 84/02/29, O'REILLY, Region 2, Office of Director 12pp 22675 270 24X Fiche 50-335,84/02/29,8403190384
- 8403060112 Forwards "Safety Parameter Display Sys Parameter Solec Evaluation & Implementation Plan," per Generic Ltr 82-33, "Suppl i to NUREG-0737 Requirements for Emergency Response Capability "
 WILLIAMS.J W Florida Power & Light Co 84/03/01 EISENHUT, Division of Licensing ip 22518 322 24% Fiche 50-335, 84/03 8403040112
- --8403060i16 "Safety Parameter Display Bys Parameter Selection Ey & Implementation Plan "
 * Florida Power & Light Co 84/03/01 10pp 22518 323 "
 Fiche 50-335,84/03/01,8403060112
- B403i60254 Notifies of 8403i6 workshop to discuss 10CFR50, App R requirements & Insp results to resolve misunderstandings re fire protection Attenders should be limited to six due to size of conference room

 LEWIS, R C Division of Project & Resident Programs 84/03/02, WILLIAMS, J W Florids Power & Light Co 1p 22660 253 24X Ficha 50-000, 84/03/02, 8403160254
- 8403290181 Expresses appreciation for cooperation throughout 10-m period of planning & developing federal full field exercise Exercise provided planning focus & field experience for completing radialogical emergency response planning O'REILLY, U F Region 2, Office of Director 84/03/15 ADDMAT Florida Power & Light Co 2pp 2800 208 24X Fiche 50-335,84/03/15,8403290181
- 8403290109 Ack receipt of 840309 ltr informing NRC of steps taken correct violations noted in IE Insp Repts 50-335/83-43 & 50-389/83-71

 DANCE: H C Division of Project & Resident Programs 84/03/19, HILLIAMS.J W Florida Power & Light Co ip 22807 001 24% Fiche 50-335,84/03/19,8403290109

- --8403290132 IE Insp Repts 50-335/83-43 & 50-387/83-71 on B31211-840110 Violation identified failure to maintain control room procedures in areas of administration, operation, emergency & off-normal BIBB, H E Region 2, Office of Director ELROD, S Division of Project & Resident Programs 84/02/08 4pp 22807 007 24X Fiche 50-335,84/03/19,8403290109
- 8403270247 Notifies that one pressurizer level transmitter W/radiant energy shield.will be separated.per App R.Section III 0 2 F Fire detector will aiso be installed at each pump in intake cooling water pump area MILLIAMS.JW Florida Power & Light Co 84/03/21 EISENHUT.D 0 Division of Licensing ip 22772 ii3 24X Fiche 50-335.84/03/21.8403270247

H General correspondence

- 8403280149 Responds to 840208 ltr requesting assistance in responding to J Paskavitch ltr requesting latest EIS on concentrations of Sr-90.Cs-137 & I-I31 near plants Two annual repts enci W/o repts
 DIRCKS.W J Office of the Executive Director for Departions 84/03/07 CHLES.L Senate. App 22809 316 24X
 Fiche 30-000.84/03/07.8403280149
- --B403280156 Forwards constituent J Paskavitch itr requesting latest EIS on concentrations of Sr-90.Cs-137 & I-131 near plants Comments & views requested CHILESL Senate B4/02/0B KAMMERER, C Office of Congressional Affairs Bpp 22809 320 24X Fiche 50-000.B4/03/07.8403280149
- J Insurance & indemnity information
- 84030A0234 Forwards Endorsement 52 to NELIA Policy NF-227 DUCX,J R Marsh & McLennan. Inc 84/02/28 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 22517 315 24X Fiche 50-335.84/02/28,8403060234
- P Operating license stage documents & correspondence
- 840i130296 Application to amend License DPR-67, deleting radiological efficient Tech Specs from App B. Phylron protection plan WILLIAMS, J W Fiorida Power & Light Co 84/01/10 EIBENHUT, D G Division of Licensing 5pp 21801 135 24X Fiche 50-335,84/01/10,840i130296
- 8402210274 Forwards request for add1 info re reactor coolant pump seized rotor & loss of all nonemergency ac power accidents Apparent conflicts found in ciarifying info W/o encl MILLERJR Operating Reactors Branch 3 84/02/13 WILLIAMS, J W Florida Power & Light Co ip 22323 360 24% Fiche 50-335, 84/02/13, 8402210274
- 8403060077 Forwards Amends 62 & 5 to Licenses DPR-67 & NPF-16, respectively & safety evaluation Amends change personnel titles & revise shift technical advisor function SELLS, D E Operating Reactors Branch 3 84/02/24 WILLIAMS, J W Florida Power & Light Co 2pp 22547 020 24X Fiche 50-335,84/02/24,8403060077
- --8403060080 Amends 62 & 5 to Licenses DPR-67 & NPF-16, respectively, changing personnel titles & revising shift technical advisor functions
 MILLER, J R Operating Reactors Branch 3 84/02/24 12pp
 22549 022 24X Fiche 50-335
- --8403060527 Safety evaluation supporting Amends 62 & 5 to Licenses DPR-67 & NPF-16 respectively # Office of Nuclear Reactor Regulation. Director 84/02/24 2pp 22549 034 24X Fiche 50-335,84/02/24,8403060077
- 8403050354 Requests requalification of electrical equipment at higher beta doses Completion of action within 60 days or submittal of proposed completion date within 15 days requested MILLER, J R Operating Reactors Branch 3 84/02/27 HILLIAMS, J H. Florida Power & Light Co 2pp 22501 333 24X Fiche 50-335,84/02/27,8403050334
- 8403040168 Notifies that administrative program & procedures now in effect will be reviewed to confirm implementation of recommended guidelines in NUTAC rept.per Generic Ltr 83-28 WILLIAMS, J C Florida Power & Light Co 84/03/01 EISENHUT, D O. Division of Licensing 19 82518 336 24% Fiche 50-000, 84/03/01, 8403040168

- B4D3120214 Forwards Amend 63 to License DPR-67 & safety evaluation Amend revises Tech Boecs to change shutdown margin requirements, moderator temp coefficient limits & deletes flux peaking augumentation curve for Cycle 6 MILLER, J R Operating Reactors Branch 3 84/03/01 WILLIAMS, J W Florida Power & Light Co 3pp 22619 253 24X Fiche 50-335,84/03/01,8403120214
- --B403120217 Amend 63 to License DPR-67, revising Tech Specs to change shutdown margin requirements, moderate temp coefficient limits 5 deieting flux peaking augumentation curve for Cycle 6 MILLER, J R Operating Reactors Branch 3 84/03/01 24pp 22619 256 24X Fiche 50-335.84/03/01,8403120214
- --8403120219 Safety evaluation supporting Amend 63 to License DPR-67 * Office of Nuclear Reactor Regulation, Director 84/03/01 30pp 22619 280 24X Fiche 50-335,84/03/01.8403120214
- 8403190150 Notifies of 840402-06 meeting & preimplementation audit at Turkey Point to discuss confirmatory items identified in safety evaluation of detailed control room design reviews for facilities

 VARGA, B A Operating Reactors Branch i 84/03/07 WILLIAM, J W Florida Power & Light Co 6pp 22681 311 24X Fiche 50-000,84/03/07,8403190150.
- 8403130066 Advises that request to revise Tech Bpecs to provide requirements for overtime limits & reporting of relief & safety valve failures will be submitted per Generic Ltr 82-16 (NURGO-0737) by 840515 WILLIAMS, J W Fiorida Power & Light Co 84/03/08 MILLER, J R Operating Reactors Branch 3 ip 22601 252 24X Fiche 50-335,84/03/08,8403130066
- O Inspection reports, IE Builetins & correspondence
- B403070034 Provides status of efforts in development of inservice insporganization manual & plans for issuance.per IE Insp Rept 50-335/83-08 Manual should be in effect by 840315 MILLIAMB, J W Fiorida Power & Light Co 83/12/21 D'REILLY, J P Region 2, Dffice of Director 3pp 22541 278 24X Fiche 50-335,83/12/21,8403070034
- B403070140 Forwards IE Insp Repts 50-335/84-03 & 50-389/84-04 on B40118-20 No vigiations or deviations nated DANCE,H C Division of Project & Resident Programs 84/02/13 HILLIAMS,J W Fiorida Power & Light Co 2pp 22538 285 24X Fiche 50-335,84/02/13,8403070140
- --8403070145 lE Insp Repts 50-335/84-03 & 50-389/84-04 on 840118-20 No violations or deviations noted Major areas inspected emergency preparedness to assess on-shift prompt emergency classification & protective action recommendations DECKER.TR Region 2. Office of Director JENKINS.O R Division of Emergency Preparedness & Materials Safety 84/02/10 4pp 22538 287 24X Fiche 50-335.84/02/13.8403070140
- 8403160206 Forwards IE Insp Repts 50-335/84-04 & 50-369/84-05 on B40201-03 No violations or deviations noted DANCE.H C Division of Project & Resident Programs. 84/02/21 WILLIAMS.J W Florida Power & Light Co 2pp 22655 233 24X Fiche 50-335.84/02/21.8403160206
- --8403160210 IE Insp Repts 50-335/84-04 & 50-389/84-05 on 840201-03 No violations or deviations noted Major areas inspected maint & surveillance observation: plant operations; preoperational testing; procedures & low power testing KRUO.H E Region 2, Office of Director JAPE, F Division of Engineering & Operational Proprems 84/02/13 4pp 22655 235. 24X Fiche 50-335,84/02/21.8403160206
- B403160264 Forwards IE Insp Repts 50-335/83-42 & 50-389/83-70 on 831101-1210 No violations or deviations noted DANCE.H C Division of Project & Resident Programs. 84/02/24 WILLIAMS,J W Fiorida Power & Light Co 2pp 22660 335. 24X Fiche 50-335,84/02/24,8403160264
- --8403160268 IE Insp Repts 50-335/83-42 & 50-389/83-70 on 831111-1210 No violations or deviations noted Major areas inspected; maint & surveillance observation, plant operations, LERs & IE info notices

 8 IBB, H E Region 2, Office of Director ELROD, B A Division of Project & Resident Programs 84/02/23 10pp 22660, 337, 24X Fichs 50-335, 84/02/24,8403160264
- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22709 237 24X Fiche 50-000.84/02/28.8401190072

- B403120240 Forwards request for addl info re util responses to IE Bulletin 80-ii. "Masonry Wall Design," in order to complete review Response requested by 840409 Technical evaluation repts also encl MILLER, J R Dereting Reactors Branch 3 84/02/29 WILLIAMS, J W Florida Power & Light Co 7pp 22619 208 24X Fichs. 50-335,84/02/29,8403120240
- --8403120244 "Use of Joint Reinforcement in Block Masonry Walle," technical rept HAMID.A A. HARRIS,H G. Drexel Univ., Philadelphia, PA BECICA.I.J Franklin Institute/Franklin Research Center 84/03/31 12pp 22619 215 24X Fiche 50-335.84/02/29,8403120240
- --B403120252 "Evaluation of Arching Theory in Unreinforced Masonry Walls in Nucleer Fower Plants " HAMID.A.A., HARRIB.H G Drexel Univ , Philadelphia, PA CON.V Franklin Institute/Franklin Research Center B3/06/30 5pp 22619
- 8403290317 Forwards IE Insp Repts 50-335/84-05 & 50-389/84-07 on B40206-10 No violetions or deviations noted DANCE, H. C. Division of Project & Resident Programs 84/02/29 HILLIAMB.J W. Florida Power & Light Co. 2pp. 22802 052 24: Fiche 50-335,84/02/29,8403290317
- ~~8403270320 IE Inep Repts 50-335/84-05 & 50-389/84-07 on 840206-10 No violatione or devictions noted Major areas inspected health physics instrumentation, ection on NUREO-0737 items, ALARA activities & followup on previous items MRAY, J. R. Region 2, Office of Director BARR, K.P. Division of Engineering & Operational Programs 84/02/22 Bpp 22802,034 24X Fichs 50-335,84/02/29,8403270317
- 8402090007 IE Info Notice 84-i4, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list enci QRACE.J N Division of QA, Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp. 22552 329 24X Fiche 50-000.84/03/02,8402090007
- 8402090008 IE Info Notice 84-i6. "Feilure of Automatic Sprinkler 8ys Velves to Operate " Svc list encl JORDAN, E L Division of Emergency Preparednees & Engineering Response (Poet 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- B402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Byc list encl
 JDRDAN,E L. Division of Emergency Preparednese & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553-217 24X Fichs 50-000,84/03/02, B402090009
- 8403270174 Forwards IE Insp Repte 50-335/84-02 & 50-389/84-03 on 840111-0210 No violations or deviations noted. DANCE, H. C. Division of Project & Resident Programs 84/03/02 WILLIAMS, J W Floride Power & Light Co. 2pp. 22803 076. 24X Fiche: 50-335:84/03/02,8403270174.
- --8403270180 IE Insp Repts 50-335/84-02 & 50-389/84-03 on 840111-0210 No violations or deviations noted Major areas inepected maint observation, surveillance observation, plant operations & TMI Action Item III B 4 2.8 followup
 FEIERABEND.C , BIBB.H E Region 2. Office of Director. ELROD.8 A Division of Project & Resident Progrems. 84/01/02 2pp 22803-078. 24X Fiche-50-335,84/03/02.8403290174
- B402070011 IE Info Notice B4-17, "Probleme W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Bvc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche 50-000, B4/03/05, B402070011
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Inspe of Fire Protection Safe Shutdown 8ys." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/07. Consolidated Edison Co., of New York, Inc. 118pp 22635;049 24X Fiche 80-000,84/03/07,8402090024
- B402070028 IE Info Notice 84-18, "Btress Corrosion Cracking in PWR Bys." Bvc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/07 Consolidated Edison Co. of New York
- 8402090031 IE Bulletin 84-02, "Failuree of OE Type HFA Relays in Use in Class IE Safety Sys " Syc list enc! DEYDUNG,R C Director's Office of Inspection and Enforcement 84/03/12 Consolidated Edieon Co of New York, Inc 134pp. 22823-094. 24X Fiche. 50-000.84/03/12.8402090031

- 8403290109 Ack receipt of 840309 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/83-43 & 50-389/83-71
 DANCE,H C Division of Project & Resident Programs 84/03/19
 WILLIAMS,J W Florida Power & Light Co 1p 22807 001 24X
 Fiche 50-335,84/03/19.8403290109
- --B403290114 Responds to NRC 840202 ltr re violations noted in IE Insp Repts 50-935/83-43 & 50-389/83-71 Corrective actions all indexes reviewed against master copies & procedures in control room verified against indexes WILLIAMS, J W. Florida Power & Light Co. 84/03/09 O'REILLY, J P. Region 2. Office of Director 2pp 22807 002 24X Fiche 50-335, 84/03/19.8403290109
- --8403270124 Forwards IE Insp Repts 50-335/83-43 & 50-389/83-71 on 831211-840110 & notice of violation DANCE:H C Division of Project & Resident Programs 84/02/10 WILLIAMS.J W Florida Power & Light Ca 2pp 22807 004 24X Fiche 50-335,84/03/19,8403270109
- --8403270126 Notice of violation from insp on 831211-840110 * Region 2, Office of Director 84/02/10 ip 22807 006 24% Fichs 50-335, 84/03/19,8403290109
- --8403270132 iE Insp Repts 50-335/83-43 & 50-387/83-71 on 831211-840110 Violation identified failure to maintain control room procedures in areas of administration operation emergency & off-normal BIBB.H E Region 2. Office of Director ELROD, 5 Division of Project & Resident Programs 84/02/08 4pp 22807/007 24X Fiche 50-335,84/03/19.8403270109
- B402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN, E L Division of Emergency Preparadness & Engineering Reeponse (Post 830103) 84/03/21 Cansolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Bvc list encl JORDAN.E. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- R Periodic operating reporte & related correspondence
- 8403020033 Monthly operating repts for Jan 1784 W/840215 itr GRANT,N.W., WILLIAMS.J W Florida Power & Light Co 84/01/3i 17pp. 22442 235 24X Fiche 50-000,84/01/31,8403020033
- B403300173 Forwards monthly operating repts for Feb 1984 & corrected Page 1 of St Lucie Unit 2 monthly operating rept for Jan 1984
 HILLIAMS, J W Florida Power & Light Co 84/03/15 Office of Resource Management, Director 1p 22819 263 24X
 Fiche 50-000,88/03/15,8403300173
- --8403300185 Monthly operating repts for Feb 1984 QRANT, N.W. Florida Power & Light Co. 84/03/15 16pp 22819 264 24X Fiche 50-000, 84/03/15, 8403300173
- 8 Reportable occurrences, LERs & related correspondence
- Bi04220046 Forwards brief description of 801130 event at facility Liceneess of operating C-E PWRs should be informed of concern re inadequacy in reactor protection sys test procedures
 MICHELSON, C Director's Office 81/04/15 JORDAN, E L Director's Office 3pp 22789 297 24X Fiche 50-335, 81/04/15, 8104220046
- 8210120303 Discusses ticensee actions re 811219 dual MSIV closures & presentizer safety valve actuations Cause unidentified Proper corrective action implemented CINTULA,T C Reactor Operations Analysis Branch 82/09/24 SEYFRIT.K V Reactor Operations Analysis Branch 6pp 22789 309 24X Fithe 50-335,82/09/24,8210120303
- 8403220070 Updated LER 81-039/03L-1.on 810802.during power operation, PDRV block valve MV1403 would not close Caused by loose electrical connection on valve limit switch Connection tightened during Oct 1981 refueling W/840319 ltr ROTELLA.T.8. WILLIAMB.J W Florida Power & Light Co 84/03/19 2pp 22712 304 24X Fiche 50-335.84/03/19.8403220070

V Operator Examinations

8403080164 Forwards request for site visits to conduct operator licensing exams requested in Generic Ltr 83-40 WILLIAMS, J H Florida Power & Light Co 84/03/01 EISENHUT, D Q Division of licensing 5pp 22559 293 24X Fiche 50-335.84/03/01.

DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans

- 8403260195 Rev 4i to emergency plan implementing procedure index & Rev 1 to Procedure EPIP 4305A. "Meteorological Tower Emergency Operations Facility Computer Terminal Operation" | W/840309 ltr | COUNSIL.W 0, SEARS.C F | Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 0 | Northeast Utilities | Q4/02/15 | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | Fiche 50-245.84/022/15 | Fiche 50-245.84/022/15 | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | Fiche 50-245.84/022/15 | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | Division of Licensing | 14pp | 22756 171 | 24X | EIBENHUT.D 0 | DIVISION | 24X | EIBENHUT.D 0 | 24X | EIBENHUT.D 0 | 24X | 2
- B4032&0143 Forwards general position statement on Reg Guide 1 97, Rev 2 re justification of significant generic deviations, per NUREC-0737, Suppl 1 COUNSIL.W G . SEARS.C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Connecticut Yankee Atomic Power Co 84/02/29 MILLER.J R Operating Reactors Branch 3 CRUICHFIELD.D Operating Reactors Branch 5 3pp 22758 162 24X Fiche 50-000.84/02/29,8403260143
- --8403260151 General position statement on Reg Guide 1 97,Rev 2 reinstrumentation for assessing plant & environ conditions during & following accidents

 **Northeast Nuclear Energy Co (subs of Northeast Utilities) **Connecticut Yankee Atomic Power Co **Northeast Utilities 84/02/27 69pp 22758 163 24X Fiche 50-000,84/02/27,8403260143
- 8403150106 Forwards FEMA final exercise rept for 820319 joint exercise of state & local radiological emergency preparadness plans for facility Rept of 831005 exercise will be forwarded MARTIN.T T Pivision of Engineering & Technical Programs 84/03/09 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22640 142 24X Fiche 50-336.84/03/09.8403150106
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop ent!

 MURLEY.TE Region i. Office of Director 84/03/09 O'TOOLE, J D Consolidated Edison to of New York. Inc KANDA.B K General Public Utilities GPU Service Corp MODLEVER, E J Duquesne Light Co 35pp 22672 062 24X Fiche 50-000.84/03/09.8403190243
- 8403260146 Forwards revised procedures for corporate organization for nuclear incidents procedure manual, including Procedure CONI 1 of recorporate emergency operations ctr operations W/o enci COUNSIL.4 G . SCARS.CF Connecticut Yankee Atomic Power Co COUNSIL.4 G . Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/03/09 EISSNHUT.D O Division of Licensing 2pp 22750 330 24% Fiche 50-000.84/03/09,8403260146
- 8403220136 Provides results of reevaluation of performance assessment, per util 831219 ltr addressing topics discussed at 831127 SALP mpt meeting Category 1 rating will be assigned to refueling area for Millstone 2 Explains Category 2 ratings MURLEY.T E Region 1. Office of Director 84/03/16 COUNBIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pc 22716 047 24X Fiche 50-000.84/03/16.8403220136
- 8403270009 Informs that util will provide info re planned deviations from Suppl 1 to NUREC-0737 by 840501 Delay has no effect on schedules for implementation of Suppl 1 to NUREG-0737 COUNSIL.W 0 SEARS.CF Connecticut Yankee Atomic Power Co COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/03/16 EISEN,KUT.D 0 Division of Licensing. 2pp 22770 011 24X Fiche 50-000.84/03/16.8403270008
- 8403300084 Advises that B3i214 Rev iB to security plan & B40110 Rev 2 to training & qualification plan consistent w/provisions of iOCFR30 54(p) & acceptable MRTIN.T T Division of Engineering & Technical Programs B4/03/26 CDUNBIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 22822 014 24X Fishe 50-245.B4/03/26.B403300084

- P Operating license stage documents & correspondence
- 8403080344 FOIA request for documents re proposed NSHC determination on license amends for Millstone 2 & entry into operational mode for conducting final tests of pressurizer safety valves at Trojan ADATO, M Union of Cuncerned Scientists 84/02/02 FELTON. J M Division of Rules and Records 1p 22583 038 24X Fiche 30-000.84/02/02.8403080344
- B403060454 Forwards Amends 95 & 92 to Licenses DPR-21 & DPR-65, respectively Amends chango Tech Specs to comply w/final rule on licensed operator staffing CRUTCHFIELD. D Operating Reactors Branch 5 84/02/16 CQUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 22511 193 24X Fiche 50-245,84/02/16,8403060454
- --B403060439 Amends 93 & 92 to Licensos DPR-21 & DPR-65, respectively, changing Tech Spocs to comply wffinal rule on licensed operator staffing cRUTCHFIELD, D Operating Reactors Branch 5 84/02/16 14pp 22511 196 24X Fithe 50-245, B4/02/16, B403060454
- 8403010235 Submits info re NUREG-0737. Items II E 1 2. "Bafety Grade Auxiliary Feedwater Sys Initiation & Flow Indication" & II K 3 3. "Reporting of Safety & Rollef Vaive Failures & Chaltenges." per util 81230 ltr & Generic Ltr 82-16 CUUNBIL. W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL. W 0 Northeast Utilities 84/02/21 MILLER, JR. Operating Reactors Branch 3 3pp 22434 188 24X Fiche 30-336,84/02/21,8403010235
- 8403050105 Advisos that operability testing of RCB vent valves will be performed per requirements of ASME, Section XI. Bubsection IMV-3410, for Category B valves, per NUREO-0737. Item II B 1 CDUNBIL.W 0 Connecticut Yanke Atomic Power Co CQUNBIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) B4/02/21 MILLER, J R Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 24X Fiche 50-000,84/02/21,8403050105
- 8403070297 Advises that GE Cask IF-300 will be utilized for disposal of thermal shiold Three shipments to Barnweil, BC disposal site in spent fuel railroad transportation cask planned COUNSIL, W Q. DEPKA, J F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL, W Q. Northeast Utilities, 84/02/24 MILLER, J R. Operating Reactors Branch 3 2pp 22373 257, 24X Fichs 50-336,84/02/24,8403090257
- 8403090272 Notifies that submittal date for STS addressing NUREO-0737 items, per Guneric Ltr 83-37, rescheduled for 840305 COUNBIL, W 0 Connecticut Yankse Atomic Power Co COUNBIL, W 0, Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W 0 Northeast Utilities, 84/02/24 EIGEN-HUT, D 0 Division of Licensing 2pp 22572 196 24X Fiche 50-336,84/02/24,8403090272
- B403070304 Provides responses to three open items from NRC/ENL Yankee Atomic Electric Co & consultants Mark I containment program plant-unique analysis rept B40216 review meeting CELIA.N 8 Teledyne Engineering Services B4/02/28 SIEGEL, B NRC No Detailed Affiliation Given 4pp 22546 171, 24X Fichs 30-000.84/02/28.8403070304
- B403130027 Informs that Amends 54.92 & 87 to Licenses DPR-61, DPR-21 & DPR-65 respectively, inadvertently eliminated reporting requirements for exceeding radiological limiting conditions for operation Corroctive actions identified COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL, W G Connecticut Yankse Atomic Power Co COUNBIL, W O Northeast Utilities B4/03/01 MILER, J.R Operating Reactors Branch 3 CRUTCHFIELD. D Operating Reactors Branch 5.
- B4030B0347 Partial response to FDIA request for documents re proposed NBHC determinations for Millstone 2 & entry into operational mode for conducting final tests of pressurizer safety valves at Trojan forwards App B documents FELTON.J M Division of Rules and Records 84/03/02 ADATO, M Union of Concerned Bcientists 4pp 22583 037 24X Fiche 50-000, B4/03/02, B4030B0347
- --B312230261 Evaluates util B31102 arguments to support validity of previous LOCA analyses for removal of thermal shield from core barrel Reanalysis of small break LOCAs not required Restart approved subj to confirmation of peak clad temp. HOUSTON,R W Assistant Director for Reactor Safety, B3/12/13 LAINAS,G C Assistant Director for Operating Reactors. 2pp. 22583 040 24X Fiche 50-000,84/03/02,8403080347.

- ---8403080332 Returns request for publication in FR of notice of consideration of issuance of amend to QL & proposed NSHC determination re Tech Spec changes resulting from Cycle 6 refueiling considerations Revs requested W/o encl RDTHSCHILD, M U Office of the Executive Legal Director 83/06/13 CLARK.R A Operating Reactors Branch 3 ip 22583 059 24X Fiche 50-000, 84/03/02, 8403080347
- 8403140222 Notifies that Class III fee appropriate for review of 831012 proposed Tech Spec changes re mod of pressurizer level band DIOGS:R M License Fee Management Branch 84/03/07 COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 22637 330 24X Fiche 50-336.84/03/07.8403140222
- 8403260200 Comments on Issue 3 of NUREG-0885, "NRC Policy & Planning Guidance, 1984 " Seven themes identified represent important objectives for industry GUUNBIL, W G Northeast Utilities 84/03/12 DIRCKS, W J Office of the Executive Director for Operations 4pp 22756 204 24X Fiche 50-000, 84/03/12, 8403260200
- B4032&0145 Submits details of followup actions on Amend 90 to License DPR-65 Adequate justification provided to demonstrate applicability of current large break LOCA evaluation for operation w/o thermal shield COUNSIL, W O. Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W O. Northeast Utilities B4/03/13 MILLER, J R Operating Reactors Branch 3 2pp 22750 328 24X Fichs 50-336, 84/03/13,8403260145
- 8403270081 Forwards response to NRC concerns re 840104 application to amend Tech Specs, revising pressure-temp limits & max heat-up rate for RCS & reactor vessel matl radiation specimen withdrawal schedule CDUNBIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W G Northeast Utilities 84/03/16 MILLER, JR Operating Reactors Branch 3 10pp 22769 232 24% Fichs 50-336, 84/03/16, 8403270081.
- 8403210070 Forwards Amends 96 & 93 to Licenses DPR-21 & DPR-65, respectively Amends consist of changes to Section 6 of Tech Specs re nuclear review board, reorganization & STS CRUTCHFIELD, D Operating Reactors Branch 5 84/03/19 COUNSIL, W G Northeast Nuclear Energy Co. (subs of Northeast Utilities) App 22705 089 24X Fiche 50-245,84/03/19,8403210070
- --8403210079 Amends 96 & 93 to Licenses DPR-21 & DPR-65, respectively, consisting of changes to Section 6 of Tech Specs re nuclear review board, reorganization & STB CRUTCHFIELD, D Operating Reactors Branch 5 84/03/19 23pp 22705 095 24X Fichs 50-245,84/03/19,8403210070
- 8403270230 Forwards Class III fee for 831012 Tech 8pec change request, in response to NRC 840307 request COUNSIL, N.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNBIL, N.G. Northeast Utilities 84/03/22 DIOGB-R M. License Fee Management Branch. 1p 22800 237 24X Fiche 50-336,84/03/22,8403290230
- Q Inspection reports, IE Bulletins & correspondence
- B403050352 Forwards request for addl info re IE Bulletin B0-11,
 "Masonry Wall Dasign " Info required within 60 days of
 ltr receipt
 MILLER, J R. Operating Reactors Branch 3 84/02/24, COUNBIL, W G
 Northeast Nuclear Energy Co (subs of Northeast Utilities) 7pp
 22519 243 24X Fiche 50-336,84/02/24,8403050352
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering
 - JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22709 239, 24X Fiche 50-000,84/02/28,8401190072
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Bvc list encl QRACE.JA Division of QA, Bafeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp. 22552,329 24X Fichs 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate." Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 930103) 84/03/02 Consolidated Edison Co of New York: Inc 122pp 22553 098 24X Fiche 50-000.84/03/02,8402070008
- B402070007 IE Info Notice 84-15. "Reporting of Radiological Releases."

 Evc list enc!

 JORDANIE L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000, B4/03/02, B402070007

- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Belaw Nil Ductility Temp " Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402070011
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 8490307 Consolidated Edison Co of New York, Inc 118pp 22435 049 24% Fiche 50-000,84/03/07,8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PNR 8ys " Svc list enci JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402070031 iE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list enci DEYOUNG:R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403220136 Provides results of reevaluation of performance assessment, per util 831219 ltr addressing topics discussed at 831129 SALP mgt meeting Category I reting util be assigned to refueling area for Milistone 2 Explains Category 2 ratings MURLEY.T E Region i, Office of Director 84/03/16 COUNSIL,W C Northwest Nuclear Energy Co (subs of Northwest Utilities) 4pp 22716 047 24X Fiche 50-000,84/03/16.8403220136
- 8402090043 iE Info Notice 84-17. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Evolist encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, inc 135pp 2293 001 24X Fiche 50-000,84/03/21,8402070044
- 8403300144 Responds to IE Bulletin 83-08. "Electrical Circuit Breekers W/Undervoitage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Haddam Neck facility uses 31 Westinghouse-type DB breakers CGUNBIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) CGUNBIL, W G Connecticut Yankee Atomic Power Co CGUNBIL, W G Northeast Utilities 84/03/21 MURLEY, T E Region 1. Office of Birector 4pp 22820 058 24X Fiche 50-000,84/03/21.
- 8409300086 Ack receipt of 840824 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/83-20 & 50-936/83-28 MARTIN, T T Division of Engineering & Technical Programs 84/03/23 COUNBIL, W J Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 28822 017 24X Fiche 50-245/84/03/23/8409300086
- --8403300072 Responds to NRC B40125 itr re violations noted in IE Insp. Repts 50-245/83-20 & 50-336/83-28 Corrective actions Procedure CP 807A rewritten to include method of determining hi & hi-hi alarm setpoints

 COUNSIL.W 0 Northeast Nuclear Fnergy Co (subs of Northeast Utilities) COUNSIL.W 0 Northeast Utilities 84/02/24

 MMRLEY,T E Region 1, 0ffice of Director 2pp 22822 017 24X Fichs 50-245,84/03/23,8403300086
- R Periodic operating reports & related correspondence
- 8403230022 "Haddam Neck Plant & Millstone Station Units 1 & 2 Annual Rept,1983 " W/840301 ltr COUNGIL.W 0 , BEARS,C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O Connecticut Yankee Atomic Power Co 83/12/31 MURLEY,T.E Region 1, Office of Director 348pp 22727 001 24% Fiche 50-000,83/12/31.8403230022
- 8403020133 Monthly operating rept for Jan 1984 W/840213 ltr 01880N.J., MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA,E.J. Northeast Utilities 84/01/31 6pp 22441 351 24X Fiche 50-336.84/01/31.8403020133
- 8403120135 Forwards "Semiannual Radioactive Effluents Release Rept, Jul-Dec 1983" Offsite dose estimates not included due to estimate delays Complete rept will be resubmitted by 840430 COUNSIL.W 9. OPENA.JF Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL.W 9. Northeast Utilities. 84/02/28 MURLEY.T E Region 1. Office of Director 1p 22590 076 24X Fiche 50-245,84/02/28,8403120135

- --8403120138 "Semiannual Radioactive Effluents Release Rept. Jul-Dec 1983 "
 • Northeast Nuclear Energy Co (subs of Northeast Utilitles) 83/12/31 42pp 2290 097 24% Fiche 50-245.84/02/28.8403120135
- 8403300080 Monthly operating rept for Feb 1984 W/840313 ltr GIBSON.J. MRGCZKA.E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) HRDCZKA.E J. Northeast Utilities 84/02/29 Opp 22821 175 24X Fiche 50-336.84/02/29.8403300080
- S Reportable occurrences, LERs & related correspondence
- 8211150076 Discusses events involving loss of electrical inverters including attendant inverters to vital instrument buses. Recommendations provided by Nuclear Safety Analysis Ctr are excellent in helping to reduce instrument failures. ASHEIF Reactor Operations Analysis Branch 82/10/21 SEYFRIT. K V Reactor Operations Analysis Branch 82p 22775 223 24X Fiche 50-000-82/10/21-8211150076
- 840323017: Forwards Technical Review Rept AEOD/T314, "Improper Size of Inlat Piging to Primary Safety Valves" IMBRO,E Reactor Operations Analysis Branch 83/05/R4 SEYPRIT.K V Reactor Operations Analysis Branch ip 22759 297 24X Fiche 50~000.83/05/24.8403230171
- --8403230175 "Improper Size of Inlet Piping to Primary Safety Valves." technical review rept Reduced diameter inlet piping does not represent safety concern IMBRO.E V Director's Diffice 83/05/24 2pp 22759 298 24X Fiche 50-000.83/05/24.8403230171
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 T&T valve to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BHR plants
 THEROUX.R R Terry Corp 84/02/22 WOODRUFF, R W Director's Office of Inspection and Enforcement App 22704 327 24: Fiche 50-000.84/02/22.8403210032
- 8403010219 LER 84-005-00 on 840128, during Type 8 & C containment penetration local leak rate test-combined leakage rates exceeded Tech Spec 3 & 1 2 b limits Caused by mechanical deficiencies Isolation valves repaired W/840227 ltr FOSTER, E R . MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MRGCZKA, E J Northeast Utilities 84/02/27 3pp 22436 019 24x Fiche 50-336, 84/02/27, 8403010219
- 8403200113 LER 84-006-00 on 840213.12 of 16 primary coolant loop RTDs exceeded Tech Spec limit of B s or less during respose time testing Caused by time constant for element installation in thermouell b sensor thermouell mismatch W/840314 Ltr BRIKMMAN.S. HERRERI.R J. HROCZWA.E J. Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/03/14 5pp 22697 111 24% Fiche 30-336.84/03/14.8403200113
- DOCKET 50-338 NORTH ARNA POWER STATION, UNIT 1
- F Security, modical, emergency & fire protection plans
- 8403070239 Forwards SALP Repts 50-280/83-33.50-281/83-35.50-338/83-33 & 30-339/83-33 for Oct 1982 Aug 1983 Evaluation will be discussed at 831208 meeting at North Anna site Lewis, R C Division of Project & Resident Programs 83/11/25 STEMART, W L Virginia Electric & Power Co 2pp 22536 227 24X Fiche 50-000.83/11/25.8403070239
- --8403070246 SALP Repts 50-280/83-33,30-281/83-35,30-339/83-33 & 50-339/83-33 for Oct 1982 ~ Aug 1983 Reliable performance wimprovement in most previously noted areas of weakness demonstrated * Region 2, Office of Director 83/11/25 42pp 22536 229 24X Fiche 50-000,83/11/25,8403070239
- 8403050462 Grants 831031 request for examption from requirements of App R to 10CFR30. Section III G 3 b re installing fixed fire suppression sys in control room Exemption encl MILLER. J R Operating Reactors Branch 3 84/02/23 STEWART, W L Virginia Electric & Power Co lp 22549 331 24X Fiche 50-338,84/02/23,8403060462
- ~~8403060465 Examption from requirements of App R to 10CFR50, Section III G 3 b re installing fixed fire suppression sys in control room EISENHUI. D. O Division of Licensing 84/02/23 Virginia Electric & Power Co App 22547 332 24X Fiche 50-338, 84/02/23, 8403060462

- 8403190263 Rev I to corporate emergency response plan W/840315 ltr STEWART.W L Virginia Electric & Power Co 84/02/24 O'REILLY, J P Region 2. Office of Director 105pp 22670 135 24x Fiche 50-000.84/02/24.8403190263
- 8403050198 Forwards Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively & safety evaluation Amends revise Tech Specs to reflect addition & installation of new fire protection sys W/o encl ENGLE, L B Operating Reactors Branch 3 84/02/28 STEWART, W L Virginia Electric & Power Co ip 22528 184 24X Fiche 50-338.84/02/28,8403050198
- 84030B0264 Forwards "Control Room Design Review Program Plan for North Anna & Surry Power Stations." in response to Suppl I to NUREG-0737 Review expected to be completed by 850830 BTEMART.W L Virginia Electric & Power Co 84/03/01 DENTON,H R Office of Nuclear Reactor Regulation, Director EISENHUT,D o Division of Licensing 2pp 22557 298 24% Fiche 50-000,84/03/01, 84030B0264
- --8403080269 "Control Room Design Review Program Plan for North Anna & Burry Power Stations." In response to Suppl i to NUREO-0737 virginla Electric & Power Co 84/03/01 111pp 22557 299 24X Fiche 50-000.84/03/01.8403080269
- 840308009; Submits add1 info in order to conduct detailed review of penergency response procedures generation package.per 840123 request Items 1 & 2 will be addressed by 840530 Item 3 should be addressed by Westinghouse Cuners Group STEWART.W L Virginia Electric & Power Co 84/03/02 DENTON, H R. Dffice of Nuclear Reactor Regulation, Director Elsenhut, D. O. Division of Licensing 2pp 22559 197 24X Fiche 50-000,84/03/02,8403080091
- 8403160276 Extends invitation to attend 840316 workshop at regional afc to discuss lOCFR50.App R requirements & results of lnsps to help resolve misunderstandings associated whrequirements LEWIS-R C Division of Project & Resident Programs 84/03/02 STEMART.W L Virginia Electric & Power Co ip 22660 OBO. 24X Fiche 50-000.84/03/02.8403160276
- 8403260273 Forwards corrected Tech Spec pages for Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively, covering axial power distribution monitoring sys, penetration fire barriers & fire detection instrumentation ENOLE, L B Operating Reactors Branch 3 84/03/06 STEMART, W L Virginia Electric & Power Co ip 22761 343 24X Fiche 50-338,84/03/06,8403260273
- ~-84032602Bl Corrected Tech Spec pages to Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively, covering axial power distribution monitoring sys, penetration fire barriers & fire detection instrumentation

 ### Operating Reactors Branch 3 84/03/06 15pp 22761*344, 24x Fiche 50-338,84/03/06,8403226273
- 8403190052 Informs that local emergency operations facilities at North Anna & Surry Power Stations will be functional accept for data communications & display by 85073; per NUREO-0737, Suppl i STEWART, N. L. Virginia Electric & Power Co. 84/07/14 DENTON N. R.
- STEWART, W.L. Virginia Electric & Power Co. 84/03/14, DENTON, H.R. Office of Nuclear Reactor Regulation, Director EISCNHUT, D. O. Division of Licensing 2pp 22666 173 24% Ficher \$0-000.84/03/14, 8403190052
- 8403290250 Ack receipt of 840306 ltr informing NRC of steps taken to correct violations noted in 16 Insp Repts 50-338/83-31 & 50-339/83-31 &
- --8403290260 Responds to NRC 840207 ltr re violations noted in IE Insp. Repts 50-038/80-01 & 50-039/80-01 Corrective actions: wall classified as fire barrier & cubicles reclassified as seperate fire areas Procedure revised to include insp. STEWART, N.L. Virginia Electric & Power Co. 84/03/06 O'REILLY, J.P. Region 2, Office of Director. 3pp. 22802:033 24X Fichs 50-038,84/03/16,8403290250
- ~-8403270267 Forwards IE Insp Repts 50-338/83-31 & 50-339/83-31 on 831206-840105 & notice of violation LEHIB,R C Division of Project & Resident Programs 84/02/07, BIEMART,W L Virginia Electric & Power Co 2pp. 22802:036 24x Fiche 50-338,84/03/16,8403290250
- ~-8403270280 Notice of violation from insp on 831204-840105. # Region 2, Office of Director 84/02/07 2pp. 22802:038 24X Fichs 50-338,84/03/14,8403290250

- --B403290291 IE Insp Repts 50-338/83-31 & 50-339/83-31 on B31206-B40105 Noncompliance noted failure to maintain procedures re insp of wall & failure to inspect fire barriers LUEHMAN.J G Region 2. Office of Director ELROD.S Division of Project & Resident Programs 84/02/06 9pp 22802 040 24X Fiche 50-338,84/03/16,8403290250
- 8403270184 Forwards FEMA final rept for 830618 emergency exercise DANCE:H C Division of Project & Resident Programs 84/03/19 BTEMART.N L Virginia Electric & Power Co 1p 22802 174 24x Fiche 50-338,84/03/19.8403290184
- J Insurance & indemnity information
- 8403140047 Endorsement 49 to NELIA Policy NF-240 * Nuclear Energy Liability Insurance Association 84/03/01 ip 22634 164 24% Fiche 50-338.84/03/01.8403140047
- P Operating license stage documents & correspondence
- B403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON,5 I Oarvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13.8403080179
- B403070001 Notifies that Class III & Class I fees submitted w/820608 application for amend will be refunded, based on B40123 withdrawal of application MILLER, W O License Fee Management Branch B4/02/24 STEWART, W L Virginia Electric & Power Co ip 22562 343 24% Fiche 50-338,84/02/24,8403070001
- 8403020195 Forwards add1 info to complete review of Topical Rept VEP-FRD-41: "VEPCO Reactor Sys Transient Analysis Using RETRAN Computer Gode," in response to NRC Nov 1982 informal request STEMART, W.L. Virginia Electric & Power Co. 84/02/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director Elsenhull, D.G. Division of Licensing 16pp 22443 257 24X Fiche 50-000,84/02/27, 2007/2019
- 8403050229 Submits review of post-accident sampling sys, Item II.8 3 Ten of 11 criteria met Remaining criterion re procedure for estimating extent of core damage based on radionuclide evaluation:acceptable on interim basis MILLER, J R Operating Reactors Branch 3 84/02/27 STEWART, W L Virginia Electric & Power Co. 6pp 22528 001 24X Fiche. 50-000, 84/02/27, 8403050229
- 8403020001 Requests interim approval of inservice insp & testing requirements for pumps & valves Approval would increase scope of insp & testing & enhance safety Implementation of revised inservice testing programs expected by 840315 STEWART.W L Virginia Electric & Power Co 84/02/28 DENTON.H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 2pp R2442:155 24X Fiche 50-338,84/02/28,8403020001
- 8403020042 Forwards revs to inservice testing program for pumps & valves, clarifying previous submittals
 8TEMART.W L. Virginia Electric & Power Co. 84/02/28 DENTON, H R
 Office of Nuclear Reactor Regulation, Director MILLER, J R
 Operating Reactors Branch 3 15pp 82442 272 24X
 Fiche: 50-338,84/02/28,8403020042
- 8403050198 Forwards Amends 5: & 35 to Licenses NPF-4 & NPF-7, respectively & safety evaluation Amends revise Tech Specs to reflect addition & installation of new fire protection eys W/o encl ENGLE, L B Operating Reactors Branch 3 94/02/28 STEWART, W. L Virginia Electric & Power Co. 1p 22528 184, 24x Fiche, 50-338, 84/02/28, 8403050198
- 8403120176 Advises that 11 6% permit responsibility transferred to Old Dominion Electric Cooperative on 831221, per 840131 ltr Requests NPDES permit & 401 certificate dtd 720211 be modified to reflect transfer W/o stated encl TAYLOR, J.A. Virginia Electric & Power Co. 84/03/01 BURTON, R M Virginia, Commonwealth of, 1p. 22590 203, 24% Fiche: 50-338,84/03/01,8403120176
- 8403210203 Forwards Amends 52 & 34 to Licenses NPF-4 & NPF-7, respectively Amends clarify testing requirements in Tech Gpac Table 3 6-1 re containment isolation valves.

 ENGLE, L B Operating Reactors Branch 3 84/03/06 STEWART, W L Virginia Electric & Power Co 3pp 22707 172 24X Fiche: 50-338, 84/03/06, 8403210203

- --8403210206 Amends 52 & 36 to Licenses NPF-4 & NPF-7, respectively, clarifying testing requirements in Tech Spec Table 3 6-1 re containment isolation valves MILER, JR Operating Reactors Branch 3 84/03/06 9pp 22709 195 24X Fiche 50-338,84/03/06,8403210203
- 8403220208 Forwards Amend 53 to License NPF-4 & safety evaluation Amend revises Tech Spec Table 4 3-2 by removing requirement for surveillance in Mode 4 for auxiliary feedwater pump actuation signals ENGLE.L B Operating Reactors Branch 3 84/03/06 STEWART, W L Virginia Electric & Power Co 2pp 22723 266 24X Fiche 50-338,84/03/06,8403220208
- --8403220212 Amend 53 to License NPF-4 revising Tech Spec Table 4 3-2 by removing requirement for surveillance in Mode 4 for auxiliary feedwater pump actuation signals MILLER, JR Derating Reactors Branch 3 84/03/05 5pp 22723 268 24% Fiche 50-338.84/03/06.8403220208
- --B403220213 Safety evaluation supporting Amend 53 to License NPF-4 * Office of Nuclear Reactor Regulation, Director 84/03/06 2pp 22723 273 24X Fiche 50-338,84/03/06,8403220208
- 8403260273 Forwards corrected Tech Spec pages for Amends 51 & 35 to Licenses NPF-4 & NPF-7 respectively covering axial power distribution monitoring sys, penetration fire barriers & fire dataction instrumentation ENGLE.L B Operating Reactors Branch 3 84/03/06 STEWART, W L Virginia Electric & Power Co ip 22761 343 24X Fiche 50-338,84/03/06,8403260273
- --8403260281 Corrected Tech Spec pages to Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively, covering axial power distribution monitoring sys, penetration fire barriers & fire detection instrumentation # Operating Reactors Branch 3 84/03/06 15pp 22761 344 24X Ficho 50-338,84/03/06.8403260273
- B403:3029B Provides implementation ltr rept for reactor vessel level instrumentation system NRC 640:16 ltr & TMI Action Item II F 2 Requests NRC approve use of installed reactor vessel level instrumentation based on previous acceptance STEWART. W.L. Virginia Electric & Power Co B4/03/07 DENTON, H R Offico of Nuclear Reactor regulation, Director EISENNUT, D G Division of Licensing 3pp 22407 360 24% Fiche 50-338,84/03/07,8403:30298
- 8403190377 Application for amend to Licenses NPF-4 & NPF-7, changing Tech Specs to delete requirements for min & max temp limits for A36 & A572 beams in steam generator supports & determination of beam temps
 STEWART.W L Virginia Electric & Power Co 84/03/15 DENTON, H R Office of Nuclear Reactor Regulation. Director MILLER, J R Operating Reactors Branch 3 3pp 22675 237 24X
 Fiche 50-338.84/03/15,8403190377
- --8403190381 Proposed Tech Specs deleting requirements for min & max temp limits for A36 & A572 beams in steam generator supports & determination of beam temps Request for removal of steam generator support heaters & insulating tent encl # Virginia Electric & Power Co 84/03/15 30pp 22675 240 24% Fichm 50-338,84/03/15,8403190377
- 8403220028 Application for amend to Licenses NPF-4 & NPF-7, revising Tech Specs to reflect new LER sus, per 10CFR50, 73 & immediate notification requirements, per 10CFR50 72 STEWART.W L Virginia Electric & Power Co 84/03/16, DENTON, HR Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 4pp 22713 128 24x Fiche 50-338,84/03/16,8403220028
- --8403220032 Proposed Tech Specs reflecting new LER sys & immediate notification requirements
 * Virginia Electric & Power Co 84/03/16 85pp 22713 132 24X Ficha 50-338,84/03/16,8403220028
- B403220077 Requests exemption from iOCFR50 44(c) (3) (iii) requirements. Operability of reactor vessel head vents should be verified during proposed outages & procedures & training implemented whrevised emergency operating procedures BTEHART, W L Virginia Electric & Power Co 64/03/16 DENTON, H R OFfice of Nuclear Reactor Regulation, Director MILLER, J R Derasting Reactors Granch 3 2pp 22712 311 24x Fiche 50-338,84/03/16,8403820077
- B40327020B Forwards voucher check for required license amend fees omitted from B40315 ltr STEWART'N L Virginia Electric & Power Co B4/03/23 DENTON, H R Office of Nuclear Reactor Regulation. Director MILLER. J R Operating Reactors Branch 3 ip 22772 084 24X Fichs 50-338, B4/03/23.840327020B

- 8403300028 Forwards response to 840116 request for add) info re core exit thermacouple (CETC) & subcooling margin monitoring sys. per 840430 commitment CETC add) info deferred until after B40801 due to sys replacement.per Reg Guide i 97 STEWART.W L Virgains Electric & Power Co. 84/03/23 DENTON,H R Office of Nuclear Reactor Regulation, Director EISENHUT,D O Division of Licensing 4pp 22821 307 24X Fiche 50-338.84/03/23.8403300028
- 8403300005 Informs that independent testing lab conducting overvoltage tests on motor control ctr contactor coils Current schedule for completing tests is May 1994 Resolution & related schedule will be submitted by Jul 1994 STEWART.W. U. Virginia Electric & Power Co. 84/03/26 DENTON.H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 1p 22822 125 24X Fiche 50-338.84/03/26.8403300005
- Q Inspection reports: 1E Bulletins & correspondence
- 8403070237 Forwards SALP Repts 50-280/83-33,50-281/83-35,50-338/83-33 & 50-339/83-33 for Oct 1982 Aug 1983 Evaluation will be discussed at 831208 meeting at North Anna site LEHIS, R C Division of Project & Resident Programs 83/11/25 STEMART, N L Virginia Electric & Power Co 2pp 22536 227 24X Fiche 50-000,83/11/25,8403070239
- --8403070246 SALP Repts 50-280/83-33,50-281/83-35,50-338/83-33 & 50-339/83-33 for Oct 1982 Avg 1983 Reliable performance w/improvement in most previously noted areas of weakness demonstrated * Region 2, Office of Director 83/11/25 42pp 22534 229 24x Fiche 50-000,83/11/25,8403070239
- 8403070279 Discusses SALP evaluation issuance of SALP rept approved No major weaknesses identified during assessment period at North Anna One major weakness identified in area of radicological controls at Surry O'REILLY.JP Region 2. Office of Director 84/02/16 STEMART.W L Virginia Electors 2. Office of Director 24/02/16 STEMART.W L Fiche 50-000,84/02/16.8403070279
- 8401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunclation " Svc 11st encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,64/02/28,8401190072
- 8403020001 Requests Interim approval of inservice lnsp & testing requirements for pumps & valves Approval would increase scape of insp & testing & enhance safety implementation of revised inservice testing programs expected by 840015 STEWART.W. L. Virginia Electric & Power Co. 84/02/28 DENTON, H.R. Office of Nuclear Reactor Ragulation, Director MILLER, J.R. Operating Reactors Branch 3 2pp 22442 155 24X Fiche 50-338.84/02/28.8403020001
- 8402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl ORACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprintler Sys Valves to Operate " Svc list enc! JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 2253 098 24% Fiche 50-000.84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Reipases"
 Bvc list encl
 JORDAN, E Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84703/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8403160154 Responds to IE Bulletin 83-08 re electrical circuit breakers w/undervoltage trip feature in use in safety-related applications other than trip sys Unit reactor trip breakers contain subj trip attachments
 STEHART.W L Virginia Electric & Power Co 84/03/02 0'REILLY, J P
 Resion 2. Office of Director 2pp 22806 008 24X
 Fichm 50-000.84/03/02.8403160154
- 8402090011 IE info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Duckility Temp "Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117gp 22553 336 24X Fiche 50-000,84/03/05,8402090011

- 8403270287 Forwards IE lnsp Repts 50-338/84-01 & 50-339/84-01 on 840104-0205 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/03/05 STEMART.H L Vipinia Electric & Power Co 2pp 22800 048 24X Fichs 50-338.84/03/05,8403270287
- --84032Y0274 IE Insp Repts 50-336/84-01 & 50-337/84-01 on 840106-0205 No violations or deviations identified Major areas Inspected onsite areas of surveillance & maint activities, previous insp findings & identified items & safety sys walkdowns BRANCH.N W . LUEHMAN.J G Region 2. Office of Director ELROD, B Division of Project & Resident Programs 84/03/02 10pp 22800 050 24X Fiche 50-336,84/03/03,8403290289
- 8402090024 IE Info Notice 84-09.Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York Inc 118pp 22635 049 24X Fiche 30-000.84/03/07.8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG:R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche \$0-000.84/03/12.8402090031
- B403270250 Ack receipt of B40306 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/83-31 & 50-339/93-31 LEWIS,R C Division of Project & Resident Programs B4/03/16 STEWART.W L Virginia Electric & Power Co 1p 22802,032. 24X Fiche 30-338.84/03/16.8403270250
- --B403270260 Responds to NRC B40207 ltr re violations noted in IE Insp Repts 50-338/83-31 & 50-339/83-31 Corrective actions wall classified as fire barrier & cubicles reclassified as seperate fire areas Procedure revised to include insp. BTEWART.W L Virginia Electric & Power Co B4/03/06 D'REILLY.JP Region 2. Office of Director 3pp 22802.033 24X Fiche 50-338,84/03/16.8403270250
- --8403270267 Forwards 1E Insp Repts 50-338/83-31 & 50-339/83-31 on 831206-840105 & notice of violation LEHIS.R C Division of Project & Resident Programs 84/02/07 BTEMART.W L Virginia Electric & Power Co 2pp 22802 036 24) Fiche 50-338,84/03/16,8403270250
- --8403290280 Notice of violation from Insp on 831206-840105 * Region 2, Office of Director 84/02/07 2pp 22802 038 24X Fiche 50-338,84/03/16,8403290250
- --8403270291 IE Insp Repts 50-338/83-31 & 50-339/83-31 on 831206-840105 Noncompliance noted failure to maintain procedures re insp of wall & fallure to inspect fire barnlers LUEHMAN.J C Region 2. Office of Director ELROD.8 Division of Project & Resident Programs 84/02/06 9pp 22802,040, 24X Fiche 50-338,84/03/16,8403290250
- 8402090043 IE lnfo Notice 84-17, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " 8vc list encl JURDAN,E L Divlsion of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Flohe 50-000,84/03/21,8402090043
- 8402090044 IE 1nfo Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list enc! JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001, 24X Ficha 50-900.84/03/21.8402090044
- 8403270021 Informs that due to add1 review required re mat1 supplied by Ray Hiller, Inc, utl1 unable to respond to IE Bulletin 83-07 until 840406 STEMART, W.L. Virginia Electric & Power Co. 84/03/22 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement, 1p. 22770 068 24X Fiche 50-000,84/03/22,8403270021.
- 8403270157 Resubmits 840302 response to 1E Builetin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications "Affirmation inadvertently omitted from 840302 ltr encl STEWART. W L Virginia Electric & Power Co 84/03/27 O'REILLY, J P. Region 2, Office of Director 2pp 22806 006 24X Fiche 50-000,84/03/29,8403290157

- R Periodic operating reports & related correspondence
- B403020122 Monthly operating repts for Jan 1984 W/840214 ltr LEE,J N , STEWART,W L Vinginia Electric & Power Co 84/01/31 HALLER:N M NRC - No Detailed Affiliation Given 23pp 22442 066 24X Fiche 50-33B.84/01/3: 8403020122
- 8403300055 Monthly operating repts for Feb 1984 W/840314 ltr LEE,J N . BTEWART.W L Virginia Electric & Power Co 84/02/29 HALLER,N M Dffice of Resource Management. Director 16pp 22821 270 24X Fiche 50-338,84/02/29,8403300055
- 8. Reportable occurrences. LERs & related correspondence
- 8305270051 Forwards technical review rept. "Blocking of Automatic Safety Injection (81) Bignals "LERs should be included in forthcoming power reactor events issue to alert other Westinghouse PUR operators CHIRAMALIM Reactor Operations Analysis Branch B3/04/25 SEVFRITIK V Reactor Operations Analysis Branch ip 22789 272 24X Fiche 50-000.83/04/25,8305270051
- --8305270056 "Blocking of Automatic Safety Injection (SI) Signal," technical review rept * Director's Office 83/04/25 4pp 22789 293 24X Ficha 30-000,83/04/25,8305270051
- 8403280332 Forwards preliminary results of natural circulation analyses for 811111 transient at McGuire & 800605 natural circulation low power test at North Anna CHARLTON.T R EG&O. Inc 83/09/22 LITTENEKER.P E Energy, Dept of, Idaho Operations Office 29pp 22807.259. 24X Fiche 50-000.83/09/22,8403280332
- 8403060153 Updated LER 83-061/03X-1 on 830921, both high head safety injection pumps removed from svc Caused by maint & high thrust bearing vibrations first pump tested satisfactorily & returned to svc W/840229 ltr HARRELL,E W Virginia Electric & Power Co 84/02/29 4pp 22513-387 24X Fiche 50-338,84/02/29,84033060153
- B403090213 NPDEB noncompliance notification re 840213 oil spill Caused by lube oil associated w/overflow of bearing cooling tower makeup reservoir Oil contained by floating boom & removed w/absorbent matis
 TAYLOR, J A Virginia Electric & Power Co 84/02/29 VOLTAOGIO, T Environmental Protection Agency. 7pp 22075 07B 24X
 Fiche 50-338,84/02/29,8403090213
- B403140010 LER 84-003-00 on 840208, turbine trip-reactor trip occurred due to spurious electro-hydraulic control fluid reservoir law level turbine trip signal Caused by pump vibration due to unloader malfunction Unloaders readjusted M/840307 ltr MARRELL,E W. Virginia Electric & Power Co 84/03/07 3pp 22632 141 24X Fiche 50-338,84/03/07,8403140010
- 8403190396 Forwards completed Oil Spill Questionnaire VA-84-093 for 840215 occurrence
 TAYLOR, J A Virginia Electric & Power Co 84/03/07 VOLTAGGIO, T Environmental Protection Agency 7pp 82675 193 24% Fiche 50-338,84/03/07,8403190396
- 8403170080 NPDEB noncompliance notification on 840214, lubricating oil spilled into Lake Anna, Caused by crack on intake screen of drive chain lubricant reservoir Completed spill Questionnaire VA-84-072 encl
 TAYLOR, J. A Virginia Electric & Power Co 84/03/08 VOLTAGOIO, T Environmental Protection Agency 7pp 22668 334 24X
 Fiche 50-338,84/03/08,8403170080
- 8403140122 Part 21 rept re status update concerning abnormal wear on linear converters. Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry DODSON, J.P. Pacific Air Products Co. 84/03/09 Director's Office, Office of Inspection and Enforcement 7pp. 22624.068 24X Fiche. 50-000, 84/03/09, 8403140122.

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

- A. Application/construction stage documents & correspondence
- 8403080179 Fourth partial response to FOIA request for aix categories of documents are facilities Forwards App A documents App B document stricely withheld (ref FOIA Exemption 5). Review of addl documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERBON.S I Garvey, Schubert, Adams k Berer 7pp, 22583 226 24% Fiche: 50-000,84/02/13,8403080179

- F Security, medical, emergency & fire protection plans
- B403070239 Forwards SALP Repts 50-280/83-33,50-281/83-33,50-338/83-33 & 50-339/83-33 for Dct 1982 Aug 1983 Evaluation will be discussed at 831208 meeting at North Anna sits.

 LEWIS.R C Division of Project & Resident Programs 83/11/25 STEWART.N L Virginia Electric & Power Co 2pp 22536 227 24X Fiche 50-000.83/11/25,8403070239
- --8403070246 SALP Repts 50-280/83-33,50-281/83-35,50-338/83-33 & 50-339/83-33 for Oct 1982 Aug 1983 Reliable performance U/Improvement in most previously noted areas of weakness demonstrated a Region 2, Office of Director 83/11/25 42pp 22536 227 24X Fiche 50-000,83/11/25,8403070239
- 8403060462 Grants 831031 request for exemption from requirements of App R to 10CFR30, Section III G 3 b re installing fixed fire suppression sys in control room Exemption encl MILLER, J R Operating Reactors Branch 3 84/02/23 STEWART, W L Virginia Electric & Power Co ip 22549-331 24% Fiche 50-338,84/02/23,8403060462
- --B4030A0466 Exemption from requirements of App R to 10CFR30, Section 111 G 3 b re installing fixed fire suppression sys in control room.

 EIBENHUT, D 9 Division of Licensing B4/02/23 Virginia Electric & Power Co 4pp 22347 332 24X Fiche 50-338,84/02/23.8403060462
- 8403170263 Rev i to corporate emergency response plan W/840315 ltr STEWART.W L Virginia Electric & Fower Co 84/02/24 105pp 22670 135 24X Fithe 50-000.84/02/24,8403170263
- 8403050198 Forwards Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively & safety evaluation Amends revise Tach Specs to reflect addition & installation of new fire protection sys W/o encl ENOLE, L 8 Operating Reactors Branch 3, 84/02/28 STEWART, W L Virginia Electric & Power Co 1p 22528 184 24X Fiche 50-338.84/02/28,8403050198
- 8403080264 Forwards "Control Room Design Review Program Plan For North Anna & Burry Power Stations," in response to Suppl 1 to NUREG-0737 Review expected to be completed by 850810 BYEWART,W L. Virginia Electric & Power Co. 84/03/01 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22557 295 24X Fichs 50-000.84/03/01.8403080264
- --B403080269 "Control Room Design Review Program Plan for North Anna & Burry Power Stations." in response to Suppl 1 to NUREO-0737 # Virginia Electric & Power Co 84/03/01 111pp 22557 299 24X Fiche 50-000.84/03/01,0403080264
- 8403080091 Bubmits add1 info in order to conduct detailed review of emergency response procedures generation package, per 840125 request Items i & 2 will be addressed by 840330 Item 3 should be addressed by Westinghouse Owners Group STEWART.W L Virginia Electric & Power Co. 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22559 199 24X Fiche 50-000,84/03/02,8403080091
- 8403160276 Extends invitation to attend 840316 workshop at regional ofc to discuss 10CFR50, App R requirements & results of inspato help resolve misunderstandings associated w/requirements LEHIS, R C Division of Project & Resident Programs 84/03/02 BTEWART, W L Virginia Electric & Power Co 1p 22660'080 24X Fiche 50-000, 84/03/02, 8403160276
- B403260273 Forwards corrected Tech Spec pages for Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively, covering exial power distribution monitoring sus, penetration fire barriers & fire detection instrumentation ENOLE, L B Operating Reactors Branch 3 84/03/06 STEHART, H L, Virginia Electric & Power Co ip 22761 343 24X Fiche 50-338:84/03/06.8403260273
- --8403260281 Corrected Tech Spec pages to Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively, covering axial power distribution monitoring sys, penetration fire barriers & fire detection instrumentation

 * Operating Reactors Branch 3 84/03/06, 15pp. 22761 344 24X Fiche 50-338, 84/03/06, 8403260273
- B403190052 Informs that local emergency operations facilities at North Anna & Burry Power Stations will be functional, except for data communications & display, by B50731, per NUREG-0737, Suppl i.

 STEWART, W L Virginia Electric & Power Co B4/03/14 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 2pp 22666·173 24X Fiche. 50-000. B4/03/14. B403190052

- 3403270250 Ack receipt of B40306 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-338/83-31 & 50-339/83-31
 - 30-339/83-3: LEHIS, R C Division of Project & Resident Programs 84/03/16 BTEWART, W L Virginiz Electric & Power Co 1p 22802 032 24 Fiche 30-338,84/03/16,8403290250
- --B403290260 Responds to NRC B40207 ltr re violations noted in IE Insp Repts 50-338/83-31 & 50-339/83-31 Corrective actions wall classified as fire berrier & cubicles reclassified as saperate fire areas. Procedure ravised to include insp BTEMART.W L Virginia Electric & Power Co B4/03/06 O'REILLY.J P. Region 2. Office of Director 3pp. 22802 033 24X Fiche.50-338.84/03/16.8403270250
- -8403290269 Forwards IE Insp Rspts 50-338/83-31 & 50-339/83-31 on 831206-840105 & notice of violation LEMIS.R C. Division of Project & Resident Programs 84/02/07 8TEMART.W L Virginia Electric & Power Co 2pp 22802 036 24X Fichs 50-338,84/03/16.8403290250
- ~-8403290280 Notice of violation from insp on 831206-840105 * Ragion 2, Office of Director 84/02/07, 2pp 22802:038 24X Fiche 50-338,84/03/16,8403290250
- --8403290291 IE Insp Repts 50-338/83-31 & 50-339/83-31 pn 831206-840105 Noncompliance noted failure to maintain procedures re insp of wall & failure to inspect fire barriers LUEHMAN, J G Region 2, Office of Director 84/02/06 9pp 22802 040 24X Fiche 50-338/84/03/16/8403290250
- P Operating licenss stage documents & correspondence
- 8403070001 Notifies that Class III & Class I fees submitted w/820608 application for amend will be refunded, based on 840123 withdrawal of application.

 MILLER, W O Licanse Fee Menagement Branch 84/02/24 STEWART, W L Virginia Electric & Power Co ip 22562.343 24X Fiche 50-338,84/02/24,8403070001
- 8403020195 Forwards add1 info to compiste review of Topicel Rspt VEP-FRD-41. "VEPCO Reactor Bys Transient Analysis Using RETRAN Computer Code," in response to NRC 1982 (informal request STEMART, W L. Virginia Electric & Power Co. 84/02/27 DENTON: H R Defice of Nucisar Reactor Regulation, Director 16pp 22443 257 24X Fiche 30-000.84/02/27,8403020195
- 8403050229 Submits reviaw of post-accident sampling sys. Item 11 B 3 Ten of it criteria met Remaining critation re procedura for estimating extent of core damage based on radionucitée evaluation, acceptable on interim basis.

 MILLER. J R Operating Resectors Branch 3 84/02/27 STEWART. W L Virginia Elactric & Power Co 6pp 22528:001 24X Fichs 50-000.84/02/27.8403050229
- B403020001 Requests interim approval of inservice into & testing requirements for pumps & valves Approval would increase scope of into & testing & anhance safety Implementation of revised inservice testing programs expected by 840315 SIEWART, W L. Virginia Electric & Power Co. 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 22442 155 24X Fichs 50-338.84/02/28.8403020001
- 8403020042 Forwards revs to inservice testing program for pumps & valvas, clarifying previous submittals
 STEWART, N. U. Virginia Electric & Power Co. 84/02/28 DENTON, H.R. Office of Nuclear Reactor Regulation, Director MILLER, J.R. Operating Reactore Branch 3 15pp 22442 272 24X
 Ficha. 50-338,84/02/28,8403020042
- 8403030198 Forwards Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively & safety evaluation Amends ravisa Tech Specs to reflact addition & installation of new fire protection bys W/o ancl ENGLE, B Operating Reactors Branch 3 84/02/28 STEWART, W L Virginia Electric & Power Co ip 22528 184, 24x Ficha 50-338,84/02/28.8403050198.
- E4031R0176 Advises that i1.6% permit responsibility transferred to Old Dominion Electric Cooperativs on 831221, per 840131 ltr Requests NPDES permit & 401 certificate dtd 720211 be modified to reflect transfer W/o stated encl TAYLOR.J A. Virginia Electric & Power Co. 84/03/01. BURTON.R.M Virginia. Commonwealth of, ip 22590, 203 24% Fiche 30-338.84/03/01,8403120174

- B4030B0071 Informs NRC that submittal date for low pressure turbine disc cracking rept delayed until 840330 due to delay in Bouthwest Research receipt of dissected disc.

 STEWARTH L Virginia Electric & Power Co. 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation. Director MILLER, J R Operating Reactore Branch 3 ip 22560 024. 24X Fiche 50-339.84/03/02,84030B0071
- B403210203 Forwards Amends 52 & 36 to Licensee NPF-4 & NPF-7, respectively Amends clarify testing requirements in Tech Spac Table 3 6-i re containment isolation valves ENOLEL B Operating Reactors Branch 3 84/03/06. STEWARY, M. L Virginia Electric & Power Co 3pp 22709 192 24X Fiche 50-338.84/03/06.8403210203
- --8403210206 Amende 52 & 36 to Licaness NPF-4 & NPF-7, respectively, clarifying testing requirements in Tach Spec Table 3 6-1 recontainment isolation valves MILLER, J R Operating Reactors Branch 3 84/03/06 9pp. 22709 195 24X Fichs 50-338,84/03/06,8403210203.
- 8403260273 Forwards corrected Tsch Bpsc pages for Amsnds 51 & 35 to Licsnsas NPF-4 & NPF-7, respectively, covering axial power distribution monitoring sys, psnstration fire barriers & fire detection instrumentation.

 ENGLE.L B Operating Reactors Branch 3 84/03/06, STEWART, W L Virginia Electric & Power Ce ip 22761-343 24X Fiche 50-338.84/03/06,8403260273
- --8403260281 Corrected Tech Spec pages to Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively, covering extal power distribution monitoring systemstration fire barriers & fire detection instrumentation • Operating Resctore Branch 3 84/03/06 15pp 22761:344 24X Ficha 50-388.84/03/06.8403260273
- 8403130298 Provides implementation 1tr rapt for reactor vessal Isvel instrumentation sys, per NRC 840116 1tr & TMI Action Itsm 1I F 2. Requests NRC approve use of instelled reactor vessal level instrumentation based on previous acceptance. STEWARTH L. Ulrighina Electric & Power Co. 84/03/07, DENTON, H R Office of Nuclear Reactor Regulation, Director, EISENHUT, D Q. Division of Licensing 3pp 22607, 360, 24X Fiche 50-338,84/03/07,860,310298
- 8403190201 Application for amend to Licansa NPF-7, changing Tech Space to delste Surveillance Requirement 4 8 i, i 2 c, 6 re simulated loss of diesel generator w/offsits power unavailable.psr Genaric Ltr 83-30 STEMART.W L Virginia Electric & Power Co 84/03/15 DENTON.H.R. Office of Nuclear Reactor Regulation. Director MILLER, J R. Operating Reactors Branch 3 3pp 22671.123 24X Fiche 50-339,84/03/15,8403i90201
- ~-8403190204 Proposed Tech Spec changs's raffecting diletion of Burveillance Requirement 4 8 i.i.2.c.6 re simulated loss of dissel generator w/offsite power unavailable.

 * Virginta Electric & Power Co. 84/03/15 5pp 22671:127. 24X Fiche 50-339,84/03/15,8403190201
- 8403190377 Application for emend to Licenses NPF-4 & NPF-7.changing Tach Epecs to delate raquiraments for min & max temp limits for A36 & A572 beams in steam generator supports & determination of beam temps STEWART.H L Virginia Electric & Power Co 84/03/15 DENTON.H.R. Office of Nuclear Reactor Regulation. Director MILLER.J.R. Operating Reactors Branch 3 3pp. 22675.237. 24X Fichs 50-339.84/03/15.8403190377.
- --8403190381 Proposed Tech Boacs delsting requirements for min & max tsmp limits for A36 & A572 beams in steam generator supports & determination of basm temps. Request for removal of steam generator support heaters & insulating tent encl # Virginia Electric & Power Co. 84/03/15, 30pp. 22675,240 24X Fiche 50-338,84/03/15,8403190377
- 8403220028 Application for amand to Licenses NPF-4 & NPF-7, revising Tach Specs to reflect new LER sys.par 10CFR50, 73 & immediate notification requirements, per 10CFR50, 72.

 8TEWART.W.L. Virginis Electric & Power Co. 84/03/16, DENTON, H.R. Office of Nuclear Reactor Regulation, Director MILLER, J.R. Operating Resctors Branch 3, 4pp. 22713, 128 24X Fiche 50-338,84/03/16,8403220028.
- --B403220032 Proposed Tach Space reflecting new LER sys & immediate notification requirements.

 * Virginia Electric & Power Co B4/03/16. 85pp. 22713:132. 24X Fiche: 30-338,84/03/16.840320028.

- B403220077 Requests exemption from 10CFR50 44(c) (3) (iii) requirements Operability of reactor vessel head vents should be verified during proposed outages & procedures & training implemented Wrevised emergency operating procedures BTEMART, H L Virginia Electric & Power Co 84/03/16 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 2pp 22712 311 24X Fiche. 50-338, 84/03/16, 8403220077
- 8403270208 Forwards youther theck for required license amend fees omitted from 840315 ltr
 BTEWART.W L Virginia Electric & Power Co 84/03/23 DENTON, M R
 Office of Nuclear Reactor Regulation, Director MILLER, J R
 Operating Reactors Branch 3. ip. 22772 084 24X
 Fiche. 50-338, 84/03/23, 8403270208
- 840327024B Forwards fee for 84031D proposed Tech Spec change. BTEWART, W.L. Virginia Electric & Power Co 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 ip 22771 311 24X Fiche. 30-339, 84/03/23, 840327024B.
- 8403300028 Forwards response to 840116 request for add1 info re core exit thermocouple (CETC) & subcooling margin monitoring sys, per 840130 commitment CETC add1 info deferred until after 840801 due to sys replacement per Reg Ouide 1 97.

 8TEWART.W L Virginia Eisectric & Power Co 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D. O Division of Licensing 4pp 22821.307 24X Fiche 50-338,84/03/23.
- 8403300005 Informs that independent testing lab conducting overvoltage tests on motor control ctr contactor coils Current schedule for completing tests is May 1984 Resolution & related schedule will be submitted by Jul 1984 STEMART.W L. Virginia Electric & Power Co 84/03/26 DENTON.H R Office of Nuclear Reactor Regulation, Director MILLER, J. R Operating Reactors Branch 3. ip 22822:123 24X Fiche: 50-338,84/03/26,8403300005
- Q Inspection reports. IE Bulletins & correspondence
- 8403070239 Forwards 8ALP Repts 50-280/83-33, 50-281/83-35, 50-338/83-33 & 50-339/83-33 for Oct 1982 Aug 1983 Evaluation will be discussed at 831208 meeting at North Anna site LEWIS, R. C. Division of Project & Resident Programs 83/11/25 BTEWART, W L. Virginia Electric & Power Co 2pp 22536 227 24X Fiche: 50-000, 83/11/25, 8403070239.
- --8403070246 SALP Repts 50-280/83-33, 50-281/83-35, 50-338/83-33 & 50-339/83-33 for Oct 1982 Aug 1983 Relieble performance w/improvement in most previously noted areas of weekness demonstrated.

 * Region 2, Office of Director 83/11/25 42pp, 22536, 229, 24x Fichs: 50-000, 83/11/25, 8403070239
- 8403070279 Discusses SALP evaluation Issuance of BALP rept approved No major weaknesses identified during essessment period at , North Anna One major weakness identified in area of radiological controls at Surry O'REILLY, J P Repion 2, Office of Director, 84/02/16 BTEHART, W L Virginia Electric & Power Co. 2pp. 22541-286 24X Fiche: 50-000,84/02/16,8403070279
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/28. Consolidated Edison Co. of New York: Inc. 115pp. 22709.239 24X Fiche.50-000.84/02/28.8401170072
- 8403020001 Requests interim approval of inservice insp & testing requirements for pumps & valves Approval would increase scope of insp & testing & enhance safety Implementation of revised inservice testing programs expected by 840310.

 8TEHART.W L. Virginia Electric & Power Co 84/02/28. DENTON.H R Office of Nuclear Reactor Regulation, Director. MILLER, J.R. Operating Reactors Branch 3. 2pp 22442 155. 24X Fiche: 50-338.84/02/28.8403020001.
- B402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Svc list encl GRACE, J. N. Division of QA. Safeguards & Inspection Programs (Post B30103). B4/03/02 Consolidated Edison Co. of New York, Inc 130pg. 22552:329. 24X Fiche: 50~000,84/03/02,8402090007.
- B40209000B IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate." Byc list encl.

 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). B4/03/02. Consolidated Edison Co. of New York, Inc. 122pp. 22553.098 24X Fiche.50-000,84/03/02.8402090008

- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases "
 Svc list encl
 JURDAN,E L Division of Emergency Preperedness & Engineering
 Response (Post 830103) 84/03/02, Consolidated Edison Co of New
 York, Inc. 119pp 22553 217 24X Fiche 50-000.84/03/02,8402090009
- 8403i60154 Responds to IE Bulletin 83-0B re electrical circuit breakers W/undervoltage trip feature in use in sefety-related applications other than trip sys Only reactor trip breakers contain subj trip attachments
 BTEWART,W L Virginia Electric & Power Co 84/03/02 O'REILLY,J P
 Region 2. Office of Director 2pp 22806 008 24X
 Fiche 50-000.84/03/02.8403160154
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Conecolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403290289 Forwards IE Inep Repts 30-338/84-01 & 30-339/84-01 on 840106-0205 No violations or deviations identified DANCE: H C Division of Project & Resident Programs 84/03/05 STEHART, H L Virginia Electric & Power Co. 2pp 22800,048, 24X Fiche 50-338,84/03/05,8403290289
- --8403270274 IE Insp Repts 50-338/84-01 & 50-339/84-01 on 840106-0205 No violations or deviations identified Major ereas inspected, onsite areas of surveillance & meint activities, previous insp findings & identified items & safety sys walkdowns BRANCH.M W , LUEHMAN.J Q. Region 2. Office of Director ELROD,S Division of Project & Resident Programs 84/03/02, iOpp 22800 050 24X Fiche 50-338.84/03/05,8403270289
- 8402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preperadness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000, 84/03/07, 8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys," Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Rasponse (Post 830103), 84/03/07 Consolidated Edison Co of New York, Inc. 118pp. 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 840207003i IE Bulletin 84-02, "Feilures of GE Type HFA Releys in Use in Class IE Safety Sys " Syc list encl DEYDUNG, R C Director's Office, Office of Inspection and Enforcement B4/03/12 Cansolidated Edison Co of New York, Inc 134pp, 22823 074 24x Fiche 50-000,84/03/12,8402070031
- 8403290250 Ack receipt of 840306 ltr informing NRC of steps taken to correct violations noted in IE Insp Repte 50-338/83-31 & 50-339/83-31.

 LEHIS,R.C Division of Project & Resident Programe 84/03/16
 BYEWART,N L. Virginia Electric & Power Co. 1p 22802 032 24X
 Fiche 50-338.84/03/16.8403290220
- --8403270260 Responds to NRC 840207 ltr re violations noted in IE Insp Repts 50-338/83-31 & 50-339/83-31 Corrective ections wall classified as fire barrier & cubicles reclassified as seperate fire ereas Procedure revised to include insp STEMART.M.L. Virginia Electric & Power Co. 84/03/06 O'REILLY.J P Region 2, Office of Director 3pp. 22802,033 24X Fiche 50-338,84/03/16,8403290250
- --8403270267 Forwards IE Insp Repts 50-338/83-31 & 50-339/83-31 on 831206-840105 & notice of violation LEMIS.R.C. Division of Fraget & Resident Programs 84/02/07 8TEMART.W.L. Virginia Electric & Power Co. 2pp. 22802.036 24X Fiche.50-338,84/03/16,8403270250
- --8403270280 Notice of violation from insp on 831206-840105. * Region 2, Office of Director. 84/02/07 2pp 22802 038 24X Fiche. 50-338,84/03/16,8403270250.
- B402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities " Syc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103). B4/03/21. Consolidated Edison Co. of New York, Inc. 123pp. 22823-229 24X Fiche.50-000,84/03/21,8402090043

- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related 8ys " Svc list encl JORDAN: E L Division of Emergency Preparedness & Enginsering Rasponse (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402070044
- 8403270021 Informs that due to addl review required re matl supplied by Ray Miller. Inc. util unable to respond to IE Bulletin 83-07 until 840406 STEWART. W L. Virginia Electric & Power Co. 84/03/22. DEYDUNG, R.C. Director's Office. Office of Imspection and Enforcement 19 22770-048 24X Fiche 50-000,84/03/22,8403270021
- 8403270157 Resubmits 840302 response to 1E Bulletin 83-08, "Electrical Circuit Breakers WVIndervoltage Trip Feature in Use in Safesty-Related Applications ." Affirmation inadvertently omitted from 840302 ltr sncl STEWART, W.L. Virginia Electric & Power Co. 84/03/27, O'REILLY, J.P. Region 2, Office of Director 2pp. 22806-006. 24% Fiche 50-000,84/03/29,8403290157
- . Periodic operating reports & related correspondence
- 8403020122 Monthly operating repts for Jan 1984 W/840214 ltr LEE,J N , STEWART.W L Virginia Electric & Power Co B4/01/31 HALLER.N H NRC - No Dataliad Affiliation Given. 23pp 22442-066 24X Fiche 50-338.84/01/31.8403020122
- B403300055 Monthly operating repts for Feb 1984 W/840314 ltr LEG,J N , BTEMART.W L Virginia Electric & Power Co 84/02/29 HALLER,N M Office of Resource Management, Director 16pp 22821 270 24X Fichs 50-338,84/02/29,8403300055
 - Reportable occurrences, LERs & related correspondence
- 9403280332 Forwards preliminary results of natural circulation analyses for 81:11: transient at McQuire & 800605 natural circulation low power test at North Anna GHARLTON,T R 2040, Inc 93/09/22 LITYENEKER,P E Energy, Dept of, Idaho Opsrations Office 29pp 22807 259 24X Fiche 50-000,83/09/22,8403280332
- 8403090213 NPDES noncompliance notification rs 840213 oil spill Caused by lube oil associated w/overflow of bearing cooling tower makeup reservoir Oil contained by floating boom & removed w/absorbent matls TAYLOR, J. A Virginia Electric & Power Co 84/02/29 VOLTAGGIO, T Environmental Protection Agency 7pp 22575 078, 24X Fiche 50-338.84/02/29,8403090213
- 3403190396 Forwards completed Oil Spill Questionnaire VA-B4-093 for B40213 occurrence TAYLOR.J. A Virginia Electric & Power Co 84/03/07 VDLTA0010.T Environmental Protection Agency. 7pp 22675 193 24X Fiche 50-338.84/03/07.8403190396.
- 34031900B0 NPDES noncompliants notification on 840214, lubricating oil spilled into Lake Anna Caused by crack on intake screen of drive chain lubricant reservoir Completed spill Questionnairs VA-84-092 enc1
 TAYLOR, J.A. Virginia Electric & Power Co. 84/03/08 VOLTAQQIO, T Environmental Protection Agency 7pp 22668 334 24X
 Fiche 50-338,84/03/08,84031900B0
- MCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2 . Application/construction stage documents & correspondence
- 3403140340 Summary of B31215 meeting w/QE & Marx I Owners Group in Bethesda. MD ra Merx I containment wetwell-drywsll vacuum brasker dasign methodology SIEGEL. B.L. Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24% Fiche 50-000, 84/02/21, 8403140340,
- 3403020164 Submits request for addl info re postulated failurs of HPCl steam line w/o isolation.
 YOUNGELOOD, B. J. Licensing Branch 1 84/02/22, JENS, W. Detroit Edison Co. 3pp. 22491-135 24X Fiche-30-341,84/02/22,8403020164
- 3403020121 Rssponds to 840105 Osneric Ltr 84-01 rs NRC use of terms important to safety & safety-related. Bubj will be discussed further through steering committee & chairman of Util Bafety Classification Group JENBLW H Detroit Edison Co 84/02/24, TAYLOR, J M. Director's Office. Office of Inspection and Enforcement. ip 22442-065, 24X Fiche 50-041,84/02/24,8403020121

- 8403090247 Advises that util will adopt all applicable provisions associated w/8 h Type A test detailed in Rev 1 to Bh-TGP-1, "Testing Criteria for Integrated Leakage Rats Testing of Primary Containment Structures for Nuclsar Plants "
 JENB.W H Detroit Edison Co 84/03/05 YOUNGBLOOD, B J Licensing Branch i 1p 22572 201 24X Fichs 50-341,84/03/05,8403090247
- B403130009 Forwards Certificate of 8vc for Amend 53 to amended & substituted application for licenses HATHAHAY.0 H Detroit Edison Co B4/03/09 Office of Nuclear Reactor Regulation. Director. 3pp 22615 166 24X Fichs 80-341
- 8403130044 Forwards Amend 54 to amended & substituted application for licenses, consisting of Amend 54 to FBAR LANDGRAF, L. C. LeBoeuf, Lamb, Leiby & MacRae LANDGRAF, L. C. Detroit Edison Co. 84/03/09 DENTON, H. Office of Nuclear Reactor Regulation, Director ip 22610 168 24X Fichs 50-341,84/03/09,8403130044
- --8403130051 Amend 54 to amended & substituted application for licensss, consisting of Amend 54 to FBAR * Duquesne Light Co 84/02/R2 ip R2610 169 24X Fichs 50-341,84/03/97,8403130044
- 8403200185 Affirms resolution of TMI Action Flam Item II K 3 31 rs small break LOCA analysis No further action necessary JENS.H H Detroit Edison Co 84/03/14 YOUNGBLOOD, B. J Licensing Branch 1 2pp 22686 338 24% Fiche. 50-341.84/03/14.8403200185.
- 8403210048 Requests issuance of proof & review version of Tech Space Resources to support effort available & impact of obtaining add1 test data minimal JENSIN H Detroit Edison Co 84/03/14 YOUNOBLOOD, B J Licensin Branch 1 1p 22706 333, 24X Fiche 50-341,84/03/14,8403210048
- 8403210074 Forwards "Environ Qualification of Bafsty-Related Mechanical Equipment for Harsh Environ," per 831201 masting JENS, H H Detroit Edison Co. 84703/14, YDUNGBLOOD, B J Licensing Branch i 1p 22706 140 24X Fiche 50-341,84703/14,8403210074
- --8403210078 "Environ Qualification of Bafety-Related Machanical Equipment for Harsh Environ" * Datroit Edison Co 84/03/31 150pp 22706 141, 24X Fiche. 50-341:84/03/14.8403210074
- B403230018 Forwards revised NRC licensed operator training requalification program, administrative guide, incorporating addressed comments contained in 831219 itr JENS W H Detroit Edison Co 84/03/14 YOUNOBLOOD, B J. Licensing Branch 1 1p 22726 178 24X Fichs. 50-341, 84/03/14, 8403230018
- --B403230021 NRC licensed opsravor training requalification program administrator guide

 # Dstroit Edison Co. B4/01/31 50pp. 22726 179 24X Fichs 50-341.84/03/14.8403230018
- 8403280237 Discusses WV Lipton qualification review, per 840119 response to request for add1 info Lipton qualified as radiation protection manager, per Reg Guide 1 8 YOUNOBLEOD, B J Licensing Branch i 84/03/14 JENS, W. Detroit Edison Co 2pp 22808.210, 24% Ficher 50-341,84/03/14,8403280237
- 8403270043 Informs that ultrasonic test sxams of blend radii ersa & magnetic particle sxam conducted by vess1 mfg to determine degree of conformancs to NUREO-OA19 No recordable indications found utilizing either techniqus

 JENS.# H Detroit Edison Co 84/03/21, YOUNOBLOOD, B. J. Licensing

 Branch 1 1p 22769.315 24X Fiche: 50-341,84/03/21,8403270043
- 8403300138 Forwards Certificate of Bvc indicating appropriate parties served w/Amend 34 to amended & substituted application for licenses HATHAHAY,0 H. Detroit Edison Co. 84/03/26 Office of Nuclear Resector Regulation, Director. 3pp 22820.349 24X Fiche:50-341.84/03/26,8403300138
- F Security, medical, emergency & fire protection plans
- 8403120049 Extends invitation to attend regional workshop on fire protection safe shutdown requirements of 10CFR50.App R on 840323 in Rosemont, IL Proposed agenda encl for review PPEBSARD.R L Division of Emergancy Preparedness & Operational Support 84/03/06 WELLB.D.A Detroit Edison Co. 3pp. 22589:292 24X Fiche. 50-341.84/03/06.8403120049.

H General correspondence

- E403280045 Responds to 840217 inquiry re plants not considered for insp of vent header cracks in torus Insp inapplicable becauss Fermi & Hope Creek skill in const stage DENTON.H R. Office of Nuclear Reactor Regulation, Director 64/03/12 WESTOVER.A T Monroe County, MI ip 22812 358 24X Ficher 50-000.84/03/12.8403280045
- --B403280054 Requests explanation as to why facility not considered for insp for cracks in vent header similar to crack found at Hatch.

 WEBTOVER, A. J. Monroe County, MI 84/02/17 Office of Nuclear Reactor Regulation, Director 2pp. 22812 359 24X

 Fiche. 50-000, 84/03/12, 8403280045

K. Utility Final Safety Analysis Report (FSAR) & amends

- 8403i30044 Forwards Amend 54 to amended & substituted application for licenses, consisting of Amend 54 to FBAR LANDQRAF,L C LeBoeuf, Lamb, Leiby & MacRae. LANDQRAF,L C. Detroit Edison Co 84/03/09 DENTON,H Office of Nuclear Reactor Regulation, Director 1p. 22610 i68 24X Fiche. 50-341,84/03/09, 8403i30044.
- --8403130051 Amend 54 to amended & substituted application for licenses, consisting of Amend 54 to FBAR.

 e Duquesne Light Co. 84/02/22 ip 22610.169 24X Fiche.80-341,84/03/09.8403130044
- --8403130060 Amend 54 to FSAR Twenty-eight oversize drawings encl.
 Drawings available in PDR
 # Detroit Edison Co 84/03/31 789pp 22610.170 24X
 Fiche 50-341.84/03/09.8403130044

G. Inspection reports, IE Bulletins & correspondence

- 840:190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Velve Control Circuits & Annunciation." Svc list enci. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/28 Consolidated Edison Co. of New York, Inc. Ii5pp. 22709:239. 24X Fiche 50-000,84/02/28,8401190072
- 8403060170 Ack receipt of 840217 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Rept 50-341/83-27 KNOP,R C. Region 3, Office of Director. 84/03/01 WELLS,D.A Detroit Edison Co. 1p. 22518 337 24X Fiche: 50-341/84/03/01, 8403060170
- --8403060173 Resubmits 840123 response to NRC 831222 ltr re noncompliance noted in IE Insp Rept 50-341/83-29.

 HELL&I.D.A Detroit Edison Co. 84/02/17 KNDP.R C. Region 3, Office of Director 1p. 22518.338 24X Fiche 50-341.84/03/01.
- --8403060177 Responds to NRC 831222 ltr re noncompliance noted in IE Insp Rept 50-341/83-27 Corrective actions.Plant Operation Manual 12,000 revised.damaged unistrut scrapped & satellite storage areas marked & roped off WELLS.D.A., ALESSI,T.A Detroit Edison Co. 84/01/23. KNOP.R C Region 3, Office of Director 5pp 22518:339. 24X Fichs.50-341,84/03/01,8403060170
- 8403170307 Forwards IE Insp Rept 50-341/84-03 on 840131 & 0201-02.No noncompilance noted, PAPERIELLO.C.J. Region 3, Office of Director, 84/03/01 WELLS,D A Detroit Edison Co. 2pp. 22673 168 24X Fiche.50-341.84/03/01, 84031
- --B403190313 IE Insp Rept 50-341/B4-03 on B40131 & 0201-02 No noncompliance noted, Major areas inspected; preoperational radiological environ monitoring program including mpt controls & program implementation & results OESTMANN.M.J., SLAMINSKI.M.J., SCHUMACHER.M.C Region 3, Office of Director. B4/02/29, 9pp 22673:170. 24X Fiche.50-341,84/03/01.
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Svc list encl. ORACE.J.N. Division of GA. Bafeguards & Inspection Programs (Post 830103), 84/03/02, Consolidated Edison Co. of New York, Inc 130pp. 22552:329. 24X Fiche: 50-000.84/03/02.8402090007
- 8402070008 IE Info Notice 84-i6, "Failure of Automatic Sprinkler Sys Valves to Operate." Syc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/02, Consolidated Edison Co. of New York, Inc. 122pp. 22553:098. 24X Fiche: 50-000.84/03/02.8402070008

- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases" 8vc list encl JORDAN.EL Division of Emergency Praparedness & Enginsering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 117pp 22553 217 24X Fichs 50-000.84/03/02.8402070007
- 8402090011 IE Info Natice 84-17, "Problems W/Liquid Nitrogen Caoling Components Below Nil Ductility Temp " Svc list enc! JURDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05. Consolidate Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403220109 Forwards IE Insp Rept 50-341/83-30 on 831201-840131 & notice of violation KNOP.R C Region 3. Office of Director 84/03/05 WELLS,D A Detroit Edison Co 2pp 22716 197 24X Fichs 30-341.84/03/05, 04.0730109
- --8403220111 Notice of violation from imap on 831201-840131 KNOP.R C Region 3, Office of Director 84/03/05 2pp 22716 199 24X Fiche 30-341,84/03/05,8403220109
- --8403220114 IE Insp Rept 50-341/83-30 on 831201-840131 Noncompliance identified HPCI sys test procedure not rsvisued for campleteness & adequacy & RCIC sys did not incorporate all valve timing requirements in FSAR BYRON.P M . PARKER.M E . KONKLIN.J E Region 3. Office of Director 84/03/02 15pp 22716 201 24X Fiche 50-341,84/03/05,8403220109
- 8402090024 IE Info Notice 84~09,Rsv I. "Lessons Learned From Insps of First Protection 8afs Shutdown Eys." Svc list encl JORDAN.E L. Division of Emergency Freparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp. 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " Svc IIst enci JORDAN,E L. Division of Emergency Preparedness & Engineering Responses (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. i18pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402070031 IE Bulletin 84-02, "Failures of 0E Type HFA Relays in Use in Class IE Safety Bys " 8vc list and DEYOUNG.R C Director's Office. Offics of Inspection and Enforcement 84/03/12 Consolidated Edison Co. of New York, Inc. 134pp 22823 074 24X Fiche: 50-000.84/03/12,8402070031
- 8403260127 Responds to IE Bulletin B3-08 re failures & problems w/ possible improper operation of circuit breakers w/ undervoltage trip attachments Field mod requests issued to remove undervoltage device from breakers HELLB.D A Detroit Edison Co 84/03/14 KEPPLER,J G Region 3, Office of Director 4pp 22758 143 24X Fiche 30-341,84/03/14,8403260127
- 8403300033 Forwards IE Insp Rept 50-341/84-01 on 840114-0217 No noncompliancs noted BTREETER, J F Region 3, Office of Director, 84/03/15 WELLS, D A Detroit Edison Co ip 22821 253 24X Fiche 50-341.84/03/15, 8403300053
- --B403G00057 IE Insp Rept 50-341/B4-01 on B40114-0217 No noncompliance or deviations noted Major areas inspected previous insp findings, preoperational test program procesdure review & verification, result review & test witnessing DUPONT. 8.0 , LANKBURY, R D. , REYEG. L. A Region 3, Offics of Director. B4/03/15 IOpp. 22821 254 24X Fiche 50-341.84/03/15, B403300053
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cevities." Svc list encl JORDAN.E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21. Consolidate Edison Co of New York, Inc 123pp 22823 229. 24% Fiche 50-000.84/03/21.8402090043
- B402090044 IE Info Notice 84-20, "Svc Life of Releys in Safety-Related Bys " Svc list encl JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp. 22933 001, 24X Fiche. 50-000, 84/03/21, 8402090044
- R. Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL revisus for Jan 1984, Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues.

 DIRCKS, H. J. Office of the Executive Director for Operations 84/02/21 PALLADINO Commissioners. 9pp 22492 083 24X Fiche 50-000, 84/02/21, 8403020443.

S Reportable Occurrences, LERs & related correspondence

- 8403120009 Interim deficiency rept. Item 55 re defective spot usids & Power-Strut support matl Initially reported on 820211 Evaluation for spot weld members for overload conditions continuing Addl use of members discontinued WELLS, D. A. Detroit Edison Co. 84/02/23 KEPPLER, J. G. Region 3, Office of Director 2pp 22588 029 24x Fiche 50-341,84/02/23, 8403120007
- 8403120160 Deficiency rept. Item 113 re linear indications in seem of ASTM ASOU OR B tube steel Initially reported in 840124 telcon Further evaluation pending completion of visual inspof electrical cable tray supports WELLS.D A Detroit Edison Co 84/02/23 KEPPLER.J G Region 3, Office of Director 2pp 22590-142 24% Fiche 5D-341,84/02/23,8403120160
- 8403120155 Deficiency rept. Item i15 re possible impingement of essential piping during pipe break Initially reported on 840124 Sueep paths & jet impingement rones will be reevaluated & pipe break locations reassessed HELLB.D A Detroit Edison Co 84/02/25 KEPPLER.J G Region 3. Office of Director 2pp 22586 248 24X Fiche 50-341,84/02/25,8403120155
- 8403120068 Interim deficiency rept. Item ilo re potential for freezing of buried fire protection sys piping to RHR bldg Initially reported on 840631 Mater will be passed through line once per whift during freezing weather MELLS.B A Detroit Edison Co 84/02/29 KEPPLER, J & Region 3, Office of Director 1p 22590 284 24X Fiche 50-341,84/02/29,8403120068
- 8403190079 Interim deficiency rept. Item i14 re possible overpressurization of north RHR HX (PiS Eii-01-800iA) Initially reported on 840124 Leakage observed coming through insulation in HX sheii flange No piping demage found WELLS.D A Detroit Edison Co 84/03/07 KEPPLER.J @ Region 3. Office of Director 2pp 22668 341 24X Fiche 50-341.84/03/07, 8403190079

T Hearing transcripts on non-antitrust matters

8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Duners Group Distribution list encl EISEN-RUT, D O Division of Licensing 84/D3/12 PALLADINO Commissioners 5pp 22708 001 24X Fiche 50-000, 84/03/12, 8402090039

V Operator Examinations

- 8403090188 forwards updated info re operator licensing exams Submittal includes estimate of need for operator licensing exams for remainder of FY84 & FY85 through FY87.

 JENS.W H Detroit Edison Co 84/03/05 YDUNOBLOOD.B Licensing Branch 1 2pp 22573 30R 24X Fiche 50-341.84/03/05.8403090188
- B403150021 Forwards individual operating shift experience status, per DF Schnell request Util will use shift advisors to satisfy hot participation experience requirements Licensed classroom training & exam conducted
 JENS.W H Detroit Edison Co B4/03/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 22643 043 24X Fiche 30-341.84/03/09.2403150021
- B403230018 Forwards revised NRC licensed operator training requalification program, administrative guide, incorporating addressed comments contained in B31219 ltr JEN9.4 H Setroit Edison Co B4/03/14 YOUNGBLOOD, B J Licensing Branch 1 1p 22726:178 24X Fiche 50-341,84/03/14,8403230018
- --8403230021 NRC licensed operator training requalification programmadministrator guide

 ** Detroit Edison Co 84/01/31 50pp. 22726 177. 24X
 Fiche 50-341,84/03/14,8403230018

OCKET 50-344 TROJAN NUCLEAR PLANT

- F Security, medical, emergency & fire protection plans
- 8400130381 Ack receipt of 831128 ltr transmitting changes to security plan Changes consistent w/provisions of 100FR50, 54(p) & acceptable schustent M Region 5, Office of Director. 84/01/20 WITHERB, B. D. Portland General Electric Co. 2pp. 22616, 276 24X Fiche 80-344, 84/01/20, 8403120381.

- 8403060341 Forwards IE Insp Rept 50-344/83-34 on 631128-1230, No noncompliance identified BISHOP.T.W Region 5. Office of Director 83/02/07 WITHERS, B. D Portland General Electric Co 2pp 22519, 073 24X Ficha. 50-344, 84/02/07, 8403060341
- --B403060344 IE Insp Rept 50-344/B3-34 on B3112B-1230, No noncompliance or deviations identified Major areas inspected plant operations, security, maint, surveillance testing, cold weather preparation & plant review board JOHNSTON, G W. RICHARDS, B A. DODDS, R T. Region 5, Office of Director B4/02/03 App 22519 075 24X Fiche: 50-344, B4/02/07, B403060341
- 8403120379 Forwards rept of results of in-progress audit for facility detailed control room design review per Buppi 1 to NUREO-0737 conducted on 831212-16 NUREO-0737 conducted on 831212-16 Publication of the Protein Operating Reactors Branch 3, 84/02/29, WITHERS, B.D. Portiand General Electric Co. 73pp 22619 008 24X Fiche 50-344,84/02/29,8403120379
- 8403190378 Revised emergency plan implementing procedures, including Procedure EP-1 re emergency ciassification.EP-7 re operation of technical support ctr & EP 8.6 re communications staff W/840314 ltr.

 # Portland General Eiectric Co 84/03/05 CLARK,R.A Office of Nucisar Resctar Regulation, Director. 72pp 22671:001 24X Fichs 50-344,84/03/05,8403190378
- 8403260302 Forwards exemption from 10CFR50 48 & App R to 10CFR50 refire protection for reactor coolant pump jubricating oil. Exemption conditioned on implementing fire protection improvements by plant startup MILLER, J. R Operating Reactors Branch 3 84/03/05 HITHERS, B D Portland General Electric Co 1p 22759, 349 24X Fiche 50-344, 84/03/05, 8403260302
- --8403260304 Forwards exemption from 10CFR30. App R fire protection requirements for FR publication * Division of Licensing 84/03/05 Docketing & Services Branch, 2pp 22759.350. 24X Fiche.50-344.84/03/05.8403260302.
- --B403260308 Exemption from 10CFR50 48 & App R to 10CFR50 requirements re fire protection for reactor coolant pump lubricating oil. EIBEMHUT.D 0 Division of Licensing 84/03/05 Portland General Electric Co 4pp 22759:352 24X Fiche 50-344.84/03/05. 8403260302
- 8403270240 Advises that 840112 rev to physical security plan consistant u/provisions of iOCFR50.54(p) & acceptable SCHUBTER,M B Region 5, OFFice of Director 84/03/22 WITHERB,B D. Portland General Electric Co 2pp 22800.253. 24X Fiche: 50-344.84/03/22.8403270240

O Adjudicatory correspondence

- B403220247 Response to Coalition for Safe Power & State of DR B40305 contentions Certificate of Svc encl JOHNSON:R W Portland General Electric Co DBB 056, 84/03/20, Admic Safety and Licensing Board Penel 46pp 22719:051 24X Fiche, 50-344, 84/03/20, 8403220247
- 8403300272 Forwards notices of appearance in proceeding of M Axelrad & BA Goldberg Certificate of Byc encl.
 AXELRAD.M Portland General Electric Co AXELRAD.M Newman & Hoitringer DB 215. 84/03/29 App. 22824.033 24X
 Fiche:50-344,84/03/29,8403300272

H General correspondence

- 8403060384 Advises that correspondence & pleadings should be directed to RM Johnson at listed address
 JOHNSON.R.W Portland General Electric Co. 84/02/29. SCHAEFER, K
 NRC NO Detailed Affiliation Given. 1p 22518:131 24X
 Fiche: 50-344,84/02/29,8403060384.
- J Insurance & indemnity information
- 8403200197 Forwards listing of present levels of property insurance & sources of insurance for facility. Info represents max amount of insurance coverage available for nuclear generating plants.

 WITHERS, 8 D Portland General Electric Co 84/03/16. MILLER, J. R. Operating Reactors Branch 3. 2pp. 22699.356 24X

 Fiche 50-344, 84/03/16, 8403200197
- 8403280022 Forwards Endorsement 8 to NELIA Policy EB-57.
 HIECHMANN, 8 H Portland General Electric Go. 84/03/20. BALTZMAN, J.
 Assistant Director for State & Licensee Relations 3pp. 22777.084.
 24X Fichs. 50-344, 84/03/20, 8403280022

- 8403280041 Forwards Endorsement 54 to MAELU Policy MF-86 & Endorsements 64 & 65 to NELTA Policy NF-225
 WIECKMANN, B M Portland General Electric Co 84/03/20 SALTZMAN, J
 Office of State Programs, Director App 22777 006 24X
 Fiche, 50-344, 84/03/20, 8403280041
- P. Oparating license stage documents & correspondence
- 8403010117 Partial response to FOIA request for documents by named individuals re repts analyses, studies, procedures & sys for measurement of RCB leakage App B documents placed in PDR App A documents already available in PDR PS sarch continuing FELTON, J M Division of Rules and Records 84/01/25 MADDEN, T J Kaye, Scholer, Fierman, Hays & Handler 7pp 22480, 026 24X Ficha. 50-000.84/01/25.8403010117
- --P403010175 Rev 6 to Procedure PDT-1-3, "Periodic Operating Test RCS Leakage Evaluation." LAMOUREAUX, T. H. Portland General Electric Co. 78/06/19 9pp 22481.184 224 Fiche 50-000,84/01/25.8403010117
- ---8403010233 Discusses RCS leak rata calculations, per 820504 telcon Mods to RCSLK7 computer program psymit isak rate calculations for pressures between 1,900 & 2,100 psig w/temp between 260 f & 270 F Plent data encl.

 MORRILL, F J. Region 5, Office of Director 82/05/05

 WOODRUFF, R W Reactor Engineering Branch 17pp. 22481,362 24X
 Flche: 50-000,84/01/25,8403010117
- 8403080344 FOIA request for documents ra proposed NSHC determination on license amends for Millstone 2 & entry into operational mode for conducting final tests of pressurizer safety valves at Trojan.

 ADATO,M Union of Concerned Scientists 84/02/02. FELTON, J M Division of Ruies and Records 1p 22583,038 24X Ficha 50-000.84/02/02.8403080344
- B403030223 Further response to FDIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCB leekage Forwards App C documents, Seerch continuing. FELTON, J. M Division of Rules and Records 84/02/07 MADDEN, T J Kaye. Scholer, Flarman, Hays & Handler Spp 22476 234 24X Ficher 50-000, 84/02/07, 8403050223
- --8403050250 Forwards plant-specific data cards for facilities re raector coolant leakage calculations, per Bio702 request, Add) data cards for remaining plants will be sent shortly CREMB, J. Division of Resident, Reactor Projects & Enginsering Inspection 81/09/16, BAER, R.L. Division of Resident & Regional Reactor Inspection 2pp. 22476 268 24X Fiche 50-000, 84/02/07, 8403050223
- B4030B0179 Fourth partial response to FOIA request for six categorias of documents ra facilities. Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON.J M. Division of Rules and Records. B4/02/13 ANDERSON.S I Garvey. Schubert, Adams & Berer. 7pp 22583 226. 24X Fichs. 50-000. 84/02/13. 8403080179
- --8009090737 Forwards airworthiness alert ra corrosive & abrasive characteristics of volcanic ash which has failen in Pacific Northwest, Questions re ash amount, chemistry & size distribution will be forwarded to licansees, M/o encl JACKSON, R E. Geosciencas Branch 80/06/12, VOLLMER, R H Division of Engineering, 2pp. 22583, 258, 24X Fiche: 50-000, 84/02/13, 8403080179.
- 8403010112 Grants 831123 & 1230 requests that Nuclear Energy 8vcs. Inc rack design drawings be withheld from public disclosure (ref 10CFR2, 790). MILLER, J. R. Operating Reactors Branch 3, 84/02/21. WiTHERS, B. D. Portland Genaral Electric Co. 3pp 22479-278. 24X Ficha: 50-344, 84/02/21, 8403010112
- 8403060447 Forwards rev to 830314 order, changing completion dates for NUREQ-0737, Items II.F. i i, "Noble Gas Effluent Monitors" & II.F. I.2, "Indine Monitors," from 831231 to startup for fuel Cycle 7.
 MILLER, U R. Operating Reactors Branch 3 84/02/21. WITHERB, B, D, Portland General Electric Co 3pp 22552:023. 24X Fiche: 50-344,84/02/21,8403060447
- --8403060449 Rev to 830314 order extending completion date for Items II.F. 1: 1 & II F.1 2 from 831231 to startup for 1984 refualing outaga.

 EIBENHUT.D.Q Division of Licensing. 84/02/21 Portland General Electric Co. 4pp. 22552:026. 24X Fiche:50-344,84/02/21,8403060447.

- 8403050226 Notifies that issuance of FR notice will be delayed until supplemental info received for B40127 license change application Issuance of amend unnecessary to remove reactor vessel surveillance capsule X HILLER, J R Operating Reactors Brench 3 B4/02/29 WITHERS, B D Fortiand Gensral Electric Co. ip 22527 359 24X Fichs 50-344,84/02/29,8403050226
- 8403060382 Notifiss that monthly milk semple could not be obtained during Feb 1984, because dairy animals (goats) at Location 17A not producing milk Monthly milk sample sxpscted to be attainable for Mar 1984 HITHERS, B D Portland General Electric Co 84/03/02 MILLER, J R Operating Reactors Branch 3 1p 22518 189 24X Fiche 50-344,84/03/02.8403060382
- 84030B0347 Partial response to FDIA request for documents rs proposed NBHC determinations for Milistons 2 & entry into operational mode for conducting final tests of pressurizer sefety valves at Trojan Forwards App B documents.
 FELTON, J M Division of Rules and Records 84/03/02 ADATO, M Union of Concerned Scientists 4pp 22583 039 24x F1che 50-000,84/03/02,8403080347.
- --B307180403 Initial NSHC determination & noticing action re util 830524 application to amend License NPF-1.clarifying purpose of auxiliary hoist & tasting of hoist & manipulator crans TRAMMELL.C NRC No Detailed Affiliation 01vsn 83/06/27 2pp 22583 043 24X Fiche 50-000.84/03/02.8403080347
- ---8307180414 Requests FR publication of notics of consideration of issuance of amend to License NPF-1 & proposed NSHC determination & opportunity for hearing is 830324 request to heat up to hot standby mode CLARK.R A Operating Resectors Branch 3 83/07/06 KREUTZER,P M Operating Reactors Branch 3 pp 22583 045 24% Fiche 30-000,84/03/02.8403080347
- 8403260071 Forwards seismology questions as MPPS-3 sits, accepted NRC research proposal on subduction zone undertaken by US93 & current safety evaluation of Trojan Miller, J. R. Operating Reactors Branch 3. 84/03/05 WITHERS, B. D. Portland General Electric Co. 2pp. 22759 300 24X Fiche 50-000,84/03/05.8403260071
- --8403260077 Forwards request for add1 info re WPP8-3 site ssismology, based on review of FBAR
 JACKBON, R E Geosciences Branch 83/04/28 KNIGHTON, O W Licensing Branch 3 9pp 22759 302 Z4X Fichs 50-000, 84/09/05, 8403260071
- --8403240083 Forwards draft SER input rs WPP8-3 site geology & seismology Open items includs possibility of large earthquake on subduction gons beneath site & possibility of unrecognized low angle thrust Faults in sits vicinity KNIGHT, J P Assistant Director for Comp. & Structures Engineering (Post 830201) 83/11/01 NOVAK.T H Assistant Director for Licensing. 18pp 22759 311 24X Fiche 50-000,84/03/05,8403260071
- ---B4032600BB "Northwest US Subduction Zone Seismic Risk Assessment," proposel to USGS rasearch program for NRC.
 HEATON,T H California Institute of Tachnology, Passdene, CA
 B4/03/26 20pp 22789 329 24X Fiche 50-000, B4/03/05, B403260071
- B403190325 Informs that requestsd info re core exit thermocouples & subcooling margin monitors psr NUREQ-0737 & Generic Ltr B2-28 will be provided by 841231 WITHERB. B D Portland Operal Electric Co 84/03/12 EISENHUT, D G Division of Licensing. ip 22673 237 24X Fiche 50-344,84/03/12,8403190325
- 8403300168 Responds to 840105 Generic Ltr 84-01 rs NRC use of terms important to safety & safety-related Recommends that NRC refrain from any rule changes or other regulatory process Present rules & definitions edequate WITHERS, B. D. Portland General Electric Co. 84/03/27 EISENHUT, D C Division of Licensing 2pp 22821 099 R4X Fiche 50-344,84/03/27,8403300168
- Q Inspection reports, IE Bulletins & correspondence
- 8403060341 Forwards IE Insp Rapt 50-344/83-34 on 831128-1230 No noncompliance identified BIBHOP, T.W. Region 5. Office of Director. 83/02/07. WITHERS, B D Portland General Electric Co. 2pp. 22519 073. 24X Fiche: 50-344.84/02/07.8403060341

- --8403050344 IE lnsp Rept 50-344/83-34 on 831128-1230 No noncompliance or deviations identified Major areas inspected plant operations, security, maint, surveillance testing, cold weather preparation & plant review board
 JDHNSTON, 0 W. RICHARDS, 8 A. DODDS, R. T. Region 5, Defice of Director 64/02/03 4pp 22519 075 24X Fiche: 50-344, 84/02/07, 8403040341.
- 8403080408 FOIA request for repts of inspirarried out under Condition 2 of Nuclear Energy Liability policies for facilities CALSOYAS.C D. Affiliation Not Assigned 84702/07 Region 5, Office of Director, 4pp 22547 341. R4X Fiche 50-000.84/02/07. 8403080408
- 8403080419 Responds to FOIA request for repts of insp carried out under Condition 2 to Nuclear Energy Liability policies for facilities.NRC does not have repts FELTON.J M Division of Rules and Records 84/02/22 CALSOYAS,C D Affiliation Not Assigned 1p 22567 345 24X Fiche 50-000,84/02/22,8403080419
- 8403060436 Provides suppl to NRC 831219 ltr granting relief from certain inservice insp requirements of Section XI of ASME Boiler & Pressure Vessel Code Details of reactor vessel cladding inadvertently omitted from 831219 ltr MILLER.J R Operating Reactors Branch 3 84/02/24 WITHERS.B.D Portland General Electric Co 2pp 22550 001 24X Fiche 50-344.84/02/24,8403060456
- 8401190072 1E Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Svo list encl.
 JDRDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/28. Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 30-000.84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl. GRACE.J M. Division of GA, Safeguarés & Inspection Programs (Post 830103). 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552:327 24X Fichs 50-000.84/03/02,8402090007
- B402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operete " Svc list encl. JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc 122pp 22533.098 24X Fiche 50-000,84/03/02,8402090008
- 8402090007 lE Info Notice 84-i3. "Reporting of Radiological Releases "
 Svc list encl
 JCRDANLE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553:217 24X Fiche 50-000:84/03/02.8402090009
- 8402070011 IE Info Notice 84-i7, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidate Edison Co of New York, Inc 117pp. 22553:336 24X Fiche: 50-000,84/03/05,8402090011
- 8402070024 IE Info Notice 84-09.Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl.

 JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635-049 24X Fichs. 50-000,84/03/07,8402090024.
- 8402070028 IE 1nfo Notice 84-18, "Stress Corrosion Crecking in PWR Bys " 8vc list enci. JRRDAN,E L Division of Emergency Preparedness & Engineering Risponse (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584.186 24X Fiche: 50-000,84/03/07,8402070028
- B403200141 Discusses evaluation of BALP for Bapt 1982 Aug 1983, forwarded by NRC 831130 ltr WITHERS:8 D. Portland General Electric Co. 84/03/07 MARTIN.J. B Region 5. Office of Director 1p. 22698-361 24X Fiche:50-344,84/03/07,8403200141
- 8402090031 IE Bulletin 84-02, "Failures of QE Tupe HFA Relays in Use in Class IE Sefety Sys " Svc list encl, DEYOUND, R C. Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823-094 24X Fiche: 50-000.84/03/12,8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Enteries into PWR Resector Cavities " Syc list encl JURDAN E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21, Consolidated Edison Co. of New York, Inc 123pp. 22823 227 24x Fiche 50-000,84/03/21,8402090043

- B402090044 IE Info Notice B4-20. "Svc Life of Releys in Bafety-Related Bys " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402099044
- R Periodic operating reports & related correspondence
- 8403020030 Monthly operating rept for Jan 1984, H/840203 ltr NICHOLBON, H G , YUNDT, C P Fortland General Electric Co 84/01/31 5pp 22442 001 24% Fiche 50-344,84/01/31,8403020050
- 8403300106 Monthly operating rept for Feb 1984 W/840316 ltr PETERSON,L 8, YUNDY,C P Portland General Electric Co 84/02/29 Spp 22821 218 24X Fichs 50-344,84/02/29,8403300106
- B Reportable occurrences. LERs & related correspondence
- 8305270051 Forwards technical review rept. "Blocking of Automatic Bafety Injection (SI) Signals " LERs should be included in forthcoming power reactor events issue to alert other Westinghouse PRR operators CHIRAMALIM Reactor Operations Analysis Branch 83/04/23, SEYRBIT.K V Reactor Operations Analysis Branch 1p 22789.292, 24X Fiche 50-000/83/04/25,8305270051
- --8305270036 "Blocking of Automatic Safety Injection (SI) Bignel," technical review rept
 * Director's Office 83/04/25, 4pp. 22789:293 24X
 Fiche 50-000:83/04/25,8305270051,
- 8403230178 Forwards Technical Review Rept AEOD/T313, "Capped Containment Pressure Sensing Lines." & proposed IE info notice Issue edequately resolved RUBIN:8 D Reector Operations Analysis Branch 83/05/11 BEYFRIT.K V Reactor Operations Analysis Branch 19 22759.286. 24X Fiche 50-000,83/05/11,8403230178.
- --8403230181 "Capped Containment Pressure Bensing Lines," technical review rept Condition caused by procedural inadequacy. RUBIN, 6 D. Director's Office. 83/05/11 6pp 22739 287 24X Fichs 50-000,83/05/11.8403220178
- 8403010117 Partiel response to FOIA request for documents by named individuals re repts. anelyses, studies, procedures & sys for measurement of RCS leekage App B documents placed in FDR App A documents elready available in PDR. Search continuing. FELYON. J M Division of Rules and Records 84/01/25 MADDEN, T J Kaye, Scholer, Fierman, Heys & Handler 7pp 22480 026. 24% Fiche 50-000.84/01/25.8403010117.
- 8403010355 LER 84-002-00 on 840127, train B safety injection pump oil cooler inspected & found packed w/sediment Caused by throttled valve in cooler discharge line Svc water side of cooler flushed W/840227 ltr
 BAIR. 0 : YUNDT, C P Portland General Electric Co 84/02/27 4pp 22433.005 24% Fiche 50-344,84/02/27,8403010355
- 8403260216 LER 84-003-00 on 840218 during periodic surveillance test, containment atmosphere sampling valve 8V-5643 failed to open Operator removed wrong fuse causing short circuit & reactor trip Wiring will be relocated H/H940316 ltr BAIR.O., YUNDT.C P Portland General Electric Co 84/03/16 4pp 22756.157. 24X Fiche 50-344,84/03/16.8403260216.
- DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

 F. Becurity, medical, emergency & fire protection plans
- 8403150243 Forwards order confirming commitments to implyment post-THI-related items set forth in Suppl 1 to NUREO-0737, "Requirements for Emergency Response Capability," based on util 821217 response to Generic Ltr 82-33.

 STOLZ, J.F. Operating Reactors Branch 4, 84/02/21 CROWSE, R P Toledo Edison Co 1p 22649,001. 24X Fiche 50-346,84/02/21,8403150243
- --8403150246 Forwards order confirming licensee commitments re emergency response capability for transmittel to Ofc of FR for publication.

 * Operating Reactors Branch 4. 84/02/21. Docketing & Services Branch. 2pp 22649.002 24% Ficha. 30-346.84/02/21, 8403150243.
- --8403150250 Order confirming licensee commitments on emergency response capability, per requirements set forth in Suppl 1 to NUREO-0737. "Requirements for Emergency Response Capability " EISENHUT, D 0 Division of Licensing 84/02/21. Toleda Edison Co 6pp 22649:003 24X Fithe 50-346,84/02/21. B403150243

- 8403130276 Rev 11 to Administrative Procedure AD 1827 12, "Protective Action Quidelines." W/840305 ltr MURRAY.T.D. Toledo Edison Co 84/02/24 25pp 22614.150 24X Fichs 50-346.84/02/24.8403130276
- 8403260394 Notification of 840321 meeting w/util in Bethesde.MD to review status for resolution of fire protection deficiencies

 DE AGAZIO, A Operating Reactors Branch 4 84/02/28 STOLZ, J F Operating Reactors Branch 4 2pp. 22775 252 24X

 Fiche 50-346,84/02/28,8403260396
- 8403050107 Forwards "Abnormal Transiant Operating Guidelines,Part I Procedural Guidelines," "Part II-Vol 1 Fundamentals of Reactor Control "& "Part II-Vol 2," per 830415 schedule for completing Suppl 1 to NUREO-0737 requirements CROUSE,R.P. Toledo Edison Co. 84/03/01 E18ENHUT,D @ Division of Licensing 35pp 22523 221 24X Fiche 50-346,84/03/01,8403050107
- ---8403050110 Procedure 74-1125531-00, "Abnormal Transient Operating Ouidelines.Part I Procedural Quidelines "
 + Babcock & Wilcox Co. 82/10/12 86pp 22523-256 24X
 Fiche 50-346,84/03/01,8403050107
- --B403050114 Procedure 74-1125531-00, "Abnormal Transient Operating Quidelines.Part Il-Vol i Fundemental of Reactor Control for Abnormal Transients " * Babcock & Wilcox Co. B2/07/06 245pp 22523'342. 24X Fiche'50-346,84/03/01,8403050107.
- --8403050118 Procedure 74-1125331-00, "Abnormal Transient Operating Quidelines, Part II-Vol 2 Discussion of Selected Transients "

 * Bebcock & Wilcox Co. 82/07/06 230pp 22524 227 24x
 Fichs. 30-346, 84/03/01, 8403050107
- 8403120100 Extends invitation to attend 840323 regional workshop in Rosemont, IL re 10CFR50, App R safe shutdown requirements Workshop will cover subje described in IE Info Notice 84-09 & provide addl guidance in safe shutdown enalyses BFEBBARD, R L Division of Engineering 84/03/06 CROUSE, R, P Toledo Edison Co. Spp 22588 166 24X Fiche. 50-346, 84/03/06, 8403120100.
- 8403190311 Revs to emergency plan supporting procedures, consisting of Rev 204 to "Emergency Plan Supporting Procedures Rev Index" & Rev 13 to Administrative Memorandum 38-13, "First Aid Response," W/840309 transmittal & receipt form # Toledo Edison Co. 84/03/09, 4pp 22673 179 24X Fiche: 50-346, 84/03/09, 8403190311
- B403260019 Forwards IE Bafeguards Insp Rept 50-346/B4-03 on 840221-24 & notice of violation Notice of violation & insp rept details withheld (ref 10CFR73 21) AXELSON, N. L. Region 3, Office of Director, B4/03/16 CROUBE, R P Toledo Edison Co. 2pp. 22747.352 24X Fiche 50-346, 84/03/16, B403240019.
- ---8403260023 IE Safeguards Insp Rept 50-346/84-03 on 840221-24.

 Noncompliance noted intrusion alarms did not mest sacurity
 plan criteria in vital & protected areas Details withheld
 (ref iOCFR73 21).
 PIRTLE, L., GREED, J. R. Region 3, Office of Director 84/03/15
 2pp. 22747:354 24X Fichs, 50-346/84/03/16/8403260019.
- B403230009 Ack receipt of 840221 order confirming commitments to implement post-THI-related items in Suppl i to NUREO-0737 re emergency response capability status for completing each basis requirement submitted CROUSE, R.P. Toledo Edison Cp. 84/03/20 EIBENHUT, D. G Division of Licensing 4pp 22730:133 24X Fiche. 50-346, 84/03/20, 8402230009
- 8403270167 Temporary Change T-7803 to Emergency Plan Implementing Procedure EI 1300.0B, "Radiological Testing Lab Equipment List." Rev 37 to revised index & 840320 transmittal litrencl DURDEL, R.R., MURRAY, T.D. Toledo Edison Co. 84/03/20 7pp 22803:348, 24X Fiche, 50-346, 84/03/20, 8403290167
- J Insurance & indemnity information
- 8403260197 Forwards Endorsement 48 to NELIA Policy NF-236, Endorsements 69 & 72 to NELIA Policy NF-208, Endorsement 59 to MAGLU Palicy MF-77 & Endorsement 67 to NELIA Policy NF-230, QULDEN, M P Marsh & McLennen, Inc. 84/03/12, 8ALTZMAN, J, Assistant Director for State & Licenese Relations 6pp. 22751'033, 24X Ficha. 50-000, 84/03/12, 8403260197

8403300178 Submits list of insurers policy numbers & coverage limits, in response to 10CFRSO 54(w)(4) re reporting of property insurance coverage for facility CROUSE.R P Toledo Edison Co 84/03/26 STOLZ.J F Operating Reectors Branch 4 ip 22819-362 24X Fiche 50-346,84/03/26,8403300178

M Antitrust correspondence

- 8403050194 Responds to Antitrust Div request for NRC imposition of civil penelties re alleged willful failure to comply fully w/Antitrust License Condition 3 Commission believes imposition of civil penelties inappropriate PALLADINO.N J Commissioners 84/01/31 CUTLER, M S , MCGRATH, J P Justice, Dept of, Attornsy General, Office of 2pp 22528.187 24X Fiche 50-000.84/01/31,8403050194
- P Operating license stage documents & correspondence
- B403010117 Pertiel response to FQIA request for documents by nemed individuals re repts, analyses, studies, procedures & sys for measurement of RCS leakage App B documents placed in FDR App A documents elready aveilable in FDR Seerch tontinuing FELTON, J M Division of Rules and Records 84/01/25 MADDEN, T J Kaye. Scholer, Fierman, Reys & Handler 7pp 22480 026 24% Fichs 50-000,84/01/25,8403010117
- --B3111504B1 Forwards results of review of RCS leak rate test procedures & calculational methods used in 1978 at two randomly selected BWR plents, per 830920 request Deficiencies discovered during trial use period corrected DEYOUNG.R C. Director's Office, Office of Inspection and Enforcement B3/11/07 DIRCKB-W J. Dffice of the Executive Director for Operations 22pp 22482 020 24x Fiche 50-000,84/01/25,8403010117
- 8403050053 Summary of 840203 meeting w/util at site re review of NUREO-0737 items Agenda. attendance list & handouts encl VISBING. 0 8 Operating Reactors Branch 4 84/02/23 Operating Reactors Branch 4. 24pp 22527 332 24X Fiche: 50-344, 84/02/23, 8403050053
- 8403150263 Forwards mod of order confirming licenses commitments on post-TMI-related issues Proposed implementation schedule for Items II.F 1 i & II F i 2 acceptable STOLZ.J.F Operating Reactors Branch 4 84/02/27 CROUSE.R P Toledo Edison Co 2pp 22649 340 24X Fichs 50-346.84/02/27, 2003180263
- --B403180298 Mod of order confirming licensee commitments on post-TM1-related issues Order revised to extend completion dete for Items II F. i & II F i 2 from B31231 to 84031, EIBENHUT.D Q. Division of Licensine 84/02/27 roledo Edison Co 7pp. 22649:342 24X fiche 50-346:84/02/27,8403150263
- 8403130133 Forwards application for amend to License NPF-3, changing Tech Bpec Tables 3 3-10 & 4.3-10 to delete containment recirculating sys from post-accident monitoring requirement CROUSE, R. P. Toledo Edison Co 84/02/28 8TOLZ, J. F. Operating Reactors Branch 4. 1p 22608 164 24X Fiche 50-346,84/02/28.8403130133
- --B403130143 Application for amend to License NPF-3, changing Tech Spec Tables 3 3-10 & 4 3-10 to delete containment recirculating sys from pott-accident monitoring requirement * Toledo Edison Co 84/02/28 4pp 22608.165, 24X Fiche 50-344,84/02/28,8403130133
- 8403130429 Responds to 830706 ltr re instrumentation to detect inadequate core coding. Detailed analysis of measurement errors for coolant inventory in hot legs & reector vessel provided CRDUSE, R.P. Toledo Edison Co. 84/03/09 STOLZ, J.F. Operating Reactors Branch 4 App. 22613 127 24X Fiche 50-346, 84/03/09, 8403130429
- 8403130085 Forwards "B&W 177 Fuel Assembly Owners Group Bafe End Task Force Rapt on Generic Investigation of HPI/MU Nozzle Cracking," summarizing util involvement in cracking program CROUSE/R.P. Toledo Edison Co 84/03/09 8TCL2, J.F. Operating Reactors Branch 4 2pp. 22639 055 24X Fiche 50-346,84/03/09,8403150085

- 8403200046 Application to amend License NPF-3, revising Tech Specs re radiological plant effluents, offsite dose calculation manual & process control manual CROUSE, R P Toledo Edison Co 84/03/15 STOLZ, J F. Operating Reactors Branch 4 3pp 22684 078 24x Fiche 50-346, 84/03/15, 8403200046
- --8403200052 Proposed Tech Specs re radiological plant effluents, offsite dose calculation manual & process control manual # Toledo Edison Co 84/03/15 66pp 22684 083 24% Fiche 50-346,84/03/15,8403200046
- --8403200058 "Solid Radwaste Process Control Program Davis-Bessa Nucleer Power Station " * Toledo Edison Co 84/03/31 5pp 22684 150 24X Fichs 50-346,84/03/15,8403200046
- --8403200063 "Offsite Dose Calculation Manual for Davis-Besse Nuclear Power Station"

 ** Toledo Edison Co 64/03/31 186pp 22684 155 24%
 Fichs 50-346,84/03/15.8403200046
- B403300149 Forwards application for amend to License NFF-3.revising Tech Spers to reflect changes in post-eccident sempling sys & post-accident instrumentation for In-core thermocouple.per NUREO-0737 & Generic Ltr 83-37 CROUSE.R P Toledo Edison Co 84/03/22 STOLZ.J F Operating Reactors Branch 4 3pp 22821 002 24X Floha 50-346.84/03/22, 8403300149
- --8403300156 Application for amend to License NPF-3, revising Tach Specs to reffect changes in post-accident sampling sys & post-accident instrument etion for in-core thermocouple & reactor coolant hot leg level
 CRUMSE.R P Tolefo Edison Co 84/03/22 7pp 22821 004. 24X
 Fichs 50-346,64/03/22,8403300147
- --8403300158 Proposed Tech Specs.consisting of changes to Section 6 8 4 & Tables 4 3-10 & 3 3-10 re post-accident monitoring instrumentation surveillance requirements # Toledo Edison Co. 84/03/22 3pp 22821 011 24X Fiche 50-346,84/03/22,8403300149
- B403300163 Submits add1 info in support of 831202 request for exemption from requirements of IOCFR50 54(m)(iii) re licensed operator staffing.per 840313 telcon w/NRC Responsibilities of senior reactor operator chenged CROUSE.R P Toledo Edison Co 84/03/23 BTDLZ.J F Operating Reactors Branch 4 ip 22821 091 24X Fiche 50-345.84/03/23.
- O Inspection reports. IE Bulletins & correspondence
- 8403050223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCS leakage Forwards App C documents Search continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN.T J Keye, Scholer, Fierman, Haus & Handler 3pp 22496 234 24X Fiche 50-000,84/02/07,8403050223
- --B403050256 Notlifies that independent measurements of identifies & unidentified RCS leek rates for all PWRs in Region III performed per Procedures 617278 & 61728B Insp findings summarized NORELIUS.C E Division of Englneering 82/03/08 JDRDAN,E L Division of Engineering & Quality Assurance (Pre B30103) 2pp 22476 270 24X Fiche 50-000.84/02/07.8403050223
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Svc llst encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 6403050067 Forwards addendum to 1E Insp Rept 50-346/83-02.including confirmatory measurements program data involving comparison of gross bete analyses on spitef liquid sample Info closes Open Item 50-346/83-02-01

 PAPERIELLO, C. J., Ragion 3, Office of Director 84/02/29 CROUSE, R.P. Toledo Edison Co. ip. 22470, 180 24X Fichs 50-346,84/02/29,8403050067
- ~-8403050069 Afdendum to 1E Insp Rept 50-346/83-02 ra confirmatory measurements progrem deta involving comparison of gross bata analysis on spiked liquid sample * Repion 3, Office of Director 84/02/29 ip 22490 i81 24X Fichs 50-346,84/02/29,8403050067

- B402090007 IE Info Notice 84-14, "Highlights of Recent Trensport Regulatory Revs by DOT & NRC " Evc list encl ORACE.J N Division of GA: Safeguards & Inspection Programs (Post B30103) B4703/02 Consolidated Edison Co of New York, Inc. 130pp 22552 329 24X Fiche 50-000.84/03/02,8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- B402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"

 Bvc list encl

 JORDAN, EL Division of Emergency Preparedness & Enginearing
 Response (Post 830103), 84/03/02 Consolidated Edison Co. of New
 York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notica 84-17, "Problems W/Liquid Nitrogen Cooling Components Balow Nil Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notica 84-09.Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Bys " Syc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Responsa (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Byc list enci JORDAN,E L Division of Emergency Preparedness & Englneering Response (Post 830103) 84/03/07 Consolideted Edison Co of New York, Inc 118pp 22584 866 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Builetin 84-02. "Fallures of GE Type HFA Relays in Use in Class IE Safety Sys." Evc list encl
 DEYOUNG.R C Director's Office. Office of Inspection and
 Enforcement #4/03/12 Consolidated Edison Co. of New York, Inc.
 134pp 228R3 094 24X Ficha 50-000.84/03/12.8402090031.
- 8403200008 Forwards response to IE Bulietln 83-07 re epparently fraudulent products sold by Ray Miller, Inc 81x Reco Industries, Inc flanges installed in nonsafety-related boric acid storaga tanks CROUSE, R P Toledo Edison Co. 84/03/12 KEPPLER, J Q Ragion G. 0ffice of Director 4pp 22685 203 24X Fiche. 50-346, 84/03/12, 8403200008
- 8403240019 Forwards IE Safeguards Insp Rept 30-346/84-03 on 840221-24 & notice of violation Notice of violation & insp rept details withheld (ref 10CFR73 21)
 AXELEDN.W.L. Region 3, Office of Director 84/03/16 CROUSE,R P Tolado Edison Co 2pp. 22747,352 24X Fiche: 50-346,84/03/16,840326019.
- --8403260023 IE Bafeguards Insp Rept 50~346/84~03 on 840221~24
 Noncompliance noted intrusion alarms did not meet sacurity
 plan criteria in vitel & protected #reas Details withheld
 (ref 10CFR73 21)
 PIRTLE.0 L., CREED, J. R. Region 3, Office of Director 84/03/15,
 2pp 22747 234 24% Fiche 50~346/84/03/16,8403260019
- 8402070043 IE Info Notice 84-17, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co. of New York, Inc 123pp 22823,229 24X Fiche 50-000,84/03/21,8402070043
- 8402090044 IE Info Notice 84-20, "Bvc Life of Relays in Safety-Related Bys." Svc list ancl JURDAN,E L. Division of Emergency Praparedness & Engineering Response (Post 830103) 84/03/21. Consolidated Edison Co. of New York, Inc. 135pp 22933 001. 24X Fiche:50-000,84/03/21,8402090044.
- R Pariodic operating reports & ralated correspondence
- 8403090251 Rev 1 to monthly operating rept for Bept 1983 4/840222 ltr. BARSQUR, B. HURRAY, T.D. Toledo Edison Co. 83/09/30, HALLER, N. Office of Resource Management, Director 2pp. 22572.202, 24X Fiche 50-346,83/09/30,8403090251
- 8403020078 Monthly operating right for Jan 1984.W/840207 ltr.

 9ARSDUR, B., MURRAY, T D. Toledo Edison Co 84/01/31 HALLER, N.
 Division of Data Automation & Management Information, 6pp.
 22441 325 24X Fiche 50-346,84/01/31,8403020078

- 8403190109 "NPDES Discharge Monitoring Rept for Feb 1984 " W/840313 ltr MURRAY.T D Toledo Edison Co B4/02/29 10pp 22666 253 24X Fiche 50-346,84/02/29,8403190109
- 8403190213 Wastewater rept for Feb 1984 W/840313 1tr MURRAY, T D. Toledo Edison Co 84/02/29 9pp 22671 111 24X Fiche: 50-346, 84/02/29, 8403190213
- 8403300184 Monthly operating rept for Feb 1984 W/840309 ltr BARSOUR.B.: MURRAY.T D Toledo Edison Co 84/02/29 HALLER, N Uffice of Resource Management, Director 6pp 22820 338 24X Fiche 50-346.84/02/29.8403300184
- B Reportable occurrences, LERs & related correspondence
- 8403210095 Part 21 rapt re nonconformance of metal hose assemblies for ABME, Baction III, Class 2 & 3 svc. Status of nonconforming items shipped encl A11 customers notified LALIKOB, J. M. Titefiex Corp. 83/12/16 Director's Office, Office of Inspection and Enforcement 4pp 22704.324, 24X Fichs 50-000,83/12/16,8403210095
- B401160250 Rsvised LER 83-040/03X-1 on 830725, auxiliary feed pump i-1 failed to respond to speed change signals from automatic & manual control caused by design deficiency in clutch mechanism New design slip clutch installed W/831227 ltr THOMPBON, T., HURRAY, T D Toledo Edison Co B3/12/27. KEPPLER, J G. Region 3, Office of Director 4pp 21814 197 24X Fiche 50-346,83/12/29,8401160250
- 8403210032 Part 2: rept re failure of auxiliary feedwater pump drive turbines, Gimpel NPS-4 T&T valve to close Enci ltr dtd 840203 sent to listed utils QE notified of affected units in BWR plants.

 THEROUX.R R Terry Corp 84/02/22 WOODRUFF, R W Director's Office, Office of Inspection and Enforcement 6pp 22706 327 24X Fiche'50-000, 84/02/22; 8403210032.
- 8403070256 Followup Part 21 rept re defective mechanical snubber capstan springs supplied by Pacific Boientific Affected utils listed Purchasers have been notified & advised to work directly w/Pacific Scientific in disposition HOVI.L. NPS Industries, Inc 84/02/24 DEYOUNO, R C Director's Defice. Office of Inspection and Enforcement 2pp 22536 279 24X Fiche: 50-000, 84/02/24, 8403070256
- 8403130275 PNO-III-84-021: on 840302, MSIV closure tripped reactor Cause unknown. Befety valve stuck open following pressure reduction Incident response ctr in standby mode, JACKIM, I., 80YD, D. Region 3, 0Pfice of Director 84/03/02 ip. 22607. i39, 24X Fiche: 50-346,84/03/02,8403130275
- 8403130380 Confirmatory action ltr re 840302 unusual event following reactor trip Prior to restart transient will be reviewed & effect of transient on Steam Generator 2 will be assessed Cause of MSIV closure will be determined KEPPLER.J G. Region 3. Office of Director 84/03/03 CROUSE.R P Toledo Edison Co. 2pp. 22616.281. 24X Fiche. 50-346.84/03/03. R803130380
- 8403130336 PNO-III-84-021A, pn 840303, MBIV replaced & steam generator 2 refilled following 840302 reactor trip. Generator isolated during refilling to protect against release of radioactivity in event of steam generator tube failure JACKIM, I , BDYD, D. Region 3, Office of Director, 84/03/05. 2pp 22607-243 24X Fiche: 50-346, 84/03/05, 8403130336
- B403170341 Ack receipt of B40306 ltr informing NRC of steps taken to address items contained in B40303 confirmatory action ltr KEPPLER.J.O. Region 3. Dffice of Director. B4/03/14. CROUSE.R P Toledo Edison Co. 1p. 22675.033. 24X Fiche: 50-346.84/03/14.
- --8403190349 Responds to NRC 840303 confirmatory action itr re 840302 plant trip due to failure of main steam safety vaive to fully close, CROUSE: R P. Toledo Edison Co. 84/03/06, KEPPLER, J. O. Region 3. Office of Director 10pp, 22675: 034 24X Fiche: 50-346.84/03/14.8403190341.
- DOCKET 50-348 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8403140212 Public version of Rev 28 to Emergency Pian Implementing Procedure FNP-0-EIP-008, "Bvc Bldg Telephone Directory " W/B30706 1tr & JH Felton 840312 release memo. HUBBFCH,J,B. Alabama Power Co. 83/07/01 77pp. 22638 157. 24X Fiche: 50-348, 83/07/01, 8403140212.

- 8403140210 Public version of Rev 4 to Emergency Plan Implementing Procedure 9D-EIP-111, "Corporate Activation & Notification Procedures " W/831025 ltr & JM Felton 840312 release memo CLAYTON;F L , MCQUMAN, J W Alabama Power Co 83/10/25 82pp 22638 237 24% Fichs 50-348/83/10/25.8403140210
- 8403090303 Public version of duty roster for First Querter 1984, reflecting nuclear generation dept on cell emergency positions & public info site coordination position W/ UM Feiton release memo GIBSON, M O Alabama Power Co 83/12/22 4pp 22584 342 24X Fiche 50-348, 83/12/22, 8403090303
- 8403280198 Public version of 1984 emergency on-cell coverage schedules, as part of Emergency Plan Implementing Procedure GO-EIP-111 W/840106 ltr & JM Felton release memo ROBERTS R O Alebame Power Co 83/12/29 15pp 22808 228 24X Fiche 50-348,83/12/29,8403280198
- 8403280109 Public version of temporary change notices for emergency plan implementing procedures, including Procedure GD-EIP-101 re nuclear generation dept componete emergency operation. H/ 840126 ltr & JM Felton 840322 release memo OIBSON. M D . MUDD, C H Alabama Power Co 84/01/26 20pp 22812 001 24X Fichs 50-348.84/01/26.8403280109
- 8402130400 Forwards IE Safeguerds Insp Repts 50-348/84-02 & 50-364/84-02 on 840116-20 No violations noted VERRELLI.D M Division of Project & Resident Progrems 84/02/08, MCDONALD.R F Alabama Power Co 2pp 22203,251 24X Fichs 50-348,84/02/08,8402130400
- --8402130404 IE Sefsguards Insp Repts 50-348/84-02 & 50-364/84-02 on 840116-20. No violetions noted Major areas inspected security organization, testing & maint & physical berriers Details withheld (ref 10CFR2 790 & 73 21) MODRE, D E Region 2, Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 84/02/02 ip 22203 253 24X Ficha 50-348.84/02/08,8402130400
- 8403160142 Forwards IE Insp Repts 30-348/84-01 & 30-364/84-01 on 840118-19 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/02/15 MCDUNALD.R P Alabama Power Co 2pp 22655 325 24X Fiche 50-348,84/02/15,8403160142
- --8403160146 IE Insp Repts 50-348/84-01 & 50-364/84-01 on 840118-19 No violations or deviations noted Major areas inspected amergancy preparedness area of protective action decisionmaking CLINE.W Region 2. Office of Director. JENKING.O.R Emergancy Preparedness & Materials Safety 84/02/15 22655 327 24% Fichs: 50-348.84/02/15,8403160142.
- 8403290019 Forwards IE Insp Repts 50-348/84-04 & 50-364/84-04 on 840131-0202 No violations or deviations noted VERRELLI,D M Division of Project & Resident Programs 84/02/29. MCDDNALD,R P Alabame Power Co 2pp 22806.209. 24X Fiche 50-348,84/02/29,8403290019
- --8403270027 IE Insp Repts 50-348/84-04 & 50-364/84-04 on 840131-0202, No violations or deviations noted Mejor areas inspected emergency exercise.

 DECKER, T R. Region 2. Office of Director JENKINS, O R Division of Emergency Preparedness & Meterials 8afety. 84/02/27 7pp 22806 211 24% Fiche: 50-348.84/02/29.8403270019
- 8403080077 Forwards add1 fees for applications for fire protection reviews & approvals.

 CLAYTON.F.L. Alabama Power Co. 84/03/01. MILLER.W.O. License Fee Management Branch. ip. 22557.237. 24X Ficha 50-348.84/03/01. 8403380077
- 8403160354 Notifies of fire protection workshop on 840316 in Region II ofc to discuss questions re App R requirements & results of recent App R inses.

 LEMIS.R C. Division of Project & Resident Programs 84/03/02 MCDONALD.R P Alabama Fower Co ip 22660.172 24X

 Fiche: 50-348,84/03/02,8403160354.
- 8403280329 Forwards comments on detailed control room design review program plant per 831031 submittal Plan does not comply fully w/Buppl 1 to NUREO-0737 requirements. Recommends meeting in Mar or Apr 1784.

 VARQALB A Operating Reactors Branch 1 84/03/09, CLAYTON,F L Alabama Power Co 17pp. 22807 288 24X Ficher 50-348,84/03/09, 8403280329

- 8403290078 Ack receipt of 840308 itr informing NRC of steps taken to correct violations noted in iE Insp Repts 50-348/84-03 & 50-364/84-03 WERELLI, D H Division of Project & Resident Programs 84/03/i4 MCDUNALD, R P Alabama Power Co ip 22806 31i 24X Fiche 50-348,84/03/14.8403290078
- --B403270103 IE Insp Repts 50-348/84-03 & 50-364/84-03 on 840111-0205 Visitation found failure to implement procedures for control of maint activities BRADFORD, W H. RULAND, W H. Region 2. Office of Director CANTRELL, F. 8. Division of Project & Resident Programs. 84/02/15 Bpp 22806 317 24% Fich. 50-348.84/03/14.8403290078

J Insurance & indemnity information

- 8403040448 Forwards Endorsement 58 to NELIA Policy NF-238 DUCK,JR Harsh & McLennan, inc 84/02/28 SALTZMAN,J Director for State & Licensee Relations 2pp. 22518 220 Fichs 50-348,64/02/28,6403060448 Assistant
- B403140044 Forwards Endorsement 4 to NELIA Certificate N-13 correcting name of insured on Endorsements 2 & 3 BUCK, J.R. Harsh & McLennan. Inc. 84/03/05 BALTZMAN, J. Assistant Director for State & Licensee Relations 2pp 22634 162 24X Fiche 50-348.84/03/05,8403140044
- 8403280053 Forwards Endorsements 49 & 50 to MAELU Policy MF-93 & Endorsements 59 & 60 to NELIA Policy MF-238 DUCK-JR March & McLennan, Inc. 84/03/20 SALTZMAN, J Assistant Director for State & Licensee Relations 5pp 22777 001 24X Fiche 50-348,84/03/20,8403280053
- P Operating license stage documents & correspondence
- 8401120394 Forwards Amends 37 & 27 to Licenses NPF-2 & NPF-8. WILLOOM Forwards Amends 37 & 27 to Licenses NPF-2 & NPF-0, respectively & BER Amends allow operation w/slightly positive moderator temp coefficient at low power levels & increased hot channel factor limit below full power REEVES.E A Operating Reactors Branch 1 B3/12/30 CLAYTON.F. Alabama Power Co 2pp 21776.274 24X Fichs 50-348.83/12/30.8401120594 CLAYTON, F. L.
- --8401120597 Amends 37 & 27 to Licenses NPF-2 & NPF-8, respectively, allowing operation w/slightly positive moderator temp coefficient at low power levels & increased hot channel factor limit below full power VAROA: 8 A Operating Reactors Branch 1 83/12/30 i8pp 21796 276 24X Fiche 50-348.83/12/30.8401120594
- --8401120600 Safety evaluation supporting Amends 37 & 27 to Licenses NPF-2 & NFF-B, respectively ** Office by Nuclear Reactor Regulation, Director 83/12/30 4pp 21776 294 24% Fiche 50-346,83/12/30,8401120594
- 8403010117 Partial response to FOIA request for documents by named individuals re repts.analyses, studies, procedures & sys for measurement of RCB leakage App B documents placed in PDR App A documents elready evailable in PDR Search continuing. FELTON, J. M. Division of Ruise and Records 84/01/25 MADDEN, T Kaye. Bicholer, Filmman, Hays & Handler 7pp. 22480 026 24X Fiche 50-000,84/01/25,8403010117 MADDEN, T J
- --80:1070522 Summarizes results of independent evaluations of primary sys leak rate k some considered extensions Extension of specific evaluations to all PHR facilities recommended Draft procedure re evaluations will be submitted by 800915 JGRDAN.E L Bivision of Reactor Operations Inspections 80/08/21 HOSELEY.N C Division of Reactor Operations Inspections 1ipp 22480 266 24X Fiche 50-000,84/01/25,8403010117
- --8403010129 Table of "Pressurizer Design Data " Related info encl * Alabama Power Co 84/01/25 460p 22480 033 24X Fiche:50-000, 64/01/25, 84/03010117
- --8403010137 Rsy 2 to Surveillance Test Procedure FNP-1-8TP-9 D. "RCS Leakage Test " Related info encl PODLE: D L Alabama Power Co 79/03/25 22pp. 22480.079 24x Fiche: 50-000, 84/01/25, 8403010117
- --8403010141 Rev 2 to Instrument Haint Procedura FNP-1-1MP-202 B. "Voi Control Tank Level LT-112." Related into encl. HCGRACKEN.K.W. Alabama Fower Co. 78/03/07 24pp 22480.101 24k Fiche.50-000.84/01/25.8403010117
- --8403010146 Rev 2 to instrument Maint Procedure FNP-1-iMP-201 22. "Pressurizer Level Control.LC-459F."
 * Alabama Power Co. 78/06/17. 100pp. 22480 125. 24X
 Fiche 50-000,84/01/25,8403010117

- --B403010152 Rev i to Instrument Haint Procedure FNP-1-IMP-202 9, "Vol Control Tank Level LT-115" THOMAS.J Alabama Power Co 78/08/02 22pp 22480 i56 24X Fiche 50~000, 84/01/25, 84/03010117
- --8403010156 Rev 2 to Instrument Maint Procedure FNP-1-IMP-201 28, "Pressurizer Relief Tank Level LT-470" THOMAS! Alabama Power Co 78/08/02 26pp 22480 178 24X Fichs 50-000, 84/01/25.8403010117
- --8403010163 Rev 1 to Instrument Maint Procedure FNP-1-1MP-224 2. "Reactor Cociant Drain Tank Level,LT-1003 " Related info encl enci SHIPMAN.W B Alabama Power Co 80/01/25 62pp 22480 204 24X Fiche 50-000.84/01/25.8403010117
- 8403020156 Responds to util 830113 request for exemption from 10CFR20 re protection factors for respirators Exemption would allow credit for radioiodine protection factor while employing MSA 466220 OMR-1 canister Review continuing VARGA: 8 A Deprating Reactors Branch 1 84/02/17 CLAYTON: F L Alabams Power Co 3pp 22471 150 24X Fiche 50-348:84/02/17,
- 8403010210 Notification of 840228 meeting w/util in Bethesda.MD to review changes to licensing amend schedules for 1984. REEVES,E Operating Reactors Branch 1 84/02/22 VAROA.B A Operating Reactors Branch 1 2pp 22479 197 24X Fiche 50-348.84/02/22:8403010210
- 8403070339 Notification of cancellation of 840228 meeting w/util in Bethesda: HD to discuss proposed changes to licensing amend schedules for 1984 REEVES,E Operating Reactors Branch 1. 84/02/22 VAROA: 8. A Operating Reactors Branch 1 2pp 22364 145 24X Fiche 30-348.84/02/22.8403070359
- 8403020440 Notification of 840308 meeting w/util in Bethesda.MD to discuss proposed changes to licensing amend schedules for 1784. 1984. REEVEB.E Operating Reactors Branch 1 84/02/28 VARGA.S.A Operating Reactors Branch 1 4pp 22471 200 24X Fiche 50-348.84/02/28.8403020440
- 8403070379 Forwards Amend 43 to License NPF-2 & safety evaluation Amend consists of administrative changes to safety-related snubber Table 3 7-4a re addition of steam generator REEVES, E A Operating Reactors Branch 1 B4/02/27 CLAYTON, F Alabama Power Co Spp 22567 043 24X Fiche 50-348, 84/02/27, 8403070377 CLAYTON F. L.
- --8403070382 Amend 43 to License NPF-2, consisting of administrative changes to safety-related snubber. Table 3 7-4a re addition of steam generator hydraulic snubbers VAROA, S A Operating Reactors Branch 4 84/02/29 42pp 22567 046 24x Fiche:50-348,84/02/29,8403070379
- --8403070384 Safety evaluation supporting Amend 43 to License NPF-2

 * Office of Nuclear Reactor Regulation. Director 84/02/29 2pp
 22567 088 24% Fiche 50-348/84/02/29/8403070379
- 8403090255 Forwards "Analysis of Capsule U From Alabama Power Co JM Fariey Unit i Reactor Vessel Radiation Surveillance Program "
 CLAYTON F L Alabama Power Co 84/03/01 VARGAS A Office of Nuclear Reactor Regulation, Director 2pp 22568 201 24X Fiche 50-348.84/03/01.8403090255
- --B403090259 "Analysis of Capsule U From Alabama Power Co uM Farley Unit 1 Reactor Vessel Radiation Burveillance Program " B0005:R 8 , YANICHKO, B E , CHENEY.C A Westinghouse Electric Corp WCAP-10474 84/02/29 90pp 22368 204 24X Fiche 50-348,84/03/01.8403090255
- 840313003i Supplemental application for amend to Licenses NPF-2 & NPF-8, changing Tech Specs 3/4 7.7 & 3/4 7.8 me control room emergency ventilation sys & penetration room filtration sys; respectively & deleting 3/4 9.14 me bypass piping CLAYTON; F. L. Alabama Power Co. 84/03/01 VAROA; B. A. Office of Nuclear Reactor Regulation, Director 8pp 22615 001 24X Fiche 50-348,84/03/01.8403130031.
- --8403130038 Proposed Tech Specs 3/4 7.7 & 3/4 7.8 re control room emergency ventilation sys & penetration room filtration sys, respectively * Alabama Power Co. 84/03/01 14pp. 22615 009. 24X Fiche 50-348,84/03/01.8403130031.

- 8403130455 Application for amend to Licenses NPF-2 & NPF-8, making Tech Bpacs administrative changes NSHC determination requested CLAYTON F L Alabama Power Co 84/03/01 VARGA, 8 A Office of Nuclear Rescater Regulation, Director 2pp 22613 336 24X Fiche 50-348,84/03/01.8403130455
- --8403130463 Proposed Tech Space, providing administrative changes * Alebama Power Co 84/03/01 10pp 22613 338 24X Fiche: 50-348, 84/03/01, 8403130455
- 8403080081 Forwards corrections to Tech Spsc pages for moderator temp coefficient at low power levels submitted 831013 which contained typographical errors CLAYTON.F L Alabama Power Co 84/03/02 VARGA.S A Office of Nuclear Reactor Regulation, Director ip 22559 258 24X Fichs.50-348,84/03/02,8403080081
- --8403080086 Corrected Tech Spec pages for moderator temp coefficient at low power levels # Alebame Power Co 84/03/02 4pp 22559 259 24X Ficha 50-348.84/03/02,8403080081
- B40308014B Forwards response to NRC B40104 request for add1 info re util B31230 application for change to diesel generator/river water Tech Specs CLAYTON.F.L Alebems Power Co 84/03/02 VARGA, 9 A Operating Reactors Branch 1 8pp 22559 283 24x Fiche, 50-348, 84/03/02. B40308014B
- 8403080158 Application for emend to Licenses NPF-2 & NPF-8, revising Tech Specs re meteorological monitoring instrumentation Change includes air temp difference to conform w/STS CLAYTON,F L Alabame Power Co 84/03/02 VARGA,8 A Uffice of Nuclear Reactor Regulation, Director 2pp 22559 145. 24% Fiche 50-348,84/03/02,8403080158
- --8403080175 Proposed changes to Tech Specs re meteorological monitoring instrumentation Change includes eir temp difference to conform w/BTB # Alabama Power Co 84/03/02 5pp 22559 147 24X Fichs 50-348,84/03/02.8403080158
- B403210175 Requests identification of any potential problems in completing NVREO-0737 items by Sept 1984 Response requested within 30 days of itr receipt VAROA-8.A. Operating Reactors Brench i 84/03/02 CLAYTON,F L Alabama Power Co 2pp 22709.176 24X Fiche 50-348,84/03/02,8403210195
- 8403080272 Informs of deley in responding to 840217 request for add1 info re iodins filter respiratory protection exemption request Reprioritization of request to 100FR20, App A, footnote (c) to 4-month interval requested CLAYTON.F L Alabama Power Co 84/03/05 VAKUA, H. A Dffice of Nuclear Resolve regulation, Director ip 22557 294 24X Fiche 50-348,84/03/05,8403080272.
- 8403240326 Forwards corrected Tech Spec pages re reactor trip systems instrumentation setpoints contained in Amends 37 & 27 to Licenses NFF-2 & NFF-8, respectively, issued on 831230 REEVES, E A Operating Reactors Brench i 84/03/08 CLAYTON, F L Alabama Power Co. 2pp 22775, 296, 24X Fiche 50-348, 84/03/08, 8403260326
- --8403260329 Corrected Tech Spec pages to Amends 37 & 27 to Licenses NPF-2 & NPF-8, respectively, rs reactor trip sysingtrumentation setpoints * NRC No Detailed Affiliation Given 84/03/08 4pp 22775, 298. 24X Fiche 50-348, 84/03/08, 84/03260326
- 8403230134 Requests relief from hydrostatic testing of feedwater reducers during current refueling outage Reducers replaced after vitresonic exams found crecks in weld areas. Radiographic & visual exams performed per IE Bulletin 79-13 CLAYTON.F.L. Alabama Power Co. 84/03/19. VAROA.S.A. Office of Nuclear Reactor Regulation. Director 4pp. 22730:207 24X Fiche 50-348.84/03/19.8403230134
- 8403260227 Application to amend Licenses NPF-2 & NPF-B, consisting of corrected Tech Specs incorporating positive moderator temp coefficient at low power levels & increased enthalpy hot channel factor limit below full power.per 831013 submittal CLAYTON.F L Alabama Power Co. 84/03/22 VARGA.S.A Office of Nuclear Reactor Regulation, Director 1p 22756 072 24X Fiche. 50-348,84/03/22,8403260227.
- ---8403260234 Corrected proposed Tach Space, incorporating moderator temp coefficient at low power levels & increased enthalpy hot channel factor limit below full power **

 ** Alabama Power Co. 84/03/22 10pp. 22756.073 24X Fiche.50-348,84/03/22,8403260227

- 8403280037 Application for amend to Licenses NPF-2 & NPF-8, changing Tech Specs 3 6 i 7 & 4 6 i 7 2 re containment venting Valves will be used for safety-related applications of containment pressure & radiological control CLAYTON,F L Alabama Power Co 84/03/23 VARGA,S A NRC No Detailed Affiliation Given 2pp 22777 015 24X Fiche 50-348,84/03/23,8403280037
- --8403280044 Proposed changes to Tech Specs 3 6 i 7 & 4 6 i 7 2 re containment venting * Alabama Power Co 84/03/23 4pp 22777 017 24X Fichs 50-348,84/03/23,8403280037
- 8403300077 Forwards suppl to 840319 hydrostatic testing relief request re replacement of feedwater to steam generator notable reducers Amend includes welding necessary to complete realignment of feedwater Line C CLAYTON, FL Alabama Power Co 84/03/26 VAROA, 8 A Office of Nuclear Reactor Regulation. Director 3pp 22822 084 24X Fiche 50-348.84/03/26.8403300077
- G Inspection reports, IE Bulletins & correspondence
- 8402130400 Forwards IE Safequards Insp Repts 50-348/84-02 & 50-364/84-02 on 840116-20 No violetions noted VERRELLIJD M Division of Project & Resident Programs 84/02/08 MCDDNALD, R P Alabama Power Co 2pp 22203 251 24X Fiche 50-348-84/02/08,8402130400
- --B402130404 IE Safeguards Insp Repts 50-348/84-02 & 50-364/84-02 on 840116-20 No violations noted Major areas inspected security organization, testing & maint & physical barriers Details withheld (ref 10CFR2 790 & 73 21) MODRE, D E. Region 2, Office of Director MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 84/02/02 ip 22203 253 24X Fiche 50-348.84/02/08.8402130400
- 8403160142 Forwards IE Insp Repts 30-348/84-01 & 30-364/84-01 on 840118-19 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/02/15 MCDONALD.R P Alabama Power Co 2pp 22655 325 24X Fiche 50-348,84/02/15,8403160142
- --8403160146 [E Insp Repts 50-348/84-01 & 50-364/84-01 on 840118-19 No violations or devietions noted Hajor areas inspected samegency preperedness area of protective action decisionmaking CLINE.W Region 2, Office of Director JENKINS.OR Division of Emergency Preparedness & Materials Safety 84/02/13 4pp 22655 327 24X Fiche 50-348.84/02/15.8403160142
- 8401190072 lE info Notice 84-13, "Potential Deficiency in Motor Operated Velve Control Circuits & Annunciation " Svc list enc!

 JORDAN: E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York. Inc. 118pp 22909 239 24X Fiche 50-000.84/02/28.8401190072
- B403060125 Forwards summary of identified technical evaluation rept deficiencies re environ qualification of safety-related electrical equipment, defined by 1E Bulletin 79-018 & NUREG-058B, respectively Encl withheld (ref 100FR2 770) CLAYTON, F L. Alabama Power Co. 84/02/29 VAR9A, 5 A. Office of Nucleer Reactor Regulation, Director App. 22519 036 24X Fiche 50-34B,84/02/29,8403040125
- 8403290019 Forwards 1E Insp Repts 50-348/84-04 & 50-344/84-04 on 840131-0202 No violations or deviations noted VERRELLI.D M Division of Project & Resident Progrems 84/02/29 MCDBNALD, R P Alabema Power Co 2pp 22806 209 24X Fiche 50-348, 84/02/29, 8403290019
- --8403270027 IE Insp Repts 50-348/84-04 & 50-364/84-04 on 84013i-0202 No violations or deviations noted Major areas inspected emergency exercise DECKER, T R Region 2. Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Safety 84/02/27 7pp 22806 21i 24X Fichs 50-348.84/02/29.8403290019
- 8402070007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of CA. Befeguards & Inspection Programs (Post 830103) 8403/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 30-000,84/03/02,8402070007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp. 22553 078 24X Fiche 50-000,84/03/02,8402070008

- 8402090009 1E Info Notice 84-15. "Reporting of Radiological Releases" Svc list enci
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 117pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 84020900ii IE Info Natice 84-17, "Problems W.Liquid Nitragen Cooling Components Below Nil Ductiffty Temp " Bvc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Constitated Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,840209001i
- 8403150055 Responds to 840209 request for additinfore iE Builetin 80-11 concerning masonry walls. Block walls qualified by energy balance methods listed CLAYTON,F L Alabama Fower Co 84/03/05. VARGA.8 A Office of Nuclear Reactor Regulation, Director. 3pp 22641 161 24X Fiche: 50-348,84/03/05,8403150055
- 8403160257 Ack receipt of 840228 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-348/83-33 & 50-364/83-31 & LEWIS.R C Division of Project & Resident Progrems 84/03/05 HCDONALD.R.P Alabeme Pawer Co. ip 22660 280 24x Fichs 50-348,84/03/05.8403160257
- --8403160265 Responds to NRC 840203 ltr re violations noted in iE insp Repts 50-348/83-33 & 50-344/83-31 Corrective actions personnel counseled on importance of adhering to procedures CLAYTON,F L Alabama Power Co 84/02/28 LEHIS,R C Region 2, Office of Director 4pp 22660 281 24% Fiche 50-348,84/03/05, 8403160257
- --8403160272 Forwards IE Insp Rapts 50-348/83-33 & 50-364/83-31 on 831112-840110 & notice of violation LEMIB.R C Division of Project & Resident Programs 84/02/03 MCDONALD.R P Alabama Power Co 2pp 22660 295 24X Fiche 50-348.84/03/03.8403160257
- --8403160277 Notice of violation from insp on 831211-840110

 Region 2. Office of Director 84/03/05 2pp 22660 287 24X
 Fiche 50-348.84/03/05.8403160257
- --8403i60284 IE insp Repts 50-348/63-33 & 50-344/63-31 on 8312ii-8401i0 Noncompliance noted failure to follow procedures & failure to establish corrective measures to insure svc water value MOV 336 remained open to supply Train 8 BRADFORD, W H . RULAND, W H . Repton 2. Office of Director CANTRELL, F S Division of Project & Resident Programs 84/01/30 10pp 22660 289 24X Fiche 50-348,64/03/05,8403i60257
- 8402070024 IE Info Natice 84-07. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Eys " 8vc list encl JORDAN.E L Division of Emergency Preparegness & Engineering Response (Post 830103) 84/03/07 Conecidated Edison Co. of New York, Inc 118pp 22635 049 24X Fiche 90-000,84/03/07,8402090024
- B40209002B IE Info Notice B4-18, "Stress Corrosion Cracking in PWR
 Bys " Swc list enci
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/03/07 Consolidated Edison Co. of New
 York, Int. 118pp 22584 186 24X Fichs 50-000.84/03/07.8402090028
- B403290319 Responds to IE Bulletin B3-07, "Apparently Fraudulent Products Bold by Ray Milier, Inc " Results of review showed only Hestinghouse supplied equipment utilizing Ray Miller components List of 30 ventors contected encl CLAYTON.F L. Alabama Power Co. B4/03/09 O'REILLY, J. P. Region 2, Office of Director Spp. 22802 067 24X Fiche 50-349,84/03/09,840390319
- 3402090031 IE Builetin 84-02. "Feiluras of GE Type HFA Relays in Use in Class IE Safety Sys " Byc list encl DEYDUNG:R C Director's Defice. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, inc 134pp. 22823 074. 24X Fiche 50-000.84/03/12.8402090031
- 3403270078 Ack receipt of 840308 itr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-348/84-03 to 50-344/84-03 VERRELLI, D M Division of Project & Resident Programs 84/03/14 MCDDNALD, R F Alebama Power Co ip. 22806 311, 24X Fiche: 50-348,84/03/14,8403270078
- -8403270084 Responds to NRC 840215 ltr re violations noted in IE Insp Repts 50-348/84-03 & 50-364/84-03 Corrective actions responsible personnel instructed to implement procedures for control of maint activities CLAYTON.F.L. Alabama Power Co. 84/03/08 VERRELLI.D.M., Region 2. Office of Director 2pp 22806 3i2 24X Fiche: 50-948, 84/03/14,8403270078.

- --8403270089 Forwards IE Insp Repts 50-348/84-03 & 50-264/84-03 on 840111-0205 & notice of violation VERRELLI.D.M Division of Project & Resident Programs 84/02/15 MCDDNALD.R P Alebama Fower Co 2pp 22806.314 24X Fiche 50-348.84/03/14.8403290078
- --8403290096 Notice of violation from insp on 840i11-0205.

 * Region 2, Office of Director, 84/02/15 ip 22806 3i6. 24X Fich 50-348,84/03/14,8403290078
- --8403290103 IE Insp Repts 50-348/84-03 & 50-364/84-03 on 840111-0205 Violation found failure to implement procedures for control of maint activities BRADFORD H H , RULAND, H H Region 2. Defice of Director. CANTRELL, F B Division of Project & Resident Programs 84/02/15 8pp 22806:317 24% Fiche 50-348,84/03/14,8403270078.
- 8403230134 Requests relief from hydrostetic testing of feedwater reducers during current refueiing outage. Reducers replaced after ultrasonic exams found tracks in weld areas Radiographic & visual exams performed per 1E Bulletin 79-13 CLAYION.F.L Alabama Power Co. 84/03/19 VARQA.8 A Office of Nuclear Reactor Regulation, Director 4pp 22730, 207 24X Fiche. 50-348, 84/03/19, 8403230134
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities" 8vc list enci.

 UGRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21. Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21.8402090043
- 8402090044 IE Info Notice 84-20, "Bvt Life of Relays in Sefety-Related Bys " Svt list entl JURDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22933:001 24X Fithe 50-000.84/03/21.8402090044.
- R Periodic operating reports & related correspondence
- 8 Reportable occurrences, LERs & related correspondence
- 8403260233 Forwards summary list of deficiencies identified per iOCFR80 55(e), Part 21 & potential generic ltr repts for comments
 STAROBTECKI, R Division of Project & Resident Programs
 Region i. Office of Director, 7pp 22756 065 24X
 Fiche: 50-000, 84/02/28, 8403260233.
- 8403070263 PNO-II-84-020 on 840301, redioagraphic tests confirmed feedwater norzle crack indications on all three steam generators Component replacements under active consideration IE & NRR informed SLAKE, J. J. BUTCHER, R. C. Region 2, Office of Director 84/03/02 2pp 22547-298 24X Fiche 50-348.84/03/02,8403070263
- 8403090243 LER 84-002-00 on 840210, reactor tripped from approx 10% power due to intermediate range high flux signal Caused by overly conservative trip setpoints New trip setpoints inputed W/840306 itr.
 HAIRSTON.H 0 . CLAYTON.F.L. Alebame Power Co 84/03/06 3pp. 22573 250 24% Fiche 50-348.84/03/06.8403090243
- 8403150084 LER 84-003-00 on 840218, detensioning of reactor vessel head stude begun w/RCS boron concentration greater than Tech Spec limits Ceused by misinterpretation of Tech Specs. Personnel counsaled, N/840309 ltr HAIRSTON, N 0 , CLAYTON, F L Alebama Power Co 84/03/09, 3pp 22642-355. 24x Fiche: 50-346, 84/03/09, 8403150084.
- 8403260017 Forwards LERs 84-006-00,84-007-00,84-004-00 & 84-005-00. CLAYTON,F L Alabama Power Co 84/03/21 Record Services Branch (Document Control Desk). 2pp 22748/348. 24X Fiche; 50-348, 84/03/21,8403260017
- --8403260040 LER 84-004-00: on 840227, during planned maint on MSIVs, surface indications in operator side packing bland area discovered on three of six shafts Investigation ongoing. All six shafts will be replaced HAIRSTON, W G. Aisbama Power Co 84/03/21. 2pp 22748 352, 24X Fiche 50-348,84/03/21,8403260017.

- ~-8403260046 LER 84-005-00 on 840227, during planned ultrasonic exam of feedwater piping, indications found in feedwater reducer to steam generator notile welds Repairs will be completed during current outage HAIRSTON W 0 Alabama Power Co 84/03/21 3pp 22748 354. 24x Fiche 50-348,84/03/21,8403260017
- 8403250026 LER 84-006-00 on 840223, w/unit in Mode 6, both containment personnel airlock doors opened simultaneously for 30 s Cause undetermined linner door immediately closed HAIRBTON, N O Alabama Power Co 84/03/21 2pp 22748 348 24X Fiche. 30-348, 84/03/21, 9003260017
- DUCKET 50-352 LIMERICK GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings. Forwards App A,8 & C documents FELTON. J M Division of Rules and Records 83/10/31 RDSENBADM. D M Technical Analysis Corp 19pp 22193 292. 24X Fichs 30-000.83/10/31.8402090003
- --8402070183 Hendwritten notes & calculations re const activities & fuel load preparation.

 * NRC No Datailed Affiliation Given, 79/07/24 5pp 22175:057 24X Fiche 50-000.83/10/31.8402070003
- 8401240207 Forwarde add1 info re stress-assisted corrosion cracking of primary sys comments & potential main cooling tower failure modes & consequences, in response to ACRS 831018 ltr KEMPER, J 8 Philadelphia Electric Co 84/01/18 ECHWENCER, A Licensing Brench 2 3pp. 21908 148 24X Fichs 50-352,84/01/18,8401240207
- --8401240211 "Rept on Effects of Postulated Failure of Cooling Tower" W/three oversize drawings Aperture cards are available in POR.

 + Philadelphia Electric Co P-281/2 83/12/31 15pp 21908 151 24X Fiche: 50-352,84/01/18,8401240207
- 8403020104 Forwards magnetic tape containing hour by hour meteorological data for Oct 1983 Jan 1984, per 831013 ltr Data from primary meteorological tower & satellite tower & tape formats described KEMPER, J 8. Philadelphia Electric Co 84/02/27 SCHWENCER, A Licensing Branch 2 3pp 22443.240 24X Fiche 50-352, 84/02/27, 8403020104.
- B403020257 Forwards application for amend to CPPR-106 & CPPR-107 (filed in Category A). Rev 17 to environ rept DL stage (filed in Category C) & Rev 29 to FBAR (filed in Gategory K).

 BRADLEY.E J Philadelphia Electric Co. B4/02/29 DENTON. H R

 Office of Nuclear Reactor Regulation. Director 2pp 22495 026
 24X Fiche 50-352.84/02/29,8403020257
- ---8403020266 Application for amend to CPPR-106 & CPPR-107. Certificate of Byc encl KEMPER, J 8 Philadelphia Electric Co 84/02/27 6pp 22495 028 24X Fiche:50-352,84/02/29,8403020257
- 8403150262 Forwards request for add1 info re standby gas treatment sys Info needed to eveluate FSAR, Section 6 5, Rev 25. BCHWENCER, A. Licensing Branch 2. 84/02/29. BAUER, E. G. Philadelphia Electric Co. 4pp. 22648 342 24X Fiche. 50-352, 84/02/29, 8403150262
- 9403160189 Notification of 840314:15 & 16 meetings w/util in Philedelphia:PA & Montgomery County-PA:respectively.to discuse NRC audit of environ qualification files & installed equipment.

 KINTNER, L Licensing Branch 1, 84/03/05 8CHHENCER, A. Licensing Branch 2, 4pp 22662:259 24X Fiche 50-352,84/03/05,8403160189
- 8403160192 Advisee of errors made in wind direction frequencies for GRACZ calculation. Revised calculations for severe accident risk assessment expected to change predicted latent cancer fatalities.

 KEMPER. J. B Philadelphia Electric Cp 84/03/13, 8CHWENCER, A Licensing Branch 2, 2pp 22655 244, 24X Fiche 50-352,84/03/13,8403160192,
- B403190197 Forwards Rev C to Anchor/Darling Valve Co Drawing 93-14182, correspondence re HPCI,RCIC & reactor water cleanup containment isolation valve closure capabilities & Rev 23 to Matl Requisition 8031-P-104, per 840202 telcon. KEMPER, J. B Philadelphia Electric Co. 84/03/13. BCHWENCER, A. Licensing Branch 2 134pp 22670 001, 24x Fiche 50-352,84/03/13,8403190197.

- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT.D G Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24% Fiche 30-000.84/03/14,8402090041
- 8403270172 Informs that 840801 is current const completion date, per B10811 request for quarterly updates Possibility of advancing date being reviewed, per util 831227 ltr Svc list encl
 KEMPER. J 8 Philadelphia Electric Co 84/03/22 EISENHUT. D O Division of Licensing 2pp 22771 309 24X Fiche 50-352, 84/03/22, 8403270172
- C Utility Environmental Report (ER). amends & correspondence
- 8403020237 Forwards Rev 17 to environ rept OL stage BRADLEY,E J Philadelphia Electric Co 84/02/29 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22495 026 24% Fiche 50-352,84/02/29,8403020257
- --8403020270 Rev 17 to environ rept OL stage * Philadelphia Electric Co 84/02/29 20pp 22495 034 24x Fiche 50-352,84/02/29,8403020257
- B403150036 Forwards Affidavit of Svc re distribution of Rev 29 to FBAR & Rev 17 to environ rept, per DO Eisenhut 810706 request BRADLEY, E J Philadelphia Electric Go B4/03/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 22643 270 24X Fiche 50-352, 84/03/12, 8403150036
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8403160026 Notifies that Natl Ctr for Devices & Radiological Health has no comment re poetulated plant accidents described in DES (NUREO-0974)

 VILLFORTH, J C Food & Drug Administration 84/02/10 SCHWENCER, A Licensing Branch 2 1p 22654 346 24X Fiche 50-352, 84/02/10, 8403160026
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403010144 Forwards draft FPER pages containing info to close BER Open Issue 15 re electrical cable & cable tray & fire areas having high concentrations of cables info in draft FPER will be incorporated into Rev 5 scheduled for Mar 1984 BOYER: V 9 Philadelphia Electric Co 84/02/16 SCHMENCER: A Licensing Branch 2 9pp 22495 313 24x Fiche 50-352.84/02/16, 8403010144
- 8403050161 Forwards "Structural Steel Survivability Evaluation." in response to 840207 request for addition (RAI 280 26), per SER Open Item 14
 KEMPER. J B Philadelphia Electric Co 84/02/29 SCHWENCER, A Licensing Branch 2 3pp 22483 037 24x Fiche 50~352,84/02/29, 8403050161
- --8403050163 "Structural Steel Survivability Evaluation " Rev 1 to "Comparison of Philadelphia Electric Co Heat Balance Model w/NUREG/CR-3172" enc1 * Philadelphia Electric Co 84/02/24 372pp 22483 040, 24X Fiche 50-352,84/02/29,8403050161
- B403260249 Forwards "UHS Extreme Hind Hazard Analysis." in response to B30808 ltr re SSER Open Issue 2 KEMPER.J 8 Philadelphia Electric Co 84/03/22 SCHWENCER.A Licensing Branch 2 2pp 22755 001 24X Fiche 50~352,84/03/22,8403260249
- --8403260253 "UHS Extreme Wind Hazard Analysis " BITOMF. T B : PARRY. Q W NUS Corp NUS-4507 84/03/31 134pp 22755 004 24X Fiche 50-352.84/03/22.8403260249
- F Becurity, medical, emergency & fire protection plans
- 8403070361 Public version of revised emergency plan implementing procedures, including Procedure EP-201 re technical support ctr activation: EP-210 re dose assessment team & EP-222 re field survey group W/831212, 840215 ltrs & 840302 memo DALTROFF; S.L. Philadelphia Electric Co 83/11/30 MURLEY; T E Region 1, Office of Director, SCHMENCER, A Licensing Branch 2 163pp 22564 061 24x Fiche, 50-352, 83/11/30, 8403070361.
- 8403090290 Public version of Rev O to emergency plan implementing procedures including Procedure EF-110 repersonnel assembly. EP-221 repersonnel dosimetry & EP-208 resecurity team activation W/831212 ltr & JM Felton release memo DALTROFF, B L. Philadelphia Electric Co. 83/11/30 SCHWENCER, A Licensing Branch 2. 80pp. 22592 062 24X Fiche 30-352.83/11/30.8403090290

- 8403010144 Forwards draft FPER pages containing into to close SER Open Issue 15 re electrical cable & cable tray & fire areas having high concentrations of cables into in draft FPER uill be incorporated into Rev 5 stehduled for Mar 1984 BOWER.V S Philadelphia Electric Co 84/02/16 8CHHENCER.A Licensing Branch 2 9pp 22435 313 24X Fiche 50-352,84/02/16,8403010144
- B402090006 Board Notification B4-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT.D G Division of Licensing 84/02/23 FALLADING Commissioners ip 22576 203 24X Fiche 50-000.84/02/23. B402090006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRR Off Ltr 19,646 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering. 84/02/06 EISENHUT, D 9 Division of Licensing 10pp 22576 204 24X Fiche 50-000,84/02/23.8402090006
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-07 Agenda for workshop encl HURLEY.TE Region I. Diffice of Director 84/03/09 O'TODLE.J D Consolidate Edison Co of New York. Inc. FIEDLER.P B General Public Utilities OPU Service Corp. 33pp 22672-062 24x Fiche 50-000.84/03/09.8403190243
- 8403270144 Forwards IE Insp Rept 50-352/84-08 on 840206-09 No violations noted MARTIN: T Division of Engineering & Technical Programs 84/03/13 KEMPER, J S Philadelphia Electric Co 2pp 22806 096 24X Fiche 30-352.84/03/13,8403290144
- --B403290130 IE Inep Rept 50-352/B4-08 on 840206-09 No violations noted Major areas inspected onsite/offsite safety committee activity.operational staff training & fuel receipt & storage programs PRELL.J A. BISECTI, P. CLIVEIRA: W. Region 1, Office of Director B4/03/07 8pp 22806 098 24X Fichs 50-352, B4/03/13, B403290144
- 8403R1002B Forwards response to NRC 840306 & OB requests for add1 info re emergency action lavels, specifically, containment radiation levels Draft changes to emergency plan will be incorporated as stated in enc1
 DALTROFF, S L Philadelphia Electric Co 84/03/16 BCHWENGER, A Licensing Branch 2 80pp 22708 255 24X Fiche 50-352, 84/03/16, 840321002B

G Adjudicatory correspondence

- 8403010271 Forwards reply to applicant & staff response to City of Philadelphia issues SMOLEN, H Philadelphia, PA 84/02/28 Docketing & Services Branch 1p 22432 207 24X Fiche 50-352,84/02/28,8403010271
- --B403010275 Reply to applicant & staff responses to City of Philadelphia issues re emergency response plan State plan does not contain & is not based upon standardized protective action guidance for exposure from feedstuffs & water EMDLEN-H Philadelphia, PA 84702/28 Atomic Safety and Licensing Board Panel 43pp 22432 20B 24X Fiche 50-352,84702/28,8403010271
- 8403020099 Forwards answer to City of Philadelphia interrogatories on sys interaction designated Discovery 28 W/exception of three listed documents, documentary mat responsive to request will be made available for insp Related correspondence METTERMANN H J Conner & Wetterhahn 84/02/29 BUSH, M W Philadelphia, PA 6pp 22443 048 24% Fiche 50-352, B4/02/29, B403020099
- --B403020105 Answers City of Philadelphia Interrogetories on sys interaction contention Certificate of Svc encl.Related correspondence BOVER.V S Philadelphia Electric Co B4/02/27, 65pp 22443 054 24X Fiche 50-352,84/02/29,8403020099.
- 8403020125 Transmittal of mat) supporting applicant 840228 revised testimony re-ability of safety-related structures to withstand effects of postulated detonation from pigeline ruptures Certificate of Svc enci Related correspondence.
 WETTERHAHN.M J Philadalphia Electric Co WETTERHAHN.M J Conner Retterhahn. 84/02/29 4pp 22442 143 24X Fiche 50-352,84/02/29,8403020125

- 8403020163 Response opposing new contention proposed by Air & Water Pollution Patrol re discharge of asbestos fibers Contention lacks basis & specificity required by 10CFRZ 714(b) Certificate of Byc encl METTERHAHN, M J Philadelphia Eiectric Co WETTERHAHN, M J Conner & Hetterhahn B4/02/27 Atomic Safety and Licensing Board Panel lipp 22442 006 24X Fiche 50-352,84/02/29,8403020163
- B403060129 Forwards Certificate of Bvc for reply to applicant & staff responses to City of Philadelphia issues
 SMOLEN.H Philadelphia. PA 64/02/29 Docketing & Services
 Branch 3pp 22306 327 24% Fiche 30-332.84/02/29,8403060129
- 8403060081 Response opposing Friends of the Earth 840224 motion to strike applicant & staff structural analysis testimony Motion fails to establish testimony as unreliable Certificate of Svc enc. Related correspondence WETTERHAHN, M Philadelphia Electric Co WETTERHAHN, M Conner & Metterhahn 8403/01 Atomic Safety and Licensing Board Panel opp 22516 337 24X Fiche 50-352.84/03/01.8403060061
- 8403060248 Amswer to new contentions proposed by Friends of the Earth on onsite storage of unirradiated fuel & transmittal of related correspondence Proposed late contentions should be denied Certificate of 80c enci HETTERHAHN, M J Philadelphia Electric Co HETTERHAHN, M J Conner & Hetterhahn 84/03/01 Atomic Safety and Licensing Board Panel 33pp 22517 079 24X Fiche 50-352,84/03/01,8403040248
- 8403140118 Forwards cross-examination plans for structural analysis hearing on blast overpressures, per ASLB 840120 order W/o encl
 VOCLER.B H Hearing Branch 2. 84/03/01 BRENNER.L., COLE.R F, HORRIG.P A Atomic Safety and Licensing Board Panel 2pp 22623 338 24X Fiche 50-352.84/03/01.8403140118
- 8403060097 Hemorandum & order damying intervenor Lewis 831224 motions based on newly received info Lewis discovery rights not abridged per Contention 1-62 M/Certificate of 8vc BRENNER.L. COLE: R F , MORRIS.P A Atomic Safety and Licensing Board Panel 84/03/02 Lewis M 11pp 22506 262 24X Fichs 50-352,84/03/02,8403060097
- 8403070142 Response opposing Air & Hater Pollution Patrol 840221 request for extension of discovery period for Contention VI-1 Centificate of Svc encl Related correspondence HETTERHAHN. H J Philadelphia Electric Co HETTERHAHN. M J Conner & Wetterhahn 84/03/02 Air and Water Pollution Patrol 7pp 22538 271 24X Fiche 50-352,84/03/02.8403070142
- 8403070234 Response to Air & Water Pollution Patrol motion to compel discovery Applicant denies that answer to interrogatory evasive Related Correspondence METTERHAHN, H J Philadelphia Electric Co HETTERHAHN, H J Conner & Wetterhahn 84/03/02 Atomic Safety and Licensing Board Panel 3pp 2236 217, 24% Fiche 50-332,84/03/02,8403070236
- --8403070238 Response opposing Air & Hater Pollution Patrol request for depositions re Contention VI-1 No reason given why depositions necessary W/Certificate of Evc HETTERHAHN.M J Philadelphia Electric Co WETTERHAHN.M J Conner & Wetterhahn 84/03/02 Atomic Safety and Licensing Board Panel App 22536 221 24% Fichs 50-332,84/03/02,8403070236
- 8403140085 Response opposing Friends of the Earth 840223 application to file contention based on new matter re fuel storage Certificate of gvc encl WILCOVE, M N Hearing Branch 2 84/03/02 Atomic Safety and Licensing Board Panel 14pp 22633.235 24X Fiche 50-252.84/03/02, 8403140085
- 8403120001 Notice of withdrawal of offsite emergency planning issue re evacuation time estimate study Applicant 840824 representation addresses issues W/Certificate of Svc FERKIN, 7 G Pennsylvania, Commonwealth of, 84/03/05 5pp 22588.036 24X Fiche 50-352,84/03/05,8403120001
- B403140103 Response opposing Air & Hater Poilution Patrol (AWPP) B40213 motion filing new info contention. AWPP fails to meet stde for laterfiled contentions Certificate of Bvc encl WRIGHT, N A Hearing Branch 2 B4/03/05 Atomic Safety and Licensing Board Panel Bpp 22623,330 24X Fiche 50-352,84/03/05,8403140105

- B403:3041: Forwards notice of change of address & firm name Certificate of Bvc encl
 SUGARMAN,R J Bugarman & Denworth SUGARMAN,R J Del-Aware
 Unlimited, Inc 84/03/07 Docketing & Services Branch 6pp
 22616 319 24% Fiche 50-352,84/03/07,8403:30411
- 8403140110 Findings of fact & conclusions of law in form of partial initial decision on Air & Water Pollution Patrol Contention V-4 re carburetor icing Certificate of 5vc encl HODOPOIN.A P Hearing Branch 2 84/03/07 25pp 22624 075 24X Fiche 50-352.84/03/07.8403140110
- B403150024 Reply findings of fact & conclusions of law re Contention V-4 in response to Air & Water Pollution Patrol (AWPP) B40224 proposed findings AMPP findings should be rejected Certificate of Svc encl HETTERHAHN, M J . NICHOLS, N N Philadelphia Electric Co HETTERHAHN, M J . Conner & Wetterhahn 84/03/12 9pp 22641 282 24X Ficha 50-352,84/03/12,8403150024
- 8403190007 Responses to util interrogatories on Contention 1-42 Centificate of Svc encl Related correspondence • Philadelphia, PA, 84/03/12 Philadelphia Electric Co 15pp 2265 337 24x Fiche 50-352,84/03/12,8403190007
- 8403160010 Forwards affidavit of L8 Pyrih & P8 Stansbury re hypothetical accidents involving unirradiated fuel to be stored at plant No credible potential for violating regulations identified Rejated correspondence WETTERHAHN, M J Philadelphia Electric Co. WETTERHAHN, M, J Conner & Wetterhahn 84/03/13 lp 22662 164 24X Fiche 50-352.84/03/13, 8403160010
- --8403160187 Affidavit of LB Pyrih re storage of Unirradiated fuel No potential for violating provisions of 10CFR20 as result of credible accidents affecting new fuel assemblies stored at plant Certificate of Svc encl
 PYR
- --8403160188 Affidavit of P8 Stansbury re calculation of exposure rates in various assumed configurations of specified quantities of U enriched to 1 85% in isotope U-235 STANSBURY:P 8 General Electric Co 84/03/12 7pp 22662 186 24% Fiche 50-352:84/03/13:8403160010
- B403190132 Appeal opposing dismissal of Anthony/Friends of the Earth contention on util application to store nuclear fuel outdoors & ASLB denial of immediate stay on moving fuel ANTHONY, R L ANTHONY, R L Friends of the Earth B4/03/13 Atomic Bafety and Licensing Appeal Panel 1p 22666-306 24X Fiche.50-352.84/03/13.8403190132
- --BA0319013B Application to file contention re util application to store fuel outdoors Fuel storage is hazard to community due to question of whether bldgs can utilstand overpressures & impacts from offsite eccidents.

 ANTHONY.R L ANTHONY.R L Friends of the Earth B4/02/23 Atomic Eafety and Licensing Board Penel 1p 22666 307 24X Fiche, 50-352,84/03/13,8403190132
- 8403170160 Affidavit of N Ketrlach re possibility of radiological releases from fuel assemblies in shipping containers in violation of NRC regulations Certificate of Svc encl KETILACH.N Uranium Fuel Licensing Branch 84/03/13 5pp 22668.358, 24% Fiche 50-352.84/03/13,8403170160
- 8403190173 Forwards ND Romney 840313 memo to G Lear re results of 840306 conference call from applicant. VOOLER, B H Hearing Branch 2 84703/13 BRENNER, L, MORRIS, P A, COLE, R F Atomic Bafety and Licensing Board Panel 4pp 2267: 158 24X Fiche 50-352,84/03/13,8403190173
- 8403200090 Forwards 840313 ltr documenting discovery of errors in predicted consequences reported in severe accident risk assessment Consideration of admissibility of contentions should proceed as scheduled, Related correspondence HETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co. 84/03/13 BRENNER, L , MORRIB, P A., COLE, R F Atomic Safety and Licensing Board Panel. 3pp 22685, 278 24X Fiche: 50-352, 84/03/13, 8403200090
- 8403200144 Forwards listed add1 info re HPCI isolation valves, per NRC Equipment Qualification Branch 840202 telcon request W/o encl. Related correspondence
 KEMPER, J S Philadelphia Electric Co 84/03/13 BCHHENCER, A Licensing Branch 2 2pp 22699 159 24X Fiche 50~352,84/03/13, 8403200144.

- 8403190038 Motion for new contention based on IE Notice 84-17 re problems w/liquid nitrogen cooling components below nil ductility temp Facility design deficient because liquid nitrogen can cool vital components below temp. LEWIS, M I Lewis, M 84/03/14 Atomic Safety and Licensing Board Panel 4pp 22666 235 24X Fiche 50-352,84/03/14,8403190038
- 8403190040 Order directing parties to hold settlement conferences for onsite emergency planning contentions Courtesy notification encl
 BRENNER, L Atomic Safety and Licensing Board Panel 84/03/15
 Office of the Executive Legal Director 5pp 22666 240 24X
 Fiche 50-332.84/03/15.8403190040
- 8403190140 Supplemental info on Limerick Ecology Action offsite emergency planning Contentions 3,4,13,17,20 & 28 requested at pre-hearing conference Certificate of Svc encl # Limerick Ecology Action 84/03/15 Atomic Bafety and Licensing Board Panel 34pp 22666 316 24X Fiche 50-352,84/03/15,8403190140
- 8403190153 Order confirming miscellaneous oral rulings made at hearing held during wk of 040305 Testimony & hearing schedules listed Courtesy notification encl.
 BRENNER, L. Atomic Safety and Licensing Board Panel 04/03/15
 Office of the Executive Legal Director. 8pp. 22668,346 24X
 Fiche 50-352.84/03/15.8403190153
- 8403200015 Forwards revised radiological emergency response plan for Pennhurst Mental Retardation Ctr to ASLB, intervenors & City of Philadelphia W/o encl Related correspondence BELSER, A L. Pennsylvania. Commonwealth of. 84/03/15 IRENNER. L. MORRIES, P. A. COLLER F. Atomic Safety and Licensing Board Panel 2pp. 22698:344 24X Fiche 50-352,84/03/15,8403200015
- 8403200060 Forwards "Protective Order on SNM Security Plan Info" & "Affidavit of Non-Disciosure" re storage of irradiated fuel Certificate of Bvc encl Related correspondence. WETTERHAHN.M J Canner & Wetterhahn WETTERHAHN.M J Philadelphia Electric Co 84/03/16 BRENNER.L COLE.R F . MORRIS.P A Atomic Bafety and Licensing Board Panel 14pp 22684 342 24X Fiche 50-352.84/03/16.8403200060
- 8403200070 Memorandum & order on Friends of the Earth contentions & Limerick Ecology Action petition re Part 70 application to store new fuel BRENNER.L., MCRRIB.P A Atomic Safety and Licensing Board Panel 84/03/16 30pp. 22685-106 24X fiche.50-352.84/03/16.8403200070
- 8403200110 Requests that enci AS Joffe 840311 ltr re assessos piping be served to parties in proceeding LANE, v.M. Atomic Safety and Licensing Board Penel. 84/03/14 CLEMENTS, U. Defice of the Secretary of the Commission 2pp 22697-043 24X Fiche 30-352,84/03/14,8403200110
- 8403210067 Forwards Commission statement of policy re challenge to elimination of financial qualification review requirements Related correspondence WRIGHT, N A Hearing Branch 2 84/03/16. BRENNER, L., MORRIS, P.A., COLE, R.F. Atomic Bafety and Licensing Board Panel 4pp 22705 052 24X Fiche. 30-352, 84/03/16, 8403210047
- 8403210096 Forwards Transportation Certification Branch 840312 memo & Certificate of Compliance mentioned in 840313 affidavit of N Ketzlach, Related correspondence WRIGHT.N A Hearing Branch 2 84/03/16 BRENNER.L. MORRIS,P A. COLE,R F Atomic Safety and Licensing Board Panel 7pp 22706 001 24X Fiche 50-352,84/03/16,8403210096.
- 8403210128 Forwards Delaware River Basin Commission Aug 1980 final environ assessment for Neshaminy Water Supply Bys & 800825 negative declaration.per ASLAB 840315 telcon request W/o encl Related correspondence HDD000N.A P Hearing Branch 2 84/03/16 NOHL.C N , EDLES.C J . GOTCHY.R L Atomic Safety and Licensing Board Panel 2pp 22707:242 24X Fiche 50-352,84/03/16.8403210128
- 8403280354 Memorandum & order on Friends of the Earth contentions & Limerick Ecology Action petition based on 100FR70 application to store new fuel Served on 840327 BRENNER.L. MORRIS.P A Atomic Safety and Licensing Noard Panel D88 147 84/03/16 Friends of the Earth 30pp 22787 174 24X Fiche 50-352.84/03/16,8403280354
- 8403210092 Answer to Limerick Ecology Action (LEA) supplemental info on LEA offsite emergency planning contentions Proposed contentions should be denied Certificate of Syc encil CONNER. T B Philadelphia Electric Co. CONNER. T B Conner & Hetterhahn 84/03/19 17pp. 22705 322 24X Fiche 50-352, 84/03/19, 8403210092

- 8403210103 Motion to delete specific instances in support of Contention VI~1 advanced by Air & Water Pollution Patrol as unrelated to welding or welding GA activities Certificate of Svc encl HETTERHAKN, M J Philadelphia Electric Co WETTERHAKN, M J Conner & Wetterhakn B4/03/19 Atomic Safety and Licensing Board Panel 10pp 22705 ii8 24X Fiche 50-352.84/03/19,8403210103
- 8403210167 Forwards Commission "Statement of Policy on Environ Qualification" & proposed rule, "Environ Qualification of Electric Equipment; Renoval of B20830 Deadline" Related correspondence
 HODODON, A.P. Hearing Branch 2 DSB 017 84/03/19 BRENNER, L., COLE, R.F., MORRIS, P.A. Atomic Safety and Licensing Board Panel 11pp 22710 103 24x Fiche 50-05284/03/19,8403210167
- 8403220226 forwards request for reconsideration of asbestos contention & motion requiring further depositions be Contention VI-I ROMANG, F.R. Air and Water Pollution Patrol. DBB 046 B4/03/19 BRENNER, L., MORRIS, P. COLE, R. Atomic Safety and Licensing Board Panel. ip 22719 007 24% Fische 50-352,89/03/19,8403220226
- --8403220227 Request for reconsideration of asbestos contention Board did not adequately address hazard to public ROMAND.F R Air and Water Pollution Patrol 84/03/19 BRENNER,L. MORRIS.P., COLE.R. Atomic Safety and Licensing Board Panel 2pp 22719 008 24X Fiche 50-352,84/03/19,8403220226
- --8403220234 Motion to require further depositions re Contention VI-I contenting 760601 broomstick deficient welding affair RDMAND.F Air and Water Pollution Potrol 84/03/19 BRENNER.L., COLE, R Atpair Safety and Licensing Board Panel 2pp. 22719 010 24X Fiche 50-352.84/03/19.8403220226
- 8403270065 Protective order on SN1 security plan info Served on 840326 BRENNER.L. Atomic Sefety and Licensing Board Panel DSB 123 84/03/19 Limerick Ecology Action 3pp 22766 149 24X Fiche 50-352.84/03/19.8403270065
- --8403270069 Affidavit on mondisclosure for CW Elliott ELLIOTT, C W Limerick Ecology Action 84/03/16 4pp 22766 152 24x Fichs 50-352,84/03/19,8403270065
- 8403290378 Request for reconsideration of Air & Water Pollution Patrol asbestos contention ROMAND.FR Air and Water Poliution Patroi DSB 186 84/03/19 Atomic Safety and Licensing Board Panei 2pp 22814 142 24X Fiche 30~352
- 8403270017 Supplemental responses to info requests of City of Philadelphia Related correspondence 90YER.V S Philadelphia Electric Co DSB i12, 84/03/21 12pp 22770 056 24X Fiche 50-352,84/03/21,8403270017
- 8403280336 Forwards complaint of util vs Bouth Coventry Township filed on 840309, memorandum of law in opposition to petition for Preliminary Injunction 84-01645 & order of court dissolving injunction against Township Related correspondence ZITZER.P Limerick Ecology Action DSB 145 84/03/21 BRENNER, L MORRIS.P A . COLLE.R F Atomic Safety and Licensing Soard Panel 3290. 22787 055 24X Fiche 50-352,84/03/21,8403280336
- B403230005 Order delegating authority to exercise review functions over Part 70 issues raised in proceeding to Appeal Board Berved on B40322 CHILK-S J Office of the Secretary of the Commission DSO 070 B4/03/22 Atomic Safety and Licensing Appeal Panel 22726 359 24X Fichs 50-352,64/03/22,8405230005
- 8403230278 Order confirming briefing schedule for Friends of the Earth appeal of ASLB 840316 memorandum & order & for staff to provide Part 70 application.
 SHOEMAKER.C J. Atomic Safety and Licensing Appeal Panel B4/03/22 Office of the Executive Legal Director 2pp 22743 094 24% Fiche 50-352;84/03/22.8403230278
- B40326033 Forwards supplemental correspondence & documents re emergency planning. Math suppls earlier ltrs & covers period B40206-0315 W/o encls Related correspondence BADLEY,E J Philadelphia Electric Co DBB 09B 84/03/22 ZITZER,P Limerick Ecology Action 2pp 22760 162 24X Fiche 50-352,84/03/22.8403260333
- 8403270012 Informs that applicant will suppl 840217 responses to Info Requests 6.7:11 & 12 Related correspondence WEJTERHAHN,M J Conner & Wetterhahn WEJTERHAHN,M J Philadelphia Electric Co DSS 109 84/03/22 BUSH,M W Philadelphia, PA 2pp 22769 356 24X Fiche, 50-352, 84/03/22, 8403270012

- 840327007: Informs that feasibility of 84080: as current const completion date will be reviewed for possible advancement Related correspondence
 KEMPER.J B Philadelphia Electric Co DSB 108 84/03/22 EISENHUR.D 0 Division of Licensing 2pp 22766 164 24X Fiche 50-332.84/03/22.8403270071
- 8403270301 Informs that monthly repts for Nov 1983 Feb 1984 re Contract NRC-03-092 being sent by express mell Related correspondence HUTBERQ, J Heering Branch 2 DSB 135 84/03/22 ELLIOTT, C W Bross & Poswistills 2pp. 22789 032 24X Fiche 50-352,84/03/22, 8403270301
- 8403280333 Forwards rept, "UHS Extreme Wind Hezard Analysis." W/o encl Releted correspondence KEMPER.J 5 Philadelphia Electric Co DSB 160 84/03/22 8CHWENCER.A Licensing Branch 2 1p 22787 173 24X Fiche 50-352.84/03/22.8403280353
- 8403260349 Motion to dismiss particular onsite amargancy planning contentions for which discovery not provided or no litigable basis shown Certificate of Sve encl CONNER.T B Philadelphia Electric Co CONNER.T B Conner & Hetterhahn DSB 074 84/03/23 Atomic Bafety and Licensing Board Panel 16pp 22760 243 24x Fiche 50-352,84/03/23,8403260349.
- 8403300122 Response to Limerick Ecology Action (LEA) supplemental info on LEA offsite emergency planning contentions Certificate of Svc enci FERKIN, Z © Pennsylvania, Commonwealth of, D88 203 84/03/23 7pp 22820 303 24X Fiche 50-352,84/03/23,8403300122
- B403290375 Forwards response to applicant motion to delete specific instances in support of Contention VI-I as unrelated to uselding or welding-related QA activities Certificate of Boc enci
 RDMAND, F.R. Air and Water Pollution Patrol DBB 201 84/03/25
 Atomic Bafety and Licensing Board Penel 1p 22814 326 24X
 Fiche 50-352, 84/03/25, 8403290375
- --8403270397 Response to applicant motion to delete specific instances in support of Contention VI-I advanced by Air & Weter Pollution Patrol as unrelated to welding or welding-related GA activities
 RUMANO,F R Air and Water Pollution Petrol 84/03/24 Atomic Safety and Licensing Board Panel 11pp 22814 327 24X
 Fiche 50-382,84/03/25,8403290395
- 8403270027 Notice of ASLB constitution L Brenner, chairman & RF Cole & PA Morris, members Served on 840326 COTTER, B P Atomic Befety and Licensing Board Panel DBB 125, 84/03/26 2pp 22769 339 24X Fiche 50-352,84/03/26,8403270027.
- 8403270060 Stipulation re storage of unirradiated fuel WETTERHANN M J Philadelphia Electric Co. ELLIOTT.C H Limerick Ecology Action DBB 122 B4/03/26 2pp 22766,162 24X Fiche 50-352,84/03/26,8403270060
- B403280331 Memorandum & order confirming 840321 oral ruling on affidavits re-radiation releases from unirradiated new fuei rods Served on 840327
 BRENNER./L Atomic Safety and Licensing Board Panel, D8B 14B 84/03/26 Office of the Executive Legal Director. 2pp 22787.049 24X Fiche 50-352,84/03/26.8403280331
- 8403280359 Order imposing temporery stey of ABLB 840316 memorandum & order pending ruceipt of Friends of the Earth appeal of order Berved on 840328 SMCEMAKER, C J Atomic Befety and Licensing Appeal Panel DBB 161. 84/03/27 2pp 22787 229 24X Fiche 50~352,84/03/27,8403280359
- B403300129 Joint rept on status of negotiations re onsite emergency planning contentions & Limerick Ecology Action dismissal of particular contentions. Certificate of Svc encl RADER, R M Philadelphia Electric Co RADER, R M Conner & Hetterhahn ELLIOTT, CW Limerick Ecology Action DBB 204 B4/03/27 App. 22820 008 24% Fiche 50-352,84/03/27,8403300129
- 8403300271 Forwards QA audits re Colt Industries Fairbenks Morse Engine Div.dissel generators W/o encl.Related correspondence WETTERHAHN, M J Philedelphia Electric Co WETTERHAHN, M J Gonner & Wetterhahn DSB 212 84/03/27. 3pp 22824 037 24X Fiche 50-352,84/03/27,8403300271
- --B403300274 Response to Air & Water Pollution Petrol (AMPP) 840319 motion to require further depositions re Contention VI-1. AMPP failed to support request for relief & motion should be denied W/Certificate of Svc Related correspondence WETTERHAMN. M. J. Philadelphia Electric Co WETTERHAMN. M. J. Affiliation Not Assigned 84/03/27 Atomic Safety and Licensing Board Panel 7pp 22824:040 24% Fiche: 50-352,84/03/27, 840300271

- 8403290374 Forwards portions of transcripts re ASLB 840320 ruling on admissibility of Limerick Ecology Action contentions & City of Philadelphia issues on facility DEB, Suppl 1 Related correspondence HODGODN.A P Hearing Branch 2 DSB 199 84/03/28 ELLIOTT, C W Brose & Poewistillo BUSH, N W Bush, N W FERKIN, Z O Penneylvania, Commonwealth of: 31pp 22814 091 24% Fiche 50-332,84/03/28,8403290374
- 8403270384 Brief in apposition to intervenor Friends of the Earth for stay of onsite storage of unirradiated fuel Stay request fails to demonstrate any conceivable harm as result of fuel storage Certificate of Svc encl
 HETTERHAHN.M J Philadelphia Electric Co HETTERHAHN.M J Conner & Hetterhahn DSE 190 84/03/28 1ipp. 22814 240 24%
 Fiche 50-352,84/03/28,8403270384
- 8403290393 Memorandum & order confirming denial of Air & Weter Poliution Patrol motion for further dispositions re Contention VI-1 Certificate of Bvc encl BRENNER,L Atomic Safety and Litensing Board Panel DSB 187 84/03/28 4pp 22814 322 24X Fiche 50-352,84/03/28,8403290393
- 8403270399 Forwards staff 840320 response to Limerick Ecology Action supplementary info.
 VOGLER, B H Hearing Branch 2 DSB 200 84/03/28 DRENNER, L,
 MORRIS, P A , COLE, R F Atomic Safety and Licensing Board Panel
 2pp 22814 338. 24X Fiche, 50-352, 84/03/28, 8403290399
- --8403290400 Response to Limerick Ecology Action 840313 supplementary info on offsite emergency planning contentions Staff position remains unchanged Certificate of Svc encl VOQLER,B.H. Hearing Branch 2 84/03/20 2pp. 22814 340 24X Fiche.50-352,84/03/28,8403290399
- 8403300127 Transmittal of refe & errata to applicant 840321 testimony of kJ Boyer, DJ Thompson, DA Kline, L Steniey, EF Sproat, WH Bowers, TE Shannon & J Doering on Contention 1-42 Related correspondence HETTERHANN, M J Philadelphia Electric Co HETTERHANN, M J Conner & Wetterhahn DSB 204 84/03/28 7pp 22820 245 24X Fiche 50-352, 84/03/28, 8403300127.
- 8403300128 Reeponse opposing M Lawis 840314 motion for new contention besset on IE Info Notice 84-17 cooling of vital components by liquid nitrogen, Certificate of Svc encl METTERHAHN, M. J. Philadelphia Electric Co. METTERHAHN, M. J. Conner & Wetterhahn DSB 205 84/03/28 Atomic Sefety and Licensing Board Panel. 12pp. 22820 291 24X Fliche 50-352,84/03/28,8403300128
- 8403300287 Forwards PH Patery 840315 ltr re questione concerning fiscion producte Ltr should be forwarded to appropriate NRC individual for response & response served in proceeding 8erved on 840330 LANE.V. M. Atomic 8afety and Licensing Board Panel, D8B 218 84/03/29, VOGLER, B.H. Hearing Branch 2, 2pp 22824:016 24X Fichs. 50-352, 84/03/29, 8403300287
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8403020257 Forwards Rev 29 to FSAR BRADLEY,E, J. Phlladelphia Eiectric Co 84/02/29 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22495.026 24X Fiche. 50-552,84/02/29,8403020257.
- --8403020273 Rev 29 to F8AR

 * Phlladelphia Electric Co 84/02/29, 538pp 22495 056 24X
 Fiche: 50-352, 84/02/29, 8403020257,
- 8403150036 Forwards Affidavit of Svc re distribution of Rev 29 to FBAR R Rev 17 to environ rept, per DO Eisenhut 810706 request.

 BRADLEY, E. J Philadelphia Electric Co 84/03/12 DENTON, H. R
 Office of Nuclear Reactor Regulation, Director 5pp 22643 270
 24X Fiche 50-352,84/03/12,8403150036
- G. Inspection reports, IE Bulletins & correspondence
- 8403010307 Forwards IE Insp Rept 50-352/84-02 on 840105-06. No yiolations observed.

 MARTIN, T T. Division of Engineering & Technical Programs, 84/02/16 KEMPER, J. S. Philadelphia Electric Co. 2pp. 22433 074 24X Fichs. 50-352. 84/02/16, 8403010307.
- --8403010314 IE Insp Rept 50-352/84-02 on 840105-04, No violations identified. Major areas inspected, chamistry & radioactive effluent control programs, KOTTAN, J, J., ZIBULSKY, H, PABCIAK, W J Region i, Office of Director 84/02/14, 4pp. 22433:076 24X Fiche: 50-352, 84/02/16, 8403010307.

- 8403070055 Responds to IE Bulletin 83-06, "Nonconforming Matla Supplied by Tube-Line Corp Facilities "Disposition of subj matl supplied by Guyon Alloys, Inc described Ten 6-inch 45 degree elbows & one 4-inch 8 R 90 degree elbow quarantined GALLACHER, J Philadelphia Electric Co 84/02/16 MURLEY, T E Region 1, Office of Director 100p 22576 051 24X Ficha 50-352,84/02/16,8403090055
- 8403070314 Forwards IE Insp Repts 50-352/84-01 & 50-353/84-02 on 840103-31 No violations noted STAROBIECKIR Division of Project & Resident Programs 84/02/22 KEMPER.J B Philadelphia Electric Co 4pp 22546 204 24% Ficha 50-352.84/02/22.8403070314
- ~-8403070319 IE Insp Repts 50-352/84-01 & 50-353/84-02 on 840103-31 No violations noted Major areas inspected followsp on previous insp findings.plant tour.followsp on IE bulletins & Nuclear Review Board Charter
 HIGGINS.J T , CHAUDHARY.8 K . CONNER.E L Region 1. Office of Director 84/02/17 16pp 22546 208 24X Fiche 50-352.84/02/22, 8403070314
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 840302034B Advises of consideration on use of plant-specific PRA & severe accident risk assessments (SARA) to assist NRC in evaluating sampling lnep program Requeste meeting in Mar 1984 to obtain insights from performing PRA & SARA STAROBIECKIR Division of Project & Resident Programs 84/02/28 KEMPER.J S Phisedelphia Electric Ca 2pp 22439 020 24X Fiche 50-352.84/02/28.840302034B
- 8403070276 Ack receipt of 831222 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-352/83-12
 Response not 1n accordance w/10CFR2 201 Add1 info requested MARTIN.T T Division of Engineering & Technical Progress 84/02/28 KEMPER.J B Philadeiphia Electric Co 2pp. 22546 302 24X Fichs 50-352.84/02/28.8403070276
- --8403070281 Responds to NRC 831122 ltr re violetione noted in IE insp Rept 50-352/83-12 Corrective ectione field inep of MCC power panel performed & resulte being evaluated Actions to prevent recurrence will be completed by 840301 KEMPER.J 8 Philadelphia Electric Co 83/12/22 MURLEY.T E Divleion of Engineering & Technical Progrems 3pp 22946 304 24X Fiche 50-352,84/02/28.840070276
- 8402090007 IE Info Notice 84-i4, "Highlighte of Recent Trensport Regulatory Revs by DOT & NRC " Svc list enci, GRACE, J N Division of GA, Safeguarde & Inspection Programs (Poet 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22532 329 24X Fiche 50-000,84/03/02,8402090007.
- 8402070008 IE Info Notice 84-14, "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list encl JORDAN; E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 078 24% Fiche 50-000,84/03/02,8402070008
- 8402070007 IE Info Notice 84-13, "Reporting of Rediological Releases" 8vc 11st encl JORDAN, E.L. Division of Emergency Preperedness & Engineering Reports (Poet 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 117pp 22553 217 24X Fiche 50-000,84/03/02,8402070007
- 8403160241 Forwards IE Insp Repts 50-352/84-03 & 50-353/84-01 on

 840109-10 & 12-13 No violations noted

 MARTIN.T T Division of Engineering & Technical Programs
 84/03/02

 KEMPER.J S Philadelphia Electric Co 2pp 22661 036. 24X

 Fiche 50-352.84/03/02.840316024i
- --8403160248 IE Insp Repts 50-352/84-03 & 50-353/84-01 on 840109-10 & 12-13 No violations noted, Mejor areas inspected preoperational radiological environ monitoring programings controls, program for GC for analystical measurements
 STRUCKNEYER, R. PASCIAK, H. J. Region 1, Office of Director, 84/02/23 5pp 22661 038 24% Fichs 50-352,84/03/02,8403160241
- 8402090011 IE Info Notice 84-17, "Probleme W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " 8vc list enci JURDAN E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/05. Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche 50-000.84/03/05, 8402090011

- 8402090024 IE Info Notice 84-07.Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking In PWR 8ys " 8vc list encl JORDAN.6 L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22384 186 24X Fichs 50-000,84/03/07,8402090028
- 8402090031 IE Builstin 84-02. "Failures of GE Type HFA Relsys in Uss in Class IE Safety Sys " Svc list encl DEYOUNO.R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidate Edison Co of New York, Inc 134pp 22823.094 24X Fichs 50-000.84/03/12.8402090031
- 8403290144 Forwards IE Insp Rept 50-352/84-08 on 840206-09, No violations noted MARTIN.T T Division of Engineering & Tschnical Programs 84/03/1 KEMPER.J S Philadeiphia Electric Co 2pp 22806 076 24X Fiche 50-352-84/03/13,8403290144
- --8403290150 IE Insp Rept 50-352/84-08 on 840206-09. No violations noted Major areas inspected onsite/Offsite safsty committee activity, operational staff training & fuel receipt & storage programs
 PRELL. J A . BISSETT.P , CLIVEIRA W. Region 1, Office of Director 84/03/07 Spp. 22806 098 24X Fichs 50-352, 84/03/15,8403290144
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unsuthorized Entries into PWR Reactor Cavities." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fichs 50-000.84/03/21, 8402090043
- 8402090044 IE Info Notics 84-20. "Bvc Life of Rsizys in Bafety-Rsizted Sys " Svc list enci
 JORDAN, E L Division of Emsrgency Prsparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp. 22933 001 24X Fiche 50-000.84/03/21.8402090044
- R. Periodic operating reports & related correspondence
- B403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite smergency planning issues
 DIRCKS.W J Office of the Executive Director for Operations 94/02/21 PALLADINO Commissioners 9pp 22492 083 24X Fiche 50-000.84/02/21.8403020443
- 8 Reportable occurrences, LERs & related correspondence
- 8403130084 Final Bignificant Deficiency Rept 127 re Agastat CR0075 relay socket failures Defective sockets replaced w/Agastat CR002 sockets correcting any adverse safety implications induced by socket failure KEMPER. J. 8 Philadelphia Electric Co. 84/02/17. MURLEY, T. E Region 1, Office of Director Spp. 22598:343 24% Fiche 50-352.84/02/17.8403130084.
- 8403260233 Forwards summary list of deficiencies identified per iOCFR5D 55(e).Part 21 & potential generic ltr repts for comments
 STAROSTECKI,R Division of Project & Resident Programs. 84/02/28 Region i. Dffice of Director 7pp 22756 065 24X Fichs 50-000.84/02/28.8400240233
- 8403270219 Part 2; rept re broken contact cerrier in control device of 7 5 kV-15 kV, 500-750 MVA; 5 kV 350-3, 000 & all HKV circuit breakers. Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.) 84/03/19 Record Services Branch (Document Control Desk). 5pp 22772 114 24% Fiche: 50-000; 84/03/19; 8403270219.
- T Hearing transcripts on non-antitrust matters
- 8403020129 Forwards revised testimony re ability of safety-related structures to withstand affects of postulated detonation resulting from assumed ruptures of Arco & Columbia gas transmission pipslines Related correspondence METTERHAHN, M J Conner & Hetterhahn, M HETTERHAHN, M J, Philadelphia Electric Co 84/02/29 BRENNER, L Atomic 8afety and Licensing Board Panel 2pp. 22442, i12. 24X Fiche: 50-352, 84/02/29, 8403020129

- --8403020136 Rsvised testimony of Philadelphia Electic Co re ability of safety-related structures to withstand effects of postulated detonation due to ruptures of transmission pipelines W/Certificate of Bvc Related correspondence * Philadelphia Electric Co 84/02/28 27pp 22442,114 24X Fiche 50-352,84/02/28,8403020129
- B4030B0235 Transcript of G40305 hearing in Philadelphia, PA Pp 7.565-7.496 * Commissioners 64/03/05 13ipp. 22556.306 24x Fiche 50-352,84/03/05,84030B0255.
- B403120092 Yranscript of B40306 hearing in Philadelphia, Pa. Pp 7,696-7,942
 Commissioners 84/03/06 246pp. 22588 249 24X
 Fichs 30-332,84/03/06,8403120092
- 8403120151 Transcript of 840307 hesring in Philadelphia, PA Pp 7, 943-8, 158 5 Atomic Safety and Licensing Board Pansi 84/03/07 216pp 22585 263 24X Fiche 50-332, 84/03/07, 8403120151
- 8403130040 Transcript of 840308 hesring in Philadsiphia, PA Pp 8, 159-8, 383. # Atomic Safety and Licensing Board Panel 84/03/09 268pp 22598 067 24% Fiche 50-352,84/03/08,8403130040
- 8403130113 Transcript of 840309 hearing in Philadeiphia, PA Pp 8,384-8,505 * About Safety and Licensing Board Panel 84/03/09 22pp 22601 001 24% Fiche 50-352,84/03/09,8403130113
- 8403220145 Transcript of 840319 hearing in Philadsiphia.PA Pp 8,506-8,647

 * Atomic Safsty and Licensing Board Panel. 84/03/19 150pp. 22714 142 24% Fiche 50-332,84/03/19,8403220145
- 8403260254 Transcript of 840320 hssring in Philadelphia, PA Pp 8.647-B.842 Supporting documentation encl Actual 8afety and Licensing Soard Pansi 84/03/20 202pp 82755 208 24X Fiche 50-332.84/03/20.8403260254
- 8403260015 Transcript of 840321 hearing in Philadelphia, PA Pp 8,843-9.059 Supporting documentation encl # Atomic Safety and Licensing Board Panel 84/03/21 283pp 22746-001, 24X Fiche 50-332,84/03/21,8403260015.
- 8403260334 Transcript of Commission 840321 affirmation/discussion & vote in Washington, DC re proposed order delegating authority to ASLB to hest Part 70 issues raised in Limsrick processding Pp i-3 = Commissioners 84/03/21 6pp 22775.281 24X Fichs 30-332.88/03/21.88403260334
- B403270042 Transmittal of testimony re Contention I-42, "Environ dualification of Electrical Equipment" Related Correspondence WETTERHAHN.M.J. Philadelphia Electric Co. WETTERHAHN.M.J. Conner & Wetterhahn DBD 120 B4/03/21 2pp 22769:242 24X Fichs 50-332,84/03/21,8403270042
- --8403270048 Testimony of WJ Boyst, DJ Thompson, DA Kline, L Stanley, EF Bproat, WH Boyers, TE Shannon & J Dosring rs Contention I-42, "Environ Qualification of Electrical Equipment" Certificate of Svc snc1 BDYER, W J : THOMPSON, D J : KLINE, D A Philadsiphia Electric Co 84/03/21 55pp 22769 244 24X Fiche 50-352,84/03/21,8403270042.
- B403270296 Testimony of A Masciantonio on Limerick Ecology Action Contention I-42 re electrical environ qualification. Related correspondence MASCIANTONIO: A Equipment Qualification Branch. DSB 138 B4/03/21. 10pp 22789-037. 24X Fiche: 50-352, B4/03/21, 8403270296
- 8403270171 Transcript of 840322 hearing in Philadelphia, PA Pp 9,060-9,266 * Atomic Safety and Licensing Board Panel. 84/03/22 210pp. 22773:150, 24X Fiche:50-352,84/03/22,8403270171.
- 8403270160 Transcript of 840323 hesring in Philadelphia,PA.Pp 9,267-9,401.
 # Atomic Safety and Licensing Board Panel. 84/03/23, 137pp. 22764-233. 24% Fiche 50-332,84/03/23,8403270160
- 8403300009 Memorandum serving transcript pages re 840323 prefiled testimony on Limerick Ecology Action Contention I-42 concerning environ qualification. Served on 840329 REENER; L. Atomic Safety and Licensing Board Panel DBB 209. 84/03/29 pp 22822 131 24X Fichs: 50-352,84/03/29,8403300009.

- --8403300014 Transcript Pp 9,270-9,274 of 840323 testimony on Limerick Ecology Action Contention I-42 ra environ qualification + Office of the Executive Lagal Director + Philadelphia Elactric Co + Limerick Ecology Action 84/03/27 5pp 22822 132 24X Fiche·50-352,84/03/27,8403300009
- DUCKET 50-353 LIMERICK GENERATING STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- E402070003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Foracast Panel meetings Forwards App A:B & C documents
 FELTON. J. M Division of Rules and Records. 83/10/31
 RDSENBAUM. D M Technical Analysis Corp 19pp 22193 292 24x
 Fiche: 50-000,83/10/31,8402090003
- --8402090183 Handwritten notes & calculations re const activities & fuel load preparation * NRC - No Datailed Affiliation Given 79/07/24 5pp 22195.057 24X Ficha 50-000,83/10/31,8402090003
- 8401240207 Forwards add1 info ra strass-assisted corrosion cracking of primary sys commants & potential main cooling tower failure modes & consequences. in response to ACRS 83/018 1tr KEMPER. J S. Philadalphia Elactric Co 84/01/18 SCHWENCER, A. Licensing Branch 2. 3pp 21908 148 24X Ficha 50-352.84/01/18, 8401240207
- --8401240211 "Rept on Effects of Postulated Failura of Cooling Towar "
 W/three oversize drawings Aperture cards are available in
 PDR.

 * Philadelphia Electric Co P-281/2 83/12/31 15pp
 21908 151 24X Fiche 50-352,84/01/18,8401240207
- 8403020104 Forwards magnatic tape containing hour by hour mateurological data for Oct 1983 Jan 1984, psr 831013 ltr. Data from primery meteorological tower & satallite tower & tape formats dascribad KEMPER.J S. Philadelphia Elactric Co 84/02/27 BCHWENCER.A Licensing Branch 2 Spp. 22443,240 24X Fiche 50-352,84/02/27,8403020104.
- 8403020237 Forwards application for amend to CPFR-106 & CPFR-107 (filed in Catagory A), Rev 17 to snviron rept OL stage (filed in Catagory C) & Rev 29 to FBAR (filed in Catagory K)

 BRADLEY, E J Philadelphia Electric Co. 84/02/29 DENTON, H. R. Office of Nuclear Reactor Regulation, Diractor 2pp 22493-026

 24X Ficha: 50-352, 84/02/29, 8403020257
- --8403020266 Application for smend to CPPR-106 & CPPR-107 Cartificate of Svc encl.

 KEMPER, J S. Philadelphia Electric Co 84/02/27 6pp 22495 028

 24X Fiche 50-352;84/02/27,8403020257
- 8403150262 Forwards request for add1 info re standby gas treatment sys Info needed to aveluate FBAR, Section 6 5, Ray 25 ECHMENCER, A Licensing Branch 2 84/02/29 BAUER, E, O Philadelphia Electric Co 4pp 22648 342, 24X Fich=: 50-352, 84/02/29, 8403150262
- B403160189 Notification of B40314,15 & 16 meetings w/util in Philadelphia:PA & Montgomery County:PA:respectively,to discuss NRC audit of environ qualification files & installed equipment.

 KINTNER, L. L. Licaneing Branch 1 84/03/03 SCHWENGER, A. Licensing Branch 2. 4pp. 22662,239, 24% Ficha 50-352:84/03/03,8403160189
- 8403150192 Advises of errors made in wind direction frequencies for CRAC2 calculation Ravised calculations for severe accident risk assessment expected to change pradicted latent cancer fatalities.

 KEMPER, J B. Philadelphia Elactric Co. 84/03/13 ECHMENGER.A. Liceneing Branch 2. 2pp. 22655 244 24X Fiche 50-352,84/03/13,8403160192.
- 8403170197 Forwards Rev C to Anchor/Darling Valve Co Drawing 93-14182, correspondence re HPCI.RCIC & reactor water cleenup containment isolation valve closure capabilities & Rev 23 co Mati Requisition 8031-P-104, per 840202 telcon.

 KEMPER. J. B. Philadelphia Electric Co. 84/03/13 BCHWENCER, A Licensing Branch 2, 134pp. 22670,001. 24% Fiche 50-352,84/03/13,8403190197
- 8402090041 Board Notification 84-050.provides Commission policy statement & proposed rulemaking on environ qualifications EIBENHUT, D. 0 Division of Licensing. 84/03/14. Atomic Sefety and Licensing Board Panel. 10pp. 24X Fiche.50-000.84/03/14.8402090041

- C Utility Environmental Report (ER), amends & correspondence
- 8403020257 Forwards Rev 17 to anviron rept CL stage HRADLEY.E J Philadsiphia Electric Co 84/02/29 DENTON.H R Offica of Nuclear Reactor Regulation. Director 2pp 22495 026 24X Fiche 50-332.84/02/27.8403020257
- --8403020270 Rev 17 to environ rept OL stage * Philadelphia Electric Co 84/02/29 20pp 22495 034 24X Fiche 50-332,84/02/29,8403020257
- B403150036 Forwards Affidavlt of Svc rs distribution of Rsv 29 to FSAR & Rev 17 to environ rapt.per DG Eisenhut 810706 request.

 BRADLEY.E J Philadslphia Elactric Co 84/03/12 DENTON,H R
 Office of Nuclear Reactor Ragulation, Director 5pp 22643 290
 24X Fiche 50-352:84/03/12:8403150036
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8403160026 Notifies that Natl Ctr for Devices & Radiological Health has no commant re postulated plent accidents described in DEB (NURGE-0974)

 VILLFORTH, J C Fond & Drug Administration, 84/02/10 SCHWENCER, A Licansing Branch 2 1p 22654 346 24X Fiche: 50-352, 84/02/10, 8403160026
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403010144 Forwards draft FPER pages containing Info to close SER Open Issua 15 re slectrical cable cable tray & fire areas having high concentrations of cables info in draft FPER will be incorporated into Rev 5 scheduled for Mar 1984 BOYER V 8 Philadelphia Electric Co 84/02/16 SCHMENCER, A Licensing Branch 2 9pp 22435 313 24X Fiche: 50-352: 84/02/16, 8403010144
- B403050161 Forwards "Structural Steel Survivability Evaluation," In response to B40209 request for addl info (RAI 280 26), par SER Open Item 14 KEMPER, J S Philadsiphia Electric Co 84/02/29 SCHMENCER, A Licensing Branch 2 Spp 22483 037 24X Fiche 50-352,84/02/29,84030016)
- 8403260249 Forwerds "UHS Extreme Hind Hazard Analysis," in response to B30808 ltr re BSER Open Issue 2

 KEMPER, J 8 Philadeiphia Electric Co 84/03/22 BCHWENGER, A Licensing Branch 2 2pp 22755 001 24X Fiche 50-352,84/03/22,84/03/247
- --8403260253 "UMB Extreme Wind Hazard Analysis " BITOMF.T B., PARRY.O W NUB Corp. NUS-4507 84/03/31 134pp 22755 004 24X Ficha 50-352.84/03/22.8403280249
- F. Becurity, medical, emergency & fire protection plans
- 8403070361 Public vsrsion of revised smargency plan implementing procedures, including Procedure EP-201 rs technical support ctr activation, EP-210 ra dose assessment team & EP-222 re fisid survey group W/831212, 840215 ltrs & 840302 msmo DALTROFF, 8 L Philadelphia Electric Co 83/11/30 MURLEY, T E Region 1, Office of Director 8CHMENCER, A Licensing Brench 2 165pp. 22566 061 24X Fichs 30-352,83/11/30,8403070361
- 8403090270 Public version of Rev O to emergency plan implementing procedures, including Procedure EP-110 re personnel assembly, EP-221 ra personnel dosinetry & EP-208 re security team activation W/831212 it & JM Felton release memo DALTROFF, S L Philadeiphia Electric Co 83/11/30 BCHMENCER, A Licensing Branch 2. BOpp. 22592 062 24X Fiche. 50-352, 83/11/30, 8403070270
- B403010144 Forwards draft FPER pages containing info to closs BER Open Issue 15 re alectrical cable & cable tray & fire areas having high concentrations of cables Info in draft FPER will be incorporated into Rev 5 scheduled for Mar 1784 BDYER, V 8 Philadelphia Electric Go 84/02/16 SCHMENCER, A Licensing Branch 2 9pp 22435 313 24x Fiche 50-352,84/02/16,8403010144
- 8402070006 Board Notification 84-034 forwards R Vollmsr 840206 memo to D Eissehut rs fira research results concerning fires in electrical cabinets in control room EISENHUT.D Q. Division of Licensing. 84/02/23 PALLADINO Commissioners, ip. 22576'203 24X Fichs 50-000,84/02/23,8402090066

- --B403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRR Ofc Ltr 19, dtd 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering B4/02/06 EISENHUT, D 9 Division of Litensing 10pp 22576 204 24% Fiche 50-000.84/02/23,8402090006
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl MURLEY.T E Region 1. Office of Director 84/03/09 O'TOOLE.J D Consolidated Edison Co of New York. Inc FIEDLER.P B General Public Utilities OPU Service Corp 35pp 22672 062 24X Fiche 50-000.84/03/09.8403190243
- 8403210028 Forwards response to NRC 840306 & 08 requests for add1 info re smorgency action levels, specifically, containment radiation levels Draft changes to emergency plan will be incorporated as stated in enc! DALTROFF, S.L. Philadelphia Electric Co. 84/03/16 SCHMENCER, A Licensing Branch 2 80pp 22708 255 24% Fiche 50-352.84/03/16, 8403210028

O Adjudicatory correspondence

- 840301027i Forwards reply to applicant & staff response to City of Philadelphia issues SMDLEN.H Philadelphia PA 84/02/28 Docketing & Services Branch ip 22432 207 24X Fiche 50-352.84/02/28.8403010271
- ---8403010275 Reply to applicant & staff responses to City of Philedelphie issues re emergency response plan State plan does not contain & is not based upon standardized protective action guidance for exposure from feedstuffs & water SMDLEN.H Philadelphia. PA 84/02/28 Atomic Safety and Licensing Board Panel 43pp 22432 208 24X Fiche 50-352,84/02/28,8403010271
- 8403020099 Forwards answer to City of Philadelphia interrogatories on sue interaction, designated Discovery 28 W/esception of three listed documents, documentery meth responsive to request will be made available for insp Related correspondence WETTERHAHN, M J. Conner & Wetterhahn B4/02/29 BUSH, M W Philadelphia, PA App. 22443 048 24X Fiche 50-352,84/02/29, 8403020099
- --8403020105 Answers City of Philadelphia interrogetories on sye interaction contention Certificate of Svc encl Releted correspondence
 DOYER.V S Philadelphia Electric Co 84/02/27 65pp 22443 054 24X Fiche 50-352,84/02/29,8403020099
- 8403020125 Transmittal of matl supporting applicant 840228 revised testimony re ability of safety-related structures to withetand effects of postulated detonation from pipeline ruptures Certificate of Svc encl Related correspondence WETTERMARN.M J Philadelphia Electric Co WETTERMARN.M J Conner & Hetterhahn 84/02/29 4pp 22442 143 24% Fiche 50-352,84/02/29,8403020125
- 8403020163 Response apposing new contention proposed by Air & Water Pollution Patrol re discharge of asbestoe fibers Contention lacks basis & specificity required by 10CFR2 714(b) Cartificate of 8vc encl WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 84/02/29 Atomic Safety and Licensing Board Penel 11pp 22442 006 24X Fiche 50-352.84/02/29.8403020163
- 8403060129 Forwards Certificate of Bvc for raply to applicant & staff rasponses to City of Philadelphia issues
 SMOLEN.H Philadelphia. PA B4/02/29 Docketing & Services
 Branch Spp 22506 327 24% Ficha 50-352; B4/02/29, B4/03/2060129
- 8403060081 Response opposing Friends of the Eerth 840224 motion to strike applicant & staff structural enalysis testimony Notion fails to establish testimony as unreliable Cartificate of Bvc ancl.Related correspondence METTERHANNM Philadelphia Electric Co METTERHANN, M Conner & Hetterhahn 84/03/01 Atomic Bafety and Liceneing Board Panel, 6pp. 22516 339 24X Fiche 50-352, 84/03/01, 84030600091
- 8403050248 Answer to new contentions proposed by Friends of the Earth on onsite storage of unirradiated fuel & transmittel of related correspondence Proposed late contentions should be denied Certificate of Svc encl WETTERHANN.H J Philadelphia Electric Co WETTERHANN.H J Conner & Wetterhahn 84/03/01 Atomic Safety and Licensing Board Panel 33pp 22517 079 24X Fiche 50-352,84/03/01.8403060248

- B403140118 Forwards cross-examination plans for etructural analysis heering on blast overpressures.psr ABLB B40120 order W/o enc!
 VIOLER, B H Hearing Branch 2 B4/03/01 BRENNER, L , COLE, R F , MORRIS, P A Atomic Bafety and Licensing Board Penel 2pp 22623 33B 24x Fiche 50-352; B4/03/01, B403140118
- 8403060097 Memorandum & order denying intervenor Lewis 831224 motions based on newly received info Lewis discovery rights not abridged per Contention I-62 W/Certificate of Bvc BRENNER, L., COLE, R. F., MORRIS, P. A. Atomic Bafety and Licensing Board Pamel 84/03/02 Lewis, M. 11pp 22506.262 24X Fiche 50-352.84/03/02,8403060097
- 8403070142 Response opposing Air & Heter Pollution Patrol 840221 request for extension of discovery period for Contention VI-1 Cartificate of Bvc encl Related correspondence WETTERHAHNM J Philadelphia Electric Co WETTERHAHNM J Conner & Wetterhahn 84/03/02 Air and Hater Pollution Patrol 7pp 22538 271 24% Fiche 50-352,84/03/02,8403070142
- 8403070236 Response to Air & Water Pollution Patrol motion to compel discovery Applicant denies that answer to interrogatory evactive Related correspondence WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhehn 84/03/02 Atomic 8efety and Liceneing Board Panel 3pp 22536 217 24X Fiche 50-352,84/03/02,8403070236
- --8403070238 Response opposing Air & Water Pollution Patrol request for depositione of Contention VI-1 No reason given why depositione necessery W/Certificate of Syc HETIERHAHN.M J Philadelphia Electric Co HETYERHAHN.M J Conner & Wetterhehn. 84/03/02 Atomic Safety and Licensing Board Penel 6pp 22536 221 24X Fiche 50-352.84/03/02,8403070236
- 8403140085 Response opposing Friends of the Earth 840223 application to file contention based on new metter refuel storage Certificate of Bvc encl MILCOVE. M N. Hearing Branch 2 84/03/02 Atomic Safety and Licensing Board Panel 14pp 22633 235 24X Fiche, 50-352, 84/03/02, 8403140085
- 8403140115 Response to Limerick Ecology Action & City of Philadelphia contentions filed on 840214 re environ assessment of severe accidents as set forth in DES. Suppl 1 Certificete of Byc encl VOOLER, B H . HODODON, A P Hearing Branch 2 84/03/03 Atomic Bafety and Licensing Board Panel 17pp 22623 340 24X Fiche 50-352.84/03/03,8403140115
- B403120001 Notice of withdrawel of offsite emergency planning issue re evecuation time estimate study Applicent B40224 representation addresses issues W/Certificate of Svc FERKIN, Z Q Pennsylvenia, Commonyealth of, B4/03/05 3pp 22588 036 24X Fiche 50-352: B4/03/05.8403120001
- B403140105 Response opposing Air & Weter Pollution Patrol (AWPP) 840215 motion filing new info contention AWPP fails to meet stde for laterfiled contentions Certificate of Buc ent WRIGHT.N A Heering Branch 2 84/03/05 Atomic Safety end Licensing Board Panel 8pp 22623 330 24X Fiche 50-352,84/03/05,8403140105
- 8403130411 Forwards notice of change of address & firm name Certificate of Svc enc1 8U0ARMAN:R J Bugarman & Denworth SU0ARMAN:R J Del-Aware Unlimited, Inc. 84/03/07 Docketing & Services Branch 6pp 22616:319 24X Fiche 50-352,84/03/07,8403130411.
- 8403140110 Findings of Pect & conclusions of law in form of partial initial decision on Air & Weter Pollution Patrol Contention V-4 re carburetor icing Certificate of Bvc encl HODGODON.A F Hearing Branch 2 84/03/07 25pp 22624.075 24X Fiche, 50-352, 84/03/07, 8403140110
- 8403130024 Reply findings of fact & conclusions of law re Contention V-4 in response to Air & Weter Pollution Patrol (AMPP) 840224 proposed findings AWPP findings should be rejected Certificate of Byc encl WETTERHAHNM J , NICHOLS, N. N. Philadelphia Electric Co. WETTERHAHNM J Conner & Wetterhahn 84/03/12 9pp 22641:282 24X Fiche 50-352,84/03/12,8403150024
- B403190007 Responses to util interrogatories on Contention 1-42 Ceptificate of Svc encl.Releted correspondence # Philadelphia, PA 84/03/12 Philadelphia Electric Co. 15pp 22665.337 24x Fichs 50-352,84/03/12,8403190007

- 8403160010 Forwards affidavit of LB Pyrih & PS Stansbury re hypothetical accidents involving unirradiated fuel to be stored at plant No credible potential for violating regulations identified Related correspondence WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn, 84/03/19 1p 22662 164 24X Fiche 50-352, 84/03/13, 8403160010
- --B403i60187 Affidavit of LB Pyrih re storage of unirradiated fuel No potential for violating provisions of iOCFR20 as result of credible accidents affecting new fuel assemblies stored at plant Certificate of Svc encl
 PYRIN.L B Philadelphia Electric Co 84/03/13 22pp 22662 165
 24X Fiche 50-352,84/03/13,8403160010
- --8403160188 Affidavit of PS Stansbury re calculation of exposure rates in various assumed configurations of specified quantities of U enriched to 1 85% in isotope U-235 STANSBURY, P. B. General Electric Co. 84/03/12 9pp 22662 186 24% Fiche. 50-352, 84/03/13, 8403160010
- 8403190132 Appeal opposing dismissal of Anthony/Friends of the Earth contention on util application to store nuclear fuel outdoors & ASLB denial of immediate stay on moving fuel ANTHONY.R L. Anthony. R L. ANTHONY.R L. Friends of the Earth 84/03/13 Atomic Safety and Licensing Appeal Panel ip 22686 308 24% Fiche 50-352.84/03/13.8403190132
- --840319013B Application to file contention re util application to store fual optdoors Fual storage is hazard to community due to question of whether bldgs can withstand overpressures & impacts from offsite accidents
 ANTHONY,R.L. Anthony, R.L. ANTHONY,R.L. Friends of the Earth B4/02/23. Atomic Bafety and Licensing Board Panel ip 22666:307 24X Fiche:50-352,84/03/13,8403190132
- --8403190142 Addition to application for contention re util application to move & store 764 bundles of fuel Util plans to move highly dangerous fuel onto sita in Mar 1984 & store fuel in especially vulnerable location for 4 months
 ANTHONY.R L Anthony.R L Anthony.R L Friends of the Earth 84/02/28 Atomic Bafety and Licensing Board Panel 2pp. 22666 308 24X Fiche 50-353,84/03/13,8403190132
- 8403190160 Affidavit of N Ketrlach re possibility of radiological releases from fuel assemblies in shipping containers in violation of NRC regulations, Certificate of Svc encl KETZLACH.N Upanium Fuel Licensing Branch. 84/03/13 5pp 22668.358 24X Ficher 50~352,84/03/13,8403190160.
- 8403190173 Forwards ND Romney 840313 memo to G Lear re results of 840306 conference call from applicant VOOLER, B H Hearing Branch 2 84/03/13 BRENNER, L. MORRIS, P A. COLE, R. F. Atomic Sefety and Licensing Board Panel 4pp 22671 158 24X Fiche. 50-352, 84/03/13, 8403190173
- BA03200090 Forwards BA0313 ltr documenting discovery of errors in predicted consequences reported in severe accident risk assessment Consideration of admissibility of contentions should proceed as scheduled Related correspondence HETTERHAHN.M J Conner & Wetterhahn WETTERHAHN.M J Philadelphia Electric Co B4/03/13, BRENNER.L . MORRIB.P A . COLE.R F Atomic Bafety and Licensing Board Panel 3pp 22685 278 24X Fliche 50-352.84/03/13.8403200090
- 8403200144 Forwards listed add1 info re HPCI isolation valves, per NRC Equipment Qualification Branch 840202 telcon request W/o encl. Related correspondence KEMPER, J. 8. Philadalphia Electric Co 84/03/13 SCHWENCER, A Licensing Branch 2 2pp. 22699:159. 24X Fiche: 50-352,84/03/13, 6403200144.
- 840319003B Motion for new contention based on IE Notice 84-17 re problems w/liquid nitrogen cooling components below nil ductflitty temp Facility design deficient because liquid nitrogen can cool vital components below temp LEMIS, M. Lewis, M. 84/03/14 Atomic Bafety and Licensing Board Panel. 4pp. 22666.235 24X Ficher 50-352,84/03/14,8403190038
- 8403190040 Order directing parties to hold settlement conferences for onsite emargency planning contentions Courtesy notification encl.

 BREINNER, L. Atomic Safety and Licensing Board Panel 84/03/15 Office of the Executive Legal Director. 5pp. 22666.240 24X Fiche.30-352,84/03/15,8403190040
- 8403190140 Supplemental info on Limerick Ecology Action offsite emergency planning Contentions 3,4;13,17,20 & 28 requested at pre-hearing conference Certificate of Svc encl. ELimerick Ecology Action 84/03/15 Atomic Bafety and Licensing Board Panel 34pp 22666:316 24X Fiche, 50-352, 84/03/15, 8403190140

- 8403190153 Order confirming miscellaneous oral rulings made at hearing held during wk of 840305 Testimony & hearing schedules listed Courtesy notification encl BRENNER.L Atomic Safety and Licensing Board Panel 84/03/15 Office of the Executive Legal Director 8pp 22668 346 24X Fiche 50-352.84/03/15-8403190183
- 8403200015 Forwards revised radiological emergency response plan for Pennhurst Mental Retardation Ctr to ABLB, intervenors & City of Philadelphia W/o encl Related correspondence BELSER, A L Pennsylvania, Commonwealth of, 84/03/13 BRENNER, L, MORRIS, P A, COLE, F Atomic Safety and Licensing Board Panel 2pp 22698 344 24X Fichs 30-392,84/03/15,8403200015
- 8403200060 Forwards "Protective Order on SNM Security Plan Info" &
 "Affidavit of Non-Disclosure" restorage of irradiated fuel
 Certificate of Evc encl Related correspondence
 WETTERHAHM, M J Conner & Wetterhahn WETTERHAHM, M J Philadelphia
 Electric Co 84/03/16 BRENNER, L, COLE, R F, MORRIS, P A Atomic
 Safety and Licensing Board Panel 14pp 22684 342 24X
 Fiche 50-352,84/03/16,8403200060
- 8403200070 Memorandum & order on Friends of the Earth contentions & Limerick Ecology Action petition re Part 70 application to store new fuel BRENNER.L., MORRIB,P A Atomic Safety and Licensing Board Panel 84/03/16 30pp 22685 104 24X Fiche 50-352,84/03/16,8403200070
- 8403200110 Requests that encl AB Joffe 840311 ltr re assestos piping be served to parties in proceeding LANE.V M Atomic Safety and Licensing Board Panel 84/03/16 CLEMENTS.W L Office of the Secretary of the Commission 2pp 22699 043 24x Fiche 50-332.84/03/16.8403200110
- 8403210067 Forwards Commission statement of policy ra challenge to elimination of financial qualification review requirements Related correspondence HRIGHT,N A Hearing Branch 2 84/03/16 BRENNER.L., MORRIS,P A., COLE.R F. Atomic Safety and Licensing Board Panel 4pp. 22705 052 24X Fiche 50-382.84/03/16.8403210067
- 8403210076 Forwards Transportation Certification Branch 840312 memo & Certificate of Compliance mentioned in 840313 affidavit of N Kettlach Ralated correspondence WRIGHT,N A Hearing Branch 2 84/03/16 BRENNER,L, MORRIS,P A, COLE,R F Atomic Bafety and Licensing Board Panel 7pp 22706 001 24X Fiche 30-352,84/03/16,8403210076
- 8403210128 Forwards Delaware River Basin Commission Aug 1780 final environ assessment for Neshaminy Water Bupply 8ys & 800825 negative declaration, per ABLAB 840315 telcon request W/o encl Related correspondenca HDD9DON.AP Hearing Branch 2 84/03/16 KOHL.CN, EDLEB,OJ. ODTCHY.R.L Atomic Bafety and Licensing Board Panel 2pp 22707 262 24X Fiche 50-352.84/03/16.8403210128
- 8403280354 Memorandum & order on Friends of the Earth contentions & Limerick Ecology Action pacition based on IOCFR70 application to store new fuel Berved on 840327 BRENNER.L. MORRIS.P A Atomic Bafety and Licensing Board Panel DBB 147 84/03/16 Friends of the Earth. JOpp 22787 174 24X Fiche: 50-352.84/03/16.8403280354
- 8403210092 Answer to Limerick Ecology Action (LEA) supplemental info on LEA offsite amergency planning contentions Proposed contentions should be denied Certificate of Byc encl CONNER.T B Philadelphia Electric Co CONNER.T B Conner & Wetterhahn 84/03/19 17pp 22705:322 24X Fiche 50-352,84/03/19.8403210092
- B403210103 Motion to delete specific instances in support of Contention VI-1 advanced by Air & Watar Pollution Patrol as unrelated to welding or welding GA activities Certificate of Svc encl. WETTERHAHN.M J Philadelphia Electric Co WETTERHAHN.M.J Conner & Wetterhahn B4/03/19 Atomic Bafety and Licensing Board Panel 10pp 22706 iiB 24% Fiche 50-352,84/03/19,8403210103
- 8403210167 Forwards Commission "Btatement of Policy on Environ Gualification" & proposed rule: "Environ Gualification of Electric Equipment:Removal of 820630 Deadline." Related correspondence
 HODODON:A P. Hearing Branch 2 DBB 017 B4/03/19 BRENNER, L., COLE, R. F., MORRIS, P. A. Atomic Safety and Licensing Board Panel ilpp. 22710 133 24X Fiche 50-352-84/03/19,8403210167
- 8403220226 Forwards request for reconsideration of assestos contention & motion requiring further depositions re Contention VI-I ROMANO, F.R. Air and Water Pollution Patrol DSB 046 84/03/19 SRENNER: L, MORRIS, P. COLE, R. Atomic Safety and Licensing Board Panel ip 22719 007 24X Fiche, 50-352,84/03/19,8403220226

- --8403220229 Request for reconsideration of asbestos contention Board 41d not adequately address hazard to public ROMAND.FR Air and Water Pollution Patrol 84/03/19 BRENNER, L. HORRIS.P. COLE.R. Atomic Safety and Licensing Board Panel 2pp 22719 008 24X Fiche 50-352.84/03/19.8403220226
- --8403220234 Motion to require further depositions re Contention VI-I concerning 760601 brockstick deficient welding effair ROMAND.F Air and Mater Poliution Patroi 84/03/19 BREWNER.L., COLE.R Akoaic Safety and Licensing Board Panel 2pp 22719 010 24X fiche 50-352,84/03/19,8403220226
- 8403270065 Protective order on SNM security plan info Served on 840326 BRENNER.L Atomic Sefety and Licensing Board Panel DSB 123 84/03/19 Limerick Ecology Action 3pp 22766 149 24X Fishe 50-352.84/03/19,8403270065
- --8403270069 Affidevit on mondisciosure for CW Eiliott ELLIOTT.C W Limerict Ecology Action 84/03/16 4pp 22766 152 24X Fiche 50-352/84/03/19/8403270065
- 8403290379 Request for reconsideration of Air & Water Poilution Patrol assestos contention
 ROMANO,F R Air and Water Poliution Patrol DSB 186 84/03/19
 Atomic Safety and Licensing Board Panel 2pp 22814 142 24X
 Fichm 50-352,84/03/19,8403290378
- 8403270017 Supplemental responses to info requests of City of Philadelphia Related correspondence BOYER.V S Philadelphia Electric Co DSS 112 84/03/21 12pp 22770:056 24X Fiche 50-352,84/03/21,8403270017
- 8403280336 Forwards complaint of util vs South Coventry Township flied on 840309 memorandum of lew in opposition to petition for Preliaminary injunction 84-01645 & order of court dissolving injunction egainst Township Related correspondence IITZER:P Limerick Ecology Action DSB 145 84/03/21 BRENNER, L. MORRIES-P A. COLE:RF A towalc Sefety end Licensing Board Panel 32pp 22787 065 24X Fiche 50-352-84/03/21,8403280336
- 8403230005 Order delegating authority to exercise review functions over Part 70 issues raised in proceeding to Appeal Board Served on 84032 CHILK-5 J Office of the Secretary of the Commission DSB 070 84/03/22 Atomic Sefety and Licensing Appeal Panel 2pp 22726 339 24x Fichs 50-332.84/03/22.8403230005
- 8403230278 Order confirming briefing schedule for Friends of the Earth appeal of ASLB 840316 memorendum & order & for staff to provide Part 70 application SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel D8B 077 84/03/22 Office of the Erecutive Legal Director 2pp 22743 094 24X Fiche 50-352.84/03/22.8403230278
- 8403260333 Forwards supplemental correspondence & documents re smargancy planning Math supplemental litrs & covers period 8408266-0315 M/o encla Related correspondence BRADLEY,E J Philadelphia Electric Co DSB 098 84/03/22 ZITZER,P Limerick Ecology Action 2pp 22760 162 24X Fiche. 50-352,84/03/22,8403260333
- 8403270012 Informs that applicent will suppl 840217 responses to info Requests 6.7.il & 12 Related correspondence WETTERHAMN J Conner & Wetterhehn METTERHAMN, M J Philedelphia Electric Co DSB 109 84/03/22 BUSH, M W Philedelphie, PA 2pp 22749:356 24X Fiche 50-352,84/03/22,8403270012
- 8403270301 Informs that monthly repts for Nov 1983 Feb 1984 re Contract NGC-03-83-092 being eart by express mail Related correspondence RUTBERO.J Heering Branch 2 DSB 135 84/03/22 ELLIOTT.C W Brose & Poswietiilo 2pp 22789 032 24X Fiche 50-352.84/03/22. 8403270301
- 8403280353 Forwards rept. "UHS Extreme Wine Hazerd Analysis " M/o enci Related correspondence KEMPER.J S Philadelphia Electric Co DB8 160 84/03/22 SCHWENCER.A Licensing Branch 2 1p 22787 173 24X Fiche 50-352,84/03/22,8403280353
- 8403260349 Motion to dismiss perticular onsite emergency planning contentions for which discovery not provided or no litigable basis shown Certificate of Svc encl CONNER.T 8 Philadeighia Electric Co CONNER.T 8 Conner & Wetterhahn DSB 094. 84/03/23 Atomic Safety and Licensing Board Panel. 16pp 22760,243 24x Ficher 50-332,84/03/23,8403260349
- 8403300122 Response to Limerick Ecology Action (LEA) supplemental info on LEA offsite emergency planning contentions Certificate of Svc encl FERKIN, Z 9 Pennsylvania, Commonwealth of, DSB 203 84/03/23 7pp 22820 303 24X Fiche 50-352,84/03/23,8403300122

- 8403290395 Forwards response to applicant motion to delate specific instances in support of Contention VI-I as unrelated to weiding or welding-related GA activities Certificate of Syc encl ROMAND, FR Air and Weter Pollution Petrol DSB 201 84/03/25. Atomic Safety and Licensing Board Panel ip 22814 326, 24% Fiche 50-352,84/03/25,8403290395
- --8403270397 Response to applicant motion to delete specific instances in support of Contention VI-I advanced by Air & Water Poliution Patrol as unrelated to Welding or welding-related GA activities.

 ROMANDUF R Air and Weter Pollution Patrol 84/03/24 Atomic Sefety and Licensing Board Panel 11pp 22814 327 24X Fiche 50-352,84/03/23,8403290395
- 8403270027 Natice of ABLB constitution L Brenner, chairman & RF Cole & PA Morris, members Served on 840326 COTTER, BP Atomic Bafety and Licensing Board Panel. DBB 125. 84/03/26 2pp 22769 339 24X Fiche 50-352,84/03/26,8403270027.
- 84032700&0 Stipulation re atorage of unirradiated fuel METTERHAHN, M. J. Philadelphia Electric Co. ELLIOTT, C. W. Limerick Ecology Action DSB 122 84/03/26 2pp 2276& 162 24X Fichs 50-352.84/03/26.84032700&0
- 8403280331 Memorandum & order confirming 840321 oral ruiing on affidavite re radiation releases from unirradiated new fuel rods Served on 840327 BRENNER, L. Atomic 8efety and Licensing Board Panel DSB 148 84/03/26 Office of the Executive Legal Director 2pp 22787 049 24X Fichs 50-352,84/03/26.8403280331
- 8403280337 Order imposing temporary stay of ABLB 840316 memorandum k order pending receipt of Friends of the Earth appeal of order Served on 840328 SHCEMAKERC J Atomic Safety and Licensing Appeal Panel, DSB 161, 84/03/27 2pp 22787 227 24X Fiche 50-352,84/03/27,8403260359
- 8403300129 Joint rept on status of negotiations re onsite emergency planning contentions & Limerick Ecology Action dismissal of particular contentions Cartificate of Bvc encl RADER,R M Philadelphia Electric Co RADER,R M. Conner & Wetterhahn ELLIOTT.C W Limerick Ecology Action. DBB 206, 84/03/27 6pp 22820 008 24X Fiche 50-352,84/03/27,8403300129
- 8403300271 Forwards GA endits re Colt Industries Fairbanks Morse Engine Div, diesel generators W/o enci, Related correspondence WETTERHAMN, M J. Philadelphia Electric Co. WETTERHAMN, M J. Conner & Metterhahn DSB 212 84/03/27 3pp 22824 037 24X Fiche 50-352,84/03/27,840330027i
- ---B403300274 Response to Air & Water Poilution Patrol (AWPP) B40319 motion to require further depositions re Contention VI-1 AWPP failed to support request for relief & motion should be denied W/Certificate of Svc Related correspondence WETTERHANN-M J Philadelphia Electric Co. WETTERHANN-M J. Affiliation Not Assigned 84/03/27 Atomic Bafety and Licensing Board Panel 7pp. 22824 040. 24X Fichs: 50-352,84/03/27,8403300271
- 8403290374 Forwards portions of transcripts re ABLB 840320 ruling on admissibility of Limerick Ecology Action contentions & City of Philadelphia issues on facility DEB, Suppl 1 Related correspondence
 HD00D0N:AP Heering Branch 2 DBB 199 84/03/ZB, ELLIDYT, C W. Bross & Poswistillo BUBH:H W. Bush: M W FERKIN, Z Q Pennsylvania, Commonwealth of:
 Fiche 50-352:84/03/28,8403270374
- B403270384 Brief in opposition to intervenor Friends of the Earth for stey of oneite storage of unirradiated fuel. Stay request fails to demonstrate any conceivable herm as result of fuel storage Ceptificate of Svc encl.

 HETTERHANN.M J Philadelphia Electric Co. HETTERHANN.M J. Conner & Hetterhahn DBB 170 84/03/28 11pp 22814.240 24X

 Fiche 30-352,84/03/28,8403270384
- 8403290393 Hemorandum & order confirming denial of Air & Water Pollution Patrol motion for further dispositions re Contention VI-i Certificate of Buc encl BRENNER. L Atomic Sefety and Licensing Board Panel. DSB 187. 8403290393 4pp 22814 322 24X Fiche 50-352,84/03/28,8403290393.
- 8403290399 Forwards staff 840320 response to Limerick Ecology Action supplementary info VOCLER, 8 H Hearing Branch 2. DSB 200 84/03/28 BRENNER, L., MORRIS, P. A., COLE, R. F. Atomic Safety and Licensing Board Panel. 2pp 22814 338 24X Fiche. 50-352,84/03/28,8403290399

- --B403290400 Responsa to Limerick Ecology Action 840313 supplementary info on offsite emargancy planning contantions Staff position ramains unchanged Cartificate of Svc encl VOLER,8 H Hearing Branch 2 84/03/20 2pp 22814 340 24X Ficha 50-352,84/03/28,8403270379
- 8403300127 Transmittal of rafs & arrata to applicant 840321 tastimony of MJ Boyer.DJ Thompson.DA Kline,L Stanley.EF Sproat, MM Bowars.TE Shannon & J Poaring on Contantion I-42 Related correspondence WETTERHAHN.M J Philadalphia Electric Co WETTERHAHN,M J Conner & Wetterhahn DSB 204 84/03/28 7pp 22820 245 24X Ficha.50-352.84/03/28,8403300127
- 8403300128 Response opposing M Lewis 840314 motion for new contention based on IE Info Notice 84-17 cooling of vital components by liquid nitrogen, Cartificate of 8vc ancl WETTERHAHN.M J. Philadelphia Elactric Co. WETTERHAHN.M J. Conner & Wetterhahn DSB 205 84/03/28 Atomic Safety and Licensing Soard Panel. 12pp 22820.271 24X Fiche 50-352.84/03/28,8403300128
- 8403300287 Forwards PH Parary 840315 ltm re questions concerning fission products Ltm should be forwarded to appropriate NRC individual for response & response served in proceeding Berved on 840330.

 LANE, V.M. Atomic Befety and Licensing Board Panal DBB 218 84703/29, VOGLER, B.H. Hearing Branch 2, 2pp 22824 016, 24X Ficha: 50-352,84/03/29,8403300287
- K. Utility Final Safaty Analysis Report (FBAR) & amands
- 8403020257 Forwards Rav 29 to FSAR. BRADLEY.E J Philadelphia Electric Co 84/02/29 DENTON.H R. Office of Nuclear Raector Ragulation, Director 2pp 22495 026 24X Fiche: 50-352, 84/02/29, 8403020257
- --8403020273 Rav 29 to FBAR.

 * Philadelphia Electric Co 84/02/29 538pp 22495:056 24X
 Ficha. 50-352,84/02/29,8403020257
- 8403150036 Forwards Affidavit of Bvc re distribution of Rav 29 to FSAR & Rev 17 to anviron rept, par DQ Eisenhut 810706 raquest.

 BRADLEY, E. J. Philadelphia Electric Co 84/03/12 DENTON, M R Office of Nuclear Reactor Regulation, Diractor. 5pp 22643.290 24X Fiche: 50-352.84/03/12,8403150036
- Q. Inspection reports: IE Builatins & correspondance
- 8403070055 Rasponds to IE Bullatin B3-06, "Nonconforming Matls Bupplied by Tube-Line Corp Facilities. ," Disposition of subj matl supplied by Ouyon Alloys, Inc described Tan 6-inch 45 degree albows & ona 4-inch 8 R. 70 degree albow quarantinad OALLAOHER. J Philadelphia Elactric Co. 84/02/16 MURLEY.T E Region 1, Office of Diractor. 10pp 22576'051 24X Fichs. 50-352,84/02/16,8403070055
- 8403070314 Forwards IE Insp Rapts 50-352/84-01 & 50-353/84-02 on 840103-31. No violations noted STAROSTECKI.R. Division of Project & Rasident Programs. 84/02/22 KEMPER.J. S. Philadelphia Elactric Co 4pp R2546 R04. 24X Fichs: 50-352, 84/02/22, 8403070314.
- --8403070319 IE Inep Repts 50-352/84-01 & 50-353/84-02 on 840103-31 No violations notad, Major areas inspected followup on previous insp findings, plant tour, followup on IE bulletins & Nuclear Review Board Chartar.

 WIGGINB.J T. CHAUDHARY, 8 K. CONNER, E. L. Region 1, Office of Director. 84/02/17. 16pp 22546.208 24X Fiche.50-352,84/02/22,8403070314.
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valva Control Circuits & Annunciation." Svc list encl JORDAN, E.L. Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 110pp 22909;239 R4X Fiche 50-000.84/02/28,8401190072
- 8403020348 Advises of consideration on use of plant-specific PRA & severe accident risk assassments (SARA) to assist NRC in evaluating sampling insp program Raquests meeting in Har 1984; to obtain insights from performing PRA & SARA BTAROSTECKI, R. Division of Project & Rasident Programs 84/02/28 KEMPER, J. S., Philadalphia Electric Co 2pp 22439:020 24% Fiche: 50-352,84/02/28,8403020348.
- B402070007 IE Info Notice 84-i4, "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Svc list ancl. GRACE.J.N Division of QA, Bafeguards & Inspection Programs (Post 830103), 84/03/02 Consolidated Edison Co. of New York, Inc. 130pp. 22552:329. 24X Fiche 50-000.84/03/02,8402070007.

- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valvas to Operata " Svc list encl JORDAN,E L. Division of Emergancy Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Ficha 50-000.84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"

 Bvc list encl

 JORDAN.E L pivision of Emergency Praparadness & Engineering

 Rasponse (Post 830103) 84/03/02 Consolidated Edison Co. of New

 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8403160241 Forwards IE Insp Rapts 50-352/84-03 & 30-353/84-01 on 840109-10 & 12-13 No violations noted MARTIN.T T Division of Enginearing & Tachnical Programs 84/03/02 KEMPER.J S Philadelphia Electric Co 2pp 22661 036 24X Ficha 50-352.84/03/02.8403160241
- --8403160248 IE Insp Repts 50-352/84-03 & 50-353/84-01 on 840109-10 & 12i3. No violations noted. Major areas inspected preoperational radiological environ monitoring program, mgt controls, program for GC for analytical measuremants BTRUCKMEYER, R., PABCIAK, W. J. Region 1, Office of Director 84/02/23 5pp. 22661 038, 24X Fiche, 50-352, 84/03/02, 8403160241
- 840209001i IE Info Notica 84-17. "Problems H/Liquid Nitrogan Cooling Components Balow Nil Ductility Temp " Svc list encl JORDAN.E L Division of Emergancy Preparedness & Enginaering Response (Post 830103) 84/03/05 Consolidated Edison Co of Naw York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402070011
- 8402090024 IE Info Notice 84-09.Rev i, "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Syc list encl JURDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/7 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/97,8402090024
- 8402090028 IE Info Notice 84-18, "Strass Corrosion Cracking in PWR Sys " Svc list enc! JORDAN,E L. Division of Emergancy Preparedness & Enginearing Reports (Post 830103) 84/03/07 Consolidated Edison Co. of Naw York, Inc. 118pp 22584 186, 24X Ficha 50-000,84/03/07,8402090028
- 8402090031 IE Bullatin 84-02, "Failures of GE Type HFA Ralays in Use in Class IE Safaty Bys " 8vc list encl DEYOUNG: C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000,84/03/12,8402090031
- 8402070043 IE Info Notice 84-i9, "Two Events Involving Unauthorized Entrias into PWR Reactor Cavities" Svc list ancl JURDAN.E L Division of Emergancy Praparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Ficha 50-000.84/03/21.8402090043
- 8402090044 IE Info Notica 84-20, "Svc Lifa of Relays in Safety-Ralatad Sys " Svc list encl JURDAN.E L Division of Emergancy Preparedness & Enginearing Response (Post 830i03) B4/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000.84/03/21,8402090044
- 8. Raportabla occurrencas, LERs & relatad correspondence
- B403:30084 Final Significant Deficiency Rept 129 re Agastat CR0095 ralay sockat failures. Defective sockets replaced w/Agastat CR002 sockats, sorrecting any advance safaty implications induced by socket failure KEMPER. J B Philadalphia Electric Co 84/02/17 MURLEY, T E Region 1, Offica of Director, 3pp 22978 343 24% Ficha 50-352,84/02/17,8403130084
- 8403270219 Part 21 rapt re broken contact carriar in control device of 7 5 kV-15 kV, 500-750 MVA, 5 kV 350-3,000 & all HKV circuit broakers Initially reported on 830223 Addenda to installation & maint procedures sant to affected units DUVALL, D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Bervicas Branch (Document Control Dask) 5pp 22772, 114 24% Fiche: 50-000, 84/03/19, 8403270219.
- T Hearing transcripts on non-antitrust matters
- B403020129 Forwards revised testimony re ability of safety-related structures to withstand effects of postulated detonation rasulting from assumad ruptures of Arco & Columbia gas transmission pipelines Related correspondence WETTERHAHN, H. J. Connar & Wetterhahn. WETTERHAHN, H. J. Philadalphia Electric Co. 84/02/28 BRENNER, L. Atomic Safety and Licensing Board Panel 2pp 22442.112 24X Fiche.50-352,84/02/28,8403020129

- --8403020136 Revised testimony of Philadelphia Electic Co re ability of safety-related structures to withstand effects of postulated detonation due to ruptures of transmission pipelines W/Certificate of Svc Related Correspondence Philadelphia Electric Co 84/02/28 27pp 22442 114 24X Fiche 50-032.84/02/28,8403020127
- 8403080253 Transcript of 840305 hearing in Philadelphia.PA Pp 7:565-7:696 * Commissioners 84/03/05 [3]pp 22556 306 24x Fiche 50-352.84/03/05.8403080255
- 8403120092 Transcript of 840306 hearing in Philadelphia, Pa Pp 7, 696-7, 942 * Commissioners 84/03/06 246pp R2588 249 24x Fiche 50-352-84/03/06,8403120092
- 8403120151 Transcript of 840307 hearing in Philadelphia.PA Pp 7.943-8.158 * Abomic Safety and Licensing Board Panel 84/03/07 216pp 22585 263 24X Fiche 50-352.84/03/07.8403120151
- 8403130040 Transcript of 840308 hearing in Philadelphia, PA Pp 8, 157-8, 383 * Atomic Safety and Licensing Board Panel 84/03/08 268pp 22598 067 24X Fiche 50-352,84/03/06,8403130040
- 8403130113 Transcript of 840309 hearing in Philadelphia PA Pp 8.384-8.505 * Atomic Safety and Licensing Board Panel 84/03/09 22pp 22601 001 24X Fiche 50-352,84/03/09,8403130113
- 8403220145 Transcript of 840319 hearing in Philadelphia, PA Pp 8,504-6,647 * Atomic Safety and Licensing Doard Panel 84/03/19 150pp 22714 142 24X Fiche 50~352,84/03/19,8403220145
- 8403260254 Transcript of 840320 hearing in Philadelphia, PA Pp B. 647-8, 842 Supporting documentation encl Atomic Bafety and Licensing Board Panel 84/03/20 202pp 22755 208 24X Fiche 50-352, 84/03/20, 8403260254
- 8403260015 Transcript of 840321 hearing in Philadelphia, PA Pp 8,843-9,059 Supporting documentation encl * Atomic Safety and Licensing Board Panel 84/03/21 283pp 22746 001 24X Fiche 50-352,84/03/21,8403260015.
- 8403260334 Transcript of Commission 84032i affirmation/discussion & vote in Washington, DC re proposed order delegating authority to ABLB to hear Part 70 issues raised in Limerick proceeding Pp 1-3 + Commissioners 84/03/21 6pp, 22775 281 24X Fichs 50-352.84/03/21,8403260334
- 8403270042 Transmittal of testimony re Contention I-42, "Environ Qualification of Electrical Equipment " Related correspondence | HETTERHAHN, M. J. Philadelphia Electric Co. WETTERHAHN, M. J. Conner & Wetterhahn DSB 120 84/03/21 2pp 22769:242 24X Fiche 50-352,84/03/21.8403270042
- --B403270049 Testimony of MJ Boyer, DJ Thompson, DA Kline, L Stanley, EF Sproat, MW Boyers, TE Bhannon & J Doering re Contention I-42, "Environ Qualification of Electrical Equipment" Certificate of Svc encl BOYER, H. J., THOMPSON, D. J., KLINE, D. A. Philadelphia Electric Co B4/03/21 S5pp 22769 244 24X Fiche S0-352, B4/03/21, B403270042
- 8403270296 Testimony of A Masciantonio on Limerick Ecology Action Contention I-42 re electrical environ qualification Related correspondence MASCIANTONIO, A Equipment Qualification Branch DSB 138 84/03/2 10pp 22789 037 24X Fiche 50-352.84/03/21.8403270296
- 8403270171 Transcript of 840322 hearing in Philadelphia, PA. Pp 9,060-9,266 * Atomic Safety and Licensing Board Panel 84/03/22 210pp. 22773 150. 24X Fiche 50-352,84/03/22,8403270171
- 8403270160 Transcript of 840323 hearing in Philadelphia, PA. Pp. 9, 267-9, 401

 * Atomic Safety and Licensing Board Panel 84/03/23 137pp.
 22744, 233 24X Fiche 50-332, 84/03/23, 8403270160
- 8403300009 Memorandum serving transcript pages re 840323 prefiled testimony on Limerick Ecology Action Contention I-42 concerning environ qualification Served on 840329 BRENNER L Atomic Safety and Licensing Board Panel. D88 209. 84/03/29 ip. 22822 131 24% Fiche 50-352,84/03/29,8403300009

- --8403300014 Transcript Pp 9,270-9,274 of 840323 testimony on Limerick Ecology Action Contention I-42 re environ qualification * Office of the Executive Legal Director * Philadelphia Electric Co * Limerick Ecology Action 84/03/29 5pp 22822 i32 24X Fiche 50-352,84/03/29,8403300009
- DOCKET 90-354 HOPE CREEK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8403140340 Summary of B31215 meeting w/GE & Mark I Dwners Group in Bethesda.MD re Mark I containment wetwell-dryweil vacuum breaker design methodology BEEGEL.B L Dereting Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24x Fiche 50-000,84/02/21. 8403140340
- 8403060552 Summary of 840110-12 meetings w/util, Bechtel, NUTECH, Impell, PDM & Dames & Moore in San Francisco.CA restructural & geotechnical engineering design audit. Supporting documentation encl
 HAGNER, D Licensing Branch 2 84/02/27 Licensing Branch 2 15pp 22532 276 24X Fiche 50-354,84/02/27,8403060552
- 8403140113 Forwards "Salem Generating Station 316(b) Demonstration," per 830623 request for addl info re review of UL application for Hope Creek
 MITTL:R L Public Service Electric & Gas Go of New Jersey
 84/03/05 SCHHENCER:A Licensing Branch 2 ip 22627 124 24X
 Fichs 50-000:84/03/05.8403140113
- --8403140117 "Salem Generating Station 316(b) Demonstration "

 * Public Service Electric & Gas Co of New Jersey, 84/02/29
 647pp 22629 125 24X Fiche 50-000,84/03/05,8403140113
- 8403150259 Notification of 840301 meeting w/uti1 in Artificial Island, NJ to discuss QA program MAGNER, D H Licensing Branch 2 84/03/05 8CHWENCER, A. Licensing Branch 2 3pp 22649 349 24X Fiche 50-354,84/03/05,8403150259
- 8403210036 Forwards tabulation on FSAR commitments for Feb 1984 & corresponding resolutions
 MITTL:R L Public Service Electric & Qas Co of New Jersey.
 84/03/05 SCHMENCER:A Licensing Branch 2 4pp 22707 001 24X
 Fiche 50-354
- 8403140007 Forwarde data sheets reflecting current & proposed experience levels for licensed operators at Pacility SALVESEN, R 8 Public Service Electric & Gas Co of New Jersey 84/03/12 DENTON, H Office of Nuclear Reactor Regulation, Director 11pp 22632 130 24X Fiche 50-354,84/03/12,8403140007.
- B403290302 Forwards "Qualification Test Repts.EMI Teets" & "Qualification Test Rept.Burge Withetand Capability Tests," per agreement reached at B40112 meeting on Control Bys Branch Question 421-49
 MITTL.R L Public Service Electric & Qas Co of New Jersey.
 B4/03/16 SCHWENCER.A Licensing Branch 2 ip 22802 099. 24X
 Fiche 50-354,84/03/16.8403290302.
- --8403270305 "Gualification Test Rept.EMI Tests "

 * Validyne Engineering Corp QTR-82-010 82/06/17 43pp.
 22802 100 24X Fiche 50-354,84/03/16,8403270302
- --8403270308 "Qualification Test Rept. Burge Withstand Capability."

 * Validyne Engineering Corp. GTR 82-003 83/04/21, 7pp
 22802 165 24X Fiche, 50-354, 84/03/16, 8403270302
- C Utility Environmental Report (ER), amends & correspondence
- 8403230041 Advises that "Salem Generating Station 316(b) Demonstration" being forwarded directly to GRNL.per M Adams request during NRC 840215 site vielt w/GRNL.Rept should facilitate environ rept review MITTL.R L Public Service Electric & Gas Co. of New Jareey 84/03/08 SCHMENCER.A Licensing Branch 2 ip 22728 355 24X Fiche 50-354.84/03/08.8403230041
- E NRC Safety Evaluation Report (SER): supple & correspondence
- 840322030B Forwards draft SER identifying unresolved issues as open items:per NRC safety review of docketed application & amends SER issuance scheduled for 841012 Schedule for meetings to realive open items requested SCHMENCER: A Licensing Branch 2 84703/05 MITTL,R,L Public Service Electric & Oas Co. of New Jersey 624pp. 22722.001. 24X Fiche 50-354,84/03/05,8403220308.

F Security, medical, emergency & fire protection plans

- 8403030349 Bummary of B40202 meeting w/util.HTI.Essex & Bechtel in Bathesda.MD re-control room design review.per Buppl 1 to NUREQ-0737 Further clarification required in task analysis area. Viewgraphs encl
 MAGNER.D H Licensing Branch 2 84/02/24 Licensing Branch 2 25pp 22527 284 24X Fiche 50-354.84/02/24.8403050349
- 8403220084 Forwards IE Insp Rept 50-354/84-02 on 840109-0220 No violations noted BTAROSTECKIR Division of Project & Resident Programs 84/03/04 MARTIN, T J Public Service Electric & Gas Co of New Jersey 2pp 22716 288 24x Fiche 50-354,84/03/06,8403220086
- --B403220089 IE Insp Rept 50-354/84-02 on 840109-0220 No violations noted. Major areas inspacted documentation peckages on piping sys rupture discs & licensee action on const daficiency repts.torus mod & fire protection
 BATEMAN,W H. MCCABE,E. G. Region i, Office of Director 84/03/05 Bpp. 22716:270 24X Fiche:50-354:84/03/06:8403220086
- 8403190243 Natification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl.

 MURLEY, T E Region i, Office of Director 84/03/09 0'TOOLE, J D Consolidated Edison Co. of New York, Inc. 35pp 22672 062 24X Fiche 50-000, 84/03/09,8403190243

Q. Adjudicatory correspondence

- 8403020141 Conveys agreement w/Btate of NJ Public Advocate re consent to util motion to dismiss Contention IV on environ impact of cooling tower N/o encl
 DELANEY,C.E. Delaware, State of 84/02/27 MILLER,M E Atomic Safety and Licensing Board Panel 2pp 22439 005 24X
 Fiche. 50-354,84/02/27,8403020141.
- 840D140D2B Advises that time for Commission to review ALAB-759 expired Commission declined review Decision became final agency action on B400SB CMILK.B J Office of the Becretary of the Commission 84/03/13 Atomic Befety and Licensing Board Panel ip 22633.214 24X Fiche 50-334.84/03/13.840314002B
- 8403150020 Response opposing public advocate 840227 motion to varate applicant 840222 notice of deposition & for protective order in form of declaratory ruling Related correspondence.
 CONNER, T. B. Public Service Electric & Gas Co of New Jersey CONNER, T. B. Conner & Wetterhahn 84/03/13 Atomic Safety and Licensing Board Panel 16pp 22641,262 24X Fiche: 50-354,84/03/13.8403150020.
- --B403150022 Application for subposes to JH Rodrigusz on B40330 in Newsrk.NJ.Certificate of Byc encl
 CONNER.T.B. Public Bervice Electric & Gas Co of New Jersey
 CONNER.T.B. Conner & Wetterhahn B4/03/13. Atomic Bafety and
 Licensing Board Panel 3pp 22641 277 24X Fiche 50-354,
 B4/03/13.B403150020
- B403170164 Response supporting Dept of Public Advocate of State of NJ B40227 motion for protective order. Applicant has not indicated what specific knowledge re adjudication of contantions Rodriguez believed to have DEWEY, L. B. Hearing Branch S. B4/03/14 Atomic Bafety and Licensing Board Panel. 7pp 22667 177 24X Fiche 50-354,84/03/14, B403170164
- 8403210087 Subpoeme commanding JH Rodrigue: to appear on 840330 in Newark,NJ Affidavit encl. Related correspondence MILLER, H E. Atomic Safety and Licensing Board Panel 84/03/15 Commissioners, 6pp 22705-314, 24X Fiche, 50-354, 84/03/15, 8403210087,
- B403200102 Notifies of taking of deposition of JH Rodriguez Subpoena encl
 CONNER, T. B. Conner & Wetterhahn COONER, T. B Public Service
 Electric & Cas Co., of New Jersey, 84/03/16 DENEY, L. S Office of the Executive Legal Director ip 22685, 316 24X
 Ficher 50-354, 84/03/16, 8403200102
- --8403200108 Subpoena directing UM Rodrigue: to appear on 840330 at Ofc of General Solicitor in Newark.NJ for disposition.

 MILLER.M.E Atomic Safety and Licensing Board Panel 84/03/15 RODRIGUEZ.V.H. New Jarsey. State of ip 22AB5;317. 24X Fiche: 50-354,84/03/16,8403200102.
- 8403210163 Notice of ASLB raconstitution ME Miller, chairman & PA Morris & DR Schinks members Served on 840321. COTTER, B.P. Atomic Safety and Licensing Board Panel DSB 018 84/03/20. 2pp. 22718 224. 24X Fiche 50-354, 84/03/20, 8403210163.

- B403300270 Answer to Public Advocate of State of NJ motion to quash supposena requiring attendance & testimony of JH Rodrigues Motion does not satisfy stay criteria W/Certificate of Svc Related correspondence CONNER, T B Public Service Electric & Oas Co of New Jersey CONNER, T B Conner & Wetterhehn DSB 217 84/03/27 Atomic Bafety and Licensing Appeal Panel 12pp 22824 047 24X Fiche 30-354.84/03/27,8403320270
- 840330027B Order queshing ABLB 840315 subpoena directed to intervenor JH Rodrigue: Subpoena moot Served on 840330 SHOEMAKER.C J Atomic Sefety and Licensing Appeal Panel DSB 225 84/03/29 2pp 22824 018 24% Fiche 50-354:84/03/29, 8403300278

H Ganeral correspondence

- 8403280045 Responds to 840217 inquiry re plants not considered for insp of vent header cracks in torus Insp inapplicable because Fermi & Hope Creek still in const stage DENTON, HR Office of Nuclear Reactor Regulation, Director 84/03/12 MESTOVER, A T Monroe County, M1 ip 22812 358, 24X Ficha 50-000.84/03/12.8403280045
- --8403280054 Requests explanation as to why facility not considered for insp for cracks in vant header similar to crack found at Hatch HEBIOVER, A. J. Monroe County, MI 84/02/17 Office of Nuclear Reactor Regulation, Director 2pp 22812 359 24X Fiche 50-000, 84/03/12:8403280045
- Q Inspection reports, 1E Bulletins & correspondence
- 8403070037 Forwards IE Insp Rept 50-354/84-01 on 840110-13 & notice of violation

 MARTIN, T T Division of Engineering & Technical Programs 84/02/22

 MARTIN, T J Public Service Electric & Gas Co of New Jersey 2pp 22576 020 24X Fiche 50-354,84/02/22,8403070037
- --B403070039 Notice of violation from insp on 840110-13 * Region 1, Office of Director. 84/02/22 ip 22576 022 24X Fiche:50-354,84/02/22,8403070037
- --8403090043 IE Insp Rept 50-354/84-01 on 840110-13 Violations noted heat not restored to alternators of four dissels as required by Litton Industries maint manual & licensee maint instructions FINKEL, A. PAULITZ, F., ANDERSON, C. J. Region 1. Office of Director 84/02/07 6pp 22576 023 24X Fiche 50-334,84/02/22,8403090037
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000.84/02/28,8401190072
- 8403090080 Submits supplemental response to IE Bulletin 83-06 re nonconforming matts supplied by Tube-Line Corp Remeining four suppliers confirmed that no subj matts supplied to Hope Creek Colt Industries info under review MARTIN.T J Public Servica Electric & Oas Co of New Jersey 84/02/28 MRLEY.T E Region 1. Office of Director 2pp 22575 297 24X Fiche 50-000.84/02/28.8403090080
- 8402070007 IE Info Notice 84-i4, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Evc list encl GRACE, J N Division of GA. Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329, 24X Fiche 50-000,84/03/02,8402070007.
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Poet 830103) 94/03/02 Consolidated Edison Co. of New York, Inc. 122pp. 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02. Consolidated Edison Co. of New
 York, Inc. 119pp 22553 217 24X Fiche. 50-000, 84/03/02, 8402090007
- 840209001; IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooking Components Below Nil Ductility Temp " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/05 Consolidated Edison Co of New York, Inc 117pp. 22553 336 24X Fiche 50-000.84/03/05,8402090011

- 8403220086 Forwards IE Insp Rept 50-354/84-02 on 840109-0220 No violations noted STARDSTECKI.R Division of Project & Resident Programs 84/03/06 MARTIN.T J Public Service Electric & Gas Co of New Jersey 2pp 22716 289 24% Fiche \$0-354.84/03/06.8403280086
- --8403220089 IE Insp Rept 50-354/84-02 on 840109-0220 No violations noted Major areas inspected documentation packages on piping sys rupture discs & licensee action on const deficiency repts torus mod & fire protection BATEMAN,W H. MCGABE, C. Region 1. Office of Director 84/03/08pp. 22716 290. 24X Fiche.50-354,84/03/06.8403220086
- 8402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown 8ys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24% Fiche 50-000. 84/03/07, 8402090024
- 8402090028 IE info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Sys list enri
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co of New
 York, Inc 118pp 22584 186 24x Ficher 50-000,84/03/07,8402090028
- 8403130009 Ack receipt of 840210 itr informing NRC of steps taken to correct violations noted in IE Inep Rept 50-354/83-i4 MARTIN.T T. Division of Engineering & Technical Programs 84/03/07 MARTIN.T J Public Service Electric & Gas Co of New Jersey 1p 22615 i61 24X Fiche 50-354,84/03/07,8403130009
- --B403130014 Responds to NRC B40110 ltr re violations noted in IE lnsp
 Rept 50-354/83-14 Corrective actions reinsp of all safetyrelated electrical wall mounted supports performed to
 determine extent of connections exceeding criteria
 MARTIN.T J Public Service Electric & Cas Co. of New Jersey
 B4/02/10 MURLEY.T E Region 1. Office of Director 4pp
 22615 162 24X Fiche 50-354,84/03/07,8403130009
- 8403130355 Act receipt of 840228 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50~354/83-18
 BYAROSTECKI.R Division of Project & Resident Programs 84/03/08
 MARTIN.T J Public Service Electric & Gas Co of New Jersey 1p
 22616 250 24X Fiche 50-354,84/03/08,8403130355
- --8403130372 Responds to NRC 840130 ltr re violations noted in IE Insp. Rept 50-334/83-18 Corrective actions seven nonconforming hangers will be reworked to obtain required depth of weld penetration at skewed T-joints MARTIN.T J Public Service Electric & Oas Co of New Jersey 84/02/28 MURLEY.T E Region 1. Office of Director 3pp 22616 251 24X Fiche 50-354,84/03/08,8403130355
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Sefety Sys " Svc list enci DEVOUNO,R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12,8402090031
- 8403300098 Forwards IE Insp Rept 50-354/84-03 on 840120 No violations observed MARTIN, T I Division of Engineering & Technical Programs 84/03/16 MARTIN, T J Public Service Electric & Qas Co of New Jersey 2pp 22822 004 24% Fiche 50-354,84/03/16,8403300098
- --8403300103 TE Insp Rept 50-354/84-03 on 840120 No violation identified Major areas inspected discrepancies identified in original seismic analysis of auxiliary bldg MANOLY, K . DURR, J P Region I. Office of Director 84/03/07 4pp 22872 006 24% Fiche 50-354,84/03/16,8403300098
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities" Syc list enti JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84703/21 Consolidated Edison Co of New York, Int 123pp 22823,229 24% Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Bvc list enc!
 JDRDAN: El Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York: Inc 135pp 22933 001 24X Fiche 50-000.84/03/21.8402090044
- 8403300121 Responds to IR Bulletin 83-07. "Apparently Fraudulent Products Sold by Ray Miller: Inc "Bechtel investigating suppliers not responding to request of whether fraudulent matls skipped.

 MARTIN: T Public Service Electric & Oas Co of New Jersey 84/03/21 MURLEY: T Region 1. Office of Director 2pp 22820 345 24% Fiche 30-354.84/03/21.8403300121

- S Reportable occurrences, LERs & related correspondence
- 8403210118 Interim deficiency rept re failure of GE Type AKR-30 circuit breakers initially reported on 831223 Breakers reinspected.

 Next rept will be submitted by 840314

 MARTIN.T J Public Service Electric & Qas Co of New Jersey
 84/02/24 MURLEY.T E Region 1. Office of Director 2pp.
 22705 075 24X Fiche 50-354.84/02/24.8403210118
- 8403260233 Forwards summary list of deficiencies identified per iOCFR5D 55(e).Part 21 & potential generic itr repts for comments
 STAROSTECKI,R Division of Project & Resident Programs 84/02/28
 Region i, Office of Director 7pp 22736 065 24X
 Fichs 50-000.84/02/28,8403260233
- 840315010B Potentially significant const deficiency rept re defective capstan springs in ITT Grinnel shock arrestors Initially reported on 831024 Condition does not warrant coming offline to replace springs Next rept by 840429

 MARTIN.T J Public Service Electric & Gas Co of New Jersey, 84702/29 MMREY.T E Region 1, Office of Director 2pp. 22640 207 24X Fichs 50-354.84/02/29.8403150108.
- 8403270219 Part 21 rept re broken contact carrier in control device of 7.5 tV-15 kV.300-750 MVA.5 kV.350-3.000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units.

 DUVALL.D D. Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24X Fiche 50-000,84/03/19.8403270219.
- DOCKET 50-355 HOPE CREEK NUCLEAR STATION: UNIT 2
- A Application/construction stage documents & correspondence
- 8403140340 Summary of 831215 meeting w/0E & Mark I Dwners Group in Bethesda.ND re Mark I containment wetwell-drywell vacuum breaker design methodology BIEGEL.B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635.198 24X Fiche 50-000,84/02/21, 8403140340
- F Becurity, medical, emergency & fire protection plans
- 8403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lassons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-07 Agenda for workshop encl MURLEY, T E Region i, Office of Director 84/03/09, O'TOOLE, J D Consolidated Edison Co. of New York, Inc. 35pp 22672 062, 24X Fiche 50-000,84/03/09,8403190243
- H General correspondence
- 8403280045 Responds to 840217 inquiry re plants not considered for insp of vent header cracks in torus Insp inapplicable because Fermi & Hope Craek still in const stage BENTON, HR Office of Nuclear Reactor Regulation, Director 84/03/12 MESTOVER, AT Monroe County, MI, ip 22812 358 24X Fiche 50-000,84/03/12,8403280045
- --8403280034 Requests explanation as to why facility not considered for insp for cracks in vent header similar to crack found at Hatch WESTOVER, A J. Honroe County, MI. 84/02/17, Office of Nuclear Rector Regulation, Director 2pp. 22812, 359 24X Fiche 50-000, 84/03/12, 8403280045
- G Inspection reports, 1E Bulletins & correspondence
- 8403070080 Submits supplemental response to IE Bulletin 83-04 re nonconforming matts supplied by Tuber-Line Corp Remaining four suppliers confirmed that no subj matts supplied to Hope Creek Colt Industries info under review MARTIN, J. Public Service Electric & Cae Co. of New Jersey, 84/02/28 MURLEY, T.E. Region 1, Office of Director 2pp. 22575-297 24% Fiche 50-000,84/02/28,8403070080.
- 8403300121 Responds to IE Bulletin B3-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc." Bechtel investigating suppliers not responding to request of whether fraudulent matls shipped MARTIN.T T Public Service Electric & Oas Co. of New Jersey 84/03/21 MURLEY, T.E. Region 1, Office of Director. 2pp 22820 345 24X Fiche 50-354,84/03/21,8403300121.

S Reportable occurrences, LERs & related correspondence

- B403240233 Forwards summary list of deficiencies identified per 10CFR30 55(e).Part 21 & potential generic ltr repts for comments
- B40315010B Potentially significant const deficiency rept re defective capstan springs in ITT Grinnel shock arrestors Initially reported on 831024 Condition does not warrent coming offline to replace springs Next rept by 840427 MARTIN,T J Public Service Electric & Oas Co of New Jersey 84/02/29 WRILEY,T E Region I. Office of Director 2pp 22640 207 24X Fiche 50-354,84/02/29,8403150108
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 tV-15 kV.500-750 MVA,5 kV 350-3.000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL,D D. Brown Bovarl Corp. (subs of Brown Boveri & Co., Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24X Fiche 50-000,84/03/19,8403270219
- DOCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8403130288 Forwards Natl Board of Boiler & Pressure Vascel Inspectors 840227 ltr to State of OH re util abandonment of facility as nuclear unit & board wlilingness to provide support should plant be reinstated.

 #### HARRISON.8 F. National Board of Boiler & Pressure Vascel Inspectors 84/03/05 DIRCKG, W Office of the Executive Director for Operations 17pp 22608 017 24X Fiche 50-358,84/03/05,8403130288
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D 0 Division of Licensing 84/03/14, Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000.84/03/14,8402090041
- 8403260065 Respands to 831128 ltr clarifying role in work parformed for HJ Kaissr Co during Apr-Sapt 1983 Reevaluation personnsi verification program recommended KEPPLER.J G. Region 3: Office of Director 84/03/20 ROBERTS.J Cygne Energy Services 7pp 22750 245. 24X Fiche 50-358.84/03/20. 8403260065
- F Security, medical, emergency & fire protection plans
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning first in electrical cablinets in control room EISENHUT, D Q. Division of Licensing. 84/02/23 PALLADINO Commissioners 1p 22576-203 24X Fiche 80-000.84/02/23, 8402090006
- --84D30B0314 Recommends that info re fire research results concerning fires In slectrical cabinets in control room be submitted for board notification, per NRR Ofc Ltr 19, dtd 821001 Further evaluation of test data required VOLLMERR M. Division of Engineering 84/02/06 EISENHUT, D 0 Division of Licensing 10pp 22576 204 24X Ficha, 50-000, 84/02/23, 8402090006
- 8403120093 Extends invitation to attend 840323 regional workshop in Rosamont. IL re 100FR50, App R safe shutdown requirements Workshop will cover subjs described in IE Info Notice 84-09 & provide add1 guidance in safe shutdown analyses 8PESBARD.R L Division of Engineering 84/03/06 WAGNER.E J Gincinnati Oas & Electric Co 3pp 22588 191, 24X Fiche: 50-358.84/03/06.8403120093.
- Adjudicatory correspondence
- 8403050066 Order extending time until further order for Commission to act to review Director's Decisions DD-83-19 & DD-84-3 CHILK: 8 J. Office of the Secretary of the Commission 84/02/29 Commissioners 1p. 22490 182 24X Ficha 50-358.84/02/29, 8403050066.
- 8403210178 Motion requesting Issuance of order authorizing withdrawal of application Plant will be used as part of new fossil fuel-fired electric generating plant Certificate of Syc ancl.

 CONNER. T. B. Cincinnati Gas & Electric Co CONNER. T B Conner & Wetterhahn DBB 024 84/03/20 Atomic Bafety and Licensing Board Panel Spp. 22710 098 24% Fiche. 50-358, 84/03/20, 8403210178

- G Inspection reports, IE Bulletins & correspondence
- 8403230104 Requests add1 40 days to accomplish review of work performed by Reactor Controls. Inc.in response to NRC 831017 draft info notice Extension required due to physical walkdown of selected sys
 HILLIAMB. J Cincinneti Gas & Electric Go 83/11/22 KEPPLER. J Q Region 3. Office of Director 2pp 22730 226 24X
 Fiche 50-358.83/11/22.8403230104
- 8401190072 iE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post B30103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 82909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403i903i5 Forwards IE Insp Rept 50-358/84-0i on 840107-02i3 No noncompliance identified WARNICK:R F Region 3, Offics of Director 84/02/29 WAGNER:E J Cincinnati Qas & Electric Co Rpp 22673 215 24X Fiche 50-338,84/02/29,8403190315
- --8403190323 IE Insp Rept 50-358/84-01 on 840107-0213 No noncompliance identified Major areas inspected previous insp findings, quality confirmation program nonconformance rept revisu & personnel indoctrination program ONYNN.T.P , NIGHTINOALE.E , HILL.W M Region 3, Office of Director 84/02/28 19pp 22673 217 24X Fiche 50-358.84/02/29.8403190315
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Svc list encl ORACE.J N Division of QA, Bafeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24% Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-i6. "Fallure of Automatic Sprinkler Sys Valves to Operate" Svc list encl
 JORDAN.E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co. of New
 York. Inc. 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- B402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl
 JURDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02.8402090009
- 84020900ii lE Info Notice 84-i7, "Problems W/Liquid Nitrogen Cooling Components Below Nii Ductility Temp " 8vc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of Nsw York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,84020900ii
- 8402090024 IE Info Notice B4-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list sncl JORDAN, E. L. Division of Emsrgatncy Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Flche 50-000,84/03/07,8402090024
- 8402070028 IE Info Notics 84-18, "Stress Corrosion Cracking in PWR Bys " Byc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE 8afety Sys " Svc list enc!
 DEYOUNG:R C Director's Office: Diffice of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorlisd Entries into PWR Reactor Cavities" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fichs 50-000,84/03/21,8402070043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safsty-Related 8ys." Svc list ancl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000-84/03/21,8402090044

- 8 Reportable occurrences, LERs & related correspondence
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 S kV-i5 kV.500-750 MVA.5 kV 350-3.000 & all HXV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24X Fiche 50-000.84/03/19.8403270219
- U Congressional/Executive Correspondence
- 8402130393 Responds to 840111 request for development of facility public safety oversight committee Merits of committee not judged due to util intention not to complete project as nuclear plant PALLADING.N J Commissioners 84/01/31 COLLINS.M L Kentucky. Commonwealth of, 1p 22662 250 24X Fiche 50-358,84/01/31,8402130393
- --8402130397 Responds to B31212 request for development of facility public safety oversight committee Merits of committee not judged due to util intention not to complete project as nuclear plant PALLADINDLY J Commissioners 84/01/31 BURTZ. A Cincinnati. CH 1p 22662 251 24X Fiche 50-356.84/01/31.8402130393
- --8402130390 Responds to 831221 request for development of facility public safety oversight committee Merits of committee not judged due to util intention not to complete project as nuclear plant PALLADING.N J Commissioners 84/01/31 METZENBAUM.H M Senate. Energy & Natural Resources 1p 22662 252 24X Fiche 50-358,84/01/31.8402130393
- --B402130353 Responds to 831215 request for development of facility public safety oversight committee Merits of committee not judged due to util intention not to complete project as nuclear plant PALLADIND.N J Commissioners 84/01/31 CELEBTE,R F Chio, State of 4pp 22662 253 24X Fiche 50-338.84/01/31.8402130393
- --B402130395 Requests development of proposed facility public oversight committee Committee establishment would inspire public confidence CDLINB, M L Kentucty, Commonwealth of, 84/01/11 PALLADIND, N Commissioners ip 22662 254 24X Fiche 50-358,84/01/31, 8402130393
- --8402130392 Requests development of public oversight committee to review famility safety-related problems NRC & util credibility questioned as public witness cost overruns & safety flaws.

 METZENBAUH, H M Senate, Energy & Natural Resources B3/12/21

 PALLADINO.N J Commissioners 1p 22662 257 24X

 Fiche 50-358,84/01/31,8402130393
- --8402130360 Requests changes in proposed facility oversight committee Changes needed to inspire public confidence in oversight process CELESTE, R F Ohio, State of 83/12/15 PALLADINO, N Commissioners 1p 22662 258 24% Fiche 50-358,84/01/3i, 8402130393
- DOCKET 50-361 SAN DNOFRE NUCLEAR STATION, UNIT 2
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403020333 Forwards "Evaluation of Natural Circulation Cooldown Test Performed at San Onofre Nuclear Generating Station " Boron mixing tests in lieu of natural circulation test accepted by updated SER & SERR 5 COOK.K W Louisiana Power & Light Co 84/02/29. KNIGHTON.O W Licensing Branch 3 ip 22439.035 24X Fiche 50-000,84/02/29, 8403020333
- F Security, medical, emergency & fire protection plans
- 840203033B Forwards revised "Emergency Plan Implementing Procedures. Ban Onofre Nuclear Generating Station Units i, 2 & 3 " CRCY, P. A. Southern California Editon Co. 84/01/27 NRC - No. Detailed Affiliation Given 1p. 22064 013 24X Fiche 50-206.84/01/27,840203033B
- --B4D2030344 Revised "Emergency Plan Implementing Procedures, San Unofre Nuclear Generating Station, Units 1:2 & 3 " ANDERSON, C N , PATRISSI, O A Southern California Edison Co B4/01/27 525pp 22064:015 24X Fiche: 50-206, B4/01/27, B402030338

- 8403050148 Forwards "Evaulation of Southern California Edison Site-Epecific Offsite Radiological Emergency Preparedness Frompt Alert & Notification Sys Evaluation " Sys adequate to alert & notify public in event of accident SPECK.S W Federal Emergency Management Agency 84/01/31. DIRCKS W J Office of the Executive Director for Operations ip 22487 314 24X Fiche 50-206.84/01/31.8403050148
- --8403030172 "Evaluation of Southern California Edison Site-Specific Offsite Radiological Emergency Preparedness Prompt Alert & Notification Sys "

 + Federal Emergency Management Agency, 84/01/05 61pp 22407 315 24X Fiche 50-206,84/01/31,8403050148
- B403150031 Revs to emergency plan implementing procedures, including EPIP S0123-VIII-0 202, "Assignment of Emergency Response Personnel" & B023-VIII-1, "Recognition & Classification of Emergencies " M/840227 itr BENNETY.D D. PEACOR.D H., CROY.P A. Bouthern California Edison Co. B4/02/15 68pp. 22643 207. 24X Fiche 50-206,84/02/15,8403150031
- B402230176 Forwards revised State of CA nuclear power plant emergency response plan MEDFORD.M O Southern California Edison Co 84/02/16 E16ENAUT, D G Division of Licensing. 2903pp. 22353 001 24X Fiche 50-000.84/02/16.8402230176
- --G403020117 Revised State of CA nuclear power plant emergency response plan * California: State of 83/04/30 2901pp 22353,003 24X Fiche 50-000,84/02/16.8402230176
- 8403050127 Forwards exemption from 10CFR50. App E. Bection IV. F. 1 re requirement for state & local participation in annual emergency plan exercise scheduled for 840229 EISENHUT, D o Division of Licensing 84/02/29 BASKIN, K P. Bouthern California Edison Co 3pp 22489 165 24X Fiche 50-206.84/02/29,8403050127
- --B403050132 Exemption from 10CFR50.App E.Bection IV F i re requirement for state & local participation in annual emergency plan exercise scheduled for 840227 MIRAQLIA.F J Division of Licensing 84/02/27. Southern California Edison Co Spp. 22489 168 24X Fiche, 50-206, 84/02/27, B403050127
- 8403120184 Forwards IE Safeguards Insp Repts 50-361/84-03 & 50-362/84-03 on 840124-25 No noncompliance noted NORDERHAUG.L R Region 5, Office of Director 84/03/06 MCCARTHY.C I Southern California Edison Co 2pp 22586,255. 24X Fiche 50-361.84/03/06.8403120184
- --8403120185 IE Safeguards Insp Repts 50-361/84-03 & 50-362/84-03 on 840124-25 No noncompliance or deviations noted Major areas inspected organization, operation, shipping & receiving & records & repts Details withheld (ref 10CFR2 790) WIEDER, A V, NORDERHAUG, L. Region 5, Office of Director 84/03/05 ip 22586 257 24X Fiche 50-361,84/03/06,8403120184
- 8403270256 Forwards Rev 12 to physical security plan Rev withheld (ref 10CFR73 21) HAYNES, J G. Bouthern California Edison Co 84/03/07 MARTIN, J. B Region 5. Office of Director 2pp 22772 031 24X Fiche 50-206.84/03/07.8403270256
- B403200097 Informs that emergency operations facility HVAC control logic mod & procedures necessary to implement HVAC isolation completed gridor to B40229 commitment date MEDFORD, M O Southern California Edison Co B4/03/14 E1SENHUT, D O Division of Licensing 1p 22699 095 24X Fiche 50-206. B4/03/14,6403200097
- 8403220018 Forwards "Updated Fire Hazards Analysis, Vols 1-4."

 BABKIN,K P Bouthern California Edison Co 84/03/19 DENTON.H R
 Office of Nuclear Reactor Regulation, Director. 10pp
 24X Fiche 30-204,84/03/19,8403220018
- --8403220027 "Updated Fire Hazards Analysis:Vols 1-4"
 * Southern California Edison Co 84/03/19 1178pp 22735:341,
 24X Fiche 50-206:84/03/19,8403220018
- 8403270205 Discusses Southern California Edison submittal of 1983 revised State of CA emergency response plan on behalf of all State of CA plants, incorporating plan into Diablo Cangon Addl planning info will not be developed for Humboldt Bay. SCHUYLER, J O Pacific Gas & Electric Co. 84/03/22 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p 22772.137, 24% Fiche 50-000.84/03/22.8403270205.

H. General correspondence

B403140063 Requests that MB Stoshr be removed from distribution list & that L Esrnath ba added MULBEY. B A San Diego Cas & Elsctric Co 84/03/12. EISENHUT, D O Division of Licansing ip 22655 089 24X Fichs 50-206,84/03/12,

J Insuranca & indemnity information

8403060395 Forwards Endorsaments 100 & 88 to NELIA Policy NF-146 & MAELU Policy NF-38, respectively ROCCO, J Boutharn California Edison Co 84/02/29 DINITZ, I Office of Nuclser Rasctor Regulation, Director 3pp 22518 152 24X Ficha. 50-206.84/02/29,8403060395

P. Operating license stags documents & correspondence

- 8403010117 Partiel rasponse to FOIA request for documents by named individuals re repts; anelyses, studies, procaduras & sys for massurement of RCS isskegs App 8 documents placed in PDR App A documents elready availed in FDR, 8 serch continuing FELTON, J M Division of Rules and Racords 84/01/25 MADDEN, T J. Keye, 8choler, Fishman, Hays & Handier 7pp 22480 026 24X Fiche: 30-000,84/01/25,8403010117
- --8403010233 Discusses RCS leak rata calculations.per 820504 talcon Mods to RCSLK7 computer program psrmit Isak rate calculations for pressures between 1.900 & 2,100 psig w/temp bstwssn 260 F & 270 F Plent data encl MCRRILL.P J. Raylon 5. Office of Director 82/05/05. HODRUFF.R.M. Raactor Enginesring Branch 17pp 22481 362 24X Fiche 50-000.84/01/25.8403010117
- 8403020092 Application for emend to Licenses NPF-10 & NPF-15, changing Tach Spac Table 3 3-2, "Reactor Protective Instrumentation Response Times," to incorporate panelty factor MEDFORD.M 0 Bouthern California Edison Co 84/02/29 KNIOHTON.O M. Licensing Branch 3. 7pp. 22442 299. 24X Fiche: 50-36184/02/29, 8403020092
- ---8403020098 Proposed Tech Spacs, changing Table 3 3-2, "Reector Protective Instrumentation Response Timse." * Bouthern Celifornia Edison Co 84/02/29, 15pp 22442 306 24X Fiche. 30-361,84/02/29,8403020092
- B403020335 "Evaluation of Naturel Circulation Cooldown Tast Performed at San Onofre Nuclear Generating Station."

 * Combustion Engineering: Inc CEN-259 64/01/31. 136pp. 22439:036 24X Fiche: 50-000.84/02/27.6403020333
- 8403060424 Application for amand to Licenses NPF-10 & NPF-15, revising Tech Specs ra radiation & radioective effluent monitoring instrumentation & radiological environ monitoring program HEDFORP.H O. Bouthern Callfornia Edison Co 84/03/02 Offica of Nuclear Reactor Regulation: Director. KNIGHTON.Q W. Licensing Brench 3. 3pp. 22507 154. 24X Ficha: 50-361, 84/03/02, 8403060424
- ---B403060427 Proposed Tach Specs revising radiation & radioactive effluent monitoring Instrumentation & radiological anviron monitoring program ** Bouthern Celifornia Edison Co. 84/03/02, 256pp. 22507-157 24X Fiche 50-361-84/03/02,8403060424
- 8403090177 Forwards application for Amand 24 to Licensa NPF-10 & Amand 10 to Licensa NPF-15, Amands ravise Tech Bpsc 4. 8. 1. 1. 2. C re Isval of insolublas in diesel fuel oil & Saction 6 re organizational changes BABKIN, K.P. Southern California Edison Co. 84/03/07 DENTON, H R Office of Nuclear Rescut Regulation, Dlractor. 2pp. 22571.247, 24X Fichs. 50-341, 84/03/07, 8403090177.
- --8403090227 Application for Amend 10 to Licenss NPF-15, revising Tsch Spec 4.8, 1.1.2, C to determine operability of diesel generator should diesel fuel die fail to meat test for insolubles & revising Bestion 6 re organization changes, BABKIN.K P. Southern California Edison Co. 84/03/07 10pp 22571:249. 24X Fiche: 50-361,84/03/07.8403090177
- --8403090230 Proposed revs to Tech Spec 4.8 i 1.2 C to determine operability of diasel generator should diesel fusl oil fail to meet test for inaclubles & proposed revs to Section 6 re organizational changes.

 # Bouthern California Edison Co. 84/03/07, iippp 22571,259 24X Fiche: 50-361,84/03/07,8403090177.

- --8403090233 Application for Amend 24 to License NPF-10, ravising Tech Spec 4 8 i 1 2 C to determine operability of diesel generator should diesel fuel oil fail to meet test for insolubles & revising Section 6 re organizational changes BASKIN.K P Southern California Edison Co 84/03/07 10pp 22372 014 24X Fiche 50-364:84/03/07.8403090177
- --8403090238 Proposad revs to Twch Spec 4 8 1 1 2 C to determine operability of diesel generator should dissel fuel oil fail to meet test for insolubles & proposed revs to Section 6 rs organizetional changes
 BASKIN.K P Southern California Edison Co 84/03/07 117pp 22572 024 24X Fichs 50-361.64/03/07.8403090177
- 8403270370 Notification of 840308 maeting w/util in Sethesds, MD to discuss turbing missile probabilities & turbing overspeed protection Tech Spec Agenda encl RODD.N Licensing Branch 3 84/03/07 KNIGHTON, 0 W Licensing Branch 3 4pp 22787 331 24X Fiche 50-361.84/03/07,8403270370
- 8403270331 Informs that NUREG-0737. Item 11 K 2 17. "Voiding in RCS During Transients" complets besed on util andorsement of CEN-199. "Effacts of Vessel Head Voiding During " KNIOHTON.G W Licansing Branch 3. 84/03/08 BASKIN.K P. Bouthern California Edison Co HOLCOMBE.J C San Diggo Gas & Electric Co 9pp. 22822 220 24X Fiche 50-341.84/03/08.8403290331
- 8403130134 Informs thet equipment requiring environ qualification revlawad for potential age-related degradation.per NRC 820830 Itr & replacament schedulas incorporated into meint program MEDFORD.M D Southern California Edison Co 84/03/09 KNIGHTON.O W Licansing Brench 3 lp 22601.023 24X Fiche 50-361.84/03/09.8403130134
- B403i60013 Forwards "Evaluation of Naturel Circulation Cooldown Test Performed at Ban Onofra Nuclsar Conserting Bitation "Rept provides svaluation of applicability of results to Gt Lucia Unit 2 WILLIAMS, J W Florida Power & Light Co 84/03/13 EISENHUT. D C Division of Licansing ip 22652:179 24X Fiche 50-000,84/03/13,8403160013
- 8403170345 Forwards clarification of previous responses to NRC Questions 8, 9, 12 & 13 rs discharge piping sys & "EPRI PWR Bafaty & RSlief Valvs Tast Program Ouida" Info satisfias requirements of TMI Item II.D 1.
 MEDFORD.M D Southern Celifornie Edison Co 84/03/14
 KNICHTON.O W Licansing Branch 3 lipp 22675 079 24X
 Fiche. 50-361.84/03/14.8403190345
- ~-8403190351 Rsv 1 to "EPRI PHR Sefety & Relief Valva Test Program Guida for Application of Valvs Tast Program Rasults to Plant-Specific Evelutions " * MPR Associates, Inc. 82/03/31 86pp 22675 090 24X Ficha 50-361.84/03/14.8403190345
- 8403270217 Requests exemption from 10CFR70 24 requiring meint of accidental criticality radiation monitoring sys Evaluations distermined potential for criticality for new & spant fuel nonexistent based on geometric spacing MEDFORD, M D. Southarn California Edison Co 84/03/27 KNIGHTON, G, W Licansing Branch 3, 4pp 22803 284 24X Fiche 50-361, 84/03/27, 8403290217.
- G Inspection reports, IE Bulletins & correspondence
- B4030B040B FOIA request for repts of insp cerried out under Condition 2 of Nuclear Energy Lisbility policies for fecilities, CALBOYAB.C D. Affiliation Not Assigned 84/02/07 Region 5, Office of Director 4pp 22567.341 24X Fiche.50-000.84/02/07, 84030B040B
- 8403060025 Forwards lE lnsp Repts 50-206/83-28.50-361/83-43 & 30-362/83-42 on 831210-840121 No noncompliance noted BISHOP, T W. Division of Resident: Reactor Project & Engineering Programs 84/02/09 BARKIN, K. P. Southern Celifornia Edizon Co 2pp 22516:285 24X Fiche 50-206.84/02/09.8403060025
- --8403060027 IE Insp Repts 30-206/83-28,50-361/83-43 & 50-362/83-42 on 831210-840121 No noncompliance or deviations noted Major areas inspected operational safety verification.power assession trenslant testing & meint activities.

 CHAFFEE, A E , STEWART, J. P , D'ANOELO, A Region 5, Office of Director 84/02/07 13pp. 22516:287 24X Ficha 50-206,84/02/09,8403060025
- 8403060008 Forwards IE Insp Repts 50-206/84-02.50-361/84-02 & 50-362/84-02 on 840115-20.No noncompliance nated MENSLAWSKI, F.A. Region 5. Office of Director 84/02/16. BASKIN, K. B. Southern California Edison Co. 2pp 22516

- --8403060017 IE Insp Repts SC-206/84-02.50-361/84-02 & 50-362/84-02 on 840113-20 No noncompliance or deviations noted Major areas inspected radiation protection program.health physics & chemistry training & general employee training & GHERHAN, C I , HENSLAMSKI,F A Region 5. Office of Director 84/02/15 | 19pp | 22516-270 | 24% Fichs 50-206.84/02/16.840306000B
- 8403080419 Responds to FOIA request for repts of insp carried out under Candition 2 to Nuclear Energy Liability policies for facilities NRC does not have repts FELTON, J M Division of Rules and Records 84/02/22 CALSOYAS, C D Affiliation Not Assigned 1p 22567 345 24K Fiche 50-000.84/02/22.8403080419
- B401190072 IE Info Notice B4-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Bvc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. ilSpp 22709 237 24X Fiche 50-000,84/02/28,8401190072
- 8403190367 Forwards IE Insp Rept+ 50-206/84-04.50-361/84-05 & 50-362/84-03 on 840123-27 No noncompliance noted. WENSLAMSKI,F A Region 5, Office of Director 84/03/01 BASKIN,K B Southern California Edison Co 2pp 22673 220 24X Fiche 50-206.84/03/01.8403190367
- --8403190373 IE Insp Repts 50-206/B4-04.50-361/B4-05 & 50-362/B4-05 on B40123-27 No noncompliance noted Major areas inspected radiological environ monitoring program & followup on licensee action re previous insp findings YUNAS.6 P. WENSLAMSKI,F A Region 5. Diffice of Director B4/03/01 6pp 22675.222 24X Fiche 50-206.84/03/01,8403190367
- 8402090007 IE info Notice 84-14, "Highlights of Recent Transport Regulatory Rave by DOT & NRC " Syc list encl GRACE.J N Division of OA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-16, "Failurs of Automatic Sprinkler Bys Valves to Operats " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York Inc 122pp 22553 098 24X Fiths 50-000,84/03/02,8402070008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Release "
 Svc list enci
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fichs 50-000,84/03/02,8402090009
- 8402070011 IE Info Notice B4-17, "Problems W/Liquid Mitrogen Cooling Components Below Ni) Ductifity Temp " Bvc list enci JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidate Edison Co of New York. Inc 117pp 22553 336 24X Fiche 50-000.84/03/03.8402070011
- 8403120184 Forwards IE Safeguards Insp Repts 50-361/84-03 & 50-362/84-03 on 840124-25 No noncompliance noted. NORDERMAUGL R Region 5. Office of Director 84/03/06 NCCARTHY.C B Southern California Edison Co 2pp 22586 255 24X Fichs 50-361.84/03/06.8403120184
- --8403120185 IE Safeguards insp Repts 50-361/84-03 & 50-362/84-03 on 840124-25 No noncompliance or deviations noted Major areas inspected organization operation shipping & receiving & records & repts Details withheld (ref 100FR2 790).

 WIEDER-A.V. NORDERHAUG, L. Region 5, Office of Director 84/03/05 ip, 22586-257 24X Fiche 50-361.84/03/06.8403120184.
- 8402090024 IE Info Notice 84-09.Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Syc list encl JORDAN, Et Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000.84/03/07,8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PHR Sys." Svc list encl
 UCRDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp. 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403090127 Responds to IE Bullatin B3-08 re electrical circuit breakers w/undervoltage trip feature used in applications other than reactor trip sys No circuit breakers utilized in safety-related applications Bulletin inapplicable.
 MEDFORD.M O Southern California Edison Co 84/03/07 MARTIN.J B Region 5. Office of Director ip 22575 340 24X Fiche 50-361.84/03/07.8403090127

- B40207003i IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list and DEVOUNG: R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823:094. 24X Fiche 30-000.84/03/12.8402070031
- 8402070043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list enc! JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402070043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list snc1 JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- 8403230118 Responds to Items i & 4 of IE Bulletin 83-07, "Apparently Frauduisnt Products Bold by Ray Miller, Inc." No evidence found to indicate that any vendor matls provided to or used at facilities MRIEGER, R W Southern California Edison Co 84/03/21 MARTIN, J B Region 5, Offics of Director 2pp 22730 159 24X Fiche 50-361,84/03/21,8403230118
- A Periodic operating reports & related correspondence
- 8403060438 "Annual Personnel Homitoring Rept. 1983 " W/840229 ltr HAYNES, J G Southern California Edison Co 83/12/31 4pp 22511 189 24X Fiche 50-206, 83/12/31, 8403060438
- 8403020010 Monthly operating repts for Jan 1984, W/840215 1tr MORRIB. C A , HAYNEB. J Q Southern California Edison Co 84/01/31 12pp 22442 223 24% Fichs 50-361, 84/01/31, 8403020010
- B403020040 Forwards auxiliary feedwater sys monthly outage rept for 831216-B40115, per License Condition 2 C(26) MEDFORD.M D Bouthern California Edison Co B4/02/29, KNIGHTON.G W Licensing Branch 3 3pp 22442 269 24X Fiche 50-361,84/02/29,8403020040
- B403200053 Forwards monthly operating repts for Feb 1984 & revised monthly operating rspts for Aug 1983 Jan 1984, Revs reflect values rezeroed from beginning of commercial operation, per NUREQ-0020.
 - Values rezeroed from deginning of tommercial operation, per NURCO-0020. HAYNES, J Q Southern California Edison Co B4/03/15 Office of Resourcs Management, Director 1p R2685 001 24X Fiche 50-361.84/03/15.8403200053
- --8403200057 Monthly operating repts for Feb 1984 MORRIS, C A Bouthern California Edison Co 84/02/29 10pp. 22685 002 24X Fichs 50-361,84/03/15,8403200053
- --8403200074 Revised monthly operating repts for Jan 1984, MORRIS, C A Southern California Edison Co. 84/01/31. 4pp 22685 012 24X Fiche 50-361,84/03/15,8403200053
- --8403200077 Revised monthly operating rept for Dec 1983 MORRIS, C A Bouthern California Edison Co 83/12/31 3pp. 22685 016 24X Ficher 50-361,84/03/15,8403200053
- --8403200082 Revised monthly operating rept for Nov 1983 MORRIB.C A Bouthern California Edison Co 83/11/30 3pp 22685 019 24X Fichs 50-361,84/03/15,8403200053
- --8403200086 Revised monthly operating rept for Oct 1983, HORRIB, C A Bouthern California Edison Co 83/10/31 3pp 22685 022 24X Fichs, 50-361,84/03/15,8403200053
- --8403200088 Revised monthly operating rept for Sept 1983 MORRIS, C A Bouthern California Edison Co 83/09/30. 3pp 22485 025 24X Fiche 50-361.84/03/15.8403200053
- --8403200091 Rsylsed monthly operating rept for Aug 1983 MORRIS,C A Bouthern California Edison Co 83/08/31. 3pp. 22685 028 24X Fiche 50-361,84/03/15,8403200053.
- 8403230074 Forwards auxiliary feedwater sys monthly outage rept for 840i16-02i5.including 840i12.i4 & 15 outages.omitted from last months rept, per License Condition 2. C(26) Next rept ull1 cover period 8402i6-03i3.
 MEDFORD.M D Southern California Edison Co. 84/03/20 KNI9HTON.0 W Licensing Branch 3 3pp 22726-330 24X Fiche 30-36i.84/03/20.8403230074

- 8 Reportable occurrences, LERs & related correspondence
- 82i201030i Diecusses 8203i4 lose of shutdown cooling when low pressure earsty injection (LPSI) pumps became nitrogen bound IE info notice re gas binding of LPSI pumpe while backfluehing purification filter should be issued CINTULA, T C Reactor Operations Analysis Branch 82/i1/24 BEYFRIT, K V Reactor Operations Analysis Branch 9pp 22775 238 24X Fiche 50-361,82/11/24,8212010501
- 8403010451 Informe Commission of problems w/emergency diesel generatore mfg by Transemerice Deiaval, Inc DIRCKB.W.J Office of the Executive Director for Operations SECY-83-034 84/01/25 4pp 22438 347 24X Fichs 50-000.84/01/25.8403010451
- 8403210032 Pert 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpei NPS-4 T&T valves to close Enci ltr dtd 840203 sent to listed utils. GE notified of affected units in RWR plants
 THERDUX.R R Terry Corp 84/02/22 WOODRUFF.R W Director's Office, Office of Inspection end Enforcement 6pp 22706 327 24X Fichs 50-000.84/02/22.8403210032
- 8403150074 Revised special rept.on 830712. Channels 1.7 & 12 discovered inoperable during 31-day channel functional testing per Surveillance Procedure 8023-II 1 13 Caused by sensor probes becoming detached from reactor vessel bottom HAYNES, J & Southern Californie Edison Co 84/02/23 MARTIN, J B Region 5. Office of Director 2pp 22641 049 24X Fiche, 50-361, 84/02/23, 8403150074
- 8403050003 LER 84-002-00 on 840130-0203, containment purge isolation eye spuriously actuated Caused by electrical noise spike on train E containment sirborne monitor 2RT7807 Use of addl euppression circuit being investigated W/840228 ltr HAYNES, J 0 Bouthern California Edison Co 84/02/28 3pp 22470 237 24X Fichs 50-361,84/02/28,84030800003
- 8403060378 LER 84-006-00 on 840103, spurious toxic gas isolation systemations occurred Caused by toxic gas isolation eys setpoint set at threshold level of detection Tech Specs revised to raise setpoint requirements. W/840228 ltr HAYNEB, J G Southern Californie Edison Co 84/02/28 3pp 22511,327. 24X Fichs. 50-361,84/02/28,8403060378
- 8403060403 LER 84-001-00. on 840111, preparation of updated fire hazards analysis resulted in 91 nonconformence repts (NCR) re fire protection program deficiencies Compensatory measures established NCR dispositions planned W/840228 itr HAYNES, J 9 Southern California Edison Co 84/02/28 9pp 22518.283 24X Fichs 50-361.84/02/28,8403060403
- 8403150033 LER 83-143/03L-O on 830316, inubber on 8-Inch demineralized water makeup & transfer line between condensate storage tanks discovered frozen Caused by internal damege, Snubber replaced on 840328 M/840228 ltr.

 MAYNES, J O Southern California Edison Co 84/02/28 MARTIN, J B Ragion 5, Office of Director, 4pp 22641 006 24X

 Fiche 50-361,84/02/28,8403150033.
- 8403060215 PNO-V-84-011 on 840221, reactor trip breaker 8 undervoltage device inoperable Caused by metal shevings in one control room manual reactor trip pushbutton. On 840228, four leads in plant protection sys cabinets found disconnected GANTER: H Region 5, Office of Director. 84/02/29 1p. 22517 230 24% Fiche. 50-361, 84/02/29, 8403060215
- 8403150057 LER 84-005-00 on 840127, while in Mode 5, w/purge/vent stack wide-rangs monitor 3RY-7865 & flow rate monitor out of svc for installation of noise suppression circuit, flow rate estimates not performed as required W/840301 ltr HAYNES, J Q. Southern California Edison Co 84/03/01 3pp 22641:359 24X Fiche. 50-361,84/03/01,8403150057
- 8403120069 Updated PND-V-84-011A discovered manual pushbutton not inoperable as result of metal shavings in contacts Only operability of undervoltage trip on RTB-8 affected Source of metal flakes undetermined DDDBR T. Region 5. Office of Director 84/03/05 1p. 22586 288 24X Fiche.80-361.84/03/05.8403120069.
- 8403120064 LER 84-007-00 on 840203 & O4. Train A & B main steam isolation sys spuriously actuated on low pressure signal from E-088 Caused by voltage fluctuation resulting from electrical realignments. testing & maint W/840305 ltr HAYNEB, J G. Bouthern California Edison Co 84/03/05. 3pp 22586, 287 24X Fiche 50-361, 84/03/05, 8403120064

- 9403190376 PNS-V-84-004 on 840314, licensee notified that results of chemical tests performed on contractor employees suspected of posseession or use of controlled substances while onsite indicated positive in two of four tests SCHMAN, C A , NORDERHAUGL R Region 5, Office of Director 84/03/15 1p 22675 218 24X Fichs 50-206.84/03/15.8403190376
- 8403200194 LER 84-009-00 on 840214.analysis of etartup test data established calculated thermal power calculated by core protection calculators may become decalibr relative to secondary calorimetric power Procedure changed W/840315 1tr HAYNES.J O Southern California Edison Co 84/03/15 3pp 22686 336 24X Fiche 30-36184/03/15.8403200194
- 8403280002 LER 94-011-00 on B40225, containment purge leoletion eye actuated when containment airborne monitor 2RE-7804 gaseous Channei C failed Caused by water in gaseous detector cell, ehort circuiting pre-amp Water removed W/B40322 ltr HAYNES, J G Bouthern Cailfornia Edison Co B4/03/22 3pp 22777 i52 24X Fiche 50-361,84/03/22,8403280002
- X Onsite Storage of Low Level Weste
- 8403060363 Forwarde program description for waste classification & form to be used to implement 100FR61 & 100FR20 311 requirements re land disposal of radwaste & stde for protection from radiation
 MEDFORD,M O Southern California Edison Co 84/03/02
 EISENHUT.D G Division of Licensing Spp 22518 207 24X
 Fiche 50-206,84/03/02.8403060363
- DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3
- F. Becurity, medical, emergancy & fire protection plans
- 840203033B Forwards revised "Emergency Plan Implementing Procedures. San Onofre Nuclear Generating Station.Units 1,2 & 3 " CROY.P A Southern California Edleon Co 84/01/27 NRC - No Detailed Affiliation Given ip 22064 013 24X Fiche 50-206,84/01/27,840203033B
- --8402030344 Revised "Emergency Plan Implementing Procedures, San Onofre Nuclear Generating Station, Units 1,2 & 3 " ANDERBON, C K , FATRISSI, G A Southern California Edleon Co 84/01/27 525pp 22064 015 24X Fiche 50-206, 84/01/27, 8402030338
- 8403050148 Forwarde "Evaulation of Bouthern California Edieon Site-Bpecific Offeite Radiological Emergency Preparedness Prompt Alert & Notification 8ys Evaluation " Sys adequate to alert & notify public in event of accident SPECK.8 W Federal Emergency Management Agency. 84/01/31 DIRCKS, W J Office of the Executive Director for Operatione is 22487:314 24X Fiche 50-206.84/01/31,8403050148
- --8403050172 "Eyaluation of Southern California Edison Site-Specific Offsite Redialogical Emergency Preparedness Prompt Alert & Notification Sys " * Federal Emergency Menagement Agency 84/01/05 6lpp 22487 315 24X Fiche 50-206/84/01/31/8403050148
- 8403150031 Reve to emergency pian implementing procedures, including EPIP 80123-VIII-0 202, "Assignment of Emergency Response Personnel" & 8023-VIII-1, "Recognition & Classification of Emergencies" W/840227 itr
 BENNETT, D D , PEACOR, D H , CROY, P A Bouthern Californie Edison Co 84/02/15 48pp. 22443 207 24X Fiche 50-204,84/02/15,8403150031
- 8402230176 Forwards revised State of CA nuclear power plant emergency response plan MEDFORD, M O. Southern California Edison Co 84/02/16 EISENHUT, D O. Division of Licensing 2903pp. 22353 001 24X Fichs 50-000,84/02/16.8402230176
- --8403020117 Revised State of CA nuclear power plant emergency response plan * California, State of 83/04/30 2901pp 22353 003 24X Fiche 50-000,84/02/16,8402230176

- 8403050127 Forwards exemption from 10CFR50, App E. Section IV F 1 re requirement for state & local participation in annual amergancy plan exercise scheduled for 840229 EISENBUT, D 0 Division of Licensing 84/02/29 BASKIN, K P Bouthern Gilifornia Edison Co 3pp 22487 165 24X Fiche 50-206.84/02/29,8403050127
- --B403050132 Exemption from iQCFR50. App E. Section IV F 1 re requirement for state & local participation in annual emergency plan exercise scheduled for 840229 MRAQLIA.F J Division of Licensing B4/02/29 Southern California Edison Co 3pp 22489 168 24% Fiche 50-204.84/02/29. B403050127
- 8403120184 Forwards IE Safeguards Insp Rapts 50-361/84-03 & 50-362/84-03 on 840124-25 No noncompliance noted NORDERHAUGLER Region 5, Office of Director 84/03/06 HCCARTHY.C B Bouthern California Edison Co 2pp 22586 255 24X Fichs 50-361/84/03/06/8403120184
- --8403120185 IE Safeguards Insp Repts 50-361/84-03 & 50-362/84-03 on 840124-25 No noncompliance or deviations noted Major areas inspected organization, operation, shipping & receiving & records & repts Details withheld (ref 100FR2 790) HIEDER, A V Region 5, Office of Director 84/03/05 ip 22586 257 24X Fiche 50-361,84/03/06,8403120184
- 8403270256 Forwards Ray 12 to physical security plan Rev withheld (ref 10CFR73 21)
 HAYNES, J G Southern Celifornia Edison Co 84/03/07 MARTIN, J B Region 5. Office of Director 2pp 22772 031. 24X
 Fiche 50-206/84/03/07.8403270256
- 8403200097 Informs that emergency operations facility HVAC control logic mod & procedures nacessary to implement HVAC isolation completed prior to 840229 commitment date MEDFORD, M O Southern California Edison Co 84/03/14 EISENRUT. D O Division of Licensing ip 22699 093 24X Fiche 50-206,84/03/14.8403200097
- 8403220018 Forwards "Updated Fire Hazards Analysis, Vols 1-4"
 BABKIN, K.P. Southern California Edison Co. B4/03/19. DENION, H.R.
 Office of Nuclear Reactor Regulation, Director 10pp. 22735-238
 24X Fichs 50-206, 84/03/19, 8403220018
- --0403220027 "Updated Fire Hexards Analysis.vois 1-4"

 * Bouthern Californie Edition Co 84/03/19 1178pp 22735 341
 24% Fiche 50-206,84/03/19,8403220018
- 8403270205 Discusses Southern California Edison submittal of 1983 revised State of CA smergency response plan on behalf of all Stats of CA plants, incorporating plan into Diablo Canyon Addl planning (nfo will not be developed for Humboldt Bay SCHUYLER, J O Pacific Cas & Electric Co 84/03/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 22772 137 24% Fiche. 50-000.84/03/22.8403270205

H General correspondence

- 8403160063 Requests that HB Stockr be removed from distribution list & that L Bernath be added HULBEY-S A San Diego Cas & Electric Co 84/03/12 EISENHUT, D O Division of Licansing 1p 22655 083 24x Fiche 50-206,84/03/12,8403160063
 - Insurance & indemnity information
- 1403040395 Forwards Endorsements 100 & 88 to NELIA Policy NF-146 & MAELU Policy MF-38, respectively ROCCO, J Southern California Edison Co 84/02/29 DINITZ, 1 Office of Nuclear Reactor Regulation, Director 3pp 22518 152 24X Fiche 50-204,84/02/29,8403060395
- Operating license stage documents & correspondence
- 403010117 Partial response to FOIA request for documents by named individuals re repts, analyses, studies, procedures & sys for measurement of RCB leakage App B documents placed in PDR App A documents already available in FDR Search continuing FELTON. J M Division of Rules and Records 84/01/25 MADDEN, T J Kaye, Scholer, Fleman, Hays & Hendler 7pp 22480 026 24X Fiche 50-000,84/01/25,840301017
- -8403010233 Discusses RCS leak rate calculations, per 820504 telcon Mods to RCSLK7 computer program permit leak rate calculations for pressures Setween 1:700 & 2:100 psig w/tamp between 260 F & 270 F Piant data encl MCRRILLP J Region 5. Office of Director 82/05/05 MCCDRUFF.R W Reactor Engineering Brench 17pp 22481 362 24X Piche 50-000,84/01/25.8403010117

- B403020072 Application for amend to Licenses NPF-10 & NPF-15, changing Tech Spec Table 3 3-2, "Reactor Protective Instrumentation Response Times," to incorporate penalty factor MEDFORD, M O Bouthern California Edison Co 84/02/29 KNIGHTON, O W Licensing Benech 3 7pp 22442 279 24X Fiche 50-361.84/02/27,8403020092
- --8403020098 Proposed Tech Spacs, changing Table 3 3-2, "Reactor Protective Instrumentation Response Times" + Bouthern California Edison Co 84/02/29 15pp 22442 306 24X Fiche 50-361.84/02/29,8403020092
- 8403060424 Application for amend to Licentes NPF-10 & NPF-15, revising Tach Space re radiation & radioactive effluent monitoring instrumentation & radiological environ monitoring program MEDFORD, M O. Southern California Edison Co 84/03/02 Office of Nuclear Reactor Regulation, Director KN10HTON, 9 W Licensing Branch 3 3pp 22507 154 24X Fichs 50-361.64/03/02,8403060424
- --8403060427 Proposed Tech Spacs revising radiation & radiosctive effluent monitoring instrumentation & radiological environ monitoring program + Bouthern California Edison Co 84/03/02 256pp 22507.157 24X Fichs 50-361.84/03/02.8403060424
- 8403070177 Forwards application for Amend 24 to License NPF-10 & Amend 10 to License NPF-15. Amends revise Tech Spec 4.8 1 i 2 C relevel of insolubles in diesal fuel oil & Section 6 re organizational changes BASKIN.K P Southern California Edison Co 84/03/07. DENYON, H R Office of Nuclear Reactor Regulation. Director 2pp 22571.247. 24X Fiche 50-361.84/03/07, 8403090177
- --8403090227 Application for Amend 10 to License NPF-15, revising Tech Spec 4 B i 1 2 C to determine operability of dissel generator should dissel fuel oil fail to mest test for insolubles & revising Section 6 re organization changes BASKIN.K P Southern California Edison Co B4/03/07 10pp 22571 249 24X Fiche: 50-361,84/03/07,8403090177.
- --B403090230 Proposed ravs to Tech Spec 4 8 1 1 2 C to determine operability of distal generator should distal full oil fail to maet test for insolublas & proposed revs to Saction 6 re organizational changes # Bouthern California Edison Co 84/03/07 115pp 22571 259 24X Fiche 50-361,84/03/07,8403090177
- 8403270370 Notification of B40308 meeting w/util in Bethesda.MD to discuss turbine missile probabilities & turbine overspeed protection Tech Spec. Agenda enct RODD-H ticensing Dranch 3 84/03/07 KNIGHTON, 0 W Licensing Branch 3 4pp 22787 331 24X Fichs 50-361,84/03/07,8403270370
- 8403290331 Informs that NUREQ-0737. Item II K 2.17. "Voiding in RCB During Translents" complete based on util endorsement of CEN-197. "Effects of Vessel Head Voiding During ."
 KNIGHTON, O W Licensing Branch 3 64/03/08 BASKIN, K P. Bouthern California Edison Go HOLCHME, J. C Ben Diego Qas & Electric Co. 7pp 22822 220 24% Fichs 30-361.84/03/08,8403290331
- 8403130134 Informs that equipment requiring environ qualification reviewed for potential age-related degradation.per NRG 820830 ltr & replacement schedules incorporated into maint program MEDFORD.M O Southern California Edison Co 84/03/09 KNIGHTON.O W Licensing Branch 3 1p 22601 023 24X Fiche 50-361.84/03/09.8403130134
- 8403160013 Forwards "Evaluation of Natural Circulation Cooldown Test Performed at Ban OnoPre Nuclear Generating Station " Rept provides evaluation of applicability of results to St Lucie Unit 2 WILLIAMS.J W. Florida Power & Light Co. 84/03/13 EISENHUT, D O Division of Licensing ip 22652 179 24X Fiche 50-000,84/03/13, 8403160013
- B403190345 Forwards clarification of previous responses to NRC Questions B, 9, 12 & 13 re discharge piping mys & "EPRI PWR Bafaty & Reliaf Valve Test Program Guide " Info satisfies requirements of TMI Item II D 1 MEDFORD, M O Southern California Edison Co. B4/03/14 KNIGHTON, 0 W Licensing Branch 3 11pp, 22675-079, 24X Fiche 50-361,84/03/14,8403190345.
- B403290217 Requests exemption from 10CFR70 24 requiring meint of accidental criticality radiation monitoring sys. Evaluations determined potential for criticality for new & spent fuel nonexistent, based on geometric specing.
 MEDFORD, M D Bouthern California Edison Co 84/03/27.
 KNIGHTON, O. W. Licensing Reach 3 4pp. 22803 284 24X Fiche 50-361,84/03/27,8403290217

- O Inspection reports. IE Bulletins & correspondence
- B4030B0408 FOIA request for repts of insp carried out under Condition 2 of Nuclear Energy Liability policies for facilities CALBOYAB, C D Affiliation Not Assigned B4/02/07 Region 5, Office of Director 4pp 22567 341 24X Fiche 50-000,84/02/07, 84030B0408,
- 84030A0025 Forwards IE Insp Repts 50-204/83-28.50-361/83-43 & 50-362/83-42 on 831210-840121 No noncompliance noted BISHOP.T W Division of Resident Reactor Project & Engineering Programs 84/02/09 BABKIN.K P Southern Cailfornia Edison Co 2pp. 22516-285 24X Fiche 50-206.84/02/09.8403060025
- ---B403060027 IE Insp Repts 50-206/83-28,50-361/83-43 & 50-362/83-42 on B31210-840121, No noncompliance or deviations noted Major areas inspected operational safety verification, power ascension transient testing & maint activities GHAFFEE, A E , BTEWART, J P , D'ANGELO, A Region 5, Office of Director 84/02/07 13pp 22516 287 24X Fiche 50-206,84/02/09,8403060025
- 8403060008 Forwards IE Insp Repts 50-206/84-02,50-361/84-02 & 50-362/84-02 on 840115-20 No noncompliance noted WENBLAMEKIF A Region 5, Office of Director, 84/02/16 848KIN,K B. Bouthern California Edison Co 2pp 22516 268 24X Fiche: 50-206,84/02/16,8403060008
- ---8403060019 IE Insp Repts 50-206/84-02,50-361/84-02 & 50-362/84-02 on 840115-20 No noncompliance or deviations noted Major areas inspected radiation protection program health physics & chemistry training & general employee training EHERMAN.G. I. WENBLAWBKI,F A Region 5. Office of Director 84/02/15, 15pp 22516.270 24X Fiche 50-206.84/02/16.8403060008
- B403080419 Responds to FDIA request for repts of insp carried out under Condition 2 to Nuclear Energy Liability policies for facilities NRC does not have repts FELTON, J.M. Division of Rules and Records 84/02/22 CALSOYAS, C.D. Affiliation Not Assigned ip 22567 345 24X Fiche 50-000,84/02/22,8403080419
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Matar Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Poet 830103), 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403190367 Forwards IE Insp Repts 50-206/84-04,50-361/84-05 & 50-362/84-05 on 840123-27 No noncompliance noted MEMBLAHBKI,F A. Region 5, Office of Director 84/03/01 BABKINK B Bouthern California Edison Co 2pp 22675 220 24X Fiche 50-206,84/03/01,8403190367
- --8403190373 IE Insp Repts 50-206/84-04, 50-361/84-05 & 50-362/84-05 on 840123-27 No noncompliance noted Major areas inspected radiological environ monitoring program & followup on licensee action re previous insp findings YUHAS.0 P. WENBLAWSKI,F A Region 5, Office of Director 84/03/01 6pp 22675-222 24X Fiche 50-206,84/03/01,8403190367
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDY & NRC." Svc list enc1 GRACE.J. Division of QA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc 130pp. 22552 329 24X Ficher 50-000/84/03/02,8402090007.
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate." Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) * 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553:098 24X Fiche: 50-000, 84/03/02, 8402090008
- E402090009 IE Info Notice 84-15, "Reporting of Radiological Releases "
 Svc list encl.
 JURDAN, E.L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/03/02 Consolidated Edison Co of New
 York, Inc 119pp. 22553 217 24X Fiche. 50-000, 84/03/02, 8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche: 50-000, 84/03/05, 8402090011
- 8403120184 Forwards IE Bafeguards Insp Repts 50-361/84-03 & 50-362/84-03 on 840124-25 No noncompliance noted NORDERHAUGIL, R. Region 5. Office of Director 84/03/06 MCCARTHY, C. B. Bouthern California Edison Co 2pp 22586, 255 24X Fichs: 50-361,84/03/06,8403120184.

- --B403120185 IE Safeguards Insp Repts 50-361/84-03 & 50-362/84-03 on 840124-25 No noncompliance or deviations noted Major areas inspected organization. operation shipping & receiving & records & repts Details withheld (ref IOCFR2 790) MIEDER, A V , NORDER, AUGUL Region 5, Office of Director 84/03/05 ip 22586 257 24% Fiche 50-361/84/03/06/8403120184
- 8402090024 IE Info Notice 84-09.Rev 1. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Bys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc liBpp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- B40207002B IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8403090127 Responds to IE Bulletin 83-08 re electrical circuit breakers w/undervoltage trip feature used in applications other than reactor trip sys No circuit breakers utilized in safety-related applications Bulletin inapplicable MEDFORD.M O Bouthern California Edison Co 84/03/07 MARTIN, J 8 Region 5, Office of Director ip 22975 340 24X Fiche 50-361.84/03/07.8403090127
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys." Svc list encl
 DEYOUNG/R C Director's Office. Office of Inspection and
 Enforcement 84/03/12 Consolidated Edison Co of New York
- 8402090043 IE Infa Notice 84-19. "Two Events Involving Unauthorized Entries into PHR Reactor Cavities " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21.8402090043
- B402090D44 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list encl JDRDAN, EL Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- B403230110 Responds to Itams 1 & 4 of IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller. Inc " No evidence found to indicate that any vendor malls provided to or used at facilities KRIEGER. R W Bouthern California Edison Co. 84/03/21 MARTIN, J B Region 5. Office of Director 2pp 22730 159 24X Fiche 50-361.84/03/21.8403230118
- R Periodic operating reports & related correspondence
- 8403060438 "Annual Personnei Monitoring Rept, 1983 " W/840229 ltr MAYNES, J O Southern California Edison Co 83/12/31 4pp 22511 189 24X Fiche 50-206,83/12/31,8403060438
- 8403020010 Monthly operating repts for Jan 1984 W/840213 ltr MORRIB.C A. HAYNES, J G Southern California Edison Co 84/01/31 12pp. 22442 223 24% Fiche 50-361.84/01/31.8403020010
- B403020040 Forwards auxiliary feedwater sys monthly outage rept for B31216-840115, per License Condition 2 C(26) MEDFORD. M D Southern California Edison Co B4/02/29 KNIGHTON. O W Licensing Branch 3 3pp 22442 269 24X Fiche 50-361.84/02/29.8403020040
- 8403200053 Forwards monthly operating repts for Feb 1984 & revised monthly operating repts for Aug 1983 Jan 1984 Revs reflect values reserved from beginning of commercial operation, per NURED-0020 HAYNES, J G Southern California Edison Co 84/03/15 Office of Resource Management, Director ip 22685 001 24X Fiche: 50-361, 84/03/15, 8403200053
- --B403200057 Monthly operating repts for Feb 1984, MORRIB.C A Southern California Edison Co B4/02/29 10pp 226B5 002 24X Fiche 50-361.84/03/15.8403200053
- --8403200074 Revised monthly operating repts for Jan 1984 MORRIS:C A Bouthern California Edison Co 84/01/31 4p 22685 012 24X Fiche 50-361,84/03/15,8403200053

- 8403230074 Forwards auriliary feedwater sys monthly outage rept for 840116-0215, including 840112.14 & 15 outages, omitted from last months rept,per License Condition 2 C(R6) Next rept will cover period 840216-0315
 HEBFORD.H B Southern California Edison Co 84/03/20
 KNIGHTON.G W Litensing Branch 3 3pp 22726 330 24X
 Fichs 30-361.84/03/20,8403230074
- 5 Reportable occurrences, LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diessl generators mfg by Transamerica Dalavat, Inc DIRCKS, K J Diffice of the Executive Director for Operations SECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000.84/01/25, B403010451
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpel NPS-4 TMT valve to close Enci ltr dtd 840203 sent to listed utils GE notified of affected units in BMR plants
 THERRUX.R R Tsrry Corp 84/02/22 WOODRUFF, R W Director's Office, Office of Inspection and Enforcement 6pp 22706 327 24X Fiche 30-000.84/02/22.8403210032
- 8403060215 PND-V-84-011 on 840221. reactor trip breaker 8 undervoltage device inoperable Caused by metal shavings in one control room manual reactor trip pushbutton On 840228, four leads in plant protection eye cabinets found disconnected CANTER, H Region 5, Office of Director 84/02/29 ip 22517 230 24% Fiche 50-361,84/02/29,8403060215
- 8403200175 Discusses 840217 immediate notification that ESF actuated, por 10CFR50 72(b)(2)(ii) Power supply failure did not result in semrgency feedwater actuation sys channel trips No LER rept written, per NUREG-1022

 HAYNES, J G Southern California Edison Co 84/03/12 Record Services Branch (Document Control Dest) 2pp 22699 325 24X

 Fichs 50-362.84/03/12.8403200175
- 8403190374 PNS-V-84-004 on 840314, licensee notified that results of chamical tests performed un contractor employees suspected of possession or use of controlled substances while onsits indicated positive in two of four tests 8CH4AN.C A Region 5. Office of Director 84/03/13 ip 22675 216 24% Fiche 30-206.84/03/15.8403190376
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV, 500-750 MVA, 5 kV 390-3, 600 & all HKV circuit breaters initially reported on B30223 Addenda to installation & maint procedures sent to affected units DUVALL, D D Brown Boveri Corp (subs of Brown Boveri & Co. Ltd.) 84/03/19 Record Services Branch (Document Control Dssk.) 5pp 22772 114 24X Fiche 50-000, 84/03/19, 8403270219
- 8403270164 LER 84-004-00 on 840222 three safety injection pumps started & injected 150 gailons of water into RCS Caused by dirty contacts on relay hold pushbutton Contacts cleaned W/840322 ltr.

 MAYNES, J D Bouthern California Edison Co 84/03/22 Jpp 22766 025 24% Fichs 50-362,84/03/22,8403270164
- X Onsite Storags of Low Level Waste
- 3403060363 Forwards program description for waste classification & form to be Usset to implement 10CFR61 & 10CFR62 311 requirements re land disposal of radwaste & stds for protection from radiation
 MEDFORD N O Southern California Edison Co 84/03/02
 EISENHUT.D O Division of Licensing Bpp 22518 207 24X
 Fichs 50-206.84/03/02.8403060363
- OCCHET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2 F Security, medical, emergency & fire protection plans
- 8403140212 Public version of Rev 28 to Emergency Plan Implementing Procedure FNP-D-EIP-008, "Syc Bldg Talephone Directory " W/830705 itr & JM Felton 840312 rsigase memo HUDSPETH.J B Alabama Power Co 63/07/01 77pp 22638 157 24X Fiche 50-348,83/07/01.8403140212
- 8403140210 Public version of Rev 4 to Emsrgency Plan Implementing Procedure GO-EIP-111. "Corporate Activation & Notification Procedures" "H/931022 ltr & JM Feiton 840312 release mamo CLAYTON-F.L., MCGOWAN.J & Alabama Power Co 83/10/25, 82pp 22639 237 24X Fiche 50-348,89/10/25,8403140210.

- 8403090303 Public version of duty roster for First Quarter 1984, reflecting nuclear generation dspt on call smergency positions & public info site coordination position W/ JM Feiton release memo 01850N/M D Alabama Power Co 83/12/22 4pp 22584 342 24x Fiche 50-348.83/12/22,8403090303
- 8403280198 Public version of 1984 emergency on-call coverage schedulss, as part of Emergency Plan Implementing Procedure GD-EIP-111 W/840106 itr & JM Feiton release memo RGBERTS R O Albama Power Co 83/12/29 15pp 22808 228 24X Fiche 50-348,83/12/29,8403280198
- 8403280109 Public version of temporary change notices for smergency plan impliamenting procedures, including Procedure CD-EIP-101 re nuclear generation dept corporate emergency operation W/840126 ltr & JM Felton 840322 releass memo OIBSUN M D : MUDD.C H Alabama Power Co 84/01/26 20pp 22812 001 24X Fiche 50-349.84/01/26.8403280109
- 8402130400 Forwards 1E Safequards Insp Repts 50-348/84-02 & 50-364/84-02 on 840116-20 No violations noted VERRELLI.D M Division of Project & Resident Programs 84/02/08 MCDDNALD.R P Alabams Power Co 2pp 22203 251 24X Fiche 50-348,84/02/08,8402130400
- ~-B402130404 IE Bafsguards Insp Repts 50-348/84-02 & 50-364/84-02 on B40116-20 No violations noted Major areas inspected security organization, testing & maint & physical barriers Details withheld (ref 10CFR2 790 & 73 21) MODRE, D. & Region 2, Offics of Director B4/02/02 1p 22203 253 24X Fichs 50-348,84/02/08,8402130400
- 8403160142 Forwards IE Insp Rspts 50-348/84-01 & 50-364/84-01 on 840118-19 No violations or deviations identified VERRELLI,D M Division of Project & Rssident Programs 84/02/15 MCDDNALD,R P Alabama Power Co 2pp 22655 325 24X Fiche 50-348,84/02/15,8403160142
- --8403160146 IE Insp Repts 59-348/84-01 & 50-364/84-01 on 840118-19 No violations or deviations noted Major areas inspectsd emergency prepsredness area of protective action decisionmaking CLINE, W Replon 2, Office of Director 84/02/15, 4pp 22655 327 24X Fiche 50-348,84/02/15,8403160142
- B403270019 Forwards IE Insp Repts 50-348/84-04 & 50-364/84-04 on B40131-0202 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/02/29 MCDDNALD,R P Alabams Power Co 2pp 22806 209 24X F1che 50-348,84/02/29,8403290019
- --B403270027 IE Insp Repts 50-348/84-04 & 50-344/84-04 on 840131-0202 No violations or deviations noted Major areas inspected emergency exercise DECKER, T R Region 2, Office of Director 84/02/27 7pp 22806 211 24X Fichs 50-348.84/02/29,8403290019
- 8403080077 Forwards add1 fees for applications for fire protection reviews & approvals CLAYTON.FL Alabama Power Co 84/03/01 MILLER.W II License Fee Management Branch 1p 22559 257 24X Fichs 50-348,84/03/01,8403080077
- 8403160354 Notifies of fire protection workshop on 840316 in Region II ofc to discuss questions or App R requirements & results of recent App R Insps
 LEWIS.R C Division of Project & Resident Programs 84/03/02 MCDONALD.R P Alabama Power Co ip 22660 192 24X
 Fichs 50-348-84/03/02-8403160354
- 8403280329 Forwards comments on detailed control room design revisw program plan,per 831031 submittal Plan does not comply fully w/8uppl 1 to NUREQ-0737 requirements, Recommends meeting in Mar or Apr 1984 VARCA:8 A Operating Reactors Branch 1 84/03/09, CLAYTON:F L. Alabama Power Co 17pp 22807 R88 24X Fichs 50~348,84/03/09, 8403280329
- 8403270078 Ack recsipt of 840308 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/84-03 & 50-38/94-03 VERRELLI,D M Division of Project & Resident Programs 84/03/14 MCDDNALD,R P Alabama Power Co ip 22806 Sii 24X Fiche 50-348,84/03/14,8403270078
- --8403270103 IE Insp Rapts 50-348/84-03 & 50-364/84-03 on B40111-0205 Violation found failurs to implement procedures for control of maint activities BRAPGRD.W H Region 2, Office of Director. 84/02/15 Epp. 22806 317 24X Fiche 50-348.84/03/14.8403270078

J Insurance & indemnity information

- 8403060448 Forwards Endorsement 98 to NELIA Policy NF-238 DUCK.JR Marsh & McLennan. Inc 84/02/28 SALTZMAN.J Director for State & Licensee Relations 2pp 22518 220 Fiche 50-348.84/02/28.8403060448
- 8403140044 Forwards Endorsement 4 to NELIA Certificate N~13 correcting name of insured on Endorsements 2 & 3

 DUCKLUR Marsh & McLennan, Inc 84/03/05 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 22634 162 24X

 Pichs 50-348,84/03/05,8403140044
- B403280053 Forwards Endorsements 49 & 50 to MAELU Policy MF-93 & Endorsements 59 & 60 to NELIA Policy NF-238 DUCK, JR Mersh & McLennan, Inc 84/03/20 SALTZMAN, J Assistant Director for State & Licensee Relations 5pp 22777 Q01 24X Fiche 50-348,84/03/20,8403280053
- P Operating license stage documents & correspondence
- 8401120394 Forwards Amends 37 & 27 to Licenses NPF-2 & NPF-8, respectively & SER Amends allow operation w/slightly positive moderator temp coefficient at low power levels & increased hot channel factor limit below full power. REEVEB,E A Operating Reactors Branch i B3/12/30. CLAYTON,F L Alzbama Power Co 2pp. 21796.274 24X Fiche 50-348,83/12/30. B401120594
- --B40i120597 Amends 37 & 27 to Licenses NPF-2 & NPF-8, respectively, allowing operation w/slightly positive moderator temp coefficient at low power levels & increased hot channel factor limit below full power VARDA:8 A Operating Reactors Branch 1 83/12/30 18pp 21796 276 24X Fiche 50-348;83/12/30,8401120594
- --8401120600 Bafety evaluation supporting Amends 37 & 27 to Licenses NPF-2 & NPF-6, respectively * Office of Nuclear Reactor Regulation, Director. 83/12/30 4pp 21796 294 24X Fiche 50-348/83/12/30/8401120594
- 8403010117 Partial response to FDIA request for documents by named individuals re repts, analyses, studies, procedures & sys for measurement of RCS leakage App I documents placed in PDR App A documents already available in PDR Search continuing FELTON, J M Division of Rules and Records 84/01/25 HADDEN, T Kayes, Scholbr, Fierman, Hays & Handler 7pp 22480 026 24X Fiche 50-000, 84/01/25, 8403010117 HADDEN, T J
- --B011070522 Summerizes results of independent evaluations of primary sys leak rate & some considered extensions Extension of specific evaluations to all PWR facilities recommended Draft procedure re evaluations will be submitted by 800915 JORDAN.E L Division of Reactor Operations Inspections 80/08/21 MOSELEY.N C Division of Reactor Operations Inspections 11pp 22480 266 24X Fiche 50-000,84/01/25,8403010117
- --B403010127 Table of "Pressurizer Design Data " Related info encl # Alebama Power Co 84/01/25 46pp 22480 033 24X Fich# 50-000,84/01/25,8403010117
- 8403020186 Responds to util B30113 request for exemption from 10CFR20 reprotection factors for respirators Exemption would allow credit for radioiodine protection factor while employing MBA 466220 GMR-1 canister Review continuing VARQA, B A Operating Reactors Branch 1 B4/02/17 CLAYTON, F L Alabama Power Co 5pp. 22491 150 24X Fiche 50-34B,84/02/17, B403020156
- B403010210 Notification of B40228 meeting w/util in Bethesda. MD to review changes to licensing amend schedules for 1984 REEVES, E Operating Reactors Branch i B4702/22 VARGA, B A Operating Reactors Branch 1 2pp 22479 197 24X Fiche: 50-348, 84/02/22, 8403010210
- 8403070359 Notification of cancellation of 840228 meeting w/util in BathesdarMD to discuss proposed changes to licensing amend schadules for 1984. REEVEB.E. Operating Reactors Branch 1 84/02/22 VAROA B A Departing Reactors Branch 1 2pp 22564 145 24X Fichs. 50-348, 84/02/22, 8403070359
- 8403020440 Notification of 840308 meeting w/util in Bethesds.MD to discuss proposed changes to licensing amend schedules for 28 VARQA, B A 1994 REEVEB,E Operating Reactors Branch 1 84/02/28 Operating Reactors Branch 1 4pp 22491,200 24 Fiche.50-348,84/02/28,8403020440

- 8403i3003i Supplemental application for amend to Licenses NPF-2 & NPF-B. Changing Tech Specs 3/4 7 7 % 3/4 7 8 re control room emergency ventilation sys & penetration room filtration sys. respectively & deleting 3/4 7 14 re bypass piping CLAYTON, F L Alabama Power Co 84/03/01 VAROA, 8 A Office of Nuclear Results on Director Spp 22615 00; 24% Fiche 50-348,84/03/01,8403130031 Office of
- --B40313003B Proposed Tech Specs 3/4 7 % 3/4 7 8 re control room emergency ventilation sys & penetration room filtration sys, respectively * Alabama Power Co 84/03/01 14pp 22615 009 24X Fiche 50-348,84/03/01,8403130031
- B403;30455 Application for amend to Licenses NPF-2 & NPF-8, making Tech Specs administrative changes NSHC determination requested CLAYTON.F L Alabama Power Co B4/03/0i VARCA, S A Office of Nuclear Reactor Regulation, Director 2pp 22613 336 24X Fiche 50-348,84/03/0i,8403130455
- --8403130463 Proposed Tech Epecs, providing administrative changes # Alabama Power Co 84/03/01 iOpp 22613 338 24X Fiche 50-348, 84/03/01, 8403130455
- 840338008i Forwards corrections to Tech Spec pages for moderator temp coefficient at low power levels submitted 831013 which contained typographical errors CLAYTON,F L. Alabama Power Co. 84/03/02 VARGA,8 A. Office of Nuc
- --8403080086 Corrected Tech Spec pages for moderator temp coefficient at low power levels * Alebama Power Co 84/03/02 4pp 22559 259 24X Fiche 50-348.84/03/02.840308008i
- 8403080148 Forwards response to NRC 840104 request for addi info re util 831230 application for change to diesel generator/river water Tech Beecs CLAYTON.F L Alabama Power Co 84/03/02 VARGA,S A Operating Reactors Branch 1 8pp 22539 283 24X Fiche 50-348.84/03/02. B4030B0148
- 8403080138 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs re meteorological monitoring instrumentation Change includes air temp difference to conform w/STS CLAYTON,F L. Aiebama Power Co. 84/03/02 VARGA, & A. Office of Nuclear Reactor Regulation, Director 2pp 22559 145 24X Fiche 50-348,84/03/02.8403080158
- --84030B0193 Proposed changes to Tech Specs re meteorological monitoring instrumentation Change includes air temp difference to * Alabama Power Co 84/03/02 5pp 22559 147 24X Fiche 50-348, 84/03/02, 8403080158
- B403210195 Requests identification of any potential problems in completing NUREG-0737 items by Sept 1984 Response requested within 30 days of ltr receipt VAROA. B A Operating Reactors Branch i 84/03/02 CLAYTON.F L Alabama Power Co 2pp 22709 176 24X Fiche 50-348,84/03/02,8403210195
- 8403080272 Informs of delay in responding to 840217 request for additinform indication of the second request for additing the second request to 10CFR20. App A, footnote (c) to 5-month interval requested CLAYTON.F L. Alabama Power Co. 84/03/03 VAROA.8 A. Office of Nuclear Reactor Regulation, Director 1p. 22537 274 24X Fichs 50-348,84/03/05,8403080272
- 8403260326 Forwards corrected Tech Spec pages re reactor trip sys instrumentation setpoints contained in Amends 37 & 27 to Licenses NPF-2 & NPF-B, respectively, issued on 631230 REEVEB, E A Operating Reactors Branch i 84/03/08 CLAYTON,F Alabama Power Co 2pp 22775 276 24X Fiche 50-348,84/03/08, CLAYTON F L 8403260326
- --8403260327 Corrected Tech Spec pages to Amends 37 & 27 to Licenses NPF-2 & NPF-8, respectively, re reactor trip sys instrumentation setpoints * NRC No Detailed Affiliation Given 84/03/08 4pp 22775 298 24X Fiche, 50-348,84/03/08,8403260326
- B403260227 Application to amend Licenses NPF-2 & NPF-8, consisting of corrected Tech Specs incorporating positive moderator temp coefficient at low power levels & increased enthalpy hot channel factor limit below full power-per B31013 submittal CLAYTON, F L Alabama Power Co 84/03/22 VARGA, S A Office of Nuclear Reactor Regulation, Director ip 22756 072 24X Fiche 50-348.84/03/22,8403260227

- --8403260234 Corrected proposed Tech Specs incorporating moderator temp coefficient at you power levels & increased enthalpy hot channel factor limit below full power * Alabama Power Co 84/03/22 10pp 22756 073 24X Fiche 50-348,84/03/22,8403260227
- B403280037 Application for amend to Licenses NPF-2 & NPF-B, changing Tech Bpecs 3 6 i 7 & 4 6 i 7 2 re containment venting Valves will be used for safety-related applications of containment pressure & radiological control CLAYTON.F L Alabama Power Co 84/03/23 VARGA.8 A NRC No Detailed Affiliation Oliven 2pp 22777 013 24X Fiche 50-348.84/03/23.8403280037
- --8403283044 Proposed changes to Tech Specs 3 & 1 7 & 4 & 1 7 2 re containment vanting * Alabama Power Co 84/03/23 4pp 22777 017 24X Fiche 50-348,84/03/23,8403280037
- E403300077 Forwards suppl to 840319 hydrostatic testing relief request re-replacement of feedwater to steam generator noisis reducers Amend includes welding necessary to complete realignment of feedwater Line C
 CLAYTON F L Alabama Power Co 84/03/26 VAROA, S A Office of Nuclear Reactor Regulation. Director 3pp 22822 084 24X
 Fiche 50-348,84/03/26,8403300077
- O Inspection reports. IE Builetins & correspondence
- 8402130400 Forwards IE Safeguards Insp Repts 50-348/84-02 & 50-344/84-02 on 840116-20 No violations noted VERRELLI.D M Division of Project & Resident Programs 84/02/08 MCDONALD.R P Alabama Power Co 2pg 22203 251 24X Fiche 50-348.84/02/08.8402130400
- --8402130404 IE Sefeguards Insp Repts 50-348/84-02 & 50-364/84-02 on 840116-20 No violations noted Major areas inspected security organization, testing & maint & physical barriers Details withheld free iOCFR2 790 & 73 21)

 MODRE, D E Region 2. Office of Director MCGUIRE, D R Division of Emergency Preparedness & Matsrials Safety 84/02/02 ip 22203 253 24X Fiche 50-348,84/02/08,8402130400
- 8403160142 Forwards IE Insp Rspts 50-348/84-01 & 50-364/84-01 on 840118-19 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/02/15 MCDDMALD.R P Alabama Power Co 2pp 22655 325 24X Fiche 50-348.84/02/15.8403160142
- --8403160146 tE insp Repts 50-348/84-01 & 50-364/84-01 on 840118-19 No violations or dsviations noted Major areas inspected emergency preparedness area of protective action decisionmaking

 CLINE, W. Region 2. Office of Director JENKINS, G. R. Division of Emergency Preparedness & Materials 88fety 84/02/15 4pp 22655 327 24K Fiche 50-348.84/02/15,8403160142
- 8401190072 IE Info Notice 84-13. "Potential Deficiency in Mator Operated Valve Control Circuits & Annunclation " Svc list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. i15pp 22909 239 24X Fiche 30-000-84/02/28,8401190072
- B403040125 Forwards summary of identified technical evaluation rept deficiencies re environ qualification of safety-related electrical equipment defined by IE Bulletin 79-018 & NUREQ-0388, respectively Encl withheld (ref 100FR2 790) CLAYTON, F. Alabama Fower Co B4/02/29 VARGA, S.A. Office of Nuclear Reactor Regulation, Director 4pp 22519 036 24% Fithe 50-348,84/02/29,8403060125
- 23403270019 Forwards IE Insp Repts 50-348/84-04 & 50-364/84-04 on 840131-0202 No violations or deviations noted VERRELLI, D M Division of Project & Resident Programs 84/02/29 MCDONALD, R P Alabama Power Co 2pp 22806 209 24X Fiche 50-348.84/02/29,8403290019
- -8403290027 IE Insp Repts 50-348/84-04 & 50-364/84-04 on B40131-0202 No violations or deviations noted Major areas inspected emergency exercise
 DECKER.T R Region 2. Office of Director JENKINS, Q R. Division of Emergency Preparadness & Materials Safsty B4/02/27 7pp 22806 211 24% Fiche 50-348,84/02/29:8403270019
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of QA. Safeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000, B4/03/02, B402090007

- 8402090008 IE Info Notics 84-16. "Failure of Automatic Sprinklar Bys Valysk to Operate " Svc list encl JORDAN, E L Division of Emergency Preparedness & Enginesring Response (Post 830103) 84/03/02. Consolidated Edison Co of New York, Inc. 122pp 22553 078 24X Fichs 50-000.84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Relsases"
 Byc list enci
 JDRDAN, E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. i19pp 22559 217 24% Ficha 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Deiow Nil Ductility Temp " Svc list sncl JURDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403160257 Ack receipt of 840228 ltr informing NRC of steps taken to correct violations noted in IE Insp Rapts 50-348/83-33 & 50-348/83-31 LEHIS.R C Division of Project & Resident Programs 84/03/05, MCDONALD.R P Alabama Power Co ip 22660 280 24x Fiche 50-348,84/03/05.8403160257
- --B403i60265 Responds to NRC 840203 itr rs violations noted in IE Insp Repts 50-348/83-33 & 50-364/83-31 Corrective actions personnel counseled on importance of adhering to procedures CLAYTON.F L Alabama Power Co 84/02/28 LEWIS.R C Region 2, Office of Director 4pp 22660/281 24X Fichs 50-348,84/03/05, 8403160257
- --8403i60272 Forwards IE Insp Repts 50-348/83-33 & 50-364/83-31 on 83i112-840i10 & hotice of violation LEMIS.R C Division of Project & Resident Programs 84/02/03, MCDONALD, R P Alabama Powsr Co 2pp 22660 285 24X Fiche 50-348,84/03/05,8403160257
- --8403160277 Notics of violation from insp on 831211-840110, * Region 2. Office of Director 84/03/05 2pp 22660 287 24X Fichs 50-345,84/03/05,8403160287.
- --B403160284 IE Insp Rspts 50-348/83-33 & 50-364/83-31 on B31211-840110 Noncompliance noted failure to foliow procedures & failure to setablish corrective measures to insure svc water valve MCV 536 remained open to supply Train B BRADFORD, W H . RULAND, W H . Region 2. Office of Director CANTRELL.F S Division of Project & Resident Programs 84/01/30 10pp 22660.289 24X Fichs.50-348,84/03/05.8403160257.
- 8402070024 IE Info Notice 84-07. Rev i. "Lassons Larned From Insps of Fire Protection Safe Shutdown Bys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. Litapp 22635 049 24X Fiche 50-000,84/03/07,8402070024
- 8402090028 iE Info Notics 84-18, "Stress Corrosion Cracking in PWR 8ys " 8vc list encl JORDANAE L Division of Emsrgency Preparedness & Enginsering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- B40327031? Responds to IE Bulletin B3-07. "Apparently Fraudulent Products Bold by Ray Niller, Inc." Results of revise showed only Westinghouse supplied equipment utilizing Ray Miller components list of 30 vendors contacted encl.
 CLAYTON.F L Alabame Power Co B4/03/09 O'REILLY, J. P Region 2. Office of Director Spp 22802 067 24X Fiche 50-348.84/03/09, 8403270319
- 8402090031 IE Bullstin 84-02, "Failures of GE Type HFA Rslays in Use in Glass IE Bafety 8ys," 8vc list sncl.
 DEYOUND:R C Director's Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24% Fiche: 50-000,84/03/12,8402090031
- 8403270078 Act receipt of 840308 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/64-03 & 50-348/84-03 VERRELLI.D M Division of Project & Resident Programs. 84/03/14 MCDDNALD.R P Alabama Power Co ip 22806 311 24X Fiche 50-348.84/03/14.8603270078.
- --8403270084 Responds to NRC 840215 ltr re violations noted in IE Insp Rapts 50-348/84-03 & 50-364/84-03 Corrective actions responsible personnel instructed to implement procedures for control of maint activities CLAYTON.F.L Alabama Power Co 84/03/08 VERRELLI, D M Region 2, Office of Director 2pp 22806:312 24X Fiche 50-348, 84/03/14,8403290078

- --8403270087 Forwards 1E Insp Repts 50-348/84-03 & 50-364/84-03 on 840111-0205 & notice of violation VERRELLI.D M Division of Project & Resident Programs 84/02/13 MCDDNALD.R P Alabama Power Co 2pp 22806 314 24X Fiche 50-348,84/03/14,8403290078
- --8403290096 Notice of violation from insp on 84011i-0205 * Region 2. Office of Director 84/02/15 ip 22806 316 24X Fiche 50-348,84/03/14,8403290078
- --B403290103 IE Insp Repts 50-348/84-03 & 50-364/84-03 on 840111-0205 Violation found failure to implement procedures for control of maint activities BRADFORD W H , RULAND W H Region 2, Office of Director CANTRELL F B Division of Project & Resident Programs 84/02/15 Bpp 22806 317 24X Fiche 50-348,84/03/14,8403290078
- B402090043 IE info Notice 84-i9, "Two Events Invoiving Unauthorized Entries into PHR Reactor Cavities" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- B402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 133pp. #2733 001 24% Fichs 50-000,84/03/21,8402090044
- R. Periodic operating reports & related correspondence
- 8403300134 Monthly operating rept for Feb 1984 W/840314 1tr HAIRBTON, W G . CLAYTON, F L Alabama Power Co 84/02/29, 7pp 22820.001 24X Ficha 50-364,84/02/29,8403300134
- 8 Reportable occurrences, LERs & related correspondence
- B403010417 Forwards revised LER 84-002-01 & LER 84-003-00 CLAYTON, F L Alabama Power Co 84/02/27 Record Services Branch (Document Control Desk) ip 22434 019 24X Fiche 50-364,84/02/27,8403010417
- --8403010422 LER 84-003-00 on 840i30 reactor tripped due to iqu-low level in steam generator 2C Caused by closure of main feedwater regulating valve 2C due to instrumentation channel epiking low NLP card replaced HAIRBIDN H G. Alabama Power Co 84/02/27 2pp 22434 020 24X Fiche 50-364,84/02/27,84030i04i7
- --8403010428 Revised LER 84-002-01 on 840124, hourly firewatch patrol in train B auxiliary bldg battery charger room not performed at specifisd timee Caused by personnel error Personnel counselsd & firewatch patrol immediately performed HAIRBTON.H.Q Alabama Power Co 84/02/27 2pp 22434 022 24X Fiche 50-364,84/02/27,8403010417
- 8403240233 Forwards summary liet of deficiencies identified per IOCFR50 55(s). Part 21 & potential generic ltr repts for comments

 STAROSIECKI, R Division of Project & Recident Programs. 84/02/28
 Region i. Office of Director. 7pp 22756 065 24X
 Ficher 50-000,84/02/28,8403240233
- DOCKET 50-366 EDWIN I HATCH NUCLEAR PLANT, UNIT 2

 F Security, medical, emergency & fire protection plane
- 8403300339 Public version of transmittal & title pages of deleted Emergency Plan Implementing Procedures HNP-8019, "Inep of Steel Radwaste Shipping Drums" & HNP-8422, "Handling & Loading of Chem-Nuclear Cask " W/840119 1tr & 840322 memo BORRELL, E.C., NIX, H.C. Georgia Power Co 84/01/25 App 22842:306 24X Fiche, 50-321, 84/01/25, 8403300339
- 840326026: Forwards order confirming licensee commitment to implement post-TMI-related itmes in NUREO-0737: Suppl 1 (Generic Ltr 82-33), "Requirements for Emergency Response Capability " STOLZ.J.F. Operating Reactors Branch 4 84/02/21 BECKHAH, J. T Georgia Power Co 3pp. 22763 179, 24X Fiche 50-321;84/02/21;84/03/0261

- --B403260265 Order confirming licensee commitments on emergency response capability requiremente set forth in NUREG-0737. Suppl 1 (Generic Ltr B2-33) ETSENNUT.D G Division of Licensing 84/02/21 Georgia Power Ca 6pp 22763-182 24X Fiche 50-321.84/02/21.8403260261
- B403090067 Forwards rev to physical security plan Rev withheld (ref 10CFR2 790 & 73 2!) Transmittal ack encl BECKHAH.J T Georgia Power Co 84/02/27 O'REILLY,JP Region 2. Office of Director 2pp 22575 351 24X Fiche 50-321.84/02/27. 8403090067
- 8403130165 Revs 6 & 7 to Emergency Plan Implementing Procedures
 HNP-8006.Rev 9 to HNP-8007 & Rev 0 to HNP-8043 re
 decontamination & Rev 8 to HNP-4860.HP-4891.HP-4867.4868 &
 4869 re reveiw & rev to emergency plan W/840306 ltr
 SURRELL.E C Qeorgia Power Co 84/03/02 124pp 22600 132 24x
 Fiche 50-321.84/03/02.8403130165
- 8403130346 Advises that next annual amergancy exercise scheduled for B40B02 Btate of GA & local govts do not pian to fully participate Exemption to 10CFR50.App E necessary to proceed u/exercise Reply requested if data & exercise acceptable BECKHAM.JT Georgia Power Co B4/03/02 DENTUN.HR Office of Nuclear Reactor Regulation, Director 1p 22607 149 24X Fiche 50-321.84/03/02,8403130346
- B403i60i90 Notifies of 8403i6 workshop meeting to discuss iOCFR50.App R requirements & associated inepresults to resolve fire protection misunderetandings. Number of attendees should be limited to six due to conference room elze LEWIS.R C Region 2. Office of Director 84/03/02 KELLY.R J Georgia Power Co ip 22655 3i7 24X Fiche 50-321,84/03/02, B403i60i50
- 8403i30004 Transmittal & title pages of deleted emergency pian implementing procedures, including HNP-i-4205 re turbine lube oil reservoir oil fire & HNP-i-4206 re turbine lube oil conditioner & etorage fire W/840306 ltr SORRELLIE C Georgia Power Co 84/03/06 i2pp 22615 i83 24X Fiche 50-321,84/03/06,8403i30004
- 8403240150 Revised emergency plan implementing procedures, including Procedure HNP-8033 re quantitative fit teeting, Procedure HNP-4526 re aiert emergency rally point leader & Procedure HNP-8010 re use & care of respirators W/840320 ltr SORRELL.E C Georgia Power Co 84/03/20 i14pp 22758: 270 24X Fiche 50-321,84/03/20,8403240150
- 8403300143 Rev 4 to Emergency Plan Implementing Procedures HNP 4726 & 4626 & Rev 8 to Procedure HNP-8012 re general & site area emergency raily peint leaders & radiation & contamination survoye W/840326 1tr 80RRELLE C Georgia Power Co 84/03/26 ii9pp 22820 083 24X Fiche 30-321,84/03/26,8403300143
- J Insurance & indemnity information
- 840306028i Forwarde Endorsement 85 to NELIA Policy NF-2:5
 DUCK.J R Nareh & McLennam. Inc 84/02/28 SALTZMAN.J Assistant
 Director for State & Licensee Relations 2pp 22518 i87 24X
 Fiche 50~321.84/02/28.840306028i
- 840328003B Forwards Endorsements 86 & B7 to NELIA Policy NF-215 & Endorsements 70 & 71 to MAELU Policy MF-78
 DUCK.J R Marsh & McCennan, Inc 84/03/21 SALTZMAN,J Assistant Director for Btate & Licensee Relations 5pp 22777 010 24X
 Fichs 50-321.84/03/21.8403280038
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 8402270263 Reeponds to FOIA request for JC Mark 801204 memo to ACRS re hydrogen burn w/lgniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards App A documents App B documents in FDR FELTON, J M Division of Rules and Records 84/01/30 HIATT, 8 L Ohio Citizens for Responsible Energy 7pp 22412 051 24X Fiche 50-000,84/01/30,8402270263
- --8402270314 Forwards eummary of investigations re hydrogen recombiners & relay failures in HPCI sys
 ZUKOR.D J ACRS Advisory Committee on Reactor Safeguarde.
 80/10/30 MOELLER.D W ACRS Advisory Committee on Reactor
 8

P Operating license stage documents & correspondence

- 8401120436 Notification of 840214 meeting u/OPU, Bethtel & Southern Svcs Co in Bethesda, MD to discuss equipment qualification RIVENBARK.O W Operating Reactors Branch 4 84/01/09 STOLZ, J F Operating Reactors Branch 4 200 21804 101 24X Fiche 50-321,84/01/09.8401120456
- 8403090187 Application for amend to Licenses DPR-57 & NPF-5, revising Tech Specs re listed TMI Action Plan Items, per Generic Ltr 83-36
 BECKHAM.J T Georgia Power Co 84/02/06 STOLZ.J F Operating Reactors Branch 4 8pp 22573 276 24X Fiche 50-321, B4/02/06, 8403090187
- --8403090196 Proposed Tech Specs re instrumentation providing surveillance info.post-accident sampling & enalysis & post-accident monitoring instrumentation # Georgia Fouer Co 84/02/06 18pp 22573 284 24X Fiche 50-321,84/02/06,8403090187
- 8403160226 Reviews 840112 meeting to discuss responses to 831004 request for addi info needed to review 0A program description List of meeting attendees encl LEWIB.R C Division of Project & Resident Programs 84/02/09 KELLY.R J Georgia Power Co 3pg 22641 064 24% Fiche 50-321,84/02/09.8403160226
- 8403050085 Discusses analyses on 22 sefety relief valve (SRV) discharge lines per 821229 request to address questions re SRV test progrem per TMI Item I1 D 1 Analyses indicate supports & paping geometry adequate GUCMA:L T Georgie Power Co 84/02/10 STGLZ, J.F. Operating Reactors Branch 4 2pp 22490 007 24X Fiche 50-321,84/02/10, B403050085
- 8403080179 Fourth partial response to FOIA request for six cetegories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON.S J Garvey, Schubert, Adams & Barre 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- 8403060436 Forwards notice of consideration of issuance of Amends 97 & 34 to Licenses DPR-57 & NPF-5, respectively & proposed NSHC determination & opportunity for hearing re time requirements for Scram discharge vol vent & drain velves RIVENDARK, O Operating Reactors Branch 4 84/02/21 BECKMAN, J T Georgia Power Co 3pp 22549 344 24X Fiche 50-321, 84/02/21, 8403060436
- --B403060440 Notice of consideration of issuance of Amends 97 & 34 to Licenses DPR-57 & NPF-5, respectively & proposed NBHC determination & opportunity for hearing SFOLZ.JF Operating Reactors Branch 4 84/02/21 Bpp 22549 347. 24% Fiche 50-321,84/02/21,8403060436
- 8403140340 Summary of 831215 meeting w/GE & Mark 1 Owners Group in Bethesda. MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL, B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 178 24X Fiche 50-000, 84/02/21, 8403140340
- 8403010110 Forwards Amends 98 % 35 to Licenses DPR-57 & NPF-5, respectively & safety evaluation Amends revise Tech Spacs to extend time allowed to restore thermal power scram & control rod block trip setpoints within Tech Spac limits RIVENBARK.9 Operating Resectors Branch 4 84/02/22 BECKHAM.J T Georgia Power Co 2pp 22477 281 R4X Fiche 50-321,84/02/22,8403010110
- r-B403010124 Amends 98 & 35 to Licenses DPR-57 & NPF-5, respectively, revising Tech Bpecs to extend time allowed to restore thermal power scram & control rod block trip setpoints within Tech Specs limits STOLZ, J F Operating Reactors Brench 4 84/02/22 15pp 22477 283 24X Fiche 50-321,84/02/22,8403010110
- ---8403010128 Safety evaluation supporting Amends 98 & 35 to Licenses DPR-57 & NPF-5, respectively 10 office of Nuclear Reactor Regulation, Director 84/02/22 3pp 22479 298 24X Fiches 50-321,84/02/22,8403010110
- 8403070357 Forwards request for add1 info to complete review of proposed progrems for inservice testing of pumps & valves submitted in 830812 itr Info requested within 30 days STDLZ.JF Operating Reactors Branch 4 84/02/23 BECKHAM.JT Operate Power Co 4pp 22564-134 24x Fiche 50-321,84/02/23,8403070357

- 8403070251 Forwards update on facilities conformance & info re plans & schedules for any needed improvements & rept re vendor equipment technical info program by Nuclear Util Task Action Committee on Deneric Ltr 83-28, Section 2 2 2 GUCHA, L T Georgia Power Co 84/02/27 STOLZ, J F Operating Resctors Brench 4 24pp 22536 087 24X Fiche 50-321,84/02/27,8403070251
- --8403070252 "Vendor Equipment Technical Info Progrem." per Generic Ltr 83-28. Section 2 2 2.ftnal draft + Nuclear Utility Task Action Committee 84/02/29 63pp 22336 il2 24X Fiche 50-321.84/02/29.840307025i
- 8403200005 Responds to 840229 request for addi action to verify aspects of overhead crame design at facility, per NUREG-0612 guidelines Crame safety & reliability satisfactory OUCHAL T Georgia Power Co 84/03/12 STOLZ. J F Operating Resctors Brench 4 2pp 22685 209 24X Fichs 50-321,84/03/12, paggangon
- 8403200262 Forwards GE repts on metellographic exam of metal semples taken from tracked vent header, per NRC 840206 meeting w/ util. BMR Regulatory Response Group & GE Vent header tracking brittle frecture caused by injection of cold nitrogen QUCMA, L T Georgia Power Co 84/03/i3 STGLZ, J F Operating Reactors Branch 4 5pp 22671 102 24X Fiche 50-366, 84/03/i3, 8403200242
- B403:50275 Generic Ltr B4-07 to ell licensees of BWRs re procedural guidance for pipe repiecement et BHRs Svc list encl EISENHUT, D 0 Division of Licensing B4/03/14 Commonweelth Edison Ca 20pp 22823 334 24X Fiche 50-000.84/03/14,8403150275
- G Inspection reports, IE Bulletins & correspondence
- 8403160176 Forwards IE Insp Repts 50-321/84-04 & 50-366/84-04 on 840204-07 No vigletions or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/24 KELLY.R T Georgia Power Co 2pp 22655 351 24X Fiche 50-321.84/02/24.8403160176
- --8403160198 IE Insp Repts 50-321/84-04 & 50-366/84-04 on 840204-07 No violations or deviations identified Major areas inspected torus vent header crecking feedwater line ultrasonic indication & rectroulation piping replacement CROWLEY, B R , BLAKE, J J Region 2, Office of Director, 84/02/23 App 22655 353 28% Fichs 50-321,84/02/24,8403160176
- 8401i90072 IE Info Notice 84-13, "Potential Deficiency in Motor Derated Vaive Control Circuits & Annunciation " Svc list encl JORDAN,E L Division of Emergency Preperedness & Engineering Response (Post 830103) 84/02/28 Censolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 lE Info Notice 84-i4, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list and GRACE, J.N Division of GA. Sefeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc i30pp 22552 327 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE 1nfo Notice 84-16, "Failure of Autometic Sprinkler Sys Valves to Operate " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/02 Consolidated Edison Co. of New York: Inc 122pp 22553 098 24X Fichs 50-000,84/03/02,8402090008
- B402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Byc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Coaling Components Below Nii Ductility Temp " Svc list encl.

 JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidate Edison Co. of New York, Inc 117pp. 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Sefe Shutdown Sys " Svc list encl JURDAN; E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/07, Consolidated Edison Co. of New York, Inc 118pp 22635 049 24% Fiche 50-000,84/03/07,8402090024
- 8402070028 IE Info Notice 84-19, "Stress Corrosion Cracking in PWR Bys " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584:186 24X Fiche 50-000,84/03/07,8402070028

- 8403140338 Ack receipt of 840206 itr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-321/83-32 & 50-346/83-34

 DANCE-H C Division of Project & Resident Programs B4/03/09 KELLY:R J Georgia Power Co 1p 22660 013 24% Fiche 50-321,84/03/09,8403160338
- ---8403160349 Responds to NRC 840106 itr re violations noted in IE Insp Repts 50-321/83-32 & 50-366/83-34 Corrective actions procedure rays drafted & undergoing review & approval process QUCKA,L T Georgia Power Co 84/02/06 Q'REILLY, J P Region 2, Qffice of Director 2pp 22660 016 24X Fiche 50—321,84/03/09.
- --8403160359 Forwards IE Insp Repts 50-321/83-32 & 30-366/83-34 on 831114-18 & notice of deviation DANCE, H C Division of Project & Resident Programs 84/01/06 KELLY, R J @eorgia Power Co 2pp 22660 018 24X Fichs 50-321,84/03/09.8403160338

8403140338

- --8403160365 Notice of deviation from insp on 831114-18 # Region 2, Office of Director 84/01/06 1p 2: Fiche 30-321,84/03/09,8403160338 22660.050 54X
- --8403160372 IE Insp Repts 50-321/83-32 & 50-366/83-34 on 831114-18 Deviation noted failure to electronically calibr high range dryweil radiation monitors, per NNREO-0737, Item II F i NRAY, J R Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 84/01/04 7pp 22660 021 24X Fiche 50-321,84/03/09,8403160338
- 8402070031 IE Bulletin 84-02. "Failures of GE Type HFA Ralays in Use in Class IE Safaty Sys " Syc list encl DEYOUNO.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823 094 24X Fiche 50-000.84/03/12.8402070031
- 8403270193 Ack receipt of 840301 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-366/83-26 LEWISHR C Division of Project & Resident Programs 84/03/15 KELLYR J Georgia Power Co. 1p 22801 008 24X Fiche. 50-366. 84/03/15. 8403290193
- ---8403270194 Responds to NRC 840201 ltr re violations noted in IE Insp Repts 50-321/83-25 & 50-366/83-26 on 830721-0820, Corrective actions administrative controls to stress independent actions administrative verification upgraded execution upgraded BECKHAM.J T Georgia Power Co 84/03/01 O'REILLY, J P Region 2. Office of Director 6pp 22801 009 24X Fiche 50-366,
- --B403290195 Forwards IE Insp Repts 50-321/83-25 & 50-366/83-26 on B30721-0820 & notice of violation LEWIS.R C Division of Project & Resident Programs 84/02/01 KELLV.R J Georgia Power Co. 2pp 22801 015 24X Fiche 50-366,84/03/15,8403290193
- --8403290196 Notice of violation from insp on 830721-0820. * Region 2, Office of Director. 84/02/01 2pp 22801:017 24X Fiche. 50-366, 84/03/15, 8403290193
- --8403290i97 IE Insp Repts 50-32i/83-25 & 50-366/83-26 on 83072i-0820 Violations noted safety-related equipment & sys not aligned & limiting condition for operation for main steam isolation laakage control sys not established CRLENJAN,R V , HOLMES-RAY,P,, PANCIERA,V W Region 2, Office of Director 84/01/28 5pp 2280i 018 24X Fiche 50-366,84/03/15,8403290193
- 8403290208 Ack receipt of 840301 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-321/84-03, DANCE: N. C. Division of Project & Resident Programs. 84/03/19 KELLY: R. J. Georgia Power Co. ip 22800, 302 24X Fiche 50-321:84/03/19,8403290208
- ---B403290212 Responds to NRC 840210 ltr re violations noted in IE Insp Repts 50-321/84-03 & 50-366/84-03 Corrective actions.NDE personnel reminded of importance of proper & complete data Personner of the property of the state of th
- --B403270215 Forwards IE Insp Repts 50-321/84-03 & 50-366/84-03 on 840124-27 & notice of violation. DANCE,H C. Division of Project & Resident Programs B4/02/10 KELLYR.J Georgis Power Co 2pp 22800.305 24X Fiche 50-321,84/03/19,8403290208

- --8403290219 lE Insp Repts 50-321/84-03 & 50-366/84-03 on 840124-27 Violation noted uitrasonic insp records for Fall 1982 insp of reactor vessel flange to Shell Weld C-1 did not show of reactor vesses riange to oness were described to location of area extent or location of area CROMLEY.B R Region 2. Office of Director. DLAKE, J. J. Division of Emergency Preparedness & Materials Safety 84/02/09 lipp 22800 308 24X Fiche 50-321.84/03/19.8403270208
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JURBAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Natice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JURBAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Conselidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000.84/03/21.8402090044
- R Periodic operating reports & related correspondence
- 8403150071 Monthly operating repts for Feb 1984 W/840310 ltr RAFEEDIE.D P , NIX.H C Georgia Power Co 84/02/29 12pp 22643 191 24X Fiche 50-321.84/02/29.8403150071
- 8 Reportable occurrences. LERs & related correspondence
- 8304270367 Forwards for review, technical review rept on method of detection used in 800726 failure of scram discharge vol detection used in 800/26 failure or stram discharge vol level switches PELLET.J L Reactor Operations Analysis Branch B3/04/13 SEYFRIT.K V Reactor Operations Analysis Branch 1p 22/ 24X Fiche 50-366.B3/04/13,B304270367 2280B 314
- --8403280079 "Scram Discharge Vol Level Switch Failure," technical review rept Caused by crushed floats Piping mods made to alleviate high differential pressure across float chamber during scram reset PELLET.J Reactor Operations Analysis Branch B3/04/13 3pp 22808 315 24% Ficha 50-366,83/04/13,8304270367
- 8403260233 Forwards summary list of deficiencies identified per 10CFR50 55(e), Part 21 & potential generic 1tr repts for Comments
 STAROSTECK1,R Division of Project & Resident Programs 84/02/28
 Region 1. Office of Director 7pp 22756 065 24X
 Fiche 50-000,84/02/28,8403260233
- 8403050284 Summary of 840223 meeting w/BWR Regulatory Response Group in Bethesda.MD re industry response to vent header cracking incident Presentation outline.info request.GE svc info itr & meeting attendance list enci
 TREMBLAY.P Operating Reactors Assessment Branch B4/02/29
 HOLCHAN.O M Operating Reactors Assessment Branch 18pp
 22501-188 24X Fiche 50-366.84/02/29.8403050284
- B403120031 LER B4-001-00 on B40203, personnel detected fracture in 66-inch vent header in bay 5 Caused by brittle facture of vent header mat1 Vent header will be repaired & addi changes or sys mod will be made to improve sys W/840304 ltr TIPPS,S B , NIX.H C Georgia Power Co 84/03/04 5pp 22588 020 24X Fiche 50-366,84/03/04,8403120031
- 8403160031 Updated LER 83-040/03X-1 on 830707 & 14, control rod drive low pressure or high level alarm received for HCV 2011-26-31 & 02-27 Caused by leaking EP-111 nitrogen charging valves Valves replaced & HCVs returned to svc W/840312 itr TIPPE, 8 B, NIX.H.C Georgia Power Co 84/03/12 O'REILLY, J P Region 2, Office of Director 8pp 22654 347 24X Fiche 50-366,84/03/12,8403160031
- 8403160039 PNO-II-84-021 crack indications identified in all 14 12-inch riser elbows in replacement recirculation piping scheduled to be installed Caused by improper forming temps used during BLAKE, J. J. R000E, J. F. Region 2, Office of Director 84/03/12, 2pp. 22655 134 24X Fiche 50-366,84/03/12,8403160039
- 8403190026 Updated LER 83-040/03X-1 on 830728, control rad drive low pressure or high level alarm received for hydraulic control units 2Ci1-26-31 & 02-19. Caused by leaking EP-11f nitrogen charging valves Valves replaced W/840312 itr TIPPS, S B, NIX,H C Georgia Power Co 84/03/12 D'REILLY,J P Region 2, Office of Director Bpp 22666 105 24X Fiche 50-366,84/03/12,8403190026

- 8403170284 PNO-]I-84-022 circumferential crack found on one of four feedwater nozzles during exam of feedwater nozzles per NUREG-0691 Corrective action being svaluated Inspectors monitoring litenses work on regular basis CRUMLEY, B R: PANCIERA, V. Region 2. Office of Director 84/03/14 p. 22672 279 24% Fiche 50-366.84/03/14.8403190284
- 8403260086 Updated LER 82-123/03X-1 on 821030, reed switch position indicators for control rods 14-07 & 34-43 found inoperable Caused by component failure Control rod drivers 2011-34-43 & 2011-14-07 repaired W/840319 lber TIPPS 8 B , NIX.H C Georgia Power Co 84/03/19 D'REILLY, J P Region 2, Dffice of Director 4pp 22748 358 24X Fiche 50-366,84/03/19,8403260086
- B400250191 LER 84-002-00 on B40220, five main steam safety relief valves failed to lift in 1% tolerance range required by Tech Specs Caused by corrosion buildup on pilot assembly Safety relief valves calibr W/840320 ltr TIPPS 8 B , NIX.H C Georgia Power Co 84/03/20 5pp 22755 116 24X Fichs 50-365,84/03/20,8403260191
- B409290013 Confirms IE mgt meeting on 840923 at Region II ofc to discuss crack found in feedwater nottle & future corrective action.per 840316 telcon
 LEMIS.R C Division of Project & Resident Programs B4/03/20 KELLY.R J Georgia Power Co IP 22803 283 24X
 Fiche 50-366.84/03/20.8403290013
- 8403260ii9 Revised LER 84-001-01 on 840203, piant personnel detected fracture in 66-inch vent header in Bay 5 Caused by brittle fracture of vent header mat! Vent header will be repaired prior to startup. W/84032i ltr TIFPS, S , NIX.H C Georgia Power Co 84/03/2i 6pp 22757 357 24X Fichs 50-366,84/03/2i,8403260l19
- 8403300104 Advises that program of periodic manual operation of safety relief valves will be discontinued based on results of BHR Owners Group investigation Safety relief valve cycling caused valves to leak prematurely OUCHA.L T Georgia Power Co 84/03/26 STOLZ, J F Operating Reactors Branch 4 Zpp 22821 216 24X Fiche 50-321,84/03/26, 8803300104

S TINU , SMO RABIOL SARANSAS NUCLEAR ONE, UNIT 2

- F Security, medical, emergency & fire protection plans
- 8403130437 Documents results of activities conducted during 831031-1104 IE insp to review open items re emergency planning Commitment status to resolve items provided Expeditious actions by NRC to remove items requested HAREHALL.J R Arkansas Power & Light Co 83/12/09 COLLINS, J T Region 4, Office of Director 15pp 22613 233 24X Fichs 50-313,83/12/09,8403130437
- 8403120011 Forwards Amend 10 to emergency plan W/o encl MARSHALL.J R Arkansas Power & Light Co B4/01/20 COLLINS,J T Region 4. Office of Director 1p 22085 221 24X Fiche 50-313,84/01/20,8403120011
- 8403280074 Public version of Amend 10 to emergency plan #/840120 ltr & JM Felton 840322 release memo MARSHALL.J R Arkansas Power & Light Co 84/01/20 COLLINS.J T Region 4. Office of Director Spp 22812 288 24X Fiche 50-313.84/01/20.8403280094
- 8403130473 Submits response to Hakney request for add1 info re emergency plan training for non-util employees Vendors & contractors w/unescorted access within protected area receive training commensurate w/job assignments HARSHALLJR Arkansas Power & Light Co 84/01/24 QAGLIARDO, J E Division of Resident, Reactor Project & Engineering Programs ip 22613 330 24% Fiche 50-313,84/01/24,8403130473
- 8403050142 Notifies that NRC will provide inspectors to observe onsite aspects of periodic aspecies for amergency preparedness Scenario for submission of info listed COLLINB.J T Region 4. Office of Director 84/02/09 GRIFFIN.J H Alabama Power Co 2pp 22487,308 24X Ficher 50-313,84/02/09, 34013804.02
- 8403130395 Forwards IE Insp Repts 50-313/84-05 & 50-368/84-05 on 840126 No violations or deviations identified GAQLIARDO, J E Region 4, Office of Director 84/02/16 ORIFFIN. J M. Arkansas Power & Light Co 2pp 22616 325 24X Fichs 50-313,84/02/16,8403130395

- --8403130402 IE Insp Repts 50-313/84-05 & 50-368/84-05 on 840126 No violations or deviations identified Major areas inspected status of REX-84 exercise scenario development HACKNEY,C A Region 4, Office of Director 84/02/16 3pp 22616 327 24X Fiche 50-313.84/02/16.8403130395
- B403060350 Requests approval of mod to health physics network & emergency notification sys phones from handset to headset to alieviate fatigue during continuous open-line communications maintained in emergencies

 MARSHALL.JR Arkansas Power & Light Co 84/02/17 DENISE.R P
 Division of Resident. Reactor Project & Engineering Programs 19
 22519 085 24x Fiche 50-313.84/02/17,8403060350
- 8403060198 Ack receipt of 840203 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-25 & 50-368/83-25 GAGLIARDO.J E Region 4. Office of Director 84/02/29 ORIFFIN.JM Arkansas Power & Light Co ip 22517 226 24X Fiche 50-313,84/02/29,8403060198
- --B403060203 Responds to NRC B31024 itr re violations noted in IE Insp Repts 50-313/83-25 & 30-385/83-25 Corrective actions fire watch posted at Doors 267 & 340 until mods to eliminate excessive air gaps under doors completed MAREHALLJR Artansas Power & Light Co B4/02/03 DENIBERR P Division of Resident, Reactor Project & Engineering Programs 3pp 22517 227 24X Fiche 50-313.84/02/27.8403060198
- 8403060430 Provides preliminary estimates for emergency operations facility mods to raise radiation protection factor to greater than or equal to five, per NUREO-0694, in response to NRC 840214 request Util will not implement mods MAREHALL.JR Arkansas Power & Light Co. 84/02/27 8TOLZ,JF Operating Reactors Branch 4 MILLER,JR Operating Reactors Branch 3 2pp 22318.192 24X Fiche.50-313,84/02/29,8403060430
- 8403060324 Forwards proprietary Rev 12 to Procedure 1903 10. "Emergency Action Level Response" & proprietary Procedure 1904 series (1904 01.02.03.06.07 & 08). "Offsite Dose Projections " Proprietary procedures withheld # Ankansas Power & Light Co 84/03/01 NRC No Detailed Affiliation Given 2pp 22513 333 24X Fiche 50-313,84/03/01. B403060324
- 8403070358 Public version of Rev 12 to Emergency Plan Implementing Procedure 1903 10. "Emergency Action Level Response " W/ 840207 transmittal form & UM Felton 840302 release memo LEVING, J M Pennsylvania Power & Light Co 84/03/01. 68pp. 22566 227 24% Fiche 50-313,84/03/01.8403070358
- 8403240070 Forwards IE Insp Repts 50-3i3/84-04 & 50-368/84-04 on 840124-24 No violations or deviations identified OAGLIARDO.J E Region 4, Office of Director 84/03/05 ORIFFIN.J M Arkensas Power & Light Co 2pp 22758 271 24X Fichs 50-3i3.84/03/05.8403260070
- ~-8403260099 IE Insp Repts 50-313/84-04 & 50-368/84-04 on 840124-24 No violations or deviations identified Hajor areas inspected, security organization personnel per alleged compromise of safeguards info Details withheld (ref 10CFR73 21) KELLY, J A Region 4. Office of Director 84/03/02 ip 22758:273 24X Fiche 50-313,84/03/05,8403240090
- 840323023B Advises that, based on review of 831125 submittal of detailed control room design, specific areas of program plan do not meet requirements of Suppl 1 to NUREG-0737 Meeting requested to resolve deficiencies STOLZ, J F Operating Reactors Branch 4 84/03/06 ORIFFIN, J M Arkansas Power & Light Co 2pp 22759 278 24X Fiche 50-313,84/03/06,8403230238
- B403i90277 Notifies of error in 840216 ltr transmitting IE Inap Repts 50-313/B4-03 & 50-368/B4-03 ltr indicated rept numbers 50-313/B3-03 & 50-368/B3-03 Records should be changed accordingly OAGLIARDGU E Region 4, Office of Director 84/03/OB ORIFFIN, J M Arkansas Power & Light Co 1p 22673 170 24X Fiche 50-313,84/03/OB,8403190277
- --8403190203 Forwards IE Insp Repts 50-313/84-03 & 50-368/84-03 on 840125 No violations or deviations noted GACLIARDOLJE Region 4. Office of Director 84/02/16. ORIFFIN.J H Arkansas Power & Light Co 2pp 22673-191. 24X Fiche 50-313,84/03/08,8403190277
- --8403170288 IE Insp Repts 50-313/84-03 & 50-368/84-03 on 840125 No violations or deviations noted Major areas inspected actions taken as result of discrepancy between public info brochure & Jan 1984 telephone directory for emergency planning zone HACKNEY, C. A. Region 4, Office of Director 84/02/16 3pp 22673 193 24X Fiche 50-313,84/03/08,8403190277.

- 8403i30113 Forwards exercise repts of 8203i9 & 8303i6 joint exercises of offsite radiological emergency preparedness plans for Arkansas Nuclear One Power Station Deficiencies observed at both exercises Approval under FEMA Rule 44CFR350 in effect KRIMM-R W Federal Emergency Management Agency 84/03/09 JDRDAN-E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22640 001 24X Pichs 50-313.84/03/09,8403150113
- --8403150119 Exercise repts of 820519 & 830316 joint exercises of offsite radiological emergency preparedness plan for Arkansas Nuclear One Power Station RRIMIR W Federal Emergency Management Agency 84/03/09 45pp 22640 003 24X Fiche 50-313,84/03/09.8403150113
- 8403200246 Forwards Amend 4 to nuclear contingency plan. Rev 4 to Nuclear Contingency Plan Procedures 1,2,3,7 & 9.Rev 3 to Procedures 5,6,8 & 11,Rev 2 to Procedures 4 & 13 & Rev 1 to Procedure 15 MARSHALL. J R Arkenses Power & Light Co 84/03/14 EISENHUT, D Q Office of Nuclear Reactor Regulation. Director 1p 22688 027 24X Fichs. 50-313,84/03/14,8403200246
- --8403200251 Rev 4 to nuclear contingency plan
 * Arkansas Power & Light Co 84/02/06 49pp 22688 028 24X
 Fichs 50-313,84/03/14,8403200246
- ---8403200258 Revs 4.3.2 & 1 to Nuclear Contingsncy Plan implementing Procedures 1.2.7 & 9.5.6.8 & 11.4 & 13 & 15, respectively, reassignment of personnel to emergency response organization, notification & command & control *Arkansas Power & Light Co 84/03/i5 i43pp 22688 077. 24X Fiche 50-313,84/03/i4.8403200246
- 8403200179 Forwards Amend 11 to smergency plan & Amend 4 to nuclear contingency plan.

 MARSHALL, JR Arkansas Powsr & Light Co 84/03/15 COLLINS, J T Region 4. Office of Director 1p #2689 120. 24X Fiche 50-313,84/03/15,8403200179
- ---8403200180 Amend i1 to emergency plan & Amend 4 to nuclear contingency plan.

 A Triansas Power & Light Co 84/02/06 57pp 22689 121 24X Fiche 30-313,84/03/15,8403200179
- --8403200181 Rev 4 to Nuclear Contingency Plan implementing Procedure i, "Assignment of Personnel to Emergency Response Organization"

 Ankansas Power & Light Co 84/02/06 137pp. 22689,177 24X Fiche: 50-313,84/03/15,8403200179.
- 8403220185 Responds to 840217 request for relocation of HFN telephone in emergency control ctr & for approval to add headsets. Request forwardsd to Telecommunications Branch Headset mod approved GAOLIARDO. J E. Region 4. Office of Director 84/03/19 GRIFFIN. J. M. Arkansas Power & Light Co ip 22717 035 24X Fiche. 50-313,84/03/19,8403220185.
- P. Operating license stage documents & correspondence
- B403060551 Forwards safety evaluation re adequacy of fuel assembly shoulder gaps for Cycle 4 operation Requests exam plan & related acceptance criteria be submitted 2 months before glant shutdown for next refueling, W/o encl HILLER, J R. Operating Reactors Branch 3 84/02/24 ORIFFIN, J M Arkaneas Power & Light Co 2pp. 22552 291 24X Fiche: 50-368,84/02/24,8403060551
- 83.4031200B2 Requests rev or withdrawal of 830927 amend application to delete remote shutdown monitoring instrument measurement ranges Min instrument measurement ranges should be specified MILLER, J. R. Operating Reactors Branch 3 84/02/29 ORIFFIN, J M Arkansas Power & Light Co 3pp. 22619-343 24X Fiche 50-368.84/02/29,8403120082.
- E3403140299 Forwards request for add1 info re control of heavy loads.
 Response requested within 60 days.
 MILLER, J. R. Operating Reactors Branch 3 84/03/06, ORIFFIN, J M
 Arkansas Power & Light Co 2pp 22635 327 24X
 Fiche. 50-313,84/03/06,8403140299

- 840326005i Application to amend Licenses DPR-51 & NPF-6, changing Tech Specs re RGS vents.post-accident sampling.long-term auxiliary feedwater sys evaluation.noble gas monitor & iodine particulate sampling.per NUREG-0737 items GRIFFIN.J M Arkansas Power & Light Co 84/03/16 STOLZ,J F Operating Reactors Branch 4 MILLER.J R Operating Reactors Branch 3 9pp 22750 293 R4X Fiche 50-313,84/03/16,840326005i
- --8403260157 Proposed Tech Spec changes re RCS vent post-accident sampling.long-term auxiliary feedwater sys evaluation, noble gas monitors; lodine particulate sampling & containment water level monitor

 **Arkanas Fower & Light Co 84/03/16 27pp 22750 302 24X Fiche 50-013,84/03/16,8403260051
- G inspection reports, IE Bulletins & correspondence
- 8403130437 Documents results of activities conducted during 831031-i104
 IE insp to review open items re emergency planning
 Commitment status to resolve items provided Expeditious
 actions by NRC to remove items requested
 MARSHALL.JR Arkansas Power & Light Co 83/12/09 CGLLINS,JT
 Region 4. Office of Director 15pp. 22613 233 24x
 Fiche 50-313.83/12/09.8403130437
- 8403300046 Forwards IE Insp Repts 50-313/83-36 & 50-368/83-36 on 831219-21 No violations or deviations identified QAGLIARDO, J E. Region 4. Office of Director. 84/01/31 ORIFFIN.J M. Arkensas Power & Light Co. 2pp. 22821 240 24X Fiche 50-313.84/01/31.8403300046
- --8403300050 IE Insp Repts 50-313/83-36 & 50-368/83-36 on 831219-21 No violations or deviations identified Major areas inspected GA plans, instructions & procedures for low levs1 radwaste storage facility HILBORN,L , MURRAY.B , JOHNSON,W D. Region 4. Office of Director 84/01/27 10pp 22821 242 24X Fiche 50-313.84/01/31,8403300046
- 8403130395 Forwards IE Insp Repts 50-313/84-05 & 50-368/84-05 on 840126 No violations or deviations identified GAOLIARDO.J.E. Region 4. Office of Director 84/02/16 ORIFFIN.J M. Arkansas Power & Light Co. 2pp. 22616-325 24X Fiche 50-313.84/02/16.8403130395
- --B403130402 iE insp Repts 50-313/84-05 & 50-368/84-05 on 840126 No violations or deviations identified Major areas inspected, status of REX-B4 exercise scenario development HACKNEY.C A , BAIRD.J B , JOHNSON, H. D. Region 4, Office of Director 84/02/16 3pp 22616 327 24X Fiche: 50-313,84/02/16,8403130375
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Syc list enc!

 JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of Nsw York, Inc 115pp 22707 237 24X Fichs 50-000.84/02/28.8401170072
- 8403040198 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-25 & 50-3348/83-25 GAGLIARDO, J E Region 4, Office of Director 84/02/29 GRIFFIN, J M Arkansas Pawer & Light Co ip 22517 226 24X Fiche 50-313,84/02/29,8403040198
- --8403060203 Responds to NRC 831024 1tr re violations noted in 1E Insp Repts 50-313/83-25 & 50-368/83-25. Corrective actions fire watch posted at Doors 267 & 340 until mods to eliminate excessive air gaps under doors completed MARSHALL, J. R. Arkansas Power & Light Co. 84/02/03 DENISE, R.P. Division of Resident, Reactor Project & Engineering Programs 3pp 22517 227 24X Fiche 50-313,84/02/29,8403060198
- 8403240137 Forwards results of stsam generator tube inservice insp performed during 2R3 refueling outage Minor tubs wall degradation indications observed during data analysis for Bteam Generator A & B in both hot & cold leg sides. MARSHALL.JR Arkansas Power & Light Co. 84/02/29 COLLING.J T Region 4. Offics of Director 8pp 22758 150 24X Fiche 50-368.84/02/29,8403260137
- 8403040122 Notification of significant licensee enforcement conference on 840309 w/util in Arlington.TX * Region 4, Office of Director 84/03/01 Region 4, Office of Director ip 22516 328 24K Fiche 50-313,84/03/01.8403060122
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl. GRACE J.N Division of OA, Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fichs 50-000,84/03/02,8402090007

- 8402090008 iE lnfo Notice 84-15, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JURDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fishe 50-000,84/03/02,8402090008
- 9402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consult/ated Edison Co of New York, Inc 119pp 22553 217 24x Fiche 50-000,84/03/02,8402090009
- 84020900il IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list enci JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 94/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24% Fishe 50-000,84/03/05,8402070011
- 8403260090 Forwards IE Insp Repts 50-313/84-04 & 50-368/84-04 on B40124-26 No violations or deviations identified GAGLIARDD J E Region 4. Office of Director 84/03/05 GRIFFIN J N Arkansas Power & Light Co 2pp 22758 271 24X Fichs 30-313,84/03/05,8403260090
- --B403260099 IE Insp Repts 50-313/84-04 & 30-368/84-04 on 840124-26 No violations or deviations identified Major areas inspected security organization personnel per alleged compromise of safeguards info Details withheld (ref iOCFR73 21)
 KELLY.J A , HALL,R E , JUHNSON,W D Region 4, Office of Director 84/03/02 1p 22758 273 24X Fiche 50-313,84/03/05.8403260090
- 8402090024 IE Info Notice 84-09. Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list enci JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York. Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Btress Corrosion Cracking in PWR Sys " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403130120 Informs that IE Insp Repts 50-313/83-12, 50-368/83-12, 50-313/83-33 & 50-369/83-33 cancelled No insp repts wiil be issued for subj numbers GAOLIARDD, J E Region 4. Office of Director B4/03/08 GRIFFIN.J M Arkansas Power & Light Co ip 22602 197 24X Fiche 50-313,84/03/08.8403130120
- 8403190277 Notifies of error in 840216 ltr transmitting iE Insp Repts 50-313/84-03 & 50-368/84-03 Ltr indicated rept numbers 50-313/83-03 & 50-368/83-03 Records should be changed accordingly GAGLIARDO. J E Region 4, Office of Director 84/03/08 GRIFFIN, J M. Arkansas Power & Light Co ip 22673 i70 24x Fiche 50-313.84/03/08.8403190277
- --8403190283 Forwards IE Insp Repts 50-313/84-03 & 50-368/84-03 on 840125 No violations or deviations noted GACLIARDD.J E Region 4. Office of Director 84/02/16 GRIFFIN.J M Arkansas Power & Light Co. 2pp 22673 191 24X Fich
- --8403190288 IE insp Repts 50-313/84-03 & 50-368/84-03 on B40125 No violations or deviations noted. Major areas inspected actions taken as requit of discrepancy between public info brochure & Jan 1984 telephone directory for emergency planning tone HACKNEY: C A , BAIRD, J B , JOHNEDN, W D Region 4, Office of Director 84/02/16 3pp 22673 193 24X Fiche 50-313,84/03/08,8403190277
- 8403240230 Forwards IE Insp Repts 50-313/84-06 & 50-368/84-06 on 840221-24 No violations or deviations noted. GAGLIARDB.J E Region 4, Office of Director 84/03/08 GRIFFIN.J M Arkansas Power & Light Co 2pp 22755 151 24X Fiche 50-313.84/03/08.8403260230
- --8403260232 IE Insp Repts 80-313/84-06 & 50-368/84-06 on 840221-24 No violations or deviations noted Major areas inspected maint program BOARDMAN, J R. JOHNSON, H D. CROSSMAN, H A. Region 4: Office of Director 84/03/08 5pp. 22755 153 24X Fiche 50-313,84/03/08,8403260230
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list entl, DEYDUNG.R C Director's Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co. of New York, Inc 134pp. 22823 074 24% Fiche 50-000.84/03/12.8402090031

- 8403200169 Forwards QA Program Insp Rept 99900786/83-02 Significance of reported findings should be evaluated to determine acceptability of product or svc provided by vendor W/o encl QAGLIARDD. J E Region 4. Office of Director 84/03/16 ORIFFIN.J M Artenses Power & Light Co ip 22696 353 24X Fiche 30-313.84/03/16.8403200169
- B402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Bvc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 R4X Fiche 30-000,84/03/21,8402090043
- B402090044 IE Info Notice B4-20, "Svc Life of Relays in Safety-Related Bys " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000.84/03/21,8402070044
- R Periodic operating reports & related correspondence
- 8403060308 "Annual Radiation Exposure Rept.1983 " W/840229 ltr MARSHALL,JR Arkansas Power & Light Co 83/12/31 DEYOUNG.R C Director's Office of Inspection and Enforcement 3pp. 22517 047 24% Fiche 50-313,83/12/31,8403060308
- 8403020081 Monthly operating rept for Jan 1984 W/840215 itr BRAMLETT,L 8 , MAREHALL,J R Arkansas Power & Light Co 84/01/31 BASSET,H S Division of Data Automation & Management Information 6pp 22441 318 24X Fiche 50-366,84/01/31,8403020081
- B403300164 Monthly operating rept for Feb 1984 W/840315 ltr BRANLETT.L 8 , MARSHALL.J R Arkansas Power & Light Co 84/02/29 BASSETT.H B Division of Data Automation & Management Information 7pp 22821 092 24% Fiche 50-366,84/02/27,8403300164
- S Reportable occurrences, LERs & related correspondence
- B403280i17 "Analysis of 800624 Loss of Offsite Power Transient at Arkansas Nuclear One Unit 2" BAYLESS.P D E080, Inc FIN A-6234 E00-NTAP-6309 83/09/30 NRC No Detailed Affiliation Given 46pp 228ii 189 24X Fiche 50-358.
- B403280124 "Analysis of 800129 Turbine Trip at Arkansas Nuclear One Unit 2" BAYLE89.P D E080, Inc FIN A-6234 E00-BAAM-6415 B3/09/30 NRC - No Detailed Affiliation Given 43pp 22811,087 24X Fiche 30-328,82/09/30,8403280124
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BWR plants
 THERDUX.R R Terry Corp 84/02/22 WOODRUFF, R W Director's Office, Office of inspection and Enforcement 6pp. 22706 327 24: Fiche 80-000.84/02/22,8403210032
- 8403090139 LER 84-001-00 on 840128.unit tripped during low power physics testing Caused by one pin peaking factor limit being exceeded due to control element assembly position during testing Procedures modified W/840229 ltr RUGERB,P, MARSHALL,JR, Arkansas Power & Light Co 84/02/29, 3pp 22575 045 24X Fiche, 50-368,84/02/29,8403090139.
- B403130347 LER B4-002-00 on B40129, during routine surveillances of core protection calculator sys, operations personnel observed that valves of addressable constants did not agree w/valves for Cycle 4 Caused by reactor trip on B4012B W/B40302 ltr RUGERB, P, MARBHALL, J R Arkansas Power & Light Co 84/03/02, 4pp. 22607 i50 24X Fiche 50-36B.84/03/02.8403130347.
- 8403130024 LER 84-003-00 on 840130, unit tripped on low steam generator pressure w/concurrent main steam isolation sys actuation. Caused by leaking boric acid addition flow control valve 2CV-4926 Valve repaired W/840305 ltm. ROGERS, P., HARBHALL, J.R. Arkansas Power & Light Co. 84/03/05 3pp. 22615 iii 24X Fiche 50-368,84/03/05,8403130024,
- 8403130324 LER 84-004-00 on 840131, reactor tripped from approx 10% full power Caused by low steam generator level in steam generator B due to manual level control difficulties W/840305 ltr ROGERS, P. MARSHALL, J. R. Arkansas Power & Light Co. 84/03/05 3pp. 22607 140 24% Fiche 50-368, 84/03/05, 8403130324

- 8403270258 LER 63-050/99X-0 on 831109, diesel generator 2 exhibited erratic performance Caused by bad contacts on droop relay in conjunction w/lees than optimum tuning of governor controls Droop relay replaced M/840307 ltr ROGERS, P. MARSHALL, J. R. Arkansas Power & Light Co B4/03/07 DENISE, R. P. Division of Resident, Reactor Project & Engineering Programs 3pp 22772 027 24X Fiche 50-368.84/03/07, 8403270258
- 8403220020 LER 84-005-00 on 840210, output of Channel A ex-core detector subchannels appeared to saturate at 50 7% power Preamp assembly & filter replaced Testing confirmed proper functioning of subchannels W/840311 ltr RDOERS.P. MARSHALL.JR Arkansas Power & Light Co 84/03/11 3pp 22713 352 24X Fiche 50-368.84/03/11.8403220020
- 8403290127 LER 84-006-00 on 840221, operations personnel recognized that addressable constant updated for core protection calculator Channel C still in progress when Channel D prepared for monthly surveillance testing Procedure changed W/840320 ltr ROQERS.P. MARSHALL.J R Arkanses Power & Light Co 84/03/20 3pp 22807:078 24X Flohe 50-368.84/03/20,8403270127
- DOCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

 E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403020317 Forwards Rev 10 to "Analysis of Hydrogen Control Measures at McGuire Nuclear Station," per SSER 7 (NUREG-0422)
 TUCKER: H B Duke Power Co 84/02/27 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E 0 Licensing Branch 4 2pp 22441;216 24X Fiche 30-000, 84/02/29, 8403020317
- F Security, medical, emergency & fire protection plans
- 8403090254 Public version of revised crisis mgt plan implementing procedures, including Procedures 5 3 4 re scheduling/pianning support group, 5,3.6 re radioiogical support group & 5,3.7 re technical support group, W/831107 ltr & JM Felton memo TUCKER, H B Duke Power Co 83/10/31 27ipp 22595.055 24X Fiche 50-000, 83/10/31,8403090254
- 8403140231 Public version of revised emergency plan implementing procedures, including Procedures PT/D/A/4600/06 re exercise & drills:RP/D/A/5700/02 re alert & RP/D/A/5700/03 re site area swergency W/831213 ltr & W Felton 840312 release memo GLOVER:M S . SAMPLE:M . TUCKER:H B . Duke Power Co 83/11/28 DENTON:H R . Dffice of Nuclear Reactor Regulation. Director ADENSAM:E Q . Licensing Branch 4 141pp 22637 177 24X Fiche. 50-369,83/11/28,8403140231.
- 8403090276 Public version of revised emergency plan implementing procedures, including Procedure RP/0/A/5700/Oi re notification of unusual event. EP/0/A/5700/O2 re alert & RP/0/A/5700/O3 re site emergency W/840123 ltr & 840307 memo GLDVER, M.S., GILBERT, Q.D., TUCKER, H.B. Duke Power Co. 84/01/05 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ADENSAM, E.Q. Licensing Branch 4. 102pp 22594 321 24X Fiche 50-369, 84/01/05,8403090276
- 8403070352 Public version of revised emergency plan implementing procedures, including Procedure HP/0/B/1009/05 re first response evaluation of reactor coelent leak & PY/0/A/4600/06 re exercises & drills W/B40210 tr & UM Felton B40302 memo. FOSTER, J. MCCONNELL, T., TUCKER, H. B. Duke Power Co. 84/01/18 ADENBAN & O. Licensing Branch 4 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 84pp 22565 319 24X Fiche: 50-369, 84/01/19, 8403070352
- B403D&0225 Rev ii to crisis mgt plan W/840224 ltr & public info pamphlet. VANONN.T.E. Duke Power Co 84/02/02 &&pp 22516 199 24X Fiche, 50~000, 84/02/02, 84030&0225.
- 8403060106 Changes 0-2 to Emergency Plan Implementing Procedure PF/O/A/4600/11, "Function Check of Emergency Vehicle at Equipment." W/840224 ltr.

 KCDONALD:B.A., FOBTER:J., TUCKER:H.B. Duke Power Co. 84/02/10

 JENTON:H.R. Office of Nuclear Reactor Regulation, Director ADENSAM:E 0. Licensing Branch 4. 32pp. 22506,149 24X

 Fiche: 50-359,84/02/10,8403060106
- B403160101 Forwards IE Insp Repts 50-369/84-03 & 50-370/84-03 on 840130-31 No violations or deviations identified DANCE: H C Division of Project & Resident Programs 84/02/16, TUCKER; H. B. Duke Power Co 2pp. 22652; 341 24% Fiche: 50-369, 84/02/16, 8403160101

- --8403160111 IE Insp Repts 30-369/84-03 & 50-370/84-03 on 840130-31 No violations or deviations identified Major areas inspected emergency preparedness area of protective action decisionaling CLINE, W E Region 2, Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Safety 84/02/15 3pp 22652 343 24X Fiche 50-369,84/02/16,8403160101
- 8403020254 Ack receipt of 840125 & 831010 itrs transmitting Revs & & 5 to guard training & qualification plan respectively Revs consistent w/100FR50 54(p) & acceptable LEWIS,R C Division of Project & Resident Programs 84/02/29 TUCKER,H B Duke Power Co 2pp 22439 003 24X Fiche 50-369,84/02/29,8403020254
- 8403290275 Forwards IE Insp Repts 50-369/84-02 & 50-370/84-02 on 840213-17 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/03/01 TUCKER.H B Dute Power Co 2pp 22800 083 24X Fiche 50-369.84/03/01.8403290275
- --8403290290 lE Insp Repts 50-369/84-02 & 50-370/84-02 on 840213-i7 No violations or deviations identified Major areas inspected emergency preparedness STODDART.P O Region 2. Office of Director JENKING.OR Division of Emergency Preparedness & Materials Safety 84/02/29 7pp 22800 085 24% Fiche 50-369,84/03/01.8403290275
- 8403160278 Extends invitation to attend 840316 workshop to discuss IOCFR50.App R requirements & results of recent insp to help resolve misunderstanding associated w/requirements LEWIS.R C Division of Project & Resident Programs 84/03/02 TUCKER.H B Duke Power Co ip 22660 274 24X Fiche 50-000.84/03/02.8403160278
- 8403120110 Advises that 840116 Rev 16 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable LEWIS.R C Division of Project & Resident Programs 84/03/08 TUCKER.H B Duke Power Co 2pp 22588 200 24X Fiche 50-369.84/03/08.8403120110
- 8403270230 Forwards Rev 19 to security plan Rev withheld (ref 10CFR73 21) TUCKER,H B Duke Power Go 84/03/16 D'REILLY,J P Region 2. Office of Director ip 22772 129 24% Fiche 50-369,84/03/16. 8403270230
- 8403300022 Advises that 83i122 Rev 17 to physical secruity plan consistent w/provisions of 10CFR50 54(p) & acceptable LEWIS.R C Division of Project & Resident Programs 84/03/26 TUCKER.H B Duke Power Co 3pp 22822 179 24X Fiche 50-369.84/03/26.8403300022
- P. Operating license stage documents & correspondence
- 8403120210 Forwards Amends 29 & 10 to Licenses NPF-9 & NPF-17, respectively & safety evaluation Amends change Tech Specs re response time for steam line isolation & surveillance requirements for sprinkler sys valves
 ADENBAM.E Q Licensing Branch 4 84/02/29 TUCKER, H B Duke Power Co 3pp 22419 310 24X Fiche 50-369,84/02/29,8403120210
- --8403120213 Amends 29 & 10 to Licenses NPF-9 & NPF-17, respectively, changing Yech Bpecs re response time for steamline isolation, deleting mechanical snubbers & surveillance requirements for sprinkier sys valves ADENBAM, E 0 Licensing Branch 4 84/02/27 27pp 22619 312 24X Fiche 50-369,84/02/29.8403120210
- --8403120216 Bafety evaluation supporting Amends 29 & 10 to Licenses NPF-9 & NPF-17.rsepectively * Office of Nuclear Reactor Regulation, Director 22619 339 24X Fiche: 50-369,84/02/29,8403120210
- 8403190257 Forwards "Steam Pressure Buppression Characteristics of Water-Boluble Plastic Mambrane Shielded Ice for Ice Condenser Containment Nuclear Power Plants "
 TUCKER, H B Duke Power Co 84/03/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E 0 Licensing Branch 4 7pp. 22672, 102 24% Fiche 50-000, 84/03/07.8403190257
- --8403190261 "Steam Pressure Suppression Characteristics of Hater-Soluble Plastic Membrane Shielded Ica for Ica Condenser Containment Nuclear Power Plants " Supporting documentation enci SCRABIS.C M Westinghouse Electric Corp 83/06/30 125pp 22672 109 24X Fiche 50-000,84/03/07.8403190257

- 8403130136 Forwards proprietary info to support NRC review of proposed amends to Licenses NPF-9 & NPF-17 Info changes operating limitations affected by optimized fuel assembly design for Unit i/Cycla 2 reload Info withheld (ref 10CFR2 790) TUCKER.H B Dute Power Co 84/03/09 DENTON.H R Office of NUCLEAR Reactor Regulation, Director ADENBAM E O Licensing Branch 4 5pp 22643 020 24X Fiche 50-369,84/03/09.8403130156
- 840329014B Forwards Rev 6 to "McGuire Unit i Pump & Valve Inservice Testing Program" & Rev 2 to "McGuire Unit 2 Pump & Velve Inservice Testing Program"

 TUCKER, H B Duke Power Co 84/03/16 DENTON, H R Defice of Nuclear Reactor Regulation, Director ADENBAM, E. 0 Licensing Branch 4 1p 22806 036 24% Fiche 50-369, 84/03/16, 8403290148
- --8403270134 Rev 6 to "McGuire Unit 1 Pump & Valve Inservice Testing Program" * Buke Power Co 84/03/16 13pp 22806 037 24x Fiche 50-369,84/03/16,8403290148
- --8403270164 Rev 2 to "McGuire Unit 2 Pump & Valve Inservice Testing Program " # Duke Power Co 84/03/16 13pp 22806 050 24k

Fiche 50-367, 84/03/16, 8403270148

- B40322003B Forwards "Spent Fuel Pools Remark Mod. Safety & Environ Analysis " Analysis supple info to enable datailed safety avaituation of B40217 license amend request TUCKER. H B Duke Power Co B4/03/20 DENTON. H R Office of Nuclear Reactor Regulation, Director ADENBAM, E 9 Licensing Branch 4 ip. 22715 001 24% Fiche 50-369, 84/03/20, 8403220038
- --8403220044 "Spent Fuel Pools Rerack Mod.Bafety & Environ Analysis "
 W/26 oversite drawings Aperture cards are available in PDR
 + Duke Power Co 84/03/20 120pp 22715 002 24X
 Fiche 50-369, 84/03/20, 8403220038
- 8403270243 Forwards addi documentation of acceptability of "claer & bright" test proposed in Tech Spec change submitted by B31118 ltr Demonstrations revealed that "cleer & bright" more sensitive than "water & sediment" test TUCKER.H S Dute Power Co 84/03/20. DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E O Licensing Branch 4 2pp 22772 021 24X Fiche: 50-369, 84/03/20.8403270243.
- 8403270267 Rev to BG1212 application for emend to Litenees NPF-9 & NPF-12. changing listed Tech Spec bases, per Y Hsii & MS Dumenfeld 840315 & i6 telcoms.respectively Westinghouse proprietary into uithheld (ref 10CFR2 70)
 TUCKER.H B Dute Power Co 84/03/23 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch 4 3pp 22800 092. 24X Fiche 50-369.84/03/23.8403290267
- --8403290273 Revised proposed Tech Bpecs clarifying & correcting 831212 amends to operating conditions for reactor core, radial peaking factor rept & special repts # Buke Power Co 84/03/23 3pp 22800.075 24X Fiche 50-369,84/03/23,8403290267
- --8403290279 Requests withholding of proprietary info requested by util from public disclosure (ref 10CFR2 790) Affidavit AH-76-60 dtd 761202 encl HIESEMANN.R A Westinghouse Electric Corp 84/03/14. DENTON,H R Office of Nucleer Reactor Regulation, Director 10pp 22800 100 24X Fiche 50-369,84/03/23,8403290267.
 - 9403290282 Nonproprietary info reflecting use of Rosemount resistance temp detector = Westinghouse Electric Corp 84/03/23 57pp 22800 110. 24X Fiche 50-359,84/03/23,8403270257
 - Inspection reports, IE Bulletins & correspondence
- 403L60110 Forwards IE Insp Rapts 30-369/84-01 & 50-370/84-01 on 8401R3-27 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/15 TUCKER.H B Duke Power Co 2pp 22632 346 24X Fiche: 50-369, 84/02/15, 8403160110.
- 8403160120 IE Insp Repts 50-369/84-01 k 50-370/84-01 on 840123-27 No violations or deviations identified Hajor areas inspected plent water chemistry & inservice testing of pumps & valves. ROSS, W J Region 2, Office of Director BLAKE, J. J Division of Engineering & Operational Programs 84/02/10. lipp 22652-348 24X Fiche 50-369.84/02/15,8403160110
- 8403160101 Forwards IE 1nsp Repts 50-369/84-03 & 50-370/84-03 on 840130-31 No violations or deviations identified. DANCE H C Division of Project & Resident Programs 84/02/16, TUCKER, H B. Duke Power Co 2pp 22652 341 24X Fiche 50-369,84/02/16,8403160101

- --B403160111 IE Insp Repts 50-369/84-03 & 50-370/84-03 on B40130-31 No violations or deviations identified Major eress inspected emergency preparedness aree of protective action decisionmeking CLINE, W E Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Sefety B4/02/15 3pp 22652 343 24X Fiche 50-369,84/02/16,8403160101
- 8401190072 IE Info Natice 84-13, "Potential Deficiency in Mater Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E,L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc 118pp 22909 239 24X Fiche 50-000.84/02/28,8401190072
- 8403270275 Forwards IE Insp Repts 50-369/84-02 & 50-370/84-02 on 840213-17 No violations or deviations identified DANCE: H C Division of Project & Rasident Programs 84/03/01. TUCKER: H B Duka Power Co 2pp 22800 083 24X Fiche 50-369.84/03/01.8403290275
- --8403270270 IE Insp Repts 50-369/84-02 & 50-370/84-02 on 840213-17 No violetions or deviations identified Major areas inspected emergency preparedness BTODDART.P @ Region 2, Office of Director JENKINS.G. R. Division of Emergency Preparedness & Materials Safaty. 84/02/29 7pp. 22800:085 24% Fiche 50-369,84/03/01.8403290275.
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC," Svc list encl. GRACE, J N. Division of QA: Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche: 50-000:84/03/02,8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Autometic Sprinkler Sys Valves to Opereta " Svc list and JORDAN,E.L. Division of Emergency Preparedness & Enginearing Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22533 098. 24X Fiche. 50-000.84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Raleases," Byc list encl JORDANN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217. 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl.

 JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553:336 24X Fiche 50-000.84/03/05.8402090011
- 8402070024 IE Info Notice 84-09. Rev i. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Bys." Svc list enci. JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/07 Consolidated Edison Co. of New York. Inc 118pp 22635 049. 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list enc! JDRDAN,E L Division of Emergency Preparedness & Engineering Rasponse (Post 630103) 84/03/07 Consolidated Edison Co of New York, Inc. 1189p. 22584 186, 24X Fiche: 50-000, 84/03/07, 8402090028.
- 8403160297 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-45 % 50-370/83-52 LEMIS.R C Division of Project & Rasident Programs. 84/03/07. TUCKER:H B Dute Power Co 2pp. 22660 041. 24X Fiche 50-369.84/03/07.8403160297
- --8403160304 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-45 & 50-370/83-52, Util will be informed of acceptability of corrective actions at later date LEMIS.R C Division of Project & Resident Programs 84/02/21, TUCKER.H B. Duke Power Co 1p 22660:043, 24X Fiche 50-369,84/03/07,8403160297.
- --8403160313 Responds to NRC 840104 ltr re violations noted in IE Insp Repts 50-369/83-45 & 50-370/83-52 Violetion disputed, Steps involved in surveys of eipborne effluent hazards listed, TUCKER.H B Duke Power Co 84/02/03 O'REILLY, J.P. Region 2, Office of Director. 3pp 22660.044 24X Fiche: 50-369, 84/03/07, 8403160297
- --B403160317 Forwards IE Insp Rapts 50-369/83-45 & 50-370/83-52 on 831206-09 & notice of violation LEWIS.R.C. Division of Project & Resident Programs, 84/01/04 TUCKER.H B Duke Power Co. 2pp 22660.047. 24X Fiche 50-369.84/03/07.8403160297

- --8403160322 Notice of Violation from insp on 831206-09 * Region 2, Office of Director 84/01/04 ip 22660 049 24X Fich: 50-369,84/03/07,8403160297
- --8403160329 IE Insp Repts 50-369/83-45 & 50-370/83-52 on 831206-09 Violation noted failure to peform adequate surveys for release of airborns effluents to unrestricted areas KUZO, 0 B Region 2. Office of Director MONTOOMERY, D N Division of Engineering & Operational Programe 83/12/30 16pp 22660:050. 24X Fichs 50-369.84/03/07.8403160297
- 8402070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Byx " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402070031
- 8402070043 IE Info Notice 84-19, "Two Evants Involving Unauthorized Entries into PWR Reactor Cavitias" Svc 11st encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edieon Co of New York, Inc 123pp 22823 229 24X Fichs 50-000,84/03/21,8402070043
- B402090044 IE Info Notice B4-20, "Svt Life of Relays in Safety-Related Bys " Svt list ent! JORDAN, E. Davision of Emergency Preparedness & Engineering Response (Post B30103) B4/03/21 Consoildated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8402R10130 Monthly operating repts for Jan 1984 W/840215 ltr REAVIS, J. A. , TUCKER, H B. Dute Power Co 84/01/31 8pp 22316 349 24X Fiche, 50-369, 84/01/31, 8402210150
- 8403200123 Monthly operating repts for Feb 1984 W/840313 itr REAVIB.T A., TUCKER.H B Dute Power Co 84/02/29 Bpp 22697 103 24X Fiche 50-369.84/02/29.8403200123
- B. Reportable occurrences, LERs & related correspondence
- B2iili0314 Forwards evaluation of Bi0825 overpressurization of suction iines to turbine driven auxiliary feedwater pump Relief capability may be needed for check valves ZUKOR, D J. Reactor Operations Analysis Branch. 82/i1/02 MICHELBON.C Director's Office 4pp 22775 231 24X Fiche: 50-369,82/11/02,82iill0514
- 8403280332 Forwards preliminary results of natural circulation analyses for 811111 translent at McQuire & 800605 natural circulation low power test at North Anna CHARLTON,T R EG&O. Inc 83/09/22 LITTENEKER.P E Energy. Dept of, Ideho Operations Office 29pp. 22807 259 24X Fiche 50-000.83/09/22,8403280332
- 8403150181 Forwards "Falluras in Upper Head Injection Bys " Licensees taking action to resolve setpoint drift on Barton level transmitters No AEOD action recommended ZUKOR, D. J. Reactor Operations Analysis Branch, 84/02/28, 8EYFRIT, K. V Reactor Operations Analysis Branch ip 22646, 272 24X Fiche; 50-000, 84/02/28, 8403150181
- --8403150183 "Failures in Upper Head Injection 8ys." AEOD engineering evaluation rept.
 ZUKOR: A Director's Office 84/02/28, 8pp. 22646 273 24X Fichs 80-000,84/02/28,8403150181
- 8403130332 LER 84-002-00 on 840130, reactor protection sys initiated trip following voltage spike in loop C Caused by failure of loop C laad/lag card of process control sys Faulty card replaced H/840229 ltr.
 NARDDCI,P.B., TUCKER,H B. Duke Power Co 84/02/29 3pp 22607:146 24X Fiche, 50-369, 84/02/29, 8403130332
- DOCKET 50-370 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 2
- E. NRC Safety Evaluation Report (BER), suppls & correspondence
- 8403020317 Forwards Rev 10 to "Analysis of Hydrogen Control Heasures at McQuire Nuclear Station," per SSER 7 (NUREG-0422) TUCKER, H. B. Duke Power Co 84/02/27. DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENSAN, E o Licensing Branch 4. 2pp. 22441 216 24X Fiche. 50-000, 84/02/27, 8403020317.

- F Security, medical, emergency & fire protection plans
- 8403090234 Public version of revised crieis mgt plan implementing procedures, including Procedures 5 3 4 re scheduling/planning support group, 5 3 6 re radiological support group & 5 3 7 re technical support group W/83ii07 ltr & UM Felton memo TUCKER, H B Duks Power Co 83/10/31 27ipp 22595 055 24X Fiche 50-000:83/10/31,8403090254
- 8403140231 Public version of revised emergency plan implementing procedures including Procedures PY/D/A/4600/06 re exercise & drills, RP/0/A/5700/02 re alert & RP/0/A/5700/03 re site area swergency W/B31213 ltr & JM Felton 840312 release memo OLOVER, M 8 . SAMPLE, M . TUCKER, H B Duke Power Co B3/11/28 DENTON, H R Office of Nuclear Reactor Regulation. Director ADENSAM, EO Licensing Branch 4 141pp 22637 177 24X Fiche 50-369, 83/11/28,8403140231
- 8403070276 Public version of revised emergency plan implementing procedures, including Procedure RP/0/A/5700/01 re notification of Unusual event.EP/0/A/5700/02 re alert & RP/0/A/5700/03 re site emergency W/B40123 ltr & B40307 memo OLOVER.H 8 , OILBERT.Q D , TUCKER.H B Duke Power Co 84/01/05 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E Q Licensing Branch 4 102pp 22594 321 24X Fichs 50-369,84/01/05,8403090276
- 8403070352 Public version of revised emergency plan implementing procedures, including Procedure HP/0/B/1009/05 re first response evaluation of reactor coolant leak & PT/0/A/4600/06 re exercises & drills W1840210 ltr & UN Felton B40302 mamo FOBTER, J. MCCONNELL, T. TUCKER, H B Duke Power Co B4/01/18 ADENSAM, E Q Licensing Branch 4 DENTON, H R Office of Nuclear Reactor Regulation, Director B4pp 22565 319 24% Fiche 50-369,84/01/18,8403070352
- 8403060225 Rev ii to crisis mgt plan W/840224 ltr & public info pamphlet VAUQHN:T E Duke Power Co 84/02/02 66pp 22516 i89 24X Fiche 30-000:64/02/02,8403060225
- 8403040106 Changes 0-2 to Emergency Plan Implementing Procedure PT/0/A/4600/1i. "Function Check of Emergency Vehicle at Equipment " W/840224 ltr HCDGNALD.D A, FUSTER.J., TUCKER.H B Duke Power Co 84/02/10 DENTON.H.R Office of Nuclear Reactor Regulation, Director ADENSAM.E 0 Licensing Branch 4 32pp 22506 149 24X Fiche 50-369,84/02/10,8403060106
- 8403160101 Forwards IE insp Repts 50-369/84-03 & 50-370/84-03 on 840130-31 No violations or deviations identified DANCE:H C Division of Project & Resident Programs 84/02/16 TUCKER:H B Duke Power Co 2pp 22652 341 24X Fiche 50-369,84/02/16,8403160101
- --8403160111 IE Insp Repte 50-367/84-03 & 50-370/84-03 on 840130-31 No violations or deviations identified Major areas inspected mergency preparedness area of protective action decisionmaking CLINE, W E Region 2. Office of Director 84/02/15 3pp. 22652 343 24X Fiche 50-367,84/02/16,8403160101
- 8403020234 Ack receipt of 840125 & 831010 Itre transmitting Revs & & 5 to guard training & qualification plan, respectively Revs consistent w/10CFR50 54(p) & acceptable LEHIS, R C Division of Project & Resident Programs 84/02/29 TUCKEN, H B Duke Power Co 2pp 22437 003 24X Fiche 50-369,84/02/29,8403020254.
- 8403290275 Forwards IE Inep Repts 50-369/84-02 & 50-370/84-02 on 840213-17 No violations or deviations identified BANCE.H C Division of Project & Resident Programs 84/03/01 TUCKER.H.B Duke Power Ca 2pp 22800 083 24X Fiche 50-349,84/03/01,8403290275
- --8403270270 IE Insp Repts 50-349/84-02 & 50-370/84-02 on 840213-17 No violations or deviations identified Major areas inspected emergency preparedness STODDART.P G. Region 2. Office of Director 84/02/27 7pp 22800.085 24X Fichs 50-349,84/03/01.8403290275
- 8403160278 Extende invitation to attend 840316 workshop to discues 10CFR30. App R requirements & results of recent insp to help resolve Misunderstanding associated w/requirements LEWIG, R C Division of Project & Resident Programs 84/03/02 TUCKER.H. B Duke Power Co 1p 22660 274 24X Fichs. 50-000.84/03/02.8403160278
- 8403120110 Advises that 840116 Rev 16 to physical security plan consistent w/provisions of 10GFR30 54(p) & acceptable LEMIS,R C Division of Project & Resident Programs 84/03/08 TUCKER,H B Duke Power Co 2pp 22588 200 24X Fiche 50-369,84/03/08,8403120110

- 8403270230 Forwards Rev 19 to security plan Rev withheld (ref 100F873 21)
 TUCKERI B Dute Power Co 84/03/16 O'REILLY, J P Region 2, Office of Director 1p 22772 129 24X Fiche 50-369.84/03/16.
- 8403300022 Advises that 831122 Rev 17 to physical secruity pian consistent Wyprovisions of 10CFR50 34(p) & acceptable LEWIS.R C Division of Project & Resident Programs 84/03/26 TUCKER.H B Dute Power Co 3pp 22822 179 24X Fiche 50-369.84/03/26.8403300022
- P Operating license stage documents & correspondence
- 8403130341 Forwards "McGuire Nuclear Station Unit 2 Startup Rept," addressing results of startup testing from initial fuel loading through testing at 90% full power Supplementary repts will be submitted every 3 months until operation TUCKER.H B Dute Power Co 84/02/08 O'REILLY, J P Region 2, Office of Director 1p 22606 129 24% Fiche 50-370, 84/02/08, 8403130341
- --8403130344 "McQuire Nuclear Station Unit 2 Startup Rept "
 Dute Power Co 84/02/08 352pp 22606 130 24X
 Fiche 50-370.84/02/08.8403130341
- B403120210 Forwards Amends 29 & 10 to Licenses NPF-9 & NPF-17, respectively & safety evaluation Amends change Tech Specs re response time for steam line isolation & surveillance requirements for sprintier sys valves ADENSAM E 9 Licensing Branch 4 B4/02/29 TUCKER, H B Duke Power Co 3pp 22619 310 24X Fiche 50-369.84/02/29.8403120210
- --8403120213 Amends 29 & 10 to Licenses NPF-9 & NPF-17, respectively, changing Tech Specs re response time for steamline isolation deleting mechanical anubbers & surveillance requirements for sprintier sus valves ADENSAM.E © Licensing Branch 4 84/02/29 27pp 22619 312 24X Fichs 50-369,84/02/29,8403120210
- --8403120216 Safety evaluation supporting Amends 29 & 10 to Licenses NPF-9 & NPF-17, respectively 9 Office of Nuclear Reactor Regulation, Director 84/02/29 4pp 22619 339 24X Fiche 50-369,84/02/29,8403120210
- B403190237 Forwards "Steam Pressure Suppression Characteristics of Water-Soluble Plastic Membrane Shielded ice for Ice Condenser Containment Nuclear Power Plants "
 TUCKER, H B Duke Power Co 84/03/07 DENITON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E Q Licensing Branch 4 7pp 22672 102 24% Fiche 30-000, 84/03/07, 8403190257
- 8403150156 Forwards proprietary info to support NRC review of proposed amends to Licenses NPF-9 & NPF-17 Info changes operating immitations affected by optimized fuel assembly design for Unit 1/Cycle 2 reload info withheld (ref 10CFR2 790) TUCKER-H B Duke Power Cs 84/03/09 DEXTON-HR Office of Nuclear Reactor Regulation. Director ADENSAN-E Q Licensing Branch 4 Spp 22643 020 24X Fishe 50-369,84/03/09.8403150156
- 8403290148 Forwards Rev 6 to "McGuire Unit 1 Pump & Valve Inservice Testing Program" & Rev 2 to "McGuire Unit 2 Pump & Valve Inservice Testing Program"
 TUCKER: HS Duke Power Co 84/03/16 DENTON, HR Office of Nuciear Reactor Regulation, Director ADENSAM, E G Licensing Branch
 4 ip 22806 036 24% Fiche 50-369,84/03/16,8403290148
- 840322003B Forwards "Spent Fuel Pools Rerack Mod. Safety & Environ Analysis " Analysis suppls info to enable detailed safety evaluation of 840217 license amend request TUCKER, H B Duke Power Co 84/03/20 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAN, E G Licensing Branch 1p 22715 001 24% Fiche. 50-369, 84/03/20, 8403220038
- --8403220044 "Spent Fuel Pools Rerack Mod. Bafety & Environ Analysis "
 W/26 oversize drawings Aperture cards are available in PDR
 4 Dute Power Co 84/03/20 120pp 22715 002 24X
 Ficha 50-369,84/03/20,8403220038
- 8403270243 Forwards addl documentation of acceptability of "clear & bright" test proposed in Tech Spec change submitted by 831118 its Demonstrations revealed that "clear & bright" more sensitive than "water & sediment" test TUCKER, H B Duke Power Co 84703/20. DENTON, H R Dffice of Ruclear Reactor Regulation. Director ADENSAM, E O Licensing Branch 4 2pp 22772 021 24% Fiche 50-369, 84/03/20, 8403270243

- 8403290267 Rev to 831212 application for amend to Licenses NPF-9 & NPF-12, changing listed Tech Spec bases, per Y Hsii & NPF-9 & HB Dunenfeld 840315 & 16 telcons, respectively Westinghouse proprietary info withheld (ref 100FR2 790)
 TUCKER, HB Duke Power Co 84/03/23 DENTON, HR QFfice of Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch 4 3pp 22800 092 24% Fiche 50-369,84/03/23,8403290267
- --8403270273 Revised proposed Tech Specs clarifying & correcting 831212 amends to operating conditions for reactor core, radial peaking factor rept & special repts # Duke Power Co 84/03/23 3pp 22800 095 24X Fiche 50-349,84/03/238403270267
- --B403290279 Requests withholding of proprietary info requested by util from public disclosure (ref 10CFR2 770) Affidavit AU-76-60 dtd 761202 enc | B403414 | BENTON.H R Office of Nuclear Reactor Regulation, Director 10pp 22800 100 24X Fiche: 50-369, 84/03/23, 8403290267
- Q Inspection reports, iE Bulietins & correspondence
- 8403160110 Forwards IE Insp Repts 50-369/84-01 & 50-370/84-01 on 840123-27 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/15 TUCKER.H B Duke Power Co 2pp 22652 346 24X Fiche 50-369:84/02/15.8403160110
- --E403160120 iE Insp Repts 50-369/84-01 & 50-370/84-01 on 840123-27. No violations or deviations identified Hajor areas inspected plant water chemistry & inservice testing of pumps & valves ROSB, M. J. Region 2. Office of Director BLAKE, J. J. Division of Engineering & Operational Programs 84/02/10 11pp 22652.348 24X Fichs 50-369.84/02/15.8403160110
- 8403140101 Forwards IE Insp Repts 50-369/84-03 & 50-370/84-03 on 840130-31 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/16 TUCKER, B Dus Power Co 2pp 22652 341 24X Fiche 50-369.84/02/16.8403160101
- --8403160111 IE Insp Repts 30-369/84-03 & 50-370/84-03 on 840130-31 No violations or deviations identified Major aroas inspected, emergency preparedness area of protective action decisionmaking CLINE.W E Region 2. Office of Director JENKINS, Q R Division of Emergency Preparedness & Materials Safety, 84/02/15 3pp, 22652 343 24X Fiche 50-369,84/02/16,8403160101
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/02/28 Consolidated Edison Co of New York, int 115pp 22909 239 24X Fichs 50-000,64/02/28.8401190072
- 8403290275 Forwards IE Insp Repts 50-369/84-02 & 50-370/84-02 on 840213-17 No vigilations or deviations identified DANCE.H C Division of Project & Resident Programs 84/03/01 TUCKER.H B Duke Power Co 2pp 22800 083 24X Fichs 50-369-84/03/01.8403290275
- --8403290290 IE Insp Repts 50-369/84-02 & 50-370/84-02 on 840213-17. No violations or deviations identified, Major areas inspected: emergency preparedness 8T00DART, P O Region 2, Office of Director JENKINB, Q. R Division of Emergency Preparedness & Materials Sefety, 84/02/29, 7pp 22800 085 24X Fichs 50-369,84/03/01,8403290275
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA, 8afeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24% Fichs 50-000.84/03/02.8402070007.
- B40209000B IE Info Notice B4-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list and!

 JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098, 24X Fiche 50-000, 84/03/02, 8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases, "
 Svc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/03/02 Consolidated Edison Co. of New
 York, Inc. 119pp 22553 217 24X Fiche 50-000, 84/03/02, 8402090009

- 8402090011 IE Info Notice 84-17, "Problems H/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl, JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Cansolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05, 8402090011
- 8402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown 8ys " Bvc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/63/07 Consolidated Edison Co of New York, Inc 18pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402040028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Bys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc i18pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403160297 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-369/83-45 & 50-370/83-52 LEWIS.R C Division of Project & Resident Programs 84/03/07. TUCKER, H B Duke Power Co 2pp 22660 041 24x Picke 50-369.84/03/07.8403160297
- --8403166304 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-369/83-45 & 50-370/83-52 Util will be informed of acceptability of corrective actions at later date
 LEMIS.R C Division of Project & Resident Programs 84/02/21
 TUCKER.H B Duke Power Co ip 22660-043 24X
 Fiche 50-369,84/03/07.8403160297
- --8403160313 Responds to NRC 840104 ltr re violations noted in 1E Insp Repts 50-369/83-45 & 50-370/83-52 Violation disputed Staps involved in surveys of airborne effluent hazards listed. TUCKER.H B Duts Power Co. 84/02/03. O'REILLY, J P Region 2. Office of Director 3pp 22660 044 24x Fiche 50-369, 84/03/07. 8403160297
- --8403160317 Forwerds IE Insp Repts 30-369/83-45 & 50-370/83-52 on 831206-09 & notice of violation. LENTB,R C Division of Project & Resident Programs 84/01/04 TUCKER,H B Duke Power Co 2pp 22660 047 24X Fiche: 50-369,84/03/07,8403160297
- --8403160322 Notice of violation from insp on 831206-09 * Region 2, Office of Director 84/01/04 1p 22660 049 24X Fiche, 50-369,84/03/07,8403160297
- --B403160329 IE Insp Repts 50-369/83-45 & 50-370/83-52 on 831206-09 Violation noted failure to peform adequate surveys for release of althorne effluents to unrestricted areas, KUZO, G B Region 2. Office of Director MONTGOMERY, D M Division of Engineering & Operational Programs 83/12/30 16pp. 24X Fich# 50-369,84/03/07,8403160297
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Sefety Sys " Syc list encl
 DEVOUNG.R C Director's Office, Office of Inspection and
 Enforcement 84/03/12, Consolidated Edison Co. of New York, Inc
 £34pp. 82823 094 24X Fiche 50~000.84/03/12.8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities" Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- B402090044 IE Info Notice B4-20, "Svc Life of Releys in Safety-Related Bys " Byc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche.50-000.64/03/21.6402090044
- R Periodic operating reports & related correspondence
- B402210150 Monthly operating repts for Jan 1784 W/840215 ltr REAVIS J A., TUCKER, H. B. Duke Power Co. 84/01/31 8pp 22316 347. 24% Fiche: 50-369.84/01/31,8402210150
- 8403200123 Monthly operating repts for Feb 1984 W/840313 ltr. REAVIS.T.A., TUCKER.H B Duke Fower Co 84/02/29, 8pp 22697.103 Z4X Fiche: 50-349.84/02/29,8403200123

- 8 Reportable occurrences, LERs & related correspondence
- 8403280332 Forwards preliminary results of natural circulation analyses for Billil transient at McGuire & 800605 natural circulation low power test at North Anna CHARLYON, TR E080, Inc 83/09/22 LITTENEKER, PE Energy, Dept of, Idaho Operations Office 29pp 22807 259 24X Fichs: 50-000,83/09/22,8403280332
- 8403060232 LER 84-003-00 on 840122, during RCS leak test, reactor trip occurred Caused by personnel error Pressure monitored from instrument independent of trip logic Test procedure revised W/840221 ltr
 NARDDCI,P B. TUCKER.H B. Duke Pawer Co. 84/02/21 4pp
 22516 094 24X Fichs 50-370.84/02/21.8403060232
- 8403i30i81 Forwards "Failures in Upper Head Injection Sys " Licensees taking action to resolve setpoint drift on Barton level transmitters No AEOD action recommended ZUKOR, D J Reactor Operations Analysis Branch 84/02/28.

 SEYPRIT.K V Resctor Operations Analysis Branch 1p 22646 272 24X Fiche 30-000,84/02/28,8403i50i81
- --8403150183 "Failures in Upper Head Injection Sys." AEOD enginearing evaluation rept ZUKGR: A Director's Office 84/02/28 Upp 22646 273 24X Fiche 30-000,84/02/28,8403150181
- 8403120173 LER 84-002-00 on 840115,both ND trains declared inoperable when breakers for valves 2ND-18 & 2NB-2A closed Gaused by personnel error, Procedures revised & personnel counseled H/840229 ttr
 NARDOCI.P B , TUCKER.H B Duke Power Co 84/02/29 4pp 22589.175 24X Fiche, 50-370.84/02/29, 8403120173,
- 8403130167 LER 84-004-00 on 840115, chemical & vol control pump 2A ran approx 19 minutes w/o suction Caused by vol control tank outlet isolation valve inadvertently closing & by parsonnel error Pump repaired Personnel counseled W/840229 ltr NARDOCI, P B. TUCKER, H B Duke Power Co 84/02/29 4pp 22608 112 24X Fiche 50-370,84/02/29,8403130167.
- B403120150 LER 84-006-00 on 840203.digital RP1 sys failed, resulting in manual reactor trip Caused by failure of central control card & display card Cards replaced W/B40305 1th RMSDCI.P B. TUCKER.H B Duke Pewer Co 84/03/05 3pp 22585 260 24X Fiche 50-370.64/03/05.8403120150
- 8403150138 LER 84-005-00 on 840202.reactor trip initiated.Coused by personnel mistakenly pushing TRIP button Unit stabilized & fest recovery initiated Personnel counseled H/840305 ltr NARDOCI.P 9. TUCKER.H B Duke Power Co
- 8403190303 Updated RD 370/83-57 shutdown capability never jeopardized & unit could be shut down given fire in annulus w/sprinker isolation valve closed Cause unknown Figure illustrating cable separation and TUCKER, H B Duke Power Co 84/03/07 O'REILLY, J P Region 2, Office of Director, 3pp 82673 183 24% Fiche 50-370,84/03/07,8403190303

DOCKET 50-373 LABALLE COUNTY STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8403200041 Forwards Rev 17 to physical security plan, responding to NRC comments re Rev 14 to plan & addressing measures to secure openings allowing potential access to vital areas Rev withheld (ref 10CFR2.790 & 73 21).

 FARRAR, D. L. Commonwealth Edison Co. 84/02/16 Region 3: Office of Director 1p. 22698 343 24X Ficher 50~373, 84/02/16,8403200041
- 8403020207 Forwards order confirming licenses commitments on emergency response capability, based on info provided in util 830414 & 0825 responses to Generic Ltr 82-33. Suppl 1 to NUREO-0737 SCHMENGER, A Licensing Branch 2 84/02/21 FARRAR, D L Cummonwealth Edison Co 2pp 22494 324 24X Ficher 50-373, 84/02/21. 8403020207
- --8403020221 Order confirming licensee 830414 & 0825 commitments on emergency response capability, per Generic Ltr 82-33, Suppl 1 to NUREG-0737 EISENHUT, D G Division of Licensing 84/02/21 Commonwealth Edison Co 7pp 22494 326 24X Fiche 50-373,84/02/21,8403020207

- 8403050063 Advises that fire protection sys analysis re RCIC ~ RHR high/low pressure interface completed Analysis process described, including failure moder acceptance criteria, evaluation results & mods to be performed SCRROEDER.C H Commonwealth Edison Co 84/03/01 DENTON.H R Depice of Nuclear Reactor Regulation, Director 37pp 22487 232 24X Fiche 50-373,84/03/01,8403050063
- 8403120128 Rev 23 to Procedure LAP 820-3, "Offsite Procedure" * Commonwealth Edison Co 84/03/05 24pp 22590 062 24) Fiche 30-373,84/03/05,8403120128
- 8403120025 Notifies of 840323 regional workshop in Rosemont, IL w/all Region III licensees to discuss fire protection safe shutdown requirements Workshop will provide addl guidance roughtforwards App R requirements Agenda enci SPESSARD, R L Division of Emergency Preparedness & Operational Support 84/03/06 REED, C Commonwealth Edison Co. 3pp 22587 264 24% Fiche 50-373,84/03/06.8403120025
- B403140175 Forwards final Interim Repts 1.2 & 3 re fire detection sysper 831123 request & IE Insp Repts 50-373/83-44 & 50-374/83-48 Detector installations meet intent of NFPA & require no compensatory measures
 SCHROEDER.C W Commonwealth Edison Co 84/03/09 DENYON.H R
 Office of Nuclear Reactor Regulation. Director 4pp 22625 171
 24X Fiche 50-373.84/03/09.8403140175
- --8403140180 Analysis of fire detector locations at Lasalle County Station, final Interim Rept 1 JCHNSON.W A . SCHULTZ.Q R . BALDASBARRA,C Schirmer Engineering Corp 84/02/21 75pp 22625 193 24X Fiche 50-373,84/03/09, 8403140175
- --9403140183 Analysis of fire detector locations at Lasalle County Station, final Interim Rept 2 BREZINSKI, M B . JOHNSON, W A . SCHULTZ, O R. Schirmer Engineering Corp 84/03/06 65pp 22625 298 24X Fiche 50-373, 84/03/09, 8403140175
- --8403140184 Analysis of fire detector locations at Lasalle County Station, final Interim Rept 3 JOHNSON, M A. BCHULTZO 8, PALDASSARRA, C. Schirmer Engineering Corp. 84/03/08 45pp 22626 012 24X Fiche 50-373,84/03/09,
- 8403200256 Forwards info & Rev I to Procedure LTS-1000-36. "Fire Damper Visual insp." per NRC request & IE Insp Repts 50-373/83-44 & 50-374/83-48 SCHROEDER.C & Commonwealth Edison Co 84/03/13 DENTON.H R Office of Nuclear Reactor Regulation. Director 5pp 22697 022 24% Fiche 50-373.84/03/13.8403200256
- --8403200263 Rev i to Procedure LT6-1000-36. "Fire Damper Visual Insp "
 * Commonwealth Edison Co 84/03/05 48pp 22697 027 24X
 Fiche 50~373,84/03/13,8403200256
- B403300244 Forwards NRC position recertain items being appealed by util in fire protection area per B40127 ltr 9CMHENCER, A Licenting Branch 2 B4/03/14 FARRAR, b L Commonwealth Edison Co. 7pp 22840 352 24X Fiche 50-373,84/03/14. B403300244
- 8403220123 Forwards Rev D to Procedure LTE-1900-35, "Fire Damper Operability Test" SCHROEDER.C W Commonwealth Edison Co 84/03/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22716.085 24X Fiche 30-373,84/03/15.8403220123
- ---8403220127 Rev Q to Procedure LTS-1000-35, "Fire Damper Operability Test"

 * Commonwealth Edison Co 84/03/15 85pp 22716 087 24X
 Fiche 50-373,84/03/15,8403220123
- 8903230075 Ack receipt of 831213 & 22 ltrs describing interim fire prevention/protection compensatory measures, per IE Insp. Repts 50-373/83-44 & 30-374/83-48 SPESSARD.R L Division of Emergency Preparedness & Operational Support 84/03/19 REED.C Commonwealth Edison Co ip 22726 293 24% Fiche 50-373.84/03/19.8403230075
- --B40323008i Revises B31i23 & 1213 commitment re fire watch training situations addressed in NFPA 516.per IE Insp Repts 50-373/83-44 & 50-374/83-48 BCHROEDER, C. W. Commonwealth Edison Co. 83/12/22 KEPPLER, J. Q. Region S. Office of Director. 2pp. 22726 274 24X Fiche 50-373, 84/03/19, 8403230075

- --8403230087 Responds to NRC 831212 Itr reviolations noted in IE Insp. Repts 50-373/83-44 & 50-374/83-48 Corrective actions continuous fire watch posted on refuel floor & cable spreading rooms & roving fire watch established SCHROEDER, C. W. Commonwealth Edison Co. 83/12/13 KEPPLER, J. Q. Resion 3, Office of birector 3pp. 22726 276 24X Fichs: 50-373, 84/03/19,8403230075
- 8403200204 Revised emergency plan implementing procedures, including L7P index & Rev 3 to Procedure LZP-1550-6. "Operational Support Ctr Quarterly Surveillance" & Commonwealth Edison Co 84/03/22 13pp 22700 007 24X Fiche 50-373.84/03/22.8403200206

G Adjudicatory correspondence

- 8403260368 Forwards executed signature page for affidavit of M Kaku submitted as attachment to Joint Intervenors 840320 renewal of application for stay REVNOLDS.JR Center for Law in the Public Interest REYNOLDS.JR Joint Intervenors Diablo Canyon DSB 100 84/03/22 PALLADING.N. OILINSKY,V. ROBERTS.T Commissioners 2pp. 22760 133 24X Fiche 50-275.84/03/22,8403260368
- --8403260369 Executed signature page of affidavit of M Kaku in support of B40320 renewal of application for stay MAKU, M Joint Intervenors Diablo Canyon 84/03/21. ip 22760 135 24K Fiche 50~275.84/03/22,8403260368

K Utility Final Safety Analysis Report (FSAR) & amends

- 8403210085 Forwards Amend 64 to FBAR BCHROEDER,C W. Commonwealth Edison Co. 84/03/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22701 001 24X Fichs 50-373,84/03/15.8403210085
- --8403210091 Amend 64 to FSAR Twenty-five oversized drawings enci Aperture cards available in PDR + Commonwealth Edison Co. 84/09/31 48ipp 22701 003 24X Fiche 50-373,84/03/15,8403210085

P Operating license stage documents & correspondence

- 8403050119 Forwards supplemental response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Balem ATHS Events "BARNES, P.L. Commonwealth Edison Co. 84/02/29 DENTON, H. R. Offit of Nuclear Reactor Regulation, Director 26pp. 22488:084 24X Fiche 50-000, 84/02/29, 8403050119
- 8403130400 Forwards 840210 responses to Generic Ltr 83-35 clarifying TMI Item II K 3 31 Util concurs w/NRC position Item should be closed RYBAK, B Commonwealth Edison Co 84/03/02. EISENNUT, D. 0 Division of Licensing 2pp. 22613 143 24X Fichs 50-000,84/03/02,8403130400
- 8403200013 Discusses 840308 telcon w/A Bournia Te RHR & RGIC high/low pressure interface boundary Lists reasons that full open on valve 2612-F051A would not be detrimented to low pressure piping SCHROEDER.C W Commonwealth Edison Co 84/03/13 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp, 22683;355, 24X Fiche 50-373,84/03/13,8403200013
- 8403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs 8vc list encl EISENHUT.D 0 Division of Licensing 84/03/14. Commonweelth Edison Co 20pp 22823 354 24X Fiche 50-000.84/03/14.8403150275
- 8403260122 Discusses differences in Tech Specs per rays to BTS, generic 1trs.NRR requirements & grammatical corrections, Differences between two Tech Specs do not affect edequacy of current Unit i Tech Specs SCHROEDER, C. M. Commonwealth Edison Co. 84/03/21 DENTON, H.R. OFFice of Nuclear Reactor Regulation, Director 1p 22758'132 24% Fiche 50-373,84/03/21,8403260122

G Inspection reports: IE Bulletins & correspondence

8403080114 Forwards IE Insp Repts 50-373/84-04 & 50-374/84-03 en 840131-0203 No noncompliance identified LITTLE, W S Region 3. Office of Director 84/02/23. REED, C Commonwealth Edison Co 2pp. 22559-273 24X Fiche: 50-373,84/02/23, 8403080114

- --8403080125 IE Insp Repts 30-373/84-04 & 50-374/84-03 on 840131-0203 No noncompliance identified Major areas inspected licensee action on previous insp findings & 10CFRSD 55(e) repts CHRISTNOTE, WILLLIAMS, C C Region 3, Office of Director 84/02/23 3pp 22559 275 24X Fichs 50-373,84/02/23,8403080114
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan " Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THOMAS, B Commonwealth Edison Co 84/02/24 KEPPLER, J O Region 3, Office of Director 3pp 22470 i39 24X Fiche 50-000,84/02/24,8403050043,
- --8403050046 Rev 0 to "Corporate Regulatory Performance Improvement Plan" * Commonweelth Edison Co 84/02/27 22pp 22470 142 24X Fiche 50-000,84/02/24,8403050043
- 8403050168 Ack receipt of 840120 & 0207 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-41 & 50-374/83-42 STREETER; JF Region 3, Office of Director 84/02/27 REED, C Commonwealth Edison Co ip 22489 067 24X Fiche 50-373,84/02/27, page 2016.68
- --840305017! Responds to NRC 831207 ltr re violations noted in IE Insp Repts 50-373/83-41 & 50-374/83-42 on 830908,28-29,1020 & 1110 Future changes to inboard fredwater check valves will be conducted per GP 3-51 FARRAR.D.L. Commonwealth Edison Co 84/01/20. KEPPLER.J G Region 3, Office of Director 3pp 22487 068 24X Fiche 50-373,84/02/27,8403050168
- --8403050174 Suppls 840120 response to NRC 831207 ltr re violations noted in IE Insp Repts 30-373/83-41 & 30-374/84-42 Corrective actions mod approval ltr checklist & safety-related/ABME code change procedure will be revised FARRAR, D. L. Commonwealth Edison Co 84/02/09 KEPPLER, J 9 Region 3, Office of Director 4pp. 22489 072 24X Fiche 30-373, 84/02/27, 8403050168.
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22709-239 24X Fiche. 50-000.84/02/28,8401190072
- 8403190290 Forwards IE Inep Repts 50-373/83-54 & 50-374/83-57 on 831219-840210 & notice of violation.
 STREETER, J. F. Region 3, Dffice of Director, 84/02/29 REED, C Commonwealth Edison Co. 2pp 22675 064 24X Fiche 50-373,84/02/29, 8403190290
- --8403190293 Notice of violation from insp on 831219-840210 BTREETER, J. F. Region 3, Office of Director 84/02/29 2pp 22675.066, 24X Fiche, 50-373, 84/02/29, 8403190290
- --8403190279 IE Insp Repts 50-373/83-54 & 50-374/83-57 on 831219-840210 Noncompliance identified, temp gauge utilized in calculating LPCS pump total dynamic head did not have unique number LANKBBURY.R D , WRIGHT.Q , MAURA.F A Region 3, Office of Director. 84/02/27, 10pp. 22675 068, 24X Fiche 50-373.84/02/29, 8403190290.
- B402070007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Byc list encl GRACE.J.N Division of QA. Safeguards & Inspection Programs (Post 830103). B4/03/02 Consolidated Edison Co of New York, Inc 130pp. 22552 327, 24X Fiche 50-000.84/03/02,8402070007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate." Svc list encl JORDAN,E L Division of Emergency Preparedness & Enginearing Response (Post 830103). 84/03/02. Consolidated Edison Co of New York. Inc 122pp 22553:098 24X Fiche 50-000.84/03/02.8402090008
- B402090009 IE Info Notice 84-15, "Raporting of Radiological Releases"
 Byc list encl.
 JORDAN,E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/03/02. Consolidated Edison Co of New
 York, Inc i19pp. 22553 217. 24X Fiche, 50-000, 84/03/02, 8402090009
- 840319006B Forwards IE Insp Repts 50-373/84-02 & 50-374/84-01 on 840116-0210 & notice of violation. 8HAFER.W.D. Region 3, Office of Director 84/03/02, REED, C Commonwealth Edison Co 2pp. 22671 173 24X Fiche 50-373,84/03/02, 8403190068.

- --8403170072 Notice of violation from insp on 840114-0210 SHAFER, W D Region 3, Office of Director 84/03/02 2pp 22671 175 24% Fiche 50-373,84/03/02.8403170068
- ~-B403190076 IE Insp Repts 50-373/84-02 & 50-374/B4-01 on B40116-0210 Noncompliance noted 673 ft elevation of reactor bldg contaminated to level in excess required for posting as controlled area & six valves found unlocked GULDEMOND W G , GUTHRIE, B C , EVANS, C D Region 3, Office of Director B4/02/27 29pp 22671 177 24X Fiche 50-373,84/03/02,8403190068
- 8402090011 IE Info Notice 84-i7. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list enci JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05,8402090011
- B40313034B Ack receipt of B40215 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-373/83-44 & 50-374/83-4B Addl response to 840215 ltr will be submitted following completion of actions on B40127 appeal BPESBARD.R L Division of Engineering B4/03/06 REED.C Commonwealth Edison Co 1p 22616 223 24X Fiche 50-373.84/03/06.860330348
- --8403130357 Responds to NRC 831212 ltr re violations noted in IE Insp Repts 50-373/83-44 & 50-374/83-48 Corrective actions procedures written to require periodic surveillance of lights Some items should not be categorized as violations REED. C Commonwealth Edison Co 84/02/15 KEPPLER, J Q Region 3. Office of Director 20pp 28616 224 24X Fiche 50-373,84/03/06.8403130348
- 8402090024 IE info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc 1ist encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York. Inc. 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR

 Bys " Svc list encl

 JORDAN, E. L. Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/03/07 Consolidated Edison Co. of New

 York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8403140175 Forwards final Interim Repts 1.2 & 3 re fire detection sys, per 831123 request & IE Insp Repts 50-373/83-44 & 50-374/83-48 Detector installations meet intent of NFPA & require no compensatory measures
 8CHRIEDER, C W Commonwealth Edison Co 84/03/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 22625 191 24X Fiche 50-373.84/03/09.8403140175
- B402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Bafety Bys " Syc list enc!
 DEYQUNG:R C Director's Office Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000:B4/03/12.8402090031
- 8403170084 Ack receipt of 840229 ltr informing NRC of staps taken to correct violations noted in IE Insp Repts 50-373/83-53 & 50-373/83-53 & 840-374/83-58 BHAFER, W D Region 3, Office of Director 84/03/13 REED, C Commonwealth Edison Co 1p 22669 319 24X Fiche 50-373,84/03/13,840319084
- --8403190090 Responds to NRC 840130 ltr re violations noted in IE Insp Repts 50-373/83-53 & 50-374/83-58 Corrective actions, control room tag board updated to reflect current status, burned out bulbs replaced & refresher training program developed FARRAR, D L. Commonwealth Edison Co. 84/02/29. KEPPLER, J. 0 Region 3. Office of Director 5pp. 22669 320 24X Fiche 50-373,84/03/13,8403190084.
- B403200256 Forwards info & Rev i to Procedure LTB-1000-36, "Fire Damper Visual Insp," per NRC request & IE Insp Repts 50-373/B3-44 & 50-374/B3-48
 BCHROEDER,C W. Commonwealth Edison Co B4/03/13 DENTON.H R Office of Nuclear Reactor Regulation. Director 5pp 22697 022 24X Fiche 50-373,84/03/13,8403200256
- --8403200263 Rev i to Procedure LT8-1000-36, "Fire Damper Visual Insp " # Commanuealth Edison Co 84/03/05 48pp 22677 027 24X Fishe, 50-373, 84/03/13, 8403200236.
- 8403260225 Documents 840314 distribution of GJ Diederich 840313 memo to RD Walker & W Ouldemond in response to 831128 confirmatory action ltr re integrity of discs & valves 8CHROEDER, C. W. Commonwealth Edison Go 84/03/16 KEPPLER, J G Region 3, Office of Director. 4pp 82757 316 24X Fiche 50-373, 84/03/16, 8403260225

- 8403230075 Ack receipt of 831213 & 22 ltrs describing interim fire prevention/protection compensatory measures.psr IE Insp Repts 50-373/83-44 & 50-374/83-48 SPESSARD.R L Division of Emergency Preparedness & Operational Support 84/03/19 REED.C Commonwealth Edison Co ip 22726 293 24X Fiche 50-373,84/03/19,8403230075
- ~~84032300B1 Revises 831123 & 1213 commitment re fire watch training situations addressed in NFPA 516, per JE Insp Repts 50~373/83~44 & 50~374/83~48 SCHRDEDER.C W Commonwealth Edison Co 83/12/22 KEPPLER.J O Region 3, Office of Director 2pp 22/26 274 24X Fichs 50~373.64/03/59.6403230075
- --8403230087 Responds to NRC 831212 itr re violations noted in IE Insp Repts 50-373/83-44 & 50-374/83-48 Corrective actions continuous fire watch posted on refuel floor & cable spreading rooms & roving fire watch established SCHROEDER, C.W. Commonwealth Edison Co. 83/12/13 KEPPLER, J.O. Region 3, Office of Director 3pp. 22726-296 24X Fiche 50-373,84/03/19,8403230075
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER.J & Region 3. Office of Director 3pp 22/30 142 24X Fiche 50-000. 84/03/20.8403230088
- --B403230126 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresdem.Quad Cities, Zion & LaGalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations" " Commonwealth Edison Co B4/02/29 22pp 22730 165 24X Fiche 50-005,84/03/20,840323008
- 8403260196 Forwards responses to IE Bulletin B3-07. "Apparently Fraudulent Products Sold by Ray Miller, Inc " Guad Cities supplied w/piping maths from Ray Miller, Inc during const Evaluation encl Concerns of IE Bulletin B3-06 satisfied BARNES, P L Commonwealth Edison Co 84/03/20 KEPPLER, J 9 Region 3. Office of Director. 19pp 22756 185 24% Fiche 50-000.84/03/20.8803260196
- 8402090043 IE info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 227 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Bafety-Related Bys " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403060150 Rev 0 to "Rept of Radioactive Effluents, Jul-Dec 1983 " W/ 840116 ltr *, DIEDERICH, G J Commonwealth Edison Co 83/12/31 KEPPLER, J G Region 3, Office of Director 9pp 22513 337 24X Fiche 50-373, 83/12/31, 8403060150
- 8403080197 "Rept of Occupational Personnel Radiation Doses,1983 "
 W/840227 ltr
 SCOTT.J S Commonwealth Edison Co 83/12/31 13pp 22559:099
 24X Fichs 50-000,83/12/31,8403080197
- 8403220120 Annual whole body external exposures for 1983 W/840316 1tm RYBAK.B Commonwealth Edison Co 83/12/31 7pp 22716/007 24X Fiche 50-000.83/12/31.8403220120
- 8403020138 Monthly operating rept for Jan 1984 W/840215 ltr L1N,D L , DIEBERICH.Q J Commonwealth Edison Co 84/01/31, 31pp 22442 034 24X Fiche 50-373,84/01/31,8403020138
- 8403160261 Monthly operating rept for Feb 1984 W/840309 ltr LIN.D. DIEDERICH.O.J. Commonwealth Edison Co. 84/02/29 16pp 22660 256 24x Fiche 50-373,84/02/29,8403160261

- 8 Reportable occurrences, LERs & related correspondence
- 8403120080 Updated LER 83-129/03x-1 on 831018.LIS-RR-1 calibr exceeded critical date by 1 day Frequency changed from 18 months to 3 months & not entered on computer Caused by personnel error Surveillance completed W/840210 ltr PRESLEY,K E. DIEDERICH,O J Commonwealth Edison Co 84/02/04 KEPPLER,J O Region 3, Office of Director 3pp 22590 301 24x Fiche 50-373,84/02/04,8403120080
- 8403120034 LER 83-048/03X-1 on 830310, mechanical snubber locked between hot & cold settings. Caused by excessive heat in upper drywell Failed snubbers replaced, stroke test performed & temp sys & monitoring plan initiated W/440214 ltr SPENCER.D A. DIEDERICH.9 J. Commonwealth Edison Co. 84/02/14 KEPPLER.J G. Region 3. Office of Director 3pp 22588 041 24X Fiche 50-373,84/02/14,8403120054
- 8403120095 Updated LER 83-117/03X-1 on 830920 & 30.RHR HX B outlet valve limit suitches temporarily changed.allowing wedge travel to stop W/840215 ltr PETERS.M A. DIEDERICH.G J Commonwealth Edison Co. 84/02/14 KEPPLER.J G Region 3. Office of Director. 3pp 22585 231, 24X Fiche 50-373.84/02/14, 8403120095
- 8403010380 Confirms 840228 enforcement conference at Region III ofc to discuss ESF reset function deficiencies.per 840222 discussion Meeting notice enci NDRELIUS.C E Division of Project & Resident Programs 84/02/28 REED.C Commonwealth Edison Co 2pp 22434 059 24X Fiche 50-373,84/02/28.8403010380
- 8403120020 LER 84-007-00° on 840203, during surveillance.RCIC initiated while reactor at 89% power Caused by improperly placed ohmseter Water level & pressure quickly brought under control Technician involved disciplined.W/840301 ltr WESTPHAL.B S , DIEDERICH.G J Commonwealth Edison Co 84/03/02 4pp 22586 268 24% Fiche.50-373,84/03/02,8403120020
- 8403230015 LER 84-009-00. on 840219, noncoincident scram occurred from upscale trip on intermediate range monitor (IRM) 1A Caused by personnel bumping into IRM IA cable Scram reset & parsonnel counseled re sensitivity of cables W/840315 1tr 8AKER P E . DIEDERICH, G J Commonwealth Edison Co 84/03/13 3pp 22727 349 24% Fiche 50-373,84/03/13,8403230015
- 8403230017 LER 84-008-00. on 840218, noncoincident scram occurred from upscale trip on intermediate range monitor E Caused by maint personnel inadvertently bumping cable Scram reset & personnel notified W/840315 ltr
 BAKER, P E . DIEDERICH, O J Commonwealth Edison Co 84/03/13 Jpp 22726 356 24x Fichs 50-373,84/03/13,8403230017
- 8403230027 LER 84-010-00 on 840219, noncoincident scram occurred from upscale trip on intermediate range monitor (IRM) A Caused by inadvertant bumping of IRM by maint personnel Personnel notified of sensitivity of IRM cables W/840315 ltr
 BAKER:P E , DIEDERICH,G J Commonwealth Edison Co 84/03/13 3pp 22730 330 24X Fiche 50-373,84/03/13,8403230027.
- 8403190117 LER 84-011-00 on 840213 scram resulted when turbine generator tripped from loss of condenser vacuum Caused by expansion joint in low pressure heater extraction steam line 14A failure New joints installed W/840314 ltr WESTPHAL,8 S. DIEDERICH,C.J. Commonwealth Edison Co. 84/03/14 5pp 22666 268 24X Fiche 50-373.84/03/14,8403190117
- 8403200032 LER 84-013-00 on 840214, nine of 16 mein steam high flow switches found out of spec, in violation of Tech Spec limits Caused by increase in follower drag on Barton 288A switch Instruments recalibr W/840315 ltr REIS.J B. DIEDERICH.G.J Commonwealth Edison Co 84/03/15. 6pp 22697 118 24X Fiche: 50-373,84/03/15,8403200032
- 8403200204 LER 84-012-00 on 840214, containment leakage limit exceeded Tech Spec limits Caused by misalignment problem Valve realigned W/840315 ltr.

 DUS.R S., DIEDERICH, O J Commonwealth Edison Co 84/03/15 4pp 22686 350 24X Fiche. 50-373,84/03/15,8403200204
- DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 84032&0194 Responds to D9 Eisenhut 840308 itr to C Reed re BWR 878 certification Tech Specs accurately reflect plant & FSAR. REED: C Commonwealth Edison Co 84/03/21 DENTON.H R. Office of Nuclear Reactor Regulation, Director 3pp 22756,167 24X Fiche 50-374,84/03/21,8403260194

- F Security, medical, emergency & fire protection plans
- B403200041 Forwards Rev 17 to physical security plan, responding to NRC comments re Rev 14 to plan & addressing measures to secure openings allowing potential access to vital areas Rev withheld (ref 10CFR2 790 & 73 21)
 FARRAR, D. L. Commonwealth Edison Co 84/02/16 Region 3, Office of Director 1p 22678 343 24X Fiche 50-373,84/02/16,8403200041
- B403050063 Advises that fire protection sys analysis re RCIC RHR high/low pressure interface completed Analysis process described including failure mode, acceptance criteria, evaluation results & mods to be performed BCHRDEDER, C W Commonwealth Edison Co B4/03/01 DENYON, H R Defice of Nuclear Reactor Regulation, Director 39pp 22487 232 24X Fiche 50-373,84/03/01.8403050063
- 8403120128 Rev 23 to Procedure LAP 820-3, "Offsite Procedure," # Commonwealth Edison Co 84/03/05 24pp 22590 062 24x Fiche 50-373,84/03/05,8403120128,
- 8403120025 Notifies of 840323 regional workshop in Rosemont, IL w/all Region III licensees to discuss fine protection safe shutdown requirements Workshop will provide add1 guidance re iOCFRSD, App R requirements Agenda enci SPESSARD, R. L. Division of Emergency Preparedness & Operational Support. 84/03/06 REED, C. Commonwealth Edison Co. 3pp 22589:264 24X Fiche 50-373,84/03/06,8403120025
- B403140350 Notification of B40312 appeal meeting w/util & Region III in Betherda,MD to discuss fire protection positions Agenda wncl BCURNIA,A Licensing Branch 2 84/03/06 BCHWENCER,A Licensing Branch 2 4pp 22635 174 24X Fiche 50-374,84/03/06,8403140350
- B40314Di75 Forwards final Interim Repts 1,2 & 3 re fire detection syspen 831123 request & IE Insp Repts 50-373/83-44 & 50-374/83-48 Detector installations meet intent of NFPA & require no compensatory measures.

 BCHROEDER: C W. Commonwealth Edison Co 84/03/09 DENTON, H R Office of Nuclear Reactor Regulation, Director. 4pp 22625 191 24X Fiche 50-373,84/03/09,8403140175
- --8403140180 Analysis of fire detector locations at Lasalle County Station final Interim Rept 1 JOHNBON W.A., SCHULTZ, Q R , BALDABBARRA, C Behirmer Engineering Corp 84/02/21 75pp 22623 195 24X Fiche 50-373,84/03/09, 8403140175.
- --8403140183 Analysis of fire detector locations at Lasalle County Station, final Interim Rept 2 BREZINSKI,M S , JOHNSON,W A , BCHULTZ,O.R Schirmer Engineering Corp, 84/03/06 65pp 22625 298 24X Fiche 50-373,84/03/09, 8403140175
- --8403140184 Analysis of fire detector locations at Laxalle County Station final Interim Rept 3. JOHNBON W. A., SCHULTZ, O R., BALDASBARRA, C. Schirmer Engineering Corp. 84/03/08 45pp 22626 012. 24X Fiche 50-373, 84/03/09, 8403140175
- B403200236 Forwards info & Rev 1 to Procedure LTB-1000-36, "Fire Damper Visual Inbp." per NRC request & IE Insp Repts 50-373/83-44 & 50-374/83-48 BCHROEDER.C.M. Commonwealth Edison Co 84/03/13 DENTON,H R Dffice of Nuclear Reactor Regulation, Director. 5pp 22697 022 24X Fiche' 50-373,84/03/13,8403200256.
- --8403200263 Rev 1 to Procedure LTS-1000-36, "Fire Damper Visual Insp " * Commonwealth Edison Co 84/03/05 48pp. 22697,027 24X Fiche: 50-373,84/03/13,8403200256.
- 8403300244 Forwards NRC position recertain items being appealed by util in fire protection area per 840127 itr 8CHHENCER.A. Licensing Branch 2. 84/03/14 FARRAR.D L. Commonwealth Edison Co. 7pp. 22840 352. 24X Fiche 50-373,84/03/14.8403300244
- 8403220123 Forwards Rev O to Procedure LTB-1000-35, "Fire Damper Dperability Test."
 BCHROEDER, C. H. Commonwealth Edison Co. 84/03/15. DENTON: H R Office of Nuclear Reactor Regulation: Director 2pp 22716,085 24% Fiche. 50-373,84/03/15.8403220123

- 8403230075 Ack receipt of 831213 & 22 Itrs describing interim fire prevention/protection compensatory measures, per IE Insp. Repts 50-373/83-44 & 30-374/83-48 SPESSARD.R L Division of Emergency Preparedness & Operational Support 84/03/19 REED.C Commonwealth Edison Co 1p 22726 273 24X Fiche 50-373,84/03/19,8403230075
- --B403230081 Revises 831123 & 1213 commitment re fire watch training situations addressed in NPPA 516.per JE Insp Repts 50-373/83-44 & 50-374/83-48 BCHROEDER.C W Commonwealth Edison Co 83/12/22 KEPPLER.J G Region 3. Office of Director 2pp 22726 294 24X Fichs 50-373.84/03/19.8403230075
- --B4032300B7 Responds to NRC B31212 ltr re violations noted in IE Insp Repts 50-373/B3-44 & 50-374/B3-4B Corrective actions continuous fire watch posted on refuel floor & cable spreading rooms & roving fire watch established BCHROEDER, C W Commonwealth Edison Co B3/12/13 KEPPLER, J G Region 3. Office of Director 3pp 22726 296 24X Fiche 50-373,64/03/19,8403230075
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8403210085 Forwards Amend 64 to FSAR BCHROEDER,C W Commonwealth Edison Co 84/03/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22701 001 24X Fichs 30-373,84/03/15,8403210085
- --8403210091 Amend 64 to F8AR Twenty-five oversized drawings encl Aperture cards available in PDR * Commonwealth Edison Co 84/03/31 481pp 22701 003 24X Fiche: 50-37g, 84/03/15, 8403210085
- P Operating license stage documents & correspondence
- 8403050119 Forwards supplemental response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATWB Events"

 BARNES, P. L. Commonwealth Edison Co. 84/02/29 DENTON, H. R. Offic of Nuclear Reactor Regulation, Director 26pp 22488, 084 24X Fiche 50-000, 84/02/29, 8403030119
- 8403060250 Confirms 840229 plans for 840302 meeting in Glan Eilyn, IL to discuss questions raised by outside concerns re facility const NORELIUS, C E Division of Project & Resident Programs 84/03/01 REED, C Commonwealth Edison Co ip 22516 160 24X Fiche 50-374,84/03/01,8403060250
- B403130400 Forwards B40210 responses to Generic Ltr B3-35 clarifying TM1 Item II K 3 31 Util concurs w/NRC position Item should be clased RYBAK,B Commonwealth Edison Co. B4/03/02 EISENFUT,D C Division of Licensing 2pp 22613 143 24X Fiche 50-000,84/03/02, 8403130400
- B403280287 Requests certification that Tech Specs accurately reflect plant; F8AR, SER analyses & other documentation within 10 days Proposed changes should be identified EIBENHUT, D G Division of Licensing 84/03/08 REED, C Commonwealth Edison Co 2pp 22808 056 24X Fiche 50-374,84/03/08,8603280287
- 8403300224 Notification of E40314 meeting w/util in LaBalla County, IL to conduct NRC mgt review of licenses readiness for full power operation Agenda encl BOURNIA.A. Licensing Branch 2 84/03/08 BCHWENCER, A Licensing Branch 2 4pp 22845 031 24X Fiche 50-374, 84/03/08, 8403300226
- 8403200013 Discusses 840308 telcon w/A Bournia Te RHR & RCIC high/low pressure interface boundary Lists reasons that full open on valve 2E12-F051A would not be detrimental to low pressure piping SCHRREDER, C W Commonwealth Edison CO 84/03/13, DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22683 355 24X Fiche 50-373,84/03/13,8403200013
- 8403260122 Discusses differences in Tech Boscs per revs to STB, generic ltrs.NRR requirements & grammatical corrections Differences between two Tech Specs do not affect adequacy of current Unit 1 Tech Specs.

 8CHROEDER, C W Commonwealth Edison Co 84/03/21 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 22758.132. 24X Fiche: 50-373,84/03/21,8403260122

Q Inspection reports. IE Bulletins & correspondence

- 8403090114 Forwards IE Insp Repts 50-373/84-04 & 50-374/84-03 on 840131-0203 No noncompliance identified LIYTLE.N S Region 3. Office of Director 84/02/23 REED.C Commonwealth Edison Co 2pp 22559 273 24X Fiche 50-373,84/02/23,8403080114
- --8403080125 IE Insp Repts 50-373/84-04 & 50-374/84-03 on 840131-0203 No noncompliance identified Hajor areas inspected licensee action on previous insp findings & 10CFRSO 55(e) repts CHRISTNDT.E. WILLIAMS.C.C. Region 3, Office of Director 84/02/23 3pp 22599 275 24X Fiche 50-373,84/02/23.8403080114
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan" Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER.J G Region 3. Office of Director 3pp 22470 139 24X Fiche 50-000.84/02/24.8403050043
- --8403050046 Rev O to "Corporate Regulatory Performance Improvement Plan "
 - rian " * Commonwealth Edison Co 84/02/29 22pp 22490 142 24X Fichs 50-000,84/02/24,8403050043
- 8403050168 Ack receipt of 840120 & 0209 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-41 & 50-374/83-42 STREETER.J F Region 3, Office of Director 84/02/27 REED.C Communealth Edison Co 1p 22489 067 24X Fiche 50-373,84/02/27,8403050168
- --8403050171 Responds to NRC 831207 itr re violations noted in LE Insp Repts 50-373/83-41 & 50-374/83-42 on 830908,28-29,1020 & 1110 Future changes to inboard feedwater check valves will be conducted per QP 3-51 FARRAR,D L Commonwealth Edison Co 84/01/20 KEPPLER,J Q Region 3, 0Ffice of Director 3pp 22489 068 24X Fiche 50-373,84/02/27,8403050168
- --8403050174 Suppls B40120 response to NRC 831207 ltr re violations noted in iE Insp Repts 50-373/83-41 & 50-374/84-42 Corrective actions mod approval ltr checklist & safety-related/ASME code change procedure will be revised FARRAR. B L. Commonwealth Edison Co. 84/02/09 KEPPLER. J Q Region 3, Dffice of Director 4pp. 22489 072 24X Fiche 50-373,84/02/27.8403030168
- 8401190072 IE Info Notice 84~13, "Potential Deficiency in Motor Derated Valve Control Circuits & Anunciation " Svc list enci. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403190290 Forwards IE Insp Repts 50-373/83-54 & 50-374/83-57 on 831219-840210 & notice of violation STREETER.J F Region 3. Office of Director 84/02/29 REED.C Commonwealth Edison Co. 2pp 22675 064 24X Fiche 50-373,84/02/29.8403190290
- --8403190293 Notice of violation from insp on 831219-840210 STREETER.JF Region 3, Office of Director 84/02/29 291 22675 066 24% Fichs 50-373,84/02/29,8403190290
- --B403170277 IE Insp. Repts 50-373/83-54 & 50-374/83-57 on 831219-840210 Noncompliance identified temp gauge oblitied in calculating LPCS pump total dynamic head did not have unique number LANKSDURY, R D . WRIGHT, G . MAURA, F A Region 3. Office of Director 84/02/27 iOpp. 22675 O68 24X Fiche 50-373,84/02/29,8403190290
- 8402090007 IE Info Notice 84-i4, "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Bvc list encl GRACE.J N Division of OA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc 130pp 22552 327 24X Fiche 50-000.84/03/02,8402090007.
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402070007 IE Info Notice 84-i5, "Reporting of Radiological Releases "
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 117

- 84031900A8 Forwards IE Insp Repts 50-373/84-02 & 50-374/84-01 on 840116-0210 & natice of violation EHAFER; N D Region 3, Office of Director 84/03/02 REED, C Commonwealth Edison Co 2pp 22671 173 24% Fiche 50-373,84/03/02,88031900A8
- --8403190072 Notice of violation from insp on 840116-0210 SHAFER, W D Region 3, Office of Director 84/03/02 2pp 22671 175 24x Fiche 50-373.84/03/02.8403190068
- ~-8403190076 iE Insp Repts 50-373/84-02 & 50-374/84-01 on 840116-0210 Noncompliance noted 673 ft elevation of reactor bidg contaminated to level in excess required for posting as controlied area & six valves found unlocked GULDEMOND.W 0. GUTHRIE.S C., EVANS.C D Region 3, Office of Director 84/02/27 29pp 22671 177 24X Fiche 50-373.84/03/02, 8403190068
- 8402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403130348 Ack receipt of 840215 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-44 & 30-374/83-48 Add1 response to 840215 ltr will be submitted following completion of actions on 840127 appeal SPEBSARD.R L Division of Engineering 84/03/06 REED.C Commonwealth Edison Co ip 22616 223 24X Fiche 50-373,84/03/06,8403130348
- --8403130357 Responds to NRC B31212 itr re violations noted in IE Insp. Repts 50-373/83-44 & 50-374/83-48 Corrective actions procedures written to require periodic surveillance of lights Bome items should not be categorized as violations. REED, C. Commonwealth Edison Co. 84/02/15 KEPPLER, J. G. Region 3, Office of Director. 20pp. 22616 224 24X Fiche 50-373,84/03/06,8403130348
- B402090024 IE Info Natice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 840209002B IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Sys " Svc list encl. JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York: Inc 118pp 22584 186 24X Fiche 50-000:84/03/07.8402090028
- 8403140175 Forwards final Interim Repts 1,2 & 3 re fire detection system 831823 request & 1E Insp Repts 50-373/83-44 & 50-374/83-48 Detector installations meet intent of NFPA & require no compensatory measures SCHROEDER,C W Commonweelth Edison Co 84/03/09. DENTON.H R. Office of Nuclear Reactor Regulation. Director 4pp 22625-191 24X Fichs 50-373,84/03/09:8403140175
- B402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYDUNG: R C Director's Office: Office of Inspection and Enforcement B4/03/12 Consolidate Edison Co of New York, Inc 134pp 22823 094 24% Fiche 30-000,84/03/12,8402090031.
- 8403190084 Ack receipt of 840229 itr informing NRC of steps teken to correct violations noted in IE Insp Repts 50-373/83-53 & 50-374/83-58 SHAFER.W D Region 3, Office of Director. 84/03/13 REED,C Commonwealth Edison Co ip 22669 319 24X Fiche: 50-373,84/03/13,8403190084
- --8403170070 Responds to NRC 840130 itr re violations noted in IE Insp. Repts 50-373/83-53 & 50-374/83-58 Corrective actions control room tag board updated to reflect current status, burned out bulbs replaced & refresher training program developed. FARAR.D L. Commonwealth Edison Co. 84/02/27 KEPPLER.J 9. Region 3. Office of Director Spp. 22669 320 24X Fiche 50-373,84/03/13,8403190084
- 8403200256 Forwards info & Rev 1 to Procedure LT8-1000-36. "Fire Damper Visual Insp." per NRC request & IE Insp Repts 50-373/83-44 & 50-374/83-48
 SCHROEDER,C. W. Commonwealth Edison Co. 84/03/13 DENTON; H.R. Office of Nuclear Reactor Regulation, Director 5pp 22697-022 24X Fiche; 50-373,84/03/13,8403200256

- 8403260225 Documents 840314 distribution of GJ Diederich 840313 memo to RD Walker & W Guldemond in response to 831128 confirmatory action itr re integrity of discs & valves 8CHROEDER.C W Commonwealth Edison Co 84/03/16 KEPPLER.J O Region 3, Office of Director 4pp 22757 316 24x Fiche 50-373.84/03/16,8403260225
- 8403230075 Ack receipt of 831213 & 22 ltrs describing interim fire prevention/protection compensatory measures, per IE Insp. Repts 50-373/83-44 & 50-374/83-48 SPESSARD, R L Division of Emergency Preparedness & Operational Support 84/03/19 REED, C Commonwealth Edison Co ip 22726 293 24X Fiche 50-373,84/03/19,8403230075
- --8403230081 Revises 831i23 & 1213 commitment re fire watch training situations addressed in NFPA 516.per IE Insp Repts 50-373/83-44 & 50-374/83-4B BCHROEDER, C W Commonwealth Edison Co 83/i2/22 KEPPLER, J G Region 3. Office of Director 2pp 22726 274 24X Fiche: 50-373,84/03/19,8403230075
- --B403230087 Responds to NRC B31212 ltr re violations noted in IE Insp Repts 50-373/B3-44 & 50-374/B3-48 Corrective actions continuous fire watch posted on refuel filoor & cable spreading rooms & roving fire watch established BCHROEDER: C W Commonwealth Edison Co B3/12/13 KEPPLER, J O Region 3, Office of Director 3pp R2726 296 24X Fiche 50-973,84/03/19.8403230075
- 8403230088 Ack receipt of regulatory performance improvement plan
 Periodic meetings requested to discuss progress on program
 & pravvide feedback
 KEPPLER.J. O. Region 3, Office of Director 84/03/20 THDMAS, B
 Commonwealth Edison Co ip 22730 161 24X Fiche 50-000, 84/03/20,
 8403230088
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAS.B. Commonwealth Edison Co. 84/02/24 KEPPLER.J G. Region 3. Office of Director 3pp. 22730 162 24X Fiche 50-000, 84/03/20,8403230088
- --8403230126 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden, Quad Cittes, Zion & LaSalle Operating Nuclear Stattons & Byron & Braidwood Project Operating Organizations " * Commonwealth Edison Co 84/02/29 22pp 22730 i65 24X Fiche, 50-000, 84/03/20, 8403230088.
- B403260196 Forwards responses to IE Bulletin B3-07, "Apparently Frauduient Products Sold by Ray Miller.Inc " Guad Cities supplied w/piping matts from Ray Miller. Inc during const Evaluation encl Concerns of IE Bulletin B3-06 satisfied BARNES.P L. Commonwealth Edison Co B4/03/20 KEPPLER.J 0 Region 3, Office of Director 19pp 22754 185 24X Fiche 50-000.84/03/20.8403260196
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities" 8vc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. i23pp. 22823:229 24X Fiche, 50-000, 84/03/21, 8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Bafety-Related Bys " Svc list encl, JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. i35pp 22933:001, 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403060150 Rev O to "Rept of Radioactive Effluents, Jul-Dec 1983 " W/ B40116 ltr #. DIEDERICH.O.J Commonwealth Edison Co 83/12/31 KEPPLER, J O Region 3, Office of Director 9pp. 22513 337. 24X Fichs. 50-373,83/12/31.8403060150
- 8403080197 "Rept of Occupational Personnel Radiation Doses, 1983 " W/840227 Itr 860371.J.B. Commonwealth Edison Co 83/12/31 13pp 22559 099. 24X Fiche: 50-000, 83/12/31, 8403080197
- 8403220120 Annual whole body external exposures for 1983 W/840316 ltr RYBAK.B. Commonwealth Edison Co. 83/12/31, 7pp 22716 007 24X Fiche: 50-000,83/12/31,8403220120

- S Reportable occurrences, LERs & related correspondence
- 8403120047 LER 84-003-00 on 840202, intended trip on sys auxiliary transformer feed breaker failed to occur Caused by breaker plunger being too short Addl washers installed on plunger assembly W/840302 itr
 HIETALA: J J DIEDERICH, G J Commonwealth Edison Co 84/03/01
 3pp 22589 284 24X Fiche 50-374.84/03/01.8403120047
- 8403i60266 LER 84-004-00 on 840212. Div 2 isolation signal received, causing secondary containment isolation & standby gas treatment sys to start Caused by blown electrical fuse Fuse replaced W/840306 ltr KDEN10.R. DIEDERICH.O J Commonwealth Edison Co 84/03/06 3pp 2266i 001 24X Fiche 50-374.84/03/06.8403160266
- 8403190013 PNO-III-84-025 on 840310 unit achieved initial criticality Agreement observed between actual conditions & predicted conditions HALKER, R., SHAFER, W. Region 3, Office of Director 84/03/12 1p 22665-333 24% Fiche 30-374,84/03/12.8403190013
- 8403200212 LER 84-005-00 on B40215, during performance of HPC8 inservice testing, pump breaker failed to reclase second time Caused by failure of breaker position switch (33).5818 to close in second cycle Breaker reracked H/840315 ltr
 KOENTO: R. DIEDERICH: 0 J Commonwealth Edison Co 84/03/15 3pp 22679 344 24X Fiche 50-374.84/03/15.8403200212
- 8403280023 LER 84-007-00 on 840218; reactor water cleanup isolated on Pump Room A high differential temp Caused by difference in room temp due to misconfiguration of area ventilation sys.

 Review for corrective actions in progress W/840322 ltr REIS.J 0 , DIEDERICH, 0 J Commonwealth Edison Co 84/03/21 9pp 22777 051 24x Fiche 50-374,84/03/21,8403280023
- B4032B0073 LER B4-006-00 on B40223, reactor water cleanup sys isolated on Pump Room C ventilation differential temp high Caused by normal operating temp gradient across pump rooms due to cold reactor bidg air blasting in
- T Hearing transcripts on non-antitrust matters
- 8403270320 Transcript of Commission 840323 discussion/possible vote in Washington DC re full power OL for LaSalle Unit 2 Pp 1-76 Supporting documentation encl # Commissioners 84/03/23 84pp 22787 153 24X Fiche, 80-374, 84/03/23, 8403270320
- DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 84030i0262 Further response to FOIA request for documents re Sendia Contract A-1123 & bibliography used by R Bernero Forwards App A documents FELTON, J M Division of Rules and Records FIN A-1123 83/12/20 RUTLEDGE.P Carolina Environmental Study Group 2pp 22444 069 24X Fiche 50-000/83/12/20,84030i0262
- --8301280380 Responds to 821108 itr & newspaper article, clarifying distorted & incomplete picture of nuclear accident probabilities & consequences & modeling uncertainties presented in article
 DIRCKS,W J Office of the Executive Director for Operations 82/12/27 B0008;L House of Rep 4pp 22444.078 24X Fiche 50-000,83/12/20.8403010262
- 8403050269 Notification of cancellation of 840228 meeting w/util & Ebasco in Bethesda, MD to discuss emergency feedwater control sys WILEON, J H Licensing Branch 3 84/02/16 KN19HTON, Ø W Licensing Branch 3. 3pp 22501·106 24X Fiche 50~382, 84/02/16, 8403050269.
- 8403020205 Forwards info re corrective actions identified during control room design review. Lighting survey results, color code convention & results of control room liveability review enci Lighting mods complete CODK: K W Louisiana Power & Light Co 84/02/28 KNICHTON, 9 H Licensing Branch 3 12pp. 22440, 242 24X Fiche 50-382,84/02/28,8403020205
- 8403020333 Forwards "Evaluation of Natural Circulation Cooldown Test Parformed at Ban Onofre Nuclear Generating Station." Boron mixing tests in lieu of natural circulation test accepted by updated BER & BBER 5 COOK, K W Louisiana Power & Light Co 84/02/29 KNIGHTON, G. W Licensing Branch 3 1p 22439:035 24X Fiche 50-000, 84/02/29, 8403020333

- ~-8403020335 "Evaluation of Natural Circulation Cooldown Test Performed at San Dnofre Nuclear Generating Station "
 * Combustion Engineering, Inc CEN-259 84/01/31 136pp 22439 036 24% Fiche 50-000, 84/02/29, 8403020333
- 8403090032 Final response to FOIA request for five categories of documents re facility Forwards addl documents listed on App A FELTON, J M Division of Rules and Records B4/03/02 LYON, V F Lyon & Kurz 2pp 22592 333, 24X Fiche 50-382,84/03/02,8403090032
- ~-8403090038 Lists areas of contern at facility requiring investigation Ebaseo & util failed to address & resolve deficiencies identified by many personnel including QA documentation reviewers * Louisiana Power & Light Co 84/03/02 NRC No Detailed Affiliation Given 2pp 22392 336 24X Fiche 30-382,84/03/02,8403090032
- 8403130446 Confirms that all SQRT files closed Info adequate to close out seismic qualification issue CQUK.K W Louisiane Power & Light Co 84/03/02 KNIGHTON.G W Licensing Branch 3 ip 22613 i81 24% Fiche 30-382,84/03/02,8403330446
- B403120169 Advises that listed procedures & Tech Specs reviewed, per Generic Ltr B3-29 re post-maint testing of reactor trip sys components Check of vendor & engineering recommendations concluded test guidance incorporated into procedures GGGM.X X Louisiana Power & Light Co B4/03/05 KNIOHTON, Q H Licensing Branch 3 6pp 22590 154 24X Fiche: 50-382, 84/03/05, B403120169
- 840312016B Discusses activities & commitments to be completed prior to fuel load Listed open items will be completed prior to 840430 COGK.K W Louisiana Power & Light Co. 84/03/08 KNICHTON.O W Licensing Branch 3 6pp 22590 14B 24X Fiche 50-382,84/03/08,840312016B
- 8403130170 Responds to Generic Ltr 83-28, item 4 5 3 re reactor trip sys reliability (sys functional testing) Util participating in C-E Owners Group evaluation Results due by 841203 COGK, K H Louisiana Power & Light Co 84703/08 KNIGHTON, G W Licensing Branch 3 1p 22608 iil 24X Fiche 50-382, 84703/08.
- 8403i50046 Responds to Item 4 2 of Generic Ltr 83-28 re reactor trip sys reliability (preventative maint & surveillance program for reactor trip breakers) Breaker opening time will be trended monthly to forecast breaker degradation COOKLX W Louisiana Power & Light Co 84/03/08 WNIGHTON.9 W Licensing Branch 3 2pg 22643 136 24X Fiche 50-382.84/03/08.8403150046
- B403280062 Notification of B40315 meeting w/util & Ebasco in Bethesda. MD to discuss Tech Specs prior to licensing MILGON, J H Licensing Branch 3 84/03/08 KNIGHTON, G W Licensing Branch 3 3pp 22812 335 24X Fiche 50-382,84/03/08,8403280062
- 8403160020 Informs that facility will employ 17 I psid setpoint for containment isolation as reflected in current draft Tech Specs, per Item II E 4 2 of NURE0-0737 Item should be closed in next SSER COOK, K H Louisiana Power & Light Co 84/03/12 KNIOHTON, G W Licensing Branch 3 2pp 22653 351. 24X Fiche 50-382,84/03/12.
- B40320016B Advises that commitment for vendor review of emergency operating procedures fulfilled, based on meeting TMI Action Item I C 7 requirements COOK, K W Louisiana Power & Light Co 84/03/12 KNIGHTON, Q W Licensing Branch 3 ip 22699.351 24X Fiche 50-382, 84/03/12, 8403200168
- 8403200209 Provides justification for interim operation pending complete environ qualification of ex-core neutron flux detectors még by Hestinghouse COOK.K W Louisians Power & Light Co Eicansing Branch 3 2pp 22696 354 24x Fiche 50-382, 84/03/13, 8403/13,
- B402090041 Board Notification B4-D50 provides Commission policy statement & proposed rulemaking on environ qualifications EISCMHUT.D © Division of Licensing B4/03/14 Atomic Gafety and Licensing Board Panel 10pp 24X Fichs 50-000,84/03/14,8402090041

- 8403210030 Forwards justification for exemption from Type C leak testing, list of isolation valves within essential sys & penetration isometric drawings re finalization of Tech Specs in preparation for DL COOK K W Louisiana Power & Light Co 84/03/16 KNICHTON: O W., Licensing Branch 3 17pp 22707 016 24X Fiche 50-382:84/03/16.8403210030
- B403270154 Replaces itr previously issued as H3P84-0431 re activities a commitments to be completed prior to fuel load due to missing page from attachment All open items to be completed by 840430 Anticipates receipt of OL on same date CUDK, K H Louisiana Power & Light Co 84/03/20 KNIOHTON. Q. H Licensing Branch 3 opp 22770 019 24X Fiche 50-382,84/03/20,8403270154
- 8403260154 Forwards completed operating shift experience forms BARKHURST,R P. Louisiana Power & Light Co. 84/03/22 DENTON,H Defice of Nuclear Reactor Regulation, Director 8pp 22756 226 24X Fiche 50-382.84/03/22,8403260154
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403050065 Submits info in response to SER Open Item 7 i,2(2), par IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Info should enable closeout of SER item COSK K W Louisiana Power & Light Co E4/02/27 KNIGHTON.O.W. Licensing Branch 3 2pp 22470 183 8403050065
- 84030403040 Supplements add1 info provided in 830805 ltr justifying use of analysis in resolving aging & operability issue to qualify Rosemount 1153A transmitter use at facility.per SBER 5 COOK, K W Louisiana Power & Light Co 84/03/01 KNIOHTON, O W Licensing Branch 3 2pp 22515 355 24X Fiche 50-382,84/03/01.
- 8403060293 Forwards post-accident sampling sys status rept per BBER 2. containing updated info on actions & plans COOK. K. W. Louisiana Power & Light Co. 84/03/02 KNIOHTON. O. W. Licensing Branch 3. 3pp. 22518.126. 24X Fichs. 50-382, 84/03/02. 8403040293.
- 8403060337 Advises that SEER 5 provides incorrect listings of CPC penalty factors resulting from rod bow penalty Requests that corrected table of penalty factors be included in next SEER CDDK.K H Louisiana Power & Light Co 84/03/02 KNIOHTON.O H Licensing Branch 3 ip 22513 336 24X Fiche 50~382,84/03/02,8403060337
- 8403120186 Requests that NUREO-0737, Item II E 4 2 re containment pressure setpoint be closed in next SSER Facility will employ i/ I paia setpoint, per Tech Specs COOK. K. H. Louisiane Power & Light Co 84/03/05 KNIGHTON, Q H. Licensing Branch 3 ip 22585 001 24X Fiche. 50-382, 84/03/05, 8403120186
- B403160020 Informs that facility will employ 17.1 psid satpoint for containment isolation as reflected in current draft Tech Specs, per Item II E 4 2 of NUREO-0737 Item should be closed in next SSER GOKK X H Louisiana Power & Light Co B4/03/12 KNIOHTON, 9 H Licensing Branch 3 2pp 22633.331 24X Fiche 50-382,84/03/12.
- F Security, medical, emergency & fire protection plans
- 8403130434 "Louisiana Power & Light Co.Waterford 3 Emergancy Preparedness Exercise May 25, 1983 " * Louisiana Power & Light Co 83/05/25 378pp. 22607, 125. 24x Fiche 50-382, 83/05/25, 8403130434.
- 8403120014 Forwards changes & reve to emergency plan implementing procedures, including EP-2-050 re offsite dose assessment & EP-2-060 re radiological field monitoring W/o encl DRUMHON, F. J. Louisiana Power & Light Co. 83/08/08 COLLING, J. T. Region 4, Dffice of Director 2pp. 22388, 034 24X Fiche. 50-382, 83/08/08, 8403120014.
- 8403130105 Responds to emergency preparedness appraisal items noted in IE Emergency Preparedness Appraisal Rept 50-382/83-08. Burvey of site public address sys performed In-plent paging sys reviewed for possible mods COOK. W W Louisiana Power & Light Co 83/12/28. JCHNBON. E Region 4, Office of Director ip 22601-300 24X Fiche 50-382,83/12/28.

- 8403i3013i Forwards IE Insp Rept 50-382/83-34 on 83i001-ii30 No violations or deviations noted JDHNSON,E H Region 4. Office of Director 84/01/18 LEDDICK,R S Louisiana Fower & Light Co 2pp 2260i 054 24X Fiche 50-382,84/01/18.8403i30i3i
- --8403130140 IE Insp Rept 50-382/83-34 on 831001-i130 No violations or deviations noted Major areas inspected preoperational test procedure review & test witnessing, HPSI pump performance restest & emergency operating procedure review CONSTABLE.0 L . FLIPPO, T A . CROSSMAN, W A Region 4, Office of Director 84/01/12 opp 22601 056 24X Fiche 50-382,84/01/18,8403130131
- 840305024B Forwards public version of Rev 6 to emergency plan & Rev 3 to emergency plan implementing procedures, including Procedures EP-i-001 re recognition & classification of emergency conditions & EP-i-020 re alert W/840301 memo LEDDICK, R 8 Louisiana Power & Light Co 84/01/30 Office of Nuclear Reactor Regulation, Director 7pp 22519 283 24X Fiche 50-382,84/01/30,8403050248
- --8403050251 Public version of Rev & to emergency plan * Louisiana Power & Light Co 84/01/30 535pp 22519 290. 24X Fiche 50-382,84/01/30,8403050248.
- --8403050253 Public version of revised emergency plan implementing procedures, including Procedure EP-1-001 re recognition & classification of emergency conditions, EP-1-020 re alert & EP-1-010 re unusual event ALLENMAN S A . BARKHURST R P Louisiana Power & Light Co 84/01/26 836pp 22521 105 24X Fiche 50-382,84/01/30,8403050248.
- 8403130331 Suppls 830727 & 1018 responses to IE Emergency Preparadness Appraisal Rept 50-382/83-08, providing current status of action on emergency preparadness appraisal open items CODK.K. W Louisiana Power & Light Co 84/02/01 JOHNSON.E Region 4, Office of Director 5pp 22614 114 24X Fiche 50-382,84/02/01,8403130331
- 8403050137 Notifies that NRC will provide inspectors to observe ensite aspects of periodic exercises for emergency preparedness Scenario for submission of info listed COLLINB, J T Region 4, Office of Director 84/02/09 LEDDICA, R S Louislana Power & Light Co 2pp 22489 100 24X Fiche 50-382,84/02/09,8403050137
- 840305056i Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810709 Generic Ltr 81-27 W/o request, entire glan will be placed in PDR KNIGHTON, 0 W Licensing Branch 3 84/02/20 LEDDICK, R 8 Louistana Power & Light Co 3pp 22552, 269 24X Fichs 50-382,84/02/20,840306056i
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EIBENHUT.D 9 Division of Licensing 84/02/23 PALLADING Commissioners 1p 22576 203 24X Fiche 50-000,84/02/23,8402090006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NRR Dfc Ltr 19, dtd 821001 Further evaluation of test data required VDLLMER, R. H. Division of Engineering. 84/02/06 EIBENHUT, D 0 Division of Licensing 10pp 22376'204. 24X Fiche 50-000,84/02/23,8402090006
- 8403260078 Forwards IE Insp Rept 50-382/84-05 on 840123-27 No yiolations or deviations identified Status of actions taken re-previously identified insp findings examined JOHNSON, E. H. Region 4, Office of Director 84/02/27 LEDDICK, R 8 Louisiana Power & Light Co. 2pp 22758 274 24X Fiche. 50-382, 84/02/27, 8403260078,
- --B403260087 IE Insp Rept 50-382/B4-05 on 840123-27 No violations or deviations identified Major areas inspected radiation protection program & implementing actions for NUREQ-0737 action items
 CHANEY, H. D., MURRAY, B., CROSSMAN, W. A. Region 4, Office of Director. B4/02/27 13pp 22758 276 24X Fiche 50-382,84/02/27,8403260078.
- 8403140191 Forwards technical guidelines required by NUREQ-0737, Buppl 1, including guidance on station blackout conditions (Unresolved Bafety Issue A-44), to be considered as response to Generic Ltr 81-04 COOK, X, W Louisians Power & Light Co 84/03/05 KNIOHTON, G W Licensing Branch 3 837pp. 22621 001 24X Fiche 50-382,84/03/05, 8403140191

- 8403120164 Forwards marked-up corrections to emergency plan implementing procedures per undated Ltr M3F84-0029 & marked-up reve to emergency plan LEDDICK.R S Louisiana Power & Light Co 84/03/08 Office of Nuclear Reactor Regulation, Director 4pp 22587 IB6 24X Fiche 50-382,84/03/08,8403120164
- --8403120165 Marked-up Rev 6 to emergency plan implementing procedure.ger undated Ltr W3F84-0027 * Louisiana Power & Light Co 84/03/08 7pp 22587 190 24X Fiche 50-382,84/03/08,8403120164
- --B403120167 Marked-up Rev 6 to emergency plansper undated Ltr H3F84-0029 * Louisiana Fower & Light Co 84/03/08 Spp 22589 199 24X Fiche 50-382, 84/03/08, 8403120164
- B403150075 Forwards 13 ltrs of agreement from chemical industries within 5 miles of facility re toxic chemicals per emergency plan COOK, K W Louisiana Power & Light Co 84/03/08 KNIGHTON, 0 W Licensing Branch 3 15pp 22642 333 24X Fiche 50-382.84/03/08.8403150075
- 8403200161 Lists items addressed by training program.per L Bender request including coordinated training of plant fire brigade & local fire dept.operational precautions & training for mitigating core damage COOK, K W Louisiana Power & Light Co 84/03/15 KNIOHTON, G W Licensing Branch 3 ip 22699 349 24x Fiche 50-382,84/03/15,8403200161
- 8403300048 Forwards "Alert/Notification Sys "
 COOK, K W Louisiana Power & Light Co 84/03/28 KNIGHTON, G W
 Licensing Branch 3 3pp 22825 049 24X Fiche 50-382,84/03/28,
 8403300048
- --8403300049 "Alert/Notification Sys " W/four oversized drawings Drawings available in PDR
 * Lauisiana Power & Light Co 84/03/31 300pp 22825 052 24X
 Fiche 50-382,84/03/28,8403300048

G Adjudicatory correspondence

- B403010187 Advises that NRC request for extension of time to B40413 to respond to Joint Intervenors B31212 motion to reopen record unopposed Target fuel load set for 840430 Certificate of Bvc encl
 CHURCHILLIB W Shaw, Pittman, Potts & Trowbridge CHURCHILLIB W Louisiana Power & Light Co B4/02/28 KOHLLC N, WILBER, H A, JOHNSON, W R Atomic Safety and Licensing Appeal Panel 4pp 22435 278 24X Fiche 50-382,84/02/28,8403010187
- B4030B0130 Requests G Hill B40110-11 statement re QA deficiencies be forwarded to G Groesch & author BURBTEIN,C H Joint Intervenors Waterford B4/02/29 PALLADINO,N Commissioners 1p 22359 278 24X Fiche: 50-382,84/02/29,8403080130
- 8403210180 Order extending time until 840427 for Commission to act to review ALAB-753 Berved on 840321 CHILK.8 J Office of the Becretary of the Commission DSB 017 84/03/20 PALLADING.N J, GILINSKY.V . ROBERTS T M Commissioners ip 22718 227 24X Fiche 50-382,84/03/20,8403210180
- Q Inspection reports, IE Bulletins & correspondence
- 8403130105 Responds to emergency preparedness appraisal items noted in IE Emergency Preparedness Appraisal Rept 50-382/83-08 Burvey of site public address sys performed In-plant paging sys reviewed for possible mods COOK, K W Louisiana Power & Light Co 83/12/28 JOHNSON, E Region 4, Office of Director ip 22401 300 24% Fiche 50-382,83/12/28, 8403130105
- 8403:3013i Forwards IE Insp Rept 50-382/83-34 on 83:00i-ii30.No violations or deviations noted JOHNBON, E H Region 4, Office of Director 84/0i/i8 LEDDICK, R 8 Louisiana Power & Light Co 2pp 2260i 054 24X Fiche, 50-382,84/0i/i8,8403:3013i
- --B403:30:40 IE Insp Rept 50-3B2/B3-34 on B3:00:-1:30 No violations or deviations noted Major areas inspected preoperational test procedure review & test witnessing. HBI pump performance retest & emergency operating procedure review CONSTABLE O. L., FLIPPO.T A., CROSSMAN.W.A. Region 4, Office of Director B4/01/12 App. 22401 054 24X Fiche 50-3B2,84/01/18,8403:30:31

- 8403130331 Supple 830727 & 1018 responses to IE Emergency Preparedness Appraisal Rept 30-382/83-08 providing current status of action on emergency preparedness appraisal open items CODK.K W. Louisiana Power & Light Co. 84/02/01 JCHNSON, E. Region 4. Office of Director 5pp 22614 114 24X Fiche 50-382,84/02/01. 8403130331
- 8403260245 Forwards IE Insp Rept 50-382/84-06 on 84016-20 No violations or deviations identified Concern re lack of comprehensive calibr program for effluent monitors raised JOHNSON, E Region 4, Office of Director 84/02/14 LEDDICK, R & Louisiana Power & Light Co 2pp 22756 050 24x Fiche 50-382,84/02/14,8403260245
- --8403260250 IE Insp Rept 50-382/84-06 on 840116-20 No violations or deviations identified Major areas inspected radwate program & transportation activities, including organization, training & qualifications BAER.R E . HOLLEY.W L . HURRAY.B Region 4. Office of Director 84/02/14 11pp 22756 052 24X Fiche 50-382.84/02/14.8403260245
- 8403050065 Submits info in response to SER Open Item 7 1 2(2); per IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Info should enable classeout of SER item CODK, K W Louisiana Power & Light Co 84/02/27 KNIGHTON, O W Licensing Branch 3 2pp 22490 183 24X Fiche 50-382, 84/02/27, 8403050045
- 8403260078 Forwards IE insp Rept 50-382/84-05 on 840123-27. No violations or deviations identified Status of actions taken re previously identified insp findings examined.

 JOHNSON,E H Region 4. Office of Director 84/02/27 LEDDICK,R S Lovisiana Power & Light Co 2pp 22758 274 24X

 Fiche 50-382,84/02/27,8403260078
- --84032600B7 IE Insp Rept 50-382/84-05 on 840123-27 No violations or deviations identified Hajor areas Inspected radiation protection program & implementing actions for NUREG-0737 action (tems CHANEY, H D, MURRAY, B, CROBSHAN, W A Region 4, Office of Director 84/02/27 i3pp 22758 276 24X Fiche 50-382,84/02/27,8403260078
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN. & L Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22709 239 24X Fiche 50-000.84/02/28.8401190072
- B402090007 IE Info Notice B4-i4, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE.J N Division of GA. Bafeguards & Inspection Programs (Post B30103) B403/02 Consolidated Edison Co of New York. Inc 130pp. 22552,329 24X Fiche 50-000.84/03/02.8402090007
- 840209000B IE Info Notics 84-16, "Failure of Automatic Sprinkler Bys Valves to Operats" Svc list sncl JORDAN, E L. Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 30-000,84/03/02,8402090008
- 402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svr list encl
 JORDAN, E L Division of Emergency Preparednsss & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553:217 24X Fichs 50-000.84/03/02,8402090009
- 8402090011 IE Info Notice 84~17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22593 336 24X Fiche 50~000.84/03/05,8402090011
- 3402070024 IE Info Notice 84-09, Rev 1. "Lessons Learns From Insps of Fire Protection Safe Shutdown Sys " Svc list entl JORDAN, E. L. Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PHR 8ys " Syc list snc! JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York. Inc 118pp 22584 186 24X Fisher-50-000.84/03/07,8402090028

- 8403170271 Ack receipt of 831207 & 840207 supplemental ltrs informing NRC of steps taken to correct violations noted in IE Insp. Rept 50-382/83-17 implementation of corrective actions will be reviewed during future insp. JOHNSON, E. H. Reglon 4. Office of Director 84/03/09 LEDDICK, R. 8. Louisiana Power & Light Co. 1p. 22671 301 24X Fiche 50-382, 84/03/08, 8403190271
- --B403190272 Responds to NRC B30606 ltr reviolations noted in IE Inep Rept 50-3B2/B3-17 Corrective actions Ebasco Nonconformants Rept 3594 initiated due to lack of info available re erection of structural steel for missile protection GERRETS.T F Louisiana Power & Light Co 84/02/09 JOHNBON.E Region 4. Office of Director. 3pp 22671 302 24X Fiche 50-382,84/03/08.8403190271
- 8402090031 IE Bullstin 84-02. "Failures of GE Typs HFA Rslays in Use in Class IE Safaty Sys " Byc list encl DEYOUNO.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Ficha: 50-000.84/03/12.8402090031
- 8403160242 Forwards vendor insp repts Identifying concerns found by Vendor Program Branch during insp of vendor activities Evaluation of findings re quality & acceptability of product or svc by vendors requested JOHNSON.E H Region 4. Office of Director 84/03/13. LEDDICK.R S Louisiana Power & Light Co 3pp 22661 026 24X Ficha 50-382.84/03/13.8403160242
- 8403200247 Forwards vendor insp repts identifying concerns noted by Vendor Program Branch during insps of vandor activities Bignificance of reported findings rs acceptability of product or svc provided by vendor requested W/o sacl JOHNSON.E H Region 4. Office of Director 84/03/16 LEDDICK.R S Louistana Power & Light Co 3pp 22696 350 24X Fiche 50-382:84/03/16.8403200247
- B402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavitles" Byo list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/21 Consolidated Edison Go of New York, Inc 123pp 22823 229, 24X Fichs 50-000,84/03/21,8402070043
- 8402090044 IE Info Notics 84-20. "Bvc Life of Relays in Bafety-Related Bys " Bvc list enci JORDAN,E L Division of Emergency Preparedness & Enginearing Response (Post B30103) B4/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fichs 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403020443 Forwards monthly status rept of offsits emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay dus to offsits emergency planning issues
 DIRCKB.W J Offics of the Executive Director for Operations
 B4/02/21 PALLADINO Commissioners 9pp 22492.083 24X
 F1che 50-000.84/02/21.84030R0443
- 8 Reportable occurrences, LERs & related correspondence
- B403010069 Becond interim significant Const Deficiency Rapt 93 re charging & letdown containment isolation valve defect Initially reported on B31202. Corrective action complete. Further testing required Next rept sxpacted by 840701 GERRETS, T.F. Louisiana Power & Light Co. 84/02/20. COLLINS, J.T. Region 4. Office of Director. 20pp 22435 219 24X Fiche 50-382-84/02/20, 8403010069
- B403210032 Part 21 rspt re failure of auxiliary feedwater pump drive turbines.0impel NPB-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils 0E notified of affected units in BWR plants
 TMEROUX, R Terry Corp 84/02/22 WOODRUFF, R W Director's Office, Office of Inspection and Enforcement 6pp 22706.327, 24 Fiche 50-000.84/02/22.8403210032
- 8403060196 Fourth interim rept re significant Const Deficiency 92 concerning HPBI sys psrformance Rsvisw of supporting documentation scheduled to be complete by 840309 Final rept will be submitted on 840316 GERRETB, TF Louisiana Power & Light Co 84/02/24 COLLINB, J. T. Region 4, Office of Director 2pp 22517 355 24X Fiche. 50-382, 84/02/24, 8403060196.
- B403060238 Finel rept of significant Const Deficiency 42-R1 re defect in GE Type HMA auxiliary relays mfg batussn 1976 & June 1981. Nonconformance Rspt H3-3361 initiated. GERRETB, T F Louisiana Power & Light Co 84/02/24 COLLINS, J T. Region 4, Office of Director 4pp. 22517.141. 24X Fiche' 50-382.84/02/24,8403060258

- 8403060337 Second interim significant const Deficiency Rept 95 re HPSI pumps A/AB failing to start on safety injection actuation signal Final rept will be submitted by 840330 GERRETS.TF Louisians Power & Light Co 84/02/24 COLLINS.JT Ragion 4. Office of Director 2pp 22517 043 24X Fichs 50-382.84/02/24.8403080339
- 840313031i Final Significant Const Deficiency Rept 88 re overstrassed refueling water storage pool liner/nozzle Initially reported on 831213 Restraints added to condensate storage pool to reduce pipe forces transmitted to liner OERRETS, T F Louisiana Power & Light Co 84/02/27 COLLINS, J T Region 4. Office of Director 4pp 22608 059 24x Fiche 50-382.84/02/27.8403130311
- 8403130267 Final deficiency rept, Item 151 re hydraulic transient, sheared support/restraint on line Initially reported on 840213 Further investigation indicated condition not reportable per 10CFR50 55(e)
 GERRETS, T F Louieiana Power & Light Co 84/02/28 COLLING, J T Region 4. Office of Director 2pp 22605 054 24X Fiche 50-382,84/02/28,8403130267
- 8403130303 Final deficiency rapt. Item 147 re potential failure of safety injection valve actuators Initially reported on 840202 Valves not yet fully qualified for operational use Incident not reportable per 10CFR50 55(e) OERRET8, T. F. Louisiana Power & Light Co. 84/02/29 COLLING, J T Region 4. Office of Director 2pp 22614 191 24X Fiche: 50-382,84/02/29,8403130303
- 8403130427 First interim Significant Conet Deficiency Rept 99 re safety injection tank isolation valve mechanically binding causing valve motor to trip on overload Valve actuator inspected, repaired & tested Final rept by 840406
 GERRETS, TF Louisiana Power & Light Co 84/02/29 COLLINS, J T Region 4. Office of Director 3pp 22614 097 24X
 Fiche 50-382.84/02/29.8403130427
- B40G130436 Final Potential Deficiency Rept 149 rm sheared valve eteme in component cooling water sys Caused by excessive force used to close valvee in order to prevent leakage Item not reportable per 10CFR50 55(e)

 OERRETS, T. F. Louisiana Power & Light Co. B4/02/29 COLLING, J T Region 4. Office of Director 2pp 22613 161 24X Fiche 50-382,84/02/29,8403130436
- 8403130339 Second interim Significant Const Deficiency Rept 97 rediesel generator B turbocharger failure Official response from Cooper Energy Sycs re cause to be completed by late Mar 1984 Final rept will be submitted on 840406 GERRETB.TF Louisiane Power & Light Co 84/03/01 COLLINB.J T Repion 4, Office of Director 2pp 22617 120 24X Fiche: 50-382,84/03/01,8403130339
- 8403170253 Final significant const deficiency reptiltem 32 re stress analysis for welded pipe support attachments not performed prior to fabrication Bergen-Patereon analysis identified 85 supports requiring rev & rework.

 OERRETS:T.F. Louisiana Power & Light Co. 84/03/01 COLLINS:J T. Regison 4. Office of Director. 3pp. 22671 275 24X Fiche. 50-382,84/03/01.8403190253
- B40319036B Second interim Bignificant Const Deficiency Rept 94 rechemical vol control eys heat trace temp drift Corrective action k documentation review scheduled for completion by late Mar 1984. Final rept will be submitted by B40406 OERRETS: T. Louisians Power & Light Co 84/03/01 COLLINS: J T Region 4, Office of Director 2pp. 22675:200 24X Fiche: 50-382: 84/03/01. 8403190368
- E403190262 Final Significant Const Deficiency Rept B3 re heat tracing design defects identified during hot functional testing Capacitors added to high temp cutout modules to prevent spurious or false tripping of device GERRETB: T F Louisiana Power & Light Co B4/03/02, COLLINS, J T Region 4, Defice of Director 3pp 22672 059, 24X Fiche: 50-382,84/03/02,8403190262
- 8403170230 Final Potentially Reportable Deficiency Rept 150 re problem W/alarm setpoints for low temp protection sys Initially reported on 840210, Condition not reportable per 100FR50 35(s) 9800 Per 100FR50 35(s) Per 100FR50 15(s) Per 100FR50 15(
- B403200022 Interim Significant Const Deficiency Rept. Item 102 refailure to install dowels & shear blocks on emergency faedwater pumps. Initially reported on 840216. Final rept expacted by 840406 GERRETS, T.F. Louisiana Power & Light Co. B4/03/09 COLLINS, J. T. Region 4, Office of Director. 3pp. 22698 358. 24X Fiche: 50-382, 64/03/09, 8403200022.

- 8403200267 Second interim rept re Significant Const Deficiency 96, failure of chemical & vol control sys pump Train A to start on safety injection actuation signal Final rept will be submitted by 840330 OERRETS.T F Louisiana Power & Light Co 84/03/07 COLLINS.J T Region 4. Office of Director 2pp 22676 i21 24X Ficher 50-382.84/03/09.8403200267
- 8403200276 First interim rept re Significant Const Deficiency 101, traceability of stainless steel instrumentation tubing Insp & tests underway to determine if tubing installed to code requirements Final rept expected by 8404046 GERRETS.T F Louisiana Power & Light Co 84/03/09 COLLINS, J T Region 4. Office of Director 3pp 22697 097 24X Fiche 50-382.84/03/09.8403200276
- 8403270102 Final Deficiency Rept 148 re ASCO solenoide & NANCO limit ewitchee Initially reported on 840206 Bolenoids will be replaced to provide traceability & documentation OERRETS.T F Louisiana Power & Light Co 84/03/09 COLLINS.J T Region 4. Office of Director 2pp 22766 349 24X Fiche 50-382,84/03/09.8403270102
- 8403270206 Seventh interim Significant Const Deficiency Rept 78 re American Bridge Corp structural steel defects Corrective action remains on two nonconformance repte Completion scheduled for Mar 1984 Next rept by 840406 GERRETB.T F Louisiana Power & Light Co 84/03/09 COLLINS.J T Region 4. Office of Director 2pp 22770 282 24X Fiche 50-382.84/03/09.8403270206
- 8403270059 Interim eignificant const deficiency rept, Item 100 reterminations to Knox fuse blocks.0E 4.160 kV switchgear All Knox fuse block terminations reinspected Next rept will be submitted by 840406 Also reported per Part 21 GERRETS.TF Louisiana Power & Light Co 84/03/12 COLLINS, J T Region 4. Office of Director 3pp 22766 159 24X Fiche 50-382,84/03/12.8403270059
- 8403270202 Final Significant Const Deficiency Rept 75 re station battery equalizing charge voltage exceeding coil ratings Initially reported on 840120 Class IE dc equipment evaluated during equalizing charge voltage of 139 B volt & GERRETB.T F Louisiana Power & Light Co 84/03/14 COLLINS.J T Region 4. Office of Director 3pp 22770 288 24X Fiche 50-382.84/03/14.8403270202
- 8403270044 Fourth interim Significant Const Deficiency Rept 80 re unsatisfactory stroking of emergency feedwater turbing steam shutoff valvee Further testing during post-core hot functional testing required Next rept by 840713 GERRETS, T. F. Louisiana Power & Light Co. 84703/15 COLLINS, J. T. Region 4. Office of Director 2pp 22769 342 24X Fiche 50-382,84703/15,8403270046
- 8403270095 Final Deficiency Rept 146 re A-490 bolts for framing above steam generators Initially reported on 840203 Condition determined not reportable per 10CFR50 55(e) GERRETS,T F Louisiana Power & Light Co 84/03/15 COLLINS,J T Region 4. Diffice of Director 3pp 22766 336 24X Fiche 50-382,84/03/15.8403270095
- 8403270040 First interim Significant Const Deficiency Rept 103 re
 RADFLEX wall penetrations installed by 8&8 Insulation, inc
 Insp procedures initiated All RB-8 seals installed in wall
 penetrations will be included in rept Next rept by 840420
 OERRETS, T F Louisiana Power & Light Co 84/03/16 COLLINS, J T
 Region 4, Office of Director 5pp 22769 316 24X
 Fiche 50-382,84/03/16,8403270040
- B403270161 Final rept of Significant Const Deficiency 98 re measuring & test equipment propram Evaluation procese to determine impact of out-of-tolerance condition on safety-related testing completed GERRETS.TF Louisiana Power & Light Co 84/03/16 COLLINS, J T Ragion 4, Office of Director 3pp. 22769 162 24X Fiche 50-382,84/03/16,8403270161

U Congressional/Executive Correspondence

- 8403140204 Responds to B40201 ltr re economic penalties accruing from delays in achieving commercial operation Const Assessment Team conducting insp to determine if completed work in accord w/design documents
 DIRCKB.W J Office of the Executive Director for Operations
 84/03/04 TAUZIN.B House of Rep 4pp 22637 336 24X
 Fiche 50-382,84/03/06,8403140206
- --8403140208 Requests sarliest consideration of util licensing requests
 Delay will be at customers expense
 TAUZIN:8 House of Rep 84/02/01 KENT:8 Office of
 Congressional Affairs. 6pp 22637 360 24X Fiche 50-382,
 84/03/06:8403140206

V Operator Examinations

B403260134 Forwards completed operating shift experience forms BARKHURST.R P. Louisians Power & Light Co B4/03/22 DENTON.H Office of Nuclear Reactor Regulation. Director 8pp 22756 226 24X Fichs 50-382,84/03/22,8403260154

DOCKET 50-383 WATERFORD GENERATING STATION, UNIT 4

- A Application/construction stage documents & correspondence
- 840201050B Provides updated status of rev to Westinghouse designed PWR ECCS actuation logic Westinghouse plans completion of evaluation for submittal by mid-Mar 1984 MATTSON.R J Division of Systems Integretion (post 811005) 84/01/23 EISENMUT,D Division of Licensing 2pp 22546 007 24X Fiche:50-000.84/02/27.8402070017

DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re fecilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON. J H Division of Rules and Records 84/02/13 ANDERSON. S 1 Garvey. Schubert. Adams & Barer 7pp 22583 R26 24X Fiche 50-000.84/02/13.8403080179.
- --B005i30793 Provides status of SER inputs & acceptance reviews for OL & CP applications Schedule should be met BURKE.W C Effluent Treatment Systems Branch 80/02/06 KREGER.W E Assistent Director for Bite Analysis ip 22583 235 24% Fiche 50-000.84/02/i3.8403080179
- F Security, medical, emergency & fire protection plans
- 8403090209 Rev 4 to Emergency Plan Implementing Procedure EP-IP-045, "Action Step Emergency Director OSC Coordinator TSC Coordinator:" including Rev 37 to table of contents.Rev 16 to forms index & B4030B transmittal W/840229 ltr Pennsylvania Power & Light Co 84/02/28 26pp. 22575 089 24X Fiche 30-387,84/02/28.8403090209
- 8403050090 Revised emergency plan implementing procedures, including Rev 37 to table of contents, Rev 16 to forms index & Rev 4 to Procedure EP-IP-045 re PASS 14 7 ml gas sample W/840229 transmittal ltr
 MILLER, D.W. Pennsylvania Power & Light Co. 84/02/29 SCHWENCER, A Licensing Branch 2 25pp 22490 019 24X Fiche 50-387, 84/02/29, 8403030090
- 8403090231 Responds to 831026 ltr re Change B amended to security training & qualification plan & Changes N & O amended to physicel security plan Changes consistent w/10CFR50 54(p) & acceptable MARTIN.T T Division of Engineering & Technical Programs 84/02/29 KENYON.B D Pennsylvania Power & Light Co 3pp 22571 244 24X Fiche 50-387.84/02/29.8403090231
- |403050116 Forwards proposed change to physical security plan & proposed Amend 37 to License NPF-14 Amend revises physical security plan & License Condition 2 D Plan change withheld (ref 10CFR2 790)
 CURTISIN W Pennsylvania Power & Light Co B4/03/01 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22489 159 24X Fiche 50-387,84/03/01,8403050114
- -B403050122 Application for proposed Amend 37 to License NPF-14 revising physical security plan & License Condition 2 D CURTIS.N W Pennsylvania Power & Light Co B4/03/01 ip 22489-161 24X Fiche 50-387.84/03/01.8403050116
- O3140276 Forwards evaluation of 830627 request for epproval of Change P to physical security plan Change acceptable SCRNENCER: A Licensing Brench 2 84/03/02 CURTIS, N W Pennsylvania Power & Light Co 4pp 22635 329 24X Fiche 50-387.84/03/02:8403140296
- ### Pennsylvenia Power & Light Co Detailed Affiliation Given 3pp Fiche 50-387.84/03/07.8403130020

- 8403130126 Revs to Emergency Plan Implementing Procedures EP-IP-001, EP-IP-002, EP-IP-003, EP-IP-004, EP-IP-007 & EP-IP-008 re swergency classification mgt notification & mgt responsibilities W/840309 ltr * Pennsylvenie Power & Light Co 84/03/09 SCHWENCER.A NRC No Detailed Affiliation Given 75pp 22640 219 24X Fiche 30-387, 84/03/09 (A03150126)
- B403190243 Notification of B40418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-07 Agenda for workshop enci MURLEY. T E Region i. Office of Director 84/03/07 0'100LE. J B Consolidated Edison Co of New York. Inc 35pp 22672'062 24X Fiche 50-000.84/03/09,8403190243
- 8403200292 Forwards Change C to security training & qualification plan Changes do not decrease safeguards affectiveness & can be made w/o prior Commission approvel Change withheld (ref 10CFR73 21)

 KENYON.B D Pennsylvenia Power & Light Co 84/03/12 MURLEY.T E, Region 1. Office of Director ip 22696 176 24X

 Fiche 30-387.84/03/12.8403200292
- B403170242 Rev 3 to Emergency Plen Implementation Procedure EP-IP-002
 "Emergency Mgt Notifications " Table of contents, forms
 index & B40313 transmittal ltr enc!
 # Pennsylvenia Power & Light Co 84/03/13 SCHWENCER, A NRC No
 Detailed Affiliation Given 78pp 22671.213 24X
 Fiche 30-387.84/03/13.8403190242
- 8403200103 Clarifies cover ltr to Rev 7 to emergency plan (PLA-1940)
 Deteils provided for manning emergency aperation facility
 (EGF) & ectivation of beckup EOF Unit 2 fuel load scheduled
 for 8400226 Expeditious epproval requested
 CURTIS,N W Pennsylvania Power & Light Co 84/03/13 SCHHENCER.A
 Licensing Brench 2 3pp 22699 096 24X Fiche 50-387.84/03/13,
 8403200103
- 8403200250 Notifies of issuance of Changes P.Q & R to physical security plen Ambiguities in vital equipment list noted in Change P corrected in Changes Q & R KENYON. B D Pennsylvania Power & Light Co 84/03/13 MURLEY, T E Region i. Office of Director 1p 22691 i13 24X Fiche 50-387.84/03/13,8403200250
- 8403190232 Updates achedules for completing safety perameter display sys.emergency operating procedures & emergency facilities, per Generic Ltr 82-33 Updated emergency procedures will be implemented in Dec 1905 CURTIS: N W Pennsylvanie Power & Light Co 84/03/14 SCHWENCER. A Licensing Branch 2 Rpp 22672 032 24X Fiche 50-387.84/03/14, 8403190232
- B403190346 Advises that Commonweelth of PA will not perticipate in util emergency exercise during CVB4.due to involvement w/other fixed nuclear facilities State will participate in CVB5 exercise
 TAYLOR, D.F. Pennsylvania, Commonwealth of, 84/03/15, CRUTCHFIELD Operating Reactors Branch 5 ip 22673 155 24X
 Fiche 50-387.84/03/15,8403190346
- 8403230120 Notifies that State of PA eligible for bienniel frequency for perticipation in rediclogical emergency preparedness exercise Change from annuel exercise requirement would be supported if requested by util KRIMMR W Federal Emergency Hanagement Agency 84/03/15 JORDAN. EL Division of Emergency Preparedness & Engineering Response (Post 830103) ip 22730 336 24X Fiche 50-387,84/03/15.840330120
- I Finenciel information
- 8403270195 Annual Financiel Rept 1983 W/840322 ltr CAMPBELL.R K . CURTIS N W Pennsylvenia Power & Light Co 83/12/31 DENTON: H R Office of Nuclear Reactor Reguletion, Director. 53pp 22771 049 24X Fiche 50-387,83/12/31,8403270195
- J Insurance & indemnity information
- 8403060437 Provides present level of onsite property damege insurance for facilities
 CURTIS.N W Pennsylvanie Power & Light Co 84/02/29 SALTZMAN, J P
 Assistant Director for State & Licensee Relations 1p. 22518 222
 24X Fiche 50-387,84/02/29,8403060437

K Utility Final Safety Analysis Report (FSAR) & amends

- E403210072 Forwards Amend 56 to application for Class 103 OL, consisting of Rev 34 to FBAR CURTIS,N W Pennsylvania Power & Light Co 84/03/07 BCHHENCER, A Licensing Branch 2 App 22702 278 24X Fiche 50-387, 84/03/07, 8403210072
- --8403210081 Amend 54 to application for Class 103 OL.consisting of Rev 34 to FBAR CURTIS,N W Pennsylvania Power & Light Co 84/03/09 ip 22702 283 24X Fiche 50-387,84/03/09,8403210072
- --8403210090 Rev 34 to FSAR Twenty-eight oversized drawings encl Drawings available in PDR # Pennsylvania Power & Light Co 84/02/29 760pp 22702 284 24% Fiche 50-387, 84/03/09, 8403210072

P Operating license stage documents & correspondence

- 8403010234 Notification of 840222 meeting w/util in Bethesda,MD to discuss proposed changes to standby gas treatment sys Tech Specs PERCH.R Licensing Branch 2 84/02/21 SCHWENCER,A Licensing Branch 2, 3pp 22449 356 24X Fiche 50-387,84/02/21,8403010254
- 8403020329 Responds to request for schedule for completion of Reg Quide 1,97 requirements Exceptions to 811113 ltr re equipment replacement will be addressed in May 1984, in response to Conspic Ltr 82-33 CURTIB,N W Pennsylvania Power & Light Co. 84/02/29 SCHHENGER,A Licensing Branch 2 ip 22439 207 24% Fiche 50-387,84/02/29,8403020329
- B40305010B Forwards ravised response to Generic Ltr 83-28. "Required Actions Based on Generic Implications of Balem ATWS Events." reflecting updates to Items 1 2 .2 1. 2 2 & 4 5 CURTIS.N W Fennsylvania Power & Light Co 84/03/01 EISENHUT.D 0 Division of Licensing Aipp 22485 242 24X Fichs 50-387, 84/03/01,8403050108
- 8403050116 Forwards proposed change to physical security plan & proposed Amend 37 to License NPF-14 Amend revises physical security plan & License Condition 2 D Plan change withheld (ref 10GFR2 790) CURTIS,N.W Pennsylvania Power & Light Co 84/03/01 DENTON.H R Uffice of Nuclear Reactor Regulation, Director 2pp 22489 159 24X Fichs, 50-387, 84/03/01, 8403050116
- --8403050122 Application for proposed Amend 37 to License NPF-14 revising physical security plan & License Condition 2 D CURTIS,N W Pennsylvanja Power & Light Co 84/03/01 1p 22487 161 24X Fiche 50-387.84/03/01.84030500116
- 8403150232 Notification of 840312 meeting w/util in Bethesda,MD to discuss NRC evaluation of detailed control room design review rept PERCM,R L Licensing Branch 2 84/03/05 8CHWENCER,A Licensing Branch 2 3pp 22648 360 24X Fiche 50-387,84/03/05,8403150232
- 8403130111 Informs that util will provide supplemental rept to detailed control room design review summery rept by 840301.containing implementation schedule for resolution of outstanding issues

 CURTIS.N W Pennsylvania Power & Light Co 84/03/06, SCHWENCER.A Licensing Branch 2 ip 22615 271 24X Fiche 50-387.84/03/08, 8403130111.
- 8403210072 Forwards Amend 56 to application for Class 103 OL, consisting of Rev 34 to FSAR, CURTIS, N. W. Pennsylvania Power & Light Co. 84/03/09 SCHWENCER, A Licensing Branch 2 6pp 22702 278 24X Fiche 50-367, 84/03/09, 8403210072
- --8403210081 Amend 56 to application for Class 103 UL; consisting of Rev 34 to F8AR CURTIS,N W Pennsylvania Power & Light Co 84/03/09 1p 22702,283 24X Fiche. 50-387, 84/03/09, 8403210072
- 8403150070 Responds to 831230 requests for response to items identified in E940 technical evaluation rept on conformance to Reg Ouide 1 97 & comments on any assumptions that surpass util 813113 submittal CURTIS, N.M. Pennsylvania Power & Light Co 84/03/13 SCHWENCER, A Licensing Branch 2 Spp. 22643 183 24X Fiche 50-387,84/03/13,8403150070
- 8403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement et BWRs Svc list encl EISENHUT.D 0. Division of Licensing 84/03/14 Commonwealth Edison Co 20pp. 22823.354 24X Fiche 50-000,84/03/14:8403150275

- 8403190395 Forwards proprietary "Analysis of Feedwater Containment Isolation Valves Foilowing Postulated Pipe Rupture," in response to NRC 830831 request for addl info Affidavit and Rept withheld (ref 100FR2 790) CURTIS,N W Pennsylvania Power & Light Co 84/03/15 8CKWENCER, A Licensing Branch 2 4pp 22674 085 24X Fiche 50-387, 84/03/15, 8403190395
- 8403200073 Requests that further action on BWR core thermal hydraulic stability be deferred, due to lack of time to review new info presented at 840308 meeting w/NRC CURTIS.N W Pennsylvania Power & Light Co 84/03/15 SCHWENCER.A Licensing Branch 2 ip 22697 147 24x Fiche 50-387,84/03/15,8403200073
- 8403220102 Forwards revs to FBAR Chapters 6.7 & 1B Revs update containment isolation provisions for facilities & will be incorporated in annual FSAR update in Jul 1984 CURTIB.N W Pennsylvania Power & Light Co 84/03/16 SCHWENGER.A Licensing Branch 2 95pg 22715 184 24X Fiche 50-387.84/03/16. B403220102
- 8403220137 Rev 3 to Procedure EP-IP-046, "PASS lodine/Particulate Sample " W/840319 transmittal ltr " Pennsylvania Power & Light Co. 84/03/16 SCHWENCER, A NRC No Detailed Affiliation Given 3pp 22716 082 24X Fiche 50-387,84/03/16,8403220137

G Inspection reports. IE Bulletins & carrespondence

- 8403070240 Forwards 1E Insp Repts 50-387/84-04 & 50-388/84-05 on 840124-27 No violations noted MARTIN, T T Division of Engineering & Technical Programs 84/02/17 KENYON, B D Pennsylvania Power & Light Co 2pp 22547 318 24X Fiche 50-387,84/02/17.8403070240
- --8403070242 IE Insp Repts 50-387/84-06 & 50-388/84-05 on 840124-27 No violation noted Hajor areas inspected licensee action in closing electrical insp rept findings FINKEL.A. ANDERSON,C J. Region 1. Office of Director. 84/02/16 5pp 22547 320 24% Fiche 50-387,84/02/17,8403070240
- 8403070301 Forwards IE insp Repts 50~387/84~02 & 50~388/84~02 on 840116~20 No violations observed Steps taken to correct violation noted in 830827 Itr verified MARTIN.T T Division of Engineering & Technical Programs 84/02/21 KENYON.B D Pennsylvania Power & Light Co 2pp 22546 342 24X Fiche 50-387,84/02/21,8403070301
- ~-8403070306 iE Insp Repts 50-387/84-02 & 50-388/84-02 on 8401i6-20 No violations identified Hajor areas inspected radiation pretection program & preoperational testing, including itcenses action on previous finding & training NIMITZ.R L . SHANBAKY, M Region I, Office of Director 84/02/13 10pp 22546 344 24X Fiche 50-387.84/02/21.8403070301
- 8403060175 Responds to IE Bulletin 93-08 Circuit breakers w/
 undervoltage trip attachments not used in safety-related
 applications in Unit 1 Subj attachments installed in Unit 2
 will be removed from safety-related applications
 CURTIS, N W Pennsylvania Power & Light Co 84/02/27 MURLEY.T E
 Region 1, Office of Director 2pp 22518 267 24X
 Fiche. 50-387,84/02/27,8403060175
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/20 Consolidated Edison Co of New York Inc 115pp 22907 237 24X Fichs 50-000.04/02/28.8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Gonsolidated Edison Go of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02.8402090007.
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDÁN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York: Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402070007 IE Info Notice 84~15, "Reporting of Redictogical Releases"
 Byc list encl
 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 119pp 22553 217 24X Fiche 50-000.84/03/02,8402090009

- 8402090011 IE Info Natice 84~17, "Problems H/Liquid Nitrogen Cooling Components Below Ni! Ductility Temp " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York. Inc. 117ap 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8402070024 IE Info Natice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown 8ys." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24% Fiche 50-000.84/03/07.8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list enc:
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584 186 24X Fiche 50-000.84/03/07.8402070028
- 8403150053 Forwards IE Insp Rept 50-387/84-11 Enforcement conference scheduled for 840313 to discuts inoperability of RPCI & RCIC sys on 840126 resulting in overflow of condensate storage tank
 STARGSTECKI, R Division of Project & Resident Programs 64/03/08 KENYON, B D Pennsylvania Power & Light Co 2pp 22641 015 24X Fiche 50-387.84/03/08,8403150053
- --8403130060 IE Insp Rept 50-387/84-11 on 840221-24 Major areas inspected sys lineup problems resulting in MPCI sys & RCIC sys inoperability PLISCOLL COMPILL C , JACOBS R Region 1, Office of Director 84/03/08 App. 22641 017 24% Fichs. 50-387,84/03/08.8403150053
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Byc list encl.

 DEYOUND, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823 094 24% Fiche 30-000/84/03/12/8402090031
- 8403190360 Ack receipt of 840225 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/83-31 & 50-388/83-31 MARTIN.T T Division of Engineering & Technical Programs 84/03/13 KENVON.D Pennsylvania Power & Light Co ip 22673 312 24X Fiche 50-387/84/03/13/8403190360.
- --8403170366 Responds to NRC 840127 ltr re violations noted in IE Insp Rapts 50-387/83-31 & 50-388/83-31 Corrective actions status repts for Nonconformance Repts 83-779 & 83-1190 received by GC supervisor on 840201 & 0131, respectively MENYON, B D Fennsylvania Power & Light Co 96/02/25 MARTIN, T T Division of Engineering & Technical Programs 3pp 22673 313 24X Fiche 50-387.84/03/13.8403190360
- 8403220128 Act receipt of 840225 ltr informing NRC of staps taken to correct violations noted in 1E Insp Repts 50-387/83-30 & 50-388/93-25
 MARTIN.T T Division of Engineering & Technical Programs 84/03/13
 KENYON.B D Pennsylvania Power & Light Co ip 22716 014 24X
 Fiche.50-587.84/03/13.8403220128
- --8403220135 Responds to NRC 840126 ltr re violations noted in IE Insp Repts 50-387/63-30 & 50-388/83-25 Corrective actions Temporary Setpoint Changes 82-028T & 82-029T made into germanent setpoint changes KENYON 8 D Pennsylvania Power & Light CO 84/02/25 HARTIN, T T Division of Engineering & Technical Programs 4pp 22716-015 24x Fiche 50-387.84/03/13.8403220128
- 8403290114 Forwards IE Insp Repts 50-387/84-05 & 50-388/84-06 on 840130-0203 & notice of violation MARTIN, T.T. Division of Engineering & Technical Programs 84/03/13 KENYON, B.D. Pennsylvania Power & Light Co. 2pp. 22806 292, 24X Fiche 50-387,84/03/13,8403290116
- --B403290ii9 Notice of violation from lnsp en 840130-0203 * Region i, DfPice of Director. 84/03/13 ip 22806 294, 24% Fiche 50-387.84/03/13,8402290116
- ~-8403293120 IE Insp Repts 80-387/84-05 & 50-388/84-06 on 840130-0203
 Noncompliance noted failure to follow QC procedure for
 radiochemistry to determine instrument operating voltage
 KOTTAN-J J. ZIBULSKY.H. HOOM.R. Region 1. Office of Director
 84/03/07 8pp. 22806 245. 24X Fiche 50-387,84/03/13,8403270116
- 8403270140 Forwards IE Insp Repts 50-387/83-29 & 50-388/83-32 on 831217-840130 & notices of violation & deviation. Uncorrected repetitive trips of standby gas treatment fans during Unit 2 Cold Functional Tast P200 18 noted STAR09TECKI.R Division of Project & Resident Programs 84/03/14 KENYON, B D Pannaylvania Power & Light Co 2pp. 22806 011 24% Fiche, 30-387,84/03/14,8403270140

- --8403270142 Notice of violation from insp on 831219-840130 # Region i, Office of Director 84/03/14 lp 22806 013, 24x Fiche 50-387,84/03/14,8403290140
- --8403290149 Notice of deviation from insp on 831219-840130 * Region I. Office of Director 84/03/14 ip 22806 014 24x Fichs 50-387,84/03/14,8403290140
- --B403290155 IE lnsp Repts 30-387/83-29 & 50-388/83-32 on 831219-840130 Violation identified conditions adverse to quality not promptly identified & corrected Deviation identified failure to meat FSAR commitment for automatic depressurization sys JACOBS:R , PLISCO, L. Region 1. Office of Director MCCABE.E C Division of Project & Resident Programs 84/02/24 21pp. 22806 015 24X Fiche, 50-387, 84/03/14,8403290140
- 8403220033 Ack receipt of 840301 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/83-23 STAROSTECKI.R Division of Project & Resident Programs. 84/03/15 KENYON, 8 D Pennsylvanie Power & Light Co ip 22712 325 24X Fichs 50-387.84/03/15.8403220033
- --8403220041 Responds to NRC 640104 ltr re violations noted in IE Insp. Rept 50-387/83-23 Corrective actions total responsibility assumed for design change process & program for processing F6AR change requests adopted KENYON.8 D Pennsqlvania Power & Light Co 84/03/01 STARGETECKI.R Division of Project & Resident Programs 3pp 22712 326 24X Fiche 50-387.84/03/15,8403220033
- 8403220069 Completes response to 1E Bulletin 83-07. "Apparently Fraudulant Products Sold by Ray Miller, Inc." & two suppls No Ray Miller, Inc mati installed Nuclear Energy Svc. Inc supplied ultrasonic calibr blocks CURTIS:N W Pennsylvania Power & Light Co B4/03/16 MURLEY, T.E. Region 1. Office of Director 99p 22712 275 24x Fiche 50-387,84/03/16,8403220069.
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl, JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list ene! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- 8403300043 Atk receipt of 840309 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/83-27 & 50-386/83-24 MARTEN.T T Division of Engineering & Tachnical Programs 84/03/2 KENYON. B D Pennsylvania Power & Light Co 2pp 22821 286 24) Fiche 30-387.84/03/21.8403300063
- --8403300069 Responds to NRC 840208 ltr ra violations noted in IE Insp. Repts 50-387/83-27 & 50-388/83-26 Corrective actions min requirements for satisfactory calibr of monitor established & added as acceptance criteria to surveillance procedure. KENYON, 8 D. Pennsylvania Power & Light Co 84/03/09 MARTIN, T T Division of Engineering & Technical Programs 3pp 22821.288 24X Fiche 50-387,84/03/21.8403300063
- R Periodic operating reports & related correspondence
- 8403130039 "Bemjannual Effluent & Waste Disposal Rept.Jul-Dec 1983."

 M/840301 ltr

 WIDNER.T E. KENYON.B D., DOTY.R L. Pennsylvenia Power & Light Co
 83/12/31 MURLEY.T E. Region 1. Office of Director 13ipp
 22501 119 24% Fiche 50-387.83/12/31.8403130059
- 8403210112 "Annual Personnel Exposure Rapt for CY83 " W/840229 ltr KENYONAB D Pannsylvania Power & Light Co 63/12/31 MURLEY, T.E. Region 1. Office of Director. 2pp. 22705 060 24X Fiche. 50-387. 83/12/31, 8403210112
- 8403020036 Monthly operating rapt for Jan 1984 W/840214 ltr. KUCYYNSKI, L A , KENYON, B D Pennsylvania Power & Light Co 84/01/31 BEEBE, M Management Information Branch 5pp 22442 237 24% Fiche 50-387.84/01/31,8403020036
- 8403300147 Monthly operating rept for Feb 1984 M/840313 ltr KUCZYNBKI, L A., KENYON, B D Pennsylvania Power & Light Go. 84/02/29 BEEBEM, R Management Information Branch. 6pp 22820-077 24X Fische 50-387. 84/02/29, 8403300147

- 840:3090232 NPDES noncompliance notification sewage treatment plant Outfall 079 failed to meet required 85% reduction in total suspended solids for Jan 1984 FIELDS.J S Pennsylvania Power & Light Co 84/03/06. Pennsylvania. Commonweelth of. 2pp 22572 213 24% Fiche. 50-087:84/03/06.8403090232
- --8403090239 "NPDES Discharge Monitoring Rept for Jan 1984 "
 * Pennsylvania Power & Light Co 84/03/01 9pp 22572 215 24X
 Fiche 50-387,84/03/06,8403090232

B Reportable occurrences: LERs & related correspondence

- 8403020253 LER 84-002-01 on 840106, emergency svc water B1 spray risers would not pump down due to spray network inlet valve leaking past seet Caused by minimal thread engagement between distribution arm coupling & riser nipple.W/840228 ltr KUCZYNSKI/L A, KEIBER, H W. Pennsylvania Power & Light Co 84/02/28 4pp 22440 103, 24X Fiche 50-387,84/02/28,8403020253
- B403020319 Updated LER 83-14B/03X-1 on B31209, microprocessor enalyting flow rate data falled & word normal printed for channel output during each daily surveillance Microprocessor replaced M/840228 ltr WILKS:B L., KEISER:H W Pennsylvania Power & Light Co 84/02/28 4ne 22439*201 24X Fiche, 50-387, 84/02/28, 8403020319.
- B403060108 RD carbon dioxide fire supprassion sys declared inoperable, due to design deficiency. Fire watch postad & mod initiated to remove enough penetration seals to permit proper carbon discide discharge
 KEIBER. H M. Pennsylvania Power & Light Co 84/03/01. Racord Bervices Branch (Document Control Desk) ip 22506 181. 24X Fiche: 50-387.84/03/01.8403060108.
- 8403060253 LER 84-007-00: on 840202, shear valve explosive cartridge unexpectedly fired during surveillance testing, shearing transvarsing in-core probe detector cable Cause unknown. New detector & cable Instelled Procedure changed W/840302 ltr WILMS, B.L., KEISER, H.W. Pennsylvania Power & Light Co. 84/03/02 3pp. 22515, 191. 24X Fiche, 50-387, 84/03/02, 8403040253
- B403070224 PNO-I-84-022 on B40303 reactor scrammed from 74% power. Caused by fest closure of main turbine control valve during surveillance on hydraulic detector Suspect relays in detector test instrumentation replaced JACOBB.R., KELLY.E. Region i, Office of Director 84/03/05, ip 22575 077. 24% Fiche 50-387,84/03/05,8403070224.
- 3403090232 NPDES noncompliance notification.sewage treatment plant Outfall 079 failed to meet required 85% raduction in total suspended solids for Jan 1984 FIELDS, J.S. Pennsylvania Power & Light Co., 84/03/06 Pennsylvania, Commonwealth of, 2pp 22572.213 24% Fiche: 50-387.84/03/06.8403090232
- -8403090239 "NPDES Discharge Monitoring Rept for Jan 1984."

 # Pannsylvania Power & Light Co 84/03/01 9pp 22572-215. 24X
 Fiche: 50-387,84/03/06,8403090232.
- 403140011 LER 84-008-00, on 840207, during outage RHR sael water coolers discovered improperly designed Coolers replaced Teledyne Engineering Svc conducting independent review. M/840309 ltr MOOD, D. C., KEIBER, H, M. Pennsylvania Power & Light Co. 84/03/09. 3pp 22633-226, 24X Fiche, 50-387, 84/03/09, 8403140011.
- 403140018 Updated LER 83-164/01x-1 on 831221, test results indicated that 3-way clamps on control rod drive insert & withdrewal lines may not be able to withstand worst case axial water hammer loads Plant mods completed W/840309 itr. WOOD, D. C., KEISER, H. W. Pennsylvania Power & Light Co 84/03/09, MURLEY, T.E. Region 1, Office of Director 3pp. 22633;222, 24X Fiche 50-387,84/03/09,8403140018.
- 103160197 Special rept.fire barrier damper inoperable longer than Tech Epec limits. Caused by damper being physically blocked open. Mod performed to install access hatch in ductwork Damper resat.
- KEIBER, H W. Pennsylvania Power & Light Co 84/03/12. Record Bervices Branch (Document Control Desk). 1p 22655.350 24X Fiche: 50-387.84/03/12,8403160197.
- O3260226 LER 84-009-00 on 840221, during restert, HPCI steam supply line pressure indicator did not respond to werm up & reactor pressure exceeded 130 psig. Checkoff list & operating procedure revised, H/840320 ltr MCOD, D C., KEISER, H. N Pennsylvania Power & Light Co. 84/03/20 Gpp. 22756:083. 24% Fiche: 50-387, 84/03/20, 8403260226

- DOCKET 50-388 SUBGUEHANNA STEAM ELECTRIC STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8403010254 Notification of 840222 meeting w/util in Bethesda.MD to discuss proposed changes to stendby gas treatment sys Tech Spacs PERCH,R Licensing Branch 2 84/02/21 SCHWENCER.A Licensing Branch 2 3pp 22449 356 24X Fiche 50-387.84/02/21,8403010254
- 8403020329 Responds to request for schedule for completion of Reg Guide
 1 97 requirements Exceptions to Billi3 ltr re squipment
 replacement will be addressed in Mey 1984, in response to
 Generic Ltr B2-33
 GURTIS.N W Psnnsylvania Power & Light Co 84/02/29 BCHWENCER, A
 Licensing Branch 2 1p 22437 207 24% Fiche 50-387, 84/02/27,
 8405020329
- 8403050108 Forwards revised response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Balem ATMS Events." reflecting updates to Items 1 2 2, 2 1, 2 2 2 4 5 CURTIS,N M Pannsylvanie Pawer & Light Co 84/03/01 EISENHUT,D 0 Division of Licensing 61pp 22485 242 24X Fiche 50-387, 84/03/01,8403050108
- 8403:50321 Notification of 840308 meeting w/util in Luzerne County, PA to perform sits visit re readiness of fecility for licensing. PERCH.R L Licensing Branch 2. 84/03/01 SCHWENCER, A Licensing Branch 2 4pp 22649 299 24X Flche 50-388, 84/03/01, 8403150321
- 8403150832 Notification of 840312 meeting w/util in Bethesda, MD to discuss NRG evaluation of deteiled control room design review rept PERCH.R.L Licensing Branch 2 84/03/05 BCHWENCER.A. Licensing Branch 2 3pp 22648 360 24X Fiche 50-387,84/03/05,8403150232
- 8403:50268 Requests review of enci finel draft Tech Specs & amend to appilcation confirming that draft accurately reflects plant. FEAR & SER analyses Results should be submitted under each or affirmation. M/o enci EIBENNUT.D 0 Division of Licensing 84/03/05 CURTIS.N W Pennsylvania Power & Light Co. 2pp 22648 283 24X Fiche: 50-388.84/03/05.8403:50268
- 8403:20026 Forwards "Reactor Containment Bldg Integrated Leakage Rate Test, Unit 2-Flnai Rept," KENYON,B.D Pannsylvanis Power & Light Co 84/03/07. Offics of Nuclear Reactor Regulation, Director ip 22590 227 24X Fiche: 50-388-84/03/07.8403:20026.
- --8403120030 "Reactor Containment Bldg integrated Leakage Rate Test, Unit 2.Finel Rept " * Bechtei Corp 83/11/30. 54pp 22590-228 24X Fiche. 50-388, 84/03/07, 8403120024.
- 8403130iii Informs that util will provide supplemental rept to detailed control room design review summary rept by 840301, containing implementation schedule for resolution of outstending issues

 CURTIS,N W Pennsylvania Power & Light Co 84/03/08 9CHMENCER, A Licensing Brench 2 ip 22615, 291. 24X Fiche 50-387, 84/03/08, 8403/3011i
- B403210072 Forwards Amend 56 to application for Class 103 OL, consisting of Rsv 34 to FBAR.

 CURTIS,N W. Pennsylvania Power & Light Co 84/03/09 SCHWENCER, A Licensing Branch 2. 6pp 22702'278 24X Fichs 50-387, 84/03/09, 8403210072.
- --8403210081 Amend 56 to application for Ciess 103 DL,consisting of Rev 34 to FSAR CURTIS,N W Pennsylvania Power & Light Co 84/03/09 ip 22702 283 24X Fiche. 50-387,84/03/09,8403210072
- 8403150070 Responds to 831230 requests for response to items identified in EQ&Q technical avaluation rept on conformance to Reg Quide 1 97 & comments on any assumptions that surpass util 811113 submittal.

 CURTIS,N W Panniylvania Power & Light Co 84/03/13 SCHMENCER,A Licensing Branch 2, 8pp 22643.183 24X Fiche 50-387,84/03/13,8403150070
- B403190395 Forwards proprietary "Analysis of Feedwater Containment Isolation Valves Following Postulated Pips Rupture: "In response to NRC B30831 request for add1 info Affidayit encl. Rept withheld (ref 10CFR2.790). CURTIB.N W Pennsylvania Power & Light Co 84/09/15 SCHWENCER./ Licensing Branch 2. 4pp. 22674:085 24X Fiche 50-387,84/03/15. 8403190395

- 8403200006 Documents discussions w/R Perch re status of dynamic qualification of listed items, including Valcor control rod drive solenoid valves & condensate storage tank CVRTE, N W Pennsylvania Power & Light Co 84/03/15 BCHWENCER, A Licensing Branch 2 2pp 22683 207 24X Fiche 50-388,84/03/15,840320006
- B403200073 Requests that further action on BWR core thermal hydraulic stability be deferred due to lack of time to review new info presented at 840308 meeting w/kRC CURTES, N W Pennsylvania Power & Light Co 84/03/15 SCHWENCER, A Litensing Branch 2 lp 22679 147 24X Fiche: 50-387, 84/03/15. 8403200073
- 8403220040 Notifies of const completion & assurance that plant conforms w/design intent & regulatory requirements Comprehensive GA program in place through-out life of project Util has not allowed contractor to function independently CURTIS,N W Pennsylvania Power & Light Co 84/03/16 DENTON,H R Office of Nuclear Reactor Regulation. Director. 2pp 22712 144 24X Fiche 50-388,84/03/16,8403220040.
- B403220102 Forwards revs to FBAR Chapters 6.7 & 18 Revs update containment isolation provisions for facilities & will be incorporated in annual FBAR update in Jul 1984 CURTIS,N W Pennsylvania Power & Light Co 84/03/16 BCHWENCER,A Licensing Branch 2 95pp 22715 184 24% Fiche 50-387.84/03/16, 8403220102
- B403260305 Forwards draft NUREG-1042, "Tech Specs, Susquehanna Steam Electric Station" CURTIS,N W Pennsylvania Power & Light Co 84/03/20 DENTON, H R Office of Nuciear Reactor Regulation, Director 480pp 22753 158 24X Fiche 50-388,84/03/20,8403280305
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FDIA Exemption 5) Review of add1 documents subj to request continuing FELYON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche, 50-000. 84/02/13. 8403080179
- --B005130793 Provides status of SER inputs & acceptance reviews for OL & CP applications Schedule should be met BURKE.N C Effluent Treatment Systems Branch B0/02/06 KREOER.N E Assistent Director for Site Analysis ip 22589 235 24X Fiche 50-000.84/02/13.8403080179
- 8403010294 Forwards Rev 2 to Rept 02-0160-1102, "Review of Unit 2 Control Sys Farlures, Final Rept. Unit 2 Control Sys Power Supply & Sensor Melfunctions " Rept submitted per SER CURIIS, N Pennsylvania Power & Light Co 84/02/27 SCHWENCER, A Licensing Branch 2 1p 22432 304 24% Fiche 50-388, 84/02/27, 8403010294
- --8403010303 Rsv 2 to Rept 02-0160-1102. "Review of Unit 2 Control Bys Failures, Final Rept, Unit 2 Control Bys Power Supply & Sensor Halfunctions" SHAMADIAN, R. L., KEREKES, W. A. Impell Corp. 02-0160-1102 R02 84/02/27 19pp 22432 306 24X Fiche 50-388,84/02/27,8403010294
- 8403200071 Confirms that 42 human engineering discrepancies generated from preliminary design assessment 5 NRC control room audit of Unit 1 incorporated into Unit 2 control room.per App F to SSER 5 CURTIS, N M Pennsylvania Power & Light Co 84/03/15 9CHWENCER, A Licensing Branch 2 1p 22684 341 24% Fiche 50-388, 84/03/15, 8403200071
- F Security, medical, emergency & fire protection plans
- B403090209 Rev 4 to Emergency Plan Implementing Procedure EP-IP-045,
 "Action Step Emergency Director QSC Coordinator TSC
 Coordinator: "Including Rev 37 to table of contents:Rev 16
 to forms index & 840308 transmittal W/840229 ltr
 * Fennsylvania Power & Light Co 84/02/28 26pp 22575 089 24X
 Fiche 50-387.84/02/28,8403090209
- 8403050070 Revised emergency plan implementing procedures, including Rev 37 to table of contents. Rev 16 to forms index & Rev 4 to Procedure EP-1P-045 re PASS 14 7 ml gas sample H/B40229 transmittal ltr MILLER, D W Pennsylvania Power & Light Co 84/02/29 SCHWENCER, A Licensing Branch 2 25pp 22470 019 24% Fiche 50-387.84/02/29, 8403050070

- 8403140276 Forwards evaluation of 830627 request for approval of Change P to physical security plan Change acceptable SCHWENCER, A Licensing Branch 2 84/03/02 CURTIS, N W Pennsylvania Power & Light Co 4pp 22635 329 24X Fiche 50-387,84/03/02.8403140296
- 8403150126 Revs to Emergency Plan Implementing Procedures EP-1P-001. EP-1P-002. EP-1P-003. EP-1P-003 & EP-1P-008 re emergency classification, mpt notification & mgt responsibilities W/B40309 itr spensylvanie Power & Light Co B4/03/09 BCHWENCER, A NRC No Detailed Affiliation Givan 95pp 22640 219 24X Fichs 50-387.84/03/09.8403150126
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agende for workshop enci NURLEY.TE Region I. Office of Director 84/03/09 D'YDOLE.J b Consolidated Edison Go of New York. Inc 35pp 22672 062 24X Fiche 50-000.84/03/09.8403190243
- 8403190242 Rev 3 to Emergency Plan Implementation Procedure EP-IP-002 "Emergency Mgt Notifications " Table of contents, forms index & 840313 transmittal ltr encl # Pennsylvania Power & Light Co 84/03/13 8CHWENCER, A NRC No Detailed Affiliation Given 78pp 22671 213 24X Fiche 50-387,84/03/13,8403190242
- B403200103 Clarifies cover ltr to Rev 7 to emergency plan (PLA-1940)
 Betails provided for manning emergency operation facility
 (EOF) & activation of backup EOF Unit 2 fuel load scheduled
 for 840326 Expeditious approval requested
 CURTIS.N W Pennsylvania Power & Light Co 84/03/13 8CHWENCER.A
 Licensing Branch 2 3pp 22699 096 24X Fiche 50-387,84/03/13,
 8403200103
- B403190232 Updates schedules for completing safety parameter display sys.emergency operating procedures & emergency facilities, per Generic Ltr B2-33 Updated emergency procedures will be implemented in Dec 1985 CURTIS,N W Pennsylvania Power & Light Co 84/03/14 BCHMENCER.A Licensing Branch 2 2pp 22672 032 24X Fiche 50-387,84/03/14. B403190232
- B403190346 Advises that Commonweelth of PA will not participate in util emergency exercise during CVB4, due to involvement w/dther fixed nuclear facilities State will participate in CVB5 exercise

 TAYLOR, D.F. Pennsylvania, Commonwealth of, 84/03/15 CRUTCHFIELD Operating Reactors Branch 5 1p 22673 135 24X

 Fiche 50-387,84/03/15,8403190346
- 8403230120 Notifies that State of PA aligible for biennial frequency for participation in radiological emergency preparedness exercise Change from annual exercise requirement would be supported if requested by util KRIMM,R W Federal Emergency Management Agency 84/03/15. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) ip 22730 336 24X Fiche 50-387.84/03/15.8403230120

I Financial information

- 8403270195 Annual Financial Rept 1983, W/840322 ltr CAMPBELL,R K , CURTIS N W Penneyivania Power & Light Co 83/12/31 DENTON H R Office of Nuclear Resctor Regulation, Director 53pp 22771 049 24X Fiche 50-387.83/12/31,8403270195
- J Insurance & indemnity information
- 8403060437 Provides present level of onsite property damage insurance for facilities CURTIE:N W Pennsylvania Power & Light Co. 84/02/29 SALTZMAN.J D Assistant Director for State & Licensee Relations, 1p 22518 222 24X Fiche 50-387:84/02/29:8403060437
- K Utility Final Safety Analysis Report (FSAR) & amends
- B403210072 Forwards Amend 56 to application for Class 103 DL, consisting of Rev 34 to FSAR, CURTIS, N Pannsylvania Power & Light Co 84/03/09, 8CHMENGER, A Licensing Branch 2 6pp 22702 278, 24X Fiche 50-387, B4/03/09, 8403210072
- ---8403210081 Amend 56 to application for Class 103 OL, consisting of Rev 34 to FSAR CURTIS, N W Pennsylvania Power & Light Co 84/03/09. 1p 22702 283 24X Fiche 50-387,84/03/09,8403210072

- --8403210090 Rev 34 to FSAR Twenty-sight oversized drawings encl Drawings available in PDR
 * Pennsylvania Power & Light Co 84/02/29 760pp 22702 284 24% Fiche 50-387, 84/03/09, 8403210072
- O Inspection reports, IE Bulletins & correspondence
- 9403020214 Forwards IE Insp Rept 50-388/84-03 on 840109-13 No violatione observed MARTIN, T T Division of Engineering & Technical Programs 84/02/17 KENYON, B D Penneylvania Power & Light Co 2pp 22440 254 24X Fichs 30-388,84/02/17,8403020214
- --B403020220 IE Insp Rept 50-388/84-03 on 840109-13 No violations or deviations identified Major areas inspected preoperational testing GA.preoperational test records & GA for startup test program NAPUDA.O : PRELL. J Region I. Office of Director CODY, A T Division of Engineering & Technical Programs B4/02/16 7pp 28440 256 24X Fiche 50-388.84/02/17.8403020214
- 8403070240 Forwards IE Inep Repts 50-387/84-06 & 50-388/84-05 on 840124-27 No violations noted MARTIN, T T Division of Engineering & Technical Programs 84/02/17, KENYON; B D. Pennsylvania Power & Light Co 2pp 22547-318 24X Fichs 50-387,84/02/17,8403070240
- --8403070242 IE Insp Repte 50-387/84-06 & 50-388/84-05 on 840124-27 No violation noted Major areas inspected licensee action in closing alectrical insp rept findinge FINKEL.A. ANDERSON, C. J. Region 1. Office of Director 84/02/16 Spp 22547 320 24X Fiche 80-387.84/02/17.8403070240
- 8403070301 Forwards IE Insp Repte 50-387/84-02 & 50-388/84-02 on 840116-20 No violations observed Steps taken to correct violation noted in 830829 itr verified MARTIN.T T Division of Engineering & Technical Programs 84/02/21 KENYON,B D Penneylvania Power & Light Co 2pp 22546 342 24X Fiche 50-387.84/02/21.8403070301
- 8403050175 Responde to IE Bulletin 83-08 Circuit breakers w/
 undarvoltage trip attachments not used in safety-halated
 applications in Unit i Subj attachments installed in Unit 2
 will be removed from safety-helated applications
 CURTIS:N W Pennsylvania Power & Light Co 84/02/27 MURLEY, T E
 Region i, Office of Director. 2pp 22518 267 24X
 Ficha 50-387,84/02/27,8403060175
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuite & Annunciation " Svc list ancl.

 JORDAN.E L Division of Emergency Preparednees & Engineering Response (Poet 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22707 237 24X Fiche 50-000.84/02/28.8401190072
- 8403150027 Forwards IE Insp Rept 50-388/83-19 on 831017-28 & notice of violation MARTIN.T.T. Division of Engineering & Technical Programs 84/02/28 KENYON, B. D. Pennsylvania Power & Light Co. 2pp. 22645-327 24X Ficha: 50-388-84/02/28-8403150027.
- --8403130030 Notice of violation from inep on 831017-28 Assessment of strangths & weaknesses. App 8. encl * Region 1. Office of Director. 84/02/28 3pp 22645 329 24X Fiche: 50-388, 84/02/28, 8403150027
- ---8403150034 IE Insp Rept 50-388/83-19 on 831017-28 Violations noted: inadequate preparation of weld for ultrasonic insp & small bore piping flex leg not inetalled per engineering design calculation

 BETTENHAUSEN, L., CAMPBELL, R.M., HARRIS, R.H. Region 1, Office of Director, 84/02/27 36pp, 22645-332, 24X Fichs 50-388,84/02/28,8403150027
- 8402090007 IE Info Notice 84-14, "Highlighte of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl ORACE, J. N. Division of QA, Bareguards & Inspection Programs (Post 830103). 84/03/02, Consolidated Edison Co of New York, Inc. 130pp 22552;329 24X Fiche. 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-14, "Failure of Automatic Sprinkler Sys Valves to Operate." Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553.098 24% Fiche 50-000,84/03/02,8402070008

- 8402070007 1E Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 117
- 8402090011 IE Info Natice 84-17, "Probleme W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 2253 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09:Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sye " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 11899 22635 049 24X Fiche 50-000:84/03/07:8402070024
- B40209002B IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list enci JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consultdated Edison Co. of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of OE Type HFA Relays in Use in Class IE Safety Sye " Svc list encl
 DEYOUNG:R C Director's Office. Diffice of Inspection and
 Enforcement 84/03/12 Consolidated Edison Co of New York, Inc
 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403190360 Atk receipt of 840223 ltr informing NRC of atepe taken to correct violations noted in IE Inep Repts 50-387/83-31 & 50-387/83-31 MARTIN.T T Division of Engineering & Technical Programs 84/03/13 KENYON.B D Pennsylvania Power & Light Co ip 22673 312 24X Fiche 50-387.84/03/13.8403190360
- --B403190366 Reeponde to NRC B40127 ltr re violations noted in IE Insp Repte 50-387/83-31 & 50-388/83-31 Corrective actions statue repts for Nonconformance Repts 83-779 & 83-190 received by GC supervisor on 840201 & 0131, respectively KENYON.B D Pennsylvania Power & Light Co 84/02/25 MARTIN.T T Bivision of Engineering & Technical Programs 3pp 22673 313 24X Fiche 50-387,84/03/13,8403190360
- 8403220128 Ack receipt of 840225 itr informing NRC of stepe taken to correct violations noted in IE Insp Repts 50-387/83-30 & 50-389/83-25 MARTIN, T T Division of Engineering & Technical Programs 84/03/13 KENYON, B D Pennsylvania Power & Light Co Ip 22716 014 24X Fiche 50-387.84/03/13.8403220128
- --8403220135 Responde to NRC 840126 itr re violations noted in IE Insp Repts 50-387/83-30 & 50-388/83-25 Corrective actions Temporary Setpoint Changes 82-028T & 82-029T made into permanent setpoint changes KENYON: B D Penneyivania Power & Light Co 84/02/25 MARTIN, T T Division of Engineering & Technical Programs 4pp 22716 015 24% Fichs 50-387, 84/03/13, 8403220128
- 8403290116 Forwards IE Insp Repts 50-387/84-05 & 50-388/84-06 on 840130-0203 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 84/03/13 KENYON.B D Panneylvania Power & Light Co 2pp 22806 292 24X Fiche 50-387,84/03/13,8403290116
- --8403270120 IE Insp Repts 50-387/84-05 % 50-388/84-06 on 840130-0203 Noncompliance noted failure to follow GC procedure for radiochemistry to determine instrument operating voltage KOTTAN.J J. ZIBULSKY, H. HOGAN-R Region 1. Office of Director 84/03/07 Bpp. 22806 273 24X Fiche 50-387,84/03/13,8403270116
- 8403290140 Forwarde IE Insp Repts 50-387/83-29 & 50-388/83-32 on B31219-840130 & notices of violation & deviation Uncorrected repetitive trips of standby gas treatment fans during Unit 2 Cold Functional Test P200 ID noted STAROBTECKI.R Division of Project & Resident Programs 84/03/14 KENYON, B D Fennsylvania Power & Light Co 2pp 22806 011 24X Fiche: 50-387, 84/03/14, 8403290140
- --8403290142 Notice of violation from insp on 831219-840130 * Region i, Office of Director 84/03/14 lp 22806 013 24X Fiche 50-387,84/03/14,8403290140
- --8403290149 Notice of deviation from insp on 831219-840130 * Region i, Office of Director 94/03/14 ip 22806 014 24X Fiche, 50-387, 84/03/14, 8403290140.

- --8403270155 IE Insp Repts 50-387/83-27 & 50-388/83-32 on 831219-840130 Violation identified conditions adverse to quality not promptly identified & corrected Deviation identified fallure to meet FSAR commitment for automatic depressurization sys JACOBS.R. P.LESCO, L. Region i. Office of Director MCCABE, E C Division of Project & Resident Programs 84/02/24 21pp 22806 015 24% Fiche 50-387,84/03/14.8403290140
- 8403220069 Completes response to IE Bulletin 83-07. "Apparently Fraudulent Products Soid by Ray Miller.Inc" & two suppls No Ray Miller, Inc meti installed Muclear Energy Svc.Inc supplied ditresonic calibr blocts CURTIS.N W Pennsylvania Power & Light Co 84/03/16 MURLEY, T E Region I. Office of Director 9pp 22712 275 24X Fiche 30-387.84/03/16.8403220069
- 8402090043 IE info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21, 8402090043
- 8402070044 IE Info Notice 84-20, "Evc Life of Relays in Safety-Related Bys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24% Fiche 50-000,84/03/21,8402070044
- 8403300063 Ack receipt of 840309 itr Informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-387/83-27 & 50-388/83-26 MARTIN.T T Division of Engineering & Technical Programs 84/03/21 XENYON,B D Pennsylvania Power & Light Co 2pp 22821 286, 24X Fiche 50-387,84/03/21,8403300063
- --B403300069 Responds to NRC 84020B ltr re violations noted in IE Insp Repts 50-387/83-27 & 50-388/83-26 Corrective actions min requirements for satisfactory calibr of monitor established & added as acceptance criteria to surveillance procedure KENYON.8 D. Pennsylvania Power & Light Co 84/03/09 MARTIN.T T Division of Engineering & Technical Programs 3pp 22821 288 24X Fiche 50-387.84/03/21.8403300063
- R Periodic operating reports & related correspondence
- 8403090232 NPDES noncompilance notification sewage treatment plant Outfall 077 failed to meet required 85% reduction in total suspended solids for Jan 1984
 FIELDS.J S Pennsylvania Power & Light Co 84/03/06
 Pennsylvania. Commonweelth of: 2pp 22372 213 24X
 Fiche 50-387,88/03/06.8403090232
- --8403090239 "NPDES Discharge Honitoring Rept for Jan 1984 "

 * Pennsylvania Power & Light Co 84/03/01 9pp 22572 215 24X
 Fiche 50-387,84/03/04,8403090232
- S Reportable occurrences, LERs & related correspondence
- 8403210145 Final deficiency & Part 21 repts re safety parameter display sys Technology Energy Corp Model 156 isolators Initially reported on 840106 Non-IE power supply will be provided for isolator prior to end of first refueling CURTIS.N W Pennsylvania Power & Light Co 84/02/27 MURLEY, T E Region 1. Office of Director 4pp 22707 281 24X Fiche 30-388,84/02/27,8403210145
- 8403260233 Forwards summary list of deficiencies identified per 10CFR30 55(e).Part 21 & potential generic itr rapts for comments
 STAROSTECKI.R Division of Project & Resident Programs
 Region 1. Office of Director 7pp 22756 065 24X
 Fiche 50-000.84/02/28.8403260233
- 8403230095 Second interim deficiency rept re improper relief valve setting design pressures & design temp within several sys Initially reported on B31118 Spec M-179 revised & code data repts amended Also reported per Part 21 CURTIGN W Pennsylvania Power & Light Co 84/03/02 MURLEY, T E Region 1, Office of Director 14pp 22726 277 24X Fiche 50-388,84/03/02.8403230095
- 8403090232 NPDES noncompliance notification sewage treatment plant Outfail 079 failed to meet required 85% reduction in total suspended solids for Jan 1984 FIELDS, J. 5. Pennsylvania Power & Light Co. 84/03/04 Pennsylvania, Commonwealth of, 2pp. 22572 213 24% Fiche: 50-387,84/03/06,8403090232

- 8403210125 Final deficiency rept re cavitation of jet pumps due to induction heating stress improvement cooling Initially reported on 831206 No erosion found Also reportable per Part 21 Item not reportable per 10CFR50.55(e) CURTIB.N W Pennsylvania Power & Light Co 84/03/06 MURLEY.T E Region 1. Dffice of Director 4pp 22707 228 24X Fiche 50-388.84/03/06.8403210125
- V Operator Examinations
- 8403i30i50 Forwards nuclear power plant experience tables for operating shift position forms for senior reactor operators & reactor operators Licensed classroom training & exam conducted Fuel ioad expected on 840326 CURTIB.N W Pennsylvania Power & Light Co 84/03/09 DENTON.H R Office of Nuclear Reactor Regulation. Director Spp 22608 106 24X Fiche 50-388.84/03/09.8403i30i50
- DOCKET 50-389 ST LUCIE PLANT, UNIT 2
- E NRC Safety Evaluation Report (SER), supplie & correspondence
- 8401130319 Informs that redundant boron dilution sys alarm installed & deciared operational on 840106, per 821029 & ii04 ltrs & SSER 3

 WILLIAMS, J W Fiorida Power & Light Co 84/01/10 EISENHUT, D Q Division of Licensing ip 21798 305 24X Fiche 50-389, 84/01/10, 8401130319
- F Security, medical, emergency & fire protection plans
- 8403070249 Responds to NRC 831123 itr re vioiations noted in 1E Insp Rapt 30-389/83-57 Corrective actions detectors wiil be moved to ceiling Rereview of IOCFR50.App R commitments conducted Full compliance will be achieved by 840630 WILLIAMS.J W Florida Power & Light Co 83/12/20 D'REILLY, J P Region 2. Office of Director 2pp 22536 271 24X Fiche 50-389.83/12/20.8403070249
- 8403090280 Public version of Rev 13 to radiological emergency pian W/ 840124 ltr & JM Felton 840307 release memo WILLIAMB, J W Florida Power & Light Co 84/0i/04 D'REILLY, J P Region 2, Office of Director 227pp 22593 001 24X Fiche. 50-335, 84/01/04, 8403090280
- 8403040340 Revised emergency implementing plan procedures, including Procedures 2-0030140 re biackout operation, 2-0030143 re total loss of ac power, 2-0120042 re LOCA & 2-1010030 re ioss of instrument air H/840229 ltr SAGER, D. A. HETHY, C. N. Florida Power & Light Co. 84/01/23 App 22519 074 24X Flohe 50-335,84/01/23,8403040340
- 8403070140 Forwards IE Insp Repts 50-335/84-03 & 50-389/84-04 on 840118-20 No violations or deviations noted, DANCE, H C Division of Project & Resident Programs 84/02/13, WILLIAMS, J W Fiorida Power & Light Co. 2pp 22538 285 24X Fiche 50-335,84/02/13,8403070140
- --8403070145 IE Insp Repts 50-335/84-03 & 50-389/84-04 on 840118-20 No violations or deviations noted Major areas inspected samergency preparadness to assess on-shift prompt emergency classification & protective action recommendations BECKER, T R. Region 2, Office of Director 84/02/10 App 22538 287 24X Fichs 50-335.84/02/13,8403070140
- 8403190386 Rev 12 to Emergency Pien Implementing Procedure 3100024E, "Natural Emergencies" W/840307 ltr WILLIAMS, J W Florida Power & Light Co 84/02/29 O'REILLY, J, P Region 2, Office of Director 12pp 22675 270 24X Fiche: 50-335,84/02/29,8403190386
- 8403060186 Forwards safety parameter display sys implementation plan & parameter selection rept.per 830415 commitment Rept meets requirements of Generic Ltr 82-33 re Suppl 1 to NREG-0737 WILLIAMS, J W Florida Power & Light Co 84/03/01 EISENHUT, D G Division of Licensing itpp 22517 001 24X Fiche 50-389,84/03/01,8403060186
- 8403160254 Notifies of 840316 workshop to discuss 10CFR30.App R requirements & insp results to resolve misunderstandings refire protection Attendees should be limited to six due to size of conference room LEWIG.R C Division of Project & Resident Programs 84/03/02.WILLIMB.J W Floride Power & Light Co 1p 22660 255. 24X Fichs 50-000.84/03/02.8403160254.

- 8403270181 Expresses appreciation for cooperation throughout 10-month period of planning & developing faderal full field exercise Exercise provided planning focus & field experience for completing radiological emergency response planning G'REILLY, J P Region 2, Defice of Director 84/03/15 ADOMAT, E A Florida Power & Light Co 2pp 22802 208 24X Fiche 50-335,84/03/15,8403290181
- 8403290109 Ack receipt of 840309 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/83-43 & 50-389/83-71 DANCE: H C Division of Project & Resident Programs WILLIAMB: J W Florida Power & Light Co ip 2280; Fiche 50-335,84/03/19,8403290109 84/03/19 22807 001
- ---8403290126 Notice of violation from insp on 83i21i-840110 * Region 2, Office of Director 84/02/10 ip 22807 006 24X Fiche 50-335,84/03/19,8403290109
- --8403290132 IE insp Repts 50-335/83-49 & 50-389/83-71 on 831211-840110 Violation identified failure to maintain control room procedures in areas of administration, operation, emergency & off-normal.

 BIBB.H E Region 2, Office of Director 84/02/02/02/07 007 24X Fiche 50-335,84/03/19.8403290109 84/02/08 4pp

H General correspondence

- 8403280149 Responds to 840208 ltr requesting assistance in responding to J Paskavitch ltr requesting latest EIB on concentrations of Br-90, Cs-i37 & I-i3i near plants Two annual repts encl W/o resta B4/03/07 CHILES.L Senate 4pp 22809 316 24X
 Fiche'50-000,84/03/07,8403280149
- --8403280156 Forwards constituent J Paskavitch 1tr requesting latest EIS on concentrations of 8r-90.Cs-137 & I-131 near plants Comments & views requested
 CHILES, L Benate 84/02/08 KAMMERER, C Office of Congressional
 Affairs 8pp 22807 320 24X Fiche 50-000,84/03/07,8403280149

J Insurance & indemnity information

- B403060234 Forwards Endorsement 52 to NELIA Policy NF-227 DUCK, J. R. Marsh & McLennan, Inc. 84/02/28 BALTZMAN, J. Assistant Director for State & Licensee Relations 2pp 22517 315 24X Fiche: 50-335, 84/02/28, 8403060234
- P. Operating license stage documents & correspondence
- 8401130182 Suppl to 831222 application for amend to License NPF-16, changing Tech Specs for axial shape index to achieve consistency between Unit i & Unit 2 Tech Specs WILLIAMS.J.W. Florida Power & Light Co 84/01/10. EISENHUT, D Q Division of Licensing ip 21802 054 24X Fiche 50-389,84/01/10,840130382 B401130182
- 8401130319 Informs that redundant boron dilution sys alarm installed & declared operational on 840106, per 821029 % i104 ltrs & BBER 3. MILLIAMB, J W Florida Power & Light Co 84/01/10 EISENHUT, D Q Division of Licensing 1p 21798 305 24X Fiche. 50-389, 84/01/10, 8401130319.
- 8403010297 Application for amend to License NPF-16, modifying Tech Specs to delay initial inservice insp for two mechanical snubbers on containment spray sys until first refueing outage HILLIAMS. J W Florida Power & Light Co 84/02/24 EIBENHUT, D O Division of Licensing 3pp. 22432 107 24X Fiche 50-389,84/02/24,8403010297.
- --8403010302 Proposed Tech Specs re initial inservice insp of two mechanical snubbers on containment spray sys HILLIAMS.J W Filorida Power & Light Co 84/02/24 3pp. 22432.110, 24X Fiche 50-389.84/02/24,8403010297.
- 8403040077 Forwards Amends 62 & 5 to Licenses DPR-67 & NPF-16, 4030a00// Forwards Amends 62 & 5 to Licenses DPR-67 & NPF-16, respectively & safety evaluation. Amends change personnel titles & revise shift technical advisor function.

 SELLB, D. E. Operating Reactors Branch 3 84/02/24 WILLIAMS, J W Florida Power & Light Co. 2pp. 22549 020 24X

 Fiche: 50-335, 84/02/24, 8403060077.
- ~-8403060080 Amends 62 & 3 to Licenses DPR-67 & NPF-16, respectively, changing personnel titles & revising shift technical advisor functions
 MILLER, J. R. Operating Reactors Branch 3 84/02/24 12pp. MILLER, J. R Operating Reactors Branch 3 84/02 22549: 022. 24% Fichs. 50-335, 84/02/24, 8403060077

- ~-8403060527 Safety evaluation supporting Amends 62 % 5 to Licenses DPR-67 % NPF-16. respectively * Office of Nuclear Reactor Regulation, Director 84/02/24 2pp 22549 034 24% Fiche 50-335.84/02/24,8403060077
- 8403010400 Bubmits info re pressurizer heater transformer berrier design, per License Condition 2 C 9 Missile protection structure will be seismically anchored on concrete floor WILLIAMS, J W Florida Power & Light Co 84/02/27 EISENHUT, D Q Division of Licensing 3pp 22434 026 24% Fiche 50-387,84/02/27. 8403010400
- 840306024i Requests exemption from requirement to submit entirely reprinted & updated FSAR by 850406 Requests update be submitted as Amend 15 to arriginal FSAR MILLIAMS.J W Florida Power & Light Co 84/02/28 EISENHUT, D O Division of Licensing 1p 22515 190 24X Fiche 50-389,84/02/28,
- 8403060168 Notifies that administrative program & procedures now in effect will be reviewed to confirm implementation of recommended guidelines in NUTAC rept.per Generic Ltr 83-28 WILLIAMS, J C Florida Power & Light Co 84/03/01 EIBENHUT, D 9 Division of Licensing ip 22518 336 24% Fichs 50-000, 84/03/01, 8403060168
- 8403120040 Requests NRC approval of proposed license amend dtd 840224 by 840413, to permit initial visual insp of safety-related snubbers between 4 & 10 months after commencing power operation on 830413 WILLIAMS, J W Fiori WILLIAMS, J W Fiorida Power & Light Co B4/03/07 EISENHUT, D Q Division of Licensing ip 22590 318 24X Fiche, 50-389, 84/03/07, 8403120040
- 8403120087 Requests that environ protection plan study re evaluation &/ our mitigation of turtie entrapment at intake structure be presented during wk of 84040B Draft results expected by early Mar 1984 Rept will be discussed w/listed agencies WILLIAMS.J W Florida Power & Light Co 84/03/07 EISENHUT.D O Division of Licensing 2pp 22588 194 24X Fiche 50-389,84/03/07,8403120089
- 8403190150 Notifies of 840402-06 meeting & preimplementation audit at Turkey Point to discuss confirmatory items identified in safety evaluation of detailed control room design reviews for facilities VARQA:B A Operating Reactors Branch 1 84/03/07 WILLIAM, J W Florida Power & Light Co App 2268i 311 24X Fiche 50-000.84/03/07,8403190150
- 8403:30066 Advises that request to revise Tech Specs to provide requirements for overtime Ilmits & reporting of relief & safety vaive failures will be submitted per Oeneric Ltr B2-16 (NUREG-0737) by 8405:15 HILLIAMB.J W Florida Power & Light Co 84/03/08 MILLER.J R Operating Reactors Branch 3 1p 22401-252 24X Fiche 50-335,84/03/08.8403130066
- 8403270371 Requests appropriate fee to continue review of 830707 proposed changes to License Condition 2 C 7 re natural circulation cooldown & boron mixing test MILLER, W O License Fee Management Branch 84/03/12 UHR10,1 Florida Power & Light Co 1p 22787 330 24X Fiche 50-387, 84/03/12,8403270371 UHR10.R E
- 8403140013 Forwards "Evaluation of Natural Circulation Cooldown Test Performed at San Unofre Nuclear Generating Station " Rept provides evaluation of applicability of results to St Lucle Unit 2. WILLIAMB, J W Florida Power & Light Co 84/03/13 EIBENHUT, D Q Division of Licensing ip 22652 179 24% Fiche 50-000, 84/03/13, 8403140013
- 8403190227 Application to amend License NPF-16, changing Tech Specs to permit remarking of spent fuel pool to ensure sufficient storage capacity. Approval requested by 840901.
 WILLIAMB.J W Florida Power & Light Co 84/03/13 EISENHUT, D C Division of Licensing 3pp 22671 305 24X Fiche 50-389,88
- --8403190228 Proposed Tech Spec changes re remacking of spent fuel pool NBHC & BAR encl * Floride Power & Light Co 84/03/13 78pp. 22671 308 24X Fiche, 50-389, 84/03/13, 8403190227

- Q Inspection reports, 1E Bulletins & correspondence
- B403070249 Responds to NRC 83i123 ltr re violations noted in IE Insp Rept 50-389/83-57 Corrective actions detectors will be moved to ceiling Rereview of iOCFR50, App R commitments conducted Full compliance will be achieved by B40630 WILLIAMS.J W Florida Power & Light Co 83/12/20 O'REILLY.J P Ragion 2. Office of Director 2pp 22536 271 24X Fiche 50-389.83/12/20,8403070249
- 8403070140 Forwards IE Insp Repts 50-335/84-03 & 50-389/84-04 on B40118-20 No violations or deviations noted BANCE.H C Division of Project & Resident Programs 84/02/13 WILLIAMS.J W Florida Power & Light Co 2pp 22538 285 24X Fiche 50-335.84/02/13.8403070140
- --B403070145 iE Insp Repts 50-335/B4-03 & 50-3B9/B4-04 on B40118-20 No violations or deviations noted Major areas inspected emergency preparedness to assess on-shift prompt emergency classification & protective action recommendations DECKER.TR Region 2. Office of Director JENKING.GR Division of Emergency Preparedness & Materials Safety B4/02/10 4pp 22538 287 24X Fichs 50-335.84/02/13.8403070140
- B403160206 Forwards 1E Insp Repts 50-335/B4-04 & 50-389/B4-05 on 840201-03 No violations or deviations noted DANCE.H C Division of Project & Resident Programs 84/02/21 HILLIAMS.J W Fiorida Power & Light Co 2pp 22655 233 24X Fiche 50-335/84/02/21.8403160206
- ---B403160210 IE Insp Repts 50-335/84-04 & 50-389/84-05 on 840201-03 No violations or deviations noted Major areas inspected maint & surveillance observation.plant operations: preoperational testing, procedures & low power testing KRUO.H E Region 2. Office of Director JAPE.F Division of Engineering & Operational Programs 84/02/13 4pp 22655 235 24X Fiche 50-335.84/02/2i.8403160206
- B403010297 Application for amend to License NPF-16, modifying Tech Specs to delay initial inservice insp for two mechanical snubbers on containment spray say whili first refueing outage WILLIAMS. J W Fiorida Power & Light Co B4/02/24 EIBENHUT, D Q Division of Licensing 3pp 22432 107 24X Fiche 50-389.84/02/24, 8403010297
- --8403010302 Proposed Tech Specs re initial inservice insp of two mechanical snubbers on containment spray sys WILLIAMS. J H Fiorida Power & Light Co 84/02/24 3pp 22432 ii0 24X Fiche 50-387.84/02/24.8403010297
- B403i60264 Forwards IE Insp Repts 50-335/83-42 & 50-389/83-70 on B3ii0i-1210 No violations or deviations noted DANCE.H C Division of Project & Resident Programs B4/02/24 WILLIAMS.J W Fiorida Power & Light Co 2pp 22660 335 24X Fiche 50-335,84/02/24.8403160264
- --8403160268 IE Insp Repts 50-335/63-42 & 50-389/83-70 on 83iil1-1210 No violations or deviations noted. Major areas inspected maint & surveillance observation.plant operations, LERs & IE info notices
 BI88.H E Region 2, Office of Director ELROD, 8 A Division of
 - notices BIBB.H E Region 2, Office of Director ELROD, 8 A Division of Project & Resident Programs 84/02/23 10pp 22660 337 24X Fiche 50-335.84/02/24,8403160264
- 8401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enci JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22907 239 24X Fiche 50-000,84/02/28,8401190072
- 8403270317 Forwards IE Insp Repts 50-335/84-05 & 50-389/84-07 on 84020A-10 No violations or deviations noted DANCE,H C Division of Project & Resident Programs 84/02/29 WILLIAMS,J W Florida Project & Light Co 2pp 22802 052 24: Fiche 50-333.84/02/29,8403290317
- ~-8403290320 IE Insp Repts 50-335/84-05 & 50-389/84-07 on 840206-10 No violations or deviations noted Major areas inspected health physics instrumentation, action on NUREG-0737 items, ALARA activities & followup on previous items MRAY. J R Region 2. Office of Director BARR, K P Division of Englineering & Derational Programs 84/02/22 8pp 22802 054 24X Fiche 50-335,84/02/29,8403290317
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Reys by DOT & NRC " Byc list enc! GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 530103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000,84/03/02,8402090007

- 8402090008 iE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Bvc list ancl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of Naw York, Inc 122pp 22583 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090007 IE Info Notice 84-i5. "Reporting of Radiological Releases "
 Svc iist encl
 JORDAN, E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 117pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8403270174 Forwards 1E Insp Repts 50-335/84-02 & 50-389/84-03 on 840111-0210 No violations or deviations noted BANCE.H C Division of Project & Resident Programs 84/03/02 WILLIAMS,J W Fiche 50-335.840/34/02.8403900174
- --8403270iB0 JE Insp Repts 50-335/84-02 & 50-387/84-03 on 840111-0210 No violations or deviations noted Major areas inspected maint observation, surveillance observation, plant operations & TMI Action item III 8 4 2 B following.
 FEIERABEND.C., BIBB.H E Region 2, Office of Director ELROD, 8 A Division of Project & Resident Programs 84/01/02 2pp 22803 078 24X Fiche 50-335,84/03/02,8403270174
- 84020900ii iE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 82553 336 24X Fiche 30-000.84/03/05,8402090011
- B402090024 IE Info Notice 84-09, Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc iist enci JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co of New York Inc 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list enc! JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584 186 24X Fichs 50-000,84/03/07,8402090028
- 8403120040 Requests NRC approval of proposed license amend dtd 840224 by 840413, to permit initial visual insp of safety-related shubbers between 4 & 10 months after commencing power operation on 830613
 HILLIAMS, J W Fiorida Power & Light Co 84/03/07 EISENHUT, D Q Division of Licensing ip 22590 318 24X Fiche 50-389, 84/03/07, 8403120040
- 840207003i iE Builetin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consulidated Edison Co of New York. Inc 134pp 22823 074 24X Fiche 50-000.84/03/12.8402070031
- 8403270107 Ack receipt of 840307 itr informing NRC of steps taken to correct violations noted in 1E insp Repts 50-335/83-43 & 80-387/83-71
 DANCE:H C Division of Project & Resident Programs 84/03/17
 WILLIAMS, J W Florida Power & Light Co ip 22807 001 24X
 Fiche 50-335.84/03/19,8403270107
- --8403290ii4 Responds to NRC 840202 itr re violations noted in IE Insp Repts 50-335/83-43 & 50-389/83-7i Corrective actions, all indexes reviewed against master copies & procedures in control room verified against indexes WILLIAMS, J W Florids Power & Light Co 84/03/09, D'REILLY, J P Region 2, Office of Director 2pp 22807 002, 24X Fichs 50-335,84/03/19,8403290109
- --8403270124 Forwards IE Insp Repts 50-335/83-43 & 50-389/83-7; on 831211-840110 & notice of violation DANGE, H C Division of Project & Resident Programs 84/02/10, HILLIAHS, J W Florida Power & Light Co 2pp 22807 004 24X Fiche 50-335,84/03/19,8403290109
- --8403290126 Notice of violation from insp on 831211-840110
 * Region 2, Office of Director 84/02/10 ip 22807.006, 24X
 Fich* 50-335,84/03/19,8403290109
- --B403270132 IE Insp Repts 50-335/63-43 & 50-389/83-71 on 831211-840110 Violation identified failure to maintain control room procedures in areas of administration operation emergency & off-normal BIBB:HE. Region 2. Office of Director ELROD, 8 Division of Project & Resident Programs 84/02/08 4pp 22807 007 24X Fichs 50-335,84/03/19,8403290107

- 8402070043 IE Info Notice 84-19. "Two Events Involving Uneuthorized Entries into PNR Reactor Cavities" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24% Fiche 50-000,84/03/21,8402070043
- B402090044 IE Info Notice 84-20; "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consulidated Edison Co of New York, Inc 135pp 22933 001 24% Fiche 50-000.84/03/21.8402090044

R Pariodic operating reports & related correspondence

- 8403020033 Monthly operating repts for Jan 1984 W/840215 1tr ORANT,N W Florida Power & Light Co 84/01/31 17pp 22442 235 24X Fiche 50-000.84/01/31,8403020033
- 8403300173 Forwards monthly operating repts for Feb 1784 & corrected Page 1 of St Lucie Unit 2 monthly operating rept for Jan 1784
 HILLIAMS, J W Floride Power & Light Co 84/03/15 Office of Resource Henegement, Director 1p 22819·263 24X
 Fiche 50-000.84/03/15,8403300173
- --8403300185 Monthly operating rapts for Feb 1984 QRANT, N W Florida Power & Light Co 84/03/15 16pp 22819 264 24X Ficha 50-000,84/03/15,8403300173
- --8403300193 Corrected Page 1 of monthly operating rept for Jan 1984 GRANT, N. W Florida Power & Light Co 84/02/15 1p 22819 280 24X Fiche: 50-000, 84/03/15, 8403300173

B Reportable occurrences, LERs & related correspondence

- 8403210032 Pert 21 rept re feilure of auxiliary feedweter pump drive turbines. Gimpel NPB-4 T&T velve. to close. Encl Itr dtd 840203 sent to listed utils GE notified of affected units in BKR plants.

 THEROUX.R.R. Terry Corp 84/02/22. WOODRUFF.R W Director's Office. Office of Inspection and Enforcement App 22706 327 24X Fiche 50-000.84/02/22.8403210032
- 840302025B LER 84-003-00 on 840129, hi-hi steem generator level turbine trip occurred, resulting in reactor trip Caused by leakage through main feed reguleting valve A Reactor started & plent returned to svc W/84022B ltr.

 MALLING, 0 E , MILLIAMS, J W Floride Power & Light Co 84/02/28, 2pp. 22440 091 24X Fiche, 50-387, 84/02/28, 8403020258
- 8403060370 LER 84-002-00 on 840130, hydrogen anelyzer 28 & control room air conditioner MVA-3A unavaileble for mode changes as required by Tech Specs. Caused by improper review & recordkeeping Parsonnel reinstructed W/840301.1tr MCLAU9HLINL, WILLIAMS, J W Florida Power & Light Co 84/02/29 3pp. 22311 354. 24X Fiche 50-387,84/02/27,8403060390
- B403230028 Followup Part 21 rapt re nuclear valve/ectuetor stroking time possibly lengthened beyond 15 s when using hydrocarbon-based lubricents. Ltrs to affected utils encl. WILBON, A. K. Henry Pratt Co 64/03/08 KEPPLER, J 0 Region 3, Office of Director, 6pp 22790 306 24X Fiche 50-000, 84/03/08, 8403230028.
- 8403330035 LER 84-004-00 on 840209, while at 100% power, mein feedwater pump tripped due to low suction pressure. Cause not determined Auxiliery feedwater pump 2C tripped due to transients on power supply. Nut pin replaced W/840309 itr PARKS, B., Williams, J. W. Florida Power & Light Co. 84/03/09 2pp 22614 305 24% Fiche: 50-389, 84/03/09, 8403130035

V. Operator Examinations

8403080164 Forwards request for site visits to conduct operator licensing exams requested in Generic Ltr 83-40.
WILLIAMB, J W Florida Power & Light Co 84/03/01 EIBENHUT, D G Division of Licensing 5pp 22559.293 24X Fiche 50-335,84/03/01,8403080164

DOCKET 50-390 WATTE BAR NUCLEAR PLANT, UNIT 1

- A. Application/construction stage documents & correspondence
- 8403060534 Notification of 840315-16 meetings w/util in Sweetwater, TN to conduct confirmatory site visit per Section 13 6 of ERP (NUREO-0800).
 KENYON, T. J., Licensing Branch 4 84/02/28 ADENSAM, E Q Licensing Branch 4. 3pp 22552 317, 24X Fiche 30-390,84/02/28,8403060534

- 8403160247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rev 7 to topical QA program, per 840302 telcon

 LEWIS,R C Region 2. Office of Director 84/03/08 PARRIS,H Q

 Tennessee Valley Authority 1p 22660 361 24X

 Fiche 30-000,84/03/08,8403160247
- 8403160373 Notifies of use of ASME Nuclear Components Code Case N32-4 for hydrostatic testing of Class 3 embedded piping NRC position re use of Code Case N32-4 requested MILLB.L M Tennesses Valley Authority 84/03/12 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 22660 014 24 Fichs 50-000.84/03/12.8403160373
- 8403200225 Advises that similarity of Unit 1 & 2 175-ton poler crane verified by noting that cranes purchased under same contract w/same vendor.using identical procurement specs.ger NUREO-0612 & 840223 telcon MILLB.L M Tennessee Valley Authority 84/03/14 ADENSAM.E Licensing Dranch 4 2pp 22699 361 24X Fiche 50-390.84/03/14, 8403200225
- 8403260212 Forwards revised info re monorell paths, updating util 840206 ltr responding to Generic Ltr 81-07 concerning NUREO-0612, "Control of Meavy Loads at Nuclear Power Plants " Field investigation will be provided i month prior to fuel load MILLS,L M Tennessee Vailey Authority 84/03/20 ADENSAM,E Licensing Branch 4 2pp 22756 164 24X Fiche 50-390,84/03/20, 840320212
- B403260218 Forwards shift experience info.in response to Util Group on Operating Shift Experience request MILLS.L M Tennessee Valley Authority 84/03/20 DENYON.H R Office of Nuclear Reactor Regulation. Director 8pp 22754 091 24X Fiche 50-390.84/03/20.8403260218

E NRC Safety Evaluation Report (SER), supple & correspondence

- 8403080179 Fourth pertial response to FOIA request for six categories of documents re fectlities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, 6 I Garvey, Bchubert, Adams & Darer 7pp 22583 226 24X Fiche 50-000, 84/02/13, 8403080179.
- --8005130793 Provides status of SER inputs & acceptance reviews for DL & CP applications Schedule should be met BURKE.W C Effluent Treetment Systems Branch 80/02/06 KREGER,W E Assistant Director for Site Analysis ip 22583
- B403120179 Forwards info supporting util position that implementation of add1 insp criteria provides no add1 increese in safety.

 per BER (NUMEG-0847)

 MILLB.L M Tennesses Velley Authority B4/03/07 ADENSAM, E
 Licensing Branch 4 3pp 22590 205 24X Fiche 50-390, 84/03/07,
 B403120179
- 840330003B Forwards responses to NRC 840214-16 audit findings re util equipment qualification program per NUREO-0847 (SER) W/94 oversize drawings Aperbure cards are available in PDR MILL8.L.M Tennessee Valley Authority 84/03/20 ADENSAM.E Licensing Branch 4 138pp 22824 146 24X Fiche 50-390,84/03/20.8403300038
- 8403270218 Forwerds addl info re quelification of diesel generator auxiliary sys piping (SER Open Item 13), in response to NRC 840112 request, Diesel engine auxiliary sys acceptable, based on ODC i requirements MILLS, L. M. Tennessee Velley Authority 84/03/21 ADENBAM, E. Licensing Brench 4 6pp 22770 259 24% Fiche 50-390, 84/03/21, 840320218

F Escurity, medical, emergency & fire protection plans

- 8403070092 Submits second supplemental response to NRC ltr reviolations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 Corrective ections fire protection actions will be complete by 840131

 KAMMER, D S Tennesses Valley Authority 83/11/29 O'REILLY, J P Region 2, Office of Director ip 22541 219 24X

 Fichs: 50-390,83/11/29,8403070092
- 8402090380 Forwards Rav 2 to Procedure IP-10. "Medical Emergancy Procedure" & Rav 3 to radiological amargency plan MILLS.L M. Tennesses Vailey Authority 84/02/06 ADENSAM, E Licensing Branch 4 2pp 22161.136. 24X Fiche 50-390.84/02/06.8402090380

-)2090384 Rev 2 to Procedure (P-10, "Medical Emergency Procedure tillER,W A Tennessee Valley Authority 83/11/08 4pp 22:61 138 24X Fiche 50-390,84/02/06.8402090380
- J40235 Rev 5 to Procedure IP-9. "Muscle Shoals Emergency Ctr Jlementing Procedures Dacument " M/840213 ltr GMELL.R Tannessee Vailey Authority 84/02/13 63pp 22518 023 X Fiche 50-000.84/02/13.8403060235
-)20334 Forwards response to informal questions re calculation of tical temp gradients.per Radiological Emergency Planning nch request Backup procedures will be limited to times n radiological emergency program procedures activated L.B.L. M. Tennessee Valley Authority 84/02/27 ADENSAH.E :ensing Branch 4 4pp 22439 288 24X Fiche 50-390.84/02/27, 23020334
-)20236 Forwards Rev 4 to physical security plan Rev withheld f 10CFR73 21)
 LS.L H Tennessee Valley Authority 84/02/28 DENTON.H R ice of Nuclear Reactor Regulation, Director 1p 22440 041 24% the 50-390.84/02/28.8403020236
- 160147 Forwards revised effective pages to Knoxville Emergency Ctr. stral Emergency Control Ctr.Div of Nuclear Power Emergency & Muscle Shoals Emergency Control Ctr emergency pian itamenting procedures W/o Huscie Shoals pages
 L.S.L. M. Tennessee Valley Authority 84/02/28 0'REILLY, J.P. ion 2. Office of Director ip 22516 165 24X
 he 50-000.84/02/28.8403060147
- K3060163 Revised list of effective pages to Knozville Emergency Ctramergency plan implementing procedures
 Tennessee Valley Authority 84/02/06 8pp 22516 166 24% iche 30-000.84/02/28.8403060147
- 33060189 Revised list of effective pages to Central Emergency ontrol Ctr emergency pian amplementing procedures
 Tennessee Valley Authority B4/02/06 Bpp 22516 174 24X
 Fiche 50-000.84/02/28.8403060147
- M3060206 Revised list of effective pages to Div of Nuclear Power imergency Ctr emergency plan implementing procedures

 Tennessee Valley Authority 84/02/06 4pp 22516 182 24X
 Flohe 50-000.84/02/28.8403060147
- .60209 Ack receipt of 831230 ltr re emergency exercise scheduled June 1984 Scenario will be reviewed & any addi comments details of exercise will be made by telephone to B Marks (RELLI.D M Division of Project & Resident Frograms 84/03/02 RRIS.H G Tennessee Valley Authority ip 22655 232 24X the 50-390.84/03/02.8403160209
- .60345 Extends invitation to attend region B40316 workshop at ional ofc to discuss lOCFR50. App R requirements & recent rules of insp to help resolva misunderstandings associated requirements
 415.8 C Division of Project & Resident Programs 84/03/02
 415.8 C Division of Project & Resident Programs 84/03/02
 415.8 G Tennessee Valley Authority 2pp 22660 083 24X
 the 50-000:84/03/02.8403160345
- :60008 Forwards IE Insp Rept 50-390/84-17 on 840221-23 No stations or deviations identified RELLI,D M Division of Project & Resident Programs 84/03/13 RRIG.H G Tennessee Valley Authority 2pp 82655 171 24X the 50-390.84/03/13.8403160008
- 33160016 IE Insp Rept 50-390/B4-i7 on B40221-23 No violations ofted Major areas inspected implementation status of security plan commitments Details withheld (ref 10CFR2 790 73 21)

 OBJN.W Region 2. Office of Director McGUIRE, D.R. Division
- 73 217 OBIN.W Region 2: Office of Director MCGUIRE, D.R. Division of imargency Preparedness & Materials Safety 84/03/12 12655 173 24% Fiche 50-390;84/03/13,8403160008
- 170145 Rev 5 to radiological emergency plan updating agreement itr UE.correcting filing error for agreement itr W/Rhea inty Ambulance Svc W/840021 itr.
 LS.L M Tennassee Valley Authority 84/03/21 ADENSAM, E ensing Branch 4 11pp 22769 122 24X Fiche 50-390.84/03/21, 0270145
- surance & indemnity information
- 60277 Forwards Endorsement 25 to NELIA Policy NF-256
 K.J.R. Marsh & McLennan. Inc. 84/02/28 SALTZMAN, J. Assistant
 actor for State & Licensee Relations 2pp 22517 045
 24X
 he 50-390.84/02/28.8403060277

- Q Inspection reports, IE Bulletins & correspondence
- B403D70230 Supple response to NRC B20707 itr re violations noted in IE Insp Repts 30-370/82-16 & 50-371/82-15 Corrective actions operational GA evaluator resources increased by 50% MILLE, L Tennessee Valley Authority 83/09/09 O'REILLY, J P Region 2, Defice of Director 4pp 22541 304 24% Fiche 50-390,83/09/09,8603070230
- 8403070235 Supple response to NRC 820827 ltr re deviations noted in IE Insp Repts 50-390/82-28 & 50-391/82-26 Corrective actions piping drawings of reactor & auxiliary bidgs completed 830901
 MILLSIL M Tennessee Valley Authority 83/10/19 D'REILLY, J P Region 2. Office of Director 19 22541 309 24X Fiche 50-390.83/10/19.8403070235
- 8403070245 Supply response to NRC 821109 itr re violations noted in IE Imap Repts 50-390/82-05 & 50-391/82-03 Corrective actions will be completed by B31212 for Unit i & 840109 for Unit?

 MILLS.L. M. Tennessee Valley Authority B3/11/01 O'REILLY.J P. Region 2. Office of Director ip 22547 295 24X

 Fiche 50-390.83/11/01.8403070245
- 8403070092 Submits second supplemental response to NRC ltr reviolations noted in iE lnsp Repts 50-390/82-20 & 50-391/82-20 Corrective actions fire protection actions will be complete by 840131 KAMMER, D 8 Tennessee Valley Authority 83/11/29 O'REILLY, J P Region 2. Office of Director ip. 22541 219 24X Fiche 50-390.83/11/29.8403070092
- 8403160201 Forwards IE Insp Repts 50-390/84-04 & 50-391/84-04 on 840123-25 No violations or deviations identified VERRELLIPM M Division of Project & Resident Programs 84/02/14, PARRISH 6 Tennessee Valley Authority 2pp 22655 342 24X Fiche 50-390.84/02/14.8403160201
- --8403i60202 IE lasp Repts 50-390/84-04 & 50-391/84-04 on 840123-25 No violations or deviations identified Major areas inspected preoperational radiological affluent & environ monitoring programs.program mgt & administrative controls CUNNINGHAM.A L. Region 2. Office of Director MONTGOMERY, D M Division of Engineering & Operational Programs 84/02/10 5pp 22655 344 24% Fichs 50-390,84/02/14,8403160201
- 8403160214 Forwards IE insp Repts 50-390/83-36 & 50-391/83-44 on 831225-840120 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/02/1 PARRIS.H 0 Tennessee Valley Authority 2pp 22661 047. 24X Fiche 50-390.84/02/17.8403160214
- --B403160222 IE lnsp Repts 50-370/B3-56 & 50-371/B3-44 on B31225-B40120 No violation or deviations identified Major areas inspected, action on previous enforcement matters & insplictment followup on licensee identified items & verification of as-builts.

 SHYMLDCK.M B , BWAN.W B., HOLLAND.W E Region 2, Office of Director B4/02/16 9pp 22661 069 24X Fiche-50-370,84/02/17,8403160214
- B403160237 Forwards IE Insp Rept 50-390/84-09 on 840130-0203 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/02/27 PARRISH O Tennessee Valley Authority 2pp 22660 315 24X Fiche 50-390,84/02/27.8403160237
- --B403i40240 IE Insp Rept 50-390/B4-09 on B40130-0203 No violations or deviations noted Major areas inspected const status & as-built configuration for radioactive resin transfer sys & preoperational testing of radwaste sys.
 HDEEY,C M. Region 2. Office of Director BARR,K.P. Division of Engineering & Operational Programs 84/02/23 Bpp 22660,317
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl.

 JORDAN, E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22907 237 24% Fiche 50-000.84/02/28.8401190072
- 8403290201 Forwards iE Insp Repts 50-390/84-06 & 50-391/84-06 on BA0130-0203 No violations or deviations identified VERRELLID N Division of Project & Resident Programs 84/03/01. PARRIE, H G Tennessee Valley Authority 2pp 22803, 294 24X Fiche 50-390, 84/03/01, 8403290201

- --8403270207 IE insp Repts 50-370/84-06 & 30-371/84-06 on 840130-0203 No violations or deviations noted Major areas inspected preoperational test program test program implementation & licensee action on previous enforcement matters THOMAS, M Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 84/02/27 5pp 22803 276 24X Fiche 50-370,84/03/01,8403270201
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, JN Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp. 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 840209000B IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- B402090009 IE Info Notice B4-15, "Reporting of Radiological Releases " Evc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 119pp. 22553 217. 24X Fiche 50-000,84/03/02,8402090009
- B402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Coaling Components Below Nil Ductility Temp " Svc Ilst encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/05 Consolidated Edison Co of New York, Inc. 117pp 22583 336 24X Fiche 50-000,84/03/05,8402090011
- 8403160350 Ack receipt of 840222 ltr Informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/84-01 & 50-391/84-01 VERRELLI,D M Division of Project & Resident Programs. 84/03/05 PARRIS,H G. Tennessee Valley Authority, 1p 22660 166 24X Fiche 50-390,84/03/05,8403160350
- --8403160364 Responds to NRC 840123 ltr re violations noted in IE Insp Repts 50-370/84-01 & 50-371/84-01 Corrective actions deficiencies documented in Nonconformance Rept 5307 which require revork per design drawings & vendor catalogs MILLS.L M Tennessee Valley Authority 84/02/22 O'REILLY, J P Region 2. Office of Director. 3pp 22660 167 24X Fiche 50-370,84/03/05,8403160350
- --B403140374 Forwards IE Insp Repts 50-390/84-01 & 50-391/84-01 on B40103-06 & notice of violation VERRELLI.D M Division of Project & Resident Programs 84/01/23 PARRIS.H G Tennessee Valley Authority 2pp 22660 169 24X Fiche 50-390.84/03/09.8403160350
- --B403160378 Notice of violation from insp on B40103-06 # Region 2, Office of Director 84/01/19 ip 22660 171 24X Fiche 50-390,84/03/05.8403160350
- 8403290042 Forwards IE Insp Rept 50-390/84-10 on 840206-10 No violations or deviations noted VERRELLI, D M Division of Project & Resident Programs 84/03/06 PARRIES H O Tennessee Valley Authority 2pp 22806 252. 24X Fiche. 50-390, 84/03/06, 8403290042
- --B403270050 IE Insp Rept 50-390/B4-10 on B40206-10 No violations or deviations noted Major areas inspacted review of lab GC programm review of procedures & instructions, facilities, equipment & capability tests.

 TROUP. 0 L Region 2, Office of Director MONTGOMERY, D Division of Engineering & Operational Programs 84/02/27 iipp 22806:254 24X Fiche 50-390.84/03/04,8403270042
- 8402070024 IE Info Notice 84-07. Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JDRDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co. of New York, Inc 118pp 22635.049 24X Fiche. 30-000. 84/03/07. 8402070024
- B40209002B IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys," Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584-186 24X Fiche 30-000,84/03/07,8402090028

- 8402090031 IE Bulletin 84-02, "Failures of QE Type HFA Relays in Use Class IE Safety Bys " Svc list enc) DEYOUNG.R C Director's Dffice. Dffice of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8403160008 Forwards IE Insp Rept 50-370/84-17 on 840221-23 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/03/13 PARRIE,H G Tennessee Valley Authority 2pp 22655 171 24X Fiche 50-370,84/03/13,8403160008
- --8403160016 IE Insp Rept 50-390/84-17 on 840221-23 No violations noted Major areas inspected implementation status of security plan commitments Details withheld (ref 100FR2 790 to 73 21)
 TOBIN.W Region 2. Office of Director MCGUIRE, D.R. Division of Emergency Preparedness & Materials Safety 84/03/12 lp 22655 173 24X Fiche 50-390.84/03/13,8403160008
- 8403160271 Forwards IE Insp Rpsts 30-390/84-03 \$ 30-391/84-03 on 840117-20 & 24-27 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/03/15 PARRIS, H @ Tennessee Valley Authority 2pp 22660 351. 24X Fichs 50-390.84/03/15.8403160271
- --8403i60279 IE Insp Repts 50-390/84-03 & 50-391/84-03 on 840i17-20 & 24-27 No violations or deviations identified Major areas inspected independent insp effort & following in licensee identified items, unresolved litems & IE bulletins COLEY, J & Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 84/02/13 Bpp 22660 353 24X Fiche 50-390, 84/03/15, 8403160271
- B402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000.84/03/21.8402070043
- 8402090044 IE Info Notice 84-20. "Bvc Life of Relays in Bafety-Related Sys " Svc list enci JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21.8402090044
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS, W J Office of the Executive Director for Operations
 84/02/21 PALLADINO Commissioners 9pp 22492 083 24X
 Fiche 50~000.84/02/21.8403020443
- S Reportable occurrences. LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines.01mpel NPS-4 T&T valve.to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BWR plants.
 THEROUX.R R Terry Corp 84/02/22 HUGDRUFF,R W Director's Office. Office of Inspection and Enforcement 6pp 22706.327 24X Fiche 50-000.84/02/22.8403210032
- 8403010339 Second interim deficiency rept re environ qualification of mechancial equipment Initially reported on 831109 Condition not reportable per 100FR50 55(e) Next rept to be submitted by 840330 MILLS.L M. Tennessee Valley Authority 84/02/23 O'REILLY.J P Region 2. Office of Director 3pp 22432 321 24X Fiche 50-390.84/02/23.8402010339
- 8403070050 Final deficiency rept re live loads not considered in concrete partition wall design initially reported on 831213 Program established to determine walls requiring structural restraints Typical support drawings revised MILLS.L M Tennessee Valley Authority 84/02/28, O'REILLY, J P. Region 2, Office of Director 3pp 22575 360 24X Fiche.30-370,84/02/28,8403070050
- B403090206 First interim deficiency rept re improper design loads for base plates & anchor bolts initially reported on B40131 Two supports under evaluation using flexible plate analysis Next rept will be submitted by 840416 MILLS.L M Tennessee Valley Authority 84/02/28 O'REILLY,J P Region 2. Office of Director 2pp 22574 326 24X Fiche 50-390.84/02/28.8403090206

- 8403070174 Second interim deficiency rept re alteration of fire doors & frames w/o engineering design approval Initially reported on 84114 Altered fire-rated doors replaced or repaired Neit rept expected by 840413 MILLS.L M Tennessee Valley Authority 84/02/29 0'REILLY.J P Region 2. Office of Director 2pp 22538 349 24x Fiche 50-390.84/02/29.8403070174
- B403070286 Final deficiency rept re Parsons-Peebles emergency diesei generator 28-B rear bearing problem Initially reported on B30627 Generator repaired to be used as spare Aiso reported per Part 21 MELLS.L M Tennessee Vailey Authority 84/02/29 0'REILLY.J P Region 2. Dffice of Director 4pp 22346 224 24x Fiche 50-390.84/02/29.8403070286
- 8403150127 Final deficiency rept re temp of Class IE medium voitage cables in cable trays Initially reported on 840118 Conditions not reportable per 10CFR50 55(e) MILLS:L M Tennessee Valley Authority 84/03/05 O'REILLY.J P Region 2. Office of Director 2pp 22640 315 24X Fiche 50-390.84/03/05.8403150127
- 8403190034 Final deficiency rept re loading on diesel generator for LOCA & blackout causing unacceptable frequency transient Initially reported on 831107. Mods made to all four diesel generator load sequences increasing sequence time MILLS.L M Tennessee Valley Authority 84/03/08 0'REILLY, J P Region 2. Dffice of Director 3pp 22666 125 24X Fiche 30-390.84/03/08.8403190054
- 8403190099 Suppls info to 831017 final deficiency rept re supports not designed or modified as required by engineering change notice Initially reported on 830118 Design & subsequent const will be completed by 840517
 MILLS.L M Tennesses Valley Authority 84/03/08 O'REILLY, J P Region 2. Office of Director. 1p 22669 304 24X
 Fiche 50-370.84/03/08.8403190099
- 8403190358 First interim deficiency rept re installed supports not in agreement w/Mestinghouse requirements Initially reported on 840210 Pressurizer surge line support designs updated Invastigation in progress Next rept by 840420 MILLS.L M Tennessee Valley Authority 84/03/08 0'REILLY, J P Region 2. Office of Director 2pp 22473 310 24X Fichs 50-390.84/03/08.8403190358
- 6403210086 Final deficiency rept re fire damper fusible links Initially reported on 840214 All existing fusible links will be replaced w/higher temp fusible links that can withstand temps occurring during high energy line break MILLS.L M Tennessee Valley Authority 84/03/13 0'REILLY, J P Region 2. Office of Director 2pp 22705 087 24X Fishe 50-390,84/03/13,8403210086
- 8403210037 Final deficiency rept re operating conditions used in piping analysis initially reported on 820518 Pipe stresses for test runs within ASME Code aliowables Flanges notzles & supports qualified Documentation will be completed by 860131 MILLGL M Tennesses Valley Authority 84/03/15 O'REILLY, J P Region 2. Office of Director 6pp 22707 005 24x Fiche 50-390.84/03/15.8403210037
- 8403210066 First interim deficiency rept re Target Rock solenoid vaives on post-accident sampling facility not meeting backpressure requirements Initially reported on 840215 Engineering change notices being issued Next rept by 840423 MILLS.L M Tennessee Vailey Authority 84/03/15 D'REILLY.J P Region 2. Office of Director 2pp 22704 355 24X Fiche. 50-370.84/03/15.8403210066
- 8403300109 First interim deficienty rept re new defects in Barton pressure transmitters supplied by Wastinghouse initially reported on 840223 Wastinghouse will define corrective action by 840331 Also reportable under Part 21.

 MILLS,L M Tennessee Valley Authority 84/03/22 D'REILLY, J P Region 2. Defice of Director 2pp 22821 223 24x

 Fiche 50-390.84/03/22,8403300109

V Operator Examinations

8403260218 Forwards shift experience info, in response to Util Group on Operating Shift Experience request MILLS.L M Tennessee Valley Authority 84/03/20 DENTON, H R Office of Nuclear Reactor Regulation Director 8pp 22736 091 24X Fiche 50-370,84/03/20,8403260218

- DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8403060534 Notification of 840315-16 meetings w/util in Sweetwater.TN to conduct confirmatory site visit per Section 13 6 of BRP (NUREG-OBOO)
 KENYON,T J Licensing Branch 4 84/02/28 ADENSAM,E G Licensing Branch 4 3pp 22552
- 8403160247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rev 7 to topical GA program per 840302 teston LEHIB.R C Region 2. Office of Director 84/03/08 PARRIS.H G Tennessee Valley Authority 1p 22660 361 24X Fiche 50-000.84/03/08.8403160247
- 8403140373 Notifies of use of ASME Nuclear Components Code Case N32-4 for hydrostatic testing of Class 3 embedded piping NRC position re use of Code Case N32-4 requested MILLS,L M Tennessee Valley Authority 84/03/12 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 22460 014 24 Fiche 50-000.84/03/12.8403140373
- 8403200225 Advises that similarity of Unit I & 2 175-ton polar crane verified by noting that cranes purchased under same contract w/same vendor, using identical procurement specs, per NUREG-OA12 & 840223 telcon MILLS.L M Tennessee Valley Authority 84/03/14 ADENSAM.E Licensing Branch 4 2pp 22699 361 24X Fiche 30-390,84/03/14,8403200225
- 8403260212 Forwards revised into re monorail paths.updating util 840206 ltr responding to Generic Ltr 81-07 concerning NUREO-0612.
 "Control of Heavy Loads at Nuclear Fower Plants " Field investigation will be provided i month prior to fuel load MILLS.L M Tennessee Vailey Authority 84/03/20 ADENSAM.E Licensing Branch 4 2pp 22756 i64 24X Fiche 50-390.84/03/20.
- 8403260218 Forwards shift experience info, in response to Util Group on Operating Shift Experience request MILLS.L M Tennessee Vailey Authority 84/03/20 DENTON, H R Office of Nuclear Reactor Regulation. Director 8pp 22736 091 24X Fiche 50-390.84/03/20,8403260218
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403080177 Fourth partial response to FOIA request for six catagories of documents re facilities Forwards App A documents App B document entirely withheid (ref FOIA Exemption 5) Review of addi documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, B i Garvey, Schubert, Adams & Barer 7pp 22383 226 24X Fiche 30-000.84/02/13.8403080177
- --B005130793 Provides status of SER inputs & acceptance reviews for OL & CP applications Schedule should be mat BURKE, W C Effluent Treatment Systems Branch B0/02/06 KRECER, W E Assistant Director for Site Analysis ip 22583 235 24X Fiche 50-000,84/02/I3,8403080179
- B403120179 Forwards info supporting util position that implementation of addl insp criteria provides no addi increase in safety, per SER (NUREG-DR47)
 MILLS.L M Tennessee Valley Authority B4/03/07 ADENSAM.E Licensing Branch 4 3pp 22590 205 24X Fiche 50-390.84/03/07, B403120179
- 8403300038 Forwards responses to NRC 840214-16 audit findings re util equipment qualification programmer NUREQ-0847 (BER) W/84 oversite drawings Aperture cards are available in PDR MILLBIL M Tennessee Vailey Authority, 84/03/20 ADENSAM.E, Licensing Branch 4 138pp 22824 146 24X Fiche 50-370,84/03/20,8403300038
- 8403270218 Forwards add1 info re qualification of diesel generator auxiliary sys piping (SER Open Item 13), in response to NRC 840112 request Diesel engine auxiliary sys acceptable, based on ODC requirements
 MILLGIL M Tennessee Valley Authority 84/03/21 ADENBAM.E LIcensing Branch 4 6pp 22770 259 24X Fiche 50-390,84/03/21,8403270218

F Security, medical, emergency & fire protection plans

- B403070092 Submits second supplemental response to NRC ltr reviolations noted in IE Insp Repts 50-390/82-20 the S0-391/82-20 Corrective actions fire protection actions will be complete by B40131 KAMMER, D B Tennessee Vailey Authority B3/11/29 O'REILLY, J P Region 2, Dffice of Director 1p 22541 219 24X Fiche 50-390,83/11/29,8403070092
- 8402090380 Forwards Rev 2 to Procedure 1P-10, "Medical Emergency Procedure" & Rev 3 to radiological emergency plan MILLS.L M Tennessee Valley Authority 84/02/06 ADENSAM.E Lifensing Branch 4 2pp 22161 136 24X Fiche 50-390,84/02/06, 8402090380
- --8402090384 Rev 2 to Procedure IP-10. "Medical Emergency Procedure "
 MILLER, W A Tennessee Valley Authority 83/11/08 4pp
 22161 (38 24X Fiche 50-390, 84/02/06, 8402090380
- 8403040235 Rev 5 to Procedure IP-9, "Muscle Shoals Emergency Ctr Implementing Procedures Document " W/840213 1tr MAXWELL.R Tennesses Valley Authority 84/02/13 63pp. 22518 023 24X Fiche 50-000, 84/02/13, 8403050235
- 8403020334 Forwards response to informal questions re calculation of vertical temp gradients, per Radiological Emergency Planning Branch raquest Backup procedures will be limited to times when radiological emergency program procedures activated, MILLS, L M Tennessee Valley Authority 84/02/27 ADENSAM.E Licensing Branch 4 4pp. 22439 288 24X Fiche 50-390,84/02/27. 8403020334
- 8403020236 Forwards Rev 4 to physical security plan Rev withheld (ref 10CFR73 21) MILLS.L M Tennessee Valley Authority 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22440 041 24) Fiche 50-390.84/02/28.8403020236
- 8403060147 Forwards revised effective pages to Knoxville Emergency Ctr. Central Emergency Control Ctr.Div of Nuclear Power Emergency Gtr & Muscle Shoals Emergency Control Ctr emergency plan implementing procedures W/o Muscle Shoals pages MILLS, L M Tennessee Valley Authority 84/02/28 O'REILLY, J P Region 2. Office of Director 1p 22516 165 24X Fiche 50-000, 84/02/28, 8403060147
- --2403060163 Revised list of effective pages to Knozviile Emergency Ctremempency plan implementing procedures a Tennessee Valley Authority 84/02/06 8pp 22516 166 24X Fiche 30-000,84/02/28,8403060147
- --8403060189 Revised list of effective pages to Central Emergency Control Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 8pp 22516 174 24X Fiche 50-000,84/02/28,8403060147
- --8403060206 Revised list of effective pages to Div of Nuclear Power Emergency Ctr emergency plan implementing procedures # Tennessee Valley Authority 84/02/06 4pp 22516.182 24X Fiche 50-000,84/02/28.8403060147
- 8403160209 Ack receipt of 831230 itr re emergency exercise acheduled for June 1984 Scenario will be reviewed & any add1 comments on datails of exercise will be made by telephone to B Marks VERRELLI,D M Division of Project & Resident Programs 84/03/02 PARRIB:H 0 Tennesses Valley Authority 1p 22655:232 24X Fiche: 50-390, 84/03/02, 8403160209
- B403160345 Extends invitation to attend region 840316 workshop at regional ofc to discuss 100FR50.App R requirements & recent results of insp to help resolve misunderstandings associated w/requirements

 LEMIBLE C Division of Project & Resident Programs 84/03/02 PARRIS, H 9 Tennessee Valley Authority 2pp 22660 083 24X Fiche. 50-000.84/03/02.8403160345
- B403270145 Rev 5 to radiological emergency plan updating agraement 1tr w/DDE, correcting filing error for agreement 1tr w/Rhea County Ambulance Svc W/B40321 ltr.
 MILLS/L M Tennessee Valley Authority B4/03/21 ADENSAM, E. Licensing Branch 4, 11pp 22767 122 24X Fiche 50-390, B4/03/21, B403270145

J Insurance & indemnity information

B4030A0277 Forwards Endorsement 25 to NELIA Policy NF-256
BUCK,J R Marsh & McLennan, Inc 84/02/28 SALTZMAN,J Assistant
Director for State & Licenses Relations 2pp 22517 045
Fichs 30-390,84/02/28,84030A0277

- O inspection reports. IE Builetins & correspondence
- 8403070230 Suppls response to NRC 820707 ltr re violations noted in IE Insp Repts 50~390/82-18 & 50~391/82-15 Corrective actions operational QA evaluator resources increased by 50% MILLS:L M Tennessee Valley Authority 83/09/09 0'ÆILLY.J P Region 2. Office of Director 4pp 22541 304 24% Fiche 50~390.83/09/09.8403070230
- 840:3070239 Supple response to NRC 820827 ltr re deviations noted in IF Insp Repts 50-390/82-29 & 50-391/82-26 Corrective actions plping drawings of reactor to availiary bldgs completed 830701 MILLS.L M Tennessee Valley Authority 83/10/19 O'REILLY.J P Region 2. Office of Director ip 22541 309 24X Fiche 50-390.83/10/19.8403070235
- B403070245 Supple response to NRC 821109 ltr re violations noted in IE Insp Repts 50-390/82-05 & 50-391/82-03 Corrective actions will be completed by 831212 for Unit 1 & 840109 for Unit 2
 MILLB.L M Tennessee Valley Authority B3/11/01 O'REILLY, J P Region 2, Office of Director ip 2547 295 24X
 Fiche 50-390.83/11/01.8403070245
- 8403070092 Submits second supplemental response to NRC ltr reviolations noted in IE lmsp Repts 50-390/82-20 & 50-391/82-20 Corrective actions fire protection actions will be complete by 840131 KAMMER. D S Tennessee Valley Authority 83/11/29 O'REILLY, J P Region 2. Office of Director 19 22541 219 24X Fiche 50-390.83/11/29,8403070092
- B403160201 Forwards IE Insp Repts 50-390/84-04 & 50-391/84-04 on B40123-25 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/02/14 PARRIS.H G Tennessee Valley Authority 2pp 22655 342 24% Fiche 50-390.84/02/14.8403160201
- --8403160202 IE Insp Repts 50-370/84-04 & 50-371/84-04 on 840123-25 No violations or deviations identified Major areas inspected preoperational radiological effluent & environ monitoring programs: program mpt & administrative controls CUNNINGHAM: A L. Region 2. Office of Director MONTGDMERY.D M Division of Engineering & Operational Programs 84/02/10 5pp 22655 344 24X Fiche 50-370,84/02/14,8403160201
- 8403160214 Forwards 1E Insp Repts 50-390/B3-56 & 50-391/B3-44 on B31225-B40120 No violations or deviations identified VERRELLI,D M Bivision of Project & Resident Programs B4/02/17 PARRISH 0 Tennessee Valley Authority 2pp 22661 067 24X Fiche 50-390,84/02/17,8403160214
- --B403160222 IE insp Repts 50-390/83-56 & 50-391/83-44 on B31225-B40120
 No violation or deviations identified Major areas inspected action on previous enforcement matters & insp items, followup on licensee identified items & verification of as-builts BHYMLOCK.M B . SHAN, W B . HOLLAND.W E . Region 2. Office of Director B4/02/16 9pp 22661 069 24% Fiche 50-390,84/02/17. B403160214
- 8401170072 IE info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22907 237 24% Fiche 50-000,84/02/28,8401190072
- 8403270201 Forwards IE Insp Repts 50-370/84-06 & 30-371/84-06 on 840130-0203 No violations or deviations identified VERRELLI,D M Division of Project & Resident Programs 84/03/01 PARRIB,H O Tennessee Valley Authority 2pp 22803 274 24X Fiche 50-370,84/03/01,8403270201
- --8403270207 IE Insp Repts 50-390/84-06 & 50-391/84-06 on 840130-0203 No violations or deviations noted Major areas inspected prespectional test program, test program implementation & licensee action on previous enforcement matters THOMAS, M. Region 2. Office of Director JAPE, F. Division of Engineering & Operational Programs 84/02/27 Spp 22803 296 24X Fiche 50-390,84/03/01,8403270201
- B402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of QA, Safeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327. 24X Fiche 50-000,84/03/02,8402090007
- B402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering R#sponse (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc. 122pp 22533 098 24X Fiche 50-000,84/03/02.8402090008

- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fichs 50-000,84/03/02,8402090009
- B40209001i iE lnfo Notice B4-i7. "Problems W/Liquid Nitrogen Cooling Companents Below Nil Ductility Temp " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403160350 Ack receipt of 840222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/84-01 & 50-391/84-01 VERRELLI, D.M. Division of Project & Resident Programs 84/02/05

WERRELLI.D M Division of Project & Resident Programs 64/03/05 PARRIE, H 0 Tennessee Valing Authority ip 22660 i66 24X Fiche, 50-390, 84/03/05, 8403i60350

- --8403160364 Responds to NRC 840123 ltr re violations noted in IE Insp Repts 50-390/84-01 & 50-391/84-01 Corrective actions deficiencies documented in Nonconformance Rept 5307 which require rework per design drawings & vendor catalogs MILLB-L M Tennesses Valley Authority 84/02/22 O'REILLY, J P Region 2. Office of Director 3pp. 22860 167 24X Fiche 50-390,84/03/05,8403160350
- --B403i60374 Forwards IE Insp Repts 50-390/84-01 & 50-391/84-01 on 840103-06 & natice of violation VERRELLI.D M Division of Project & Resident Programs 84/01/23 PARIS.H 0 Tennessee Valley Authority 2pp 22660 169 24X Fich
- --B403160378 Notice of violation from insp on 840103-06 * Regian 2, Office of Director B4/01/19 ip 22660 171 24X Fithe 50-390,84/03/05,8403160350
- --8403i60383 IE lnsp Repts 50-370/84-01 & 50-37i/84-01 on 840103-06 Violation noted failure to follow procedures for hanger insp LTU,W C Region 2, Office of Director BLAKE,J J Division of Engineering & Operational Programs 84/01/19 5pp 22660 172 24X Fiche 30-370,84/03/05,8403160350
- 8402070024 IE Info Notice 84-07. Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 18pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- B4D2070028 IE Info Notice B4-18, "Stress Corrosion Cracking in PWR Bys " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/07 Consolidated Edison Co of New York, Inc 118pp 223B4 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulistin 84-02, "Failures of QE Type HFA Relays in Use in Class IE Safety Sys " Svc iist enc!
 DEYOUND, R C Director's Dffice. Dffice of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823, 094 24X Fichs 50-000.84/03/12, 8402090031
- 8403150271 Forwards IE Insp Rpets 50-390/84-03 & 50-391/84-03 on 840117-20 & 24-27 No violations or deviations identified VERRELLI-D N Division of Project & Resident Programs 84/03/15 PARRISH O Tempesses Valley Authority 2pp 22660 351 24X Fiche 50-390.84/03/15.840316027i
- --8403160279 IE Insp Repts 50-390/84-03 & 50-391/84-03 on 840117-20 & 24-27 No violations or deviations identified Major areas inspected independent insp effort & followup on licensee identified items, unreasolved items & IE bulisting COLEY, JL Region 2. Office of Director BLAKE, J J Division of Engineering & Derational Programs 84/02/13 8pp 22660-353 24X Fiche 50-390, 84/03/15, 8403160271
- 8402070043 IE lnfo Notice 84-19. "Two Events Involving Unauthorized Entries anto PWR Reactor Cavities " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp. 22823 227 24X Fiche. 50-000, 84/03/21, 8402070043
- B402070044 IE Info Notice B4-20. "Svc Life of Relays in Safety-Related Sys " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp. 22932 001 24X Fiche 50-000.84/03/21.8402070044

- 8 Reportable occurrences, LERs & related correspondence
- 8403210032 Part 21 rept re failurs of auxiliary feedwater pump drive turbines, Oimpsi NPS-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BMR plants
 THEROUX, R R Terry Corp 84/02/22 WOODRUFF, R W Director's Office, Office of Inspection and Enforcement 6pp 22706 327, 24X Fichs 50-000,84/02/22,8403210032
- 8403010339 Second interim deficiency mept me environ qualification of mechancial equipment initially reported on 831109 Condition not reportable per iOCFRSO 35(e) Next mept to be submitted by 840330.
 MILLS.L M Tennessee Valley Authority 84/02/23 O'REILLY, J P Region 2: Office of Director 3pp 22432 321 24X Fiche 50-390,84/02/23,8403010339
- 8403090050 Final deficiency maptime live loads not considered in concrete partition wall design Initially reported on 831213 Program satabilished to determine walls requiring structural restraints Typical support drawings revised.

 MILLS.L M Tennesses Valley Authority 84/02/28 O'REILLY, J. P. Region 2. Office of Director 3pp 22575 360 24X
 Fichs 50-390, 84/02/29, 8403090050
- 8403090206 First interim deficiency rept re improper design loads for base plates & anchor bolts Initially reported on 840131 Two supports under evaluation using flexible plate analysis. Next rept will be submitted by 840416
 MILLS.L M Tennesses Valley Authority 84/02/28 O'REILLY, J P Region P. Office of Director 2pp 22574 326 24X
 Fichs 30-390.84/02/28.8403090206
- 8403070174 Second interim deficiency rept re alteration of fire doors & frames w/o engineering design approval Initially reported on B41114 Altered fire-rated doors replaced or repaired Next rept expected by 840413 MILLB.L M Tennessee Valley Authority B4/02/29 O'REILLY, J P Region 2, Office of Director 2pp 2238 349 24X Fichs 50-390.84/02/29.8403070174
- 8403070286 Final deficiency rept re Parsons-Peebles emergency diesel generator 28-8 rear bearing problem Initially reported on 830627 Generator repaired to be used as spare Also reported per Part 2i MILLS.L M Tennessee Valley Authority 84/02/29 D'REILLY.J P Region 2. Office of Director 4pp 22546.224 24X Fiche 50-390.84/02/29.8403070286
- 8403i50i27 Final deficiency rept re temp of Clast IE medium voltage cables in cable trays Initially reported on 840iiB Conditions not reportable per IOCFR50 55(s) MILLB.L M Tennesses Valies Authority 84/03/05. O'REILLY, J P Region 2, Office of Director 2pp 22640 315 24X Fiche 50-390,84/03/05,8403150i27
- 8403i90054 Final deficiency rept re loading on diesel generator for LOCA & blackout causing unecceptable frequency transient. Initially reported on 831i07, Mods made to all four diesel generator ioad sequences increasing sequence time MILLS.L M Tennessee Valley Authority 84/03/08 O'REILLY, J P Region P. 0ffice of Director 3pp 22666 125 24X Fiche 50-390.84/03/08.8403i90054
- 8403190358 First interim deficiency rept re instelled supports not in agreement w/Mestinghouse requirements Initially reported on 840210 Pressurizer surge line support designs updated Investigation in progress Next rept by 840420 MILLS.L N Tennesse Valiey Authority 84/03/08 0'REILLY, J P Region 2, Office of Director 2pp 22673 310, 24X Fichs 50-390,84/03/08,8403190358
- 8403210086 Final deficiency rept re fire damper fueible links Initially reported on 840214 All existing fueible links will be replaced whigher temp fueible links that can withstand temps occurring during high energy line break.

 MILLS.L M Tennesse Vallsy Authority. 84/03/13 O'REILLY.J P. Region 2. Office of Director. 2pp 22705 087 24X

 Fichs 50-390.84/03/13.8403210086
- 8403210037 Final deficiency rept re operating conditions used in piping analysis initially reported on 820518, Pipe stresses for test runs within ASME Code allowables Flanges, nozzles & supports qualified Documentation will be completed by 840131 MILLB.L M Tennesse Valley Authority 84/03/15 O'REILLY.J P Region 2. Office of Director 4pp 22707 005, 24% Fichs.50-390.84/03/15,8403210037

- B403210066 First interim deficiency rept re Target Rock solenoid valves on post-accident sempling facility not meeting beckpressure requirements Initially reported on B40215 Engineering change notices being issued Next rept by B40423
 MILLB.L M Tennessee Valley Authority 84/03/15 D'REILLY, J P Region 2, Office of Director 2pp 22704 355 24X
 Fiche 50-390.84/03/15,8403210066
- 8403300109 First interim deficiency rept re new defects in Barton pressure transmitters supplied by Westinghouse Initially reported on 840223 Westinghouse will define corrective action by 840331 Also reportable under Part 2: MILLB:L M Tennessee Valley Authority 84/03/22 O'REILLY, J P. Region 2. Office of Director 2pp 2282; 223 24X Fiche, 50-390, 84/03/22, 8403300109

V. Operator Examinations

- 8403260218 Forwards shift experience info.in response to Util Group on Operating Shift Experience request MILLELL M Tennessee Valley Authority 84/03/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 22756 091 24X Fiche.50-390,84/03/20,8403260218
- DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1 F. Security, medical, emergency & fire protection plans
- B403130377 Rev 10 to Emergency Plan Procedure EPP-002, "Communication & Notifications," W/840308 ltr & revised table of contents COUNTB.M., BRADHAM.O B., DIXON.O W. Bouth Cerolina Electric & Gas. Co., B4/02/03 DENTON.H R. Office of Nucleer Reactor Regulation, Director 40pp 22616 005 24X Fiche 50-395,84/02/03,8403130397
- 8403070085 Forwards IE Insp Rept 50-375/84-03 on 840110-13 No Violations or deviations noted,
 VERRELLI, D. M. Division of Project & Resident Programs. 84/02/07
 DIXON. D W South Carolina Electric & Gas Co 2pp 22541 210 24x Fiche 50-395,84/02/07,8403070085
- --8403070088 IE Insp Rept 50-395/84-03 on 840110-13 No violations or devictions noted Mejor creas inspected operational safety verification, maint & surveillance activities, physical protection. Tech Spec compliance & LER followup IGNATUNIS.A. J. Region 2. Office of Director CANTRELL.F S Division of Project & Resident Programs 84/02/06 7pp 22541 212 24X Fiche 50-395.84/02/07,8403070085
- B403070007 Forwards IE Insp Rept 50-395/84-02 on 840114-20 No violations or deviations identified VERRELLI.D.M Division of Project & Resident Programs 84/02, DIXON,W.O Bouth Carolina Electric & Que Co 2pp. 22547 337 Fiche 50-395,84/02/10,8403070007
- --B403070013 IE Insp Rept 50-395/B4-02 on B40116-20 No violetions or deviations identified Major areas inspected emergency preparedness
 STODDART,P Q , KREN,J L , JENKINS,Q.R Region 2. Office of Director B4/02/09 Bpp 22547 339 24X Fiche 50-395,84/02/10,8403070007
- B403160276 Notifies of B40316 workshop to discuss lOCFR50,App R requirements for fire protection results of recent App R insp to help resolve eny misunderstandings associated
- LEWISIR C Division of Project & Resident Programs. 84/03/02 DIXON,O W South Carolina Electric & Gas Co ip 22660 079. 24x Fiche, 50-395, 84/03/02, 8403160296
- I Insurence & indemnity information
- 3403140015 Forwards Endorsement 3: to NELIA Policy NF-252 HOFFMAN.J Marsh & McLennan, Inc. 84/03/06 DINITZ.I Assistant Director for State & Licensee Relations 2pp 22620 167 24X Fiche:50-395,84/03/06,8403140015
- . Operating license stage documents & correspondence
- A03020297 Advises that util plans to follow general guidelines set forth by equipment vendor Technical info program rept, providing program description required by Section 2 2 2 of Generic Ltr 83-28, will be provided by 840430
 DIXON.O W. South Cerolina Electric & Gas Co. 84/02/29, DENTON, H R Office of Nuclear Recotor Regulation, Director 2pp 22440; 064 24X Fiche 50-395,84/02/29,8403020297.

- 8403060128 Application for amend to License NPF-12 revising Tech Spec requirement to rept new cracks of svc water intake DENTON, H R
 - structure DIXON,O W Gouth Carolina Electric & Gas Co° 84/02/29 DENTON,E Office of Nuclear Reactor Regulation, Director 2pp 22518 302 24X Fiche 50-395,84/02/29,8403060128
- --8403060130 Proposed Tech Spec.changing monitoring program on stability of west embankment & effects on intake structure

 * Bouth Carolina Electric & Gas Co 84/02/29 ip 22518 304
 24X Fichs 50-395,84/02/29,8403060128
- 8403220101 Notification of 840313 meeting w/util in Bethesde, MD to discuss 840123 spent fuel pool rerack submittal HOPKINS, J B Licensing Branch 4 84/03/02 ADENSAM, E. G. Licensing Branch 4 3pp 22723 275 24X Fiche 50-395,84/03/02,8403220101
- B403090R71 Submits add1 info re high density spent fuel storage racks, per 840217 request Combination of matls in support leg highly resistant to galling & provide desirable matl properties for boric acid environs
 DIXON.OW South Carolina Electric & Ges Co 84/03/06 DENTON.H R
 Office of Nucleer Reactor Regulation, Director 3pp 22574 165
 24X Fiche 30-395,84/03/06.8403090271
- 8403270183 Forwards portion of combustible gas control Tech Spec surveillance requirement inadvertently omitted from util 840118 response to Generic Ltr 83-37, "NUREG-0737 Tech
- Section Temporary to Carolina Electric & Gas Co 84/03/22 DENTON, Police of Nuclear Reactor Regulation, Director 2pp 22771 123 24X Fiche 50-375,84/03/22,8403270183 DENTON, H R
- --8403270188 Proposed change to Tech Spec 4 6 5 i re combustible ges control hydrogen monitors * Bouth Carolina Electric & Gas Co 84/03/22 ip 22771 125 24X Fiche 50-395,84/03/22,8403270183
- 8403270223 Application for amend to License NPF-12 requesting rev to Tech Spec Table 3 8-2, "Motor Operated Valves Thermal Overload Protection &/or Bypass Devices "
 DIXON, D W South Caroline Electric & Qas Co 84/03/22 DENTON, H
 Office of Nuclear Reactor Regulation, Director 2pp 22770 265
 24X Fiche 50-375,84/03/22,8403270223
- -8403270225 Proposed Tech Spec rev to Table 3 8-2, "Motor Opereted Valves Thermal Overload Protection &/or Bypess Devices "

 * Bouth Caroline Electric & Gas Co. 84/03/22 2pp 22770 267 24% Fiche 50-375,84/03/22,8403270223
- G. Inspection reports, IE Bulletins & correspondence
- 8403070040 Submits followup rept re violation addressed in IE Insp Rept 50-393/83-01.detailing progress & completion schedule on development of mester cross-reference program for identification of Tech Spec components
 DIXON.O W Bouth Carolina Electric & Gas Co B3/09/15
 D'REILLY.J P Region 2, Office of Director 2pp 22541 260 24X
 Fiche 50-395,83/09/15,8403070040
- 8403070085 Forwards IE Insp Rept 50-395/84-03 on 840110-13 No violetions or devietions noted. VERRELLI.D M Division of Project & Resident Programs 84/02/ DIXON.D W Bouth Cerolina Electric & Oas Co 2pp 22541 210 Fiche 50-395.84/02/07.8403070085
- --B403070088 IE Insp Rept 50-395/84-03 on B40110-13 No violetions or devietions noted Major erees inspected operationel safety verification, maint & surveillance activities, physical protection, Tech Spec compliance & LER followup IGNATONIS, A J Region 2. Office of Director CANTRELL, F B Division of Project & Resident Programs 84/02/06 7pp 22541.212 24X Fiche 50-395,84/02/07,8403070085
- 8403070007 Forwerds IE Insp Rept 50-395/84-02 on 840116-20 No violations or deviations identified VERRELLI.D H Division of Project & Resident Progrems 84/02/10 DIXON/W O South Carolina Electric & Oas Co 2pp 22547 337, 24X Fiche 50-395/84/02/10/8403070007
- --8403070013 IE Insp Rept 50-375/84-02 on 840116-20 No violations or deviations identified Major arees inspected emergency preparedness STODDART.P g , KREN.J L , JENKINS.O.R. Region 2, Office of Director 84/02/09 8pp 22547 339 24X Fiche 50-395,84/02/10, 8403070007
- 8403160305 Forwards IE Insp Rept 50-395/84-01 on 840116-19 No violations or deviations noted

 VERRELLI,D M Division of Project & Resident Programs 84/02/15

 DIXON,O W South Carolina Electric & Gas Co 2pp 22660 066, 24X

 Fiche 50-393.84/02/15,8403160305

- --8403160309 lE lnsp Rept 50-395/84-0i on 840116-19 No violations or deviations noted Major areas inspected lab GC program, chemical & radiochemical procedures, airborne effluent sampling methodology & results of split samples KUZO. 8 B . TROUP.0 L Region 2, Office of Director MONTOOMERY, D H Davision of Engineering & Operational Programs 94/02/13 [ipp 22660 068 24% Fithe 50-395,84/02/15,8403160305
- 8403070125 Ack receipt of 840110 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Rept 50-395/83-38 LEMIS.R C Division of Project & Resident Programs 84/02/24 DIXON.O W South Carolina Electric & Gas Co lp 22538 214 24X Fiche 50-395,84/02/24.8403070125
- --8403070129 Responds to NRC 840111 ltr re violations noted in IE Insp. Rept 50-395/83-38 Corrective actions testing satisfactorily performed on both diesel generator breakers while escalating in Mode 2 Valves LCV-115 B & D satisfactorily tested DIXON, O W South Carolina Electric & Gas Co 84/01/10 O'REILLY, J P. Region 2. Office of Director 5pp 22538 215 24X Fiche 50-395,84/02/24,8403070125
- --8403070131 Forwards 1E Insp Rept 50-395/83-38 on 831212-15 & notice of violation
 LEWIS,R C Division of Praject & Resident Programs 84/01/11
 DIXON.O W South Carolina Electric & Gas Co 2pp 22838 220
 24X Fiche 50-395.84/02/24.8403070125
- --8403070133 Notice of violation from insp on 831212-15 + Region 2, Office of Director 84/01/11 ip 22538 222 24X Fiche 50-375.84702/24.8403070125
- --8403070136 IE Insp Rept 50-395/83-38 on 831212-15 Noncompliance noted failure to perform slave relay to actuated device continuity tests & operational modes changed w/diesel generators inoperable BUTCHER.R C , HEH., C W Region 2, Office of Director CANTRELL.F S Division of Project & Resident Programs 84/01/10 8pp 22538 223 24X Fiche 50-395,84/02/24,8403070125
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000.84/02/28,8401190072
- 8402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list enc! GRACE, J N Division of GA: Safeguards & Inspection Programs (Post 830103) 84/03/02 Conspillated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000:84/03/02.8402090007
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post #30103) 84/03/02 Consolidated Edison Co of New York. Inc 122pp 2253 098 24X Fiche 50-000,84/03/02.8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list enc)
 JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090Dil 1E Info Notice 84-17, "Problems H/Liquid Nitrogen Cooling Components Below Nil Ductility Temp" Svc list encl JURDANIE 1. Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/05 Consolidated Edison Co of New York: Inc 117pp 22553 336 24X Fiche 50-000, 84/03/05, 840209001;
- 8402070024 IE info Notice 84-07.Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24X Fichs 50-000,84/03/07,8402070024
- 840209002B IE Info Notice 84-18, "Btress Corrosion Cracking in PWR Sys " 5vc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York: Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8402090031 IE Bulletin 84-02, "Failures of QE Type HFA Relays in Use in Class IE Safety Sys " Syr list enc! DEYDUNO,R C Director's Office, Office of Inspection end Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp R2883 094 24% Fiche 50-000,84/03/12,8402090031

- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 227 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list enc! JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403020039 Monthly operating rept for Jan 1984 W/840213 ltr LDIGNDN.G A . DIXON.D W South Carolina Electric & Gas Co 84/01/31 5pp 22442 264 24% Fiche 50-395,84/01/31,8403020039
- 8403300145 Monthly operating rept for Feb 1984 W/840314 ltr LOIONON.0 A . DIXON.0 W South Carolina Electric & Gas Co 84/02/29 BARRY,L W Office of Resource Management, Director 5pp 22820 072 24X Fiche 50~395.84/02/29.8403300145
- S Reportable occurrences, LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpei NPS-4 T&T valve, to close Encl itr dtd 840203 sent to listed utils GE notified of affected units in BWR plants
 THERDUX, R R Terry Corp 84/02/22 WDODRUPF, R W Director's Office, Office of Inspection and Enforcement 6pp 22706 327 24X Fiche 50-000.84/02/22,8403210032
- B403070337 Special Rept SPR 84-002 on 840131, fire-rated wall in Room 63-15, control bldg, 463-ft elevation, degraded by hole approx 2-inch in diameter from chair pushed against wall Damaged area not repaired until 840216, due to personnel error DIXON.O W South Carolina Electric & Gas Co 84/02/27 O'REILLY, JP Region 2, Office of Director 2pp 22546 307 24X Fiche 50-375, 84/02/27, 8403070337
- 8403060242 LER 84-006-00 on 840131, noted that overcurrent protection devices for plant paging sys not included in Tech Bpec 3 8 4 Rev to Tech Spec will be submitted adding acceptable fuses W/840301 ltr KGON, A R. DIXON, O W South Carolina Electric & Gas Co 84/03/01 2pp 22516 155 24X Fiche 50-395,84/03/01.8403060242
- 8403060351 LER 84-007-00 on 840227, potential bomb threat received via telcon Cause unknown Search of 412 ft elevation of control bldg conducted w/negative results Plant returned to security condition green H/840302 ltr
 KODNA R , DIXONO W South Carolina Electric & Gas Co 84/03/02 2pp 22319 082 24X Fiche 50-395,84/03/02,8403060351
- 8403080153 iER 84-010-00 on 840209, reactor manully tripped at 8% power Plant experienced problems w/main turbine speed control Cause unknown Reactor coolant pumps restarted Operating procedure revised H/840305 ltr
 KOON, A R., DIXON, OW South Carolina Electric & Gas Co 2pp 22559 291 24% Fiche 30-395,84/03/05,8403080153
- 8403090052 LER 84-008-00 on 840207.low-low level in steam generator E tripped reactor Caused by electronic card FCY-48B control circuitry failure partially closing main feedwater regulating valve Post-trip review conducted W/840305 ltr KCON.A R. DIXON.O W South Carolina Electric & Gas Co 84/03/05 2pp 22575 358 24X Fiche 50-375,84/03/05,8403090052
- B403090249 LER 84-009-00 on B40208.unit tripped on low-low steam generator level in steam generator C Caused by low feedwater temp Plans made to restart reactor W/A40305 ltr W/A0305 RA003090249
- 8403130260 Special Rept SPR 84-003 on 840125, seismic instrument IYM-1783 removed from svc to verify calibr Caused by damaged integrated circuit chip Mod change, reinstallation & testing in progress
 DIXON.O W South Carolina Electric & Gas Co 84/03/05
 O'REILLY, J P. Region 2, Office of Director Rpp 22614 176 24X
 Fiche 50-395,84/03/05,8403130260
- 8403130371 LER 84-011-00 on 840210, reactor tripped due to turbine trip on low discharge pressure of shaft-driven oil pump Caused by procedural inadequacy in not verifying motor suction pump operation prior to restart W/840308 ltr KOON.A R . DIXON.D W South Carolina Electric & Gas Co 84/03/08 3pp 224i3 150 24X Fiche 50-395,84/03/08,8403130371

١

- 8403190248 Supplemental Part 21 rept re failed engine thrust bearing Plugs properly installed in both units Units free of potential defect
 MDRIARTY.J M Colt Industries. Inc. 84/03/08 KEPPLER.J C Regi
 - MDRIARTY.J M Colt Industries. Inc 84/03/08 KEPPLER.J O Region 3, Office of Director 10 22675 045 24X Fiche 50-000.84/03/08.84/03/0248
- 8403150042 LER 84-012-00 on 940214.ieak rate test not performed on reactor bidg emergency escape hatch within 72 h foliowing closure Caused by personnel error Special instruction issued M/840312 ltr KODN.A R . DIXON.O N South Carolina Electric & Gas Co 84/93/12 2pp. 22643 128 24% Fiche 50-395.84/03/12,8403150042

V Operator Examinations

- 8403290284 Forwards summary of 840202-03 operator & senior operator requalification exams Requalification program meets iOCFR55.

 App A requirements to maintain continued qualification of licensed personnel VERRELLI.P M Division of Project & Resident Programs 84/03/19 DIXON.O W South Carolina Electric & Gas Co 4pp 22800 060 24X Fiche 50-395.84/03/19,8403290284
- DUCKET 50-394 UNIV OF VIRGINIA CAVALIER REACTOR
- R Pariodic operating reports & related correspondence
- B403010397 Annual operating rept for 1983 FARRAR.J P Virginia, Univ of, Charlottesville, VA 84/02/16 Division of Licensing 10pp 22433 093 24X Fiche 50-062,84/02/16,8403010397
- DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 8403010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also placed in FDR App B documents will be placed in FDR upon request Review continuing FELTON. J M Division of Rules and Records 84/01/17 ANDERSON, S 1 Oarvey, Schubert Adams & Barer 4pp 22446 293 24X Fiche 50-000,84/01/17,8403010050
- --B3081004B3 Discusses status of UL applications Review of encl HPPS8
 B30712 ltr requested in order to determine present status of
 Unit 3 for hilling purposes W/o encl
 MILLER, W O License Fee Management Branch B3/08/05 FONNER, R L
 Regulations Division 2pp 22446 326 24% Ficho 30-000,
 84/01/17,8403010050
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 3) Review of addl documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON.S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 30-000,84/02/13,8403080179
- --8009090737 Forwards airworthiness aiert re corrosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Questions re ash amount, chemistry & size distribution will be forwarded to licensees W/o encl JACKBON.R E Geosciences Branch 80/06/12 VOLLMER.R H Division of Engineering 2pp 22883 258 24X Fiche: 50-000, 84/02/13, 8402080179
- --8101060767 Notifies of findings of possible capable fault near facility JACKBON:R E Geosciences Branch 80/10/27 ROUSE,L C Advanced Fusi & Spent Fusi Licensing Branch 1p 22583 267 24X Fiche 50-000,84/02/13,8403080179
- --B104300020 Responds to B10414 memo re util request for clarification in use of ASME code cases Util use of code cases w/o prior NRC approval is inedvisable due to potential hardship for user BUBNAK,R J Mechanical Engineering Branch 8i/04/21 YOUNOBLOOD,B J Licensing Branch 1 ip 22583 280 24X Fiche 50-000,84/02/13,8403080179
- --811i2002i9 Informs of receipt of twicon from Yakamar Indian Nation requesting that tribe be given full rights in facilities proceedings TEDESCO.R L. Assistant Director for Licensing 8i/i0/2i KETCHEN.E Hearings Division ip 22583 3IO 24X Fiche 50-000,84/02/13,8403080179

- --8303100476 Forwards util 830223 submittal in response to teicon during which remaining Phase I open items of "Control of Heavy Loads -- Case Reviews," were discussed W/o enci CLEMENSON: F Auxiliary Systems Branch NRC-20-18-388 83/02/28 STICKLEY, T H E0&6, Inc. 1p 22583 360 24X Fiche 50-000,84/02/i3,8403080179
- --B304060577 Requests search for documents re govt litigation w/util on five specific issues
 BLAGGIE.E L Office of the General Counsel 83/03/23
 DIRKNEW J Dffice of the Executive Director for Operations 1p
 22583 361 24X Fiche 50-000.84/02/13.840308D179
- --8304070113 Recommends that radiation exposure records be retained for 1 yr prior to disposal Ref Murphy to Varga 801222 CONGEL.F J Radiological Assessment Branch 83/04/01 SCHMENCER.A Licensing Branch 2 ip 22583 327 24X Fiche 50-000.84/02/13.8403080179
- 8403050288 Fifth partial response to FOIA request for six categories of documents re Pacilities Forwards App A documents App A & D documents also available in PDR Documents listed on App C & D located in Central Files & not available publicly FELTON.J M Division of Rules and Records 84/02/17 ANDERSON.S I Garvey, Schubert, Adams & Barer 9pp 22501 289 24X Fichs 50-397.84/02/17.8403050288
- --7908010232 Responds to 790405 Region 5 comments re Revision 4 to NPP8S-0A-004, "Operational GA Program Description "Expresses intent to request util to delete Section 3 3 6 entirely HAASS.W P Quality Assurance Branth 79/05/01 BRYAN, S E Division of Reactor Operations Inspections 1p 22501 305 24X Fiche 50-397,84/02/17.8403050288
- --Bli019005: Responds to Bl0923 FOIA Bl-378 request for QA documents for WPPES All documents re evaluation of licensee QA programs are in FDR HAASS, W.P. Quality Assurance Brench Bi/10/05 WILSON.V.H Management Analysis Branch 2pp 22501 310 24X Fiche 50-397,84/02/17.8403050288
- --8201300236 Forwards data for fee assessment re QA Branch review of WPP68-QA-004, "Operational QA Program Description " HAASS.W P Guality Assurance Branch 82/01/14 GERKOW,H N Management Analysis Branch 2p 22501 314 24X Fiche 50-397,84/02/17,8403050288
- C Utility Environmental Report (ER), amends & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON.J M Division of Rujes and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13,8403080179
- --8203100570 Recommends environ rept be accepted Addi questions re external appearance, plant layout & socioeconomics of single unit operation will be submitted REGAN.W H Biting Analysis Branch 82/02/25 ADENSAN.E O Licensing Branch 4 ip 22583 328 24% Fiche 50-000, 84/02/13, 8403080179
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re factifities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON J M Division of Rules and Records 84/02/13 ANDERSON, 6 I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --8003250477 Forwards hydrologic engineering questions re proposed waste treatment sys Response will supply necessary info re design basis for seepage & floodful, Also forwards generic questions re floodfulains Info will assist NRC environ review SELLS, D.E. Environmental Projects Branch 2 80/03/07 RENBERGER, D.L. Washington Public Power Supply System Spp 22583 253 24X Fiche 50-000.84/02/13.8403080179
- --8003270142 Discusses suspension of facility prooperational aquatic monitoring program Suspension approved Operational monitoring program results should not be affected by suspension

 SAMMURTHAR B Environmental Epecialists Branch 80/02/29
 SELLB, D E Environmental Projects Branch 2 2pp 22583 239 24X
 Fiche 50-000,84/02/13,8403080179

- 8403140228 Farwards State of HA Dept of Fisheries response to EIS Response received after state response forwarded to NRC Enci should be attached to other state agency ltrs SORLE. O Washington. State of 84/03/16 KNIGHTON NRC No Detailed Affiliation Given 2p 22660 121 24x Fiche 30-397.84/03/16.8403160228
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403080179 Fourth partial response to FDIA request for six categories of documents re-facilities Forwards App A documents App B document entirely withheld (ref FQIA Exemption 9) Review of addl documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON, 9 I Garvay, Schubert, Adams & Barer 7pp 22593 226 24% Fiche 50-000,84/02/13,8403080179
- --B005130793 Provides status of SER inputs & acceptance reviews for OL & CP applications Schedule should be set BURKE.N C Effluent Treatment Systems Branch B0/02/06 RREGER.N E Assistant Director for Site Analysis ip 22583 235 24% Fiche 50-000.84/02/13.8403080179
- --BIO3040032 Forwards short & long-term OL & CP review schedules, in response to 801216 meeting w/USCS List of OL plant reviews for which NRC tentatively plans to seek USCS askistance is provided JACKSON.R E Geosciences Branch NRC-03-80-113 BI/01/21 DEVINE.J F Interior. Dept of Geological Survey 3pp 2238 272 24% Fiche 50-000:84/02/13:8403080179
- 8403090121 Advises that 24 h humidity test of three safety-related components per SSER 4 (NUREG-0892) satisfactorily completed SDREMSEN. 0 C Hashington Public Power Supply System 84/03/01 SCHMENGER. A Licensing Branch 2 ip 22576 066 24X Fiche 50-397.84/03/01.8403090121
- B403130227 Forwards into re shift experience, per DF Schnell 840301 itr & SER (MUREO-0892) Licensed classroom training & exam conducted SDRCNSEN.0 C Hashington Public Power Supply System 84/03/09 DENTON.H R Office of Nuclear Reactor Regulation Director 7pt 22608 231 24x Fiche 50-397.84/03/09.8403130227
- 8403260006 Informs that functional training for personnel necessary to staff requirements per Table B-I of PAREO-0654 & staff tey emergency program positions not included in Table B-I complete.per License Condition 24 & SSER 4 SORENSEN. C Washington Public Power Supply System 84/03/19 SCHMENGER.A Licensing Branch 2 ip 22747 357 24X Fiche 50-377.84/03/19.8403260006
- 8403270220 Advises that equipment qualification program & RCIC sys reviewed.per NUREG-0892.SER Outstanding Issue 1 7(9).mods to automatic depressurization sys RCIC valves required for containment isolation remain in qualification program SURENIEN.G C Washington Public Power Supply System 84/03/22 SCHMENGER.A Licensing Branch 2 1p 22770 269 24% Fiche 50-397.84/03/22.8403270220
- F Security, medical, emergency & fire protection plans
- 8403080179 Fourth partial response to FOIA request for sis categories of decuments re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of additionants sub) to request continuing FELTON. J Division of Roles and Records 84/02/13 ANDERSON, S I Garvey. Schubert. Adams & Barer 7pp 22583 226 24% Fiche 30-000.84/02/13.8403080179
- --8231170297 Forwards Central Files version of "Description of Early Warning Sys for MPPSS Nuclear Plants 1, 2 & 4, " in response to NRC 810720 ltr re prompt notification in event of smergency Sys will be in place prior to 0L issuance BCUCHEY. 0 D Washington Public Power Supply System 62/01/11 TEDESCO. R L Assistant Director for Licensing 10 22583 321. 24X Fiche 50-000,84/02/13,8403080179
- --8208120240 Forwards Central Files version of revised page to Revision 2 of emergency plan adding local fire depts within 20 miles of facility to backup fire protection svcs BOUCHEY.O D Maskington Public Power Supply System B2/08/03 SCHMENCER.A Licensing Branch 2 2pp 22383 348 24X Fiche 30-000.84/02/13.8403080179
- --8208120248 Central Files version of revised page to Revision 2 of sarrgenty plan re provision of backup fire protection svcs a Washington Public Power Supply System 82/08/05 ip 22583 350 24x Fiche 50-000.84/02/13.8403080179

- 8403130318 Application for amend to License NPF-21.consisting of listed administrative & technical Tech Spec changes No significant hazards or unreviewed safety questions will result from changes SORENSEN. G C Washington Public Power Supply System 84/03/09 SCHWENCER, A Licensing Branch 2 Spp 22607 248 24% Fiche 30-397.84/03/09.8403130318
- --B4031210330 Proposed Tech Spec changes re fire detection instrumentation # Hashington Public Power Supply System 84/03/09 20pp 22607 253 24X Fiche 50-397,84/03/09,8403130318
- 8403260006 Informs that functional training for personnel necessary to staff requirements per Table 8-1 of NOREO-0.54 & staff key emergency program positions not included in Table 8-1 complete.per License Condition 24 & ESER 4
 SDRENSEN.O C Washington Public Fower Supply System. 84/03/17 BCHMENCER.A Licensing Branch 2 1p 22747 357 24X
 Fiche 30-397.84/03/19.8403260006
- 8403270141 Discusses updated status of Licensing Condition (16) re amergency response capability Transient Data Acquisition Sys & Graphics Displey Sys computers now functional. SGRENSEN.O C Washington Public Power Supply System 84/03/22. SCHMENCER.A Licensing Branch 2 2pp. 22769.143. 24X Fiche 50-397.84/03/22.8403270141.

Q Adjudicatory correspondence

- 8403010030 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in PDR upon request Review continuing FELTON-J M Division of Rules and Records 84/01/17 ANDERSON, S I Garvey, Schubert, Adams & Barer 4pp 22446.293 24X Fiche 50-000.84/01/17.8403010050
- --8304040532 Requests search for relevant documents re govt litigation w/util Response due by 830408
 GRIMSLEV, D H NRC No Detailed Affiliation Given 83/03/29
 FITTI, C Atomic Safety and Licensing Board Panel. ip 22446 314
 24X Fiche 30-000,84/01/17,8403010050

J Insurance & Indomnity information

- 8403040377 Forwards Endorsement 8 to MAELU Policy MF-110 & Endorsements 13 & 14 to NELIA Policy NF-270 ASHBURN.D J Harsh & McLennan, Inc 84/02/28 BALTZMAN, J Assistant Director for State & Licensee Relations 4pp. 22811:323 24X Fichs 50-397,84/02/28,8403060377
- 8403270207 Bubmits annual rept of insurance coverages for facility SGRENSEN.G C. Washington Public Power Supply System 84/03/R3. SCHKENCER.A Licensing Branch 2. ip 22772 170 24X Fiche 50-397.84/03/23.8403270207.
- P Operating license stage documents & correspondence
- 8403050292 Notification of 840301 meeting w/util in Richland, WA to discuss licensee readiness for full-power operation. Agenda encl AULUCK, R Licensing Branch 2 84/02/23 SCHWENCER, A Licensing Branch 2 4pp 22501 207 24% Fich#: 50-397, 84/02/23, 8403050292.
- 8403020330 Forwards operating experience survey in response to Generic Ltr 84-02. "Notice of Meeting re Facility Staffing "
 SORENBEN.O C Washington Public Power Supply System 84/02/24.
 SCHMENCER.A Licensing Branch 2 3pp 22439 208. 24X
 Fiche 50-397.84/02/24.8403020330
- 8403090236 Application for amend to License NPF-21, revising License Condition 13 repost-accident sampling. Class II amend fee enci SORENSEN. G C Hashington Public Power Supply System 84/03/01. SCHWENCER. A Licensing Branch 2 5pp. 22572-293 24X Fichs. 50-397, 84/03/01, 8403090236
- 8403130480 Advises of effort to determine effect of dead leg piping extending into secondary containment.per NUREO-0737.Item II B 2 & util 830916 ltr re environ qualification of safety-related equipment SCRENSEN.O C. Washington Public Power Supply System. 84/03/05. SCHWENCER.A Licensing Branch 2 2pp. 22613.214. 24X Fiche 50-397.84/03/05.8403130480

- 8403280283 Requests certification that Tech Specs accurately reflect plant.FSAR.SER analysis & other documentation within 10 days Proposed changes should be identified EIBENHUT.D G Division of Licensing 84/03/08 MAZUR.D W Washington Public Power Supply System 2pp 22808 061 24X Fiche 30-397.84/03/08.8403280283
- 8403130318 Application for amend to License NPF-21, consisting of listed administrative & technical Tech Spec changes No significant hazards or unreviewed safety questions will result from changes SDRENSEN.o C Washington Public Power Supply System 84/03/09 SCHMENGER.A Licensing Branch 2 Spp 22607 248 24X Fiche 50-397,84/03/09,8403130318
- --8403130330 Proposed Tuch Spec changes re fire detection instrumentation * Washington Public Power Supply System 84/03/09 20pp 22607 253 24X Fiche 50-397,84/03/09,8403130318
- 8403200236 Application to amend License NPF-21.revising Tech Specs to correct time during which battery capable of supplying & maintaining actual emergency loads in operable status from B h to 2 h
 SCRENSEN.O C Washington Public Power Supply System 84/03/13
 SCHWENGER.A Licensing Branch 2 3pp 22670 201 24X
 Fiche.50-397.84/03/13,8403200236
- --8403200241 Proposed Tech Specs changing time during which bettery capable of supplying & maintaining actual emergency loads in operable status from 8 h to 2 h # Washington Public Power Supply System 84/03/13 3pp. 22690
- 8403200261 Advises that control equipment for air operators CSP-AD-5, CSP-AD-6 & CSP-AD-7, listed on Table B of 10CFR50, 49 Justification for interim operation revised to not qualified Status to be upgraded by 850331 commitment date SORENSEN, 0 C Washington Public Power Supply System 84/03/14 BCHMENCER, A Llcensing Branch 2 2pp 22690 199 24X Flche, 50-397, 84/03/14, 8403200261
- 8403220061 Discusses completion of const mods re pipe supports Plant mods physically completed & final as-built configuration satisfies technical requirements SORENSEN, 9 C Washington Public Power Supply System 84/03/16 SCHMENCER, A Licensing Branch 2 2pp 22718 101 24X Fiche, 50-397, 84/03/16, 8403220061
- B403260165 Advises that human engineering deficiencies identified in Licensing Condition 16, Attachment 2, Item 2 corrected Deficiency D-1 30, identified in B31004 audit rept, also complate SDRENSEN, O C Washington Public Power Bupply Bystem 84/03/19 BCHWENCER, A Licensing Branch 2 ip 22750 354 24X Fiche: 50-397, B4/03/19, 8403260165.
- 8403260274 Forwards outline of Tech Spec preparation & review to insure accurate reflection of FSAR & BER analyses
 MAZUR,D W Washington Public Power Supply System 84/03/19
 SCHHENGER,A Licensing Branch 2 5pp 22753 150 24X
 Fiche,50-397,84/03/19,8403260274
- 8403260292 Retracts 840301 request for amend to License NPF-21, deferring demonstration of dissolved gas analysis capability for post-accident sample sys Mod can be completed w/o impact on power ascension program EDRENSEN.9 C Washington Public Power Supply Bystem 84/03/19 8CHURDER.A Licensing Branch 2 ip 22751.081 24X Fiche: 50-397, 84/03/19, 8403260292
- G Inspection reports, IE Bulietins & correspondence
- 8403080266 Forwards IE Insp Rept 50-397/83-60 on 831205-31 & notice of violation W/o notice of violation BISHOP, T W Division of Resident, Reactor Project & Engineering Programs. 84/02/22 SORENBEN, G C Washington Public Power Supply Systam 2pp 22357 121 24X Fiche 50-397,84/02/22,8403080266
- --8403080270 IE Insp Rept 50-397/83-40 on 831205-31. Noncomplience identified failure to complete maint corrective actions, per leakage surveillance program TOTH.A.D. HAITE.R.B. D. DODDS,R.T. Region 5. Diffice of Director 84/02/08 32pp. 22557.i23. 24X Fiche 50-397.84/02/22.8403080266
- 8401190072 IE Info Notice 84-19, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list snc1 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22709 239 24X Fiche 50-000,84/02/28,8401190072

- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22592 329 24X Fiche 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24% Fiche 50-000.84/03/02, 8402090008
- 8402070009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc iist enc!
 JURDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402070009
- 8402090011 IE Info Notice 84-17. "Problems H/Liquid Nitrogen Cooling Components Below Nil Ductility Temp "Svc list encl JORDAN,E L Division of Energency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402070024 IE lnfo Notice 84-09.Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07,8402070024
- B402070028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Bys " Bvc list enc! JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000.84/03/07,8402070028
- 8402070031 IE Bulletin 84-02. "Failures of QE Type HFA Relays in Use in Class IE 8afety Sys " 8vc list enci DEYCUNO.R C Director's Office Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24x Fiche 50-000.84/03/12.8402070031
- 84032701iB Requests approval to use portions of later addenda of ASME Section XI requirements resulection & exam of Class 2 piping (Category CF only) for inservice insp program Proposed code case enci SIGNENSEN. C Washington Public Power Supply Bystem 84/03/20 SIGNENSEN. C Licensing Branch 2 7pp 22774 055 24X Fiche 50-397.84/03/20.8403270118
- 8402090043 iE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21,8402090043
- B402090044 IE Info Notice B4-20, "Svc Life of Relays in Safety-Related Bys " Svc list encl JORDANA: L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403020097 Monthly operating rept for Jan 1984 W/840209 ltr GDWAN, K D , MARTIN, J D Washington Public Power Supply System 84/01/31 4pp 22442 331 24X Fiche 50-397.84/01/31,8403020097
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for DL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues DIRCKB,W J Office of the Executive Director for Operations 84/02/21 PALLADINO Commissioners 9pp 22492 083, 24X Fiche 50-000.84/02/21.8403020443
- B403300056 Monthly operating rept for Feb 1984 W/840308 ltr CDWAN,K D , MARTIN,J D Washington Public Power Supply System B4/02/29, 4pp 22821,266 24X Fiche 50-397,84/02/29,8403300056
- B Reportable occurrences, LERs & related correspondence
- 8403260233 Forwards summary list of deficiencies identified per iOCFR30 55(e).Part 21 & potential generic ltr repts for comments BTAROSTECKI.R Division of Project & Resident Programs 84/02/28 Region i. Office of Director 7pp 22756 065 24X Fiche 30-000.84/02/28.8403260233

J3130337 LER 84-010-00 on 840213, four excess flow check valves failed surveillance testing Caused by installation error Valves lesigned for water see but installed in gas see line Valves removed & replaced M/840307 ltr (ASSAKATIS.L D. HARTIN.J D. Weshington Public Power Bupply System 4/03/07 3pp 22614 iii 24X Fiche 50-397,84/03/07,8403130337

13200105 LER 84-013-00 on 840213, during shutdown conditions, both 10st-LOCA hydrogen recombiner (CAC-HR-1A & 1B) motors tripped on electrical overload Caused by differences between nameplate date & design Fuses resized W/840312 ltr 4A85AKATIS.L D. HARTIN.J P. Washington Public Power Bupgly System 34/03/12 3p 22685 360 24X Fiche. 50-397,84/03/12,8403200105

03200239 LER 84-014-00 on 840219, reactor protection sys (RPS) trip occurred Caused by water rejection flow from reactor ressure vessel isolated w/o reducing water injected Power to RPS buses A or B will not be transferred W/840314 1 tr 4ASSAKATISL D. HARTINJ D Washington Public Power Supply System 34/03/14 3pp 22590 i54 24X Fiche 50-397, 84/03/14, 8403200239

03260025 LER 84-012-00 on 840221.24 & 0302.diesel generator fuel oil tenk chemistry results not received in required time, violating Tech Spec 4 B i 1 2 d.3 Caused by misunderstanding letween util & lab W/840319 ltr 4688AKATIGL D. MARTIN.J D Washington Public Power Supply System 34/03/19 3pp 22751 026 24X Fiche 30-397.84/03/19.8403260025

)3280003 LER 84-011-00 on 840302 during intermediate renge monitor surveillance test reactor protection sys (RPS) actuation sccurred when only 1/2 scram anticipated Caused by loose connection in RPS trip sys A scram circuitry U/840321 itr 4ABSAKATIS,L D . Westington Public Power Supply System 34/03/21 4pp 22777 i55 24X Ficha 50-397.84/03/21.8403280003

13280007 LER 84-013-00 on 840307.dc input circuit breaker & fuse tripped due to loss of power Caused by inverter static witch transferring to inverter source Fuse repieced & inverter returned to svc W/840321 ltr.
(ASSAKATESL D. HARTIN.J D. Weshington Public Power Supply System 84/03/21 Spp. 22777 071 24X Fiche 50-397.84/03/21.8403280007

Congressional/Executive Correspondence

03080179 Fourth partial response to FDIA request for six categories of documents re facilities Forwards App A documents App B locument entirely withheld (ref FOIA Exemption 5) Review of iddl documents sub; to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S 1 Oarvey, Schubert, Adems & Berer 7pp 22583 226, 24X Fiche 50-000, 84/02/13.8403080179

8009110203 Responds to B00702 itr re E Borhek concern about ultimate responsibility for civil penalities proposed against util Civil penalities ere imposed as enforcement action State egencies should be contacted re responsibility for payment DIRCKS, N J Office of the Executive Director for Operations 80/08/24 JACKSDN.H M Senate 4pp 22593 260 24X Fiche 50-000.84/02/13,8403080179

BOJRI60351 Forwerds 800625 ltr from constituent E Borhek for response Requests that duplicate rept be forwarded to 802 United States Courthouse, Seattle, MA 98104 JACKSON, H M Senate, Energy & Netural Resources 80/07/21 KAMMERER, C C Office of Congressional Affairs 2pp 22383 264 24X Fiche 50-000, 84/02/13, 8403080179,

Operator Examinations

)3130227 Forwards info re shift experience, per DF Schnell B40301 ltr & SER (NUREQ-0892).Licensed classroom training & exem conducted GORENSEN.0 C Washington Public Power Supply System 84/03/09 DENTON.H R Office of Nuclear Reactor Regulation, Director 7p. 22608 231 24% Fiche 50-297, B4/03/09, 8403130227

- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8402230207 Further response to FDIA request for documents re const flaws at facility Forwards documents listed in App A Documents also being placed in PDR & LPDR Review continuing FELTON, J M Division of Rules and & Records 83/12/02 VADEN, T News & Observer/Raleigh Times, Raleigh, NC 3pp 22378 299 24X Fiche 50-400,83/12/02,8402230207
- --BA02230226 Forwards Dfc of Inspector & Auditor "Inquiry into Alleged Omission of Line Inspector Views from CP Hearing " No further distribution should be made outside of ofc Rept under Commission review GOSSICK.L V Office of the Executive Director for Operations 78/11/19 DENTON Office of Nuclear Reactor Regulation, Director SHAPAR Office of the Executive Legal Director DAVIS Office of Inspection & Enforcement, Office of the Director. ip 22378 305 24X Fiche 50-400,83/12/02,8402230207
- --8402230237 Forwards Apps A.B.C & D to be included w/questions for Panel III re facility testimony Related info encl MURPHY.C.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/11/16 REIS.E J Office of the Executive Legal Director Sipp 22378 308 24X Fiche 50-400,83/12/02,8402230207
- --B402230245 Ack 820510 conversation re allegations by Pacility employee D Jarvis.per Regionel Ofc Instruction 2251, Rev 2, Paragraph 2 C (3) Case file and MAXHELL, O Region 2, Office of Director 82/05/10 VORSE, J NRC No Detailed Affication Given 2pp 22379 032 24X Fiche 50-400, B3/12/02, B402230207
- --8402230248 Requests that Region II civik insp personnel investigate allegations by Unidentified individual re coatings during next routine insp at site Case chronology encl MAXWELL, OF Region 2, Office of Director 82/07/07 VORSE, J NRC No Detailed Affiliation Given 2pp 22379.034 24X Fiche 50-400,83/12/02.8402230207
- --840223025; Hatl maint requirements for Procedure AP-XIII-07, "in-Storage Insp & Meint " Equipment purchase order form encl + Carolina Power & Light Co 83/12/02 9pp 22379 040 24X Fiche 50-400,83/12/02,8402230207
- 8403i60330 Informs that design & const GA program transmitted by 830509 ltm acceptable LEWIS,R C Division of Project & Resident Programs 84/02/24 UTLEY,E E Carolina Power & Light Co 1p 22660 102 24X Fiche 50-400,84/02/24,8403140330
- 8402090017 Board Notification 84-038 forwards RJ Mattson 840123 memo to DG Eisenhut providing status update of NRC actions re Hestinghouse ECCS actuation logic EISENHUT, D 0 Division of Licensing 84/02/27 PALLADIND Commissioners 7pp 22546 007 24X Fiche 50-000,84/02/27,8402090017
- 8403280070 Notification of 840321 meeting w/util in Bethesda.MD to discuss util qualification program, including both environ & seismic considerations
 BUCKLEY.B C Licensing Branch 3 84/03/01 KNIGHTON.O W Licensing Branch 3 4pg 22812.314 24X Fiche 50-400.84/03/01, 8403280070
- 8403280122 Summery of 840224 meeting w/Westinghouse Owners Oroup in Bethesda, MD re proposed Westinghouse steam generator tube rupture generic program Attendee list & agenda encl NERSES, V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp. 22811 131 24X Fiche 50-000,84/03/07,8403280122
- 8403210131 Application to amend CPPR-159 to reflect latest date for const completion as 860301, per 10CFR50 55(b) Extension results from delays in projected inservice date k corresponding fuel load date, per util 821014 ltr MCDUFFIE, M A Carolina Power t Light Co 84/03/16 DENTON, H R Defice of Nuclear Reactor Regulation, Director. 2pp. 22707 264 24X Fiche 50-400,84/03/16,8403210131
- E NRC Sefety Evaluation Report (SER), suppls & correspondence
- 840305006i FDIA request for extant drafts of sections or portions of BER for plant & documents showing dissenting opinions of staff reviewers EDDLEMAN.W Eddleman, W 84/01/12 FELTON.U Division of Rules and Records 1p 22476 346 24% Fiche 50-400.84/01/12,8403050061.

- 8403050064 Partial response to FOIA request for extant drafts of sections of SER for plant & documents showing dissenting opinions of staff reviewers Forwards App A documents Documents also in PDR Search for addl documents in progress FELTON.J M Division of Rules and Records 84/02/07 EDDLEMAN.W Eddleman. W 4pp 22476 347 24% Fiche 50-400.84/02/07.8403050064
- ---8205i20076 Forwards request for add1 info re organic matls & spent fuel pool cleanup sys FBAR sections BENARDYA.V Chemical Engineering Branch 82/04/27 MIRAGLIA.F Licensing Branch 3 4pp 22496 35i 24X Fiche 50-400.84/02/07. 8403050064
- --8205270420 Forwards request for add1 info re fire protection program needed to complete review Info needed by 821102
 BENARDYA.V Chemical Engineering Branch 82/03/17 MIRAGLIA.F Licensing Branch 3 7pp 22497 015 24X Fiche 50-400.84/02/07.8403059064
- ~-B207140072 Submits branch input for draft SER Input assumes that plant meets design objective of App I

 GAMMILL, H P Meteorology & Efficient Treatment Branch B2/06/25

 MIRAGLIA, F J Licensing Branch 3 57pp 22501 007 24X

 Fiche 50-400, B4/02/07.8403050064.
- --S211090008 Forwards draft SER input re SRP Sections 2 5 i on basic geology & satemic info, 2 5 2 on seismology & 2 5 2 3 on SBE. No capable faults exist at or around site SSE & OBE adequate KNIGHT.J P Assistant Director for Comp & Structures Engineering (Pre B30201) B2/10/20 NGVAK.T M Assistant Director for Operating Reactors 21pp 22476 355 24X Fiche 50-400.84/02/07.8403050064
- ---B211090035 Submits Core Performence Branch input to draft SER Confirmatory & open issues listed RUBENBTEIN-L B Assistant Director for Core & Plant Systems B2/10/21 NOVAK, T M Assistant Director for Licensing 2p; 22497
- --821111046i Advises that applicant has not responded to request for info re SER items concerning oil collection sys for reactor coolant pump, alternate shutdown trapability, fire protection for safe that down to NUREO-0800 BENARDYA, V. Chemical Engineering Branch 82/i0/28 KNIGHTON, 9 Licensing Branch 3 ip 22497 088 24X Fiche 50-400, 84/02/07, 8403030064,
- ---8211160112 Forwards draft SER input re FGAR Sections 2 5 4 2 5 6
 Request for addl info also encl Site visit necessary before
 and of yr to observe as-built conditions & implementation of
 dam safety monitoring plans
 LEAR.O. E Hydrologic & Geotechnical Engineering Branch 82/11/09
 KERRIOAN.J D Licensing Branch 3 40pp 22497 260 24X
 Fiche 50-400.84/02/07.8403050064
- --8211170249 Forwards draft SER input based on Auxiliary Sys Branch review of FSAR Unresolved items listed RUBERNSTEINL S Assistant Director for Core & Plant Systems 82/11/04 NDVAK,T M, Assistant Director for Licensing 165pp 22497 089 24X Fiche 50-400,84/02/07.8403050064
- --821i300017 Forwards Chemical Engineering Branch draft SER input re listed sections of FSAR through Amend 2 & 820802 ltr.based on SRP (NUREQ-OBSO) & NUREQ-0737, Item II B 3 Add1 info needed to complete review of post-accident sampling sys. JOHNSTON, W V. Assistant Director for Matls & Qual Engineering (Pre 830201) 82/11/17 NOVAK.T Assistant Director for Licensing 21pp 22497 300 24X Fiche 30-400,84/02/07. 8403050064.
- --8212140163 Forwards Structural Engineering Branch summary of FSAR review & draft BER input.

 KNIGHT.J P Assistant Director for Comp. & Structures Engineering (Pre 830201) 82/12/06 NOVAK,T M Assistant Director for Licensing 16pp. 22497 346 24X Fiche 50-400,84/02/07,8403050064
- ~~8212160220 Forwards revised Hydrologic Engineering Section SER input Revised input superscades previous submittal transmitted by 821014 memo.

 LEAR.O.E. Hydrologic & Geotechnical Engineering Branch 82/12/03 KNIOHTON.O. Licensing Branch 3 25pp 22497;321 24X Fichs.30-400.84/02/07.8403030064.
- T-8212300403 Forwards draft revised SER input to BRP Sections 2 5 1, 2 5.2 & 2.5 3 re geology & seismology Revision includes applicant commitment to install & operate free-field accelerometers

 KNICHT, J.P. Assistant Director for Comp. & Structures Engineering (Pre. 830201), 82/12/21 LAINAS, 0 C. Assistant Director for Licensing 24pp. 22497 362 24X Fiche 50-400,84/02/07, 8403050064.

- --8301060211 Forwards draft SER input, including one open item re possible shipments of toxic metls past plant site MULLER, D R Assistant Director for Environmental Technology (Pre 830201) 82/12/22 NOVAK, T M Assistant Director for Licensing 9pp 22498 024 24X Fithe 50-400, 84/02/07, 8403050064
- --8301140474 Forwards Equipment Gualification Branch input for SER Suppl 5 re environ qualification of mechanical & electrical equipment JDHNSTON.W V Assistant Director for Matls & Qual Engineering (Pre 830201) 83/01/10 NOVAK.T M Assistant Director for Licensing 3pp 22478 033 24X Fiche 50-400.84/02/07.84030500044
- --830:260036 Forwards Meteorology & Effluent Treatment Branch input to draft SER Assumption that draft meets 10CFR30.App I objectives will be verified when fluidize bed dryer effluents calculated NUREG-0737.Item III D i incomplete HDUBTON:R W Assistant Director for Radiation Protection 83/01/06 NOVAK.T M Assistant Director for Licensing 58pp 22500 310 24% Fiche 50-400.84/02/07.8403050064
- --8309060390 Forwards Equipment Qualification Branch SER input for environ qualification of equipment important to safety KN10HT.JP Assistant Director for Comp & Structures Engineering (Flost 830201). 83/08/26 NGVAK.T M Assistant Director for Licensing 5pp 22498 036 24X Fiche 50-400.84/02/07.8403050064
- --8309200478 Forwards Geotechnical Engineering Section input to SER Input based on FBAR through Amend 9 Stability of 400-ft long retaining wall still open issue LEAR. O Structural & Geotechnical Engineering Branch 83/09/02 KNIGHTON. G Licensing Branch 3 76pp. 22498 188 24X Fiche 50-400.84/02/07.8403050064
- --8309210098 Forwards Power Sys Branch SER for Chapters 8-10 of FSAR Issues requiring resolution include containment electrical penetrations.use of load sequencer w/offsite power & frequency of testing of turbine valves RUBENBTEIN:L S Assistant Oirector for Core & Plant Systems 83/08/31 NOVAK,I M Assistant Director for Licensing 80pp 22498 041 24X Fichs 50-400,84/02/07,8403050064
- --8309210116 Forwards SER input for FSAR Sections 4 2.4 3.4 4.15 4 i. 15 4 2.15 4 3.15 4 7 & 15 4 8 Confirmatory & open issues identified listed RUBENSTEIN, L B Assistant Director for Core & Plant Systems 83/09/01 NOVAK, T M Assistant Director for Licensing 69pg 22498 119 24X Fichs 50-400,84/02/07.8403050064
- --8309220302 Forwards hydrologic engineering input to SER One open item exists re potential for intense local precipitation to flood safety-related structures Tech Spec defining anti-sediment deposit procedure required JOHNSTON, W V Assistant Director for Matis. Chem & Environ Technology (Post 830201) 83/09/14 NOVAK, T H Assistant Director for Licensing 24pp 22499 188 24X Fiche 30-400.84/02/07.8403050064
- --8309260018 Forwards SER supporting geology & seismology at facility KNIGHT, J P Assistant Director for Comp & Structures Engineering (Post 830201) 83/09/08 NOVAK, T M Assistant Director for Licensing 44pp 22498 264 24% Fiche 50-400,84/02/07,8403050064
- --8307260421 Forwards structural engineering SER sections based on review of FSAR through Amend 9 Three open & one confirmatory items remain Resolution of open/confirmatory items will be addressed in subsequent SER KNIGHT. J P Assistant Director for Comp & Structures Engineering (Post 830201) 83/09/15 NDVAK.T M Assistant Director for Licensing 16pp 22499 212 24X Fiche 50-400,84/02/07,8403050064
- --8307260482 Forwards Auxiliary Sys Branch SER input based on review of all amends to FSAR up to Amend 9 & applicants 830418.0603, 30.0705,15 & 0812 responses Summary of unresolved Issues to be used as basis for meeting w/applicant also enci RUBENBTEIN,L S Assistant Director for Core & Plant Systems 83/09/14 NDVAK,T M Assistant Director for Licensing, 25ipp 22498 308 24X Fiche 50-400,84/02/07,8403050064
- --8309290412 Forwards Effluent Treatment Sys Section input to SER reflecting changes in status of open items based on 830824 meeting MULLER, D.R. Assistant Director for Radiation Protection 83/09/14 NDVAK, T.M. Assistant Director for Operating Reactors 60pp 22500 190 24X Fichs 50-400,84/02/07,8403050064

- --8309290474 Forwards SER on plant personnel training Util training programs for licensed reactor operators acceptable Util inadequately addressed training of shift technical advisor (STA) when STA absent from STA duties RUSSELL, B Division of Human Factors Safety 83/09/21 NOVAK, T Assistant Director for Licensing 21pp 22499 228 24X Fiche 50-400,84/02/07.8403050064
- --83i0i30378 forwards branch SER input re status of unresolved issues.In response to ALAB-444 decision Issues A-45 & A-47 listed as confirmatory items rather than open items W/o encls KNIELLK Generic lasues Branch 83/10/04 KNIGHTON,0 Licensing Branch 3 26pp 22499-247 24X Fiche 50~400.84/02/07.8403050064
- --8310170095 Forwards Chemical Engineering Branch proposed license condition re TMI Item II B 3. "Post-Accident Sampling Sys " Contents of draft SER should be used for SER JUHNSTON, W V Assistant Director for Matis, Chem & Environ Technology (Post B30201) 83/10/06 NOVAK, T M Assistant Director for Licensing 3pp 22499 279 24X Fiche 30-400,84/02/07.8403050064
- ~-8310190067 Forwards aerial maps as input to 821222 draft SER item re shipment of toxic matls past plant site not resolved JOHNSTON.H V Assistant Director for Matls, Chem & Environ Technology (Post 830201) 83/10/11 NOVAK,T M Assistant Director for Licensing App 22497 331 24X Fichs. 30~400,84/02/07,8403050064
- --8310200096 Forwards SER input on pump & valve operability assurance program & seismic & dynamic qualification of seismic Category I mechanical & siectrical equipment Addi info needed for TMI Items II E 4 2 & II.D I re reliability KNIGHT.J P Assistant Director for Comp & Structures Engineering (Post 830201) 83710/06 NOVAK.T M Assistant Director for Licensing 4pp. 22499 275 24X Fiche 50-400.84/02/07.8403050064
- --B310310445 Forwards results of review of Sections 5 2 2.5 4 7.6 3 % 15 through Amend 10 of FSAR Open issues which will be summarized in later SER suppl listed HOUSTON.R W Assistant Director for Reactor Safety B3/10/07 NOVAK,T M Assistant Director for Licensing 49pp 224% Fishs 50-400.84/02/07.8403050064
- --B311100049 Informs that applicant is to submit calculation of ultimate strength capacity of containment bldg under internal pressure as resolution of BER outstanding confirmatory structural ltem Marked-up BER input encl

 LEAR.G Structural & Geotechnical Engineering Branch 83/10/28

 KN19H7ON.G Licensing Branch 3 3pp 22500 024 24X

 Fiche 50-400.84/02/07.8403050044
- --B31110263 informs of closeout of listed sections of B30714 SER based on new lnfo Updated sections end Closeout of additionen ltems, including NUREO-0612 info.will take place as acceptable info made available RUBENSTEIN.L 8 Assistant Director for Core & Plant Systems B3/10/28 NOVAK, T M Assistant Director for Licensing 49pp 22497 337 24X Fiche 50-400.84/02/07,8403050064
- --83:1140004 Advises that, due to need to coordinate effort w/Aux\$11ary Sys Branch, revised SER to be submitted on 83:127 will still contain listed fire protection open items JOHNSTON, W V Assistant Director for Matls, Chem & Environ Technology (Post 830201) 83/11/03 NOVAK, T Assistant Director for Licensing 2pp 22500 030 24X Fiche 50-400,84/02/07, 8400000064
- --B311160283 Forwards revised SER input on confirmatory item re ultimate strength capacity of concrete containment bldg Item resolved LEAR.O Structural & Geotechnical Engineering Branch 83/11/14 KNIGHTON.G Licensing Branch 3 3pp 22500 047 24X Fiche 50-400,84/02/07,8403050064
- --8311160367 Informs that draft SER Section 17 acceptable except in area of items subj to 10CFR50. App B.GA program during operations phase Info re current status & acceptability of GA program enci
 PARTLON. J G Division of GA, Safeguards & Inspection Programs (Post 830103) 83/11/09 YOUNGBLOOD B J Licensing Branch 1
 3pp 22300 027 24% Fiche 50-400.84/02/07.8403050064
- --8311270301 Forwards revised Nydrologic Engineering input to SER New Tech Spec requirement developed re watertight doors for eafsty-related bidgs JOHNSTON.W V Division of Engineering Technology 83/11/10 NOVAK.T M Assistant Director for Licensing 15pp 22500 032 24X Fiche 50-400,84/02/07,8403050064

- --8311270352 Updates SER re stability of retaining wall west of fuel handling bldg Based on applicant 830719 submittals, stability cannot be assured due to lack of listed info Final SER update encl
 LEAR, O E Hudrologic & Geotechnical Engineering Branch 83/11/18
 KNIOHTON. O Licensing Branch 3 5pp 22501 049 24X
 Fiche 50-400,84/02/07,8403050064
- --8312020063 Forwards SBER resolving Open item on toxic gas shipments past site Concurs w/findings & considers item closed UDHN9TON, W V Assistant Director for Matls, Chem & Environ Technology (Post 830201) 83/11/18 NOVAK, T M Assistant Director for Licensing 2pp 22301 054 24X Fiche 50-400,84/02/07,8403050064
- ---8312080188 Forwards effluent treatment sys section input to SER Open items include method for determining releases of noble gases from mechanical vacuum pumps & radioactivity monitor on discharge from syc water sys MULLER.D R Assistant Director for Radiation Protection 83/1/1/18 NOVAK,T M Assistant Director for Licensing 51pp 22500 137. 24X Fichs 50-400.84/02/07.8403050064
- --8312120002 Lists closed out open items in SER forwarded on 830914 & sections w/remaining open items
 RUBENSTEIN:L B Assistant Director for Core & Plant Systems
 83/1/17 NOVAK:T M Division of Licensing 88pp 22500 050
 24X Fichs 50-400,84/02/07.8403050064
- --8312120445 Forwards input to SER.consisting of emergency plan evaluation rept & responses to NUREO-0737. Items
 III.A 1 1. III A 1 2 & III A 2 re emergency preparedness
 MATTHEMB.D B Division of Emergency Preparedness & Engineering Response (Post 830103) 83/11/30 KNIGHTON. C Licensing Branch
 3 36pp 22501 058 24X Fiche 50-400.84/02/07.8403050064.
- --8312140429 Submits review of draft SER response to Open Item 47 on RCS vents Proposed design conforms w/criteria gutlined in NUREO-0737 ciarification pertaining to electrical power supplies to vent valves SRINIVABAN.M Power Systems Branch 83/11/23 SHERON, B Reactor Bystems Branch 2pp 22501 034 24X Fiche 50-400, 84/02/07, 8403050064
- --8312230278 Forwards revised SBER re fire protection Listed items remain open
 UCHNSTON.W V Assistant Director for Matis, Chem & Environ
 Technology (Post 830201) 83/12/14 NOVAK.T Assistant Director for Licensing 12pp 22501 094 24X Fiche 50-400,84/02/07,
 8403030064
- 8403130062 Forwards add1 info re fuel handling bldg retaining wall design, in response to SER Open Item 1 from Structural & Geotechnical Engineering Branch HCDUFFIE, HA Carolina Power & Light Co 84/03/07 DENTON, H, R Office of Nuclear Reactor Regulation, Director Spp 22601.254 24X Fiche 50~400,84/03/07,8403130062
- 8403140174 Forwards Rev O to Inservice Insp Procedure ISI-201, "ABME Preservice Insp Program Plan (Except Reactor Vessel)," in response to Matls Engineering Branch SER Open Item 6 McDUFFIE,M A Carolina Power & Light Co 84/03/07 DENTON.H R. Office of Nuclear Reactor Regulation, Director 2pp 22620,090 24X Fiche 50-400,84/03/07,8403140174
- --B40314017B Rev 0 to Inservice Insp Procedure ISI-201, "ASME Preservice Insp Program Plan (Except Reactor Vessel)," W/45 aperture cards Aperture cards are available in PDR carolina Power & Light Co. 84/02/03 74pp 22620 092 24X Fiche 50-460,84/03/07,8403140174
- 8403140120 Forwards Rev 2 to emergency plan.per SER Changes reflect cancellation of Unit 2, interfaces w/State of NC radiological emergency response plan & evacuation time study results. HCDUFFIE,M A Carolina Power & Light Co 84/03/08 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp. 22624,271. 24X Fiche 50-400,84/03/08,8403140120
- --8403140125 Rev 2 to emergency plan, plant operating manual, Vol 1, Part 2 Related info encl HillER.J L Carolina Power & Light Co 84/02/29 173pp. 22624 273 24X Fiche, 50~400, 84/03/08, 8403140120.
- B403290134 Forwards add1 info re svc water sys effluent monitoring in response to SER Open Item 11 from Meteorology & Effluent Treatment Branch.
 MCDUFFIE,M A Carolina Power & Light Co 84/03/22. DENTON,M R Office of Nuclear Reactor Regulation. Director. 6pp 22807:101.
 24% Fichs 50-400,84/03/22.8403290134

- F Security, medical, emergency & fire protection plans
- 8403160283 Advises of 840316 meeting in Region II ofc to discuss App R requirements & results of recent App R insps Attendance should be limited to six util employees LEWIS.R C Division of Project & Resident Programs 84/03/02 UTLEY,E E Carolina Power & Light Co ip 22660 109 24X Fiche 50-000.84/03/02,8403160283
- 8403140120 Forwards Rev 2 to emergency plan, per SER Changes reflect cancellation of Unit 2.interfaces w/State of NC radiological emergency response plan & evacuation time study results MCDUFFIE, M A Carolina Power & Light Co 84/03/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22624 27i 24X Fiche 50-400,84/03/08,8403140120
- --8403140125 Rev 2 to emergency plan, plant operating manual, Vol 1, Part 2 Related info encl MILLER, J.L. Garolina Power & Light Co. 84/02/29 173pp 22424 273 24X Fiche 50-400,84/03/08.8403140120
- 8403190065 Forwards State of NC & Chatham Harnett, Lee & Wake Counties emergency response plan Plan forwarded to ASLAB for use in hearings by separate itr dtd 840228 MCDUFFIE, M A Carolina Power & Light Co 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 22663 130 24X Fiche 50-400,84/03/12,8403190065
- --8403190067 Emergency response plan * North Carolina, State of 84/02/29 454pp 22663 131 24X Fiche 50-400,84/03/12,8403190065
- Q Adjudicatory correspondence
- 8402230207 Further response to FOIA request for documents re const flaws at facility Forwards documents listed in App A Documents also being placed in FDR & LFDR Review continuing FLTON.J M Division of Rules and Records 83/12/02 VADEN.T News & Observer/Raleigh Times, Raleigh, NC 3pp 22378 299 24 Fichs.50-400.83/12/02.8402230207
- --Bi04210125 Discusses implications of Ofc of Inspector & Auditor 781012 interview w/facility ABLD Dfc of Inspector & Auditor attempted to probe thought processes of & require justification from Board re action taken in adjudication YORE, J R Atomic Safety and Licensing Board Panel 78/10/19 HENDRIE, J, H Commissioners 3pp 22378, 302 24x Ficher 50-400, 83/12/02, 8402230207
- --8402230237 Discusses investigation by Ofc of Inspector & Auditor (QIA) re facility proceeding ABLAB unwilling to be interrogated by OIA Many questions in OIA interrogation of members of ABLB manifestly improper ROBENTHAL.A. B Atomic Safety and Licensing Appeal Panel. 78/10/20 HeNDRIE Commissioners 2pp 22378 306 24% Ficha 50-400.83/12/02.8402230207
- 8402070054 Forwards corrected copy of Page 10 of NRC 840130 response in opposition to Eddleman proffered Contentions 169,170. 171 & 172 re safety parameter display sys MOURE. J E Hearing Branch 1 84/01/31 KELLEY. J L , CARPENTER, J H , BRIGHT, Q, O Atomic Safety and Licensing Board Panel 1p 22102 361 24X Fiche 50-400,84/01/31,8402070054
- --8402070057 Corrected Page 10 of response opposing Eddleman proffered Contentions 169, 170, 171 & 172 re safety parameter display was # Hearing Branch 1 84/01/30 Atomic Bafety and Licensing Board Panel 1p 22102 362. 24X Fiche 50-400,84/01/31.
- 8402290081 Amended Certificate of 8vc for applicant 840224 motion for reconsideration or clarification of ASLB memorandum & order on health effects contentions Certificate of 8vc encl BAXTER, T.A. Caroline Power & Light Co
- 8403020182 Motion for summary disposition of Joint Intervenor Contention V re continuous air monitors & portable air samples. No genuine issue of mati fact exists & applicant entitled to favorable decision.Related correspondence ANDEREGN.P H Carolina Power & Light Co ANDERBON.P H Shaw, Pittman, Potts & Trowbridge 84/02/27 Atomic Safety and Licensing Board Panel 14pp 22440 193 24X Fiche 30-400.84/02/27.8403020182

- --8403020188 Statement of matl facts as to which there is no genuine issue to be heard on Joint Contention V Related correspondence
 ANDERSON, P H Carolina Power & Light Co ANDERSON, P H Shaw, Pittman. Potts & Troubridge 84/02/27 Atomic Safety and Licensing Board Panel 3pp 22440 207 24X Fiche 50-400. 84/02/27,8403020182
- --B403020192 Affidavit of WH Wilkie in support of applacant motion for summary disposition of Joint Intervenors Contention V Certificate of Svc encl Related correspondence WILLIE.W H. Carolina Power & Light Co. B4/02/24 17pp 22440 210 24X Fiche 50-400.84/02/27,8403020182
- 8403010263 Response opposing W Eddleman motion to admit Contention SE(2d) on Financial qualifications of co-applicants ASLB has no basis or authority to reconsider original ruling on contention & motion must be denied Cerbificate of Svc encl O'NEILL.JH Carolina Power & Light Co O'NEILL.JH Shaw, Pittman, Potts & Troubridge 84/02/28 Atomic Safety and Licensing Board Panol 7pp 22432 258 24X Fiche 50-400,84/02/28,8403010263
- 8403070051 Forwards emergency response plan in support of facility Plan encompasses state plan & plans of Chatham Harnett, Lee. & Wake Counties W/o encl Related correspondence HOLLAR.D E Carolina Power & Light Co 84/02/28 KELLEY, J L , BRIOHT, G O . CARPENTER, J H Atomic Safety and Licensing Board Panel 2pp 22541 276 24X Fiche 50-400,84/02/28.8403070051
- 8403070055 Motion for summary disposition of Eddleman Contention 15AA re capacity factor No genuine issue of matl fact exists
 Related correspondence
 HOLLAR.D E Carolina Power & Light Co 84/02/28 Atomic Safety
 and Licensing Board Panel 15pp 22541 123 24X
 Fiche 50-400.84/02/28,8403070055
- --B403070058 Statement of matl facts as to which there is no genuine issue
 HDLLAR.D E Carolina Power & Light Co 84/02/28 Atomic Safety and Licensing Board Panel 3pp 22541 i38 24X
 Fiche 50-400.84/02/28.8403070055
- --B403070039 Affidavit of RH Koppe in support of applicant motion for summary disposition of Eddleman Contention 15AA Certificate of Svc antl Related correspondence KODPE:R H Carolina Power & Light Co 84/02/27 24pp 2254
- 8403140102 Policy statement on environ qualification of safety-related electrical equipment Commission will conduct notice & comment rulemaking proceeding to delete formally 820630 compliance deadline Certificate of Svc encl
 CHILM, 8 J Office of the Secretary of the Commission 84/03/01
 37pp 22624 144 24X Fiche 50-400.84/03/01.8403140102
- 8403070134 Amend to 840113 motion for protective order preventing public disclosure of employee info abught by discovery request of W Eddleman Order issued by ASLB appropriate & necessary Certificate of Svc encl Related correspondence BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Troubridge 84/03/02, Atomic Safety and Licensing Board Panel lipp. 22338 254 24X Fiche 50-400,84/03/02,8403070134
- 8403070225 Requests questions re Contention 41 requiring discovery responses be filed before B40315 Second round discovery will be given if protective order issue not resolved before 840315 McCertificate of Svc Related correspondence BAXTER, T A Shaw, Pittman, Potts & Troubridge BAXTER, T A Carolina Power & Light Co 84/03/02 EDDLEMAN, W Eddleman, W 4pp 22341 300 24X Fiche 50-400,84/03/02,8403070225
- 8403140157 Response opposing W Eddleman 840213 motion for admission of Contention 58 (20) re financial qualifications Eddleman argument inaccurate W/NRC 840227 statement of policy MODRE, J E Hearing Branch 2 84/03/05 Atomic Safety and Licensing Board Panel 5pp 22624 001 24% Fiche 50-400,84/03/05,8403140159
- --8403140163 Response in support of applicant 840207 motion for summary disposition of Eddleman Contention 83/848 on grounds that there is no genuine issue of matl fact to be liftgated MODRE.J E Hearing Branch 2 84/03/05 Atomic Safety and Licensing Board Panel 10pp 22624 006 24X Fiche 50-400,84/03/05,8403140159
- --8403140168 Affidavit of JC Lehr supporting NF motion for summary disposition of Eddleman 83/848 Applicant assessment consistent w/NF FES W/Certificate of Svc LEHR, J C Environmental & Hydrologic Engine 84/03/05 11pp 22624 016 24% Fiche 50-

- 8403120002 Supplemental answer to applicant interrogatories & requests for production of documents on Joint Contentions I & VII Certificate of Svc encl Related correspondence.

 PAYNE M T Kudiu Alliance PAYNE M T Edelstein & Payne PAYNE M T Joint Intervenors Shearon Harris 84/03/07 420 22589 298 24% Fiche 50-400.84/03/07,8403120002
- B403130001 Reply to applicant & staff on SER contentions & motion to continue deferral of parts of Eddleman Contention 107 Contentions on SER & Contention 107 should be admitted EDDLEMAN.W Eddleman.W 84/03/07 Atomic Eafety and Licensing Board Panet 9pp 22615 204 24X Fiche 50-400,84/03/07,8403130001
- 8403130186 Motion to declare applicant 840228 motion for summary disposition on Contention 15-AA untimaly Twenty-day extension should be granted to respond to motion in alternative Related correspondence EDDLEMAN.W Eddleman. W 84/03/07 Atomic Safety and Licensing Board Panel 4pp 22634 220 24X Fiche 50-400.84/03/07.8403130186
- ~~8403130195 Motion to ailow filing of affidavit of JO Blackburn re W Eddieman tOCFR2 758 petition & affidavits Related correspondence EDDLEMAN.W Eddieman.W 84/03/07 Atomic Safety and Licensing Board Panel 19 22534 224 24% Fiche 50-400,84/03/07, 8403130185
- ~-8403130207 Affidavit of JO Blackburn in support of W Eddlaman IOCFR2 758 potition & affidavits BLACKBURN.J O Affiliation Not Assigned 84/02/14 Jpp 22634 223 24X Fiche 50-400.84/03/07.8403130186
- --8403130220 Answer to staff on summary disposition of Eddleman Contention 65 & applicant 840214 answer to Contention 65. Summary disposition lethal wrapon not to be faced unarmed Halated correspondence EDDLEMAN'R Eddleman, W 84/03/07 Atomic Safety and Licensing Board Panel 2pp 22634 228 24X Fiche 50-400.84/03/07, 8403130186
- --8403130230 Response to applicant interrogatories re Contentions 9.11 & 132(C)(2) Related correspondence EDDLEMAN W Eddieman W 64/03/07 Atomic Safety and Licensing Board Panel 20pp 22634 230 24X Fiche 50-400,84/03/07, 8403130186
- 8403130156 Hotion for summary disposition of Joint Intervanor Contention VI re monitoring sys. No genuine issue of matlifact exists & applicant entitled to favorable decision Related correspondence ANDERSON.P H Carolina Power & Light Co ANDERSON.P H Shaw, Fittman, Potts & Trowbridge 84703/09 Atomic Safety and Licensing Board Panel 18pp 22599 003 24X Fiche 50-400.84/03/09, 8403130156
- --8403130164 Affidavit of NH Wilkie & RL Shearin in support of applicant motion for summary disposition of Joint Intervenor Contention VI Certificate of Svc enc! WILKIE.W H , SHEARIN.R V Carolina Power & Light Co 84/03/08
- 8403130447 Response to N Eddleman 840307 motion to declare util 840228 motion untimely Eddleman motion frivajous insulting & unfounded Related correspondence
 O'NEILL, J H Carolina Power & Light Co
 Pittman, Potts & Trowbridge 84/03/09 Atomic Safety and Licensing Board Panel 5pp 22613 182 24X Fiche, 50-400, 84/03/09, 8403130447
- ---8403130459 Response opposing W Eddleman 840307 motion to allow filing of affidavit of JO Blackburn Good cause undemonstrated Certificate of Svc encl
 D'NEILL.J H Carolina Power & Light Co D'NEILL.J H Shew, Pittman, Potts & Trowbridge 84/03/09 Atomic Safety and Licensing Board Panel. Opp 22613 187 24X fiche: 50-400, 84/03/09,8403130447
- B40316001B Memorializes B40313 telcon extending time for discovery requests on safety contentions & for response to applicant motion for summary disposition Certificate of Svc encl BAXTER, T A False, Pittman, Potts & Troubridge BAXTER, T A Carolina Power & Light Co 84/03/13 EDDLEMAN, W. Eddleman, W 4pp 22653 360 24X Fiche 50-400, 84/03/13, 8403160018
- 8403220222 Supplemental document listing on discovery Related correspondence EDDLERAN, W Eddleman, W DS8 052 84/03/13 Carolina Power & Light Co 2gp 22717 001 24X Fiche 30-400,84/03/13,8403220222

- 8403220270 Joint Intervenort second suppl to answers to applicant interrogatories on Joint I re mpt incapability Certificate of Svc enci Related correspondences EDDLEMAN.W Eddleman. W EDDLEMAN.W Joint Intervenors Shearon Harris DSB 054 84/03/13 Carolina Power & Light Co Epp 22719 135 24X Fiche 50-400,88/03/13,8403220270
- 8403190137 Forwards applicant & NRC joint motion to withdraw Contentions 2.3 & 6 re security plan Agreement exchanged resolving issues
 FLYNN-8 F Carolina Power & Light Co B4/03/14 RELLEY, J L ,
 BRIGHT, 6 O . CARPENTER, J H Atomic Safety and Licensing Doard Panil
 2pp 22666 310 24X Fiche 30-400.84/03/14,8403190137
- --8403190141 Joint motion to withdraw security plan Contentions 2,3 & b Certificate of Suc enc? RUNKLE.J D Joint Intervenors - Shearon Harris FLYNN, B F Carolina Power & Light Co BARTH.C A Hearing Branch 1 84/03/14 Atomic Safety and Licensing Board Panel 3pp 22666 312 24X Fiche 50~400,84/03/14.8403190137
- 8403200030 Supplemental responses to W Eddleman general interrogatories & interrogatories on Contentions 41 & 65 Certificate of Svc ent; Related correspondence BAXTER.T A Carolina Power & Light Co BAXTER.T A Shaw. Pittam. Patte & Troubridge 84/03/14 Eddleman. W 7pp 22683,345 24x Fiche 50-400.84/03/14.8403200030
- 8403190025 Memorandum & order reaffirming rulings on response to B4012) order re health effects
 BRIGHT. 00 . CARPENTER: J H . KELLEY: J L Atomic Safety and Licensing Board Panel 84/03/15 Office of the Executive Legal Director 20pp 22666 085 24X Fiche 50-400:84/03/15,8403190025.
- 8403190053 Interrogatory to Joint Intervenors re Joint Contention VII Response in Writing required by 840403 BARTH-C A Mearing Branch 1 84703/15 Joint Intervenors -Shearon Harris 1p 22666 188 24X Fiche 50-400,84/03/15,
- 8403200054 Interragatories to applicant on admitted security contention Enci withheld (ref 10CFR73 21) M/Certificate of Bvc Related correspondence
 RUNKLE. J Joint Intervenors Shearon Harris 84/03/15 Carolina Power & Light Co 3pp 22698 273 24X Fiche 50-400,84/03/15,840320034
- 8403200117 Interrogatories & request for production of documents on H Eddieman Contention 1320(II) second set Certificate of Svc and Related correspondence CARRON, H Carolina Power & Light Co 84/03/15 Eddieman, H Bpp 22685
- 8403200135 Notice of ER Bleacher & JR Haples depositions on 840329 in Raisigh.NC Certificate of Svc anci Related correspondence CARROW, H Carolina Power & Light Co CARROW, H Shaw. Pittman. Potts & Troubridge 84/03/15 3pp 22699 161 24X Fiche 50-400,84/03/15,8403200135
- 8403210120 Informs that part of transcript of 840308 teicon of identification of persons in room at time of call missing BARTH.C A Hearing Branch 1 84/03/16 KELLEY, L . BRIGHT.Q O . CARPENTER, J H . Atomic Safety and Licensing Board Panel ip 22707 179 24% Fiche 50-400,84/03/16.8403210120
- 8403200048 Provides corrections to statements of scheduling agreements per 840313 ltr Extension to 840403 for Eddleman 4! applies only to second round questions not based on welder info Related correspondence EDDLEMAN.W Eddleman, W 84/03/17 BAXTER.T Shaw, Pittman, Pettle Trowbridge 1p 22699 185 24X Ficha 50-400,84/03/17,8403200048
- 8403210051 Order approving joint motion to withdraw security plan Contentions 2,3 & 6 Cooperation commended KELLEY.J L . CARPENTER.J H., BRIGHT.O D Atomic Safety and Litinisms Board Panel 84/03/19 Office of the Executive Legal Director 2pp 22704 342 24X Fichs 50-400,84/03/19,8403210051
- 8403220223 Motion to quash applicant notice to take deposition of Bleacher & Maples. Unlikely applicants can meet even threshold showing of good cause Certificate of Svc encl. Related correspondence SUNKLE, J Joint Intervenors Shearon Harris DSB 045. B4/03/19 Atomic Safety and Licensing Board Panel App 22719 003 24% Fiche 50-400.84/03/19.8403220223

1

- 8403220227 Responds to 840313 response to Eddleman 41 Related Correspondence EDDLEMAN, W Eddleman, W DSB 051 84/03/17 BAXTER, T Shaw, Pittman, Potts & Trowbridge 2pp 22717 012 24X Fiche 50-400,84/03/19.8403220227
- B40322026i Interrogatorias & request for production of documents to Joint Intervenors (seventh set) Certificate of Svc enci Related correspondence O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittmann, Petts & Troubridge DSB 05B 84/03/19 Joint Intervenors Shearon Harris 2ipp 22719 110 24X Fiche 50-400,84/03/19,840322026i
- 8403220265 Joint Intervenor general interrogatories & interrogatories on Contention 7 (first set) Related correspondence EDDLEMAN.W Joint Intervenors Shearon Harris D88 053 84/03/19 Carolina Power & Light Co 24pp 22719
- 8403280341 Clarification of Joint Intervenors position re J Gofman Gofman absolutely unwilling to appear as intervenor witness EDDLEMAN.W Joint Intervenors Shearon Harris EDDLEMAN.W Eddieman. W DSD 175 84/03/20 2pp 22787 232 24X Fiche 50-400,84/03/20,8403280361
- B403260327 Interrogatories & request for production of documents re Eddleman Contentions 9 & ii (second set) Certificate of Byc encl Related correspondence BMICER, M A Carolina Power & Light Co SMIGER, M A Bhaw, Pittman, Potts & Troubridge DSB 104 84/03/23 Eddleman, W 14pp 22760 143 24X Fiche 50-400,84/03/23,8403260327
- B40326032B Responds to 8403;7 & i9 ltrs re extension to file discovery requests, welder info confidentiality & interrogatory answers, Svc list enci Related correspondence
 BAXTER, T A Shaw, Pittman, Potts & Troubridge BAXTER, T A
 Carolina Power & Light Co DSB 103 84/03/23 EDDLEMAN, W
 Eddleman, W 4pp 22760 i37 24X Fiche 50-400, 84/03/23, 8403260328
- 8403280348 Responses to general interrogatories & interrogatories on Contention 65 (seventh set) Related correspondence BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Troubridge D68 102 84/03/23 Eddleman, W 47pp 22760 190 24X Fiche 50~400,84/03/23,8403260348
- --8403260354 Response to request for production of documents (Contention 65) Certificate of Svc encl BAXTER:TA Carolina Power & Light Co BAXTER:TA Bhaw, Pittman, Potts & Troubridge 84/03/23 Eddleman, W Ap 22760 237 24X Fiche 50-400,84/03/23.8403260348
- 8403270319 Response opposing W Eddleman 840307 motion to allow filing of affidavit of JD Blackburn Affidavit is untimely suppl to patition re need for power & alternative energy sources Certificate of Svc encl MODREJ.E. Hearing Branch i DSB 133 84/03/23 5pp 22789 023 24X Fiche 50-400,84/03/23,8403270319
- 8403270321 Clarification of staff response in support of applicant motion for summary disposition of Joint Intervenors Contention IV re TLDs
 BARTH.C A Hearing Branch 1 DSB 130 84/03/23 Atomic Bafety and Licensing Board Panel 3pp 22789 020 24X
 Fisher 50-400,84/03/23,8403270321
- 8403270333 Response in support of applicant 840227 motion for summary disposition of Joint Intervenors Contention V re calibr of air monitors Related correspondence
 BARTH.C A Hearing Branch 1 DBB 129 84/03/23 Atomic Safety and Licensing Board Panel. 2pp 22789 004 24X
 Fiche 50-400,84/03/23,8403270333
- --8403270338 Affidavit of S Block in support of summary disposition of Joint Contention V. Centificate of Buc encl BLOCK, S Division of Systems Integration (post Bl1005) 84/03/15 Bp 22789:008 24% Fichs 50-400,84/03/23,8403270333
- B403280344 Response to applicant interrogatories re Eddleman 116
 Related correspondence.
 EDDLEMAN, H Eddleman, H DSB 177 84/03/23 Carolina Power &
 Light Co App 22787, 116 24% Fiche 50-400, 84/03/23, 8403280344
- BA03280349 Natifies of inability of copy ctrs to copy new filings due BA0328. Motion made for extension of time to ensure duplication Related correspondence EDDLEMAN, H. Eddleman, W. DSB 176 B4/03/23 KELLEY, J. Atomic Bafety and Licensing Board Panel BAXTER. T. Shaw, Pittman, Potts & Trowbridge, 2pp. 22787 144 24X Fiche 50-400,84/03/23,8403280349

- B403280351 Eddleman general interrogatories & interrogatories on Contentions 9, ii, 41, 45, ii6 & 132(c)(2) to applicant (eighth set) Certificate of Svc encl Related correspondence EDDLEMAN. W Eddleman, W DSB 166 B4/03/23 * Carolina Power & Light Co 24pp 22787 148 24X Fiche 30-400, B4/03/23, B403280351
- 8403280360 Response to util motion for summary disposition on B3/84B t motion for licensing conditions No Cape Fear River water should be used by util for cooling Related correspondence EDDLEMAN.H Eddlemen, W DSB 174 B4/03/23 Atomic Sefety and Licensing Board Panel ip 227B7 231 24X Fiche 50-400.84/03/23, 8403280360
- B403270327 Advises that term job experience.used in B40314 discovery responses, includes only welding experience Related correspondence
 BAXTER.T A Shaw, Pittman, Potts & Troubridge BAXTER.T A Carolina Power & Light Co DSB 144 B4/03/26 EDDLEMAN.H
 Eddleman, W 3pp 22789 016 24X Fiche 50-400,84/03/26,8403270327
- 8403280347 Eddleman & Joint Intervenors interrogatories to NRC staff (third set) Related correspondence EDDLEMAN.W Eddleman.W DBB i65 84/03/26 Dffice of the Erscutive Legal Director 16pp 22787 127 24X Fiche 50-400.84/03/26.8403280347
- M Antitrust correspondence
- 8403020076 Notification of 840224 meeting w/util in Bethesda.MD to discuss antitrust matters BuckLEY, B C Licensing Branch 3 84/02/17 KNIOHTDN, G W Licensing Branch 3. 4pp 22491 179 24X Fiche 50-400,84/02/17,840302076
- B403020084 Notification of change in date & time for B40302 meeting w/util in Bethesda.MD to discuss antitrust matters
 BUCKLEY. D C Licensing Branch 3 84/02/27 KNIGHTON, O W
 Licensing Branch 3 App 22491 iB4 24X Fiche 50-400.84/02/27,
 8403020084
- B4032B0024 Forwards MA McDuffie 840216 response to B30119 request for add1 antitrust info to continue review of GL application.per Rag Guide 9 3 Recipient inadvertently omitted from list ZIMMERMAN.S R Carolina Power & Light Co 84/03/19 VDGLER, B NRC No Detailed Affiliation Given ip 22777 087 24x Fiche 50-400.84/03/19, B403280024
- 8403260009 Forwards responses to questions raised in 840302 meeting reantitrust review

 MCDUFFIE.M A Carolina Power & Light Co 84/03/20 TOALSTON, A L

 Biting Analysis Branch 70pp 22750 i55 24% Fiche 50-400,
 84/03/20.8403260009
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- B403i40302 Discusses seismology issues in OL review Extremely conservative values established for OBE & SSE Plant site is as nearly assismic as any site in eastern US MAXMELL, J C Maxwell, J C MAXMELL, J C AGRB Advisory Committee on Reactor Safeguards 84/01/05 KERR, W AGRB Advisory Committee on Reactor Safeguards ip 22635 317 24X Fiche 50-400.84/01/05, 8403140302
- B403160085 Comments on 840103-04 site visit & GL hearing in Apex.NC Requests opportunity to view final control room & new simulator PEARSON.R G North Carolina State Univ. Raleigh. NC PEARSON.R G ACRS Advisory Committee on Reactor Safeguards 84/01/05 KERR.W ACRS Advisory Committee on Reactor Safeguards MAJOR.R. North Carolina State Univ. Raleigh. NC 3pp 22662 276 24% Fiche 50-400.84/01/05.8403160085
- 840:30012: Summarizes ACRS 285th meeting on 840:12-14 re review of GL application: control room design & tube degradation investigation of allegations re 64 requested EBERBGLE, J C ACRS Advisory Committee on Reactor Safeguards 84/01/16 PALLADING.N J Commissioners Spp 22044-023 24X Fiche 30-400.84/01/16, Re0330012:
- Q Inspection reports, IE Bulletins & correspondence
- B403070179 Ack receipt of B40208 ltr informing NRC of steps taken to correct violations noted in lE Insp Rept 50-400/83-34
 Implementation of corrective actions will be examined during future insps
 VERRELLI.D M Division of Project & Resident Programs B4/02/22
 UTLEY.E E Carolina Power & Light Co ip 22547 276 24X
 Fiche 30-400, B4/02/22, 8403070179

- --B403070184 Responds to NRC B40110 ltr re violations noted in IE Insp Rept 50-400/83-36 Corrective actions transformer replaced Full compilance will be achieved on 840220 PARSDNS,R M Carolina Power & Light Co 84/02/08 O'REILLY, J P Region 2, Office of Director 2pp 22547 277 24X Fiche 50-400, 84/02/22, 8403070179
- --8403070193 Forwards iE insp Repts 50-400/83-36 & 50-401/83-36 on 831120 & 1220 & notice of violation VERRELLI.D M Division of Project & Resident Programs 84/01/10 UTLEY/EE Carolina Pawer & Light Co 2pp 22547 279 24X Fiche 50-400,84/02/22,8403070179
- --8403070197 Notice of violation from insp on 831120-1220 * Region 2. Office of Director 84/01/10 ip 22547 281 24X Fiche 50-400,84/02/22.8403070179
- --8403070199 IE Insp Repts 50-400/83-36 & 50-401/83-36 on 831120-1220 Violation noted failure to protect equipment from rainwater entering reactor auxiliary bidg from roof MAXWELL.0 F, PREVATTE.R L Region 2. Office of Director BEMIS.P R Division of Project & Resident Programs 84/01/09 9pp 22547 282 24X Flche 50-400.84/02/22.8403070179
- 8403070074 Ack receipt of 840118 & 27 itrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/83-35 VERRELLI.D M Division of Project & Resident Programs 84/02/23 UTLEY, E E Caralina Power & Light Co ip 22545 348 24X Fiche 50-400.84/02/23.8403070094
- --8403070095 Ciarifies response to NRC 831220 itr re vioistions noted in IE Insp Rept 50-400/83-35 Corrective actions sock-o-let restamped w/correct number on fitting on 840iii PARSONS,R M Carolina Power & Light Co 84/01/27 O'REILLY,J P Region 2. Defice of Director 2pp 22545 349 24X Fishe 50-400,64/02/23.8403070094
- --8403070096 Responds to NRC 831220 itr re vibiations noted in iE Insp Rept 50-400/83-35 Corrective actions sock-a-let restamped w/correct number on fitting on 840111 PARSONS.R M Carolina Power & Light Ca 84/01/18 D'REILLY.J P Region 2. Office of Director 2pp 22545 351 24X Fiche 50-400,84/02/23,8403070074
- --8403070100 Forwards IE Insp Repts 50-400/83-35 & 50-401/83-35 on 831129-1202 & notice of violation VERRELLI.D M Division of Project & Resident Programs 83/12/20 UTLEY/E E Carolina Power & Light Co 2pp 22545 353 24X Fiche 50-400.64/02/23.8403070094
- --8403070102 Notice of violation from insp on B31129-1202 + Ragion 2, Office of Olrector B3/12/20 ip 22545 355 24x Fiche 50-400,B4/02/23,B403070074
- --B403070105 1E Insp Repts 50-400/B3-35 & 50-401/B3-35 on B31129-1202 Violation noted failure of as-built drawings to reflect actual plping configuration MLEINSORGE, W.p. Region 2. Office of Director BLAKE, J. J. Division of Engineering & Operational Programs B3/12/13 9pp 22545.336 24X Fiche 50-400,B4/02/23,B403070094
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Syc list enci
 - JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolldated Edison Co. of New York, Inc. i15pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403160194 Ack receipt of 840207 ltr Informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/83-25 LEWIS.R C Division of Project & Resident Programs 84/03/01 UTLEY.E E Capolina Power & Light Co ip 22695 359 24% Fichs 50-400,84/03/01.8403160194
- 8402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Svc list enc.! ORACE.J N Division of OA, Bafeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22352 329 24X Fiche 50-000,84/03/02,84020900007
- 840209000B IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate," Svc list encl JORDAN, EL Division of Energancy Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- B402090009 IE Info Notice B4-i5, "Reporting of Radiological Releases"

 Svc 11st encl

 JORDAN, E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/03/02 Consolidated Edison Co of New

 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009

- B402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Caaling Components Below Nil Ductility Temp " Svc llst encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24% Fiche 50-000,84/03/05,8402090011
- 8403290198 Forwards IE Insp Rept 50-400/84-04 on 840214-17 No violations noted VERRELLI.D M Division of Project & Resident Programs 84/03/06 UTLEY.E E Carolina Power & Light Co 2pp 22803 314 24X Fichs 30-400,84/03/06.8403290198
- --8403290199 IE Insp Rept 50-400/84-04 on 840214-i7 No violations noted Major areas inspected structural concrete structural backfill, previously identified enforcement items & previously identified inspector followsp items HARRIS, J. R., CONLON.T. E. Region 2, Office of Director 84/03/03 3pp 22803 3i6 24X Flohe 50-400,84/03/06,8403290198
- 8402090024 IE info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc 11st enci JOROAN, E L Bivision of Emergency Preparedness & Engineering Response (Past 630103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- B402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Byc list enc! URDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24% Fiche 50-000,84/03/07,8402090028
- B403:40:74 Forwards Rev O to Inservice Insp Procedure ISI-20: "AGME Preservice Insp Program Pian (Except Reactor Vessel)," in response to Matis Engineering Branch SER Open Item 6 MCDUFFIE,M A Carolina Power & Light Co 84/03/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22620 090 24X Fiche 30-400.84/03/07,8403:40:74
- --B403i40i7B Rev O to Inservice insp Procedure ISI-201, "AGME Preservice Insp Program Plan (Except Reactor Vessei) " W/45 aperture cards Aperture cards are available in PDR * Carolina Power & Light Co 04/02/03 74pp 22620 092 24X Fiche 50-400,84/03/07.8403140174
- B403160267 Forwards IE Enforcement Conference Repts 50-261/84-0B & 50-409/84-08 on B40223 B/REILLY, JP Region 2, Office of Oirector 84/03/09 UTLEY, & E Carolina Power & Light Co 2pp 22660 275 24X Fiche 50-000,84/03/09,8403160267
- --8403i60274 iE Enforcement Conference Repts 50-26i/84-08 & 50-400/84-08 on 840223 Major areas discussed unauthorized entry into facility reactor cavity & QA programs re procurement of sycs & matis
 VERRELLI, D M Oivision of Project & Resident Programs 84/03/06
 3pp 22660 277 24% Fiche 50-000,84/03/09,8403i60267
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Bvc list enci DEYDUNO.R C Director's Opfice. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403290163 Ack receipt of 840309 ltr lnPorming NRC of steps taken to correct violations noted in 1E Insp Rept 50-400/84-03 Implementation of corrective actions will be examined during future insp VERRELLI.D.N. Division of Project & Resident Programs 84/03/20 UTLEY.E E Carolina Power & Light Co ip 22803 329, 24X Fiche 50-400.84/03/20.8403290163
- --B403290i64 Respands to NRC 840213 ltr re violations noted in IE Insp Rept 50-400/84-03 Corrective actions Weld Joint 1-BI-150-FM-536 documentation changed to show correct Heat Number M 2945 for weided end of Spool 1-RC-134-1 PARSONS.R M Carolina Power & Light Co 84/03/09 O'REILLY, J. P Region 2. Office of Director 2pp 22803 330 24X Fiche 50-400, 84/03/20. 8400290163
- --8403290169 Forwards IE Insp Rept 50-400/84-03 on 840124-27 & notice of violation
 VERRELLI,D M Division of Project & Resident Programs. 84/02/13
 UTLEY,E E Carolina Power & Light Co 2pp 22809-332, 24X
 Fiche 50-400,84/03/20,8403290163
- --8403290171 Notice of violation from lnsp on 840124-27 * Region 2, Office of Director 84/02/13 ip 22803.334 24X Fiche 50-400,84/03/20,8403290163

1

- ~-B403270173 IE Insp Rept 50-400/84-03 on 840124-27 Violation noted failurs to provide adequate procedures for heat number verification
 KLEINSORGE P Region 2. Defice of Director BLAKE, J J Division of Engineering & Operational Programs 84/02/08 13pp 22803 335 24% Fiche 50-400.84/03/20,8403270163
- 8402070043 IE Info Notice 84-19: "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21,8402070043
- 8402090044 IE into Notice 84-20, "Svc Life of Relays in Safety-Related Sqs." Svc list enci JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21.8402090044

R Periodic operating reports & related correspondence

- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates hot caused by delay due to offsite emergency planning issues
 DIRCKS, W. J. Office of the Executive Director for Operations 84/02/21 PALLADINO Commissioners 9pp 22472 083 24X Fiche 50-000.84/02/21.8403020443
- 8 Reportable occurrences, LERs & related correspondence
- B403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval.Inc
 DIRCKS.W.J Office of the Executive Director for Operations
 BECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000.84/01/25.8403010451
- 8402270274 Third interim deficiency rept, Item 111 re seismic quelification test failure of Transamerica Delavai, Inc starting air chack for emergency diesel engine generator sets Also reportable per Part 21 Next rept by 840025 PARBONS, R M Carolina Power & Light Co 84/02/15 O'REILLY, J P Region 2. Office of Director 4pp 22391 304 24X Fiche 50-400.84/02/15.8402270274
- 8403010350 Interim deficiency rept, Item 158 re Pullman Const Industries/Ebasco design interface HVAC ductwork Differences impacting seismic qualification may exist between design & fabrication documents Also reportable per Part 21 PARSINE, R M Carolina Power & Light Co 84/02/17 0'REILLY, J PRegion 2, Office of Director 1p 22432 328 24X Fiche 30-400,84/02/17,8403010350
- 8403010394 Deficiency & Part 21 repts. Item 197 re Ruskin Mfg Co supplied actuators failing to meet functional test requirements of 6H Bettis Co Intitially reported on 831221 Next rept will be submitted by 840323 PARBONG.R M Carolina Power & Light Co 84/09/17 O'REILLY, J P Region 2, Office of Director 1p. 22434 046 24X Fiche 50-400:84/02/17,8403010394
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines.oimpel.NPS-4 Y&T valve.to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BWR plants.
 THEROUX.R R Terry Corp 84/02/22 WOODRUFF.R.W Director's Office of Inspection and Enforcement 6pp 22706.3R7 24X Fiche.50-000.84/02/22.8403210032
- 8403070270 Fourth interim deficiency rept, Item 77 re seismic Class I cable tray, conduit & HYAC hangers supplied by Peden Stael Initially reported on 820802 Component reliasp in progress Next rept by 840701. Also reported per Part 21 PARBONS, R M Carolina Power & Light Co 84/02/24 D'REILLY, J P Region 2, Office of Director 4pp 28547 067 24X Fiche 50-400, 84/02/24, 8403070270
- 8403070082 Fourth interim & Part 21 repts, Item 101 re defective governor drive coupling supplied by Transamerica Delaval. Initially reported on 820707 Couplings to be replaced Final rept by 840525.

 PARBUNE, R. M. Carolina Power & Light Co. 84/02/24 O'REILLY, J. P. Region 2. Office of Director. App. 22575 279 24X Fiche. 50-400.84/02/24, 8405070082
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval, Inc Owners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Oulf Nuclear Power Stations HUSELER, W J. TDI (Transamerica Delaval, Inc.) Owners Group 84/02/27 DENTON, HR Office of Nuclear Reactor Regulation, Director 3pp 22434 090 24X Fiche. 50-000, 84/02/27, 8403010207

- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc. emergency diesel generators MUSELER.K J TII (Transamerica Delaval, Inc.) Owners Group 84/02/28 DENYON, H R Office of Nuclear Rea
- 8403070285 Fifth interim deficiency & Part 21 repts. Item 117 re welding defects on Class IE 6 9 kV circuit breakers Initially reported on 830211 All Class IE breakers at site returned to Siemens-Allis Final rept expected by 840331 PARBONS.R M Carolina Power & Light Co 84/02/29 D'REILLY, J P Region 2. Office of Director 4pp 22547 075 24X Fiche. 50-400. 84/02/29, 8403070285
- 8403130398 Fifth interim deficiency rept. Item 53 re-potential for Westinghouse mfg gate valves failing to fully clote/open under design conditions Also reportable per Part 21 Hardware changes completed Final rept expected by 840415 PARSUNS.R.M Carolina Power & Light Co 84/03/01 0'REILLY.J P Region 2, Office of Director 10pp 22616 283 24X Fiche 50-400.84/03/01.8403130398
- 8403130237 Interim deficiency & Part 21 repts, Item 159 re flexible coupling drive shaft in overspeed governor & fuel transfer pump drive of standby diseal generator Initially reported on 840206 Final rept will be submitted by 840416 PARSONS,R M Carolina Power & Light Co 84/03/02 O'REILLY, J P Region 2. Office of Director in 22617 277 24x Fiche 50-400.84/03/02.8403130237
- 8403140048 Forwards "Grand Guif Component Tracking Sys." "Shoreham Component Tracking Sys" & "Transamerica Daiaval.Inc Diesel Generators Owners Group Program Plan." to resolve concerns w/emergency diesel generators MUSELER.W J Long Island Lighting Co 84/03/02 DENTUN.H R Office of Nuclear Reactor Regulation, Director 2pp 22626 062 24X Fiche 50-000,84/03/02,8403140048
- --8403140095 "Transamerica Delaval, Inc Diesel Generators Duners Group Program Plan" # TDI (Transamerica Delaval, Inc.) Owners Group 84/03/02 261pp 22628 223 24X Fiche 50-000,84/03/02,8403140048
- 8403120084 Interim deficiency rept, Item 148 re nondeterminate quality characteristics of 99 of 235 pipe hangers Hanger program revised & 99 hangers reinspected Next rept will be submitted by 840507 PARSONS.R M Carolina Power & Light Co 84/03/05 O'REILLY, J P Region 2, Office of Director 1p 22588 183 24% Fiche 50~400,84/03/05.8403120084
- B403200203 Interim deficiency rept. Item 10: & Part 21 rept re defective governor drive coupling Correct ltr date is B40224-hot B30224 PARBUNS: R M Carolina Power & Light Co B4/03/09 O'REILLY, J P Region 2: Office of Director ip 22699 347 24X Fiche 50-400: 84/03/09: 8403200203
- 8402070037 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 15 meetings between NRC & Transamerica Delaval, Inc (YDI) Queers Group Distribution 11st encl EISENHUT, D & Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22708 001 24X Fiche 50-000,84/03/12,8402070039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Owners Group in Bethesda, MD re problems w/emergency
 diesel generators
 CARUSO, R Licensing Branch 2 84/02/27 D'REILLY, J P NRC No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000,84/03/12,8402090039
- --B403060554 Transcript of B40210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re-problems w/emergency diesel generators * NRC - No Detailed Affiliation Given B4/02/10 147pp 67201 008 24X Fiche 50-000, B4/03/12, B402090039
- --8403070409 Summary of B40216 meeting w/Transamerica Delaval, Inc Owners Oroup in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl
 MILLER, M A Licensing Branch 4 84/02/27 Licensing Branch 4
 Bpp 22708 161 24X Fiche 30-000,84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 30-000,84/03/12,8402070039

- 8403140030 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delavai Enterprise Engines" for Shoreham & Orand Guif diesel generators MUSELER, M J Long Island Lighting Co 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 22632 074 24X Fiche 30-000,84/03/12,8403140050
- B403150133 Forwards "Transamerica Delavai, Inc Diesei Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & svc conditions HUSELER.H J TDI (Transamerica Delaval, Inc.) Gwners Group B4/03/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000,84/03/13,8403150133
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started enci
 MATHEMS.C S Transamerica Delawal, Inc 84/03/16 EJSENHUT, D G
 Division of Licensing 20pp 22691 179 24X Fiche 50-000.84/03/16, 8403200222
- 8403270091 Interim deficiency rept re seismic HVAC ductwork by Puliman Const Industries not meeting design specs Initially reported on 840120 To date, 63% of suspected ductwork evaluated & determined acceptable Next rept by 840620 PARSONS,R M Carolina Power & Light Co 84/03/20 D'REILLY, J P Region 2. Office of Director ip 22766 332 24% Fiche 50-400, 84/03/20, 8403270091
- 8403300043 Third interim deficiency rept. Item 95 re shop welding defects in Seismic I pipe hangers supplied by Bergen-Patterson & Item 72 re understred skewed ter fillet weld on hangers Final rept by 841201 Also reported per Part 21 PARSUNS.R M Carolina Power & Light Co 84/03/21 0'REILLY, J P Region 2. Office of Director 5pp 22819 315 24X Fiche 50-400.84/03/21.8403300043
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capecrew Dimension & Stress Analysis: "prepared by S&W for Transamerica Dajaval,inc (TDI) Diesel Generator Duners Group MUSELER.W J TDI (Transamerica Delavai, Inc.) Owners Group 84/03/23 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22774 001 24X Fiche 50-000,84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & iong-term corrective actions & investigations re Transamerica
 Delaval dissel generators List of suggested meeting topics anci
 MCGAUGHY, J P TDI (Transamerica Delaval, Inc.) Euners Group
 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 4pp 22769 133 24X Fiche 50-000, 84/03/23, 8403270134
- 8403300034 Interim deficiency rept. Item 157 we GH Bettis aperators on Ruskin-supplied HVAC dampers fasting to meet functional test requirements Initially reported on 831221 Required info unavailable Naxt rept by 840321 Also reported per Part 21 PARSONS.R M Carolina Power & Light Co 84/03/23 D'REILLY, J P Region 2. Office of Director 1p 22821 311 24X Fiche 50-400.84/03/23.8403300034
- T Hearing transcripts on non-antitrust matters
- 8403120121 Transcript of 840308 telephone conference in Bethes6a.MD Pp 751-807 * Commissioners 84/03/08 58pp 22586 117 24X Fiche 50-400.84/03/08.8403120121
- B402070039 Board Notification B4-052 forwards meeting summaries containing transcripts of B40210 % 16 meetings between NRC & Transamerica Delavai, inc (TDI) Cumers Group Distribution isstenci
 EISENMUT.D 9 Division of Licensing B4/03/12 PALLADING Commissioners 5pp 2270B 001 24X Fiche 50-000, 84/03/12, 8402070039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval. Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators GARUSG, R Licensing Branch 2 84/02/27 Q'REILLY, J P NRC No Detailed Affiliation Given 6pg 22708 006 24X Fiche 50-000, 84/03/12, 84020900039

- --B403070409 Summary of B40216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list soci HILLER, M.A. Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 50-000,84/03/12,8402090039
- --B403070423 Transcript of B40216 conference in Wading River,NY re Transamerica Deiaval, Inc diesei generators Pp 1-82 - Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000,84/03/12.8402090039

V Operator Examinations

- 8403:20076 Forwards tables listing nuclear plant operating experience Tables detail experience as of 840305 & experience expected by Puel load Shift advisors if utilized will be from within util UTLEY.E E Carolina Power & Light Co 84/03/06 DENTON, HR
- UTLEY,E E Caroline Power & Light Co 84/03/06 DENTON,H R Office of Nuclear Reactor Regulation, Director 19pp 22590 208 24X Fiche 50-400,84/03/06,8403120076
- DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8402230207 Further response to FOIA request for documents re const flaws at facility Forwards documents listed in App A Documents also being placed in PDR & LPDR Review continuing FELTON.J M Division of Rules and Records 83/12/02 VADEN.T News & Observer/Raleigh Times, Raleigh, NC 3pp 22378 299 24X Fiche 30-400.83/12/02.8402230207
- --8402230226 Forwards Ofc of Inspector & Auditor "Inquiry into Alieged Omission of Line inspector Views from CP Hearing " No further distribution should be made outside of ofc Rept under Commission review GOSBICK, V Office of the Executive Director for Operations 78/11/15 DENTON Office of Nuclear Reactor Regulation, Director SHAPAR Office of the Executive Logal Director DAVIS Office of Inspection & Enforcement, Office of the Director 1p 22378 305 24% Fiche 30-400,83/12/02,8402230207
- --8402230239 Forwards Apps A.B.C & D to be included w/questions for Panel III re facility testimony Related info enci HURPHY.C E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/11/16 REIS.E J. Defice of the Executive Legal Director Sipp 22378 308 24X Ficha 50~400.83/12/02, 8402230207
- --8402230246 Ack 820510 conversation re allegations by facility employee D Jarvis, per Regional Ofc Instruction 2251, Rev 2, Paragraph 2 C (3) Case file encl MAXHELL, G Region 2, Office of Director 82/05/10 VORSE, J NRC -- No Detailed Affiliation Given 2pp 22379 032 24X Fiche 50-400, 83/12/02.8402230207
- --B40223024B Requests that Region iI civil insp personnel investigate allegations by unidentified individual re coatings during next routine insp at site Case chronology encl MAXHELL, 0 F Region 2, Office of Director 82/07/07 VORSE, J NRC No Detailed Affiliation Given 2pp 22379 034 24X Fiche 50-400, 83/12/02, 8402230207
- --8402230231 Met] maint requirements for Procedure AP-XIII-07,
 "in-Storage Insp & Maint " Equipment purchase order form
 enci
 " Caroline Power & Light Co 83/12/02 9pp 22379.040 24X
 Fiche 50-400,83/12/02,8402230207
- 8403160330 Informs that design & const QA program transmitted by 830509 ltr acceptable
 LEWIS,R C Division of Project & Resident Programs 84/02/24
 UTLEY,E E Carolina Power & Light Co ip 22660 102 24X
 Fichs 30-400.84/02/24,8403160330
- B402090017 Board Notification 84-038 forwards RJ Mattson 840123 mame to DO Eisenhut providing status update of NRC ections re Wastinghouse ECCS actuation logic EISENHUT.D 0 Division of Licensing 84/02/27 PALLADINO Commissioners 7pp 22546:007 24X Fiche.50-000.84/02/27, 840020017
- E NRC Bafety Evaluation Report (BER), supple & correspondence
- 8403050061 FOIA request for extant drafts of sections or portions of SER for plant & documents showing dissenting opinions of staff reviewers EDDLEMAN.W Eddleman, W 84/01/12 FELTON, J Division of Rules and Records 1p 22494 346 24X Fiche. 50-400, 84/01/12, 8403050061

- 8403050064 Partial response to FOIA request for extant drafts of sections of BER for plant & documents showing dissenting opinions of staff reviewers Forwards App A documents

 Documents also in PDR Search for addl documents in progress
 FELTON: J M Division of Rules and Records 84/02/07 EDDLEMAN, H
 Eddleman, W 4pp 22496 347 24X Fiche 50-400.08/02/07.8403030064
- --8205120076 Forwards request for addi info re organic matls & spent fuel pool cleanup sys FBAR sections BENAROYA V Chemical Engineering Branch 82/04/27 MIRAGLIA, F Licensing Branch 3 4pp 22496 351 24X Fiche 50-400, 84/02/07, 8403050064
- --8205270420 Forwards request for add1 info re fire protection program nameded to complete review Info needed by 82:102
 BENAROYA,V Chemical Engineering Branch 82:05/17 MIRAGLIA,F
 Licensing Branch 3 7pp 22497 015 24X Fiche 50-400,84/02/07,8403050064
- --8207140072 Submits branch input for draft SER Input assumes that plant meets design objective of App I
 OAMMILL.W P Heteorology & Effluent Treatment Branch B2/06/25
 MIRACLIA.F J Licensing Branch 3 57pp 22501 007 24X
 Fiche.50-400.84/02/07.8403050064
- --821109000B Forwards draft SER input re SRP Sections 2 5 1 on basic geology & seismic info, 2 5 2 on seismology & 2 5 2 3 on SSE No capable faults exist at or around site SSE & OBE adequate KNIOHT, J P Assistant Director for Comp & Structures Engineering (Pre 830201) 82/10/20 NOVAK.T M Assistant Director for Operating Reactors 21pp 22476 355 24X Fiche 50-400,84/02/07,8403050064
- --8211070035 Submits Core Performance Branch input to draft SER Confirmatory & open issues listed RUBENSYEIN, L B Assistant Director for Core & Plant Bystems 82/10/21 NDVAK, T M Assistant Director for Licensing 2pp 22497,022 24X Fiche 50-400,84/02/07.8403050064
- --8211110461 Advises that applicant has not responded to request for informed BER items concerning oil collection sys for reactor coolant pump, alternate shutdown capability, fire protection for safe shutdown & NUREG-0800

 BENARDYA, V Chemical Engineering Branch 82/10/28 KNIGHTON, O Licensing Branch 3 ip 22497 088 24X Fiche 50-400.84/02/07, 8403050064
- --8211160112 Forwards draft BER input re FBAR Sections 2 5 4 2 5 6
 Request for add1 info also encl Site visit necessary before
 end of yr to observe as-built conditions & implementation of
 dam safety monitoring plans
 LEAR.0 E Hydrologic & Geotechnical Engineering Branch 82/11/09
 KERRIQAN, J D Licensing Branch 3 40pp 22497 260 24X
 Fiche 50-400,84/02/07,8403050064
- --8211170249 Forwards draft BER input based on Auxiliary Bys Branch review of FBAR Unresolved items listed RUBENBTEIN:L B Assistant Director for Core & Plant Bystems, 82/11/04 NDVAK.T M Assistant Director for Licensing 165pp 22497 089 24X Fiche 50-400.84/02/07,8403050064
- --8211300017 Forwards Chemical Engineering Branch draft BER input re listed sections of FBAR through Amend 2 & 820802 ltr.based on SRP (NUREQ-0800) & NUREQ-0737. Item 11.8 3 Add1 info needed to complete review of post-accident sampling sys JOHNSTON, W V Assistant Director for Matls & Qual Engineering (Pre 830201) 82/11/17 NOVAW.T Assistant Director for Licensing 21pp 22497 300. 24X Fiche 50-400,84/02/07, 8403050064
- --8212160163 Forwards Structural Engineering Branch summary of FBAR review & draft BER input KNIGHT.JP Assistant Director for Comp & Structures Engineering (Pre 830201) 82/12/06. NOVAK.T M Assistant Director for Licensing 16pp 22497 346. R4X Fiche 50-400.84/02/07. 8403050064
- --8212160220 Forwards revised Hydrologic Engineering Bection SER input Revised input superscedes previous submittal transmitted by 821014 memo LEAR.0 E Hydrologic & Geotechnical Engineering Branch 82/12/03 KNIOHTON,0 Licensing Branch 3, 25pp 22497,321 24X Fiche: 50-400,84/02/07,8403050064.
- --8212300403 Forwards draft revised SER input to SRP Sections 2 5 1.
 2 5 2 & 2 5 3 re geology & seismology. Revision includes applicant commitment to install & operate free-field accelerometers
 KNIGHT.J P Assistant Director for Comp & Structures Engineering (Pre 830201) 82/12/21 LAINAS.G C Assistant Director for Licensing. 24pp 22497 362, 24X Fiche 30-400, B4/02/07, B403050064

- --8301140474 Forwards Equipment Qualification Granch input for SER Suppl 5 re environ qualification of mechanical & electrical equipment JGHNSTON. W V Assistant Director for Matls & Qual Engineering (Pre 830201) 83/01/10 NQVAK.T M Assistant Director for Licensing 3pp 22478 033 24X Fiche 50-400.84/02/07, 8403050064
- ~~8301260036 Forwards Meteorology & Effluent Treatment Branch input to draft SER Assumption that draft meets 10CFR30.App 1 objectives will be verified when fluidize bed dryer effluents calculated NUREG-0737. Item III D i i incomplete HOUSTON.R W Assistant Director for Radiation Protection 83701706 NOVAK.T M Assistant Director for Licensing 58pp 22500 310 24X Fiche 50-400.84/02/07.8403050064
- --8309060390 Forwards Equipment Qualification Branck SER input for anviron qualification of equipment important to safety KNIQHT, J P Assistant Director for Comp & Structures Engineering (Post 830201) 83/08/26 NOVAK.T M Assistant Director for Licensing 5pp 22498 036 24X Fiche 50-400.84/02/07.8403050064
- --8309200478 Forwards Gootechnical Engineering Section input to SER Input based on FSAR through Amend 9 Stability of 400-ft long retaining wall still open issue LEAR.0 Structural & Geotechnical Engineering Branch 83/09/02 KNIGHTON.0 Licensing Branch 3 76pp 22498 188 24X Fiche 50-400,84/02/07.8403050064
- --8309210098 Forwards Power Sys Branch SER for Chapters 8-10 of FSAR Issues requiring resolution include containment electrical penetrations, use of load sequence w/offsite power & frequency of testing of turbine valves RUBENSTEIN.L 8 Assistant Director for Core & Plant Bystems 83/08/31 NOVAK, T M Assistant Director for Licensing 80pp 22498 041 24X Fiche 50-400.84/02/07.8403030064
- --8309210116 Forwards SER input for FSAR Sections 4 2.4 3.4 4.15 4 1. 15 4 2.15 4 3.15 4 7 & 15 4 8 Confirmatory & open issues identified listed RUBENSTEIN.L S Assistant Director for Core & Plant Systems B3/09/01 NGVAW.T H Assistant Director for Licensing &9pp 22498 119 24% Fiche 50-400,64/02/07,6403050046
- --8309220302 Forwards hydrologic engineering input to BER One open item exists re potential for intense local precipitation to flood safety-related structures Tech Spec defining anti-sediment deposit procedure required JOHNSTON: W V Assistant Director for Matls, Chem & Environ Technology (Post 830201) 83/09/14 NOVAK: T M Assistant Director for Licensing 24pp 22479 188 24X Fiche 50-400.84/02/07.8403050064
- --8309260018 Forwards SER supporting geology & seismology at facility KNIGHT.J P Assistant Director for Comp & Structures Engineering (Post 830201) 83/09/08 NOVAK.T M Assistant Director for Licensing 44pp 22498 264 24X Fiche 50-400.84/02/07, 8403050064
- --8309260421 Forwards structural engineering BER sections based on review of F8AR through Amend 9. Three open & one confirmatory items remain Resolution of open/confirmatory items will be addressed in subsequent BEER KNIGHT.J P Assistant Director for Comp & Structures Engineering (Post B30201) B3/09/15 NOVAK.T M Assistant Director for Licensing 16pp 22499 212 24X Fiche 50-400,84/02/07,8403050064
- --8309260482 Forwards Auxiliary Sys Branch SER input based on review of all amends to FSAR up to Amend 9 & applicants 830418,0603, 30,0703,15 & OBI2 responses Summary of unresolved issues to be used as basis for meeting w/applicant also encl RUBENSTEIN: L S Assistant Director for Core & Flant Systems 83/09/14 NOVAK, T M Assistant Director for Licensing 251pg 22498 308 24X Fiche 50-400,84/02/07,8403050064
- --8309290412 Forwards Effluent Treatment Bys Section input to SER reflecting changes in status of open items based on 830824 meeting MULLER, D.R. Assistant Director for Radiation Protection 83/09/14. NOVAK, T.M. Assistant Director for Operating Reactors 60pp 22500 190 24X Fiche 50-400,84/02/07.8403050064
- --8309290474 Forwards SER on plant personnel training Util training programs for licensed reactor operators acceptable Util inadequately addressed training of shift technical advisor (STA) when STA absent from STA duties RUSSELL.W Division of Human Factors Safety 83/09/21. NOVAK.T Assistant Director for Licensing 21pp 22479 228 24X Fiche 50-400,84/02/07,8403050064

- --B310130378 Forwards branch SER input re status of unresolved issues. In response to ALAB-444 decision Issues A-45 & A-47 listed as confirmatory items rather than open items W/o encis KNIEL.K Generic Issues Branch B3/10/04 KNI6HTON, 0 Licensing Branch 3 26pp 22499 249 24X Fiche 50-400.84/02/07.8403050064
- --B310170099 Forwards Chemical Engineering Branch proposed license condition re TMI Item II B 3. "Post-Accident Sampling Sys "Contents of draft SER should be used for SER JOHNSTON.W V Assistant Director for Matis. Chem & Environ Technology (Post B30201) B3/10/06 NOVAK.T M Assistant Director for Licensing 3pp 22499 279 24X Fiche 50-400, B4/02/07. B403050064
- --B310310445 Forwards results of review of Sections 5 2 2.5 4 7.6 3 % 15 through Amend 10 of FSAR Open issues which will be summarized in later SER suppl listed HDUSTON,R W Assistant Director for Reactor Safety NDVAX.T M Assistant Director for Licensing 49pp 2247 Fiche 50-400. B4/02/07. B403050064
- --83iii00049 informs that applicant is to submit calculation of ultimate strength capacity of containment bldg under internal pressure as resolution of SER outstanding confirmatory structural item Marked-up SER input enci

 LEAR.O Structural & Geotechnical Engineering Branch 83/10/28

 KN16HTON.O Licensing Branch 3 3pp 22500 024 24X

 Fiche 50-400.84/02/07.8403050064
- --83iiii0263 informs of cioseout of listed sections of 830714 SER based on new info Updated sections enci Closeout of addi open items.including NUREO-0612 info.will take place as acceptable info made available RUBENSTEIN.L 8 Assistant Director for Core & Pient Systems 83/10/28 NOVAX.T M Assistant Director for Licensing 49pp 22499 337 24X Fiche 50-400.84/02/07.8403050064
- --8311140004 Advises that, due to need to coordinate affort w/Auxiliary Sys Branch, revised SER to be submitted on 831127 will still contain listed fire protection open items JOHNSTON, N V Assistant Director for Matls, Chem & Environ Technology (Post 830201) 83/11/03 NOVAK, T Assistant Director for Licensing 2pp 22500 030 24X Fiche 50-400,84/02/07,8403050064
- --83iii60283 Forwards revised SER input on confirmatory item re ultimate strength capacity of concrete containment bldg Item resolved LEAR, G Structural & Geotechnacai Engineering Branch 83/11/14 KNIGHTON, O Lacensing Branch 3 3pp 22500 047 24% Fiche 50-400,84/02/07,8403050064
- ~-B311160367 Informs that draft SER Section i7 acceptable except in area of items subj to iOCFR50, App B.OA program during operations phase Info re current status & acceptability of OA program encl
 PARTLON, J © Division of OA, Safeguards & Inspection Programs (Post 830103) 83/11/09 YOUNGBLOOD, B J Licensing Branch 1
 3pp 22500 027 24X Fichs 50-400, 84/02/07, 8403030064
- --8311270301 Forwards revised Hydrologic Engineering Input to SER New Tech Spec requirement developed re watertight doors for safety-related bldgs
 JOHNSTON.W V Division of Engineering Technology 83/11/10
 NOVAX.T M Assistant Director for Licensing 15pp 22500 032
 24X Fiche 50-400.84/02/07.8403050064
- --8311270352 Updates SER re stability of retaining wail west of fuel handling bidg Based on applicant 830919 submittals, stability cannot be assured due to lack of listed info Final SER update enci
 LEAR, GE Hydrologic & Geotechnical Engineering Branch 83/ii/18
 KNIGHTON. O Licensing Branch 3 5pp 22501 049 24X
 Fiche 50-400, 84/02/07, 8403050044
- --B3i208018B Forwards efficient treatment sys section input to SER Oper items include method for determining releases of noble gases from mechanical vacuum pumps & radioactivity monitor on discharge from swc water sys.

 MULLER: DR Assistant Director for Radiation Protection 83/11/18 NOVAH, I M Assistant Director for Licensing Sipp 22300 137 24X Fiche 50~400,84/02/07,8403050064
- --8312120002 Lists closed out open items in SER forwarded on 830914 & sections w/remaining open items
 RUBENSTEINL S Assistant Director for Core & Plant Systems
 83/11/17 NOVAK.7 M Division of Licensing 88pp 22500 050
 24X Fiche 50-400.84/02/07.8403050064

- --8312120445 Forwards input to SER, consisting of emergency plan evaluation rept & responses to NUREG-0737, Items
 III A 1 1. iiI A 1 2 & III A 2 re emergency preparedness
 MATTHEWS, D B Division of Emergency Preparedness & Engineering Response (Post 830103) 83/11/30 KNICHTON, Q Licensing Branch
 3 36pp 22501 058 24X Fiche 50-400.84/02/07.8403050064
- --8312140429 Submits review of draft SER response to Open Item 47 on RCS vents Proposed design conforms w/criteria outlined in NUREO-0737 clarification pertaining to electrical power supplies to vent valves
 SRINIVASAN.M Power Systems Branch 83/11/23 SHERON.B Reactor Systems Branch 2pp 22501 036 24X Fiche 50-400.84/02/07, 8403030064
- --B312230278 Forwards revised SEER re fire protection Listed Items remain open
 JOHNSTON, W V Assistant Director for Matls, Chem & Environ
 Technology (Post B30201) B3/12/14 NDVAK, T Assistant Director
 for Licensing 12pp 22501 094 24X Fiche 50-400,84/02/07,
 B403050064
- F Security, medical, emergency & fire protection plans
- 8403i60283 Advises of 840316 meeting in Region Ii ofc to discuss App R requirements & results of recent App R insps Attendance should be limited to six util employees LEHIS:R C Division of Project & Rosident Programs 84/03/02 UTLEV.E E Carolina Power & Light Co ip 22660 109 24X Fiche: 50-000,84/03/02,8403160283
- G Adjudicatory correspondence
- 8402230207 Further response to FOIA request for documents re const flaws at facility Forwards documents listed in App A Documents also being placed in PDR & LPDR Review continuing FELTON, J M Division of Rules and Records 83/12/02 VADEN, T News & Observer/Raieigh Times, Raieigh, NC 3pp 22978 297 24X Fiche 50-400,83/12/02,8402230207
- --Bi04210125 Discusses implications of Ofc of inspector & Auditor 781012 interview w/facility ASLB Ofc of Inspector & Auditor attempted to probe thought processes of & require justification from Board re action taken in adjudication YORE, J R Atomic Safety and Licensing Board Panel 78/10/19 HENDRIE, J M Commissioners 3pp 22378 302 24X Fiche 30-400, 83/12/02, 8402230207
- --8402230237 Discusses investigation by Ofc of Inspector & Auditor (OlA) re facility proceeding ABLAB unwilling to be interrogated by OlA Hany questions in OlA interrogation of members of ABLB manifestiy improper RDSENTHAL.A S Atomic Safety and Licensing Appeal Panel 78/10/20 HENDRIE Commissioners 2pp 22378 306 24X Fiche 50-400, 83/12/02, 8402230207
- 8402070034 Forwards corrected copy of Page 10 of NRC B40130 response in opposition to Eddleman proffered Contentions 169,170, 171 & 172 re safety parameter display sys MOORE. J E Hearing Branch 1 84/01/31 KELLEY, J L , CARPENTER, J H , BRIGHT, 9 O Atomic Safety and Licensing Board Panei 1p 22102 361 24X Fiche 50-400,84/01/31,8402070054
- --B402070037 Corrected Page iO of response opposing Eddieman proffered Contentions 169,170,171 & 172 re safety parameter display sys * Hearing Branch 1 B4/01/30 Atomic Safety and Licensing Board Panel 1p 22102 362 24X Fiche 50-400,84/01/31, B402070034
- B402290081 Amended Certificate of Svc for applicant B40224 motion for reconsideration or ciarification of ASLB memorandum k order on health effects contentions Certificate of Svc encl BAXTER, T A Carolina Power & Light Co
- 8403020182 Hotion for summary disposition of Joint Intervenor Contention V re continuous air monitors & portable air samples No genuine issue of matl fact exists & applicant entitled to favorable decision Related correspondence ANDERSON, P H Carolina Power & Light Co ANDERSON, P H Shaw, Pittman, Potts & Troubridge B4/02/27 Atomic Safety and Licensing Board Panel 14pp. 22440 193 24X Fiche 50-400,84/02/27,8403020182
- --B40302018B Statement of matl facts as to which there is no genuine issue to be heard on Joint Contention V Related correspondence
 ANDERSON,P H Carolina Power & Light Co ANDERSON,P H. Shaw, Fittmen, Potts & Trowbridge 84/02/27 Atomic Safety and Licensing Board Panel 3pp 22440 207 24X Fiche 50-400, B4/02/27,8403020182

- --B403020192 Affidavit of WH Wilkie in support of applicant motion for summary disposition of Joint Intervenors Contention V Certificate of Svc encl Related correspondence WILKIE,W H Carolina Power & Light Co B4/02/24 19pp 22440 210 24X Fiche 50-400,84/02/27,8403020182
- 8403010263 Response opposing W Eddleman motion to admit Contention 5842d) on financial qualifications of co-applicants ASLB has no basis or authority to reconsider original ruling on contention & motion must be denied Certificate of Svc encl G'NELL,J H Carolina Power & Light Co G'NELL,J H Shaw. Fittman, Potts & Trowbridge 84/02/28 Atomic Safety and Licensing Board Panel 7pp 22432 258 24X Fiche 50-400,84/02/28.
- 8403070051 Forwards emergency response plan in support of facility Plan encompasses state plan & plans of Chatham Harnett, Lee, & Wate Counties W/o encl Related correspondence HOLLAR, D & Carolina Power & Light Co 84/02/28 KELLEY, J L , BRIGHT, G O , CARPENTER, J H Atomic Safety and Licensing Board Panel 2pp 22541 276 24X Fiche 50-400,84/02/28,8403070051
- B403070055 Motion for summary disposition of Eddleman Contention 15AA re capacity factor No genuine issue of matl fact exists Related correspondence HOLLAR.D E Carolina Power & Light Co 84/02/28 Atomic Safety and Licensing Board Panel 15pp 22541 123 24x Fiche 50-400,84/02/28,8403070055
- --8403070058 Statement of mat1 facts as to which there is no genuine issue
 HOLLAR, D E Carolina Power & Light Co 84/02/28 Atomic Safety
 and Licensing Board Panei 3pp 22541 138 24X
 Fiche 50-400, 84/02/28, 8403070055
- --B403070059 Affidavit of RH Koppe in support of applicant motion for summary disposition of Eddleman Contention 15AA Certificate of Svc enci Related correspondence KODPE.R H Carpiina Power & Light Co 84/02/27 24pp 22541 141 24X Fiche 50-400,84/02/28,8403070055
- 8403140102 Policy statement on environ qualification of safety-related electrical equipment Commission will conduct notice & comment rulemaking proceeding to delete formally 820630 compliance deadline Certificate of Svc enci
 CHILK.S J Office of the Secretary of the Commission 84/03/01
 37pp. 22624 164 24X Fiche 50-400,84/03/01,8403140102
- 8403070134 Amend to 840113 motion for protective order preventing public disclosure of employee info sought by discovery request of W Eddleman Order issued by ABLB appropriate & necessary, Certificate of Svc encl Related correspondence BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 84/03/02 Atomic Safety and Licensing Board Panel lipp 22538 254 24X Ficha 50-400, 84/03/02, 8403070134
- B403070225 Requests questions re Contention 41 requiring discovery responses be filed before B40315 Becond round discovery will be given if protective order issue not resolved before B40315 W/Certificate of Svc Related correspondence BAXTER: TA Shaw: Pittman, Potts & Trowbridge BAXTER: TA Capolina Power & Light Co 84/03/02 EDDLEMAN.W Eddieman. W 4pp 22541 300 24X Fiche 50-400,84/03/02,8403070225
- B403140159 Response opposing W Eddleman 840213 motion for admission of Contention 58 (2D) re financial qualifications Eddleman argument inaccurate W/NRC 840227 statement of policy MDDRE.JE Hearing Branch 2 84/03/05 Atomic Safety and Licensing Board Panel 5pp 22624 001 24X Fiche 50-400,84/03/05.84/03/40159
- --8403140163 Response in support of applicant 840207 motion for summary disposition of Eddleman Contention 83/848 on grounds that there is no genuine issue of mat! fact to be litigated MODRE, J E Hearing Branch 2 84/03/05 Atomic Safety and Licensing Board Panel 10pp 22624 006 24X Fiche 50-400, 84/03/05, 8403140159
- --8403140168 Affidavit of JC Lehr supporting NRC response to applicant motion for summary disposition of Eddleman Contention 83/848 Applicant assessment consistent w/NRC conclusion in FEB. W/Certificate of 8vc LEHR, J C Environmental & Hydrologic Engineering Branch 84/03/03 11pp 22624 016 24X Fiche 30-400,84/03/05.8403140159
- 8403120002 Supplemental ensuer to applicant interrogatories & requests for production of documents on Joint Contentions 1 & VII Certificate of Syc encl Related correspondence PAYNE:M T Kudzu Alliance PAYNE:M T Edelstein & Payne PAYNE:M T. Joint Intervenors Shearon Harris 84/03/07 4pp 22589: 298 24X Fiche 50-400, 84/03/07, 8403120002

- B403130156 Motion for summary disposition of Joint Intervenor Contention VI re monitoring sys No genuine issue of matifact exists & applicant entitled to favorable decision Related correspondence ANDERSON.P H Carolina Power & Light Co ANDERSON.P H Shaw, Pittman, Potts & Trowbridge 84/03/09 Atomic Safety and Licensing Board Panel 18pp 22599 003 24X Fiche 50-400.84/03/09.8403130136
- --0403130164 Affidavit of WH Wilkie & RL Shearin in support of applicant motion for summery disposition of Joint Intervenor Contention VI Certificate of Svc ancl WILLIE, W H., SHEARIN, R V Carolina Power & Light Co 84/03/08 122pp 22599 021 24X Fiche 50-400,84/03/09,8403130156
- B403130447 Response to W Eddleman B40307 motion to declare util 840228 motion untimely Eddleman motion frivolous, insulting & unfounded Related correspondence
 O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 84/03/07 Atomic Safety and Licensing Board Panel 5pp 22613 182 24X Fiche 50-400,84/03/09,8403130447
- --8403130457 Response opposing W Eddleman 840307 motion to allow filing of affidavit of JO Blackburn Good cause undemonstrated Certificate of Evc enci D'NEILL. J H Carolina Power & Light Co Pittman. Potts & Trowbridge 84/03/09 Atomic Safety and Licensing Board Panel App 22613 187 24X Fiche 50-400.
- B403i6001B Memorializes 840313 telcon extending time for discovery requests on safety contentions & for response to applicant motion for summary disposition Certificate of Svc encl BAXTER, T A Shaw, Pittman, Potts & Troubridge DAXTER, T A Carolina Power & Light Co 84/03/13 EDDLEMAN, W Eddleman, W 4pp 22653 360 24X Fichs 50-400.84/03/13.8403160018
- 8403170137 Forwards applicant & NRC joint motion to withdraw Contentions 2,3 & 6 re security plan Agreement exchanged resolving issues FLYNN.8 F Carolina Power & Light Co B4/03/14 KELLEY.J L , BRIGHT.0 D , CARPENTER.J H Atomic Safety and Licensing Board Panel 2pp. 22666 310 24X Fiche 50-400.84/03/14.8403190137
- --8403170141 Joint motion to withdraw security plan Contentions 2.3 % 6 Certificate of Svc enci RUMKLE.J D Joint Intervenors - Shearon Harris FLYNN, S F Carolina Power & Light Co BARTH.C A Hearing Branch i 84/03/14 Atomic Safety and Licensing Board Panel 3pp 22666 312 24X Fiche 50-400,84/03/14.8403190137
- B403200030 Supplemental responses to W Eddieman general interrogatories & interrogatories on Contentions 41 & 65 Certificate of Svc ancl. Related correspondence
 BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Troubridge 84/03/14 Eddieman, W 7pp 22683 345 24X
 Fichs 50-400.84/03/14,8403200030
- B403190025 Memorandum & order reaffirming rulings on response to 840127 order re health effects
 BRIGHT.G O. CARPENTER, J. H. KELLEY, J. L. Atomic Safety and Licensing Board Panel B4/03/15 Office of the Executive Legal Director 20pp 22666 085 24X Fiche 50-400.84/03/15.8403190025
- B403190033 Interrogatory to Joint Intervenors re Joint Contention VII Response in writing required by 840403 BARTH: C A Hearing Branch i 84/03/15 Joint Intervenors -Shearon Harris ip 22666 188 24X Fiche 50-400,84/03/15, 8403190053
- --B40319005B Interrogatories to W Eddleman re Eddleman Contentions 11.45, 67 & iid Response in writing required by 840403 Certificate of Svc encl
 BARTH, C A Hearing Branch i 84/03/15 EDDLEMAN, W Eddleman, W 8pp 22466 189 24X Fiche 50-400,84/03/15,8403190033
- 8403200054 Interrogatories to applicant on admitted security contention Enci withheld (ref 10CFR73 2i) W/Certificate of Svc Related correspondence RUNKLE,J Joint Intervenors Shearon Harris 84/03/15 Carolina Power & Light Co 3pp 22698 273 24X Fiche 50-400,84/03/15, 8403200054
- B403200117 Interrogatories & request for production of documents on W Eddlaman Contention 132C(11) second set Certificate of Svc entl Related correspondence CARROW.H Carolina Power & Light Co 94/03/15 Eddleman, W 8pp 22685 336 24X Fiche 50-400.84/03/15,8403200117

- 1403200135 Notice of ER Bleather & UR Maples depositions on 840327 in Raleigh.NC Cortificate of Svc encl Related correspondence CARROW.H Carolina Power & Light Co CARROW.H Shaw. Pittman. Potts & Troubridge 84/03/15 3pp 22677 161 24X Fiche 50-400.84/03/15.8403200135
- 1403210120 Informs that part of transcript of B40308 telcon reidentification of persons in room at time of cell missing DARTH.C A Hearing Branch i 84/03/16 KELLEY.J L. BRIGHT.O O. CARPENTER.J H. Atomic Bafety and Liconsing Board Penel. ip 22707 179 24X Fiche 50-400,84/03/16.8403210120
- 403210051 Order approving joint motion to withdraw security plan Contentions 2.3 & 6 Cooperation commended KELLEY, J. L. CARPENTER, J. H. BRIGHT, G. O. Atomic Bafety and Licensing Board Fanel. Bi-0/3/19 Office of the Erecutive Legal Director. 2pp. 22704 342 24X Fiche 50-400,84/03/19,8403210051
- 403220223 Nation to quash applicant notice to take deposition of Bleacher & Maples Unlikely applicants can meet even threshhold showing of good cause Certificate of Svc encl Related correspondence RUNKLE.J Joint Intervenors Shearon Harris DBS 045 84/03/Atomic Sefety and Licensing Board Panel App 22719 003 24) Fiche 50-400.84/03/19.8403220223
- 84/03/19.
- 403220261 Interrogatories & request for production of documents to Joint Intervenors (seventh set) Certificate of Svc enci Related correspondence
 0'NGILL, JH Carolina Power & Light Co O'NEILL, JH Shaw, Pittman, Potts & Trowbridge. DGB 058 84/03/19 Joint Intervenors Shearon Harris 21pp 22719 110 24X
 Fiche 50-400,84/03/19,8403220261
- i03260327 Interrogatories & request for production of documents re Eddlemen Contentions 9 & 11 (second set) Certificate of Svc enci Related correspondence SWIGER.M A Carolina Power & Light Co SWIGER.M A Shaw. Pittman. Potts & Troubridge DSB 104 84/03/23 Eddleman. W 14pp 22760.143 24X Fiche 50-400.84/03/23,8403260327
- O3240328 Responds to 840317 & 17 ltrs re estension to file discovery requests, welder info confidentiality & interrogatory answers Svc list enci Related correspondence.

 BAXTER, T A Shaw, Pittman, Potts & Troubridge BAXTER, T. A Carolina Power & Light Co DSP 103 84/03/23 EDDLEMAN, W Eddleman, W 4pp 22760 137 24X Fiche 50-400,84/03/23,8403260328
- O3260348 Responses to general interrogatories & interrogatories on Contention 65 (seventh set) Related correspondence
 BAXTER: 7 A Carolina Power & Light Co BAXTER: 7 A Shaw, Pittman, Potts & Trowbridge DSS 102 84/03/23 Eddleman, H 47pp.
 22760 190 24X Fiche 50-400.84/03/23,8403260348
- 8403260354 Response to request for production of documents (Contention 65) Certificate of Svc encl BAXTER.7 A Carolina Power & Light Co BAXTER.7 A Shipition Potts & Troubridge 84/03/23 Eddleman, W 22760 237 24X Fichs 50~400,84/03/23,8403260348 Shaw,
- D3270319 Response opposing W Eddleman 840307 motion to allow filing P affidavit of JO Blackburn Affidavit is untimely suppl to settition re need for power & alternative energy sources certificate of Svc encl HORREJ E Hearing Branch i DSB 133 84/03/23 5pp 22789-023 4X Fiche 50-400,84/03/23,8403270319

- J3270321 Clarification of staff response in support of applicant action for summary disposition of Joint Intervenors contention IV re TLDs contention IV re TLDs 130 94/03/23 Atomic Bafe and Licensing Board Panel 3pp 22789.020 24X Tiche: 50-400.84/03/23.8403270321 Atomic Bafetu
- N3270333 Response in support of applicant 840227 motion for summary isposition of Joint Intervenors Contention V re callor of it munitors Related correspondence ARTH.C A Hearing Branch 1 DSB 127 B4/03/23 Atomic Safety nd Licensing Board Panel 2pp. 22789 006 24X iche 50-400.84/03/23.8403270333
- I4D3270338 Affidaylt of 8 Block in support of summary disposition of Joint Contention V Certificate of Svc encl BLOCK. S Division of Systems Integration (post 811005) 84/03/15 8pp 22789 008 24X Fiche 50-400.84/03/23,8403270333.
- 3270327 Advises that term job experience, used in 840314 discovery exponses, includes only welding experience Related orrespondence
 AXTER.T A Shaw, Pittman, Potts & Troubridge BAXTER.T A, aroline Power & Light Co DSB 144 84/03/26 EDDLEMAN. W, ddleman, W. 3pp 22789 016 24% Fiche 50-400.84/03/26.8403270327

- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 8403140302 Discusses seismology (saues in OL review Extremely conservative values established for OBE & 88E, Plant site is as nearly aseismic as any site in sestern US.

 MAXWELL, J C. Mexwell, J C MAXWELL, J C ACRS Advisory Committee on Reactor Safeguards 84/01/05, KERR: M ACRS Advisory Committee on Reactor Safeguards 1p. 22635 317. 24X Fiche 50-400,84/01/05,8409140302.
- 8401300121 Summarizes ACRS 285th meeting on 840112-14 ra raview of OL application control room design & tube degradation investigation of allegations re GA requested EBERBOLE, J C ACRS Advisory Committee on Reactor Safeguards 84/01/16 PALLADINO, N J. Commissioners 3pp. 22044 023 24X Fiche 50-400,84/01/16,8401300121
- O Inspection reports, IE Bulletins & correspondence
- 8403070179 Ack receipt of 840208 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/83-36, Implementation of corrective actions will be examined during future insps VERRELLI.D M Division of Project & Resident Programs B4/0 UTLEY, E E Carolina Power & Light Co ip, 22547-276, 24X Ficha 50-400.84/02/22,8403070179.
- --8403070193 Forwards IE Insp Repts 50-400/83-36 & 50-401/83-36 on 831120 & 1220 & notice of violation VERRELLID M. Division of Project & Resident Programs 84/01/10. UTLEY: E E Carolina Power & Light Co 2pp 22547-279 24X Fiche 50-400,84/02/22,8403070179
- --8403070199 IE Insp Repts 50-400/83-36 & 50-401/83-36 on 831120-1220 Violation noted: failure to protect equipment from rainwater entering reactor auxiliary bldg from roof MAXHELL.0 F , PREVATTE.R.L Region 2, Office of Director BENIS.P R Division of Project & Resident Programs 84/01/09. 9pp 22547 282 24X Fiche 50-400.84/02/22.8403070179.
- 8403070074 Ack receipt of 840118 & 27 Itrs informing NRC of steps taken to correct violations noted in IE Insp Rept 30-400/83-35 VERRELLI.D M Division of Project & Resident Programs 84/02/23, UTLEY, E. Carolina Power & Light Co. ip. 22545 348, 24X Fichs 50-400,84/02/23,8403070094.
- --B403070100 Forwards IE Insp Repts 50-400/83-35 k 50-401/83-35 on 831129-1202 k notice of violation VERRELLI.D M Division of Project & Resident Programs 83/12/20, UTLEY, E E Carolina Power & Light Co. 2pp 22545, 253, 24X Fiche: 50-400, 84/02/23, 8403070094.
- --8403070105 IE Imsp Repts 30-400/83-35 & 50-401/83-35 on B31129-1202 Violation noted failure of as-built drawings to reflect actual piping configuration KLEINBORDE, WP Region 2: Office of Director BLAKE, J J. Division of Engineering & Operational Programs. 83/12/13. 9pp 22345 356 24X Fiche 50-400.84/02/23.8403070094
- 8 Reportable occurrences, LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Cimpel NPS-4 TWT valve, to close Encl 1tr dtd 840203 sent to listed utils GE notified of affected units in BMR plants
 THEROUX R R Terry Corp. 84/02/22 WOODRUFF,R W, Director's
 Office, Office of Inspection and Enforcement App. 22706:327 24X
 Fiche:50-000,84/02/22,8403210032
- B403010207 Forwards "Investigation of Types AF & AE Piston Bkirts," per Transamerica Delavai, inc Owners Group program commitments.
 Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations
 MUSELER,N J TDI (Transamerica Delavai, Inc.) Owners Group B4/02/27 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 22434,090 24X Fiche 50-000,84/02/27,8403010207.
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Deleval, Inc. emergency diesel generators, MUBELER, W. J. TDI (Transamerica Deleval, Inc.) Dwners Group 84/02/28 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 42pp. 22435, 177. 24X Fiche: 50-000, 84/02/29, 8403010218
- 8403140048 Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Trensamerica Delaval, Inc Diesel Generators Owners Group Program Plan," to resolve Concerns W/emergency dissal generators

 HUSELER, W J. Long Island Lighting Co. 84/03/02 DENTON, H. R.

 Office of Nuclear Reactor Regulation, Director. 2pp 22626:062

 24X Ficha 30-000, 84/03/02, 8403140048

- --8403140095 "Transamerica Delaval, Inc Diesel Generators Dwners Group Program Plan " * TDI (Transamerica Delaval, Inc) Dwners Group 84/03/02 261pp 22628 223 24% Fiche 50-000.84/03/02.8403140048
- 8402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Dwners Group Distribution list encl.
 EIBENHUT, D. 9. Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fiche 50-000,84/03/12,8402090039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda/MD re problems w/emergency diesel generators CARUSO,R. Licensing Branch 2 84/02/27 O'REILLY,J P NRC No Detailed Affiliation given dep 22708 006 24X Fichs: 50-000,84/03/12,8402090039
- ---8403060534 Transcript of 840210 meeting w/Transamerica Deiaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesei generators # NRC - No Detailed Affiliation Oiven 84/02/10 147pp 67201.008 24X Fiche 50-000,84/03/12,8402070039
- --8403070409 Summary of 840216 meeting w/Transamerica Delayal, Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl
 MILLER, M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp. 22708 161 24X Fiche 50-000,84/03/12,8402090039
- --8403070423 Transcript of 8402i6 conference in Wading River,NY re Transamerica Delaval.Inc diesel generators Pp i-82 * Commissioners 84/02/16. 840p 22708 169 24X Fiche, 30-000, 84/03/12. 8402090037.
- B403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators.

 MUSELER, W. J. Long Island Lighting Co 84/03/12 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 22632,074 24X Fiche: 50-000,84/03/12,8403140050.
- B403150133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Arm Capscrew Btress Analysis Rept " Capscrew design adequate for applicable angines & svc conditions MUSELER, W. J. TDI (Transamerica Delaval, Inc.) Owners Group B403/13, DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 22639-270 24X Fiche 50-000, 84/03/13, 8403150133
- E403200222 Responds to B40214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number model & svc number, customer name & address, rating, date shipped & date started encl
 MATHEMB, C B. Transamerica Deiaval, Inc 84/03/16 EISENHUT, D Q
 Division of Licensing 20pp. 22691;179 24X Fiche 50-000, 84/03/16, 8403200222
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis." prepared by 8&W for Transamerica Delaval, Inc (TDI) Diesel Generator Owners Group.

 MUSELER, H J TDI (Transamerica Delaval, Inc.) Owners Group.

 84/03/23, DENTON, H R Office of Nuclear Reactor Regulation, Director. 2pp. 22774,001. 24X Fiche 50-000,84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delayal diesel generators List of suggested meeting topics encl.
 MCGAUGHY, J. P. TDI (Transamerica Delayal, Inc.) Duners Group 84/03/23 DENTON, H. R. Defice of Nuclear Reactor Regulation, Director 4pp 22769-133, 24X Fiche 50-000,84/03/23,8403270134
- T. Hearing transcripts on non-antitrust matters
- B403120121 Transcript of 840308 telephone conference in Bethesda, MD Pp 751-807 * Commissioners 84/03/08 58pp 22586:119 24X Fiche:30-400,84/03/08,8403120121
- 8402070037 Board Notification 84-052. forwards meeting summaries containing transcripts of 840210 k 16 meetings between NRC & Transamerice Delayal. Inc (TDI) Owners Group Distribution list encl EIBENHUT, D G. Division of Licensing 84/03/12 PALLADINO Commissioners, 3pp 22708.001 24X Fiche: 50-000.84/03/12, 8402070037

- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, HD re problems w/emergency diesel generators CARUSO, R Licensing Brench 2 84/02/27 O'REILLY, J P NRC No Detailed Affiliation Given 6pp 22708 006 24X Fiche 30-000, 84/03/12, 8402090039
- --B403060554 Transcript of B40210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given B4/02/10 147pp 67201 008 24X Fiche 50-000,84/03/12,8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Deiaval, inc Owners Group in Hading River.NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list enci hiller, M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp. 22708 161. 24X Fiche 50-000,84/03/12,8402090039
- --B403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval, Inc diesel generators Pp 1-82 + Commissioners 8402716 84pp 22708 169 24X Fiche 50-000,84/03/12,8402090039
- DOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT. UNIT 3

 A Application/construction stage documents & correspondence
- 8402230207 Further response to FOIA request for documents re const flaws at facility. Forwards documents listed in App A Documents also being placed in PDR & LPDR Review continuing FELTON, J M Division of Rules and Records 83/12/02 VADEN. T News & Observer/Raleigh Times. Raleigh. NC 3pp 22378 299 24X Fiche 50-400.83/12/02.8402230207
- --B402230226 Forwards Ofc of Inspector & Auditor "Inquiry into Aileged Omission of Line Inspector Views from CP Hearing " No further distribution should be made outside of ofc Rept under Commission review GOSSICK, L V Office of the Executive Director for Operations 78/11/19 DENTON Office of Nuclear Reactor Regulation, Director ip. 22378 305 24X Fiche 50-400,83/12/02.8402230207
- --8402230239 Forwards Apps A.B.C & D to be included w/questions for Panel III re facility testimony Related info enci HURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 78/i1/16 REIS.E J Office of the Executive Legal Director. Sipp 22378 308 24X Fiche 50-400,83/12/02. 8402230207
- --8402230251 Matl maint requirements for Procedure AP-XIII-07,
 "In-Storage Inap & Maint " Equipment purchase order form
 encl
 * Carolina Power & Light Co 83/12/02 9pp 22379 040 24X
 Fiche 50-400,83/12/02,8402230207.
- E NRC Bafety Evaluation Report (BER), supplis & correspondence
- 8203270420 Forwards request for add1 info re fire protection program needed to complete review Info needed by 821102 BENARDYA, V Chemical Engineering Branch 82/05/17 HIRAQLIA, F Licensing Branch 3 7pp 22497 015 24X Fiche 50-402, 84/02/07, 8403050064.
- O Adjudicatory correspondence
- 8402230207 Further response to FOIA request for documents re const flaws at facility. Forwards documents listed in App A Documents also being placed in PDR & LPDR Review continuing FELTON, J M Division of Rules and Records 83/12/02 VADEN. T News & Observer/Raieigh Timas, Raieigh, NC 3pp 22378 299 24X Fiche 30-400,83/12/02,8402230207
- --Bi04210125 Discusses implications of Ofc of Inspector & Auditor 761012 interview u/facility ABLB Ofc of Inspector & Auditor attempted to probe thought processes of & require justification from Board re action taken in adjudication. YORE, J.R. Atomic Safety and Licensing Board Panel 78/10/19 HENDRIE, J M. Commissioners Spp. 22378 302, 24X Fiche 50-400, 83/12/02, 8402230207.
- --8402230237 Discusses investigation by Ofc of Inspector & Auditor (QIA) re facility proceeding ASLAB unwilling to be interrogated by DIA Many questions in OIA interrogation of members of ASLB manifestly improper ROBENTHALA B. Atomic Safety and Licensing Appeal Panel 78/10/20 HENDRIE Commissioners 2pp 22378 306 24X Fiche 50-400,83/12/02,8402230207

- D Advisory Committee on Reactor Safeguards reports & correspondence
- 8401300121 Summarizes ACRS 285th meeting on 840112-14 re review of OL application; control room design & tube degradation investigation of allegations re GA requested EBERSQLE.J C. ACRS Advisory Committee on Reactur Safeguerds. 84/01/16 PALLADINO,N J. Commissioners 3pp 22044 023 24X Fiche 30-400.84/01/16.8401300121.
- DOCKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4
- A Application/construction stage documents & correspondence
- 8402230207 Further response to FOIA request for documents re const flaws at facility Forwards documents listed in App A Documents also being placed in POR & LPDR Review continuing FELTON, J M Division of Rules and Records 83/12/02 VADEN, T News & Observer/Raiosgh Times, Raieigh, NC 3pp 22378 299 24; Fiche 50-400.83/12/02.8402230207
- ---8402230226 Forwards OPC oF Inspector & Auditor "Inquiry into Alleged Omission of Line Inspector Views from CP Hearing " No further distribution should be made outside of ofc Rept under Commission review GOSSICK.L.V Dffice of the Executive Director for Operations 78/11/15 DENION Office of Nuclear Reactor Regulation. Director ip 22378.305 24% Fiche 50-400.83/12/02.8402230207
- --8402230237 Forwards Apps A.B.C & D to be included w/questions for Panel III re Pacility testimony Related info encl.

 MURPHY.C E Region 2. Atlants. Reactor Construction & Engineering Support Branch 78/11/16 REISLE J Office of the Executive Legal Director 81pp 22378 308 24x Fiche. 50-400.83/12/02. 8402230207
- --8402230251 Matl maint requirements for Procedure AP-XIII-07.
 **In-Storage Insp & Maint " Equipment purchase order form
 enci .
 ** Carolina Power & Light Co 83/12/02 9pp 22379 040 24X
 Fichs 50-400.83/12/02,8402230207
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8205270420 Forwards request for add1 info re fire protection program needed to complete review Info needed by 821102
 BENAROYA: V. Chemical Engineering Branch 62/05/17 MIRAGLIA, F
 Licensing Branch 3 7pp 22497-015 24X Fiche 50-402, 84/02/07,
 8403050064
- G Adjudicatory correspondence
- 8402230207 Further response to FOIA request for documents re const flaws at facility Forwards documents listed in App A. Documents also being placed in APR A. LPDR Review continuing FELTON. J M Division of Rules and Records 83/12/02 VADEN. T News & Observer/Raleigh Times, Raleigh, NC 3pp 22378 299, 24X Fiche 50-400,63/12/02,8402230207,
- --8104210125 Discusses implications of Ofc of Inspector & Auditor 781012 interview w/ferility ASLB Ofc of Inspector & Auditor attempted to probe thought processes of & require justification from Board re action taken in adjudication YORE, J R Atomic Safety and Licensing Board Panel 78/10/19 HENRIE, J M Commissioners 3pp 22378 302 24X Fiche 50-400,83/12/02,8402230207
- --8402230237 Discusses investigation by Ofc of Inspector & Auditor (DIA) re facility proceeding ASLAB unwilling to be interrogated by OIA Many questions in OIA interrogation of members of ASLB manifestly improper ROSENTHAL, A 8 Atomic Safety and Litensing Appeal Panel 78/10/20 HENDRIE Commissioners 2pp 22378 306 24X Ficha 50-400,83/12/02,8402230207.
- Advisory Committee on Reactor Safeguards reports & correspondence
- 8401300121 Summarizes ACRS 285th meeting on 840112-14 re review of OL application control room design & tube degradation Investigation of allegations re GA requested.

 BEERSCLEIJ C. ACRS Advisory Committee on Reactor Safequards 84/01/16 PALLADIND.N J Commissioners 3pp. 22044 023. 24X Ficha 50-400,84/01/16,8401300121.

- DOCKET 50-407 UNIV OF UTAH RESEARCH REACTOR
- F Security, medical, emergency & fire protection plans
- 8403140145 Forwards Rev i to physical security plan Rev withheld BANDOUIST.O Utah. Univ of. Salt Lake City. UT 84/03/12 NRC -No Detailed Affiliation Given ip 22620 331 24X Fiche.50-407.84/03/12,8403140145
- 8403200281 Forwards revised emergency plen, add1 financial info & 1983 financial statement for univ SANDOUIST.O N Utah, Univ of, Salt Lake City, UT 84/03/14 THOMAS, C D Standardization & Special Projects Branch ip 22476 281 24X Fiche 50-072,84/03/14,8403200281
- --B403200293 Revised "Univ of Uteh Emergency Plan for Training & Research Reactors "BANDQUIST.O M Utah, Univ. of, Salt Lake City, UT UTEC ME 84-0205 84/03/14 28pp 22696 282 24X Fiche 50-072,84/03/14, 8403200281.
- I Financiel information
- 8403200281 Forwards revised emergency pian, addl finencial info & 1983 financial statement for Univ SANDQUIST.O.M Uteh. Univ of, Salt Lake City, UT 84/03/14 THOMAS.C G Standardization & Special Projects Branch 1p 22696 281 24X Fiche, 50-072, 84/03/14, 8403200281
- --8403200296 Univ of Utah operating budget 1983-84 * Utah, Univ of, Sait Lake City, UT 84/03/14 37pp 22696 310 24X Fiche 50-072,84/03/14,8403200281,
- DOCKET 50-409 LA CROSSE BOILING WATER REACTOR
- F Becurity, medical, emergency & fire protection plans
- 8403120074 Extends invitation to attend 840323 regional workshop in Rosemont. IL re 10CFR50, App R safe shutdown requirements Workshop will cover subjs described in IE Info Notice 84-09 & provide eddi guidance in safe shutdown analyses SPEBSARD.R L Division of Engineering. 84/03/06 LINDER, F W Deityland Power Cooperative. 3pp 22588:240 24X Fiche: 50-409,84/03/06.8403120074
- 8403160047 Revs to emargency plan implementing procedures, including Procedures EPP-2, "Organization & Operations During Emergencies," EPP-3, "Communications Sys," & EPP-5, "Estimate of Offsite Dose" #/840310 ltm LINDER, F Dairyland Power Cooperative. 84/03/10 CRUTCHFIELD, D Operating Reactors Branch 5 75pp 22655-006 24X Fiche: 50-409.84/03/10.8403160047.
- 8403200109 Ack receipt of 840309 request for attendance at 840322 meeting in LaCrosse.WI to discuss scope & objectives of 840619 emergency preparedness exercise NRC unable to attend meeting. PAPERIELLO, C. J. Region 3. Office of Director 84/03/16 LINDER, F. W. Deiryland Power Cooperative ip 22685 325 24X Fichs 50-409;84/03/16,8403200109
- --8403200112 Requests attendence at 840322 masting in LaCrosse.WI to discuss scope & objectives for 840619 emergency preparedness assertise Objectives must be submitted for review by 840406 MARGEE.R. Dairyland Power Cooperative 84/03/09 PHILLIPS.M Region 3. Optice of Director 1p 22685;326, 24X Fiche 50-409,84/03/16,8403200109
- P Operating license stage documents & correspondence
- 8403030009 Forwards request for add1 info re NUREO-0737, Item I1. B. 3, "Post-Accident Sampling Sys." to complete raview. Requests response within 45 days of itr receipt CRUTCHFIELD. O Operating Reactors Branch 5 84/02/29. LINDER, F. Dairyland Power Comperative 3pp. 22470 in 24X Fiche: 50-409, 84/02/29, 8403050009.
- 8403130270 Forwards response to Section 4 of NUREO-0827, BEP Topic II-3 C. "Safety-Releted Water Supply (UHS) " Submittal of applicable Tech Spec changes rescheduled for 840401. LINDER, F. Deiryland Power Cooperative, 84/03/08 CRUTCHFIELD, D Operating Reactors Branch 5 5pp. 22608:034 24X Fiche: 50-409, 84/03/08, 8403130270.
- B403150275 Qeneric Ltr B4-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs, Bvc list encl EIBENHUT, D G. Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000, B4/03/14, B403150275

- 8403160074 Forwards acceleration time histories for Nodes i3 & 19 of EGEO seismic analysis of containment bldg Time histories provided in all three model global directions ORIMED C. I Operating Reactors Assessment Branch 84/03/14 LINDER, F. Dairyland Power Cooperative 14pp 22655 089 24X Ficher 50-409,84/03/14,8403160074
- 8403300089 Application to amend License DPR-45 changing Tech Specs to revise reporting requirements to improve accessibility LINDER.F. Dairyland Power Cooperative 84/03/20 CRUTCHFIELD.D Operating Reactors Branch 5 4pp 2282I 187 24X Fichs 50-409, 84/03/20, 8403300089
- --8403300093 Proposed Tach Spec changes, modifying reporting requirements to improve accessibility # Dairyland Power Cooperative. 84/03/20. 2ipp 22821 I91 24X Fichs: 30-409, 84/03/20, 8403300089
- 8403290283 Application for amend to License DPR-45, revising Tech Spect rs min requirements for elternate cooling water source to be used during loss of UHS event LINDER, F. Dairyland Power Cooperative 84/03/21 CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp. 22800:079, 24% Fiche 50-409,84/03/21,8403290283
- --8403290287 Proposed Tech Specs re min requirements for elternate cooling water source to be used during loss of UHS event.

 * Dairyland Power Cooperetive 84/03/21 1p 22800 082 24X Fiche: 50-409, 84/03/21, 8403290283
- 8403280066 Forwards safety evaluation re NUREO-0737.TMI Action Item II K.3.44, "Evaluation of Anticipated Transients W/Bingle Failures." Fecility in conformance w/NUREO-0737 position & evaluation acceptable.
 CRUTCHFIELD.D. Operating Reactors Branch 5. 84/03/26 LINDER,F Dairyland Power Gooperative 3pp. 22776.349 24X Fiche.50-409.84/03/26.8403280066
- G. Inspection reports, IE Bulletins & correspondence
- 8403120083 Responds to IE Bulletin 76-24. Rev 1. Item 4 & re results of addy current exams of absorber tubes. Encl liets absorber tube segments unfit for eddy current insp due to bending. List showing major indications also encl LINDER. F. Dairyland Power Cooperative 84/02/24 KEPPLER. J Q Region 3. Office of Director 4pp 22588: IB5 24X Fiche: 50-409, 84/02/24, 8403120083
- 8401190072 IE Info Notice 84-I3, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunclation." Svc Iist encl JORDAN. E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/28 Consolidated Edison Co. of New York, Inc. 113pp. 22709:239 24X Fichs. 50-000. 84/02/28, 8401170072
- B402070007 IE Info Notice 84-i4, "Highlights of Recent Transport Regulatory Reve by DOT & NRC." Evo list ancl. QRACE, N Division of GA, Safaguards & Inspection Programs (Post B30103) 84/03/02. Consolidated Edison Co. of New York, Inc 130pp. 22552:329. 24X Fiche: 50-000,84/03/02,8402070007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valvae to Operate " Svc list encl. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02. Consolidated Edison Co. of New York, Inc. 122pp. 22553:098 24X Fiche 50-000.84/03/02.8402090008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases" Byc list encl. JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Poet 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 117pp. 22553:217. 24X Fiche 50-000,84/03/02,8402070007
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp." Syc list encl. JORDAN.E L. Division of Emergency Preparedness & Engineering Responss (Poet 830103). 8402/05 Consolidated Edison Co. of New York, Inc. 117pp. 22553.336 24X Fiche 50-000.84/03/05.8402070011
- 8403130326 Ack receipt of 840222 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/83-22, Add1 response required by 840320 re stop watch celibr & stetic trip device tast setyper commitment.

 8HAFER W.D. Region 3, Office of Director 84/03/05 LINDER, F W Dairyland Power Cooperative. ip 22607:143, 24X Fiche: 50-409, 84/03/05, 8403130326.

- ~-8403130335 Responds to NRC 840125 ltr re violations noted in IE Insp Rept 30-407/83-22 Corrective ections static trip device test set setifactorily tested & placed on instrument calbr equipment list for scheduled periodic retesting LINDER:F Deirylend Power Cooperative 84/02/22 KEPPLER:J 0 Region 3, Office of Director 2pp 22607 144 24X Ficha 50-409.84/03/05.8403130326
- 8402070024 IE Info Notice 84-07.Rev 1, "Lessons Leerned From Insps of Fire Protection Bafe Shutdown Sys " Svc iist encl JORDAN,E L Division of Emergency Preperedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402070024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Svc list encl JDRDAN.E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc (18pp 22584 186 24X Fiche 50-000.84/03/07.8402090028
- 8403270233 Forwards IE Insp Rept 50-407/84-03 on 840206-10 & notice of violation
 HIND, J A Division of Radiological & Materiels Sefety Progrems
 84/03/07 LINDER, F W Dairyland Power Cooperative 2pp
 22771.335 24X Fiche 50-407,84/03/07,8403270233.
- --8403270238 Notice of violation from insp on 840206-10 HIND, J. A Division of Radiological & Materials Safety Programs 84/03/09 2pp R2771 337 24X Fiche 50-409,84/03/09,8403270233
- --B403270242 IE insp Rept 50-409/84-03 on 840206-10 Noncompliance noted fellure to adhere to radiological control procedures & to properly control high radiation erea PAUL, R A. GREGER, L R. Region 3, Office of Director 84/03/09 8pp 22771 339 24X Fiche 50-409,84/03/09,8403270233
- 8402090031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Sefety Sys " Svc list ent!
 DEYOUNG,R C Director's Office, Office of Inspection end
 Enforcement B4/03/12 Consolidated Edison Co of New York, Inc
 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- 8402070043 IE Info Notice 84-17. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities." Svc 11st encI JURDAN, E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 30-000 84/03/21 8402070043
- 8402070044 IE Info Notice 84-20, "Byc Life of Relays in Sefety-Releted Sys " Byc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp. 22733 001 24X Fiche, 50-000, 84/03/21, 8402070044
- R Periodic operating reports & related correspondence
- 8403080031 "Personnel Whole Body Exposures for CY83 " W/840227 itr LINDER, F Dalrylend Power Cooperative 83/12/31, 2pp 22559 227 24X Fiche 50-409,83/12/31,8403080031
- 8403080236 "Radioactive Effluent Rept & Rediological Environ Monitoring Rept, 1983 " W/840227 itr LINDER, F Deiryland Power Cooperative 83/12/31 KEPPLER, J & Region 3, Office of Director 97pp 22560:025 24X Fiche 20-409,83/12/31,8403080234
- 8403230002 "Radioactive Effluent Rept & Radiological Environ Monitoring Rept for 1983 " W/840227 ltr LINDER, F Dairyland Power Cooperative 83/12/31 XEPPLER, J. G Region 3, Office of Director. 99pp. 22728 iii 24X Fiche: 50-409, 83/12/31, 8403230002
- 8403020161 Monthly operating rapt for Jan 1784 W/840207 ltr. GOODMAN.L B., LINDER,F Deiryland Power Cooperative 84/01/31 11pp 22442:017 24% Fiche. 50-409, 84/01/31, 8403020161.
- 8403300131 Monthly operating rept for Feb 1984 W/840305 ltr 0000MAN.L.8., LINDER Dairyland Power Cooperative 84/02/29 9pp 22820.014 24% Fiche: 50-409,84/02/29,8403300131
- S Reportable occurrences. LERs & related correspondence
- 8403200163 LER 84-003-00 on 840220, erroneous high containment bldg pressure eiarm received. Caused by fuse failure Fuse repleced.clearing high pressure signel Bys restored to normel W/840312 ltr 000DMAN, L 8 , LINDER, F Dairyland Power Cooperative 84/03/12 3pp 22697 134, 24X Fiche, 50-409, 84/03/12, 8403200163

- DOCKET 50-410 NINE HILE POINT NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8403010.298 Notification of 840326.27 & 28 meetings w/util in Scriba.NY to review const progress & obtain info for assessing peojected fuel load date Supporting documentation encl HAUCHEY.NF Licensing Branch 2 84/02/17 SCHMENCER.A Licensing Branch 2 89p 22479 174 24X Fiche 30-410.84/02/17,8403010298
- 8403050370 Requests review of documentation submitted in instrumentation & control area & confirmation that documentation reflects actual plant design Changes should be submitted as amends to FGAR in timely manner SCHWENCER.A Licensing Branch 2 84/02/29 RHODE.O K Niagara Hohawk Power Corp 2pp 22527 261 24X Fiche 50-410, 84/02/29, 8403050370
- --B403050371 Summary of 840118 & 0207-08 meetings w/util in Bethesda.MD & Cherry Hill.MJ.respectively.re instrumentation & controls List of discrepancies within & between licensing documents encl HAUGHEY.H F Licensing Branch 2 B4/02/27 Licensing Branch 2 20pp 22327 243 24% Fiche 50-410.84/02/29.8403050370
- 8403060539 Summary of 84018 & 0207-08 meetings w/util.GE & StW in Bethesda.HD re instrumentation & controls Supporting documentation enci HAUOHEY.H F Licensing Branch 2 84/02/29 Licensing Branch 2 22pp 22552 295 24X Fiche 50-410.84/02/29,8403060539.
- 8403070240 Summary of 840216 meeting w/Northeast Nuclear Energy Co, Boston Edison Co.Verment Yankee Nuclear Power Co & Teledyne Enginemring Svcs in Waltham MA re addl Mark I torus structural analysis List of attendees encl SHEA-J J Operating Reactors Branch 5 84/03/07 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 22372 298 24X Fiche 50-000.84/03/07.8403070240
- 8403270374 Notification of 840404 & 03 meetings w/util, OE & S&W in Ban Jose-CA to discuss instrumentation & control HAUGHEY, MF F. Licensing Branch 2 84/03/08 SCHMENCER, A Licensing Branch 2 3pp 22822 291 24X Fiche 30-410,84/03/08,8402270374
- 8403200232 Forwards "Evaluation of Angled Screen Fish Diversion Sys at Oswego Steam Station.Unit 6." "Nine Mile 2 Voiney 345 kV Transmission Facility" & "Environ Mgt & Const Pian Nine Mile 2 Voiney 345 kV Transmission Facility " MANGAN.C V Niagara Mohawk Power Corp 84/03/15 EISENHUT.D @ Division of Licensing 1p 22694 221 24X Fiche 50-410,84/03/15,8403200232
- --8403200240 "Evaluation of Angled Screen Fish Diversion Sys at Oswego Steam Station Unit & "
 # Lawler: Matusky & Skelly Engineers 84/01/31 118pp 22694 223 24X Fiche 50-410,84/03/15,8403200232
- --8403200243 "Environ Mgt & Const Plan Nine Hile 2 Voiney 345 kV
 Transmission Facility "
 * Niægara Hohawk Power Corp 83/09/30 146pp 22694 341 24X
 Fiche 50-410.84/03/15.8403200232
- --8403200248 "Nine Hile 2 Voiney 345 kV Transmission Facility "
 W/three oversize maps Aperture cards are available in PDR
 * Niagara Hohauk Power Corp 82/04/30 350pp 22695: 127 24X
 Fiche 50-410,84/03/15,840320032
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8403210213 Summary of 840224 meeting w/util re administrative matters concerning closing out draft SER open items # Licensing Branch 2 84/03/05 Licensing Branch 2 32pp 22709 208 24X Fiche 50-410.84/03/05.8403210213
- 8403270314 Forwards request for addi info to complete review of draft SER re pressure-temp limit curves to comply w/explicit closure flange math temp requirements of 10CFR. App © Info should be submitted as FSAR amend no later than 840515 SICHHENCER: A Licensing Branch 2 84/03/06 RHODE.0 K. Niagare Mohawk Power Corp 4pp 22789 246 24X Fiche 50-410, 84/03/06,
- 8403220301 Forwards interim draft SER (NUREQ-1047) identifying unresolved issues as open items Complete draft SER expected to be relaxued in May 1984 Detailed agenda aimed at resolving open items requested SCHMENCER, A Licensing Branch 2 84/03/08 RHODE, 0 K Niagara Rhobaut Power Corp 456pp 22720 001 24% Fiche 50-410,84/03/08,84/03220301

- B403280236 Forwards list of issues to be discussed at Mechanical Engineering SER review during wk of 840604 at 8&M ofcs in Cherry Hill NJ SCHMENCER: A Licensing Branch 2 84/03/12 RHODE: 0 K Niagara Mohawk Power Corp 15pp 22789 326 24X Fiche 50-410.84/03/12.8403280234
- F Security, medical, emergency & fire protection plans
- 8403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-07 Agenda for workshop encl MURLEY.T.E Region I. Office of Director 84/03/07 O'TOOLE, J D Consolidated Edison Co. of New York, Inc. 35pp. 22672.062. 24X Fiche 50-000,84/03/09.8403190243
- G Adjudicatory correspondence
- 8403080(36 Resolution submitted by Legislature of Eric County requesting FERC & NRC intevene to halt util withdrewal from project & State of NY Public Bvc Commission investigate util actions
 SHARTS.D J Buffelo. NY B4/03/01 2pp 22561 150 24X Fiche 50-410.84/03/01.8403080(36
- I Financial information
- B403270177 Annual Financial Rept 1983 W/840322 ltr HAEHL,J G , DONLON,H J , LEMPGES.T E Niagara Hohawk Power Corp. 83/12/31. 41pp 22800 319 24X Fiche 80-220,83/12/31,8403270177.
- Q Inspection reports, IE Bulletins & correspondence
- 8403010006'Notification of Significant Licensee Meeting 84-18 on 840222 in King of Prossis.PA to discuss const appraisal team & BALP findings
 COLLING: 3 J Division of Project & Resident Programs 84/02/17 Division of Project & Resident Programs 1p 22479 337. 24X Fiche 30-410.84/02/17,8403010006
- B401190072 IE Info Notice B4-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enci JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) B4/02/28 Consolidated Edison Co of New York, Inc 115pp 22707 237 24X Fiche 50-000,84/02/28,8401190072
- 8403150096 Forwards IE Insp Rept 50-410/83-17 on B31205-840120. No violations observed STAROBITCKIIR Division of Project & Resident Programs. 84/03/01 RHDDE, 9 K Niegars Mohawk Power Corp 2pp 22643 146 24X Fichs 50-410,84/03/01,8403150096
- --B403150101 IE Insp Rept 50-410/B3-17 on B31205-B40120 No violations identified Hajor areas inspected work activities, procedures & records re reactor pressure vessel storage & hydraulic control unit installation GRAMM.R. A, LAZARUS, W J, COLLING, B J, Region 1, Office of Director B4/02/27 lipp 22643 148, 24X Fiche 50-410,84/03/01.8403150096
- 8402090007 IE Info Notice 84~14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " 8vc list and GRACE.J N Division of QA, Befeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007.
- 8402090008 IE Info Notice 84-16. "Pailure of Automatic Sprinkler Bys Valves to Operate " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 22053 098 24X Fiche 30-000,84/03/02,8402090000
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Go. of New York, Inc 119pp, 22553 217 24X Fiche: 50-000, 84/03/02, 8402090007
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nii Ductility Temp " Svc list encl.
 JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553:336 24X Fiche. 50-000, 84/03/05, 8402070011

- 8402070024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown 89a " Svc list encl JURDAN.E L Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000:84/03/07:8402070024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Svc 1(st encl JURDAN,E L Division of Emsrgency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000:84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYDUNG,R.C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- 8402070043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PHR Reactor Cavities" Svc list enci JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21 Gonsolidated Edison Co. of New York. Inc. 123pp. 22823 229 24X Fiche 50-000.84/03/21.8402070043
- 8402090044 IE Info Notice 84-20; "Svc Life of Relays in Bafety-Related Bys " Svc list and! JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402090044
- R Pariodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding detes not caused by delay due to offsite emergency planning issues,
 DIRCKG.W.J. Office of the Executive Director for Operations 84/02/21 PALLADINO Commissioners 9pp 22492 083 24X FIChe 50-000.84/02/21.8403020443
- 8. Reportable occurrences, LERs & related correspondence
- B40307007B Dificiency rspt re items supplied by Tube-Line Corp Final rept delayed until 840430 per 840213 telcon RHODE, G K Niagara Mohawk Power Corp 84/02/15 STAROBTECKI, R Division of Project & Resident Programs ip 22576 06B 24X Fiche. 30-410.84/02/15.840307007B
- B403210136 Intsrim deficiency rept re Anchor Darling HPCB sys valve vibration loosening anti-rotational set screws Initially reported on 840127 % reported by GE per Part 21 Investigation in progress Final rept by 840723
 MANGAN.C V Niagara Mohawt Power Corp 84/02/27 STAROSTECKI,R Division of Project & Resident Programs 2pp 22707 272 24X Fichs 50-410.84/02/27,8403210136
- 8403260233 Forwards summary list of deficiencies identified per 100FR30. 55(e). Part 21 & potential generic itr repts for comments
 8TAROSTEGKI, R Division of Project & Resident Programs 84/02/28
 Region I, Office of Director, 7pp 22756, 065 24X
 Fiche 50-000. 84/02/28. 8403260233
- 8403130363 Interim deficiency rept re hydrostatic uplifft pressure not considered in reactor bldg mat design Initially reported on 840130, Final rept will be submitted by 840518 MANGAN, C. V Niagara Mohawk Power Corp 84/02/29 STAROSTECKI, R Division of Project & Resident Programs 2pp 22616 248 24X Ficher 50-410,84/02/29,8403130363
- 8403140122 Part 21 rept re status update concerning abnormal wear on linear converters. Test program underway Rasults of invastigation indicate excessive wear caused by hunting of control circuitry.

 DQDSON. J P Pacific Air Products Co. 84/03/09 Director's Office, Office of Inspection and Enforcement 7pp 22624 06B 24X Fiche. 50-000:84/03/09.8403140122.
- 8403170135 PNS-I-84-002 on 840312 bomb threat received from unidentified caller Sits emergency & safeguards contingency plan requirements implemented, Public areas & site protected area searched w/negative findings MADDEN, B., JOYNER, J., Region 1, Office of Director 84/03/12 ip 22674-352 24X Fiche 50-220,84/03/12,8403170135.
- 8403220075 EN-84-015 on 840320, notice of violation & proposed imposition of civil penalties in amount of #180,000 will be issued to licensee Action based on failure to maintain containment integrity & failure to conduct survaillance CRAIO.J., AXELRAD.J., Director's Office, Office of Inspection and Enforcement, 84/03/15, 2pp 22712 308, 24X Fiche, 50-220,84/03/15,8403220075

V Operator Examinations

8403130124 Forwards nuclear power plant experience for operating shift positions, as requested in 840301 ltr LEMPOES, T E Niegara Mohawk Power Gorp 84/03/05 DENTON, H Dffice of Nuclear Reactor Regulation, Director 5pp 22603 237 24X Fiche 30-410.84/03/05.8403130124

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8403010030 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in PDR upon request Review continuing FELTON. J M Division of Rules and Records 84/01/17 ANDERSON, S i Garvey, Schubert Adams & Barer 4Pp 22446 293 24X Fiche 50-000,84/01/17,8403010050
- --8112020204 Forwards new format for nuclear power plants -- const status rept. NUREO-0030 (yellow book) New format should be used to provide next update into for planned Nov 1981 publication (data as of Sept 30, 1981) due Blil120 M/2 encl HARTFIELD.R A Office of Managament and Program Analysis 81/10/30 DUNN.C N Duquesne Light Ca 9pp 22446 305 24X Fiche 50-000, 84/01/17, 8403010030
- 8403010387 Requests delay in submitting addi info per Accident Evaluation Branch 831202 request Response to Questions E450 i & 2 will be submitted on 840323 HOOLEVER.E J Duquesne Light Co 84/02/24 KNIGHTON.G W. Licensing Branch 3 ip 22434 067 24X Fiche 50-412,84/02/24, 8403010387
- B403270369 Notification of 840403-05 meetings w/S&W & util in Bostom, MA to discuss NRC questions re-mechanical engineering portions of FGAR & perform detailed design documentation audit on facility

 LAZOL L Licensing Branch 3 84/03/01 KNIGHTON, O W Licensing Branch 3 4pp 22787 335 24X Fiche 50-412, B4/03/01, 8403270369
- B4032B0056 Notification of B40321 meeting w/util in BethesdarMD to discuss Environ & Hydrological Engineering Branch Guestions 240 O1 & 240 O8 LAZOL Licensing Branch 3 84/03/02 KNIGHTON & W Licensing Branch 3 4pp 22B12 350 24X Fichs 50-412,84/03/02.84032B0056.
- B403i90152 Responds to 840i23 ltr re use of Rockbestos Co cable at facility Vendor stated in writing that cable fully suitable for safety-related use WOOLEVER, E. J. Duquesna Light Co. 84/03/06 POTAPOVS, U. Region 4. Office of Director. 2pp. 22668 343 24X Fiche, 50-412,84/03/06, 8403190152
- 8403280067 Notification of 840313 meeting w/util in Bethesda.MD to discuss Chemical Engineering Branch.Chemical Technology Saction, quostions & open litems LAZD.L Licensing Branch 3 84/03/07 KNIGHTON, 0 w Licensing Branch 3 4pp 22812 331 24X Fiche 50-412,84/03/07,8403280067
- 8403280122 Summary of 840224 meeting w/Westinghouse Duners Group in Bathesda: MD re proposed Westinghouse steam generator tube rupture generic program Attendes list & agenda Sncl NERBEG, V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp \$2811 131. 24X Fiche 50-000.64/03/07.8403280122
- 8403280060 Notification of 840403 meeting w/util in Shippingport,PA to visit specific points of interest within branch environ review scope LAZO,L Licensing Branch 3 84/03/08 KNIOHTON.OW Licensing Branch 3 5pp 22812.338 24X Fiche 50-412.84/03/08.8403280060
- 8403160090 Forwards SMECO 7703, "Missile-Barrier Interaction," submitted per 840227 response to Action Item 18 of structural design avoit HOOLEVER E J Duqussne Light Co 84/03/09 KNICHTON, G W Licensing Branch 3 1p 22653 001 24X Fiche 50-412,84/03/09,8403164090
- --8403160096 "Missile-Barrier Interaction"
 JANKOV, Z D, SHANAHAN, J A, WHITE, M P. Stons & Webster Engineering
 Corp. SWECO 7703 77/09/30 223pp 22653 002 24X
 Fichs 50-412,84/03/09,8403160090

- B403160190 Forwards minutes from B31205-08 meeting w/Instrumentation & Control Sys Branch re discussion of 830919 request for add1 info Items listed as closed imply that info requested by NRC has been provided WOOLEVER. E. J. Guquesne Light Co. B4/03/09 XNIOHTON, O. W. Licensing Branch 3. 21pp. 22655 246 24X Fishe 50-412, B4/03/09, B403160190
- 8403200234 Forwards responses to Procedures & Sys Review Branch questions re nuclear engineering dept organization & administrative procedures forwarded in 840106 ltr Responses will be included in FSAR Amend 6 MODLEVER, E. J. Duquesne Light Co. 84/03/16 KN1GH70N, 0 W Licensing Branch 3 13pp 22671 089 24X Fiche 50-412.84/03/16.8403200234
- 8403300062 Forwards operating shift experience tables Util does not plan to use shift advisors CAREY, J. J. Duquesne Light Co. 84/03/26 DENTON, H. Defice of Nuclear Reactor Regulation, Director App. 22821 167 24X Fiche 50-412.84/03/26.8403300062
- C Utility Environmental Report (ER). amends & correspondence
- 8403270372 Requests addl info re environ site visit scheduled for wk of 830926 to review environ rept DL stage KNIGHTON O W Licensing Branch 3 84/03/02 WOGLEVER.E J Duquesne Light Co 4pp 22787 326 24X Fiche 50-412,84/03/02,8403270372
- B403150075 Forwards Affidavits of Svc certifying distribution of Amend 4 to environ rept & Amend 5 to FSAR WOOLEVER.E J Duquesne Light Co. B403/07 DENTON H R Office of Nuclear Reactor Regulation. Director 5pp 22641 164 24X Fiche 50-412,84/03/09,8403150095
- B403270145 Forwards Amend 5 to environ rept DL stage Amend consists of responses to Questions E451 5.E450 1 & E450 2.per QU Knighton 631020 & 1202 ltre & various technical & editorial changes.

 MODLEVER: E J Duquesne Light Co 84/03/17 DENTON, H R Office of Nuclear Reactor Regulation Director 5pp 22801 244 24X

 Fiche: 50-412, 84/03/19, 8403290145
- --8403290146 Amend 5 to environ rept ~ OL stage * Duquesne Light Co 84/03/31 79pp 22801 250 24X Fiche 50-412,84/03/19,8403290145
- 8403260059 Forwards responses to Accident Evaluation Branch 831202 questions re-environ rept Revised environ rept. Section 7 i also encl HODLEVER, E. J. Duqueane Light Co. 84/03/22 KNIGHTON, O. W. Licensing Branch 3 23pp 22751 003 24X Fiche 50-412,84/03/22,8403260057
- E NRC Safety Eveluation Report (SER), supple & correspondence
- 8403140197 Forwards draft BER (NUREO-1057) re operation Proposed schedule for submittel of written response to open items should be provided by 840330 KNIOHTON, G W Licensing Branch 3 84/03/01 WODLEVER, E J. Duquesne Light Co 311pp 22636 001 24X Fiche, 50-4(2,84/03/01,840)14,0197
- F Security, medical, emergency & fire protection plans
- 8403270357 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licenses per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR KNIOHTON, 0 W Licensing Branch 3 84/03/01 WOULEVER, E J Duquesne Light Co 4pp 22787 348 24X Fiche 50-412, 84/03/01, 8403270357
- B403200040 Emergency Preparedness Plan EPP/IP 1 2: Attachments 6 & 7 MILLER, D J Duquesne Light Co 84/03/02. Spp 22578: 316 24X Fiche 50-334, 84/03/02, 8403200040
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-07 Agenda for workshop ent! MURLEY.T E Region i. Office of Director 84/03/09 0'TODLE.J D Consolidated Edison Co of New York, Inc 35pp 22672 062, 24X Fiche 50-000.84/03/09.8403190243

- K Utility Final Bafety Anelysis Report (FBAR) & amends
- 8403150D95 Forwards Affidavits of Svc certifying distribution of Amend 4 to environ rept & Amend 5 to FSAR WOOLEVER.E J Duquesne Light Go 84/03/09 DENTON H R Office of Nuclear Reactor Regulation, Director 5pp 22641 164 24X Fiche 50-412,84/03/09,8403150095
- Q Inspection reports. IE Bulletins & correspondence
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103), 84/02/28 Consolidated Edison Co. of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403070303 Ack receipt of 840112 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/83-15 STAROSTECKIR Division of Project & Resident Progrems 84/02/28 MODLEVER, E J Duquesns Light Co 2pp 22546 282 24X Fiche 30-412,84/02/28,8403070303
- --8403070308 Responds to NRC 831212 itr re violations noted in IE Insp Rept 50-412/83-15 Corrective actions engineering in process of analyzing all KH applications to confirm acceptability of judgment made in response to Request for Info RI-0383-4C MODLEVER.E. J. Duquesne Light Co. 84/01/12. BYARGSTECKI.R Division of Project & Resident Programs 4pp 22346-284 24X Fiche 50-412,84/02/28.8403070303
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl ORACE, J N. Division of GA. Bateguerds & Inspection Programs (Post 830103) 84/03/02 Comeplieted Edison Co of New York, Inc. 130pp 22552 327 24% Fiche 50-000,84/03/02,8402090007
- B402070008 JE Info Notice B4-i6. "Failure of Autometic Sprinkler Sys Valves to Operate" Svc list encl
 JORDAN, EL Division of Emergency Preparadness & Engineering
 Response (Post B30103) 84/03/02 Consolidated Edison Co. of New
 York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02,8402090008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases" Svc list encl JORDANAE L Division of Emergency Preperedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 117pp 22559:217 24X Fiche: 50-000.84/03/02.6402090009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl.

 JRDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York Inc. 117pp 22553-336 24X Fiche 50-000,84/03/05,8402070011
- B402090024 IE Info Notice 84-09, Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Bys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/07 Compolidated Edison Co. of New York, Inc. i1Bpp 22635 049 24X Fiche, 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in FWR Bys " Svc list enc! JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403220131 Forwards IE Insp Rept 50-412/84-01 on 840117-0221 No violations observed STAROSTECKI,R Division of Project & Resident Programs 84/03/08 WOOLEVER,E J Duquesne Light Co 2pp 22716 019 24X Fiche 50-412,84/03/08.8403220131
- --B403220139 IE Insp Rept 50-412/B4-01 on 840117-0221 No violations observed Major ereas inspected, previously identified items. FBAR descriptions, post-weld heat treatment storage requirements & procedure review of piping instelletion. MALTON.G A Region 1. Office of Director TRIPPIL.E. Division of Project & Resident Programs. B4/03/07 Spp. 22716 021, 24X Fiche 50-412,84/03/08.8403220131
- B402070031 IE Bulletin 84-02, "Failures of QE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl.

 DEYOUNG: R C. Director's Office: Office of Inspection and Enforcement. B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823.094 24X Ficher 50-000,84/03/12,8402090031.

- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PNR Reactor Cavities " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of N York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,84020900 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Svc list encl Bys - SyC 11st encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/21 Consolidated Edison Co of New
 York, Inc. 133pp 22933 001 24X Fiche 50-000.84/03/21,8402090044
- 8403270200 Ack receipt of 840302 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/83-13 Corractive actions will be examined during future insp BTARDSTECKI.R Division of Project & Resident Programs WOOLEVER,E J Duquesne Light Co ip 22803 293 24X Fiche: 50-412,84/03/22,8403270200
- -8403270204 Responds to NRC 831110 ltr re violations noted in 1E Insp Rept 50-412/83-13 Engineering evaluation confirmed ATBM A325 bolts maintain required min bolt preload No addl action required
 HOOLEVER,E J Duquesne Light Co 84/03/02 STAROSTECKI,R
 Division of Project & Resident Programs 4pp 22803 301
 Fiche: 50-412,84/03/22,8403290200
- B403300200 Forwards summary of actions taken.per IE Bulletin 83-07, "Apparantly Fraudulent Products Sold by Ray Miller, Inc "Pittsburgh-Des Moines Steel & Joseph Cat Corp received matls from Ray Miller, Inc Matls not fraudulent WOOLEVER, E. J. Duquesne Light Co. 84/03/22 MURLEY, T. E. Region i. Office of Director Spp. 22819 321 24X Fiche 50-412.84/03/22, 8403300200.
- 8 Reportable occurrences, LERs & related correspondence
- 8403070298 Interim significant Deficiency Rept 84-01 re clamp anchor essemblies w/undersized welds Vendor surveillance group will perform sample insp to establish sffectiveness of vendor QC Next rept by 840601 WOOLEVER, E. J. Duquesne Light Co. 84/02/16 MVRLEY, T. E. Region 1, Office of Director 4pp 22541 272 24X Fiche 50-412,84/02/16, 8403070298
- 8403130374 Interim Bignificant Deficiency Rept 84-02 re poor wiring workmanship on two Gould 480-volt motor control ctrs Random insps conducted Evaluation underway Next rept will be submitted by 80701 HOOLEVER, E. J. Duquesne Light Co. 84/02/21 MURLEY, T. E. Region Office of Director. 3pp 22616 278 24X Fiche 50-412,84/02/21,8403130374. Region 1,
- 8403210130 Interim Bignificant Deficiency Rept 84-03 re GE Type HEA lock-out relays Initially reported on 840127 Field test procedure developed to test relays Defective relays will be procesure developed to test relays bettive relays bill of replaced Next rept by 840615

 WOOLEVER, E. J. Duquesne Light Co. 84/02/28 MURLEY, T. E. Region 1. Office of Director 4pp 22707.266 24X Fiche 50-412.84/02/28, 8403210130
- 8403250233 Forwards summary list of deficiencies identified per 10CFR50 55(e), Part 2i & potential generic ltr repts for Comments
 STARDSTECKI,R. Division of Project & Resident Programs 84/02/28
 Region i, Office of Director 7pp 22756 065 24X
 Fiche, 50-000,84/02/28,8403260233
- 8403210058 Final Significant Deficiency Rept 83-02 re GC acceptance of nonconforming cable pulling conditions Initially reported on 840227. GC section reorganized Continued sampling of GC inspactor activities implemented WDOLEVER, E J Duquesne Light Co 84/02/29 MURLEY, T E Region 1, Office of Director. 4pp 22704 346 24X Fiche 50-412,84/02/27, 8403210058. 840321005B
- 8403270219 Part 21 rept ra broken contact carrier in control device of 7 3 kV-15 kV,500-750 MVA,5 kV 350-3,000 & all HKV circuit breakers Initially reported on 830223 Addenda to Installation & maint procedures sent to affected units
 DUVALL,D D Brown Boveri Corp. (subs of Brown Boveri & Co , Ltd)
 84/03/19 Record Services Brench (Document Control Desk). 5pp
 22772:114. 24X Fiche 50-000,84/03/19.8403270219

V Operator Examinations

8403300062 Forwards operating shift experience tables Util does not plan to use shift advisors.

GAREY, J. J. Duquesne Light Co. 84/03/26. DENTON, H. Office of Nuclear Reactor Regulation, Director. App. 22821 167 24X

Fiche: 50-412,84/03/26,8403300062

- DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & corresondance
- 8403080196 FD1A request for documents re WR McAfre allegations involving facility from Mar 1977 Mar 1979, NRC open conference at site in Nov 1979 & review of util topical GA manual
 GARDE, B P , ANSELL, E Covernment Accountability Project 83/11/21
 Office of Administration 2pp 22584 162 24x
 Fiche 50-413,83/11/21,8403080196
- 8403060477 Notification of 840313 meeting w/util in York County, SC to conduct confirmatory site visit per Section 13 6 of SRP (NUREG-0800) JABBOUR, K N Licensing Branch 4 84/02/24 ADENSAM, E 0 Licensin Branch 4 3pp 22549 24X Fiche 50-413,84/02/24,8403060477
- 8402090017 Board Notification 84-038 forwards RJ Mattson 840123 memo to DG Eisenhut providing status update of NRC actions ra Westinghouse ECCS actuation logic EISENHUT.D Q Division of Licensing 84/02/27 FALLADING Commissioners 7pp 22546 007 24X Fiche 50-000.84/02/27, 8402090017
 - 8402090017
- 8403020230 Notifies that Class II fee appropriate for review of 840123 application requesting extension of const completion date to 84101 DIGOS,R M License Fee Management Branch 84/02/27 TUCK Co 1p 22494 317 24% Fiche 50-413,84/02/27, Duke Pawer Co 8403020230
- 840:3070189 Forwards equipment data sheets for SORT & pump & valve operability review team onsite audits Qualification of components complete W/five oversize drawings Aperture cards are available in FDR TUCKER. H B Duke Pawer Co 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation. Director ADENBAN, E Q Licensing Branch 4 601pp 22536 281 24X Fiche 50-413,84/02/28,8403070185
- --8403070202 Rev 10 to Procedure CNS-1390 01-00-0073, "Installation Spec Manual Mechanical Installation Procedure for Electrical Penetration Types B.C.D.F.O.H.J.K.L.&M" * Duke Power Co 83/08/24 34pp 22537 087 24X Fichs 50-413,84/02/28,8403070185
- --8403070219 Rev B to Procedure CNB-1390 01-00-0071, "Procedure for Installation of Type A (6.900 Volt) Electric Penetration Assemblies ' DDVER.R P Duke Power Co 83/03/07 350pp 22537 167 24X Fiche 50-413,84/02/28,8403070185
- 8402090016 Board Notification 84-031 informs that Commission raceived affidavit from former util employee alleging that util deliberately undermined GA program at facilities Investigation in progress
 NOVAK.T M Assistant Director for Licensing, 84/02/29. KELLY
 PURDOM.P. FUBTER.R Atomic Safety and Licensing Board Panel
 67217 043 24X Fiche 50-413.84/02/29.8402070016 KELLY, J ,
- 8403190394 Forwards nonproprietary & proprietary "Technical Basis for Eliminating Pressurizor Burge Line Ruptures as Structural Design Basis for Catawba. Units 1 & 2 " Revised FSAR pages also encl Proprietary rept withheld (ref loCFR2 790)
 TUCKER. H B Duke Power Co 84/02/29 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E O Licensing Branch 4 3pp 22474 089 24X Fiche 50-413,84/02/29,8403190394
- --8403190399 Application for withholding proprietary rept HCAP-10487,
 "Technical Basis for Eliminating Pressurizer Surge Line
 Ruptures as Btructural Design Basis "
 HIEBEMANN,R A Westinghouse Electric Corp 84/02/15 DENTON,H R
 Office of Nuclear Reactor Regulation, Director 9pp 22474:092
 24X Fiche, 50-413,84/02/29,8403190394
- ---B403190404 Nonproprietary "Technical Basis for Eliminating Pressuriter Burge Line Ruptures as Structural Design Basis for Catawba Units 1 & 2 "
 SWAMY.S A. YANG.C Y., SANE.A D Westinghouse Electric Corp WCAP-10488 (NP) 84/02/10 107pp 22674 101 24X
 Fiche 50-413.84/02/29.8403190394
- 8403060422 Provides second suppl to B31i18 submittal & add1 info on positive aspects of elimination of arbitrary intermediate pips breaks from facilities
 TUCKER, H B Duke Power Co 84/03/01 DENTUN.H R Office of Nuclear Reactor Regulation, Director ADENBAM, E G. Licensing Branch 4 2pp. 22511 359 24X Fiche, 50-413, 84/03/01, 8403060422

- 8403130086 Forwards fee for review of 840123 request for extension of const completion date to 841101 TUCKER.H B Duke Power Co 84/03/02 DIGOS.R M License Fee Hanagement Branch 1p 22614 270 24X Fiche 50-413,84/03/02,840
- 8403160028 Advises that all refs to three (N-1) loop operation should be deleted in proof & review Tech Specs issued 840302 Plant will operate only wifour loops in operation during st-power modes, in response to FSAR Guestion 440 58
 TUCKER, H B Duke Power Co 84/03/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4. 2pp 22654 347 24X Fiche 50-413,84/03/07,8403160028
- 8403190257 Forwards "Steam Pressure Suppression Characteristics of Water-Soluble Plestic Membrane Shielded Ice for Ice Condenser Containment Nuclear Power Plants " TUCKEH.H B Duke Power Co 84/03/07 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 7pp 22672 102 24% Fiche 50-000.84/03/07.8403190257.
- B403280122 Summary of 840224 meeting w/Westinghouse Owners Group in Bathssda,MD re proposed Westinghouse steam generator tube rupture generic program Attendee list & agenda encl NERSES.V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp 22811 131 24X Fiche 50-000.84/03/07.8403280122
- 8403130104 Provides clarification of third paragraph of 840229 ltr repressibility of welded piping attachments being located in close proximity to eliminated arbitrary intermediate breaks TUCKER, H B Dute Power Co 84/03/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAN, E C Licensing Branch 4 2pp. 22600 256 24X Fiche 50-443, 84/03/08, 8403130104
- B403160197 Forwards responses to EQ Adensam 820401 request for qualification decumentation re operability af containment purge & vent valves in Modes 1-4 per Tech Spec 3 6 1 9
 TUCKER, H B Duke Power Co 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch 4 333pp 22658 185 24X Fiche 50-413,84/03/12,8403160197
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT.D C Division of Licensing 84/03/14 Atomic Bafety and Licensing Board Panel 10pp 24X Fichs 30-000.84/03/14.8402090041
- 8403200165 Forwards summary of experience for operations personnel to be licensed on Unit i.per 840114 & 0226 commitments Based on operating shift experience requirements, sufficient experience available to startup & operate Unit 1
 TUCKER.H D Duke Power Co B4/03/14 DENTON.H R Office of NUCKER.H D DUKE TOWNER AND ADMINISTRY OF ADMINISTRY
- 8403220074 Requests that snubber Tech Specs be written to reflect inspon unit basis instead of current sys basis Conclusions from review of J Sapir 740301 ltr ng Yech Specs for snubber operability & surveillance listed
 TUCKER.H B Duke Power Co 84/03/15 DENTON, HR Office of Nuclear Reactor Regulation, Director ABENSAM.E Q Licensing Branch 4 2pp 22712 306 24% Fishe 50-443.84/03/15.8403220074
- 8403250034 Forwards proposed amends for proof & review Tech Specs
 Amends change surveillance requirements for diesel fuel oil
 Supporting justification & analysis encl
 TUCKER.H B Dute Power Co 84/03/15 DENTON.H R Office of
 Nuclear Reactor Regulation, Director ADENSAMEE C Licensing Branch
 4 2pp 22750 260 24X Fiche 50-413,84/03/15,8403260034
- --8403250137 Proposed amends to proof & review Tech Specs, changing diesel furl all surveillance requirements * Duke Power Co 84/03/15 9pp 22750 252 24X Ficha 50-413.84/03/15.8403260034
- 8403270213 Forwards response to followup questions from 840209 meeting re-environ qualification of DG Obrian electrical penetrations Tests verify adequacy of Type K module for plant applications
 TUCKER-H B Duke Power Co 84/03/14 DENTON-H R Office of Nuclear Reactor Regulation, Director, ADENSAM-E G Licensing Branch 4 App 22770 273 24X Fiche 30-413,84/03/16,8403270213
- 8403240073 Forwards proposed amends to proof & review Tech Specs reverlification of position of inaccessible fire suppression & sprinkler sys valves, high radiation area & radiological environ monitoring program
 TUCKER.H. B Duke Power CD. 84/03/20 DENTON.H. B Office of Nuclear Reactor Regulation. Director ABENSAH, E G. Licensing Branch
 4. Ip 22746 284 24% Fiche 50-413.84/03/20,8403240073

- --8403260080 Proposed amends to proof & review Tech Specs re Action Statements & b & 19 b on position verification of inaccessible fire suppression & sprinkler sys valves, high radiation area & radiological environ monitoring program * Duke Power Co 84/03/20 38pp 22746 285 24X Fiche 80-413,84/03/20.8403260073
- 8403270103 Forwards test exemptions required to perform NUREO-0737,
 Item I Q 1, "Natural Circulation Testing " Exemptions need
 to be included in Tech Specs
 TUCKER.H B Duke Power Co 84/03/21 DENTON,H R Defice of
 Nuclear Reactor Regulation, Director ADENBAM.E Q Licensing Branch
 4 3pp 22766 341 24% Fiche 50-413,84/03/21.8403270103
- 8403300188 Provides plant-specific info & generic info omitted from Westinghouse Duners Group 831201 & 840312 ltrs.in response to Generic Ltr 83-10C Issues re reactor coolant pump trip resolved TUCKER. H B Duke Power Co 84/03/26 DENTON. H R Office of Nuclear Reactor Regulation, Director EISERHUT. D 0 Division of Licensing 3pp 22819 292 24X Fiche 50-413,84/03/26,8403300188
- 8403300107 Forwards proprietary & nonproprietary varsions of,
 "Methodology for Addressing Superheated Steam Releases to
 Ice Condenser Containments "Proprietary version withheld
 (ref 10CFR2 790)
 TUCKER-H B Duke Power Co 84/03/28 DENTON,H R Office of
 Nuclear Reactor Regulation, Director ADENGAM,E 0 Licensing Branch
 4 2pp 22819 001 24X Fiche 50-413,84/03/28.840300107
- --8403300116 Requests proprietary "Methodology for Addressing Superheated Steam Releases to Ice Condenser Containments," be withheld from public disclosure per iOCFR2 790 HIESEMANN.R A Hestinghouse Electric Corp 84/03/26 DENYON,H R Office of Nuclear Reactor Regulation, Director 8pp 22819 003 24X Fiche 50-413,84/03/28,8403300107
- --B403300119'Nonproprietary, "Methodology for Addressing Superheated Steam Releases to Ice Condenser Containments" * Westinghouse Electric Corp 84/03/28 240pp 22819 011 24X Fiche 50-413,84/03/28.8403300107
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403120153 Forwards revised Procedures 8D-DP-003, "Process Control Program ," SD-DP-042, "Assembly & Disassembly Procedure " & SD-DP-042, "Assembly & Disassembly Procedure for Mobile Coment " per FGAR Question 460 il & SER Section 11 4 l TUCKER, H B Duke Power Co 83/10/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAME & Licensing Branch 4 2pp 22586 188 24% Fiche 80-413,83/10/28,8403120153
- ---8403120156 Rev M to Procedure SD-DP-003. "Process Control for Chem-Nuclear Sys. Inc. Cament Solidification Units "
 # Chem-Nuclear Systems. Inc. 83/05/20 20pp 22586 187 24X Fiche 30-413,83/10/28.8403120153
- --8403120158 Rev A to Procedure 8D-OP-042, "Assembly & Disassembly Procedure For Mobile Cement Solidification Unit 121 (MSU-C-121)" Chem-Nuclear Systems. Inc 82/10/22 14pp 22586.207 24X Fiche 50-413,83/10/28.8403120153
- --8403120161 Rev D to Procedure SD-OP-039, "Operating Procedure for Hobile Cement Solidification Unit 12! (MSU-C-121) " * Chem-Nuclear Systems, Inc. 83/11/17 27pp 22586 221 24X Fichs 50-413,83/10/28,8403120153
- 8403010335 Discusses mode to emergency response guidelines in response to SER & NUREO-0737. Suppl 1
 TUCKER. H B Duke Power Co 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENGAM, E 0 Licensing Branch
 4 2pp 22432 324 24X Fiche 50-413.84/02/22.8403010335.
- 8403050377 Notification of 840306-08 site visit & meeting w/util in Charlotte,NC & York County,8C to audit equipment environ qualification (8ER Outstanding Issue 4b)
 JABBOUR,K N Licensing Branch 4. 84/02/24. ADENSAM,E 0 Licensing Branch 4. 3pp 22527 258 24X Fichs 50-413,84/02/24,8403050377
- 8403070422 Notification of 840312 meeting w/util & Westinghouse in Bethesda.ND to discuss resolution of main steam line break analysis (BER Confirmatory Issue 12) JABBOUR.K N Licensing Branch 4 84/02/24 ADENBAM, E. Q Licensing Branch 4 3pp 22566 300. 24X Fiche. 50-413,84/02/24,8403070422
- 8403020317 Forwards Rev 10 to "Analysis of Hydrogen Control Measures at McGuire Nuclear Station," per 89ER 7 (NUREO-0422).
 TUCKER: H B Duke Power Co 84/02/79 DENTON: H R Office of Nuclear Reactor Regulation, Director ADENSAM, E Q. Licensing Branch 4 2pp, 22441:216 24X Fiche. 50-000, 84/02/29, 8403020317

- --8403020321 Rev 10 to "Analysis of Hydrogen Control Measures at McOusre Nuclear Station " * Duke Power Co 84/02/29 30pp 22441 218 24X Fiche 50-000.84/02/29.8403020317
- 8403200078 Advises that all essential equipment cooled by nuclear syc water sys requalified for 100 F.per 831013 ltr re SER Open Item 2
 - Open Item 2
 TUCKER.H B Duke Power Co 84/03/13 DENTUN,H R Office of
 Nuclear Reactor Regulation, Director ADEMSAM.E 0 Licensing Branch
 4. 1p 22699 i55 24X Fiche 50-413.84/03/13.8403200078
- 8403200221 Requests NRC approval of proposed fire brigade organization
- TUCKER, H B Duke Power Co 84/03/14 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E Q Licensing Branch 4 2pp 22700 022 24X Fiche. 50-413, 84/03/14, 8403200221
- 8403300079 Discusses redundant emergency lighting per SER Open Item 15 Lighting unnecessary in areas not manned during transient or accident conditions, Lighting available for maint in iisted
 - areas TUCKER.H B. Duke Power Co 84/03/23 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E O Licensing Branch 4. 2pp 22821 173, 24X Fiche 50-413,84/03/23,8403300077
- F. Security, medical, emergency & fire protection plans
- B403090254 Public version of revised crisis mgt plan implementing PROCURE FOR THE PROCESS OF THE STATE PARTY PARTY PARTY PARTY PROCESS OF THE STATE PARTY PA 22575 055 24X
- 8403060336 Revised emergency implementing procedures, including Procedures RP/0/A/5000/01 re classification of emergency. RP/0/A/5000/02 re notification of unusual event & RP/0/A/5000/03 re alert W/840227 ltr
 TUCKER, H B Duke Power Co 83/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ADEMSANE C Licensing 4. 198pp 22513 122 24X Fiche 50-413,83/12/08,8403060336 Licensing Branch
- 8403060225 Rev 11 to crisis mgt plan 9/840224 itr & public info pamphist. VAUGHN: T E Duks Power Co 84/02/02 66pp 22516 187 24X Fichs 50-000,84/02/02,8403040225
- 8403280102 Public version of revised emergency plan implementing procedures, including Procedure RP/0/A/5000/02 re notification of unusual event & RP/D/A/5000/03 re alert H/840312 ltr & JH Felton 840321 release memo BDLCH, H.E., COX, J W., TUCKER, H.B. Duke Power Co. 84/02/06, DENTON, H.R. Qffice of Nuclear Reactor Regulation, Director ADENSAM, E.O., Licensing Branch 4 267pp 22812 021 24X Fiche: 50-413, 84/02/06, 8403280102
- 8403010335 Discusses mods to emergency response guidelines in response to SER & NUREG-0737.8uppl 1
 TUCKER.H B. Duke Power Co B4/02/22 DENTON.H.R Office of Nuclear Rector Regulation. Director ADENSAM.E 9 Licensing Branc 4. 2pp. 22432-324 24X Fiche 30~413.84/02/22.8403010335. Licensing Branch
- 8402090006 Board Notification 84-034. Forwards R Voltmer 840206 memo to D Eisanhut re fire research results concerning fires in electrical cabinats in control roam.
 EISENHUT.D 0 Division of Licensing 84/02/23 PALLADING Commissioners. ip 22576 203 24X Fiche 50-000,84/02/23, 8800000006 8402070004
- --B4030B0316 Recommends that info re fire research results concerning fires in electrical cebinsts in control room be submitted for board notification, per NRR Ofc Ltr 19, dtd B21001 Further valuation of test data required:
 VOLLMER.R.H. Division of Engineering 84/02/
 Division of Licensing. 10pp. 22376 204 24X
 Fiche: 50-000, 84/02/23-8402090006. 84/02/06. EISENHUT, D 0
- 8403160086 Forwards IE Insp Repts 50-413/84-11 & 50-414/84-07 on 840131-0203. No violations or deviations identified DANCE: H C. Division of Project & Resident Programs, 84/02/27 TUCKER, H. B. Duke Power Co 2pp 22655:103 24% Fiche: 50-413,84/02/27,8403160086.
- --B403160092 IE insp Repts 50-413/84-11 & 50-414/84-07 on 840131-0203 No violations or deviations identified Major areas inspected fire protection/prevention.
 HILLER, M.H. Region 2, Office of Director CONLON, T E. Division MILLER. M.H. Region 2. Office of Director CONLON, T E. Division of Engineering & Operational Programs. 84/02/21 9pp 22655 105 24X Fiche: 50-419, 84/02/27, 8403160086. 22655 105

- 8403060419 Responds to EO Adensam 840120 itr transmitting summary of fire protection site audit on 831i01704 Fire protection sys valves will be locked in appropriate position since related circultry not supervised per NFPA 72D TUCKER.H B Dute Pawer Co 84/02/29 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAH,E O Licensing Branch 4 2pp 22518 190 24X Fiche 50-413.84/02/29,8403060419
- 8403050177 Forwards IE Insp Rept 50-413/84-24 on 840221-24 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/03/01 TUCKER.H B Duke Power Co 2pp 22487 062 24X Fiche 50-413.84/03/01.8403050177
- --8403050178 IE Insp Rept 50-413/84-24 on 840221-24 No violations or deviations identified Mayor areas inspected review of preoperational activities re protected & vital area physical barriers Details withheld (ref 100FR73 21)
 MODRE, D E Region 2, Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 84/03/01 ip 22489 064 24X Fiche 50-413,84/03/01.8403030177
- 8403160278 Extends invitation to attend 840316 workshop to discuss 10GHB50, App R requirements to attend equals workshop to discuss 10GFB50, App R requirements to results of recent insp to help resolve misunderstanding associated w/requirements LEHIB:R C Division of Project & Resident Programs 84/03/02 TUCKER.H B Duke Power Co 1p 22660 274 24X Fiche 50-000.84/03/02.8403160278
- 8403200221 Requests NRC approval of proposed fire brigade organization In SBER Duke Power Co 84/03/14 DENYON,H R Office of TUCKER.H B Duke Power Co 84/03/14 DENYON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E 0 Licensing Branch 4 2pp 22700 022 24X Fiche 50~413.84/03/14.8403200221
- 8403260073 Forwards proposed amends to proof & review Tech Specs reverification of position of inaccessible fire suppression & sprinkler sys vaives, high radiation area & radiological environ monitoring program
 TUCKER.H B Duke Power Co 84/03/20 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAN.E G Licensing Branch 1p 22746 284 24X Fiche 50-413,84/03/20,8403260073
- ~~8403260080 Proposed amends to proof & review Tech Specs re Action Statements 6 b & 17 b on position verification of inaccessible fire suppression & sprinkler sys valves, high radiation area & radiological environ monitoring program # Duke Power Co 84/03/20 38pp 22746 283 24% Fiche 50-413,84/03/20,8403260073
- G Adjudicatory correspondence
- 8403010209 Motion for extension of time Until 840323 to submit views on ASLB referral to ASLAB re rejection of Palmetta Aillance contention on reilability of Transamerica Delaval diese: generators
 JCHNBON, O E Hearing Branch 4 84/02/27 Atomic Safety and
 Licensing Appeal Panel Spp 22436 004 24% Fiche 50-413,84/02/29,
 8403010209
- 8403070033 Forwards joint proposed findings of fact & conclusions of law on Contentions PA44/CES018 re reactor embrittlement & joint Contention DES17 re adverse weather RILEY, J Carolina Environmental Study Group RILEY, J Palmstto Alliance 84/02/27 KELLEY, J, FOSTER, R, PURDOM, P Atomic Safety and Licensing Board Panel 1p 22541 165 24X Fiche 50-413.84/02/29,8403070033
- --8403070037 Proposed findings of fact & conclusions of law in form of partial initial decision on Contentions PA44/CEB0 iB reactor ambrittlement & Contention DES17 re adversa weather reactor emprittlement & Contention DESLY re-adverse Gential Centificate of Stv enci.
 RILEY, J. L. Carolina Environmental Study Group GUILD, R. Palmett Alliance GUILD, R. Guild, R. 84/02/29 34pp 22541 166 24X Fichs 50-413,84/02/29,8403070033
- 8403140123 Forwards NRC insp repts & accompanying violation notices re facility QA Encl repts & notices issued after close of Dec 1983 hearings Palmetto Alliance served w/notices & util responses JOHNSON, O E Hearing Branch 4 84/02/27 KELLEY, J L , PURDOM, P W , FOSTER, R F Atomic Safety and Licensing Board Pengl 28pp 22624,040 24X Fiche 50-413,84/02/27,8403140123
- 8403070050 Order granting staff request for extension to & including 840323 of time within which to submit views re ASLB 830223 referral order in proceeding SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 84/03/01 Office of the Executive Legal Director 2pp 22541 274, 24X Fiche 50-413,84/03/01,8403070050

- 8403060240 Forwards exercise evaluator focument used in conjunction w/840215-16 emergency mgt exercise.NUREO-0654.Rev 1 & portion of community issues survey dealing w/emergency planning W/o encis
 SHEARIN.R V Dute Power Co 84/03/02 GUILD.R Palmetto Alliance RiLEY.J L Affiliation Not Assigned 2pp 22516 157 24X
 Fiche 50-413.84/03/02.8403060240
- 8403070048 Response opposing Carolina Environ Study Group 840214 offer of proof re reactor vessel technology, fatigue at high temp; strain gauge technology & structural integrity or LHR components Certificate of Svc enci MCQARRY, J M Duke Power Co MCOARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds 84/03/02 Atomic Safety and Licensing Board Panel 14pp 22541 235 24X Fiche 50-413,84/03/02,8403070048
- B403i40043 Forwards J Smercak affidavit of nondiscipsure for assistance in preparation of staff proposed findings W/o enci JDHNBON.G E Hearing Branch 4. B4/03/02 KELLEY.J L Atomic Safety and Licensing Board Panel ip 22633 i19 24X Fiche 50-413.84/03/02.8403i40043
- 8403090112 Forwards supplied Palmetto Alliance proposed findings of fact & conclusions of law in form of partial initial decision Part V on honeycombing omitted due to in camera matl OUILD, R Guild, R GUILD, R Palmetto Alliance 84/03/06 KELLEY, J. L. FOSTER, R F., PURDAM, P W Atomic Safety and Licensing Board Panel 38pp 22575 218 24X Fiche 50-413,84/03/06.
- --8403090i15 Buppi to proposed findings of fact & conclusions of law in form of partial initial decision Certificate of Svc encl GUILD, R Paimetto Ailiance GUILD, R Guild, R 84/03/06, 36pp. 22575 256 24% Fiche 50-413,84/03/06,8403090i12
- 8403140124 Response opposing Carolina Environ Study Group 840216 motion to reopen record on reactor embrittlement Offer of proof as to matis acceptable Certificate of Svc enc!

 JOHNSON G E Hearing Branch 4. 84/03/07. Atomic Safety and Licensing Board Panel 9pp 22620 288 24X Fiche: 50-413.84/03/07.8403140124
- 8403140150 Notifies of 840313 enforcement conference in Atlanta, GA to inform licenser of weider B issue so corrective ection may be commenced Meeting summary will be forwarded to ABLB & parties to proceeding JOHNSGN, GE Hearing Branch 4 84/03/07 KELLEY, JL, FOBTER, RF, PURDON, PW Atomic Safety and Licensing Board Panel ip 22620 338 24X Fiche 50-413,84/03/07,8403140150
- B403i40i69 Informs of improper svc of Carolina Environ Btudy Group/ Palmetto Alliance proposed findings of fact & conclusions of law re adverse weather & nonreceipt of proposed findings on Contention 16 JOHNSON.0 E Hearing Branch 4. B4/03/07 KELLEY, J L , FOSTER, R F , PURDON, P W Atonic Bafety and Licensing Board Penei ip 22620 333 24X Fiche 50-413,84/03/07,8403140169
- B403i40046 Proposed findings of fact & conclusions of law in form of partial initial decision on Contention 6. Paimetto Alliance Contentions 16 & 44 & DEB Contention 17 Certificate of Svc encl JOHNSON. 0. E Hearing Branch 4 84/03/08 210pp 22633, 309 24X Fiche 50-413, 84/03/08.8403140046
- 8403130071 Forwards applicant interrogatories & request to produce documents re diesel generator contention.per 840223 order Related correspondence CARR.A V. Duke Power Co 84/03/11 RILEY.J L Carolina Environmental Study Group GUILD.R Guild, R 1p 22602 169 24X Fiche 50-413,84/03/11.8403130071
- --B403130077 Interrogatories & requests to produce documents on diesel generator contention to Carolina Environ Btudy Group & Paimetto Alliance Certificate of Bvc encl Related correspondence CARR.A V. Duke Power Co 84/03/11 Carolina Environmental Study Group 27pp. 22602 170 24X Fiche:50-413,84/03/11,8403130071
- 8403160029 Reply to intervenors & NRC staff proposed findings of fact & conclusions of law Certificete of Svc encl.
 MCGARRY, J. M. Duke Power Co. MCGARRY, L. M. Biskop, Libermen, Cook, Purcs11 & Reynolds 84/03/15 1979p 22654 123 24X
 Fiche: 50-413,84/03/15,8403160029.
- 8403190073 Forwards questions for FEMA witnesses to assist in preparation of testimony on offsite smergency planning contentions All testimony will be required to be filed on 840406 & 07 Hearing will commence on 8404024. W/o encl MGGURREN.H J Hearing Branch 3 84/03/15 PERRY, 8 Federal Emergency Management Agency. 1p 22666:135 24% Fiche. 30-413, 84/03/15, 8403190073

- 8403190174 Forwards "NRC Staff Supplemental Proposed Findings of Fact in Form of Partial initial Decision on In Camera Issues re Contention & (GA)." per 840307 telcon W/o encl JOHNSON.G. E Heering Branch 4 84/03/15 KELLEY, J.L., FOBTER.R.F., PURDOM.P.W. Atomic Safety and Licensing Board Panel 1p 22671:162 24X Fiche 50-413,84/03/15,8403190174
- 8403200042 Memorendum & order denying motion to defer further ection on two pending OL diesel generator contentions until efter BSER issuance FOSTER,R F., PURDOM,P W., KELLEY,J L. Atomic Sefety end Licensing Board Panel 84/03/16 Palmetto Alliance 3pp 22699 182 24X Fiche 50-413,84/03/16,8403200042
- 8403200007 Interrogetories & requests to produce documents to Caroline Environ Study Group & Palmetto Alliance on ASLB contention re diesel generator reliability Certificate of Svc encl Reieted correspondence
 CARR.A V Duke Power Co CARR.A V Bishop, Liberman, Cook, Purceil & Reynolds B4/03/17 Caroline Environmental Study Group 2ipp 22699 202. 24% Fiche 50-413, B4/03/17, B403200007.
- 8403220237 Supplemental interrogatories to util re emergency diesel contentions admitted by ASLB Certificate of Svc encl Related correspondence
 RILEY.J L. Carolina Environmental Study Group DBB 047 84/03/19
 Duke Power Co 5pp 22719.034 24X Fiche 50-413.84/03/19,
 8403220237
- 8403220233 Interrogetories & requests to produce documents re diesel generator contentions to applicent & NRC staff Cartificate of 8vc encl. Related correspondence QUILD, R Paimetto Aliiance QUILD, R Caroline Environmental Study Oroup. QUILD, R Ouiid, R DSB 047 84/03/22 Duke Power Co 20pp. 22719 014 24X Fiche 50-413.84/03/22,8403220233
- 8403270011 Notifies that svc list amended to reflect appointment of seperate board for emergency planning Sheerin 840302 ltr to Quild & Riley,840312 ltr to Guild & supplemental answers to interrogetories enci H/a encl Related correspondence SHEARIN.R V Duke Power Co DSB 114 84/03/22 MARQULIES,M B , LAZO.R M , HODER.F.F. Atomic Sefety end Licensing Board Penel 1p 22769 355 24X Fiche 50-413,84/03/22,8403270011
- 8403260367 Response to ASLB questions re whether memorendum referred to concerning diesei generators should be accepted & how ASLB should decide possed issues Referrel request feils to satisfy interlocutory review test. Certificate of Buc enci. MCGARRY, J M Duke Power Co MCGARRY, J M Bishop, Libermen, Cook, Purcell & Reynolds DSB 083 84/03/23 55pp 22760 079 24X Fiche 50-413,84/03/23.8403260367
- 8403270322 Views on ASLB 840223 referral of 840217 rejection of generic aspects of intervenors diesel generator contention Certificate of Svc enci JOHNSON G E Heering Branch 4. D88 i32 84/03/23 84pp 82789 069 24X Fiche 50-413.84/03/23.8403270322
- 8403290392 Motion to amené & suppl diesel generator contentions, or in elternative, motion for admission of new diesel generator contention ASLB urged to grant motion & edmit recasted contention OUILD, R Palmetto Aliiance DSB 192 84/03/23 Atomic Sefety end Licensing Boerd Panel 11pp 22814 153 24x Fiche 50-413,84/03/23,8403290382
- 8403290388 Memorendum on emergency diesel generator questions referred per 10CFR2.730 Acceptence of referral urged Certificate of syc enci GUILD, R Palmetto Alliance GUILD, R Carolina Environmentel Study Group CVILD, R Quild, R, D88 194 84/03/23 29pp, 22814 283 24X Fichs 30-413,84/03/23,8403290388.
- 8403290379 Responses to utll interrogetories & request to produce documents on dissel generator contention Certificate of Svc enci Reiated correspondence QUILD: R Palmetto Alliance QUILD: R Quild: R + Ceroline Environmental Study Group DSB 191 84/03/25 9pp 22814*144 24X Fiche. 50-413, 84/03/23, 8403290379.

J Insurence & indemnity information

8403140037 Forwards Endorsement 9 to NELIA Policy NF-281, ROBBINS, J. G. Mersh & McLennan, Inc. 84/03/05 DINITZ, I Assistent Director for State & Licansee Relations. 2pp 22633:122. 24X Fiche 50-413,84/03/05,8403140037

M Antitrust correspondence

- B4030B027B Forwards notice of finding of no significant antitrust changes & time for filing requests for resvaluation for transmittal to Ofc of FR for filing & publication REGAN: W H Site Analysis Branch 84/02/29 STUCKY. S W Docketing & Services Branch 1p 225B4 062 24X Fiche 50-413,84/02/29, 8403080278
- --8403080283 Notice of finding of no significant antitrust changes & time for filing requests for reavaluation REGAN,W H Bite Analysis Branch 84/02/29 3pp 22584 063 24x Fichs 30-413,84/02/29,8403080278
- G Inspection reports, IE Bulletins & Correspondence
- B4030B0203 Responds to FDIA request for documents from Mar 1977 Mar 1977 rs WR McAfee allegations Forwards App A documents Info also available in PDR FELTON, J.M Division of Rules and Records 84/01/24 GARDE, B P GAVETNMENT Accountability Project 2pp 22584 164 24X Fiche 50-413,84/01/24,84030B0203
- --8403080212 Discusses 791113-16 interviews w/craftsmen Interviewees selected by principal inspector.per TI 2512/4 criteria Related info encl.

 MURPHY-C E Region 3. Chicago. Reactor Construction & Engineering Support Branch 79/12/04 THORNSURG.H D Director's Office.

 Office of Inspection and Enforcement 9pp 22584 166 24X Fiche.50-413.84/01/24.8403080203
- 8403070012 Forwards IE Insp Rept 50-413/84-05 on 840109-13 No violations or deviations noted DANCE: H C Division of Project & Resident Programs 84/02/13 TUCKER, H. B Duke Power Co 2pp 22529,001 24X Fiche 50-413.84/02/13.8403070012
- --8403070017 IE Insp Rept 50-413/84-05 on 840107-13 No violations or deviations noted Major areas inspected containment structural intergrity test & containment integrated leak rate test
 LENAHAN.J J., WHITENER.H L., JAPE.F Region 2, Office of Director 84/02/07, 7pp 22529 003 24X Fiche 50-413,84/02/13,8403070012
- 8403160349 Forwards IE Insp Repts 50-413/84-03 & 50-414/84-03 on 840103-06 & 11-13 No violations or deviations noted DANCE.H C Division of Project & Resident Programs 84/02/17 TUCKER,H B Duke Power Co 2pp 22660 177 24X Fiche: 50-413,84/02/17,8403160343
- ---8403160356 Forwards IE Insp Repts 50-413/84-03 & 50-414/84-03 on 840103-06 & 11-13 No violations or deviations noted Proprietary review of document waived by util to assure distribution to parties in licensing proceeding DANCE, H C. Division of Project & Resident Programs 84/01/20 CARR, A V Duke Fower Co ip 22660 179 24X Fiche 50-413,84/02/17,8403160343
- --B403160363 IE Insp Repts 50-413/84-03 & 50-414/84-03 on B40103-06 & i1-13 No violations or deviations noted Major areas inspected containment spray-welding, welding math control & radiographic exam ECCNOMORS, Region 2, Office of Director, BLAKE, J. Division of Engineering & Operational Programs 84/01/20 9pp 22660 180 24X Fiche 50-413,84/02/17,8403160343
- 8403070327 Ack receipt of 840120 ltr informing NRC of steps taken to correct deviations noted in IE Insp Rept 50-413/83-45 DANCE: H C. Division of Project & Resident Programs. 84/02/22 TUCKER: H B Duke Power Co 1p 22546.315 24X Fiche: 50-413,84/02/22,8403070327
- --8403070331 Responds to NRC 831222 ltr re deviations noted in IE Insp Rept 50-413/83-45 Corrective actions complete retest of ABME Code piping thermal expansion will be performed during pracritical heatup of plant sys THIE8, A C Duke Power Co 84/01/20 D'REILLY, J P Region 2, Office of Director 3pp 22546;316 24X Fiche 50-413,84/02/22, 8403070327
- --8403070334 Forwards IE Insp Rapt 50-413/83-45 on 831115-18 & notics of deviation DANCE, H.C Division of Project & Resident Programs 83/12/22 TUCKER, H.B Duke Power Co. 2pp. 22546 319 24X Fiche 50-413, 84/02/22, 8403070327
- --8403070335 Notice of deviation from insp on 831115-18 * Region 2, Office of Director. 83/12/22 ip 22546:32i 24X Fiche:50-413,84/02/22,8403070327

- --8403070338 IE Insp Rept 50-413/83-45 on 83i115-18 Deviation identified failure to comply w/FBAR commitments for thermal expansion preoperational testing WHITENER; H L Region 2, Office of Director JAPE; F Division of Engineering & Operational Programs 83/12/20 6pp 22546-322 24% Fiche 30-413.84/02/22,8403070327
- 8403070205 Ack receipt of 840123 ltr supplementing 830908 response informing NRC of steps taken to correct violations noted in IE Insp Repts 30-413/83-17 & 50-414/83-16

 DANCE: H C Division of Project & Resident Programs 84/02/24 TUCKER: H B Dute Power Co ip 22538 359 24X

 Fiche 50-413.84/02/24,8403070205
- ---B403070210 Forwards revised response to NRC ltr re violations noted in IE Insp Repts 50-413/83-17 & 50-414/83-16 Corrective actions GA Procedure GA-140. "Inspector Certification," will be revised TUCKER.H D Duke Power Co B4/01/23 O'REILLY, J P Region 2, Office of Director 2pp 22538 360 24X Fiche 50-413, 84/02/24, B403070205
- 8403160253 Informs that no circuit breakers w/undervoltage trip attachments in use in safety-related application other than reactor trip sys. in response to IE Bulletin 83-09 TUCKER, H B Duke Power Co 84/02/24 O'REILLY, J P Region 2. Office of Director ip 22660 142 24X Fiche 50-413,84/02/24. 8403160253
- 8403140360 Forwards IE Inap Rept 50-413/84-16 on 840206-10. No violations or deviations noted DANCE.H C Division of Project & Resident Programs 84/02/24 TUCKER.H B Duke Power Co 2pp 22660 193 24X Fiche: 50-413.84/02/24.8403160360
- --8403160370 IE Insp Rept 50-413/84-16 on B40206-10 No violations or deviations noted Major areas inspected preoperational test results evaluation, reactor protection sys functional test procedure & engineered safeguard functional test TAYLOR.P A Region 2, Office of Director JAPE.F Division of Engineering & Operational Programs, 84/02/23 4pp 22660 195 24X Fiche 50-413.84/02/24.8403160360
- 8403160086 Forwards IE Insp Repts 50-413/84-11 & 50-414/84-07 on 840131-0203 No violations or deviations identified DANGE.H C Division of Project & Resident Programs 84/02/27 TUCKER,H B Date Power Co 2pp. 22655 103 24X Fiche.50-413.84/02/27.8403160086
- --8403160092 IE Insp Repts 50-419/84-11 & 50-414/84-07 on 840131-0203 No violations or deviations identified Major areas inspected fire protection/prevention MILLER, W H Region 2, Office of Director CONLON, T E Division of Engineering & Operational Programs 84/02/21 9pp 22655 105 24% Fichs 50-413,84/02/27,8403160086
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-00084/02/28,8401190072
- 8403270143 Forwards 1E Insp Rept 50-413/84-14 on 840204-09 No violations or deviations noted.

 DANGE, H C Division of Project & Resident Programs 84/02/28 TUCKER, H B, Duke Power Co 2pp 22806-079 24X Fiche 50-413,8402/28,8403290143
- --8403290147 IE Insp Rept 30-413/84-14 on 840206-09 No violations or deviations noted Major areas inspected QC for chemistry & radiochemistry, including GC programs chemistry lab & counting room facilities
 KUZD, 0 B Region 2, Office of Director, MONTOOMERY, D M Division of Engineering & Operational Programs 84/02/24 4pp 22806 081 24X Fiche 50-413,84/02/28,8403270143
- B403140123 Forwards NRC insp repts & accompanying violation notices refactifity GA Encl repts & notices issued after close of Dec 1793 hearings Palmetto Alliance served w/notices & util responses

 JCHNEON, O E Hearing Branch 4. 84/02/27 KELLEY, J L, PURDON, P W, FOSTER, R. F Atomic Safety and Licensing Board Panel 28pp

 22624-040 24X Fiche 50-413,84/02/27,8403140123
- 8403160143 Forwards final response to IE Bulletin 77-14, Rev i. Suppl 2 re GA program for seismic analysis of Seismic Catsgory i piping sys
 TUCKER: H B Duka Power Ca 84/02/27 O'REILLY, J P Region 2,
 Office of Director App 22655 321 24% Fiche 50-413, 84/02/29.

- B403030177 Forwards IE Insp Rept 30-413/84-24 on 840221-24 No violations or deviations identified DANCE,H C Division of Project & Resident Programs B4/03/01 TUCKER,H B Dute Power Co 2pp 22489 062 24X Fiche 50-413.84/03/01
- --8403050176 IE Insp Rept 50-413/84-24 on 840221-24 No violations or deviations identified Major areas inspected review of preoperational activities re protected & vital area physical barriers Details withheld (ref 10CFR73 21)
 MODRE, D E Region 2, Defice of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 84/03/01 19
 22487 064 24X Fiche 50-413,84/03/01,8403050177
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl QRACE. J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York. Inc 130pp 22552 327 24X Fiche 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp. 22553 098 24X Fithe 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list entl JURDANAE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 117pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W.L. iquid Nitrogen Cooling Components Below Ni1 Ductility Temp " Svc 11st enc1 JORDAN, E. L. Division of Emergency Preparedness & Engineering Responss (Post 830103) 84/03/05 Contoildated Edison Co. of New York, Inc. 117pp 22593 336 24X Fiche 50-000,84/03/05,8402090011
- 8403160211 Ack receipt of 840127 itr Informing NRC of steps taken to correct violations noted in [E Insp Rept 50-413/83-48 LEMIS.R C Division of Project & Resident Programs 84/03/05 TUCKER H B Duke Power Co 1p 22661 078 24X Fiche 50-413-84/03/05.8403140211
- --8403160216 Responds to NRC B31230 ltr re violations noted in IE Insp Rept 50-413/83-48 Violations denied Review of acceptance criteria statements in preoperational test procedures will be conducted TUCKER, H B Dute Power Co 84/01/27 O'REILLY, J P Region 2, Office of Director 3pp 22661 079 24X Fiche 50-413,84/03/05, 8403160211
- --8403160220 Forwards 1E Insp Rept 50-413/83-48 on 831116-21 & notice of violation LEHIS.R C Division of Project & Resident Programs 83/12/30 TUCKER,H B Duke Power Co 2pp 22651 082 24X Fiche 30-413,84/03/05,8403160211
- --8403160221 Notice of violation from insp on 831116-21 * Region 2, Office of Director 83/12/30 ip 22661.084 24X Ficha 50-413,84/03/05,8403160211
- --8403160224 IE Insp Rept 50-413/83-48 on 83i116-21 Violation noted failure to provide adequate acceptance criteria for preoperational pressurizer dynamic response functional test
 TAYLOR, P A Region 2, Office of Director. JAPE, F Division of Engineering & Operational Programs 83/12/17 App 22661 085 24% Fiche 30-413,84/03/05,8403160211
- 8402070024 IE info Notice 84-09, Rev 1, "Lessons Learnsd From Insps of Fire Protection Safe Shutdown Sys " Svc list enci JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 8402090028 JE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " Syc list enel JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584 186, 24% Fiche 50-000,84/03/07,8402090028
- B403i60273 Ack receipt of B40215 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-413/B3-52 k 50-414/B3-37 LEWIS,R C Division of Project & Resident Programs 84/03/08 TUCKER.H B Duke Power Co 1p. 22660/124 24% Fichs.50-413,84/03/08,8403i60273

. .

- --8403160299 Responds to NRC 840117 ltr re violations noted in IE Insp Repts 50-413/83-52 & 50-414/83-39 Corrective actions GA Procedure GA-130 revised to assure that util written qualifications for auditors in full compliance w/codes TUCKER.H B Duke Power Co 84/02/15 D'REILLY.J P Region 2. Dffice of Director 2pp 22660 125 24X Fichs 50-413,84/03/08, 8803160293
- --8403160307 Forwards IE Insp Repts 50-413/83-52 & 50-414/83-37 on 831212-16 & notice of violation LEWIB.R C Division of Project & Resident Programs 84/01/17 TUCKER.H B Duke Power Co 2pp 22660 127 24X Fiche 50-413.84/03/08.8403160273
- --8403160314 Notice of violation from insp on 831212-16 * Region 2, Office of Director 84/01/17 ip 22660 i27 24X Fiche 50-413.84/03/08.8403160293
- --8403140319 IE Insp Repts 50-413/83-52 & 50-414/83-39 on 831212-16 Violation noted fallure to establish personnel qualifications for auditors BELISTE, A A FOSTER, L SMITH, C Region 2, Office of Director 84/01/13 12pp 22660 130 24X Fiche 50-413,84/03/08,8403160293,
- 8402090031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG.R C Director's Offics, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823 094 24x Ficha 50-000,84/03/12,8402090031
- 8403290270 Ack receipt of 840305 ltr informing NRC of steps taken to correct violations noted in 1E insp Repts 50-413/83-21 & 50-414/83-22 LEWIS.R.C Division of Project & Resident Programs 84/03/15 TUCKER, H B Duke Power Co ip 22800 020 24X Fiche 50-413.84/03/15,8403290270
- --8403270276 Responds to NRC 830912 ltr re violations noted in IE insp Repts 50-413/83-21 & 50-414/83-22. Corrective actions GC insp criteria for cable pulling revised to clarify insps of cable bending radius & Unsupported length during routing TUCKER.H B Duke Power Co 84/03/05 O'REILLY, J P Region 2, Office of Director 3pp 22800 021 24X Fiche 50-413,84/03/15, 8403290270
- B402090043 IE info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities." Svc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche S0-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safaty-Related Sys " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22933 001 24X Ficha 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403020443 Forwards monthly status rept of offsite emergency preparatness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKB.W J Office of the Executive Director for Operations
 84/02/21 PALLADINO Commissioners 9pp. 22492-083 24X Fiche B0-000.64/02/21.8403020443.
- 9. Asportable occurrences, LERs & related correspondence
- 8403010451 Informs Commission of problems w/amergency diesel generators mfg by Transamerica Delaval, Inc DIRCKS.W J Office of the Executive Director for Operations 8ECY-83-034 84/01/25 4pp 22438 347 24X Fiche. 30-000, 84/01/25, 8403010451
- 8403010140 Significant Deficiency Rept 8D 413-414/84-02 reunconsidered effects of superheated steam possibly resulting in increased lower containment temp Meeting on 840312 requested TUCKER, H B Duke Power Co. 84/02/17 D'REILLY, J.P. Region 2, Office of Director. 2pp 22435 322 24X Fiche: 50-413, 84/02/17, 8403010140
- B403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, dimpel NPB-4 T&T valves to close. Encl 1tr dtd 840203 sent to listed utils OE notified of affected units in BWR plants
 THERQUX, R R Terry Corp 84/02/22. WOODRUFF, R. W Director's Office, Office of Inspection and Enforcement 6pp 22706:327. 24X Fiche 50-000, 84/02/22, 8403210032

- 8403070226 Bignificant Deficiency Rept 413-414/82-04 amending corrective actions to previously submitted rept Reinsp of inaccessible deficient supports may be waived if documented evaluation of design analysis provided TUCKER. H B Duke Power Co 84/02/24 O'REILLY. J P Region 2, Office of Director 2pp 22573 261 24X Fiche 50-413.84/02/24, 8403070226
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Deiaval. Inc Owners Group program commitments Rept evaluates creaks in AF piston skirts in Shoreham & Orand Oulf Nuclear Power Stations MUSELER, W J TDI (Transamerica Delaval, Inc) Owners Group 84/02/27 DENTON. H R Defice of Nuclear Reactor Regulation, Director 3pp 28434 090 24X Fiche 50-000,84/02/27,8403010207
- B403070241 Interim Bignificant Deficiency Repts SD-413/82-27 & SD-414/82-27 re cracked cell containers Six cracked cells returned to Nife for investigation & resolution Site personnel will conduct weekly battery insp TUCKER, H B Duke Power Co 84/02/27 D'REILLY, J P Region 2, Office of Director 2pp 22572 302 24X Fiche 50-413,84/02/27,8403070241
- B402090021 Board Notification B4-039 discusses NRC 840210 & 16 meetings w/Transamerica Delaval.inc Emergency Diesel Cenerators Owners Group Meeting scheduled on B40308 for finalization of generic program plan prior to NRC review EIBENHUT.D.G Division of Licensing 84/02/28 PALLADING Commissioners 5pp 22946 003 24X Fiche 50-000, 84/02/28, 8402090021
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Dslaval, Inc. emergency dissel generators MUSELER, W. J. TDI (Transamerica Delaval, Inc.) Owners Group 84/02/28 DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Flohs 50-000,84/02/28,8403010218
- B402090020 Board Notification 84-044 forwards Part 21 rept ro Transamerica Delaval. Inc turbocharger thrust bearing Jubrication defect resulting in engine nonavailability EISENNUT.D G Division of Licensing 84/02/29 PALLADING. OILINSKY, ROBERTS Commissioners 4pp 22541-263 24X Ficha 30-000.84/02/29,8402090020
- B40314D048 Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval, Inc Diesel Generators Gwners Group Program Plan," to resolve concerns w/emergency diesel generators MUBELER, W J. Long Island Lighting Co. 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22626 062 24X Fichs 50-000,84/03/02,8403140048
- --8403140095 "Transamerica Delaval. Inc Digsel Generators Clumers Group Program Plan " * TDI (Transamerica Delaval. Inc) Owners Group. 84/03/02 261pp 22628 223 24X Fiche 50-000.84/03/02.8403140048
- 8403130128 Update of Significant Deficiency Rept 414/82-25 Item should be renumbered 413-414/82-25 All necessary actions completed TUCKER.H B Duke Power Co 84/03/02 O'REILLY, J P Region 2, Office of Director ip 22639.332. 24X Fiche 50-413,84/03/02,8403150128
- 8403150065 Final Bignificant Deficiency Rept 8D 413/83-07 re vent/drain valve installation & insp GA inspectors retrained Vent/drains inspected prior to 830713 reinspected to verify that intent of Design Drawing CN-1680-47 met TUCKER H B Duke Power Co. 84/03/05 O'REILLY, J P Region 2, Dffice of Director 3pp 22646 019 RAX Fiche 50-413,84/03/05,8403150065
- 8402090033 Board Notification 84-047 forwards Transamerica Delaval. Inc Owners Group piston skirt rept & task descriptions, EISENHUT, D O Division of Licensing, 84/03/07 PALLADING Commissioners App 22674 221 24X Fichs 50-000,84/03/07, 8402090033
- 8403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry

 DODSON: J P Facific Air Products Co 84/03/09. Director's Office, Office of Insection and Enforcement 7pp 22624 068 24X Fichs 50-000,84/03/09,8403140122.
- 8402090038 Board Notification 84-051 forwards "Transamerica Delaval, Inc (TDI) Diesel Generators Owners Group Program Plan " EIBENHUT, D G Division of Licensing 84/03/12 PALLADINO Commissioners 5pp. 22688 214 24X Fiche 50-000, 84/03/12, 8402090038.

- 8402070037 Board Notification 84-032 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval.inc (TDI) Comers Group Distribution list encl EISENHUT.D Q Division of Licensing 84/03/12 PALLADIND Commissioners 5pp 22708 COI 24x Fiche 30-000,84/03/12,8402070037
- --8403040534 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Duners Group in Bethesda,MD re problems w/emergency
 diesel generatore
 CARUSO.R Licensing Branch 2 84/02/27 O'REILLY,JP NRC No
 Detailed Affiliation Given 6pp 22708 004 24x
 Fiche 50-000,64/03/12,840290037
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Buthesda, MD re problems w/emergency diesel generators * NRC ~ No Detailed Affiliation Olven 84/02/10 147pp 67201 008 24X Fiche 50-000,84/03/12,8402090039
- --8403070409 Summary of 840216 meeting u/Transamerica Delaval, Inc Owners Group in Wading River,NY re program plan to establish reliability of diesel generators Agenda meeting transcript & attendance list encl.

 MILLER,M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 50-000,84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000,84/03/12,8402090039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Dalaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators
 MUSELER, W. J. Long Island Lighting Co. 84/03/12 DENTON, H.R.
 Office of Nuclear Reactor Regulation, Director 2pp 22632 074
 24% Fiche 50-000,84/03/12,8403140050
- 8403150133 Forwards "Transamerica Delaval, Inq Diesel Generator Rocker Arm Capacrew Btress Analysis Rept " Capacrew design adequate for applicable engines & svc conditions MUSELER, W. J. TDI (Transamerica Delaval, Inc.) Owners Group 84/03/13 DENTON: H.R. Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24% Fiche 50-000,84/03/13,8403150133
- B403290244 Final Significant Deficiency Rept 5D 413-414/83-14 re smal conduit connection to safety-related equipment located in harsh environs Initially reported on B31102 Util continuing to evaluate alternative scaling methods
 TUCKER. H B Duke Power Co 84/03/15 O'REILLY, J P Region 2, Office of Director 3pp 22800 224 24X Fiche 50-413,84/03/15,8403270244
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number, model & syc number, customer name & address, rating, date shipped & date started enci
 MATHEMS, C S Transamerica Delayal, Inc 84/03/16 & ESENHUT, D G Division of Licensing 20pp 22671 179 24X Fiche 50-000,84/03/16, 8403200222
- 8403300126 Final Significant Daficiency Rept 413/82-07 re overtorquing of ITT-Phillips concrete expansion anchors to close excessive plate to concrete gaps on plpe support Initially reported on 820210 Anchors will be retorqued TUCKER: H B. Duke Power Co 64/03/16 O'REILLY, J P Region 2, Diffice of Director. Spp 22819 357 24X Fiche 50-413:84/03/16, 8403300126
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by S&W for Transamerica Delaval.Inc (TDI) Diesel Generator Owners Group MUSELER,W J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/23 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22774 001 24X Fiche 50-000,84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term Corrective actions & investigations re Transamerica Delaval diesel generators List of suggested meeting topics encl.

 MCGAUGHY, J. P. TDI (Transamerica Delaval, Inc.) Owners Group 84/03/23 DENTON, H. R. Office of Nuclear Reactor Regulation, Dirsctor 4pp 22769 133 24X Fiche 50-000,84/03/23,8403270134

T Hearing transcripts on non-entitrust matters

- B402090039 Board Notification B4-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Deleval, Inc (TDI) Duners Group Distribution list enci.

 EISENHUT, D 0 Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22708 0Di, 24X Fiche 50-000, 84/03/12, 8402090039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Duners Group in Sethes6. MD re problems w/emergency
 dissel generators
 CARUSO.R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No
 Detailed Affilietion Given 6pp 22708 006 24X
 Fiche 50-000,84/03/12.8402090037
- --8403060554 Trenscript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, HD re problems w/emergency diesel generators > NRC - No Detailed Affiliation Given 84/02/10 147pp 6/201.008 24X Fiche 50-000, 84/03/12:8402090039
- --8403070409 Summary of 840216 masting w/Transemerica Delavai, Inc Duners Group in Wading River,NY re program plan to establish reliability of diesel generators Agenda, meating transcript & attendance list encl HILLER,M A Licensing Branch 4 84/02/27 Licensing Branch 4 Bpp 22708 161 24X Fiche 50-000,84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval. Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000,84/03/12,8402090039
- 8403160236 Transcript of 840314 telcon re facility Pp 12.580-12.624 * Atomic Safety and Licensing Board Panel 84/03/14, 45pp. 22660 208 24x Fiche 50-413.84/03/14.8403160236
- 8403260251 Transcript of 840321 talaphone conference in Bethesda.MD Pp 1-24 * Atomic Safety and Licensing Board Panel 84/03/21 28pp 22754 283 24X Fiche 50-413.84/03/21.8403260251

DOCKET 50-414 CATAMEA NUCLEAR STATION, UNIT 2 A Application/construction stage documents & correspondence

- 8403080196 FDIA request for documents re WR McAfee allegations involving facility from Mar 1977 ~ Har 1979, NRC open conference at site in Nov 1979 & review of wtil topical OA manual OARDE. B P . ANSELL. E Covernment Accountability Project 83/11/2i Office of Administration 2pp 22984 162 24X Fiche 30-413.83/11/21.8403080196
- 8403050477 Notification of 840313 meeting w/util in York County, SC to conduct confirmatory site visit per Section 13 & of SRP (NVREQ-0800)

 JABBOUR, K N Licensing Branch 4 84/02/24 ADENSAM, £ O Licensing Branch 4 3pp 22547 340 24% Fiche 50-413,84/02/24,8403060477
- 8402070017 Board Notification 84-038 forwards RJ Mattson 840123 memo to DO Eisenbut providing status update of NRC actions re Hestinghouse ECCS actuation logic EISENNUT.D 0 Division of Licensing 84/02/27 PALLADIND Commissioners 7pp 22346 007. 24X Fichs 50-000,84/02/27,
- 8403070185 Forwards equipment date sheets for SORT & pump & valve operability review team onsite audits Gwalification of components complete Whitve oversize drawings Aperture cards are available in FDR TUCKER, H B DWR Fower Co B4/02/28 DENTON-H R Office of Nuclear Reactor Regulation, Director ADENSAM.E Q, Licensing Branch 4 601pp 22536 281 24% Fiche 50-413,84/02/28,8403070185.
- ---8403070202 Rev 10 to Procedure CNS-1390 01-00-0073, "Installation Spec Manual Mechanical Installation Procedure for Electrical Penatration Types B.C. D.F. G.H.J.K.L. & H. " a Dute Power Co. 83/08/24 36pp 22537 087 24X Fichs 50-413,84/02/28,8403070185
- --8403070219 Rev B to Procedure CNS-1390 01-00-0071, "Procedure for Installation of Type A (6,900 Volt) Electric Penstration Assemblies "
 BOVER R P Duke Power Co. E3/03/07 350pp 22537-167. 24X Fiche: 50-413,84/02/28,8403070185

- 8402090016 Board Notification 84-031 informs that Commission received affidavit from former util employee alleging that util deliberately undermined GA program at facilities investigation in progress.

 NOVAK.T K Assistant Director for Licensing 84/02/29 KELLY.J., PURDOM.P. FOSTER.R Atomic Sefety and Licensing Board Panel 3pp 67217 043 24X Fiche 50-413.84/02/29.8402090016
- 8403190394 Forwards nonproprietary & proprietary "Technical Basis For Eliminating Pressurizer Surge Lina Ruptures as Structural Design Basis for Catawba, Units 1 & 2 " Revised FBAR pages also encl Proprietary rept withheld (ref 10CFR2 790)
 TUCKER.H B Duke Power Co BA/02/29 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSANE & Licensing Branch 4 Jpp 22674 089 24X Fiche 50-413.84/02/29,8403190394
- --8403190399 Application for withholding proprietary rept HCAP-10487, "Technical Basis for Eliminating Pressurizer Surge Line Ruptures as Structural Design Basis "
 MIESEMANN.R A Westinghouse Electric Corp 84/02/15. DENTON.H R Office of Nuclear Reactor Regulation. Director. 9pp 22674:092 24X Fiche 30-413.84/02/29,8403190394
- --8403170404 Nonproprietary "Technical Besis for Eliminating Pressuring Surge Line Ruptures as Structural Design Basis for Catawba Units 1 & 2" SHAMY, S A , YANG, C Y. SANE, A D. Westinghouse Electric Gorg WCAP-10488 (NP) 84/02/10 107pp 22674.101. 24X Fichs 50-413,84/02/29,8403190374
- 8403060422 Provides second suppl to 831118 submittal & eddl info on positive aspects of elimination of arbitrary intermediate pips breaks from facilities
 TUCKER.H.B Duke Power Co 84/03/01. DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAN.E Q. Licensing Branth 4 29p 22511 359 24X Fiche 50-413.84/03/01.8403060422
- 8403190257 Forwards "Steam Prassure Suppression Characteristics of Water-Soluble Plastic Membrane Shielded Ice for Ice Condenser Containment Nuclear Power Plants" TUCKER, H.B. Duke Power Co. 84/03/07 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 7pp. 22672 102 24X Fiche 50-000,84/03/07,8403190257
- 8403280122 Summary of 840224 meeting w/Hestinghouse Owners Orcup in Bathesda. MD re proposed Westinghouse steam generator tube rupture generic program Attendee list & agenda and 1 NERSES, V Licensing Branch 3. 84/03/07 Licensing Branch 3 35pp 22811 131 24X Fiche 50-000.84/03/07.8403280122.
- 8403130104 Provides clarification of third paragraph of 840227 ltr repossibility of welded piping attachments being located in close proximity to sliminated arbitrary intermediate breaks TUCKER. H B Duke Power Co 84/03/08 DENYDN. H R Office of Nuclear Reactor Regulation, Director AbensAM: E 9. Licensing Branch 4 29p 22600 256 24K Fichs 30-413.88/03/08.8403130104
- B403i6D197 Forwards responses to EQ Adensem 820401 request for qualification documentation re operability of containment purge & vent valves in Modes 1-4 per Tech Rocc 3 6.19
 TUCKER: H B Dute Power Co. 84/03/12 DENTON.H.R Office of Nuclear Reactor Regulation, Director ADENSAM.E.O Licensing Branch 4 333pp 22638 185 24% Fiche 50-413.84/03/12.8403i60197
- 8402070041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications FISENHUT.D O Division of Licensing 84/03/14 Atomic Safety and Licensing Board Fanel 10pp 24% Fiche 50-000.84/03/14.8402090041.
- 8403200165 Forwards summary of experience for operations personnel to be licensed on Unit 1,per 840114 & 0226 commitments Based on operating shift experience requirements, sufficient experience available to startup & operate Unit 1 TUCKER.H.B. Duke Power Co. 84/03/14. DENTON.H.R. Office of Nuclear Resctor Regulation, Director ADENSAH.E.O. Licensing Branch 4 120p 22697 001. 24X Fiche.50-413,84/03/14,8403200165
- 8403220074 Requests that snubber Tech Spece be written to reflect insponunit basis instead of current sys basis, Conclusions from review of J Sapir 740301 ltr re Tech Specs for snubber operability & surveillance listed TUCKER.H B Duke Power Co 84/03/15 DENTON,H.R. Office of Nuclear Reactor Regulation, Director ADENSAM,E Q. Licensing Branch 2pp 22712-306 24X Fichs: 50-413,84/03/15,8403220074.
- 8403270213 Forwards response to follows questions from 840209 meeting re-environ qualification of DO Obrian electrical penetrations Tests verify adequacy of Type K module for plant applications.

 TUCKER, H B Duke Power Co. 84/03/16, DENTON, H. R. Office of Nuclear Reactor Regulations Director. ADENSAM, E. O. Licensing Branch 4 4pp. 22770:273 24X Fichs 50-413.84/03/16,8403270213.

- 8403300188 Provides plant-specific info & generic info omitted from Westinghouse Owners Group 831201 & 840312 itrs, in response to Generic Ltr 83-100 lesues re reactor coolant pump trip resolved
 - resolved
 TUCKER,H B Duke Power Co 84/03/26 DENTON.H R. Office of
 Nuclear Reactor Regulation, Director EISEMHUT,D G Division of
 Licensing 3pp 22819 292 24X Fiche 50-413,84/03/26,8403300188
- 8403300107 Forwarde proprietary & nonproprietary versions of,
 "Methodology for Addressing Superheated Steam Releases to
 Ice Condenser Containmente " Proprietary version withheld
 iref 10CFR2 790)
 TUCKER, H. B. Duke Power Co. 84/03/28 DENTON, H. R. Office of
 Nuclear Reactor Regulation, Director ADENSAM.E. 9 Licensing Branch
 4 2pp. 22819 001 24X Fiche 50-413,84/03/28,8403300107
- --8403300116 Requeste proprietary "Methodology for Addressing Superheated Steam Releases to Ice Condenser Containments," be withheld from public disclosure per IOCR2 790 WIESEMANN.R.A. Westinghouse Electric Corp 84/03/26. DENTON.H R Office of Nucleer Reactor Regulation, Director 8pp 22819 003 24X Fiche: 50-413,84/03/28,8403300107
- --8403300117 Nonproprietary, "Methodology for Addressing Superheeted Steam Releases to Ice Condenser Containments" + Westinghouse Electric Corp 84/03/28 240pp 22819.011. 24X Fichs. 50-413,84/03/28.8403300107
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403120153 Forwards revised Procedures SD-DP-003, "Process Control Program ," SD-DP-042, "Assembly & Disassembly Procedure " & SD-DP-37, "Operating Procedure for Mobile Cament. ." per FSAR Guestion 460 11 & EER Section 11, 4 1. TUCKER, H. B. Duke Power Co 83/10/28, DENTON, H. R. Diffice of Nuclear Reactor Regulation, Director ADENSAME Q. Licensing Branch 4 2pp. 22586 185. 24X Fiche 50-413,83/10/28,8403120153
- B403010335 Discusses mode to emergency response guidelines in response to SER & NUREG-0737. Suppl i TUCKER. H. B. Duke Power Co B4/02/22 DENTON. H. R. Office of Nuclear Reactor Regulation, Director 2pp 22432 324. 24X Fiche: 50-413, 84/02/22, 8403010335
- 8403050377 Notification of 840306-08 with visit & meeting w/util in Charlotte.NC & York County.80 to audit equipment environ qualification (SER Outstanding Issue 4b)
 JABEOUR.K N. Licensing Brench 4. 84/02/24 ADENBAM.E G. Licensing Branch 4. 3pp. 22527.258 24X Fiche 50-413.84/02/24.8403050377
- 8403070422 Notification of 840312 meeting w/util & Westinghouse in Bethesda, MD to discuss resolution of main steem line break analysis (SER Confirmatory leeue 12)
 JABBUN, K. N. Liceneing Branch 4 84702/24, ADENSAM, E. 9 Liceneing Branch 4. 3pp. 22566:300 24X Fiche: 50-413, 84/02/24, 8403070422
- 8403020317 Forwards Rev 10 to "Analysis of Hydrogen Control Measures at McQuire Nuclear Station." per 88ER 7 (NUREQ-0422) TUCKER, H B Duke Power Co. 84/02/29 DENTON. H R Office of Nuclear Reactor Regulation, Director 2pp. 22441 216 24X Fiche: 50-000,84/02/29,8403020317
- --B403020321 Rev 10 to "Anelysis of Hydrogen Control Measures at McGuire Nuclear Station," * Bulke Power Co. B4/02/29, 50pp 22441.218 24X Fiche: 50-000,84/02/29,8403020317
- 840320307B Advises that all essential equipment cooled by nuclear evolution system as requalified for 100 F, per 831013 ltr re SER Open Item 2.
 TUCKER, H. B. Duke Power Co. 84/03/13 DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director ADEMBAN, E. O. Licensing Branch 4. 1p. 22699, 135. 24X Fiche 50-413, 84/03/13, 8403200078
- 8403200221 Requests NRC approval of proposed fire brigade organization in SBER.
 TUCKER, H B. Duke Power Co. 84/03/14. DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 22700, 022. 24X Fiche. 50~413.84/03/14,8403200221.
- 8403300079 Discusses redundant emergency lighting per BER Open Item 15 Lighting unnecessary in areas not manned during transisht or accident conditions Lighting available for maint in listed areas.

 TUCKER: H. B. Duke Power Co. 84/03/29 DENTON.H.R Office of Nuclear Reactor Regulation, Director ADENBAM.E.O Licensing Branch 4, 2pp 22821:173 24X Fiche 50-413,84/03/20,8403300079

- F Security, medical, emergency & fire protection plans
- 8403070254 Public version of revised crisis mgt plan implementing procedures: including Procedures 5 3 4 re scheduling/planning support group, 5 3 6 re radiological support group & 5 3 7 re technical support group W/831107 Itr & JM Felton memo TUCKER, H B Duke Power Co 83/10/31 271pp 22395 055 24X Fiche 50-000.83/10/31.8403070254
- 8403060336 Revised emergency implementing procedures including Procedures RP/0/A/5000/01 re classification of emergency. RP/0/A/5000/02 re natification of unusual event & RP/0/A/5000/03 re alert W/840227 ltr
 TUCKER.H B Duke Power Co 83/12/08 DENTON.H R Office of Nuclear Reactor Repulation. Director ADENSAN.E G Licensing Branch 4 198pp. 22513 122 24% Fiche 50-413,63/12/08,8403040334
- 8403060225 Rev 11 to crisis mgt plan W/840224 ltr & public info pamphlet VAUGHN.T E Duke Power Co 84/02/02 66pp 22516 189. 24X Fiche 50-000, 84/02/02, 8403060225
- 8403280102 Public version of revised emergency plan implementing procedures, including Procedure RP/D/A/5000/02 re notification of unusual event & RP/D/A/5000/03 re alert. W/840312 ltr & JM Felton 840321 release memo BDLCH.M.E : COX.J W : TUCKER.H.B Duke Power Co 84/02/06 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM.E O. Licensing Branch 4 267pp 22812 021 24X Fiche 50-413,84/02/06.8403280102
- 8403010335 Discusses mads to emergency response guidelines in response to SER & NUREQ-0737. Suppl 1
 TUCKER. H B Duke Power Co 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp. 22432:324 24X Fiche 50-413.84/02/22.8403010335
- 8402070004 Board Notification 84-034 forwards R Volimer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D 9. Division of Licensing 84/02/23 PALLADING Commissioners ip 22576 203 24X Fiche 50-000, 84/02/23, 8402090004
- --B403080316 Recommends that info re fire research results concerning firee in electrical cabinets in control room be submitted for board notification.per NRR Off Ltr 17,4td 821001 Further evaluation of test data required VOLLMER, R H Division of Engineering 84/02/06 EISENHUT.D 0 Division of Licensing 10pp 22576 204 24X Fichs: 50-000,84/02/23,8402090006
- 8403160086 Forwards IE Insp Repts 50-413/84-11 & 50-414/84-07 on 840131-0203 No violations or deviations identified DANCE: H C Division of Project & Resident Programs 84/02/27 TUCKER: H B Duke Power Co 2pp 22655 103 24X Ficher 50-413,84/02/27,8403160086
- --8403160092 IE imag Repte 30-413/84-11 & 50-414/84-07 on 840131-0203 No violations or deviations identified Major areas inspected fire protection/prevention MILLER.W.H. Region 2. Office of Director 84/02/21 9pp 22655:105 24X Fiche 50-413.84/02/27.8403160086
- 8403060419 Responds to EQ Adensam B40120 ltr transmitting summary of fire protection site audit on B31101-04 Fire protection sys valves will be locked in appropriate position since related circuitry not supervised per NFPA 72D TUCKER, M.B. Duke Fower Co 84/02/29 DENTON, H.R. Office of Nuclear Reactor Regulation. Director ADENSAM, E C Licensing Branch 4 2pp 22518:170 24X Fiche 50-413,84/02/29,8403060419
- 8403160278 Extends invitation to attend 840316 workshop to discuse 10CFR30. App R requirements & results of recent insp to help resolve misunderetanding associated whrequirements LEWISLR.C Division of Project & Resident Programs 84/03/02 TUCKER.H B. Duke Power Co. 1p 22660 274 24X Fiche 50-000.84/03/02.8403160278
- 8403200221 Requests NRC approval of proposed fire brigade organization in SSER.
 TUCKER, H. B. Duke Power Co. 84/03/14 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENBAM, E. O. Licensing Branch 4 2pp. 82700.022 24X Fichs: 50-413,84/03/14,8403200221

G Adjudicatory correspondence

- B403010209 Motion for extension of time until 840323 to submit views on ASLB referral to ASLAB re rejection of Palmetto Alllance contention on reliability of Transamerica Delaval diesel generators

 JOHNSON, 0 E Hearing Branch 4 B4/02/29 Atomic 8afety and Licensing Appeal Panel 3pp 22436 004 24% Fiche 30-413.84/02/29, 8403010209
- 8403070033 Forwards joint proposed findings of fact & conclusions of law on Contentions PA44/CES01B re reactor embrittlement & joint Contention DES17 re adverse weather RILEY. J Carolina Environmental Study Group RILEY, J Palmetto Alliance 84/02/29 KELLEY. J FOSTER. R PURDOM. P Atomic Safety and Licensing Board Panel 1p 22541 165 24X Fiche 90-413.84/02/29.8403070033
- --8403070037 Proposed findings of fact & conclusions of law in form of partia) initial decision on Contentions PA44/CESG 18 re reactor embrittlement & Contention DESI7 re adverse weather Certificate of Svc enci
 RILEY. J L Carolina Environmental Study Group GUILD.R Palmetto Alliance GUILD.R Guild. R 84/02/29 34pp 22541 166 24X Fiche 50-413.84/02/29,8403070033
- 8403140123 Forwards NRC insp repts & accompanying violation notices refacility QA Encl repts & notices issued after close of Dec 1983 hearings Palmetto Alliance served w/notices & util responses
 JOHNBON, G E Hearing Branch 4 84/02/27 KELLEY, J L , PURDOM, P W . FOSTER, F Atomic Safety and Licensing Board Panel 28pp.
 22624 040 24X Fiche 50-413,84/02/27,8403140123
- 8403070050 Order granting staff request for extension to & including 840323 of time within which to submit views re ASLB 830223 referral order in proceeding 840264 referral order in proceeding 840264 referral order in proceeding 840366 Office of the Executive Legal Director 2pp 22541 274 24X Fiche 50-413.84003/01.8403070050
- 8403060240 Forwards exercise evaluator document used in conjunction w/840215-16 amergency mgt exercise. NUREO-0654. Rev 1 & portion of community issues survey dealing w/emergency planning W/o encis SHEARIN. R V Duke Power Co 84/03/02 GUILD. R Palmetto Alliance RILEY. J L Affiliation Not Assigned 2pp 22516 137 24X Fiche 50-413.84/03/02.8403060240
- 640307094B Response opposing Carolina Environ Study Group 640214 offer of proof re reactor vessel technology, fatigue at high temp, strain gauge technology & structural integrity or LMR components Certificate of Svc ancl MCOARRY, J M Bishop, Liberman, Couk, Purcell & Reynolds 64/03/02 Atomic Safety and Licensing Board Ranel 14pp 22541 235 24X Fiche 50-413,84/03/02,840307004B
- 8403140043 Forwards J Smercak affidavit of nondisclosure for assistance in preparation of staff proposed findings W/o encl JOHNBON, G E Hearing Branch 4 BA/O3/O2 KELLEY, J L Atomic Safety and Licensing Board Panel 1p 22633 119 24x Fiche 50-413,84/03/O2,8403140043
- 8403090112 Forwards suppl to Palmetto Alliance proposed findings of fact & conclusions of law in form of partial initial decision Part V on honeycombing unitted dus to in camera matl GUILD, R Guild, R GUILD, R. Palmetto Alliance 84/03/06 KELLEY, J L. FOSTER, R F., PURDAM, P W Atomic Safety and Licensing Epard Panel 38pp 22375 218 24% Fiche 50-413,84/03/06,8403970112
- --8403090(13 Suppl to proposed findings of fact & conclusions of law in form of partial initial decision Certificate of Svc encl, OUILD:R Palmetto Alliance QUILD:R Quild:R 64/03/06 36pp 28575 256 24% Fiche 30-413,84/03/06,8403090112
- 8403140124 Response opposing Carolina Environ Study Group 840216 motion to reopen record on reactor embrittlement Offer of proof as to matis acceptable Certificate of Svc encl
 JOHNSON.0 E Hearing Branch 4 84/03/07 Atomic Safety and Licensing Board Panel 7pp 22620 288 24X Fiche.50-413,84/03/07, 8403140124
- 8403140130 Notlfiss of 840313 enforcement conference in Atlanta, QA to Inform licensee of welder B issue so corrective action may be commenced Heeting summary will be forwarded to ASLB & parties to proceeding JDHNDDN.Q.E Hearing Branch 4 84/03/07 KELLEY, J. FOSTER.R F. PURDDN.P H. Atomic Safety and Licensing Board Panel ip 22620,338 24% Fiche 50-413.84/03/07.8403140150

B403140169 Informs of improper svc of Carolina Environ Study Group/ Palmetto Alliance proposed findings of fact & conclusions of law re adverse weather & nonreceipt of proposed findings on Contention 16 JOHNSON.0 E Hearing Branch 4 84/03/07 KELLEY, J L FOBTER.R F , PURDON.P H Atomic Safety and Licensing Board Panel 1p 22620 333 24X Fiche 50-413.84/03/07.8403140169 1

- 8403140046 Proposed findings of fact & conclusions of law in form of partial initial decision on Contention 4.Palmetto Alliance Contentions 16 & 44 & DES Contention 17 Certificate of Svc sncl JUHNSON, C E Hearing Branch 4 84/03/08 210pp, 22633-309 24X Fiche 30-413-84/03/08.0403140046
- B403130071 Forwards applicant Interrogatories & request to produce documents re diesel generator contention, per 840223 order Related correspondence CARR.A V Duke Power Co 84/03/11 RILEY, J L Carolina Environmental Study Group. GUILD.R Guild, R lp 22602 169, 24% Fiche 50~413.84/03/11.8403130071
- --B403130077 Interrogatories & requests to produce documents on dissel generator contention to Carolina Environ Study Group & Palmetto Alliance Cartiflicate of Byc encl Related correspondence CARR, A V Duke Power Co B4/03/11 Carolina Environmental Study Group 27pp 22402 170 24X Fiche 50-413,84/03/11,
- 8403160027 Reply to intervenors & NRC staff proposed findings of fact & conclusions of law Certificate of Svc encl MCGARRY, J M Duke Power Co MCGARRY, L, M Bishop, Liberman, Cook, Purcell & Reynolds 84/03/15 197pp 22654 123 24X Floke 50-413.84/03/15.8403160029
- 8403190073 Forwards questions for FEMA witnesses to assist in preparation of testimony on offsite emergency planning contentions All testimony will be required to be filed on 840405 & 09 Hearing will commence on 840424 W/o encl MCGURREN, H J Hearing Branch 3 84/03/15 PERRY, 8 Federal Emergency Management Appency 1 p 22664 135 24X Fiche 50-413,84/03/15,8403190073
- 8403190174 Forwards "NRC Staff Supplemental Proposed Findings of Fact In Form of Partial Initial Decision on In Camera Issues re Contention 6 (GA)," per 840307 telcon W/o encl JOHNSON, G.E Hearing Branch 4 84/03/15 KELLEY, J.L., FOSTER, R.F., PURDDM.P.W. Atomic Safety and Licensing Board Panel 1p 22671 162 24X Fichs 50-413,84/03/15,8403190174
- 8403200042 Memorandum & order denying motion to defer further action on two pending CL diesel generator contentions until after SEER Issuance FOSTER,R F. PURDDN.P W., KELLEY,J L. Atomic Safety and Licensing Board Fanel 84/03/16 Palmetto Alliance 3pp 22699,182. 24: Fiche 50-413,84/03/16,8403200042
- 8403208007 Interrogatories & requests to produce documents to Carolina Environ Study Graup & Palmetto Alliance on ARLB contention re diesel generator reliability Certificate of Svc encl Related correspondence CARR, A V Bishop, Liberman, Cook, Purcell & Reynolds 84/03/19 Carolina Environmental Study Group 21pp 22679.202 24X Fiche 50-413,84/03/19,8403200007
- 8403220237 Supplemental Interrogatories to util re emergency diesel contentions admitted by ASLB Certificate of Svc encl Related correspondence
 RILEY, J. L. Carolina Environmental Study Group DSB 047. 84/03/19
 Dute Power Co. 5pp. 22719 034 24X Fichs 50-413,84/03/19,
 04072200277
- 8403220233 Interrogatories & requests to produce documents re diesel generator contentions to applicant & NRC staff Certificate of SVC encl Related correspondence QUILD, R Palmetto Alliance QUILD, R Carolina Environmental Study Group GUILD, R Guild, R DBS 049 84/03/22 Dute Power Co. 20pp 22719 014 24X Fiche 50-413,84/03/22,8403220233.
- 8403270011 Notifies that svc list amended to reflect appointment of separate board for amergency planning Shearin 840302 ltr to Ouild & Riley, 840312 ltr to Guild & supplemental answers to interrogatories and W/o and. Related correspondence SHEARINR V Duke Power Co DSB 114 84/03/22, MARGULIEB, N B . LAZO,R M . HODPER, F F Atomic Safety and Licensing Board Panel. 19 22769 355 24X Fiche 50~413,84/03/22,8403270011

- 8403260367 Response to ASLB questions re whether memorandum referred to concarning diesal gamerators should be accepted & how ASLB should decide posed issues Referral request fails to satisfy interlocutory review test Certificate of Svc encl MCGARRY, JM Duke Power Co MCGARRY, JM Bishop, Liberman, Cook, Purcell & Reynolds DSB OBS 84/03/23 55pp 22760 079 24X Fichs 50-413,84/03/23,8403260367
- B40G270GR2 Viaws on ASLB 840223 refarral of 840217 rejection of generic aspects of intervenors diasel generator contantion Certificate of Svc encl JODNBON, G E Hearing Branch 4 DSB 132 84/03/23 84pp 22789 069 24X Ficha 50~413.84/03/23,8403270322
- 8403270382 Motion to amand & suppl dissel generator contantions, or in alternative, motion for admission of New dissel generator contantion ASLB urgad to grant motion & admit recested contantion GUILD, R Palmatto Allianca DSB 192 84/03/23 Atomic Safety and Licensing Board Panel 11pp 22814 153 24X Fichs 50-413,84/03/23,8403290382
- 8403290388 Memorandum on emergency diasai ganarator questions referred per 10GFR2 730 Accaptance of referral urged Certificate of syc encl.

 OUILD, R Peimetto Allianca GUILD, R Carolina Environmental Study Group. OUILD, R, Ouild, R DSS 194 84/03/23 29pp 22814*283, 24X Ficha*50-413,84/03/23,8403290388
- 8403290379 Responses to util interrogatories & request to produce documents on diesel generator contention Cartificate of Syc encI Related correspondance OUILD,R Palmatto Allianca GUILD,R Guild, R * Carolina Environmental 8tudy Group DSB 191 84/03/25 9pp 22814 144 24X Ficha 50-413,84/03/25,8403290379
- J Insurance & indomnity information
- B403140037 Forwards Endorsement 7 to NELIA Policy NF-201 ROBBINB, J G Marsh & McLennan, Inc 84/03/05 DINITZ, I Assistant Director for Stata & Licansae Relations 2pp 22633 122 24X Ficha: 50-413, 84/03/05, 8403140037
- G Inspection raports. IE Bullatins & correspondence
- 8403080203 Responds to FOIA request for documents from Har 1977 Mar 1979 ra WR McAfee allagations Forwards App A documents Info also available in PDR. FELTON, J M Division of Rules and Racords. 84/01/24 GARDE, 8. P 30varnmant Accountability Project. 2pp 22584 164 24X Ficha: 50-413, 84/01/24, 8403080203
- --8403080212 Discusses 791113-16 intarviews w/craftsmen Interviewess selected by principal inspector, par TI 2512/4 criteria Related info ancl MURPHY.CE Region 3. Chicago, Reactor Construction & Engineering Bupport Branch 79/12/04 THORNSURG.H D Director's Offica, Offica of Inspection and Enforcement 9pp 22584 166 24X Ficha: 50-413.84/01/24.8403080203
- 8403160343 Forwards IE Insp Rapts 50-413/84-03 & 50-414/84-03 on 840103-06 & 11-13 No violations or deviations noted BANCE.H.C Division of Project & Rasidant Programs 84/02/17 TUCKER.H B Duke Power Co. 2pp 22660 177 24X Ficha: 30-413,84/02/17,8403160343
- --B403160356 Forwards IE Insp Repts 50-413/B4-03 & 50-414/B4-03 on 840103-06 & 11-13. No violations or deviations notad Proprietary review of document waived by util to assuradistribution to parties in licansing proceading DANCE, H. C. Division of Project & Rasident Programs 84/01/20, CARR, A. V Duke Power Co. ip 22660 179 24X Fichs 50-413,84/02/17,8403160343
- --8403160363 IE Inep Repts 50-413/84-03 & 50-414/84-03 on 840103-06 & 11-13. No violations or deviations noted Major areas inspacted containment spray-walding, welding matl control & radiographic exam

 ECONOMORS N Region 2. Office of Director BLAKE, J, J Division of Enginaaring & Operational Programs. 84/01/20 9pp 22660 180. 24X Fiche: 50-413, 84/02/17, 8403160343
- B403070205 Ack receipt of B40123 ltr supplementing B30908 response informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/83-17 & 50-414/83-16 DANCE, H. C. Division of Project & Resident Programs B4/02/24 TUCKER, H. B. Duke Power Co. 1p 22538.359, 24X Fichs: 50-413,84/02/24,8403070205

- --B403070210 Forwards revised response to NRC ltr re violations noted in IE Insp Repts 50-413/83-17 & 50-414/B3-16 Corrective actions GA Procedure GA-140, "Inspector Certification," will be revised TUCKER, H B Duke Power Co 84/01/23 0'REILLY, J P Region 2, Office of Director 2pp 22538 360 24X Fiche 50-413,84/02/24, 8403070205
- B403160253 Informs that no circuit breakers w/undervoltage trip attachments in use in safety-related application other than reactor trip sys, in response to IE Bulletin 83-00 TUCKER, H B Duke Power Co 84/02/24 D'REILLY, J P Region 2, Office of Director ip 22660 142 24X Fiche 50-413,84/02/24,8403140253
- 8403160086 Forwards IE Insp Repts 50-413/84-ii & 50-414/84-07 on 840131-0203 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/27 TUCKER, H B Duke Power Co 2pp 22655 103 24X Fiche: 50-413.84/02/27.8403160086
- --8403160092 IE Insp Rapts 50-413/84-11 & 50-414/84-07 on 840131-0203 No violations or deviations identified Major areas inspected fire protaction/prevention
 MILLER.W H Region 2. Office of Director CONLON.T E Division of Engineering & Operational Programs 84/02/21 9pp 22653 105 24X Fichs 50-413.84/02/27.8403160086
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enci JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403140123 Forwards NRC insp repts & accompanying violation notices re facility QA Encl repts & notices issued after close of Dec 1983 hearings Falmetto Alliance served w/notices & util responses. JOHNSON, G E Hearing Branch 4 84/02/29. KELLEY, JL Atomic Safety and Licensing Board Panei 28pp 22624 040 24X Fiche 50-413,84/02/29,8403140123
- B403160143 Forwards final response to IE Bulletin 79-14, Rav 1, Suppl 2 re GA program for seismic analysis of Seismic Category 1 piping sys
 TUCKER, H B Duke Power Co 84/02/29 G'REILLY, J P Region 2,
 Office of Diractor 4pp 22655 321 24X Fiche 50-413,84/02/29,
 8403160143
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.JN Division of QA. Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fichs 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E. L. Division of Emergency Preparadness & Engineering Responsa (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Raporting of Radiological Releases" Svc list encl
 JORDAN,E L. Division of Emargancy Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notica 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " 8vc list encl. JURDAN, E L Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp. 22553 336 24X Ficha 50-000.84/03/05,8402090011
- 8402090024 IE Info Notice 84-09, Rav 1. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24% Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice B4-18, "Stress Corrosion Gracking in PMR Sys " Syc list encl JORDAN,E L Division of Emergency Praparedness & Engineering Response (Post B30103) 84/03/07. Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Ficha 50-000,84/03/07.8402090028
- 8403i60293 Ack receipt of 8402i5 itr informing NRC of staps taken to correct violations noted in IE Insp Repts 50-413/83-52 & 50-414/83-39
 LENTS,R C Division of Project & Resident Programs 84/03/08
 TUCKER,H B Duke Power Co ip 22660 124 24X
 Fiche. 50-413,84/03/08,8403i60293

- --8403160299 Responds to NRC 840117 ltr re violations noted in IE Insp. Repts 50-413/83-32 & 50-414/83-39 Corrective actions QA. Procedure QA-130 revised to assure that util written qualifications for auditors in full compliance wicodes. TUCKER, H.B. Duke Power Co. 84/02/10 O'REILLY, J.P. Region 2, Qffice of Director 2pp. 22560 125 24X Fiche 50-413, 84/03/08, 8403140293
- --8403160307 Forwards IE Insp Repts 50-413/83-52 & 50-414/83-39 on 831212-16 & notice of violation LEMIS.R C Division of Project & Resident Programs 84/01/17 TUCKER.H B. Duke Power Co. 2pp 22660 127 24X Fichm 50-413.84703/08.8403160273
- --8403160314 Notice of violation from insp on 831212-16 * Region 2. Office of Director 84/01/17 1p. 22660 129 24X Fiche 50-413.84/03/08.8403140293.
- --8403160319 IE Insp Repts 50-413/83-52 & 50-414/83-39 on 831212-16 Violation noted failure to establish personnel qualifications for auditors BELISLE, 0 A , FOSTER, L , EMITH, C. Region 2, Office of Director 84/01/13 12pp 22660 130, 24X Fichs.50-413,84/03/08,8403160293
- 8402090031 IE Bulletin 84-02, "Failures of GE Type MFA Relays in Use in Class IE Safety Gys " Svc list encl DEYOUNG:R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche. 50-000.84/03/12,8402090031
- B403290270 Ack receipt of 840305 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-413/83-21 & 50-414/83-22 LEWIS.R C Division of Project & Resident Programs 84/03/15 TUCKER.H B Dute Power Co ip 22800 020 24X Fichs 50-413.84/03/15 4903290270
- --B403270276 Responds to NRC 830912 ltr re violations noted in IE Insp Repts 50-413/83-21 & 50-414/83-22 Corrective actions GC insp criteria for cable pulling revised to clarify insps of cable bending radius & unsupported length during routing. TUCKER.H B Duke Power Co 84/03/05 O'REILLY, J.P. Region 2, Office of Director 3pp 22800 021 24X Fiche 50-413,84/03/15.
- B402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into FWR Reactor Cavities." Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 820103). 84/03/21 Consolidated Edison Co of New York, Inc 123pp. 22823 229 24X Fiche 50-000,84/03/21.8402090043
- B402090044 IE Info Notice B4-20. "Byt Life of Relays in Safety-Related Bys " Syc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- 8 Reportable occurrences, LERs & related correspondence
- B403010451 Informs Commission of problems w/emargency diesel generators mfg by Transamerica Delaval, Inc pIRCKB,W J Office of the Executive Director for Operations SECY-B3-034 84/01/25 4pp 22438 347 24% Fiche 50-000,84/01/25,8403010451
- B403010140 Significant Deficiency Rept 8D 413-414/84-02 re unconsidered effects of superheated steam possibly resulting in increased iower containment temp fiesting on 840312 requested TUCKER.H B Duke Power Co 84/02/17 G'REILLY, J P Region 2, Office of Director 2pp 22435 322 24X Fiche 50-413,84/02/17,84/02/17
- B403210032 Part 21 rept re failure of auxiliary feedwater pump drive turblnes. Ośmpel NPB-4 T&T velverto close Encl 1tr dtd B40203 sent to listed utils GE notified of affected units in BHR plants THEROUX,R R Terry Corp B4/02/22 WDODRUFF,R W Director's Office. Office of Inspection and Enforcement 6pp, 22706 327 24X Fiche 50-000.84/02/22.8403210032.
- B403090226 Significant Daficiancy Rept 413-414/62-04 amending corrective actions to previously submitted rept.Reinsp of inaccassible deficient supports may be waived if documented evaluation of design analysis provided.

 TUCKER, H. B. Dute Power Co. 84/02/24 O'REILLY, J.P. Region 2, Diffice of Director 2pg 22573, 261 24X Fiche 50-413, 84/02/24, 84003019224.

1

- B403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval Inc Owners Oroup program commitments.
 Rept evaluates cracks in AF piston skirts in Shoreham & Orand Guif Nuclear Power Stations
 MUSELER, M. J. TDI (Transamerica Delavai, Inc.) Owners Oroup.
 84/02/27 DENTON. H. R. Office of Nuclear Reactor Regulation.
 Director 3pp 22434 090 24X Fichs. 50-000, B4/02/27, B403010207
- 840309024i Interim Significant Deficiency Repts 8D-413/82-27 & SD-414/82-27 re cracked cell containers Six cracked cells returned to Nife for investigation & resolution Site personnel will conduct weekly battery insp TUCKER.H B Duke Power Co 84/02/27 D'REILLY, J P Region 2, Office of Director 2pp 22572 302 24X Fiche. 50-413, 84/02/27, 840309024.
- 8402090021 Board Notification 84-039 discusses NRC 840210 & 16 mestings w/Transamerica Delayal, Inc Emergency Diesel Qenerators Duners Group Meeting scheduled on 840208 for finalization of generic program plan prior to NRC review EISENHUT, D © Division of Licensing 84/02/28 PALLADING Commissioners. 5pp 22546 009 24X Fiche: 50-000, 84/02/28, 8402070021.
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc. emergency dissel generators NUBELER, H. J. TDI (Transamerica Delaval, Inc.) Owners Group. 84/02/28 DENTON; H. R. Office of Nucleer Reactor Regulation. Director. 42pp. 22435 177 24X Fiche 50-000,84/02/28,8403010218
- 8402090020 Board Notification 84-044 forwards Part 21 rept re Transamerica Delaval, Inc. turbocharger thrust bearing iubrication defect resulting in engine nonavailability EISENHUT, D. Ø Division of Licensing 84/02/27 PALLADING Commissioners App 22341 263 24X Fiche: 50-000, 84/02/27, 840000000
- 8403140048 Forwards "Grand Guif Component Tracking Bys." "Shorehea Component Tracking Bys" % "Transamerica Delavai. Inc Dissel Generators Comers Group Program Plan." to preolve concerns w/sepsency dissel generators MUSELER.N J Long Island Lighting Co 84/03/02 DENTON. H R Office of Nuclear Reactor Regulation, Director. 2pp. 22626 062 24X Fiche 50-000,84/03/02,8403140048
- --8403140095 "Transemerica Delaval. Inc Dissel Generators Dwners Group Program Plan."

 * TDI (Transemerica Delaval. Inc.) Gwners Group 84/03/02.
 261pp 22528 223. 24X Fiche 50-000,88/03/02.8403140048.
- 8403150128 Update of Significant Deficiency Rept 414/82-25. Item should be renumbered 413-414/82-25 All necessary actions completed TUCKER, H B Duke Power Co. 84/03/02 O'REILLY, J. P. Region 2: 04/03/02 Defice of Director ip 22639 332 24X Fiche. 50-413, 84/03/02; 8403150128
- 8402090033 Board Notification 84-047, forwards Transamerica Delayel, Inc Owners Group piston skirt rept & task descriptions EISENHUT, D 0 Division of Licensing 84/03/07 PALLADIND Commissioners 4pp 22674 221 24X Ficher 50-000, 84/03/07, 6402090003
- 8403140122 Part 21 rapt re status update concerning abnormel wear on ilnear converters. Text program underway Results of investigation indicate excessive wear caused by hunting of control circuitry.

 BUDSON, J.P. Pacific Air Products Co. 84/03/09 Director's Office, Office of Inspection and Enforcement. 7pp 22624; 068. 24% Fiche: 50-000, 84/03/09, 8403140122.
- B402090038 Board Notification 84-051.forwards "Transamerica Delayal, Inc (TDI) Diesel Cenerators Owners Group Program Flam " EISENHUTD, Q Division of Licensing 84/03/12, PALLADINO Commissioners 5pp 22688.214 24X Fiche.50-000,84/03/12,
- B402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delavai, Inc. (TDI) Duners Group, Distribution list enci.
 EISENHUT, D. G. Division of Licensing 84/03/12 PALLADING Commissioners, 5pp. 22708,001. 24X Fiche 50-000,84/03/12, 240090009
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Guners Group in Bethesda.HD re problems w/emergency
 dissel generators.
 CARUSO.R Licensing Branch 2 84/02/27. O'REILLY, J. P. NAC No
 Detailed Affiliation Oiven. App 22708:006. 24X
 Fiche: 50-000, 84/03/12, 8402070039.

- --B403060554 Transcript of B40210 meeting w/Transamerics Delaval, Inc duners Group in Bethasda. MD re problems w/emergency diesel generators • NRC - No Detailed Affiliation Given B4/02/10 147pp 67201 008 24X Fiche 50-000,84/03/12,8402070039
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl
 HILLER: M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24% Fiche 50-000,84/03/12,8402090039
- --8403070423 Yranscript of 840216 conference in Wading River.NY re Transamerica Deieval. Inc diesel generators Pp 1-82 * Commissioners 84/02/16. 84pp R2708 169 24X Fichs. 50-000.84/03/12.8402070039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Sheils for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators
 MUSELER, W.J. Long Island Lighting Co. 84/03/12 DENTON, H.R.
 Defice of Nuclear Reactor Regulation, Director 2pp 22632 074
 24X Fiche 50-000,84/03/12,8403140050
- 8403150133 Forwards "Transamerica Deiaval, Inc Diesel Generator Rocker Arm Capscraw Stress Analysis Rept " Capscraw design adequate for applicable engines & svc conditions MURELER, W J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22639, 270 24X Fichs. 50-000, 84/03/13, 8403150133
- 8403290244 Final Bignificant Deficiency Rept 8D 413-414/83-14 re seal conduit connection to safety-related equipment located in harsh anvirons. Initially reported on 831102 Util continuing to evaluate alternative sealing methods
 TUCKER.H B Duke Power Co 84/03/15 O'REILLY, J P Region 2, Office of Director 3pp 22800.224 24X Fiche 50-413,84/03/15.
- B403200222 Rasponds to 840214 Requests for Info 1 & 2 re R-4 series engines.List indicating engine number model & svc number customer name & address rating, date shipped & date started encl.

 MATHEME, C S. Transamerica Delaval. Inc 84/03/16 EISENHUT, D 0 Division of Licensing 20pp. 22691.179 24X Fiche.50-000,84/03/16.8403200222.
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis." prepared by S&W for Transamerica Delaval.Inc (TDI) Diesel Generator Owners Group HUSELER, W. J. TDI (Transamerica Delaval, Inc.) Owners Group 84/03/23. DENTON.H R. Office of Nuclear Reactor Regulation, Director. 2pp 22774.001 24X Fiche 50-000,84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica
 Delaval diesel generators List of suggested meeting topics
 encl.
 MCGAUGHY, J.P. TDI (Transamerica Delaval, Inc.) Dunars Group.
 84/03/23. DENTON: H R Office of Nuclear Reactor Regulation,
 Director. 4pp 22769-133, 24X Fiche 50-000.84/03/23,8403270134

T. Hearing transcripts on non-antitrust matters

- 8402070037 Board Notification 84-052 forwards masting summaries containing transcripts of 840210 % 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Owners Group Distribution list encl EISENHUT, D Q. Division of Licensing. 84/03/12 PALLADIND Commissioners. 5pp. 22708:001. 24X Fiche 50-000,84/03/12,8402070037
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval. Inc Owners Group in Bethesda, MD re problems w/emergency dissel generators CARUSO, R. Licensing Branch 2 84/02/27 O'REILLY, J. P. NRC No Detailed Affiliation Given. App 22708 006, 24X Fiche. 50-000, 84/03/12, 8402090039
- --B403060554 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Oroup in Bethesda, MD re problems w/emergency diesel generators. * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201:008, 24% Fiche, 50-000, 84/03/12, 8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Ordup in Hading River, NY re program plan to establish reliability of diesel generators. Agenda, meeting transcript & attendance list encl.
 HILLER: M.A. Licensing Branch 4, 84/02/27, Licensing Branch 4, 8pp. 22708;161 24X Fiche: 50-000;84/03/12,8402090039

- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval.Inc diesel generators Pp 1-82 - Commissioners 84/02/16 E4pp 22708 169 24X Fiche 50-000.84/03/12.8402090039
- 8403160236 Transcript of 840314 twlcon re facility Pp 12.580-12.624 * Atomic Safety and Licensing Soard Panel 84/03/14 45pp 22660 208 24X Fichs 50-413.64/03/14.8403160236
- 8403260251 Transcript of 840321 telephone conference in Bethesda, MD Pp 1-24

 * Atomic Safety and Licensing Board Panel 84/03/21 28pp 22754 283 24X Fiche 50-413, 84/03/21, 8403260251
- DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

 E NRC Bafety Evaluation Report (SER), supple & correspondence
- 840308D179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000, 84/02/13, 8403080177
- --8005130773 Provides status of SER inputs & acceptance reviews for OL & CP applications Schedule should be met BURKE.W C Effluent Treatment Systems Branch 80/02/06 KREGER.W E Assistant Director for Site Analysis ip 22583 235 24% Fiche 50-000.84/02/13.8403080179
- 8403210140 Forwards confirmation of Lonergan safety relief velve qualification & operability testing of reclassified valves, per util 82100 & 18 Ifre & 88ER 4

 BALE:-L F Mississippi Power & Light Co 84/03/13 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 4pp 22707 276
 24X Fiche 50-416,84/03/13,8403210140
- F Security, medical, emergency & fire protection plans
- 8403210115 Forwards SALP Repts 50-416/83-55 & 50-417/83-09 for Sept 1982 - Sept 1983 LEWIS:R C Division of Project & Resident Programs 84/01/11 RICHARD.J B Massissippi Power & Light Co 2pp 22707 144 24X Fiche: 50-416, 84/01/11, 8403210115
- --8403210122 BALP Repts 50-416/63-55 & 50-417/83-09 for Sept 1982 Sept 1983 + Region 2, Office of Director 84/01/11 32pp 22707 146 24X Fiche 50-416,84/01/11,8403210115
- 8403160281 Notifies of 840316 workshop to discuss 10CFR30.App R requirements & insp results to resolve misunderstandings refire protection Attendees should be limited to six due to size of conference roam LEWIS.R C Division of Project & Resident Programs 84/03/02 RICHARD.J B Mississippi Power & Light Co 1p 22660 350 24X Fiche: 50-416.84/03/02.8403160281.
- 8403160336 Discusses util 840224 ltr re 1984 emergency exercise
 Exercise objectives reviewed & comments provided to
 P Benedict, corporate emergency preparedness coordinator
 VERRELLI.D M Division of Project & Resident Programs 84/03/05
 RICHARD, J B Mississippi Power & Light Co 1p 22660:031 24X
 Piches 30-416, 84/03/05, 8403160336
- B403150052 Forwards State of LA B31227 request for exemption from full participation at 840410 annual radiological emergency preparedness exercise.FEMA supports exemption based on State of LA full participation in Waterford exercise KRIMM.R W. Federal Emergency Management Agency 84/03/09 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 3pp. 22641 355 24X Fiche 50-416.84/03/09.8403150052

O Adjudicatory correspondence

- 8403050102 Order allowing NRC & applicant until 840319 to respond to petitioner renumbered Contentions 1.2 & 3 & allowing petitioner 10 days after svc for response ORDBSMAN.H Atomic Safety and Licensing Board Panel 84/03/02 2pp. 22517.019 24X Fiche 80-415.84/03/02.8403060102
- 8403190219 Forwards emergancy planning contentions as modified & forwarded to ABLP ODDDARD.R.J Hearing Branch 3 84/03/16 SNELL.W Region 3, Office of Director ip 22674:199 24X Fiche 50-416,84/03/16,8403190219

- --8403190220 Summarizes 840228-29 meetings u/util.Prairie Alliance & FEMA in Champaign. IL re mod & deletion of portions of Contention i on emergency planning Proposed mods encl Submits schedule for parties to further settle issues GODDARD.R J Hearing Branch 3 84/03/05 CLARK,H K . PARIS,D H . FERGUSON.G A Atomic Safety and Licensing Board Panel 5pp 22674 200 24X Fiche 50-416,84/03/16.8403190219
- 8403200018 Response to first order following preheating conference modifying briefing schedule ASLB should deny admission of Paragraphs 6.7 & B as well as Contentions 1.2 & 3 & dismiss proceeding Certificate of Svc enc!

 CONNER.T B Hississippi Power & Light Co CONNER.T B Conner & Wetterhahn 84/03/16 Atomic Safety and Licensing Board Panel 22pp 22697 001 24X Fiche 50-416.84/03/16.8403200018
- 8403210165 Response to Jacksonians United for Livable Energy Policies renumbered Contentions 1.2 & 3 Admission of renumbered contentions acceptable Certificate of Svc enci MANNER.H E Hearing Branch 4 DSB 016 84/03/19 Atomic Safety and Licensing Board Panel 7pp 22718 217 24X Fiche 50-416.84/03/19.8403210165
- 8403270318 Forwards staff 830319 response to petitioner renumbered Contentions 1.2 & 3.per request W/o encl WAGNER.M E Hearing Branch 4 DSB 131 84/03/22 STEWART.C Affiliation Not Assigned 1p 22789 028 24% Fiche 50-416, 84/03/22.8403270318

H General correspondence

- 8403270211 Expresses concern on safety of facility NRC should not allow operation before plant meets sefety criteria WIENER, J. Affiliation Not Assigned 84/03/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22772 144 24X Fiche 50-416,84/03/22,8403270211
- J Insurance & indemnity Information
- 8403140121 Forwards Endorsement 29 to NELIA Policy NF-257 & Endorsement 11 to MAELU Policy MF-106
 DALE: L F Mississipp: Power & Light Co 84/03/02 KERR, G W Office of State Programs. Director 4pp 22620 284 24X Fiche 50-416.84/03/02.8403140121
- P Operating license stage documents & correspondence
- 8403070325 Forwards Info re shift advisors including job description MCGAUCHY, J.P. Hississippi Power & Light Co. 84/02/20. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. Opp. 22546 198 24X Fiche 30-416,84/02/20,8403070325
- 8403010136 Forwards Amend 12 to License NPF-13 & safety evaluation Amend corrects administrative & technical deficiencies in Tech Speck re low-low set function source range monitors & Div 2 batteries
 SCHMENCER,A Licensing Branch 2 84/02/21 KCGAUGHY, J.P. Mississippi Power & Light Co. 4pp. 22479 257 24X
 Fiche 30-416.84/02/21.8403010136
- --8403010143 Amené 12 to License NPF-13, correcting administrative & tachnical deficiencies in Tech Specs re low-low set function, source range monitors & Div 2 batteries SCHMENCER, A Operating Reactors Branch 2 84/02/21 12pp 22479 261 24X Fiche 50-416,84/02/21,8403010136
- ~~8403010147 Safety evaluation supporting Amend 12 to License NPF-i3 » NRC - No Detailed Affiliation Given 84/02/21 App 22479 273 24X Fiche 50-416,84/02/21,8403010136
- B403280009 Forwards new problem sheets, problem sheets w/supporting documents & uncontrolled Tech Specs w/punchlist numbers on tops of pages where inconsistencies identified BTARLING.J Mississippi Power & Light Co 84/02/21 KINTNER, L NRC No Detailed Affiliation Civen 1,453pp 22782 349 24X Fiche 50-416,84/02/21,8403280009
- --8403280014 Proposed Tech Specs w/inconsistencies identified * Hississippi Power & Light Co 84/02/21 573pp 22785 053 24X Fiche 50-416,84/02/21,8403280009
- --B40328001B Rev O to "Offsite Dose Calculation Manual"
 MCKAY, L R Mississippi Power & Light Co 82/08/3i 35pp
 22786 268 24X Fiche 50-416,84/02/21,8403280009
- ---8403280025 Rev 1 to "Offsite Dose Calculation Manual "
 SMITH, Q D , MCKAY, L R Mississippi Power & Light Co 83/07/31
 33pp 22786 327 24X Ficha 50-416,84/02/21.8403280009

- 8403070394 Requests review of amended Tech Specs & certification that Tech Spacs reflect plant FSAR & SER analyses, within 10 days of ltr receipt EIBENHUT, D O Division of Licensing 84/02/24 RICHARD, J B Mississippi Power & Light Co 2pp 22564 132 24X Fiche 50-416,84/02/24,8403070354
- 8403080367 Responds to FDIA request for documents re BWR Integranular Stress Corrosion Cracking Owners Group meeting on or about 81028 Forwards App A documents Records also In PDR. FELTON.J M Division of Rules and Records 84/02/28 HAFNER.D 8uffolk Nuclear Study Group 2pp 22583 008 24X Fiche 50-000.84/02/28.8403080367
- ---8309210434 Requests evaluation of Grand Gulf & Shoreham 830817 & 23 responses, respectively re intergranular stress corrosion cracking in BHR piping. Response requested by 830916 W/o sacl
 EISENHUT, D Q Division of Licensing 83/09/06, VOLLMER, R
 Division of Engineering 1p 22383:010 24X
 Fiche 50-000,84/02/28,8403080367
- 8403050236 Forwards detailed breakdown of approx 200 Tech Bpec changes requested by licensee & categorized in Dircks 840202 memo DIRCKS.H J Office of the Executive Director for Operations, 84/02/29 PALADINO, OILINSKY, ROBERTS Commissioners 34pp. 22527 215 24X Fichs 50-416,84/02/29,8403050236
- 8403230273 Notification of 840307 meeting w/util in Bethesda, MD to revisw program for Tech Bpecs.
 HOUSTON:M D Licensing Branch 2 84/03/05 8CHWENCER, A. Licensing Branch 2. 3pp 22759 RB2 24X Fiche:50-416,84/03/05,8403230273
- 8403300251 Summary of 840221 meeting w/util in Bathesda. MD re datalls of util proposed onsite/offsite electrical power raliability program for Transamerica Delaval. Inc diesel generators Attendance list & viewgraphs encl.

 HOUSTON. M D Licensing Branch 2 84/03/06. Licensing Branch 2 21pp 22845 001 24X Fiche 50-416.84/03/06.8403300251
- 8403090215 Forwards results of enalysis performed showing relationship between ECCS reliability & Agastat relay test intervals. Analysis withheld (ref 10CFR2, 790).

 DALELL F Missispip Fower & Light Co 84/03/07 DENTON, H. R. Office of Nuclear Reactor Regulation. Director. App. 22372:286. 24X Fiche 30-416,84/03/07,8403090215
- 8403120037 Forwards requested Info re experience levels of util operating shift personnel & expresses support of position taken by Industry Working Oroup on Operating Shift experience on 840224

 DALE/L F Mississippi Power & Light Co 84/03/08. DENTON, H R Office of Nuclear Reactor Regulation. Director 13pp 22590-304. 24X Fiche 50-446.84/03/08.8403120037
- 8403210109 Submits interim response to 840224 ltr requesting certification re Tech Specs & FSAR Review & certification program in progress Meeting scheduled for 840309 to discuss program scope.review criteria & schedule DALE, F Mississippi Power & Light Co 84/03/08 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 22704-360, 24X Fiche 50-416,84/03/08,8403210109
- 8403210053 Endorses 8H Hobbs Feb 1984 Ltr HON-013 to HR Denton in response to NRC 831208 request for add1 Info re Hydrogen Control Owners Ordup (HCOO) test program Guestions to be enswered by HCOO & util.respectively.listed DALE.L F Mississippi Power & Light Co. 84/03/09 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 2pp 22704:344 24X Fiche 50-416,84/03/09,8403210053
- 8403150275 Ceneric Ltr 84-07 to all licensaes of BWRs re procedural guidance for pipe replacement at BWRs 8vc list encl EISENHUT,D 0 Division of Licensing, 84/03/14, Commonwealth Edison Co 20pp 22823 354 24% Fiche, 50-000, 84/03/14, 8403150275.
- 8403270074 Forwards updated info on operating shift experience to supersede previous submittal, including chart of experience levels of five proposed operating shifts DALE, L. F. Mississippi Power & Light Co. 84/03/16. DENTON, H. R. Office of Nuclear Reactor Regulation, Director Spp 22806:341, 24X Fiche 50-416,84/03/16,8403270074
- 8403210057 Forwards description of Tach Spec review program, per 840224 request Program estimated to end on 840406 Formal response sipected by 840409 Mississippi Power & Light Go 84/03/18 DENTON, H R. Dffice of Nuclear Resector Regulation, Director 2pp 22705:021 24X Fiche 50-416, 84/03/18, 8403210057
- --8403210062 "Tech Spec Review Program Description "
 * Mississippi Power & Light Co 84/03/31, 20pp 22705:023 24X
 Fiche 50-416,84/03/18,8403210057

- 8403300305 Notification of 840322.28,0404 & 11 meetings w/util in Betherda, MD to review program for processing Tech Spec change requests KINTMER, L L Licensing Branch 1 84/03/19 ADENSAM, E 0 Licensing Branch 4 3pp 22844
- 8403230084 Forwards application for amend to License NPF-13, changing Tech Specs re automatic depressurization sys valve operability requirements to achieve consistency between Tach Specs & design & accident analyses MCQAUGHY. J P Mississippi Power & Light Co 84/03/20 DENTON. H R GFFice of Nuclear Reactor Regulation. Director 2pp 22726 299 24X Fiche 50-416,84/03/20,8403230084
- --8403230089 Application for amend to License NPF-13, changing Tech Specs re automatic depressurization sys valva operability requirements to achieve consistency between Tech Specs & design & accident analysis MCGAUCHY, J. P. Mississippi Power & Light Co. 84/03/20 ip 22726-301 24X Fiche. 50-416, 84/03/20, 8403230084
- --B403230092 Proposed Tech Specs changing automatic depressurization systalve operability requirements & min operable channels per trip systo one for standby liquid control systinitiation reactor water cleanup isolation function

 Hississippi Power & Light Co B4/03/20 11pp 22726 302 24X Fiche 30-416,84/03/20,8403230084
- 8403300097 Transmits fee for proposed amend to License NPF-13, DALE/L F. Mississippi Power & Light Co 84/03/27 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp. 22821 212 24X Fiche: 50-416, 84/03/27, 8403300097
- 8403260335 "Orand Gulf Nuclear Power Plant Audit of Nuclear Flant Tech Specs." FEHRINGER, J M., RDCKHOLD, H. C., COOK, T. L. EQ&Q, Inc. FIN A-6816 EQQ-EA-6542. 84/03/31 DDNOHEN, J H., MEYER, Q C Division of Licensing. 18pp 22775: 263, 24X Ficha 50~416,84/03/31,8403260335
- G. Inspection reports, IE Bulletins & correspondence
- 8403070057 Forwards rept describing generic problems discovered during surveillance program review effort & corrective actions implemented to correct surveillance deficiencies.per 1E Insp Rept 50-416/82-67

 DALE/L.F. Mississippi Power & Light Co. 83/12/01. D'REILLY, J. P Region 2, Office of Director 27pp 22547 34B 24X
 Fishe 90-416,83/12/01.8403070057
- 8403070268 Responds to questions raised during special safety insp on 830322-25 re IE Bulletin 80-ii that three morter cube compression tests did not meet min compressive strength requirements. Structural integrity unimpaired DALE-L.F. Mississippi Power & Light Co 83/12/30 O'REILLY, J P Region 2, Office of Director. 6pp 22546 086. 24X Fiche: 50-416, 83/12/30, 8403070268
- 8403210115 Forwards SALP Repts 50-416/83-55 & 50-417/83-09 for Bept 1982 ~ Sept 1983, LEMIS.R.C Division of Project & Resident Programs 84/01/11, RICHARD, J B Mississippl Power & Light Co. 2pp. 22707 144 24X Fiche, 50-416, 84/01/11, 8403210115
- --8403210122 BALP Repts 50-416/83-55 & 50-417/83-09 for Sept 1982 Sept 1983, * Region 2. Defice of Director. 84/01/11. 32pp 22707-146. 24X Fiche 50-416,84/01/11.8403210115.
- 8403070247 Forwards IE Insp Rept 50-416/84-03 on 840116-19 No violations or deviations identified VERRELLI, D.M. Division of Project & Resident Programs 84/02/07 RICHARD, J. B. Mississippi Power & Light Co 2pp. 22536 081, 24X Fiche: 50-416, 84/02/07, 8403070247.
- --B403070248 IE Insp Rept 50-416/84-03 on 840116-19, No violations or deviations identified, Major areas inspected, radioactive gaseous & liquid effluents, raduaste organization, mods. procedures, audits & solidification KAHLE, J. B. Region 2, Office of Director BARR, K.P. Division of Engineering & Operational Programs. 84/02/02 6pp 22536:083 24% Fiche:50-416:84/02/09,8403070247.
- B403160100 Forwards IE Insp Rept 50-416/84-04 on 840130-0202 No violations or deviations identified.

 VERRELLI, D. M. Division of Project & Resident Programs 84/02/15 RICHARD.J. B. Mississippi Power & Light Co. 2pp 22652-334, 24: Fiche: 50-416, 84/02/15, 8403160100

- --8403160108 IE Insp Rept 50-416/84-04 on 840130-0202 No violations or deviations identified Major areas inspected review of startup test procedures review of completed startup tests & closeout of outstanding Items
 BURNETT,P T Region 2. Office of Director JAPE,F Division of Engineering & Operational Programs 84/02/10 3pp 22652 336 24X Fiche 30-416.84/02/15.8403160100
- B403070168 Ack receipt of B40213 ltr informing NRC of steps taken to correct violations & deviations noted in iE Insp Rept 50-416/89-50
 VERRELLI,D M Division of Project & Resident Programs B4/02/22 RICHARD, J B Mississippi Power & Light Co 1p 22536 193 24X Fiche 50-416,84/02/22.8403070168
- --8403070173 Responds to NRC 840112 ltr re violations & deviations noted in IE Insp Rept 50-416/83-50 Corrective actions training superintendent given written reprimans & importance of attention to dstail stressed DALE; F Mississippi Power & Light Co 84/02/13 O'REILLY, J P Region 2. Office of Director 3pp 22536 174 24X Fiche 50-416,84/02/22;8403070168
- --B403070176 Responds to NRC B31115 ltr re violations noted in IE Insp Rept 50-416/B3-50 Requests compliance due date be extanded until B40120 DALE, L.F. Mississippi Power & Light Co. B4/01/13 G'REILLY, J.P. Region 2, Office of Director ip 22536 197 24X Fiche 50-416,84/02/22,8403070169
- --B403070180 Responds to NRC B31115 ltr re violations noted in IE Insp Rept 50-416/B3-50 Corrective actions change to Tach Specs prepared balancing degree of detail portraged in table DALE, L F Hississippi Power & Light Co B3/12/15 O'REILLY, J P Region 2, Office of Director 2pp 22536 198 24X Fichs 50-416,84/02/22,8403070168
- ---8403070186 Ack receipt of 831213 & 21 ltrs informing NRC of steps taken to correct violations & deviations noted in 1E imap Rept 50-416/83-50 Specific programmatic controls to be implemented should be provided VERRELLI.D M Division of Project & Resident Programs 84/01/12 RICHARD, J B. Mississippi Power & Light Co 2pp 22536 200 24X Fiche 50-416,84/02/22,8403070168
- --8403070189 Responds to NRC 831115 itr re deviation noted in IE Insp Rept 50-416/83-50 Corrective actions add 15 design changes being reviewed to determine if training required DALE,L.F Mississippi Power & Light Co 83/12/21 D'REILLY,J P Region 2, Office of Director 2pp 22536 202 24X Fiche: 50-416,84/02/22,8403070168
- --8403070206 Forwards IE Insp Rept 50-416/83-50 on 830926-1014 & notices of violation & deviation VERRELLI, D M Division of Project & Resident Programs 83/11/15 RICHARD, J B Mississippi Power & Light Co 2pp 22536 206 24X Fiche: 50-416,84/02/22,8403070168
- --8403070208 Natice of violation from insp on 830926-1014. * Region 2, Office of Director. 83/11/15 ip 22536 208 24X Fiche 30-416,84/02/22,8403070168
- --8403070209 Notice of deviation from insp on 830926-1014 * Region 2, Office of Director 83/11/15 1p 22536 209 24X Fiche 50-416,84/02/22,8403070168
- --84030702i6 IE insp Rept 50-416/83-50 on 830926-1014 Violation noted failure to meet Tech Bpec organization chart. Deviation noted failure to provide operator training on design changes to plant

 HAONER: A O Region 2, Office of Director JULIAN.C A. Division of Project & Resident Programs 83/ii/13 7pp 22536 210 24X Fiche 50-416,84/02/22,8403070168
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list and JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22909 239 24X Fiche. 50-000.84/02/28.8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl ORACE, J N Division of GA, Bareguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552,329 24X Fiche 50-000,84/03/02,8402090007
- 840209000B IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate" Svc list encl. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp. 22553.098 24X Fiche 50-000,84/03/02,8402090008

- 8402090009 IE Info Notice 84 15, "Reporting of Radiological Releases "
 - Svc list encl Division of Emergency Preparedness & Engineering AURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Cansulidated Edison Ca of New York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402070007
- 8403120034 Staff requirements memo re 840229 briefing in Washington.DC re SALP review of areas prior to issuance of full-power recommendation & document interpreting LER rept CHILK, S J Office of the Secretary of the Commission 84/03/02 DIRCKS.W J Office of the Executive Director for Operations ip 22617 346 24x Fiche 50-416.84/03/02.8403120034
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24% Fiche 50-000,84/03/05,8402070011
- 8403290151 Forwards IE Insp Rept 30-416/84-02 on 840116-20 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/03/05. RICHARD.J B hississippl Power & Light Co 2pp 22806 001 24X Fich
- --8403270156 1E Insp Rept 50-416/84-02 on 840116-20 No violetions or deviations noted Major areas inspected electrical preventive & corrective maint activities maint records & training of maint personnel
 OIBBONS.T D Region 2. Office of Director CONLON.T E Division
 of Engineering & Operational Programs 84/02/22 3pp 22804 003
 24X Fiche 30-416.84/03/05,8403290151
- 8402090024 IE Info Notice 84-09.Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84703/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-19, "Stress Corrosion Cracking in PWR 10209002B IE Info MOTICE OF
 Sys "Svc list enci
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/03/07 Cansolidated Edison Co of New
 York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 840209003i IE Bulietin 84-02, "Failures of GE Type HFA Ralays in Use in Class IE Safety Sys " Svc list enci
 DEYOUNO.R C Director's Office, Office of Inspection and
 Enforcement 84/03/12 Consolidated Edison Co of New York, Inc
 i34pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- 8403290030 Provides interim response to IE Bulletin 83-07, "Apparently 403270030 Provides interim response to IR Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller.lnc " Results of investigation to date indicate no Ray Miller products supplied to facilities Final response expected by B40325 MCGAUGHY.J P Mississippi Power & Light Co 84/03/13 O'REILLY.J P Region 2. Office of Director 3pp 22806 224 24x Fichs 50-416.84/03/13,8403270030
- 8403290306 Requests addl delay in submittal of inservice insp program until 840801 Justification provided DALE.L F Mississipp: Power & Light Co 84/03/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22802 172 24X Fiche 50-416.84/03/16.8403290306
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 80103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Ficha 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Svc list enci JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/21 Consolidated Edison Co of New
 York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403020047 Monthly operating rept for Jan 1984 H/840215 ltr CESARE, J G . DALE, L. F Mississippi Power & Light Co 84/01/3i DEYOUNO.R C Director's Office, Office of Inspection and Enforcement 12pp. 22441 175 24X Fiche 50-416,84/01/31, 8403020047
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS; W J Office of the Executive Director for Operations
 84/02/21 PALLADINO Commissioners 9pp 22492 083 24X
 Fiche 50-000,84/02/21,8403020443

- 8403220147 Monthly operating rept for Feb 1984 W/840315 1tr CEBARE.J O. DALE.L F. Mississippi Power & Light Co. 84/02/29 DEYOUNG.R C. Director's Office. Defice of Inspection and Enforcement 4pp 22716 051 24X Fiche 50-416,84/02/29,8403220147
- 8 Reportable occurrences, LERs & related correspondence
- 8403230148 Forwards Technical Review Rept AEOD/T332, "Reactor Vessel Drainage SALAH, S SALAH.S Reactor Operations Analysis Branch 83/10/07 SEYFRIT, K V Reactor Operations Analysis Branch 1p 22743 358. 24X Fiche 50-416,83/10/07,8403230148.
- --8403230150 "Reactor Vessel Drainage," technical review rept. No further evaluation necessary 8ALAH B Director's Office 83/10/07, 3pp 22743:357 24X Fiche 50-416,83/10/07,8403230148
- 84030i0451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Deiaval Inc DIRCKS,W J Office of the Executive Director for Operations, BECY-83-034 84/01/25 App 22438 347 24X Fiche 50-000,84/01/25,
- 8403010121 Updated LER 83-181/03X-1. on 831110; channel C as-found eduction to proceed Lex 83-181/00A-1.on addition channel a servoing setpoints for undervoitege trip were 116 2-Volt ac Cause unknown Voltage adjusted within desired range.W/840221 ltr PARKER.J. DALE.L F. Mississippi Power & Light Co. 84/02/21 O'REILLY,J P. Region 2, Office of Director, 3pp. 22436:035. 24X Fiche 50-416.84/02/21,8403010121
- 8403020406 Advises that draft "Final Rept on Div I & II Transamerica Delaval, Inc Diesel Generators," forwarded to NRC on 840216 will be submitted in final form on 840221, HOUSTON M D Licensing Branch 2 84/02/21. Licensing Branch 2 3pp 22472 104 24X Fiche 50-416,84/02/21,8403020406
- --8403020410 Draft "Final Rspt on Div I & II Transamerica Delaval, Inc Dissel Generators " * Mississippi Power & Light Co 84/02/15 74pp, 22472.107, 24X Fiche 50-416, 84/02/21, 8403020406
- 8403060453 Discusses deficiencies discovered in Delaval emergency diesel generators Written submittal requested giving details of anhancement program to justify interim operation EISENHUT.D 9 Division of Licensing 84/02/24. RICHARD, J 8, Mississippi Power & Light Co 4pp 22550,003. 24X Fiche 50-416,84/02/24.8403060453.
- 8403080011 Forwards response to Commissioner Gilinsky request for info on frsquency of parsonnel errors at selected operating plants. Summary of tabulated events ra operator errors, personnel errors or procedural errors provided for CYB3 DIRCKS: M J Office of the Executive Director for Operations. 84/02/24 PALLADINO Commissioners 17pp 22584, 142. 24X Fiche 50-000,84/02/24,8403080011.
- 8403090091 LER 84-006-00 on 840120, during drywell high pressure channel A functional test indicator light failed to illuminate Caused by failure of test procedure to properly instruct technicians Procedure being revised, W/840224 ltr. 8YRD.R. W. DALE.L. F. Mississippi Power & Light Co. 84/02/24 22876.035 24X Fiche 50-416.84/02/24,8403090091. 84/02/24 3pp
- 8403090192 Final RD 84-006/0 on 840118, Fire Doors 1A312, 0C414, 0C103 & #USDYUTZ FINAL KU 64-000/O ON GROULD, FITE MOOTS INSIZE UNTER
 1A314 taken out of syc for maint Causad by damage as result
 of heavy use Fire watches established until doors restored,
 DALE, LF Mississippi Power & Light Co 84/02/24 O'REIL
 Region 2. Office of Director. 2pp 22573 307. 24X
 Fiche. 50-416. 84/02/24, 8403090172 /24 O'REILLY, J, P 24X
- 8403010207 Farwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval, Inc Owners Group program commitments. Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations.

 MUSELER, H.J. TDI (Transamerica Delaval, Inc.) Owners Group, MUSELER, H.J. Long Island Lighting Co. 84/02/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 3pp. 22434-090, 24X Fiche: 50-000, 84/02/27, 8403010207
- --8403010446 "Investigation of Types AF & AE Piston Skirts."

 * Failurs Analysis Associates FAAA-84-2-14. 84/02/27. 83pp.
 22434 093. 24X Fiche 50-000.84/02/27.8403010207
- 8403140203 Forwards "Operating History Overview for Diesel Generators in Nuclear Syc," comparing Transamerica Delaval, Inc generators w/generators mfg by other vendors HEBDON, F.J. Program Technology Branch. 84/02/27. BERLINGER, C. H. NRC No Detailed Affiliation Given. 1p 22638:319, 24% Fiche 50-000,84/02/27,8403140203.

- --8403140205 "Operating History Overview for Diesel Generators in Nuclear Bvc " Byc " By Color By Color
- 8403010218 Forwards task descriptions for 16 known problems re Transemerica Delaval. Inc emergency diesal generators MUSELER, W J TDI (Transamerica Delaval. Inc.) Gwners Group MUSELER, W J Long Island Lighting Co. 84/02/28 DENTON, H F Office of Nuclear Reactor Regulation, Director 42pp 2243: 24X Fiche 50-000, 84/02/28, 8403010218 22435 177
- 8403240233 Forwards summary list of deficiencies identified per 10CFR50 55(e), Part 21 & potential generic 1tr repts for BTARCSTECKI, R Division of Project & Resident Programs Region 1, Diffice of Director 7pp 22756 065 24X Fiche 50-000,84/02/28,8403260233 84/02/28
- 8402070020 Board Notification 84-044 forwards Part 21 rept re Transamerica Delaval, Inc turbocharger thrust bearing Iubrication defect resulting in engine nonavailability EIBENHUY, D. Division of Licensing 84/02/27 PALLADINO, 01LINSKY, ROBERTS Commissioners 4pp 22541 263 24X Fiche 50-000,84/02/27,8402090020 PALLADINO,
- B403090265 Finel Deficiency Rept PRD B3/08 re inability to maintain pressurized water supply to RHR pumps & discharge piping supplied by Bechtel Initially reported on B30415 Hardwars mods implemented Aiso reportable per Pert 21 MCQAUOHY, J.P. Hississippi Power & Light Co 84/03/02 0'REILLY, J.P. Region 2, Office of Director 4pp 22572 i44 24 Fiche.50-416,84/03/02,8403090265. 22572 144 24X
- 8403120148 LER 84-007-00 on 840128, discovered Heion sys control panel for computer & control panel room w/missing fuses Cause unknown Fuses replaced W/840302 itr PARKER, J. DALE, L.F. Hississippi Power & Light Co 84/03/02 3pp 22585:257 24X Fiche: 50-416,84/03/02,8403120148
- 8403120159 Special Rept B4-007/O on B40131 & 0210, bolts securing Div i standby diesel generator left bank turbocharger failed during 100 h test runs No noticeable effect on engine performance noted LER B3-107 will be updated DALE, L F Mississippi Power & Light Co. 84/03/02 0'REILLY, J P Region 2, Office of Director 2pp 22586'253 24X Fiche. 50-416, 84/03/02, 8403120159
- 8403130075 Updated RD 83-088/i on 830704, control room temp reached 80 F.exceeding limit of 77 F No immediate disquelification of affected equipment occurred Worst case effect is reduction of equipment qualified life, DALE, L F Mississippi Power & Light Co 84/03/02 O'REILLY, J P Region 2, Office of Director 2pp 22599.001, 24X Fiche 50-416,84/03/02,8403130075
- 8403130192 Updated LER 83-185/03X-1 on 831201, while in cold shutdown, breaker 552-2103 tripped, causing loss of power to Div 1 EBF bus & all baiance of plant loads Caused by two shorted wires in breaker hand switch Mires altered M/840302 ltr BYRD.R., DALE,L.F Mississippi Fower & Light Co 84/03/02 0 7KEILLY.J P Region 2. Office of Director, 3pp 22617.275 24X Fiche.50-416,84/03/02,8403130192.
- B403130274 Updated LER B3-154/03X-i:on B31003.capscrew securing starting air manifold to support piate on left bank cylinder B found broken inside plate Cause undetermined Capscrew replaced W/B40302 ltr.
 BYRD.R., DALE,L.F., Mississippi Power & Light Co B4/03/02 0'AEILLY,J.P. Region 2, Office of Director 3pp. 22617:130 24X Fiche 50-416.84/03/02.8403130274,
- 8403140048 Forwards "Grand Guif Component Tracking Bys," "Shoreham Component Tracking Bys" & "Trantamerica Delaval, Inc Diesel Generators Guners Group Program Plan." to resolve concerns w/emergency diesel generators MUSELER, W J. Long Island Lighting Co 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22626 062 24X Fiche: 50-000, 84/03/02, 8403140048
- --B403140080 "Grand Gulf Component Tracking Bys "
 # Long Island Lighting Co. 84/02/29 879pp
 Fiche. 50-000, 84/03/02, 8403140048. 22626.064. 24X
- --- 8403140095 "Transamerica Delaval, Inc Dissel Generators Duners Group Program Plan. *

 * TDI (Transamerica Delaval, Inc.) Gwners Group 84/03, 261pp 22628; 223, 24% Fiche: 50-000, 84/03/02, 8403140048

- 8403130248 RO 84-008/0 on 840124, fire barriers located in U720 control room floor modules LA59-L01 & LA59-L04 opened to implement design change package Fire watch established Work task will be completed by 940416
 DALE.L F Mississippi Power & Light Co 84/03/05 O'REILLY.J P Region 2. Office of Director 2pp 22617 297 24X
 Fishe 50-416.8403/03/08.8403 Fiche 50-416,84/03/05,8403130248
- 8403130253 Special Rept 84-009/0 on 840121, smoke detector in Zone 2-4 covered for planned maint activities Caused by weiding in piping room Fire watch established Zone reset & restored to operability on 840206
 DALE, L.F. Mississippi Power & Light Co. 84/03/05 O'REILLY, J.P. Region 2. Office of Director 2pp 22617 135 24% Fiche 50-416,84/03/05,8403130253
- 8403190059 LER 84-008-00 on 840202 during cold shutdown, control power AUSIYOUSY LEM 84-000-00 on 84020%, OUTing cold shutdown, control power to HFCB pump last Caused by incorrect info on electrical iineup sheet of sys operating instruction Instructions changed to correct breaker info W/840305 ltr PARKER, J. DALEL F. Miesissippi Fower & Light Co. 84/03/05 3pp 22666 197 24X Fiche 50-416,84/03/05,8403190059
- 8403170119 Special Rept 84-005/0 on 840201, HPCS diesel generator NO3190115 Special Rept 84-003/0 on 540201, Arcs diesel generator tripped on iou lube gil pressure during routine surveiliance Ceused by failed reiay Agastat relay replaced w/identicel component & similar type relays calibr MALE.L F Mississippi Power & Light Co 84/03/05, U'REILLY, J P. Regian 2. Office of Director 2pp 22666 264 24X Fiche 50-416,84/03/05,8403170115
- 8403300251 Summary of 840221 meeting w/util in Bethesda, MD re details of util proposed onsite/offsite electrical power reliability progrem for Transamerica Delavel-Inc diesel generators Attendance list & viewgraphs encl HOUBTON, M D Licensing Branch 2 84/03/06 Licensing Branch 2 2ipp 22845 001 24X Fiche 50-416:84/03/06:8403300251
- 8403120136 Part 2i rept re Westinghouse Type SA-i DBR or DBRV stendby diesel generator differential relay defect Relay problem reported in 840215 Suppl i to IE Info Notice 83-63 RTE Delta requested to review defect & recommend correction BDYER:R E Transamerica Delavai, Inc 84/03/07 Director's Office, Office of Inspection and Enforcement 2pp 22585 217 24X Fiche 50-416,84/03/07.8403120136 22585 219 24X
- B403130464 LER B4-003-00 on B40210, while power removed from control room fresh air unit chloring detector B, per maint work order, unit started up automatically in isolation mode Caused by personnel error Personnel counseled W/840308 itr PARKER, J. DALE, L. F. Mississippi Power & Light Co. B4/03/08 3 22613 249 24X Fiche 50-416,84/03/08,8403130464 84/03/08 300
- 8403190033 Updated LER 83-126/01X-1 on 830904, Div 1 diesei generator Fluck line ruptured causing fire near left benk turbocharger
 Caused by fatigue crack propagation Fuei line support added
 to Div i & 2 diesel generators W/B40308 itr
 BYRD.R . DALE,L F Mississippi Power & Light Co B4/03/08
 D'REILLY.J P Region 2, Office of Director 7pp 22666 ii5 24X
 Fiche 50-4i6.84/03/08.8403190033
- 8403200064 Updeted LER 83-179/03x-1.on 831105.Div II diesei generator TOURDOOD OPDERED LEN 83-1/7/03X-1. On 831405. Div II diesei gene shut down upon discovery of fuel oil return line leek After repair during restert, generetor tripped due to isolation of fuel supply velve F016B W/840308 ltr.

 BYRD, R W , DALE, L F Mississippi Power & Light Co. 84/03/08 D'REILLY, J P Region 2, Office of Director App 22684 357 Fiche 50~416,84/03/08,8403200064.
- 8403190043 Special Rept 84-013/0 on 840127, smoke detectors in Zone 2-10 alermed & would not reset Fire watches established per Tech Spec 3.3 7 9, Ceused by accumulation of dust particles on ionization detector Detectors cleaned & reset DALE/L F Mississippi Power & Light Co. 84/03/09 Q'REILLY, J P Region 2, Office of Director 2pp. 22666 246 24X Fiche 50-416,84/03/09,8403190043
- B403i9033i Special Rept 84-0i2/0 on 84020i, special fire door insp revealed 147 doors in auxiliary & control bldgs not in compliance w/spec requirements Updated rapt expected by Edoppinance w/spec regorders and a 1840331.

 PALE, L F Mississippi Power & Light Co 84/03/09 O'REILLY, J P Region 2, Dffice of Director 2pp 22673, 280 24X Fiche 50-416, 84/03/09, 8403190331
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delayal, Inc (TDI) Comers Group Distribution list encl list enci EISENHUT,D Q Division of Licensing 84/03/12 PALLADING Commissioners 3pp 22708:001 24X Fiche 50-000,84/03/12. B402090039

- 3060536 Forwards summary of 840210 meeting u/Transamerica Delavaling Quners Group in Bethesda. HD re problems u/emergency lessel generators
 ARUSD.R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No
- ARUSO,R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No atailed Affiliation Oiven App 22708 006 24X iche 30-000,84/03/12,8402090039
- 3060554 Transcript of 840210 meeting w/Transamerica Delaval.Inc dners Group in Bethesda.MD re problems w/emergency diesel
- nerators NRC No Detailed Affiliation Given 84/02/10. 147pp 7201 008 24X Fiche 50-000,84/03/12,8402090039
- 3070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners roup in Hading River.NY re program plan to establish eliability of diesel generators Agenda, meeting transcript & thendance list encl eance list enc: R.M A Licensing Branch 4 84/02/27 Licensing Branch 4 22708 161. 24% Fiche 50-000,84/03/12,8402090039
- 1070423 Transcript of B40216 conference in Wading River, NY re 'ansamerica Delaval. Inc diesel generators Pp 1-82 Commissioners 84/02/16 84pp 22708 169. 24X chs 30-000.84/03/12.8402090037
- iOO50 Forwards "Design Review of Connecting Rod Bearing Shells for isamerica Delayal Enterprise Engines" For Shoreham & id Oulf diesel generators
 LER, W J Long Island Lighting Co 84/03/12. DENTON-H R
 ce of Nuclear Reactor Regulation. Director 2pp 22632 074
 Fiche 50-000,84/03/12,8403140050
- ii40086 "Design Review of Connecting Rod Bearing Shells for ansamerica Delaval Enterprise Engines " Failure Analysis Associates PAD 7396 84/03/12 5ipp 632 076 24% Fiche 50-000.84/03/12.8403140050
- O216 Special Rept 84-010/0 on 840210, diesel generator 12 failed tart on manuel initiation signal from control room ed by erroneous step in procedure resulting in improper stment of lifters during pushrod replacement. LF Mississippi Power & Light Ca 84/03/12 0/REILLY, J P on 2, Office of Director 2pp 22670 246 24% e 50-416,84/03/12,8403;90216
- 0292 Special Rept B4-014/0.on B40204, listed fire doors blocked to support planned maint activities. Fire watches blished per Tech Spec 3.7 7 until doors restored .L F Mississippi Pawer & Light Co 84/03/12 0'REILLY, J P on 2. Office of Director 2pp 22674 359 24X e 50-416,84/03/12,8403190292
- Oi7 Updated LER 83-189/03X-1 on B31207 & 840201, breaker 132-1704 iv 3 EEF bus tripped Caused by broken current limiter stor socket for breaker position indicating light tat relay 7012 replaced W/B40312 ltr (R. DALE, F. Mississippi Power & Light Co. B4/03/12 ILLY, J.P. Region 2. Office of Director 49p 22698 346 24X e 30-416.84/03/12.8403200017
-)133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Capscrew Stress Analysis Rept " Capscrew design adequate applicable engines & syc conditions ... ER.N. J. TDI (Transamerica Delaval, Inc.) Dwners Group 3/13 DENTON, H. R. Office of Nuclear Reactor Regulation, ctor 2pp 22539, 270 24X Fiche: 50-000, 84/03/13, 8403150133
- 2014 Special Rept B4-015/O on 840229, GA identified failure to orm monthly verification per Item 2 C(28) requiring fuel pool coolers to be isolated from standby svc sys Temporary change notice initiated LF Mississippl Power & Light Co. 84/03/13, D'REILLY, JP no 2. Office of Director 3pp 22683 353 24X 50-416,84/03/13,8403200014
- 192 Final deficiency rept re anti-rotational setscrews in Anchor ng glove valves Initially reported on 8402f3. Setscrew ened & stem collar threads staked using ctr punch reported per Part 21 for Unit 1, IBHY.J.P. Mississippi Power & Light Co. 84/03/14 LLY.J.P. Region 2: 04fice of Director 5pp. 22707, 257 24X 50-416,84/03/14,8403210192.
- 222 Responds to 840214 Requests for Info 1 & 2 re β -4 series es List indicating engine number, model & syc number, mer name & address, rating, date shipped & date started
- MS.C 8 Transamerica Delaval, Inc. 84/03/16 E16ENHUT, D 0 ion of Licensing 20pp. 22691 i79 24X Fiche, 50-000, 84/03/16, 00222

- 8403260244 Updated LER 83-171/03x-1 on 831028, fuel oil leak & broken connector gushred discovered Caused by crack in oil tubing & difficulty in welding pushrod Tubing & pushrod replaced H/840316 ltr BYRD.R : DALE,L F Mississippi Power & Light Co 84/03/16 O'REILLY,J P Region 2, Office of Director 4pp 22754,355 24X Fiche 30-416,84/03/16,8403260244
- 8403300114 Special Rept 84-011/0 broadleaf vegetation samples unavailable for collection in Feb 1984 due to unseasonable weather conditions Required sampling will resume when vegetation recovered from harsh weather conditions DALE: LF Mississippi Power & Light Co 84/03/20 0'REILI Region 2. Uffice of Director ip. 22821 236 24% Fiche 90-416.84/03/20,8403300114 ons /20 o'REILLY,JP 24%
- B40330007 Updated Special Rept 84-003/1 on B40i12 standby dissel gammator 12 tripped on reverse power while running parallel ω/offsite power Caused by faulty control rectifier diode Reactifier replaced DALG-L F Mississippi Power & Light Co 84/03/21 G'REILLY, J Region 2. Office of Director 2pp 22822 127 24X Fiche 50-416-84/03/21.8403300007
- B403300027 Updated LER B3-122/01X-1 on B3090B, valve P64F467 which supplies operating pressure to CO2 fire protection master selector valve found closed Cause Unknown Valve now locked open W/840321 Itr
 BYRD.R. DALE, F Hississippi Power & Light Co B4/03/21
 0'REILLY, J P Region 2, Office of Director 4pp 22822 184
 Fiche 50-416.84/03/21,8403300027
- 8403300037 Updated LER 83-i69/03X-i on 831023, nitrogen pressure in control rod screm accumulators 40-53 & 24-29 fell below i.520 psig Caused by normal leakage Pressure switch & gauge tested W/840321 ltr
 BYRD.R , DALE.L F Missiesippi Power & Light Co 84/03/21
 0 'REILLY.J P Region 2, Office of Director 3pp 22821 237 24X
 Fiche 50-416.84/03/21.8403300037
- 8403300082 Updated Special Rept 84-iii/1 on 830328 fire penetration CE-519D in computer room opened under maint work order (MMO) to install conduits Caused by design closure datail being omitted from MMD Programmatic control implemented. DALE: LF Mississippi Power & Light Co 84/03/21 0'REILLY; J P Region 2. Office of Director 2pp 22822 076 24x Fiche 50-416,84/03/21,8403300082
- 8403300113 Update LER 82-080/01X-4 on 821004, capscrew on Div 2 standby dissel generator securing rear crankcase cover to engine block cracked Caused by fatigue due to engine operation Capscrews raplaced. W/840321 ltr BYRD.R. DALE,L F. Mississippi Power & Light Co. B4/03/21 D'REILLY,J P. Region 2, Office of Director 5pp. 22821 231 24X Fiche 50-416,84/03/21,8403300113
- 8403300117 Updated LER 83-188/03X-1 on 831201. reactor protection sys 90330017 / Updated LEK 83-189703X-1 on BIRO1. reactor protection sys Bus B & shutdoun cooling lost when power supply breaker tripped Caused by isolation valve on suction of pump closing Time delay setting increased to 3 5 s H/840321 ltr BYRD:R: DALE:L F Mississippi Power & Light Co 84/03/Z1. D'REILLY, J P Region 2, Office of Director 3pp 22820:252, 24X Fiche 30-416/84/03/21.8403300117
- B403300118 Updated LER 83-190/03X-1 on 831214. Div 2 isolation occurred, causing loss of shutdown cooling when pump suction valve F009 isolated Caused by temporary outage restoration procedure error. Procedure retired W/840321 ltr PARKER, J., DALE, L.F. Mississippi Power & Light Co. 84/03/21 0/REILLY, J.P. Region 2. Office of Director 3pp. 22820:310 24X Fiche 50-416,84/03/21,8403300118
- 8403300124 Updated Special Rept 84-110/1 on 831213, Fire Door 1A320 blocked open to support planned maint & testing activities Fire Watches established until door restored on 840306 DALE/L F Mississippi Power & Light Co 84/03/21 g/REILLY, J P Region 2, Dffice of Director 1p 22821 101. 24X Fiche 50-416,84/03/21,8403300124
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by S&W for Transamerica Delaval, Inc (TDI) Diesel Generator Owners Group MUSELER, H J TDI (Transamerica Delavai, Inc.) Owners Group. MUSELER, H J Long Island Lighting Co B4/03/23 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp. 22774:001 24X Ficha 50-000.84/03/23,8402270132

- B403270134 Requests meeting on B40418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delayal diesel generators List of suggested meeting topics encl MCGAUGHY, JP TDI (Transamerica Delayal, Inc.) Duners Group MCGAUGHY, JP Mississippi Power & Light Co B4/03/23 DENYON, HR Dffice of Nuclear Reactor Regulation, Director 4pp 22769 133 24% Fiche 50-000, 84/03/23, 8403270134
- T Heering transcripts on non-antitrust matters
- B40306008B Transcript of 840229 hearing in Vicksburg, MS Pp 1-95
 * Atomic Safety and Licensing Board Panel 84/02/29 103pp
 22306.001 24X Fiche 50-416.84/02/29,840306008B
- 8403070378 Transcript of Commission 840227 briefing in Washington, DC re status of util progress toward obtaining full power OL Pp 1-73 Supporting documentation encl # Commissioners 8402/27 101pp 22567 090 24X Fiche 50-416,84/02/27,8403070378
- B402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerice Delayal, Inc (TDI) Owners Group Distribution list and EIGENHUT, D O Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fichs 50-000,84/03/12,8802090039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Deiavai, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators CARUBO, R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No Datelled Affiliation Given App 22708 006 24X Fiche 50-000, 84/03/12, 8402090039
- --B403060554 Transcript of B40210 meeting w/Transamerica Delaval, Inc Owners Oroup in Bethesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given B4/02/10 147pp 67201 008 24X Fiche 50-000, B4/03/12, 8402090039
- ~-8403070407 Summary of 840216 meeting w/Transemerica Delavai. Inc Owners Oroup in Wading River, NY re progrem plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl.

 MILLER: M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161. 24X Fiche 50-000.84/03/12.8402090039
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delavai.Inc diesel generators Pp 1-82 # Commissioners 84/02/16 84pp 22708 169 24X Fiche 30-000.84/03/12,84020790037
- 8409230195 Transcript of 840320 briefling in Washington,DC re Tech Spec requirements Pp 1-74 Supporting documentation enci # Commissioners 84/03/20, 85pp 22759 178 24X Fichs.50-416,84/03/20,8403230195

V Operator Examinations

- 8403270074 Forwards updated info on operating shift experience to supersede previous submittal, including chart of experience levels of five proposed operating shifts.

 DALE, L. F. Mississippi Power & Light Co. 84/03/16 DENTON. H. R. Office of Nuclear Reactor Regulation, Director Bpp 22806 341 24X Fiche 50-416,84/03/16,8403270074.
- X Onsite Storage of Low Lavel Waste
- 8403220156 Informs of plans for meeting classification & weste form requirements of 10CFR61. Contractor currently dewatering resins w/epproved procedures to ensure no free standing water exists

 DALE, L. F. Mississippi Power & Light Co 84/03/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22715 335 24X Fiche: 50-416,84/03/16,8403220156
- DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

 A. Application/construction stage documents & correspondence
- 8403160252 Forwards request for eddl info re const GA program to complete evaluation of changes to program LEWIG.R.C Division of Project & Resident Programs 84/02/13 RIGHARD.J B Mississippi Power & Light Co 3pp 22660 i15 243 Fiche: 50-417,84/02/13,8403160252

- B403070325 Forwards info re shift advisors including job description MCGAUGHY. J P Mississippi Power & Light Co 84/02/20 DENTON H R Office of Nuclear Reaction Regulation. Director 6pp 22546 198 24X Fiche 50-416. B4/02/20, B403070325
- 8403080367 Responds to FDIA request for documents re BMR Integranular Stress Corrosion Cracking Duners Group meeting on or about 811028 Forwards App A documents Records also in PDR FELTON, J M Division of Rules and Records 84/02/28 HAFNER. B 804foik Nuclear Study Group 2pp 22583 008 24% Fiche 50-000.84/02/28.8403080367
- --8309210434 Requests evaluation of Grand Gulf & Shoreham 830817 & 23 responses respectively re intergranular stress corrosion cracking in BHR piping Response requested by 830916 W/o encl
 EISENHUT, D G Division of Licensing 83/09/06 VOLLMER, R
 Division of Engineering ip 22583 010 24X
 Fiche 50-000, 84/02/28, 8403080367
- B403050236 Forwards detailed breakdown of approx 200 Tech Spec changes requested by licenses & categorized in Dircks 840202 memo DIRCKS; M J Office of the Executive Director for Operations 84/02/29 PALLADIND, OILLINSKY, ROBERTS Commissioners 36pp , 22527 215 24x Fiche 50-416,84/02/29,8403050236
- 8403210109 Bubmits interim response to 840224 ltr requesting certification re Tech Spacs & FBAR Review & certification program in progress Meeting scheduled for 840309 to discuss program scope, review criteria & schedule DALE, L.F. Mississippi Power & Light Co. 84/03/08 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp. 22704 360 24X Fiche 50-416,84/03/08,8403210109
- B403210053 Endorses SH Hobbs Feb 1984 Ltr HGN-015 to HR Denton in response to NRC B31208 request for addl info re Hydrogen Control Owners Group (HCCG) test program Questions to be answered by HCCG & util.respectively, listed DALE, L F Mississipp: Power & Light Co 84/03/09 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 22704 344 24X Fiche 50-416,84/03/09.8403210053
- 8403210057 Forwards description of Teth Spec review program, per 840224 request Program estimated to end on 840406 Formal response expected by 840409 MCGAUGHY, J P Mississippi Power & Light Co 84/03/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22705 021 24X Fiche 50-416,84/03/18,8403210057
- --B403210062 "Tech Spec Review Program Description "
 # Mississippi Power & Light Co 84/03/31 20pp 22705 023 24X
 Fichs 50-416,84/03/18,8403210057
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B documents entirely withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S 1 Carvey, Schubert, Adams & Baner 7pp 22583 226 24X Fichs 50-000,84/02/13,8403080179
- --B005130793 Provides status of SER inputs & acceptance reviews for OL & CP applications Schedule should be met
 BURKE.W C Effluent Treatment Systems Branch B0/02/06
 KREGER.W E Assistant Director for Site Analysis ip 22583 235
 24X Fiche 50-000.84/02/13,8403080179
- 8403210140 Forwards confirmation of Lonergan safety relief valve qualification & operability testing of reclassified valves, per util 821108 & 18 itrs & 85ER 4

 DALE, L F Mississippi Power & Light Co 84/03/13 DENTON, H R

 Office of Nuclear Reactor Regulation, Director 4pp 22707 276

 24X Fiche 50-416,84/03/13,8403210140
- F Security, medical, emergency & fire protection plans
- 8403210115 Forwards BALP Repts 50-416/83-55 & 50-417/83-09 for Sept 1982 - Sept 1983 LEWIS,R C Division of Project & Resident Programs 84/01/11 RICHARD,J B Mississippi Power & Light Co 2pp 22707 144 24X Fiche 50-416,84/01/11.8403210115
- --8403210122 BALP Repts 50-416/83-55 & 50-417/83-09 for 8ept 1982 --Sept 1983 * Region 2, Office of Director 84/01/11 32pp 22707 146 24X Fiche 50-416,84/01/11,8403210115

- 8403160281 Notifies of 840316 workshop to discuss 10CFR50.App R
 requirements & inspresults to resolve misunderstandings re
 fire protection Attendees should be limited to six due to
 size of conference room
 LEWIS.R C Division of Project & Resident Programs 84/03/02
 RICHARD. J B Mississippi Power & Light Co ip 22660 350 24X
 Fiche 50-416.84/03/02.8403160281
- 8403160336 Discusses util 840224 ltr re 1984 emergency exercise Exercise objectives reviewed & comments provided to P Benedact, corporate emergency preparedness coordinator VERRELLI,D M Division of Project & Resident Programs 84/03 RICHARD,J B Mississippi Power & Light Co ip 22660 03i Fiche 50-416,84/03/05.8403160336 84/03/05
- B403130052 Forwards State of LA B31227 request for exemption from full participation at B40410 annual radiological smergency preparedness exercise FEMA supports exemption based on State of LA full participation in Waterford exercise KRIMM,R W Federal Emergency Management Agency 84/03/09 JURDAN,E L Division of Emergency Preparedness & Enginssring Response (Post B30103) 3pp 22641 355 24% Fiche 50-416.84/03/09, B403130052

9 Adjudicatory correspondence

- 8403210165 Response to Jacksonians United for Livable Energy Policies renumbered Contentions 1,2 & 3 Admission of renumbered contentions acceptable Certificate of Svc enci MAGNER, M E Hearing Branch 4 DSB 016 84/03/19 Atomic Safety and Licensing Board Panel 7pp 22718 217 24X Fiche: 30-416,84/03/19,8403210165 Atomic Safety
- 8403270318 Forwards staff 830319 response to petitioner renumbered Contentions 1,2 & 3,per request W/o enci WAGNER,M E Hearing Branch 4 DBB 131 84/03/22 STEWART,C Affiliation Not Assigned 1p 22789 028 24X Fiche 50-416, 84/03/22,8403270318

H General correspondence

- B403270211 Expresses concern on safety of facility NRC should not allow operation before plant meets safety criteria HIEMER.J. L. Affiliation Not Assigned B4/03/22 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 22772 144 24% Fiche 50-416.84/03/22.8403270211
- J Insurance & indemnity information
- 8403140121 Forwards Endorsement 29 to NELIA Policy NF-257 & Endorsement 11 to MAELU Policy MF-106
 DALE.L F Mississippi Power & Light Co 84/03/02 KERR, 0, W
 Dffice of State Programs, Director 4pp 22620 284 24X
 Fiche 50-416.84/03/02.8403140121
- O Inspection reports. IE Bulletins & correspondence
- 840307026B Responds to questions raised during special safety insp on B30322-25 re lE Bulletin 80-11 that three mortar cube compression tests did not meet min compressive strength requirements Structural integrity unimpaired.

 DALE, L. F. Mississippi Power & Light Co. 83/12/30 0'REILLY, J. P. Regian 2. Offics of Director & Dp. 22546 086 24X
 Fische 50-416,83/12/30,840307026B
- 8403210115 Forwards SALP Repts 50-414/83-55 & 50-417/83-09 for Sept 1982 Sept 1983 LEWIS.R.C Division of Project & Resident Programs 84/01/11 RICHARD.J B Nississippi Power & Light Co 2pp 22707-144 24X Fiche 50-414, 84/01/11, 8403210115
- ~-8403210122 SALP Repts 50-416/83-55 & 50-417/83-09 for Sept 1982 -Region 2, Office of Director 84/01/11 32pp 22707 146 24X Fiche: 50-416,84/01/11,8403210115
- 1190072 IE Info Notice 84-13. "Potential Deficiency in Motor perated Valve Control Circuits & Annunciation " Svc list JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-i4. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enc! CRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc i30pp. 22552 329 24X Fiche 50-000,84/03/02,8402090007

- 8402090008 IE Info Notice 84-16, "Failure of Autometic Sprinkler Bys Valves to Opswate " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of No Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 078, 24X Fiche 50-000,84/03/02,8402070008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02. Consolidated Edison Co. of New York, Inc. 119pp 22553,217 24X Fiche 50-000,84/03/02,8402090009
- 8403120034 Staff requirements memo re 840229 briefing in Washington, DC re BALP review of areas prior to issuance of full-power recommendation & document interpreting LER rept CHILK.8 J Office of the Becretary of the Commission 84/03/02 DIRCKS, W J Office of the Executive Director for Operations Ip 22619 346 24% Fichs: 50-416,84/03/02,8403120034
- 84020900ii IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Int 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09, Rev i. "Lessons Leerned From Insps of Fire Protection Safe Shutdown Sys " Svc list enci JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York Inc 118pp 22635 049 24X Fichs 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list encl
 JORDAN,E L Division of Emergancy Preparadassa & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co of New
 York, Inc 188p 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of QE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12.8402090031.
- 8403270030 Provides interim response to IE Bulietin B3-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " Results of Investigation to date indicate no Ray Miller products supplied to facilities Final response expected by 840525 MCGAUGHY, J P Mississippi Power & Light Co 84/03/13, 0'REILLY, J P. Region 2, Office of Director, 3pp 22804 224, 24X Fiche 50-416.84/03/13,8403270030.
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities" Svc list encl.

 JURDAN: EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fichs 50-000,84/03/21,8402090043
- 8402090044 IF Into Notice 84-20, "Byo Life of Relaus in Safetu-Related Sys "Byc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001, 24X Ficha 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emsrgency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRKES, W J Office of the Executive Director for Opera
 84/02/21 PALLADINO Commissioners 9pp 22492.083
 Fichs 50-000,84/02/21,8403020443
- 8 Reportable occurrences, LERs & related correspondence
- B403010451 Informs Commission of problems w/emergancy dissel generators mfg by Transamerica Delaval, Inc DIRCKS, W J Office of the Executive Director for Operations, BECY-83-034 84/01/25, 4pp. 22438 347. 24X Fichs 50-000,84/01/25, RADBOLDASI
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transemerica Belaval, Inc Owners Oroup program commitments, Rept evaluates cracks in AF piston skirts in Shoreham & Grand Guif Nuclear Power Stations HUSELER, H J TDI (Transamerica Delavai, Inc.) Owners Group, 84/02/27 DENTON-H, R Office of Nuclear Reactor Regulation, Director 3pp 22434,090 24X Fiche 50-000,84/02/27,8403010207

- --8403010446 "Investigation of Types AF & AE Piston Skirts "
 # Failure Analysis Associates FAAA-84-2-14 84/02/27 83pp
 22434 093 24X Fiche 50-000.84/02/27.8403010207
- 8403140203 Forwards "Operating History Overview for Diesel Generators in Nuclear Svc," comparing Transamerica Delaval Inc generators w/generators mfg by other vendors HEBDIN.F J Program Technology Branch 84/02/27 BERLINGER, C H NRC - No Detailed Affiliation Given ip 22638 319 24X Fiche 50-000.84/02/27,6403140203
- --8403140205 "Operating History Overview for Diesel Generators in Nuclear 8vc." # Director's Office 84/02/27 65pp 22639 001 24X Fiche 50-000, 84/02/27, 8403140203
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval.Inc amorgancy diesel generatore MUSELER.W J TDI (Transamerica Delaval. Inc.) Dwners Group MUSELER.W J Long Island Lighting Co. 84/02/28 DENTON.H R Office of Nuclear Reactor Regulation. Director 42pp 22435 177 24X Fiche 50-000.84/02/28.8403010218
- 8403260233 Forwards summary list of deficiencies identified per 10CFRSO 35(e),Part 21 & potential generic ltr repts for comments
 STAROBTECKI.R Division of Project & Resident Programs. 84/02/28 Region 1. Office of Director. 7pp 22756 065 24X Fiche. 50-000.84/02/28.840326023.
- 8403090265 Final Deficiency Rept PRD 83/08 re inability to maintain pressurized water supply to RHR pumpe & discharge piping supplied by Bechtel Initially reported on 830415 Hardware mode implemented Also reportable per Part 21 MCGAUOHY, J.P. Mississippi Power & Light Co. 84/03/02 0'46ELLY, J.P. Region 2. Office of Director 4pp 22572 144 24X Fiche. 50-416, 84/03/02,8403090265
- 8403140048 Forwards "Grand Gulf Component Tracking Sys." "Shoreham Component Tracking Sys" & "Transamerica Delaval. Inc Dieszi Generators Dwnere Group Progrem Plan." to resolva concerns w/emergency dieszi generators MUSELER.W J. Long Ieland Lighting Co. 84/03/02 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 22626-062 24X Fiche 50-000.84/03/02.8403140048
- --8403140080 "Grand Oulf Component Tracking Sye "
 * Long Taland Lighting Co. 84/02/27 879pp 22626 064 24X
 Fiche: 50-000, 84/03/02, 8403140048
- ---8403140095 "Transamerica Delaval, Inc Diesel Generators Duners Group Program Plan," * TDI (Transamerica Delaval, Inc.) Guners Group, 84/03/02 261pp 22628-223, 24X Fiche 50-000.84/03/02.8403140048
- 8403120136 Part 21 rept re Westinghouse Type 8A-1 DSR or DBRV standby diesel generator differential relay defect Relay problem reported in 840215 Suppl i to IE Info Notice 83-63 RTE Delta requested to review defect & recommend correction.

 80YER:R E Transamerica Delaval, Inc 84/03/07 Director's Office, Office of Inspection and Enforcement. 2pp 22585:219 24X Fiche:50-416,84/03/07,8403120136
- 8402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Duners Group Distribution list encl
 EIBENHUT, D. 9. Division of Licensing 84/03/12 PALLADING Commissioners, 5pp. 22708,001 24X Fichs 50-000,84/03/12,8402070039
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators % NRC - No Detailed Affiliation Given, 84/02/10 147pp 67201-008, 24X Fichs 50-000, 84/03/12, 8402090039,
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators. Agenda, meeting transcript & attendance list encl.
 MILLER, M.A. Licensing Branch 4. 84/02/27 Licensing Branch 4
 8pp 22708-161 24X Fiche 50-000.84/03/12,8402090039

- --8403070423 Transcript of 840214 conference in Wading River, NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fichs 50-000, 84/03/12, 8402090039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delavel Enterprise Engines" for Shoreham & Opand Gulf dises) generators MUSELER.W J Long Island Lighting Co 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 22632 074 24X Fiche 30-000.89/03/12.8803140050
- --B403140086 "Design Review of Connecting Rod Bearing Shelis for Transamerica Delavai Enterprise Engines " * Failure Analysis Associates PAQ 7396 84/03/12 51pp 22632 076 24% Fiche 50-000,84/03/12,8403140050
- 8403130133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Arm Capacrew Stress Analysis Rept " Capacrew detign adequate for applicable engines & syc conditione MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/13, DENTON. H R Office of Nuclear Reactor Regulation, Director 2pp 22637 270 24X Fiche 50-000,84/03/13,8403150133
- 8403210192 Final deficiency rept re anti-rotational setscrews in Anchor Darling glove valves Initially reported on 840213 Setscrew tightened & stem collar threads staked using ctr punch Also reported per Part 21 for Unit i MCGAUGHY, JP Mississippi Power & Light Co 84/03/14 O'REILLY, JP Region 2, Office of Director 5pp 22707 257 24X Fiche 50-414,8403/14,8403210192
- 8403210041 Final deficiency rapt re incorrect operation of Div I & II diesel generator load shedding sequencing sys penels Initially reported on 830921 circuit cards & card racke returned for mod Reinstallation expected by 840427 MCGAUGHY. JP Mississippi Power & Light Co 84/03/15 O'REILLY. JP Region 2. Office of Director 5pp 22707 032 24X Fiche 50-417.84/03/15,8403210041
- 8403200222 Responds to 840214 Requests for Info i & 2 re R-4 series engines List indicating engine number model & evc number, customer name & address rating, date shipped & date started enci
 MATHEWS.C 8 Transamerica Delaval. Inc 84/03/16 EISENHUT.D Q
 Division of Licensing 20pp 22491 179 24% Fiche 50-000,84/03/16,8403200222
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysia: "prepared by S&W for Transamerica Delaval, Inc (TDI) Diesel Generator Dwners Group MUSELER. W J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22774 001 24X Fiche 50-000.84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica
 Delaval dissel generators List of suggested meeting topics
 anci
 MC9AUGHY, J P TDI (Transamerica Delavai, Inc.) Owners Oroup
 84/03/23 DENTON.H R Dffice of Nuclear Reactor Regulation,
 Director 4pp 22769 133 24X Fiche 50-000.84/03/23,8403270134

T Hearing transcripts on non-antitrust matters

- 8403070378 Transcript of Commission 840227 briefing in Washington, OC re status of util progress toward obtaining full power GL Pp 1-93 Supporting documentation ent!

 ** Commissioner* 84/02/27 101pp 22567 090 24X

 Fiche 50-416,84/02/29,8403070378
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delayai, Inc (TDI) Duners Group Distribution list anci EIBENHUT, D 0. Division of Liceneing 84/03/12 PALLADINO Commissioners 5pp 22708,001, 24X Fiche 50-000,84/03/12.8840299039.
- ---8403060536 Forwards summary of 840R10 meeting w/Transametica Delaval, Inc Owners Group in Bethesda.MD re-probleme w/emergency diesel generatore GARU80,R Licensing Branch 2. 84/02/27 O'REILLY.JP NRC No Detailed Affiliation Given 6pp 22708:006 24X Fichs 50-000.84/03/i2.8402090039
- --B403060554 Transcript of B40210 meeting w/Transemerica Delaval, Inc Owners Group in Bathesda, MD re problems w/emergency diesal generators * NRC - No Detailed Affiliation Given. B4/02/i0 147pp 67201:008 24X Fichs 50~000,84/03/12,8402070039

- --8403070409 Summary of 840216 meeting w/Transamerica Delaval. Inc Cuners Group in Wading River. NY re program plan to establish reliability of diesei generators Agenda, meeting transcript & attendance list enci HILLER, M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 50-000.84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval.Inc diesei generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000,84/03/12.8402090039
- DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8401120455 Notification of B40117-19 meetings w/util in Bethesda, MD to discuss applicant responses to Mechanical Engineering Branch safety review Guestions 210 B to 210 49 DOOLITTLE/E L Licensing Branch 1 84/01/05 YOUNGBLOOD, B J Licensing Branch 1 3pp 21804 104 24% Fiche 50-423.84/01/05.8401120455
- 8403070299 Forwards proprietary response to Question 492 4 re measurement of RCS flow Response withheld (ref 10CFR2 790) COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O Northeast Utilities 84/02/16 YOUNGBLOOD.B J Licensing Branch 1 2pp 22547 054 24X Fiche 30-423.84/02/16.8803070299
- --8403070302 Requests withholding proprietary info re response to Question 492 4 concerning RCE flow measurement uncertainty (ref 10CFR2 790) HIESEMANN.R A Westinghouse Electric Corp 83/08/18 YUUNOBLOOD.B J Licensing Branch I 8pp 22547 056 24X Fithe 30-423.84/02/16.8403070279
- 8403020158 Forwards requests for add1 info to complete evaluation of environ & safety portions of application for OL Response requested by 840315
 YOUNGELOOD, B J Licensing Branch i 84/02/17 COUNDIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 7pp 22491 142 24X Fiche 50-423,84/02/17,8403020158
- B403070304 Provides responses to three open items from NRC/BNL Yankee Atomic Electric Co & consuitants Mark I containment program plant-unique analysis rept 840216 review meeting CELIA:N S Teledyne Engineering Services 84/02/28 BiEGEL, B NRC No Detailed Affiliation Olven 4pp 22546 171 24X Fiche 50-000.84/02/28,8403070304
- 8403120320 Responds to 831228 ltr advising that rept, "Beismology & Geophysical Studies Miramichi Area, New Brunswick & Central NH." Vois I & II.no longer proprietary YOUNOBLOOD, B J Licensing Branch I 84/03/01 COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22596 335 24X Fiche 50-423.84/03/01.8403120320
- B403200182 Forwards Topical Rept 7703 on missile barrier interaction W/o rept
 EMERSON, W F Stone & Webster Engineering Corp 84/03/06
 PODLITTLE, E L Licensing Branch i 1p 22686 340 24X
 Fiche 50-423,84/03/06,8403200182.
- 8403280122 Summary of 840224 meeting w/Westinghouse Owners Group in Bethesda.MD re proposed Westinghouse steam generator tube rupture generic program Attendee list & agenda enci NERSES, v Licensing Granch 3 84/03/07 Licensing Granch 3 35pp 22811 131 24X Fiche 50-000.84/03/07,8403280122
- 8403260299 Forwards request for addi info to complete evaluation of safety portion of DL application resulting from 840105 meeting re util response to Guestion 230 & Response by 840315 requested YOUNDELOOD. B J Licensing Branch I 84/03/09 COUNCIL. W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 5pp 22759 356 24X Fiche 50-423, 84/03/09, 8403260299
- B403260200 Comments on Issue 3 of NUREO-OBB5, "NRC Policy & Pianning Quidance, 1984 " Seven themes identified represent important objectives for industry CDUNBIL.W 6 Northeast Utilities 84/03/12 DIRCKS, W J Office of the Executive Director for Operations 4pp 22756 204 24X Fiche 50-000, B4/03/12, 8403260200.
- 8403200149 Forwards "Seismic Fragilities of Structures & Components at Milistone 3 Nuclear Power Station," per 840306 meeting commitment COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W.O Northeast Utilities 84/03/13 YOUNGBLOOD, B J Licensing Branch 1 ip 22689 320 24X Fiche 50-423.84/03/13.8403200149.

- --B403200152 "Seismic Fragilities of Structures & Components at Millstone 3 Nuclear Power Station " WESLEY, D A., CAMPBELL.R D., HASHIMOTO,P 8 Associates SMA 20601 01-Ri-0 84/03/31 193pp 22689 321 24X Ficha 50-423,84/03/13,8403200149
- B403260181 Forwards six marked-up oversized P&IDs showing RCB pressure isolation valves, in response to Mechanical Engineering Branch Guestion 210 42 Aperture cards are available in PDR COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 0 Northeast Utilities 84/03/13, YDUNGSLOOD, B J Licensing Branch i 2pp 22796,048 24 X Fiche 50-423,84/03/13,8403260181
- 8403270112 Forwards completed operating shift experience survey Survey reflects shift experience base at present & projected shift experience base at time of fuel load Shift advisors will not be used Proposal encl COUNBIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W O Northeast Utilities 84/03/19 THOMPSON.H L Division of Human Factors Safety Bpp 22806 303 24X Fiche 50~423.84/03/19,8403290112
- 8403300187 Forwards proposed agenda for second corporate IE mgt meeting on 840403 to discuss const phase to preoperational & startup test phases & fire protection & security programs BTAROSTECKI, R Division of Project & Resident Programs 84/03/27 CDUNSIL.H O Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 22819 281 24X Fiche 50-423.84/03/27.8403300187
- C Utility Environmental Report (ER), amends & correspondence
- 8403130360 Forwards "Effluent Toxicity Testing at Milistone Nuclear Power Station Using Sheepshead Minnow During 1981-82" & "Davelopment of Long-Term Effluent Toxicity Testing Procedure ," in response to environ rept question COUNSIL.W Q Northeast Utilities Service Co (subs of Northeast Utilities) COUNSIL.W Q Northeast Utilities 84/02/03 YOUNOBLOOD.B J Licensing Branch 1 2pp 22617 023 24X Fiche 50-423.84/02/03.8403130360
- --8403130367 "Efficient Toxicity Testing at Millstone Nuclear Power Btation Using Bheepshead Minnow (Cyprinodon Variegatus) During 1981-82 " • Northeast Utilities 83/07/31 3ipp 22617 025 24X Fiche 50-423,84/02/03,8403130360
- --8403130376 "Development of Long-Term Efficient Toxicity Testing Procedure W/Bay Mysid (Mysidopsis bahia) & Preliminary Testing Results at Millstone Nuclear Power Station "

 Northeast Utilities 83/07/31 24pp 22617 056 24X Fiche 50-423,84/02/03,8403130360
- 8403070273 Forwards Amend 6 to environ rept OL stage, revising seismic risk assessment curves Transmittal & receipt forms encl COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W O , BEARS, C F Northeast Utilities 84/03/01 YOUNGELOOD, B J Licensing Branch 1 4pp 22546 293 24% Fiche 50-423,84/03/01,8403070273
- --8403070275 Amend & to environ rept OL stage * Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/03/31 5pp 22546 297 24X Fiche 50-423:84/03/01.8403070273
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8403030001 Discusses issuance of DES on 840417 Revised seismic fragilities data developed & effect on overall risk curves will be completed shortly Expresses concern that NRC unable to support issuance of DES on time COUNSIL, N O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W Q Northeast Utilities 84/02/21 YOUNDSLOOD, B J Licensing Branch 1 2pp 22490 063 24x Fiche 50-423,84/02/21,8403050001
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8403070130 Forwards sections of draft SER not transmitted in 831230 ltr Requests review of info & written response to open items prior to 840515 in order to accommodate schedule for issuance of final SER on 840716 YOUNOBLOOD, B. J. Licensing Branch 1 84/02/24 COUNBIL, W.O. Northeast Nuclear Energy Co (subs of Northeast Utilities), 120pp, 22564-001 24X Fiche 50-423,84/02/24,8403070130
- B403160272 Forwards response to SER questions contained in NRC 831205 ltr & discussed at Mechanical Engineering Branch 840117~19 meetings COUNSIL.W 0 . SEARS, C F Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL.W 0 Northeast Utilities. 84/03/01 YOUNOBLOOD, B J Licensing Branch i 100pp 22661.119, 24X Fiche 30~423.84/03/01.8403160292

- 8403220148 Forwards status of draft SER open items re fire protection, per 840216 meeting w/Chemical Engineering Branch All ventilation sys penetrating fire barriers verified, per Branch Technical Position CMEB 9 5-1 COUNSIL.W 0. SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL.W 0. Northeast Utilities 84/03/09 YOUNOSICODER J. Licensing Branch 1 23pp 22716 058 24% Fiche 50-423,84/03/09,8403220148
- 8403280286 Notification of Instrumentation & Contol Sys Branch (ICSB) 840313 meeting w/util in Bethesda, MD to discuss applicant responses to ICSB unresolved items redraft SER. Section 7 DODLITTLE. E. Licensing Branch 1 84/03/13 YOUNGBLOOD, B J Licensing Branch 1 3pp 22808 058 24X Fiche 50~423,84/03/13,
- 8403260149 Forwards response to Core Performance Branch draft SER Open Item 229 re rod bow analysis COUNSIL.W 0, SEARS.C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W 0 Northeast Utilities 84/03/16 YOUNOBLOOD.B J Licensing Branch 1 3pp 22750.332 24X Fiche 50-423.84/03/16.8403260149

F Security, medical, emergency & fire protection plans

- B403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in 1E Info Notice 84-09 Agenda for workshop encl MURLEY, TE Region 1, Office of Director 84/03/09 O'TOGLE, J D Consolidated Edison Co of New York, Inc 35pp 22672 062 24X Fichs 50-000,84/03/09,8403190243
- 8403220148 Forwards status of draft SER open items refire protection, per 840216 meeting w/Chemical Engineering Branch All ventilation sys penetrating fire barriers verified per Branch Technical Postion CMES 9 5-1 COUNSIL, W 0 , SEARS, C F Northeast Nuclear Energy Cn (subs of Northeast Utilities) COUNSIL, W 0 Northeast Utilities. 84/03/09 YOUNGELOOD, D J Licensing Branch 1 23pp 22716 058 24X Ficher 50-423, 84/03/09. 8403220148
- B40327000B Informs that util will provide info re planned deviations from Buppi 1 to NUREO-0737 by 840501 Delay has no effect on schedules for implementation of Buppi 1 to NUREO-0737 COUNSIL, H O Connecticut Vankee Atomic Power Co SEARS, C F Northeast Nuclear Energy Co, (subs of Northeast Utilities) COUNSIL, W O Northeast Utilities B4/03/16 EIBENHUT, D O Division of Licensing 2pp 22770 011 24X Fiche 80-000, 84/03/16, B403270008
- 8403300187 Forwards proposed agenda for second corporate 1E mgt meeting on 840403 to discuss const phase to preoperational & startup test phases & fire protection & security programs STAROSTECKI. R Division of Project & Resident Programs 84/03/27 COUNBIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp, 22819 281 24X Fiche 50-423,84/03/27,8403300187
- K Utility Final Bafety Analysis Report (FBAR) & amends
- B403140101 Forwards Amend 7 to FBAR List of responses to NRC requests for add 1 info & transmittal & receipt form dtd 840309 gncl CDUNBIL.M.O Northeast Nuclear Energy CO (subs of Northeast Utilities OCUNBIL.W.O Northeast Utilities B4/03/07 YOUNDBLODS B J. Licensing Branch 2 Spp 22622 OO1 24X Fiche: 50-423, 84/03/09, 8403140101
- --8403140107 Amend 7 to FBAR

 * Northeast Nuclear Energy Co. (subs of Northeast Utilities)
 84/03/31 526pp 22622.007 24X Fiche 50-423,84/03/09,
 8403140101
- Q Inspection reports, 1E Bulistins & correspondence
- 8403010427 Forwards IE Insp Rept 50-423/84-01 on 840116-20 No violations observed PARTLOW,J G. Division of GA, Bafeguards & Inspection Programs (Post 830103) 84/02/02 COUNSIL-N. G. Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp. 22449 323 24X Fiche. 50-423.84/02/02.8403010427
- --8403010430 IE Insp Rept 50-429/84-01 on 840116-20 No violations identified Major areas inspected implementation of GA program w/respect to Bahnson Co.implementation of GA program for sample of matl suppliers & HVAG equipment.

 MERBCHOFF,E W. NORMAN, D. Region 4. Diffice of Director BAKER, E. B

- B401190072 IE info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl URPAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24% Fiche 50-000.84/02/28, B401190072
- 8403070333 Ack receipt of 840209 ltr informing NRC of steps taken to correct deviations noted in IE Insp Rept 50-423/83-18 MARTIN, T Division of Engineering & Technical Programs 84/02/28 COUNSIL. W O Northeast Nuclear Energy Co (400s of Northeast Utilities) 2pp 22546 309 24X Fiche 50-423.84/02/28.8403070333
- --8403070336 Responds to NRC 840110 ltr re deviation noted in IE Insp Rept 50-423/83-18 Util will continue to allow use of cable splices when justified by analysis Rev to FSAR will be submitted by 800515 to clarify position COUNBIL, W Q , SEARS, C F Northeast Nuclear Energy Co. (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 84/02/09 MARTIN, T T Division of Engineering & Technical Programs 2pp 22546 311 24X Fithe 50-423,84/02/28,8403070333
- 8403210011 Requests extension until 840401 to respond to IE Bulletin 83-06, "Nonconforming Matls Supplied by Tube-Line Corp "Evaluation by S&M incomplete COUNSIL.W 0, SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) CCUNSIL.W 0 Northeast Utilities 84/02/29 MURLEY, T E Region 1, Office of Director 3pp 22706 341. 24X Fichs 50-423,84/02/29,8403210011
- 8402070007 IE info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC "Svc list encl GRACE.J N Division of GA. Bafeguards & inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22532 327 24X Fiche 50-000,84/03/02,8402070007
- 8402090008 IE info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fichs 50-000.84/03/02.8402090000
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Eve list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22353 217 24X Fiche 50-000.84/03/02.8402090009
- B402070011 iE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Gumponents Heiow Nil Ductifity Temp " Svc fist encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fishe 50-000.84/03/05,8402090011
- 8402090024 IE Info Notice 84-09.Rev i, "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys "Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (fost 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000.84/03/07,8402070028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type RFA Relays in Use in Class IE Bafety Sys " Svc list enci DEVOUNG.R C Director's Office. Diffice of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823-094 24x Fiche 50-000,84/03/12,8492090031.
- 8403220136 Provides results of reevaluation of performance assessment, per util 831219 ltr addressing topics discussed at 831127 SALP mgt meeting Category 1 rating will be assigned to refueling area for Milistone 2 Explains Category 2 ratings MURLEY.T E Region 1. Office of Director 84/03/16 COUNBIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) App 22716-047 24X Fiche 50-000,84/03/16,8403220136
- 8403230033 Forwards revised Class i & Class 2 portions of Rev 2 to FSI 2,01, "Preservice Insp Manual" COUNSIL,W G , SEARB,C.F Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL,W G Northeast Utilities 84/03/20 YOUNOBLOOD,B J Licensing Branch i 2pp 22744 001 24X Fiche 50-423.84/03/20,8403230033
- --B403230037 Revised Class 1 & Ciass 2 portions of Rev 2 to PSI 2 01,
 "Preservice Insp Mahual"

 * Northeast Nuclear Energy Co (subs of Northeast Utilities)
 B4/03/20 714pp 22744 003 24X Fiche 50-423,84/03/20,
 B403230033

- B402070043 IE Info Notice B4-19, "Two Events Involving Uneuthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 227 24X Fiche 50-000, 84/03/21, 8402090043
- 8402070044 IE Info Notice 84-20, "Bvc Life of Relays in Befety-Related Bys " Svc list enc! JORDAN, E L Division of Emergency Preperadness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933.001 24X Fiche 50-000,84/03/21,8402070044
- B403300144 Responds to IE Bulletin 83-08, "Electrical Circuit Breakers M/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Frip Bys " Haddam Nack fecility uses 31 Westinghouse-type DB breakers COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) B4/C3/21. MURLEY.T E Region 1. Office of Director 4pp 22820 068 24% Fiche 50-000.84/03/21.8403300144
- R Periodic operating reports & related correspondence
- B403020443 Forwards monthly status rept of offsite amergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS, W J Office of the Executive Director for Operations
 B4/02/21 PALLADING Commissioners 7pp 22492 083 24%
 Fiche 30-000,84/02/21,8403020443
- 8 Reportable occurrences. LERs & related correspondence
- 8403210095 Part 21 rept re nonconformance of metal hose essemblies for ASME, Bection III. Class 2 k 3 svc Status of nonconforming items shipped encl All customers notified LALIKOS. J M Titeflex Corp B3/12/16 Director's Office, Office of Inspection and Enforcement App 22704 324 24x Fiche: 50-000.83/12/16.8403210095
- B403210032 Part 21 rept re failure of auxiliary feedweter pump drive turbines, Olmpel NPS-4 T&T valve, to close Enci itr dtd 840203 sent to listed utils GE notified of affected units in BMR plants
 THERDUX.R R Terry Corp 84/02/22 WOODRUFF, R W Director's Office, Office of Inspection and Enforcement 4pp 22706 327 24X Fiche 50-000, 84/02/22, 8403210032
- B403070256 Followup Part 21 rept re defective mechanical snubber capatan springs supplied by Pacific Brientific Affected utils listed Purchasers have been notified & advised to work directly w/Pacific Brientific in disposition HDVI.L. NP9 Industries, Inc. 84/02/24 DEYOUNG.R.C. Director's Office, Office of inspection and Enforcement 2sp. 22536-279 24) Fiche 50-000,84/02/24,8403070256.
- 8403260233 Forwards summary list of deficiencies identified per 100FRSO 55(e).Part 21 & potential generic itr repts for comments
 STAROSTECKI.R Division of Project & Resident Programs 84/02/28 Region 1. Office of Director 7pp 22756 065 24X Fiche: 50-000, 84/02/28, 8403260233
- 8403130213 Potential Significant Deficiency Rept BD-51 re design & const of NAMCO Model EA-180 limit switches provided es accessories on valves supplied by Pecific Valves Initially reported on 840131 Discussions w/vendor initiated COUNSIL. N 0 , SEARS.C.F Northeast Utilities 84/03/01 MURLEY.T E Region 1, Office of Director 2pp 22617 320 24X Fiche 50-423,84/03/01,8403130213.
- 8403210161 Significant Deficiency Rept 8D-48 re defective design & const of mein control board lug wires supplied by Reliance Electric Co Initially reported on 831i10 Insp & repeir program initiated. Next rept by Nov 1984 CDUNBIL, W 0., SEARS, C, F Northeast Utilities 84/03/01 MURLEY, T E. Region 1. Office of Director 2pp 22707.110 24X Fiche 50-423.84/03/01,8403210161.

V Operator Examinations

8403290112 Forwards completed operating shift experience survey Burvey reflects shift experience base at present & projected shift experience base et time of fuel load Shift advisors will not be used Proposal encl COUNSIL.W.O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W.O Northeast Utilities 84/03/19 THOMPSON.H L Division of Humen Factors Safety 8pp. 22806 303, 24% Fiche 50-423,84/03/19,8403290112

- DOCKET 50-424 VOOTLE ELECTRIC GENERATING PLANT
- A Application/construction stage documents & correspondence
- B403030311 Notification of B40306-07 meetings w/util in Waynesboro.QA to facilitate NRC review through site visits MILLER,M A Licensing Branch 4 84/02/23 ADENSAM,E @ Licensing Brench 4 3pp 22501 272 24X Fiche 50-424,B4/02/23,B403050311.
- 8403010319 Amend 4 to epplication for OLs, consisting of Amend 4 to FBAR FORTER, D D Georgia Power Co 84/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22433, 111 24X Fiche 50-424,84/02/24,8403010319
- C Utility Environmental Report (ER), amends & correspondence
- 8403090189 Comments on soviron rept OL stage, per Ofc of Environ Project Review Dec 1983 memo Two unresolved aquetic issues should be addressed as speciel study conditions of OL MCBAY.L Q Interior. Dept of. Fish & Wildlife Service 84/01/20 FARLEY, J Q Southern Co. Services, Inc. Jpp 22573 304. 24X Fiche 30-424,84/01/20,8403090189.
- E NRC Sefety Evaluation Report (SER), suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents. App B document metirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13, ANDERSON, B I Garvey, Schubert, Adems & Barer. 7pp 22583'226. 24X Fiche 50-000,84/02/13,8403080179.
- --Bi03040052 Forwards short & long-term OL & CP review schedules, in response to B01216 meeting w/USOS List of OL plant reviews for which NRC tentatively plans to seek USOS assistance is provided.

 JACKSON, R E Oeosciences Branch NRC-03-80-113 81/01/21 Interior, Dept. of, Geological Survey, 5pp. 22583 272 24X Fiche 50-000,84/02/13,8403080179
- 9 Adjudicatory correspondence
- 8403020126 Response opposing applicant answer to petitions for leave to intervene & requests for hearing Request for hearings to be held in Atlanta, 0A reiterated Certificate of Bvc encl. TEPER, D C Georgians Against Nuclear Energy 84/02/24 Atomic Befety and Licensing Board Panei 4pp 22442:147, 24X Fiche 50-424,84/02/24,8403020126.
- B403140114 Reiterates staff B40215 response to Campaign for Prosperous Georgie B40224 request that hearings be held in Atlanta, QA Site of hearings question does not need resolution at present BORDENICK, BM Hearing Branch 3. 84/02/29. MARQULIES, MB, LINENBERGER, O. PARIS, O. H. Atomic Sefety and Licensing Board Panel 2pp 22423 357 24X Fiche 50-424,84/02/29,8403140114.
- B403040090 Applicant response to Campaign for Prosperous Georgia (CPG) B40224 memorandum re location of hearing CPG has no reason for departing from NRC policy & ignores fact that project ofc moved from Atlanta to site W/Gertificate of Svc TROWBRIDGE.O.F. Georgia Power Co TROWBRIDGE.O.F. Shaw, Pittman, Potts & Troubhidge B4/03/01 Bpp 22516:301 24X F1che 50-424.84/03/01.8403040090
- 8403:30457 Requests that hearings on OL epplication be held in State of GA to afford state officials & constituents opportunity to attend & monitor proceedings.

 LOVETY, B. Georgia, State of 84/03/07 Office of the Secretary of the Commission ip 226:3:348 24X Fiche: 50-424,84/03/07, 8403:30457
- B403130394 Memorandum & order scheduling B40530 special prehearing conference in Auguste, GA to identify key issues, to consider all intervention petitions & to establish schedule for further ection MAROULIES, M B , LINENBERGER, Q , PARIB, O H Atomic Bafety and Licensing Boerd Panel B4/03/09, 10pp 22616-081, 24X Fiche, 30-424, 84/03/09, 8403130394
- B403230279 Requests that hearings be located in Waynesborg, QA. PARRISH, S O Waynesborg, QA. DBB 078 B4/03/19. Office of the Secretary of the Commission 19 22743 093 24% Fiche, 50-424, 84/03/19, 8403230279

H General correspondence

- 8403150023 Advises of change to correspondence distribution adding JE Joiner & RE Conwey deleting DE Dutton & changing addresses of DO Foster & RA Thomas
 FOBTER D O Georgia Power Co 84/03/08 ADENSAM, E 0 Licensing
 Branch 4 2pp 22441 280 24X Fiche 50-424,84/03/08.8403150023
- K Utility Final Bafety Analysis Report (FBAR) & amends
- B403010319 Amend 4 to application for OLs.consisting of Amend 4 to FBAR FOBYER, D O Georgia Power Co 84/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22433 iii 24X Ficha 50-424, 84/02/24, 8403010319
- --8403010325 Amend 4 to F8AR * Deorgie Power Co 84/02/24 184pp 22433 113 24) Fiche 50-424,84/02/24,8403010319
- G Inspection reports, IE Bulletins & correspondence
- 8403080870 Appeals denial of FDIA request for draft IE Insp Repts 50-424/83-13 % 50-425/83-13 DOMBY. A H Troutman. Sanders, Lockerman & Ashmore 83/11/14 Office of the Executive Director for Operations 2pp 22576 244 24X Fiche 50-424, 83/11/14, 8403080370
- 8403080372 Responds to appeal re deniel of FDIA request for draft IE Insp Repts 50-424/83-13 & 50-425/83-13 Forwards documents FELTON.J M Division of Rules and Records 84/01/31 DOMBY, A H Troutman, Sanders. Lockerman & Ashmore 1p 22576 246 24X Fiche 50-424,84/01/31,8403080372
- --8403080377 Forwards IE Insp Repts 50-424/83-13 & 50-425/83-13 on 830621-0720 & notice of violation LEMIB.R C Division of Project & Resident Programs 83/10/14 KELLEY.R J Georgia Power Co 2pp 22576 247 24X Fichs 50-424,84/01/31,8403080372
- --8403080381 Natice of violation from insp on 830621-0720 * Ragion 2, Diffice of Director 83/10/14 3pp 22576 249 24X Fiche 50-424,84/01/31,8403080372
- --8403080384 IE Insp Repts 50-424/83-13 & 50-425/83-13 on 830621-0720 Violations noted fellure to implement pipe support control documents & provide appropriate concrete expansion anchor & structural steel ecceptance or literia BROWNLEE, V L., BANDERS, W F., JACKEON, L H. Region 2, Office of Director 83/10/11 36pp. 22576 232 24X Fiche 50-424,84/01/31,8403080372
- B40307001B Forwards IE Insp Repts 50-424/83-23 & 50-425/83-23 on B31111-840116 No violations or deviations noted. DANCE.H.C Division of Project & Resident Programs B4/02/10 KELLY.R.J Georgia Power Co. 2pp 22547.327. 24X Fiche 50-424,84/02/10,840307001B.
- --8403070024 IE Insp Repts 50-424/83-23 & 50-425/83-23 on 83illl-840il6
 No violations or deviations noted Major areas Inspected
 installation of electrical cabinets, reactor vessel closure
 head cladding repeir.weld metl control & reber & forme
 8ANDERS, W.F. Region 2, Office of Director PANGIERA, V Division
 of Project & Resident Programs 84/02/09 App 22547 328 24X
 Fiche. 50-424, 84/02/10, 8403070018
- 8403160207 Forwards IE Insp Repts 50-424/84-02 & 50-425/84-02 on 840130-0203 No violations or deviations identified DANCE: H C Division of Project & Resident Programs 84/02/23 XELLY,R.J Georgia Power Co. Zpp 22655,221 24X Fiche: 50-424,84/02/23,8403160207.
- --8403160212 IE Insp Repts 50-424/84-02 & 50-425/84-02 on B40130-0203 No violations or devietions identified Major areas inspected electrical cable instellation, cable termination, 0A procedures, insulation resistance testing & training MERRIMEATHER, N. CONLON.T E Region 2. Office of Director 84/02/21, 8pp. 22655, 223, 24% Fichs 50-424,84/02/23,8403160207
- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl.

 JURDAN, E. L. Division of Emergancy Preparedness & Engineering Response (Post B30103) B4/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22709 239, 24X Fiche 50-000, 84/02/28, 8401190072

- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22592 329 24X Fiche 50-000.84/03/02.8402090007
- B40209000B IE Info Notice B4-16. "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Evc list encl
 JORDAN.EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 117pp 22553 217 24X Fiche 50-000.84/03/02,84020790007
- 8402090011 IE Info Notice 84-17. "Problems H/Liquid Nitrogen Cooling Components Below N11 Ductility Temp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05.8402040011
- B402090024 1E Info Notice B4-09.Rev 1, "Lessons Leerned From Insps of Fire Protection Safe Shutdown Sys " Syc list encl JORDAN; E L Division of Emergency Preparadness & Engineering Response (Post B30103) B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07,8402090024
- B402090028 IE Info Notice 84-18, "Stress Corrosion Cracking In PWR
 Bys " Svc list encl
 JORDAN,E L. Division of Emergency Proparedness & Engineering
 Response (Post 830103) B4/03/07 Consolidated Edison Co. of New
 York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- B402090031 IE Bulletin B4-02. "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement B40403/12 Consolidated Edison Co of New York. Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403290037 Provides interim response to IE Bulletin B3-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " Matls supplied by primary suppliers listed Investigation of subtier suppliers in progress Final rept expected by 840624 FUSTER, D D Georgia Power Co 84/03/12 O'REILLY, J P Region 2, Office of Director 5pp 22806 232 24X Fiche 50-424, 84/03/12, 8403290037
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavitles " Svc list encl JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21,8402090047
- 8402090044 IE Info Notice 84-20, "Syc Life of Relays in Safety-Related Bys " 8vc list encl JORDAN,E L. Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- S Reportable occurrences. LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval.Inc DIRCK9.W J. Office of the Executive Director for Operations BECY-83-034, 84/01/25 4pp 22438 347 24X Fiche 50-000.84/01/25,
- B403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpel NPS-4 T&T valve to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BHR plants
 THEROUX, R R Terry Corp 84/02/22 WOODRUFF, R W Director's Office, Office of Inspection end Enforcement 6pp 22704 327 24X Fiche. 50-000, 84/02/22, 8403210032
- 8403010354 Interim deficiency rept re broken capstan spring tangs on Pacific-Ectientific shock arrestors Initially reported on 840126, Metallyrgicel analysis indicates cracking due to stress induced by spring forming Next rept by 840518 FOSTER, D.O. Georgia Power Co. 84/02/23 D'REILLY, J.P. Region 2, Office of Director 2pp 22433 003 24X Fiche 50-424,84/02/23,8403010354

- 8403090097 Final deficiency rept re Pullman Const Industries undersized shop filet wolds on corner details of stiffener angles for HVAC ducts Condition not reportable per IOCFR30 55(e) or IOCFR21 FUSTER. D G Georgia Power Co 84/02/24 G'REILLY, J P Region 2, Uffice of Director 1p 22576 004 24% Fiche 50-424,84/02/24, 8403090097
- 8403010207 Forwards 'Investigation of Types AF & AE Piston Skirts." per Transamerica Delaval. Inc Ouners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Guif Nuclear Power Stations MUSELER.W.J. TDI (Transamerica Delaval, Inc.) Owners Group 84/02/27 DENTON: HR Office of Nuclear Reactor Regulation. Director 3pp 22434 090 24% Fiche 50-000.64/02/27.6403010207
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Deiaval, Inc emergency diesel generators MUSELER.W J TDI (Transamerica Deiaval, Inc.) Domers Group 84/02/28 DENTON.H R Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Fiche 50-000,84/02/28,8403010218
- 8403260233 Forwards summary list of deficiencies identified per iOCFR50 55(e) Part 21 & potential generic ltr repts for comments
- comments
 STAROSTECKI.R Division of Project & Resident Programs 84/02/28
 Region 1. Office of Director 7pp 22756 065 24X
 Fiche 50-000.84/02/28.8403260233
- 8403:20:46 Interim deficiency rept re HVAC duct support weld defects found during reinsp program Initially reported on 84013: Add1 investigation underway Interim rept will be submitted by 8409:0
 FOSTER.D O Georgia Power Co 84/03/02 O'REILLY.J P Region 2. Office of Director 2pp 22585 252 24X Fiche 50-424.84/03/02.
- 840314004B Forwards "Orand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval, Inc Diesei Generators Unners Group Program Plan," to resoive concerns w/emergency diesel generators MUSELER.W J Long Island Lighting Co 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 22626 062 24X Fiche 50-000,84/03/02.8403140048
- 8403i50043 Interim deficiency rept re cracks in containment penetration welds initially reported on 840209 All welds repaired per ASHE Code-Section III. Subsection NC FOSTER. D 0 Georgia Power Co 84/03/07 0'REILLY, J P Region 2, Office of Director 4pp 2264i 010 24x Fiche 50-424,84/03/07, 8403130043
- 8403150069 Final deficiency rept re unverified computer code in design of main feedwater pipe supports Review & evaluation complete Event not reportable per 10CFR50 35(e) & Part 21 Unverified valve computer subroutine replaced by Bechtel FOSTER.D O Georgia Power Co 84/03/07 O'REILLY.J P Region 2, Office of Director ip 22643 182 24% Fiche 50-424,84/03/07,8403150069
- 8403190103 Deficiency rept re Pullman Power Products febrication shop spool piece welds Initially reported on 831021 Spools containing reported defects reworked or repaired & presently in acceptable condition FOSTER.D O Georgia Power Co 84/03/09 O'REILLY, J.P. Region 2. Office of Director 7pp 22669 312 24X Fiche 50-424,84/03/09,8403190105
- 8402090039 Board Notification 84-032 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval. Inc (TDI) Dwners Group Distribution list enc: EISENHUT. D C Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fiche 50-000, 84/03/12, 8402090039
- --8403060336 Forwards summary of B40210 meeting w/Transamerica Delaval.
 Inc Owners Group in Bethesda. HD re problems w/emergency
 dissel generators
 GARUSD.R Licensing Branch 2 84/02/27 D'REILLY, J P NRC No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000, 84/03/12, 8402090039
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, HD re problems w/emergency diesel generators NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fiche 50-000.84/03/12.8402090039

- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners
 Group in Wading River,NY re program plan to establish
 reliability of dissel generators Agenda, meeting transcript &
 attendance list encl
 HILLER,M A Licensing Branch 4 84/02/27 Licensing Branch 4
 8pp 22708 161 24% Fiche 50-000,84/03/12,8402070037
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval. Inc dissel generators Pp 1-82, * Commissioners 84/02/16 84pp 22708 169 24x Fiche 50-000.84/03/12,8402090039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shalls for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators
 HUBELER, H. J. Long Island Lighting Co. 84/03/12 DENTON, H.R. Office of Nuclear Reactor Ragulation: Director 2pp 22632 074 24% Fiche 50-000, 84/03/12, 8403140050
- 8403i50133 Forwards "Transamerica Deleval, Inc Diesal Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & syc conditions MUSELER, W J TD1 (Transamerica Delaval, Inc.) Owners Group, 84/03/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22639,270 24X Fiche 50-000,84/03/13,8403i50133
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series angines List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started enci

 MATHEWS, C S Transamerica Delaval, Inc. 84/03/16. EIBENHUT, D Q Division of Licensing 20pp 22691 179, 24x Ficha 50-000,84/03/16,8403200222
- B403270217 Part 21 rept re broken contact carriar in control device of 7 5 kV-15 kV.300-750 MVA:5 kV.350-3.000 & all HKV circuit breaters Initially reported on B30223. Addenda to installation & maint procedures sent to affected units DUVALL, D Brown Boveri Corp (subs qf Brown Boveri & Co., Ltd.). B4/03/17 Record Services Branch (Document Control Desk). 5pp 22772 ii4 24% Fiche: 50-000, 84/03/19, 8403270217.
- B403270132 Forwards "Emergency Diesel Generator Air Start Valve Captures Dimension & Stress Analysis," prepared by B&H for Transamerica Delaval, Inc (TDI) Diesel Generator Guners Group MUSELER, M J TDI (Transamerica Delaval, Inc) Owners Group B4/03/23 DENTON, H R Office of Nuclear Reactor Ragulation, Director 2pp 22774, 001 24X Fiche, 50-000, 84/03/23, 8403270132,
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamarica Delaval diesel generators List of suggested meeting topics and MCOAUGHY, J P TDI (Transamerica Delaval, Inc.) Owners Group, 84/03/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pp 22769 i33 24X Fiche 50-000,84/03/23,8403270134
- T Hearing transcripts on non-antitrust matters
- 8402070037 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Duners Group Distribution list encl EIBENHUT, D.G. Division of Licensing 84/03/12 FALLADINO Commissioners 5pp 22708 001 24X Fiche, 50-000, 84/03/12, 8402070037
- --8403060536 Forwards summary of 840210 meeting w/Transamarica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators
 GARUSD, R Licensing Branch 2 84/02/27 O'REILLY, J P. NRC No Detailed Affiliation Given 6pp 22708 006. 24X
 Fiche 50-000,84/03/12,8402090039
- --8403060534 Transcript of 840210 meeting w/Transamerica Delaval, Inc Guners Oroup in Bethesda, MD re problems w/emergency diesel generators = NRC - No Detailed Affiliation Given. 84/02/10. 147pp. 67201 008 24X Fiche, 50-000, 84/03/12, 8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delayal, Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list enci
 MILLER, M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Ficher 50-000,84/03/12,84020900039
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval, Inc diesel generators.Pp 1-82 * Commissioners 84/02/16 84pp 22708 169. 24X Fiche: 50-000,84/03/12,8402070039

V Operator Examinations

8403150038 Forwards operating shift experience tables for shift supervisors, senior reactor operators, reactor operator & shift technical advisor Licensed classroom training & exam conducted FOBYER, D O Georgia Power Co 84/03/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 14pp 22643 068 24X Fiche 50-424,84/03/09,8403150038

DOCKET 50-425 VOOTLE ELECTRIC GENERATING PLANT

A Application/construction stage documents & correspondence

- B4030503ii Notification of B40306-09 meetings w/utii in Haynesboro, QA to facilitate NRC review through site visits MILLER, MA Licensing Branch 4 B4/02/23 ADENBAM, E 0 Licensing Branch 4 Bp 2250i 272 24X Fiche 50-424, 84/02/23, 84030503ii
- 8403010319 Amend 4 to application for OLs, consisting of Amend 4 to FBAR
 FOBTER, D O Georgia Power Co 84/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22433 iii 24X
 Fiche, 50-424, 84/02/24, 8403010319

C Utility Environmental Report (ER), amends & correspondence

B403090189 Comments on soviron rept - DL stage, per Ofc of Environ Project Review Dec 1983 memo. Two unresolved aquatic issues should be addressed as special study conditions of OL MCSAY, L G Interior, Dept of, Fish & Wildlife Service 84/01/20 FARLEY, J O. Bouthern Co Bervices, Inc 3pp 22573, 304, 24X Fiche. 50-424, 84/01/20, 8403090189

Q Adjudicatory correspondence

- 8403020126 Response opposing applicant answer to patitions for leave to intervene & requests for hearing Request for hearings to be held in Atlanta. GA reiterated Certificate of Svc encl TEPER.D. C Georgians Against Nuclear Energy 84/02/24 Atomic 8afety and Licensing Board Panei 4pp 22442 147 24X Fiche. 30-424.84/02/24.84803020126
- 8403140114 Reiterates staff 840215 response to Campaign for Prosperous Georgia 840224 request that hearings be held in Atlanta. GA Site of hearings question does not need resolution at present BORDENICK, B M Hearing Branch 3 84/02/29 MARQULIES, M B . LINENSERGER. G , PARIB. G H Atomic 8afety and Licensing Board Panei 2pp 22623 357. 24X Fiche 50-424,84/02/29,8403140114
- 8403060090 Applicant response to Campaign for Prosperous Georgia (CPG) 840224 memorandum re location of hearing CPG has no reason for departing from NRC policy & ignores fact that project of moved from Atlants to site W/Centificate of Svc TRGWBRIDGE, 0, F Georgia Power Co TRGWBRIDGE, 0, F Georgia Power Co TRGWBRIDGE, 0, F Shaw, Pittman, Potts & Troubridge 84/03/01 8pp 22516.301 24X Fiche: 50-424,84/03/01,8403060090
- B403130457 Requests that hearings on OL application be held in State of QA to afford state officials & constituents opportunity to attend & monitor proceedings

 LOVETT, B. Georgia, State of B4/03/07 Office of the Secretary of the Commission ip. 22613 348 24X Fiche 50-424,84/03/07, B403130457
- B403130394 Memorandum & order scheduling B40530 special prehearing conference in Augusta, OA to identify key issues; to consider all intervention petitions & to establish schedule for further action MARQULIES, M B, LINENBERGER, O, PARIS, O H Atomic Bafety and Licensing Board Panel B4/03/09 10pp 22616; OB1 24X Fiche 50-424, 84/03/09, 8403130394,
- 8409230279 Requests that hearings be located in Wayneshoro, OA. PARRIERIS 9. Wayneshoro, OA DSB 078 84/03/19 Office of the Secretary of the Commission 1p. 82743 093 24x Fiche. 50-424, 84/03/19, 8403230279.

H. Owneral correspondence

B403150023 Advises of change to correspondence distribution adding JE Jainer & RE Conway deleting DE Dutton & changing addresses of DO Foster & RA Thomas, FOBTER, D. O., Georgia Power Co 84/03/08 ADENBAM, E 9 Licensing Branch 4 2pp. 22641 280 24X Fiche. 50-424, 84/03/08, 8403150023

X Utility Final Safety Analysis Report (FSAR) & amends

- 8403010319 Amend 4 to application for DLs, consisting of Amend 4 to FBAR FOSTER, D O Georgia Power Co 84/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22433 111 24X Fichs 50-424,84/02/24,8403010319
- --8403010325 Amend 4 to FSAR * Georgia Power Co 84/02/24 184pp 22433 113 24X Fichs 50-424,84/02/24,8403010319

@ Inspection reports, 1E Bulletins & correspondence

- 8403080370 Appeals denial of FDIA request for draft IE Insp Repts 50-424/83-13 & 50-425/83-13 BDMBY.A H Troutman, Sanders, Lockerman & Ashmore 83/11/14 Office of the Executive Director for Operations 2pp 22576 244 24X Fiche 50-425,83/11/14.8403080370
- 8403080372 Responds to appeal re denial of FOIA request for draft IE Insp Repts 50-424/83-13 & 50-423/83-13 Forwards documents FELYON, J M Division of Rules and Records 84/01/31 DOMBY, A H Troutman, Sanders, Lockerman & Ashmore 1p 22576 246 24X Fiche 50-424.84/01/31.8403080372
- --8403080377 Forwards IE Insp Repts 30-424/83-i3 & 50-425/83-i3 on 830621-0720 & notice of violation LEWIS.R C Division of Project & Resident Programs 83/10/14 KELLEV.R J Georgia Power Co 2pp 22376 247 24X Fiche 50-424,84/01/31,8403080372
- --8403080381 Notice of violation from inap on 830621-0720 * Region 2, Office of Director 83/10/14 3pp 22576 249 24X Fiche 30-424,64/01/31,8403080372
- --8403080384 IE Insp Repts 50-424/83-13 & 50-425/83-13 on 830621-0720 Violations noted failure to implement plpe support control documents & provide appropriate concrete expansion anchor & structural steel acceptance criteria BROWNLEE, V L , LIU, W , RUFF, A B Region 2, Office of Director 83/10/11 36pp 22576 252 24X Fiche 50-424,84/01/31,8403080372
- 8403070018 Forwards IE Insp Repts 50-424/83-23 & 50-425/83-23 on B31111-840116 No violations or deviations noted DANCE.H C Division of Project & Resident Programs 84/02/10 KELLY,R J Georgia Power Co 2pp 22547 327 24X Fichs 50-424,84/02/10.8403070018
- --8403070024 IE Insp Repts 50-424/83-23 & 90-425/83-23 on 831111-840116
 No violations or deviations noted Major areas inspected
 Installation of electrical cabinets: reactor vossel closure
 head cladding repair, weld math control & rebar & forms
 SANDERS, W F Region 2, Office of Director PANCIERA, V Division
 of Project & Resident Programs 84/02/09 4pp 22547 328 24X
 Fiche 50-424,84/02/10,8403070018
- 8403160207 Forwards IE Insp Repts 50-424/84-02 & 50-425/84-02 on B40130-0203 No violations or deviations identified DANCE, H C Division of Project & Resident Programs 84/02/23 KELLY, R J Georgia Power Co 2pp 22655 221 24X Fiche 50-424,84/02/23,8403160207
- --8403160212 IE insp Repts 50-424/84-02 & 50-425/84-02 on 840130-0203 No violations or deviations identified Major areas inspected electrical cable installation; cable termination GA procedures, insulation resistance testing & training MERRIMEATHER, v. CONLON, T E Region 2, Defice of Director 84/02/21 Bpp 22655 223 24X Fiche 50-424,84/02/23,8403160207
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000, 84/02/28, 8401190072
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list enc! GRACE, J N Division of OA, Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE info Notice 84-i4, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list enci
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co. of New
 York, Inc i22pp 22553 098 24X Fiche 50-000,84/03/02,8402090008

- 8402070007 IE Info Natice 84-15, "Reporting of Radiological Releases "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22533 217 24X Fiche 50-000.84/03/02,84020790007
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post B00103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8402090024 IE Into Notice 84-07, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 80103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 047 24X Fiche 50-000,84/03/07,8402070024
- B402090028 IE Info Notice 84-1B. "Stress Corrosion Cracking in PWR Sys " Svc list end: JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07.8402090028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8403270037 Provides interim response to IE Bulletin 83-07, "Apperently Fraudulent Products Sold by Ray Miller, Inc." Matis supplied by primary suppliers listed Investigation of subtler suppliers in progress Final rept expected by 840624 FOSTER, D.O. Georgia Power Co. 84/03/12 D'REILLY, J.P. Region 2. Office of Director 5pp. 22806 232 24X Fiche 50-424,84/03/12,8403270037
- 8402090043 IE Info Notice 84-19, "Two Events Involving Uneuthorized Entries into PMR Reactor Cavities " Svc 11st encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 820103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21,8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22933 001 24X Fiche 50-000.84/03/21.8402090044
- S Reportable occurrences, LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval, Inc DIRCKS.W J Office of the Executive Director for Operations 8ECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000.84/01/25, 8403010451
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPB-4 T&T valve to close Enci itr did 840203 sent to listed utils OE notified of affected units in BMR plants
 PHEROUX. R Terry Corp 84/02/22 HOODRUFF, R W Director's Office. Office of Inspection and Enforcement Opp 22700 327 24X Fiche 50-000.84/02/22.8403210032
- 8403010354 Interim deficiency rept re broken capstan spring tangs on Pacific-Scientific shock arrestors Initially reported on 840126 Metallurgical analysis indicates cracking due to stress induced by spring forming Next rept by 840518 FOSTER D O Georgia Power Co 84/02/23, 0'REILLY, J P Region 2. Office of Director 2pp 22433 003 24X Fichs 50-424.84/02/23, 8403010354
- 8403090097 Final deficiency rept re Pullman Const Industries undersized shop filet welds on corner details of stiffener angles for HVAC ducts Condition not reportable per iOCFR30 35(e) or iOCFR21 FOSTER, D O Georgia Power Co 84/02/24 O'REILLY, J P Region 2, Office of Director ip 22576 004 24X Fiche 50-424, 84/02/24, 8403090097
- B403010207 Forwards "Investigation of Types AF & AE Piston Bkirts," per Transamerica Delaval. Inc Owners Group program commitments Rept evaluates cracks in AF piston skirts in Shorehem & Grand Oulf Nuclear Power Stations.

 MUSELER.W J TDI (Transamerica Delaval. Inc.) Owners Group B4/02/27 DENION.M R Office of Nuclear Reactor Regulation, Director 3pp 22434 070 24% Ficha 50-000.84/02/27,8403010207

- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval. Inc emergency diesel generators MUBELER. W. J. TDI (Transamerica Delaval. Inc.) Owners Group 84/02/28 DENTON, H. R. Diffice of Nuclear Reactor Regulation, Director 42pg 22435 177 24X Ficha 50-000.84/02/28,8403010218
- 8403260233 Forwards summary list of deficiencies identified per 10CFR50 S5(e), Part 21 & potential generic 1tr repts for comments STAROSTECKI.R Division of Project & Resident Programs 84/02/28 Region 1. Office of Director 7pp 22756 065 24X Fiche 50-000,84/02/28,8403260233
- 8403120146 Interim deficiency rept re HVAC duct support weld defects found during reinsp program Initially reported on 840131 Add1 investigation underway Interim rept will be submitted by 840910 F09TER.D O Georgia Power Co 84/03/02 O'REILLY, J P Region 2, Office of Director 2pp 22585 252 24X Fiche 50-424,84/03/02, 8403120146
- 840314004B Forwards "Grand Gulf Component Tracking Bys," "Shoreham Component Tracking Bys" & "Transamerica Delavel, Inc Diesel Generators Dunars Group Program Plan:" to resolve concerns w/emergency diesel generators MUSELER, W.J. Long islend Lighting Co. 84/03/02, DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 22626 062 24X Fiche 50~000,84/03/02,840314004B
- 8403130043 Interim deficiency rept re crecks in containment penetration welds Initially reported on 840209 All welds repaired per ASME Code: Section III, Subsection NC FOSTER: D 0 Georgia Power Co 84/03/07 0'REILLY, J. P. Region 2, Office of Director 4pp 22441 010 24X Fiche 50-424, 84/03/07, 8403150043
- 8403130069 Final deficiency rept re unvarified computer code in design of main feedwater pipe supports Review & eveluation complete Event not reportable per 10EPR30, 35(e) & Part 21 Unverified valve computer subroutine replaced by Bechtel FOSTER, D D Georgia Power Co 84/03/07 D'REILLY, J P Region 2, Office of Director 1p 22643 182 24X Fiche 30-424, 84/03/07, 8403130069
- 8403190105 Deficiency rept re Pullman Power Products fabrication shop spool piece welds initially reported on 831021 Spools containing reported defects reworked or repaired & presently in acceptable condition FOSTER.D O Georgia Power Co 84/03/09 O'REILLY, J.P. Region 2, Office of Director 7pp 22669 312 24X Fiche 50-424,84/03/09,8400190105
- 8402070039 Board Notification 84-052 forwards meeting summeries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval. Inc (TDI) Owners Group, Distribution list enci
 EISENHUT, D 0 Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22708.001 24% Fiche 50-000.84/03/12, 8402070039
- --8403060536 Forwards summary of 840210 meeting w/Transamerice Delavel, Inc Guners Group in Bethesda, MD re problems w/emergency diesel generators CARUSO, R Licensing Branch 2 84/02/27 0'REILLY, J P NRC Np Detailed Affiliation Given 6pp 22708, 006 24X Fiche 50-000, 84/03/12, 8402090039
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesde, MD re problems w/emergency diesel generators * NRC - No Deteiled Affiliation Given 84/02/10 147pp 67201 008 24X Fiche 30-000,84/03/12,8402090039
- --8403070409 Summary of 840216 meeting b/Transamerica Delayal, Inc Owners Group in Mading River.NY re program plan to establish reliability of dissel gamerators Agenda, meeting transcript & attendance list encl
 MILLER.M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708, 161 24X Fiche, 50-000, 84/03/12, 8402090039.
- --8402070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval. Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708; 169 24X Fiche 50-000, 84/03/12, 8402090039

- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators
 MUSELER:M J Long Island Lighting Co 84/03/12 DENTON;H R
 Office of Nuclear Reactor Regulation, Director 2pp 22632 074
 ...Y Fiche 50-000,84/03/12,8403140050
- 8403130133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Arm Capacrew Btress Analysis Rept " Capacrew design adequate for applicable engines & svc conditions MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/13 DENTON: H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000,84/03/13,8403150133
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number model & svc number customer name & address rating, date shipped & date started encl.

 MATHEMS.C 8 Transamerica Delaval. Inc 84/03/16 EISENHUT, D @ Division of Licensing 20pp 2269: 179 24X Fiche 50-000,84/03/16,8403200222
- 8403270219 Part 21 rept re broken contact carrier in control device of 7.5 kV-15 kV,500-750 MVA,5 kV 350-3,000 & all HKV circuit breakers Initially reported on B30223 Addenda to installation & maint procedures sent to affected units DUVALL.D.D. Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772-114 24X Fiche 50-000.84/03/19,8403270219
- 8403270132 Forwards "Emergency Dissel Generator Air Btart Valva Capscrew Dimension & Stress Analysis," prepared by B&W for Transamerica Delaval, Inc (TDI) Diesel Generator Gwners Group.

 MUSELER, W.J. TDI (Transamerica Delaval, Inc.) Owners Group 84/03/23 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 22774 001, 24% Fichs 50-000,84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & longterm corrective actions & investigations re Transamerica Delaval diesel generators List of suggested meeting topics encl MCGAUGHY, J P TDI (Transamerica Delaval, Inc.) Owners Group
- MCGAUGHY.J P TDI (Transamerica Delaval, Inc.) Owners Group 84/03/23 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 22769 133 24X Fiche 50-000.84/03/23,8403270134

T. Hearing transcripts on non-antitrust matters

- 8402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval. Inc (TD1) Gwners Group Distribution list encl
 EISENHUT, D Q Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fiche 50-000,84/03/12,8402070039
- ---B403060536 Forwards summary of B40210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesei generators CARUSO, R Licensing Branch 2 84/02/27 D'REILLY, J P NRC No Detailed Affiliation Given 6pp 22708 006 24X Fiche 50-000, 84/03/12, 8402090039
- ---8403060554 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bathesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp. 67R01.008 24X Fiche 50-000,84/03/12,8402090039
- ---8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance liet encl.

 MILLER, M A Licensing Branch 4 84/02/27. Licensing Branch 4 8pp. 22708; idl 24% Fiche 30-000,84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delavai.Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708·169, 24X Fichs. 50-000,84/03/12,8402090039.

V. Operator Examinations

8403150038 Forwards operating shift experience tables for shift supervisors, senior reactor operators, reactor operator & shift technical advisor Licensed classroom training & examiconducted FOBTER, D. O. Georgia Power Co. 84/03/09 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 14pp 22643.068, 24X Fithe 50-424,84/03/09,8403150038

- DOCKET STN-50-437 FLOATING NUCLEAR PLANT
- G Inspection reports, IE Bulletins & correspondence
- 8401190072 lE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) B4/02/28 Consolidated Edison Co of New York, Inc 115pp 22790 237 24X Fiche 50-000.84/02/28,8401190072
- 8402090007 IE info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl ORACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-i6. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 2255 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"

 Bvc list encl

 JCRDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New

 York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02,8402090009
- 8402090011 IE lnfo Notice 84-17. "Problems H/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05,8402090011
- 8402090024 IE Info Notice 84-09.Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc iist encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Caneolidated Edison Co of New York, Inc 118pp 22695 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-i8, "Stress Corrosion Cracking in PWR 8ys " 8vc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 1:8pp 22584 i86 24X Fiche 50-000.84/03/07,84020
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class 1E Safety Sys " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8402090043 IE Info Notice B4-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JDRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21.8402090043
- B402090044 IE Info Notice 84-20, "Syc Life of Relays in Safety-Related Bys " Byc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21, Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8403160247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rev 7 to topical QA program.per 840302 telcon LEHIS.R C Region 2. Office of Director 84/03/08 PARRIS.H Q Tennessee Vailey Authority ip 22660 361 24X Fiche 50-000.84/03/08.8403160247
- B403160373 Notifies of use of ABME Nuclear Components Code Case N32-4 for hydrostatic testing of Class 3 embedded piping NRC position re use of Code Case N32-4 requested.

 MILLS, L. M Tennesse Valley Authority B4/03/12 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 22660 014 24X
 Fiche, 50-000, 84/03/12, 8403160373

- F Security, medical, emergency & fire protection plans
- 8403160345 Extends invitation to attend region 840316 workshop at regional ofc to discuss 10CFR30. App R requirements & recent results of insp to help resolve misunderstandings associated w/requirements

 LEMIS.R C Division of Project & Resident Programs 84/03/02

 PARRIB.H G Tennessee Valley Authority 2pp 22660 003 24X

 Fiche 50-000.84/03/02.8403160345

J Insurance & indemnity information

- 8403060413 Forwards Endorsement 23 to NELIA Policy NF-258 DUCK-J R Marsh & McLennan, Inc 84/02/28 SALTZMAN.J Assistant Director for State & Licensee Relations 2pp 22518 267 24X Fiche 50-438.84/02/28.8403060413
- O Inspection reports: IE Builetins & correspondence
- 8403070241 Suppls response to NRC ltr re violations noted in IE Insp Rapts 50-438/83-20 & 50-439/83-20 No actions by vendor necessary to prevent recurrence of abrasion of condensate pot piping MILLS.L M Tennessee Vailey Authority 83/12/05 O'REILLY.J P Region 2. Office of Director 2pp 22347 325 24X Fiche 50-438.83/12/05.8403070241
- 8403070066 Responds to NRC 811208 itr re violations noted in IE Insp Repts 50-438/81-29 & 50-439/81-29 Corrective actions repair plan for ietdown cooler supports revised Completion dates expected by 840601 for Unit 1 & 850131 for Unit 2 MILL9.L M Tennessee Valley Authority 83/12/07 D'REILLY.J P Region 2. Office of Director ip 22545 340 24X Fiche 50-439.83/12/07.8403070066
- 8403070089 Revises 831103 response to NRC 831005 itr re violations noted in IE insp Rept 30-438/83-23 Corrective actions craft GA training revised to include training for ironworkers on HVAC ductwork supports Training complete MILLS.L M Tennessee Valley Authority 83/12/13 G'REILLY, J P Region 2. Office of Director 2pp 22541 281 24X Fiche 50-438,83/12/13,8403070087
- 8403070218 Ack receipt of 840125 supplemental ltr informing NRC of steps taken to correct violations noted in IE lasp Repts 30-438/81-33 & 50-439/81-33 Concurs w/denial of violation VERRELLI.D M Division of Project & Resident Programs 84/02/23 PARRIS.H G Tennessee Valley Authority 1p 22541 296 24X Fiche 50-438,84/02/23,8403070218
- --8403070224 Submits second revised response to NRC 820126 itr re viniations noted in IE insp Repts 50-438/81-33 & 50-439/81-31 Violation re piping being cold sprung due to installation of sessmic supports densed MILLG.L M Tennessee Vality Authority 84/01/25 O'REILLY, J P Region 2, Office of Director 3pp 22541 297 24X Fiche 50-438,84/02/23,8403070218
- 840ii90072 IE info Notice 84-13, "Potential Deficiency in Motor Derated Valve Control Circuits & Annunciation " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830i03) B4/02/2B Consolidated Edison Co of Naw York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,840i190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J.N Division of GA, Bafeguards & Inspection Programs (Post 830103) 84003/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02.8402090007
- 8402090008 IE info Notice B4-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- B402090009 lE Info Notice B4-i5, "Reporting of Radiological Releases"
 Byc list anci
 URDANA EL Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/03/02 Consolidated Edison Co of New
 York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8403160140 Ack receipt of 831103 & 1213 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/63-23 & 50-439/83-23 Concurs w/denial of Factors 2 & 3 of Item B
 LEMIS.R C Division of Project & Resident Programs 84/03/02 PARRIS, N O Tennessee Valley Authority 2pp 22655 333 24X Fiche 50-438,84/03/02,8403160140

- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Gooling Components Below Nil Duttiity Temp " Svc list encl JORDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/03/05 Consolidate Edison Co of New York, Inc 117pp 22583 336 24X Fiche 50-000,84/03/05,8402090011
- 8402070024 IE Info Notice 84-07.Rev 1. "Lessons Learned From Insps of Fine Protection Bafe Shutdown 8ys " 8vc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Responss (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Fiche 50-000.84/03/07,8402070024
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Bys " Byc list enc! JORDANA E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fishe 50-000.84/03/07,840R090028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Bys " Svc list encl DEYQUNO,R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche, 50-000, 84/03/12, 8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Invoiving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823,229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE info Notice 84-20, "Svc Life of Releys in Bafety-Related Bys " Svc list enc! JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- S Reportable occurrences. LERs & related correspondence
- 8403010376 Final deficiency rept re welds on assemblies supplied by Transamerica Delaval & IIE Imperial not meeting QA requirements Initially reported on 830615 Condition not reportable per 10CFR50 55(e) MILLS.L M Tennesses Valiay Authority 84/02/22 O'REILLY.J P Region 2. Office of Director 2 pp 22434 057 24X Fiche 50-438.84/02/22,8403010376
- 8403010073 Third interim deficiency ropt ro manual adjustment of diesei generator setpoints Initially reported on 830309 Util will install automatic voltage regulator reset package Next rept will be submitted by 840824 MILLGIL M Tannessee Valley Authority 84/02/23 O'REILLY, J P Region 2, Office of Director 2pp 22435 361 24X Fiche 50-438.84/02/23.8403010099
- 8403010207 Forwards "Investigation of Tupes AF & AE Piston Skirts," per Transamerica Delavai, Inc Owners Group program commitments Rept evaluates craces in AF piston skirts in Shoreham & Grand Guif Nuclear Power Stations MUSELER, W J TDI (Transamerica Delaval, Inc) Owners Group 84/02/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22434 090 24X Fichs 50-000.84/02/27,8403010207
- 8403090163 First interim deficiency rept re carbon steel pipe supports top coated w/Carboline 305 paint in contact w/steinless steel piping Instructions issued to remove paint from surfaces where contact exceeds 140 F Next rept by 840822, MILLSIL M Tennessee Valley Authority 84/02/27 O'REILLY, J P Region 2, Office of Director 2pp 22575 133 24X Fiche 30-438,84/02/27,8403090163
- 8403070181 Tweifth interim deficiency rept re main steam line failure due to main feedwater overfill Initially reported on 800319. Field change package submitted by BWN Next rept by 840622. Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 84/02/27 G'REILLY, J P. Region 2, Office of Director. Spp 22573.272. 24X Fiche 50-438,84/02/27,8403090181
- 8403010218 Forwards tesk descriptions for 16 known problems re Transamerica Delaval, Inc emergency diesel generators MUSELER.W J TOI (Transamerica Delaval, Inc.) Duners Group 84/02/28 DENTON, H R. Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Ficha 50-000,84/02/28,8403010218.

- B403070024 Revised final deficiency rept re defective attachments of pipe supports to 6-inch strip plates Initially reported on B11231 Engineering Change Notico 1572 written to accomplish required mods
 MILLB.L M Tennessee Vailey Authority B4/02/2B O'REILLY, J P Region 2, Office of Director 2pp 22576 027 24X Fiche 30-438,84/02/2B,8403070024
- 8403070297 First interim deficiency rept re numerous deficiencies on E-max panels Initially reported on 840131 Incorrect connected wires will be repaired Next rept by 840607 Also reportable per Part 21 HILLS.L M Tennessee Valley Authority 84/02/29 ()'REILLY, J P Region 2, Office of Director 2pp 22546 357 24X Fiche 50-438.84/02/29.8403070297
- B403070329 First interim deficiency rept re adaptor keyway on 8-inch Borg-Marner globe valves Initially reported on 840131 Vendor will provide corrective action & identify addl valves requiring mods Also reportable per Part 21 MILLS,L M Tennessee Valiey Authority 84/02/29 0'REILLY,J P Region 2. Office of Director 2pp 22546 313 24X Fiche 50-438.84/02/29.8403070329
- B403070274 Socond interim deficiency rept re carbon steel dowel pin found in HPI pump Initially reported on B31107 Pin removed & wat cloth test performed to verify no residual rust remains Next rept expected by 840822 MILLS.L M Tennessee Valley Authority B4/03/01 O'REILLY.J P Region 2. Office of Director 2pp 22541 270 24X Fiche 50-438,84/03/01,8403070274
- 8403120105 First interim deficiency rept re loose drive hubs on overspeed governor drive shaft on Transamerica Delaval, inc dieseis Initiality reported on 840203 Svc info memo being reviewed for approvai Aiso reportable per Part 21 MILLS.L M Tennessee Vailey Authority 84/03/01 O'REILLY, J P Region 2. Office of Director 2pp 22585 227 24X Fiche 50-000.84/03/01.8403120105
- 8403i20i63 First interim deficiency rept re setting of shutdown voltage for vital inverters by inti Power Machines Initially reported on 840209 Corrective action requested from vondor Next rept by 840522 Also reported per Part 2i MILLB.L M Tennessee Vaiiey Authority 84/03/01 O'REILLY.J P Region 2, Office of Director 2pp 22589 207 24% Fiche 50-438,84/03/01,8403i20i63
- 8403140048 Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys," "Transamerica Delaval, Inc Diesei Generators Owners Group Program Plan," to resolve concerns w/emergency diesei generators MUSELER.W J Long Island Lighting Co 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 22626 062 24X Fiche, 50-000.84/03/02, 8403140048
- --8403i40075 "Transamerica Delavai, Inc Diesol Generators Guners Group Program Pian " * TDI (Transamerica Delavai, Inc) Owners Group 84/03/02 261pp 22628 223 24X Fiche 50-000,84/03/02,8403i40048
- B403i50057 Revised final Deficiency Rept NCR 2053 re cable bend radii for diesel generator control cabinets Initially reperted on B2i206 Buby not considered nonconforming condition Records amended deleting nonconformance as iOCFRSD 55(e) item MILLB.L II Tennesses Vailey Authority B4/03/05 O'REILLY, J P Region 2, Office of Director 2pp 22641 023 24X Fiche 50-438,84/03/05,8403150059
- 8403i60042 First interim deficiency rept re ITT Orlnnei pipe supports designed w/sway struts instead of required gaps Initially reported on 840108 Alternate analysis load tables will be revised Also reportable per Part 21 Next rept by 840828 MILLS,L M Tennesser Valley Authority 84/03/06 D'REILLY,J P Region 2, Office of Director 2pp 28655 126 24% Fiche.50-439,84/03/06,8403160042
- 8402070039 Board Notification 84-032 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delayal, Inc (TDI) Owners Group Distribution list encl EISENHUT.D G. Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Ficha. 50-000.84/03/12, 8402070039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Gumare Group in Bethesda.MD re problems w/emergency
 diesel generators
 CARUSO.R Licensing Branch 2 84/02/27 O'REJLLY, J P NRC No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000.84/03/12.8402090039

- --8403060594 franscript of 840210 meeting w/Transamerica Delaval.Inc Owners Group in Bethesda,MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Olven 84/02/10 147pp 67201 008 24X Fiche 50-000,84/03/12.8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delavai, Inc Owners
 Group in Wading River, NY re program plan to establish
 reiiability of diesel generators Agenda, meeting transcript &
 attendance list encl
 MILLER, M & Licensing Branch 4 B4/02/27 Licensing Branch 4
 Bpp 22708 161 24X Fiche 50-000.84/03/12,8402090039
- --8403070423 Transcript of 840215 conference in Wading River,NY re Transamerica Delaval,Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000,84/03/12.8402099039
- 8403i40090 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Quif diesel generators MUSELER, H J Long Island Lighting Co 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22632 074 24X Fishe 50-000,84/03/12,8403140050
- 8403i90297 Third interim Deficiency Rept NCR 2393 re Bingham-Willamette makeup/HPI pump vibration Initially reported on 830622 Next rept expected by 840723 ltem also reportable under Part 21 MILLS.L M Tennessee Valley Authority 84/03/i2 O'REILLY, J P Region 2. Office of Director 3pp 22672 275 24X Fiche 50-438,84/03/i2,8403i90287
- 8403150133 Forwards "Transamerica Deiavai, inc Diesei Generator Rocker Arm Capscrew Stress Anaiysis Rept " Capscrew design adequate for applicable engines & svc conditions MUSELER, H J TDI (Transamerica Deiaval, Inc.) Owners Group 84/03/13 DENTON. H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000, 84/03/13, 8403150133
- B4032i0046 First Interim deficiency rept re iTT Grinnei pipe supports designed w/sway struts Instead of required caps inItialiy reported on B402i6 Next rept by B502i3 Aisa reportable per Part 21
 MILLS.L M Tennessee Vailey Authorlty 84/03/13 O'REILLY.J P Region 3. Office of Director 2pp 22704 328 24X
 Fiche 50~438,84/03/13,84032i0046
- B4032i0042 First interim deficiency rept re incorrect insuiation weights for intake pumping station plping initially reported on 84022i Util will perform document insulation weight calculations for ERCW sys MILLS, L. K. Tennessee Valloy Authority 84/03/14 D'REILLY, J. P. Region 2, Office of Director 2pp 22707 037 24X Fiche 50-438,84/03/14,8403210042
- B403210132 First interim deficiency rept re defects in reactor pressure vessei (RPV) stud holes initially reported on B40216 for Unit I Maint inspirequirements revised to include vendor requirements for inspired to the bolt holes MILLS.L M Tennessee Valley Authority 84/03/14 D'REILLY, J P Region 2, Office of Director 2pp 22707 270 24X Fiche 50-438,84/03/14,8403210132
- 8403200222 Responds to 840214 Requests for info 1 & 2 re R-4 series angines List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started enci
 MATHEMS, C S Transamerica Delavai, inc 84/03/16 EiGENHUT, D 9
 Division of Licensing 20pp 22691 179 24X Fiche 30-000, 84/03/16.
 8403200222
- 8403300021 Suppiemental deficiency rept re Incorrect insulation wrights for intake pumping station piping Initially reported on 840221 First interim rept did 840314 inadvertently omitted fact that next rept would be submitted on 841130 MILLS.i. M Tennessee Valley Authority 84/03/21 O'REILLY, J P Region 2. Office of Director ip 22822 178 24X Fichs 30-438,84/03/21,8403300021
- 8403300039 Suppigmental deficiency rept re defects in reactor pressure vessel stud holes initially reported on 840216 for Unit i Next rept will be submitted by 840716 MILLS.L M Tennessee Valley Authority 84/03/21 O'REILLY.J P Region 2. Office of Director ip 22821 339 24x Fiche 50-438,84/03/21,8403300039
- 8403300004 Final deficiency rept re incorrect modeling of problems in TPIPE program Initially reported on 820801 Item not considered reportable under 10CFR30 55(e) Records amended to delete subj.nonconformance
 MILLG.L M Tennessee Valley Authority 84/03/22 O'REILLY, J P
 Region 2. Office of Director 2pp 22819 275 24X
 Fiche 50-438,84/03/22,8403300004

- 8403300054 Fifth interim deficiency rept re defects in raw cooling water chiller unit flow control valves afg by Metrex Valve Corp Initially reported on 82125 Investigation in progress Next rept by 850421 Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 84/03/22 O'REILLY.J P Region 2. Office of Director 2pp 22821 264 24X Fiche 50-439.84/03/22.8403300054
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve
 Capscrew Dimension & Stress Analysis." prepared by SkW for
 Transamerica Delaval. Inc (TDI) Diesel Generator Duners
 Group
 MUSELER. W. J. TDI (Transamerica Delaval. inc.) Guners Group
 84/03/23 DENTON.H R. Diesec of Nuclear Reactor Regulation.
 Director 2pp 22774 001 24% Fiche 50-000, 84/03/23, 8403270132
- 8403270134 Requests meeting on B40418 to discuss short-term & long-term corrective actions & investigations re Transamerica
 Delaval dless! generators List of suggested meeting topics
 enci
 MCGAUGHY, J P TD1 (Transamerica Delaval, Inc.) Owners Group
 84/03/23 DENTON.H R Office of Nuclear Reactor Regulation.
 Director 4pp 22769 133 24% Fishe 50-000.84/03/23,8403270134
- T Hearing transcripts on non-antitrust matters
- 8402090039 Board Notification 84-032 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval.inc (TDI) Owners Group Distribution list encl EISENHUT, D 0 Division of Licensing 84/03/12 PALLADIND Commissioners 5pp 22708 001 24X Fiche 50-000.84/03/12, RANDARDOGG
- --8403060536 Forwards summary of B40210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda.hD re problems w/emergency diesel generators
 CARUSO.R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000,84/03/12,8402090039
- --8403060554 Transcript of 840210 maeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/zmergency diesel generators • NRC - No Detailed Affillation Given 84/02/10 147pp 67203 OOB 84X Fiche 50-000.84/03/12.8402090039
- --8403070409 Summary of 840214 meeting w/Transamerica Delaval, Inc Duners Group in Wading River,NY to program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list enci MILLER,M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 50-000,84/03/12,8402090039
- ---8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delawal, Inc. diesel generators Pp. 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000, 84/03/12, 8402090039
- DOCKET 50-439 DELLEFONTE NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8403160247 Informs of 840327 meeting to discuss projoted responses to NRC questions on Rev 7 to topical GA program, per 840302 telcon
 LEWIS,R C Region 2. Office of Director 84/03/08 PARRIS,H G Tennessee Vailey Authority ip 22660 361, 24X Fiche 30-000:84/03/08.8403160247
- 8403i60373 Notifies of use of ASME Nuclear Components Code Case N32-4 for hydrostatic testing of Class 3 embedded piping ARC position re use of Code Case N32-4 requested.

 MIELCS,L M Tennessee Valley Authority 84/03/12 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 22660 014 24X Fiche 50-000.84/03/12,8403160373
- F Security, medical, emergency & fire protection plans

1

8403160345 Extends invitation to attend region 840316 workshop at regional off to discuss 10CFR50.App R requirements & recent results of insp to help resolve misunderstandings associated w/requirements

LEMIS.R C Division of Project & Resident Programs 84/03/02

PARRES.H G Tennessee Valley Authority 2pp 22660 083 24X

Fiche 30-000.84/03/02.8403160345

- O Inspection reports, IE Bulistins & correspondence
- 8403070241 Supple response to NRC itr re violations noted in IE Insp Repts 50-438/83-20 & 50-439/83-20 No actions by vendor necessary to prevent recurrence of abrasion of condensate pot pipling MILLS,L M Tennesses Vailey Authority 83/12/05 O'REILLY, J P Region 2. Office of Director 2pp 22547 325 24X Fiche 50-438,83/12/05.8403070241
- 8403070066 Responds to NRC 811208 itr re violations noted in 1E Insp Repts 50-438/81-29 & 50-439/81-29 Corrective actions repair plan for letdown cooler supports revised Completion dates expected by 840601 for Unit 1 & 850131 for Unit 2 MILLS,L M Tennessee Valley Authority 83/12/07 0'REILLY,J P Region 2, Office of Director 1p 22545 340 24X Fiche 50-438,83/12/07,8403070066
- 8403070218 Ack receipt of 840125 supplemental ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-439/81-33 & 50-439/81-33 Concurs w/denial of violation. VERRELL.1.D M Division of Project & Resident Programs 84/02/23 PARRIS.H 0 Tennessee Valley Authority. 1p 22541 276 24X Fiche 50-438,84/02/23,8403070218
- ---8403070224 Submits second revised response to NRC 820126 itr re violations noted in IE Insp Repts 50-439/81-33 & 50-439/81-31 Violation re piping being cold sprung due to installation of seismic supports denied MILLS.L M Tennesser Valley Authority 84/01/25 G'REILLY, J P Region 2. Office of Director 3pp 22841 297 24X Fiche 50-438,84/02/23,8403070218
- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunclation." Svc 1{st enci JURDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22709 239 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-i4. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list anc! GRACE. J N Division of GA. Safeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, inc 130pp 22552 329 24% Fische 50-000.84/03/02.8402090007.
- 8402090008 IE info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JOHDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24% Fiche 50-000,84/03/02,8402090008
- B402090009 IE info Notice 84-15, "Reporting of Radiological Releases"

 8vc list encl

 URDRAN, E. Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/03/02 Consolidated Edison Co of New

 York, Inc 119pp 22553 217 24X Fichs 50-000,84/03/02,8402090009
- 8402090011 FE info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fichs 50-000,84/03/05,8402090011
- 8402090024 IE info Notice 84-09, Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys "Svc list encl JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Bvc list ancl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 820103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584.186 24X Fiche.50-000.84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Svc list enc!
 DEYBUNGER C Director's Office, Diffice of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24X Fiche 50-000,84/03/12,8402070031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21. Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043

- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/2i,8402090044
- S Reportable occurrences, LERs & related correspondence
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transemerica Delaval, Inc Owners Group program commitments Rept eveluates cracks in AF piston skirts in Shoreham & Grand Oulf Nucleer Power Stations MUSELER,W J 7DI (Transamerica Delaval, Inc.) Owners Group 84/02/27 DENTON,H R Uffice of Nuclear Reactor Regulation, Director 3pp 22434 090 24% Fiche 50-000,84/02/27,8403010207
- B40301045i Informs Commission of problems w/smergency diesel generators mfg by Transemerice Delaval, Inc DIRCKS, W J Office of the Executive Director for Operations SECY-83-034 B4/01/25 4pp 2243B 347 24X Fiche 50-000,84/01/25. B40301045i
- B403010376 Final deficiency rept re welds on assemblies supplied by Transamerica Delavai & IIE Imperial not meeting GA requirements Initially reported on 830615 Condition not reportable per 100FR50 55(e) MILLSIL M Tennessee Valley Authority 84/02/22 O'REILLY, J P Region 2, Office of Director 2pp 22434 057 24X Fiche 50-438,84/02/22.8403010376
- 8403010075 Third interim deficiency rept re manual adjustment of diesel generator setpoints initially reported on 830307 Util will instell automatic Voltage reguletor reset package Next rept will be submitted by 840824 MILLS.L M Tennessee Valley Authority 84/02/23 O'REILLY.J P Region 2, Office of Director 2pp 22435 361 24X Fiche 50-438.84/02/23,8403010095
- 8403090163 First interim deficiency rept re cerbon steel pipe supports top coated w/Carboline 305 paint in contact w/stainless steel piping Instructions issued to remove paint from surfaces where contect exceeds 140 F Next rept by 840822 MILES.L M Tennessee Valley Authority 84/02/27 D'REILLY, J P Region 2, Office of Director 2pp 22575 133 24X Fiche.50-438.84/02/27.8403090163
- 8403090iBi Twelfth interim deficiency rept re main steam line failure due to main feedwater overfiil Initially reported on 800319 Field change package submitted by B&M Next rept by 840622 Also reportable per Part 21 MILLB.L.M. Tennessee Vailey Authority 84/02/27 D'REILLY, J.P. Region 2. Office of Director 3pp 22373 272. 24X Fiche: 50-438, 84/02/27, 8403090iBi
- B403010218 Forwards task descriptions for 16 known problems re Trensamerica Delavei, Inc emergency diesel generators MUSELER, M. J. TD1 (Transamerica Delavai, Inc.) Owners Group B4/02/28 DENTON, H.R. Office of Nucleer Reactor Regulation, Director 42pp 22435 177 24X Fiche 50-000,84/02/28,8403010218
- 8403090024 Revised final deficiency rept re defective attachments of pipe supports to 6-inch strip plates Initially reported on 811231 Engineering Change Notice 1572 written to accomplish required mods
 MILLERL M Tennessee Valley Authority 84/02/28 D'REILLY, J P Region 2, Office of Director 2pp 22576 029 24X
 Fiche 50-438.84/02/28.8403090024
- 8403070297 First interim deficiency rept re numerous deficiencies on E-max paneis, Initially reported on 840131 Incorrect connected wires will be repeired Next rept by 840607 Also reportable per Part 2!

 MILLS,L.M Tennessee Valiey Authority 84/02/29 D'REILLY, J P Region 2, Dffice of Director 2pp 22546 357, 24X
 Fiche: 50-438,84/02/29,8403070297
- 8403070329 First interim deficiency rept re adaptor keyway on 8-inch Borg-Werner globe valves Initially reported on 840131 Vendor will provide corrective action & identify add1 valves requiring mods, Also reportable per Part 21 MILLE, L.M. Tennessee Vailey Authority 84/02/29 O'REILLY, J.P. Region 2, Office of Director 2pp 22546 313 24X Fiche 50-438,84/02/29,8403070329
- 8403070294 Becond interim deficiency rept re carbon steel dowel pin found in HPI pump Initially reported on 831109. Pin removed & wet cloth test performed to verify no residual rust remains. Next rept expected by 840822

 MILLS.L M Tennessee Valley Authority 84/03/01 O'REILLY, J P Region 2, Office of Director 2pp 22541, 290 24X

 Fiche: 50-438, 84/03/01, 8403070294

- B403120105 First interim deficiency rept re ioose drive hubs on overspeed governor drive shaft on Transamerica Delaval.Inc diesels Intially reported on B40203 Svc info memo being reviewed for approval Also reportable per Part 21 MILLS.L M Tennessee Valley Authority B4/03/0i O'REILLY, J P Region 2. Office of Director 2pp 22985 229 24X Fiche 50-000.84/03/01.8403120105
- 8403140048 Forwards "Grand Gulf Component Tracking Sys," "Bhorsham Component Tracking Sys" & "Transamerica Delayai, Inc Dissel Generators Owners Group Program Plan," to resolve concerns w/emrgency diesel generators MUSELER.W J Long island Lighting Co 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22626 062 24X Fiche 50-000,84/03/02,8403140048
- --8403140095 "Transamerica Delavai, Inc Diesei Generators Owners Group Program Pian " * TDI (Transamerica Delavai, Inc.) Owners Group 84/03/02 261pp 22628 223 24% Fiche 50-000,84/03/02,8403140048
- B403150007 First interim deficiency rept re failure of dc isolation amplifiers in safety-related panels mfg by El-Teiresulting in erroneous control room indications on 125-volt dc sys Initially reported on B40214 Next rept by B40706 MILLS.L M Tennessee Vailey Authority B4/03/05 D'REILLY.J P Region 2. Office of Director 2pp 22643 295 24X Fiche 50-439.84/03/05.8403150007
- 8403160042 First interim deficiency rept re ITT Orinnel pipe supports designed W/sway struts instead of required gaps Initially reported on 840108 Alternate analysis load tables will be revised Also reportable per Part 21 Next rept by 840828 MILLGIL M Tennessee Valley Authority 84/03/06 O'REILLY, J P Region 2. Office of Director 2pp 22655 126 24X Fiche 50-438,84/03/06.8403160042
- 8402070039 Board Notification B4-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delayai, Inc (TDI) Owners Group Distribution list encl EISENHUT, D o Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fiche 50-000,84/03/12, 8402090039
- --B403060536 Forwards summary of B40210 meeting w/Transamerica Delavai.
 Inc Dwmers Group in Bethesda.MD re problems w/emergency
 diessi generators
 CARUSO.R Licensing Branch 2 84/02/27 G'REILLY.J P NRC No
 Detailed Affiliation Oiven 6pp 22708.Q06 24X
 Fiche 50-000.B4/03/12.B402070037
- --8403060554 Transcript of 8402iO meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators. * NRC ~ No Detailed Affiliation Given 84/02/iO 147pp 67201 008 24X Fiche 50~000,84/03/12,8408090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delayai.inc Owners
 Group in Wading River,NY re program plan to establish
 reliability of diesel generators Agenda,meeting transcript &
 attendance list enci
 MILLER,M A Licensing Branch 4 84/02/27 Licensing Blanch 4
 8pp 22708 i61 24X Fiche 50-000.84/03/12.8402090039
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc diesei generators Pp i-82 * Commissioners. 84/02/16 8pp 22708 169 24X Fichs 50-000, 84/03/12, 8402090039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delavai Enterprise Engines" for Shoreham & Grand Gulf dises! generators MUBELER.W J Long Island Lighting Co 84/03/12 DENTON, H R. Office of Nuclear Reactor Reguletion. Director 2pg 22632.074 24X Fiche 50-000.84/03/12.8403140050
- B403130133 Forwerds "Transamerica Delavel, Inc Diesel Generator Rocker Arm Cepscrew Stress Analysis Rept " Capscrew design adequete for applicable engines & svc conditions MUSELERN U J TDI (Transamerica Delaval, Inc.) Gwners Group B4/03/13 DENTON: H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000,84/03/13,8403150133
- 8403210046 First interim deficiency rept re IYT Grinnel pipe supports designed w/sway etruts instead of required caps Initially reported on 840216 Next rept by 850213 Aiso reportable per Part 21
 MILLS,L M Tennessee Valley Authority 84/03/13 O'REILLY,J P Region J. Office of Director 2pp 22704-328 24X
 Fiche 50-438,84/03/13.8403210046

- 8403210042 First interim deficiency rept re incorrect insulation weights for intake pumping station piping Initially reported on 840221 Vtil will perform document insulation weight calculations for ERCW sys MILLS.L M Tennessee Valley Authority 84/03/14 0'REILLY, J P Region 2. Defice of Director 2pp 22707 037 24X Fiche 50-438.84/03/14.8403210042
- 8403210132 First interim deficiency tept to defects in reactor pressure vessel (RPV) stud holes Initially reported on 840216 for Unit 1 Maint insp requirements revised to include vendor requirements for insp of RPV stud boit holes MILLS.L & Tennessee Valley Authority 84/03/14 0'REILLY.J P Region 2. Office of Director 2pp 22707 270 24X Fiche 50-438.84/03/14.8403210132
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number model & svc number, customer name & address rating date shipped & date started encl
 MATHEMS, C S Transamerica Delaval. Inc 84/03/16 EISENMUT, D Q Division of Licensing 20pp 22691 179 24X Fiche 50-000,84/03/16,8403200222
- 8403300021 Supplemental deficiency rept re incorrect insulation weights for intake pumping station piping Initially reported on 840221 First interim rept dtd 840314 inadvertently omitted fact that mext rept would be submitted on 841230 MILLS,L M Tennessee Vailey Authority 84/03/21 O'REILLY, J P Region 2. Office of Director ip 22822 178 24X Fiche 50-438.84/03/21.8403300021
- 8403300039 Supplemental deficiency rept re defects in reactor pressure vessel stud holes Initially reported on 840214 for Unit i Next rept will be submitted by 840714 HILLS.L H. Tennessee Valley Authority 84/03/21 O'REILLY.J P. Region 2. Office of Director ip 22821 339 24x Fiche 50-438.84/03/21,8403300039
- 8403300004 Final deficiency rept re incorrect modeling of problems in TPIPE program Initially reported on 830801 Item not considered reportable under 10CFR50 551s) Records amended to delate subj numconformance
 MILLS.L M Tennessee Valley Authority 84/03/22 O'REILLY, J P
 Region 2. Office of Director 2pp 22819 295 24X
 Fiche 50-438,84/03/22,8403300004
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve
 Capscrew Dimension & Stress Analysis." prepared by S&W for
 Transamerica Delaval.Inc (TDI) Diesel Generator Owners
 Group
 MUSELER.W J TDI (Transamerica Delaval, Inc.) Owners Group
 84/03/23 DENTON.H R Dffice of Nuclear Reactor Regulation,
 Director 2pp 22774 00(24% Fiche 50-000.84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delaval diesel generators List of suggested meeting topics encl

 MCOAUGHY.J P TD; (Transamerica Delaval, Inc.) Owners Group 84/03/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 4p 22769 133 24X Fiche 50-000.84/03/23.8403270134
- T Rearing transcripts on non-antitrust matters
- 8403060413 Forwards Endorsement 23 to NELTA Policy NF-258 DUCK,J R Marsh & McLennan, Inc 84/02/28 GALTZMAN,J Assistant Director for State & Licensee Relations 2pp 22518 269 24x Fiche 30-438.04/02/20,8403060413
- 8402070037 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delayal, Inc (TDI) Owners Group Distribution list encl
 EISENHUT, D Q Division of Licensing 84/03/12 PALLADIND Commissioners 5pp 22708 001 24X Fichs 50-000,84/03/12,8402070039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators

 CARUSO,R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No Detailed Affiliation Given 6pp. 22708 006 24X

 Fiche 50-000,84/03/12,8402070039
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval.inc Owners Group in Bethesda.HD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 00B 24X Fiche 50-000.84/03/12.8402070037

- --8403070409 Summary of 840216 meeting w/Transamerica Delaval. Inc Geners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl MILLER, M A. Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24% Fiche 30-000.84/03/12.8402090039
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000,84/03/12,8402090039
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8403070213 F01A request for documents re 830719 meeting to discuss steam erosion issue in facility proceeding & TM Novak 830825 memo on steam erosion issue HIATT.S L. Ohio Citizens for Responsible Energy 83/12/08 FELTON.J M Division of Rules and Records ip 22563 219 247 Fiche 50-440.83/12/08.8403070213
- 8403070215 Responds to FOIA request for documents re B30919 meeting to discuss steam erosion issue in facility proceeding & TM Novak B30825 memo on subj Forwards App A documents Documents 4 & 5 withheld (ref FOIA Exemption 3) FELTON.J M Division of Rules and Records 84/01/23 HIATT.S Ohio Citizens for Responsible Energy 3pp 22563 220 24X Fichs 50-440.84/01/23,8403070215
- --83062R0210 Forwards draft staff position on Contention 15 re steam erosion Applicant has not demonstrated capability to prevent or discover effects of steam erosion Comments requested PARR, D D Auxiliary Bystems Branch 83/06/14 LIAM, B Mechanical Enginepring Branch 1p 22563 226 24X Fiche 50-440,84/01/23,8403070215
- --8403070221 Requests confirmation on lead responsibilities for finalizing NRC position re steam erosion contention issue Responsibility should be shared by Mechanical Engineering Branch & Meteorology & Effluent Treatment Branch NVAK.T M Assistant Director for Licensing B3/08/25 KNIGHT.J P Assistant Director for Comp & Structures Engineering (Post B30201) JOHNSTON, W V Assistant Director for Matls, Chem & Environ Technology (Post B30201) 2pp 22563 224 24X Fichs 50-440.84/01/23,8403070215
- 8403010246 Notification of 840417 meeting w/util, BNL & Gilbert Assoc in Bethesds ND to discuss NRC preliminary findings re LCCA-related pool dynamic loads STEFANG, J J Licensing Branch 1 84/02/17 YOUNGBLOOD, B, J Licensing Branch 1 3pp 22449 359 24X Fiche 50-440,84/02/17, 8403010246
- B403020037 Notification of contract execution "Dresden & Perry Bimulator Leasing," awarded to GE JESBUP. B Technical Assistance Contracts Branch FIN B-8713 84/02/17 HAVINS, O H Director's Office, Office of Inspection and Enforcement 1p 22491 045 24X Fiche 50-000,84/02/17,8403020037
- --8403020043 Contract "Dresden & Perry Simulator Leasing," awarded to GE PIERCE,R L General Electric Co FIN 8-8713 84/02/17 38pp 22491 044 24X Fiche 50-000,84/02/17,8403020037
- 8403020435 Further response to FDIA request for documents re const assessment team visit to plant in Aug & Bept 1983 Forwards listed documents FELTON, J M Division of Rules and Records 84/02/22 HIATT, S. L. Ohio Citizens for Responsible Energy 1p 22491 203 24X Fiche 30-440,84/02/22,8403020435
- --B403020441 Submits outline re const assessment team visit Related info encl

 * NRC - No Detailed Affiliation Civen B3/09/27 ROHRBACHER, R Director's Office, Office of Inspection and Enforcement. 58pp 22491 204 24X Fiche 30-440,84/02/22,8403020435
- B403060181 Responds to Generic Ltr 84-01 re use of terms important to safety & safety-related Further discussion w/Util Classification Group & AIF Subcommittee on Bafety Glassification recommended EDELMAN, M.R. Cleveland Electric Illuminating Co. B4/02/29, TAYLOR, J. H. Director's Office, Office of Inspection and Enforcement 1p. 22518 251 24X Fiche 50-440, 84/02/29, 8403060181.

- 8403130092 Forwards responses to NRC 840214 itr re environ equipment qualification audit Response to exception taken by NRC in generic evaluation of Rev 1 to NEDE-24326-F will be submitted by 840423 EDELMAN, M R Cleveland Electric liluminating Co 84/03/07 YOUNDBLOBD, B J Licensing Branch 1 374pp 22602 225 24X Fiche 50-440,84/03/07,8403130092
- --8403130106 Rev O to "Sys Component Evaluation Worksheet for Class IE Equipment in Harsh Environ " GOSCH.C., THOMAS,E B. MATHENY,K A Cleveland Electric Illuminating Co CC-74-133 ROO 84/02/06 6pp 22603 192 24X Fiche 50-440,84/03/07,8403130092
- ---8403130118 Rev B to "Sys Component Evaluation Horksheet for Class IE Equipment in Harsh Environ" OBSCH.C., THOMAS, E B., MATHENY, K A. Cleveland Electric Illuminating Go. ES-1000 RB 84/02/06 6pp 22603 178 24X Fiche 50-440,84/03/07,8403130072
- --840313012B Rev A to "Bys Component Evaluation Worksheet for Class IE Equipment in Harsh Environ " QOBCH.C., THOMASI B B. MATHENY.K A Cleveland Electric Illuminating Co 100025 RA 84/02/06 20pp 22603 204 24X Fiche 30-440.84/03/07.8403130072
- --B40313013B Rev B to "Bys Component Evaluation Workshop for Class IE Equipment in Harsh Environ " QOSCH, C. THOMAB, E B , MATHENY, K A Cleveland Electric Illuminating Co 546-8654-2 RB B4/02/06 13pp 22603 224 24x Fiche 50-440,84/03/07.8403130092
- 8403190375 Informs that GA plan for operations phase, per Chapter 17 2 of FBAR.approved to expedite development of procedures & instructions during preoperational testing phase EDELMAN, MR Cleveland Electric Illuminating Co 84/03/08 KEPPLER.J G Region 3, Office of Director ip 22675 217 24X Fichs 30-440,84/03/08,8403190375
- 8403190391 Forwards tables reflecting nuclear power plant experience for operating shift positions, including current staffing experience levels & level projected at time of fuel load EDELMAN.M R Cleveland Electric Illuminating Co 84/03/09 DENTON.H R Office of Nuclear Reactor Regulation. Director 13pp 22675 282 24X Fiche 50-440.84/03/09.8403190391
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualiffications EIBENHUT,D 0 Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000.84/03/14.8402090041
- 8403230047 Advises that completion of final field wiring for diesel generator extended to 840515 EDELMANM R. Cleveland Electric Illuminating Co 84/03/15 KEPPLER.J G Region 3. Office of Director 1p 22728 350 24X Fichs. 50~440,84/03/15,8403230047
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8403010017 Forwards 85ER 4 (NUREO-0887) re operation of facilities W/o antl YOUNGBLOOD, B J Licensing Branch 1 84/02/17. EDELMAN, M P Clevaland Electric Illuminating Co 3pp 22479 341 24X Fiche. 50-440.84/02/17, 8403010017
- 8403270357 Requests add1 copies of proposed inservice testing program for pumps & valves submitted in response to SER Gutstanding Issue 5 Relief requests should be granted, pending completion of staff review YOUNGBLOOD, B J Licensing Branch i 84/03/14 EDELMAN, M R Cleveland Electric 111uminating Co 3pp 22822 263 24X Fiche; 50-440, 84/03/14, 8403270357
- F. Security, medical, emergency & fire protection plans
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical rabinets in control room EISENHUT, D G Division of Licensing 84/02/23 PALLADING Commissioners 1p 22576, 203 24X Fiche 50-000, 84/02/23, 8402090006.
- --B403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NRR Dfc Ltr 19, dtd 821001, Further evaluation of test data required, VOLLMER.R.H. Division of Engineering 84/02/06 EIBENHUT.D.O Division of Licensing 10pp 22576, 204 24% Fiche. 30-000, 84/02/23, 8402090006

- 8403070363 Forwards FEMA comments on Draft 2 of public info brochure, for review & consideration YOUNGBLOOD, B J Licensing Branch 1 84/02/29 EDELMAN, M R Cleveland Electric Illuminating Co 3pp 22567 205 24X Fiche 50-440.84/02/29,8403070363
- B403130194 Responds to NRC comments on detailed control room design review program plan.per 831223 itr Control room inventory requirements will be satisfied.per Suppl I to NUREG-0737 & Generic Ltr 83-16 during Apr 1984 task analysis review EDELMAN,M R Cieveland Electric Illuminating Co 84/02/29 YDUNGBLOOD, B J Licensing Branch 1 /pp 22617 300 24X Fiche 50-440.84/02/29,8403130194
- 8403030128 Forwards "Perry Nuclear Power Station Offsite Radiological Emergency Planning." Interim rept Exercise to test plans scheduled for 841128 KRIMM.R W Federal Emergency Management Agency 84/03/01 JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 1p 22488 223 24X Fiche 50-440.84/03/01.8403050128
- --8403050131 "Perry Nuclear Power Station Radiological Emergency Planning." interim rept * Federal Emergency Management Agency 84/01/10 192pp 22488 224 24X Fische 50-440.84/03/018403050128
- B403120112 Forwards agenda for B40323 regional workshop in Rosemont.1C w/all Region 111 licensees to discuss fire protection safe shutdown requirements of 10CFR50.App R Workshop will provide guidance to licensees

 SPEBSARD.R L. Division of Engineering 84/03/06 EDELMAN.M R Cleveland Electric Illuminating Co 3pp 22988 232 24X

 Fiche 50-440.84/03/06.8403120112
- G Adjudicatory correspondence
- 8403020106 Answer to Sunflower Alilance, inc 840214 motion to readmit Issue 2 re financial qualifications contention Motion should be denied based on 1982 financial qualifications rule Certificate of 8vc encl SILBERG. J E Cloveland Electric Illuminating Co SILBERG. J E Shaw, Pittman. Potts & Trowbridge 84/02/29 Atomic Safety and Licensing Board Panel 7pp 22442 101 24X Fiche 50-440.84/02/29, 8403020106
- 8403060275 Forwards supplemental answers to interrogatories on issues 6.8 & 15 W/o affidavits Related correspondence GLASSPIEGEL, H Shaw. Pittman. Potts y Trowbridge GLASSPIEGEL, H Claveland Electric 111 uminating Co 84/02/29 HIATT, S Ohio Citizens for Responsible Energy 2pp 22519 040 24x Fiche 50-440,84/02/29,8403060275
- --8403060280 Supplemental answers to interrogatories on Issues 6.8 & 15 Certificate of Svc encl Related correspondence OLASSPIEGEL,H Cleveland Electric Illuminating Co 84/02/29 24pp 22519 042 24X Fiche 50-440.84/02/29.8403060275
- B403060297 Forwards affidavits to accompany applicant supplemental answers to interrogatories on issues 6.8 & 15 Certificate of Svc encl Related correspondence GLASBF[CGEL.H Bhaw. Pittman. Potts & Trowbridge GLASSP[EGEL.H Cleveland Electric I] luminating Co 84/03/01 HIATT, 8 Ohio Citirons for Responsible Emergy 5pp 22516 255 24X Fiche 50-440.84/03/01.8403060257
- 8403140176 Response to Sunflower Ailiance 840214 motion to readmit Contention 2 re applicant financial qualifications ASLB should hold in abeyance motion until further guidance provided by NRC Certificate of 8vc enc1 MODDHEAD.C P Hearing Branch 4 84/03/05 Atomic 8afety and Licensing Board Panel 7pp 22624 104 24X Fiche 50-440,84/03/05.8403140176
- 8403130010 Answer to Ohio Citizens for Responsible Energy eleventh set of interrogatories to applicant re Issue io Certificate of Bvc encl Related correspondence BWIGER, M A Cleveland Electric lliuminating Co SWIGER, M A Shaw, Pittman, Potts & Troubridge 84/03/08 17pp 22614 327 24X Fiche 50-440,84/03/08,8403130010
- B403i30i39 interrogatories & request for production of documents to Ohio Citizens for Responsible Energy re reliability of Transamerica Deliavai standby diesel generators W/Certificate of Svc Related correspondence SHIGER: A Clawsiand Electric Illuminating Co SWIGER: A Shaw. Pittman, Potts & Trowbridge 84/03/09 Ohio Citizens for Responsible Energy 28pp 2260i 024 24X Fiche 50-440.84/03/09, 8403130139

- 8403130403 Updates applicant 840208 response to Dhio Citizens for Responsible Energy interrogatory 10-2 re consultants used on Issue 16 concerning reliability of standby diesel generators Related correspondence SHIGER. M A Shaw. Pittman. Potts & Trowbridge SHIGER, M A Cleveland Electric Illuminating Co. 84/03/09 HJATT. S L. Chio Citizens for Responsible Energy 3pp 22616 045 24% Fiche 50-440,84/03/09,8403130403
- 8403130007 Response to ABLB 830330 order for affidavit supporting contention that polymer degradation would not create unsafe conditions Electrical equipment in Zone DW-2 acceptable Related correspondence
 SWIGER, M.A. Cleveland Electric Illuminating Co. SWIGER, M.A. Bhaw, Pittman, Potts & Trowbridge 84/03/09 5pp. 22642 312 24X Fiche 50-440,84/03/09.08403150009
- --8403150014 Affidavit of 8 Kasturi in response to ASLB 830330 order re summary disposition of Issue 9 Certificate of Svc encl KASTURI.8 Impell Corp 84/03/08 9pp 22642 317 24X Fishe 3D-440, 84/03/09, 8403150009
- 8403i3000: Forwards original affidavit of EJ Christiansen to replace photocopy attached to applicant 840308 answers to Ohio Citizens for Responsible Energy eleventh set of interrogatories Related correspondence SHIGER.M A Shaw. Pittman. Potts & Trowbridge SHIGER.M A Cleveland Electric Illuminating Co 84/03/12 Office of the Secretary of the Commission 3pp 22641 291 24X Fiche 50-440.84/03/12,8403i50001
- B403190066 Forwards recent insp repts re facilities to ABLB & parties H00DHEAD: C P Hearing Branch 4 B4/03/14, BLOCH.P B , KLINE, J R , BRIGHT.C C Atomic Safety and Licensing Board Panel 97pp 22664 225 24X Fichs 50-440.84/03/14,8403190066
- 8403270075 Brief in support of exceptions to partial initial declaion rs GA issue Cartificate of Svc encl LODOE; Y J Sunflower Alliance DBs i07 84/03/20 Atomic Bafety and Literasing Appeal Panel 21pp 22766 224 24x Fiche 50-440.84/03/20,8403270075
- 8403300262 Order denying Ohio Citizens for Responsible Energy 831014 motion to reconsider summary disposition re turbine missile Served on 840330 BLOCH.PB, KLINE, JR, BRIGHT.0 D Atomic Safety and Licensing Board Panel DEB 226 84/03/29 Ohio Citizens for Responsible Energy 2pp 22824 014 24X Fiche 50-440,84/03/29,8403300262

H General correspondence

8403050350 Ack receipt of 840210 ltr re NRC actions on use of stiff pipe clamps IE lnfo Notice 83-80 issued identifying potential problem Evaluation of addl info will be documented in future SER STEFANO.J J Licensing Branch i 84/02/27 HIATT.S Ohio Citizens for Responsible Energy 3pp 22501 323 24x Fiche 50-440.84/02/27, 8403050350

M Antitrust correspondence

- 8403050174 Responds to Antitrust Div request for NRC imposition of civil penalties re alleged willful fallure to comply fully w/Antitrust License Condition 3 Commission believes imposition of civil penalties inappropriate PALLADINO.N J Commissioners 84/01/31 CUTLER,M S , MCGRATH, J P Justice, Dept of, Attorney General, Office of 2pp 22528 187 24X Fiche. 30-000,84/01/31,8403050194
- B403080140 Responds to City of Cleveland B40206 motion for clarification & correction of finding of Director of RRR reCL antitrust review NRR should reaffirm findings of no significant change & deny City of Cleveland motion.

 ZAMLER.R E Shaw, Pittman, Potts & Trowbridge ZAMLER.R.E Cleveland Electric Illuminating Co B4/03/06 DENTON, HR Office of Nuclear Reactor Regulation, Director 42pp. 22559 327, 24X Fiche 50-440,84/03/06,8403080140

@ Inspection reports, IE Bulletins & correspondence

- B401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunclation " Svc list encl JGRDAN, Et. Division of Emergency Preparedness & Engineering Response (Post B30103). 84/02/28 Consolidated Edison Co of New York, Inc. 115pp. 22709 239 24% Fiche 50-000,64/02/28,8401170072
- 3403190348 Forwards IE lnsp Repts 50-440/84-01 & 50-441/84-01 on 840130-0203 No noncompliance noted LITTLE.W 8 Region 3. Office of Director. 84/02/28 EDELMAN,M R Cleveland Electric Illuminating Co 2pp 22673,286 24X Ficke: 50-440,84/02/28,8403190348

- --8403190354 IE Insp Repts 50~440/84-01 & 50~441/84-01 on 840130-0203 No noncompliance or deviations noted Major areas inspected procedures,work activities & quality records review for safety-related piping CILIMBERO,R L . KAUFMAN.P D . DANIELBON,D H . Region 3, Diffice.of Director 84/02/27 7pp 22673 288 24% Fiche 50~440,84/02/28, 8403190348
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000:84/03/02,8402090007
- 8402090008 IE Info Notice 84~16. "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50~000.84/03/02,8402090008
- 8402070007 IE Info Notice 84~15. "Reporting of Radiological Releases "
 Svc list encl
 JDRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of Naw
 York, Inc 117pp 22553 217 24X Fiche 50-000,84/03/02,8402070007.
- 8402090011 IE lnfo Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductifity Temp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05. Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403120122 Ack receipt of 840224 ltr Informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-440/83-37 & 50-44/83-35 LITTLE: N B Region 3, Office of Director 84/03/06 EDELMAN, N R Cleveland Electric Illuminating Co ip 22589 221, 24X Fiche, 35-440, 84/03/06, 8403120122
- --8403120126 Responds to NRC 840127 ltr re violations noted in IE lnsp Repts 50-440/83-37 & 50-441/83-35 Corrective actions training & reevaluation of candidate performed per LK Comstock Procedure 4 14 EDELMAN,M R Cleveland Electric Illuminating Co 84/02/24 LITTLE,W B Division of Engineering 7pp 22589 222 24X Fichs 50-440,84/03/06,8403120122
- 8402090024 IE info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Bys " Svc 11st encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co of New York, Inc. 118pp 22635 049 24% Fiche 50-000:84/03/07,8402070024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8403130204 Confirms 840410 meeting in Region III ofc in Glen Ellyn, IL to discuss SALP NDRELIUS, C E Division of Project & Resident Programs 84/03/09 EDELMAN, M R Cleveland Electric Illuminating Co ip 22417, 319 24X Fiche 50-440,84/03/09,8403130204
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG!R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24X Fiche 30-000:84/03/12:8402090031
- B403190066 Forwards recent insp repts re facilities to ABLB & parties HODDHEAD.C P. Hearing Branch 4 84/03/14 BLOCH.P.B . KLINE, J R . BRIGHT, O O Atomic Safety and Licensing Board Penel. 97pp 22664 225 24% Fichs 50-440.84/03/14,8403190066
- 8403270224 Responds to Suppls 1 & 2 to IE Bulletin 83-07 re apparently fraudulent Ray Miller, Inc products Initial contact w/vendors indicates one application of product in nonsefety-related sys Completion of investigation expected by Dec 1984 EDELMAN.M R Cleveland Electric Illuminating Co. 84/03/16 KEPPLER.J.O. Region 3, Office of Director 1p 22772.085 24X Fiche: 50-440,84/03/16,8403270224.
- 8402090043 IE lnfo Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidate Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043

- 8402090044 IE Info Notice 84-20, "Svc Life of Releys in Safety-Related Sys "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating raports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite smergency plenning issues
 DIRCKB, W J Defics of the Executive Director for Operations
 84/02/21 PALLADINO Commissioners 9pp 22492 083 24X
 Fiche 50-000,84/02/21,8403020443
- 8 Reportable occurrences, LERs & related correspondence
- B403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval, Inc DIRCKS, W J Office of the Executive Director for Operations SECY-82-034 B4/01/25 4pp 22438 347 24X Fiche 50-000,84/01/25,8403010451.
- 8402290274 Interim deficiency rept re looso flexible coupling drive hubs on components supplied by Transamerica Delaval.Inc Initially reported on B40120 Next rept by B40331 Also reported per Part 21 EDELMAN.M R Cleveland Electric Illuminating Co. B4/02/17 KEPPLER.J & Region S. Office of Director 2pp 22426 299 24X Fiche: 50-440.84/02/17.8402290274
- 8403010207 Forwards "Investigation of Typss AF & AE Piston Skirts," per Transamerica Delavel. Inc Owners Group program commitments Rept evaluates cracks in AF piston skirts in Shorshem & Grand Gulf Nuclear Power Stations. MUSELER,W J TDI (Transamsrica Delaval, Inc.) Owners Group 84/02/27 DENTON,H R Office of Nuclear Reactor Regulation. Director 3pp 22434:090 24X Fiche 30-000,84/02/27,8403010207
- 8402090021 Board Notification 84-039 discusses NRC 840210 & 16 meetings w/Trensamerica Delaval, Inc Emergency Diesel Generators Duners Group Heeting scheduled on 840308 for finalization of general progrem plan prior to NRC review EISENHUT, D 0 Division of Licensing 84/02/28 PALLADING Commissioners 5pp. 22546 003 24X Fiche 50~000,84/02/28, 8402090021
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Deleval, Inc emergency diesel generators MUSELER, W J TDI (Transamerica Deleval, Inc.) Owners Group 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 42pp. 22495 177. E4X Fiche 50-000,84/02/28,8403010218
- 8403260233 Forwards summary list of deficiencies identified per 10CFR50 55(#), Part 21 & potential generic ltr repts for commants 8TAROSTECKI.R. Division of Project & Resident Progrems 84/02/28 Region I. Office of Director, 7pp. 22756 065 24X Fiche, 50-000, 84/02/28, 8403260233
- B402070020 Board Notification B4-044 forwards Part 2: rept re Transamerica Delaval. Inc turbocharger thrust bearing lubrication defect resulting in engine nonaveilability EIBENHUT, D @ Division of Licensing 84/02/29 PALLADING Commissioners 4pp 2254:, 269. 24X Fiche 50-000, 84/02/29, 8402090020
- 8403120076 Supplemental final deficiency rept re Bailey 720 station devices supplied by 0E in Power Generation control complex panels (RDC 32(81)) Due to repair delays, three stations not returned Corrective action will be completed by 840501 EDELMAN, M. R. Cleveland Electric Illuminating Go 84/03/01 KEPPLER, J. Q. Region 3, Office of Director ip 22588, 189 24X Fiche: 30-440, 84/03/01, 8403120076
- B403120052 Interim deficiency rept re cracks on actuator mounting brackets for motor operated exhaust louvers (RDC 93(84)). Initially reported on B40203. Nonconformance repts issued by M. C. C. Powers, Final rept will be submitted by B40427 EDELMANIM R. Cleveland Electric Illuminating Co 84/03/02 KEPPLER.J Q. Region 3. Office of Director 2pp 22586.279 24X Ficher 90-440, 84/03/02, 84/03120052
- B40314004B Forwards "Orand Oulf Component Tracking Sys," "Shoreham Component Tracking Bys" & "Trensamerica Delavel, Inc Diesel Cenerators Comers Group Progrem Plan:" to resolve concerns w/zmergency diesel generators.
 MUSELER:W J Long Island Lighting Co. B4/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 22626 062 24X Fishe 50-000, 84/03/02. B40314004B

- --B403140095 "Transamerica Delaval, Inc Diesel Generators Owners Group Program Plan " * TDI (Transamerica Delaval, Inc) Duners Group B4/03/02 261pp 2262B 223 24X Fichs 50-000.84/03/02.8403140048
- 8402090033 Board Notification B4-047 forwards Transamerica Dslavel, Inc Duners Group piston skirt rept & task descriptions EISENHUT.D 0 Division of Licensing 84/03/07 PALLADING Commissioners 4pp 22674 221 24X Fiche 50-000.84/03/07, 8402090033
- 8403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry DDD80N.J P Pacific Air Products Co 84/03/07 Director's Office, Office of Inspection and Enforcement 7pp 22624:068 24X Fiche 50-000.84/03/07.8403140122
- 8403170051 Interim deficiency rept re failure of linear converters on multi-blade dampers supplied by Pacific Air Products:Co utilized in safety-related HVAC sys Initially reported on 840216 Final rept by 840710 Also reported per Part 21 EDELMAN.M R Cleveland Electric Illuminating Co 84/03/07 KEPPLER:J G Region 3, Office of Director 2pp 22666 186 24% Fiche 90-440,84/03/09.8403190051
- B40207003B Board Notification 84-051 forwards "Transamerica Delaval.inc (TDI) Diesel Generators Quiners Group Program Flan "
 B18ENHUT.D O Division of Licensing 84/03/12 PALLADINO
 Commissioners 5pp 22688 214 24X Fishe 50-000, 84/03/12, 8407090038
- 8402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval.Inc (TDI) Owners Group Distribution list encl EISENNUT.D G Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fiche 50-000,84/03/12,
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Owners Group in Bethesda,MD to problems w/emergency
 diesel generators
 CARUSD,R Licensing Branch 2 84/02/27 O'REILLY,J P NRC No
 Detailed Affiliation Given 6pp 22708 006, 24X
 Fiche 30-000,84/03/12,8402090039
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bathesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/i0 147pp 67201 008. 24X Fiche 50-000,84/03/12.8402090039
- --8403070409 Summary of B40216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River,NY re program plan to establish reliability of diesel generators Agenda,meeting transcript & attendance list encl MILLER,M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 50-000.84/03/12.8402090039
- --B403070423 Transcript of B402i6 conference in Wading River, NY re Transamerica Deleval, Inc dissel generators Pp 1-82 * Commissioners. B4/02/16 B4pp 22708.167 24X Fiche 50-000,84/03/12,8402090039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delayal Enterprise Engines" for Shorehem & Orand Gulf diesel generators MUSELER, W J Long Island Lighting Co 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22832 074 24X Fiche 50-000,84/03/12,8403140050
- 8403:50133 Forwards "Transamerica Dejayal, Inc Diess) Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & syc conditions MUSELER, W J TDI (Transamerica Delayal, Inc.) Gwners Group 84/03/13 DENTON, H.R. Office of Nuclear Reactor Regulations Director 2pp 22639:270 24X Ficha 50~000,84/03/13,8403150133
- 8403200222 Responds to 840214 Requests for Info i & 2 re R-4 series engines List indicating engine number, model & svc number, customer name & address, rating, dats shipped & date started enci HATHEMB, C & Transamerica Delaval, Inc 84/03/16 & EISENHUT, D Q Division of Licensing 20pp 22691 179 24X Fiche: 50-000, 84/03/16, 8403200222

- 8403230011 Interim deficiency rept re synchronization between standby diesel generator & alternate preferred power source Initially reported on 840216 Evaluation of as-dasigned condition underway Nest rept by 840430 EDELMAN.M R Cleveland Electric Illuminating Co 84/03/16 KEPPLER, J C Region 3, Office of Director 2pg 22727 359 24X Fichs 50-440.84/03/16.8403230011
- 8403230045 Interim deficiency rept re design of diesel generator logic inconsistent w/FSAR Initially reported on E402i6 Gilbert Assoc. Inc investigating possible safety implications of identified discrepancies Next rept expected by 840430 EDELMAN.M R Cleveland Electric Illuminating Co 84/03/16 KEPPLERJ O Region 3. Defice of Director 2pp 22727 361 24% Fiche 50-440.84/03/16.8403230045
- 8403230083 Interim deficiency rept re defects in design of HPCS interfaces to suppression pool cleanup sys Ollbert Assoc. Inc evaluating as-designed condition & associated logic to determine if design change necessary Next rept by 840a30 EDELMAN, M R Cleveland Electric Illuminating Co 84/03/i6 KEPPLER Region 3. Office of Director 2pp 22724 291 24% Fiche 50-440.84/03/16,8403230083
- 8403230101 Interim deficiency rept re design of valve coordination for HPCS sys initially reported on 840216 AE currently investigating as-designed condition of valves & associated logic Next rept expected by 840430 EDELMAN, M R Cleveland Electric Illuminating Co 84/03/16 KEPPLER J O Region 3, Office of Director 2pp 22726 341 24X Fiche 50-440-84/03/16.88032301010
- 8403260247 Final deficiency rept re lack of power monitor downstream of fuses in MPCS safety-related control circuits Oilbert Associate evaluating as-designed condition of sys to make appropriate design changes Changes expected by 840501 EDELMAN.M R Cleveland Electric Illuminating Co 84/03/16 KEPPLERJ O Ragion 3. Office of Director 2pp 22756 063 24% Fiche 50-440-84/03/16.8403260247
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valvs Capstrew Dimension & Stress Analysis." prepared by S&W for Transamerica Detaval, Inc (TD1) Diesel Generator Owners Group MUSELER, J J TDI (Transamerica Delava), Inc) Dwners Group 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22774 001 24X Flohe 50-000, 84/03/23, 8403270332
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term correctly actions & investigations re Transamerica Delaval diesel generators List of suggested meeting topics encl MCGAUGHY, J P TDI (Transamerica Delaval, Inc.) Owners Group 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 22769 133 24% Fiche 50-000, 84/03/23, 8403270134

V Operator Examinations

8403190391 Forwards tables reflecting nuclear power plant experience for operating shift positions, including current staffing experience levels & level projected at time of fuel load EDELMAN, R Cleveland Electric Illuminating Co 84/03/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 13pp 22675 282 24X Fiche 50-440,84/03/07,8403170391

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8403070213 FOIA request for documents to 830919 meeting to discuss steam prosion issue in facility proceeding & TM Novak 830825 memo on steam prosion issue HIATT.8 L. Ohio Citizens for Responsible Energy 83/12/08 FELTON.J H Division of Rules and Records 1p 22563 219 24% Fichs 50-440.83/12/08,8403070213
- B403070215 Responds to FDIA request for documents ro 830919 mesting to discuss steam erosion lasue in facility proceeding & TM Novat 830825 memo on subj Forwarés App A documents Documents 4 & 5 withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 84/01/23, HIATT, 6 Ohio Citizens for Responsible Energy 3pp 22563 220 24X Fiche 50-440,84/01/23,8403070215

position on Contention 15 rs steam
Postrated capability to prevent
Prosion Comments requested
Pranch 83/05/14 LIAW, 8
P 22563-226 24X

- --840307022i Requests confirmation on lead responsibilities for finalizing NRC position re steam erosion contention issue Responsibility should be shared by Mechanical Enginesring Branch & Meteorology & Effluent Treatment Dranch NDVAKLT M Assistant Director for Licensing 83/08/25, MNIGHT.J P Assistant Director for Comp & Structures Enginearing (Post 830201) JOHNSTON.H V Assistant Director for Matts. Chem & Environ Technology (Post 830201) 2pp 22563 224 24X Fiche 50-440,84/01/23,8403070215
- 8403010246 Notification of 840417 meeting w/util.ENL & Gilbert Assoc in Bethssda.MD to discuss NRC preliminary findings re LOCA-related pool dynamic loads STEFAND, J J Licensing Branch i 84/02/17 YOUNOBLOOD.B J Licensing Branch | 3pp 22449 359 24X Fiche 50-440.84/02/17. 8403010246
- B403020037 Natification of contract execution "Dresden & Parry Simulator Leasing," awarded to GE
 JESSUP, B Technical Assistance Contracts Branch FIN B-8713
 84002/17 HAVING, O H Director's Office, Office of Inspection and Enforcement ip 22491 043 24X Fiche 50-000, 84/02/17, 8403020037
- --8403020043 Contract "Dresden & Perry Bimulator Leasing," awarded to GE PIERCE,R L. General Electric Co FIN 8-8713 84/02/17, 38pp 22491 046 24X Fiche 50~000.84/02/17,8403020037
- 8403020435 Further response to FOIA request for documents re const assessment team visit to plant in Aug & Sept 1983 Forwards listed documents FELTON, J H Division of Rules and Records 84/02/22 HIATT: B L Ohlo Citizens for Responsible Energy 1p 22491 203 24X Ficher 50-440.84/02/22, 8403020435
- --B403020441 Submits outline re const assessment teem visit Releted info enci * NRC - No Detailed Affiliation Oiven. 83/09/29 ROHRBACHER, R Director's Office, Office of Inspection and Enforcement 58pp 22491 204 24X Fiche 50-440,84/02/22.8403020435
- 8403050181 Responds to Generic Ltr 84-01 re use of terms important to safety & safety-related Further discussion w/Util Classification group & AIF Bubcommittee on Safety Classification recommended EDELMAN.MR Cleveland Electric Illuminating Co 84/02/29 TAYLOR, J M Director's Office, Office of Inspection and Enforcement 1p 22518 251 24x Fiche 50-440,84/02/29,8403060181
- 8403130092 Forwards responses to NRC 840214 ltr re environ equipment qualification audit Response to exception taken by NRC in generic evaluation of Rev I to NEDE-24326-P will be submitted by 840423 EDELMAN, M R Cleveland Electric Illuminating Co 84/Q3/07 YOUNOBLOOD, B J Licensing Branch i 374pp 22602 225 24X Fiche 50-440,84/03/07,8403130092
- --8403130106 Rev O to "Bys Component Evaluation Worksheet for Class IE Equipment In Harsh Environ" "

 ODSCH.C. THOMAS.E B. MATHENY, K.A. Claysland Electric Illuminating Co. CC-74-133 ROO. 84/02/06 6pp. 22603 192 24X Fiche 50-440,84/03/07,8403130092
- --8403130118 Rev B to "Bys Component Evaluation Workshest for Class 1E Equipment in Harsh Environ"

 OBSCH. C. THOMAS, E.B. MATHENY, K.A. Claveland Electric Illuminating Co. E8-1000 RB 84/02/06 6pp. 22603 178 24X Fiche 50-440,84/03/07,8403130092
- --8403130128 Rev A to "Bys Component Evaluation Worksheet for Class 1E Equipment in Harsh Environ" GOSCH. C. THOMAS. B. MATHENY.K A Claveland Electric Illuminating Co 108028 RA 84/02/06 20pp. 22603:204 24X Fichs 50-440.84/03/07.8403130092
- --8403130138 Rev B to "Bys Component Evaluation Workshop for Class IE Equipment in Harsh Environ" ODECH.C. THOMAS.E B . MATHENY.K A Clsveland Electric Illuminating Co 548-8854-2 RB 84/02/04 13pp 22603;224, 24X Fiche 50-440.84/03/07.8403130072
- 8403190375 Informs that GA plan for operations phase, per Chapter 17 2 of FBAR, epproved to expedits development of procedurss & instructions during preoperational testing phase. EDELMAN, MR Cleveland Electric Illuminating Co 84/03/08, KEPPLER, J. 9 Region 3, Office of Director. 1p. 22675:217 24X Fiche 50-440,84/03/08,8403190375

- 840319039: Forwards tables reflecting nuclear power plant experience for operating shift positions, including current staffing experience levels & level projected at time of fuel load EDELMAN, M R Cleveland Electric Illuminating Co 84/03/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 13pp 22675-282 24X Fiche 50-440,84/03/09,8403190391
- 840209004: Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D 0 Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000.84/03/14,8402090041
- 8403230047 Advises that completion of final field wiring for diesel generator extended to 840515
 EDELMAN.M R Cleveland Electric Illuminating Co 84/03/15
 KEPPLER.J O Region 3, Office of Director 1p 22728 350 24X
 Fiche: 50-440, 84/03/15, 8403230047
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8408080179 Fourth partial response to FDIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FDIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records, 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Darer 7pp 22583 226 24X Fiche 50-000,84/02/13.8403080179
- --8103040052 Forwards short & long-term OL & CP review schedules, in response to 801216 meeting w/UBOS List of DL plant reviews for which NRC tentatively plans to seek USOS assistance is provided.

 JACKBON, R E Geosciences Branch NRC-03-80-113 81/01/21 DEVINE, J F Interior, Dept of, Geological Burvey 5pp 22583, 272 24X Fiche 50-000, 84/02/13, 8403080179
- 8403010017 Forwards SBER 4 (NUREO-0887) re operation of facilities W/o snc1. YDUNGBLOOD, B J. Licensing Branch 1 84/02/17 EDELMAN, M P Cleveland Electric Illuminating Co 3pp 22479 341 24X Fichs, 50-440, 84/02/17, 8403010017
- 8403290337 Requests addl copies of proposed inservice testing program for pumps & velves submitted in response to SER Dutstanding Issue 3 Relief requests should be granted, pending completion of staff review YOUNOBLOOD, B J Licensing Branch i 84/03/14 EDELMAN, M R Clevelend Electric Illuminating Co 3pp 22822, 263 24X Fiche: 30-440, 84/03/14, 8403290337
- F Becurity, medical, emergency & fire protection plans
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in sheetrical cabinets in control room EISENHUT, D C Division of Licensing 84/02/23 PALLADING Commissioners ip 22576 203 24X Fiche 50-000,84/02/23,8402090006
- --B403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NRR Ofc Ltr 19, dtd 821001 Further evaluation of test data required VOLLMER: H Division of Engineering 84/02/06 EIBENHUT: D O Division of Litemaing 10pp. 22376 204 24% Fiche 50-000,84/02/23,8402090006
- 8403070363 Forwards FEMA comments on Draft R of public info brochure, for review & consideration.
 YOUNGELDDD, B J. Licensing Branch 1 84/02/29 EDELMAN, H. R. Claveland Electric Illuminating Co Fiche. 50-440, 84/02/29, 8403070363
- 8403130194 Responds to NRC comments on detailed control room design review program plan.per 831223 ltr Control room inventory requirements will be estisfied, per Suppl 1 to NUREO-0737 & Generic Ltr 83-18 during Apr 1984 task enalysis review EDELMAN.M.R. Claveland Electric Illuminating Co 84/02/29 YOUNOBLOOD.B.J. Licensing Branch 1 7pp 22617 300 24X Fiche: 50-440, 84/02/29, 8403130194
- 8403050128 Forwards "Perry Nuclear Power Station Offsite Radiological Emergency Planning." Interim rept Exercise to test plans scheduled for 84128. KRIMM,R.W. Federal Emergency Menagement Agency 84/03/01 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 1p 22488'223 24X Fiche 50-440.84/03/01.840305128

- --8403050131 "Perry Nuclear Power Station Radiological Emergency Planning," interim rept * Federal Emergency Management Agency 84/01/10 192pp 22488 224 24X Fiche 50-440,84/03/01.8403050128
- 8403120112 Forwards agenda for 840323 regional workshop in Rosemont.IL W/all Region III licensees to discuss fire protection safe shutdown requirements of lOCFR50.App R Workshop will provide guidance to licensees

 SPESSARD.R L Division of Engineering 84/03/06 EDELMAN.M R Cleveland Electric Illuminating Co 3pp 22588 232 24X Fiche 50-440.84/03/06.8403120112
- G Adjudicatory correspondence
- 8403020106 Answer to Sunflower Alliance, Inc 840214 motion to readmit Issue 2 ra financial qualifications contention Motion should be denied based on 1982 financial qualifications rule Certificate of Svc encl SILBERO, J E Cleveland Electric Illuminating Co SILBERO, J E Shaw, Pittman, Potts & Troubridge 84/02/29 Atomic Safety and Licensing Board Panel 7pp 22442 101 24X Fiche 30-440,84/02/29,8403020106
- 8403060275 Forwards supplemental answers to interrogatories on Issues 6.8 % 15 W/o affidavits Related correspondence OLASSPIEGEL, H Shaw, Pittman, Potts & Troubridge GLASSPIEGEL, H Cleveland Electric Illuminating Co 84/02/29 HIATT, S Ohio Citizens for Responsible Energy 2pp 22517 040 24X Fiche 50-440,84/02/29,8403060275
- --8403040280 Supplemental answers to interrogatories on Issues 6,8 & 15 Certificate of Svc encl Related correspondence GLASSPIEGEL,H Cleveland Electric Illuminating Co 84/02/29 24pp 22519 042 24X Fiche 30-440.84/02/29.8403060275
- 8403060257 Forwards affidavits to accompany applicant supplemental answers to interrogatories on Issues 6.8 & 15 Certificate of Svc encl Related correspondence GLASSPIEGEL, H Bhaw. Pittman. Potts & Trowbridge GLASSPIEGEL, H Cleveland Electric illuminating Co B4/03/01 HIATT. S Onio Citirens for Responsible Energy 5pp 22516 235 24X Fiche 50-440,84/03/01.8403060257
- 8403140176 Response to Sunflower Alliance 840214 motion to readmit Contention 2 re applicant financial qualifications ASLB should hold in absyance motion until further guidance provided by NRC Certificate of Svc encl HODDHEAD.C P Hearing Branch 4 84/03/05 Atomic Safety and Licensing Board Panel 7pp 22624 104 24X Fiche 50-440,84/03/05.8403140176
- 8403130010 Answer to Ohio Citizens for Responsible Energy eleventh set of interrogatories to applicant re Issue 16 Certificate of Byc encl Related correspondence SMIGER, M A Cleveland Electric Illuminating Co SMIGER, M A Shaw. Pittman. Patts & Trowbridge 84/03/08 17pp 22614 327 24X Fiche 50~440,84/03/08,8403130010
- 8403130137 Interrogatories & request for production of documents to Ohio Citizens for Responsible Energy re reliability of Transamerica Delaval standby diesel generators W/Certificate of Svc Related correspondence SWIOER, M A Cleveland Electric Illuminating Co SWIOER, M A Shaw, Pittman. Potts & Trombridge 84/03/09 Ohio Citizens for Responsible Energy 28pp 22601 024 24X Fiche 50-440.84/03/09, 8403130139
- 8403130403 Updates applicant 840208 response to Ohio Citizens for Responsible Energy Interrogatory 10-2 re consultants used on Issue 16 concerning reliability of standby diesel generators Related correspondence SWIGER, M A Shaw, Pittman, Potts & Troubridge SWIGER, M A Cleveland Electric Illuminating Co 84/03/09 HIATT, S L Qhio Citizens for Responsible Energy 3pp 22616 045 24X Fiche 50-440,84/03/09,8403130403
- 8403130007 Response to ASLB 830330 order for affidavit supporting contention that polymer degradation would not create unsafe conditions Electrical equipment in Zone DM-2 acceptable Related correspondence SMIGER.M.A Claveland Electric Illuminating Co SMIGER.M.A Shaw, Pittman. Potts & Trowbridge, 84/03/07 5pp 22642 312 24X Pitche: 50-440.84/03/09, 8403150009
- --B403130014 Affidavit of E Kasturi in response to ASLB 830330 order re summary disposition of Issue 9 Certificate of Syc encl KASTURI, E Impell Corp 84/03/08 9pp 22442 317 24X Fiche 50-440,84/03/09,8403150009

- 8403i5000i Forwards original affidavit of EJ Christiansen to replace photocopy attached to applicant 84030B answers to Chio Citizens for Responsible Energy eleventh set of interrogatories Related correspondence SHIGER.N A Shaw Pittman. Potts & Trowbridge Cleveland Electric Illuminating Co 84/03/12 SHIGER.N A Office of the Secretary of the Commission Spp 22641 271 24X
- B403190066 Forwards recent insp repts re facilities to ABLB & parties HOODHEAD,C P Hearing Branch 4 84/03/14 BLDCH,P B , KLINE,J R , BRIGHT,O O Atomic Bafety and Licensing Board Panel 97pp 22664 225 24x Fiche 30-440,84/03/14,8403190066
- 8403270075 Brief in support of exceptions to partial initial decision re QA issue Certificate of Svc encl LODGE,T J Sunflower Alliance DSB 107 B4/03/20 Atomic Safety and Licensing Appeal Panel 21pp 22766 224 24X Fiche 50-440.84/03/20,8403270075
- 8403300262 Order denying Ohio Citizens for Responsible Energy 831014 motion to reconsider summary disposition re turbine missile Served on 840330 BLOCK,P 8 . KLINE,J R . DRIGHT, O DATE of Panel . DEB 226 84/03/29 Ohio Citizens for Responsible Energy 2pp 22824 014 24X Fiche 50-440.84/03/27, B403300262

H General correspondence

8403050350 Ack receipt of 840210 ltr re NRC actions on use of stiff pipe clamps IE Info Notice 83-80 issued identifying potential problem Evaluation of add1 info will be documented in future SER STEFANOLU J Licensing Branch 1 84/02/27 HIATT,8 Ohio Citizens for Responsible Energy 3pp 22501 323 24X Fiche 50-440,84/02/27,8403050350

M Antitrust correspondence

- 8403030194 Responds to Antitrust Div request for NRC imposition of civil penalties re alleged willful failure to comply fully u/Antitrust License Condition 3 Commission believes imposition of civil penalties inappropriate PALLADIND, N J Commissioners 84/01/31 CUTLER, M B , MCGRATH, J P Justice, Dept af, Attorney General, Office of 2pp 22528 187 24X Fiche 50-000,84/01/31,8403050194
- 8403080140 Responds to City of Cleveland 840206 mation for clarification & correction of finding of Director of NRR reDL. antitrust review NRR should reaffirm findings of no significant change & deny City of Cleveland motion IAMLER.R E Shaw, Pittman, Potts & Trowbridge. ZAMLER.R E Cleveland Electric Illuminating Co 84/03/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 42pp. 22559 327 24X Fichs 50-440,84/03/06,8403080140

Q Inspection reports, IE Bulletins & correspondence

- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403190348 Forwards lE Insp Repts 50-440/84-01 & 50-441/84-01 on 840130-0203 No noncompliance noted LITTLE.W S Region 3. Office of Director 84/02/28 EDELHAN, M R Cleveland Electric Illuminating Co 2pp 22673 286 24X Fiche 50-440.84/02/28,8403190348
- --8403190354 IE Insp Repts 50-440/84-01 & 30-441/84-01 on 840130-0203 No noncompliance or deviations noted Major areas inspected procedures.work activities & quality records review for safety-related piping CILIMBERG, R. L. KAUFMAN, P. D. DANIELSON, D. H. Region 3, Office of Director 84/02/27, 7pp. 22673 288 24X Fiche 50-440,84/02/28,8403190348
- 8402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of GA: Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York: Inc 130pp 22532 329 24X Fiche 50-000,84/03/02,8402070007
- B402090008 IE Info Notice B4-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JDRDAN.E L Olivision of Emergancy Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008

- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 8vc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co. of New
 York, Inc. 119pp 22553 217 24X Fiche 30-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of Naw York. Inc 117pp 22553 336 24X Ficha 50-000.84/03/05.8402090011
- 8403120122 Ack receipt of 840224 ltr informing NRC of steps taken to correct honcompliance noted in IE Insp Repts 50-440/83-37 & 50-441/83-35 LITTLE.H S Region 3. Office of Director 84/03/06 EDELMAN,M R Cleveland Electric 11Jumineting Co ip 22589:221 24X Fiche 50-440.84/03/06.8403120122.
- --8403120126 Responds to NRC 840127 ltr re violations noted in IE Insp Repts 50-440/83-37 & 50-441/83-35 Corrective actions training & resvaluation of candidate performed per LK Comstock Procedure 4 14. EDELMAN.M R Cleveland Electric Illuminating Co 84/02/24, LITTLE.W S Division of Engineering 7pp 22589 222, 24X Fiche 50-440,84/03/06,8403120122.
- 8402070024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys" Svc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co. of New York. Inc. 118pp 22635 049 24X Fiche 30-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PHR Sys " Syc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403130204 Confirms 840410 meeting in Region III ofc in Glen Ellyn, It. to discuss SALP
 NORELIUS.C E Division of Project & Resident Programs 84/03/09
 EDELMAN.M R Cleveland Electric Illuminating Co ip 22617 319
 24X Fiche 50-440.84/03/09.8403130204
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl.

 DEYDUNG: R C Director's Office: Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co. of New York, Inc 134pp 22823 094 24% Fiche 50-000,84/03/12,8402090031
- 8403190066 Forwards recent insp repts Te facilities to ASLB & parties. HOUDHEAD, C P Hearing Branch 4 84/03/14 BLUCH.P B Atomic Safety and Licensing Board Panel 97pp 22664.225 24X Fithe 50-440,84/03/14.8403190066
- B403270224 Responds to Suppls 1 & 2 to 1E Bulletin 83-07 re apparently fraudulant Ray Miller. Inc products Initial contact w/vendors indicates one application of product in monsafety-related sys Completion of investigation expected by Dec 1984 EDELMAN.M R Cleveland Electric Illuminating Co. 84/03/16 KEPPLER, J C Region 3, Office of Director 1p 22772'085 24% Fiche 50-440.84/03/16,8403270224
- B402070043 IE Info Notice B4-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of Naw York, Inc 123pp 22823 227 24X Fiche, 50-000, 84/03/21, 8402070043,
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Bafety-Related Bys " Bvc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc 135pp. 22933 001 24% Fiche 50-000,84/03/21,8402090044.
- 8 Reportable occurrences. LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval, Inc.
 DIRCKS: W J Office of the Executive Director for Operations
 SECY-83-034 84/01/25 4pp 22438-347, R4X Fiche, 50-000, 84/01/25, 8403010451
- 8402290274 Interim deficiency rept re loose flexible coupling drive hubs on components supplied by Transamerica Delaval, Inc. Initially reported on 840120 Next rept by 840531. Also reported per Part 21
 EDELMAN.M R Cleveland Electric Illuminating Co 84/02/17
 KEPPLER.J O Region 3, Office of Director 2pp 22426:279, 24X Fiche 50-440.84/02/17.8402290274

- B403010207 Forwards "Investigation of Types AF & AE Piston Bkirts," per Transamerica Delaval, Inc Owners Group program commitments Rept avaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations MUBELER: # J TDI (Transamerica Delaval, Inc.) Guners Group B4/02/27 DENTON: HR Office of Nuclear Reactor Regulation, Director 3pp 22434 090 24X Fiche 50-000, 64/02/27, B403010207
- 8402070021 Board Notification 84-039 discusses NRC 840210 & 16 maetings W/Transamerica Delaval. Inc Emergency Diesel Generators

 Gunerus Group Meeting scheduled on 840208 for finalization of generic program plan prior to NRC review

 EIEENHUT.D 9 Division of Licensing 84/02/28 PALLADING

 Commissioners 5pp 22546 003 24X Fiche 50-000,84/02/28,8402090021
- B403D1021B Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc emergency diesel generators MUSELER,N J DIT (Transamerica Delaval, Inc) Owners Group, B4/02/28 DENTON, HR Office of Nuclear Reactor Regulation, Birector 42pp 22435 177 24X Fiche 50-000,84/02/28,8403010218
- 8403260233 Forwards summary list of deficiencies identified per IOCFR50, 55(e), Part 21 & potential generic ltr repts for comments.

 BTAROSTECKI,R. Division of Project & Resident Programs B4/02/28 Region I: Office of Director 7pp 22756 065 24X Fiche, 50-000, 84/02/28, 8403260233
- 8402070020 Board Notification 84-044 forwards Part 21 rept re Transamerica Delaval inc turbocharger thrust bearing lubrication defect resulting in engine nonavailability EIBENHUT, D 0 Division of Licensing, 84/02/29 PALLADIND Commissioners, 4pp 22541 263 24X Fiche 50-000,84/02/29, 8402070020.
- 8403120096 Supplemental final deficiency rept re Bailey 720 station devices supplied by GE in Power Generation control complex panels (RDC 32(81)) Due to repair delays, three stations not returned Corrective action will be completed by 840501 EDELMAN.M.R. Cleveland Electric Illuminating Co. 84/03/01 KEPPLER, J Q. Region 3, Office of Director ip 22588 189 24X Fichs 50-440,84/03/01,8403120096
- 8403120032 Interim deficiency rept re crecks on actuator mounting brackets for motor operated exhaust louvers (RDC 93(84)). Initially reported on 840203 Nonconformance repts issued by M C C. Powers Final rept will be submitted by 840427. EDELMAN.M.R. Clevelend Electric Illuminating Co 84/03/02 KEPPLER.J Q. Region 9, Office of Director 2pp 22586 277 24% Ficher 50-440,84/03/02,8403120052.
- 840314004B Forwards "Grand Oulf Component Tracking Bys." "Bhoreham Component Tracking Bys" & "Transamerica Delaval. Inc Diesel Generators Owners Oroup Program Plan." to resolve concerns w/emergency diesei generators MUSELER.W J Long Island Lighting Co 84/03/02 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22626 062 24X Fiche 50-000.84/03/02.8403140048
- --B403140075 "Transamerica Delaval, Inc Diesel Generators Dwners Group Program Plan " # TDI (Transamerica Delaval, Inc.) Owners Group 84/03/02 261pp 22628(223 24X Fiche 50-000,84/03/02,8403140048
- 8402070033 Board Notification 84-047 forwards Transamerica Delaval, Inc Owners Group piston skirt rept & task descriptions ETBENHUT, D. 9. Division of Licensing 84/03/07, PALLADING 'Gommissioners 4pp. 22674 221 24X Fiche, 50-000, 84/03/07, 8402070033
- B403140122 Part 21 rept re status update concerning abnormal wear on lignear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry DODBON, J.P. Pacific Air Products Co. 84/03/09 Director's Office, Office of Inspection and Enforcement 7pp 22624,068 24X Fiche: 50-000, 84/03/07, 8403140122.
- 8403190051 Interim deficiency rept re failure of linear converters on multi-blade dampers supplied by Pacific Air Products, Co utilized in safety-related HYAC sys Initially reported on 840216. Final rept by 840710 Also reported per Part 21 EDELMAN.M.R. Cleveland Electric Illuminating Co 84/03/09 KEPPLER, J. Q. Region 3, Office of Director 2pp 22666 186 24X Fiche: 50-440.84/03/09,8403190051
- 8402070038 Board Notification 84-051 forwards "Transamerica Delaval, Inc (TDI) Diesel Generators Owners Group Program Plan."
 EIBENHUT,D G. Division of Licensing 84/03/12 PALLADINO Commissioners 5pp. 22688 214, 24X Fiche 50-000,84/03/12, 8402090038.

- B402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval Inc (TDI) Owners Group Distribution list encl
 EISENHUT.D 0 Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fiche 50-000.84/03/12.8402090039
- --8403060536 Forwards summary of 840210 meeting w/Transamerice Delaval.
 Inc Owners Group in Bethesda,MD re problems w/emergency
 diesel generators
 CARUSO,R Licensing Branch 2 84/02/27 O'REILLY,JP NRC No
 Detailed Affiliation Given 6pp 22708 006 24x
 Fiche 50-000,84/03/12,8402090039
- --8403060554 Transcript of 840210 meeting u/Transamerica Delaval. Inc Owners Group in Bethesda. MD re problems u/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fiche 50-000.84/03/12:8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners
 Group in Wading River,NY re program plan to establish
 reliability of dissel generators Agenda.meeting transcript &
 attendance list encl
 MILLER,M A Licensing Branch 4 84/02/27 Licensing Branch 4
 Bpp 22708 161 24X Fiche 50-000.84/03/12.8402070039
- --8403070423 Transcript of B40216 conference in Wading River,NY re Transamerica Delaval,Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000,84/03/12.8402090039
- B403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Orand Gulf diesel generators MUSELER, W J Long Island Lighting Co 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22632 074 24X Fiche 50-000,84/03/12,8403140050
- B403150133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & svc conditions MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group B4/03/13 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24% Fiche 30-000,84/03/13,8403150133
- B403200222 Responds to B40214 Requests for Info i & 2 re R-4 series angines List indicating engine number model & svc number, customer name & address, rating, date shipped & date started enc!

 MATHEMS.C S Transamerica Delaval. Inc B4/03/16 EIBENHUT, D O Division of Licensing 20pp 22691 179 24X Fiche 50~000, B4/03/16. B403200222
- B4032300il Interim deficiency rept re synchronization between standby diesel generator & alternate preferred power source Initially reported on B40216 Evaluation of as-designed condition underway Next rept by B40430 EDELMAN, M R Cleveland Electric Illuminating Co 84/03/16 KEPPLER. J G Region 3, Office of Director 2pp 22727:359 24X Fiche 50-440,84/03/16,8403230011
- 8403230045 Interim deficiency rept re design of dietel generator logic inconsistent w/FBAR Initially reported on 840216 Glibert Assoc. Inc investigating possible safety implications of identified discrepancies Next rept expected by 840430 EDELMAN. M R Cleveland Electric Illuminating Co 84/03/16 KEPPLER. J G Region 3. Office of Director 2pp 22727 361 24X Fiche 50-440.84/03/16.8403230045
- 8403230083 Interim deficiency rept re defects in design of HPCS interfaces to suppression pool cleanup sys Gilbert Assoc. Inc evaluating as-designed condition & associated logic to determine if design change necessary Next rept by 840430 EDELMAN, M R Cleveland Electric Illuminating Co 84/03/16 KEPPLER Region 3, Office of Director 2pp. 22726 291 24X Fiche, 50-440, 84/03/16, 8403230083
- B403230101 Interim deficiency rept re design of valve coordination for HPCS sys Initially reported on 840216 AE currently investigating as-designed condition of valves & associated logic Next rept expected by 840420 EDELMAN.M R Cleveland Electric Illuminating Co 84/03/16 KEPPLER.J O. Region 3, Office of Director 2pp 22726 341 24X Fiche 50-440.84/03/16.8403230101
- 8403260247 Final deficiency rept re lack of power monitor downstream of fuses in HPCB safety-related control circuits Gilbert Assoc, Inc evaluating as-designed condition of sys to make appropriate design changes, Changes expected by 840501 EDELMAN, H R Cleveland Electric Illuminating Co 84/03/16 KEPPLER.J Q Region 3, Office of Director 2pp 22756.063 24X Fiche 50-440,84/03/16,8403260247

- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by 5&W for Transamerica Delavel, Inc (TDI) Diesel Generator Owners Oppun
- Oroup MUSELER: N J TDI (Transamerica Delaval, Inc.) Dwners Oroup 84/03/23 DENTON: H R Office of Nuclear Reactor Regulation, Director 2pp 22774 001 24X Fiche 50-000, 84/03/23, 8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica
 Delavai dissel generators List of suggested meeting topics encl
 MCGAUCHY, JP TDI (Transamerica Delavai, Inc.) Owners Group
 84/03/23 DENTON: HR Office of Nuclear Reactor Regulation,
 Director 4pp 22769 133 24K Fiche 50-000, 84/03/23, 8403270134

T Hearing transcripts on non-antitrust matters

- B402090039 Board Notification B4-052 forwards meeting summaries containing transcripts of B40210 & 16 meetings between NRC & Transamerica Delavai. Inc (TDI) Guners Group Distribution list encl EISENHUT, D G Division of Licensing B4/03/12 PALLADING Commissioners 5pp 22708 001 24X Fiche 50-000, B4/03/12, B402090039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda.MD re problems w/emergency diesei generators CARUSO,R Licensing Branch 2 84/02/27 O'REILLY.J P NRC No Detailed Affiliation Given 6pp 22708 006 24X Fiche 50-000.84/03/12,8402090039
- --8403060554 Transcript of 840210 mpeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency dissel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fiche 50-000,84/03/12,8402090039
- --8403070409 Summary of B40216 meeting w/Transamerica Delavai.Inc Dwners Oroup in Wading River.NY re program plan to establish reliability of diesel generators Agenda.meeting transcript & attendance list encl MILLER.H A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Ficher50-000.84/03/12.8402090039
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval, Inc diesel generatore Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000,84/03/12,8402070039

V Operator Examinations

8403190391 Forwards tables reflecting nuclear power plant experience for operating shift positions, including current staffing experience levels & level projected at time of fuel load EDELMAN.M R Cleveland Electric Illuminating Co 84/03/09 DENTON.H R Office of Nuclear Reactor Regulation, Director 13pp 22675 282 24X Ficha 50-440.84/03/09.8403190391

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

- 8402070003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A,B & C documents.
 FELTON,U M Division of Rules and Records 83/10/31
 RDSENSAUM,D M Technical Analysis Corp 17pp 22193 292 24X
 Fichs 50-000.83/10/31.8402070003
- --B402090186 Handwritten calculations & graphs re const activities & preoperational & acceptance testing Related info enci
 * NRC No Datailed Affiliation Given Bi/09716 6pp
 22194,191 24X Fiche 50-000,83/10/31,8402090003
- 84D2070017 Board Notification 84-038 forwards RJ Mattson 840123 memo to DQ Eisenbut providing status update of NRC actions re Hestinghouse ECCS actuation logic EIBENNUT.D.O Division of Licensing 84/02/27 PALLADINO Commissioners 7pp 22546-007 24X Fiche:50-000,84/02/27,840090017
- 8403150080 Requests correction to Amend 5 to CPPR-135 & CPPR-136 to indicate that Washington Electric Cooperative. Inc never became joint owner or licensee of project RITSHER, J.A. Ropes & Gray RITSHER, J.A. Public Service Co. of New Hampshire 84703/07 Division of Licensing 2pp 22641 051. 24X Fiche: 50-443:84/03/07,8403150080

- 8403280122 Summary of 840224 meeting w/Westinghouse Guners Group in Bethesda.MD re-proposed Westinghouse steam generator tube rupture generic program Attendes list & agenda enc.l NERSES.V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp 22811 131 24X Fiche.50-000.84/03/07.8403280122
- 8402090041 Board Notification 84~050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT.D G Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000.84/03/14.8402090041
- 8403210097 Forwards news release re joint owners 840301 meeting, notification of ASEB & svc list Estimated date for initial operation of Unit 1 is Jul 1986 DEVINCENTIS, J Public Service Co of New Hampshire 84/03/14 KNIGHTON, O W Licensing Branch 3 9pg 22706 090 24X Fiche S0-443,64/03/14,8403210099
- --8403210101 Advises of new interim schedule for fuel load at facility
 Estimated fuel load date for Units 1 & 2 are 851231 &
 900731:respectively
 GAD:R K Ropes & Oray GAD:R K Public Service Co of New
 Hampshire 84/03/01 HOYT:H , HARROUR:J , LUEBKE,E A Atomic
 Safety and Licensing Board Panel 1p 22706 099 24X
 Fiche 50-443,84/03/14,8403210099
- 8403210142 Requests approval to implement Paragraphs NF-3324 5,1983 edition & NF-4427,1980 edition through Winter 1982 of ASME Section III Code for linear-type piping supports DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS. J Public Service Co of New Hampshire 84/03/15 KNICHTON, O W Licensing Branch 3 14pp 22707 112 24X Fiche 50-443,84/03/15,8403210142
- 8403270121 Forwards operator shift experience tables, per DF Schneli request First set of tables identifies experience levels as of 840430 Second set projects experience levels to Dec 1785, scheduled fuel load date Shift advisors will not be used DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 84/03/20 DENTON, HR Office of Nuclear Reactor Regulation, Director 18pp 22775 139, 24X Fiche 50-443,84/03/20,8403270121
- 8403230061 Forwards Caseload Forecast Panel data package presented to Panel representatives during 840313 & 14 visit to plant Data package prepared in response to encl panel agenda DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS, J Public Bervice Co of New Hampshire 84/03/21 KNIGHTON. 6 W Licensing Branch 3 139pp 22726 041 24X Fiche 50-443.84/03/21.8403230061

F Security, medical, emergency & fire protection plans

- 8403060559 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810709 Generic Ltr 81-87 W/o request, entire plan will be placed in PDR KNIGHTON.9 W Licensing Branch 3 84/02/20 HARRISON.R J Public Service Co of New Hampshire 4pp 22552 272 24X Fiche 50-443,84/02/20,8403060559
- 8402070006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D G Division of Licensing 84/02/23 PALLADING Commissioners 1p 22576 203 24% Fiche 50-000.84/02/23, 8402070006
- --B4030B0316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NRR Ofc Ltr 17.dtd B21001. Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT.D Q Division of Licensing 10pp 22576 204 24X Fiche 30-000,84/02/23,8402090006
- 8403090143 Summarizes 831219 meeting w/util at Region I ofc re emergency telecommunications at facility Summary encl Locations for emergency notification sys adequate for NRC emergency response MARTIN,T.T Division of Engineering & Technical Programs, 84/03/02 HARRISON,R J Public Service Co of New Hampshire 4pp 22575 062 24X Fiche 50-443,84/03/02.8403090143.
- 8403190243 Notification of 840418 workshop in King of Prussia,PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl MURLEY,T E Region i, Office of Director, 84/03/09 0'TOOLE,J D. Consolidated Edison Co of New York, Inc. 35pp 22672'062 24X Fiche 50-000,84/03/09.8403190243

ı

- 8403160256 Forwards finalized updated App A to rediclogical emergency plan describing emergency classification & action Rev will be included in future amend to OL application DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Bervice Co of New Hampshire 84/03/14 KNIGHTON, G W Licensing Branch 3 ip 22661 010 24X Fiche 50-443,84/03/14,8403160256
- --8403160263 Updated App A to radiological emergency plan.comsisting of emergency classification sys & emergency action levels # Public Service Co of New Hampshire 83/05/31 15pp 22661 011 24% Fiche 50-449.84/03/14.8403160256

@ Adjudicatory correspondence

- 8403070042 Suppl to 840224 answer to Beacoast Anti-Pollution League (SAPL) 840210 motion for reconsideration of dehial of BAPL supplemental Contention 5 Certificate of Svc encl QAD,R K Public Bervice Co of New Hampshire OAD,R K Ropes & Gray 84/02/28 Atomic Safety and Licensing Board Panel 5pp. 22541 255 24X Fiche 50-443,84/02/28,8403070042
- 8403020173 New England Coalition on Nuclear Pollution Contention VII re financial qualifications of util to operate & decommission facility Certificate of Svc enci CURRAN, D New England Coalition on Nuclear Pollution CURRAN, D, UCRDAN, B Harmon & Weiss 84/02/27 Atomic Safety and Licensing Board Panel 15pp 22443 225 24X Fiche 50-443,84/02/29,8403020173
- 8403070020 Forwards supplemental responses to Atty General Belloti interrogatories, Related correspondence GABSIOV.B P Federal Emergency Management Agency 84/02/29 Docketing & Services Branch 2pp 22545 329 24X Fich# 50-443,84/02/29,8403070020
- --8403070022 Supplemental response to Atty General Belloti interrogatories re number of persons for which State of NH must assure medical sycs.per 10CFR50 47 W/Certificate of Byc.Related correspondence SWIREN.B J Federal Emergency Management Agency 84/02/29 7pp 22545 331 24% Fiche 50-443.84/02/29.8403070020
- 8403140051 Response to Seacoast Anti-Pollution League (SAPL) 840210 motion for reconsideration of denial of SAPL 830913 supplemental Contention 5 re util financial qualifications. Motion should be denied W/Certificate of SVc PERLIB.R O Hearing Branch 3 84/03/01 Atomic Safety and Literwing Board Panel 7pp 22633 112 24X Fiche 30-443,84/03/01,8403140031
- 8403070232 Informs that as result of correspondence & discussion w/coursel for applicant. New England Coalition on Nuclear Pollution will withdraw Contention III 3 w/ASLB approval GURRAN. D Harmon & Weiss CURRAN. D New England Coalition on Nuclear Pollution 84/03/05 HOYT. H F, LUEBKE, E A, HARBOUR, J. Atomic Safety and Licensing Board Penel 1p 22538 362 24X Fiche: 50-443,84/03/05,8403070232
- 84030B0142 Response to Seacoast Anti-Pollution League (SAPL) 840217 appeal of denial of motion to dismiss application for Unit 2. ASLAB decision not erroneous & should be affirmed SAPL motion should be denied W/Certificate of Svc DIGNAN, T 0, OADLR K Public Service Co of New Hampshire DIGNAN, T 0 Ropes & Gray 84/03/05 Atomic Safety and Licensing Appeal Panel 11pp 22559, 207 24X Fiche 50-443, 84/03/05, 84/03/05,
- 8403090093 Response to New England Coalition on Nuclear Pollution (NECNP) Contention VII re financial qualification of util to operate & decommission facility NECNP Contention VII should be excluded Certificate of Svc encl DIGNAN, T O Public Bervice Co of New Hampshire DIGNAN, T G Ropes & Gray 84/03/05. Atomic Safety and Licensing Board Panel 4pp 22376:031 24% Fiche 50-443,84/03/05,8403090093
- 8403090124 Forwards util response to Beatoast Anti-Pollution League appeal of denial of motion to dismiss application for Unit 2 W/o enci Related corespondence DIQNAN.T O Ropes & Gray DIGNAN.T O Public Bervice Co of New Hampshire 84/03/05 Public Document Branch ip 22574 063. 24X Fiche. 50-443.84/03/05.8403090124
- B403140025 Notice of withdrawal of appearance in proceeding ZIYSER, B, B Connecticut, State of 84/03/06 2pp 22633 2i5 24X Fiche: 50-443, 84/03/06, 8403140025
- 8403070107 Order accepting New England Coalition on Nuclear Pollution 840305 decision to withdraw Contention III 3 re training of unit shift supervisors HDYT-HF Abomic Safety and Licensing Board Panel 84/03/07 ip 22376 080, 24X Fiche 30-443,84/03/07,8403090107

- 8403090062 Advises that time for Commission to review ALAB-758 expired Commission declined review Decision became final agency action on 840305 CHILK,6 J Office of the Secretary of the Commission 84/03/08 Atomic Safety and Licensing Appeal Panel ip 22576 049 24X Fiche 50-443,84/03/08.8403090062
- 8403140052 Response in opposition to Seacoast Anti-Pollution League appeal of denial of motion to dismiss application Appeal failed to meet requirements for directed certification Certificate of Svc encl PATTERSON.W F Hearing Branch 3 84/03/08 Atomic Safety and Licensing Appeal Panel 20pp 22633 093 24X Fiche 50-443, 84/03/08,8403140052
- 8403190129 Memorandum & order denying motion for directed certification of ASLB 840113 memorandum & order SHOEMAKER.C J. Atomic Safety and Licensing Appeal Panel 84/03/16 Beacoast Anti-Pollution League 9pp 22669 191 24X Fiche 50-443-84/03/16.8403190129
- 8403210196 Response opposing New England Coalition on Nuclear Pollution (NECNP) Contention VII re financial qualifications of util to operate & decommission facility Certificate of Svc encl PERLIS.R O Hearing Branch 3 DSB 013 84/03/20 Atomic Safety and Licensing Board Panel 5pp 22710 079 24X Fiche 50-443.84/03/20.8403210196
- 84032301BO Response opposing New England Coalition Against Nuclear Power motion to file supplemental contention on state & local emergency response plans Probabilistic safety assessment summary rept encl W/Certificate of Svc GAD.R K Public Bervice Co of New Hampshire GAD.R K Ropss & Gray DS8 075 84/03/20 Atomic Safety and Licensing Board Panel 36pp 22743 025 24X Fiche 50-443,84/03/20,8403230180
- 8403270002 Second petition for leave to intervene in proceedings Certificate of Svc encl DDHERTY.JF Doherty, JF DSB 111 84/03/22 Atomic Sefety and Licensing Board Panel Bpp 22770 001 24X Fiche 50-443.84/03/22, 8403270002
- 8403260343 Order denying & rejecting Seaccast Anti-Poliution League motion for reconsideration & New England Coalition on Nuclear Pollution proffered Contention 5, respectively Served on 840326 HOYTH F Office of the Secretary of the Commission DBB 087. 84/03/23 Seaccast Anti-Pollution League 5pp 22760 179 24X Fichs 50-443,84/03/23,8403260343
- B403300269 Response opposing JF Doherty B40328 second petition for leave to intervene Petition fails to show good cause for late filing Certificate of Bvc enc!

 QAD.R K. DIONANIT G Public Service Co of New Hampshire QAD.R X Ropes & Gray DSB 213 84/03/28 Atomic Safety and Licensing Board Panel 9pp 22824 059 24X Fiche 50-443.84/03/28.8403300269
- 8403300263 Notice of change in address in svc list Certificate of Svc encl CURRAN, D Harmon & Weiss DSB 227 84/03/30 3pp 22824 068 24X Fiche 50-443,84/03/30,8403300263
- G Inspection reports. IE Bulletins & correspondence
- 8403020282 Forwards IE Insp Repts 50~443/83-22 & 50~444/83-15 on 831206-840120 & notice of violation STARQSTECKI,R Division of Project & Resident Programs 84/02/17 HARRIBON,R J Public Service Co of New Hampshire 2pp 24X Fiche 50~443,84/02/17,8403020282
- --B403020301 Notice of violation from insp on B31204-B40120 * Region i, Office of Director 84/02/17 2pp 22439:174 24X Fiche 50-443,84/02/17,8403020282
- --8403020308 IE insp Repts 50-443/83-22 & 50-444/83-15 on 831206-840120 Violations noted recurrent electrical const violation which may be indicative of interface problem between AE & electrical contractor CERNE, A C . KESCOTT.H M Region 1, Office of Director GALLO,R M Division of Project & Resident Programs 84/02/07 12pp 22437 176 24X Fiche 50-443,84/02/17,8403020282
- 8403150100 Final deficiency rept & final response to IE Bulletin 83-06
 "Nonconforming Matls Supplied by Tube-Line Corp " Add1
 testing performed Tube-Line matl acceptable Item not
 reportable per 100FR50 35(e)
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J. Public
 Bervice Co of New Hampshire 84/02/22 MURLEY, T C Region 1,
 Office of Director 3pp 22643 159 24X Fiche 50-443,84/02/22,
 8403150100

- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl
 - encl JDRDAN,E L. Divísion of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consplidated Edison Co. of New York, Inc. 115pp 22709 239 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Reve by DDT & NRC." Svc list encl GRACE.J.N Division of GA, Safeguarde & Inspection Programe (Post 830103). 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24x Fiche 50-000.84/03/02.8402090007
- 840209000B IE info Notice 84-i6. "Failure of Automatic Sprinkler Sye Valvee to Operate " Svc list enci JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp. 22553 098 24X Fiche 50-000.84/03/02,8402090008
- 8402070007 IE Info Notice 84-15: "Reporting of Radiological Releases" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Poet 830103) 84/03/02. Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fichs 50-000,84/03/02.8402070007
- 840207001i IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05. Consolidated Edison Co. of New York, Inc. 117pp 22553 336. 24X Fiche 50-000,84/03/05,840209001i.
- 8402090024 IE Info Notice 84-09, Rev i, "Lessons Learnef From Insps of Fire Protection Bafe Shutdown Sys." Byo list enci JORDAN, E.L. Division of Emargency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049. 24% Fichs 50-000,84/03/07,8402090024
- 8402090028 IE.Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Bvc list encl. JORDANAE L Division of Emergency Preparedness & Engineering Response (Post 830103), B4/03/07 Consolidated Edison Co of New York, Inc. 118pp. 22584 (86. 24X Fiche 50-000,84/03/07,8402090028
- B402070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNO.R C Diractor's Office, Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823-094 24% Fichs 50-000.84/03/12.8402090031
- B402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 227 24X Fiche 50-000,84/03/21,8402090043
- B402070044 IE Info Notice 84-20. "Svc Life of Relaye in Sefety-Related Sye " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22733 GOL. 24X Fiche 30-000.84/03/21.8402070044
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for DL reviews for Jan 1984. Changes in FEMA finding dates not caused by deley due to offsite emergency planning issues
 DIRCKS.W.J. Office of the Executive Director for Operations
 84/02/21 PALLADINO Commissioners. 9pp 22492 083 24X
 Fichs 50-000.84/02/21.8403020443
- B Repurtable occurrences, LERe & ralated correspondence
- 8403210075 Part 21 rapt re nonconformance of metal hose accemblies for ASME, Section III, Clase 2 & 3 svc Status of nonconforming items shipped encl All customers notified LALIKOB, J M Titefler Corp 83/12/16, Director's Office, Office of Inspection and Enforcement, 4pp. 22704 324 24X Fiche 50-000,83/12/16,8403210095.
- B403130468 Interim deficiency rept re cracked & broken guffer piston rods in Brown Boveri Type 5HK breakers Initially reported on B40119. All Unit 1 breakers will be inspected during next scheduled maint in Mar 1984.

 DEVINCENTIS.J Public Service Co of New Hampshire. B4/02/i4 BTAROBTECKI.R Division of Project & Resident Programs 3pp. 22613 216 24X Fiche 50-443.84/02/14.8403130468

- 8403130100 Final deficiency rept & final response to IE Bulletin 83-06
 "Nonconforming Mette Supplied by Tube-Line Corp " Add1
 taeting parformed Tube-Line met1 acceptable Item not
 reportable per 10CFR30. 536 etc.
 DEVINCENTIS. J Yankee Atomic Electric Co. DEVINCENTIS, J Public
 Sarvice Co of New Hampshire 84/02/22 MURLEY. T. C Region 1, .
 Office of Director 3pp 22643 159. 24X Fiche 30-443,84/02/22,
 8403130100
- 8403210032 Part 21 rept re failure of auxiliary feadwater pump drive turbinas; Gimpel NPS-4 T&T valve to close Enci ltr dtd 840203 eent to listed utils GE notified of affected unite in BMR plants.

 THEROUX,R R Terry Corp 84/02/22 MODDRUFF,R W Director's Office, Office of Inspection and Enforcement 6pp 22706 327 24X Fiche 50-000,84/02/22,8403210032
- 8403060311 Part 21 final design rept re inedequacy of evc water & circulating water pump house attractura Analysis completed. Rapeir const activities in progress.

 KREIDER: H 9 United Engineers & Constructors, Inc (subs. of Raythaon Co) B4/02/28 Director's Office. Office of Inspection and Enforcement 3pp 22515:335 24X Fiche: 50-443,84/02/28.
- 8403220130 Interim deficiency rept re cracked mechanical chock arrector capetan epringe supplied by Pecific Briantific. Initially reported on 831024. All 48 arrectors returned to vendor for exem & will be replaced if necessary. Next rapt by 840330.

 DEVINCENTIS, J. Yankes Atomic Electric Co. DEVINCENTIS, J. Public Sarvice Co of New Hampehire 84/02/28, 81AROSTECKI, R. Division of Project & Resident Programs. 2pp. 22715, 361. 24X
 Fiche. 50-443, 84/02/28, 8403220150
- 8403260233 Forwards summary list of deficiencies identified per iOCFR50 51es). Pert 21 & potential generic itr repts for comments.

 BTAROBTECKI.R Division of Project & Resident Programs 84/02/28. Region i, Office of Director. 7pp 22756:065 24X Fichs: 50-000.84/02/28.8403260233
- 8403220005 Interim deficiency rept re isolated incident of violation of spec for assembly & eraction of piping & mechanical equipment Initially reported on 821110. Investigation underway. Work will be completed by 840401.

 DEVINCENTIS. J Yankes Atomic Electric Co. DEVINCENTIS, J Public Barvica Co. of New Hampshire. 84/03/02. STAROBTECKI.R. Division of Project & Resident Programe 2pp. 22712-361. 24X

 Fiche: 50-443.84/03/02.8403220005.
- B403220164 Interim deficiency rept re possible jamming of Gould combination reversing motor starters. Initially reported on 840210. Sould replacing self defective combination reversing motor starters. Next rapt will be provided by 840430 DEVINCENTIS, J. Yankee Atomic Electric Co DEVINCENTIS, J. Public Barvice Co. of New Hampshirs. B4/03/05 STAROBTECKI, R Division of Project & Resident Programs 3pp. 22718 054 24X Fiche 50-443,84/03/05,8403220164.
- B40319024B Supplementel Part 21 rept re failed engine thrust bearing, Piugs properly ineteilad in both units. Units free of potential defect.
 MORIARTY.J M Colt Industrias, Inc. B4/03/0B KEPPLER, J. Q. Region 3, Defice of Director ip 22675-045 24X Fiche. 50-000, 84/03/0B,
- B403190374 Part 2: rept re failed engine thrust bearing. Initially reported on 800502 Field insp of Colt-Pieletick Type PC-2 diesal generator sets completed using revised drawings Unit in compliance w/insp procedure & free of potential defect HORIARTY, J M. Colt Industries, Inc. 84/03/08 KEPPLER, J, Q. Regio 3, Office of Director ip. 22674.353. 24% Ficha: 50-443,84/03/08,8403190374
- B403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-i5 kV.500-750 MVA.5 kV 350-3.000 & all HKV circuit breakers Initially reported on B30223 Addenda to installetion & maint procedures sent to affected units. DUVALL.D D Brown Boveri Corp. (subs. of Brown Bovari & Co., Ltd.). B4/03/19 Record Barvices Branch (Dacument Control Desk). 5pp. 22772:114 24X Ficher 50-000.84/03/19.8403270219.
- V. Operator Examinations
- 8403270121 Forwards operator shift experience tables, per DF Schnell request First set of tables identifies experience levels as of 840430 Second set projects experience levels to Dec 1985, scheduled fuel load date. Shift advisore will not be used. DEVINCENTIS. J Yankes Atomic Electric Co. DEVINCENTIS. J. Public Service Co. of New Hampshire. 84/03/20 DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 18pp 22775;139. 24X Fiche: 30-443,84/03/20.8403270121

- DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B402070003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A, B & C documents
 FELTON, J M Division of Rules and Records 83/10/31
 RDSENBAUM, D.M Technical Analysis Corp 17pp 22193 272 24X
 Fiche 50-000,83/10/31,8402070003
- --B402090iB6 Handwritten calculations & graphs re const activities & preoperational & acceptance testing Related info encl * NRC No Detailed Affiliation Given BI/09/16 6pp 22i96 19i 24X Fiche 50-000.83/10/31,8402090003
- 8402090017 Board Notification 84-038 forwards RJ Mattson 840123 memb to DG Eisenhut providing status update of NRC actions re Hestinghouse ECCB actuation logic EISENHUT.D G Division of Licensing 84/02/27. PALLADING Commissioners 7pp 22546 007 24X Fichs 50-000,84/02/27, 8402090017
- 84031500B0 Requests correction to Amend 5 to CPPR-135 & CPPR-136 to indicate that Washington Electric Cooperative, Inc never became joint owner or licensee of project RITSHER, J A Ropes & Gray RITSHER, J A Public Bervice Co of New Hampshire 84/03/07 Division of Licensing 2pp 22641.051 24X Fiche 50-443,84/03/07,8403150080
- 8403280122 Summary of 840224 meeting w/Westingbouse Owners Group in Bethesda, MD re proposed Westingbouse steam generator tube rupture generic program Attendee list & agenda ench NERSES, V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp. 22811 131 24X Fiche 50-000,84/03/07,8403280122
- 840207004i Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D G Division of Licensing 84/03/14. Atomic Bafety and Licensing Board Panel 10pp 24X Fiche 50-000.84/03/14.8402070041
- 8403210099 Forwards news release re joint owners 840301 meeting, notification of ABLB & svc list Estimated date for initial operation of Unit 1 is Jul 1986
 BEVINCENTIB, J. Yankee Atomic Electric Co DEVINCENTIB, J. Public Service Co of New Hampshire 84/03/14 KN10HTDN, 0 W Licensing Branch 3 9pp 22706 090 24X Fichs 50-443,84/03/14,8403210099
- --8403210101 Advises of new interim schedule for fuel load at facility Estimated fuel load date for Units 1 & 2 are 851231 & 900731, respectively QAD.R K Ropes & Gray. GAD.R K Public Service Co of New Hampshire. 84/03/01 HOYT.H , HARBOUR,J , LUEBKE,E A Atumic Safety and Licensing Board Panel ip. 22706:099 24X Fiche: 50-443,84/03/14.8403210099
- 8403210142 Requests approval to implement Paragraphs NF-3324 5,1983 edition & NF-4427,1980 edition through Winter 1982 of ABME Section III Gode for linear-type piping supports DEVINCENTIS, J. Yankee Atomic Electric Co DEVINCENTIS, J. Public Service Co of New Hampshire 84/03/15 KN19HTON, 0 W Licensing Branch 3 14pp 22707 112 24X Fiche 50-443,84/03/15,8403210142.
- 8403270121 Forwards operator shift experience tables, per DF Schneil request, First set of tables identifies experience levels as of 840430 Second set projects experience levels to Dec 1985, scheduled fuel load date. Shift advisors will not be used DEVINCENTIS, J. Yankee Atomic Electric Co DEVINCENTIS, J. Public Bsrvice Co. of New Hampshire 84/03/20 DENTON: H. Office of Nuclear Reactor Regulation, Director 18pp 22775 139 24X Fiche. 50-443,84/03/20,8403270121
- 8403230061 Forwards Caseload Forecast Panel data package presented to Panel representatives during 840313 % 14 visit to plant Data package prepared in response to encl panel agenda DEVINCENTIB.J. Yankee Atomic Electric Co. DEVINCENTIB.J. Public Service Co. of New Hampshire. 84/03/21. KNIGHTON. 0 W Licensing Branch 3 139pp 22726:041. 24X Fiche. 50-443.84/03/21.8403230061
- F Becurity, medical, amergency & fire protection plans
- 8403060559 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR.

 KNIGHTON, 0 W. Licensing Branch 3 84/02/20. HARRISON, R J Public Service Co. of New Hampshire. 4pp 22552'272 24X

 Fiche. 50-443,84/02/20,8403060559

- B402090006 Board Notification 84-034 forwards R Vollmer B40206 memo to D Eisenhut re fire research results concerning fires in electrical Cabinets in control room EISENHUT, D Q Division of Licensing 84/02/23 PALLADINO Commissioners ip 22576 203 24% Fiche 50-000, 84/02/23, 8402090006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NRR Off Ltr 17,6td 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT,D 6 Division of Licensing 10pp 22576 204 24X Fiche 50-000.84/02/23,8402070006
- 8403070143 Summarizes 831219 meeting w/util at Region I ofc re emergency telecommunications at facility Summary encl Locations for emergency notification sys adequate for NRC emergency response MARTIN.T T Division of Engineering & Technical Programs 84/03/02 HARRISON.R J Public Service Co of New Hampshire. 4pp 22578 062 24X Fiche 50-443,84/03/02.8403090143
- B403170243 Notification of B40418 workshop in King of Prussia,PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topice described in IE info Notice B4-09 Agenda for workshop enci MURLEY,T E Region 1. Office of Director B4/03/09 0'TOGLE,J D Consolidated Edison Co of New York Inc 35pp 22472 062 24X Fiche 50-000.84/03/09.8403190243
- 8403160256 Forwards finalized updated App A to radiological emergency plan describing emergency classification & action Rev will be included in future amend to OL application DEVINCENTIS. J Yankse Atomic Electric Co DEVINCENTIS. J Public Bervice Co of New Hampshire 84/03/14 KNIGHTON, C W Licensing Branth 3 ip 22661 Q10 24X Fiche 30-443,84/03/14,8403160256
- --B403160263 Updated App A to radiciogical emergency plan, consisting of emergency classification sys & emergency action levels

 * Public Service Co of New Hampshire B3/05/31 15pp
 22661 011 24% Fiche 50-444,84/03/14,8403160256
- Q Adjudicatory correspondence
- 8403070042 Suppl to 840224 answer to Seacoast Anti-Pollution League (SAPL) 840210 motion for reconsideration of denial of SAPL supplemental Contention 5 Certificate of Svc enci QAD.R.K Public Service Co of New Hampshire QAD.R.K Ropes & Gray 84/02/28 Atomic Safety and Licensing Board Panel 5pp 22541 255 24X Fiche 50-443.84/02/28.8403070042
- 8403020173 New England Coalition on Nuclear Poliution Contention VII re financial qualifications of util to operate & decommission facility Certificate of Svc smcl CURRAN, D New England Coalition on Nuclear Pollution CURRAN, D , JORDAN, W S Harmon & Weiss 84/02/29 Atomic Safety and Licensing Board Panei 15pp 22443 225 24X Fiche 50-443,84/02/29,8403020173
- B403070020 Forwards supplemental responses to Atty General Helloti interrogatories Related correspondence GABSIDY,B P Federal Emergency Management Agency B4/02/29 Docketing & Bervices Branch. 2pp 22345 327 24x Fiche 50-443.84/02/29.8403070020
- --8403070022 Supplemental response to Atty General Belioti
 interrogatories re number of persons for which State of NH
 must assure medical svcs, per 10CFRSO 47 W/Certificate of
 Svc Related correspondence
 BWIREN. B J Federal Emergency Management Agency 84/02/29 9pp
 22545:331 24X Fiche 50~443.84/02/29.8403070020
- B403i4005i Response to Beaccast Anti-Pollution League (SAPL) 8402i0 motion for reconsideration of denial of SAPL 8309i3 supplemental Contention 5 re util financial qualifications Motion should be denied W/Certificate of Svc. PERLIB.R 0. Hearing Branch 3 B4/03/01 Atomic Bafety and Licensing Board Panel 7pp 22633 112 24X Fiche: 50-443,84/03/01.8403i40051.
- B403070232 Informs that as result of correspondence & discussion w/coursel for applicant. New England Coalition on Nuclear Pollution will withdraw Contention III 3 w/ASLB approval CURRAN.D Harmon & Weiss CURRAN.D New England Coalition on Nuclear Pollution 84/03/05 HOYT. H F, LUEBKE.E, A, HARBOUR. J Atomic Safety and Licensing Board Panel. ip 22538 362 24X Ficher 50-443.84/03/05.8403070232

HOBO142 Response to Seaccest Anti-Pollution League (SAPL) 840217 speal of denial of motion to dismiss application for Unit ASLAB decision not erroneous & should be affirmed BAPL tion should be defield M/Certificate of Svc (ORAN, T O , CAD, R X Public Service Co of New Hampshire CRAN, T O Ropes & Gray E4/03/05 Atomic Safety and Licensing speal Panel 11pp 22559 207 24X Fiche 50~443,84/03/05,103080142

1

- 8090093 Response to New England Coalition on Nuclear Pollution (ECNP) Contention VII re financial qualification of util operate & decommission facility NECNP Contention VII util be excluded Certificate of Svc enci ONAN.T O Public Service Co of New Hampshire DIGNAN.T O Rope: Gray 84/03/05 Atomic Safety and Licensing Board Panel 4pp 1976 031 24% Fiche 50-443,84/03/05.8403090093
- O90124 Forwards util response to Seacoast Anti-Pollution League peal of denial of motion to dismiss application for Unit W/o encl Releted corespondence GNAN, I G Ropes & Gray DIGNAN, I G Public Service Co of Newmoshire 84/03/05 Public Document Branch ig 22576 063 K Fiche 50-443,84/03/05,8403090124
- 140025 Notice of withdrewal of appearance in proceeding.
 TSER:B S Connecticut. State of B4/03/06 2pp 22633 215. 24X
 che 50-443,84/03/06.8403140025
- 090107 Order accepting New England Coalition on Nuclear Pollution 1305 decision to withdraw Contention III 3 re training of thift supervisors 'T.H.F. Atomic SeFety and Licensing Board Panel 84/03/07 ip 375 080 24X Fiche 50-443,84/03/07,8403090107
- 170062 Advises that time for Commission to review ALAB-758 ifred Commission declined review Decision became finel new action on 840305 LK.S J Defice of the Secretary of the Commission 84/03/08 mic Safety and Licensing Appeal Panel ip 22576 047 24% het 30-443-84/03/08.8403070062
- 40052 Response in opposition to Beacoast Anti-Poliution Leegue eal of denial of motion to dismiss application Appeal led to meet requirements for directed certification tificate of Svc encl
 TERSON W F Hearing Branch 3 84/03/08 Atomic Safety and ensing Appeal Panel 20pp 22633 093 24X Fiche 50-443, 03/08.8403140052
- 90129 Memorandum & order denying motion for directed certification ASLB 840113 memorandum & order HAKERIC J Atomic Safety and Licensing Appeal Panel 84/03/16 accoast Anti-Pollution League 9pp 22669 191 24X re 50-443.84/03/16.8403190129
- l0176 Response opposing New England Coalition on Nuclear Pollution NP) Contention VII re financial qualifications of util sperate & decommission facility Certificate of Svc uncl 15.R & Hearing Branch 3 DSB 013 84/03/20 Atomic Sefety Licensing Board Panel 5pp 22710 077 24X s 50-443.84/03/20,8403210196
- OldO Response apposing New England Coalition Against Nuclear, motion to file supplemental contention on state & lamergency response plans Probabilistic safety assment summary rept encl W/Certificate of Syc K Public Service Co of New Hampshire GAD.R.K Ropes & DSB 075 84/03/20 Atomic Safety and Licensing Board 1 36pp 22743 025 24x Fiche 50-443.84/03/20,8403230180.
- 1002 Second petition for leave to intervene in proceedings. ificate of Svc entl
 TY, U.F. Doherty, J.F. DSB iii 84/03/22 Atomic Safety end sing Board Panet 8pp 22770 001 24% Fiche 50-443,84/03/22,270000
-)343 Order denying & rejecting Seacoast Anti-Pollution League
 in for reconsideration & New England Coalition on
 iar Pollution proffered Contention 5, respectively Served
 (0326
- N269 Response opposing UF Doherty 840328 second petition for to intervene Petition fails to show good cause for filing Certificate of Svc encl. K., DIGNAM, T O Public Service Co of New Hampshire AAD, R K s & Gray D68 213 84/03/28 Atomic Safety and Licensing Panel 9pp 22824 059 24X Ficha-50-443,84/03/28,8403300269

- 8403300019 Order denying State of CT Div of Consumer Counsel petition to intervene in CP renewal proceeding & declaring Seacoast Anti-Pollution League motion for joinder most Served on 840329 CHILK.8 J Office of the Secretery of the Commission 1958 208 84/03/29 Seccest Anti-Pollution League opp 22822.165 24X Fiche 50-444.84/03/29.8403300019
- 84D3300263 Notice of chenge in address in svc list Certificate of Svc encl CURRAN.D Harmon & Heiss DSB 227 84/03/30 3pp 22824 068 24X Fiche 50-443.84/03/30.8403300263
- Q Inspection reports, IE Bulletins & correspondence
- 8403020282 Forwards IE Insp Repts 50-443/83-22 & 50-444/83-15 on 831206-840120 & hoticm of violation 874081ECKI, R Division of Project & Resident Programs 84/02/17. HARRIEGON, R J Public Bervics Co of New Hampshire. 2pp 22439 172 24X Fiche 50-443,84/02/17,8403020282
- --B403020308 IE Insp Repts 50-443/83-22 & 50-444/83-15 on 831206-840120 Violations noted recurrent electrical const violation which may be indicative of interface problem between AE & electrical contractor CERNEA C . MESCOTT. H M Region i, Office of Director. QALLO, R, H Division of Project & Resident Programs 84/02/09 12pp 22439 176 24X Fiche 50-443,84/02/17,8403020282
- 8403150100 Final deficiency rept & final response to IE Bulletin 83-06 "Nonconforming Matls Supplied by Tube-Line Corp." Additesting performed Tube-Line methacceptable Item not reportable per 10CFR50 55(a) DEVINCENTIS, J Yankee Atomic Electric Co 84/02/22. MURLEY, T C Region 1. Office of Director 3pp 22643 159 24% Fiche 50-443,84/02/22,8403150100
- 8401i90072 IE Info Notice 84-13. "Potentie! Deficiency in Hotor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22907:239 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Infg Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of GA: Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York: Inc 130pp 22552 329 24X Ficher 50-000:84/03/02.8402090007.
- 8402090008 IE info Notice 84-16, "Failure of Autometic Sprinkler Siys Valves to Operate " Svc list and JURDAN,EL Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Ficha 50-000,84/03/02,8402090008.
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 117pp 22553 217 24X Fiche 50-000,84/03/02,8402090009.
- 8402090011 lE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl. JURDAN,E L Division of Emergency Preperedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp. 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8402090024 IE Info Notice 84-09, Rev 1: "Lessons Learned From Insps of Fire Protection Sefe Shutdown Sys." Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24X Fichs; 50-000, 84/03/07, 8402099024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " Bvc list enc! JORDAN, EL Division of Emergency Preparadness & Engineering Response (Past 830103) 84/03/07 Consolidated Edison Co of New York: Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of OE Type HFA Relays in Use in Class IE Sefety Sys " Syc list encl.
 DEYOUNG,R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co. of New York, Inc 134pp 22823; 094 24X Fiche 50-000:84/03/12,8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cevities" Svc list encl JORDAN, E. L. Division of Emergency Preparadness & Engineering Responee (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche, 50-000, 84/03/21, 8402090043

- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Bys " Byc list encl Bys " Byc list and JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York. Inc 135pp 22933 001 24X Fiche 30-000.84/03/21.8402090044
- A Reportable preuprences, LERS & related correspondence
- 8403130468 Interim deficiency rept re cracked & broken puffer piston rods in Brown Boverl Type 5HK breakers Initially reported on 840119 All Unit 1 breakers will be inspected during next schaduled maint in Har 1984
 DEVINCENTIS, J Public Bervice Co of New Hampshire 84/02/14
 8TAROBTECKIR Division of Project & Resident Programs. 3pp 22613 216 24X Fiche 50-443,84/02/14,8403130468
- 8403150100 Final deficiency rapt & final response to 1E Bulletin 83-06
 "Nonconforming Matls Supplied by Tube-Line Corp " Add1
 testing performed Tube-Line matl acceptable Item not
 reportable per 10CFR50 55(e)
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co. of New Hampshire 84/02/22 MURLEY, T C Region 1,
 Defice of Director 3pp 22643 159 24X Fiche 50-443,84/02/22,
 8403150100
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbings. Oimpel NPS-4 T&T valve, to close Enci ltr dtd 840203 ment to listed ubils GE notified of affected units in BWR Plants.
 THERDUX.R R Terry Corp 84/02/22 HDODRUFF.R.W Director's Office of Inspection and Enforcement 6pp 22706 327 24X Fiche 50-000.84/02/22.8403210032
- 8403060311 Part 21 final design rept re inadequacy of svc water & circulating water pump house structure Analysis completed Repair const activities in progress KREIDER, H O United Engineers & Constructors, Inc (subs of Raytheon Co) 84/02/28 Director's Office, Office of Inspection and Enforcement 3pp 22515 335 24X Fiche 50-443,84/02/28, 8403060311.
- 8403220150 Interim deficiency rept Te crecked mechanical shock arrestor capstam springs supplied by Pacific Scientific Initially reported on 831024 All 48 arrestors returned to vendor for exam & will be replaced if nucessary Next rept by 840330 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 84/02/28 STAROSTECKI, R Division of Project & Resident Programs 2pp 22715 361 24X Fiche 50-443,84/02/28,8403220150
- 3403240233 Forwards summary list of deficiencies identified per IOCFR50 55(a).Part 21 & potential generic ltr repts for comments STAROSTECKIAR

Ediments STARDSTECKI.R Division of Project & Resident Programs. 84/02/28 Region to Office of Director. 7pp 22756,065 24X Fiche 50-000,84/02/28,8403260233

- H03220003 Interim deficiency rept re isolated incident of violation of spec for assembly & prection of piping & mechanical equipment Initially reported on 821110 Investigation underbug Work will be completed by 840601 DEVINCENTIS.J Yankee Atomic Electric Go DEVINCENTIS.J Public Service Go of New Hampshire. 84/03/02 STARDSTECKI.R. Division of Project & Resident Programs 2pp 22712-361 24X Fiche 50-443.84/03/02.8403220005
- 403220164 Interim deficiency rept re possible jamming of Gould combination reversing motor starters initially reported on 840210 Gould replacing all defective combination reversing motor starters Next rept will be provided by 840430 DEVINCENTIB, J Yankes Atomic Electric Co DEVINCENTIB, J Public Service Go of New Hampshire 84/03/05 BTARCBTECKI, R Division of Project & Resident Programs, Spr 22718 054 24X Fishe: 90-443,84/03/05,8403220164
- 403270219 Part 21 rept re broken contact carrier in control device of 7.5 kV-15 kV,500-750 MVA,5 kV 350-3,000 & ell HKV circuit breakers. Initially reported on 830223 Addende to installation & meint procedures sent to affected units DUVALL.D.D. Brown Bover: Corp (subs of Brown Bover: & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772:114. 24X Fiche 50-000,84/03/19,8403270219
- Hearing transcripts on non-antitrust matters
- 103270335 Transcript of Commission 840323 affirmation/discussion & vote in Washington, PC re request for denial of renewal of Seabtrook Unit 2 CP & SECY-94-48 concerning review of ALAB-724 in matter of Mat Ed Pp 1-3 * Commissioners. 84/03/23 6pp. 22787 356 24X Fiche. 50-000:84/03/23,8403270335

V Operator Examinations

- 8403270121 Forwards operator shift experience tables, per DF Schnell request First set of tables identifies experience levels as of 840330 Second set projects experience levels to Dec 1985, scheduled fuel load date Shift advisors will not be used DEVINCENTER, J Yankes Atomic Electric Co 84/03/20 DENTON, H R OFFICE of Nuclear Reactor Regulation, Director 18pp 22775 139 24X Fiche 50-443,84/03/20,8403270121
- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA . UNIT 1 A Application/construction stage documents & correspondence
- 8401120425 Forwards Amend 7 to CPPR-126 & CPPR-127, safety evaluation & notice of issuance & availability Amend reflects change in ownership of facilities
 EISENRUT, D G Division of Licensing 83/12/30 GARY, R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co)

 3pp 22210 343 24% Fiche 50-445.83/12/30,8401120425
- 101120428 Amena / to CPPR-128 & CPPR-127, reflecting change in dunership of facilities EISENNUT, D Q Division of Licensing 83/12/30 4pp 21804 341 24% Fiche 50-445,83/12/30,8401120425
- --8401120433 Safety evaluation supporting Amend 7 to CPPR-126 & CPPR-127
 * Office of Nuclear Reactor Regulation, Director 63/12/29 3pp
 21804 338 24X Fiche 50-445, 83/12/30, 8401120425
- ~-RAD1120437 Notice of issuance & availability of Amend 7 to CPPR-126 & OFPR-127
 YOUNGBLOOD, B J Licensing Branch 1 83/12/29 3pp 21804 348 24X Fiche 50-445, 83/12/30, 8401120425
- 8403D60155 Requests exemption from provisions of GDC 4 requiring protection of structure.sys & components against certain dynamic effects associated w/postulated breaks in RCS primary loop.per Generic Ltr 84-04 GARY, R J Texas Utilities Electric Co (formerly Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/02/17 YOUNGBLCOD.B J Licensing Branch l 4pp 22513 351 24x Fichs 50-445.84/02/17,84030&0155
- 8403020148 Forwards, for review, draft environ protection plan proposed For App B to plant OLS
 YOUNDBLOOD, B J Licensing Branch 1 84/02/21 GARY, R J Texas
 Utilities Electric Co (formerly Texas Utilities Generating Co)
 2pp. 22491 (57 24% Fichs 50-445 84/02/21,8403020148
- --B403020152 Environ protection plan (monradiological) for facility. App B
- 8402090017 Board Notification 84-038 forwards RJ Mattson 840123 memo 10209001/ Board Notification 84-030 forwards No matten 84012 to DO Elsenhut providing status update of NRC actions re Westinghouse ECCS actuation logic EISENHUT, D G Division of Licensing 84/02/27 PALLADINO Commissioners 7pp 82546 007 24X Fiche \$0-000.84/02/27, 8402090017
- 8403050273 Requests provision of alternative surveillance to replace requirement presently in Tech Specs re turbine overspeed protection Proposed alternative maint, calibr & testing program should assure that protection sus operable YOUNGBLOOD, B. J. Licensing Branch 1 84/02/27 GARY, R. J. Texas Utilities Electric Co. (Formerly Texas Utilities Cenerating Co.) 4pp. 22501 109 24X Fiche 50-445,84/02/29,8403050273
- 8403060299 Informs NRC that Nuclear Util Task Action Committee completed final draft of rept defining appropriate vendor interface program discussed in Generic Ltr 83-28 Final rept scheduled to be released by Apr (984 SCHMIDT, N.C. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) 84/02/29 EISENHUT, D.G. Office of Nuclear Reactor Regulation, Director 1p 22515-362 24X Fiche 50-445,84/02/29, 8403060299
- 8403070308 Forwards request for addl info re leak-before-break analysis & fracture toughness of piping matls under thermal aging conditions Submittal date requested within 5 days of itr receipt
 receipt
 YOUNOBLOOD, B J Licensing Branch 1 84/03/02 GARY, R J Texas
 Utilities Electric Co. (formerly Texas Utilities Generating Co.)
 4pp. 22584 338. 24X Fiche 50-445, 84/03/02, 8403090308
- 8403160079 Forwards Suppl 1 to "Human Factors Control Room Design Review," final rept GARY.R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/03/08 YOUNGSLOOD, B J Licensing Branch 1 1p 22654 001 24X Fiche 50-445,84/03/08,8403160079

- --8403160083 Suppl 1 to "Human Factors Control Room Design Review," final rept

 Texas Utilities Electric Co (formerly Texas Utilities
 Generating Co) 84/03/31 122pp 22654.002 24X
 Fiche 50-445.84/03/08.8403160079
- 8402090041 Board Notification 84-030 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D © Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000,84/03/14,8402090041
- 8403300249 Notification of Caseload Forecast Team 840319-21 meetings & site visit w/util in Arlington & Glen Rose.TX to discuss const completion schedule Agenda encl
 BURHELL.S B Licensing Branch | 84/03/15 VOUNGBLOOD, 8 J
 Licensing Branch | 9pp 22845 022 24X Fiche 50-445.84/03/15,
 8403300249
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addi documents subj to request continuing FELTON, J M Division of Ruies and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24% Fiche 50-000.88/02/13,8403080179
- --B005i30793 Provides status of SER inputs & acceptance reviews for OL & CP applications Schedule should be met
 BURKE, W C Effluent Treatment Systems Branch 80/02/04
 KREGER, W E Assistant Director for Site Analysis ip 22583 235
 24X Fiche 50-000.84/02/i3.8403080179
- 8403020289 Forwards resolution of BER Confirmatory issue ii re utii B30218 & 0316 submittals concerning TM1 Action Items I C 2 & I C 5 YOUNOBLOOD, B J Licensing Branch i 84/02/21 QARY, R J Texas Utilities Electric Co (Formerly Texas Utilities Generating Co) 5pp 22492 241 24X Fiche 50-445,84/02/21.8403020289
- 8403260069 Forwards evaluation of B3071B request for deletion of steam elactric station license condition re iow-pressure turblne disc insp NRC maintains position in SER (NUREO-0797) that insp must be conducted YOUNOBLOOD. B J Licensing Branch i 84/02/28 OARY.R. J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 22763 235 24X Fichs 50-445.84/02/28.8403260069
- 8403140288 Forwards SSER re TM1 Action Plan items 1 C 1 & I C 8 of SER Confirmatory Issue 3 concerning guidance for evaluation & development of procedures for transients & accidents YOUNOBLOOD.8 J Licensing Branch i 84/03/06 GARY, R. J Texas Utilities Electric Co (formerly Texas Utilities Cenerating Co) 6pp 22636 312 24X Fiche 50-445.84/03/06.8403140208
- 8403140293 Provides clarification of NRC favorable findings re SER Confirmatory Issue 11 for TM1 Action Pian I tem 1 g i Util should either commit to perform natural circulation boron mixing test or ref boron mixing test at Diablo Canyon YOUNOBLOOD, B J Licensing Branch i 84/03/06. GARY, R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 22635 333 24X Fiche 50-445.84/03/06.8403140293
- 8403150103 Forwards vibration instrumentation plan Pian closes out SBER 3 Confirmatory Issue C6 re pressure of flow induced tube failure in Model D-4 & D-5 steam generators SCHHIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Schemators College of State of St
- 8403270345 Requests schedule for responding to SER Outstanding Issue 3 re environ qualification of safety-related mechanical equipment in hersh environs & Issue 4 re alternate safe shutdown YOUNGELOOD, B J Licensing Branch i 84/03/13. CARY, R J Texas Utilities Electric Co (formerly Texas Utilities Congrating Co) 4pp 22787 352 24X Fiche 50-445,84/03/13,8403270345
- F Security, medical, emergency & fire protection plans
- B403130116 Forwards proposed guidelines & Rev 1 to proposed objectives for 1983 emergency preparedness field exercise; for review Exercise scheduled for B31214 Comments requested by B30923 JONESR A Taxas Utilities Electric Co (formerly Texas Utilities Generating Co) B3/09/13 MADSEN,O L Region 4, Office of Director 2pp 22601-301, 24X Fiche 50-445, B3/09/13, B403130116

- --8403130126 Proposed guidalines for 1983 emergency preparadness field exercise scheduled for 831214

 » Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 83/09/13 3pp 22601 303 24X
 Fiche 50-445,83/09/13,8403130116
- --8403130136 Rev 1 to proposed objectives for 1983 emergency preparedness field exercise * Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 83/04/12 14pp 22601 306 24X Fiche 50-445.83/09/13.8403130116
- 8403130313 Forwards "NRC Emergency Preparedness Appraisal Items Status Tracking Rept." to aid NRC in preparations for Upcoming appraisal Emergency preparedness planning project organization chart & iist of responsibilities also encl JONES:R A Texas Utilities Electric Co (formerly Texas Utilities Cenerating Co) 83/09/13 MADSEN.9 L. Region 4. Office of Director 6pp 22605 095 24X Fiche 50-445.83/09/13.8403130313
- --B403130319 "NRC Emergency Preparedness Appraisal 1tem Status Tracking Rept "

 * Texas Utilities Electric Co (formerly Texas Utilities Generating Co) B3/09/11 79pp 22605 101 24X Fiche 50-445,83/09/13.8403130313
- 8403260206 Forwards IE Insp Rept 50-445/83-43 on 831114-18 No violations or deviations noted JOHNSON, E H Region 4, Office of Director 84/02/03 QARY, R. J Teras Utilities Electric Co (formarly Texas Utilities Generating Co) 2pp 22756 223 24X Fiche 50-445, 84/02/03, 8403260206
- --8403260214 IE Insp Rept 50-445/83-43 on 831114-18 No violations or deviations noted Major areas inspected protected area, physical barriers vital area, testing & maint & security sys power supply Details withheld (ref 10CRR73 21), CALDHELL:R A , KELLY, J , HUNNICUTT, D M Region 4, Office of Director 84/02/02 ip 22756 225 24X Fiche 50-445,84/02/03,8403260206
- 8403050146 Submits scenario for providing info re emergency preparedness exercise COLLINS.JT Region 4. Office of Director 84/02/09 GARY.R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 22487 312 24X Fiche 50-445,84/02/09,8403050146.
- 8403i30442 Forwards IE Insp Rept 50-445/83-5i on 83i201-840i3i No deviations or violations identified UNN80N.E H Region 4. Office of Director, 84/02/22 QARY,R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co). 2pp 22613 i53 24X Fiche 50-445,84/02/22,8403130442
- --B403130453 1E Insp Rept 50-445/83-51 on 831201-840131 No violations or deviations identified Major areas inspected initial startup procedures review fuel receipt emergency drill & IE bulletin follows

 KELLEY, D L , BMITH, W F , HUNNICUTT, D M Region 4, Dffice of Director 84/02/22 opp 22613 155 24X Fiche 50-445,84/02/22, 8403130442
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT.D 0 Division of Licensing 84/02/23 PALLADIND Commissioners ip 22576 203 24X Fiche 50-000,84/02/23,8402090006
- --B4030B0316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRR OFC Ltr 19.dtd 821001 Further evaluation of test data required VOLLKER.R H Division of Engineering 84/02/06. EISENHUT.D Q Division of Licensing 10pp 22576 204 24X Fiche 50-000.84/02/23.8402090006

G Adjudicatory correspondence

- 8403070177 Motion re summary of cross-examination areas supplied to CYCNA on 840222 Applicants have used thin wall pipe & many instances of min pipe wall violations exist H/M Walsh affidavit Related corespondence ELLIB.J Citirens Association for Sound Energy 84/02/29. Atomic Safety and Licensing Board Panel 4pp 22541:326. 24X Fiche 50-445,84/02/29,8403070177
- ~-B403070181 Affidavit of W Walsh re thin wall pipe Pipe fittings larger than nominal wall thickness assumed by piping designers will increase thermal expansion loads on piping supports & nozzies
 WALSH.M Citizens Association for Sound Energy 84/02/28 4pp 22541 330 24X Fichs 50-445,84/02/29,8403070177.

- --8403070182 Forwards M Walsh affidavit Certificate of Svc encl ELLIS, J Citizens Association for Sound Energy 84/02/29 Docketing & Services Branch 3pp 2254: 352 24X Fichs 50-445,84/02/29,8403070177
- 8403070191 Notifies that no conflict of interest exists in dual representation of Brown & Root & Hutchinson re investigation of CYGNA matter CHARNOFF, 0 Bhau. Pittman, Potts & Trowbridge CHARNOFF, 0 Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/03/01 BLOCH P Atomic 84fety and Licensing Board Panel 3pp 22347 273 24x Fiche 50-445,84/03/01.8403070191
- 8403070126 Notice of appearance in proceeding Certificate of Svc encl PIGOTT, D Cygna Energy Services PIGOTT, D Grrick, Herrington & Sutcliffe B4/03/05 4pp 22575 341 24X Fiche 50-445,84/03/05, 8403090126
- 8403070128 Answer urging rejection of util 840203 plan to respond to ASLB memorandum & order re GA for design ASLB should require 100% reinsp.design verification & mgt audit Certificate of Svc encl.

 ELLIB.J Citizens Association for Sound Energy 84/03/05 Aton Safety and Licensing Board Panel. 19pp 2257i 021 24% Fiche. 50-445.84/03/05.8403090128.
- 8403070097 Memorandum requesting Ofc of Investigations file target dates for completion & release of rept re facility investigations & policy for filing completed repts w/ASLB subj to protective order BLOCH.P B. Atomic Bafety and Licensing Board Panel 84/03/08 ip 22376.001 24X Fiche 50-445,84/03/08,8403070097
- 8403140055 Comments on util plan to respond to 840203 memorandum & order re GA for design Plan supported in part Certificate
- order re GA for design Plan supported in part Certificate of Bvc encl
 MIZUNO.0 S Hearing Branch 1 84/03/07. 17pp 22634 165 24X
 Fiche 50-445.84/03/07.8403140055
- 8403140034 Forwards response to 840305 comments on generic problems & cross-examination questions Exhibits 720-725,706 & 871-701 spc1 Certificate of Svc encl.Related correspondence ELLIB, J. Citizens Association for Sound Energy 84/03/10 HILLIAMS.N H Cygna Energy Services 25pp 22633 021 24X Fiche: 50-445,84/03/10,8403140034
- B403i40013 Confirms agreement to preserve any matls informally requested on discovery re electrical inspectors Related correspondence HORIN. W A Bishop, Liberman, Cook, Purcell & Reynoids HORIN. W A Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) 84/03/12 BLOCH, P B, MCCOLLOM, K A, JORDAN, W H. Atomic Bafety and Licensing Board Panel 1p 22633 225 24X Fiche: 50-445,84/03/12.8403i40013
- 8403140020 Answer to Citizens Assoc for Bound Energy (CABE) 840229 motion re cross-examination areas supplied to CYONA CABE matters inappropriate & irrelevant in context of CYONA rept. M/Certificate of Svc.Related correspondence REYNOLDS, N S., HORIN, W A Texas Utilities Electric Co (formerly Texas Utilities Generating Co.) REYNOLDS, N S. Bishop, Liberman. Cook, Purcell & Reynolds 84/03/12 Atomic Safety and Licensing Board Panel 11pp. 22633 290 24X Fiche. 50-445,84/03/12.
- 8403190024 Beventeenth set of interrogatories & requests to produce to applicante Certificate of 8vc encl Related correspondence ELLIB-J. Citizens Association for Bound Energy. 84/03/12. Texas Utilities Electric Co. (formerly Texas Utilities Cenerating Co.) 9pp. 22666-076 24X Ficher 50-445,84/03/12,8403190024
- 8403190032 Motion for discovery re T-shirt incident. Incident falls under heading of new & significant info re intimidation matters & deemed discoverable Certificate of Svc encl Related correspondence ELLIS. J. Citizens Association for Sound Energy 84/03/12 Atomic Safety and Licensing Board Panel 9pp. 22666 067. 24X Fiche. 50-445.04/03/12.8403190032
- B403150032 Suppl to applicant 840203 plan to respond to memorandum & order re QA for design, discussing ASLB 840224 comments on Walsh/Doyle issues re compliance w/Criteria I & XVI. Ceptificate of Bvc encl Related correspondence REYNGLDS, N B Texas Utilities Electric Co (formerly Texas Utilities Generating Co.), REYNGLDS, N B, Bishop, Liberman, Gook, Purcell & Reynolds 84/03/13 12pp 22643 275. 24X Fiche, 50-445, 84/03/13, 8403150032

- 8403190006 Informs that Insp Rept B3-32 particularly app.Page 6. Items B & C re allegations of undue pressure & restriction & threatening w/firing will be used for cross-examination during hearing Certificate of 8 vc encl ELLIGIJ Citizens Association for Sound Energy B4/03/13 BLOCH.P B , MCCOLLOM.K A , JORDAN.W K Atomic Safety and Licensing Board Panel 9pp 22664 332 24X Fiche 50-445.84/03/13.8403190006
- 8403190148 Forwards Investigation Repts 4-83-001 & 4-83-013 dtd 830824 & i103.respectively Complete & redacted versions encl TREBY.B A Hearing Branch i 64/03/i3 BLOCK.P B., JURDAN.W H., MCCOLLON.K A Atomic Safety and Licensing Board Panel 200pp 22667-001 24X Fiche 50-445.84/03/13.8403[90148
- B403i90iii Notice of appearance in proceeding Certificate of Svc encl BACHMANN.R 0 Hearing Branch 1 84/03/i4 3pp 22666 263 24X Fiche.50-445.84/03/i4.8403i90iii
- 8403190118 Forwards NRC Insp Repts 97700330/84-01 & 50-445/83-52 of CYONA Energy Sycs OA program used during Unit 1 independent assessment program No application to withhold rept received TREBY.8 A Hearing Branch i 84/03/14 8LOCH.PB. JORDAN.W H. MCCOLLUM.K A Atomic Sefety and Licensing Board Panel 23pp 22666 273 24X Fiche 50-445.84/03/14.8403190118
- 8403200026 Eighteenth set of interrogatories & requests to produce to applicants re issue of intimidation harassment & threatening of GC inspectors & other employees Certificate of Svc encl. Related correspondence ELLIS.J Citizens Association for Sound Energy 84/03/14 Texast Utilities Electric Co (formerly Texas Utilities Oenerating Co) 5pp 22699 228 24X Fiche 50-445.84/03/14.8403200026
- B403200126 Nineteenth set of interrogatories & requests to produce to applicant Certificate of Svc encl Related correspondence ELL19.J Citizens Association for Sound Energy 84/03/i4. Ilpp 22679 067 24X Fiche 50-445.84/03/i4.8403200126
- 8403170002 Memorandum clarifying open listed issues re GA program BLDCH.P B . JORDAN.H H . MCCOLLOM.K A Atomic Safety and Licensing Board Panei 84/03/15 2ipp 22664 326 24X fiche 50-445, 84/03/15.8403170002
- B403i9002B Memorandum ordering Ofc of Investigations to file-by B40329, affidavits responsive to ASLP concerns re observation of interviewees Applicants should file affidavits stating' results of investigation by B404i1
 BLOCH.P B Atomic Safety and Licensing Board Panei B4/03/13 2pp 22665 360 24X Fiche 50-445,84/03/15.8403i9002B
- 8403200009 Requests to be informed about requested supplementation of answers to interrogatories & requests to produce Related correspondence ELLIS, J Citizens Association for Sound Energy 84/03/15 REYNOLDSN S Bishop, Liberman, Cook, Purcell & Reynolds ip 22685 202 244 Fiche 50-445,84/03/15,8403200009
- 8403200012 Advises that listed documents will be used in crossexamination of NRC staff witnesses on welding Related correspondence ELLIS.J Citizens Association for Gound Energy 84/03/15 TREBY. B., MIZUNG.O.B. Office of the Executive Legal Director ip 22483 357 24X Fiche 50~445,84/03/15,8403200012
- 8403200025 Forwards further responses from Waish re Cygna 840313 responses to Citizens Assoc for Sound Energy Certificate of Svc encl Related correspondence ELLIS, J Citizens Association for Sound Energy 84/03/15 P100TT, D R. Orrick. Herrington & Sutcliffe 5pp 22699 223 24x Fiche 50-445,84/03/15,8403200025
- 8403200049 Requests ABLB advise if motion for admission of encl two pages re nonconformance repts concerning handwritten/
 typewritten discrepancies would be entertained at present Related correspondence
 ELLIB, J Citizens Association for Sound Energy 84/03/15
 BLOGH, P B , MCCOLLON, K A , JORDAN, W. H Atomic Safety and Licensing Board Panel 4pp 22698 287 24X Fiche 50-445.84/03/15.8403200049
- 8403200073 Requests listed documents for 18th & 20th sets of interrogatories Certificate of Svc encl Related correspondence ELLIS.J Citizens Association for Sound Energy 84/03/15 REYNOLDS.N S , HORIN.D Bishop, Liberman, Cook, Purcell & Reynolds 1p 22684 362 24X Fiche 50-445.84/03/15.8403200073
- B403200114 Discusses supplementation of answers to interrogatories & requests to produce re T-shirt incident Applicants have history of being uncooperative re discovery matters Related correspondence ELLIB.J. Citizens Association for Sound Energy B4/03/15 BLOCH.P.B. JURDAN.W H. MCCOLLOM.K A. Atomic Safety and Licensing Board Panel Spp. 22685-327 24X Fiche 50-445.84/03/15,8403200114

- 8403200118 Twentieth set of interrogatories & request to produce to applicant Certificate of Svc encl Related correspondence ELLIS.J Citizens Association for Bound Energy 84/03/15 Texas Utilities Ejectric Co (Formerly Texas Utilities Generating Co) 8pp 22685 344 24X Fiche 50-445,84/03/15,8403200118
- B403200147 Forwards Citizens Assoc for Sound Energy Exhibit 927,
 "Formulas for Stress & Strain," omitted from 840313 ltr
 W/o encl Related correspondence
 ELLIS.J Citizens Association for Sound Energy.
 B4/03/15
 PIGOTY.D R Orrick, Herrington & Sutcliffe ip 22699 138 24X
 Fiche 50-445.84/03/15.8403200147
- 8403210102 Forwards IE Insp Repts 50-445/83-47 & 50-446/83-22 W/o encls Related correspondence
 TREBY.S A Hearing Branch 1 84/03/16 BLDCH.P 8 . JDRDAN.W H .
 MCCOLLOM.K A Atomic Safety and Licensing Board Panel 19
 22706 117 24X Fiche 50-445,84/03/16.8403210102
- 8403200065 Notice that evidentiary hearing scheduled for 840423-27 rescheduled for 840424-27 in Fort Worth.TX BLOCH.P B Atomic Safety and Licensing Boarf Panel 84/03/19. ip 22684 361 24X Fiche 30-443.84/03/19.8403200065
- 8403270031 Requests that MD Spence be substituted for RJ Gery on sycists Related correspondence
 REYNOLDS.N S Bishop. Liberman. Cook. Purcell & Reynolds
 REYNOLDS.N S Texas Utilities Electric Co (formerly Texas Utilities
 Generating Co) DSB 118 84/03/19 CLEMENTS.W L Docketing &
 Services Branch. 1p 22769 327 24X Fiche 50-445.84/03/19.
 8403270031
- 8403280337 Responds to ASLB 840308 memorendum re schedule & policy of OPC of Investigation Policy re release of repts to ASLB Includes review of rept & deletions to protect Identity of confidential sources

 MAVES.B B Office of Investigation DSB 157 84/03/21

 MCCDLOM.K A . BLBCH.P B . JORDAN.H H Atomic Sefrey and Licensing Board Panei . 2pp 22787 097 24X Fiche 50-445.84/03/21.8403280339
- 8403280342 Memorandum & order releasing transcript of 840221 in camera tessions & applicant memo re release of transcript as part of public record of proceeding BLOCH.P B Atomic Safety and Licensing Board Panel DSB 150 84
- H General correspondence
- 8403270173 Requests that name be placed on malling list for matis issued in facility OL & iE monitoring process GARDE.B P Government Accountability Project 84/03/19 8URWELL,S Office of Nuclear Reactor Regulation, Director ip 22771 137 24X Fiche 50-445,84/03/19,8403270173
- B403230059 Designetes MD Spence as recipient of official correspondence pertaining to facilities CLEMENTS, B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co). 84/03/20 DENTON, H R Office of Nuclear Reactor Regulation, Director Ip 22726 227 24X Fiche 50-445, 84/03/20, 8403230059
- G inspection reports. IE Bulletins & correspondence
- B403080324 F0iA request for documents considered by NRC in preparetion of notice of violation & proposed imposition of civil penalty, 831222 itr transmitting violation & rept of investigation re intimidation of QA personnel HARYMAN. S. L. Debevoise & Liberman 83/12/30 FELTON, J.M. Division of Rules and Records 2pp 22583 169 24X Fiche 50-445, 83/12/30, 8403080324.
- 8403080325 Partial response to FOIA request for documents considered by NRC in preparation of three categories of documents concerning facilities Forwards documents listed on App A FELTON, J M Division of Rules and Records 84/01/20 HARTMAN, B L Debevoise & Liberman 2pp 22583 171 24X Fiche 50-445, 84/01/20, 8403080325
- --8403080327 Rev 27 to Procedure GI-OP-il 4-5 re visual defects insp & fry film thickness Releted info encl to Texas Utilities Co (formerly Texas Utilities Generating Co 1. 83/11/08. 6pp 22583 173 24X Fiche 50-445,84/01/20,8403080325
- --8403080332 Describes commitments made to NRC in RJ Dary 830928 response to notice of violation & proposed imposition of civil penalty CLEMENTS, B Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 83/11/29 COLLING, J T Region 4, Office of Director lipp 22583 182 24X Fiche 50-445,84/01/20,8403080325

- --B4030B0333 Notification of significant licensee meeting on B3i212 w/
 util in Ariington.TX to discuss potential enforcement action
 re intimidation of employees by H Williams
 * Region 4, Office of Director B3/12/08 Region 4, Office of
 Director 1p 22583 193 24X Fiche 50-445,84/0i/20,8403080325
- --8403080335 Forwards rept re investigation into allegations made by WA Dunham & concerns related to protective coatings Related documents encl
 GARY,R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 83/12/13 CQLLING/J Region 4, Office of Director 22pp 22583 204 24X Fichs 50-445,84/01/20,8403080325
- 8403260206 Forwards IE insp Rept 50-445/83-43 on 831114-18 No violations or deviations noted JOHNSON-E H Region 4, Office of Director 84/02/03 QARY,R J Texes Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 22756 223 24X Fiche 50-445,84/02/03,8403260206
- --8403260214 IE Insp Rept 50-445/83-43 on 831114-18 No violations or deviations noted Major areas Inspected protected area, physical barriers vital area; testing & maint & security sys power supply Details withheld (ref iOCFR73,21) CALDWELL: A A . XELLY. J . HUNNICUTT. D. M. Region 4, Office of Director 84/02/02 lp 22756 225. 24X Fiche 50-445,84/02/03,8403260206
- 8403040180 Forwards IE insp Rept 50-445/84-01 on 840123-27 No violetions or deviations identified JUHNSUN.E H Region 4, Office of Director 84/02/17 QARY,R J Texes Utilities Electric Co (formerly Texes Utilities Generating Co) 2pp 22519 012 24X Fiche 50-445/84/02/17,8403040180.
- --B403060184 iE Insp Rept 50-443/84-01 on B40123-27. No violations or deviations identified Major ereas Inspected licensee chemistry/radiochemistry programs Including primery chemistry programs.callbr & GC & corporate GA program. NICHDLAS. J B . WISE. R . MURRAY. B Region 4. Office of Director B4/02/17 20pp 22519.014 24X Fiche 50-445.84/02/17.8403060180
- 8403060371 Forwards IE insp Rept 50-445/83-52 on 831220-840130 No violations or devictions noted JOHNSDN.E H Region 4, Office of Director 84/02/21 QARY,R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 22511 315 24X Fiche 50-445,84/02/21,8403660371
- --8403060373 iE insp Rept 50-445/83-52 on 831220-840130 Major areas inspected alleged poor electrical cable tray clamping practices Concerns re poor const practices unsubstantiated, OBERGO. C R. HUNNICUTT, D M. Region 4. Office of Director. 84/02/17 6pp 22511 317 24X Fiche 50-445.84/02/21,8403060371
- 8403130442 Forwards IE Insp Rept 50-445/83-51 on 831201-840131.No deviations or violations identified JOHNSON.E H Region 4. Office of Director 84/02/22 GARY,R J Texes Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 22613 i33 24X Fiche 50-445.84/02/22,8403130442.
- --8403130453 1E Insp Rept 50-445/83-51 on 831201-840131 No violations or deviations identified Major areas inspected initial startup procedures review, fuel receipt emergency drill & IE bulletin followup KELLEY, D. L., SMITH, W.F., HUNNICUTT, D.M., Region 4, Office of Director 84/02/22 opp 22613 155 24X Fiche 50-445,84/02/22,8403130442
- 840305043i Requests eddl info re ultresonic exam of cast stainless steel piping in RCPB es part of preservice insp program Response requested within 5 days of itr receipt YOUNGBLOOD, B J Licensing Branch i 84/02/24 QARY, R, J Texas Utilities Electric Co (formerly Texas Utilities Generating Co.). 3pp 22552 047 24% Fiche 50-445,84/02/24,8403060431
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Veive Control Circuits & Annunciation " Svc iist encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, inc. 115pp 22909 239 24X Fiche. 50-000, 84/02/28, 8401190072.
- 8403130183 Forwards IE Insp Repts 50-445/83-47 & 50-446/83-22 on 830801-840117 No violations or deviations noted JDHNSDN.E H Region 4. Office of Director 84/02/28. GARY,R.J. Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 22607 127 24X Fiche: 50-445, 84/02/28, 8403130183
- --8403130219 IE Imsp Repts 50-445/83-47 & 50-446/83-22 on 830801-840117
 No violations or deviations noted Major areas inspected
 issues before ABLB hearing board
 TAYLOR.R 0 , HUNNICUTIO M Region 4, Office of Director,
 84/02/28 6pp 22607 131 24X Fiche 50-445,84/02/28,8403130183

- 8403260069 Forwards evaluation of 830718 request for deletion of steam electric station license condition re low-pressure turbine disc insp NRC maintains position in SER (NUREG-0797) that insp must be conducted YOUNOBLOOD. B J Licensing Branch 1 84/02/28 OARY.R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 22763 235 24% Fiche 50-445.84/02/28,8403260069
- --8403240081 Evaluation of util 830718 request to delete turbine disc insp license condition UT insps required at first refueling & every subsequent refueling outage * NRC - No Detailed Affiliation Given 84/02/28 19pp 22763 237 24X Fiche 50-445,84/02/28.8403260069
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Evc list encl GRACE.J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 840209000B IE Info Notice B4-16, "Failure of Automatic Sprinkler Sys Valvas to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svr List encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche. 50-000, 84/03/02, 8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductitity Temp " Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,840209001i
- 8402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Bafe Bhutdown Sys " Svc list enc! JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- B402090028 IE Info Notice 84-i8, "Stress Corrosion Cracking in PWR Bys " Byc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp. 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403190406 Informs that no insp repts will be issued for Rept Numbers 50-445/83-41 & 50-446/83-25
 JOHNSON,E H Region 4, Office of Director B4/03/07 GARY,R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co.) ip 22674 357 24X Fiche 50-445,84/03/09,8403190406
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Bys " Svc list enc!
 DEYOUNG, R C. Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8403190118 Forwards NRC Insp Repts 99700330/84-01 & 50-445/83-52 of GYONA Energy Svcs GA program used during Unit 1 independent assessment program No application to withhold rept received TREBY, B A Hearing Branch 1 84/03/14 BLOCH, P B , JURDAN, H H , MCCOLLOH, K. A Atomic Safety and Licensing Board Panel 23pp 22666; 273 24X Fiche 50-445,84/03/14,8403190118
- 8403200125 Forwards vendor insp repts for info & action Repts identify concerns found by Vendor Program Branch during insps of vendor activities Ack of itr receipt requested JOHNSON.E H Region 4, Diffice of Director 84/03/16 GARY,R J Texas Utilities Electric Co (formarly Texas Utilities Generating Co). 3pp 22699 173 24X Fiche.50-445,84/03/16,8403200125
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities "Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21.8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related 8ys " Svc list encl JDRDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044

- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKE.W J Office of the Executive Director for Operations
 84/02/21 PALLADINO Commissioners 9pp 22492 083 24X
 Fiche 50-000.84/02/21.8403020443
- S Reportable occurrences. LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency dissel generators mfg by Transamerica Delavel. Inc DIRCKS. W Office of the Executive Director for Operations SECY-83-034 B4/01/25 4pp 22438 347 24X Fiche 50-000,84/01/25.
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BWR plants
 THERDUX.R R Terry Carp 84/02/22 WODDRUFF, R W Director's Office, Office of Inspection and Enforcement App 22704 327 24X Fiche 50-000, 84/02/22, 8403210032
- 8403070236 Followup Part 21 rept re defective mechanical snubber capstan springs supplied by Pacific Scientific Affected utils listed Purchasers have been notified & advised to work directly w/Pacific Scientific in disposition MOVI.L NPS Industries, Inc. 84/02/24 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 2pp 22336 279 24% Fiche 50-000.84/02/24.8403070236
- 84030i0207 Forwards "Investigation of Types AF & AE Piston Skirts," por Transamerica Delaval, Inc Owners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations
 MUSELER,W J TDI (Transamerica Delaval, Inc.) Guners Oroup
 84/02/27 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 3pp 22434 070 24X Fiche 50-000, 84/02/27,8403010207
- 8402090021 Board Notification 84-039 discusses NRC 840210 & 16 meetings w/Transamerica Delavel, Inc Emergency Diesel Generators Owners Group Heeting scheduled on 840308 for finalization of generic program plan prior to NRC review EISENHUT, D © Division of Licensing 84/02/28 PALLADIND Commissioners 5pp 22546 003 24% Fiche 50-000,84/02/28, 8402090021
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc. emergency diese) generators MUSELER.W J TD1 (Transamerica Delaval, Inc.) Owners Group 84/02/28 DENTON.H R Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Fiche 50-000.84/02/28.8403010218
- B402070020 Board Notification 84-044 forwards Part 21 rept re Transamerica Delaval. Inc turbocharger thrust bearing Inbrication defect resulting in engine nonavailability EIBENHUT.D G Division of Licensing 84/02/29 FALLADINO Commissioners 4pp 22541 243 24X Fiche 50-000,84/02/29, 8402090020
- 840314004B Forwards "Orand Oulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delavai.Inc Diesel Generators Guners Group Program Plan," to resolve Concerns w/emergency diesel generators MUSELER.W J Long Island Lighting Co 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22626 062 24X Fiche 50-000.84/03/02,8403140048
- --8403140095 "Transamerica Delaval, Inc Diesel Generators Guners Group Program Plan " * TDI (Transamerica Delaval, Inc.) Guners Group 84/03/02 261pp 22628 223 24X Fiche, 50-000, 84/03/02, 8403140048
- 8403160213 Interim Deficiency Rept BDAR-125 re laminations & delaminations in cable tray support column in cable spread room. Initially reported on 840111 Evaluation continuing Completion expected by 840515

 GARY.R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/03/04 JOHNSON.E H Region 4. Office of Director ip 22655 231 24X Fiche. 50-445, 84/03/06, 8403160213
- 8402090033 Board Notification 84-047 forwards Transamerica Delaval.inc Owners Group piston skirt rept & task descriptions EIBENHUT.D G Division of Licensing 84/03/07 PALLADINO Commissioners 4pp 22674 221. 24X Fiche 50-000.84/03/07. 8402090033

- 8402090038 Board Notification 84-051 forwards "Transamerica Delaval.Inc (TDI) Diesel Generators Owners Group Program Plan "
 EISENHUT.D G Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22888 214 24% Fichs 50-000,84/03/12, BADDERGORD
- 8402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delayal, Inc (TDI) Owners Group Distribution list enci EISENHUT: D 9 Division of Licensing 84/03/12 PALLAOINO Commissioners 5pp 22708 001 24% Fiche 50-000, 84/03/12, 8402070039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Gumers Group in Bethesda.MD re problems w/emergency
 diesel generators
 CARUSD.R Licensing Branch 2 84/02/27 0'REILLY, J P NRC No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000.84/03/12.8402070039
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators # NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fiche 50-000,84/03/12,8402090039
- --8403070409 Summary of B40216 meeting W/Transemerica Delaval, Inc Cumers Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl MILLER, M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 2270B 161 24X Fiche 50-000, B4/03/12, 8402090039
- --8403070423 Transcript of 840216 conference in Wading River.NY re Transamerica Belaval. Inc dissel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Ficha 50-000.84/03/12.8402090039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Bhoreham & Grand Gulf diesel generators MUSELER,W J Lang Island Lighting Co 84/03/12 DENTON, H R Office of Nuclear Regulation, Director 2pp 22632 074 24X Fiche 30-000,84/03/12,8403140050
- 8403150133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & swc conditions HUSELER, H J TD1 (Transamerica Delava), Inc) Owners Group 84/03/13 DENTON: H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000,84/03/13,8403150133
- 8403200222 Responds to 840214 Requests for Info i & 2 re R-4 series engines List indicating engine number model & syc number, customer name & address rating date shipped & date started enct
 MATHEMS, C B Transamerica Delaval, Inc. 84/03/16 EISENHUT, D Q
 Division of Licensing 20pp 22691 179 24X Fiche 50-000,84/03/16,8403200222
- 8403270132 Forwards "Emergency Diesel Generator Air Btart Valve Capscrew Dimension & Stress Analysis," prepared by 58M for Transamerica Delaval, inc (TDI) Diesel Generator Owners Group MUSELER, N J TDI (Transamerica Delaval, inc.) Owners Group 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22774 001 24% Fiche 50-000, 84/03/23, 8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delaval diesel generators List of suggested meeting topics encl MCOAUGHY. J. P. TD1 (Transamerica Delaval, Inc.) Owners Group 84/03/23 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 4pp. 22769 133 24X Ficha 50-000 84/03/23, 8403270134
- T. Hearing transcripts on non-antitrust matters
- 8403020145 Transcript of 840228 telephone conference in Bethesda, MD Pp 10:350-10:383 * Abonic Safety and Licensing Board Panel, 84/02/28 35pp 22440 275 24X Fiche 50-445, 84/02/28, 8403020145.
- 8403090104 Forwards correction to J Doyle 840222 testimony Related correspondence ELLIG.J Citizens Association for Sound Energy 84/03/05 ELOCHEP B. JORDON, W.H., MCCOLLOH.K.A. Atomic Safety and Licensing Board Panel 1p 22576 OBI. 24X Fiche 50-445.84/03/05.8403090104

- --8403090108 Affidavit of J Doyle, correcting 840222 testimony during cross-examination of CYGNA Certificate of Svc encl DOVLE, J Citizens Association for Sound Energy 84/03/03 7pp 22876 082 24X Fiche 50-445,84/03/05.8403090104
- B402070039 Board Notification B4-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Umners Group Distribution list encl EISENHUT, D G Division of Licensing B4/03/12 PALLADING Commissioners Spp 22708 OOI 24% Fiche 50-000,84/03/12, 8402090039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Dwners Group in Bethesda.MD re problems w/emergency
 diesel generators
 CARUSO.R Licensing Branch 2 84/02/27 D'REILLY, J P NRC No
 Detailed Affiliation Given App 22708 006 24X
 Fiche 50-000,84/03/12.8402090039
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Sethesda. MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10, 147pp A7201 008 24X Ficha 50-000,84/03/12,8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval. Inc Owners Group in Mading River.NY re program plan to establish reliability of diesel generators Agenda.meeting transcript & attendance list encl MILLER.M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24% Fiche 50-000.84/03/12.8402090037
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval, Inc. diesel generators Pp. 1-82 * Commissioners 84702716. 84pp. 22708 169 24X Fiche 50-000,84703/12,8402090039
- 8403260008 Transcript of 840319 hearing in Fort Worth,TX Pp 10,384-10,713 * Atomic Bafety and Licensing Board Panel 84/03/19 340pp 22747 001 24X Fiche 50-445,84/03/19,8403260008
- 8403270167 Transcript of 840321 hearing in Fort Worth,TX Pp 11,019-11,318 * Atomic Safety and Licensing Board Panel 84/03/21 349pp 22774 150 24X Fiche 50-445.84/03/21,8403270167
- 8403270082 Transcript of 840322 hearing in Fort Worth, TX Pp 11,337-11,710. * Atomic Safety and Licensing Board Panel 84/03/22 373pp 22765 009 24X Fiche 50-445,84/03/22,8403270082
- B403280021 Transcript of 840323 hearing in Fort Worth, TX Pp 11,711-11,998 * Atomic Safety and Licensing Board Panel 84/03/23 300pp 22777 173 24X Fiche 50-445,84/03/23,8403280021

V Operator Examinations

- 8403130160 Forwards nuclear plant experience tables for shift advisors, shift supervisors, assistant shift supervisors, reactor operators & shift technical advisors Expected OL & fuel load dates are 840701
 CLEMENTG. B R Texas Utilities Electric Co (formerly Texas Utilities Operating Co) 84/03/08 DENTON.H,R Defice of Nuclear Reactor Regulation Director Spp 22608 238 24% Fiche 50-445,84/03/08.8403130160
- DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA , UNIT 2

 A Application/construction stage documents & correspondence
- 8401120425 Forwards Amend 7 to CPPR-126 & CPPR-127.safety evaluation & notice of issuance & availability Amend reflects change in ownership of facilities EISENHUT, D © Division of Licensing 83/12/30 OARY, R. J Texas Utilities Electric Co (formerly Texas Utilities Generating Co). 3pp 22210 343 24X Fichs 50-445.83/12/30.8401120425
- --8401120428 Amend 7 to CPPR-126 & CPPR-127, reflecting change in ownership of facilities EISENHUT, D Q Division of Licensing, 83/12/30 4pp. 21804 341 24% Fiche 50-445.83/12/30,8401120425
- --8401120433 Safety evaluation supporting Amend 7 to CPPR-126 & CPPR-127.

 * Office of Nuclear Reactor Regulation, Director 83/12/29. 3pp.
 21804 338 24% Fiche 50-445,83/12/30,8401120425

- ~-8401120437 Notice of issuance & availability of Amend 7 to CPPR-126 & CPPR-127 CPPR-127 YOUNGBLOOD.B J Licensing Branch 1 83/12/29 3pp 21804 348 24X Fiche 50-445,83/12/30,8401120425
- 8403040155 Requeste exemption from provisions of GDC 4 requiring protection of structure, sys & components against certain dynamic effects associated w/postulated breaks in RCS primary loop, per Generic Ltr 84-04 GARY, R. J Fexas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/02/17 YDUNGBLOOD, B J Licensing Branch 1 4pp 22513 351 24X Fiche 50-445,84/02/17,8403040155
- 8403020148 Forwards, for review, draft environ protection plan proposed HOGO20148 Forwards, for review, or ert environ provection, plan prof-for App B to plant OLs YOUNGBLOOD, B J Licensing Branch 1 84/02/21 GARY, R J Texa Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 22491 157 24X Fiche 50-445, 84/02/21, 8403020148
- --8403020152 Environ protection plan (nonradiological) for facility. App B # NRC ~ No Detailed Affillation Given 84/02/21 15pp 22491 159 24X Fiche 50-445,84/02/21,8403020148
- B403050273 Requests provision of alternative surveillance to replace requirement presently in Tech Specs re turbine overseed protection Proposed alternative mainticalibr & testing protection Proposed alternative maintrealist & testing program should assure that protection sys operable YOUNOBLOOD B J Licensing Branch 1 84/02/27 GARY,R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 4pp. 22501 107 24X Fiche 50-445.84/02/27.8403050273
- 8403060277 Informs NRC that Nuclear Utll Task Action Committee completed final draft of rept defining appropriate vendor interface program discussed in Generic Ltr 83-28 Final rept scheduled to be released by Apr 1984
 BCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/02/27 EISENHUT, D Office of Nuclear Reactor Regulation, Director ip 22515,362 24X Fiche. 50-445,84/02/27,8403060277
- 8403070308 Forwards request for add1 info re leak-before-break analysis & fracture toughness of piping matls under thermal aging conditions Submittal date requested within 5 days of itr receipt
 YOUNGBLODD B J Licensing Branch 1 84/03/02 GARY,R J Texa
 Utilities Electric Co (formerly Texas Utilities Generating Co)
 4pp. 22584 338 24X Fiche 50-445.84/03/02,8403090308 receipt
- B403160079 Forwards Suppl 1 to "Human Factors Control Room Design Review," final rept GARY.R.J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) B4/03/08 YOUNGBLOOD, B J Licensing Branch 1 1p. 22634 001 24X Fiche 50-445,84/03/08,8403160079
- --8403140083 Buppi 1 to "Human Factors Control Room Design Review." final rspt. # Taxas Utilities Electric Co (formerly Texas Utilities Generating Co). 84/03/31 122pp 22654 002 24X Fiche 30-445,84/03/08,8403160079
- B402090041 Board Notification B4-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D 0 Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000,84/03/14,8402090041
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents. App B document sntirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERSON, S I Carvey, Echubert, Adams & Barer 7pp 22583, 226 24X Fiche: 50-000, 84/02/13, 8403080179.
- --8005130793 Provides status of BER inputs & acceptance reviews for UL & CP applications. Schedule should be met, BURKE, W C. Effluent Treatment Systems Branch 80/02/06 KREGER. W E. Assistant Director for Site Analysis ip 22583 235 24X Fiche. 50-000, 84/02/13, 8403080179.
- 8403020289 Forwards resolution of SER Confirmatory Issue 11 re 830218 & 0316 submittals concerning TMI Action Items I.C.2 & 83021B & 0316 submittals concerning (n) Action feems 1.0.2 & I.C.5.
 YDUNGBLOOD, B. J. Licensing Branch 1 84/02/21 QARY, R. J. Texast Utilities Electric Co. (formerly Texas Utilities Generating Co.) 3pp. 22472 241 24X Fiche 50-445, 84/02/21, 8403020289

- 8403260069 Forwards evaluation of 830718 request for deletion of NG328006Y Forwards evaluation of 830/18 request for deletion or steam electric station license condition re lumpressure turbine disc insp NRC maintains position in SER (NUREG-0797) that insp must be conducted YOUNOBLOOD, B.J. Licensing Branch 1 84/02/28 GARY, R.J. Texa-Utilities Electric Co. (formerly Texas Utilities Generating Co.) 2pp 22763 233 24X Fichs 30-445.84/02/28.8403280069
- 8403140288 Forwards SSER re TM1 Action Plan Items I C i & I C 8 of SER Confirmatory Issue 5 concerning guidance for evaluation & development of procedures for transients & accidents YOUNOBLOOD, B J Licensing Branch 1 84/03/04 GARY, R J Texas Utilities Electric Co (formerly Texas Utilities Conserating Co) 6pp 22636 312 24X Fiche 50-445,64/03/04,6403140288
- 8403140293 Provides clarification of NRC favorable findings re SER Confirmatory Issue 11 for TM1 Action Plan Item I G 1 Util should wither commit to perform natural circulation boron mixing test or ref boron mixing test at Diablo Canyon YOUNGBLOOD, B J Licensing Branch 1 84/03/06 GARY, R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 22635 333 24X Fiche 50-445.84/03/06,8403140293
- 8403270345 Requests schedule for responding to SER Outstanding Issue 3 re environ qualification of safety-related mechanical equipment in harsh environs & Issue 4 re alternate safe shutdown YOUNOBLODD,B J Licensing Branch 1 84/03/13 GARY.R J Texa Utilities Electric Co (formerly Texas Utilities Generating Co) 4pp 22787 352 24X Fiche 50-445.84/03/13.8403270345
- F Security, medical, emergency & fire protection plans
- 8403130114 Forwards proposed guidelines & Rev 1 to proposed objectives roused a rowards proposed guidelines & Rev 1 to proposed objective for 1993 emergency preparedness field exercise, for review Exercise scheduled for 831214 Comments requested by 830923 JUNES, R A Toxas Utilities Electric Co (formerly Texas Utilities Querenting Co) 83/09/13 MADSEN, G L Region 4, Office of Director 2pp 22601.301 24X Fiche 50-445,83/09/13,8403130116
- --B403130126 Proposed guidelines for 1983 emergency preparedness field exercise scheduled for B31214 # Texas Utilities Electric Co (formerly Texas Utilities Generating Co) B3/09/13 3pp 22401 303 24X Fiche 50-445,83/09/13.8403130116
- --8403130136 Rev 1 to proposed objectives for 1983 emergency preparedness field exercise

 * Texas Utilities Electric Co (formerly Texas Utilities
 Ownerating Co) 83/04/12 14pp 22601 306 24X
 Fiche 50-445,83/09/13,8403130116
- 8403130313 Forwards "NRC Emergency Preparedness Appraisal Items Status Tracking Rept," to aid NRC in preparations for upcoming appraisal Emergency preparedness planning project organization chart & list of responsibilities also encl. JONES, R A Texas Utilities Electric Co (formarly Texas Utilities Coenerating Co 9 33/09/13 MADEN, O L Region 4, Office of Director 6pp 22605.095 24X Fiche 50-445.83/09/13.8403130313
- --8403130319 "NRC Emergency Preparedness Appraisal Item Status Tracking Rept "
 # Taxas Utilities Electric Co (farmerly Texas Utilities
 Generating Co) 83/09/11 79pp 22605 101 24X
 Fiche 50-445,83/09/13,8403130313
- 8403050146 Submits scenario for providing info re emergency preparedness exercise
 COLLING.J T Region 4. Office of Director B4/02/09 QARY.R J
 Texas Utilitles Electric Co (formerly Texas Utilitles Generating
 Co) 2pp 22487 312 24X Fiche 50-445.84/02/09,8403050146
- 8402090006 Board Notlfication 84-034 forwards R Vollmer 840206 memo to Positives some notification server reverse K verimer Beautiful Electrical cabinets in control room
 Ele
- --8403080316 Recommends that info re fire research results concerning voluments that into the fire feet research results that fires in electrical cabinets in control room be submitted for board notification.per NRR Ofc Ltr 19, dtd 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT, D. Q Division of Licensing 10pp 22576 204 24X Fichs 30-000,84/02/23,8402090006

G Adjudicatory correspondence

- 8403070177 Motion re summary of cross-examination areas supplied to CYONA on 840222 Applicants have used thin wall pipe & many instances of min pipe wall violations exist. W/M Walsh affidavlt Related corespondence ELLIS.J Citizens Association for Sound Energy 84/02/29 Atomic Safety and Licensing Board Panel 4pp 22541 326 24X Fiche: 50-445, 84/02/29, 8403070177
- ---B4030701B1 Affidavit of W Walsh re thin wail pipe.Plpe fittings larger than nominal wall thickness assumed by piping designers will increase thermal expansion loads on piping supports & norzles WALSHIM Citizens Association for Sound Energy. B4/02/28 4pp 22541 330 24X Fiche 50-445,B4/02/29.B403070177
- --B403070182 Forwards M Walsh affidavit Certificate of Svc encl ELLIS.J Cltizens Association for Sound Energy 84/02/27 Docketing & Services Branch 3pp 22541 352 24X Fiche 50-445,84/02/27,8403070177
- 8403070191 Notifies that no conflict of interest exists in dual representation of Brown & Root & Mutchinson re investigation of GYONA matter CHARNOFF, O Shaw, Pittman, Potts & Trowbridge CHARNOFF, O Texas Utilities Electric Co (formerly Texas Utilities Generating Co). 84/03/01 BLOCH, P Atomic Safety and Licensing Board Panel 3pp 22547.273 24X Fiche 50-445,84/03/01.8403070191
- 8403090126 Notice of appearance in proceeding Certificate of Syc enci PIOOTT.D Cygna Energy Services PIGOTT.D. Orrick, Herrington & Sutcliffe 84/03/05 4pp 22575 341 24X Fiche 50-445,84/03/05, 8403090196
- 8403090128 Answer urging rejection of util 840203 plan to respond to ASLB memorandum & order re GA for design. ASLB should require 100% reinsplessign verification & mpt audit Certificate of Syc enci ELLIB.J Citizens Association for Sound Energy 84/03/05 Atom Eafety and Licensing Board Panel 19pp 22571 021 24% Fiche 50-445.84/03/05.8403070128
- 8403090099 Memorandum requesting Ofc of Investigations file target dates for completion & release of rept re facility investigations & policy for filing completed repts w/ASLB subj to protective order BLOCH.PB Atomic Safety and Licensing Board Panel 84/03/08 1p 22576 001 24X Fiche 50-445.84/03/08.8403090099
- 8403i40055 Comments on util plan to respond to 840203 memorandum & order re GA for design Plan supported in part Certificate
- of Svc encl
 MIZUND. G B Hearing Branch 1 84/03/09 17pp 22634 165 24X
 Fiche 50-445.84/03/09,8403140055
- 8403140034 Forwards response to 840305 comments on generic problems & cross-examination questions Exhibits 720-725, 706 & 891-701 enci Certificate of Svc enci Related correspondence ELLIS.J Citizens Association for Sound Energy B4/03/10 WILLIAMS,N H Cygna Energy Bervices 25pp 22633.021 24X Fiche 50-445.84/03/10.8403140034
- 8403140013 Confirms agreement to preserve any matls informally requested on discovery re electrical inspectors Related correspondence
 HGRIN.W A Bishop, Liberman, Cook, Purcell & Reynolds HORIN.W A Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/03/12 BLOCH.P B, MCCGLLOM.K A, JORDAN.W H Atomic Safety and Licensing Board Panel 1p 22633 225 24X Fiche 50-445,84/03/12,8403140013
- 8403140020 Answer to Citizens Assoc for Sound Energy (CABE) 840229 motion re cross-examination areas supplied to CYGNA CABE matters inappropriate & irrelevant in context of CYGNA rept W/Certificate of Evc Related correspondence REYNOLDS,N S , HORIN.W A Texas Utilities Electric Co (formerly Texas Utilities Generating Co) REYNOLDS,N S Bishop, Liberman, it & Reynolds 84/03/12 Atomic Safety and Licensing 1ipp 22633 290, 24X Fiche 30-445,84/03/12.
 - eventmenth set of interrogatories & requests to produce to Certificate of Evc and Related correspondence litizens Association for Sound Energy 84/03/12 Texas lectric Co (formerly Texas Utilities Generating Co), 076 24X Ficher 50-445,84/03/12,8403190024

- 8403190032 Motion for discovery re T-shirt incident Incident falls under heading of new & significant info re intimidation matters & deemed discoverable. Certificate of Svc encl Related correspondence
 ELLIB.J Citizens Association for Sound Energy 84/03/12 Atomic Safety and Licensing Board Panel 9pp 22666 067 24X Fichs 50-445,84/03/12,8403190032
- 8403150032 Suppl to applicant 840203 plan to respond to memorandum & order re QA for design, discussing ASLB 840224 comments on Waish/Doyle Issues re compliance w/Criteria I & XVI Cartificate of Svc encl Related correspondence REYNOLDS,N S Teras Utilities Electric Co (formerly Texas Utilities Centrating Co) REYNOLDS,N S Bishop, Liberman, Cook, Purceli & Reynolds 84/03/13 12pp 22643 275 24X Fiche 50-445,84/03/13,8403150032
- 8403190006 Informs that Insp Rept 83-52, particularly app, Page 6. Items B & C re allegations of undue pressure & restriction & threatening w/firing will be used for cross-examination during hearing Certificate of Bvc enc! ELLIS.J Citizens Association for Sound Energy 84/03/13 BLOCHAP B, MCGCLLOM.K A, JORNAN,W W Atomic Safety and Licensing Board Panel 9pp 22664 332 24X Fiche 50-445,84/03/13,8403190006
- 8403190148 Forwards Investigation Repts 4-83-001 & 4-83-013 dtd 830824 & 1103, respectively Complete & redacted versions encl TREBY. B A Hearing Branch 1 84/03/13 BLOCH, P B , JORDAN, W H , MCCOLLOH, K A Atomic Bafety and Licensing Board Panel 200pp 22667.001 24X Fiche 50-445,84/03/13,8403190148
- B403170111 Notice of appearance in proceeding Certificate of Svc encl BACHMANN,R 9 Hearing Branch i 84/03/14 3pp 22666 263 24% Fiche: 50-445, 84/03/14, 8403170111
- 8403190118 Forwards NRC Insp Repts 99900530/84-01 & 50-445/83-52 of CYGNA Energy Bycs GA program used during Unit 1 independent assessment program No application to withhold rept received TREBY.8 A Hearing Branch 1 84/03/14 BLOCH.P B., JORDAN.W H., MCCOLLOH.K A Atomic Bafety and Licensing Board Panel 23pp 22666 273 24X Fiche 50-445.84/03/14.8403190118
- B403200026 Eighteenth set of interrogatories & requests to produce to applicants re issue of intimidation, harassment & threatening of GC inspectors & other employees Certificate of Bvc enc1 Related correspondence ELLIS, J Citizens Association for Bound Energy B4/03/14, Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 5pp 22679 228 24% Fiche 30-445,84/03/14,8403200026
- 8403200126 Nineteenth set of interrogatories & requests to produce to applicant Certificate of Svc enti Related correspondence ELLIS, J Citizens Association for Sound Energy 84/03/14 lipp 22699, 067 24X Fiche 50-445,84/03/14,8403200126
- 8403190002 Memorandum ciarifying open listed issues re GA program BLOCH P B . JORDAN W H . MCCOLLOM K A Atomic Bafety and Licensing Board Panel 84/03/15 21pp 22664 326 24X Fiche 50-445, 84/03/15.8403190002
- 8403190028 Memorandum ordering Ofc of Investigations to file, by B40329, affidavits responsive to ABLP concerns re observation of interviewee Applicants should file affidavits stating results of investigation by 840411
 BLOCH.P. B Atomic Safety and Licensing Board Panel 84/03/15 2pp 22665 360 24X Fiche 50-445.84/03/15,8403190028
- 8403200009 Requests to be informed about requested supplementation of answers to interrogatories & requests to produce Related correspondence ELLIG.J Citizens Association for Sound Energy 84/03/15 REYNOLDB.N 5 Dishop, Liberman, Cook, Purcell & Reynolds ip. 22685 202 24X Fiche 50-445.84/03/15.84032000097
- 8403200012 Advises that listed documents will be used in crosseramination of NRC staff witnesses on welding Related correspondence ELLIS.J Citizens Association for Bound Energy 84/03/15 TREBY.S , HIZUND.0 S Office of the Executive Legal Director. 1p 82683:357 24X Fiche 50-445.84/03/15.8403200012
- 8403200025 Forwards further responses from Walsh re Cygna 840313 responses to Citizens Assoc for Sound Energy Certificate of Svc encl Related correspondence ELLIB. J Citizens Association for Sound Energy 84/03/15 PIGOTT, D R Orrick, Herrington & Sutcliffe, 5pp. 22679, 223. 24X Fichs 50-445, 84/03/15, 8403200025

- 8403200049 Requests ASLB advise if motion for admission of enci two pages re nonconformance repts concerning handwritten/ typewritten discrepancies would be entertained at present Related correspondence ELLIB.J Citizens Association for Sound Energy 84/03/15 BLOCKLP B. MCCOLLOM, K.A. JORDAN, W.H. Atomic Safety and Licensing Board Panel 4pp 22698 287 24X Fiche 50-445,84/03/15,8403200049
- 8403200073 Requests listed documents for 18th & 20th sats of interrogatories Certificate of Svc encl Related correspondence ELLIS. J Citizens Association for Sound Energy 84/03/15 REYNOLDS.N S. HORIN. B Bishop, Liberman. Cosk. Purcell & Reynolds ip 22684 362 24% Fiche 50~445,84/03/15,8403200073
- 8403200114 Discusses supplementation of answers to interrogatories & requests to produce re T-shirt incident Applicants have history of being uncooperative re discovery matters Related correspondence ELLIS.J Citizens Association for Sound Energy 84/03/15 BLOCH.P B. JORDAN.W H. MCCOLLOM.K A. Atomic Safety and Licensing Board Panel 8pp 22685 327 24X Fiche 50-445,84/03/15.8403200114
- 8403200118 Twentieth set of interrogatories & request to produce to applicant Certificate of Svc encl Related correspondence ELLIB: J Citizens Association for Bound Energy 84/03/15 Texa: Utilities Electric Co. (formerly Texas Utilities Generating Co.) 8pp 22685 344 24X Fiche 50-445.84/03/15.8403200118
- 8403200147 Forwards Citizens Assoc for Bound Energy Exhibit 927, "Formulas for Stress & Strain," omitted from 840313 ltr W/o encl. Related correspondence ELLIS.J Citizens Association for Bound Energy 84/03/15 FIGOTT, D.R Orrick, Herrington & Sutcliffe 1p 22699 158 24X Fiche 50-445, 84/03/15, 8403200147
- 8403210102 Forwards IE Insp Repts 50-445/83-47 & 50-446/83-22 W/o encls.Related correspondence
 TREBY:8 A. Hearing Branch 1 84/03/16 BLOCH,P B., JORDAN,W H., MCCOLLOM,K A. Atomic Safety and Licensing Board Panel ip
 22706-117 24X Fiche 50-443.84/03/16.8403210102
- 8403200065 Notice that evidentiary hearing scheduled for 840423-27 reschaduled for 840424-27 in Fort Worth.TX BLOCH.P B Aboutc Safety and Licensing Board Penei 84/03/17 1p 22684 361 24X Fiche 50-445.84/03/19.8403200065
- 8403270031 Requests that MD Spence be substituted for RJ Gary on svc list Related correspondence REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds REYNOLDS, N S Texas Utilities Electric Co (formerly Texas Utilities Conerating Co) DSB 118 84/03/19 CLEMENTS, W L Docketing & Services Branch, 1p 22769 327 24X Fiche 50-445,84/03/19, 8403270031
- 8403280339 Responds to ASLB 840308 memorandum re schedule & policy of Ofc of Investigation Policy re release of repts to ASLB includes review of rept & delations to protect identity of confidential sources HAVES.B B Office of Investigation DBB 157 84/03/21 HCCOLLOM, K.A., BLOCH, P.B., JORDAN.W.H. Atomic Safety and Licensing Board Panel 2pp 22787 097 24X Fiche 50-445,84/03/21.8403280339
- 8403280342 Memorandum & order releasing transcript of 840221 in camera sessions & applicant memo re release of transcript as part of public record of proceeding BLOCH.P B Atomic Safety and Licensing Board Panel DSB 150 84/03/26 ip 22787 100 24X Fiche 50-445,84/03/26,8403280342
- H General correspondence
- 8403270173 Requests that name be placed on mailing list for matls issued in facility OL & IE monitoring process.

 9ARDE, B. P. Government Accountability Project 84/03/19 BURWELL, S
 Office of Nuclear Reactor Regulation. Director ip 22771 137
 24X Fiche 50-445,84/03/19,8403270173
- 8403230059 Designates MD Spence as recipient of official correspondence pertaining to facilities CLEMENTS, B.R. Texas Utilities Electric Co (formerly Texas Utilities Cenerating Co) 84/03/20 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p 22726 229 24X Fiche 50-445,84/03/20, 8403230059.

- G Inspection reports, IE Bulletins & correspondence
- 8403080324 F01A request for documents considered by NRC in preparation of notice of violation & proposed imposition of civil penalty,831222 ltr transmitting violation & rept of investigation re intimidation of GA personnel HARTHAN,8 L Debevoise & Liberman 83/12/30 FELTON,J M Division of Rules and Records 2pp 22583 169 24% Fiche 50-445,83/12/30.8403880324
- 8403080325 Partial response to FOIA request for documents considered by NRC in preparation of three categories of documents concerning facilities Forwards documents listed on App A FELTON, J M Division of Rules and Records 84/01/20 HARTMAN.9 L Debevoise & Liberman 2pp 22583 171 24X Fiche 50-445,84/01/20.8403080325
- --8403080327 Rev 27 to Procedure GI-QP-11 4-5 re visual defects insp & dry film thickness Related info enc1

 * Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 83/11/08 6pp 28583 173 24X
 Fiche 50-445,84/01/20,8403080325
- --8403080332 Describes commitments made to NRC in RJ Gary 830928 response to notice of violation & proposed imposition of civil penalty CLEMENTS, B R Texas Utilities Electric Co (formerly Taxas Utilities Cenerating Co) 83/11/29 CCLLINS, J T Region 4, Dffice of Director 11pp 22583 182 24X Fiche 50-445,84/01/20,8403080325
- --8403080335 Forwards rept re investigation into allegations made by WA Dunham & concerns related to protective coatings Related documents encl
 GARY, R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 83/12/13 COLLINS, J Region 4, Office of Director 22pp 22583 204 24X Fiche 50-445,84/01/20,8403080325
- 8403060431 Requests add1 info re ultrasonic exam of cast stainless steel piping in RCPB as part of preservice insp program Response requested within 5 days of itr receipt YOUNGBLODD B J Licensing Branch ! 84/02/24 GARY.R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 22552 047 24X Fiche 50-445.84/02/24(840306043)
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JURDAN. E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403130183 Forwards IE Inap Repts 50-445/83-47 & 50-446/83-22 on B30801-B40117 No violations or deviations noted JUHNBON, E H Region 4. Office of Director B4/02/28 GARY, R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 22607 129 24x Fichs 50-445, 84/02/28, 8403130183
- --8403130217 IE 1psp Repts 50-445/83-47 & 50-446/83-22 on 830801-840117 No violations or deviations noted Major areas inspected issues before AGLB hearing board TAYLOR.R G , HUNNICUTT, D M Region 4, Office of Director 84/02/28 6pp 22607 131 24X Fiche 50-445.84/02/28.8403130183
- 8403260069 Forwards evaluation of 830718 request for deletion of steam electric station license condition re low-pressure turbine disc insp NRC maintains position in SER (NUREG-0797) that insp must be conducted YOUNOBLOOD, B. J. Licensing Branch i 84/02/28 OARY, B. J. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) 2pp 22763 235 24X Fiche 50-445.84/02/28,8403260067
- --840326008i Evaluation of util 830718 request to delete turbine disc insp license condition UT insps required at first refueling & every subsequent refueling outage * NRC - No Detailed Affiliation Given 84/02/28 19pp 22763 237 24X Fichs 50-445.84/02/28,8403260069
- 8402070007 IE info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enc! GRACE.J N Division of OA, Emfeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22592:327 24X Fiche 50-000.84/03/02.8402090007
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list enc! JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402070008

- B402090009 IE Info Notice B4-15. "Reporting of Radiological Releases" Svc list and Junean, E. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc. 119pp 22553 217 24X Fiche 50-000.84/03/02.8402090009
- 8402070011 IE Info Notice 84-17, "Problems H/Liquid Nitrogen Cooling Components Below Mil Ductility Temp " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 1170p 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8402090024 IE Info Notice 84-09. Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Sys " Syc list and! JORPAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 (86 24X Fiche 50-000,84/03/07,8402090028
- 8403190406 Informs that no insp ropts will be issued for Rept Numbers 50-445/83-41 & 50-446/83-25 JUHNSCN.E H Region 4, Office of Director 84/03/09 GARY,R J Texas Utilities Electric Co (formerly Toxas Utilities Cenerating Co) ip 22674 357 24% Fiche 50-445.84/03/09,8403190406
- 8402090031 IE Bulletin 84-02, "Failures of GE Type MFA Relays in Use in Class IE Safety Sys " Svc list enc!
 DEYOUNG:R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12,8402090031
- B403190118 Forwards NRC Insp Repts 99900530/84-01 & 50-445/83-52 of CYGNA Energy Svcs QA program used during Unit 1 independent assessment program No application to withhold rept received TREBY, S A Hearing Branch 1 B4/03/14 BLOCH.P B Atomic Safety and Licensing Spard Panel 23pp 2256 273 24X Fiche 50-445.84/03/14.8403190118
- 8403200125 Forwards vendor insp repts for info & action Repts identify concerns found by Vendor Program Branch during insps of vendor activities Ack of ltr receipt requested JOHNSON.E H Region 4. Office of Director 84/03/16 QARY,R J Taxas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 22499 173 24% Fichs 30-445.84/03/16.8403200125
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PKR Reactor Cavities" Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402070043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list enc! JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 30-000.84/03/21,8402090044
- S Reportable occurrences, LERs & related correspondence
- 840301045: Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval.Inc
 DIRCKB, W J Office of the Executive Director for Operations
 EECY-83-034 84/01/25 4pp 22438 347 24% Fiche 50-000.84/01/25,
 880701045:
- 8403210032 Part 21 rapt re failure of auxiliary feedwater pump drive turbines, Gimpel NPS-4 T&T valve to close Encl ltr d&d 840203 sent to listed utils GE notified of affected units in BHR plants
 THEROUX-R R Terry Corp 84/02/22. WOODRUFF.R W Director's Office Office of Inspection and Enforcement 6pp 22706 327 24X Fiche 50-000,84/02/22,8403210032
- 8403070254 Followup Part 21 rept re defective mechanical snubber capstan springs supplied by Pacific Scientific Affected utils listed Purchasers have been notified & advised to work directly w/Pacific Scientific in disposition HOVIrL NPS Industries, Inc. 84/02/24 DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 2pp. 22536 279 24: Fiche: 50-000, 84/02/24, 8403070254.

- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval. Inc Cumers Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Oulf Nuclear Power Stations MUSELER.W. J. IDI (Transamorica Delaval, Inc.) Owners Croup 84/02/27 DENTON. HR Office of Nuclear Reactor Regulation, Director 3pp 22434 090 24% Fiche 50-000,84/02/27,8403010207.
- B402090021 Board Notification B4-039 discusses NRC B40210 & 16 mastings w/Transamerica Delaval.Inc Emergency Dissel Operators Owners Group Meeting scheduled on 840308 for finalization of generic program plan prior to NRC review EIBENNUT.D 0 Division of Licensing B4/02/28 PALLADING Commissioners 5pp 22346 003 24X Fiche 50-000, 84/02/28, 8402090021
- 840301021B Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc emergency diesel generators MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group 84/02/28 DENTON, K R Office of Nuclear Reactor Regulation, Director 42pp 22435 177. 24X Fiche 50-000,84/02/28.8403010219
- 840g090020 Board Notification 84-044 forwards Part 21 rept rateamerica Delaval. Inc turbocharger thrust bearing lubrication defect resulting in engine nonavailability EISENHUT.0 0 Division of Licensing 84/02/27 PALLADING Commissioners 4pp 22541:263 24X Fiche 50-000,84/02/27,8402090020
- 8403140048 Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval, Inc Diesel Generators Ubwers Group Program Plan," to resolve concerns w/smergency diesel generators MUSELER, M J Long Island Lighting Co 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 22626,062 24X Fiche 50-000,84/03/02,8403140048
- --B403i40095 "Transamerica Delaval, Inc Diesel Generators Owners Group Program Plan " # TDI (Transamerica Delaval, Inc.) Owners Group 84/03/02 261pp 22628:223 24X Fiche 50-000,84/03/02,840314004B
- 8403160213 Interim Deficiency Rept SDAR-125 re laminations & delaminations in cable tay support column in cable spread roam Initially reported on 840111 Evaluation continuing Completion expected by 840515
 GARY.R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/03/06 JOHNSON-E H Region 4, Office of Director ip 22655 231 24X Fiche 50-445,84/03/06,8403160213
- B402070033 Board Notification B4-047 forwards Transamerica Dalaval Inc Owners group piston skirt rept & task descriptions EISERNUT. D O Division of Licensing B4703/07 PALLADINO Commissioners 4pp 22674 221. 24½ Fiche 50-000,84/03/07. B402090033
- 840209003B Board Notification 84-051 forwards "Transamerica Delaval, Inc (TDI) Diesel Generators Owners Group Program Flan " EISEMHUT, D 0 Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22488 214 24X Fiche 50-000, 84/03/12, 8402090038
- 8402090037 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Dalaval. Inc (TDI) Owners Group Distribution list encl EISENHUT, D @ Division of Licensing 84/03/12. PALLADIND Commissioners 5pp 22708 OOI 24X Fiche 50-000, 84/03/12. 8402090037
- --B403060335 Forwards summary of B40210 meeting w/Transamerica Delavel.
 Inc Guners Group in Bethesda, MD re problems w/emergency
 diesel generators
 CARUSO, R Licensing Branch 2 B4/02/27 G'REILLY, J P NRG No
 Detailed Affiliation Given App 22708 006 24X
 Fiche 30-000, B4/03/12, B402090039
- ---B403060354 Transcript of 840210 meating w/Transamerica Delaval, Inc Owners Group in Bethesda.MD re problems w/smergency diesel generators # NRC - No Detailed Affiliation Civen 84/02/10 147pp. 67201 QQB 24X Fiche, 50-000, 84/03/12, 8402090039
- --8403070407 Summary of 840216 meeting w/Transamerica Delaval. Inc Owners Oroup in Wading River. NY re program plan to establish reliability of diesel generators Aganda. meeting transcript & attendance list encl
 MILLER. M A Licensing Branch 4 84/02/27. Licensing Branch 4.

 Epp. 22708-161 24X Fiche 50-000.84/03/12,8402070037

- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Ficha 50-000, 84/03/12, 8402070039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf dissel generators

 MUSELER.W J Long Island Lighting Co 84/03/12 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 22632 074
 24% Fiche 50-000,84/03/12,8403140050
- 8403150133 Forwards "Transamerica Delavai, inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & svc conditions MUBELER.W J TDI (Transamerica Delavai, Inc.) Owners Group 84/03/13 DENTON.H R Diffice of Nuclear Reactor Repulation, Director 2pp 22639 270 24X Fiche 50-000.84/03/13,8403150133
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number model & svc number, customer name & address rating, date shipped & date started encl
 MATHEMS, C 8 Transamerica Delaval. Inc 84/03/16 EISENHUT, D 9
 Division of Licensing 20pp 22691 179 24X Fiche 50-000,84/03/16,8403200222
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis." prepared by S&W for Transamerica Delaval. Inc (TDI) Diesel Generator Owners Oroup HUSELER, W J TDI (Transamerica Delaval. Inc.) Owners Group. 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 22774 001 24X Ficha 50-000,84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delaval diesel generators List of suggested meeting topics encl MCGAUGHY.JP TD1 (Transamerica Delaval, Inc.) Owners Group 84/03/23 DENTON.HR Office of Nuclear Reactor Regulation, Director 4pp 22769 i33 24X Fiche 50-000.84/03/23.8403270134
- T. Hearing transcripts on non-antitrust matters
- 8403020145 Transcript of 840228 telephone conference in Bethesda. MD Pp 10.350-10.383 * Atomic Safety and Licensing Board Panel 84/02/28 35pp 22440 275 24% Fiche 50-445.84/02/28.8403020145
- B403090104 Forwards correction to J Doyle 840222 testimony Related correspondence ELLIB, J. Citizens Association for Sound Energy 84/03/05 BLOCH.P B . JORDON.W H . MCGOLLOM.K A Atomic Bafety and Licensing Board Panel Ip 22576 081 24X Fiche 50-445.84/03/05.8403090104
- --B40309010B Affidavit of J Doyle, correcting 840222 testimony during cross-examination of CYGNA Certificate of Evc encl DOYLE, J Citizens Association for Sound Energy 84/03/03 7pp 22576 082 24% Fiche 50-445.84/03/05.8403090104
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 14 meetings between NRC & Transamerica Delaval, Inc (TD1) Owners Group Distribution list ancl EISENHUT, D. 9 Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708,001 24X Fiche 50-000,84/03/12, 8402090039
- --B403060536 Forwards summary of B40210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda:MD re problems w/emergency diesel generators CARUBO,R Licensing Branch 2 84/02/27. O'REILLY,J.P. NRC No Detailed Affiliation Given. App 22708 006 24X Fiche:50-000,84/03/12,8402090039
- --B403060554 Transcript of B40210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp. 67201 008, 24% Fiche 50-000,84/03/12,8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval. Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list and MILLER, MA Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708:161 24X Fichs 50-000.84/03/12,8402070037

- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 30-000, 84/03/12, 8402090039
- 8403260008 Transcript of 840319 hearing im Fort Worth,TX Pp 10,384-10,715 * Abomic Safety and Licensing Board Panei 84/03/19 340pp 22747 001 24X Fiche 50-445,84/03/19,8403260008
- 8403270167 Transcript of 840321 hearing in Fort Worth,TX Pp 11,019-11.318

 Atomic Safety and Licensing Board Panel 84/03/21 349pp 22774 150 24X Fiche 50-445.84/03/21.8403270167
- 8403270082 Transcript of 840322 hearing in Fort Warth.TX Pp 11.337-11.710 * Atomic Safety and Licensing Board Panel 84/03/22 373pp 22745 009 24X Fiche 50-445.84/03/22.8403270082
- 8403280021 Transcript of 840323 hearing in Fort Worth, TX Pp 11,711~ 11,978 * Atomic Safety and Licensing Board Panel 84/03/23 300pp 22777 173 24X Fiche 50-445,84/03/23,8403280021
- V Operator Examinations
- 8403130160 Forwards nuclear plant experience tables for shift advisors, shift supervisors, assistant shift supervisors, reactor operators & shift technical advisors Expected OL & fuel load dates are 84070i CLEMENTS, BR Texas Utilities Electric Co (formerly Texas Utilities Ownersting Co) 84/03/08 DENTON.H.R Office of Nuclear Reactor Regulation, Director 8pp 22608 238 24% Fiche 50-445, 84/03/08, 8403130160
- DOCKET STN-50-447 GESSAR-238
- A Application/construction stage documents & correspondence
- B403010013 Further response to FDIA request for documents re PRA & evacuation time estimates Forwards "Review & Evaluation of OEBBAR-II PRA-Containment Fallure Modes & Fission Product Release "Rept partially withheld (ref FOIA Exemption 4) FELTON, J M Division of Rules and Records B4/01/03 HIATT, 8 Ohio Citizens for Responsible Energy 4pp 22445 276 24X Fiche 50-447, 84/01/03, 8403010013
- --8308170191 "Review & Evaluation of GEBSAR-I1 Probabilistic Risk Assessment - Containment Failure Modes & Fission Product Release," itr rept * Brookhaven National Laboratory 83/07/27 Division of Systems Integration (pos
- 8403300216 Notification of 840320 meeting w/GE & BNL in Bethesda.MD to discuss source term reanalysis & results of sensitivity studies on parameters affecting fission product release SCALETTI.D Standardization & Special Projects Branch 84/03/15 THOMAS.C O Standardization & Special Projects Branch 3pp 22845 048 24X Fiche 50-447.84/03/15.8403300216
- S Reportable occurrences, LERs & related correspondence
- 8400240233 Forwards summary list of deficiencies identified per 10CFR90 55(e).Part 21 & potential generic ltr repts for comments STAROSTECKI.R Division of Project & Resident Programs 84/02/28 Region 1. Office of Director 7pp 22754 065 24X Fiche 50-000.84/02/28.8403260233
- DOCKET SYN-50-454 BYRON STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8403010106 Forwards addl info re design of Category 1 masonry walls Rept identifies all cracks & explains why cracks do not compromise structural integrity of walls TRAMM, TR Commonwealth Edison Co 84/02/22 DENTON, HR Office of Nuclear Reactor Regulation, Director 16pp 22436 041 24X Fiche 50-000.84/02/22.8403010106
- 8402090017 Board Notification 84-038 forwards RJ Mattson 840123 memo to DO Eisenhut providing status update of NRC actions re Westinghouse ECCS actuation logic EISENHUT.D G Division of Licensing 84/02/27 PALLADING Commissioners 7pp 22546 007 24X Fiche 50-000,84/02/27, 8402090017

- 8403050245 Forwards revised info re preservice exam & testing of snubbers at facilities Enct testing program supercedes program provided in 820319 ltr & accepted in SSER 12 TRAMM:T R Communication Co 84/02/28 DENTON,H R OF OF Nuclear Reactor Regulation, Director 1p 22516 013 24X Fiche:50-000,84/02/28,8403060245 ER 12 DENTON, H R OF office
- ~~8403060267 Rev 1 to "Preservice Testing (Preservice Insp) Program Plan for Smubbers " # Commonwealth Edison Co 83/10/21 47pp 22516 014 24X Ficha 30-000.84/02/28.8403060245
- 8403060374 Advises of changes to schedules for initial fuel loading of facilities Requests NRC resources be allocated to support fuel load after resolution of pending license appeal REED.C Commonwealth Edison Co B402/28 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 22518 150 24X Fiche. 50-000.84/02/28.8403060374 Office of
- 8403050119 Forwards supplemental response to Generic Ltr 83-28. "Required Actions Based on Generic Implications of Salem "Required Actions Based on Generic Implications of Service
 ATMS Events "
 BARNESIP, L. Commonwealth Edison Co 84/02/29 DENTON: H R OfOf Nuclear Reactor Regulation. Director 26pp 22486-084. 24X
 Fiche 50-000.04/02/29.8403050119 Diffice
- 8403260018 Trip rept of 831107-09 site visit to conduct second seismic qualification review team audit Appropriate seismic & dynamic qualification program defined to assurance that equipment will function properly LEE, A Equipment Qualification Branch 84/03/05 NODNAN, V S Equipment Qualification Branch 5pp 22763 306 24X Fiche 50-454.84/03/05.8403260018
- --8403260022 Forwards review comments in SSERs for second seismic qualification review team audit Addendum rept includes some resolutions based on applicant 840103 submittal SUBUDHI.M Brookhaven National Laboratory, 84/01/31 NOONAN Equipment Qualification Branch 20pp 22763.311 24X F1che 30-454,84/03/05,8403260018 NOONAN, U
- 8A032&0057 Trip rept of 821113-17 site visit to conduct seismic qualification review team audit w/BNL personnel Appropriate seismic & dynamic qualification program defined to assure equipment operation during & after BBE LEE, A Equipment Qualification Branch 84/03/05 NOQNAN, V S Equipment Qualification Branch 5pp 22763 236 24X Fiche 50-454.84/03/05.8403260057
- ---8403260061 Forwards review comments on SSERs for second seismic qualification review team audit Based on audit findings.
 equipment qualification status at plant satisfactory SUBUDHI.M Brookhaven National Laboratory 84/01/31 NDONAN Equipment qualification Branch ,20pp 22763 261 24X Fiche 50-454.84/03/05.8403260057 NOONAN, V S
- 8402090041 Board Nutification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications FIBENHUT. BO Division of Licensing 84/02/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000.84/02/14.8402090041
- 8403220133 Forwards info re experience level of individuals assigned to shift operating positions, in response to request Tabulation showing experience of shift engineer, shift foreman station control room engineer & operator enci TRAMM-T R Commonwealth Edison Co 84/03/19 DEMTON, H R Office of Nuclear Reactor Regulation, Director 7pp 22716 030 24X Fiche: 50-454.84/03/19.8403220133
- 8403260182 Charifies NUREG-0737, Item II K 3 31.in response to Generic Ltr 83-35 Westinghouse Owners Group authorized program to demonstrate conservatism of WFLASH small break LOCA analyses.per Item II K 3 30 BARNEG.P L Commonwealth Edison Co 84/03/21 EISENHUT.D G Division of Licensing ip 22736 170 24X Fiche 50-000.84/03/21, 8403260182
- E. NRC Safety Eveluation Report (SER), suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for aix categories of documents re facilities Forwards App A documents App B decument entirely withheld (ref FOIA Examption 3). Review of add1 documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S 1 Garvey, Schubert, Adams & Barer 7pp 22383 226 24x Fiche 30-000.84/02/13,8403080179
- --8005130793 Provides status of BER inputs & acceptance reviews for OL & CP applications Schedule should be met BURKE.W C Efficient Treatment Systems Branch 80/02/06. KREGER.W E Assistant Director for Site Analysis ip. 22583 235 24X Fiche 50-000.84/02/13.8403080179

- 8403010120 Forwards addl info to 831230 submittal re NUREO-0737. Item III D i i, "Primary Coolant Outside Containment " Rev identifies portions of sys not to be tested & responds ONCC comments Info should close SER Confirmatory Issue 28 TRAMM.T R Commonwealth Edison Co 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 22432 002 24X Fiche 50-000.84/02/22.8403010120 Office
- 8403010286 Provides addl info re effects of local intense precipitation at facilities InPo resolvas Confirmatory Issua A 2 identified in SER Reinforced concrete curbs provided at exterior grade floor level doors FRAMM. T R Commonwealth Edison Co 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22434 257 24X Fiche 50-000.84/02/22.8403010286
- E403260132 Submits addl info re design of hydrogen recombiners per Section 6 2 5 of SER Hydrogen recombiners operate in parallel utilizing same suction & exhaust piping for each containment Diagram encl dison Co 84/02/22 DENTON, H R Offiof Notlear Reactor Regulation. Director 2pp 22758:147. 24X Fiche: 50-000, 84/02/22, 8403260132 Office
- 8403060345 Forwards "Rept Qeatechnical Svcs Seismic Crosshole Survey & Dynamic Soil Properties at River Screenhouse. Byron Station Units 1 & 2 " Info closes out SER Confirmatory Issue i & responds to two FEAR questions

 TRAPM, T R Commonwealth Edison Co 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22511 136 24X fiche 50-454.84/02/28.8403060345
- --8403050347 "Rept Geotechnical Svcs Beismic Crosshole Survey & Dynamic Soil Properties at River Screenhouse.Byron Station Units i & 2 " 1 & 2 " • Dames & Moore 84/02/06 22pp 225ii.i37 24X Fiche 50-454.84/02/28.8403060345
- 8403260018 Trip rept of 831107-09 site visit to conduct second seismic qualification review team audit Appropriate seismic & dynamic qualification program defined to assurance that squipment will function properly LEE, A Equipment Qualification Branch 84/03/05 NOONAN, V 8 Equipment Qualification Branch Spp 22763 306 24X Fiche 50-454,84/03/05,8403260018
- --8403260022 Forwards review comments in SSERs for second smismic NO320022 Forwards review comments in SSERs for second salim qualification review team audit Addendum rept includes some rasolutions based on applicant 840103 submittal SUBUDHI.M Brookhaven National Laboratory, 84/01/31 NDO Equipment Qualification Branch 20pp 22763 311 24X Fiche 30-454,84/03/05,8403260018 NDONAN, V
- 8403260057 Trip rept of 821113-i7 site visit to conduct selsmic qualification review team audit w/RML personnel Appropriate seismic & dynamic qualification program defined to assure equipment aperation during & after SSE

 LEE, A Equipment Qualification Branch 84/03/05 NDQNAN, V S Equipment Qualification Branch 5pp 22763, 256 24X

 Fiche 50-454,84/03/05,8403260057
- --8403260061 Forwards review comments on SSERs for second seismic qualification review team audit Based on audit findings, equipment qualification status at plant satisfactory SUBUDHI.M Brookhaven National Laboratory 84/01/31 NDCNAR Equipment Gualification Branch 20pp 22763.261, 24X Fiche. 50-454,84/03/05.8403260057 NOONAN, U. S
- F Security, medical, emergency & fire protection plans
- 9403070347 Public version of revised emergency plan implementing procedure index W/840215 transmittal form & JM Felton 840302 release memo * Commonwealth Edison Co 84/01/20 18pp 22566 041. 24X Fiche 50-454.84/01/20.8403070347
- 8403010403 Rev O to Procedure BZP 500-Ti, "Checklist-Communication ** Commonwealth Edison Co 84/02/18 7pp. 22433 104 24X Fiche 50-454,84/02/18,8403010403
- 8403020198 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR YOUNGELOOD, B J Licensing Branch 1 84/02/21 FARRAR, D L Commonwealth Edison Co 2pp 22494 360 24X Fiche 50-000, 84/02/21, RAD300198 8403020198

- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D G Division of Licensing 84/02/23 PALLADIND Commissioners ip 22576 203 24% Fiche 50-000,84/02/23,8402090006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRR DFC Ltr 19. dtd 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT.D G Division of Licensing 10pp 22576 204 24x Fiche 50-000,84/02/23,8402090006
- E403010336 Forwards IE Bafeguerds Insp Rept 50-454/84-12 on 840208-10 No noncompitance noted AKELEDN.W L Region 3, Office of Director 84/02/28 REED.C Commpnuealth Edison Co 2pp 22433 039 24X Fiche 50-454,84/02/28, 8403010336
- --B40301034B IE Safeguards Insp Rept 50-454/84-12 on 840208-10 No noncompliance noted Major areas inspected organization & operation measurement & controls & storage & internal controls Details withheld (ref 100FR2 790) MADEDA,T J. CREED,J R. Region 3, Defice of Director 84/02/28 2pp 22433 041 24X Fiche 50-454,84/02/28,8403010336
- 8403120162 Rev O to Procedure BZP 500-i, "Operation Checks of Communications Sys " W/B40320 transmittal & receipt form * Commenwealth Edison Co B4/02/28 App 22590 i44 24X Fiche 50-454.B4/02/28.8403120162
- 8403050162 Forwards FEMA 840201 itr, final exercise evaluations on 831115 offsite emergency preparedness exercise & interim finding recommendations re offsite emergency response plan for area around facility No deficiencies identified PAPERIELLO,C J Region 3, Office of Director 84/02/29 REED,C Commonwealth Edison Co 2pp 22485 061 24x Fiche 50-454,84/02/29.8403050142
- 84031R0109 Notifies of 840323 workshop on fire protection safe shutdown requirements of 10CFR50.App R in Rosemont, IL to discuss IE Info Notice 84-09 & provide add shutdown analyses 2/or mod guidance Agenda enci SPESSARD.R L Division of Emergency Preparedness & Operational Support 84/03/06 REED, C Commonwealth Edison Co 3pp 22588 163. 24X Fiche 50-454,84/03/06,8403120109
- 8403150044 Rev i to Procedure BZP 380-7, "Estimation of Offsite Dose From Unplanned Release of Radioactive Effluents " W/B30310 transmittal form # Commonwealth Edison Co 84/03/07 App 22643 130 24X Fisha 50-454.84/03/07.8403150044
- 8403190308 Rev 2 to Procedure BZP-600-A3 "Station Directory & Mgt Personnel Home Phone List " W/840312 transmittai 1tr # Commonwealth Edison Co 84/03/12 9pp 22673 265 24X Flehe: 50-454.84/03/12.8403190308
- 8403260346 Rev 1 to Emergency Plan Implementing Procedure BZP 380~3. "Post-Accident Stack Sampling of Wide-Range Gas Monitor (WRGM)" + Commonwealth_Edison Co 84/03/15 5pp 22751 055 24X Fiche: 50~000, 84/03/15, 8403260346
- 8403140190 Emergency plan implementing procedures index H/840329 transmittal & receipt form Commonwealth Edison Co 84/01/20 17pp 22620 216 24X Fiche: 50-454,84/03/29,8403140190

Q. Adjudicatory correspondence

- 8403140035 Requests reconsideration of decision to bar facility from starting up Util most experienced w/nuclear plants & revs will result in corrective actions
 HDPKINS.R. Affiliation Not Assigned 84/02/20 NRC No Detailed Affiliation Given 2pp 22634 159 24X Fiche 50-454,84/02/20,8403140035.
- 8403020181 Forwards "Rept on Byron QC Inspector Reinspection Program" BIELAMSKI,A P Isham, Lincoin & Beaie BIELAMSKI,A P Commonwealth Edison Co 84/02/27 ROSENTHAL.A B, GOTCHY,R L, KOHL,C W Atomic Safety and Licensing Appeal Panel 224pp 22440 311 24X Fiche 50-454.84/02/27,8403020181
- 8403060079 Advises of issues to be addressed in 840312 brief, per 840127 request. WHICHER,J M Businessmen for the Public Interest 84/03/01 ROSENTHALLA S , KOHL,C W , GOTCHY,R L Atomic Safety and Licensing Appeal Panel 1p 22516 338 24X Fiche 50-454,84/03/01,8403060079

- 8403140129 Advises that staff unable to accelerate schedule for filing of appellate brief on GA, need for power & alternative energy sources, financial qualifications & seismology Brief will be filed by 840330 RAWSON, R J Hearing Branch 4 84/03/06 ROSENTHAL, A S , KOHL, C N , OTTCHY, R L Atomic Safety and Licensing Appeal Panel 1p 22624 204 24X Fiche 50-454.84/03/06,8403140129
- 8403i40i46 Forwards Paperisiio 840229 ltr to C Res6 forwarding FEMA interim finding on offsite radiological emergency planning NRC will address interim finding in SSER RAWBON R J Hearing Branch 4 84/03/06 ROSENTHAL, A S . ODTCHY, R L . KOHL. C N Atomic Safety and Licensing Appeal Panel 22pp 22624 212 24X Fiche 50-454.84/03/06.8403i40i46
- 8403140068 Forwards potentially relevant documents & matl to matters pending before ASLAB W/o encis RAWSON: R J Hearing Branch 4 84/03/07 ROSENTHAL, A S , KOHL, C N , OTCHY, R L Atomic Safety and Licensing Appeal Panel 2pp 22633 079 24X Fiche 50-454,84/03/07.8403140068
- 8403140148 Forwards 1E Imsp Repts 50-454/83-6i,50-455/83-4i,50-454/84-02,50-455/84-02,50-455/83-43,50-455/83-43,50-455/84-05,50-455/84-04,50-455/84-06,50-455/84-05 per requirements of ALAB-143
 RAWSON,R J Hearing Branch 4 84/03/07 ROSENTHAL,A S, QOTCHY,R L, KOHL,C N Atomic Safety and Licensing Appeal Panei 76pp 22625 086 24X Fichs 50-454,84/03/07,8403140148
- 8403090102 Memorandum scheduling 840417 oral argument in Bethesda,MD re pending appeal Formal argument wiil be issued in meriy Apr SHDEMAKER:C J Atomic Safety and Licensing Appeal Panel 84/03/08 2pp 22375 356 24X Fichm 50-454.84/03/08.8403090102
- 8403160002 Response opposing applicant alternative motion to reopen record & vacate ASLB denial of DL Motion would be considered acceptable under single issue of reinspection program Certificate of Svc encl HHICHER. J M DeKalb Area Ailiance for Responsible Energy HHICHER. J M Hhicher. J M 84/03/12 Atomic Safety and Licensing Appeal Panel ilpp 22655 198 24X Fiche 50-454,84/03/12,8403160002
- 8403160019 Brief in response to applicant appeal of ASLB 840113 initial decision denying OL application ASLB properly denied OL HHICHER.J M. CASBEL.D W. Dekaib Area Alliance for Responsible Energy WHICHER.J M. Whicher. J M. 84/03/12 Atomic Safety and Licensing Appeal Panel 64pp 22653 225 24X Fiche 50-454. 84/03/12.8403160019
- 840314004i Memorandum changing proposed date for oral argument of pending appeal from 840417 to 0419 SHOEMAKER.C J Atomic Bafety and Licensing Appeal Panei 84/03/13 1p 22634 ldi 24% Fichs 50-454,84/03/13,840314004i
- 8403200122 Discusses util 840218 & 0314 nonconformance repts re discrepant welds in cable pan hangers supplied by Bys Control Corp Earlier nonconformance repts re matter issued in 1977 at Byron Related correspondence MILLER, M I Isham, Lincoin & Beele MILLER, M I Commonwealth Edison Co 84/03/14 KOHL, C W : GUTCHY, R L : ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 2pp 22699 043 24% Fiche 50-454,84/03/14,84/03200122
- 8403260351 Forwards listing of errate in 840312 brief
 HHICKER.J M Businessmen for the Public Interest WHICKER.J M
 Nnicher. J M D5B 070 84/03/22 KCHL.C N. GOTCHY.R L.,
 ROSENTHAL.A S Atomic Safety and Licensing Appeal Panel 3pp
 22760 257 24X Fiche 50~454.84/03/22.8403260351

M Antitrust correspondence

- 8403270376 Forwards staff significant change analysis W/o enci Related correspondence VOOLER. B. H. Hearing Branch 2 DSB 180 84/03/28 LIEBERMAN, M Affiliation Not Assigned ip 22814 122 24X Fiche 50-454, 84/03/28,8403290376
- G Inspection reports, iE Builetins & correspondence
- 8403010130 Revises & suppls preservice insp program plan, in response to NRC comments & suggestions Addl info re exam of cast stainless steel components provaded Revised Relief Request NR-14 & Note 8 ancl for NRC approval
 TRAMM.T R Commonwealth Edison Co 64/02/17 DENTON, H R Office of Nuclear Reactor Repulation, Director 5pp 22435 342 24X
 Fiche 50-454,84/02/17,8403010130
- 8403010083 Forwards final rept on Byron GA inspector reinsp program DELOEGRGE.L O Commonwealth Edison Co 84/02/24 KEPPLER, J G Region 3, Office of Director 1p 22434 268 24X Fiche 50-454,84/02/24,8403010083

- ---8403010087 Final "Rept on Byron Inspector Reinsp Program"
 4 Commonwealth Edison Co 84/02/29 283pp 22434-270 24x
 Fiche 50-454,84/02/24,8403010083
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Pian " Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THOMAS. B Commonwealth Edison Co 84/02/24 KEPPLER, J G Region 3, Office of Director 3pp 22490 i39 24X Fiche 50-000,84/02/24,8403050043
- ---B403030046 Rev 0 to "Corporate Regulatory Performance Improvement Plan" * Commonwealth Edison Co B4/02/27 23pp 22490 142 24X Fishe 50-000.B4/02/29.B403050043
- 8403020181 Forwards "Rept on Byron QC Inspector Reinspection
 Program"
 BIELAMSKI,A P Isham, Lincoln & Beale BIELAMSKI,A P. Commonwealth
 Edison Co 84/02/27 ROSENTHAL,A S , GOTCHY,R L , KOHL,C W Atomic
 Safety and Licensing Appeal Panel 224pp 22440 311 24X
 Fiche 50-454,84/02/27.8403020181
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 113pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- B403010336 Forwards IE Safeguards Insp Rept 50-454/84-12 on 840208-10 No noncompliance noted AXELSON,W L Region 3. Office of Director 84/02/28 REED.C Commonwealth Edison Co 2pp 22433 039 24X Fiche 50-454.84/02/28. 8403010334
- --840301034B IE Safeguards Insp Rept 50-454/84-12 on 840208-10 No noncompilance noted Major areas Inspected organization & operation measurement & controls & storage & internal controls Details withheld (ref IOCFR2 790) MADEDA, T J , CREED. J R Region 3. Office of Director 84/02/28 2pp 22433 D41 24X Fiche 50-434.84/02/28,8403010336
- 8403060245 forwards revised into re preservice exam & testing of snubbers at facilities Encl testing program supercedes program provided in 820319 ltr & accepted in 85ER 12 TRAMM, T.R. Commonwealth Edison Co. 84/02/28 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p. 22516-013 24X Fiche: 50-000, 84/02/28, 8403060245
- --8403060267 Rev 1 to "Preservice Testing (Preservice Insp) Program Plan for Snubbers " * Gammahwealth Edison Co 83/10/21 47pp 22516 014 24X Fiche 50-000,84/02/28-8403060245
- 840,2090.007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list enc! GRACE J N Division of GA. Safeguards & Inspection Programs (Post 830103) 840,302 Consolidated Edison Ca of New York, Inc 130pp 22592 329 24x Fiche 50-000,84/03/02,8402050007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York Inc 122pp 22553 098 24X Fiche 50-000.84/03/02, 8402090008
- 8402070007 [E Info Notice 84-15, "Reporting of Radiological Releases Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402070009
- 8402090011 IE into Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp." Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consultated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05,8402090011
- B403190297 Forwards IE insp Repts 50~454/84~04 & 50~455/84~03 on 840123~26 No noncompliance identified.

 LITTLE.N B Region 3. Office of Director 84/03/05 REEP.C Commonwealth Edison Co 2pp 22673 255 24% Fiche 50~454.84/03/05, 8403190297.
- --8403170305 IE Insp Repts 50-454/84-04 & 50-455/84-03 on 840123-26 No noncompliance or deviations identified Hajor areas inspected closeout of open items & deficiency items & se-built waitdown of structural step1 framing & supports XEATING.D E , DANIELSON.D H Region 3, Office of Director 84/03/05 6pp 22673 257 24X Fiche 50-454.84/03/05,8403190277

- B403200295 Forwards IE Insp Rept 50-454/83-60 on 831212-16 & 27 & notice of violation SPESSARD,R L. Division of Emergency Preparedness & Operational Support 84/03/06 REED,C Commonwealth Edison Co 2pp 22696 234 24% Fiche 50-454,84/03/06.8403200295
- --8403200277 Notice of violation from insp on 83:212-16 & 27 8PESBARD,R L Division of Emergency Preparedness & Operational Support 84/03/06, 1p 22676 236 24X Fiche 30-454,84/03/06, 8403200295
- --8403200300 IE Insp Rept 50-454/83-60 on 831212-16 & 29 Noncompliance noted sanding line connections to safety-related instruments it.T-0529,39 & 49 installed contrany to Bargent & Lundy Drawing Beries M-2036 requirements MENDEZ.R. WILLIAMB.C C Region 3, Office of Director 84/02/27 9pp 22496 237 24% Fiche 50-454,84/03/06,8403200295
- B402070024 IE Info Notice B4-09: Rev 1: "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E i. Division of Emergency Preparedness & Engineering Response (Post 800103) 84/03/07 Consolidated Edison Co. of New York. Inc 118pp 22635 049. 24X Fiche 50-000.84/03/07.840207024
- 8402090028 IE Info Notice 84-i8, "Stress Corrosion Cracking in PWR Sys " Svr list enri JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403140148 Forwards IE Insp Repts 50-454/83-61.50-455/83-41.50-454/84-02.50-455/84-02.50-455/83-43.50-454/84-05.50-455/84-03.50-455/84-05.50-455/84-05.50-455/84-05.50-455/84-05.50-455/84-05.50-455/84-05.50-454/84-
- 8403220074 Forwards IE Insp Repts 50-454/84-10 & 50-455/84-08 on B40131.0201-03 & 07-10 No noncompliance noted PAPERIELLO.C J Region 3. Office of Director 84/03/07 REED.C Commonwealth Edison Co 2pp 22716 311 24X Fiche 50-454.84/03/07.
- --840322007 IE Insp Repts 50-454/84-10 & 50-455/84-08 on 840131.0201-03 & 07-10 No noncompliance noted Major areas inspected preoperational radiation protection program including organization, staffing, training & NUREO-0737 items HUETER.L J. GREGER.L R Region 3. Office of Director 84/03/07 itpp 22716 313 24X Fiche 50-454,84/03/07,8403220074
- 8403190268 Ack receipt of 840223 ltr informing NRC of steps taken to correct violations re steam generator snubber qualification tests noted in IE Insp Repts 30-454/84-08 & 50-455/84-06 LITTLE, W S Region 3, Office of Director 84/03/08 REED, C Commonwealth Edison Co 1p 22672 226 24X Fiche 50-454,84/03/08,8403190268
- --8403190274 Responds to NRC 840206 itr re violations noted in JE Insp Repts 50-454/84-08 & 50-455/84-06 Corrective actions leak on snubber repaired & quasi-static structural test combined w/fluid stiffness calculation performed SWARTZ.E D Commonwealth Edison Co 84/02/23 KEPPLER.J O Region 3, DPfice of Director 3pp 22672 227 24X Fiche 50-454.84/03/08.8403190268
- --8403190278 Preliminary Spec 120. "Testing Sycs for Steem Generators." * Sargent & Lundy, Inc. 84/02/22 38pp. 22672 232 24X Fiche 50-454,84/03/08,8403190268
- 8403220245 Ack receipt of 831230 response to 1E Insp Rept 50-454/83-23 Add1 insp of interhal flooding & postulated cracks & breaks in high-energy & moderate-energy lines will be conducted during wt of 840317

 DEYQUND.R C Director's Office. Office of Inspection and Enforcement 84/03/09 REED.C Commonwealth Edison Co 3pp 22723-336 24X Fiche 50-454,84/03/09.8403220245
- 840209003f IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Sefety Sys " Syc list encl PEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidate Edison Co of New York. Inc 134pp 22823 094 24X Fiche 30-000.84/03/12.8402090031.
- E403300017 forwards IE Insp Rept 50-454/84-07 on 840123-0225 k natice of violation STREETER.) F Region 3. Office of Director 84/03/13 REED.C R Commonwealth Edison Co 2pp 22822 i48 24% Fiche 50-454.84/03/13.

- --B403300023 Notice of violation from insp on B40123-0225 BTREETER, J F Region 3. Office of Director B4/03/13 2pp 22222 150 24X Fiche 50-454.B4/03/13.B403300017
- --8403300030 IE Insp Rept 50-454/84-07 on 840123-0225 Noncompliance noted Pailure to adequately evaluate preoperational test procedure results & failure to adequately document personnel instruction corrective actions RINO, M . WILLIAMS, D . VANDENBURGH, C Region 3, Office of Director 64/03/12 13pp 22822 152 24% Fiche 50-454,84/03/13,8403300017
- 8403230088 Ack receipt of regulatory performance improvement plan Periodic meetings requested to discuss progress on program & provide feedback KEPPLER, J G Region 3, Office of Director 84/03/20 THOMAS, B Commonwealth Edison Co ip 22730 161 24% Fiche 50-000, 84/03/20, 8403230088
- --8403230107 Forwards corporate regulatory performence improvement plan
 THOMAS. B Commonwealth Edison Co 84/02/24 KEPPLER, J O Region
 3, Office of Director 3pp 22730 162 24X Fiche 50-000,
 84/03/20,8403230088.
- --B403230126 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden, Quad Cities, Zion & LaBalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations " # Commonwealth Edison Co 84/02/27 22pp 22730 I65 24X Ficher 50-000, 84/03/20, 840323008B
- 8403260196 Forwards responses to IE Bulietin 83-07. "Apparently Fraudulent Products Sold by Ray Milter Inc." Quad Cities supplied w/piping matis from Ray Milier Inc during const Evaluation encl Concerns of IE Bulietin 83-06 satisfied. BARNES, P. L. Commonwealth Edison Co. 84/03/20 KEPPLER. J. Q. Region 3. Office of Director, 19pp. 22756 185 24X Fiche 50-000.84/03/20.8603260196.
- B403270111 Forwards response to IE Bulletin 80-15, "Emergency Notification 8ys (ENS) Power Supplies "ENS tested & found functional during preoperational testing BARNES, F.L. Commonwealth Edison Co 84/03/20 KEPPLER. J O Region 3, Office of Director 3pp 22774 048 24X Fiche. 30-454,84/03/20, 8403270111
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co of New York, Inc 123pp. 22823 229 24X Fiche 50-000.84/03/21.8402090043
- B402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys." Byc list encl.
 JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co. of New York
- 8403250226 Ack receipt of 840227 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Rept 50-454/83-54, LITYLE, W B. Region 3, Office of Director 84/03/21 REED, C Commonwealth Edison Co 2pp 22755:145 24X Fiche 50-454,84/03/21,8403260228.
- --8403260237 Responds to NRC B31212 ltr re violations noted in IE Insp Rept 50-454/83-54. Corrective actions. Conduit G1A51A6 smaltight fitting loosened & rotated to attain separation from Conduits G1A4102 & G1A51E4 FARRAR, D. L. Commonwealth Edison Co. 84/02/27 KEPPLER, J G Region 3, Office of Director. 4pp 22755, 147 24X Fiche: 50-454, 84/03/21, 8403260228
- 8403270246 Forwards BALP Repts 50-454/83-22, 50-455/83-18, 50-456/83-06 & 50-457/83-06 for 1982 Increased emphasis required in areas of HVAC & electrical sys KEPPLER, J G. Region 3, Office of Director Commonwealth Edison Co 7pp 22770 135. 24X Fiche. 50-000, 84/03/22, 8403270246
- ~-8403270252 SALP Repts 50~454/83-22 & 50~455/83-18 for 1982. * Region 3, Office of Director 84/03/22, 29pp. 22770,142, 24X Fiche-50~000,84/03/22,8403270246
- --8403270255 Forwards significant BALP rept findings which will be discussed at 830613 meeting HIND, J.A. Region 3, Office of Director 83/06/08. REED, C. Commonwealth Edison Co 4pp. 22770 171 24X Fiche: 50-000, 84/03/22, 8403270246.

- --8403270260 SALP Repts 50-456/83-06 & 50-457/83-06 for 1982 Category 2 assigned in areas of piping sys & supports & electrical power supply & distribution * Region 3, Office of Director 84/03/22 25pp 22770 203 24% Fiche 50-000.84/03/22.8403270246
- --8403270263 Forwards summary of significant findings for SALP rept which will be discussed at 830613 meeting HIND, J A Region 3, Office of Director 83/06/08 REED, C Commonwealth Edison Co 3pp 22770 228 24X Fiche 30-000.84/03/22,8403270246
- R Periodic operating reports & related correspondence
- 8403220120 Annual whole body external exposures for 1983 W/840316 itr RYBAK.B Commonwealth Edison Co 83/12/31 7pp 22716 007 24X Fiche 50-000.83/12/31.8403220120
- B403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues

 BIRCKS,W J Office of the Executive Director for Operations, 84/02/21 PALLADINO Commissioners 9pp 22492 083 24X Fiche 50-000,84/02/21,8403020443
- S Reportable occurrences, LERs & related correspondence
- 8403140122 Pert 21 rept re status update concerning abnormal wear on ilnear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry DDDSON, J P Pacific Air Products Co 84/03/09 Director's Office, Office of Inspection and Enforcement 7pp 22624 068 24X Fiche 50-000, 84/03/09,8403140122
- U Congressional/Executive Correspondence
- 8403200043 Provides edd1 remarks on NRC exceptions to accuracy of statements in recent Congressionel testimony re failure of NRC to inform ASLO promptly of problems at facility Problem can be cured by eliminating NRC role in hearings OLLINGKY, V Commissioners 84/03/16 UDALL.M K House of Rep , Interior & Insular Affairs 5pp 22698 322 24X Fiche 50-454,84/03/16,8403200043
- B403200075 Submits addi comments to remark made at recent NRC budget hearing & forwards Dircks memo re comments Roie of NRC as full party in licensing heerings should be eliminated GILINEKY, V Commissioners 84/03/16 SIMPSON, A Senate, Environment & Public Works 5pp 22697 036 24X Fichs: 50-454,64/03/16,8403200075
- V Operator Examinations
- B403220133 Forwards info re experience level of individuals assigned to shift operating positions, in response to request Tabulation showing experience of shift engineer, shift forgman, stetion control room engineer & operator encl TRAMM, T.R. Commonwealth Edison Co. 84/03/19 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 7pp 227i6 030 24X Fiche. 50-454, 84/03/19, 8403220133
- DOCKET STN-50-455 BYRON STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8403010106 Forwards addl info re design of Category 1 masonry wails Rept identifies all cracks & explains why cracks do not compromise structural integrity of walls TRAMM.T.R Commonwealth Eddson Go 84/02/22 DENTON.H R. Office of Nuclear Reactor Regulation, Director 1App 22436 041 24X Fiche 50-000.84/02/22.8405010106
- B402090017 Bpard Notification 84-038 forwards RJ Mattson 840123 memo to DO Eisenhut providing status update of NRC actions re Hestinghouse ECCS actuation logic.
 EISENHUT, D o Division of Licensing 84/02/27 PALLADINO Commissioners 7pp 22546 007. 24X Fiche 50-000.84/02/27.8402090017
- 8403060245 Forwards revised info re preservice exam & testing of snubbers at facilities Encl testing program supercedes program provided in 820319 lth & accepted in SEER 12 TRAMM.TR Commonwealth Edison Co 84/02/28 DENTON.HR Office of Nuclear Reactor Regulation, Director 1p 22516 013 24X Fiche 50-000,84/02/28.8403060245

- --B403060267 Rev 1 to "Preservice Testing (Preservice insp) Program Plan
 - * Commonwealth Edison Co 83/10/21 47pp 22516 014 24x
 Fichs 50-000,84/02/28,8403060245
- 8403060394 Advises of changes to schedules for initial fuel loading of facilities Requests NRC resources be allocated to support fuel load after resolution of pending license appeal REED. C Commonwealth Edison Co 84/02/28 DENTON-H R Office of Nuclear Reactor Regulation, Director 2pp 22518 130 24X Fiche 50-000,84/02/28.8403060394
- 8403030119 Forwards supplemental response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATUG Events"
 - ARNES Events "BARNES, Pt. Commonwealth Edison Co 84/02/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 26pp 22488 084 24X Fishe 50-000, 84/02/29, 8403050119
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT. D © Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 30-000.84/03/14.8402090041
- 8403220133 Forwards into re experience level of individuals assigned to shift operating positions in response to request Tabulation showing experience of shift engineer. shift foreman, station control room engineer & operator ent TRAMM. TR Commonwealth Edison Co 84/03/19 DENTON, H.R. Office of Nuclear Reactor Regulation. Director 7pp 22716 030 24% Fich > 50-454,84/03/19.8403220133
- 8403260182 Ciarifies NUREQ-0737, Item II K 3 31, In response to Generic Ltr B3-35 Westinghouse Duners Group authorized program to demonstrate conservatism of WFLASH small break LGCA analyses.per Item II K 3 30 BARNES.P L Commonwealth Edison Co 84/03/21 EISENHUT.D Q Division of Licensing ip 22756 170 P4X Fliche 30-000,84/03/21,8403260182
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403080179 Fourth partial response to FGIA request for six categories of documents re facilities Forwards App A documents App B documents entirely withheld (ref FGIA Exemption 5) Ruvisu of addi ducuments sub; to request continuing FELTGN.J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13.8403080179
- --B005130793 Provides status of SER inputs & acceptance reviews for OL & CP applications Schedule should be met BURKE.W C Effluent Treatment Systems Branch 80/02/06 KREGER.W E Assistant Director for Site Analysis ip 22583 235 24X Fiche 50-000.84/02/13.8403090179
- B403010120 Forwards add1 info to B31230 submittal re NUREG-0737, Item III D i 1. "Primary Contant Outside Containment " Revidentifies portions of sys not to be tested & responds to NRC comments Info should close SER Confirmatory Issue 2B TRAMMIT R Commonwealth Edison Co 84/02/22 DENTON, H R Office of Nurlear Reactor Regulation, Director Bpp 22432 002 24X Fiche 50~000,84/02/22,8403010120
- 8403010286 Provides add1 info re effects of local intense precipitation at facilities info resolves Confirmatory Issue A 2 identified in SER Reinforced concrete curbs provided at exterior grade floor level doors
 TRAMM.T R Commonwealth Edison Co 84/02/22 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 22434 257 24X
 Fiche 50-000.84/02/22.8403010286
- 8403260132 Submits addi info re design of hydrogen recombiners per Section 6 2 5 of SER Hydrogen recombiners operate in paraliel.utilizing same suction & exhaust piping for each containment Diagram enci TRAMMLT R Commonwealth Edison Co 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 22758 147 24X Fiche 50-000,84/02/22,8403260132
- 8403060345 Forwards "Rept Geotechnical Svcs Seismic Crosshole Survey & Dynamic Soli Properties at River Screenhouse, Byron Station Units 1 & 2 " Info closes out SER Confirmatory Issue 1 & responds to two FBAR questions
 TRAMM.T R Commanwealth Edison Co B4/02/28 DENTON, H R Office of Nuclear Reactor Repulation, Director 1p 22511 136 24X
 Fiche 50-454,84/02/28,8403060345
- --8403060347 "Rept Geotechnical Svcs Seismic Crosshole Survey & Dynamic Soil Properties at River Screenhouse, Byron Station Units & & 2 "
 - * Dames & Moore 84/02/06 22pp 225ii i37 24x Fichm 50-454,84/02/28,8403060345

- F Security, medical, emergency & fire protection plans
- B403070347 Public version of revised emergency plan implementing gracedure index W/840215 transmittal form & JM Felton 840302 release memo * Commonwealth Edison Co 84/01/20 18pp 22564 041 24X Fithe 50-454,84/01/20.8403070347
- B403010403 Rev 0 to Procedure BZF 500-T1, "Checklist-Communication Checks" + Commonwhalth Edison Co 84/02/18 7pp 22433 104 24X Fiche 50-454,84/02/18.8403010403
- 840302019B Advises that NRC will not review emergency plans to delete privacy or proprietary info unises specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR YOUNDELOOD.B J Licensing Branch 1 84/02/21 FARRAR.D L Commonwealth Edison Co 2pp 22494 360 24X Fiche 50-000.84/02/21.
- B402090006 Board Notification B4-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EIBENHUT.D g Division of Licensing 84/02/23 PALLADING Commissioners ip 22576 203 24X Fiche 50-000;84/02/23, B402090006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRR Ofc Ltr 19.dtd 821001 Further avaiuation of test data required VOLLMER.R H Division of Engineering 84/02/06. EISENHUT, D 0 Division of Licensing 10pp 22076 204 24X Fichs 50-000,84/02/23.8402090006
- 8403120162 Rev O to Procedure BZP 500-i, "Operation Checks of Communications Bys " W/840320 transmittal & receipt form * Commonwealth Edison Co 84/02/28 4pp 22590 144 24X Fiche 50-454,84/02/28.8403120162
- 8403050162 Forwards FEMA 840201 ltr.final exercise evaluations on 831115 offsite emergency preparedness exercise & interim finding recommendations re offsite emergency response plan for area around facility No deficiencies identified PAPERIELLO.C J Region 3. Office of Director 84/02/29 REED.C Commonwealth Edison Co. 2pp 22485 061 24X Fichs 50-454.84/02/29, 8403050162
- 8403120109 Notifies of 840323 workshop on fire protection safe shutdown requirements of IOCFRSO.App R in Rosemont.IL to discuss IE Info Notice 84-09 & provide addi shutdown analyses &/or mod guidance Agenda enci SPESSARD.R.L Division of Emergency Preparedness & Operational Support 84/03/06 REED,C Commonwealth Edison Co Spp 22588 163 24X Fiche 30-454,84/03/06,8403120109
- 8403i50044 Rev i to Procedure BZP 380-7, "Estimation of Offsite Dase From Unplanned Release of Radioactive Effluents " W/8303i0 transmittal form * Commonwealth Edison Co 84/03/07 6pp 22643-130 24X Fiche 50-454.84/03/07.8403i50044
- B403260346 Rev 1 to Emergency Pian Implementing Procedure BZP 380-3, "Post-Accident Stack Bampling of Wide-Range Gas Monitor (MRGM)"

 * Commonwealth Edison Co 84/03/15 5pp 22751.055 24x Fiche 50-000.84/03/15,8403260346
- 8403i40190 Emergency plan implementing procedures index W/840329 transmittal & receipt form * Commonwealth Edison Co 84/01/20 17pp 22620.216 24X Fiche 50-454.84/03/27,8403140190

G Adjudicatory correspondence

- 8403i40035 Requests reconsideration of decision to bar facility from starting up Util most experienced w/nuclear plants & revs will result in corrective actions HOPKING.R. Affiliation Not Assigned 84/02/20 NRC No Detailed Affiliation Given 2pp 22634.159. 24X Fiche 50-454.84/02/20, 880314035
- 8403020181 Forwards "Rept on Byron GC Inspector Reinspection Program" BIELAMSKI.A.P Isham, Lincoln & Braie BIELAMSKI.A.P Commonwealth Edison Co 84/02/27 ROSENTHAL.A B. GDTCHY.R L., KOHL.C.W. Atomic Safety and Licensing Appeal Panel 224pp 22440-311 24X Fichs 50-454:84/02/27,8403020181

- 8403060079 Advises of issues to be addressed in 840312 brief, per B40127 request WHICHER, J M Businessmen for the Public Interest 84/03/01 ROSENTHAL, A S , KOML, C W , GOTCHY, R L Atomic Safety and Licensing Appeal Panel ip 22516 338 24X Fiche 50-454,84/03/01,8403060079
- 8403140129 Advises that staff unable to accelerate schedule for filing of appellate brief on GA need for power & alternative energy sources; financial qualifications & seismology Brief will be filed by 840330 RAWSON; R J Hearing Branch 4 84/03/06 ROSENTHAL, A S, KOML, C N, COTCHY, R L Atomic Safety and Licensing Appeal Parel 1p 22624 204 24X Fiche 50-454,84/03/06.8403140129
- 8403140146 Forwards Paperiello 840229 itr to C Reed forwarding FEMA interim finding on offsits radiological emergency planning NRC will address interim finding in SSER RAHBON.R J Hearing Branch 4 84/03/06 ROSENTHAL.A 8 , GUTCHY.R L , KOHL.C N Atomic Safety and Licensing Appeal Panel 22pp 22624 212 24X Fichs 50-454.84/03/06.8403140146
- 840314006B Forwards potentially relevant documents & matl to matters pending before ABLAD W/o encls RAMSON.R J Hearing Branch 4 84/03/07 ROSENTHAL, A S . KOHL.C N . OTCHY.R L Atomic Safety and Licensing Appeal Panel 2pp 22633 079 24X Fiche 50-454,84/03/07.8403140068
- 8403140148 Forwards IE Insp Repts 50-454/83-61:50-455/83-41:50-454/84-02:50-455/84-02:50-454/84-05:50-455/84-04:50-454/84-05:50-455/84-04:50-454/84-05:60-455/84-05:60-455/84-05:60-454/84-05-60-454/84-05-60-454/84-
- 8403090102 Memorandum scheduling 840417 oral argument in Bethesda.MD repending appeal Formal argument will be issued in early Apr 8HDEMAKER.C J Atomic Safety and Licensing Appeal Panel 84/03/08 2pp 22575 356 24X Fiche 50-454.84/03/08.8403090102
- 8403160002 Response opposing applicant alternative motion to reopen record & vacate ABLB denial of OL Motion would be considered acceptable Under single issue of reinspection program Cartificate of Svc encl HHICHER, J M DeKaib Area Alliance for Responsible Energy HHICHER, J M Whicher, J M 84/03/12 Atomic Safety and Licensing Appeal Panel 11pp 22655 178 24X Fichs 30-454, 84/03/12, 8403160002
- 8403160019 Brief in response to applicant appeal of ASLB 840113 initial decision denying OL application ASLB properly denied OL MHICHER, J M. CASSEL. D W. DeKalb Area Alliance for Responsible Energy WHICHER, J M. Whicher, J M. 84/03/12 Atomic Bafety and Licensing Appeal Panel 64pp. 22653 225 24% Fiche 50-454, 84/03/12, 8403160019
- 8403140041 Memorandum changing proposed date for oral argument of pending appeal from 840417 to 0419
 8HOEMAKER, C J. Atomic Safety and Licensing Appeal Panel 84/03/i3 ip 22634 ibi 24X Fich* 50-454,84/03/13,840314004i
- 8403200122 Discusses util 840218 & 0314 nonconformance repts re discrepant walds in cable pan hangers supplied by Bys Control Corp Earlier nonconformance repts re matter issued in 1977 at Byron. Related correspondence MILLER, M I Isham, Lincoln & Beale MILLER, M I, Commonwealth Edison Co 84/03/14 KDHL, C W, GUTCHY, R L, ROSENTHAL, A 8 Atomic Safety and Licensing Appeal Panel 2pp. 22677, 045 24X Fiche, 30-454, 84/03/14, 8403200122.
- 8403260351 Forwards listing of errata in 840312 brief.
 WHICHER, J M Businessmen for the Public Interest WHIGHER, J M Whicher, J M DBB 090 B4/03/22 KOHL, C N., GOTCHY, R.L., ROSENTHAL, A. 8 Atomic Bafety and Licensing Appe
- Q Inspection reports, IE Bulletins & correspondence
- 8403010083 Forwards final rept on Buron QA inspector reinsp program DELGEORCE, L. Q. Commonwealth Edison Co. 84/02/24 KEPPLER, J. Q. Region 3. Office of Director 1p. 22434 268 24X Fiche: 50-454, 84/02/24, 8403010083.
- --8403010087 Final "Rept on Byron Inspector Reinsp Program." * Commonwealth Edison Co. 84/02/29 223pp 22434 270 24X Fiche 50-454,84/02/24,8403010083

- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan" Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance
 THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER, J C Region 3, Office of Director 3pp 22490 i39 24% Fiche 50-000,84/02/24, 8403050043
- --8403050046 Rev 0 to "Corporate Regulatory Performance Improvement Plan" * Commonwealth Edison Co 84/02/29 22pp 22490 142 24X Fiche 50-000,84/02/24,8403050043
- 8403020181 Forwards "Rept on Byron QC Inspector Reinspection Program" BIELAWBRI.A P Isham, Lincoin & Beaie 84/02/27 ROSENTHAL,A S Atomic Safety and Licensing Appeal Panel 224pp 22440 311 24X Fiche 50-454,84/02/27,8403020181
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Mator Operated Valve Control Circuits & Annunciation " 8vc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 930103) 84/02/28 Consolidated Edison Co. of New York: Inc. 115pp 22909 239 24X Fiche.50-000.84/02/28,8401190072
- 8403060245 Forwards revised info re preservice exam & testing of snubbers at facilities Enci testing program supercedes program provided in 820319 ltr & accepted in 85ER 12 TRAMM, T R Commonwealth Edison Co 84/02/28 DENTON, H.R Office of Nuclear Reactor Regulation, Director ip 22516 013 24X Fichs 30-000.84/02/28.84030860245
- --8403060267 Rev i to "Preservice Testing (Preservice Insp) Program Pian for Shubbers " * Commonwealth Edison Co 83/10/21 47pp 22516 014 24X Fichs 50-000, 84/02/28, 8403060245
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of QA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fi-he 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc i22pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Syc list enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 84020900ii IE Info Notice 84-i7, "Problems W/Liquid Nitrogen Gooling Components Below Nii Ductiiity Temp " Svc iist encl, JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/03 Consolidated Edison Co of New York, Inc ii7pp 22553 336 24X Fiche 50-000,84/03/03,840209001i
- B403190297 Forwards IE Insp Repts 50-454/84-04 & 50-455/84-03 on 840123-26 No noncompliance identified LITTLE: W S Region 3. Office of Director 84/03/05 REED, C. Commonwealth Edison Co 2pp 22673 255 24X Fiche 50-454, 84/03/05. 8403190297
- --8403190305 IE Insp Repts 50-454/84-04 & 50-455/84-03 on 840123-26 No noncompliance or deviations identified Major areas inspected closeout of open items & deficiency items & as-built walkdown of structural steel framing & supports KEATING, D E , DANIELSON, D H , Region 3, Office of Director B4/03/05 App 22673 257 24X Fichs 50-454/84/03/05.8403190297
- 8402070024 IE Info Notice 84-09, Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN; E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24X Fiche, 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys," Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584 186 24X Fiche 50-000.84/03/07,8402090028

- 840314014B forwards IE insp Repts 50-454/83-61.50-455/83-41.50-454/84-02.50-455/84-02.50-454/83-58.50-455/83-43.50-494/84-05.
 50-455/84-04.50-454/84-06 & 50-455/84-05 per requirements of ALAB-143
 RAWSON.R J Hearing Branch 4 84/03/07 ROBENTHAL.A B Atomic Safety and Licensing Appeal Panel 76pg 22625.086 24X
 Fiche 50-454.84/03/07.840314014B
- 8403220074 Forwards IE lnsp Repts 50-454/84-10 & 50-455/84-08 on 840131.0201-03 & D7-10 No noncompliance noted PAPERIELLO, C J Region 3. Office of Director 84/03/07 REED.C Commonwealth Edison Co 2pp 22716 311 24% Fichs 50-454.84/03/07.8403220074
- --B403220097 IE insp Repts 50-454/B4-10 & 50-455/B4-0B on B40131,0201-03 & 07-10 No noncompliance noted Major areas inspected preoperational radiation protection program including organization, staffing training & NUREC-0737 items HUETER, L.J., GREGER, L.R. Region 3, Office of Director B4/03/07 11pp 22716 313 24X Fiche 50-454,84/03/07,8403220094
- 8403190268 Ack receipt of 840223 ltr informing NRC of steps taken to correct violatione re steam generator snubber qualification tests noted in IE Inep Repts 50-454/84-08 & 50-455/94-06 LITLE.W S Region 3. Office of Director 84/03/08 REED.C Commonwealth Edison Co ip 22672 226 24X Fichs 50-454.84/03/08.8403190268
- --B403190274 Responds to NRC B40206 itr re violations noted in IE Insp Repts 50-454/84-08 & 50-455/84-05 Corrective actions lask on snubber repaired & quasi-etatic structural test combined offluid stiffness calculation performed SWARTZ, E D Commonwealth Edison Co 84/02/23 KEPPLER, J O Region G. Office of Director. Spp. 22672 227 24X Fiche 30-454,84/03/08,8403190268
- --8403i90278 Preliminary Spec 120, "Testing Sycs for Steam Generators"

 * Sargent & Lundy, Inc 84/02/22 38pp 22672 232 24X
 Fiche 50-454,84/03/08,8403190268
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl.

 DEYOUNG, RC Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc i34pp 22823 094 24X Fiche 50-000,84/03/12.8402090031.
- 8403230088 Ack receipt of regulatory performance improvement plan
 Periodic meetings requested to discuss progress on program
 & provide feedbact
 KEPPLER.J C Region 3. Office of Director 84/03/20 THOMAS.B
 Commonwealth Edison Co 1p 22730 161 24X Fiche:50-000,84/03/20.
 8403230088
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER, J Q Region 3. Office of Director 3pp 22730 162 24X Fiche 50-000, 84/03/20,8403230088
- --8403230126 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden, Quad Cities, Zion & LaSalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations " * Commonwealth Edison Co 84/02/29 22pp 22730 165 24X Fiche 50-000, 84/03/20, 8403230088
- 8403260196 Forwards responses to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller.Inc " Guad Cities supplied w/plping matts from Ray Miller. Inc during const Evaluation encl Concerns of IE Bulletin 83-06 satisfied BARNES.P L Commonwealth Edison Co 84/03/20 KEPPLER.J Q Ragion 3. Office of Director 19pp 22754 185 24X Fiche 50-000,84/03/20,8403260196
- B403270111 Forwards response to IE Bulletin B0-15, "Emergency Notification Sys (ENB) Power Supplies " ENB tested & found functional during preoperational testing BARNES,P.L. Commonwealth Edison Co B4/03/20 KEPPLER, J G Region 3, Office of Director Spp 22774 04B 24X Fiche 50-454,84/03/20,8403270111
- B402090043 IE info Notice B4-19, "Two Events Involving Unauthorized Entries into PNR Reactor Cavities " Svc liet encl.

 JORDAN, E L Division of Emergency Preparednees & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823:229. 24X Fiche 50-000:84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys." Svc list encl
 JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22933 001. 24% Fiche 50-000,84/03/21,8402090044

- 8403270246 Forwards SALP Repts 50-454/83-22.50-455/83-18,50-456/83-06 & 50-457/83-06 for 1982 Increased emphasis required in areas of HVAC & electrical sus KEPPLER.J G. Region 3. Office of Director 84/03/22 REED,C Commonwealth Edison Co 7pp 22770 135 24X Fiche 50-000.84/03/22.8403270246
- --8403270252 8ALP Repts 50-454/83-22 & 50-455/83-18 for 1982 * Replom 3, Office of Director 84/03/22 29pp, 22770 142 24% Fiche 50-000, 84/03/22,8403270246
- --8403270285 Forwarde significant SALP rept findings which will be discussed at 830613 meeting HIND, J A Region 3, Diffice of Director 89/06/08, REED, C. Cumnonwealth Edison Co 4pp. 22770-171 24X Fiche 50-000, 84/03/22, 8403270246
- R Periodic operating reports & related correspondence
- 8403220120 Annual whole body external exposures for 1983 W/840316 ltr RYBAK.B Commonwealth Edison Co. 83/12/31 7pp 22716.007 24X Fichs.50-000.83/12/31.8403220120
- S Reportable occurrences. LERs & related correspondence
- 8403140122 Part 21 rept re status update concerning abnormal weer on linear converters Teet program underway Results of investigation indicate excessive wear caused by hunting of control circuitry DDB30N.J P Pacific Air Products Co 84/03/09 Director's Office, Office of Inspection and Enforcement 7pp, 22624.068. 24X Fiche 50-000.84/03/09.8403140122
- U Congressional/Executive Correspondence
- 8403200043 Provides add1 remarks on NRC exceptions to accuracy of statements in recent Congressional testimony re failure of NRC to inform ABLB promptly of problems at facility Problem can be cured by eliminating NRC role in hearings OILINEKY. V Commissioners 84/03/16 UDALL.M.K House of Rep , Interior & Insular Affairs 5pp 22678 322, 24% Fiche 50-454.84/03/16.8403200043.
- 8403200075 Submits addl comments to remark made at recent NRC budget hearing & forwarde Dircks memo re commente Role of NRC as full party in licensing hearings should be eliminated OILINSKY.V Commissioners 84/03/16 SIMPBON, A Senate, Environment & Public Works 5pp 22699 036 24X Fiche. 50-454,84/03/16.8403200075
- V Operator Examinations
- 8403220133 Forwards info re experience level of individuale assigned to shift operating positions in response to request. Tabulation showing experience of shift engineer shift foremen, station control room engineer & operator enci TRANKITR Commonwealth Edison Co 84/03/17 DENTON, H.R of Nuclear Reactor Regulation. Director 7pp 22716 030 24X Fiche 50-454,84/03/19.8403220133
- DOCKET STN-50-456 BRAIDWOOD STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B403010106 Forwards addl info re design of Category 1 mesonry walls. Rept identifies all cracks & explains why cracke do not compromise structural integrity of walls TRAMM.TR Commonwealth Edison Co 84/02/22, DENTON,HR Office of Nuclear Reactor Regulation, Director 16pp 22436-041, 24X Fichs 50-000.84/02/22.8403010106
- 8403060245 Forwards revised info re preservice exam % testing of snubbers at facilities Encl testing program supercedes program provided in 820319 ltr & accepted in 88ER 12 TRAMM.T R Commonwealth Edison Co 84/02/28 DENTON.H R. Office of Nuclear Reactor Regulation, Director 1p. 22516 013, 24X Fiche 50-000.84/02/28,8403060245
- --8403060267 Rev 1 to "Preservice Testing (Preservice Insp) Program Plai for Bhubbers " * Commonwealth Edison Co. 83/10/21 47pp. 22516:014. 24X Fiche 50-000,84/02/28:8403060245.
- 8403060394 Advises of changes to schedules for initial fuel loading of facilities, Requests NRC resources be allocated to support fuel load after resolution of pending license appeal, REED, C Commonwealth Edison Co 84/02/28, DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp, 22518 150, 24X Fiche 50-000,84/02/28,8403060394

- #403260182 Clarifies NUREG-0737. Item II K 3 31. in response to Generic Ltr 83-35 Westinghouse Dwners Group authorized program to demonstrate conservatism of WFLASH small break LOCA analyses.per Item II K 3 30

 BARNEB, F L Commonwealth Edison Co 84/03/21 EISENHUT, D Q Division of Licensing ip 22756 170 24X Fichs 50-000, 84/03/21. 84032A0182
- D NRC Draft/Final Environmental Statements, supple & correspondence
- #403i30037 Ack receipt of DEB Meeting tenatively scheduled for E40222 for consideration by Governmental Svcs Committee # Illinois, Btate of. 84/02/02 BTEVENS, J A Division of Licensing ipp 22613 362 24X Fiche 50-456.84/02/02.8403130037
- BA03060313 Provides comments on DES (NUREO-1026) Justification for not providing design enalysis of seismic event requested ETCHIBONID. Illinois, Bates of, Dept Nuc Bafesty (formerly Dept Public Health) B402/22 Division of Licensing. 3pp 22515 330 24X Fiche 50-456.84/02/22.8403060313
- 23403080227 Lists concerns on proposed water supply sys discussed in Dec 1983 DES (NUREG-1026), including degradation of water quality from cooling water discharge to Kankakee River GALLAGHER, JR Will County, IL 84/03/02 Division of Licensing 1p 22561 031, 24X Fiche 50-456,84/03/02,8403080227
- #2403130057 Comments on DES (NUREO-1026) for facility DES does not completely describe fuel cycle impact & should contain statement re range of nonfatal cancer injuries & birth defects induced by fuel cycle Rn-222 DOHERTY, JF Doherty, JF 84/03/07 BIEVENS, J. A Division of Licensing 2pp 22601 i17 24X Fiche 50-456, B4/03/07, B403130057
- 9403130474 Forwards comments on DES re operation of facilities Major environ concerns identified during 1970s & appropriate mitigating actions to alleviate concerns adequately reflected More data re aquatic impact should be referenced MENNEY, D Illinois, Btate of 84/03/08 Division of Licensing App. 22613 357 24X Fiche 50-456,84/03/08,8403130474
- #3403140001 Forwards comments on DES (NUREO-1024) Comments submitted for consideration by Commission per 100FR51.

 MCDONDUOH.C L Commonwealth Edison Co 84/03/12 Division of Licensing 13pp 22633:251. 24X Fiche. 30-456.84/03/12.8403140001
- ### 403200104 Discusses review of DES. Facility will employ two PWRs to produce up to 6830 MWt No major objections to proposed operation FEB should provide add1 radwasts treatment systings.

 REED. L. O Environmental Protection Agency 84/03/12, YOUNGILOOD, B. J. Licensing Branch 1 3pp. 22695:357 24% Fiche 50-456,84/03/12,8403200104
- 🖭 NRC Bafety Evaluation Report (BER), suppls & correspondence
- —B005130793 Provides status of BER inputs & acceptance reviews for OL & CP applications Schedule should be met BURKE, M. C. Effluent Treatment Systems Branch 80/02/06 KREGER, M. E. Assistant Director for Site Analysis. 1p 22583; 235 24X Fichs 50-000,84/02/13,8403080179
- ### OB010120 Forwards add1 info to 831230 submittal re NUREQ-0737. Item
 III. D. i 1. "Primary Coolant Outside Containment " Rev
 identifies portions of sys not to be tested & responds to
 NRC comments Info should close SER Confirmatory Issue 28
 TRAMH.T.R. Commonwealth Edison Co. 84/02/22 DENYION.H R. Office
 Of Nuclear Reactor Regulation, Director Spp. 22432 002 24X
 Fichs: 50-000,84/02/22,8403010120
- ### OBJ010286 Provides add1 info re effects of local intense precipitation at facilities Info resolves Confirmatory Issue A.2 identified in BER. Reinforced concrete curbs provided at exterior grade floor level doors.

 TRAMM.T.R. Commonwealth Edison Co 84/02/22 DENTON, H.R. Office Of Nuclear Reactor Regulation, Director 2pp 22434 257. 24X Fiche: 50-000, 84/02/22, 8403010286

- 8403260132 Submits addi info re design of hydrogen recombiners per Section 6 2 5 of SER Hydrogen recombiners operate in parallel. utilizing same suction & enhaust piping for each containment Diagram encl TRAMM.T R Commonwealth Edison Co 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22758 147 24X Fichs 50-000,84/02/22,8403260132
- F Security, medical, emergency & fire protection plans
- 8403020198 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81~27 W/o request, entire plan will be placed in PDR YDUNOBLOOD, B. J. Licensing Branch i 84/02/21 FARRAR. B. L. Commonwealth Edison Co. 2pp. 22494 360 24X Fiche 50-000, 84/02/21. PAGGBOOLS
- 840312000B Advises of 840323 regional workshop in Rosemont IL w/all Region III licensees to discuss fire protection safe shutdown requirements of 10CFR50.App R Agenda encl SPESBARD.R L Division of Emergency Preparedness & Operational Support 84/03/06 REED.C Commonwealth Edison Co Spp 22586 260 24% Fiche 50-456.84/03/06.840312000B
- 8403260346 Rev 1 to Emergency Plan Implementing Procedure BZP 380-3, "Post-Accident Stack Sampling of Wide-Range Cas Monitor (WRCM)"

 * Commonwealth Edison Co 84/03/15 5pp 22751 055 24X Fiche 50-000,84/03/15,8403260346
- G Adjudicatory correspondence
- 8403140040 Comments of JF Doberty on DES (NUREG-1026) Statement must clarify if, in analysis of environ impacts of postulated accidents-any credit given for applicant compliance w/any TMI-related requirements Related correspondence DOHERTY. JF Affiliation Not Assigned 84/03/07 STEVENS, J A Division of Licensing 2pp 22633 120 24X Fiche 50-456.84/03/07, 8403140040
- 8403i6001) Forwards C Reed 840228 ltr re schedule for fuel loading dates & notice of appearance H/o notice of appearance Related correspondence GALLO, J Commonwealth Edison Co 84/03/13 MILLER, M E . CALLIHAN, A D . COLE, R F Atomic Safety and Licensing Board Panel 3pp 22655 i68 24X Fiche 50-456, 84/03/13, 8403i6001i
- B403160023 Notice of appearance in proceeding Certificate of Svc encl GALLO, J Commonwealth Edison Co GALLO, J Isham, Lincoln & Beale B4/03/i3 2pp 22653 353 24X Fiche 50~456.84/03/i3,8403i60023
- 8403260361 Notice of appearance in proceeding. Certificate of Syc encl BLODM, J G Commonwealth Edison Co BLODM, J O Isham, Lincoln & Beale DSD 086 84/03/22 3pp 22760 074 24X Fiche 50-455,84/03/22.8403260361
- Q Inspection reports, IE Bulletins & correspondence
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan" Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance
 THOMAS, B Commonwealth Edison Co 84/02/24 KEPPLER, J G Region 3, Office of Director 3pp 22490 139 24X Fiche 50-000,84/02/24,8403050043
- --8403050044 Rev O to "Corporate Regulatory Performance improvement Plan" * Commonwealth Edison Co 84/02/29 22pp 22490 142 24X Fiche: 50-000: 84/02/24, 8403050043
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403060245 Forwards revised info re-preservice exam & testing of shubbers at facilities Encl testing grogram supercedes program provided in 820317 ltr & accepted in SSER 12 TRAMMIT R Commonwealth Edison Co 84/02/28 DENION, H R Office of Nuclear Reactor Regulation, Director 1p. 22316-013 24X Fiche 50-000,84/02/28,8403060245
- --B403060267 Rev 1 to "Preservice Testing (Preservice Insp) Program Plan for Shubbers " * Commonwealth Edison Co B3/10/21, 47pp 22516 014 24X Fiche 30-000.84/02/28,8403060245

- 8402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list enci ORACE., N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000.84/03/02.8402070007
- 8402090008 IE Info Notice 84-i6, "Failure of Automatic Sprinkier Sys Valves to Operate " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc i22pp 22553 098 24X Fiche 50-000,84/03/02,8402070008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JURDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New Yort, Inc. 117pp 22553 217 24X Fiche 50-000,84/03/02,8402070007
- 84020900ii 1E Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nii Ductliity Temp " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,840209001i
- 8402090024 IE Info Notice 84-09.Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc i18pp 22633 049 24X Fiche 50-000.84/03/07.8402090024
- 8402070028 IE Info Natice 84-18, "Stress Corrosion Cracking in PHR Sys " Syc list enc! JURDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc ii8pp 22584 i86 24X Fiche 50-000.84/03/07,8402070028
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Releys in Use in Class IE Safaty Sys " Svc list enci DEYBUNO,R C Director's Dffice. Office of Inspection end Enforcement 84/03/12 Consolidated Edison Co of New York, Inc i34pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403300026 Forwards IE Insp Repts 50-456/84-03 & 50-457/84-03 on 840228-0302 No noncompliance noted PAPERIELLO,C J Region 3, Office of Director 84/03/16 REED.C Componwealth Edison Co 2pp 22817 277 24X Fiche 50-456.84/03/i6. 8403300026
- --B403300033 IE Insp Repts 50~456/B4-03 & 50-457/B4-03 on B4022B-0302 No violations or deviations identified Major areas inspected mpt controls, QA, chemistry program & procedures, actions taken re previous items of noncomplicance & open Items CESTMANN, M J , SLAWINSKI, W J , SCHUMACHER, M C Region 3, Office of Director B4/03/15 Bpp 22819 297 24X Fiche 50-436,84/03/16, B403300026
- 84032300B8 Ack receipt of regulatory performance improvement plan
 Periodic meetings requested to discuss progress on program
 & provide freeback
 KEPPLER.J Q Region 3. Office of Director 84/03/20 YHOMAS.B
 Commonwealth Edison Co ip 22730 161 24X Fiche 50-000,84/03/20,84/03200B8
- --8403230107 Forwards corporate regulatory performence improvement plan THOMAS, B. Commonwealth Edison Co. 84/02/24 KEPPLER, J. Q. Region 3, Office of Director 3pp 22730 162 24% Fiche 30-000. 84/03/20,8403230088
- --8403230126 Rev O to "Corporate Regulatory Performance Improvement Pien For Dresden, Quad Cities, Zion & LaSalle Opereting Nuclear Stations & Byron & Braidwood Project Opereting Organizations " * Commonwealth Edison Co 84/08/29 22pp 22730 165, 24X Fiche 50-000, 84/03/20, 8403230088
- 8403R60196 Forwards responses to IE Builetin B3-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " Guad Cities supplied w/piping matls from Ray Miller, Inc during const Evaluetion encl Concerns of IE Builetin 89-06 satisfied BARNES, P L Commonwealth Edison Co 84/03/20 KEPPLER, J Q Region 3, Office of Director 19pp 22756 185 24X Fiche 50-000,84/03/20,8403280196
- 8402090043 IE Info Notice 84-i9, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities " Svc list enci, JDRDAN.E L Division of Emergency Preparedness & Engineering 830103) 84/03/21 Consolidated Edison Co of New 3pp 22823 229 24X Fiche 50-000,84/03/21,8402090043

- 8402070044 IE Info Notice 84-20, "Svc Life of Releys in Safety-Related Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50~000,84/03/21,8402090044
- 8403270246 Forwards SALP Repts 50-454/83-22:50-455/83-18;50-456/83-06 & 50-457/83-06 for 1982 increased emphasis required in areas of HVAC & electrical sys KEPPLER:J O Region 3, Office of Director 84/03/22 REED,C Commonwealth Edison Co 7pp 22770 135 24X Fichs 50-000;84/03/22, RA03270246
- --8403270260 GALP Repts 50-456/83-06 & 50-457/83-06 for 1982 Cetegory 2 assigned in areas of piping sys & supports & electricel power supply & distribution * Region 3, Office of Director 84/03/22 25pp 22770 203 24x Fiche 50-000,84/03/22,8403270246
- --B403270263 Forwards summary of significant findings for BALP rept which will be discussed et B30613 meeting
 HIND. J A Region 3. Office of Director B3/06/0B REED, C
 Commonwealth Edison Co 3pp 22770 228 24X
 Fiche 50-000, 84/03/22, 8403270246
- R Periodic operating reports & related correspondence
- 8403220120 Annuai whole body external exposures for 1983 W/840316 ltr RYBAK.B Commonweeith Edison Co 83/12/31 7pp 22716 007 24X Fiche 50-000,83/12/31,8403220120
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKB: W J Office of the Executive Director for Operations 84/02/21 PALLADINO Commissioners 9pp 22492 083, 24X Fiche 50-000.84/02/21,8403020443
- S Reportable occurrences, LERs & related correspondence
- B403120013 Interim Deficiency Rept B4-01 re need to improve LK Comstock documentation filing sys Initially reported on 840131 LK Comstock provided three level review to prevent incomplete or unacceptable filing Final rept by 840501 SMARTZ.E D Commonwealth Edison Co 84/03/02 KEPPLER.J Q Region 3, Office of Director 3pp 22588 031 24X Fiche 50-456,84/03/02,840312013
- 8403i40i22 Part 2i rept re status update concerning ebnormal wear on iinear converters Test progrem Underwey Results of investigation indicate excessive wear ceused by hunting of control circuitry DODSON.J P Pacific Air Products Co 84/03/09 Director's Office. Office of Inspection and Enforcement 7pp 22624.068, 24% Fiche 50~000.84/03/09.8403i40122
- 8403i90i93 Final Deficiency Rept 84-02 re incorrectly wired distribution penel IDCOSE Initially reported on 840207. Internet wiring revised to meet approved design drawings Revs to be completed by June 1984 SWARTZ.E D Commonwealth Edison Co 84/03/12 KEPPLER, J. Q. Region 3, Office of Director 2pp 22674 205 24X Fiche 50-456,84/03/12,8403190193
- T Hearing transcripts on non-antitrust matters
- 8403130222 Transcript of ACRS Subcommittee on Braidwood Station 840308 meeting in Joilet, IL Pp 1-163 Viewgrephs enci * ACRS ~ Advisory Committee on Reactor Sefeguards 84/03/08, 185pp 22605 195 24X Fiche 50-456.84/03/08,8403130222.
- 8403140008 Transcript of ACRB Subcommittee on Breidwood Station 840309 meeting in Joliet IL Pp 164-283 Supporting documentation and ** ACRB ~ Advisory Committee on Reactor Bafeguards 84/03/09, 379pp 82631 055 84X Fiche 50-436.84/03/09,8403140008.
- DOCKET STN-50-457 BRAIDWOOD STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8403010106 Forwards addi info re design of Category 1 masonry walls.
 Rept identifies all cracks & explains why cracks do not
 compromise structural integrity of wells
 TRAMMIT R Commonwealth Edison Co 84/02/22 DENTON; H R Office
 of Nuclear Reactor Regulation, Director 16pp. 22436:041 24X
 Fiche 50-000,84/02/22,8403010106

- #2403050245 Forwards revised info re preservice exam & testing of snubbers at facilities Enc] testing program supercedes program provided in 820319 ltr & accepted in SSER 12 TRAMM, T R Commonwealth Edison Co 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 22516 013 24x Fiche 50-000,84/02/28,8403060245
- --8403060267 Rev 1 to "Preservice Testing (Preservice Insp) Program Plan for Shubbers " * Commonwealth Edison Co 83/10/21 47pp 22516 014 24X Fiche 50-000,84/02/28,8403060245
- 3403060394 Advises of changes to schedules for initial fuel loading of facilities Requests NRC resources be allocated to support fuel load after resolution of pending license appeal REED.C Commonwealth Edison Co 84/02/28 DENTUN.H R Office of Nuclear Reactor Regulation, Director 2pp 22518 130 24x Fiche.50~000.84/02/28.8403060394
- 14 03050119 Forwards supplemental response to Generic Ltr 83-28,
 "Required Actions Based on Generic Implications of Balem
 ATMS Events"
 - BARNES,P L Commonwealth Edison Co 84/02/27 DENTON,H R Office of Nuclear Reactor Regulation, Director 26pp 22488 084 24X Fichs. 50-000:84/02/27.8403050119
- 403260182 Clarifies NUREQ-0737, Item II K 3 31, in response to Generic Ltr 83-35 Westinghouse Duners Group authorized program to demonstrate conservatism of WFLASH small break LOCA analyses, per Item II K 3 30 BARNES, PL Commonwealth Edison Co. 84/03/21 EISENHUT, D 0 Division of Licensing 1p 22756 170 24X Fiche 50-000, 84/03/21. 8400300182
- NRC Draft/Final Environmental Statements, supply & correspondence
- 403130037 Ack receipt of DES Meeting tenatively scheduled for 840222 for consideration by Governmental Svcs Committee # Illinois, State of 84/02/02 STEVENS, J A Division of Licensing to 2263 362 24X Fiche 50-456, 84/02/02
- ‡03060313 Provides comments on DES (NUREO-1026) Justification for not providing design analysis of seismic event requested ETCHISON,D Illinois, State of, Dept Nuc Bafety (formerly Dept Public Health) 84/02/22. Division of Licensing. 3pp. 22515 330 24X Fiche 50~456.84/02/22,8403060313
- FO3080227 Lists concerns on proposed water supply sys discussed in Dec 1983 DEB (NUREO-1026), including degradation of water quality from cooling water discharge to Kankakee River QALLACHER,J R Will County, IL 84/03/02 Division of Licensing ip. 22561°031 24X Fiche 50-456,84/03/02,8403080€27
- O3130057 Comments on DEB (NUREO-1026) for facility DEG does night completely describe fuel cycle impact & should contain a tatement re range of nonfatal cancer injuries & birth defects induced by fuel cycle Rn-222
 DDHERTY, J.F. Doberty, J.F. 84/03/07 STEVENS, J.A. Division of Licensing, 2pp 22601 117 24X Fiche: 30-436, 84/03/07.8403:30057
- O3130474 Forwards comments on DES re operation of facilities Major environ concerns identified during 1970s & appropriate mitigating actions to alleviate concerns adequately reflected. More data re aquatic impact should be referenced AENNEY, D Illinois, Btate of 84/03/08 Division of Licensing app. 22613:357. 24% Fiche 50-456.84/03/08.8403130474.
- D314Q001 Forwards comments on DES (NUREQ-1026) Comments submitted for consideration by Commission per 10CFR51 TCDD(NUD)(), CL. Commonwealth Edison Co 84/03/12 Division of licensing. 13pp. 22633; 251 24X Fiche 50-456, 84/03/12, 8403140001
- PCB200104 Discusses review of DEB. Facility will employ two PWRs to produce up to 6850 MHt No major objections to proposed interaction FEB should provide addl radwesta treatment systems. EED, L. O. Environmental Protection Agency 84/03/12 CDUNOBLODE J Licensing Branch 1. 3pp 22685 357 24X iche. 50-456.84/03/12.8403200104
- NRC Safety Evaluation Report (SER), supply & correspondence
- SOBO179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B accument entirely withheld (ref FOIA Exemption 5) Review of add documents subj to request continuing ELTON, J H Division of Rules and Records 84/02/13 ANDERSON, S I Dervay, Schubert Adams & Barer 7pp 22583 226, 24X ichs: 50-000, 84/02/13, 8403080179

- --8005130793 Provides status of SER inputs & acceptance reviews for GL & CP applications Schedule should be met BURKE, W C Effluent Treatment Systems Branch 80/02/06 KREGER, W E Assistant Director for Site Analysis ip 22583 235 24X Fiche 50-4000, 84/02/13,8403080179
- 8403010120 Forwards add1 info to B31230 submittal re NUREO-0737. Item
 III D 1 i. "Primary Coolant Outside Containment " Rev
 identifies portions of sys not to be tested & responds to
 NRC comments Info should close SER Confirmatory Issue 28
 TRAMM, T R Commonwealth Edison Co 84/02/22 DENTON, H R Office
 of Nuclear Resctor Regulation, Director 8pp 22432 002 24X
 Fiche 50-000.84/02/22.8403010120
- 8403010286 Provides addi info re effects of local intense precipitation at facilities Info resolves Confirmatory Issue A 2 identified in SER Reinforced concrete turbs provided at exterior grade floor level doors

 TRAMM.T R Commonwealth Edison Co 84/02/22 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 22434 257 24X

 Fiche 50-000.84/02/22.8403010286
- 8403260132 Submits add1 info re design of hydrogen recombiners per Section 6 2 5 of SER Hydrogen recombiners operate in parallel. utilizing same suction & exhaust piping for each containment Diagram enc1 TRAMM.T R Commonwealth Edison Co 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22758 147 24X Fiche 50-000.84/02/22.8403260132
- F Security, medical, emergency & fire protection plans
- 8403020198 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR YOUNGBLODD, B J Licensing Branch i 84/02/21 FARRAR, D L Comnonwealth Edison Co 2pp 22494 360 24X Fiche 50-000,84/02/21,8403020198
- 8403120008 Advises of 840323 regional workshop in Rosemont, IL w/all Region III licensees to discuss fire protection safe shutdown requirements of 10CFR50.App R Agenda enci SPESSARD.R L Division of Emergency Preparedness & Operational Support 84/03/06 REED.C Commonwealth Edison Co 3pp 2258 260 24X Fiche 50-495.84/03/06.8403120008
- 8403260346 Rev 1 to Emergency Pian Implementing Procedure BZP 380-3, "Post-Accident Stack Sampling of Wide-Range Gas Monitor (WRGM)" * Commonwealth Edison Co 84/03/15 5pp 22751 055 24X Fiche 50-000, 84/03/15, 8403260346

G Adjudicatory correspondence

- B403140040 Comments of JF Doherty on DEB (NUREG-1026) Statement must clarify if, in analysis of environ impacts of postulated accidents, any credit given for applicant compliance w/any THI-related requirements Related correspondence DOHERTY, JF Affiliation Not Assigned 84/03/07 STEVENS, JA Division of Licensing 2pp 22633 120 24X Fiche 50-456,84/03/07,8403140040
- B403i600li Forwards C Reed 840228 itr re-schedule for fuel loading dates & notice of appearance W/o notice of appearance Related correspondence QALLO.J Isham Lincoln & Beale GALLO.J Commonwealth Edison Co 84/03/13 MILLER.M E. CALLIHAN.A D. CDLE.R F. Atomic Safety and Litensing Board Panel 3pp 22655 id8 24X Fiche 50-456.84/03/13-8403i60011
- 8403140023 Notice of appearance in proceeding Certificate of Syc enci 9ALLO, J Commonwealth Edison Co OALLO, J Isham, Lincoln & Beale 84/03/13 2pp 22453 353 24X Fiche 50-456,84/03/13,8403140023
- B403260361 Notice of appearance in proceeding.Certificate of Svc encl BLDOM,J G Commonwealth Edison Co BLOOM,J G Ishem, Lincoln & Beale DSB 086 84/03/22 3pp 22760 074 24X Fiche 50-496.B4/03/22.8403260361
- Q Inspection reports: IE Bulletins & correspondence
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan " Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER.J. O Region 3. Office of Director 3pp 22490 139 24X Fiche 50-000,84/02/24. 8403050043

- --8403050046 Rev O to "Corporate Regulatory Performance improvement
 - E Commonwealth Edison Co 84/02/29 22pp 22490 142 24X Fiche 50-000,84/02/24,8403050043
- 8401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl
 - enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239 24% Fiche 50-000,84/02/28,8401190072
- 8403060245 Forwards revised info re preservice exam & testing of snubbers at facilities Enci testing program supercedes program provided in 85c8 12 TRAMM.T R Commonwealth Edison Co 84/02/20 DENTON, H R On of Nuclear Reactor Regulation. Director 1p 22516 013 24X Fiche 50-000.84/02/28.8403060245
- --8403060267 Rev 1 to "Preservice Testing (Preservice Insp) Program Plan for Snubbers " * Commonwealth Edison Co 83/10/21 47pp 22516 014 24X Fiche 50-000, 84/02/28, 8403060245
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACELJ N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402070007
- 8402090008 IE info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02, 8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" 102070007 IE Info Number 5.... Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc. 117pp 22553 217 24X Fiche 50-000,84/03/02,8402070007
- 840207001i IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Beiow Nii Ductility Temp " Svc list encl JORDAN, E Division of Emergency Preparedness & Engineering Respense (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402070011
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- B402090028 IE Info Notice B4-18, "Stress Corrosion Cracking in PWR 02090028 IE Info Notice 84-18, "Stress corrosion cracking in PWA Sys " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 886 24X Fiche 30-000.84/03/07.8402070028
- 8402090031 IE Bulletin B4-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl
 DEYOUNG.R C Director's Office of Office of Inspection and
 Enforcement 84/03/12 Consolidated Edison Co of New York, Inc
 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403300026 Forwards IE Insp Repts 50-456/84-03 & 50-457/84-03 on B40228-0302 No noncompliance noted PAPERIELLO.C J Region 3, Office of Director 84/03/16 REED.C Commonwealth Edison Co 2pp 22819 277 24X Fiche 50-456,84/03/16,
- --B403300033 IE Insp Repts 50-456/84-03 & 50-457/84-03 on 840228-0302 No violations or deviations identified Hajor areas inspected mgt controls (Acchemistry program & procedures actions taken represented the program of the provious items of noncomplicance & open items OESTMANN, M. J. SLAWINSKI, W. J. SCHUMACHER, M. C. Region 3, Office of Director 84/03/15 8pp 22819 299 24X Fiche 50-456,84/03/16,8403300026
- 8403230088 Ack receipt of regulatory performance improvement plan Periodic meetings requested to discuss progress on program & provide feedback KEPPLER.J.G. Region 3. Office of Director 84/03/20 THOMAS.E KEPPLER, J G Region 3. Office of Director 84/03/20 THOMAS, B Commonwealth Edison Co ip 22730 161 24% Fiche 50-000,84/03/20, 8403230088
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAS. B. Commonwealth Edison Co. 84/02/24 KEPPLER J G. Region 3, Office of Director 3pp 22730 162 24x Fiche 50-000, 84/03/20,8403230088

- --B403230126 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden Guad Cities Zion & LaSaile Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations "

 * Commonwealth Edison Co 84/02

 Fiche 50-000,84/03/20,8403230088 84/02/29 22pp 22730 (65 24X
- 8403260196 Forwards responses to 1E Bulletin 83-07, "Apparently Fraudulent Products 8old by Ray Miller, Inc " Guad Cities supplied W/piping matts from Ray Miller, Inc during const Evaluation enci Concerns of 1E Bulletin 83-06 satisfied BARNES; P. L. Commonwealth Edison Co. 84/03/20 KEPPLER, J. O. 3, Office of Director 19pp. 22756 185 24% Fichs 30-000,848403260196 24X Fiche 30-000, 84/03/20,
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of t 123pp 22823 229 24x Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Byc Life of Relays in Safety-Related Svc list encl Sys "Syc list enci JORDAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co 22933 001 24X Fiche 50-000, 84/03/21, 8402090044 York, Inc. 135pp
- 8403270246 Forwards SALP Repts 50-454/83-22,50-455/83-18,50-456/83-06 & 50-457/83-06 for 1982 increased emphasis required in areas NOT HVAC & electrical sys KEPPLER, J O Region 3. Office of Director 84/03/22 REED, C Commonwealth Edison Co 7pp 22770 135 24X Fiche 50-000, 84/03/22,
- --8403270260 SALP Repts 50-456/83-06 & 50-457/83-06 for 1982 Category 2 assigned in areas of piping sys & supports & electrical power supply & distribution Region 3. Office of Director 84/03/22 25pp 22770 203 24X Fichs 50-000,84/03/22,8403270246
- --B403270263 Forwards summary of significant findings for BALP rept which will be discussed at 830613 meeting
 HIND: J A Region 3. Office of Director 83/06/08 REED, C
 Commonwealth Edison Co 3pp 22770 228 24X
 Fiche 50-000.84/03/22.8403270246
- R Periodic operating reports & related correspondence
- 8403220120 Annual whole body external exposures for 1983 H/B40316 ltr RYBAK, B Commonwealth Edison Co 83/12/31, 7pp 22716 007 24X Fiche 50-000, 83/12/31, 8403220120
- 8 Reportable occurrences, LERs & related correspondence
- 8403120013 Interim Deficiency Rept 84-01 re need to improve LK Comstock ACCURATION OF THE PROPERTY OF Region
- 8403190193 Final Deficiency Rept 84-02 re incorrectly wired distribution panel IDCOSE Initially reported on 840207. Internal wiring revised to meet approved design drawings Revs to be completed by June 1984 SWARTZ,E D Commonwealth Edison Co 84/03/12 KEPPLER,J. 0 Regio 3, Office of Director 2pp 22674 205 24X Fiche 50-456,84/03/12,8403190193
- T Hearing transcripts on non-antitrust matters
- 8403i30222 Transcript of ACRS Subcommittee on Braidwood Station 840308 meeting in Jolist IL Pp 1-163 Viewgraphs encl * ACRS Advisory Committee on Reactor Safaguards 84/03/08 185pp 22605 195 24% Fitchs 50-456.84/03/08.8403130222
- 8403140008 Transcript of ACRS Bubcommittee on Braidwood Station 840309 meeting in Joliet, IL Pp 164-283 Bupporting documentation encl encl Advisory Committee on Reactor Safeguards 84// 379pp 22631 035 24% Fiche 50-456.84/03/07.8403140008

- DOCKET 50-458 RIVER BEND STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8403070061 Forwards responses to Containment Sys Branch Questions 480 7 & 480 16 re PRV & major components & suppression pool bypass lackage & FSAR revs to be included in next amend BOOKER. J E Quif States Utilities Co 84/02/17 DENTON, H R Office of Nuclear Reactor Regulation. Director 16pp 22541 310 24X Fiche: 50-458,84/02/17,8403070061
- 8403080378 Forwards responses to NRC 840106 questions re FSAR revs. including info re training staff qualifications. OA staff qualifications. FSAR revs. Reg Guide 8 13 Proposed revs to FSAR also enci BOOKER. J E Guif States Utilities Co 84/02/17 DENTON. H R OFFice of Nuclear Reactor Regulation. Director 42pp 22556 200 24X Fiche 50-458.84/02/17.8403080378
- 8403070350 Forwards request for addl info re spent fuel rack welding details & structural design.based on review of application for OL SCHWENCER.A. Licensing Branch 2 84/02/23 CAHILL.W J. BOOKER.J E Gulf States Utilities Co 5pp 22564 127 24X Fiche 50-458.84/02/23.8403070350
- 8403010321 Notifies that structures adjacent to Unit 2 excavation area under analysis for effects of excavation pending per revised design basis flood analysis Ponding will not produce significant add1 structural loads
 BOUKER, J. E. Oulf States Utilities Co. 84/02/27 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 22432.101 24X
 Fichs. 50-458, 84/02/27, 8403010321
- B403070052 Forwards clarifications to Procedures & Sys Review Branch quastions. Changes to FSAR will be incorporated in next amend BOCKER, J E Oulf States Utilities Co 84/02/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 21pp 22541 102 24X Fiche: 50-458, 84/02/27, 8403070052
- 8403020274 Provides info re status of generic & plant-specific work concerning containment issues raised by Humphreys, per util 830815 commitment Status rept will be provided by 840731 BOOKER, J E Oulf States Utilitles Co. 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22440, 048 24X Fiche 50-458, 84/02/28, 8403020274
- B40305007B Forwards "Historical & Archaeological Investigation of Ruins of Nineteenth Cantury Sugar Mill (16WF-36) in West Feliciana Perish.LA " Determination re Natl Register eligibility requested BOOKER, J E Gulf States Utilities Co 84/03/01 DEBLIEUX.R.8 Louisiana, State of 1p 22485 152 24X Fiche 50-458,84/03/01,8403050078
- --8403050081 "Historical & Archaeological Investigation of Ruins of Nineteenth Century Sugar Mill (16MF-36) in West Feliciana Parish.LA " BHUMAN.M K Affiliation Not Assigned ORBER.C E Louisiana State Univ 84/02/10 56pp 22485 153 24X Fiche 50-458.84/03/01. 8403050078
- 8403070010 Forwards celculeted methodology for source terms & source distribution pathways based on design besis LOCA for equipment qualification radiation environs EDOKER, J. E Oulf States Utilities Co 84/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 22547 332 24X Fiche 30~458,84/03/01,8403070010
- B403130170 Forwards response to NRC 801222 request for review of controls for handling heavy loads, as committed to in 830807 ltr Response to items in Section 2 1 of 801222 ltr also encl
 BODKER, J E. Oulf States Utilities Co 84/03/01 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 63pp 22606.063 24X Fiche 50-458,84/03/01,8403130190
- 8403210067 Forwards responses to Power Bys Branch request for add1 info re mat1 contained in 831230 & 840210 correspondence, including diesel generator operations training & fuel oil storage tank Changes will be incorporated in FSAR amend BOOKER, J E Gulf States Utilities Co. 84/03/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 150pp 22702 124 24X Fiche 50-458,84/03/05,8403210069
- 8403260180 Forwards operating shift experience tables.per DF Bchnell request OBELL,W H. Gulf States Utilities Co. 84/03/06 THOMPSON,H Division of Human Factors Safety 9pp 22751 046 24X Fichs. 30-458,84/03/06,8403260180

- 8403300272 Summary of 840215 meeting w/util in Bethesda, ND re Power Sys Branch review items Topics discussed re mechanical & electrical areas identified Attendee list encl WEINKAM.S J Licensing Branch 2 84/03/06 Licensing Branch 2 5pp. 22844 321 24X Fiche 50-458,84/03/06,8403300292
- B403200034 Forwards response to Power Sys Branch request for additions ags, lighting sys & circuit configuration curves Written changes to FSAR text, including table & figures, also encl BODKER, J E Oulf States Utilities Co 84/03/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 22685 145 24% Fiche 50-458, 84/03/07, 8403200034
- 8403260291 Forwards organization charts re corporate structure, plant administrative structure & project mgt structure Changes will be supplied in form of FSAR test rev in future submittel & FSAR amend BOCKER. J E Gulf States Utilities Co 84/03/16 DENTON, H R Office of Nuclear Reactor Regulation. Director ip 22751 070 Fiche 30-458.84/03/16.8403260291
- 8403220209 Forwards Army Corps of Engineers B31127 ltr re Old River Control project, in response to NRC request. Damage sustained by low sill structure in 1973 resolved W/four oversize brochures Aperture cards are available in FDR B00KER. J E Oulf States Utilities Co 84/03/19 DENTON, H R Office of Nuclear Reactor Regulation. Director 13pp 22718 193 24X Fiche 50-458,84/03/19,8403220209
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403070062 Forwards supplemental responses to requests for addl info draft SER open items, identified by Mechanical Engineering Branch in 831229 ltr Where indicated, responses will be provided in future amend to FSAR BOOKER.J E Guif States Utilities Co 84/02/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 29pp 22548 014 24X Fiche 50~458.84/02/21.8403070062
- 8403130069 Forwards responses to open items in Auxiliary Sys Branch draft SER & NRC 810805 & 1231 requests for addl info Responses supplement util 831201.30 & 840202 submittals BOOKER, J E Oulf States Utilitles Co 84/03/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 23pp 22615.222 24X Fiche 50-458,84/03/06,8403130069
- B403190017 Forwards response to NRC 840123 position re drywell/
 containment purge sys Discussions held on 840131 w/
 Containment Sys Branch clarified bases for position &
 detailed util responses for input to SER
 BHOKERJ E Oulf States Utilities Co 84/03/13 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 6pp 22665 354
 24X Fiche 50-458,84/03/13,8403190017
- F Security, medical, emergency & fire protection plans
- 840326060 Forwards IE Coordination Meeting Rept 50~438/83-18 on 831003 No violations or deviations identified JOHNSON.E H Region 4. Office of Director 84/01/12 CAHILL.W J Gulf States Utilities Co 2pp 22746 360 24X Fich# 50-458.84/01/12.8403260060
- --8403260068 IE Coordination Meeting Rept 50-458/83-18 on 831003 No violations or deviations identified Details withheld (ref 10CFR2 790).
 KELLY, J A , HALL, R E , CROSSMAN, W A Region 4, Office of Director 83/12/30 ip 22746 362 24X Fiche 50-458,84/01/12,8403260060
- 8403260217 Forwards IE Insp Rept 50-458/84-03 on 840109-13 No violations or deviations noted JOHNSON/E H Region 4, Office of Director 84/02/06 CAHILL,W Gulf States Utilities Co 2pp 22756 154 24% Fiche.50-458,84/02/06,8403260217
- --8403260220 IE Insp Rept 50-458/84-03 on 840107-13 No viplations or deviations noted Major areas inspected physical security plan & implementing procedures Details withheld (ref 10CFR73 21)

 EVANS.C A , KELLY, J A , CROBSMAN, W A Region 4, Office of Director 84/02/06 ip 22756 156 24X Fiche 50-458, 84/02/06, 8403260217
- B403050145 Notifies that NRC will provide inspectors to observe onsite aspects of periodic exercises for emergency preparedness Scenario for submission of info listed COLLING.J T Region A. Office of Director B4/02/09 CAHILL.W J Quif States Utilities Co 2pp 22487 310 24% Fiche 50-458,84/02/09.8403050145

- 8403080378 Forwards responses to NRC 840106 questions re FSAR revs, including info re training staff qualifications. GA staff qualifications, fire protection training & conformance to Reg Guide B i3 Proposed revs to FSAR also entl 800KER. J E Guif States Utilities Co 84/02/17 DENTON, H R Office of Nuclear Reactor Regulation. Director 42pp 22556 200 24X Fiche 50-459.84/02/17.8403080378
- B403130486 Forwards add1 info re Generic Ltr B2-33. "Suppl 1 to NUREG-0737 - Requirements for Emergency Response Capability " Info suppls emergency operating procedures generation package submitted 830831 B0DKER.J E Quif States Utilities Co 84/02/27 DENTON, H R Office of Nuclear Reactor Regulation. Director 4pp 22614 009 24X Fiche 30-459.84/02/27.8403130486
- --8403130487 Rev 1 to Procedure ADM-0003, "Development, Control & Use of Procedures" HAMMOND, E Gulf States Utilities Co 84/02/13 38pp 22614 013 24X Fiche 50-458.84/02/27.8403130486
- B403140196 Notification of 840314 meeting w/util & 56M in Bethesda.MD to discuss design of control room w/respect to fire protection aiternate & safe shutdown MEINKAM.E J Licensing Branch 2 84/03/02 SCHWENCER.A Licensing Branch 2 3pp 22637 352 24X Fiche 50-458,84/03/02.8403140196
- 8403130393 Forwards Rev 2 to physical security plan & explanation of major changes to facilitate review Rev & explanation withheld (ref 10CFR2 790)
 CAMILL, W. J. Guif States Utilities Co. 84/03/07 DENTON, H. R. Defice of Nuclear Reactor Regulation, Director 1p. 22616 273 24X
 Fiche 50-458,84/03/07,8403130393
- G Adjudicatory correspondence
- B403140009 Forwards offsite emergency pianning Contentions 1-12 WATKINS.L B Watkins. L B 84/03/09 Atomic Safety and Licensing Board Panel ip 22633 267 24% Fiche 50-458.84/03/09.8403140009
- --8403140012 Proposed emergency planning Contentions i-12.identifying major flaws in emergency plan Certificate of Svc enci IRVING. S M. WATKING.L B. PIERCE.J W. Joint intervenors River Bend 84/03/13 Atomic Safety and Licensing Board Panel 20p; 22833 248 24X Fiche 50-458.84/03/09.8403140009
- B403290392 Answer opposing Joint Intervenors B40309 contentions re offsite emergency planning No contention meets basis & specificity requirements of iOCFR2 714 W/svc list WETTERHAHN, M J Gulf States Utilities Co WETTERHAHN, M J Conner & Wetterhahn DSB 193 B4/03/26 Atomic Bafety and Licensing Board Panel 38pp 22814 342 24X Fiche 50-458,84/03/26,8403290392
- 8403300025 Order establishing purpose of 840418 prehearing conference Berved on 840327 COTTER, B P Atomic Safety and Licensing Board Panel 84/03/28 3pp 22822 182 24X Fiche 50-458,84/03/28,8403300025

M Antitrust correspondence

- 8403220271 Requests clarification k/or comments on listed items or documents as result of review of updated responses to Reg Guide 9 3.per antitrust review Response requested within 14 days from Itr date REGAN, H Site Analysis Branch 84/03/12 CAHILL, W J Guif States Utilities Co 3pp 22723 317 24X Fiche 50-438.84/03/12, 840320271
- B403280161 Ack receipt of B30915 & 840203 ltrs responding to NRC request for addi into re antitrust review Listed addl into requested within 14 days of ltr receipt & prior to setting up meeting to resolve issues
 REGAN,W H Site Analysis Branch 84/03/12 SPIEGEL, G Spiegei, G 2pp 22809 292 24X Fichs 50-458.84/03/12, B403280161
- 8403280032 Forwards response to 840312 request for add1 info re antitrust review & draft proposed reliability coordination agreement Draft agreement prepared by Middle South Utils unacceptable CAHILLIW J Gulf States Utilities Co 84/03/23 REGAN.W H Siting Analysis Branch. 1,673pp 22778 ii6 24% Fiche 50-458.84/03/23.8403280032
- 8403270176 Forwards addl matls requested in NRC 840312 ltr re antitrust review Util attempting to lock St Martinville into renewed long-term commitment OUTINAN.D Spiegel & McDiarmid 84/03/26 REGAN.W Site Analysis Branch 226pp 22802 210 24X Fiche 50-458,84/03/26,8403270176

- @ Inspection reports: IE Builetins & correspondence
- B403260060 Forwards IE Coordination Meeting Rept 50-458/83-18 on B31003 No violations or deviations identified JOHNSON.E H Region 4. Dffice of Director B4/01/12 CAHILL.W J Oulf States Utilities Co 2pp 22746 360 24X Fiche 50-458.84/01/12.8403260060
- --8403260068 IE Coordination Meeting Rept 50-458/83-18 on 831003 No violations or deviations identified Details withheld (ref 10CFR2 790) KELLY,J A. HALL,R E. CROSSMAN,W A. Region 4, Office of Director 83/12/30 ip 22746 362 24X Fiche 50-458,84/01/12,8403260060
- B403260217 Forwards 1E Insp Rept 50-458/B4-03 on 840109-13. No violations or deviations noted JOHNSON, E H Region 4, Office of Director 84/02/06 CAHILL, W Guif States Utilities Co 2pp 22756 154 24X Fiche 50-458, 84/02/06, 8403260217
- --B403260220 IE Insp Rept 50-458/84-03 on B40109-13 No violations or deviations noted Major areas inspected physical security plan & implementing procedures Details withheld (ref 100FR73 21)
 EVANS,C A : KELLY, J A : CROSSMAN,W A Region 4, Office of Director B4/02/06 ip 22756 156 24X Fiche 50-458,84/02/06,8403260217
- 8403050127 Forwards iE Insp Rept 50-458/83-21 on 831118-840120. No violations or deviations noted JOHNSON, E H Region 4, Office of Director, B4/02/14 CAHILL, W J Oulf Btates Utilities Co 2pp 22487 102 24X Fiche 50-458,84/02/14,8403050127
- --B403050134 IE Insp Rept 50-458/83-21 on 831118-840120 No violations or deviations noted Major areas inspected site tour-licensee identified deficiency rept.safety-related piping & hanger installation & electrical cable & raceway installation. FARRELL R E , CROSSMAN, M A Region 4, Office of Director 84/02/14 5pp 22489 i04 24X Fichs 50-458.84/02/14.8403050129
- B403120065 Forwards IE Insp Rept 50-458/83-22 on B31201-B40131 & notice of violation
 JOHNSON,E H Region 4, Office of Director B4/02/22 CAHILL, W J,
 Quif States Utilities Co 2pp 22586 292 24X
 Fiche 50-458,84/02/22,8403120065
- --8403120067 Notice of violation from insp on 831201-840131. * Region 4, Office of Director 84/02/22 3pp 22586 294 24X Ficha 50-458,84/02/22.8403120065
- --8403120072 IE insp Regt 50-458/83-22 nn B3i201-840i31 Vioiation identified failure of foliowup action in audit program & records of activities affecting quality not identifiable or retrievable CHAMBERLAIN,D., CROSSMAN,W.A. Region 4, Office of Director 84/02/21 5pp 22886 297 24X Fiche 50-458,84/02/22,8403120065
- 8401190072 iE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Gontrol Circuits & Annunciation " Svc iist enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. ii5pp 22909 239 24X Fiche 50-000.84/02/28,8401190072
- B402090007 IE Info Notice B4-i4, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of GA: Bafeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co. of New York, Inc. 130pp 22552:329 24X Fiche 50-000:84/03/02.8402090007.
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Bprinkler Sys Valves to Operate " Svc list enci JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche.50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Bvc list encl. JURDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. i19pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 84020900i1 iE Info Notice 84-i7, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05. Consolidated Edison Co. of New York, Inc 117pp 22553 336 24X Fiche.50-000.84/03/05.8402070011

- 8402070024 IE Info Notice 84-07, Rev 1. "Lessons Learned From Insps of Firs Protection Safe Shutdown Sys " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 11899 22638 049 24X Fichs 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " 8vc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000.84/03/07,8402090028
- 8403130438 Ack receipt of 840206 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-458/83-20 JOHNSON, EH Region 4, Office of Director 84/03/08 CAHILL, W J Ouif States Utilities Co. ip. 82613
- --8403130448 Responds to NRC 840109 itr re violations noted in IE Insp Rept 50-458/83-20 Corrective actions FSAR changed per Change Notice F8 3 9, Rev 1, to accurately reflect loading calculation CAMILL.W.J. Gulf States Utilities Co. 84/02/06 COLLINS, J T Region 4, Office of Director 4pp. 22613 319 24X Fichs 50-459,84/03/08,840310438
- 8402070031 IE Bulletin 84-02. "Failures of CE Type HFA Relays in Use in Class IE Bafety Bys " Bvc list enc! DEYDUNO.R C. Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823.074 24% Fiche 50-000.84/03/12.8402070031.
- 8403160235 Forwards vendor insp repts identifying concerns found by Vendor Program Branch during insp of vendor activities Evaluation of significance of findings re quality & acceptability of product or svc requested JOHNSON,E H Region 4, Office of Director 84/03/13 CAHILL,W S Quif Btates Utilities Co 2pp 22661 043 24X Fiche 50-458,84/03/13,8403160235
- 8402070043 IE Info Notice 84-17, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities " Evo list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York: Inc 123pp 22823 229. 24X Fiche. 50-000,84/03/21,8402070043
- 8402070044 IE Info Notice 84-20, "8vc Life of Relays in Safety-Related Bys " 8vc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/2! Consolidated Edison Co of New York, Inc. 135pp. 22933 00: 24X Fiche-50-000,84/03/2!,8402090044
- 8403270070 Ack receipt of 840217 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-458/83-19 JDHN80N.E.H Region 4. Office of Director. 84/03/23 CAHILL, W J Gulf Btates Utilities Co ip 22766 327 24X fiche 50-458.
- --8403270076 Responds to NRC 840120 Itr re violations noted in IE Insp Rept 30-458/83-19 Corrective actions Process Requirement Sheet (PRS) 2 re-socket welds revised & insp personnel retrained to requirements of GAI 10-1 & PRS-02, Rev 7. CAHILL.M. J. Gulf States Utilities Co. 84/02/17 COLLINS, J.T. Region 4, Office of Director. 4Pp 22766:328 24X Fishe 50-458,84/03/23,8403270070.
- R. Periodic operating reports & related correspondence
- B403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1784 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues.

 DIRGKS.W.J. Office of the Executive Director for Operations B4/02/21, PALLADINO Commissioners 7pp. 22492.083, 24X Fiche.30-000,84/02/21,8403020443
- 🖰. Reportable occurrences, LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Trensemerica Delaval, Inc DIRCKS: M. J. Office of the Executive Director for Operations 8ECY-03-034 84/01/25 App. 22438 347 24X Fiche 50-000,84/01/25,8403010451.
- 8403010073 Interim Deficiency Rept DR-147 re end attachment of pips support component supplied by Bergen-Paterson, Investigation continuing, Next rept expected by 840403 BOOKER, J. E. Oulf States Utilities Co. 84/02/23 COLLINS, J. T. Region 4. Office of Director. 1p. 22432-001, 24X Fiche: 50-458,84/02/23,8403010073.

- 8403010228 Interim Deficiency Rept DR-134 re four lines located at outlet of each RHR sys HX shell Investigation incomplete
 Next status rept will be submitted by 840425
 BODKER, J E Gulf States Utilities Co 84/02/23 COLLINS, J T
 Region 4. Office of Director 1p 22435 176 24X
 Fiche 50-458,84/02/23.8403010228
- B403010379 Interim Deficiency Rept DR-162 re ABOL10 trip coils supplie by Gould Investigation incomplete Next rept will be submittd by B40430 BOOKER.J E Gulf States Utilities Co B4/02/23 COLLING.J T Region 4. Office of Director 1p 22434 OB1 24X Fiche 50-458.84/02/23.8403010379
- B403010207 Forwards "Investigation of Tupes AF & AE Piston Skirts," per TransAmerica Delaval. Inc Owners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Orand Gulf Nuclear Power Stations
 MUSELER.W J TDI (Transamerica Delaval, Inc.) Owners Group B4/02/27 DENTON.H R Office of Nuclear Reactor Regulation,
 Director 3pp 22434 090 24% Fiche 50-000,84/02/27,8403010207
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc emergency diesel generators MUSELER.W J TDI (Transamerica Delaval, Inc.) Owners Group 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Fiche 50-000,84/02/28,8403010218
- 8403060320 Final Deficiency Rept DR-92 re Category I stainless steel thermowells supplied by PYCO, Inc Condition not reportable per 10GFR50 55(e)
 BOOKER, J E Quif States Utilities Co 84/02/28 COLLINS, J T Region 4. Office of Director 1p \$2517 362 24X
 Fiche. 50-458, 84/02/28, 8403060320
- B403130264 Interim Deficiency Rept DR-127 re Agastat relays w/CR0095 bases supplied by GE Investigation incomplete Next rept will be submitted by B40427
 BDOKER.JE Quif States Utilities Co 84/02/28 COLLINS.JT Region 4. Office of Director Ip 22607 138 24X Fiche 50-458,84/02/28.8403130264
- 8403130175 Interim Deficiency Rept DR~163 re set screw over key on drive hub for overspeed governor fuel transfer pump drive in standby diesel generator A supplied by Transmerica Belaval. Inc Investigation incamplete Next rept by 840430 BODKER. J E Gulf States Utilities Co 84/03/02 COLLINS, J T Region 4. Office of Director 1p 22615 298 24X Fichs 50-458.84/03/02,8403130175
- 8403440048 Forwards "Orand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delavai, Inc Diesei Generators Owners Group Program Plan," to resolve concerns w/emerators MUSELER.W J Long Island Lighting Co 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 22626 062 24X Fiche 50-000,84/03/02,8403440048
- --8403140095 "Transamerica Delaval, Inc Diesel Generatora Dwners Group Program Plan " * TDI (Transamerica Delaval, Inc) Owners Group 84/03/02 261pp 22628 223 24X Fiche 50-000,84/03/02,8403140048
- 8403160310 Interim Deficiency Rept DR-164 re intermixed electrodes Investigation incomplete Next rept by 840425 BODKER, J E Guif States Utilities Co 84/03/07 CDLLING, J T Region 4. Office of Director 1p 22660 273 24X Fiche 50-458,84/03/07.8403160310
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 14 meetings between NRC & Transamerica Delaval.Inc (TDI) Duners Group. Distribution list and EISENHUT.D G Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fiche. 50-000.84/03/12, 8402090039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Duners Group in Bethesda, MD re problems w/emergency
 diese) generators
 CARUSO,R. Licensing Branch 2 84/02/27 G'REILLY, J.P. NRC No
 Detailed Affiliation Given 6pp 22708-006. 24X
 Fiche: 50-000, 84/03/12: 84020
- --8403060554 Transcript of B40210 meeting w/Transamerica Delayal.Inc Owners Group in Bethesda.MD re problems w/amergency diesel generators * NRC - No Detailed Affiliation Civen 84/02/10, 147pp 67201 008 24X Fiche 50-000.84/03/12.8402090039

- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Dwners Group in Wading River.NY re program plan to establish reliability of diesel generators Agenda.meeting transcript & attendance list encl MILLER.H A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 50-000.84/03/12.8402090039
- --BA03070423 Transcript of B40216 conference in Hading River,NY re Transamerica Delaval, Inc diesel generators Pp I-B2 * Commissioners 84/02/16 B4pp 22708 169 24X Fiche 30-000.84/03/12.8402070039
- 8403140030 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators MUSELER.W J Long island Lighting Co 84/03/12 DENTON.H R Defice of Nuclear Reactor Regulation. Director 2pp 22632 074 24X Fichs 50-000,84/03/12,8403140050
- 8403150133 Forwards "Transamerica Delaval Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & svc conditions MUSELER.W J TDI (Transamerica Delavai Inc.) Gwners Group 84/03/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000.84/03/13,8403150133
- 8403270039 Interim Deficiency Rept DR-166 re incation of terminal blocks Investigation incomplete Interim or final rept will be provided by 840511
 BOOKER, J E Oulf States Utilities Co 84/03/15 COLLINS, J T Region 4. Office of Director ip 22769 321 24X Fiche 50-458,84/03/15,8403270039
- 8403270201 Interim Deficiency Rept DR-165 re copper bus bars supplied by Southern Metais Corp & Gulf Coast Supply Investigation incompiete Next rept will be provided by 840515 BODKER, J E Gulf States Utilities Co 84/03/15 COLLING, J T Region 4, Office of Director ip 22772 138 24X Fiche 50-458, 84/03/15, 8403270201
- B403200222 Responds to B40214 Requests for info i & 2 re R-4 series engines List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started enci
 MATHEWS, C 5 Transamerica Deiavai, Inc B4/03/16 EISENHUT, D Q
 Division of Licensing 20pp 22691 i79 24% Fiche 50-000, 84/03/16; 8403200222
- 8403270026 Interim Deficiency Rept DR-152 re wire terminations in ABO-voit standby motor control ctrs supplied by Gould Brown Boveri Investigation incomplete Interim or final rept expected by 840514 BODKER. J E Gulf States Utilities Co 84/03/16 COLLINS, J T Region 4. DPfice of Director ip 22769 341 24X Fiche 50-458,84/03/16,8403270026
- 8403270045 Interim Deficiency Rept DR-112 re Class IE battery chargers supplied by Power Conversion Products Investigation incomplete Interim or final rept to be submitted by 840413 mcomplete Interim or final rept to be submitted by 840413 mcoMER. J E Gulf States Utilities Co 84/03/16 COLLINS. J T Region 4. Dffice of Director ip 22769 314 24% Fiche 50-458.84/03/16.8403270045
- 8403270132 Forwards "Emergency Diesel Generator Air Start Vaive Capacrew Dimension & Stress Analysis." prepared by S&W for Transamerica Delaval. Inc (TDI) Diesel Generator Duners Oroup MUSELER.W J TDI (Transamerica Delaval, Inc.) Duners Group B4/03/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22774 001 24% Fiche 50-000,84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term Corrective actions & investigations re Transamerica
 Delaval diesel generators List of suggested meeting topics
 encl
 MCOAUGHY, J P TDI (Transamerica Delaval, ln.) Duners Group
 84/03/23 DENTON: R Office of Nuclear Reactor Regulation,
 Director 4pp 22769 133 24X Fiche 50-000, 84/03/23, 8403270134

T Hearing transcripts on non-antitrust matters

8402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of B40210 & 16 meetings between NRC & Transamerica Delaval, Inc (TD1) Owners Group, Distribution list encl.
ELISENHUT, D @ Division of Licensing 84/03/12 PALLADING Commissioners 3pp 22708,001 24X Fichs, 50-000, 84/03/12, 8402070039

- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Guners Group in Bethesda: MD re problems w/emergency
 diesel generators
 CARUBO, R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No
 Detailed Affiliation Given App 22708 006 24X
 Fiche 50-000, 84/03/12, 8402090039
- --B403060554 Transcript of B40210 meeting w/Transamerica Delaval.Inc Owners Group in Bethesda.MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Olven 84/02/10. 147pp 67201 008 24X Fiche 50-000,84/03/12.8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delavai. Inc Owners Group in Wading River.NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl MILLER.H A Licensing Branch 4 84/02/27, Licensing Branch 4. 8pp. 22708 161 24X Fiche. 50-000.84/03/12,8402090037.
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval. Inc diesel generators Pp 1-82. * Commissioners. 84/02/16 84pp 22708.169 24X Fiche 50-000,84/03/12.8402090037
- V Operator Examinations
- 8403260180 Forwards operating shift experience tables,per DF Schnell request UDELL.W H Guif States Utilities Co 84/03/06 THOMPSON,H Division of Human Factors Safety 9pp. 22751.046 24X Fiche 50-458.84/03/06.8403260180

DUCKET 50-459 RIVER BEND STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8403070061 Forwards responses to Containment Bys Branch Questions 480 7 & 480 16 re PRV & major components & suppression pool bypass leakage & F6AR revs to be included in next amend.
 BODKER.J E Quif States Utilities Co 84/02/17, DENTON, H R
 Office of Nuclear Reactor Regulation, Director. 16pp 22541 310
 24X Fichs 50-458,84/02/17,8403070061
- 8403080378 Forwards responses to NRC 840106 questions re FSAR revalinctuding info re training staff qualifications. GA staff qualifications, fire protection training & conformance to Reg Ouide 8 19 Proposed revs to FSAR also enci.

 BOOKER, J E Guif States Utilities Co 84/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 42pp. 22556.200 24X Fiche 50-458.84/02/17,8403080378
- 8403010321 Notifies that structures adjacent to Unit 2 excavation area under analysis for effects of excavation ponding per revised design basis flood analysis Ponding will not produce significant addi structural loads

 BOOKER, J E Oulf States Utilities Co 84/02/27, DENTON, H R Office of Nuclear Reactor Regulation, Director 1p. 22432 101, 24X Fiche 50-458.84/02/27,8403010321
- 8403070052 Forwards ciarifications to Procedures & Bys Review Branch questions Changes to FBAR wiil be incorporated in next amand BOOKER, JE Quif States Utilities Co 84/02/27 DENTON, H R, Office of Nuclear Reactor Regulation, Director Ripp, 22541:102, 24X Fiche 30-458.84/02/27,8403070052
- 8403050078 Forwards "Historical & Archaeological Investigation of Ruins of Mineteenth Century Sugar M(1) (16HF-36) in West Feliciana Parish.LA "Determination re Natl Register sligibility requested BOOKER.JE Gulf States Utilities Co. 84/03/01 DEBLIEUX.R.B. Louisiana, State of 1p 22485 152 24X Fiche 50-458,84/03/01,8403050078.
- --8403050081 "Historical & Archaeological Investigation of Ruins of Nineteenth Century Sugar Hill (16MF-36) in West Feliciana Parish, LA " SHUMAN, M K Affiliation Not Assigned ORBER, C. E. Louisiana State Univ 84/02/10 56pp, 22485:153 24X Fiche, 50-458, 84/03/01, 8403050078
- 8403220209 Forwards Army Corps of Engineers 831127 ltr re Old River Control project, in response to NRC request Damage sustained by low sill structure in 1973 resolved W/four oversize brochures Aperture cards are available in PDR BOCKER, J E Quif States Utilities Co 84/03/19 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 15pp. 22718:193. 24X Fiche 50-458,84/03/19,84032202099

- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- ### A 03070062 Forwards supplemental responses to requests for add1 info & draft BER open items, identified by Mechanical Engineering Branch in B31229 itr Where indicated responses will be provided in future amend to FBAR BOCKER, JE Out States Utilities Co 84/02/21 DENTON, HR Office of Nuclear Reactor Regulation, Director 29pp 22548 014 24X Fiche 50-458,84/02/21,8403070062
- □ 403170017 Forwards response to NRC 840123 position re drywell/

 containment purps sys Discussions held on 840131 w/

 Containment Sys Branch clarified bases for position &

 detailed util responses for input to SER,

 DIDOKER, J E Gulf States Utilities Co 84/03/13 DENTON, H R

 Diffice of Nuclear Reactor Regulation, Director 6pp 22665 3

 24X Fiche 50-458,84/03/13.8403190017 6pp 22665 354.
- E. Security, medical, emergency & fire protection plans

- Adjudicatory correspondence
- B40314009 Forwards offsite emergency planning Contentions 1-12 WATKINS.L.B Watkins. L.B. 84/03/09 Atomic Safety and Licensing Board Panel. ip 22633 267 24X Fiche 50-458.84/03/09.8403140009
- B403270372 Answer opposing Joint Intervenors 840307 contentions re offsite emergency planning, No contention meets basis & specificity requirements of 100FR2, 714 W/svc list

 WEITERHAHN/M J Ouif States Utilities Co WEITERHAHN/M, J Conner & WeIterhahn DBB 173, 84/03/26 Atomic Safety and Licensing Board Penel 38pp 22814 342 24X Fiche 50-458/84/03/26,8403270392.
- 8403300025 Order establishing purpose of 840418 prehearing conference Berved on 840329.

 CDTTER.B P. Atomic Safety and Licensing Board Panel 84/03/28

 3pp. 22822.182. 24X Fiche 50-458.84/03/28.8403300025
- Imspection reports, IE Bulletins & correspondence
- ### 40 1 190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list - 5-1
 - CORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York: Inc 115pp. 22709:237 24X Fiche: 50-000, 84/02/28, 8401190072
- 340 ⊇090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Svc list encl.
 □RACE,J N. Division of GA. Befequards & Inspection Programs (Post 1300103). 84/03/02 Connabidated Edison Co of New York, Inc. 130pp. 22552:327. 24X Fiche: 50-000,84/03/02,8402090007
- PACE OF STATE OF STAT
- ♣92090009 IE Info Notice 84-15, "Reporting of Radiological Releases " OROGO009 IE Info Notate 6.7...
 UC 11st encl.
 UCRIAN.E.L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) 84/03/02 Consolidated Edison Co. of New
 York, Inc. 117pp. 22553;217 24X Fiche: 50-000;84/03/02;8402090009

- 8402070011 IE Info Notice 84-17, "Problems H/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Natice 84-09. Rev i. "Lessons Learned Fram Inaps of Fire Protection Safe Shutdown Sys " Syc list encl JORDAN, E. L. Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New 118pp 22435 047 24% Fiche 50-000, 84/03/07, 8402070024
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Sys " Bvc list enci JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/07 Consolidated Edison Co of New York, lnc 118pp 22584 186 24X Fiche 30-000,84/03/07,8402090028
- 8402090031 IE Bulietin 84-02, "Failures of QE Tupe MFA Relays in Use in Class 1E Safety Sys " Syc list encl
 DEYBUNG:R C Director's Office Office of Inspection and
 Enforcement B4/03/12 Consolidated Edison Co of New York, Inc
 134pp 22823,094 24X Fiche 50-000:84/03/12,8402090031
- 8402070043 IE Info Notice 84-i9. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Bvc list encl JURDAN. E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York. Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402070043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related 102090044 IE Info Notice on a...

 Bys "Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/21 Consolidated Edison Co of New
 York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- S Reportable occurrences, LERs & related correspondence
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval, Inc. Owners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Fower Stations
 MUSELER.W. J. TDI (Transamerica Delavai, Inc.) Owners Group 84/02/27 DENTON.H R. Office of Nuclear Reactor Regulation, Director 3pp 22434 090 24X Fiche 50-000.84/02/27.8403010207
- 840301021B Forwards task descriptions for 16 known problems re Transamerica Delavai. Inc emergency diesel generators MUSELER.W J TDI (Transamerica Delavai. Inc.) Gwners Group 84/02/2B DETON.H R Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Fichs 50-000.84/02/28.8403010218
- 8403140048 Forwards "Grand Quif Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delavai, Inc Diesel Generators Comers Croup Program Plan," to resolve concerns w/emergency diesel generators MUSELER, W J. Long Island Lighting Co. 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 22426 062 24X Fiche 50-000,84/03/02,8403140048
- --B403140075 "Transamerica Dejaval, Inc Diesel Generators Owners Group Program Pian "
 * TDI (Transamerica Delaval, Inc.) Owners Group 84/03.
 26ipp 22628:223 24X Fiche 50-000,84/03/02,8403140048
- 8402090037 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc. (TDI) Duners Group Distribution List enc!
 EIBENHUT,D G Division of Licensing 84/03/12 PALLADING
 Commissioners 5pp 22708 001 24X Fiche 50-000,84/03/12,8402090039.
- --8403040536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Owners Group in Bethesda.MD re problems w/emergency dissel generators
 CARUSO.R Licensing Brench 2 84/02/27 G'REILLY, J P NRC - No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche. 50-000, 84/03/12, 8402090039
- --8403060554 Transcript of 840210 meeting w/Transamerica Delayal.Inc Owners Group in Bethesda,MD re problems w/emergency diesel generators
 * NRC - No Detailed Affiliation Given 84/02/10 147pp.
 67201 008 24X Fiche 50-000,84/03/12,8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River, NY re program plan to establish reliability of diesei generators Agenda, meeting transcript & attendance list encl. ence 1187 enc1. IM A Licensing Branch 4. 84/02/27 Licensing Branch 4 22708 161 24X Fiche 50-000,84/03/12,8402090039

- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval,Inc dissel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000,84/03/12,8402090039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shalls for Transamerica Delaval Enterprisa Engines" for Shoreham & Grand Quif diesel genarators MUSELER, H J Long Island Lighting Co 84/03/12 DENTON, H R OUFFICE of Nuclear Reactor Regulation, Director 2pp 22432 074 24X Fiche 50-000, 84/03/12,8403140050
- B403i30l33 Forwards "Transamerica Dslaval, Inc Diesel Osnerator Rocker Arm Capscraw Stress Analysis Rept "Capscraw design adequate for applicable engines & svc conditions MUSELER, N J TDI (Transamerica Dalaval, Inc.) Owners Group B4/03/13 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 2pp 22637 270 24% Fiche 80-000.84/03/13,8403150133
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating angine number, model & svc number, customer name & address, rating, date shipped & date started enc!

 MATHEMS, C B Transamerica Dalaval, Inc 84/03/16 EIBENHUT, D 0
 Division of Licensing 20pp 22691 179 24% Fiche 50-000,84/03/16,8403200222
- 8403270i32 Forwards "Emergency Diesel Gensratur Air Start Valva Capscrew Dimension & Stress Analysis." prepared by S&W for Transamerica Delaval. Inc (TDI) Diesel Generator Dwnsrs Group MUSELER, W. J. TDI (Transamerica Dalaval. Inc.) Owners Group 84/03/23 DENTGR.H R. Office of Nuclear Reactor Regulation. Director 2pp 22774'001 24X Fiche 50-000.84/03/23,8403270i32
- 8403270i34 Requests meeting on 840418 to discuss short-tsrm & long-term corrective actions & investigations ra Transamsrica
 Dalaval dissel generators List of suggested meeting topics
 ancl
 MCOAUGHY. J P TDI (Transamarica Delaval, Inc.) Guners Group
 84/03/23 DENTON. H R Office of Nuclear Reactor Regulation.
 Director 4pp 22769 133 24X Fichs 30-000,84/03/23,8403270/334
- T Hearing transcripts on non-antitrust matters
- B402090039 Board Notification 84-052 forwards meeting summarlss containing transcripts of B40210 & 16 meetings between NRC & Transmerica Delaval. Inc (TDI) Dwnars Group Distribution list anci
 EISENHUT.D 0 Division of Licansing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fichs 50-000,84/03/12.
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators
 CARUSO.R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000, 84/03/12, 8402070037
- --B403060554 Transcript of 840210 meeting w/Transamsrica Dalaval, Inc Cwners Oroup in Bethssda, MD re problems w/amsrgsncy diasel generators * NRC - No Detalled Affiliation Givan B4/02/10 147pp 67201 008 24X Ficha 50-000,84/03/12,8402090039
- --B403070409 Summary of B40216 mesting w/Transamsrica Dalaval. Inc Owners Group in Wading River,NY re program plan to sstablish railability of dissel generators Agenda,mseting transcript & attendance list enci MILLER.H A Licansing Branch 4 84/02/27 Licansing Branch 4 8pp 22708 161 24X Fiche 50-000.84/03/12,8402090039
- --B403070423 Transcript of 840216 conference in Wading River,NY ra Transamerica Delaval, inc diessi generators Pp 1-82 * Commissioners 84/02/16 Bpp 22708 169 24X Fiche 50-000,84/03/12,8402090039
- DUCKET 30-460 WPPSB NUCLEAR PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- B403010050 Third partial response to FDIA request for six catagorlas of documents as facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in PDR upon request Review continuing FELTON, J M Division of Rules and Records B4/01/17. ANDERSON, S 1 Garvey, Schubert, Adams & Barer 4pp 22446 293 24% Fiche 50-000,84/01/17,8403010050

- --B30B100AB3 Discusses status of DL applications Review of ancl MPPSB 830712 ltr requested in order to determine present status of Unit 3 for billing purposes M/o encl MILLER, W O License Fee Managament Branch 83/08/05 FONNER R L Regulations Division 2pp 22446 326 24X Fiche 50-000, 84/01/47.840210040
- 8403080179 Fourth partial response to FOIA request for six catagories of documents re facilities Forwards App A documents App B documents strively withheld (ref FOIA Examption 3) Raviaw of addl documents subj to request continuing FELTON, J M Division of Rules and Racords 84/02/13 ANDERSON, 8 I Garvey, Schubert, Adams & Barar 7pp 22383 226 24x Fiche 50-000.84/02/13,8403080179
- --B001140316 Notifies that NRC has amended regulations re implementation of resident insp program Expresses gratitude for assistance randered Forwards final rule M/O encl BTELLO,V Office of Inspection & Enforcement, Office of the Director 79/11/19 O'STRAND.N Hashington Public Power Supply System lp 22583 234. 24X Fichs 50-000.84/02/13.8403080179
- --B009090737 Forwards alrworthiness alert re corrosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Quastions re ash amount, chemistry & size distribution will be forwarded to licensees W/o encl JACKBON, R E Geoscisnoes Branch B0/06/12 VOLLMER, R. H. Division of Engineering 2pp 22583 258 24X Fiche 50-000,84/02/i3,8403080179
- --8010090260 Discusses review of applicant 800814 request for approval of proposal to substitute in-plant tests w/scale model ratirculation sump tasts Response to requests deferred pending NRC review of program SPEIS.7 Reactor Systems Branch 80/09/24 YOUNGELOOD, B. J Licsnsing Branch 1 ip 22583 266 24X Ficha 50-000,84/02/13,8403080179
- --8104220329 Concludes that Tabla 3 2-2 of PSAR.ra safety-related structures.sys & components, is incomplate from Gaotachnical Engineering Branch viewpoint LEAR.O E Hydrologic & Gaotachnical Enginearing Branch. 81/04/08 HAASS.W P Guality Assurance Branch 2pp 22583 278 24% Ficha 50-000.84/02/13.8403080179
- ~-8104300020 Rasponds to BiO4i4 memo re util request for clarification in uss of AGME code cases Util use of code cases w/o prior NRC approval is inadvisable due to potentle! hardship for user BUSNAK,R J Machanical Engineering Branch 81/04/21, YUUNGBLOOD,B J Licensing Branch 1 lp 22583 280 24X Fiche 50-000,84/02/13,8403080179
- --Bi00010594 Adviss that Mechanical Engineering Branch completed ravisw of util request for authorization to use ABME Code Cases N-217 & N-287 for application in design of concrete containments Code cases acceptable RMIGHT. J P Assistant Director for Comp & Structures Engineering (Fre 800201) 81/04/29 TEDESCUR L Assistant Director for Licensing lp 22583 281. 24X Ficha. 50~000.84/02/13,8403080179
- --B105140106 Advises that info provided on 810213 & 0403 re air intake arrangements for diesel generators reviewed Diesel generator combustion air supply arrangement meets acceptance criteria in Section II of SRP a 5 B Sys acceptable as designed UNOARC, A R Power Systems Branch 81/05/01 YOUNGBLOOD, B J Licensing Branch 1 ip 22583-282 24X Ficha 50-000,84/02/13,8403080179
- --8105180436 Forwards ltr from util requesting concurrence by NRC to omit Subsections 2 5 1-2 5 3 of FBAR Review & comments requested by B10622 ADENSAM, E G Assistant Director for Licensing 81/05/12, JACKSON, R E Geoscientes Branch ip 22583 283 24X Fiche 50-000,84/02/13,8403080179
- --8105210109 Concurs w/licenses proposal to ref Sections 2 5 i-2 5 i-2 5 i-2 5 3 of WPPS-2 FSAR in WPPS-1/4 FSAR since both projects located in close proximity Mods listed JACKSON, R E Geosciences Branch 81/05/15 ADENSAM, E G. Licensing Branch 4 2pp 22583 286 24% Fiche. 50-000. 84/02/13, 8403080179
- --B107280171 Notification of 810729 meeting w/util & B&W in Bethesda,MD to discuss method util intends to use to fulfill requirments of NUREO-0737 Itam II F 2 (inadequata core cooling instrumentation)
 HERNAN,R W Licensing Branch 4 B1/07/21 ADENBAM,E 9
 Licansing Branch 4 2pp 22583 305 24X Fiche: 50-000,84/02/13,8403080179

- --810B11003B Notification of B10820 meeting w/util in Bethesda, MD to discuss proposed independent design review programs HERNAN, B W Licensing Branch 4 91/07/30 ADENBAM, E Q Licensing Branch 4 3pp. 22583 302 24X Fiche 50-000, 84/02/13, 8403080179
- --B110080612 Discusses proposal to use IDRs in licensing process IDRs may be useful in certain areas, but clarification of role needed, TEDEBCO.R L Assistant Director for Licensing 81/09/23 EIBENHUT.D O Division of Licensing 1p 22583 307 24X Fiche 50-000,84/02/13,8403080179
- --BillObO497 Notifies of util intention of sending technical team to present FSAR to review staff during wk of 811130 Reviewers should complete attached form & confirm attendance HERNAN, R W Licensing Branch 4 81/10/23 Licensing Branch 4 4pp 22583 311 24X Fiche 50-000.84/02/13.8403090179
- --Bilil30007 Submits names of D Gupa & G Stalley as technical reviewers for facility FBAR per 811023 memo LEAR, G Hydrologic & Geotechnical Engineering Branch Bi/10/30 ADENBAM, E. Litemsing Branch 4 1p 22583 315 24X Fichs. 30-000, 84/02/13, 8403080179
- --B111200219 Informs of receipt of telcon from Yakamar Indian Nation requesting that tribe be given full rights in facilities proceedings TEDESCO, R L Assistant Director for Licensing, 81/10/21 KETCHEN, E Hearings Division Ip 22583 310, 24X Fiche 50-000, 84/02/13, 8403080179
- --B112300305 Notification of B11211 meeting w/util in Bethesda, MD to discuss FBAR w/technical review staff at time OL application is tendered HERNAN, R W Licensing Branch 4 B1/11/23 ADENBAH, E 0 Licensing Branch 4 3pp 22583 318 24X Fiche 50-000, 84/02/13, 8403080179
- --8212070382 Ack receipt of 821109 itr re Target Rock environ qualification testing program Info re valve upgrade & retest anticipated HEISHMAN, R.F. Division of Reactor Programs (Pre 830103) 82/12/01. BOUCHEY, C. D. Washington Public Power Supply System ip 22583 337 24X Fiche 50~000.84/02/13.8403080179
- --B304060577 Requests search for documents re govt litigation w/util on five specific issues SLA00IE.E L Office of the General Counsel 83/03/23 DIRCKB.W.J Office of the Executive Director for Operations, ip 22583.361 24X Fiche 50-000.84/02/13.8403080179
- --8304070113 Recommends that radiation exposure records be retained for i yr prior to disposal Ref Murphy to Varga 801222 CONCEL.F.J. Radiological Assessment Branch 83/04/01 BCHWENCER.A. Licensing Branch 2 ip 22583 327 24X Fichs: 50-000, 84/02/13.8403080179
- 8403050288 Fifth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App A & B documents also available in PDR Documents listed on App C & D located in Central Files & not available publicity FELTON, J. M. Division of Rules and Records 84/02/17 ANDERSON, 8 I Garvey, Schubert, Adams & Barer 7pp 22501, 289 24X Fiche: 50-397, 84/02/17, 8403050288
- --7908010232 Responds to 790405 Region 5 comments re Revision 4 to NPP88-GA-OO4, "Operational GA Program Description " Expresses intent to request util to delete Section 3 3 6 entirely HAA88, W.P. Quality Assurance Branch 79/05/01, BRYAN, B E Division of Resctor Operations Inspections ip 22501, 305 24X Fichs 50-397, 84/02/17, 8403050288
- --8110170031 Responds to 810923 FOIA 81-378 request for GA documents for WPSS. All documents re evaluation of licenses GA programs are in PDR.
 HAAGS.W.P. Quality Assurance Branch. 81/10/05 WILSON, V. H
 Management Analysis Branch. 2pp 22501;310 24X
 Fiche: 30-397,84/02/17,8403050288
- --8110210316 Informs of receipt of Bouchey/Adensam 810722 Itr containing util current GA program description for design & const of facilities GA program description acceptable HAASB,W.P. Quality Assurance Branch 81/10/14 TEDESCO,R.L. Assistant Director for Licensing ip 22501 312 24X Fiche: 50-460, 84/02/17, 8403050288
- --8201300234 Forwards data for fee assessment re QA Branch review of HPPSS-QA-004, "Operational QA Program Description "HAASS,W P. Quelity Assurance Branch, 82/01/14 BERKOW.H N. Hanagement Analysis Branch, 2pp 22501 314 24X Fiche 50-397,64/02/17.8403050268

- 8403050219 Forwards listing of board notifications issued since 820716, per 840127 inquiry re failure to provide ASLB & parties w/notifications DENTON, H R Office of Nuclear Reactor Regulation, Director 84/02/28 BELL,N Coalition for Safe Power 25pp 22700 222 24 Fiche 50-460.84/02/28.8403050219
- 8403070014 Explains why two recent board notifications re environ qualification of equipment not received List of all board notifications issued since 820716 docketing of Unit 1 encl DENTON. HR Office of Nuclear Reactor Regulation. Director 84/02/28 BELL.N Coalition for Safe Power 25pp 22563 166 24) Fiche 50-460,84/02/28,8403070014
- C Utility Environmental Report (ER), amends & correspondence
- B4030B0179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I, Carvey, Schubert, Adams & Barer 7pp 22583.226 24X Fiche 50-000,84/02/13,8403080179
- --8202260171 Requests assistance in performing acceptance review of environ rept for OL application Only portions applicable to Unit 1 need be considered since Unit 4 cancelled on 820122 ADENSAM.E C Licensing Branch 4 82/02/10 JACKSON.R E Geosciences Branch 1p 22583 324 24X Fiche 50-000.84/02/13.8403080179
- ~~8203100570 Recommends environ rept be accepted Add1 questions reexternal appearance, plant layout & socioeconomics of single unit operation will be submitted REGAN, WH Siting Analysis Branch 82/02/25 ADENSAM, E Q Licensing Branch 4 ip 22583 328 24X Fiche 50-000, 84/02/13, 8403080179
- --8203150028 Forwards add] info requirements for review of ER for GL application per 820210 request
 BALLARD,R L Environmental Engineering Branch 82/03/02
 APENBAM,E Q Licensing Branch 4 3pp 22583 327 24X
 Ficher 50-000,84/02/13,8403080179
- --8203180004 Advises that environ rept is acceptable re radiological impacts
 HDUSTON,R W Assistant Director for Radiation Protection
 82/03/02 TEDESCO,R L Assistant Director for Licensing 1p
 22383 332 24X Fiche 50-000,84/02/i3.84030801/9
- --8204090099 Informs that sufficient info provided to begin meteorology review Inappropriate models & diffusion parameters used in Section 6 i 3 2 & accident evaluations HULMAN, L O Accident Evaluation Branch 82/03/16 ADENBAM, E Licensing Branch 4 2pp 22583 336 24% Fiche 50-000, 84/02/13, 8403080179
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON.8 I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --B003230477 Forwards hydrologic engineering quastions re proposed waste treatment sys Response will supply necessary info re design basis for seepage & flooding Also forwards generic quastions re floodplains Info will assist NRC environ review SELLS.D E Environmental Projects Branch 2 B0/03/07 RENBERGER,D L Washington Public Power Supply System 5pp 22583 253 24X Fiche 50-000,84/02/13,8403080179
- ---8003270142 Discusses suspension of facility preoperational aquatic monitoring program Buspension approved Operational manitoring program results should not be affected by suspension SAMHORTH, R.B. Environmental Specialists Branch 80/02/27 SELLB: D.E. Environmental Frojects Branch 2 2pp 22583 239 24X Fiche 50-000,84/02/13,8403080179
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities. Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J. M. Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24% Fiche 50-000,84/02/13,8403080179

- --8103040052 Forwards short & long-term OL & CP review schedules.in response to 801216 meeting w/USOS List of OL plant reviews for which NRC tentatively plens to seek USOS assistance is provided JACKBON.R E Geosciences Branch NRC-03-80-113 81/01/21 DEVINE.J F Interior, Dept of, Oeological Survey 3pp 22583 272 24X Fiche 50-000.84/02/13.8403080179
- --Biiii20935 Forwards form which identifies Power Bys Branch electrical & mechanical reviewers for project in eccordence w/Bii023 memo Requests established review schedule dates when available UNGARD. A Power Bystems Branch Bi/11/02 HERNAN.R W Licensing Branch 4 2pp 22383 316 24X Fiche 30-000.84/02/13.8403080179
- F Security, medical, emergency & fire protection plens
- 8403080177 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Examption 5) Review of addl documents subj to request continuing FELTON.J M Division of Rules end Records 84/02/13 ANDERSON.8 I Oarvey, Schubert, Adems & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13,8403080179
- --B201190297 Forwards Central Files version of "Description of Early Harning Sigs for HPPSS Nuclear Pients 1,2 & 4." in response to NRC 810720 ltr re-prompt notification in event of emergency Sigs will be in place prior to CL issuance BOUCHEY, G D. Heshington Public Power Supply System 82/01/11 TEDEBCO, R L. Assistent Director for Licensing ip 22583 321 24X Fiche 50-000,84/02/i3,8403080179
- -- B2021B0456 Requests that Fire Protection Section perform ecceptance level review of facilities' revised fire protection progrem prior to docketing of OL epplicetion Util aware that App R to 10CFR50 will apply ADENBAM.E O Licensing Brench 4 82/01/27 BENAROYA.V Chemica Engineering Branch ip 22583 322 24X Fiche. 50-000. B4/02/19. B4030B0179
- --8203020139 Advises that listed info meeded to perform acceptence review of fire protection program for conformance w/NURE0-0800.

 Bection 9 5-1

 BENARDYA, V Chemical Engineering Brench 82/02/09 ADENSAM, E G
 Licensing Branch 4 ip 22583 323 24X Fiche 50-000,84/02/13,8403080179
- --8205070088 Forwards list of sys to be edded to Q-list Bys provides ongoing knowledge of changes in radiction environ & ebility to deal effectively w/unusuelly high radiction by radioectivity levels
 CONCEL.F J Radiological Assessment Branch 82/03/23, HAASS.W P Guality Assurance Branch 2pp 22583 338 24X
 Fiche 50-000.64/02/13.8403080179
- ~-8208120240 Forwards Central Files version of ravised pege to Revision 2 of emergency plan adding local fire depts within 20 miles of facility to backup fire protection sycs
 SOUCHEY.O D Hashington Public Power Supply Bystem 82/08/05
 SCHMENCER.A Licensing Branch 2 2pp 22583 348 24X
 Fiche 50-000,84/02/13,8403080179
- --820B12024B Central Files version of revised page to Revision 2 of emergency plen re provision of backup fire protection evcs * Mashington Public Power Supply System 82/08/05 1p 22B3 350 24X Fiche 50-000,84/02/13,8403080179
- B403050288 Fifth partial response to FDIA request for six categories of documents are facilities Forwerds App A documents App A & B documents also evaileble in PDR Documents listed on App C & D located in Central Files & not evailable publicly FELTON.J, M Division of Rules end Records 84/02/17 ANDERSON.S, I Garvey, Schubert, Adams & Baner 9pp 22501 289 24X Fiche:50-508,84/02/17.8403050288
 - on progrem description & related
 h 79/05/10 PARRIO D. Light
 1 309 24X

x categories A laced ANDERSON, S. I '4X

- --8304050552 Requests search for relevant documents re govt litigation w/util Response due by 83040B
 GRIMBLEY.D H NRC No Detailed Affiliation Given 83/03/29
 FITTI.C Atomic Sefety and Litensing Board Panel 1P. 22446-314
 24% Fiche 50-000.84/01/17.8403010050
- 8403220049 Appeal of ASLB 840202 order granting applicant & staff motions for summany disposition on Coalition for Safe Power Contention 2 Certificate of Bvc encl BELL:N Coelition for Safe Power DSB 025 84/03/19 Atomic Befety and Licensing Appeal Panel. 15pp 22712.202 24X Fiche 50-460.84/03/19,8403220049
- J Insurance & indemnity information
- 8403060377 Forwards Endorsement B to MAELU Policy MF-110 & Endorsements 13 & 14 to NELIA Policy NF-270 ABHBURN, D J Marsh & McLennan, Inc. 84/02/28 SALTIMAN, J. Assistant Director for State & Licensee Relations, 4pp. 22511-323 24X Fichs 50-397.84/02/28.8403060377
- O Inspection reports, IE Bulletins & correspondence
- B403080179 Fourth partial response to FOIA request for six categories of documents re fecilities Forwards App A documents.App B document entirely withheld (ref FOIA Exemption 5) Review of addi documents subj to request continuing FELTON, J H Division of Rules end Records 84/02/13 ANDERSON, S, I Gervey, Schubert, Adams & Darer 7pp 22583:226 24X Fiche 50-000.84/02/13,8403080179
- ---8207280i65 Forwards Cycle 3 systematic appraisal of licensee performance input for Bi0701 through 820730 in response to Region 5 820425 request Strong mgt evident, Resolution of technical issues, responsiveness & steffing satisfactory HERNAN, R W Licensing Branch 4 82/09/15 EISEN-UT, D. O. Division of Licensing App 22583, 351 24X Fiche 50-000, 84/02/19, 8403080179
- 8 Reportable occurrences. LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Trensamerica Delaval, Inc DIRCKS.W J Office of the Executive Director for Operations. SECY-83-034 84/01/25 4pp 22438 347 24X Fiche: 50-000.84/01/25.8403010451
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents.App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing, FELTON, J M Division of Rules end Records 84/02/13 ANDERBON, B I Garvey, Schubert, Adams & Barer 7pp. 22583.226, 24X Fiche: 50-000,84/02/13.8403080179
- --B203i004i9 Discusses Part 21 rept re UE&C design of structural steel at fecility Generic implications eppear to be nonexistent since no similar design concept used et other facilities. Two oversize drewings encl Aperture cards in Central Files BHEWHAKER.R E Division of Engineering & Quality Assurance (Pre B30103) B2/02/24 DROMERICK.A W Division of Engineering & Quelity Assurance (Pre B30103) 2pp 22583 325, 24X Fiche 50-000,84/02/13,8403080179
- 8403210032 Part 21 rept re failure of auxiliary feadwater pump drive turbines.0imps1 NPS-4 T&T valve.to close Enci 1tr ded 840203 sent to listed utils GE notified of affected units in BHR plants
 THEROUX.R R Terry Corp 84/02/22. HOODRUFF.R W. Director's Office. Office of Inspection and Enforcement 6pp. 22706.327. 24X Fiche 50-000.84/02/22.8403210032
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transemerica Delevel, Inc Owners Group program commitments. Rept evaluates cracks in AF piston skirts in Bhoreham & Grand Gulf Nuclear Power Stations

 MUSELER.W J TDI (Transamerica Delaval, Inc.) Owners Group.

 84/02/27 DENTON.H.R Office of Nuclear Reactor Regulation,
 Director 3pp 22434 090 24X Fichs 50-000,84/02/27,8403010207.
- 8403010218 Forwerds task descriptions for 16 known problems re Transamerica Delaval, Inc. emergency diesel generators, MUSELER, W. J. TDI (Transamerica Delaval, Inc.) Owners Group, 84/02/28 DENTON, H.R. Office of Nucleer Reactor Regulation, Director 42pp 22435 177, 24X Fiche. 50-000, 84/02/28, 8403010218.

- 8403140048 Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval, Inc Diesel Generators Owners Group Program Plan: " to resolve concerns W/smergency diesel generators MUSELER, W J. Long Island Lighting Co. 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22626 062 24X Fiche 50-000,84/03/02,8403140048
- --8403140095 "Transamerica Delaval.inc Diesel Generators Dumers Group Program Plan "

 * TDI (Transamerica Delaval. Inc.) Owners Group 84/03/02 261pp 22628 223 24X Fichs 50-000.64/03/02.8403140048
- 8402070039 Board Notification 84-052 forwards meeting summaries containing transcripte of 840210 & 16 meetings between NRC & Transemerica Delaval Inc (TD) Guners Group Dietribution list encl EIBENHUT, D O Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fiche 50-000.84/03/12.
- --8403060536 Forwards eummary of 840210 meeting w/Transamerica Delaval, inc Owners Group in Bethesda, MD re probleme w/Emergency diesel generatore CARUBO, R Licensing Branch & 84/02/27 O'REILLY, J. P NRC No Detailed Affiliation Given 6p, 22708 006 24X Fiche 50-000,84/03/12,8402090039
- --8403060554 Transcript of 840210 meeting w/Transamerica Delavel, Inc Owners Group in Bethesda, MP re problems w/emergency dissel generators * NRC - No Detailed Affiliation Given 84/02/10. i47pp 67201 008 24X Fiche 50-000.84/03/12.8402090039.
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval.Inc Owners Oroup in Wading River.NY rs program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl MILLER.M.A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161. 24X Fichs. 50-000.84/03/12,8402090039
- ---8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval. Inc dissel generators Pp i-82 # Commistioners 84/02/16, 84pp 22708 169 24X Fiche: 50-000, 84/03/12, 8402070039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Opand Gulf diesel generators MUSELER, W J Long Island Lighting Co 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22632 074 24X Fiche 50-000,84/03/12,8403140050
- 8403150133 Forwards "Transamerica Delaval Inc Diesel Generator Rocker Arm Capstrew Stress Analysis Rept " Capetrew design adequate for applicable enginee & svc conditions MUSELER, W J TDI (Transamerica Delavai, Inc.) Owners Group 84/03/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22639-270 24X Fiche 50-000,84/03/13,8403150133
- 8403200222 Responds to 840214 Requests for Info 1 & 2 rs R-4 series engines Liet indicating engine number model & svc number, customer name & address, rating, date shipped & date started encl
 MATHEMS, C S Transamerica Deiaval, Inc 84/03/16 E19ENHUT, D. Q
 Division of Licensing 20pp 22691-179 24X Fiche 50-000, 84/03/16, 8403200222,
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV. 500-750 MVA.5 kV 350-3,000 & ail HKV circuit breakers. Initially reported on 890223 Addenda to installation & maint procedures eent to affected units DUVALL,D D Brown Boveri Corp (subs of Brown Boveri & Co., Ltd) 84/03/19. Record Services Branch (Document Control Desk). 5pp 22772:114 24X Fiche 50-000,84/03/19,8403270219
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by 8kW for Transamerica Delaval, Inc (TDI) Diesel Generator Owners Group MUSELER, W J TDI (Transamerica Delaval, Inc) Owners Group 84/03/23 DENTON, H R. Office of Nuclear Reactor Regulation, Director, 2pp 22774-001, 24X Fiche: 50-000, 84/03/23, 8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delaval diesel generators List of suggested meeting topics encl MCGAUGHY, J.P. TDI (Transamerica Delaval, Inc.) Dumers Group 84/03/23, DENTON, H.R. Office of Nuclear Reactor Regulation, Director 4pp 22769:133 24% Fichs 50-000, 84/03/23, 8403270134

T Hearing transcripts on non-antitrust matters

- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval. Inc (TDI) Duners Group Distribution list Brc1 EISENHUT.D G Division of Licensing 84/03/12 PALLADING Cummissioners 5pp 22708 001 24X Fiche 50-000,84/03/12,8402090039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Owners Group in Bethesda.MD re problems w/emergency
 diesel generators
 CARUSOR Licensing Branch 2 84/02/27 O'REILLY.J P NRC No
 Detailed Affiliation Given 6pp 22708 006 24x
 Fiche 50-000.84/03/12.8402090039
- --8403060554 Transcript of 840210 meeting of Transamerica Delaval. Inc Owners Group in Bethesda MD re-problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fiche 50-000,84/03/12,8402090039
- --8403070407 Summary of 840216 meeting w/Transamerica Deleval, Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl
 MILLER, M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fishe 50-000.84/03/12.8402090037
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc diesel gonerators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000, 84/03/12, 8402070039

U Congressional/Executive Correspondence

- 84030B0179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addi documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S J Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --B009110203 Responds to B00702 ltr re E Borbek concern about ultimate responsibility for civil penalities proposed against util Civil penalities are imposed as enforcement action State agencies should be contacted re responsibility for payment DIRCKS.W J Office of the Executive Director for Operations B0/09/26 JACKGON.H M Senate 4pp 22583 260 24X Fich# 50-000.84/02/13.8403080179
- --B012160551 Forwards 800625 ltr from constituent E Borhek for response Requests that duplicate rept be forwarded to 802 United States Courthquee, Beattle, WA 96104 JACKEON.H M Senate, Energy & Natural Resources 80/07/21 KAMMERER.C C Office of Congressional Affairs 2pp 22583·264 24X Fiche 50-000, 84/02/13.8403080179

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8403130193 Responds to Generic Ltr 83-28 re generic implication of Salem ATMS events Util using methodologies developed by industry groups Behedule for info submittal will be provided within 45 days after receipt of owners group repts HERBORN,D I Illinois Power Co 84/03/02 EISENHUT,D 0 Division of Licensing 2pp 22617 298 24X Fiche 50-461,84/03/02,8403130193
- 8403290346 Notification of 840405 meeting w/util in Dethesda. MD to discuss tafety parameter display eys
 HARRISON C Liceneing Branch 2 84/03/08 SCHWENCER, A Licensing Branch 2 3pp 22822 253 24% Fiche 50-461,84/03/08.8403270346
- 8403190398 Forwards tabulated results re review of operating shift experience for facility HALL, D F litinois Power Co 84/03/09. DENTON: H R. Office of Nuclear Reactor Regulation. Director 6pp 22675 058 24X Fiche 50-461.84/03/09.8403190398.
- B403150089 Forwards responses to Mechanical Engineering Branch Questions 210 05 % 210.06 re HVAC duct work Strees limits for duct work & duct supports will be included in FBAR Buckled portions of ducts will be replaced HERBORN, D I Illinois Power Co 84/03/12 8CHWENCER, A. Licensing Branch 2 5pp 22642 358 24X Fiche 50-461,84/03/12,8403150089

- B402090041 Board Notification B4-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D 0 Division of Licensing B4/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000.84/03/14.8402090041
- B403200190 Ack receipt of B40307 request for concurrence in modifying program for pulling Class IE cable Installation of cable will not preclude insp of cable tray hangers Concurrence granted KEPPLER, J © Region 3, Office of Director B4/03/16 QERSTNER, W C Illinois Power Co ip 22686 341 24X Fiche 50-461, 84/03/16, B403200190
- --8403200193 Submits proposed mods to prerequisites for pulling Class IE cable previously modified in 840103 ltr Prior to Class IE cable pull, cable tray in pull path will be field inspected & accepted by Baldwin Assocs Quality & Technical Svcs HALL, D P Illinois Power Co 84/03/07 KEPPLER, J O Region 3, Office of Director 5pp 22686 342 24X Fichs 50-461, 84/03/16, 8403200190
- F Security, medical, emergency & fire protection plane
- B402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenbut re fire research results concerning fires in electrical cabinets in control roum EISENHUT. D 9 Division of Licensing 84/02/23 PALLADINU Commissioners 1p 22376 203 24% Fichs 50-000,84/02/23, 8800000006
- ~-8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NRR Ofc Ltr 19, dtd 821001 Further evaluation of test data required VOLLMER,R H Division of Engineering 84/02/06 EISENHUT,D G Division of ticensing 10pp 22376 204 24X Fichs 50-000,84/02/23,8402070006
- 8403120077 Notifies of 840323 workshop on fire protection safe shutdown revirements of 100FR50.App R in Rosemont IL to discuse IE Info Notice 84-09 & provide add! shutdown analyses &/or mod guidance Agenda enci SPESSARD, R L Division of Emergency Preparedness & Operational Support 84/03/06 GRSTNER, W C Illinois Power Co Spp 22586 302 24X Fiche 50-461.84/03/06.8403120077
- B403300287 Notification of B40403 meeting w/util in Betheeda.MD to discuss emergency planning HARRISON.G Licensing Branch 2 B4/03/08 BCHWENCER.A Licensing Branch 2 3pp 22844 326 24X Fiche 50-461.84/03/08.8403300289
- 8403270177 Forwards IE Mgt Meeting Rept 50-461/B4-06 on 840228-29 PAPERIELLO.C J Region 3. Office of Director 84/03/09 GERBINER.C J Illinois Power Co 2pp 22771 126 24X Fiche 50-461.84/03/09.8403270177
- --B403270180 IE Mgt Meeting Rept 50-461/84-06 on 840228-27 Major areas discussed progress of emergency preparedness program & hearing board contentions re emergency preparedness SNELL, W C. PHILLIPS. M P. Region 3, Office of Director 84/03/08 3pp 22771 128 24X Fiche 50-461.84/03/07.8403270177

G Adjudicatory correspondence

- B4D3O70120 Notice of filing of joint stipulation in OL hearing FOX.C D | Illinois Power Co | FOX.C D | Schiff, Hardin & Haite B4/O3/O2 | CLARK.H K | FEROUSON.G A | PARIS.O H. Atomic Bafety and Licensing Board Panel | 2pp | 22547 262 | 24X Fiche 50-461.84/03/02: B4O3O70120
- --8403070123 Joint stipulation that Paragraphs f,g,h,i & J of Contention III hereby withdrawn in entirety Certificate of Svc encl. ODDDARD.R NRC No Detailed Affiliation Given FOY.J M Prairie Alisance IAREL, SA Illinois Power Co 84/03/01, 3pp 22547 244 24X Fiche 50-461.84/03/02,8403070120
- 8403140057 Forwards proposed mod of Contention 1 re emergency planning discussed w/applicant, Prairie Alliance, FEMA & NRC at 840228-29 meetings in Champaign, IL Schedule to Further settle remaining emergency planning issues listed CODDARD, R J Hearing Branch 3 84/03/05 CLARK, H K, PARIS, O H, FERROUSBON, Q A Atomic Safety and Liceneing Board Panel App 22633 085 24X Fiche 50-461,84/03/05,8403140057.
- --8403140060 Requests notice of dates of licensing hearings in Clinton, IL. in order to make necessary arrangements
 STITES, S J Clinton, IL 84/02/24 CODDARD, R J Hearing Branch
 3 1p 22633 072 24X Fiche 50-461.84/03/05.8403140057

- B403140i35 Forwards util submittal providing functional description of safety perameter display sys W/o encl. OUDDARD.R J Hearing Branch 3 84/03/05 WILLMAN.P L Illinois, State of ip 22620 297 24X Fiche 50-461.84/03/05.8403140i35
- 8403140106 Forwards emergency planning contentions as modified at recent meeting w/intervenor & transmittal ltr to ASLB GDDDARD.R J Hearing Branch 3 84/03/06 PERRY.S Federal Emergency Managament Agency 9pp 22620 275, 24X Fiche 50-461.84/03/06.8403140106
- B403140142 Forwards modified emergency planning contention as amended on 840227 by party agreement QUDDARD,R J Hearing Branch 3 84/03/07 FGY,J Prairie Alliance 5pp 22624 035 24% Fiche 30-461.84/03/07,8403140142.

I Financial information

- 8403290093 Forwards util Annual Financial Rept 1983, Soyland Power Cooperative, Inc Annual Financial Rept 1982 & Western III incis Fower Cooperative, Inc Annual Financial Rept 1983. HERBORN DI Illinois Fower Co. 84/03/23 DENTON.H.R. Office of Nuclear Reactor Regulation, Director 1p 22806 106 24% Fichs 50-461,84/03/23,8403270093
- --8403290098 Annual Financial Rept 1983 KELLEY.W J Illinois Power Co 83/12/31 38pp 22806·127 24X Fichs 30-441.84/03/23.8403290093
- --8403270102 Annual Financial Rept 1982 FERGUSON,C E , WILLIAMS,E H Soyland Power Cooperative, Inc 82/12/31 22pp 22806 107 24% Fiche 50-461,84/03/23,8403290093
- ---8403290107 Annual Financial Rept 1983 QANT.R E Western Illinois Power Cooperative, Inc. 83/12/31 16pp 22806 167 24X Fiche 50-461,84/03/23,8403290093
- G Inspection reports, IE Bulletins & correspondence
- 8403130416 Forwards IE Insp Rept 50-461/83-19 on B31101-840111 & notice of violation KNDP,R. C Region 3, Office of Director. 84/02/21 GERBINER,W C Illinois Power Co 2pp 22613.091. 24x Fichs 50-461,84/02/21. 8400130416
- --8403130421 Notice of violation from insp on 831101-840111 * Region 3. Office of Director 84/02/21. 2pp 22613.093. 24X Fichs 50-461,84/02/21,8403130416
- --B403130430 IE Insp Rept 50-461/83-19 on B31101-840111 Violations noted deviation repts not dispositioned per Baldwin Assoc Rev 2 to Procedure BAP 1 0 i & acceptance criteria not setablished for dispositioning nonconformance repts JABLONBKI,F J., HAVEB.D W Region 3, Office of Director 84/02/21 32pp 22613 095 24X Fiche 50-461,84/02/21,8403130416
- 8403080174 Forwards IE Inep Rept 50-441/84-02 on 840118-20 & 24-27. No noncompliance identified STREETER. J F Region 3, Defice of Director 84/02/23 GERSTNER. M C 111inois Power Co. 2pp 22559 314 24X Fiche 50-441.84/02/23
- --8403080188 IE Inep Rept 50-461/84-02 on 840118-20 & 24-27. No noncompliance or deviations identified Major areas inspected review of previous noncompliance, unresolved & open items in IE Inep Repts 50-461/82-18 & 50-461/83-15. GA & GC. CHOULES.N C , SCHULZ.R D , HUNTER, D R. Region 3, Office of Director 84/02/17 lipp 22559-316 24X Fiche 50-461,84/02/23,8403080176
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Bvc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc 115pp 22909 239 24X Fiche-50-000,84/02/28,8401190072.
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Reve by DDT & NRC " Svc list encl. GRACE, J N Division of QA, Safeguarde & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co. of New York, Inc. 130pp, 22552 327 24X Fichs, 50-000, 84/03/02, 8402090007.
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Vaives to Operate," Svc list encl.
 JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc 122pp 22553 098, 24X Fiche 50-000.84/03/02,8402090008.

- 8402070009 IE Info Notice 84-15, "Reporting of Radiological Releases"

 See list and
 - Svc list enci
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/03/02 Consolidated Edition Co of New
 York, Inc 119pp 22553 217 24X Fich= 50-000.84/03/02.8402070009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Companents Below Nil Ductility Temp " Svc list encl JDRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York Inc 117pp 22533-336 24X Ficha 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown 84s" 8vc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- B40209002B IE Info Natice 84-18, "Stress Corrosion Cracking in PWR Sye." Svc list encl
 JCRDAN,E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co. of New
 York, Inc. 118pp 22584 186 24X Fiche 50-000.84/03/07,8402090028
- E403270177 Forwards IE Mgt Meeting Rept 50-461/84-06 on 840228-29 PAPERIELLO.C J. Region 3. Office of Director 84/03/09. GERSTNER, C J. Illinois Power Co 2pp 22771.126 24X Fiche: 30-461.84/03/09,8403270177.
- --B403270180 IE Mgt Heeting Rept 50-461/84-06 on 840228-29. Major areas discussed progress of emergency preparedness progrem & hearing board contentions re emergency preparedness BNELL, W G . PHILLIPS, M P. Region 3, Office of Director. B4/03/08. 3pp 22771-128 24X Fiche 50-461, B4/03/09, 8403270177.
- 8402090031 IE Bullatin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Byc list encl DEYONOR C. Director's Office, Office of Inspection and Enforcement. 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823.094 24X Fiche 50-000.84/03/12.8402090031
- 8403190170 Ack receipt of 840305 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-441/83-23 BPESSARD R L Division of Emergency Preparedness & Operational Support. 84/03/14 GERSTMER.W C Illinois Power Co 1p 22671.152 24% Fiche.50-461.84/03/14.8403190170.
- --8403170175 Responds to NRC 840117 ltr re violations noted in IE Insp. Rept 50-461/83-29 Corrective actions Procedure BAP 3.3, 2 revised to incorporate directive requirements for seismic Category I cable tray cable installation HALL, D.P. Illinois Power Co. 84/03/05 KEPPLER, J.O. Region 3, Office of Director 5pp 22671.153 24X Ficha: 50-461, 84/03/14, 8403190170
- 8403190329 Forwards Vendor Program Insp Repts 99700231/83-01 k 99900231/84-01 on B31115-17 & 840116-20, respectively, closing out Part 21 rept re seepage of p11 from Dkonite cables. POTAFOVS, U Region 4, Office of Director 84/03/15, NORELIUB, C E Division of Project & Resident Programs 1p 22675 026 24X Fichs: 50-461, 84/03/15, 8403190329.
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities." Syc list enti JURDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp. 22829 229, 24X Fiche: 50-000; 84/03/21; 8402090043.
- 8402090044 IE Info Notice 84-20, "Byo Life of Relays in Safety-Related Bye." Byo list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21. Consolidated Edison Co. of New York, Inc. 135pp. 22933 001. 24X Fiche 30-000.84/03/21,8402090044
- R. Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preperadness for DL reviews for Jan 1984, Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS,W J. Office of the Executive Director for Operations.
 84/02/21. PALLADINO Commissioners, 9pp 22492,083, 24X Fiche: 30-000, 84/02/21, 8403020443.

- 8 Reportable occurrences, LERs & related correspondence
- 8403080240 Part 21 rept re failure of Pacific Air Products linear converter Initially reported on 840117 Failure due to excessive wear of brass shaft guides on input & output shafts Investigation underway HALL. D P Illinois Power Co 84/02/29 KEPPLER. J Q Region 3, Office of Director 2pp 22536 289 24% Fiche 50-461,84/02/29,8403080240
- 8403260255 Interim Deficiency Rept 55-83-06 re weld defects on structural steel members supplied by Rockwell Engineering. Initially reported on 830427 Repairs initiated & vendors notified of 0A responsibility HALL-D.P Illinois Power Co 84/03/15 KEPPLER. J O Region 3, Office of Director 4pp 22754 313 24X Fiche 50-461.84/03/15, 8403260255

V Operator Examinations

8403190398 Forwards tabulated results to review of operating shift experience for facility HALL-D P lilinois Power Co 84/03/09 DENTON, H, R Office of Nuclear Reactor Regulation, Director Opp 22675:038 24X Fiche 50-461,84/03/09,8403190398

DOCKET 30-462 CLINTON POWER STATION. UNIT 2

F Security, medical, emergency & fire protection plans

B403120077 Notifies of B40323 workshop on fire protection safe shutdown revirements of 10CFR50/App R in Rossmont, IL to discuss IE Info Notice 84-09 & provide addl shutdown analyses &/or mod guidance Agenda and SPESBARD, R L Division of Emergency Preparedness & Operational Support. B4/03/06 OER8TNER, W C Illinois Power Co 3pp. 22586 302 24X Fiche 50-461,84/03/06/8403120077

- G. Inspection reports, IE Bulletins & correspondence
- 8403190329 Forwards Vendor Program Insp Repts 97900231/83-01 & 99900231/84-01 on 831115-17 & 840116-20, respectively, closing out Part 21 rept re seepage of oil from Okonite cables.

 POTAPOVS, U Region 4, Office of Director 84/03/15, NORELIUS, C E Division of Project & Resident Programs ip 22675 026. R4X Fiche: 50-461.84/03/15, 8403190329.
- 8 Reportable occurrences, LERs & related correspondence
- 8403i40122 Part 2: rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry
 DDDSON, J P Pacific Air Products Co 84/03/09 Director's Office of Inspection and Enforcement 7pp, 22624 068 24X Fiche, 50-000, 84/03/09, 8403140122
- DOCKET 50-463 FULTON GENERATING STATION, UNIT 1
- Q Adjudicatory correspondence
- 8403010221 Forwards brief on issues re liability for feat & expenses. Related correspondence IRWIN.D P Hunton & Williams IRWIN.D P Philadelphia Ejectric Co 84/02/27 COTTER.B P, LINENBERGER.G., DEBYLVA.D.P. Atomic Bafety and Licensing Board Panel. ip 22435'132 24X Fiche: 50-463.84/02/27.8403010228
- --8403010229 Brief on issues re liability for feet & expenses Certificate of 8vc entl.Related correspondence IRWIN, D.F. Hunton & Williams. 84/02/27 Atomic Safety and Licensing Buard Panel 41pp. 22435 133. 24% Fiche 50-463,84/02/27,8403010221
- T. Hearing transcripts on non-antitrust matters
- 8403050071 Transcript of 840229 hearing in Philadelphia, PA. Pp 1-83 # Atomic Bafety and Licensing Board Panel 84/02/29 83pp 22490 284 24X Fiche 50-463,84/02/29,8403050071

DOCKET 50-464 FULTON GENERATING STATION, UNIT 2

O Adjudicatory correspondence

8403010221 Forwards brief on issues re liability for fees & expenses Related correspondence IRNIN, D P Hunton & Williams IRNIN, D P Philadelphia Electric Co B4/02/27 COTTER, B P , LINENBERGER, O , DESYLVA, D P Atomic Safety and Licensing Board Panel ip 22435 132 24X Fiche 50-463,84/02/27.8403010221

--8403010229 Brief on Issues re liability for fees & expenses Certificate of Svc encl Related correspondence IRWIN.D P Philadelphila Electric Co IRWIN.D P Hunton & Williams 84/02/27 Atomic Safety and Licensing Board Panel 4ipp 22435 133 24X Fiche 50-463,84/02/27,8403010221

T Hearing transcripts on non-antitrust matters

8403050071 Transcript of 840229 hearing in Philadelphia, PA Pp 1-83 * Atomic Safety and Licensing Board Panel 84/02/29 83pp 22490 284 24X Fiche 50-463,84/02/29,8403050071

DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FDIA Exemption 3) Review of add1 documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON.8 I Garvey, Schubert. Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13.8403080179

--8102200029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications, per Dfc of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by 810601 EISENBUT.D Q Division of Licensing B0/12/31 VOLLMER, R Division of Engineering 1p 22583 277 24X Fiche 50-000,84/02/13,8403080179

DUCKET 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2

Application/construction stage documents & correspondence

9403080179 Fourth partial response to FOIA request for six categories of documents re facilitles Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, B 1 Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000, 84/02/13, 8403080179

--Bi02200029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications per Oft of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by Bi0401 EISENHUT.D Q Division of Licensing 80/12/31 VOLLMER.R Division of Engineering 1p 22583 277 24X Fiche 50-000,84/02/13.8403080179

DOCKET STN-50-470 CESSAR SYSTEM BO

NRC Safety Evaluation Report (SER), suppls & correspondence

3403010276 Forwards interface requirements re block valves on atmospheric dump valves to close out Confirmatory Item 2 of SSER 2 re steam generator tube rupture analysis SCHERER.A E Combustion Engineering, Inc 84/02/24 EISENHUT, D 0 Division of Licensing 3pp 22435 173 24X Fiche 50-470,84/02/24,8403010276

3403270107 Forwards interface requirement re shutdown cooling analysis of reactor coolant gas vent sys per BSER 2 Confirmatory item closed SCHERER: A E Combustion Engineering, Inc 84/03/22 EIBENHUT, D 0 Division of Licensing 2pp 22766 347 24X Fichs 50-470, 84/03/22, 8403270107

K Utility Final Safety Analysis Report (FSAR) & amends

84032000Bi Forwards for review, Amend 9 to C-E atd SAR Major changes result from response to confirmatory items & NRC questions SCHERER. A E Combustion Engineering. Inc. 84/03/16 EISENHUT.D C Division of Licensing 2pp 22682 001 24X Fiche 50-470,84/03/16. BA03200Bi

--8403200885 Amend 9 to C-E std 8AR WEBT.J M Combustion Engineering: Inc 84/02/27 524pp 22682 003 24X Fiche 50-470,84/03/16:8403200081

DOCKET 50-471 PILORIM NUCLEAR POWER BIATION, UNIT 2

A Application/construction stage documents & correspondence

840308D179 Fourth pertial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, 8 I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13.8403080179

~~8102200029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications.per Ofc of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by \$010601 EISENHUT, D O Division of Licensing 80/12/31 VOLLMER, R Division of Engineering ip 22583 277 24X Fiche 50-000,84/02/13,8403080179

B Reportable occurrences, LERs & related correspondence

8403260233 Forwards summary list of deficiencies identified per 10CFR90 55(e),Part 21 & potential generic ltr repts for comments 8TARGBTECKI.R Division of Project & Resident Programs 84/02/28. Region 1. Office of Director 7pp 22756 065 24X Fiche 50-000.84/02/28.8403260233

DDCKET STN-50-48R WOLF CREEK GENERATING STATION

A Application/construction stage documents & correspondence

8402090302 Notlflas that Rev 2 to "Rept of Independent Review of Environ Qualification Programs to NUREO-0588" not complete reissus.per 840201 itr Several rept apps had no changes PETRICK.N A Standardized Nuclear Unit Power Plant Bystem 84/02/07 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 22160 174 24X Fiche 50-000.84/02/07.8402090302

8402090017 Board Notification 84-038 forwards RJ Mattson 840123 mamo to D9 Eisenhut providing status update of NRC actions re Hestinghouse ECCS actuation logic EISENHUT.D G Division of Licensing 84/02/27 PALLADIND Commissioners 7pp 22546 007 24X Fiche 50-000.84/02/27, 8402070017

8403010406 Forwards listed addl info re slave relay testing Tech Spec requirements for ESF actuation sys.per 840217 request Meeting w/instrumentation & Control Sys Branch requested during wk of 840227 PETRICK,N A Standardized Nuclear Unit Power Plant System 84/02/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 82pp 22433 297 24X Fiche.50-000,84/02/27,8403010406.

8403020274 Forwards response to Generic Ltr 83-28 re required actions based on generic implications of Balem ATMS events. Withree oversize drawings Aperture cands are available in PDR KOESTER, G L. Kansas Cas & Electric Co. 84/02/29 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 48pp. 22482 042 24X Fiche 30-482,84/02/29,8403020274

B403120315 Forwards comments & request for add1 info to complete review of facility procedures generation package. Info requested within 30 days of itr receipt YDUNOBLOOD, B J. Licensing Branch i 84/02/29, KOESTER, P. L. Kansas Gas & Electric Co 7pp 22619 001 24X Fiche. 50~482, 84/02/29, 8403120315

8403120363 Forwards request for add1 info to complete evaluation of Instrumentation & Control Bys Branch site audit Info should be submitted by 840420 YOUNGBLOOD.B J Licensing Branch 1 84/02/29 KOESTER.G.L Kansas Gas & Electric Co GCHNELL.D F Union Electric Co 4pp 22615 354 24X Fichs 50-000.84/02/29,8403120363.

- B403140283 Ack receipt of util B40202 request to withhold proprietary varsion of "SNUPPS Steam Generator Tube Plugging Margin Evaluation" from public disclosure Based on listed reasons, submitted info will be withheld (ref iOCFR2 790) YOUNDBLOOD, B Licensing Branch 1 84/03/01 WIESEMANN, R A Westinghouse Electric Corp 4pp 22636.323 24x Fiche 50-000,84/03/01,8403140283
- 8403060278 Forwards equipment qualification data package for HE-1 to support justifications for interim operation Odd-numbered pages mistakenly not copied EGDP-HE-1 substitutes info in previous package PETRICK.N A Standardized Nuclear Unit Power Plant System 84/03/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22518 097. 24X Fiche 50-000,84/03/05,8403060278
- 8403130342 Forwards justification for interim operation (JIO) for listed programs & draft Hestinghouse Class 3 topical repte Final resolution of lesues for listed JIOs expected by 830331 PETRICK, N.A. Standardized Nuclear Unit Power Plant System, 84/03/06, DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 22616:147 24X Fiche 30-000:84/03/06.8403130342
- --8403130358 Draft "Equipment Qualification Data Package," Rev 4 to EGDP-EBE-13, "Process Protection Bys "
 RAHE,E P Westinghouss Electric Corp WCAP-8587 R4E8E-13D B3/06/30 22pp 22616 153 24X Fiche 50-482,84/03/06,8403130342
- --B403130375 Draft "Equipment Qualification Data Package," Rev 0 to EQDP-ESE-47A. "Boron Dilution Fix Source/Intermediate Range Neutron Detector"
 RAHE.E P Westinghouse Electric Corp WCAP-ESB7 ROESE-47AD
 B3/05/31 20pp 22616 175. 24X Fiche: 50-482, 84/03/06, 8403130342
- B403170421 Notifies of Caseload Forecast Panel B40320-22 sits visit to obtain info re const status Info will be used to better allocate NRC resources during license review List of info requested encl YOUNGBLOOD, B J Licensing Branch i 84/03/07 KOESTER, O. L. Kansas Oas & Electric Co App 22681:336 24X Fiche, 50-482, 84/03/07, 8403190421
- B403270283 Notification of Caseload Forecast Panel 840320-22 eithe visite w/util to review comet progress & assess projected fuel load datas Agenda enci 0'CONNOR.P H Licensing Branch i 84/03/07 YOUNOBLOOD.B J Licensing Branch 1 7pp 22789 254 24X Fiche 50-482.84/03/07.8403270283.
- 840327035i Notification of cancellation of Caseload Forecast Panei 84032i site visit & 840320 & 22 public meetings O'CONNOR:P & Licensing Branch i 84/03/07 YOUNGOLOOD, B J Licensing Branch i 7pp. 22822 256 24X Fiche 30-482,84/03/07, 840327035i
- B403270240 Summary of B40217 meeting w/utile. Bechtei & Westinghouse re slave relay testing frequency & SER open items on loss of instrument bus & boron dilution control HOLONICH.J.J., D'CONNOR.P.W., Licensing Branch 1 B4/03/08 Licensing Branch 1 6pp. 22787.275 24X Fiche 50-000.84/03/08.8403270240
- 8403130197 Forwards add1 info re design process used in constructing facility.per 840104 request Attachment discusses nearly identical design of Callaway & Wolf Creek & minor design features unique to Wolf Creek KDEHTER.O L Kansas Gas & Electric Go 84/03/09 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 30pp 22405:065 24X Fichs: 50-482,84/03/09,8403130197
- 8403150064 Forwards experience tables for shift consultant for hot participation requirements of plan proposed by util group on operating shift experience, KDESTER.Q L. Kanses Qas & Electric Co 84/03/12 DENTON.H R Office of Nuclear Reactor Regulation. Director. 3pp 22643.065 24X Fiche: 50-462.84/03/12,8403150064
- 3403190225 Ack receipt of 840217 ltr responding to NRC 830525 request High school verification diploma verification process acceptable CAGLIARDD.J E. Region 4. Office of Director. 84/03/13. KOESTER. & L. Ransas Gas & Electric Co. 1p 22672 097. 24X Fichs: 50-482, 84/03/13, 8409190225.

- --B403190229 Responds to NRC B30511 & 25 ltrs verifying that employees in positions requiring high school diploma have graduated from high school Background investigation contractor will routinely verify highest education ltr KOESTER. G L Kansas Oas & Ejectric Co 84/02/17 OAGLIARDO, J & Region 4, Office of Director ip 22672 098 24X Fiche 50-482,84/03/13,8403190225
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT.D 0 Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel iOpp 22716 338 24X Fiche 50-000,84/03/14.8402090041
- 84032i0073 Informs that facility fuel load scheduled for 840923 Commercial operation planned for Spring 1985, w/plant scheduling activities retaining target for going commercial during Feb 1985 KDESTER, O L Kansas Gas & Electric Co 84/03/15, DENYON, H R Defice of Nuclear Reactor Regulation, Director 1p 22704 362 24X Fichs 50-482, 84/03/15, 8403210073
- 8403200252 Forwarde Rev 1 to "Review of Boron Dijution Transishte at Wolf Creek" & proof & review pages of Tech Specs deleting boron dilution mitigation sys W/two oversize drawings Aperture cards are available in FDR KOESTER, O L. Kansas Qas & Electric Co. 84/03/ió. DENTON, H. R. Office of Nucteur Reactor Regulation, Director. 5pp. 22687 170 24X Fiche 50-482.84/03/ió.8403200252
- --8403200260 Proof & review pages of Tech Specs deleting boron dilution mitigation sys.

 * Kansas Gae & Electric Co 84/03/16 4pp 22687 175 24X
 Fiche 50-482,84/03/16,8403200232
- --8403200269 Rev i to "Review of Boron Dilution Transiente at Wolf Creek " RUBIN,A , UNIONE,A Impell Corp STEWART,K Kansas Gas & Electric Co 01-0780-1269 ROL 84/03/31 B3pp 22687 180 24: Fiche 50-482,84/03/16.8403200232
- 84032200i9 Forwards add1 info re equipment & seismic qualification & pump & valve operability issues identified by NRC PETRICK,N A Standardized Nuciear Unit Power Plant System 84/03/16 DENTON, HR Office of Nuciear Reactor Regulation, Director 3pp 22713 355 24X Fishe 50-000,84/03/16,84032200i9
- 8403220029 Responds to three NRC questions re analysis of steam generator tube rupture event.contained in FSAR Util reanalyzing condition using operator times from actual events & ANS Draft Std 58 8 Rept expected by 840600 PETRICK.N A Standardized Nuclear Unit Power Plant System 84/03/16 DENTON.H R Office of Nuclear Bactor Regulation, Director 3pp, 227i2 318 24X Fiche 50-000.84/03/16.8403220029
- B403220026 Forwards requested changes to final draft Tech Specs List of Tech Specs discussed widescription of status & action required aiso end!

 PETRICK, N A Standardized Nuclear Unit Power Plant System.

 B4/03/20, DENTON, H R Office of Nuclear Reactor Regulation.

 Director 67pp 22713 215 24% Fiche 50-000.84/03/20.8403220026
- 8403220184 Forwards implementation schedule for resolutions of supplementary survey & auxiliary shutdown panel review findings & list of addl commitments made during NRC audit Human factors items considered closed PETRICK, N A Standardized Nuclear Unit Power Plant System 84/03/21 DENTON, H R. Office of Nuclear Reactor Regulation, Director 7pp 22717 028 24X Fiche 50-000.84/03/21.8403220184
- B4032602B2 Forwards add1 info documenting environ qualification of mechanical equipment program completion per BSER 4 for Wolf Cresk
 PETRICK,N A Brandardized Nucisar Unit Power Plant System 84/03/21 DENTON,H.R Office of Nuclear Reactor Regulation, Director 116pp 22753 034 24X Fiche 50-000.84/03/21.8403260282
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of add1 documents subs to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000, 84/02/13, 8403080179.

- --Bi03040052 Forwards short & long-term OL & CF review schedules, in response to 801216 meeting w/USOS List of OL plant reviews for which NRC tentatively plans to seek U80S assistance is provided
 JACKSON,R E Geosciences Branch NRC-03-80-113 81/01/21 DEVINE,J F Interior. Dept of, Grological Survey Jpp 22583 272 24X Fishe 50-000,84/02/13.8403080179.
- B403270240 Summary of 840217 meeting w/utils, Bechtel & Westinghouse ra slave relay testing frequency & SER open items on loss of instrument bus & boron dilution control HDLONICH, J. J. O'CONNOR, P. W. Licensing Branch 1 84/03/08 Licensing Branch 1 &pp 22789 275 24X Fiche 50-000.84/03/08, MANAGEMENT
- B403200050 Advises that containment pressure-high-1 setpoint complies w/TMI Action Item II E. 4 2. "Containment Isolation Dependability" & SER requirements PETRICK: NA Bandardized Nuclear Unit Power Plant System 84/03/15 DENTON: HR Diffice of Nuclear Reactor Regulation, Director 2pp 22698 271 24% Fiche 50-000.84/03/15,8403200050
- 8403200257 Forwards updated response to request for add1 info remonitoring & evaluating seepage at downstream toe of main dam (SER Confirmatory Item A-2) Info incorporated in OL application
 KUESTER. 9 L Kansas Gas & Electric Co 84/03/16 DENTONH, H R
 Office of Nuclear Reactor Regulation, Director 3pp 22696 359
 24X Fiche 50-482,84/03/16,8403200257
- 8403260282 Forwards add1 info documenting environ qualification of mechanical equipment program completion per 68ER 4 for Holf Creek
 PETRICK.N A Standardized Nuclear Unit Power Flant System 84/03/21. DENTON-H R Office of Nuclear Reactor Regulation,
 Director 116pp 22753 034. 24X Fiche 50-000.84/03/21.8403260282
- F Security, medical, emergency & fire protection plans
- 8403050192 Submits scenario for submittal of info re emergency preparedness & upgrade & maint necessary to snsure proper review & coordination w/all participant organizations COLLINS.J T Region 4, Office of Director 84/02/09 KOESTER, 0 L Kansas Cas & Electric Co 2pp 22485 233 24% Fiche 50-482,84/02/09,8403050152
- 8402090005 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D Q Division of Licensing 84/02/23 PALLADING Commissioners 19 22575 203 24X Fiche 50-000, 84/02/23, 8402090004
- --B403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRR Ofc Ltr 19, dtd 821001 Further swaluation of test data required VOLLMER, R H Division of Engineering 84/02/06 EISENHUT, D. O Division of Licensing. 10pp 22576.204. 24X Fiche 50-000,84/02/23,8402090006
- B403010270 Advises of design changes instituted as result of NRC fire protection review Addl sprintler heads will be installed in auxiliary bldg west corridors at 2.000 ft & 1,974 ft elevations
 PETRICKIN A Standardized Nuclear Unit Power Plant System
 84/02/24. DENTON.H R Office of Nuclear Reactor Regulation,
 Director 2pp 22432 251 24% Fiche 50-000,84/02/24,8403010270
- 8403200253 Clarifies FSAR statement rw fire protection review of seismic design of ail collection devices to maintain functional integrity during postulated SSE Sys pressure boundary will remain intact PETRICK.N A Standardized Nuclear Unit Power Plant System 84/03/14 DENYON.H R Office of Nuclear Reactor Regulation, Director 1p 22690-207 24X Fiche 50-000,84/03/14.8403200253
- G Adjudicatory correspondence
- 8403090053 Patition of Nuclear Awareness Network for leave to intervene & request for hearing Certificate of Syc & affidavits encl JOHNSON A R Nuclear Awareness Network 84/03/06 Commissioners 14pp 22576 189 24X Fiche. 50-482, 84/03/06, 8403090053
- 8403140061 Response to applicant 840203 & staff 840208 responses to Nuclear Awareness Network 840119 petition to intervene & request for hearing. Requests for late-filed intervenor status should be granted. Certificate of Svc encl JOHNSON, A R Nuclear Awareness Network 84/03/06 Commissioners 14pp 22633.065 24X Fiche 50-482,84/03/06,8403140061

- 8403140002 Memorandum memorialiring 840312 conference call re Nuclear Awareness Network. Inc 840221 & 0306 motions WDLFE, 8 J Atomic Safety and Licensing Board Panel. 84/03/13 2pp 22632 127 24X Fiche 50-482,84/03/13.8403140002
- B403140030 Order granting B40221 motion for time extension of addl 15 days to file reply & affidavite per 840209 order WULFE, B J Atomic Sefety and Licensing Board Panel 84/03/13, 1p. 22633 213 24% Fiche 50-482,84/03/13
- 8403190138 Notifias of Caseload Forecast Panel 840320-22 meetings at site to review const progress & obtain add1 info for assessing projected fuel load dates
 MARMAN, M Hearing Branch 1 84/03/13, HOLFE, 8 J. PAXTON, H C.,
 ANDERSON, O C. Atomic Safsty and Licensing Board Panel 1p.
 22668 335 28X Fiche 30-482, 84/03/13, 8403190188.
- 8403190123 Informs that Caseload Forecast Panel 840320-22 meetings cancelled ASLB & parties will be notified upon rescheduling KARMAN, M Hearing Branch 1 84/03/14 WOLFE, S. J., ANDERBON, G.C., PAXTON, H.C. Atomic Safety and Licensing Board Panel 1p. 22669 219 24X Fiche 50~482,84/03/14,8403190123
- 8403190035 Bubmits best estimate dates.par 830412 conference call Completion of const scheduled for 840923, fuel load scheduled for 840923 & commercial operation scheduled for Spring 1985 Certificate of Syc encil Related correspondence SILBERG, J.E. Shaw, Pittman, Potts & Trowbridge SILBERG, J.E. Kansas Oas & Electric Co. 84/03/15 WDLFE.B.J., ANDERSON, G.C. PAXTON, H.C. Atomic Safety and Licensing Board Panel 3pp 22666 212 24X Fichs 50-482,84/03/15,8403190035.
- 8403260325 Proposed findings of fact, conclusions of law & brief in form of proposed initial decision Certificate of 8vc encl BILBERO, J. E. Kansas Cas & Electric Co. SILBERO, J. E. Shaw, Pittman, Potts & Troubridge DBB 091 84/03/20, 275pp. 22760°264, 24X Fiche 50-482,84/03/20,8403260325
- 8403270326 Advises of Caseload Forecast Panel meeting scheduled for BA0410-12 Related correspondence. KARMAN,M Hearing Branch 1 DSB 134 B4/03/22. MOLFE,S J., PAXTON,H C, ANDERSON,O C Atomic Safety and Licensing Board Panel. 1p 22789 019 24X Fiche, 50-482,84/03/22,8403270326.
- B403280334 Memorandum & order denuing patition for leave to intervene & request for hearing Served on 840327 WOLFE, S J Atomic Safety and Licensing Board Panel DSB 146. 84/03/26 Nuclear Awareness Network. 14pp 22787.051. 24X Fiche 50-482.84/03/26.8403280334
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8403200187 Forwards Rev 14 to FSAR Rev will be incorporated into applications of listed dockets by amends submitted by Kansas Oss & Electric Co & Union Electric Co PETRICK, N A Standardised Nuclear Unit Power Plant System.

 84/03/14 DENTON:H R Office of Nuclear Reactor Regulation.

 Director 3pp 22691 i99 24X Fichs 50-000.84/03/14.8403200187
- --B403200189 Rev 14 to FSAR
 * Standardized Nuclear Unit Power Plant System, 84/03/31
 1099pp 22691:202 24X Fiche:50-000.84/03/14.8403200187
- G. Inspection reports: IE Bulletins & correspondence
- 8403280211 FOIA request for documents re falsification of QA/QC records by M Annas at facility BELL.N Nuclear Information & Resource Bervice. 84/01/05. Office of Administration 2pp 22799:326 24X Fiche.50-482.84/01/05. 8403280211.
- 8403130250 Ack receipt of 831130 ltr informing NRC of steps taken to correct violations noted in IE Inep Rept 50-482/83-20 Listed info re experience & training of radiation protection technicians due in 30 days GAQLIARDO, J. E. Region 4. Office of Director 84/02/08. ROESTER: O L. Kanses Gas & Electric Co 2pp 22614.193. 24X Fiche: 50-482,84/02/08,8403130250.
- 8403050177 Forwards IE Insp Rept 50-482/83-36 on 831114-18 % 1128-1201 % notices of violation % deviation GAGLIARDD, J E Region 4. Diffice of Director KOESTER, G, L. Kansas Qas & Electric Co 2pp 84/02/14. Fiche 50-482,84/02/14,8403050179
- --8403050180 Notice of violation from insp on 831114-18 & 1128-1201 * Region 4, Office of Director. 84/02/14 5pp 22485-122, 24% Fiche 50-482,84/02/14,8403050179

- --8403030182 Notice of deviation from insp on 831114-18 & 1128-1201 + Region 4, Office of Director 84/02/14 1p 22485 127 24% Fiche 50-482,84/02/14,8403030179
- --8403050186 IE Insp Rept 50-482/83-36 on 831114-18 & 1128-1201 Violations noted failure to have steel erection & audit procedures Deviation noted failure to comply w/FSAR commitment to ANSI N45 2 12-1977
 BOARDMAN.J.R., EMITH.W.F., JCHNSON.W.D. Region 4, Dffice of Director 84/02/14 21pp 22485 128 24X Fiche 30-482.84/02/14.8403050179
- 8403010213 Provides data supporting preservice insp relief request re random component & piping welds.per util 840118 itr Listed welds require partial relief from Section XI volumetric exam requirements

 BEIKEN. 8 J Standardized Nuclear Unit Power Plant Bystem 84/02/24

 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp

 22435 231 24X Fiche 50-000.84/02/24.8403010213
- 8401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl.

 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239 24x Fichs 50-000.84/02/28.8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " 8vc list enci GRACE.J N Division of GA, Bafeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp. 22552:329 24X Fiche 50-000.84/03/02,8402090007
- 840207000B IE Info Notice 84-16. "Failure of Automatic Sprinkier Sys Valves to Operate " Svc list encl JORDAN. E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York. Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releasss" Bvc list enci JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Into Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below NI1 Ductility Temp "Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24% Fiche 30-000,84/03/05,8402090011
- B402090024 IE Into Notice 84-09 Rev 1. "Lessons Learned From Image of Firm Protection Bafe Shutdown Bys " 8vc list enc! JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07, Consolidated Edison Co of New York. Inc 118pp 22635.049 24X Fiche 50-000.84/03/07.8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 184 24X Fiche 50-000,84/03/07,8402070028
- 8403280216 Partial response to FDIA request for documents refalsification of GA/GC records by M Annas at facility Forwards App A documents Documentation also available in PDR FELTON, J. M Division of Rules and Records 84/03/07 SELL, N Nuclear Information & Resource Service 2pp 22799 328 24X Fiche 50-482.84/03/07.8403280216
- --8403280225 Discusses review of closed & open files re alleged falsification of traveler records A Gauthier "spread sheet" shows Files 82-10 & 82-13 as closed & assigned to J Sinclair, Region IV had nothing in files BOWERS, H Office of Inspector & Auditor 89/03/16 CUMMINOS. J Office of Inspector & Auditor 1p 22797.330 24X Fiche: 50-482,84/03/07.8403280216
- --8403280227 Forwards I& investigation rept re facility.per telcon request W/o encl CUMMINGS, J. J. Office of Inspector & Auditor 82/01/12. MORRIBETTE, K. Justice, Dept of 1p 22797,331 24X Fiche: 50-482,84/03/07,8403280216
- --8403280235 Responds to Region IV 810722 & IE 811016 memos re improper duplication of safety-related pipe hanger DOJ contacted & advised that no objection raised to IE issuing investigation rept SCHNEBELEN, A Office of Inspector & Auditor 81/12/23. THOMPBON, D. Enforcement & Investigation Staff (Pre 820201) ip 22797:332 24% Fiche 50-482,84/03/07,8403280216

- ~-8403280240 Discusses improper duplication of safety-related pipe hanger K Morrissette.DDJ.apprised on 81:208 of contents of Region IV investigation rept refabrication of safety-related pipe hanger DDJ had no objections to rept issuance SINCLAIR.J R Office of Inspector & Auditor 81/12/23 Office of Inspector & Auditor 81/12/23 Office 84/03/07.8403280216
- 8403130320 Ack receipt of 840217 ltr informing NRC of steps taken to correct violations noted in JE Insp Rept 30-462/83-30 OAGLIARDO, JE Region 4. Office of Director 84/03/08 KOESTER, O L. Kansas Qas & Electric Go 2pp 22607 273 24X Fiche 50-482,84/03/08.8403130320
- --8403130345 Revises response to NRC 631125 ltr re violations noted in IE Insp Rept 50-482/83-30 Corrective actions pracedure revised to require quality inspector to complete tool, mati-equipment & personal property written records KOESTER.6 L Kansas Qas & Electric Co 84/02/17 OAQLIARDO, J E Region 4, Office of Director ip 22607 275 24% Fiche 50-482,84/03/08,8403130320
- 8403130390 Ack receipt of 840222 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-482/83-39 GAGLIARDO, J E Region 4, Office of Director 84/03/08 KDESTER, G L Kansas Cas & Electric Co ip 22616 001 24X Fiche 50-482,84/03/09.8403130390
- --8403130397 Responds to NRC 840123 itr re violations noted in IE Insp. Rept 50-482/83-37 Corrective actions two bonic acid transfer pumps roinstailed & bent frame on Pump PB002A reworked Sys. Flushed & hydrostatically tasted KOESTER, C. Kansas Qas & Electric Co. 84/02/22 GAGLIARDO, J. E. Region 4, Office of Director. 3pp. 22616 002 24X Fiche 50-482,84/03/08,8403130390
- 8402090031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl
 DEYQUNG.R C Director's Office, Office of Inspection and
 Enforcement 84/03/12 Consolidated Edison Co of New York, Inc
 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- 8403160119 Forwards vendor insp repts identifying concerns based on Vendor Program Branch insps of vendor activities Significance of findings re quality & acceptability of product or svc provided by vendor should be evaluated GAOLIARDO.J E Region 4, Office of Director B4/03/13 KDESTER, O L Kansas Gas & Electric Co 2pp 22655.116 24x Fiche 50-482-84/03/13.8403160119
- 8403200178 Forwards vendor insp repts indentifying concerns found during insps of vendor activities Evaluation of significance of reported findings re quality & acceptability of product or svc provided by vendors requested W/o enci repts OAOLIARDO, J & Region 4. Office of Director 84/03/16 KDESTER, O L Mansas Oas & Electric Co 4pp 22697 127 24X Fiche 50-482,84/03/16,8403200178
- 8402090043 IE info Notice 84-i9, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000.84/03/21.8402090043
- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Refety-Related Bys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000.84/03/21,8402090044
- 8403270128 Suppls 840224 request for relief from ASME Section XI preservice exam requirements for component & piping sys unlds.per 840308 belicon Relief requested for reactor pressure vessel weld SEIKEN.S J Standardized Nuclear Unit Power Plant System 84/03/26 DENTON, H R Defice of Nuclear Reactor Regulation, Director 2pp. 22807 192 24X Fiche 50-000.84/03/26.8403270128
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS,W J Office of the Executive Director for Operations
 84/02/21 PALLADINO Commissioners 9pp 22492 083 24X
 Fiche, 50-000, 84/02/21, 8403020443

- S Reportable occurrences, LERs & related correspondence
- 8403010145 Final deficiency rept re Bergen-Paterson weld beam attachment laminations Initially reported on B30617 Item determined not reportable per 10CFR50 55(e) KOESTER, G L Kansas Gas & Electric Co 84/02/22 GAGLIARDO, J E Region 4. Office of Director ip 22435 312 24x Fiche 30-482.84/02/22,8403010145
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpol NP8-4 T&T valve, to close Enci 1tr dtd 840203 sent to listed utils GE notified of affected units in BWR plants
 THEROUX, R. Terry Corp. 84/02/22 WOODRUFF, R.W. Director's Office, Office of Inspection and Enforcement. 6pp. 22704 327 24X Fiche 50-000,84/02/22,8403210032
- 8403130219 Interin potential deficiency rept re water damaged Limitorque operators Initially reported on 840203 Investigation indicated water may mave entered actuator bores through installed flexible conduit KCESTER.G L Kansas Gas & Electric Co 84/03/01 GAGLIARDO, J E Region 4. Office of Director 1p 22614 110 24X Fiche 50-482.84/03/01,8403130215
- 8403190036 Interim deficiency & Part 21 repts re status on open items KDESTER.G L. Kansas Gas & Electric Co. 84/03/05 GAGLIARDO, J & Region 4, Office of Director 18pp 22666 215 24X Fiche 50-482.84/03/05,8403190036
- 8403190316 Interim deficiency rept re leaking check valves Initially reported on 840206 Constructor/startup interface examined to assure controls exist to identify 2 track incomplete items KDESTER.O L. Kansas Gas & Electric Co. 84/03/07 GAGLIARDO, J. E. Division of Resident, Reactor Project & Engineering Programs 2pp 22674 361 24x Fiche 50-482,84/03/07.8403190316
- 8403270105 Final deficiency rept re exposed threads on seal welded connections on Class 2 threaded pipe connections Initially reported on 831012 Connections reworked & dye penetrant tested KDESTER, C L. Kansas Gas & Electric Co. 84/03/16. GAGLIARDD, J E Region 4. Office of Director 1p. 22766 346 24X Fiche 30-482,84/03/16,8403270105
- 8403270191 Withdraws deficiency rept re cracked cand edge connector receptacles in Westinghouse 7300 process sys initially reported on 831025 Uti) determined no adverse affect on safety operations Item not reportable per 10CFRSO 55(e) KDESTER.O L. Kansas Gas & Electric Co. 84703/16 GAGLIARDO, J E Region 4. Office of Director 1p. 22769 148 24% Fiche 50~482.84/03/16.8403270151
- 8403270163 Withdraws deficiency rept re welds on Bergen-Paterson sway struts Initially reported on B30224 Welds should not have adversely affected safety of operations if gone uncorrected Item not reportable per 10CFR50 55(e) KOESTER.G L Kansas Gas & Electric Co 84/03/16 GAGLIARDD.J E Region 4. Office of Director 1p 22764 024 24X Fiche 50~482.84/03/16.8403270163
- 8403270179 Deficiency rept re interpretation of code welding subsection classification initially reported on 831208 Helds dye penetrant tested & found acceptable Condition determined not reportable per 10CFR50 85(s)
 KDESTER.O L Kansas Oas & Electric Co 84/03/16 GAGLIARDD, J E Region 4. Defice of Director 1p 22771 131 24X
 Fithe 50-482.84/03/16.8403270179
- 8403270268 Withdraws deficiency rept re pulsation dampeners for positive displacement charging pump initially reported on B31222 Util determined conditions would not affect safety of operations Item not reportable per 10CFRS0 55(e) MOESTER.G L Kansas Gas & Electric Co 84/03/16 GAOLIARDD, J E Region 4. Office of Director 1p 22770 134 24X Fiche 50-482.84/03/16.8403270268
- 8403230108 Part 21 rept re design deficiency in field-run cables to Valcor solenoid valves Initially reported on 840319 Approx 50 valves affected at each facility Mgt corrective action repts issued MEYERS.B L. Bechtel Corp. 84/03/19 DEYOUNG.R Director's Office. Office of inspection and Enforcement 2pp 22730 234 24X Fiche 50-000.84/03/19.8403230108

V Operator Examinations

- B403090225 Forwards operating shift experience tables for shift supervisors, sentor reactor operators & control room operators, per Util Group on Operating Shift Experience B40224 meeting KOESTER, 9 L Kansas Gas & Electric Co 84/03/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 22571 016 24% Fiche 50-482,84/03/06,8403090225
- DOCKET STN-50-483 CALLAWAY PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8402090302 Notifies that Rev 2 to "Rept of Independent Review of Environ Gualification Programs to NUREG-0588" not complete reissue, per 840201 1tr Several rept apps had no changes PETRICK, N A Standardized Nuclear Unit Power Plant System 84/02/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 82160 174 24X Fiche 50-000,84/02/07,8402090302
- B402090017 Board Notification 84-038 forwards RJ Mattson 840123 memo to D0 Eisenhut providing status update of NRC actions re Hestinghouse ECC8 actuation logic EISENHUT,D G Division of Licensing 84/02/27 PALLADING, GILINSKY, ROBERTS Commissioners 7pp 22546.007 24X Fiche 50-000,84/02/27,8402090017
- --B40201030B Provides updated status of rev to Westinghouse designed PWR ECCS actuation logic Westinghouse plans completion of evaluation for submittal by mid-Mar 1984 MATTSON,R J Division of Bystems Integration (post 811005) 84/01/23 EIBENHUT.D Division of Licensing 2pp 22546 007 24% Fiche 50-000, 84/02/27,8402090017
- 8403010406 Forwards listed addi info to slave relay testing Tech Spec requirements for ESF actuation sys.per 840217 request Meeting winstrumentation & Control Sys Branch requested during wit of 840227 PETRICK, N A Standardized Nuclear Unit Power Plant System 84702/27 DETRION, H R Office of Nuclear Reactor Regulation, Director 82pp 22433 297 24X Fiche 50-000,84/02/27,8403010406
- 8403050383 Requests specific wording of proposed change to Tech Spec 3 6 i 7 b % technical bases for acceptability of change re 500 h mini purge limit Changes requested within 7 days of itr receipt YOUNOBLOOD. II J. Licensing Branch 1 84/02/27 8CHNELL.D.F. Union Electric Co. 3pp. 22501 330 24X Fiche 50-483.84/02/27,8403050333
- 8403120182 Revised "Process Control Program" W/840308 Itr MAMILTON.0 W , SCHNELL.D F Union Electric Co 84/02/28 DENTON.H R Office of Nuclear Reactor Regulation, Director 22587 151 24X Fiche 50-483,84/02/28,8403120182
- 8403120363 Forwards request for addl info to complete evaluation of Instrumentation & Control Bys Branch site audit Info should be submitted by 840420 YOUNGILODD, B. J. Licensing Branch i 84/02/29 KOESTER, Q. L. Kansas Oas & Electric Co. SCHNELL, D. F. Union Electric Co. 4pp 22615 354 24% Fiche 50-000.84/02/29,8403120363
- 8403120249 Forwards comments of review of process control program Revised version, incorporating comments, requested no later than 14 days from itr date YOUNGBLOOD, B J Licensing Branch 1 84/03/01 SCHNELL, D F Union Electric Co 4pp 22619 145 24X Fichs 50-483,84/03/01,8403120249
- 8403140283 Ack receipt of util 840202 request to withhold proprietary version of "BNUPPB Steam Generator Tube Plugging Margin Evaluation" from public disclosure Based on listed reasons, submitted info will be withheld (ref 100FR2 790) YDUNGBLOOD, B Licensing Branch 1 84/03/01. WIESEMANN, R. A Westinghouse Electric Corp 4pp 22636 323 24X Fiche 50-000,84/03/01,8403140283.
- 8403060278 Forwards equipment qualification data package for HE-1 to support justifications for interim operation Odd-numbered pages mistakeniy not copied EGDP-HE-1 substitutes into in previous parkage
 PETRICK,N A Standardzized Nuclear Unit Power Plant System,
 84/03/05 DENTON,H R Office of Nuclear Reactor Regulation,
 Director 1p 22518 099 24X Fiche 50-000/84/03/05,8403060298
- 8403130342 Forwards justification for interim operation (JIO) for listed programs & draft Westinghouse Class 3 topical repts Final resolution of issues for listed JIOs expected by 830331 PETRICK, N A Standardized Nuclear Unit Power Plant System 84/03/04 DENTON, H R Office of Nuclear Reactor Regulation, Diractor 4pp 22616 149, 24X Fiche 30-000,84/03/06,8403130342

- 8403120104 Rev 2 to "Offsits Dose Calculation Manuel " W/840308 ltr NEIGHALFEN A P , SCHNELL, D F Union Electric Co 84/03/07 DENTON, H R Office of Nuclear Reactor Regulation, Cirector 127pp 22585 002 24% Fiche 50-483,84/03/07,8403120104
- 8403120171 Forwards revs to FBAR Section 17 2 12 re calibr performed against certified equipment of ref stds Revs resulted from recent discussions w/94 Branch personnel & will be incorporated in Rev 8 to FBAR site addendum SCHNELL.DF Union Electric Co 84/03/08 DENTUN,H R Office of Nuclear Reactor Regulation, Director 3pp 22587 181 24X Fichs 50~483.84/03/08,8403120171
- 8403270240 Summary of 840217 meeting w/utils, Bechtel & Westinghouse re slave relay testing frequency & SER open items on loss of instrument bus & boron dilution control HDLONICH, J J , D'CDNNDR, P W Licensing Branch 1 84/03/08 Licensing Branch 1 &pp 22789 275 24X Fiche 50-000,84/03/08,8403270240
- 8403270271 Summary of 840215 & 14 meetings w/util re rev to operational GA program Util responses received by 840221 & NRC evaluations will be reported in SERR 3 Attender list encl HDLONICH, J J Licensing Branch 1 84/03/08 Licensing Branch 1 5pp 22789 267 24X Fiche 50-483,84/03/08,8403270271
- 8403280129 Forwards final draft Tech Specs for review Amend to application should be submitted incorporating changes to accurately reflect plant, FSAR & SER analyses EISENHUT, D O Division of Licensing 84/03/08 SCHNELL, D F. Union Electric Co 467pp 22807 331 24X Fiche, 50-483, 84/03/08, 8403280129,
- 8403160323 Forwards addl responses to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATMS Events"
 Bufficient info submitted to support issuance of DL by three oversize drawings Aperture cards are in PDR SCHNELL.DF Union Electric Co 84/03/12 DENTON.H R Office of Nuclear Reactor Regulation. Director 55pp 22662 195 24X Fichs.50-483.84/03/12.8403160323
- 8403190269 Forwards tables defining nuclear plant experience of shift supervisors, senior operators, reactor operators & shift technical advisors
 SCHNEEL, D. F. Union Electric Co. 84/03/19 DENTON, H. R. Defice of Nuclear Reactor Regulation, Director 7pp 22671 206 24X
 Fichs: 50-483, 84/03/13, 8403190269
- 8403280015 Notification of 840315 meeting w/utils in Bethesda.MD to discuss appeal of containment purge operation time limit given in Tech Specs Agenda encl HOLDNICH.J J Licensing Branch 1 84/03/13 YOUNOBLOOD.B J Licensing Branch 1 5pp 22812 326 24X Fiche 50-483.84/03/13.8403280015
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EIBENHUT, D G Division of Licensing 84/03/14 Atomic Bafety and Licensing Board Panel 10pp 24X Fiche 50-000,84/03/14,8402090041
- B403210121 Advises of inadvertent error in Attachment 2 of 840306 ltr (ULNRC-754) appealing 300 h mini-purge limit, per Tech Spec 3, 6 1, 7 b First & second paragraphs should read as stated SCHNELL-D F Union Electric Co 84/03/14 DENTON, H R Office of Nuclear Reattor Regulation, Director 3pp 22707 igo 24X Fiche 50-483,84/03/14,8403210121
- 8403220019 Forwards addl info re equipment & seismic qualification & pump & valve operability issues identified by NRC PETRICK.N A Standardized Nuclear Unit Power Plant System 84/03/16 DENTON, HR Office of Nuclear Reactor Regulation, Director. 3pp. 22713 355 24X Ficher 50-000, 84/03/16, 8403220019
- B403220029 Responds to three NRC questions re analysis of steam generator tube rupture event, contained in FBAR Util reanalyzing condition using operator times from actual swents & ANB Draft Std 58 B Rept expected by 840630 PETRICK.N.A Standardized Nuclear Unit Power Flant System B4/03/14 DENTON.HR Diffice of Nuclear Reactor Regulation, Director 3pp 22712.318 24X Fiche 50-000,84/03/16,8403220029
- 8403220026 Forwards requested changes to final draft Tech Specs List of Tach Specs discussed w/description of status & action required also encl PETRICK.N A Standardized Nuclear Unit Power Plant System 84/03/20 DENTON, H R Office of Nuclear Reactor Regulation, Director. 67pp. 22713,215 24X Fiche 50-000,84/03/20,8403220026

- 8403220184 Forwards implementation schedule for resolutions of supplementary survey & auxiliary shutdown panel review findings & list of addi commitments made during NRC audit Human factors items considered closed PETRICK, N A Standardized Nuclear Unit Power Plant System 84/03/21 DENTON.H R Office of Nuclear Reactor Regulation. Director 7pp 22717 028 24X Fiche 50-000,84/03/21,8403220184
- 8403260282 Forwards add) info documenting environ qualification of mechanical equipment program completion per 55ER 4 for Wolf Creel
 PETRICK, N A Standardized Nuclear Unit Power Plant System 84/03/21 DENTON:H R Office of Nuclear Reactor Regulation, Director 1/6pp 22753 034 24% Fiche 50-000.84/03/21.8403260282
- B403270016 Requests issuance of QL in order that outlined activities for fuel load may proceed as planned Unit may be ready for fuel load as early as 840423 SCHNELL, D F Union Electric Co 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 13pp 82770 043 24X Fiche 50-483,84/03/23,8403270016
- 8403270229 Provides add1 info re 40-yr operating term commencing w/ Issuance of OL SCHNELL, D.F. Union Electric Co. 84/03/23 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 4pp 22772 130 24X Fiche 50-483,84/03/23.8403270229
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403270240 Summary of 840217 meeting w/utils.Bechtel & Westinghouse re slave relay testing frequency & SER open items on loss of instrument bus & boron dilution control HDLONICH.J.J. Licensing Branch 1 6403/08 Licensing Branch 1 6pp 22789 275 24X Fiche 50-000.84/03/08.8403270240
- B403270271 Summary of 840215 & 16 meetings w/utl1 re rev to operational GA program Utl1 responses received by 840221 & NRC evaluations will be reported in SSER 3 Attender list encl HOLONICH.J J Licensing Branch 1 84/03/08 Licensing Branch 1 5pp 22787 267 24X Fiche 50-483,84/03/08,8403270271
- B403200050 Advises that containment pressure-high-1 setpoint complies w/TMI Action Item II E 4 2, "Containment Isolation Dependability" & SER requirements PETRICK: N A Standardized Nuclear Unit Power Plant System B4/03/15 DENTON: R Office of Nuclear Reactor Regulation, Director 2pp 22698 291 24X Fiche 50-000,84/03/15,8403200050
- F Security, medical, emergency & fire protection plans
- 84030700B1 Callaway/Fulton Countles,MO radiological emergency response plan * Callaway County, MO * Fulton, MO 83/05/11 164pp 22539 110 24X Fiche 50-483,83/05/11,8403070081
- 8403070078 Hontgomery County, MO radiological emergency response plan 4 Montgomery County, MO 83/05/16 156pp 22539 274 24X Fiche 50-483,83/05/16,8403070078
- 8403070084 Qasconade County, MO radiological response plan * Gasconade County, MO 83/05/16 160pp 22547 101 24% Fiche 50-483, 83/05/16, 8403070084
- 8403070090 Usage County, MO radiological emergency response plan * Daage County, MO 83/05/16 158pp 22548 102 24X Fiche 50-483,83/05/16,8403070090
- B403070087 State of MO nuclear accident plan * Missourl, State of B3/05/31 400pp 22540 070 24X Fiche 50-483,83/05/31,8403070087
- 8402270156 Revised emergency plan implementing procedures, including Procedures EIP-22-00202 re callout of emergency organization & EIP-22-00224 re transport of contaminated injured/111 personnel W/840216 transmittal & receipt form # Union Electric Co 84/02/16 53pp 22387 238 24X Fiche 50-483,84/02/16,8402270156
- 8403090204 Rev O to Security Dept Procedure SDP-ZZ-PP005, "Protected & Vital Area Entry/Exit" W/transmittal & receipt form 4td B40302 H1001NS.T Union Electric Co B4/02/17 Sipp 22574 294 24X Fiche 50-483,84/02/17,8403090204

- 8402070006 Board Notification 84-034 forwards R Vollmer 840206 memu to D Elsenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D 6 Division of Licensing 84/02/23 PALLADINO, GILINSKY, ROBERYS Commissioners 1p 22576 203 24X Fiche 30-000,84/02/23,8402070006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NRR OFC Ltr 19, dtd 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT, D O Division of Licensing 10pp 22576 204 24% fiche 50-000, 84/02/23, 84020900006
- B403010270 Advises of design changes instituted as result of NRC fire protection review Add1 sprinkler heads will be installed in auxiliary bidg west corridors at 2.000 ft & 1.974 ft elevations
 PETRICK, N A Standardized Nuclear Unit Power Plant System 84/02/24 DENTUM, H R Office of Nuclear Reactor Regulation, Director 2pp 22432 251 24X Fiche 50-000, B4/02/24. B403010270
- 8403090263 Revised emergency plan implementing procedures, including Procedures EIP-22-00101 re classification of emergencies & EIP-22-00210 re in-plant radiological controls W/B40225 transmittal & receipt forms * Union Electric Co 84/02/25 200pp 22573 319 24X Fiche 50-483.84/02/25.8403090263
- 8403050016 Forwards Rev 7 to radiological emergency response plan. SCHNELL.D F Union Electric Co 84/03/01 DENTON.H R Office of Nuclear Reactor Regulation. Director 5pp 22485 304 24X Fiche.50-483.84/03/01.6403050016
- --8403050019 Rev 7 to radiological emergency response plan • Union Electric Co 84003/01 354pp 22486 238 24: Fiche 50-483, 84/03/01, 8403050016
- 8403090283 Forwards State of MO & local radiological emergency response plans, for incorporation into Facility application W/o encls SCHNELL, D F Union Electric Co 84/03/01 DENTON, H Office of Nuclear Reactor Regulation, Director 3pp 22574 269 24X Fiche 30-483,84/03/01,8403090283
- 8403120046 Advises of 840323 regional workshop in Resement, IL w/all Region III licensess to discuss fire protection safe shutdown requirements of 10CFR50, App R Agenda encl SPESSARD, R L Division of Emergency Preparedness & Operational Support 84/03/06 SCHNELL, D F Union Electric Co 3pp 22589 295 24X Fiche 50~483,84/03/06,8403120046
- 8403200111 Forwards IE Emergency Preparadness Appraisal Rept 50-AB3/B4-O2 on 840107-20 & 0222 No deficiencies, deviations or noncompliance noted Apps A & B re open & Improvement items, respectively, also enci PAPERIELLO, C J Region 3, Office of Director 84/03/06 SCHNELL, D F Union Electric Co 17pp 22683 167 24X Fiche 50-483,84/03/06.8403200111
- --B403200119 IE Emergency Preparedness Appraisal Rept 50-483/B4-02 on 840109-20 \$ 0222 No deviations or noncompliance noted Major areas inspected onsite emergency preparedness involving organization, training & retraining & drills & exercises PLOSKI.T. GLOERSEN.W. Region 3, Office of Director ROHRER, D Director's Office. Office of Inspection and Enforcement 84/03/05 67pp 22683 184 24X Fiche 50-483,84/03/06.8403200111
- 8403160246 Revised emergency plan implementing procedures, including Procedure EIP-ZZ-00102 re emergency implementing actions, EIP-ZZ-00201 re notifications & EIP-ZZ-00212 re protective action recommendations W/840307 trensmittal.

 MITTENBERGER'S Union Electric Co 84/03/07 134pp 22861 226 24X Fiche 50-483,84/03/07.8403160246
- B403200237 Revised emergency implementing procedures, including Rev 2 to Health Physics Departmental Procedure HDP-ZZ-06000 re contamination guidelines & limits & Rev 1 to Health Physics Technical Procedure HTP-ZZ-02005 W/840308 ltr KANYO,J P Union Electric Co 84/03/08 40pp 22471 135 24X Fiche 50-483,84/03/08,8403200237

- 8403200253 Clarifies FSAR statement re fire protection review of spismic design of oil collection devices to maintain functional integrity during postulated SSE Sys pressure boundary will remain intact PETRICK: N A Standardized Nuclear Unit Power Flant System 84/03/14 DENTON: H R Office of Nuclear Reactor Regulation, Director ip 22690 207 24x Fiche 50-000.84/03/14.8403200253
- 8403300209 Procedure request form & nuclear safety evaluation checklist for Rev 1 to Emergency Implementing Procedure ETP-ZZ-00210. "Radiological Controls During Emergencies " W/840322 Transmittal 1039 Uncontrolled copy & Union Electric Co 84/03/22 4pp 22819 327 24X Fiche 50-483,84/03/22,8403300209

G Adjudicatory correspondence

- 8403070116 Order extending time until 840312 for Commission to act to review ALAB-740, -750, -750A & -754 CMILK, 5 J Office of the Secretary of the Commission 84/03/05 Commissioners 1p 22341 355 24X Fiche 50-483,84/03/05,
- 8403190144 Advises that time for Commission to review ALAB-740,750.750A & 754 expired Commission declined review Decision became final agency action on 840312 CHILK, S J Office of the Secretary of the Commission 84/03/16 Union Electric Co 1p 22666 357 24X Fiche 50-483,84/03/16, 8403190144
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8403050016 Forwards Rev 7 to FSAR site addendum (filed in PDR Category K) & Rev 7 to radiological emergency response plan (filed in PDR Category F)
 8CHNELL, D F Union Electric Co 84/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 22485 304 24X
 Fiche 50-493,84/03/01.8403050016
- --8403050018 Rev 7 to FSAR site addendum * Union Electric Co 84/03/01 287pp 22485 309 24X Fiche 50-483,84/03/01.84/03050016
- 8403200187 Forwards Rev 14 to FBAR Rev will be incorporated into applications of listed dockets by amends submitted by Kansas Gas & Electric Co & Union Electric Co PETRICK, N A Bandardized Nuclear Unit Power Plant Bystem B4/03/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22671 199 24X Fiche 50-000, 84/03/14, 8403200187
- --8403200189 Rev 14 to FSAR * Standardized Nuclear Unit Power Plant System 84/03/31 1099pp 22691 202 24X Fiche 50-000,04/03/14.8403200187

M Antitrust correspondence

- B403070045 Apologizes for slow response to 840208 request for addl info on wheeling contract No new addl info available Agreement not yet in sight CARTER.B R Kirksville, MO 84/02/29 LAMBE,W Site Analysis Branch lp 22541 247 24X Fiche 50-483,84/02/27,8403070045
- G Inspection reports, 1E Bulletins & correspondence
- 8403080251 Forwards IE lnsp Rept 50-483/84-01 on 840104-27 % notice of violation SYREETER, J F Region 3, Office of Director 84/02/22 SCHNELL, D F Union Electric Co 2pp 22556 273 24X Fiche 50-483,84/02/22,8403080251
- --B4030B0256 Natice of violation from Insp on 840104-27 STREETER, J F Region 3, Office of Director 84/02/21 2pp 22556 295 24X Fiche 50-483,84/02/22,8403080251
- --8403080261 IE Insp Rept 50-483/84-01 on 840104-27 Noncompliance identified inadequate procedures during testing & maint & inadequate test program for spent fuel cooling sys WOHLD:P R . WILLIAMS.D L . FARBER.M J Region 3, Defice of Director 84/02/21 9pp 22556 297. 24X Fiche 50-483,84/02/22.8403080251
- 8403010213 Provides data supporting preservice insp relief request re random component & piping welds, per util 840118 ltp Listed welds require partial relief from Section XI volumetric eram requirements
 SEIKEN.S J Standardized Nuclear Unit Power Plant System 84/02/24
 DENTON, H R Office of Nuclear Reactor Regulation, Director, App 22435 231 24X Fichs 50-000.84/02/24.8403010213

- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enci
 - URDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE.J N Division of GA. Bareguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000,84/03/02,8402090007
- B402090008 IE Info Notice 84-15, "Failure of Automatic Sprinkler Sys Valvee to Operate " Bvc list encl JORDAN,E L Division of Emergency Preparednees & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-i5, "Reporting of Radiological Releases"

 8vc liet encl

 JORDAN,E L. Division of Emergency Preparednees & Engineering

 Response (Post 830103) 84/03/02 Coneolidated Edison Co of New

 York, Inc 119pp 22553 217 24X Fiche 30-000,84/03/02,8402090009
- B4020900i1 IE Info Notice 84-17, "Probleme W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403200111 Forwarde IE Emergency Preparedness Appreisal Rept 50-483/84-02 on 840109-20 & 0222 No deficiencies deviatione or noncompliance noted Apps A & B re open & improvement items, respectively, also encl PAPERIELLO, C J Region 3, Office of Director 84/03/06 BCHNELL, D F Union Electric C o 17pp 22683 167 24X Fichs 50-483,84/03/06,8403200111
- --8403200117 IE Emergency Preparedness Appraisal Rept 50-483/84-02 on 840109-20 & 0222 No deviations or noncompliance noted Major areas inspected onsite emergency preparedness involving organization, training & retraining & drille & exercises PLOSKI, T. GLOERSEN, W. Region 3. Office of Director ROHRER, D. Director's Office, Office of Inspection and Enforcement 84/03/05/67pp 22683 184, 24X Fiche 50-483,84/03/06,8403200111
- B402090024 IE into Notice 84-09. Rev i. "Leseons Learned From Insps of Fire Protection Bate Shutdown Eys" Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co. of New York. Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Btress Corrosion Cracking in PWR 8ys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fichs 50-000,84/03/07.8402090028
- B402090031 IE Bulletin 84-02, "Failures of QE Type HFA Relays in Use in Class IE Bafety Sys." Syc list encl
 DEYOUNG,R C. Director's Office, Office of Inspection and
 Enforcement, 84/03/12 Consolidated Edison Co of New York, Inc
 134pp 22823 674 24X Fiche 50-000,84/03/12,8402090031
- B403200279 Ack receipt of B40309 ltr informing NRC of eteps taken to correct violations noted in 1E Insp Rept 50-483/83-27 BTREETER. J F. Region 3, Office of Director, 84/03/15 BCHNELL, D F Union Electric Co. 1p 22697.093 24X Fiche 50-483,84/03/15,8403200279.
- --8403200285 Responds to NRC 840126 itr re-violations noted in IE Insp. Rept 50-483/83-27 Corrective actions test objectives eection of C8-03E002 revised to indicate changes & acceptance criteria for RHR sus verified 8GNNELL.D F. Union Electric Co. 84/03/09 BTREETER.J F Region 3, Dffice of Director. 3pp 22697 094 24X Fiche, 50-483, 84/03/15,8403200279
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities " Svc liet encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Concolidated Edison Co of New York: Inc 123pp 22823 227 24X Fiche 50-000.84/03/21.8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Sefety-Related Bye." Svc list encl
 JORDAN, EL. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/21 Consolidated Edison Co. of New
 York, Inc. 135pp. 22933 001 24X Fiche 50-000,84/03/21,8402090044

- 8403270128 Supple 840224 request for relief from ABME Section XI preservice eram requirements for component & piping syswelds, per 840308 telcon Relief requested for reactor pressure vessel weld SEIKEN. S. J. Standardized Nuclear Unit Power Plant System 84/03/26 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 22807 192 24X Fiche 50-000.84/03/26,8403270128
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRGKE, H J Office of the Executive Director for Operations 84/02/21 PALLADING Commissionere 9pg 22492 083 24X Fichs 50-000,84/02/21,8403020443
- 8 Reportable occurrences, LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines.01mps1 NPB-4 T&T valve, te close Encl 1tr dtd 840203 sent to listed utils GE notified of affected units in BWR plants
 THEROUX.R R Terry Corp 84/02/22 WDDDRUFF.R W Director's Office. Office of Inspection and Enforcement 4pp 22706 327 24 Fiche 50-000.84/02/22.8403210032
- 8403190034 Interim Deficiency Rept U-69 re missing seismic positioners on four breakers used in reactor trip switchgear supplied by Hestinghouse Initially reported on 840207 Final rept expected by 840414
 SCHNELL, D.F. Union Electric Co. 84/03/08 KEPPLER, J.C. Region 3, Office of Director 2pp 22666 123 24X Fiche 50-483,84/03/08,8403190034
- 8403200028 Final Deficiency Rept U-46 re structural etect boits not tightened to spec requirements Structural adequacy of connections sufficient in as-found condition Potential 10CFR80 55(e) deficiency withdrawn 8CHNELL,D F Union Electric Co 84/03/12 KEPPLER,J 0 Region 3-04/12-05 Director 1p 22696 341 24% Fiche 50-483,84/03/12,8403200028
- 8403230115 Final Deficiency & Part 21 Rept U-62 re failure of stator winding on NEO25 emergency diesel generator mfg by Belvit Power Bys Initially reported on 830812 Stator replaced Emergency generator installed & load tested SCHNELL.D F Union Electric Co 84/03/15 KEPPLER.J O Region 3.04fire of Director 4pg 22730 211 24X Fiche 50-483,84/03/15,8403230115
- B403270079 Final Deficiency Rept U-34 re pipe clamp interference w/rod end of rigid sway etrut assemblies evpplied by Corner & Lada Initially reported on BioBi3 Rework Plan FV-14 implemented to repair sway strut assemblies onsite BCHNELL. D.F. Union Electric Co. B4/03/16 KEPPLER. J. G. Region 3. Office of Director 9pp 22769 220 24X Fiche 50-483.84/03/16. B403270079
- 8403270187 Interim Deficiency Rept U-59 re inconsistent installation beinsp of safety-related control value accessories & vendor supplied safety-related HVAC instrumentation Initially reported on 830727 Final rept by 840411

 8CHNELL-DF Union Electric Co 84/03/16 KEPPLER, J O Region 3-00416 of Director 2pp 22771 322 24X Fiche 30-483.84/03/16, 8403270187
- 8403230108 Part 21 rept re design deficiency in field-run cables to Valcor solenoid valves Initially reported on 840319 Approx 50 valves affected at each facility Mgt corrective action repts issued MEYERS: BL Bechtel Corp 84/03/19 DEYOUNG: R Director's Office. Office of inspection and Enforcement 2pp 22730 234 24X Fiche: 50-000, 84/03/19, 8403230108
- 8403270182 Final Deficiency & Part 21 Hept U-64 re Limitorque valve actuators BN-HV-8812A & B Initially reported on 831017 Valve failure due to improper installation of motor pinion gear All 88-2-80 actuatore verified for proper gear installation 8CHNELL, D F Union Electric Co 84/03/20 KEPPLER, J Q. Region 3: Office of Director 4pp 22771 331 24% Fiche 50-483:84/03/20.8403270182

V. Operator Examinations

8403190269 Forwards tables defining nuclear plant experience of shift supervisore senior operators, reactor operators & shift technical advisore

SCHNELL, D.F. Union Electric Co. 84/03/13 DENTON, H.R. Uffice of Nuclear Reactor Regulation, Director 7pp 22671 206 24X

Fiche: 50-483, 84/03/13, 8403190269

X Onsite Storage of Low Level Waste

8403120182 Revised "Process Control Program" W/840308 ltr HAMILTON,0 W , SCHNELL.D F Union Electric Co 84/02/28 DENTON,H R Office of Nuclear Reactor Regulation, Director 22pp 22589 151 24X Fiche 50-483.84/02/28.8403120182

DOCKET STN-50-486 CALLAWAY PLANT, UNIT 2

A Application/construction stage documents & correspondence

B402090041 Board Notification B4-050 provides Commission policy statement & proposed rulemaking on environ qualifications EIBENHUT, D G Division of Licensing B4/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000,84/03/14,8402090041

S Reportable occurrences, LERs & related correspondence

B403230115 Final Deficiency & Part 21 Rept U-62 re failure of stator winding on NEO28 emergency diesel generator mfg by Beloit Power Bys initially reported on 830812 Stator replaced Emergency generator installed & load tested SCHNELL.D F Union Electric Co 84/03/15 KEPPLER.J Q Region 3, Defice of Director 4pp 22730 211 24X Fiche 50-483.84/03/15, 8402330115

B403230108 Part 21 rept re design deficiency in field-run cables to Valcor solenoid valves Instially reported on B40319 Approx 50 vaives affected at each facility Mgt corrective action repts issued MEYERG. B L Bechtel Corp 84/03/19 DEYOUND. R Director's Office. Office of inspection and Enforcement 2pp 22730 234 24X Fiche 50-000.84/03/19.8403230108

DOCKET STN-50-488 PERKINS NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubet, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179

--Bi02200029 Forwards action pian for resolution of non-TMI issues for pending CP/mfg license applications, per Dfc of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by Bi060i EISENHUT, D G Division of Licensing B0/12/31 VOLLMER, R Division of Engineering ip 22583 277 24X Fiche 50-000,84/02/13,8403080179

DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8403080179 Fourth partial response to FOIA request for six categories of focuments re facilities Forwards App A documents App B document untirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON. J M Division of Ruies and Records 84/02/13 ANDERSON. 8 i Garvey. Schubert. Adams & Barer 7pp 22583 226 24X Fiche 30-000.84/02/13.8403080179

--B102200029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications per Ofc of Nuclear Reactor Regulation approach to resumption of licensing Barete evaluation inputs should be provided by B10601 EISENBUT.D O Division of Licensing 80/12/31 VOLLMER, R Division of Engineering 1p 22583-277 24X Fiche 50-000,84/02/13.8403080179

LEAR STATION, UNIT 3
tage documents & correspondence

sponse to FOIA request for six categories; Forwards App A documents App B (ref FOIA Exemption 5) Review of juest continuing lutes and Records 84/02/13 ANDERSON, 8 I 8 Barer 7pp 22583 226 24X 1080179

--8102200027 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications.per Ofc of Nuclear Reactor Regulation approach to resumption of licensing Safety availuation inputs should be provided by \$10001 EISENHUT.D Q Division of Licensing 80/12/31 VOLLMER.R Division of Engineering 1p 22383 277 24X Fiche 50-000.B4/02/13.8403080179

DOCKET STN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3

G Inspection reports, IE Bulletins & correspondence

B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list and! ORACE.J N Division of GA, Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fichs 50-000.84/03/02.84020900007

DOCKET 50-496 MONTAGUE NUCLEAR FOMER STATION, UNIT 1

G Inspection reports, IE Bulletins & correspondence

8401190072 IE info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 1155p 22909 239 24X Fiche, 50-000, 84/02/28, 8401190072

8402070008 IE info Notice 84-i6. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 078 24X Fiche 50-000,84/03/02,8402070008

8402090009 IE info Notice 64-15, "Reporting of Radiological Releases" Byc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fichs 50-000,84/03/02,8402090009

B402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Caoling Campanents Below Nil Ductility Temp " Svc list enci JDRDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) B4/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22533 336 24X Fiche 50-000,84/03/05,8402070011

8402090024 IE info Notice 84-09. Rev 1. "Lessons Learned From Inspa of Fire Protection Safe Shutdown Bys " Svc iist encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc ii8pp 22635, 049 24X Fiche 50-000, 84/03/07, 8402090024

8402070028 iE info Notice 84-i8, "Stress Corrosion Cracking in FWR Bys " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, inc 118pp 22584 i86 24X Fiche 50-000,84/03/07,8402070028

8402090031 iE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc iist encl
DEYOUNG.R C Director's Office Office of Inspection and
Enforcement 84/03/12 Consolidated Edison Co of New York, Inc
134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031

8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl, JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidate Edison Co. of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043

8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Bys " Svc list enc! JORRAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp. 22933 001 24X Fiche 50-000.84/03/21.8402090044

DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2

G Inspection reports, IE Bulietins & correspondence

8401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Velvs Control Circuits & Annunciation " Svc list enci.

JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 1159p. 22707 237 24X Fiche 50-000,84/02/28,8401190072.

- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl ORACE, J N Division of GA. Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02.8402090007
- 8402090008 IE Info Natice 84-16, "Failure of Automatic Sprinkler Sys Vaives to Operate " Svc list encl JORDAN.E L Division of Emergency Preparednees & Engineering Response (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc liet encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Poet 830103) 84/03/02 Consolidated Edison Co of New York, Inc 117pp 22553 217 24X Fiche 50-000.84/03/02.8402090009
- B402090011 IE Info Notice 84-17. "Probleme W/Liquid Nitrogen Cooling Companente Below N(1 Ductifity Temp " Svc list encl JARDAN, E L Division of Emergency Preparedness & Engineering Responee (Past 830103) B4/03/05 Concolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-07. Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Buc liet enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Strees Corrosion Cracking in PWR Sys " Syc list enci JURDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fichs 50-000,84/03/07,8402090028
- B402090031 IE Bulietin 84-02, "Failures of GE Type HFA Relays in Use in Clase IE Safety Sye " Bvc liet encl DEYOUND, R.C Director's Office, Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823-094 24X Fiche 50-000.84/03/12,8402090031
- B402090043 IE Info Notice B4-19, "Two Events Involving Unauthorized Entries into PNR Reactor Cavities" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Poet B30103) B4/03/21 Consolidated Edison Co of New York Inc 123pp 22823 229 24X Fichs 50-000.84/03/21.8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Byc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Poet B30103) 84/03/21 Consolidated Edison Co. of New York, Inc 135pp 22933 001 24X Fichs 50-000,84/03/21,8402090044
- DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8403010444 Summary of 831130-1202 Caseload Forecast Panel meetings w/util at sits in Matagorda County, TX re review of const progress to obtain info for use as input to OL review schedule process Viewgraphs encl VIETTI.A Liceneing Branch 3 84/02/22 Liceneing Branch 3 79pp. 22449-226 24X Fiche 50-498.84/02/22.8403010444
- B402070017 Board Notification 84-038 forwards RJ Mattson 840123 memo to DG Eisenhut providing status update of NRC actions re Wastinghouse ECCB actuation logic.
 EISENHUT, D 0 Division of Liceneing 84/02/27 PALLADING Commissioners 7pp 22546 007. 24X Fiche 50-000,84/02/27,8402070017
- 8403280122 Bummary of 840224 meeting w/Hestinghouse Gwners Group in Bathesda.MD re proposed Hestinghouse steam generator tube rupture generic program Attendee list & agenda encl NERSES, V Licensing Brench 3 84/03/07 Licensing Brench 3 35pp 22811 131 24X Fiche.50-000.84/03/07.8403280122.
- 8403300125 Forwards draft, "Mitigative Techniques & Analysis of Generic Site Conditions for Groundwater Contamination Associated W/Severe Accidents" KNIOHTON.G.W Licensing Branch 3 84/03/15 GOLDBERO.J H Houston Lighting & Power Co 3pp. 22841 001 24% Fiche 50-498.84/03/15, 8403300125.
- --8403300132 Draft, "Mitigative Techniques & Analysis of Generic Bite Conditions for Groundwater Contamination Associated w/ Severe Accidents "
 SHAFER, J M , QBERLANDER, P. L. , SKAGGS, R. L. Battelle Memorial Institute: Pacific Northwest Laboratories 84/01/31 300pp 22841 004. 24X Fiche 50-498,84/03/15,8403300125

- F Security, medical, emergency & fire protection plans
- 8403050149 Submits scenario for submittal of info re emergency preparedness upgrade & maint necessary to onsure proper review & coordination w/oil participant organizations COLLING.J T Region 4. Office of Director 84/02/09 OPREA.G W Houston Lighting & Power Co 2pp 22484 052 24X Fiche 50-498.84/02/09.8403050149
- 8403010544 Advises that NRC will not delete privacy or proprietary info from emergency plans unless specifically requested by licensee.per 810709 Generic Ltt 81-27 W/o request entire pian will be placed in PDR KNIGHTON.O W Licensing Branch 3 84/02/14 00LDBERO.J H Houston Lighting & Power Co 4pp 22438 339 24X Fichs 50-498.84/02/14, 8403010544
- G Adjudicatory correspondence
- B403070117 Advisee that encl final rept on condition identified in 10CFRSO 55e rept was submitted on 840216 Rept concludes design basic differential settlement criteria not exceeded M/o final rept Certificate of Svc encl NEWMAN, J R Newman & Haltzinger * Houston Lighting & Power Co 84/03/05 BECHHOEFER C. LAMB, J C. HILL, E E Atomic 8afety and Licensing Board Panel 4pp 22541 356 24X Fiche 50-478,84/03/05,840337017
- 8403140192 Motion for reconsideration of ASLB 830714 memorandum & order re 830530 suppl to motion for new contention Centificate of Svc encl SINKIN.L Citizens Concerned About Nuclear Power, Inc 84/03/06 Atomic Safety and Licensing Board Panel 18pp. 22625 173 24X Fiche 50-498.84/03/08.8403140152
- 8403150037 Nemorandum & order for parties not to respond to Concerned Citizens Against Nuclear Power 840308 motion for reconsideration of ASLB 830714 order re financial qualifications contention BECHMOEFER.C Atomic Safety and Licensing Board Panel 84/03/13 Office of the Executive Legai Director 2pp 22643 082 24X Fichs 50-478.84/03/13.8403150039
- 8403i50016 Partial initial Decision LDP-84-13 (Phase 1) re OL Citizens Concerned About Nuclear Power B30808 motion to reopen Phase I record denied BECHMDEFER.C., LAMB, J.C., Hill.E.E. Atomic Safety and Licensing Board Panel B4/03/14, 359pp 22644 001 24X Fiche 50-478, 84/03/14, 8403i50016
- 8403220238 Notice of change of mailing address for Judge Hill ECCHHOEFER.C Atomic Bafety and Licensing Board Panel DED 060 84/D3/20 Office of the Executive Legal Director ip 22719 039 24X Fiche 50-498.84/03/20.8403220238
- B403270025 Notice of intent to appeal Partial Initial Decision 79-421-07 OL Certificate of Svc encl SINKIN.L Citizens Concerned About Nuclear Power, Inc. DBD 119 84/03/23 2pp 22770 071 24X Fiche 50-498,84/03/23.8403270025
- G Inspection reports, IE Bulletins & correspondence
- 8403010125 Further response to FOIA request for IE Rept 79-19, notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards documents listed on App A FELTON-J M Division of Rules and Records 84/01/11 HAMLIN, J B Shaw, Pittman, Potts & Troubridge 2pp 22447 176 24X Fiche 50-498.84/01/11.8403010125
- --8403010132 Requests info re public hearing on insp of facilities SCHMARTIA R Texes. State of 60/06/03 EEYERIT.K Region 4. Dailas. Office of the Director ip 22447 179 24X Fiche 50-498,84/01/11.8403010125
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/28 Consolidated Edison Co of New York, Inc. 113pp 22707 237 24x Fishe 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list and I GRACE, J N Division of On Safeguards & Inspection Programs (Post E30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22532 327 24X Fiche 50-000.84/03/02,8402090007.

- 840207000B IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 078 24X Fiche 50-000.84/03/02,8402070008
- 8402070007 IE Info Notice 84-i5, "Reporting of Radiological Raleases"
 Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02. Consolidated Edison Co. of New
 York, Inc. 1173p 22553 217 24X Ficha 50-000,84/03/02.8402070007
- E402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Delow Ni) Ductility Temp " Svc list encl JURDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York: Inc. 117pp 22532.336 24X Fiche 50-000,84/03/05.8402090011
- 8402090024 IE Info Notice 84-09. Rav i, "Lessons Learnes From Insps of Fire Protection Sase Shutdown Sys " Svc list enc! JORDAN. E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York. Inc. 11839. 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 40209002B IE Info Notice 84-1B, "Stress Corrosion Cracking in PWR Bys " 8yc List encl JGRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 30-000.84/03/07.8402090028
- BA02090031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Glass IE Safety Sys " Svc list encl DEYOUNG.R.C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co. of New York, Inc 134pp 22823 094 24% Fiche: 50-000.84/03/12,8402090031
- B402090043 IE info Notice B4-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list and JORDANIE L Polvision of Emergency Preparedness & Engineering Response (Post B30103) B4/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24% Fiche 50-000.84/03/21,8402090043
- 8402070044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related 102070044 IE Info Notice 84-20. "SWC Life of Relays in Bafety-Related Sys " SVC list encl. JORDAN-E L Division of Empreency Preparadness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc (33pp 22733 001 24X Fiche 30-000-84/03/21,8402070044
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 planning issues
 DIRKMS-W J Dffice of the Executive
 84/02/21 PALLADINO Commissioners
 Fiche 50-000,84/02/21,8403020443 Office of the Executive Director for Operations 22472:083
- B Reportable occurrences. LERs & related correspondence
- 8403210032 Part 2; rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 F&T valve, to close Encl 1tr dtd 840203 sent to listed utils GE notified of affected units in BMR plants
 THEROUX.R R Terry Corp 84/02/22 WOODRUFF.R W Director's
 Office. Office of Inspection and Enforcement 6pp. 22706:327 24X
 Fiche 50-000,84/02/22,8403210032
- 8403130328 Final deficiency rept re pipe stress analysis design process initially reported on 831228 Evaluation complete Item determined not reportable per IOCFR50 55(e) DPREA, G.H. Heuston Lighting & Power Co. 84/02/27 COLLINS, J T Region 4. Office of Director 3pp 22607 245 24X Fishe 50-478, 84/02/27, 8403130328
- 8403130477 Final deficiency rept re reactor containment bldg post-tensioning sys tendone Initially reported on 830826 Demaged tendons will be replaced Tendons will be mfg in time frame to preclude need for long-term storage OPREA.0 H Houston Lighting & Power Co 84/02/29 COLLING, J T Region 4. Office of Director 4pp. 22613 176 24X Fiche. 50-498. 84/02/29, 8403130477.
- 84032702i9 Part 21 rept re broken contect carrier in control device of 7 5 kV-15 kV.300-750 MVA:5 kV 330-3.000 & all HKV circuit breakers. Initially reported on 830223 Addends to installation & maint procedures sent to affected units DVALL:0 D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/i9 Record Services Branch (Document Control Desk) 5pp 22772 114 24% Fiche 50-000:84/03/19:8403270219

T Hearing transcripts on non-antitrust matters

- 8403010125 Further response to FOIA request for IE Rept 79-19, notice of proposed imposition of civil panalties, notice of violation & order to show cause Forwards documents listed on APP A FELTON, J M APP O FELTON, J. M. Division of Rules and Records, 84/01/11 H. Shaw, Pittman, Potts & Trowbridge 2pp 22447·176 24X Fiche 50-498.84/01/11.8403010125
- --8403010139 Transcript of 800819 public meeting in Ray City.TX.Pp 1-382 Supporting documentation encl + Commissioners 80/08/19. 382pp 22447 181 24X Fiche 50-499,64/01/11.8403010123

DOCKET STN-30-499 SOUTH TEXAS PROJECT, UNIT 2

- A Application/construction stage documents & correspondence
- 8403010444 Bummary of B31130-1202 Caseload Forecast Panel ##etings w/util at site in Matagorda County.TX re review of const progress to obtain info for use as input to OL review schedule process.Viewgraphs enc!
 VIETTI, A. Licensing Branch 3 84/02/22 Licensing Branch 3 79pp 22449 226 24X Fiche 50-498,84/02/22,8403010444
- 8402070017 Board Notification 84-038; forwards RJ Matteon 840123 menu to DO Eisenbut providing status update of NRC actions re Westinghouse ECCG actuation logic. EISENHUT.D O Division of Licensing 84/02/27 PALLADING Commissioners 7pp 22546 007 24X Fiche 50-000.84/02/27,
- 8403280122 Summary of 840224 meeting w/Hestinghouse Owners Group in Bethesda: MD re proposed Hestinghouse steam generator tube rupture generic program, Attendee list & agenda encl NERSEG. V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp 22811 131 24X Fiche. 50-000. 84/03/07, 8403280122
- 8403300125 Forwards draft, "Mitigative Techniques & Analysis of Ceneric Site Conditions for Groundwater Contamination Associated w/Severe Accidents"

 KNIGHTON, O W. Licensing Branch 3 84/03/15 QULDBERO, J M. Hous Lighting & Power Co Spp. 22841 001 24X Fichs. 50-498, 84/03/15, 8403300125 Hauston
- F Security, medical, amergency & fire protection plans
- 8403050149 Submits scenario for submittal of info re emergency preparedness upgrade & maint necessary to ensure proper preparedness upgrade & maint necessary to ensure proper raview & coordination w/all participant organizations.

 COLLINS, J T Region 4, Office of Director 84/02/09 OPREA, 0, W Houston Lighting & Power Co 2pp 22484.052, 24X

 Fiche 50-498,84/02/09,8403050149
- 8403010544 Advises that NRC will not delete privacy or proprietary info from emergency plans unless specifically requested by licensee.par 810709 Generic Ltr 81-27 W/o request.entire plan will be placed in PDR KNIOHTON.O W Licensing Branch 3 84/02/14 OOLDBERG.J.H Houston KNICHTON, O W Licensing Branch 3 84/02/14 COLDBERO, J. H House Lighting & Power Co 4pp 22438; 339 24X Fiche, 50-498, 84/02/14, 8403010544.

@ Adjudicatory correspondence

- 8403070117 Advises that encl final rept on condition identified in 100FR30 35e rept was submitted on 840216 Rept concludes design basis differential settlement criteria not exceeded, W/o final rept. Certificate of Bvc encl NEWMAN, J R Neuman & Holtzinger * Houston Lighting & Power Co. 84/03/05 BECHNOFFR; C, LAMB, J, C, HILL, E, E Atomic Safety and Licensing Board Panel 4pp 22541 356 24X Fiche: 50-498, 84/03/05, 84/03/070117
- 8403140152 Motion for reconsideration of ASLB 830714 memorandum & order re 830530 suppl to motion for new contention Certificate of 8yc encil SINKIN, L. Citizens Concerned About Nuclear Power, Inc. 84/03/08 Atomic Sefety and Licensing Board Panel 18pp 22625 173, 24X Fichs 50-498,84/03/08,8403140152 84/03/08.
- 8403150037 Memorandum & order for parties not to respond to Concerned Citizens Against Nuclear Power 840308 motion for reconsideration of ABLB 830714 Order re financial qualifications contention.

 EECHIOEFER, C Atomic Safety and Licensing Board Panel 84/03/13.

 Office of the Executive Legal Director. 2pp 22643.082 24X

 Fiche 50-498,84/03/13,8403150039

- 8403150016 Partial initial Decision LBP-84-13 (Phase I) re OL Citizens Concerned About Nuclear Power 830808 motion to reapen Phase I record denied.
 BECHHOEFER, C., LAMB, J. C., HILL, E. E. Atomic Safety and Licensing Board Panel. 84703/14 357pp 22644 001 24X Fichs 30-498,84/03/14.8403150016
- 840322023B Notice of change of mailing address for Judge Hill BECHMOEFER, C Atomic Safety and Licensing Board Panel DSB 060 84/03/20 Office of the Executive Legal Director ip 22719 039 24X Fiche 30-49B.84/03/20.840322023B
- 3403270025 Notice of intent to appeal Partial Initial Decision 79-421-07 OL Certificate of Syc encl BINKIN, L Citizens Concerned About Nuclear Power, Inc. DBB 119. B4/05/23 2pp. 22770 071 24X Fithe 50-498.B4/03/23, B403270025

Inspection reports: IE Bulletins & correspondence

- 403010125 Further response to FOIA request for IE Rept 79-19, notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards documents listed on 84/01/11 HA App A.
 FELTON, J H Division of Rules and Records 84/01/1
 Shaw, Pittman, Potts & Troubridge 2pp. 22447:176
 Fiche-50-498,84/01/11,8403010125 HAMLIN. J B
- -8403010132 Requests info re public hearing on insp of facilities BCHMARTZ, A R. Texas, State of 80/06/03 SEVERIT, K Region 4, Dallas, Office of the Director. 1p 22447; 179. 24X Fiche: 50-490, 84/01/11.8403010125.
- 01190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Syc list
- WALL JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239, 24% Fiche 50-000,84/02/28,8401190072 JORDAN, E L
- 02070007 IE Info Notice 84-14. "Highlights of Recent Fransport Regulatory Revs by DOT & NRC " Svc list encl 9RACE.J N Division of GA, Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 130pp. 22352:329. R4X Fiche 30-000.84/03/02.8402090007
- 0209000B IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys /alves to Operate." Syt list entl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/02 Consolydated Edison Co of New York, Inc 122pp 22353-078 24X Fiche 50-000.84/03/02.8402090008
-)2070009 IE Info Notice 84-i5. "Reporting of Radiological Releases "
- ye list encl

 IDRDAN.E.L. Division of Emergency Preparedness & Engineering

 ISSUAN.E.L. Division of Emergency Preparedness & Engineering

 Isspense (Post 830103) 84/03/02 Consolidated Edison Co of New

 Tork, Inc. 117pp 22553 217 24X Fiche 50-000.84/03/02.8402070009
- 207001: IE Info Notice B4-17, "Problems W/Liquid Nitrogen Gooling amponents Below Nil Ductility Temp " Svc list encl ORDANIE L. Division of Emergency Preparedness & Engineering sepanse (Post B30103), B4/03/05 Consolidated Edison Co of New Ork, Inc. 117Ap. 22503 336 24X Fiche 50-000,84/03/05,8402090011
- 2090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of ire Protection Sefe Shutdown Sys " Bvc list encl. DRUNN, E L. Division of Emergency Preparedness & Engineering exponse (Post 830103), 84/03/07. Consolidated Edison Co of New ork, Inc. 118pp. 22635 049. 24% Fiche: 50-000, 84/03/07. 8402090024
- 2090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR rs. "Byc list encl.

 RBAN.E L. Division of Emergency Preparedness & Engineering rsponse (Post B30103), 84/03/07 Consolidated Edison Co of New rs, Inc. 118pp. 22884-186 24X Fiche 50-000,84/03/07,8402070028
- '090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in ass IE Safety Sys " Syc list enc! YOUNO, R C. Director's Office, Office of Inspection and forcement 84/03/12. Consolidated Edison Co. of New York, Inc 4pp. 22823: 074. 24% Fiche 50-000, 84/03/12, 8402070031.
- 090043 IE info Notice 84-19, "Two Events Involving Unauthorized tries into PWR Reactor Cavities." Svc list encl RDAN.E.L. Division of Emergency Preparedness & Engineering apponse (Post 830103). 84/03/21 Consolidated Edison Co of New rk. Inc. 123pp. 22823:229. 24X Fiche 50-000,84/03/21,8402090043

- 8402070044 IE Info Notice 84-20, "Syc Life of Relays in Safety-Related 902070049 IE Info Notice B4-20, "Byo Life of Relays in Sarety-Related Sys " Byo list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidate Edison Co of New York, Inc. 133pp 22933 001 24% Fiche 30-000,84/03/21,8402090044
- S Reportable occurrences, LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpel NPB-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BHR THERRUX.R R Terry Corp 84/02/22 MODDRUFF.R W Director's Office. Office of Inspection and Enforcement 5pp 22706 327 24X Fiche. 50-000, 84/02/22, 8403210032.
- 8403130328 Final deficiency rept re pipe stress analysis design process. Initially reported on 831228 Evaluation complete. Item determined not reportable per 100FR50 55(s) OPREAG W Houston Lighting & Power Co 84/02/29 COLLINS, J T Region 4. Office of Director 3pp 22607 245 24X Fiche 50-498,84/02/29,8403130328
- 8403130477 final deficiency rept re reactor containment bldg post-tensioning sys tendons Initially reported on 830826 Demaged fendons will be replaced Tendons will be mfg in time frame to preclude need for long-term storage OPREA:0 W. Houston Lighting & Power Co 84/02/29 COLLINS, J T Region 4. Optice of Director 4pp 22613 176 24X Ficha: 50-498, 84/02/29, 8403130477
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV,500-750 MVA,5 kV 350-3,000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units BUVALL-D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24% Fiche 50-000,84/03/19,8403270219

T Hearing transcripts on non-antitrust matters

- 8403010125 Further response to FOIA request for IE Rept 79-19, notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards documents listed on app A FELTON.J M Division of Rules and Records 84/0i/ik H/ Bhaw, Fittman, Potts & Trombridge 2pp 22447 176 24% Fiche:50-498,84/01/ii,84030i0125
- --8403010139 Transcript of 800819 public meeting in Bay City,TX Pp 1-382 Bupporting documentation enci * Commissioners 80/08/19 382pp 22447 181 24X Fiche 50-498,84/01/11,8403010125.
- DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2 8 Reportable occurrences, LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines.Gimpel NPS-4 TAT valve.to close Encl 1tr dtd 840203 sent to listed utils GE notified of affected units in BWR plants THEROUX, R R THEROUX, R R Terry Corp 84/02/22 WBODRUFF, R W Director's Office, Office of Inspection and Enforcement 5pp 22706 327. 24X Fiche: 50-000, 84/02/22, 8403210032
- DOCKET 50-501 DAVIS-BESSE NUCLEAR POWER STATION: UNIT 3 8 Reportable occurrences, LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE natified of affected units in BWR plants
 THEROUX.R R Terry Corp 84/02/22 MGDRUFF.R.W Director's
 Office, Office of Inspection and Enforcement 6pp 22706 327, 24X
 Fiche 30-000,84/02/22.8403210032
- DOCKET BIN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3 A Application/construction stage documents & correspondence
- 8403010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in PDR upon request Review continuing FELTON.J M. Division of Rules and Records 84/01/17 ANDERSON.S! Oatvey, Schubert, Adams & Barer App 22446 293 24X Fiche 50-000,84/01/17,8403010050

- --B003240159 Advises of refund owed licenses re CP fees for facilities based on professional manpower extended & contractual svcs costs incurred HILLER,W Q License Fee Hanagement Branch 80/03/03 MANION,W E Office of the Controller 2pp 22446 303 24X Fiche 50-000,84/01/17,8403010050
- --8004010752 Confirms B00229 telcon re professional manpower (152-h) provided by B00228 memo Manpower should be divided equally between two units HOLLOMAY, C. J. License Fee Management Branch 80/02/29 FITTII.C. J. Atomic Safety and Licensing Board Panel ip 22446 300 24X Fiche 50-000,84/01/17,8403010050
- --8004010759 Confirms 800226 telcon re professional manpower (18-h) provided by A Rosenthal 781002 memo Manpower should be divided equally between two units HOLLUMAY.C J License Fee Management Branch 80/02/29 BIEHOP.J Atomic Safety and Licensing Appeal Panel. 1p 22446 301 24X Fiche 50-000.84/01/17.8403010050
- --Bii2210133 Informs of 8 McKinney opinion that allocation of ACRS manpower for fee purposes should be divided equally for review of two units at site HOLLOMAY.C J License Fee Management Branch 79/01/22 License Fee Management Branch 50-000,84/01/17.8403010050
- --B30B1004B3 Discusses status of DL applications Review of encl WPPBS B30712 It requested in order to determine present status of Unit 3 for billing purposes M/o encl HILLER-W O Litense Fee Management Branch B3/OB/O5 FONNER, R L Regulations Division 2pp 22A46 326 24X Fiche 50-000. B4/Of/17.8403010050
- 8403080179 Fourth partial response to FGIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld tref FGIA Exemption 5) Review of addi documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERSON. S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 30-000.84/02/13.8403080179
- --B003240202 Submits review costs for facilities Hearing was uncontested Billing procedure may be completed BERKOW.H N Office of Muclear Reactor Regulation, Director 80/02/22 MILLER, U C License Fee Management Branch 1p 22583 242 24X Fiche.50-000.84/02/13.8403080179
- --8003240207 Forwards 15 cost data worksheets for facilities No costs relacted for licensee contractor vendor inspirepts COBB.L I Executive Officer for Management & Analysis 77/01/29 MILLER.W O License Fee Management Branch 3pp 22583 243 24% Fiche 50-000, 84/02/13, 8403080179
- --8003240219 Corrects 781028 memo re WPPSS 3 & 5 being contested Memo reflecting actual ASLB time spent on case encl FITTLC V Atomic Safety and Licensing Board Panel 80/02/28 HOLLOMAY, C J License Fee Management Branch 1p 22583 248 24X Fiche 50-000, 84/02/13, 8403080179
- -8003240222 Submits rept of time spent since program initiated on HPPSS 3 % 5 Professional time ail spent on post-hearing work regarding CP hearing LAZO,R M Atomic Safety and Licensing Board Panel 78/04/11. FITTI.C J Atomic Safety and Licensing Board Panel 3pp 22583 249 24% Fiche 50-000.84/02/13,8403080179
- -8009070737 Forwards airworthiness alert re corrosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Questions re ash amount chemistry & size distribution will be forwarded to licenses Wo enci JACKSON-R E Ososciences Branch 80/06/12 VOLLMER.R H Division of Engineering 2pp 22583 258 24X Fiche 50-000.84/02/13,8903080179
- ~8104300020 Responds to B10414 memo re util request for clarification in use of ASME code cases Util use of code cases w/o prior NRC approval is inadvisable due to potential hardship for user BOSNAX,R J Mechanical Engineering Branch B1/04/21 YOUNGBLOOD,B,J Licensing Branch 1 ip 22583 280 24X Fiche 50-000,84/02/13,8403080179.
- -8107270274 Accepts use of ASME Code Case N-242-1 dt# 800410 for application in const of pipe support frames in pipe chases located in two lower elevations of reactor auxiliary bidg Conditions of use discussed KNIGHT.JP Assistant Director for Comp & Structures Engineering (Pre 830201) 81/07/21 TEDESCO.R L. Assistant Director for Licensing ip 22589 301 24X Fiche. 50-000: 84/02/13,8403080179

- --810811003B Notification of 810820 meeting w/util in Bethesda, MD to discuse proposed independent design review programs HERNAN, R W Licensing Branch 4 81/07/30 ADENSAM, E Q Licensing Branch 4 3pp 22583 302 24X Fiche 50-000, 84/02/13, 8403080179
- --8110080612 Discusses proposal to use IDRs in licensing process IDRs eave be useful in certain areas, but clarification of role needed, TEDESCO.R L. Assistant Director for Licensing 81/09/23 EISENHUT, D 0 Division of Licensing ip 22583 307 24X Fiche 50-000,84/02/13,8403080179
- --Bli1200219 Informs of receipt of telcon from Yakamar Indian Nation requesting that tribe be given full rights in facilities proceedings
 TEDESCO, R L. Assistant Director for Licensing. Bl/10/21
 KETCHEN, E. Hearings Division 1p 22583 310 24X
 Fiche 50-000, 84/02/13,8403080179
- ---8203180118 Forwards two relevant documents for FOIA request re HPPSS & Exxon Litigation
 MIRAGLIA.F J Licensing Branch 3 82/03/08 WILSON,V H.
 Management Analysis Branch 3pp 22583:333 24x
 Fichs 50-000,84/02/13,8403080177
- --8204270657 Notification of 820511 meeting w/util to discuss review process & preliminary identification of any possible unique features

 WHEELER. L Licensing Branch 3 82/04/22 MIRAGLIA, F J
 Licensing Branch 3 1p. 22583 340 24X Fiche 30-000,84/02/13,8403080179
- --B206300082 Lists info not yet addressed for QL application Recomments general info be accepted for docketing LEE, I J. Licensing Branch 3 82/06/18 WHEELER, L L Licensing Branch 3 1p. 22583 347 24X Fiche 50-000.84/02/13.8403080179
- --8303100476 Forwards util 830223 submittal in response to telcon during which remaining Phase I open items of "Control of Heavy Loads -- Case Reviews," were discussed W/o encl CLEMENSON, F. Auxiliary Systems Branch NRC-20-i8-388 83/02/28 STICKLEY, I H. EG&G. Inc. 1p. 22583 360, 24X Fiche 50-000,84/02/13,8403080179
- --8304060977 Requests search for documents re gavt litigation w/util on five specific issues
 BLA091E, E. Office of the General Counsel 83/03/23,
 DIRKKB, W.J. Office of the Executive Director for Operations ip
 22583 361 24X Fiche:50-000,84/02/13,8403080179,
- --8403080253 Forwards summary of review costs & supporting documentation from program ofcs W/o encl HOLLOWAY.C J License Fee Management Branch 80/03/03 License Fee Management Branch 80/03/03 License Fee Management Branch 1p 22583 241 24X Fiche 50-000.84/02/13, 8403080179
- 8403050288 Fifth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App A & B documents also available in PDR Documents listed on App C & D located in Central Files & not available publicly FELTON, J M Division of Rules and Records 84/02/17 ANDERSON, & I Garvey, Schubert, Adams & Barer 7pp 22501,289 24X Fiche 50-508,84/02/17,8403050288
- --7908010232 Responds to 790405 Region 5 comments re Revision 4 to NPPSS-04-004, "Operational GA Program Description " Expresses intent to request util to delete Section 3.3.6 entirely HAABS.W P. Quality Assurance Branch 79/05/01 BRYAN.S.E Division of Reactor Operations Inspections ip 22501:305 24X Fiche 30-508,84/02/17.8403050288
- --B003240209 Discusses conversation w/R McKinney of ACRS re dual unit plants Time should be cut in helf HOLLOWAY. C J Diffice of Management and Program Analysis 77/01/22. Office of Management and Program Analysis ip 22501:308 24X Fiche 50-508,84/02/17,8403050288.
- --Bil0190051 Responds to B10923 FDIA B1-378 request for GA documents for WPPSB All documents re evaluation of licensee GA programs are in PDR HAABS, WP Guality Assurance Branch B1/10/05, WILGON, V. H. Management Analysis Branch 2pp 22501; 310 24X Fiche 50-508, 84/02/17, 8403050288
- --Bili020578 Concludes that util & principal contractors continue to mest criteria of 10CFR50 App B Revised GA program description acceptable for design & const of facilities HAABS, W P Quality Assurance Branch. 81/10/22, TEDESCO, R. L. Assistant Director for Licensing. 1p 22501 313, 24X Ficher 50-508,84/02/17,8403050288

- --8201300236 Forwards data for fee assessment re QA Branch review of MPPSB-QA-004, "Operational GA Program Description" HAASS, W.P. Guslity Assurance Branch 82/01/14 BERKOW, H N Management Analysis Branch 2pp 22501 314 24X Fichs 50-508,84/02/17.8403050288
- 8403050219 Forwards listing of board notifications issued sincs 820716, per 340127 inquiry re failure to provide ASLB & parties w/notifications
 DENTON, H R Offics of Nuclear Reactor Regulation, Director 84/02/28 BELL, N Coalition for Safe Power. 25pp 28700 222 24x Fiche 50-460.84/02/28,8403050219
- 8403070014 Explains why two recent board notifications rs snviron qualification of squipment not received List of all board notifications issued since 820716 docketing of Unit i sncl DENTON: HR Office of Nuclear Reactor Regulation, Director 84/02/28 BELL: N Coalition for Safe Power 25pp 22563 166 24x Fiche 50-460.84/02/28.8403070014
- 8403260071 Forwards esismology questions re HPPB-3 sits.accmptsd NRC research proposal on subduction lons undertaken by USGS & current safety evaluation of Trojan MILLER.J R Operating Reactors Branch 3 84/03/05 WITHERS,B D Portland General Electric Co 2pp 22759 300 24x Fiche 50-000.84/03/05.8403260071
- --8403260077 Forwards request for addl info re WPPS-3 site seismology, based on review of FSAR
 JACKBON, R E Geosciences Branch 89/04/28, KNIGHTON, Q W
 Licensing Branch 3 7pp 22759 302 24% Fichs 50-000, 84/03/05, 8403260071.
- 8403120199 Forwards addl info re Osneric Ltr 82-14, in response to NRC requests W/ons oversize drawing Aperture card is available in PDR.

 SORENSEN,O C Washington Public Power Supply System 84/03/07 KNIOHTON,O W Licensing Branch 3 7ipp 22585 129, 24X Fiche 50-508,84/03/07,8403120199
- D. NRC Draft/Final Environmental Statements, supple & correspondence
- 840313017B Forwards FR notice of extension of comment period for DES (NUREO-1033) to 840312.per 840430 ltr KNTOHTON, O W Licensing Branch 3 84/02/27 HIRSCH, A. Environmental Protection Agency 7pp. 22662 028 24X Fiche 50-508,84/02/27,8403150198
- --8402290440 Notice of extension of comment period for DE8 (NUREO-1033) to 840312 KNICHTON, O W Licensing Branch 3 84/02/24 ip 22662,035 24X Fiche: 50-50B, 84/02/27, 8403150198
- 8403090118 Forwards comments is DES (NUREO-1033) for consideration in preparation of FES SURENBEN,9 C Washington Public Power Supply System 84/03/05 KNIGHTON-0 W Licensing Branch 3 5pp 22576 074 24X Fiche, 50-508,84/03/05,8403090118
- 8403120174 Comments on facility DES DES accurately describes project conditions & impacts existing in original licensing considerations & svolving over initial const period FITCH.W.L. Washington, State of 84/03/06 Division of Licensing. 3pp 22589 179 24X Fiche 50-508,84/03/06.8403120174
- 8403120007 Rsqussts explanation of process by which snc1 avc list composed for NRC 840227 itr to EPA rs DES, REYNOLDS,N S Bishop, Liberman, Cook, Purcell & Reynolds REYNOLDS,N 8 Washington Public Power Supply System 84/03/07 KNIGHTON,O W Licensing Branch 3 2pp 22586 258 24X Fiche: 50-508,84/03/07,8403120007.
- 8403130180 Comments on DES for operation of facility Coverage of DES adequate & no objections raised to proposed action, BURD, R. 8. Environmental Protection Agency 84/03/07 Division of Licensing ip, 22606:128 24X Fiche: 50-508,84/03/07,8403130180
- 8403150151 Comments on facility DES Info should be segregated into generic site-specific topics & put into laymans language if essential part of format required for DES.
 LUNDELAD.D Washington, State of 84/03/08. KNIOHTON, O Licensing Branch 3. 2pp 22639:337 24X Fichs 50-508.84/03/08.8403150151
- 8403200238 Comments on DEB (NUREG-1033) Assertions re sociateonomic impacts from station operation demonstrate low Isvel of expertise among study team or refusal to consider relevant research findings on social impacts.

 FREUDENBURG, W Washington State Univ. Pullman, WA 84/03/12.

 VIETTI, A Division of Licensing 2pp 22691-111 24X

 Fichs. 50-508,84/03/12,8403200238

- 8403220178 Comments on DES re operation of facility Commistive impacts on regional water use should be more explicitly evaluated DEG adequate. but unnecessary as decisionmaking tool DEGENS.5 Affiliation Not Assigned 84/03/13 NRC No Detailed Affiliation Given 7pp 22718 044 24x Fiche 50-508,84/03/13, 8403220178
- 8403190343 Comments on DES Long-term adequacy of underdrain sys storage capacity should be descussed Evaluation of sys long-term integrity if used to retain contaminated sump water, necessary

 BLANCHARD.B Interior, Dept of 84/03/15 Division of Licensing 1p 22675 078 24X Fiche 30-308,84/03/15,8403190343
- E NRC Safsty Evaluation Report (SER), supply & correspondence
- 8403080179 Fourth partial response to FOIA request for six categoriss of documents re facilities Forwards App A documents App B document entirely withhild (ref FOIA Exemption 5) Review of addi documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche: 50-000, 84/02/13, 8403080179
- --8103040052 Forwards short & long-term OL & CP revisw schedules,in response to 801216 meeting w/USOS List of OL plant revisws for which NRC tentatively plans to sesk USOS assistancs is provided,

 JACKSON,R E Quescisnes Branch NRC-03-80-113 81/01/21
 DEVINE,JF Interior, Dept of Geological Survey 5pp
 22383 272 24X Fiche 50-000,84/02/13,8403080179
- 840326007i Forwards seismology questions re HPPS-3 site.accsptsd NRC ressarch proposal on subduction tone undertaken by USOS & current safety evaluation of Trojan MILLER.J R Operating Reactors Branch 3 84/03/05 WITHERS.B D Portland General Electric Co. 2pp 22759 300 24X Fiche 50-000.84/03/05.8403260071
- --8403260083 Forwards draft SER input re WPP8-3 site gsology & seismology Open items include possibility of large earthquake on subduction zone beneath site & possibility of unrecognized low angle thrust faults in site vicinity KNIOHT.JP Assistant Director for Comp & Btructures Enginssring (Post 830201) 83/11/01 NOVAK.T M Assistant Director for Licensing 18pp. 22759 311 24X Fiche 50-000,84/03/05,8403260071
- F Sscurity, medical, emergency & fire protection plans
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B documents natirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S 1 Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000, 84/02/13.8403080179
- --8110190026 Requests that comparison of fire protection program to App R of 10CFR50 be included in overall firs protection program submittal W/o encl FR notice EISENHUT,D Q Division of Licensing 81/09/30 FERGUSDN,R L Washington Public Power Supply System 2pp 22583 308 24X Fiche 50-000,84/02/13,8403080179
- 840301050B Advises that NRC will not delste privacy or proprietary info from emergency plans unless specifically requested by licenses.per 810709 Generic Ltr 81-27 W/o request, entire plan will be piaced in PDR KNIGHTON.O W Licensing Branch 3 84/02/14 MAZUR.D W Washington Public Power Supply 89xtem, 3pp 2243B 332 24X Fiche: 50-508,84/02/14.840301050B
- 8403130385 Forwards responses to NRC questions re security measures for physical protection of facilities using SNN Info withheld tref 100FR73 21)
 SCRENSEN.O C Washington Public Power Supply System 84/03/07 KNIGHTON.O H. Licensing Branch 3 ip 22616 091 24X Fichs 50-508.84/03/07.8403130385
- @ Adjudicatory correspondence
- B403010050 Third partial response to FDIA request for six categories of documents re facility Forwards App A documents. App A documents also placed in PDR. App B documents will be placed in PDR upon request Review continuing FELTON, J. M Division of Rules and Records 84/01/17 ANDERSON, B I Oarvey, Schubert, Admas & Barer 4pp 22446 293. 24X Fiche 50-000,84/01/17,8403010050

- --8304050592 Requests search for relevant documents re govt littigation w/util Response due by 830408 GRIMSLEV.D H 1886 No Detailed Affiliation Given 63/03/29 FITTI.C Atomic Safety and Licensing Board Panel 1p 22446 314 24X Fiche 30-000.84/01/17.8403010050
- 3403060111 Memorandum & order ruling on further suppl to petition for leave to intervene & reinstating 830421 ruling MARGULIES.M B . SHON.F J . FOSTER.R F Atomic Gafety and Licensing Board Panel 84/03/02 Coalition for Safe Power 11pp 22518 311 24X Fiche 50-508.84/03/02.8403060111
- 3403210170 Notice of appeal of ASLB 840302 memorandum & order admitting Coalition for Safe Power as intervenor Certificate of Syctenci MARTMAN.S L Washington Public Power Supply System HARTMAN.S L Bishop, Liberman. Cook, Purcell & Reynolds DSB 003 84/03/20 Atomic Safety and Licensing Board Panel 3pp 22707 338 24X Fiche 50-508.84/03/20.8403210170
- 3403210172 Brief in support of notice of appeal of ASLB 830302 memorandum & order ASLB abused discretion by reinstating order granting petitioner intervenor status ABLB 830302 memorandum & order should be vacated W/Certificate of Svc HARTMAN. S L. Washington Public Power Supply System HARTMAN. S L. Bishop. Liberman. Cool. Purcell & Reynolds DSB 002 84/03/20 Atomic Safety and Licensing Appeal Panel 23pp 22710 324 24X Fiche 50-508.84/03/20 8403210172
- 3403210189 Motion For reconsideration of memorandum & order granting petitioner intervenor status &/or for referral or certification of question of whether limitation should be placed on petitioner participation W/Certificate of Svc HARTMAN, S. L. Washington Public Power Supply System HARTMAN, S. L. Bishop, Libernan, Cook, Purceil & Reynolds DSD 001 84/03/20 Atomic Safety and Licensing Board Panel 23pp 22710 266 24% Fiche 50-508.84/03/20,8403210189
- l Inspection reports, lE Builetins & correspondence
- 14030B0179 Fourth partial response to FOIA request for six categories of documents re Faccilities Forwards App A documents App B document entirely withheld (ref FDIA Exemption 5) Review of addi documents sub) to request continuing FELTON.J H Division of Rules and Records 84/02/13 ANDERSON.S i Garvey. Schubert. Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13.8403080179
- -8106220066 Requests that appropriate comments re Cycie 2 evaluations. per Elsenhut 810604 memo, be submitted by 810623 MIRAGLIA.F J Licensing Branch 3 81/06/18 HAASS.W 6 Quality Assurance Branch 1p 22583 271 24% Fiche 50-000, 84/02/13, 8403080177
- ~81071305Bi Forwards info re impact of Mount St Heiens eruptions on facilities.for use by SALP review board Comments prepared by HE Lefevre,groiogist

 JACKSIN,R E Geosciences Branch 81/06/23 MIRAQLIA.F J
 Licensing Branch 3 2pp 22583 293 24X Fiche 50-000,84/02/13,8403080179
- --B107140:85 Forwards Ofc of Nuclear Reactor Regulation performance evaluation in compliance w/B10604 memo re systematic assessment of licensee performance Cycle 2 Notifies that review board meeting for facility scheduled for B10723 MMETLER.L Licensing Branch 3 B1/06/30 E15ENHUT.D 0 Division of Licensing ip 22583 295 24X Fiche 50-000.84/02/13, 8403080179
- --Bi07140192 Forwards Geosciences Branch input for use by facility systematic assessment of licensee performance review board, per BI061B request JACKSON.R E Geosciences Branch BI/06/23 MIRAGLIA.F J Licensing Branch 3 Jpp 22583 298 24X Fichs 50-000, 84/02/13, 8403080179
- 3401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Vaive Control Circuits & Annunciation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 8301031 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22909 239 24X Fithe 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA, Safeguards & Inspection Programs (Post E30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000,84/03/02,8402090007

- 8402090008 iE Info Natice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of Naw York, Inc 122pp 22553 078 24X Fiche 50-000,84/03/02,8402090
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list enci JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 117pp 22553 217 24X Fiche 50-000,84/03/02,8402070007
- 8402090011 IE Info Notice 84-i7, "Problems W/Liquid Nitrogen Cooling Components Delow Nil Ductility Temp " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402040011
- 8402090024 IE info Notice 84-09. Rov 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York. Inc 118pp 22639 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG.R C Director's Office Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000,84/03/12,8402090031
- 8402090043 IE Info Notico 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc iist encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York. Inc 123pp 22823 227 24X Fiche 50-000.84/03/21,8402090043
- 840209044 IE Info Notice 84-20, "Svc Life of Relays in Bafsty-Related Sys " Svc list encl JURNAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000.84/03/21,8402090044
- S Reportable occurrences, LERs & related correspondence
- B403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, 0impei NPS-4 T&T valve, to close Encl 1tr dtd 840203 sent to listed utils GE notified of affected units in BWR piants
 THERDUX,R R Terry Corp 84/02/22 WOODRUFF, R W Director's Office, Office of inspection and Enforcement 6pp 22706 327 24X Fiche 50-000, 84/02/22, 8403210032
- T Hearing transcripts on non-antitrust matters
- 8403010113 Final response to FDIA request for five categories of info re mothballed nuclear const projects Forwards App A documents Documents aiso in PDR. FELTON.J M Division of Rules and Records 84/02/10 BELL.N Nuclear Information & Resource Service 2pp 22479-182 24X Fiche 50-508.84/02/10.8403010113
- --B403010114 Partial statement of JB Martin before House Committee on Energy & Commerce re mothballing of facility. HARTIN.J B NRC - No Detailed Affiliation Given 83/09/14 9pp. 22479 186 24X Fiche 50-508,84/02/10,8403010113
- U Congressional/Executive Correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities, Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records B4/02/13 ANDERSON, 8 I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --8009110203 Responds to 800702 itr re E Borhek concern about ultimate responsibility for civil penalities proposed against util. Civil penalities are imposed as enforcement action State agencies should be contacted re responsibility for payment DIRCKS.W J Office of the Executive Director for Operations. 80/08/26 JACKBON, H M Senate 4pp 22583.260 24X Fiche 50-000,84/02/13,8403080179

- --B012160551 Forwards B00625 ltr fram constituent E Borhek for response Requests that duplicate rept be forwarded to B02 United States Courthouse, Seattle, WA 98104
 JACKBON, H M Senate, Energy & Natural Resources 80/07/2i
 KAMMERER, C C Office of Congressional Affairs 2pp 22583 264
 24X Fiche 50-000,84/02/13,8403080179
- --8101130363 Responds to ltr forwarding M Hamilton concerns re facilities CPs issued in Apr 1978 after safety & environ reviews & ABLB public hearings Public hearings may be requested when util applies for OLs KAMMERER, C Office of Congressional Affairs BO/12/16 MAGNUSON, W Senate ip 22583 271 24x Fiche 50-000, 84/02/13, pagaraghize

DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5

- A Application/construction stage documents & correspondence
- 8403010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also paced in PDR App B documents will be placed in PDR upon request Review continuing FELTON, J M Division of Rules and Records 84/0i/17 ANDERSON, S I Garvey, Schubert, Adams & Barer App 22446 273 24X Fiche. 50-000, 84/0i/17, 8403010050
- --8003240i59 Advises of refund owed licensee re CP fees for facilities based on professional manpower extended & contractual sycs costs incurred MILLER, W O License Fee Management Branch 80/03/03 MANION, W C Office of the Controller 2pp 22446 303 24X Fiche 50-000, 84/01/17, 8403010030
- --B004010752 Confirms 800229 telcon re professional manpower (152-h) provided by 800228 memo Manpower should be divided equally between two units HOLLOWAY.C J License Fee Management Branch 80/02/27 FITTI.C J Atomic Safety and Licensing Board Panel ip 22446 300 24X Fiche 50-000.84/01/17.8403010050
- ---8004010759 Confirms 800226 telcon re professional manpower (18-h) provided by A Rosenthai 781002 memo Manpower should be divided equally between two units HOLLDMAY.C J License Fee Management Brench 80/02/29 BISHOP.J Atomic Safety and Licensing Appeal Panel. ip 22446 30i 24x Fiche 50-000,84/01/17,8403010050
- --81i2210i35 Informs of B McKinney opinion that allocation of ACRS manpower for fee purposes should be divided equally for review of two units at site HOLLOHAY, C J License fee Management Branch 79/01/22 License fee Management Branch 79/01/22 License fee Management Branch 19 22446 297 24X Fiche 50-000.84/01/17, 8403010050
- --8308100483 Discusses status of OL applications Review of encl WPPSS 830712 itr requested in order to determine present status of Unit 3 for billing purposes W/o enci MILLER,W O License Fee Management Branch 83/08/05 FONNER,R L Regulations Division 2pp 22446 326 24X Fiche 50-000, 84/01/17,8403010050
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities: Forwards App A documents App B document entirely withheid (ref FOIA Exemption 5). Review of add1 documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Darvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche: 50-000, 84/02/13, 8403080179
- --8003240202 Bubmits review costs for facilities Hearing was uncontested, Billing procedure may be completed BERKOW.H N Office of Nuclear Reactor Regulation, Director 80/02/22 MILLER.W O License Fee Management Branch ip 22583: 242 24X Fiche 50-000,84/02/13,8403080179
- --8003240207 Forwards IE cost data worksheets for facilities No costs relected for licensee contractor vendor insp repts COBB, L I Executive Officer for Management & Analysis. 79/01/29 HILLER.W O License Fee Management Branch 3pp. 22583 243 24) Fiche 30-000,84/02/13,8403080179
- --B003240219 Corrects 7B1028 memo re MPPBB 3 & 5 being contested Memo reflecting actual ASLB time spent on case encl FITTI.C V Atomic Bafety and Licensing Board Panel B0/02/28 HOLLOWAY, C J License Fee Management Branch (p 22583:248 24) Fiche 50-000, B4/02/13, B403080179.

- --8003240222 Submits rept of time spent since program initiated on HPPSS 3 & 5 Professional time all spent on post-hearing work regarding CP hearing LAZO, R M Atomic Safety and Licensing Board Panel 78/04/11 FITTI.C J Atomic Safety and Licensing Board Panel 3pp 22583 249 24X Fiche 50~000,84/02/13,8403080179
- --B009090737 Forwards airworthiness alert re corrosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Questions re ash amount, chemistry & size distribution will be forwarded to licensees M/o encl JACKSON, R E Geosciences Branch 80/06/12 VOLLMER, R H Division of Engineering 2pp 22583 258 24X Fichs 50-000, 84/02/13, 8403080179
- --8104300020 Responds to 810414 memo re util request for clarification in use of ASME code cases Util use of code cases w/o prior NRC approval is inadvisable due to potential hardship for user BOSNAK,R J Mechanical Engineering Branch 81/04/21 YOUNOBLOOD. B J Licensing Branch i 1p 22983 280 24X Fiche 50-000,84/02/13,8403080J79
- --8107270274 Accepts use of ASME Code Case N-242-1 dtd 800410 for application in const of pipe support frames in pipe chases located in two lower elevations of reactor auxiliary bldg Conditions of use discussed KNIGHTJ P Assistant Director for Comp & Structures Engineering (Pre 830201) 81/07/21 TEDESCO.R L Assistant Director for Licensing ip 22583 301 24X Fiche 50-000,84/02/i3.8403080179
- --8108116038 Notification of 810820 meeting w/util in Bethes64,MD to discuss proposed independent design review programs. HERNAN.R W Licensing Branch 4 81/07/30 ADENSAM.E Q Licensing Branch 4 3pp 22583 302 24X Fiche 50-000,84/02/13. 8403080179
- --Gi10080612 Discusses proposal to use IDRs in licensing process IDRs may be useful in certain areas, but clarification of role needed TEDEGCO.R L. Assistant Director for Licensing 81/09/23 EISENHUT, D @ Division of Licensing ip 22583 307 24X Fichs 50-000,84/02/13,8403080179
- --8111200219 Informs of receipt of telcon from Yakamar Indian Nation requesting that tribe be given full rights in facilities proceedings
 TEDESCO, R. L. Assistant Director for Licensing 81/10/21
 KETCHEN, E. Hgarings Division 1p 22583 310 24X
 Fiche 50-000, 84/02/13,8403080179
- --B203180118 Forwards two relevant documents for FOIA request re MPPSS & Exxon Litigation MIRAGLIA,F J Litensing Branch 3 82/03/08 WILSON,V H Management Analysis Branch 3pp 22583 333 24x Fiche 50-000,84/02/13,8403080179
- --B204290.657 Notification of 820511 meeting w/util to discuss review process & preliminary identification of any possible unique features
 WHEELER.L Licensing Branch 3 82/04/22 MIRAQLIA.F J
 Licensing Branch 3 ip 22583 340 24X Fiche 50-000,84/02/13,8403080179
- --8303100476 Forwards util 830223 submittal in response to teicon during which remaining Phase I open items of "Control of Heavy Loads Case Reviews," were discussed W/o encl CLEMENBON: F Auxiliary Systems Branch NRC-20-18-388 83/02/28 STICKLEY: H. E960, Inc. ip 22583 340 24X Fiche 50-000.84/02/13.8403080179
- --8304060577 Requests search for documents re govt litigation w/util on five specific issues SLAGOIE.E L Office of the General Counsel 83/03/23 DIRCKS,W J Office of the Esecutive Director for Operations 19 22583 361 24X Fiche 50~000.84/02/13.8403080179
- --8403080253 Forwards summary of review costs & supporting documentation from program ofcs W/o encl HOLLOWAY: 0 J License Fee Management Branch 80/03/03 License Fee Management Branch 80/03/03 License Fee Management Branch ip 22583 241 24X Fiche 50-000,84/02/13,8403080179
- 8403030288 Fifth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App A & B documents also available in PDR Documents listed on App C & D located in Central Files & not available publicly FELTON, J. M Division of Rules and Records. 84/02/17 ANDERSON, S I Garvey, Schubert, Adams & Barer 9pp 22301 289 24X Fiche 50-509,84/02/17,8403050288

- --7908010102 Forwards 790501 Haas-Bryan memo re NRR-QAB resolution of Region 5 comments re operational QA program NOLAN-F J Division of Reactor Operations Inspections 79/05/07 CREMS-J L Region 4. Dallas, Office of the Director ip 22501 306 24% Fiche 50-509.84/02/17.840305028B
- --7908010232 Responds to 790405 Region 5 comments re Revision 4 to NPPSE-0A-004, "Operational QA Program Description "
 Expresses intent to request util to delete Section 3 3 & entirely
 HAASS: W P Quality Assurance Branch 79/05/01 BRYAN, 8 E
 Division of Regiotor Operations Inspections ip 22501 305 2-
- --8003240209 Discusses conversation w/R McKinney of ACRS re dual unit plants Time should be cut in half HOLLOWAY.C J Office of Management and Program Analysis 79/01/22 Office of Management and Program Analysis 1p 22501 308 24X Ficho 50-500.84/02/17.8403050288
- --8110190051 Responds to 810923 FUIA 81-378 request for QA documents for WPRSS All documents re evaluation of licenses QA programs are in PDR
 HAASS:W P Quality Assurance Branch 81/10/05 WILSON:V H
 Management Analysis Branch 2pp 22501 310 24X
 Fichs 50-508.84/02/17.8403090288
- ~-Bii1020378 Concludes that util & principal contractors continus to meet criteria of iOCFR30 App B Revised GA program description acceptable for design & const of facilities HAABS,W P Quality Assurance Branch 81/10/22 TEDESCO,R L Assistant Director for Licensing 1p 22501 313 24X Fiche 50-308,84/02/17,8403050288
- --8201300236 Forwards data for fee assessment rp QA Branch review of WPPS8-GA-004, "Operational QA Program Description "HAASS,W P Quality Assurance Branch 82/01/14 BERKOW.H N Management Analysis Branch 2pp 2250t 314 24% Fiche 50-508,84/02/17.8403050288
- 8403:20199 Forwards add1 info re Generic Ltr 82-14, in response to NRC requests W/one oversize drawing Aperture card is available in PDR SORENSEN. G C Washington Public Power Supply System 84/03/07 KNIGHTCN. G W Licensing Branch 3 7ipp 22585 129 24X Fiche 50-508.84/03/07.8403120199
- 8403260221 Advises that Phase II of termination program in progress re locating new owners for facility & will last until at least June 1985 SOREMSEN.G C Washington Public Power Supply System 84/03/13 DIRCKS,W J Office of the Executive Director for Operations ip 22751 032 24X Fiche 50-509,84/03/13,8403260221
- F Security, medical, emergency & fire protection plans
- 8403080177 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addi documents suby to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adems & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13.8403080179
- --8110190026 Requests that comparison of fire protection program to App R of 10CFR50 be included in overall fire protection program submittal W/o encl FR notice EISENHUT.D Q Division of Licensing Gi/09/30, FEROUSON,R L Washington Public Power Supply System 2pp 22583 308 24X Fiche 50-000,84/02/13,8403080179

G Adjudicatory correspondence

- 840:301:0050 Third partial response to FOJA request for six categories of documents re facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in FDR upon request Review continuing FELTON, J M Division of Rules and Records 84/01/17 ANDERSON, S I Garvey, Schubert, Adams & Barer 4pp. 22446 293 24X Fiche. 50-000, 84/01/17, 840:3010050
- --B305090506 Requests advice re fee assessment cutoff date for reactor CP & OL applications that are withdrawn denied suspended, cancelled or postponed MILLER.W O License Fee Management Branch 83/05/04 FONNER,R L Office of the Executive Legal Director 3pp 22446 315 24X Fiche 50-000.84/01/17.8403010050

Q Inspection reports: IE Bulletins & correspondence

- 8403080179 Fourth partial response to FDIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FDIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, B, I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --BIO6220066 Requests that appropriate comments re Cycle 2 evaluations, per Eisenhut 810604 memorbe submitted by BIO623 MIRAGLIA.F J Licensing Branch 3 81/06/18 HAASB.W 8 Quality Assurance Branch 1p 22583 291 24X Fiche 50-000, B4/02/13, B403080179
- --Bi071303Bi Forwards info re impact of Mount Bt Helens eruptions on facilities, for use by BALP review board, Comments prepared by HE Lefevre.geologist JACKSON,R E Geosciencee Branch. Bi/06/23 MIRAGLIA,F J Licensing Branch 3 2pp 22583 293 24X Fiche.50-000,84/02/13,8403080179
- ---Bi07140183 Forwards Dfc of Nuclear Reactor Regulation performance evaluation in compilance w/Bi0604 memo re systematic assessment of licensee performance Cycle 2 Notifies that review board meeting for facility scheduled for Bi0723.

 WHEELER,L Licensing Branch 3 Bi/06/30 EISENHUT,D Q. Division of Licensing 1p 22583 275 24X Fiche. 50-000, 84/02/13, 8807989179
- --8107i40192 Forwards Geosciences Branch input for use by facility systematic assessment of licenses performance review board, per 610618 request.

 JACKSON.R E Geosciences Branch 8i/06/23 MIRAGLIA.F J, Licensing Branch 3 3pp 22583.298 24% Fiche 50-000,84/02/i3,8403080179
- 8 Reportable occurrences, LERs & related correspondence
- 8403210032 Part 2: rept re failure of auxiliary feedwater pump drive turbines, Oimpel NPB-4 T&T valve; to close Encl 1tr det 840203 sent to listed utils GE notified of affected unite in BMR plants
 THEROUX.R R Terry Corp 84/02/22 WOODRUFF, R.W Director's Office, Office of Inspection and Enforcement 6pp 22706'327. 24X Fiche. SO-000, 84/02/22, 8403210032

U Congressional/Executive Correspondence

- B403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B documents entirely withheld (ref FOIA Exemption 5) Review of addi documents subj to request continuing FELTON.J M Division of Rules and Records B4/02/13 ANDERSON.S I Garvey, Schubent, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13.8403080179
- --B009110203 Responds to B00702 itr re E Borhek concern about ultimate responsibility for civil penalities proposed against util Civil penalities are imposed as enforcement action State agencies should be contacted re responsibility for payment, pIRCKG, N J Office of the Executive Director for Operations, 80/09/26 JACKEON. HM Benate 4pp 22583 260 24% fiche 50-000,84/02/13,8403080179.
- ---B012160551 Forwards 800625 itr from constituent E Borbek for response Requests that dupiticate rept be Porwarded to 802 United States Courthouse. Beattle. MA 78104.

 JACKSON, H M Senate. Energy & Natural Resources B0/07/21 MAMBERER, C Office of Congressional Affairs. 2pp. 22583; 264 24X Fiche 50-000.84/02/13,8403080179
- --Bi0ii30363 Responds to 1tr forwarding M Hamilton concerns refacilities CPs issued in Apr 1978 after safety & environ reviews & ABLB public hearings Public hearings may be requested when util applies for OLs.

 KAMMERER, C Office of Congressional Affairs B0/12/16 MAONUSON. W Benate ip 22583 271 24X Fiche, 50-000, 84/02/13, 8403080179

DOCKET 50-513 WPPSS NUCLEAR PROJECT, UNIT 4

- A Application/construction stage documents & correspondence
- 840:3010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also placed in PDR App B decuments will be placed in PDR upon request Review continuing FELTON. J M Division of Rules and Records 84/01/17 ANDERSON. S I Garvey, Schubert, Adams & Barer 4pp 22446 293 24X Fiche 50-000.84/01/17.8403010050
- --8302250083 Responds to questions re application termination Notice of termination/withdrawal not anticipated No time limitation placed on completion of Phase One review ADENSAM, E O Licensing Branch 4 83/02/17 MILLER, W O License Fee Management Branch ip 22446 321 24X Fiche 50-000,84/01/17,8403010050
- --8308100483 Discusses status of OL applications Review of sucl WPP68 B30712 ltr requested in order to determine present status of Unit 3 for billing purposes. W/o enc! MILLER, W O License Fee Management Branch 83/08/05 FONNER, R L Regulations Division 2pp 22446 326 24X Fichs 50-000, 84/01/17,8403010050
- B403080179 Fourth partial response to FOIA request for mix catagories of documents re facilities Forwards App A documents App B documents withheld (ref FOIA Exemption 5) Review of addi documents subj to request continuing.

 FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, 8 J Garvey, Schubert, Adams & Barer. 7pp 22583 226 24X

 Fiche. 50-000. 84/02/13. 8403080179
- --B001140316 Notifies that NRC has amended regulations re implementation of resident inseprogram Expresses gratitude for assistance rendered Forwards final rule W/o enci
 BTELLO, V Office of Inspection & Enforcement, Office of the Dirsctor 79/11/19 O'STRANDAN Washington Public Power Supply Bystem, ip 22583 234 24X Fiche 50-000,84/02/13.8403080179
- --80070737 Forwards airworthiness alert re corrosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Guestions re ash amount-chemistry & size distribution will be forwarded to licensees W/o encl JACKBON, R E Geosciences Branch 80/06/12 VOLLMER, R H Division of Engineering 2pp. 22583 258 24X Fiche 50-000,84/02/13,8403080179
- --B010090260 Discusses review of applicant 800814 request for approval of proposal to substitute in-plant tests w/scale model recirculation sump tests Response to requests deferred panding NRC review of program 8PEIS.T Reactor Systems Branch 80/09/26 YUUNOBLOOD. U J Licensing Branch 1 ip 22583 266 24% Fiche 50-000.84/02/13, 8403080179
- --8104220327 Concludes that Table 3,2-2 of PBAR, re safety-related structures, sys & components, is incomplete from Geotechnical Engineering Branch viewpoint LEAR.O E Hydrologic & Geotechnical Engineering Branch 81/04/08 HAABS, W P Guality Assurance Branch 2pp 22583: 278 24% Fiche 50-000,84/02/13,8403080179
- --B104300020 Responds to B10414 memo re util request for clarification in use of ASME code cases Util use of code cases w/o prior NRC approval is inadvisable due to potential hardship for user BOSNAK.R J Mechanical Engineering Branch E1/04/21 YOUNGBLOOD,B J Licensing Branch i p 2288 280 24X Fiche 50-000,84/02/13,8403080179
- ---8105010554 Advises that Mechanical Engineering Branch completed review of util request for authorization to use ABME Code Cases N-217 & N-287 for application in design of concrete containments Code cases acceptable
 KNIGHT.J.P. Assistant Director for Comp & Structures Engineering (Pre B30201) 81/04/29. TEDESCO.R L. Assistant Director for Licensing 1p 22583 281 24X Fiche 50-000.84/02/13,8403080179
- --8105140106 Advises that info provided on 810213 & 0403 re air intake arrangements for diesel generators reviewed Diesel generator combustion air supply arrangement meets acceptance criteria in Bection II of SRP a 5 8 Sys acceptable as designed.
 UNDARO, A R Power Systems Branch 81/05/01 YOUNGELDUD, B J Licensing Branch 1 ip 22583:282. 24X Fichs.50-000,84/02/13,8403080179
- --8105180436 Forwards ltr from util requesting concurrence by NRC to omit Subsections 2 5 1-2.5 3 of FSAR.Review & comments requested by B10682 ADENBAM,E.O. Assistant Director for Licensing 81/05/12, JACKSON.R.E. Opostiences Branch. ip 22583 283 24X Fiche.50-000,84/02/13,8403080179

- --8105210109 Concurs w/licensee proposal to ref Sections 2 5 1-2 5 1-2 5 3 of MPPS-2 FSAR in MPPS-1/4 FSAR since both projects located in clase proximity Mods listed JACKSDN.R E Geosciences Branch 81/05/15 ADENSAM.E 0 Licensing Branch 4 2pp 22583 284 24% Fiche 50-000,84/02/13,8403080179
- --B107280171 Notification of B10729 meeting w/util & ILW in Bethesda.HD to discuss mothod otil intends to use to fulfill requirments of NUREG-0737 Item II F 2 (inadequate core cooling instrumentation)
 HERNAN.R W Licensing Branch 4 81/07/21 ADENSAM, E G Licensing Branch 4 2pp 22583 305 24X Fiche 50-000.84/02/13.8403080179
- --Bi0Bi10038 Notification of Bi0B20 meeting w/util in Bethesda.MD to discuss proposed independent design review programs HERNAN.R W Licensing Branch 4 Bi/07/30 ADENSAM.E O Licensing Branch 4 3pp 22583 302 24X Fiche 50-000.84/02/13. 8403080179
- --8110080612 Discusses proposal to use IDRs in licensing process IDRs may be useful in certain areas, but clarification of role needed TEDESCO.R L Assistant Director for Licensing 81/09/23 EIEENHUT, D Q Division of Licensing ip 22583 307 24X Fiche 50-000.84/02/13.8403080179
- --Bill060697 Notifies of util intention of sending technical team to present FBAR to review staff during wk of Bill30 Reviewers should complete attached form & confirm attendance HERNANAR W Licensing Branch 4 Bi/10/23 Licensing Branch 4 App 22583 3i1 24X Fiche 50-000,84/02/13,8403080179
- --Billi30007 Submits names of D Gupa & G Stalley as technical reviewers for facility FSAR per Bil023 memo LEAR.O Hydrologic & Geotechnical Engineering Branch Bi/10/30 ADENSAM.E Licensing Branch 4 Ip 22583 315 24X Fiche 50-000,84/02/13,8403080179
- --8111200219 Informs of receipt of telcon from Yakamar Indian Nation requesting that tribe be given full rights in facilities proceedings
 TEDESCO.R t. As≤istant Director for Licensing 81/10/21
 KETCHEN.E Hearings Division ip 22583 310 24X
 Fichs 50-000,84/02/13,8403080179
- --Bi12300305 Notification of 811211 meeting w/util in Bethesda,MD to discuss FSAR w/technical review staff at time OL application is tendered HERNAN,R W Licensing Branch 4 81/11/23 ADEMSAM,E 0 Licensing Branch 4 3pp 22583 318 24X Fiche 50-000,84/02/13-8403080179
- --B2120703BR Ack receipt of 821109 ltr re Target Rock environ qualification testing program Info ro valve upgrade & retest anticipated.

 HEISHMAN.R F Division of Reactor Programs (Pre 830103)
 B2/12/01 BOUCHEY.G D Washington Public Power Supply System 1p. 22583 357 24X Fiche 30-000.84/02/13.8403080179
- --8304060377 Requests search for documents re govt litigation w/util on five specific issues
 SLAGOIE.E L Office of the General Counsel 83/03/23
 DIRCKS.H J Office of the Executive Director for Operations ip
 22583 361 24X Fiche 50-000.84/02/13.8403080179
- 840305028B Fifth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App A & B documents also available in PDR Documents listed on App C & D located in Central Files & not available publicly FELTON. J M Division of Rules and Records 84/02/17 ANDERSON. 8 I Qarvey, Schubent, Adams & Barer Ppp 22501 289 24X Fiche. 50-509, 84/02/17, 8403050288
- --7908010232 Responds to 790405 Region 5 comments re Revision 4 to NPPSS-0A-004, "Operational GA Program Description "Expresses Intent to request util to delete Section 3 3 6 entirely HAASS,WP Quality Assurance Branch 79/05/01 ERYAN, 8 E Division of Reactor Operations Inspections ig 22501 305 24X Fiche 50-513,84/02/17,8403050288
- --8110170031 Responds to 810723 FOIA 81-378 request for GA documents for WPPS3 All documents re evaluation of licensee GA programs are in FDR HAABB.W P Gualtty Assurance Branch 81/10/05 WILBON,V H Management Analysis Granch 2pp 22501 310 24X Fiche 50-513,84/02/17.8403050288

- --8i10210316 Informs of receipt of Bouchey/Adensom 810722 ltr containing util current GA program description for design & const of facilities GA program description acceptable HAASS, H P Quality Assurance Branch 81/10/14 TEDESCO, R L Assistant Director for Licensing ip 22501 312 24X Fiche 30-460, 84/02/17, 8403050288
- --8201300236 Forwards data for fee assessment re QA Branch review of WPPSS-GA-004. "Operational QA Program Description " HAASS.W P Guality Assurance Branch 82/01/14 GERKOW,# N Hanagement Analysis Branch 2pp 22501 314 24X Fiche 50-513.84/02/17.8403050288
- 8403260221 Advises that Phase II of termination program in progress rollocating new owners for facility & will last until at least June 1985
 SOREMEIN.G C Washington Public Power Supply System 84/03/13
 DIRCKS.W J Office of the Executive Director for Operations ip 22751 032 24X Fichs 50-509.84/03/13.8403260221
- C Utility Environmental Report (ER), amends & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13,8403080179
- --820226017i Requests assistance in performing acceptance review of environ rept for OL application Only portions applicable to Unit I need be considered since Unit 4 cancelled on 820122 ADENSAME 0 Licensing Branch 4 92/02/10 JACKSON,R E Ordesciences Branch 1p 22583 324 24X Fiche 50-000,84/02/13,840380179
- --820315002B Forwards addi info requirements for review of ER for DL application per 820210 request
 BALLARD.R L Environmental Engineering Branch 82/03/02
 ADENSAM.E G Licensing Branch 4 3pp 22583 3R9 24X
 Fiche 50-000,84/02/13.8403080179
- --8203180004 Advises that environ rept is acceptable re radialogical impacts
 HOUSTON, R W Assistant Director for Radiation Protection
 B2/03/02 TEOESCO.R L Assistant Director for Licensing 1p
 22583 332 24X Fiche 50-000.84/02/13.840308017
- --8204090099 Informs that sufficient info provided to begin meteorology review inappropriate models & diffusion parameters used in Section & I 3 2 & accident evaluations HULMAN, C. Q. Accident Evaluation Branch 82/03/16 ADENSAM, E. Licensing Dranch 4 2pp 22583 336 24x Fiche 50-000, 84/02/13, 8403080179
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/19 ANDERSON, S 1 Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/19.8403080179
- --8003250477 Forwards hydrologic engineering questions re proposed waste treatment sys Response will supply necessary info re design basis for seepage & flooding Also forwards generic questions re floodplains Info will assist NRC environ review SELLS.D E Environmental Projects Branch 2 80/03/07 RENBERGER, Dt. Washington Public Power Supply System 5pp 22583-253 24X Fiche 50-000,84/02/13,8403080177
- --B003270142 Discusses suspension of facility preoperational aquatic menitoring program Suspension approved Operational menitoring program results should not be affected by suspension SAHNORTHER B. Environmental Specialists Branch B0/02/29 SELLES DE Environmental Projects Branch 2 2pp 22583 239 24X Fiche-50-000.84/02/13.8403080179
- NRC Safety Evaluation Report (BER), suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document antirely withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubent, Adams & Baper 7pp 22583 226 24X Fichs. 50-000, 85/02/13, 8403080179

- --8103040052 Forwards short % long-term OL & CP review schedules, in response to 801216 meeting w/V865 List of OL plant reviews for which NRC tentatively plans to seek U805 essistance is provided JACKSON, R E Geosciences Branch NRC-03-80-113 81/01/21 DEVINC. J F Interior, Dept of, Geological Survey 3pp 22583 272 24X Fiche 50-000,84/02/13,8403080179
- --Biii120935 Forwards form which identifies Power Sys Branch electrical & methanical reviewers for project in accordance w/Gij023 memo Requests established review schedule dates when available UNCARO. A Power Systems Branch Bii1/02 HERNAN, R W Licensing Branch 4 2pp 22583 316 24X Fiche 30-000,84/02/13,8403080179
- F Security, medical, emergency & fire protection plans
- 8403080179 Fourth partial response to FUIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FUIA Exemption 5) Review of add1 documents sub) to request continuing FELYON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000, 84/02/13, 8403080179
- --8201190297 Forwards Central Files version of "Description of Early Narning Sus for HPPSS Nuclear Plants 1,2 & 4," in response to NRC 810720 1tr re prompt notification in event of emergency Sus will be in place prior to OL issuance BOUCHEV, G D Hashington Public Power Supply System 82/01/11 TEDESCO, R L Assistant Director for Licensing 1p 22583 321 24X Fiche 50-000,84/02/13.8403080179
- --8202180455 Requests that Fire Protection Section perform acceptance level review of facilities' revised fire protection program prior to docketing of OL application Util aware that App R to 10CFR50 will apply ADEMBAM.E G Licensing Branch 4 82/01/27 BENARGYA.V Chemical Engineering Branch ip 22583 322 24X Fiche 50-000,84/02/13,8403080179
- --8203070088 Forwards list of sys to be added to Q-list 8ys provides angoing knowledge of changes in radiation environ & ability to deal effectively w/unusually high radiation & radioactivity levels CONGEL.F J Radioiglical Assessment Branch 82/03/23 HAASS,W P Quality Assurance Branch 2Pp 22583 338 24X Ficho 50-000,84/02/13,8403080179
- --8208120240 Forwards Central Files version of revised page to Revision 2 of emergency plan adding local fire depts within 20 miles of facility to backup fire protection svcs BOUCHEY, O D Hashington Public Power Supply System 82/08/05 SCHWENCER, A Licensing Branch 2 2pp 22583 348 24X Fiche 50-000,84/02/13,8403080179
- --8208120248 Central Files version of revised page to Revision 2 of emergency plan re provision of backup fire protection svcs + Washington Public Power Supply Bystem 82/08/05 ip 22583 350 24X Fiche 50-000,84/02/13.8403080179
- --8203020137 Advises that listed info needed to perform acceptance re/iew of fire protection program for conformance w/NUREO-0800.

 Spection 9 5-1

 BENARUYA.V Chemical Engineering Branch 82/02/09 ADENSAM.E 0

 Licensing Branch 4 ip 22593 323 24% Fiche 50-000.84/02/13.
 8403080179
- 8403050288 Fifth partial response to FDIA request for six categories of documents re facilities Forwards App A documents App A & B documents also available in PRP Documents listed on App C & D located in Central Files & not available publicly FELTON.J M Division of Rules and Records 84/02/17, ANDERSON.B I Garyey, Schubert, Adams & Barer 9pp 22501 289 24X Fichø 50-513,84/02/17.8403050288
- --7906190142 Approves GA fire protection program description & related commitments HAASS,WP Quality Assurance Branch 79/05/10 PARR,O D Light Water Reactors Branch 3 ip 22501 309 24X Fiche 50-460,84/02/17,8403050288
- G Adjudicatory correspondence
- 8403010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in PDR upon request Review continuing FELTON.J M Division of Rules and Records 84/01/17 ANDERSON,8 1 Caryey, Schubert, Adams & Barer 4pp 22446 273 24X Fiche 50-000,84/01/17.8403010050

- --8304060552 Requests search for relevant documents re govt litigation w/util Response due by 830408

 ORIMSLEY,D H NRC No Detailed Affiliation Given 83/03/29

 FITTI.C Atomic Safety and Licensing Board Panel 1p 22446 314

 24X Fiche 50-000,84/01/17,8403010050
- --8303090906 Requests advice re fee assessment cutoff date for reactor CP & OL applications that are withdrawn, denied, suspended, cancelled or postponed
 MILLER, W O License Fee Management Branch 83/03/04 FONNER, R L
 Office of the Executive Legal Director 3pp 22446 315 24X
 Fiche 50-000,84/01/17,8403010050

Q Inspection reports, IE Bulletins & correspondence

- 840308D179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTONJ M Division of Rules and Records 84/02/13 ANDERSON, 9 J Carvey, Schubert, Adams & Berer 7pp 22583 226 24X Fichs 50-000,84/02/13.8403080179
- --8209280165 Forwards Cycle 3 systematic appraisal of licensee performance input for 810701 through 820730 in response to Region 5 820625 request berong mpt evident Resolution of technical issues: responsiveness & staffing satisfactory. HERNAN: R W Licensing Branch 4 82/09/15 EISENTUT.D Q Division of Licensing App. 22583 391 24X Fiche 50-000, 84/02/13,8403080179

B. Raportable occurrences: LERs & related correspondence

- B40301045i Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delayal, Inc DERCKB.W J Office of the Executive Director for Operations BECY-83-034, 84/01/25 4pp 22438,347 24X Fiche 50-000,84/01/25,840301045i
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S 1 Garvey, Schubert, Adams & Bare 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --8203100419 Discusses Part Ri rept re UE&C design of structural steel at facility Generic implications appear to be nonexistent since no similar design concept used at other facilities Two oversite drawings encl Aperture cards in Central Files SHEWMAKER, R E. Division of Engineering & Quality Assurance (Pre 830103) 82/02/24 DRDMERICK, A W Division of Engineering & Quality Assurance (Pre 830103) 2pp 22583 325 24X Fiche 30-000, 84/02/13, 8403080179
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Ginpel NPB-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BWR plants
 THERDUX.R R Yerry Corp. 84/02/22 WODDRUFF, R W Director's Office. Office of Inspection and Enforcement 6pp 22706 327 24X Fiche 30-000, 84/02/22,8403210032
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV,500-750 MVA.5 kV 350-3.000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772-114 24X Fiche 50-000.84/03/19.8403270219

U. Congressional/Executive Correspondence

- 8403080177 Fourth partial response to FDIA request for six categories of documents re facilities Forwards App A documents App B document antirely withheld (ref FOIA Exemption 5) Review of add1 documents sub, to request continuing FELTON, J M. Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Baper. 7pp 22583 226 24X Fiche: 50-000, 84/02/13, 8403080179.
- --B007110203 Responds to 800702 ltr re E Borhek concern about ultimate responsibility for civil penalities proposed against util, Civil penalities are imposed as enforcement action State agencies should be contacted re responsibility for payment DIRCKS, W J. Office of the Executive Director for Operations. B0/08/26. JACKSON.H M. Senate 4pp 22383-260 24X Fiche. 30-000, 84/02/13, 8403080179

- ~-8012160351 Forwards 800625 ltr from constituent E Borhek for response Requests that duplicate rept be forwarded to 802 United States Courthouse. Seattle. MA 98104 JACKSON.H M Senate. Energy & Natural Resources 80/07/21 KATHMERER.C C Office of Congressional Affairs 2pp 22383 264 24X Ficho 50-000.84/02/13.8403080179
- DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheid (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERSON, 9 I Oarvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000, 84/02/13, 8403080179
- --8009090737 Forwards airworthiness alert re corrosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Owestions re ash amount chemistry & size distribution will be forwarded to licensees Mya encl JACKBON.R E Geosciences Branch 80/06/12 VOLLMER.R H Division of Engineering 2pp 22583 258 24X Fiche 50-000,84/02/13,8403080179
- --Bi02200029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications, per Dfc of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by 810601 EIBENHUT.D G Division of Licensing 80/12/31 VOLLMER, R Division of Engineering ip 22983 277 24X Fiche 50-000,84/02/13,8403080179
- E NRC Bafety Evaluation Report (SER), supply & correspondence
- 840308017? Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 9) Review of add1 documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERSON. S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fichs 50-000.84/02/13,8403080179
- ~~Bi03040052 Forwards Short & long-term OL & CP review schedules,in response to 801216 meeting w/USGS List of OL plant reviews for which NRC tentatively plans to seek USGS assistance is provided JACKSON.R E Geosciences Branch NRC-03-80-113 Bi/O1/21 DEVINE.J F Interior. Dept of, Geological Survey 5pp 22583 272 24X Fiche 50-000,84/02/13,8403080179

DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of dacuments re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addi documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Carvey, Schubert, Adams & Barer 7pp 22363 226 24X Fiche 50-000, 84/02/13, 8403080179
- --8009090737 Forwards airworthiness alert re corrosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Questions re ash amount, chemistry & size distribution will be forwarded to licensees, W/o encl JACKSQN, E. Geosciences Branch 80/06/12 VOLLMER, R. H Division of Engineering 2pp 22583 258 24X Fiche 50-000, 84/02/13, 8403080179
- --8102200029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications per Ofc of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by 810201 EISENHUT.D Q Division of Licensing 80/12/31 VOLLMER, R Division of Engineering 1p. 22583 277 24X Fiche 50-000.84/02/13.8403080179
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents sub; to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, 8 1 Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179

--8103040052 Forwards short & long-term CL & CP review schedules, in response to 801216 meeting w/USQS List of DL plant reviews for which NRC tentatively plans to seek USQS assistance is provided JACKSUM.R E Geosciences Branch NRC-03-80-113 81/01/2i DEVINE.J F Interior, Dept of Geological Survey 3pp 22883 272 24X Fichs 50-000,84/02/13.8403080179

DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT &

- 5 Reportable occurrences. LERs & related correspondence
- 840301045i Informs Commission of problems w/emergency diesei generators mfg by Transamerica Delaval.Inc
 DIRCKS.W J Dffice of the Executive Director for Operations
 SECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000.84/01/25.
- 8403;20103 First interim deficiency rept re loose drive hubs on overspeed governor drive shaft on Transamerica Delavai, Inc diesels initially reported on 840203 Svc info memo being reviewed for approval Also reportable per Part 21 MILLSIL M Tennesses Valley Authority 84/03/01 O'REILLY, J P Region 2, Office of Director 2pp 22385 229 24X Fiche 50-000.84/03/01.8403120105
- 8403230028 Followup Part 21 rept re nuclear valve/actuator stroking time possibly lengthened beyond i5 s when using hydrocarbon-based lubricants Ltrs to affected utils encl WILSON-A K Henry Pratt Co 84/03/08 KEPPLER. J O Region 3. Office of Director App 22730 30A 24X Fiche 50-000.84/03/08, 8403230028
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV.500-750 MVA.5 kV 350-3.000 & all HKV circuit breakers initially reported on 930223 Addenda to installation & maint procedures sent to affected units DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co . Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24X Fiche 50-000.84/03/19.8403270219

DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

9 Adjudicatory correspondence

- 8403090060 Advises that time for Commission to review ALAB-760 expired Commission declined review Decision became final agency action on 840307 CHILK.S J Office of the Secretary of the Commission 84/03/08 Abomic Safety and Licensing Appeal Panel 1p 22576 050 24X Fiche 50-519,84/03/08.8403090060
- S Reportable occurrences, LERs & related correspondence
- 8403310451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval.inc
 DIRCKS.W J Office of the Executive Director for Operations
 SECY-83-034 B4/01/25 4pp 22438 347 24X Fiche 50-000, 84/01/25.
 B403010451
- 8403120105 First interim deficiency rept re loose drive hubs on overspeed governor drive shaft on Transamerica Delaval, Inc diesels Initially reported on 840203 Svc info memo being reviewed for approval Also reportable per Part 21.
 MILLS.L M Tennessee Vailey Authority 84/03/01 0'REILLY, J P Region 2. Office of Director 2pp 22585 229 24X Fiche 50-000.84/03/01.8403120105
- 840323002B Followup Part 2: rept re nuclear valve/actuator stroking time possibly lengthened beyond 15 s when using hydrocarbon-based lubricants Ltrs to affected utils encl MILSON, A K. Henry Pratt Co. 84/03/08 KEPPLER, J.O. Region 3, 0ffice of Director Opp. 22730 306 24% Fiche 50-000, 84/03/08, 840323002B
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 3 kV-15 kV.500-750 MVA.3 kV 350-3.000 & all fMV circuit dreakers Initially reported on B30223 Addenda to installation & maint procedures sent to affected units DUVALL.D D Brown Boveri Corp (aubs of Brown Boveri & Co., Ltd.) 84/03/19 Record Services Branch (Document Control Dest) 5pp 22772 114 24X Fiche 50-000, 84/03/19.8403270219

- DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3
- g Reportable occurrences, LERs & related correspondence
- 84030i045i Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval, Inc DIRCKS,W J Office of the Executive Director for Operations SECY-83-034 84/01/25 App 22438 347 24X Fiche 50-000, 84/01/25, 84/30i045i
- 8403230028 Foilowsp Part 21 rapt re nuclear vaive/actuator stroking time possibly lengthened beyond i3 s when using hydrocarbon-based lubricants Ltrs to affected utils enci WILSON, A K Henry Pratt Co 84/03/08 KEPPLERJ & Region 3, Office of Director App 22730 306 24X Fiche 50-000,84/03/08,880323028
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV,500-750 MVA.5 kV 350-3.000 & ail HkV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co . Ltd } 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24X Fiche 50-000.84/03/19.8403270219

DOCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

- O Adjudicatory correspondence
- B403090060 Advises that time for Commission to review ALAB-760 expired Commission declined review Decision became finel agency ection on 840307 CHILK-8 J Office of the Secretary of the Commission B4/03/08 Atomic Safety and Licensing Appeal Penel ip 22576 090 24X Fiche 30-517, 84/03/08, 8403090060
- 5 Reportable occurrences. LERs & related correspondence
- B403010491 Informs Commission of problems w/emergency dissal generators mfg by Transamerica Delaval.lnc
 DIRCKS, W J Office of the Executive Director for Operations
 SECY-03-034 B4/01/25 4pp 2243B 347 24X Fiche 50-000,84/01/25,86.03010451
- 8403230028 Followup Part 21 rept re nuclear valve/actuator stroking time possibly lengthened beyond 15 s when using hydrotarbon-based lubricants Ltrs to affected utils encl MILBON, A K Henry Pratt Co 84/03/08 KEPPLER, J G Region 3, Office of Director 6pp 22730 306 24X Fiche 50-000,84/03/08.8403230028
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV,500-750 MVA.5 kV 350-3,000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL.D D Brown Boveri Corp (subs of Drown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24X Fiche 50-000.84/03/19.8403270219

DOCKET 50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

- A Application/construction stage documents & correspondence
- 8403080179 Fourth pertial response to FOIA request for six catagories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 3) Review of addl documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON.8 I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13.8403080179.
- --B009090737 Forwards airworthiness alert re corrosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Questions re ash amount, chemistry & size distribution will be forwarded to licensees W/o encl JACKSON, R E Geosciences Branch 80/06/12 VOLLMER, R H Division of Engineering 2pp 22583 258 24X Fiche. 30-000, 84/02/13, 8403080179
- --8:02200027 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications.per Ofc of Nuclear Reactor Regulation approach to resymption of licensing Safety evaluation inputs should be previded by 8:060: EISENHUT, D. G. Division of Licensing 60/12/31 VQLLMER, R Division of Engineering 1p. 22563 277 24X Fiche 50-000, 84/02/13, 8403080179

- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B documents not return the folia Exemption 3) Review of addl documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERSON, S I Darvey, Schubert, Adama & Barer 7pp 22583 224 24X Fiche 30-000,84/02/13,8403080179
- --B103040052 Forwards short & long-term OL & CP review schedules, in response to 801216 meeting w/USOS List of OL plant reviews for which NRC tentatively plans to seek USOS assistance is provided JACKBON.R E Geosciences Branch NRC-03-B0-113 B1/01/21 DEVINE, J F Interior, Dept of, Geological Survey 5pp 225B3 272 24X Fiche 50-000,84/02/13,8403080179
- Q Inspection reports: IE Bulletins & correspondence
- B401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000.84/02/28,8401170072
- 8402090007 IE Info Notice 84-14, "Highlights of Rocent Transport Regulatory Revs by DOT & NRC " Svc list enci GRACE.J N Division of QA, Safeguards & Inspection Programs (Post 630103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02,8402090007
- 8402090000 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list enc!
 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York: Inc. 122pp 22553 098 24X Ficho 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-i5. "Reporting of Radiological Releases "
 Svc list enci
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22353 217 24X Fiche 30-000,84/03/02,8402090009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Caoling Components Below Nil Ductility Temp " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidate Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05,8402070011
- B402090024 IE Info Notice 84-09.Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fichs 50-000.84/03/07,8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys." Svc list enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22384 186 24X Fiche 50-000.84/03/07, 8402070028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Bys " Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823 074 24X Fiche 50-000.84/03/12.8402070031
- B402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp, 22823 229, 24X Fichs 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl Sys " Svc list encl JORDANA E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc 135pp. 22933 001, 24X Fiche. 50-000.84/03/21, 8402090044

- DOCKET 50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22593 226 24X Fiche 50-000.84/02/13.8403080179
- --8007090737 Forwards airworthiness alert re corrosive & abrasive characteristics of volcanic ash which has failen in Pacific Northwest Questions re ash amount chemistry & size distribution will be forwarded to licensees M/o encl JACKSON.R E Geosciences Branch 80/06/12 VOLLMER.R H Division of Engineering 2pp 22583 258 24X Fichs 50-000.84/02/13,8403080179
- ~8102200029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications.per Ofc of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by #10601 EISENHUT.D 0 Division of Licensing 80/12/31 VOLLMER.R Division of Engineering 1p 22583 277 24X Fiche 50-000.84/02/13.8403080179
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addi documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON S I Garvey, Schubert, Adams & Barce 7pp 22583 224 24X Fiche 30-000.84/02/13,8403080179
- --8103040052 Forwards short & long-term OL & CP review schedules, in response to 801216 meeting w/USGS List of OL plant reviews for which NRC tentatively plans to seek USOS assistance is provided JACKSON, R & Obosciences Branch NRC-03-80-113 81/01/21 DEVINE, J F Interior, Dept of Geological Survey 5pp 22583 272 24X Fiche 50-000,84/02/13-8403080179
- O Inspection reports. IE Builetins & correspondence
- B401190072 IE info Notice B4-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svt list encl UDRDAN, E L. Division of Emergency Preparedness & Emgineering Response (Post 830103) B4/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000, B4/02/28, B40119007?
- 8402070007 IE info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enci ORACE,J N Division of OA, Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24% Fiche 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-14, "Failure of Automatic Sprinkler Bys Valves to Operate" Byc iist encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 078 24X Fiche 50-000,84/03/02,8402070000
- B402090009 lE info Notice 84-i5, "Reporting of Radiological Releases Byc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000.84/03/02.8402090009
- 64020900ii IE Info Notice 84-i7. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 64/03/05 Consolidated Edison Co of New York, Inc Ji7pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09, Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24x Fiche 50-000,84/03/07,8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corresion Cracking in PWR Bys " Svc list and! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22384 186 24X Fiche 50-000,84/03/07,8402070028

- 8402090031 IE Bulletin 84-02. 'Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list enc)
 DEYOUNG:R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York. Inc 134pp 22823 094 24x Fiche 50-000.84/03/12.8402090031
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unsuthorized Entries into PMR Reactor Cavities" Svc list encl
 JGRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/21. Consolidated Edison Co of New
 York, Inc. 123pp 22823 229 24% Fische 50-000,84/03/21,8402070043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24% Fiche 50-000,84/03/21,8402090044
- DOCKET STN-90-528 PALG VERDE NUCLEAR STATION: UNIT 1
- A Application/construction stage documents & correspondence
- 8403080390 Responds to FDIA request for 27 documents referenced in 1975 EIS re facilities & similiar environ documents Forwards App A Documents 1-10 Documents 11 & 12 available at NTIS FELTON, J M Division of Rules and Records 84/02/13 RYAN, J A Streich, Cang. Neeks & Cardon 2pp 22581 180 24x Fiche 50-528,84/02/13,8403080390
- --8403080409 "Groundwater Conditions of Lower Hassayampa-Centennial Alea. Maricopa County, AZ " Related info encl * Harshbarger & Associates R-900-74-2 74/06/30 83pp 22581 219 24X Fiche 50-528.84/02/13,8403080370
- B403050451 Forwards request for add1 info re open environ qualification of electrical equipment items for facility KNIGHTON.G W Licensing Branch 3 B4/02/27 VAN BRUNT.E E Arizona Public Service Co Spp 22550 007 24X Fiche 50-528,84/02/27,8403050451
- 8403010212 Forwards response to 840206 telcon re draft rev to FSAR Section 3A 10 concerning low preheat fillet welding Low preheat passes no concern principally due to low hardenability of base matis

 VAN BRUNT.E E Arisona Public Service Co 84/02/28 KNI6HTON, G Licensing Branch 3 4pp 22435 279 24x Fiche 50-328, 84/02/28, 8403010212
- 8403280043 Notification of 840320 meeting w/util & C-E in Bethesda, MD to discuss proposed testing program to demonstrate adequacy of mods to RCS pumps, thermowells, thermal sleeves & control element assembly shrouds
 LICITRA, E A Licensing Branch 3 84/02/27 KNIOHTON, G W Licensing Branch 3 3pp 22812 361 24x Fiche 50-528,84/02/27,8403280043
- 8403090130 Advises that proposed leak rate acceptance criteria for Tech Spec limiting conditions for operation unacceptable, since critoria less restrictive than 1 gpm leak rate imposed on near-term QLs KNIGHTON, G W Licensing Branch 3 64/03/01 VAN BRUNT, E E Arizona Public Service Co 2pp 22592 301 24X Fiche 50-528,84/03/01.8403090130
- 8403130094 Forwards outstanding item list for PDR List also submitted to util
 JOHNSON,P H Region 5, Office of Director 84/03/08 ALEXANDER, I Region 5, Office of Director 14pp 22641 190 24X
 Fiche 50-528,84/03/08,8403150094
- 8402070041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D @ Division of Licensing 84703/14 Atomic Safety and Licensing Board Panel 10pp 24X Ficha 50-000.84/03/14,840209004i
- 8403[6004B Forwards updated preliminary description (Rev 1) for RCS demonstration test
 VAN BRUNT, E E , RODERS, A C Arizona Public Service Co 84/03/14 KNIGHTON, Ø 1.temsing Branch 3 2pp 22659 169 24X Fiche: 50-528,84/03/14,8403160048
- --8403160052 Rev 1 to "RC8 Demonstration Test "

 * Arizona Public Service Co 64/02/27 Spp 22659 171 24X
 Fiche 50-528,84/03/14,8403160048
- 8403160069 Notifies that addi into & schedule re electrical equipment environ qualification program will be submitted by 840326, per 840227 request VAN GRUNT, E E Arizona Public Service Co 84/03/14 KNIGHTON, G Licensing Branch 3 lp 22652 326 24% Fiche 50-528, 84/03/14, 8403160065

- 8403270236 Forwards operations experience base, consisting of experience tables for presently licensed personnel Inadequate number of personnel meet 6-wk hot participation experience requirement VAN BRUNT, E E Arizona Public Service Co 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 22800 236 24X Fiche 50-528.84/03/23.8403270236
- C Utility Environmental Report (ER), amends & correspondence
- 8403080390 Responds to FOIA request for 27 documents referenced in 1975 EIS refacilities & similiar environ documents Forwards App A Documents 1-10 Documents 11 & 12 available at NTIS FELTON.J M Division of Rules and Records 84/02/13 RYAN.J A 8treich, Lang, Weeks & Cardon 2pp 22581 180 24X Fichs 50-528,84/02/13.8403080390
- --8403080400 Discusses review of environ rept re transmission lines crossing Indian reservations Tribal council consent should be obtained for right-of-way before environ rept published Related infe encl

 a Interior, Dept of, Bureau of Indian Affairs 74/12/11
 RECONNEH A Atomic Energy Commission Deputy Director for Reactor Projects 5pp 22581 184 24X Fiche 50-528,84/02/13,8403080390
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8403080385 FOIA request for 27 documents referenced in 1975 EIS refacilities & similiar environ documents List & news articles enc!

 RYAN, J A Streich, Lang, Weeks & Cardon 84/01/17 Office of Administration 9pp 22581 171 24X Fiche 50-528,84/01/17, 840/308/388
- 8403080390 Responds to FDIA request for 27 documents referenced in 1975 E18 re facilities & similiar environ documents Forwards App A Documents i-10 Documents i1 & 12 available at NTIB FELTON, J M Division of Rules and Records 84/02/13 RYAN, J A Streich, Lang, Weeks & Cardon 2pp 22381 180 24% Fiche 50-528,84/02/13,8403080390
- --B10B270490 Submits Geosciences Branch DEB input Updated summary of geology & seismology section FSAR will be included in BER JACKBUN, R E Geosciences Branch B1/0B/14 MIRAOLIA, F Licensing Branch 3 2pp. 225B1 182 24X Fiche 30-528, 84/02/13, 8403080390
- --8403080406 Comment on DES, per 750414 request Statement somewhat biased toward project More detailed maps of pipeline & transmission line corridors should be provided in final statement.

 DUREMUS, B D Interior, Dept of 75/07/23 REGAN Division of Reactor Licensing (NRR-1975 only) 29pp 22581 189 24X Fiche 50-528,84/02/13.8403080390
- 8403290341 Responds to FOIA request for records re facility Ltr dtd 840117 failed to meet criteria for waiver of reproduction costs Forwards App A documents Address of Phoenix LPDR listed FELTON, J M Division of Rules and Records 84/02/27 RYAN, J A Streich, Lang, Weeks & Cardon 3pp 22815 018 24X Fiche 50-528,84/02/27,8403290341
- --8403270344 DRAFT ENVIRONMENTAL STATEMENT RELATED TO CONSTRUCTION OF PALO VERDE NUCLEAR GENERATING STATION, UNITS 1.2 & 3 Docket Nos 50-328, 50-529 & 30-530 # Office of Nuclear Reactor Regulation, Director NUREG-75/022 75/04/30 175pp 22815 301 24X Fiche 50-528, 84/02/27, 8403290341
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B403020005 Forwards info requested in SSER 5 (NUREC-0857) re tests performed for C-E on load limiting devices in reactor vessel lower key horizontal supports
 VAN BRUNT, E E Arizona Public Service Co 84/02/10 KNIGHTUN, G
 Licensing Branch 3 9pp 22442 201 24X Fiche 50-528, 84/02/10, 8403020005
- 8403090012 Forwards "High Pressure Safety Injection Pump," methanical environ qualification rept, per SSER 5 (NUREO-0857) VAN BRUNT, E E Arizona Public Service Co 84/02/29 KNIGHTON, O W Licensing Branch 3 2pp 22568.001 24X Fiche 50-528.84/02/27, 8403090012
- --8403090014 "High Pressure Safety Injection Pump:" mechanical environ qualification rept
 HALLER.R E Bechtel Corp V-PAK-481 84/01/12. 198pp
 22068 004 24X Fichs 50-328,84/02/29,8403090012

- F Security, medical, emergency & fire protection plans
- 8403080145 Forwards IE Insp Rept 50-528/84-01 on 840116-20 No violations or deficiencies noted NORDERHAUD, L R Region 5. Office of Director 84/02/13 VAN BRUNT.E E Arizona Public Service Co 2pp 22559 132 24X Fiche 50-528
- --E4030B0152 IE Insp Rept 50-528/B4-01 on 840116-20 No violations or deficiencies noted Major areas inspected followup of open items identified during insp on 830411-22 & observation of 830511 emergency preparedness exercise FISH.R F . TEMPLE.O M . SCHUSTER.H D Region 5, Offics of Director 84/02/09 12pp 22559 154 24X Fichs 50-528.84/02/13.8403080145
- 84032600i4 Requests removal of App F & G from Rev 2 to Emergency Plan Implementing Procedure 7, per Generic Ltr 81-27 & GN Knighton 8402i4 ltr informing that util must request withholding of private or unlisted telephone numbers VAN BRUNT, E E Arisona Public Service Co 84/03/19 KNIGHTON, O W Licensing Branch 3 2pp 22750 258 24X Fiche 50-520, 84/03/19, 8403260014
- Q Inspection reports, IE Bulletins & correspondence
- 8402140014 FOIA request for records re NRC tonst assessment tsam (CAT) insp at facilities
 BERNABEI.L Government Accountability Project 83/10/07 Office of Administration 2pp 22254 001 24X Fiche 50-528,83/10/07,8402140014
- 840214001B Responds to FDIA request for records re NRC const assessment team (CAT) insp at facilities Forwards App A documents
 Documents also in FDR App B documents listed for review to
 identify specific interest
 FELTON.J M Division of Rules and Records 83/12/20 GARDE, 8 P
 Government Accountability Project 18pp 22254 003 24X
 Fiche 30-328,83/12/20,8402140018
- --8402140022 Summarizes civil insp items. Bechtel 830929 ltr re reinsp of nuclear pipe hangers (Q class) & related info encl VORDERBRUEGGEN Region 5. Offics of Director 83/09/19 NARBUT, P NRC - No Detailsd Affiliation Given 60pp 22254 021 24X Ficha 50-528, B3/12/20, B402140018
- --B402140026 "insp Plan " Draft outline given to inspectors on 830906 encl. **
 ** NRC No Detailed Affiliation Given 83/12/20 12pp 22254 081 24X Fiche 50-528,83/12/20,8402140018
- --8402140028 Provides add1 info re 830930 exit interview meeting w/const assessment team, for preliminary review of findings NRC critsria utilized during insp more applicable to operating plant Related info encl WOODS, T 0 Arizona Public Service Co 83/10/12 MARTIN, J B Region 5. Office of Director 339pp 22234, 320 24% Fiche 80-528.83/12/20,8402140018
- --8402140031 Comments on review of draft writeup on NDE Rewrite requested Related info encl NARBUT,P NRC - No Detailed Affiliation Given 83/09/27 KERCH.H NRC - No Detailed Affiliation Given 41pp 22254 094 24X Fichs 50-520,83/12/20.8402140018
- --8402140032 Summary of B30916 exit status meeting w/NRC const appraisal team re 830907-16 insp
 IDE.W E Arizona Public Service Co 83/09/19 ROEDEL, J A Arizona Public Service Co 6pp 22254 137 24X
 Fiche. 50-328, 83/12/20, 8402140018
- --8402140036 Forwards marked-up draft insp scops & objectives Related info encl
 ALBERT, W. G. Region 5, Office of Director 83/09/21 YDUNO, T
 Region 5, Office of Director 18pp 22254 143 24X
 Fiche 50-528,83/12/20,8402140018
- --8402140037 Corrective action request re piping cleanliness, per Procedure WPP/GCI 204 O, Rev 2, "Piping Bys Reisesse for Insulation," Related info encl GAITHER.C F Artiona Public Service Co. 83/09/13 23pp 22255 299 24X Fiche 50-528,83/12/20.8402140018
- --B402i4003B Forwards feeder rept rs insp activities at facility. Combined insp of concrate expansion anchor bolts & embedded plates will be written by L Vorderbruegen Radiographs rsviaued will be included in H Kerch rept Related info sncl WALTON.0 A. Region i. Office of Director B3/10/07 YOUND, T Region 5. Office of Director 153pp 22254:165. 24X Fichs 50-528,83/12/20,8402140018

- --8402140043 Provides list of NDE repts available from insplactivities completed w/NRC mobile NDE van at facility.per FOIA request Related info encl EBNETER, S.D. Rsgion i. Office of Director 93/11/13 ALEXANDER, I.M. Region 5, Office of Director 97pp 22255 324 24X Fiche 50-528.83/12/20,8402140018
- --8402140048 Rev O to "Palo Verde Station HPSI Sys Electrical & Instrumentation Const Audit Insp." final rept Related infoencl * Zytor. Inc NRC-IE-82/83-46C 83/10/04 158pp 22256 063 24X Fiche 90-528.83/12/20.8402140018
- --8402140052 Provides resolution for laces bolts on structural steel found during NRC const assessment team (CAT) insp Item considered closed Related info encl FORRESTER.R D Arizona Public Service Co 83/09/26 IDE.W E Ari
- B403080145 Forwards 1E Insp Rept 50-528/84-01 on 840116-20 No violations or deficiencies noted NORDERHAUG, L R Region 5, Office of Director 84/02/13 VAI BRUNT, E E Artiona Public Service Co 2pp 22559 152 24X Fiche 50-528,84/02/13,8403080145
- ~~8403080152 IE insp Rept 50-528/84-01 on 840116-20 No violations or deficiencies noted Major areas inspected followup of open items identified during insp on 830411-22 & observation of 830511 emergency preparedness exercise FISH, R F , TEMPLE, 0 M , SCHUSTER, M D Region 5, Office of Director 84/02/09 12pp 22559.154 24X Fiche 50-528,84/02/13,8403080145
- 8403080254 Forwards iE insp Repts 30-528/84-02 & 50-529/84-02 on 840103-0203 No noncompliance identified BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 84/02/27 VAN BRUNT.E E Arizona Public Service Co 2pp 22557 104 24X Fiche 50-528,84/02/27,8403080254
- --B403080243 IE Insp Repts 50-528/84-02 & 50-529/84-02 on B40103-0203 No noncompliance or deviations identified Major areas inspected startup testing program, info notice reviews, GA, low pressure safety injection pumps & pressurizer heater power FIORELLI, 0, YOUNO, T Region 5, Office of Director B4/02/10 6pp 22557 106 24X Fichs 50-528,84/02/27,8403080254
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc 11st enc1 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22907 237 24X Fiche 50-000,84/02/28,8401170072
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl ORACE, J N Division of GA. Bafeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22532 329 24% Fiche 50-000.84/03/02.8402090007
- 8402090008 IE info Notice 84-14, "Failure of Automatic Sprinkier Sys Valves to Operats" Svc list smc!

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Reisases "

 Bvc list encl

 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New

 York, Inc. 119pp 2253 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Duttility Temp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fichs 50-000.84/03/05,8402090011
- B403140024 Informs that Bingham-Williamette spare flange piece will be replaced by B40415 instead of 840227, dus to problems encountered w/yendom, per IE Bulletin 83-06. "Nonconforming Matls Supplied By Tube-Line Corp"

 VAN BRUNTLE E Arizona Public Servics Co 84/03/05 MARTIN, J B Region 5. Offics of Director ip 22633 217 24X

 Fiche 50-528,84/03/05,8403140024
- 8402090024 IE Info Notice 84-09. Rev i, "Lessons Learned From Insps of Fire Protection 8afe Shutdown 8ys " 8vc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc 1189p 22635 049 24X Fiche 50-000.84/03/07.8402090024

- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR
- 8402090031 IE Bulistin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list enc! OEYOUNG:R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24x Fichs 50-000,84/03/12,8402090031
- 8402090043 IE Info Notice 84-19. "Tub Events Involving Unauthorized Entries into PUR Reactor Cavities " Svc iist enci JORDANIE L Division of Emergency Preparedness & Engineering Responsy (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fiche 50-000.84/03/21,8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list and John Sys " John Sys " Svc list and John Sys " Svc list and
- 8403270135 Forwards IE Conference Rept 50-528/84-11 on 840305 re 1032/0133 Forwards IE Conference Rept 50-528/84-11 on 840305 recorrective actions talen in response to IE Insp Rept 50-528/83-34 Response to open questions requested BISHOP, T W Division of Residents Reactor Project & Engineering Programs 84/03/22 MODDs. T O Artisona Public Service Co 1 22769 137 24X Fishe 50-528.84/03/22.8403270135
- --8403270139 IE Conference Rept 50-528/84-11 on 840305 Major areas discussed corrective actions described in util 840131 response to IE lnsp Rept 50-528/83-34 & NRC 831212 enforcement Itr YOUNG.T. NARBUT, P.P. FIGRELLI.G. Region 5, Office of Director 84/03/22 3pp 22769 138 24X Fiche 50-528,84/03/22,8403270135
- R Persodic operating reports & related correspondence
- 8403320443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency finding dates not caused by delay due to oresite emergency planning issues DIRCKS.W J Dffice of the Executive Director for Operations 84/02/21 PALLADIND Commissioners 9pp 22492 083 24X Fiche 50-000.84/02/21,8403020443
- S Reportable occurrences, LERs & related correspondence
- 8403090087 Interim Deficiency Rept 83-81 re Schadule 140 SS pipe supplied by Gulfalloy, Inc. containing mfg min wall thickness defect Initially reported on 831128 No new info presently available Final rept expected by 840417

 VAN BRUNT, E E Arizona Public Service Co 84/02/22 B18HOP. 7 Division of Resident, Reactor Project & Engineering Programs 22575 325 24X Fiche 30-528, 84/02/22, 8403090087 84/02/22 B18H0P, T W
- 8403390122 Interim Potentially Reportable Deficiency Rept DER 83-69 re seismic support on Posi-Seal valves not installed per spacs Due to extensive investigation, final rept delayed until 840315 VAN BRUNT.E E Arizona Public Service Co B4/02/22 BISHDP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 22376 064 24% Fiche 50-528.84/02/22.8403090122
- 8403090197 Interim Deficiency Rept DER 83-82 re cables in Units 1 & 2 diesel generator control cabinets & Unit 1 diesel generator bldg w/small bend radius Initially reported on 831202 Final rept delayed until 840425 VAN BRUNT, E E Arligna Public Service Co 84/02/22 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 22574 290 24X Fithe 50-528,84/02/22,8403090197
- 849309025B Interim Deficiency Rept DER 83-75 re improperly torqued bolts securing two D01265A panel filler assemblies, supplied by Forboro No new info available at present time Final rept will be submitted by 840419 VAN BRUNT.E E Arijona Public Service Co 84/02/22 BISHOP, TW Division of Resident.Reactor Project & Engineering Programs 2pp 22572 211 24X Fiche 50-528.84/02/22.8403090258
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpsi NPS-4 T&T valve, to close. Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BMR sent to assess outs a management to proceed to plants
 THEROUX, R Terry Corp 84/02/22 WDDDRUFF, R W Director's
 Office, Office of Inspection and Enforcement App 22706 327 24X
 Fiche 50-000.84/02/22.8403210032

- 840229000B Forwards response to listed items identified in 840125 telcon request for info generated based on preliminary review of 831230 deficiency rept re missing thermal liner in safety injection sys line Encis withheld VAN BRUNT.F. E. Arizona Public Service Co. 84/02/24 KNIGHTON.O Licensing Branch 3 Spp. 22516 184 24X Fiche 50-528.84/02/24.8402290008
- 8403090077 Interim Deficiency Rept 83-72 re undersized wolds in Audition by light overtiency when the Per Hard re uncertained was about library bidg discovered by const appraisal team initially reported on 831026 Due to extensive investigation & evaluation final rept will be delayed until 840315 VAN BRUNT.E E Arisona Public Service Co 84/02/24 DIBM Region 5. Defice of Director 2pp 22573 274 24X Fiche 30-528.84/02/24.8403090077 DIBHOP, T W
- 8403090096 Deficiency Rept DER 83-73 re unqualified Foxbord power supplies instaited in IE instrument cabinets initially reported on 831027 No new info presently available Next rept will be provided by 840425 VAN BRUNTLE E Artiona Public Service Co 84/02/24 BIBHOF, Y Division of Resident. Reactor Project & Engineering Programs 2; 22576 179 24X Fiche 30-528,84/02/24,8403090096
- 8403090167 Interim Deficiency Rept DER 82-80 re low insulation resistance on installed Conex electrical penetrations not meeting qualification test criteria Initially reported on 821217 Final rept delayed until 1840429.

 VAN BRUNTLE E Anizona Public Bervice Co 84/02/24 DIBHOP, T W Division of Resident-Reactor Project & Engineering Programs 2pp 22575 116 24X Fiche 50-528,84/02/24,8403070167
- 8403060429 Requests add1 info needed to complete evaluations of & fires for reactor coolant pump problems encountered during hot functional testing Response requested within 2 wks KNIGHTON, 0 & Licensing Branch 3 84/02/27 VAN BRUNT, E Arizona Public Bervice Co 3pp 22592 210 24X Fichs 50-528,84/02/27,8403060429
- 8403120032 Final Deficiency Ropt DER 83-70 re wiring in omergency response facility cabinets supplied by Energy, Inc. not in conformance w/IEEE-384 critoria Initially reported on 831011 Drawings resubmitted Also reported per Part 21 VAN BROWNTE E Arizona Public Bervice Co. 84/02/28 BIBHUP, Y W Division of Resident.Reactor Project & Engineering Programs App 22588 025 24X Fichs 50-528.84/02/28,8403120032
- B403120069 Final Deficiency Rept DER 83-10 re main steam relief valves supplied by C-E & mfg by Dresser Industries exceeding specified 5% blowdown limit Initially reported on 830228 Deficiency determined not reportable per 10CFR90 93(e) VAN BRUNTLE E Artiona Public Service Co 84/02/28 BISHOP, T H Division of Resident, Reactor Project & Engineering Programs 4pp 22591 129 24X Fiche 50-528.84/02/28.8403120069
- 8403130449 Potential Deficiency Rept DER 83-64 re Target Rock pressure relief valves failing to meet preroquisite tests Final rept delayed until 840402 VAN BRUNTLE E Artiona Public Service Co 84/02/28 BIBHUP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 22613 212 24x Fiche 50-528,84/02/28,8403130449
- 8403130461 Potential Deficiency Rept DER 83-68 re Dorg Warmer MPBI isolation valves failing to open against MPBI A & B pump flows Final will rept delayed until 840417 VAN BRINTIE E Afizona Public Service Co 84/02/28 BISHUP, T, N Division of Resident, Reactor Project & Engineering Programs 2pp 22613 355 24X Fiche 50-528.84/02/28,8403130461
- 8403090149 Forwards request for add1 info re Deficiency Rept DER 01-39 concerning leaks in temporary water lines that distributed backfill under seismic Category 1 structures Responses requested within 2 wks of itr receipt KNIGHTON, G W Licensing Dranch 3 84/02/29 VAN BRUNT, E E, Arizona Public Service Co Bpp 22584 350 24X Fiche 50-528, 84/02/29, 8403090149
- 8403120113 Final Deficiency Rept DER 83-32 re socket wolds in steam generator process plping in violation of requirements initially reported on 830525 Condition determined not reportable per 10CFR90 55(s) VAN BRUNTLE E Arizone Public Service Co 84/02/29 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 5pp 22588 218 24X Fiche 50-526, 84/02/29,8403120113
- 8403200115 Interim Deficiency Rept DER 83-80 re Anchor Darling main feedwater isolation valves closing in 20 s, violating 5 s spec requirement Initially reported on 831122 Final rept will be delayed until 840403 due to extensive investigation, VAN BRUNTLE E Arizona Public Service Co 84/03/02 BIBHOP, T W Division of Resident Reactor Project & Engineering Programs 2pp. 22685:355 24X Fichs 50-528,84/03/02,8403200115

- 8403200186 Interim Deficiency Rept DER 83-56 re discrepancies w/MSIVs mfg by Anchor-Darling Initially reported on 830808 Investigation will be finalized by 840413 at which time complete rept will be submitted VAN BRUNT, E E Arizona Public Service Co 84/03/08 BISHOP, T W Division of Residenth Reactor Project & Engineering Programs 2pp 22686 359 24X Fiche 50-328.84/03/08.8403200186
- 8403200226 Interim Deficiency Rept DER 84-06 re defective absolute & deviation alarm modules supplied by Foxboro. C-E requested that all alarm modules u/dste Codes 8048-8152 be inspected for potential defect Next rept by 840612 VAN BRUNT, E E Arizona Public Service Co 84/03/07 BISHDP, T W Division of Resident/Reactor Project & Engineering Programs 3pp 22699 358 24X Fiche 50-528,84/03/07,8403200226
- 8403230039 Final Deficiency Rept DER-83-79 re ac interference spikes on 125-volt dc bus exceeding spec Initially reported on 831118 Deficiency deemed not reportable per 100FR30 55(e) VAN SRUNT, E Arizona Public Service Co 84/03/09 BISHDP, T W Division of Resident Reactor Project & Engineering Programs 4pp 22730 302 24X Fiche 50-528,84/03/09,8403230039
- 8403230113 Rev 1 to final Deficiency Rept 82-30 re possible damaged flexible conduit couplings between auxiliary & control bldgs in event of veismic events exceeding 3/4 inch movement changes final rept disposition to reportable under 10CFR21 VAN BRUNT.E E Arizona Public Service Co 84/03/09, BISHOP.T W Division of Resident. Reactor Project & Engineering Programs App 22730 215 24X Fiche 50-528.84/03/09.8403230113
- 8403230006 Final Deficiency Rept DER 83-87 re vaives w/handwheei adapter nut missing & rising stem supplied by Roto-Hammer. Inc longer than operating bridle Initially reported on 840103 Condition not reportable per 10CFR50 55(e) & Part 21 VAN BRUNTLE E Arizona Public Service Co. 84/03/13 818HOP, T & Division of Resident, Reactor Project & Engineering Programs 6pt 22728 343 24X Fiche 50-528,84/03/13,8403230006
- 8403230099 Final Deficiency Rept DER 83-72 rs undersize welds in auxiliary bldg initially reported on 831026 Condition determined not reportable per 10CFR50 55(e)

 VAN BRUNT,E E Arizona Public Service Co 84/03/14 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 6pp 22728 336 24X Fiche 50-328, 84/03/14, 8403230079
- 8403230019 Final Deficiency Rept DER 82-46 ve ITT Berton pressure transmitters supplied by C-E not meeting averpressure requirements Coused by leakage of metallic washers & methodology error during calibr Also reported per Part 21 VAN BRUNTLE E Arizona Public Service Co 84/03/15 BISHOP.T W Division of Resident Reactor Project & Engineering Programs 7pp 22724 333 24X Fiche 30-528.84/03/15.8403230019
- 8403300096 Interim Deficiency Rept DER 84-08 re ITY Barton Model 763 transmitters having errors of -2 to -3% of calibr span Bechtal corresponding w/C-E to determine impact of design mods to transmitters

 VAN RRUNT, E E Arrisona Public Service Co 84/03/16 BIBHOP, T, W Division of Resident, Reactor Project & Engineering Programs 3pp 22822 010 24% Fiche 50-528, 84/03/16, 8403300096
- 8403300020 Rev i to final Deficiency Rept DER 82-46 re lTT-Barton pressure transmitters supplied by C-E failing to meet overpressure requirements Initially reported on 820824 Also reported per Part 21

 VAN BRUNT,E E Arizone Public Service Co 84/03/19 BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 7pp 22822:171 24X Fiche 50-528.84/03/19.8403300020

V Operator Examinations

- B403290236 Forwards operations experience base, consisting of experience tables for presently licensed personnel Inadequate number of personnel meet 6-wk hot participation experience requirement

 VAN BRUNT, E E Arizona Public Service Co 84/03/23 DENTON, H R. Office of Nuclear Reactor Regulation. Director 17pp 22800 236 24X Fiche 20-328:84/03/23,8403270236
- DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 2403080390 Responds to FOIA request for 27 documents referenced in 1975 EIB me facilities & similiar environ documents Forwards App A Documents 1-10 Documents 11 & 12 available at NTIS FELTON, J M Division of Rules and Records B4/02/13 RYAN, J A Btraich, Leng, Weeks & Cardon 2pp 22581 180 24X Fiche 30-328,84/02/13,8403080390

- --8403080409 "Groundwater Conditions of Lower Hassayampa-Centennial Area. Maricopa County.AZ " Related info encl * Harshbarger & Associates R-900-74-2 74/06/30 83pp 22581 219 24X Fishe 50-528.84/02/19.8403080390
- 8403060451 Forwards request for additinfo re open environ qualification of stectrical equipment items for facility KNIGHTON.G W Licensing Branch 3 84/02/27 VAN BRUNT.E E Aprilona Public Service Co 5pp 22550 007 24X Fiche 50-528.84/02/27.8403060451
- 8403010212 Forwards response to 840206 telcon re draft rev to FSAR Section 3A 10 concerning low preheat fillet welding Low preheat poses no concern, principally due to low hardenability of base matts
 VAN BRUNT, E.E. Arizona Public Service Co. 84/02/28 KNIGHTON, 0 Licensing Branch 3. 4pp. 22435 279. 24X Fiche 50-528,84/02/28,84/03010212
- 8403280043 Notification of 84D320 meeting w/util & C-E in Bethesda.MD to discuss proposed testing program to demonstrate adequacy of mods to RCS pumps, thermoweils, thermal sleeves & control element assembly shrouds
 LICITRALE A Licensing Branch 3 84/02/27 KNIGHTON, 0 W
 Licensing Branch 3 3pp 22812 361 24X Fiche 50-528.84/02/29, 8403280043
- 8403090130 Advises that proposed leak rate acceptance criteria for Tech Spec limiting conditions for operation unacceptable since criteria less restrictive than 1 gpm leak rate imposed on near-term (LLs KNIGHTON: 0 W Licensing Branch 3 84/03/01 VAN GRUNT, E E Apricona Public Service Ca 2pp 22572 301 24X Fiche 50-528,84/03/01,84030970130
- 8403130094 Forwards outstanding item list for PDR List also submitted to util JOHNSON, P. H. Region 5, Office of Director 84/03/08 ALEXANDER, R. Region 5, Office of Director 14pp 22641 190 24X Fiche 50-528,84/03/08,8403150094
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D 0 Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000:84/03/14:8402090041
- 8403160048 Forwards updated preliminary description (Rev i) for RCS demonstration test
 VAN BRUNT, E E. RQGERS, A C. Arisona Public Service Co. 84/03/14
 KNIGHTUN, G. Licensing Branch 3 2pp 22639 i69 24X
 Fiche 50-528,84/03/14,8403160048
- --8403160052 Rev 1 to "RCS Demonstration Test "
 * Arizona Public Service Co 84/02/27 Bpp 22659 171 24X
 Fiche 50-528.84/03/14.8403160048
- 8403160065 Notifies that add1 info & schedule re electrical equipment environ qualification program will be submitted by 840326, per 840227 request VAN BRUNT.E E Arisona Public Service Co 84/03/14 KNIGHTON.G Licensing Branch 3 ip 22652 326 24% Fiche 50-528,84/03/14,8403160065
- B403270236 Forwards operations experience base consisting of experience tables for presently licensed personnel inadequate number of personnel meet 5-wk hot participation experience requirement VAN BRUNTLE E Ariona Public Service Co 64/03/23 DENTON, H R Office of Nuclear Reactor Regulation Director 17pp 22800 236 24X Ficho 50-520, 84/03/23, 8403270236
- C Utility Environmental Report (ER), amends & correspondence
- 8403080390 Responds to FDIA request for 27 documents referenced in 1975 EIS re facilities & similar environ documents Forwards App A Documents 1-10 Documents 11 & 12 evaluable at NTIS FELTON, J M Division of Rules and Records, 84/02/13 RYAN, J A Streith, Lang, Weeks & Cardon 2pp 22581:180 24% Fiche 50-528,84/02/13,8403080390
- --8403080400 Discusses review of environ rept re transmission lines crossing Indian reservations Tribal council consent should be obtained for right-of-way before environ rept published Related info encl
 # Interior: Dept of, Bureau of Indian Affairs 74/12/11
 REGAN.W H Atomic Energy Commission Deputy Director for Reactor Projects 5pp. 22581 184 24X Fiche 50-528,84/02/13,8403080390

- D MRC Draft/Final Environmental Statements, supple & correspondence
- 8403080385 FOIA request for 27 documents referenced in 1975 EIS refacilities & similiar environ documents List & news articles encl
 RYAN, J A Streith, Lang, Weeks & Cardon 84/01/17 Office of Administration 9pp 22581 171 24X Fiche 50-528.84/01/17. 8403880385
- 8403080390 Responds to FOIA request for 27 focuments referenced in 1975 EIB re facilities & similiar environ documents Forwards App A Documents 1-10 Documents 11 & 12 available at NTIS FELYON, J M Division of Rules and Records 84/02/13 RYAN, J A Streich, Lang, Weeks & Cardon 2pp 22581 180 24X Fiche 30-528.84/02/13,8403080390
- --8108270490 Submits Geosciences Branch DES input Updated summary of geology & seismology section FSAR will be included in SER JACKSON.R. E. Geosciences Branch 81/08/14 MIRAOLIA.F. Licensing Branch 3 2pp 22581 182 24X Fiche 50-528, 84/02/13, 8403080390
- --B403080406 Comment on DES, per 750414 request Statement somewhat biased toward project More detailed maps of pipeline & transmission line corridors should be provided in final statement DOREMUS.S D Interior, Dept of 75/07/23 REGAN Division of Reactor Licensing (NRR-1975 only) 29pp 22581 189 24X Fiche 50-528,84/02/13,8403080390
- 840329034: Responds to FGIA request for records re facility Ltr dtd 840117 failed to meet criteria for waiver of reproduction costs Forwards App A documents Address of Phoenix LPDR listed FELTON, J M Division of Rules and Records 84/02/27 RYAN, J A Streich, Lang, Weeks & Cardon 3pp 22815 018 24X Fiche 50-528,84/02/27,8403290341
- --8403290344 DRAFT ENVIRONMENTAL STATEMENT RELATED TO CONSTRUCTION OF PALO VERDE NUCLEAR GENERATING STATION.UNITS 1.2 % 3 Docket Nos 50-328, 50-329 % 50-530 % Office of Nuclear Reactor Regulation, Director NUREG-75/029 75/04/30 175pp 22815 301 24X Fiche 50-528,84/02/27,8403290341
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403020005 Forwards info requested in SSER 5 (NUREO-0857) re tests performed for C-E on load limiting devices in reactor vessel lower key horizontal supports VAN BRUNT.E E Arizona Public Service Co 84/02/10 KNIGHTGN.0 Licensing Branch 3 Typ 22442 201 24X Fiche 50-528.84/02/10.8403020005
- 8403090012 Forwards "High Pressure Safety Injection Pump," mechanical environ qualification rept, per SSER 5 (NUREO-0857)
 VAN BRUNT-E E Arizona Public Service Co 84/02/27 KNIGHTON, G W Licensing Branch 3 2pp 22568 001 24X Fiche 50-528, 84/02/27, 8403090012
- --8403070014 "High Pressure Safety Injection Pump," mechanical environ qualification rept
 HALLER, R E Bechtel Corp V-PAK-481 84/01/12 198pp
 22568 004 24X Fiche 50-528,84/02/29,8403090012
- F Security, medical, emergency & fire protection plans
- B402090006 Board Notification 84-034.forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D G Division of Licensing 84/02/23 PALLADING Commissioners Ip 22576 203 24% Fiche 50-000,84/02/23,8402090006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board natification, per NRR OFC Ltr 19, dtd 821001 Further evaluation of test data required VOLLHER, R H Division of Engineering 84/02/06 EISENHUT, D G Division of Licensing 10pp 22576 204 24% Fiche 50-000,84/02/23,8402090006
- 8403260014 Requests removal of App F & O from Rev 2 to Emergency Plan Implementing Procedure 7, per Generic Ltr 81-27 & GW Knighton 840214 1tr informing that util must request withholding of private or unlisted telephone numbers VAN BRUNT.E E Arizona Public Bervice Co B4/03/17 KNIGHTON,6 W Licensing Branch 3 2pp 22750 258 24X Fiche 50-528,84/03/19, 8403260014

- @ Inspection reports. IE Bulletins & correspondence
- BA02140014 F01A request for records re NRC const assessment team (CAT) insp at facilities
 UERNABELL Government Accountability Project 83/10/07 Office of Administration 2pp 22294 001 24X Ficho 50-528.83/10/07, B402140014
- 8402140018 Responds to FOIA request for records re NRC const assessment team (CAT) insp at facilities Forwards App A documents

 Documents also in PDR App B documents listed for review to identify specific interest

 FELTON.J M Division of Rules and Records 83/12/20 GARDE, B P Government Accountability Project 18pp 22234 003 24X

 Fiche 50-528,83/12/20,8402140018
- --8402140022 Summarizes civii insp items Bechtel 830929 ltr re reinsp of nuclear pipe hangers (G tlass) & related info enci VORDERINUEGOEN Region 5, Office of Director 83/09/19 NARBUT, P NRC - No Detailed Affiliation Given 60pp 22254 021 24X Fithe 50-928,83/12/20,8402140018
- --B402140031 Comments on review of draft writeup on NDE Rewrite requested Related info encl NARBUT,P NRC - No Detailed Affiliation Given 83/09/27 KERCHH NRC - No Detailed Affiliation Given 41pp 22254 094 24X fichs 50-528,83/12/20,8402140018
- --8402140032 Summary of B30916 erit status meeting w/NRC const appraisai team re 830907-16 insp IDE.W E Arizona Public Service Co 83/09/19 ROEDEL, J A Arizona Public Service Co 6pp 22254 137 24X Fiche 50-329.83/12/20.8402140018
- --8402140036 Forwards marked-up draft insp scope & objectives Related info encl ALBERT, N G Region 5. Office of Director 83/09/21 YOUNG, T Region 5. Office of Director 18pp 22254 143 24X Fiche 50-528,83/12/20,8402140018
- --8402140043 Provides list of NDE repts available from insp activities completed w/NRC mobile NDE van at facility, per FOIA request Related info encl EUNETER.5 D Region i, Office of Director 83/11/15 ALEXANDER.1 M Region 5, Office of Director 97pp 22255 JZ4 24X Fiche 50~528.83/12/20,8402140018
- --8402140032 Provides resolution for loose bolts on structural steal found during NRC const assessment team (CAT) insp Item considered closed Related info encl FORRESTER.R D. Arizona Public Service Co. 83/09/26 IDE.W E. Arizona Public Service Co. 3pp. 22236 221 24X Fiche 50-328,83/12/20.8402140018
- 8403080294 Forwards IE Insp Repts 50-528/84-02 & 50-529/84-02 on 840103-0203 No noncompliance identified BISHOP.T W Division of Resident.Reactor Project & Engineering Programs 84/02/27 VAN BRUNT.E E Arizona Public Service Co 2pp 22557 104 24X Fiche 50-528.84/02/27, 8403080254
- --8403080263 IE Insp Repts 50-528/84-02 & 30-529/84-02 on 840103-0203 No noncompliance or deviations identified Major areas inspected startup testing program.info notice reviews, GA, low pressure safety injection pumps & pressurizer heater power FIORELLI, G, YOUNG, T Region 3, Office of Director 84/02/16 opp 22557 106 24X Fichs 30-528,84/02/27,8403080254
- B401190072 IE Info Nutice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24% Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Reys by DOT & NRC " Svc list encl CRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24% Fiche 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24% Fiche 50-000,84/03/02,8402070008

- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list encl
 JDRDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductlijty Temp "Svc 11st encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402070011
- 8403140024 Informs that Bingham-Williamette spare flange piece will be replaced by 840415 instead of 840229; due to problems encountered w/vendor.per IE Bulletin 83-06, "Nonconforming Matis Supplied By Tube-Line Corp"

 VAN BRUNTLE E Arizona Public Service Co 84/03/05 MARTIN, J B Region 5, Office of Director ip 22633 217 24X

 Fiche 50-528,84/03/05,8403140024
- 8402070024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list enci JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07, 8402070024
- 8402070028 IE Info Notice 84-19, "Stress Corrosion Cracking in PWR 8ys " Svc list encl JURDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 90-000,84/03/07,8402070028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Syc list enci DEYBUNO,R C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12.8402070031
- B402090043 IE Info Notice B4-19. "Two Events Involving Unauthorized Entries into PMR Reactor Cavities " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York: Inc 123pp 22823 229 24X Fiche 50-000:84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22939 001 24X Fiche 50-000,84/03/21,8402090044
- 8 Reportable occurrences. LERs & related correspondence
- 8403090087 Interim Deficiency Rept 83-81 re Schedule 160 SS pipe supplied by Quifailoy, inc. containing mfg min wall thickness defect Initially reported on 831128 No new info presently available Final rept expected by 840417

 VAN BRUNT, E E Arizona Public Service Co 84/02/22 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 22575, 325 24X Fiche, 50-528, 84/02/22, 8403070087
- 8403090197 Interim Deficiency Rept DER 83-82 re cables in Units i & 2 diesel generator control cabinets & Unit i diesel generator bldg w/smail bend radius Initiality reported on 831202 Final rept delayed until 840425 VAN BRUNT.E E. Artiona Public Service Co 84/02/22 BIBHOP, T W Division of Resident.Reactor Project & Engineering Programs 2pp 22574 290 24X Fiche 50-528,84/02/22.8403090197
- 8403090288 Interim Deficiency Rept DER 83-75 re improperly torqued bolts securing two D01268A panel filler assemblies, supplied by Foxboro No new info available at present time Final rept will be submitted by 840419
 VAN BRUNT. E E Arizona Public Service Co 84/02/22 BISHOP, T W Division of Resident. Reactor Project & Engineering Programs 2pp 22572
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Dimpel NPB-4 T&T valve. to close Encl ltr dtg 840203 sent to listod utils GE notlfied of affected units in BWR plants
 THERDUX.R R Terry Corp 84/02/22 WOODRUFF.R W Director's Office. Office of Inspection and Enforcement opp 22706:327 24% Fichs. 50-000.84/02/22.8403210032
- B40229000B Forwards response to listed items identified in B40125 telcon request for info penerated based on preliminary review of B31230 deficiency rept re missing thermal liner in safety injection sys line Encls withheld VAN BRUNT, E.E. Arlzona Fublic Service Co 84/02/24 KNIGHTON, O. Licensing Branch 3. 3pp 22516 186 24X Fiche 50-528, 84/02/24, 8402270008

- 8403090096 Deficiency Rept DER 83-73 re unqualified Forboro power supplies installed in IE instrument cabinets Initially reported on 831027 No new info presently available Next rept will be provided by 840425 VAN BRUNTLE E Arizona Public Service Co 84/02/24 BISHDP,T N Division of Resident. Reactor Project & Engineering Programs 2pp 22576 179 24X Fiche 90-328.84/02/24.8403070096
- 8403090i67 Interim Deficiency Rept DER 82-80 re low insulation resistance on installed Conax electrical penetrations not meeting qualification test criteria Initially reported on 821217 final rept delayed until 840425 VAN BRUNT.E E Arisona Public Service Co 84/02/24 BISHOP,T W Division of Resident.Reactor Project & Engineering Programs 2pp 22579 116 24x Fiche 30-528,84/02/24.8403090i67
- B403060429 Requests add1 info needed to complete evaluations of & fixes for reactor coolant pump problems encountered during hot functional testing Response requested within 2 wks KNIGHTON, O W Licensing Branch 3 84/02/27 VAN BRUNT, E E Arizona Public Service Co 3pp 22552 210 24X Ficha 50~528.84/02/27, B403060429
- 8403120032 Final Opficiency Rept DER 83-70 to wiring in emergency response facility cabinets supplied by Energy, Inc not in conformance witEEE-384 criteria initially reported on 831011 Drawings resubmitted Also reported per Part 21 VAN BRUNT.E E Artiona Public Service Co 84/02/28 BISHDP, TW Division of Resident Reactor Project & Engineering Programs App 22588 025 24% Fiche 50-528,84/02/28,8403120032
- 8403120069 Final Deficiency Rept DER 83-10 re main steam relief valves supplied by C-E & mfg by Dresser Industries exceeding specified 5% bloodown timit Initially reported on 830228 Deficiency determined not reportable per 10CFR30 55(e) VAN DRUNTLE E Arizona Public Service Co 84/02/28 BISHOP, T N Division of Resident. Reactor Project & Engineering Programs 4pp 22591 127 24% Fiche 50-528.84/02/28.8403120069
- 8403130449 Potential Deficiency Rept DER 83-64 re Target Rock pressure relief valves failing to meet prerequisite tests Final rept delayed until 840402

 VAN BRUNT.E E, Arizona Public Service Co 84/02/28 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs 2pp 22613 212 24X Fiche 30-528.84/02/28.8403130449
- 8403130461 Potential Defictency Rept DER 83-68 ro Borg Marner HPSI isolation valves failing to open against HPSI A & B pump flows Final will rept delayed until 840417 VAN ERUNT, E E Arizona Public Service Co 84/02/28 BISHOP, T N Division of Resident, Reactor Project & Engineering Programs 2pp 22613 355 24X Fiche 50-528, 84/02/28, 8403130461
- B40320D115 interim Deficiency Rept DER 83-80 re Anchor Darling main feedwater isolation valves closing in 20 s.violating 5 s spec requirement Initially reported on 831122 Final rept Will be delayed until 840403 due to extensive investigation VAN SRUNT.E E Ariona Public Service Co 84/03/02 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 22685 355 24% Fiche 50-528,84/03/02.8403200115
- 8403200160 Interim Deficiency Rept DER 84-07 re extension of Darg Harner valve stems & failure to provide corrective action stated in Rept DER 80-21 Initially reported on 84029 Bechtoi investigating corrections Final rept by 840416 VAN GRUNTLE E Arizona Public Service Co 84/03/02 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 22697 131 24X Fiche 50-527,84/03/02,8403200160
- 8403200186 Interim Deficiency Rept DER 83-56 re discrepancies w/MSIVs mfg by Anchor-Darling Initially reported on 830808 Investigation will be finallized by 840413 at which time complete rept will be submitted VAN DRUNTLE E Arizona Public Service Co 84/03/08 BISHQP,T W DIVISION of Resident, Reactor Project & Engineering Programs 2pp 22686 359 24X Fiche 50-328.84/03/08,8403200186
- 8403200226 Interim Deficiency Rept DER 04-06 re defective absolute & deviation alarm modules supplied by Foxboro C-E requested that all alarm modules w/date Codes 8048-8152 be inspected for potential defect Next rept by 840612 VAN BRUNT, E & Arizona Public Service Co 8403/09 BIBHOP, T W Division of Resident Reactor Project & Engineering Programs 3pp 22699 358 24% Fiche 50-528,84/03/09,8403200226
- 8403230039 Final Deficiency Rept DER-83-79 re at Interference spikes on 123-volt dc bus excepting spec Initially reported on 831118 Deficiency deemed not reportable per 100FR90 55(e) VAN BRUNT, E E Arizona Public Service Co 84/03/09 BISHOP, T W Division of Resident. Reactor Project & Engineering Programs 4pp 22730 302 24X Fiche 50-328, 84/03/09, 84032300309

- 8403230132 Final Deficiency Rept DER 83-59 re lEEE-384 separation criteria violated by wiring in post-accident control room cabinet & safety radiation monitoring cabinet Supplied by Ramen Instrumentation Item not reportable per 10CFR50 55(e) VAN BRUNIT.E E Arizona Public Service Co 84/03/09 BIBMDP.T W Division of Resident.Reactor Project & Engineering Programs 5pp 22730 154 24X Fiche 50-529.84/03/09.8403230132
- B4D3230099 Final Deficiency Rept DER 83-72 re undersize welds in auxiliary bldg Initially reported on 831026 Condition determined not reportable per 10CFR80 55(e) VAN BRUNT, E E Arizona Publik Service Co 84/03/14 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 6pp 22728 356 24% Fiche 50-528, 84/03/14, 8403230099
- 8403230019 Final Deficiency Rept DER 82-46 rp lTT Barton pressure transmitters supplied by C-E not meeting overpressure requirements Caused by leakagp of metallic washers & nethodology error during calibr Also reported per Pant 2: VAN BRUNT.E E Arizona Public Service Co 84/03/15 Bi8HDP,T W Division of Resident Reactor Project & Engineering Programs 7pp 22724 353 24X Fiche 50-528,84/03/15.8403230019
- 8403300076 Interim Deficiency Rept DER 84-08 re ITT Barton Hodel 763 transmitters having errors of -2 to -3% of calibr span Dechtel corresponding o/C-E to determine impact of design mode to transmitters

 VAN BRUNTLE E Arizons Public Service Co 84/03/16 BISHDP.T W Division of Resident.Reactor Project & Engineering Programs Jpp 22822 010 24% Fiche 50-528.84/03/16.8403300096
- 8403300020 Rev 1 to final Deficiency Rept DER 92-46 re ITY-Barton pressure transmitters supplied by C-E failing to meet overpressure requirements initially reported on 820824 Also reported per Part 21 VAN BRUNT.E E Arijona Public Service Co 84/03/19 818HDP.T W Division of Resident, Reactor Project & Engineering Programs 7pp 22822 171 24X Fiche 50-528,84/03/19,8403300020

V Operator Examinations

- 8403290236 Forwards operations exp./ ence base.consisting of experience tables for presently licensed personnel inadequate number of personnel meet 6-uk hot participation experience requirement

 VAN DRUNT, E E Arizona Public Service Co 84/03/23 DENTON, H R

 Office of Nuclear Reactor Regulation, Director 17pp 22800 236

 24X Fiche 50-528,84/03/23,8403290236
- DOCKET STN-50-530 PALG VERDE NUCLEAR STATION. UNIT 3

 A Application/construction stage documents & correspondence
- 8403080390 Responds to FOIA request for 27 documents referenced in 1975 EIS re facilitles & similiar environ documents Forwards App A Documents 1-10 Documents 1-1 & 12 available at NTIS FELTON,J M Division of Rules and Records 84/02/13 RYAN,J A Streich, Lang, Weeks & Cardon 2pp 2238) 180 24x Fiche 50-528.84/02/13.8403080390
- --8403080407 "Groundwater Conditions of Lower Hassayampa-Centennial Area. Maricopa County.AZ " Related info encl * Harshbarger & Associates R-700-74-2 74/06/30 83pp 22581 219 24% Fiche 50-328,84/02/13.8403080390
- 8403060451 Forwards request for addi info re open environ qualification of electrical equipment items for facility KNIGHTON. 6 W Licensing Branch 3 84/02/27 VAN BRUNT, E E Afizona Public Sprvice Co 5pp 22550 007 24X Fiche 50-528.84/02/27,8403060451
- 8403010212 Forwards response to 840206 telcon re draft rev to FEAR Section 3A 10 concerning low preheat fillet welding Low preheat poses no concern, principally due to low hardenability of base matts

 VAN BRUNT, E E Ariiona Public Service Co 84/02/28 KNIOHTGN.0 Licensing Granch 3 4pp 22435 277 24X Fiche 50-528,84/02/28,8403010212
- 8403280043 Notification of 840320 meeting w/util & C-E in Bethesda.MD to discuss proposed testing program to demonstrate adequacy of mods to RCS pumps. thermowells: thermal sleeves & control element assembly shrouds LICITRA.E A Licensing Branch 3 84/02/29 KNICHTDN, G W Licensing Branch 3 3pp 22812 36t 24X Fiche 50-528.84/02/29, 8403280043

- B403090:30 Advises that proposed leak rate acceptance criteria for Tech Spec limiting conditions for operation unacceptable, since criteria less restrictive than 1 gpm leak rate imposed on near-term OLs MNIGHTON, GW Licensing Branch 3 84/03/01 VAN DRUNT, E Arizona Public Service Co 2pp 22592 301 24X Fiche 50-328,84/03/01,8403090130
- 8403150074 Forwards outstanding item 11st for PDR List also submitted to util JOHNSON.P H Region 5, Office of Director 84/03/08 ALEXANDER, I Region 5, Office of Director 14pp 22641 190, 24X Fiche 50-528.84/03/08.8403150094
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EIRENHUT.D G Division of Licensing 84/03/14 Atomic Bafety and Licensing Board Panel 10gp 24X Fiche 50-000,84/03/14/8402090041
- 8403i60048 Forwards updated preliminary description (Rev I) for RCS demonstration test VAN BRUNT, E E, RUGERS, A C Arizona Public Service Co 84/03/14 KN16HTON, G Licensing Branch 3 2pp 22659 169 24X Fiche 50-528,84/03/14,8403160048
- ---B403160052 Rev) to "RCS Demonstration Test "
 # Arizona Public Service Co 84/02/29 8pp 22659.171, 24X
 Fiche 50-528.84/03/14.8403160048
- 8403160065 Notifies that addl info & schedule re electrical equipment environ qualification program will be submitted by 840326, per 840227 request

 VAN BRUNT, E E Artiona Public Service Co 84/03/14 KNIGHTON, 0 Licensing Branch 3 lp 22652 326 24X Fiche 50-528, 84/03/14, 8403160065
- 8403290236 Forwards operations experience base, consisting of experience tables for presently licensed personnel Inadaquate number of personnel meet 6-wk hot participation experience requirement

 VAN BRUNTLE E Arizona Public Service Co 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 22800 236 24X Fiche 50-528,84/03/23,8403290236
- C Utility Environmental Report (ER), amends & correspondence
- 8403080390 Responds to FDIA request for 27 documents referenced in 1975 EIS re facilities & similiar environ documents Forwards App A Documents 1-10 Documents 11 to 12 available at NTIS FELTON.J M Division of Rules and Records 84/02/13 RYAN.J A Streich, Lang, Weeks & Cardon 2pp 22381 180 24X Fiche 30-528.84/02/13.8403080390
- ---B403080400 Discusses review of environ rept re transmission lines crossing Endian reservations Tribal council consent should be obtained for right-of-way before environ rept published Related info enci s interior. Dept of, Bureau of Indian Affairs 74/12/11 REOAN.W H Atomic Energy Commission - Deputy Director for Reactor Projects 5pp 22581 184 24X Fiche 50-528,84/02/13,8403080390
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8403080385 FOIA request for 27 documents referenced in 1975 EIS re facilities & similiar environ documents List & news articles ancl RYAN J. A Streich, Lang, Weeks & Cardon 84/01/17 Office of Administration 9pp 22581 171 24X Fiche 50-528,84/01/17, 8403080385
- 8403080390 Responds to FüiA request for 27 documents referenced in 1975 EIB re facilities & similiar environ documents Forwards App A Documents 1-10 Documents 11 & 12 available at NTIB FELTON.J M Division of Rules and Records 84/02/13 RYAN.J A Streich Lang, Weeks & Cardon 2pp 22581 180 24X Fichs 50~528,84/02/13,8403080390
- --BiO8270490 Submits Geosciences Branch DES input Updated summary Pf geology & seismology section FSAR will be included in SER JACKSUN-R E Geosciences Branch Bi/OB/14 MIRAGLIA-F Licensing Branch 3 2pp 22581 182 24X Fiche 50-528,84/02/13, 8403080390
- ---84030B0406 Comment on DEB, per 750414 request Statement somewhat blassed toward project More detailed maps of pipeline & transmission line corridors should be provided in final statement.

 DOREMUS, 8 D Interior. Dept of 75/07/23 REGAN Division of Reactor Licensing (NRR-1975 only) 2750 22501 189 24X
 Fiche 30-328,84/02/13,8403080390

- 8403290341 Responds to FOIA request for records re facility Ltr dtd B40117 failed to meet criteria for waiver of reproduction costs Forwards App A documents Address of Phoenix LPDR listed FELTON.J M Division of Rules and Records 84/02/27 RYAN,J A Streich, Lang, Weeks & Cardon 3pp 22815 018 24X Fichs 50-528.84/02/27.8403290341
- --B403290344 DRAFT ENVIRONMENTAL STATEMENT RELATED TO CONSTRUCTION OF PALD VERDE NUCLEAR GENERATING STATION, UNITS 1, 2 & 3 Docket Nos 30-529, 50-529 & 30-530 * 0ffice of Nuclear Reactor Regulation, Director NUREG-75/022 75/04/30 175pp 22815 301 24% Fiche 50-528,84/02/27,8403290341
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8403020005 Forwards info requested in SSER 5 (NUREO-0857) re tests performed for C-E on load limiting devices in reactor vessel lawer key horizontal supports VAN BRUNT, E E Arizona Public Service Co 84/02/10 KNIGHTON, G Licensing Branch 3 9pp 22442 201 24X Fiche 50-528, 84/02/10, 8403020005
- 8403090012 Forwards "High Pressure Safety Injection Pump," mechanical environ qualification rept, per SEER 5 (NUREO-0837) VAN BRUNTLE E Arliona Public Service Co 84/02/29 KNICHTON, O N Licensing Branch 3 2pp 22568 001 24X Fiche 50-528,84/02/29, 8403090012
- --8403070014 "High Pressure Safety Injection Pump," mechanical environ qualification rept HALLER,R E Dechtel Corp V-PAK-481 84/01/12 198pp 22548 004 24X Fiche 50-528,84/02/29,8403090012
- F Security, modical, emergency & fire protection plans
- 8402090006 Board Notification 84-034 forwards R Volimor 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EIBENHUT D G Division of Licensing 84/02/23 PALLADING Commissioners 1p 22576 203 24X Fiche 50-000,84/02/23, 8402090006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRR Ofc Ltr 19.6td 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT, D G Division of Licansing 10pp 22576 204 24X Fiche 50-000,84/02/23.8402090006
- 8403260014 Requests removal of App F & 9 from Rev 2 to Emergency Plan Implementing Procedure 7, per Generic Ltr 81-27 & GW Knighton 840214 Itr informing that util must request withholding of private or unlisted telephone numbers VAN BRUNT.E & Arliona Public Service Co 84/03/19 KNIGHTON.O W Licensing Branch 3 2pp 22750 258 24X Fiche 50-528,84/03/19, 8403260014
- @ Inspection reports, 18 Bulletins & correspondence
- B402140014 FOIA request for records re NRC const assessment team (CAT) imp at facilities

 BERNABEI.L Government Accountability Project B3/10/07 Office
 of Administration 2pp 22254 001 24X Fiche 50~528, B3/10/07,
 B402140014
- B40214001B Responds to FDIA request for records re NRC const assessment team (CAT) Insp at facilities Forwards App A documents Documents also in PDR App B documents listed for review to identify specific interest FELTON.J M Division of Rules and Records 83/12/20, GARDE.B P Government Accountability Project 18pp 22234 003 24X Fiche 50-528,83/12/20,8402140018
- --8402140022 Summarizes civil insp items, Bechtel 630929 ltr re reinsp of nuclear gipe hangers (Q class) & related info encl VORDERBRUEGGEN Region 5, Defice of Director 63/09/19, NARBUT,P NRC NO Detailed Affiliation Given 60pp, 22254:021 24X Fiche 50-028, 83/12/20,8402140018
- --8402140031 Comments on review of draft writeup on NDE Rewrite requested Related info enc!
 NARBUT,P NRC No Detailed Affiliation Given E3/09/27
 KERCH,H NRC No Detailed Affiliation Given. 41pp 22254,094
 24X Fiche 30-528,83/12/20.8402140018

- --8402140032 Summary of 830916 exit status meeting w/NRC const appraisal team re 830907-16 insp IDE.W E Arizona Public Service to 83/09/19 ROEDEL, J A Arizona Public Service to 6pp 22254 137 24X Fiche 30-528,83/12/20.8402140018
- --8402140036 Forwards marked-up Graft Insp scope & objectives Related info enc! ALBERT,N O Region 5, Office of Director 83/09/21 Young,T Region 5, Office of Director 18pp 22254 143 24X Fiche 30-528,83/12/20.8402140018
- --8402140043 Provides list of NDE repts available from insplactivities completed w/NRC mobile NDE van at facility, per FDIA request. Related Info encl EDNETER, S D Region 1, Office of Director 83/11/15 ALEXANDER: I M Region 3, Office of Director 99pp 22235 324 24X Fiche 50-528,83/12/20,8402140018
- --8402140048 Rev Q to "Polo Verde Station HPSI Sys Electrical & Instrumentation Const Audit Insp," final rept Related Info encl
 4 Zytor. Inc NRC-1E-82/83-46C 83/10/04 158pp 22256 063 24% Fiche 50-528, 83/12/20, 8402140018
- --8402140052 Provides resolution for loose bolts on structural steel found during NRC const assessment team (CAT) insp Item considered closed Related info encl FORRESTER.R D Artiona Public Service Co 83/09/24 IDE.W E Artiona Public Service Co 3pp 22256 221 24X Fiche 50-528,83/12/20,8402140018
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc 11st encl JORDAN, E t. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22709 239 24X Fiche 50-000.84/02/23,8401190072
- 8402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc 11st enc! GRACE. J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York. Inc 130pp 22552 327 24X Fiche 50-000/84/03/02/8402090007.
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprintler Sys Valves to Operate " Svc list encl JORDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 078 24X Fiche 50-000.84/03/02,8402090008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 83310J) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402070009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Bvc list encl JORDANE L. Division of Energency Preparedness & Engineering Response (Post 630103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22533 336 24X Fiche 50-000,84/03/05,8402070011
- 8403140024 Informs that Bingham-Williamette spare flange plece will be replaced by 840415 instead of 840229, due to problems encountered w/vendor, per IE Bulletin 83-06, "Nonconforming Matis Supplied By Tube-Line Corp"

 VAN BRUNT. E E Arizona Public Service Co 84/03/05 MARYIN, J B Region 5. Office of Director 1p 22639 217 24X

 Fiche 50-928,84/03/05,8403140024
- 8402090024 IE Info Notice 84-09. Rev i. "Lessons Learned Prom Inspa of Fire Protection 8afe Shutdown Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07. 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrusion Cracking in PWR Sys " Svc list enc! JORDANAE L Division of Emorgancy Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York: Inc 118pp 22584 186 24X Fiche, 50-000, 84/03/07, 8402090028
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031

- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 227 24X Fiche 50-000.84/03/21,8402090043
- 8402090044 JE Info Notice 84-20. "Svc Life of Relays in Safety-Related Sys " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 30-000,84/03/21,8402090044

S Reportable occurrences, LERs & related correspondence

- 8403090087 Interim Deficiency Rept B3-81 re Schedule 160 89 pipe supplied by Oulfalloy. Inc. containing mfg min wall thickness defect Initially reported on 831128 No new info presently available final rept expected by 840417 VAN BRUNT. E Arizona Public Service Co 84/02/22 BISHOP.T W Division of Resident. Reactor Project & Engineering Programs 2pp 22575 325 24X Fishe 50-528.84/02/22.8403090087
- 8403090258 Interim Deficiency Rept DER 83-75 re improperly torqued boits securing two DGI265A panel filler assemblies, supplied by Foxboro No new info available at present time Final rept will be submitted by 840419

 VAN BRUNT, E E Arizona Public Service Co 84/02/22 BISHDP, T W Division of Resident. Reactor Project & Engineering Programs 2pp 22572 211 24X Fiche 50-528.84/02/22.8403090258
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Campei NPS-4 T&T valve, to close, Encl itr dtd 840203 sent to listed utils GE notified of affected units in BWR plants
 THEROUX.R R Terry Corp 84/02/22 WOODRUFF, R W Director's Office. Office of Inspection and Enforcement 6pp 22706 327 24X Fiche 50-000.84/02/22.8403210032
- B402270008 Forwards response to listed items identified in B40125 telcon request for info generated based on preliminary review of B31230 deficiency rept re missing thermal liner in safety injection sys line Encls withheld VAN BRUNT.E E Arizona Public Service Co B4/02/24 KNIGHTON.O Licensing Branch 3 3pp 22516 186 24X Fiche 50-528.84/02/24, B402270008
- 8403090096 Deficiency Rept DER 83-73 re unqualified Forboro power supplies installed in IE instrument cabinets Initially reported on 831027 No new info presently available Next rept will be provided by 840425
 VAN BRUNT, E E ATIZONA PUBLIC SERVICE CO 84/02/24 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 22576 179 24X Fiche 50-528, 84/02/24, 8403070076
- 8403090167 interim Deficiency Rept DER 82-80 re low insulation resistance on installed Conax electrical penetrations not meeting qualification test criteria initially reported on 821217 Final rept delayed until 840425
 VAN BRUNT.E E Ariona Public Service Co 84/02/24 BISHOP,T W Division of Resident.Reactor Project & Engineering Programs 2pp 22575 116 24X Fiche 50-528,84/02/24,8403090167.
- 8403060427 Requests add1 info needed to complete evaluations of & fixes for reactor coolant pump problems encountered during hot functional tosting Response requested within 2 wits KNIGHTON.O U Licensing Branch 3 84/02/27 VAN BRUNT, E Arizona Public Service Co Spp. 22552 210 24X Fiche 30-328.84/02/27, 3403060427.
- 8403120032 Final Deficiency Rept DER 83-70 re wiring in emergency response facility cabinets supplied by Energy, Inc not in conformance w/IEEE-384 criteria Initially reported on 831011 Drawings resubmitted Also reported per Part 21 VAN SRUNT, E E Arizona Public Service Co 84/02/28 BISHOP, T W Division of Resident Reactor Project & Engineering Programs, App 22588 025 24% Fiche 50-528, 84/02/28, 8403120032
- 6403120069 Final Deficiency Rept DER 83-10 re main steam relief valves supplied by C-E & mfg by Dresser Industries exceeding specified 5% bloodown limit initially reported on 830228 Deficiency determined not reportable per IOCFR50. 55(e) VAN BRUNT.E E Arizona Public Service Co 84/02/28 BISHOP.T.W Division of Resident/Reactor Project & Engineering Programs 4pp 22591 129. 24X Fiche. 50-528.84/02/28.8403120069
- 8403130447 Potential Deficiency Rept DER 83-64 re Target Rock pressure relief valves failing to meet prerequisite tests Final rept delayed until 840402 VAN BRUNT, E E Arizona Public Service Co 84/02/28 BISHDP, T W Division of Resident Reactor Project & Engineering Programs. 2pp 22613 212 24X Fiche 50-528,84/02/28,8403130449

- 8403130461 Potential Deficiency Rept DER 63-68 re Borg Warner HPBI isolation valves failing to open against HPBI A & B pump flows Final will rept delayed until 640417 VAN BRUNT.E E Arriona Public Service Co 84/02/28 BISHOP.T U Division of Resident.Reactor Project & Engineering Programs 2pp 22613 355 24X Fiche 50-528.84/02/28.8403130461
- 8403200115 Interim Deficiency Rept DER 83-80 re Anchor Darling main feedwater isolation valves closing in 20 s.violating 5 s spec requirement initially reported on 831122 Final rept will be delayed until 840403 due to extensive investigation VAN DRUNTLE Arizona Public Service Co 84/03/02 BISHOP, T W Division of Resident Reactor Project & Engineering Programs 2pp 22685 335 24X Fiche 50-528,84/03/02.8403200115
- B403200160 Interim Deficiency Rept DER 84-07 re extension of Dorg Warner valve stems & failure to provide corrective action stated in Rept DER 80-21 initially reported on 840209 Bechtel investigating corrections Final rept by 840416 VAN BRUNT.E E Arizona Public Service Co 84/03/02, BISHOP, Y W DIVISION of Resident.Reactor Project & Engineering Programs Opp. 22697 131 24X Fiche 50-529.84/03/02.8403200160
- 8403200186 Interim Daficiency Rept DER 83-36 re discrepancies w/MSIVs mfg by Anchor-Darling initially reported on 830808 investigation will be finalized by 840413 at which time complete rept will be submitted VAN BRUNT, E E Arizona Public Service Co 84/03/08 BISHOP, T W Division of Resident. Reactor Project & Engineering Programs 2pp 22686 339 24X Fiche 30-328,84/03/08,8403200186
- B403200226 Interim Deficiency Rept DER 84-06 re defective absolute & deviation alarm modules supplied by Foxboro C-E requested that all alarm modules w/date Codes 8048-8152 be inspected for potential defect Next rept by 840612 VAN BRUNT, E E Arisona Public Service Co 84/03/07 BISHOP, T W Division of Resident. Reactor Project & Engineering Programs 3pp 22679 338 24x Fiche 50-528,84/03/07,8403200226
- 8403230039 Final Deficiency Rept DER-83-79 re ac interference spikes on 123-volt dc bus exceeding spec initially reported on 831118 Deficiency deemed not reportable per 100FR90 55(e) VAN DRUNT, E E Arizona Public Service Co 84/03/09 BIBHOP, T, W Division of Resident. Reactor Project & Engineering Programs 4pp 22730 302 24X Fiche 50-528,84/03/09,8403230039
- 8403230086 Final Deficiency Rept DER 83-60 re failure of wiring in Vitro main steam & feedwater activation sys to meet IEEE-384 separation criteria Condition determined not reportable per IOCFR50 55(e) VAN BRUNT.E E Arizona Public Service Co 84/03/07 BISHDP.T W Division of Resident.Reactor Project & Engineering Programs 4pp. 22724 339 24X Fiche 50-530.84/03/09.8403230086
- B403230097 Final Deficiency Rept DER 83-72 re undersize welds in auxiliary bidg Initially reported on B31026 Condition determined not reportable per 10CFR50 55(e) VAN BRUNT, E E Ariona Public Service Co 84/03/14 BISHOP, T. W Division of Resident, Reactor Project & Engineering Programs 6pp 22720-356 24X Fiche 50-526, B4/03/14:8403230079
- 8403230019 Pinal Deficiency Rept DER 82-46 re ITT Barton pressure transmitters supplied by C-E not meeting overpressure requirements Caused by leakage of metalic washers & methodology error during calibr Also reported per Part 21 VAN BRUNT, E. Arizona Public Bervice Co. 84/03/15 BISHOP,T W Division of Resident, Reactor Project & Engineering Programs 7pp 22724 353 24% Fiche 50-528,84/03/15,8403230019
- 8403300096 Interim Deficiency Rept DER 84-08 re ITT Barton Model 763 transmitters having errors of -2 to -3% of calibr span Bechtel corresponding w/C-E to determine impact of design mods to transmitters VAN BRUNT, E E Arizona Public Service Co 84/03/16 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs, 3pp 22822 010, 24% Fiche 50-529,84/03/16,8403300096
- 8403300020 Rev 1 to final Deficiency Rept DER 82-46 re ITT-Barton pressure transmitters supplied by C-E failing to meet overpressure requirements Initially reported on 820824 Also reported per Part 21 VAN BRUNT: E Arizona Public Service Co 84/03/19, BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 7pp. 22822.171 24X Fiche 50-528,84/03/19,8403300020

V Operator Examinations

8403290236 Forwards operations experience base, consisting of experience tables for presently licensed personnel Inadequate number of personnel meet 6-wk hot participation experience requirement

VAN BRUNT, E E Arizona Public Service Co 84/03/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 17pp 22800 236
24X Fiche 50-528, 84/03/23, 8403290236.

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

- A Application/construction stage documents & correspondence
- 8403090219 Forwards applicant responses to Commission 811224 order on behalf of Project Mgt Corp & TVA
 CHIPHAN, 0 L Energy, Dept of 82/01/18 PALLADINO, N J .
 GILINSKY, V , ROBERTS, T F Commissioners 101pp 22574:168 24X
 Fichs 50-537, 82/01/18, 8403090219
- 8403020014 Partial response to FDIA request for seven categories of socuments re NRC regionalitation program App A documents in PDR. Review of remaining documents incomplete FELTON, J M Division of Rulas and Records 83/12/16 LDHENTHAL, J Nuclear Information & Resource Service 3pp 22472 248, 24% Fiche, 50-000, 83/12/16, 8403020014
- --840302005i Informe that MK Udall Subcommittee on Energy & Environ marked-up & reported 1984-85 NRC authorization bill to Interior Committee for future consideration NRC authorization bill HR 2510 & 830420 amende encl KAMMERER.C Office of Congressional Affaire 83/04/20 PALLADING, 01LINGKY, AHEARNE Commissioners. 11pp 22493 326 24X Fiche 50-000,83/12/16,8403020014
- 8403080070 Forwards Page 15 inadvertently emitted from 840227 transmittal of draft CRBR plant redress plan. Related correspondence.

 OROSS, P. J. Enargy, Dept. of, Clinch River Bresder Reactor Plant 84/03/02 KING.T. Clinch River Bresder Reactor Program Office 2pp. 22559 265. 24X Fiche 50-537.84/03/02.8403080090
- 8403060337 Forwards "Bite Redrese Plan" Minor clarifications & corrections to draft plan submitted 840227 made in response to NRC comments
 OAVIGAN, FX Energy, Dept of 84/03/05 KING, T Clinch River Breader Reactor Program Offica ip 22519 169 24X
 Fiche: 30-537, 84/03/05, 8403060357
- --8403060360 "Site Redress Plan" * Energy, Dept of 84/03/31 36pp 22519 170 24x Fiche 50-537,84/03/05,8403060357
- 8403230216 AN ASSESSMENT OF CRBR CORE DISRUPTIVE ACCIDENT ENERGETICS THEOFANOUS, T O , BELL. C R. Los Alamos Scientific Laboratory FIN A-7271 NOREO/CR-3224 B4/03/31 Clinch River Breeder Reactor Program Office 436pp Available at NRC 88 50 22740:001. 24X Ficha. 50-537, 84/03/31. 8403230216

O Adjudicatory correspondence

- 8403050068 Memorandum & order denying appeals of ASLB determination to limit intervenor participation in proceedings on remand to limited appearance statement. Opinion of Dr Johnson encl. TOMPKINS: B A Atomic Safety and Licensing Appeal Panel 84/02/29 16pp 22490 164 24X Ficha 50-537.84/02/29.8403050068
- 8403020100 Forwards Page 15 of CRBR program redress plan, inadvertently omitted from 840227 transmittal Certificate of Svc enci EDOAR, 9 L. Newman & Holtzinger EDOAR, 9 L. Project Management Corp 84/03/01 MILLER, M E , HAND. C. LINENBERGER, 9 Atomic Safety and Licensing Board Panel. 5pp 22442, 096 24X Ficha. 50-537: 84/03/01.8403020100.
- 8403060082 Petition for review of Appeal Board 840229 memorandum & order readmitting intervenore to proceedings Intervenor perticipation will protract proceeding for project which is terminated, Certificate of Syc enci
 EDGAR, G. L. Project Management Corp LUCK, W.D. Energy, Dept. of, 84/03/05, 4pp 22516 345 24X Fiche 50-537,84/03/05,8403060082
- B403090056 Forwards final CRBR eite radrees plan for review & approval Related correspondence W/o encl GAVIGAN,F.X. Energy, Dept of 84/03/05, KIND,T Clinch River Breeder Reactor Program Defice ip 22375,349 24X Fiche,30-537,84/03/05,8403090054
- 8403090084 Confirms that ASLB intends to vacate notice of 840314 conference & raschedule later date due to delay in funding for review of redrese plan & possible lack of availability of one ASLB member. Certificate of 8vc encl EDGAR. Q. L. Newman & Holtzinger EDGAR. Q. L. Project Management Corp 84/03/08, MILLER. M. E. HAND. C., LINENBERGER. Q. Atomic Safeti and Licensing Board Panel. 5pp. 22375:320, 24% Fiche: 50-537.84/03/08.8403090086,

- 8493190047 Informs of receipt & consideration of 840305 petition for Commission review of ALAB-761 re readmitting intervenors to proceeding Staff prepared to file brief addressing issues in event Commission grants petition for review TREBY.8 A Hearing Branch 1 84703/15 CHILK,S J Office of the Secretary of the Commission ip 22666 250 24X Fiche 90-537,84703/15,8403190047
- 8403190120 Answer to applicant petition for review of ASLB \$40229 memorandum & order re CRBR LWA proceedings on site redress plan Intervenors main contern is that redress be rapid & effective W/Certificate of Svc FINAMORE.B A Natural Resources Defense Council FINAMORE.D A Bierra Club 84/03/15 Commissioners 10p 22666 296 24% Fiche 50-537,84/03/15,8403190120
- DOCKET 50-538 MEMPHIS STATE UNIV RESEARCH REACTOR

 R Periodic operating reports & related correspondence
- 8403230060 "Annual Rapt of Nuclear Reactor Operations, 1983 " W/840317 ltr JUNES, D W., DIETZ, R L. Memphis State Univ. Memphis. TN 83/12/31 1898. 22730:284 24X Ficha 50-538.83/12/31.8403230060
- DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT L

 A Application/construction stage documents & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, 8 1 Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fichs 50-000.84/02/13.8403080179
- F Security, medical, emergency & fire protection plans
- 8403120058 Notifies of 840323 workshop on fire protection safe shutdown requirements of 10CRt50. App R in Rosemont, IL to discuss IE Info Notice 84-07 & provide addi shutdown analyses &/or mod guidance. Aganda encl SPE88ARD. R L Division of Emergancy Preparedness & Operational Support 84/07/06 SHIELDS. B P public Service Co of Indianalinc Spp 22586 282 24X Fiche 50-546.84/03/06.8403120058
- G Inspection reports, IE Bulletins & correspondence
- 8401190872 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl URPAN. L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22907 239, 24X Fichs 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Racent Transport Regulatory Revs by DDT & NRC " Svc list encl ORACE.J N Division of QA, Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 130pp 22552 329 24X Fishe 50-000.84/03/02,8402090007.
- 8402070008 IE Info Notice 84~i6. "Failure of Automatic Sprinkler Bys Valves to Operate." Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 8301031. B4/03/02 Consolidated Edison Co of New York, Inc. 122pp 22553 098 24X Fiche 30-000,84/03/02,8402070008
- B402090009 IE Info Notice B4-15, "Reporting of Radiological Releases"

 Svc list enci.

 JORDAN, EL Division of Emergency Proparedness & Engineering
 Response (Post 830103) B4/03/02 Consolidated Edison Co of New
 York, Inc. 11989 22553 217 24X Fiche 50-000, 84/03/02, 8402090009
- 8402090011 IE Info Notice 84-17, "Froblems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L Division of Energency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- B402090024 IE Info Notice 84-09, Rev I. "Lessone Learned from Insps of Fire Protection Sefe Shutdown Sys " Syc list snc1.

 JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co. of New York, Inc 11899. 22635 049. 24X Fiche. 50-000, 84/03/07, 8402090024

- 8402090028 IE Info Notice 64-18. "Stress Corrosion Cracking in PHR Sye " Syc list enc! JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000.64/03/07.8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl
 DEYBUND, R C Director's Office, Office of Inspection and
 Enforcement 84/03/12 Consolidated Edison Co of New York, Inc
 134pp 22823 094 24% Fiche 50-000.84/03/12.8402090031
- 8403190286 Discusses Dept of Labor decision re 830120 termination of electrical contractor personnel & forwards notice of violation KEPPLER.J G Region 3, Office of Director 84/03/14 SHIELDS.S & Public Service Co of Indiana. Inc 2pp 22673 186 24X Fiche 30-946.84/03/14.8403190286
- --8403190294 Notice of violation based on investigation & hearing by Dept of Labor Noncompliance noted discrimination by licensee or contractor against employee for engaging in certain protected activities

 KEPPLER.J G Region 3, Office of Director 84/03/14 2pp. 226/3 188 24% Fiche 50-546,84/03/14.8403190286
- 8402090043 IE Info Notice 84-i9, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24% Fiche 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Sys " Svc list ent! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- S Reportable occurrences, LERs & related correspondence
- 8493i40i22 Part 21 rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circultry DOOSON.J P Pacific Air Products Co 84/03/09 Director's Office, Office of Inspection and Enforcement 7pp 22624 068 24X Fiche 50-000,84/03/09.8403140122
- 8403270219 Part 2t rept re broken contact carrier in control device of 7 5 kV-15 kV,500-750 MVA,5 kV 350-3.000 & all HKV circuit breakers initially reported on B30223 Addenda to installation & maint procedures sent to affected units DUVALL,D D Brown Boveri Corp (subs of Brown Boveri Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk). Spp 22772 114 24X Fiche 50-000,84/03/19,8403270219
- DOCKET SIN-50-347 MARBLE HILL NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELION.J M Division of Rules and Records 84/02/13 ANDERSON,S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 30-000,84/02/13.8403080179
- F Security, medical, emergency & fire protection plans
- 8403120058 Notifies of 840323 workshop on fire protection safe shutdown requirements of JOCRESO. App R in Resement, IL to discuss IE Info Notice 84-09 % provide add1 shutdown analyses &/or mod guidance Agenda enci
 SPESSARD. R L Division of Emergency Preparedness & Operational Support 84/03/04 SHIELDS. 8 M Public Bervice Co of Indiana. Inc 3pp 22586 282 24X Fiche 50-546.84/03/06.8403120058
- G Inspection reports. IE Bulletins & correspondence
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Volve Control Circuits & Annunciation " Bvc list enc!

 JORDAN, E. L. Division of Emargency Preparedness & Engineering Response (Post 830103) 84/02/28 Consultdated Edison Co. of New York, Inc. 115pp 22909 239 24X Fichs 50-000,84/02/28,8401190072

- 8402070007 IE Info Notice 64-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRRCE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02,8402070007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys-Valves to Operate " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22953 098 24X Fiche 50-000,84/03/02,8402090008
- 8402070007 JE Info Notice 84-15, "Reporting of Radiological Releases" Syr list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 117pp 22593 217 24X Fiche 50-000,84/03/02,8402070007
- B402070011 IE Info Notice B4-17. "Problems W/Liquid Nitrogen Cooling Components Oslow Nil Ductility Tamp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Ficha 50-000.84/03/05,8402070011
- 8402070024 IE info Notice 84-09.Rev l. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402070028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Sys " Syc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000.84/03/07.8402090028
- E402090031 IE Bulletin 84-02, "Failures of GE Type HFA Rolays in Use in Class IE Safety Sys " Svc list enc!

 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000,84/03/12,8402090031
- B403190286 Discusses Dept of Labor decision re B30120 termination of electrical contractor personnel & forwards notice of violation
 KEPPLER.J G Region 3, Office of Director B4/03/14 SHIELDB,S W Public Service Co of Indiana, Inc 2pp 22673 186 24X Fiche 50-546.84/03/14.8403190286
- --8403170294 Notice of violation based on investigation & hearing by Dept of Lebor Noncompliance noted discrimination by licensee or contractor against employee for engaging in certain protected activities

 KEPPLER, J G Region 3, Office of Director 84/03/14 2pp 22673 188 24X Fiche 50-546,84/03/14,8403170286
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 630103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 227 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JÜRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- S Reportable occurrences. LERs & related correspondence
- B403i40i22 Part 2i rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry DDBSON, J P Pacific Air Products Co 84/03/09 Director's Office, Office of Inspection and Enforcement 7pp 22624 068 24% Fiche 50-000,84/03/09,8403i40i22
- B403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV,500-750 MVA,5 kV 350-3,000 & all HKV circuit breakers Initially reported on B30223 Addenda to installation & maint procedures sent to affected units DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.) B4/03/19 Record Services Branch (Document Control Desk) 5pp. 22772 114 24X Fiche 50-000,84/03/19,8403270219

- DOCKET STN-30-553 PHIPPS BEND NUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- B403160345 Extends invitation to attend region 840316 workshop at regional ofc to discuss 10CFR50. App R requirements & recent results of insp to help resolve misunderstandings associated w/requirements

 LEWIS, R C Division of Project & Resident Programs 84/03/02 PARTIS, H G Tennessee Valley Authority 2pp 22660 083 24X Fiche 50-000.84/03/02, 8403160345
- 8 Reportable occurrences, LERs & related correspondence
- B403230028 Followup Part 21 rept re nuclear valve/actuator stroking time possibly lengthened beyond 15 s when using hydrocarbon-based lubricants Ltrs to affected utils enci WILSON, A K Henry Pratt Co 84/03/08 KEPPLER, J G Region 3, Office of Director App 22730 306 24X Fiche, 50-000, 84/03/08, 8403230028
- B403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV.500-790 MVA.5 kV 350-3.000 & all HKV circuit breakers initially reported on 830223 Addenda to installation & maint procedures sent to affected units.

 DUVALL.D D Brown Boverl Corp. (subs of Brown Boveri & Co , Ltd) B4/03/19 Record Services Branch (Document Control Desk) 5pp 22772,114 24X Fiche 30-000.84/03/19.8403270219
- DDCKET STN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2

 8 Reportable occurrences, LERs & related correspondence
- 8403230028 Followup Part 21 rept re nuclear valve/actuator stroking time possibly lengthened beyond 15 s when using hydrocarbon-based lubricants Ltrs to affected utils encl MILSON, A K Henry Pract Co 84/03/08 KEPPLER, J @ Region 3, Office of Director. 6pp 22730 306 24X Fiche 50-000,84/03/08, 8403230028
- 8403270219 Part 21 rept re broken contact carrier in control device of 7.5 kV-15 kV.500-750 MVA, 5 kV 350-3.000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units, DUVALL, D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Dask) 5pp 22772 i14 24X Fiche 50-000,84/03/19,8403270219

DOCKET STN-50-556 BLACK FOX STATION, UNIT 1

A Application/construction stage documents & correspondence

- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 9) Review of addI documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/19 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp. 22383 R26 24X F1che 30~000,84/02/19,8403080179
- --8102200029 Forwards action glam for resolution of non-TMI issues for punding CP/mfg license applications, per Dfc of Nuclear Reactor Regulation approach to resumption of licensing Bafety evaluation inputs should be provided by 810601.
 EIBENHUT.D.O. Division of Licensing 80/12/31. VOLLMER, R Division of Engineering 1p 22583 277 24X Fiche 50-000,84/02/13,8403080179

G. Adjudicatory correspondence

- 840:301:0050 Third partial response to FDIA request for slx categories of documents re facility. Forwards App A documents, App A documents also placed in FDR App B documents will be placed in FDR upon request Review continuing FELTON, J.M Division of Rules and Records 84/01/17 ANDERSON, S J Garvey, Schubert, Adams & Barer, 4pp 22446 273 24X Fiche. 50-000, 84/01/17, 8403010050

- --8305090506 Requests advice refee assessment cutoff date for reactor CP & OL applications that are withdrawn.denied.suspended, cancelled or postponed MILLER.W O License Fee Management Branch 83/05/04 FONNER.R L Office of the Executive Legal Director 3pp 22446 315 24X Fiche 50-000,84/01/E7,8403010050
- B403230186 Requests reconsideration of 801009 split vote to release Reed Rept & Sub-Task Force Repts Return of repts requested Separate views of Commissioner Hendrie & Certificate of Svc encl
 EDOAR.G L. Newman & Holtzinger EDOAR.G L. General Electric Co DBD 073 84/03/22 PALLADING.N J. ASSELSTINE.J K., ROBERTS.T M. COmmissioners 11pp 22743 061 24% Fiche 50-556.84/03/22,
- DOCKET STN-50-957 BLACK FOX STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 84030B0179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 3) Review of addl documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERSON, 8 I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 30~000,84/02/13,8403080179
- --8102200029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications.per Ofc of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by \$10201 EISENHUT.D o Division of Licensing 80/12/31 VOLLMER, R Division of Engineering 1p 22583 277 24X Fiche 50-000,84/02/13,8403080179
- O Adjudicatory correspondence
- 8403010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in PDR upon request Review continuing FELTON.J M Division of Rules and Records 84/01/17 ANDERSON.S 1 Darvey, Schubert, Adams & Marer App 22446 293 24% Fiche 50-000,84/01/17,8403010050
- --8211090018 Advises that brench will wait to determine what action util plans to take in response to ASLB 820618 order before collecting prof NRC hours & contractual costs & billing util for review of withdrawn application
 MILLER, W O License Fee Management Branch 82/10/04 License Fee Management Branch 1p 82446 323 24X Fiche 50-000.84/01/17.8403010050
- --B305090506 Requests advice re fee assessment cutoff date for reactor CP to UL applications that are withdrawn, denied, suspended, cancelled or postponed MILLER, M O License Fee Management Branch B3/05/04 FONNER, R L Office of the Executive Legal Director 3pp 22446 315 24X Fiche 30-200, 84/01/17, 8403010050
- 8403230186 Requests reconsideration of B01007 split vote to release Reed Rapt & Bub-Task Force Repts Return of repts requested Beparate views of Commissioner Hendrie & Certificate of Svc encl
 EDQAR.O L Newman & Holtzinger EDQAR.O L General Electric Co
 DBB 073 B4/03/22 PALLADINO,N J . ASSELBTINE; J K . ROBERTS: T M
 Commissioners 11pp 22743 061 24X Fiche 50-556,84/03/22.
- DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT i
- 8403280233 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by license, per Bio707 Generic Ltr 81-27 W/o request entire plan will be placed in PDR KNIGHTON. 9 W Licensing Branch 3 84/03/07 PARRIS. H 0 Tennessee Valley Authority 3pp. 22789 341 24X Ficher 50-566, 84/03/07, 8403280233
- 8 Reportable occurrences, LERs & related correspondence
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 3 kV-15 kV, 300-750 MVA.5 kV 330-3.000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL.D D Brown Boveri Carp. (subs of Brown Boveri & Co . Ltd ? 84/03/19 Record Services Branch (Document Control Deak) 5pp 22772 114 24X Fiche 50-000.84/03/19.8403270219

DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT. UNIT 2

F Security, medical, emergency & fire protection plans

8403280233 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by license, per 810709 Generic Ltr 81-27 W/a request, entire plan will be placed in PDR KMIGHTON. G W Licensing Branch 3 84/03/07 PARRIS. H O Tennessee Valley Authority 3pp 22789 341 24x Fiche 50-566, 84/03/07, 8403280233

S Reportable occurrences. LERs & related correspondence

8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV,500-750 MVA:5 kV 350-3,000 & all MKV circuit breakers initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.) 84/03/19 Record Services Branch (Document Control Dest.) 3pp 22772 114 24% Fiche 50-000.84/03/19.8403270219

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DUCKET 70-0027 BASCOCK & WILCOX CO . LYNCHSURG, VA

- 8401240304 Ack receipt of 831214 itr informing NRC of steps taken to correct violations moted in 1E Insp Rept 70-0027/83-19
 D'REILLY,J P Region 2, Office of Director 84/01/10 ECKERT,J P Babcack / Wilcox Co ip 21909 237
- --8401240315 Responds to NRC 831115 ltr re violations noted in IE Insp Rept 70-0027/83-19 Corrective actions sys of notification established when byproduct license certification requested & health physicist added to radiation control staff ECKERT.J P Babcock & Wilcox Co 83/12/14 O'REILLY,J P Region 2, Office of Director 8pp 21909 238
- 8403320t67 Application for amend to License SNM-42 revising Section IV re fundamental nuclear matis control plan to provide production scheduling flexibility for research reactor fuel Amend fee and ## 8 Bacock & Hilcor Co 84/01/31 BROWN,W B Fuel Facility Safeguards Licensing Branch 1p 22491 134
- 8403090197 Requests all correspondence distributed to NRC regional ofc re SNN mat) control & accounting & physical protection Correspondence will enable more timely awareness of issues that may exist w/regional ofc BROWN, W B Fuel Facility Safeguards Licensing Branch 84/02/07 REGAN, N Gaboock & Wilcox Co 2pp 22528 182
- 8403070146 Ack receipt of 830909, 1007 & 1214 ltrs informing NRC of steps taken to correct violations noted in IE lnsp Rept 70-0027/83-14
 STOHR.JP Division of Emergency Preparedness & Materials Bafety 84/02/08 ECKERT.JP Babcock & Wilcor Co ip 22547 267
- --5403070147 Responds to NRC 83it17 ltr re violations noted in IE Insp Rept 70-0027/83-14 Corrective actions control limits for each std will be calculated from data generated for each std within one inventory period ECKERT.JP Babcock & Wilcox Cp 83/12/14 D'REILLY.JP Region 2. Office of Director 2pp 22347 268
- --6403070153 Responds to NRC 830811 ltr re violations noted in IE Insp Rept 70-0027/83-14 Corrective actions control limits for finished fuel.UNH dissolver feed & isotopic measurement sys recomputed ECKERT.JP Babcock & Wilcor Co 83/09/08 O'REILLY.JP Region 2. Office of Director 3pp 22547 270
- 8403300041 Forwards 1E Insp Rept 70-0027/84-02 on 840123-27 STOHR.J P Division of Emergency Preparedness & Materials Safety 84/02/15 ECKERT,J P Datcock & Wilcox Co 2pp 22821 340
- --B403300044 IE insp Rept 70-0027/B4-02 on B40123-27 Noncompliance noted failure of guards of carry all required equipment & adequately test & meintain protected area fence Details withheld ENNIB.J D Region 2. Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety B4/02/14 ip. 22821 342
- 8403050205 Forwards request for add1 info re 840126 request for exemption from 10CFR70 38(1)(2) re long-term storage of scrap Encl withheld (ref 10CFR2 76)
 BRGUNN W B Fuel Facility Safeguards Licensing Branch 84/02/21 REOAN, N A Babcock & Wilcox Co 19 22528 154

- 8403070326 Forwards IE Insp Rept 70-0027/84-03 on 840124-27 No violations or deviations identified BTOHR.J P Division of Emergency Preparedness & Materials Safety 84/02/23 ECKERT.J P Babcock & Wilcox Co ip 22346 328
- --8403070328 IE Insp Rept 70-0027/84-03 on 840124-27 No noncompliance noted Major areas inspected mgt of matl control sys & internal control Details withheld (ref 100FR2 790 & 73 21) JONES.D W Region 2. Office of Director MCALPINE.E J Division of Emergency Preparedness & Materials Bafety B4/02/13 ip 22546 327
- 8403050361 Responds to 840131 & 0216 ltrs re Ontario-Hydro scrap processing contract B&W wiil composite isotopic samples of dissalver solution on U-weighted daily basis & assay each composite for U-235
 BROWN. W B Fuel Facility Bafeguards Licensing Branch 84/02/24
 TRENT. L K Babcock & Wiicox Co 1p 22501 338
- 8403160286 Forwards proprietary IE Insp Rept 70-0027/84-01 on 840116-20 No violations or deviations identified Rept withheid (ref 100FR2 790 & 73 21)
 810HR,J P Division of Emergency Preparedness & Materials Safety 84/03/07 ECKERT,J P Babcock & Wilcox Co 2pp 22660 203
- 8403260179 Forwards IE Insp Rept 70-0027/84-05 on 840312-16. No violations or deviations noted STURA, J P Dyision of Emergency Preparedness & Materiels Rafety 84/03/22 ECKERT, J P Babcock & Wilcox Co 2pp 22756 150.
- --8403260183 IE Insp Rept 70-0027/84-05 on 840312-16 No noncompliance noted Major areas inspected security organization.records & repts. locks, keys & combinations & physical barriers Details withheld (ref 10CFR75)

 ENNIS.J D Region 2. Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 84/03/22 Ip 22756:152
- B4033000is Ack receipt of B403i5 ltr informing NRG of steps taken to correct violations noted in IE Safeguards insp Rept 70-0027/84-02 STONR, J P Division of Emergency Preparedness & Materials Safety B403/86 ECKERT, J P Babcock & Wilcox Co ip 22822 137
- --8403300015 Responds to NRC 840215 ltr re violations noted in [E Safeguards Imap Rept 70-0027/84-02 Corrective actions Withheld (ref iOCFR2 790) ECKERT.J P Babcock & Wilcox Co 84/03/15 D'REILLY.J P Region 2. Office of Director ip 22822 i38
- 8403270267 ENVIRONMENTAL IMPACT APPRAISAL FOR RENEWAL OF SPECIAL NUCLEAR MATERIAL LICENSE NO SMM-42 Docket No 70-27 (Babcock & Wilcox Company, Naval Nuclear Fuel Division) * Division of Fuel Cycle & Material Safety NUREG-1049 B4/03/31 B7pp Available at NRC \$4 50 22787 235
- DOCKET 70-0036 COMBUSTION ENGINEERING, INC., WINDSOR, CT
- 8403270273 Informs of issuance of Amend 1 to License SNM-33 redecommissioning of evaporation ponds
 PAGE,R, 0 Uranium Fuel Licensing Branch 84/03/08 ESKRIDGE,H & Combustion Engineering, inc. ip 22789 244
- DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC , ERWIN, TN
- 8403050363 Grants 840117 request for 7-day extension for completing certain requirements of 100FR70 5(e)(4) for 831228 high-enriched U physical inventory, BURNETF, RF Division of Safeguards 84/01/19 HENSLEY, K. D. Nuclear Fuel Services, Inc (subs of Getty Dii Co) Ip 22527 317
- 8403160325 Forwards IE Enforcement Conference Rept 70-0143/84-06 on 840216 D'REILLY, J.P. Region 2, Office of Director 84/02/24 GUINN, F.K. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) Ip. 22459-158
- --B403160387 IE Enforcement Conference Rept 70-0143/84-06 on B40216 Major areas discussed nuclear criticality safety violations. KARLE, J B Region 2, Office of Director, MCALPINE, E J. Division of Emergency Preparedness & Materials Safety B4/02/24 3pp. 22639 159

i

- 8403020176 PNO-II-84-017 on 840227 power to plant lost due to power outage caused by high winds Licensee declared unusual event & initiated plant radiological contingency plan Backup power continued to function KAMLE, J 8 , MCALPINE, E J Region 2, Office of Director 84/02/27 2pp. 22437 001
- 8403160337 Forwards IE Safeguards Insp Rept 70-0143/84-02 on 840130-0203 No violations or deviations identified 8TCHR.J P Division of Emergency Preparedness & Materials Safety 84/02/27 OUINN.F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 22660 ii8
- --8403160353 IE Bafeguards Insp Rept 70-0143/84-02 on 840130-0204 No noncompliance noted Major areas inspected measurements & statistical controls Details withheld (ref 10CFR2 790 & 73 21)
 RICHARDS B L Region 2, Office of Director MCALPINE, E J Division of Emergency Preparedness & Materials Bafety 84/02/27 ip 22660 120
- 8403050220 Responds to 831221 Itr w/two requests for exemption from 10CFR70 57(b)(ii) re control charts First request approved New License Condition 4 10 to Amend MPP-1 to License SMM-124 encl Second request requires add1 demonstration BROWN.W B Fuel Facility Bafeguerds Licensing Branch 84/02/28 HENSLEY,K D Nuclear Fuel Services, Inc (subs of Getty Oil Co) 4pp 22528 110
- 8403160138 Ack receipt of 840201 ltr informing NRC of steps taken to correct violation noted in IE has Rept 70-0143/83-47 STOHR, J P Division of Emergency Preparedness & Materials Safety 84/02/28 QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Dit Co) ip 22635 210
- --8403160173 Forwards IE Insp Rept 70-0143/83-47 on B31003-1202 & notice of violation Notice of violation & insp rept withheld (ref 100FR2 790)
 BYOUR, J P Division of Emergency Preparedness & Materials Safety
 B4/01/05 GUINN, F K Nuclear Fuel Services, Inc (subs of Getty
 G11 Co) 2pp 22655 214
- 8403140377 Discusses 1E Enforcement Conference Rept 70-0143/84-04 on 840216. Item 3 a of licensee commitments on Page 2 of rept details changed as listed OFREILLY, J.P. Region 2. Office of Director 84/03/05 GUINN, F.K. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 1p 20AMS 338
- --8403160386 IE Enforcement Conference Rept 70-0143/84-06 on 840216 Major areas discussed nuclear criticality safety violations identified by resident & regional Inspectors KAHLE.J D. Region 2. Office of Director MCALPINE.E J. Division of Emergency Preparedness & Materials Safety 84/02/24 3pp 22639 360
- 8403160258 Forwards IE Insp Rept 70-0143/84-05 on 840214-17 No viplations or deviations noted BTOHR.JP Division of Emergency Preparedness & Materials Safety 84/03/07 OUINN.F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 22660 205
- --8403160270 IE Insp Rept 70-0143/84-05 on 840214-17 No noncompliance noted Major areas inspected matl control & accountability Date: Is withheld (ref 10CFR2 790 & 73 21) JONES: D W Replon 2: Office of Director MCALPINE, E. J. Division of Emergency Preparedness & Materials Safety 84/03/02 12 22660:207
- 8403290285 Ack receipt of 840301 ltr Informing NRC of steps taken to correct violation noted in IE Bafeguards Insp Rapt 70-0143/83-41 Corrective actions will be examined during future Insps Encis withheld (ref 100FR2 790) STCHR.J.P Division of Emergency Preparedness & Materials Safety 84/03/09, GAINN.F.K Nuclear Fuel Services, Inc. (subs of Gatty Oli Co) ip 22801 335
- 8403210151 Forwards IE Safeguards Insp Rept 70-0149/84-09 on 840103-0302 No violations or deviations identified 8TCHR.J P Division of Emergency Preparedness & Materials Safety 84/03/19 QUINN,F.K. Nuclear Fuel Services, Inc (subs of Gette Qii Co) 2pp. 22707.102
- --8403210156 IE Bafeguards Insp Rept 70-0143/84-09 on 840103-0302 No violations noted Major areas inspected events reported by licenses, facility operation, changes & mod. radiation, environ & physical protection & matl control & accounting LEE-T D . MCALPINE, E J Region 2, Office of Director 84/03/19 App 22707-104

- DUCKET 70-0152 PURDUE UNIV . WEST LAFAYETTE, IN
- 8403190211 Forwards IE Safeguards Insp Repts 50-182/84-01 & 70-0152/84-01 on 840216-17 No noncompilance identified AKELBON.N L. Region 3. Office of Director 84/03/14 LYKOUDIS, P Purdue Univ . West Lafayette. IN 2pp 22671 109 24X Fiche 50-182.84/03/14.8403190211
- POCKET 70-0190 CATHOLIC UNIV OF AMERICA, WASHINGTON, DC
- 0403130422 Discusses IE insp of Licenses SNM-164.5UD-157 & 08-02075-03 on 840126-27 & forwards notice of violation MARTIN.T T Division of Engineering & Technical Programs 84/03/08 MURPHY, J Catholic Univ of America, Washington, DC 2pp 20413 140
- DOCKET 70-0371 UNC NAVAL PRODUCTS, INC , UNCASVILLE, CT
- 8403010289 Efficient monitoring rept Jui-Dec 1983 W/840126 Itr KIRK,W F United Nuclear Corp 83/12/31 MURLEY,T E Region 1, Office of Director 2pp 22434 259
- 8403190231 Ack receipt of 840224 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0371/83-08 Corrective actions will be examined during future insp BTARDSTECKI.R Division of Project & Resident Programs 84/03/09 AMY.H O United Nuclear Corp 1p 82672 026
- --8403190234 Responds to NRC 840126 ltr re violations noted in IE Insp Rept 70-0371/83-08 Corrective actions Feb 1984 awareness meeting & Mar 1984 annual health physics reorientation training will reemphasize exiting contamination check AMY-0 0 United Nuclear Corp 84/02/24 STARGSTECKI.R Division of Project & Resident Programs 2pp 22672 027
- 8403220249 Ack receipt of 830B12 application & 830915 rev re storage of fuel components interaction analysis failed to identify physical & administrative controls to ensure all components centrally located in common place
 BIDINGER G H Urenium Fuel Licensing Branch 84/03/12 KIRK, W United Nuclear Corp 1p 22723 335

DOCKET 70-0378 ARMY, DEPT OF, ADELPHI, MD

- 8403190259 Discusses IE insp of Licenses SNM-348,19-17250-01, 19-17250-03,19-17250-04 & 19-17250-05 on 840202 No violations noted Major areas inspected Interviews w/ personnel & procedures & representative records MARTIN, T T Division of Engineering & Technical Programs 84/03/14 MARCUS, S M Army, Dept of 2pp 22670 237
- DOCKET 70-0398 COMMERCE, DEPT OF, WASHINGTON, DC
- B403290043 Forwards IF Safeguards Insp Rept 70-0398/84-01 on 840213-16 No violations observed MARTIN,T T Division of Engineering & Technical Programs 84/02/13 PEVEY.L E Commerce, Dept of National Bureau of Standards 2pp 22806 265
- --8403270066 IE Safeguards Insp Rept 70-0378/84-01 on 8402:3-16 No noncompliance noted Major areas inspected facility organization & operation, physical inventory, records & repts & mpt of nuclear matis control sys DELLA RATTA, A. JOYNER, J H Region i, Office of Director 84/03/13 4pp 22806 247
- DOCKET 70-0474 UPSALA COLLEGE, EAST DRANGE, NJ
- 8403070244 Ack receipt of 840209 ltr re disposition of Pu-Be source under License SNM-450 License will be retired & renewal action voided QLENN, J E Division of Engineering & Technical Programs 84/02/27 FELDER, R Upsala College, East Orange, NJ 1p 22546 228
- --B403070267 Informs that Pu-Be source shipped via QF Consolidiated Freightways & donated to DDE.LASL for recovery under License SNM-450 Transaction rept 5 bill of lading enci FELDER, R Upsala College, East Orange, NJ 84/02/07 NRC No Detailed Affiliation Given 3pp 22546 227

DOCKET 70-0553 ARMY, DEPT OF, SACRAMENTO, CA

8403200064 IE Insp Findings & Licensee Ack dtd 840206-07 of License SNM-507 Insp Findings no violations observed SNOV.D D Region S. Office of Director 84/02/17 ip 22684 356

DOCKET 70-0687 UNION CARBIDE CORP , TUXEDO, NY

- 8403020231 Forwards final rept. "Evaluation of Seismic Response Characteristics of Hot Celis & Related Structures & Equipment at UCC Sterling Forest Research Ctr " ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 84/02/16 RUZICKA.H G Union Carbide Corp 1p 22519 219
- --8403050032 "Evaluation of Seismic Response Characteristics of Hot Cells & Related Structures & Equipment at UCC Sterling Forest Research Ctr." final rept 3 Science Applications, Inc. NRC-02-83-035 SA1-1-148-08-781 83/15/30 NRC - No Detailed Affiliation Given 21pp 22519 217
- 8403270332 Forwards request for add1 info to complete NRC review of util 831014 license renewal application Capability needs to be strengthened in safety area to provide for audits by competent personnel w/current operating practice ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 84/03/12 MCGOVERN.J J Union Carbide Corp 12pp 22822 238
- 8403300137 Ack receipt of 840302 ltr informing NRC of steps taken to correct violations noted in IE insp Rept 70-0687/83-04 STAROSTECKI,R Division of Project & Resident Programs B4/03/27 MCGOVERN,J J Union Carbide Corp ip 28820 347
- ---8403300140 Responds to NRC 840120 ltr re violations noted in 1E lnsp Rept 70-0687/83-04 Corrective actions addl criticality safety signs posted in target production lab 1 waste storage facility MCGOVERNU J Union Carbide Corp 84/03/02 STARGSTECKI.R Division of Project & Resident Programs 1p 22820 348

DOCKET 70-0712 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, DK

- B400260116 FOLA request for five categories of documents re facilities DARNES, C. Affiliation Not Assigned 83/12/02 FELTON, J M Division of Rules and Records 1p 22763 333
- B403260123 Partial response to FOIA request for five categories of documents re Kerr-McOee Oil Industries. Inc Forwards documents listed on app Review of addi documents subj to request continuing FELION, J M Division of Rules and Records 84/03/02 BARNES.C Affiliation Not Assigned 2pp 22763 334
- --8403260153 Discusses certification of 660426 rept re disposition of SNM, per G Haller 660602 telcon Rept should indicate that contamination limits met in order for Commission to authorize transfer of facility NUSSBAUMER.D A Atomic Energy Commission 66/06/10 LAMBERTUS.H Kerr-McGea Corp 2pp 22763 349

DOCKET 70-0734 GA TECHNOLOGIES, INC , SAN DIEGO, CA

- 8403040329 Forwards IE Safeguards Insp Rept 70-0734/84-02 on 840124-27 No noncompliance observed NORDERHAND-LR Region 5. Office of Director 84/03/01 PARKER, J W GA Technologies, Inc. /Qeneral Atomic Co 2pp 22517 359
- --8403060331 IE Safeguards Insp Rept 70-0734/84-02 on 840124-27 No noncompliance identified Major areas inspected organization & operations measurement controls & shipper/receiver verification Details withheld (ref 10CFR2 790) NELSON G B . NORDERHAUG L R Region 5. Office of Director 84/02/27 ip 22517 361

DOCKET 70-0824 BABCOCK & WILCOX CO , LYNCHBURG, VA

B403070107 Informs of issuance of Amend & to License SNM-778, revising radiological contingency plan. SER encl PAGE.R & Uranium Fuel Licensing Dranch 84/02/26 GLSEN. A F Babcock & Wilcox Co ip 22564 124

--8403070112 SER supporting Amend 6 to License SNM-778, revising Condition 13 re radiological contingency plan KETZLACH N Uranium Fuel Licensing Branch 84/02/28 lp 20564 125

DOCKET 70-0920 RENSSELAER POLYTECHNIC INSTITUTE, TROY, NY

8403350228 Requests submission of physical security plan meeting fixed site requirements of 10CFR73 67(d) for protection of SNM of moderate strategic significance Reg Guide 9 59 & addl guidance encl W/o encl BRONN-W Fuel Facility Safeguards Licensing Branch 84/02/17 RYAN,R M Rensselaer Polytechnic Institute, Troy, NY 1p 22527 358

DOCKET 70-0925 KERR-MCGEE NUCLEAR CORP . OKLAHOMA C1TY, OX

8403280028 Submits address change for Nuclear Licensing & Regulation Dept JC Stauter will serve as primary addressee for encl list of licensees SHELLEY, H J Kerr-McGee Corp 84/03/21 SCHAEFFER, C NRC - No Detailed Affiliation Given 3pp 22777 060

DOCKET 70-0984 BATTELLE MEMORIAL INSTITUTE, RICHLAND, WA

8403190199 Forwards IE Safeguards insp Rept 70-0984/84-01 conducted on 840213-15 Noncompliance noted Notice of violation & insp rept withheld (ref 100FR2 790) NORDERHAUG, L R Region 5. Office of Director 84/03/15 OLESEN, D E Battelle Memorlai Institute, Pacific Northwest Laboratories 2pp 2668 356

DOCKET 70-1100 COMBUSTION ENGINEERING, INC , WINDSOR, CT

- 8401240337 Ack receipt of 831214 itr Informing NRC of steps taken to correct violations noted IE Insp Rept 70-1100/83-06 MARTIN:T T Division of Engineering & Technical Programs 84/01/19 LICHTENDERGER Combustion Engineering. Inc. ip 21920 305
- --B401240340 Responds to NRC B31129 itr re violations noted in 1E insp.
 Rept 70-100/E3-06 Corroctive actions waste shipping
 procedure revised to insure proper loading & storing of
 waste containors
 LICHTENDERGER Combustion Engineering, Inc. 83/12/14 MARTIN.T 7
 Division of Engineering & Technical Programs 2pp 21920 306
- 8403010360 Forwards IE Insp Rept 70-1100/83-07 on 831201 & notice of violation
 MARTINIT T Division of Engineering & Technical Programs 84/02/16
 Lichtenberger Combustion Engineering. Inc. 2pp 22434 084.
- --8403010362 Notice of violation from lasp on 831201 * Region 1, Office of Director 84/02/14 1p 22434.086
- --8403010366 IE Insp Rept 70-1100/83-07 on 631201 Violation Identified pyrophoric math not made inert & burial site not licensed to receive untreated pyrophoric math CLEMONS.P. PASCIAK.W. Region 1. Office of Director 84/01/16 3pp 22434 087
- 840307025B Forwards IE Safeguards Insp Rept 70-1100/84-02 on 840130-0200 No violations observed MARTIN T T Division of Engineering & Technical Programs E4/02/17 LICHTENBERGER Combustion Engineering, Inc. 2pp 22536 273
- --B403070257 IE Safeguards Insp Rept 70-1100/B4-02 on B40130-0203 No noncompilance noted Major areas inspected facility organization & operation.shipper/receiver verification, internal control & records & repts SMITH.0 C., DELLA RATTA.A., DUNLAP.J M Region 1, Office of Diroctor B4/02/16 App 22536 275
- 8403130472 Ack receipt of 840301 itr Informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1100/84-01. STAROBTECKI, R Division of Project & Resident Programs 84/03/07. LICHTENBERGER Combustion Engineering, Inc. 1p. 22613 326
- --8403130476 Responds to NRC 840213 ltr re violations noted in 16 Insp. Rept 70-1100/84-01 Corrective actions criticality safety analysis for nuclear matls stored on pellet shop messanine will be completed by 840316 LICHTERNERGER Combustion Engineering. Inc. 84/03/01 STARDSTECKI,R Division of Project & Resident Programs. 2pp. 22613 327

DOCKET 70-1113 GENERAL ELECTRIC CO , WILMINGTON, NC

- 8403160105 Ack receipt of 830804 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1113/83-17 Two violations correctly designated as separate violations D'REILLY, J P Region 2, Office of Director 84/02/29 LONO, J A General Electric Co 2pp 22655 114
- E403160340 Forwards IE Safeguards Insp Rept 70-1113/84-02 on B40206-10 No violations or deviations noted SYOHR, J.P. Division of Emergency Preparedness & Materials Safety B4/03/02 LONG, J.A. General Electric Co. 2pp. 22659
- --8403160348 IE Safeguards Insp Rept 70-1113/84-02 on 840206-10
 No noncompliance noted Major areas inspected measurements
 & statistical controls Details withheld (ref 10CFR2 790)
 CLAY, E. L. Region 2, Office of Director MCALPINS, E. J. Division
 of Emergency Preparedness & Materials Safety 84/02/29 ip
- 8403160375 Forwards IE Safeguards Insp Rept 70-1113/84-01 on 840206-10 No violations or deviations identified 8TCHR, JF Division of Emergency Preparedness & Materials Safety 84/03/02 LONGJ A General Electric Co 2pp 22660 189
- --8403160380 IE Safeguards Insp Rept 70-1113/84-01 on 840206-10 No noncompliance noted Major areas inspected followup on previous insp findings & verification of export shipment Details withheld (ref 10CFR2 790 & 73 21)

 BATES.J W Region 2, Diffice of Director MCALPINS.E J Division of Emergency Preparedness & Materials Safety 84/02/29 1p 22660 191
- DOCKET 70-1143 WEBTINGHOUSE ELECTRIC CORP , PITTEBURGH, PA
- B403010326 "Effluent Semiannual Rept.Jul-Dec 1983 " W/840130 1tr WDDDBUM.H C Wastinghouse Electric Corp 83/12/31 2pp 22432 012
- DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP , FITTSBURGH, PA
- E3403160043 Ack receipt of B40107 rev to fundamental nuclear maticontrol plan Addi Info re descriptions for all positions having functional responsibility requested Rev withheld (ref 10CFR2 790)
 STOHR.J P Division of Emergency Preparedness & Materials Safety 84/03/13 BRITTON.W H Westinghouse Electric Corp 2pp
- DOCKET 70-1193 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK
- ### 403280028 Submits address change for Nuclear Licensing & Regulation Dept JC Stauter will serve as primary addressee for ancl list of licensees SHELLEY.W J Kerr-McGee Corp 84/03/21 SCHAEFFER,C NRC No Detailed Affiliation Given 3pp 22777 060
- EDICKET 70-1201 BABCDCK & NILCOX CO , LYNCHBURG, VA
- E303070015 Informs of issuance of Amend 1 to License SNM-1168, revising Condition 24 re radiological contingency plan SER encl PAGE, R 0 Uranjum Fuel Licensing Branch 84/02/28 FORD, J, T Babcock & Wilcox Co 2pp 22563 191
- DOCKET 70-1257 EXXON NUCLEAR CO , INC , RICHLAND, WA
- 8403270214 Forwards IE Insp Rept 70-1257/83-10 on 831114-18 & notice of violation SCARANO,R A Division of Radiological Safety & Safeguards Program 84/01/16 NILSON,R Exxon Nuclear Co , Inc (subs. of Exxon Corp) 2pp 22772-144

- --8403270221 IE Insp Rept 70-1257/83-10 on 831114-18 Violations noted buckets containing SNM in specialty fuels bldg separated by only 3 inches & specialty fuels bldg not posted w/sign restorage Safeguards info deleted (ref IOCFRZ 790) BROCK, B. L. ZURAKONSKI, P. R. THOMAS, R. D. Region 5, Office of Director 84/01/10 21pp 22772 149
- B403060416 Ack receipt of B40207 Itr informing NRC of steps taken to correct violations noted in [6 insp of License SNM-1227 MENSLAMSKI.F A Region 5, Office of Director B4/03/01 MALODY, C W Exion Nuclear Co , Inc (subs of Erson Corp) ip 2251(344
- --BA03060421 Responds to NRC 840116 itr re violations nated in IE insp of License SNM-1227 Corrective actions taped array outline replaced w/metal grid spacing arrangement to provide permanency & to keep storage buckets from pushing together MALODY.C W Exxon Nuclear Co., Inc. (subs. of Exxon Curp.) 84/02/07 THOMAS.R D Region 5, Office of Director 25p 22511 345
- 8403260082 Advises of issuance of Amend 15 to License SNM-1227, authorizing changes to environ monitoring program covering well monitoring SER enci PAGE,R G Uranium Fuel Licensing Branch 84/03/09 MALODY,C W Exxon Nuclear Co , Inc (subs of Exxon Corp) 1p 22763 232
- --8403260084 SER supporting issuance of Amend 15 to License BNM-1227 to environ menitoring program BIDINGER.G H., GROW.W T Uranium Fuel Licensing Branch 84/03/09 2pp 22763 233
- B403190224 Forwards IE Safeguards Insp Rept 70-1257/84-01 on 840214-17 No noncompliance noted Rept withheld (ref 10CFR2 790) NORDERHAUG. R. Region 5. Office of Director B4/03/15 NILSON.R Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 2pp 22670-241
- 8403300293 Notifies that Sections 2 & 3 of License 5NM-(227 amended to authorize organizational changes PAGE.R G Uranlum Fuel Licensing Branch 84/03/15 MALODY,C W Exton Nuclear Co., Inc. (gubs of Exton Corp.) 1p 22844 319
- --8403300277 SCR supporting 031205 & 840305 applications for amends to License 6NM-1227, authorizing organizational changes BIDINGER, G H Uranium Fuel Licensing Branch 84/03/15 to 2084 200
- DOCKET 70-1311 AIR FORCE, DEPT OF, USAF ACADEMY, CO
- 8403130401 IE Insp Findings & Licensee Ack dtd 840206 & 07 of License SNM-1285 Insp findings no violations observed BHDFENN,N M Region 4, Office of Director 84/02/07 Ip 22413 334
- DOCKET 70-1359 IRT CORP . SAN DIEGO. CA
- 8403200224 IE Insp Findings & Licensee Ack dtd 840124-25 of License BNM-1405 Insp findings refresher training of authorized users not conducted every 2 yes & annual audit not conducted.per Condition 9 PANO, J F Region 5. Office of Director 84/01/30 ip 22700 021
- 8403230241 Forwards revised License SNM-1405 & 8ER supporting license amend Request for amend should be submitted in form of replacement pages to license application PAGE, R 0 Uranium Fuel Licensing Branch 84/03/09 MASCHKA, P R IRT Corp 1p 22759 263
- --B403230244 License ENM-1405 for IRT Corp authorizing receipt & possession of 25 g U-235,100 g Pu/8e source & 500 g Pu-239 PAGE.R G Uranium Fuel Licensing Branch 84/03/09 2pp 22739 264
- --8403230246 Safety evaluation supporting renewal of License ENM-1405 POBLA, B M Uranium Fuel Licensing Branch CROW, W T Division of Fuel Cycle & Material Safety 84/03/09 4pp 22759 266
- DOCKET 70-1621 DUGUESNE LIGHT CO , PITTSBURGH, PA
- 8403010293 Forwards Endorsement 58 to MAELU Policy MF-87 & Endorsements 67 & 68 to NELIA Policy NF-226
 BARNETI, J E Conover & Associates, Inc 84/02/28 DINITZ, I.
 Office of Nuclear Reactor Regulation, Director 4pp 22434 264

DOCKET 70-1717 NORWALK HOSP , NORWALK, CT

8403300167 IE Insp Findings % Licensee Ack dtd 840307 of Licenses 06-06941-01 & SNM-1904 Insp findings no violations observed Steps taken to correct violations noted in previous insp verified STEARNS.C F Region i, Office of Director 84/03/07 ip

DOCKET 70-2199 VETERANS ADMIN MEDICAL CENTER, WASHINGTON, DC

B403130294 Ack receipt of B30830 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-2199/83-02
MARTIN,T T Division of Engineering & Technical Programs B4/03/08
QAVAZZIA A Veterans Admin Medical Center, Mashington, DC ip

--8403130302 Responds to NRC 830810 itr re violations noted in 1E Insp Rept 70-2199/83-02 Corrective actions appropriate officials notified that NRC approval required to accept nuclear pacemakers GAVAZZI.A A Veterans Admin Medical Center, Washington, DC 83/08/30 MARTIN.T T Division of Engineering & Technical Programs 7ρρ 22608 040

--8403130308 Act receipt of 830810 ltr on Circular 10-83-66 re explanted cardiac pacemaker prostheses Recission of nuclear units to Veterans Administration facilities completed SMITH.JJ Veterans Admin Medical Center, Washington, DC B3/08/26 MARTIN.T T Division of Engineering & Technical Programs 5pp 22608 042

DOCKET 70-2946 LOUISIANA POWER & LIGHT CO , NEW ORLEANS, LA

8403060190 Forwards Endorsement 13 to NELIA Policy NF-263 COCK.K.W. Louisiana Power & Light Co. 84/02/27 Assistant Director for State % Licensee Relations 2pp. 22519 034

DOCKET 70-2955 EDLOW INTERNATIONAL CO . WASHINGTON, DC

G403030365 Notifies that G40123, "Physical Security Plan for Protection of SNM of Low Strategic Significance" acceptable as amended, per encl provisions Encl withheld (ref 100FR2 790)
BROWN, M B Fuel Facility Safeguards Licensing Branch B4/01/27
EDLOW, J Ediow International Co 3pp 22527 314

DOCKET 70-2988 PHILADELPHIA ELECTRIC CO . PHILADELPHIA, PA

8403050367 Forwards request for add1 info re physical security plan for protection of SNM of low strategic significance Response requested within 30 days W/o encl BROWN, W Fuel Facility Safeguards Licensing Branch 84/01/31 BRADLEY, E.G. Philadelphia Electric Co. 1p. 22527-313

8403300307 Submits items of interest Affidavit issued 840313 confirming that even if fuel pellofs damaged by accident involving fuel assemblies in shipping containers no radiological releases in violation of NRC regulations would result CUNNINGHAM.R E Division of Fuel Cycle & Material Safety 84/03/15 DAVIS.J O Office of Nuclear Material Safety & Safeguards, Director ip 22844 302

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0511 DELTAK CORP

8403010149 Forwards revised App H to QA program for transportation of radioactive matls Organization chart from radiation safety manual added as Figure 1 JORDAN, D Deltak Corp 84/01/24 CORDON, L Transportation Certification Branch 1p 22479 250

--8403010153 GA program for transportation of radioactive matls * Deltak Corp 84/01/24 5pp 22479 231

DOCKET 71-0513 EDLOW INTERNATIONAL CO

8403140235 Forwards QA program approval for radioactive matl package 0313,Rev | MACDONALD, C E, Transportation Certification Branch 84/03/05 PODMURST, B W Ediow International Co 1p 22636 361 --8403140238 QA program approval for radioactive matl package C513.Rev L MACBOHALD.C E Transportation Certification Branch 84/03/05 ip 22636 362

DOCKET 71-0514 NORTH AMERICAN INSPECTION

8403050338 Forwards QA program approval for radioactive math Package 0314 Rev O MACDDNALD, C E Transportation Certification Branch 84/02/24 SHUMMAY.R North American Insp 1p 22501 319

--8403050340 GA program approval for radioactive matl Package 0314.Rav 0 MACDDNALD.C E Transportation Cortification Branch 84/02/24 ip 22301 320

DOCKET 71-5450 MODEL RCC. -1, -2, -3, -4, WESTINGHOUSE ELECTRIC CORP

8403260331 Forwards Rev 19 to Certificate of Compliance 5450 for Models RCC.RCC-1.RCC-2.RCC-3 & RCC-4 RCC.RCC-1.RCC-2.RCC-3 & RCC-4 RACDONALD.C E Transportation Certification Branch 84/03/09 WEINTRAUB.A A Energy, Dept of 2pp 22775 288

~~8403260336 Certificate of Compliance 5450, Rev 19, for Models RCC,RCC-1, RCC-2, RCC-3 & RCC-4 MACDONALD, C E Transportation Certification Brench 84/03/09 6pp 22/75 270

DOCKET 71~6206 MODEL B. BABCOCK & WILCOX CO

84030i0162 Application for amond to Certificate of Compliance 6206, changing Fissile Class III to Fissile Class II or III FORD, J Y Babcock & Wilcox Co 84/01/24 MACDGNALD, C E Transportation Certification Dranch 2pp 22479 219

--8403010166 Rev O to "Shipping Safety Analysis " • Babcock & Wilcox Co 80/02/27 11pp 22479 221

DOCKET 71-6406 MODEL NONE, ENERGY, DEPT OF

B403080374 Forwards Rev 5 to Certificate of Compliance 6406 for unirradiated fuel assembles MACDONALD.C E Transportation Certification Branch 84/02/29 ENGEL.N P Energy, Dept of ip 22581 352

--8403080376 Certificate of Compliance 6406.Rev 5.for unirradiated fuel assemblies Approval record encl MACDONALD.C E Transportation Certification Branch 84/02/29 5pp 22581 353

DOCKET 71-6601 MODEL CNB 8-120, CHEM-NUCLEAR SYSTEMS, INC

8403080312 Forwards Rev 15 to Certificate of Compliance &601 for Model CNS 8-120 MACDUNALD, C E Transportation Certification Branch 84/03/02 DEAL, R Chem-Nuclear Systems, Inc 4pp 22577 350

---8403080314 Certificate of Compliance 6601,Rev 15 for Model CNS 8-120 Approval record enc! MACOUNALD.C E Transportation Certification Branch 84/03/02 4pp 22577 354

8403210212 Notification of registration as user of Models CNS 8-120 & NUPAC 14 D-2 O in response to 840221 request MACDONALD, C E Transportation Certification Branch 84/03/09 WETHY.C M Florida Power & Light Co 1p 22709 205

B403230166 Notification of registration as user of Model CNS 8-120 in response to 840221 request MCCDDNALD, C E Transportation Certification Branch B4/03/09 KELBLEY, N D Advanced Medical Systems, Inc. 1p 22743,348

DOCKET 71-9001 MODEL IF-300, GENERAL ELECTRIC CO

B403080397 Forwards Rev 17 to Certificate of Compliance 9001 for Model IF-300 MACDONALD, C E Transportation Certification Branch 84/02/29 DAMEDN, D M General Electric Uranium Management Corp 2pp 22581:342

--8403080399 Certificate of Compliance 9001, Rev 17, for Model IF-300 Approval record enci MACDONALD.C E Transportation Certification Branch 84/02/29 8pp 22561 344

DOCKET 71-9009 MODEL FL 10-1, GENERAL ELECTRIC CO

8402060574 Forwards request for addl info re 840121 application requesting approval for Model FL 10-1 Info requested 60 days from ltr receipt MACDONALD, C E Transportation Certification Branch 84/02/29 VAUGHN, C M General Electric Co 3pp 22552 296 04/03/30

8403230269 Notification of registration as user of Model FL 10-1 in HACDDNALDIC E Transportation Certification Dranch 84/03/09
WEINTRAUB, A A Energy, Dept of 19 22/59 285

DOCKET 71-9027 MODEL 741 & 741E, TECHNICAL OPERATIONS, INC.

8403300298 Forwards Rev 4 to Certificate of Compliance 9027 for Models 741 & 7418 MACDONALD.C E Transportation Certification Brench 84/03/19 84/03/19 Technical Operations, Inc. 2pp 22844 311

--B403300302 Certificate of Compliance 9027,Rev 4.for Models 741 & 741F MACDONALD,C E Transportation Certification Branch 84/03/19 3pp 22844 312

DOCKET 71-9036 MODEL C-1. SOURCE PRODUCTION & EQUIPMENT CO . INC

8403280214 Forwards Rev 4 to Certificate of Compliance 7036 for Model C-1 MACDDNALD.C E Transportation Certification Branch 84/03/14 DICHARRY.R F Source Production & Equipment Co . Inc 2pp

--8403280218 Certificate of Compliance 7036, Rev 4, for Model C-1 MACDONALD, C E Transportation Certification Branch 84/03/14 3pp 22787 348

DOCKET 71-9071 MODEL AP-101, ANEFOD, INC

8403020227 Requests listed info to complete review of 840117 application for amend to Model AP-101 to include borosilicate & other silicate solid waste forms in steel canisters as authorized contents MACDDNALD.C E Transportation Certification Branch 84/02/22 MURPHY, J D Anefco, Inc. 2pp. 22493 361

DOCKET 71-9079 MODEL HN-100, SERIES 2 & 2A, HITTMAN NUCLEAR

B403210212 Notification of registration as user of Models CNS 8-120 % NUPAC 14 D-2 0 in response to B40221 request MAGDONALD, C & Transportation Certification Branch B4/03/09 WETHY. C N Florida Power & Light Co ip 22709 205

DOCKET 71-9080 MODEL HN-600, NUPAC 7-100 & CNS 7-100, HITTMAN NUCLEAR

8403080416 Forwards Rev 9 to Certificate of Compliance 9080 for Models HN-600, NUPAC 100 & CNS 7-100 MACDUNALD, C E Transportation Certification Branch 84/03/0 ROME, B S Westinghouse Electric Corp 4pp 22547 346

NUPAC 100 & CNB 7-100 Approval record encl MACDIMALD.C E Transportation Certification Branch B4/03/01 3pp 22567:350 --8403080418 Certificate of Compliance 9080.Rev 9.for Models HN-600,

DOCKET 71-9108 MODEL CNS 4-75, CHEM-NUCLEAR SYSTEMS, INC

840302042D Forwards Rev 5 to Certificate of Compliance 9108 for Model CNS 4-75
MACDONALD, C E, Transportation Certification Branch 84/02/22,
DEAL, R Cham-Nuclear Systems, Inc. 3pp. 22491 269

--8403020423 Certificate of Compilance 710B.Rev 5.for Model CNS 6-75 MACDDNALD.C E Transportation Certification Branch 84/02/22 4pp. 22491 272

DOCKET 71-9134 MODEL ETR. EXXON NUCLEAR IDAHO CO

8403300224 Forwards Rev 3 to Certificate of Compliance 9134 for Model ETR
MACDDNALD.C E Transportation Certification Branch 84/03/15
WEINTRAUB.A A Energy. Dept of 2pp 22845 039

--8403300227 Certificate of Compliance 9134, Rev 3 for Model ETR MACDUNALD, C E Transportation Certification Branch 84/03 4pp 22845 041

DOCKET 71-9160 MODEL 20-VS & 40-VS, GULF NUCLEAR, INC.

8403070011 Forwards request for add1 info re 840121 application requesting approval for Models 20-VS & 40-VS Info requested 40 days from itr receipt MACDONALD.C & Transportation Certification Branch 84/02/29 BEVILL.M Gulf Nuclear, Inc. 2pp 22963 164

8403300229 Forwards request for addl info re 840306 application for approval of Models 20-VS & 40-VS Addl info should be submitted in form of revised pages Submittal schedula requested within 30 days of ltr receipt MACDONALD.C E Transportation Certification Branch 84/03/15 BEVILL,M Guif Nuclear, Inc. 2pp 22844 360

DDCKET 71-9161 MODEL R. GULF NUCLEAR, INC.

8403020239 Requests add1 info re 840121 application for approval of Model R packaging Info requested 30 days from Itr date MACDUNALD.C E Transportation Certification Branch 84/02/24 BEVILL.M Gulf Nuclear, inc ip 22493 360

DOCKET 71-9142 MODEL GNM-20, GULF NUCLEAR, INC

8403260074 Forwards request for add: info in response to 830624 application for approval of Model GNM-20 Add info should be submitted in form of revised pages Submittal date requested within 30 days of lir date MACDONALD, C E Transportation Certification Branch 84/03/07 DEVILL, M Guif Nuclear, inc. ip 22763 188

DOCKET 71-9175 MODEL CNS6-ROB, NUCLEAR PACKAGING, INC

8403160164 Summary of B40302 meeting w/Chem-Nuclear Sys, Inc in Silver Spring, MD re application for Model CNS 6-808 packaging ODEGAARDEN, R H Transportation Certification Branch B4/03/06 Transportation Certification Branch ip 22662 265

DOCKET 71-9190 MODEL CASTOR V. GESELLSCHAFT FUER NUKLEAR SERVICE, MBH

8403070002 Forwards comments on 831107 partial application for CASTOR (030)0002 Forwards comments on 831109 partial application for CA
Vb cask Based on info submitted NRC cannot conclude that
proposed test would be adequate for approving cask design
Application for QA program needed prior to next submittal
MACDUNALD.C E Transportation Certification Branch 84/02/23
ROLLINS.J D Gasellschaft fuer Nuklear Service, mbH 8pp 22562 344

		11.0
		,

9403010047 Transcript of B40224 briefing in Washington, DC re need for & availability of experienced reactor operators for future nuclear power plants Pp 1-95 Supporting documentation & viewgraphs encl

B Commissioners B4/02/24 i41pp 22446 348

9403050246 Staff requirements memo re Commission B40222 meeting in Hashington, DC on advance motice of rulemaking on backfitting Commission directed Regulatory Reform Task Force to reconvens & consider proposal CMILK, G J Office of the Secretary of the Commission MB40222 D4/02/27 TOURTELLOTTE, J NRC - No Detailed Affiliation Given DJRCKS, W J Office of the Executive Director for Operations PLAINC, H Uffice of the General Counsel Zpp 22527 186

8403050295 Staff requirements memo re Commission affirmation, discussion & vate in Washington, DC Commission by 3-0 vote approved CHILK, U J Office of the Secretary of the Commission MB4022BA B4/02/27 PLAINE, H H Uffice of the General Counsel ip 22527 105

8403050277 Transcript of B40227 briefing in Washington, DC re advanced teatfors Pp 1-35 Supporting documentation enci commissioners B4/02/27 53pp 22501 211

8403050277 Transcript of B40227 briefing in Washington, DC re financial qualifications & long-term rulemaking proposals Pp 1-47 * Commissioners B4/02/27 53pp 22501 211

8403050277 Transcript of B40227 affirmation/discussion t vote in Washington, DC re BECY-04-71A on statement policy re financial qualifications & long-term rulemaking proposals Pp 1-47 * Commissioners B4/02/27 7pp 22501 202

8403050376 Transcript of Commission B40228 affirmation/discussion & vote in Washington, DC re publication of FR notice on equipment qualification of commission statement policy re financial qualification of Commission B40228 affirmation/discussion & vote in Washington, DC re publication of FR notice on equipment qualification of commission B40228 briefing in Washington, DC re status of vitil progress toward obtaining full power DL vote subpowers

CHILK, G J Office of the Secretary of the Commission B4/02/27 Publist Document Branch ip 22547

COMMISSION MEETING RECORDS

LOCER

8403150130 Transcript of Commission 840227 discussion & possible vote in Woshington, DC re NRC recommendations on DEE repository siting guidelines Supporting documentation encl # Commissioners 84/02/29 70pp 22648 160 8403230162 Staff requirements memo re 840227 discussion & possible vote on staff recommendations on DDE repository siting guidelines in Washington, DC CHILK, 8 J Office of the Secretary of the Commission M840227A 84/03/12 DIRCKS, W J Office of the Executive Director for Operations ip 22743 347 --8403230164 Advises that NRC has approved FR publication of preliminary decision re DDE repository siting guidelines presented in SECY-84-67D, subj to listed items CHILKE J Defice of the Secretary of the Commission 84/03/08 DIRCKS H J Office of the Executive Director for Operations 2pp 8403230175 Transcript of 840320 brisfing in Washington.BC re Tech Spec requirements Pp 1-74 Supporting documentation enci * Commissioners 84/03/20 B5pp 22759 178 24X Fiche 80-416.84/03/20.8403230175 8403260334 Transcript of Commission 840321 affirmation/discussion k vote in Washington, DC re proposed order delegating authority to ABLO to hear Part 70 issues raised in Limerick proceeding Pp 1-3

* Gommissioners 84/03/21 app 22775 281 24X * Commissioners 84/03/21 &pFiche 50~392,84/03/21,8403260334 6403270320 Transcript of Commission 840323 discussion/possible vote in Washington, DC re fuil power OL for LaSaile Unit 2 Pp 1-76 Supporting documentation and ### *Commissioners, 84/03/23 84pp 22787 153 24X Fiche 50-374 8403270335 Transcript of Commission 840323 affirmation/discussion & vote in Washington, DC re request for denial of renewal of Seabrook Unit 2 CP & SECY-84-48 concerning review of ALAB-724 in matter of Met Ed Pp 1-3 ** Commissioners ALAB-724 84/03/23 App 22787 35A 24X Fishe 30-000, 84/03/23, 8403270335 ADVISORY COMMITTEE ON REACTOR SAFEOUARDS ACRE 8307260036 Forwards comments on proposed priority rankings of additional properties of several discussed during ACRS 279th meeting on 830707-09 ACRS disagrees w/certain priority rankings proposed by NRC LIBARKIN. NW ACRS - Advisory Committee on Reactor Safeguards 830707/15 DIRCKS, WJ Office of the Executive Director for Operations 18pp 22444 082 ---B403010013 Submits comments & requirements re 820819 meeting on safeguards issues Safeguards country analyses spent fuel & spent fuel strategy & safeguard goals addressed MAUBSHARDT. D D Office of Nuclear Material Safety & Safeguards Director 82/08/20 BURNETI.R F Division of Safeguards 2pp 22444 100

--8403010022 Comments on safequerds research More structuring & emphasis should be placed on investigating insider particularly coming to grips w/answer to FRA approach Shared research between DOE & NRC could work DAVIS.J 9 Office of Nuclear Material Safety & Safeguerds. Director 83/07/14 BURNETT.R F Division of Safeguerds ip 22444 102

--8403010029 Requests different cross cuts of data on "Insider Adversary Study" to help quantify certain aspects of malevolence risk Ciassified insider adversary rept requested BURNTTIR F Division of Safeguards 82/10/26 CAUDLE.R. Energy, Dept of ip. 22444 103

- ~-8403010033 Forwards histograms & explanatory notes that represent most recent work in analyzing safeguards event data Halevolent simildents that challenged safety sys & imident frequencies & trends examined BURNLTT.R F Division of Safeguards 82/11/05 MAUSSHARDT Office of Muclear Material Safety & Safeguards. Director 29pp 22444 104
- -0403010042 Forwards "Quantification of Risk Due to Babotage at Power Reactors" NRC conclusion that inclusion of radiological sabotage in safety goal unfeasible BURNETTER F Division of Safeguards 83/12/14 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 35pp 22444 134
- --B30804057G Discusses development of safrguards goal.per 830609 memo Probability of nuclear power plant sabutage cannot be estimated w/any confidence No good measures for predicting effectiveness of securities safeguards improvements, THOMPSON.M L. Division of Human Factors Safety 83/07/26 BURNCTT-R F. Division of Safeguards 2pp 22444 206
- --B312150241 Provides concurrence on NMSS summary of EDO 830927 briefing on quantification of risk to sobotage at power reactors Use of PRA as tank to develop sabotage stds should be portrayed more positively
 THOMAS.C O Standardization & Special Projects Branch 83/12/07
 [RJCKSON.R A Licensing Policy & Programs Branch 1p 22444 218
- --831i140170 Comments on chronology re quantification of risk due to subbtage at power reactors. In response to 831027 memo SPF15.1 P Division of Safety Technology 83/11/02 EISENHUT. D G Division of Licensing 2pp 22444 219
- --H312120006 Clarifies position on quantification of risk due to sabotage Author incilnes toward more positive view of role PRA techniques might play in regulatory stds development hearing upon sabotage

 SPEIS.T P Division of Safety Technology 83/11/29

 EISCNHUT, D & Division of Licensing 1p 22444 220
- -8403010057 Submits six items requiring followup re status of safeguard program items Preliminary Agenda for Nov 1984 & meeting notice re weekly collequía on PRA activities encl HAUSSHARDI. D Dff;ce of Nuclear Haterial Safety & Safeguards.Director 83/10/20 BURNETT,R F Division of Safeguards 116pp 22444 222
- --B311140250 Discusses initiatives to improve coordination, morale & training among divs on PRA-related subjs ROMSOME, F Assistant Director for Technology Review B3/09/21 SPFIS, T Division of Safety Technology 3pp 22444 338
- --8403010065 Requests conference room beginning on 831108 & every Tuesday thereafter to hold coiloquia between NRR & RES members on PRA related issues ROMSUME. F. Assistant Director for Technology Review 83/10/26 ISCLIN.R E. Building & Operations Granch ip 22444 341
- B311140249 Pruposes program to Improve coordination among divs on FRArelated subjs
 ROMSOMG.F H Assistant Director for Technology Review 63/10/3i ERNST.M L Division of Risk Analysis 2pp 22444 342
- --8312170358 Forwards preliminary agenda instituting weekly colliquia on tractor risk assessment Colliquia series will begin on 831108 to discuss NRR PRA for FYBA RUBSUME.F Assistant Director for Technology Review 83/10/31 Assistant Director for Technology Review 1p 22444 344
- B401300121 Summarizes ACRS 285th meeting on B40112-14 re review of GL application.control room dasign & tube degradation investigation of allegations re GA requested EBERSOLE.J C. ACRS Advisory Committee on Reactor Safeguards B4/01/16 PALLADING,N J. Commissioners 3pp 22044 023 24X Fiche 50-400, B4/01/16, 8401300121
- 8403050346 Notifies of reappointment to ACRS
 PALLADIMO,N J Commissioners 84/02/22 EBERSOLE.J C. Affiliation
 Not Assigned EBERSOLE.J C ACRS Advisory Committee on Reactor
 Safeguards 1p 22501 321

- B40305034B Notifies of reappointment to ACRB
 PALLADING,N J Commissioners B4/02/22 BIESB,C P Apriliation
 Not Assigned SIESB,C P ACRB Advisory Committee on Reactor
 Safeguards ip 22501 322
- 8403090340 Discusses major deficiencies in "Critique of 306," pactage re inappropriate status & qualifications of training manager & low level of educ requirements Request views be presented at ACRS 831215-17 committee meetings
 PEARSON, R O North Carolina State Univ , Raieigh, NC PEARSON, R O ACRS Advisory Committee on Reactor Bafeguards 83/12/06 WARD, D ACRS Advisory Committee on Reactor Bafeguards 55p 22584 333
- B403130222 Transcript of ACRS Subcommittee on Draidwood Station B4030ff meeting in Joliet.IL Pp 1-163 Viewgraphs enc1 + ACR3 - Advisory Committee on Reactor Safeguards B4/03/08 185pp 22605 195 24X Fiche 50-456, B4/03/08, B403130222
- B40314000B Transcript of ACRB Subcommittee on Oraidwood Station B40309 meeting in Joliet.it Pp 164-283 Supporting documentation encil ACRS Advisory Committee on Reactor Bafeguards 84/03/09 379pp 22631 035 24% Fiche 50-456, 84/03/09, 8403140008
- 8403140302 Discusses seismology issues in OL review Extremely conservative values established for OBE & SSE Plant site is as nearly assismic as any site in eastern US MAXWELL, J C MAXWELL
- 8403140323 Summary of ACRS Subcommittees on Reactor Radiological Effects & Site Evaluation 830718-20 meetings in Washington, DC re FPA proposed natl emission stds & radiological emergency plans * ACRS - Advisory Committee on Reactor Safeguards 83/08/31 ACRS - Advisory Committee on Reactor Safeguards 23pp 22635 2
- 8403140334 Forwards comments on draft "PRA Ref Document," based on brief & incomplete review Agrees that use of "bottom-line risk numbers" should be discouraged Document comprehensive & consistent GARCIA: A Lawrence Livermore Laboratory 88-84-004/1177U 84/01/10 OKREMI, P. Callfornia, Univ of Los Angeles, CA OKREMI, D. AGR8 Advisory Committee on Reactor Bafeguards 4pp 20/15 171
- 8403140339 Comments on document evaluating PRA methodology sefectiveness Risk-worth tabulations for each complete PRA should be included MUELLER.C J. PCDEREEN.D R Argonno National Laboratory MUELLER.C J. ACRS Advisory Committee on Reactor Sefeguards B7/01/06 SAVIO.R ACRS Advisory Committee on Reactor Sefeguards DKRENI,D California, Univ of, Los Angeles, CA 4p 22635 247
- 8403140352 Summary of ACRB Waste Mgt Subcommittee 830908-09 meetings in Richiand, WA to continue review of DDE site characteritation rept for BWIP e ACRB Advisory Committee on Reactor Safeguards 83/11/01 ACRS Advisory Committee on Reactor Safeguards 19pp. 22435 173
- B403140004 Transcript of ACRS Subcommittees on Reliability & PRA & Indian Point Units 2 & 3 B40314 meeting in Washington, DC.
 Pp 1-60 Supporting documentation encl
 * ACRS Advisory Committee on Reactor Bafeguards B4/03/14 61pp 22653 289 24X Fiche 50-247,84/03/14,8403160004
- 8403160012 Transcript of ACRB Subcommittee on Reliability & Risk Assessment 840314 moeting in Washington DC Pp 1-54. Supporting documentation enci * ACRS Advisory Committee on Reactor Safeguards 84/03/14 Adpp
- 8403160037 Transcript of AGRB Subcommittee on Maint Practices & Procedures 840314 meeting in Washington.DC Pp 1-234
 Supporting documentation encl
 # AGRS Advisory Committee on Reactor Safeguards 84/03/14.
 509pp 22650 001
- 8403160046 Discusses adequacy of proposed rulemaking change to IOCFR50. App A, insuring human factor specs in design operation criteria
 DEDDNS: A ACRS Advisory Committee on Reactor Safeguards
 63/12/21 WARD.D ACRS Advisory Committee on Reactor Safeguards
 2pp 22662 322
- 8403160053 Comments on DOE B31118 final guidelines for recommendation of sites for nuclear waste repositories
 PHILBRICK, B S ACR9 Advisory Committee on Reactor Safeguards
 PHILBRICK, S B Philbrick, B S 83/12/19 MOELLER, D H ACRS -Advisory Committee on Reactor Safeguards, 2pp 22667-320

- B403160059 Discusses B31206 meeting w/8 Sheron & J Gutman re contribution of semiscale integral facility in licensing afforts Specific issues addressed w/help of semiscale
 - CATTON. I ACR9 Advisory Committee on Reactor Safeguards 84/01/05 BDEHNERT.P ACR9 Advisory Committee on Reactor Safeguards 2pp 22662 316
- 8403160067 Transcipt of ACRS Subcommittee on Safety Philosophy. Technology & Criteria 840314 meeting in Washington, DC Pp i-171 Supporting documentation and & ACRS Advisory Committee on Reactor Safeguards 84/03/14 171pp 22659 179
- 8403160076 Comments on TRAC-PHR or RELAPS for future development Recommends code development be stopped Code assessment program should be conducted by final user of code CATTON: I ACRS Advisory Committee on Reactor Safeguards 8401706 BDEHNERT.P ACRS Advisory Committee on Reactor Safeguards 2pp 22662 286
- 8403160085 Comments on 840103-04 site visit & OL hearing in Apex,NC Requests opportunity to view final control room & new simulator PEARBON, R G North Carolina State Univ. Raleigh, NC PEARSON, R Q PERROUNIA O NOTION CATGLINA DEBEG ONLY RELEIGN NO PERROUNIA ACRS - Advisory Committee on Reactor Bafeguards 84/01/05 KERR. ACRS - Advisory Committee on Reactor Safeguards MAJOR, R North Carolina State Unity Raleigh, NC 3pp 22662 276 24X Fiche 50-400,84/01/05,8403160085
- 8403190108 Transcript of ACRS 287th general meeting on 840315 in Washington, DC, Pp 1-190 Supporting documentation encl # ACRS Advisory Committee on Reactor Safeguards 84/03/15 237pp. 22668 007
- 8403210084 Transcript of 287th ACRS general meeting on 840316 in Washington, DC Pp 191-287 Supporting documentation encl * ACRS Advisory Committee on Reactor Sefeguards 84/03/16 100pp
- 8403220064 Transcript of ACRS Subcommittee on ECCS DHR B40320 meeting in Washington, DC Pp 1-363 Supporting documentation encl * ACRS Advisory Committee on Reactor Safeguards 84/03/20 479pp 227ii:001
- 8403220118 Recommends that proposed rule change to 10CFR50, App A be published for public comment & provides editorial comments Change would add human factor design criterion to general criterion MEYSERLING, W. M. ACRS Advisory Committee on Reactor Sefeguards KEYBERLING, W M ACRS - Advisory Committee on Reactor Safeguards 83/12/12 WAND, D ACRS - Advisory Committee on Reactor Safeguards Rpp. £2723,285
- 8403230121 Transcript of ACRB Subcommittee on ECCS & DHR 840321 meeting in Mashington, DC Pp 364-480 ** ACRS Advisory Committee on Reactor Safeguards 84/03/21 481pp. 22727 001
- B403240297 Transcript of ACRS 840322 seminar on PRA in Washington,DC Pp 1-4R1 Bupporting documentation enci * ACRS Advisory Committee on Reactor Safeguards B4/03/22 666pp. 22751 082
- 8403270005 Transcript of 840323 seminar in Washington.DC to PRA Pp 422-653 Supporting documentation enci. * ACRS Advisory Committee on Reactor Safeguards 84/03/23 370pp 82767 001
- B403280241 Questions requirements of Reg Guide i 97 to insure instrumentation to foilow course of accident, including severe accidents. Qualification requirements do not include anything beyond DBA CATTON, I. California, Univ of, Los Angeles, CA CATTON, I ACR Advisory Committee on Reactor Safeguards B4/02/17 CAPUCCI.A ACRS Advisory Committee on Reactor Safeguards 1p 22808 209
- 8403280307 Summary of ACRS Subcommitted on Extreme External Phenomena 831012 maeting w/util, Westinghouse: TERA & Univ of Illinois in Washington, DC re use of tan effect methodology in seismic design analysis at Diablo Canyon. Agenda encl * ACRS Advisory Committee on Reactor Safeguards 83/11/25 ACRS Advisory Committee on Reactor Safeguards. 16pp 22808,040 24X Fiche 50-275,83/11/25,8403280307
- 8403280308 Summary of ACRS Subcommittee on Human Factors 831130 meeting w/Westinghouse, BNL, Interlock Group & DOE in Washington, DC re proposed revs to Reg Quides I 149, I B, I 134 & 1,114 & proposed mod to 10CFR50, App A. * ACRS Advisory Committee on Reactor Bafeguards 84/02/24 ACRS Advisory Committee on Reactor Safeguards 33pp 22808 007

- 8403280310 Summery of ACRS Subcommittee on Electrical Sys 831116 merting in Washington.DC re FY85-86 research programs for Instrumentation & Control Branch including surveillance & diagnostic techniques Agenda & viewgraphs encl # ACRS Advisory Committee on Reactor Safeguards 82/12/19 ACRS Advisory Committee on Reactor Safeguards 17pp 22807 17pp 22807 352
- B403280313 Summary of ACRS Subcommittee on Reliability & Probabilistic Assessment B31116 meeting w/GAD in Washington, DC re FYB5-86 budget proposals & GAD B30927 ltr concerning PRA * ACRS Advisory Committee on Reactor Safeguards B4/01/23 ACRS Advisory Committee on Reactor Safeguards 9pp 22807 343
- B4032803i4 Summarizes IDCOR Fission-Product/Source-ferm meeting Overall treatment given to severe accident problem commendable
 CORRADINI,M Wisconsin, Univ of Madison, WI CORRADINI,M
 Advisory Committee on Reactor Safeguards 84/02/23 KERR,W
 Michigan, Univ of Ann Arbor, MI KERR,W ACRS - Advisory
 Committee on Reactor Safeguards 4pp 22807 CORRADINI, H ACR9 -
- B403280316 Submits comments on B31221 containment mesting in Knoxville, TN Value of TM1-2 Action Plan as tool for reducing severs accident risk debatable BENDER, M Guorytech, Inc. BENDER, M ACRS - Advisory Committee on Reactor Safeguards 84/01/31 KERR, W ACRS - Advisory Committee on Reactor Safeguards 2pp 22/97 357
- 8403280320 Summary of ACRS Subcommittees on Reactor Radiological Effects, Air Sys & Waste Mgt 931201-03 meetings w/Bechtel.

 DDE, Nucleonics Wk & Doub & Muntying in Washington, DC re proposed research

 * ACRS - Advisory Committee on Reactor Safeguards E4
 ACRS - Advisory Committee on Reactor Safeguards 17pp B4/03/15
- 8403280328 Comments on ACRS Class 9 Subcommittee 840127 meeting raworking draft of final NRC policy statement on severe reactor accidents Mati should be carefully reworded to make statements precise & nonrepetitive CGRRADINI.M Hicconsin. Univ of Madison, WI CORRADINI.M Advicory Committee on Reactor Safeguards 8701/30 KERR.W ACRS Advisory Committee on Reactor Safeguards 2pp 22799 360 ACRS -
- G403280335 Summary of ACRE Subcommittee on RE Ginna B31116 meeting w/
 utile, Gilbert Assoc. Westinghouse, KMC, Inc. Taylor Assoc &
 LeBoeuf. Lamb. Leiby & MacRae in Washington, BC re application
 to convert pruvisional OL to full-term OL
 # ACRS Advisory Committee on Reactor Safeguards 84/02/10
 ACRS Advisory Committee on Reactor Safeguards 20pp 22807 239
 24X Fishe 50-244, B4/02/10, B403280335
- 8403280341 Forwards rept on 831129-1201 meetings at Harpers Ferry, HV re IDCOR analysis program Becond meeting on same sub; matter, w/specific preestablished set of questions needed DENDER, M Querytech, Inc BENDER, M ACRS Advisory Committee on Reactor Bafeguards 84/01/04 KERR, W ACRS Advisory Committee on Reactor Safeguards 9pp 22807 194
- 8403280345 Summarizes ACRS Class 9 831012 meeting re 830922 rev to 830805 document, "Severe Accident Decisions for Existing Nuclear Power Plants " Regulatory questions.technical issues & direction of future meetings addressed CORRADINI.M ACRS Advisory Committee on Reactor Gafeguards 83/10/12 KERRW ACRS Advisory Committee on Reactor Safeguards 22pp 22799 334
- 8403270002 Final response to FOIA request fur four categories of documents tests, studies & analyses referencing or pertaining to NUREG-0103, "SIB for B&W PWR " App A documents encl FELTON, J M Division of Rules and Records 84/01/13 MADDEN. I J Raye, Scholer, Fierman, Hays & Handier 6pp 22816 127 24X Fiche. 50-000, 84/01/13, 8403270002
- --8403270068 Lists proposed reg guides that Engineering Stds Granch plans to submit to ACRB Safety Outde Subcommittee for consideration at Feb meeting. ARLOTTO.G A Atomic Energy Commission Directorate of Regulatory Standards 73/01/26 EURNB.W ACRS Advisory Committee on Reactor Safeguards ip 22816 337
- 8403290067 Summary of ACRS Subcommittee on Guality & QA in Design & Const 831206 meeting w/S&H, NUTECH Engineers, Inc. Sandia Labs, EEI, DDL, Gasser Assoc, Taylor Assoc, Fauth Assoc, Inc & Becktel in Washington, DC

 # ACRS - Advisory Committee on Reactor Baseguards 84.
 ACRS - Advisory Committee on Reactor Baseguards 19pp 84/01/25
- 8403290110 Forwards J Preston B30104 memo re generic safety issues prioritization methodology for placement in PDR ROBERTB.B J ACRS Advisory Committee on Reactor Safeguards 84/03/14 MCKNIGHT.J Distribution Services Branch | Ip 22822 214

- --8403P90113 Advises of review of generic safety issues prioritization methodology described in NUREO-0933 Inherent limitations of value impact score formule discussed Use of itructured & itriative consensus judgement methodology recommended PRESION. J ALRS Advisory Committee on Reactor Safeguards 83/01/04 BENDER. M ACRS Advisory Committee on Reactor Safeguards Safeguards 3pp 2/2022 219
- 8403290362 Summary of ACRS Subcommittee on Safety Research Program
 BA0111 meeting in Washington, DC to DMB final mark on NRC
 safety research program budget for FY85 & draft version of
 ACRS rept to Congress on related matter Viewgraphs encl
 8 ACRS Advisory Committee on Reactor Safeguards 84/02/22
 ACRS Advisory Committee on Reactor Safeguards 22pp 22882 266
- 8403300240 Summury of ACRS Subcommittee on Human Factors \$31207 meeting in Washington.UC re status of ongoing activities in NRC human Factors program plan, human reliability data base & uses & review of program budget for FYB5-86 e ACRS Advisory Committee on Reactor Safeguards 83/12/07 ACRS Advisory Committee on Reactor Safeguards 24pp 22842 320
- 8403300246 Commonts on containment performance guidelines.fifth source term meeting & severe accident program for LWR regulation CATTON.I ACRS Advisory Committee on Reactor Safeguards 84/02/06 HANG.A ACRS Advisory Committee on Reactor Safeguards 4pp 22840 348

ADVCM NRC ADVISORY COMMITTEE

- 8403080410 Responds to 840214 request for 30-day extension to comment on draft suppl to programmatic E15 Due date for comments extended to 840402 DENYON, H.R. Office of Nuclear Reactor Regulation, Director 84/03/01 MORRIS, A.E. Lancaster, PA. 2pp. 22381 328 24X Fiche 50-320,04/03/01.8403080410
- --B4030B0412 Requests JO-day extension to comment on programmatic EIB update NBRRIS A E Advisory Council for Decontamination of TM1 Unit 2 B4/02/14 PALLADIND N J Commissioners 2pp 225B1 327 24X Fiche 50-320,84/03/01,8403080410

COMMISSION NRC CONMISSIONERS

- 8402130393 Responds to 840111 request for development of facility public safety oversight committee Merits of committee not judged due to util intention not to complete project as nucleor plant PALLADINO, N. J. Commissioners 84/01/31 COLLINS, M. L. Rentucky, Commonwealth nf. ip 22667 250 24X Fiche 50-359, 84/01/31, 8402130393
- --0402130399 Responds to 031212 request for development of facility public safety oversight committee Nerits of committee not judged due to util intention not to complete project as fuciliar plant PALLADINOLN J Commissioners 84/01/31 BORTZ, A Cincinnati, OH IP 22642 251 24X Fiche 50-338,84/01/31,8402130393
- --B402130390 Responds to 831221 request for development of facility public safety oversight committee Merits of committee not judged due to util intention not to complete project as nuclear plant PALLADINON J Commissioners 84/01/31 METZENBAUN.H & Senate, Lineray & Natural Resources 19 22662 232 24% Fichs 50-358,64/01/31:8402130393
- -8402130333 Responds to 831215 request for development of facility public safety appraight committee Merits of committee not judged due to util intention not to complete project as nuclear plant PALLABINON J Commissioners 84/01/31 CELESTER F Ohio. State of 4pp 22662 253 24X Fiche 30-3388-84/01/31,8402130393
- --B402130393 Requests development of proposed facility public oversight committee Committee establishment would inspire public confidence GOLLINS.M L. Kentucky. Commonwealth of. 84/01/11 PALLADINO.N Commissioners ip 22662
- --8402130392 Requests development of public oversight committee to review facility safety-related problems NRC & util credibility questioned as public witness cost overruns & safety flaws METZLIBAUM.H M Senate, Energy & Natural Resources 83/12/21 PALLADINO.N J Commissioners 19 22662 257 24% Fiche 30-359,84/01/31.8402130393

- --B402130360 Requests changes in proposed facility oversight committee Changes needed to inspire public confidence in oversight process CELESTE, R F Ohio, State of B3/12/15 PALLADINO, N Commissioners ip 22662 258 24X Fiche 50-358,84/01/31, RADE 13739
- B402220291 Responds to B31209 1tr in opposition to restart until all outstanding issues resolved PALLADING: N J Commissioners B4/01/31 HEINZ: J Senate Ip 22384 306 24X Fiche 70-289: 84/01/31: 8402220291
- --8403070003 Responds to 831212 Itr expressing concern re protracted time period for resolving TM1-1 restart issue Notice to parties assued on 840127 encl W/a encl PALLADINDO N J Commissioners 84/01/31 KOLTER J P House of Rep 1p 22584 305 24X Fiche 50-289.84/01/31.8402220291
- --8403090004 Responds to 831212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties assued on 840127 encl W/o encl PALLADINO,N J Commissioners 84/01/31 MURPHY,A J House of Rep Ip 22584 307 24X Fiche 50-289,84/01/31,8402220291
- --8403070005 Responds to 831212 Itr expressing concern re protrected tase period for resolving TMI-1 restart issue Notice to parties issued on 840127 encl W/o encl PALLADINO.N J Commissioners 84/01/31 MURTHA.J P House of Rep ip 22584 308 24% Fiche 50-289.84/01/31,8402220291
- --8403090007 Responds to B31212 ltr expressing contern re protracted time period for resolving TM1-1 restart issue Notice to parties issued on B40127 encl W/o encl PALLADINO.N J Commissioners B4/01/31 CLINOER.W F House of Rep ip 22584 309 24X Fiche 30-289.84/01/31.8402220291
- --840309000B Responds to 831212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on B40127 enci W/o enci PALLADIND.N J Commissioners 84/01/31 CAYDD9, J M House of Rep ip 22584 310 24X Fiche 50-289,84/01/31,8402220291
- --B403090009 Responds to 831212 itr expressing concern re protracted time period for resolving TMi-i restart issue Notice to parties issued on 840127 entl W/o entl PALLADIMON D J Commissioners 84/01/31 RiTTER,D House of Rep Ip 22584 311 24X Fiche 50-289,84/01/31,8402220291
- --8403090010 Responds to 831212 ltr expressing concern re protracted time period for resolving [Mi-1] restart issue Notice to parties issued on 840127 encl W/o encl PALLADIND, N J Commissioners 84/01/31 HARRISEN, P House of Rep 1p 22584 312 24X Fiche 30-289,84/01/31,8402220271
- --8403090013 Expresses concern re protracted time period for resolution of assues surrounding TMI-1 restart Commission should place primary emphasis on ability of util mgt to operate plant safely GAYDNS, J M. KOLTER, J P., MURPHY, A J House of Rep. 83/12/12 PALLADIND, N., OILLINSKY, V., RODERTS, T. Commissioners 259 22584 331 24X Ficho 50-289, 84/01/31, 8402220291
- --8403070011 Expresses concern re protracted time period for resolution of issues surrounding TMI-i restart Commission should place primary emphasis on ability of util mgt to operate plant safely HARRISON.F House of Rep. 83/12/13 PALLADIND.N., CILINSKY,V., ROBERTS,T. Commissioners 2pp. 22584-327, 24X Fithe 50-289,84/01/31,8402220291
- 840:1010024 Responds to PDIA request for documents re petition for rulemaking PRM-50-31 from Citizens Task Force of Chapel Hill:NC Forwards App A documents App B documents completely withheld (ref FDIA Exemption 5) FELION.J H. Division of Rules and Records 84/01/18 SHOLLY:S C Union of Concerned Scientists 4pp 22446 035
- --8403010038 Requests documents re petition for rylemaking PRM-50-31 filed by Citizens Task Force & R Bernero 830916 memo to NIC div directors re draft rylemaking on emergency preparedness MARKLY,E J House of Rep , Interior & Insular Affairs 83/09/22 PALLADINO,N J Commissioners ip 28446,040
- 84030104/7 Responds to 840113 ltr re release of radioactive matl into atmosphere & embrittlement of containment shells in older nuclear power plants & capability of containment structure to withstand pressurized thermal shock RCM10N:H R Defice of Nuclear Reactor Regulation, Director 84/02/15 AMEDRD.D A Affiliation Not Assigned 3pp 22438.300

- --B403D10500 Expresses concern re backward shift rotation of plant operators & embrittlement of containment shells in older nuclear power plants due to constant bombardment of high levels of radiation AMDORD D A Affiliation Not Assigned B4/01/13 PALLADIND, N J Commissioners ip 2243B 303
- 8403050196 Requests to be notified if WO Bell will continue to be state limits on officer or if new limits on officer will be appointed PALLADINON J Commissioners 84/02/22 ALLAIN,WA Mississippi, 8tate of 2pp 22528 i85
- 8403050200 Forwards rept on administration of FOIA by NRC for CY83,per Public Law 93-502 PALLADING,N J Commissioners 84/02/24 O'NEILL,TP House of Rep. Speaker of the House 1p 22528 167
- --B403050204 Forwards rept on administration of FDIA by NRC for CYB3, per Public Law 93-502 PALLADINO, N J Commissioners B4/02/24 BUSH, O H Senate, President of the Senate 14pp 22528 168
- 8402030346 Notifies of reappointment to ACR8
 PALLADING N J Commissioners 84/02/22 EBERSOLE, J. C Affiliation
 Not Assigned EBERSOLE J C ACRS Advisory Committee on Reactor
 Safeguards 1p 22501 321
- 8403030348 Notifies of reappointment to ACRS
 PALLADING.N J Commissioners 84/02/22 SIESS.C P Affiliation
 Not Assigned 81ESS.C P ACRS Advisory Committee on Reactor
 Safoguards ip 22501 322
- 8403050362 Forwards responses to B3ii08 questions for inclusion in record of 830906 hearing re Southeast Interstate Low Level Radwaste Mgt Compact PALLADINO,N J Commissioners 84/02/09 THURMOND,8 Senate, Juditiary 16pp 22519 267
- 8403050379 Requests to be notified if RL Sanders will continue as state IIalson officer or if new liaison will be appointed PALLADINO,N J Commissioners 84/02/22 COLLINS,M L Kentucky, Commonwealth of, 2pp 22527:256
- 8403060014 Prepared testimony of NJ Pelladino to Subcommittee on Nuclear Regulation. Committee on Environ & Public Works, UB Senate re Commission budget request for FY85 PALLADINO, NJ Commissioners 84/02/23 23pp 22548:260
- B403060018 Forwards NRC CYB3 summary of actions taken in response to Comptroller General recommendations. Activities fall short of intent of Recommendation 2 of GAU/RCED-83-4 re improving reactor operator capabilities W/o encl PALLADINON J Commissioners. 84/01/31 HATFIELD.M D Senate, Appropriations ip R2528 338
- --8403060023 Forwards NRC CYB3 summary of actions taken in response to Comptroller General recommendations Activities fall short of intent of Recommendation 2 of GAD/RCED-83-4 re improving reactor operator capabilities W/o encl PALLADING.N J Commissioners 84/01/31 RDTH,W V Bonate, Governmental Affairs 1p 22528 339
- --8403060030 Forwards NRC CYB3 summary of actions taken in response to Comptroller General recommendations Activities fall short of intent of Recommendation 2 of OAD/RCED-83-4 re improving reactor operator capabilities W/o encl FALLADING.N.J Commissioners 84/01/31 BRODKS.J House of Rep., Government Operations 1p 22328 340
- --8403060037 Forwards NRC CY83 summary of actions taken in response to Comptroller General recommendations Activities fall short of Intent of Recommendation 2 of GAD/RCED-83-4 re improving reactor operator capabilities W/o encl PALLADINO,N J Commissioners 84/01/31 SIMPSON,A K Senate, Environment & Public Works ip 22328 341
- --B403060046 Forwards NRC CYB3 summary of actions taken in response to Comptroller General recommendations Activities fall short of intent of Recommendation 2 of GAD/RCED-83-4 re improving reactor operator capabilities W/o encl.
 PALLADING,N J. Commissioners 84/01/31 UDALL,N K. House of Rep. Interior & Insular Affairs ip, 22528 342
- --B4G3060061 Forwards NRC CYB3 summary of actions taken in response to Comptroller General recommendations Activities fall short of intent of Recommendation 2 of GAD/RGED-83-4 re improving reactor operator capabilities W/o encl PALLADINO.N J. Commissioners, 84/01/31 OTTINGER,R L House of Rep , Energy & Commerce ip 22528 343

- B403060065 Forwards NRC CYB3 summary of actions taken in response to Comptroller General recommendations Activities fall short of intent of Recommendation 2 of GAD/RCED-83-4 re improving reactor operator capabilities W/o end. PALLADINO.N J Commissioners 84/0i/31 WHITTEN.J House of Rep , Appropriations ip 22528 344
- --840306007i Forwards NRC CYB3 summary of actions taken in response to Comptroller General recommendations Activaties fall short of intent of flocummendation 2 of GAD/RCE0-83-4 re improving reactor operator capabilities M/o enc! PALLADING.N J. Commissioners 84/01/31 BOWSHER.C A General Accounting Office 1p 22528 345
- --8403060074 Forwards NRC CYB3 summary of actions taken in response to Comptroiler General recommendations Activities fall short of intert of Recommendation 2 of GAO/RCED-83-4 re improving reactor operator capabilities
 PALLADIND N J Commissioners 84/01/31 STOCKMAN, D A Office of Management & Budget 7pp 22528 346
- 84030404B7 Weekly info rept for Wk ending 840224 REHM.T A Office of the Executive Director for Operations 84/03/01 45pp 22552 116
- 8403070053 Responds to 831214 ltr suggesting Commission refuse to restart Unit 1 until funding for Unit 2 cleanup in place Commission does not believe that Unit 1 restart & Unit 2 cleanup should be tied together PALLADIND.N J Commissioners 84/02/08 PDRRIS.A E Advisory Council for Drentamination of TMI Unit 2 1p 22563 198 24X Ficho 50~287.84/02/08.8403070053
- ~-8403070060 Responds to 831213 ltr re-criminal indictment of Met Ed 'c cleanup of Unit 2 Commission does not believe delaying restart would accelerate Unit 2 Cleanup Unit i restart & Unit 2 cleanup should not be tied together PALLADING:N J Commissioners 84/02/08 MORRIS;A E House of Rep 1p 22563 199 24X Fiche 50-289,84/02/08,8403070053
- --B403070069 Responds to B31207 Itr urging Commission not to authorize restart of Unit 1 Commission views on restart set forth in encl B40127 notice to parties Commission does not believe Unit i restart & Unit 2 cleanup related PALLADINO.N J Commissioners B4/02/0B QEKAS,0 W House of Rep 1p 22563 200 24% Fiche 50-289,84/02/08.8403070050
- --84030/0073 Urges Commission not to accept recommendation to restart Unit i in light of mgt integrity review & criminal proceedings & slow pace of Unit 2 cleanup CEKAS, G W House of Rep 83/12/07 PALLADING, N J Commissioners ip 22563 217 24X Ficho 50-289,84/02/09,8403070053
- --B4030/0076 Advises of convictions re Unit 1 restart Due to criminal indictments & belief that Unit 1 revenue should go directly toward Unit 2 cleanup, recommends against restart WALKER,R S House of Rep 83/12/13 PALLADINO,N, ASSELSTINE,J BERNIHAL,F Commissioners ip 22563 218 24X Fiche 50-289,84/02/08,8403070053
- B4031203/6 Responds to 840107 request for info re accident source term & emergency planning zone Final resolution will not be made until review process complete PALLADING.N J Commissioners 84/02/04 MARKEY.E J House of Rep , Interior & Insular Affairs 3pp 22617 081
- --B4031203BB Responds to statements in Markey B40109 ltr re impact of Citizens Task Force petition on emergency preparaness rule Rev to emergency preparedness rule independent of source term reevaluation DIRCKS.W J Office of the Executive Director for Operations B4/01/24 PALLADING, N Commissioners 2pp 22619 084
- --84031P0393 Advises that draft info & documents provided in response to 830922,1028 & 1220 ltrs re offsite emergency preparedness creates impression Chairman position used to pursue politically motivated regulatory changes MARKLY.E.J. House of Rep., Interior & Insular Affaira 84/01/09 PALLADING, N.J. Commissioners 5pp. 22619 094
- 8403160032 Responds to 831206 ltr re Commission consideration of applicant request for Commission approval of restart Final decision will be made in near future PALLADIND, N U Commissioners 84/03/15 UDALL, N K House of Rep , Interior & Insular Affairs 2pp 22655 141. 24x Fiche 50-289,84/03/15,8403160032

84/03/01 - 84/03/31 PAGE 1

MONTHLY TITLE LIST U S NUCLEAR REGULATORY COMMISSION B4/03/01 - 84/03/31 PAGE

MONTHLY TITLE LIST
U S NUCLEAR REGULATORY COMMISSION

8403260106 Provides current status of facility literaing process in response to 840126 ltr Bince 840124 hearings NRC has continued investigation, may be evaluation of allegations, which will be resolved prior to low power authorization DENTON, HR Defice of Nuclear Reactor Regulation, Director 84/03/07 MCCARTHY.L T California. State of 4pp 82761 356 24X Fichs 50-275, 84/03/07, 8403260106

--8403260111 Expresses concern re possibility that facility will be licensed w/o meeting safety stds MCCARTHY.L T California, State of 84/01/26 PALLADING.N Commissioners Ip 22761 359 24X Fiche 50-275,84/03/09,8403260106

8403280153 Forwards documents for inclusion in Cheirman 840223 testimony before Senate Subcommittee on Nuclear Regulation. Committee on Environ & Public Works

a Office of Congressional Affairs 84/03/08 Record Services
Branch (Document Control Deski in 22807 294 24X
Fiche '0-287,84/03/08.8403280153

--B403280157 Testimony of V Gilinsky on B40223 before Subcommittee on Nuclear Regulation.Committee on Environ & Public Works re rearienting NRC toward nuclear operations & budget shifts away from research GILINSKY,V Commissioners 84/02/23 13pp 22809 275

--8403280160 Statement of JK Asselstine on 840223 re Commission authority to issue temporary OL, review of NRC NSHC determination pertaining to steam generator repairs at TMI-1 & licensing refulm legislation
ASSCLSTINE, JK Commissioners. 84/02/23 Bpp 22809 308 24X Fiche 50-289, 84/03/88, 8403280153

3403280248 Requests info re lack of issuance of revised proposed rule on diverse scram sys for Westinghouse reactors approved on 831103 OILINSKY, V Commissioners 84/03/06 Commissioners ip

3403290087 Forwards rept directed by 830524 House Rept 98-217 re NRC progress on backfitting rule to replace 100FR50 109 & measures to control issuance of plant-specific requirements PALLADING.N J Commissioners 84/03/12 BEVILL.7 House of Rep Appropriations 4pp 22822 210

.DNTRACT NRC CONTRACTS AND MODIFICATIONS

1403010003 Notification of contract execution, Mod 12, to "Technical Assistance in Repository Design" Contractor Golder Assoc BELOATCH, V Technical Assistance Contracts Branch NRC-02-81-037 G4/01/20 DAVIS, J Office of Nuclear Material Safety & Safeguerds, Director BUCKLEY, J NRC - No Detailed Affiliation Given 1p 22479 337

--8403010004 Mod i2.estending period of performance to 840229 % deleting L Haltung & adding J Buckley as project officer, to "lechnical Assistance in Repository Design"
JALMOT.R Colder Associates GUSTAVE,R P Division of Contracts
NRC-02-81-037 84/01/20 Ip 22479 338

1403010019 Notification of contract execution. Mod 15. to "Licensing Technical Assistance" Contractor Science Applications. Inc PAGE.M Technical Assistance Contracts Branch FIN 8-7391-3 NRC-02-83-035 84/02/22 DAYIS.J Office of Nuclear Haterial Safety & Safeguards. Director LAYSEN.P NRC - No Detailed Affiliation Given 1p 28479 344

--8403010027 Hos 15, extending period of performance of Task Order 001 to 860121 at no add1 cost.to "Licensing Technical Assistance" * Science Applications, Inc. GUSTAVE.R P Division of Contracts FIN 8-7391-3 NRC-02-83-033 84/02/22 jp 22479 345

3403010035 Notification of contract execution, Mod 9, to "Career Counseling " Contractor Binder, Elster, Mendelson & Wheeler PERLMAN, J Administrative Contracts Branch NRC-10-82-358 84/02/21 DDRIEW Office of Administration VAN BANTEN, L NRC - No Detailed Affiliation Given. 1p 22479, 346

--8403010044 Mod 9.extending period of performance to 850131 & increasing Funds, to "Career Counseling"
MENDELSON, I N Binder, Elster, Mendelson & Wheeler, Inc.
HA96N, I F Division of Contracts NRC-10-82-358 84/02/21 2pp

1403010040 Notification of contract exacution.Mod 2.to "Gubscription Svcs to 1983 Eddtion of ASME Boiler & Pressure Vessel Code "Contractor ASME HARKINS, D A Division of Contracts NRC-10-83-349 84/02/22 BEBAH, M.J. Division of Technical Information & Document Control CUNYNORAM.M MRC - No Detailed Affiliation Given 1p 22479:351

--8403010045 Mod 2.revising address in Attachment XI.to "Subscription Svcs to 1983 Edition of ASME Boiler & Pressure Vessel Code " SDMCLOHSKI, W. American Society of Mechanical Engineers HAGAN.T F. Division of Contracts NRC-10-83-369 84/02/22 1p 22479 352

8403010051 Notification of contract execution, Mod 4, to "Technical & Engineering Support Svcs for Radio Communications "Contractor DDI MCLEAREN, T Administrative Contracts Branch NRC-10-83-352 84/02/21 CORLEY, J Division of Facilities & Operations COMEN, B. MELVILLE, T NRC - No Detailed Affiliation Olven ip 22479 349

---8403010060 Mod 4.providing addi funds for FY84 & changing abligation of funds, to "Technical & Engineering Support Svcs for Radio Communications"

* Interior, Dept of HAGAN, T F Division of Contracts
NRC-10-83-352 84/02/21 1g 22479 350

8403010070 Notification of contract execution, Mod &, to "Analysis of Atmosphere Diffusion Through Application of Lider Technology "Contractor SRI Intl HOLLETT'S Technical Assistance Contracts Branch FIN 8-6793 NRC-04-81-211 84/02/10 BATSON'N Office of Nuclear Regulatory Research Director KORNASIEWICZ NRC - No Detailed Affiliation Given ip 22479 353

--8403010078 Mod & extending period of performance to 850131 & changing consideration & payment, to "Analysis of Atmospheric Diffusion Through Application of Lidar Technology"
Hilly,C F SRI International GUSTAVE,R P Division of Contracts FIN B-6793 NRC-04-81-211 B4/02/10 2pp
22079 354

84030100?1 Notification of grant execution, Mod 5, to "Experimental Phase of Development of Noninvasive Liquid Level & Density Gauge for Nuclear Power Reactor Vessels" Grantes Pennsylvania State Univ UNBEL, D Technical Assistance Contracts Branch FIN 0-1029 NRC-0-04-81-024 84/02/14 BATSON, W Office of Nuclear Regulatory Research, Director CHEN.Y NRC - No Detailed Affiliation Given ip 27479 357

--8400010098 Mod 5.increasing funds & extending period of performance to B40501.to "Experimental Phase of Development of Noninvasive Liquid Level & Density Gauge for Nuclear Power Reactor Vessels "

BABE.K Pennsylvania State Univ , University Park, PA MORTON Technical Assistance Contracts Branch FIN 0-1053 NRC-0-04-81-024 B4/02/14 1p 22477 358

8403010435 Notification of contract execution, Mod 4, to "Stenographic Reporting Svcs" Contractor Toyloe Assoc Hollenken, T Administrative Contracts Branch NRC-17-83-399 84/02/24 HOYLEJJ C Office of the Becretary of the Commission SULLIVAN.P, NDRAN.D NRC - No Detailed Affiliation Given 1p 22449 1200

--8403010437 Mod 6, Extending period of performance to 840315, to "Sterographic Reporting Sycs" RILEY, A Tayloe Associates HAGAN.TF Division of Contracts NRC-17-83-399 84/02/24 ip 22449 321

8403010461 Notification of contract execution, Mod 9, to "Quantitative Classification of Two Phase Flow Regimes Using Global & Lucal Neutronic Perturbations II" Contractor Univ of Hashington UNIBCL II Technical Assistance Contracts Branch FIN B-6324 NRC-04-78-245 84/02/10 BATSON, W Office of Nuclear Regulatory Research, Director SUDER, N NRC - No Detailed Affiliation Given 19 22438 283

--8403010462 Mod 9, extending period of performance to 840331, to
"Quantitative Classification of Two Phase Flow Regimes Using
Global & Local Neutronic Perturbations II "
BALDHIN.D R. Washington, Univ of, Seattle, WA GUSTAVE, R P
Division of Contracts FIN B-6324 NRC-04-78-245 84/02/10
Zpp. 22438 284

8403010528 Notification of contract execution, Mod 2, to "Automated Library Sys " Contractor On-Line Computer Sys, Inc BASSET: H Division of Data Automation & Management Information NRC-33-83-454 84/02/24 BROMBERO, B J Administrative Contracts Branch ZUNGOLI S NRC - No Detailed Affiliation Given ip 22438 344

--8403010334 Mod 2.changing govt property & extending period of performance to 850101 at no add1 cost.to "Automated Library Sys" >> Online Computer Systems, Inc HAGAN, T Division of Contracts NRC-33-83-454 84/02/24 2pp 22438,345

- 8403020037 Notification of contract execution "Dreaden & Perry Simulator Leasing," awarded to GE
 JESSUP, B Technical Assistance Contracts Branch FIN B-8713
 NC-05-84-159 84/02/17 HAVINS, D H Director's Office Office of Inspection and Enforcement ip 22491 045 24X
 Fiche 50-000,84/02/17,8403020037
- --8403020043 Contract "Dresden & Perry Simulator Leasing." awarded to GE PIERCE.R L General Electric Co MORTON, K V Division of Contracts FIN D-8713 NRC-05-84-159 84/02/17 38pp 22491 046 24X Fiche 30-000,84/02/17,8403020037
- B4D3D2O069 Notification of contract execution, Mod 3, to "Technical Assistance in Defense of Appeal of TERA Advanced Svcs Corp before OSA Board of Contract Appeals " Contractor Dataflow Sys. Inc
 TOWNSEND: B L Administrative Contracts Branch NRC-10-83-368
 64/02/27 NORRY, P O Office of Administration AVERY, R E NRC No Detailed Application Given 1p 22491 187
- --8403020073 Mod 3, adding computer svcs & changing dollar amount of contract, to "Technical Assistance in Defense of Appeal of TERA Advanced Svcs Corp before OSA Doard of Contract Appeals"

 DOUDNIKOTT, B Dataflow Systems Inc REBELLO. J E Division of Contracts NRC-10-83-368 84/02/27 ip 22491 170
- --8403020077 Submits proposal to assist in analyzing selected data collected in course of Docket 6713-NRC re NRC Contract 10-83-368 W/o consuitants description of projects MALCOM.J D Dataflow Systems. Inc. NRC-10-83-368 84/02/21 AVERY.R Commissioners 3pp 22491 191
- B403050231 Notification of grant execution, Mod 3: to "Study of Steam Mater Flows" Grantes Northwestern Univ UMBEL. ID Technical Assistance Contracts Branch FIN 9-1000 NRC-9-04-BI-020 B4/02/13 BATEON. W Office of Nuclear Regulatory Research, Director ZUBER, N NRC No Detailed Affiliation Given 1p. 22327 25:
- --B403050237 Mod 3, providing add1 funds, extending period of performance to 840930 & changing project officer to "Study of Steam Water Flows"

 GEALY, W J. Northwestern Univ , Evanstan, IL MORTON, K J. Technical Assistance Contracts Dranth FIN 0-1000 NRC-G-04-B1-020 84/02/13 1p 22527 252
- 8403040471 Notification of contract execution, Mod 3, to "Development of Reg Quide & Regulatory Analyses " Contractor Analysis & Technology, Inc JACOBB, A Technical Assistance Contracts Branch FIN B-8645 NRC-02-83-107 84/02/27 DENTON.H R Office of Nuclear Reactor Regulation, Director BENDER, L NRC No Detailed Affiliation Given ip 22552 207
- ---8403040495 Mod 3,increasing funding & extending period of performance to 841031.to "Development of Reg Guide & Regulatory Analyses" JANKONSKI.S M Analysis & Technology, inc MORTON, K V Division of Contracts FIN B-8645 NRC-02-83-107 84/02/27 1g 22552 208
- B403060500 Notification of contract execution, Mod 11, to "Fission Product Transport Analysis" Contractor. 2M1 PAGE.M Technical Assistance Contracts Branch FIN 8-6747 NRC-04-80-177 84/02/27 BATSON.W Office of Nuclear Regulatory Research, Director WALKER, T NRC - No Detailed Affiliation Given 1p 22552 185
- ---8403060502 Mod il,increasing funding to "Fission Product Transport Analysis" * Battelle Memorial Institute. Columbus Laboratorias MDRTON: K V Division of Contracts FIN B-6747. NRC-04-80-177 84/02/27 io 22532 86
- B403070005 Notification of contract execution "Technical Assistance for Support of Const Appraisal Team Insps," awarded to Parameter, Inc WIGGINS, E. J. Technical Assistance Contracts Branch FIN B-8718 NRC-05-84-152 B4/02/06 DEYOUNO, R. C. Director's Office, Office of Inspection and Enforcement DAKER, E. NRC No Detailed Affiliation Given 1p 22562 354
- --B403070007 Ltr contract "Technical Assistance for Support of Const Appraisal Team Insps." awarded to Parameter. Inc MDRTUN.K V Division of Contracts FIN B-8718 NRC-05-84-152 B4702706 LOFY.R A Parameter. Inc 168pp 22562:355

- 84030700,'9 Notification of grant execution, Mod 2, to "Investigation of Recent Crustal Movements in State of ME" Grantee State of ME UMBEL.D Technical Assistance Contracts Branch FIN G-1041 NRC-G-04-M2-009 84/02/27 BATSON, W Office of Nuclear Requistor Research, Director SCHMITT, T NRC No Detailed Affiliation Give. 1p 22563 194
- --8403070032 Mod 2,providing add1 funding,to "Investigation of Recent Crustal Movements in State of ME" ANDERSON,R D , ANDERSON,N A Maine, Blate of MORTON,K V Technical Assistance Contracts Branch FIN 9-1041 NRC-9-04-82-007 84/02/27 ip 22563 175
- 0403070037 Notification of contract execution Nod 13 to "Site Suitability Assassments Dased on Seepage & Groundwater Conditions Associated W/U Recovery Operations " Contractor Williams & Associated Contracts Granch NRC-02-81-039 84/02/27 SNITH.D R Uranium Recovery Field Office GARCIA.P No Detailed Affiliation Given 1p 22563 196
- --8403070044 Mod 13.extending period of performance through 840430 at add1 cost to "Bito Sultability Assessments Based on Seepage & Groundwater Conditions Associated W/U Recovery Operations " Williams & Associates GUSTAVE, R P Division of Contracts NRC-02-81-037 84/02/27 ip 22563 197
- 8403070152 Notification of contract execution "Technical Support for Region I NDE Van," awarded to VJ Thompson.Inc TOLSON.V Region i. Office of Director FIN 0-8361 NRC-28-D4-431 84702/08 MCGSCAR.J Region i. Office of Director DURR.J P Na Detailed Affiliation Given Iρ 22364 327
- ---B403070161 Contract "Technical Support for Region I NDE Van," award to VJ Thompson Inc THOMPSON V J Vester J Thompson, Jr. Inc MORTON, K V Divisio of Contracts FIN β-8361 NRC-28-84-431 84/02/08 8pp 2254 320
- --H403070167 Forwards amend to original Articles of Incorporation Amen changes name of company to Thompson Engineering lesting. Inc & decreases par value of stock to correspond w/tax laws Requests contract be amended to reflect name change SHUMACK.JH Vester J Thompson. Jr. Inc. 84/02/08 MDRTON.K V Jochnical Assistance Contracts Branch. 7pp 22364 336
- --H403070172 Forwards Solicitation for Proposals RS-RG1-84-431. "Technical Support for Region I NDE Van " Wencle MORTON K V Technical Assistance Contracts Branch 83/10/11 Affiliation Not Assigned 177pp 22544 343
- 8403070339 Notification of contract execution "Structural Integrity o LMR Boundary Components - 11," awarded to Matls Engineering Assoc.lnc EDGLWORTH:P Technical Assistance Contracts Dranch NRC-04-84-102 84/02/10 FOREHAND.B Office of Nuclear Regulatory Research, Director VAGINS.M NRC - No Detailed Affiliation Given ip 22566 059
- --B4030/0346 Ltr contract "Structural Integrity of LHR Boundary Components - II." awarded to Matis Engineering Assoc.Inc MDRTON.K V Division of Contracts NRC-04-B4-IO2 B4/02/IO ORFENBLATT,M Materials Engineering Associates, Inc. ip 22546 040
- B403070371 Notification of contract execution, Mod 5, to " Review, Abstract.Index & Guarterly Update Practice & Procedure Bigest " Contractor Aspen Sys. Inc PERLNAN, J. Administrative Contracts Branch FIN B-1588 NRC-14-82-448 B4/02/29 CUNNINGHAM G H , GRAY, J. Office of the Executive Legal Director 1p 22567 178
- --8403070373 Mod b, extending period of performance to 850228 & increasing funds, to "Review, Abstract, Index & Quarterly Update Practice & Procedure Digest"

 **Aspen 8gstems, Inc HAGAN, T F Division of Contracts flN D~1588 NRC-14-82-448 84/02/29 lp 22547 199
- 8403070380 Notification of contract execution.Mod 5, to "Evaluation of Locations & Rates of Groundwater Discharge from Sheffield Low level Waste Disposed Facility "Contractor USG9 PAGE.M Technical Assistance Contracts Branch NRC-02-80-069 84/03/01 DAVIS.J Diffice of Nuclear Material Safety & Safeguards.Director GODDE.D J NRC No Detailed Affiliation Olven 1p 22547 041
- --8403070383 Mod 5, changing name of project officer, to "Evaluation of Locations & Rates of Groundwater Discharge from Sheffield Low Level Waste Disposal Facility "

 * Interior, Dept of Geological Survey SMITH P Division of Contracts NRC-02-80-049 84/03/01 lp 22567 042

- B403070411 Notification of contract execution, flod 3, to "Major Earthquakes on Lett Side of New Madrid Earthquake Zone "Contractor Vanderbilt Univ PAGE, N Technical Assistance Contracts Branch FIN B-8078 NRC-04-81-195 84/02/29 BATSON, W Office of Nuclear Regulatory Research, Director MURPHY, A NRC No Detailed Affiliation Given ip 27967 020
- --8403070414 Mod 3,increasing funding to "Major Earthquakes on East Side of New Madrid Earthquake Zone" « Vanderbiit Univ , Nashville, TN SMITH P Division of Contracts FIN B-8078 NRC-04-81-195 84/02/29 ip 22567 021
- 8403070133 Notification of contract execution Mod 4.to "Non-Equilibrium Heat Transfer & Two-Phase Instrumentation " Contractor Lehigh Univ Lenigh Univ
 PAGE.N Technical Assistance Contracts Branch FIN B-6794
 NRC-04-81-183 B4/02/27 BATSON,N Office of Nuclear Regulatory
 Research, Director YDUNG,M NRC - No Detailed Affiliation Given
 1p 27534-361
- --8403090135 Mod 4, increasing funding to fully fund contract, to "Non-Equilibrium Heat Transfer & Two-Phase Instrumentation" % Lehigh Univ. Bethlehem, PA MORTON, K.V. Division of Contracts FIN B-6794 NRC~04-Bi-183 84/02/27 ip 22984 360 22594 362
- 8403090i38 Notification of contract execution Mod 2, to "Investigation of Alternative Heans to Accomplish Goals of Diennial Calibr of Ionization Chambers " Contractor Univ of Misconsin-MAdison
 PAGE, M Technical Assistance Contracts Branch NRC-04-83-0
 84/02/27 BATSON.W Dffice of Nuclear Regulatory Research.
 Director YANIV.S NRC - No Detailed Affiliation Given i NRC-04-83-002
- --8403090i41 Mod 2 revising contract statement of work & schedule for deliverables at no addl cost & incorporating addl general provisions to "Investigation of Alternative Means to Accomplish Goals of Biennial Calibr of Innization Chambers " ERICKSUN R W Wisconsin. Univ of Madison. WI QUBTAVE, R P Division of Contracts NRC-04-83-002 84/02/27 5pp 22592 305 22592 304
- BADDIZOPP' Notification of contract elecution, Mod 5, to "Fire Protection Review Case Work Plants : "Contractor Gage Babcock & Assoc UNNLL,U Technical Assistance Contracts Branch FIN B-8020 NRC-03-82-118 84/03/02 VOLLNER,R H Division of Engineerit NOLAN,I NRC - No Detailed Affiliation Olvon 1p 22615 358
- --8403120226 Nod 5, revising Article IX re travel reimbursement, to "Fire Protection Program Review Case Work Plants 1 " * Gage-Dabcock Associates, Inc SMITH, P Division of Contracts FIN N-8020 NRC-03-62-118 84/03/02 ip 22619 359
- E403190306 Notification of contract execution Mod 5, to "NRC Procurement Training for Project Officers " Contractor Graduate School USDA PERLANAL Administrative Contracts Branch NRC-10-8i-402 84/02/28 DDRIE W Office of Administration BASSIN, C M Dovelopment & Tiaining Staff 1p 22896 357 Management
- --8403120314 Mod 5. adding new course & increating funds, to "NRC Procurement Training for Project Officers"

 VARNIRL S Agriculture, Dept of, Graduate Bohool HAGAN, T F
 Bly/sign of Contracts NRC+10-81402 84/02/28 2pp 22896 22396 358
- 8403;20340 Notification of contract execution. Med 2, to "Supervising Human Resources Course" Contractor Oraduate School.USDA PERLHAN. J Administrative Contracts Branch NRC-10-82-366 84/02/22 90,004AN, P J Management Development & Training Staff SPECTUR. A NRC ~ No Detailed Affiliation Given Ip 28649 138
- --8403120349 Mod 2.extending period of performance to 841231 at no add1 cost.to "Supervising Human Resources Course"
 VARNIR.L S Agriculture, Dept of, Graduate School HAGAN,T F Division of Contracts NRC-10-02-366 84/02/22 ipp 22619 139
- 8403130494 Notification of contract execution "Page Make-up Svcs." awarded to Photocreft Custom Lab. Inc Invitation for bid FIELDS, JA Administrative Contracts Branch NRC-10-84-231 84/02/23 DESAW W J Division of Technical Information & Document Control THO7-THOMPSON NRC - No Detailed Affiliation Given Ep 22634 250
- --B403130495 Solicitation.offer & award of "Page Make-up Sycs" awarded to Photograft Custom Lab, Inc. MATTIA, M J Division of Contracts NRC-10-84-231 84/02/23 93pp 22634 238

- 8403140325 Notification of contract execution, Mod 4, to "Earthquake RECUrronco Intervals at Nuclear Power Plant Sites
 Contractor Ertoc Western.Inc
 JACOBS, A Technical Assistance Contracts Branch
 NRC-04-81-147 84/03/05 BATRON.W Office of N.
 Research. Director MURPHY, A NRC - No Detailed
 1p #P635 301 FIN B-7224 BATEON, W Office of Nuclear Regulatory
 Y, A NRC - No Detailed Affiliation Given
- --B40314032B Mod 4.extending period of performance to B4022B at no addition to the country of th
- 8403150194 Notification of contract execution, Mod 11, to "Memphis Area Regional Seismic Network New Madrid " Contractor gional Seismic Network ...
 nphis State Univ
 COBS, A Technical Assistance Contracts Branch FIN B-4276
 C-04-78-200 84/03/05 BATSON, W Office of Nuclear Regulatory
 search, Director MURPHY, A NRC - No Detailed Affiliation Given NRC-04-78-200 Research, Director 1p 22646 266
- --8403150196 Mod II.extending period of performance to 841130 & intreasing funds, to "Memphis Area Seismic Network New Modrid " Supplemental agreement & App A encl CARPINTER, TO Memphis State Univ . Hemphis, TN OUSTAVE, R P Division of Contracts FIN B-6276 NRC-04-78-200 89/03/03 5pp 22646 267
- B403150204 Notification of contract execution, Mod 1, to "Technical Assistance to Bupport IE Personnel in Integrated Dasign Insp." Contractor Westec Svrs. Inc EDGEHURTH.P Licensing Branch 3 NRC-05-84-151 84/02/28 ML Director's Office. Office of Inspection and Enforcement PARTL NRC No Detailed Affiliation Given 1p 22649 354 MUTR. A PARTLON, J
- --8403150209 Ltr Contract NRC-05-84-151. Mod i, increasing funding, to "Technical Assistance to Support IE Personnel in Integrated Design Insp "NORTON: K V Division of Contracts NRC-05-84-151, 84/02/28 SARGLNT, I H Westreco, Inc 1p 22649 355
- B4031502/O Notification of contract execution, Mod 2, to "Autoprint 1800 "F" Microfiche Printer " Contractor Tameran, Inc HAMKINS, D A Division of Contracts NRC-10-83-723 B4/03/07 BESAN, W Division of Technical Information & Document Control BKDCZIAS, J NRC No Detailed Affiliation Given 1p 22662 036
- --B403150278 Mod 2.extending deliverable items date to 840312.to "Autoprint 1800 "F" Microfiche Printer " * lameran. Inc HAGAN.T F Division of Contracts NRC-10-83-723 84/03/07 2pp 22662 037
- ~~8403150306 Advises that, due to late delivery of Contract NRC-10-83-723, vendor offers to extend warranty period to 180 days & establishes firm delivery date of 840312
 DYBELLIJ C Tampran, Inc NRC-10-83-723 84/02/09 HAWKINB, D
 Division of Contracts 1p 22662 039
- B403220816 Notification of contract execution, Mod 1, to "Maint & Operation of LPDRs " Contractor Perry, OH Public Library TOWNSEND, D Administrative Contracts Dranch NRC-10-83-736 B4/03/12 FELTCH, J M Office of Administration SOUDER, J No Detailed Affiliation Given ip 22721 359 NRC -
- --B403220219 Mod i.correcting serial number on microfiche reader/printer, to "Maint & Uperation of LPDRs " * Perry, ON REBELLO, J E Division of Contracts NRC-10-83-736 B4/03/12 Ip 22721 360
- 8403220240 Contract "Subscription to Energy Daily." awarded to Energy Daily THOMAS.B P Energy Daily, Inc. MATTIA.M J Division of Contracts NRC-10-84-275 84/02/17 36pp 22739 076
- B403220256 Notification of contract execution. Mod 1. to "Maint & Operation of LPDRs " Contractor Plymouth. MA Public Library TOWNSEND. B Administrative Contracts Branch NRC-10-83-748 B4/03/12 FELTON. J M Office of Administration SUUDER. J No Detailed Affiliation Given. 1p 22723 323 NRC -
- --B403220262 Mod i.correcting serial number on microfiche reader/printer.
 to "Maint & Operation of LPDRs"
 s Plymouth, MA NRC-10-83-748 84/03/12 1p 22723, 324
- 8403220275 Notification of contract execution, Mod 1, to "Maint & Operation of Lipons." Contractor Univ of Wisconsin Analts & Operation of Lipons." Contractor Univ of Wisconsin TOWNSEND. B Administrative Contracts Branch NRC-10-84-253. 84/03/12 FELTON, J M Office of Administration SQUBER, J No Betailed Affiliation Given ip 22723.313 NRC -

;

1

- --8403220280 Mod 1.correcting serial number on microfiche reader/printer. to "Maint & Operation of LPDRs " * Wisconsin, Univ of, Green Bay, WI REBELLO, J E Division of Contracts NRC-10-84-253 84/03/12 ip 22723 314
- 8403220307 Notification of contract execution Mod 1. to "Maint & Operation of LPDRs " Contractor Greeley CO Public Library MURPHY.LE Administrative Contracts Branch NRC-10-83-742 84/03/08 FELTON.J M Office of Administration SOUDER, J NRC No Detailed Affiliation Given 1p 22723 340
- --B403220312 Mod 1, adding serial number for microfiche reader/printer, to "Maint & Operation of LPDRs" * Oreely, CO REBELLD.J E Division of Contracts NRC-10-83-742 8403/08 ip 22/23 341.
- 84032203i6 Notification of contract execution.Mod 2. to "Maint & Operation of LPDRs" Contractor LaCrosse,WI Public Library HOPPER,A Administrative Contracts Branch NRC-10-82-685 64/03/09 FEITON.J M Office of Administration SQUDER,J NRC No Detailed Affiliation Olyen 1p 22723 343
- --8403220319 Mod 2, changing serial number for microfiche reader/printer. to "Meint & Operation of LPDRs" + La Crosse, WI REBELLO, J E Division of Contracts NRC-10-82-685 84/03/09 Ip 22723 344
- 8403220325 Notification of contract execution.Mod i, to "Maint & Operation of LPDRs " Contractor Penfield Library, Oswego, N Y HOYLE, A Administrative Contracts Branch NRC-10-83-747 84/03/07 FELTON.J M Office of Administration SOUBER, J NRC ~ No Detailed Affiliation Given ip 22723 301
- --8403220327 Mod i,changing serial number on microfiche reader/printer,to "Maint & Operation of LPDRs "

 * Obwego, NY REBELLO,J E Division of Contracts

 NRC-10-83-749 84/03/07 ip 22723 302
- B403230044 Notification of contract execution Mod i, to "Maint & Operation of LPDRs" Contractor Norris, IL Public Library
 HOYLE: A Administrative Contracts Branch NRC-10-83-735 84/03/07
 FELTON.J M Office of Administration SOUDER, J NRC ~ No Detailed Affiliation Given ip 22742-361
- --8403230052 Mod i,changing serial number on 3M microfichs reader printer,to "Maint & Operation of LPDRs " * Morris, IL REBELLO,J E Division of Contracts NRC-10-83-735, 84/03/07 ip 22742 362
- 8403230071 Notification of grant execution. Mod 3.to "Davelopment of Radiation Stds " Grantse: ICRP UMBEL. D Technical Assistance Contracts Branch FIN 0-1035 NRC-0-04-82-004 84/03/05 DATSDN Office of Nuclear Regulatory Research Director FOULKE, J NRC No Detailed Affiliation Given to 22759 280
- --8403230076 Mod 3 extending period of performance to 850331 & increasing funds to "Development of Radiation Stds"

 SCHBY:F International Commission on Radiological Protection, MORTON & V Division of Contracts FIN G-1035, NRC-0-04-82-004 84/03/05 ip 22759 281
- 8403230129 Notification of contract execution "Quantification through Experimentation of Bource Term Lixely to Result from Sabotage of Spent Fuel Bhipments," awarded to Battelle Columbus Labs

 JEBSUP. B Division of Contracts FIN B-8977 NRC-04-84-113

 84/03/01 FOREMAND. B Office of Resource Management. Director BARNCLD. A NRC No Detailed Affiliation Oiven ip 22/41 307
- --8403230130 Contract: "Quantification through Experimentation of Source Term Likely to Result from Sabotage of Spent Fuel Shipments," awarded to Battelle Columbus Labs SEWELL.H M Battelle Memorial Institute, Columbus Laboratories MORTON,K V Division of Contracts FIN 8-8897 NRC-04-84-113 84/03/01 37pp 22741 308
- 8403230152 Notification of contract execution. Mod i, to "Maint & Operation of LPDRs." Contractor Crystal River, FL Public Library.
 TOWNBEND, B. Administrative Contracts Branch NRC-10-83-747
 84/03/12 FELTON, J M Office of Administration SQUDER, J NRC No Detailed Affiliation Qiven ip 22743 356
- --8403230154 Mod 1,correcting sarial number on microfiche reader/printer, to "Maint & Operation of LPDRs " * Crystal River, FL REBELLO, J E Division of Contracts NRC-10-83-747 84/03/12 ip 22743 357

- B403230159 Notification of contract execution.Mod 2, to "Selsmicity of Pacific Northwest (Northern State of OR) " Contractor Univ of Washington
 UMBEL.D Technical Assistance Contracts Branch FIN B-6614
 NRC-04-81-177 B4/03/07 BATSON.W Office of Nuclear Reactor
 Regulation. Director ZURFLEUH.E NRC No Detailed Affiliation
 Given ip 22743 352
- --8403230160 Mod 2.adding funds & extending period of performance to B41130.to "Seismicity of Pacific Northwest (Northern State of DR)" RYAN.J F Washington, Univ of Seattle, WA QUSTAVE,R P Division of Contracts FIN B-6614 NRC-04-81-177 84/03/07 1p 22/43 393
- 8403260296 Notification of contract execution, Mod 1, to "Maint & Operation of LPDRs" Contractor Salom, NJ Free Library NURPHY, L O Administrative Contracts Branch NRC-10-83-752 84/03/08 FELTON, J M Office of Administration SOUDER, J NRC No Detailed Affiliation Given 1p 22759 361
- --8403260307 Mod 1.correcting serial number for microfiche reader/printer, to "Maint & Operation of LPDRs " * Balem, NJ REDELLO, J E Division of Contracts NRC-1083-752 84/03/08 ip 22759 362
- B4U3E6O316 Notification of contract execution. Mod 2 to "Electrostatic Copying Svc " Contractor Literature Research Corp PERLEYAN.J Administrative Contracts Branch 84/03/01 HOYLE, J Office of the Secretary of the Commission KRONEBUSCH.J Public Document Branch 1p 22775 306
- --8403260322 Mod 2 adding govt furnished property at no addit cost to "Electrostatic Copying Svc " * Literaturo Research Co HAGAN.T F Division of Contracts NRC-17-82-474 B4/03/01 2pp 22775 307
- 8403240323 Notification of contract execution Nod 19, to "Technical Assistance in Bupport of NRC Reactor Licensing Actions Proquam 2" Contractor Science Applications, Inc MOLLETT, 5 Technical Assistance Contracts Branch Fin B-80il NRC-03-82-096 84/03/06 DISENHUT, D Division of Licensing BAJWA, 8 NRC No Detailed Affiliation Oiven ip 22775 302
- --8403260341 Mod 19.incorporating award fee garned for June-Nov 1983, to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2"

 # Science Applications. Inc SMITH, P Division of Contracts FIN N-8011 NRC-03-82-036 84/03/06 3pp 22775 303
- 84032A0352 Notification of contract execution, Mad 1, to "Maint & Operation of LPDRs " Contractor Washington Univ HOPPER:A Administrative Contracts Branch NRC-10-84-252 84/03/09 FELTON.J M Office of Administration SDUDER:J NRC -No Detailed Affiliation Given 1p 22775 256
- --8403260356 Mod l.changing perial number for microfiche reader/printer. to "Maint & Operation of LPDRs " * Washington Univ., Bt Louis, MG REDELLO, J E Division of Contracts NRC-10-84~252 84/03/09 ip 22775 237
- 8403240343 Notification of contract execution Mod 1, to "Maint & Operation of LPDRs" Contractor Rochester, NY Public Library HOPPER, A Administrative Contracts Branch NRC-10-83-729 84/03/08 FELTON, JM Office of Administration SQUBER, J NRC No Detailed Affiliation Given ip 22763 361
- ---8403260370 Mod I.changing serial number of microfiche reader/printer, to "Maint & Operation of LPDRs "

 * Rochester, NY REDELLO, J E Division of Contracts NRC-10-83-729 84/03/08 ip 22763 362
- B403270282 Notification of contract execution Mod 1.to "Maint & Operation of LPDRs," Contractor Shoreham-Wading River, NY Public Library HDYLE.A Administrative Contracts Branch NRC-10-83-728 84/03/07 FELTON, J M Division of Rules and Records, GQUDER, J NRC No Detailed Affiliation Given 1p 28787 261
- --B4032702B4 Med i, changing serial number on 3M 800 microfiche reader/printer, to "Maint & Operation of LPDRs " * Bhoreham, NY REDELLO, J E Division of Centracts NRC-10-83-728 84/03/07 ip R2787 262
- 8403270286 Notification of contract execution, Mod 1, to "Radiation Monitoring Program Requirements" Contractor State of ME UMBELO Technical Assistance Contracts Branch FIN 8-8357 NRC-28-83-603 84/03/07 MCOSCAR.J Office of Resource Management, Director KOTTAN, J. NRC No Detailed Affiliation Given 1p 22787 252

- ~-8403270290 Mod i.provading funds for CY84 & changing B&R number & NRC authorized representative to "Radiation Monitoring Program Requirements"
 - Requirements "

 * Maine: State of SMITH.P A Division of Contracts FIN D-DJ07 NRC-28-83-603 84/03/07 ip 22787 253
- 8403270302 Notification of contract execution.Mod 1.to "Maint & Operation of LPDRs " Contractor White Plains,NY Public
- HOVLE.A Administrative Contracts Branch NRC-10-83-730 84/03/ FELION.J M Division of Rules and Records SOUDER,J NRC No Detailed Affiliation Given 1p 22787 230
- --B403270305 Mod i changing serial number on 3M 800 microfiche reader/printer to "Maint & Operation of LPDRs" + White Plains, NY REGELLO J E Division of Contracts NRC-10-83-730 B4/03/07 ip 22787 251
- 84032/0360 Notification of contract execution, Mod 5, to "Evaluation of Mat1 Accounting Performances at Nuclear Fuel Cycle Facilities " Contractor NUSAC, Inc JACOBS: A Technical Assistance Contracts Branch FIN 8-7379 NRC-02-83-027 84/03/07 BAVIS: J Office of Nuclear Maturial Safety & Safeguards, Director MillER, M NRC No Datailed Affiliation Given ip 22787 342
- --8403270362 Mod 5, issuing change order to statement of work w/funds, to "Evaluation of Mat! Accounting Performances at Nuclear Fuel CgclF Facilities"

 LUMD.R F NUSAC, Inc GUBTAVE.R P Division of Contracts FIN B-7379 NRC-02-83-027 84/03/09 3pp 22/87 342
- 84032/0355 Notification of contract execution.Mod 14.to "Technical Assistance in Support of NRC Reactor Licensing Action Program 2 " Contractor Franklin Research Ctr WOLLETT.S Technical Assistance Contracts Branch FIN 8-6891 NRC-03-81-130 84/03/08 EISENHUT.D 8 Division of Licensing CARRINGTON.M NRC No Betailed Affiliation Given 19 22787 339
- --B4032/0369 Mod 14.incorporating award fee earned to "Technical Assistance in Support of NRC Reactor Licensing Action Program 2 "
 - Program & Tranklin Institute/Franklin Research Center SMITH.P A Division of Contracts FIN 8-6891 NRC-03-81-130 84/03/08 Ppp 22/87 340
- 8403280049 Notification of contract execution, Mod 1, to "Criteria for Evaluating Engineered Facilities" Contractor US Army Corps of ingineers or ingineers
 FLEENOKIC Technical Assistance Contracts Dranch FIN D-1001-4
 NRC-02-83-046 84/03/06 DAVIS,J Office of Nuclear Material
 Bafety & Safeguards, Director SHAFFNER,J NRC - No Datailed
 Affiliation Given ip 22812 336
- --B40J2B0052 Hod 1.authorizing commencement of Task 2 & providing incremental funds.to "Criteria for Evaluating Engineered Facilities "
 - Facilities "
 * Almy, Dept of, Corps of Engineers SMITH, P.A. Division of Contracts FIN D-1001-4 NRC-02-83-046 84/03/06 1p 82817 357
- 8403280186 Notification of contract execution, Mod 1, to "Maint & Operation of LPDRs," Contractor Sacramento, CA Public Library
 HOYIE, A Administrative Contracts Branch NRC-10-83-739 84
 FELTON, J M Division of Rules and Records Souder, J NRC Detailed Afficiation Given 1p 22808 212 84/03/07 NRC - No
- --8403280:87 Mod i changing serial number on 3M 800 microfiche reader/ printer.to "Maint & Operation of LPDRs" * Secremento, CA REBELLO, JE Division of Contracts NRC-10-83-739 84/03/07 tp 22808 213
- 8403280260 Notification of contract execution "Installation, Deinstallation & Maint Support for High Frequency, VHF & UHF Radio Equipment Owned & Operated by NRC," awarded to Tactec
- Sys. Inc.
 BAZIN.J.P. Administrative Contracts Branch NRC-10-84-239
 BAZIN.J.P. Administrative Contracts Branch NRC-10-84-239
 BAZIN.J.P. Administrative Contracts Branch NRC-10-84-239
 BAZIN.J.P. NRC-
- -8403260263 Contract "Installation Deinstallation & Maint Support for 903/20263 Contract "Installation Deinstallation & Maint Supp High Fraquency, Whf & UHF Radio Equipment Duned & Operated by NRC: awarded to Tactec Sys. Inc * Tactec Systems, Inc MATTIA.M J Division of Contracts NRC-10-84-239 84/03/09 41pp 22808 082
- 840329033B Responds to FOIA request for contract & mods resulting from RFP RS-RES-83-025. Forwards documents listed on app Documents also available in FDR FELTON-JH Division of Rules and Records 84/03/05 DAVIS, K, L Trammell, Chase, Lambert & Martindale Epp 22818 274

- --8403290343 Ltr Contract NRC-04-84-102, "Structural Integrity of LWR Boundary Components II." awarded to Matls Engineering Assor.Inc MORTUN, K V Technical Assistance Contracts Branch NRC-04-84-102 84/02/10 GREENBLATT.M Materials Engineering Associates, Inc 77pp 22818 279
- 8403300309 Notification of contract execution.Mad 2, to "Ultrasensitive Bicassay Measurements Using Sputter Initiated Resonance Ionization Spectroscopy " Contractor Atom Sciences. Inc. UNIBEL. B Tochnical Assistance Contracts Branch FIN D-1127 NRC-04-83-180 84/03/20 FOREHAND Uffice of Nuclear Regulatory Research. Director NEEL.R NRC No Detailed Affiliation Given Ip 82845-035
- --8403300312 Mod 2 changing period of performance and date to 840930, to "Ultrasensitive Bioassay Measurements Using Sputter Initiated Resonance Ionization Spectroscopy "
 SCHMITT,H H Atom Sciences, Inc SMITH.P A Administrative Contracts Branch FIN D-1127 NRC-04-83-180 84/03/20 ip 22845 036
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- B310200141 Requests that listed documents be made available based on B31004 memo ro Board Notification B3-191 on Westinghouse ECCS actuation logic POLLAND, R B Union of Concerned Scientists B3/10/18 EISENMUT, D G Division of Licensing 1p 22567 292
- 8401230630 Partial response to FOIA request for IE 800103 rept re review of matl false statement at facilities, associated & supporting records to rept & repts prepared in response. Forwards App A documents Review of edd1 records in progress FELTON. J M Division of Rules and Records 83/11/01 WINSLOW, R Hall Street Journal 2pp 21905 337 24X Fiche 50-329.83/11/01, 800133033
- --B401230660 PND-79-039 on 790305, investigation concluded that GA progrea for obtaining proper soil compaction of facility deficient excessive settlement observed widesal generator bidg & incorrect info re soil foundation contained in FSAR SHEWMAKER F E . KENDERSON J B . THORNSURG H D Office of Inspection & Enforcement. Office of the Director 79/03/06 2pp 21905 352 24X Fiche 50-329.83/11/01.8401230630
- 0402090003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A.U. & C documents
 FELTON.J M Division of Rules and Records 83/10/31.
 ROSENBAUM.D M Technical Analysis Corp 19pp 22193 292 24X
 Fiche 50~000.83/10/31.8402090003
- --B402090183 Handwritten notes & calculations re const activities & fuel | NRC - No Detailed Affiliation Given 79/07/24 | 22/95 057 | 24% Fiche | 50-000,83/10/31,8402070003
- --B402090186 Handwritten calculations & graphs re const activities & preoperational & acceptance testing Related info encl.
 * NRC No Detailed Affiliation Given Bi/09716 App 22196 191 24x Fiche 50-000,83/10/31.8402090003
- 8402:40014 FOIA request for records to NRC const assessment team (CAT) insp at facilities BERNADF1,L Government Accountability Project 83/10/07 Of of Administration 2pp 22254 001 24X Fithe 50-528,83/10/07,
- 8402140018 Responds to FOIA request for records re NRC const assessment team (CAT) insp at facilities Forwards App A documents
 Documents also in PDR App B documents listed for review to identify specific interest
 FELTON.J M Division of Rules and Records 83/12/20 GARDE.B P
 Government Accountability Project 18pp 22254 003 24X
 Fiche 50-528.83/12/20.8402140018
- --8402140022 Summarizes civil insp items Bechtel 830929 itr re reinsp of nuclear pipe hangers (Q class) & related info encl VORDERBRUGGEN Region 5. Diffice of Director 83/09/19. NARBUT,P NRC No Detailed Affiliation Given. 60pp 22954,021 24X Fiche 50-528,83/12/20,8402140018
- --8402140026 "Insp Plan " Draft autline given to inspectors on 830906 encl, * NRC - No Detailed Affiliation Given 83/12/20 12pp 22254 081 24X Fiche 50-528,83/12/20,8402140018

- --B40214002B Provides add1 info re 830730 exit interview meeting w/const assessment team for preliminary review of findings NRC criteria utilized during insp more applicable to operating plant Related info encl WODDS.T O Arizona Public Service Co 83/10/12 MARTIN.J B Regison 5. Office of Director 337pp 22254 320 24X Fiche 50-528,83/12/20,8402140018
- ---B402140031 Comments on review of draft writeup on NDE Rewrite requested Related info encl NARDUT.P NRC - No Detailed Affiliation Given 83/09/27 KERCH.H NRC - No Detailed Affiliation Given 41pp 22234 094 24X Fiche 50-526.63/12/20,8402140018
- ---B402140032 Summary of B30916 erit status meeting w/NRC const appraisal team re B30907-16 insp
 IDE:W E Arizona Public Bervice Co B3-C-B3/WEI B3/09/19
 ROEDEL, J A Arizona Public Service Co 4pp 22254 k37 24X
 Fiche 50-528
- --8402140036 Forwards marked-up draft insp scope & objectives Related info encl ALDERT, W G Region 5, Office of Director 83/09/21 YOUNG, 1 Region 5, Office of Director 18pp 22834 143 24X Fiche 50-528,83/12/20,8402140019
- ---B402140037 Corrective action request re piping cleanliness.per Procedure WPP/QCI 204 O.Rev 2. "Piping Bys Release for Insulation " Related info enc! GAITHER.C F Artiona Public Service Co 83/09/13 25pp 22255:279 24X Fiche 50-528.83/12/20.8402140018
- ---840214003B Forwards feeder rept re insp activities at facility Combined insp of concrets expansion anchor boits & embedded plates will be written by L Vorderbrueggen Radiographs reviowed will be included in H Kerch rept.Related info enci WALTON.0 A Region 1, Defice of Director 83/10/07 YOUNG, T Region 5, Defice of Director 155pp 22294 165 24X Fiche 50-528,83/12/20,8402140018
- ---8402140043 Provides fiat of NDE repts available from inap activities completed w/NRC mobile NDE van at facility.per FOIA request Related info encl EBNETER.8 D Region 1. Office of Director. 83/11/15 ALEXANDER.1 M Region 5. Office of Director 97pp 22255 324 24X Fiche 50-528.83/12/20,8402140018
- --8402140052 Provides resolution for loose bolts on structural steel found during NRC const assessment team (CAT) insp Item conseldered ciosed Related info encl FORRESTER.R D Arizona Public Service Co 83-C-87/RDF 83/09/26 1DE, M E Arizona Public Service Co 3pp 22256 221. 24X Fiche 50-528,83/12/20.8402140018
- --8402140022 Summarizes civii insp items Bechtel 830929 ltr re reinsp of nuclear pipe hangors (G class) & related info encl VORDERBRUEGGEN Region 5, Defice of Director 83/09/19 NARBUT,P NRC - No Detailed Affiliation Given 60pp 22254 021 24X Fithe 50-528,83/12/20,8402140018
- ---84021400R4 "Insp Plan" Draft outline given to inspectors on 830906 encl # NRC - No Detailed Affiliation Given 83/12/20 12pp 22254 OB1 24X Fiche 50-528.83/12/20.8402140018
- --8402140028 Provides add1 info re 830930 exit interview meeting w/const assessment team, for preliminary review of findings NRC criteria utilized during insp more applicable to operating plant. Related info enc! WODDS, T O Arizona Public service Co 83/10/12 MARTIN. J B. Region 5. 0 Effice of Director 339pp. 22254 320 24X Ficho. 50-528, 83/12/20. 8402140018
- ---8402140032 Summary of 830916 exit status meeting w/NRC const appraisal team re 830907-16 insp IDE,W E Arizona Public Service Co 83-C-83/WEI 83/09/19 RGEDEL,J A. Arizona Public Service Co 6pp 22254 137 24X Fiche 50-528,63/12/20,8402140018

- ---8402140036 Forwards marked-up draft insp scope & objectives Related info encl ALBERT, H G Region 5. Office of Director 83/09/21 YOUNG, T Region 5. Office of Director 18pp 22254 143 24X Fiche 50-528,83/12/20.8402140018
- --8402140037 Corrective action request re piping cleanliness.per Procedure WPP/GCI 204 O.Rev 2. "Piping Sys Release for Insulation" Related info encl OAITHER, CF Arizona Public Service Co 83/09/13 25pp 22255 299 24X Fiche 50-528,83/12/20,8402140018
- --8402140038 Forwards feeder rept re insp activities at Parility Combined insp of concrete expansion anchor bults & embedded plates will be written by L Vorderbrueggen Radiographs reviewed will be included in H Kerch rept Related info encl
 WALTON.O A Rogion i. Office of Director 83/10/07 YOUNG.T
 Region 5. Office of Director 83/10/07 YOUNG.T
 Fiche 50-528,83/12/20.8402140018
- --B402140043 Provides list of NDE repts available from insplactivities completed w/NRC mobile NDE van at facility, per FDIA request Related info encl
 ENNETER.S D. Region i. Office of Director 83/11/15
 ALEXANDER.i M. Region 5. Office of Director 99pp 22255 324
 24% Fiche 50-528,83/12/20,8402140018
- --B402140048 Rev 0 to "Palo Verde Station HPSI Bys Eiectrical & Instrumentation Const Audit Insp." final rept Related info encl.

 * Zytor, Inc NRC-IE-82/83-46C HSB PAR0003 83/10/04 158pp 22256 063 24X Fiche.50-528,83/12/20,8402140018
- --8402140052 Prevides resolution for loose bolts on structural steel found during NRC const assessment team (CAT) insp Item considered closed Related info encl FURRESTER.R D. Arizona Public Service Co 83-C-87/RDF 83/09/26 IDE,W C Arizona Public Service Co 3pp 22256 221 24% Fiche, 50-528, 83/12/20, 8402140018
- 8402230207 Further response to FDIA request for documents re const flows of facility Forwards documents listed in App A Documents also being placed in PDR & LPDR Review continuing FELTON. J M Division of Rules and Records 83/12/02 VADEN, T Rews & Observer/Raleigh Times, Raleigh. NC Jpp 22378 299 24X Fiche 50-400.83/12/02.8402230207
- --8104210325 Discusses implications of Ofc of Inspector & Auditor 781012 interview w/facility ASLB Ofc of Inspector & Auditor attempted to probe thought processes of & require justification from Board re action taken in adjudication YORE. J R Atomic Safety and Licensing Doard Panel. 78/10/19 HENDRIE. J R Commissioners 3pp 22378 UOR 24X Fiche 50-400,83/12/02.8402230207
- --8402230226 Forwards Oft of Inspector & Auditor "Inquiry into Alieged Omistion of Line Inspector Views from CP Hearing " No further distribution should be made outside of oft Rept under Commission review.

 OGSSICK,L V Office of the Executive Director for Operations 78/11/13 DENTON Office of Nuclear Reactor Regulation. Director SHAPAR Office of the Executive Legal Director DAVIS Office of Inspection & Enforcement, Office of the Director ip 22378 305 24X Fichs 50-400,83/12/0R,8402230207
- --B402230237 Discusses investigation by Ofc of Inspector & Auditor (OIA) re facility proceeding ASLAB unwilling to be interrogated by OIA Many questions in OIA interrogation of members of ASLU manifestly improper ROSENTHAL A S Atomic Bafety and Licensing Appeal Panei 76/10/20 HENDRIE Commissioners 2pp 22978 306 24X Fiche 50-400,83/12/02.8402230207
- --8402230239 Forwards Apps A.B.C & D to be included w/questions for Panel III re facility testimony Related info enc!
 MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 78/11/16 REIB.E J Office of the Executive Legal Director Sipp 22378 308 24x Fiche 50-400.83/12/02, 8402230207
- --840223024R Requests that interim guidance re proparation of staff testimony in NRC adjudicatory proceedings be transmitted to all personnol invoived. Ofc directors should carefully review existing procedures for NRC testimony Related info encl GOSBICKLL V. Office of the Executive Director for Operations 79/03/30 NRC No Detailed Affiliation Given 5pp 22077 02/
- --8402230246 Ack 820510 conversation re allegations by facility employee D Jarvis, per Regional Ofc Instruction 2251. Rev 2. Paragraph 2 C (3) Case file encl MAXNELL, 0. Region 2. Office of Director 82/05/10 VORSE, J NRC No Detailed Affiliation Given 2pp 22377 032 24X Fiche: 50-400, 83/12/02, 8402230207

- -8402230248 Requests that Region II civil insp personne) investigate allegations by unidentified individual re coatings during next routine insp at site Case chronology encl MAXWILL, GF Region 2. Office of Director 82/07/07 VORSE, J. NKC No Detailed Affiliation Given 2pp 22379 034 24X Ficho 50-400,83/12/02,8402230207
- -8402230251 Math maint requirements for Procedure AP-XIII-07.
 "In-Storage Insp & Maint " Equipment purchase order form enc!
 * Carolina Power & Light Co 83/12/02 9pp 22379 040 24X
 Fiche 30-400,83/12/02,8402230207
- 402270263 Responds to FOIA request for JC Hark 801204 memo to ACRS re hydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards app A documents in FOR FELION J M Division of Rules and Records 84/01/30 HIATF, S L Ohio Citizens for Responsible Energy 7pp 22412 051 24X Fishe 50-000:84/01/30,8402270263
- -84022/0314 Forwards summary of investigations re hydrogen recombiners & rclay follows in HPCI bys ZUKCK, b J ACRS Advisory Committee on Reactor Safeguards 80/10/30 MDELLER, b W ACRS Advisory Committee on Reactor Safeguards 4pp 22412 084 24% Fiche 50-000,84/01/30.
- 403010010 FOIA request for documents to TMI-1 Restart Issues Task Force to be placed in PDR SMOLLY:9 C Union of Concerned Scientists B3/12/12 FELTON.J M Division of Rules and Records ip 22446 036 24X Fiche 50-289.B3/12/12.B403010010
- 403010013 Further response to FDIA request for documents re PRA & evocuotion time estimates Forwards "Review & Evaluation of GISSAR-II FRA-Containment Failure Modes & Fission Product Release " Rept partially withheld (ref FDIA Exemption 4) FCLION. J M Davision of Rules and Records 84/01/03 HIATT. S Ohio Citizens for Responsible Energy 4pp 22445 276 24X Fische 50-447.84/01/03.8403010013
- -8308170191 "Review & Evaluation of GESSAR-II Probabilistic Risk Assersment - Containment Failure Modes & Fission Product Release." Itr rept # Dipokhaven National Laboratory 83/07/27 Division of Systims Integration (post 811005) 180pp 66922 170 24X Fiche 50-447.84/01/03.8403010013
- 403010014 Partial response to FOIA request for documents to TMI-1
 Restart Issues Task Force Forwards documents listed on app
 Info also available in PDR
 IEL10N.J M Division of Rules and Records 84/01/03 SHOLLY.8 C
 Union of Concerned Scientists 2pp 22446 057 24X
 Fiche 50-287.84/01/03.8403010014
- --8305110034 Informs that reevaluation of Cycle 5 reload application, has identified two issues re nonconservative cladding swc)ling & rupture models & IAFY/TACO penalty proposed by IRLY that shout be resolved prior to restart.
 RMSH-NSTEIN.L S Assistant Director for Core & Plant Systems TAC 513/9 63/05/02 LAINAS.G C Assistant Director for Operating Reactors 3pp 22446 212 24X Flohe 50-289,84/01/03.8403010014
- --G403010020 Assigns recipients to TMI-1 Restart Issues Task Force to verify that NRC requirements for restart correctly identified & facility treated similar to all operating plants for other NRC requirements
 EISENHUT, D.G. Division of Licensing STARDSTECKI, R. Division of Project & Resident Programs B3/04/15 JACOUS, Region 1.
 Office of Director VAN VLIET, J. DIIANNI, D. Division of Licensing ip 22445 059 24X Fiche 50-289, 84/01/03, 8403010014
- --8403010023 Responds to B30415 memo & Perwards "Rept of TMI-1 Restart Issues Task Force Members " Heeting requested to respond to questions WILLIAMS.M H IMI-1 Restart Issues Task Force 83/04/29 EISENHUT.D & Division of Licensing STARGSTECKI.R Division of Project & Resident Programs 1p 22446 060 24% Firlie 50-289.84/01/03.8403010014
- --8403010030 "Rept of TMI-1 Restart Issues Task Force Members "
 WILLIAMS M , VAN VLIET, J , YOUNG, F IMI-1 Restart Issues Task
 Force 83/04/29 150pp 22446 061 24X Fiche 50-289,84/01/03,
 8403010314
- --8403010036 List of generic ltrs from 1978-1983 Related in po encl # NRC - No Detailed Affiliation Given 84/01/03 27pp 22446. 247 24X Flohe 50-289,84/01/03,8403010014

- --8403010043 Forwards input to 830429 TMI-1 Restart Issues Task Force rept Info derived from ASLB partial initial decisions in restart proceedings Related info encl GOLDBERG, J R Office of the Executive Legal Director 84/01/03 HILLIAMS, M Division of ticensing 19pp 22446 274 24X Fich
- 8403010016 Further response to FOIA request for 16 categories of documents Forwards HJ Dircks 811217 ltr re 810606 sebatage event & special rept to Commonwealth of PA Info partially withheld (ref FOIA Exemption 3) FELTON.J M Division of Rules and Records 84/01/04 SHOLLY, 8 C Union of Concerned Scientists 2pp 22479 076 24X Fiche 50-334.84/01/04.8403010016
- --8403010032 Responds to 811021 % 1104 requests for Info re 810606 Sabbtage event at facility Details withheld (1ef 10CFR73 21)
 DIRCKS.W J Office of the Executive Director for Operations 81/12/19 TAYLOR, FR Pennsylvania, Commonwealth of, 2pp 22479 080 24X Fiche 50-334,64/01/04.8403010016
- --8403010061 "Response to Apparent Act of Sabotage at Beaver Valley, Unit i " Info partially deleted (ref 10CFR2 790(d) & 10CFR73 21)

 * NRC No Detailed Affiliation Given 84/01/04 App 22479 112 24X Fiche 50-334, 84/01/04. 8403010016
- B403010018 F01A request for 1982 NUREG/CR-2815, "NRC.Natl Reliability Evaluation Program (NREP) Procedures Guide " BETCHFR.J L Northern States Power Co 83/12/15 BELTON.J Office of Administration 1p 22477 001
- 8403010021 FOIA request for documents to petition for rulemaking PRM-50-31 from Citizens Task Force of Chapel Hill, NC SHOLLY, S C Union of Concerned Scientists B3/10/31 FELTON, J M Division of Rules and Records 1p 22446 034
- 8403010074 Responds to FOIA request for documents re petition for rulemaking PRM-50-31 from Citizens Task Force of Chapel Hill.NC Forwards App A documents App B documents completely withheld (ref FOIA Examption 5) FELTON, J M Division of Rules and Records 84/01/18 SHOLLY, S C Union of Concerned Scientists 4pp 22446 035
- --B301060420 Requests review & comments re encl draft FR notice to deny Cltizens Task Force of Chapel Hill.NC petition for rulemaking (PRM-50-31) W/o encl NORBERG.J Human Factors & Safeguards Granch 82/12/27 BASSITT.O E Division of Accident Evaluation (Pre 840101) 2pp
- --8305040013 Informs that reply to petition for rulemaking PRM-50-31, filed 811202 will be delayed until May 1984 since NRC is reevaluating severe accident radiation source terms & technical basis for 10-mile emergency planning rone radius PHILLES, J D Division of Rules and Records 83/04/13 KATB, C H Citizens' Task Force 1p 22446 039
- --8403010038 Requests documents re petition for rulemaking PRM-50-31 filed by Citizens Task Force & R Bernero 830916 memo to NRC div directors re draft rulemaking on emergency preparedness MARKEYLE J House of Rep., Interior & Insular Affairs, 83/09/22 FALLADING, N. J. Commissioners 1p. 22446-040
- --8403010046 Forwards predecisional documents re emergency preparedness per request Documents do not represent NRC proposed or actual policy Package should be restricted to subcommittee members & staff only W/o encl KAMMERER, C Office of Congressional Affairs 83/10/28 OTTINGER, R L House of Rep . Energy & Commerce 1p 22446 043
- --8403010049 Forwards predecisional documents re emergency preparedness per request Documents do not represent NRC proposed or actual policy, Package should be restricted to subcommitter members & staff only W/o spcl KAMMLRER.C Office of Congressional Affairs 83/10/28, SIMPSON.A Senate, Environment & Public Works 1p 22446 044
- --D403010054 Forwards predscisional documents re emergency preparedness per request Documents do not represent NRC proposed or actual policy. Package should be restricted to subcommittee members & staff only M/o encl KAMMCRER.C Office of Congressional Affairs. 83/10/28 UDALL, M House of Rep , Interior & Insular Affairs. 1p 22446.045.
- --8403010058 Forwards predecisional documents re emergency preparedness per request Documents do not represent NRC proposed or actual policy Package should be restricted to subcommittee members & staff only W/o encl
 KAMMICRER.C Office of Congressional Affairs 83/10/28 DEVILL.T
 House of Rep., Appropriations 1p 22446-046

- --B403010063 Forwards predecisional documents re emergency preparedness per request Documents do not represent NRC proposed or actual policy Package should be restricted to subcommittee members & staff only H/o encl KAMMIRER.C Office of Congressional Affairs 83/01/28 HATFIELD.M O Benate, Appropriations 1p 22446 047
- --8403010067 Forwards predecisional documents re emergency preparedness per request Documents do not respresent NRC proposed or actual policy Package should be restricted to subcommittee members & staff only W/o encl
 KAMMERER.C Office of Congressional Affairs 83/10/28
 DINGELL.J House of Rep , Energy & Commerce 1p 22446 048
- --B403010074 Forwards review comments on draft RES denial of petition for rulemaking on emprgency planning zone at suclear power plants, per request General comments encl HULMAN, L G Accident Evaluation Branch B3/01/07 COTA, P C Research & Standards Coordination Branch 7pp 22446 049
- B403010026 Responds to FDIA request for 1982 NUREO/CR-2815, "NRC, Natl Reliability Evaluation Program (NREP) Procedures Quide " Forwards NUREO FELTON, J M Division of Rules and Records 84/01/04 DETCHER, J L Northern States Power Co ip 22477 002
- ---8403010041 NUREQ/CR-2815 DRFT
 Draft PROBABILIBITC SAFETY ANALYSIB PROCEDURES OUIDE
 BARI,R A. BUSLIK,A. J. Brookhavan National Laboratory
 EL-BABBIONI,A. Office of Nuclear Reactor Regulation, Director
 FIN A-3382 BNL-NUREO-51559, 83/09/01 NRC No Datailed
 Affiliation Given 231pp 22477 003
- 8403010050 Third partial response to FDIA request for six categories of documents re facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in PDR upon request Review continuing FELTON, J M Division of Rules and Records 84/01/17 ANDERSON. 8 I Garvey, Schubert. Adams & Barer 4pp 22444 293 24X Fiche 50-000,84/01/17,8403010050
- ---B003240159 Advises of refund omed licensee re CP fees for facilities based on professional manpower extended & contractual sycs costs incurred.

 MILLER, W O License Fee Management Branch B0/03/03 MANION, W E Office of the Controller 2pp 22446 303 24X
 Fiche 30-000, B4/01/17, B403010050
- --B004010752 Confirms B00229 telcon re professional manpower (152-h) provided by B00228 mean Manpower should be divided equally between two units HOLLOWAY, C. J. License Fee Management Branch B0/02/29 F1711.C J. Atomic Bafety and Licensing Board Panel 1p 22446 300 24X Fichs 30-000.84/01/17.8403010050
- ---BOO4010759 Confirms BOO226 telcon re professional manpower (18-h) provided by A Rosenthal 781002 mems Manpower should be divided equally between two units MULLUMAY.C J License Fee Management Branch 80/02/29 BISHOP, J Atomic Safety and Licensing Appeal Panel ip 22446 301 24% Fiche 50-000,84/01/17,8403010050
- --8112020204 Forwards new format for nuclear power plants const status rept, NUREO-0030 (yellow book) New format should be used to provide next update info for planned Noy 1981 publication (data as of 8ept 30.1981) due 811120 W/o encl HARTFIELD.R A Office of Management and Program Analysis 81/10/30 DUNN,C N, Duquesne Light Co 9pp 22446,305 24X Fiche 50-000,84/01/17,8403010050
- --0112210135 Informs of B McKinney opinion that allocation of ACRS manpower for fee purposes should be divided equally for reviou of two units at site HOLLOHAY; C. J. License Fee Management Branch 79/01/22 License Fee Management Branch 1p 22446 297 24X Fiche 50-000,84/01/17,8403010050
- --B302250083 Responds to questions re application termination Notice of termination/withdrawal not anticipated No time limitation pleced on completion of Phase One review ADENBAME Q Licensing Branch 4 B3/02/17 MILLER, W D License Fee Management Branch ip 22446 321 24X Fiche 50-000,84/01/17, B403010050

- --8304060552 Requests search for relevant documents re govt litigation w/util Response due by 830408 GRIMSLEY, D H NRC No Detailed Affiliation Given 83/03/29 FITT). C Atomic Safety and Licensing Board Panel lp 22446 3i4 24% Fiche 50-000,84/01/17,8403010050
- --B305070506 Requests advice re fee assessment cutoff date for reactor CP & OL applications that are withdrawn denied suspended, concelled or postponed MILLERW O License Fee Management Branch 83/05/04 FONNER, R L Office of the Executive Legal Director 3pp 22946 315 24X Fish: 50-000, 84/01/17, 8403010050
- --83081004B3 Discusses status of OL applications Review of encl MPPS8 830712 Itr requested in order to determine present status of Unit 3 for billing purposes W/o encl MILLER.W O License Fee Management Branch 83/08/05 FONNER.R L Regulations Division 2pp 22446 326 24X Fiche 30-000. 84/01/17.8403010050
- 8403010068 Add1 response to FD1A request for two categories of documents re 1DCDR program Forwards document Documents also available in PDR FELTON, J M Division of Rules and Records 84/01/03 SHOLLY, S C Union of Concerned Scientists 1P 22449 307
- --B403010074 Forwards core debris dispersal & vessel failure issue summary, developed at 1DCOR B31129-1202 meetings in Harpers Ferry Steps taken to fulfill agreement of close cooperation among interested party in test data analyses POMERS.D A Sandia Laboratories 83/12/05 ROSENTHAL, J Office of Nuclear Reactor Regulation, Director 3pp 22449 308
- 8403010085 FOIA request for ORNL draft or final rept on severe accident precursors at US nuclear plants during 1980 & 1981 H1AT7.9 L Dhio Citizens for Responsible Energy 83/12/10 FFL1ON.J M Division of Rules and Records 1p 22477 234
- BA03010092 Final response to FOIA request for comparative evaluation of nuclear facilities compliance w/NUREO-0578 & NUREG-0737 requirements Forwards App A documents App B document entirely withhold (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records B4/02/09 WEISB, E R Union of Concerned Scientists App 22446 190
- --8403010097 R-1206671-001 "TN1 Action Plan," computerized list * NRC - No Detailed Affiliation Given 34/02/09 146pp 22448 227
- 8403010074 Responds to FOIA request for ORNL rept. "Precursors to Potential Severe Core Damage Accidents 1980-1981 Status Rept." Forwards draft rept FELION.J M Division of Rules and Records 84/01/03 HIATE.S Ohio Citizens for Responsible Energy 1p 22477 235
- --8403010102 Draft "Precursors to Potential Severe Core Damage Accidents 1980-1981 Status Rept," Vols 1 & 2 main rept & App A & B COTTRELL,W B , MAGEN.E W , MARRIS, J D Oak Ridge National Laboratory FIN B-0435 DRNL/NBIC-217 83/07/31 Office of Nuclear Regulatory Research, Director 560pp 22477 235
- B403010100 Further response to FDIA request for eight categories of records re CL amends Forwards listed documents Documents also avaitable in FDR Bearch for addl documents subj to request in progress FELTON.J M Division of Rules and Records 83/12/22 BELL.N Nuclear Information to Resource Service 3pp 22445 087
- --8311230247 Discusses Public Law 97-415 which amended Atomic Energy Act of 1934 Section 189 to authorize NRC to issue & make immediately effective amends to OL w/NSMC W/o encl DENTON.H R Office of Nuclear Reactor Regulation, Director 83/10/31 SIMPSON,A Senate 1p 22445 090
- ---8403010104 Forwards fifth monthly FR notice re OL amends, per Public Law 97-415 W/o encl DENTON, H R Office of Nuclear Reactor Regulation, Director 83/07/30 9TAFFORD.R T Senate, Environment & Public Works 1p 22445 089.
- --8403010108 Forwards FR notice of UL amends, per Public Law 97-415 W/o encl DENTUN,H R Office of Nuclear Reactor Regulation, Director 83/12/06 SIMPSON,A, Senate, Environment & Public Works Ip 22445 091

- G403010111 FDIA request for documents by mamed individuals, including repts, analyses, studies, procedures & sys for measurement of RCS leakage
 MADDEN, T J Kaye, Scholer, Flerman, Hays & Handler 83/12/27
 NORRY, P G Office of Administration 2pp 22480 024
 - NORRY.P G Office of Administration 2pp 22480 024
- 8403010113 Final response to FDIA request for five categories of info re mothballed nuclear const projects Forwards App A documents Documents aiso in PDR FELTON.J M Division of Rules and Records 84/02/10 BELL.N Nuclear information & Resource Service 2pp 22479 182 24X Fiche 50-508.84/02/10.8403010113
- --B403010114 Partial statement of JB Martin before House Committee on Energy & Commerce re mothballing of facility MARTIN.J B NRC - No Detailed Affiliation Given B3/09/14 9pp 22479 186 24X Fiche 50-508,84/02/10,8403010113
- B403010117 Partial response to FOIA request for documents by named individuals re repts.analyses, studies, procedures & sys for measurement of RCB leakage App B documents placed in PDR App A documents already available in PDR Search continuing FELION, J M Division of Rules and Records 84/01/25 MADDEN, T J Kaye, Scholer, Flerman, Hays & Handler 7pp 22480 026 247 Fiche 50-000,84/01/25,8403010117
- --GD11070322 Summarizes results of independent evaluations of primary sys leak rate & some considered extensions Extension of specific evaluations to all PMR facilities recommended Draft procedure re evaluations will be submitted by 600915 JORDAN.E L. Division of Reactor Operations Inspections 80/08/21 MOSPLEY,N C. Division of Reactor Operations Inspections 11pp 22480 266 24X Fiche 50-000,84/01/25,8403010117
- --BIO3250553 Forwards draft Procedures 617278, "Preparation for independent Measurement of RCS Leak Rates for PWR" & 617289, "Independent Measurement of RCS Leak Rate for PWR" & 617289, "Independent Measurement of RCS Leak Rate for PWR" Manual Chopters 2514 & 2515 will be revised to add procedures SNIE/EK, J H Division of Resident & Regional Reactor Inspection BI/01/22 GRIER, B H Region 1. Philadelphia. Defice of the Director D'REILLY, J P Region 2. Atlanta. Defice of the Director KEPPLER, J G Region 3. Chicago. Office of the Director 22pp 22400 345
- --B103250630 Requests that encl Procedures 617278 & 617280 be Issued for trial JUKUAN,E L. Director's Diffice B1/01/22 BRYAN,S E Program Development Branch 17pp 22480 328
- --Bi07160213 Forwards description of RCSLK 7 for reactor coolent leakage calculation, magnetic cards & quad memory module W/o magnetic cards & quad memory WHODINTOF,R W Mechanica). Structural & Metallurgical Section 81/06/23 CHLNG, J Test Program Section CRLENVAK, J Reactor Projects Section IA FIELDER, R Test Program Section 2pp 22401 013
- ---B107160215 "RCSLK 7"
 KIKKPATRICK,D Director's Office Office of Inspection and
 Cnforcement WODDRUFF,R W Mechanical Structural & Metallurgical
 Section B1/05/07 5pp 224B1 005
- --8109180036 Requests two remote computer terminals to be used in developing programs for calculational support for complex insp.
 SNIEZEK, J H Division of Resident & Regional Reactor Inspection 81/09/08 TROUTMAN, C R Office of Management and Program Analysis 2pp 22481 345
- --B202120295 Submits progress rept on development of computerized insp techniques, including development of RCSLKB program for ECLIPEE computer Recommends purchase of add1 TX Instruments 700 portable torminal for regional ofcs Program enci KIRKPATRICK.D., WOODRUFF,R W Reactor Engineering Branch 81/11/17 DROMERICK,A W Reactor Engineering Branch 14pp 22481 348
- --B203120197 Forwards RCB B20121 leak rate calculation program for Hewlett Packard 41C (RCSLK 7) consisting of plant-specific data & sample calculations Data for remaining plants requested BATRIR L Division of Engineering & Quality Assurance (Pre B30103) 82/02/16 MARTIN.T T Region 1. Office of Director CLSHINSKI.J A Region 2. Office of Director NORELUIS, C E Region 3. Office of Director 16pp 22481 132
- --B309150400 Comments on 930629 schedule for initial independent measurements of RCS leak rates by Region V using RCSLKB Estimate of time required to gather verify & program plant-specific data acceptable WODRUFF, R W Engineering & Generic Communications Branch B3/07/12 MCKEE, P E Division of GA, Bafeguards & Inspection Programs (Post B30103) 1p 22482 019

- --8309150401 Submits scope & schedule for independent measurements of RCS leak rates of operating plants in Region V Evaluations not expected to begin until Sopt or Oct 1983 MORRILL, P Region 5. Diffice of Director 83/06/29 BISHOP, T Region 5. Office of Director 10pp 22481 242
- --B3111504B1 Forwards results of review of RC9 leak rate test procedures & calculational methods used in 1978 at two rendomly selected BMR plants.per 830920 request Deficiencies discovered during trial use period corrected DLYQUNO,R C Director's Dffice, Office of Inspection and Enforcement 83/11/07 DIRCKS, W J Office of the Executive Director for Operations 22pp 224B2 020 24x Fiche 50-000,84/01/25,8403010117
- --9403010127 "RCSLK8 "
 KIRKPATRICK,D., WOODRUFF,R W NRC No Detailed Affiliation Given 81/10/30 32pp 22481 021
- --84030i0129 Table of "Pressurizer Design Data " Related info encl * Alabama Power Co 84/01/25 46pp 22480 033 24X Fiche 50-000,84/01/25,8403010117
- --8403010131 "RCSLKB"

 KIRKPATRICK, D , WODDRUFF, R W NRC ~ No Detailed Application Given 81/11/03 13pp 22481 044
- --8403010137 Rev 2 to Surveiliance Test Procedure FNP-i-8TP-9 0, "RCS Leakage Test " Related Info encl PODLE: D L Alabama Power Co 79/03/25 22pp 22480 079 24X Firhe 50-000,84/01/29,8403010117
- --8403010138 "RCSLK8" Related Info enc1 KIRKPATRICK,D. WOODRUFF,R W NRC - No Detailed Affiliation Given 81/11/17 74pp 22481 057
- --B403010141 Rev 2 to Instrument Maint Procedure FNP-1-1MP-202 8, "Vol Control Tank Level LT-112" Related Info encl MCGRACKEN.K W Alabama Power Co 78/03/07 24pp 22480 101 24X Fichs 50:000, B4/01/25, 8403010117
- --8403010144 Rev 2 to Instrument Maint Procedure FNP-1-1MP-201 22, "Pressurizer Level Control.LC-439F" * Alabama Power Co 78/06/17 30pp 22480 125 24X Fiche 30-000,84/01/25,8403010117
- --8403010151 Responds to 820303 request for application of RCS loak rato program. RCSLK7, to Ban Onofre 2 RCSLK7, as written, applies to listed conditions Directions given to prepare Hewlett Packord to run modified program Mark-up of RCSLK7 encl MODRUFF, R Engineering & Technical Bupport Branch 82/05/05 MORRILL.P Region 5, Office of Director 17pp 22481 148
- 8403010152 Rev 1 to Instrument Maint Procedure FNP-1-IHP-202 9, "Vol Control Tank Level 17-115"
 THCMAS, J Alabama Power Co 78/08/02 22pp 22480 156 24X
 Fiche 50-000, 84/01/25, 8403010117
- --8403010156 Rev 2 to Instrument Maint Procedure FNP-1-IMP-201 28,
 "Pressurtier Relief Tank Level LT-470 "
 THOMAS, J Alabama Power Co 78/08/02 24pp 22480 178 24x
 Fiche 50-000, 84/01/25, 8403010117
- --8403010159 Discusses independent measurement of RCS loak rates for PMRs New version of program RCSLKB developed for use w/ portable computer Seminar tentatively scheduled for Feb 1963
 JORDAN, E.L. Division of Engineering & Guality Assurance (Pre 830103) 82/10/05 HAYNES, R.C. Region 1, Office of Director O'REILLY, J.P. Region 2, Office of Director KEPPLER, J.G. Region 3, Office of Director 2pp 22481 165
- --8403010161 "RCSLK8"

 KIRKPATRICK,D , WOODRUFF,R W NRC No Detailed Affiliation Given 62/11/26 12pp 22481 14/
- --B403010163 Rev 1 to Instrument Maint Procedure FNP-1-IMP-224 2,
 "Reactor Coolant Drain Tank Level, LT-1003 " Related info
 enci
 SHIPMAN, W B Alabama Power Co 80/01/25 62pp 22480 204 24x
 Fiche 50-000, 84/01/25, 8403010117
- --84030i0164 Discusses status of implementation of RCSLKB.
 WDDDRUFF.R NRC No Detailed Affiliation Given 82/12/01
 CUNNINGHAM, J NRC No Detailed Affiliation Given 3pp

- --8403010175 Rev 6 to Procedure PDT-1-3, "Persodic Operating Test RCS Leakage Evaluation " LAMOUREAUX.T H Portiand General Electric Co 78/06/19 Ypp 22481 184 24X Fiche 50-000.84/01/25.8403010117
- --B40301017B "RCSLKB RCS Leakrate Determination for PWRs," Users Guide KIRKPATRICK,D., WOODRUFF,R W NRC - No Detailed Affiliation Given 63/02/i5 43pp 22481 193
- --B4030i01B1 Informs that new version of computer program, RCSLKB, incorporates improvements suggested by regional ofcs & by IE Evaluation of Osborne completed Osborne 1 computer & Itoh printer ordered for each regional ofc JORDAN.E L Division of Emergoncy Proparedness & Engineering Response (Post 830103) 83/03/04 HAYNES, R C Region i, Office of Director O'REILLY, J P Region 2, Office of Director & Region 3, Office of Director 2pp 22481 234
- --84030i0184 Discusses how IE could develop capability to periodically & independently calculate identified & unidentified reactor coolant leak rates in operating water reactors by using portable calculators Description of existing program encl KIRKPATRICK, D., WOODRUFF, R NRC No Detailed Affiliation Given 80/05/29 JORDÁN, E NRC No Detailed Affiliation Given 11pp 22480 277
- --8403010185 Notifies of 830413-14 seminar in Bethesda, MD for regional ofcs on use of RCSLKG, improved computer program for determining leak rates of PMR cooling sys
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/01 HAYNES, R C Region 1, Office of Director O'REILLY, J P Region 2, Office of Director KEPPLER, J Q Region 3, Office of Director 2pp 22481 236
- ---84030i0191 Discusses how IE could develop capability to periodically & independently calculate identified & unidentified reactor coolant leak rates in operating water reactors using portable calculators Description of existing program enci KIRKPATRICK, D. NRC No Detailed Affiliation Oliven 80/06/03 JGROAN, E. Division of Reactor Operations Inspections 2ipp 22480 288
- --8403010193 Informs that portable computers obtained for regional ofcs for use in independent measurement of leak rates from PMR cooling sys Draft module & user guide (NUREG-0986) encl M/o encls
 UDRUAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 TAYLOR,J M Division of GA, Gafeguards & Inspection Programs (Post 830103) 4pp 22481 238
- --B403010196 Requests authorization to conduct leak rate test at selected C-E & Westinghouse facilities. Test needed to evaluate R Woodruff & D Kirkpatrick program to independently assess leak rates W/o enci
 JORDAN.E L Division of Reactor Operations Inspections B0/06/03
 BRUNNER.E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 1p. 22480 309
- --84030i0201 IE Change Notice 8i-05, revising listed manual chapters Related info enci * Director's Office, Office of Inspection and Enforcement 81/03/11 86pp 22481 252
- 8403010205 Forwards TANK program description & program cards Program calculates & plots voi of liquid in program for RCS leak rate Requests J Chung to be coauthor of program description WQQDRUFF,R Director's Office of Inspection and Enforcement, Bi/05/22 CHUNG, J Region i. Philadelphia, Office of the Director (81/03/01). 5pp 22481,340
- --8403010206 Requests Procedures 617278 & 617288 be issued & Manual Chapters 2514 & 2515 be revised to require that Procedure 617278 be performed during hot functional testing & Procedure 617280 be performed annually JORDAN, E. L. Division of Reactor Operations Inspections 80/08/22 DRYAN, 8 E NRC No Detailed Affiliation Given ip. 22480 310
- --8403010214 Forwards Procedures 617278 & 617288. Procedures outline steps necessary to perform independent measurements of leak rates from RCB for PWRs Each region requested to apply both procedures to one PWR per wk starting 801018 W/o encis JORDAN, E L. Division of Reactor Operations Inspections 80/08/22 Region 1. Philadelphia. Office of the Director. Spp 22480 311
- --8403010222 Forwards progress rept on development of computerized inep techniques.W/o encl. SNIEZEK, J NRC - No Detailed Affiliation Given 81/11/18 DEYGUNG, D NRC - No Detailed Affiliation Given ip 22481 347

- -8403010233 Discusses RCS leak rate calculations, per 820504 teicon Mods to RCSLK7 computer program permit leak rate calculations for pressures between 1,900 & 2,100 psig w/temp between 260 F & 270 ! Plant data enci MORRILL.P J Region 5, Office of Director 82/05/05 WODRNUFF, R M Reactor Engineering Dranch 17pp 22481 362 24x Fichc 50-000,64/01/25,8403010117
- --8403010239 Agrees that use of computers as insp tool needs to be explained further per 830413-14 presentation Lists recommendations based on review of RCBLKB User Guide & practical demonstration of computer program KEAKNEY, J NRC No Detailed Affiliation Given 83/04/15 MDDDRUFF, R NRC No Detailed Affiliation Given 2pp 22482 017
- --8403010257 "DKHT5-Calculated Net Power & Integral of Net Power as Function of Time After Scram " WDDDKUFF,R W NRC - No Detailed Affiliation Given BO/12/05 6pp 22480 322
- --8403010284 "RC9LK8 "
 * NRC No Detalied Affiliation Given 81/07/08 7pp
 22401 007
- --B403010287 Forwards Hewlett Peckard program cards for RCS Leak Rate Program 7 (RCSLK7) W/o encl KIRKPATRICK, D Director's Office, Office of Inspection and Enforcement 81/07/21 MORRILL:P J Reactor Projects Section 1 ip 22481 019
- --B403010292 Requests Hewiett Packard 4iC data cards for piont reactor conjunt leakage calculations Program being developed to run reactor conjunt leakage calculations on NRC ECLIPSE computer Data cards needed to set up data base BAER, R L Reactor Engineering Branch 81/09/02 MARTIN, T T Division of Engineering & Technical Inspection OIBSON, A F Division of Engineering & Technical Inspection ip 22481,020
- 8403010ii9 FOIA request for studies performed by USGS & State of CA Div of Mines & Geoiogy re facility seismic design CALSOYAS,C D Affiliation Not Assigned 83/11/14 NRC -- Nu Detailed Affiliation Given 4pp 22444 345 24X Fiche 50-312.83/11/14,8403010ii9
- 8403010123 Responds to FOIA request for studies performed by USGS & State of CA Div of Mines & Geology re facility seismic design Forwards App A documents Info also available in PDK FCLTON.J M. Division of Rules and Records 83/12/20 CALSDYAS, C.D. Affillation Not Assigned 3pp 22444 349 24X Fiche 50-312.83/12/20.8403010123
- --7706440545 Summary of telcon to provide response to 770413 ltr requesting info re seismic analysis QARNERD Operating Reactors Branch 4 (Pro 770625) 77/04/25 REID, R W Operating Reactors Branch 4 (Pre 770625) ip 22444 352 24X Fiche 50-312,83/12/20,8403010123
- --7906140548 Discusses review of plant earthquake design criteria & requests info re seismic analysis
 BAVI3.J F California, State of 79/04/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22444 353 P4X Fiche 50-312,83/12/20,8403010123
- --7910760122 Summarizes view of recent fault data, NRC requirements & fact that FSAR considered only three faults active Recommends that new info on fault sys be assessed MiNOQUE, R B Office of Standards Devolopment, Director 79/10/01 DENION.H R Office of Nuclear Reactor Regulation, Director 4pp 22444 358 24% Fiche 50-312,83/12/20,8403010123
- --7911120317 Forwards RB Minogue 791001 memo to HR Denton & evaluation of televancy to proceedings before ASLD EIGENHUT.D G Division of Operating Reactors 79/10/19 SCUTT,S Distribution Services Dranch 3pp 22444 355 24X Fiche 50-312,83/12/20,8403010123
- --7911120366 Forwards seismicity rept re Sacramento County, CR & portions of 680816 CA application & 730608 safety evaluation TISON.J C Commerce, Dept of. 68107/05 FRICE, H L Atomic Energy Commission, Directorate of Regulatory Operations, 1p 22445 085 24% Ficha 50-312,83/12/20,8403010123
- --791i120370 Requests add1 info to complete review of initial site examination info data form DEYDUNG.R C Atomic Energy Commission. Directorate of Licensing 74/12/13 DAVIB.E K Bacramento Municipal Utility District Rpp 22445 028 24X Fichs 50-312.83/12/20,8403010123

- --791iiPO403 Requests initial site eramination info OIAMBUSSO.A Atomic Energy Commission, Directorate of Licensing 74/00/14 DAVIS.E K Sacramento Municipal Utility District 5; 22445 034
- --7911120413 Responds to 760115 ltr re DL Kelleker 751217 concern about nuclear plant in Drville, CA vicinity No plant glanned for area Discusses DBE re plant design DIRCKS, W J NRC No Detailed Affiliation Given 76/02/06 CRANSTON, A Senate 3pp 22445 041 24x Fiche 50-312,83/12/20,8403010123
- --B001290311 Forwards response to 791001 memo re geologic & seismic reassessment of facility No immediate hazard at site Licensee should undertake program to assemble & assess new info re geology & seismology of site region JACKSON.R E Geosciences Branch 79/12/21 GAMMILL, W P Assistant Director for Standard & Advanced Reactors 7pp 22445 050 24X Fiche 50-312,83/12/20.8403010123
- --8009250342 Recommends meeting w/util to review progress of seismit NOMBOUSER RECOMMENTS WAS ASSESSED BY RESIDER H OPERAL STORM RESIDER H OPERAL STORM RESIDER H OPERAL RESIDER H OPERAL RESIDER H PACTOR Branch 4 Ip 22445 057 24% Fiche 50-312,03/12/20. Operating Reactors Branch 4 8403010123
- ---B007250345 Discusses util response to NRC request for seismic reassessment Soven listed areas of info should be directed to util to avoid delay in reviewing rept ALFERMAN. I B. Geosciences Branch B0/09/12 JACKBON, R E. Geosciences Branch Jpp 22445 058 24X Fiche 50-312,83/12/20, page 1012-1012
- --B403010150 Forwards evaluation of Unit 2 initial site exam info data review Site safety members participating in review listed DENTON-HR Atomic Energy Commission. Directorate of Licensing 74/10/10 BEYOUNG, RC Atomic Energy Commission. Directorate of Licensing 4pp 22445 046 24X Fiche 50-312.83/12/20.8403010123
- B403010125 Further response to FOIA request for IE Rept 79-19, notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards documents listed on
 - FRELTON, J.M. Division of Rules and Records 84/01/11 H Shaw, Pittman, Potts & Trowbridge 2pp 22447 176 24X Fiche 50-498,84/01/11,8403010125
- --B403010132 Requests info re public hearing on insp of facilities SCHMARTIA R Texas, State of B0/06/03 SEYFRIT, K Region 4, Dallas, Office of the Director 1p 22447 179 24X Fiche 50-498,84/01/11.8403010125
- --8403010139 Transcript of 800819 public meeting in Bay City.TX Pp 1-382 Supporting documentation encl * Commissioners 80/08/19 382pp 22447 181 24X Ficht 30-499,84/01/11,8403010125.
- B403010168 Further response to FDIA request for all 1982 SECY papers to be available in PDR SECY-82-2.60.1978.1970.228.270A.334A. 377A.389.394.455A.472 & 472A withheld (ref FOIA Exemption
 - D) FELTON, J.M. Division of Rules and Records 83/12/21 WEISS, E.R. Union of Concerned Scientists WEISS, E.R. Harmon & Weiss App 22449 313
- 8403010192 FOIA request For records relevant to or generated in connection w/831021 "Rept on Review of Diesel Generator Bldg at Misland" ex Mibianu "GARDE, N P Government Accountability Project 63/11/26 Off of Administration 2pp 22445 092 24X Fiche 50-329, 83/11/26, 8403010192
- B40301019B Responds to FOIA request for records relevant to or generated in connection w/B31021 "Rept on Review of Diesel Generator Bldg at Midland " Forwards App B documents App A documents available in PDR FELJON. J M Division of Rules and Records B3/12/14 GARDI Government Accountability Project App 22445 092 24% Fiche 50-327.83/12/14.8403010178 GARDE, B P
- --8310310471 Forwards task group rept. "Rept on Review of Diesel Generator Didg at Midland," Dct 1983 Large addl settlements not anticipated More accurate program to monitor cracks needed
 - -tural & Geotechnical Engineering Branch 83/10/21 Assistant Director for Comp & Structures Engineering 2pp. 22445 152 24X Fiche 50-329,83/12/14,
 - eview of Diesel Generator Bldg at Midland " 1 & Geotschnical Engineering Branch 89/10/31 24% Fiche 50-327,83/12/14,8403010178

- --8312010004 Forwards corrected Pages 9,17,20 & 4 to App 11 to rept on review of diesel generator bldg
 KWO,P Btructural & Geotechnical Engineering Granch
 KNICHT.JP Assistant Director for Comp & Structures Engineering
 (Post 830201) Spp 22445-256 24X Fiche 50-329,83/12/14,
- --8312050628 Requests rept re adequacy of diesel generator bldg on expedited basis as input to Congress re Landsman concerns EISENHUT, D G Division of Licensing 83/11/18 VOLLMER.R Division of Engineering ip 22445 263 24% Fiche 50-329.83/12/14,8403010198
- -- H312070022 Forwards Structural & Geotechnical Engineering Branch assessment of "Rept of Review of Diesel Generator Eldg at Midland," dtd 831021 per E Adensam & W Paton requests Midland, " oto 831021 per E Adensem & Feson requests
 Meeting & Possible reopening of hearing recommended
 LEAN, O Structural & Geotechnical Engineering Branch 83/11/22
 VOLLMER, R H Division of Engineering 2pp 22445 268 24X
 Fiche 50-329,83/12/14,8403010198
- --8312070278 Discusses recommendation for suppl to Board Notifications 83-165 & 83-153 re diesel generator bldg Comments & recommendations of J Kane & F Rinaldi on task group rept & recommendations of J wane & Filingia on task group rept & reopening of hearing provided HODD, D & Licensing Branch 4 ISSUANCES OM 83/11/22 EISENHUT, D O Division of Licensing 4pp 22445 264 24X Fiche 50-329,83/12/14,8403010198
- --8312080134 Recommends PT Kuo 831114 memo containing four corrected pages to rept re structural adequacy of diesel generator bldg be forwarded to Board as supplemental notification to Blog se rormance to source at 1850 and EISENHUT. D
- --8403010204 Advises that info re plan to address Landsman concerns should be issued as Board Notification 83-109
 EISENHUT, D. Q. Division of Licensing 83/07/27 NOVAK, T. Assistant Director for Licensing in 22445 098 24X
 Fiche 50-329,83/12/14,8403010198
- --8403010211 Advises that attached correspondence re new schedule for review of Landsman concerns should be issued as Doard Notification 83-142 W/o encl EISENHUT, D. @ Division of Licensing 83/07/20 NOVAK.T Assistant Director for Licensing 1p 22445 099 24X ROCEFFICATION 83-142 W/O encl CISENHUT, D.Q Division of Licens Assistant Director for Licensing Fiche 50-329,83/12/14,8403010198
- --8403010217 Draft rept, "Review of Diesel Generator Bldg at Midland Plant MILLIR, C.A., COSTANTINO, C.J. Brookhaven National Laboratory 83/07/23 25pp 22445 100 24X Ficha 50-329.83/12/14,8403010198
- --8403010223 Advises that encl JP Knight 830923 memo to RH Vollmer should be issued as Board Notification 83-153 W/o entl BIBENHUT, D © Division of Licensing 83/10/05 NOVAK, T Assistant Director for Licensing pp 22445 125 24X Fiche 50-329:83/12/14,8403010198.
- --8403010227 Forwards "Review of Diesel Generator Bldg at Nidland Plant " REICH.M Brookhaven National Laboratory 83/10/17 KUO.P T Structural & Geotechnical Engineering Branch ip 22445 126 24X Fiche 50-329, 83/12/14.8403010198
- --B403010231 "Review of Diesel Generator Bldg at Midland Flant" MILLER.C A., COBTANTINO.C J. Brookhaven National Laboratory, B3/10/17 25pp. 22445 127 24X Fiche 50-329,83/12/14,8403010198
- --8403010245 Requests that encl rept on review of diesal generator bldg & util analysis requested during review be issued as Board Notification 83-165 EISENHUT, D. G. Division of Licensing 83/10/26 NOVAK, T. Assistant Director for Licensing 6pp 22445-250 24X Fiche 50-329,83/12/14,8403010198
- --84030i0279 Advises that supplemental info provided in PT Kup 831i14 we will be seen that supplemental into provided in PLAUS memo to JP Knight will be transmitted to Hidland Board as suppl to Board Notification 83-165. Issue will be incorporated as Board Notification 83-165 M/o encl EISCNHUT. D. O. Division of Licensing 83/11/16 NOVAK, T Assistant Director for Licensing 1p 22445.262 24X Fiche 50-329.83/12/14,8403010198
- --B4030102B2 Forwards guidants for use in deciding whether to recommend that hearing be reopened Hearing should be reopened based on listed reasons VOLLMER, R H Division of Engineering 83/11/25 EIBENHUT, D. G. Division of Licensing. 3pp. 22445, 270. 24X Fiche 50-329, 83/12/14, 8403010198

- ---B403010285 Advises that Vollmer recommended reopening Midland hearing on diesel generator bldg structural adequacy issue, based on task group rept Vollmer memo encl W/o encl ADENSAM,E NRC No Detailed Affiliation Given 83/11/25 EISENHUT,D NRC No Detailed Affiliation Given ip 22445 273 24X Fiche 50-329,83/12/14.8403010198
- B403010262 Further response to FOIA request for documents re Sandia Contract A-1123 & bibliography used by R Bernero Forwards App A documents
 FELTON, J M Division of Rules and Records FIN A-1123 83/12/20 RUTLEDGE.P Carolina Environmental Study Group 2pp 22444 069 24X Fiche 50-000.B3/12/20.B403010262
- --8301280380 Responds to 821108 ltr & newspaper article.clarifying distorted & incomplete picture of nuclear accident probabilities & consequences & modeling uncertainties presented in article DIRCKS,W J Office of the Executive Director for Operations 82/12/27 DOGOS,L House of Rep 4pp 22444 078 24X Fiche 50-000,83/12/20.8403010262
- --840301026B Forwards preliminary draft documents re Sandia Labs work in area of siting criteria development Repts represent work being done in expanding use of probabilistic analysis in regulatory work W/O encls
 DIRCKS.W J Office of the Executive Director for Operations
 B2/04/26 GILINSKY Commissioners 5pp 22444 071 24X
 Fiche 50-000,83/12/20,8403010262
- --8403010274 Discusses research rept.NUREO/CR-2239 (Band81-1549),
 "Technical Guidance for Biting Criteria Development "
 Forwards NUREO/CR-2723 & NUREO/CR-2899 for ref use only W/o
 encls
 DIRCKG,W J Office of the Executive Director for Operations
 B2/11/22 PALLADING, OILINSKY, AHEARNE Commissioners Rpp
 22444 076 24X Fiche 50-000,83/12/20,8403010262
- 8403010278 FDIA request for SECY-83-288 to be piaced in PDR PEDRO.J NV8 Corp CD-18-83-535 83/11/16 Division of Rules and Records 1p 22449 137
- 8403010279 Responds to FOIA request for SECY-83-288 to be placed in PDR Forwards SECY-83-288. Document also available in PDR FELTON, J M Division of Rules and Records 83/12/16 PEDRO, J NUS Corp 1p 22/49/138
- --8403010283 Comments on SECY-83-288 re proposed rule on pressurized thermal shock Proposed rule should address CP applicants in addition to OL applicants & operating reactors Schedule for preparation of plant-specific safety analyses acceptable ZERDE. J E Office of Policy Evaluations 83/08/01 PALLADING. GILINSKY, ROBERTS Commissioners 4pp 22449 222
- 8403010383 Responds to FDIA request for map detailing background radiation levels, prapared as result of aerial survey conducted out of Pease Air Force Base No records subj to request located FELTON, M Division of Rules and Records 83/12/20 DOUGHTY, J Beacoast Anti-Pollution League ip 22446 346
- 8403010385 FDIA request for add1 search of files for map detailing background radiation levels, prepared as result of aerial survey conducted out of Pease Air Force Base DDUGHTY, J Baccoast Anti-Pollution League 83/11/23 FELTON, J M Division of Rules and Records 1p 22446 347
- B403010407 Responds to FDIA request for info on Tatum salt dome tests performed in State of MS in late 1760s or early 1770s No documents available pertaining to request info may be obtained from State of MS Dept of Natural Resources FELTON, J M Division of Rules and Records B3/12/16 LEGGETT, L H Affiliation Not Assigned ip 22443 280
- B403010409 FDIA request for lists of all source disposal companies licensed to handle redueste disposal GEBELE, H W Foxboro Corp 83/11/18 Office of Administration ip 22446 331
- B403010410 Responds to FD1A request for list of all source disposal companies licensed to handle radwaste disposal Forwards two lists
 FELTON, J M Division of Rules and Records B3/12/15 GEBELE, H W Foxboro Corp ip. 22446
- --8403010412 "Waste Disposal Licensees "

 * NRC No Detailed Affiliation Given. 82/02/05 App 22446:333
- --B403010414 "Active Byproduct Licenses." * NRC - No Detailed APPlilation Given 83/12/02 7pp 22446.339

- B403010469 FOIA request for info on Tatum selt dome tests performed in State of MS in late 1960s or early 1970s LEGGETT.L H Affiliation Not Assigned B3/12/02 NRC - No Detailed Affiliation Given Ip 22443 2B1
- 8403010474 FD1A request for info re sign posted near toilst at Angonatte reactor at Univ of Fibrida GROSSMAN.K leiand Closeup News Service, Sag Harbor, NY 84/01/31 NRC - No Detailed Affiliation Given 1p 22443 278
- 8403010480 Responds to FOIA request for info re sign posted near toilet at Angonatte reactor at Univ of Florida FELTON. J M Division of Ruies and Records 84/02/27 GROSSMAN. K Island Closeup News Service, Sag Marbor, NY ip 22443 279
- B403010488 Appeals denial of FDIA request for T Novak notes generated by or during visit to Glen Ellyn IL to discuss Dfc of Special Cases findings re facilities from Sept 1982 to Dec 1983 GARDE, B P Government Accountability Project 84/01/17 FELTON, J M Division of Rules and Records 1p 22443 274 24X Fiche 50-329, 84/01/17, 8403010488
- 8403010497 Responds to appeal re denial of FOIA request for records in possession of T Novek on visit to Olen Eliyn.iL to discuss findings of Ope of Special Cases re facilities NRC has no records subj to request DIRCKS.H J Office of the Executive Director for Operations 84/02/28 QARDE.B F Qovernment Accountability Project ip 22443 273 24X Fiche 50-329.84/02/28.8403010497
- 840302000B FOIA request for radiation source or device registration certificates issued by NRC to listed organizations HAMMITI HA FOI Services 3451 84/01/26 FELTON J M Division of Rules and Records 3pp 22494 001
- 8403020011 Responds to FOIA request for radiation source or device registration certificates issued by NRC to organizations listed in request itr Forwards requested documents FELTON.J M Division of Rules and Records 84/02/09 HAMMITT.H A FOI Services ip 22494 004
- --B403020016 Registry of radioactive sealod sources & devices, safety evaluation of X-ray fluorescence cell mfg by AMP, Inc using New Ingland Nuclear Model NER-476C * NRC No Detailed Affiliation Given NR-140-D-101-5 83/07/08 5pp 22494 005
- --84030P0018 Registry of radioactive sealed sources & devices, safety evaluation of detector cell mfg by Antok Instruments, Inc using US Radium Madel LAB-508-1 & New England Nuclear Model NER-002
 KLINGER, JO NRC No Detailed Affiliation Given TY-145-D-103-6 82/12/17 3pp 22474 010
- --B403D20023 Registry of radioactive sealed sources & devices, safety evaluation of luminous front post sight containing 3M Model EEX Army Fart B48B490 for Pr-147 & Part 12002966 for tritium distributed by US Army Armament Readiness Command F NRC No Detailed Affiliation Given NR-153-D-101-5 B3/03/07 2Pp 22494 013
- --8403020027 Registry of radioactive sealed sources & devices, safety ovaluation of radioluminous lamp containing 3 Ci tritium. distributed by US Army Armament Matl Readiness Command M NRC No Detailed Affiliation Given NR-195-8-101-9 83/03/08 App 22494 015
- --B403020034 Registry of radioactive scaled sources & devices, safety evaluation of radioluminous lamp containing 10 Ci tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Given NR-155-2-102-B 83/03/08 Gpp 22494·019
- --8403020038 Registry of radioactive sealed source* & devices, safety evaluation of radioluminous lamp containing B C1 tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Given NR-155-S-103-S 83/03/08 3pp 22474 022
- --B403020057 Registry of radioactive sealed sources & devices safety evaluation of radioluminous lamp containing tritium, distributed by US Army Armament Matl Readiness Command.

 * NRC No Detailed Affiliation Given NR-155-S-104-S 83/03/08 7pp. 22474 025
- ---B403020040 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous lamp containing 6 Ci tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Given NR-155-8-105-8 83/03/08 3pp 22494 034

- --8403020067 Registry of radioactive sealed sources % devices, safety evaluation of radioluminous lamp containing 2 2 C1 tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Gaven NR-155-S-106-S 83/03/0 3pp 22494 037
- --8403020070 Registry of radioactive sealed sources & devices, safety evaluation of radioiuminous lamp containing & Ci tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Given NR-135-8-107-8 83/03/08 3pp 22494 040
- --8403020074 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous iamp containing 4 Ci tritium, distributed by US Army Armament Matl Readiness Commend * NRC No Detailed Affiliation Given NR-155-5-108-S B3/03/0 Upp 22494 043
- --8403020080 Registry of radioactive sealed sources & devices, safety evaluation of radioiminous lamp containing tritium:
 distributed by US Army Armament Mati Readiness Command
 * NRC No Detailed Affiliation Given NR-155-S-109-S 83/03/08
 700 22474 046
- --B4030200B2 Registry of radioactive smaled sources % devices, safety evaluation of mass spectrometer containing 15 mCi Ni-63 in Phemto-Chem HMS-160 distributed by PCP, Inc * NRC No Detailed Affiliation Given FL528D102U 79/08/29 2pp 22494 232
- --8403020087 Registry of radioactive seaked sources & devices, safety evaluation of radioluminous lamp containing 1 C₃ tritium, distributed by US Army Armament Mat1 Readiness Command * NRC No Detailed Affiliation Given NR-155-8-110-9 83/03/08 3pp 22494 053
- --8403020091 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous lamp containing 1 2 Ci tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Given NR-155-8-111-9 803/03/08 30p 22494 056
- --8400020075 Registry of radioactive sealed sources & devices, safety evaluation of electron capture detector cell assembly containing 15 mC, Nix-63 in New England Nuclear NER-002 & Nuclear Radiation Development N1001 sealed source BROWN J H, SINGER, B NRC No Detailed Affiliation Given NR536D0198 82/04/30 App 22494 234
- --B403020101 Registry of radioactive spaled sources & devices, safety evaluation of interstitial implant source & storage vessel w/15 mCi Ir-192 in Model R/1 (seeds) & P-1,P-2,P-3 & P-4 containers, mfg by RAD/IRID. Inc BROWN. J M NRC NO Detailed Affiliation Given NR-558-8-101-8 G3/01/20 lipp 22494 240
- ---8403070107 Registry of radioactive scaled sources & devices, safety evaluation of gaseous tritium light sources (OTLS) in military fire control products mfg by Ruoff & Sons, Inc & distributed by UB Army Armament Readiness Command WRIGHT, E G., SINGER, B NRC No Detailed Affiliation Given NR-575-D-101-S 82/09/24 Spp 22494 251
- --8403020iiO Registry of radioactive sealed sources & devices, pafety evaluation of radioluminous lamp containing 8 Ci tritium, distributed by US Army Armament Matl Readiness Command * NRC *No betailed Affiliation Given NR-155-9-112-8 83/03/08 3pp 22494 039.
- --84030P0113 Registry of radioactive sealed sources & devices, safety evaluation of self-luminous compass containing 175 mCi tritium in Brandhurst Co light source Model RT/60-25/10 mfg by Suuncb Oly & distributed by Sea Quest, Inc BROWN, J M NRC No Detailed Affiliation Civen. NR-591-D-103-E 03/07/22 9pp 22494 259
- --8403020114 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous lamp containing tritium, distributed by US Army Armament Matl Readiness Command, # NRC No Detailed Affiliation Given. NR-153-6-113-8 83/03/08 3pp 22494 062
- --8403020116 Registry of radioactive smaled sources & devices, safety evaluation of electron capture detector cell containing 150 mci tritium in Safety Light Corp foil source Model 508-3,mfg by Bentex Gensing Technology Inc BROWN, J M NRC No Detailed Affiliation Given NR-595-D-101-8 B3/08/26 7pp 22494 268

- -- GAOGORO119 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous lamp containing tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Given NR-155-8-114-8 63/03/08 3pp 22474 065
- --8403020120 Registry of radioactive soaled sources & devices, safety evaluation of gas chromatograph containing 20 mCi Ni-63 in US Radium LAB 784. New England Nuclear NER-004 & Amersham/ Searl NBC.neg by Spectra-Physics WONG, G NRC No Detailed Affiliation Given CA615D101S 82/12/07 4pp 22494 275
- B403020124 Registry of radioactive sealed sources & devices, safety evaluation of ionization smoke detector containing 1 uci Am-24i foil source in NRD Model A-001 or Amersham Model AMH-1001H, mfg by Square D Co WRIGHT, E O. SINGER, B NRC No Detailed Affiliation Given NR-616-D-101-E 82/09/07 Epp 22494 279
- --B403020127 Registry of radioactive sealed sources & devices, mafety evoluation of lensatic induction damped compass containing 120 mci tritium in Stocker & Yale, Inc Model SY-183 SINGER, D NRC + No betailed Affiliation Oiven NR-622-D-102-E B3/01/18 Bpp 22494 287
- --8403020132 Registry of radioactive sealed sources & devices, safety evaluation of calibr device containing 100 Cl Cs-137 in GRNL Drawing RD309 8, mfg & distributed by TEMCO PATRICK, D P. BURGESS, J L. NRC No Detailed Affiliation Given ND431D101S 83/06/14 3pp 22494 295
- --8403020135 Registry of radioactive sealed sources & devices, safety evaluation of self-luminous source in watch models containing 200 mCi tritium in Mertz-Bentelli T4173-1 & T4173-1, mfg by Texas Instruments * NRC No Detailed Affiliation Given NR-432-S-102-E 82/10/08 ip 22474 298
- --8403020137 Registry of radioactive sealed sources & devices, safety evaluation of density gauge containing 230 mCi Cs-137 in Amersham Corp Model CDC 810.mfg by Tatabanyai Szenbanyak BROWN.J M NRC No Detailed Affiliation Oiven NR-633-D-102-8 83/08/15 8pp 22494 299
- 8403020142 Registry of radioactive smaled sources & devices, marety evaluation of consolidation monitoring device containing 500 mCi Cs-137 in Oulf Nuclear. Inc Model CSV.mfg by Rexnord, lnc & distributed by DUT EROWN.J M NRC No Detailed Affiliation Given NR-643-D-102-8 83/11/04 7pp 22494 307
- --B403020144 Registry of radioactive scaled sources & devices, safety evaluation of pipe wall thickness gauge containing 10 Ci CS-137 in 3N Model 406L & Gulf Nuclear CSV, mfg by WB Wilson Mfg Co # NRC No Detailed Affiliation Given TX672D106S 79/07/31
- --8403070149 Registry of radioactive sealed sources & devices, safety evaluation of sulfur-in-oil analyzer containing 550 mCi
 Am-241 in Amersham/Searle AMC 17.mfg by Yokugawa Electric
 Works & distributed by Yokugawa Corp of America
 ** NRC No Datailed Affillation Given GA678D1028 80/09/25
 2pp 22494 317
- --8403020i50 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous lamp containing 8 Ci tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Given NR-155-8-115-8 83/03/08 3pp 22494 068
- --8403020153 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous lamp containing 8 Ci tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Given NR-155-8-116-8 83/03/08 3pp 22494 671.
- --840302014A Registry of radioactive sealed sources & devices, safety evaluation of radiation source assembly containing 500 mCi cs-137 in Amersham CDC 192,809,810 & 811 mfg by Level Link, Inc.
 WDN0,0 NRC No Detailed Affiliation Given CA423D1028 83/04/15. 7pp 22494 145
- --8403020170 Registry of radioactive scaled sources & devices, safety evaluation of radioluminous lamp containing 2 2 Ci tritium, distributed by US Army Armament Matl Readiness Command. ** NRC No Detailed Affiliation Given NR-155-8-117-8, 83/03/08 3pp 22494 074

- --8403020172 Registry of radioactive sealed sources & devices, safety evaluation of X-ray fluorescence spectrometor containing 10 mCl Fe-53 & 15 mCl Cd-109 in lsotope Products Labs Model XFD-5, distributed by Martin Marietta Corp BRCWN.J M , SINGER.B NRC No Detailed Affiliation Given NR-441-D-101-B 82/10/01 5pp 22494 172
- --840302017& Registry of radioactive sealed sources & devices, safety evaluation of chemical agent detector, containing 250 uC; Am-24i in Amersham Corp foil source Model AMM:1001, distributed by US Army Armament Matl Readiness Lommand BROWN, J M NRC No Detailed Affiliation Given NR-155-D-118-S G3/06/15 5pp 22494 077
- --B403020177 Registry of radioactive scaled sources & devices safety evaluation of UV emitting light source containing i C: tritium, distributed by Mh-Microtec BROWN, J M NRC No Betailed Affiliation Oiven NR-446-S-101-S 83/09/22 4pp 22494 177
- --B403020179 Registry of radioactive scaled sources & devices safety evaluation of pipe monitor containing 200 mCl Cs-i37 in New England Nuclear NER-370 (ANSI CS4434), distributed by Merrick-Scale Mfg # NRC No Detailed Affillation Given NR452D101S B0/09/03 4pp 22494 B1
- --8403020180 Registry of radioactive swaled sources & devices, safety evaluation of gamma ganging device containing 14 mCi Am-241 in Amersham Nodel AMC 24 or New England Nuclear Model NER-478C.mFg by Bedford Engineering Corp WRIGHT, E O , SINGER, B, NRC No Detailed Affiliation Given NR-182-D-101-B 82/11/10 Bpp 22494 082
- --8403020183 Registry of radioactive sealed sources & devices, safety evaluation of backscatter probe Model JLK. containing 30 mC: Am-241 in Amersham/Searle Corp AMC 66. distributed by Mettronix Co WONG, 0 NRC No Detailed Affillation Given CA 45701018 82/11/03 5pp 22494 185
- ---8403020184 Amended registry of radioactive sealed sources & devices, safety evaluation of brachytherapy source & storage devices containing 30 mCi 1r-192 in Best Model 81-01 seeds.mfg by Best Industries.Inc

 * NRC No Detailed Affiliation Given NR187D101S 82/12/09 10pp 22494 090
- --8403020187 Registry of radioactive sealed sources & devices, safety evaluation of beta source containing 500 mCl Pm-147 in New England Nuclear Model NER-8190 BROWN, J M , BABSIN, N NRC No Detailed Affillation Given NR47681448 82/10/18 5pp 22494 190
- --B403020191 Registry of radioactive scaled sources & devices, safety evaluation of beta source containing 1,150 mCi Kr-85 in New Ingland Nuclear Model NER-8180 BROWN,J M. BASSIN,N NRC No Detailed Affiliation Given NR-476-6-145-8 82/10/18 5pp 22494 195
- --8403020193 Registry of radioactive sealed sources & devices.safety evaluation of brachytherapy sources containing 33 mCi Au-198, mfg by Best Industries.Inc BINGLR.O NRC - No Detailed Affiliation Olven NR18791028 82/12/09 8pp 22494 100
- --84030P0194 Registry of radioactive sealed sources & devices, safety evaluation of beta source containing 2,200 mC1 Kr-85 in New England Nuclear Model NER-584 WRT6HT,E 0, SINGER, B NRC No Detailed Affiliation Given NR47681468 82/03/18 App 22494 200
- --B403020199 Registry of radioactive scaled sources & devices, safety evaluation of Am-241 low energy photon disc source containing 10 mg/s Am-241 in New England Nuclear Model NER-478H BROWN, J M , SINGER, B NRC No Detailed Affiliation Given NR47681478 62/08/06 5pp 22474 206
- --84030202000 Registry of radioactive sealed sources & devices, safety evaluation of whole body counter calibr sources containing Co-60, Cs-137, 1-125, 1-131, Cr-51, Cd-107, Zn-65, Ba-133 & Mn-54, mfg by Bio-Nuclear Measurements, Inc BROWN, J M NRC No Detailed Affiliation Given NR-188-S-101-S 63/07/23 6pp 22494 108
- --8403020201 Registry of radioactive sealed sources & devices, safety evaluation of low energy photon annular source containing 1.150 mCi Cd-109 in New England Nuclear Model NER-468 R & NER-468 A BROWN, J M NRC No Detailed Affiliation Given NR-476-9-148-9 82/12/27 App 22494-211

- B403020208 Registry of radioactive sealed sources & devices, safety evaluation of beta radiation source containing i, i50 mC1 Kr-B5 in New England Nuclear Model NER-B170 BRCWIN.J M NRC No Detailed Affiliation Given NR-474-8-149-5 83/i0/25 5pp 22494 2i5
- --8403020210 Registry of radioactive sealed sources & devices.safety evaluation of gas aeroso) detector containing 10 mCi Ni-63 in detector cell sources mfg by Ion Track instruments or Chevron Research Co BRCWN.J M NRC No Detailed Affiliation Given NR-224-D-101-E 03/00/15 6pp 22494 114
- ~~8403020212 Registry of radioactive sealed sources & devices, safety evaluation of interstitial treatment of cancer involving 34 mCi Au in grains, distributed by Nuclear Sources & Svcs, Inc.

 NRC No Detailed Affiliation Given TX5089105U 78/02/28 3pp 22494 220
- --8403020215 Registry of radioactive sealed sources & devices, safety evaluation of logging tool tailbr std containing 5 uCi
 Th-232 or natural U in Nuclear Bources & Svcs Model 69-C or
 GS-M
 BASS, J T NRC No Detailed Affiliation Given TX50851060
 83/11/03 3pp 22494 223
- --B4030P0219 Registry of radioactive sealed sources & devices, safety evaluation of dosimeter irradiator containing 100 Ci Cs-13/ in DRNL Drawing RD309 B PATRICK,DP P, BURGESS,J L NRC No Detailed Affiliation Given ND518S103S B3/06/14 6pp 22494 226
- 8403020224 Registry of radioactive sealed sources & devices, safety evaluation of computer sys containing smoke detector unit w/l uCl Am-241 in Honeywell TC 100C smoke detector unit distributed by Control Data Corp MRIGHT.E G NMC No Detailed Affiliation Given NR-233-D-101-E G3/03/08 7pp 22494 120
- --0403020227 Registry of radioactive sealed sources & devices, safety evaluation of sample irradiator containing 100 mCi Sr-90 in Isotope Products Labs Model BF90 Ti distributed by Daybreak Nuclear & Medical Sys.inc DROWN.J M NRC No Detailed Affiliation Given NR-250-D-101-S 03/07/03 5pp 22494 i27
- --8403020232 Registry of radioactive sealed sources & devices, safety evaluation of electron capture cell containing to mci tritium in Bafety Light Corp Model 20203 or US Radium LAB-508-3, distributed by Deiphl Instruments, Inc MONG, 0 C NRC No Detailed Affiliation Given CA254D1020 B3/06/28 Spp 22494 132
- --8403020237 Registry of radioactive sealed sources & devices, safety evaluation of luminous marker switch containing 44 mCi tritium in MH 1132/0/150 Model I distributed by Dowty Electronics Co & Baunders Ror Development

 * NHC No Detailed Affiliation Olven NR-258-D-101-S B2/10/05 ip 22474 137
- --8403020240 Registry of radioactive scaled sources & devices, safety evaluation of X-ray fluorescence analyzer containing iOO mCs Fe-55 in New England Nuclear Model NER-461A, mfg by Texas Nuclear & distributed by Dow Chemical USA BELL, S NRC No Detailed Affiliation Given NR-260-D-101-9 83/iO/18 Δpp 22494 i38
- --B403020243 Registry of radioactive scaled sources & devices, safety evoluation of gas chromatograph containing 15 mC: NI-43, mfg by Victoreen instrument Co & distributed by Fisher Scientific Co * Atomic Energy Commission NR294DiOiV 70/11/30 2pp 22/14 144
- ---8403020244 Registry of radioactive sesied sources & devices, safety evaluation for gas chromatography detector ceil containing 15 mCl Ni-40 in Amorsham/Searle foil.mfg by Victoreen Instrument Co & distributed by Fisher Scientific Co * Atomic Energy Commission NR294D102V 70/11/26 2pp
- --8403020251 Registry of radioactive sealed sources & devices, safety evaluation of cigarette density gauge containing 25 mCi Sr-90 in Amersham Buchler GmbH & Co kg Model 1411 mfg by Hauni-Herke & distributed by Hauni-Richmond, Inc BROWN, J M NRC No Detailed Affiliation Given NR-345-D-103-S 63/06/07 bpp 22494 148

- --8403020255 Registry of radioactive sealed sources & devices, safety evaluation of smoke detector containing i uCi Am-241 in Amercham Model ARM-1001 mfg by Hochiki Corp & distributed
 - by Hoth Hir-American Corp

 NRC No Detailed Affiliation Given NR-355-D-103-E 83/07/22
 3pp 22494 153
- --8403020259 Registry of radipactive sealed sources & devices, safety evaluation of aerosol analyser containing 124 uCi Am-24i in Amersham Model AMMQ-2367, distributed by IITRI Research Inst

 NRC No Detailed Affiliation Given NR-367-D-101-S 82/10/0 pp 22494 155 82/10/06
- --8403020264 Registry of radioactive sealed sources & devices, safety evaluation of underwater radiography containing 100 Gi Ir-192 in Oamma Industries.Inc PTL-1.distributed by
 - JG Sylvester Assoc. Inc

 * NRC No Detailed Affiliation Given NR-407-D-101-8 82/10/06

 19 22474 159.
- ---8403020267 Registry of radioactive smaled sources & devices, safety evaluation of neutron generator tube containing 7 Ci tritium in Xaman 1-314-115781-000 or 1-314115782-000.mfg by Kaman * NRC - No Detailed Affiliation Given CO411D1-15 82/03/03
 - 22494 160
- 8403020014 Partial response to FOIA request for seven categories of documents re NRC regionalization program App A documents in PDR Review of remaining documents incomplete. FELTON.J M Division of Rules and Records 83/12/16 LOWENTHAL, J Nuclear Information & Resource Service 3pp. 22492-248 24X Fiche 50-000,83/12/16,8403020014
- ~-BB02220056 Summarizes decisions made on three important matters re regionalization Regionalization concept, critical skill base for regionalization of licensing & administrative efforts for regionalization are discussed DIRCKS.W J Office of the Executive Director for Operations B2/01/28 DENION.H R Office of Nuclear Reactor Regulation, Director DEYQUNG.R C Director's Office, Office of Inspection and Enforcement DAVIS.J G Office of Nuclear Material Safety & Safeguards, Director 2pp 22472 251 24X Fiche 50-000, B3/12/16, B403020014
- --8210220012 Forwards plan for FYB3-FYB5 regionalization of NRR Comments should be roceived by 821012

 DENTON.HR Office of Nuclear Reactor Regulation, Director 82/09/30 Region i. Office of Director ip 22492 313 24X Fiche 50-000.83/12/16.8403020014
- --8210220014 "FY83-FY85 Preliminary Regionalization Plan for NRR" * Office of Nuclear Reactor Regulation, Director 82/09/21 19pp 22492 314 24X Fiche 50-000,63/12/16,8403020014
- --8210220084 Forwards preliminary regionalization plan for FYB3-FYB5 Schematic presentation of scheduled milestones & activities provided in lieu of critical path presentation Revised plan & functional checklists to be submitted by 821015 DENTON.H R Dffice of Nuclear Reactor Regulation, Director 82/09/21 STELLO, V. Regional Derations & Generic Requirements 1p 22492 333 24X Fiche 50-000.83/12/16.8403020014
- -82iii90102 Forwards final regionalization plan incorporating comments from regions.per 820903 request NRR will update plan periodically DENYON.H R Office of Nuclear Reactor Regulation, Director 82/ii/01 8TELLO,V Regional Operations & Generic Requirements. ip 22493-082 24X Fiche 50-000-83/i2/16,8403020014
- -B211190103 "FYB3-FYB5 Preliminary Regionalization Plan for NRR "
 # Office of Nuclear Reactor Regulation, Director B2/10/19,
 200pp 22493 083 24X Fiche 50-000,83/12/16,8403020014
- --8212080692 Forwards FR notice amending iOCFRSD 4.informing public that communications & applications should be sent to Region 4.Ltr to Congressional committees encl DENTON.H R Office of Nuclear Reactor Regulation, Director B2/12/01 FELTON.J M Division of Rules and Records 2pp 22493 309 24X Fichs 50-000.83/iZ/16.8403020014.
- ---B212080A93 "Regional Licensing Program Fort St Vrain Generating Station." iOCFR30 final rule Amend delegates responsibility for implementing licensing program to regional administrator Draft Congressional ltrs encl
 DIRCKS.W J Office of the Executive Director for Operations
 B2/12/01 5pp 22493 311 24X Fiche, 30-000, 83/12/16, 8403020014

- --8212100130 Requests implementation of interim policy controlling requests for regional review & comment DIRCKS.W J Office of the Executive Director for Operations 82/11/29 DAVIS.J Office of Nuclear Material Bafety & Safeguards.Director DENTON.H R Office of Nuclear Reactor Regulation. Director DEYDUNG.R Director's Office. Office of Inspection and Enforcement 4pp 82493 298 24X Fichs 50-000,83/12/16.8403020014
- --B212130052 Summary of 821116 meeting w/util onsite re delegation of licensing functions to Region 4 Uniqueness of facility & need to treat aspects differently from other LWRs discussed Draft delegation of authority memo B403020014
- --8212160059 Forwards FR notice & amend to 10CFR50, reflecting delegation & assignment of certain licensing actions to Region 4 M assignment or certain licensing actions to Neglon 4 administrator DENTON, H R Office of Nuclear Reactor Regulation, Director 82/11/30 DIRCKS, W J Office of the Executive Director for Operations 7pp 22473 302 24X Fiche 50-000,83/12/16, 8403020014
- --8301i40484 Describes selected approach for transfer & maint of facility official docket files & supporting documentation to Region 4 Region 4 will assume routine document distribution Region 4 : on 821101 FUNCHES, J L Flenning & Program Analysis Staff 82/10/18 EISFNHUT, D & Division of Licensing 2pp 22492 353 24X Fiche 50-000,83/12/16,8403020014
- --B30i140470 Advises that Region 4 assumes responsibility for receipt & distribution of all facility documentation, effective B2ii01 BCOTT.R S Document Management Branch B2/10/28 Document Management Branch ip 22492 355 24% Fiche 50-000.83/12/16, B403020014
- --B30ii40494 Advises that Region 4 assumes responsibility for receipt & dissemination of incoming licensee communications for Pacility, effective 82ii0i SCOTT.R S Document Management Branch 82/10/27 GAGLIARDO, J E Division of Resident, Reactor Project & Engineering Programs ip 22492 356 24X Fiche 50-000.83/12/16.8403020014
- --B304260013 Forwards functional transfer checklist used to coordinate administrative aspects of transfers of NRC headquarters functions to regions. Subjs to prepare checklists for listed STELIO.V Regional Operations & Generic Requirements. B3/04/19 DENTON.H Office of Nuclear Reactor Regulation, Director DEVOUNG.R Director's Office. Office of Inspection and Enforcement DAVIS.J Office of Nuclear Material Safety & Bafeguards.Director 3pp 22493 337 24X Fiche 50-000, 83/12/16, B40320014 Bafeguards, Director 8403020014
- --8403020021 Informs of 821207 training & schedule review meeting re numpower reactor transfers Meeting agenda.transfer milestones & graphic schedule of transfer activities encl & SESENHUT.D O Division of Licensing 82/11/05 STAROSTECKI,R Division of Project & Resident Programs OLBHINSKI,T. Division Engineering & Operational Programs GFESSARD,R Division of Project & Resident Programs GFESSARD,R Division of Project & Resident Programs SPESSARD,R Division of Project & Resident Programs SPESSARD,R Division of Project & Resident Programs SPP 22473 281 24X Fiche 50-000.83/12/16,8403020014
- --B403020025 Identifies three major program area candidates for regionalization of regulatory functions enforcement program, emergency preparedness program & licensee performance appraisal program Comments in response to Biili2 memo.

 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 62/02/01 STELLO, V. Regional Operations & Generic Requirements 7pp 22492 253 24X Ficher 50-000, 83/12/14, 844020014
- --B403020028 Provides charter for regional coordination staff, incorporating some suggested changes Charter now in three parts according to rough time frame necessary for regions to assume various responsibilities W/o distribution list. DINNORHUE.D.J. Dffice of Administration. B2/02/17 NRC -- Detailed Affiliation Given 7pp 22492-260 24X Fiche 50-000, 83/12/16, 8403020014. NRC - No
- --B403020027 Discusses delegation & assignment to Region IV of certain licensing functions for facility.

 DIRCKB, M. J. Office of the Executive Director for Operations DENTON. HR Office of Nuclear Reactor Regulation, Director.

 OJSB-82-5 B2/ii/29 COLLINS.J T Region 4. Office of Director 9pp 22493 289 24% Fiche 50-000.83/12/i6.8403020014.

- --8403020032 Summary of 820901 initial planning meeting w/NRR, OELD, EDD.
 Region IV & Ofc of Administration re licensing transfer from
 NRR to Region IV Details encl Next meeting scheduled for
 820915
 WESSMAN, R Assistant Director for Safety Assessment 82/09/03
 IPPOLITO, T A Assistant Director for Safety Assessment 27pp
 22492 267 24X Fiche 50-000.83/12/16.8403020014
- --B403020035 Forwards final draft program guidance for FY83-85, per NUREO-0885, "NRC Policy & Planning Ouidance " Rev of current ofc operating plan, incorporating Commission Aug 1782 budget decisions & program guidance, expected by 82:030 DIRCKS, W J Gffice of the Executive Director for Operations B2/09/20 NRC No Detailed Aprillation Given 19pp 22492 294. R4X Fiche 30-000.83/12/16,8403020014
- --8403020041 Informs of forthcoming FR publication of encl amend to Commission rules in 10CFR50 re implementation of facility regionalization program Amend issued as final rule effective on 821201 W/o encl
 DENTON.H R Office of Nuclear Reactor Regulation. Director 83/12/16 UDALL.M K House of Rep. Interior & Insular Affairs ip 22493 316 24X Fiche 50-000.83/12/16.8403020014
- --8403020045 Informs of forthcoming FR publication of encl amend to Commission rules in iOCFR50 re implementation of facility regionalization program Amend issued as final rule effective on 821201 W/o encl
 DENTON, HR Office of Nuclear Reactor Regulation. Director 83/12/16 MDFFETT, T House of Rep. 90vernment Operations ip 22493 317 24X Fiche 50-000,83/12/16,8403020014
- --8403020044 Informs of forthcoming FR publication of enci amend to Commission rules in IOCFR50 re implementation of facility regionalization program Amend issued as final rule effective on G2:201 W/o enci PENTUN.H R Office of Nuclear Reactor Regulation, Director 83/12/16 07TINOERR L House of Rep. Energy & Commerce 1p 22493 310 24X Fiche 50-000.83/12/16.8403020014
- --8403020048 Imporms of forthcoming FR publication of encl amend to Commission rules in iOCFR50 re implementation of facility regionalization program Amend issued as final rule effective on 821201 W/o encl
 DENTON-H R Defice of Nuclear Reactor Regulation. Director 83/12/16 SIMPSON, A Benate, Environment & Public Works ip 22493 319 24X Fiche 50-000.83/12/16.8403020014
- --8403020049 Forwards list of major milestones re nonpower reactor regionalization actions for facilities in Regions I, IV & V Identification of individual responsibilities & appropriate action requested, per functional transfer checklists MIKAGLIA, F. J. Assistant Director Por Safety Assessment 82/10/19 BRUNNER, E. Region i, Office of Director BERNARD, H., HOEFLING, D. NRC No Detailed Affiliation Given 75pp 22492 357 24% Fiche 50-000, 83/12/16, 8403020014
- --BADJO20051 Informs that MK Udall Subcommittee on Energy & Environ marked-up & reported 1984-85 NRC authorization bill to Interior Committee for future consideration NRC authorization bill H R 2510 & 830420 amends encl KAMMERER, C Office of Congressional Affairs 83/04/20 PALLADINO, GILINSXY, AMEARNE Commissioners 11pp 22493, 326-24X Fiche 30-000, 83/12/16, 8403020014
- --BA03020052 Provides program guidance for FY83-86, developed in support of NUREG-OBB5.Issue 2, "NRC Policy & Planning Guidance 1783 " Correct ofc operating plan should be revised to incorporate encl comments DIRCKB.W J Office of the Executive Director for Operations B3/05/20 NRC No Detailed Affiliation Given 20pp 22473 340 24X Fichs 50-000.83/12/16.8403020014
- 3403020936 FOLA request for SECY-83-434 SECAL, J. L. Union of Concerned Scientists 83/12/22 FELTON, J M Division of Rules and Records 1p 22493 007
- 8403020062 Appeals danial of FOIA request for BECY-83-454, BEEOAL, J. L. Union of Concerned Scientists 84/01/12 FELTON, J.M. Division of Rules and Records ip 22475 008
- 8403020068 Responds to appeal re denial of FOIA request for SECY-83-454 Forwards document Info partially withheld (ref FOIA Exemption 5) CHILK, 8. J. Opfice of the Secretary of the Commission 84/02/15 SEEGAL, J. Union of Concerned Scientists 2pp 22495 009
- --8403020094 SECY-83-454
 Approves release of substantive info in Chairmans loge, calendars & notes, per UCS request Info deleted & withheld FITZGERALD, J. A Office of the General Counsel 83/11/04 2pp 2245 011

- B403020102 F01A request for records relevant to or generated in connection w/regulations re future of Ofc of Inspector & Auditor GARDE-O P Government Accountability Project G3/01/09 Office of Administration 2pp 22495 013
- B403020109 Responds to FDIA request for records relevant to or generated in connection w/regulations re future of Ofc of inspector & Auditor NRC has no records subj to request FELTON, J M Division of Rules and Records B4/02/27 GARDE, B F Government Accountability Project 19 22495 015
- 8403020392 FOIA request for Chilk 821019 memo to Dircks re postaccident sampling sys (NUREG-0737, Item 11 B 3) to be placed in PDR PEDRO, J NUS Corp CD-LIB-83-048 84/01/26 Division of Rules and Records ip 22491 285 24X Fiche 50-289, 84/01/26, 8403020392
- 840:3020395 Responds to FDIA request for Chilk 821019 memo to Dircks re SECY-82-384 concerning status of TM1-1 NURG-0737 items Forwards document Document also available in PDR FELION.J M Division of Rules and Records 8402/15 PEDRO,J NUS Corp 1p 22491 286 24X Fiche 50-289,84/02/15,6403020395
- B403020400 F01A request for NRC license issued to Atom Mechanical STEIN.5 S Advanced Medical Systems, Inc 84/02/01 NRC - No Detailed Affiliation Given ip 22491 279
- 8403020405 Responds to FDIA request for license issued to Atom Mechanical Forwards License 34-19854-01 dtd 020208 & Amend I dtd 820718 FELYON,J M Division of Rules and Records 84/02/15 STEIN,S 8 Advanced Medical Systems, Inc. ip 22491 280
- --8403020408 Matl/Dyproduct License 34-19854-01. authorizing possession of to-60 sealed sources for maint & repairs of Picker radiography & teletherapy devices
 QUINN.P R Division of Fuel Cycle & Material Safety 82/02/23
 200 22471 281
- --8403020412 Amend i to Mat1/Byproduct License 34-17854-01, amending license in entirety to authorize use of Co-60 sealed sources for maint & repairs of Picker radiography & teletheraphy devices, por 820312 ltr GUINN, PR Division of Fuel Cycle & Material Safety 82/07/29 Epp 22491 283
- 8403020435 Further response to FDIA request for documents re const assessment team visit to plant in Aug & Sept 1983 Forwards listed documents FELTON.J M Division of Rules and Records 84/02/22 HIATT, S L Ohio Citizens for Responsible Energy ip 22491 203 24X Fiche 50-440.84/02/22,8403020435
- --8403020441 Submits outline re const assessment team visit Related info encl # NNC ~ No Optailed Affiliation Given 83/09/29 ROHRBACHER, R Director's Office of Inspection and Enforcement 58pp 22491 204 PAX Fiche 30-440,84/02/22,8403020435
- 8403030017 FOIA request for SECY-78-369, UCID-19310, "Review of PASNY Sys Interaction Study" & records of NRC staff & consultant review of PASNY sys interaction study on Indian Point Unit 3 SHOLLY,S C Union of Concerned Scientists B3/10/20 FELTON, J M Division of Rules and Records ip 22523 097 24% Fiche 50-286, 83/10/20, 8403050017
- 8403050020 Responds to FOIA request for documents re PASNY submittal on sys interactions, repts evaluating submittal & list of repts/analyses from LLL evaluating PASNY sys interaction program Forwards App A documents
 FELTON.J M Division of Rules and Records 83/12/07 SHOLLY,8
 Union of Concerned Scientists App 22925 098 24x
 Fithe 50-000.83/12/07,8403050020
- --7912050523 Requests comments on 791012 ACRS 1tr re sys interaction Plans inhouse meeting for 791115
 SCHWINCER, A Operating Reactors Branch 1 (Pre 800428) 79/11/09 HANAUER, 8 Assistant Director for Plant Systems ZECH, 0 Division of Operating Reactors GAMMILL, W Assistant Director for Operating Reactor Projects (Pre 791030) ip 22527-146 24X Fiche 50-000, 03/12/07, 8403050020
- --8103040048 Discusses NHC requests for licensee sys interaction studies Forwards draft ltr to util documenting past advise & requesting meeting date when util can provide definition & realistic schedule for sys interaction program RUBENSTEIN.L B Assistant Director for Core & Containment Systems 81/02/10 NDVAK.T M Assistant Director for Operating Reactors 5pp 22527 175 24X Fiche 50-000.83/12/07.8403030020.

- ~~8103050718 Responds to 80093D request we possible safety advantages of interim plant power denatings on consequences resulting from control says Pariure Denatings are not recommended Only basis for selecting level is "lower is safer"

 ROSS.D F Division of Systems Integration (pre 811005) 80/12/04

 DEN1ON.H R Office of Nuclear Reactor Regulation, Director 1pp 22527 160
- --Bi04220BB; Summary of Bi0402 meeting w/util.Ebasco.LLL & BNL re status of bys interaction study ROBS.W J Operating Reactors Branch 1 Bi/04/09 Operating Reactors Branch 1 Bi/04/09 Operating Reactors Branch 1 4pp 22526 192 24X Fiche 50-000 B3/12/07.
- --8P01R20170 Discusses program on adverse sys interactions in LWRs Sys interaction inviews to be completed at four selected plants. A Indian Point Unit 3 Final guidance for interaction analyses to be based on experience w/reviews

 ERNST.M.L. Division of Safety Technology 82/01/05 TEDESCO.R.L.
 Assistant Director for Licensing 3pp 22526 242 24X

 Fichs 50-000, 83/12/07, 8403050020
- --BE08090277 Provides status rapt om NRC evaluation of licensee sys interaction study Initial guidance delayed pending further cost/benefit analysis Generac program review planned for Fall 1982 GQODWIN.E F Technical Support Branch 82/07/30 FRALEY.R F ACRS - Advisory Committee on Reactor Safeguards 2pp 22526 265 24X Fiche 50-000,83/12/07,8403050020
- --8003080270 "Preliminary Investigation of Interconnected Sys Interactions for Safety Injection Sys of Indian Point 3 " ALESSO, H.P. Lawrence Livermore Laboratory 83/03/04 NRC - No Deteiled Affiliation Given 33pp 22526 139 24X Fishe 50-000.83/12/07.8403050020
- --B305230117 Notification of B30511 meeting w/BNL & LLL in Bethesda. MD to discuss details of contract scope for application of sys interactions analysis methods to Indian Point 3 COFF MAN. F NRC No Detailed Affiliation Given 83/05/03 THADANI. A Reliability & Risk Assessment Branch 23pp 22526 288 24X Fiche 50-000,83/12/07,8403050020
- --B307270506 Notification of B30B09 follow-up meeting w/util in Bethesda, MD to discuss sys interaction at facility PCLK.F J Operating Reactors Branch i B3/07/22 VARGA, S A Operating Reactors Branch i 3pp 22525, 248 24X Fiche 50-000, B3/12/07, 8403050020
- --8308040003 Forwards proposed text for 1tr to PASNY requesting info for sys interaction methodology studies Timing for receipt of documents critical to plan for resolving Unresolved Bafety issue A-I7 Expedited transmittal requested THADANI.A C Reliability & Risk Assessment Branch 83/06/14 VARSA.S A Operating Reactors Branch 1 ip 22325 198 24X Fichs 50-000,83/12/07,8403050020
- --B309220297 Requests B30805 memo be sent to Indian Point ASLB Memo will be recommended to be sent to all recipients of Board Notification B3-i03 CONTAN.H Reliability & Risk Assessment Branch 83/08/23 MODRE.J E Office of the Executive Legal Director 2pp 22525 284
- --0310170712 Identifies info required by LLL from util for contract re sys interaction study covering off normal operating procedures & check-off procedures & lists MORRIB.C Heliability & Risk Assessment Branch FIN A-0445 B3/09/29 POLK.F J NRC - No Detailed Affiliation Given 20pp 22525 327 24% Fiche 50-000, B3/12/07, 8403050020
- --8403050023 "Diagraph-Matrix Application on Indian Point 3 for Sys Interactions," statement of work Related info entl. # NRC - No Detailed Affiliation Given FIN A-0445 20-19-30-51-5 B3/12/07 35pp 22525 111 24X Fith: 50-000,83/12/07,8403050020
- ---8403050024 Draft "Evaluation of Indian Point 3 Sys Interaction Analysis Program" # NRC - No Detailed Affiliation Given 82/02/20 7pp 29525 104 24X Fichs 30-000.83/12/07,8403050020
- ---8403050025 Informs that listed individuals will visit site during wk of 831017 Svcs requested & schedule provided Related info encl MORRIS, C Division of Systems Integration (post 811005) FIN A-0455 83/10/04 COFFMAN, F D Division of Systems Integration (post 811005) Zipp 22526 034 24X Fiche 50-000,83/12/07, 8803050020

- --B403050007 Notification of 83i121-23 site visit to obtain info re sys intoraction methodology study PCLK.P J Operating Reactors Branch I 83/10/31 VARQA.9 A Operating Reactors Branch I 2pp 22526 055 24X Fiche 50-000,83/12/07.8403050020
- --BA03050028 Discusses licensee proposed review plans addressing ACRB recommendations re sys interaction study QQLLER.K R Assistant Director for Operating Reactor Projects (Pre 791030) 77/10/21 BENDER.M ACRS Advisory Committee on Reactor Bafoguards 2pp 22525 146 24X Fiche 50-000, 83/12/07, 8403050020
- --8403050029 NUREG/CR-2050
 SYSTEMS INTERACTION EVALUATION PROCEDURE FOR APPLICATION TO
 SYSTEMS INTERACTION EVALUATION PROCEDURE FOR APPLICATION TO
 LIM.J J. ALESSO, H P., RICE, T R. Lawrence Livermore Laboratory
 FIN A-0405 UCRL-53024 81/04/30 NRC No Detailed
 Affiliation Given 50pp 22526 089 24x Fiche 50-000,83/12/07,8403050020
- ---8403050031 SECY-78-569
 Recommends obtaining Commission comments &/or approval of proposed multi-agency NOU re federal responses to radioactive contamination from specified foreign nuclear detonations
 GDSSICK.L. V Office of the Executive Director for Operations 78/11/01 24pp 22525 174
- --B403050034 Discusses 79ii15 meeting re ACRS ltr on Indian Point 3 sys interactions SCHMENCER: A Operating Reactors Branch 1 (Pre B0042B) 79/12/05 EISENHUT.D 0 Division of Operating Reactors 2pp. 22527 147 24X Fishe B0-000.83/12/07.8403050020
- --8403050035 "Review of PASNY Sys Interaction Study."

 ALESSO.H P Lawrence Livermore Laboratory KELLY, J E Science Applications, Inc. 81/06/15 9pp 22526 196 24X Fiche 50-000,83/12/07.8403050020
- --8403050037 Discusses effect of control sys failures on plant safety STOLZ.J.F Systems Interaction Branch 80/12/18 Systems Interaction Branch 10/12/18 Systems Interaction Branch 10/12/18 Systems 122527 158 24X Fiche 50-000,83/12/07.
- --8403050038 UCID-19130
 "Review of PASNY Bys Interaction Study "
 ALESSOL H P Lewrence Livermore Laboratory 82/03/01 7pp
 22526 256 24X Fiche 50-000,63/12/07,8403050020
- --8403050042 Requests update to memos discussing probability that next major accident will occur within prescribed intervals Preliminary response requested by 821115 AHEARME. J Commissioners 82/11/02 Office of Policy Evaluations 1p 22526 267
- 840305055 FOIA request for computer printouts of all NRC byproduct math licenses in Regions I & III & set of gummed peel-off mailing labels for each printout MCDONALD. DO Nuclear Pharmacy, Inc 84/01/19 FELTON, J M Division of Rules and Records 1p 22528 208
- 8403050057 Responds to FOIA request for computer printouts of all NRC byproduct matl licensees in Regions I & III & set of gummed peel-off mailing labels for each printout Forwards four printouts & two sets of gummed labels H/o encl FELTON, J M Division of Rules and Records 84/02/15 MCDONALD, D O Nuclear Pharmacy, Inc. 1p 22528 209
- 8403030058 FOIA request for records re weekly colloquia on PRA activities & safeguerds goal development SHOLLY, B. C. Union of Concerned Scientists 83/12/14 FELTON, J. M. Division of Rules and Records 2pp 22528 193
- B403030060 Partial response to FQIA request for records re weekly colloquia on PRA activities & development of safeguards goal App A documents available in PDR FELTON, J H Division of Ruies and Records 84/02/22 SHOLLY, 8 C Union of Concerned Beientists, 3pp 22528 195
- 8403050061 FOIA request for extent drafts of sections or portions of BER for plant & documents showing dissenting opinions of staff reviewers EDDLEMAN.W Eddleman, W 84/01/12 FELTON, J. Division of Rules and Records. 1p 22496 346 24X Fiche 50-400, 84/01/12, 8403050061
- 8403030064 Partial response to FOIA request for extant drafts of sections of SER for plant & documents showing dissenting opinions of staff reviewers Forwards App A documents Documents also in PDR Search for addi documents in progress FELTON, J M Division of Rules and Records 84/02/07 EDDLEMAN, W Eddleman, W App. 22496, 347 24X Fiche 50-400, 84/02/07, 8403030064

- --8203120076 Forwards request for add1 info re organic matls & spent fuel pool cleanup sys FBAR sections BENAROYA, V Chemical Engineering Branch 82/04/27 MIRAGLIA.F Licensing Branch 3 4pp 22476 351 24X Fiche 50-400, 84/02/07, 8403050064
- --B205270420 Forwards request for add1 info re fire protection program needed to complete review Info needed by B21102
 BENAROYA.V Chemical Engineering Brench B2/05/17 HIRAGLIA.F Licensing Brench 3 7pp 22497 015 24% Fiche 50-400, 84/02/07, 8403050064
- -- B207140072 Submits branch input for draft SER Input essumes that plant 20/1400/2 Submits branch input for orart SEK Input essumes that p maets design objective of App I CAMMILL.W P Meteorology & Effluent Treatment Branch 82/06/25 MIRAGLIA.F J Licensing Branch 3 57pp 22501 007 24X Fiche 50-400.84/02/07.8403050064
- --821109000B Forwards draft BER input re SRP Sections 2 5 1 on basic geology & seismic info,2 5 2 on seismology & 2 5 2 3 on SSE No capable faults exist at or around site SSE & OBE KNIOHT, J P Assistant Director for Comp & Structures Engineering (Pre 830201) 82/10/20 NOVAK, T M Assistant Director for Operating Reactors 21pp 22496,355 24% Fiche 50-400,84/02/07,8403050064
- --8211090035 Submits Core Performence Branch input to draft SER Confirmatory & open issues listed RUBENSTEIN-L S Assistant Director for Core & Plant Systems B2/10/21 NOVAK.T M Assistant Director for Licensing 2p 22497 022 24X Fichs 50-400.84/02/07.8403050064
- --B211110461 Advises that applicant has not responded to request for inforce SER items concerning oil collection sys for reactor coolant pump, alternate shutdown capability, fire protection for safe shutdown & NUREG-OBOO BENAROYA.V Chemical Engineering Branch B2/10/28 KNIGHTON.O Licensing Branch 3 ip 22497.088 24X Fiche 50-400.84/02/07.8403050064.
- --B211160112 Forwards draft BER input re FBAR Sections 2 5 4 2 5 6
 Request for addi info elso enci Site visit necessary before
 end of yr to observe as-built conditions & implementation of
 dam safety monitoring piens.
 LEAR, O. E. Hydroiogic & Geotechnical Engineering Branch 82/11/6
 KERRIOAN, J. D. Licensing Branch 3, 40pp 22497 260, 24%
 Fiche 50-400,84/02/07,8403050064 B2741709
- --82iii70249 Forwerds dreft SER input based on Auxiliary Sys Branch review of FBAR.Unresolved items listed RUBENSTEIN.L 8 Assistent Director for Core & Plant Systems. 82/11/04 NOVAK.T M Assistant Director for Licensing 145pp 22497 089 24X Fiche 50-400.84/02/07.8403050064
- --B211300017 Forwards Chemice: Engineering Branch dreft SER input re iisted sections of FSAR through Amend 2 & B20802 ltr, based on ERF (NUREO-OBSO) & NUREO-O737. Item II B 3 Addl info needed to compiete review of post-accident sampling sys.

 JOHNSTON, W V Assistant Director for Metls & Guei. Engineering (Pre B30201) B2/11/17 NOVAK.T. Assistant Director for Licensing 2ipp 22497 300 24% Fiche 50-400, 84/02/07.
- --B212160163 Forwards Structurel Engineering Branch summary of FSAR review & draft SER input.

 KNICHT.J P Assistant Director for Comp. & Structures Engineering (Pre 830201) B2/12/06, NGVAK.T M Assistent Director for Licensing 16pp 22477 346 24X Fiche: 50-400, 84/02/07, 8403050064
- ---B212160220 Forwards revised Hydrologic Engineering Section SER input Revised input superscedes previous submittal transmitted by B21014 Memo.

 LEAR, 9. E. Hydrologic & Geotechnical Engineering Branch. 82/12/03 KNIGHTON, 9. Licensing Branch 3 25pp 22497 321 24X Fiche: 50-400, B4/02/07, B403030064
- --B212300403 Forwards dreft revised SER input to SRP Bections 2 5, i. 2, 5 2 & 2, 5, 3 re geology & seismology. Revision includes applicant commitment to install & operate free-field accelerometers Accelerometers
 KNIGHT, J.P. Assistant Director for Comp. & Structures Engineering
 {Pre 830201}, 82/12/21 LAINAS.G.C Assistent Director for Licensing. 24pp. 22497.362 24X Ficher 50-400.84/02/07.8403050064.
- --B301060211 Forwards draft SER input, including one open item re possible shipments of toxic matls past plant site MULLER, D. R. Assistant Director for Environmental Technology (Pre B30201). B2/12/22. NOVAK, T.M. Assistant Director for Licensing 9pp. 22498, 024. 24X Fiche: 50-400, 84/02/07, 8403050064.

- --B301140474 Forwards Equipment Qualification Branch input for SER Suppl 5 to environ qualification of mechanical & electrical equipment
 - equipment JOHNSTON.W V Assistant Director for Matls & Qual Engineering (Pre 830201) B3/01/10 NOVAK.T M Assistant Director for Licensing 3pp 22498 033 24X Fiche 30-400,84/02/07,8403050064 Licensing 3pp
- --8301260036 Forwards Meteorology & Effluent Treatment Brench input to draft EER Assumption that draft meets 100FR50.App t objectives will be verified when fluidize bed dryer effluents calculated NUREO-0737. Item III D I i incomplete HOUSTON.R H Assistant Director for Radiation Protection 83/01/06 NOUAK, I M Assistant Director for Licensing 58pp 22500 310 24X Fiche 50-400.84/02/07.8403050064
- --B307060390 Forwards Equipment Qualification Branch SER input for environ qualification of equipment important to safety KNIGHT.J P Assistant Director for Comp & Structures Engineering (Post B30201) B3/08/26 NDVAK.T M Assistant Director for Licensing 5pp 22498 036 24X Fiche 50-400,84/02/07,8403050064
- ---8309200478 Forwards Geotechnical Engineering Section input to SER Input Based on FSAR through Amend 9 Btability of 400-ft long retaining wall still open issue LEAR, G Structural & Geotechnical Engineering Branch 83/09/02 KNIGHTON. G Licensing Branch 3 76pp 22498 188 24X Fiche 50-400.84/02/07.8403050064
- --8309210098 Forwards Power Sys Branch SER for Chapters 8-10 of FSAR 1ssues requiring resolution include containment electrical penetrations.use of load sequencer w/offsite power & frequency of testing of turbine valves RUBENBTEIN.L S Assistant Director for Core & Plant Systems 83/08/31 NOVAK.T M Assistant Director for Licensing BOpp 22478-041 24X Fiche 50-400,84/02/07.8403050064
- --8309210116 Forwards SER input for FSAR Sections 4 2.4 3.4 4.15 4 1.
 15 4 2.15 4 3.15 4 7 & 15 4 8 Confirmatory & open issues
 identified listed
 RUBENSTEIN.L 8 Assistant Director for Core & Plant Systems
 83/09/01 NOVAK.T M. Assistant Director for Licensing & Spp
 22498-119 24X Fiche 50-400.84/02/07.8403050064
- --B307220302 Forwards hydrologic engineering input to SER One open item exists re potential for intense local precipitation to flood safety-related structures Tech Spec defining anti-sediment deposit procedure required JGHNSTON, W. V. Assistant Director for Matls, Chem & Environ Technology (Post B30201) 83/09/14 NOVAN, T. M. Assistant Director for Licensing 24pp 22499 188 24X Fiche 50-400.84/02/07,8403050044
- --8309260018 Forwards SER supporting geology & seismology at facility MNIGHT, J.P. Assistent Director for Comp & Structures Engineering (Post 830201) 83/09/08 NDVAK,TM Assistant Director for Licensing. 44pp 22478 264 24X Fiche 50-400,84/02/07,8403050044
- ---B309240421 Forwards structural engineering SER sections besed on review of FSAR through Amend 7 Three open & one confirmatory items remain Resolution of open/confirmatory items will be addressed in subsequent SSER KNIGHT. J P. Assistent Director for Comp. & Structures Engineering (Post B30201) B3/09/15 NOVAK.T M. Assistant Director for Licensing. 16pp. 22479 212 24X Fiche 50-400, B4/02/07, B403050064
- ---8309240482 Forwards Auxiliary 8ys Branch SER input besed on review of all amends to FBAR up to Amend 9 & applicants 830418,0603, 30,0703,15 & 0812 responses Summary of unresolved issues to be used as basis for meeting w/applicant aiso encl RUBENSTEIN.L 8. Assistant Director for Core & Plant Bystems 83/07/14 NOVAK.T M Assistant Director for Licensing 251pp 22478:308, 24X Fichs 50-400,84/02/07,8403050064
- --B309290412 Forwards Effluent Treatment Bys Section input to SER reflecting changes in status of open items based on B30824 meeting MULLER, D.R. Assistent Director for Radiation Protection B3/09/14, NOVAK, T.M. Assistant Director for Operating Reactors 60pp 22500:190, 24X Fiche.50-400,84/02/07,8403050064.
- --B309290474 Forwards SER on plant personnel training. Util training programs for licensed reactor operators ecceptable Util inadequately addressed training of shift technical advisor (BTA) when BTA absent from STA duties RUBGELL. W. Division of Human Fectors Sefety B3/09/21 NOVAK. Assistant Director for Licensing. 2ipp. 22497 228 24% Fiche: 50-400,84/02/07,8403050064 NOVAK, T

- --8310130378 Forwards branch SER input re status of Unresolved 165ues, in response to ALAB-444 decision Issues A-45 & A-47 listed as confirmatory items rather than open items W/o encl4 KNIEL/K Generic Issues Branch ALAB-444 83/10/04 KNIGHTON, G Licensing Branch 3 26pp 22499 247 24X Fiche 50-400,84/02/07,8403050064
- --8310170095 Forwards Chemical Engineering Branch proposed license condition re TMI Item II B 3, "Post-Accident Sampling Sys "Contents of draft SER should be used for SER JOHNSTON, W V Assistant Director for Matis, Chem & Environ Technology (Post 83020i) 83/10/06 NOVAK, T M Assistant Director for Licensing 3pp 22499 279 24X Fithe 50-400,84/02/07,8403050064
- --8310190067 Forwards aerial maps as input to 821222 draft SER Item re shipment of taxic maths past plant site not resolved JOHNSTON.W V Assistant Director for Maths, Chem & Environ Technology (Post 830201) 83/10/11 NOVAX,T M Assistant Director for Licensing App 22499 331 24X Fiche 50-400,84/02/07,8403050064
- --B310200096 Forwards SER input on pump & valve operability assurance program & seismic & dynamic qualification of seismic Cattgory I mechanical & electrical equipment Addl info needod for THI Items II E 4 2 % 11 D i re reliability.

 KNIGHT-JP Assistant Director for Comp & Structures Engineering (Post B30201) B3/10/06 NOVAK,TM Assistant Director for Licensing 4pp 22499 275 24X Fiche 50-400,84/02/07,8403050064
- --8310310445 Forwards results of review of Sections 5 2 2.5 4 7.6 3 4 15 through Amend 10 of FSAR Open issues which will be summarized in later SER suppl listed HOUSTON.R W Assistant Director for Reactor Safety NOVAK.T M Assistant Director for Licensing 47pp 22499 282 24X Fithe 30-400.84/02/07.8403050064
- --B3[1100049 Informs that applicant is to submit calculation of ultimate strength capacity of containment bldg under internal pressure as resolution of SER outstanding confirmatory structural item Marked-up SER input encl

 LEAR. G Structural & Geotechnical Engineering Branch 83/10/28 KNIGISTON.0 Licensing Branch 3 3pp 22300 024 24X Fiche 50-400.04/02/07.8403050064
- --83illi0263 Informs of closeout of listed sections of 830714 SER based on new info Updated sections encl Closeout of addit open items, including NUREG-0612 info, will take place as acceptable info made available RUBENSTEIN.L S Assistant Director for Core & Plant Systems 83/10/28 NOVAK, T M Assistant Director for Licensing 49pp 22499 337 24X Fiche 50-400.84/02/07,8403050044
- --B311140004 Advises that due to need to coordinate affort w/Auxiliary Sys Branch-revised SER to be submitted on B31127 will stiil contain listed fire protection open items.

 JOHNSTON-H V Assistant Director for Matls. Chem & Environ Technology (Post 830201) B3/11/03 NGVAK, T Assistant Director for Licensing 2pp 22500 030 24X Fiche 50-400,84/02/07,8403(50064.
- ---8311160283 Forwards revised SER input on confirmatory item re ultimate strength capacity of concrete containment bldg liem 1 2503ved LFAR, 0 Structural & Gentechnical Engineering Branch. 83/11/14 KNICHTON, 0 Licensing Branch 3 Jpp 22500 047 24X Fiche 50-400, 84/02/07, 8403050064.
- --B311160367 Informs that draft BER Bection 17 acceptable except in area of items subj to 10CFR50, App B.0A program during operations phase Info re current status & acceptability of GA program encl.

 PARTION-J O. Division of GA. Bafeguards & Inspection Programs (Post B30103) B3/11/09 YOUNDRLOOD.B J Licensing Branch I 3pp 22500 027 24% Fiche 50-400.84/02/07.8403050064
- --831i290301 Forwards revised Hydrologic Engineering input to SER New Tech Spec requirement developed re watertight doors for safety-related bidgs
 JOHNGTON W V Division of Engineering Technology 83/11/10
 NOVAK, 1 M Assistant Director for Licensing 15pp 22500 032
 P4X Fiche 80-400, 84/02/07, 8403050004
- --8311290352 Updates SER re stability of retaining wall west of fuel handling bldg Based on applicant 830919 submittals, stability cannot be assured due to lack of listed info final SER update encl
 LEART, GE Hydrologic & Geotechnical Engineering Branch 83/11/18
 KNICHTON. O Licensing Branch 3 5pp 22501 049 24X
 Fiche 50-400,84/02/07.8403050064

- --0312020063 Forwards SSER resolving open item on toxic gas shipments past site Concurs w/findings & considers item closed UDHNSTON, W V Assistant Director for Matls, Chem & Environ Technology (Post 830201) 83/11/18 NOVAK, T M Assistant Director for Licensing 2pp 22501 054 24X Fiche 50-400,84/02/07,8403050064
- --B312080188 Forwards effluent treatment sys section input to SER Dpen items include method for determining releases of noble gases from methodical vacuum pumps & radioactivity monitor on discharge from syc water sys MULLER, D R Assistant Director for Radiation Protection 83/1/18 NOVAK, T M Assistant Director for Licensing 51pp 22500 139 24X Fichr 50-400,84/02/07,8403050064
- --B312120002 Lists closed out open items in SER forwarded on 830914 & sections w/romaining open items
 RUBINSTEIN.L S Assistant Director for Core & Plant Bystems
 83/11/17 NOVAK.T M Division of Licensing 88pp 22500 050
 24% Fiche 50-400.84/02/07.8403050064
- --8312120445 Forwards input to SER, consisting of emergency plan evaluation rept & responses to NUREG-0737. Items
 III A i I, III A i 2 & III A 2 re emergency preparedness
 MATTHEMS, D D Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/II/30 KN10HTON, G Licensing Branch
 3 36pp 22501 058 24X Fiche 50-400.84/02/07, B403050064
- ~~8312140429 Submits review of draft SER response to Open Item 47 on RCS vents Proposed design conforms w/criteria outlined in NUREO-0737 clarification pertaining to electrical power supplies to vent valves SRINIVASAN M Power Systems Branch B3/11/23 SHERON B Reactor Systems Branch 2pp 22501 056 24X Fiche 50-400,84/02/07,84/03050064
- --8312230278 Forwards revised SBER re fire protection Listed items remain open
 JUHNSTON.W V Assistant Director for Matls, Chem & Environ
 Technology (Post 830201) 83/12/14 NOVAK,T Assistant Director
 for Licensing 12pp 22501 074 24X Fiche 50-400.84/02/07.
 8403030044
- 8403050223 Further response to FDIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCS leakage. Forwards App C documents Bearch continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN, T J Kaye. 8cholsr. Fierman, Hays & Handler 3pp 22476 234 24X Fiche 50-000,84/02/07,8403050223
- ---8208240003 Forwards computer program developed to analyze & measure RCS leak rates, per commitment made at 820607 meeting Program calculates inventory of water in RCS & in tanks which collect coolent leakage CUNNINGHAM.L. J. Division of Engineering & Quality Assurance (Pre 830103) BE/06/15, PARR.O D. Auxiliary Systems Branch 1p 22496 272
- ---8403050232 Forwards Hewlett Packard 41C data cards containing plantspecific data for RCS leakage calculations for all Region 111 PMRs together w/complete card listing Ail PMRs in Region 111 evaluated NORELIUS, C E Division of Engineering & Technical Inspection 82/01/13 DAMER, R L Division of Engineering & Quality Assurance (Pre 830103), 7pp 22496 237 24X Fiche 50-000,84/02/07, 8403030223
- --8403050235 Advises, that cartain aspects of facility Tach Spec requirements governing RCS leakage appear to be inconsistent wistd nuclear industry practice Licensee should be requested to modify Tech Specs Related info encl NURRELIUB, C E Rogion 3, Office of Director 82/03/10 EIBENHUT, D 0 Division of Engineering lipp 22476:246 24X Ficho 50-000,84/02/07,8403050223
- ---B40305024i Forwards potentially generic issue data sheet on B00611 event re failure of BUR drywell leakage detection sys to identify significant leakage
 BRUNNER,E J Region i, Philadelphia, Office of the Director B0/07/10 JURDAN,E Region i, Philadelphia, Office of the Director LEWIG.R.C Region 2, Atlanta, Reactor Operations Nuclear Support Branch HEISHMAN.R F Region 3, Chicago: Reactor Operations Nuclear Support Branch 2pp 22496 257 24X Fiche 50-000,84/02/07,8403050223
- --8403050245 Discusses independent measurement of RCB leak rates, Proposed leak rate calculation using programmable HP41C calculator reviewed Lists advantages of having analytical equation CAPHTON, D L. Test Program Section Bi/03/i9 SNIEZEK, J. H Division of Resident & Regional Reactor Inspection 5pp. 22476 243.

- --8403050250 Forwards plant-specific data cards for facilities re reactor coolont leakage calculations, per 810702 request Add1 data cards for remaining plants will be sent shortly CREWS-J L Division of Resident, Reactor Projects & Engineering Inspection 81/09/16 BAER.R L Division of Resident & Regional Reactor Inspection 2pp 22496 268 24X Fiche 50-000.84/02/07, 84030350223
- --B403050256 Notifies that independent measurements of identified & unidentified RCS leak rates for all PMRs in Region III performed per Procedures 617278 & 617288 Insp findings summarized NORELIUS.C E Division of Engineering 82/03/08 JGRDAN,E L Division of Engineering 82/03/08 JGRDAN,E L Division of Engineering & Quality Assurance (Pre 830103) 2pp 22496 270 24X Fiche 50-000,84/02/07,8403050223
- --8403050266 Forwards revised computer program for determining RCS leak rates & draft insp procedure Revised computer program incorporates improvements based on suggestions received from field improvements listed KIRKPATRICK, D. WODDRUFF, R W Division of Engineering & Quality Assurance (Pre B30103) 82/08/27 JDRDAN, E L Division of Engineering & Quality Assurance (Pre B30103) 4pp 22496 273
- --8403050270 "RCSLK8, Program for Calculating RCS Leak Rates for PWRs "
 KIRKPATRICK, D , WOODRUFF, R W Division of Engineering & Quality
 Assurance (Pre 830103) 82/07/30 64pp 22496 277
- --B403050274 Informs that Region I attendees at 830413 & 14 RCSLK8 seminar in Dethesda are JW Chung & PC Wen, per 830304 memo Permanent custodian of computer & printer is L Bettenhausen. Chief. Test Program Section. Engineering Programs Branch MARTIN, T T Division of Engineering & Technical Programs 83/03/18 JORDAN, EL Division of Emergency Programdless & Engineering Response (Post 830103) lp 22476-341
- ---8403050279 Informs that LA Reyes designated custodian for Osborne computer & printer per 830304 memo MA Ring.PR Wohld & LA Reyes scheduled to attend seminar on application of RCSLKB program & computer use SPESBARD.R L Division of Engineering 83/03/22 JORDAN.E L Division of Emergancy Preparedness & Engineering Response (Post 830103) ip 22496 342
- 840305028B Fifth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App A & B documents also available in PDR Documents listed on App C & D located in Central Files & not available publicly FELTON.J M Division of Rules and Records 84/02/17 ANDERSON.B 1 Garvey, Schubert, Adams & Barer 9pp 22501 289 24X Fiche 50-507.84/02/17,8403050288
- --7906190142 Approves GA fire protection program description & related commitments HAASS.W P. Guality Assurance Branch 79/05/10 PARR.O D Light Water Reactors Branch 3 ip 22501 309 24X Fiche: 50-460, 84/02/17, 8403050288
- --790B010102 Forwards 790501 Haas-Bryan memo re NRR-QAB resolution of Region 5 comments re operational QA program NDLAN.F J Division of Reactor Operations Inspections 79/05/09 CREMBJ L Region 4, Dallas, Office of the Director 1p. 22501:306 24X Fiche:50-509,84/02/17,8403050288
- ---7908010232 Responds to 790405 Region 5 comments re Revision 4 to NPP88-GA-004, "Operational GA Program Description "
 Expresses intent to request util to delete Section 3 3 6 entirely.

 HAA95.W P Quality Assurance Branch 79/05/01 BRYAN, 8 E Division of Reactor Operations Inspections 1p 22501 305 24X Fiche 50-397, 84/02/17, 8403050288
- --8009240209 Discusses conversation w/R McKinney of ACR6 re dual unit plants Time should be cut in half HOLLOWAY.C J. Diffice of Hanagement and Program Analysis 79/01/22 Qiffice of Hanagement and Program Analysis lp. 22501 308. 24X Fiche 50-508.84/02/17.8403050288
- ---Boiii2010i Forwards results of contacts w/three NSBS vendors re level of GA controls applied to power operated relief valves & block valves for PMRs in operation & under const HAASBUM P. Quality Assurance Branch BO/OB/26 VOLLMER,R H Division of Engineering 5pp 22301.300
- --8110170051 Responds to 810923 FOIA 81-378 request for GA documents for WPP88. All documents re evaluation of licenses GA programs are in PDR HAABS, W P Quality Assurance Branch 81/10/05 WILSON, V H Management Analysis Branch, 2pp. 22501 310. 24X Fiche: 50-397, 84/02/17, 8403350288

- --Bi10210316 Informs of receipt of Bouchey/Adensam B10722 ltr containing util current BA program description for design & const of facilities BA program description acceptable HAASS, W.P. Quality Assurance Branch B1/10/14 TEDESCO.R L Assistant Director for Licensing 1p 22501 312 24X Ficht 30-460.84/02/17.840305028B
- --8111020578 Concludes that util & principal contractors continue to meet criteria of 10CFR50 App B Revised QA program description acceptable for design & const of facilities HAASS.W P Quality Assurance Branch 8[/10/22 TEDESCO.R L Assistant Director for Licensing Ip 22501 313 24X Fich: 50-508.04/02/17.8403050288
- --8201300236 Forwards data for fee assessment re GA Branch review of WPPSS-GA-004, "Operational GA Program Description "
 HAAS5.W P Quality Assurance Branch 82/01/14 BERKOW, H N
 Management Analysis Branch 8pp 2501 314 24X
 Fiche 30-397,84/02/17,8403050288
- 8403060085 FOIA request for documents re Equipment Qualification
 Whench request to OELD for clarification of 10CFR30 49
 HOLZMAN.P M Engineering Planning & Management, Inc. P13503 004
 83712728 FELTON.J M Division of Rules and Records Ip
 82528 213
- 8403060091 Responds to FOIA request for records prepared by NRC re request to OELD for clarification of IOCFR50 49 Forwards App A documents No add1 records located subj to request FELTON, J M Division of Rules and Records 84/01/23 HOLZMAN, P M Engineering Planning & Management, Inc. 2pp 22528 214
- ---8307120556 Requests comments on interpretations of Section 50 49 of IOCFR5D. "Environ Qualification of Electric Equipment Important to Safety for Nuclear Power Plants" VOLLHER:R H Division of Engineering 83/08/31 OLMSTEAD, W J Regulations Division 3pp 22528 216
- --B403060095 Responds to specific questions raised in 830831 request re legal interpretation of iOCFR50 49. "Environ Gualification Rule" OLMBTEAD.W J Office of the Executive Legal Director 83/10/04 VOLLMER.R H Division of Engineering 3pp 22528 219
- B403060120 FOIA request for notices of violation issued by NRC re leak rate detection or limiting conditions of operation for leakago LEVIN.L A Affiliation Not Assigned 83/12/01 NORRY,P 9 Office of Administration 2pp 22528 244
- 8403060123 Responds to FOIA request for two categories of records re RCS leakage Documents listed on App A placed in FDR FELTON.J M Division of Rules and Records 84/01/20 LEVIN.L A Affiliation Not Assigned 3pp 22528 246
- 8403060135 FOIA request for winning proposal submitted by Advanced Technology. Inc under NRC Contract NRC-33-84-380 PADEN.R C Control Data Corp 83/12/15 NRC - No Detailed Affiliation Olvon 1p 22552 213
- 840306014B Responds to FOIA request for winning proposal submitted by Advanced Technology, Inc under NRC Contract NRC-33-84-380 Forwards monproprietary version of 830815 technical proposal beat & final B31014 technical proposal FELTON, J M Division of Rules and Records NRC-33-84-380 84/01/17 PADEN, R C Control Data Corp ip 22552 214
- --8403060152 "Programming.Training.Testing.Conversion & Implementation of LPDR," best & final technical proposal # Advanced Technology, Inc. R8-ORM-83-462 83/10/14 9pp 22552 215
- ---8403060154 "Programming, Training, Testing, Conversion & Implementation of LPDR," technical proposal

 * Advanced Technology, Inc. RS-ORM-83-462 83/08/15 28pp
- 8403060158 Responds to FOIA request for 831230 FOIA request filed w/NRC by Texas Utils Generating Co (TUGC) & records requested by TUGC, Brarch revealed no documents subj to request FELTON, J M Division of Rules and Records 84/01/30 LODGE, G Dallas Morning News 1p 22528 235.
- 8403060164 FDIA request for 831230 FDIA request filed w/NRC by Texas Utils Generating Co (TUGC) & all records requested by TUGC List of FDIA requests filed by 10 listed utils also requested LDDGE, B Dallas Morning News 84/01/19 NRC ~ No Detailed Affiliation Given 1p 28528/236

- 8403040169 Responds to FOIA request for info re computer sys facilities appraised by contractor & list identifying svc contractor name.contract value & contract number Forwards incomplete updated list FELTON.J M Division of Rules and Records 84/01/31 MADDEN.C H Information Handling Services 4pp 22528 237
- 84030601/1 FOIA request for info re computer sys facilities operated for NRC Info needed in order to perform marketing study MADDEN Information Handling Services 84/01/18 NRC No Detailed Affiliation Given 3pp 22528 241
- 8403040461 Appeals denial of FOIA request for SECY-82-340 HICKEY, J P Shaw, Pittman, Potts & Troubridge 84/02/10 CHILK, S J Office of the Secretary of the Commission 1, 22332 050
- B4030&0444 FDIA request for SECY-B2-340 re current Dfc of Investigations policy on board notifications HICKEY, J P Shaw, Pittman, Potts & Trowbridge B3/11/30 GRIMSLIV, D H Division of Rules and Records ip 22552 051
- 8403060469 Responds to appeal re denial of FOIA request for SECY-B2-340 Dotument placed in PDR FELTON, J M Division of Rules and Records 84/02/17 HICKEY, J P Shaw, Fittman, Potts & Troubridge ip 22552 035
- --8209200364 SECY-82-340
 Informs of procedures to process board notifications involving allegations which may fall within investigative purview of Off of Investigations DIRCKS.W J Office of the Executive Director for Operations 82/03/17 7pp 22552 057.
- B403040486 Further response to FDIA request for documents re evaluation or review of design.const.scheduling.cost & litensing of facilities from 1977 to present Rept unavailable for Categories 1 & 2 Panel records on evaluations placed in PDR FELTON, J N Division of Rules and Records 84/01/24 ZACK, A M Barris, Sott. Denn & Deriker 2pp 22552 252 24% Fiche 50-329.84/01/24.8403060485
- 8403070078 FOIA request for V Stello 830803 memo re task group to study surveillance testing in Tech Specs & 830916 & 1004 ltrs from JJ Sheppard of Westinghouse Dumars Group to be placed in PDR Dacuments referenced in NUREG-1024 PEDRO, J NUS Corp CD-LIS-83-073 84/02/02 Division of Rules and Records ip 22541 152
- 8403070101 Responds to FDIA request for V Stello 830803 memo re task group to study surveillance testing in Tech Specs & 830916 & 1006 ltrs from JJ Sheppard to be placed in PDR Forwards documents Documents also available in PDR FELTON J M Division of Rules and Records 84/02/16 PEDRO NVS Corp 1p 22561 153
- --B30Bi50440 Requests nominations for task group to study design of surveillance testing required in Tech Specs One person familiar W/PWR lock Specs & one familiar W/BWR Tech Specs should be nominated STELLO-V Regional Operations & Generic Requirements B3/OB/O3, DENTON: H.R., MINDOUE, R.D., HELTEMES, C.J., NRC No Detailed Affiliation Given 2pp 22561 154
- --8403070106 Comments on list of Tech Spec surveillance problem Areas requested at Hestinghouse Owners Group subcommittee 830708 meeting List anci SHEPPARD. J J Hestinghouse Operating Plants Charles Group SHEPPARD. J J Carolina Power & Light Co 00-103 83/09/16 SMIEZEK. J H Regional Operations & Generic Requirements Spp 22561 136
- ~~B40307010B Comments on list of priority Tech Spec problem areas requested at Westinghouse Comers Group & NRC task force 830920 meeting List encl SHEPPARD. J J Westinghouse Operating Plants Comers Group SHEPPARD. J J Carolina Power & Light Co 80-107. 83/10/04 SMIEZEN. J H Regional Operations & Generic Requirements 3pp 22551 161
- 8403070110 Responds to FOIA request for names & addresses of various NRC matl licensees in Regions II & III Forwards two printouts furnishing into subj to request W/o encis FELTON, JM Division of Rules and Records. 84/02/22. MIKOWSKI, J. Affiliation Not Assigned ip 22564 121
- 3403070113 FDIA request for names & addresses of various NRC matl licensees in Regions II & III MIKOWSKI.J Affiliation Not Assigned 84/02/07 Office of the Executive Director for Operations 2pp. 22564 122

- 8403070213 F01A request for documents re 830919 meeting to discuss steam erosion issue in facility proceeding & TH Novak 830825 mamo on steam erosion issue H1ATT, S L Obio Citizens for Responsible Energy 83/12/08 FELTON, J M Division of Rules and Records 1p 22563 219 24x Fiche 50-440,83/12/08,8403070213
- B403070215 Responds to FOIA request for documents re 830919 meeting to discuss steam erosion issue in facility proceeding & TM Novak 030825 memo on subj Forwards App A documents Documents 4 & 5 withheld (ref FDIA Exemption 5) FELTON, J M Division of Rules and Records 84/01/23 HIATT, 8 Ohio Citizens for Responsible Energy 3pp 22363 220 24X Fiche 50-440,84/01/23.8403070215
- --B306220210 Forwards draft staff position on Contention 15 re steam erosion Applicant has not demonstrated capability to prevent or discover effects of steam erosion Comments requested PARR.O D Auxiliary Systems Branch 83/05/14 LIAW.B Mechanical Engineering Branch 1p 22563 226 24X Fiche 50-440,64/01/23,8403070215
- --B403070221 Requests confirmation on lead responsibilities for finalizing NRC position re steam erosion contention issue Responsibility should be shared by Mechanica) Engineering Branch & Metrorology & Effluent Treatment Branch NOVAK.T M Assistant Director for Licensing B3/08/25 MNICHT.J.P. Assistant Director for Comp & Btructures Engineering (Post B30201) J0HNSTON.M.V Assistant Director for Matls. Chem & Environ Technology (Post B30201) 2pp 22563 224 24% Fiche 50-440,84/01/23,8403070215
- 8403070226 FDIA request for repts re results of investigation of failed reactor vessel halddown studs on Unit 1 reactor vessel PLATO, F D Kohl, Secrest, Wardle, Lynch, Clark & Mampton 84/01/23 KEPPLER, J O Region 3, Office of Director 2pp 22364 147 24X Fiche DO-329.84/01/23,8403070226
- 8403070279 Partial response to FGIA request for repts re NRC investigation of failure of reactor vessel holddown studs on Unit 1 reactor vessel Forwards App A & B documents FELTON, J M Division of Rules end Records 84/02/23 PLATO, E D Kohl. Secrest, Wardle, Lynch, Clark & Hampton App 22364 149 24X Fiche 50-327.84/02/23,8403070229
- --B403070234 PNO-III-066 on 791217, second reactor vessel anchor bolt found broken Teledyne Engineering Svc currently performing tests on bolt mati Results expected in near future KNDP, R C Region 3, Chicago, Office of the Director 79/12/20 3pp 22564 155
- --8403070340 Ack receipt of 791214 interim rept re broken anchor bolt in reactor vessel support skirt flange FIORELLI, G. Region S. Chicago. Office of the Director 79/12/26 HOMELL, B. H. Consumers Power Co. 10pp. 22564 158 24X Fiche 50-329, 84/02/23, 8403070229
- --8403070343 Forwards IE Insp Repts 50-329/80-12 & 50-330/80-13 on 800301-31 No nencompliance noted Major areas inspected. ezam of procedures & representative records, observations & interviews w/personnel W/o encl FIDRELLI.O Region 3. Chicago, Office of the Director E0/05/19 HOMELLS H. Consumers Power Co. 2pp. 22564 170 24X Fiche 50-329,84/02/23,8403070229
- --B403070345 Recommends order be issued to util requiring action to correct unacceptable anchor bolts at facility Draft ltr & order encl KEPPLER, J O Region 3, Chicago, Office of the Director 60/06/27 THOMPRON, D Executive Officer for Operations Support 3App 22544 172 24X Fiche 50-329,84/02/23,8403070229
- --@4030/0349 Forwards depositions re preservice failure of reactor vassel studs utilized at Unit 1.Related info encl LEMIS.8 H Region 3. Office of Director 84/01/06 BERKOYTY.D M Office of the General Counsel 52pp 22564.264 24X Fiche 50-029.84/02/23.8403070229.
- --8403070351 Responds to 830901 1tr & forwards IE Investigation Repts 50-329/80-13 & 50-330/80-14 W/a encl LEMIS.8 H Region 3. Office of Director 83/09/20 MYERS.T F Garan. Lucow, Miller, Seward, Cooper & Becker ip 22564.263 24X Fiche 50-329.84/02/23.8403070229
- 8403080003 FOIA request for 10 contractor repts on generic modeling for vital area & safeguards analysis referenced in NUREO/CR-3121 SHOLLY, 8 C Union of Concerned Scientists 84/01/10 FELTON, J M Division of Rules and Records 2pp 22578 001.

ī

- 8403080005 Responds to FOIA request for 10 contractor repts to be placed in PDR Forwards nine specified repts Rept identified in Item 9 of request not yet published Rept expected to be published within next 3 months FELTON.J M Division of Rules and Records 84/02/24 SHOLLY, S C Union of Concerned Scientists 1p 22578 003
- --B403080006 BANDB2-7220

 "Technical Basis for & Description of Function Level Generic Fault Trees for LWR Plants." contractor rept
 FINN, S . HORTON, W Science Applications, Inc FIN A-1060
 SAI01580-399LJ B3/03/31 Division of Facility Operations 200pp 22578 004
- --8403080008 BANDBR-7032 VOI
 Vol 1 to "Generic Modeling Approach for Major Components in
 LWRs Fault Trees for Generic Modeling Approach," contractor
 rept
 HORTON, W., FINN, S. Science Applications, Inc. FIN A-1060
 SAI01381-309LJ 83/03/31 Division of Facility Operations
 234pp 22578 205
- --8403080010 SANDB2-7219 VOI
 Vol 1 to "Generic Modeling Approach for Fluid Sys Found in
 LMRs Fault Trees for Generic Modeling Approach," contractor
 rept
 FINN,S , HORTON,W Science Applications, Inc FIN A-1060
 SAI01381-410LJ 83/03/31 Division of Facility Operations
 64pp 22579 079
- --B4030BD012 SANDB2-7217 VO2
 Vol 2 to "Generic Modeling Approach for Fluid Sys in LWRs.
 Questionnaires for Application of Generic Modeling
 Approach," contractor rept
 FINN.B, HORTON,W Science Applications, Inc FIN A-1040
 SAI01381-411LJ B3/03/31 Division of Facility Operations
 133pp 22579 144
- --B4030B0017 BANDB2-7032 VO2
 Vol 2 to "Generic Modeling Approach for Major Components in LWRs Questionnaires for Application of Generic Modeling Approach." contractor rept
 HORTUN.W., FINN.S Science Applications, Inc FIN A-1060
 BA101381-30B1, BB3/03/31 Division of Facility Operations 125pp 22579 277
- ---8403080019 SANDB2-7219 VO3
 Vol 3 to "Generic Modeling Approach for Fluid Sys in LWRs
 Instruction Sheats for Application of Generic Modeling
 Approach," contractor rept
 FINN S , HORTON, W Science Applications, Inc FIN A-1060
 SAI01381-412LJ 83/03/31 Division of Facility Operations
 165pp 22580-042
- ---8403080025 SAND82-7032 V03
 Vol 3 to "Generic Modeling Approach for Major Components in LWRs: Instruction Sheets for Application of Generic Modeling Approach," contractor rept
 HORTON, W., FINN, 8 Science Applications, Inc. FIN A-1040
 SAI01381-293LJ, 83/03/31 Division of Facility Operations
 215pp 22580 207
- ---B403080029 SANDB2-1457
 "Computer Automation of Generic Modeling Approach for Major Components in LWRs."
 DANIEL, B L , HIGGINS, B, J , HILL, M S Sandia Laboratories FIN A-1060 B3/05/31 Division of Facility Operations 120pp 22581, 062
- 8403080016 Further response to FOIA request for lists & records re Go-60 licensees, Forwards App A documents, per Item 3 of request Portions of Documents 2 through 5 of App B deleted (ref FOIA Exemptions 6 & 7) FELTON, J M Division of Rules and Records 84/01/11, COMIE, D. J Bouck, Holloway, Kiernan & Casey. 5pp 22576 294
- --B005010203 PNO-III-B0-60 on B00316,25 mCi Co-60 sesied source under License 12-13720-01 fell into coke hopper Source believed to be in pile of coke in facility yard, on barge heading for Chicago or in freight car bound for Shawinigan Quebec. SCHULTZ.H. H., DAVIB,A B Region 3. Chicago, Office of the Director B0/03/25 ip 22576 299
- --B005280975 Forwards IE Insp Rept 30-04297/B0-01 on 800327 of activities under License 12-13720-01 No noncompliance noted DAVIS, A B. Region 3. Chicago, Fuel Facility & Materials Safety Branch B0/04/17, Clark Gil & Refining Corp 2pp 22574 300.
- ---B005280798 IE Insp Rept 30-04297/80-01 on 800327 No noncompliance noted. Major areas inspected, attempt was made to relocate 6 mGI scaled source level indicator lost by licensee ADAM. W. J. Region 3. Chicago. Office of the Director PAPERIELLO, C. J. Region 3. Chicago. Puel Facility & Materials Safety Branch B0/04/14 Spp 22576 302

- --8010230503 Forwards personnel exposures measured from recunst of 800925 incident involving jamming of Co-60 teletherapy source Corrective actions procedures reviewed w/personnel & new colbalt source installed LIBICE, W E , IGNATON 8 B Ft Hamilton-Hughes Memorial Hosp Center, Hamilton OH 80/10/17 WEIL, C Region 3, Chicago, Office of the Director 6pp 22577 044
- --B10129070B Responds to B10112 telcon re B10121 meeting w/WE Lister & Kereiakes to discuss proposed corrective actions & NRC enforcement options for B00920 investigation KEPPLER.J O Region 3. Chicago. Office of the Director B1/01/16 LISTER.W E Ft Hamilton-Hughes Memorial Hosp Center, Hamilton, OH 1p 22576 319
- --BI0224003B Forwards IE Insp Rept 30-00143/BI-02 on BI0120 of activities under License 12-00912-03 No noncompliance noted FIBHCR.W L Region 3, Chicago. Office of the Director B1/02/09 SISTER JEANINE Oak Park Hosp., Oak Park, IL 1p 22577 123
- --Bi02240066 IE Insp Rept 30-00143/81-02 on 810120 No noncompliance noted Major areas inspected re-enactment of emergency procedures in response to Bi013 teletherapy unit malfunction BUR91N.R E , BCRLTZ.W H Region 3, Chicago, Office of the Director 81/02/03 App 22577 1P4
- --B403080033 Notifies that on B00325.25 mCl of Co-60 missing from north cok: drum at Wood River Refinery in Hartford.lL Chronological events listed Diagrams of coke drums enci # Clark Oil & Refining Corp 80/05/12 SCHULT2.8 NRC No Detailed Affiliation Oiven 7pp 22576 307
- --8403080038 informs of 801002 talcon w/W Lister of Fort Hamilton-Hughes Medical Ctr re agreement on Immediate action ltr Lister appred to items in ltr No final determination made of enforcement action DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/10/03 Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/10/03 Region 3. Chicago, Fuel Facility & Materials
- --84030B0044 Ack receipt of B01017 ltr informing NRC of personnel exposures measured during reconstruction of incident on B00925 & advising NRC of courses of action investigation rept re incident will be issued within next 10 wks KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/11/02 LISTER, W E Ft Hamilton-Hughes Memorial Hosp Center, Hamilton-DH ip 22976 317
- --B4030B004B Notification of Bi012i meeting w/licensee in Glen Ellyn.IL to discuss NRC findings during recent insp of teletherapy incident & possible enforcement options

 * Rtgion 3, Chicago, Office of the Director B1/01/13 Region 3, Chicago, Office of the Director 1p 22576 318
- --84030B0057 Discusses 800930 & 1003 investigation re 800925 incident concerning unplanned radiation exposure Forwards draft itr to licensee w/notice of violation & draft investigation rept Related info enc.

 KEPPLER. J O Region 3. Chicago. Office of the Director Bi/01/22 THOMPSON. D Director's Office. Office of Inspection and Enforcement 78pp 22576 320
- --B403080101 Forwards IE Investigation Regt 30-13020/81-01 on 800930,1003 & Bi0121 Violation noted

 KEPPLER J 9 Region 3, Chicago, Office of the Director (B1/03/01)

 B1/03/05 LISTER W E Ft Hamilton-Hughes Memorial Hosp Center,

 Hamilton, OH ip 22577 054
- --8403080108 IE investigation Rept 30-13020/81-01 on 800930,1003 & B10121 Violations noted failure to notify responsible personnel of equipment failure.per License Condition 23 & servicing of teletherapy unit at 5-yr intervals WELL, C H . ADAM.W J . BURGIN.R E Region 3, Chicago, Office of the Director (81/03/01) 81/03/03 20pp 22577 055
- --B4030BDii3 Requests 7-day extension to respond to 810303 ltr & notices of violation & proposed imposition of civil penalties RULLMAN, B D Millikin & Fitton RULLMAN, B D Ft Hamilton-Hughes Memorial Hosp Center, Hamilton, OH EA-Bi-i9 81/03/25 SIELLO, V NRC No Detailed Affiliation Given ip 22577 084
- ---84030B0120 Notifies that extension until 810406 granted for submitting response to 810303 natices of violation & proposed imposition of civil penalties.per 810325 request THOMPSON.D Director's Office. Deflice of Inspection and Enforcement 81703/31 RULLMAN.S.D Millikin & Fitton RULLMAN.S.D, Ft Hamilton-Hughes Memorial Hosp Center, Hamilton.OH ip 22577 085

- --B4030B0127 Discusses licensee 810403 response & IE investigation rept Civil penalties should be remitted due to insufficient info incident should be classified under Severity Level IV Braft itr & draft notice of violation enci KCPPLER, J @ Region 3. Chicago, Office of the Director (81/03/01) 81/03/27 THOMPSON. D Director's Office of Inspection and Enforcement 20pp 22577 086
- --B403080162 PND-I-81-033A on B10307, special insp conducted to determine extent of Co-60 contamination resulting from leaking radiography source Contaminated clothing found at employee residence will be treated as radioaste COSTELLO.F Director's Diffice, Office of Inspection and Enforcement KINNEMAN, J. Region i, Philadelphie, Diffice of the Director (81/03/01) B1/03/09 ip 22577 i27
- --B403080170 PNA-81-006 on B10714. Louisiana Nuclear Energy Div notified NRC of radiography incident occurring on barge located less than 3 miles offshore Barge captain & radiographer exposed to 11 Ci Co-60 Medical attention obtained DUDA:R J Region 4. Dalias, Office of the Director (81/03/01) 81/07/21 2pp 22577 130
- --B4030B0175 Confirms B20416 telephone agreement that EL Saenger will assist NRC by serving as medical consultant remisadministration Findings & conclusions requested within 30 days of completion of advisory efforts KEPPLER.J G Region 3, Office of Director B2/04/23 SAENGER.E & Affiliation Not Assigned 2pp 20577 143
- --8403080iBO Submits chronological sequence of events re mispiacod radiological source.per B20112 telson Related info encl BRONN.R T Affiliation Not Assigned B2/01/13 HIDEMAN.D NRC -No Detailed Affiliation Given 12pp 22577 i&6
- ---8403080i86 Forwards internal investigation documents prepared by emergency sycs & disaster agency as result of temporary ioso of Co-60 source.per request Documents should be kept confidential WISC.D L Illinois, State of 82/01/19 WIEDEMAN.D Region 3. Office of Director 17pp 22577 178
- --B4030B0i9) Discusses 8304i1 & 12 special insp performed of licensee program in response to allegations made by anonymous caller Five violations identified Special insp rept written & enforcement itr will be sent to licensee HILLERJ R Region 3. Office of Director 83/05/03 Region 3. Office of Director 2pp 22577 238
- --8403080194 iE Special Safety Insp Rept 30-04315/83-01 on 830411-12 Violations noted unauthorized individuals removed source & holder from coke drum II & five Victoreen pocket type radiation dosimeters not calibr since gurchase on 820830 * Region 3. Office of Director 83/04/15 i9pp 22577 244
- --B40308019B Forwards draft ltr to licensee w/notice of violation & proposed imposition of civil penalties & IE insp Rept 30-00418/82-01 on BE0419 for review & concurrence Justifications listed for reducing proposed civil penalty MARNICK, R F Region 3, Office of Director 82/06/23 LIFBFRMAN.J Director's Office, Office of Inspection and Enforcement 10pp 22577 286
- --B403080202 IE Insp Rept 30-004iB/B2-0i on 820419 Violation noted individual in restricted area exposed in excess of premissible ijmits & 24 h notification of incident not made BUROIN.R E , BRENIAMSKI, D J Region 3, Office of Director 82/06/16 iOpp 22577 276
- --0403080204 Submits rept re 810622 incident concerning Co-60 medical teletherapy unit. Individual film badge showed dosage of 9 710 rems whole body Person notified & advised to avoid radiation exposure for 6 months Related info encl TiDABACK, A.J. Blanchard Valley Hosp Findlay, OH B2/04/06 SRENIAMSX1.D Region 3. Office of Director 12pp 22377 306
- --B4030B0209 Discusses IE Insp Rept 30-00394/82-01 on 820413 & 12 & forwards notice of violation NORELIUS, C E Region S, Office of Director 82/07/21 KRIEGER, J Cleveland Clinic, Cleveland, GH 2pp 22577 31B
- ~~84030802il Notice of violation from insp on 820413-14 NORELIUS.C C Division of Emergency Preparedness & Operational Support 82/07/21 ip 22577 320
- --B403080215 IE imag Rept 30-00394/82-01 on 820413-14 Violation noted failure to perform full calibr using dosimetry sys calibr by NBB or by regional calibr lab MULLAUER, JR, MADERA, JR, SRENIAWSKI, DJ, Region 3, Office of Director 82/07/09 26pg 22577 DR1

- --8403080217 Submits questions,per 820420 telcon re misadministration Info will be kept confidential SACNGER,E L NRC - No Detailed Affiliation Given 82/04/23 RODRIGUES,A Cleveland Clinic, Cleveland, OH 1p 22577 347
- B4030B007: FDIA request for documents re NRC internal procedures or guidance for evaluating new generic requirements & for use of cost-benefit or value-indpact analysis & CROR guidance or procedures on cost-benefit or value-impact analysis WEJSS,E R Union of Concerned Scientists 83/12/21 FELTON,J M Division of Rules and Records 1p 22984 114
- 84030B0023 FDIA request for documents re NRC & Radiation Technology Inc. located in Rockaway.NJ Documents should include all insp correspondence from 1976 to present enforcement info from 1977 & 78 & hearing transcript re 1976 incident KASSJD E Affiliation Not Assigned 83/11/22 Office of Administration 1p 22582 OOi
- B4030B0027 Responds to FDIA request for documents re NRC & Radiation Technology inc.iocated in Rockaway, NJ Forwards App A documents FELTON, J M Division of Rules and Records 83/12/30 KASS, D E Affiliation Not Assigned 3pp 22582 002
- --8403080032 Forwards IE Insp Repts 30-07022/77-03 & 30-07022/77-04 on 770923-1014 Violation noted failure to make immediate rept of personnel overexposure Item of noncompliance will not be included in notice of violation GRILR, B H Region 1, Philadelphia, Office of the Director 78/01/06 WELT, M A Radiation Technology, Inc. 2pp 22582 225
- --B403080036 Initial prelicessing visit insp rept on 70:120 EPØTEIN.E Atomic Energy Commission 70/11/22 10pp, 22582 005
- --8403080040 Submits clarifications & corrections to items found in IE
 Insp Repts 30-07022/77-03 & 30-07022/77-04 Request for
 meeting w/appropriate NRC personnel reliterated
 WEIT,M A Radiation Technology, Inc 78/01/18 GRIER,B H
 Region 1, Philadeiphia, Office of the Director 5pp 22582 227
- --8403080043 Forwards IE Insp Rept 30-07022/77-06 on 771220-22 No violations noted GRIER.B H. Region i, Philadelphia, Office of the Director 78/01/19 WELTM A. Radiation Technology, Inc. 3pp. 22582 23
- --8403080045 Discusses inspector evaluation of License 29-13613-01 License properly categorized as E-lif Extension of 12 months in reinse frequency recommended Next insp will be scheduled in Apr 1974 EPSTEINE Atomic Energy Commission 71/05/06 NELSON, PR Atomic Energy Commission 1p 22582 015
- ---B4030B0046 Responds to NRC 770314 ltr re violations noted in IE insp of License 29-12613-02 Corrective actions pool water will be sampled on routine basis & NRC will be notified if reading equois or exceeds 0 05 uc/100 ml Meeting w/NRC requested HELT.M A Radiation Technology, Inc. 77/04/01 VDLGENAU.E Office of Inspection & Enforcement, Office of the Director Rpp 22587 105
- --8403080049 IE insprept of 710427 initial insp of License 29-13613-01 Noncompliance noted sealed sources not leak tested at required intervals EPSTIN.E., NELBON, P.R. Atomic Energy Commission 71/05/06 5pp 22582 016
- --8403080050 Draft IE Insp Rept 30-07022/77-06 on 771220-22 No violations noted Major areas inspected review of nonroutine procedures for svc irradiator maint following licensee notification of planned shutdown on 771219
 SLOBODIEN.M J, GLENN, J E. Region I, Philadelphia, Office of the Director NCLEON, P. R. Region I, Philadelphia, Fuel Facility & Materials Safety Branch 78/01/18 8pp 22582 235
- --B403080051 Discusses 770419 meeting & 770420 telcon Licensee agrees to remove leaking Co-60 sources from storage pool & transfer source to authorized licenses for disposal by 770601 Meeting summary & attendance list encl
 O'REILLY, J P Region 1, Philadelphia, Office of the Director 77/05/05 WELT, M A Radiation Technology, Inc. 4pp. 22582 107
- --8403080054 Discusses insp of License 29-13613-01 on 710427 & forwards notice of violation KIRKMAN:R W Atomic Energy Commission 71/05/07 WELT.M Radiation Technology. Inc ip 22582-021
- --8403080055 Ack receipt of 780109 ltr re IE Insp Rept 30-07022/77-06 Clarification provided re comments raised by inspectors, HELT.M A Radiation Technology, Inc 78/01/23 ORIER, B H Region 1, Philadelphia, Office of the Director 4pp 22582 243

- --8403080056 Forwards IE Insp Rept 30-07022/77-01 on 770527 No violations noted O'REJLLY, J P Region i. Philadelphia, Office of the Director 77/06/10 WELT, M A Radiation Technology, Inc 2pp 22582 111
- --8403080098 Notice of violation from insp on 710427 Violation noted Sr-90 swaled sources not tested for leakage &/or removable contamination at 6-month intervals EPSTEIN,E Atomic Energy Commission 71/05/06 ip 22582 022
- --B4030B0059 Clarifies statements contained in 780ii8 ltr re repts written following insps in Sept & Oct 1977 Clarifications listed GRIER, B H Region i, Philadelphia, Office of the Director 78/03/20 WELT, M A Radiation Technology, Inc 5pp 22582 247
- --B4030B0060 IE Insp Rept 30-07022/77-01 on 770527 No violations noted Major areas inspected encapsulation of sealed sources; interviews whypersonnel, measurements & observations of loading of sources to be sent for reencepsulation GLENN, J. Region 1. Philadelphia, Office of the Director 77/06/02 12pp 22582 113
- --8403080064 Responds to NRC 710507 ltr re violations noted in insp of License 29-13613-01 Corrective actions two Sr-90 scaled sources wiped for contamination Wipe samples sent to lab for analysis Removable contamination iess than 05 uCi HARAM.8 A Radiation Technology, Inc 71/05/14 KIRXMAN,R W Atomic Energy Commission ip 22582 023
- --8403080069 Ack receipt of 710514 ltr informing NRC of steps taken to correct violation noted in insp of License 29-13613-01 on 710427 Corrective actions will be reviewed during next insp KIRKMAN.R W Atomic Energy Commission 71/05/27 HARAM.S A Radiation Technology. Inc. 2pp. 22582 024
- ---8403080070 IE insp Rept 30-07022/77-02 on 770627-28 No violation noted Major areas inspected disposal of leaking scaled sources, Interviews w/personnel, measurements & observations CLENN, J E , MCCLINTOCK, R Region J. Phliadelphia, Office of the Director 77/07/05 5pp 22582 127
- --8403080072 Responds to 780123 ltr re inspector access to licensee facilities Difficulties encountered during insp on 771220 Procedure should be developed for inspectors to receive training, in order to qualify for unescorted access GRIER.D H Region l. Philadelphia. Office of the Director 78/03/29 WELT, M A Radiation Technology, Inc. 3pp 22522 252
- --8403080074 Discusses insp of License 29-13613-02 on 720227 & forwards natice of violation Response requested within 20 deys O'REJLLY, J P Region 2, Atlanta, Office of the Director 72/04/12, WELT, M Radiation Technology, Inc ip 22582:026
- --8403080078 Informs of possible misstetement in second paragraph of NRC 780329 Itr rs inspector access to licensee facilities NRC suggestion to qualify inspector access w/o escort acceptable WELT.M A Radiation Technology, Inc. 78/03/31 GRIER.B H Region i. Philadelphia, Office of the Director 2pp. 22582 255
- --8403080079 Forwards IE Investigation Rept 30-07022/76-02 on 761022-1104 Violation noted ORIER,B.H Region i, Philadelphia, Office of the Director. 77/09/14. WELT,M.A. Radiation Technology, Inc. 2pp. 22582-142
- --8403080082 Notice of violation from insp on 720229, Violations noted rept showing results of rediation survey not sent to Metis Branch Matis Licensing Brench & Region I. Div of Compliance within 30 days following installation of sources * Region 2, Atlenta, Office of the Director. 72/04/12 ip
- --B4030B0084 Responds to NRC 7B0320 ltr re issues reised in prior correspondence between ofc & vendor.
 WELT,M A. Radiation Technology, Inc. 7B/04/03 CRIER,B K
 Ragion I. Philadelphia. Office of the Director 4pp 22582 257

- --0403080087 IE Investigation Rept 30-07022/76-02 on 761022-1104 Violations noted two employees carried film inside of billfolds rather than wearing designed film badge holder & radioactive matl located in unrestricted area SMITHIR H. OLENN. JE, MCCLINTOCK, R. O. Region i, Philadelphia. Office of the Director 76/12/13 32pp 22582 144
- --8403080089 Responds to NRC 720412 ltr re violations noted in insp of License 29-13613-02 Corrective actions results of radiation survey sent to AEC on 720306 W/o encl WELT,M A Radiation Technology, Inc 72/04/18 O'REILLY,J P Atomic Energy Commission 1p 82582 028
- ---84030BD092 Forwards order immediately suspending license due to overexposure reported on 770927 VDLGCNAU-F Defice of Inspection & Enforcement, Defice of the Director 77/09/23 WELT-M A Radiation Technology, Inc. ip 29582
- --B4030B0095 Order immediately suspending license Licensee has not taken adequate actions to comply w/Commission rules, regulations & license conditions

 VCH OENAULE OFFIce of Inspection & Enforcement, Defice of the Director 77/09/23 Radiation Technology, Inc. 4pp 22982 177
- --8403080099 IE Insp Rept 30-07022/77-03 on 770923 & 27 Violations noted overoxposure of one individual to 150-300 rem & failure to evaluate hazarda associated w/operating irradiator w/maze door interlock rendered inoperable NCCLINTOCK.R O. SLODODIEN.M J. Region i. Philadelphia, Office of the Director NELSON,P R. Region i. Philadelphia, Fuel Facility & Haterials Safety Branch 77/10/20 .16pp 22582 181
- --8403080102 iE Insp Rept 30-07022/77-04 on 771005.07.10 & 14 No violation noted Major areas inspected licenses actions in response to Commission order suspending license & subsequent mode & observation of procedures allowed by order SLORODIEN.M J . KINNEMAN.J D Region 1. Philadeiphia. Office of the Director GLERN.J E Region 1. Philadeiphia, Fuel Facility & Materials Safety Branch 77/10/21 9pp 22582 197
- --8403080:107 Forwards 1E Insp Rept 30-07022/77-05 on 77:107 & 08 No violation noted GRIER, B H Region i, Philadelphia. Office of the Director 77/11/22 WELT, M A Radiation Tochnology, inc 2pp 22582 206
- --8403080109 IE Insp Rept 30-07022/77-05 on 771107-08 No violation noted Major areas inspected licensee actions since lifting of order suspending license on 771014; radiation & contamination surveys & safety review committee actions 8LOBODIEN.M J. COSTELLO,F Region I, Philadelphia, Office of the Director NELSON.P R Region I, Philadelphia, Fuel Facility & Materiais Safety Granch 77/11/18 4pp 22582 208
- --B4030B0iii Submits results of radiation survey conducted on 71072i Results listed Results not sent to AEC due to lack of radiation detected in vicinity of new installation HARMIS A Radiation Technology, Inc. 72/03/04 HENDRIX, J Atomic Energy Commission ip 22582 029
- --8403080112 Discusses IE insp of License 29-13613-02 on 770923-1014 & forwards notice of violation
 VDL-9ENAU.E Office of Inspection & Enforcement, Office of the Director 77/12/30 WELT.M A Radiation Technology, inc 2pp 22582 212
- ~-B4030B0117 Notice of violation from insp on 770923 & 27 Violations noted individual entered in-air irradiator white nominal 500,000 Ci Co-60 source exposed & mare door interlock rendered inoperable, permitting access to irradiation room * Office of Inspection & Enforcement, Office of the Director 77/12/30 3pp 22582 214
- --8403080121 Ack receipt of 720418 ltr informing NRC of steps taken to correct violations noted in insp of License 29-13513-02 Corrective actions will be verified during next insp Field notes from insp encl
 O'REILLY.J P Atomic Energy Commission 72/04/25 WELT.M
 Rediation Technology, Inc 7pp 22582 030
- --B403080122 Forwards order rescinding order suspending license, in response to 771012 & 13 ltrs. Add1 enforcement correspondence re events & inspection 770923-1014 will be sent VOLCENAU,E Office of Inspection & Enforcement, Office of the Director B3/12/30 HELT. HA Radiation Technology, Inc. ip 22582: 217
- --B4030B0123 Discusses insp of License 29-13613-02 on 741212 & forwards 'notice of violation NELSON,P R Region i, Philadelphia, Office of the Director 75/01/23 WELT.M A Radiation Technology, Inc. 2pp 22582 037

- --8403080124 Agrees to meet at mutually convenient time for addl discussion.per 760403 request Neeting on 780321 did not provide adequate basis for negotiating settlement of pending civil penalty case JORDAN.E L. Executive Officer for Operations Support 78/04/11 HELT.M A. Radiation Technology. Inc. 1p 22582 261
- --8403080129 Notice of violation from insp on 741212 Violations noted byproduct mati used by unauthorized personnel & water losses in Co-60 storage pools not routinely made up * Region 1, Philadelphia, Office of the Director 75/01/23 ip 22502 039
- --8403080132 Order rescinding order Suspending license Licensee organized safety review committee & hired new radiation safety officer VOLCENAU.E Office of Inspection & Enforcement, Office of the Director 77/10/11 Radiation Technology. Inc 4pp 22582 218
- --8403080133 IE Insp Rept 30-07022/79-01 on 770323 No violation noted Major areas inspected selective exams of procedures & representative records interviews w/personnel.measurements & observations SLOBODIEN.d. COSTELLO, F. Region 1. Philadelphia, Office of the Director 79/03/23 10pp 22582 330
- --B403080134 Responds to NRC 750123 itr re violations noted in insp of License 29-13613-02 Corrective actions license amend will be requested to specify addl persons as designated operators. HARANS A Radiation Technology. Inc 75/02/14 NELSON.P R Region 1. Philadelphia, Office of the Director ip 22582 040
- --B403080137 Responds to 771230 ltr re order to suspend license Suspension of license for 3 wks Unjustified Charges of gross Lapses of mgt control unsubstantiated WELT, M A Radiation Technology, Inc 70/01/06 VOLGENAU, E Diffice of Inspection & Enforcement, Office of the Director 3pp 22502 222
- --8403080139 Ack receipt of 750214 ltr informing NRC of steps taken to correct violations noted in imap of License 29-13613-02 Request for license amend should be expedited NELSON,P R. Atomic Energy Commission 75/02/27 WELT,M A Radiation Technology, Inc. 2pp 22582 041
- --8403080144 Discusses IE Insp Repts 30-05458/75-01 & 30-07022/75-01 on 751023 & forwards notice of violation NELSON-P R Region i, Philadelphia, Fuel Facility & Materials Safety Branch 75/11/11 WELT, M A Radiation Technology, Inc 2pp 22592 043
- --840:30B0147 Notice of violation from insp on 76:1027 & 1:01 Violations noted failure to rept 75:09:1 leak test requits to NRC & failure to notify Region I of incident involving cobalt activity in R&D pool Enforcement history enci # Office of Inspection & Enforcement, Office of the Director 77/01/05 7pp 22582 973
- -B403080130 Responds to NRC 770103 ltr re violations noted in insp of License 29-13613-02 Corrective actions guidelines proposed for Co-60 concentration in pool water & for training program Civi) fine of \$44.800 should be withdrawn MELT.M A Radiation Technology, Inc. 77/01/31 VOLOENAU,E Office of Inspection & Enforcement, Office of the Director iipp 22582 080
- -8403080151 Notice of violation from insp on 751023 Violations noted failure to post documents specified in 10CFR19 il & failure to submit annual rept of radiation exposure incurred by personnel during 1974 Data sheet from insp enc!

 * Region I, Philadelphia, Office of the Director 75/11/11 Bpp 22582 045
- 8403080136 Ack receipt of 770131 response to notices of violation & proposed imposition of civil penalties No edequate reasons stated as to why penalties should not be imposed. Apps A & B enc. Add1 response requested.

 VOLCENAU.E Office of Inspection & Enforcement. Office of the Director 77/03/14 WELT, M A Radiation Technology, Inc 10op 22582 091
- 8403080157 Confirms 75:111 telcon between Epstein & 8 Haram re results of NRC analyses of cobalt activity existing in irradiator pool Requests analytical results in writing & action planned to identify source of leakage NELSON.PR Region i, Philadelphia, Fuel Facility & Materials Safety Branch. 75/11/12 HARAM.8 Radiation Technology, Inc. ip 22582 050

- ---8403080139 Notice of violation from insp on 810402.09,21 & 22
 Noncompliance noted operation of sealed source irradiator
 caused radiation levels exceeding 500 rems/h
 MARTIN.T T Division of Engineering & Technical Inspection
 81/07/20 2pp 22582 347
- --8403080160 Order imposing civil monetary penalties in amount of \$4,800 Payment due within 20 days of receipt of order VOLGENAU. E Office of Inspection & Enforcement, Office of the Director 77/03/14 Radiation Technology, Inc. 3pp 22582 101
- ~-8403080163 Responds to NRC 751111 ltr re violations noted in insp of Licenses 29-13613-01 & 29-13613-02 Corrective actions documents specified in 100FR19 11 posted & annual rept of radiation exposure incurred by personnel submitted WELT.M A Radiation Technology, Inc 75/12/02 NELSDN,P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch ip 22582 054
- --B403080164 IE Insp Rept 30-07022/81-01 on B10402,09 & 21-22 Violations noted failure to provide exit portal w/device to detact loose sources & operation of irradiator in continuous mode under supervision of unauthorized individuel COSTELLO,F, ROME,C, BHEPHERD,R Region i, Philadelphia, Office of the Director (81/03/01). B1/07/23 10pp 22582 351
- ---8403080167 Advises of progress in handling cobelt activity in R&D pool water Activity traced to improperly weided outer encapsulation of Co-60 source pencil Pool water cleaned up by circulation through demineralizer * Radiation Technology, Inc 75/12/03 NELSON, P.R. Region I. Philadelphia, Fuel Facility & Materials Safety Branch ip 22502 035
- ---8403080168 Requests hearing re ambiguities in interpretation of License 29-13613-02 & alleged infractions, resulting in proposed tivit penalty HELT, M A Radiation Technology, Inc. 77/04/01 VOLGENAU, E, Office of Inspection & Enforcement, Office of the Director ip 20582 104
- ~-8403080172 Responds to NRC 751215 ltr re violation noted in IE Insp Repts 30-05458/75-01 & 30-07022/75-01 Corrective actions necessary regulations will remain posted & radiation exposure reporting procedures described in exposure logbook WELY.M A Radiation Technology, Inc. 75/12/19 MCCLINTOCK,R O Region i, Philadelphia, Office of the Director ip 22582.056
- --8403080177 Discusses iE Insp Rept 30-07022/76-01 on 760618 & forwards notice of violation NELSON.P R Region I. Philadelphia, Fuel Facility & Materials Safety Branch 76/07/02 WELT,M A Radiation Technology, Inc 2pp 22382 057.
- ~~8403080182 Notice of violation from insp on 740418 Violations noted licensed maths left unattended in unrestricted sample counting area & radiation levels existed in unrestricted sample counting area exceeding safe level Data sheets encl # Region i, Philadelphia, Office of the Director 76/07/02 9pp 22502 059
- --8403080185 Responds to NRC 760702 ltr re violations noted in IE Insp Rept 30-07022/76-01 Corrective actions any source utilized for calibr purposes will be signed out of log book WELT.M A Radiation Technology, Inc. 76/07/12, NELSON.P.R Region i, Philadelphia, Fuel Facility & Materials Safety Branch 200 22582.068
- --B4030B0190 Discusses IE insp of License 29-13613-02 on 761027 & 1101 & forwards notices & violation & proposed imposition of civil penalties

 VOLGENAU,E Office of Inspection & Enforcement, Office of the Director 77/01/03 WELT,M A Radiation Technology, Inc 3pp 22582-070
- 8403080030 Partial response to FOIA request for documents re NRC internal procedures or guidance for evaluating new generic requirements & NRG & CRGR procedures for use of cost-benefit or value-impact analysis Forwards App A documents FELTON, J M Division of Rules and Records 84/01/18 WEISB, E R Union of Concerned Scientists 2pp 22584,115.
- 8403080068 Further response to FOIA request for documents re Lixi, Inc. Lixiscope of America, Inc & SA Huber Consultants, Inc. Forwards App D documents Documents also available in FDR FELTON.J.H Division of Rules and Records 84/01/17 CAULK, Q H Radiation Service Organization 2pp 22584 001
- ---8403080098 Ack receipt of 830222 ltr re State of NV reciprocity agreement BULLING, L A Diffice of State Programs, Director 83/03/03 SAVINI, R J LIXI, Inc. ip 22384 013

- --8403080119 Forwards, to Agreement States, proposed rule establishing new category to Group VI of 10CFR35 100 for 1-125 as sealed source in portable device for bone imaging & foreign body detection Change permits use of Lixiscope W/o encl NUSSBAUMER: D A Assistant Director for State Agreements Programs 83/04/07 Affiliation Not Assigned 1p 22384 014
- --8403080128 Forwards, to Agreement States, Itr to Lixi re demonstration & industrial training in use of Lixiscope device Ltr requests clarifying info.not final licensing action W/o encl NUSSBAUMER, D. A. Assistant Director for Btate Agreements Programs 83/06/28 Affiliation Not Assigned 1p 22584 015
- --8403080i3B Forwards NMSS policy to Agreement States re licensing human use of Lixiscope & bone matl analyter Byproduct matl authorized for human use by nonphysicians (podiatrists & dentists)
 NUSSBAUMER, D A Assistant Director for State Agreements Programs 83/11/18 Affiliation Not Assigned 1p 22584 016
- --8403080146 Submits policy & guidance directive re licensing Lixiscope & bone mineral analyzer for human use CUNNINGHAM.R E Division of Fuel Cycie & Material Safety B3/11/10 Region 1. Office of Director 4pp 22584 017
- --B403080195 Discusses use of Lixiscope by podiatrists & dentists NRC will assume podiatrists & dentists not physicians & consider whether exemption per 10CFR30 it could be granted MILLER. V L. Division of Fuel Cycle & Material Safety B3/11/07 CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 2pp
- --8403080165 Forwards IE Insp Repts 30-14668/83-01 & 30-17164/83-01 in Jan 1983 re possession & demonstration of Lixiscope JOYNER, J H Region 1. Defice of Director B3/06/17 MILLER, J R Region 3. Office of Director 2pp 22384 023
- --8403080173 IE Imap Repts 30-14648/83-01 & 30-19164/83-01 in Jan 1983 Violation noted Liziscope Models LSM-82 & 82-209 possessed &/or used by unauthorized licensee DARBEN.T H. KINNEMAN.J D Region 1. Office of Director 30-19164/83-01 83/06/16 35pp 22584 025
- --8403080181 Requests info re Lixiscope licensing concerning number of hours & which topics to be covered in training of physicians not meeting Group VI criteria NUSSBAUMER, D.A. Assistant Director for State Agreements Programs 83/09/09 MILLER, V.L. Division of Fuel Cycle & Material Safety ip 22584 060
- BAGDOBOOB5 FOIA request for SER & BSER 21 (NUREG-0675) re operation of facilities
 OARDE, B P Government Accountability Project 84/01/09. Office of Administration 2pp 22584 074 24X Fiche 50-275,84/01/09,8405080085
- B4030B0076 Partial response to FOIA request for SER re operation of facilities Forwards documents listed on app Documents also placed in PDR Review of remaining documents continuing FELTON, J M Division of Rules and Records 84/01/23 GARDE, B P Government Accountability Project. 2pp 22584 076 24X Fiche 50-275.84/01/23, 84030B0076.
- ---B4030B0103 Allegations 51 & 52 re NRC concern that plant personnel reluctant to come forward w/safety concerns since candor endangers jobs * NRC No Detailed Affiliation Given. B4/01/23 2pp 22584.089 24% Fiche 50-275.84/01/23.8403080096
- 8403080126 Further response to FOIA request for licenses & current ref supporting documents for companies & individuals licensed to perform rediation detection instrument calibr Fowards App A documents Portions deleted (ref FOIA Exemption 6) FELTON, J M Division of Rules and Records 84/03/01 MIKOWSKI, J Standard Nuclear Consultants, Ltd 2pp 22567 219
- --7904030132 Forwards application for renewal of Matl/Byproduct License 12-09160-01 Filing fee encl. RIVKIN.W B Health Physics Associates. Ltd 98798 79/02/28 Radioisotopes Licensing Branch (Pre 790501) ip 22367 221

- --7904030135 Application for renewal of Matl/Hyproduct License 12-09160-01 for use of licensed matls in analysis of leak test samples, callbr of radiation survey instruments, preparation of std solutions & possession of sources RIWNIN.W B Health Physics Associates, Ltd 98998 79/02/28 22p 22567 222
- --8101300020 Forwards application for renewal of Mati/Byproduct License 34-16779-01 CALLENDINE,0 W Callendine, G W 04119 80/11/17 COOPER,J Region 3. Chicago, Office of the Director ip 22567 278
- ---Bi01300025 Application for renewal of Matl/Byproduct License 34-16777-01 authorizing use of Sr-90.Cs-137.Co-60 & Ra-133 sealed source for test purposes to calibr radiation survey & measuring instruments
 CALLENDINE.G W Callendine, 9 W 04119 80/11/17 2pp 33547 279
- --B4030B0149 Application for matl/byproduct license, authorizing CC Lu, RA Cerlson, JE Carey, J Colvin. W Hack & T Mason to use &/or supervise use of Cs-137 sealed source in calibr of survey metris

 CARLEON, R A Medical Physics Consultants, Inc. 81/04/20 17pp
- --B4030B0154 Forwards addl info requested by NRC B01115 ltr re renewal of License 34-16272-01 Quarterly inventory of all sources will be mainteined FERRELL, J R Nuclear Medicine Associates, Inc. 01998 61/01/09 COOPER, J W Region 3, Chicago, Office of the Director (81/03/01) 16pp 22867 261
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13.8403080179
- --8001140316 Notifies that NRC has amended regulations re implementation of resident insp program Expresses gratitude for assistance rendered forwards final rule W/o encl
 STELLO.V Office of Inspection & Enforcement, Office of the Director 79/11/19 O'STRAND,N Washington Public Pawer Supply System 1p 22583 234 24% Fiche 50-000,84/02/13,8403080179
- --8003240202 Submits review costs for facilities Hearing was uncontested Billing procedure may be completed BERKOW. H N Office of Nuclear Reactor Regulation. Director 60/02/22 MILLER, W O License Fee Management Granch ip 22583 242 24% Fiche 50-000.84/02/13.8403080179
- --8003240207 Forwards IE cost data worksheets for facilities No costs relected for licenses contractor vendor insprepts COBD. I Executive Officer for Management & Analysis 79/01/29 MILLER. W O License Fee Management Dranch 3pp 22583 243 24X Fiche 30-000,84/02/13,8403080179
- --8003240219 Corrects 781028 memo re WPPBS 3 & 5 being contested Memo reflecting actual ASLB time spent on case encl FITTI.C V Atomic Eafety and Licensing Board Panel 80/02/28 HOLLOWAY.C J License Fee Management Branch 1p 22583 248 24X Fiche 50-000.84/02/13,8403080179
- ---BO03240222 Submits rept of time spent since program initiated on WPPSS 3 & 5 Professional time all spent on post-hearing work reparding CP hearing LAZO,R M Atomic Bafety and Licensing Board Panel 78/04/18 FITTI.C J Atomic Bafety and Licensing Board Panel 3pp 22583 249 24X Fiche 50-000.84/02/13.8403080179
- --8003250477 Forwards hydrologic engineering questions re proposed waste treatment sys Response will supply necessary info re design basis for seepage & flooding Also forwards generic questions re floodplains info will assist NRC environ review GELLS.D E Environmental Projects Branch 2 80/03/07 RENBERGER.D L Washington Public Power Supply System 5pp 22583 253 24X Fiche 50-000,84/02/13,8403080179
- --BO03270142 Discusses suspension of facility preoperational aquatic monitoring program Buspension approved Operational monitoring program results should not be affected by suspension SAMWORTH.R D Environmental Specialists Branch 80/02/27 BELLS.D E Environmental Projects Branch 2 2pp 22583 239, 24x Fiche 50-000,84/02/13,8403080179

- --8005130793 Provides status of SER inputs & acceptance reviews for OL & CP applications Schedule should be met BURKE.W C Effluent Treatment Systems Branch 80/02/06 KREGER.W E Assistant Director for Site Analysis ip 22583 235 24X Fithe 50-000,84/02/13.8403080179
- --B005150677 Forwards R Ostrhy review of JJ Osffman article re radiation causation of cancer in Hanford workers No new or significant info presented KRECER, H E Assistant Director for Site Analysis 80/02/07 SLAGGIE, L Office of the General Counsel ip 22583 236
- --B0051506B3 Reviews JH Gofman Nov 1979 article per 791226 request
 Analysis statistically weak Results fell within BEIR rept
 risk estimates NIH B00310 & il conference will discuss
 low-level ionizing radiation biological effects
 GDTCHY.R Division of Site Safety & Environmental Analysis
 B0/02/01 NURPHY.7 Radiological Assessment Branch 2pp
 22503 237
- --8009090737 Forwards airworthiness elect to corrosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Questions to esh amounts chemistry & size distribution will be forwarded to licensees W/o encl JACKSON.R E Geosciences Branch 80/06/12 VOLLMER,R H Division of Engineering 2pp 22583 258 24X Fiche 50-000,84/02/13,8403080179
- --8009110203 Responds to 800702 ltr re E Borhek concern about ultimate responsibility for civil penalities proposed against util Civil penalities are imposed as enforcement action, State agencies should be contacted re responsibility for payment DIRCKS:N J Diffice of the Executive Director for Operations BD/09/26 JACKBON,N M Senate 4pp 22583 260 24X Fiche 50-000,84/02/13,8403080179
- --B010070260 Discusses review of applicant B00B14 request for approval of proposal to substitute in-plant tests w/scale model recirculation sump tests Response to requests deferred pending NRC review of program SPEI9.1 Reactor Systems Branch B0/09/26 YOUNOBLOOD, B J i.censing Branch i ip 22583 266 24X Fiche 50-000,84/02/13,84030B0179
- --8012160551 Forwards 800625 ltr from constituent E Borhek for response Requests that Suplicate rept be forwarded to 802 United States Courthouse. Seattle-MA 98104
 JACKSON, H M Benate, Energy & Natural Resources 80/07/21.
 KAMMERER, C.C. Office of Congressional Affairs 2pp 22583 264 24X Fichs. 50-000, 84/02/13, 8403080179.
- --B101060747 Notifies of findings of possible capable fault near facility JACKSON.R E Geosciences Branch B0/10/27 R0USE.L C Advanced Fuel & Spent Fuel Licensing Branch ip 22503 267 24X Fiche 50-000,84/02/13.8403080179
- --Bi01130363 Responds to ltr forwarding M Hamilton concerns re facilities CPs issued in Apr 1978 after safety & environ reviews & ABLB public hearings Public hearings may be requested when util applies for OLS KAMMERER, C Office of Congressional Affairs 80/12/16 MACNUSON W Senate ip 22583 271 24X Fichs.50-000,84/02/13, 8403080179
- --BiO2200029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications, per Ofc of Nuclear Reactor Regulation approach to resumption of licensing. Bafety evaluation inputs should be provided by BiO601 EISENHUT, D C Division of Licensing 80/12/31 VOLLMER, R Division of Engineering. 1p 22583 277 24X Fiche 50-000, B4/02/13, 8403080179
- --Bi03040032 Forwards short & long-term OL & CP review schedules, in response to 801216 meeting w/UEOS List of OL plant reviews for which NRC tentatively plans to seek UEOS assistance is provided JACKBON.R E Quesciences Branch NRC-03-80-113 81/01/21. DEVING. J F Interior. Dept of. Geological Survey Spp 22583, 272. 24% Fiche 50-000, 84/02/13, 8403080179
- --8104920329 Concludes that Table 3.2-2 of PSAR, re safety-related atructures, sys & components, is incomplete from Geotechnical Engineering Branch viewpoint
 LEAR, G E. Hydrologic & Geotechnical Engineering Branch 81/04/08
 HAASB. 14, P. Quality Assurance Branch. 2pp 22583: 278 24X
 Fiche 50-000, 84/02/13, 8403080179.
- --BID4300020 Responds to Bi0414 memo re util request for clarification in use of ABME code cases Util use of code cases w/a prior NRC approval is inadvisable due to potential hardship for user BUSNAK.R.J. Hechanical Engineering Branch. Bi/04/21. YDUNGBLOOD.B.J. Licensing Branch i ip 22583 280 24X Fiche 50-000, B4/02/13, B4030B0179.

- --BIQ5010554 Advises that Mechanical Engineering Branch completed review of util request for authorization to use ABME Code Cases N-219 & N-287 for application in design of coherete containments Code cases acceptable KNIOHT, J P Assistant Director for Comp & Structures Engineering (Pre 830201) 81/04/29 TEDESCO.R L Assistant Director for Licensing 1p 22503 281 24X Fiche 50-000.84/02/13.8403080179
- --BIO5140106 Advises that info provided on SIO213 & O403 re air intake arrangements for diesel generators reviewed Diesel generator combustion air supply arrangement meets acceptance criteria in Bection II of SRP a 5 B Bys acceptable as designed UNGARO.A R Power Bystems Branch BI/O5/01 YOUNGBLOOD.B J Licensing Branch 1 1p 22583 282 24X Fiche 50-000,84/02/13,8403080179
- --G1051B0436 Forwards ltr from util requesting concurrence by NRC to antt Subsections 2 5 1-2 5.3 of FSAR Review & comments requested by 810622

 ADENSAM, E. G. Assistant Director for Licensing 61/05/12

 JACKSDN, R. E. Geosciences Branch 1p 22583 283 24X
 Fiche 50-000, 84/08/13, 8403080179.
- --BIO5210109 Concurs w/licensee proposal to ref Sections 2 5.1-2 5 1-2.5 3 of HPPB-2 FGAR in WPPB-1/A FGAR since both projects focated in close proximity Mods listed JACKBON, R E Geosciences Branch 81/05/15 ADENBAM, E. Q Licensing Branch 4 2pp 22583 286 24X Fiche. 50-000, 84/02/13, 8403080179
- --8106170138 Forwards results of branch review of EPRI/PWR test, per 810602 memo MIRAOLIA,F J Licensing Branch 3. 81/06/12 TEDEBCO,R L Assistant Director for Licensing 1p. 22383:288
- ~-B106220066 Requests that appropriate comments re Cycle 2 evaluations, per Eisenhut 810604 memo, be submitted by 810623 MIRAQLIA, F. J. Licensing Branch 3 81706/18 HAASB, W. S. Guality Assurance Branch 1p 22583 291 24X Fiche. 50~000, 84/02/13, 8403080179
- --Bi07i305B1 Forwards info re impact of Hount St Helens eruptions on facilities, for use by SALP review board Comments prepared by HE Lefevre geologist.

 JACKBON.R E. Geosciences Branch 81/06/23 MIRAQLIA, F J.

 Licensing Branch 3 2pp 22383'293 24X Fiche.50-000,84/02/13,8403080179
- --Bi071401B5 Forwards Ofc of Nuclear Reactor Regulation performance evaluation in compliance w/Bi0604 memo re systematic assessment of licensee performance Cycle 2. Notifies that review board meeting for facility scheduled for Bi0723 WHEELER, L Licensing Branch 3 81/06/30, EISENHUT, D.O. Division of Licensing ip 22583 295 24X Fiche 50-000.84/02/13, 8403080179.
- ---B107140192 Forwards Geosciences Branch input for use by facility systematic assessment of licensee performance review board, per B10618 request

 JACKBON.R E Geosciences Branch. B1/06/23. MIRAGLIA.F J.
 Licensing Branch 3. 3pp 22583 298 24X Fiche, 50-000, 84/02/13, 8403080179
- --8107270274 Accepts use of ABME Code Case N-242-1 dtd 800410 for application in const of pipe support frames in pipe chases located in two lower elevations of reactor auxiliary bldg. Conditions of use discussed KNIOHT.J.P. Assistant Director for Comp & Structures Engineering (Fre 830201) 81/07/21. TEDESCO.R L. Assistant Director for Licensing ip 22583.301. 24X Fiche: 50-000, 84/02/13, 8403080179
- --Bi07280171 Notification of Bi0729 meeting w/util & B&W in Bethesda, MD to discuss method util intends to use to fulfill requirments of NUREQ-0737 Item II F 2 (inadequate core cooling instrumentation)
 HERNAN, R W Licensing Branch 4 91/07/21 ADENSAM, E Q Licensing Branch 4 2pp. 22583-305, 24X Fiche 50-000, 84/02/13, 8403080179,
- --8i0Bli0038 Notification of Bi0820 meeting w/util in Bethesds, MD to discuss proposed independent design review programs, HERNAN, R. W. Licensing Branch 4 B1/07/30, ADENBAM, E. G. Licensing Branch 4 Bpp 22583 302. 24X Fiche: 50-000, B4/02/13, B4030B0179
- --Bi10080612 Discusses proposal to use IDRs in licensing process, IDRs may be useful in certain greas, but clarification of role needed. TEDESCO.R.L. Assistant Director for Licensing 81/09/23. EIBENHUT, D.Q. Division of Licensing 1p. 22583 307. 24X Fiche 50-000, 84/02/13, 8403080179.

- --8110190026 Requests that comparison of fire protection program to App R of 10CFR50 be included in overall fire protection program submittal W/o encl FR notice EISENHUT, D Q Division of Licensing 81/09/30 FERGUSON, R L Washington Public Power Supply System 2pp 22583 308 24X Fiche 50-000, 84/02/13,8403080179
- ---8ii1060697 Notifies of util intention of sending technical team to present FBAR to review staff during wk of Siii30 Reviewers should complete attached form & confirm attendance HERNAN,R W Licensing Branch 4 8i/10/23. Licensing Branch 4 App 22583,311 24X Fiche 50-000.84/02/13.8403080179
- --8111120935 Forwards form which identifies Power Sys Branch electrical & mechanical reviewers for project in accordance w/811023 memo Requests established review schedule dates when available UNPARG, A Power Systems Branch 61/11/02 HERNAN, R W Licensing Branch 4 2pp 22583 316 24X Fiche 50-000,84/02/13.8403080179
- --81iii30007 Submits names of D Oups & O Stalloy as technical reviewers for facility FBAR per 811023 memo
 LEAR, O. Hydrologic & Osotechnical Engineering Branch 81/10/30
 ADENSAM, E. Licensing Branch 4 1p 22583 315 24X
 Fichs 50-000,84/02/13,8403080179
- --81i1200219 Informs of receipt of telcon from Yakemar Indian Nation requosting that tribe be given full rights in facilities proceedings.

 TEDESCO,R L. Assistant Director for Licensing 81/10/21.

 KETCHEN.E. Hearings Division. ip. 22583.310 24X

 Fiche.50-000.84/02/13.8403080179
- --Bii2300305 Notification of Bii2il meeting w/util in Bethesda.MD to discuss FBAR w/technical review staff at time DL application is tendered.

 HERNAN,R.W. Licensing Branch 4 Bi/i1/23 ADENSAM.E. C Licensing Branch 4. 3pp 22583 3IB 24X Fiche 50-000,84/02/13.8403080179
- --B201190297 Forwards Central Files version of "Description of Early Warning Bys for WPPBS Nuclear Plants 1.2 & 4." in response to NRC 810720 ltr re prompt notification in event of mergency. Sys will be in place prior to OL issuance BOUCHEY, O D Washington Fublic Power Supply System 62/01/11 TEDESCO, R L Assistant Director for Licensing 1p 22583 321 24X Fichs. 50-000. 84/02/13. 8403080179
- --8202180456 Requests that Fire Protection Section perform acceptance invel review of facilities' revised fire protection program prior to docketing of DL application Util sware that App R to 10CFR50 will apply.

 ADENSAM, E. Q. Licensing Branch 4 82/01/27. BENARDYA. V Chemical Engineering Branch. 1p 22583 322 24X Fiche 30-000,84/02/13,8403080179
- --8202260171 Requests assistance in performing acceptance review of environ rept for OL application Unity portions applicable to Unit i need be considered since Unit 4 cancelled on 820122 ADENBAN, E. 0. Licensing Branch 4 82/02/10 JACKSON, R. E. Geosciences Brench. ip 22583 324 24X Fiche 50-000,84/02/13,640300178.
- --8203020139 Advises that listed info needed to perform acceptance review of fire protection program for conformance w/NUREG-0800.

 Section 9 3-1

 BENAROYA,V Chemical Engineering Branch. 82/02/09 ADENSAM,E Q Licensing Branch 4 ip 22583.323 24X Fiche 50-000,84/02/13,8403080179
- --8203100570 Recommends environ rept be accepted. Add1 questions re external appearance plant layout & socioeconomics of single unit operation will be submitted. RECAN, M. H. Biting Analysis Branch. 82/02/25 ADENSAM, E. Q. Licensing Branch 4 ip 22583 328, 24X Fiche 50-000,84/02/13,8403080179
- --8203150028 Forwards add1 info requirements for review of ER for OL application per 820210 request.

 BALLARD,R.L. Environmental Engineering Branch 82/03/02, ADENBAM,E 0, Licensing Branch 4, 3pp. 22583,329 24X Fiche, 50-000,84/02/13,8403080179

- --8203180004 Advises that environ rept is acceptable re radiological impacts
 HOUSTON, R W Assistant Director for Radiation Protection
 82/03/02 TEDESCO.R L Assistant Director for Licensing ip
 82883 332 24X Fishe 50-000,84/02/13.840308017
- --82031801;8 Forwards two relevant documents for FOIA request re WPPSS & Exxon Litigation MIRAQLIA.F J Licensing Branch 3 82/03/08 WILEON.V H Hanagement Analysis Branch 3pp 22983 333 24% Fiche 50-000.84/02/13.8403080179
- --8204070097 Informs that sufficient info provided to begin meteorology review inappropriate models & diffusion parameters used in Section 6 1 3 2 & accident evaluations HULMAN, L 0 Accident Evaluation Brench 82/03/16 ADENSAM, E Licensing Branch 4 2pp 22583 336 24X Fiche 50-000, 64/02/13, 8403080179
- --8204290657 Notification of 820511 meeting w/util to discuss review process & preliminary identification of any possible unique features
 WHEELER, L. Licensing Branch 3 82/04/22 MiRAQLIA.F., J. Licensing Branch 3 1p. 22583 340 24x Fiche 30-000, 94/02/13, 8403080179
- --B205070088 Forwards list of sys to be added to G-list Sys provides ongoing knowledge of changes in radiation environ & ability to deal effoctively w/wnusually high radiation & radioactivity isvels
 CONOEL.F J Radiological Assessment Branch 82/03/23 HAASS, W P Guality Assurance Branch 2pp 22583 338 24X
 Fithe 50-000,84/02/13,8403080179
- --8205300082 Lists info not yet addressed for OL application Recommends general info be accepted for docketing LEE, I J Licensing Branch 3 82/06/18 WHEELER, L. L. Licensing Branch 3 ip 22583 347 24% Fiche 50-000.04/02/13,8403080179
- --8208120240 Forwards Central Files version of revised page to Revision 2 of emergency plan adding local fire depts within 20 miles of facility to backup fire protection svcs
 BOUCHEY, 8 D. Washington Public Power Bupply System GD2-82-642
 82/08/05 SCHWENCER, A. Licensing Branch 2 2pp 22583 348 24X
 Fiche 50-000,84/02/13.8403080179
- --B20B12024B Central Files version of revised page to Revision 2 of emergency plan re provision of backup fire protection svcs # Hashington Public Power Supply System 82/08/05 ip 22583 350 24X Fiche 50-000,84/02/13.8403080179
- --8209280165 Forwards Cyclo 3 systematic appraisal of licensee performance input for B10701 through 820730 in response to Region 5 820625 request Strong mgt evident Resolution of technical issues, responsiveness & staffing satisfactory HERNAN, R W Licensing Branch 4, 82/09/15 EISENHUT.D 9 Division of Licensing 4pp 22583 351 24X Fiche; 50-040, 84/02/13, 8403080179
- --82:2070382 Ack receipt of 82:109 ltr re Target Rock environ qualification testing program Info re valve upgrade & retest anticipated HEISHMAN.R F. Division of Reactor Programs (Pre 830:103), 82/12/01 BDUCHEY, O.D. Mashington Public Power Supply System 1p 22583 357, 24% Fiche 50-000,84/02/13,8403080179
- --8303i00476 Forwards util 830223 submittal in response to telcon during which remaining Phase I open items of "Control of Heavy Loads -- Case Reviews," were discussed, W/o encl CLEMENBON, F. Auxiliary Systems Branch NRC-20-iB-388 83/02/28 STICKLEY, TH EORG, Inc. ip 22583 360 24X Fiche 50-000, 84/02/13, 8403080179
- --8304060577 Requests search for documents re govt litigation w/util on five specific issues
 81,4001E,E L Office of the General Counsel 83/03/23
 DIRKKS,M.J. Defice of the Executive Director for Operations ip
 22583.361. 24X Fiche 50-000,84/02/13.8403080179.
- --8304070113 Recommends that radiation exposure records be retained for 1 yr prior to disposal Ref Murphy to Varga 801222 CONOBL, F J Radiological Assessment Branch 83/04/01 SCHMENCER, A Licensing Branch 2. 1g. 22583,327 24X Fiche 50-000,84/02/13,8403080179
- --8403080253 Forwards summary of review costs & supporting documentation from program ofts M/o encl HOLLOHAY.C J License Fee Management Branch. 80/03/03 License Fee Management Branch. 1p 22583 241 24X Fiche 50-000.84/02/13.8403080179

- 8403080196 FDIA request for documents re WR McAfee allegations involving facility from Mar 1977 - Mar 1979.NRC open conference at site in Nov 1979 & review of util topical GA manual GARDEAB P, ANSELL, E. Government Accountability Project 93/11/21 Office of Administration 2pp 22584 162 24X Fiche 50-419.83/11/21.8403080196
- B40308020D F01A request for 2 categories of documents to NRC correspondence w/Lizi.inc & 5A Huber Consultants WIESELMAN,K LIXI. Inc & 93/11/22 MILLER,V L Division of Fuel Cycle & Material Bafety ip 22567 208
- 84030802D3 Responds to FDIA request for documents from Mer 1977 Mar 1977 re WR McAfee allegations Forwards App A documents. Info also available in PDR FELTON.J M Division of Rules and Records 84/01/24 GARDE.B.P Government Accountability Project. 2pp 22584 164 24X Fichs 50-413.84/01/24.8403080203
- --B403080212 Discusses 791113-16 Interviews w/craftsmen Interviewers selected by principal inspector.per Y1 2512/4 criteria. Related info encl HURPHY.C E Region 3, Chicago, Reactor Construction & Engineering Support Branch 79712/04 THORNBURG.H D Director's Office. Defice of Inspection and Enforcement. 9pp. 22584 166. 24X Fiche 50-413,84/01/24,8403080203
- B4030B0207 Responds to FDIA request for NRC correspondence w/Lixi,Inc & BA Huber Consultants Forwards documents listed on app Documents also available in PDR FELTON.J M Division of Rules and Records, 84/01/23 WIESELMAN.K LIXI, Inc 3pp 22567 209
- --7906250470 Comments on proposed Reg Quide 10 B 100 dem limit seems very expitrary & requires calculations to relate to individual equipment Strict application of reg guides should be avoided
 - HUBER, S A Stan A Huber Consultants, Inc 79/02/08 Bocksting & Services Branch 2PP 22567 212.
- --B4030B021B Advises that 83D12B memo requiring Lixiscope evaluation to include public comment period contradicts advice given at 821013 meeting Comment period will unressonably delay license issuance & cause financial loss BAVINI.R J. LIXI. Inc. 83/02/24 OLMSTEAD.W. Office of the Executive Legal Director 2pp 22567 214
- --84030B0225 Responds to 830224 request for reconsideration of advice re public comment on proposed rule concerning addition of Lisiscope to list of devices in 10CFR33 100 Public comment unnecessary for issuance of Lisiscope license OLMSTEAD, H J. Office of the Executive Legal Director, 83/03/30 SAVINI, R J. LIXI, Inc. 3pp 22367 216
- 8403080219 Partial response to FOIA request for two categories of documents re PMR RCS & specified inap repts Document available in PDR Search for addl documents continuing FELTON.J M Division of Rules and Records 84/01/25. MADDEN.T J Kays, Scholer, Fierman, Hays & Handler 2pp 22584.182
- 8403080226 FOIA request for two categories of documents re PMR RCS & specified inap repts
 HADDEN-T.J Kaye Scholer, Fiermen, Hays & Handler 83/12/12,
 NORRY:P G Office of Administration 2pp. 22584,184
- 8403080324 FDIA request for documents considered by NRC in preparation of notice of violation k proposed imposition of civil panalty.831222 ltr transmitting violation k rept of investigation re intimidation of GA personnel HARTMAN.8.L. Debevoise k Libermen 83/12/30 FELTON.J.M Division of Rules and Records 2pp 22583 169. 24X Fiche 50-445.83/12/30.8403080324
- 8403080325 Partial response to FOIA request for documents considered by NRG in preparetion of three categories of documents concerning facilities Forwards documents listed on App A. FELTON.J H Division of Rules and Records 84/01/20. HARTMAN.S.L. Debayoise & Liberman 2pp 22583:171, 24X Fiche 50-445.84/01/20. 8402090325
- --B4030B0327 Rev 27 to Procedure 01-GP-11 4-5 re visual defects insp & dry film thickness Related info encl e Texas Utilities Electric Co (formerly Texas Utilities Geotype Coestrating Co) B3/11/08 4pp. 22583.173. 24X Fiche 50-44p.84/01/20.8403080325

- --B403080332 Describes commitments made to NRC in RJ Qary 830928 response to notice of violation & proposed imposition of civi) penalty CLEMENTB.B R. Tejes Utilities Electric Co. (formerly Texas Utilities Generating Co.). EA-83-064 83/11/29 COLLING.J T Region 4. Office of Director 11pp 22583 182 24X Fiche 50-445.84/01/20.8403080325
- --8403080333 Notification of significant licenses meeting on 831212 w/
 util in Arlington. TX to discuss potential enforcement action
 rs intimidation of employees by H Williams
 * Region 4, Defice of Director 83/12/08, Region 4, Office of
 Director ip 22583 193 24X Fiche 50-445.84/01/20.8403080325
- ---8403080335 Forwards rept re investigation into allegations made by WA Dunham & concerns related to protective coatings Related documents and OARY, R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) TXX-4087 83/12/13 COLLINS, J Region 4, Office of Director 22pp 22583 204 24X Fiche 50-445,84/01/20, presentating Co.
- 8403080339 Final response to FOIA request for documents re NRC investigation of industrial accident involving burst steam pips at facility "VEPCO Investigative Board Preliminary Rept" on accident placed in FDR FELTON, J M. Division of Rules and Records 84/01/20 GARDE, B P. Government Accountability Project ip 22576-214 24X Fiche: 50-280, 84/01/20, 8403080339
- --8403080341 "VEPCO Investigative Board Preliminary Rept." W/o cover sheet * Virginia Electric & Power Co 84/01/20 29pp 22576:215 24X Fiche:50-280,84/01/20,8403080339
- 8403080344 FOIA request for documents re proposed NSHC determination on license, amends for Millstone 2 & entry into operational mode for conducting final tests of pressurizer safety valves at Trojan ADATO.M Union of Concerned Scientiste 84/02/02 FELTON.J M Division of Rules and Records 1p 22583 038. 24X Fiche 50-000, 84/02/02, 8403080344
- B403080344 Appeals denial of FOIA request for "Boresele Rept " Rept discussed in Board Notification BN-83-151, "Westinghouse ECCB Actuation Lagic " WEISS.E R Union of Concerned Scientists. B4/01/05 DIRCKE,W J Office of the Executive Director for Operations 3pp, 22567-288
- 8403080347 Partial response to FDIA request for documents re proposed NEHC determinations for Millstone 2 & entry into operational mode for conducting final tests of pressurizer safety valves at Trojan Forwards App B documents FELTON, J. M Division of Rules and Records 84/03/02 ADATO, M Union of Concerned Scientists 4pp 22583 039 24X Fiche 50-000, 84/03/02, 8403080347
- --8307180403 Initial NSHC determination & noticing action re util 830524 application to amend License NPF-1, clerifying purpose of auxiliary hoist & testing of hoist & menipulator crane.
 TRAMMELL, C NRC No Detailed Affiliation Given 83/06/27 2pp 22583 043 24X Fichs 50-Q00,84/03/02,8403080347.
- --B307180414 Requests FR publication of notice of consideration of issuance of emend to License NPF-1 & proposed NBHC determination & opportunity for hearing rs 830524 request to heat up to hot standby mode CLARK, R. A Operating Reactors Branch 3 83/07/06, KREUTZER, P M Operating Reactors Branch 3 3pp 22583 045 24X Fichs 50-000, 84/03/02, 8403080347
- --8312230261 Evaluates util 831102 arguments to support validity of previous LOCA analyses for removal of thermal shield from core between Research specific and subject to confirmation of pask clad temp HDUSTONIR W Assistant Director for Reactor Safety. TAC 51969 83/12/13 LAIMAB. 9.C. Assistant Director for Operating Reactors. 2pp 22583.060. 24X Fiche 50-000.84/03/02.8403080347.
- ---8403080352 Returns request for publication in FR of notice of consideration of issuance of amend to OL & proposed NSHC determination re Tech Spec changes resulting from Cycle 6 refueling considerations Revs requested W/o encl.
 ROTHSCHILD, M. U. Office of the Executive Legal Director. 83/06/13 CLARK, R A Operating Reactors Branch 3 1p 22383 059, 24X Fithe. 50-000, 84/03/02, 8403080347.
- 8403080350 Responds to 831018 & 1201 requests for "Boresele Rept."
 "Borstele Rept" submitted in confidence to Commission by
 foreign source & exempt from public disclosure per
 100FR2. 770

 DENTON: H R Office of Nuclear Reactor Regulation, Director
 83/12/22 POLLARD.R. Union of Concerned Scientists ip
 82/12/22 791

- B403080354 Requests essistance in obtaining reply to B31018 itr to D Eisenhut requesting "Borssale Rept "
 POLLARD, R D Union of Concerned Scientists B3/12/01 DIRCKB, W J Diffice of the Executive Director for Operations. ip 22567 293
- 8403080357 Responds to eppeal re deniel of FDIA request for "Borssele Rept " Forwards two repts on Borssela Nuclear Power Station FELTON, J M Division of Rulas end Racords 84/01/17 WEIGS, E R Union of Concerned Scientists 1p 22567 274
- ---B4030B0360 Forwards two rapts, "Steam Generator Tube Rupturs Procedure at Borsseia Nuclear Powar Station" & "Natural Circulation & Heat Transfar Tasts in Borsseia Nuclear Power Plant "
 VAN DAATSELAAR Netherlands, Govt of B3/08/02 LAFLEUR, J D
 Office of International Programs, Director. 19 22567 295
- --8403080364 "Steam Cenerator Tube Rupture Procedure et Borssele Nuclear Power Station, Implementation of Lessons From TMI, DOEL & Ginna " VAY881ER, Q Natherlands, Govt of 83/06/30 17pp 22567.276
- --8403060366 "Natural Circulation & Heat Transfer Tests in Borssele Nuclear Power Plant " KALVERBOER.C Netherlands, Govt of. 83/07/11 18pp 22367 312
- ----B4030B0360 Forwards two repts, "Steam Generator Tube Rupture Procedure at Borssela Nuclear Power Station" & "Natural Circulation & Heat Transfer Tests in Borssele Nuclear Power Plant "
 VAN DAATSELAAR Natherlands, Govt of, 83/08/02 LAFLEUR, J D
 Office of International Programs, Director ip 22567-295
- --B403080364 "Steam Generator Tube Rupture Procedure et Borssele Nuclear Power Station, Implementation of Lessons From TMI, DOEL & Ginna " VAYBBIER, G. Netherlands, Govt of. B3/06/30 17pp 22367 296
- ---8403080366 "Neturel Circulation & Heat Transfer Tests in Borssele Nuclear Fower Pient." KALVERBOER, C Netherlands, Govt of 83/07/11 18pp 22567 312
- 8403080363 FDIA request for documents re BWR Intergranular Stress Corrosion Cracking Owners Group marting on or ebout 811028 MAFNER, B. Suffolk Nuclear Study Group. 83/11/26 Office of Administration ip 22583 007, 24X Fiche 30-322,83/11/26, 8403080363.
- 8403080367 Responds to FOIA request for documents re BHR integrenular Stress Corrosion Cracking Duners Group meeting on or ebout 811028. Forwards App A documents. Records also in PDR FELTON.J. M Division of Rules end Records 84/02/28 HAFNER, B 8uffolk Nuclear Study Group 2pp. 22583.008 24x Fiche. 50-000, 84/02/28, 8403080367
- ~-B30B090070 Advises that Div of Licensing responsible for developing plan for coordination of BHR pipe crack activities Review & input to encl proposed draft of ectivities list requested by B30729 CABE, E. Q. Office of Nuclear Reactor Regulation, Director B3/07/28, ARLOTTO, Q A Division of Engineering Technology URDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B3003). MATTBON, R. Division of Systems Integration (post B11005). 3pp. 22583 016.
- ---8309210434 Requests evaluation of Grand Gulf & Shorehem 830817 & 23 responses, respectively re intergranular stress corrosion cracking in EWR piping. Response requested by 830916 W/o encl.
 - encl.
 EIBENHUT, D @ Division of Licensing. 83/09/06, VOLLMER, R
 Division of Engineering. 1p 22583,010, 24X
 Fiche: 30-000,84/02/28,8403080367
- 8403080370 Appeals denial of FDIA request for draft iE Insp Repts 50-424/83-13 & 50-425/83-13.

 8DMBY,A H. Troutman, Senders, Lockerman & Ashmore 83/11/14
 Office of the Executive Director for Operations, 2pp 22576-244
 24X Fiche: 50-425,83/11/14,8403080370.
- B4030B0372 Responds to appeal re denial of FOIA request for draft IE Insp Repts 50-424/83-13 & 50-425/83-13, Forwards documents FELTON, J. M. Division of Rules and Records. B4/01/31 DOMBY, A. H. Troutman, Bandars, Lockerman & Askmore. 1p 22576-246. 24X Fiche: 50-424, 84/01/31, 84030B0372
- --8403080377 Forwards 1E Insp Repts 50-424/83-13 & 50-425/83-13 on 830621-0720 & notice of violation.

 LEWIS.R.C. Division of Project & Resident Programs 83/10/14 KELLEY.R.J. Qeorgia Power Co 2pp. 22576-247, 24X Fiche, 50-424, 84/01/31, 8403080372

- ~-8403080381 Notice of violation from insp on B30621-0720 * Region 2, Office of Director 50-425/83-13 83/10/14 3pp 22576 247 24% Fiche 50-424,84/01/31.8403080372
- --8403080384 IE Insp Repts 50-424/83-13 & 50-425/83-13 on 830621-0720 Violations noted failure to implement pips support control documents & provide appropriate concrete expansion anchor & structural steel acceptance criteria
 BROWNLEE, V. L., BANDERS, W. F., VACKSON, L. H. Region 2, Office of Director 50-425/83-13 83/10/11 36pp 22576-252 24X Fiche 50-424.84/01/31,8403080372
- --8403080377 Forwards 1E Insp Repts 50-424/83-13 & 50-425/83-13 on 830621-0720 & notice of violation LEHTS,R C Division of Project & Resident Programs 83/10/14 KELLEY,R J Georgia Power Co 2pp. 22576 247 24X Fiche 50-424,84/01/31,8403080372
- --8403080381 Notice of violation from insp on 830621-0720 # Region 2, Office of Director 50-425/83-13 83/10/14. 3pp. 22576: 247 24X Fiche: 50-424,84/01/31,8403080372
- --B4030803B4 1E Insp Repts 50-424/83-13 & 50-425/83-13 on 830621-0720 Violations noted failure to implement sipe support control documents & provide appropriate concrets expansion enchor & structural steal acceptance criteria

 BROWNLEE.V L , BANDERB.W F , JACKSON,L H Region 2, Office of Director 50-425/83-13 83/10/11 36pp 22576 252 24X Ficher 50-424, 84/01/31, 8403080372
- 8403080375 Final response to FDIA request for SECYs 83-32,788,228A,240,246 & 261 to be placed in PDR Attachment 3 to SECY-83-228 Wassucteted encl placed in PDR Attachment 4 to SECY-83-228 partielly withheld (ref FDIA Exemption 5) FELTON, JM Division of Rules end Records 84/02/17 ORABER, L D NUS Corp. 2pp 22567 330
- --8301140173 Provides responses to 821220 questions re SECY-82-489, "Licensing of Gunsights Illuminated by Dyproduct Mati " DIRCKS, W J Gffice of the Executive Director for Operations 83/01/05 AHEARNE. J F Commissioners 3pp 22567 334
- --8403080379 Requests commants on whether public distribution of illuminated gunsights would contravene any existing fisheral regulation or policy re firsarms or accessoriss Response requested by 830218 W/o SECY-82-489 MALSCH.M G Office of the General Counsel 83/01/19 OLSON.T B Justice. Dept of 2pp 22567 332
- ---B4030B03B3 Responds to inquiry rs NRC review of solicy concerning licensing of gunsights illuminated by nuclear byproduct mat! Contact w/criminal div of DOJ & FDI may provide insight re firearms control Info deleted BHANKB, R.B. Justice, Dept of, 83/06/03 MALSCH, M.G. Office of the Osneral Counsel 3pp 22567-337
- B4030803B5 F0IA request for 27 documents referenced in 1975 EIS refacilities & similiar environ documents List & news articles encl.

 RYAN, J A Etrsich, Lang, Wesks & Cardon 84/01/17 Office of Administration 7pp 225B1 171 24X Ficher 50-528,84/01/17, B4030803B5
- 8403080388 FOIA request for documents rs landfill located in Middletown Township, Bucks County, PA MILL.S. White & Hilliams 84/02/13 FELTON, J Office of Administration Ip 22881 326
- 8403080390 Responds to FOIA request for 27 documents referenced in 1975 EIB re fecilities & similiar environ documents Forwards App A Documents 1-10 Documents 11 & 12 available at NTIS FELTON, J M Division of Rules and Records, 84/02/13 RYAN, J A Streich, Lang, Weeks & Cardon 2pp 22581 180 24% Fichs 50-528,84/02/13,8403080390
- --8108270490 Bubmits Geosciences Brench DES input Updated summary of gaology & seismology section FBAR will be included in BER. JACKSON, R E Geosciences Brench 81/08/14 MIRACLIA.F Licensing Brench 3 2pp. 22381 182 24% Fiche 50-028,84/02/13,840380390
- --B4030B0400 Discusses review of environ rept re-trensmission lines crossing Indian reservations Tribel council consent should be obtained for right-of-way before environ rept published. Related info enci
 # Interior, Dapt of, Bureeu of Indian Affairs 74/12/11
 REOAN.W.H Atomic Energy Commission Deputy Director for Reactor Projects 5pp 223Bi 184. 24X Fiche 50-528,84/02/13,84030B0390

- --8403080406 Comment on DEB, per 750414 request Statement somewhat biased toward project More detailed maps of pipeline & transmission line corridors should be provided in final statement BOREMUS, S.D. Interior, Dept of 7915 75/07/23 REGAN Division of Reactor Licensing (NRR-1975 only) 29pp 22581 189 24X Fiche 50-528,84/02/13,8403080390
- --8403080409 R-900-74-2
 "Oroundwater Conditions of Lower Hassayampa-Centennial Area, Maricopa County, AZ " Related info encl # Harshbarger & Associates 74/06/30 83pp 22581 219 24X Fiche 50-528,84/02/13,8403080390
- 8403080391 Responds to FOIA request for info re landfill located in Middletown Township, Bucks County, PA Forwards J Kinneman 840207 ltr to Korman Corp W/o encl. FELTON, J N Division of Rules and Records 84/03/02 MILL, 8 White & Williams ip. 22581: 327
- 8403080393 Forwards DL Jensen 830517 ltr to N Palladino re DOJ investigation of TML Document subj to Volgt 830526 FDIA request & 830919 appeal Document should be placed in PDR SMEENEY.M Office of the General Counsel 84/01/27 PDUL.M J NRC - No Detailed Affiliation Given. 1p 22567 354. 24X Fiche 50-289,84/01/27.8403080393
- --B403080425 Responds to B30411 ltr re TMI-1 restart & DDJ investigation into allegations re mgt competence investigation being pursued diligently but will not be completed by requested date

 JENSEN.D L Justice, Dept of B3/05/17 PALLADINO,N J
 Commissioners 4pp 22567.355 24X Fiche 50-289,84/01/27.
- 8403080398 Responds to FOIA request for info on nuclear freeze NRC has no documents subj to request Suggests that DDD be contacted at listed address for info FELTON.J N Division of Rules and Records 94/02/28. ENOS.B Affiliation Not Assigned 19 22567.361
- B403080401 FOIA request for info re nuclear freeze ENDS, B Affiliation Not Assigned. 84/02/05 Office of Administration 1p 22867 362
- 8403080402 F01A request for info or sources of info re nuclear waste JDNES,F H Affiliation Not Assigned 84/02/14 FELTON, J Division of Rules and Records 1p 22547:359
- B4030B0404 Responds to FOIA request for info re nuclear waste Ferwards listed documents W/o encls FELTON.J H Division of Rules and Records 84/02/23 JONES,F H Affiliation Not Assigned 1p 22567 360
- 9403090405 Further response to FGIA request for documents re SER related to operation of facilities Forwards App B documents App A B documents available in PDR Review of remaining documents swaj to request in progress FELTON, J M Division of Rules and Records. 94/03/02 GARDE, B P Opvernment Accountability Project. 4pp 22583:073 24x Fiche: 50-275,84/03/02,8403080405
- --8312230256 Forwards responses to Allegations 7.9 & 48, per 831130 request SPEIS.TP Division of Safety Technology 83/12/09 KNIGHTON, G Office of Nuclear Reactor Regulation. Director. 12pp. 22583:111 24X Fichs. 50-275, 84/03/02, 8403080405
- --8403080411 Forwards response to Allegation RV-83-A-0034.per ON Knighton B31122 note Tamporarily exampting licenses from maintaining physical security & safeguards contingency plans did not increase risk of radiological sabotage MCCORKLE.O M. Power Reactor Safeguards Licensing Branch 83/12/01 THOMAS.C O. Stanfardization & Special Projects Branch 4pp 22583 077. 24X Fiche. 50-275.84/03/02,8403080405
- --8403080417 Resubmits response to Allegation RV-83-A-0034, per GW Knighton 831103 memo Temporarily brempting licensee from maintaining physical security & safeguerds contingency plans did not increase risk of radiological sabotage MCCORKLE GW Power Reactor Safeguards Licensing Branch 83/12/05 THOMAS, CO Standardization & Special Projects Branch 3pp. 22583 081. 24X Fichs 50-275,84/03/02,8403080405
- --B4030B0420 Forwards response to Allegation RV-83-A-0034, per GW Knighton B21122 note Yemporarily exempting licensed from maintaining physical security & safeguards contingency plans did not increase risk of radiological sabotage BURNETT, R F, Division of Gafeguards 83/12/08, EISENHUT, D O, Division of Licensing. 3pp 22583 084 24X Fiche 50-275, B4/03/02/8403080403

- --B4030B042: Requests assistance in addressing improper design activities re use of U-bolts & code break (code boundary) design.psr affidavit re allegations
 BISHOP, T W Division of Resident.Reactor Project & Engineering Programs 63/11/27 EISENHUT.D O Division of Licensing 15pp 22583 093 R4X Fiche 50-275.84/03/02.8403080405
- --8403080422 Forwards input on Allegations 51 & 52 Fuel loading addressed in 831108 Memorandum & Order CLI-83-27 No significant safety concerns matl to fuel loading & precriticality testing warrant continuation or suspension of activities BURNS.8 Office of the Executive Legal Director CLI-83-27 83/12/09 KNIGHTON, G Office of Nuclear Reactor Regulation, Director 3pp 22583 108 24X Fiche 50-275.84/03/02.8403080405
- --8403080426 Forwards safety evaluations for Allegations 8,10,11,14,15, 16,17,27,28,27,31,32,33,35,36,55,65 & 86 Licensee approach for determining containment stability against tilting acceptable VOLLMER,R H Division of Engineering IEB-80-11 B3/12/09 EIBENHUT,D @ Division of Licensing Sipp 22563 132 24X Fichs 50-275,84/03/02,8403080405
- --8403080431 Forwards SSER input re Allegation AS Programmatic breakdown in Pullman Power Products QA program not indicated Installed hardware safety concerns not identified LIEBERMAN.J Office of the Executive Legal Director 83/12/27 EIBENMUT.D Division of Licensing 4pp 22583:163, 24X Fiche 50-275.84/03/02,8403080405
- 8403080408 FOIA request for rapts of insp carried out under Condition 2 of Nuclear Energy Liability policies for facilities CALSOYAS,C D Affiliation Not Assigned 84/02/07 Region 5, Office of Director 4pp 22567 341, 24X Fiche 50~000,84/02/07,8403080408
- E4030B0419 Responds to FDIA request for repts of inspicarried out under Condition 2 to Nuclear Energy Liability policies for facilities NRC does not have repts FELTON, J M Division of Rules and Records B4/02/22 CALSOYAB, C D. Affiliation Not Assigned. 1p 22567 345 24X Fiche 50-000.64/02/22,84030B0419
- 8403090006 Further response to FOIA request for all 1982 SECY papers to be made available SECY-82-37 & SECY-82-37A placed in FOR FELION, J M Division of Rules and Records 84/02/22 WEISB, E R Union of Concerned Scientists ip 22991 218.
- ---B203050065 SECY-82-037
 Informs of receipt of Executive Branch final draft rept
 to Congress per Section 601 of Nuclear Non-proliferation
 Act of 1978 Rept generally accurate No areas warrant
 formal NRC Lomment
 DIRCKS,W J Office of the Executive Director for Operations,
 82/01/29 100pp 22591,220
- --B204160230 SECY-B2-037A
 Informs Commission of receipt of final version of rept to congress re Section 601 of Nuclear Nonpreliferation Act DIRKESH J Office of the Executiva Director for Operations 82/03/29. 64pp 22591,317.
- B403090015 FGIA request for SECY-B3-445 to be placed in PDR
 BUCKLES,R NUS Corp. CD-L15-83-058, 84/01/26 Division of Rules
 and Records ip 22592 311
- B403090016 F0IA request for documents re background radiation survey at BNL.
 GROSSMAN,K Island Closeup News Service, Sag Harbor, NY 84/02/15
 FELTON NRC No Detailed Affiliation Glven ip 22592:343
- B403070017 Responds to FOIA request for SECY-83-445 to be placed in PDR Forwards SECY-83-445 Dacument also in PDR FELTON, J M Division of Rules and Records, 84/02/28 BUCKLES, R. NUB Corp ip. 22592; 312.
- ---8403090019 SECY-83-445
 Responds to Commission request for human factors program
 plan quarterly repts cited in Chilk 830216 staff
 requirements memo
 DIRCKS.W J Diffice of the Executive Director for Operations,
 83/10/28 16pp 22592,313
- B40309001B Responds to FDIA request for documents re BNL background radiation survey DOE preparing Shoreham & BNL sits rapts. When printed Shoreham rept will be available from NRC & BNL rept will be available from DOE FELTON, J M Division of Rules and Records 84/03/02, ORDSEMAN, K Island Closeup News Service, Sag Harbor, NY. 1p. 22592:344, 24X Fiche:50-322,84/03/02,840309001B

- B403090020 FOIA request for Nov 1983 document re resolution of Gensric Issue BO. "Reactor Vessel Levsl Instrumentation in BWRs."

 CHAPMAN.N. 9 Bechtel Corp B4/02/01 FELTON.J M Division of Rules and Records 1p 22592 340
- 8403090021 Responds to FOIA request for documents proposing resolution of Gensric Issue 50, "Reactor Vessel Lsvel Instrumentation in BRRs," Documents entirely withheld (rsf FOIA Exemption 5) FELTON, J M Division of Rules and Records 84/03/02 CHAPMAN, N O Bechtsl Corp 2pp 22592 341
- 8403090027 FOIA request for records rs 1977 Nuclsar Svcs Corp audit of Pullman Power Products,
 REYNOLDB.J Center for Law in the Public Interest 84/01/20
 Office of Administration, 2pp 22592 327 24X
 Fiche, 50-275, 84/01/20, 8403090027
- 8403070028 Partial response to FOIA request for records re 1977 Nuclear Stycs Corp audit of Pollman Power Products Documents entirely withheld (ref FOIA Exemption 5). Review of remaining documents subj to request in progress FELTON, J M Division of Rules and Records 84/03/01 REYNOLDB, J Center for Lew in the Public Interest 2pp. 22592 331 24X Fiche: 50-275,84/03/01,8403090028
- 8403090032 Final response to FOIA request for five categories of documents re fecility. Forwards add1 documents listed on App A. FELTON, J M Division of Rules and Records 84/03/02, LYON, V F Lyon & Kurz 2pp 22592,333 24% Fiche. 50-382,84/03/02,8403090032
- identified by meny personnel/including GA documentation reviewers.

 * Louisiana Power & Light Co 84/03/02. NRC No Datailed Affiliation Given 2pp. 22592.336. 24X Ficha 50-382.84/03/02.8403090032.
- B403260116 FDIA request for five cetegories of documents re facilities BARNEB.C Affiliation Not Assigned 83/12/02, FELTON.J M Division of Rules and Records 1p 22763 333
- B403260123 Partial response to FOIA request for five categories of documents rs Kerr-McGee Dil Industriss.Inc Forwards documents listed on app. Review of addl documents subj to request continuing.

 FELTON.J.M Division of Rules and Records 84/03/02 BARNES, C. Affiliation Not Assigned 2pp 22763 334.
- --B403260129 Repts 660207 explosion dus to eccumulation of hydrogen gas, killing operator & injuring two other employees. Operation of thorium process line terminated WMLER, O.E. Kerr-McGee Corp. 66/03/03 PRICE, E.R. Atomic Energy Commission 2pp 22763.336
- --8403260136 Forwards investigation rept re 660207 sxplosion at facility Licensee evaluation of hexards involved in processing source matt should be reviewed. W/o stated encls.
 DUBINDENI, L. Atomic Energy Commission 66/08/02 PAGE, R O Atomic Energy Commission 4pp 22763 340
- --B40326014i Confirms that Enforcement Branch will not communicate w/licensee re compliance investigation rept Concerning explosion on 600207, No items of noncompliance noted during investigation
 PAGE.R. 9. Atomic Energy Commission 66/08/17 Atomic Energy Commission ip 22763;344
- --8403260148 Forwards Region IV 660729 memo re results of survey of licensee fecility at Cushing, OK. Licensee measurements, as reported in 660609 ltr, substantiated by Region IV findings RDY.W Atomic Energy Commission, 66/08/08 NUSSBAUMER, D A Atomic Energy Commission, ip 22763 345.
- --8403260153 Discusses certification of 660426 rept re disposition of BNH, per 9 Waller 660602 telcon Rept should indicate that contamination limits met in order for Commission to authorize transfer of facility, NUSSBAUHER, D. A. Atomic Energy Commission, 66/06/10 LAMBERTUS, H. Kerr-McGee Corp. 2pp 22763:348,
- ---8403260158 Confirms 660207 chemical explosion at Gushing, OK thorium processing plant; per 660207 telcon Investigation complete LAMBERTUS, H. Kerr-McGee Corp. 66/02/08 WALKER, N I. Atomic Energy Commission. 3pp. 22763, 352
- 8403280076 FDIA request for seven categories of documents HIATT-S L Ohio Citizens for Responsible Energy, 83/11/30 FELTON, J. M. Division of Rules and Records 1p. 22808: 243.

- 8403280080 Partial response to FOIA request for seven categoriss of documents Forwards App A documents responsive to Itsms 1, 2, 5, 6 & 7 of request NUREG-0386, "NRC Practice & Procedures Manual," presently being updated FELTON, J H Division of Rules and Records 84/01/17 HIATT, 8 Ohio Citizens for Responsible Energy 2pp 22808 244
- --B107200104 Rssponds to NRC request for legality of providing free transcripts of adjudicatory proceedings NRC may use funds appropriated by Energy & Water Development Appropriation Act 1981 to provide free hearing transcript to all parties VAN CLEVE.H D General Accounting Office B-200585 Bi/05/II Commissioners 4pp 22808 266
- --8403280081 Discusses costs of intervention & isgal authority to provide financial assistance to intervenors in NRC proceedings KELLER,R F General Accounting Offics 76/02/19 General Accounting Office 16pp 22808/246
- 8403280163 Second partial response to FOIA request for documents re NRC internel procedures or guidance for evaluating new generic requirements Forwards App A document App B documents available in PDR. Bearch for eddl documents continuing FELTON.J M Division of Rules and Records 84/02/17 WEISS.E R Union of Concerned Scientists 3pp 22789:351
- --8312150232 Outlines formel NRR procedures to ensure timely feedback & closure on CROR reviews of generic issues developed by NRR Director's ofc will distribute mesting minutes to div directors
 DENTON, H R Office of Nuclear Reactor Regulation, Director 83/12/06 EISENHUT, D. G. Division of Licensing 2pp 22789, 355
- 8403280146 FOIA request for rediation source or dsvics registration certificates issued to JL Sheperd & Assoc & Alpha Omsga & application for device registration from JL Bheperd HAMMITH. H.A FOI Services 3469 84/02/07 FELION, J M Division of Rules and Records ip. 22807 203
- 8403280167 Responds to FOIA request for radiation source or device registration certificates issued to JL Sheperd & Assoc & Alpha Umage Forwards certificates Application for device registration available from State of CA Dept of Health Svcs FELTON, J M Division of Rules and Records 84/02/22 HANMITT, H. FOI Services ip. 22807:204
- --8403280170 Registry of radioactive sealed sources & devices, safety symbologic of calibrator mfg by JL Sheperd & Assoc using 13.500 mCi Cs-137 in Merk IV TL desimeter irradiator * NRC No Detailed Affiliation Glysn CA598D1055 80/05/07 3pp. 22807 205.
- ---8403280174 Registry of radioactive sealed sources & devices, safety avaluation of instrument calibrator & gamme irradiator mfg by JL Shsperf & Assoc using various sseled source model designations containing 300 Ci Cs-137 & 33 Ci Co-60 ** NRC No Detailed Affiliation Given CA59801060 B0/06/23 4pp. 22807 208.
- --8403280177 Amended registry of radioactive scaled sources & devices, safety eveluation of instrument calibrator & gamma irradiator mfg by JL Shaperd & Assoc using various scaled source model designations containing Cs-i37 & Co-60 ** NRC No Detailed Affiliation Given CA598D107U 83/01/31 4pp. 22807 212
- --8403280182 Amended registry of radioactive sealed sources & dsvices, safety evaluation of calibr range mfg by JL Sheperd & Assocusing sources in 78 or 28 series calibrators containing 440 Ci Cs-137

 NRC No Datailed Affiliation Given CA59801080 83/01/31 3pp 22807-216.
- --8403280185 Registry of redicactive sealsd sources & devices, safety evaluation of neutron detector calibrator mfg by JL Shaperd & Assoc using Monsanto 27228 258,27278 & 2765 containing FU-238/Be, Am-241/Be & Cf-252 ** NRC No Detailed Affiliation Given CA5980107U 80/10/06 3pp 22807; 219.
- --8403280188 Rsgistry of radioactive sealed sources & devices, safety evaluation of portable calibrator mfg by JL Shsperd & Assoc using Industrial Reactor Lab Sarias 2,3M CO 4P6E & Isotope Products Lab 193 containing 390 mCI Cs-137
 WONO, G J NRC No Detailed Affiliation Givsn. CA59801108
 81/06/29, 5pp 22807, 222
- --8403280191 Registry of radioactive stailed sources & devices, safety evaluation of gamma irradiator mfg by JL Shaperd & Assoc using JL Shaperd & Assoc Hodel 7810 & Gamma Industries Typs VDHP (ANSI 46515) containing 4,011 Ci Co-60. ECKBERO: B R. NRC No Detailed Affiliation Given CA598D1138, 83/09/21 App 22807 227

- --8403280197 Registry of radioactive sealed sources & devices, safety evaluation of dosimeter calibrator mfg by JL Sheperd & Assoc using Isotope Products Lab Beries 2.1sotope Products Lab Hudel 225 & 3M Co Model 4F&E containing 25 mCi Cs-137 HONO.0 NRC No Detailed Affiliation Diver CA598D1129 B2/12/02 6pp 22807 203
- 8403280211 FDIA request for documents re falsification of OA/QC records by M Annas at facility
 BELL.N Nuclear Information & Resource Service 84/01/05 Office of Administration 2pp 22799 324 24X Fiche 30-482.84/01/05.8403280211
- 8403280216 Partial response to FOIA request for documents re falsification of GA/GC records by M Annas at facility Forwards App A documents Documentation also available in PDR FELTON, J M Division of Rules and Records 84/03/07 BELL.N Nuclear Information & Resource Service 2pp 22799 328 24X Fische 50-482,84/03/07.8403280216
- ~-8403280225 Discusses review of closed & open files re alleged falsification of traveler records A Dauthier "spread sheet" shows Files 82-10 & 82-13 as closed & assigned to J Sinclair Region IV had nothing in files.

 BONERS: H Office of Inspector & Auditor 83/03/16 CUMMINGS: J Office of Inspector & Topic 10 22799 330 24X fiche 50-482.84/03/07.8403280216
- --8403280229 Forwards 1E investigation rept re facility.per telcon request M/o encl. CUMMINOS.J. J Office of Inspector & Auditor 82/01/12 MORRISSETTE, K. Justice, Dept of 1p 22799 331 24X Ficho 50-482.84/03/07.8403280216
- --8403280235 Responds to Region IV 810722 & IE 811016 memos re improper duplication of safety-related pipe banger DOJ contacted & advised that no objection raised to IE issuing investigation rept SCHNC-DELEN, A Office of Inspector & Auditor B1/12/23 THOMPSON. O Enforcement & Investigation Staff (Pre 820201) ip 22/79 332 24% Fiche 50-482.84/03/07,8403280216
- --8403280240 Discusses improper duplication of safety-related pipe hanger K Horrissette, DDJ, apprised on 811208 of contents of Region IV investigation rept re Pabrication of safety-related pipe hanger DDJ had no objections to rept issuance SINCLAIR.J R Office of Inspector & Auditor BI/12/23 Office of Inspector & Auditor BI/12/23 Office 84/03/07.8403280216
- B403270002 Final response to FOIA request for four categories of documents, tests, studies & analyses referencing or pertaining to NURCO-0103, "SIS for OM PWR " App A documents and I FELTON, J. M. Division of Rules and Records 84/01/13 MADDEN, T. J. Kaye, Scholer, Fierman, Hays & Handler Spp 22816 127 24X Fiche 50-000, 84/01/13, 8403270002
- --8403270004 Speech entitled "RCPB Leakage Detection Sys "
 POMERGY.D L. Atomic Energy Commission. Directorate of Regulatory
 Operations 84/01/13 Spp 22817 003 24% Fiche 50-000.
 84/01/13-8403270002
- --8403290006 Discusses 730115 Draft 2 of proposed safety guide entitled.
 "RCPB Leakage Detection Sys "
 ROGERS.L. Atomic Energy Commission Directorate of Regulatory
 Standards 73/01/17 SHAW.M Atomic Energy Commission 1p
 22817 008
- --8403290007 Forwards draft safety guide re leakage detection sys Guide suitable for publication PAMLICKI,8 8 Atomic Energy Commission - Directorate of Regulatory Standards 72/03/16 MINSGUE,R Atomic Energy Commission -Directorate of Regulatory Standards ip 22814 135
- --B403290009 Discusses Reg Quide 1 43 re RCPB leakage detection sys k rept on leakage observed at plant in Germany PORSE: t Atomic Energy Commission - Directorate of Regulatory Standards 73/05/17 MURLEY, T E Atomic Energy Commission 1p 22817 009
- --8403270010 Draft safety guide. "RCPB Leakage Detection " * Atomic Energy Commission 72/03/15 9pp 22816 136,
- --8403270011 Requests comments on encl Draft 2 of safety guide to RCPB leakage detection sys by 730119
 PORSE.L Atomic Energy Commission. 73/01/15 PAHLICKI, S 8., KLECKER.R W. HAASS.H P Atomic Energy Commission 2pp 22817 010

- --8403290012 Forwards Surveillance & Noise Diagnostics Program Planning 750607 meeting minutes FARMER, W.S. NRC - No Detailed Affiliation Given 79/06/26 BROWN, E. JABBUUR, K. NRC - No Detailed Affiliation Given HENDERSON, J. Office of Inspection & Enforcement, Office of the . Director Sopp 22816 145
- --8403290014 Draft 2 to safety guide. "RCPB Leakage Detection Sys "
 * Atomic Energy Commission 73/01/15 11pp 22917 012
- --8403290016 Forwards Draft 1 to 721219 proposed safety guide entitled, "RCPB Leakage Detection Sys " W/o enci ROGERS.L. Atomic Energy Commission Directorate of Regulatory Standards 72/12/20 FRALEY.R F Atomic Energy Commission. 1p 20817 023
- --8403290018 Notification of 730110 meeting w/ACR8 Subcommittee on Sefety Guides in Mashington.DC to discuss Draft 1 of 721219 proposed rsg guides re RCP8 leakage detection sys ARLOTTO.C A Atomic Energy Commission - Directorate of Regulatory Standards 73/01/04 ROGERS-L Atomic Energy Commission -Directorate of Regulatory Standards 1p 22817 024
- ---8403270020 Discusses draft safety guide re RCPB leakage detection sys Editorial changes suggested PORSE: L Atomic Energy Commission - Directorate of Regulatory Standards 72/12/04, ARLOYTO, 0 A Atomic Energy Commission. 4pp 22817-025.
- --8403290021 Task II B.Draft 3 to proposed rule requiring inerting of Mark I to II containment structures & hydragen control measures to deal w/accident conditions involving large amounts of hydrogen generation in BHR containment vessels w NRC No Detailed Affiliation Given 60/03/05 12pp.
- --8403290022 Summarizes comments on seismic qualification for leakege detection instruments & equipment PORSEL Atomic Energy Commission Directorate of Regulatory Standards 72/11/10 ARLOTTO, Q A Atomic Energy Commission opp 22817,029
- --8403270023 Forwards ballot change re 1SA draft 8td 67 03.Rev N,
 "8td for Light Water Power RCPB Leek Detection"
 WENZINGER.E C Office of Standards Development, Director,
 80/12/10 Instrument Society of America 1p 22816:213
- --8403290024 Requests assistance in reviewing draft safety guide,
 "Leakage Petertion Sys."
 MINOGUE,R. B. Atomic Energy Commission Directorate of Regulatory
 Standards 72/09/28 HANAUER, 8 H., KRUEBI, F. E., HENDRIX, J. M.
 Atomic Energy Commission ip 22817.035.
- --8403270025 Forwards positive bellot re draft 5td 67 03.Rev N, "8td for Light Water Power RCPB Leak Detection"
 HENZINGER.E C Office of Standards Development, Director 80/11/03 Instrument Society of America ip. 22816, 214
- --B403290028 Discusses proposed safety guide, "RCPB Leakege Detection" Comments & decision on whether to proceed w/guide requested PORSE: L Atomic Energy Commission Directorate of Regulatory Standards 72/04/25 ARLOTTO: Q A Atomic Energy Commission 2pp 22817 036
- --8403290031 Advises that draft sefety guide forwarded to S Pawlicki, R Klecker & D Pomeroy to enlist preliminary comments prior to formal request for review & comments, PORSE, L Atomic Energy Commission Directorate of Regulatory Standards 72/09/25 Atomic Energy Commission Directorate of Regulatory Standards 1p #2817 038
- ~-8403270034 Discusses Reg Guide 1 45.18A draft Std S67.03 & ANSI draft Std N 41 21 Suggested items clarifying reg guide listed.
 MCQUEEN, M M Affiliation Not Assigned 77/07/29 Atomic Energy Commission Directorate of Regulatory Standards. 15pp. 22817 039
- --B40329D035 Requests comments re 18A draft Std 67 03, Rev N, "Std for Light Water Power RCPS Leak Detection." Response requested by 801001 Related documents encl.

 MDR015UN.W M Assistant Director for General Engineering Standards 80/08/22 MURLEY.T E. Office of Nuclear Regulatory Research. Director MUSELEY.N C Division of Reactor Operations Inspections THORNBURG.H D Division of Reactor Construction Inspection 82pp 22816 220
- --B403290036 Distustes ray to Reg Quide 1 45 re RCPB leakage detection sys PORSE, L. NRC - No Detailed Affiliation Given, 79/02/26, ANDERSON, W.F. NRC - No Detailed Affiliation Given, 4pp. 22817 054

- ---8403290040 Discusses Rev i to Reg Guide 1 45, "RCPB Leak Detection Bys " Decision to revise reg guide not yet made PORSEL. Atomic Energy Commission - Directorate of Regulatory Standards 74/10/07 Atomic Energy Commission - Directorate of Regulatory Standards Ip 22816 302
- --B403290041 Forwards ISA draft Std S67 03.Rev K(11) & ballot on std Recommends 867 03 be adopted as replacement for Reg Guide 1 45 ROSZTOCZY, Z R Analysis Branch 79/01/19 TEDESCO, R L Assistant Director for Reactor Safety 172pp 22817 05B
- --B403290044 Discusses study of primary sys leakage detection monitors Related info encl FAIRTILE.M B Atomic Energy Commission 71/09/10 PAWLICKI,S Atomic Energy Commission 96pp 22817 230
- --8403290045 Discusses Q Reed 730301 ltr to Q Arlotto re RCPB leakage detection sys Method for detecting slow departure from normal indications of leakage detection sys provided in util monitoring charts
 PURSE, L. Atomic Energy Commission Directorate of Regulatory Standards, 73/03/09 WICHMAN, K. Atomic Energy Commission 2pp 22816-303 24% Fiche 50-000,84/01/13.8403290002
- --8403290046 Bubmits proposed response to SH Bush 730310 comments on guides reviewed at ACRS Bubcommittee on Leakage Detection Bys & Loading Combinations Feb 1973 meeting WICHMAN.K R. Atomic Energy Commission Directorate of Regulatory Standards 73/03/20 WICHMAN.K R. Atomic Energy Commission Directorate of Regulatory Standards 4pp 22817 326
- --8403270048 Notifies of ANSI-N274 committee meeting to include requirements of App J in ANSI Std N45 4 Related info encl ARLDITO.0 A Atomic Energy Commission Directorate of Regulatory Standards 74/04/18 TEDESCO.R L Atomic Energy Commission, Directorate of Licensing MACCARY.R R Atomic Energy Commission, Deputy Director for Technical Review (Pre-1775) GRIER, B H Atomic Energy Commission, Directorate of Regulatory Operations 4pp 22816 305
- --8403270047 Forwards info describing RCS leakage monitoring. Related info encl REED, O A Wisconsin Electric Power Co 73/03/01 ARLOTTO, G Atomic Energy Commission - Directorate of Regulatory Standards 40pp. 22817 330 24X Fiche 50-000, 84/01/13, 8403270002
- --8403270051 Forwards FR notice of issuance & availability of six reg guides classified as power reactor guides ROGERS.L. Atomic Energy Commission - Directorate of Regulatory Standards 73/05/21 KARAS.F.W. Atomic Energy Commission ip 22816-313
- --B403290052 Forwards listed info re NUTEC moisture leak detection sys Sys applications considered at various facilities include piping of ECCS & welds of main steam lines TELLOCK.H C Nutec. Inc 72/07/14 PORGE, L Atomic Energy Commission - Directorate of Regulatory Standards 229pp 22818-008.
- --8403290054 Notice of issuance & availability of six reg guides, including Reg Guides 1 43 re stainless steel weld cladding of low alloy steel components & 1 44 re control & use of sensitized stainless steel ROSERB.L Atomic Energy Commission Directorate of Regulatory Standards 73/05/18 5pp 22816 314
- --B403270055 Comments on Reg Ouids 1 45,RCPB leakage detection sys Editorial changes suggested KEELEY,0 8 Consumers Power Co KEEL 115-73 73/07/18 Atomic Energy Commission ip 22818-237
- --B403270058 Forwards draft reg guide. "RCPB Leakage Detection Sys." for comment Comments will be incorporated into guide prior to issuance ROGERB, L. Atomic Energy Commission Directorate of Regulatory Standards 73/03/19 RAMEY Atomic Energy Commission ip
- --8403290059 Comments on Reg Guide 1 45. "RCPB Leakage Detection Sys "Calibr of leakage detection sys during shutdown sufficient Related info encl SALVATORIAR, Westinghouse Electric Corp NB-RS-112 73/12/12 MUNTZING-L.M Atomic Energy Commission Directorate of Regulatory Standards. 23pp 22818 238.
- --840327006i Discusses issuance of six reg guides categorized as power reactor guides Ouides delineate techniques used to evaluate problems or postulated accidents & provide guidance re info needed in review Documents encl
 ROGERS.L Atomic Energy Commission Directorate of Regulatory Standards. 73/05/21 BAUSER,E J Congress (Joint & Rotating Committees, etc.). 14pp 22916-320

- --B403290063 Discusses comments on reg guide re RCPB leakage detection sys PORSE.L Atomic Energy Commission - Directorate of Regulatory Standards 73/04/04 WICHMAN.X R Atomic Energy Commission ip 22814 334
- --8403270065 Comments on guides reviewed in Feb by ACRS Subcommittee on Leakage Detection Sys & Loading Combination Secondary effects (thermal) from transients may cause valve body distortion & ampair aperability
 HICHMAN.K R Atomic Energy Commission Directorate of Regulatory Standards 73/03/20 ARLOTTO,6 A Atomic Energy Commission 2pp 22816-335
- --8403270068 Lists proposed reg guides that Engineering Stds Branch plans to submit to ACRS Safety Guide Subcommittee for consideration at Feb meeting ARLUTTO.6 A Atomic Energy Commission - Directorate of Regulatory Standards 73/01/26 DURNS,W ACRS - Advisory Committee on Reactor Bafeguards ip 22816 337
- --8403290070 Marked-up Draft 2 to safety guide, "RCPB Leakage Detection Sys" * Atomic Energy Commission 73/12/26 14pp 22816 338
- ~-8403290073 Forwards Draft 1 to proposed safety guide entitled, "RCPB Leakage Detection Sys," dtd 721219 RCOCRS, L Atomic Energy Commission - Directorate of Regulatory Standards 72/12/20 FRALEY, R F NRC - No Detailed Affiliation Given 1p 22816 352
- --8403270075 Draft 1 to safety guide, "RCPO Leakage Detection Sys "
 * Atomic Energy Commission 72/12/19 12pp 22816 353
- 8403290334 FOIA request for contract & mods resulting from RFP RS-RES-83-023 DAVIS.K L Trammell, Chase, Lambert & Martindale 84/02/14 Office of Administration 1p 22018 273
- 840329033B Responds to FOIA request for contract & mods resulting from RFP RS-RES-83-025 Forwards documents listed on app Dacuments also available in PDR FELTON.J M Division of Rules and Records 84/03/05 DAVIS.K L Trammell. Chase, Lambert & Martindale 2pp 22018 274
- --8403290342 Advises that contract performance may exceed current funding.per Hod 13 to Contract NRC-04-82-102 ENSA unable to obtain firm price for disposal of radwaste HAASS.M APFILiation Not Assigned NRC-04-82-013 B4/02/14 GUSTAVE.R NRC -- No Detailed Affiliation Given ip 22818 276
- --8403270343 Ltr Contract NRC-04-84-i02, "Structural Integrity of LWR Boundary Components - II," awarded to Matla Engineering Assoc.inc MORTON.X V Technical Assistance Contracts Branch NRC-04-84-i02 84/02/10 GREENBLATT.M Materials Engineering Associates, Inc 77pp 22818 279
- 8403290341 Responds to FOIA request for records re facility Ltr dtd 840117 failed to meet criteria for waiver of reproduction costs Forwards App A documents Address of Phoenix LPDR listed FELTUN.J M Division of Rules and Records 84/02/27 RYAN,J A Streich, Lang, Weeks & Cardon 3pp 22815 018 24x Fiche 50-528.84/02/27,8403290341
- --8403290344 NUREG-75/022

 DRAFT ENVIRONMENTAL STATEMENT RELATED TO CONSTRUCTION OF PALD VERDE NUCLEAR GENERATING STATION.UNITS 1,2 & 3 Docket Nos 50-528,50-529 & 50-530

 # Office of Nuclear Reactor Regulation, Director 75/04/30 175pp 22815 301 24X Fiche 50-528,84/02/27.8403270341
- GEN TEC 18 GENERIC TECHNICAL ISSUES
- B312070358 Notification of CROR Meeting 31 on B3i123 to review exemption from CROR review of Unresolved Safety Issue A-1 "Water Hammer" & proposed rev to Reg Guide 1 28, "GA Program Requirements (Design & Const)"

 BTELLO,V Committee to Review Generic Requirements 83/ii/10 MATTSON,R J Office of Nuclear Reactor Regulation, Director JORDAN,E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM,R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22481 332

- 8401250468 Forwards engineering evaluation rept, "Temporary Loss of All AC Power due to Relay Failures in Diesel Generator Load Shedding Circuitry "Practice of running emergency power sources in parallel w/offsite power sys may be prevalent HELTERES.C. J. Director's Office 84/01/06 DENTON, H. R. Office of Nuclear Reactor Regulation. Director 3pp 22437 349 24X Fiche 50-267.84/02/21,8402270004
- 8403010279 Responds to FOIA request for 8ECY-83-288 to be placed in PDR Forwards SECY-83-288 Document also available in PDR FELTON, J M Division of Rules and Records 83/12/16 PEDRO, J NUS Corp ip 22449 138
- --8403010283 Comments on SECY-83-288 re proposed rule on pressurized thermal shock Proposed rule should address CP applicants in addition to OL applicants & operating reactors Schedule for preparation of plant-specific safety analyses acceptable ZERDE, J E Office of Policy Evaluations 83/08/01 PALLADINO, OILINSKY, ROBERTS Commissioners 4pp 22449.222
- B4030(0477 Rasponds to B401)3 ltr re release of radioactive matl into atmosphere & embrittlement of containment shells in older nuclear gower plants & capability of containment structure to withstand pressurized thermal shock DENTON, H R Office of Nuclear Reactor Ragulation, Director B4/02/15 AMBORD, D A Affiliation Not Assigned. 3pp 22436 300
- B4030203i3 Forwards add1 comments to Ouidelines 5a.7a & 7b of technical evaluation rapt in response to NRC 820630 ltr re control of heavy loads.per Generic Ltr 81-07 MILLS.L M Tennessee Valley Authority QL-81-07. B4/02/28 ADENSAM.E Licensing Branch 4 iipp 22439 190 24X Fiche: 50-327.84/02/28,84030203i3
- 840303D020 Responds to FDIA request for documents ra PABNY submittal on sys interactions repts evaluating submittal & list of rapts/analyses from LLL avaluating PASNY sys interaction program Forwards App A documents
 FELTON.J M Division of Rules and Racords 83/12/07 8H0LLY, 8 Union of Coherned Scientists App 22525 098 24X
 Fichs 50-000,83/12/07,8403050020
- --8308040003 Forwards proposed test for ltr to PASNY requesting info for sys interaction methodology studies. Timing for receipt of documents critical to plan for resolving Unrasolved Bafety Issue A-17 Expedited transmittal requested THADANI.A C Reliability & Risk Assassment Branch 83/06/14 VARGA.S A Derating Reactors Branch 1 1p 22525 198 24X Fiche 50-000.83/12/07.8403050020
- --8403050023 "Diagraph-Hatrix Application on Indian Point 3 for Sys Interactions," statement of work Related info encl # NRC - No Detailed Affiliation Olven FIN A-0445 20-19-50-51-5 83/12/07 33pp 2255 111. 24X Fiche 50-000,83/12/07.8403050020
- --8403050024 Draft "Evaluation of Indian Point 3 Sys Interaction Analysis Program" * NRC - No Detailed Affiliation Given 82/02/20 7pp 22525 104 24X Fiche: 50~000,83/12/07,8403050020
- ---B403050034 Discusses 791115 meating re ACRS 1tr on Indian Point 3 sys interactions SCHWENCER, A Deprating Reactors Branch 1 (Pre B00428), 79/12/05 EISENHUT, D 9 Division of Operating Reactors, 2pp 22527 147 24X Fiche 50-000,83/12/07,8403050020
- B403070135 Brief on conflict posed by legal requirement of timeliness & equitable considerations ASLB should issue ruling allowing patitioners contentions that address new fuel core design, changes in Tech Specs & reduction in safety margins HODDER, H H Center for Nuclear Responsibility OLA 84/03/03 11pp 22338 265 24X Fichs 50-250,84/03/03,8403070135.
- --8403070143 Forwards applicant 830325 ltr w/encl re util pressurized thermal shock & flux reduction program per 840228 request. W/o ltr HODDER: M H HODDER: M H Center for Nuclear Responsibility OLA 84/03/03 Atomic Safety and Licensing Board Panel. 7pp 22538:278 24X Fiche 50-250,84/03/03.8403070135
- 8403080020 Forwards integral neutron source data for avaluating k verifying flux reduction per 84117 request. Data for Cycla 9 core octant time avaraged relative power density, critical weld praking factor & perigheral assembly pin power and HILLIAMO.J. W. Florida Power & Light Co. L-84-34. 84/03/01 VARGA.S A Operating Reactors Tranch 1 10pp 22359; 229 24X Fiche 50-250,84/03/01.8403080020

- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents. App B document entirely withheld (ref FDIA Exemption 3) Review of add1 documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERBON. S I, Garvey. Schubert, Adams & Barer 7pp 22383 226 24X Ficha 50-000.84/02/13.8403080179
- --8303100476 Forwards util 830223 submittal in response to telcon during which remaining Phase 1 open items of "Control of Heavy Loads Case Reviews." were discussed W/o encl CLEMENBON, F Auxiliary Bystems Branch NRG-20-18-388, 83/02/28 8TICKLEY, T M. E080, Inc. 19 22583 360 24X Fichs 50-000,84/02/13,8403080179
- 8403120081 Forwards safety avaluation re Sections 5 i 1 & 5 3 of NUREQ-0612, "Control of Haavy Loads at Nuclear Power Flants " Ouidelines satisfied Phase I acceptable JOHNSON, E. H. Region 4. Office of Director 84/03/06 LEE, O. R Public Service Co of Colorado 2pp 22590:168 24X Fiche, 50-267, 84/03/06, 8403120081
- --8403120086 Bafety evaluation re NUREO-0612, "Control of Heavy Loads," Phase I Guidelines satisfied Roll of Heavy Loads," NRC No Detailed Affiliation Given 84/03/06. 2pp. 22590 170 24X Fiche 50-267, 84/03/06,8403120081
- --8402280725 E00-H6-6274 RO3
 "Control of Heavy Loads at Nuclear Power Plants, Fort St
 Vrain Nuclear Generating Station, Phase I, * technical
 evaluation rept
 STICKLEY, T H E080, Inc FIN A-6457 84/01/31, NRC No
 Detailed Affiliation Given 27pp. 22570, 172 24X
 Fiche 50-267, 64/03/05, 8403120081
- 8403130190 Forwards response to MRC 801222 request for review of controls for handling heavy loads as committed to in 830809 ltr Response to items in Section 2.1 of 801222 ltr also encl BOOKER, J E Gulf States Utilities Co R89-17168 64/03/01. DENTON, H R Office of Nuclear Reactor Regulation, Director, 63pp. 22606-063 24X Fiche 50-458.84/03/01.8403130190
- 8403140017 Clarifies Sept 1983 draft technical evaluation rept of Phase 11 submittal of control of heavy loads, per 840107 telcon. Safe load paths for reactor bldg closed loop cooling water pumps revised MCCAFFREY, B R Long Island Lighting Co SNRC-1012, 84/03/05 DENTON, H R Office of Nuclear Reactor Regulation, Diractor. 4pp 22633 218 24X Fiche 50-322,84/03/05,8403140019
- B403140191 Forwards technical guidelines required by NUREO-0737.
 Suppl 1.including guidance on station blackout conditions
 (Unresolved Barety Issue A-44), to be considered as response
 to Generic Ltr 81-04.
 CODK.K W Louisians Power & Light Co. W3P84-0494 84/03/05
 KNIGHTON.C W Licensing Branch 3 337pp 22621 001 24X
 Fiche D0-382,84/03/05,8403140191
- B403140279 Forwards request for add1 info re control of heavy loads Response requested within 60 days HILLER, J R Operating Reactors Branch 3 84/03/06, QRIFFIN, J. H. Arkansas Fower & Light Co 2pp 22635 327, 24X Fiche 50-313,84/03/06,6403140299.
- 8403160131 Forwards draft "Status of Vessel Failure Mode Analyses Feasibility Study & Preliminary Evaluations," to satisfy agreement reached during NRC 840112 meeting w/BNML PEDERSON,L T Battelle Memorial Institute, Pacific Northwest Laboratories FIN 8-2510, 84/02/24 MODDS,R. Generic Issues Branch 163pp. 22662 324
- 8403190002 Notifies of CRQR Meeting 45 on 830817 to discuss results of NRR study of electromagnetic pulss & proposed exemptions from regulations in implementation of Multi-Plant Action D-10 (Unresolved Issue A-2)
 8TELLO, V. Committee to Review Generic Requirements 83/08/04 MATTSDN, R.J. Division of Systems Integration (post 81005).

 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) CUNNINGHAM, R.E. Office of Nuclear Material Safety & Safeguards, Director 3pp 22664; 347.
- 8403170031 Notifies of CRGR Maeting 44 on 830802 in Betheeds, ND to discuss NUREG-0978; re behavior of BMR Mark III containment & commission paper re integrated safety assessment program STELLO, V. Committee to Review Generic Requirements, 83/07/22. MATSON, R. J. Division of Systems Integration (post 81005), JORDAN, E. L. Division of Fuel Cycle & Material Safety. 2pp. 22464-113

i

NONDOCKETED ITEMS

- 8403170037 Notifies of CROR Meeting 43 on 830727 in Bethesda.MD to discuss Unresolved Safety Issue A-12. "Steam Generator & Reactor Coolant Pump Bupport Toughness" & Generic Issue B-56 re discel penerator requirements
 STELLO.V Committee to Review Generic Requirements 83/07/18
 NATISON.R J Division of Systems Integration (post Bil005)
 JORDAN.E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 2pp
- 8403170081 Notifies of CROR Meeting 57 on 840328 in Bethesda, MD to discuss proposed resolution of Unresolved Safety Issue A-44 re station blackout & Generic Iesue B-56 re diesel generator reliability BTELLO. V Committee to Review Generic Requirements 84/03/14 MATTSON.R J Office of Nuclear Reactor Regulation, Director JORDAN.E L Director's Office. Office of Inspection and Enforcement CUNNINGHAM.R.E. Office of Nuclear Material Bafety & Bafeguards, Director ip 22667 362
- B403190103 Notifies of CR0R Meeting 60 on B40411 to discuss activities of NRC Piping Review Committee & proposed resolution of Generic Issue A-30. "Adequacy of Sefety-Related DC Power Bupply "
 BTELLO,V Committee to Review Generic Requirements 84/03/14 MATTSON:R J Office of Nuclear Reactor Regulation, Director JORDAN.E.L Director's Office, Diffice of Inspection and Enforcement CUNNINGHAM,R E Office of Nuclear Material Bafety & Bafeguards, Director. 2pp. 22669 310
- B403190146 Notifies of CROR Meeting 47 on B30923 in Bethesda, MD to discuss proposed exemptions to regulations in implementation of Multi-Plant Action D-10 (Unresolved Bafety leeve A-2) & Rev 2 to Reg Ouide 1,105
 BIELLO, V Committee to Review Generic Requirements B3/09/15
 MATTBON, R J Office of Nuclear Reactor Regulation, Director JORDAN, E L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Bafeguards, Director 2pp 22666 359.
- B403190171 Response to petitioners B40303 brief re consolidating two eets of license amends issued in late 1983 in support of naw fuel essemblies ABLB ehould confine proceeding to B41007 emende.

 BAUSER, MA Florida Power & Light Co. BAUSER, M.A Newman & Holtzinger DLA 84/03/14 Atomic Safety and Licensing Board Fanel. 15pp 22670 265 24X Ficher 50-250, B4/03/14 B403190171
- --8403190179 Affidavit of DC Poteralski on patitioners 840303 brief reconflict posed by legal requirement of timelinees & equitable conedierations Util 830720 amands not part of pressurized thermal shock program W/Certificate of 8vc PDIERALSKI, D C Florida Power & Light Co A-49 84/03/09 i7pp 22670:280, 24X Fiche 50-250.84/03/14.8403190171
- 8403200005 Responds to 840227 request for add1 action to varify aspects of overhead crane design at facility.per NUREO-0612 guidelines. Crane safety & reliability setisfectory OUCHA:L.T. Georgia Power Co NED-84-129 84/03/12, STOLZ, J F Operating Reactors Branch 4 2pp 22685 209 24X Fiche 50-321,84/03/12,8403200005
- B403200099 Forwards schedule for implementation of activities for control of heavy loads, per NRC requests re NUREQ-0612 Cask pit gate listing lugs will be modified by B41015
 HUKILL.H D General Public Utilities GPU Service Corp 5211-84-2072 B4/03/15 EIBENHUT.D G Division of Licensing 3pp 22685-313. 24X Fiche, 50-289, 84/03/15, 8403200099
- 8403200225 Advises that similarity of Unit 1 & 2 175-ton polar crans verified by noting that cranes purchased under eams contract w/same vendor, using identical procurement specs, per NUREO-0612 & 840223 telcon MILLES. H. Tennessee Valley Authority. 84/03/14 ADENSAM, E Licensing Branch 4. 2pp R2699-361 24X Ficha 50-390.84/03/14.
- 8403210029 Comments on proposed rule 10CFR50 re minimisation of thermal annealing requirements of App 0/Bection IV B re pressurized thermal shock Supports rule Requirements not needed FAY.C. W Wisconsin Electric Power Co 49FR4498 002 84/03/15 CHILK.B. J. Diffice of the Secretary of the Commission 2pp. 22704-1358.
- 8403210116 Forwards addl info re power distributions as part of pressurized thermal shock program to effect flux reduction; per 830930 submittal; in response to 840301 telcon ZINMERMAN,8 R Carolina Power & Light Co NLS-84-115 84/03/12 VARGA,8,A Operating Reactors Branch 1 3pp 22705 064 24x Fiche; 50-261,84/03/12,8403210116

- 8403220192 Forwards "Control of Heavy Loads, Phase II " Rept result of review of crane operation, design & maint including analysis of load drop risk to safety-related equipment beneath travel paths Confirms defense-in depth per NNEG-0612 WHITTIER, O D Maine Yankee Atomic Power Co GOW-84-33 84/03/19 MILLER, J R Operating Reactors Branch 3 2pp 22717 048 24X Fiche 50-309,84/03/19,8403220192
- --8403220199 "Control of Heavy Loads. Phase II"
 # Maine Yankse Atomic Power Co 2763L-SEN 84/03/19 124pp
 22717 050 24% Fiche 50-309.84/03/19.8403220192
- 8403220326 NUREG-0978 FC
 MARK IJI LOCA-RELATED HYDRODYNAMIC LOAD DEFINITION Genetic
 Technical Activity 8-10

 * Division of Systems Integration (post 811005) 84/08/29. 75pp
- 8403260212 Forwards revised info re monorail paths.updating util 840206 1tr responding to Generic Ltr 81-07 concerning NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants" Field investigation will be provided i month prior to fuel load. MILLS, L M Tennessee Valley Authority QL-81-07 84/03/20 ADENSAM, E Licansing Branch 4 2pp 22756 164 24X Fiche 50-390,84/03/20,8403260212.
- 8403290083 Responds to 840221 request for addl info re control of heavy loads Initial load testing performed for head strongback, dryer seperator sling & spent fuel cask yoke ZIMMERMAN.8 R Carolina Power & Light Co NL8-84-094 84/03/20 VASSALLO,D D Operating Reactors Branch 2 2pp 22806-325 24X Fiche 50-324.84/03/20,8403290083
- B403290110 Forwards J Preston B30104 memo re generic safety issues prioritization methodology for placement in PDR ROBERTS, B J ACRS — Advisory Committee on Reactor Safeguards 84/03/14 MCKNIGHT, J Distribution Services Branch ip 22822. 214
- --B40329013 Advises of review of generic safety issues prioritization methodology described in NUREG-0933 Inherent limitations of value impact score formula discussed Use of structured & iterative consensus judgement methodology recommended PRESTON.J ACRS Advisory Committee on Reactor Safeguards B3/01/04 BENDER.M ACRS Advisory Committee on Reactor Safeguards Safeguards 3pp 22022 215
- 6403290295 Provides justification why limiting use of 6-inch containment vent sys considered unnecessary Based on info provided vent sys demonstrated capable of performing intended isolation function under transient conditions MEDFORD, M O Southern California Edison Co 84/03/27 CRUTCHIFIELD, D Operating Reactors Branch 5 Spp 22600:037. 24X Fichs 50-206,84/03/27,8403270295
- 8403300288 Requests remittance of fee for review of 840210 rept summarizing available reactor vessel matts data in response to pressurized thermal shock concerns DIGGS.R M License Fee Management Branch 84/03/15 UkRIG.R E Florida Power & Light Co 1p 22844 329 24X Fiche 50-250. 84/03/15.8403200288

INSPECTION AND ENFORCEMENT

- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valva Control Circuits & Annunciation " Svc list enc!

 JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115p 22909 239 24X Fiche 50-000.84/02/28.8401190072
- 8401230630 Partial response to FOIA request for IE 800103 rept re review of meth false statement at facilities associated & supporting records to rept & repts prepared in response Forwarde App A documente Review of addi records in progress FELTON, J M Division of Rules and Records 83/11/01 WINSLOW, R Wall Street Journal 2pp. 21705 337
- --8401230660 PND-77-039 on 790305, investigation concluded that QA program for obtaining proper soil compaction of facility deficient excessive settlement observed w/dissel generator bldg & incorrect info re soil foundation contained in FSAR SHEWMAKER, R. E. Office of Inepection & Enforcement, Office of the Director 79/03/06 2pp 21905 352
- 8402090007 IE Info Natice 84-i4, "Highlights of Recent Transport Regulatory Revs by DDT & NRC." Svc list encl GRACE, JN Division of GA, Safeguards & Inspection Programs (Post 830103). 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552; 329 24X Fiche 50-000,84/03/02,8402090007.

- 8402090008 IE info Notice 84-16, "Failure of Automatic Sprankler Sys Valves to Operate " Svc list encl JORPAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50~000,84/03/02,8402090008
- B402090009 IE Info Notice B4-15. "Reporting of Radiological Releases" Svc list and JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402070009
- 8402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN,E t. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Concolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402070011
- 8402090024 IE Info Notice 84-07. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JARDAN. E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York. Inc. 118pp 22635 049 24X Fithe 50-000.84/03/07, 8402090024
- 8402090028 IE Info Notice 84-IB. "Stress Corrosion Cracking in PWR 8ys "Svc list encl JURDANNE L Bivision of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 IB& 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Releys in Use in Class IE Safety Sys " Svc list encl
 DEYOUNGR C Director's Office Of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 67245 275 24x Fiche 50-000.84/03/12,8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24% Fiche-50-000,84/03/21,8402090044
- 8402210133 PND-1-84-014 on 840111. New England Nuclear truck carrying radiopharms & research products ran off Interstate 90 No breakage or leakage of radioactive contents found & radiation levels within DDT requirements FRIEDMAN GLENN, J., JONNER, J. Region 8. Office of Director 84/02/13 1p 22314 318
- 8403010363 EN-84-005 on 840229, natice of violation & proposed imposition of civil penalties to be issued in amount of 440,000 Action based on five violations re open containment isolation valves CRAIG.J. AXELRAD.J Director's Office. Office of Inspection and Enforcement 84/02/24. 2pp 22433 0i3 24X Fiche. 50-287,84/02/24.8403010363.
- 8403010375 EN-83-069A on 84022B, suspension & order modifying license rescinded Action based on licensee responses to order to show cause Licensee & State of MY will be notified FLACK.F. AKELRAD.J. Director's Office. Office of Inspection and Enforcement 84/02/28 Ip 22434 083
- 8403020196 PNO-11-84-017 on 840227, power to plant lost due to power outage caused by high winds Licensee declared unusual event & initiated plant radiological contingency plan Backup power continued to function KAHLE.J B , MCALPINE.E J Region 2. Office of Director. 84/02/27 2pp 22439 001
- 3403020235 PNG-II-84-019 on 840228 trip occurred interrupting electric svc Caused by lightening errector failing on 230-tV line due to voltage transient sensed by reactor coolant pump power monitors Svc restored within 30 minutes R000E.J.F., PANCIERA, V Region 2. Office of Director 84/02/28 2pp P2440 079 24X Fiche 50-302,84/02/28,8403020235
- 403020238 PNO-11-84-020 labor contract w/lntl Brotherhood of Electrical Norkes expires at midnight on 840227 Possibility exists that workers will reject contract & not rept to work on 840302 Supervisory personnel will continue operations GRECNMANLE Region 2, Office of Director LIPINSKLD Region 1, Office of Director 84/02/29 ip 82440-093 24X Fiche-50-813,84/02/29,8403020238

- 8403020248 PNO-II-84-018 on 840227. Units shut down following failure of Siemena-Allis breaker to trip during functional test of 4-kV electrical breakers for nonsafety-related electrical bus 3C Insp & repair undarway
 DANCE.H C . LEMIS.R C Region 2. Office of Director 84/02/28
 2pp 22440-101 24X Fiche 50-250,84/02/28,8403020248
- B4030203ii PNO-1-84-019 on E40228.Region 1 advised of contamination at facility Decontamination activities halted until approved plan developed JOYNER-J Region i. Office of Director 84/02/29 2pp 22439 188
- 8403050074 EN-84-006 on 840302.notice of violation & proposed imposition of civil panelty in amount of \$8,000 to be issued. Action based on failure to equip two radiography rooms w/audible & visible alarms
 FLACK.E., AXELRAD.J Director's Office, Office of Inspection and Enforcement 84/02/28 lp 22488 064
- 8403060103 PNO-TMI-84-002 licenses pleaded guilty to one count of using incorrect procedure to determine RCS water inventory & nois contendere on six of remaining 10 counts, subj to final acceptance by court on 840227 FASANO.A. DARRETT, L. TMI Program Office 84/02/27 ip. 22517 018 24% Fiche 30-320,84/02/27,8403060103
- 8403060110 FND-TMI-84-003 on 840229, load test of reactor bidg polar crame scheduled Load test will qualify crame to lift 170 ton reactor vessel head NRC plans to continue monitoring events
 MUSLAK, T , GASANO, A . BARRETT, L THI Program Office 84/02/29
 22018 310 24x Fiche 50-320,84/02/29,8403060110
- B403060119 EN-84-008 on B40302, order to show cause & order temporarity suspending license issued Action based on B40223 contemination incident resulting from employee repackaging radewaste FLACK, E , AXELRAD, J Director's Office, Office of Inspection end Enforcement 84/03/02 lp 22516;327
- 8403060144 PNO-TM1-84-002A on 840229, court accepted licensee plea of guilty to one count of using incorrect procedure to determine RCS water inventory & plea of nolo contenders on six of remaining 10 counts
 FASAND, A. BARRETT, L. TMI Program Office 84/02/29 1p 22513 330 24X Fiche 50-320,84/02/29,8403060144
- 8403040215 PND-U-84-01i on 84022i, reactor trip breaker 8 undervoitage device inoperable Caused by metel shavings in one control room manual reactor trip pushbutton Dn 840228, four leads in piant protection sys cabinets found disconnected CANTER: H Region 5, Office of Director 84/02/27 ip 22517-230 24X Fiche 50-361.84/02/29, 8403050215
- 8403060435 PND-TM1-84-003A on 840229, qualification load test of reactor bldg polar craps completed Load test qualified craps to lift i70 ton reactor vessel head scheduled for summer MDSLAK.T. FASAND.A. BARRETT, L. TMI Program Office 84/03/01. ip 22511 362 24X Fichs 50-320,84/03/01,8403040435
- 8403070263 PNO-11-84-020 on 840301, radioagraphic tests confirmed feedwater nozzle crack indications on all three eteam generators Component replacements under active consideration IE & NRR informed BLAME, J J, BUTCHERIR C Region 2, Office of Director IEE-79-13, 84/03/02 2pp. 22547 298, 24X Fiche 50-348,84/03/02,8403070263.
- B4030702B3 PND-I-B4-021 on 840301 radiographer working at field site could not fully retract 24 1 Ci Ir-i92 to safe shielded position Caused by improperly connecting pigtail to guidetube Whole body dose read 40 mrem ROME. C. GLENN, J Region 1, Office of Director 84/03/02, 1p 22546 359 287 Fiche 50-293,84/03/02.84030702B3
- 8403080016 Further response to FOIA request for liste & records re Co-60 licensess Forwards App A documents, per Item 3 of request Portions of Documents 2 through 5 of App B deleted (ref FOIA Exemptions 6 & 7) FELTON, J ff Division of Rules and Records, 84/01/11 COWIE, D J Bouct, Holloway, Kiernan & Casey 5pp 22576,274
- --8403080170 PNA-81-004 on 810714-Louisians Nuclear Energy Div notified NRC of radiography incident occurring on barge located less than 3 miles offshore Barge captain & radiographer exposed to 11 Ci Cu-40. Medical attention obtained DDDA-R. J. Region 4. Dallas, Office of the Director (81/03/01), 81/07/21 2pp. 22577 130

- --8403080162 PNO-I-BI-033A on Bi0307, special insp conducted to determine extent of Co-60 contamination resulting from leaking radiography source Contaminated clothing found at employee residence will be treated as radwaste COSTELLD, F Director's Office, Office of Inspection and Enforcement KINNEMAN, J Region 1, Philadelphia, Office of the Director (81/03/01) 81/03/09 1p. 22577 129
- --8005010203 PNO-III-80-60 on 800318,25 mCi Co-60 sealed source under License 12-13720-01 fell into coke hopper Source believed to be in pile of coke in facility yard on barge heading for Chicago or in freight car bound for Shawinigan, Guebec SCHULTZ, W H, DAVIS, A B Region 3, Chicago, Office of the Director 80/03/25 ip 22576 279
- 8403080213 EN-84-007 on 840307, notice of violation & proposed imposition of civil penalties in amount of \$40,000 to be issued Action based on feilure to control access into vital area due to guard leaving post ROBAND, R, AXELRAD, J Director's Office, Office of Inspection and Enforcement. 84/03/02 ip 22560 021 24X Fiche 50-259,84/03/02,880380213
- 8403080293 PNU-III-84-017A several cracks discovered in steinless steel piping sections in LPCI sys & jet pump instrument seel Btainless steel sections & jet pump instrument seal lines will be replaced.

 DEFAYETTE.R. CHRIBBOTIMOS.N. SHAFER.W Region 3. Office of Director IEB-83-02 B4/03/01 ip 22560 i25. 24X Fiche. 50-263. 84/03/01.8403080223
- 8403080257 PND-III-84-012.on 840129. Campbell Pacific moisture/density gauge containing 10 mCi Cs-137 & 50 mCi Am-241 sealed sources stolen from back of pickup truck in Norwood.OH Suspect in custody LASUK.BR. AXELSON.W L. Region 3. Office of Director 84/01/30 lp. 22557.092
- B403090224 PNO-I-84-022 on 840303, reactor scremmed from 74% power Caused by fast closure of mein turbing control valve during surveillance on hydraulic detector. Buspect relays in detector test instrumentation replaced JACOBB, R. KELLY, E. Region 1, Office of Director 84/03/05 1p 22575 077 24% Fiche 50-387, 84/03/05, 8403090224
- 8403120063 Updeted PNO-V-84-OilA discovered manual pushbutton not imperable as result of metal shevings in contacts Only operability of undervoltage trip on RTB-8 affected Source of metal flakes undetermined DDDS,R T Region 5. Office of Director 84/03/05 ip 22586 288 24X Fiche 50-361,84/03/05,8403120063
- 840312007B Updated PND-III-84-020A three reactor depressurization system valves feiled. Caused by binding of disc in seat resulting from increase in closing air pressure Reactor restarted & in situ testing conducted DEFAYETTE, R. Region 3. Office of Director 84/03/04 ip 22586-305 24X Fiche DO-135,84/03/06,8403120078
- B40313020B PNO-I-B4-023 on 840306 worker repairing lights in turbine bldg sustained radioactive contamination on waist & head Incident investigated & critiqued. Corrective actions being reviewed by specialist.

 NIMITZ.R. L. BHANBAKY.M., BELLAMY.R. Region 1. Office of Director 84/03/07 1p. 22605-036. 24x Fiche 50-219.84/03/07,8403130208.
- 8403130235 PNO-III-84-023, on 840305. HPCI sys declared inoperable when surveillance test revealed excessive laskege on mein pump outboard bearing, During test of automatic depressurization sys, electromatic relief valve E failed to open, CHRISSOIIMOB.N. SHAFER, W. Region 3, Office of Director 84/03/06 ip. 22617:278, 24X Fiche 50-254,84/03/06,8403130235
- B403130275 PNO-III-B4-021:on 840302; MSIV closura tripped reactor Cause unknown Safety valve stuck open following pressure reduction Incident response ctr in standby mode JACKIM, I., BOYD, D. Region 3. Office of Director 84/03/02 ip. 22607:139 24X Fichs: 50-346,84/03/02,8403130275
- B403130310 PNO-III-B4-024; from B4013Q-0305, patient edministered B,700 rads to midline-brain rather than prescribed 6,000 rads Treatment stopped upon discovery of misadministration NRC medical consultant will review case.

 BIMMONS,T, SRENIAMKSI,D. Region 3, Office of Director. B4/03/07, ip. 22613 335
- 8403130336 PNO-III-84-021A on 840303 MBIV replaced & steam generator 2 refilled following 840302 reactor trip Generator isolated during refilling to protect against release of radioactivity in event of steam generator tube feilure,

 JACKIN I., BOYD, D. Region 3, Office of Director 84/03/05, 2pp, 22607:243. 24x Fiche 50-346.84/03/05,8403130336

- B403130379 PND-III-84-022 in response to IE Info Notice 82-29, exam identified 67 of 74 control rod drive support pins \(\omega/crack \) indications Licensee \(\omega-ck \) Westinghouse evaluating exam findings to determine required action
 \(\omega-ck \) JORDAN. M. JACKIW. I. SHAFER. N. Region 3. Defice of Director IEIN-82-29 84/03/02 ip 22616 092 24% Fiche 50-266, 84/03/02, 84/03/30379
- 8403130408 EN-84-010 notice of violation & proposed imposition of civil penalties in amount of \$2,000 will be issued on 840312 Action based on multiple failures to comply w/NRC requirements re radiation safety FLACKIE AXELRADJ Director's Office, Office of Inspection and Enforcement 84/03/07 ip 22616 050
- 8403130423 PND-III-84-0178 on 840308.during visual insp.four J nozzles on feedwater spangers of reactor vessel found cracked Decision on repair & replacement pending more detailed exam State of MN notified DEFAYETTE.R , WALKER,R , SHAFER,W Region 3, Office of Director 84/03/08 1p 22413 090 24x Fische 50-283,84/03/08,8403130483
- 8403130445 EN-84-009 on 840312.notice of violation & proposed imposition of civil penalty in amount of \$30,000 will be issued based on Failure of Tech Specs procedures re entry into locked high radiation area FLACK.Γ, AXELRAD.J Director's Diffice. Office of Inspection and Enforcement EA-009 84/03/07 2pp 22813 138 24X Fiche 50-261.84/03/07.8403130445
- B403130456 PND-I-B4-024 on B40306 during resin replacement operation, unplanned release of gaseous radioactivity occured Several workers slightly contaminated w/Rb-B8 No ectivity detected State of ME informed BICEHOUSE, H. SHANBAKY, M., BELLAMY, R. Region I. Office of Director B4/03/07 Ip 22613 329 24X Fiche 30-309, B4/03/07, B403130456
- 8403150073 EN-84-012 on 840313 notice of violation & proposed imposition of civil penalty in amount of \$40,000 will be issued to license Action based on violation of Tech Spacs re containment appray sys inoperability CRAIO.J. AXELRAD.J Director's Office. Office of Inspection and Enforcement 84/03/08 ip 22641 248 24X Fiche 50-247.84/03/08.840315093
- 8403150121 PNO-V-84-013 on 840307. Bechtel laborer suffered heart attack while working in auxiliary bldg Medical attention provided to individual at site Individual pronounced dead upon arrival at Sierra Vista Hosp DDDBR T Region 5, Office of Director 84/03/07 ip 22640 218 24% Fiche 50-275,84/03/07.8403150121
- 8403160001 EN-84-013 notice of violation & proposed imposition of civil penalty in amount of \$3,000 will be issued by 840315 re three violations concerning loss of well logging source FLACK, E. AXELRAD, J. Director's Office. Office of Inspection and Enforcement 84/03/12 ip 22655 209
- B403160039 PNO-II-84-021 crack indications identified in all 14 12-inch riser albows in replacement recirculation piping scheduled to be installed Caused by improper forming temps used during bending process.

 BLAKE, J. J., ROGGE, J. F. Region 2. Office of Director 84/03/12 2pp 22655 134 24X Fiche 50-366.84/03/12.8403160039
- B403160051 EN-84-011 notice of violation & proposed imposition of civil penalty in amount of \$20,000 to be issued Action based on failure to control access to vital area ROSAND.R., AXELRAD.J. Director's Office. Office of Inspection and Enforcement B4/03/0B ip 22652 019 24X Fiche 50-331.84/03/0B, 8403160051
- B403190013 PNO-III-84-025 on 840310 unit achieved initial criticality Agreement observed between actual conditions & predicted conditions MALKER, 8: BHAFER, W. Region 3: Office of Director 84/03/12 lp. 22665:353 24X Fiche: 50-374,84/03/12;8403190013
- 8403190091 PNO-III-84-026 on 840313, during insp to verify support plate integrity after tube-pulling activities, demage observed to auxiliery feedwater sparger piping in both steam generators Demage may delay May 1984 startup
 DEFAYETTE, R. BDYO, D. Region 3, Office of Director 84/03/13 ip 22669 227 24X Fiche: 50-235,84/03/13,8403190091
- 8403190135 PNB-I-B4-002 on 840312, bomb threat received from unidentified caller, Site emergency & safeguards contingency plan requirements implemented Public areas & site protected area searched w/negative findings.

 MADDEN, 8 . JUYNER, J Region 1, Office of Director 84/03/12 ip 22674 352 24X Fiche: 50-220,84/03/12,8403190135

- 8403;90284 PND-II-84-022 tircumferential crack found on one of four feedwater notices during exam of feedwater notices per NUREC-0691 Corrective action being evaluated Inspectors monitoring licenses work on regular basis CROMLEY, Br. PANCJERA-V Region 2, Office of Director 1p 22672 279 24X Fiche 50-356.84703/14.8403190284
- B4031702B5 PNO-I-84-025 on 840313 licensee found crack in emergency diesel generator 103 engine block between cylinders 4 & 5 Crack being investigated through use of eddy current ineptechniques
 PETRONE. C. EGELOROTH, P Region I. Office of Director 84/03/14
 Jp 22672 278 24X Fiche 50-322 84/03/14 8403190285
- B403190335 EN-84-014 on 840316, notice of violation & proposed imposition of civil penalty in amount of \$6,000 issued to licensee Action based on violations involving radiological occurrence w/potential for radiation exposures FLACK, E. AKELRAD. J. Director's Office, Office of Inspection and Enforcement B4/03/13 2pp 22675 027
- 8403190376 PNS-V-84-004 on 840314 licensee notified that results of chemical tests performed on contractor employees suspected of possession or use of controlled substances while onsite indicated positive in two of four tests.

 SCHWAN, C A: NORDERHAUGL R Region 5. Office of Director 84/03/15 ip 22675 216 24X Fishe 50-206.84/03/15.8403190376
- 8403200132 Updated PNO-V-B4-012A on 840304 radiographer received estimated 3 8 rems to whole body & 72 rems to left hand Caused by radiographer negligence Independent evaluation of incident in progress
 THOMAS.R D. PANO.J F Region 5. Office of Director 84/03/16 1p
- 8403200286 PNO-III-84-024A on 840130-0305, patient undergoing Co-60 teletherapy treatments received therapeutic radiation exposure to head 45% in excess of prescribed dose New procedure instituted Region III reviewing case SRENAHKKI, D. AXELSON, W. Region 3. Office of Director 84/03/15 2pp 22676 174
- 84032:0040 Updated PNO-J-84-021A on 840301.radiographer working at Pilgrim site received radiation overexposure of 550 millinems Caused by recoupling of source guide tube Enforcement action being evaluated ROME.C. KINNEMAN, J Region 1. Office of Director 84/03/05 19 22707 015
- 8403210133 PND-II-84-023 on 840312. State of 8C advised of possible overexposure of radiographer & assistant radiographer Caused by assistant radiographer performing duties as radiographer Exposures of 5,000 to 10,000 rem possible TROJANOMSKI.R. HOODRUFF.R.L. Region 2, Office of Director 84/03/16 2pp 22707:236
- 8403220075 EN-84-015: on 840320, notice of violation & proposed imposition of civil penalties in amount of \$180.000 will be issued to licensee Action based on failure to maintain tontainment integrity & failure to conduct surveillance CRAIG.J. AXELRAD.J Director's Office, Office of Inspection and Enforcement 84/03/15 2pp 22712 308 24X Fiche: 50-220,84/03/15,8403220075
- 8403230023 PND-111-84-027; on 840318, diver working on fuel assembly upender received radiation dose to right thigh of 45 rems Caused by licenses failure to identify localized high rediation field near upender GREGER, LR, PAPERIELLO, C. Region 3, Office of Director, 84/03/19 ip 22728 318 24X Fiche 50-255, 84/03/19, 8402230023
- 8403230074 FNO-I-84-026 on 840313; crack discovered in emergency diesel generator engine. Ultrasonic & eddy current examindicated crack depth of 1 inch & length of 2 inches. State of NY informed PETRONE. C. ESELOROTH, P. Region i. Office of Director 84/03/20 1p. 28724 345 24X Fiche 50-322, 84/03/20, 8403230094
- 8403230117 PNO-V-84-016 on 840319, hydrogen explosion occurred in main generator Caused by circuit breaker trip shutting down hydrogen seal oil pump, resulting in hydrogen leak Manual safety injection to seal oil tank initiated NARBUT, P. ECKHARDT. J. Region 5. Office of Director. 84/03/20 ip 22730 335 24X Fiche, 50-312, 84/03/20, 8403230117
- 8403270114 EN-83-076A: on B40323, order imposing civil monetary penalties in amount of \$50,000. Action based on feilure to classify torus-to-drywell vacuum breaker actuation arm shaft seals under App B. Hitigation of 831115 penalty unwarranted.

 KLINGLER: 0. AXELRAD. J Director's Office, Office of Inspection and Enforcement. 84/03/23, 1p 22774-051 24% Fiche 50-237,84/03/23, 84/03/20114

11

- 8403290008 PNO-I-84-027 on 840323, through-well creck discovered an weld on condensate return line from south isolation condenser. No repair or replacement plans formulated Facility currently shut down for refueling & mod TRIPP.L., KEIMIG.R. Region 1, Office of Director. 84/03/23. ip 22003:282 24X Fiche 50-219,84/03/23,8403290008
- 8403300045 PNO-III-84-028 on 840322.Cs-137 source, part of industrial gauge.lost inspector dispatched to waste treatment plant to review gauge removal & shipment circumstances State personnel sent to fecility to search for missing source SRENIAMSKI,D. AXELSON,W Region 3. Office of Director 84/03/23. 19 22821 102
- 8403300074 PNS-1-84-003 on 840324.male phoned Jersey Central Power & Light Customer 8vc Ctr & notified that FFA will start demolishing plants Oyster Creek implemented emergency contingency plan & TMI increased security awareness MADDEN, W. JOYNER, J. Region 1. Office of Director 84/03/26, ip 22822 OBB 24X Fiche 50-000.84/03/26,8403300074
- 8403300112 PNO-II-84-024 on 840326. State of TN informed Region II that state licenses, Quadrex Co. suspected as source of sawer line contenination detected by DOE State investigation underway TROJANDWSKI, R Region 2. Office of Director 84/03/27 ip

MISC PUBLIC DOCUMENT ROOM HIBCELLANEOUS

- 9310060076 Forwards AEOD engineering evaluation rept, "Review of Events Involving Failures of Power Supply in Instrumentation & Control Sys " Rept should be forwarded to Regions II & III CHIRAMAL, M Reactor Operations Analysis Branch AEOD-6324 83/09/21 SEYFRIT, K V Reactor Operations Analysis Branch ip.
- --8310060077 AEOD/E324
 "Review of Events Involving Failures of Fower Supply in
 Instrumentation & Control Sys." engineering evaluation rept
 CHIRAMALIM Director's Office AEOD/E324 83/09/21. 32pp
- 84030204R4 Responds to 840123 itr re-original issuance & subsequent revs to SRP 9 5 i & associated branch technical position Matrix of SRP fire protection chronology & SRP revs encl.per telcon M/o SRP revs.

 SPEIGN T Division of Safety Technology 84/02/17, FLORA, J. H. Flora, J H 3pp 22491 264
- B403050330 Forwards A Lakner B40214 differing prof opinion on reliability matters for trensmittal to PDR FLORY, S Office of Nuclear Regulatory Research, Director 84/02/27, Record Services Brench (Document Control Desk), ip 22001:316,
- --8403050935 Requests NRC reconsider differing prof opinion on reliability matters by eppointing peer review group composed of competent & impartial members Reasons for request provided LAKNER, A A Lakner Associates 84/02/14 HINOQUE, R. B Office of Nuclear Regulatory Research, Director. 2pp 22501.317
- 8403060529 Responds to 840214 memo re 8100 series of insp procedures applicable to power reactor & fuel fecility security insp programs Review indicated procedures provide tatisfactory working tool for NRC inspectors EISENHUT, D & Division of Licensing 84/02/17. PARTLOW, J. & Division of OA. Bafeguards & Inspection Programs (Post 830103) ip 22349 355.
- --B402030555 Forwards index of 8100 series insp procedures applicable to power reactor & fuel facility security insp programs previously developed by LLL Review & comments requested by B40224 PARTLOW, J C Division of GA, Sefeguards & Inspection Programs (Post 830103) B4/01/24 HARTIN.T T Division of Engineering & Technical Programs STOHRIJP. Division of Emergency Preparedness & Meterials Sefety. HIND, J A Division of Emergency Preparedness & Operational Support, 3pp 22549,356.
- 8403070103 Responds to 840130 request for NRR assistance in defining components subsys & sys subj to NPRDS reporting under general description of reactor protective sys/ESF actuation sys

 DENTON, H R Office of Nuclear Reactor Regulation, Director, 84/02/23 HELTEMES, C. J Director's Office, 1p 22361:164

- --8402160020 Informs of review of NPRDS data collection for reactor protection sys/ESF actuation sys instrumentation IEEE 8td 603, "IEEE 8td for Safety Sys for Nuclear Power Generating Station," should be used to establish boundaries RDSA: Instrumentation & Control Systems Branch 84/02/08 HDLAHAN.G M Operating Reactors Assessment Branch 2pp
- --B402240387 Forwards response to Feb memo re NPRDS data collection for ESF actuation sys SPEIB.TP Division of Safety Technology 84/02/13 EIBENHUT.D G. Division of Licensing 3pp 22561 167
- --8402130042 Requests assistants in defining reportable components for use by licensees in reporting engineering & failure data for reactor protection sys/EBF actuation sys instrumentation to NPRDB
 HELTEMES, C. J. Director's Office 84/01/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director MINOGUE, R.B. Office of Nuclear Regulatory Research, Director DEYGUNG, R.C. Director's Office, Office of Inspection and Enforcement 2pp 22561 170
- 8403080106 Requests NRC prepare proposed rule on use of high enriched U & plan & schedule for development of steps to improve security measures at domestic nonpower reactors using high enriched U fuelby 840330 for Commission consideration CHILK, S. J. Office of the Secretary of the Commission 84/02/23 DIRCKS, W. J. Office of the Executive Director for Operations 4pp
- 8403080271 Recommends that backfitting of anticipatory trips in custom Tech Specs, per JA Olshinski 830727 msmo to DG Eisenhut, be treated as Unique generic issue in accordance w/NRR Ofc Ltr 40 Supporting info for anticipatory trip issue enci MIRAGLIALF. J Assistant Director for Safety Assessment 84/02/23 MINNERS.W. Safety Program Evaluation Branch Spp 22584 066
- 8403130300 Responds to questions in 831125 itr to State of NJ Dept of Environ Protection re former Wastinghouse facility in Bloomfield, NJ, Contamination removed. MARTIN.T.T Division of Enginsering & Technical Programs 84/02/23 PENN, J Affiliation Not Assigned. 2pp 22607 124
- --8403130312 Requests response to enc1 831125 itr to State of NJ Dept of Environ Protection re use of former Westinghouse facility in BloomField.NJ PENN.J. Affiliation Not Assigned 84/02/11 ALLAN.J M Region 1. Office of Director 3pp 22607 126.
- B403140233 Comments on proposed revs to 10CFR73 71 re safeguards reporting requirements Requirements can be relaxed w/o changing NRC ability to respond to incidents on possible gameric safeguards problems
 DENTON:H R Office of Nuclear Reactor Regulation, Director B4/03/05 DAVIS.J.O Office of Nuclear Material Bafety & Bafeguards, Director 2pp. 22638, 021.
- 8403150160 Forwards "Trends & Patterns Program Plan, FY84-86" Analysis of responses yielded listed conclusions from 830802 request for comments on draft version of plan HELTEMEB, C.J. Director's Office. AEDD/P402 84/03/02 DENTON, H.R. Office of Nuclear Resetor Regulation, Director DEYDUNG, R.C. Director's Office, Office of Inspection and Enforcement MINOQUE, R.B. Office of Nuclear Regulatory Research, Director. 2pp 22648 307.
- B4032A0134 Requests deletion of C Bedky name from mailing list
 HAMILTON,P Kirkpatrick, Lockhart, Hill, Christopher & Phillips
 B4/03/R2, NRC No Detailed Affiliation Given. 1p. 2275B 149
- 8403270155 Informs that as result of review of 520 items identified in 840215 ltr re products furnished by Bonney Forge Carlinville Plant, 510 are sock-o-lets or nip-o-lets.2-inch nominal pipe size & Chemical Analysis NCA3867.4 does not apply GERWIN.E F. Pullman, Inc. 84/03/21 JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 4pp. 22769, 151.

- B403270280 Ack receipt of 840227 ltr re leak rate testing proposal Requests meeting w/technical evaluators of "Containment Sys Leakage Testing Requirements" on 840312 Decision on four other proposals should be made as soon as possible REYTBLATT. Z Extran. Inc 8403/02 THOMPSON.R D Administrative Contracts Branch 3pp 22789 263
- B4032B0270 Forwards preliminary case study rept re breaching of encapsulation of smaled well logging sources Comments re technical accuracy requested within 30 days of ltr receipt HELIEMES.C J Director's Office 84/03/07 LEE, J Dresser Atlas Export Sales 1p 22808 068
- --8403280273 Forwards preliminary case study rept re breaching of encapsulation of sealed well logging sources Comments re technical accuracy requested within 30 days of itr receipt HELTEMES, C. J. Director's Office 84/03/07 ACREE, E. H. Gulf Nuclear, Inc. ip 22808 069
- --B4032B027B Forwards preliminary case study rept re breaching of encapsulation of seeled well logging sources Comments re technical accuracy requested within 30 days of itr receipt HELTEMES, C. J. Director's Office B4/03/07 SHELTON. C. D. Shelwell Services, inc. ip 22808 070
- --8403280282 Forwards preliminary case study rept re breathing of encapsulation of sealed well logging sources Comments re technical accuracy requested within 30 days of itr receipt HELTEMES.C J Director's Office 84/03/07 SELF,D M Consolidation Coal Co ip 22808 071
- --8403280288 Forwards preliminary case study rept rs breaching of encapsulation of sealed well logging sources Comments retechnical accuracy requested within 30 days of ltr receipt HELTEMES, C. J. Director's Dffice 84/03/07 SMITH.D A Professional Logging Services, Inc. ip 22808 072
- --8403280274 Forwards preliminary case study rept re branching of encapsulation of sealed well logging sources Preliminary findings, conclusions & recommendations provided to give complets picture of rept Comments requested within 30 days HELTENES.C.J. Director's Office 84/03/07 DAVIB,J.Q. Office of Nuclear Material Safety & Safeguards, Director DEVEUNGR C Director's Office, Office of Inspection and Enforcement MINOQUER B Office of Nuclear Regulatory Research, Director 3pp 22808 073
- --8403280296 Forwards preliminary case study rept re breaching of encapsulation of well logging sources Requests rept be forwarded to States of KY.CO.TX & other states w/large number of well logging licenses HELTEMES.C J Director's Office 84/03/07 KERR.O W Office of State Programs, Director ip 22808 076
- --8403280301 "Preliminary Case Study Rept on Breaching of Encapsulation of Sealsd Well Logging Sources"
 PETTIJOHN,S L Director's Office 84/03/31 47pp 22808 124

NUREO NUREO REPORTS AND RELATED CORRESPONDENCE

- 8402070302 Notifies that Rev 2 to "Rept of Independent Review of Environ Qualification Programs to NUREO-0588" not complete reissue.per 840201 ltr Several rept apps had no changes PETRICK.N A. Standardized Nuclear Unit Power Plant System SLNRC 84-0025 84/02/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 22160 174 24X Fiche 50-000.84/02/07.8402070302
- B403010016 Further response to FOIA request for 16 categories of documents Forwards MJ Dircks Bil2i9 ltr re 810606 sabotage event & special rept to Commonwealth of PA info partially withheld (ref FOIA Exemption 3) FELTON, J M Division of Ruiss and Records B4/01/04 SHOLLY, S C Union of Concerned Scientists 2pp 22479 076 24X Fiche 50-334,84/01/04,8403010016
- B403010017 Forwards BSER 4 (NUREQ-0887) re operation of facilities W/o encl YOUNGBLOOD, B J Licensing Branch i 84/02/17 EDELMAN, M P Cleveland Electric Illuminating Co 3pp 22479 341 24X Fiche 50-440,84/02/17,8403010017
- BAO3010024 Responds to FOIA request for documents as petition for rulemaking PRM-30-31 from Citizens Task Force of Chapel Hill NC Forwards App A documents App B documents completely withheld (ref FOIA Examption 3) FELTON, J H Division of Rules and Records 84/01/18 SHOLLY, S C Union of Concerned Scientists 4pp 22444 035

- --B403010074 Forwards review comments on draft RES deniel of petition for rulemating on emergency planning zone at nuclear power plants.per request General comments enct HULMAN.L G Accident Evaluation Branch 83/01/07 CDIA.P C Research & Standards Coordination Branch 7pp 23446 049
- 8403010026 Responds to FDIA request for 1982 NUREO/CR-2815, "NRC, Natl Reliability Evaluation Program (NREP) Procedures Quide " Forwards NUREO FELTON.J M Division of Rules and Records 84/01/04 DETCHER.J L Northern States Fower Co 1p 22477 002
- --8403010041 NUREG/CR~2815 DRFT
 Draft PROBABILISTIC SAFETY ANALYSIS PROCEDURES GUIDE
 BARI.R A. BUSLIKA J. Brookhaven National Laboratory
 EL-BASSIONI.A Office of Nuclear Reactor Regulation, Director
 FIN A-3382 BNL-NUREG-31559 83/09/01 NRC No Detailed
 Affiliation Given 231pp 22477 003
- B403010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in PDR upon request Review continuing FELTON, J M Division of Rules and Records B4/01/17 ANDERSON, S I Oarvey, Schubert, Adams & Barer 4pp 22446 293 24X Fiche 50-000, 84/01/17, 8403010050
- --Bil2020204 Forwards new format for nuclear power plants -- const status rept. NUREG-0030 (yellow book) New format should be used to provide next update info for planned Nov 1781 publication (data as of Sept 30, 1981) due Bill20 W/o enci HARTITELD.R A Office of Management and Program Analysis Bi/10/30 DUNN, C N Duquesne Light Co 9pp 22446-305 24X Fiche 50-000, 84/01/17, 8403010050
- 8403010066 Forwards safety evaluation to B21223 response to Generic Ltr 82-16 concerning NUREO-0737 Tech Specs Two items closed Items 1 A 1 1 3 & I] E 4 i under consideration Response acceptable VAROA:S A Operating Reactors Branch 1, Gt.-82-16 84/02/10 OFESLER,C W Wisconsin Public Service Corp 7pp 22480 001 24X Fiche 50-303.84/02/10.8403010066
- 8403010072 Final response to FOIA request for comparative evaluation of nuclear facilities compliance w/NUREG-0578 & NUREG-0737 requirements Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 84/02/09 WEISS.E R Union of Concerned Scientists 4pp 22448 190
- B403010117 Partial response to FOIA request for documents by named individuals re repts, analyses, studies, procedures & sys for measurement of RCS leakage App B documents placed in PDR App A documents already available in PDR Search continuing FELTON, J M Division of Rules and Records 84/01/25 MADDEN. T J Raye, Scholer, Fierman, Hays & Handler 7pp 22480 026 24% Fiche 50-000,84/01/29,8403010117
- --8403010193 Informs that portable computers obtained for regional ofcs for use in independent measurement of leak rates from PWR cooling sys Draft module & user guide (NUREG-0996) encl M/o encls
 UCRDAN, E'L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/31 TAYLOR. J M Division of GA, Safeguards & Inspection Programs (Post 830103) 4pp 22481:238
- 8403010120 Forwards addi info to B31230 submittal re NUREO-0737, Item III.D I i, "Primary Coolant Outside Containment " Rev identifies portions of sys not to be tested & responds to NRC comments Info should close SER Confirmatory Issue 28 TRAMM.TR Commonwealth Edison Co B177N 84/02/22 DENYON.H R Office of Nuclear Reactor Regulation. Director 8pp 22432 002 24X Fiche 50-000.84/02/22,8403010120
- B403010173 Forwards order confirming licenses commitments to implement post-TMI related items per Suppl i to NUREO-0737 Schedular commitments reasonable achievable & will provide timely upgrading of emergency response capability VARGA.S A Operating Reactors Branch i OL-82-33 B4/02/23 HILLIAMS, J J Florida Power & Light Co 4pp 22479 209 24X Fiche 80-250.84/02/23,8403010173
- --B403010180 Order confirming licensee commitments to upgrade emergency response capability.per Suppl 1 to NUREG-0737 (Generic Ltr 82-33)
 EISENHUT.D @ Division of Licensing OL-82-33 84/02/23, Florida Power & Light Co 6pp 22479 213 24X
 Fiche 50-250,84/02/23,8403010173

- 8403010203 Forwards licensee 840120 & 24 ltrs on Christa-Maria
 Subcontention 9(4) which questions adherence to guidance of
 NUREO-0737 re radiation monitoring sys Related
 correspondence
 GALLO, J. Isham, Lincoln & Beale
 GALLO, J. Consumers Power Co
 ISSUANCES GLA. 84/02/27 BLOCH P B. PARIS, O H. SHON. F J. Atomic
 Safety and Licensing Board Panel
 Fiche 50-155,84/02/27,8403010203
- 8403010235 Submits info or NUREO-0737. Items II E 1 2. "Safety Grads Auxiliary Feedwater Sys Initiation & Flow Indication" & II K 3 3. "Reporting of Safety & Relief Valve Failures & Challenges." per util 821230 itr & Generic Ltr 82-16 COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Outilities) COUNSIL.W 0 Northeast Utilities A03616 84/02/21. MILLER, JR Operating Reactors Branch 3 3pp 22434 188 24X Fiche 50-336.84/02/21.8403010235
- 8403010262 Further response to FOIA request for documents re Sandia Contract A-1123 & bibliography used by R Bernero Forwards App A documents FELTON.J H Division of Rules and Records FIN A-1123 83/12/20 RUTLEDGE,P Carolina Environmental Study Group 2pp 22444.069 24X Fiche 50-000,83/12/20.8403010262
- --8403010274 Discusses research rept.NUREO/CR-2239 (Band81-1349).
 "Technical Guidance for Siting Criteria Development "
 Forwards NUREO/CR-2723 & NUREO/CR-2899 for ref use only, W/o encis
 DIRCKS,W J Office of the Executive Director for Operations
 82/11/22 PALLADINO. GILINSKY, AHEARNE Commissioners 2pp.
 22444 076 24X Fiche 50-000.83/12/20.8403010262
- 8403010306 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs to lower Group I isolation sespoint for reactor lower water level W/proprietary NEDE-30012, " MBIV Water Level "Rept withheid (ref 100FR2 790) MILLG.L M' Tennessee Valley Authority TVA BFNP TB 196 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22433 042 24% Fiche 50-259,84/02/22,8403010306
- --8403010313 Proposed changes to Tech Bases lowering Group 1 isolation setpoint for reactor lower water level W/affidavit * Tennessee Valley Authority 84/02/22 29pp 22433.045 24X Fishe 50-259,84/02/22,8403010306
- 84030;0347 Forwards status & justification for nine listed NUREO-0737 & Reg Quide i 97 items.per 840222 request Analysis of safety parameter display sys will be submitted by 840430 HUKILL.H D General Public Utilities QPU Service Corp 521:-64-2045 84/02/27 El8ENHUT.D O Division of Licensing 21pp 22433 018 24X Fiche 50-287.84/02/27.8403010347.
- B403010351 Summary of B40209 meeting w/utii.Science Applications, Inc.
 MPR Assoc & MIT re NRC comments on detailed control room
 design review program pian.per requirements of Suppl 1 to
 NUREO-0737 Viewgraphs enci
 PAULSDN.W A Operating Reactors Branch 5 LSD5-84-02-057
 B4/02/29 Operating Reactors Branch 5 36pp 22432·329 24X
 Fiche: 50-255, 84/02/29, 8403010351
- E403010384 Forwards BER for SEP Topic II-3 C, "UHS " Issue adequately resolved based on review of B31114 itr Resolution will be incorporated in suppl to integrated plant safety assessment rept (NUREO-0824)
 CRUTCHFIELD.D. Operating Reactors Branch 5 LGO5-84-02-036
 84/02/28 COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 6pp 22434 061 24X Fiche 50-213,84/02/28,8403010384
- B403010371 Summarizes findings from audit of TMI action items during wk of 83.024 Item II B 3. "Post-Accident Sampling Sys (PASS)." findings are of most concern Corrective actions listed COUNSIL.H G . OPERA.J F Connecticut Yankee Atomic Power Co B10757 B3/11/23 NURLEY.T E Region 1. Office of Director App 22434 068 24x Fichs.50-213.83/11/23.8403010371
- B4030i0400 Submits info re pressurizer heater transformer barrier design, per License Condition 2 C.7 Missile protection structure will be seismically anchored on concrete floor slab HILLIAMS, J W Florida Power & Light Co L-84-44 B4/02/27 EISENHUT, D @ Division of Licensing Spp 22434 026 24X Fiche 50-389,84/02/27,8403010400
- B403010516 Summary of 840130-31 meetings w/util at site in Dauphin Gounty.PA re status, schedule & scope of implementation of selected NUREO-0737 action items Agenda & viewgraphs encl
 VAN VLIET, J Operating Reactors Branch 4, 84/02/22 Operating Reactors Branch 4 130pp 22443 303 24X Fiche 50-289,84/02/22,8403010516

- B403020005 Forwards info requested in SSER 5 (NUREG-0857) re tests performed for C-E on load limiting devices in reactor vessel lower key horizontal supports VAN BRUNT, E E Arizona Public Service Co ANPP-28836-WFG/ B4/02/10 KNIGHTON.0 Licensing Branch 3 7pp 22442 201 24: Fiche 50-528,84/02/10,8403020005
- 8403020014 Partial response to FOIA request for seven categories of documents re NRC regionalization program App A documents in PDR. Review of remaining documents incomplete FELTON, J M Division of Rules and Records 83/12/16 LOWENTHAL, J Nuclear Information & Resource Service 3pp 22492 248 24% Fiche 50-000, 83/12/16, 8403020014
- --8403020035 Forwards final draft program guidance for FY83-85, per NUREQ-0885. "NRC Policy & Planning Guidance " Rev of current ofc operating plan incorporating Commission Aug 1792 budget decisions & program guidance.expected by 821030 DIRCKS.W J Office of the Executive Director for Operations 82/07/20 NRC No Detailed Affiliation Given 19pp 22472 274 247 Fiche 50-000,83/12/16.8403020014
- --8403020052 Provides program guidance for FY83-84.developed in support of NUREQ-0885, Issue 2, "NRC Policy & Plenning Quidance 1983" Gorrect of operating plan should be revised to incorporate encl comments
 DIRCKB.W J Office of the Executive Director for Operations
 83/05/20, NRC NO Detailed Affiliation Given, 20pp
 22493 340 24X Fiche 50-000,83/12/16.8403020014,
- 8403020165 NUREO-0936 Vo2 NO4 NRC REQULATORY AGENDA Quarterly Report,October-December 1983
 - # Division of Rules and Records 84/02/27 180pp 22482 212
- 8403020171 Forwards order confirming util commitments to implement requirements of Suppl 1 to NUREO-0737 Order based on 830418 & 0823 ltrs in response to Generic Ltr 82-33. VARGA.8 A. Operating Reactors Branch 1 GL-82-33 84/02/21 BAYNE.J P. Power Authority of the State of New York 4pp 22491:091 24X Fiche 50-286,84/02/21,8403020171.
- --8403020175 Order confirming licensee 830418 & 0823 commitments on emergency response capability.per requirements of Suppl I to NUREO-0737 & Generic Ltr 83-33 EISENHUT, D O Division of Licensing GL-82-33 84/02/21 Power Authority of the State of New York 5pp 22491 095 24X Fiche 50-286, 84/02/21, 8403020171
- 8403020184 Requests identification of any potential problems or items that cannot be met within time frame required to mest Sept 1984 goal for completion of NUREO-0737 items VAROA. B. A Operating Reactors Branch 1. 84/02/22, WILLIAMS, J Florida Power & Light Co 2pp 22495 005 24X Fiche: 50-250,84/02/22,8403020184
- 8403020207 Forwards order confirming licensee commitments on emergency response capability, based on info provided in util 8304i4 & OR25 responses to Generic Ltr 82-33.8uppl 1 to NUREG-0737 SCHWENCER, A. Licensing Branch 2 QL-82-33 84/02/21 FARRAR, D L Commonwealth Edison Co. 2pp 22474 324 24X Fiche 50-373.84/02/21.8403020207
- --B403020221 Order confirming licensee B30414 & 0825 commitments on smergency response capability, per Generic Ltr 82-33. Buppl i to NUREO-0727
 EISENHUT, D. Q. Division of Licensing GL-82-33. 84/02/21 Commonwealth Edison Co. 7pp 22494-326 24X
 Fiche. 50-373. 84/02/21. 8403020207
- 8403020297 Forwards "Rept on Special Lifting Devices," per 831111 response to SER Open Item 59 Rept covers design fabrication & initial acceptance testing of six special lifting devices listed in Table 3 of 810717 ltr.

 MCCAFFREY.B R. Long Island Lighting Co SNRC-1007 84/02/21 DENTON.H R. Office of Nuclear Resctor Regulation, Director 3pp 22441.268, 24X Fiche.50-322,84/02/21,8403020287
- B403020289 Forwards resolution of SER Confirmatory Issus ii re util B30218 & 0316 submittals concerning TMI Action Items I C 2 & I.C.5. YOUNGBLOOD, B J. Licensing Branch I 84/02/21 9ARY.R.J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 5pp. 22492:241. 24% Fichs. 50-445.84/02/21,8403020289
- B403020295 Notifies that proposed Tech Spec for certain NUREQ-0737 items per Generic Ltr B3-37 will be submitted by B40401.

 GIEBLER: C. N. Wisconsin Public Service Corp NRC-B4-33. B4/02/28 EIEEMHUT, D. Q. Division of Licensing 2pp 22440 046 24% Fiche: 50-305, 84/02/28, 8403020295

- 8403020313 Forwards add) comments to Quidelines 5a,7a & 7b of technical evaluation rept in response to NRC 820630 ltr re control of heavy loads, per Generic Ltr 81-07
 MILLS:L M Tennesses Valley Authority GL-81-07 84/02/28
 ADENSAM,E Licensing Branch 4 lipp 22439 190 24X
 Fiche 50-327,84702728,8403020313
- 8403020317 Forwards Rev 10 to "Analysis of Hydrogen Control Measures at McOuirc Nuclear Station," per SSER 7 (NUREO-0422)
 TUCKER,Η Β Duke Power Co 84/02/29 DENTON,Η R Office of Nuclear Reaction Prector 2ρρ 22441 216 24X
 Fiche 50-000.84/02/29,8403020317
- --8403020321 Rev 10 to "Analysis of Hydrogen Control Measures at McGuire Nuclear Station" * Duke Power Co 84/02/29 50pp 22441 218 24X Fiche 50-000,84/02/29,8403020317
- B403020327 Requests that completion date of emergency operations facility be extanded from B50201 to B50628, per B30415 & OB24 ltrs & NUREO-0737, Buppl i Completion date dues not cover safety parameter display sys installation BAYNE, J P Power Authority of the State of New York JPN-84-15 B4/02/279 VASBALLO, D B Operating Reactors Branch 2 2pp 22439 205 24X Fiche 50-333,84/02/29,84030203327
- 8403020343 Forwards BALP rept for Oct 1982 Sept 1983 Maint of low personnel error rate merits continued attention MURLEY.T E Region 1. Office of Director 84/02/29 LUNDVALL.A E Baltimore Gas & Electric Co 3pp 22439 217 24X Fiche 50-317.84/02/29.8403020343
- --0403020345 SALP rept for Oct 1982 Sept 1983 * Region 1, Office of Director IEB-83-04 B3/12/12 57pp 22439 220 24X Fiche 50-317.84/02/29,8403020343
- 8403020392 FOIA request for Chilk 821019 memo to Dircks re postaccident sampling sys (NUREQ-0737. Item II II 3) to be placed in PDR PEDRO.J NUS Corp CD-LIS-83-048 84/01/26 Division of Rules and Records ip 22491 285 24% Fiche 50-289, 84/01/26, 8403020392
- 8403020375 Responds to FOIA request for Chilk B21019 memo to Dircks re BECY-82-384 concerning status of TMI-1 NUREG-0737 items Forwards document Document also available in PDR FELTON.J M Division of Rules and Records 84/02/15 PEDRO,J NU Carp 1p 22491 286 24X Fichs 50-287,84/02/15,8403020395
- 8403080440 NUREG-0072 RD1 EDO PROCEDURES MANUAL. * Office of the Executive Director for Operations 84/01/31 155pp. 22491 288
- 8403050009 Forwards request for add1 info re NUREG-0737. Item 11 B 3.
 "Post-Accident Sampling Sys," to complete review Requests
 response within 45 days of 1tr receipt
 CRUTCH/IELD, D Operating Reactors Branch 5 LS05-84-02-057
 84/02/29 LINDER,F Dairyland Power Cooperative 3pp 22490 i87
 24% Fiche 50-409,84/02/29,8403050009
- 8403050016 Forwards Rev 7 to FSAR site addendum (filed in PDR Category K) & Rev 7 to radiological emergency response plan (filed in PDR Category F)
 9CHNELL, D F Union Electric Co ULNRC-751 84/03/01 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 5pp 22485 304
 24X Ficher 50-483, 84/03/01, 8403050016
- --8403050019 Rev 7 to radiological emergency response plan * Union Electric Co 84/03/01 354pp 22486 238 24X Fiche 50-483,84/03/01.8403050016
- 840:3050020 Responds to FOIA request for documents re PASNY submittal on sys interactions, repts evaluating submittal & list of repts/analyses from LLL evaluating FASNY sys interaction program Forwards app A documents
 FELTON, J M Division of Rules and Records 83/12/07 SHOLLY, S Union of Concerned Scientists 6pp, 22525 098 24X
 Fiche, 50-000, 83/12/07, 8403050020
- --8403050029 NUREG/CR-2030
 SYSTEMS INTERACTION EVALUATION PROCEDURE FOR APPLICATION TO
 INDIAN POINT-3
 LIM, J J, ALESSO, H P, RICE, T R Lawrence Livermore Laboratory
 FIN A-0405, UCRL-33024 81/04/30 NRC No Detailed
 Affiliation Given 50pp 22526 089 24X Fiche.30-000,83/12/07,
 8403050020
- 8403050053 Summary of 840203 meeting w/util at site re review of NUREO-0737 items Agenda, attendance list & handouts encl VISSING, 6 S. Operating Reactors Branch 4 84/02/23 Operating Reactors Branch 4 24pp 22527 332 24X Fiche 50-346,84/02/23,8403050053

- 8403050085 Discusses analyses on 22 safety relief valve (SRV) discharge lines per 821227 request to address questions re SRV test program per FMI Item II D i Analyses indicate supports & piping geometry adequate QUCHA.L T Georgia Power Co NED-84-040 84/02/10 STDLZ, J F Operating Reactors Dranch 4 2pp 22490 007 24X Fiche 50-321,84/02/10.8403050085
- 840305009B Forwards "Rept on Task 0508B, Pressurizer Relief Valve Discharge Piping Qualification for Calvert Cliffs, Unit 2, " per IMI Item II D I LUNDVALL, A E Baltimore Gas & Electric Co 84/02/29 MILLER, J R Operating Reactors Branch 3 Dpp 22484 147 24X Fiche 50-318.84/02/29,8403050098
- --8403050100 "Rept on Task 05088, Pressurizer Relief Valve Discharge Piping Gualification for Calvert Cliffs. Unit 2 " Approx nine of G4 existing pipe supports may experience stress PATELR B Bechtel Curp 84/02/14 162pp 22484 170 24X Fiche 50-318, 84/02/29, 8403050098
- --8403050103 CEN-248(B) RO2
 Rev 2 to "Pressuriter Safety Valve Operability Rept"
 * Combustion Engineering, Inc 84/01/31 50pp 22484 332 24X
 Fiche 50-318,84/02/29,8403050098
- B403050105 Advises that operability testing of RCS vent valves will be performed per requirements of ASME Section XI. Subsection IMV-3410. for Category B valves.per NUREO-0737. Item II B I CDUNSIL. W G Connecticut Yankee Atomic Power Co COUNSIL. W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL. W G Northeast Utilities B III043 B4/02/21 MILLER, J R Operating Reactors Branch 3 CAUTCHFIELD. D Operating Reactors Branch 5 2pp 22488 043 24X Fiche 50-000, 84/02/21, 8403050105
- 8403050107 Forwards "Abnormal Transient Operating Quidelines. Part I Procedural Oxidelines." "Part II-Vol 1 Fundamentals of Reactor Control "&" Part II-Vol 2 ," per B30415 schedule for completing Buppl 1 to NUREO-0737 requirements CROUSC.R P Toledo Edison Co 1030 B4/03/01 EISENHUT.D 0 Division of Licensing 35pp 22523 221 24X Fiche 50-346.84/03/01.8403050107
- --8403050110 Procedure 74-1125331-00, "Abnormal Transient Operating Quidelines:Pert I Procedural Guidelines " # Bubcuck & Wilcox Co 82/10/12 85pp 22523 256 24X Fishe 50-346,64/03/01,6403050107
- --8403050114 Procedure 74-1125331-00. "Abnormal Transient Operating Guidelines,Part II-Vol 1 Fundamental of Reactor Control For Abnormal Transients " * Bebtock & Wilton Co 82/07/06 245pg 22523 342 24X Fiche 50-346,84/03/01,8403050107
- --8403050118 Procedure 74-1125531-00. "Abnormal Transient Operating Guidelines.Part 11-Vol 2 Discussion of Selected Transients " * Dabcock % Wilcox Co 82/07/06 230pp £2524 227 24X Fiche 50-344.64/03/01.8403050107
- 8403050121 Forwards notice of consideration of issuance of amend to License DRR-6, based on 811215 & revised 831216 applications Amend changes Tech Specs re stack gas monitoring sys CRUTCHFIELD.D Operating Reactors Branch 5 L803-84-02-048 84/02/32 VANDEMALLE, B J Consumers Pawer Co 4pp 22488 032 24% Fiche 50-155, 84/02/22, 8403050121
- 8403050161 Forwards "Structural Steel Survivability Evaluation." in response to 840209 request for add1 info (RAI 280 26), per SER Open Item 14 KEMPER, J.S. Philadelphia Electric Co. GDVT 1-1 84/02/29. SCHMENCER, A. Licensing Branch 2. 3pp. 22483 037 24X Fiche 50-352,84/02/29,8403050161
- --B403050163 "Structural Steel Survivability Evaluation " Rev 1 to "Comparison of Philadelphia Electric Co Heat Dalance Model w/NURCO/CR-3192" encl 4 Philadelphia Electric Co 84/02/24 372pp 22483 040 24X Fiche 50-352,84/02/29,8403050J61
- 8403050229 Submits review of post-accident sampling sys, Item II D 3 Ten of il criteria met Remaining criterian ne procedure for estimating extent of core damage based on radionuclide evaluation, acceptable on interim basis
 MILLER, R Operating Reactors Branch 3 84/02/27 STEWART, W L Virginia Electric & Power Co dpp 22828 CO1 24X
 Fichs 50-000,84/02/27,8403050229

- 6403050233 Notifies that Class IV rather than Class III fee appropriate for review of 840127 application for amend to License DR-49, changing Tech Spacs re NUREG-0737 & min staffing requirements DIGGS,R M License Fee Management Branch 84/02/29 ARNOLD, U. Iowa Electric Light & Power Co 1p 22527 337 24x Fiche 50-331,64/02/29,6403030223
- 8403050238 Forwards Amends 68 & 62 to Licenses DFR-42 & DFR-60, respectively & safety evaluation Amends revise Tach Epecs reemergency air treatment sys & electric hydrogen recombiners DIIANNI.D C Operating Reactors Branch 3 84/02/21 MVSOLF, D H Northern States Power Co 2pp 22527 168 24X Fiche 50-282.84/02/21.840305028
- B403050273 Requests provision of alternative surveillance to replace requirement presently in Tech Bpecs re turbine overspeed protection Proposed alternative maint, calibr & testing program should assure that protection sys operable YOUNGBLOOD, B. J. Licensing Branch 1 84/02/29 GARY, R. J. Teras Utilities Electric Co. (formerly Texas Utilities Generating Co.). App. 22501 109 24% Fiche 50-445,84/02/29,8403050273.
- 8403050369 Summary of 840202 mreting w/util, HTI. Essex & Bechtel in Bethesda. ND re control room design review.per Suppl 1 to NURSE0-0727 Further clarification required in task analysis area Viewgraphs encl MAGNER. D H Liconsing Branch 2 84/02/24 Licensing Branch 2 25pp 22527 284 24X Fichs 50-354.84/02/24,8403050069
- B403060039 Board Notification 84-041 forwards util 840202 updated proposed resolutions & commitments per integrated assessment of plant Several issues under litigation before ABLB reproposed expansion of spent fuel pool storage capacity MIRAGLIA.F J Assistant Director for Safety Assessment 84/02/24 BLOCHP B . PARIS.O H . SHON,F J Atomic Safety and Licensing Board Panel 5pp 22548 283 24X Fiche 50-155,84/02/24,8403060039
- 8403060044 Forwards SER for NUREO-0737. Item II B 2 2 re plant shielding Actions taken or planned for post-accident vital area access satisfy requirements of NUREO-0737 VARGA. S A Operating Reactors Branch 1 84/02/28 BAYNE, J P Power Authority of the State of New York App 28528: SIB 24X Fichs 30-286.84/02/28,8403060044
- 8403040085 FDIA request for documents re Equipment Qualification Branch request to OBLD for clarification of 10CFR30 49, HOLLMAN.P M Engineering Planning & Management, Inc P13503.004 83/12/28 FELTON.J M Division of Rules and Records ip 22528 213
- B403060086 Approves state & local plans & preparedness for electing & protecting public in event of radiological emergency Approval conditional on verification of alert & natification supper criterie of App 3 of NUREO-0634/FEMA-REP-1. Rev 1. SPECK-8 W Federal Emergency Management Agency 84/02/15 DIRCKS W J Office of the Executive Director for Operations 1p 22514 300 24X Fiche 50-250.84/02/15,8403060086
- 8403060071 Responds to FOIA request for records prepared by NRC re request to OELD for clarification of IOCFR50 47 Forwards App A documents No addl records located subj to request FELION.J M Division of Rules and Records 64/01/23 HOLZMAN.P M Engineering Planning & Management, Inc. 2pp 22528 214
- --8309120556 Requests comments on interpretations of Section 50 49 of iOCFR50. "Environ Qualification of Electric Equipment Important to Safety for Nuclear Power Plants"
 VOLLMER:R H Division of Engineering 63/08/31 DLMSTEAD.W J Regulations Division 3pp 22588 216
- --8403060095 Responds to specific questions raised in 830831 request re legal interpretation of 10CFR50 49, "Environ Qualification Rule." OLMSTEAD, W.J. Office of the Executive Legal Director 83/10/04 VOLLMER, R.H. Division of Engineering 3pp 22528, 219
- --8307120556 Requests comments on interpretations of Section 50 49 of 10CFR30, "Environ Gualification of Electric Equipment Important to Safety for Nuclear Power Plants"
 VDLLMER, R H Division of Engineering 63/08/31, OLMBTEAD, H J Regulations Division Spp 22528 216

- 8403060112 Forwards "Safety Parameter Display Sys Parameter Selection Evaluation & Implementation Plan," per Generic Ltr 82-33.
 "Buppl 1 to NUREO-0737 Requirements for Emergency Response Capability"
 WILLIAMS.J W Floride Power & Light Co L-84-48 84/03/01 EISENHUT, D O Division of Licensing ip 22518 322 24X
 Fiche 50-335,84/03/01,8403060112
- --8403060116 "Safety Perameter Display Sys Parameter Selection Evaluation & Implementation Pien" # Florida Power & Light Co GL-82-33 84/03/01 10pp 22518 323 24X Fiche 50-335.64/03/01.8403060112
- 8403060125 Forwards summary of identified technical evaluation rept deficiencies re environ qualification of safety-related slactrical equipment, defined by IE Bullatin 77-018 & NUREG-058B; respectively Enci withheld (ref 100FR2 790) CLAYTON, F. L. Alabema Power Co. IEB-79-018 84/02/29 VAROA, B. A. Office of Nuclear Reactor Regulation, Director 4pp 22519 036 24X Fiche 50-348,84/02/29,8403060125
- 8403060160 Forwards results of chemical analysis techniques performed on std test metrix solution as required by NUREQ-0737. Action Item II.8. Sper util 831122 ltm. Response to Critarion 10 of draft BER complete HUKILL, HD General Public Utilities QPU Service Corp 5211-84-2035 84/02/29 870LZ, JF Operating Reactors Branch 4 Spp 22516 263 24X Fiche 50-289, 84/02/29, 8403060160
- 8403060167 Advises thet NUREQ-0737. Action Items II K 3 30 & II K 3 31 considered complete, besed on 840104 telcon between NRC & GE Licensee need only identify to NRC ref on docket to GE Topical Rept NeDD-203666 or NEDD-203667 ZIMMERHAN, S R. Caroline Power & Light Co NLB-84-096 84/02/29 VABSALUO, D 8 Operating Reectors Brench 2, 2pp 22518 334 24X Fiche: 50-324, 84/02/29, 8403060167
- 8403040186 Forwards safety perameter display sys implementation pian & parameter selection reptiper 830415 commitment Rept meets requirements of Generic Ltr 82-33 re Suppl 1 to NUREG-0737 HILLIAMS, J. W. Florida Power & Light Co. L-84-47 84/03/01 EIBENHUT, D. O. Division of Licensing 11pp 22517 001 24% Fichs. 50-387, 84/03/01,8403060186
- 8403060233 Forwards design info, instrument accuracy & response times to assist in post-implementation review of containment water level monitoring (NUREO-0737, Item II F. 1), per 830719 request MUKILL.H.D General Public Utilities GPU Service Corp 5211-84-2043 84/03/01 STOLZ, J F Operating Reactors Branch 4 App 22517:317 24X Fiche 50-289,84/03/01,8403040233
- 8403060264 Forwards "Program Plan for Detailed Control Room Design Review," including proposed schedule for implementation, per NUREG-0737, Suppl 1 requirements PILANT, J M Nebraska Public Power District NLS8400074 84/03/01 EISENHUT, D 0 Division of Licensing 1p 22515 225 24X Fiche. 50-298, 84/03/01, 8403060264
- ---8403060274 "Program Plen for Detailed Control Room Design Review "
 * Nebraske Public Power District 84/02/29 65pp 22515 226
 24X Fiche 50-298,84/03/01,8403060264
- 8403060297 Lists conterns re operator license exam review process. Proper security measures can be taken to prevent dissemination of questions to license applicants during exam Requests NRC reconsider new guidence.per NUREQ-1021 CAREY.J J Duquesne Light Cn 84/02/24 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22511 134 24X Fiche: 50-334, 84/02/24, 8403060297
- 8403040313 Provides comments on DEB (NUREO-1026) Justification for not providing design analysis of seismic event requested ETCHISON,D Illinois, State of, Dept, Nuc Safety (formerly Dept Public Health) 84/02/22 Division of Licensing 3pp 22515.330 24X Fiche 50-456.84/02/22,8403040313
- B403060323 Notification of CROR Meeting 58 on B40315 to discuss proposed NOREO-0801. "Evaluation Criteria for Detailed Control Room Design Review " Requests ofc directors limit attendance of steff at CROR meetings.

 STELLO, V. Committee to Review Generic Requirements B4/03/02 MATTSON, R. J. Office of Nuclear Reactor Regulation. Director. JORDAN, E.L. Director's Office. Office of Inspection and Enforcement, CUNNINGHAM, R. E. Office of Nuclear Material Bafety & Safeguards, Director ip. 22513 335
- 8403060354 Forwards descriptions of Reg Quids 1 97 requirements & schedule for implementation of emergency response capability, per NAREO-0737, Suppl 1 PILANT, J. M. Nebreska Public Power District NLS8400073 84/03/01 EISENHUT, D. 9. Division of Licensing 19pp 22515 311 24X Fiche: 50-298, B4/03/01.8403060354

- B403060364 Revised application for amend to License DPR-72, changing Tech Spers to reflect addition of two independent, in-place hydrogen monitors Certificate of Svc encl WESTAFER, G R Florida Power Corp 3F0284-13 84/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 22511 297 24X Fiche 50-302.84/02/24, 88403060364
- --8403060368 Proposed Tech Specs reflecting addition of two independent.
 in-place hydrogen monitors in response to NUREG-0737, Item
 II F I
 * Florida Power Corp OL-83-37 B4/02/24 9pp 22511 303 24X
 Fiche 50-302.84/02/24, 8403060364
- 8403060399 Provides add1 info re reactor coolant gas vent sys, per NUREG-0737. Item 11 B i Sys used to purge nitrogen accumulated in reactor vessel head on 831118 RCS will be vented periodically to reduce nitrogen pressure MEDFORD. M O Southern California Edison Co 84/03/02 CRUTCHFIELD. D Operating Reactors Granch 5 3pp 22518, 271 24X Fiche 50-206, 84/03/02, 8403060399
- 8403060430 Provides prellminary estimates for emergency operations facility mods to raise radiation protection factor to greater than or equal to five, per NUREG-0696. In response to NRC 840214 request Util will not implement mods MRBHALLJR Arkenses Power & Light Co OCANO28413 84/02/29 8TOLZ.JF. Operating Reactors Branch 4 WILLERJR Operating Reactors Branch 4 WILLERJR Operating Reactors Branch 3 2pp 22518 192 24X Fiche. 50-313. 84/02/29.
- 8403060439 Forwards marked-up procedures generation package for implementing symptom-based emergency operating procedures, per Suppl 1 to NUREG-0737, for comment LEMPGLS,T E Niegara Mohawk Power Corp 84/03/01 VASSALLO,D B Operating Reactors Branch 2 122pp 22508 143 24X Fiche 50-220,84/03/01,8403DA0439
- 8403060447 Forwards rev to 830314 order, changing completion dates for NUREO-0737. Items II F 1 1, "Nobie Oas Effluent Monitors" & Ii F 1 2, "lodine Monitors," from 831231 to startup for fuei Cycle 7
 MILLER, J R. Operating Reactors Branch 3 84/02/21 WITHERS, B D Portland General Electric Co 3pp 22552 023 24X
 Fiche 50-344.84/02/21,8403060447
- --B403060449 Rev to 830314 order extending completion date for Items if F 1 I k iI F 1 2 from 831231 to startup for 1984 refuging outage EISENHUT.D C Division of Licensing 84/02/21 Partland General Electric Co 4pp 22552 026 24X Fiche 50-344,84/02/21,84030A0447
- 8403040470 Discusses negotiations w/licensee on NUREC-0737 items re emergency operating procedures, per 830401 & 0712 memos REGUA.0 Operating Reactors Branch i 83/09/09 EISENHUT, D G Division of Licensing 1p 22549 326 24X F1che 50-241, 83/09/09, 8403040470
- B403060473 Requests espected completion dates for NUREG-0737 items & justification for proposed schedule for items that will not be completed by June 1784 by 840227 EIBENNUT.D © DIVIsion of Licensing 84/02/22 HUKill, H D General Public Utilities 0PU Service Corp. 4pp 22552 325 24X Fiche. 50-289, 84/02/22.84-03060473
- 8403040476 Requests expected response date for each TMI action item listed in encl within 10 days EJBENNUT.D 0 Division of Licensing 84/02/21 HUKILL.H D General Public Utilities - OPU Service Corp 5pp 22552 320 24X Fiche.50-289, 84/02/21.8403040476
- B4030604/7 Notification of 840313 meeting w/util in York County,8C to conduct confirmatory site visit per Section 13 & of BRP (NURED-OB00). JABBDUR,K N Licensing Branch 4 B4/02/24 ADENSAM,E 0 Licensing Brench 4 Jpp 22549 340 24X Fiche 50-413,84/02/24,8403060477
- B403060508 Forwards order confirming util commitments to implement requirements of Suppl 1 to NUREO-0737 Order based on commitments contained in util 840415 & 830824 responses to 821217 Generic Ltr 82-33 VARQA: B A Operating Reactors Branch 1 QL-82-33 84/02/21 UTLEY; E Carolina Power & Light Co 3pp 22552 165 24X Fiche 50-261; 84/02/21, 8403060508
- --8403060510 Order confirming licensee commitments on emergency response cepability, per Generic Ltr 82-33, Suppl 1 to NUREG-0737 EIBENHUTD & Division of Licensing, GL-82-33 64/02/21. Carolina Power & Light Co 6pp 22552,168 24X Fiche, 50-261,84/02/21,8403040508

8403040533 NUREC/CR-3067 CALIBRATION SOURCES FOR THE C-M COUNTER USED WITH THE BNL CALIBRATION SUBRCES FOR THE CHARGE COLOR SAMPLER
HUCHTON R L , BIRD, S K , TKACHYK, J W Exxon Nuclear Co ,
of Exxon Corp) FIN A-6347 ENICO-1125 B4/02/29
Facility Operations 32pp 2232-064 Division of

8403060534 Natification of 840315-16 meetings w/util in Sweetweter, TN to conduct confirmatory site visit per Section 13 6 of SRP KENYON, T J L Branch 4 3pp

8403070093 NUREQ/CR-3607

403070073 NURED/CR-3607
RADIONUCLIED INTRIBUTIONS AND MIGRATION MECHANISMS AT
SHALLOW LAND BURIAL SITES 1982 Annual Report of Research
Investigations On The Distribution Migration And Containment
Of Radionuclides At Maxey Flats Kentucky
KIRBY.L J Battelle Memorial Institute Pacific Northwest
Laboratories FIN 8-2291 84/02/29 Division of Health,
Waste Management 80pp Available at NRC \$5.50 22563.22 Division of Health, Siting & RC \$5 50 22563 229

8403070098 FDIA request for V Stello 830803 memo re task group to study surveillance testing in Tech Specs & 830916 & 1004 ltrs from JJ Shappand of Hestinghouse Owners Group to be placed in PDR Documents referenced in NUREO-1024 PEDROJ NUS Corp CD-LIS-83-073 84/02/02 Division of Re and Records. 1p. 22561 132 Division of Rules

8403070104 NUREG-0675 817 8AFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2 Dacket Nos 50-275
And 50-323 (Pacific Cas And Electric Company)

* Division of Licensing 84/02/29 22pp Available at Ne
\$3 00 22361 214 24% Fiche 50-275,84/02/29,8403070104 Available at NRC

8403070109 NUREG/CR-3601 MANAGEMENT AND URGANIZATIONAL ASSESSMENTS. A REVIEW OF MANAGEMENT AND DROAMIZATIONAL ASSESSMENTS A REVIEW OF SELECTED ORGANIZATIONS NADEL,M V , KERWIN,C M Battelle Human Affairs Research Centers Battelle Memorial Institute, Pacific Northwest Laboratories FIN B-2350 PNL-4813 84/02/27 Division of Human Factors Safety 42pp Available at NRC. \$3 75 22561 172

8403070114 NUREC/CR-3649 (03070]]4 NUREC/CR-3649
DYNAMIC TESTING OF AS-BUILT CIVIL ENGINEERING STRUCTURES A REVIEW AND EVALUATION
SRINIVASAN.M G , KOT.C A , HSIEM.B J Argonne National Labor.
FIN A-2217 ANL-B3-20 84/01/31 Division of Engineering
Technology 117pp 22562 055 Argonne National Laboratoru

B403070115 NUREQ/CR-3091 V03 1030/0115 NOREO/CR-3091 VOS REVIEN DF WASTE PACKAGE VERIFICATION TEBTS Semiannual Report Covering The Period April-September 1983 SUG.P Brookhaven National Laboratory FIN A-3167 BNL-NURG-51630, 84/02/29 Division of Waste Management 164pp Available at NRC 65 50 22562 176

8403070118 NUREG/CR-3449 403070118 NUREC/CR-3449
LABORATORY EVALUATION OF LIMESTONE AND LIME NEUTRALIZATION
OF ACIDIC URANIUM MILL TAILINGS SOLUTION Progress Report
OP172,B E , DODSON.M E , SERNE,R J Battelle Memorial Institute,
Pacific Northwest Laboratories FIN B-2370 84/02/29 Division
of Health, Siting & Waste Management 50pp Available at NRC
44 00 22562 004

8403070121 NUREG-1022 BOI LICENSEE EVENT REPORT SYSTEM Description Of Bystem And Guidelines For Reporting HEBDON,F J. Director's Office 84/02/29 58pp Available at NRC 44 SO. 22561 308

8403070157 Application supplementing 820316,830623 & 0906 requests for amend to Licenses DPR-62 & DPR-71, consisting of Tech Spec changes For Item 9 re isolation of HPC1 & RCIC mod (NUREO-0737, Action Item II x.3 15) & Generic Ltr 83-02 HOWE, P W Carolina Power & Light Co GL-83-02 84/02/28 VASSALLO.D B Operating Reactors Branch 2 2pp 22538 316 24X Fiche 50-324,84/02/28,8403070157.

--8403070162 Proposed Tech Spec changes for Item 9 re isolation of HPCI & RCIC mod (NUREO-0737, Action Item II K 3 15) & Generic Ltr 83-02 02 Carolina Power & Light Co 9L-83-02 84/02/ 38-318 24X Fiche+50-324,84/02/28,8403070157 B4/02/28 31pp 22538-318

8403070215 Responds to FOIA request for documents re 830919 meeting to discuss steam erosion issue in facility proceeding & TM Novak 830825 memo on subj Forwards App A documents Documents 4 & 5 withheld (ref FOIA Exemption 5) FELTON, J. M Division of Rules and Records 84/01/23 HIATT, S Ohio Citizens for Responsible Energy 3pp 22563 220

--B403070221 Requests confirmation on lead responsibilities for NGGO/DEZI Requests confirmation on lead responsibilities for finalizing NRC position re steam erosion contention issue Responsibility should be shared by Mechanical Engineering Branch Metoprology & Effluent Treatment Branch NGVAK.TM Assistant Director for Licensing 83/08/25 KNIGHT.JP Assistant Director for Comp & Structures Engineering (Post 830201) 2pp 22563 224

8403070255 Application for amend to Licenses DPR-24 & DPR-27 Amend incorporates changes to Tech Specs re accident munitoring instrumentation to be installed per MUREG-0737 requirement FAY, C W Hisconsin Electric Power Co GL-83-37 84/02/29 DENTON: H R Office of Nuclear Reactor Regulation, Director MILLER, J R Derating Reactors Branch 5 4pp 22536 179 24X Fiche 50-266,84/02/29,8403070255

--8403070257 Proposed Tech Specs incorporating changes re accident monitoring instrumentation to be installed per NUREG-0737 requirement # Histonin Electric Power Co 84/02/29 10pp 22536 183 24X Fiche 50-266.84/02/29,8403070255

8403070282 Forwards IE Insp Rept 50-289/83-32 on 831101-840112 No violations noted

STARGSTECKI, R Division of Project & Resident Programs 84/02/21,
HUKILL, H D General Public Utilities - GPU Service Corp 22347 077 24% Fiche 50-289, 84/02/21, 8403070282

-8403070287 IE Insp Rept 50-289/83-32 on 831101-840112 No violations NOW OPEN IN THE STATE OF SUPERVISORS OF STATE OF

8403070307 Forwards IE Insp Repts 50-324/83-42 & 50-325/83-42 on 831215-840115 No violations or deviations noted VERRELLI,D M Division of Project & Resident Programs 84/02/06 UTLEV,E E Carolina Pawer & Light Co 2pp 82546-175 24X Fiche:50-324,84/02/06,8403070307

-8403070310 IE Insp Repts 50-324/83-42 & 50-325/83-42 on 831215-840115 No violations or devietions noted Major areas inspected surveillance, maint, operational safety verification, EEF sysualKdown, LER review, independent insp & plant transients MYERS, D. D., OARNER, L. W. Region 2. Defice of Director BEMIS.P. R. Division of Project & Resident Programs 50-225/82-42 84/02/03 8pp. 22546 177 24X Fichs 50-324.84/02/04.8403070307

8403070385 NUREG-1039 NOSCIOLES NORGE 1039
REVIEW AND EVALUATION OF THE NUCLEAR REGULATORY COMMISSION
SAFETY RESEARCH PROGRAM FOR FISCAL YEAR 1985
* ACRS - Advisory Committee on Reactor Safeguards 84/02/29. 74pp
Available at NRC \$4 50 22561 234.

8403070372 NUREC/CR-2000 VO3 N1 LICENSEE EVENT REPORT (LER) COMPILATION For Month Of January 1984 * Oak Ridge National Laboratory FIN A-9135 ORN B4/02/29 Director's Office 123pp 22354 092 GRNL/NSIC-200

8403070397 NUREG/BR-0059 RO1 ER SMALL BUSINESS INNOVATION RESEARCH PROGRAM Program Solicitation FY1984 s Office of Nuclear Regulatory Research, Director 84/02/21 ip 22557 022

8403070401 NUREG-0304 VOB NO4 REQULATORY AND TECHNICAL REPORT Compilation For 1983 * Division of Technical Information & Document Control 84/02/29 569pp 22554 217

8403080003 FOIA request for 10 contractor repts on generic modeling for vital area & safeguards analysis referenced in NURRE/CR-3121 SHDLLYS C Union of Concerned Scientists 84/01/10, FELTON, J. H Division of Rules and Records 2pp 22578 001

8403080039 Lists planned submittal dates for eight action items.per

8403080083 Forward's order modifying implementation date for TMJ Action Item 11 F 1 1, "Noble Gas Steam Effluent Monitor," per NUREQ-0737 Order provides new completion date of 841231 W/o encl R Operating Reactors Branch 3 84/03/02 LUNDVALL, A E Baltimore Qas & Electric Co 4pp 22584 095 24X Fiche 50-317,84/03/02,8403080083

- 8403080005 FD1A request for SER & SER 21 (NUREQ-0675) re operation of facilities
 0ARDE, 8.P Qovernment Accountability Project 84/01/09 Office of Administration 2pp 22584 074
- B4030H0179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A document App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records B4/02/13 ANDERSON, H I Garvey, Schubert, Adams & Berer 7pp 22583 226 24X Fiche 50-000.84/02/13,8403080179
- --B107280171 Notification of B10729 meeting w/util & B&W in Bethesda.MD to discuss method util intends to use to fulfill requirments of NUREO-0737 Item II F 2 (inadequate core coding instrumentation)
 HERNAN.R W Licensing Branch 4 B1/07/21 ADENSAM,E G Licensing Branch 4 2pp 22583 305 24X Fiche 50-000, 84/02/13. B403080179
- --8207280165 Forwards Cycle 3 systematic appraisal of licensee performance input for BiO701 through 820730 in response to Region 5 820625 request Strong mgt evident Resolution of technical issues, responsiveness & staffing satisfactory HERNAN, R W. Licensing Branch 4 82/09/15 EISENHUT, D, Ø Division of Licensing 6pp. 22583 351 24X Fiche 50-000, 84/02/13,8403080179
- B4030B0227 Lists concerns on proposed water supply sys discussed in Der 1983 DEB (NUREO-1026). Including degradation of water quality from cooling water discharge to Kankakee River QALLAOHER. J R Wiil County, IL. B4/03/02 Division of Licensing 1p 22561.031, 24X Fiche 50-456.84/03/02.84030B0227
- 8403080264 Forwards "Control Room Design Review Program Pian for North Anna & Surry Power Stations." in response to Suppi i to NUREG-0737 Review expected to be completed by 850830 BEHART.W L Virginia Electric & Power Co 087 84/03/01. DENTON, H R Office of Nuclear Reactor Regulation, Director Rpp 22557-275 24X Fiche 50-000.84/03/01,8403080264
- --B4030B0269 "Control Room Design Review Program Plan for North Anna & Surry Power Btations," in response to Suppi i to NUREO-0737 * Virginia Electric & Power Co 84/03/01 111pp. 22557 279 24% Fitche 50-000,84/03/01.84030B0264
- B4030B0265 Forwards three repts re facility sefety parameter display sys (BPDB), per requirements of Buppl 1 to NUREG-0737 BPDS wiil be instailed during upcoming recirculation piping replacement outage PILANT, J M Nebraska Public Power District LGAB400069 B4/03/01 EIBENHUT, D Q Division of Licensing 2pp 22558 050 24X Fichs 50-278, 84/03/01,8403080265
- 8403080405 Further response to FOIA request for documents re BER related to operation of facilities Forwards App B documents. App A & B documents available in PDR. Review of remaining documents subj to request in progress

 FELTON, J M Division of Rules and Records 84/03/02 GARDE, B P Opvernment Accountability Project 4pp 22583 073
- --B312230256 Forwards responses to Allegations 7.9 & 48, per 831130 request.

 SPEIB,T P Division of Befety Technology. 83/12/09 KNIGHTON, 0 Office of Nuclear Reactor Regulation. Director 12pp 22583 111
- --8403080426 Forwards safety evaluations for Allegations 8,10,11,14,15, 16,17,27,28,29,31,32,33,35,36,55,85 & 86 Licensee approach for determining containment stability against tilting acceptable.

 VDLLMER,R,H Division of Engineering IEB-80-11 83/12/09 EISENHUT,D 0, Division of Licensing 31pp 22583 132,
- 8403090012 Forwards "High Pressure Safety Injection Pump," mechanical environ qualification rept.per BSER 5 (NUREQ-0857). VAN BRUNTS E. Arizona public Bervice Co. ANPP-28970-WFG/. 84/02/29. KNIGHTON, Q. Licensing Branch 3 2pp 22568 001 24% Fiche: 50-528,84/02/29.8403090012
- 8403070081 Forwards Suppl 4 to response to IE Bulletin 83-02, consisting of rept, "Recirculation, RHR Shutdown Cooling, Head Spray Line Reactor Info (Rev 2) "
 DALTROFF, S L. Philadelphia Electric Co. IEB-83-02 84/02/21
 HURLEY, T. E. Region 1, Office of Director 3pp 22575 153 24X
 Fiche 50-277, 84/02/21, 8403070081.
- 8403070075 Forwards application to amend License DPR-26 consisting of proposed Tach Spec changes, incorporating requirements of Item II B i of NUREG-0737, "Reactor Coolant Vent Sys"
 O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. QL-83-37
 84/02/28. VARGA, 8, A. Operating Reactors Branch i 2pp. 22376 007
 24X Fiche 50-247,84/02/28,8403070095.

- ---8403090098 Application for amend to License DPR-26.revising Tech Specs to incorporate requirements for reactor coolant vent sys O'TOOLE.J D Consolidated Edison Co of New York, Inc 84/02/28 2pp 22576 009 24% Fiche 30-247.84/02/28.8403090095
- --8403090101 Proposed Tech Spec re RCS vents per NUREG-0737. Item II B 1 * Consolidated Edison Co. of New York, Inc. 84/02/29 Epp 22576 011 24X Fiche 50-247,84/02/28,8403090095
- 8403090100 Application for amend to License DPR-16.changing Tech Specs re fire detection instruments to comply w/NUREG-0737 (Generic Ltr 63-36).Items II 8 1.II 8 3.II F 1 & II D 3 4 KUNCL, L Q Nebraska Public Power District NLS 8400076 84/02/29 VASSALLD, D B Operating Reactors Branch 2 6pp 22571 116 24x Fiche 50-298.84/02/29.8403090100
- --B403090116 Proposed radiological Tech Specs per NUREG-0737 (Generic Ltr 83-36) re fire detection instrumentation * Nebraska Pubilc Power District (L-B3-36 84/02/29 16pp 22571 122 24X Fiche 30-298,84/02/29,8403090100
- B40309011B Forwards comments re DES (NUREG-1033) for consideration in preparation of FES SOREMSEN.9 C. Washington Public Power Supply System 903-84-131 84/03/05 KNIGHTON.6 W. Licensing Branch 3 5pp 22576 074 24X Fiche.50-508.84/03/05.8403090118
- 8403090121 Advises that 24 h homidity test of three safety-related components per SSER 4 (NUREO-0892) satisfactorily completed SURENSEN, G C Washington Public Fower Supply Bystem G02-84-108 84/03/01 BCHWENCER, A Licensing Branch 2 ip 22576 066 24) Fiche 50-397,84/03/01.8403090121
- 8403090145 Requests submittal of documentation re NUREG-0737 items within 30 days to complete technical reviews & implementation.excluding Suppl 1.by Sept 1984 VARGA:S A Operating Reactors Branch 1 84/03/02 FARRAR.D L Commonwealth Edison Co 2pp 22592 309 24X Fiche 50-295,84/03/02,8403090145
- B403070153 Notifies that goal for completion of technical reviews & implementation of NUREG-0737 items, excluding Suppl 1, is Sept 1984 All required documents must be provided & Tech Spscs in place to meet goal VARGA. BA Deparating Reactors Branch 1 84/03/02 CAREY. J J Duquesne Light Co 3pp 22584 358 24X Fiche 50-334.84/03/02.8403070153
- B403070179 Forwards supplemental info re core exit thermocouples (CET) for inadequate core cooling interim operation, per 840210 telcon CET sys compiles w/most NUREG-0737, Item II F 2 requirements
 HARSHALL.J R Arkansas Power & Light Co 1CAN038401 84/03/07 STOLZ.J F Operating Reacture Branch 4 5pp 22573 267 24% Fiche 50-313,84/03/07,8403090179
- B403070210 Advises that util B40220 proposed variance for high-range stack gas monitors unacceptable Sys should be modified to meet display guidance of NOREO-0737. Item II F 1(i), "Addl Accident Monitaring Instrumentation "CRUTCHTIELD.D Operating Reactors Branch 5 LS05-84-03-007 B4/03/07 VANDEWALLE,D J Consumers Power Co 5pp 22574 358 24X Fiche 50-000.84/03/07.8403070210
- 8403090252 Application to amend Licenses DPR-71 & DPR-62, revising Tech Specs rs accident monitoring instrumentation per NUREC-0737 & Generic Ltr 83-36 HOWE.P W Carolina Power & Light Co NL6-84-074 84/03/02 VASSALLO.D B Operating Reactors Branch 2 7pp 22571 192 24X Fiche 50-324,84/03/02,8403090252
- --8403090260 Proposed Tech Spacs re limiting conditions for operation & surveillance requirements for actident monitoring instrumentation per NUREG-0737 & Generic Ltr 83-36 & Carolina Power & Light Co GL-83-36 84/03/02 21pp 22571,179 24X Fiche 50-324.84/03/02.8403090252
- B403090272 Notifies that submittal date for STG addressing NUREQ-0737 items, per Generic Ltr B3-37, rescheduled for B40305 COUNGIL, W G COUNGIL, W G COUNGIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNGIL, W G Northeast Utilities A03610 B4/02/24 EISENHUT, D G Division of Licensing. 2pp 22572 196 24X Fiche 50-336, 84/02/24, B403090272
- B403120004 Reevaluates response to NUREG-0737, Itsm III D 3 4. "Control Room Habitability." based on PRA technique for onsite & offsite sources App R mods will assure adequate smake detection in control room HUKILL.H D General Public Utilities GPU Service Corp 3211-84-1036 B4/03/02 BTOLZ, J F Operating Reactors Branch 4 2pp 22586 306 24% Fiche 50-287,84/03/02,8403120004

- 8403120042 "Annual Rept of Facility Changes Tests Experiments & Safety & Relief Valve Failures & Challenges, 1983 " W/840301 itr MINECK.D L Tows Electric Light & Power Co DAEC-84-129 83/12/31 KEPPLER.J O Region 3, Office of Director 73pp 22591 145 24% Fiche 50-331, 83/12/31, 8403120042
- 8403120059 Forwards results of sefety evaluation of NUREO-0737, Item II K 3 iB concluding that eliminating high drywell pressure permissive could increase severity of loss of feedwater transfent by actuating autometic depressurization sys MANDAN. C V Niagara Mohawk Power Corp 84/03/06 VASSALLO, D 8 Operating Reactors Brench 2 3pp 22586 285 24X Fiche 50-220.84/03/06.8403120059
- 840312008) Forwards safety evaluation re Sections 5 1.1 & 5 3 of NUREG-0612, "Control of Heavy Loads at Nurlsar Power Plents " Guidelines satisfied Phase I acceptable JUHNSON,E H Region 4, Office of Director B4/03/06 LEE,O R Public Service Co of Colorado 2pp 22570 168 24X Fiche 50-267.84/03/06,8403120081
- --8403120086 Safety evaluation re NUREG-0612, "Control of Heavy Loeds,"
 Phase I Guidelines satisfied
 NRC No Detailed Affiliation Given 84/03/06
 22990 170 24X Fiche 50-267,84/03/06.8403120081
- --8402280725 E00-HS-6294 RO3

 "Control of Heavy Loads at Nuclear Power Plants, Fort St
 Vrain Nuclear Generating Station, Phase I." technical
 evaluation rept
 STICKLEY, T H E000, Inc FIN A-6497 84/01/31 NRC No
 Detailed Affiliation Given 27pp 22590 172, R4X
 Fiche 50-267,84/03/06,8403120081
- 8403120130 Comments on NURES-0737. Item II B 1, "RCS Vents " Six listed jtems completed.per 830703 SER RCS vent sys solenoid velves not susceptible to common mode Failure No corrective ection necessary
 WESTAFER.G R Florida Power Corp 3F0384-04 84/03/07 STOLZ, J F Operating Reactors Branch 4 3pp 22588 202 24X
 Fiche 50-302.84/03/07.8403120130
- 8403120157 Advises that due to delays in delivery & instellation of auxillary safety instrumentation panels (ASIPs), installation of six accident monitors addressed in NOREG-0737. Items II F 1 through II F 1 6 will not be completed by 840630 FAY.C W Hisconsin Electric Power Cr 84/03/05 DENTON:H R Office of Nuclear Reactor Regulation. Director MILLER.J R Operating Reactors Branch 3 3pp 22584 250 24% Fiche 50-266.84/03/05.8403120157
- 8403120179 Forwards info supporting util position that implementation of add1 insp criteria provides no add1 increase in safety, per SER (NUREO-0847) HILLS.L M Tennessee Valley Authority 84/03/07 ADENSAM.E Licensing Branch 4. 3pp 22590 205 24X Fiche 50-390.84/03/07.8403120179
- 8403120183 Forwards application for amend to License DPR-40, revising Tech Specs to add limiting conditions for operation, surveilliance requirements & administrative requirements, per NUREO-0737

 ***LeBosuf, Lamb. Leiby & MecRae. *** Omahe Public Power District 84/03/07 DENTON.H Office of Nuclear Reactor Regulation, Director Jpp 22585 200 24X Fiche 50-285,84/03/07,8403120183
- --8403120192 Application for emend to License DPR-40, revising Tech Specs to add limiting conditions for operation, surveillance requirements & administrative requirements.per NUREQ-0737 JONES, W C Dmaha Public Power District 84/03/08 2pp 22585 203 24% Fiche: 50-285, 84/03/09, 8403120183
- --B403120195 Proposed Tech Specs re limiting conditions for operation, surveillance requirements & administrative requirements # Omaha Public Power District 84/03/09, 14pp 22585 205 24X Fiche 50-285.84/03/09.8403120183
- 8403120186 Requests that NUREG-0737. Item II E 4 2 re containment pressure setpoint be closed in next SSER. Facility will employ 17 i pais setpoint per Tech Specs. COOK: K W Louisiana Power & Light Co W3P84-0602 84/03/05 KNIGHTON, O W Licensing Branch 3 ip 22585 001 24X Piche 50-382. 84/03/05. 8403120186
- B403120302 Requests remittel of Class III fee for review of 840123 application for Tech Spec changes re NUREG-0737 requirements
 DIGGS.R M License Fee Management Branch 84/03/01 RODRIGUEZ.R J Sacramento Municipal Utility District ip 22596 360 24X Fiche 50-312,84/03/01.8403120302

- B403120339 Forwards order confirming util commitments to implement post-THI-related items set forth in Suppl 1 to NUREQ-0737. "Requirements for Emergency Response Capability " Order based on util 821217 response to Ceneric Ltr 82-33 STOLZ.JF Operating Reactors Branch 4 QL-82-33. 84/02/21 RODRIOUZZ.R J Secrements Hunicipal Utility District Spp. 22615 320 24X Fiche 50-312,84/02/21,8403120339
- ---8403120342 Order confirming licensee commitments on emergency response capability.per Suppl 1 to NUREO-0737.
 EISENHUT.D O. Division of Licensing 84/02/21 Secrementa Municipal Utility District 6pp 22615 323 24X
 Fiche 50-312,84/02/21.8403120339
- 8403120354 Forwards order confirming licenses commitments to implement post-TMI-releted items set forth in Suppl i to NUREQ-0737, "Requirements for Emergency Response Cepability." Order based on util responses to 821213 Generic Ltr 82-33 STOLZ, J.F., Operating Reactors Branch 4 QL-02-33 84/02/21, MILCUS, H.S. Floride Power Corp. 3pp. 22615-329 24X Fiche 50-302,84/02/21,8403120354.
- ---8403120359 Order confirming licenses commitments on emergency response cepability.per Suppl i to NUREO-0737.
 EISENHUT,D. G. Division of Licensing 84/02/21 Fibride Power Corp App. 22615 332 24X Fiche:30-302:84/02/21,8403120354.
- 8403120379 Forwerds rept of results of in-progress audit for facility detailed control room design review per Suppl 1 to NUREO-0737 conducted on 831212-16 MILLER JR Operating Reactors Branch 3 84/02/29, WITHERS, B. D Portland General Electric Co 73pp. 22619.008 24X Fiche 50-344,84/02/29,8403120379
- 8403130007 Forwards response to Generic Ltr 83-36 re NUREG-0737 Tech Specs HILLS,L M Tennessee Valley Authority GL-83-36 84/03/07 DENTON,H R Defice of Nuclear Reactor Regulation, Director 3PP. 22613.347 24X Fiche. 50-259, 84/03/07, 8403130007
- 8403130087 Comments on DEB (NUREQ-102A) for fecility DEB does not completely describe fuel cycle impect & should contein stetement re renge of nonfetal cancer injuries & birth defects induced by fuel cycle Rn-222 DDHERTY, J. F. Doherty, J.F. 84/03/07 STEVENS, J. A. Division of Licensing 2pp 22601 i17. 24X Fiche, 50-456, 84/03/07, 8403130057.
- 8403130066 Advises that request to revise Tech Bpecs to provide requirements for overtime limits & reporting of relief & safety weive feilures will be submitted per Generic Ltr 82-16 (NUREO-0737) by 840515
 WILLIAMS.J W Floride Power & Light Co. QL-82-16 84/03/08 MILLER, J R. Qperating Reactors Brench 3. 1p 22601:252 24X Fiche 50-335,84/03/08,8403130066
- 8403130155 Advises that state & local pians & preparadness for radiological emergencies adequate Approval conditional on FEMA varification of adequacy of alerting & notification sys, per App 3 of Rev i to NUREG-0654/FEMA-REP-1.

 SPECK.S W Federal Emergency Management Agency, 84/03/02 DIRCKS, W J Defice of the Executive Director for Operations 2012088 227 24% Fiche.50-254.84/03/02.8403130155
- B403i301B5 Discusses evaluation of State of IL & local plans & preparadness for facilities Pians adequate to protect health & safety of public Approval of public eight notification systemational on verification of criterie of NUREO-0634.

 SPECK.B W Faderal Emergency Management Agency. 84/03/02 DIRCKB, W.J Defice of the Executive Director for Operations 12613 316 24X Fiche 50-295.84/03/02.8403130185
- B403130190 Forwards response to NRC 801222 request for review of controls for hendling heavy loads, as committed to in 830809 ltr.Response to items in Section 2.1 of 801222 ltr also encl.

 BDOMER, J E Quif Stetes Utilities Co. RBO-17168, 84/03/01, BENTON, H R. Office of Nuclear Reactor Regulation, Director 63pp 22606 063. 24% Fiche; 50-438, 84/03/01, 8403130190.
- 8403130194 Responds to NRC comments on deteiled control room design review program plan, per 831223 ltm Control room inventory requirements will be satisfied, per Suppl 1 to NUREO-0737 & Generic Ltm 83-18 during Apr 1984 tesk anelysis review EDELMAN, M.R. Clevelend Electric Illuminating Co. PY-CEI/NRR-0095. 84/02/29 YOUNOSLOOD, B.J. Licensing Branch 1. 7pp. 22617:300, 24X Fiche 30-440, 84/02/27, 8403130194.
- B403130199 Forwards info in response to NRC B20630 ltr re NUREC-0737. Item 1), B. 3. "Post-Accident Bampling Sys." W/three oversize drawings Aperture cards are available in PDR. FIEDLER, P. B. General Public Utilities GPU Service Corp. B4/03/06 CRUTCHFIELD. Operating Reactors Branch 5 35pp. 22608:246 24: Fiche: 50-219, B4/03/06, 8403130199.

- 8403130227 Forwards info re shift experience, per DF Schnell 840301 Itr & SER (NVREO-0892) Licensed classroom training & eram conducted BORENBEN, Q C Hashington Public Power Supply System G02-04-127 84/03/09 DENYON, H R Office of Nuclear Reactor Regulation, Director 7pp 22608 231 24X Fiche 30-397,84/03/09,8403130227
- B403130234 Disagrees w/util 840207 ltr concluding that no Tech Spec revs required to finalize NUREG-0737 items presented in Generic Ltrs 83-36 & 83-37 Changes needed for conformance to NUREG-0737 encl Commitments requested within 20 days JOHNSON, E H Region 4. Office of Director GL-83-36 84/03/08 LEE, O R Public Service Co of Colorado 3pp 22617 265 24X Fiche: 50-267, 84/03/08,8403130234
- 8403130287 Requests exemption from 10CFR30 44(c)(ii)(B), specifying requirements for containment penetrations designated for use as post-accident hydrogen recombiner, by 840403 KAY, J A Yankee Atomic Electric Co FYR 84-31 84/03/06 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 22614 146 24: Fiche 50-029,84/03/06.840310287
- 8403130270 Forwards response to Section 4.4 of NUREO-0827. SEP Topic II-3 C. "Sefety-Related Water Supply (UHS) " Submittal of applicable Tech Spec changes rescheduled for 840401 LINDER.F Dairyland Power Cooperative LAC-7627 84/03/08 CRUTCHFIELD.D Operating Reactors Branch 5 5pp 22608 034 24X Fiche 50-409.84/03/08.8403130270
- B403130298 Provides implementation ltr rept for reactor vessel level instrumentation sys.per NRC B40816 ltr & TMI Action Item II F 2. Requests NRC approve use of installed reactor vessel level instrumentation based on previous acceptance SIEMART.W L Virginia Electric & Power Co 047A B4/03/07 DENTON.H R. Office of Nuclear Reactor Regulation, Director EIBENHUT, D G Division of Licensing 3pp 22607 360 24X Fiche 50-338.84/03/07.8403130298
- 8403130340 Forwards offsite dose calculation manual, per proposed radiological effluent Tech Bpec dtd 840201 Response to Franklin Research Ctr comments re 830301 offsite dose calculation manual also encl
 LEMPGES,T E Niegara Mohauk Power Corp 84/03/07 VASSALLO,D B Operating Reactors Branch 2 App 22607 154 24X Fiche 50-220,84/03/07,8403130340
- --8403130349 "Offsite Dose Calculation Manual "
 * Niegare Mohawk Power Corp 84/03/01 83pp 22607 160 24X
 Fiche: 50-220, 84/03/07, 8403130340
- B403130353 Documents present resolution of SER open items & deficiencies noted in Franklin Research Ctr technical evaluation rept re environ quelification of safety-related electrical equipment RYBAM, B Commonwealth Edison Co 8121N 84/02/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 40pp 22617 080 24X Fichs 50-254,84/02/29,8403130353
- 8403130386 Forwards response to 840112 request for add1 info re NUREO-0737. Item II B 3, "Post-Accident Sampling Bys " Emergency Procedure EPP-9, "Determination of Core Damage Under Accident Conditions" also encl MANGAN. C. V Niagera Mohawk Power Corp 84/03/08 VARBALLO. D B Operating Reactors Branch 2 13pp 22605 010 24X Fiche. 50-220.84/03/08.8403130386
- 8403130480 Advises of effort to determine effect of dead leg piping extending into secondary conteinment, per NUREO-0737, Item II. B 2 & util 830916 ltr re environ qualification of sefety-related equipment.

 80RENSEN, 0 C Washington Public Power Supply System 002-84-112 84703/05, SCHWENCER, A Licensing Branch 2 2pp 22613, 214 24X Fichs. 50-397,84/03/05,8403130480
- B403130486 Forwards add1 info re Generic Ltr 82-33, "Suppl i to NUREGOOTS7 Requirements for Emergency Response Capability "
 Info suppls emergency operating procedures generation
 package submitted B30831,
 BDOKER, J. E. Gulf States Utilities Co. RBG-17137 84/02/27
 DENTON; H R Office of Nuclear Reactor Regulation, Director. 4pp
 22614:009, 24X Fithe:50-458,84/02/27.8403130486
- 8403130494 Forwards comments on 830930 detailed control room design review program plan per Buppl I to NUREG-0737 Specific areas of plan not described in enough datail to ensure that plan will meet requirements In-progress audit suggested VASEALLO,D B. Operating Reactors Branch 2 84/02/22 RHODE,OK Nisgara Mohaw Power Corp 13pp 22419 348, 24X Fiche 50-220,84/02/22,8403130494

- B403140001 Forwards comments on DES (NUREG-1026) Comments submitted for consideration by Commission per 10CFR51 MCDCNOUGH, C L Commonwealth Edison Co 4342E 84/03/12 Division of Licensing 13pp 22633 25; 24X Fiche 50~456,84/03/12,8403140001
- B403140019 Clarifies Sept 1983 draft technical evaluation rept of Phase II submittal of control of heavy loads.per 840109 telcon Bafe load paths for reactor bidg closed loop cooling water gumps revised MCCAFFREY.B R Long Island Lighting Co SNRC-1012 B4/03/05 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pp 22633 218 24X Fiche 50-322.84/03/05,8403140019
- 8403140040 Comments of JF Doherty on DES (NUREG-1026) Statement must clarify if in analysis of environ impacts of postulated accidents any credit given for applicant compilance w/any TMI-related requirements Related correspondence DOHERTY, JF Affiliation Not Assigned 84/03/07 STEVENS, J A Division of Licensing 2pp 22633 120 24X Fithe 50-456,84/03/07,8403140040
- B403140185 Forwards SER on NUREO-0737. Item II D 1 re performance tosting of BWR relief & safety valves Item satisfactorily resolved VASSALLO, D B Operating Reactor: Branch 2 84/02/24 MUSOLF, D M Northern States Power Co 17pp 22638 004 24X Fiche 50-263, 84/02/24, 8403140185
- 8403i4019i Forwards technical guidelines required by NUREG-0737, Buppl i,including guidence on station blackout conditions (Unresolved Safety Issue A-44), to be considered as response to Generic Ltr 81-04 COOK, K W Louislane Power & Light Co W3P84-0494 84/03/05 KNIGHTON, O W Liconsing Branch 3 337pp 22621 001 24X Fiche 50-382,84/03/05,8403140191
- B403140197 Forwards draft SER (NUREO-1057) re operation Proposed schedule for submittal of written response to open items should be provided by B40330 KM16HTON, G W Licensing Branch 3 84/03/01 WDQLEVER, E J Duquesne Light Co 3ilpp 22636 001 24X Fiche 50-412, 84/03/01, 8403140197
- 8403i40236 Forwards order confirming licenses commitments on emergency response capability VASSALLO,D B Operating Reactors Branch 2 84/02/22 UTLEY.E E Carolina Power & Light Co 2pp 22636 353 24X Fiche 50-324,84/02/22,8403140236
- --8403140239 Order confirming licensee commitment on emergency response capability per Generic Ltr 82-33 (Suppl 1 to NUREG-0737) EISENRUTD G Division of Licensing OL-82-33 84/02/22 Carolina Pawer & Light Co 5pp 22636 355 24x Fiche 50-324,84/02/22,8403140236
- 8403140246 Forwards comments on detailed control room design review program plan per Suppl 1 to NUREG-0737 Specific areas of plan not described in enough detail to provide assurance that applicable requirements will be met VASSALLO, D B Operating Reactors Branch 2 84/02/22 BAYNE, J P Power Authority of the State of New York 10pp 22636 343 24% Fiche 50-333,04/02/22,8403140246
- 8403140252 Forwards order confirming licenses 830415.0711 & 28 & 1230 commitments to comply w/Suppl i to NUREC-0737 rs emergency response capability VASSALLO.D B Operating Reactors Branch 2 84/02/22 FILANT.J M Nebraska Public Power District 2pp 22636 332 24X Fiche 50-298,84/02/22.8403140252
- --8403140256 Order confirming licenses commitments to comply w/Suppl 1 to NVREO-0737 (Generic Ltr 82-33) re emergency response capability CISCNUT.D G Division of Licensing QL-82-33 84/02/22 Nebraska Public Power District opp 22636 334 24% Fiche 50-278,84/02/22,8403140252
- 8403140285 Informs that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737, Item III A 2 I Reasonable assurance exists that prompt protective measures will be taken to protect public VASSALLO.D B Operating Reactors Branch 2 84/02/22 SINCLAIR, J B Vermont Yankes Nuclear Power Corp 3pp 22636 320 R4X Fiche 50-271,84/02/22,8403140285
- 8403140288 Forwards SSER re TMI Action Plan Items I C 1 & J C 8 of SER Confirmatory Issue 5 concerning guidance for evaluation & development of procedures for transients & accidents YOUNGBLGOD, B J Licensing Branch 1 GL-82-33 84/03/06 GARY, R J Texas Utilities Clectric Co (formerly Texas Utilities Clectric Co (formerly Texas Utilities Gunerating Co) bpp 22636 312 24X Fiche 50-445,84/03/06,8403140288

- 8403140293 Provides clarification of NRC favorable findings re SER Confirmatory Issue il for THI Action Plan Item I 6 i Util should either commit to perform natural circulation boron mixing test or ref boron mixing test at Diablo Canyon YOUNGELOOD 9 J Licensing Branch i 84/03/06 GARY.R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 22635 333 24X Fiche 50-445.84/03/06.8403140293
- 8403140299 Forwards request for add3 info re control of heavy loads Response requested within 60 days MILLER.J R Operating Reactors Branch 3 84/03/06 GRIFFIN.J M Ariansas Power & Light Co 2pp 22635 327 24X Fiche 50-313 84/03/06.8403140299
- B403i30040 Forwards request for add1 info to support conclusions re current design codes & criteria & load combinations in B20802 ltr per integrated plant safety assessment rept (NUREO-0823) CRUTCHFIELD. D Operating Reactors Branch 5 LSO5-84-03-010 B4/03/07 FARRAR, D. L. Commonwealth Edison Co. Bpp. 22643 084 24X Fiche 50-237,84/03/G9,8403150040
- 8403150058 NUREC-0020 VOB NOI LICENSED OPERATING REACTORS STATUS SUMMARY REPORT Data As Of December 31.1963 (Grey Bool) + Management Information Branch 84/02/29 396pp 22647 001
- 8403150092 Forwards results of in-progress audit of detailed control room design review Util pursuing course of review which NRC believes will satisfy requirements of Suppl 1 to NUREG-0737 CRUTCHFIELD. D Operating Reactors Branch 5 LS05-84-03-016 84/03/14 FARRAR.D.L. Commonwealth Edison Co 11pp 22643 002 24x Fiche 50-237.84/03/14.8403150092
- B403150146 Forwards IE Insp Rept 50-286/B4-02 on B40116-0215 & notice of violation STARDSTECKII.R Division of Project & Resident Programs 84/03/01 BRONS.J.C Power Authority of the State of New York 2pp 22643 027 24X Fiche 50-286.84/03/01.8403150146
- --8403i50i66 IE Insp Rept 50-286/84-02 on 840116-0215 Violation noted RNR sys changes not delineated on sys print or sys checkoff list & safety evaluation not performed KENNY.T J. ROSSBACH.L W. Region i. Office of Director NORRHDLMI.L Division of Engineering & Technical Programs IEB-79-15 84/02/22 13pp 22643 030 24X Fiche 50-286, 84/03/01,8403150146

8403150175 RiL-139 Research Info Ltr 139 provides appraisal of U dioxide fuel oridation phenomena & potential impacts on transportation of irradiated power reactor fuel assemblies Potential for occupational exposures during unloading major impact MINOGUE.R B Defice of Nuclear Regulatory Research. Director 84/03/05 DAVIS.J G Office of Nuclear Material Safety & Safeguards. Director 31pp 22646 311

- B403150198 forwards FR notice of eitension of comment period for DES (NUREG-1033) to B40312, per B40130 ltr KNIGHTON, G W Licensing Branch 3 84/02/27 HIRSCH, A Environmental Protection Agency 7pp 22662 028 24X Fiche 50-508,84/02/27.8403150198
- --8402270440 Notice of extension of comment period for DE8 (NUREG-1033) to 840312 KNIGHTON.C W Licensing Branch 3 84/02/24 ip 22662 035 24X Fiche 50-508.84/02/27.8403150198
- B403150211 NUREG-0885 103
 US NUCLEAR REGULATORY COMMISSION POLICY AND PLANNING
 GUIDANCE 1984
 * Commissioners 84/01/31 23pp Available at NRC \$3 00
 23662 139
- B403150R14 NUREO/CR-3605
 EVALUATION OF NUCLEAR FACILITY DECOMMISSIONING PROJECTS
 Summary Report Plum Broot Reactor Facility
 DDERGES D H. HILLERR L. United Nuclear Corp FIN B-7568
 B4/02/29 Division of Engineering Technology 34pp Available at
 NRC \$4 25 22649 032 24X Fiche 50-030.84/02/29,8403150214
- B403150219 NUREQ/CR-3422 VO2
 AEROSOL RELEASE AND TRANSPORT PROGRAM Quarterly Progress
 REPORT For April June 1983
 ADAMS, K. E. TORIAS, H. L. Dak Ridge National Laboratory FIN B-0121
 CRRA.7TH-8849/V2 B4/02/29 Division of Accident Evaluation
 3298 22662 087

- 8403150243 Forwards order confirming commitments to implement past-THI-related items set forth in Suppl 1 to NUREG-0737. "Requirements for Emergency Rasponse Capability," based on util 821217 response to Generic Ltr 82-33 STDLZ.JF Operating Reactors Branch 4 GL-82-33 84/02/21 CROUSE.R P Yoledo Edison Co 1p 22649 001 24X Fichs 50-346,84/02/21,8403150243
- --B403150246 Forwards order confirming licensee commitments re emerging response capability for transmittal to Ofc of FR for publication

 Operating Reactors Branch 4 OL-82-33 84/02/21 Docketing Services Branch 2pp 22649 002 24X Fiche 50-346.84/02/21.8403150243
- --8403150250 Order confirming licensee commitments on emergency respondence capability, per requirements set forth in Suppl 1 to NUREO-0737. "Requirements for Emergency Response Capability "
 EISENHUT.O O Division of Licensing OL-82-33 84/02/21 Toledo Edison Co 6pp 22647 003 24X Fiche 50-346.84/02/21:
- B403i60020 informs that facility will employ 17 1 paid setpoint for containment isolation as reflected in current draft Tech Specs.per Item II E 4 2 of NURE9-0737 Item should be closed in next SSER COOK.K W Louisians Power & Light Co W3P84-0615. B4/03/12. KNIOHTON.0 W Licensing Branch 3 2pp 22653 351 24X Fiche 50-382.84/03/12.8403160020
- B403160026 Notifies that Natl Ctr for Devices & Radiological Health in comment re postulated plant accidents described in DEB (NUREG-0974) VILLERTH J C Food & Drug Administration 84/02/10, BCHMENCER, A Licensing Branch 2 1p 22654 346 24X Fiche: 50-352, 84/02/10, BCHMENCER, A Licensing Branch 2 1p 22654 346 24X Fiche: 50-352, 84/02/10, BCML CONT.
- B403160080 Submits addl info on Generic Ltr B2-33 schedule requiremen for emergency response capabilities. Vendor of new computer sys requested 1-yr delay to June 1985 for delivery. Affecting schedular commitments made to MRC FAY.C W Misconsin Electric Power Co QL-82-33. 84/03/08 DENTON.H R Office of Nuclear Resctor Regulation, Director 4pp. 22652 327 24X Fiche 50-266.84/03/08.8403160080
- B403160214 Forwards IE Insp Repts 50-390/B3-56 & 50-391/B3-44 on B31225-B40120 No violations or deviations identified VERRELLI, DM Division of Project & Resident Programs B4/02/17 PARRIS.H 9 Tennessee Valley Authority 2pp 22661 067 24X Fiche 50-390/B4/02/17/8403160214
- ~~8403i60222 IE Insp Repts 50~390/83~56 & 50~391/83~44 on 831225~8401; No violation or deviations identified Major areas inspected; action on previous enforcement matters & insp items, followup on licensee identified items & verification of as-builts.

 SHYNLOCK.M B , BHAN.W B , HOLLAND.W E, Region 2, Office of Director 50~391/83~44 B4/02/16 9pp 22661*069, 24X Fiche 50~390, B4/02/17,8403160214
- 8403160237 Forwards IE Insp Rept 50-390/84-09 on 840130-0203. No violations or deviations noted VERRELLI, D M Division of Project & Resident Programs. 84/02/27. PARRIS. H 9 Tennessee Valley Authority 2pp 22660-315 24X Fiche 50-390,84/02/27.8403160237
- --B403160240 IE Insp Rept 30-390/84-07 on B40130-0203 No violations of deviations noted Major areas inspected const status & as-built configuration for radioactive resin transfer sys & preoperational testing of radwaste sys HOSEY.C M Region 2. Office of Director BARR, K.P. Division of Engineering & Operational Programs. B4/02/23 Bpp 22660; 317. 24X Fichs 50-370,84/02/27,8403160237
- 8403160249 Ack receipt of 840217 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-R61/BD-35, implementation of corrective actions will be exemined during future insps.

 LEMIS.R C Division of Project & Resident Programs 84/02/29, UTLEY.E E Carolina Power & Light Co ip 22660-299, 24X Fiche 50-261.84/02/29.8403160249
- --8403160262 Responds to NRC 84011B ltr re violations noted in IE Insp. Rept 50-261/83-35 Corrective actions Emergency Procedure PEP-105 will be revised to implement recommendations of IE Info Notice 83-28 & NUREO-0654 MORRAN.R E Carolina Power & Light Co. IEIN-83-28. 84/02/17 O'REILLY,J P' Region 2, Office of Director 3pp. 22660 300 24 Fiche 50-261,84/02/29,8403160249

- --8403160300 IE Insp Rept 50-261/83-35 on 831205-09 Violation noted IE Info Notice 83-28 guidance not incorporated into Emergency Procedure PEP-105. "Emergency Control General Emergency " STODDART.P G Region 2. Office of Director JENKINS.G R Division of Emergency Preparedness & Materials Safety IEIN-83-28 84/01/11 7pp 22660 305 24X Fiche 50-261.84/02/29.8403160249
- 8403160264 Forwards IE Insp Repts 50-335/83-42 & 50-389/83-70 on 831101-1210 No violations or deviations noted DANCE: H C Division of Project & Resident Programs 84/02/24 WILLIAMS, J W Florida Power & Light Co 2pp 22660 335 24X Fichs 50-335,84/02/24,8403160264
- --8403i60268 IE Insp Repts 50-335/83-42 & 50-389/83-70 on B3iiii~i210 No violations or deviations noted Major areas inspected maint & surveillance observation.plant operations.LERs & IE info notices

 BIBB.H E Region 2, Office of Director ELROD, S A Division of Project & Resident Programs 50-389/83-70 84/02/23 10pp 22660 337 24X Fiche 50-335.84/02/24.8403i60264
- 8403160338 Ack receipt of 840206 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-32 & 50-366/83-34

 DANCE.H. C Division of Project & Resident Programs 84/03/09

 KELLY.R J Georgia Power Co ip 22660 015 24X

 Fiche 50-321,84/03/07,8403160338
- --8403160365 Notice of deviation from insp on 831114-18 * Region 2, Office of Director 50-366/83-34 84/01/06 1p 22660 020 24% Fiche 50-321,84/03/09,8403160338
- --8403140372 IE Insp Repts 50-321/83-32 & 50-326/83-34 on 83ii14-i8 Deviation noted failure to electronically calibr high range drywell radiation monitors, per NUREQ-0737, Item II F i WRAY, J R Region 2, Diffice of Director BARR, KP Division of Engineering & Operational Programs 50-326/83-34 84/01/04 7p 22660 021 24X Fiche 50-321,84/03/09,8403i60338
- 840319000B Submits mod to agenda for CRGR Meeting 45 on 830817 in Bethesda, MD to discuss NUREQ-0737, Suppi i control room design review & NRR study of electromagnetic pulse BTELLO, V Committee to Review Generic Requirements 83/08/15 MATTSON, R J Division of Systems Integration (post 811005) JDRDAN, E. L. Director's Défice. Office of Inspection and Enforcement CUNNINOHAM, R E Office of Nuclear Material Bafety & Bafeguards, Director 2pp 22664 361
- 8403190009 Notifies of CROR Meeting 58 on 840315 to discuss proposed NUREO-OBOI, "Evaluation Criteria for Detailed Control Room Design Review "
 8TELLO, V. Committee to Review Generic Requirements 84/03/02 MATTSON, R.J. Division of Systems Integration (post 81:005), JORDAN, E. D. Division of Systems Integration and Enforcement CUNNINGHAM, R.E. Office of Nuclear Material Bafety & Safaguards, Director ip 22665:352
- 8403190018 Forwards Calvert Cliffs Instruction CCI-310, "Emergency Operating Procedure Writers Ouide," implementation schedule, validation verification plan & training plan per Suppl i to NOREG-0737
 LUNDVALL.A E Baltimore Qas & Electric Co 84/03/14 HILLER, J R Operating Reactors Branch 3 Dpp 22666 O01 24X
 Fiche 50-317,84/03/14,8403190018
- 8403190029 Notifies of CRGR Meeting 57 on 840213 to discuss proposed NUREG-0801, "Evaluation Criteria for Detailed Control Room Design Review" & NUREG-0835, "Human Factors Review Guidelines for Safety Parameter Display Sys "
 STELLD, V Committee to Review Generic Requirements 84/02/07 MATTSON:R J Division of Bystems Integration (post 811005), JORDAN.E.L Director's Office, Office of Inspection and Enforcement CUNNINGHAM,R E Office of Nuclear Material Bafety & Bafeguards, Director ip 22665 362
- 8403190031 Notifies of CRQR Meeting 44 on 830802 in Bethesda, MD to discuss NUREO-0978, re behavior of BUR Mark III containment & commission paper re integrated safety assessment program STELLO, V Committee to Review Generic Requirements 83/07/22 MATTSUN, R. J. Division of Systems Integration (post 811005) JCRDAN, E. L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety 2pp 22666, 113
- B40319004B Informs that util postponed ultrasonic test/insp of saferend, nozzle bore & blend regions of feedwater nozzle per NUREO-0619, due to installation of low flow feedwater controller COUNSIL.W.O Northeast Nuclear Energy Co (subs of Northeast Utilities). COUNSIL.W.O Northeast Utilities B11056 B4/03/05 CRUCTHFIELD.D Operating Reactors Branch 5 2pp 22666 251 24% Fiche: 50-245, 84/03/05, 840319004B

- B403170052 Informs that local emergency operations facilities at North Anna & Surry Power Stations will be functional, except for data communications & display.by B50731.per NUREG-0737, Buppl 1 STEWART, W L Virginia Electric & Power Co 137 84/03/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22666 173 24X Fiche 50-000.B4/03/14.B403190052
- 8403190055 NUREG/CR-3645
 A GUIDE TO LITERATURE RELEVANT TO THE ORGANIZATION AND
 ADMINISTRATION OF NUCLEAR POWER PLANTS
 SOMMERB,P Battelle Human Affairs Research Centers
 Hemorial Institute, Pacific Northwest Laboratories FIN B-2360
 PNL-4906 84/02/29 Division of Health, Siting & Waste
 Hanagement 656pp 22678 001
- 8403190056 Responds to constituent RE Buris 840123 request for info re accident Forwards "Population Dose & Health Impact of Accident at THI Beation." (AUREO-0558) W/o encl BIRCKS,W J Office of the Executive Director for Operations 84/03/05 HEFLIN.H Senate 3pp 22681 317 24X Fiche 50-320.84/03/05.8403190056
- 8403170073 Forwards questions for FEMA witnesses to assist in preparation of tostimony on offsite emergency planning contentions Ail testimony will be required to be filed on 840406 & 09 Hearing will commence on 840424 W/o encl MCGURRCN.H J Hearing Branch 3 84/03/15 PERRY,S Federal Fmergency Management Agency ip 22666 135 24x Fiche 50-413.84/03/15.8403190073
- 840319017B Forwards safety evaluation approving util response to NUREG-0737. Item II K 3 44, "Evaluation of Anticipated Transients W/Single Failure to Verify No Fuel Failure " Issue resolved CRUTCHTIELD D Operating Reactors Branch 5 L505-84-03-020 84/03/15 VANDEWALLE.D J Consumers Power Co 6pp 22671 167 24X Fichs 50-155,84/03/15,8403190178
- 840317025i Submits agenda mods for CRGR Meeting 55 on 840125 reproposed IE bulletin on GE HFA relays & NUREG-0801 on criteria for detailed control room design STELLO, V Regional Operations & Generic Requirements 84/01/3i MATT90N.R J Office of Nuclear Reactor Regulation. Director JURDANIE L Director's Office of Inspection and Enforcement CUNNINGHAM.R E Office of Nuclear Material Safety & Bafeguards, Director 1p 22672 270
- --8403190254 Notifies of CRGR Meeting 55 on 840125 in Bethesda, MD to discuss draft IE bulletin. "Failure of GE Type HFA Relays in Use in Class IE Safety Sys." NUREG-0801 & NUREG-0805 STELLO, V Regional Operations & Generic Requirements 84/01/09 MATTBON, R J Office of Nuclear Reactor Regulation, Director JORDAN, EL Director's Office of Inspection and Enforcement CUNNINOHAM, R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22672 271
- 8403170258 Ack receipt of 840214 itr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Rept 50-286/81-05 MARTIN, T T Division of Engineering & Technical Programs 84/03/13 BRONS, J C Power Authority of the State of New York 2pp 22672 221 24X Fiche 50-286,84/03/13,8403170258
- --8403190265 Responds to NRC Billi9 ltr re violations noted in IE
 Emergency Preparedness Appraisal Rept 50-286/81-05
 Corrective actions, post-accident instrumentation & sampling
 requirements per NUREG-0737 & Reg Guide i 97 implemented
 BRONS, J C Power Authority of the State of New York 84/02/14
 MARTIN, T T Division of Engineering & Technical Programs 2pp
 22672 223 24X Fighe 50-286,84/03/13,8403190258
- B403170276 Responds to B40208 request for info re emergency operations facility (EDF), specifically preliminary cost estimate for upgrade to overall radiation protection factor of five Existing EOF meets Suppl 1 to NUREG-0737 requirements BAYNE, J. P Consolidated Edison Co of New York. Inc INP-B4-10 B4/03/14 VRGA:S A Operating Reactors Branch 1 2pp 22674 354 24X Fiche 50-286,84/03/14,8403190296.
- 8403170314 Forwards IE Insp Repts 50-295/83-27 & 50-304/83-28 on 831122-1228 & 840202 & notice of violation Concerns re mgt control inadequacies, per THI Action Plan Item II F i i, "Noble Gas Effluent Monitor," expressed HIND, J A Division of Radiological & Materials Safety Programs 84/03/01 REED, C Commonwealth Edison Co 2pp 22673 196 24X Fiche 50-295,84/03/01,8403190314
- --8403190334 IE Insp Repts 50-295/83-27 & 50-304/83-28 on 831122-840202 Violation noted failure to follow plant procedures re source handling, to evaluate radiological hazards & to control access to high radiation area LOVENDALE, P C Region 3, Office of Director 50-304/83-28 84/02/29 14pp 22673 201 24X Fiche 50-295,84/03/01,8403190314

- 8403i903P5 Informs that requested info re core exit thermocouples & subcooling margin monitors per NUREG-0737 & Generic Ltr 82-28 will be provided by 841231 WITHERS D Portland General Clectric Co GL-82-28 84/03/12 FISENHUT.D 0 Division of Licensing ip 22673 239 24X Fiche 70-344,84/03/12,840319025
- B403i90345 Forwards clarification of previous responses to NRC Guestions 8,9,12 & 13 re discharge piping sys & "EPRI PWR Safety & Relief Valve Test Program Guide" Info satisfies requirements of TMI Item II D I MEDFORD, M O Southern California Edison Co B4/03/14 KNIGHTON, O W Licensing Branch 3 11pp 22675 079 24% Fische 50-361,84/03/14,8403190345
- B403190355 Forwards revised schedule re safety assessment sys/safety parameter display sys per Suppl 1 to NUREO-0737 Assessment indicates contractor capable of completing job 0'TODLE.J D Consolidated Edison Co of New York. Inc 84/03/12 LISENBUT.D O Division of Licensing 4pp 22675 176 24X Fiche 50-247.04/03/12.0403190355
- E403190343 Forwards evaluation of LILCO transition plan per NUREG-0654/ FEMA-RIP-1. Rev 1 Deficiencies noted SPECK, S W Federal Emergency Management Agency 84/03/15 DIRCKS, W J Office of the Executive Director for Operations 71pp 22673 081 24X Fiche 50-322.84/03/15.8403190363
- B403190379 Forwards IE Insp Rept 50-305/83-17 on B31216-840215 No noncompliance noted SHAFER.W D Region 3. Office of Director 84/02/27 GIESLER.C W Wisconsin Public Service Corp 2pp 22675 209 24X Fiche 50-305.04/02/27.8403190379
- --B4001903B4 IE Insp Rept 50-305/B3-17 on B31219-B40215 No noncompliance noted Major areas inspected maint, surveillance, independent insperegional requests & operational safety NELSON, R L., JACKINJ N Region 3, Office of Director 84/02/24 Spp 22675 211 24X Fiche 50-305.84/02/27,8403190379
- 8403i90377 Provides updated info re mods required by NUREC~0737. Item
 11 D 1 2 re safety & relief valve performance Unit 1 piping
 & supports will be installed during neit refueiing outage
 scheduled for 850105
 MUSDLF.D Northern States Power Co 84/03/14 Office of Nuclear
 Reactul Regulation. Director 1p 22675 192 24X
 Fiche 50-282.84/03/14.8403190397
- 8403190437 NUREG/CR-3666
 ASSESMENT OF THE IMPLICATIONS OF CONVERSION OF UNIVERSITY
 RESCARCE AND TRAINING REACTORS TO LOW ENRICHMENT URANIUM
 FUEL
 HARRIES D R. BURNIR R. CLARKIL
 TYON, NY FIN D-1126 84/02/29
 165pp Available at NRC \$5.50
 22680 001
- 8403190444 NUREG/CR-3508
 STANDARD SETTING STANDARDS A SYSTEMATIC APPROACH TO MANAGING PUBLIC HEALTH AND SAFETY RISKS
 FISHCHOFF, D Decision Research Inc * Dak Ridge National Laboratory FIN B-0424 CRNL/SUB-7576/3 84/02/29 Division of Risk Analysis & &pp 22681 004
- B403;90449 NUREO/CR-3573
 PERBINNEL EXPOSURE FROM RIGHT CYLINDRICAL SOURCES (PERCS)
 The Theory.The Code And Examples
 REFCE.D D . HADLEY.R T . HARDTY.R Battelle Memorial Institute.
 Pacific Northwest Laboratories FIN B-2412 PNL-4923 B4/01/31
 Division of Engineering Technology 173pp Available at NRC
 \$5 50 22680 170
- 8403200005 Responds to 840227 request for add1 action to verify aspects of overhead crané design at facility.per NUREG-0612 guidelines Crane safety & reliability satisfactory GUCHA,L T Georgia Power Co NED-84-127 84/03/12 STOLZ.J F Operating Reactors Granch 4 2pp 22685 209 24X Fiche 50-321.84/03/12.8403200005
- 8403200053 Forwards monthly operating repts for Feb 1984 & revised monthly operating repts for Aug 1983 Jan 1984 Revs reflect values reserved from beginning of commercial operation, per NUREG-0020 HAYNES, J G Southern California Edison Co 84/03/15 Office of Resource Management. Director 19 22685 001 24X Fiche 50-361.84/03/15.8403200053
- 8403200099 Forwards schedule for implementation of chivities for control of heavy loads.per NRC requests re NR4F0-0612 Cask pit gate listing lugs will be modified by 84 015 HUXILL. H D General Public Utilities GPU trvice Corp 3211-84-2072 84/03/15 EISEN#UT. D G Division of Licensing 3pp 22485 313 24X Fiche 50-289,84/03/15.84032000079

- 84032001/7 Forwards comparison of proposed radiological effluent Tech Specs (RETS) w/model SWR RETS & comparison of proposed offsite dose calculation manual w/NRC generic guidelines & NUREO-0133 CRUTCHTSELD. D Operating Reactors Branch 5 LS05-84-03-021 84/03/15 VANDEMALLE, D J Consumers Power Co 157pp. 22697 206 24X Fiche 50-155.84/03/15.8403200177
- 8403200185 Affirms resolution of TMI Action Plan Item II, K 3 31 re small break LOCA analysis No further action necessary JENS. H H Detroit Edison Co OL-83-35 84703714 YOUNGBLOOD, B, J Licensing Brench I 2pp 22686 338 24X Fiche 50-341.84703714, 8403200185
- B403200223 Application for amend to Licenses DPR-58 & DPR-74.revising Tech Specs re reactor coolant vent sys per TMI Item II II I Justification for NSHC provided in 840120 ltr still applicable ALEXICH, M P Indiana & Michigan Electric Co AEP NRC-0584C 84/03/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22690 190 24X Fiche 50-315.84/03/15,8403200223
- ---8403200228 Revised proposed Tech Specs for reactor coolant vent sys per THI Item II B i * Indiana & Michigan Electric Co 84/03/15 7pp 22690 192 24X Fiche 50-315.84/03/15.8403200223
- 8403200225 Advises that similarity of Unit 1 & 2 175-ton polar crans verified by noting that cranes purchased under same contract w/same vendor.using identical procurement specs.per NUREG-0612 & 840223 tolcon MILLS.L M Tennessee Valley Authority 84/03/14 ADENSAM.E Licensing Dranch 4 Epp 22679 361 24X Fiche 50-390.84/03/14, 8403200225
- 8403200238 Comments on DES (NUREO-1033) Assertions re socioeconomic impacts from station operation demonstrate low level of expertise among study team or refusel to consider relevant research findings on social impacts
 FREUDENBURG, W Washington State Univ , Pullman, WA 64/03/12, VIETTIA Division of Licensing 2pp 22691 111 24X
 Fiche 50-508,84/03/12,8403200238
- 8403200261 Advises that control equipment for air operators CSP-AD-5, CSP-AD-6 & CSP-AD-9, listed on Table B of 10GFRSO 49
 Justification for interim operation revised to not qualified Status to be upgraded by 850331 commitment date SDRENSEN, 0 C Washington Public Power Supply System 002-84-131, 84/03/14 SCHMENCER, A Licensing Branch 2 2pp 22690 199, 24X Fiche: 50-397, 84/03/14, 8403200261
- 8403200358 NUREG/CR-3501
 THE EFFECTS OF DELAYING THE OPERATION OF A NUCLEAR POWER
 PLANT
 HILL,L J, RAINEY,J A, TEPEL,R C Oak Ridge National Laboratory,
 Fin B-0472 ORNL/TM-8684 84/0i/3i Division of Health, Siting &
 Waste Management 47pp 22709 010
- 8403210030 Forwards justification for exemption from Type C leak testing, iist of isolation valves within essential sys & penetration isometric drawings re finalization of Tech Spacs in preparation for GL COOK, K W Louisiana Power & Light Co W3P64-0577 84/03/16. KNIGHTON, 0 W Licensing Branch 3 17pp 22707 016 24X Fiche 50-382.84/03/16.6403210030
- 8403210061 Forwards response to B40202 request for add1 info re NVREO-0737, Items II F i 4. "Containment Pressure Monitor Sys." II F i 5. "Containment Water Level Monitor Sys." & II F i 6. "Containment Hydrogen Monitor Sys." & ZIMMERMAN, S R Carolina Power & Light Co NLS-84-111 84/03/09. VASSALLO, D B Operating Reactors Branch 2 20pp 22705 001. 24X Fiche 50-324.84/03/09.8403210061
- 8403210068 "1983 Annual Rept " W/840301 ltr HEIDER.L.H Yankee Atomic Electric Co FYR 84-27 83/12/31. MURLEY.T E Region 1, Office of Director 9pp. 22705-043 24X Fiche 50-029.83/12/31.8403210068
- 8403210127 Responds to 840202 request re TMI Action Itam II. K. 3. 18 concerning automatic depressurization sys (ADS) logic mods High dryweli pressure permissive eliminated & manual inhibit switches to ADS logic added HOME. P W Carolina Power & Light Co NLS-84-102 84/03/09 VASSALLO, D B Operating Reactors Branch 2 lp 22707.235 24X Fiche 50-324.84/03/09,8403210129
- 8403210175 Forwards HD Hukill B40222 & 27 ltrs re emergency feedwater sys flow instrumentation & NUREO-0737 selective item status, respectively Svr list encl BAXTER.T A Shaw, Fittman, Potts & Trowbridge BAXTER.T.A. Metropolitan Edison Co DSB 005 84/03/20 CHILK.S.J Office of the Secretary of the Commission 27pp 22710 104 24X Fiche 50-289.84/03/20,8403210175

- 8403210195 Requests identification of any potential problems in completing NUREG-0737 items by Sept 1984 Response requested within 30 days of ltr receipt VARGA-8 A Operating Reactors Branch 1 84/03/02 CLAYTON,F L Alabama Power Co 2pp 22709 176 24X Fiche 50-348,84/03/02,8403210195
- 8403220012 Forwards responses to listed B31207 requests for info re environ qualification of electrical equipment, including resolution of deficiencies & TMI action plan items (MMREO-0737) to be installed at end of Cycle 10 outage FIEDLER, P B General Public Utilities GPU Service Corp 84/03/16 CRUTCHFIELD, D Operating Reactors Branch 5 18pp 22712 343 24 Fiche 50-219,84/03/16,8403220012
- 8403220093 Ack receipt of 840306 ltr informing NRC of corrective actions re deviation from commitment & resolution of revised emergency plan SER clarification items noted in IE Insp Repts 50-266/83-25 & 50-301/83-25 PAPERIELLD, C J Region 3, Office of Director 84/03/19 BURSTEIN, S Wisconsin Electric Power Co 1p 22716 324 24) Fiche 50-266.84/03/19.8403220093
- --B403220099 Responds to NRC 840202 ltr forwarding revised emergency plan BER & request for clarification of listed items & deviation from commitment Corrective actions Procedure EP 5 0.
 "Organizational Control of Emergencies:" revised FAY.C W Wisconsin Electric Power Co 84/03/06 KEPPLER, J G Region 3, Office of Director 9pp 22716 325 24X Ficha 50-266,84/03/19,8403220093
- B403220094 Forwards IE Insp Repts 50-454/84-10 & 50-455/84-08 on B40131,0201-03 & 07-10 No noncompliance noted PAPERIELLO, C J Region 3, Office of Director 84/03/07 REED, C Commonwealth Edison Co 2pp 22716 311 24X Fiche 50-454.B4/03/07.B403220094
- --8403220097 IE Insp Repts 50-454/84-10 & 50-455/84-08 on 840131.0201-03 & 07-10 No noncompliancs noted Major areas inspected preoperational radiation protection program. Including organization. staffing. training & NUREO-0737 items HUETER.L J. OREOER,L R. Region 3. Office of Director 50-455/84-08 84/03/07 ilpp 22716 313 24X Fiche 50-454,84/03/07.8403220094
- B403220107 Forwards safety evaluation re TMI Item II K 2 17.
 "Potential for Voiding in RCB During Translents " Bafety
 evaluation documenting completion of item encl
 STOL7.JF Operating Reactors Branch 4 B4/03/05 HUKILL.H D
 Omneral Public Utilities GPU Bervice Corp 4pp 22723.288 24X
 Fiche 50-289.84/03/05.8403220107
- 8403220143 Forwards IE Insp Rept 50-322/84-02 on 840123-0226 No violations found BTARDSTECKI, R Division of Project & Resident Programs 84/03/04 POLLOCK, M S Long Island Lighting Co 2pp 22714.317 24X Fiche: 50-322, 84/03/04, 8403220143
- --8403220160 IE Insp Rept 50-322/84-02 on 840123-0226 No violations found Major areas inspected IE Bulletin 80-07 (Detail 3), TMI action items, review of emergency diesel generator testing & previously identified insp findings PETRONE.C., SHEDLOSKY, T. MCCABE, E.C. Region 1, Office of Director IEB-80-07 84/02/28 10pp 22714 319 24X Fiche 50-322,84/03/06,8403220143
- 8403220162 Application to amend Licenses DPR-24 & DPR-27, changing Tech Specs to add add1 restrictions on heavy loads over spent fuel pool & making additions & deletions re safety-related snubbers; per IE Buljetin 79-14 & Item II D 1 FAY, C. W. Wisconsin Electric Power Co IEB-79-14 84/03/16 DENTON: HR Office of Nuclear Reactor Regulation, Director MILLER, T R Operating Reactors Branch 3 4pp 22718 057 24X Fiche. 50-266, 84/03/16, 8403220162
- E403220189 NUREQ-0430 V04 N01 LICENSED FUEL FACILITY STATUS REPORT Inventory Difference Data, January 1983 - June 1983 (Grey Book) # Director's Office. Office of Inspection and Enforcement B4/03/31 14pp 22721.097
- 8403220192 Forwards "Control of Heavy Loads, Phase II " Rept result of review of crane operation, design & maint including analysis of load drop risk to safetu-related equipment beneath travel paths Confirms defense-in depth, per NUREQ-0612, HHITTIER: 0 D. Mains Yankee Atomic Power Co GDW-84-33, 84/03/19 HILLER, JR Operating Reactors Branch 3 2pp 22717 048 24X Fiche, 50-309, 84/03/19,8403220192
- --8403220177 "Control of Heavy Loads, Phase II"

 # Maine Yanker Atomic Power Co 2763L-SEN 84/03/17 124pp
 22717-050, 24X Fiche 50-309,84/03/19,8403220192.

- 8403220215 Notification of 840327 meeting w/Westinghouse & Westinghouse Owners Group Procedures Subcommittee in Bethesda.MD to discuss how EPG tark analysis addressed operator info & control needs, per NUREG-0737. Suppl 1 CLAYTON.H B Procedures & Systems Review Branch QL-82-33 84/03/05 ZIEMANN.D L Procedures & Systems Review Branch 2pp 22721 361
- 8403220301 Forwards interim draft SER (NUREC-1047) identifying Unresolved issues as open items Complete draft SER expected to be reissued in May 1784 Detailed agenda aimed at resolving open items requested SCHMENCER, A Licensing Branch 2 84/03/08 RHODE. G K Niagara Mohawk Power Corp 456sp 22720 001 24X Fiche 50-410,84/03/08,840320301
- B403220326 NUREG-0978 FC
 MARK III LOCA-RELATED HYDRODYNAMIC LOAD DEFINITION Generic
 Technical Activity D-10
 * Division of Systems Integration (post 811005) 84/02/29 75pp
- 8403230009 Ack receipt of BA0221 order confirming commitments to implement post-TM1-related items in Suppl 1 to NUREG-0737 re emergency response capability status for completing each basis requirement submitted CROUSE.R P Tolydo Edison Co 1033 84/03/20 EISENHUT,D G Division of Licensing App 22730 133 24X Fiche 50-344,84/03/20,8403320009
- 8403230029 Forwards response to request for addI info concerning Suppl 1 to NUREG-0737 re procedures generation package & Rev I to emergency procedures guidelines COUNSIL,W G. SEARS, C.F. Northeast Nuclear Energy Co. (subs of Northeast Utilities) COUNSIL,W G. Northeast Utilities A03666 84703709 CRUICHFIELD, D. Depending Reactors Branch 5 44pp 22728 210 24X Fiche 50-245.84703709.8403230029
- 8403230040 Responds to NUREO-0737, Item II D i re relief & cafety valve testing, per 840215 Itr Facility adequately represented by EPRI valve tests Precaution of 1,000 psig overly conservative HUMILL.H D General Public Utilities GPU Service Corp 5211-84-2073 84/03/20 STGLZ, J F Operating Reactors Branch 4 1p 22724 331 24X Fiche 50-289,84/03/20,8403230040
- 8403230057 NUREC/CR-3422
 A PROBABILISTIC MODEL OF ANNULAR-DISPERSED FLOW IN A REACTOR SUBCHANNEL AS SEEN BY CYLINDRICAL GEOMETRY IMPEDANCE PROBES ALLGODD, 0 O . ROBERTS, M J Oak Ridge National Laboratory FIN B-0414 ORNL/TH-8841 84/02/29 Division of Accident Evaluation 65pp 22742 300
- B40323006B LER B4-001-00 on B40223.pipe snubber ID 2HS-M75 removed for NUREG-0737 mod prior to obtaining Tech Spec change allowing removal Snubber reinstalled within 72 h Tech Spec change to delete snubber initiated W/640315 ltr
 FAY.C W Wisconsin Electric Power Co B4/03/15 KEPPLER.J G Region 3. Office of Director 3pp 22726 324 24X
 Fiche 50-301.84/03/15.840323006B
- 8403230085 Forwards safety evaluation of BWR Owners Group generic response to NUREG-0737. Item II K 3 45 re depressurization w/other than automatic depressurization sys (ADS) No mods to plant design & operation required CRUTCHFIELD. D Operating Reactors Branch 5 L805-84-03-027 84/03/20 COUNSIL, W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) Spp 22726 335 24X Fiche 50-245, 84/03/20, 8403230085
- B403230131 NUREO/CR-3145 VO2 GEOPHYSICAL INVESTIGATION OF THE WESTERN OHIO - INDIANA REGIDN Annual Report, October 1982 - September 1983 PULLACK, H N . CRRIBTENSEN, D Hichigan, Univ of, Ann Arbor, MI B4/03/30 Division of Health, Siting & Waste Management. 64pp 22739 232
- B403230133 NUREG/CR-3529
 REVIEW OF THE ARKANSAS NUCLEAR ONE GENERATING STATION UNI:
 NO 1 EMERGENCY FEEDWATER SYSTEM RELIABILITY ANALYSIS
 YOUNGBLOOD, R. PAPA20GLOU, I A Brockhaven National Laboratory
 BNL-NUREG-51721 84/02/29 Division of Safety Technology 104;
 22739 130 24X Fiche 50-313,84/02/29,8403230133
- B403230143 Forwards corrected safety evaluation re NUREC-0737.

 Item 11 K 3 44, "Evaluation of Anticipated Transients w/Bingle Failure to Verify No Fuel Failure " Item resolved for facility (RUTCHFIELD.D) Operating Reactors Branch 5 LS05-B4-03-031 B4/03/22 VANDCHALE.D J Consumers Power Co 5pp 22730 142 24X Fiche 50-155.84/03/22.8403230143

8403230173 NUREG/CR-3560
EVALUATION METHODS FOR THE CONSEQUENCES OF BELOW WATER TABLE
MINE DISPOSAL OF URAMIUM MILL TAILINGS
MCKEON,T J , NELSON,R W Battelle Hemorial Institute, Pacific
Northwest Laboratories FIR B-2370 PNL-4904 84/01/31
Division of Health, Siting & Haste Management 90pp 22742 217

8403230177 MUREG/CR-3104
AGUIFER RESTORATION TECHNIQUES FOR IN-SITU LEACH URANIUM
MINES
DEUTSCH, W J . BELL. N E . MERCER, B W Battelle Memorial Institute.
Pacific Northwest Laboratories FIN B-2379 PML-4583 84/02/29
Division of Mealth. Siting & Maste Management 58pp Available at
NRC 14 50 22739 121

B403230163 NUREQ-0750 V1B NO4 NUCLEAR REQUIATORY COMMISSION ISSUANCES October 1983 Pages 743-1,137 • Division of Technical Information & Document Control B3/10/31 400nn 22813 040

840323019D NUREG-1015 STATE SURVEILLANCE OF RADIOACTIVE MATERIAL TRANSPORTATION Final Report SALOMON,S N Office of State Programs, Director 84/02/29 72pp Available at NRC 84 50 22759 048

8403230197 NUREG/CR-3390
DDCUMENTATION AND USER'S GUIDE UNSAT2 - VARIABLY SATURATED FLOW MODEL (Including 4 Example Problems)
DAVIS.L A. MEUMANN.S P Hater, Waste & Land, Inc FIN B-7361
WHL77H-1791-1 83/12/31 Division of Waste Management 218p; 22742 Ooi

B403230200 NUREG/CR-3621
SAFETY SYSTEM STATUS MONITORING
LEWIS,J R, MORGENSTERN,M, RIDEOUT.T B Battelle Memoriai
Institute, Pacific Northwest Laboratories FIN 8-2360 PNL-4832
84/03/31 Division of Human Factors Safety 127pp Available at
NRC \$5 50 22741 077

8403230207 NUREC/CR-3674
DESIGNING VEGETATION COVERS FOR LONG-TERM STABILIZATION
UF URANIUM MILL TAILLINGS
BEEDLOW, P A Dattelle Memorial Institute, Pacific Northwest
Laboratories FIN B-2370 PNL-4986 84/03/31 Division of
Health, Siting & Waste Management 103pp 22741 207

8403230208 NUREO/CR-3651
PROTOTYPICAL STEAM GENERATOR (MB-2) TRANSIENT YESTING
PROBRAM Task Plan/Scaling Analysis Report
YOUNG,M, TAKEUCHI,K, MENDLER,J Westinghouse Electric Corp FIN
B-8252 EPRI NP-3494 84/03/31 Division of Accident Evaluation
198pp Available at NRC \$6.00 22743 096

8403230212 NUREC-0504 V04 ND1 UNRESN'VED SAFETY ISSUES SUMMARY Data As of February 17.1994 (Aqua Book) Management Information Branch 84/02/27 55pp 22743 294

8403930216 NUREC/CR-3224
AN ASSESSMENT OF CRBR CORE DISRUPTIVE ACCIDENT ENERGETICS
THEOFANOUS.T G , BELL.C R Los Alamos Scientific Laboratory FIN
A-7271 LA-7916-MS 84/03/31 Clinch River Breader Reactor
Program Office 436pp Available at NRC \$8 50 22740 001 24X
Fiche 50-537.84/03/31,8403230216

B403230238 Advises that based on review of 831125 submittal of detailed control room design, specific areas of program plan do not meet requirements of Suppl 1 to NUREG-0737 Meeting requested to resolve deficiencies STOLZ.J F Operating Reactors Branch 4 B4/03/06 QRIFFIN.J M Arkansas Power & Light Co 2pp 22739 278 24X Fiche 50-313.84/03/06.8403230238

B403260006 informs that functional training for personnel necessary to staff requirements per Table B-1 of NUREG-0654 & staff key emergency program positions not included in Table B-1 complete, proficense Condition 24 & SSER 4 SDRENSEN.0 C Washington Public Power Supply System. GD2-84-154 B4703/19 SCHMENCER.A Licensing Branch 2 ip 22747 357 24X Fiche 50-397,84/03/19,8403260006

8403250050 Requests identification of any potential problems or items re completion of NUREG-0737 items by Sept 1984 Response requested within 30 days of itr receipt VARGA.8 A Operating Reactors Branch 1 84/03/02 UDERITZ.R A Public Service Electric & Qas Co of New Jersey 3pp 22763 281 24X Fichs 50-272.84/03/02.8403260050

84032&0051 Application to amend Licenses DPR-51 & NPF-6, changing Tech Specs re RCS vents, post-accident sampling, long-term auxiliary feedwater sys evaluation, noble gas monitor & iodine particulate sampling, per NUREG-0737 items. ORIFFINJH Arkanses Power & Light Co OL-83-37 84/03/16, BTOLZ, J F Operating Reactors Branch 4 MILLER, J R. Operating Reactors Branch 3 9pp 22730 293 24X Fiche 50-313, 84/03/16, 8403260051

--8403260157 Proposed Tech Spec changes to RCS vent post-accident sampling long-term auxiliary feedwater sys evaluation, noble gas monitors, iodine particulate sampling & containment water level monitor Ariansas Power & Light Co 84/03/16 27pp 22750:302, 24X Fiche 50-313,84/03/16,8403260051

B403260056 NUREO/BR-0051 V05 N5 POHER REACTOR EVENTS September-October 1983, MASSARD, S A Director's Office 84/02/29 37pp 22763:190.

8403240069 Forwards evaluation of 830718 request for deletion of steam electric station license condition re low-pressure turbine disc insp NRC maintains position in SRC (NUREQ-0797) that insp must be conducted YOUNOBLOOD B J Licensing Branch I 84/02/28 GARY,R J, Texas Utilities Electric Co. (formerly Texas Utilities Generating Co). 2pp 92763 235 24X Fiche 50-445,84/02/28,8403260069

8403260078 Forwards IE Insp Rept 50-382/84-05 on 840123-27. No violations or deviations identified Status of actions taken re previously identified insp findings examined JOHNSON, E H Region 4, Office of Director 84/02/27. LEDDICK, R 9 Louisiana Power & Light Co 2pp. 22758; 274. 24X Fiche 50-382,84/02/27,8403260078

--8403260087 IE Insp Rept 50-382/84-05 on 840123-27 No violations or deviations identified Major areas inspected radiation protection program & implementing actions for NUREG-0737 action items

CHANEY.H D , MURRAY.B , CROSSMAN.W A Region 4, Office of Director 84/02/27 13pp 22758-276, 24X Fiche 50-382,64/02/27.840226078

8403260113 Forwards FEMA review of Rev 3 to util transition plan for offsite emergency preparedness.per NUREG-0654.

MARTIN.T T Division of Engineering & Technical Programs. 84/03/20 PDLLOCK.M S Long Island Lighting Co 3pp 22758:001 24X Fichs 50-322:84/03/20.8403260113

--8403260117 Review of Rev 3 to util transition plan for offsite emergency preparadoes, per NUREC-0544.

* Federal Emergency Management Agency. 84/02/10 66pp 22758 004 24X Fiche 50-322.84/03/20.8403260113.

B403260143 Forwards general position statement on Reg Guide 1 97.Rev 2 re justification of significant generic deviations; per NUREO-0737. Suppl 1 COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) SEARS, C F Connecticut Yankee Atomic Power Co, COUNSIL.W 0 Northeast Utilities, A02959 B4/02/29 MILLER, J R, Operating Reactors Branch 3 3pp 22758-162 24% Fiche 50-000.84/02/29,8403260143

B403260182 Clarifies NUREO-0737, Item II. K 3 31, in response to Generic Ltr B3-38 Hestinghouse Duners Group authorized program to demonstrate conservatism of WFLASH small break LOCA analyses, per Item II K 3 30 BARNES, P.L. Commonwealth Edison Co. QL-B3-35. 84/03/21. EIBENNUT.D Q Division of Licensing ip. 22756.170, 24X Fiche 50-000,84/03/21.8403260182

8403260200 Comments on Issue 3 of NUREG-0885, "NRC Policy & Planning Guidance, 1984 " Seven themes identified represent important objectives for industry CDUNSIL, H Q North, east Utilities B11048, 84/03/12, DIRCKS, H J. Office of the Executive Director for Operations. 4pp. 22756-204. 24X Fiche 50-000, 84/03/12, 8403260200.

B40326020B Corrects erroneous statement from B30425 response to Generic Ltr B3-02. "NUREG-0737 Tech Specs." re Action Item II E.4 i, "Dedicated Hydrogen Penetration " Purge/repressurization sysused as backup for combustible gas control MCOAUGHY,R W Iowa Electric Light & Power Co. GL-83-02. 84/03/20 DENTON,H Office of Nuclear Reactor Regulation, Director. ip. 22756 166 24X Fiche 50-331,84/03/20,8403260208

8403260212 Forwards revised info re monorail paths.updating util 840206 ltr responding to Ceneric Ltr Bi-07 concerning NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants." Field investigation will be provided I month prior to fuel load, MILLS,L M Tennessee Valley Authority QL-81-07, 84/03/20 ADENSAM,E Licensing Branch 4 2pp 22736-164, 24% Fiche 50-390,84/03/20,8403260212.

- B403260261 Forwards order confirming licensee commitment to implement post-TMI-related itmes in NUREG-0737. Suppl 1 (Generic Lr B2-33) "Requirements for Emergency Response Capability " BTOLZ.J F Operating Reactors Branch 4 QL-82-33 B4/02/21 BECKHAM.J T Georgia Power Co 3pp 22763 179 24X Fichs 50-321.84/02/21 8403260261
- --8403260265 Order confirming licensee commitments on emergency response capability requirements set forth in NUREQ-0737, Suppl 1 (Qeneric Ltr 82-33) EISENHUT, D. O Division of Licensing GL-82-33 84/02/21 Georgia Power Co 6pp 22763 182 24X Fiche 50-321,84/02/21,8403260261
- B4032602B0 NUREG/BR-0025 V10 N2 INFORMATION REPORT ON STATE LEGISLATION LANDAU.H Dffice of State Programs, Director 84/03/10 9pp 22761 307
- 8403260286 NUREO/CR-3153
 CALCULATION OF FLUID CIRCULATION PATTERNS IN THE VICINITY OF SUBMERGED JETS USING ORBMAC
 PARK.J E., CROSS,K E. Oak Ridge National Laboratory Fin B-0168
 DRNL/TM-8653 B3/12/31 Division of Health, Siting & Waste Hanagement 130pp Available at NRC \$6.50 R2761 176
- 8403260289 NUREO-0540 VO5 N12 TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE December 1-31:1983 # Division of Technical Information & Document Control 84/03/31 538pp 22762 001
- 8403260305 Forwards draft NUREG-1042: "Tech Specs, Susquehanna Steam Electric Station " CURTIS,N W Pennsylvania Power & Light Co PLA-2114 84/03/20 DENTON,H R Office of Nuclear Reactor Regulation, Director 480pp 22753 158 24X Fiche 50-388,84/03/20,8403260305
- 8403270003 Responds to open item identified in util integrated assessment (NUREO-0825), SEP Topic III-3. A Analysis performed per ANSI/ANS 50 2 to determine force imparted on electrical penetration Blister 12E from break on Steam Generator 2 KAY, J. A Yanker Atomic Electric Co FYR 84-36 84/03/23 CRUTCHFIELD. D Deparating Reactors Branch 5 3pp 22767 346 24X Fiche 50-029,84/03/23,8403270003
- 8403270007 Responds to open item identified in util integrated assessment (NUREO-0825). Topic III-10 A Util established criterion per Reg Quide i 106 for thermal overload protection for motor operated valves
 KAY, J A Yankee Atomic Electric Co FYR 84-37 84/03/88
 CRUTCHFIELD. D Operating Reactors Branch 5 3pp 22769 350 24X
 Fiche 50-029,84/03/22,8403270007
- 840327000B Informs that util will provide info re planned deviations from Suppl 1 to NUREQ-0737 by 840501 Delay has no effect on schedules for implementation of Suppl 1 to NUREG-0737 COUNSIL.W G Connecticut Yankee Atomic Power Co SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G. Northeast Utilities A02759 84/03/16 EISENHUT, D G Division of Licensing 2pp 22770 011 24X Fiche 30-000,84/03/16.
- 8403270043 Informs that ultrasonic test exams of blend radii area & magnetic particle exam conducted by vessel mfg to determine degree of conformance to NUREG-0619 No recordable indications found utilizing either technique

 JENS.W H Detroit Edison Co EF2-67,715 B4/03/21
 YOUNDS100D.8 J Licensing Branch i 1p 22769 315 24X
 Fiche 50-341,84/03/21,8403270043
- 8403270103 Forwards test exemptions required to perform NUREO-0737, Item I 0 1, "Natural Circulation Testing "Exemptions need to be included in Tech Specs TUCKER, H B, Duke Power Co, 84/03/21 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E 0 Licensing Branch 4, 5pp. 22766 341 24X Fiche 50-413,84/03/21,8403270103
- 8403270106 Forwards BER for SEP outstanding hydrologic issues identified during review of integrated plant safety assessment rept (NUREG-0828) Issues Include local plant flooding from PMP & flood emergency plan CRUTCHFIELD.D Operating Reactors Branch 5 L605-84-03-032 84/03/22 VANDEMALE, D J Consumers Power Co 3pp 22774:032 24X Fiche 50-155,84/03/22,8403270106
- 8403270183 Forwards portion of combustible gas control Tech 8pec surveillance requirement inadventently omitted from util 840118 response to Generic Ltr 83-37, "NUREG-0737 Tech 8pecs " DIXON.O W South Carolina Electric & Gas Co GL-83-37, 84/03/22 DENTON.H R Diffice of Nuclear Reactor Regulation, Director 2pp 22771 123 24% Fiche 50-395,84/03/22,8403270183

- --8403270188 Proposed change to Tech Spec 4 6 5 1 re combustible gas control hydrogen monitors * South Carolina Electric & Gas Co GL-83-37 84/03/22 ip 22771 125 24X Fiche 50-395,84/03/22,8403270183
- 8403270193 Notifies that util will provide addl info to performance testing of relief & safety valves.per Item II D i of NUREG-0737.by 840619.per 840308 agreement d'TODLE.J D Consolidated Edison Co of New York, Inc 84/03/16 VARGA.S A Operating Reactors Branch i ip 2277i i02 24% Fiche 50-247.84/03/16.8403270193
- 8403270209 Forwards Rev 4 to util response to NUREQ-0737. Suppl 1, including control room review implementation priority schedule TUCKER. H B Duke Power Co 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 22772 088 24X Fiche 50-269, 84/03/23, 8403270209
- 8403270215 Provides followup to 840228 telcon re Suppl 1 to NUREG-0737, "Development of Emergency Operating Procedures," from generic Hestinghouse emergency response guidelines Development will continue as described CAREY, J J Duquesne Light Co GL-82-33 84/03/14 VARGA, S A Operating Reactors Branch 1 3pp 22770 270 24X Fiche 20-334.84/03/14.8403270215
- 8403270220 Advises that equipment qualification program & RCIC systeviewed.per NUREG-OB92. BER Outstanding Issue 1 7(9), mode to automatic depressurization sys RCIC valves required for containment isolation remain in qualification program SORENSEN. O C Washington Public Power Supply System GO2-84-160 84/03/72 SCHMENCER. A Licensing Branch 2 1p 22770 269 24X Fithe 50-397.84/03/22.8403270220
- 8403270267 NUREG-1049
 ENVIRONMENTAL IMPACT APPRAISAL FOR RENEWAL OF SPECIAL
 NUCLEAR MATERIAL LICENSE NO SNM-42 Docket No 70-27
 (Babcock & Wilcor Company, Naval Nuclear Fuel Division)

 * Division of Fuel Cycle & Material Safety 84/03/31 B7pp
 Avoilable at NRC \$4 50 22787 235
- 84032/0269 NUREQ-0748 VO4 NO1

 OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As Of
 January 31, 1984 (Drange Book)

 * Office of Resource Management, Director 84/03/31 332pp.
 22788 001
- B403270315 Advises that emergency plan, documented in NUREQ-0744, "Emergency Preparedness Evaluation for TMI-1" & Suppl 1. NUREQ-0737, Item III A 2 1.complete for facility STOLZ.J F Operating Reactors Branch 4 B4/03/09 HUKILL.H D General Public Utilities QPU Service Corp 5pp 22787 241 24X Fiche 50-287, B4/03/09, B403270315
- 8403280048 Forwards response to 831205 request for add1 info re NUREC-0737 Itom II D 1, "Performance Testing of Relief & Safety Valves " Microfiche of RELAPS/ADLPIPE computer analyses encl
 GIESLER.C W Wiscomsin Public Service Corp NRC-84-48 84/03/23 VARSA, SA Operating Reactors Branch 1 36pp 22776 282 24X Fiche 50-305,84/03/23,8403280048
- 8403280066 Forwards safety evaluation re NUREG-0737, TMI Action Item
 11 K 3 44, "Evaluation of Anticipated Transients W/Single
 Failures " Facility in conformance w/NUREG-0737 position &
 evaluation acceptable
 CRUTCHFIELD.D Operating Reactors Branch 5 LSG-84-03-033
 84/03/26 LINDER,F Dairyland Power Cooperative 5pp 22776 349
 24X Fiche 50-409,84/03/26,8403280066
- 8403280076 FOIA request for seven categories of documents HIATT, 8 L Ohio Citizens for Responsible Energy 83/11/30 FELTON, J M Division of Rules and Records ip 22808 243
- 8403280080 Partial response to FDIA request for seven categories of documents Forwards App A documents responsive to Items 1.2. 5.6 & 7 of request NVREG-0386. "NRC Practice & Procedures Manual," presently being updated FELTON, J M Division of Rules and Records 84/01/17 HIATT, 8 Ohio Citizens for Responsible Energy 2pp 22808 244
- 8403280329 Forwards comments on detailed control room design review program plan, per B31031 submittal Plan does not comply fully w/Suppl 1 to NUREO-0737 requirements Recommends meeting in Mar or Apr 1984 VARGA, S A Operating Reactors Branch 1 84/03/09 CLAYTON, F L Alabama Power Co 17pp 22807 288 24X Fiche 50-348, 84/03/09, 840280339

- 8403270002 Final response to FOIA request for four categories of documents, tests, studies & analyses referencing or pertaining to NUREG-0103. "SIS for B&W PWR " App A documents encl FELTON, J M Division of Rules and Records 84/01/13 MADDEN, T J Kays, Scholer, Fierman, Hays & Handler 6pp 22816 127 24X Fiche 50-000.84/01/13.6403270026
- 8403290038 Forwards revised responses to B31123 & B40109 ltrs reapproval of proposed license amend repost-accident sampling for facilities. TMI Item II B 3 HILLS.L M Tennessee Valley Authority 84/03/23 ADENSAM, E Licensing Branch 4 9pp 22806 237 24X Fiche 50-327, 84/03/23, 840329038
- 8403290069 Ack receipt of 840208 ltr informing NRC of steps taken to correct vialations noted in IE Insp Repts 50-269/83-36, 50-270/83-37 & 50-287/83-36 Implementation of corrective actions will be examined during future insp.

 DANCE-H C Division of Project & Resident Programs 84/03/20 TUCKER, H 9 Duke Power Co ip 22807 0I1 24X Fiche 50-269,84/03/20.8403270069
- --8403270108 1E Insp Repts 50-269/83-36.50-270/83-37 & 50-287/83-34 on 831111-1210 Violation noted Failure to follow Maint Procedure 270/83-37-01 re quality performed on Reactor Conlant Pump 202
 BRYANT, J. Region 2. Office of Director 50-287/83-34 84/01/09 10pp 22807 017 24X Fiche 50-269.84/03/20.8403290069
- 8403290078 Ack receipt of 840308 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/84-03 & 50-36484-03 VERRELLI, D M Division of Project & Resident Programs. 84/03/i4 MCDONALD, R P Alabama Power Co ip 22806-311 24X Fiche 50-348.84/03/i4 8603290078
- --8403270103 IE Insp Repts 50-348/84-03 & 50-344/84-03 on 840111-0205 Violation found Pailure to implement procedures for control of maint activities. BRADFORD, M. H. Region 2, Office of Director 50-344/84-03 84/02/15 8pp 22806 317 24X Fiche 50-348,84/03/14,8403270078
- 8403270083 Responds to 840221 request for addl info re control of heavy loads Initial load testing performed for head strongback. Organ separator sling & spent fuel cask yoke ZIMMERNAN.S R Carolina Power & Light Co NLS-84-094 84/03/20 VASSALLO.D B Operating Reactors Branch 2 2pp 22806 325 24X Fiche 50-324.84/03/20,8403270083
- B403290100 Informs that util expects to complete commitment on NUREO-0737. Item 11 B 3 re post-accident sampling sys by June 1985
 BAYNEJ P Power Authority of the State of New York. IPN-84-11
 B4/03/23 VAROA.S A Operating Reactors Branch 1 1p 22806 356 24X Fiche 30-286.84/03/23.8403290100
- 8403290110 Forwards J Preston 830104 memo re generic safety issues priorItization methodology for placement in PDR ROBERTS, B J ACR8 Advisory Committee on Reactor Safeguards 84/03/14 MCKNIGHT, J Distribution Services Branch ip. 22822-214
- --B403290113 Advises of review of generic safety issues prioritization methodology described in NUREO-0793 Inherent limitations of value impact score formula discussed Use of structured & iterative consensus judgement methodology recommended PRESTON, J. ACRS Advisory Committee on Reactor Safeguards B3/01/04 BENDER, M. ACRS Advisory Committee on Reactor Safeguards Safeguards 3pp. 22822 215
- 8403270250 Ack receipt of 840306 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/83-31 & 50-338/83-31 & EWISARC Division of Project & Resident Programs 84/03/16 STEMART.W L. Virginia Electric & Power Co 1p 22802 032 24% Fiche 50-338.84/03/16.8403290250
- ---8403270271 IE lnsp Repts 30-338/83-31 & 50-339/83-31 on 831204-840105 Noncompliance noted failure to meintain procedures re insp of wall & failure to inspect fire barriers LUEHMAN, J G Region 2, Office of Director 50-339/83-31 84/02/06 9pp 22802.040 24X Fithe 50-338.84/03/16,8403270250
- 8403290289 Forwards IE Insp Repts 50-338/84-01 & 50-339/84-01 on 840104-0205 No violations or deviations identified DANCE: H C Division of Project & Resident Programs. 84/03/05 STEHART, H.L Virginia Electric & Power Co 2pp. 22800.048 24 Fiche 50-338,84/03/05,8403290289.

- --B403270274 IE Insp Repts 50-33B/B4-01 & 50-339/B4-01 on B40106-0205 No violations or deviations identified Major areas inspected onsite areas of surveillance & maint activities, previous insp findings & identified items & safety sys walkdowns BRANCH,M W . LUEHMAN, J Ø Region 2. Office of Director ELROD, 8 Division of Project & Resident Programs 50-339/B4-01 B4/03/02 10pp 22800 050 24% Fichs 50-33B, 84/03/05, 8403290289
- B403290296 Comments on proposed rule 10CFR60 & NUREC-1046 re disposal of high level radwastes in unsaturated zone HILLIAMB.R E Hilliams & Associates NRC-02-82-046 49FR5934 003 B4703/15 POHLE: J Division of Waste Management 2pp. 22800 198
- 8403290317 Forwards IE Insp Repts 50-335/84-05 & 50-389/84-07 on 840206-10 No violations or deviations noted DANCE.H C Division of Project & Resident Programs 84/02/29 HILLIAMS.J W Florida Power & Light Co 2pp 22802 052 24) Fichs 50-335,84/02/29,8403290317
- --8403270320 IE Insp Repts 50-335/84-05 & 50-389/84-07 on 840204-10 No violations or deviations noted Major arees inspected heelth physics instrumentation, action on NUREQ-0737 items, ALARA activities & followup on previous items MRAY. J R Region 2, Office of Director, BARR. K P Division of Engineering & Operational Programs 50-389/84-07 84/02/22 8pp 22802 054 24% Fiche 50-335,84/02/29,8403270317
- 840329033I Informs that NUREG-0737. Item II K 2 17. "Voiding in RGB During Transients" complete, based on util endorsement of CEN-197. "Effects of Vessel Head Voiding During "KNIGHTON.G W Licensing Branch 3 84/03/08 BASKIN, K P Bouthern California Edison Co. HOLCOMBE. J C Sen Diego Cas & Electric Co. 9pp 22822 220 24% Fiche 50-361,84/03/08,8403290331
- 8403270341 Responds to FDIA request for records re fecility Ltr dtd 840117 feiled to meet criteria for waiver of reproduction costs Forwards App A documents Address of Phoenix LPDR listed FELTON, J M Division of Rules and Records 84/02/27 RYAN, J, A Streich, Lang, Weeks & Cardon 3pp 22815-018
- --8403290344 NUREQ-75/022
 DRAFT ENVIRONMENTAL STATEMENT RELATED TO CONSTRUCTION OF PALO VERDE NUCLEAR GENERATING STATION, UNITS 1, 2 & 3 Docket Nos 50-528, 50-529 & 50-530
 # Office of Nuclear Reactor Regulation, Director 75/04/30 175pp 22815 301
- 8403300038 Forwards responses to NRC 840214-16 audit findings re util equipment qualification program.per NUREO-0847 (SER) W/84 oversize drawings Aperture cards are available in PDR MILLS,L M Tennessee Valley Authority. 84/03/20 ADENSAM,E Licensing Branch 4 138pp 22824 146 24X Fiche 50-390,84/03/20.840330038
- 8403300149 Forwards application for amend to License NPF-3, revising Tech Spaces to reflect changes in post-accident sampling sys & post-accident instrumentation for in-core thermocouple, per NVR69-0737 & Generic LTF 83-37 GROUSE, R P Toledo Edison Co GL-83-37 84/03/22 8TOLZ, J F Operating Reactors Branch 4 3pp 22821 002, 24X Fiche 50-346,84/03/22,8403300149
- --8403300156 Application for amend to License NPF-3, revising Tach Specs to reflect changes in post-accident sampling sys & post-accident instrumentation for in-core thermocouple & reactor coolant hot leg level changes RP Toledo Edison Co QL-83-37 84/03/22, 7pp 22821-004 24% Fiche. 50-346.84/03/22.8403300149
- B403300192 Forwards draft Rev 5 to Procedure OP-3838 re low voltage on Emergency Bus 1 or 6-3 480-volt bus, draft Rev 5 to OP-3844 re low voltage on Emergency Bus 2 or 4-1 480-volt bus & draft Rev 5 to OP-3845, per SEP Topic VIII-I.a. KAY, J A Yankee Atomic Electric Co FYR 84-39. 84/03/28. CRUICHFIELD, D Operating Reactors Brench 5 12pp 22819-251 24X Fiche 50-029,84/03/28,8403300192
- 8403300231 Advises that goal for completion of technical reviews & implementation of all NUREQ-0737 items.sxcluding Suppl i, is Bept 1984 Requests to be advised of potential problems within 30 days.

 VARGA:S A Operating Reactors Branch 1 84/03/13 0/TOOLE, J.D. Consolidated Edison Co of New York, Inc 2pp 22844, 338, 24X Fiche 50-247, 84/03/13, 8403300231
- 8403300232 Forwards staff comments on detailed control room design review program plan.per NUREO-0737.Suppl 1 Some areas of plan require further description VASSALLO.D B Operating Reactors Branch 2 84/03/06 HARRIMOTON,W D Boston Edison Co. 18pp 22844 264, 24X riche 50-293,84/03/06.8403300229

- 8403300233 Forwards comments on detailed control room design review Plan demonstrates commitment to meet requirements of Suppl 1 to NURED-0737, however, add 1 info required Meeting should be beld in Apr or May 1984 to discuss comments VARGA-8 A Operating Reactors Branch 1 84/03/13 DDLAN, J Indiana & Michigan Electric Co 12pp 22842 350 24X Fiche: 50-315,84/03/13,8403300233
- 8403300240 Summary of ACRS Subcommittee on Human Factors 831207 meeting in Washington.DC re status of ongoing activities in NRC human factors program plan,human reliability data base & uses & review of program budget for FV85-86 # ACRS Advisory Committee on Reactor Safeguards 83/12/07 ACRS Advisory Committee on Reactor Safeguards 24pp 22842 320
- BACCCCCCC NURSEC/CR-2896 VO.1
 CONMIX-IA A THREE-DIMENSIONAL TRANSIENT BINGLE-PHASE
 COMPUTER PROGRAM FOR THERMAL HYDRAULIC ANALYBES OF BINGLE
 AND MULTICOMPONET SYSTEMS Volume I User's Manual
 DOMANUS,H M . SCHMITT.R C . SHA.W T Argonne National Laboratory
 FIN A-2045 ANL-82-25 VO.1 B4/03/31 Division of Accident
 Evaluation 327pp 22839, 217
- B403300285 NUREG/CR-2896 VO2
 CDMMIX-1A A THREE-DIMENSIONAL TRANSIENT SINGLE-PHASE
 COMPUTER PROGRAM FOR THERMAL HYDRAULIC ANALYSIS OF SINGLE
 AND MULTICOMPONENT SYSTEMS Volume 11 Assessment and
 Verification
 DDMANUS H M , SCHMITT,R C , SHA,W T Argonne National Laboratory
 FIN A-2045 ANL-82-25 VO2 B4/02/29 Division of Accident
 Evaluation 95pp 22840 182.
- 8403300294 NUREQ/CR-3427 VO3
 LONG-TERM PERFORMANCE OF MATERIALS USED FOR HIGH-LEVEL WASTE
 PACKAGING Third Quarterly Report October December 1983
 STAML.D. MILLER.N E Battelle Hemoriai Institute, Columbus
 Laboratories FIN 8-6764, 84/03/31 Division of Health, Siting &
 Waste Management 90pp Available at NRC \$4.75 22826 203
- B403300296 Advises that goal for completion of technical reviews & implementation of all NUREO-0737 items.excluding Suppl 1.is Sept 1984 Requests to be advised of potential problems within 30 days
 VAROA.B A Operating Reactors Branch 1 'B4/03/13 DDLAN.J Indiana & Michigan Electric Co. DDLAN.J American Electric Power Service Corp 2pp 22844.316 24X Fiche 30-315.84/03/13.
- 8403300300 NUREQ-0675 822
 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POMER PLANT, Units 1 AND 2 Docket Nos 50-275
 And 50-323 (Pacific Oas and Electric Company)

 Division of Licensing 84/03/31 400pp Available at NRC \$11 00, 22843 001, 24X Fichs 50-275, 84/03/31.8403300300
- 8403300303 Notification of 840327 meeting w/util in Bathesda.MD to discuss detailed control room design review items relative to requirements of NUREO-0737. Suppl 1
 SILVER.H. Operating Reactors Assessment Branch 84/03/20
 STOLZ, J.F. Operating Reactors Branch 4 2pp 22844 307 24X
 Fiche: 50-289.84/03/20,8403300303
- 8403300306 NUREO/CR-3523
 A RANKINO SCHEME FOR MAKINO DECIBIONS ON THE RELATIVE TRAINING IMPORTANCE OF POTENTIAL NUCLEAR POHER PLANT MALFUNCTIONS
 BELBY, D L , HENBLEY, W T. Oak Ridge National Laboratory FIN 8-0466
 ORNL/TM-8750 84/02/27 Division of Facility Operations 12ipp 22842:190
- 8403300308 Board Notification 84-054 forwards NRC evaluation & conclusion re util variance from NUREO-0737 guidance concerning high range stack gas monitor (TMI Item II.F.1.1)
 MIRAGLIA:F.J. Assistant Director for Safety Assessment. 84/03/14
 BLOCH,P.B., PARIS,D H., SHON,F.J. Atomic Safety and Licensing Board Panel. 7pp 20844.282. 24X Fiche. 50-155, 84/03/14, 8403300308
- 6403300317 NUREG/CR-3334 VO3
 HEAVY-BECTION BTEEL TECHNOLOGY PROGRAM QUARTERLY PROGRESS
 REPORT FOR JULY-BEPTEMBER 1983.
 RUGH, C. E. Oak Ridge National Laboratory FIN 8-0119.
 GRNL/TH-8787/V3. 84/03/31 Division of Engineering Technology
 120pp. 22826-067
- 8403300318 NUREO/CR-3547

 EVALUATION OF CONTAINMENT LEAK RATE TESTING CRITERIA

 DOUGAN.J.R. Dak Ridge National Laboratory. FIN 8-0489

 ORNL/TM-8909. 84/03/31. Division of Enginbering Technology

 56pp. 22826,303

- 8403300325 NUREC/CR-3275
 JOB ANALYSIS OF THE ELECTRICIAN POSITION FOR THE NUCLEAR
 POWER PLANT MAINTENANCE PERSONNEL RELIABILITY MODEL
 FEDERMAN,P J. DARTTER,W D. SIEOEL,A I Applied Science Associates,
 Inc FIN B-0461 ORNL/TM-8755 84/02/29 Division of Facility
 Operations 191pp 22842 007
- 8403300342 NUREO/CR-3309
 A SIMULATOR-BASED BYUDY OF HUMAN ERRORS IN NUCLEAR POWER
 PLANT CONTROL ROOM TASKS
 BEARE,A N. DORRIS, R E., DOVELL,C R General Physics Corp FIN
 A-1188 SAND83-7095 84/01/31 Division of Facility Operations
 190pp. 22844 070
- ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS
- 8401170072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDÁN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22707 237 24X Fiche 50-000,84/02/28,8401170072
- 8402070007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of GA. Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York. Inc 130pp. 22552 329 24X Fiche 50-000.84/03/02.8402090007
- B40207000B IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553-098 24X Fiche 50-000.84/03/02, 8402070008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases"

 Byc list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/03/02 Consolidated Edison Co of New

 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090007
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Companents Below Nil Ductility Temp " Svc list enci JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05, 8402070011
- B402070024 IE Info Notice 84-09.Rev 1. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 30-000.84/03/07.B402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Byc list and. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22784 184 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Tupe HFA Relays in Use in Class IE Safety Sys " Syc list enc!
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823:094 24X Fiche 50-000,84/03/12,8402090031.
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Past 830103). 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823.229 24X Fiche 50-000.84/03/21,8402070043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl. JORDANAEL Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- 8403020378 Forwards request for OMB review & supporting statement re 10CFR110 concerning export & import of nuclear equipment & matls NORRY.P 0 Office of Administration 84/02/28, MACRAE, J B Office of Management & Budget 1p 22492 181
- 8403020380 Responds to approval request for info collection re physical invantory listing Request approved through 850331 under OMB 3150-0058.per Paperwork Reduction Act MACRAE.J B Office of Management & Budget OMB 3150-0058 84/02/27 SCOTT.S Document Management Branch 2pp 22492:092

- B4030203B1 Responds to approval request for info collection re 10CFR55 concerning operator licenses Request approved through 870229 under OMB 3130-001B. per Paperwork Reduction Act MACRAEL B Office of Management & Budget OMB 3130-001B. 84/02/19 SCOTT.S Document Management Branch 2pp 22492 094
- 8403020383 Responds to approval request for info collection re registration certificate for in vitro testing w/byproduct matl under general license Request approved through 870131 under DME 3150-0038, per Paperwork Reduction Act MACRAE, J B Uffice of Management & Budget. OMB 3150-0038 84/02/27 SCOYT, S Document Management Branch. 2pp. 22492 22492 096
- B4030203B5 Responds to approval request for info collection re 10CFR75 concerning security facility approval & safeguarding of nati security info & restricted data Request approved through B60229 under DMB 3150-0047, per Paperwork Reduction Act. MACRAE, J B Office of Management & Budget DMB 3150-0047 B4002/17 SCDTT, 8 Document Management Branch 25p. 22492 098
- 84030203B7 Responds to approved request for info collection re 100FR75 concerning safeguards on nucleer math-implementation of US/ 1AEA agreement Request approved through B70I31 under OMB 3150-0055, per Paperwork Reduction Act MACRAE, J B Office of Management & Budget OMB 3150-0055 84/02/27 SCOTT.S Document Management Branch 2pp 22492, 100
- B403020388 Responds to approval request for info collection of data effort on spouse contamination. Request approved through B70229 under DMB 3150-0026, per Paperwork Reduction Act MACRAE, J B Office of Management & Budget DMB 3150-0026 B4/02/27 SCOTT. S Document Management Branch 2pp 22492 102 22492 102
- 8403030004 Forwards FEMA 840206 ltr & final exercise evaluations on 830914 offsite emergency preparedness exercise.

 Recommendations from rest do not affect approval of plan PAPERIELLO. J. Region 3. Offsice of Director 84/02/29 REED.C Commonwealth Edison Co. 2pp 22490:240 24X Fiche 50-237,84/02/29. 8403050004
- 8403050125 Ack receipt of FEMA 840130 ltr & associated finel exercise evaluations of 831101 emergency preparedness exercise No deficiencies affecting public health & safety identified hased on performance of offsite agencies PAPERIELLO.C J Region 3. Office of Director 84/02/29. 01ESLER.C W Wisconsin Public Service Corp 2pp 22487.109 24X Fiche 50-305.84/02/29,8403050125
- B403050128 Forwards "Perry Nuclear Power Station Offsite Radiological Emergency Planning," interim rept Exercise to test plans scheduled for 841128 KRIMM: R Federal Emergency Management Agency 84/03/01. JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) ip 22488 223 24% Fiche 50-440.84/03/01, 8403050128
- --B403050131 "Perry Nuclear Power Station Radiological Emergency Planning," interim rept * Federal Emergency Management Agency 84/01/10. 192pp. 245B 224 24% Fiche 50-440.84/03/01/8403050128
- 8403080148 Forwards "Evaplation of Southern California Edison Site-Specific Offsite Radiological Emergency Preparedness Prompt Alert & Notification Sys Evaluation." Sys adequate to alert & notify public in event of accident SPECK.S W Federal Emergency Management Agency. 84/01/31 DIRCKS,W J Diffice of the Executive Director for Operations 22487 314 24X Fiche 50-206,84/01/31,8403050148
- ---8403050172 "Evaluation of Southern California Edison Site-Specific Offsite Radiological Emergency Preparadness Prompt Alert & Notification Bys " " Federal Emergency Menagement Agency 84/01/05, 61pp 22467 315 24X Fiche 50-206,84/01/31,8403030148
- 8403050162 Forwards FEMA 840201 ltr, final exercise evaluations on SUBJULION FORWARDS FERM B40201 ltr, Final exercise evaluations on B31115 offsite emergency preparedness exercise & interim finding recommendations re offsite emergency response plen for area around facility No deficiencies identified. PAFERIELLO, C. J. Region 3, Office of Director B4/02/29 REED, C. Commonwealth Edison Co. 2pp. 22485.061, 24X Fiche 50~454,84/02/29,8403050162 8403050162
- 840306086 Approves state & local plans & preparedness for sterting & protecting gublic in event of radiological emergency.
 Approval conditional on verification of alert & notification susper criteria of App 3 of NURGO-0654/FEMA-REP-1, Rev 1
 SPECK, 8 W Federal Emergency Management Agency. 84/02/15
 DIRCKB, W J Diffice of the Executive Director for Operations Ip.
 22516 300 24X Fische 50-250, 84/02/15, 8403060086.

- 8403060458 Responds to approval request for info collection re Seles ATMS events Request approved through 850930 under OMB 3150-0119, per Paperwork Reduction, Act MACRAEJ B Office of Menagement & Budget OMB 3150-0119. SCOTT.S Document Management Branch. 2pp 22549 319.
- 8403060460 Responds to approval request for info collection re iOCFR70 concerning domestic licensing of BNM Request approved through 870229 under OMB 3150-0009, per Paperwork Reduction MACRAE, J B Office of Management & Budget OMB 3150~0009. 84/02/27 BCOTT, 8 Document Management Branch 2pp 22: 84/02/27 22549 336
- 8403040463 Responds to approval request for info collection rs 100FR31 concerning domestic licensees for byproduct metl Request approved through 870229 under OMB 3150-0016, per Paperwork Reduction Act MACRAE, J B Office of Management & Budget OMB 3150-0016 84/02/17. SCOTT, 8 Document Management Brench 2pp, 22549:338
- 8403070363 Forwards FEMA comments on Draft 2 of public info brochure, for review & consideration YOUNDELOOD B J Licensing Branch i 84/02/29 EDELMAN, M R. Clevelend Electric Illuminating Co 3pp 22567'205, 24X Fiche. 50-440
- 8403080238 Forwards "Monticello Nuclear Power Plent Bite-Specific Offsite Radiological Emergency Preperedness Evaluation" & "Monticello Nuclear Power Plant Full-Scale Joint Emergency Exercise on 830223," final rept KRIMM.R.W Federal Emergency Management Agency 84/03/05. Federal Emergency Management Agency 3pp 22560,127 24X Fiche. 50-263,84/03/05,8403080238
- --8403080242 "Monticello Nuclear Power Plant Bite-Specific Dffsite Rediclogical Emergency Preparedness State of MN & Sherburns & Hright Counties, "regional directors evaluation * Federal Emergency Management Agency 84/01/26 32pp. 22560 130 24x Fiche 50-263,84/03/05,8403080238
- ---8403080244 "Monticello Nuclear Power Plant Full-Scale Joint Emergency Exercise on 830223," final rept * Federal Emergency Management Agency 84/03/05 ilOpp. 25560 255 24% Fiche 50-263,84/03/05.8403080238
- 8403090218 Forwards evaluation rapt of offsite radiological emergency preparationss exercise conducted on 8307R6 Deficiencies observed did not detrect from overall demonstrated capability to protect public KRIMM, R W Federal Emergency Management Agency 84/03/06 JORDAN, E i Division of Emergency Preparadness & Engineering Response (Post 830103). 7pp 22571:142 24X Fiche: 50-155.84/03/06. 840309021B
- --B403090221 Evaluation of Btate of MI, Charlevoix & Emmet Counties offsite radiological emergency preparedness exercise for Big Rock Point Nuclear Power Station # Federal Emergency Management Agency 83/07/26 43pp 22571 149 24X Fiche 50-155,84/03/06.8403090218
- 8403090219 Forwards applicant responses to Commission 811224 order on OGGOVERT FORMERS Applicant responses to Comments and Behalf of Project Mgt Corp & TVA
 CHIPMAN, G L Energy, Dept of BR/01/18, PALLADING, N. J.,
 GILINGKY, V , ROBERTS, T F Commissioners, 101pp 22374:168 24X Fiche 50-537, 82/01/18, 8403090219.
- 8403130155 Advises that state & locel plens & preparedness for radiological emergencies adequate Approval conditional on FEMA verification of adequacy of alerting & notification sys.per App 3 of Rev i to NUREO-0554/FEMA-REP-1.

 SPECK, S. W. Federal Emergency Management Agency, 84/03/02 pIRCKS, W J Office of the Executive Director for Operations, 26p, 22608 229 24X Fiche 50-254,84/03/02,8403130155
- 8403130163 Forwards final rept re small-scale offsite radiological emergency preparedness exercise on 821014 No deficiencies nated KRIMM,R W. Federal Emergency Hanegement Agency. 84/03/05. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) App. 22599.307. 24X Fiche 50-282,84/03/05. 8403130163
- ---8403130172 Finel rept of smell-scale joint emergency exercise on 82/12/17, 82pp Federal Emergency Management Agency, 82/12/1: 99,313 24X Fiche,50-282,84/03/05,8403130163.
- 8403130171 Forwards FEMA post-exercise assessment for 831026 joint exercise of State of DE & local radiological emergency preparedness plans for facility.

 HARTIN, T.T. Division of Engineering & Technical Programs. 84/6

 UDERITY.R A Public Service Electric & Oas Co. of New Jersey.

 22599, 223 24X Fiche: 50-272, 84/03/07, 8403130171.

ι 1

- --8403130178 Evaluation of 831026 joint exercise of State of DE & local radiological emergency preparedness plans for facility * Federal Emergency Management Agency 83/11/25 72pp 22599 226 24% Fiche 50-272.84/03/07.8403130171
- 6403130185 Discusses evaluation of State of IL & local plans & preparedness for facilities Plans adequate to protect health & safety of public Approval of public alert notification sys conditional on verification of criteria of NUREO-0554 SPECKs & W Federal Emergency Management Agency 84/03/02 DIRCKS M.J Uffice of the Executive Director for Operations ip 22619:316. 24X Fiche:50-275.84/03/02.8403130185
- B40313019B Forwards evaluation of State of MN & Shelburne & Wright Counties emergency preparedness plan for 830223 full-scale exercise Identified deficiencies corrected KRIMM R W Federal Emergency Management Agency 84/03/05 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103). 7pp 22413 234 24X Fiche 50-243,84/03/05,8403130198
- --B403130209 Evaluation of State of MN & Shelburne & Wright Counties emergency preparedness plan for B30223 full-scale exercise # Federal Emergency Management Agency 84/03/05 63pp 22613 263 24% Fiche 50-263.84/03/05.8403130198
- 8403130419 Forwards Rev 1 of Ouidance Memo 17 Rev addresses concerns of NRC & FEMA regional staff re conducting preexercise & post-exercise activities

 KRIMM, R. W. Federal Emergancy Management Agency 84/03/05

 JORDAN, E. L. Division of Emergancy Preparedness & Engineering Response (Post 830103) 10pp 22608 273
- B40315001B Informs that FEMA will transmit, on or before 840402, proposal refurther review of issues concerning evacuation time satimates for population, including work program estimate of resources & schedule for completion of major components.

 KRIMM.R.W Federal Emergency Management Agency 84/03/09

 JORDAN.E L Division of Emergency Preparadness & Engineering Response (Fost 830103) ip 22440 330. 24X Fiche 50-273,84/03/09,8403150018
- 8403150052 Forwards State of LA B31227 request for exemption from full perticipation at 840410 annual radiological emergency preparedness exercise FEMA supports exemption based on State of LA full participation in Waterford exercise KRIMM-R W Federal Emergency Management Agency, 84/03/09. JURDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 3pp 22641 355 24X Fiche 50-416,84/03/09,8403150052
- 8403i50l06 Forwards FEMA final exercise rept for 820319 joint exercise of state & local radiological emergency preparedness plans for facility Rept of 831005 exercise will be forwarded MARTIN.T.T Division of Engineering & Technical Programs 84/03/09 COUMBIL.W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22640:142 24X Fiche 50-336.84/03/09.8403150106
- 8403130113 Forwards exercise repts of 820319 & 830316 joint exercises of offsite radiological emergency preparedness plans for Arkansas Nuclear One Power Station Deficiencies observed at both exercises, Approval under FEMA Rule 440FR350 in effect.
 KRIMM.R.W. Federal Emergency Management Agency 84/03/09
 JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp. 22640.001 24X Fiche 50-313,84/03/09,8403150113
- --8403150119 Exercise repts of 820519 & 830316 joint exercises of offsite radiological emergency preparedness plan for Arkansas Nuclear One Power Station
 KRIMM; R W Federal Emergency Management Agency. 84/03/09 45pp 22640
- 8403130200 Forwards draft final exercise rapt for 840125 juint radiological emergency preparedness exercise, State of MI & Berrien County demonstrated capability to protect public in event of radiological emergency (KRIMM.R.W) Federal Emergency Management Agency 84/03/07 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 2pp 22642.001 24X Fiche 50-315,84/03/07,8403150200
- --8403150203 Draft evaluation of util, State of M1 & Berrien County 840125 Joint exercise # Federal Emergency Management Agency, 84/02/22 42pp 22642:003, 24X Fiche, 50-315, 84/03/09, 8403150200
- 8403190131 Discusses findings & determinations on LTLCO transition plan. Key to Regional Assistance Committee (RAC) 840210 raylew & consolidated RAC review encl SPECK. S. R. Federal Emergency Management Agency OL-3, 84/03/15 DIRCKB, W. J. Office of the Executive Director for Operations 70pp 22668: 258, 24% Fiche 50-322,84/03/15,8403190131

- 8403190363 Forwards evaluation of LILCO transition plan per NUREG-D654/ FEMA-RCP-1.Rev | Deficiencies noted BPECK-S W Federal Emergency Management Agency DIRCKS W J Office of the Executive Director for Operations 71pp 22673
- 8403200029 Forwards FEMA evaluation of Town of Lusby. Calvert County. MD post-exercise radiological emergency preparedness plans for facilities Schedule for corrective actions re offsite emergency preparedness deficiencies requested MARTIN, T T Division of Engineering & Technical Programs 84/03/15 LUNDVALLA E Baltimore Gas & Electric Co 3pp 22699-234 24X Fiche 50-317.84/03/15.8403200029
- --B403200035 Evaluation of Town of Lusby, Calvert County, MD post-exercise radiological emergency preparedness plans for facilities # Federal Emergency Management Agency B3/10/13 56pp 22697 237 24% Fiche 50-317,84/03/15
- 840320007B Forwards final exercise rept prepared by FEMA for 830629 joint exercise of state & local radiological emergency preparedness plans MARTIN.TT Division of Engineering & Technical Programs 84/03/15 HARRINGTON, W D Boston Edison Co 3pp 22699 099 24X Fiche 50-293,84/03/15,8403200098
- B403200166 Forwards FEMA B20609 final post-exercise assessment for B20218 joint radiological emergency preparedness exercise Rept for 830921 exercise will be issued shortly MARTIN,T T. Division of Engineering & Technical Programs. 84/03/15 MURPHY.W P Vermont Yankee Nuclear Power Corp 3pp 22698 041 24X Fiche 50-271,84/03/15,8403200166
- B403230077 Responds to approval request for info collection re 10CFR70 concerning domestic licensing of SNN Request approved through B70331 under OMB 3150-C009, per Paperwork Reduction Act MACRAE, J B Office of Management & Budget OMB 3150-0009 B4/03/14 SCOTT, B Document Management Branch 2pp 22759.046
- 8403230080 Responds to approval request for info collection re 10CFR32 concerning specific domestic licenses to mfg or transfer certain items containing byproduct matl Request approved through 870331 under OMB 3150-0001 MACRAE. J B Office of Management & Budget OMB 3150-0001 84/03/15 SCOTT.8 Document Management Branch 2pp 22759 044
- 8403230120 Notifies that State of PA eligible for biennial frequency for participation in radiological emergency preparedness exercise Change from annual exercise requirement would be supported if requested by util KRIMM, R W Federal Emergency Management Agency 84/03/15 JDRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) ip. 22730-336 24X Fiche 50-387.84/03/15.8403230120
- 8403260037 Responds to approval request for info collection re 10CFR110 concerning export & import of nuclear equipment & mat1 Request approved through 861231 under OMB 3150-0036, per Paperwork Reduction Act MACRAE, J B 0
- 8403260113 Forwards FEMA review of Rev 3 to util transition plan for offsite emergency preparedness, per NUREG-0654
 MARTIN. T T Division of Engineering & Technical Programs 84/03/20
 POLLOCKLM S Long Island Lighting Co 3pp. 22758 001 24X
 Fiche 50-322,84/03/20,8403260113
- --B403260117 Review of Rev 3 to util transition plan for offsite emprgency preparedness, per NLREG-0654 * Federal Emergency Management Agency 84/02/10 66pp 22758 004 24% Fiche-50-322,84/03/20,8403260113
- 8403270104 Requests extension until Oct 1984 for annual emergency preparedness exercise Extension would allow inclusion of offsite plans & use of proposed alternate emergency facility location DALTROFF, 8 L Philadelphia Electric Co 84/03/20 EISENHUT, D G Division of Licensing 6pp 22769:217 24X Fiche 50-277,84/03/20,8403270104
- 8403290117 Forwards FEMA final rept for 831015-16 emergency exercise VERRELLI.D M Division of Project & Resident Programs 84/03/20 PARRIS.H 0 Tennessee Velley Authority 1p. 22607 027 24X Fiche 50-239,84/03/20,8403290117
- 8403290184 Forwards FEMA final rept for 830618 emergency exercise DANCE.H C Division of Project & Resident Programs 84/03/19 STEWART.W L Virginia Electric & Power Co ip 22802 174 24X Fiche. 50-338.84/03/19.8403270184

8403300265 Forwards request for CMB review & supporting statement re NRC Form 313. "Application for Matl License." concerning 10CFR30.33-35 & 40 NGRRY.P & Befice of Administration 84/03/28 MACRAE.J B Office of Management & Budget 1p 22844 336

R PROPOSED RULE

- B402090105 Comments on proposed rule 10CFR20 re accreditation of personnel dosimetry processors Requirement should provide degree of consistency & accuracy in personnel exposure dusinetry Supports rule MOBLEY, M H Tennessee, State of 49FR1205 025 84/02/16 CHILK: 9 J Office of the Secretary of the Commission 1p 22576 178
- 8403090106 Package of four comments supporting proposed rule 10CFR20 re improved personnel dosimetry processing MARD.J O California. State of JERRETT.L E Florida. State of VILLFORTH.J C Maryland. State of 49FR1205 E4/03/05 CHILK.S J Office of the Secretary of the Commission 5pp 22576 069
- 8403090159 Comments on proposed rule 10CFR20 re accredited dosimeter processors Supports rule PARIS.R D Oregon, State of 49FR1205 028 84/02/24 Docketing & Services Branch 1p 22575 072
- 8403070174 Comments on proposed rules iOCFR2 & 72 re hybrid hearing procedures for expansion of onsite spent fuel storage capacity at civilian nuclear power reactors Recommends NRC establish attingent threshold for new contentions ZIMMERMAN.8 R Carolina Power & Light Co 48FR54479 017 64/03/05 CHILM.5 J Office of the Secretary of the Commission 2pp 22573.310
- 8403090178 Forwards comments on proposed rule 10CFR20 re improving personnel dosimetry processing Personnel & area monitoring of exposures to inniting radiation principal foundation for control of radiation RUMERFIELD.P. Applied Hadiation Protection Services. 49FR1205 035 84/03/02 PALLADINO, N Commissioners ip 22573 312
- --B4030901B3 Comments on proposed rule 10CFR20 re improvement of personnel dosimetry processing Vendor among best providers of accurate readouts for persons exposed to low energy photons in diagnostic radiology.

 RUMMERFIELD,P Applied Radiation Protection Services 49FR1205 84/03/02 Docketing & Services Branch 6pp 22573 313
- 8403070199 Advises recipients of comments on proposed rule iOCFR2 that Comment 12 miscaded Number i2 will not be used again * Bocketing & Bervices Branch 48FR50550 84/02/23 Docketing & Services Branch. ip 28573 115
- 8403090201 Comments on proposed rules iOCFR2 & 72 re hybrid hearing procedures for expansions of onsite spent fuel storage capacity at civilian nuclear power reactors Suggests procedures as alternative to Commission options RAMESEP Westinghouse Electric Corp 4BFR54499 016 84/02/21 Docketing & Bervices Branch 4pp 22575 073
- 8403070208 Comments on proposed rule 10CFR20 re improving personnel dosimetry processing Extending accreditation to Feb 1986 Questioned JACOBEON. N League Against Nuclear Dangers 49FR1205 026 84/02/25 Docketing & Services Branch 2pp 22574 356
- B403090212 Comments on proposed rule 10CFR20 re improved dosimetry processing Opposes rule.Rule sllows no differentiation between performance testing requirements for large commercial processor & in-house programs MASSE, F X Massachusetts Institute of Technology, Cambridge, MA 49FR1205 027. 84/02/27 Docketing & Services Branch 2pp 20874 020
- B403090214 Package of two comments supporting proposed rule 10CFR20 re improving personnel dosimetry processing TAPERT, A C Delaware, State of EISENHOHER, E H Commerce, Dapt of, National Bureau of Standards 49FR1205 84/03/06 Docketing & Services Branch 4pp 22575 085
- 8403130203 Comments on proposed rule 100FR20 re improved personnel dosimetry processing Opposes rule SGRENSEN. 0 C Washington Public Power Supply System 49FR1205 040 84/03/07 Doctating & Services Branch 2pp. 22617 317
- B403130218 Comments on proposed rule 10CFR20 re improved dosimstry processing Opposes rule EVDONNINDER,V N Baston Univ Medical Center, Boston, MA 49FR1205 037 84/03/05 Doctsting & Services Branch ip 22617; 291

- 8403130236 Package of four comments supporting proposed rule 10CFR20 re improved personnel dosimetry processing REBH.D L. Maryland, State of BRADLEY, F.J. New York, State of BRICH.R South Dakota, State of 49FR1205 84/03/09 Docketing Services Branch 5pp 22617 260
- B403130282 Comments on proposed rules 10CFR2 & 72 re hybrid bearing procedures for expansions of onsite spent fuel storage capacity at civilian nuclear power reactors Supports Option 2.66/mod SHERHUDD, Q.Q. Gameral Electric Co 49FR54499 017, 84/03/02 Docketing & Services Branch 3pp 22614 188
- 8403130327 Package of three comments supporting proposed rule 10CFR20 re improved personnel dosimetry processing SKIERKONSKI.P Oblahoms, Univ. of. Norman, OK THOMADBEN, B R. Wisconsin Clinic Cancer Center, Madison, HI QULLNICK, D. A. Pacific Radiation Corp 49FR1205 84/03/08 Docketing & Services Branch Bpp 22617 122
- B40313036B Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Supports rule KEARNEY.J J Edison Electric Institute, 49FR1205 043 B4/03/06 CHILK,B J Office of the Secretary of the Commission 3pp. 22616-244
- 8403130378 Comments on proposed rule iOCFR20 re licensee requirement to utilize only personnel monitoring ave certified by naticalibr see Rule unnecessarily complicated & overly restrictive TANNER, R L. Nurnberger Radiation Protection Service 49FR1205 044 84/02/06 Docketing & Services Branch 2pp 22616 274.
- 8403140137 Comments on proposed rule iOCFR20 re improved personnel dosimetry processing Addl dosimetry processor accreditation guidence required before implementation of rule MITHERS, D D Portland General Electric Co 49FR1205 056 84/03/09, Docketing & Services Branch 2pp 22624 iii
- 8403140144 Comments on proposed rule 100FR20 re improved personnel dosimetry processing Requests, under FOIA, contract batween NBB & Univ of Michigan re 810717 interagency agreement to administer dosimeter program SCHUTZ, D F Teledyne Isotopes, 49FR1205 053 64/03/09 Docketing & Services Branch 3pp 22623 360
- 8403140147 Comments on proposed rule iOCFR20 re improved personnel dosimetry processing Supports Alternatives 2 or 3. Option A as acceptable approach for obtaining competent results from dose measurements CLEMENTS. B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 47FR1205 055 84/03/07 Docksting & Services Branch ip 22620 332
- 8403140149 Comments on proposed rule 10GFR20 re improved personnel dosinetry processing Prefers Alternative 2 re use of dosinetry provider in GA program Alternative 3 B also acceptable although somewhat restrictive 3 B also HILBONDE F Arkansas, State of. 49FR1205 050. 84/03/09. Docketing & Services Branch 1p 22620, 263
- 8403140151 Package of four comments supporting proposed rule (OCFR20 re improved personnel dosimetry processing FARRAR, D. L. Commonwealth Edison Co. WISENBURG, M. R. Houston Lighting & Power Co. PLATO, P. Michigan, Univ. of, Ann. Arbor, MI. 49FR1205 84/03/12 Docksting & Services Branch 9pp. 22624 026
- 8403140153 Package of two comments supporting Alternative 3, Option E in Natl Voluntary Lab Accreditation Program on proposed rule 100FR20 re improved personnel dosimetry processing.

 BAYNE, J P Power Authority of the State of New York. SCHUYLER, J O Pacific Oas & Electric Co. 49FR1205 84/03/12 CHILK, S. J. Office of the Secretary of the Commission 4pp 22620; 334.
- 8403140156 Forwards Frontier Airlines comments on proposed rule 10CFR20 re personnel dosimetry processing. Frontier Airlines does not favor change in current requirements.

 BALLENDER, V.W. Air Transport Association 49FR1205 0&2, 84/03/08 Docketing & Services Branch 2pp. 22&20: 233.
- 8403140160 Comments on proposed rule 10CFR60 re high level radwastes in unsaturated rone Application of same std of measure to all rock types & all sites essential DOVER.B Affiliation Not Assigned 48FR5934 001 84/03/06, Office of the Secretary of the Commission. 1p 22620.362.
- 6403140166 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Dosimetry accreditation will impact on dosimetry research & upgrade. ENML "Ouidelines for Calibr of Personnel Dosimeters" ancl for review. DEAL, L. J. Energy, Dept. of 49FR1203 047. 84/03/09 Docketing & Services Branch. 5pp 22624, 113.

ľ

- --8403140170 PNL-4515
 "Quidelinss for Calibr of Personnel Dosimeters "
 ROBERSON,P L , HOLBROOK,K L Battelle Memorial Institute, Pacific
 Northwest Laboratories UC-41 84/01/31 45pp 22624 118
- B403140172 Package of four comments on proposed rule iOCFR20 re improved desimetry processing Opposes rule in present form BAKANAUSKAS.J Massachusetts. Univ of hadical School DRISCOLL,F Tufts Univ, School of Medicine, Medford, MA JOHNSON,R U Harvard Univ., Cambridge, MA 49FR1205 B4/03/12. Docketing & Services Branth. Bpp 22620 244
- 8409190280 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Subj should be addressed by reg guide CDUN91L.W G Connecticut Yankee Atomic Pour Co CDUN91L.W G Northeast Nuclear Energy Co (subs of Northeast Utilities). CDUN91L.W O Northeast Utilities Service Co (subs of Northeast Utilities) Services Branch. 2pp 22672 279
- 8403190289 Package of three comments supporting proposed rule 10CFR20 rs improved personnel dosimetry processing TUCKER: H B Dukw Power Co WISENBURG, H R Houston Lighting & Power Co SUDBLOM, O L Environmental Protection Agency 49FR1205 84/03/14 Docketing & Services Branch 11pp 22673 244
- 8403190295 Package of two comments opposing proposed rule 10CFR20 re improved perspanel dosimetry processing MCGAUGHYJR.W. IDWA Electric Light & Power Co PRICE, X.W. Yale Univ., New Haven, CT 49FR1205. 84/03/14 CHILK, S J Docketing & Bervices Branch opp 22675 312.
- B403190317 Package of four comments supporting Alternative 3, Option B of proposed rule 10CFR20 re improved personnel dosimetry processing.

 BZALAY, R. Atomic Industrial Forum DOLECEK, E. H., WYNVEEN, R. A. Argonne National Laboratory 49FR1205 84/03/16 Docketing & Bervices Branch 6pp 22675 001
- B403190326 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Supports Alternative 3.Option B NB9 logical administrative unit to establish stds for processing DELAND. F. H Ve Admin Hosp Lexington. KY 49FR1205 065 B4/02/24 CUNNINOHAM. R. E Division of Fuel Cycle & Material Safety ip. 22673:165
- 8403170369 Comments of proposed rule IOCFR20 re improved personnel dosimetry processing Recommends further consideration be given to other methods of certifying dosimetry processors HILLS; L. H Tennessee Valley Authority 49FR1205 016 84/03/12 Docketing & Services Branch. 2pp 22675,307
- B4031903B7 Package of three comments supporting proposed rule 10CFR20 re improvée personnel dosimetry processing VAN BRUNT, E & Arizona Public Bervice Co THORPE, J.R. General Public Utilities OPU Service Corp EURE, J. A Iowa, State of 49FR1205, 84/03/15 Docksting & Services Branch Spp 22675, 309.
- 8403170403 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing. Supports rule.
 KENYON: B D. Pennsylvania Power & Light Co. 49FR1205 063 84/03/12
 CHILK: S J. Docketing & Services Branch ip 22674 336
- 8403210004 Comments on proposed rule 100FR20 re improved personnel dosimetry processing Supports Alternative 3.0ption B re NBS lab accreditation programs, BROWN,8. W Mallincknodt, Inc. 49FR1205 0B0 84/03/14 Docketing & Services Branch 2pp 22706.334
- 8403210009 Package of three comments supporting proposed rule 10CFR20 re improved personnel dosinetry processing GIEGLER, C. W. Hisconsin Public Service Corp. DIXON, O. W. Southern California Edison Co. REED, J. D. Standard Oil Co. of Indiana (see also AMCCO). 49FR1205. 84/03/19 Docketing & Bervices Branch. 5pp. 22706:336
- B403210012 Comments on proposed rule iOCFR20 re improved personnel dosimetry processing. Recommends range of 50% plus or minus for dosimeters.

 LINTON.D.W. American College of Radiology 49FR1205 083 84/03/15.
 Docketing & Services Branch. 2pp. 22706-344.
- B40321001B Comments on proposed rule 100FR60 re waste burial in saturated & uneaturated zones, Buggests containment be shaped like pyramid to with stand earthquakes, tornadoes & concussion from bomb blasts,
 NEMETHY, E Affiliation Not Assigned, 49FR3934 002, 84/03/14, Docketing & Services Branch, 1p. 22706:349.

- 84032:0022 Comments an proposed rule 10CFR110 re expart/import of huclear matl Questions why Soviet Union is not on list of embargoed or restricted destinations NEMETHY.E Aftlistion Not Assigned 49FR7572 001 84/03/15 Docketing & Services Granch 1p 22705 086
- B403210029 Comments on proposed rule 10CFR50 re elimination of thermal annualing requirements of App 0.Section IV.B re pressurized thermal shock Supports rule Requirements not needed FAY, C W Misconsin Electric Power Co 49FR449B 002 B4/03/15 CHILKS J Office of the Secretary of the Commission 2pp
- 8403230058 Comments on proposed rule 100FR20 re improved personnel dosimetry processing Supports Alternative 3.Option B re utilisation of NBS lab accreditation program THRON.R W Minnesots. State of 49FR1205 084 84/03/14 Docketing & Services Branch IP 22724 362
- 8403290002 Final response to FOIA request for four categories of documents tests, studies & analyses referencing or pertaining to NUREG-0103, "815 for I&W PHR" App A documents encl FELTON, J.M. Division of Rules and Records 84/01/13 MADDEN, T.J. Kays, Scholer, Fiermen, Hays & Handler 6pp 22816 127. 24% Fiche 50-000, 84/01/13.8403270002
- ~-8403290034 Discusses Reg Guide I 45, ISA draft Std 867 03 & ANSI draft Btd N 41 21 Suggested items clarifying reg puide listed MCGUEEN'M M. Affiliation Not Assigned 79/07/23 Atomic Energy Commission - Directorate of Regulatory Standards 15pp 22817.039
- 8403290242 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Seriously questions need for change Prefers current sys SDRENSEN.9 C Hashington Public Power Supply System 49FR1205 087 84/03/07 Docketing & Services Branch 2pp. 22800.227
- 8403290252 Advises recipients of comments on proposed rule LOCFR20 that Comment 69 duplicate of Comment 60 Number 69 will not be used again * Docketing & Services Branch 49FR1205 84/03/26 Docketing & Barvices Branch ip 22800 069
- 8403290255 Comments on proposed rules 10CFR2 & 72 re hybrid hearing procedures for expansions of onsite spent fuel storage capacity at civilian nuclear power reactors Prefers Option 2 w/mod.

 8HERMODD.0 0 General Electric Co 49FR54499 018 84/03/02 Docketing & Services Branch 3pp 22800 072
- 8403290263 Comments on proposed rule 10CFR20 re specifying residual radioactive contamination limits for decommissioning Adoption of 50 mrem per yr effective dose equivalent for limiting value acceptable TEDFORD. C F Arixona, State of 49FR1205 08B 84/03/21 CMILK:8 J Office of the Secretary of the Commission 1p 22800 078
- 8403270277 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing. Concurs w/EEI comments to minimize unnecessary paper work & to provide suggested definition of dosimetry processor MITTL.R.L. Public Service Electric & Gas Co of New Jersey 49FR1203 085 84/03/12 CHILK.J Office of the Secretary of the Commission ip 22814 080
- B403270276 Comments on proposed rule 10CFR60 & NUREO-1046 re disposel of high level radwastes in unsaturated zone HILLIAMS, R E Milliams & Associates NRC-02-82-046 47FR5734 003 84/03/15 POHLE, J Division of Waste Management 24p 22800 178
- B403290297 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Concurs w/actions to improve accuracy & reliability of dosimetry sys. Buggests NRC clarify intent of rule to licensee HUDHEG.T J. Navy. Dept. of 49FR1205-086-84/03/22 Docketing & Services Branch ip 22800-036
- 8403270321 Advises that encl 840309 ltr commenting an proposed rule 10CFR20 re improved dosimetry processing not comments by J Bakanauskas Bignature forged Comments should be withdrawn from consideration Forged 1tr dtd 840309 encl. BAKANAUSKAS, J Massachusetts, Univ of: Medical School. 49FR1205 84/03/20. Docketing & Services Branch 2pp. 22602 065

PRM PETITION FOR RULEMAKING

- 8403010024 Responds to FOIA request for documents re petition for rulemaking PRH-50~50-31.from Citizens Test Force of Chapel Hill.NC Forwards App A documents App B documents completely withheld (ref FOIA Exemption 5).
 FELTON.J M Division of Rules and Records 84/01/18 SHOLLY.8 C. Union of Concerned Scientists 4pp 22446 035
- --B301060420 Requests review & comments re encl draft FR notice to deny Citizens Task Force of Chapel Hill.NC petition for rulemeking (PRM-50-31) W/o encl NORBERO. J Human Factors & Safeguards Branch 82/12/27.
 BASSETT. D E Division of Accident Evaluation (Pre 840101) 2pp. 22446 041
- ~-8403010038 Requests documents re petition for rulemaking PRM-50-31 filed by Citizens Task Force & R Bernero 830916 memo to NRC div directors re draft rulemaking on emergency preparedness MARKEV.E J House of Rep. Interior & Insular Affairs 83/09/22 PALLADING,N J Commissioners 1p 22446-040.
- 8403090075 Comments on petition for rulemaking PRM-20-14 re disposai of short-fived radionuclides No comments offered.

 8ZYMCZAK.G. Firex Corp 49FR3667. 84/02/27 FELTON.J M. Division of Rules end Records ip. 22575 293
- 8403090173 Commants on petition for rulemaking PRM-20-14 re disposal of very low level radwaste Supports rulemaking MARTIN.JB Affiliation Not Assigned 49FR3647 009. 84/02/28 CHILK.S J Office of the Secretary of the Commission 6pp. 22575 137
- 8403990180 Comments on patition for rulemaking PRM-20-14 ra short-lived radionuclides Company does not use short-lived radionuclides JDHNSON,5,M Sangemo Weston, Inc. 49FR3667, 84/02/16 FELTON,J M Division of Rules and Records 1p. 22574 272
- B40309DiB4 Comments on petition for rulemaking PRM-20-14 re deregulation of radionuclides w/less than 100 days physical half-life Supports petition Waste would be toxic & should be
- BUTTREE CABTRONOVD.F Messachusetts General Hosp., Boston, MA 49FR3667 007 84/02/27 Pocketing & Services Branch. 1p 22573:309
- 8403070186 Comments on petition for rulemaking PRM-20-14 re disposal of short-lived low level radwaste Supports rule Change would resolve low level waste disposal problem since airborne radiation hezard will be negligible
 OUT.M Worcester Foundation for Experimental Biology 49FR3667 008
 84/03/01 Ducketing & Services Branch 1p. 22573:275
- B403130249 Comments on petition for rulemaking PRM-R0-14 re disposal of very low concentrations of short-lived radioactive mati Supports enend proposed by Univ of Utah WIEN.8 0 Wish Laboratories. Inc. 49FR3647 010 83/03/05 Docketing & Services Brench 2pp 22617:255
- 8403140189 Comments on petition for rulemaking PRM-20-14 re disposal of very low concentrations of short-lived radioactive matl. Emphasis should be placed on disposal of truly hazardous chemical waste HADE.L Texas, Univ of, Austin, TX 49FR3667 0ii 84/03/09 Docketing & Services Branch. 1p 22620 215.
- 8403i40221 Comments on petition for rulemaking PRM-20-14 re proposed extension of scintillation viel exemption to include short-lived isotopes Supports proposed rule GLAS9.D J Biotechnics International, Inc. 49FR3667 DIR 84/03/09 Docketing & Services Brench. 3pp. 22631,052
- 8403170362 Comments on petition for rulemaking PRM-20-14 re disposal of short-lived radionuclides. Supports rulemaking JOHNSON R U Harvard Univ , Cambridge, MA. 49FR3667 013 84/03/05 Docketing & Services Branch 2pp 22675 235.
- 8403210107 Package of four comments supporting petition for rulemaking PRM-20-14 re disposal of very low level concentrations of short-lived radionuclides.

 MILES.H L. Army, Dept of LIETO,R.P Henry Ford Hosp, Detroit, MI LANCIONE, Hillipore Corp. 49FR3667. 84/03/19 Docketing & Services Brench, 5pp 22706:135
- 8403230069 Comments on petition for rulemaking PRM-20-14 submitted by Univ of Utah re current restrictions on waste disposal. Supports rulemaking MADE-L. Health Physics Society 49FR3667 018, 84/03/09, Docketing & Services Branch ip 22726 327.

- B40329023B Package of two comments on petition for rulemaking PRM-20-14 re disposal of short-lived redignuclides by burial DURKOSH.E D Pittsburgh, Univ of, Pittsburgh, PA ORUNEWALD.R. Hisconsin, Univ, of, Milwaukee, HI. 49FR3667 B4/03/26 Docksting & Services Branch 10pp 22800:176
- 8403290233 Comments on petition for rulemaking PRM-35-5 re restricting use of bone mineral analyzer to qualified & trained physician. Suggests increase in min number of hours from 8 to 16 Supports petition
 KRISHNAMURTHY Vet Admin. Hosp. Portland. OR 49FR8621. 84/03/20, Office of the Secretary of the Commission 1p 22800.175.
- 8403290259 Package of three comments opposing patition for rulemaking PRM-35-5 submitted by Nuclear Radiation Consultants on use of 94-153 bone mineral analyzer.

 SILBERSTEIN.E. Cincinnati, Univ of, Hosp., Cincinnati, OH LLAURADD, J 9 Vet. Admin Hosp Lome Linda, CA ZIELONKA, J, 8 Veterans Admin Medical Center, Wood, WI 49FR6821 84/03/26 CHIEK, B, J Office of the Becretary of the Commission. 5pp. 22800.005
- 8403290272 Comments on petition for rulemaking PRM-20-14 re burial of certain redicactive mat) in hazardous waste landfills.

 Opposes rulemaking BALZMAN,L Friands of the Earth, 49FR3667 025. 84/03/19.

 Docksting & Services Branch ip 22814'076.
- B403290301 Package of two comments on petition for rulemaking PRM-20-14 re disposal of short-lived radionuclides.

 KANE, M S Brandeis Univ Waltham, MA DDERGEBJ.E. Wyoming, Univ of, Leramte, My 49FR3667. 84/03/23 Docketing & Services
 Branch Jpp. 22800:043.
- B4032903i1 Package of two comments on petition for rulemaking PRM-20-i4 re disposal of short-lived radionuclides. Supports petition, w/rev, '
 HOLLEMAN, D Alaska, Univ of, Fairbanks, TUTTLE, H. K., Vet. Admin Hosp. Portlend, OR. 49FR3667. B4/03/23 Office of the Secretary of the Commission 3pp. 22802.094

PROJ PROJECTS - PREDOCKET LICENSING

- 84030i0123 Responds to FDIA request for studies performed by USGS & State of CA Div of Mines & Geology re facility seismic design, Forwards App A documents Info also available in PDR, FELTON, J. M Division of Rules and Records. 83/12/20 CALSOYAS, C. D Affiliation Not Assigned 3pp 22444.347, 24X Fiche.50-312,83/12/20.8403010123
- ---79:1120370 Requests add1 info to complete review of initial site examination info date form
 DEYOUNG:R C Atomic Energy Commission, Directorate of Licensing-74/12/13 DAVIB.E.K Becramento Municipal Utility District, 2pp 22445 028 24X Fiche 50-312/83/12/20/8403010123.
- --79iii20403 Requests initial sits examination info. GIAMBUSSO, A Atomic Energy Commission, Directorate of Licensing 74/08/14, DAVIS, E K Secramento Municipal Utility District Spp. 22445 034
- --79ii120413 Responds to 760ii3 ltr re DL Kelleker 75i2i7 concern about nucleer plant in Orviiie. CA vicinity. No plant planned for area Discusses DBE re plant design DIRCKS, M J. NRC No Detailed Affiliation Given. 76/02/06 CRANSTON. A Beneta 3pp. 22445.041. 24X Fiche. 50-312,83/12/20, 8403010123
- ---B403010150 Forwards evaluation of Unit 2 initial site exam info data review Site safety members participating in review iisted, DENTON.H.R. Atomic Energy Commission, Directorate of Licensing 74/10/10 DEYOUNGR.C. Atomic Energy Commission, Directorate of Licensing 4pp 22445:046 24X Fiche:50-312,83/12/20,8403010123

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

- B402070020 Board Notification 84-044: forwards Part 21 rept re Transamerica Delaval. Inc turbocharger thrust bearing lubrication defect resulting in engine nonavailability. EISENHUT.D.9 Division of Licensing. 84/02/29. PALLADING Commissioners. 4pp 22541.263 24X Fiche: 50-000.84/02/29. 8402070020.
- 8402270274 Third interim deficiency rept, Item 111 re seismic qualification test failure of Transamerica Delaval, Inc starting air check for emergency diesel engine generator sets Also reporteble per Part 21. Next rept by 840525 PARSONS; R M. Carolina Power & Light Co NRC-181 84/02/15 0'AELLLy, J P. Region 2, Office of Director. 4pp 22391: 304 24X Ficha: 50-400, 84/02/15, 8402270274.

- B402290274 Interim deficiency rept re loose flexible coupling drive hubs on components supplied by Transamerica Delaval. Inc Initially reported on B40120 Next rept by B40531 Also reported per Part 2: EDELMAN.H R Cleveland Electric Illuminating Co B4/02/17 KEP/LER.J G Region 3, Office of Director 2pp 22426 299 24X Fiche: 50-440, 84/02/17, 8402290274
- E403010350 Interim deficiency rept. Item 158 re Pullman Const Industries/Ebasco design interface HVAC ductuork. Differences impacting seismic qualification may exist between design & febrication documents Also reportable per Part 2! PARSONS, R M Carolins Power & Light Co 158 84/02/17 0'REILLY, J P. Region 2, Office of Director 1p 22432-328, 24% Fiche. 50-400, 84/02/17, 8403010350
- 8403010374 Deficiency & Part 21 repts, Item 157 re Ruskin Mfg Co supplied actuators failing to meet functional test requirements of QH Bettis Co. Initially reported on 831221 Next rept will be submitted by 840323 PARSONS.R M. Carolina Power & Light Co. NRC-182 84/02/17. G'REILLY, J.P. Region 2. Office of Director ip 22434 046 24X Fiche. 50-400, 84/02/17. 8403010394
- B403050120 Responds to NRC B40126 ltr re daviation noted in QA Program Inep Rept 9990030/83-02. Corrective actions specified max value reevaluated, Exceeding value did not adversely affect performance of UVID Condition not reportable per Part 21, BAUTER, D M Westinghouse Electric Corp 84/02/23 PUTAPDVS, U Vendor Program Branch. 2pp. 22488 030
- 8403050170 Part 21 rept re potential degradation of actuator stroking times re elapsed time from original mfg Caused by ethylene propolene seal absorbing hydrocarbone from grease UPTDN:RT OH-Bettis Co 84/02/20 SEYFRIT, C Region 4, Office of Director 18pp 22485:210
- B403060311 Part 21 final design rept re inadequacy of evc water & circulating water pump house structure Analysis completed Repair conet activities in progress.
 KREIDER.H.O. United Engineers & Constructors, Inc. (subs. of Raytheon Co.). 84/02/28. Director's Office, Office of Inspection and Enforcement. 3pp 22515 335 24X Fiche 50-443,84/02/28, B403040314
- B403070256 Followup Part Ri rept re defective mechanical anubber capstam springs supplied by Pacific Bcientific Affected utils listed. Purchasers have been notified & advised to work directly w/Pacific Bcientific in disposition.

 HGUI-L. NPB Industries, Inc. NPBI-01-3825, 84/02/24 DEVOUNG,R C Director's Office, Office of Inspection and Enforcement 2pp 22536:279 24X Fiche 50-000,84/02/24,8403070256
- B403070285 Fifth interim deficiency & Part 21 repts, Item 117 re welding defects on Class IE 6 9 kV circuit breakers Initially reported on B3021i, All Class IE breakers at sits returned to Bismens-Allie Final rept expected by B40331.
 PARSONS, R M. Carolina Power & Light Co NRC-18B. 84/02/29 0'REILLY, J P. Region D. Office of Director 4pp. 22547.075 24X Fichs 50-400, B4/02/29, B403070285
- B403070286 Final deficiency rept re Parsons-Peebles amergancy diesel generator 28-B rear bearing problem Initially reported on 830627 Generator, repaired to be used as spare Alan reported per Part 21 MILLS.L.M. Tennessee Valley Authority 84/02/29. O'REILLY, J.P. Region 2, Office of Director 4pp 22546 224, 24X Fiche: 50-390, 84/02/29, 8403070286
- 8402070290 Fourth interim deficiency rept. Item 77 re seismic Class I cable tray, conduit & HVAC hangers supplied by Peden Bteel Intitially reported on B20802, Component reins; in progress, Next rept by 840701, Also reported per Pent 21 PARSONS, R M Carolina Power & Light Co 77 84/02/24 07/EELLLY, J.P. Region 2, Office of Director, 4pp. 22547 067 24X Fiche 50-400, 84/02/24, 8403070290
- B403070297 First interim deficiency rept re numerous deficiencies on E-max panels Initially reported on 840131, Incorrect connected wires will be repaired. Next rept by 840607 Also reportable per Part 21 HILLS.L.M. Tennessee Valley Authority, 84/02/29, 0'REILLY, J.P. Region 2, Office of Director, 2pp. 22546:357, 24% Fiche: 50-438, 84/02/29, 8403070297
- 8403070329 First interim deficiency rept re adaptor keyway on 8-inch Borg-Harner globe velves, Initially reported on 840131, Vendor will provide corrective section & identify add1 valves requiring mods, Also reportable per Pert 21.

 MILLS, L.M. Tennesses Velley Authority. NCR 2787 84/02/29, 0'AEILLY, J.P. Region 2: 0ffice of Director. 2pp. 22546, 313 24X Fiche: 50-438, 84/02/29, 8403070329

- B4030B0240 Part 21 rept re failure of Pacific Air Products linear converter Initially reported on B40117 Failure due to excessive wear of brass shaft guider on input & output shafts investigation underway HALL,D P Illinois Power Co U-10132 84/02/29 KEPPLER,J G Repion 3, Office of Director 2pp 22554 269 24% Fiche 50-461,84/02/29,8403080240
- 8403090082 Fourth interim & Part 21 repts, Item 101 re defective governor drive coupling supplied by Transamerica Delaval Initially reported on 820909 Couplings to be replaced final rept by 840525
 PARSONS, R M Carolina Power & Light Co NRC-185 84/02/24 G'REILLY, J P Region 2, Office of Director 4pp 22575 299 24X Fiche 50-400.84/02/24,8403090082
- B403090181 Twelfth interim deficiency rept re main steam line failure due to main feedwater overfill Initially reported on 800319 Field change package submitted by B&W Next rept by B40822 Also reportable per Part 21.

 MILLS.L M Tennessee Valley Authority 84/02/27 O'REILLY, J P Region 2. Office of Director. Spp 22573 272 24X Fiche 50-438,84/02/27,8403090181
- BA0309019B Forwards two itrs referenced in B30916 itr.representing entire dialogue w/NRC re GC breakdown All future correspondence will be forwarded to IE & will be routed through author opc KALE.D L. 901f & Western Industries. Inc B4/01/17 ANDERSON.W F Director's Office. Office of Inspection and Enforcement ip 22574 273.
- ---B403070200 Potential Part 21 rept reviewing documentation re all nuclear component shipments Based on review, quality problem nonexistent & Part 21 inapplicable ΚΑΙΕ, D L. Gulf & Western Industries, Inc. B3/09/i6 O'REJLLY, J P. Region 2, Office of Director 2pp 22574 274
- --8403070202 Advises of potential quality program breakdown re metallic pipe fittings Thorough internal investigation underway KALE,D L. Gulf & Western Industries, Inc. 83/03/1 O'REILLY,J P. Region 2, Office of Director 1p 22574 277
- --B403070203 Submits followup rept to 830311 initial notification of potential quality program breakdown Areas of concern include traceability of matl through mfg mill test repts & heat treatment of matl KALE,D L Gulf & Western Industries, Inc. B3/04/11 G'REILLY,J P Region 2, Office of Director 12pp 22574 278
- 8403090865 Final Deficiency Rept PRD 83/08 re inability to maintain pressurized water supply to RHR pumps & discharge piping supplied by Bechtel. Initially reported on 830415. Hardware mode implemented Also reportable per Part 21 ROGAUGHY. J. P. Mississippi Fawer & Light Co PRD 83/08 84/03/02 D'RETLLY. J. P. Region 2. Office of Director. 4pp 22572.144 24X Fiche 50-416.84/03/02.8403090265
- B403120032 Final Deficiency Rept DER 83-70 re wiring in emergency response facility cabinets supplied by Energy. Inc not in conformance w/IEEE-384 criteria Initially reported on 83101; Drawings resubmitted Also reported per Part 21 VAN BRUNT.E E Arizone Public Service Co DER 63-70 84/02/28 BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 4pp 22588 025, 24% Fiche 50-528,84/02/28,8403120032
- B403120105 First interim deficiency rept re loose drive hubs on overspeed governor drive shaft on Transamerica Delaval. Inc diesels Initially reported on B40203 Svc info memo being reviewed for approval Also reportable per Part 21.

 MILLEL M. Tennessee Valley Authority 84/03/01 O'REILLY, J P Region 2, Office of Director 2pp. 22585, 229 24X Fichs, 50-000, 84/03/01, 8403120105
- 8403120136 Part 21 rept re Westinghouse Type SA-1 DSR or DSRV standby diesel generator differential relay defect Relay problem reported in 840215 Buppl 1 to IE Info Notice 83-63 RTE Delta requested to review defect & recommend correction.

 BOYER:R E Transamerica Delaval, Inc. IEIN-83-63 84/03/07 Director's DSfice, DSfice of Inspection and Enforcement 2pp 22565:219 24X Fiche 50-416,84/03/07,8403120136
- B403120163 First interim deficiency mept re setting of shutdown voltage for vital inverters by Intl Power Machines Initially reported on B40209. Corrective action requested from vendor Next mept by B40582. Also reported per Part 21 HILLSIL M Tennessee Valley Authority 84/03/01 O'REILLY, J P Region 2, Office of Director 2pp 28589 207. 24X Fiche 50-438,84/03/01.8403120163

- 8403130237 Interim deficiency & Part 21 repts, Item 159 re flexible coupling drive shaft in overspeed governor & fuel transfer pump drive of standby diesel generator Initially reported on 840206 Final rept will be submitted by 840416 PARSONS.R M Carolina Power & Light Co NRC-190 84/03/02 0'REILLY,J P Region 2. Office of Director 1p 22617 277 24X Fiche 50-400.84/03/02.8403130237
- B403130387 Part 21 rept re stop tab breakage in BBM type control switches Replacement front plates will be furnished to affected customers
 MANKOFF.L L. General Electric Co B4/03/02 DEYOUNG, R Director's Office, Office of Inspection and Enforcement 3pp 22613 323
- 84031310378 Fifth interim deficiency rept. Item 53 re potential for Heatinghouse mfg gate valves failing to fully close/open under design conditions Also reportable per Part 21 Hardware changes completed Final rept expected by 840415 PARSONS:R M Carolina Power & Light Co NRC-187 84/03/01 G'REILLY.J P Region 2. Office of Director. 10pp 22616 283 243 Fiche 50-400, 84/03/01.8403130378
- 8403140122 Part 21 rept re status update concerning abnormal wear on linear converters. Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry.

 DDDSQN.J P Pacific Air Products Co. B4/03/09. Director's Office. Office of Inspection and Enforcement 7pp 22624 068 24X Fiche 50-000.84/03/09.8403140122
- 8403140138 Part 21 rept re matis shipped from Carlinville plant lacking chemical overcheck requirement Affected items listed Ltrs sent to affected vendors encl KALE.D L. Gulf & Western Industries, Inc. PY21-84-133-000 84/02/17 DEYOUND.R Director's Office, Office of Inspection and Enforcement 33pp 22520 298
- 8403160042 First interim deficiency rept re ITT Grinnel pipe supports designed wisway struts instead of required paps. Initially reported on 84010B Alternate analysis load tables will be revised Also reportable per Part 21 Next rept by 84082B MILLS.L M Tennessee Valley Authority 84/03/06 0'REILLY, J P Region 2. Office of Director 2pp 22653 126 24X Fithe 50-438,84/03/06,8403160042
- B403i90036 Interim deficiency & Part 21 repts restatus on open items KOESTER.O.L. Kansas Cas & Electric Co. KMLNRC 84-025 84/03/05 OAGLIARDO.JE Region 4. Office of Director IBpp 22666-215 24X Fiche 50-482, 84/03/05, 8403190036
- 8403190051 Interim deficiency rept re failure of linear converters on multi-blade dampers supplied by Pacific Air Products, Co utilized in safety-related HVAC sys Initially reported on 840216 Final rept by 840710 Also reported per Part 21 EDELMAN, M R Cleveland Electric Illuminating Co RDC 94(84) 84/03/07 KEPPLER, J O Region 3, Office of Director 2pp 22666 186 24X Fiche 50-440,84/03/09,8403190051
- 8403190101 Part 21 rept re apparent design deficiency in Siemens Allis Model NA-2058 stored energy circuit breaker Breaker insp & hold down device orientation will be complete by 840401 Betermination of permanent fix & implementation by 840601 JOHNSON, B D., VANDEWALLE, D J. Consumers Power Co. 84702729 KEPPLER, J G. Region 3, Office of Director 5pp. 22669 305 24X Fiche 50-255,84702729,8403190101
- B403190248 Supplemental Part 21 rept re failed engine thrust bearing Plugs properly installed in both units Units free of potential defect MDRIARTY, J M Colt Industries, Inc. 84/03/08 KEPPLER, J G Region 3. Office of Director ip 22675 045 24X Fiche. 50-000. 84/03/08. 8403190248
- B403190287 Third interim Deficiency Rept NCR 2393 re Bingham-Willamette makeup/RP1 pump vibration Initially reported on B30622 Next rept expected by B40723 item also reportable under Part 21 MILLS,L M Tennessee Velley Authority NCR 2393 B4/03/12 O'REILLY,J P Region 2, Office of Director. 3pp 22672 275 24X Fithe 50-438,84/03/12.8403190287
- 8403190329 Forwards Vendor Program Insp Repts 79700231/83-01 & 97900231/84-01 on 831i15-17 & 840116-20, respectively. closing out Part 21 rept re seepage of oil from Dionite cables PDTAPOUS.U Region 4, Office of Director 84/03/15 NURELIUS.C E Division of Project & Resident Programs 1p 22675 026 24X Fache 30-461.84/03/15,8403190389

- 8403190374 Part 21 rept re failed engine thrust bearing Initially reported on 800502 Field insp of Colt-Pielstick Type PC-2 diesel generator sets completed using revised drawings Unit in compliance winsp procedure & free of potential defect MORIARTY. J M Colt Industries, Inc 84/03/08 KEPPLER, J Q Region 3. Office of Director 1p 22674 353 24% Fiche 50-443, 84/03/08, 8403190374
- 8403200203 Interim deficiency rapt. Item 101 & Part 21 rapt radefective governor drive coupling Correct Itr date is 840224.not 830224
 PARSONS.R M Carolina Power & Light Co NRC-192 84/03/09 D'REILLY.J P Region 2. Office of Director 1p 22699 347 24X Fiche: 50-400.84/03/09.8403200203
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPB-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils OE notified of affected units in BWR plants
 THEROUX, R R Terry Corp PT21 84-140-000 84/02/22 WOODRUFF, R W Director's Office, Office of Inspection and Enforcement 6pp 22706 527 24x Fiche 50-000, 84/02/22, 8403210032
- 8403210041 Final deficiency rept re incorrect operation of Div I & II diesel generator load shedding sequencing sys panels Initially reported on B309721 Circuit cards & card racks returned for mad Reinstallation expected by 840427 MCGAUCHY. J P Mississippi Fower & Light Co AECM-B4/0148 B4/03/15 0'REILLV.J.P. Region 2. Office of Director 5pp 22707 032 24X Fiche 50-417,84/03/15,8403210041
- 8403210046 First interim deficiency rept re ITT Orinnel pipe supports designed w/sway struts instead of required caps. Initially reported on 840216 Next rept by 850213 Also reportable per Part 21
 MILLS.L M Tennessee Valley Authority 84/03/13 Region 3, Office of Director 2pp. 22704 328 24X Fiche. 50-438, 84/03/13, 8403210046
- 8403210095 Part 21 rept re nonconformance of metal hose assemblies for ABME, Section III, Class 2 & 3 svc. Status of nonconforming items shipped encl AlI customers notified LALIKOS, J M Titeflex Corp PT21 83-141-000. 83/12/16. Director's Office. Offica of Inspection and Enforcement 4pp 22704 324 24% Fiche 50-000,83/12/16,8403210095
- 8403210125 Final deficiency rept re cavitation of jet pumps due to induction heating stress improvement cooling. Initially reported on 831206 No erostion found Also reportable per Part 21 Item not reportable per 10CFR50 55(e) CURTIS.N W Pennsylvania Power & Light Co. PLA-2103 84/03/06 MURLEY.T E Region 1, Office of Director 4pp. 22707, 228 24X Fiche: 50-388, 84/03/06, 8403210125
- 8403210136 Interim deficiency rept re Anchor Darling MPC8 sys valve vibration loosening anti-rotational set screws. Initially reported on 840127 & reported by GE per Part 21 Investigation in progress. Final rept by 840723 MANGAN.C V Niagara Mohawk Power Corp 8113 84/02/27 STAROSTECKI, R. Division of Project & Resident Programs. 2pp 22707 272 24x Fiche 50-410,84/02/27,8403210136
- 8403210145 Final deficiency & Part 21 repts re sefety peremeter display sys Technology Energy Corp Model 156 isolators Initially reported on 840106. Non-1E power supply will be provided for isolator prior to end of first refueling CURTIS.N W Pennsylvania Power & Light Co. PLA-2089 84/02/27 MURLEY, T E Region 1. 0ffice of Director 4pp. 22707.281. 24X Fichs 50-388.84/02/27.8403210145.
- 8403210192 Final deficiency rept re enti-rotational setscrewe in Anchor Darling glove valves. Initially reported on 840213, Setscrew tightened & stem coller threade staked using ctr punch. Also reported per Part 21 for Unit 1.

 MCGAUGHY, J.P. Mississippi Power & Light Co AECM-84/0159 84/03/14 D'REILLY, J.P. Region 2, Office of Director, Spp 22707 257 24% Fiche: 50-416, 84/03/14, 8403210192
- B403230019 Final Deficiency Rept DER 82-46 re ITT Barton pressure transmitters supplied by C-E not meeting overpressure requirements Caused by leakage of metallic washers & methodology error during calibr Also reported per Part 21, VAN BRUNT,E E Arizona Public Service Co. DER 82-46. 84/03/15. BISHOP,T W Division of Resident, Reactor Project & Engineering Programs 7pp 22724 353 24X Fiche 50-528,84/03/15,8403230019
- 8403230028 Followup Part 21 rept re nuclear valve/actuator stroking time possibly lengthaned beyond 15 s when using hydrocarbon-based lubricents Ltrs to affected utils encl HILBON, A K Henry Pratt Co CAR 0023 84/03/08 KEPPLER, J. G Region 3, Office of Director opp. 22730:306, 24X Fiche: 50-000,84/03/08,8403230028.

- 8403230056 Pert 21 rept re Westinghouse mechanically interlocked full voltage revereing starters hat maintaining required relative positions. Caused by essemblers incorrectly removing backing plates.
 RODRIGUEZ.R J. Sacremento Municipal Utility District RJR 84-054 84/02/15. MARTIN.J B Region 5. Dffice of Director 5pp 22726.045 24x Fiche 50-312,04/02/15,0403230056
- B403230095 Second interim deficiency rept re improper relief valve setting, design pressures & design temp within several sys Initially reported on B3iiiB Spec M-199 revised & code date repts amended, Also reported per Pert 21 CORTIS,N.W. Pannsylvenie Fower & Light Co. PLA-2075 B4/03/02 MURIEV.T E Region 1. Office of Director 14pp 22726 277 24X Fiche 50-388,84/03/02,8403230095
- B\$03230108 Part 21 rept re design deficiency in fleid-run cebles to Velcor solenoid velves Initially reported on 840319 Approx 50 velves affected at each facility Mgt corrective action repts issued MEYERS, B.L. Bechtel Corp. 84/03/19 DEYOUNG, R. Director's Office, Office of Inspection end Enforcement. 2pp 22730 234 24% Fiche: 50-000, 84/03/19, 8403230108.
- 8403230ii3 Rev 1 to final Deficiency Rept 82-50 re possible demeged flexible conduit couplings between euxiliary & control bldgs in event of seismic events exceeding 3/4 inch movement. Rev changes final rept disposition to reportable under 10CFR21. VAN BRUNTLE E Arizone Public Service Co. DER 82-50 84/03/09 BISHOPT.N Division of Resident, Reactor Project & Engineering Progrems. 4pp. 22730:215. 24X Fiche 50-528.84/03/09.8403230113
- 8403230115 Finel Deficiency & Part 21 Rept U-62 re fellure of stator winding on NEO2B seargency dissel generator mfg by Beloit Power Bys Initially reported on 830812 Stator repleted. Emergency generator installed & load tested BCHNELL, D. F. Union Electric Co ULNRC-766 84/03/15 KEPPLER, J. Q Region 3, Office of Director 4pp. 22730, 211. 24X Fiche 50-483, 84/03/15, 8403230115
- B403260233 Forwards summary list of deficiencies identified per iOCFR50.55(s).Part 21 & potential generic itr repts for comments BTAROBTECKIR Division of Project & Resident Programs. 84/02/28 Region i, Office of Director 7pp. 22756.065. 24X Fiche 50-000.84/02/28.8403260233
- 8403270039 Interim significant const deficiency rept. Item 100 reterminations to Knox fuse blocks, 9E 4, 160 kV switchgear All Knox fuse block terminations reinspected Next rept will be submitted by 840406 Also reported per Part 21 GERRETS, T. F. Louisiana Power & Light Co 100, 84/03/12, COLLINS, J. T. Region 4, Office of Director. 3pp 22766 159, 24% Ficher 50-382, 84/03/12, 8403270059
- 8403270182 Finel Deficiency & Part 21 Rept U-64 re Limitorque valve ectuetors BN-HV-8812A & B Initially reported on 831017 Valve failure due to improper installation of motor pinion gear. All 68-2-80 actuetors verifies for proper gear installation BCHWELL, D.F. Union Electric Co. ULNRC-769, 84703720, KEPPLER, J G Region 3, Office of Director 4pp 22771; 331, 24% Fiche: 50-483,84703720,8403270182
- 8403270219 Part 21 rept re broken contect cerrier 1n control device of 7.5 kV-15 kV.500-750 MVA.5 kV 350-3,000 & ell HKV circuit breekers. Initially reported on 830223 Addenda to instellation & maint procedures sent to affected units DUVALL.D.D. Brown Boveri Corp. (subs. of Brown Boveri & Co., Ltd.). 84/03/19. Record Services Branch (Document Control Desk) 5pp 22772:114. 24X Fiche 30-000.84/03/19.8403270219
- 8403300020 Rev i to finel Deficiency Rept DER 82-45 re ITT-Berton pressure transmitters supplied by C-E falling to meet overpressure requirements. Initially reported on 820824. Also reported per Pert 21 VAN BRUNT.E.E. Arizona Public Service Co. ANPP-29099-BBK/. 84/03/19. BISHOP.T.W. Division of Residents Reactor Project & Engineering Programs. 7pp, 22822 i7i. 24X Fichs 50-528,84/03/19, 840370020
- B403300034 Interim deficiency rept. Item 137 re GH Bettis operators on Ruskin-supplied HVAC dampers failing to meet functional test requirements. Initially reported on 831221. Required info unaveilable. Next rept by 840321. Also reported per Part 21. PARSONS.R.M. Capplina Power & Light Co. NRC-198 B4/03/23. O'REILLY.J.P. Region 2. Office of Director 1p. 22821-311, 24X Fiche: 50-400. 84/03/23. 8403300034.
- 8403300043 Third Interim deficiency rept, Item 95 re shop welding defects in Beismic I pipe hangers supplied by Bergen-Patterson & Item 72 re undersized skewed tee fillet weld on hangers. Finel rept by 841201 Also reported per Part 21 PARBONS,R.M. Cerolina Power & Light Co NRC-196, 84/03/21. O'REILLY, J.P. Region 2, Office of Director, 5pp 22819 315 24X Fiche: 50-400.84/03/21, 8403300043

- 8403300054 Fifth interim deficiency rept re defects in raw cooling water chiller unit flow control valves mfg by Metrex Valve Corp Initially reported on 821126 Investigation in progress Next rept by 850421 Also reportable per Part 21 HILLG.L M Tennesses Valley Authority 64/03/22 O'REILLY,J P Region 2. Office of Director 2pp 22821 264 24X Fiche 50-438,64/03/22,640300054
- B403300079 Suppl to Gould B30724 Part 21 rept re potential defects in molded case for 100 empere frame.multi-pole E & HE series circuit breakers, clarifying part distribution & affiliation arrangement BRADLEY, R D Siemans-Allis, Inc 83/11/17 MURLEY, T E Region 1. Office of Director 1p 22821.360.
- B403300107 First interim deficiency rept re new defects in Berton pressure transmitters supplied by Westinghouse Initially reported on 840223 Westinghouse will define corrective action by 840331 Also reportable under Pert 21 MILB.L M Tennessee Valley Authority 84/03/22 O'REILLY, J P Region 2, Office of Director 2pp 22821 223 24X Fiche 50-390.84/03/22.8403300109

QAP99 GUALITY ASSURANCE INSPECTIONS

- B4020i017B Ack receipt of B31223 ltr informing NRC of steps taken to correct nonconformence noted in GA Program Insp Rept 99900743/83-01 PDTAPGVB,U Region 4, Office of Director 84/01/25 DUVALL,D D Brown Boveri Corp (subs. of Brown Boveri & Co., Ltd.) ip 22038:335
- ---B402010185 Responds to NRC B31202 ltr re nonconformance noted in GA Program Insp Rept 99900743/83-01 Corrective actions Engineering Drawing 605143 revised w/appropriate detes & signatures DUVALL, D.D. Brown Boveri Corp. (subs of Brown Boveri & Co, Ltd) 83/12/23 PDTAPDVS, U. Region 4. Office of Director ip 20088 334
- 8402150211 Forwards GA Program Insp Rept 99900319/83-03 on 831031-1104 Implementation of GA program failed to meet certain NRC requirements. POTAPOUS.U Region 4, Office of Director 83/12/26 KOMES,J M Bechtel Corp 2pp 22244 121
- --8402150216 Notice of nonconformance from lnsp on 831031-1104 * Region 4, Office of Director 83/12/28 ip 22244 123
- --B402150224 GA Program Insp Rept 97900519/83-03 on B3103i-1104 Noncompliance noted might pipe whip restraints requested by mechanciel group to civil group, specified in FBAR but not installed. CQBTCLLOJR, MADSEN, C.L. Region 4, Office of Director B3/12/23, 12pp 22244 124
- B403010075 Responds to NRC B40126 ltr re nonconformance noted in GA Program Insp Rept 99900255/83-01 Corrective ections suppliers of code exempt items will be evaluated on basis of quality sus questionmains & performance review THOMBEN, E.R. Pacific Scientific 6000-08-52-84, 84/02/14 PDTAPDVB.U. Region 4, Office of Director 13pp. 22436 098
- 8403010079 Responds to 840123 ltr informing of nonconformences noted in GA Program Insp Rept 99900378/83-01. Insp Procedures NSP20-0003-0008 revised, issued & implemented. 8HANSON,N E Acme-Claveland Co 84/02/17. POTAPOVS.U Vandor Program Branch. 1p. 22436 114
- 8403010082 Advises that proposed engineering QA manual will be revised within 60 days to comply w/Criterion V of App B to 10CFR50, per 840123 request WILKINS, W D Anaconda Co (subs. of Atlantic-Richfield Co.) 84/02/14 POTAPRUS, U Vendor Progrem Branch ip 22435:278
- 8403010:22 Responds to NRC 830921 & 1205 ltrs re violations & nonconformances noted in GA Program Insp Repts 99900277/83-01,99900277/83-02 & 79900277/83-04 Corrective actions tests will be performed on Class IE cable types LITTLEHALES.0, Rocibestos Co. 84/02/14, POTAPOVS,U Region 4, Office of Director 25pp. 22405;253
- 8403050086 Confirms GA program insp at Philedelphie, PA facility on 840305-09, per 840216 telcon.
 POTAPOVS, U. Vendor Program Branch 84/02/23 CURNANE, R. A. United Engineers & Constructors, Inc. (subs. of Raytheon Co.), 1p. 22490, 006.

- 8403050089 Confirms dA program insp at Grove City,PA plant on 840312i6,per 840217 telcon PDTAPOUS,U Vendor Program Branch 84/02/24 STOLBA,F & Cooper Industries, Inc. 1p. 22490 013
- 8403050i02 Clarifies items mentioned in GA Program Insp Rept 99900820/83-0i Formai training conducted in Nov 1983 included personnel performing quality affecting activities Dmega Englneering certified calibr of equipment performed MCCRONE.J Fluorocarban Co 84/02/17 POTAPDVS, U Vendor Program Branch 3pp 22485 230
- 8403050120 Responds to NRC 840126 ltr re deviation noted in QA Program Insp Rept 99700330/83-02 Corrective actions specified max value reevaluated Exceeding value did not adversely affect performance of UVID Condition not reportable per Part 21 SAUTER, D.N. Westinghouse Electric Corp. 84/02/23 PDTAPOVS, U Vendor Program Branch 2pp. 22488 030
- 8403050126 Confirms QA program insp at Willimantic.CT plant on 840312-16.per 840213 telcon POTAPOVS.U Vendor Program Branch 84/02/27 ROBERTS.L B Brand-Rex CO 1p 22489 158
- 8403050130 Confirms QA program insp at Lynchburg.VA plant on 840312-16, per 840224 telcon POTAPOVS.U Vendor Program Branch 84/02/27 GUILBERT.D.E Babcock & Wilcox Co ip 22489 i71
- 8403050176 Confirms QA program limp at State of DR ofc on 840305-09, per 840216 telcon POTAPOVS,U Vendor Program Branch 84/02/24 WALTERS,C H Oregon, State of Ip 22489 065
- 8403040806 Confirms GA program Insp at Colorado Eprings.CO plant on 840312-16.per 840224 telcon PDTAPOVS.U Vandor Program Branch 84/03/01 PIRAIND.D Kamen Co ip 22513 362
- 8403060092 Ack receipt of 831013 & 840131 ltrs informing NRC of steps taken to correct violation & nonconformance noted in GA Program Insp Rept 99700330/83-01 POTAPOVS.U Region 4. Office of Director 84/03/01 BAUTER.D M Westinghouse Electric Corp 19 22516 309
- --8403060096 Responds to NRC 840109 ltr re nonconformance noted in QA Program Insp Rept 99900330/83-01 Corrective actions each undervoitage trip device assigned unique serial number JONESO B : SAUTER. D N Westinghouse Electric Corp 84/01/31 PDTAPQVS.U Region 4, Office of Director 1p 22516-310
- --8403060098 Ack receipt of 831013 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900330/83-01 Addl info required for Item C of notice of nonconformance re undervoltage trip devices POTAPDVS.U Region 4. Office of Director 84/01/09 SAUTER.D M Westinghouse Clectric Corp 1p 22516 311
- ---B403060101 Responds to ARC 830913 ltr re violation & nonconformance noted in GA Program Insp Ropt 99700330/83-01 Corrective actions revised poster w/revs promulgated up to 890110 completed & revised poster will be posted promptly JONES, D B . SAUTER, D M Westinghouse Electric Corp 83/10/13 POTAPOVS, U Region 4. Office of Director 5pp 22516 312
- 8403060157 Ack receipt of 840202 ltr informing NRC steps taken to correct nonconformance noted in OA Program Insp Rept 99900002/83-02 POTAPOVS.U Region 4. Office of Director 84/03/0] LICHTENBERGER Combustion Engineering. Inc. ip 22528 210
- --8403040161 Responds to NRC 840109 ltr re nonconformance noted in 9A Program Insp Rept 99900002/83-02 Corrective actions individuals responsible for review & approval of certification data alerted to discrepancies observed LICHIENDERGER Combustion Engineering, Inc. NOA 84-003 84/02/02 FOTAPOVS, U. Region 4. Office of Director. 2pp 22528 211
- 8403060187 Responds to NRC 840124 ltr re nonconformance noted in GA Program Insp Rept 99900231/83-01 Corrective actions 810922 ltr from Isomedix confirmed applicability of Parts 21 & 50 for prior work SRUDEUR.R I Obsnite Co 84/02/14. POTAPOVS.U Region 4, Office of Director 1p 22518 361
- 8403060219 Ack receipt of 840125 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900519/83-03 POTAPOVS, U Vendor Program Branch 84/02/16 KOMES, J M Dechtel Corp ip 22508 264

- --8403060228 Responds to NRC 831228 ltr re nonconformance noted in GA Program Insp Rept 99900519/83-Q3 Corrective actions Engineering Dept Procedure EDP 5 I revised to require interdiscipline communications of significant nature KONES.J M Bechtel Corp. DAS-84/030 84/01/25 POTAPOVS.U.. Vendor Program Branch 3pp 22508 265
- 8403060251 Confirms GA program insp at Tulsa, OX plant on 840326-30, per 840228 telcon POTAPOVS, V Vandor Program Branch 84/03/01 DUVALL, D.D. Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.) 1p 22515 194
- 8403050262 Responds to NRC 831220 ltr re nonconformances noted in GA Program Insp Rept 99900277/83-03 Corrective actions GC supervisor responsible for followup to assure irradiation unit calibr completed on schedule & stickers in order LITTLEHALES, G Rockbestos Co 84/02/27 PGTAPGV8,U, Region 4, Office of Director 3pp 22517 129
- 8403060282 Confirms QA program insp at ABME administration ofc on 840326-30, per 840227 telcon PDTAPOVS, U Region 4, Office of Director American Society of Mechanical Engineers 1p. 22519, 070.
- 8403060287 Confirms OA program insp at Beloit.WI plant on 840326-30, per 840301 teleon POTAPOVS.U Vendor Program Branch 84/03/02 MORIARTY.J M Colt Industries, Inc. 1p 22518-362
- 8403040348 Ack receipt of 831123 & 840217 ltrs informing NRC of steps taken to correct deviations & nonconformance noted in QA Program Insp Rept 97900820/83-01. POTAPOUS U Vendor Program Branch. 84/03/02 MCCRONE, J Fiuorocarbon Co 1p 22508 054
- --B403060352 Ack receipt of B3110B & 23 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 97900B20/83-01 Addl info re training & surveys requested within 25 days of itr date POTAPOVB.U Vendor Program Branch B4/01/23 MCCRONE, J Fluorocarbon Co 1p 22508 055
- --8403060355 Requests delay in submitting response to 831012 ltr re nonconformance noted in GA Program Insp Rept 99700820/83-01 Response expected by 831118 MCCRONE,J Fluorocarbon Co 83/11/08 CDNWAY,J T Region 4, Office of Director 1p 22508 056
- --B403060361 Responds to NRC 831012 Itr re nonconformance noted in QA Program Insp Rept 97900820/83-01 Corrective actions Section 206.FCD QA Procedure CQCP-013 & 830831 10CFR21 notice pasted MCCRONE, J. Fluorocarbon Co 83/11/23 POTAPOVE, V Region 4, Office of Director 4pp 22508 057
- --8403060365 Rev O to Procedure CGCF-013, "Procedure for Reporting Defects & Noncompliance" SHIBLER,E Fluorocarbon Co 63/11/17 Spp 22508 061.
- --8403040369 Rev O to Procedure OCP-014, "Indoctrination & Training Procedure for GC Personnel"

 SHIBLER,E Fluorocarbon Co 83/09/28 App 22508 049
- --8403060372 Rev O to Procedure GCP-017, "Qualification of Personnel for NDT" SHISLER.E Fluoracarbon Co 83/11/17 24pp 22508:073
- --B403060374 Rev O to Procedure CMP-047. "Weld Removal Procedure BHISLER.E Fluoracerbon Co 83/11/17 30pp 22508 097.
- --8403060376 Rev 1 to Procedure CP8-023, "Weld Aging Procedure for Nuclear O-Rings" PRINTZ: M Fluorocarbon Co 83/11/17 7pp 22508 127
- --8403060379 Rev 1 to Procedure QCP-020; "Training Procedures for Radiographers" SHISLER,E Fluorocarbon Co. 83/11/17, 9pp 22508,134.
- 8403120036 Ack receipt of 840217 ltr informing NRC of steps taken to correct nonconformance noted in 8d Program Insp Rept 97900378/83-01 implementation of corrective actions will be reviewed during future insp POTAPOVS, U Vendor Program Branch, 84/03/05 SWANSON, N. E. Acme-Cleveland Co ip 22589:270

- B403120043 Responds to NRC 840124 ltr re nonconformance noted in GA Program Insp Rept 99900702/83-01 Corrective actions Engineering Change Proposal 6717 Instigated to activate Engineering Change Notice 8712 voided 820702 JONES, W.F. Morrison-Knudsen Co., Inc. 84/02/28 POTAPOVS, U Vendor Program Branch 7pp 22589 279
- 8403120108 Ack receipt of 840203 ltr informing NRC of notification to customers re-potential loosening of globe valve anti-rotation collar set screws & recommended corrective action per QA Program Insp. Rept. 99700037/83-03 POTAPOUS. U Vendor Program Branch 84/03/05 CARDN. A E Anchon/Darling Valve Co (subs of Anchon/Darling Industries, Inc.) ip 22588 122
- --8403120114 Forwards sample ltr.w/attachments & cover ltrs dtd 831017-840130.sent to customers having Anchor/Darling globe valves w/nonrotating stems per GA Program Insp Rept 99900053/83-03 KNIEBER, G W Anchor/Darling Valve Co (subs of Anchor/Darling Industries, Inc.) 84/02/03 KELLEY, W Vendor Program Branch 37pp 22589 123
- 8403120117 Responds to NRC ltr re nonconformance noted in GA Program Insp Rept 99700394/83-02 on 831215 Corrective actions Rejection Rept 05660 paporwork corrected & memo issued rerequirements for recording rejection rept numbers SHAFER.J C Metal Belious Corp 84/02/24 POTAPOVS.U Vendor Program Branch 4pp 22589 214
- 8403i30026 Responds to NRC 840i3i itr re nonconformance noted in GA Program Insp Rept 99700786i/B3-02 Corrective actions annual GA audit will confirm documentation for set-up & operator training & qualification,per GA manual requirements DIXON.D J Generai Electric Co 84/03/01 POTAPOVS,U Vendor Program Branch 9pp 22615 1i4
- 8403130032 Forwards GA Program Insp Rept 99900273/83-02 on 831205-07 & notice of nonconformance POTAPOVS, U Vendor Program Branch 84/02/02 SCHMIDT.W T Westinghouse Electric Corp 2pp 22614.308
- --8403130036 Notice of nonconformance from insp on 831205-09 * Vendor Program Branch 84/02/02 1p 22614 310
- ---8403130042 GA Program Insp Rept 97900273/83-02 on 831205-09 Noncompliance noted internal audits not performed prior to current NRC insp & correct suffix not applied to style numbers on SA-1 relay nameplates for current relay units SUTTON.J W , HALE,C. Vendor Program Branch 84/01/30 13p; 22614 311
- B403130046 Ack receipt of undated itr received on B40126 informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 97900400/83-02 POTAPOVS.U Vendor Program Branch B4/02/16 GUILBERT.D E Babcock & Wilcox Co 1p 22615 247
- ---B40313005B Responds to NRC B31117 & 1223 ltrs re nonconformance noted in GA Program Insp Rept 99900400/83-02 Corrective actions STALUM computer program users manual updated & B&W Calculation Document 32-4578-00 will be revised CUILBERT, D E Babcock & Wilcox Co 84/01/26 POTAPOVS, U Vendor Program Branch App 22615 248
- ---B40313006B Forwards correct encis to B31117 transmittal ltr.consisting of QA Program Insp Rept 97900400/83-02 on B31004-07 & notice of nonconformance W/o encis POTAPOVS, U Region 4, Office of Director B3/12/23 QUILBERT, D E Babcock & Wilcox Co ip 22615 254
- --8403130076 Advises that NRC 831117 ltr forwarded GA program insp rept of another company Original ltr & rept enci. KOB18A,R E Babcock & Wilcox Co 83/11/28 POTAPOVS.U Region 4. Office of Director 1p 22615 255
- ---B403130087 Forwards GA Program Insp Rept 79700400/B3-02 on B31004-07 & notice of nonconformance. W/o correct encls
 POTAPOVS, U Region 4, Defice of Director B3/11/17
 OUILBERT, D E. Babcock & Wilcax Co 2pp 22615 236
- 8403130055 Ack receipt of 840201 ltr informing NRC of steps taken to correct nonconformances noted in GA Program Insp Rept 99900403/83-04 POTAPDVB, U. Vendor Program Branch 84/02/07. BRUGGEMAN, W H General Electric Co ip 22615 216
- --8403130064 Responds to NRC B40109 ltr re nonconformances noted in GA Program Insp Rept 99700403/83-04 Corrective actions design change documentation initiated, database updated & audit initiated to preclude recurrence BDML, L 8 General Ejectric Co 84/02/01 POTAPOVS, U Vendor Program Branch, 2pp. 22615 217.

- 8403130169 Responds to NRC 831206 ltr re nonconformance noted in GA Program Insp Rept 99900224/83-02 Corrective actions Instruction 1766-03-01 re contact for unknown customers revised Related info enci HOME: H Bailey Controls Co (subs of Babcock & Wilcox Co) 84/02/29 POTAPOVS, U Vendor Program Branch 31pp 22608 116
- B403130244 Responds to NRC B31223 ltr re nanconformance & violation noted in GA Program Insp Rept 99900539/B3-01 Corrective actions procedures for evaluating deviations reviewed & Section 206 of Enorgy Reorganization Act posted ALLENR D MATSCO (subs of Multi-Amp Corporation) B4/01/10 POTAPOVS, U Region 4. Office of Director 3pp 22617 273
- B403130268 Forwards GA Program Insp Rept 99900616/84-01 on B40116-18 No noncompilance noted PCTAPUS.U Vendor Program Branch 84/02/17 GREEN.M American Society of Mechanical Engineers 2pp 22604 350
- --B403130432 QA Program Insp Rept 99900616/B4-01 on 840116-18 No noncompliance noted Major areas inspected program survey, manual review & acceptance criteria, program implementation & certificate of authorization status SUTTON, J W., HALE, C J Vendor Program Branch 84/02/17 5pp 22604 352
- 8403130274 Forwards GA Program Insp Rept 97700522/84-01 on 840114-19 & notice of nonconformance POTAFOVS, U Vendor Program Branch 84/02/08 STRATTON, C D Bechtel Corp 2pp 22417 147
- --8403130281 Notice of nonconformance from insp on 840116-19 * Vendor Program Branch 84/02/08 2pp 22617 169
- --B403i3029i QA Program Insp Rept 99900522/84-01 on 840i16-i9
 Noncompliance noted faiture to include preaudit & post-audit conference w/project audit & incorporate all design changes into design documents by required due date
 COSTILLO, J.R., NADSEN, Q. Vendor Program Branch 84/02/07 25pp
 22617 171
- 8403130284 Responds to NRC 840208 ltr re nonconformance noted in GA Program Insp Rept 979700222/8:-01 Corrective actions senior person designated in each engineering discipline group to be responsible to project engineer for document followup STATION.C D Bechtel Corp 84/03/01 POTAPOVS,U Vendor Program Branch App 22614 140
- 8403130309 Forwards OA Program Insp Rept 99900616/84-02 on 840123-25 No moncompliance noted POTAPOUS.U Vendor Program Branch 84/02/16 OREEN, M American Society of Mechanical Engineers 2pp 22614 132
- --B403i30325 QA Program Insp Rept 999006i6/84-02 on 840i23-25 No noncompliance noted Major areas inspected program survey, manual review & acceptance criteria.program implementation & certificate of authorization status GLLER.R E . HALE.C J Vendor Program Dranch B4/02/16 4ρρ
- 8403130314 Responds to NRC 840117 ltr re nonconformances noted in QA Program Insp Repts 97900334/83-02 & 97900334/83-03 Corrective actions QA manual & assembly route sheet revised & training class for inspectors will be held BOYER.R E Transamerica Delaval, Inc 84/03/02 POTAPDUS, U Vendor Program Branch 18pp 22608 063
- 8403130317 Atk receipt of 840104 & 0214 ltrs informing NRC of steps taken to correct monconformance noted in GA Program Insp Rept 99900255/83-01 POTAPOVS.U Vendor Program Branch 84/03/05 HADNAOY,P A Pacific Scientific ip 22614 120
- --B403130329 Ack receipt of B40104 ltr in response to GA Program Insp Rept 99900255/83-01 Addl info requested re manner by which suppliers of non-ABME Code items qualified & approved & GA manual revised to exempt non-ASME vendors POTAPOVB, U Vendor Program Branch B4/01/26 HADNAGY, P A Pacific Scientific ip 22614 121
- --8403i3033B Responds to NRC B3i205 ltr re nonconformance noted in GA Program Insp Rept 99700255/83-01 Corrective actions calibratechnician advised to exercise greater care in maintaining certifications
 THOMBEN, E.R. Pacific Scientific 6000-98-43-84 84/01/04 POTAPOVS, U. Region 4, Office of Director 4pp 22614 122
- 8403130407 Forwards GA Program Insp Rept 99900400/83-02 on 831004-07 & notice of nonconformance POTAPDVS.U Region 4, Office of Director 83/11/17 GUILDERT.D E Babcock & Wilcox Co 2pp 22608 276

- ~-8403|30414 Notice of nonconformance from insp on 831004-07 * Region 4, Office of Director 83/11/17. 2pp 22608 278
- --8403130425 GA Program Insp Rept 9990400/83-02 on 831004-07 Noncompliance noted full certified Version 17 O of STALUM computer program did not have controlled grogram manual & failure to identify incorrect values in stiffness matrix BRICKLEY,R H , HALE.C J Region 4, Office of Director 83/11/17 13pp 22408 280
- 8403130441 Forwards QA Program Insp Rept 79700530/84-01 on 840123-26 & notice of honconformance POTAPOVS,U Vendor Program Branch 84/02/17 SHULMAN,M Cygna Energy Services 2pp 22614 051
- --8403130444 Notice of nonconformance from into on 840123-26 * Vendor Program Branch 84/02/17 ip 22614 053
- ---8403130460 GA Program lnsp Rept 99900330/84-01 on 840123-24
 Nonconformance noted quality std operating procedures in GA
 dept procedures manual did not indicate effective date &
 four procedures did not contain preparer signature or date
 BRICKLEY,R H , HALE,C J Vendor Program Branch 84/02/17 10pg
 22244 054
- 8403160119 Forwards vendor insp repts identifying concerns based on Vendor Program Branch insps of vendor activities Significance of findings re quality & acceptability of product or svc provided by venfor should be evaluated 0A0LIANDB.J E Region 4. Diffice of Director 84/03/13 K0ESTER.O L Kansas Oss & Electric Co 2pp 22655 116 24X Fiche, 50-482, 84/03/13, 8403160119
- B403i60235 Forwards vendor insp repts identifying concerns found by Vendor Progrem Branch during insp of vendor activities Evaluation of significance of findings re quality & acceptability of product or syc requested JOHNSON,E H. Region 4, Office of Director B4/03/13 CAHILL,W S Oulf States Utilities Co. 2pp 22661 049 24X Fiche 50-458,84/03/13,8403160235
- B403160242 Forwards vendor insp repts Identifying concerns found by Vendor Progrem Dranch during insp of vendor activities Eveluation of findings re quality & acceptability of groduct or svc by vendors requested JOHNSON.E H Region 4, Office of Director 84/03/13 LEDDICK.R B Louisians Power & Light Co 3ps 22661 026 24% Fiche 50-382,84/03/13,8403160242
- B403190041 Confirms QA program insp et Alexandria.LA plant on B40326-30.per B40302 telcon POTAPQVB.U Region 4. Office of Director B4/03/09. SCHAUS.R L. Dresser Industries, Inc. 1p 22666 245
- 8403190046 Confirms GA program insp et Apex,NC leb on 840319-23.per 840301 telcon POTAPDVS.V Region 4, Office of Director, 84/03/08 YOW.J.R Corporate Consulting & Development Co. Ltd 1p 22666 249
- 8403190070 Ack receipt of B40224 ltr informing NRC of steps taken to correct nonconformance noted in GA Progrem Insp Rept 9900394/83-02 PDTAPGVS,U Region 4, Office of Director 84/03/07. SCHAFER,J C Metal Reliows Corp 1p 22666:134
- B403190078 Ack receipt of 840301 ltr Informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 9900522/84-01 POTAPUS.U Region 4, Office of Director 84/03/08 STATTON, C. D Bechtel Corp 1p 22669 361
- 8403190112 Forwards Vandor Program Insp Rept 99900100/84-01 on 840130-0203 Insp rept closes out tack welding of motor shaft deficiency POTAPOUS U Region 4, Office of Director 84/03/15, LEWIS, R C. Division of Project & Resident Programs ip R2669 218

b NRC 840202 ltr re nonconformance noted in GA '900273/83-02 Corrective actions.1983 div te.all audit repts on file in GA ofc & onducted --- vetric Corp 84/03/02, PDTAPDV8,U in 22666,315,

Informing NRC of steps taken to noted in GA Program Insp of corrective actions

lrector 84/03/08 VIGGIANG, V A.

- E403190183 Forwards QA Program Insp Rept 99900100/84-01 to B40130-0203 & notice of nonconformance POTAPOVS.U Region 4. Office of Director B4/03/02 MIGNOGNA.T. Limitorque Corp 3pp 22670 323
- ~-B403190183 Notice of nonconformence from insp on 840130-0203 * Region 4. Office of Director 84/03/02, 2pp. 22670 326.
- --8403190190 0A Program Insp Rept 99700100/84-01 on 840130-0203.
 Nunconformance noted:corrective action in training non-QC
 personnel inadequate
 MCNEILL,W M. HALE,C J. Region 4. Office of Director 84/03/01.
 26p 22670 328.
- 8403170203 Confirms 840307 telcon request to withhold info in NRC 840229 1tr & GA Progrem Insp Rept 997000840/83-01 FIEDLER, D C Cardinel Industrial Products Corp 84/03/12. POTAFOVS, U Region 4. Office of Director 1p 22671 131
- 8403170206 Discusses closeout of AITS F02700410 re inadequate GA progrem at Limitorque Corp. addressed in encl Vendor Program Branch Insp Rept 97900100/98-01 on B40130-0203 TVA audit conclusions valid Limitorque GA program inadequate. W/s encl PDTAPDVB, V Region 4. Office of Director 84/03/14 LEWIS,R.C. Division of Project & Resident Programs, PARTLOW,J.Q. Division of GA, Safeguerds & Inspection Programs (Post 830103). 2pp 22670:36
- B40B190209 Forwerds GA Program Insp Rept 99900231/84-01 on 840116-20 & notice of nonconformance PDTAPOVB, V Region 4. Defice of Director. 84/02/23 VIGGIANO, V. A DXonite Co 2pp 22670 297.
- --8403190210 Notice of nonconformance from insp on 840116-20. * Region 4, Office of Director 84/02/23 ip. 22670.299.
- --8403190214 GA Program Insp Rept 97900231/84-01 on 840116-20
 Noncompliance noted qualification test results did not
 include lack of 10 s rise time during accident environ
 simulation testing
 HUBBARD,0 T . PHILLIPS.H S Region 4, Office of Director
 84/02/23 14pp. 22670.300
- 8403170218 Forwards GA Program Insp Rept 99900904/83-01 on 831213-16. No noncomplience noted. POTAPUS, U Region 4. Office of Director 84/02/24 MIGNOGNA.T Limitorque Corp 2pp 22670 248
- --8403190221 QA Progrem Insp Rept 97900904/83-01 on 831213-16. No noncomplience noted Hajor arees inspected environ qualification test plan & action on previously identified findings re nuclear qualification facility QA menual JOHNBON, A R. PHILLIPS: H 8 Region 4. Office of Director 84/02/23. 15pp 22670 250
- B403190254 Confirms GA program insps et Chalfont, Horsham & Spring House, PA pients on B40416-19, per B40309 telcon POTAPOVS. U. Region 4, Office of Director B4/03/14 DUVALL, D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd.), 1p 22671 298
- 8403190328 Forwards GA Program Insp Rept 99900781/84-01 on 840116-20 & notices of violation & nonconformancs POTAPOVS.U Region 4, Office of Director. 84/02/24 JANDL, J. C. Lone Star Screw Co 3pp 22675'007
- --8403190330 Notice of violation from insp on 840116-20. * Region 4, Office of Director. 84/02/24. 1p. 22675-010.
- ---8403190333 Notice of nonconformance from Insp on 840116-20 * Region 4, Office of Director 84/02/24 5pp. 22675.011.
- --B403190340 QA Program Insp Rept 99900781/84-01 on 840116-20 Violations & noncompliance noted, lack of appropriate procedures to evaluate deviations & review of records revealed eye examrecord missing for 1981 for Level II examiner. CONMAY, J T , BARNES, I, Region 4. Office of Director, B4/02/24, 10pp. 22675 016.
- 8403190329 Forwards Vendor Program Insp Repts 99900231/83-01 & 99900231/84-01 on 831115-17 & 840116-20 respectively, closing out Part 21 rept re seepage of 011 from Okonite cables.

 POTAPOVS, V Region 4, Office of Director. 84/03/15, NORELIUS, C E Division of Project & Resident Programs. 1p. 22675.026. 24X Fiche; 50-461.84/03/15.8403190329.
- B403190337 Confirms GA program insp at Los Angeles, CA plant on G40326-30, per B40307 telcon.
 POTAPOVS, U. Region 4, Office of Director, B4/03/09, PATTERSON, R. L. Bechtel Corp. 1p. 22675: 029

- 8403190338 Discusses insp on 840130-0203 re failure of Limitorque spring compensator housings Resulte of insp documented in encl Vendor Program Branch Insp Rept 97900100/84-01
 Westinghouse ovaluation continuing W/o encl
 PdTAPDVS,U Region 4. Office of Director ViT8 84-031 84/03/15
 LEWIS,R C Division of Project & Resident Programs 1p 22673 285
- 8403190342 Confirms GA program insp at Salem, MA plant on 840402-06, per 840301 telcon POTAPDUS, U Region 4, Office of Director 84/03/15 COVEY, J Atwood & Morrill Co , Inc (subs of Foster Wheeler Corp) 1p
- 8403i90364 Discusses inep on 840i30-0203 re Limitorque cracked/broken limit switch rotors Regults of inep documented in encl Vendor Program Branch Insp Rept 99900100/84-01 Evaluation of condition continuing W/o encl.
 PDTAFDV8.U Region 4, Office of Director VITS 83-184 84/03/15 NORELIUS.C E Divielon of Project & Resident Programs ip
- 8403190380 Ack receipt of 840214 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 97900230/63-01 Implementation of corrective actions will be reviewed during future lnsp POTAPOVS.U Region 4, Office of Director 84/03/07 CARDELLO,F S Anaconda Co (eubs of Atlantic-Richfield Co) ip 22674 220
- B403200072 Ack receipt of B31219 & 840229 ltrs Informing NRC of etepe taken to correct nonconformance noted in GA Program Insp. Rept 99900224/B3-02 POTAPOVB, U. Region 4. Office of Director 84/03/15 KEYEB, M.A. Bailey Controls Co (eubs of Babcock & Wilcox Go.) ip 22685 03i
- --8403200076 Responds to NRC 831206 ltr re honconformance noted in GA Program Insp Rept 99900224/83-02 Requests 30-day extension of response time due to personnel on vacation & facility closed 831223-840102.

 HOME, H Bailey Controls Co (subs of Babcock & Milcox Co) 83/12/19 POTAPOVS, U Region 4, Office of Director 1p 22685 032
- 8403200138 Ack receipt of 831017,1108 & 840228 ltrs informing NRC of steps taken to correct violations a nonconformance noted in OA Program Insp Rept 99700702/83-01 Implementation of corrective actions will be reviewed during future insp POTAPOVS.U. Region 4, Office of Director 84/03/07 JONES.W F. Morrison-Knudsen Co., Inc. 1p. 22697 075.
- ---8403200142 Ack receipt of 831017 & 1108 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Inep Rept 99900702/83-01 Add1 info re eelsmic capability of valve requested within 25 days
 POTAPOVE, U Region 4, Office of Director 84/01/24 JONES, W F. Morrison-Knudsen Co , Inc. ip 22697 076
- --8403200150 Responde to NRC 830930 ltr re violations & nonconformance noted in GA Program Insp Rept 99900702/83-01 Corrective actions personnel involved wydata acquietition & Part 21 repts instructed on need for describing violations JONES,F Morrison-Knudsen Cg., Inc. 83/10/17. Region 4, Office of Director dpp 22697 077.
- --8403200157 Forwarde Morrison-Knudsen Co.Inc 831017 response to OA Program Insp Rapt 99900702/83-01.
 STAUBER.R. M Morrison-Knudsen Go . Inc 83/11/08 POTAPOVS.U Region 4. Office of Director ip 22697 083
- B403260052 Confirms QA program insp at Tempe, AZ plant on 840409-13, per B40306 telcon, POTAPOVB.U. Region 4, Office of Director B4/03/19 SAYLOR, K Tobar, Inc 1p. 22748, 362.
- 8403270050 Ack receipt of 840111 ltr informing NRC of corrections to GA Program Insp Rept 99900932/83~01
 POTAPOVS.U. Region 4, Office of Director 84/03/21 SEMMLER,R. H
 Eaton Corp. 1p 22769:309
- --8403270054 Responds to NRC 840103 ltr rs QA Program Insp Rept 99900932/83-01. Errors found in rept listed SEMMLER,R.W. Eaton Corp 84/01/11. POTAPOVS.U Region 4, Office of Director. 2pp. 22769:310
- 8403270087 Responds to NRC 840223 ltr re nonconformance noted in OA Program Insp Rept 99700231/84-01. Corrective actions nuclear qualification repts revised re temp-pressure profile & teet vessel modified.

 BRODEUR, R. I. Okonita Co 84/03/14 POTAPOVS, U Region 4, Office of Director. ip 22766; 247.

- 8403270072 Ack rereipt of B40202 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 797900537/83-03
 PDTAPOVS, U Region 4, Office of Director 84/03/21 CARDN, A E Anthor/Darling Valve Co (subs of Anchor/Darling Industries, Inc.) 1p 22766 333
- --B403270097 Responds to NRC B40112 ltr re nonconformance noted in GA Program Insp Rept 99900033/83-03 Corrective actions training session conducted on importance of checking radii for baciface on valve bonnet flanges
 KNIFBER, G W Anchor/Darling Valve Co (subs of Anchor/Darling Industries, Inc.) B4/02/02 POTAPOVS, U Region 4, Office of Director 2pp 22766 334
- B403270108 Responds to B40307 request for additinfore measures taken or to be taken to preciude recurrence of nonconformance w/ASME Code requirements identified in GA Program Insp Rept 99900845/83-01 Titeflex Corp nonconformance regt encl LALIKOS.J M Titeflex Corp 84/03/12 PDTAPOVB.U Region 4, Office of Director 3pp 22774 029
- 8403270115 Responds to NRC 840217 itr re nonconformance identified in OA Program Insp Rept 99900330/B4-01 Corrective actions all quality std operating procedures reviewed & corrections issued

 SHULMAN, M N Cygna Energy Services 84/03/12 POTAPOVS, U Region 4. Office of Director 3pp 22774 052
- B403270142 Confirms QA program insp at Ban Diego, CA plant on B40402-06, per B40319 teltun PQTAPQVS.V Region 4. Office of Director B4/03/22 COLANDRA, T R QA lechnologies. Inc / General Atomic Co ip 22769 145
- 8403270148 Responds to GA Program Insp Rept 99900371/83-01 & 840307
 Itr Bolt lists are not drawings & do not require checking
 Bolt lists prepared as convenience for preparing summaries
 in procurement & for convenience of erector
 CDRRINGR J Bristol Steel & Iron Works, Inc 84/03/14 POTAPOVS, U
 Region 4. Office of Director 2pp 22769 146
- B40327016B Confirms GA program insp at Richland.WA plant on 840403-05, pur B40320 telcon Insp concerns implementation of GA program re control of computer codes SLOTRAX & PTMPMR2 POTAPOUS.U Region 4. Office of Director 84/03/22 VOLMER, C J Exxon Nuclear Co , Inc. (subs of Exxon Corp.) 1p 22772 181
- 8403270174 Confirms GA program insp survey at administrative of of Factory Mutual Engineering Assoc on 840416-20, per 840319 telcon NRC representative will be JM Button POTAPOUS, U Region 4. Office of Director 84/03/21 WHELAN, M Factory Mutual Engineering Corp Ip 22771 308
- 8403270178 Forwards QA Program Insp Rept 99900616/84-03 on 840213-15 PDTAPOVS, U Region 4: DPFice of Director 84/03/07 GREEN.M American Society of Mechanical Engineers 2pp 22772 139
- --B403270184 GA Program Insp Rept 99900616/84-03 on 840213-15 Major areas inspected. ASME audit activities during Newport News Bhipbuilding & Dry Dock Co GA program audit OLLER, R. E. HALE, C J. Region 4. Office of Director 84/03/06 3pp. 22772 141
- B403270222 Responds to NRC telcon request re nonconformance noted in QA Program Insp Rept 99700732/83-02 Corrective actions items reinspected & individually marked Preliminary stress analysis rept returned for correction of minor errors OIESLER, J V Robert Shaw Controls Co 84/03/13 POTAPOVS, U Region 4. Office of Director ip 22772 086
- 8403270228 Forwards QA Program Insp Rept 99900884/83-01 on 831205-09 & notice of nonconformance POTAFDVS.U. Region 4. Office of Director 84/03/02 BLANKLEY,W Ametek,Inc. 2pp 22772-045
- --8403270234 Notice of nonconformance from insp on 831205-09 * Region 4. Office of Director 84/03/02 5pp 22772 067
- --8403270241 GA Program Insp Rept 97900884/83-01 on 831205-09
 Noncompliance noted ABME Code requirements not certified on
 matl manufacturer certified matl test repts to vendor
 CONMAY.J T , HAMILTON.J . BARNES, I Region 4, Office of Director
 84/02/08 9pp 22772.072

REGGD REGULATORY GUIDES

- 83:2070358 Notification of CRCR Meeting 5: on 83:23 to review exemption from CRCR review of Unresolved Safety Issue A-1 "Mater Hanmer" & proposed rev to Reg Guide 1 28, "QA Program Requirements (Design & Const)"
 STELLGY Committee to Review Generic Requirements B3/1:/10 MATTSON,R J Office of Nuclear Reactor Regulation, Director JORDAN,E L Director's Office, Office, of Inspection and Enforcement CUMNINGHAM,R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22681 352
- 8403010347 Forwards status & justification for mine listed NUREO-0737 & Rep Guide i 97 items.per 840222 request Analysis of safety parameter display sys will be submitted by 840430 MURILL.H 0 General Public Utilities GPU Service Corp 5211-84-2045 84/02/27 EISEMMUT.D G Division of Licensing 21pp 22433 018 24X Fiche 50-289,84/02/27,8403010347
- 8403020225 Reg Guide 5 53.Rev 1.Tast 80 049-4, "Gualification.Calibr & Error Estimation Methods for Nondestructive Assay "

 # Office of Nuclear Regulatory Research, Director 84/02/29 ilpp 22491 008
- 8403020329 Responds to request for schedule for completion of Reg Quide i 97 requirements Exceptions to Blill3 ltr re equipment replacement will be addressed in May 1984, in response to Generic Ltr 82-33 CURTIS.N W Pennsylvania Power & Light Co PLA-2081 84/02/29 SCHMENCER.A Licensing Branch 2 ip 22439 207 24X Fiche 50-387,84/02/29,8403020329
- 8403060354 Forwards descriptions of Reg Guide 1.97 requirements & schedule for implementation of emergency response capability.ger NUREG-0737.Suppl i PILANT.JM Nebraska Public Power District NLS8400073 84/03/01 EISENHUT.D & Division of Licensing 19pp 22515 311 24X Fiche 50-278.84/03/01.8403040354
- 8403060494 Reg Guide 5 23.Rev 1.Tasi 59 045-4. "In Situ Assay of Pu Residual Holdup " * Office of Nuclear Regulatory Research, Director 84/02/29 18pp 20552 187
- --8403060499 Value/impact statement of Reg Guide 5 23,Rev i, Task SØ 045-4, "In Situ Assay of Pu Residual Holdup " * Office of Nuclear Regulatory Research, Director 84/02/29 ip 20850 208
- 8403060378 Forwards responses to NRC 840106 questions re FEAR rays, including info re training staff qualifications, 64 staff qualifications, fire protection training & conformance to Reg Guide B 13 Proposed rays to FSAR also encl BOOKER, J E Gulf States Utilities CO REO-17, 082 B4/02/17 DENIGN, HR Office of Nurlear Reactor Regulation, Director 42pp 22556 200 24% Fich# 50-458,84/02/17,9403080378
- 8403150070 Responds to 831230 requests for response to items identified in EG&G technical evaluation rept on conformance to Reg Guide I 97 & comments on any assumptions that surpass util 811113 submittal CURTIS.N W Permsylvania Power & Light Co PLA-2099 84/03/13 SCHWENCER.A Licensing Branch 2 Bpp 22443 183 24X Fichs 50-387,84/03/13,8403150070
- B4D3170146 Notifies of CRGR Meeting 47 on B30923 in Bethesda, MD to discuss proposed exemptions to requisitions in implementation of Multi-Plant Action D-10 (Unresolved Safety Issue A-2) & Rev P to Reg Guide 1 103
 STELLD.V Committee to Review Generic Requirements B3/09/15
 MATTSON.R J Office of Nuclear Reactor Regulation, Director JORDEAN, E.L Director's Office of Finspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22666 339
- 8403190176 Notifies of CRGR Meeting 48 on 831020 in Bethesda, MD to discuss exemption of Category 2 personnel from 10CFR30 55a, "Codet & Stds," proposed rulemaking & proposed rev to Reg Ouide 1 i05
 STELLO, V Regional Operations & Generic Requirements 83/10/14
 NATISDN:R J Office of Nuclear Reactor Regulation, Director JDRDAN; E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM, RE Office of Nuclear Haterial Safety & Safeguards, Director 2pp 22471 i63

- 8403190260 Notifies of CRGR Heeting 54 on 840118 in Bethesda, MD to discuss Rev I to Reg Guide i 87. "Environ Qualification of Electric Equipment Important to Safety for Nuclear Power Plants "
 STELLO. V Regional Operations & Generic Requirements IEB-79-018.
 83/12/27 MATTSON.R J Office of Nuclear Reactor Regulation, Director JORDAN.E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director ip 22672 058
- 8403190372 Notifies of CRGR Meeting 53 on 840111 in Bethesda, MD to discuss revs to 10CFR51 & 73 & Reg Guide i 105 re instrument setpoints for safety-related sys STELLG, V Regional Operations & Generic Requirements 83/12/19 MATTSON, R J Office of Nuclear Reactor Regulation, Director JURDAN, E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22675 218
- B40322013B Forwards revised schedule for supplying info re emergency response capabilities requested by Generic Ltr 82-33, per 840223 telcon Reg Guide i 97 rept will be completed by 85022B RREY.H L Public Service Co of Colorado OL-82-33 84/03/09 COLLINS.J T Region 4. Office of Director 3pp 22714 285. 24X Fiche 50-267,84/03/09.8403220138
- 8403280024 Forwards MA McDuffie 840216 response to 830119 request for addi antitrust info to continue review of OL application.per Reg Guide 9 3 Recipient imadvertently omitted from list ZIMMERMAN, S.R. Carolina Power & Light Co. NLB-84-128 84/03/19 VOGLER, B. NRC No Detailed Affiliation Given ip 22777:087 24X Fiche 50-400,84/03/19.8403280024
- 840328024: Questions requirements of Reg Ovide 1.97 to insure instrumentation to follow course of accident including severe accidents Qualification requirements do not include anything beyond DBA CATTON. I California. Univ of, Los Angeles, CA CATTON, I. ACRB Advisory Committee on Reactor Safeguards 84/02/17 CAPUCCI, A J ACRB Advisory Committee on Reactor Safeguards 1p 22808 209
- B403280308 Summary of ACRS Subcommittee on Human Factors 831130 meeting w/Hestinghouse, BNL. Interlock Group & DOE in Hashington, DC re proposed revs to Reg Guides 1, 149, 1 8, 1 134 & 1 114 & proposed mod to 10CFR30, App A A ACRS Advisory Committee on Reactor Safeguards 84/02/24 ACRS Advisory Committee on Reactor Safeguards 33pp 22808:007
- 8403270002 Final response to FOIA request for four categories of documents, tests, studies & analyses referencing or pertaining to NUREQ-0103, "STS for B&H PHR" App A documents encl FELTON. J M Division of Rules and Records 84/01/13 MADDEN. T J. Kaye. Scholer, Fierman, Hays & Handler 6pp 22816 127. 24X Fiche 50-000.84/01/13,8403270002
- --8403270054 Notice of issuance & availability of six reg guides, including Reg Ouides 1 43 re stainless steel weld cladding of low alloy steel components & 1 44 re control & use of sensitized stainless steel RODERS.L Atomic Energy Commission Directorate of Regulatory Standards 73/05/18 5pp 22816 314
- --8403290009 Discusses Reg Guide 1 45 re RCFB leakage detection sys & rept on leakage observed at plant in Germany.
 PORSE, L. Atomic Energy Commission Directorate of Regulatory Standards 73/05/17 MURLEY, T. E. Atomic Energy Commission. 1p. 22817 009
- --8403290034 Discusses Reg Guide 1 45. ISA draft Std 867 03 & ANSI draft Std N 41 21 Suggested items clarifying reg guide listed MCGUEEN, M N Affiliation Not Assigned 79/07/23 Atomic Energy Commission - Directorate of Regulatory Standards 15pp 32817 039
- --B403290036 Discusses ray to Reg Guide 1 45 re RCPB leakage detection sys PORBE.L NRC - No Detailed Affiliation Given 79/02/26. ANDERSON, H. F. NRC - No Detailed Affiliation Given 499. 22817:054
- --B403290040 Discusses Rev 1 to Reg Quide 1 45. "RCPB Leak Detection Bys " Decision to revise reg guide not ust made. PDRSG.L Atomic Energy Commission - Directorate of Regulatory Standards 74/L0/07 Atomic Energy Commission - Directorate of Regulatory Standards 1p 22816 302
- --8403290055 Comments on Reg Quide 1 45,RCPB leakage detection sys Editorial changes suggested KEELLEY.0 S. Consumers Power Co. KEEL 115-73 73/07/18. Atomic Energy Commission ip 22818 237

1

NONDOCKETED ITEMS

---8403270039 Comments on Reg Ouide 1 45, "RCPB Leakage Detection Sys "
Calibr of leakage detection sys during shutdown sufficient
Related info encl
BALVATORI,R Westinghouse Electric Corp NB-RS-112 73/12/12
MUNTZINO,L M Atomic Energy Commission - Directorate of Regulatory
Standards 23pp 22818 238

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

- 8403050227 "Radionuclide Release Under Specific LWR Accident Conditions," Vol III, "Mark III Design " GIESEKE.J A., CYBULSKIS.P. P. DENNING,R B. Batteile Memorial Institute, Columbus Laboratories 84/02/29 Office of Nuclear Regulatory Research, Director 106pp 22528-007
- 8403050230 "Radionuclide Release Under Specific LWR Accident Conditions," Vol V. "PWR-Large, Dry Containment (Surry Recalculations)"

 OLESEKE, J.A., CYBULSKIS, P., DENNINO, R.S. Battelle Memorial Institute, Columbus Laboratories 84/01/12 Office of Nuclear Regulatory Research, Director 212pp 22502 001 24X Fiche 50-280, 84/01/12, 8403050230
- 8403050242 "Radionuclide Release Under Specific LWR Accident Conditions," Vol II, "BWR.Mark 1 Design " GIESEKE.J A., CYBULSKIB.F. DENNING.R 8 Battelle Memorial Institute, Columbus Laboratories. 84/02/29 Office of Nuclear Regulatory Research, Director 222pp 22503 079
- 8403120255 "Generic Btudy of Recycle of Contaminated Matis," monthly progress rept for Jan 1984 O'DONNELL, F.R. Oak Ridge National Laboratory FIN B-0824. NRC-40-10-01-05 84/02/15 SOUBERG, D.E. Transportation & Materials Risk Branch. 4pp. 22415 338
- B403120257 "Severe Accident Research Fragram," quarterly rept for Feb 1984. # Bettelle Memorial Institute, Columbus Laboratories B4/02/29 NRC - No Detailed Affiliation Given 51pp 22619 156
- 8403130175 RIL-137
 Research Info Ltr 139 provides appraisal of U dioxide fuel oxidation phenomena & potential impacts on transportation of irradiated power reactor fuel assemblies Potential for occupational exposures during unloading major impact MINGOUE, R. B. Office of Nuclear Regulatory Research, Director 84/03/05, DAVIB, J. O. Office of Nuclear Material Safety & Safeguards, Director. 31pp. 22646 3ii
- B403270329 "FRAP-T6 Calculations for Intl Btd Program i4 "
 WAGDNER, B. R., LAATS, E. T. EGRO, Inc. FIN A-6046 EGG-BAAM-6499
 B3/12/31 NRC No Detailed Affiliation Given 30pp. 22788 333
- 8403300120 Procedure "Chemtron Users Manual " MILLER, C. W. Lawrence Berkeley Laboratory FIN 8-3040 LBL-16152 83/03/31 Division of Health, Siting & Waste Management 150pp 22822: 294

REVIEW ORP NRC RESEARCH REVIEW GROUPS

- 831207035B Notification of CROR Meeting 51 on 831123 to review exemption from CROR review of Unresolved Bafety Issue Ari "Water Hammer" & proposed rev to Reg Quide 1 28, "GA Program Requirements (Dasign & Gonst)"

 BTELLO, V Committee to Review Generic Requirements 83/11/10 MATISON.R.J Office of Nuclear Reactor Regulation, Director JORDAN.E.L. Director's Office, Diffice of Inspection and Enforcement CUNNINONAM,R E Diffice of Nuclear Material Bafety & Bafeguards, Director 2pp 22681 352
- B403010109 Forwards revised CROR charter, Rev reflects Commission directions contained in 840106 memo DIRCKB, M. J. Office of the Executive Director for Operations 84/02/24. PALLADING, GILINSKY, ROBERTS Commissioners 16pp 22436:063
- B403010329 Forwards Rev 1 to CROR charter 8td B40131.

 DIRCKB.H.J. Office of the Executive Director for Operations
 B4/02/24. DENTON,H R, DAVIB,J G, DEYDUNG,R,C NRC No Detailed
 Affiliation Given. 3pp 22432-056
- --8403010334 Rev 1 of CROR charter # Committee to Review Generic Requirements 84/01/06, 14pp 22432:039.

- 8403040323 Notification of CROR Meeting 58 on 840315 to discuss proposed NURGO-0801. "Evaluation Criteria for Detailed Control Room Design Review " Requests of directors limit attendance of staff at CROR meetings STELLO, V Committee to Review Generic Requirements 84/03/02 MATTSON, R J Office of Nuclear Reactor Regulation, Director JORDAN, E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 1p 22513 335
- 8403170003 Notifies of CRGR Meeting 45 on 830817 to discuss results of NRR study of electromagnetic pulse & proposed exemptions from regulations in implementation of Multi-Plant Action D-10 (Unresolved Issue A-2) STELLO.V Committee to Review Generic Requirements 83/08/04 MATTSON.R J Division of Systems Integration (post 811003) JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) CUNNINGHAM.R E Office of Nuclear Material Safety & Safeguards. Director 3pp 22664 347
- BA03170005 Notifies of CRGR Meeting 47 on B31024 in Bethesda, MD to discuss proposed requirements for reinsp of BMR piping & repair of cracked piping STELLD, V Committee to Review Generic Requirements B3/10/19 MATTSON, R J Office of Nuclear Hoactor Regulation, Director JORDAN, E L Director's Office, Office of Inspection and Enforcement CUNNINOHAM, R E. Office of Nuclear Material Bafety & Safeguards, Director 2pp 22664 350
- 8403190008 Submits mod to agenda for CROR Meeting 45 on 830817 in Bithesda. MD to discuss NUREG-0737. Suppl 1 control room design review & NRR study of electromagnetic pulse BTELLO, V Committee to Review Generic Requirements 83/08/15 MATTSON.R J Division of Systems Integration (post 8:1005) JORDAN, E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22644 361.
- 8403170009 Notifies of CRGR Meeting 58 on 840315 to discuss proposed NUREG-0801, "Evaluation Criteria for Detailed Control Room Design Review "
 STELLD, V Committee to Review Generic Requirements 84/03/02 MATTSDN, R J Division of Systems Integration (post 811005) JORDAN, E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R C Office of Nuclear Material Safety & Bafeguards, Director 1p. 22665:352
- 8403190012 Notifies that CROR Meeting 52 on 831209 in Dethesda, MD rescheduled for 831207 Mod to agenda discussed STELLD, V Committee to Review Generic Requirements 83/11/25 MATTSON, R J Office of Nuclear Reactor Regulation, Director JORDAN, E L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R Office of Nuclear Material Safety & Safeguards, Director Rpp 22665 335
- 8403170017 Notifies of CRGR Meeting 54 on 840203 to discuss evaluation & conclusions re need for PDRVs for C-E plants BTELLD, V Committee to Review Generic Requirements 84/01/23 MATTSDN, R J Division of Bystems Integration (post 811003) JURDAN, E L, Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director. 1p. 22666 052
- B40319029 Notifies of CROR Meeting 57 on B40213 to discuss proposed NUREO-OBO1, "Evaluation Criteria for Detailed Control Room Design Revise" & NUREO-OB35, "Human Factors Revise Quid+lines for Safrty Parameter Display Sys" BTELLO, V Committee to Revise Generic Requirements 84/02/07 MATTSON, R J Division of Systems Integration (post Bi1005) JORDAN, E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Bafety & Bafeguards, Director 1p. 22665, 362
- B403190031 Notifies of CRGR Mesting 44 on B30802 in Bethesda,MD to discuss NUREG-0978,re behavior of BWR Mark III conteinment & commission paper re integrated safety assessment program BTELLO,V Committee to Review Generic Requirements B3/07/22 MATTBON,R J Division of Bystems Integration (post B11005) JURDAN,E L Director's Office Office of Inspection and Enforcement CUNNINGHAN,R E Division of Fuel Cycle & Material Safety 2pp 22666 113
- B403190037 Notifies of CROR Meeting 43 on B30727 in Bethesda,MD to discuss Unresolved Bafety Issue A-12, "Bteam Generator & Reactor Goolant Pump Support Toughness" & Generic Issue B-36 re diesel generator requirements
 STELLO,V Committee to Review Generic Requirements 83/07/18
 MATTSON,R J. Division of Bystems Integration (post 811005)
 URDAN,E L. Director's Office, Office of Inspection and Enforcement CUNNINGHM:R.E Division of Fuel Cycle & Material Safety 2pg 22266 233

- 840319008: Notifies of CROR Meeting 59 on 840328 in Bethesda, MD to discuss proposed resolution of Unresolved Safety Issue A-44 re station blackbut & Generic Issue B-56 re diesel generator reliability STELLO.V Committee to Review Generic Requirements 84/03/14. MATTSON, R J Office of Nuclear Reactor Regulation, Director JORDAN, E L Director's Office, Office of Inspection and Enforcement CUNNINGHAN, R E Office of Nuclear Material Safety & Safeguards, Director ip 22669 362
- 8403170103 Notifies of CRGR Meeting 60 on B40411 to discuss activities of NRC Piping Review Committee & proposed resolution of Generic Issue A-30. "Adequacy of Bafety-Related DC Power Supply"
 STELLO,V Committee to Review Generic Requirements 84/03/14. MATTSON,R J Office of Nuclear Reactor Regulation, Director JURDAN,E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM,R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22669 310
- 8403170144 Notifies of CRGR Meeting 47 on B30923 in Bethesda.MD to discust proposed exemptions to regulations in implementation of Multi-Piant Action D-10 (Unresolved Safety Issue A-2) & Rev 2 to Reg Guide 1 105
 STELLD.V Committee to Review Generic Requirements B3/09/15
 MATISON.R J Office of Nuclear Reactor Regulation, Director JGRDAN.E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM.R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22666 359
- B403190176 Notifies of CROR Meeting 48 on 831020 in Bethesda.MD to discuss exemption of Category 2 personnel from 10CFR30.55a.
 "Codes & Stds," proposed rulemaking & proposed rev to Reg Guide i 105
 STELLO,V Regional Operations & Generic Requirements 83/10/14
 NATISON,R J. Office of Nuclear Reactor Regulation, Director JORDAN,E L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM.R E. Office of Nuclear Material Safety & Safeguards, Director 2pp 22671 163
- 8403190251 Submits agenda mods for CRGR Maeting 55 on 840125 re proposed IE bulletin on 0E HFA relays & NUREG-0801 on criteria for detailed control room design STELLOV Regional Operations & Generic Requirements 84/01/31 MATTSON,R J Office of Nuclear Reactor Regulation, Director JURDANIE L Director's Office, Office of Inspection and Enforcement CUNNINOHAM,R E Office of Nuclear Material Safety & Safeguards, Director 19 22672 270
- ---8403190256 Notifies of CRGR Meeting 55 on 840125 in Bethesda.MD to discuss draft IE hulletin, "Failure of GE Type HFA Relays in Use in Class IE Safety Sys," NUREO-0801 & NUREO-0835 STELLO.V Regional Operations & Generic Requirements. 84/01/07 MATTOON.R J Office of Nuclear Reactor Regulation, Director JORDAN.E L Director's Office. Office of Inspection and Enforcement CUNNINOHAM.R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22672 271
- 8403190260 Notifies of CRGR Meeting 54 on 840118 in Bethesda,MD to discuss Rev 1 to Reg Guide | 89. "Environ Qualification of Electric Equipment important to Safety for Nuclear Power Plantt"
 Plantt "
 STELLO,V Regional Operations & Generic Requirements | 188-79-018 83/12/27 MATTSON,R J Office of Nuclear Reactor Regulation, Director JORDAN,E L Director's Office, Office of Inspection and Enforcement CUNNINOHAM,R E Office of Nuclear Material Safety & Safeguards,Director | 1p 22672 058
- 8403190266 Forwards proposed rev to 10CFR72, "Licensing Requirements for Storage of Spent Fuel in ISFSI," for review comment & recommendations CAO should participate in review for listed items M/o encl
 SNIEZEK, J H Regional Operations & Generic Requirements 84/01/12
 TRINER, E G Division of Budget & Analysis Ip 22672 225
- 8403190372 Notifies of CROR Meeting 53 on 840111 in Bethesda, MD to discuss revs to 10CFR51 & 73 & Reg Guide I 105 re instrument setpoints for safety-related sys STELLO, V Regional Operations & Generic Requirements 83/12/19 MATTSON, R J Office of Nuclear Reactor Regulation Director JORDAN, E L Director's Office. Diffice of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22675 218

SECY POSITION PAPERS DEFORE THE COMMISSION

8402220050 SECY-84-047
Provides Commission w/draft preliminary document to focus on whether to grant or withhold concurrence in DOE general guidelines for recommendations of sites for nuclear waste repositories
DIRCKS.N.J. Office of the Executive Director for Operations B4/02/09 45pp 22646,183

- 8403010277 Responds to FOIA request for SECY-83-288 to be placed in PDR Forwards SECY-83-288 Document also available in PDR FELTON.J M Division of Rules end Records 83/12/16 PEDRO.J NUS Corp 1p 22447 138
- ---B403010283 Comments on SECY-B3-288 re proposed rule on pressurized thermal shock Proposed rule should address CP applicants in addition to OL applicants & operating reactors Schedule for preparation of plant-specific safety enalyses acceptable ZERBE.J E Office of Policy Evaluations B3/OB/Oi PALLADING, OILINSKY, ROBERTS Commissioners App 22449 222
- BA03010451 SECY-B3-034
 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval. Inc
 DJRCKS, W J Deffice of the Executive Director for Operations
 B4/01/25 4pp 22438 347 24% Fiche 50-000, 84/01/25, 8403010451.
- B40302006B Responds to appeal re denial of FOIA request for SECY-B3-454 Forwards document Info partielly withheld (ref FOIA Examption 5).
 CHILK, S J Office of the Secretary of the Commission 84/02/15 SEEGAL. J Union of Concerned Scientists 2pp 22495.009
- --B403020D94 SECY-B3-454
 Approves release of substantive info in Chairmans logs,
 calendars & notes.per UCS request Info deleted & withheld.
 FITZOERALD, J A Office of the General Counsel B3/11/04 2pp.
- 8403050469 Responds to appeal re denial of FOIA request for SECY-B2-340 Document placed in PDR FELTON.J M Division of Ruies and Records 84/02/17 HICKEY, J P. Bnaw. Pittman, Potts & Trowbridge Ip 22552 036
- --8209200364 SECY-82-340
 Informs of procedures to process board notifications involving allegations which may fall within investigative purview of Ofc of Investigations
 DIRCKS.W J Office of the Executive Director for Operations
 82/08/17 7pp 22552 057
- 840308004i SECY-84-075
 Requests Commission review of proposed issuance of License XV-B586.approving export of natural V to EURATOM countries, to Braunkohle Transport USA DIRCKB,N J Office of the Executive Director for Operations 84/02/24 15pp 22584 079
- B403080436 BECY-84-067A
 Provides updete to preliminary draft document re DDE general guidelines for recommendation of sites for nuclear waste repositories, dtd B31118, to assist Commission in deciding whether to grant or withhold concurrence DIRCK9, W J Office of the Executive Director for Operations B4/02/22 49pp 22646 134
- 8403070006 Further response to FOIA request for ell 1982 SECY papers to be made available SECY-82-37 & SECY-82-37A placed in PDR FELTON, J M Division of Rules and Records 84/02/22 WEISB, E. R. Union of Concerned Scientists 1p 22591 219
- ---B203050065 BECY-B2-037
 Informs of receipt of Executive Branch finel draft rept to Congress per Section A01 of Nuclear Non-proliferation Act of 1978 Rept generally accurate No areas warrant formal NRC Lommant BIRCKS, W J Defice of the Executive Director for Operations B2/01/29 100pp 22591 220
- ---B204160230 SECY-B2-037A
 Informs Commission of receipt of finel version of rept to
 congress re Section 601 of Nuclear Nonproliferation Act
 DIRCKS.W J Office of the Executive Director for Operations,
 B2/03/29 64pp 22591 317
- B403070017 Responds to FOIA request for SECY-B3-445 to be placed in PDR Forwards SECY-B3-445 Document also in PDR FELION. M Division of Rules and Records B4/02/28 BUCKLEB,R. NUS Corp ip 22592 312
- --8403090019 BECY-83-445
 Responds to Commission request for human factors program
 plan quarterly repts cited in Chilk 830216 staff
 requirements memo
 DIRCKS.W J Office of the Executive Director for Operations
 83/10/28 16pp. 22592 313

- 8403140244 Board Notification 84-066 forwards SECY-84-104 re NRC insp of Nuclear Svcs Corp audit of Pullman Power Products at sits, including draft IE Insp Rept 50-275/83-37 & 840229 final rept EISENHUT, D 0 Division of Licensing OL 84/03/28 BUCK, J H , MDORE, T 8 , JOHNSON, W R Atomic 8afsty and Licensing Appeal Panel 3pp. 22747 070 24% Fiche 50-275,84/03/28,8403140244
- --8403200301 Provides inpo to Commissioners re circumstances surrounding documentation of NRC insp of 1977 Nuclear Eves Corp audit of Pullman Power Products Co DIRCKS,W J Office of the Executive Director for Operations 84/03/02 124pp 22947 073 24X Fichs 50-275,84/03/28, 8403140244

BTATE PROG STATE PROGRAMS

- 8402230176 Forwards revised State of CA nuclear power plant emergency response plan MEDFORD, M D Southern California Edison Co 84/02/16 EISENHUT, D 0 Division of Licensing 363pp 22353 001 24X Fiche 50-000, 84/02/16, 8402230176
- --8403020117 Revised State of CA nuclear power plant emergency response plan.

 * California, State of 83/04/30 2901pp R2353 003 24X Fiche 50-000, 84/02/16, 8402230176
- 8403020174 Notifies of upcoming meetings List will be updated weekly TAYLOR.T.J Environmental Protection Agency 84/02/17 MILLER.H. NRC No Detailed Affiliation Given 1p 22491 090
- 8403020206 Requests list of waste mgt documents from 631014 to present re Nevada Test Site project & info concerning process by which future documents can be received JDHN80N.C A Nevada, Blate of. 84/02/03 RUSSELL.C F Division of Waste Management. 27pp 22494 333
- 8403020332 Forwards H Bheely B30210 ltr containing State of BC comments on Chem-Nuclear topical rept, "Polyethylene High Integrity Containers "
 NUSBBANMER, D.A. Assistant Director for State Agreements Programs
 84/02/16. HIGGINBOTHAM.L. Low-Level Waste & Uranium Recovery
 Projects Branch. ip 22492, 238
- ---B403020337 Comments on Chem-Nuclear topical rept. "Polyethylene High Integrity Containers." per NRC B31227 & 840123 requests.

 Container acceptable for use at Barnwell site.

 BHEALY.H Q. Bouth Carolina. State of 84/02/10 NUBSBAUMER, D A

 Assistant Director for State Agreements Programs 2pp 22472 239
- 8403050109 Forwards responses to technical comments from NRC review of State of NM U licensing programmer 831216 ltm Addl personnel unavailable for U licensing & licensing & registration sections dus to budgetary restrictions BUHLT New Hexico, State of 84702/15. COLLINS.J.T. Region 4, Office of Director 14pp 22488 045
- B403050196 Requests to be notified if HO Bell will continue to be state liaison officer will be appointed PALLADIND,N J Commissionere, 84/02/22 ALAIN,H.A Mississippi, State of 2pp 12528-185
- 8403030362 Forwards responses to 831108 quastions for inclusion in record of 830906 hearing re Southeast Interstate Low Level Radwaste Mgt Compact PALLADINO, N. J. Commissioners, 84/02/08, THURMOND, S. Senate, Judiciary 16pp 22519 267.
- 8403050377 Requests to be notified if RL Banders will continue as state liaison officer or if new liaison will be appointed, PALLADING, N J Commissioners. 84/02/22 COLLINS, M L. Kentucky, Commonwealth of,. 2pp 22527, 256.
- 8403070029 Notification of grant execution, Mod 2.to "Investigation of Recent Crustal Movements in State of ME." Grantee State of ME. UMBEL, D. Technical Assistance Contracts Branch FIN G-1041. NRC-0-04-82-009, 84702/27. BATSON, M. Office of Nuclear Regulatory Research, Director, SCHMITT, T NRC No Detailed Affiliation Given. ip. 22563 194
- --B403070032 Mod 2.providing add1 funding.to "Investigation of Recent Crustal Movements in State of ME" ANDERSON, B., ANDERSON, N.A. Maine, State of. MORTON, K.V. Technical Assistance Contracts Branch. FIN 0-1041 NRC-0-04-82-009 84/02/27 lp. 22363.195.

- 8403070087 State of MO nuclear accident plan * Missouri State of 83/05/31 400pp 22540 070 24X Fiche 50-483,83/05/31,8403070087
- 8403080016 Further response to FQIA request for lists & records re Co-60 licensees Forwards App A documents, per Item 3 of request Portions of Documents 2 through 5 of App B deleted (ref FQIA Exemptions 6 & 7) FELTON, J H Division of Rules and Records 84/01/ii COHIE, D J Bouck, Holloway, Kiernan & Casey 5pp 22576 274
- --8403080170 PNA-81-006 on 810714, Louisiana Nuclear Energy Div notified NRC of radiography incident occurring on barge located less than 3 miles offshore Barge captain & radiographer exposed to 11 Ci Co-60 Medical attention obtained.

 DDDA:R J Region 4, Dallas, Office of the Director (81/03/01) 81/07/21 2pp. 22377 130
- 840308006B Further response to FOIA request for documents re Lixi.Inc. Lixiscope of America.Inc & SA Huber Consultants.Inc Forwards App B documents Documents also available in PDR FELTON.J M Division of Rules and Records 84/01/17 CAULK.O H Radiation Service Organization. 2pp 22584.001
- --8403080117 Forwards to Agreement States, proposed rule establishing na category to Group VI of 10CFR35 10O for I-125 as sealed source in portable device for bone imaging & foreign bady detection Change permits use of Liriscope. W/o enci NVSSRAVMER, D. A. Assistant Director for State Agreements Programs 83/04/07 Affiliation Not Assigned 1p. 22584 014.
- --8403080128 Forwards, to Agreement States, itr to Lixi re demonstration industrial training in use of Lixistope device Ltr requests clarifying info.not final licensing action. W/o encl NUSSIAUMER, D.A. Assistant Director for State Agreemente Programs 83/06/28 Affiliation Not Assigned ip. 22584-015
- --B40308013B Forwards NMBS policy to Agreement States re licensing huma use of Liviscope & bone math analyser. Byproduct math authorized for human use by nonphysicians (podiatrists & dentists) NUSSBAUMER, D. A. Assistant Director for Btate Agreements Programs B3/11/18 Affiliation Not Assigned 1p 22584-016
- --8403080181 Requests info re Liriscope licensing concerning number of hours & which topics to be covered in training of physicians not maeting Group VI critaria NUSSDAUMER, D. A. Assistant Director for State Agreements Programs 83/09/09 MILLER, V.L. Division of Fuel Cycle & Material Safety ip 22584 060
- --8403080098 Act receipt of 830222 ltr re State of NV reciprocity agreement BOLLINGL A Office of State Programs, Director 83/03/03 SAVINIR J. LIXI, Inc. 1p. 22584:013.
- B40312024B Responds to request for technical assistance in evaluating Nuclear Packaging. Inc FL50 high integrity container (HIC). HIC design can be approved for continued use provided vendor submits further info.

 NUBBBAUMER.D. Assistant Director for State Agreements Programs 84/02/29 STRONO.T R. Washington. State of Dept of Social & Health Services 3pp 22618 357.
- 8403150125 Discusses IE inep on 831220-21 & forwards notice of violation MARTIN.T T Division of Engineering & Technical Programs 84/02/28, EIBENBUD, M. New York Univ Medical Center, New York, NY 2pp. 22640:317 24X Fiche 50-320,84/02/28,8403150125
- --B403150132 Notice of violation from insp on 831220-21. Violation noted 5.8 mCi Ce-144 source transported to & passessed at facility not authorized by specific or general license * Region i, Office of Director. 84/02/28 ip. 22640 319 24X Fiche 50-320.84/02/28,8403150125
- 8403150221 Forwards study of soil samples collected during drilling of well located 100 ft south of Smatty eta Requests any comments on study be submitted to State of NV NUSSBAUMER.D A Assistant Director for State Agreements Programs 84/03/07 HIOGINBOTHAM, L. Low Level Waste Licensing Branch Jp 22648, 287.
- --B403150222 Forwards study made on soil samples collected during drilling of well 100 ft south of Beatty site. According to data, sorption of selected ions decreases below 270 ft. VADEN, U. Nevada, State of. B4/02/21. NUBBRAUMER, D A. Assistant Director for State Agreements Frograms ip 22448 289

- 8403190065 Forwards State of NC & Chatham, Harnett, Lee & Wate Counties emergency response plan Plan forwarded to ASLAB for use in hearings by separate ltr dtd 840228 HCDUFFIE, M A Carolina Power & Light Co NLS-84-104 84/03/12 BENTON, M R Gffice of Nuclear Reactor Regulation, Director 1p 22663 130 24X Fiche 50-400,84/03/12,8403190065
- --8403190067 Emergency response plan # North Carolina, State of 84/02/29 454pp 22663 131 24X Fiche 50-400,84/03/12,8403190065
- 8403190420 Reviews responses to MRC comments on high integrity container design for TMI EPICOR-II prefilter wastes Approval of design recommended following resolution of listed comments NUSSBAUMER, D A Assistant Director for State Agreements Programs B4/02/01 KIRNER, N Washington, State of 2pp 22681,342
- 8403190447 Forwards trip rept of 840130-0203 visit to Golden & Fort Collins.CO to attend NRC Agreement States meeting, quarterly meeting of UMTRAP participants & sixth symposium on mgt of U tailings.low level waste & hazardous waste WEDER,M F Geotechnical Branch (Post 831001) 84/02/15 KNAPP,M R Geotechnical Branch (Post 831001) 60pp 22679-297
- 8403210133 PNO-II-84-023 on 840312. State of 8C advised of possible overexposure of radiographer & assistant radiographer Caused by assistant radiographer performing duties as radiographer Exposures of 5.000 to 10.000 rem possible TROJANOMSKI.R., WoodRUFF, R. L. Region 2, Office of Director. 84/03/16 2pp 22707 236
- 8403230025 Comments on petition for rulemaking re DDE guidelines for recommendation of sites for nuclear waste repositories. Concurs w/seven points in preliminary decision FRISHMAN.S Texas, State of 49787850 004 84/03/19 CHILK,S J Office of the Secretary of the Commission ip 22728:349.
- 8403230188 List of State of WA Dept of Ecology high level nuclear wester mpt legislative proposals as of 840302 * Washington, State of 00675 84/03/02 2pp 22759 119
- 8400200190 NUREQ-1015
 STATE SURVEILLANCE OF RADIDACTIVE MATERIAL TRANSPORTATION
 Final Report
 SALDMON.S N Office of Stats Programs, Director 84/02/29 72pp
 Available at NRC \$4 50 22759 048
- 8403230250 Bummary of State of WA High Level Nuclear Waste Advisory Council 840120 meeting w/listed attendess re forthcoming public info program w/Ofc of High Level Nuclear Waste Mgt * Washington, State of 00686 \$4/01/20 Washington, State of 35pp 22739 327
- B403260203 Advises that proposed license amend re spent fuel storage expansion submitted on 840314 forwarded to state designee for State of FL, in accordance w/10CFR50 91(b)(1)
 WILLIAMS, J W Florida Power & Light Co L-84-74 B4/03/16
 EISENHUT, D Q Division of Licensing ip 22756 209 24X
 Fiche: 50-250, 84/03/16, 8403260203
- 8403260280 NUREG/BR-0029 VIO N2 INFORMATION REPORT ON STATE LEGISLATION LANDAU M Office of State Programs, Director 84/03/10 9pp 22761 307
- 8403270286 Notification of contract execution. Mod 1, to "Radiation Monitoring Program Requirements" Contractor State of ME. UMBEL. O Technical Assistance Contracts Branch FIN 8-8537. NRC-28-83-603 84/03/07 MCOSCAR.J Dffice of Resource Management. Director KOTTAN.J NRC No Detailed Affiliation Given ip 22789.252
- ---B403270270 Mod 1, providing funds for CYB4 & changing B&R number & NRC authorized representative, to "Radiation Monitoring Program Regultements"

 *** Mains: State of SMITH, P A Division of Contracts FIN B-8357 NRC-28-83-603 B4/03/07 Ip 22789 253.
- 8403280221 Requests response to author 840201 ltr re sources of funding in 1984 for cleanup of facility Svc list encl SALTZMAN.J Assistant Director for State & Licensee Relations 84/03/12 ORAHAM.J O General Public Utilities OPU Service Corp 2pp 22787.344 24X Fiche 50-320.84/03/12,8403280221
- 8403280254 Forwards draft itr incorporating conclusions & recommendation re technicel assistance to State OP MA on NUPAC high integrity container design Addl info required recorrosion performance of F255 welds & pitting corrosion HICQINBOTHAMAL Low-Level Waste & Uranium Recovery Projects Branch 84/02/16. NUSSBAUMER, D Assistant Director for State Agreements Programs 7pp 22808 182

- 84032903i6 Comments on patition for rulemaking re DDE general guidelines for recommendation of sites for nuclear waste repositories NRC concurrence decision offers some improvement to DDE guidelines KALITOHSKI.T Minnesota
- 8403300112 PNU-II-84-024 on 840326. State of TN informed Region II that state licenses. Guadrez Co. suspected as source of sawer line contamination detected by DDE State investigation underwey. TROUANGURSKIR Region 2. Office of Director. 84/03/27 ip 20801 230
- TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE
- 8305190492 Forwards technical review rept on undetectable failure in Westinghouse solid-state protection sys. CHIRAMALIM Reactor Operations Analysis Branch. AEOD/T308, 83/04/20 SEYFRIT.K V Reactor Operations Analysis Branch 1p 22789 285
- --8305190497 AEQD/T308
 "Undetectable Failure in Westinghouse Solid State Protection
 Sys (SSPS)." technical review rept
 CHIRAMAL, M Reactor Operations Analysis Branch. 83/04/20. 6pp
- B401120525 Forwards nonproprietery version of topical rept."
 "Title 10CFR61, Weste Form Certification Cement."
 BTAEHR, J P. POPPE, L K. Chem-Nuclear Bystems, Inc., 83/11/30,
 JDHNSGN, T. NRC No Detailed Affiliation Given. 1p., 21803*111
- --8401120550 CNSI-WF-C-01-NP Nonproprietary version of "Title 10CFR61, Waste Form Certification - Cement." * Chem-Nuclear Systems, Inc. 83/11/30 105pp 21803:113
- 8401130363 Comments on proposed new SRP 5 3 4 re fracture toughness of steam generator & reactor coolant supports No add1 regulatory guidance necessary CAHN.A L Bechtel Corp. 84/01/09 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 21799 360.
- 8401190217 Notification of rescheduled 840130 meeting w/Hestinghouse in Bethesda: MB to discuss nine topical repts to be published in CY84 re BHR fuel reloeds Meeting originally scheduled on 840113 MORAN. D H Standardization & Special Projects Branch. 83/12/22. THDMAS. C O Standardization & Special Projects Branch. 1p 21870-2288
- 8402070020 Board Notification 84-044, forwards Part 21 rept re Transemerica Delaval. Inc turbucharger thrust bearing ibbricetion defect resulting in engine nonavailability, EIBENHUT-D 0. Division of Licensing 84/02/29, PALLADIND Commissioners 4pp. 22541 263 24X Ficher 50-000, 84/02/27, 8402090020
- 8402070021 Board Notification 84-039 discusses NRC 840210 & 16 meetings bu/Transamerica Delayal, Inc Emergency Diesel Generators Duners Group Heeting scheduled on 840308 for finalization of generic program plen prior to NRC review.

 EIBENHUT, D @ Division of Licensing. 84/02/28 PALLADING Commissioners 5pp 22546,003 24X Fiche: 50-000,84/02/28,8402070021
- 8402090033 Board Notification 84-047: forwards Transamerica Delaval, Inc Owners Group piston skirt rept & task descriptions EISENHUT, D O Division of Licensing, 84/03/07 PALLADINO Commissioners 4pp. 22674, 221. 24X Fiche: 50-000, 84/03/07, 8402090033.
- 8402090035 Board Notification 84-033 forwards "Emergency Diesel Generator Component Tracking Bys," facility component data base for design review & quality revalidation effort of Transemetrica Delavai Owners Group program plan, EISENHUT,D @ Division of Licensing, 84/03/12 PALLADINO, OILINENY, RUBERTS Commissioners, 4pp. 67218'079, 24X Fiche: 50-322,84/03/12,8402090035
- --B403190385 "Emergency Diesel Generator Component Tracking Sys "
 * TDI (Transemerica Delayal, Inc.) Owners Group. 84/02/29,
 515pp 22675-322, 24% Fiche: 50-322, 84/03/12, 8402090035,
- 8402090038 Board Notification 84-051 forwards "Transamerica Delaval, Inc (TDI) Diesel Generators Owners Group Program Flan."
 EISENHUT,D Q Division of Licensing. 84/03/12 PALLADINO Commissioners 5pp 22688.214 24X Fichs 50-000,84/03/12,8402090038

- ~~8403200143 "Transamerica Delaval (TDI) Diesel Generators Dwners Group
- 8402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delavai, Inc (TDI) Owners Group Distribution list encl
 EIBENHUT.D 0 Division of Licensing 84/03/12 PALLADIND
 Commissioners 5pp 22708 001 24% Fiche 50-000,84/03/12,8402090039
- ~-8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval. Inc Dwners Group in Bethesda. MD re problems w/emergency Inc Dwhers Group in Bethesda.MD rs problems w/emergency dissel generators CARUSD.R Licensing Branch 2 84/02/27 D'REILLY, J. P NRC - No Detailed Affiliation Given App 22708 006 24X , Fiche 50-000, 84/03/12, 8402090039
- -8403050554 Transcript of 840210 meeting w/Transamerica Delaval.Inc Owners Group in Betheada,MD re problems w/emergency diesel generators * NRC No Detmiled Affillation Given 84/02/10 147pp tors - No Detailed Affiliation Given 84/02/1 108 24% Ficha 50-000, 84/03/12, 8402090039 84/02/10 147pp A7201 DDB
- ~-8403070409 Summary of 840R16 meeting w/Transamerica Delaval, Inc Owners Oroup in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl
 MILLER.M.A. Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708-161 24X Fiche 50-000,84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche. 50-000,84/03/12.84020990039
- 8402100259 Forwards proprietary "Probability of Missile Generation in QE Nutlear Turbines," per 830428 commitment Rept will be presented at 840207 meeting in Bethesda, MD Affidavit encl Rept withheld (ref 100FRZ, 790)
 TIMO, D.P. General Electric Co. 84/02/06 IPPOLITO, T.A. Operating 84/02/06 IPPOLITO T A Deprating Reactors Branch 2 9pp 22181 266
- B403010105 Summary of 820209 meeting w/Hestinghouse & Hestinghouse Owners Oroup re generic emergency operating procedure technical guidelines Viewgraphs encl CLAYTON.H B Procedures & Systems Review Branch B2/02/24 ZIEMANN.D L, Procedures & Systems Review Branch 36pp 22479: 22479 301
- 9403010115 Forwards revs to organization for GA dept, reflecting listed Changes KELLY.R B Stone & Hebster Engineering Corp 84/02/10 POTAPOVS.U Vendor Program Branch. App 22436 022
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval, Inc Duners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations WUSELER, H J TDI (Transamerica Delaval, Inc.) Dwners Group IDI-2 B4/02/27. DENTON, H R Office of Nuclear Reactor Regulation, Director. 3pp 22434:090. 24X Fiche. 50-000, 84/02/27, 8403010207
- ---B403010446 FAAA-B4-2-14
 "Investigation of Types AF & AE Piston Skirts "
 Failure Analysis Associates. FME-R-6/7396 (
 22434'093 24X Fiche: 50-000, 84/02/27, 8403010207, 84/02/27. 83pp.
- 8403010218 Forwards task descriptions for 16 known problems re Transamarica Delavai, Inc emergency diesel generators, MUSELER:N J TDI (Transamerica Delaval, Inc.) Owners Oroup TDI-1 84/02/2B, DENTON:H R Office of Nuclear Reactor Regulation, Director 42pp. 22435,177 24X Fiche,50-000,84/02/2B,8403010218
- 8403010305 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, NOSILISMO Application for amend to Licenses DPR-33, DPR-32 & DPR-68, changing Tech Speck to lower Group 1 isolation setpoint for reactor lower water level W/proprietary NEDE-30012, "...MSIV Water Level ..." Rept withheld (ref lOCFR2 790)
 MILLS, L M. Tennessee Valley Authority. TVA BFNP TS 196, 84/02/22
 DENTON H R Diffice of Nuclear Reactor Regulation, Director, 3pp 22433-042 24X Fithe 50-259,84/02/22,8403010306.
- 8403010451 SECY-83-034 03010451 SECT-83-034 Informs Commission of problems w/emergency dietal generators mfg by Transamerica Delayal, Inc. DIRCKS, H. J. Office of the Executive Director for Operations 84/01/25, 4pp 22438:347. 24X Fiche.50-000.84/01/25, 8403010481.

- 8403020195 Forwards addl info to complete review of Topical Rept VEP-FRD-41, "VEPCO Reactor Sys Transient Analysis Using RETRAN Computer Code." in response to NRC 1982 informal
- 8403020226 Requests that CRGR consider merits of NRC position re containment isolation requirements for post-LDCA hydrogen recombiner lines, per 830908 appeal meeting NRC position extends beyond clarification of intent of BRP 6.2.4 HELMIG.D R BWR Dwners Group BWR03-8403 84/02/27 DRNTON. Office of Nuclear Reactor Regulation, Director 2pp 22439.2: DENTON, H. R.
- B403020275 Responds to reliability survey questions re diesel generator startup & operation Responses to NRC request for add1 info re Transamerica Delava1 emergency diesel generators will be re transamerica betaval emergency diesel gene submitted by 84080: MEDFORD.M D Gouthern California Edison Co CRUTCHFIELD.D Operating Reactors Branch 5 84/02/29
- 8403020406 Advises that draft "Final Rept on Div I & II Transamerica Delaval. Inc Diesel Generators," forwarded to NRC on 840216 will be submitted in final form on 840221 HOUSTON M D Licensing Branch 2 84/02/21. Licensing Branch 2 3pp 22492 104 24X Fiche 50-416.84/02/21.8405020406
- --- 8403020410 Draft "Final Rept on Div I & II Transamerica Delaval, Inc
- 8403050098 Forwards "Rept on Task 05088, Pressurizer Relief Valve Discharge Piping Gualification for Calvert Cliffs, Unit 2, "per TMI Item II D I LUNDVALL, A E Baltimore Oas & Electric Co 84/02/29 MILLER, J R. Operating Reactors Dranch 3 3pp 22484 167 24X Fiche 50-318, 84/02/29, 8403050058
- --8403050103 CEN-248(B) RO2
 Rev 2 to "Pressurizer Safety Valve Operability Rept
 Combustion Engineering, Inc 84/01/31 50pp :
 Fiche 50-318.84/02/29.8403050098 22484 332 24X
- 8403050215 Notifies of fee due for review of NEDO-24934, "Emergency Procedure Guidelines Rept.Rev 2" MILLER. W O License Fee Management Branch CL-83-05 84/02/22 GUIRK.J F. General Electric Co ip 22528 143 Panch GL-83-05 84/02/22
- 8403050222 Informs of fee due for review of 811130 Westinghouse Owners Group emergency response guidelines tept. MILLER, W O License Fee Management Branch 84/02/22 RAHE, E P Westinghouse Electric Corp 1p 22527 361
- 8403050229 Advises of fee due for review of CEN-152, "C-E Emergency Procedure Quidelines Rept " MILLER,W D License Fee Management Branch 84/02/22 BCHERER,A E Combustion Engineering, Inc. 1p 22527 360
- 8403060011 Informs that NRR completed review of B&W Owners Group rept on emergency procedures & response guidelines Div of Finance & Accounting will forward bill MILLER.W O License Fee Management Branch 84/02/22 TAYLOR.J H Babcock & Wilcox Co ip 22928 353
- 8403040147 Advises that NUREO-0737. Action Items II K 3 30 & 11 K, 3 31 considered complete, based on 840104 telcon between NRC & 0E Licensee need only identify to NRC ref on docket to GE Topical Rept NEDO-20566 or NEDO-20566 or NEDO-20566 NES-84-096 84/02/27 VASSALUG.D B Operating Reacture Branch 2 2pp 22518,334 24X Fiche. 50-324,84/02/29,8403060167
- 8403040174 Confirms CASE GA program insp at Arizona Public Byc Co in Phospix.AZ & Aerojet Mfg Co in Bacramento, CA on B30305-07 & OB-09, respectively, per 840216 telcon POTAPOVS.U Vendor Program Branch. 84/02/27 MARSH,R N Flori¢a Power & Light Co ip. 22518:344
- 8403060325 Forwards MCAP-10433, "Determination of Copper Content of Longitudinal Held Seams in Intermediate Bhell Region of Haddam Neck Reactor Vessel: "confirming past estimates of copper content & through-wall distribution COUNSIL.W G. Connecticut Yankee Atomic Power Co 811040 84/02/17 CRUTCHFIELD.D Operating Reactors Branch 5. ip 22513-320. 24X Fiche.50-213.84/02/17,84030A0325

- --B4030A032A WCAP-10433 NOSMONAL MEAN-10433
 "Determination of Copper Content of Longitudinal Wald Seams in Intermediate Shall Region of Haddam Neck Reactor Vessel" 80068, R 8 , VANICHKO, 8 E Hestinghouse Electric Corp. 83/11/30 ilpp 22513 321 24X Fiche 50-213,84/02/17,8403060325
- 8403060338 Advises of problem compromising integrity of design review/ quality revalidation of emergency dissel generators mfg by Transamerica Delaval, Inc Util involvement in review represents conflict of interest BRDWN, H. H. Kirkpetrick, Lockhart, Hill, Christopher & Phillips BRDWN, H. Buffolk County, NY 84703/01 DENTON, H. Office of Nuclear Resctor Regulation, Director Spp. 22519 088 24X Fiche 50-322,84/03/01,8403060338
- 8403040357 Forwards Endorsement 127 to NEL1A Policy NF-34 ASHBURN.D J Marsh & McLennan, Inc. 84/02/28 SALTIMAN, J Assistant Director for State & Licenses Relations 2pp 23 22511 357
- 8403060375 Forwards Endorsements 62 & 63 to NELIA Policy NF-193 & Endorsement 33 to MARLU Policy MF-94 ASHBURN, D.J. Marsh & McLennan, Inc. 84/02/28 SALTZMAN, J. Assistant Director for State & Licensee Relations. 4pp. 22518, 203
- 8403060409 Transmits Rev O to Rept 84-3. "Mark I Hetwell to Bruwell Vacuum Breaker Load Methodology." per Mark I/NRC 831215 maeting Affidavit encl Rept withheld PFEFFERLEN. H C General Electric Co MFN-025-84. 84/03/02 VASSALLO.D B Operating Reactors Brench 2 5pp 22518 215
- 8403060453 Discusses deficiencies discovered in Delaval emergency diesel generators Written submittal requested giving details of enhencement program to justify interim operation EISENHUT. D. G. Division of Licensing 84/02/24 RICHARD. J.B. Mississippi Power & Light Co. 4pp. 22550 003 24X Fiche 30-416.84/02/24.8403060453
- 8403070127 Forwards proprietary Rev i.Amend 1 "Exxon Nuclear Analysie of Power Distribution Measurement Uncertainty for Westinghouse PWRs " Rept withheld (ref iOCFRZ 790) CHANDLER, J C. Exxon Nuclear Co., Inc. (eubs of Exxon Corp.), 84/02/03 THOMAS, C.D. Standardization & Special Projects Branch ip. 22541 360
- 8403080205 Forwards proprietary & nonproprietary info supporting application for Tech Spec changes for Cycle 5 reload Proprietary repts withheld CHANDLER, J C Exxon Nuclear Co , Inc. (aubs. of Exxon Corp.) JCC, 040 84 84/03/02 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 5pp 22558 224. 24% Fiche 50-316, 84/03/02, 840030000 8403080205
- ---B4030B0210 XN-NF-B3-B5 B01
 Suppl 1 to "DC Cook Unit 2, Cycle 5 BAR "
 CDPELAND,R A, STOUT,R B, YILLIAMSDN,H E. Exxon Nuclear Co, Inc
 (subs of Exxon Corp). B4/02/23 13pp 22558 229 24X
 Fiche 50-316,84/03/02,8403080205.
- --B4030B0216 XN-NF-84-21 (NP)
 Nonproprietary "DC Cook Unit 2 Cycle 5 5% Steam Generator
 Tube Plugging Limiting Break LOCA/ECCS Analysis."
 ADES: M. J. BRAUN; D J. FAUBZ; N. F. Exxon Nuclear Co., Inc. (subs
 of Exxon Corp.) 84/03/01 65pp. 22558 244 24%
 Fiche. 59-316. B4/03/02; 8403080205.
- --8403080220 XN-NF-B3-85 #DC Cook Unit 2.6ycle 5 8AR "
 #DC Cook Unit 2.6ycle 5 8AR "
 #IMPY,P D , BKD0EN,F B , WILLIAMBON,H E Exxon Nuclear Co., Inc
 (subs of Exxon Corp) 83/10/24 34pp 22558 310 24X
 Fiche.30-316.84/03/02.8403080205
- --8403080223 XN-NF-82-32 (NP) RC2
 Nompreprietary Rev 2 to "Plant Transient Analysis for DC Cook Unit 2 Reactor at 3.425 MHT Operation H/5% Steam Centrator Tube Flugging"
 ADAMS.F T , KAYSER.W V , CHANDLER. J. C Exxon Nuclear Co. , 1 (subs of Exxon Corp.) 84/03/03 114pp 22558:345. 24X Fiche.50-316.84/03/02.8403080205
- 8403090198 Forwards two itrs referenced in 830916 itr.rspresenting entire dialogue w/NRC re GC breakdown, All future correspondence will be forwarded to IE & will be routed through author ofc.
 KALE, D L. Gulf & Western Industries, Inc. 84/01/17 ANDERSON, W F Director's Office, Office of Inspection and Enforcement. ip 22574, 273
- 8403070255 Forwards "Analysis of Capsule U From Alabama Power Co UM Farley Unit 1 Reactor Vessel Rediation Surveillance Program " .CLAYTON.F.L Alabama Power Co. 84/03/01, VARGA, 8 A Office of Nuclear Reactor Regulation, Director 2pp 22568:201 24X Fiche:50-348,84/03/01,8408070255

- --8403090259 WCAP-10474 4030490239 MCAP-10474
 "Analysis of Capsule U From Alabama Power Co JM Farley Unit
 1 Reactor Vessel Rediation Surveillance Program."

 BOGOS.R B , YANICHKO B E , CHENEY.C A Wastinghouse Electric Corp.

 84/02/29 90pp R256B 204 24X Fiche 50-348,84/03/01,

 B403090235
- 8403070314 Forwards repts re passive containment sys & comments on ALO-137. "Evaluation of Passive Containment Sys." by Sandia Natl Labs
 FALLS.O B NucleDyne Engineering Corp 83/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director THOMAS, C O Standardization & Special Projects Branch 3pp 22568.347
- --8403070315 NEC-6
 "Passive Containment Sys for Nuclear Power Plant"
 * NucleDyne Engineering Corp 83/07/30 66pp. 22568 351,
- --8403090319 NEC-10 "Response to Comments on Passive Containment Sys made at Meeting of ACRO Subcommittee on Fluid Dynamics " * NucleDyne Engineering Corp. 81/05/13. 59pp 22568 352.
- --B403070322 NEC-9 Westponee to Comments on Passive Containment Sys made at Masting of ACRS Subcommittee on Fluid Dynamice " * NucleDyna Engineering Corp 81/01/30 161pp 22569:055.
- --B403090324 "Presentation to ACR# Bubcommittee on Improved Reactor Sefety," on 770626 * NucleDyna Engineering Corp 79/06/26. 33pp 22549-116
- --B403090318 NEC-8 "Passive Containment Sys Overcomes Class 7 Accidents " * NucleDyne Engineering Corp. 83/09/30 34pp 22569,216
- ---8403090323 "Bafety Improvements w/Passive Containment Sys."

 * NucleDyne Engineering Corp. 78/06/12 37pp 22569 256
- ---8403070328 Paper entitled "Passive Containment Sys in High Earthquake Motion." presented at 770730-0804 meetings in Sun Vailey.ID.

 KLEIMOLA,F W., FALLS.O. B. NucleDyne Engineering Corp. 77/07/30 ippp 22367 270
- ---B403070330 "Accessibility Into Fassive Containment Sys "
 KLEIMOLA,F W., FALLB, D. B., NucleDyne Engineering Corp. 63/09/30
 35pp 22569 327
- --8403090316 "Inservice Insp & Plant Surveillance w/Passive Containment KLEIMOLA, F W. FALLS, O. B. NucleDune Engineering Corp. 78/01/23 53pp 22569.345.
- ---8403070021 Speech sntitled "Recommissioning -- en Alternate to Decommissioning," presented at ANB winter meeting in Washington.DC KLEIMOLA,F.W., FALLB,O.B., NucleDyne Engineering Corp. 78/11/30 28pp 22570,019
- --8403090325 Speech entitled "Pagaive Containment Sys, New Concept to Solve Safety Concerns," presented at American Power conference on 790424 in Chicago IL FALLS, 0.8, r. KLEIMDLA, F. W. NucleDyne Engineering Corp. 79/04/24. 33pp. 22570 072
- --8403070327 Speech entitled "ALARA Considerations w/Passive Containment Sys." presented at ANS 830613 annual meeting in Detroit, HI FALLB. 0 B , KLEIMOLA, F. W NucleDune Engineering Corp. 83/06/13 17pp. 22570:100.
- ---8403070332 "Evaluation of Passive Containment Bys Concept as Applied to PWR Nuclear Power Plant."
 LEININGER, H. J. COLEMAN, J. H., MERRELL, H. H. Ebasco Barvices, Inc., (subs. of Enserch Corp.) 80/01/25 206pp. 22570; 160
- 8403120103 First interim deficiency rept re loose drive hubs on overspred governor drive shaft on Trensmerica Delaval, Inc diese's, Initially reported on 840203. Svc info memo being reviewed for approval, Also reportable per Part 21, MILLB, L.M. Tennesses Valley Authority, 84/03/01, 0'REILLY, Region 2, Office of Director 2pp 22585, 229 24% Fiche: 50-000, 84/03/01, 8403120105. O'REILLY, J. P.

1

- 8403120127 Informs of cooperation of BMR Owners Group on intergranular stress corrosion cracking issue & w/EPRI & LLL on NRC-supported studies on double-edged guillatine break CURTIS:N W DHR Owners Group. CURTIS:N W Pennsylvania Power & Light Co. 84/03/06 DENTON:H R. Office of Nuclear Reactor Regulation, Director ip 22568 205
- 8403120136 Part 21 rept re Westinghouse Typo 8A-1 DBR or DBRV stendby diesel generator differential relay defect Relay problem reported in 840215 Suppi 1 to IE Info Notice 83-63 RTE Delte requested to review defect & recommend correction 84/03/07 Director's Office, Office of Inspection and Enforcement 2pp 22585 219 24X Fiche, 50-416, 84/03/07, 8403120136
- 8403120180 Responds to NRC 840214 request for info re Trensamerica Delaval diesel engines Response to Items 1 & 2 will be provided within required 30 days Owners group working to develop info to satisfy Items 3,4 & 5 BIXBY, D T Transamerica Delaval, Inc. 84/03/02 EISENHUT, D. Q Division of Licensing 2pp 22587 173
- 8403130ii2 Forwards tentative schedule for responding to NRC questions re Transamerica Delayal diesel generators.per 84013i ltr. Delays or changes in owners group qualification program could change schedule.

 RODRIGUEZ.R.J. Bacramento Municipal Utility District. RUR 84-084
 84/03/05 STOLZ.U.F Operating Reactors Branch 4 3pp 22615-292
 24X Fiche. 50-312: 84/03/05.8403130112
- 8403130175 Interim Deficiency Rept DR-163 re set screw over key on drive hub for overspeed governor fuel transfer pump drive in standby diesel generator A supplied by Transamerica Delaval, Inc. Investigation incomplete Next rept by 840430 BODKER, J. E. Quif States Utilities Co. DR-163 84/03/02. CCLLINS, J. T. Region 4, Office of Director. ip 22615, 298, 24X Ficher 50-458, 84/03/02, 8403130175
- 8403130237 Interia deficiency & Pert 21 repts, Item 159 re flexible coupling drive shaft in overspeed governor & fuel transfer pump drive of stendby diesel generator Initially reported on 840206, Final rept will be submitted by 840416 PARSONS.R.M. Caroline Power & Light Co. NRC-170. 84/03/02. 07REILLY.J.P. Region 2. Office of Director. 1p. 22617 277 24X Fichs: 50-400,84/03/02,8403130237
- 8403130277 Forwards proprietary & nunproprietary "Response to NRC Request Number i for Addl Info on C-E Rept CEN-203-NP, Rev 1-NP, 'Further Response to NRC Action Plan Item II.K 3 30 " Proprietary rept withheld (ref iOCFR2, 790) HELLS, R. W. C-E Operating Plants Owners Group WELLS, R. W. Northeast Utilities, RHW-69-12 B4/02/28 THOMAS, C 0 Standardization & Special Projects Branch 2pp. 22604-002
- -8403130293 CEN-203-NP R01 801
 Rev 1 to Suppl 1 to nonpreprietary "Response to NRC Request Number 1 for Addi Info on C-E Rept CEN-203-NP, Rev 1-NP 'Further Response to NRC Action Plen Item II K 3 30, Justification of Small Break LOCA Methods."

 * Combustion Engineering, Inc 84/02/29 321pp, 22603 246
- 8403130285 Forwards proprietary draft Rev 1 to "GESTR-LOCA & SAFER Models for Evaluation of LOCA," Vol 3, "SAFER/GESTR Application Methodology," Affidevit encl. Rept withheld (ref 10CFR2 790)

 GUIRK, J. F General Electric Co. MFN-023, 84/02/27, THOMAS, C. O. Btandardization & Special Projects Branch 6pp. 22614.182.
- B403190342 Forwards justification for interim operation (JIO) for listed programs & draft Westinghouse Cless 3 topical repts. Final resolution of issues for listed JIOs expscted by B50331. PETRICK, N. A. Btandardized Nuclear Unit Power Plent System. SLNRC 84-0040. 84/03/06. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp 22616-149. 24X Fichs: 50-000, 84/03/06. 8403130342
- ---8403130338 HCAP-8587 R4E8E-13D
 Draft "Equipment Qualification Data Package," Rev 4 to EGDP-EBE-13, "Process Protection Bys."
 RANE, E. P. Westinghouse Electric Copp. EGDP-EBE-13, 83/06/30 22pp. 22616:153, 24% Fichs 50-482,84/03/06.8403130342.
- --8403130375 WCAP-8587 ROESE-47AD
 Draft "Equipment Qualification Data Package," Rev 0 to
 EGDP-ESE-47A. "Boron Dilution Fix Source/Intermediate
 Range Neutron Detector."
 RAME, E. P. Hestinghouse Electric Corp. EGDP-ESE-47A 83/05/31,
 20ps. 22616;175 24X Fichs:30-482,84/03/06.8403130342.

- --8403130389 WCAP-8587 ROHE-108 D
 Draft "Equipment Qualification Data Package." Rev 0 to
 E0DP-HE-108. "Head Vent Sys Electronic Control Hodule
 (HE-108) "
 RAHE. E. Hestinghouse Electric Corp EQPP-HE-108 83/10/31
 20p 22616-195 24X Fiche 50-482.84/03/06.8403130342
- 8403140006 Forwards Rev 2 to NEDE-24011-P-A-2, "GE Gameric Reload Fuel Application," issued in Jul 1981 W/o encl ENGELR E General Electric Co. MFN-022-82 82/02/17 BERGOREN, J S Standardization & Spacial Projects Branch 1p 20032 198
- 8403140048 Forwards "Grend Gulf Component Tracking Bys," "Shorshem Component Tracking Sys" & "Transamerica Delaval, Inc Dissel Generators Duners Group Program Plan," to resolve concerns w/smergency diesel generators MUSELER, W.J. Long Island Lighting Co TDI-3 84/03/02 DENTON, H.R. Office 96 Nuclear Reactor Regulation, Director 2pp 22626 062 24X Fiche 50-000,84/03/02.8403140048
- ---8403140080 "Grand Gulf Component Tracking Bys "
 # Long Island Lighting Co. 84/02/29 877pp. 22626.064 24X
 Ficha. 50-000, 84/03/02, 8403140048
- --8403140071 "Shoreham Component Tracking Sys " * Long Island Lighting Co. 84/02/29 516pp 22627.069 24X Fiche 50-000.84/03/02.8403140048
- --8403140095 "Transamerica Delaval, Inc Dissel Generators Dwners Group Program Plan " * TDI (Transamerica Delaval, Inc) Dwners Group, 84/03/02 261pp. 22628:223 24X Fiche:50-000,84/03/02.8403140048
- 6403140050 Forwards "Design Review of Connecting Rod Bearing Ehells for Transgmerica Delayal Enterprise Engines" for Shoreham & Grand Gulf dissal generators.

 MUSELER, W. J. Long Island Lighting Co. 84/03/12, DENTON, H.R. Office of Nuclear Reactor Regulation. Director 2pp 22632 074 24X Fiche. 50-000.84/03/12, 8403140050
- ---B403140086 PA0 7376
 "Design Review of Connecting Rod Bearing Shells for Transamerica Delayal Enterprise Engines"
 # Failure Analysis Associates FAAA-84-3-1 84/03/12 51pp 22632 076. 24X Fiche: 50-000, 84/03/12, 8403140050
- 8403140072 Documents B&W Owners Group Leak-Refore-Break Task Force 840119 meeting w/NRC in Bethesda, MD. Owners group intention to apply leak-before-break concept to reactor vessel core flood noziles discusses, Agenda & handouts enci DAYKIN-H W Bebcock & Wilcox Operating Plants Guners Group DAYKIN-H W Consumers Power Co 84/03/06 KADAMBI, P NRC No Detailed Affiliation Given. 30pp 22634:190.
- E403140128 Forwards comments on PNL drafts, "Proposed Quidelines for Util Organization Plan" & "Proposed Workbook for Assessment of Organization & Administration of Utils Seeking OL for Nuclear Power Plant " Drafts well prepared & thorough.

 EISENHUT, D. Q. Division of Licensing. 84/03/02 THOMPBON, H. Division of Human Factors Safety. 141pp 22697 001
- B403140131 Forwards "Justification of Trip Two/Leave Two Reactor Coolant Pump Strategy During Transient," to assist NRC & owners group utils in resolution of TMI Action Item II. K. 3.5 per Gensric Ltr 83-10A HELLS,R W C-E Operating Plants Owners Group HELLS,R. W. Northeast Utilities RHM-84-13 B4/02/29 EISENHUT,D. 9 Division of Licensing 2pp. 22620 001.
- B403140203 Forwards "Operating History Overview for bless! Generators in Nuclear Syc," comparing Transamerica Delaval, Inc generators w/generators mfg by other ysndors HEBDON, F. J. Program Technology Branch, AEGD/P401 B4/02/27 BERLINGER.C.H NRC No Detailed Affiliation Given ip 22638 319 24X Fiche: 50-000, 84/02/27, 8403140203
- ---B403140205 "Operating History Overview for Diesel Generators in Nuclear Svc."

 * Director's Office. AEOD/P401 84/02/29. 65pp. 22638:320 24X Fiche.50-000.84/02/27,8403140203.

- 8403140340 Summary of 831215 meeting w/GE & Mark I Owners Group in Bethesda. MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL. B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24% Fiche 50-000.84/02/21, 8403140340
- 840315002B Responds to 840105 Generic Ltr 84-01 re NRC use of terms important to safety a safety-related Meeting to discuss important to safety issue requested after 840401 Definition of important to safety unresolved CUTTER: A B Carolina Power & Light Co GL-84-01 84/03/12 TAYLOR: J H Director's Office, Office of Inspection and Enforcement ip 22640 331
- 8403150085 Forwards "B&W 177 Fuel Assembly Duners Group Safe End Task Force Rept on Generic Investigation of HPI/MU Nozzle Cracking," summarizing util involvement in cracking program CROUSE, R P Toleda Edison Cn 1029, 84/03/09 STOLZ, J F Operating Reactors Branch 4 2pp 22639 055 24X Fiche 50-346,84/03/09,8403150085
- 8403150097 Forwards nonproprietary version of XN-NF-82-90(NP). Suppl 1. "Potential Radiological Consequences of Incidents Involving High Exposure Fuel," which supports application for Tech Spec changes for Cycle 5 reload CHANDLER.J C Exxon Nuclear Co , Inc (subs of Exxon Corp) UCC-048 84 B4/03/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 6pp 22639 024 24X Fiche: 50-314, 84/03/13, 8403150097
- --B403150104 XN-NF-B2-90 (NP) S01
 "Potential Radiological Consequences of Incidents Involving
 High Exposure Fuel, DC Cook, Unit 2 "
 COPELAND.R A , KAYEER, W V , STOUT.R B Exxon Nuclear Co , Inc
 (subs of Exxon Corp) XN-NF-B2-90(NP) B4/03/31 24pp
 22637 030 24X Fichs 50-316.B4/03/13.B403150097.
- 8403150107 Suppls add1 info submitted in 840127 ltr re fuel surveillance program, per request Insp of nonleakers not performed on routine basis unless info of special interest can be obtained CHARNLEY, J 8 General Electric Co MFN-024-84 84/02/29 RUBENSTEIN. 1 9 Assistant Director for Core & Plant Systems 2pp 22429 207
- B4D3150133 Forwards "Transamerica Delaval. Inc Diesel Generator Rocker Arm Capacrew Stress Analysis Rept " Capacrew design adequate for applicable engines & svc conditions MUSELER. M. J. TDI (Transamerica Delaval. Inc.) Guners Group TDI-5 84/03/13 DENTON. H. R. Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fichs 50-000.84/03/13,8403150133
- --8403150134 "Emergency Diesel Generator Rocker Arm Capscrew Stress Analysis," prepared for Transamerica Delayal, Inc Ouners Group * Stone & Webster, Inc 64/03/31. 27pp 22639 272. 24X Fithe 50-000.84/03/13.8403130133
- 8403160055 Notification of 840314 meeting w/Westinghouse, BMNL & ANL in Bethesda, MD to discuss Westinghouse research program re ultrasonic testing of cast stainless steel pipe LIAM, B D Materials Engineering Branch 84/03/06 JGHNSTON, W V Assistant Director for Matls, Chem & Environ Tethnology (Post 830201) 2pp 22663 128
- 8403160070 Forwards SMECO 7703, "Missile-Barrier Interaction," submitted per 840227 response to Action Item 18 of structural design audit HOOLEVER.E J Duquesne Light Co. 2NRC-4-024 84/03/07 KNIGHTON,O W Licensing Branch 3 1p 22653.001 24X Fiche 50-412.84/03/07.8403160070
- --8403160076 SWECO 7703

 "Missile-Barrier interaction."

 JANKOV, Z D., SHANAHAN, J A., WHITE, M P. Stone & Webster Engineering Corp. EHTR-801. 77/09/30 223pp. 22653 002 24X

 Fiche 50-412,84/03/09,8403160090
- 8403160369 Advises that 831209 description of proposed techniques for inerting & packaging Zircalou matts reviewed & found acceptable Restrictions contained in confirmation action 1tr dtd 830819 withdrawn 870HR, J.P. Division of Emergancy Preparadness & Materials Safety, CAL 84/01/20 SRITTON, W. Hestinghouse Electric Corp. 1p. 22660 082
- 8403190241 Forwards Rev 2 to BAN-1543, "Integrated Reactor Vessel Matl Surveillance Program" Rev reflects modified capsule withdrawal schedule TAYLOR, J H Bebook & Hilcox Co ESC-164, 84/03/14 MORAN, D Office of Nuclear Reactor Regulation, Director 2pp 22672 321

- --B403170246 BAW~1543 RO2
 Rev 2 to "Integrated Reactor Vessel Matl Surveillance
 Program"
 LOHE,A L . MOORE,K E , AADLAND, J D Babcock & Wilcox Co
 B4/02/29 65pp 22672 323
- 8403190257 Forwards "Steam Pressure Suppression Characteristics of Water-Soluble Plastic Membrane Shielded Ice for Ice Condenser Containment Nuclear Power Plants "
 TUCKER.H B Duke Power Co 84/03/07 DENTON.H R Defice of Nuclear Reactor Regulation. Director 7pp 22672 102 24X
 Fiche 30-000.84/03/07.8403190257
- --B403170261 "Steam Pressure Suppression Characteristics of Water-Boluble Plastic Membrane Shielded Ice for Ice Condenser Containment Nuclear Power Plants " Supporting documentation encl SCRABIG.C M Westinghouse Electric Corp B3/06/30 125pp 22672 109 24X Fichs 50-000.84/03/07.8403170257
- 8403190394 Forwards nonproprietary & proprietary "Technical Basis for Eliminating Pressurizer Surge Line Ruptures as Structural Design Basis For Catawba. Units 1 & 2 " Revised FBAR pages also enci Proprietary rept withheld (ref 10CFR2 790) TUCKER.H B Duke Power Co 84/02/29 DENTON.H R Office of Nuclear Reactor Regulation, Director. ADENBAM.E G Licensing Branch 4 3pp 22674 089 24X Fiche 50-413.84/02/29.8403190394
- ---B403170377 Application for withholding proprietary rept WCAP-10487.
 "Technical Basis for Eliminating Pressurizer Burge Line
 Ruptures as Structural Design Basis "
 WIESEMANN, R A Westinghouse Electric Corp CAW-84-13 84/02/15
 DENTON.H R Office of Nuclear Reactor Regulation, Director 7pp
 22674 092 24X Fiche 50-413,84/02/29,8403190394
- --B403190404 WCAP-104B8 (NP)

 Nonproprietary "Tachnical Basis for Eliminating Pressurizer Surge Line Ruptures as Structural Design Basis for Catawba Units 1 & 2 "

 SHAMY. 8 A . YANG, C Y , SANE, A D Wastinghouse Electric Corp B4/02/10 107pp 22674 101 24X Fiche 50-413, B4/02/29, B403190394
- 8403200100 Forwards Rev 1 to XN-NF-83-85, Suppl 1. "DC Cook Unit 2, Cycle 5 84R"
 CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp)
 JCC 052 84 84/03/16 DENTON, H R Office of Nuclear Reactor
 Regulation, Director 1p 22679 186 24X Fiche 50-316, 84/03/16, 8403200100
- --8403200101 XN-NF-83-85 R01 801
 Rev 1.8uppl 1.to "DC Cook Unit 2.Cycle 5 SAR "
 COPELAND.R A, WILLIAMSON.H E, STOUT.R B Exxon Nuclear Co, Inc
 (subs of Exxon Corp) 84/03/15, 12pp 22699 187 24X
 Fiche 50-316,84/03/16,8403200100
- B403200129 Advises that GE control rod drive (CRD) tests indicated unanalysed load in design & analysis of CRD sys Newly identified load does not represent condition reportable under Part 21
 HELWIG, D.R. BWR Dwners Group BWRUG-B405 84/03/13 EISENHUT, D.G.
 Division of Licensing 2pp 22697 041.
- 8403200182 Forwards Topicel Rept 7703 on missile barrier interaction W/o rept EMERSON.H.F Stone & Webster Engineering Corp 84/03/06, DOOLITHE.E L Licensing Branch 1 ip 22686:340 24X Fiche 50-423.84/03/06,8403200182
- 8403200184 Forwards procurement spac to which Transamerica Delayel standby diseal generators ordered, in response to NRC 840131 request ROBRIGUEZ, R.J. Sacramento Municipal Utility District RJR 84-99 84/03/15 870LZ, J.F. Operating Reactors Branch 4 337pp 22686 001 24X Fiche 50-312, 84/03/15,8403200184
- B403200222 Responds to B40214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started encl
 MATHEWS, C S Transamerica Delaval, Inc B4/03/16 EISENHUT, D G, Division of Licensing 20pp 22691.179 24X Ficher 50-000, B4/03/16, B403200222
- 8403200271 Affidayit of Q Sherwood requesting NEDE-20392-6P, "STR Sundle Submittal, Milistone-1 Segmented Test Rod Bundle, Suppl A," det Jul 1982, be withheld from public disclosure SHERWOOD, Q General Electric Co B3/06/02, 3pp. 22696, 171 24X Fichs 50-245,83/06/02,8403200271.

- 10015 Forwards proprietary response to 840222 telcon request for 1 info on WCAP-10107 (P). "CONDOR-A Thermal-Hydraulic formance Code for EWRs " Response withheld (ref FR2 790)
- PR2 770)

 PRE P Westinghouse Electric Corp N9-EPR-2894 84/03/09

 ASS C D Standardization & Special Projects Branch 2pp

 O6 346
- 3210020 Requests that response to request for add1 info on HCAP0107 (P), "CONDUR-A Thermal-Hydraulic Performance Code
 0T BHRs." per EP Rahe B40309 ltr.be withheld per
 0CFR2 790 k 9 5
 \$EBEMANN.R A Westinghouse Electric Corp AW-84-17 B4/03/09
 HOMAS.C O Standardization & Special Projects Branch 1p
 2706 348
- 10053 Endorses SH Hobbs Feb 1984 Ltr HGN-013 to HR Denton in plans to NRC 031208 request for add1 info re Mydrogen! Erol Owners Group (HCDO) test program Questions to be wered by HCDO & util respectively.listed Erl F Mississippi Power & Light Co AECH-84/0091 84/03/09 TON.H R Office of Nuclear Rescutor Regulation, Director 2pp 04:344 24X Fiche 50-416,84/03/09,8403210053
- 1 0075 Forwards add1 info re BWR steady-state analysis methods, per 840117 request Answers provided to 12 of 15 questions sed by NRC GE will provide input to Questions 4.8 & 13 1 responses will be submitted by 840321 MERMAN.S R Carolina Power & Light Co NLS-84-112 84/03/15. SALLO.D B Operating Reactors Branch 2 2pp 22705 122 24X ps 6 50-324,84/03/15.8403210075.
- 3210080 NF-1583 04-1 A01
 April 1 to "Verification of Carolina Fower & Light Ref BHR
 h ermal-Hydraulic Methods Using FIBHR Code "
 JMITAR K Carolina Power & Light Co B 4/03/31 41pp
 2705 124 24X Fichs 50-324,84/03/15,8403210075
- 20215 Notification of B40329 meeting w/Westinghouse & Westinghouse ers Group Procedures Bubcommittee in Bethesda,MD to cuss how EPO task analysis addressed operator info & troi needs,per NUREQ-0737, Suppl 1

 ¥TON.H B Procedures & Systems Review Branch GL-82-33

 ⊃3705, ZIEHANN,D L Procedures & Systems Review Branch 2pp

 ≥1:361
- 30093 Application for amend to License DPR-20 consisting of posed Tech Spec change request to revise accident & saient analyses due to steam generator tube plugging ss III amend fee encl. Heatup scheduled for 940508 490N.B D Consumers Power Co 84/03/16 CRUTCH-IELD, D, rating Reactors Branch 5 18pp 22731 099 24X ne 50-255,84/03/16.8403230093.
- 3230106 XN-NF-84-18

 That Trensient Analysis for Pailsades Nuclear Power Plant

 TOX Bteam Generator Plugging "
 ENDOUIST.T R. NUTT,W T Exxon Nuclear Co., Inc. (subs. of Exxon or p.) 84/03/09 150pp 22731.202 24X Fiche 50-255,84/03/16,80320093
- 3230111 XN-NF-84-24
 *alisades LOCA-ECCS Analysis for 2125 MHt Operation & 50%
 -eam Generator Tube Plugging."
 *AHVILIT. Expon Nuclear Co., Inc. (subs. of Exxon Corp.).
 \$/03/09 54pp 22731 353 24X Fiche: 50-255, 84/03/16, 8403230093
- a CO24 Forwards "Justification of Manual RCP Trip For Small Break a Events," Westinghouse Owners Group response to Generic B3-10C & Darage Department of Small Break a B3-10C & Darage Department of Small Break Barbard J. Hestinghouse Operating Plants Owners Group PARD. J J. Carolina Power & Light Co. GL-83-10C 84/03/07 PSDN R J Division of Systems Integration (post 811005), 134pp 30,017
- *OOPS Summary of 840214 mesting W/OE, Westinghouse & Bechtel repower uprating program Attender list & agenda encl **EY, V. L. Operating Reactors Branch 2. 84/02/29, VASSALLO.D. B. **ating Reactors Branch 2. 20pp. 22761:317.
- *O170 Forwards Endorsement 127 to NELIA Policy NF-1.

 INS,J 0 Marsh & McLennan, Inc 84/03/07. SALTZMAN.J.

 stant Director for State & Licensee Relations. 2pp. 22750:357

- B403260219 Corrects Buppl 1 to Rev 2 to XN-NF-79-71(P), "Methodology for Including Code Uncertainties in Determining Operating Limits for Rapid Pressurization," to indicate broken line curves as COTRANSA & solid line curves as DATA CHANDLER. J C Exxon Nuclear Co . Inc (subs of Exxon Corp.) JCC 054 84 84/03/19 THOMAS.C D Standardization & Special Projects Branch 1p 22756 153
- 8403270010 Application for amend to License DPR-35.consisting of Proposed Tech Bpec Change 84-02 allowing increased core flow HARRINGTON, H D. Boston Edison Co. BECO 84-045 84/03/20 VASSALLO, D.B. Operating Reactors Branch 2 3pp 22769 165 24) Fiche 50-293,84/03/20.8403270010
- --B403270022 NEDO-30242

 "Safety Review of Pilgrim Nuclear Power Station,Unit 1 at
 Core Flow Conditions Above Rated Flow Throughout Cycle 6 "
 FISCHER, D L., ORIDLEY,R L. General Electric Co 83/08/31 34pp
 22769 170 24X Fiche 50-293.84/03/20,8403270010
- --8403270024 NEDO-30242 SO1
 Suppl 1 to "Safety Review of Pilgrim Nuclear Power Station
 Unit 1 at Core Flow Conditions Above Rated Flow for End-ofCycle 6 "
 FISCHER.D L , GRIDLEY.K L General Electric Co 83/09/30 i5pp
 22769 201 24X Fiche 50-293,84/03/20,8403270010
- 8403270130 Application for amend to License DPR-25 changing Tach Specs to extend certain MAPLHGR curves to 40,000 MWd/8T RYBAK.B Commonwealth Edison Co 8282N 84/03/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp , 22774 129 24X Fichs 50-000.84/03/19,8403270130
- --B403270135 NEDO-24145A ERR 09
 Errata & Addenda Sheet 9.replacing Page 4-14 to "LOCA
 Analysis Rept for Dresden Units 2 & 3 & Guad Cities 1 & 2
 Nuclear Power Stations "

 **Oeneral Electric Co 79NED273 83/01/31 2pp 22774 135
 24% Fiche.50-000.84/03/19,8403270130
- 8400270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by S&W for Transamerica Delayel, Inc (TDI) Diesel Generator Duners Group MUSELER, W J TDI (Transamerica Delayal, Inc > Owners Group TDI~6 84/03/23 DENTON, H.R Office of Nuclear Reactor Regulation, Director 2pp. 22774 001 24X Fiche 50-000.84/03/23,8403270132
- --8403270107 "Emargency Dissel Generator Air Start Valve Capscrew Dimension & Stress Analysis." prepared for Transamerica Delaval Inc (TDI) Dissel Generator Owners Group * Stone & Webster Engineering Corp 84/03/31 23pp 22774 003 24X Fiche 50-000,84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delayal diesel generators List of suggested meeting topics encl.

 MCGAUCHY, J P TDI (Transamerica Delayal, Inc.) Owners Group AECM 84/0187 84/03/23. DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 22769 133 24X Fiche 50-000, 84/03/23, 8403270134
- 8403280043 Notification of 840320 meeting w/util & C-E in Dethesda,MD to discuss proposed testing program to demonstrate adequacy of mods to RCS pumps, thermouells, thermal sleeves & control element assembly shrouds
 LICITRA,E A Licensing Branch 3 84/02/29 KNIGHTON,G W
 Licensing Branch 3. 3pp 22812.361 24X Fiche 50-528,84/02/29,8403280043
- 8403280122 Summary of 840224 meeting w/Westinghouse Gwners Group in Bethesda, MD re proposed Westinghouse steam generator tube rupture generic program Attendee list & agenda encl NERSES, V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp 22811 k31. 24X Fiche: 50-000.84/03/07,8403280122
- 8403280242 Summarizes 840222 meeting w/Westinghouse re evaluation methodology for EGCS & convolution of LGCA uncertainties Westinghouse presented WCAP-10395(P), "Bitatistical Evaluation of LGCA Heat Source Uncertainties" MDRAN.D H Standardization & Special Projects Branch 84/03/16 THOMAS, C O Standardization & Special Projects Branch. 3pp 22808:206
- 8403280248 Requests info re lack of issuance of revised proposed rule on diverse scram sys for Westinghouse reactors approved on 831103 OILINSKY, V Commissioners 84/03/06 Commissioners. 1p 22806: 199.

- 8403290267 Rev to 831212 application for amend to Licenses NPF-9 & NPF-12.changing listed Tech Spec bases, per Y Hail & MS Dunenfeld 840315 & 16 telcons, respectively Westinghouse proprietary info withheld tref 100FR2 790)
 TUCKER.H B Duke Power Co 84/03/23 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 3pp 22800 092 24X Fiche 50-369,84/03/23.8403290267.
- --B403290279 Requests withholding of proprietary info requested by util from public disclosure (ref 100FR2 790) Affidavit AH-76-60 dtd 761202 epc |
 HIESEHANN, R A Hestinghouse Electric Corp CAH-84-18 B4/03/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 22800 100 24X Fiche 50-369,84/03/23,8403290267
- --8403270282 Nonproprietary info reflecting use of Rosemount resistance temp detector
 + Westinghouse Electric Corp 84/03/23 59pp 22800 110 24x
 Fiche 50-369,84/03/23,8403250267
- 8403300088 Advises that fee reluctantly paid to Div of Accounting & Finance for review of Topical Rept NEDE-23785-1-P, Vols 1-3 NRC incorrectly termed Vol 3 as separate rept GUIRK, JF General Electric Co MFN-033-84, 84/03/23, MILLER, W O License Fee Management Branch 2pp 22821 361
- B403300107 Forwards proprietary & nonproprietary versions of,
 "Methodology for Addressing Superheated Steam Release to
 Lee Condenser Containments " Proprietary version withheld
 (ref 10CFR2 790).
 TUCKER: H B Dute Power Co 84/03/28 DENTON: H R Office of
 Nuclear Reactor Regulation, Director ADENSAM: E Q Licensing Branch
 4 2pp 22819:001 24X Fiche 50-413,84/03/28,8403300107
- --8403300116 Requests proprietary "Methodology for Addressing Superheated Stram Releases to Ice Condenser Containments," be withheld from public disclosure per 100FR2 790 WIESEMANN.R.A Westinghous Electric Corp CAM-84-24 84/03/26 DENTON.H R Office of Nuclear Reactor Regulation, Director Spp 22817 003 24X Fichs 50-413, 84/03/28, 8403300107.
- --8403300119 Nonpropristary, "Mathodology for Addressing Superheated Steam Releases to Ice Condenser Containments" • Westinghouse Electric Corp 84/03/28 240pp 22819.011 24X Fiche 50-413,84/03/28,8403300107
- 8403300170 Requests that Transamerica Delaval, Inc diesel review program be stopped promptly due to improper role of util in directing review New independent review should be established, in consultation w/Buffoll County JONES, F.F. Suffolk County, NY 84/03/23 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp 22820,047 24x Fichs 50-322,84/03/23,8403300170
- 8403300179 Requests that Issues Mgt Program document, transmitted on 840209, be clessified proprietary. Affidavit will be submitted separately. Updated list of cognitant contacts between B&W Guners Group & MRC encl TAYLOR. J H Babcock & Wilcox Co 84/03/19 DENTON, H R. Office of Nuclear Reactor Regulation. Director. 2pp. 22820 331.
- 8403300235 Responds to request for review of add1 info re NucleDyne passive containment sys design Review must be preceded by application for std design epproval DENTON. HR Opfice of Nuclear Reactor Regulation, Director 84/03/13 FALLS 0 B NucleDyne Engineering Corp. 2pp 22842:346
- --8403300237 Forwards response to rept re review of NucleDune Enginesring Corp containment sys design, W/o encl. FALLS. 0 B NucleDune Engineering Corp. 84/02/17, DENTON, H R. Office of Nuclear Resetor Regulation, Director. 2pp 22842:348
- 8403300251 Bummary of 840221 meeting w/util in Bethesda. MD re details of util proposed onsite/offsite electrical power reliability program for Transemerice Delayal, Inc diesel generators Attendance list & vieugraphs encl HOUSTON.H D. Licensing Branch 2 84/03/06 Licensing Branch 2 21pp 22845:001 24X Fiche 50-416.84/03/06.8403300251.
- HASH REGULATORY PUBLICATIONS PRE-NURED SERIES

* 1

8403010024 Responds to FDIA request for documents re-petition for rulemaking PRM-80-31 from Citizens Task Force of Chape! Hill-NC Forwards App & documents completely withheld tref FDIA Exemption 3). FELTON, J.H. Division of Rulss and Records. 84/01/18. SHOLLY, S.C. Union of Concerned Scientists 4pp. 22446:035.

--8403010074 Forwards review comments on dreft RES denial of patition for rulemaking on emergency planning zone at nuclear power plants, par request General comments encl HULMANL G Accident Evaluation Brench 83/01/07 COTA, P C Research & Standards Coordination Brench 7pp 22446.049.

WASTE MOT NUCLEAR WASTE MANAGEMENT

- 8401120323 Forwards nonproprietary version of topical rept."
 "Title 10CFR61. Waste Form Cartification Cement "
 STAEHR. J P. POPPE, L K. Chem-Nuclear Systems, Inc. 83/11/30,
 JOHNSON, T. NRC No Deteilsd Affiliation Given ip 21803.11:
- --8401120550 CNSI-HF-C-01-NP
 Nonproprietary version of "Title 10CFR61, Waste Form
 Certification Cement "
 Certification Cement "
 Chem-Nucleer Systems, Inc. 83/11/30 105pp. 21803; 113.
- 8402170325 Forwards UMTRA project EIS & snviron assessment revised schedules
 ARTHUR.J Energy, Dept. of. 84/01/26. PENNFILL.R NRC No Detailed Affiliation Given 5pp 32313 198
- 8402270471 Forwards evaluation requested by 840127 memo re Shiprock, NM sits selsmicity estessment as pert of remedial action plan for stabilization of inactive U mill tellings, Level of conservatism for assessment not specified, par request JACKBON, R. E. Geosciences Branch. 84/02/16. JUSTUS, P. 8 Geotechnical Branch (Post 831001) 4pp 67189, 211
- B403010356 Requests results/comments on review of encl energysis of water semples OA progrem by 840229
 HHITE,H O Energy, Dapt of 84/02/16 KNAPP,H NRC No Detailed Affiliation Given 12pp 22449.336
- B40302D174 Notifies of upcoming meetings.List will be updated weekly TAYLOR, T. J. Environmental Protection Agency. 84/02/17, MILLER, M. NRC NO Datailsd Aprillation Given CHRISTOFFERSON Utah, State of FRISHMAN, B Taxas, State of ip 22491-090.
- 8403020185 Lists Div of Waste Mgt representatives chosen to be located at sites under investigation by DDE as potential repositoriss for geologic disposel of high level waste, per UO Davis 830729 memo.

 BROWNING R.E. Division of Weste Menagement Region 3. Office of Director MARTIN, J.B. Region 5. Office of Director 2pp. 22495 003.
- B403020204 Requests list of weste mgt documents from 63:014 to present rs Neveda Test Site project & info cancerning process by which future documents cen be received JOHNSON, C A Nevada, State of 84/02/03, RUSSELL, C.F. Division of Weste Management 27pp 22494, 333
- 8403020216 Forwards records of PNL rediological surveys at Edgemont, SD. Add1 datailed evaluation of van "misses" to "false hits" needed by DDE Add1 DDE funding for ectivities necessary.

 JACKBON.P II Sattells Hemorial Institute, Pacific Northwest Laboratoriss 84/02/08 FLORY, C. A Low Level Waste Licensing Branch 76pp 22482, 132
- 8403020332 Forwards H Shsely 830210 itr containing State of EC comments on Chem-Nuclear topical rept, "Polyethylene High Integrity Containers," NUSSBAUMER, D A Assistant Director for State Agreements Programs 84/02/16 HIGGINBOTHAM, Low-Level Weste & Uranium Recovery Projects Brench. 1p 22492-238.
- --8403020339 Comments on Chem-Nuclear topical rept, "Polyethylene High Integrity Conteiners," per NRC 831227 & 840123 requests.

 Container acceptable for use et Barnwell site.

 8HEALY, H O South Ceroline, State of 84/02/10 NUSSRAUMER, D A Assistant Director for State Agreements Programs, 2pp. 22492 239.
- 840302034A Forwards summary of 830527-28 meetings w/DOE/NPO in Silver Spring, MD re preparetion of sits cherecterization plan for celt site-par 830711 telcon.

 COPLAN.S.M High Level Haste Technical Development Branch.

 83/07/21 VIETH D L. Energy, Dept of. 13pp. 22472: 225.
- 8403020374 "Procedures for Fisid Chemical Analyses of Water Bamples,"
 KORTE, N., EALEY, D. Bendix Corp KORTE, N. Energy, Dept. of, Idaho
 Operations Office UC-70A. 83/12/31. 32pp 22492-190.
- B403050315 Forwards "Date for Geochemical Investigation of UMTRAP Designated at Galt Lake City.UT " ", at Grend Junction. Co: " ", ... at Shiprock.NM" & " ... at Mexican Hat.UT " BUSH,K J. Geochemistry & Environmental Chemistry Research, Inc GEOR-90/2-B4/5, B4/02/08 HEBER:M NRC No Detailed Affiliation Given. Ip. 22505:031

1

- --B403050318 R-B217
 "Data for Geochemical Investigation of UMTRAP Designated Bite at Balt Lake City, UT"
 MARKOS, G. BUSM, K. J. Geochemistry & Environmental Chemistry Research, Inc. BOE/UMT/0236 B4/02/08 63pp 22505 032
- --8403050319 R-8215
 "Data for Geochemical Investigation of UNTRAP Designated
 Bite at Orand Junction, CO"
 MARKOS, G. BUSH. K. J. Oeochemistry & Environmental Chemistry
 Research, Inc. DOE/UMT/0232 84/02/08 73pp 22505 095
- --8403050322 R-8216
 "Data for Geochemical Investigation of UNTRAP Designated
 Site at Shiprock.NM"
 MARKOS.G., BUSH,K.J. Geochemistry & Environmental Chemistry
 Research, Inc. DDE/UMT/0234 84/02/08 65pp 22505 168
- ---B403050323 R-B212

 "Data for Ceochemical Investigation of UMTRAP Designated Bite at Mexican Hat.UT"

 MARKOS.O., BUSH.K J. Geochemistry & Environmental Chemistry Research, Inc. UMTRA-DOE/ALO- B4/02/08. 128pp 22505 233
- 8403060432 Forwards Design Section comments on draft Site Technical Position NNWSI STP-i O. "Groundwater Issues for Nevada Nuclear Waste Storage Investigations "Marked-up copy encl providing general & specific comments GREEVES.J T High Level Waste Technical Development Branch B3/08/17 POHLE.J A High Level Waste Technical Development Branch 17pp 22552 030
- 8403040450 Forwards current schedule of DDE/NRC technical meetings on repository licensing. Schedule being updated & distributed at least blueskiy to reflect changes.
 MILLER, H. J. Repository Projects Branch (Post 831001) 84/02/01
 BROWNING, R., BELL, H., BUNTINO, J. NRC No Detailed Affiliation Given 4pp. 22552 019
- 8403060519 Forwards "Rempdial Actions at Former Vitro Chemical Co Site South Sait Lake Preliminary FES," for review & comment MORLEY, J A Energy, Dept of 84/02/24 HIGGINBOTHAM, L., MARTIN, D NRC - No Detailed Affiliation Given GRGELSEMA, D Energy, Dept of 3pp 22550 012
- --8403060521 UMTRA-DDE/AL-0099-F
 "Remedial Actions at Former Vitro Chemical Co Site South Sait Lake, Preliminary FEB"
 * Energy, Dept of 84/02/29 724pp. 22550 013
- 840312024i Draft annotated agenda for 840315-16 meetings w/DOE in Richland.WA to discuss geology of BNIP * NRC - No Detailed Affiliation Given 00687 84/02/15 NRC -No Detailed Affiliation Given 5pp 22619-232
- 840312024B Responds to request for technical assistance in evaluating Nuclear Packaging, Inc FL50 high integrity container (HiC) HIC design can be approved for continued use provided vendor submits further info NUSBBAUMER, D. Assistant Director for State Agreements Programs 84/02/29, STRONG-IR, Washington, State of, Dept of Social & Health Services, Spp. 22618,359
- 8403140027 Forwards comments on NRC proceeding for concurrence in DDE guidelines for recommendation of sites of nuclear waste repositories & interpretation of available evidence MATHEBON, B M Utah, State of 48FR50432. 84/03/09, PALLADINO, N J Commissioners 8pp 22633.301
- 8403140132 Discusses 840227 telcon w/B Cook re Hovis itr concerning data collection effort at Hanford that involved L Lehman & availability of data.

 DELLIGATTI, M. Repository Projects Branch (Post 831001), 84/02/28, WRIGHT, R. Repository Projects Branch (Post 831001), ip 22637 355
- B403140312 Forwards monthly update detailing project activities covering contacts w/States of PA,UT,WY,& OR & plan for implementing EPA Stds at UMTRAP sites MORLEY,J,A Energy, Dept. of. 84/03/01 HIGOINBOTHAM,L Low Level Waste Licensing Branch. 5pp 22635.308
- B403150221 Forwards study of soil samples collected during drilling of well located 100 ft south of Beatty site. Requests any comments on study be submitted to State of NV NUBBBAUHER, D.A. Assistant Director for State Agreements Progrems. B4/03/07 HIGGINBOTHAM, L. Low Level Haste Licensing Branch | Ip. 22648 227

- --8403150222 Forwards study made on soil samples collected during drilling of well 100 ft south of Beatty site According to data, sorption of selected ions decreases below 290 ft VADEN, J. Nevada, State of 84/02/21 NUSSBAUMER, D.A. Assistant Director for State Agreements Programs ip 22648 288
- --B403150223 "Sorption of Selected Ions in Alluvial Profile "
 HEIDKER, J C Neveda, Univ of 84/02/21 18pp 22648 289
- B403150300 Suggests meeting of groundwater hydrologists re proposed exploration program at Lakeview OR UMTRAP site Exploratory program should provide groundwater info required for NRC cuncurrence in NEPA documents & radiological assessment HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch B4/02/14 MATHEWS, M. Energy, Dept. of ip 22649-316
- B403150315 Forwards repts of telcons held w/NRC re BWIP A8H.E B Rockwell International Corp 685 84/02/16 OLBON,O L Energy, Dept of 5pp 22649 309
- B403i60056 Trip rept of B40201-03 visit to Fort Collins,CO to attend conference on mgt of U mill tailings.low level waste & hazardous waste ODODE.D Geotechnical Branch (Post B31001) 84/02/20 KNAPP.M R Geotechnical Dranch (Post B31001) 2pp 22662 318
- 8403160072 Requests written concurrence on DDE/State of MY & Nava;o Indian Tribe cooperative agreements, to provide record of review process HIGGINDOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch B4/02/2B FONNER, R L Regulations Division ip 22662 309
- 8403160073 Forwards J Fields rept summarizing effects of two changes on ouput of NHFT/DVN graphics package HISE,M J Repository Projects Branch (Post 831001) 84/02/16 Repository Projects Branch (Post 831001) 21pp 22662 288
- B403190420 Reviews responses to NRC comments on high integrity container design for TMI EPICOR-11 prefilter wastes Approval of design recommended following resolution of listed comments
 NUSSBAUMER.D A Assistant Director for State Agreements Programs
 B4/02/01 KIRNER.N Washington. State of 2pp 22681 342
- 8403190422 Notifies of 840306-07 meetings w/onsite licensing representatives in Silver Spring. MD to discuss activities required to provide timely guidance to DOE Agenda encl BROWNING.R E Division of Waste Management 00393 84/02/24 CODA, F R , PRESTHOLT, P T , VERMA.T R Division of Waste Management 4pp 22681-332
- 8403190447 Forwards trip rept of 840130-0203 visit to Golden & Fort Collins,CO to attend NRC Agreement States meeting, quarterly meeting of UMTRAP participants & sixth symposium on mgt of U tailings.low level waste & harardous waste HEBER,M F Geotechnical Branch (Post 831001) 84/02/13 KNAPP,M R Geotechnical Branch (Post 831001) 40pp 22679 297
- B403200312 Responds to B40130 memo requesting review of Shiprock remedial action plan for UNTRAP Due to limited resources, assistance requested from Beismology Section in reviewing & commenting on plan Seismologist comments encl UUBTUS.P.S Gentechnical Branch (Post B31001) B4/02/27 H1001NB0THAPL, Low-Level Waste & Uranium Recovery Projects Branch in 22709 168
- B403200314 Forwards notice of upcoming meetings as result of 830719-20 meetings Notice will be updated weekly TAYLOR, I J Energy, Dept of 00388 84/02/24 MILLER, H NRC No Detailed Affiliation Given CHRISTOFFERSON Utah, State of FRISHMAN, S Texas, State of ip, 22709-167
- B403200331 Notification of U subcommittee & U administrative group organization B40207 meeting in Richmond, VA Resolution passed by State of VA Coal & Energy Commission and CATON, B. J. Virginia, Commonwealth of, 84/01/24 Virginia, Commonwealth of, 799 22709 132
- 8403200345 Forwards current list of technical meetings on repository licensing tentatively established w/DQE Several addinations being scheduled & organized MILLER, H. J. Repository Projects Branch (Post 831001) 00693 84/02/16 BROWNING, R. BELL, M. MILLER, H. NRC No Detailed Affiliation Given 4pp 22709 110
- 8403200348 Announces fifth bimonthly salt states/NRC meeting in Columbus.OH Forwards draft agenda for next meeting scheduled for 840327-30
 NEFF,J,O Energy, Dept of 84/02/27 JOHNSON,R NRC No Detailed Affiliation Given 3pp. 22709 107

- 8403200331 Discusses DOE request for meeting to discuss dreft comments on Durango preliminary DES Comments should be sent by 830215 List of attendees & handouts from 840214-25 meetings attached PENNIFILL.R Uranium Recovery Licensing Branch 84/02/21 MARTIN.D E Uranium Recovery Licensing Branch 27pp 22709 075
- 8403200354 Forwards environ assessment preparation schedule fulfilling OPS Plan Commitments 53141211, 53141221 & 53141231 & reflecting current scheduling for site workshops, data review & products
 - & producte KNAPP.M R Geotechnical Brench (Post B31001) B4/02/17 BROWNING.R E Division of Waste Management. 2pp 22708 361
- 8403200356 "Ra-226 Analysis for Shiprock Site Tailings Samples" * Bendix Corp. 83/08/09 10pp 22709 065
- 8403200370 Forwards questions & comments re review of surface water hydrology, arosion & long-term stabilization aspects of draft remedial ection plan JOHNSON, T L. Geotechnical Branch (Post 831001). 84/02/28 PENNIFILL: R. Low-Level Waste & Uranium Recovery Projects Branch bp 22708 351
- 84032i0034 Comments on petition for rulemaking re DOE guidelines for recommendation of sites for nuclear waste repositories FINN.D F Affiliation Not Assigned 49FR9450 002 84/03/15 Docksting & Services Brench 3pp. 22706 360
- 8403210038 Forwards State of NV comments on petition for rulemeking reconcurrence in DOE guidelines for recommendation of sites for nuclear waste repositories MURPHY.M R Murphy & Davenport 49FR9650 001 84/03/16 PALLADING.N Commissioners 4pp. 22707 011
- 8403220112 Submits notice of upcoming meetings of salt state representatives & onsite representatives TAYLOR.J J Energy. Dept of 00398 84/03/02. MILLER.H NRC No Detailed Affiliation Given FRISHMAN.8 Texas. State of FORSYTHE.R Mississippi. State of ig 22723 287
- 8403220122 Forwards schedule for review of Topical Rept CNSI-HIC-14871-01. "Polythlene High Integrity Containers " JUNGLIND.T L. Engineering Branch (Post 831001). 84/02/27 PDPPE, L. K. Cârm-Nuclear Systems. Inc. 2pp. 22723 283
- 8403220193 Trip rept of attendance at 840109 & 13 clese re geotechnical aspects & reclemation of tellinge impoundments PENNIFILL, R Uranium Recovery Licensing Branch 84/02/21 MARTIN, D E Uranium Recovery Licensing Branch 1p 22723 280
- B403220205 Provides process for dealing w/irregularities, both technical & procedurel. In hydrologic test methods
 HRIGHT.R J Repository Projecte Branch (Poet 831001) 00499
 84/02/23 MILLER.H J Repository Projects Branch (Poet 831001)
 2pp 22/23 275
- 8403220225 GJ-04(83)
 "Environ Assessment of Preliminary Cleanup Activities et Offsite Properties Contaminated by Tailings from Grand Junction Inscrive U Hillsits Grand Junction CO."
 # Bendix Corp 83/04/30 28pp 22719 309
- 840322028 Informe of review of lletrd sections of Shiprock remediel action plan Plan acceptable upon receipt of adequete response to encl comments & questions YOUND, Y Division of Waste Management 84/03/02 PENNIFILL, R Division of Waste Management 5pp 22723 353.
- BA03220231 Confirms verbal advice that ELD reviewed & approved cooperative agreements negotiated between DOE & State of MY & Navayo Nation, for reclamation & cleanup of U mill taulings disposal eitee FONNER, R L. Regulatione Division. B4/03/07 HIGGINBOTHAM, L. Low-Level Weste & Uranium Recovery Projects Branch ip. 22719 359
- 8403220239 Confirme info on NRC plans & preparations for review of draft environ essessments presented at 831115-16 meetings R Browning 831130 itr & 8 Coplan 831116 itr encl LINE(48), J Repository Projects Branch (Post 831001) 00402 84/02/24, NEFF,J Q Energy, Dept of, Spp 22719,360
- 8403220274 Ack receipt of 840111 response to 830615 ltr re exploratory shaft const & easling.List of requested refs entl. LINEHAN, J J. Repository Projects Brench (Post 831001), 00401, 84702/29 NEFF, J. Q Energy, Dapt of 4pp 22723 315

- B403220277 Forwards Hydrology Team proposed action plan for reviewing data on salt hydrology prior to environ assessment release Comments requested by B30227 CDDKE, B A Geotechnical Branch (Post B31001) 00403 B4/02/21 JDHNSON.R L Repository Projecte Branch (Post B31001) 2pp 22723 311
- B403220303 Forwards description of hydrogeological exploration test program per B40223 telcon Meeting should be deferred until after exploration program initiated in late Mar MATHEMS M L. Energy, Dept. of B4/03/02 HIGGINBOTHAM, L. Low-Level Maste & Urenium Recovery Projects Branch 14pp 22730 344
- 8403230025 Comments on petition for rulemaking re DOE guldelines for recommendation of sites for nuclear waste repositories Concurs w/seven points in preliminary decision FRISHMAN,S Texas, State of 49FR9550 004 84/03/19, CHILK,B J Office of the Secretary of the Commission 1p. 22728-349,
- 8403230030 Suppls comments on petition for rulemaking re DDE guidelines for recommendation of sites for nuclear weste repositories. Requests serious action be teken on DDE failure to provide peer environ program FINN, D F Affiliation Not Assigned 49FR650 003 84/03/17 Docketing & Services Branch 2pp 22724 333.
- 8403230050 Comments on petition for rulemaking re compliance w/DDE guidelines for recommendation of sites for nuclear waste regositories Generally supports Commission position.

 JTM.R. Yakime Indian Nation 49FR9650 005 84/03/20.

 PALLADINO.N J Commissioners ip 22726 343.
- 8403230188 List of State of WA Dept of Ecology high level nuclear waste mpt legislative proposals as of 840302 # Washington, State of 00695 84/03/02 2pp 22759:119
- 8403230193 Forwards documents re high level nuclear waste repository issue.per 840206 request Clerification of same documents listed W/o encl MATEGN.D R Policy & Program Control Branch (Post 831001) 00394 84/02/24 DRIVER.D M Utah, State of 2pp. 22741 361
- B403230245 Forwards agenda for NRC/DDE B40313-15 briefing on geological sciences investigation in Richland, WA OLBON, O L Energy, Dept of 00694 B4/03/01, WRIGHT, R J Repository Projects Branch (Post B31001) 4pp 22741 357.
- 8403230250 Summary of State of WA High Level Nuclear Weste Advisory Countll 840120 meeting w/listed attendees re forthcoming public info program w/Ofc of High Level Nuclear Waste Mgt * Washington, State of 00686 84/01/20. Washington, State of 35pp 22739:327
- 8403260043 Informs that preliminary version of NUS topical rept, "Qualifications of Cament Solidification Process for Stabilizing Waste Forms," cannot be processed for detailed review due to absence of incomplete info HIGGINDOTHAM.L Low-Level Waste & Urenium Recovery Projects Branch. WM-84047 84/02/17 POMELL.R. NUS Corp 1p 22769-296.
- 8403260344 Summarliee 840123-26 data review vieit at site Review process consisted of conveying preliminary observations, review & analysis of data & performance of censitivity analyses & analysis of test data NATARAJAM & Engineering Branch (Post 831001), 84/02/27 HRIGHTR J Repository Projects Branch (Post 831001) Sipp. 22775 313
- --BA03260347 RHO-BH-8A-286 P
 "Design & Const of Block Test in Closely Jointed Rock "
 BLACK, M T , CRAMER, M L Rockwell International Corp 83/06/30
 124pp 22776,034
- ---8403260350 Forwards data obtained or requested from DDE during 840124-26 data review visit RAJARAM,V Engineers Internetional, Inc. 84/01/31, SEAMANS,T, Engineering Branch (Poet 831001) 19pp 22776,161
- ---8403260333 Forwards draft rock mechanics data review checklist.FORTRAN listing of algorithm to calculete displacements from extensometer deta & sample input data instruction for plots generated by data aquisition eys.

 WAHI.K.K Samdia Laboratoriee 84/01/31 NATARAJA, N. S.
 Engineering Branch (Post 831001) 49pp 22776 180.
- B403280253 Trip rept of attendance at Third Workshop on Region-to-Area Screening Methodology for Crystalline Repository Project on B40221-24 in Atlanta. GA. Registration list and LOGBODN, M J Repository Projects Branch (Post B31001), MATTSON, D R. Policy & Program Control Branch (Post B31001) B4/03/07 BROWNING.R E Division of Waste Management 10pp. 22808-190.

- 8403280254 Forwards draft ltr incorporating conclusions & recommandation re technical assistance to State DF MA on NUPAC high integrity container design Add1 info required recorrosion performance of F255 welds & pitting corrosion H1091NB0THAML Low-Level Waste & Urenium Recovery Projects Branch 84/02/16 NUSSBAUMER.D Assistant Director for State Agrasments Programs 7pp 22808 182
- 8403280257 Trip rspt of attendance at 8ixth Symposium on Mgt of U Mill Tailings.Low Level Waste & Hazardous Waste on 840201-03 in Fort Collins.CD Agenda sncl FEARRING.J R Engineering Branch (Post 831001) B4/03/06 GREEVES.J T Enginsering Branch (Post 831001), 7pp 22808 175
- B403280259 Trip rept of perticipation et working session on DDE UMTRAP document, "Vicinity Properties Mgt & Implementation Manual "FLORY, C. Low-Level Waste & Uranium Recovery Projects Branch 84/03/07 HQ01N80THAM, L. Low-Level Weste & Uranium; Recovery Projects Branch. 4pp 22808:173.
- 8403280267 Forwards info re gsotechnical engineering topics suggested for consideration in development of UMTRAP remedial ection plans. Plan should include sufficient info to indicate that bases for conclusions & findings are well founded OREEVES. J T Engineering Brench (Post 831001) 84/03/02 HIGGINBOTHAN.L. Low-Level Wests & Uranium Recovery Projects Branch. App 22808.077
- B403270316 Comments on petition for rulemeking rs DOE gameral guidelines for racommendation of sites for nuclear waste repositories. NRC concurrence decision offers some improvament to DOE guidalines KALITOMSKI.T Hinnesota, State of 49FR9650 006. 84/03/20 PALLADINO,N 8. Commissioners. 3pp 22802 062
- 8403300239 Forwards K Schmadsr 840119 ltr to prospective offerors re Amend 1 to RFP E512-08400R & cover ltr & std order for work dtd 831230, W/O sncl, NEFF, J. D. Energy, Dept of 00057 84/03/14 LINEHAN, J L Repository Projects Branch (Post 831001) 2pp. 22842, 344
- 8403300243 Requests listed documents to BMIP be forwarded to Yakima Indian Nation. TOWSELY, D.R. Harmon & Weiss 00703 84/03/08 BUNTING, J Division of Weste Menegement. 2pp 22840,359.
- 8403300248 Rev O to Procedure 8D-BHI-PHP-003, "Project Mgt Plan For Hydrothermal Testing of Wests-Barrier-Rock Interactions Using Fully Radweste Project "DE-U,R.A Rockwell International Corp EVANS,E.A Westinghouse Electric Corp CHIKALLA,T.D Battelle Memorial Institute, Pecific Northwest Laboratories 00709 02/10/31 67pp 22840 281

XPORTLIC EXPORT AND IMPORT LICENSES

- 8402020431 Amand 2 to Edlow Intl Co export license, extending expiration date to 860101 PETERBONNH R Assistent Director for Expurt/Import & International Sefeguerds. 84/01/16, 1p 22062*182.
- B403010084 Application to amend expert llcense, extending expiration date to B70331.

 WILBON, B. D. General Electric Co BDM-13-84. B4/02/06. HEMBY, E 0 Office of International Programs. Director 1p 22479:336.
- 8403010338 License for Mitsui & Co. Inc to export 189,750 lbs Zr-2 & Zr-4 trex to Japan
 ZINHERMAN, J. V. Assistant Director for Export/Import & International Safeguards 803-236. 84/02/24. 1p. 22449 355
- 8403010346 Licenss for Westinghouss to sxport ons proportional countsr.
 Type 23744 to Francs
 ZIMMERMAN.J V. Assistant Director for Export/Import & International
 Bafeguards. ZE 40170. 84/02/21. ip 22449.352.
- 8403010364 License for Sandyik Special Metals Corp to export 200,000 lbs Zircalou 4 part pilgered cladding to Cameda. ZIMMERMAN.J. V Assistant Director for Export/Import & International Safeguards. SSN-31016. 84/02/21 ip. 22479-173.
- 8403010369 License for Westinghouse to export six compensated isnization chambers. Type 23944, to France.
 ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safsguards ZE 40189, 84/02/21, ip 22449:362.
- 8403010418 Amend i to Reactor Experiments, Inc suport license, increasing quantity of U-235 to 15 g & U to 16.84 g ZIMMERMAN, J. V Assistant Director for Export/Import & International Bafeguards 1464 84/02/24, 1p 22449:335.

- B403010421 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
 ZIMMERMANJ V Assistant Director for Export/Import & International Bafeguards B4/02/23 STOIBER, C.R. Btate, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 1p 22449 334
- 8403010425 License for Westinghouse to export four sirconium fuel tubes, top end plugs, bottom end plugs & stainless steel springs to Belgium 21MMERMAN, J V Assistant Director for Export/Import & International Safeguerds MMH~453 84/02/21 1p 22449 333
- 8403010432 License for Mitsui & Co.Inc to export 164,430 lbs Ir-2 trex to Japan ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards 803-230 84/02/24 ip 22449 322
- 8403010454 Forwards application to export 200 Zircaloy channel blank strips to Japan BTREET.L L Edicw International Co WUI 64387 84/02/16 MOURE.N NRC - No Detailed Affiliation Given ip 22444 047
- --8403010454 Application for license to export 200 Zircaloy channel blank strips to Japan BTREET, L Edlow International Co ABEA 84/02/15 lp 22444 OA8
- B403010459 Application for licenss to export 10 kg thorium fluoride powder, containing 7 54 kg thorium to Italy CDLTON.E Cerac, lnc B4/02/15 HEMBY, E NRC No Dstailed Affiliation Given lp. 22444 066.
- 8403010463 Application for licens to export three BF3 proportional counters, two compensated ion chambers & two startup assembliss to Switzerland.
 HEETHER, W H Wastinghouse Electric Corp ZE 10597 84/02/21 19
- 8403010464 Ltr of assurance rs export of 13 g U-235, contained in 325 g U, to Japan U, to Japan SHIRAKAWA, T Japan, Govt of 84/02/08 RAYMOND, J F Energy, Dept. of ip. 22443 301.
- 8403010465 Forwards application to export 571 kg U-235, enriched to 3 40% U hexafluoride, to Japan SkiMA: S Mitsubishi International Corp. (subs of Mitsubishi Corp.) 84/02/10. Assistant Director for Export/Import & International Bafeguards 2pp 22443 298
- --8403010468 Application for license to export 751 kg U-235, enriched to 3 40% U hexafluoride to Japan 8H1NA, 8 Mitsubishi International Corp (subs of Mitsubishi Corp) 84/02/21 jp 22443 300.
- 8403010466 Forwards application to export 20 g Pu (mstel) to Japan NAKAMURA:N Harubeni America Corp (subs of Harubeni Corp) 84/02/15 WRIOHT:B L Assistant Director For Export/Import & International Safeguards 1p 22438 286
- ---B403010467 Application for licenss to export 20 g Pu (metal) to Japan End use statement encl YAMADA.K. Herubeni America Corp (subs of Marubsni Corp) ZH--0119 B4/02/15 3pp. 22438-287
- 8403010470 Forwards application to export slightly shriched U hexafluoride to Japan BHIMA:B Mitsubishi International Corp (subs. of Mitsubishi Corp.) HBA-5483-10. 84/02/10 Assistant Director for Export/Import & Intsrnational Sefeguerds. 2pp. 22443-295
- --8403010473 Application for licanse to export 583 kg U-235, enriched to 3,40% U hexafiluoride, to Japan 8HIMA, 8 Mitsubishi International Corp (subs. of Mitsubishi Corp.). H8A-5483-10. 64/02/10 ip 22443:297.
- 8403010471 Ltr of assurance re export of 302 kg U-235,containsd in 9,993 kg U-to Japan SHIRAKAHA,T Japan, Govt of, 84/02/22, RAYMUND,J.F Energy, Dept. of 1p. 22438 362
- B403010478 Application to amend export license.sxtending expiration date to 870331.
 WILSON.B.D General Electric Co. BDW-12-84. 84/02/06 HEMBY.E O Office of International Programs, Director. 1p. 22438:361

- 8403Bi0479 Requests Executive Branch position re Nissho Iwai American Corp application for amends to licenses to export increasing quantity of U authorized for export to Japan ZIMBEMAN.J V Assistant Director for Export/Import & International Safeguards 84/02/17 870IBER.C State, Dept of, Bureeu of Oceans & Intl Environ & Scientific Affairs 1p 22443 287.
- 8403010484 Application to amend export licenses, increasing quantity of Australian origin hexafluoride, contained in fuel rods/assys, for export to Korea HERSCH.M M Westinghouse Electric Corp. MMH-460. 84/02/17 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 2pp 22438 304
- 8403010487 Ltr of assurance re application for amend to license to export 16 84 g high enriched U metal.containing 15 7 g U-235 to Japan SHIRAKAMA:T Japan, Govt. of 84/02/22 RAYMOND, J.F. Energy. Dept of 1p 22438 360
- 8403010490 Application for license to export 002 g CF-252,ta India BENSON E C Isotope Products Laboratories H/O 10274 83/11/02 ip 22438 359
- 8403010491 Requests Executive Branch position re 840221 application for license to export 1.000.000 Ci tritium in bulk gaseous form, to United Kingdom W/o encl ZiMMERHAN, J V Assistant Director for Export/Import & International Safeguards 84/02/23 STOIBER, C R State, Dept. of, Bureau of Oceans & Intl Environ & Scientific Affairs. 1p 22438,358
- 8403010495 Forwards application for export license for minor nuclear export to Canada Ltr of assurance required W/o encl ZBMMCRMAN, J V Assistant Director for Export/Import & International Safeguards 84/02/24 RAYMDND, J Energy, Dept of 1p 22438 357
- 8400010497 Application for license to export 25 pieces of zirconium tubing mat1 to West Germany WILSBN BD General Electric Co BDM-28-84. 84/02/16 1p 22498 356
- 8403010502 Advises that Westinghouse 840221 application for license to export miscellaneous fuol assembly components to Italy for weld qualification tests issued w/o normal 15-day waiting period ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/02/24 Assistant Barbards 84/02/24 Assistant 84/02/24 Assistant 84/02/24 Assistant 84/02/24
- B4U30i0505 Application for license to export 150 kg U dioxide:as powder or pellets,to Taiwan # General Electric Co BDW-27-84 84/02/14 1p 22438 307
- 8403010312 Forwards application to export 322 kg U-235, enriched to 2 40% U hexafluoride, to Japan 8HIMA,8 Mitsubishi International Corp (subs of Mitsubishi Corp) 84/02/10 Assistant Director for Export/Import & International 8afeguards 2pp 22438 336
- --8403010517 Application for license to export 322 kg U-235, enriched to 2 40% U herefluoride to Japan SHIMA, S Mitsubishi International Corp (subs of Mitsubishi Corp) H9A-3483-08 B4/02/01. ip 22438 338
- 8403010522 Forwards newsletter on Omnibus sys describing GEDAC plant monitoring & display sys per 840208 discussion & 840201 application for export license W/o encl WILSON, B D General Electric Co. BDM-21-84 84/02/08 PETERSON, M R Office of International Programs, Director ip 22438 352
- --B403010546 Forwards application to export plant monitoring & display sys, consisting of three VAX & two GEDAC sys, to Finland. WILSON B D General Electric Co BDW-09-84 B4/02/01 WRISHT, B.L. Office of International Programs, Director ip. 22438 353
- --8403010350 Application for license to export plent monitoring & display sys, consisting of three VAX & two GEDAC sys, to Finland.

 # General Electric Co BDH-08-84. 84/02/01 ip 22438 354
- 8403010539 Application to amend export license, extending expiration date to 870930, increasing quantity to 150 pieces & changing sescription of equipment.
 WILSON B D General Electric Co. 84/02/17, HEMBY.E.O Office of International Programs, Director. 1p 22438 343

The same

- 8403010340 Application to amend export license, extending expiration date to 870331
 HILSON.B D General Electric Co BDM-11-B4 84/02/06 HEMBY.E C Office of International Programs, Director 1p 22438 351.
- B403010545 Application for license to export fuel assembly tubes, zirconium pluge, stainless steel springs & Incomel.to Italy HERSCH.M M Hestinghouse Electric Corp B4/02/23 1p 22443-302
- 8403020015 Forwards Transnuclear, Inc 840202 application for amend to export license increasing quantity to 1,348 354 kg U-235, contained in 36,643 kg U ZIMBERMANJ V Assistant Director for Export/Import & International Bafeguards 84/02/07 RAYMOND, J Energy, Dept. of 1p 22471 084
- ---8403020024 Application to amend export license increasing quentity to 1.348 354 kg U-235,conteined in 36,643 kg U HANNETT,B A Transnuclear, Inc. RBU-394. 84/02/02 MODRE,R.N. Diffice of International Programs. Director 1p. 22491;085
- 8403020077 Application for license to export miscellaneous designed primary pump components to Spain PEARSON. A Borg-Warner Corp 836-V-2258 84/02/06 ip 22491 188
- 8403020089 Application to amend export license, extending expiration date to 870331.

 HILSON: B D General Electric Co BDW-17-84. B4/02/06 HEMBY, E D Office of International Programs. Director ip 22491:183
- 8403020112 Forwards application to export spent nickel/U catelyst NUA-21; containing 7% U & 11% nickel/to Canada VANDERSEEO,F Parkans International, Inc. 84/02/14 MODRE,R.N. Office of International Programs, Director 1p 22491 177
- --8403020115 Application for license to export spent nickel/U cetalyst NUA-21.containing 7% U & 11% nickel.to Canada * Parkans International, Inc. 84/02/10 ip 22491,178.
- 8403020151 License for Westinghouse to export miscellanceous fuel assembly components to Italy ZIMMERNAN, J V Assistant Director for Export/Import & Internetional Safequards 84/02/24 ip 22491*156
- 8403020154 License for Teledyne Wah Chang Albany to export 60,000 ib ZirceIoy-2 trex to West Germany ZIMMERMAN.JV Assistant Director for Export/Import & International Bafeguards 3350 (JFM) 84/02/21 ip 22491,155.
- 8402020157 Application to amend license to export, increesing quantity by addI 250 kg & extending expiration date to 860501 LUCENA,S Interective Rediation, Inc 84/02/17 HEMBY, & O NRC No Detailed Affiliation Given ip 22491 149.
- B403020422 Application for license to export 164,450 lb Zr-2 TREX to Japan End use statement encl * Mitsui & Co , Ltd) 803-205. B4/02/03 2pp 22491 267
- 8403020428 Application for license to export compounds, containing deuterium, equivalent to 5 kg deuterium liquid over 2-yr period to India 8 Sigma Chemical Co. D-112 84/02/07 ip 22491,263
- 8403020451 Forwards application for export license for minor nuclear export. Ltr of assurance required IIMMERMAN, J V Assistent Director for Export/Import & International Befeguards. 84/02/10 BTAIBER, C R State, Dept of, Bureau of Oceans & Intl Environ & Bcientific Affairs 1p, 22491, 197.
- --8403020453 Application to amend export license, adding ATLAS, AS as fabricator/manufacturer of fuel elements. End use statement encl.
 HANNETT, B A Transnuclear, Inc. NUK-420. 84/02/02 MOORE, R. N. Office of International Programs, Director, 2pp 22491:198
- 8403050026 Amend 3 to GE export license, extending expiretion date to B70331 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards DDW 14-84 84/02/10 Ip 22476-345
- 8403050033 Application for license to export 187,750 lb Zr-2 & Zr-4 trpx to Japan.
 EJIHAM. Mitsul & Co. (USA), Inc (subs of Mitsul & Co., Ltd.).
 803-236 84/02/03 2pp 22527:330

- B403050036 Application to amend license to export, extending expiration date to B51231 MDZNIAK, D.R. Carpentsr Tschnology Corp. B4/02/01 HEMBY, E. Assistant Director for Export/Import & International Safeguards 1p. 22527
- 8403050039 Application to amend license to export extending expiration date to 870331

 HILSON B D General Electric Co BDW-15-84 84/02/06 HEMDY.E O OPPice of International Programs. Director ip 22027 328
- B403050044 Application for license to export two compensated ionization chambers, Tupe 6377, to France
 HEETHER, W H Westinghouse Electric Corp ZE40195 84/02/21 ip 22027.323
- 8403050045 Amend 2 to GE export licsnee, extending expiration date to 870331

 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguerds 8DW 17-84 84/02/10 ip 22527 322
- 8403050047 Application for license to export 3,233 kg U-235, contained in 97,957 kg U, to Belgium HERSCH, M, M Westinghouse Electric Corp MMH-455 84/0i/3i 19
- 8403050050 Application for licenss to export 225 kg U-235 as U oxide powder to Bslgium, HERSCH M M Hestinghouse Elsctric Corp MMH-454 84/01/31 1p
- 8403050188 Advises that Rauter-Stokss 840221 application for license to export two flasion country to Japan issued w/o normal 18-day waiting period ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/02/24 Assistant Director for Export/Import & International Safeguards 1p 22528 192
- 8403050190 Licsner for B&W to export 13 g U-235.containsd in 325 g U. to Japan. ZIMHERNAN,J V Assistant Director for Export/Import & International Safeguards. 84/02/28 2pp 22528 190
- 8403050193 Licanse for Byron Jeckson Pump Div to export miscellaneous specially designed primery pump components to Spain ZIMMERMAN, J. V. Assistant Director for Export/Import & International Sefsguards 836-V-2258 84/02/27 ip 22828:189
- 8403050209 License for Westinghouse to export three proportional counters, Model 6998, to Itely ZIMMERMAN, J V. Assistant Director for Export/Import & International Bafsguards ZE-40193 84/02/29 ip 22528 i51
- 8403050213 Amend 1 to licanse for GE to import 17 kg U.conteined in ,250 kg U-235 & 110 kg Pu metel clad fuel asgments, from Norway.
 - rormey. ZIMMERMAN, J. V Assistant Director for Export/Import & International Bafeguards 84/02/24, ip 22528 144
- 840305026i Application to amand licents to export sxtending expiration data to 870331.

 WILSON. B.D. General Electric Co RDW-16-84 84/02/06, HEMBY, E O Office of International Programs. Director 1p 22527 184
- 8403050276 Amend 2 to GE export license, extending expiration date to 870331.
 ZINNERMAN, J V. Assistant Director for Export/Import & International Safeguards. BDH-16-84. 84/02/10. ip 22501:186
- B403050282 Amend 2 to QE export literase, extending expiration date to B70331
 ZINMERNAN.J.V Assistant Director for Export/Import & International Sefeguards. BDW 12-84. 84/02/10 1p. 22501.187.
- 8403050286 Amend 2 to QE syport licenes, extending expiration data to 870331.
 ZIMMERMAN, J. V. Assistant Director for Export/Import & International 8afeguards EDW 12-84. 84/02/10 ip. 22501-206
- 8403050320 Forwards application for export license for minor nuclear export, Ltr of assurance required.
 ZIMMERHAN.J V. Assistant Director for Export/Import & International Bafeguards 84/02/28 RAYMUNDJ Energy. Dept of. 1p
- --8403050327 Forwards application for license to export 13,127 kg U, contained in 322 kg U-235, to Jepan.
 SHIMA: 8. Mitsubishi International Corp. (subs of Mitsubishi Corp.) HBA-3483-08, 84/02/10 Assistant Director for Export/Import & International Safeguards. 2pp 22501:276

- ---B403050333 Application for license to export 13.127 kg U.contained in 322 kg U-235.to Japan SHIMA.S Mitsubishi International Corp (subs of Mitsubishi Corp) 84/02/01 jp 22501 278
- 8403050358 Requests Executive Branch position re Narubeni America Co application for license to export 20 g fu to Japan ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/02/28 STOIDER.C R Energy, Dept of 1p 22501 339
- --8403050364 Forwards application to renew expired License XBNM-1617 to export 20 g Pu to Japan NAKAMURA: Maruben: America Corp (subs of Marubeni Corp) 84/02/15 WRIGHT: B L Assistant Director for Export/Import & International Safeguards ip 22501 340
- --8403050366 Application for license to export 20 g Pu to Japan NAKAMURA:N Harubeni America Corp (subs of Marubeni Corp) ZH-Q119 84/02/15 3pp 22501 341
- 8403030359 Requests Executive Branch position on NRD Div application for license to export 60.000 Ci tritium in bulk gaseous form to Sustrerland W/o encl
 ZIMMERMAN, V Assistant Director for Export/Import & International Safeguards 84/02/27 STOINER, C R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs ip 22501 337
- 8403050368 Forwards application for export license for minor nuclear export Ltr of assurance required ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards 84/02/28 RAYMDND,J Energy, Dept of 1p 22527 309
- --B403050373 Forwards application for license to export slightly enriched U hexafluoride to Japan SHIMA. 9 Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-19483-10 B4/02/10. Assistant Director for Export/Import & International Safeguards 2pp 22527 310
- ---8403030376 Application for license to export 16,684 kg U.contained in 383 kg U-233.to Japan SHIMA.8 Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-5483-10 84/02/10 1p 22327 312
- B403060035 Licanae for Mitsuí & Co.Inc to export 302 kg U-235.contained in 9.973 kg U.to Japan ZiMMERMAN.J V Assistant Director for Export/Import & International Safeguards MEK-2F1-R3 (B) B4/02/27 2pp 22528 329
- 8403040038 License for Reuter-Stakes, Inc to export two fission counters, Nofel R8-P4-0805-134, to Japan Zimmerman, J V Assistant Director for Export/Import & International Safeguards B-1053 84/02/24 ip 22847 343
- 8403060075 Application to amend license to export increasing quantity to 22,560 kg U for export to Hest Germany DUB018, D European Communities. Commission of RBU-428 84/01/20 RAYMOND, J Energy, Dept of 1p 22528 292
- 6403040087 Forwards Westinghouse 840221 ltr withdrawing application for license to export four fission chambers to Argentine IIMMERMANU V Assistant Director for Export/Import & International Safeguards 84702/27 STOIBER.C R State, Dept of, Bursau of Oceans & Intl. Environ & Scientific Affairs ip 22528 287
- B4030403549 Requests waiving 15-day waiting period to expedite issuance of export license as shipment scheduled for B40301 PDHELL.C Reuter-Stokes, Inc 84/02/21 HENDY.E. NRC No Detailed Affiliation Civen 1p 22352 239
- --8403060573 Application for license to export 2 Model RB-P0-0905-134 fission counters to Japan POWELL.C Reuter-Stokes, Inc B-0153 64/02/21 19 22552 260
- 8403070004 Amend 2 to QE export literate extending expiration date to B70331
 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards. BDW 13-84 84/02/10. 1p. 22562 353
- 8403070353 Application to amend export license, extending expiration date to 870331. WILSBN,B D General Electric Co. BDH-14-84 84/02/06 HEMSY,E O , Office of International Programs, Director, 1p 22564 316.
- B403070377 Forwards Westinghouse B40217 epplication for amend to export license Assistance in obtaining required approvals per US/Australian Agreement requested ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards. B4/02/27. HART.T. Energy, Dept of 1p 22567-194

- --8403070381 Requests assistance in obtaining ltr of assurance from Australia to reexport Australian-origin mat! HERSCH.M M General Electric Co MMH-460 84/02/17 ZIMECRNAN.J V Assistant Director for Export/Import & International Safeguards ip 22567 195
- 8403070424 Forwards application for export license for minor nuclear resource poweres application for export license for minor muclear export Ltr of assurance required LIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/02/28 RAYMOND, J Energy, Dept of ip 22066
- --8403070425 Forwards application to export slightly enriched U herafluoride to Japan SHIMA. S Mitsubishi International Corp (subs of Mitsubishi Corp | HSA-5483-11 84/02/17 Assistant Director for Export/Import & International Safeguards 2pp 22566 296
- --8403070426 Application for license to export 34.489 kg U herafluoride. contained in 1.104 kg U-235 to Japan SHIMA.5 Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-5483-11 84/02/17 2pp 22566 298
- 8403080115 Forwards application for export license for minor nuclear export Ltr of assurance required ZIMMERNAN, J V Assistant Director for Export/Import & International Safeguards 84/02/28 RAYMOND,T Energy, Dept of 1p 22581 358
- 8403140229 Forwards application for export license for minor nuclear export Ltr of assurance required
 71hMERNAN.J V Assistant Director for Export/Import & International
 Safeguards 84/02/06 STOIBER.C R. State Dept. op. Bureau of
 Oceans & Intl Environ & Scientific Affairs 1p 22637 350
- 8403140307 Forwards Transnuclear.Inc 840224 application to amend export license to include CERCA.Romano-sur-Isers.France.as intermediate consignee for fabrication of fuel slaments ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/03/07 STOISER.C State. Dept of Suresu of Greans & Intl Environ & Scientific Affairs ip 22635 313
- --8403140308 Application to amend license to include CERCA, Romano-sur-Isere, France, as intermediate consignoe for fabrication of fuel elements
 HANNLTT.8 A Transnuclear, Inc NUK-408 84/02/24 MDORE
 Office of International Programs, Director ip 22635 314 MOORE, R. N.
- 8403140315 Forwards Marubeni America Corp application to export 24,355 kg U hexafluoride.containing 717 kg U-235 to Japan Assistance in obtaining required approvals per US-Australia Agreement requested
 ZIMMERMAN.J V Assistant Director for Export/Import & International
 Safeguards 84/03/06 HART.T Energy, Dept of ip 22635 298
- B403150129 Informs that license for Nt. Industries. Inc to export 10,582 3 kg depleted U to Canada, issued u/o 15-day waiting period ZIMMERMAN, J V Assist Assist Assist Assistant Director for Export/Import & International Safeguards 84/03/01 Assistant Director for Export/Import & International Safeguards ip 22646 353
- 8403150134 Forwards application to export 15 kg U.enriched to 5% U hexaf]worlde.to West Germany HARMON.D W Brawnkoble Transport & Storage. Inc HEX-EX-4 84/02/28 WRIGHT.B Assistant Director for Export/Import & International Safeguards ip 22646 349
- --B403150142 Application for license to export 15 kg U.enriched to 5% U hexafluoride, to West Germany.
 HARMON.D W Braunkohle Transport & Storage, lnc HEX-EX-4.
 84/02/28 ip 22646 350.
- 8403150153 Application to amend export license, extending expiration date for 2 addi yrs
 MORGENSTERNA Sigma Chemical Co 84/03/01 HEMBY, E Assistant Director for Export/Import & International Safeguards ip 22646 352
- 8403150158 Application to amend export license, adding miscellaneous special designed primary pump components for export to Spain PEARSUN. A Borg-Warner Corp. 84/03/01 HEMBY NRC No Detailed Affiliation Given 1p 22446 351
- 8403150169 Application to amend export license, dtd 820713, to include CERCA, Romans-sur-Isere, as possible intermediate consignee for fabrication of fuel elements
 HANNETT, BA Transnuclear, Inc NUK-408, 84/02/24 MODRE, R. N. Office of International Programs, Director, Ip 22646 344.

- 8403150174 License for NL Industries, Inc to export 10,582 3 kg depleted U to Canada ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/03/01 2pp 22646 342
- 8403150195 Requests discontinuation of further investigation re export license Order canceled & export license no longer required TERMILLIGER, L. Westinghouse Electric Corp. B4/02/21 Assistant Director for Export/Import & International Safeguards ip 22646 265
- B403150197 Forwards application to export 3 9 kg natural thorium & 26 kg depleted U-238.as coated particles & oxide particulates to West Germany MOHRY.W R GA Technologies, Inc /General Atomic Co IEL-5086 84/02/29. ZIMMERMAN.J. HEMBY.E Assistant Director for Export/Import & International Bafeguards ip 22646 263
- --8403150199 Application for license to export 3 9 kg netural thorium & 26 kg depleted U-238, as coeted particles & oxide particulates, to Nest Germany HORRY.H R GA Technologies, Inc /General Atomic Co IEL-5086 84/02/29 ip 22646 264
- B403150241 License for CERAC, Inc to export 7 540 kg thorium, contained in 10 00 kg thorium Fluoride powder, to Italy ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguerds TLX 8427 84703707 2pp. 22649 352
- 8403160169 Forwards application to export 2,002 mCi Cf-252 in cormet wire to France HANNETT, B A Transnuclear, Inc TNP-443 84/02/29 MOORE, N Office of International Programs, Director ip 22662 263
- -- 8403160184 Application for license to export 2,002 mCi Cf-232 in cermet wire to France HANNCTT, B A Transnuclear, Inc TNP-443 84/02/29 ip 22662 264
- 8403200305 Ltr of assurance notifying that employer name changed from Elsinore Shipyard to Atlas AS Installation & personnel identical
 DUBOIS.D European Communities, Commission of 84/03/05 NEAL
 Assistant Director for Export/Import & Internetional Safeguards
 82709 169
- B403200371 Hithdraws application for license to export 29,33 g deuterium to South Africa NOVAKOVICH D Air Products & Chemicels, Inc. 84/02/28, MARTIN, N Assistant Director for Export/Import & International Safeguards, 22708 350
- B403200373 Application for license to export 31,000 lb depleted U tetrafiuoride.containing 23,281 lb depleted U to Canada POTTER.A NL Industries. Inc B4/02/27 MOORE,N Assistant Director for Export/Import & International Safaguards 1p 2270B 344
- B403200392 Informs that License XBNM-2098 mey be issued. No math changed circumstances since issuance of License XBNM-2097 MODRE, IR N. Assistant Director for Export/Import & International Bafeguards 84/02/22 Assistant Director for Export/Import & International Bafeguards 1p 22708:309,
- 8403200375 Executive Branch position re Westinghouse application to export io g U-235 contained in 220 g U to Spain License should be issued should be issued
 DEVINE.J B Blate. Dept of, Bureau of Oceans & Intl, Environ &
 Scientific Affairs 84/03/06 BHEALJR Diffice of International
 Programs. Director 4pp 22708 305
- 8403200396 License for Natl Nuclear Corp to import 20 238 kg U, enriched to 4% U-235, from United Kingdom ZIMMERMAN.J Assistant Director for Export/Import & International Safeguerds 84/03/09 ip 22708 304
- 8403200378 License for Braunkohle Transport USA to export 15 kg
- 8403220197 Ltr of assurance re export of 757 kg U-235, contained in 21.932 kg U to Japan SHIRAKAMA: T Japan: Govt. of 84/02/28 RAYMOND: J. F Energy, Dept of 1p. 22723 278
- B403220201 License for Westinghouse to export two compansated ionization chambers, Type 6377, to France ZIMMERMAN, J V. Assistant Director for Export/Import & International Bafeguards, ZE40195 B4/03/20 ip. 22723,277

- 8403220230 Ltr of assurance re export of 15 kg U-235, contained in 307kg U, to the Netherlands, United Kingdom, France & West Germany DUBOIS, D European Communities, Commission of HEX-EX-4 B4/02/28 RAYMOND, J Energy, Dept of 1p 22723 353
- 8403220264 Consents to proposed retransfer of nuclear matl to Japan Guestions whether matl is of South African or Australian origin ODRDON, R. Australia, Govt of 84/01/03 NIELBEN, C. Office of Nuclear Material Safety & Safeguards, Director HART, T. Energy, Dept of 1p 22723 322
- 8403220279 Consents to proposed retransfer of nuclear math to Japan Ouestions whether math is of South African or Australian origin GORDON, R. Australia, Govt of 84/01/03 NIELSEN, C. Office of Nuclear Material Bafety & Safeguards, Director HART, T., Energy, Dept of 1p. 22723 310
- B403220203 Amend 2 to GE export license, increasing quantity to 150 pieces irronium tubing, revising description of matl & extending expiration date to B70930 ZIMMERMAN, J. Assistant Director for Export/Import & International Bafeguards BDH-26-84 84/03/08 1p 22723 309
- 8403220284 Ltr of assurance re export of 3 9 kg natural thorium & 0 26 kg depleted U-238, to West Germany DUBOIB.D European Communities. Commission of IEL-8594 84/03/07 RAYMOND, J Energy. Dept of 1p 22723 308
- 8403220286 Amend 1 to Interactive Radiation, Inc export license, increasing quantity to 250 kg deutertum oxide
 ZIMMERMAN, Assistant Director for Export/Import & International
 Safeguards 8L-4-81 84/03/07 ip 22723 307
- 8403220289 Forwards application for amend to export licenses for minor nuclear export Ltr of assurance required ZIMMERHAN, J Assistant Director for Export/Import & International Bafeguards 84/02/27 HART, T Energy Dept of ip 22723 303
- --8403220294 Requests authorization to reexport Australian origin U hexafluoride to permit export license amend request to increase quantity of matl to be processed HERSCH,M M Westinghouse Electric Corp MMH-460 84/02/17 ZIMMERMAN,J Assistant Director for Export/Import & International Safeguards 1p 22723 304
- 8403220297 License for QA Technologies, Inc to export 3 9 kg natural thorium & 0.26 kg depleted U. to West Germany ZIMMERMAN, J Assistant Director for Export/Import & International Bafeguards 1EL-5086 84/03/09 ip 22723 348
- 8403220304 License for GE to export R5 pieces :irconium tubing matl to West Germany ZIMMERHAN, J Assistant Director for Export/Import & International Bafeguards BDM-28-84 84/03/08 ip 22723 342
- 8403220314 License for Parkans Intl. Inc to export 15,876 kg natural U. contained in matl to be smelted for recovery of spent nickle content only, to Canada.

 ZIMMERNAN, J. Assistant Director for Export/Import & International Safeguards PISC-711 84/03/08 ip 22723 337
- 8403220315 License for Westinghouse to export three proportional counters two compensated ionization chambers & two startup assemblies to Switzerland ZIMMERMAN.J Assistant Director for Export/Import & International Safeguards 84/03/09 ip 22723 345
- 8403220322 Forwards application to export Pu, containing approx 10-12X weight Pu-240, to Switzerland CEJA, S N Energy, Dept of 84/03/02 Assistant Director for Export/Import & International Safeguards 1p 22723 349
- --8403220324 Application for license to export Pu.containing approx 10-12% weight Pu-240.to Switzerland CEJA.8 N Energy. Dept of. 79/12/20 ip 22723 350
- B403220328 Application for license to export five Model RS-GA-1100-241 local power range assemblies to Sweden POWELL, C Reuter-Stokes, Inc. B-0152 B4/03/02 ip 22723; 351
- 8403230179 Discusses QA Technologies, Inc 840227 application for export license to return small quantity of source meth to West Germany License issued w/o normal 15-day waiting period. ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/03/09. Assistant Director for Export/Import & International Safeguards, ip 22743 347

- 8403260011 Application to amend export license.adding NUKEM 0mbH & CERCA as intermediate consignees
 DUBDIS.D European Communities. Commission of NUK-408 84/02/24
 RAYHDMD.J Energy, Dept of ip 22763 332
- 8403260027 Forwards application to export 10 504 kg U-235, contained in 52 650 kg U-to various EURATOM countries

 HANNETT, B A Transnuclear, Inc NUK-442 84/03/05 MODRE, N

 Office of International Programs, Director 1p 22763 302
- --8403260030 Application for license to export 10 504 kg U-235.contained in 52 650 kg U, to various EURATOM countries End use statement encl
 HANNCTT.B A Transnuclear, Inc MUK-442 84/03/05 3pp 22763 303
- B403260037 Forwards application to export 24.830 kg U,enriched to 3 80% U-235 to Taiwan
 MIEL OR Exxon Nuclear Co . Inc (subs of Exxon Corp) 84/02/23
 ZIMBEL Assistant Director for Export/Import & International
 Bafeguards 1p 22763 300
- --B403260042 Application for license to export 24,850 kg V.enriched to 3 BOX U-235, to Taiwan KIEL,0 R Exxon Nuclear Co , Inc (subs of Exxon Corp) B4/02/24 ip 22763 301
- 8403260041 Ltr of assurance re export of 1,109 kg U-235, contained in 32,123 kg U. to Japan BHIRAKAWA.T Japan, Govt of 84/02/28 RAYMOND, J F Energy, Dept of 1p 22763 297
- 8403260390 Ltr of assurance re export of 749 kg U-235.contained in 21.688 kg-U.to Japon BHIRAKAWA.T Japon. Oovt of 84/02/28 RAYMOND.J C Energy. Dept of ip 22773 235
- 8403280050 Forwards application for export license for minor nuclear export Ltr of assurance required ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/03/13 RAYMOND, J Energy, Dept of 1p 22812:346
- --B403280099 Application for license to export 92 650 kg U.in form of UF6, to EURATOM countries End use statement encl HANNLTT, B A Transnuclear, Inc. MUK-442 84/03/05 3pp
- B403280057 Application to amend license to reexport three i 5 microgram sources of CF-292 to Israel RAVENSCROFT.N Edlow International Co 84/03/07 HEMBY.E Assistant Director for Export/Import & Intornational Safeguards 1p 22812 345
- B403280072 Executive Branch position re QE application to export U densitometer.w/Cs-137 source, for use in automatic measurement of fuel pellet density, to Spain Liconse should be granted DEVINC.J B State, Dopt of Bureau of Oceans & Intl. Environ & Brientific Affairs 84/03/12 SKEA.J R Office of International Programs, Director 1p 22811 360
- 8403280147 Forwards Air Products 840228 Itr advising that export license for proposed shipment of deuterium of Bouts Africa prigin no longer required ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards 84/03/08 87018ER.C R State, Dept of, Bureau of Oceans & Intl Environ & Boientific Affairs 1p 22809 329
- --8403280151 Informs of withdrawal of export license application for shipment of 29 23 g deuterium to Bouth Africa.
 NOVAKOVICH, D. Air Products & Chemicals, Inc. 84/02/28 MARTIN, N. Assistant Director for Export/Import & International Safeguards 1p. 22809-330
- 8403280k30 License for Mitsubishi Intl Corp to export 749 kg U-235, contained in 21,688 kg U, to Japan ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards MBA-5483-04. 84/03/13 3pp 22789 357
- 8403280252 License for Reuter-Stakes Inc to export five Model RS-PG-0805-134 fission counters to Finland ZIMMERMAN.J V. Assistant Director for Export/Import & International Safeguards B-0046 84/03/13 ip. 22808 201,
- 8403280272 License for Mitsubishi Intl Carp to export i 109 kg U-235, contained in 32,123 kg U, to Japan ZIMMERMAN,J V Assistant Director for Export/Import & International Bafeguards H8A-5483-05 84/03/13 3pp 22808-065

- B403280327 Amend 1 to Transnuclear Inc export license increasing quantity of U-235 to 793 3735 kg. contained in 22:560 kg U ZIHMERMAN J V Assistant Director for Export/Import & International Safeguards RBU-428 84/03/12 1p 2279 359
- 8403280337 Informs that Amend I to License XSNM-2002 may be issued No matl changed circumstances since issuance of License XSNM-2043 MOORE.R N Assistant Director for Export/Import & International Safeguards 84/03/02 Assistant Director for Export/Import & International Safeguards 1p 22799 356

- 8403290129 Discusses Natl Nuclear Corp 840217 application for license authorizing import of up to 20 258 kg U.enriched to 4 0% U-225. From United Kingdom License should be lesued MDGRE, R N Assistant Director for Export/Import & International Safeguards 84/03/08 Assistant Director for Export/Import & International Safeguards ip 22822 218
- 8403290325 Requests Executive Branch position re Exxon Nuclear Co. Inc application for license to export SNM to Taiwan IlMMERNAN.J V Assistant Director for Export/Import & International Safeguards 84/03/09 STDIBER.C R State, Dept of, Bureau of Oceans & Int) Environ & Scientific Affairs 1p 22822 219
- 8403270327 Application for license to export 2.133 pieces Zircaley-4 thimble & instrument tubes to Japan DANGERTER.D H Sandvik Special Hetals Corp SSM-41095/41098 84/03/04 2pp 22818 341

- 8403290403 Forwards Mitsubishi Intl Corp 840217 application for license ROJEVOROS Forwards hitsubishi inti corp MAGZI application for licens, to export Australian origin mati to Japan Requests assistance in obtaining required approvals, per US-Australia Agreement for Feaceful Uses of Nuclear Energy ZIMMERMAN, J.V. Assistant Director for Export/Import & International Mafeguerds 84/03/12 HART, Y Energy, Dept of IP 22818 356
- 8403290404 Forwards ltr of assurance re export of five fission counters to Finland STDIBER.C.R State, Dept of, Burfau of Oceans & Intl Environ & Scientific Affairs 64/03/08 ZIMMERNAN.J V Assistant Director for Export/Import & International Bafeguards 2pp 22822 188
- ~-8403270405 Ack receipt of retransfer assurance from Govt of Finland re expert license application Due to error in translation, word "retransfer" was replaced w/ "retransformation" HEMBY.E O NRC No Detailed Affiliation Given 84/03/07 NRC No Detailed Affiliation Given ip 22822 190
- 8403300311 Informs that license to export UFA heels to EURATOM countries being issued w/o 15-day waiting period ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/02/29 Assistant Director for Export/Import & International Safeguards 1p 22840 362

1

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AADLAND, J D	8403170246*	TOPREP	ANDERSON, C J	8403070242#	50~387 0	AXELRAD, J	8403190335	40-8681
AAMODT, N D	B403130013	50-287 @	ANDERSON, C J	#E403070043*	50-354 Q	AXELRAD, J	8403220075	50-220 8
AAMODT, N O	8403220242	50-287 0	ANDERSON, C J	8403220091*	50-277 Q	AXELRAD, J	8403270114	50-237 Q
ABELSON, H I	8403300250	50-333 P	ANDERSON, C J	B403290071*	50-271 Q	AXELRAD. M	8403300272	50-344 Ø
						AXELRAD, M	8403300272	50~344 G
ABELSON, H. I	B403300252	50-333 P	ANDERSON, C K	8402030344*	50-206 F	WELKWA! U	540330027E	20-244 6
ACGUARIO, W J	8403040226*	50-322 T	ANDERBON, C R	B4030&012&*	50-244 P	AXELROD, D	8403020233	50-322 0
ACGUARIO, W J	8403060246*	50-322 T	ANDERSON, J J	8403260091	50-264 8	AXELSON, W	8403200284	IFE
ADAM, W. J	8005280998*	FOIA	ANDERSON, J J	8403260257	50-286 5	AXELBON: W	8403300045	I&E
ADAM, W J.	8403080108*	FOIA	ANDERBON, M T	8403270181*	50-282 G	AXELSON, W L	8403010336	50~454 Q
ADAMS, F T	8403080223*	50-316 P	ANDERSON, P H	8403020182	50-400 G	AXELSON, W. L.	8403060185	50-263 F
ADAMS, R.E.	8403150219	NUREO	ANDERBON, P H	8403020192	50-40D Q	AXELSON, W L	8403080088	50-305 F
		50-336 P		8403020188*	50-400 Q	AXELBON, W. L.	8403080257	18E
ADATO, M	8403080344		ANDERSON, P H.			AXELBON W L	8403130145	50-331 F
ADENBAM, E,	8403010285*	50-327 A	ANDERSON, P H	840302018B*			8403190211	50-182 G
ADENBAM, E &	8105180434*	50-460 A	ANDERSON, P H	8403130156	50-400 G	AXELBON W L		50-102 G
ADENSAM, E Q	8202180456*	50-460 F	ANDERSON, P H	Ø40313015A	50-400 Q	AXELBON, M L	8403170239+	20-331 d
ADENSAM, E Q.	8202260171*	50-460 C	ANDERSON, R B.	#403070032#	CONTRACT	AXELSON, W 1.,	8403240019	50-346 Q
ADENSAM, E O	8302250083*	50-513 A	ANDRUS, N J	8403200325*	40-4492	BADE, K	8403010098*	CONTRACT
ADENSAM, E O.	8403120210	50~367 P	ANDRUS, N. J.	8403220045	40-4492	BACHMANN, R C	8403140077*	50-155 G
ADENSAM, E. C	8403120213*	50-349 P	ANSELL, E	8403080174	50-413 A	EACHMANN, R Q	6403190111	50-445 G
ADEB, M. J	8403080216*	50-316 P	ANTHONY R L	840317013R	50-352 0	DAER, R E	8403260250*	50-382 0
444T 4 TANE 1		FDIA			50-352 G	DAER, R. L	8203120197*	FOIA
AHEARNE, J	8403050042*		ANTHONY R L	8403190132		BAER, R. L.	8403010272*	FOIA
ALBERT, W. O	8402140036*	50~528 Q	ANTHONY R L	Ø40319013B≭	50-352 0		8403220010*	50-272 G
ALBERTIN, R D	8403060226*	50-322 T	ANTHONY R L	B403190138*	50-352 0	DAILEY, R J		
ALBERTIN, R D.	8403060246#	50-322 T	ANTHONY, R L	8403190142#	50-353 G	DAIR. O	8403010355	
ALDEN: W. M	,B403050117	50-277 R	ANTHONY, R L.	#403190142*	50-353 G	BAIR, Q	8403240214	50-344 9
ALDEN, W. M.	8403170178	50-277 R	ARCHITZEL, R	B403220103*	50-309 G	BAIRD, J B.	#403130402*	50-313 0
ALESSI, T A.	8403060177*	50-341 Q	ARIAB, J.	8402270125	50-250 B	BAIRD. J II	8403190288*	50-313 Q
ALEBBO, H P	8303080290#	50-286 P	ARIAS, J	8403160069	50-251 8	BAKANAUSKAS, J	8403140172	PR
ALEBSO, H. P.	8403050029*	50-286 P	ARIAB. J	8403220104	50-250 8	BAKANAUSKAS, J	8403270321	PR
ALESSO, H. P	8403050035*	50-286 P	ARLOTTO O. A	B403270018#	FOIA	DAKER, C	8403280110	50-250 F
		50-284 P	451 575 5 A	#40000004040.c	-0.1	DAKER.E	8403010430+	50-423 Q
ALEBBO, H P.	8403050038*		ARLOTTO, G. A	8403270048*	FOIA	BAKER, K R	8403200217	50-316 B
ALEXICH, H P	8403060191	50-316 P	ARLUTTO, O. A.	8403270068#	FOIA			50-318 B
ALEXICH, M. P	8403060195	50-315 P	ARTHUR, J	8402170325	HASTE MOT	DAKER, P E	8403230015	50-373 B
ALEXICH, M. P.	8403060315#	50-315 Q	ASH, E B	8403150315	HASTE MOT	BAKER, P. E	8403230017	
ALEXICH, M P.	8403080169	50-315 R	ASHBURN, D. J.	8403040347	TOPREP	DAKER, P. E	8403230027	50-373 S
ALEXICH, M, P	8403080214#	50~315 0	ASHBURN, D. J.	B403060375	TOPREP	DAKER, R	B403010241	50-333 \$
ALEXICH, M. P	8403130202	50-315 F	ASHBURN, D J	B403040377	50-397 J	BALCH, L.	8403300152	50-155 R
ALEXICH, M. P	B403160034	50-315 G	ABHE, F	8211110578	50-27 \$	BALCH, L. L	6403020088	50-155 R
ALEXICH, M P.	8403200210	50-316 P	ASHE, F	8211150076	50-272 B	BALDASSARRA, C	6403140180*	50-373 F
ALEXICH, M P	8403200223	50-315 P	ABHE, F	8403230125	50-317 B	BALDASSARRA, C.	#481041E04B	50-373 F
ALEXICH, M P	8403220040*	50-315 Q	ASHE, F.	8403230128*	50-317 8	BALDWIN, D. R	8403010442*	CONTRACT
		50-315 G			50-289 T	BALLARD, M F	8403200062*	50-217 0
ALEXICH, M. P	8403230138*		ABBELSTINE, J. K.	6403280160*		BALLARD, R. L.	8203150028*	50-460 C
ALEXICH M P.	B403260002	50-315 P	AULUCK, R.	8403050292	50-397 P			PR
ALEXICH, M. P	8403260178	50-315 F	AUSTIN, O.	8403190156	50-275 R	BALLENGER, V H	B403140154	50-29B R
ALEXICH, M. P.	B403270047	50-315 G	AUSTIN, P N.	B403010105*	FOIA	BALLINGER, P L.	8403020083	20"275 R
ALEXICH, M P.	8403270110	50-314 P	AXELRAD, J	8403010363	50-289 G	BALLINGER.P L	8403300150	50-298 R
ALLEN, M. T.	8403010135	50-324 8	AXELRAD, J.	B403010375	ILE	BANGERTER, D H	8403290327	XPORTLIC
ALLEN, M. T	8403210139	50-325 8	AXELRAD, J	8403050094	ILE	BARAKIA J.	B403170172#	50-329 A
ALLEN, R D	8403130244	QA999	AXELRAD, J.	8403060119	IAE	BARAN, R	B403020128	50-219 R
ALLENMAN, S. A	8403050253*	50-382 F	AXELRAD, J	8403080213	50-259 Q	BARAN, R.	8403300001	50-219 R
ALLODOD, Q. D	8403230057	NUREO	AXELRAD, J.	8403130408	1&E	DARI,R A	8403010041*	FOIA
		50-312 P				BARKHURBT.R P	8403050253*	50-382 F
ALTERMAN, I. B.	8009250345*		AXELRAD, J	8403130445	50-261 S 50-247 S	BARKHURST, R. P	8403240154	50-382 A
ANBORD, D A	#000010500#	COMMISSION	AXELRAD, J.	8403150073		BARNES, C	8403260134	40-1478
AMY, O. D	8403190234*	70-371	AXELRAD, J.	B403160001	I&E		8403190340*	0A777
ANDERSON, C.	B403160157*	50-272 G	AXELRAD. J	8403160051	50-931 9	BARNEB, I.	ロイクコエンクコイロル	V-1111

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION	BUBJECT CATEGORY
Darnes, I Darnes, P Darnes, P Darnes, P Darnes, P Darnes, P L	8403270241* 8403050119 8403260182 8403260196 8403270111	0A779 50-237 P 50-295 P 50-237 G 50-454 G	BAYNE, J P.	8403170294 8403200094 8403260171 8403270185 8403270100	50-286 F 50-333 P 50-333 P 50-333 F 50-286 P	BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W	8403130343 8403150136* 8403150144* 8403150152* 8403150159*	50-312 Q 50-275 T 50-275 T 50-275 T 50-275 T
BARNETT, JE Barr, K Barr, K P Barr, K P Barr, K P	8403010293 8403290234* 8403070072* 8403070248* 8403160240*	70-1621 50-302	Bayne, J P Bazin, J P Beach, F J Beare, A N Beaudoin, D E	6403290152 8403280240 8403130091* 8403300342 8403220025	50-286 P CONTRACT 50-322 G NUREO 50-329 A	BISHOP.T W BISBETT.P BITOWF.T B BYVEXIB	8403170114* 8403270135 8403270150* 8403240253* 8403120180	50-275 0 50-528 0 50-352 0 50-352 E YOPREP
DARR.K P BARR.K P BARR.K P BARRETT.L BARRETT.L	8403160372# 8403270220# 8403270320# 8403060103 8403060110	50-321 0 50-259 0 50-335 0 50-320 8 50-320 8	BEAVER, J R BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C	8403130118 8403130114 8403130014 8403130039 8403220238	50-320 F 50-327 0 50-498 0 50-498 0 50-498 0	BLACK,M.T BLACKBURN,J O BLAKE,E L BLAKE,E L BLAKE,E L	8403260347* 8403130207* 8403070025 8403070025 8403070129	HABTE NOT 50-400 0 50-287 0 50-287 0 50-287 0
DARRETT.L DARRETT.L DARRETT.L H DARRETT.L H DARRETT.L H	8403050144 8403050435 8403120253 8403120334 8403130467	20-350 d 20-350 k 20-350 k 20-350 8	BECHHDEFER, C BECICA: I J BECKHAM, J T BECKHAM, J T. BECKHAM, J T	8403220244 8403120244* 8403090067 8403090187 8403130346	50-327 0 50-335 0 50-321 F 50-321 P 50-321 F	BLAKE, J J BLAKE, J J BLAKE, J J BLAKE, J J	8403070105* 8403070263 8403160037 8403160120* 8403160178*	50-400 0 50-348 8 50-366 8 50-369 0 50-321 0
Barth, C A Barth, C A Barth, C A Barth, C A Barth, C A	8403190053 8403190058* 8403190141* 8403210120 8403210321	50-400 G 50-400 G 50-400 G 50-400 G 50-400 G	BECKHAM, J. T BEEDLOH, P. A BEGHIAN, L BEHRENS, D. H BEINECKE, P. J.	8403270174* 8403230207 8403300167* 8403230141* 8403270107	50-366 Q NURED 50-223 Q 50-275 R 50-295 B	BLAKE, J J. BLAKE, J J. BLAKE, J J. BLAKE, J J.	8403160279* 8403160363* 8403160383* 8403140247* 8403270173*	50-370 0 50-413 0 50-370 0 50-254 0 50-400 0
Darth.c a Barton.j m Bartter,w d. Daskin.k p, Baskin.k p	8403270333 8403070264 8403300325 8403070177 8403070227*	50~400 0 50~320 F NURE0 50~361 P 50~361 P	BEINECKE.P J. BELIBLE.G A. BELL.C R. BELL.J BELL.N	8403270265 8403140319* 8403230216 8403130471* 8403220049	50-295 S 50-413 G 50-537 A 50-320 Q 50-460 G	BLAKE, J J BLANCHARD, B BLANCHARD, B BLATT, M BLATT, M	8403290219* 8403020277 8403190343 8403020155 8403130405	50-321 Q 50-320 P 50-508 D 50-247 R 50-247 8
Baskin, k p Baskin, k p Bass, J t Bassett, h	8403070233* 8403070236* 8403220018 8403020215* 8403010528	50-361 P 50-361 P 50-206 F FDIA CONTRACT	BELL, N DELL, N E BELL, S, DELLAMY, R BELLAMY, R	8403260211 8403230177 8403020240* 8403130208 8403130456	50-482 Q NUREQ FOIA 50-219 S 50-309 S	BLATT, M BLATT, M. BLOCH, P. B BLOCH, P. B	8403210154 8403270184 8403130121 8403080110 8403090099	50-247 8 50-247 R 50-315 F 50-155 9 50-448 9
DASSIN, N BASSOL F BATEMAN, W M DATES, J W	8403020187* 8403020191* 8403130039 8403220089* 8403180380*	FD1A FD1A 50-318 S 50-354 G 70-1113	DELLAMY, R, R DELMORE, C I DELSER, A L BEMIS, P R DEMIS, P. R	8403090070 8403230112* 8403200015 8403070199* 8403070310*	50-219 G 50-219 R 50-352 O 50-400 G 50-324 G	BLOCH, PB BLOCH, PB BLOCH, PB BLOCH, P, B BLOCH, PB	8403090132 8403190002 8403190028 8403200065 8403280342	50-155 9 50-445 9 50-445 9 50-445 9 50-445 9
BAUER, E Q BAUNACK, H BAUSER, D B BAUSER, D B BAUSER, D B	8403150140* 8403070287* 8403200066 8403200066 8403210187	50-277 P 50-287 G 50-287 C 50-287 C 50-289 G	Bemis, p. r Demis, p. r Benardya, v Benardya, v Benardya, v	8403140385# 8403270072# 8203020137# 820512007&# 8205270420#</td><td>50-261 G 50-324 G 50-460 F 50-400 E 50-400 E</td><td>BLOSBOM, J. N BLOOM, J. & BLOOM, J. & BLOOM, J. N</td><td>8403300262 8403270338* 8403260361 8403260361 8403150102</td><td>50-440 Q 50-400 Q 50-456 Q 50-456 Q 40-8452</td></tr><tr><td>BAUBER.D B. BAUBER.M A BAUBER.M A BAXTER.T.A BAXTER.T.A</td><td>8403210187 8403190171 8403190171 8402290081 8403070134</td><td>50-289 0 50-250 0 50-250 0 50-400 0 50-400 0</td><td>BENAROYA. V BENDER, M. BENDER, M BENDER, M BENDER, M</td><td>8211110461* 8403280316 8403280316 9403280341 8403280341</td><td>50-400 E ACRB ACRB ACRB ACRB</td><td>ELOSBOM, J N ELOUGH, A R BLOUGH, A R GLUBAUGH, R E. BLUBAUGH, R E</td><td>8403150226 8403010322* 8403150063* 8401120171 8403150280</td><td>40-8452 50-277</td></tr><tr><td>BAXTER,T,A BAXTER,TA BAXTER,TA BAXTER,TA BAXTER,TA</td><td>8403070134 8403070225 8403070225 8403140018 8403160018</td><td>50-400 9 50-400 0 50-400 9 50-400 0 50-400 0</td><td>DENNETT, D D BENBON, E C BERG, R & DERGAN, O W BERKOW, H N</td><td>8403150031 8403010490 8403260213 8403270056 8003240202*</td><td>50-206 F XPORTLIC 40-8585 50-237 B 50-308 A</td><td>elubaugh, r e egardman, j r edardman, j r. eogden, o eogge, r e</td><td>8403230267 8403050186# 8403260232# 8403150215 8403060326#</td><td>40-3453 50-482</td></tr><tr><td>GAXTER,T A. BAXTER,T A BAXTER,T A GAXTER,T A BAXTER,T A</td><td>8403200030 8403200030 8403210175 8403210175 8403210193</td><td>50-400</td><td>Bernabel. L Bernard, H Bess, J e Betcher. J L. Bettenhausen. L.</td><td>8402140014 8403070412 8403260177* 8403010018 8403150034*</td><td>50-528</td><td>BOLLING, L A BOLTEL, E C, BOLCH, M E BOCCH, M E</td><td>8403070257* 8403130064* 8403060405 8403280102 8403080078*</td><td>50-348 F 0A999 50-30 R 50-413 F FDIA</td></tr><tr><td>DAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A</td><td>8403210193 8403260328 8403260328 8403260348 8403260348</td><td>50-289 0 50-400 0 50-400 0 50-400 0 50-400 0</td><td>BETTENHAUSEN.L. BEHLEY.E K BIBB.H E BIBB.H E,</td><td>5403290191* 640320003 6403160268* 6403290132* 6403290160*</td><td>50-289</td><td>BOLOKER, J. E BOOKER, J. E BOOKER, J. E</td><td>8403170086* 8403080370 8403010073 8403010228 8403010321</td><td>50-123 0 50-425 0 50-458 8 50-458 8 50-458 A</td></tr><tr><td>DAXTER.T A BAXTER.T A BAXTER.T.A BAXTER.T A BAXTER.T A</td><td>B403260354* 8403260354* B403270327 B403270327 B4032703B5</td><td>50-400 G 50-400 G 50-400 G 50-400 G 50-289 G</td><td>Bicehouse, H Bicehouse, H Bidinger, O H Bidinger, O, H</td><td>8403130456 8403150017# 8403220249 8403260084# 8403300297#</td><td>50-309 8 50-219 0 70-371 70-1257 70-1257</td><td>BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E</td><td>8403010379 8403020294 8403050078 8403060320 8403070010</td><td>50-458 B 50-458 A 50-458 A 50-458 S 50-458 A</td></tr><tr><td>BAXTER, T A BAY, J. H BAY, J. H, BAYLESS, P D BAYLESS, P D.</td><td>8403270386 8403200021 8403200021 8403280117 8403280124</td><td>50-289 0 50-142 0 50-142 0 50-368 S 50-368 8</td><td>BIELAWSKI.A P BIELAWSKI.A P BIEMILLER, B BIEMILLER, B A BIRD, B K</td><td>8403020181 8403020181 8403020065 8403300162 8403060533</td><td>50-454 0 50-454 0 50-309 R 50-309 R NUREO</td><td>BOOKER, J. E BOOKER, J. E. BOOKER, J. E. BOOKER, J. E</td><td>8403070052 8403070061 8403070062 8403080378 8403130069</td><td>50-458 A 50-458 A 50-458 E 50-458 A 50-458 E</td></tr><tr><td>Dayne, J. P Dayne, J. P Dayne, J. P. Bayne, J. P. Dayne, J. P.</td><td>8401200078 8403020327 8403020351 8403090267 8403120024</td><td>50-286 V 50-333 F 50-333 P 50-286 P 50-333 P</td><td>BISHOP, T. W BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W.</td><td>8403060025 8403060131 8403060138 8403060207 8403060341</td><td>50-206 Q 50-275 Q 50-275 Q 50-275 Q 50-344 Q</td><td>BOOKER, J. E. BOOKER, J. E. BOOKER, J. E. BOOKER, J. E. BOOKER, J. E.</td><td>8403130175 8403130190 8403130264 8403130486 8403160310</td><td>50-458 8 50-458 A 50-458 B 50-458 F 50-458 8</td></tr><tr><td>P. SAYPAB P. SAYPAB P. SAYPAB P. SAYPAB P. SAYPAB P. SAYPAB</td><td>8403130162 8403130466 8403140153 8403160007 8403160017*</td><td>50-284 F 50-333 G PR 50-284 P 50-284 P</td><td>BISHOP, T W. BISHOP, T W. BISHOP, T W. BISHOP, T. W. BISHOP, T. W</td><td>8403040401 8403080254 8403080266 8403080274 8403080421*</td><td>50-312 0 50-528 0 50-377 0 50-312 0 50-275 8</td><td>BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E</td><td>8403190017 8403200034 8403210069 8403220209 8403260291</td><td>50-458 E 50-458 A 50-458 A 50-458 A 50-458 A</td></tr></tbody></table>				

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR
BOOKER, J. E BOOKER, J. E BOOKER, J. E BOOKER, J. E BORCHARDT, R	8403270026 8403270039 8403270045 8403270201 8403150073*	50-458 B 50-458 B 50-458 B 50-458 B 50-273 Q	BRICHT, G D BRINKMAN, B BRITT, L F BROCK, B L BRODEUR, R 1	8403300262 8403200113 8403010220 8403270221* 8403040187	50-440 Q 50-336 S 50-322 Q 70-1257 QA999	BURNETT, R F BURNETT, R F BURNETT, R F BURNETT, R F BURNETT, R, F	8403010033* 8403010037* 8403010042* 8403050343 8403080420*	ACRS ACRS ACRS 70-143 50-275
BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M	8403140039 8403140100 8403140114 8403140136 8403140135	50-322 0 50-322 0 50-424 0 50-322 0 50-322 0	BRODEUR.R 1 BRONS.J C BRONS.J C BRONS.J C.	84032700B7 8403120152 8403130256 8403150047 8403150050	0A999 50-286 S 50-286 R 50-286 S 50-286 S	BURNB.E M BURNB.S BURSTEIN.C H BURWELL.S B BUBH.K J	8403120029# 8403080422# 8403080130 8403300249 8403050315	50-275 50-275 50-382 50-445 WASTE NO
BORDENICK, B M BURDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M	8403140158 8403140161 8403190124 8403190169 8403210100	50-322	Brons. J. C. Brons. J. C. Brons. J. C. Brons. J. C.	8403170265* 8403210047 8403210113 8403260071 8403260257	50-266 0 50-266 8 50-266 8 50-266 8 50-266 8	DASTIK' Y BREH' K Y BREH' K Y BREH' K Y	8403050318* 8403050319* 8403050322* 8403050323* 8403010041*	WASTE HO WASTE HO WASTE HO WASTE HO FOLA
BORDENICK, B M BORDENICK, B. M. BORST, F. J. BORST, F. J. BORST, F. J.	8403280340 8403280362 8403010118 8403040309 8403130177	50-322	erons. J. C. Brons. J. C. Dronski, D Bronzan. B Brown. C. H.	8403300159 8403300175 8403120038 8403270352 8403120145#	50-286 R 50-286 0 50-206 H 50-275 G 50-283 Q	BUTCHER,R C BUTCHER,R C BUTCHER,R C. BUTLER,B D BUTLER,B D	8403070136* 8403070263 8403160282* 8403070163* 8403160225*	50~395 50~348 50~259 50~327 50~327
Bosnak, R. J. Bosnak, R. J. Bouchey, G. D. Bouchey, G. D. Bournia, A.	8104300020* 8403070370* 8201170297* 8208120240* 8403140350	50-397 A 50-315 P 50-397 F 50-397 F 50-374 F	HOHN, E. J. BROWN, E. J. H. H. HAIGRE H. H. HAIGRE H. H. HAIGRE H. H. HAIGRE	8303170014 8303170017# 8403060338 8403040338 8403020095#	50-315 8 50-322 6 50-322 6 50-322 6	BAND' B BAND' B BAND' B BAND' B	8403130192 8403130274 8403190033 8403200017 8403260244	50-416 50-416 50-416 50-416 50-416
Bournia, A. Bovell, C. R. Bovers, H. Bowman, C. E. Bowman, D. C.	8403300224 8403300342 8403280225# 8403120027 8403210001	50-374 P NUREQ 50-482 Q 50-293 R 40-6920	W C'NYOUE W C'NYOUE W C'NYOUE W C'NYOUE W C'NYOUE	8403020101# 8403020113# 8403020116# 8403020137# 8403020142#	FOIA FOIA FOIA FOIA	BAND' K BAND' K BAND' K BAND' K	8403300027 8403300037 8403300113 8403300117 8403000071	50-416 50-416 50-416 50-416 50-416
BOHMAN, D. C. BOYD, D. BOYD, D. BOYD, D. BOYD, D. C.	8403300008 8403130275 8403130336 8403190071 8403220165*	40-6920 50-346 8 50-346 8 50-255 8 50-295 0	M でいるいのは でいる。 でいることを M でいることを M でいる M で M で M でい M で M で M で M で M で M を M でい M を M で M を M で M を M で M を M を M を M を M を M を M	8403020172# 8403020174# 8403020177# 8403020187# 8403020191#	FOIA FOIA FOIA FOIA	BYRD,R W BYRUN,P M. CAHILL,W J. CAHILL,W J	8403200064 8403220114* 8403130393 8403130448* 8403270076*	50-416 50-341 50-458 50-458 50-458
BDYER, L ROYER, R E. BOYER, R, E. BOYER, V, S. BOYER, V, S.	8403200033 8403120134 8403130314 8403010144 8403020105#	50-324 F 50-416 B GA797 50-352 E 50-352 Q	eroun, J. M Drown, J. M. Brown, J. M Brown, J. M Brown, J. M	8403020199# 840302020# 8403020201# 8403020208# 8403020210#	FOIA FOIA FOIA FOIA FOIA	CAHILLIW J. CAHNA L CALDWELLIR A CALDWELLIR A CALDWELLIR A	8403280032 8401130343 8403240167* 8403240214* 8403240240*	50-458 TOPREP 50-247 50-445
BOYER, V S BOYER, M, J. BRADFORD, W H. BRADFORD, W H BRADHAM, O, S	8403270017 8403270048* 8403160284* 8403270103* 8403130397	50-352 G 50-352 T 50-348 G 50-348 G 50-375 F	erdun, J. M. Brown, J. M Brown, R. T Brown, R. W Brown, H.	8403020227* 8403020251* 8403080180* 8403210004 8403050228	FOIA FOIA FOIA PR 70-420	CALLENDINE. G M CALLENDINE. G M CALLENDINE. G M	B101300020* B101300025* B403010119 B4030B040B B403060249	FOIA FOIA 50-312 , 50-206 (50-295
BRADLEY, E. J.	8403020257 8403150036 8403150140* 8403210045 8403240054	50-352 A 50-352 C 50-277 P 50-277 P 50-277 J	Brown, W Brown, W. B. Brown, W. B Brown, W. B. Brown, W. B.	8403050367 8403050177 8403050205 8403050220 8403050361	70-2988 70-27 70-27 70-143 70-27	CAMPBELLIR D CAMPBELLIR K CAMPBELLIR M CANTERIH CANTERIH L	8403200152# 8403270195 8403150034# 8403060215 8403060029#	50-423 , 50-387 50-388 ; 50-361 50-206 (
BRADLEY, E J. BRADLEY, F J BRADLEY, R, D BRADY, J, A, BRADY, J A	8403260333 8403130236 8403300097 8403050151 8403080178	50-352 0 PR PT2: 50-320 F 50-320 F	Brown: H B Browning: R E, Browning: R. E, Browning: R. E, Brownlee; V L	8403050365 8403020185 8403170422 8403220218 8403080384*	70-2755 WASTE MGT WASTE MGT 27-39 50-424 Q	CANTER, H L CANTER, H L CANTER, H L CANTER, H. L CANTER, H. L	8403060142# 8403060143# 8403060146# 8403060147# 8403080277#	50-275 t 50-275 t 50-275 t 50-275 t
BRADY, J.A. BRADY, J.A. BRAMLETT, L. 9 BRAMLETT, L. 9, BRANCH, M. H.	8403140088 8403270073 8403020081 8403300164 8403270274*	50-287 F 50-320 F 50-348 R 50-348 R 50-338 Q	BROWNLEE, V L. BRUNNER, E. J BRUNNER, J. E BRUNNER, J. E BRUNNER, J. E	8403290108* 8403050241* 8403060093 8403120039 8403190166	50-259 0 50-271 8 50-329 0 50-329 0 50-329 0	CANTRELL, F B CANTRELL, F S CANTRELL, F S CANTRELL, F S CANTRELL, F S	840307008B* 840307013&* 8403160186* 8403160282* 8403160284*	50-375 f 50-375 f 50-257 t 50-259 f 50-348 f
BRANT, K. T. BRAUN, D. J. BREJBMEIBTER, F. BRENNER, L. BRENNER, L.	8403130295 8403080216* 8403120010* 8403060097 8403190040	50-317 8 50-316 P 50-275 0 50-352 0 50-352 0	erurg.r L Brugven.a D Bryant.j. Bryant.j Buckleg.r.	84030602B5 8403270115 B403070369# B40327010B# B403070015	50-243 F 50-243 I 50-247 Q 50-247 Q FOIA	CANTRELL, F 8 CAPHTON, D, L. CAREY, J J CAREY, J J CAREY, J J	8403270103* 8403050245* 840302088 6403060297 8403070243	50-348 " F01A 50-334 " 50-334 V 50-334 R
Brenner, L. Brenner, L. Brenner, L. Brenner, L. Brenner, L.	8403190153 8403200070 8403270045 8403280331 8403280350	50-352 0 50-352 0 50-352 0 50-352 0	BUCKLEY, B. C. BUCKLEY, B. C. BUCKLEY, B. C. BUHL, T. BURD, R, B.	8403020084 8403020076 8403280070 8403030107 8403130180	50-400 M 50-400 M 50-400 A State Prog 50-50B D	CAREY, J. J. CAREY, J. J. CAREY, J. J. CAREY, J. J.	8403070269 8403070344* 8403120172* 8403170276 8403170317*	50-334 R 50-334 G 50-334 R 50-334 R
Brenner, L. Brenner, L Brenner, L. Brenner, L. Brewer, R.	8403280354 8403290373 8403290393 8403300009 8403020241*	50-352 0 50-322 0 50-352 0 50-352 T 50-250 0	BURDOIN.J. BURDOIN.J.F. BURDOIN.J.F. BURGER.F.J. BURGEBS.J.L.	8403270139* 8403060223* 8403060406* 8403170086 8403020132*	50-528 G 50-323 G 50-312 G 50-271 R FDIA	CAREY, J. J. CAREY, J. J. CAREY, J. J. CAREY, J. J. GAREY, J. J.	8403260160 6403270215 8403280017 8403300062 8403300181	50-334 R 50-334 F 50-334 F 50-412 A 50-334 R
BREY, H L. BREY, H. L. BREY, H L BREZINBKI, M. S. BRICH, R.	8403010304 8403130374 8403220138 8403140183* 8403130236	50-267 Q 30-267 R 50-267 F 50-373 F PR	BURGESSIJ L BURGINIR.E BURGINIR.E, BURGINIR.E, BURKEID J.	8403020219# 8102240066# 8403080108# 8403080202# 8403070253#	FOIA FOIA FOIA FOIA 50-260 Q	Carlbon, D M Carlbon, D M. Carlbon, D. M. Carlbon, R. A Carpenter, J H	8403010260* 8403010265* 8403190014* 8403080149* 8403190025	50-142 Q 50-142 Q 50-142 Q FOIA 50-400 Q
BRICKLEY, R H. BRICKLEY, R. H BRIGHT, O. O. BRIGHT, O. O. BRIGHT, O. O.	8403130425* 8403130460* 8403170025 8403210051 8403260003	0A979 9A979 50-400 0 50-400 0 50-142 0	BURKE, W C BURN, R. R. BURNETT, P. T BURNETT, P. T. BURNETT, R. F	8005130793* 8403190437 8402140193* 8403160168* 8403010029*	50-387 E NUREQ 50-261 Q 50-414 Q ACRB	CARPENTER, J H CARPENTER, T Q. CARR, A. V. CARR, A. V. CARR, A. V.	8403210051 8403150176* 8403130071 8403130077* 8403200007	50-400 Q CONTRACT 50-413 Q 50-413 Q 50-413 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
CARRIA V CARROW, H CARROW, H CARROW, H CARTERIB R	8403200007 8403200117 8403200135 8403200135 8403270045	50-413 G 50-400 G 50-400 G 50-400 G 50-401 M	CHICK'S A CHICK'S A CHICK'S A CHICK'S A	8403230164* 8403260001 8403280343 8403280348 8403290381	100FR 50-293 0 50-289 0 50-329 0 50-275 0	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8403130455 8403140210 8403150055 8403150084 8403160265*	50-348 P 50-349 F 50-349 Q 50-348 B 50-348 B
CARYER, R. E CARTER, S CARTER, S CARUSO, R, CASE, E O,	8403010255* 8403200171 8403020325 8403060536* 8308070070*	50-142 9 50-260 9 50-257 5 50-322 8 FOIA	CHILK,8 J CHILK,9 J CHIN,R Y CHIPMAN,0 L CHIRANAL,M	840330000 8403300017 8403270203 8403070217 8211120254	50-293 0 50-444 0 50-295 8 50-537 A 50-311 8	CLAYTON.F L CLAYTON.F L CLAYTON.F L CLAYTON.F L CLAYTON.F L	8403230134 8403240017 8403260227 8403280037 8403270084*	50-34B F 50-34B 8 50-34B P 50-34B P 50-34B Q
CASSEL, D W CASSEL, D W CASSIDY, D. P CASTIGLIONE, L CASTRONDVO, F	8403160017 8403160017 8403070020 8403270064 8403070184	50-454 0 50-454 0 50-443 0 50-155 8 PRM	CHIRAMAL, M CHIRAMAL, M CHIRAMAL, M CHIRAMAL, M CHIRAMAL, M	8211220027 8302020107 8305190492 8305190497* 8305200133	50-282 B 50-255 B TOPREP TOPREP 50-219 B	GLAYTON, F. L GLAYTON, F. L GLAYTON, F. L GLAYTON, F. L, GLAYTON, H. B.	8403270317 8403300077 8403300134 8403300172 8403010105	50-348 0 50-348 P 50-364 R 50-348 R TOPREP
CATON, B J CATTON, I CATTON, I CATTON, I CATTON, I	8403200331 8403160057 8403160076 8403280241 8403280241	WASTE MOT ACRS ACRS ACRS ACRS	CHIRAMAL: M CHIRAMAL: M CHIRAMAL: M CHIRAMAL: M CHIRAMAL: M,	8305270051 8310060076 8310060077# 8401250496# 8401250510#	50-338 8 MISC MISC 50-267 P 50-267 P	CLAYTON, H. B CLEMENSON, F CLEMENTS, B. R CLEMENTS, B R. CLEMENTS, B R	8403220215 8303100476* 8403080332* 8403130160 8403140147	TOPREP 50-397 A 50-445 G 50-445 Y PR
CATTON: 1 CAVADAS: K. J CAYOT: R F CEARLEY: J E CEJA: 8 N	8403300246 8403120140 8403230141* 8403190317 8403220322	ACR8 50-255 R 50-275 R PR XPDRTLIC	CHOULES, N C CHOULES, N C CHRISSOTIMOS, N CHRISSOTIMOS, N CHRISSOTIMOS, N	8403060176# 8403080188# 8403080233 8403120137# 8403130235	50-266 Q 50-461 Q 50-269 S 50-237 Q 50-254 S	CLEMENTS, B. R CLEMENTS, W. L. CLEMETT, J CLEMETT, J CLEMETT, J	8403230059 8403200195* 8403010366* 8403060303* 8403060303*	50-445 H 50-287 0 70-1100 50-275 0
CEJA, 9 N CELESTE: R F CELIA, N. 9 CERNE: A C. CESARS: J &	8403220324* 8402130360* 8403070304 8403020308* 8403020047	XPDRTLIC 50-358 U 50-245 P 50-443 Q 50-416 R	CHRISTENSEN.D CHRISTMAN.J N CHRISTMAN.J N CHRISTMAN.J N CHRISTMAN.J.N	8403230131 8403010195 8403010195 8403060245 8403130090*	NUREG 50-322 0 50-322 0 50-322 0	CLEMETT, J CLEMETT, J. CLINE, H CLINE, H.	8403150010 8403150010 8403260364 8403160116# 8403160111#	50-275 9 50-275 0 50-275 0 50-348 0 50-369 0
CEBARE, J. 0 CHAFFEE, A. E CHAILLE. C E CHAMBERLAIN, D GHANDLER, J C	8403220147 8403040029* 8403220024* 8403120072* 8403070127	50-416 R 50-206 Q 50-206 F 50-458 Q TOPREP	CHRISTMAN, J N CHRISTMAN, J N CHRISTMAN, J N CHRISTMAN, J, N CHRISTMAN, J N	8403130090* 8403130119* 8403130119* 8403200031 8403200031	50-322 0 50-322 0 50-322 0 50-322 0	CLINE, W. E COBB, L I, COFFMAN, F COHEN, I, COLBURN, T Q.	8403160141* 8003240207* 8305230119* 8403210016* 8403060575	50-269 0 50-508 A 50-286 P 50-317 0 50-266 P
CHANDLER: J C CHANDLER: J C CHANDLER: J C CHANDLER: J C CHANDLER: J C	8403080205 8403080223* 8403150097 8403200100 8403260219	50-316 P 50-316 P 50-316 P 50-316 P TOPREP	CHRIBTMAN, J N CHRIBTMAN, J N CHRIBTMAN, J N CHRIBTMAN, J N	8403200037* 8403200037* 8403300254 8403300256 8403080125*	50-322 0 50-322 0 50-322 0 50-322 0 50-373 0	COLBURN, T. Q COLE, R. F COLEMAN, J H. COLEY, J L COLLING, J T	8403220254 8403040097 8403090332* 8403140279* 8402210338	50~246 P 50~352 Q TOPREP 50~390 Q 50~285 Q
CHANDLER, L J CHANDLER, L J CHANDLER, L J. CHANDLER, L J CHANDDLA, V	8403170100 8403210033 8403210114 8403270278 8403080009#	50-275 0 50-275 0 50-275 0 50-275 0 50-27 P	CHRISTNOT, E CHURCHILL, B W CHURCHILL, B, W, CHURCHILL, B W CHURCHILL, B W	8403170076* 8403010009 8403010009 8403010187 8403010187	50-373 G 50-287 9 50-287 9 50-382 9 50-382 9	COLLINS, J. T.	8403050137 8403050138 8403050141 8403050142 8403050145	50-382 F 50-285 F 50-298 F 50-313 F 50-458 F
CHAPMAN, M CHAPMAN, M CHAPMAN, M CHAPMAN, M	8403130148# 8403260087# 8403020103 8403300139# 8403090020	50-267 G 50-382 G 50-259 R 50-259 R FOIA	CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W, CHURCHILL, B W CILIMBERO, R L	8403060084 8403060084 8403130443 8403130443 8403170208*	50-289 0 50-289 0 50-289 0 50-289 0 50-254 0	COLLINS, J, T. COLLINS, J T COLLINS, J T COLLINS, J T. COLLINS, J T. COLLINS, M. L.	8403050146 8403050149 8403050152 8403260187 8402130395#	50-445 F 50-498 F 50-482 F 40-8681 50-358 U
CHARLTON, T R CHARNLEY, J E CHARNLEY, J. 8 CHARNDEF, 0. CHARNDEF, 0.	8403280332 8403070318# 8403150107 8403070191 8403070191	50-33B S 50-325 Q TOPREP 50-445 Q 50-445 Q	CILIMBERG,R L CINTULA,T C CINTULA,T,C CIPOLLA,A J CLANDY,L S,	8403170354* 8210120303 8212010501 8403230097 8403120133*	50-440	COLLINS, 8, J, COLLINS, 8, J COLLINS, 8, J COLLINS, 8, J,	B40301000& B40307031&# B403130021# B403150101# B403170425	50-410 0 50-333 0 50-220 0 50-410 0 50-244 V
CHARNOFF.0. CHAUDHARY.8 K CHENEY.C A CHENO.T M CHIKALLA.T.D	8403270385 8403070319* 8403070259* 8403160078 8403300248	40-2061 50-352 G 50-346 P 50-206 P Warte Mot	CLARK, B. L CLARK, B. L CLARK, B. L CLARK, B. L. CLARK, B. L	8403010358 8403120019 8403120085 8403120175 8403130158	50-277 B 50-278 B 50-277 B 50-278 B 50-278 B	COLOMBO, R. W COLOMBO, R. W COLOMBO, R. W. COLOMBO, R. W COLTON, E.	6403200045 6403060452 6403060467 6403200001 8403010459	50-312 R 50-312 B 50-312 S 50-312 P XPORTLIC
Chifk's' a Chifk's' a Chifk's' a Chifer'f	8403280156* 8402220157 8403010238 8403020068 8403050066	50-250 H 50-10 C 50-10 C FOIA 50-35B C	CLARK, B. L CLARK, D. CLARK, D. CLARK, D. C. GLARK, J. R	8403200017 8403120107 8403200106 8403160027 8403010226	50-277 8 50-265 8 50-265 8 50-265 8 50-259 8	CON, V. CONGEL, F J CONGEL, F J. CONLON, T. E. CONLON, T E.	8403120252* 8205070088* 8304070113* 8403160092* 6403160212*	50-335 0 50-460 F 50-397 A 50-413 0 50-424 0
CHILK' 8' 7 CHILK' 8' 7 CHILK' 8' 7 CHILK' 8' 7	8403050244 8403050258 8403070114 8403070370 8403080104	10CFR 10CFR 50-483 0 50-320 0 M18C	CLARK,L CLARK,L, CLARK,P R. CLARK,R A CLARK,R,J.	8402130347 8403190437 8403090244 8307180414* 8403050051	50-20 F NUREG 50-320 F 50-344 P 50-296 S	CONLON, T, E, CONLON, T, E, CONNER, E CONNER, E, L, CONNER, E, L,	8403270156# 6403270199# 8403070287# 8403070319# 6403130280#	50-416 Q 50-400 Q 50-287 Q 50-352 Q 50-217 Q
CHILK, 8 J. CHILK, 8 J. CHILK, 8 J. CHILK, 8 J.	8403070060 8403070062 8403070067 8403070074 8403070113	50-519 0 50-443 G 50-10 0 50-10 0 50-10 0	CLAMBON, C A. CLAMBON, C A CLAMBON, C A. CLAMBON, C. A, CLAY, E. L	8403070150* 8403070154* 8403070204* 8403260379* 8403160348*	50-322 T 50-322 T 50-322 T 70-1113	CONNER, T. B.	8403150020 8403150020 8403150022* 8403150022* 8403200018	70-354 9 50-354 9 50-354 9 50-354 9 50-416 9
CHICK'S 7 CHICK'S 7 CHICK'S 7 CHICK'S 7	8403120028 8403120034 8403140028 8403140102 8403140005	10CFR 50-416 0 50-354 0 50-400 0 50-320 0	CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L.	8403010417 8403040125 8403080077 8403080081 8403080148	50-344 8 50-348 9 50-348 F 50-348 P 50-348 P	CONNER, T. B.	8403200018 8403200102 8403210092 8403210092 8403210178	50-414 9 50-354 9 50-352 9 50-352 9 50-358 9
CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J	8403160014 8403190144 8403210160 8403230005 8403230162	50-275 0 50-483 0 50-382 0 50-352 0 10CFR	CLAYTON; F. L CLAYTON; F. L CLAYTON; F. L, CLAYTON; F. L, CLAYTON; F. L	8403080138 8403080272 8403090243 8403090255 8403130031	50-348 P 50-348 P 50-348 B 50-348 P 50-348 P	CONNER, T. B.	8403210178 8403260349 8403260349 8403300270 8403300270	50-358 0 50-352 0 50-352 0 50-354 0 50-354 9

AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CA:ECORY
CONTAN, H CONSTABLE, O L CONTE, R, CONHAY, J, T CONHAY, J, T	B309220297* B403130140* B403070287* B403190340* B403270241*	FOIA 50-382 Q 50-289 Q QA777 QA999	CORRADINI, M CORRADINI, M CORRADINI, M CORRADINI, M CORRIN, R	8403280314 8403280324 8403280324 8403280345 8403270148	ACRE ACRE ACRE ACRE GA999	CONNSIL, W O	8403260149 8403260162 8403260181 8403260181 8403260181	50-423 E 50-213 P 50-423 A 50-423 A 50-245 F
COCK, J. W. COCK,	8403130350 8403060104 8403060269 8403060272 8403070008	50-333 R 50-329 S 50-329 S 50-329 B 50-329 R	COBOROVE, P F COBEAR, A G, COSTANTING, C J COSTANTING, C J COSTALLO, F	8403060322* 8403220117 8403010217* 8403010231* 8403080107*	50-322 T 50-309 H 50-329 A 50-329 A FOIA	COUNBIL, W C COUNBIL, W C COUNBIL, W C COUNBIL, W C	8403240195 8403240200 8403240252 8403270008 8403270008	50-245 F 50-213 P 50-213 P 50-213 F 50-213 F
CODK' 7 H CODK' 7 M CODK' 7 H' CODK' 7 H'	8403080171 8403080222 8403140021 8403140032 8403220016	50-329 8 50-329 5 50-329 A 50-329 A 50-329 G	COSTELLO, F COSTELLO, F COSTELLO, J COSTELLO, J, R	8403080133* 8403080162* 8403080166* 8402150224* 8403130291*	FOIA FOIA FOIA GA999 GA999	COUNBIL, W O COUNBIL, W O COUNBIL, W O COUNBIL, W O	8403270008 8403270048 8403270081 8403270081 8403270112	50-213 F 50-213 F 50-336 P 50-336 P 50-423 A
COOK, J. H COOK, K. W COOK, K. W	8403220067 8403220108 8403020205 8403020333 8403050065	50-329 8 50-329 8 50-382 A 50-382 E	COTTER, B. P COTTER, B. P COTTER, B. P COTTRELL, W. B COUNBIL, W. G	8403210163 8403270027 8403300025 8403010102# 8403010235	50-354 0 50-352 G 50-458 G FOIA 50-336 P	COUNSIL, W C.	8403290112 8403290230 8403290230 8403290278 8403300092#	50-423 A 50-336 P 50-336 P 50-213 P 50-245 Q
COOK, K. W. COOK, K. W. COOK, K. W. COOK, K. W.	8403040190 8403040293 8403040304 8403040337 8403120148	70-2946 50-382 E 50-382 E 50-382 E 50-382 A	COUNBIL, W @ COUNBIL, W @ COUNBIL, W @ COUNBIL, W @	8403010235 8403010340 8403010391 8403050001 8403050001	50-336 P 50-213 P 50-213 P 50-423 D 50-423 D	COUNBIL, W G COUNBIL, W G COUNBIL, W G. COUNBIL, W G.	8403300072# 8403300144 8403300144 8403300144 8403300166*	50-245 G 50-213 G 50-213 G 50-213 G 50-213 G
CDOK, K, W CDOK, K, W COOK, K, W COOK, K, W	8403120169 8403120186 8403130105 8403130170 8403130331	50-382 A 50-382 E 50-382 G 50-382 A 50-382 Q	COUNSIL, W @ COUNSIL, W @, COUNSIL, W. @ COUNSIL, W. @ COUNSIL, W @	8403050105 8403050105 8403050105 8403060325 8403070273	50-213 P 50-213 P 50-213 P 50-213 P 50-423 C	COUNTS, M COWAN, K. D COWAILL, C COMOILL, C	8403130397 8403020097 8403300056 8403130280* 8403130060*	50-395 F 50-397 R 50-397 R 50-219 G 50-387 Q
COOK, K, W COOK, K, W COOK, K, W COOK, K, W	8403130446 8403140191 8403150046 8403150075 8403160020	50-382 A 50-382 F 50-382 A 50-382 F 60-382 A	CONVEIL'H C CONVEIL'H C CONVEIL'H C CONVEIL'H C	8403070273 8403070299 8403070299 8403070336* 8403070336*	50-423 C 50-423 A 50-423 A 50-423 G 50-423 G	CHAIC, J COYLE, L. COYLE, L. COWLEY, P COWLEY, P COWLEY, P CHAIC, J	8403230200 8403280102 8403260223 8403260260 8403010363	NURE9 50-413 F 50-237 B 50-237 B 50-289 Q
CODK, K, W. CODK, K, W. CODK, K, W. COOK, K, W.	8403200161 8403200168 8403200209 8403210030 8403270154	50-382 F 50-382 A 50-382 A 50-382 A 50-382 A	COUNBIL, W. C COUNBIL, W. C COUNBIL, W. C COUNBIL, W. C	8403070137 8403070257 8403070257 8403070272 8403070272	50-213 0 50-336 P 50-336 P 50-336 P 50-336 P	CRAIO, J GRAIO, J GRAMER, M L GRANE, P A. GRANE, P A.	8403150093 8403220075 8403260347* 8403060178 8403270063	50-247 S 50-220 S WASTE MOT 50-133 J 50-275 O
COOK, K. W. COOK, R. J COOK, T. L. COOK, T. L. COOKE, B. A	8403300048 8403230046* 8403070395* 8403260335 8403220277	50-392 F 50-329 R 50-315 P 50-416 P WASTE MOT	COUNSIL, W G COUNSIL, W G COUNSIL, W G COUNSIL, W G	8403090272 8403120135 8403120135 8403130027 8403130027	50-336 P 50-245 R 50-245 R 50-213 P 50-213 P	CRANE,PA CRANE,PA CRANLEY,DE CREED,JR CREED,JR	B403280033 B403280051 B403260277 B40301034B* B403170239*	50-275 J 50-133 1 50-327 F 50-454 Q 50-331 Q
CODNER, T B. CODNEY, M. J COPELAND, R. A COPELAND, R. A COPELAND, R. A	8403200102 8403090285 8403080210* 8403150104* 8403200101*	50-354 9 50-277 F 50-316 P 50-316 P 50-316 P	COUNBIL, W Q. COUNBIL, W Q COUNBIL, W Q COUNBIL, W Q	8403130027 8403130213 8403130283 8403130360 8403130360	50-213 P 50-423 B 50-213 R 50-423 C 50-423 C	CREED, J R. CREWB, J L. CREWB, J L CREWB, J L CRLENJAK, R V	8403260023* 8403050250* 8403190126* 8403190130* 8403290197*	50-346 0 50-312 P 50-275 Q 50-275 G 50-346 Q
COPELAND, V COPELAND, V COPLAN, B. M CORDARD, M. C. GORDARD, M. C.	8403060192* 8403060192* 8403020344 8403070150* 8403070154*	50-155 0 50-155 0 HABTE HOT 50-322 T 50-322 T	COUNSIL, W G COUNSIL, W G COUNSIL, W. G COUNSIL, W. G	8403140014 8403140101 8403140101 8403160272 8403160272	50-213 P 50-423 K 50-423 K 50-423 E 50-423 E	CROCKER, H. W CROCKER, H. W CROCKER, H. W CROCKER, H. W GROCKER, H. W	8403020342* 8403020357* 8403210016* 8403210054* 8403210105*	50-247 Q 50-286 Q 50-317 Q 50-320 Q 50-334 Q
CORDARD, M. C.	8403070158* 8403070160* 8403070165* 8403070171* 8403070178*	50-322 T 50-322 T 50-322 T 50-322 T 50-322 T	COUNSIL, W G, COUNSIL, W G COUNSIL, W G COUNSIL, W G	8403170048 8403170048 8403170155* 8403170280 8403170280	50-245 P 50-245 P 50-213 G PR PR	CROSS.K.E CROSSMAN.W.A CROSSMAN.W.A CROSSMAN.W.A CROSSMAN.W.A	8403260286 8403050134* 8403050186* 8403120072* 8403130140*	NUREQ 50-459 Q 50-482 Q 50-458 Q 50-382 Q
GORDARO, M. C. GORDARO, M. C. CORDARO, M. C. GORDARO, M. C. CORDARO, M. C.	8403070183* 8403070190* 8403070195* 8403070198* 8403070201*	50-322 T 50-322 T 50-322 T 50-322 T 50-322 T	COUNSIL, W. O COUNSIL, W. O COUNSIL, W. O COUNSIL, W. O. COUNSIL, W. O.	8403190280 8403200149 8403200149 8403210011 8403210011	PR 50-423 A 50-423 A 50-423 G 50-423 G	CRDSSMAN, W A CROSSMAN, W A CROSSMAN, W A CROSSMAN, W A CROSSMAN, W A	8403260068* 8403260087* 8403260220* 8403260232* 8403260250*	50-458 0 50-382 0 50-458 0 50-313 0 50-382 0
CORDARD, M. C.	9403070204* 8403070207* 8403070211* 8403070214* 8403070217*	50-322 T 50-322 T 50-322 T 50-322 T 50-322 T	COUNBIL, W Q, COUNBIL, W Q, COUNBIL, W Q COUNBIL, W, Q	8403210161 8403220148 8403220148 8403230022 8403230022	50-423 B 50-423 F 50-423 F 50-213 R 50-213 R	CROUBE, R P CROUBE, R P CROUBE, R P CROUBE, R P GROUBE, R P	8403050107 8403130133 8403130429 8403150085 8403150085	50-346 P 50-346 P 50-346 P 50-346 P 50-346 B
CORDARD, M. C.	8403070220* 8403070222* 8403070227* 8403070231* 8403230016	50-322 T 50-322 T 50-322 T 50-322 T 50-322 T	COUNBIL, W. O. COUNBIL, W. O. COUNBIL, W. O. COUNBIL, W. O.	8403230022 8403230029 8403230029 8403230033 8403230033	50-213 R 50-245 F 50-245 F 50-423 Q 50-423 Q	CROUSE,R P CROUSE,R P CROUSE,R P, CROUSE,R P, CROUSE,R P	840320008 8403200046 8403230007 8403300149 8403300156*	50-346 P 50-346 F 50-346 F 50-346 P
CORDARO, H. C. CORDARO, M. C. CORDARO, M. C. CORDARO, M. C. CORDARO, M. C.	8403230020 8403230032 8403230038 8403230048 8403230064	50-322 T 50-322 T 50-322 T 50-322 T	COUNSIL, W. C. COUNSIL, W. C. COUNSIL, W. G. COUNSIL, W. C. COUNSIL, W. C.	8403230136 8403260143 8403260143 8403260143 8403260145	50-213 Q 50-213 F 50-213 F 50-213 F 50-336 P	CRDUSE.R P CROUSE.R.P CROW.H.T. CROW.H T CROW.W T.	8403300163 8403300178 840300013* 840306470 8403140217*	50-346 P 50-346 J 40-8027 40-481 40-8027
CORDARD, M. C. CORDARD, M. C CORMIER, W. H. CORMIER, W. H. CORRADINI, M	8403260379* 8403140089 8403260380	50-322 T 50-322 T 50-142 G 50-142 G ACRS	COUNSIL, W Q. COUNSIL, W Q. COUNSIL, W Q. COUNSIL, W Q.	8403260145 8403260146 8403260146 8403260146 8403260146	90-334 P 90-213 F 50-213 F 50-213 F 50-423 E	CROW, W T. CROW, W T CROME, D. S CROWLEY, B. R CROWLEY, B. R	8403230246* 8403260084* 8403300342 8403160178* 8403170284	70-1359 70-1257 NUREG 50-321 G 50-366 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY	SOHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CROWLEY. B R. CROY. P A CROY. P A CROY. P A CROY. P A CROYCHFIELD. D CRUTCHFIELD. D.	8403290219* 8402030338 8403150031 8403010331 8403010372*	50-321 0 50-204 F 50-206 F 50-27 0 50-25 P	CUTTER, A B	8403060140 8403130093 8403150028 8403210093 8403270235	50-324 P 50-261 P TOPREP 50-261 P 50-261 P	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8403160264 8403160306 8403160334 8403160338 8403160343	50-335 Q 50-250 Q 50-302 F 50-321 Q 50-413 Q
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8403010384 8403050005 8403050006* 8403050007 8403050121	50-213 P 50-155 P 50-155 P 50-407 P 50-155 P	CYBULBKIB: P CYBULBKIB: P E'ANGELD: A DALE: L F.	8403050227 8403050230 8403050242 8403060029* 8403010121	RES 50-280 P RES 50-206 G 50-416 B	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8403160356* 8403160357* 8403160360 8403270067 8403270070*	50-413 G 50-321 G 50-413 G 50-269 G 50-269 G
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8409060321 8403060327 8403060454 8403060459* 8403080094	50-155 P 50-219 P 50-245 P 50-245 P 50-219 P	DALE,L F DALE,L F DALE,L F DALE,L F, DALE,L F	8403020047 8403070057 8403070173* 8403070176* 8403070180*	50-416 R 50-416 G 50-416 G 50-416 G	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8403290109 8403290124* 8403290143 8403290174 8403290184	50-335 0 50-335 0 50-413 0 50-335 0 50-338 F
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8403070210 8403070297 8403130216 8403130225 8403140133	50-155 P 50-219 P 50-206 P 50-244 P 50-249 P	DALE:L F. DALE:L F DALE:L.F. DALE:L.F. DALE:L.F.	8403070187* 8403070268 8403090071 8403090172 8403090215	50-416 G 50-416 G 50-416 B 50-416 B 50-416 P	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8403290208 8403290215* 8403290231 8403290262 8403290275	50-321 Q 50-321 Q 50-302 Q 50-369 Q
CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D	8403140143# 8403150040 8403150072 8403150074 8403170178	50-249 P 50-237 P 50-237 F 50-249 Q 50-155 P	DALE, L F DALE, L F. DALE, L F. DALE, L F. DALE, L F.	8403120037 8403120148 8403120157 8403130075 8403130172	50-416 F 50-416 S 50-416 S 50-416 B 50-416 B	DANCE.H C DANCE.H C. DANIEL.S L. DANIELS.Q H DANIELSON.D H	8403290289 8403290317 8403080029# 8403060124* 8403080302*	50-338 Q 50-335 Q FDIA 50-244 P 50-315 Q
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D. CRUTCHFIELD, D.	8403200177 8403210070 8403210079* 8403210135 8403210143*	50-135 P 50-245 P 50-245 P 50-244 P 50-244 P	DALE,L F DALE,L F DALE,L F, DALE,L F DALE,L,F	8403130248 8403130253 8403130274 8403130464 8403140121	50-416 8 50-416 8 50-416 8 50-416 8 50-416 J	DANIELSON, D H DANIELSON, D H DANIELSON, D H DARDEN, T H DARWISH, M	B40317020B* B403170305* B403170354* B403080173* B403150045*	50-254 Q 50-454 Q 50-440 Q FDIA 50-237 P
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8403220021 8403220047 8403230085 8403230143 84032701 <i>0</i> 6	50-155 F 50-237 P 50-245 P 50-155 P	DALE, L F DALE, L F DALE, L F DALE, L, F DALE, L, F.	8403190033 8403190043 8403190059 8403190115 8403190216	50-416 S 50-416 S 50-416 B 50-416 S 50-416 B	DAVENPORT, K E DAVERID, C A DAVERID, C A DAVERID, C A DAVERIO, C A	8403160238* 8403070150* 8403070154* 8403070158* 8403070165*	50-259 Q 50-322 T 50-322 T 50-322 T 50-322 T
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CULVER, M M. CUMMINOS, J, J	8403280005 8403280011 8403280066 8403160036 8403280229*	50-217 G 50-219 P 50-409 P 50-302 R 50-482 G	DALE, L. F. DALE, L. F DALE, L. F DALE, L. F DALE, L. F	8403170292 8403170331 8403200014 8403200017 8403200044	50-416 8 50-416 8 50-416 8 50-416 8 50-416 8	DAVERIO, C A DAVERIO, C A DAVERIO, C, A DAVERIO, C, A DAVERIO, C, A	8403070178* 8403070183* 8403070217* 8403230016 8403230032	50-322 T 50-322 T 50-322 T 50-322 T 50-322 T
Cunninoham, A L Cunninoham, A L, Cunninoham, O E Cunninoham, O E Cunninoham, O H	8403160202# 8403290239# 8403150072 8403200242 8403140141	50-390 0 50-259 0 50-73 R 50-70 R 50-322 0	DALE, L. F DALE, L. F, DALE, L. F DALE, L. F DALE, L. F.	8403210053 8403210105 8403210140 8403220147 8403220156	50-416 P 50-416 P 50-416 E 50-416 R 50-416 X	DAVERID, C A DAVERID, C A DAVERID, C A DAVIS, A B DAVIS, A B	8403230048 8403230073 8403260379* 8005010203* 8005280995*	50-322 T 50-322 T FOIA FOIA
CUNNINGHAM, O H CUNNINGHAM, L J CUNNINGHAM, R E CUNNINGHAM, R E CUMMO, M	8403140182 8208240003* 8403080144* 8403300307 8403020123	50-322	DALE, L. F. DALE, L. F. DALE, L. F. DALE, L. F. DALE, L. F.	8403240244 8403270094 8403270306 8403300007 8403300027	50-416 B 50-416 P 50-416 G 50-416 B 50-416 B	DAVIB,A B DAVIB,C B DAVIB,J F. DAVIB,J Q DAVIB,J Q.	8403080038* 8403280113 7906140348* 8403010022* 8403140240*	FOIA 50-313 8 50-312 P ACRB HIEC
CURRAN: D CURRAN: D, CURRAN: D CURRAN: D CURRAN: D	8403020173 8403020173 8403070232 8403070232 8403300263	50-443 Q 50-443 Q 50-443 Q 50-443 Q 50-443 Q	DALE, L F DALE, L F. DALE, L F. DALE, L F. DALE, L. F.	8403300037 8403300082 8403300097 8403300113 8403300114	#0-416 S 50-416 S 50-416 P #0-416 S 50-416 S	DAVISIK L DAVISIL A DAVISIM J DAYKINIH W DAYKINIH W.	8403290334 8403230197 8403070253* 8403140072 8403140072	FOIA NUREO 50-280 G TOPREP TOPREP
CURTIE, D. J. CURTIE, D. J CURTIE, N W CURTIE, N W CURTIE, N, W	8403120010* 8403120023* 8403010294 8403020329 8403050108	50-275 G 50-275 G 50-388 E 50-387 P 50-387 P	DALE, L. F DALE, L. F DALE, L. F DALTROFF, S. L. DALTROFF, B. L.	8403300117 8403300118 8403300124 8403370361 8403070081	50-416 S 50-416 S 50-416 S 50-352 F 50-277 Q	DE AGAZIO, A. DE GRASSI. 9 DEAL, L. J. DEBONB, A. DEBS, B. T.	8403260396 8403200067* 8403140166 8403160046 8403070072*	50-346 F 50-219 G PR ACRS 50-259 G
CURTIS.N W. CURTIS.N W. CURTIS.N W. CURTIS.N W.	8403050116 8403050122* 8403060175 8403060437 8403120127	50-387 P 50-387 P 50-387 Q 50-387 J 10PREP	DALTROFF, S.L. DALTROFF, S.L. DALTROFF, S.L. DALTROFF, S.L. DALTROFF, S.L.	8403070131 8403070270 8403150005 8403150137 8403210028	50-277 Q 50-352 F 50-277 P 50-277 P 50-352 F	DEBS.B.T DECKER.T.R. DECKER.TR DECKER.T.R. DEFAYETTE.R	8403270220* 8403070145* 8403160244* 8403270027* 8403080233	50-259 0 50-335 0 50-259 0 50-348 0 50-263 8
CURTIS.N W. CURTIS.N W. CURTIS.N W. CURTIS.N H. CURTIS.N.H.	8403120127 8403130111 8403130150 8403150070 8403170232	TOPREP 50-387 P 50-388 V 50-387 P 50-387 F	DALTROFF, 8 L DALTROFF, 8 L DANCE, H C DANCE, H C DANCE, H C,	8403270104 8403270250 8403020248 8403050177 8403070012	50-277 F 50-277 G 50-250 S 50-413 G 50-413 G	DEFAYETTE, R. DEFAYETTE, R. DEFAYETTE, R DEGENS, S. DEHOLLANDER, Q	8403130423 8403130423 8403170071 8403220178 8403200374*	50-155 8 50-263 8 50-255 6 50-308 D 40-8681
CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, N W, CURTIS, N W	8403170375 8403200006 8403200071 8403200073 8403200103	50-387 P 50-388 A 50-388 E 50-387 P 50-387 F	DANCE, H. C DANCE, H. C. DANCE, H. C. DANCE, H. C. DANCE, H. C	8403070018 8403070140 8403070205 8403070250 8403070327	50~424 Q 50~335 Q 50~413 Q 50~280 Q 50~413 Q	DEJU,R A DELAND,F,H. DELANEY,C.E DELGEDRGE,L C DELLA RATTA,A	8403300248 8403170326 8403020141 8403010083 8403070259*	PR 50-354 q 50-454 q 70-1100
CURTIB, N W, CURTIB, N W CURTIB, N, W CURTIB, N, W CURTIB, N W	8403210072 8403210081* 8403210125 8403210145 8403220040	50-387 K 50-387 K 50-388 8 50-389 S 50-388 A	DANCE, H. C. DANCE, H. C. DANCE, H. C. DANCE, H. C. DANCE, H. C.	8403070334* 8403080384* 8403150079 8403160086 8403160101	50-413 Q FOIA 50-280 Q 50-413 Q 50-369 Q	DELLA RATTA, A. DELLIGATTI, M DELO, H. A. DELOATCH, V. DEMOSS, G T	8403270066* 8403140132 8403060231 8403010003 8403270188*	70-398 HASTE MCT 50-219 H CONTRACY 50-244 P
CURTIB, N W CURTIB, N W CURTIB, N W CURTIB, N W CURTIB, N W	8403220069 8403220102 8403230075 8403260305 8403270175	50-387 Q 50-387 P 50-388 8 50-388 A 50-387 I	DANCE: H C. Dance: H C. Dance: H C. Dance: H C Dance: H. C	8403160110 8403160134 8403160176 8403160206 8403160207	50-369 Q 50-269 Q 50-321 Q 50-335 Q 50-424 Q	DENISE R P. DENNING, R. B. DENNING, R. S. DENNING, R S. DENTON, H R	8403120071 8403050227 8403050230 8403050242 8210220012*	50-267 P REB FOIA

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	CATEON
DENTON, H R DENTON, H R DENTON, H R. DENTON, H R DENTON, H, R	8210220084# 8211170102# 8212080672# 8212130052# 8212160059#	FDIA FDIA 50-267 P 50-267 P 50-267 P	DIEDERICH, Q J DIEDERICH, Q. J DIEDERICH, Q J DIEDERICH, Q J DIEDERICH, Q, J	8403190117 8403200032 8403200204 8403200212 8403230015	50-373 S 50-373 S 50-373 S 50-374 S 50-373 S	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	840315037& 8403170056 8403200304 8403200304 8403200341	50-272 50-320 50-275 50-320 50-320
DENTON, H. R.	B311230247* B312150232* B403010104* B403010108* B403010150*	FOIA FOIA FOIA FOIA 50-312 P	DIEDERICH.O. J DIEDERICH.O. J DIEDERICH.O J DIEDERICH.O J DIETY.C.R	8403230017 8403230027 8403280023 8403280073 8403010133	50-373 S 50-373 B 50-374 S 50-374 S 50-325 S	DIXON'O M DIXON'O M DIXON'O M DIKON'O M	8403280149 8403130026 8403020039 8403020297 8403040128	50-250 0A777 50-375 50-375 50-375
DENTON, H R DENTON, H R. DENTON, H, R DENTON, H, R. DENTON, H, R.	8403010477 8403010525 8403020029* 8403020041* 8403020045*	CDMMISSION 50-275 H 50-267 P 50-267 P 50-267 P	DIETZ.C R. DIETZ.C R DIETZ.C R DIETZ.C R. DIETZ.C R.	8403010135 8403010202 8403010279 8403010375 8403070023	50-324 S 50-325 S 50-324 S 50-324 S 50-324 S	DIXON'O M DIXON'O M DIXON'O M DIXON'O'M	8403040351 8403040351 8403070040 8403070129# 8403070337	50~395 50~395 50~395 50~395 50~395
DENTON, H. R DENTON, H. R. DENTON, H. R DENTON, H. R DENTON, H. R.	8403020046* 8403020048* 8403050217 8403060057 8403070014	50-267 P 50-267 P 50-460 A 50-265 P 50-460 A	DIETZ, C R DIETZ, C, R, DIETZ, C R, DIETZ, C R, DIETZ, C R,	8403070205 8403070235 8403130047 8403130078 8403130152	50-325 8 50-324 8 50-325 8 50-324 8 50-324 8	DIXON, O. W DIXON, O. W DIXON, O. W DIXON, O. W	8403080153 8403070052 8403070247 8403070271 8403130260	50~395 50~395 50~395 50~395 50~395
DENTON, H. R. DENTON, H. R DENTON, H. R. DENTON, H. R DENTON, H. R	8403070103 8403080350 8403080410 8403120261 8403140233	MISC FOIA 50-320 P 50-320 P MISC	DIETZ, C. R DIETZ, C. R DIETZ, C. R DIETZ, C. R DIETZ, C. R	8403130301 8403130323 8403130333 8403130404 8403150035	50-324 B 50-325 B 50-324 R 50-324 B 50-325 B	DIXON, O. W. DIXON, O. W. DIXON, O. W. DIXON, O. W	8403130371 8403130397 8403130042 8403210009 8403270183	50-395 50-395 50-395 PR 50-395
DENTON, H R DENTON, H, R DENTON, H R. DENTON, H R. DENTON, H R. DENTON, H R.	8403150345* 8403170107 8403220074 8403260106 8403280045	50-305 F 50-247 Q 50-275 P 50-275 U 50-341 H	DIETZ, C R. DIETZ, C R. DIETZ, C R. DIETZ, C R. DIETZ, C, R.	8403150179 8403150186 8403190302 8403200207 8403200273	50-324 8 50-324 9 50-325 9 50-324 8 50-324 9	B1XCN, O. W D1XON, O W. DODA, R. J DODDS, R. T DODDB, R. T	8403270223 8403300145 8403080170* 8403060344* 8403080270*	50-395 50-395 FOIA 50-344 50-397
DENTON, H. R. DERKS, P. S. DERKS, P S DEUTSCH, W J DEVINCENTIS, J	8403300235 8403020006 8403300075 8403230177 8403130468	10PREP 50-133 R 50-133 R NUREQ 50-443 S	DIETZ.C R. DIETZ.C R. DIETZ.C R DIETZ.R L DIGOB.R M	8403210123 8403210137 8403270266 8403230060 8403020222	50-324 B 50-325 S 50-324 S 50-538 R 50-206 P	DODDS, R. T. DODDS, R. T. DODPE, R. E. DODDDN, J. P. DODDON, M. E	8403120043 8403150121 8403300081 8403140122 8403070118	50-341 50-275 50-244 50-220 Nureo
DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J	8403150100 8403150100 8403160256 8403160256 8403210097	50-443 S 50-443 S 50-443 F 50-443 F 50-443 A	Digob, R M Digob, R M Digob, R M. Digob, R. M Digob, R M	8403020230 8403050233 8403070003 8403120270 8403120302	50-413 A 50-331 P 50-213 P 50-278 P 50-312 P	DDERFLEIN, L.T. DDERGE, D. H DDERGEB, J. E DDERING, J. DDHERTY, J. F	840307031&# 8403150214 8403270301 8403270048# 8403130057	50-933 50-30 FRM 50-352 50-456
DEVINCENTIS, J DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J.	8403210099 8403210142 8403210142 8403220005 8403220005	50-443 A 50-443 A 50-443 A 50-443 B 50-443 B	Dioos, R. M Dioos, R. M. Dioos, R. M. Dioos, R. M Dioos, R. M	8403140222 8403300241 8403300288 8403300275 8403300323	50-336 P 50-220 P 50-250 P 50-220 Q 50-243 P	DOMERTY, J.F BOHERTY, J.F DOLECEK, E. II DOMANUS, H. M DOMANUS, H. M	8403140040 6403270002 6403190317 6403300241 8403300265	50-456 ' 50-443 ' PR NUREO NUREO
DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J.	8403220150 8403220150 8403220164 8403220164 8403230061	50-443 B 50-443 S 50-443 B 50-443 B 50-443 A	Dignan, T. Q Dignan, T. Q. Dignan, T Q Dignan, T Q. Dignan, T Q	8403080142 8403080142 8403070073 8403070073 8403070124	50-443	DOMBY, A H DONCON, W J DONOFRIO, M DONOFRIO, M DONOFRIO, M	8403080370 8403290177 8403090289 8403020028# 8401120455	50-484 (50-280 i 50-213 ; FDIA 50-483 ;
DEVINCENTIE, J DEVINCENTIE, J DEVINCENTIE, J. DEVINE, J. B. DEVINE, J. B.	8403230061 8403270121 8403270121 8403200375 8403280072	50-443 A 50-443 A 50-443 A XPORTLIC XPORTLIC	Dignan, T Q. Dignan, T. Q Dignan, T Q. Diianni, D C Dircks, W J	8403090124 8403300269 8403300269 8403050238 7911120413*	50-443	DODLITTLE.E.L DOREMUB.R R. DOREMUB.B D DOROSHOW, J DORRIS.R.E	8403280286 840323008 8403080406* 8403130065 8403300342	50-423 50-322 50-328 50-289 MUREO
DEVINE, T. DEVINE, T. DEVINE, T DEVINE, T DEVINE, T.	8403150010 8403200133 8403200133 8403260364 8403260364	50-275 0 50-275 0 50-275 0 50-275 0 50-275 0	DIRCKS, W. J. DIRCKS, W. J DIRCKS, W. J DIRCKS, W. J. DIRCKS, W. J.	8007110203# 8202220054# 8203050045# 8204160230# 8209200364#	80-397 U FOIA FOIA FOIA FOIA	DOSS, K. C. DOTY, R. L. DOUDNIKOTT, B DOUDAN, J. R. DDUOHERTY, F. A	8403120029# 8403130059 84030300318 8403220022#	50-275 P 50-387 R CONTRACT NUREO 50-327 R
DEVINE, T M DEVINE, T. M DEVLIN, J W, DEWEY, L. B, DEYDUNO, R. C	8403060303* 8403060303* 8403080087* 8403190164 7911120370*	50-275 Q 50-275 Q FDIA 50-354 Q 50-312 P	Dircks, M. J Dircks, M. J Dircks, M. J Dircks, W. J	8212080693* 8212100130* 8301140173* 8301280380* 8312140347*	50-267 P FOIA FOIA 50-382 A 50-275 E	DOUGHTY, J. DOUGLAS, M. DOVER, B DOVER, R P. DOYLE, J.	8403010385 8403010856 8403140160 8403070819* 8403070108*	FOIA 50-219 B PR 50-413 A 50-448 T
DEYOUNG, R. C.	8311130481# 8401250456# 8402070031 8403020025# 8403120234	50-312 P 50-267 P 50-3 G FDIA 40-6920	DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J.	831 2280099* 840 2220050 840 3010032* 840 3010109 840 3010268*	50-275 E SECY 50-334 B REVIEW ORP 50-247 P	DRAGOUN.T. DRAPER.D M. DRAWERIDGE.B L DRISCOLL.F DRUMMOND.F.J.	8403150017* 8403800283 8403800215 8403140172 8403120014	50-217 q 50-315 g 50-27 g PR 50-382 F
DEYDUNG, R. C DEYDUNG, R. C. DEYDUNG, R. C DEYDUNG, R. C DEYDUNG, R. C	8403120242# 8403120305 8403120308# 8403120311# 8403220245	40-6920 50-293 F 50-293 F 50-293 F 50-454 Q	DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J.	8403010274* 8403010329 8403010451 8403010497 8403020027*	FDIA REVIEW ORP 50-206 8 50-329 A 50-267 P	DUBINBRI, L. DUBOIB, D. DUBOIB, D DUBOIB, D DUBOIB, D	8403260136* 8403060075 8403200305 8403220230 8403220236	A0-1478 XPORTLIC XPORTLIC XPORTLIC XPORTLIC
Dick, Q.F Diederich, Q.J. Diederich, Q.J. Diederich, Q.J. Diederich, Q.J	8403040290 8403020138 8403040150 8403120020 8403120047	50-244 F 50-373 R 50-373 R 50-373 R 50-374 B	DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J DIRCKS, W. J	8403020035* 8403020032* 8403020443 8403050234 8403080011	FDIA FDIA 50-275 R 50-416 P 50-254 B	DUBDIB, D. DUCK, J. R. DUCK, J. R. DUCK, J. R. DUCK, J. R.	8403260011 8403060224 8403060234 8403060277 8403060281	XPORTLIC 50-327 J 50-335 J 50-390 J 50-321 J
DIEDERICH, O. J. DIEDERICH, O. J. DIEDERICH, O. J. DIEDERICH, O. J. DIEDERICH, O. J	8403120034 8403120080 8403120075 8403160261 8403160266	50-373 8 50-373 8 50-373 8 50-373 R 50-374 8	DIRCKS.W.J DIRCKS.W.J DIRCKS.W.J. DIRCKS.W.J DIRCKS.W.J	8403080041 8403080436 8403090019* 8403120388* 8403140206	SECY FOIA COMMISBION 50~382 U	DUCK, J. R. DUCK, J. R. DUCK, J. R. DUCK, J. R. DUCK, J. R.	8403060332 8403060353 6460606048 6440306048 8440406048	50-250 J' 50-259 J 50-302 J' 50-438 J 50-348 J

AUTHER	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY
DUCK, J R DUCK, J R DUCK, J R DUCK, J R	8403070175 8403140044 8403280038 8403280053 8403020147	50-327 J 50-348 J 50-321 J 50-348 J 50-327 B	EDELMAN, M R EDGAR, G L EDGAR, G L EDGAR, G L EDGAR, G L	8403270224 8403020100 8403020100 8403040082 8403070084	50-440 @ 50-537 @ 50-537 @ 50-537 @ 50-537 @	ELTIS' A ETTIS' A ETTIS' A ETTIS' A	8403070177 8403070182* 8403070104 8403070128 8403140034	50-445 Q 50-445 T 50-445 T 50-445 Q 50-445 Q
DAGOIN' O DAGOIN' C DAGOIN' C DAGOIN' C	8403050080 8403060276 8403150079 8403190121 8403190365	50-327 S 50-327 S 50-327 S 50-327 S 50-327 S	EDGAR, O L EDGAR, O L EDGAR, O L EDGENORTH, P EDGENORTH, P	8403070086 8403230186 8403230186 8403070337 8403150206	50-537 Q 50-556 Q 50-556 Q CONTRACT CONTRACT	ELLIB, J ELLIB, J ELLIB, J	8403170004 8403170024 8403170032 8403260007 8403200012	50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-445 Q
DUGGIN.G DUGGIN.G DUGSTAD.D. DUNNHAY.F R DUNLAP.J M	8403300073 8403300204 8403300075 8403220165* 8403070259*	50-327 S 50-328 S 50-262 R 50-295 Q 70-1100	EDWARDS, D L. EDWARDS, D L EISENHOWER, E H EISENHUT, D G EISENHUT, D O	8403150242 8403150264 8403070214 7711120317* 8102200027*	40-3453 40-3453 PR 50-312 P 50-466 A	ELLIS, J ELLIS, J ELLIS, J ELLIS, J	8403200025 8403200026 8403200049 8403200073 8403200114	50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-445 Q
DUNLAP, J M DUPONT, B C DURDEL, R R DURKOSH, E D DURR, J	8403270205* 8403300057* 8403270167 8403270238 8403270104*	50-320 G 50-341 G 50-346 F PRM 50-219 G	EISENHUT, D Q EISENHUT, D Q EISENHUT, D G EISENHUT, D Q EISENHUT, D Q	B110190026* B309210434* B312050628* B401120425 B401120425*	50-308 F 50-322 A 50-329 A 50-445 A 50-445 A	ELLIS, J ELLIS, J ELLIS, T ELLIS, T ELLIS, T ELLIS, T	8403200118 8403200124 8403200147 8403010242 8403010242	50-445 Q 50-445 Q 50-445 Q 50-322 Q 50-322 Q
DURR, J P DURR, J P DURR, J P DURR, J P DURR, J P	8403020272* 8403020309* 8403070322* 8403220062* 8403270062*	50-293 0 50-277 0 50-277 0 50-309 0 50-334 0	EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q	8402070004 8402070006 8402070012 8402070017 8402070020	50-275 P 50-247 F 50-275 Q 50-275 P 50-322 S	ELLIS, T, S ELLIS, T S ELROD, S ELROD, S ELROD, S	8403010249 8403010249 8403070253* 8403270132* 8403270291*	50-322 0 50-322 0 50-280 0 50-335 0 50-338 0
DURR. J P DURR. J P DUR. J P DUS. R S DUVALL. D D	8403270272* 8403300076* 8403300103* 8403200204 8402010185*	50-29 Q 50-322 Q 50-354 Q 50-373 S GA997	EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8402070021 8402070022 8402070030 8402070032 8402070033	50-322 8 50-275 9 50-275 E 50-275 T 50-322 8	ELROD, 9, ELROD, 8 A ELROD, 8 A ELBABBER, T C ELBABBER, T C	8403270274* 8403160268* 8403270180* 8403010404* 8403020305*	50-338 0 50-335 0 50-335 0 50-213 0 50-54 0
DUVALL.D D DYBELL.J C DYNNER.A R DYNNER.A R EALEY.D	8403270219 8403150306# 8403220250 8403220250 8403020374	50-204 B CONTRACY 50-322 0 50-322 0 WASTE MOT	EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8402070035 8402070038 8402070037 8402070041 8402140527	50-322	EMCH, R, L EMCH, R L. EMERBON, W F EMERY, R S ENGEL, R E	8403160122 8403280034 8403200182 8403170407* 8403140006	50-155 P 50-155 P 50-423 A 50-317 Q TOPREP
EARLEY, A F EARLEY, A F EARLEY, A F EBERBOLE. J C EONETER. S D	8403210177 8403210177 8403280043 8401300121 8402140043*	50-322 0 50-322 0 50-322 0 50-400 0 50-528 0	EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	8402140536* 8403010020* 8403010180* 8403010204* 8403010211*	90-331 P 50-289 P 50-250 F 50-329 A 50-329 A	ENGLE, L B ENGLE, L B ENGLE, L B ENNIB, J D	8403050178 8403210203 8403220208 8403260273 8403150107*	50-338 P 50-338 P 50-338 P 50-338 P 50-280 Q
EBNETER, 8 D ECHBERO, 8 R ECKERT, J P ECKERT, J P ECKERT, J P	8403150034* 8403280191* 8401240315* 8403070149* 8403070153*	50-388 0 FOIA 70-27 70-27 70-27	EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	9403010223* 8403010245* 8403010273* 8403010501 8403020021*	50-329 A 50-329 A 50-329 A 50-275 P FOIA	ennis, J d ennis, J d enos, B epstein, E epstein, E	8403260183* 8403300044* 8403080401 8403080036* 8403080045*	70-27 70-27 FOIA FOIA FOIA
ECKERT, J P ECKHARDT. J ECONOMOS, N EDDINGS, M G EDDLEMAN, W	8403300015# 8403230117 8403160363* 8403300154 8403050061	70-27 50-312 S 50-413 Q 50-327 R 50-400 E	EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8403020175* 8403020221* 8403030127 8403050341* 8403060009*	50-286 F 50-373 F 50-206 F 50-265 P 50-261 P	EPSTEIN, E, EPSTEIN, E ERICKSON, J, ERICKSON, R W ERNST, M L,	8403080049* 8403080058* 8403150210 8403070141* 8201220170*	FOIA FOIA 40-299 CONTRACY FOIA
EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W	8403130001 8403130186 8403130196* 8403130220* 8403130230*	50~400 0 50~400 0 50~400 0 50~400 0 50~400 0	EISENHAL'D O EIBENHAL'D O EIBENHAL'D O EIBENHAL'D O	8403060449* 8403060453 8403060466* 8403060473 8403060476	50-344 P 50-416 B 50-338 F 50-289 P 50-289 P	ESELGROTH, P EGELGROTH, P EGHELMAN, E. M ETCHIGON, D ETZLER, R D	8403170285 8403230074 8403130297 8403060313 8403120018*	50-322 8 50-322 8 50-317 8 50-456 D 50-275 9
eddleman, H Eddleman, H Eddleman, H Eddleman, H Eddleman, H	8403200048 8403220222 8403220227 8403220265 8403220265	50-400 0 50-400 0 50-400 0 50-400 0 50-400 0	EISENHUT, D Q EISENHUT, D, Q EISENHUT, D Q EISENHUT, D Q	8403040510* 8403040529 8403070354 8403070348 8403120342*	50-261 F MISC 50-416 P 50-313 P 50-312 F	ETZLER, R. D. EURE, J. A EVANS, C. A EVANS, C. D. EVANS, C. D	8403120029* 8403170387 8403240220* 8403120145* 8403170076*	50-275 9 PR 50-458 0 50-263 0 50-373 0
eddleman, w eddleman, w eddleman, w eddleman, w eddleman, w	8403220270 8403220270 8403280344 8403280347 8403280349	50-400 G 50-400 G 50-400 G 50-400 G 50-400 G	EISENHUT, D G EISENHUT, D, G EISENHUT, D G EISENHUT, D G	8403120359* 8403140128 8403140239* 8403140244 840314025&*	50-302 F TOPREP 50-324 F 50-275 Q 50-298 F	EVANG,E A EVDOKIMOFF, V. N EVERETT, R FAILLA, C. V. FAIR, J. R	8403300248 8403130218 8403260109* 8403260342* 8403190116*	MASTE HOT PR 40-1341 50-322 T 50-275 0
EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDELMAN, M R	8403280351 8403280360 8403280361 8403280361 8402270274	50-400 0 50-400 0 50-400 0 50-400 0 50-440 8	EISENHUT, D. G EISENHUT, D. G EISENHUT, D. G EISENHUT, D. G EISENHUT, D. G	8403140290 8403140305# 8403150250# 8403150268 8403150275	50-271 F 50-250 G 50-346 F 50-388 A 50-10 P	FAIRTILE.M B FAKLER.J.L. FALCONER.D FALCONER.D FALEVITS.Z	8403270044* 8403060322* 8403070369* 8403270108* 8403170076*	FD1A 50-322 T 50-269 0 50-373 0
EDELMAN, M. R. EDELMAN, M. R. EDELMAN, M. R. EDELMAN, M. R. EDELMAN, M. R.	8403050181 8403120052 8403120076 8403120126* 8403130072	50-440 A 50-440 S 50-440 S 50-440 Q 50-440 A	EIGENHUT, D.Q EIGENHUT, D.Q EIGENHUT, D.Q EIGENHUT, D.Q EIGENHUT, D.Q	8403150295* 8403150343 8403170433 8403220023* 8403260265*	50-346 P 50-305 F 50-272 F 50-155 F 50-321 F	FALLB, O. B. FALLB, D. B. FALLB, O. B FALLS, O. B. FALLB, O. B	8403070314 8403070316* 8403070321* 8403070325* 8403070327*	Toprep Toprep Toprep Toprep
EDELMAN, M R EDELMAN, M R EDELMAN, M R EDELMAN, M R EDELMAN, M R	8403130194 8403190051 8403190375 8403190391 8403230011	50-440 F 50-440 B 50-440 A 50-440 A 50-440 S	EIBENHUT, D G EIBENHUT, D G EIBENHUT, D. G EIBENHUT, D. G EJIMA, M	8403260308* 8403280129 8403280283 8403280287 8403050033	50-344 F 50-483 A 50-397 P 50-374 P XPORTLIC	FALLB, Q. B. FALLB, Q. B. FALLB, Q. B FALZONE, R. R FALZONE, R. R	8403070328* 8403070330* 8403300237* 8403130012 8403130012	Toprep Toprep Toprep 50-322 0 50-322 0
EDELMAN, M R EDELMAN, M R EDELMAN, M, R. EDELMAN, M, R. EDELMAN, M, R.	8403230045 8403230047 8403230083 8403230101 8403260247	50-440 S 50-440 A 50-440 S 50-440 E 50-440 S	EL-BASSIONI, A ELDER, M L ELLIDTT, C W ELLIOTT, C W. ELLIOTT, C W	8403010041* 8403270314 8403270060 8403270069* 8403300129	FOIA 50-270 P 50-352 Q 50-352 Q 50-352 Q	FALZONE, R. R. FALZONE, R. R FALZONE, R. R. FALZONE, R. R FARBER, M. J.	8403130109* 8403130109* 8403260377 8403260377 8403080261*	50-322 9 50-322 9 50-322 T 50-322 T 50-483 0

AUTHOR	ACCESSION NUMBER	SUBJECT	4	AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR	ACCEBBIDN NUMBER	CATEOD:	
FARMER, W. B FARRAR, D FARRAR, D. L FARRAR, D. L FARRAR, D. L	84032900124 8403020131 84030501714 84030501744 8403140151	50-295 50-373	P F G F	ELTON, J M ELTON, J M ELTON, J M ELTON, J. M ELTON, J. M	8403040449 8403040484 8403070101 8403070110 8403070218	FOIA 50-329 FOIA FOIA 50-440	Α Α	FINN, 8 FINN, 8 FINN, 8 FINN, 5 FINN, 8	8403080010* 8403080012* 8403080017* 8403080017* 8403080025*	FOIA FOIA FOIA FOIA	
FARRAR, D. L. FARRAR, D. L. FARRAR, D. L. FARRAR, J. P. FARRELL, E. V.	8403190090± 8403200041 8403260237± 8403010397 8403130426	50~373	F F G F R F	ELTON, J M ELTON, J. M ELTON, J. M ELTON, J M ELTON, J M	8403070227 8403080005 8403080016 8403080027 8403080030	50-329 FDIA FOIA FOIA FOIA	8	FIORELLI.0 FIORELLI.0 FIORELLI.0 FIORELLI.0 FISCHER.D L	8403070340* 8403070343* 6403080263* 8403270139* 8403270022*	50~327 50~327 50~528 50~528 50~293	8 9 9
Farrell, R E Faband, A. Faband, A Faband, A Fabond, A.	8403050134* 8403060103 8403060144 8403060435 8403130471*	50-320 50-320 50-320	9 F1 9 F1	M C,NOTJE LC,NOTJE M C,NOTJE M C,NOTJE M C,NOTJE	8403080068 8403080096 8403080126 8403080179 8403080203	FDIA 50-275 FOIA 50-507 50-413	E A G	FISCHER, D L FISH, R F FISHCHOFF, B FISHER, R FISHER, W L	8403270024* 8403080152* 8403190444 8403150340* 8102240058*	50-293 50-528 NUREO 40-8829 FOIA	P
FAURI, N F. FAWELL, T. W. FAY, C. W FAY, C. W FAY, C. W.	8403080216* 8403020130 8403060358 8403070255 8403120066	40~2041 50-244 50-244	F	ELTON, J. M. ELTON, J. M ELTON, J. M. ELTON, J. M. ELTON, J. M	8403080207 8403080219 8403080325 8403080339 8403080347	FOIA FOIA 50-445 50-280 50-336	G G P	FITCH,W L. FITTI,C V. FITZOERALD,J A FITZPATRICK,B FLACK,E	B403120174 B003240217# B403020074# B403130023# B403010375	50-508 50-508 FOIA 50-246 I&E	D A
FAY, C. W FAY, C. W. FAY, C. W FAY, C. W FAY, C. W.	8403120157 8403130005 8403140139 8403160054 8403160080	50-266	P FE	ELTON, J. M. ELTON, J. M ELTON, J. M ELTON, J. M ELTON, J. M.	8403080357 8403080367 8403080372 8403080375 8403080390	FDIA 50-322 50-424 FDIA 50-528	A Q D	FLACK, E. FLACK, E FLACK, E FLACK, E. FLACK, E.	8403050094 8403060119 8403130408 8403130445 8403160001	196 10-571 176 176 176	В
FAY, C. W FAY, C. W. FAY, C. W. FAY, C. W FAY, C. W.	8403210029 8403210077 8403220099* 8403220162 8403230068	PR 50-266 (50-266 (50-266 (50-301 (FE FE	ELTON, J. M ELTON, J. M. ELTON, J. M. ELTON, J. M. ELTON, J. M	8403080391 8403080398 8403080404 8403080405 8403080419	FDIA FDIA FDIA 50-275 50-206	E G	FLACK, E FLEENOR, C FLEIBCHMANN, R FLIPPO, T A FLORY, C,	8403190335 8403280049 8403230012 8403130140* 8403280259	40-8681 CONTRACT 50-171 50-382 MASTE NO	R
FAY, C, W FAY, C W, FAY, C, W FAY, C, W FEDERMAN, P J	8403240072 8403270078 8403270125 8403270237 8403300325	50-266 8 50-266 8 50-266 8 50-266 8 NUREQ	FE FE	ETON, J. H ILTON, J. H ILTON, J. H ILTON, J. N ILTON, J. N.	8403070006 8403070017 8403070018 8403070021 8403070028	FOIA FOIA 50-322 FOIA 50-275	A P	FLORY, 8. FLOHER, M FLYNN, 8 F FLYNN, 8, F FOLAHEE, J 8,	8403050330 8403140233* 8403190137 8403190141* 8403190071	MIBC 50-267 50-400 50-400 50-155	р О О
FEHRINGER, J. M FEIERABEND, C FEIERABEND, C. D FEITKNECHT, C. FELDER, R.	8403260335 8403290180* 8403190042* 8403010126 8403070267*	50-416 P 50-335 G 50-282 G 50-334 R 70-474	PE FE FE	LTON, J. M. LTON, J. M LTON, J. M. LTON, J. M. LTON, J. M	8403070032 8403260123 8403280080 8403280163 8403280167	50-382 40-1478 FOIA FOIA FOIA	A	FOLEY, W J FONNER, R L FORD, E, J FORD, J T	8403080197* 8403220231 8403070163* 8403160225* 8403010162	WASTE MOT	CI CI CI
FELTON, J M. FELTON, J, M FELTON, J M, FELTON, J M FELTON, J, M,	8401230630 8401260161 8402090003 8402140018 8402230207	50-329 0 50-264 F 50-352 A 50-528 0 50-400 A	FEI FEI	LTON, J. M. LTON, J. M. LTON, J. M. LTON, J. M. ROUBON, C. E.	8403280216 8403270002 8403270338 8403270341 8403270102*	50-462 50-266 FOIA 50-528 50-461	G P D I	FORNEY, W L. FORNESTER, R D FOBTER, D O. FOBTER, D O. FOSTER, D, O.	8403170323# 8402140052# 8403010317 8403010354 8403070077	50-528 50-424 50-424	Q Q K B B
Felton, J M, Felton, J M Felton, J, M, Felton, J, M, Felton, J, M,	8492270263 8403010013 8403010014 8403010016 8403010024	50~321 G 50~447 A 50~289 P 50~334 S FOIA	FEF FEF FE1	RKIN, Z. Q. RKIN, Z. Q RRELL, J. R. Y. F. L Y. F. L.	8403120001 8403300122 8403080154* 8403060285 8403090207	50-352 F01A 50-243	0 9 F	FOSTER.D.O FOSTER.D.O FOSTER.D.O FOSTER.D.O FOSTER.D.O	8403120146 8403150023 8403150038 8403150043 8403150049	50-424 50-424 50-424	8 H V B
FELTON, J. M.	8403010026 8403010050 8403010068 8403010072 8403010074	FOIA 50-509 A FOIA FOIA	FEY FEY FIE	/,F L /,F, L, /,F L EDLER,D G EDLER,P,	8403130079 8403130245 8403300130 8403190203 8403160057	50-282 50-282 04999	R R F	FOSTER, D. O. FOSTER, D. O. FOSTER, E. R FOSTER, J. FOSTER, J.	8403170105 8403270037 6403010217 8403050105 8403070352	50-424 50-336 50-369	9 0 6 F
FELTON, J. M.	8403010100 8403010113 8403010117 8403010123 8403010125	FDIA 50-508 T 50-348 P 50-312 P 50-498 Q	FIE FIE FIE	EDLER, P. B EDLER, P. B EDLER, P. B. EDLER, P. B. EDLER, P. B.	8403010256 8403010261* 8403020128 8403080231 8403090073*	50-219 50-219 50-219	명 명 R V Q	FOSTER, L. FOSTER, L. E. FOSTER, R. F FOSTER, R. F FOSTER, R. F FOX, C. D	8403160319# 8403130497# 8403060111 8403200042 8403070120	50-312 50-508 50-413	G G G G
FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M	8403010168 8403010178 8403010262 8403010279 8403010383	FDIA 50-329 A 50-247 P FDIA FDIA	FIE FIE FIE	DLER, P. B DLER, P. B DLER, P. B. DLER, P. B. DLER, P. B.	8403130199 8403150083 8403140208* 8403170063 8403200054	50-219 50-219 50-219	P Q G G	FOX,C D. FOY,J.M FRAGOLA,J FRANCE,Q.M FRANKLIN.L.A	8403070120 8403070120* 8403010041* 8403130094* 8403290234*	50-46) FOIA 40-3392	9 9
FELTON, J. M FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M.	8403010407 8403010410 8403010480 8403020011 8403020014	FOIA FOIA FOIA FOIA 50-267 F	FIE FIE FIE	DLER, P. B DLER, P. B. DLER, P. B. DLER, P. B. DLER, P. B.	8403220002 8403220012 8403220152 8403230110 8403230119	50-219 50-219 50-219 50-219 50-219	P F R	FREEMAN, M, D FREEMAN, M, D FREEMAN, M D FREEMAN, B, D FREUDENBURO, W	8403010071 8403130272 8403130274 8403200057 8403200238		9
FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. H. FELTON, J. H.	B403020109 B403020395 B403020405 B403020435 B403050020	FDIA 50-289 P FDIA 50-440 A 50-286 P	F151 F151 F161	DLER, P. B. DLER, P. B. DLER, P. B. LDB, D. LDB, J. A.	8403260074 8403270165 8403300001 8403060283 8403130494	50-219 F 50-219 F 50-219 F 50-302 F CONTRACT	± ₹	FRIEDMAN FRIEND, H. B. FRIEHMAN, S. FRITZ, D. M FRIZZLE, C. D	8402210133 8403120022* 8403230025 8403150212 8403300160	1&E 50-275 WASTE MOT 40-8463	Q
FELTON, J. H. FELTON, J. H FELTON, J. H. FELTON, J. H. FELTON, J. H	8403050057 8403050040 8403050044 8403050223 8403050288	FDIA FDIA 50-400 E 50-305 P 50-509 A	FIN FIN FIN	LDB; J. B AMORE; B. A. AMORE; B. A KEL; A. KEL; A	8403090232 8403190120 8403190120 8403070242# 8403090043#	50-367 6 50-537 6 50-537 6 50-387 6 50-354 6) }	FRYE, D. L. FRYE, D. L. FRYE, J. H FRYE, J. H FRYE, J. H.	8403010155# 8403010167# 8403070079 8403070119 8403170177	50~267 40~2061 40~2061	8 8
FELTON, J. M. FELTON, J. M. FELTON, J. M. PELTON, J. M FELTON, J. M	8403050091 8403050123 8403050148 8403050158 8403050169	FDIA FOIA FOIA FDIA	FINA			50-322 THASTE HOT HASTE HOT FOIA		FRYE, J. H. FUJITA, N. FULLER, C FULTON, J. F. FULTON, J. F.	8403240003 8403080009* 8403170344 8403270188* 8403270187*	50-29 50-247 50-244	e R P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FUNCHES.J L FURR.B J FURSE.M C FURSE.M C FURSE.M C	8301140486* 8403130070 8403060188 8403060188 8403060202*	50-267 P 50-324 S 50-155 G 50-155 G 50-155 G	GAYNDR.R K GEALY.W J GEBELE,H W GEKAS.G W GERDEMAN,F W	8403020377 8403050237* 8403010409 8403070073* 8403150213	27-48 CONTRACT FDIA 50-289 U 40-8698	QLABSPIEGEL, H GLENN, J GLENN, J GLENN, J GLENN, J E	8403040280* 8402210133 8403070283 8403080060* 8403070264	50-440 @ 1&E 50-273 S FOIA 70-474
FURSE, M C FURSE, M C GAD, R K GAD, R. K GAD, R. K	8403060202* 8403120035 8403070042 8403070042 8403080142	50-155	GERDEMAN,F W GERDEMAN,F W GERETY,H F GERNER,L GERRETS,T F	8403150249 8403220183 8403280010 8403090294 8403010069	40~8698 40~8698 50~289 J 50~254 F 50~382 8	GLENN, J E GLENN, J E GLENN, J E GLOERSEN, W	8403080050* 8403080070* 8403080087* 8403080102* 8403200119*	FOIA FOIA FOIA FOIA 50-483 Q
GAD.R K QAD.R K GAD.R K GAD.R.K QAD.R.K	8403080142 8403210101# 8403210101# 8403230180 8403230180	50-443 0 50-443 A 50-443 A 50-443 0 50-443 0	OERRETS, T F OERRETS, T F GERRETS, T F GERRETS, T F GERRETS, T F	8403060196 8403060258 8403060339 8403130267 8403130303	50-382 8 50-382 8 50-382 8 50-382 8 50-382 8	GLDVER: M S GLDVER: M S GUDDARD: R GUDDARD: R J GUDDARD: R J	8403070276 8403140231 8403070123* 8403140037 8403140096	50-349 F 50-349 F 50-441 G 50-441 G
GAD.R.K GAD.R.K GAGLIARDO.JE GAGLIARDO.JE GAGLIARDO.JE	8403300269 8403300269 8402210343* 8402210348* 8403050179	50-443	GERRETS.T F GERRETS.T F GERRETS.T F GERRETS.T F GERRETS.T F	8403130311 8403130337 8403130427 8403130436 8403170250	50-382 8 50-382 8 50-382 8 50-382 8 50-382 8	GODDARD, R J GODDARD, R J GODDARD, R, J GODDARD, R J GODDARD, R J	8403140097* 8403140106 8403140126 8403140135 8403140142	50-155 Q 50-461 Q 50-322 Q 50-461 Q 50-461 Q
GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E	8403060198 8403120147 8403130120 8403130250 8403130320	50-313 0 50-285 0 50-313 0 50-482 0 50-482 0	GERRETS,T F GERRETS,T F GERRETS,T F GERRETS,T F GERRETS,T F	8403170253 8403170262 8403170272* 8403170368 8403200022	50-382 B 50-382 S 50-382 Q 50-382 S 50-382 S	GODDARD, R J GODDARD, R J GODY, A T GODY, A T GODY, A T	8403170219 8403170220* 8403020220* 8403020379* 8403270150*	50-416 Q 50-416 Q 50-388 Q 50-273 Q 50-352 Q
GAGLIARDD, J E GAGLIARDD, J E GAGLIARDD, J E GAGLIARDD, J E OAGLIARDD, J E	8403130390 8403130395 8403160119 8403190057 8403190225	50-482 0 50-313 0 50-482 0 50-285 0 50-482 A	GERRETS, T F GERRETS, T F GERRETS, T F GERRETS, T F GERRETS, T F	8403200267 8403200276 8403270040 8403270046 8403270059	50-382 8 50-382 8 50-382 8 50-382 8 50-382 8	GOLDBERG, J R. GOLDBERG, J R GOLDBERG, S M. GOLDEN, M P GOLDEN, M P	8403010043* 8403210024 8403130499* 8403260197 8403280058	50-289 P 50-289 Q 50-312 Q 50-272 J 50-272 J
GAGLIARDD: J E GAGLIARDD: J E GAGLIARDD: J E GAGLIARDD: J E. GAGLIARDD: J E	8403190277 8403190279 8403190283* 8403200169 8403200178	50-313	GERRETS,T F GERRETS,T F GERRETS,T F GERRETS,T F GERRETS,T F	8403270095 8403270102 8403270161 8403270202 8403270206	50-382 8 50-382 8 50-382 9 50-382 9 50-382 9	GDLLER, K R GOLLNICK, D A GOODARD, R J GOODE, D GOODE, D	8403050028* 8403130327 8403210078 8403160056 8403160077	50-295 () PR 50-322 Q WASTE HOT 27-39
QAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E	8403220185 8403260070 8403260168 8403260230 8403300046	50-313 F 50-313 Q 50-285 Q 50-313 Q 50-313 Q	GERWIN, E F. GIACOBBE, F. B GIAMBUSSO, A GIANGI, Q J GIBBONS, T D	8403270155 8403130451# 7711120403# 8403270232 8403060252#	M18C 50-287	GOODIE, J 8 GOODLING, B GOODMAN, L. B GOODMAN, L. & GOODMAN, L &	8403010344 8403210137 8403020161 8403200163 8403300131	27-39 50-289 0 50-409 R 50-409 B 50-409 R
GA1THER.C F GALLAGHER.J GALLAGHER.J R GALLO,J GALLO,J	8402140037* 8403090055 8403080227 8403010203 8403010203	50-528 Q 50-352 Q 50-454 D 50-155 Q	O M. WOBBIO C. WOBBIO C. WOBBIO C. WOBBIO O. WOBBIO	8403270154* 8403020133 8403300080 8403070303 8403280109	50-416 G 50-336 R 50-336 R 50-348 F 50-348 F	GOODHIN, E F GORDON, C Z GORDON, R GORDON, R GOBCH, C	8208070297* 8403210054* 8403220264 8403220279 8403130106*	50-284 D 50-320 Q XFORTLIC XFORTLIC 50-440 A
GALLO, J GALLO, J GALLO, J GALLO, J	8403060192* 8403060192* 8403060202* 8403060202* 8403160011	50-135	GIESEKE.J A GIESEKE.J A GIESEKE.J A GIESEER.C W GIESERR.C W	8403050227 8403050230 8403050242 8402170104 8403020295	REB 50-280 P REB 50-305 P 50-305 P	QOSCH, C. QOSCH, C. QOSSICK, L. V QOSSICK, L. V	8403130118# 8403130128# 8403130138# 8402230226# 8402230242#	50-440 A 50-440 A 50-440 A 50-400 A FOIA
DALLO, J GALLO, J GALLO, J GALLO, J	8403160011 8403160023 8403160023 8403190004 8403190004	50-456 0 50-456 0 50-456 0 50-155 0 50-155 0	GIESLER,C W GIESLER,C W GIESLER,C W GIESLER,C W GIESLER,C W	8403040408 8403130147 8403130188 8403140278 8403140327	50-305 R 50-305 R 50-305 P 50-305 J 50-305 P	GDSSICK,L V GOTCHY,R GDULD,T.L GRACE,J.N GRADY,D	8403050031# 8005150483# 8403280004 8402070007 8403280125	FOIA FOIA 50-320 B 50-3 Q 50-280 F
GALLO, J GALLO, J GALLO, R. GALLO, R. M GAMMIE, G. B	8403200130 8403200130 8403150073* 8403020308* 8403140036	50-155	GIEGLER, C, W GIEGLER, C W GIEGLER, C, W GIEGLER, C W GIEGLER, C W	8403200016 8403200154 8403210009 8403270030 8403280048	50-305 Q 50-305 P PR 50-305 P 50-305 P	GRAEBBER.K.L GRAEBBER.K.L GRAEBBER.K.L GRAEBBER.K.L GRAEBBER.K.L	8403060217 8403060249 8403080174 8403090164 8403090174	50-295 R 50-295 S 50-304 0 50-295 S 50-304 S
GAMMILL.W P GANT, R E. GARCIA, A A GARCIA, P. J GARCIA, P. J	8207140072* 8403270107* 8403140334 8403060465 8403170431	30-400 E 50-461 I ACRS 40-3453 40-3453	OIL INSKY, V OIL INSKY, V OIL INSKY, V	8403270222 8403070276 8403200043 8403200075 8403280157#	GA999 50-349 F 50-454 U 50-454 U COMMISSION	GRAESSER, K.L. GRAESSER, K.L. GRAESSER, K.L. GRAESSER, K.L. GRAESSER, K.L.	8403170156 8403200173 8403270035 8403270107 8403270203	50-295 R 50-304 B 50-295 B 50-295 B 50-295 B
CARCIA.P.J GARDT,BP GARDE,BP GARDE,BP GARDE,BP	8403200377 8403010172 8403010488 8403020102 8403080085	40-3453 50-327 A 50-327 A FDIA 50-275 E	GILINGKY,V GILLEN,D,M GILLET,W T GILLET,W T	8403280248 8403200372 8403020007 8403020044 8403300155	COMMISSION 40-8827 50-316 R 50-315 R 50-316 R	GRAEBSER, K.L. GRAHAM, D GRAHAM, D GRAHAM, J. Q GRAMM, R.A.	8403270265 8403060283 8403160036 8403220195 8403220195	50-295 8 50-302 R 50-302 R 50-320 P 50-410 Q
GARDE, B P GARDE, B P GARDNER, R. N GARNER, D GARNER, L. H	8403080196 8403270173 8403060398* 7906140545* 8403070310*	50-413 A 50-445 H 50-327 Q 50-312 P 50-324 Q	GILLETT, W T GILOMEN, B R GILOMEN, B R. GILOMEN, B, R GILOMEN, B R.	8403300157 8403020146* 8403020146* 8403200011	50-315 R 50-275 e 50-275 e 50-327 e 50-327 e	Grange, G Grange, G. J Grange, G. J Grant, N. W Grant, N. W.	8403270073 8403140088 8403150118 8403020033 8403300185*	50-320 F 50-289 F 50-320 F 50-250 R 50-250 R
GARMER, L. W GARY, R J. GARY, R J. GARY, R J. GARY, R J.	8403270072* 8403040155 8403080335* 8403160077 8403160213	50-324 Q 50-445 A 50-445 G 50-445 A 50-445 B	GILOMEN, BR. GILOMEN, BR. GILECLON, JM GLASS, D. J GLASS, J.	8403270020 8403270020 8403120029* 8403140221 8403190449	50-329 0 50-329 0 50-275 0 PRM NUREO	ORANT, N W. ORANT, W B. GRAVEB, R. H. GRAVEB, R. H ORAY, E. H	8403300193* 8403200291* 8403030073 8403300176 8403020379*	50-250 R 50-243 G 50-213 R 50-213 R 50-293 G
GABAND, A. GAVAZZI.A A GAVIPAN, F X. GAVIPAN, F X GAVIPAN, F X	8403050110 8403130302* 8403060357 8403070056 8403070013*	50-320 8 70-2199 50-537 A 50-537 0 50-289 U	OLASSER, D OLASSPIECEL, H OLASSPIECEL, H OLASSPIECEL, H OLASSPIECEL, H	8403230038 8403060257 8403060257 8403060275 8403060275	50-322 T 50-440 0 50-440 0 50-440 0 50-440 0	ORAY, E. H. ORAY, E. H. ORAY, E. H. ORAY, E. H. ORAY, E. H.	8403150034* 8403290062* 8403290104* 8403290191* 8403290292*	50-388 0 50-334 0 50-219 0 50-289 0 50-27 0

AUTHOR	ACCESSION NUMBER	CATE		AUTHOR	ACCESSION NUMBER	BUBJEC		AUTHOR	ACCESS ION NUMBER	SUBJECT CATEGORY
Gray, J. R Gray, J. R Greenman, E. Greenman, E. Greeveb, J. T	8403190022* 8403270300 8403020238 8403020103* 8403040432	50-142 50-289 50-210 50-309 WASTE	7 0 3 B 7 G	Haass, W P Haass, W P Haass, W P Haass, W P Haass, W P	7708010232* 8011120101* 8110190051* 8110210316* 8111020578*	50-397 F01A 50-397 50-460 50-508	A A A	HARRAN. 0 HARRELL. E W HARRELL. E W HARRIGAN, N F HARRINGTON, T E	8403300135 8403060153 8403140010 8403060118 8403150008	50-245 50-338 50-338 40-2061 50-293
OREEVEB.J T OREGER.L R OREGER.L R OREGER.L.R OREGER.L R.	8403280267 8403130074* 8403170334* 8403200271* 8403220077*	WASTE 40-335 50-295 50-263 50-454	72 3 Q 9 Q	HAASS, H P HACKNEY, C A HACKNEY, C A HADLEY, R T HAEHL, J. O	8201300236# 8403130402# 8403190288# 8403190449 8403290177	50-397 50-313 50-313 NUREG 50-220	A Q Q	Harrington, w d Harrington, w d Harrington, w d Harrington, w d Harrington, w d	8403010324 8403070341* 8403070047 8403070147 8403070152	50-293 50-293 50-293 50-293
GREGER, L. R. GREGER, L. R. GRIDLEY, K. L. GRIDLEY, R. L. GRIER, B. H.	8403230023 8403270242* 8403270024* 8403270022* 8403080032*	50-255 50-409 50-293 50-293 FDIA	Q P	Hafner, B Hagan, T. Hagan, T. F Hagan, T. F Hagan, T. F	8403080363 8403010534* 8403010044* 8403010045* 8403010060*	50-322 CONTRACT CONTRACT CONTRACT	T T	HARRINGTON, W D HARRINGTON, W D. HARRINGTON, W D HARRINGTON, W D HARRINGTON, W D	B403130255 B403140107 B403150117* B403150177 B403200164	50-293 , 50-293 , 50-293 , 50-293 ,
GRIER, B. H GRIER, B. H. GRIER, B. H GRIER, B. H. GRIER, B. H.	8403080043# 8403080059# 8403080072# 8403080079# 8403080107#	FOIA FOIA FOIA FOIA		HAGAN, T. F HAGAN, T. F HAGAN, T. F HAGAN, T. F. HAGAN, T. F.	8403010437* 8403070373* 8403120314* 8403120345* 8403150278*	CONTRACT CONTRACT CONTRACT CONTRACT	r r r	HARRINOTON, H D HARRINOTON, H D HARRINOTON, H D HARRIS, D HARRIS, D	8403240317* 8403270010 8403270015 8403060204 8403060310*	50-293 (50-293 ; 50-293 ; 50-225 ;
GRIFFIN, J M GRIFFIN, J M. GRIFFIN, J. M GRIMES, C. I. GRIMSLEY, D H	9403060199 8403150037 8403260051 8403160074 8304060552#	50~313 50~313 50~313 50~407 50~397	P P P	HAGAN, TF, HAGEN, E, W HAGER, GW HAGUE, RL. HAIRBTON, WG	8403240322* 8403010102* 8403130139 8403130023* 8403010422*	CONTRACT FDIA 50-320 50-264 50-364	r e s	HARRIS, D HARRIS, D R HARRIS, D R HARRIS, D R, HARRIS, H G.	8403220310* 8403190437 8403200229 8403240156 8403120244*	50-322 NUREO 50-225 50-235
ordbe, J.A. Grdeb, P.J Grdebman, H Groseman, K. Groseman, K	8403120145* 8403080090 8403060102 8403010474 8403090016	50-263 50-537 50-416 FDIA FDIA	Q A G	HAIRSTON, W C. HAIRSTON, W C. HAIRSTON, W. C HAIRSTON, W C HAIRSTON, W C	8403010428* 8403070243 8403150084 8403260026* 8403260032*	50-364 50-348 50-348 50-348 50-348	8 8 8 8	HARRIS.H G HARRIS.J.D HARRIS.JR HARRIS.R H HARRISON,F	8403120252* 8403010102* 8403290179* 8403150034* 8403090011*	50-335 t FOIA 50-400 d 50-388 d 50-289 ti
GROTENHUIE, M GROTENHUIE, M GRUNEWALD, R GUADAGNO, V GUCWA, L T	8403150124 8403300254 8403270238 8403220173# 8403050085	50-324 50-324 PAM 40-8824 50-321	P P P	HAIRSTON, W. C. HAIRSTON, W. C. HAIRSTON, W. C. HAIRSTON, W. C. HALE, C.	8403240040* 8403240044* 8403300134 8403300172 8403130042*	50-348 50-348 50-364 50-348 64999	8 8 R	Harrison, F Harrison, G Harrison, G Harrison, J Harrison, J	8403130323 8403290346 8403300289 8403010296 8403060288	50-324 R 50-461 A 50-461 F 50-329 A 50-329 ö
GUCHA, L. T. GUCHA, L. T GUCHA, L. T GUCHA, L. T. GUCHA, L. T	8403070251 8403140349* 8403200005 8403200262 8403290212*	50-321 50-321 50-321 50-346 50-321	P P P	HALE, C J HALE, C J HALE, C, J HALE, C J HALE, C J	8403130325# 8403130425# 8403130432# 8403130440# 8403170170#	GA777 GA777 GA779 GA777 GA777		L C.NOSIANAH L C.NOSIANAH L C.NOSIANAH L C.NOSIANAH L C.NOSIANAH	8403050398* 8403130153 8403130482 8403200084 8403220082	50-327 0 50-327 A 50-327 A 50-327 A 50-327 A
QUCWA, L T. QUEHRINO, J B. QUERRY, J E. QUILBERT, D. E QUILD, R.	8403300104 8403050156* 8403050111 8403130058* 8403070037*	50-321 40-472 50-238 64999 50-413	5 R O	HALE, C. J. HALL, B. L. HALL, D. P. HALL, D. P. HALL, D. P.	8403270184* 8403140388* 8403080240 8403190175* 8403190398	GA999 50-302 50-461 50-461 50-461	G B G A	HARRIBON, 8 F HARTFIELD, R A HARTGEN, D T HARTIGAN, N F HARTMAN, 8 L	9403130289 9112020204* 8403130091* 9403070027 8403080324	50-358 A 50-412 A 50-322 Q 40-2061 50-445 Q
QUILD, R. QUILD, R QUILD, R QUILD, R. QUILD, R.	8403070037* 8403070112 8403070112 8403070115* 8403070115*	50-413 50-413 50-413 50-413 50-413	0 0 0 0	HALL, D.P. HALL, D.P HALL, R.E HALL, R.E HALL, R.E.	84032001 93* 8403240255 8402140325 8403010041* 8403240048*	50-461 50-461 40-8102 FOIA 50-458	A B	Hartman, B L Hartman, B L Hartman, B L Hartman, B L Hartman, S L	8403210170 8403210170 8403210172 8403210172 8403210189	50-50B Q 50-50B Q 50-50B Q 50-50B Q 50-50B Q
QUILD, R QUILD, R. QUILD, R. QUILD, R. QUILD, R.	8403220233 8403220233 8403220233 8403290379 8403290379	50-413 50-413 50-413 50-413 50-413	0 0 0 0	HALL, R E HALL, R. E HALL, R E, HALLER, R. E HAMEL, D B.	8403260077# 8403260102 8403260138 8403070014# 8403120137	50-313 40-1341 40-8102 50-328 50-331	e e	HARTMAN, B. L HARTMANN, P. L HARTZMAN, M HARVEY, R. C. HASHINOTO, P. S	8403210187 8403170042* 8403170106* 8403200270* 8403200152*	50-50B Q 50-282 Q 50-275 Q 50-27 P 50-423 A
QUILD, R QUILD, R. QUILD, R. QUILD, R QUINN, P. R.	8403290382 8403290388 8403290388 8403290388 8403020408*	50-413 50-413 50-413 50-413 FDIA	0000	Hamid, A A Hamid, A. A. Hamilton, Q. H Hamilton, J. Hamilton, P	8403120244* 8403120252* 8403120182 8403270241* 8403200164	50-335 50-335 50-483 0A779 50-293	G G A	HABBE,R A. HABBELL,D F HATHAWAY,Q H HATHAWAY,Q,H HAUGHEY,M F	8403040174* 8403140075 8403130009 8403300138 8403010298	50-266 Q 50-329 Q 50-341 A 50-341 A 50-410 A
Quinn, F. R. Qulbransen, E. A. Quldemond, W. Q. Qumble, F. W Qumble, F. W	8403020412# 8403160041 8403190076# 8403120152 8403150047	FDTA 50-320 50-373 50-286 50-286	P G S S	HAMILTON, P. HAMMER, M. F. HAMMITT, H. A. HAMMITT, H. A. HAMMITT, H. A. HAMMOND, E.	8403240134 8403130345 8403020008 8403280144 8403130487*	FOIA FOIA	8 F	HAUGHEY, M F. HAUGHEY, M F. HAUGHEY, M, F HAVERKAMP, D HAWKINS, D, A	8403050371* 8403060539 8403270394 8403070287* 8403010040	50-410 A 50-410 A 50-410 A 50-289 Q CONTRACT
QUMBLE, F. W QUMBLE, F. W QURLEY, M. K. QUBTAVE, R P. QUSTAVE, R P.	8403150050 8403210049 8403060366# 8403010004# 8403010027#	50-286 50-286 50-302 CONTRACT		HANCOCK, J. A HANNETT, B. A HANNETT, B. A. HANNETT, B. A HANNETT, B. A	8403300115* 8403020024* 8403020453* 8403140308* 8403150147	50-302 XPORTLIC XPORTLIC XPORTLIC XPORTLIC	8	HAWKINS, DA HAWKINS, EF HAWKINS, EF HAWKINS, EF	8403150270 8403200320 8403170415 8403170418 8403200335*	CONTRACT 40-8829 40-8829 40-8829 40-1341
QUSTAVE, R. P. QUSTAVE, R. P. QUSTAVE, R. P. QUSTAVE, R. P. QUSTAVE, R. P.	8403010078* 8403010452* 8403070046* 8403070141* 8403140328*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	ŗ	HANNETT, B. A. HANNETT, B. A. HANNETT, B. A HANNETT, B. A HANNETT, B. A	84031 601 69 84031 601 84* 8403260027 8403260030* 8403280055*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		Hawking, e.f. Hawking, e.f. Hawking, e.f. Hawking, e.f Hawking, e.f	8403200355 8403200360 8403200363 8403200375 8403220182	40-874B 40-8481 40-8481 40-8748 40-8502
QUBTAVE, R.P. QUBTAVE, R.P. QUETAVE, R.P. QUT, M. QUTHRIE, B, C.	8403150176* 8403230160* 8403270362* 8403070186 8403170076*	CONTRACT CONTRACT CONTRACT PRM 50-373	•	HARAM, B. A. HARAM, B. A. HARAM, B. A. HARD, J. E. HARDEN, K. C.	8403080044* 8403080111* 8403080134* 8403170042* 8403150340*	FOIA FOIA FOIA 50-292 40-8829	a	HAWKINB, E.F. HAWKINB, E.F. HAWKINB, E.F HAWXHURBT, J.J HAYDEN, T.	8403220190 8403220194 8403230157# 8403210016# 8403270364	40-8827 40-8502 40-8745 50-317 0 50-275 P
OUTHRIE, W. L. GUTTMAN, D. GWYNN, T. P. MAASE, M. HAASS, W. P.	9403270304* 9403270176 8403170323* 8403270342* 7706170142*	50-250 50-456 50-356 FDIA 50-460	e M g	HARDGROVE, T H HARDTY, R HARMON, D W HARMON, D. W. HARRAN, Q.	8403150342 8403170447 8403150134 8403150142* 8403020055	40-2259 NUREQ XFORTLIC XFORTLIC 50-245	R	HAYES, B. B HAYES, D. W. HAYNES, J. Q. HAYNES, J. Q HAYNES, J. Q	8403280337 8403130430* 8403020010 8403020218 8403050003	50-445 Q 50-461 Q 50-361 R 50-206 R 50-361 B

AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEOORY
Haynes, J. O Haynes, J. O Haynes, J. O Haynes, J. O Haynes, J. O.	8403060194 8403060378 8403060403 8403060438 8403120064	50-206 8 50-361 8 50-361 8 50-206 R 50-361 8	HIGGINBOTHAM, L HIGGINBOTHAM, L HIGGINBOTHAM, L, HIGGINB, B HIGGINB, T	8403160072 8403260043 8403260234 8403080029* 8403090204	HASTE MOT HASTE MOT HASTE MOT FOIA 50-483 F	HORIN, W A HORIN, W A HORIN, W A HORTON, W HORTON, W	8403140013 8403140020 8403140020 8403080006# 8403080008#	50-445 9 50-445 9 50-445 9 FUIA FUIA
Hayneb, J O.	8403150033 8403150057 8403150074 8403200053 8403200175	50-361 8 50-361 8 50-361 8 50-361 R 50-362 8	HILDENBRAND, P HILDENBRAND, P HILDENBRAND, P. HILDENBRAND, P HILL, C. Z.	8403200355 8403200360 8403200363 8403200375 8403280059	40-8768 40-8681 40-8681 40-8768 40-8788	HORTON: W HORTON: W. HORTON: W HORTON: W. HORTON: W.	8403080010* 8403080012* 8403080017* 8403080019* 8403080025*	FOIA FOIA FOIA FOIA
D LAYNEH O LEBNYAH O LEBNYAH O LEBNYAH O LEBNYAH	8403200174 8403210065 8403270164 8403270256 8403280002	50-361 8 50-206 8 50-362 9 50-206 F 50-361 8	HILL, E.E., HILL, L. J HILL, M. B HILL, W. M HILLMAN, R.E	8403150016 8403200358 8403080029* 8403170323* 8403230112*	50-498 Q NUREO FOIA 50-358 Q 50-219 R	HOSEY, C. M HOUSTON, M. D HOUSTON, M. D HOUSTON, M. D HOUSTON, R. W	8403160240* 8403020406 8403230273 8403300251 8203180004*	50~390 Q 50~416 S 50~416 P 50~416 P 50~460 C
HAYNES, J Q HEALD, A F HEATON, T. H HEBDON, F. J HEBDON, F. J	8403300003 8403210107 8403260088* 8403070121 8403140203	50-205 R PRM 50-344 P NUREO 50-205 B	HILLY, C. F HINCKLEY, D. Q HIND, J. A HIND, J. A. HIND, J. A	8403010078* 8403130497* 8403170314 8403170321* 8403170321*	CONTRACT 50-312	HOUSTON, R. W HOUSTON, R. W HOUSTON, R. W HOUI, L HOUE, H	8301260036* 8310310445* 8312230261* 8403070256 8403130167	50-400 E 50-400 E 50-336 P 50-217 B GA999
HEDGLON, M HEDGLON, M HEETHER, W H HEETHER, W. H HEFLIN, H	840321001 <i>9</i> 8403290389* 8403010463 840305004 <i>4</i> 8403190060*	40-2061 40-2061 XPORTLIC XPORTLIC 50-320 H	A C.GMIH A. J.GMIH A. J.GMIH A. J.GMIH A. J.GMIH	8403270086 8403270233 8403270238* 8403270255* 8403270263*	40~8760 50~409 G 50~409 G 50~454 G 50~454 G	HOWE, H. HOWE, P. W. HOWE, P. W. HOWE, P. W HOWE, P. W.	8403200076* 8403060276 8403060300 8403070157 8403070200	0A999 50-324 P 50-324 P 50-324 P 50-324 Q
HEHL, C. W. HEIDER, L. H HEIDER, L. H. HEIDER, L. H HEIDER, L. H	8403070134* 8403020072 8403020272 8403210068 8403300083	50-395 G 50-29 R 50-29 R 50-29 R 50-29 R	HIRBCH, D HOBBS, N.A. HOBBS, N.A HOBBS, N.A HOBBS, N.A.	8403260365 8403070165* 8403070178* 8403070190* 8403070222*	50-14R 0 50-322 T 50-322 T 50-322 T 50-322 T	HOWE, P. W. HOWE, P. W. HOWE, P. W. HOWE, P. W HOWE, P. W.	8403070315 8403070252 8403130452 8403210127 8403230047	50-325 Q 50-324 P 50-325 P 50-325 P
Heidker, J C Heidz, J. Heidhman, R. F Heithman, R. F	B403150223* B402220288 B402220303* B212070382* B403210208	WARTE HOT 50-289 U 50-289 U 50-440 A 50-309 0	HOCH, J. B HODDER, M H HODDER, M H HODDER, M. H HODDER, M H	8403120027* 8403070135 8403070137* 8403070143* 8403070143*	50-275 0 50-250 0 50-250 0 50-250 0 50-250 0	HOYLE, A HOYLE, A. HOYLE, A. HOYLE, A.	8403220325 8403230044 8403270282 8403270302 8403280186	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
Heltemes.C.J. Heltemes.C.J Heltemes.C.J Heltemes.C.J Heltemes.C.J	8401250448* 8402130042* 8403130140 8403280270 8403280273*	50-267 P Misc Misc Misc Misc	HODDER, M. H HODDER, M. H. HODDER, M. H. HODDER, M. H HODDON, A. P	6403140017 6403140017 6403140023* 6403140023* 6403140110	50-250 0 50-250 0 50-250 0 50-250 0 50-352 0	HOYT, H, F. HOYT, H F HOYT, H F. HBIEH, B. J. HBIEH, B B.	8403070107 8403170182 8403240343 8403070114 8403270187*	50-443 g 50-170 g 50-443 g NUREO 50-244 P
HELTEMES, C. J HELTEMES, C. J HELTEMES, C. J HELTEMES, C. J HELTEMES, C. J.	8403280278* 8403280282* 8403280288* 8403280274* 8403280276*	MISC MISC MISC MISC	HODODON, A, P HODODON, A, P HODODON, A, P HODODON, A, P HOFFMAN, D, A	8403140115 8403210128 84032101 <i>67</i> 8403270374 8403060301*	50-352 0 50-352 0 50-352 0 50-352 1	HUBBARD, Q. T HUBER, B. A HUCHTON, R. L HUDBON, B. D. HUDBPETH, J. B.	8403190214* 7906250470* 8403060533 8403130021* 8403140212	0A779 FDIA NUREG 50-220 G 50-348 F
HELHIO, D. R HELHIO, D. R. HEMBY, E. D. HENDERSON, J. 8, HENBLEY, W. T.	8403020224 8403200129 8403290405* 8401230660* 8403300306	TOPREP TOPREP XPORTLIC 50-329 B NUREG	HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, J. HOFFMAN, J. HOFFMAN, T.E	8403020088 8403300152 8403140015 8403280064 8403150286	50-155 R 50-155 R 50-395 J 50-146 J 40-8829	HUETER,L J HUFFMAN,G.N. HUGHES,T.J. HUKILL,H D HUKILL,H D.	8403220097* 8403290264* 8403290297 8403010347 8403060133	50-454 Q 50-302 Q PR 50-287 F 50-287 F
Herbert, R. J. Herborn, D. J. Herborn, D. I Herborn, D. I Hering, R. F	8403200113 8403130193 8403150089 8403290093 8403200202	50-336 E 50-461 A 50-461 A 50-461 I 50-315 Q	HOGAN, R. HOLBROOK, K. L HOLDEN, C HOLDER, E. T. HOLLAND, H. E	8403290120* 8403140170* 8403220103* 8403200213 8403160222*	50-387 Q PR 50-309 Q 50-259 B 50-390 Q	HUKILL, H. D HUKILL, H D. HUKILL, H. D. HUKILL, H. D HUKILL, H. D	8403060159 8403060160 8403060222 8403060229# 8403060233	50-289 P 50-289 P 50-289 P 50-289 P
HERMANN, R. A HERNAN, R. HERNAN, R. W HERNAN, R. W HERNAN, R. W,	8403120224 8403170427 8107280171# 8108110038# 8111060697#	30-220 P 50-302 P 30-460 A 50-460 A 50-460 A	HOLLAR, D. E. HOLLAR, D. E. HOLLAR, D. E. HOLLEMAN, D. HOLLEY, W. L	8403070051 8403070055 8403070058* 8403270311 8403260172*	50-400 Q 50-400 Q 50-400 Q PRM 50-285 Q	HUKILL, H D. HUKILL, H. D HUKILL, H. D. HUKILL, H. D HUKILL, H. D.	8403080039 8403090125 8403090244 8403120004 8403120016	50-287 P 50-287 P 50-287 Q 50-287 P 50-289 V
Hernan, R. W. Hernan, R. W. Hernandez, G. M. Herr, J. C. Herr, J. C.	8112300305# 8207280165# 8403060147# 8403270188# 8403270189#	50-460 A 50-460 Q 50-275 Q 50-244 P 50-244 P	NOLLEY, W.L. HOLLONAY, C.J. HOLLONAY, C.J HOLLONAY, C.J. HOLLONAY, C.J.	B403260250* B003240209* B004010752* B004010759* B112210135*	50-382 Q 50-508 A 50-508 A 50-508 A 50-508 A	HUKILL, H. D HUKILL, H. D. HUKILL, H. D. HUKILL, H. D. HUKILL, H. D	8403120056 8403130286 8403150141 8403160006 8403160022#	50-289 F 50-289 F 50-289 R 50-289 P
HERR. P. B HERR. P. B. HERR. P. B. HERBCH: M. M. HERBCH: M. M.	8403040259* 8403060289* 8403060307* 8403010484 8403010345	80-322 T 50-322 T 50-322 T XPORTLIC XPORTLIC	HOLONICH, J. J. HOLMES-RAY, P. HOLMES-RAY, P. HOLONICH, J. J.	8403080253* 8402170107* 8403290197* 8403270240 8403270271	50-508 A 50-305 P 50-366 Q 50-482 A 50-483 A	HUKILL, H D. HUKILL, H, D HUKILL, H, D HUKILL, H, D HUKILL, H, D	8403160024 8403200068 8403200099 8403210076 8403210138	50-287 F 50-289 R 50-289 P 50-289 R 50-289 R
HERBCH, M M HERBCH, M M HERBCH, M. M. HERBCH, M M. HEWARD, R. W	8403050047 8403050050 8403070381 * 8403220294 * 8403070203	XPORTLIC XPORTLIC XPORTLIC XPORTLIC 50-219 R	HOLONICH, J. J. HOLTZ: J. J HOLTZ: J. L. HOLZMAN: P. M. HOLZMAN: P. M.	8403280015 8403020084 8403300181 8403060085 8403120137*	50-483 A 50-334 R 50-334 R FDIA 50-237 G	HUKILL, H D, HUKILL, H D, HUKILL, H, D, HUKILL, H D, HULMAN, L, Q,	8403230001 8403230040 8403230053 8403270146 8204070077#	50-289 H 50-289 P 50-289 P 50-289 H 50-440 C
HIATT, B. L. HIATT, B. L. HIGKEY, J. P. HIGKEY, J. P.	8403010085 8403070213 8403280076 8403060461 8403060464	FOIA 50-440 A FOIA FOIA FOIA	HOLZMER, M M. HOOD, D. HOOD, D. B. HOPKINB, O. HOPKINB, J. B.	8403220165* 8312080134* 8312070298* 8403230208 8403220101	50-295 Q 50-329 A 50-329 A M/REQ 50-395 P	HULMAN, L. Q HULBEY, B. A HUNNICUTT, D. M HUNNICUTT, D. M HUNNICUTT, D. M.	8403010074* 8403160063 8403050186* 8403060184* 8403060373*	FDIA 50-206 H 50-482 G 50-445 G 50-445 Q
Hietala, J. J. Higginbotham, L. Higginbotham, L. Higginbotham, L Higginbotham, L	8403120047 8403130201* 8403150283 8403150300 8403150317	50-374 B 27-48 27-48 HASTE MOT 27-48	HOPKING, R. HOPPER, A. HOPPER, A. HOPPER, A. HORIN, W. A.	8403140035 8403220314 8403260352 8403260363 8403140013	50-454 0 CONTRACT CONTRACT CONTRACY 50-445 0	HUNNICUTT, D. M HUNNICUTT, D. M HUNNICUTT, D. M HUNNICUTT, D. M HUNNICUTT, D. M.	8403130148* 6403130219* 8403130453* 8403260107* 8403260167*	50-287 0 50-445 0 50-445 0 50-287 0 50-287 0

	AGCESSION REHUN	SUBJECT CATEOORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	CATEO
AUTHOR HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D, M HUNNICUTT, D, M HUNTER, D, R	8403260177* 8403260211* 8403260214* 8403260240* 8403260240*	50-267 Q 50-267 Q 50-267 Q 50-445 Q 50-298 Q 50-266 Q	Jenains. O R Jenkins. O R Jenkins. O R Jenains. O. R Jenains. O. R	8403070145* 6403150111* 6403150141* 8403150145* 8403150244*	50-335 G 50-349 G 50-269 G 50-289 G 50-239 G	0 жоеинос с, коеинос с, коеинос и с, коеинос н ч, коеинос н ч, коеинос	8403270322 8403150073* 8403150376 8403070270 8403150074	50-413 50-293 50-267 50-262 50-528
Hunter, D R Hubain, A. Ide, W. E. Ignatonib, A Ignatonib, A	8403080188* 8403200270* 8402140032* 8403070387* 8403070088*	50-461 G 50-29 P 50-528 G 50-269 G 50-275 G	Jenking, o r Jenking, o r Jenking, o r Jenking, o r Jennings, r t	8403160300* 8403290027* 8403290246* 8403290290* 8403300100	50-261 G 50-348 G 50-302 G 50-367 G 50-317 9	H SONGENHOUS H A SONG	8403140172 8403190362 8403060384 8403220247 8403090180	PR PRM 50-344 50-344 MRM
ignatoh, 8 8 Ilberg, D Imbro, E Imbro, E. Imbro, E V.	8010230503* 8403010041* 8305230539 8403230171 8311020249	FOIA FOIA 50-327 8 50-317 8 50-318 8	Jenb. H H Jenb. H H Jenb. H H Jenb. H H	8403020121 8403090188 8403090247 8403150021 8403200185	30-341 A 50-341 V 50-341 A 50-341 V 50-341 A	T. MOEMACL L MOEMACL A M. MOEMACL A G. MOEMACL A W. MOEMACL A M. MOEMACL A M. MOEMACL	8403200370 8403200372 8403140180* 8403140183* 8403140184*	WABTE 1 40-8829 50-373 50-373 50-373
IMERD. E. V IMERD. E. V. IMLER. R. IRVINO. S. M. IRVIN. D. H	8311020253* 8403230175* 8403060220 8403140012* 8403210107	50-318 6 50-317 8 50-289 H 50-458 9 PRM	Nemen'd F Neme'r H Neme'r H Neme'r H Neme'r H	8403210048 8403210074 8403230018 8403270043 8403080425*	50-341 A 50-341 A 50-341 A 50-341 A 50-287 P	TOHNOON, W D. O H. WOGWHOL O H. WOGWHOL D. WOGWHOL D. WOGWHOL D. WOGWHOL	8402210348* 8402050184* 8402130408* 8402170288* 8402240079*	50-285 50-482 50-313 50-313 50-313
iruin, d. p Iruin, d. p. Iruin, d. p Iruin, d. p Iruin, d. p.	8403010221 8403010221 8403010227* 8403010227* 8403020168	50-463 0 50-463 0 50-463 0 50-463 0 50-322 0	JERRETT. L E JESBUP. B. JESBUP. B JIERREE. C. C JIERREE. C. C	8403090105 8403020037 8403230129 8403230335* 8403260109*	PR 50-10 P CONTRACY 4D-1341 40-1341	O N. NOEMHOL D. H. NOEMHOL D. H. NOEMHOL D. NOTEMHOL V. W. NOTEMHOL V. W. NOTEMHOL	6403260172* 6403260232* 640320030* 6403060344* 6211300017*	50-319 50-319 50-344 50-400
irwin, d. p.	8403130022 8403130022 8403200059 8403200069 8403270292	20-355 0 20-355 0 20-355 0 20-355 0	70HABON'Y B 70HABON'Y B 70HABON'Y B 71H'B	8403230050 8403070053 8403140061 8403170221# 8403060356	WASTE MOT 50-482	JOHRSTON, W. V. JOHNSTON, W. V. JOHNSTON, W. V. JOHNSTON, W. V. JOHNSTON, W. V.	9301140474* 9307220302* 9310170075* 9310170047* 9311140004*	50-400 50-400 50-400 50-400
irwin, D. P. Iverson, O. N Jabbour, K. N Jabbour, K. N Jabbour, K. N	8403270292 8403200253 8403050377 8403040477 8403070422	50-322 0 50-263 8 50-413 E 50-413 A 50-413 E	JOHNSON, B. D. JOHNSON, B. D. JOHNSON, B. D. JOHNSON, B. D.	8403080184 8403080206 8403120041 8403120131 8403150145	50-255 R 50-255 R 50-255 R 50-155 G 50-255 P	JOHNSTON, H. V. JOHNSTON, H. V. JOLLEY, J. R. JOLLEY, J. R.	8311270301* 8312020043* 8312230276* 8403130071 8403300182	50-400 50-400 50-317 50-317
Jabloneki:f J. Jackih: I Jackih: I. Jackih: I. Jackih: I. N.	8403130430* 8403130275 8403130334 8403130377 8403130023*	50-461 0 50-346 9 50-346 9 50-266 8 50-266 0	0040904.0 D. 0040904.0 D 0040904.0 D 0040904.0 A 0040904.0 D	8403170101 8403220078 8403230073 8403020206 8403260173*	50-255 9 50-255 P 50-255 P HASTE HOT 50-334 @	JONES, D. H. JONES, D. H. JONES, D. H. JONES, D. H	8403060076# 8403060101# 8403070928# 8403160270# 8403230060	6A779 70-27 70-143 50-536
Jackih, I. N Jackson, H. H Jackson, L. H. Jackson, E. H. Jackson, P. D	8403170042* 8403170384* 8012160551* 8403080384* 8403020216	50-282 G 50-205 G 50-397 U 50-424 G HASTE MOT	Johnson, e Johnson, e, H. Johnson, e, H. Johnson, e, H. Johnson, e, H	8403260245 8403050091 8403050129 8403050133 8403060180	50-382 Q 50-29E Q 50-45B Q 50-267 Q 50-445 Q	JONES, F JONES, F, F JONES, G T JONES, G T	8403200150* 8403300170 8403060402 8403010224 8403010371	50-322 FOIA 50-259 50-259
Jackbon: R. E. Jackbon: R. E. Jackbon: R. E. Jackbon: R. E. Jackbon: R. E	8001270311* 8007070737* 8007250342* 8101060767* 8103040052*	50-312 P 50-344 P 50-312 P 50-397 A 50-397 E	JOHNSON, E. H.	8403040371 8403120045 8403120081 8403130122 8403130131	50-445 G 50-458 G 50-267 P 50-267 G 50-382 G	JDNEB, O. T. JUNEB, O. T.	8403020325 8403020244 8403070085 8403070243	50-259 50-259 50-259 50-259
Jackbon, R. E Jackbon, R. E. Jackbon, R. E. Jackbon, R. E.	B105210107* B107130581* B107140172* B108270470* B408270471	50-460 A 50-508 G 50-508 G 50-528 D HASTE MOT	JOHNSON, E. H. JOHNSON, E. H. JOHNSON, E. H. JOHNSON, E. H	8403130183 8403130231 8403130234 8403130257* 8403130307	50-445 Q 50-267 P 50-267 P 50-267 P 50-278 Q	JONES, G. T.	8403130181 8403130205 8403170125 8403170371	50-240 50-259 50-259 50-259 50-259
Jackbon, R. E. Jacobb, A. Jacobb, A. Jacobb, A. Jacobb, A.	8403260077* 8403060491 8403140325 8403150194 8403270360	50-344 P CONTRACT CONTRACT CONTRACT CONTRACT	JOHNSON, E. H. JOHNSON, E. H. JOHNSON, E. H. JOHNSON, E. H. JOHNSON, E. H.	8403130438 8403130442 8403160235 8403160242 8403160235	50-459 G 50-445 G 50-458 G 50-352 G 50-278 G	JONES, C. T.	8403200087 8403200171 8403200213 8403220046 8403220139	50-240 50-247 50-257 50-257 50-257
JACOBB: R JACOBB: R JACOBB: R JACOBB: N JACOBBON: N JACOBBON: N	8403070224 8403150060* 8403270155* 8403120010* 8403070208	50-387 8 50-387 0 50-387 9 50-275 9 PR	JOHNSON, E. H. JOHNSON, E. H. JOHNSON, E. H. JOHNSON, E. H.	8403190087* 8403190271 8403190320 8403190404 8403200125	50-267 P 50-382 Q 50-267 P 50-445 Q 50-445 Q	JONES, G T JONES, R A JONES, V H JONES, W. C	8403300133 8403130313 8403130313 8403020037* 8402170166*	50-445 50-445 50-280 50-285
Jaffeid, H. Janecek, R. F. Jankov, Z. D Jankowski, S. M. Januska, A. O.	8403050305 8403070174* 8403160076* 8403060475* 8403130117*	50-317 P 50-237 P 50-412 A CONTRACT 40-2061	TOHNEON'E'H' TOHNEON'E'H' TOHNEON'E'H' TOHNEON'E'H'	8403200247 8403220031 8403260060 8403260078 8403260100	50-382 0 50-278 0 50-458 0 50-382 0 50-267 0	TONES H C TONES H C TONES H C TONES H C	8403010312 8403050079 8403050124 8403050135	50-285 50-285 50-285 50-285
Januska, A. G. Jape, F. Jape, F. Jape, F. Jape, F.	8403220140* 8402140173* 8403070017* 8403070338* 8403140108*	50-305 G 50-261 G 50-413 G 50-413 G 50-416 G	ODMBONIE, H. JOHNBONIE, H JOHNBONIE, H JOHNBONIE, H	8403740141 8403740174 8403740205 8403740206 8403740217	50-267	Jones, H. C. Jones, H. C. Jones, H. C. Jones, H. C.	E403060376 8403070234 8403120172# 8403130200 8403130458	50-285 50-285 50-285 50-285 50-285
Jape, F. Jape, F. Jape, F. Jape, F. Jape, F.	8403160210* 8403160224* 8403160236* 8403160314* 8403160318	50-259 G 50-250 G	Johnbon, E. H Johnbon, E. H Johnbon, O. E Johnbon, O. E Johnbon, O. E	8403260235 8403270070 8403010209 8403140043 8403140046	50-298 G 50-458 G 50-413 G 50-413 G 50-413 G	Jones, H. C. Jones, H. C. Jones, H. C. Jones, H. C.	E403170061* E403170154 E403170281* E403200176 E403270249	50-285 50-285 50-285 50-285 50-285
Jape, F Jape, F. Jaudon, J. P. Jefferb, G. J. Jenking, G. R.	8403160370* 8403870207* 8403860177* 8403820272* 8403070013*	50-370 Q 50-267 Q 50-322 T	Johneon, C. E. Johneon, G. E. Johneon, G. E. Johneon, G. E. Johneon, G. E.	8403140123 8403140124 8403140150 8403140169 8403190174	50-413	Jones II. C. Jones IV C. Jones IV. F Jordan D. Jordan E. L	8403280165 8403280173 8403120043 8403010147 8011070322*	50-265 6A777 71-511

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR	ACCESSION NUMBER	6UBJECT CATEODR		AUTHOR	ACCESSION NUMBER	BUBJECT	
RDAN, E L RDAN, E L RDAN, E L RDAN, E L RDAN, E L	8103250630* 8401170072 8402020073* 8402070008 8402070009	FOIA 50~3 G 50~273 F 50~3 G 50~3 G	; 1	KARMAN, M KARR, J E KARR, J E KARR, J E KARR, J E	8403270326 8403060411 8403060442* 8403060444* 8403060443*	50-482 50-329 50-329 50-329 50-329	0 9 0 0	KELLY, M J KELLY, R B KELLY, T. KELLY, W. J KELLY, W. J	8403150237 8403010115 8403200173 8403020004 8403300141	40-1341 TOPREP 50-304 50-275 50-275	8 R R
RDAN, E L RDAN, E L RDAN, E L RDAN, E L RDAN, E L	8402070011 4500705048 8500705048 E400705048	50-3 0 50-3 0 50-3 0 50-3 0 50-3 0		KARR, J E KARR, J E KARR, J E KARR, J E. KARR, J E	8403080192 8403080221 8403080250 8403130074 8403130173	50-329 50-329 50-329 50-329 50-329	ង	KEMPER, J B KEMPER, J B KEMPER, J B KEMPER, J B KEMPER, J B	8401240207 8403020104 8403020266* 8403050161 8403070281*	50-352 50-352 50-352 50-352 50-352	AAAEG
RDAN,E L RDAN,E L RDAN,E L RDAN,E L RDAN,E L	8403010157* 8403010181* 8403010185* 8403010193* 8403010196*	FOIA FOIA FOIA FOIA		E KARR, J E KARR, J E E KARR, J E KARR, J E KARR, J E	8403130194 8403130195 8403130238 8403130271 8403130297	50-329 50-329 50-329 50-329 50-329	8 8 0	KEMPER, J 8 KEMPER, J 8 KEMPER, J 8 KEMPER, J. 8.	8403130084 8403160192 8403190197 8403200144 8403260249	50~352 50~352 50~352 50~352 50~352	BAAQE
RDAN, E.L. RDAN, E.L. RDAN, E.L. RDAN, M RDAN, M.J.	8403010206* 8403010214* 8403080124* 8403130377 8403040176*	FOIA FOIA FOIA 50-264 E 50~266 O		MARRIJE MARRIJE MARRIJE MARRIJE MARRIJE	8403130321 8403130388 8403130470 8403130479 8403270042	50-329 50-329 50-329 50-329 50-329	9 A A B R	KEMPER, J S KEMPER, J S, KEMPER, J. B KENDALL, J M KENNEDY, D	B403270071 B403270172 B4032B0353 B4030B0009* B4030600B3	50-352 50-352 50-352 50-29 50-320	O A O P H
RDAN, W H RDAN, W S RDAN, W S YNER, J YNER, J	8403170002 8403020173 8403020173 8402210133 8403020311	50-445 G 50-443 G 50-443 G I&E I&E)	KARR, J E KARR, J E KARR, J E KARR, J E KARR, J E	8403270093 8403270094 8403270227 8403300004 84033000035	50-329 50-329 50-329 50-329 50-329	8 8 8 8 8 8	KENYON, B. D. KENYON, B. D. KENYON, B. D.	8403130474 8403150166* 8403020036 8403120026 8403130059	50-456 50-286 50-387 50-388 50-387	D Q R A R
L'ABAN L'ABAN H L'ABAN H C'ABAN H C'ABAN	8403190135 8403300074 8403070259* 8403080165* 8403220010*	50-220 E 50-219 E 70-1100 FOIA 50-272 O	1	KABSAKATIB, L D KABSAKATIB, L D KABSAKATIB, L D	8403080023 8403070187 8403130337 8403200105 8403200237	FDIA 50-397 50-397 50-397 50-397	8 8 8	KENYON, B D KENYON, B D KENYON, B D KENYON, B D	8403170366* 8403170405 8403200250 8403200272 8403210112	50-387 PR 50-387 50-387 50-387	GI F F R
(NER, J. H (NER, J. H -IAN, C. A -IAN, C. A 1AN, C. A	6403290066* 6403290205* 6403070163* 6403070216* 6403160222*	70-398 50-320 0 50-327 0 50-416 0 50-390 0		KASSAKATIB, L D KASSAKATIB, L D KASSAKATIB, L D KASSUER, O KASTURI, B	8403260025 8403280003 8403280007 8403090164 8403150014*	50-397 50-397 50-397 50-295 50-440	8 8 8 8 9 Q	KENYON, B, D KENYON, B, D KENYON, B, D KENYON, B D, KENYON, T J	8403220041* 8403220135* 8403300069* 8403300147 8403060534	50-387 50-387 50-387 50-387 50-390	Q Q R A
IAN.C A GE.M GLING.T.L TUS.P S LE.J B	8403160225* 8403060109 8403220122 8403200312 8403200176	50-327 G 50-318 S WASTE MOT WASTE MOT 70-143		KAY.J A KAY.J A KAY.J A KAY.J A	8403190354* 8403080007 8403120123 8403120181 8403130287	50-440 50-29 50-29 50-29 50-29	Q P P R P	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G. KEPPLER, J G	B101290708* B403070345* B403080044* B403080057* B403080101*	FOIA 50-329 FOIA FOIA FOIA	6
FID F FEID B FEID B FEID B	8403070248* 8403160386* 8403160387* 8403260367* 8403070178	50-416 G 70-143 70-143 50-275 G PT21		KAY,J A KAY,J A KAY,J A KAY,J A	8403200284 8403200288* 8403270003 8403270007 8403270216	50-29 50-29 50-29 50-29 50-29	₽ ₽ ₽ ያ	KEPPLER, J G KEPPLER, J G KEPPLER, J. G KEPPLER, J G KEPPLER, J. G.	8403080127* 8403080175* 8403080208 8403080247 8403120116	FOIA FOIA 50-315 50-155 50-315	() ()
E.D.L E.D.L E.D.L E.D.L ITOWSKI, T	8403070200* 8403070202* 8403070203* 8403140138 8403270314	PT21 PT21 PT21 PT21 WASTE MOT		KAY, J A KAYSER, W V KAYSER, W V. KEARNEY, J. KEARNEY, J J.	8403300192 8403080223* 8403150104* 8403010239* 8403130348	50-29 50-314 50-316 FOIA PR	የ የ የ	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8403130380 8403170180 8403170234 8403170284 8403170274*	50-346 50-327 50-331 50-546 50-546	8 Q Q
IVIANAKIB. N IVIANAKIB. N IVIANAKIB. N IVIANAKIB. N	8403040113 8403120107 8403130382 8403150019 8403140027	50-254 R 50-265 8 50-254 R 50-254 R 50-254 S		KEARNEY, J P KEATING, D E KEATING, D E. KEELEY, O S KEIMIG, R.	8403130479* 8403080302* 8403170305* 8403270055* 8403270008	50-312 50-315 50-454 FOIA 50-219	0 0 8	KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O.	8403170341 8403200170 8403230088 8403260065 8403270246	50~346 50~461 50~10 50~358 50~454	8 G A G
IVIANAKIS, N IVIANAKIS, N /ERBDER, C YER, D. S YER, D. S	8403200106 8403200188 8403080366* 8403070092 8403070271	50-245 8 50-245 8 FOIA 50-390 0 50-259 0	ı	Keiber, H W Keiber, H W Keiber, H W Keiber, H W Keiber, H W	8403020253 8403020317 8403040108 8403040253 8403140011	50-387 50-387 50-387 50-387 50-387	8 8 8 8	KERCH, H W KERCH, H W. KERWIN, C. M KERWIN, C. M	8403020309* 8403150034* 8403010303* 8403070109 8403220064	50-277 50-389 50-388 NUREO 50-275	9 9 E 8
1ERER. C 1ERER. C 1ERER. C 1ERER. C	8101130353* 8403010046* 8403010049* 8403010054* 8403010058*	50-508 U FDIA FDIA FDIA FDIA		Keith'h n Keiber'h m Keiber'h m Keiber'h m	8403140018 8403160177 8403260226 8403070025 8403200231	50-387 50-387 50-387 50-333 50-333	8 8 8 8	KETZLACH, N. KETZLACH, N. KETZLACH, N KEYBERLING, H M KIEL, G. R	8403070019* 8403070112* 8403190160 8403220118 8403260037	70-1201 70-824 50-352 ACRB XPORTLIG	•
TERER. C TERER. C TERER, C , M S JA, B, K	8403010063* 8403010047* 8403020051* 8403270301 8403020318	FOIA FOIA 50-537 A PRM 50-320 P		KEITH, H N KEITH, W. R KELLER, M. KELLER, M. KELLER, R F	8403290246 8403060145 8403120033 8403220003 84032800081#	50-333 50-331 50-263 50-263 FOIA	8 8 8	Kiel, O R Kinneman, J. Kinneman, J. Kinneman, J. Kinneman, J D	8403260042* 8403080162* 8403080166* 8403210040 8403080102*	XPORTLIC FOIA FOIA I&E FOIA	;
A.B K. A.B K. M.B K M.B K A.B K	8403080257 8403090035 8403120102* 8403130428 8403130475	50-320 P 50-320 G 50-320 G 50-320 P 50-320 R		KELLEY, D. L. KELLEY, J. L. KELLEY, J. L. KELLEY, J. L. KELLEY, W. J	8403130453* 8403170025 8403200042 8403210051 8403270078*	50~445 50~400 50~413 50~400 50~461	0 0 0	Kinneman, J. D Kinneman, J. D Kinney, H. H Kinter, E. E. Kintner, L. L.	8403080173* 8403080189* 8403020305* 8403270123 8403160189	FDIA FDIA 50~54 50~320 50~352	Q P
A, B, K A, B, K, A, B, K, A, B, K,	8403170217* 8403200201 8403210057 8403270210 8403280006	50-320 Q 50-320 P 50-320 R 50-320 P 50-320 B		KELLY, E, KELLY, J, KELLY, J, A, KELLY, J, A	8403240214* 8403240214* 8403240048* 8403240097* 8403240220*	50~387 50~445 50~458 50~313 50~458	8 Q Q Q	KINTNER, L. L. KIRBY, L. J. KIRK, O. B. KIRK, O. B. E KIRK, W. F.	8403300305 8403070093 8403260164 8403020244 8403010289	50-416 NUREO 50-327 50-327 70-371	P 9 8
A.B.K LEY.J P O.J.P. AN.H AN.H.	8403300031 8403260284 8403200237 8403170123 8403170158	50-020 P 50-245 S 50-483 F 50-482 0 50-482 0		KELLY, J A F. KELLY, J. A. F. KELLY, J E. KELLY, L KELLY, M. J.	8403260167* 8403260240* 8403050035* 8403300159 8403150230	50-247 50-298 50-286 50-286 40-1341	Q Q P R	KIRKMAN, R. W KIRKMAN, R. W. KIRKPATRICK, D. KIRKPATRICK, D. KIRKPATRICK, D	8403080054* 8403080067* 8107160215* 8202120275* 8403010127*	FOIA FOIA FOIA FOIA	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEODR
KIRKPATRICK, D KIRKPATRICK, D KIRKPATRICK, D KIRKPATRICK, D KIRKPATRICK, D	8403010131#	FOIA	KDESTER, O L	8403070225	50-482 V	LAINAS, O C	8403200324	50-324
	8403010138#	FOIA	KDESTER, O L	8403130197	50-482 A	LAKNER, A A	8403050335*	MISC
	8403010161#	FOIA	KDESTER, O L	8403130215	50-482 B	LALIKOS, J M	8403210095	50-346
	8403010178#	FOIA	KDESTER, O L	8403130345*	50-482 G	LALIKOS, J. M	8403270108	GA777
	8403010184#	FOIA	KDESTER, O L	8403130399*	50-482 G	LAMB, J C	8403150016	50-478
KIRKPATRICK, D	8403010191*	FOIA	KGESTER: O L	8403150064	50-482 A	LAMBERTUB; H	8403260158*	40~1478
KIRKPATRICK, D	8403010252*	FOIA	KGESTER: O L	8403170036	50-482 8	LAMOUREAUX; T H	8403010175*	50~344
KIRKPATRICK, D	8403010287*	FOIA	KGESTER: O L	8403170227*	50-482 A	LANCIONE; G	8403210107	PRM
KIRKPATRICK, D	8403050266*	FOIA	KGESTER: G L	8403170316	50-482 S	LANDAGORA; M	8403280077	40~8586
KIRKPATRICK, D	8403050270*	FOIA	KGESTER: G L	8403200252	50-482 A	LANDAU; M	8403260280	NUREO
KIRECH, D. F. KIRSCH, D. F. KIRSCH, D. F. KIRSCH, D. F. KITTAN, J. J.	8403060149* 8403060214* 8403060223* 8403060406* 8403150078*	50-275 0 50-275 0 50-275 0 50-323 0 50-312 0 50-272 0	KDEBTER, O L KDESTER, O L KDESTER, O L KDESTER, O L KDESTER, O, L	8403200257 8403210073 8403270105 8403270151 8403270163	50-482 E 50-482 A 50-482 S 50-482 S 50-482 S	LANDGRAF, L C LANDGRAF, L C LANE, V M LANE, V M LANKSBURY, R D	8403130044 8403130044 8403200110 8403300287 8403170299*	50-341 50-341 50-352 50-352 50-373
KLEIMOLA, F. W. KLEIMOLA, F. W KLEIMOLA, F. W KLEIMOLA, F. W KLEIMOLA, F. W	8403070316* 8403070321* 8403070325* 8403070327* 8403070328*	TOPREP TOPREP TOPREP TOPREP TOPREP	KOESTER, & L KOESTER, J. P KONKL IN, J. E	8403270179 8403270268 8403070013* 8403060228* 8403220114*	50-482 8 50-482 8 50-289 U GA979 50-341 G	LANKSBURY,R D LANNING,H D LANPHER,L C LANPHER,L C LANPHER,L C	8403308057* 8403260013 8403060208 8403060208 8403060268	50-341 50-334 50-322 50-322 50-322
KLEIMOLA, F W	8403070330*	TOPREP	KONWINSKI, O.R	8403200343	40-1162	LANPHER, L C	8403060268	20-325
KLEIN, T. J.	8403150228	40-8584	KONWINSKI, O.R	8403200377	40-6659	LANPHER, L C	8403130146	20-355
KLEIN, T J	840322068	40-8584	KOON, A.R.	8403060242	50-395 8	LANPHER, L C	8403130146	20-355
KLEIN, T J	8403220117	40-8584	KOON, A.R.	8403060351	50-395 8	LANPHER, L C	8403200004	20-355
KLEINBORGE, W P	8403070105*	50-400 Q	KOON, A.R.	8403080153	50-395 8	LANPHER, L C	8403200004	20-355
KLEINSORGE, W P KLEINBORGE, W P KLINE, D A. KLINE, J R. KLINGER, J Q	8403170247* 8403270173* 8403270048* 8403300262 8403020018*	50-266 Q 50-400 Q 50-352 T 50-440 G FOIA	KOON, A.R. KOON, A.R. KOON, A.R. KOOPE, R.H	8403070052 8403070247 8403130371 8403150042 8403070059#	50-375 8 50-375 8 50-375 8 50-375 6 50-400 9	LANPHER, L. C LANPHER, L. C LANPHER, L. C LANPHER, L. C LANPHER, L. C	8403200128 8403200128 8403210186 8403210186 8403270248	50-322 50-322 50-322 50-322 50-322
KLINOLER, O	8403270114	50-237 G	KORTE, N	8403020374	WABTE MOT	LANPHER, L.C	840327024B	50-322
KNAPP, M R	8403200354	Wabte Mgt	KORTE, N	8403020374	WABTE MOT	LARSEN, G.J	8403080281*	50-275
KNIEL, K.	8310130378*	50-400 E	KOSIBA, R. E	8403130076*	QA979	LARSON, C.E	8403170264	50-263
KNIEGER, O W	8403120114*	Ga977	KOSLA, B M.	8403140217*	40-8027	LARSON, C.E	8403170200	50-282
KNIEGER, O W	8403270097*	Ga977	KOSLA, B, M	8403230246*	70-1359	LASH, T.R	8403200317	27-39
Knight, J P	8105010554*	50-460 A	KOT,C A.	8403070114	NUREG	LABUK: 8, R	0403060257	165
Knight, J P.	8107270274*	50-508 A	KOTTAN.J. J	8403010314*	50-352 G	LATHAM: D W	8403220080	50-317
Knight, J P	8211970008*	50-400 E	KOTTAN.J. J	8403270120*	50-387 G	LATHAM: W	8403050007	50-312
Knight, J P	8212160163*	50-400 E	KOVACH.B.	8403270073	50-320 F	LATHAM: W K	8403060141	50-312
Knight, J, P	8212300403*	50-400 E	KOVAK.T J	8403070274	50-254 F	LAURENSON: J A	8403010174	50-322
KNIGHT, J P. KNIGHT, J P KNIGHT, J P KNIGHT, J P. KNIGHT, J P. KNIGHT, J P	8309060390* 8309260418* 8309260421* 8310200096* 8403190102*	50-400 E 50-400 E 50-400 E 50-400 E 50-275 G	KOZINBKYJE J Kranzdorf,r. Krause,d. Kreger,h.e Kreider,h.o.	8403300342 8401040010* 8403130121 8005150677* 8403060311	NUREO 50-275 E 50-315 F F01A 50-443 S	LAURENSON, J A LAURENSON, J A LAURENSON, J A LAURENSON, J A	8403010215 8403010225 8403010232 8403010269 8403040114	50-322 50-322 50-322 50-322 50-322
Knight, J P Knighton, O W Knighton, O W. Knighton, O. W. Knighton, O W	8403240083* 8402270440* 8403010508 8403010544 8403040427	50-344 P 50-508 D 50-508 F 50-498 F 50-528 8	KREILING, R. T KREN, J. L. KRICH, R. M KRICH, R. M KRICH, R. M	8403060318* 8403070013* 8403080131 8403080141 8403270066	50-322 T 50-395 Q 50-155 R 50-155 R 50-155 S	LAURENSON, J A LAURENSON, J A LAURENSON, J A LAURENSON, J A	8403040083 8403130097 8403130107 8403140005 8403200095	20-355 20-355 20-355 20-355 30-355
Knighton, o w	8403060451	50-528 A	KRICH,R M	8403270187	50-155 P	LAURENSON, JA LAURENSON, JA LAHTON, MD LAZARUS, H, J LAZO, L	8403210083	50-322
Knighton, o, w	8403060559	50-443 F	KRIGH,R,M,	8403270247	50-155 P		8403210150	50-322
Knighton, o w	8403060561	50-382 F	KRIEGER,R W	8403070254	50-206 P		8403150208	40-6084
Knighton, o, w,	8403060564	50-275 E	KRIEGER,R W,	8403140251	50-206 P		8403150101*	50-410
Knighton, o w	8403070130	50-528 A	KRIEGER,R,W.	8403230118	50-361 Q		8403270369	50-412
Knighton, O. W Knighton, O. W Knighton, O. W. Knighton, O. W Knighton, O. W.	8403070147 8403140177 8403130165 8403150198 8403270357	50-528 8 50-412 E 50-275 P 50-508 D 50-412 F	KRIMH, R. W. KRIMH, R. W. KRIMH, R. W. KRIMH, R. W. KRIMH, R. W.	8403050128 8403080238 8403070218 8403130163 8403130178	50-440 F 50-263 F 50-155 F 50-282 F 50-263 F	LAZO, L LAZO, L LAZO, L LAZO, R M LAZO, R, M	8403280056 8403280060 8403280067 8003240222# 8403130034	50-412 50-412 50-508 50-250
Knighton, O. W.	9403270372	50-412 C	KRIPH, R. W.	8403130417	ORG	LAZD, R. M	8403130262	50-309
Knighton, O. W.	8403280233	50-566 F	KRIPH, R. W.	8403150018	50-293 F	LAZD, R. M	8403270277	50-250
Knighton, O. W.	9403270331	50-361 P	KRIPH, R. W.	8403150052	50-416 F	LEACH, E W	8403130371 ×	50-220
Knighton, O. W.	8403300125	50-498 A	KRIPH, R. W.	8403150113	50-313 F	LEAR, G	8111130007 ×	50-460
Knighton, R. O	8403060226*	50-322 T	KRIPH, R. W.	8403150117*	50-313 F	LEAR, G,	8307200478 *	50-400
Knighton, R. g	8403050245*	50-322 T	KRIMM, R. W	8403150200	50-315 F	LEAR: Q	9311100049*	50-400
Knop, R. C.	8403050170	50-341 Q	KRIMM, R. W	8403230120	50-387 F	LEAR; G.	9311160283*	50-400
Knop, R. C	8403070234*	FDIA	KRISHNAMURTHY	8403270253	FRM	LEAR: Q	9312070022*	50-329
Knop, R. C.	8403130415	50-461 Q	KRUO, H. E.	8403140210*	50-335 G	LEAR: Q E.	9104220329*	50-460
Knop, R. C	8403220107	50-341 Q	KRUO, H. E	8403140316*	50-250 G	LEAR: G E	9211160112*	50-400
KNOP, R. C.	8403220111*	50-341 0	KRUMPOS, P. J. KUCZYNSKI, L. A KUCZYNSKI, L. A KUCZYNSKI, L. A, KUCZYNSKI, L. A, KUEGHLE, C. W.	8403270181 *	50-282 Q	LEAR, Q.E.	8212140220*	50-400
KNUTSON, J. A.	8403010532*	50-275 H		8403020036	50-387 R	LEAR, Q.E	8311270352*	50-400
KOBER, R.	8403280049	50-244 P		8403020233	50-387 S	LEDDICK, R. S	8403050248	50-382
KOBER, R. W.	8403060115	50-244 P		8403300147	50-387 R	LEDDICK, R. S	8403120164	50-382
KOBER, R. W.	8403130132	50-244 R		8403070174	50-304 S	LEE, A.	8403260018	50-454
Kober, R. W. Kober, R. W Kober, R. W Kober, R. W Kocher, C. W,	8403260178 8403270150 8403270152 8403270185 8401260167#	50-244 P 50-244 Q 50-244 Q 50-244 P 50-264 F	KUNCL: L. O. KUNITA: R. K KUO: P KUO: P KUZO: G. B.	8403090100 8403210080* 8310310471* 8312010004* 8403160309*	50-298 P 50-324 P 50-329 A 50-329 A 50-395 Q	LEE, A LEE, I J. LEE, J. LEE, J.	8403260057 8206300082* 8403160015 8403220242 8403020122	50-454 50-508 50-289 50-289 50-338
KOCHER, C W.	8403050012	50-264 F	KUZO, Q B	8403140327*	50-369 Q	LEE, J. N	8403300055	50-338
KOENIO, R.	8403140244	50-374 B	KUZO, Q, B,	8403270147*	50-413 Q	LEE, D. R.	8403130435	50-247
KOENIO, R	8403200212	50-374 B	Laatb, E T,	8403270327	RES	LEE, O. R	8403170350	50-247
KOESTER, O L	8403010145	50-482 B	Lacey, W B,	8403060134	50-334 B	LEE, O. R	8403170357*	50-267
KOESTER, O. L.	8403020274	50-482 A	Laggart, M W.	8403160203	50-219 P	LEE, O. R	8403270187	50-267

AUTHOR	ACCESSION NUMBER	CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
LEE,T D	8403210156*	70-143	LEHIS,R C	8403160162	50-259 Q	LINDER	1610066048	50-409 R
LEECH,P H	8403140272	50-293 P	LEHIS,R C	8403160178*	50-259 Q	LINDER, F	1410506048	50-409 R
LEGGETT,L H	8403010467	FDIA	LEHIS,R C	8403160194	50-400 Q	LINDER, F,	1600806048	50-409 R
LEHBERGER,N	8403130100*	50-027 &	LEHIS,R C	8403160211	50-413 Q	LINDER, F	4650806048	50-409 R
LEHR,J.C	8403140168*	50-400 &	LEHIS,R C	8403160218	50-259 Q	LINDER, F	E800516048	50-409 Q
LEININGER: W J	8403070332*	TOPREP	LEWIB, A. C	8403160220*	50-413 Q	LINDER, F	8403130270	50-409 P
LEMPGES: T E	8403060437	50-220 F	LEWIB, R. C	8403160226	50-321 P	LINDER, F	8403130335#	50-409 G
LEMPGES: T E	8403070174	50-220 R	LEWIB, R. C	8403160227	50-259 V	LINDER, F	8403140047	50-409 F
LEMPGES: T E	8403120044	50-220 Q	LEWIB, R. C	8403160230*	50-259 Q	LINDER, F	8403200143	50-409 B
LEMPGES: T E.	8403130124	50-410 V	LEWIB, R. C	8403160231	50-302 P	LINDER, F.	8403230002	50-409 R
LEMPGES, T E.	8403130340	50-220 P	LEWIS,R C	8403160245	50-269 F	LINDER, F.	8403290283	50-409 P
LEMPGES, T E.	8403150051	50-220 R	LEWIS,R C	8403160247	50-259 P	LINDER, F	8403300089	50-409 P
LEMPGES, T E	8403210043	50-220 S	LEWIS,R C	8403160249	50-261 G	LINDGUIST, T R	8403230102*	50-255 P
LEMPGES, T E	8403220129	50-220 P	LEWIS,R C	8403160252	50-417 A	LINDGUIST, T R	8403230106*	50-255 P
LEMPGES, T E	8403260270	50-220 G	LEWIS,R C	8403160254	50-250 F	LINDSEY, D J.	8403060193	50-333 B
Lempoes, T e Lempoes, T. e Lenahan, J J Lenahan, J. J Leppke, M	8403290177 8403300151 8403070017* 8403080384* 8403120012*	50-220 1 50-220 Q 50-413 Q FOIA 50-275 Q	LEWIS, R C LEWIS, R C LEWIS, R, C LEWIS, R, C	8403160257 8403160269 8403160272* 8403160275* 8403160276	50-348	LINEHAN, J. LINEHAN, J J LINENBERGER, G LINTON, O. W. LINVILLE, J C	8403220237 8403220274 8403130394 8403210012 8403220115#	WASTE MOT WASTE MOT 50-424 O PR 50-272 G
LEPPKE, M E.	8403120010*	50-275	LEWIS, R C	8403160278	50-269 F	LINVILLE, J. C.	8403270137#	50-272 Q
LETSCHE, K	8403200159*		LEWIS, R C	8403160281	50-416 F	LIPINSKT, D.	8403020238	50-213 E
LETSCHE, K	8403200159*		LEWIS, R C	8403160283	50-261 F	LISENG, R	8403010345	50-333 B
LETSCHE, K	8403290390		LEWIS, R C	8403160285	50-302 F	LISTER, W E	8010230503#	FDIA
LETSCHE, K	8403290390		LEWIS, R C	8403160293	50-413 Q	LITTLE, W. 8	8403080114	50-373 Q
LETSCHE, K J. LETSCHE, K J LETSCHE, K J LETSCHE, K J LETSCHE, K J	9403010234 8403010234 8403010237 8403010237 8403060254	50-322 0 50-322 0 50-322 0 50-322 T	LEWIS,R C Lewis,R C. Lewis,R.C Lewis,R C Lewis,R C.	8403160296 8403160297 8403160304* 8403160307* 8403160308	50-395 F 50-369 Q 50-369 Q 50-413 Q 50-259 Q	LITTLE, W 8 LITTLE, W 8, LITTLE, W 8 LITTLE, W, 8 LITTLE, W 8	8403080299 8403120122 8403190207 8403190240 8403190244*	50-315 Q 50-440 Q 50-254 Q 50-266 Q 50-266 Q
LETSCHE, K J	8403040254	50-322 T	LEWIB.A C.	8403160317*	50-349 G	LITTLE, W.S.	8403190268	50-454 Q
LETSCHE, K J	8403130003	50-322 0	LEWIB.R C	8403160328*	50-259 G	LITTLE, W.S.	8403190297	50-454 Q
LETSCHE, K J	8403130003	50-322 0	LEWIS.R C.	8403160330	50-400 A	LITTLE, W.S	8403190348	50-440 Q
LETSCHE, K J,	8403130027	50-322 0	LEWIB.R.C.	8403160335	50-302 G	LITTLE, W.S	8403260228	50-454 Q
LETSCHE, K J.	8403130027	50-322 0	LEWIB.R C.	8403160345	50-259 F	LITTLEHALES, Q	8403010122	0A999
LETECHE, K J LETECHE, K J LETECHE, K J LETECHE, K J	8403200136* 8403200136* 8403220288 8403220288 8403280346	50-322 0 50-322 T 50-322 T 50-322 Q	LEWIS.R C. LEWIS.R C. LEWIS.R C. LEWIS.R C. LEWIS.R C	8403160354 8403190136 8403190172* 8403210115 8403290013	50-348 F 50-259 Q 50-259 Q 50-416 Q 50-366 B	LITTLEHALES, Q LIU, W. LIU, W. C LLAURADD, J. Q. LOBNER, P	8403060262 8403080384* 8403160383* 8403270257 8403080268*	0A999 50-424
LETSCHE, K J LETSCHE, K J LETSCHE, K J LETSCHE, K J	9403290346 8403290357 8403290357 8403290377 8403290377	50-322	LEWIS,R C LEWIS,R C. LEWIS,R,C. LEWIS,R,C. LEWIS,R C.	8403270178 8403270172 8403270173 8403270175* 8403270203*	50-259 Q 50-250 Q 50-366 Q 50-366 Q 50-259 Q	LOBNER, P. LODGE, B LODGE, T. J LOFGREN, E. LOFY, R. A.	8403080306* 8403060164 8403270075 8403010041* 8403080193*	50-298 F FDIA 50-440 9 FDIA 50-275 G
LETSCHE, K J LEVIN, H A LEVIN, H A LEVIN, H A	8403270383 8403270383 8403040370 8403060240 8403220013	50-322 Q 50-322 Q 50-329 A 30-329 A 50-329 R	LEWIS.R C. LEWIS.R.C. LEWIS.R C. LEWIS.R C. LEWIS.R C.	8403270211* 8403270213 8403270250 8403270269* 8403270270	50-259 0 50-259 V 50-338 0 50-338 0 50-413 0	LDFY,RA LOGSDON,MJ LOGUE,RH LOIGNON,GA LOIGNON,G,A	8403080177# 8403280253 8403010358 8403020037 84033300145	50-275 G HABTE MOT 50-277 B 50-375 R 50-375 R
LEVIN.H.A LEVIN.H.A. LEVIN.L.A LEVINE, J. M	9403220100 8403220113 8403270159 8403040120 8403070358	50-329 A 50-329 A 50-329 A FOIA 50-313 F	Lewis, R.C. Lewis, R.C Lewis, B.H. Lewis, S.H. Liang, C.Y	8403270322 8403300022 8403070349* 8403070351* 8403170119*	50-259 V 50-369 F 50-329 S 50-329 Q 50-275 Q	LOMBARDO, J J LOVENDALE, P C LOVETT, B LOWE, A L LUCENA, B.	8403010270 8403170334* 8403130457 8403170246* 8403020157	50-217 P 50-295 Q 50-424 9 TOPREP XPORTLIC
LEVINE, J. M LEVY, B LEVY, B LEWIS, J. R	8403090301 8403260005 8403260375 8403260378 8403230200	50-313 F 50-275 Q 50-275 Q 50-275 Q NUREQ	LIAW, B, D LIBARKIN, M W LICHTENBERGER LICHTENBERGER LICHTENBERGER	8403160055 8307260036 8401240340# 8403060161# 8403130476#	TOPREP ACRB 70-1100 GA999 70-1100	LUCKS: A. S. LUCKS: A. S. LUCKS: A. S. LUCKS: A. S.	8403060082 8403060407* 8403060413* 8403060420* 8403060423*	50-537 Q 50-329 Q 50-329 Q 50-329 Q 50-329 Q
LEMIS, M I LEMIS, M I LEMIS, R C LEMIS, R C	8403150049* 8403150291 8403190038 8403010154 8403010247	50-320 P 50-289 H 50-352 0 50-327 F 50-83 F	LICITRA, E A Liden, E. A Liden, E. A Liden, E. A Liden, E. A	8403280043 8403060312 8403070260 8403090049 8403130017	50-528 A 50-272 V 50-272 R 50-272 P 50-272 P	LUCKS, A. B. Luebke, E. A. Luehman, J. G. Luehman, J. G. Lumb, R. F.	8403060428* 8403260003 8403290291* 8403290294* 8403270362*	50-329 @ 50-142 @ 50-338 @ 50-338 @ CONTRACT
LEWIS, R C.	8403020204	50-250 Q	LIDEN, E. A.	8403130108	50~311 P	LUNDBLAD, D LUNDVALL, A. E, LUNDVALL, A. E, LUNDVALL, A. E, LUNDVALL, A. E,	8403150151	50-508 D
LEWIS, R C.	8403020248	50-250 B	LIDEN, E. A	8403220036	50~272 Q		8403020346#	50-317 G
LEWIS, R C.	8403020254	50-267 F	LIDEN, E. A	8403270281	50~272 P		8403050098	50-318 P
LEWIS, R C.	8403020285	50-250 Q	LIDEN, E. A	8403300085	50~272 P		8403060263	50-317 P
LEWIS, R C.	8403070125	50-375 Q	LIDEN, E. A	8403300177*	50~272 G		8403060400	50-317 P
LEWIS, R C.	8403070131*	50-395 Q	Liden, e.a.	8403300183*	50-272 9	LUNDVALL: A E LUNDVALL: A. E. LUNDVALL: A. E. LUNDVALL: A. E. LUNDVALL: A. E.	8403130303	50-317 R
LEWIS, R C.	8403070239	50-260 Q	Liden, e.a.	8403300186*	50-311 0		8403150049	50-317 G
LEWIS, R C.	8403070344	50-247 Q	Lieberman, e.b.	8403070158*	50-322 T		8403160040	50-317 P
LEWIS, R C.	8403080377*	50-424 Q	Lieberman, e.b.	8403070171*	50-322 T		8403190018	50-317 F
LEWIS, R C.	8403120110	50-369 F	Lieberman, e.b.	8403070198*	50-322 T		8403190408	50-317 G
LENIS, R. C.	8403120119	50-269 F	Lieberman, e B	8403070201*	50-322 T	LUNDVALL, A E. LUNDVALL, A E. LUNDVALL, A. E. LUNDVALL, A. E. LUPTAK, A.	8403220052	50-317 F
LENIS, R. C.	8403130033	50-302 F	Lieberman, e, B.	8403070207*	50-322 T		8403260112*	50-317 Q
LENIS, R. C.	8403130037	50-327 F	Lieberman, e B	8403230020	50-322 T		8403260236	50-317 P
LENIS, R. C.	8403130484	50-259 F	Lieberman, e, B	8403230066	50-322 T		8403300070	50-317 P
LENIS, R. C	8403130485	50-259 F	Lieberman, J	8403080431*	50-275 E		8403220103*	50-309 Q
LEMIB, R C.	8403160025	50-259 F	LIETO,R P.	8403210107	PRM	LYDNB, J. L.	8403010012	40-299
LEMIB, R C	8403160035	50-327 F	LIM.J J.	8403050029*	50-286 P	LYDNB, J. L.	8403190284	40-299
LEMIB, R C.	8403160137	50-327 F	LIM.T H.	8403150115	50-224 R	MACDONALD, C. E.	8403020229	71-9071
LEMIB, R. C	8403160140	50-438 Q	LIN.D	8403160261	50-373 R	MACDONALD, C. E.	8403020239	71-9161
LEMIS, R. C.	8403160150	50-321 F	LIN.D L.	8403020138	50-373 R	MACDONALD, C. E.	8403020420	71-9108

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	CATEOURY
MACDONALD, C E	8403020423*	71-910B	MARQULIES; M B	8403130374	50-424 0	MARTIN, T T	8403150106	50-334
	8403050338	71-314	MARKEY; E J	8403010038 ×	FOIA	MARTIN, T T	8403150125	50-320
	8403050340*	71-314	MARKEY; E J	8403120393 ×	COMMISSION	MARTIN, T T	8403160152	50-272
	8403050574	71-9009	MARKIN; K M	8403010371	50-259 5	MARTIN, T, T	8403160205	50-219
	8403070002	71-9190	MARKIDS; O	8403050318 ×	WASTE NOT	MARTIN, T T	8403160241	50-352
MACDONALD, C E	8403070011	71-9160	Markob, q	8403050319*	Waste Mot	MARTIN, T T	8403170151	50-213
	8403080312	71-6601	Markob, q	8403050322*	Waste Mot	MARTIN, T T	8403170215	50-320
	8403080314*	71-6601	Markob, q	8403050323*	Waste Mot	MARTIN, T T	8403170258	50-284
	8403080394	71-6406	Marobe, r	8403200112*	50-409 F	MARTIN, T T	8403170257	70-378
	8403080396*	71-6406	Marbhall, j r	8403020075	50-313 R	MARTIN, T T	8403170310	40-7455
MACDUNALD, C E	8403080397	71-7001	MARSHALL, J R	8403020081	50-348 R	MARTIN, T T	8403190360	50-387
MACDUNALD, C E	8403080399*	71-7001	MARSHALL, J R	8403050158	50-313 P	MARTIN, T T	8403200029	50-317
MACDUNALD, C E	8403080416	71-7080	MARSHALL, J R	8403040203*	50-313 0	MARTIN, T T	8403200098	50-293
MACDUNALD, C E	8403080418*	71-7080	MARSHALL, J, R	8403040308	50-313 R	MARTIN, T T	8403200166	50-271
MACDUNALD, C E	8403140235	71-513	MARSHALL, J R	8403040350	50-313 F	MARTIN, T T	8403210006	50-317
MACDONALD, C E	8403140238*	71-513	Marshall, j r	8403060430	50-313 F	MARTIN, T T	8403210047	50-320
	8403210212	71-6601	Marshall, j r	8403070137	50-368 B	MARTIN, T. T	8403210097	50-334
	8403230166	71-6601	Marshall, j, r	8403070177	50-313 P	MARTIN, T. T	8403220006	50-272
	8403230269	71-9009	Marshall, j r	8403120011	50-313 F	MARTIN, T. T	8403220034	50-20
	8403260094	71-9162	Marshall, j r	8403130024	50-368 B	MARTIN, T. T	8403220056	50-307
MACDONALD, C. E	8403260331	71-5450	MARSHALL, J R.	8403130324	50-348 8	MARTIN, T T	8403220083	50-277
MACDONALD, C. E	8403260336*	71-5450	MARSHALL, J R	8403130347	50-348 8	MARTIN, T T	8403220085*	50-277
MACDONALD, C. E	8403280214	71-9036	MARSHALL, J R	8403130437	50-313 0	MARTIN, T T	8403220070	40-672
MACDONALD, C. E	8403280218*	71-9036	MARSHALL, J R	8403130473	50-313 F	MARTIN, T T	8403220128	50-387
MACDONALD, C. E	8403300224	71-9134	MARSHALL, J R	8403200174	50-313 F	MARTIN, T T	8403220170	40-8824
MACDONALD, C E	8403300227*	71-9134	Marehall, j r	8403200179	50-313 F	MARTIN,T T	8403260104	50-317
MACDONALD, C E	8403300227	71-9160	Marehall, j r	8403200246	50-313 F	MARTIN,T T	8403260113	50-322
MACDONALD, C E	8403300298	71-9027	Marehall, j, r	8403220020	50-348 B	MARTIN,T T	8403270043	70-398
MACDONALD, C E	8403300302*	71-9027	Marehall, j r	8403230091	50-313 P	MARTIN,T T	8403270053	50-334
MACKAY, S	8403020118	50-324 F	Marehall, j r	8403260137	50-368 Q	MARTIN,T T,	8403270064	50-271
MACKAY, 8	B403260087	50-324 F	MARBHALL, J R	8403270258	50-348 S	MARTIN.T T	8403290099	50-219
MACKAY, 8 D,	B403020157	50-324 F	MARBHALL, J R	8403280094	50-313 F	MARTIN.T T	8403290116	50-387
MACRAE, J B	B4030203B0	ORG	MARBHALL, J R	8403290127	50-348 S	MARTIN.T T	8403290144	50-352
MACRAE, J B,	B4030203B1	ORG	MARBHALL, J R.	8403300068	50-313 R	MARTIN.T T.	8403290186	50-289
MACRAE, J B	B4030203B3	ORG	MARBHALL, J R	8403300164	50-348 R	MARTIN.T.T	8403290202	50-320
MACRAE, J. B.	8403020385	ORG	MARTIN.J.B	8403010114*	50-508 T	MARTIN.T T.	8403270206	50-272
	8403020387	ORG	MARTIN.J.B	8403090173	PRM	MARTIN.T T	8403270251	50-3
	8403020388	ORG	MARTIN.J.D.	8403020097	50-397 R	MARTIN.T T	8403270286	50-27
	8403060458	ORG	MARTIN.J.D	8403070187	50-397 S	MARTIN.T.T.	8403300063	50-387
	8403060460	ORG	MARTIN.J.D	8403130337	50-397 S	MARTIN.T.T.	8403300065	50-271
MACRAE, J. B.	8403060463	ORG	MARTIN.J.D	8403200239	50-397 8	MARTIN, T. T	8403300072	50-322
MACRAE, J. B.	8403230079	ORG	MARTIN.J.D	8403240025	50-397 8	MARTIN, T T	8403300084	50-245
MACRAE, J. B.	8403230080	ORG	MARTIN.J.D	8403280003	50-397 8	MARTIN, T. T	8403300086	50-245
MACRAE, J. B.	8403260039	DRG	MARTIN.J.D	8403280007	50-397 8	MARTIN, T T	840330098	50-354
MADDEN	8403060171	FDIA	MARTIN.J.D	8403300054	50-397 R	MARTIN, T T	8403300121	50-354
MADDEN: B.	8403190135	50-220 B	MARTIN, J P	8403200105	50-397 B	MARTIN, T.T.	8403300142	50-271
MADDEN: T. J.	8403010111	FDIA	MARTIN, T J	8403090080	50-272 G	MARTIN, T.T.	8403300161	50-213
MADDEN: T. J.	8403080226	FDIA	MARTIN, T J,	8403130014*	50-354 G	MABCIANTONIO, A	8403270296	50-352
MADDEN: W	8403300074	50-219 B	MARTIN, T J	8403130372*	50-354 G	MABON, C.C.	8403020002	50-327
MADDEN: W. J.	8403220010*	50-272 G	MARTIN, T J	8403130108	50-354 B	MABON, C.C.	8403020147	50-327
MADEDA: T J	B403010348*	50-454 G	MARTIN.T J	8403210118	50-354 8	MABON, C. C	B403020244	50-327
MADEDA: T J.	B403170237*	50-331 G	MARTIN.T T	8401240337	70-1100	MABON, C. C.	B403050080	50-327
MADERA: J R.	B403060210*	40-8830	MARTIN.T T	8403010301	50-317 F	MABON, C. C	B403060276	50-327
MADERA: J. R	B403080215*	FDIA	MARTIN.T T	8403010307	50-352 G	MABON, C. C	B403150079	50-327
MADERA: Q	B403130271*	GA777	MARTIN.T,T	8403010360	70-1100	MABON, C. C	B403190121	50-327
MADBEN, O L	8402150224#	GA799	MARTIN,T T	8403020214	50-388 G	MABON.C.C.	8403190365	50-327
MADBEN, B H.	8403140328#	CONTRACT	MARTIN,T T	8403020262	50-293 G	MABON.C.C.	8403260164	50-327
MAIER, J E.	8403300191#	50-244 G	MARTIN,T.T.	8403020306	50-277 G	MABON.C.C.	8403300073	50-327
MAKAY, E.	8403190282#	50-312 G	MARTIN,T T	8403020315	50-293 G	MABON.C.C.	8403300154	50-327
MALCOM, J B	8403020077#	CONTRACT	MARTIN,T T	8403020331	40-6920	MABON.C.C.	8403300204	50-328
Malddy, C. W.	8403060421*	70-1257	MARTIN,T T	8403020341	50-247 G	MABBARO, B A MABBE, F X. MATHENY, K A MATHENY, K. A MATHENY, K. A.	8403240056	NUREG
Malech, M. G.	8403080379*	FDIA	MARTIN,T.T.	8403020353	50-286 G		8403070212	FR
Mangan, C. V.	8403060221	50-220 P	MARTIN,T.T.	8403050014	50-247 G		8403130104*	50-440
Mangan, C. V.	8403060247	50-220 P	MARTIN,T T	8403050134	40-672		8403130118*	50-440
Mangan, C. V.	8403060446	50-220 P	MARTIN,T.T	8403050274*	FOIA		8403130128*	50-440
Mangan, C. V.	8403090040	50-220 P	MARTIN.T T	8403070240	50-387 Q	MATHENY, K. A MATHERON, B M MATHENS, C. S MATHENS, M. L. MATHENS, T. P.	8403130138*	50-440
Mangan, G. V.	8403090146	50-220 P	MARTIN.T.T.	8403070256	70-1100		6403140027	Watte Mg
Mangan, C. V.	8403120059	50-220 P	MARTIN.T T	8403070276	50-352 Q		6403200222	50-206
Mangan, G. V.	8403130363	50-410 S	MARTIN.T T	8403070278	50-309 F		6403220303	Waste Mg
Mangan, C. V	8403130386	50-220 P	MARTIN.T T.	8403070301	50-387 Q		6403200176	50-288
Mangan; C. V.	8403200002	50-220 P	MARTIN, T T. MARTIN, T T MARTIN, T, T, MARTIN, T, T MARTIN, T T.	8403070320	50-277 Q	MATTHENB.D.B	8312120445*	50-400
Mangan; C. V.	8403200232	50-410 A		8403070333	50-423 Q	MATTIA,M J.	6403130495*	CONTRACT
Mangan; C. V	8403210136	50-410 S		8403080159*	FGIA	MATTIA,M J.	6403220240	CONTRACT
Mangan; C. V	8403220177	50-220 P		8403090037	50-354 Q	MATTIA,M J.	8403280263*	CONTRACT
Mangan; C. V.	8403230078	50-220 P		8403090143	50-443 F	MATTIMDE,J J	8403060452	50-312
Mangan, C. V.	8403230114	50-220 F	MARTIN,T.T	8403070231	50-387 F	MATTIMOE, J. J.	8403060467	50-212
Mangan, C. V.	8403270174	50-220 P	MARTIN,T.T	8403120101	50-320 G	MATTIMOE, J. J.	8403260124	50-312
Mangan, C. V.	8403300058	50-220 P	MARTIN,T T	8403130009	50-354 G	MATTBON, D. R	8403230173	Waste Ma
Mangoba, L. B.	8403120015*	50-275 Q	MARTIN,T T.	8403130171	50-272 F	MATTBON, D. R	8403280253	Waste M
Mankoff, L. L.	8403130387	PT21	MARTIN,T T.	8403130294	70-2199	MATTBON, R. J	8402010508*	50-275
MANOLY, K.	8403300103*	50-354 Q	MARTIN, T. T.	8403130300	HIBC	MATUSEWIC, S M.	8403200020	50-156
MANOLY, K. A.	8403020272*	50-273 Q		8403130422	40-6329	MAURA, F. A	8403170277#	50-373
MANOLY, K. A	8403150034*	50-388 Q		8403150012	50-219 G	MAUSEHARDT, D. B	8403010015#	ACRE
MARANTE, R. J	8403200067*	50-219 Q		8403150027	50-388 G	MAUSEHARDT, D. B	8403010057#	ACRE
MARQULIES, M. B.	8403060111	50-508 Q		8403150068	50-272 G	MAXWELL, C,	840223024&#</td><td>50-400</td></tr></tbody></table>	

	ACCERPTON.	SUBJECT		ACCESSION	SUBJECT		ACCESSION	SUBJECT
ROHTUA	ACCESSION NUMBER	CATEGORY	AUTHOR	NUMBER	CATEGORY	AUTHOR	NUMBER	CATEGORY
MAXHELL.OF MAXHELL.OF MAXHELL.JC MAXHELL.JC MAXHELL.R	840223024B* 8403070199* 8403140302 8403140302 8403040235	50-400 A 50-400 G 50-400 G 50-400 G 50-259 F	MCGAUGHY, J. P MCGAUGHY, J. P MCGAUGHY, J. P MCGAUGHY, J. P MCGAUGHY, J. P	8403070265 8403210041 8403210057 8403210172 8403230084	50-416 S 50-417 S 50-416 P 50-416 S 50-416 P	MEDFORD, M O	8403230074 8403280030 8403290122 8403290182 8403290217	50-206 F 50-206 F 50-206 P 50-361 P
MAYER, M MAYER, M MAZUR, D H MCALPINE, E J MCALPINE, E J	8403040310# 8403220310# 8403240274 8403020174 8403070328#	50-322 T 50-322 T 50-397 P 70-143 70-27	MCGAUGHY, J P MCGAUGHY, J P. MCGAUGHY, J P. MCGAUGHY, J P. MCGAUGHY, R W	8403230087* 8403270134 8403270134 8403270030 8403020108	50-416 P 50-206 B 50-206 B 50-416 Q 50-331 P	MEDFORD, M O MEDLOCK, R L MEDLOCK, R L MEDLOCK, R L MEDLOCK, B J	8403290295 8403150235 8403150245 8403190436 8403090270	50-206 P 40-8452 40-8452 40-8452 50-282 F
MCALPINE, E J MCALPINE, E J MCALPINE, E J MCALPINE, E J MCALPINE, E J	8403160270* 8403160348* 8403160353* 8403160380* 8403160386*	70-143 70-1113 70-143 70-1113 70-143	MCGAUGHY,R W MCGAUGHY,R W MCGAUGHY,R W MCGAUGHY,R W MCGAUGHY,R W	8403040134 8403070088 8403070262 8403130144 8403150087	50-331 F 50-331 P 50-331 P 50-331 P 50-331 P	MENDELSON, I N MENDEZ, R MENDLER, J, MENGE, R C MERCER, B W	8403010044* 8403200300* 8403230208 8403200214 8403230177	CONTRACT 50-454 G NUREO 50-315 B NUREO
MCALPINE,E J MCALPINE,E J MCBAY,L Q MCBREARTY,R MCBREARTY,R A	8403160389* 8403210156* 8403090189 8403020399* 8403020272*	70-143 70-143 50-424 C 50-273 G 50-273 G	MCGAUGHY:R W MCGAUGHY:R W MCGAUGHY:R W MCGAUGHY:R W MCGAUGHY:R W.	8403170275 8403170300 8403200172 8403230004 8403230105	PR 50-331 P 50-331 P 50-331 P 50-331 Q	MERRELL, W. W MERRIWEATHER, N MERSCHOFF, E. W METZENBAUM, H. M MEYERS, B. L.	8403070332* 8403160212* 8403010430* 8402130372* 8403230108	TOPREP 50-424 Q 50-423 Q 50-358 U 50-482 S
MCBREARTY,R A MCBREARTY,R.A MCBREARTY,R.A MCBRIDE,L M MCBRIDE,L M	8403150034* 8403220062* 8403290062* 8403010155* 8403010167*	50-368 0 50-309 0 50-334 0 50-247 8 50-247 8	McGaughy, R McGolvern, J McGolvern, J McGoracken, K McGracken, K	8403260208 8403220043 8403300140* 8403140210 8403010141*	50-331 P 50-54 I 70-687 50-348 F 50-348 P	Michel, e J Michel, e J Michel, e J Michelbon, c Midura, h J	8403060287# 8403060295# 8403060307# 8104220046 8403070305	50-322 T 50-322 T 50-322 T 50-335 B 50-272 R
MCBRIDE, M MCCABE, E C MCCABE, E C MCCABE, E C MCCABE, E C	8403150073# 8403010370# 8403150060# 8403220087# 8403220160#	50-293 0 50-322 0 50-387 0 50-354 0 50-322 0	McQuire, D R McQuire, D R McQuire, D R McQuire, D R McQuire, D R	8402130404* 8403020241* 8403050178* 8403150109* 8403160016*	50-348 Q 50-250 Q 50-413 Q 50-280 Q 50-390 Q	MIELE, M. L. MIELE, M. L. MIELE, M. L. MIELE, M. L. MIELE, M. L.	8403070183* 8403070217* 8403070231* 8403230016 8403230020	50-322 T 50-322 T 50-322 T 50-322 T 50-322 T
MCCABE, E C MCCAFFREY, B R MCCAFFREY, B R MCCAFFREY, B R MCCAFFREY, B R	8403270155* 8403020139 9403020287 8403140019 8403170127	50-387 Q 50-322 A 50-322 E 50-322 A 50-322 8	MCQUIRE, D R MCQUIRE, D R MCQUIRE, D R MCQUIRE, D R MCQUIRE, P	8403160388* 8403190188* 8403260183* 8403300044* 8403060287*	50-302 G 50-259 G 70-27 70-27 50-322 T	MIELE, M L MIELE, M L MIELE, M L MIELKE, F, W	8403230032 8403230038 8403230048 8403230073 8403280051	50-322 T 50-322 T 50-322 T 50-322 T 50-133 I
MCCAFFREY.B R MCCAFFREY.B R MCCAFFREY.B R MCCAFFREY.B R MCCAFFREY.B R	8403200227 8403200302 8403270119 8403270197 8403280029	50-322 A 50-322 R 50-322 P 50-322 P 50-322 F	MCGUIRE, P MCGURREN, H J MCGURREN, H J MCKAY, L, R MCKAY, L, R	8403040275# 8403170073 8403170100 8403280018# 8403280025#	50-322 T 50-413 9 50-275 9 50-416 P 50-416 P	MIKCB:1 MIKOWSKI.J MIKOWSKI.J MIKCOB:J	8403140151 8403070113 8403210107 8403010244 8403230032	PR FOIA PRM 50-322 T 50-322 T
MCCARTHY, L T MCCLESKEY, K E MCCLESKEY, K E MCCLESKEY, K E	8403250111* 8403010183 8403010183 8403070147 8403070147	50-275 U 50-322 0 50-322 0 50-322 T 50-322 T	MCKEE, PF MCKENNA, E MCKENNA, E MCKEON, TJ MCKEON, TJ	8403130479# 8403060156 8403220001 8403230070 8403230173	50-312 0 50-204 P 50-204 P 50-206 P NUREO	MILL.8 MILLER.A MILLER.C A MILLER.C A MILLER.C W	8403080388 8403080178 8403010217* 8403010231* 8403300120	FDIA 50-320 F 50-329 A 50-329 A RES
ACCTERKEA' K E WCCTERKEA' K E WCCTERKEA' K E WCCTERKEA' K E	8403130030* 8403130030* 8403230013 8403230013 8403300277	50-322 0 50-322 0 50-322 0 50-322 0	MCLAUGHLIN, L. MCLEAREN, T MCLEAREN, T MCMURRAY, C M MCMURRAY, C M	8403060390 8403010051 8403010435 8403150026 8403150026	50-389 B CONTRACT CONTRACT 50-322 G 50-322 G	MILLER, D, E. MILLER, D J MILLER, D W. MILLER, H. J MILLER, H. J.	B403130094* B403200040 B403050090 B403060450 B403200345	40-3392 50-334 F 50-387 F HASTE MOT HASTE MOT
HCCLESKEY, K E HCCLINTOCK, R HCCLINTOCK, R O HCCLINTOCK, R O HCCLINTOCK, R O	840300277 8403080070* 8403080087* 8403080099* 8403080102*	50-322 O FDIA FDIA FDIA FOIA	MCMURRAY,C M MCMURRAY,C M MCMURRAY,C M MCMURRAY,C M, MCMURRAY,C M	8403200131 8403200131 8403200134* 8403200134* 8403200151*	50-322 0 50-322 0 50-322 0	MILLER, J. R. MILLER, J. R. MILLER, J. R. MILLER, J. R.	8403140125# 8402210274 8403010112 8403010233# 8403020283	50-400 F 50-335 P 50-344 P 50-142 G 50-309 P
1CCOLLOM, K A 1CCONNELL, T 1CCORKLE, G W 1CCORKLE, G W 1CCORACKEN, C E	8403170002 8403070352 8403080411* 8403080417* 8403170189*	50-445 0 50-367 F 50-275 F 50-275 F 50-289 0	NCMURRAY, C M NCMURRAY, C M MCMURRAY, C M NCNAMARA, A E MCNEILL, C A	8403200151* 8403200155* 8403200155* 8403020202 8403010241	50-322 9 50-322 9 50-322 9 50-322 9 50-244 R 50-333 9	MILLER, J R. MILLER, J, R MILLER, J R. MILLER, J R MILLER, J R.	8403050203 8403050208 8403050226 8403050227 8403050243*	50-317 Q 50-266 F 50-344 P 50-280 P 50-282 P
CCUMBER: J T	8403210173* 8403050102 8403060355* 8403060361* 8403020065	50-289 0 0A999 0A999 0A999 50-309 R	MCNEILL,C A MCNEILL,C A MCNEILL,C A MCNEILL,C A	8403010365 8403010413 8403010420 8403060193 8403090025	50-333 5 50-333 R 50-333 R 50-333 B 50-333 S	MILLER, J R, MILLER, J R MILLER, J, R, MILLER, J, R, MILLER, J, R	8403050352 8403050354 8403050355 8403050380 8403060080#	50-336 Q 50-335 P 50-309 P 50-309 P 50-335 P
ICCUMBER. J T ICDONALD. B A ICDONALD. D Q ICDONALD. D. O ICDONALD. J. E	8403300162 8403060106 8403010160 8403050055 8403120038	50-309 R 50-349 F 50-250 P FDIA 50-206 H	MCNEILL,C A MCNEILL,C A MCNEILL,C A MCNEILL,C A MCNEILL,C A	8403130137 8403130350 8403200231 8403220081* 8403270246	50-933 R 50-933 R 50-933 B 50-933 G 50-933 S	Miller, J. R Miller, J. R. Miller, J. R Miller, J. R. Miller, J. R	8403060447 8403060456 8403060462 8403060512 8403060551	50-344 P 50-344 Q 50-338 F 50-285 F 50-368 P
CDONDUGH, C, L CDUFFIE, M A CDUFFIE, M A CDUFFIE, M A CDUFFIE, M A	8403140001 8403130062 8403140120 8403140174 8403170065	50-456 D 50-400 E 50-400 F 50-400 D 50-400 F	MCNEILL, W M MCGUEEN, M M MEDFORD, M D. MEDFORD, M O. MEDFORD, M. O	B403170190* B403270034* B402230176 B403020040 B403020092	GA999 FDIA 50-133 F 50-341 R 50-341 P	MILLER, J. R. MILLER, J. R. MILLER, J. R. MILLER, J. R. MILLER, J. R.	8403080083 8403080191* 8403120082 8403120214 8403120217*	50-317 P FOIA 50-348 P 50-335 P
CDUFFIE, M A CDUFFIE, M A CDUFFIE, M A CGARRY, J M CGARRY, J M	8403210131 8403260009 8403290134 8403070048 8403070048	50-400 A 50-400 M 50-400 E 50-413 Q 50-413 Q	MEDFORD, NO MEDFOR	8403020275 8403050140 8403060363 8403060397 8403060424	50-204 8 50-204 8 50-204 X 50-204 S 50-361 P	MILLER, J.R. MILLER, J.R. MILLER, J.R. MILLER, J.R. MILLER, J.R.	8403120240 8403120379 8403140279 8403150290 8403150333	50-335 Q 50-344 F 50-313 P 50-282 P 50-309 P
H CANDADO CORRY, J M CORRY, J M CORRY, J M CORRY, J M	8403150029 8403150029 8403250367 8403250367 8403070325	50-413 G 50-413 G 50-413 G 50-413 G 50-414 P	MEDFORD, M. O MEDFORD, M. O MEDFORD, M. O MEDFORD, M. O MEDFORD, M. O	8403090127 8403130134 8403170345 8403200097 8403220121	50~361 Q 50~361 P 50~361 P 50~206 F 50~206 P	MILLER, J.R MILLER, J.R MILLER, J.R MILLER, J.R MILLER, J.R	8403190419 8403210206* 8403220212* 8403220259* 8403260071	50-266 P 50-338 P 50-338 P 50-266 P 50-344 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHUR	ACCESSION NUMBER	SUBJECT CATEGORY
MILLER.JR MILLER.JR MILLER.LK MILLER.LK MILLER.HA	8403240302 8403280183 8403220142 8403220174 8403050311	50-344 F 50-285 P 50-311 R 50-272 R 50-424 A	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8403160223* 8403160318* 8403160364* 8403160373 8403190054	50~259	MONTOCMERY.D M MONTOCMERY.D M MONTOCMERY.D M MONTOCMERY.D M MONTOCMERY.D M	8403160309* 8403160329* 8403290147* 8403290239* 8403060426	50-395 50-349 50-413 50-259 50-320
MILLER,M A MILLER,M E MILLER,M E MILLER,M I MILLER,M I	8403070407# 8403200108# 8403210087 8403200122 8403200122	50-322 S 50-354 G 50-354 G 50-454 G 50-454 G	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8403190099 8403190149* 8403190161* 8403190287 8403190358	50-390 8 50-259 0 50-259 0 50-438 8 50-390 8	MOONFY.JA MOONEY.JA MOONEY.JA MOORE.DE MOORE.DE	8403150003 8403200027 8403200039 8402130404* 8403030178*	50-329 50-329 50-329 50-348 50-413
MILLER,M L MILLER,M S MILLER,M S MILLER,M S MILLER,M S	8403010316 8403130174 8403130174 8403200140* 8403200140*	50-263 5 50-322 0 50-322 0 50-322 0 50-322 0	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8403170367 8403170370 8403200170 8403200225 8403210037	PR 50-327 F 50-259 P 50-390 A 50-390 S	MODRE, G H MODRE, J E MODRE, J E MODRE, J E	8403120010* 8402070054 8403140159 8403140163* 8403270319	50-275 50-400 50-400 50-400 50-400
MILLER,M B MILLER,M B MILLER,M B MILLER,M B MILLER,N E	8403200145* 8403200145* 8403200146* 8403200146* 8403300294	50-322	WILLS'T W WILLS'T W WILLS'T W WILLS'T W	8403210042 8403210046 8403210066 8403210086 8403210132	50-438 \$ 50-438 \$ 50-390 \$ 50-390 \$ 50-438 \$	MOORE,K E MOORE,R N MOORE,R N MOORE,R N MORAN,D H	8403190244* 8403200392 8403280337 8403290129 8401190219	TOPREP XPORTLIC XPORTLIC XPORTLIC TOPREP
MILLER, R L MILLER, V. L. MILLER, W A MILLER, W H MILLER, W O	8403150214 8403080155* 8402070384* 8403160072* 8003240157*	50-30 W F0IA 50-390 F 50-413 Q 50-508 A	MILLS: L M MILLS: L M MILLS: L M MILLS: L M	8403220220 8403240212 8403240216 8403240227 8403240277	40-1341 50-390 A 50-390 A 50-259 P 50-327 F	MDRAN,D H MDRELAND,P E MDRELAND,P E MGROAN,R E MGROAN,R E	8403280242 8403210005* 8403210010* 8403080135 8403080258	TOPREP 40-4920 40~6920 50-261 50-261
MILLER, W D MILLER, W D MILLER, W D MILLER, W D MILLER, W D	8211070018* 830507050&* 8308100483* 8403050215 8403050222	30-556 Q 50-509 Q 50-397 A TOPREP TOPREP	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8403270145 8403270218 8403270026 8403270038 8403270183*	50-370 F 50-370 E 50-327 P 50-327 P 50-257 Q	Morgan, R. E Morgan, R. E Morgan, R. E Morgan, R. E Morgenstern, A	8403150098 8403160262* 8403200245 8403230127 8403150153	50-261 50-261 50-261 50-261 XPORTLIC
MILLER, W. D MILLER, W. O. MILLER, W. O. MILLER, W. O. MILLER, W. O.	8403050225 8403060011 8403070001 8403120237 8403200391	TOPREP TOPREP 50-338 P 50-266 P 50-277 F	MILLS,L M MILLS,L M MILLS,L M	8403270207* 8403300004 8403300021 8403300038 8403300037	50-259 0 50-438 S 50-438 S 50-370 E 50-438 B	MORGENSTERN.M MORIARTY,J M MORIARTY,J M MORKIN.K M MORKIN.K M	8403230200 8403190248 8403190374 8403060244 8403220159	NUREQ 50-395 50-443 50-259 50-260
MILLER, W O MILLER, W O MILLER, W O MILLER, W O MILLER, W. D.	8403270358 8403270371 8403300225 8403300279 8403300279	50-206 P 50-389 P 50-261 P 50-331 P 50-324 P	MILLB:L M MILLB:L M MINARICK:J W MINECK:D L MINECK:D L	8403300054 8403300109 8403010102* 8403050145 8403120042	50-43B S 50-370 S FOTA 50-331 S 50-331 R	NORLEY, J A MORRIEL, P MORRILL, P MORRILL, P MORRILL, P J	8403060519 8403140312 8309150401* 8403010233* 8403210119*	WASTE MOT WASTE MOT FOIA 50-312 50-275
HILLER, W O MILLS, L. M MILLS, L. M MILLS, L. M MILLS, L. M,	8403300304 8402090380 8403010095 8403010306 8403010339	50-219 P 50-370 F 50-438 S 50-259 P 50-370 S	MINECK, D L MINECK, D L MINECK, D L MINECK, D L MINER, 8	8403120071 8403120139 8403130488* 8403220017 8403010374	50-331 9 50-331 9 50-331 F 50-331 R 50-312 P	MORRIB, A E MORRIB, C MORRIB, C MORRIB, C A MORRIB, C A	8403080412# 8310170712# 8403050025# 8403020010 8403020218	50-320 50-286 50-286 50-361 50-206
MILLB,L M. MILLB,L M MILLB,L M MILLB,L M MILLB,L M	8403010376 8403020236 8403020313 8403020334 8403060147	50-43B 8 50-390 F 50-327 P 50-390 F 50-259 F	MINER.S MINOGUE.R B. MINOGUE.R B. MINOGUE.R B. MINOR.G C	8403150350 7910260122* 8403150175 8403270024* 8403220305*	50-213 P 50-312 P RES FOIA 50-322 T	MORRIS,C A MORRIS,C A MORRIS,C A MORRIS,C A MORRIS,C A	8403200057* 8403200074* 8403200077* 8403200082* 8403200086*	50-361 50-361 50-361 50-361
MILLS, L M MILLS, L M MILLS, L, M, MILLS, L, M, MILLS, L M.	8403040238 8403040391 8403070023 8403070054 8403070044	50-259 F 50-327 F 50-259 G 50-259 G 50-438 G	MINOR:Q C MIRAGLIA:F.J MIRAGLIA:FJ MIRAGLIA:FJ MIRAGLIA:FJ	8403220313* 8106170138* 8106220066* 8203180118* 8403020049*	50-322 T FOIA 50-508 G 50-908 A FOIA	MORRIS, C. A MORRIS, C. A MORRIS, C. A MORRIS, P. A MORRIS, P. A	8403200088* 8403200091* 8403300003 8403300077	50-361 50-361 50-206 50-352 50-352
MILLB, L M MILLB, L M MILLB, L M MILLB, L, M MILLB, L, M	84030700B9 8403070155* 8403070174 8403070224* 8403070230	50-438 Q 50-327 Q 50-390 B 50-438 Q 50-390 Q	MIRAGLIA:F J MIRAGLIA:F J MIRAGLIA:F J MIRAGLIA:F J MIRAGLIA:F J	8403050132* 8403060037 8403080271 8403090175 8403270245	50-204 F 50-155 P MISC 50-204 P 50-322 F	MORRIS:P A MORRISON,W M MORTON MORTON,K L MORTON,K L	B403280354 6403270035# B40301007B# 6403020075 B40330006B	50-352
MILLS,L M. MILLS,L,H MILLS,L M. MILLS,L.M. MILLS,L.H.	8403070235 8403070237 8403070241 8403070245 8403070286	50-370 Q 50-257 Q 50-438 Q 50-370 Q 50-370 S	MIRAGLIA.F J MIROCHNA.R. MIBAK.A MITTENBERGER.B MITTL.R L.	8403300308 8403230076 8403130382 8403140246 8403140113	50-155 P 50-237 8 50-254 R 50-483 F 50-354 A	MORTON, K. V MORTON, K. V MORTON, K. V, MORTON, K. V MORTON, K. V	8403020043* 8403050237* 8403060495* 8403060502* 8403070009*	50-10 , CONTRACT CONTRACT CONTRACT CONTRACT
MILLS, L, M, MILLS, L, M MILLS, L, M, MILLS, L, H, MILLS, L H	8403070274 8403070297 8403070329 8403090024 8403090050	50-436 8 50-438 8 50-438 9 50-438 8 50-370 8	MITTL,R L. MITTL,R L MITTL,R L MITTL,R L MIZUND,Q.S	8403210036 8403230041 8403290277 8403290302 8403140055	50-354 A 50-354 C PR 50-354 A 50-445 Q	MORTON, K V.	8403070032* 8403070161* 8403070172* 8403070346* 8403070135*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MILLB, L, M MILLB, L, M MILLB, L, M, MILLB, L, M MILLB, L, M,	8403090163 8403090181 8403090206 8403120105 8403120163	50-438 8 50-438 8 50-370 9 50-438 8 50-438 8	MORLEY, M. H MONAGHAN, J. A MONAGHAN, J. A MONAGHAN, J. A MONAGHAN, J. A	8403070105 8403130018* 8403130018* 8403130041* 8403130041*	PR 50~322 0 50~322 0 50~322 0 50~322 0	MORTON, K V. MOSLAK, T.	8403150207* 8403230076* 8403230130* 8403270343* 8403040110	CONTRACT CONTRACT CONTRACT FOIA 50-320
MILLB, L M MILLB, L M MILLB, L M, MILLB, L, H MILLB, L M,	8403120177 8403130007 8403130025 8403130088 8403150007	50-390 E 50-259 P 50-259 P 50-327 Q 50-439 S	ACHANADH MORAPANADA MORAPANADA MORAPANADA MORAPANADA MORAPANADA	8403130053* 8403130053* 8403130043* 8403130043* 8403130073*	20-355 0 20-355 0 20-355 0 20-355 0	MOSLAK,T MOSLAK,T. MOTES:B.O. MOWRY:W R MOWRY:W R.	8403060435 8403130471* 8403060533 8403150197 8403150199*	50-320 6 50-320 6 M/REQ XPORTLIC XPORTLIC
MILLS,L M MILLS,L,M MILLS,L,M MILLS,L,M	8403150059 8403150127 8403150229 8403150042 8403160042	50-438 8 50-370 9 40-1341 50-438 8 50-259 0	MDNAQHAN, J A MONTEITH, J. L MONTEITH, J L MONTOOMERY, D MONTOOMERY, D, M	8403130073* 8403060287* 8403060275* 8403270030* 8403160202*	50-322 0 50-322 T 50-322 T 50-390 Q	MADCZKA, E. J MRDCZKA, E. J MROCZKA, E. J MROCZKA, E. J MROCZKA, E. J	8403010217 8403010217 8403020055 8403020133 8403020133	50-336 50-336 50-245 " 50-336 "

AUTHOR	ACCESSION NUMBER	BUBUECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY
HROCZKA: E J	8403200113	50-334 S	MYRABD, A. L.	8403020197	50-263 R	'NOREL IUS, C E	8403080211*	FDIA
MROCZKA: E J	8403260284	50-245 S	MYRABD, A. L	8403300087	50-263 R	NOREL IUS, C E	8403120070	50-237 Q
HROCZKA: E. J	8403300080	50-334 R	NADEL, M. V	8403070109	NUREQ	NOREL IUS, C. E	8403120073*	50-237 Q
MROCZKA: E. J	8403300080	50-334 R	NAIDU, K.	8403190076*	50-373 Q	NOREL IUS, C. E	8403120120	50-331 Q
MROCZKA: E. J	8403300135	50-245 R	NAKAMURA, N	8403010466	XPORTLIC	NOREL IUS, C E	8403120124*	50-315 Q
MROCZKA, E. J	8403300135	50-245 R	NAKAMURA, N	8403050364*	XFORTLIC	NOREL IUS, C, E	8403120125*	50-331 0
MUDD, C. H	8403280107	50-348 F	NAKAMURA, N	8403050366*	XFORTLIC	NOREL IUS, C, E	8403130204	50-440 0
MUELLER, C. J	8403140339	ACRS	NAPIER, J J.	8403300100	50-917 S	NOREL IUS, C, E	8403170085	50-123 0
MUELLER, C. J	8403140337	ACRS	NAPUDA, G	8403020220*	50-986 Q	NOREL IUS, C E	8403170094*	50-123 0
MUFFETT, J	8403080302*	50-315 G	NARIUT, P	8402140031*	50-528 Q	NOREL IUS, C E	8403230137	50-315 0
HULLAUER, J R	8403080215*	FDIA	NARBUT,P. NARBUT,P.P. NARBUCI,P.B. NARBUCI,P.B. NARBUCI,P.B. NARBUCI,P.B.	8403230117	50-312 8	NORMAN, D	8403010430*	50-423 G
MULLER, D. R	8301040211*	50-400 E		8403270137*	50-528 9	NORRHOLM, L.	8403150146*	50-286 G
MULLER, D. R	8307270412*	50-400 E		8403060232	50-370 8	NORRHOLM, L. J	8403220115*	50-272 G
MULLER, D. R	8312080188*	50-400 E		8403120150	50-370 8	NORRHOLM, L. J	8403270137*	50-272 G
MULLER, K.	8403150253	40-8786		8403120173	50-370 8	NORRIS, H, R	8403080135	50-281 R
MULLER, N. MUNSON, L. F MURLEY, T. E MURLEY, T. E MURLEY, T. E	8403150260 8403170447 8403010472 8403010483* 8403020343	40-8786 NUREQ 40-6920 40-6920 50-317 G	NARDOCI:P B NARDOCI:P B NARDOCI:P B NARROH:L NARROW:L	8403130167 8403130332 8403150138 8403020272* 8403070322*	50-370 8 50-349 8 50-370 8 50-293 0 50-277 0	NORRIE, H R. NORRIE, J. A. NORRIE, J. A. NORRY, P. Q. NORRY, P. Q.	8403080258 8403280070 8403120326 8403020378 8403300245	50-241 8 50-275 P 50-275 F CR9 CR9
MURLEY, T E MURLEY, T E MURLEY, T E MURLEY, T E MURLEY, T, E	8403080403 8403080407* 8403130212 8403150111 8403170243	50-289 G 50-289 G 50-293 G 50-293 P 50-3 F	NARVER, R. B NATARAJA: M 8 NEFF, J. O NEFF, J. O NE ICHALFEN, A P	8403140026* 8403260344 8403200348 8403360239 8403120104	50-329 A Habte Hot Habte Mot Habte Mot 50-483 A	NORTH, H B. NORTON, B. NORTON, B NORTON, B NORTON, B.	8403080075# 8403070044 8403070044 8403120006 8403120006	50-312 Q 50-275 Q 50-275 Q 50-275 Q 50-275 Q
MURLEY, T E MURPHY, A J MURPHY, C E MURPHY, C E MURPHY, L. E	8403220136	50-213 G	NEICHBORB, J D	8403020054	50-280 P	NOTARO, J. A	8403270116	50-322 A
	8403070013*	50-289 U	NELSON, O. B	8403010266#	50-142 Q	NOVACHEK, F.	8403010116	50-247 S
	8402230239*	50-400 A	NELSON, O. B	8403060331#	70-734	NOVACHEK, F	8403010135*	50-247 S
	8403080212*	50-413 G	NELSON, P. R	8403080049#	FOIA	NOVACHEK, F	8403010167*	50-247 S
	8403220307	CONTRACT	NELSON, P. R.	8403080050#	FOIA	NOVACHEK, F	8403220063	50-247 S
MURPHY, L. O	8403260296	CONTRACT	NELBON, P. R	8403080099*	FOIA	NOVAK, T. M.	8402070016	50-413 A
MURPHY, M R	8403210038	WASTE MGY	NELBON, P. R	8403080102*	FOIA	NOVAK, T. M.	8403070221*	50-440 A
MURPHY, W P	8403020247	50-271 P	NELBON, P. R	8403080109*	FOIA	NOVAK, T. M.	8403170186*	50-329 A
MURPHY, W P.	8403170086	50-271 R	NELBON, P. R	8403080123*	FOIA	NOVAKOVICH, D	8403200371	XFORTLIC
MURPHY, W P.	8403200156	50-271 G	NELBON, P. R	8403080137*	FOIA	NOVAKOVICH, D	8403280151*	XFORTLIC
MURPHY, W P MURPHY, W P MURPHY, W P. MURPHY, W P. MURPHY, W P.	8403230063	50-271 F	NELBON, P R.	B4030B0144*	FOIA	Nugent, E. L.	8403120251	40-2259
	8403270190	50-271 P	NELBON, P R	B4030B0157*	FOIA	Nugebaumer, D.	8403120248	WASTE MOT
	8403300071*	50-271 Q	NELBON, P R	B4030B0177*	FOIA	Nugebaumer, D. A.	8403020332	WASTE MOT
	8403300146*	50-271 Q	NELBON, R	B403300030*	50-454 G	Nugebaumer, D. A.	8403080119*	FOIA
	8403300153	50-271 Q	NELBON, R L	B403190384*	50-305 G	Nugebaumer, D. A.	8403080128*	FOIA
MURRAY, B	8403060184*	50-443 Q	NELBON, R W	8403230173	NUREC	NUSSBAUMER, DA	8403080138*	FDIA
MURRAY, B	8403130148*	50-267 Q	NEMETHY, E	8403210018	PR	NUSSBAUMER, DA	8403080181*	FDIA
MURRAY, B	8403260087*	50-382 Q	NEMETHY, E	8403210022	PR	NUSSBAUMER, DA	8403150221	WASTE MOT
MURRAY, B	8403260107*	50-267 Q	NERBEB, V	8403280122	50-244 P	NUSSBAUMER, D.A	8403190420	WASTE MOT
MURRAY, B	8403260172*	50-267 Q	NEUMANN, B P	8403230197	NUREC	NUSSBAUMER, DA,	8403260153*	40-1478
MURRAY, B	8403240211*	50-267 0	Newman, J R	B403070117	50-498 Q	NUTT, W. T.	8403230102*	50-255 P
MURRAY, B	8403240250*	50-382 0	Newman, T C	8403080281*	50-275 E	NUTT, W. T	8403230104*	50-255 P
MURRAY, B	8403300050*	50-313 0	Nicholas, J, B	B403060184*	50-445 Q	NYKIRK, J. W.	8403140082	50-275 F
MURRAY, T D	8401140250	50-346 B	Nicholas, N, N	B403150024	50-352 Q	O'CONNELL, J	8403270347	50-275 Q
MURRAY, T D	8403020078	50-346 R	Nicholas, N, N	B403150024	50-352 Q	O'CONNOR, P. W.	8403270240	50-482 A
MURRAY, T. D	8403070251	50-346 R	NECHOLSON, N	8403190334*	50-295 0	O'CONNOR, P. W.	8403270283	50-482 A
MURRAY, T D	8403130274	50-346 F	NICHOLSON, W O	8403020050	50-344 R	O'CONNOR, P. W	8403270351	50-482 A
MURRAY, T D	8403170107	50-346 R	NIGHTINGALE, E	8403190323*	50-358 0	O'DONNELL, F. R	8403120255	RES
MURRAY, T D	8403170213	50-346 R	NIMITZ, R. L.	8403070306*	50-367 0	O'NEILL, J.	8403260360	50-155 9
MURRAY, T D	8403270147	50-346 F	NIMITZ, R. L	8403130208	50-219 S	O'NEILL, J. H	8403010263	50-400 9
MURRAY, T D. MUSELER, W J MUSELER, W J MUSELER, W J MUSELER, W J MUSELER, W J.	8403300184 8403010207 8403010207 8403010218 8403010218	50-346 R 50-322 8 50-322 8 50-206 8	NIMITI.R L. NIX.H C NIX.H C. NIX.H C NIX.H C	8403270210* 8403010330 8403070228 8403070282 8403120031	50-272	O'NEILL,JH O'NEILL,JH O'NEILL,JH O'NEILL,JH	8403010263 8403130447 8403130447 8403130459* 8403130459*	50-400 Q 50-400 Q 50-400 Q 50-400 Q 50-400 Q
MUSELER, W. J. MUSELER, W. J. MUSELER, W. J. MUSELER, W. J. MUSELER, W. J.	840314004B 8403140050 8403150133 8403150133 8403270132	50-322 8 50-322 8 50-204 8 50-204 8 50-322 8	NIX, H. C. NIX, H. C. NIX, H. C. NIX, H. C NIX, H. C	8403180071 8403160031 8403160044 8403190026 8403260086	50-321 R 50-366 S 50-321 S 50-366 S 50-366 S	O'NEILL,J H. O'REILLY,J. P O'REILLY,J. P O'REILLY,J. P	8403220261 8403220261 8401240304 8403070067 8403070151	50~400
MUBELER, W J. MUSOLF, D MUSOLF, D MUSOLF, D, MUSOLF, D	8403270132 8403010316 8403020197 8403060425 8403120033	50-322 B 50-263 B 50-263 R 50-262 P 50-263 B	NIX.H.C. NIX.H.C NIX.H.C NOBLEB,L.M. NOLAN.F.J	8403260119 8403260191 8403300339 8403260277 7908010102#	30-366 B 50-366 B 50-321 F 50-327 F 50-509 A	O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P. O'REILLY, J. P O'REILLY, J. P.	8403070156* 8403070279 8403080051* 8403080056*	50-327 0 50-280 0 FOIA FOIA
MUBDLF, D MUBDLF, D, MUBDLF, D, MUBDLF, D, MUBDLF, D	8403120088 8403130365 8403190388 8403190397 8403200255	50-243 8 50-243 8 50-282 0 50-282 P 50-263 9	Norbergo, J Norderhaud, L. Norderhaud, L. R. Norderhaud, L. R Norderhaud, L. R	8301060420# 8403120185# 8403060327 8403060331# 8403080145	F01A 50-361	O'REILLY, J. P. O'REILLY, J P. O'REILLY, J P. O'REILLY, J. P. O'REILLY, J. P.	8403080074* 8403080121* 8403140105 8403140247 8403140273	FOIA FOIA 70-1113 50-261 G 50-259 G
MUSOLF, D.	8403220003	50-263 8	Norderhaug, L R.	8403120184	50-361 @	D'REILLY, J P. O'REILLY, J, P. O'REILLY, J, P. O'REILLY, J, P. O'REILLY, J, P.	8403160323	70-143
MUSOLF, D	8403230051	50-282 P	Norderhaug, L R	8403170157	70-984		8403160377	70-143
MUSOLF, D	8403270049	50-263 F	Norderhaug, L R.	8403170224	70-1257		8403290047	50-259 G
MUSOLF, D	8403270170	50-262 Q	Norderhaug, L R.	8403170376	50-206 B		8403290097	50-250 G
MUSOLF, D	8403300087	50-263 R	Norelius, C E	8403010380	50-373 B		8403290181	50-335 F
MUBDLF: D,	8403300075	50-282 R	NORELIUS, C. E	8403050232*	F01A	O'REILLY, J. P.	8403270170*	50-259 Q
MUTO, N. J	8403220302*	50-322 T	NORELIUS, C. E.	8403050235*	50-305 P	O'REILLY, J. P.	8403270274	50-280 Q
MYERS: D.	8403160385*	50-261 G	NORELIUS, C. E	8403050256*	50-255 Q	O'REILLY, J. P.	8403270315	50-250 Q
MYERS: D. O,	8403070310*	50-324 G	NORELIUS, C. E.	8403060250	50-374 P	O'REILLY, J. P.	8403300324	50-241 Q
MYERS: D. O,	8403270072*	50-324 G	NORELIUS, C. E.	8403080209*	F01A	O'REILLY, J. P	8403300327*	50-241 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
O'TOOLE, J. D O'TOOLE, J. D O'TOOLE, J. D O'TOOLE, J. D	8403020155 8403050015* 8403050075 8403070078* 8403070288	50-247 R 50-247 G 50-247 P 50-247 P 50-3 F	PALLADINB, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J	8403060061* 8403060065* 8403060071* 8403060074* 8403070053	COMMISSION COMMISSION COMMISSION COMMISSION 50-287 P	PARSONS, R M.	8403130237 8403130378 8403200203 8403270071 8403270166*	50-400 8 50-400 8 50-400 8 50-400 8 50-400 9
O'TOOLE, J, D O'TOOLE, J, D, O'TOOLE, J, D, O'TOOLE, J, D,	8403130405 8403150027 8403190067 8403170355 8403200124	50-247 8 50-247 0 50-3 F 50-247 F 50-247 P	PALLADINO, N J	8403070060* 8403070069* 8403070003* 8403070004* 8403070005*	50-287 U 50-287 U 50-287 U 50-287 U 50-287 U	PAREONS.R M PAREONS.R M PARTLOW.J G PARTLOW.J G PARTLOW.J G	8403300034 8403300043 8311140347# 8402030555# 8403010427	50-400 8 50-400 8 50-400 £ MISC 50-423 Q
O'TOOLE, J D O'TOOLE, J, D, O'TOOLE, J, D, O'TOOLE, J D O'TOOLE, J D,	8403210154	50-247 8	PALLADINO,N J	8403070007*	50-287 U	PARTLOW: J Q	8403130498	50-312 G
	8403230135	50-3 R	PALLADINO,N J	8403070008*	50-287 U	PABCIAK: W	8403010366*	70-1100
	8403260120	50-3 R	PALLADINO,N J	8403070007*	50-287 U	PABCIAK: W J	8403010314*	50-352 G
	8403270186	50-247 R	PALLADINO,N J	8403070010*	50-287 U	PABCIAK: W J	8403150078*	50-272 G
	8403270173	50-247 P	PALLADINO,N J	8403120376	COMMIBBION	PABCIAK: W. J	8403160248*	50-352 G
O'TOOLE, J D	8403270204	50-247 S	PALLADINO, N J	8403160032	50-287 0	Pasciak, H. J.	8403270120*	50-387 0
O'TOOLE, J, D,	8403290170	50-247 P	PALLADINO, N J	8403200191	50-287 0	Pastva, M. J.	8403010133	50-325 8
O'TOOLE, J, D	8403290172	50-247 Q	PALLADINO, N J	8403200198*	50-287 0	Pastva, M. J.	8403010202	50-325 8
O'TOOLE, J D,	8403290268	50-247 Q	PALLADINO, N J	8403290087	COMMISSION	Pastva, M. J.	8403130047	50-325 8
OBERO, C, R.	8403060373#	50-245 Q	PALMER, B	8403270014	80-327 A	Pastva, M. J.	8403130152	50-324 8
DBERO, C. T. DBERLANDER, F. L. DDEGAARDEN, R. H. DDELL, N. H. DEBTMANN, M. J.	8403060210#	40~8830	PALMER, B	8403300070	50-327 A	PAPTVA, M. J	8403130323	50-325 8
	8403300132#	50~478 A	PALOMINO, F. O.	8403230010	50-322 Q	PAPTVA, M. J	8403150035	50-325 8
	8403160164	71~9175	PANCIERA, V.	8403020235	50-302 8	PAPTVA, M. J	8403190302	50-325 8
	8403260180	50~458 A	PANCIERA, V.	8403070024*	50-424 Q	PAPTVA, M. J	8403200273	50-324 8
	8403170313#	50~341 Q	PANCIERA, V.	8403170284	50-366 8	PAPTVA, M. J	8403210123	50-324 8
OEBTMANN, M, J,	8403300033*	50-456 G	PANCIERA, V. W.	8403270197*	50-346 0	PASTVA.M. J	8403270266	50-324 8
OEBTMANN, H, J	8403300040*	50-262 G	PANETTA, L E	8312280102*	50-275 E	PATEL.R E	8403050100*	50-318 P
OLIVEIRA, W.	84033270150*	50-352 G	PANG, J F.	8403200132	INE	PATRICK.D P	8403020132*	FOIA
OLLER, R E	8403130325*	GA797	PANG, J F.	8403200224	70-1359	PATRICK.D P.	8403020219*	FOIA
OLLER, R E	8403270184*	GA797	PANGBURN, G C	8403200350	40-8452	PATRISSI.G A	8402030344*	50-206 F
OLMSTEAD, W. J OLMSTEAD, W. J OLSON, O. L. OMAN, R. OMAN, R. O.	B403060095* B403080225* B403230245 B403120012* B403120010*	FOIA FUIA HABTE MGT 50-275 0 50-275 0	Pangburn, O C Padlino, R. J. Papazoblou, I A. Paperiello, C Paperiello, C. J	8403200380 8403150034* 8403230133 8403230023 8005280798*	40-8102 50-388	PATTERSON, C. PATTERBON, C PATTERBON, J. PATTERSON, R. PATTERBON, W. F	8403170188* 8403270072* 8403200117* 8403120027* 8403140052	50-259 0 50-324 0 50-483 0 50-275 0 50-443 0
OPEKA, J. F. OPEKA, J. F. OPEKA, J. F. OPEKA, J. F. OPEKA, J. F.	B403010391 B403090137 B403090257 B403090257 B403090272	50-213 P 50-213 0 50-336 P 50-336 P	PAPERIELLO, C J. PAPERIELLO, C. J. PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J	8403050004 8403050067 8403050072 8403050125 8403050162	50-237 F 50-346 Q 50-254 Q 50-305 F 50-454 F	PATTERSON, W. F PATTIBON, R S PAUL, R A PAULES, J PAULITZ, F	8403280355 8403150274 8403270242* 8403140088 8403090043*	50-155 Q 40-8084 50-409 Q 50-289 F 50-354 Q
OPEKA, J.F.	B403090272	50-334 P	PAPERIELLO, C J,	8403050305	50-315 0	PAULK, O L	8403160186*	50-259 Q
OPEKA, J.F.	B403120135	50-245 R	PAPERIELLO, C J	8403130083	40-3392	PAULBON, W A	8403010351	50-255 F
OPEKA, J.F.	B403120135	50-245 R	PAPERIELLO, C J,	8403130101	40-2041	PAULBON, W A.	8403010368	50-255 P
OPITZ, B.E.	B403070118	NUREQ	PAPERIELLO, C J,	8403130478	50-331 F	PAULBON, W A.	8403080232	50-255 P
OPREA, O.W.	B403130328	50-498 B	PAPERIELLO, C J	8403130478	50-341 0	PAULBON, W A	8403270166	50-255 P
Oprea, o w	8403130477	50-478 8	PAPERIELLO, C. J. PAPERIELLO, C J. PAPERIELLO, C J. PAPERIELLO, C J. PAPERIELLO, C. J.	8403200109	50-407 F	PAULSON, W. A	8403300064	50-255 P
Orber, c. e.	8403050081*	50-458 A		8403200111	50-483 G	PAHLICKI, S	8403270007*	FOIA
Paden, r. c	8403060135	FUIA		8403200117*	50-483 G	PAYNE, M T	8403120002	50-400 9
Page, m.	8403010017	CONTRACT		8403200287	50-243 G	PAYNE, M T.	8403120002	50-400 9
Page, m.	8403060500	CONTRACT		8403220050	50-315 G	PAYNE, M T	8403120002	50-400 9
Page, M Page, M. Page, M Page, M Page, R. G.	8403070380 8403070411 8403070133 8403070138 8403010507	27-39 CONTRACT CONTRACT CONTRACT 40-8027	PAPERIELLO, C J. PAPERIELLO, C J. PAPERIELLO, C J. PAPERIELLO, C J. PAPERIELLO, C. J.	8403220093 8403220094 8403220134 8403270177 8403300026	50-246 0 50-454 0 50-305 0 50-461 0 50-456 0	PEACOR.D H. PEAK.G.J. PEARRING.J R PEARBON.A. PEARBON.A	8403150031 8403020007 8403280257 8403020079 8403150158	50-205 F 50-316 R WASTE HOT XPORTLIC XPORTLIC
PAGE.R.O. PAGE.R.O. PAGE.R.O. PAGE.R.O. PAGE.R.O	8403070015 8403070107 8403070348 8403140215 8403200327	70-1201 70-824 40-8820 40-8027 40-2061	PAPERIELLO,C J. PAPERIELLO,C J. PAPERIELLO,C J. PARIB,O H. PARIB,O H	8403300036 8403300042 8403300047* 8403080110 8403090132	50-282	PEARSON, R. Q. PEDERSEN, D. R.	8403090340 8403090340 8403140085 8403140085 8403140339	ACRS ACRS 50-400 (1 50-400 (1) ACRS
PAGE, R. O.	8403230241	70-1359	Paribid, H	8403130394	50-424 0	PEDERBEN.D.R	8403140339	ACRS
PAGE, R. O.	8403230244*	70-1359	Paribir D.	8403090159	PR	PEDERBEN.R.L.	8403010186	50-247 ;
PAGE, R. O.	8403260082	70-1257	Parkij, E.	8403260286	NUREG	PEDERBEN.R.L.	8403070394	50-247 ;
PAGE, R. G.	8403260141*	40-1478	Parker, J	8403010121	50-416 8	PEDERBON.L.T	8403160131	GEN TEC IS
PAGE, R. G.	8403270273	70-36	Parker, J	8403120148	50-416 B	PEDRO.J	8403010278	FOIA
PAGE, R. O.	8403300293	70-1257	Parker, J.	8403130464	50-416 8	PEDRO, J.	8403020392	50-287 ;
PALLADINO, N. J.	8402130353*	50-358 U	Parker, J.	8403170057	50-416 8	PEDRO, J.	8403070098	FOTA
PALLADINO, N. J.	8402130390*	50-358 U	Parker, J.	8403300118	50-416 8	PELLET, J.	8403280079*	50-366 ;-
PALLADINO, N. J	8402130393	50-358 U	Parker, M E	8403220114*	50-341 0	PELLET, J. L.	8304270367	50-366
PALLADINO, N. J	8402130399*	50-358 U	Parkingon, T. F.	8403170437	NUREO	PELLET, J. L.	8305040149	50-273
Palladino, N. J.	8402220291	50-287 U	Parks, B	8403130035	50-387 S	PELLETIER, J P	8403020322	50-271
Palladino, N. J.	8403050194	50-346 M	Parr, C, D	8306220210*	50-440 A	PELLETIER, J P,	8403020326*	50-271
Palladino, N. J.	8403050196	COMMISSION	Parrish, S Q	8403230279	50-424 Q	PELLETIER, J P,	8403020328*	50-271
Palladino, N. J.	8403050200	COMMISSION	Parry, O, W.	8403260253*	50-352 E	PENN, J	8403130312*	MISC
Palladino, N. J.	8403050204#	COMMISSION	Parsons, C, H	8403270314	50-270 F	PENNIFILL, R	8403200351	WASTE HOT
Palladino, n J. Palladino, n, J.	840305034& 8403050348 8403050362 8403050377 8403060014	COMMISSION COMMISSION COMMISSION COMMISSION	Parsons, R. M. Parsons, R. M. Parsons, R. M. Parsons, R. M. Parsons, R. M.	8402270274 8403010350 8403010394 8403070095* 8403070096*	50-400 B 50-400 S 50-400 B 50-400 G 50-400 Q	PENNIFILL, R. PERCH. R. PERCH. R. L. PERCH. R. L. PEREZ, Q. P.	8403220193 8403010254 8403150232 8403150321 8403080279*	WASTE MOT 50-387 50-388 50-388 50-312
Palladino, N. J. Palladino, N. J. Palladino, N. J. Palladino, N. J. Palladino, N. J.	8403060018 8403060023* 8403060030* 8403060037* 8403060046*	COMMISSION COMMISSION COMMISSION COMMISSION	PARSONS, R. M. PARSONS, R. M. PARSONS, R. M PARSONS, R. M PARSONS, R. M.	8403070184* 8403070285 8403070290 8403090082 8403120084	50-400 G 50-400 S 50-400 S 50-400 B 50-400 B	PERLIS.R.O PERLIS.R.O. PERLIS.R.O. PERLIS.R.O. PERLMAN.J.	8403140051 8403140134 8403190124 8403210194 8403010035	50-443 90-295 50-322 50-443 CONTRACT

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	АОНТИА	ACCESSION NUMBER	SUBJECT CATEGORY
PERLMAN, J	8403070371	CONTRACT	POLK, PJ	8307270506*	50-286 P	POTERALSKI, D C	8403170179*	50-250 Q XPURTLIC 50-324 B XPURTLIC XPURTLIC
PERLMAN, J	8403120306	CONTRACT	POLK, PJ	8403020064	50-286 P	FOTTER, A.	8403200373	
PERLMAN, J	8403120340	CONTRACT	POLK, PJ	8403020352	50-286 F	POULK, R M	8403010297	
PERLMAN, J	8403260316	CONTRACT	POLK, PJ,	8403050027*	50-286 P	POWELL, C	8403060569	
PERRY, P. A	8403190071	50-155 1	POLK, PJ	8403050041	50-286 P	POWELL, C.	8403060573*	
PERBINXO, D	8403160158	50-244 P	POLK,P J	8403050278	50~286 P	POWELL,C	8403220328	XPDRTLIC
PERSON, R T	8403270172	50-267 I	POLLACK,H N	8403230131	NUREQ	POWERB,D	8403010076*	FDIA
PETERB, M A	8403120075	50-373 S	POLLARD,R. B	8310200141	FOIA	PRELL,J	8403020220*	50-388 @
PETERBONL S	8403300106	50-344 H	POLLARD,R D	8403080354	FOIA	PRESLEY,K	8403270150*	50-352 @
PETERBON, M R	8402020431	XPORTLIC	POMERDY,D. L	8403270004*	50~247 P	E	8403120080	50-373 8
PETRICK, N A	6402090302 6403010270 6403010406 6403060298 6403130342	50-482 A 50-482 F 50-482 A 50-482 A	Poole, D Poppe, L Porse, L Porse, L Porse, L	8403010137* 8401120525 8403290009* 8403290011* 8403290020*	50-348 P WASTE MOT FOIA FOIA	PRESTON, J. PREVATTE, R L PRICE, K W. PRINTZ, M PUDLICK, L	8403270113* 8403070199* 8403190295 8403060376* 8403120088	ACRS 50-400 G PR GA979 50-263 S
PETRICK, N A	8403200050 8403200187 8403200253 8403220019 8403220036	50~482 E 50~482 K 50~482 F 50~482 A 50~482 A	Porse, L Porse, L Porse, L Porse, L Porse, L	#409290022 #409290028 #609290036 #360079098 *04002900	FOIA FOIA FOIA FOIA	PULLANI, S PULLANI, S V PULLANI, S, V PURDOM, P W PURPLE, R A	8403160157# 8403220091# 8403290071# 8403200042 8403190077#	50-272 0 50-277 0 50-271 0 50-413 0 50-249 0
PETRICS,N A PETRICK,N A PETRICK,N A PETRICK,N A PETRILAK,R W PETRONE,C.	8403220029	50-482 A	PORBE: L	8403270045*	50-266 P	PUTNAM, K. B	8403220017	50-331 R
	8403220184	50-482 A	PORBE: L	8403270063*	F01A	PYRIH, L. B	8403140187*	50-352 9
	8403240282	50-482 A	PORTER: 8 W	8403230048	50-322 T	QUAMME, D. L	8403080245	50-329 8
	8403220297*	50-322 T	POTAPOVS: U.	8402010178	GA779	QUAMME, D. L	8403080248	50-329 A
	8403010390*	50-322 Q	POTAPOVS: U.	8402150211	GA779	QUAMME, D. L	8403130148*	50-329 A
PETRONE, C PETRONE, C PETRONE, C PETTENGILL, H PETTENGILL, H	8403170285	50-322 S	POTAPOVS, U	8403010430*	50-423 G	GUAMME, D. L	8403130261	50-329 A
	8403220160*	50-322 G	POTAPOVS, U	8403050086	GA779	GUAMME, D. L	8403190098	50-329 A
	8403230074	50-322 S	POTAPOVS, U	8403050089	GA799	GUAMME, D. L	8403220007	50-329 A
	8403200323	40-4472	POTAPOVS, U	8403050126	GA797	GUAMME, D. L,	8403230031	50-329 Q
	8403060465	40-3453	POTAPOVS, U	8403050130	GA777	GUAMME, D. L	8403230114	50-329 A
PETTENGILL, H J	8403170413 8403170416 8403170431 8403170443 9403200343	40-8084 40-6622 40-3453 40-2259 40-1162	POTAPOVS, U. POTAPOVS, U POTAPOVS, U POTAPOVS, U. POTAPOVS, U.	8403050174 8403040006 8403040092 8403040098* 8403040157	GA979 GA979 GA979 GA979 GA979	OUAMME,D L. GUIRK,J F. GUIRK,J F RADER,R M RADER,R,M.	8403270199 8403130285 8403300088 8403300129 8403300129	50-329 Q TOPREP TOPREP 50-352 Q 50-352 Q
PETTENGILL, H J	8403200350	40-8452	POTAPOVS. U	8403060174	TOPREP	Radford, e, p	8403220305*	50~322 T
	8403200377	40-6657	POTAPOVS. U	8403060219	GA999	Rafeedie, d. p	8403150071	50~321 R
	8403200380	40-8102	POTAPOVS. U.	8403060251	GA999	Rahe, e. p.	8403090201	FR
	8403200397	40-6622	POTAPOVS. U.	8403060282	GA999	Rahe, e. p	8403130358*	50~482 A
	8403200397	40-3453	POTAPOVS. U	8403060287	GA999	Rahe, e. p	8403130375*	50~482 A
PETTENGILL, H J	8403220210	40-8602	Potapovs, u.	8403060348	GA799	RAHE, E P	8403130389*	50-482 A
PETTIJOHN, S L	8403280301*	Misc	Potapovs, u	8403060352*	GA799	RAHE, E P,	8403210015	TOPREP
PFAFF, B J	8403260242	40-6659	Potapovs, u	840312036	GA797	RAINEY, J A.	8403200358	NUREQ
PFEFFERLEN, H G	8403060409	Toprep	Potapovs, u	8403120108	GA797	RAJARAM, V	8403260350*	HASTE MOT
PHILDRICK, B S	8403160093	Acrs	Potapovs, u	8403130032	GA797	RAMAB, B. L	8403130499*	50-312 Q
PHILBRICK, S S PHILLIPS, H S PHILLIPS, H S PHILLIPS, J D PHILLIPS, M P	8403160053	ACRS	Potapove. U	8403130046	GA797	rapkin, a	8403040124*	40~2061
	8403190214*	CA777	Potapove. U	8403130055	GA797	Rapkin, a	8403070030*	40~2061
	8403190221*	CA779	Potapove. U.	8403130068*	GA797	Rapkin, a.	8403200083	40~2061
	8305040013*	FDIA	Potapove. U	8403130089*	GA797	Rapkin, a	8403200089*	40~2061
	8403200119*	50-483 G	Potapove. U	8403130268	GA797	Rapkin, a.	8403300258	40~2061
PHILLIPB, M P PHILLIPB, M P. PIERCE, J H PIERCE, R L PIGDIT, D.	8403270180*	50-461 0	POTAPOVS. U	8403130276	GA999	RATHSAM, R	8403270035	30-295 8
	8403300051*	50-315 0	POTAPOVS. U	8403130307	GA999	RAVENBCROFT, N	8403280057	XPORTLIC
	8403140012*	50-458 0	POTAPOVS. U	8403130317	GA999	RAWBON, R. J	8403140068	50-454 0
	8403020043*	50-10 P	POTAPOVS. U	8403130327*	GA999	RAWBON, R. J	8403140081	50-322 0
	8403090126	50-445 0	POTAPOVS. U	8403130407	GA999	RAWBON, R. J.	8403140129	50-454 9
PICOTT.D PILANT.J M PILANT.J M PILANT.J.M PILANT.J.M	840307012 <i>6</i> 8403050075* 8403060237 8403060264 8403060346	50-445 Q 50-298 Q 50-298 F 50-298 F 50-298 F	POTAPOVS: U POTAPOVS: U POTAPOVS: U POTAPOVS: U	8403130441 8403170041 8403170046 8403170070 8403170078	GA799 GA799 GA999 GA799 GA799	Raweon, R. J Raweon, R. J Raweon, R. J. Raweon, R. J. Read, J. J.	8403140146 8403140148 8403190124 8403210024 8403060301*	50-454 9 50-454 9 50-322 0 50-287 0 50-322 T
PILANT, J M PILANT, J M PILANT, J M, PILANT, J M PILANT, J M	8403060354 8403060392 8403080265 8403150168 8403160260*	50~278 F 50~278 Q 50~278 F 50~278 P 50~278 Q	POTAPOVS, V POTAPOVS, V POTAPOVS, V POTAPOVS, V	8403170112 8403170145 8403170183 8403170206 8403170209	GA999 GA999 GA999 GA999 GA999	REAVIB, J. A REAVIB, J. A REAVIB, T. A. REBELLO, J. E REBELLO, J. E	8402210150 8403200010 8403200123 8403020073* 8403220219*	50-349 R 50-249 R 50-349 R CONTRACT CONTRACT
PILANTIJ M PILANTIJ M PILANTIJ M PILANTIJ M	8403170089 8403200167 8403200254 8403220042* 8403220055	50-298 F 50-298 F 50-298 P 50-298 Q 50-298 F	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8403170218 8403170254 8403170328 8403170327 8403170337	GA999 GA999 GA999 50-461 (I GA999	REBELLO, J E REBELLO, J E REBELLO, J, E REBELLO, J, E, REBELLO, J E,	8403220280* 8403220312* 8403220317* 8403220327* 8403230052*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
PILANT, J M	8403270013	50-278 F	POTAPOVS.U.	8403190338	04797	REBELLO, J. E.	8403230154*	CONTRACT
PIRTLE, O L	8403170237#	50-331 0	POTAPOVS.U	8403190342	04797		6403260307*	CONTRACT
PIRTLE, G L	8403260023*	50-346 G	POTAPOVS.U.	8403190364	04797		8403260356*	CONTRACT
PLAINE, H H,	8403200205*	50-287 0	POTAPOVS.U	8403190380	04797		8403260370*	CONTRACT
PLATO, E D	8403070226	50-327 B	POTAPOVS.U	8403200072	04797		8403270284*	CONTRACT
PLATO, P	8403140151	PR	POTAPOVS, U	8403200138	GA999	REBELLO, J. E	8403270306*	CONTRACT
PLIML, Q	8403140082	50-295 F	POTAPOVS, U	8403200142*	GA999	REBELLO, J. E.	8403280187*	CONTRACT
PLIML, Q	8403210089	50-295 F	POTAPOVS, U	8403260058	GA999	REECE, H. D.	8403190449	NUREO
PLIML, Q	8403230124	50-295 F	POTAPOVS, U	8403270050	GA999	REED, C.	8403060394	50-454 A
PLIML, Q	8403280119	50-295 F	POTAPOVS, U	8403270092	GA999	REED, C.	8403130359*	50-373 G
PLISCO, L.	6403150060*	50-387 Q	POTAPOVS, U	8403270142	GA799	REED, C.	8403260194	50-374 A
PLISCO, L.	#403270155*	50-387 Q	POTAPOVS, U	8403270148	GA799	REED, O. A.	8403270049*	50-266 P
PLOSXI, T	6403200117*	50-483 Q	POTAPOVS, U	8403270174	GA799	REED, J. D	8403210009	PR
POIDHURST, B, W	#403270094*	40-8760	POTAPOVS, U	8403270178	GA799	REED, L. Q.	8403200104	50-456 D
POLICH, T.	#403060146*	50-275 Q	POTAPOVS, U,	8403270228	GA799	REED, L. L.	8403150072	50-73 R

539

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
REEVES, E	8403010210	50-348 P	RILEY, J	8403070033	50-413	ROBA, F	8403170122*	50-275 0
REEVES, E	8403020440	50-348 P	RILEY, J L	8403070037*		ROSANO, R	8403080213	50-259 0
REEVES, E	8403070357	50-348 P	RILEY, J L	8403220237		ROBANO, R	8403160051	50-331 5
REEVES, E A	8401120594	50-348 P	RING, M	8403300030*		ROSENTHAL, A S	8402230237*	50-400 0
REEVES, E A	8403070379	50-348 P	RITGHER, J A	8403150080		ROBB, D F	8103050718*	FOIA
REEVES, E. A	8403260326	50-348 P	RITSHER, J A	8403150080	50-443 A	ROSS.T.M	8403060149*	50-275 G
REGAN, W H	8203100370#	50-397 C	RIVENBARK, G	8403010110	50-321 P	ROSS.W J	8104220881*	50-286 P
REGAN, W H	8403080278	50-413 M	RIVENBARK, G	8403060436	50-321 P	ROSS.W J	8403160120*	50-369 G
REGAN, W H	8403080283#	50-413 M	RIVENBARK, G W	8401120456	50-321 P	ROSSEACH.L W	8403150166*	50-286 G
REGAN, W H	8403220271	50-458 M	RIVKIN, W B.	7704030132*	FOIA	ROSSI.A R	8403220272*	50-322 T
REGAN,W H REGENBBURG,K J REGENBBURG,K J REGENBBURG,K J REHM,T A	8403280161	50-458 M	Rivkin, w B	7904030135*	FOIA	ROSZTOCZY, Z R	8403270041*	F01A
	8403060266*	50-322 T	Roach, p. A	8403160038	50-251 S	ROTELLA, T S	8403220070	50-335 8
	8403060270*	50-322 T	Roach, p. A.	8403160058	50-250 S	ROTH, W V	8403150341*	50-272 U
	8403060278*	50-322 T	Robbins, J. G	8403140003	50-322 J	ROTHSCHILD, M U	8403080352*	90-336 P
	8403060487	COMMISSION	Robbins, J. G	8403140037	50-413 J	ROUSE, L C	8403020231	70-687
REICH.M. REICHEL.N I REICHEL.N.I REICHEL.N I REIS.E.J.	8403010227# 8403130354 8403130352 8403130491 8403270295	50-329 A 50-329 S 50-329 S 50-329 S 50-329 S	ROBBERTS, B J ROBERTS, B J ROBERTS, M J ROBERTS, R C	8403260170 8403140170* 8403290110 8403230057 8403040289*	TOPREP FR ACRS MUREO 50-322 T	RDUBE, L C ROWE, C ROWE, C ROWE, C ROWBOME, F	8403290332 8403070283 8403080166* 8403210040 8311140250*	70-487 50-293 S FOIA I&E ACRS
REIB, E J	8403280356	50-322 0	ROBERTE,R C	8403040275#	50-322 T	ROWEOME, F	8312170358*	ACR8
REIB, J B.	8403200032	50-373 S	ROBERTE,R C	8403040301#	50-322 T	ROWEOME, F	8403010065*	ACR8
REIB, J B.	8403280023	50-374 S	ROBERTE,R C	8403040317#	50-322 T	ROWEOME, F	8311140248*	ACR8
REIB, J, B.	8403280073	50-374 S	ROBERTE,R G	8403280178	50-348 F	ROY, W	8403260148*	40-1478
RENZ, H F	8403070165*	50-322 T	ROBERTSON,J A	8403020305#	50-54 Q	ROZAK, 8	8403300040*	50-282 G
RENZ, W F.	8403070178*	50-322 T	ROBINSON, E D	8403070140#	50-322 T	ROZEAR, C. J	B40313020B	50-259 B
RENZ, W F	8403070190*	50-322 T	ROBINSON, E D	8403070175#	50-322 T	ROZEAR, C. J.	B403170125	50-259 B
RENZ, W. F.	8403070222*	50-322 T	ROBINSON, E D	8403070204#	50-322 T	ROZEAR, C. J.	B403220046	50-259 B
REPKA, D. A	8403140042	50-322 Q	ROBINSON, E. O	8403070207#	50-322 T	RUBENSTEIN, L. S	B10304004B*	50-266 P
REPKA, D. A	8403140045	50-322 T	ROBINSON, E D	8403070211#	50-322 T	RUBENSTEIN, L. S	B211070035*	50-400 E
REPKA, D. A. REPKA, D. A. REPKA, D. A. REPKA, D. A. REPKA, D. A	8403140165 8403190092 8403190124 8403210100 8403210104	20-355 0 20-355 0 20-355 0 20-355 0	ROBINBON, E D ROBINBON, E D ROBINBON, E D, ROBINBON, E D, ROCCO, J.	8403070214* 8403070227* 8403230020 8403230038 8403060395	50-322 T 50-322 T 50-322 T 50-322 T 50-206 J	RUBENSTEIN.L S RUBENSTEIN.L S RUBENSTEIN.L S RUBENSTEIN.L S	B211170249* B305110054* B30921009B* B309210116* B309260482*	50-400 E 50-289 P 50-400 E 50-400 E
REQUA, Q	8403010230	50-261 P	ROCKHOLD, H C	8403070395*	50-315 P	RUBENSTEIN, L 8 RUBENSTEIN, L 8 RUBIN, A RUBIN, S RUBIN, S RUBIN, S	8311110263#	50-400 E
REQUA, Q.	8403060005	50-261 P	ROCKHOLD, H, C	8403260335	50-416 P		8312120002#	50-400 E
REGH, D	8403060470	50-261 P	RODRIGUEZ, R J,	8403010388	50-312 P		8403200269#	50-482 A
RESH, D L	8403130236	PR	RODRIGUEZ, R J	8403020350	50-312 P		8310260186#	50-278 B
REVELEY, W. T	8403130129	50-322 Q	RODRIGUEZ, R J	8403060387	50-312 F		8310260186	50-278 S
REVELEY, W T REVELEY, W T REVER, L. A. REVER, L. A.	8403130129 8403210181* 8403210181* 8403080241* 8403190299*	50-322 0 50-322 0 50-322 0 50-322 0 50-483 0 50-373 0	RODRIQUEZ,R J RODRIQUEZ,R J RODRIQUEZ,R J RODRIQUEZ,R J	8403130112 8403130125 8403170275 8403200045 8403200184	50-312 8 50-312 P 50-312 0 50-312 8	RUBIN, S D RUBIN, S D RUFF, A B RUGH, C F RUITER, G H	8403230178 8403230181* 8403080384* 8403300317 8403130147	50-305 8 50-305 8 50-424 0 NUREO 50-305 R
REYNOLDS, J R	8403300030*	50-454 G	RODRIQUEZ,R J	8403230036	50-312 8	RULAND, W H RULAND, W H RULLMAN, B D RULLMAN, B D RUMMERFIELD, P	8403160284*	50-348 Q
REYNOLDS, J,	8403300057*	50-341 G	RODRIQUEZ,R J	8403260213	50-312 P		8403290103*	50-348 Q
REYNOLDS, J,	8403070027	50-275 P	ROGERS,A C	840316048	50-528 A		8403080113*	FOIA
REYNOLDS, J R	8403070128	50-275 G	ROGERS,L.	840327006#	FOIA		8403080113*	FOIA
REYNOLDS, J R	8403070128	50-275 G	ROGERS,L.	840327016#	FOIA		8403090178	PR
REANOTDB' 7 B BEANOTDB' 7 B BEANOTDB' 7 B BEANOTDB' 7 B	8403080118 8403080118 8403170011 8403170011 8403170016#	50-275 0 50-275 0 50-275 0 50-275 0 50-275 0	ROGERB, L ROGERB, L ROGERB, L, ROGERB, L, ROGERB, L	8403270051* 8403270054* 8403270058* 8403270061* 8403270073*	FOIA FOIA FOIA FOIA FOIA	RUMMERFIELD, P RUNKLE, J RUNKLE, J RUNKLE, J D RUPP, J.	8403070183* 8403200054 8403220223 8403170141* 8403080013	PR 50-400 0 50-400 0 50-400 0 50-272 6
REYNOLDB.J.R. REYNOLDB.J.R. REYNOLDB.J.R. REYNOLDB.J.R. REYNOLDB.J.R.	8403170016#	50-275 0	Rogers, P	8403070137	50-368 8	RUPP, J	840308024 <i>b</i>	50-272 8
	8403220106	50-275 0	Rogers, P	8403130024	50-368 8	RUPP, J	8403080252	50-272 8
	8403220106	50-275 0	Rogers, P	8403130324	50-368 8	RUPP, J L	8402100176	50-272 8
	8403220110#	50-275 0	Rogers, P	8403130347	50-368 8	RUPP, J L	8403130384	50-311 8
	8403220110#	50-275 0	Rogers, P	8403220020	50-368 6	RUPP, J L	8403220037	50-311 8
REYNOLDS, J. R REYNOLDS, J. R REYNOLDS, N. S REYNOLDS, N. S REYNOLDS, N. S.	8403260368 8403260368 8403120007 8403120007 8403140020	50-275 0 50-275 0 50-508 D 50-508 D 50-445 0	ROGERB, P ROGERB, P ROGGE, J. F ROGGE, J. F ROMRER, D.	8403270258 8403290127 8403020235 8403160039 8403200119*	50-388 8 50-388 8 50-302 8 50-386 8 50-483 0	RUPP, J L RUPP, J L RUPP, J L RUPP, J L RUPP, J L RUPP, J L	8403220151 8403270099 8403270244 8403280036 8403280047	50-311 S 50-311 S 50-272 S 50-220 J 50-220 J
REYNOLDS, N. S REYNOLDS, N. S REYNOLDS, N. S REYNOLDS, N. S REYNOLDS, N. S.	8403140020 8403150032 8403150032 8403270031 8403270031	50-445 0 50-445 0 50-445 0 50-445 0 50-445 0	ROLFE, R M. ROLFE, R. M ROLFE, R. M. ROLFE, R M ROLFE, R M	8403020143 8403020143 8403060105 8403060105 8403060107*	50-322 0 50-322 0 50-322 0	RUSBELL.L B RUSBELL.L B RUSBELL.L B RUSBELL.L G RUSBELL.L G	8403020300 8403060109 8403130039 8403130081 8403130098	50-317 F 50-318 S 50-318 S 50-318 B 50-317 B
REYNOLDB, B D REYNOLDB, B. D. REYTBLATT, Z RHODE, Q. K. RHODEB, M.	8403150034* 8403170110* 8403270280 8403070078 8403010313*	50-388 G 50-275 G MISC 50-410 B 40-8027	ROLFE,R M ROLFE,R.M ROMAN,T W ROMAN,T W ROMANO,F.	8403050107* 8403270074 8403130391* 8403130051 8403220234*	50-322 0 50-322 0 50-220 P 50-220 R 50-352 0	RUBBELL, L B RUBBELL, L B RUBBELL, L B RUBBELL, L B RUBBELL, L B	8403130252 8403130279 8403130275 8403130279 8403130356	50-317 8 50-317 8 50-317 8 50-317 8
RHODEB, R. K. RICE, T. R. RICHARD, A. W. RICHARDB, B. L. RICHARDB, B. A.	8403120029# 8403050029# 8403050124 8403160353# 8403060344#	50-275 Q 50-286 P 50-285 8 70-143 50-344 Q	ROMANO, F. R ROMANO, F. R ROMANO, F. R. ROMANO, F. R ROMANO, F. R	8403220226 8403220229* 8403270378 8403270375 8403270377*	50-352 0 50-352 0 50-352 0 50-352 0	RUSSELL.L B. RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B	8403130413 8403130426 8403130430 8403140228 8403300100	50-318 8 50-317 8 50-318 8 50-317 F 50-317 8
RICHLEY, E. A	8403060405	50-30 R	RONK, D.F.	8403270236	50-327 B	Rusbell, H	8309290474*	50-400 E
RIDEOUT, T B.	8403230200	NUREQ	ROOD, H	8403270370	50-361 P	Rutberg, J	8403140071	50-275 Q
RIDGWAY, K R	8403170076*	50-123 G	ROONEY, V.L	8403260093	TOPREP	Rutberg, J	8403140179	50-275 Q
RILEY, A.	8403010437*	CONTRACT	ROPBON, D.J	8402170107*	50-305 P	Rutberg, J	8403190100	50-275 Q
RILEY, J.	8403070033	50-413 Q	ROBA, F	8402160020*	MISC	Rutberg, J	8403270301	50-352 Q

## STADLA D. SHOLDOOD 20-44 P. SCHELLE P.	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOCRY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
1906 1907 1908 1909	YAN.JA YAN.JF YBAK.B.	64030803B5 6403230140# 64030100B9	50-54 P 50-528 D CONTRACT 50-254 P	BCHNELLID F BCHNELLID F BCHNELLID F	8403270079 8403270182 8403270187 8403270229	50-483 8 50-483 8 50-483 A	SCOTT, D, J SCOTT, J S SCOTT, R S	8403270089 8403080197 8301140490*	50-237 8 50-10 R 50-267 P
	e «Xaey B «Xaey B «Xaey	8403070171* 8403130070 8403130102	50-237 P 50-237 P 50-265 P	SCHROEDER.C.W SCHROEDER.C.W SCHROEDER.C.W	8403050063 8403140175 8403170001	50-373 F 50-373 F 50-249 Q	ecrabie, c m Seare, c. f Seare, c f	8403170261* 8403070273 8403070273	50-369 P 50-423 C 50-423 C
1900 1.5 1900	YBAK, B YBAK, B	8403130400 8403130410 8403190075	50-237 P 50-237 P 50-254 G	SCHROEDER.C W SCHROEDER.C W SCHROEDER.C W	8403210085 8403220123 8403230081*	50-373 K 50-373 F 50-373 G	SEARS, C. F SEARS, C F SEARS, C F	8403130027 8403130027 8403130027	50-213 P 50-213 P 50-213 P
## ACCOUNTS C. C. C. C. C. C. C. C	увак, В. Увак, В	8403220153 8403270130 8403270175	50-237 P 50-249 P 50-254 Q	BCHRDEDER.C W BCHULTZ.G R. BCHULTZ.G R	8403260225 8403140180* 8403140183*	50-373 G 50-373 F 50-373 F	BEARS, C. F. BEARS, C. F. BEARS, C. F.	8403140014 8403160292 8403160292	50-213 P 50-423 E 50-423 E
ALAHO, B. BAD200411 S0-129 6 SCHMACHER, R. C. 8003000203 50-450 0 SCHMACHER, R. C. 800300020 50-450 0 SCHMACHER, R. C. 8003000203 50-450 0 SCHMACHER, R. C. 8003000203 50-450 0 SCHMACHER, R. C. 800300020 50-450 0 SCHMACHER, R. C. 8003	AENGER, E.L. AGER, D.A. ALAH, B.	8403080217* 8403060340 8305060337	FDIA 50-335 F 50-324 B	BCHULTZ, H H BCHULZ, R D BCHUMACHER, M C	610224 0066* 6403080186* 6403130117*	FOIA 50-461 G 40-2061	BEARS, C. F. BEARS, C. F BEARS, C. F	8403210161 8403220148 8403220148	50-423 8 50-423 F 50-423 F
ALVARDA, L. B. 0403103036	alah, B Talomon, B. N Altzman, J.	8403250411 8403230190 8403280221	50-325 B NUREQ 50-320 P	SCHUMACHER, M. C. SCHUMACHER, M. C. SCHUSTER, M. D.	8403300033* 8403300040* 8403080152*	50-456 @ 50-282 @ 50-528 @	SEARS, C. F. SEARS, C. F SEARS, C. F	8403230029 8403230029 8403230033	50-245 F 50-245 F 50-423 G
AMANTAR, P. R. B4031001014 B103200213 S0-407 F B104 B103200213 S0-407 F B104 B103200213 S0-407 F B104 B103200213 S0-407 F B104 B103200213 S0-407	ALYARDS, L. E ALYERS, E. M ALYERS, E. M.	8403130356 8403060377 8403090151	50-317 8 50-280 F 50-280 F	BCHUSTER, M D BCHUTZ, D F BCHUYLER, J, D,	8403270264 8403140144 8403070075	50-275 F PR 50-275 P	BEARS, C. F. BEARS, C. F. BEARS, C. F.	8403260143 8403260143 8403260146	50-213 F 50-213 F 50-213 F
AMDQUIST, 0 9403140148 50-407 F 8CMVILER.) 0 9403120129 70-272 F 8EARS, C.F. 8403200164 50-413 0 AMDQUIST, 0 1 8403200291 50-72 F 8CMVILER.) 0 840310011 50-277 F 8EEMA, J. L. 840370027 F AMDQUIST, 0 1 8403200291 50-346 R 8CMVILER.) 0 840310011 50-277 F 8EEMAL, J. L. 840370027 F 70-271 F ARSDUR, 8. 440320021 50-344 R 8CMVILER.) 0 8403100187 50-272 G 8EEMAL, J. L. 840320018 F 70-74 M AMDUST, 0 1 840320021 50-344 R 8CMVILER.) 0 8403100187 50-273 G 8EEMAL, J. L. 840320018 F 70-74 M AMDUST, 0 1 840320018 60-344 R 8CMVILER.) 0 8403100187 50-273 G 8EEMAL, J. L. 840320018 F 70-74 M AMDUST, 0 1 840320018 60-342 M AMDUST, 0 1 840320018 60-344 R 8CMVILER.) 0 8403200218 50-273 F 8EEMAL, J. L. 840320018 60-842 AMDUST, 0 1 840320018 60-842 M AMDUST, 0 1 840320018 60-842 M AMDUST, 0 840320018 M AMDUST, 0 840320018	AMANTA, P. K TAMPLE, M. TAMHORTH, R. B	8403010041* 8403140231 8003270142*	FDIA 50-369 F 50-397 D	BCHUYLER, J. D. BCHUYLER, J. D. BCHUYLER, J. D	8403070288* 8403070355 8403080413	50-275 P 50-275 P 50-275 P	BEARS, C. F. BEARS, C. F. BEARS, C. F	8403260149 8403260195 8403260195	50-423 E 50-245 F 50-245 F
ARBOUR, B.	ANDQUIST. 0 M	8403200281 8403200293*	50-407 F 50-72 F 50-72 F	SCHUYLER, J. D. SCHUYLER, J. D.	8403120129 8403140153 8403150011	50-275 P PR 50-275 P	BEARB, C. F. BEARB, C. F. BEDLACK, M. B	8403270068 8403300166# 8403090277#	50-213 F 50-213 Q 50-331 P
AVIDIDATE BA013201300	ARSOUR, B. ARSOUR, B. AUTER, D. M	8403070251 8403300184 8403050120	50-346 R 50-346 R GA999	SCHUYLER, J O SCHUYLER, J O SCHUYLER, J O	8403150082 8403150147 8403200218	50-275 G 50-275 E 50-275 P	BEIGERMAN, V. K. BEIKEN, S. J. BEIKEN, S. J.	8403010170 8403010213 8403290128	50-247 H 50-482 Q 50-482 Q
CHEERER, A. E. 8403270107 50-470 E. 8CHYLER, J. D. 8403280011 50-275 F. 8EYRIT, K. V. B100403177 50-285 D-285 F. BHA. H. T. 8403300281 N/REC D-1851 D	IAVIGNAC, N	8401120180* 8403080218* 8403300216	40-3453 FOIA 50-447 A	SCHUYLER, J. O BCHUYLER, J O BCHUYLER, J O	8403230171 8403260176 8403270004	50-275 ¢ 50-275 P 50-133 ¢	SELLS, D. E SELLS, D. E. SEMMLER, R. W.	8003250477# 8403060077 8403270054#	50-397 D 50-335 P GA999
CHIEFERLING H 8403190134* 50-275	CHEIDT, D. J IGHEIDT, D. J ICHEINERT, R. L IGHERER, A. E IGHERER, A. E,	8403280358 8403060285 8403010276	50-322 G 50-263 F 50-470 E	SCHUYLER, J. O BCHUYLER, J. O. BCHUYLER, J. O	8403270205 8403280001 8403280114	50-133 F 50-275 F 50-275 F	SEHELL, H M SEYFRIT, K V SHA, W. T.	8403230130* 8310060317* 8403300261	CONTRACT 50-285 Q NUREQ
CHMIDT, H. C	CHERER, A. E ICHIERLING, H ICHIFFMACHER, W ICHIFFMACHER, W ICHIFFMACHER, W	8403170134* 8403070165* 8403070170*	50-275 Q 50-322 T 50-322 T	SCHUYLER, J. P. BCHNAN, C. A BCHNARTZ, A. R	8403150004 8403190374 8403010132*	50-275 G 50-206 B 50-498 G	SHADE, J. W. SHAFER, J. C SHAFER, J. M.	8403230177 8403120117 8403300132*	NURES GA999 50-498 A
CHNELL, D. F. B403120121 50-483 A BCHMENCER, A B403120034 50-332 A BHAFER, M. D. B403130012 50-264 0 BCHMENCER, A B403120035 50-332 A BHAFER, M. D. B403130012 50-264 0 BCHMENCER, A B403120101 50-483 B B403120104 50-373 B B403120104 50-483 B B403120104 50-373 B B403120034 50-373 B B403120035 50-383 B B403120104 50-373 B B403120035 50-483 B B403120104 50-373 B B403120104 50-373 B B403120035 50-483 B B403120035 50-483 B B403120035 50-337 B B403120035 50-483 B B403120035 50-373 B B403120035 50-483 B B403120035 50-373 B B403120035 50-335 B B403120035 50-483 B B403120035 50-337 B B403120035 50-337 B B403120035 50-483 B B403120035 50-337 B B403120035 50-337 B B403120035 50-483 B B403120035 50-337 B B403120035 50-337 B B403120035 50-483 B B403120035 50-337 B B403120035 50-337 B B403120035 50-483 B B403120035 50-337 B B403120035 50-337 B B403120035 50-483 B B403120035 50-337 B B403120035 50-337 B B403120035 50-483 B B403120035 50-337 B B4031	CHMIDY, H C, CHMIDT, H C CHMIDT, W, J CHMITT, H, W CHMITT, R, C	8403150103 8403190139 8403300312#	50-445 E GA999 CONTRACT	BCHWENCER, A. BCHWENCER, A. BCHWENCER, A	8403010143* 8403020207 8403050034*	50-416 P 50-373 F 50-286 D	SHAFER, W. SHAFER, W. SHAFER, W.	8403130235 8403130423 8403190013	50-254 8 50-263 8 50-374 8
CHNELL, D. F. B403120182 50-483 A SCHMENCER, A. B403280234 50-410 E SHAFER, M. D. B403190068 50-373 Q CHNELL, D. F. B403140032 50-483 A SCHMENCER, A. B403300244 50-373 F SHAFER, M. D. B403190072* 50-373 Q CHNELL, D. F. B403190034 50-483 B SCOTT, A. E B403080135 50-261 R SHAFER, M. D. B403190084 50-373 Q SCHNELL, D. F. B403190269 50-483 A SCOTT, A. E B403080258 50-261 R SHAFER, M. D. B403190379 50-305 Q SCHNELL, D. F. B403200285 50-483 B SCOTT, D. J. B4030600258 50-10 R SHAFER, M. D. B403190379 50-305 Q SCHNELL, D. F. B403200285* 50-483 Q SCOTT, D. J. B40310015 50-237 R SHAFFNER, J. A. B403160077 27-39 SCHNELL, D. F. B40320121 50-483 A SCOTT, D. J. B403120076 50-237 R SHAFFNER, J. A. B403160077 27-39 SCHNELL, D. F. B40320113 50-483 B SCOTT, D. J. B40320096 50-237 B SHAFFNER, J. A. B403160074 27-48 SCHNELL, D. F. B40320113 50-483 B SCOTT, D. J. B403260223 50-237 B SHAFFNER, J. A. B403160074 27-48 SCHNELL, D. F. B40320113 50-483 B SCOTT, D. J. B403260223 50-237 B SHAFFNER, J. A. B403160074 27-48 SCHNELL, D. F. B40320113 50-483 B SCOTT, D. J. B403260223 50-237 B SHAFFNER, J. A. B403160074 27-48 SCHNELL, D. F. B40320113 50-483 B SCOTT, D. J. B403260223 50-237 B SHAFFNER, J. A. B403202035 27-48 SCHNELL, D. F. B40320113 50-483 B SCOTT, D. J. B403260223 50-237 B SHAFFNER, J. A. B403202035 27-48 SCHNELL, D. F. B40320113 50-483 B SCOTT, D. J. B403260223 50-237 B SHAFFNER, J. A. B40320035 27-48 SCHNELL, D. F. B40320113 50-483 B SCOTT, D. J. B403260223 50-237 B SHAFFNER, J. A. B40320035 27-48 SCHNELL, D. F. B40320113 50-483 B SCOTT, D. J. B403260223 50-237 B SHAFFNER, J. A. B4032602035 27-48 SCHNELL, D. F. B40320113 50-483 B SCOTT, D. J. B403260223 50-237 B SHAFFNER, J. A. B4032602035 27-48 SCHNELL, D. F. B40320113 50-483 B SCOTT, D. J. B403260223 50-237 B SHAFFNER, J. A. B4032602035 27-48 SCHNELL, D. F. B40320113 50-483 B SCOTT, D. J. B403260223 50-237 B SHAFFNER, J. A. B4032602035 27-48 SCHNELL, D. F. B403260223 50-237 B SHAFFNER, J. A. B4032602035 27-48 SCHNELL, D. F. B403260235 27-48 SCHNELL, D. F. B403260235 27-48 SCH	ICHMITT.R.C BCHNEBELEN.A. BCHNELL.D.F BCHNELL.D.F BCHNELL.D.F.	8403280235* 8403050016 8403070283	50-482 G 50-483 K 50-483 F	SCHWENCER, A SCHWENGER, A SCHWENCER, A	840314029& 8403150262 8403220301	50-387 F 50-352 A 50-410 E	SHAFER, W. D. SHAFER, W. D. SHAFER, W. D.	8403120141 8403130002 8403130011*	50-263 0 50-266 0 50-266 0
CHNELL, D. F. 8403200283* 50-483 0 9CDTT. D.J. 8403130015 50-237 R SHAFFNER, J.A. 8403140077 27-39 CCHNELL, D. F 8403210121 50-483 A 9CDTT. D.J. 8403230074 50-237 B SHAFFNER, J.A. 8403140074 27-48 CCHNELL, D. F. 840320113 50-483 B BCDTT. D. J. 8403240223 50-237 B SHAFFNER, J.A. 8403220235 27-48	CHNELL, D. F ICHNELL D. F ICHNELL D. F ICHNELL D. F ICHNELL D. F	8403120182 8403160323 8403170034	50-483 A 50-483 A 50-483 B	SCHWENCER, A. SCHWENCER, A. SCOTT, A. E	8403280236 8403300244 8403080135	50-410 E 50-373 F 50-261 R	SHAFER, W. D. SHAFER, W. D. SHAFER, W. D	8403190068 8403190072* 8403190084	50-373 Q 50-373 Q 50-373 Q
	ICHNELL, D. F. ICHNELL, D. F ICHNELL, D. F ICHNELL, D. F. ICHNELL, D. F.	8403200285* 8403210121 8403230115	50~483 G 50~483 A 50~483 S	SCOTT, D. J. BCOTT, D. J. BCOTT, D. J.	8403130015 8403230076 8403260223	50-237 R 50-237 9 50-237 8	SHAFFNER, J. A. SHAFFNER, J. A. SHAFFNER, J. A.	8403160077 8403160094 8403220235	27-39 27-48 27-48

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
SHAH, V L SHAHABIAN, R L SHANAHAN, J A, SHANBAKY, M SHANBAKY, M	8403300285 8403010303* 8403160076* 8403130208 8403130456	NUREO 50-388 E 50-412 A 50-217 B 50-309 B	SHOLLY, B C SHOLLY, B C SHOLLY, B C SHOLLY, B C SHOLLY, B C	8403010010 8403010021 8403050017 8403050058 8403080003	50-289 P FDIA 50-286 P FDIA FDIA	SMITH.P SMITH.P A SMITH.P A SMITH.P. A SMITH.P. A	8403260341* 8403270270* 8403270369* 8403280052* 8403300312*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
EHANBAKY, M, EHANBAKY, M M EHANCEY, R E SHANKS, R B	8403150017* 8403070306* 8403290210* 8403130028 8403080383*	50-219 Q 50-387 Q 50-272 Q 50-289 H FOIA	SHON, F J SHON, F J SHON, F J SHOPENN, N M SHORTRIDGE, E W	8403060111 8403080110 8403090132 8403130401 8403070266	50-50B	SMITH, R. D SMITH, R. D SMITH, R. D SMITH, R. D SMITH, R. D	8403070367 8403190414 8403200328* 8403200333 8403200389	40-3453 40-4492 40-4492 40-1341 40-8681
BHANNDN, J B SHANNDN, J B SHANNDN, T E SHARPE, C SHARPE, C	8402140327* 8403260142* 8403270048* 8403260005 8403260375	40-8102 40-8102 50-352 T 50-275 G 50-275 G	SHULMAN, M N SHUBTERMAN, A SHUBTERMAN, A SHUBTERMAN, A	8403270115 8403070167* 8403050081* 8403120017* 6403160222*	GA797 CONTRACT 50-458 A 50-275 G 50-370 G	SMITH, R D SMITH, R D SMITH, R H SMITH, R H SMITH, W F	8403230156 8403280127 8403080087* 8403210105* 8403050186*	40-8745 40-8768 FDIA 50-334 C 50-482 C
SHARPE,C SHAUB,T SHEA.J,J, SHEA.JJ SHEA,JJ,	8403260378 8403020399* 8403090240 8403190045 8403190383	50-275 G 50-293 G 50-220 P 50-245 G 50-245 P	SIEBER, J D SIEGEL, A I SIEGEL, B SIEGEL, B L BILBERG, J E	8403200233 8403300325 8403090240 8403140340 8403020104	50-334 F NUREQ 50-220 P 50-219 P 50-440 Q	SMITH.W F SMITH.W G SMITH.W G SMITH.W G SMITH.W G	8403130453* 8403020044 8403130259 8403200217 8403200203	30-445 (50-315 n 50-315 n 50-316 50-315
SHEA, K H BHEALY, H Q SHEARIN, R V, SHEARIN, R V, SHEARIN, R, V	9403260662 8403080339* 8403060240 8403130164* 8403270011	50-331 J WABTE MOT 50-413 9 50-400 9 50-413 9	SILBERO, J E SILBERO, J E SILBERO, J F SILBERO, J E SILBERO, J, E	8403020106 8403190035 8403190035 8403260325 8403260325	50-440 G 50-482 Q 50-482 Q 50-482 Q 50-482 Q	SMITH, H 0 SMITH, W 0 SMITH, W M SMOLEN, H SMOLEN, H	8403300155 8403300157 8403130121 8403010271 8403010275*	50-316 m 50-315 m 50-315 m 50-352 m 50-352 m
SHEDLOSKY, T SHELLEY, W. J SHELLEY, W. J SHEPHERD, R	8403220140* 8403150332 8403280028 8403280103* 8403080146*	50-322 G 40-8586 40-2061 40-8586 FDIA	Bilberstein, e Bilver, H. Bimdons, T Binclair, J B Binclair, J B	8403290259 8403300303 8403130310 8403120003 8403130481	PRM 50-289 F I&E 50-271 P 50-271 R	EMOLEN, H SMYTH, C W SNELL, W C. SNIEZEK, J.	8403040129 8403200048 8403270180* 8403300051* 8403010222*	50-352 § 50-289 R 50-461 G 50-315 A
SHEPPARD: J J SHEPPARD: J J SHEPPARD: J J SHEPPARD: J J SHEPPARD: J, J.	8403070106* 8403070106* 8403070108* 8403070108* 8403260024	FOIA FOIA FOIA FOIA TOPREP	SINCLAIR. J B BINCLAIR. J B BINCLAIR. J R BINGER, B. SINGER, B.	8403200274 8403230140 8403280240* 8403020095* 8403020107*	50-271 G 50-271 R 50-482 G FDIA FDIA	BNIEZEK, J H BNIEZEK, J H BNOW, B A BNOW, B, A	8103250553* 8107180034* 8403170244 8403020202 8403300081	FOIA FOIA REVIEW GRP 50-244 R 50-244 R
SHEPPARD, J J SHERMAN, C I SHERMAN, C I SHERR, T S SHERR, T S	9403260024 9403060017* 8403060172* 8403280205 8403270328	TOPREP 50-204 Q 50-113 G 50-2 F 50-62 F	Singer, B. Binger, B Binger, B Singer, B. Binger, B.	8403020124* 8403020127* 8403020172* 8403020180* 8403020193*	FOIA FOIA FOIA FOIA FOIA	SNOW, RA SNOW, RA SNOW, RA SNYDER, BJ SNYDER, BJ	8403060266* 8403060270* 8403060278* 840313031 I 8403230240	50-322 T 50-322 T 50-320 P 50-320 P
SHERWDOD, O. O SHERWDOD, O. O SHERWOOD, O. O SHEWMAKER, R. E. SHEWMAKER, R. E.	8403130282 8403200271 8403270255 8203100419* 8401230660*	PR 50-245 P PR 50-440 8 50-329 8	BINGER.B BINGER.B BINIBI.J M BINIBI.J.M.	8403020194# 8403020199# 8403140029 8403140031 8403140033	FDIA FDIA 50-293 J 50-245 J 30-27 J	SNYDER, B J SOKOLOWSKI, W SOMERVILLE, K G SOMMERVILLE, K G SOMMERS, P	8403280243 8403010045* 8403170411 8403170412 8403170055	50-320 F CONTRACT 40-8783 40-8783 NUREG
BHIFFER, J. D. BHIFFER, J. D BHIFFER, J. D BHIMA, B BHIMA, S	8403120029* 8403150025 8403220066 8403010465 8403010468*	50-275 Q 50-275 B 50-275 B XPORTLIC XPORTLIC	SINKIN'T SINKE'G' 7. SINISI' 1 W SINISI' 1 W	8403140078 8403140092 8403140114 8403150272 8403140152	50-244 J 50-213 J 50-213 J 40-8784 50-498 @	Sod, P Sorensen, C. C Sorensen, G. C Sorensen, G. C Sorensen, G. C	8403070115 8403020330 8403090118 8403090121 8403090236	NUREG 50-397 P 50-508 D 50-397 E 50-397 P
SHIMA, B SHIMA, B SHIMA, B, SHIMA, B, SHIMA, B	8403010470 8403010473* 8403010512 8403010517* 8403050327*	XPDRTLIC XPDRTLIC XPDRTLIC XPDRTLIC XPDRTLIC	SINKIN, L SISK, K D SISK, K D. SJOBLOM, Q L SKAQOS, R L	8403270025 8403290179 8403290179 8403290179 8403300132#	50-498 0 50-322 0 50-322 0 PR 50-498 A	SDRENSEN, O C SORENSEN, O C SORENSEN, O C SORENSEN, O C SORENSEN, O C	8403120199 020018048 03130227 03130318 03130388	50-50B A PR 50-397 V 50-397 P 50-508 F
Shima, B. Shima, B. Shima, B. Shima, B. Shima, B	8403050333# 8403050373# 8403050376# 8403070425* 8403070426#	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	SKIERKOWSKI, P SKOCEN, F B SKOV, D D SKOV, D, D BLAGOIE, E L	8403130327 8403080220* 8403200061 8403200107 8304060577*	PR 50-316 P 70-553 40-8107 50-397 A	Sorenben, G. C Borenben, G. C Borenben, G. C Borenben, G. C Borenben, G. C	8403130480 8403200236 8403200261 8403220061 8403260006	50-397 P 50-397 P 50-397 P 50-397 P 50-397 F
SHIPLEY, L E SHIPMAN, W B SHIRAKAWA, T, SHIRAKAWA, T, SHIRAKAWA, T	8403120010* 8403010163* 8403010464 8403010471 8403010487	50-275 0 50-348 P XPORTLIC XPORTLIC XPORTLIC	SLOBODIEN, M SLAWINSKI, W J SLIGER, E K SLOBODIEN, M	8403190313* 8403220140* 8403300033* 8403060235 8403080133*	50-341 Q 50-305 Q 50-456 Q 50-259 F FOIA	SORENSEN, O C SORENSEN, O C SORENSEN, O C SORENSEN, O C SORENSEN, O C	8403260165 8403260221 8403260292 8403270118 8403270141	50-397 P 50-509 A 50-397 P 50-397 Q 50-397 F
BHIRAKAWA, T. BHIRAKAWA, T BHIRAKAWA, T BHIGLER, E, SHIBLER, E	8403220197 8403260041 8403260390 8403060365* 8403060369*	XPORTLIC XPORTLIC XPORTLIC GA999 GA999	SLOBODIEN, M J SLOBODIEN, M J SLOBODIEN, M J SMITH, C	8403080000* 8403080079* 8403080102* 8403080109* 8403160319*	FOIÁ FOIA FOIA FOIA 50-413 G	BORENBEN, G C BORENBEN, G C BORENBEN, G C BORENBON, J, BORENBON, J H	8403270207 8403270220 8403270242 8403130278* 8403010244	50-397 J 50-397 E PR 50-282 R 50-322 T
SHISLER, E. SHISLER, E. SHISLER, E. SHOEMAKER, C. J. SHOEMAKER, C. J.	8403040372* 8403040374* 8403040379* 8403070050 8403070188	GA999 GA999 GA999 50-413 G 50-275 G	SMITH, D E, SMITH, D L SMITH, D, L, SMITH, D L, SMITH, G C	8403190424 8403090085 8403130181 8403190371 8403070259*	40-8481 50-257 8 50-259 8 50-259 8 70-1100	BORLIE, G BORRELL, E, C BORRELL, E C BORRELL, E C. BORRELL, E C.	8403140228 8403090282 8403130004 8403130165 8403260150	50-397 D 50-321 F 50-321 F 50-321 F 50-321 F
SHOEMAKER, C J SHOEMAKER, C. J, SHOEMAKER, C J SHOEMAKER, C J, SHOEMAKER, C, J	8403090059 8403090102 8403140004 8403140041 8403190129	50-322 0 50-454 0 50-322 0 50-454 0 50-443 0	Smith, Q. C Smith, J. C. Smith, J. F. Smith, J. H. Smith, J. J.	8403280025* 8403120091 8403080076* 8403060126* 8403130308*	50-416 P 50-331 B FOIA 50-244 P 70-2199	Borrell, E. C. Borrell, E. C Bowby, F BPECK, B. W BPECK, S. W	8403300143 8403300339 8403230076* 8403050148 8403040084	50-321 F 50-321 F CONTRACT 50-204 F 50-250 F
SHOEMAKER, C. J. SHOEMAKER, C. J. SHOEMAKER, C. J. SHOEMAKER, C. J. SHOEMAKER, C. J.	8403210159 8403230278 8403260007 8403280359 8403300278	50-275	SMITH, J.L. SMITH, J.T. SMITH, P. SMITH, P. SMITH, P.	8403290160 8403220302* 8403070383* 8403070414* 8403120226*	50-922 F 50-322 T 27-39 CONTRACT CONTRACT	SPECK, S. W. SPECK, S. W. SPECK, S. W. SPECK, S. W. SPECTER, A.	8403130155 8403130165 8403190131 8403190363 8403200200*	50-254 F 50-295 F 50-322 Q 50-322 F 50-289 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEOGRY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
ECTER, A	8403200211*	50-289 0	STAROSTECKI, R	8403190231	70-371	STEWART, W L	8403300055	50-338 R
EIS, T	8010070240*	50-460 A	STAROSTECKI, R	8403190267	50-27 P	STEWART, W L	8403300060	50-280 R
EIS, T P	8311140170*	ACRS	STAROSTECKI, R	8403220014	50-317 P	STICKLEY, T H	8402280725*	50-267 P
EIS, T P	8312120006*	4CRS	STAROSTECKI, R	8403220033	50-387 Q	STIETZEL, J F	8403130259	50-315 R
EIS, T P	8312230256*	50-275 P	STAROSTECKI, R	8403220079	50-333 Q	STILE, V R	8403060266*	50-322 T
EIS, T. P	8402240387*	M18C	STAROSTECKI, R	8403220085	50-354	STILE.V R	8403060270*	50-322 T
EIS, T. P	8403020424	M18C	STAROSTECKI, R	8403220095		STILE.V R	8403060278*	50-322 T
ENCER, D A	8403120054	50-373 S	STAROSTECKI, R	8403220105		STILL.J	8403130316	27-47
ESSARD, R L	8403050279*	FOIA	STAROSTECKI, R	8403220131		STILWELL,T C	8403150045*	50-237 P
ESSARD, R L	8403050151	50-266 O	STAROSTECKI, R	8403220143		STITES,S J	8403140060*	50-461 9
ESSARD, R L	8403040162*	50-266 0	STAROSTECKI, R.	8403260166	50-334 Q	STODDART,P G	8403070013*	50-395 0
ESSARD, R L	8403120008	50-456 P	STAROSTECKI, R.	8403260233	50-3 S	STODDART,P G	8403160244*	50-259 0
'ESSARD, R L.	8403120021	50-315 P	STAROSTECKI, R.	8403260313	50-293 Q	STODDART,P.G	8403160300*	50-261 0
ESSARD, R L	8403120025	50-373 F	STAROSTECKI, R.	8403270135	50-272 Q	STODDART,P G.	8403290290*	50-369 0
'ESSARD, R L	8403120045	50-266 P	STAROSTECKI, R.	8403270140	50-387 Q	STOHR,J P	8403070146	70-27
ESSARD, R L	8403120046	50-483 F	STAROSTECKI, R	B403270200	50-412 G	9TDHR・J P.	8403070324	70-27
ESSARD, R L	8403120048	50-305 F	STAROSTECKI, R	B403300137	70-607	9TDHR・J P.	8403160043	70-1151
ESSARD, R L	8403120049	50-341 F	STAROSTECKI, R.	B403300165	50-223 G	9TOHR・J P	8403160138	70-143
ESSARD, R L	8403120051	50-295 F	STAROSTECKI, R.	B403300171	50-272 G	9TOHR・J P	8403160173*	70-143
ESSARD, R L	8403120053	50-10 F	STAROSTECKI, R	B403300187	50-423 A	8TOHR・J, P	8403160258	70-143
ESSARD, R L ESSARD, R L ESSARD, R L ESSARD, R L ESSARD, R L	8403120057 8403120058 8403120060 8403120074 8403120077	50-331 F 50-546 F 50-263 F 50-409 F 50-461 F	STAROSTECKI, R STABEK, S STATTON, C. D STAUS, W P STAUSER, R H	B403300189 B403120079* B403130284 B403150205 B403200157*	50-244 G 50-237 G GA999 40-8781 GA999	810HK・7 b 810HK・7 b 810HK・7 b 810HK・7 b	8403160286 8403160337 8403160340 8403160369 8403160375	70-27 70-143 70-1113 TOPREP 70-1113
ESSARDJR L	8403120093	50-358 F	STEARNS, C F	BA03300167	70-1717	STOHR, J. P	8403210151	70-143
EBSARDJR L	8403120097	50-155 F	STEFAND, J. J	BA03010246	50-440 A	STOHR, J. P.	8403260179	70-27
EBSARDJR L	8403120100	50-346 F	STEFAND, J J	BA03050350	50-440 H	STOHR, J. P.	8403290285	70-143
ESSARDJR L	8403120103	50-327 F	STEIN, S S	BA03020400	FOIA	STOHR, J. P.	8403300011	70-27
ESSARDJR L	8403120104	50-282 F	STELLD, V	B001140316*	50-460 A	STOHR, J. P.	8403300041	70-27
ESBARD,R L ESBARD,R L ESBARD,R. L ESBARD,R L ESBARD,R L	8403120107 8403120112 8403120115 8403120147 8403130348	50-454 F 50-440 F 50-255 F 50-254 F 50-373 6	STELLO, V STELLO, V STELLO, V	8304260013* 8308150440* 8312070358 8403060323 8403170003	50-267 P FOIA REVIEW GRP REVIEW GRP REVIEW GRP	STOIBER, C, R STORES, C STOLZ, J F, STOLZ, J F, STOLZ, J F,	8403290404 8403190021* 8403010124* 8403010377* 8403010474	XPORTLIC 50-275 9 50-321 F 50-312 F 50-312 F
ESSARD.R L ESSARD.R L ESSARD.R L ESSARO.R L ITZBERG.D B	8403190170 8403200295 8403200297* 8403230075 8403230109*	50-461 G 50-454 G 50-454 G 50-373 G 40-1341	5TELLO, V 8TELLO, V 8TELLO, V 5TELLO, V	8403190005 8403190008 8403190009 8403190012 8403190019	REVIEW GRP REVIEW GRP REVIEW GRP REVIEW GRP	STOLZ, J F. STOLZ, J F STOLZ, J F. STOLZ, J F. STOLZ, J F.	8403020169 8403050037* 8403060440* 8403070137 8403070141*	50-289 P 50-286 P 50-321 P 50-277 P 50-277 P
ROAT, E F ENAWSKI, D ENIAWSKI, D ENIAWSKI, D ENIAWSKI, D J	8403270048* 8403200284 8403130310 8403300045 8403080202*	50-352 T I&E I&E I&E FOIA	BTELLO, V STELLO, V STELLO, V STELLO	8403170027 8403170031 8403170037 8403170081 8403170103	REVIEW GRP REVIEW GRP REVIEW GRP REVIEW GRP REVIEW GRP	STOLZ, J F STOLZ, J F STOLZ, J, F STOLZ, J F STOLZ, J F	8403070357 8403120310 8403120337 8403120354 8403150243	50-321 P 50-289 P 50-312 F 50-302 F 50-346 F
ENIAWSKI, D J ENSGON, B. A INIVASAN, M INIVASAN, M O LAURENT, N	8403080215* 8403130257 8312140429* 8403070114 8403020292	FOIA 50-315 R 50-400 E NUREQ 50-29 R	STELLO, V STELLO, V STELLO, V STELLO, V	8403170146 8403170176 8403170251 8403170256* 8403170260	REVIEW GRP REVIEW GRP REVIEW GRP REVIEW GRP	STOLZ, J F STOLZ, J. F. STOLZ, J F STOLZ, J F STOLZ, J F	8403150263 8403150328 8403150335* 8403220107 8403230238	50-344 P 50-249 P 50-249 P 50-289 P 50-313 F
LAURENT, N N	8403070175	50-29 B	STELLO.V.	8403190372	REVIEW GRP	STOLZ, J. F.	8403260045	50-321 P
LAURENT, N N	8403200215	50-29 B	STEPTOE.PP	8403020134	50-295 G	STOLZ, J. F.	8403260046*	50-321 P
NEHR, J P	8401120225	HASTE MOT	STEPTOE.P.P	8403020134	50-295 G	STOLZ, J. F.	6403260261	50-321 F
AHL, D	8403300294	NUREO	STEPTOE.PP	8403020140	50-295 G	STOLZ, J. F.	8403270315	50-289 F
AMIRIS, D	8403140119	50-329 0	STEPTOE.PP	8403020140	50-295 G	STOUT, D. M	8403150319	40-8829
AMIRIS. B	8403200139	50-329 0	BTENART, J.P.	8403040029*	50-20A	STOUT, R. B.	8403080210#	50-316 P
'NLEY, L.	8403270048*	50-352 T	BTENART, M.	8403200249*		STOUT, R. B.	8403150104#	50-316 P
ANSBURY, P S	8403140188*	50-352 0	GTENART, H. L.	8401130314		STOUT, R. B	8403200101#	50-316 P
ARLING, J	8403280009	50-416 P	BTENART, N. L.	8403020001		BTRACK, R. A	8403270198	50-54 R
AROSTECKI	8403300180	50-311 0	BTENART, N. L.	8403020042		STREET, L. L.	8403010454	XPORTLIC
AROSTECKI, R	8403010020*	50-289 P	STEHART, H L	8403020053	50-280 R	STREET, L. L	8403010456*	XPORTLIC
AROSTECKI, R	8403010310	50-277 G	STEWART, W L	8403020122	50-338 R	STREETER, J F,	8403050168	50-373 G
AROSTECKI, R	8403010381	50-322 G	STEWART, H. L	8403020195	50-280 P	STREETER, J F	8403080108*	FDIA
AROSTECKI, R	8403010397	50-213 G	STEWART, H L	8403080071	50-337 P	STREETER, J F	8403080176	50-461 G
AROSTECKI, R	8403020282	50-443 G	STEWART, H L	84030800091	50-280 F	STREETER, J F	8403080251	50-483 G
AROSTECKI, R	8403020298	50-54 0	STEWART, W. L	8403080254	50-280 F	STREETER, J.F. STREETER, J.F. STREETER, J.F. STREETER, J.F. STREETER, J.F.	8403080256*	50~483 Q
AROSTECKI, R	8403020347*	50-317 0	STEWART, W. L	8403070242	50-280 F		8403130351	50~305 V
AROSTECKI, R	8403020348	50-352 0	STEWART, W. L	8403130278	50-338 P		8403190290	50~373 Q
AROSTECKI, R	8403070282	50-289 0	STEWART, W. L	8403160154	50-280 Q		8403190293*	50~373 Q
AROSTECKI, R	8403070303	50-412 0	STEWART, W. L.	8403170052	50-280 F		8403200279	50~483 Q
AROSTECKI, R	8403070312	50-333	STEWART, W. L.	8403170201	50-337 P	STREETER, J. F	8403300017	50-454 0
AROSTECKI, R	8403070314		STEWART, W. L.	8403170263	50-280 F	STREETER, J. F	8403300023*	50-454 0
AROSTECKI, R	8403070330		STEWART, W. L.	8403170377	50-339 P	STREETER, J. F	8403300053	50-341 0
AROSTECKI, R	8403070342		STEWART, W. L.	8403200116	50-280 F	STRUCKMEYER, R,	8403160248*	50-352 0
AROSTECKI, R	8403120170		STEWART, W. L.	8403220028	50-338 P	STRUMWASSER, M	8403060260	50-275 0
Ardstecki.r Ardstecki.r Ardstecki.r Ardstecki.r Ardstecki.r	8403130006 8403130267 8403130353 8403130472 8403150053	50-220 Q 50-217 Q 50-354 Q 70-1100 50-387 Q	STEWART, W. L STEWART, W. L STEWART, W. L STEWART, W. L STEWART, W. L.	8403220077 8403240105 8403270021 8403270208 8403270248	50-338 P 50-260 P 50-260 G 50-338 P 50-339 P	SUBUDHI, M. SUBUDHI, M. SUGARMAN, R. J. SUGARMAN, R. J. SUMMERB, R. J.	8403260022* 8403260061* 8403130411 8403130411	50-454 A 50-454 A 50-352 G 50-352 G 50-272 G
ROSTECKI.R	9403150054	50-277 0	STEWART, W. L	8403280125	50-280 F	BUND, H J. BUNSER, J J. BUTTON, J. W. BUTTON, J. W. BUTTON, J. W. BYENSBON, B A.	8403070318*	50-325 Q
ROSTECKI.R	8403150067	50-273 0	STEWART, W. L	8403290157	50-280 G		8403070063	50-220 F
ROSTECKI.R	8403150076	50-410 0	STEWART, W. L	8403290260*	50-338 G		8403130042*	0A777
ROSTECKI.R	8403150105	50-307 P	STEWART, W. L	8403300005	50-338 P		8403130432*	0A777
ROSTECKI.R	8403150146	50-284 0	STEWART, W. L	8403300028	50-338 P		8403020007	50-316 R

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
Shamy, B a Shan, W B. Shanson, N, E Sharts, D J Shartz, E D	8403190404* 8403160222* 8403010079 8403080136 8403120013	50-413 A 50-390 Q GA999 50-410 G 50-456 S	Thomas, C. D. Thomas, E. B. Thomas, E. B. Thomas, E. B. Thomas, E. B.	8403270387 8403130106* 8403130118* 8403130128* 8403130138*	50-322 Q 50-440 A 50-440 A 50-440 A 50-440 A	TRIPP, L TRIPP, L E. TRIPP, L E. TRIPP, L E. TROJANOWSKI, R	8403270008 8403010322* 8403150063* 8403220137* 8403210133	50-219 50-277 50-277 50-412 1&E	3 Q Q
SWARTZ, E. D. SWARTZ, E. D. SWEENEY, M. SWETLAND, P. SWETLAND, P. D.	8403190193 8403190274* 8403080393 8403220103* 8403010404*	50-456 S 50-454 G 50-287 P 50-307 G 50-213 G	Thomas, J Thomas, J Thomas, M. Thomas, N Thomas, R	8403010152* 8403010154* 8403270207* 8403080273* 8403200132	50-348 P 50-348 P 50-390 G 50-298 F I&E	Trojanowski, r Troskoski, w m Troup, G. L Troup, G. L Trowsridoe, G F	8403300112 8403260173* 8403160307* 8403270050* 8403060070		G G G
SWIDER, M. A.	8403130010 8403130010 8403130139 8403130139 8403130403	50-440 0 50-440 0 50-440 0 50-440 0 50-440 0	THOMASIR D THOMASIR D, THOMASIN M THOMASIN P V	8403270217* 8403270221* 8312140351* 8403270367 8403020083	70-1257 70-1257 50-275 E 50-275 U 50-278 R	TROWERIDOE, OF TROWERIDOE, OF, TROWERIDOE, OF, TROWERIDOE, OF, TROWERIDOE, OF	8403040090 8403080105 8403080105 8403200055 8403200055		0000
Swiger, M. A Swiger, M. A. Swiger, M. A Swiger, M. A. Swiger, M. A.	8403130403 8403150001 8403150001 8403150007 8403150007	50-440 Q 50-440 Q 50-440 Q 50-440 Q 50-440 Q	THOMASON, P. V THOMASON, P. V THOMBERG, R. C THOMBERG, R. C THOMPSON, D	84031900B9 8403300150 8403070355 8403280114 8403080120*	50-298 F 50-298 R 50-275 F 50-275 F FDIA	TROWBRIDGE, G. F TROWBRIDGE, G F TUCKER, H B. TUCKER, H B. TUCKER, H. B	8403200120 8403200120 8403210150 8403010140 8403010308	50-289 50-369 50-413	C C R B C
Shiger, M. A. Shiger, M. A Bhiren, B. J. Sydnor, R. B Sydnor, R. B.	8403260327 8403260327 8403070022* 8403130081 8403130098	50-400 Q 50-400 Q 50-443 Q 50-318 S 50-317 B	THOMPSON, D. J. THOMPSON, H. L. THOMPSON, T. THOMPSON, V. J. THOMPSON, E. R.	8403270048* 8308040578* 8401160250 8403070161* 8403010075	50-352 T ACRS 50-346 S CONTRACT GA999	TUCKER, H. B TUCKER, H. B. TUCKER, H. B. TUCKER, H. B TUCKER, H. B.	8403010335 8403020317 8403060106 8403060225 8403060232	50-369 50-369 50-269	F F F F F F
BYDNOR, R. B BYDNOR, R. B. BYDNOR, R. B BYDNOR, R. B BZALAY, R.	9403190252 9403190279 9403190413 9403130490 9403190317	50-317 8 50-317 8 50-318 8 50-318 8 PR	THOMBEN, E. R THONUS, L. THONUS, L. THORNBERRY, R C THORNBERRY, R C	8403130338* 8403130471* 8403150135* 8403020004 8403120029*	0A999 50-320 G 50-320 G 50-225 R 50-275 G	TUCKER, H. B. TUCKER, H B. TUCKER, H B. TUCKER, H B. TUCKER, H B.	8403060292 8403060336 8403060419 8403060422 8403070185	50-413 50-413 50-413	Р F A A
EZYMCZAK, G. Tahvili, T. Takeuchi, K. Talbot, R. Tah, P.	8403090075 8403230111* 8403230208 8403010004* 8403070387	PRM 50-255 P NUREO CONTRACT 50-334 P	THORNBERRY, R. C THORNBURG, H D. THORPE, J R THORPE, J. R THORPE, J. R.	8403300141 8401230660* 8403050070 8403190387 8403290015	50-275 R 50-329 8 50-219 P PR 50-219 H	TUCKER, H B. TUCKER, H. B	8403070210* 8403070352 8403080239 8403090222 8403090226	50-369 50-269 50-269	g ド ド 野
TAM, P. 8, TAMBLING, T. N TAM, C. P. TAMMER, J. E. TAMMER, R. L	8403160061 8403190096# 8310310475# 8403190449 8403130378	50-334 P 50-123 G 50-329 A NUREO PR	THRON, R. W TIDABACK, A J. TIETZ, G. TILLMAN, A. TILLMAN, A.	8403230058 8403080204* 8403070274 8403020241* 8403170188*	PR FOIA 50-234 F 50-250 G 50-259 R	TUCKER, H. B TUCKER, H B. TUCKER, H B TUCKER, H. B TUCKER, H. B	8403090241 8403090254 8403090276 8403120150 8403120153	50-249 50-349 50-370	8 4 8 8
TAPERT, A. C. TAUZIN, B. TAYLOR, D. F. TAYLOR, J. A. TAYLOR, J. A	8403070214 8403140208* 8403190346 8403090213 8403120176	PR 50-382 U 50-387 F 50-338 B 50-338 P	TIMO, D P. TIPPB, B B. TIPPB, S B. TIPPB, S B. TIPPB, B B.	8402100259 8403120031 8403140031 8403140044 8403140024	TOPREP 50-344 8 50-346 8 50-321 9 50-344 9	TUCKER, H. B TUCKER, H. B. TUCKER, H. B TUCKER, H. B. TUCKER, H. B.	8403120173 8403130086 8403130104 8403130167 8403130332	50-413 50-413 50-370	8 A B 8
TAYLOR, J.A. TAYLOR, J.A. TAYLOR, J.H TAYLOR, J.H TAYLOR, J.J	8403190080 8403190394 8403190241 8403300179 8403220112	50-338 B 50-338 B TOPREP TOPREP WASTE MOT	TIPPS, B. B TIPPS, B. B TIPPS, B. B TISON, J. C. TKACHYK, J. W.	840326086 8403260119 8403260191 7911120366* 8403060533	50-366 B 50-366 B 50-366 B 50-312 F MUREO	TUCKER, H, B TUCKER, H, B TUCKER, H B, TUCKER, H, B, TUCKER, H, B	8403130341 8403140231 8403130065 8403150128 8403150138	50-349 50-413 50-413	P F 8 8
TAYLOR, P. A. TAYLOR, P. A TAYLOR, R. Q. TAYLOR, T. J. TAYLOR, T. J.	8403160224# 8403160370# 8403130219# 8403020174 8403200314	50-413 Q 50-413 Q 50-445 Q Habte Mot Wabte Mot	Tobiab, M L, Tobin, W Toll, J, S, Tolbon, V. Tompking, B, A,	8403130217 8403160016* 8403210124 8403070152 8403050068	NUREQ 50-390 @ 50-166 P CONTRACT 50-537 @	TUCKER.H B TUCKER.H, B. TUCKER.H B. TUCKER.H.B TUCKER.H.B	8403150156 8403160028 8403160143 8403160177 8403160216*	50-413 50-413 50-413	P A Q A Q
TEDESCO, R. L. TEDESCO, R. L. TEDFORD, C. F. TEDFORD, C. F. TEICHMANN, T	B110080612* B111200217* 8403070106 B403270263 B403010041*	50~460 A 50-397 A PR PR FOIA	TOMPKINB, B. A TONOUE, T. TONOUE, T. M. TOTH, A D TOUBLEY, D. R	8403060179 8403120137* 8403120079* 8403080270* 8403300243	50-275 0 50-237 0 50-237 0 50-397 0 WASTE MOT	TUCKER, H. B. TUCKER, H B.	8403160253 8403160299* 8403160313* 8403190257 8403190289	50-413 50-369	0 0 P
TELLOCK, H, G TEMPLE, O, M, TEPEL, R, C, TEPER, D, C, TERG, N, M,	8403270052* 8403080152* 8403200358 8403020126 8403210054*	FOIA 50-528 G NUREO 50-424 G 50-320 G	TOWNSEND, B TOWNSEND, B. TOWNSEND, B. TOWNSEND, B. TOWNSEND, B. L	B403220216 B403220256 B403220275 B403230152 B403020069	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	TUCKER, H B TUCKER, H. B. TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8403190303 8403190394 840320001 O 8403200078 8403200123	50-413 50-249 50-413	B A R E
TERWILLIGER, L, THADANI, A. C, THEOFANOUS, T. 9, THEROUX, R. R. THIES, A. C.	8403130195 8308040003* 8403230216 8403210032 8403070331*	XPORTLIC 50-204 P 50-537 A 50-200 S 50-413 Q	TRANN, T. R. TRANN, T. R. TRANN, T. R. TRANN, T. R TRANN, T. R.	840301010å 8403010120 8403010130 840301028å 8403060245	50-454 A 50-454 E 50-454 G 50-454 E 50-454 C	TUCKER, H. B TUCKER, H B TUCKER, H B TUCKER, H. B TUCKER, H. B	8403200165 8403200321 8403220038 8403220074 8403260034	50-413 50-369 50-413	A F A A
THOM, T. THOM, T. THOMADJEN, B. R. THOMAB, B THOMAB, B	8403020103 8403300134* 8403130327 8403050002 8403050043	50-239 R 50-239 R PR 50-234 G 50-10 G	TRAMM, T. R. TRAMM, T. R. TRAMM, T. R. TRAMMELL, C. TREBY, B. A.	8403060345 8403220133 8403260132 8307180403* 8403190047	50-454 E 50-454 A 50-454 E 50-344 P 50-537 0	TUCKER, H B TUCKER, H, B. TUCKER, H B TUCKER, H, B TUCKER, H, B.	8403260073 8403270103 8403270209 8403270213 8403270230	50-413 50-269 50-413	44E4E
THOMAS, B. THOMAS, B. P. THOMAS, C. D. THOMAS, C. D. THOMAS, C. D. THOMAS, C. O.	6403230107# 6403220240 8312180241# 8403020162 8403070360	50-10 G CONTRACY ACRS 50-13 F 50-5 F	TREBY, B. A TREBY, B. A TREBY, B. A. TREHAN, N TREHAN, N K	8403170118 8403170148 8403210102 8403280121* 8305160260	50-445 0 50-445 0 50-445 0 50-281 8 50-281 8	TUCKER: H B. TUCKER: H. B. TUCKER: H B. TUCKER: H B TUCKER: H B TUCKER: H, B.	8403270243 8403280102 8403270082* 8403270148 8403270244	50-269	P G P S
THOMAS, C. O. THOMAS, C. O. THOMAS, C. O. THOMAS, C. O. THOMAS, C. O.	8403120274 8403150178 8403260340 8403280065 8403280068#	50-54 P 50-54 P 50-139 F 50-83 P 50-83 P	TREHAN, N.K. TREHAN, N.K. TREMBLAY, P. TREGLER, M. TRIPP, L.	8309260510# 8309260515 8403050284 8403120012# 8403260173#	50-311 8 50-311 8 50-326 8 50-275 0 50-334 0	TUCKER, H B. TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H, B.	8403270267 8403270276# 8403300079 8403300107 8403300126	50-369 50-413 50-413 50-413 50-413	8 - A

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	
KER.H B AND.H J AND.M J KANIS.M M NER.S E	8403300188 8403060289* 8403060295* 8403080076* 8403060366*	50-413 A 50-322 T 50-322 T FOIA 50-302 P	VANDEWALLE, D J. VANDEWALLE, D J. VARELA, A A VARCA, S A VARCA, S A	8403190101 8403260115 8403300076* 8401120597* 8403010066	50-255 8 50-255 P 50-322 G 50-348 P 50-305 P	VAYESIER.Q VERRELLI.D M VERRELLI.D M VERRELLI.D.M. VERRELLI.D M	8403080364* 8402130400 8402140189 8403070007 8403070085	FOIA 50-348 50-241 50-395 50-395	Q Q Q
TLE,WK ETDN,DR RITZ,RA RICH,WT RICH,WT	8403270311 8403230177 8403300190# 8403120019 8403120085	PRM NUREQ 50-311 0 50-278 8 50-277 8	VARGA, S A VARGA, S A VARGA, S A VARGA, S A VARGA, S A.	8403010171* 8403010173 8403010174* 8403020058* 8403020156	50-250 P 50-250 F 50-247 P 50-280 P 50-348 P	VERRELLI, D M VERRELLI, D M VERRELLI, D M VERRELLI, D, M	8403070094 8403070100* 840307014B 8403070179 8403070186*	50-400 50-400 50-416 50-400 50-416	û 0 0
RICH, W T RICH, W T RICH, W T RICH, W T RICH, W T	8403120175 8403130158 8403170178 8403200017 8403270064	50-27B S 50-27B S 50-277 R 50-277 B 50-277 P	Varga, e a Varga, e a Varga, e a Varga, e a Varga, e a	8403020171 8403020178 8403020184 8403020190 8403050217	50-286 F 50-247 P 50-250 P 50-315 P 50-261 P	VERRELLI, D. M.	8403070193* 8403070206* 8403070218 8403070247 8403070307	50-400 50-416 50-438 50-416 50-324	0 0 0
EL.D EL.D EL.D. EL.D.	8403010091 8403010461 8403050231 8403070029 8403120221	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	VARGA, S A	8403060012* 8403060044 8403060504 8403060508 8403070321	50-261 P 50-286 P 50-305 P 50-261 F 50-305 P	VERRELLI, D. M. VERRELLI, D. M VERRELLI, D. M VERRELLI, D. M VERRELLI, D. M.	8403160008 8403160100 8403160142 8403160201 8403160207	50-370 50-416 50-348 50-370 50-370	0 0 0 0 F
EL.D EL.D EL.O EL.O EL.O	8403230071 8403230157 8403300307 8403070037 8403270286	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	VARGA,S A VARGA,E A VARGA,E A VARGA,E A VARGA,B A	8403070382* 8403070389* 8403070398* 8403090145 8403090153	50-348 P 50-334 P 50-247 P 50-275 P 50-334 P	VERRELLI, D M. VERRELLI, D M VERRELLI, D, M VERRELLI, D, M, VERRELLI, D M	B403160214 B403160217 B403160232 B403160237 B403160271	50-390 50-327 50-259 50-390 50-390	Q: Q: Q: Q:
ARDIA ARDIA R KEWICZIB ONEIA IGHTIC.	8111120735* 8105140106* 6403020073 8403200267* 8403160317*	50-460 E 50-460 A 50-213 R 50-482 A 50-413 G	VARGA, B A	8403140199 8403140200* 8403140224 8403140225 8403140300	50-280 G 50-280 G 50-315 P 50-305 P 50-250 G	VERRELLI, D. M VERRELLI, D. M VERRELLI, D. M VERRELLI, D. M VERRELLI, D. M,	8403160274* 8403160305 8403160336 8403160350 8403160374*	50-241 50-395 50-416 50-390 50-390	0 0 0 0 0
ON.R T .V. .V.	8403050170 8403020300 8403140228 8403150110 8403150155	9T21 50-317 F 50-317 F 50-317 F 50-317 F	VAROA, B. A VAROA, B. A VAROA, B. A VAROA, B. A VAROA, B. A	8403190150 8403190429 8403190450 8403210195 8403210197	50-250 P 50-250 F 50-315 P 50-348 P 50-247 P	VERRELLI,D M VERRELLI,D M VERRELLI,D M VERRELLI,D,M. VERRELLI,D M	8403140382 8403270017 8403270042 8403270078 8403270086	50-261 50-348 50-370 50-348 50-324	@ @ @ @
EY, E E EY, E E EY, E E EN, J BRUNT, E. E	8403070074 8403120074 8403150161 8403150222* 8402270008	50-261 F 50-400 V 50-261 P WASTE MOT 50-528 S	Varga, 5 A Varga, 5 A Varga, 5 A Varga, 5 A Varga, 6 A	8403210200* 8403260050 8403260274 8403280101* 8403280108*	50-247 P 50-272 P 50-334 P 50-295 P 50-295 P	VERRELLI, D, M VERRELLI, D M VERRELLI, D, M, VERRELLI, D M VERRELLI, D, M,	8403270089* 8403270117 8403270151 8403270163 8403270167*	50-348 50-257 50-416 50-400 50-400	0 F 0 0
DRUNT, E E BRUNT, E E BRUNT, E E BRUNT, E E BRUNT, E E	8403010212 8403020005 8403070012 8403070077 8403070087	50-528 A 50-528 E 50-528 E 50-528 S 50-528 S	VARGA, S.A. VARGA, S.A. VARGA, S.A. VARGA, S.A. VARGA, S.A.	8403280325 8403280327 8403300231 8403300233 8403300274	50-334 P 50-348 F 50-247 P 50-315 F 50-315 P	VERRELLI, D. M VERRELLI, D. M VERRELLI, D. M VERRELLI, D. M. VERRELLI, W.	8403270178 8403270201 8403270237 8403270284 8403010041*	50~400 50~390 50~259 50~395 FDIA	a a V
BRUNT, E. E BRUNT, E. E BRUNT, E E BRUNT, E E BRUNT, E E	8403070076 8403070122 8403070167 8403070177 8403070258	50-528 8 50-528 8 50-528 8 50-528 8 50-528 8	VARLEY.R A VARNER,L B VARNER,L B VASSALLO,D,B VASSALLO,D B	8403070171* 8403120314* 8403120345* 8403050337 8403060022	50-322 T CONTRACT CONTRACT 50-265 P 50-271 F	VIETTI,A. VILLFORTH,J C VILLFORTH,J,C, VISSING,G,B VITG,D.	8403010444 8403090106 8403160026 8403050053 8403270171*	50-498 PR 50-352 50-346 50-289	A D P G
BRUNT, E E BRUNT, E E GRUNT, E E BRUNT, E E BRUNT, E E	8403120032 8403120069 8403120113 8403130449 8403130461	50-528 8 50-528 8 50-528 8 50-528 8	VASSALLO, D. B VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B.	B403060034 B403060036 B403060041 B403060045 B403060050	50-273 F 50-220 F 50-263 F 50-333 F 50-331 P	VOOLER, B. H VOOLER, B. H. VOOLER, B. H VOOLER, B. H. VOOLER, B. H.	8403140115 8403140116 8403190173 8403290374 8403290399	50-352 50-352 50-352 50-454 50-352	00000
BRUNT, E E BRUNT, E E BRUNT, E E BRUNT, E E BRUNT, E E	8403140024 8403140048 8403140045 8403170387 8403200115	50~528 Q 50~528 A 50~528 A PR 50~528 S	VASBALLO, D. B. VASBALLO, D. B. VASBALLO, D. B. VASBALLO, D. B. VASBALLO, D. B.	8403060053 8403060063 8403060067 8403060069 8403060073	50-324 P 50-254 F 50-324 P 50-324 P 50-324 P	VOOLER, B, H VOKAL, D, J VOKAL, D, J, VOKAL, D, J VOLQENAU, E	8403270400* 8403130030 8403130254 8403130272 8403080075*	50-352 50-329 50-329 50-329 FOIA	8 0 8
BRUNT, E E BRUNT, E E BRUNT, E E BRUNT, E E BRUNT, E E	8403200160 8403200186 8403200226 8403230006 8403230017	50-529 8 50-528 8 50-528 8 50-528 8 50-528 8	VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B.	8403060076 8403060471 8403060550 8403060567 8403060571	50-259 P 50-298 F 50-331 F 50-324 F 50-259 F	VOLGENAU, E. VOLGENAU, E VOLGENAU, E. VOLGENAU, E. VOLGENAU, E.	8403080112* 8403080122* 8403080132* 8403080156* 8403080160*	FOIA FOIA FOIA FOIA	
BRUNT.E.E BRUNT.E.E BRUNT.E.E BRUNT.E.E BRUNT.E.E	8403230039 8403230084 8403230099 8403230113 8403230132	50-528 8 50-530 8 50-528 8 50-528 8 50-529 8	VASSALLO, D, B. VASSALLO, D B. VASSALLO, D B, VASSALLO, D, B. VASSALLO, D B	8403079086 8403130496 8403140185 8403140236 8403140246	50-324 F 50-220 F 50-243 P 50-324 F 50-333 F	VOLGENAU, E. VOLGENAU, F VOLLMER, R, H VOLLMER, R, H VOLLMER, R, H,	8403080190* 8403080092* 8309120536* 8403010282* 8403080316*	FOIA FOIA FOIA 50-329 50~247	Á
BRUNT, E E BRUNT, E E BRUNT, E E BRUNT, E E CLEVE, H D	8403260014 8403290236 8403300020 8403300076 8107200104*	50-528 F 50-528 A 50-528 S 50-528 B FDIA	VASSALLO, D B, VASSALLO, D, B VASSALLO, D, B VASSALLO, D B	8403140248 8403140252 8403140274 8403140285 8403140287	50-293 F 50-29B F 50-296 P 50-271 F 50-324 P	VOLLMER, R. H VORDERBRUEGOEN VORDERBRUEGOEN VUMBACO, F. J. VUMBACO, F. J.	8403080426* 8402140022* 8403270139* 8403050144* 8403050150*	50-275 50-528 50-528 40-672 40-672	e G
DAATBELAAR DYKE, J. W VLIET, J. VLIET, J VLIET, J	8403080360* 8403200358 8403010030* 8403010516 6403020418	FOIA MUREO 50-269 P 50-289 P 50-289 P	VASSALLO, D B VASSALLO, D B, VASSALLO, D S, VASSALLO, D S. VASSALLO, D S.	8403140291 8403140304 8403140313 8403140319 8403150323	50-324 Q 50-333 P 50-331 P 50-331 Q 50-259 P	Vumbaco, F. J Hade, L Wade, L Hagner, A. g. Hagner, D	8403220092* 8403140189 8403230069 8403070216* 8403060552	40-672 PRM PRM 50-416 50-354	Q A
VLIET, V DEMBERO, D DEMBUROH, C, DERSTEEO, F DEWALLE, D, J,	8403060472 8403120140 8403300030* 8403020112 8403070300	50-287 P 50-255 R 50-454 G XPORTLIC 50-255 G	VASSALLO, D, B VASSALLO, D, B VASSALLO, D, B. VAUGHAN, C, M VAUGHAN, T, E,	8403300232 8403300266 8403300268 8403140172 8403060225	50-273 F 50-333 P 50-271 P PR 50-269 F	WAGNER, D. H. WAGNER, D. H. WAGNER, M. E. WAGNER, M. E. WAGNER, M. E.	8403050369 9403150259 8403140111 8403160007 8403190187	50-354 50-354 50-289 50-289 50-289	F A 0 0 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WAGNER, M E WAGNER, M E WAGNER, M E WAGNER, M E WAGNER, P C	8403210165 8403210169 8403270304 8403270318 8403130251	50-416 Q 50-289 Q 50-289 Q 50-416 G 50-267 P	WEISS,E R WEISS,E R WEISS,E R WELCH,S E WELLS,D.A	8403260382 8403270003 8403300257 8403270271 8403060173*	50-289 0 50-289 F 50-289 0 50-315 F 50-341 0	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8403070238* 8403150024 8403150024 8403160010	50-352 (50-352 (50-352 (50-352 (50-352 (
WAGNER, PC WAGONER, BR WAHI, K. K WAITE, RS WALKER, J. B	8403170083 8403270327 8403240353* 8403080270* 8403070245	50-267 P RES WASTE MOT 50-397 Q 50-259 S	WELLS,DA WELLS,DA WELLS,DA WELLS,DA WELLS,DA	8403060177* 8403120009 8403120068 8403120155 8403120160	50-341 0 50-341 5 50-341 5 50-341 5 50-341 5	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8403200060 8403200060 8403200070 8403200070 8403210103	50-352 (50-352 (50-352 (50-352 (50-352 (
WALKER, J B WALKER, R, WALKER, R WALKER, R	8403070253 8403200087 8403130423 8403170013 8403170076#	50-259 S 50-296 S 50-263 S 50-374 S 50-373 Q	WELLS,D.A WELLS,D.A WELLS,R.W WELLS,R.W WELLS,R.W	8403190079 8403260127 8403130277 8403130277 8403140131	50-341 S 50-341 G TOPREP TOPREP TOPREP	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8403210103 8403270012 8403270012 8403270042 8403270042	50-352 u 50-352 g 50-352 j 50-352 j
WALKER, R. D WALKER, R. D WALKER, R. D WALKER, R. D. WALKER, R. F	8403120079* 8403120133* 8403120137* 8403120145* 8403270192	50-237 Q 50-331 Q 50-237 Q 50-263 Q 50-267 I	WELLS, R W WELT, M A WELT, M A WELT, M A	8403140131 8403080040* 8403080055* 8403080055*	TOPREP FOIA FOIA FOIA FOIA	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	B403270040 B403270384 B403270384 B403270392 8403270372	50-352 9 50-352 9 50-352 9 50-458 9 50-458 9
HALKER, R. S HALLER, H. K. HALLING, O E HALLO, E. H. WALSH, M	8403070076* 8403010349 8403020258 8403150045* 8403070181*	50-289 U 27-48 50-389 S 50-237 P 50-445 G	WELT, M A WELT, M A WELT, M A WELT, M A	8403080084* 8403080089* 8403080137* 8403080150* 8403080163*	FOIA FOIA FOIA FOIA FOIA	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8403300127 8403300127 8403300128 8403300128 8403300271	50-352 ± 50-352 ÷ 50-352 ÷ 50-352 ÷ 50-352 q
Walton, Q A. Walton, O A Ward, J D. Ward, K. D. Warembourg, D.	8402140038* 8403220137* 8403070106 8403170208* 8403010116	50-528 Q 50-412 Q PR 50-254 Q 50-267 B	WELT, M A WELT, M A WELT, M A WEN, P WENNER, T J	8403080168* 8403080172* 8403080183* 8403290171* 8403070318*	FOIA FOIA FOIA 50-289 Q 50-325 Q	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WHEELER, L WHEELER, L L	8403300271 8403300274* 8403300274* 8107140185* 8204290657*	50-352 Q 50-352 Q 50-352 Q 50-508 Q 50-508 A
WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D,	8403010134 8403140227 8403170344 8403220063 8403270172	50-267 S 50-267 P 50-267 R 50-267 S 50-267 I	WENSLAWSKI, FA WENSLAWSKI, FA WENSLAWSKI, FA WENSLAWSKI, FA	8403060008 8403060019* 8403060165 8403060172* 8403060416	50-206 Q 50-206 Q 50-113 Q 50-113 Q 70-1257	WHICHER, JM WHICHER, JM WHICHER, JM WHICHER, J, M WHICHER, J, M	8403060079 8403160002 8403160002 8403160019 8403160019	50-454 Q 50-454 Q 50-454 Q 50-454 Q
HAREMBOURG, D. W. WAREMBOURG, D. W HAREMBOURG, D. W HAREMBOURG, D. W. WAREMBOURG, D. W.	8403010101 8403010107 8403030112 8403160303 8403160326	50-267 P 50-267 G 50-267 G 50-267 G 50-267 G	WENSLAWSKI, FA WENSLAWSKI, FA WENSLAWSKI, FA WENSLAWSKI, FA	8403080061 8403080075* 8403190367 8403190373* 8403270221*	50-312	WHICHER, J M WHICHER, J M WHIPPLE, S WHIPPLE, S WHITE, M G	8403260351 8403260351 8403020072 8403300083 8403010356	50-454 Q 50-454 Q 50-27 R 50-27 R WARTE MOT
WARNICK,R F WARNICK,R.F WARNICK,R F, WARNICK,R F WARRICK,J W	8403060385 8403080198* 8403190315 8403230043 8403230139	50-329 Q FDIA 50-358 Q 50-329 R 50-275 R	HENZINGER, E C HENZINGER, E C HEBCOTT, H. M HEBLEY, D A HEBLEY, D A	8403270023* 8403270025* 8403020308* 8403140024* 8403200152*	FOIA FDIA 50-443 Q 50-329 A 50-423 A	WHITE, M P WHITE, W H WHITENER, H L WHITENER, H L WHITENER, H L	8403160076* 8403120010* 8403070017* 8403070338* 8403160337*	50-412 A 50-275 Q 50-413 Q 50-413 Q 50-259 Q
WASTLER, B. L. WATKING, L. B. WATKING, L. B. WATKING, L. B. WATT, E,	8403R30157# 8403140009 8403140012# 8403140012# 8403300130	40-8745 50-458 0 50-458 0 50-458 0 50-458 F	Wessman, R West, J M. Westafer, G. R. Westafer, G. R Westafer, G. R	8403020032* 8403200085* 8402040417 8403010072 8403040283	50~267 P 50~470 K 50~302 P 50~302 F 50~302 R	WHITMAN,D WHITTIER,GD WHITTIER,GD WHITTIER,GD WHITTIER,GD	8403270013 8403060094 8403130047 8403220192 8403230036	50-278 F 50-309 P 50-309 R 50-309 P 50-309 P
Watte, R. J. Watte, R. J. Watte, R. J Watte, R. J Weber, J.	8403230016 8403230032 8403230048 8403230073 8403080281#	50-322 T 50-322 T 50-322 T 50-322 T 50-275 E	WESTAFER, O. R WESTAFER, O. R WESTAFER, O. R WESTAFER, O. R WESTAFER, O. R	8403060343 8403060357 8403060364 8403060402 8403090193	50-302 P 50-302 P 50-302 P 50-302 Q 50-302 8	WHITTIER, O D WHITTIER, C D WHITTIER, C D WICHMAN, K R WICHMAN, K R	8403230042 8403270138 8403270256 8403270046* 8403270065*	50-309 P 50-309 P 50-309 R FOIA FOIA
WZBER, M. F. WEEKB, E. D. WEEKB, E. D WEIL, C. H WEINER, B. R,	8403170447 8403020006 8403300075 8403080108# 8403130236	WABTE MOT 50-133 R 50-133 R FDIA FR	WESTAFER, CR WESTAFER, CR WESTAFER, CR WESTAFER, CR	8403120130 8403160036 8403160315 8403200038 8403200265	50-302 P 50-302 R 50-302 P 50-302 P 50-302 P	WICKS, F. WICKS, F WICKS, F WIDNER, T E WIECHMANN, S M	8403060204 8403200229 8403260156 8403130059 8403280022	50-225 F 50-225 R 50-225 R 50-287 R 50-344 J
HEINKAM, E.J. HEINKAM, E.J. HEISE, S. HEISMANTLE, J. HEISMANTLE, J. A.	8403140196 8403300292 8403160385* 8403070231* 8403070188*	50-458 F 50-458 A 50-261 G 50-322 T 50-322 T	HESTAFER, GR. HESTAFER, GR. HESTAFER, GR. HESTAFER, GR. HESTAFER, GR.	8403230014 8403230062 8403290159 8403300111 8403060176*	50-302 P 50-302 P 50-302 P 50-302 B 50-266 Q	WIECHMANN, B M WIEDEMAN, D G WIEDEMAN, D G WIEDEMAN, D G WIEDER, A V	8403280041 8403060201 8403060210* 8403080108* 8403120185*	50-344 J 40-8830 40-8830 FOIA 50-361 Q
WEISMANTLE, J. A WEISMANTLE, J. A. WEISMANTLE, J. A WEISMANTLE, J. A. WEISMANTLE, J. A.	8403070160* 8403070171* 8403070170* 8403070175* 8403070178*	50-322 T 50-322 T 50-322 T 50-322 T	WEBTOVER, A. J WEBTPHAL, B. B. WETHY, C. N. WETTERHAHN, M.	8403280054* 8403120020 8403170117 8403040340 8403040081	50-341 H 50-373 S 50-373 S 50-335 F 50-352 G	Hiehe, J Hien, B. O Hiener, J. L Wiebelman, K Hiebemann, R	8403130471# 8403130249 8403270211 8403080200 8403070302#	50-320 0 PRM 50-416 H FOIA 50-423 Å
WEIBMANTLE, J. A. WEIBMANTLE, J. A. WEIBMANTLE, J. A. WEIBMANTLE, J. A. WEIBMANTLE, J. A.	8403070201* 8403070204* 8403070207* 8403070211* 8403070214*	50-322 T 50-322 T 50-322 T 50-322 T 50-322 T	HETTERHAHN, M. HETTERHAHN, M. J. HETTERHAHN, M. J. HETTERHAHN, M. J. HETTERHAHN, M. J.	8403040081 8403020099 8403020125 8403020125 8403020129	50-352 Q 50-352 Q 50-352 Q 50-352 Q 50-352 T	Hiesemann, R. A. Hiesemann, R. A Wiesemann, R. A Hiesemann, R. A. Wiesemann, R. A.	8403170377* 840321020* 8403260201* 8403270277* 8403300116*	50-413 A TOPREP 50-244 P 50-369 P 50-413 A
WEISMANTLE, J. A. WEISMANTLE, J. A. WEISMANTLE, J. A. WEISMANTLE, J. A. HEISMANTLE, J. A.	8403070220* 8403070222* 8403070227* 8403230020 8403230039	50-322 T 50-322 T 50-322 T 50-322 T 50-322 T	WETTERHAHN, M. J. WETTERHAHN, M. J. WETTERHAHN, M. J. WETTERHAHN, M. J. WETTERHAHN, M. J.	8403020127 8403020163 8403020163 8403060248 8403060248	50-352 T 50-352 Q 50-352 Q 50-352 Q 50-352 Q	Higgins, E, J, Higgins, J T Higginton, D, Hilborn, L. Hilborn, L	8403070005 8403070319* 8403300247 8403260107* 8403240211*	CONTRACT 50-352 G 50-315 P 50-267 G 50-267 G
Weismantle, J a Weiss, e R. Weiss, e, R. Weiss, e, R. Weiss, e, R.	8403230066 8403080021 8403080346 8403210014 8403260382	50-322 T FDIA FDIA 50-289 Q 50-289 Q	WETTERHAHN, M J. WETTERHAHN, M J. WETTERHAHN, M, J WETTERHAHN, M, J WETTERHAHN, M J.	8403070142 8403070142 8403070236 8403070236 8403070238#	50-352 0 50-352 0 50-352 0 50-352 0	WILBORN,L WILCOVE,M N WILKIE,W H WILKIE,W.H.	8403300050* 8403140085 8403140154 8403020172* 8403130164*	50-313 g 50-352 g 50-327 g 50-400 g 50-400 g

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
WILKINS, W D WILKS, B L WILLIAM, P L WILLIAMS, C C	8403010082 8403020319 8403040253 8403040233 8403080123*	94979 50-387 8 50-387 8 50-461 9 50-373 9	WIMPY, P D WINDHAM, R WISE, D L WISE, M J WISE, R	8403080220* 8403270013 8403080186* 8403160073 8403060184*	50-316 P 50-298 F F01A WABTE MOT 50-445 Q	WOZNIAK, D R WOZNIAK, S F WRAY, J R WRAY, J, R WRIGHT, E D	8403050036 8402170107* 8403160372* 8403270320* 8403020107*	XPORTLIC 50-303 P 50-321 Q 50-333 Q FOIA
WILLIAMS, C C WILLIAMS, D WILLIAMS, D L WILLIAMS, E H WILLIAMS, J	8403200300* 8403300030* 8403080261* 8403290108* 8403230104	50-454 Q 50-454 Q 50-483 Q 50-461 I 50-358 Q	WISENBURG, M R WISENBURG, M R WITHERB, B D WITHERB, B D WITHERB, B D	8403140151 8403190289 8403040382 8403140137 8403190325	PR PR 50-344 P PR 50-344 P	WRIGHT, E Q WRIGHT, E Q WRIGHT, E Q WRIGHT, E Q WRIGHT, Q	84030Z0124* 84030Z0180* 84030Z0194* 84030Z0Z24* 8403170Z97*	FOIA FOIA FOIA FOIA C-373 Q
WILLIAMS, J C WILLIAMS, J H WILLIAMS, J H WILLIAMS, J H WILLIAMS, J H	8403050168 8403010322* 8403150063* 8401130182 8401130296	50-250 P 50-277 G 50-277 G 50-389 P 50-335 P	WITHERS, B D WITHERS, B D WITHERS, B D WOESSNER, J D WOHLD, F R	8403200141 8403200197 8403300168 8403130499* 8403080261*	50~344 Q 50~344 J 50~344 P 50~312 Q 50~483 Q	MRIGHT, N A WRIGHT, N A WRIGHT, N A WRIGHT, N A WRIGHT, N A	8403140105 8403210067 8403210076 8403300129 8403220205	50-352 0 50-352 0 50-352 0 50-352 0 HABTE MOT
WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W	8401130319 8402270125 8403010297 8403010302* 8403010400	50-387 £ 50-250 S 50-389 P 50-389 P 50-389 P	HOJNAG.E J HOJNAG.E J HOJTULENTCZ.T HOLFE.R B HOLFE.B J	8403020342* 8403020357* 8403270089 8403140244 8403060182	50-247 Q 50-286 Q 50-237 S 50-483 F 50-289 Q	WRIGHT, 8 V WU, P. C WU, P. C WULLER, Q. E WYNGARDEN, B, D	8403010341 8403190189* 8403210173* 8403240129* 8403070317	27-48 50-287 Q 50-289 G 40-1478 40-6940
HILLIAMS, J W WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W	8403020033 8403020258 8403020278 8403020288# 8403060112	50-250 R 50-387 S 50-250 V 50-250 Q 50-335 F	WOLFE.S J WOLFE.S J WOLFE.S J WOLFE.S J	8403060243 8403140002 8403140030 8403260332 8403260337	50-287 0 50-482 0 50-482 0 50-287 0 50-289 0	WYNVEEN.R A YAMADA,K YANG.C Y YANICHKO,S E YANICHKO.S E	8403170317 8403010467* 8403170404* 8403060326* 8403070237*	PR XPORTLIC 50-413 A 50-213 P 50-348 P
HILLIAMS, J W W C'SHVITIN M C'SHVITIN M C'SHVITIN MILLIAMS, J M MILLIAMS, J M MILLIAMS, J M MILLIAMS, J M MILLIAMS, J M	8403060186 8403060241 8403060291 8403060390 8403070034	50-389 F 50-389 P 50-250 G 50-389 S 50-335 G	WDLFE.8 J WOLLETT.9 WOLLETT.9 WOLLETT.5 WOLTMER.E	8403280334 8403010070 8403240323 8403270365 8403210054*	50-482 Q CONTRACT CONTRACT CONTRACT 50-320 Q	YEDVAB, J YDDER, R C YORE, J, R. YDUNO, F. YDUNO, F	8403230038 8403140151 8104210125* 8403010030* 8403070287*	50-322 T PR 50-400 Q 50-289 P 30-289 Q
HILLIAMS, J H	8403070249 8403080020 8403080164 8403070280 8403120040	50-387 Q 50-250 P 50-335 V 50-335 F 50-387 P	HOLTNER, E HONG, G HONG, G HONG, G HONG, G	8403210105* 8403020120* 8403020166* 8403020183* 8403280177*	50-334	YOUNG, K YOUNG, M YOUNG, T YOUNG, T YOUNG, T	8403200121 8403230208 8403080263* 8403080274* 8403080279*	50-331 F NURE0 50-528 G 50-312 G 50-312 G
HILLIAMS, J W WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W	8403120089 8403130035 8403130066 8403160013 8403160038	50-387 P 50-387 S 50-335 P 50-387 P 50-251 S	HONG. C C. HONG. C J. HODD. D C HOOD. D C HOOD. D C	8403020232* 8403280188* 8403140011 8403140018 8403260226	FOIA FOIA 50-387 8 50-387 8 50-387 8	AGNVABEGOD'B ? AGNVABEGOD'B ? AGNVA'A AGNVA'A AGNVA'L	8403270139* 8403220228 8403140283 8401120437* 8403010017	50-528 G WABTE NOT 50-482 A 50-445 A 50-440 E
H C'SWYITIN A C'SWYITIN A C'SWYITIN A C'SWYITIN A C'SWYITIN	840314005B 8403140049 8403140227 8403140384 8403200264	50-250 9 50-251 9 50-389 P 50-335 F 50-250 P	WOODHEAD, C. P	8403140044 8403010248 8403140176 8403140010 8403170015*	50-142 0 50-142 0 50-440 0 50-142 0 50-142 0	AONMOBFOOD'B 1 AONMOBFOOD'B 1 AONMOBFOOD'B 1 AONMOBFOOD'B 1	8403020148 8403020158 8403020164 8403020198 8403020289	50-445 A 50-423 A 50-341 A 50-454 F 50-445 E
W C.EMAILLIW W C.EMAILLIW W C.EMAILLIW W C.EMAILLIW W C.EMAILLIW	8403220070 8403220104 8403260203 8403270247 8403280110	50-335 9 50-250 9 50-250 P 50-335 F 50-250 F	WOODHEAD, C. P WOODHEAD, C. P WOODHEAD, C. P WOODRUFF, R	8403190062 8403190066 8403190157 8403210027 8403010151*	50-250 Q 50-440 Q 50-142 Q 50-142 Q FOIA	AONAGETOOD' B Y AONAGETOOD' B Y AONAGETOOD' B Y AONAGETOOD' B Y	8403050273 8403050353 8403060421 8403070130 8403070363	50-445 A 50-483 A 50-445 Q 50-423 E 50-440 F
WILLIAMS, J W WILLIAMS, J W WILLIAMS, M WILLIAMS, M H	8403270114* 8403270123 8403300173 8403010030* 8403010023*	50-335 Q 50-250 Q 50-250 R 50-289 P 50-289 P	WODDRUFF, R WOODRUFF, R WOODRUFF, R WOODRUFF, R L WOODRUFF, R W	8403010164* 8403010184* 8403010205* 8403210133 8107140213*	Foia Foia Foia I&E Foia	YOUNGBLOOD, B J.	8403090308 8403120249 8403120315 8403120320 8403120320	50-445 A 50-483 A 50-482 A 50-423 A 50-482 A
WILLIAMS.R E WILLIAMS.R E WILLIAMSON.H E WILLIAMSON.H E WILLIAMSON.H E	8403070046* 8403270276 8403080210* 8403080220* 8403200101*	CDNTRACT PR 50-316 P 50-316 P 50-316 P	WOODRUFF, R W WOODRUFF, R, W WOODRUFF, R, W WOODRUFF, R W, WOODRUFF, R W	8107160215# 8202120275# 8307150400# 8403010127# 8403010131#	FOIA FOIA FOIA FOIA	YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J	8403140288 8403140293 8403190421 8403260069 8403260299	50-445 E 50-445 E 50-482 A 50-445 G 50-423 A
MITSON'B D MITSON'B D MITSON'B D	8403230028 8403010084 8403010478 8403010499 8403010522	50-389 S XPORTLIC XPORTLIC XPORTLIC XPORTLIC	HOODRUFF, R W HOODRUFF, R W HOODRUFF, R W HOODRUFF, R W KOODRUFF, R W	8403010138# 8403010161# 8403010178# 8403010252# 8403010257#	FOIA FOIA FOIA FOIA	YOUNGBLOOD, B, J YOUNGBLOOD, B J, YOUNGBLOOD, B J YOUNGBLOOD, R YOUNGBLOOD, R W.	8403270345 8403280237 8403270357 8403230133 8403010041*	50-445 E 50-341 A 50-440 E 50-313 P FOIA
MILSON, B D WILSON, B D WILSON, B D	8403010539 8403010540 8403010546* 8403020089 8403050037	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	HOODRUFF,R W WOODRJFF,R W WOODS,T O WOODSUM,H C WOOLEVER,E J	8403050266* 8403050270* 8402140028* 8403010324 8403010387	FOIA FOIA 50-528 G 70-1143 50-412 A	YUHAS, O.P. YUNDT, C.P. YUNDT, C.P. YUNDT, C.P. YUNDT, C.P.	8403170373* 8403010355 8403020050 8403260216 8403300106	50-206 0 50-344 B 50-344 R 50-344 B 50-344 R
WILSON, B D WILSON, D L WILSON, D L	8403050261 8403070353 8403200047 8403200051 8403200121	XPORTLIC XPORTLIC 50-331 F 50-331 F 50-331 F	WODLEVER, E. J. WOOLEVER, E. J. WOOLEVER, E. J. WOOLEVER, E. J.	8403070278 8403070308* 8403130374 8403150075 8403160070	50-412 8 50-412 Q 50-412 B 50-412 C 50-412 A	ZABEL, 8 A ZAHLER, R. E. ZAHLER, R. E ZAHLER, R. E. ZAHLER, R. E	8403070123* 8403080140 8403080140 8403260345 8403260345	50-461 9 50-440 H 50-440 H 50-287 0 50-287 0
WILSON, D L WILSON, E F WILSON, J WILSON, J WILSON, J	8403200183 8403140149 8403020057* 8403280125 8403300060	50-331 F PR 50-280 R 50-280 F 50-280 R	HODLEVER, E. J. HODLEVER, E. HODLEVER	8403140170 8403170152 8403200234 8403210058 8403210130	50-412 A 50-412 A 50-412 A 50-412 B 50-412 B	ZAHNLEUTER, R J ZAHNLEUTER, R J ZAHNLEUTER, R J ZAHNLEUTER, R J ZAHNLEUTER, R. J	8403020123 8403040212 8403130043 8403130085 8403210179	50-322 0 50-322 T 50-322 0 50-322 0
HILSON, J. H HILSON, J. L HILSON, J. L HILSON, J. L WILSON, J. U,	8403050267 8403280062 8403090223 8403090250 8403130424	50-382 A 50-382 A 50-280 S 50-280 S 50-280 S	WOOLEVER, E. J WOOLEVER, E. J WOOLEVER, E. J WOOLEVER, E. J WOOLEVER, F. T	8403260059 8403290145 8403290204* 8403300200 8403190443	50-412 C 50-412 C 50-412 G 50-412 G 40-2259	ZAHNLEUTER, R J ZAHNLEUTER, R J, ZAHNLEUTER, R J ZERBE, J E ZEUGIN, L, B	8403210188 8403210201 8403260338 8403010283* 8403130082*	50-322 0 50-322 T FOIA 50-322 Q

AUTHOR	ACCESSION NUMBER	BUBJEC.		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ZEUGIN, L B ZEUGIN, L B ZEUGIN, L B ZEUGIN, L B ZEUGIN, L B	8403130082* 8403130097* 8403130099* 8403150004 8403150004	50-322 50-322 50-322 50-322	0 0 0	ZUPKO, J M ZUPKO, J M ZUPKO, J M ZUPKO, J M	8403150181 8402100194 8403080013 8403080244 8403080252	50-327 S 50-272 S 50-272 S 50-272 S 50-272 S
ZIBULSKY, H ZIBULSKY, H ZIBULSKY, H ZIELONKA, J S ZIMMERMAN, J,	8403010314* 8403150078* 8403290120* 8403290259 8403200394	50~352 50~272 50~387 PRM XPORTL IO	a G G	SON W SON W SON W SON W SON W SON W SON W	8403130384 8403220037 8403220142 8403220141 8403220174	50-311 S 50-311 S 50-311 R 50-311 S 50-272 R
zimmerman, j zimmerman, j zimmerman, j zimmerman, j zimmerman, j	8403220283 8403220284 8403220287 8403220297 8403220304	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		ZUPKO, J M ZUPKO, J M ZURAKOHSKI, P R	8403270099 8403270244 8403270221*	50-311 8 50-272 8 70-1257
ZIMMERMAN, J ZIMMERMAN, J ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8403220314 8403220315 8403010338 8403010344 8403010344	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC				
ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8403010369 8403010418 8403010421 8403010425 8403010432	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC				
ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V, ZIMMERMAN, J V ZIMMERMAN, J V	8403010477 8403010491 8403010495 8403010502 8403020015	XPORTLIC XPORTLIC XPORTLIC XPORTLIC				
ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8403020151 8403020154 8403020451 8403050026 8403050045	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC				
ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J, V	8403050188 8403050190 8403050193 8403050209 8403050213	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC				
ZIMMERMAN, J V ZIMMERMAN, J, V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8403050276 8403050282 8403050286 8403050320 8403050358	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC				
ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8403050359 8403050368 8403040035 8403040038 8403040087	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC				
ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V.	8403070004 8403070377 8403070424 8403080115 8403140229	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC				
ZIMMERMAN, J V ZIMMERMAN, J V, ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8403140307 8403140315 8403150129 8403150174 8403150241	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC				
ZIMMERMAN, J, V. ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J, V	8403200378 8403220201 8403230179 8403280050 8403280147	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC				
ZIMMERMAN, J V ZIMMERMAN, J, V ZIMMERMAN, J V, ZIMMERMAN, J V ZIMMERMAN, J, V,	8403280200 8403280252 8403280272 8403280327 8403290325	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC				
ZIMMERMAN, J V ZIMMERMAN, J, V, ZIMMERMAN, J V ZIMMERMAN, B R ZIMMERMAN, B R	8403270340 8403270403 8403300311 8403060167 8403070176	XPORTLIC XPORTLIC XPORTLIC 50-324 PR	P			
ZIMMERMAN, BR ZIMMERMAN, BR ZIMMERMAN, BR. ZIMMERMAN, BR. ZIMMERMAN, BR.	8403210061 8403210075 8403210116 8403280024 8403290083	50-324 50-324 50-261 50-400 50-324	P P M P			
ZITSER, B. B. ZITZER, P. ZUKOR, A ZUKOR, D. J ZUKOR, D. J	8403140025 8403280334 8403150183* 8211110514 8402270314*	50-443 50-352 50-327 50-349 50-321	0 0 5 8 0			

<u> </u>			

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index Indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the Index entitled "Cross Reference of Enclosures to Principal Documents.'

SUBJECT CATEGORY

50-348 50-348 50-348

50-348 50-348

50-348 50-348 50-348 50-348 50-348

50-348 50-348 50-348 50-348 50-348

50-348 50-348 50-348 50-348 50-348

50-348 50-348 50-348

50-348 50-348

50-348 50-348 50-348 50-364

50-348 PRM 40-3392 40-3392

40-4492 40-4492 CONTRACT GA999

CONTRACT

GA999

0A999 50-352 50-352 50-353

FR FR NUREQ

NUREO

NUREO

NUREO

ACCESSION NUMBER 8403130038* 8403130455 8403130455

8403130463* 8403130463*

6403140210 6403140212 6403150055 8403150084 8403160265*

8403230134 8403260017 8403260026* 8403260032* 8403260040*

8403260046* 8403260227 8403260227 8403260234* 8403260234*

8403280037 9403280037 8403280044*

8403280109

8403270084* 8403270317 8403300077

B403300134 6403300172

6403290311 8403230097 8403230100# 8403210012

B403200325# 8403220045 8403010045* 8403010082

8403040495×

8403120114±

8403270097* 8403190132 8403190138* 8403190142* 8403090178 8403090183*

6403300325 6403070114 6403140339

B403300261 8403300285

amodts .cme-Cleveland Co dvanced Medical Systems, Inc dvanced Trchnology, Inc .griculture, Dept of, Graduate School .ir Products & Chemicals, Inc	8403130013 8403220242 8403010077 8603020400 8403060152* 8403120314* 84031203345* 8403200371	50-289 50-289 GA999 FDIA FOIA CONTRACT	G G	
dvanced Medical Systems, Inc dvanced Technology, Inc griculture, Dept of, Graduate Bchool gr Products & Chemicals, Inc	8403010079 8403020400 8403060152* 8403060154* 8403120314* 8403120345*	GA799 FOIA FOIA FOIA		
dvanced Medical Systems, Inc dvanced Technology, Inc griculture, Dept of, Graduate Bchool gr Products & Chemicals, Inc	8403020400 8403060152* 8403060154* 8403120314* 8403120345*	FOIA FOIA		
dvanced Trchnologý, Inc griculture, Dept of, Graduate School dir Products & Chemicals, Inc	8403060152* 8403060154* 8403120314* 8403120345*	FOIA FOIA		
ir Products & Chemicals, Inc	8403120314* 8403120345*			
ir Products & Chemicals, Inc	8403120345*	CONTRACT		
ir Products & Chemicals, Inc				
·	8403200371	CONTRACT		
		XPORTLIC		
4- T Ass (ablus	8403280151*	XPORTL IC		
ir Transport Association	8403140155	PR		
ir and Water Pollution Patrol	8403220224	50-352	Q	
	8403220228	50~352	0	
	8403220227#	50-352	9	
	8403220229*	50-352	Q	
	8403220234#	50~352	G	
	8403220234*	50-352	G .	
	8403290378	50-352	G	
	8403270378	50-352	G	
	8403290395	50-352	g .	
	B403290397#	50-352	G	
labama Power Co	8403010129*	50~348	P	
	8403010137*	50~348	P	
	8403010141*	50~348	P	
	8403010146*	50-348	P	
	8403010152*	50-34B	P	
	8403010152*	50-348	P	
	8403010156*	50-348	P P	
	8403010156* 8403010163*	50-348 50-348	P P	
	8403010417	50~364	8	
	8403010422*	50-364	8	Alaska, Univ of Fairbanks
	8403010426*	50-364	8	Allied Chemical Corp.
	8403060125	50-348	ä	Willes Auguster onthi
	8403040125	50-348	ā	American College of Radiology
	8403080077	50-348	F	American Nuclear Corp.
	B403080077	50-348	F	
	84030B00B1	50-348	P	American Society of Mechanical Engineers
	8403080081	50-348	р	Amaconda Co. (subs. of Atlantic-Richfie)
	#4800B0E0#	50-348	P	Co.) Analysis & Technology, Inc.
	8403080086*	50~34B	P	•
	8403080148	50~348	P	Anchor/Darling Valve Co (subs of
	8403080148	50-348	P	Anchor/Darling Industries, Inc.)
	8403080158	50-34B	P	
	8403080158	50~348	P	Anthony, R. L.
	8403080195*	50~34B	P	
	8403080195*	50-346	P	
	8403080272	50-348	P	Applied Rediation Protection Services
	8403080272	50-348	P	Annalist Colones Assertates. Inc
	8403090243	50-348	s	Applied Science Associates, Inc Argonne National Laboratory
	8403090255	50-34B	P	
	B403070303	50~348	F	
	8403130031	50~34B	P	
	8403130031 8403130038*	50~348 50~348	P P	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY
Arizona Public Service Co	8402140028* 8402140032* 8402140037* 8402140052* 8402270008	50-528 50-528 50-528 50-528 50-528	0 0 0 0 0 3		8403050158 8403060179 8403060203* 8403060205* 8403060308	50-313 p 50-313, q 50-313, p 50-313 p 50-313 g
	8402270008 8402270008 8403010212 8403010212	50-528 50-528 50-528 50-528 50-528	8 9 A A A		8403040324 8403040350 8403040430 8403040430 8403090139	50-313 F 50-313 F 50-313 F 50-313 F 50-368 8
	8403020005 8403090012 8403090012 8403090012 8403090077	50-528 50-528 50-528 50-528 50-528	6. 6 6 8 9		8403090179 8403090301 8403120011 8403120011 8403130024	50-313 P 50-313 F 50-313 F 50-313 F 50-368 8
	8403070087 8403070087 8403070087 8403070096 8403070096	50-528 50-528 50-528 50-528 50-528	9 9 9 9		8403130324 8403130347 8403130437 8403130473 8403150037	50-368 8 50-368 8 50-313 0 50-313 F 50-313 P
	8403090096 8403090122 8403090167 8403090167 8403090167	50~528 50~528 50~528 50~528 50~528	6 9 9 9		8403150041* 8403200174 6403200179 6403200179 8403200180*	50-313 F 50-313 F 50-313 F 50-313 F 80-313 F
	8403090197 8403090197 8403090258 8403090258 8403090258	50-528 50-528 50-528 50-528 50-528	8 8 8 8		8403200180* 8403200181* 8403200181* 3403200246 8403200251*	50-313 F 50-313 F 50-313 F 50-313 F 50-313 F
	8403120032 8403120032 8403120032 8403120069 8403120069	50-528 50-528 50-528 50-528 50-528	9 8 8 8 8 8 8 8 8		8403200251* 8403200258* 8403200258* 8403220020 8403230091	50-313 F 50-313 F 50-313 F 50-368 8 50-313 P
	8403120069 8403120113 8403130449 8403130449 8403130449	50-528 50-528 50-528 50-528 50-528	\$ 5 G G G		8403260051 8403260051 8403260137 8403260157* 8403260157*	50-313 P 50-313 P 50-368 Q 50-313 P 50-313 P
	8403130461 8403130461 8403130461 8403140024 8403160048	50-528 50-528 50-528 50-528 50-528	S 9 8 0 A		8403270258 8403280094 8403280094 8403290127 8403300068	50-368 8 50-313 F 50-313 F 50-368 \$ 50-313 R
	8403160048 8403160048 8403160052* 8403160052*	50-528 50-528 50-528 50-528 50-528	A A A	Arkansas, State of Army, Dept of Army, Dept of, Corps of Engineers Aspen Bystems, Inc	8403300164 8403140149 8403210107 8403280052* 8403070373*	50-36B R PR PRM CONTRACT CONTRACT
	8403160065 8403160065 8403160065 8403190387 8403200115	50-528 50-528 50-528 PR 50-528	A A A	Atlas Minerals, Inc	8401120171 8401120160* 8403150242 8403150264 8403150264	40-3453 40-3453 40-3453 40-3453 40-3453
	8403200115 8403200160 8403200160 8403200186 8403200226	50-528 50-529 50-529 50-526 50-528	9 9 9 9	Atom Sciences, Inc Atomic Industrial Furum Australia, Goyt op	8403230267 8403300312* 8403190317 8403220264 8403220279	40-3453 CONTRACT PR XPORTLIC XPORTLIC
	8403200226 8403200226 8403230006 8403230017 8403230037	50-528 50-528 50-528 50-528 50-528	9 8 9 9	Automation Industries, Inc	8403210001 8403210005* 8403210010* 8403300008 8403020224	40-6920 40-6920 40-6920 40-6920 Toprep
	8403230037 8403230037 8403230086 8403230077 8403230077	50-528 50-528 50-530 50-528 50-528	8 8 8 8	Babcock & Wilcox Co	8403120127 8403200127 8401240315* 8403010162 8403010166*	TOP REP TOP REP 70-27 71-4204 71-4206
	8403230099 8403230113 8403230132 8403260014 8403260014	50-528 50-528 50-529 50-528 50-528	9 8 F F		8403020167 8403050110* 8403050114* 8403050118* 8403070149*	70-27 50-344 F 50-344 F 50-344 F 70-27
	8403260014 8403270236 8403300020 8403300020 8403300020	50-528 50-528 50-528 50-528 50-528	F A 9 8 8		8403070153* 8403130058* 8403130074* 8403170241 8403170246*	70-27 GA999 GA999 TOPREP TOPREP
Arisona, State of Arkansas Power & Light Co	8403300076 8403070106 8403270263 8403020075 8403020001	50-528 PR PR 50-313 50-368	R R	Babcock & Wilcox Operating Plants Owners Group Dailey Controls Co (subs. of Babcock & Wilcox Co)	8403300015* 8403300179 8403140072 8403130169	70-27 TOPREP TOPREP GA999

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCE891ON NUMBER	SUBJECT
Baltimore Qas & Electric Co	8403200076+ 8403020300 8403020346+ 8403050078 8403060109	GA999 50-317 50-317 50-318 50-318	F Q P 8	Bechtel Corp	8403150245 8401130363 8403050100* 8403060228* 8403070014*	40-8452 TOPREP 50-318 GA799 50-528
	8403040243 8403040243 8403040400 8403040400 8403130039	50-317 50-317 50-317 50-317 50-318	P P P B		8403090020 8403120015* 8403120015* 8403120017*	FOIA 50-275 50-275 50-275 50-275
	8403130081 8403130098 8403130252 8403130279 8403130295	50-318 50-317 50-317 50-317 50-317	9 9 8 8	Bendix Corp	8403120023* 8403120030* 8403130284 8403230108 8403020374	50-275 50-388 0A999 50-482 WASTE MOT
	8403130299 8403130305 8403130305 8403130314* 8403130314*	50-317 50-317 50-317 50-317 50-317	8 R R R	Bergen Pines Hosp Paramus, NJ Binder, Elster, Mendelson & Wheeler, Inc Biotechnica International, Inc	8403200356 8403220225 8403230038 8403010044* 8403140221	WASTE MOT WASTE MOT 30-322 CONTRACT PRM
	8403130322* 8403130334* 8403130334* 8403130356 8403130413	50-317 50-317 50-317 50-317 50-318	R R R S	Bishop, Liberman, Cook, Purcell & Reynolds	8403070048 8403120007 8403140013 8403140013	50-413 50-508 50-445 50-445
	8403130426 8403130450 8403140036 8403140228 8403150049	50-317 50-318 50-317 50-317 50-317	8 9 J F		8403140020 8403140020 8403150032 8403140029 8403200007	50-445
	8403150047 8403150071 8403150110 8403150110 8403150155	50-317 50-317 50-317 50-317 50-317	Q F F F F	Blanchard Valley Hosp Findlay, DH	8403210170 8403210172 8403210189 8403240367 8403270031 8403080204#	50-508 (50-508 (50-508 (50-413 (50-445 (FOIA
	8403150155 8403160040 8403160040 8403190018 8403190018	50-317 50-317 50-317 50-317 50-317	F የ የ የ	Borg-Warner Corp Boston Edison Co	8403020079 8403150158 8403010324 8403010327* 8403070341*	XPORTLIC XPORTLIC 50-293 , 50-293 ,
	8403190023* 8403190023* 8403190408 8403200003 8403200003	50-317 50-317 50-317 50-317 50-317	F G R R		8403090047 8403090147 8403090152 8403120027 8403130255	50-293 (50-293 , 50-293 , 50-293 , 50-293 ,
	8403220052 8403220052 8403220080 8403240112* 8403240236	50-317 50-317 50-317 50-317 50-317	F F G P		8403140107 8403140279* 9403150009 8403150117* 8403150177	50-293 ; 50-293 ; 50-293 ; 50-293 ; 50-293 ;
Battelle Human Affairs Ressarch Centers	8403260248* 8403300070 8403300100 8403300102 8403070107	50-317 50-317 50-317 50-317 NUREO	P 당 당		8403200164 8403260317* 8403270010 8403270015*	50-293 R 50-293 G 50-293 P 50-293 P 50-293 P
Battelle Memorial Institute, Columbus Laboratories	8403170055 8403050227 8403050230 8403050242 8403040502*	NURED RES SO-280 RES CONTRACT	P	Boston Univ Medical Center, Boston, MA Brandeis Univ Waltham, MA Braunkohle Transport & Storage, Inc	8403270143* 8403130216 8403270301 8403150134 8403150142*	50~293 P PR PRM XPORTLIC XPORTLIC
Hattelle Memorial Institute, Pacific Northwest Laboratories	8403120257 8403230130# 8403300274 8403010041#	REB CONTRACT NUREO FOIA		Bristol Steel & Iron Works, Inc. Brookhaven National Laboratory	B40327014B 8308170191* 8403010041* 6403010217* 8403010227*	GA777 50-447 A FOIA 50-327 A 50-327 A
(NO. 10) - 10 - 10 - 10 - 10 - 10 - 10 - 10	8403020214 8403070093 8403070109 8403070119 8403140170*	NUREO NUREO NUREO PR			8403010227* 8403010231* 8403010231* 8403070115 8403230133	50-329 A 50-329 A 50-329 A NUREO 50-313 P
	8403140131 8403190055 8403190449 8403230112*	OEN TEC NURES NURES 50-217	R	Brown Boveri Corp (subs of Brown Boveri & Co., Ltd)		50-454 A 50-454 A GA979
	8403230173 8403230177	NUR EQ		Buffalo, NY	8403270219 8403080136	50-206 B 50-410 G
Bear Creek Uranium Co.	8403230200 8403230207 8403300132* 8403300248 8403150102	NUREO NUREO 50-478 WASTE MO 40-8452	PT	Businessmen for the Public Interest C-E Operating Plants Owners Group CONOCO, Inc (Continental Oil Co)	8403060079 8403260351 8403130277 8403140131 8403190317	50-454 G 50-454 G TOPREP TOPREP PR
Rearfoot Corp.	8403170436 8403150226 8403150235	40-8452 40-8452 40-8452		California Institute of Technology. Pasadena, CA California, State of	8403260088* 7906140548*	50-344 P 50-312 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	GATE 90	
	8403020117* 8403060260 8403090106 8403260111* 8403270347	50-133 50-275 PR 50-275 50-275	F 0 U		8403090176 8403090205 8403090235 8403090252 8403090252	PR 50-325 50-324 50-324 50-324	8 8 P
	8403270347 8403270352 8403270352 8403270366 8403270366	50-275 50-275 50-275 50-275 50-275	0 0 0 P P		8403070240* 8403070240* 8403120037 8403120076 8403120084	50-324 50-324 50-329 50-400 50-400	P 0 V 8
California, Univ of, Berkeley, CA California, Univ of, Los Angeles, CA Callaway County, MO	8403150115 8403140089 8403260380 8403280241 8403070081	50-224 50-142 50-142 ACRS 50-483	R 0 0		8403130049 8403130062 8403130078 8403130093 8403130152	50-325 50-400 50-324 50-261 50-324	8 8 8
Callendine, Q W Cardinal Industrial Products Corp Carolina Environmental Study Group	8101300020# 8101300025# 8403190203 8403070033 8403070033	FOIA FOIA GA979 50-413 50-413	G G		8403130156 8403130156 8403130164* 8403130164* 8403130237	50-400 50-400 50-400 50-400 50-400	0000
	8403070037* 8403070037* 8403220233 8403220237 8403220379	50-413 50-413 50-413 50-413 50-413	e 0 0 0		8403130301 8403130301 8403130323 8403130333 8403130333	50-324 50-324 50-325 50-324 50-324	8 9 8 8
Carolina Power & Light Co	8403290388 8402230251* 8402270274 8402290081 8402290081	50-413 50-400 50-400 50-400 50-400	G A B G Q		8403130398 8403130406 8403130447 8403130447 8403130452	50-400 50-324 50-400 50-400 50-325	8 9 9
	8403010133 8403010135 8403010202 8403010263 8403010263	50-325 50-324 50-325 50-400 50-400	3 8 8 0 0		8403130459* 8403130459* 8403130465* 8403140120 8403140125*	50-400 50-400 50-325 50-400 50-400	0 P F
	8403010299 8403010350 8403010394 8403010395 8403020182	50-324 50-400 50-400 50-324 50-400	8 8 8 9		8403140174 8403140178* 8403150028 8403150035 8403150070	50-400 50-400 TOPREP 50-325 50-324	0 8 8
	8403020182 8403020188* 8403020188* 8403020192* 8403020192*	50-400 50-400 50-400 50-400 50-400	0 G G		8403150078 8403150161 8403150163* 8403150177 8403150186	50-261 50-261 50-261 50-324 50-324	8 P 8 8
	8403060140 8403060140 8403060167 8403060167 8403060276	50-324 50-324 50-324 50-324 50-324	P P P P		8403160018 8403160262# 8403170065 8403170137 8403170137	50-400 50-261 50-400 50-400 50-400	9 F 0
	8403040274 8403040300 8403040300 8403040302* 8403040302*	50-324 50-324 50-324 50-324 50-324	P P P P		8403170141* 8403170141* 8403170302 8403200030 8403200030	50-400 50-400 50-325 50-400 50-400	9 9
	8403070051 8403070051 8403070055 8403070055 8403070058#	50-400 50-400 50-400 50-400 50-400	0 0 0 0		8403200033 8403200033 8403200117 8403200117 8403200135	50-324 50-324 50-400 50-400 50-400	F
	8403070058* 8403070059* 8403070059* 8403070095* 8403070096*	50-400 50-400 50-400 50-400 50-400	9 9 9 9		8403200135 8403200203 8403200207 8403200245 8403200273	50-400 50-400 50-324 50-241 50-324	9 S S F S
	8403070106* 8403070108* 8403070134 8403070134 8403070157	FDIA FDIA 50-400 50-400 50-324	0 0 P		8403210061 8403210061 8403210075 8403210080# 8403210093	50-324 50-324 50-324 50-324 50-261	P P P
	8403070157 8403070162* 8403070162* 8403070184* 8403070200	50-324 50-324 50-324 50-400 50-324	P P G G		8403210116 8403210123 8403210129 8403210129 8403210131	50-261 50-324 50-324 50-324 50-400	P P A
	8403070225 8403070225 8403070285 8403070290 8403070315	50~400 50~400 50~400 50~400 50~325	ବ ଜ ଖ ଖ		8403210139 8403220261 8403230049 8403230054*	50-325 50-400 50-400 50-325 50-325	9 9 P P
	8403080135 8403080258 8403070023 8403070082 8403070074	50-261 50-261 50-324 50-400 50-261	R R S S F		8403230127 8403260009 8403260024 8403260327 8403260327	50-261 50-400 TOPREP 50-400 50-400	F H 0 9

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8403260328 8403260328 8403260348 8403260348 8403260354#	50-400 50-400 50-400 50-400 50-400	0 0 0 0	Citizens Concerned About Nuclear Power, Inc	8403200147 8403200147 8403140152 8403270025	50-445 50-449 50-498 50-498
	8403260354* 8403270091 8403270235 8403270239* 8403270266	50-400 50-400 50-261 50-261 50-324	9 8 P P 9	Clark Oil & Refining Corp Cleveland Electric Illuminating Co	8403060033# 8402270274 8403020106 8403020106 8403060181	FOIA 50-440 50-440 50-440
	8403270327 8403280024 8403290083 8403290134 8403290164#	50~400 50~400 50~324 50~400 50~400	0 М Р Е С		8403060181 8403060257 8403060257 8403060275 8403060275	50-440 (50-440 (50-440 (50-440 (
Carpenter Technology Corp Center for Law in the Public Interest	8403300034 8403300043 8403050036 8403070128 8403080118	50-400 50-400 XPORTLIC 50-275 50-275	B B C C		84030&0280* 84030&0140 8403120052 8403120076	50-440 50-440 50-440 50-440
	8403070027 8403170011 8403170011 8403170016* 8403170016*	50-275 50-275 50-275 50-275 50-275	P 0 0 0		8403120124* 8403130010 8403130010 8403130092 8403130106*	50-440 (50-440 (50-440 (50-440 (50-440)
	8403220106 8403220104 8403220110* 8403220110* 8403260348	50-275 50-275 50-275 50-275 50-275	G G G G		8403130104* 8403130118* 8403130118* 8403130128* 8403130128*	50-440 / 50-440 / 50-440 / 50-440 /
Center for Nuclear Responsibility	8403070135 8403070135 8403070139* 8403070139* 8403070143*	50-250 50-250 50-250 50-250 50-250	0 0 0 0 0		8403130138* 8403130138* 8403130139 8403130139 8403130194	50-440 A 50-440 A 50-440 G 50-440 G
	8403070143* 8403140017 8403140017 8403140023* 8403140023*	50-250 50-250 50-250 50-250 50-250	0 0 0 0		8403130194 8403130403 8403130403 8403130001 8403150009	50-440 F 50-440 G 50-440 G 50-440 G
Cerac. Inc Chem-Nuclear Systems. Inc	8403010459 8401120525 8401120550* 8403120156* 8403120158*	XPORTLIC WASTE MG WASTE MG 50-413 50-413	G T		8403150009 8403190051 8403190051 8403190375 8403190375	50-440 9 50-440 9 50-440 A 50-440 A
Cincinnati Gas & Electric Co Cincinnati, Univ of Hosp., Cincinnati, OH	8403120161* 8403150316 8403210178 8403230104 8403270259	50-413 27-47 50-358 50-358 PRM	E 0 0		8409190991 8409190391 840929011 840929011 8409230045	50-440 A 50-440 A 50-440 S 50-440 S
Citizens Association for Sound Energy	8403070177 8403070177 8403070181* 8403070182* 8403070182*	50-445 50-445 50-445 50-445 50-445	0 0 0		8403230045 8403230047 8403230083 8403230083 8403230101	50-440 S 50-440 A 50-440 S 50-440 S
	8403090104 8403090104 8403090108* 8403090128 8403090128	50-445 50-445 50-445 50-445 50-445	T T T O		8403230101 8403260247 8403260247 8403270224 8403270224	50-440 9 50-440 9 50-440 0 50-440 0
	8403140034 8403170005 8403170024 8403170024 8403170032	50-445 50-445 50-445 50-445 50-445	Q Q Q Q	Clinton, It. Coalition for Safe Power Colorado State Univ , Ft Collins, CO Colt Industrios, Inc.	8403140040* 8403220049 8403130394 8403230032 8403190248	50-461 0 50-460 0 50-267 R 50-322 T 50-375 8
	8403190032 8403200009 8403200012 8403200012	50-445 50-445 50-445 50-445 50-445	0 0 0 0	Combustion Engineering, Inc	8403190374 8401240340* 8403010276 8403020335* 8403020333*	50-443 S 70-1100 50-470 E 50-362 A 50-362 A
	8403200025 8403200025 8403200026 8403200026 8403200047	50-445 50-445 50-445 50-445 50-445	e e e a		8403050103* 8403040161* 8403130293* 8403130476* 8403140140*	50-318 P GA999 TOPREP 70-1100 TOPREP
	B403200049 B403200073 B403200073 B403200114 B403200114	50-445 50-445 50-445 50-445 50-445	0 0 0	Commerce, Dept of: Commerce, Dept of, Maritime Administration	8403200081 8403200085* 8403270107 7911120366* 8403050111	50-470 K 50-470 K 50-470 E 50-31P P 50-238 R
	8403200118 8403200118 8403200126 8403200126	50-445 50-445 50-445 50-445	Q Q Q	Commerce. Dept of, National Bureau of Standards Committee to Bridge the Gap	840309Q214 840320Q021	PR 50-142 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	₹Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
Commonwealth Edison Co	8403010083 8403010083 8403010087* 8403010087* 8403010087	50-454 50-454 50-454 50-454 50-454			8403060113 8403060117# 8403060121# 8403060127# 8403060127#	50-254 50-254 50-254 50-254 50-254	R R R R
	B403010093* B403010106 B403010106 B403010106 B403010106	50-254 50-454 50-454 50-454 50-454	P A A A		8403040150 8403040150 8403040217 8403040217 8403060245	50-373 50-373 50-295 50-295 50-454	R R R G
	8403010106 8403010120 8403010120 8403010120 8403010120	50-454 50-454 50-454 50-454 50-454	A E E E		8403060245 8403060245 8403060245 8403060245 8403060249	50-454 50-454 50-454 50-454 50-295	9 0 0 0
	8403010120 8403010130 8403010286 8403010286 8403010286	50-454 50-454 50-454 50-454 50-454	E G E E		8403060267# 8403060273 8403060279# 8403060345 8403060345	50-454 50-254 50-254 50-454 50-454	0 P E
	8403010284 8403010284 8403010403 8403020003 8403020131	50-454 50-454 50-454 50-295 50-295	E F F P		8403060374 8403060374 8403060374 8403060374 8403060374	50-454 50-454 50-454 50-454 50-454	**
	8403020131 8403020134 8403020134 8403020138 8403020140	50-275 50-275 50-275 50-273 50-275	P 0 0 R 0		8403070347 8403070347 8403080174 8403080197 8403080197	50-454 50-454 50-304 50-10 50-10	F Q R
	8403020140 8403020146* 8403020146* 8403020181 8403020181	50-295 50-295 50-295 50-454 50-454	0 0 0 0 0		8403080197 8403080197 8403080197 8403080197 8403080197	50-10 50-10 50-10 50-10 50-10	R R R R
	8403050002 8403050002 8403050043 8403050043 8403050043	50-254 50-254 50-10 50-10 50-10	0 0 0 0 0		8403080197 8403080197 8403080197 8403090164 8403090174	50-10 50-10 50-10 50-275 50-304	R R B
	8403050043 8403050043 8403050043 8403050043 8403050043	50-10 50-10 50-10 50-10 50-10	Q Q Q Q		8403070185 8403070191* 8403070194* 8403070274 8403120013	50-237 50-237 50-237 50-254 50-456	P P F Ø
	8403050043 8403050043 8403050043 8403050043 8403050043	50-10 50-10 50-10 50-10 50-10	Q Q Q Q		8403120020 8403120047 8403120054 8403120080 8403120095	50-373 50-374 50-373 50-373 50-373	8
	8403050043 8403050046# 8403050046# 8403050046# 8403050046#	50-10 50-10 50-10 50-10 50-10	0 0 0 0 0		8403120107 8403120128 8403120128 8403120162 8403120162	50-265 50-373 50-373 50-454 50-454	8
	8403050046* 8403050046* 8403050046* 8403050046* 8403050046*	50-10 50-10 50-10 50-10 50-10	0 0 0 0 0		8403130015 8403130015 8403130070 8403130070 8403130102	50-237 50-237 50-237 50-237 50-265	R P P
	8403050046* 8403050046* 8403050046* 8403050046* 8403050063	50-10 50-10 50-10 50-10 50-373	a a a F		8403130353 8403130353 8403130359* 8403130370 8403130382	50-254 50-254 50-373 50-249 50-254	P 0 0
	8403050119 8403050119 8403050119 8403050119 8403050119	50-237 50-237 50-237 50-237 50-237	P P P P		8403130382 8403130400 8403130400 8403130400 8403130410	50-254 50-237 50-237 50-237 50-237	R P P
	8403050119 8403050119 8403050119 8403050119 8403050119	50-237 50-237 50-237 50-237 50-237	የ የ የ		8403130410 8403130418* 8403130418* 8403140001 8403140001	50-237 50-237 50-237 50-456 50-456	# # 0 0
	8403050117 8403050119 8403050119 8403050119 8403050119	50-237 50-237 50-237 50-237 50-237	P P P P		8403140082 8403140151 8403140175 8403140170 8403140170	50-295 PR 50-373 50-454 50-454	F F F
	8403050171* 8403050174* 8403060099 8403060099 8403060099	50-373 50-373 50-10 50-10 50-10	© © R R		8403150019 8403150019 8403150044 8403160011 8403160011	50-254 50-254 50-454 50-456 50-456	R R F O

AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJECT CATEOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOOR'
	8403160023 8403160023 8403160027 8403160261 8403160266	50-456 50-456 50-265 50-373 50-374	0 0 9 R 8		8403230124* 8403230124* 8403230126* 8403230126* 8403230126*	50-10 50-10 50-10 50-10 50-10
	8403170001 8403170075 8403170070* 8403170070* 8403170117	50-249 50-254 50-373 50-373 50-373	0 G G E 5		8403230126# 8403260122 8403260132 8403260132 8403260132	50-10 50-373 50-454 50-454 50-454
	8403170156 8403170156 8403170173 8403170173 8403170175	50-275 50-275 50-456 50-456 50-275	ਜ ਜ ਚ 5 ਵ		8403260132 8403260132 8403260182 8403260182 8403260194	50-454 50-454 50-295 50-295 50-374
	8403190274* 8403190308 8403200013 8403200013 8403200032	50-454 50-454 50-373 50-373 50-373	0 F P P		8403240174 8403240174 8403240174 8403240174 8403240223	50-237 50-237 50-237 50-237 50-237
	8403200041 8403200106 8403200122 8403200173 8403200188	50-373 50-245 50-454 50-304 50-265	F 9 8		8403260225 84032602374 8403260260 8403260346 8403260346	50-373 50-454 50-237 50-454 50-454
	8403200196 8403200204 8403200206 8403200212 8403200256	50-249 50-373 50-373 50-374 50-373	G 8 F 8 Q		8403250361 8403270035 8403270056 8403270089 8403270109	50-454 50-295 50-237 50-237 50-295
	8403200256 8403200263* 8403200263* 8403210085 8403210085	50-373 50-373 50-373 50-373 50-373	Q Q Q K K		8403270111 8403270111 8403270130 8403270130 8403270144*	50-454 50-454 50-249 50-249 50-249
	8403210089 8403210091* 8403220120 8403220120 8403220120	50-295 50-373 50-10 50-10 50-10	F K R R		8403270144* 8403270175 8403270203 8403270265 8403280023	50-249 50-254 50-275 50-275 50-374
	8403220120 8403220120 8403220120 8403220120 8403220120	50-10 50-10 50-10 50-10 50-10	R R R R	Connecticut Yanker Atomic Power Co	8403280073 8403280119 8403010340 8403010391 8403020093	50-374 50-295 , 50-213 , 50-213 ,
	8403220120 8403220120 8403220123 8403220123 8403220127*	50-10 50-10 50-373 50-373 50-373	R R F F		8403050105 8403040325 8403090137 8403090272 8403090289	50-213 ; 50-213 ; 50-213 ; 50-234 ;
	8403220127* 8403220133 8403220133 8403220133 8403220138*	50-373 50-454 50-237 50-237 50-237	F A P P P		8403130027 8403130027 8403130283 8403130289* 8403140014	50-213 . 50-213 . 50-213 . 50-213 .
	8403220158* 8403230015 8403230017 8403230027 8403230081*	50~237 50~373 50~373 50~373 50~373	P 8 8 9 0		8403140116 8403190155* 8403190280 8403230022 8403230022	50-213 (FR 50-213 ; 50-213 ;
	8403230087 * 8403230096 8403230107 * 8403230107 * 8403230107 *	50-373 50-237 50-10 50-10 50-10	0 8 0 0		8403230136 8403260143 8403260143 8403260143 8403260143	50-213 (50-213 (50-213 , 50-213 ,
	8403230107# 8403230107# 8403230107# 8403230107# 8403230107#	50-10 50-10 50-10 50-10 50-10	G G G G G		8403260146 8403260146 8403260146 8403260131* 8403260151*	50-213 . 50-213 . 50-213 . 50-213 F 50-213 F
	8403230107# 8403230107# 8403230107# 8403230107# 8403230107#	50-10 50-10 50-10 50-10 50-10	0 0 0 0		8403260151* 8403260162 8403260252 8403270008 8403270068	50-213 F 50-213 P 50-213 P 50-213 F 50-213 F
	8403230107# 8403230124 8403230124 8403230126# 8403230126#	50-10 50-295 50-295 50-10 50-10	Q F F Q Q	Connecticut. State of	8403270278 8403300144 8403300166* 8403300176 8403140025	50-213 P 50-213 0 50-213 0 50-213 R 50-443 9
	8403230126* 8403230126* 8403230126* 8403230126*	50-10 50-10 50-10 50-10 50-10	0 0 0 0 0	Conner & Wetterhahn	8403020077 8403020077 8403020125 8403020125 8403020127	50-352 Q 50-352 Q 50-352 Q 50-352 Q 50-352 T

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO EUBJEC		AUTHDR AFFILIATION	ACCEBBION NUMBER	CATEOD	
	8403020163 8403020163 8403040081 8403040081 84030400248	50-352 50-352 50-352 50-352 50-352	0000		8403080024 8403080131 8403080141 8403080171 8403080171	50-329 50-155 50-155 50-329 50-329	8 8 8
	8403040248 8403070142 8403070142 8403070234 8403070234	50-352 50-352 50-352 50-352	00000		8403080184 8403080187 8403080187 8403080206 8403080222	50-255 50-329 50-329 50-255 50-329	R 8 8 8
	8403070238* 8403070238* 8403150020 8403150022* 8403150024	50-352 50-352 50-354 50-354 50-352	0000		8403080222 8403080230 8403080230 8403080235 8403080235	50-329 50-329 50-329 50-329 50-329	8 8
	8403160010 8403160010 8403200018 8403200060 8403200090	50-352 50-352 50-416 50-352 50-352	0		8403060241 8403060241 8403060245 8403060245 8403060247	50-329 50-329 50-329 50-329 50-329	A 8 8
	8403200070 8403200102 8403210092 8403210092 8403210103	50~352 50~354 50~352 50~352 50~352	0 0 0		8403080247 8403080248 8403080248 8403080259 8403080259	50-329 50-329 50-329 50-329 50-329	8 A B
	8403210103 8403210178 8403260349 8403270012 8403270042	50-352 50-358 50-352 50-352 50-352	0 0 0 0 T		8403080262 8403080262 8403090229 8403120035 8403120041	50-329 50-329 50-155 50-155 50-255	A F Q R
	8403290384 8403290384 8403290392 8403300127 8403300127	50-352 50-352 50-459 50-352 50-352	9 9		8403120131 8403120131 8403120140 8403130050 8403130050	50-155 50-155 50-255 50-329 50-329	0 0 R 8 8
	8403300128 8403300128 8403300127 8403300127 8403300270	50-352 50-352 50-352 50-352 50-354	9 9		8403130161 8403130161 8403130168* 8403130168* 8403130189	50-329 50-329 50-329 50-329 50-329	B A A
Consolidated Edison Co. of New York, Inc	8403300271 8403300271 8403010293 8403020155 8403050015*	50-352 50-352 70-1621 50-247 50-247	G G R G		8403130189 8403130210 8403130210 8403130254 8403130254	50-329 50-329 50-329 50-329 50-329	8 0 0
	8403090095 8403090098* 8403090101* 8403090288 8403130405	50-247 50-247 50-247 50-3 50-247	P P F 8		8403130261 8403130261 8403130292 8403130292 8403130354	50-329 50-329 50-329 50-329 50-329	A 8 8
	8403150029 8403190069 8403190296 8403190355 8403200124	50-247 50-3 50-286 50-247 50-247	0 F F P		8403130354 8403130362 8403130362 8403130471 8403130471	50-329 50-329 50-329 50-329 50-329	8 8 8
	8403210154 8403230135 8403230135 8403260120 8403260120	50-247 50-3 50-3 50-3 50-3	9 R R R		8403140021 8403140021 8403140032 8403140072 6000316003	50-329 50-329 50-329 TOPREP 50-329	
	8403270186 8403270193 8403270204 8403290170 8403290172	50-247 50-247 50-247 50-247 50-247	R P B P O		8403150003 8403150145 8403170004 8403170071 8403170071	50-329 50-255 50-155 50-155 50-155	P Q I
Consumers Power Co	8403270268 8403010203 8403020068 8403060073 8403060073	50-247 50-155 50-155 50-329 50-329	0 17 0		8403170071 8403170078 8403170078 8403170101 8403170166	50-155 50-329 50-329 50-255 50-329	A
	8403040104 8403040104 8403040188 8403040192* 8403040202*	50-329 50-329 50-155 50-155 50-155	8 9 9		8403170146 8403200011 8403200011 8403200027 8403200037	50-329 50-329 50-329 50-329 50-329	0 0 A
	8403060269 8403060269 8403060272 8403060272 8403060356	50-327 50-327 50-327 50-327 50-155	8 8 8 8		8403200037 8403200130 8403220007 8403220016 8403220016	50-329 50-155 50-329 50-329 50-329	0 Q Q
	84030A0424 84030A042A 8403070008 8403070300 840308002A	50-320 50-320 50-329 50-255 50-329	. 8 . 8 . 8		8403220025 8403220025 8403220067 8403220067 8403220072	50-329 50-329 50-329 50-329 50-329	# # #

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT		AVTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	8403220072 8403220078 8403220108 8403220108 8403220179	50-329 50-255 50-329 50-329 50-329	8 P 8 8 A		8403190079 8403200185 8403210048 8403210074 8403210076*	50-341 50-341 50-341 50-341 50-341	A A A
	8403220179 8403220202 8403220202 8403230031 8403230093	50-329 50-329 50-329 50-329 50-255	A A O P		8403230018 8403230021* 8403240127 8403270043 8403300138	50-341 50-341 50-341 50-341 50-341	A G A
	8403230098* 8403230114 8403230114 8403260115 8403270007	50-255 50-329 50-329 50-255 50-329	P A A P	Doherty: J F Dow Chemical Co	8403130057 8403270002 8401260167* 8403050012 8403050013*	50-456 50-443 50-264 50-264 50-264	D G F F
	8403270009 8403270014 8403270014 8403270020 8403270020	50-327 50-327 50-327 50-329 50-329	A A O O	Drexel Univ , Philadelphie, PA Duke Power Co	8403120244* 8403120252* 8402210150 8403010140 8403010308	50-335 50-335 50-367 50-413 50-269	Q Q R B
	8403270023 8403270023 8403270029 8403270029 8403270064	50-329 50-329 50-329 50-329 50-155	5 8 8 8		8403010335 8403020317 8403020317 8403020317 8403020317	50-413 50-369 50-369 50-369 50-369	E E E
	8403270169 8403270169 8403270199 8403270199 8403270236	50-329 50-329 50-329 50-329 50-329	8 6 8		8403020317 8403020321* 8403020321* 8403020321* 8403020321*	50-369 50-369 50-369 50-369 50-369	E E E
	8403270236 8403270055* 8403270187 8403270247 8403200070	50-329 FOIA 50-155 50-155 50-329	В Р А		8403020321* 8403040104 8403040225 8403040232 8403040232	50-269 50-269 50-269 50-370 50-413	8 6 8
Control Date Corp Cresap, McCormick & Paget Crystal River, FL Cygna Energy Services	8403300152 8403040135 8403140038* 8403230154* 8403070126	50-155 FOIA 50-329 CONTRACT 50-445	R A O		8403060240 8403960272 8403060336 8403060417 8403060417	50-413 50-247 50-413 50-413 50-413	9 F F F
Deirgiand Power Cooperative	BA03270115 BA03020161 BA030B0031 BA030B0236 BA031200B3	GA999 50-409 50-409 50-409 50-409	R R R G		8403060422 8403070048 8403070048 8403070185 8403070202*	50-413 50-413 50-413 50-413 50-413	A @ O A A
	8403130290 8403130335* 8403160047 8403200112* 8403200163	50-409 50-409 50-409 50-409 50-409	P G F F 8		8403070210* 8403070219* 8403070331* 8403070352 8403080239	50-413 50-413 50-349 50-249	0 A G F V
	8403230002 8403290283 8403290287* 8403300089 8403300093*	50-409 50-409 50-409 50-409 50-409	P P P		8403080239 8403080239 8403090222 8403090222 8403090222	50-269 50-269 50-269 50-269 50-269	V V F F F
Dellas Horning News Dames & Moore Dataflow Bystems, Inc.	8403300131 8403060164 8403060347* 8403020073* 8403020077*	50-407 FOIA 50-454 CONTRACT			8403070226 8403070226 8403070241 8403070254 8403070276	50-413 50-413 50-413 50-269 50-369	8 8 8 F F
DeKalb Area Alliance for Responsible Energy	B403160002 B403160002 B403160019 B403160019	50-454 50-454 50-454 50-454	0 0 0 0		8403120150 8403120153 8403120173 8403130071 8403130071	50-370 50-413 50-370 50-413 50-413	0 8 8
Debevoise & Liberman Decision Research, Inc Del-Aware Unlimited, Inc. Delaware, State of	8403080324 8403170444 8403130411 8403020141 8403070214	50-445 NUREQ 50-352 50-354 PR	e o		B403130077# B403130077# B403130086 B403130104 B403130142#	50-413 50-413 50-413 50-413 50-244	e e a a r
Deltak Corp Detroit Edison Co,	8403010149 8403010153* 8403020121 8403040173* 8403040177*	71-511 71-511 50-341 50-341 50-341	A G G		8403130149* 8403130157* 8403130167 8403130332 8403130341	50-244 50-244 50-370 50-369 50-370	R S S P
	8403090247 8403120009 8403120068 8403120155	50-341 50-341 50-341 50-341	V 5 9 9		8403130344* 8403140231 8403150045 8403150128 8403150128	50-370 50-349 50-413 50-413 50-413	P 8 8
	8403120160 8403130008 8403130044 8403130060* 8403150021	50-341 50-341 50-341 50-341	8 K K V		8403150138 8403150154 8403140028 8403140029 8403140029	50-370 50-349 50-413 50-413 50-413	6 t

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOR	
	8403160143 8403160143 8403160197 8403160216* 8403160253	50-413 50-413 50-413 50-413 50-413	0 G A Q	**	8403170317* 6403170324* 6403200040 6403200233 8403200234	50-334 50-334 50-334 50-334 50-412	R R F
	8403140253 8403140299* 8403140313* 9403190257 8403190257	50-413 50-413 50-369 50-369 50-369	0 0 P P		8403210058 8403210130 8403240059 8403240140 8403270215	50-412 50-412 50-412 50-334 50-334	8 C R F
	8403190289 8403190303 8403190394 8403190394 8403200007	PR 50-370 50-413 50-413 50-413	B A A Q		8403280017 8403290145 8403290146# 8403290204# 8403300062	50-334 50-412 50-412 50-412 50-412	F C G A
	8403200010 8403200010 8403200010 8403200078 8403200123	50-269 50-269 50-269 50-413 50-369	R R E R	E@&O, Inc	8403300181 8403300200 8402280725* 8403070395* 8403260335	50-334 50-412 50-267 50-315 50-416	R G P P
	8403200123 8403200145 8403200165 8403200221 8403200221	50-349 50-413 50-413 50-413	R A P F		8403270329 8403280113 8403280117 8403280124 8403280332	RES 50-313 50-368 50-368 50-338	9 8 8
	8403220038 8403220038 8403220044* 8403220044*	50-367 50-367 50-369 50-369	P P P	Corp)	8403270054* 8403070332* 8403230123*	GA799 TOPREP 50-219	R
	8403220074 8403220074	50-413 50-413	A	Eddleman, W	8403050061 8403130001	50-40D 50-40D	6 6
	8403240034 8403240073 8403240080* 8403240139*	50-413 50-413 50-413 50-413	A A A		8403130184 8403130176* 8403130220* 8403130230* 8403200048	50-400 50-400 50-400 50-400 50-400	00000
	8403240347 8403240347 8403270011 8403270103 8403270209	50-413 50-413 50-413 50-413 50-249	0 0 0 0		8403220222 8403220227 8403220265 8403220270 8403280344	50-400 50-400 50-400 50-400 50-400	00000
	8403270213 8403270213 8403270230 8403270230 8403270243	50-413 50-413 50-369 50-369 50-369	A F F P		8403280347 8403280349 8403280351 8403280360 8403280361	50-400 50-400 50-400 50-400 50-400	0 0 0 0
	8403270243 8403280102 8403270082* 8403270148 8403270148	50-349 50-413 50-249 50-349 50-349	P G P P	Edelstrin & Payne Edison Electric Institute	8403120002 8403130368 8403010454 8403010456*	50-400 PR XPORTL 10 XPORTL 10	e c
	8403270154* 8403270164* 8403270244 8403270244 8403270267	50-369 50-369 50-413 50-413 50-369	P P S S P		8403270074* 8403280037 8403220240 8403170424 8403170282* 8402170325	40-8760 XPORTL16 CONTRAC 40-8681 50-312 WASTE MG	c T
	6403270267 8403270273* 8403270273* 8403270276* 8403270314	50-369 50-369 50-369 50-413 50-270	P G G	Energy, Sept or	8403010356 8403060082 8403060357 8403060360* 8403060517	WASTE M 50-537 50-537 50-537	OT C A A
	8403300079 8403300079 8403300107 8403300126 8403300188	50-413 50-413 50-413 50-413 50-413	E A B A		8403040521* 8403040056 8403090217 8403140166 8403140312	WASTE ME 50-537 50-537 PR WASTE ME	OT O A
uquesne Light Co	8403010124 8403010387 8403020084 8403040134 8403040297	50-334 50-412 50-334 50-334 50-334	R A R S		8403200314 8403200348 8403220112 8403220303 8403220322	WASTE MO WASTE MO WASTE MO WASTE MO XFORTLIO	0T 0T 0T 0T
	8403070243 8403070244* 8403070269 8403070298 8403070308*	50-334 50-334 50-334 50-412 50-412	R R R S G	Energy, Dept of, Clinch River Breeder Reactor Plant	8403220324* 8403230245 8403300237 8403080090	XPORTLIC WASTE MC WASTE MC 50-537	C OT
	8403070344* 8403070366* 8403120172*	50-334 50-334 50-334	Q R Q	Energy, Dept of, Idaho Operations Office Engineering Planning & Management, Inc	8403060085	WASTE M	
	8403130051* 8403130374 8403150095	50-341 50-412 50-412	K S C	Engineers International, Inc Environmental Protection Agency	8403240350* 8403020174 8403130180 8403190289	WASTE MI WASTE MI 50-508 PR	
	84031 600 90 84031 60 1 90 84031 901 52 84031 902 76	50-412 50-412 50-412 50-334	A A R	Ertec, Inc. European Communities, Commission of	8403200104 8403140328* 8403060075	50-456 CONTRAC XPORTL I	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Extran, Inc	8403200305 8403220230 8403220284 8403260011 8403270280	XPORTLIC XPORTLIC XPORTLIC XPORTLIC MISC		6403060168 6403060166 6403060241 6403060291 6403060291	50-250 P 50-389 F 50-389 P 50-250 Q 50-250 Q
Exxon Corp Exxon Nuclear Co , Inc (subs of Exxon Corp)	8402140327# 8403260142* 8403060421#	40-8102 40-8102 70-1257		8403040340 8403040390 8403070034 8403070249	50-335 F 50-389 S 50-335 Q 50-389 Q
	8403040533 8403070127	NUREG TOPREP		8403080020 8403080020	50-250 P 50-250 P
	8403080205 8403080210* 8403080214* 8403080220* 8403080223*	90-316 P 90-316 P 90-316 P 90-316 P		8403080164 8403080164 8403070280 8403120040	50-335 V 50-335 V 50-335 F 50-389 P
	8403150097 8403150104* 8403200100 8403200101* 8403230102*	50-314 P 50-314 P 50-314 P 50-314 P 50-255 P		8403120089 8403130045 8403130046 8403140013 8403140013	50-387 P 50-387 B 50-335 P 50-389 P 50-389 P
	8403230106* 8403230111* 8403240037 8403240042* 8403260219	50-255 P 50-255 P XPORTLIC XPORTLIC TOPREP		8403140038 8403140058 8403140059 8403190171 8403190171	50-251 S 50-250 B 50-251 S 50-250 0 50-250 0
FOI Services Failure Analysis Associates Faderal American Partners	B40302000B B403280166 B403010446* B4031400B6* B403200374	FOIA FOIA 50-322 8 50-322 8 40-4492		8403170177* 8403170177* 8403170227 8403170228* 8403170386	50-250 G 50-250 G 50-289 P 50-389 P 50-335 F
Federal Emergency Management Agency	8403220054* 8403050128 8403050131* 8403050148 8403050172*	40-4492 50-440 F 50-440 F 50-206 F 50-206 F		8403170386 8403200264 8403200264 8403200266# 8403200266#	50-335 F 50-250 P 50-250 P 50-250 P 50-250 P
	8403040084 8403070020 8403070020 8403070022* 8403070022*	50-250 F 50-443 G 50-443 O 50-443 G		8403200270* 8403200270* 8403220070 8403220104 8403230014	50-250 P 50-250 P 50-335 S 50-250 S 50-302 P
	B40308023B 8403080242* B403080244* B403070218 B403070221*	50-263 F 50-263 F 50-263 F 50-155 F 50-155 F		8403240203 8403270247 8403280110 8403290114* 8403290114*	50-250 P 50-335 F 50-250 F 50-335 Q
	8403130155 8403130163 8403130172* 8403130178* 8403130185	50-254 F 50-262 F 50-262 F 50-262 F 50-265 F		8403290123 8403300173 8403300173 8403300173 8403300173	50-250 G 50-250 R 50-250 R 50-250 R 50-250 R
	8403130178 8403130207* 8403130417 8403150018 8403150052	50-263 F 50-263 F 0RQ 50-293 F 50-416 F		8403300173 8403300185* 8403300185* 8403300185*	50-250 R 50-250 R 50-250 R 50-250 R 50-250 R
	8403150113 8403150113 8403150119* 8403150119* 8403150200	50-313 F 50-313 F 50-313 F 50-313 F 50-315 F	Florida Power Corp	8403300185* 8403300193* 8403300193* 8402060419 8402060421*	50-250 R 50-250 R 50-250 R 50-302 P 50-302 P
	8403150203* 8403170131 8403170363 8403200035* 8403230120	50-315 F 50-322 G 50-322 F 50-317 F 50-317 F		8403010072 8403060283 8403060243 8403060259 8403060362*	50-302 F 50-302 P 50-302 P 50-302 P
Firex Corp Fisher, Harden & Fisher Florida Power & Light Co.	8403240117* 8403070075 8403150340* 8401130182 8401130296	50-322 F PRM 40-8829 50-389 P 50-335 P		8403060364 8403060366* 8403060368* 8403060402 8403090193	50-302 P 50-302 P 50-302 P 50-302 G 50-302 S
	8401130319 8402270125 8403010297 8403010302* 8403010400	50-335 P 50-387 E 50-387 P 50-387 P 50-387 P		8403120130 8403140034 8403140315 8403140320* 8403200038	50-302 P 50-302 R 50-302 P 50-302 P 50-302 P
	8403010400 8403020238 8403020278 8403020278 8403040112	50-250 R 50-250 V 50-250 V 50-250 G 50-235 F		8403200044* 8403200265 8403230062 8403230067* 8403270159	50-302 P 50-302 P 50-302 P 50-302 P 50-302 P
	8403040112 8403040116# 8403040148 8403040148	50-335 F 50-250 P 50-250 P 50-250 P	Fjorida, State of Fjuorocarbor Co	8403290162* 8403300111 8403300115* 8403090106 8403050102	50-302 P 50-303 8 50-302 S PR GA777

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	PRY	AUTHOR Affiliation	ACCESSION NUMBER	BUBJECT CATEGORY	,
	8403060355* 8403060361* 8403060365* 8403060367* 8403060372*	GA799 GA799 GA799 GA799 GA797			8403060236# 8403070203 8403080039 8403080178 8403080231	50-267 50-219 50-269 50-320	P H P F
Food & Drug Afministration Foxboro Corp	B403060374* B403060376* B403060379* B403160026 B403010409	GA999 GA999 GA999 50-352 FOIA	σ		8403080267 8403090036 8403090073* 8403090125 8403090244	50-320 50-219 50-289	р С С Р
Franklin Institute/Franklin Research Center	8403120244#	50-335	Q.		8403070264 8403120004		F
Friends of the Earth	8403120252* 8403150045* 8403270368* 8403190132	50-335 50-237 CONTRAC' 50-352	0 F 7 9		8403120016 8403120054 8403120102#	50-289	P Q F
Ft Hamilton-Hughes Memorial Mosp	8403170138* 8403170142* 8403270272 8010230503*	50-352 50-353 PRM FOIA	9		8403130199 8403130284 8403130428 8403130439*	50-219 50-289 50-320 50-320	P ₹ P
Center, Hamilton, OH	8403080113*	FOIA			8403130475 8403130483*	50-320 50-320	R R
Fulton, MO GA Technologies, Inc./General Atomic Co GH-Dettis Co	8403070081 8403150197 8403150199* 8403050170	50-403 XPORTL I XPORTL I PT21	IC .		8403130487# 8403140088 8403150083	50-320 50-289 50-219	R F P
Gage-Babcotk Associates, Inc	9403120226*	CONTRAC			8403150118 8403150141	50-320 50-259	F R P
Oasconade County, MD General Accounting Office	8403070094 8107200104+ 84032800B1+	50-483 FOIA FOIA	r		8403160006 8403160022* 8403160024	50-289 50-289 50-289	P
General Electric Co	8402100259 8403010084	TOPREP XPORTL I	ıc		8403160057	50-219	R P
	B40301047B B403010499	XPORTL I	IC .		8403160204* 8403160208*	50-219 50-219 50-219	P Q
	8403010505 8403010522 8403010539	XPORTL II XPORTL II XPORTL II	(C		8403170043 8403170217*	50-219 50-320	F G
	8403010540 8403010546* 8403010550*	XPORTL IO XPORTL IO XPORTL IO	c c		6403170387 6403200056 8403200068 8403200077	PR 50-219 50-289 50-289	Q R P
	8403020043* 8403020089	50-10 XPORTL I	P (C		8403200201 8403200208*	50-320 50-320	P P
	8403050039 8403050241 8403060393* 8403060409	XPORTL 10 XPORTL 10 50-298 TOPREP	a a		8403210059 8403210064# 8403210071#	50-320 50-320 50-320	R R
	8403070353 8403070381# 8403130024 8403130044#	XPORTLIC XPORTLIC QA999 QA999			8403210076 8403210082* 8403210088* 8403210138 8403210141	50-287 50-287 50-287 50-287 50-287	R R R
	8403130282 8403130285 8403130387	PR TOPREP PT21			8403210146# 8403210146# 8403220002	50-269 50-289 50-219	R R P
	8403140006 8403140172 8403150072 8403150107	TOPREP PR 50-73 TOPREP	R		8403220012 8403220141 8403220152	50-219 50-289 50-219	P F
	8403150189* 8403200242 8403200244 8403200271	50-352 50-70 50-18 50-245	G R R P		8403220155* 8403220195 8403230001 8403230040	50-217 50-320 50-287 50-287	P H P
	8403230184 8403270022*	50-554	Q		8403230053 8403230110	50-287 50-217 50-217	PR
	8403270024# 8403270024# 8403270136# 8403290255 8403300088	50-273 50-273 50-247 PR TOPREP	P P P		8403230119 8403230122* 8403260074 8403270073	50-217 50-217 50-219	R R
General Physics Corp Gameral Public Utilities - GPU Service Corp	8403300342 8403010256	NUREO 50-219	9		8403270123 8403270127* 8403270127* 8403270144	50-320 50-320 50-320 50-289	Р Р
	8403010261* 8403010347 8403020128	50-219 50-289 50-219	8 F R		8403270165 8403270210 8403270212*	50-219 50-320 50-320	P
	8403020318 8403020323* 8403050070	50-320 50-320 50-219	р Р Р		8403270232 8403280006	50-289 50-320	F 8
	8403050097 8403050151	50-289 50-320	F F		8403280010 8403280010	50-289 50-289	J J
	8403050133 8403050133	50-287 50-287	F		8403290015 8403290386 8403300001	50-219 50-289 50-219	H Q R
	8403040159 8403040160	50-289 50-289	P P		8403300031	50-320	P
	8403060222 8403060227*	50-289 50-289	P P	Geochemistry & Environmental Chemistry Research, Inc.	8403050315 8403050318*	WASTE H	ют
	8403040233	50-289	P		8403050317*	WASTE H	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	CATEG	
Georgia Power Co	8403050322* 8403050323* 8403010319 8403010319 8403010325*	WASTE MG WASTE MG 50-424 50-424		Quild, R	8403070037* 8403090112 8403090112 8403090115*	50-413 50-413 50-413 50-413 50-413	0000
	8403010325* 8403010330 8403010354 8403050085 8403060090	50-424 50-321 50-424 50-321 50-424	K 5 9 P 0	Qulf & Western Industries, Inc	8403220233 8403270379 8403270388 8403070178 8403070200*	50-413 50-413 50-413 PT21 PT21	0 0
	8403070281 8403070251 8403090067 8403090097 8403090097	50-321 50-321 50-321 50-424 50-424	P P F S S	Qulf States Utilities Co	8403090202* 6403090203* 6403140136 8403010073 8403010228	PT21 PT21 PT21 50-458 50-458	9
	8403090187 8403090187 8403090196* 8403090196* 8403090228	50-321 50-321 50-321 50-321 50-321	р Р Р В		8403010321 8403010321 8403010379 8403020294 8403050078	50-458 50-458 50-458 50-458 50-458	A A A A
	8403070282 8403120031 8403120146 8403130004 8403130165	50-321 50-366 50-424 50-321 50-321	F 8 8 F F		8403050078 8403060320 8403070010 8403070052 8403070052	50-458 50-458 50-458 50-458 50-458	8 4 4
	8403130165 8403130346 8403130346 8403150023 8403150038	50-321 50-321 50-321 50-424 50-424	F F H V		8403070061 8403070061 8403070062 8403080378 8403080378	50-458 50-458 50-458 50-458 50-458	AAEAA
	8403150038 6403150043 8403150043 8403150069 8403150069	50-424 50-424 50-424 50-424 50-424	3 a a a a a a a a a a a a a a a a a a a		9400110049 7410110048 9910110048 4420110048 EPECG1EO48	50-458 50-458 50-458 50-458 50-458	E A B F
	B403150071 B403150071 B403160031 B403160044 B403160349*	50-321 50-321 50-344 50-321 50-321	R R S Q		8403130488* 8403130486 8403130486 8403130487* 8403160310	50-458 50-458 50-458 50-458 50-458	9 F F S
	8403160349* 8403190026 8403190105 8403190105 8403200005	50-321 50-366 50-424 50-424 50-321	8 8 8 9		8403170017 8403200034 8403210069 8403220207 8403260180	50-458 50-458 50-458 50-458 50-458	E A A
	8403200005 8403200242 8403240086 8403240117 8403240170	50~321 50~366 50~366 50~366 50~321	E 8 6 5		8403260291 8403270026 8403270039 8403270045 8403270076*	50-458 50-458 50-458 50-458 50-458	A 9 8 0
	8403260191 8403290037 8403290194* 8403290194* 8403290212*	50~366 50~424 50~366 50~366 50~321	8 0 0	Harmon & Weiss	8403270201 8403280032 8403290392 8403020173 8403070147	50-458 50-458 50-456 50-443 50-322	5) M G G T
	8403290212# 8403300104 8403300104 8403300143 8403300143	50~321 50~321 50~321 50~321 50~321	0 8 8 F		8403070232 8403240382 8403290005 8403300243 8403300259	50-443 50-289 50-289 WABTE M	0 6 8 9 9
Gaorgia, State of Georgians Against Nuclear Energy Gatty/Petrotomics Co. Gilbert Associates, Inc	8403300339 8403130457 8403020126 8403260242 8403060414#	50~321 50~424 50~424 40~6659 50~302	F G G	Harshbarger & Associates Harvard Univ , Cambridge, MA Health Physics Associates, Ltd	8403300263 8403080409# 8403140172 8403190362 7904030132*	50-443 50-528 PR PRM FD1A	O A
Golder Associates Government Accountability Project	8403070327* 8403270188* 8403270187* 8403010004* 8402140014	TOPREP 50-244 50-244 CONTRACT 50-528	P P Q	Health Physics Society Halgeson Nuclear Services, Inc Henry Ford Hosp , Detroit, MI Henry Pratt Co	7904030135* 8403230069 8403050156* 8403210107 8403230028	FOTA PRM 40-672 PRM 50-389	8
	8403010192 8403010488 8403020102 8403040303* 8403080085	50-327 50-327 FOIA 50-275 50-275	A A G E	Hodder, M H	8403070143* 8403140017 8403140017 8403140023* 8403140023*	50~250 50~250 50~250 50~250 50~250	0 0 0
	8403080196 8403150010 8403200133 8403260364 8403260364	50-413 50-275 50-275 50-275 50-275	A Q Q Q Q	House of Rep	8312140351* 8312280102* 8403070073* 8403070076* 8403070076*	50-275 50-275 50-289 50-287 50-287	E U U U
Greely, CO	8403240345 8403270006 8403270006 8403270173 8403220312*	50-142 50-275 50-275 50-445 CONTRACT	о е е		8403070011* 8403070013* 8403140208* 8403210137 8403270367	50-289 50-289 50-382 50-289 50-275	U U U U

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOOR	!Y	AFF	AUTHOR ILIATION	ACCESSION NUMBER	CATEGOR	
House of Rep , interior & Insular Affairs Houston Lighting & Power Co	8403010038* 8403120393* 8403070117 8403130328 8403130328	FOIA COMMISSI 50-498 50-498				8403020044 8403060191 8403060195 8403060195 8403060197*	50-315 50-316 50-315 50-315 50-316	# P P P
Hunton & Williams	8403130477 8403130477 8403140151 8403190289 8403010183	50-498 50-498 PR PR 50-322	5 5			8403040200* 8403040200* 8403040315* 8403040315* 8403080149	50-315 50-315 50-315 50-315 50-315	P 0 0 R
	8403010175 8403010221 8403010221 8403010229* 8403010229*	50~322 50~463 50~463 50~463 50~463	0 6 0			84030801&9 8403080214* 84030902&8 8403130121 8403130202	50-315 50-315 50-315 50-315 50-315	R G F F
	8403010242 8403010249 8403020143 8403040105 8403040107#	50-322 50-322 50-322 50-322	0 0			8403130202 8403130257 8403130257 8403130420* 8403130420*	50-315 50-315 50-315 50-315 50-315	F R R R
	8403130012 8403130018* 8403130032 8403130030* 8403130041*	50-322 50-322 50-322 50-322 50-322	0 0 0			8403160034 8403160034 8403200202 8403200202 8403200210	50-315 50-315 50-315 50-315 50-316	0 0 0
	8403130053* 8403130063* 8403130073* 8403130082* 8403130090*	50-322 50-322 50-322 50-322 50-322	0 0 0			8403200214* 8403200216 8403200217 8403200223 8403200223	50-316 50-315 50-316 50-315 50-315	P 8 P P
	8403130099* 8403130109* 8403130119* 8403130129 8403150004	50-322 50-322 50-322 50-322 50-322	0000			8403200228* 8403200288* 8403200283 8403220040* 8403220060*	50-315 50-315 50-315 50-315 50-315	р В О
	8403200031 8403200037* 8403200049 8403210177 8403210181*	50-322 50-322 50-322 50-322 50-322	G G G			6403230138* 6403230136* 6403260002 8403260176 6403260176	50-315 50-315 50-315 50-315 50-315	0 P F
	8403230013 8403260377 8403270272 8403270177 8403300256	50-322 50-322 50-322 50-322 50-322	G T G G			8403270047 8403270110 8403270271 8403300155 8403300157	50-315 50-316 50-315 50-316 50-315	Q P F R
ICI Americas, Inc Idaho, Univ of, Mpscow. ID Illinois Power Co	8403300277 8403210107 8403150207* 8403070120 8403070123*	50-322 PAM 40-8781 50-461 50-461	0 0	Indiana & Michigan Information Handl Interactive Radia Interior, Dept o	ing Bervices tion, Inc	8403090281 8403040171 8403020157 8403010040* 8403020277	50-315 FOIA XPORTLIC CONTRAC 50-320	
	8403080240 8403090277* 8403130193 8403150089 8403150175*	50-461 50-331 50-461 50-461 50-461	9 A A Q	Affairs Interior Dept of	f, Bureau of Indian f, Fish & Wildlife	8403080406* 8403190343 8403080400* 8403090189	50-528 50-528 50-528 50-424	D C C
	8403170378 8403200173*	30-461 50-461	A A	Service Interior, Dept o	f. Geological Survey	8403070383*	27-39	
	8403260255 8403290093	30-461 50-461	S I	Protection	mission on Radiological		CONTRAC	
Illinois, State of	8403270098* 8403010344 8403040118 8403040124*	50-461 27-39 40-2061 40-2061	ľ	Iowa Electric Ligi	ht & Power Cg	8403020108 8403020111* 8403060136 8403060145	50-331 50-331 50-331 50-331	P F 8
	8403070027 8403070030* 8403070123* 8403080184*	40-2061 40-2061 50-461 FDIA	G			8403070088 8403070072# 8403070262 8403120042 8403120071	50-331 50-331 50-331 50-331 50-331	P P R 8
	8403130037 8403130474 8403200083 8403200089#	50-456 50-456 40-2061	D D			8403120139 8403130144 8403130488# 8403150087	50-331 50-331 50-331 50-331	B F F
Illinois, State of, Dept Nuc Safety	8403200317 8403300258 8403040313	27-39 40-2061 50-454	D			8403190295 8403190300	PR 50-331	P
(formerly Dept Public Health) Impell Corp	8403010303# 8403150014#	50-438 50-388 50-440	E Q			8403190306# 8403200047 8403200051 8403200121	50-331 50-331 50-331 50-331	PFF
	8403200062* 8403200067* 8403200269* 8403230016	50-217 50-217 50-482 50-322	G A T			8403200183 8403200192 8403220017 8403230004 8403230007*	50-331 50-331 50-331 50-331 50-331	FPRP
	8403230032 8403230048 8403230073 8403020007	50-322 50-322 50-322 50-314	T T R			8403230105 8403260208	50-331 50-331	a P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	DRY	AUTHOR Affiliation	ACCESSION NUMBER	SUBJECT	RY
Inwa, State of Isham, Lincoln & Beale	8403190387 8403010203 8403020134	PR 50-155 50-275	G	Kentucky, Commonwealth of, Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)	8402130395* 8403210019	50-358 40-2061	U
	8403020134 8403020140 8403020140	50-275 50-275 50-275	G G	Kerr-McGee Corp	8403130272 8403150274 8403150332	40-8784 40-8784 40-8584	
	8403020146* 8403020146* 8403020181 8403040188	50-275 50-275 50-275 50-454 50-155	당 다 다 다		8403260129* 8403260158* 8403280028 8403280099 8403280103*	40-1478 40-1478 40-2061 40-8586 40-8586	
	8403040192# 8403040202# 8403140011 8403140011	50-155 50-155 50-454 50-456	G G G G	Kirkpatrick, Lockhart, Hill, Christopher & Phillips		40-2061 50-322	Q
	8403140023 8403160023 8403190004	50-454 50-454 50-155	a a a		8403010237 8403040208 8403040254	50-322 50-322	G T
	8403200011 8403200011 8403200122 8403200130	50-329 50-329 50-454 50-155	G G G		8403040248 8403040338 8403130003 8403130027 8403130144	50-322 50-322 50-322 50-322 50-322	G G G
Island Closeup News Service, Sag Harbor, NY	8403260361 8403270020 8403270020	50-155 50-456 50-329 50-329 FOIA	G G		8403130174 8403150024 8403200004 6403200128 8403200131	50-322 50-322 50-322 50-322 50-322	9 9 9
Isotope Products Laboratories Japan, Covt of	8403090016 8403010490 8403010464 8403010471 8403010487	FOIA XPORTLIC XPORTLIC XPORTLIC XPORTLIC	c c		8403200134* 8403200134* 8403200140* 8403200145* 8403200144*	50-322 50-322 50-322 50-322 50-322	0 0
Joint Intervenors - Diable Canyon	8403220197 8403240041 8403240390 8403080118 8403190011	XPORTLIC XPORTLIC XPORTLIC 50-275 50-275	C		8403200151* 8403200159* 8403200159* 8403210184 8403220250	50-322 50-322 50-322 50-322 50-322	G G G
	8403190011 8403190016* 8403190016* 8403190021* 8403220106	50-275 50-275 50-275 50-275 50-275	0 0 0 0		8403250268 8403260134 6403260344 6403260357 8403260358	50-322 50-322 50-322 50-322	T O O
	8403220104 8403220110* 8403220110* 8403240348 8403240349*	50-275 50-275 50-275 50-275 50-275	0 0 0 0	Kirksville, MO	8403270248 8403270377 8403270383 8403270390 8403070045	50-322 50-322 50-322 50-322 50-483	A G G O M
Joint Intervenors - River Dend Joint Intervenors - Shearon Harris	8403140012# 8403120002 8403190141# 8403200054 8403220223	50-458 50-400 50-400 50-400	0 0 0	Kohl, Becrest, Wardle, Lynch, Clark & Hampton Kudzu Aliiance LIXI, Inc	8403070226 8403120002 8403080200	50-329 50-400 FOIA	9
Joint Intervenors - Waterford Joint Petitioners - TMI	B403220223 B403220255 B403220270 8403220361 B403080130	50-400 50-400 50-400 50-400 50-400 50-382 50-289	6 0 0 0 0	La Crosse, WI Labor, Dept of Larey Township, NJ Lainer Associates Lauler, Matusky & Skelly Engineers Laurence Burkelsy Laboratory	8403080218* 8403220317* 8403130235 8403040231 8403050335* 8403200240* 8403300120	FOIA CONTRACT PR	н А
Justice, Dept. of . KLD Associates, Inc Kansas Gas & Electric Co	8403080383* 8403080425* 8403230020 8403010145	FOIA 50-287 50-322 50-482	P T B	Lawrence Livermore Laboratory	8303080290# 8403050029# 8403050035# 8403050038# 8403140334	50-286 50-286 50-286 50-286 ACRB	P P P
	8403090225 8403130197 8403130215 8403130345*	50-482 50-482 50-482 50-482 50-482	A B 0	LeBoeuf, Lamb, Leiby & MacRae League Against Nuclear Dangers	8402170155 8403120183 8403130044 8403070208	50-295 50-295 50-34; PR	P P K
	8403130399* 8403130064 8403190035 8403190036 8403190229*	50-482 50-482 50-482 50-482 50-482	Q A Q B A	Lewis, M Limerick Ecology Action	8403160049* 8403160049* 8403160291 8403190038 8403190140	50-320 50-289 50-352 50-352	PHOO
	8403190316 8403200252 8403200257 8403200260* 8403200269*	50-482 50-482 50-482 50-482 50-482	8 A E A A		8403270069* 8403270069* 8403280336 8403300014* 8403300129	50-352 50-352 50-352 50-352 50-352	0 0 0 T 0
	8403210073 8403240325 8403270105 8403270151 8403270163	50-482 50-482	A G B B	Literature Research Co. Long Island Lighting Co	8403240322* 8403010183 8403010195 8403010207 8403010207	50-322 50-322 50-322 50-322 50-322	
Kaye, Scholer, Fistman, Hays & Handler	8403270179 8403270268 8403010111 8403080226		9		8403010218 8403010218 8403010220	50-206 50-206	S S G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	·Υ	AUTHOR AFFILIATION	ACCEBBION NUMBER	CATEGORY	
	8403010242 8403010247 8403020137 8403020143 8403020168	50-322 50-322 50-322 50-322	0 0 0	Los Alamos Scientific Laboratory Louisiana Power & Light Co	8403300256 8403300277 8403230216 8403010069 8403010187	50-322 50-537 50-382	0 A B
	8403020287 8403040105 8403060107* 8403060265 8403070147	50-322 50-322 50-322 50-322 50-322	E G G T		8403020203 8403020333 8403050045 8403050248 8403050251*	50-362 50-362 50-382	A A E F
	8403070150* 8403070154* 8403070158* 8403070160* 8403070165*	50-322 50-322 50-322 50-322	T T T T		8403050253* 8403060190 8403060196 8403060258 8403060293	70-2946 50-382 50-382	8 8 8
	8403070171* 8403070178* 8403070183* 8403070190* 8403070195*	50-322 50-322 50-322 50-322 50-322	T T T		8403060306 8403060337 8403060339 8403090038* 8403120014	50-392 50-392 50-392	E E 8 A F
	8403070198* B403070201* B403070204* B403070207* B403070211*	50-322 50-322 50-322 50-322 50-322	T T T T		8403120164 8403120165* 8403120167* 8403120168 8403120169	50-382 50-382 50-382	FFAA
	8403070214# 8403070217# 8403070220# 8403070222# 8403070227#	50-322 50-322 50-322 50-322 50-322	T T T		8403120185 8403130105 8403130170 8403130267 8403130303	50~382	E G A B
	8403070231* 8403130012 8403130018* 8403130022 8403130030*	50-322 50-322 50-322 50-322 50-322	T Q Q Q		8403130311 8403130331 8403130339 8403130427 8403130434	50-382 50-382 50-382	8 0 8 9 F
	8403130041* 8403130053* 8403130063* 8403130073* 8403130082*	50-322 50-322 50-322 50-322 50-322	G G G		8403130436 8403130446 8403140171 8403150046 8403150075	50~382 50~382 50~382 50~382	8 A F A F
	8403130070* 8403130079* 8403130107* 8403130117* 8403130129	50-322 50-322 50-322 50-322	G G G		8403140020 8403170250 8403170253 8403170262 8403170272*	50~382 50~382 50~382	A S S G
	8403140019 8403140048 8403140048 8403140050 8403140050	20-322 20-325 20-355 20-355 20-355	A 8 8 8		8403170368 8403200022 8403200161 8403200168 8403200207	50-382 50-382 50-382	SFAA
	8403140080* 8403140080* 8403140091* 8403150004 8403150133	50-322 50-322 50-322 50-322 50-204	9 9 9 9		8403200267 8403200276 8403210030 8403260154 8403270040	50-382 50-382 50-382 50-382 50-382	8 8 A A 8
	8403190127 8403200004 8403200031 8403200037* 8403200069	50-322 50-322 50-322 50-322	9 6 6		8403270046 8403270059 8403270075 8403270102 8403270154	50-382 50-382 50-382 50-382	8 8 8 8
	8403200227 8403200302 8403210177 8403210181* 8403230008	50-322 50-322 50-322 50-322 50-322	A G G		8403270161 8403270202 8403270204 8403300048 8403300049#	50-382 50-382 50-382 50-382	8 8 F
	8403230013 8403230016 8403230020 8403230032 8403230038	50-322 50-322 50-322 50-322 50-322	Ω Τ Τ Τ Τ	Louisiane Btate Univ Lowell, Univ of Lowell, MA MATECO (subs of Multi-Amp Corporation) MPR Associates, Inc	8403050081* 8403300167* 8403130244 8403170351* 8403220004*	50-458 50-223 GA979 50-361 50-219	A Q P
	8403230048 8403230066 8403230073 8403260377 8403260379#	50-322 50-322 50-322 50-322	T T T T	Maine Yankee Atomic Fower Co	8403020065 8403060094 8403130047 8403220192 8403220199*	50-307 50-307 50-307 50-307	R R P P
	8403270074 8403270116 8403270119 8403270132 8403270197	50-322 50-322 50-322 50-322	G A R S O		8403230036 8403230042 8403270138 8403270236 8403300140	50-309 50-309 50-309 50-309 50-309	P P P R Q
	8403270292 8403280029 8403290160 8403290165* 8403290179	50-322 50-322 50-322 50-322	0 F F 0	Maine, State of Mallinckrodt, Inc Marsh & McLennan, Inc.	8403300142 8403070032* 8403270270* 8403210004 8403040224	50-309 CONTRACT CONTRACT PR 50-327	R J

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	RY	AUTHOR AFFILIATION		ACCESSION NUMBER	SUBJECT	
	8403040234 8403040234 8403040277 8403040281 8403040281	50-335 50-335 50-370 50-321 50-321	7777			8403090192 8403090215 8403090265 8403090265 8403120037	50-416 50-416 50-416 50-416 50-416	8 P 8 8
	8403040332 8403040334 8403040353 8403040347 8403040375	50-250 50-259 50-302 TOPREP TOPREP	J			8403120148 8403120159 8403130095 8403130192 8403130248	50-416 50-416 50-416 50-416 50-416	***
	8403060377 8403060377 8403060413 8403060448 8403070175	50-397 50-397 50-438 50-348 50-327	נננננ			8403130253 8403130274 8403130464 8403140121 8403140121	50-416 50-416 50-416 50-416 50-416	1 8 8 8
	8403140003 8403140015 8403140027 8403140031 8403140033	50-322 50-375 50-273 50-245 50-27	נננננ			8403190033 8403190043 8403190059 8403190115 8403190216	30-416 30-416 30-416 30-416	9999
	8403140037 8403140044 8403140078 8403140092 8403240170	50-413 50-348 50-244 50-213 TOPREP	したたん			8403170272 8403170331 8403200014 8403200017 8403200018	50-416 50-416 50-416 50-416 50-416	8 S S S G
	8403260197 8403280038 8403280053 8403280058 8403280064	50-272 50-321 50-348 50-272 50-146	してたた			8403200064 8403210041 8403210053 8403210057 8403210062*	50-416 50-417 50-416 50-416 50-416	8 9 P P
Marubeni America Corp (subs of Marubeni Corp.)	8403010467* 8403050364* 8403050366*	XPORTL 10 XPORTL 10 XPORTL 10 XPORTL 10	3			8403210109 8403210140 8403210140 8403210192 8403220147	50-416 50-416 50-416 50-416 50-416	P E E S R
Maryland, State of Maryland, Univ of, College Park, MD	8403070106 8403130157 8403130236 8403210124 8403210126*	PR 50-320 PR 50-166 50-166	P P			8403220156 8403230084 8403230089* 8403230092* 8403260244	50-416 50-416 50-416 50-416 50-416	Х Р Р В
Massachusetts General Hosp , Doston, MA Massachusetts Institute of Technology, Cambridge, MA	8403070164 8402130347 8403070212	PRM 50-20 PR	F			8403270134 8403280007 8403280014* 9403280018*	50-206 50-416 50-416 50-416	9 P P
Massachusetts, Univ of, Medical School Maxwell, J C	8403140172 8403270321 8403140302	PR PR 50-400	ø			8403280025# 8403270030 8403270030 8403270074	50-416 50-416 50-416 50-416	9 0 0
Medical Physics Consultants, Inc Memphis Btats Univ., Hemphis, TN Metal Bellows Corp Metropolitan Edison Co.	B4030B0149* B403150196* B403230060 B403120117 B403010009	FDIA CONTRACT 50-538 GA499 50-289	r R Q			8403270304 8403300007 8403300027	50-416 50-416 90-416	g 8
	8403040084 8403070025 8403080105 8403070127 8403130443	50-289 50-289 50-289 50-289 50-289	0000			8403300037 8403300082 8403300097 8403300113	50-416 50-416 50-416 50-416	8 8 8 8
	8403130451* 8403200055 8403200046 8403200120	50-287 50-287 50-287 50-287 50-287	9 9 9 9	Missouri, State of		8403300117 8403300118 8403300124 8403370087	50-416 50-416 50-416 50-483	9 9 F
	8403210175 8403210187	50-289 50-289	e G	Missouri, Univ of, Rolla, MO Mitsubishi International Corp Mitsubishi Corp)	(subs of	8403190088* 8403010465 8403010468*	50-123 XPORTLIC	C
Michigan, State of Michigan, Univ. of, Ann Arbor, MI	8403210173 8403260345 8403170172* 8403140151	50-289 50-289 50-329 PR	G A			071010E0P8 *E71010E0P8	XPORTLIC XPORTLIC	
Millikin & Fitton Millipore Corp Minerals Exploration Co. (subs. of Union Oil Co of California)	8403230131 8403080113* 8403210107 8403150228	NUREO FOIA PRM 40-8584				8403010512 8403010517* 8403050327* 8403050333* 8403050373*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC	C C
Minnesote, State of	8403230058 8403290316	PR WASTE MO	דנ			8403050376* 8403070425* 8403070426*	XPORTLIC XPORTLIC XPORTLIC	G
Mississippi Power & Light Co	8403010121 8403020047 8403020410#	50-416 50-416 50-416		Mitsuí & Co (USA), Inc (subs & Co , Ltd.)	of Mitsui		XPORTLIC XPORTLIC	C
	8403070057 8403070173* 8403070176* 9403070180* 8403070189*	50-416 50-416 50-416 50-416 50-416	a a a	Monros County, NI Montgomery County, MO Morris, Il Morrison-Knudsen Co , Inc		8403280054* 8403070078 8403230052* 8403120043 8403200150*	50-341 50-483 CONTRACT GA799 GA779	F
	8403070268 8403070325 8403090091	50-416 50-416 50-416	Q P S	Murphy & Davenport Mutual Atomic Energy Liability ars	Underwrit	8403200157* 8403210038 8403140065	QA999 WASTE MG 50-280	

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
NL Industries, Inc NPS Industries, Inc NUS Corp	8403200373 8403070256 8403010278 8403020372 8403070098	XPORTLIC 50-219 S FOIA 50-289 P FOIA		8403130349* 8403130363 8403130386 8403130391* 8403130051	50-220 P 50-410 8 50-220 P 50-220 P 50-220 R	1
NUSAC. Inc NUTECH Engineers, Inc National Aeronautics & Space Admin	8403070015 8403240253* 8403270362* 8403070318* 8403060405	F01A 50-352 E CDNTRACT 50-325 G 50-30 R		8403200002 8403200232 8403200243+ 8403200248+ 8403210043	50-220 P 50-410 A 50-410 A 50-410 A 50-220 B	
National Hoard of Boiler & Pressure Vesse) Inspectors Natural Resources Dafense Council	8403060410# 8403130288 8403190120	50-30 R 50-35B A 50-537 0		8403210136 8403220127 8403220177 8403230078	50-410 8 50-220 P 50-220 P 50-220 P	•
Navy, Pept of Nebrasia Public Power District	8403290297 8403020083	PR 50-298 R		8403230116 8403260270	50-220 F	
	8403050075* 8403060239 8403060264 8403060274* 8403060346	50-298 F 50-298 F 50-298 F 50-298 F 50-298 F		8403270176 8403280036 8403280047 8403290177	50-220 P 50-220 J 50-220 J 50-220 I	j J I
	8403060354 8403060372 8403080265 8403070100 8403070116#	50-298 F 50-298 G 50-298 F 50-298 P 50-298 P	North Carolina State Univ , Raleigh, NC North Carolina, State of	8403300058 8403300151 8403090340 8403140085 8403190047*	50-220 P 50-220 G ACRB 50-400 G 50-400 F	3 2
	8403150168 8403150171 * 8403150173 * 8403160260 * 8403190087	50-278 P 50-278 P 50-278 P 50-278 Q 50-278 F	Northeast Nuclear Energy Co (subs of Northeast Utilities)	8403010219 6403010235 8403020055 8403020133 8403050001	50-334 P 50-245 R 50-236 R 50-423 D	2
	8403200167 8403200254 8403220042* 8403220055 8403270013	50-278 F 50-278 P 50-278 Q 50-278 F 50-278 F		8403050105 8403050105 8403070273 8403070275* 8403070279	50-213 P 50-213 P 50-423 C 50-423 C	P C
Netherlands, Govt of Nevada, State of	8403306150 8403080360# 8403080364# 8403080366# 8403020206	50-298 R FOIA FOIA FOIA WASTE MOT		8403070336# 8403070257 8403070272 8403120135 8403120138#	50-423 Q 50-336 P 50-336 P 50-245 R	P P q
Nevada, Univ of New England Coalition on Nuclear Pollution	8403150222* 8403150223* 8403020173	WASTE MOT WASTE MOT 50-443 G		8403120138# 8403130027 8403140101 8403140109# 8403160292	50-245 R 50-213 P 50-423 K 50-423 K 50-423 E	P K K
New Mexico. State of New York Univ . New York, NY	8403050109 8403060314+	State Prog		8403190048 8403190280	50-245 P	
New York, State of	8403020123 8403020233 8403060212 8403060226*	50-322 0 50-322 0 50-322 T 50-322 T		8403200113 8403200147 8403210011	50-334 S 50-423 A 50-423 G	A
	8403060246* 8403060252* 8403130043 8403130085 8403130091*	50-322 T 50-322 T 50-322 G 50-322 G 50-322 G		8403220148 8403230022 8403230022 8403230022 8403230029	50~423 F 50~213 R 50~213 R 50~213 R 50~245 F	R Pt Pt
	8403130236 8403210179 8403210188 8403210201 8403230010	PR 50-322 G 50-322 G 50-322 G 50-322 G		8403230033 8403230034* 8403230037* 8403260143 8403260143	50-423 Q 50-245 F 50-423 Q 50-213 F 50-213 F	F Q F
Newman & Holtzinger	8403240338 8403260342* 8403020100 8403070117 8403090086	50-322 T 50-322 T 50-537 0 50-498 G 50-537 G		8403260143 8403260143 8403260145 8403260146 8403260146	50-213 F 50-213 F 50-213 F 50-213 F 50-213 F	F P F
Niagara Mohawk Power Corp.	8403170171 8403230184 8403240062 8403300272 8403040221	50~250 G 50~554 G 50~331 J 50~344 G 50~220 F		8403240151* 8403240151* 8403240151* 8403240151*	50-423 E 50-213 F 50-213 F 50-213 F 50-213 F	F F
	8403060247 8403060439 8403060446 8403070194 8403070040	50-220 P 50-220 F 50-220 P 50-220 R 50-220 P		8403240181 8403240195 8403240284 8403270008 8403270008	50-423 A 50-245 F 50-245 B 50-213 F 50-213 F	F 8 F
	8403090063 8403090078 8403090146 8403120044 8403120050*	50-220 F 50-410 8 50-220 P 50-220 G 50-220 G		840327008 8403270081 8403290112 8403290230 8403300080	50-336 F	
	8403120059 8403130124 8403130340	50-220 P 50-410 V 50-220 P		8403300092* 8403300092* 8403300135 8403300144	50-245 R	Q Q R Q

AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJE(AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY
Northeast Utilities	8403010219 8403010235 8403020133 8403050001 8403050105	50-336 50-336 50-336 50-423 50-213	8 R D		8403270115 8403270115 8403270115 8403200087 8403300075	50-263 50-263 50-263 50-263 50-283	I I I R R
	8403050105 8403070273 8403070259 8403070336* 8403070257	50-213 50-423 50-423 50-423 50-334	P G A G P	Northwestern Univ . Evanston, IL Norton, Burke, Berry & French	8403300095 8403300130 8403300130 8403050237* 8403070044	50-282 50-282 50-282 CONTRAC 50-275	R F F T
	8403090272 8403120135 8403130027 8403130213 8403130277	50-336 50-245 50-213 50-423 TOPREP	P R P S	NucleDyne Engineering Carp	8403120006 8403070314 8403070315* 8403070318*	50-275 TOPREP TOPREP TOPREP TOPREP	G
	8403130360 8403130367* 8403130376* 8403140101 8403140131	50-423 50-423 50-423 50-423 TOPREP	C C K		8403090319# 8403090321# 8403090322# 8403090323# 8403090324#	TOPREP TOPREP TOPREP TOPREP TOPREP	
	6403160272 6403190048 6403200149 6403210011 6403210161	50-423 50-245 50-423 50-423 50-423	8 6 8		8403070325* 8403070327* 8403070328* 8403070330* 8403300237*	TOPREP TOPREP TOPREP TOPREP TOPREP	
	8403220148 8403230022 8403230029 8403230033	50-423 50-213 50-245 50-423	F F G	Nuclear Awareness Network Nuclear Energy Liability Insurance Association	8403090053 8403140061 8403140047	50-482 50-482 50-338	ე 0 0
	8403260143 8403260143	50-213 50-213	F		8403140054 8403140059	50-260 50-260	") J
	8403260145 8403260146 8403260146 8403260147	50-336 50-213 50-213 50-423	F F E	Nuclear Information & Resource Service Nuclear Law Center Nuclear Medicine Associates, Inc Nuclear Metals, Inc	8403140047 8403280211 8403200021 8403080154+ 8403050144*	50-280 50-482 50-142 FDIA 40-672	0 0
	8403260151* 8403260181 8403260195 8403260200 8403270008	50-213 50-245 50-213 50-213	F F F	Nuclear Phormacy, Inc Nuclear Bervices Corp Nuclear Utility Task Action Committee	8403050150* 8403220092* 8403050055 8312280107* 8403070252*	40-672 40-672 FOIA 50-275 50-321	Æ
	840327008 8403270081 8403290112 8403290230 8403300080	50-213 50-336 50-423 50-336 50-336	F A P R	Nurnbarger Radiation Protection Service Nutec. Inc O'Neill, J Oak Ridge National Laboratory	8403130378 8403290052* 8403260360 8403010102* 8403070392	PR FDIA 50-155 FDIA NUREO	Q
Northeast Utilities Service Co (subs of Northeast Utilities)	8403300092* 8403300092* 8403300135 8403300144 8403130360	50-245 50-245 50-245 50-213 50-423	0 R 0 C		8403120255 8403150205 8403150219 8403150230 8403150237	REB 40-8781 NUREQ 40-1341 40-1341	
Northern States Power Co	8403190280 8403010018 8403010316 8403020197 8403020285	PR FO1A 50-263 50-263 50-263	8 R F		8403190444 8403200358 8403230057 8403260286 8403300304	NUREQ NUREQ NUREQ NUREQ NUREQ	
	8403040425 8403040425 8403090207 8403090270 8403120033	50-262 50-282 50-282 50-282	8 F P	Defice of Management & Budget	8403300317 8403300318 8403300325 8403020380 8403020381	NUREO NUREO NUREO ORO ORO	
	8403120088 8403130079 8403130087* 8403130096* 8403130103*	50-263 50-263 50-263 50-263 50-263	93 Pt Pt Pt		8403020383 8403020385 8403020387 8403020388 8403060458	GRG GRG GRG GRG GRG	
	8403130245 8403130258* 8403130258* 8403130270* 8403130270*	50-282 50-282 50-282 50-282 50-282	R R R R		B403060460 B403060463 B403230079 B403230080 B403260037	ORO ORO ORO ORO ORO	
	8403130278* 8403130365 8403190064 8403190200 8403190388	50-262 50-263 50-263 50-263	R 9 0 0 0	Dhio. State of	8403010085 8403070213 8403280076 8402130340* 8403130327	FOIA 50-440 FDIA 50-358 PR	A U
	8403170388 8403170377 8403200255 8403220003 8403230051	50-262 50-263 50-263 50-263 50-262	0 P B B	Omaha Public Power District	8403060187 8403270087 8402170156 8402170166* 8402170176*	qa999 qa999 50-265 50-265 50-265	P P
	8403270049 8403270170 8403270181* 8403290115	50-543 50-585 50-585 50-573	Р 9 1		8402210357* 8403010312 8403050099 8403050124	50-295 50-285 50-285 50-285	0 P F 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC.	₹¥	AUTHOR AFFILIATION	ACCEBBION NUMBER	CATEGOR	
	8403050135 8403050376 8403090234 8403120062 8403120183	50-285 50-285 50-285 50-285 50-285	R P F F		8403280051 8403280114 8403300075 8403300078 8403300141	50-133 50-275 50-133 50-275 50-275	1 # # E R
	8403120192* 8403120195* 8403130200 8403130458 8403190061*	50-285 50-285 50-285 50-285 50-285	P 0 P 0	Pacific Radiation Corp Pacific Scientific Palmetto Alliance	8403300148 8403130327 8403010075 8403130338* 8403070033	50-275 PR GAP79 GAP99 50-413	E
	8403190154 8403190281 = 8403200176 8403270249 8403270253*	50-285 50-285 50-285 50-285 50-285	F Q R Q		8403070033 8403070037* 8403070037* 8403090112 8403090112	50-413 50-413 50-413 50-413 50-413	00000
Online Computer Systems, Inc Oregon, State of Orrick, Herrington & Butcliffe	8403280165 8403280193 8403010534* 8403090159 8403090126	50-285 50-285 CONTRAC PR 50-445	F F O		8403070115* 6403070115* 8403220233 8403270377 8403270382	50-413 50-413 50-413 50-413 50-413	0000
Osage County, MO Oswego, NY Pacific Air Products Co Pacific Gas & Electric Co	8403070090 8403220327# 8403140122 8403020004 8403020006	50-483 CQNTRAC 50-220 50-275 50-133	F T B R R	Parameter, Inc	8403290382 8403290388 8403290388 8403080193* 8403080199*	50-413 50-413 50-413 50-275 50-275	0000
	8403050178 8403070044 8403070044 8403070075 8403070077*	50-133 50-275 50-275 50-275 50-275) О Р Р	Parkans International, Inc Pathfinder Hines Corp Pennsylvania Power & Light Co	8403020112 8403020115* 8403120251 8403150342 8403010294	XPORTL IO XPORTL IO 40-2259 40-2259 50-388	
	8403070083 * 8403070284 8403070288 * 8403070292 * 8403070335	50-275 50-275 50-275 50-275 50-275	Р Р Р		8403020036 8403020253 8403020317 8403020327 8403020327	50-387 50-387 50-387 50-387 50-387	A B B P P
	0403080281# 0403080413 0403080414* 0403080415# 0403090172	50-275 50-275 50-275 50-275 50-275	E P P F		8403050090 8403050090 8403050108 8403050108 8403050116	50-387 50-387 50-387 50-387 50-387	4 6 6
	8403120006 8403120006 8403120010* 8403120010* 8403120012*	50-275 50-275 50-275 50-275 50-275	6 6 6		8403050122* 8403040108 8403040175 8403040175 8403040253	50-387 50-387 50-387 50-387 50-387	P G G G
	8403120012* 8403120018* 8403120018* 8403120022* 8403120022*	50-275 50-275 50-275 50-275 50-275	6 6 6		8403060437 8403060437 8403070358 8403070209 8403070232	50-387 50-387 50-313 50-387 50-387	9 F F G
	8403120027# 8403120027# 8403120129 8403140153 8403150005	50~275 50~275 50~275 PR 50~275	G G		8403070237* 8403070237* 8403120026 8403120127 8403130020	50-387 50-387 50-388 TOPREP 50-387	8 8 A F
	8403150011 8403150013 8403150025 8403150048 8403150082	50-275 50-277 50-275 50-323 50-275	P 9 9 9		8403130057 8403130111 8403130150 8403140011 8403140018	50-397 50-387 50-388 50-387 50-387	R P P B
	8403150147 8403200218 8403200220* 8403220035 8403220046	50-275 50-275 50-275 50-275 50-275	8 P P		8403150070 8403150070 8403150124 8403150126 8403160177	50-387 50-387 50-387 50-387 50-387	8 4 4 4
	8403220172 8403230139 8403230141* 8403230191 8403260174	50-275 50-275 50-275 50-275 50-275	E R G P		8403170232 8403170242 8403170242 8403170366* 8403170364*	50-387 50-387 50-387 50-387 50-387	F F Q
	8403250176 8403270004 8403270004 8403270004 8403270004	50-275 50-133 50-133 50-133 50-133	P 0 0		8403170375 8403170375 8403170405 8403200004 8403200071	50-387 50-387 FR 50-388 50-388	P P A E
	8403270037 8403270053 8403270057 * 8403270063 8403270205	50-133 50-275 50-275 50-275 50-133	9 P P F		8403200073 8403200073 8403200103 8403200103 8403200250	50-387 50-387 50-387 50-387 50-387	# # #
	8403270205 8403270205 8403270205 8403280001 8403280033	50-133 50-133 50-133 50-275 50-275	1 1 1 1		8403200292 8403210072 8403210072 8403210081* 8403210081*	50-987 50-987 50-987 50-987 50-987	F K K K

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJE(AUTHOR AFFILIATION	ACCESSION NUMBER	CATEOD	
	8403210090* 8403210090* 8403210112 8403210125 8403210145	50-387 50-387 50-387 50-388 50-388	8 8 K K		8403120175 8403130084 8403130158 8403150005 8403150024	50-276 50-352 50-276 50-277 50-352	8 8 8
	8403220040 8403220041* 8403220069 8403220069 8403220102	50-388 50-387 50-387 50-387 50-387	A 0 0 0 P		8403150024 8403150036 8403150036 9403150137 8403150137	50-352 50-352 50-352 50-277 50-277	G C P P
	8403220102 8403220135* 8403220135* 8403220137 8403230095	50-387 50-387 50-387 50-387 50-388	P 0 P 8		8403150140* 8403150140* 8403150143* 8403150143* 8403160010	50-277 50-277 50-277 50-277 50-352	P P P
	8403240224 8403240305 8403270175 8403300047* 8403300049*	50-387 50-388 50-387 50-387 50-387	A I Q		8403160010 8403160187* 8403160187* 8403160192 8403160192	50-352 50-352 50-352 50-352 50-352	000
Pannsylvania State Univ . University	8403300147 8403010098*	50-387 CONTRAC	R		8403190197 8403190197	50-352 50-352	A
Park, PA Pannsylvania, Commonwealth of,	8403060083 8403120001 8403170346	50-320 50-352 50-387	H Q F		8403190198 8403200019 8403200060	50-277 50-277 50-352	8 8
Perry, DH Philadelphia Electric Co	8403200015 8403200122 8403220217* 8401240207 8401240211*	50-352 50-352 CDNTRAC 50-352 50-352	G T A		8403200040 8403200070 8403200070 8403200144 8403200144	50-352 50-352 50-352 50-352 50-352	0000
	8403010144 8403010144 8403010221 8403010221 8403010227*	50-352 50-352 50-463 50-463 50-463	E 0 0 0		8403210028 8403210028 8403210045 8403210045 8403210055*	50-352 50-352 50-277 50-277 50-277	F F P P
	8403010227* 8403010358 8403020104 8403020104 8403020105*	50-463 50-277 50-352 50-352 50-352	9 4 4 8		8403210055* 8403210063* 8403210063* 8403210092 8403210092	50-277 50-277 50-277 50-352 50-352	P P 0 0
	8403020105* 8403020125 8403020125 8403020127 8403020127	50-352 50-352 50-352 50-352 50-352	0 0 T T		8403210103 8403210103 8403230012 8403260054 8403260054	50-352 50-352 50-171 50-277 50-277	7 8 9
	8403020136* 8403020136* 8403020163 8403020163 8403020257	50-352 50-352 50-352 50-352	T T G G		8403260249 8403260249 8403260333 8403260333 8403260349	50-352 50-352 50-352 50-352	E 0 0
	9403020257 9403020266# 9403020266# 8403020270# 9403020270#	50-352 50-352 50-352 50-352 50-352	AAGG		8403270012 8403270012 8403270017 8403270017 8403270042	50-352 50-352 50-352 50-352 50-352	Q Q Q T
	8403020273* 8403020273* 8403050117 8403050161 8403050161	50-352 50-352 50-277 50-352 50-352	X X E E		8403270042 8403270048* 8403270048* 8403270060 8403270064	50-352 50-352 50-352 50-352 50-277	T T O P
	8403050163* 8403060081 8403060081 8403060248 8403060248	50-352 50-352 50-352 50-352 50-352	E 0		8403270064 8403270067* 8403270067* 8403270071 8403270104	50-277 50-277 50-277 50-352 50-277	4 6 6
	8403070142 8403070142 8403070236 8403070236 8403070238*	50-352 50-352 50-352 50-352 50-352	00000		8403270172 8403270250 8403280353 8403280353 8403280353	50-352 50-277 50-352 50-352 50-352	A G G G
	8403070238* 8403070281* 8403070361 8403070361 8403070055	50-352 50-352 50-352 50-352 50-352	0 F F		8403270384 8403300014* 8403300127 8403300127 8403300128	50-352 50-352 50-352 50-352 50-352	0 0 0
	8403090055 8403090081 8403090089* 8403090131 8403090285	50-352 50-277 50-277 50-277 50-277	Q Q Q Q		8403300128 8403300127 8403300129 8403300271 8403300271	50-352 50-352 50-352 50-352 50-352	0
	8403070270 8403070270 8403120017 8403120085	50-352 50-352 50-278 50-277	F B B	Philadelphia, PA	8403300274* 8403300274* 6403010271 8403010271 8403010275*	50~352 50~352 50~352 50~352 50~352	9 9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
Philbrick, S S Photocraft Custom Lab, Inc	8403010275* 8403040129 8403190007 8403160053 8403130495*	50-352 50-352 50-352 ACRS CONTRACT	9	40	8403050112 8403060307 8403130177 8403130396 8403130435	50-267 50-267 50-267 50-267 50-267	O R P R
Pittsburgh, Univ of, Pittsburgh, PA Plateau Resources, Ltd	8403150041 8403270238 8403150213 8403150247 8403220183	50-320 PRM 40-8698 40-8698 40-8698	Þ		8403160227 8403160233* 8403160303 8403160326 8403170344	50-267 50-267 50-267 50-267 50-267	P 0 0
Plymouth. MA Parter Consultants, Inc Partland General Electric Co	8403220187* 8403220191 8403220262* 8403230048 8403010175*	40-8698 40-8674 CONTRACT 50-322 50-344	T P		8403190350 8403190357* 8403190359* 8403220063 8403220138	50-267 50-267 50-267 50-267 50-267	P P P 8 F
	8403010355 8403020050 8403060382 8403060384 8403140137	50-344 50-344 50-344 50-344 PR	S R P H	Public Service Co of New Hampshire	8403270189 8403270191* 8403270192 8403270194* 8403070042	50-267 50-267 50-267 50-267 50-443	P I P Q
	8403190325 8403190378 8403200141 8403200197 8403220247	50-344 50-344 50-344 50-344 50-344	E G J G		8403070042 8403080142 8403080142 8403070073 8403070073	50-443 50-443 50-443 50-443 50-443	0 0 0
	8403260216 8403280022 8403280041 8403300106 8403300168	50-344 50-344 50-344 50-344 50-344	自力した中		8403070124 8403070124 8403130468 8403150080 8403150100	50-443 50-443 50-443 50-443 50-443	0 9 A B
Posi-Beal Valves International Power Authority of the State of New York	8403300272 8403040304* 8401200078 8403010241 8403010365	50-344 50-324 50-286 50-333 50-333	G P V E E		8403160256 8403160254 8403160263* 8403210099 8403210099	50-443 50-443 50-443 50-443 50-443	F F A A
	8403010413 8403010420 8403020327 8403020351 8403060173	50-333 50-333 50-333 50-333 50-333	R F P S		8403210101# 8403210142 8403220005 8403220150 8403220150	50-443 50-443 50-443 50-443 50-443	8 8 4
	8403090025 8403090211 8403090267 8403120024 8403120152	50-333 50-286 50-286 50-333 50-286	8 F P S		8403220164 8403220061 8403230061 8403230180 8403230180	50-443 50-443 50-443 50-443	8 8 8
	8403130137 8403130162 8403130256 8403130350 8403130412*	50-333 50-286 50-286 50-333 50-286	위 부 위 위	Public Service Electric & Gas Co of New Jersey		50-443 50-443 50-443 50-272	A O B
	8403130466 8403140153 8403150047 8403150050 8403160009	50-333 PR 50-286 50-286 50-286	9 8 9		8403040312 8403040312 8403070240 8403070240 8403070261* 8403070261*	50~272 50~272 50~272 50~272 50~272 50~272	Y R R
	8403160017# 8403160021# 8403190265# 8403200094 8403200096#	50-286 50-286 50-286 50-333 50-333	P 0 P P		8403070305 8403070305 8403080013 8403080246 8403080252	50-272 50-272 50-272 50-272 50-272	R R B S
	8403200231 8403210047 8403210113 8403220091* 8403260071	50-333 50-284 50-284 50-333 50-284	S R Q S		8403070049 8403070080 8403070080 8403070080 8403070080	50-272 50-272 50-272 50-272 50-272	P G G G
	8403260171 8403260257 8403270185 8403270100 8403270152	50-333 50-284 50-333 50-284 50-284	P F P		B403130014* B403130017 B40313010B B403130372* B403130384	50-354 50-272 50-311 50-354 50-311	0 P P 0
Prairie Alliance Project Management Corp	8403270246 8403300157 8403300175 8403070123* 8403020100	50-333 50-284 50-286 50-461 50-537	8 0 0		8403140007 8403140113 8403140117* 8403140117*	50-354 50-354 50-354 50-354 50-354	A A A
Public Service Co of Colorado	8403040082 8403090086 8403010101 8403010107 8403010116	50-537 50-537 50-267 50-267 50-267	0 6 8		8403150020 8403150022* 8403150108 8403200102 8403210036	50-354 50-354 50-354 50-354 50-354	9 9 8 4
	8403010118 8403010134 8403010155* 8403010167*	50-267 50-267 50-247 50-267 50-267	8 8 8 0		8403210118 8403220036 8403220036 8403220039	50-354 50-272 50-272 50-311	8 0 0

`.

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8403220142 8403220151 8403220174 8403230041 8403270079	50-311 R 50-311 S 50-272 R 50-334 C 50-311 S		8403040387 8403040452 8403040467 8403130112 8403130125	50-312 F 50-312 9 50-312 8 50-312 9 50-312 P
	8403270244 8403290277 8403290281 8403290281 8403290302	50-272 S PR 50-272 P 50-272 P 50-334 A		8403190275 8403200001 8403200045 8403200184 8403230056	50-312 0 50-312 P 50-312 R 50-312 8 50-312 8
	8403300085 8403300085 8403300121 8403300177* 8403300183*	50-272 P 50-272 P 50-334 Q 50-272 Q	Sacramento, CA Salem, NJ San Diego Gas & Electric Co	8403260124 8403260215 8403280187* 8403260307* 8403160063	50-312 J 50-312 P CONTRACT CONTRACT 50-206 H
Pullman, Inc Quarytach, Inc	8403300186* 8403300190* 8403300270 8403270155 8403280316	50-311 0 50-311 0 50-394 0 MIBC ACRE	San Luis Obispo Mothers for Peace Sandie Laboratories	8403060303# 8403150010 8403200133 8403260364 8403010076#	50-275 G 50-275 G 50-275 G 50-275 G FOIA
Radiation Technology, Inc	8403280341 8403080040* 8403080046* 8403080055* 8403080064*	ACRS FOIA FOIA FOIA FOIA	Sandvik Special Metals Corp Sangamo Weston, Inc	8403080029# 8403260353* 8403300342 8403270327 8403070180	FOIA WASTE NOT NUREO XPORTLIC PRM
	8403080076* 8403080078* 8403080084* 8403080089* 8403080111*	FDIA FOIA FOIA FOIA	Sargent & Lundy, Inc Schiff, Hardin & Waite Schirmer Engineering Corp	8403190278* 8403070120 8403140180* 8403140183* 8403140184*	50-454 R 50-461 9 50-373 F 50-373 F 90-373 F
	8403080134* 8403080137* 8403080150* 8403080163* 8403080167*	FOIA FOIA FOIA FOIA	Gcience Applications, Inc	8209030161* 8403010027* 8403010041* 8403010102* 8403030032*	50-280 () CONTRACT FOIA FOIA 70-687
Ransselaer Polytechnic Institute, Troy, NY	8403080168* 8403080172* 8403080185* 8403060204	FDIA FDIA FDIA 50-225 F NUREG		8403050035* 8403080006* 8403080010* 8403080012*	50-286 P FOIA FOIA FOIA FOIA
Rauter-Stokes, Inc	8403200229 8403260156 8403060369 8403060573* 8403220328	50-225 R 50-225 R XPORTLIC XPORTLIC XPORTLIC		8403080017* 8403080017* 840308025* 8403080268* 8403080273*	FOIA FOIA FOIA 50-278 F 50-278 F
Ric Algom, Ltd Hobert Shaw Controls Co Rochester Gas & Electric Corp	8403150208 8403150274 8403270222 8403020202 8403060115	40-8084 40-8084 0A999 50-244 R 50-244 P	Seacnast Anti-Pollution League Senate	8403080306* 8403240341* 8403010385 8402220288 8402220303*	50-278 F CONTRACT FOIA 50-289 U 50-289 U
	84030&012&* 8403130132 84032&0198 84032&0243 8403270150	50-244 P 50-244 R 50-244 P 50-244 G		8403150341* 8403150060* 8403200200* 8403200211* 8403280156*	50-272 U 50-320 H 50-289 G 50-289 G 50-250 H
	8403270152 8403280047 8403270185 8403300081 8403300171*	50-244 0 50-244 P 50-244 P 50-244 R 50-244 0	Semate, Energy & Netural Resources Sequoyah Fuels Corp Shaw, Pittman, Potts & Trowbridge	8012140551* 8402130392* 8403010071 8403010009 8403010187	50-397 U 50-358 U 40-8768 50-289 0 50-382 0
Rochester, NY Rockbestos Co Rockland County, NY Rockwell International Corp	8403260370# 8403010128 8403060262 8403010170 8403150315	CONTRACT GA979 GA979 50-247 H WABTE MGT		8403010263 8403020106 8403020106 8403020182 8403020182	50-400 G 50-440 G 50-440 G 50-400 G 50-400 G
Ropes & Gray	8403260347* 8403300248 8403070042 8403080142 8403080142	HASTE MOT WASTE MOT 50-443 G 50-443 G		8403020188# 8403020188# 8403060084 8403060070 8403060257	50-400 0 50-400 0 50-289 0 50-424 0 50-440 0
	8403070073 8403070073 8403070124 8403070124 8403130080	50-443		8403060275 8403060275 8403060461 8403060464 8403070025	50-440 9 50-440 0 FOIA FOIA 50-269 0
BRI International Bacramento Municipal Utility District	8403210101* 8403230180 8403300269 8403010078* 8403010388	50-443 A 50-443 G 50-443 G CONTRACY 50-312 P		8403070134 8403070134 8403070191 8403070225 8403070225	50-400 G 50-400 G 50-445 G 50-400 G 50-400 G
	8403020350 8403050007 8403050008* 8403060141	50-312 P 50-312 P 50-312 P 50-312 J		8403080105 8403080140 8403130010 8403130139 8403130139	50-289 0 50-440 M 50-440 0 50-440 0 50-440 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOD		AUTHOR AFFILIATION	ACCESSION NUMBER	CATEOD	
	8403130154 8403130154 8403130403 8403130403 8403130443	50-400 50-400 50-440 50-440 50-269	0 0 0		8403050003 8403050140 8403050143+ 8403060174 8403060363	50-361 50-206 50-206 50-206 50-206	8 8 8
	8403130447 8403130447 8403130459# 8403130459# 8403150001	50-400 50-400 50-400 50-400 50-440	0 0 0		8403060363 8403060363 8403060378 8403060395 8403060395	50-206 50-206 50-361 50-206 50-206	7 8 X
	8403150009 8403150009 8403160018 8403190035 8403200030	50-440 50-440 50-400 50-482 50-400	000		8403060395 8403060399 8403060403 8403060424 8403060424	50-206 50-206 50-361 50-361 50-361	6 8 8
	8403200055 84032000&6 8403200120 8403200135 8403210175	50-289 50-289 50-289 50-400 50-289	0 0 0		8403060427* 8403060427* 8403060438 8403060438 8403070254	50-361 50-361 50-206 50-206 50-206	P P R R
	8403210187 8403210193 8403220261 8403240325 8403240327	50-287 50-287 50-400 50-482 50-400	9		8403090127 8403090127 8403090177 8403090177 8403090227#	50-361 50-361 50-361 50-361 50-361	0 P P
	8403260327 8403260328 8403260328 8403260345 8403260348	50-400 50-400 50-400 50-289 50-400	0 0 0		8403070230* 8403070233* 8403070238* 8403120064 8403130134	50-361 50-361 50-361 50-361 50-361	P P P
	8403260348 8403260354* 8403260354* 8403270327 8403270385	50-400 50-400 50-400 50-400 40-2061	0 0 0		B403150031 B403150033 B403150057 B403150074 B403140251	50-205 50-361 50-361 50-361 50-208	F 9 9
Shorcham, NY Simmuns-Allis, Inc Sierra Club	B403270385 B403270284* B403300077 B403120039 B403170120	50-289 CONTRAC PT21 50-204 50-537	T C		8403170345 8403170345 8403200053 8403200053 8403200057#	50-361 50-361 50-361 50-361 50-361	P P R R
Sigma Chemècal Co Silver King Mines, Inc Bouth Carolina Electric & Gas Co	8403020428 8403150153 8403200370 8403020037 8403020277	XPDRTL10 XPORTL10 40-8402 50-395 50-395	C		8403200057* 8403200074* 8403200074* 8403200077* 8403200082*	50-361 50-361 50-361 50-361 50-361	R R R
	8403060128 8403060130* 8403060242 8403060351 8403070040	50~375 50~375 50~375 50~375 50~375	P P S S		8403200086* 8403200088* 8403200091* 8403200097 8403200097	50-361 50-361 50-361 50-206 50-206	R R F
	8403070129* 8403070337 8403080153 8403070052 8403070249	50-375 50-375 50-375 50-375 50-375	0 8 8 8		8403200097 8403200175 8403200194 8403210009 8403210065	50-205 50-362 50-361 PR 50-205	F 9 8
	8403070271 8403130260 8403130371 8403130397 8403150042	50-395 50-395 50-395 50-395 50-395	8 8 8 8		8403220018 8403220018 8403220018 8403220024* 8403220027*	50-206 50-206 50-206 50-206 50-206	F F F
	8403270183 8403270188* 8403270223 8403270225* 6403300145	50-395 50-395 50-395 50-395 50-395	면 면 면 면		8403220027* 8403220027* 8403220121 8403220125* 8403230074	50-20& 50-20& 50-20& 50-20& 50-3&1	P
South Carolina. State of South Dakota. State of Southern California Edison Co	8403020339# 8403050113# 8403130236 8402030338 8402030338	HASTE MG 50-238 PR 50-204 50-204	77 R F F		8403230118 8403270164 8403270256 8403270256 8403270256	50-361 50-362 50-206 50-206 50-206	F
	8402030338 8402030344* 8402030344* 8402030344*	50-206 50-206 50-206 50-206 50-133	F F F		8403280002 8403280030 8403270122 8403270182 8403270217	50-361 50-206 50-206 50-206 50-361	F
	8403020010 8403020010 8403020040 8403020040 8403020072	50-361 50-361 50-361 50-361 50-361	R R R R	Boyland Power Cooperative, Inc. Spiegel & McDiarmid Stamiris, B	8403270275 8403300003 8403270102* 8403270176 8403140117	50-206 50-206 50-461 50-458 50-329	R I H
	8403020092 8403020098* 8403020098* 8403020218	50-361 50-361 50-361 50-206	P P R	Stan A, Huber Consultants, Inc Standard Oil Co of Indiana (see also AMGCD)	8403200137 7906250470* 8403210009	50-327 FOIA PR	
	8403020275	50-206	5	Standardized Nuclear Unit Power Plant System	8402070302	50-482	A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHÜR AFF]L]AT]ON	ACCESSION NUMBER	SUBJEC
	8403010213 8403010213 8403010213 8403010270 8403010270	50-482 50-482 50-482 50-482 50-482	0 0 F	Suffolk County, NY	8403200152* 8403010234 8403010237 8403010244 8403060208	50-423 50-322 50-322 50-322 50-322
	8403010270 8403010406 8403060298 8403130342 8403200050	50-482 50-482 50-482 50-482 50-482	FAAAE		8403060254 8403060259* 8403060266* 8403060226 840306027 0 *	50-322 50-322 50-322 50-322 50-322
	8403200187 8403200187 8403200187 8403200187 8403200189*	50 - 482 50 - 482 50 - 482 50 - 482 50 - 482	K K K F		8403040278* 8403040289* 8403040295* 8403040301*	50-322 50-322 50-322 50-322 50-322
	8403200253 8403200253 8403220017 8403220017 8403220017	50-482 50-482 50-482 50-482 50-482	F A A		8403060310* 8403060314* 8403060318* 8403060319*	30-322 50-322 50-322 30-322 50-322
	8403220026 8403220027 8403220027 8403220027 8403220184	50-482 50-482 50-482 50-482 50-482	A A A		8403040338 6403130003 8403130029 8403130146 8403130174	50-322 50-322 50-322 50-322
	8403220184 8403220184 8403260282 8403260282 8403260282	50-482 50-482 50-482 50-482 50-482	A A A		8403150026 8403200128 8403200131 8403200134* 8403200136*	50-322 50-322 50-322 50-322 50-322
State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs	8403270128 84032003 7 5	50-482 XPORTL I	a		8403200140* 8403200145* 8403200146*	50-322 50-322 50-322
Stone & Webster Engineering Corp	8403280072 8403290404 8403010115	XPORTL IC XPORTL IC TOPREP			8403200151* 8403200155* 8403200159*	50-322 50-322 50-322
	8403020290# 8403160096* 8403200182 8403270122# 8403270157*	50-322 50-412 50-423 50-322 50-322	E A R B		8403210186 8403220250 8403220268 8403220272*	50-322 50-322 50-322 50-322
Stone & Webster, Inc	8403300035 8403060407* 8403060411 8403060415* 8403060420*	50-329 50-329 50-329 50-329 50-329	8 8 8		8403220297* 8403220302* 8403220305* 8403220310* 8403220313*	50-322 50-322 50-322 50-322
	8403060423* 8403060428* 8403060442* 8403060444* 8403060445*	50-327 50-329 50-329 50-329 50-329	Q Q Q Q		8403280346 8403280357 8403280358 8403290248 8403290377	50-322 50-322 50-322 50-322 50-322
	8403080192 8403080192 8403080221 8403080221 8403080225	50-329 50-329 50-329 50-329 50-329	8 8 8 8	Suffulk Nuclear Study Group Sugainan & Denworth	8403290383 8403290390 8403300170 8403080363 8403130411	50-322 50-322 50-322 50-322 50-352
	8403080250 8403130074	50-329 50-329	9 5	Sunflower Alliance TDI (Transomerica Delaval, Inc.) Owners Group	8403270075 84030102 0 7	50-440 50-322
	8403130173 8403130173 8403130184	50-329 50-329 50-329	8 8 8		8403010218 8403140075* 8403150133	50-206 50-226 50-206
	8403130184 8403130175 8403130238 8403130238 8403130271	50-327 50-327 50-327 50-327 50-327	9 8 8 8 8		8403190385* 8403200143* 8403270132 8403270132 8403270132	50-022 50-022 50-022 50-022
	8403130297 8403130297 8403130321 8403130321 8403130388	50-329 50-329 50-329 50-329 50-329	0 0 5 8		8403270132 8403270132 8403270132 8403270132 8403270132	50-322 50-322 50-322 50-322 50-322
	8403130388 8403130470 8403130470 8403130479 8403150154#	50-329 50-329 50-329 50-329 50-204	A A A B S		8403270132 8403270132 8403270132 8403270132 8403270132	50-022 50-022 50-022 50-022 50-022
	8403270062 8403270062 8403270093 8403270096 8403270096	50-327 50-327 50-327 50-327 50-327	2000		8403270132 8403270132 8403270132 8403270132 8403270132	50-322 50-322 50-322 50-322
Streich, Lang, Werks & Cardon Structural Mechanics Associates	8403270227 8403300006 9403080365 8403140026*	50-327 50-327 50-528 50-327	8 D A		8403270132 8403270132 8403270132 8403270132	50-322 50-322 50-322

AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJECT	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGOR	
	8403270132 8403270134 8403270134 8403270134 8403270134	50-322 50-206 50-206 50-206 50-206	8 8 8 8		8403060189* 8403060189* 8403060189* 8403060189* 8403060189*	50-259 50-259 50-259 50-259 50-259	F F F F
	8403270134 8403270134 8403270134 8403270134 8403270134	50-206 50-206 50-206 50-206 50-206	5 9 9 5 8		8403060189* 8403060189* 8403060189* 8403060206* 8403060206*	50-257 50-257 50-257 50-257 50-257	F F F
	8403270134 8403270134 8403270134 8403270134 8403270134	50-206 50-206 50-206 50-206 50-206	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		8403060206* 8403060206* 8403060206* 8403060206* 8403060206*	50-259 50-259 50-259 50-259 50-259	1. 1. 1.
	8403270134 8403270134 8403270134 8403270134 8403270134	50-206 50-206 50-206 50-206 50-206	8 9 9 9		8403040204* 8403040235 8403040238 8403040244 8403040274	50-259 50-259 50-259 50-259 50-327	88 B H B B H
TERA Corp	8403270134 8403270134 8403270134 8403270134 8403050010*	50-206 50-206 50-206 50-206 50-312	ន ន ទ ម		8403060391 8403070023 8403070054 8403070066 8403070089	50-327 50-259 50-259 50-438 50-438	р 0 0
	8403060370 8403080260 8403220013 8403220013 8403220022*	50-329 50-329 50-329 50-329 50-329	A A R R R		8403070092 8403070155# 8403070174 8403070174 8403070224#	50-390 50-327 50-390 50-390 50-438	0 9 8 9
	8403220022* 8403220100 8403220100 8403220113 8403270159	50-329 50-329 50-329 50-329 50-329	R A A		8403070230 8403070235 8403070237 8403070241 8403070245	50-390 50-390 50-259 50-438 50-390	a a a
Tactec Systems, Inc Tameran, Inc Target Research, Inc	B403270159 B403280263* B403150278* B403150306* B403220173*	50-329 CONTRACT CONTRACT CONTRACT 40-8824	r		8403070271 8403070284 8403070286 8403070274 8403070274	50-257 50-370 50-390 50-438 50-438	0 8 8 8
Tayloe Associates Technical Operations, Inc Teledyne Engineering Services Teledyne Isotopes Tennessec Valley Authority	8403010437* 8403140151 8403070304 8403140144 8402070360	CONTRACT PR 50-245 PR 50-340	т Р F		8403070295 8403070295 8403070297 8403070297 8403070329	50~327 50~327 50~438 50~438 50~438	R R S S
	8402070380 8402070384* 8403010075 8403010226 8403010306	50-370 50-370 50-438 50-257 50-257	F F S S P		8403070327 8403090024 8403090050 8403090050 8403090085	50-438 50-438 50-390 50-390 50-259	8 8
	8403010306 8403010306 8403010313* 8403010313*	50-259 50-259 50-259 50-259 50-259	P P ያ		8403070143 8403070143 8403070181 8403070181 8403070206	50-438 50-438 50-438 50-438 50-370	8 8
	8403010339 8403010371 8403010376 8403020002 8403020002	50-390 50-259 50-438 50-327 50-327	5 5 8 R R		8403090206 8403090245 8403090253 8403120105 8403120105	50-390 50-259 50-259 50-438 50-438	9 9 8
	8403020103 8403020103 8403020147 8403020236 8403020236	50-259 50-259 50-327 50-390 50-390	R R S F F		8403120105 8403120143 8403120179 8403130007 8403130007	50-438 50-438 50-390 50-259 50-259	8
	B403020244 B403020313 B403020313 B403020325 B403020334	50-327 50-327 50-327 50-259 50-390	e e e e		8403130007 8403130025 8403130025 8403130025 8403130088	50-259 50-259 50-259 50-259 50-327	
	9403050090 8403060147 8403060147 8403060147 8403060147	50-327 50-259 50-259 50-259 50-259	8 F F F		8403130100# 8403130181 8403130205 8403150007 8403150059	50-327 50-260 50-259 50-439 50-438	8
	8403060147 8403060147 8403060163* 8403060163* 8403060163*	50-259 50-259 50-259 50-259 50-259	F F F		8403150079 8403150127 8403150229 8403160042 8403160171*	50-327 50-390 40-134 50-438 50-259	9 i 8
	8403040143* B403060163* B403060163* B403060163*	50-259 50-259 50-259 50-259 50-259	F F F F		8403160171* 8403160171* 8403160223* 8403160318* 8403160318*	50-259 50-259 50-259 50-259 50-259	0

,

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHDR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8403160318* 8403160364* 8403160373 8403160373 8403160373	50-259 50-390 50-259 50-259 50-259	Q Q P P P		8403070191 8403080927* 8403080932* 8403080935* 8403080315*	50-445 50-445 50-445 50-445 50-445	40000
	8403160373 8403160373 8403170054 8403170054 8403170079	50-259 50-259 50-390 50-390 50-390	P 8 9 8		8403130116 8403130126* 8403130126* 8403130136* 8403130160	50-445 50-445 50-445 50-445 50-445	* * * *
	8403170121 8403170125 8403170147* 8403170147* 8403170147*	50-327 50-259 50-259 50-259 50-259	8 9 9 9		8403130160 8403130313 8403130313 8403130319* 8403140013	50-445 50-445 50-445 50-445 50-445	Y F F O
	8403190161* 8403190287 8403190358 8403190358 8403190365	50-259 50-438 50-390 50-390 50-327	0 8 8 8		8403140013 8403140020 8403140020 8403140147 8403150032	50-445 50-445 50-445 PR 50-445	0
	8403190369 8403190370 8403190371 8403200059 8403200059	PR 50-327 50-257 50-259 50-259	F B Q		8403150103 8403160079 8403160079 8403160083* 8403160213	50-445 50-445 50-445 50-445 50-445	E V V
	8403200059 8403200087 8403200170 8403200170 8403200171	50-259 50-274 50-259 50-259 50-260	0 8 P P	Texas, State of Texas, Univ. of, Austin, TX	8403230059 8403270031 8403010132* 8403230025 8403140189	50-445 50-445 50-498 WASTE MOT PRM	H O O T
	8403200213 8403200225 8403210037 8403210037 8403210042	50-259 50-390 50-390 50-390 50-438	S A S S S	Three Mile Island Alert Titeflex Corp Toledo Edison Co	8403130045 8403240382 8403210075 8403270108 8401140250	50-289 50-289 50-346 0A999 50-346	8 6 6
	B403210042 B403210046 B403210066 B403210064 B403210086	50-438 50-438 50-390 50-390 50-390	\$ \$ \$ \$		8403020078 8403050107 8403070251 8403130133 8403130143*	50-346 50-346 50-346	R r r P
	8403210132 8403210132 8403220046 8403220159 8403220220	50-438 50-438 50-259 50-260 40-1341	9 9		8403130154# 8403130296 8403130429 8403130085 8403190109	50-346 50-346 50-346	9 9 9
	8403220224# 8403260164 8403260212 8403260212 8403260218	40-1341 50-327 50-390 50-390 50-390	8 4		8403170213 8403170311 8403170347* 840320008 8403200046		R F S O P
	8403260218 8403260229 8403260277 8403270145 8403270145	50-370 50-257 50-327 50-390 50-390	A P F F		8403200052* 8403200058* 8403200063* 8403230009 8403230167	50-346 50-346 50-346	55545
	8403270218 8403270218 8403270026 8403270038 8403270183*	50-390 50-390 50-327 50-327 50-259	E F P O		8403300149 8403300156* 8403300158* 8403300163 8403300178	50-346 50-346	64444
	8403270183* 8403270183* 8403270207* 8403300004 8403300004	50-259 50-259 50-259 50-438 50-438	0 0 8 8	Transmell, Chase, Lambert & Martindals Transamerica Delaval, Inc	8403300184 8403270334 8403120136 8403120180 8403130316	FOIA	R B
	8403300021 8403300021 8403300038 8403300038 8403300039	50-438 50-438 50-370 50-390 50-438	8 8 E 8	Transnuclear, Inc.	8403200222 8403020024* 8403020453* 8403140308* 8403150149	50-206 XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	8403300037 8403300054 8403300073 8403300107 8403300133	50-438 50-438 50-327 50-370 50-259	5 6 8 8 R		8403160167 8403160184* 8403260027 8403260030* 8403280055*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	-
	8403300133 8403300136# 8403300137#	50-259 50-259 50-259	R R R	Troutman, Banders, Lockerman & Ashmore Tufts Univ , School of Medicine, Medford, MA	8403080370 8403140172	50-424 PR	a
	8403300137* 8403300154 8403300204	50-259 50-327 50-328	R R B	MA U B Ecology, Inc. (formerly Nuclear Engineering. Inc.)	8402010341	27-48	
Tennessee, State of Terry Corp.	8403090105 8403210032	PR 50-280	B	and the second s	8403010349 8403020377	27-48 27-48	
Texas Utilities Electric Co. (formerly Texas Utilities Canarating Co.)	8403060155 8403060297	50-445 50-445	A	Union 76 Minerals Exploration Co Union Carbide Corp.	8403220068 8403220071* 8403010012	40-8594 40-8584 40-277	
							1

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	DRY	AF	AUTHOR FILIATION	ACCESSION NUMBER	BUBJECT	ŀγ
	8403070266 8403130045 8403130052* 8403150284 8403200394*	40~277 50~54 50~54 40~277 40~8681	P P	Vester J Thomps	son, Jr , Inc	8403300071* 8403300144* 8403300153 8403070161* 8403070167*	50-271 50-271 50-271 CONTRACT	
Union Ejettrit Co	8403220043 8403270178 8403300140* 8402270156 8403050016	50~54 50~54 70~687 50~483 50~483	I R F K	Vet Admin Hosp Vet Admin Hosp Vet Admin Hosp Veterans Admin Washington, DC	Lome Linda, CA Portland, DR	8403170326 8403270259 8403270253 8403270311 8403130302*	PR PRM PRM PRM 70-2199	
	8403050018# 8403050017# 8403070204 8403070263 8403070283	50~483 50~483 50~483 50~483 50~483	K F F F		Medical Center, Wood, WI It & Power Co	8403130308* 8403270257 8401130314 8403020001 8403020001	70-2199 PRM 50-280 50-338 50-338	P G G
	8403120104 8403120171 8403120182 8403130409 8403140246	50~483 50~483 50~483 50~483 50~483	A A A F F			8403020042 8403020042 8403020053 8403020059* 8403020063*	50-338 50-338 50-280 50-280 50-280	PPRRR
	8403140323 8403170034 8403170247 8403200028 8403200028	50~483 50~483 50~483 50~483 50~483	8 8 8			8403020066* 8403020071* 8403020076* 8403020085* 8403020090*	50-280 50-280 50-280 50-280 50-280	R R R R
	8403200237 8403200285* 8403210121 8403230115 8403270014	50~483 50~483 50~483 50~483 50~483	P Q A B A			8403020122 8403020195 8403040153 8403040397 8403040397	50-338 50-290 50-338 50-280 50-280	R P B F F
	8403270079 8403270182 8403270187 8403270229 8403300209	50-483 50-483 50-483 50-483 50-483	8 8 9 6 F			8403080071 8403080091 8403080091 8403080091 8403080091	50-339 50-280 50-280 50-280 50-280	111111
Union Minerals Union of Concerned Scientists	8403220117 8403220124* 8403280059 8310200141 8403010010	40-8584 40-8584 40-8584 FDIA 50-269				8403080091 8403080264 8403080264 8403080264 8403080264	50-280 50-280 50-280 50-280 50-280	44444
	8403010021 8403020056 8403020042 8403050017 8403050058	FOIA FOIA 50-286 FOIA	q			8403080264 8403080269* 8403080269* 8403080269*	50-280 50-280 50-280 50-280 50-280	# # # # #
	8403080003 8403080021 8403080344 8403080346 8403080354	FOIA 50-336 FOIA FOIA	Þ			#7420802048 #1420802048 #1420802048 #14208048 #1420802048	50-280 50-280 50-280 50-280 50-280	F 0 F F 8
United Engineers & Constructors, Int (subs of Raytheon Co)	8403210014 8403060311	50-289 50-443	e s			8403090213 8403090223	50-338 50-280	9
United Nuclear Corp	8403010289 8403150214 8403190234*	70-371 50-30 70-371	Ų:			8403090242 8403090250 8403120176	50-230 50-280	F B P
Upsala College, East Orange, NJ Uranerz USA, Inc Utah, State of Utah, Univ of, Salt Lake City, UT	8403070267* 8403190411 8403190412 8403140027 8403140145	70-474 40-8783 40-8783 WASTE MO 50-407	те -			8403120176 8403130278 8403130278 8403130424 8403140010	50-338 50-338 50-338 50-280 50-338	P P B
	8403200281 8403200281 8403200293* 8403200293*	50-72 50-72 50-72 50-72 50-72	ㅋ ㅋ ㅋ ㅋ ㅋ			8403160154 8403160154 8403160154 8403160154 8403160154	50-280 50-280 50-280 50-280	0 0 0 0
Utility Safety Classification Group Validyne Engineering Corp Vanderbilt Univ , Nashville, TN	8403200296* 8403280063 8403290305* 8403290308* 8403070414*	50-72 50-322 50-354 50-354 CONTRACT	F 0 A A			8403170052 8403170080 8403170201 8403170204* 8403170263	50-280 50-338 50-339 50-339 50-280	F 8 P P F
Vermont Yaakee Nuclear Power Corp	8403020247 8403020322 8403020326* 8403020328* 8403120003	50-271 50-271 50-271 50-271 50-271	ក 8 8 ទ ទ			8403170243 8403170377 8403170377 8403170381# 8403170381#	50-280 50-338 50-338 50-338 50-338	F P P
	6403120005* 6403130481 6403190066 6403200136 6403200274	50-271 50-271 50-271 50-271 50-271	P R G G			8403170376 8403170376 8403200116 8403210117 8403210117	50-338 50-338 50-280 50-280 50-280	9 F F
	8403200277* 8403230063 8403230140 8403270190	50-271 50-271 50-271 50-271	G F R P			8403220028 8403220028 8403220032* 8403220032*	50-338 50-338 50-338 50-338	PPP

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGOR	7Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8403220077 8403220077 8403230146 8403260105 8403260105	50-338 50-338 50-280 50-280 50-280	P F P	West Chicago, IL Wastern Illinois Power Cooperative, Inc Wastern Nebraska Resources Council Wastern Nuclear, Inc (subs of Phelps Dodge Corp)	8403020130 8403290107* 8403150286 8403150215	40-2061 50-461 40-8927 40-8684
	8403240110# 8403240110#	50-280 50-280	P P	Western Water Consultants, Inc	8403150212	40-8663
	8403270021 8403270021 8403270021 8403270208	50-280 50-280 50-280 50-280	0 0 0	Hestinghouse Electric Carp	8403010326 8403010463 8403010484 8403010545 8403050044	70-1143 XPORTLIC XPORTLIC XPORTLIC XPORTLIC
	8403270208 8403270248 8403280125 8403290157	50-338 50-339 50-280 50-280	P F Q		8403050047 8403050050 8403050120 8403060096* 8403060101*	XPORTLIC XPORTLIC QA999 QA999 QA999
	8403270240# 840330005 8403300028 8403300028 8403300055	50-336 50-338 50-336 50-336 50-336	0 P P N		8403060326* 8403070302* 8403090201 8403090259*	50-213 50-423 PR 50-348
Virginia, Commonwealth of, Virginia, Univ. up, Charlottesville, VA	8403300055 8403300040 8403300040 8403200331 8403010397	50-338 50-280 50-280 MASTE MG 50-62	R		8403120029# 8403120029# 8403130358# 8403130375# 8403130389# 8403130195	TOPREP 50-275 4 50-482 4 50-482 4 XPORTLIC
Washington Public Power Supply System	8201190297# 8208120240# 8208120240# 8208120240# 8208120240#	50-397 50-397 50-397 50-397 50-513	141		8403190139 8403190261* 8403190399* 8403190404* 8403210015	GA999 50-369 50-413
	8208120248* 8208120248* 8208120248* 8208120248* 8403020097	50-397 50-397 50-397 50-513 50-397	4 4 7 8		8403210020* 8403220294* 8403230208 8403240075* 8403260201*	TOPREP TOPREP XPORTLIC NUREG 50-266 50-244
	8403020330 8403070187 8403090118 8403090121 8403090236	50-397 50-397 50-508 50-397 50-397	9 0 3 9		8403240213 8403270057* 8403270277* 8403270282* 84032300116*	40-8585 FDIA 50-369 50-369 50-413
	8403120007 8403120199 8403130203 8403130227 8403130318	50-50B 50-50B PR 50-397 50-397	Ð A V P	Westinghouse Operating Plants Owners	8403300119# 8403300248 8403070104#	50-413 WASTE MGT FOLA
	8403130330*	50-397	P	Group	8403070108* 8403260024	FDIA TOPREP
	8403130337 8403130385 8403130480 8403200108	50-397 50-508 50-397 50-397	9 F P 8	Whicher, J M	8403160002 8403160002 8403160019 8403160019	50-454 50-454 50-454 50-454
	8403200234 8403200239 8403200241*	50-397 50-397 50-397	p B P	White & Williams	8403260351 8403080389	50-454 FOLA
	8403200261 8403210170 8403210172	50+397 50-50B 50-50B	P 0	White Piains, NY White Piains, NY When Laboratories, Inc. Will County, IL Williams & Associates	8403270306* 8403130249 8403080227 8403070046*	CONTRACT PRM 50-456 CONTRACT
	8403210189 8403220061 8403260006	50-508 50-397 50-397	Q Р F	Wisconsin Clinic Cancer Center, Madison,	B403290296 B403130327	PR PR
	8403260025 8403260165 8403260221 8403260274	50-397 50-397 50-509 50-397	8 A A	WI Wisconsin Alactric Power Co	8403069358 8403060358 8403070255	50-266 50-266 50-266
	8403240292 8403270118 8403270141 8403270207	50-397 50-397 50-397 50-397	je Gr F J		8403070255 8403070257* 8403070257* 8403120066 8403120066	50-266 50-266 50-266 50-266 50-266
	8403270220 8403280003 8403280007 8403270242	50-397 50-397 50-397 PR	8		8403120157 8403120157 8403130005 8403140139	50-266 50-266 50-266 50-266
Washington State Univ., Pullman, WA Washington Univ., St Louis, MO Washington, State of	8403300054 8403200238 8403260356* 8403120174	50-397 50-508 CONTRACT 50-508	R D		8403140139 8403160054 8403160080 8403210029	50-266 50-266 50-266 PR
Bashinshan, Ilain, at Garage	8403150151 8403160228 8403230188 8403230250	50-508 50-397 WASTE NO WASTE NO	Т		8403210077 8403220099* 8403220142	50-266 50-266
Washington, Univ. of, Seattle, WA Water, Waste & Land, Inc.	8403230160* 8403230160* 8403230197	CONTRACT CONTRACT NURED			8403220162 8403220167* 8403220167* 8403220068	50-266 50-266 50-266 50-301
Watkins, L. B. Waynesboro, OA	8403140009 8403140012* 8403230279	50~45B 50~45B 50~424	900		8403260072 8403270078	30-266 30-266
						r

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOOR	Y
	8403270125 8403270237 8403270049*	50-266 50-266 50-266	P P
Misconsin Public Service Corp	B402170104 B402170107*	50-305 50-305	P
	8403020295 8403050408 8403070169	50-305 50-305 50-305	₽ IP R
	8403130147 8403130188	50-305 50-305	R
	8403160298 8403160327	50-305 50-305	J P
	8403160331* 8403200016 8403200154	50-305 50-305 50-305	6 G
	8403210009 8403270030	PR 50-305	Р
	8403270032* 8403270038* 8403280048	50-305 50-305 50-305	₽ ₽
Hisconsin, Univ of, Green Bay, WI Hisconsin, Univ of, Madison, WI	8403220280* 8403090141* 8403200020 8403280314 8403280326	CONTRACT CONTRACT 50~156 ACRS ACRS	н
Wisconsin, Univ of, Milwaukse, WI Worcester Foundation for Experimental	8403290238 8403090186	PRM PRM	
Biology Hyoming Fuel Co Wyoming, State of	8403150319 8403150210 8403150253	40-8829 40-299 40-8786	
Wyoming, Univ of, Laramie, WY Yakima Indian Nation Yale Univ , New Haven, CT	8403150240 8403290301 8403230050 8403190295	40-8786 PRM WASTE MOT PR	
Yankee Atomic Electric Co	8403020072 8403020292	50-29 50-29	R
	8403080007 8403080009* 8403090175 8403120123	50-29 50-29 50-29 50-29	P S P
	8403120181 8403130287	50-29 50-29	R
	8403150100 8403160256 8403160256	50-443 50-443 50-443	9 F
	8403200215 9403200284 9403200288#	50-27 50-29 50-29	B P P
	8403200290* 8403210068	50-27 50-29	P
	8403210099 8403210099 8403210142 8403220005 8403220150	50-443 50-443 50-443 50-443 50-443	AAASS
	8403220164 8403230061 8403270003 8403270007	50-443 50-443 50-29 50-29	8 A P
	8403270121 8403270214 8403300083	50-443 50-29 50-29	A J R
Zetec, Inc. Zytor, Inc.	8403300172 8403190409* 8402140048*	50-29 50-317 50-528	9 0 0

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents,"

02-0140-1102 R02	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
02-0370-1132 ROO 02-0370-1139 ROO 04-5079-204 ROO 108025 RA 11600.02 13737-2-007-102 RO5 322258L-001 322258L-001 323258L-001 302310104	02-0140-1102 R02	8403010303*	50-388 E	
C4-5079-204 ROO 8403100128*	02-0370-1132 R00		50-219 G	
1600.25 RA	02-0370-1139 ROO	8403200067*		
11600.02 13737-2-007-102 R05 13737-2-007-102 R05 1323258L-001 13603-00000-76 136030000-76 136030000-76 136030000-76 136030000-76 136030000-76 136030000-76 136030000-76 136030000-76 1360300000-76 1360300000-76 1360300000-76 1360300000-76 1360300000-76 1360300000-76 1360300000-76 1360300000-76 13603000000000000000000000000000000000				IEB-BO-11
3737-2-07-102 R09	108025 RA	8403130128*	50-440 A	
325258L-001 903-8500000-76 8403060268 50-298 F 8403050227 8403050227 8403050227 8403050227 8403050224 8403050224 8403050224 8403050224 8403120255 8403120255 8403120257 8403120257 8403270329 8403300120 8403300120 8403300120 8403300120 8403300120 8403300120 8403300120 8403300120 8403300120 8403300120 8403300120 8403300120 8403170329 8403300120 8403170329 84031703				
S02-B500000-76				
### S4B-9834-2 RB ### S40310138* 50-440 A ### S403050227 ### S403050230 ### S0-280 ### S403050242 ### S403050242 ### S403050242 ### S403120255 ### S403120257 ### S403120255 ### S403120255 ### S403120255 ### S403120255 ### S403120257 ### S403120227 ### S403120222 ### S4031202				
### STATE				
8403050230 8403050242 8403150255 8403120257 8403120264 840310104 840301011 840310011 840310011 8	545-4634-2 KB	8403130138*	A 044-0C	
### ### ### ### ### ### ### ### ### ##				
### 8403120255 ### 8403120257 ### 85031202004 ### 8503120257 ### 85031202004 ### 85031202004 ### 85031202004 ### 85031202004 ### 85031202004 ### 85031202004 ### 85031202004 ### 85031200204 ### 85031200				
### 8403120257 REB #### 8403270327 REB #### 8403300120 REB #### 8403300120 REB #### 8403300120 REB #### 8403300120 REB ### 840300329 TOPREP ### 840310024 TOPREP ### 840310029 SO-318 P ### 8403020333 SO-382 A ### 840302033 SO-315 P ### 840302033 SO-315 P ### 840302033 SO-315 P ### 84032033 SO-346 P ### 84032031 SO-348 B ### 84032031 SO-349 P ### 84032031 SO-349 P ### 84032031 SO-349 P ### 84032031 SO-349 P ### 840320034 SO-249 P ### 840320034 SO-2				
### BA03270329				NRC-40-10-01-0
### ### ### ### ### ### ### ### ### ##	B403120257	8403120257	REB	
AEDD/E324 AEDD/T30B AEDJ/T30B ALG-137 BAH-1543 R02 BAH-1543 R02 BAH-1543 R00 CEN-203-NP R01 S01 BAU3130104* BAU31404* BA	6403270329	8403270329	REB	E00-BAAM-6499
AEDD/T30B ALDO/T30B ALDO/T				LBL-16152
### ALG-137 ### AGG070327* TOPREP ### TOP				
BAH-1543 R02				
CC-74-133 R00 CEN-203-NP R01 S01 CEN-2248(B) R02 CEN-2248(B) R02 CEN-259 B403130273* TOPREP B403120353* S0-318 P B40320335* S0-382 A CEN-26B CN31-WF-C-01-NP B401120550* CPL-13-103 R00 B403070318* B0-225 G B403070397 B403070318* B0-225 G B403070397 B403070318* B0-225 G B403070397 B403070397 B403070397 B403070397 B403070318* B403280113 B403280113 B403280124 B403280124 B403130118* B403280124 B403130118* B403280124 B40329018* B403290318* B4032903	ALG-137	8403070327*	TOPREP	
CEN-203-NP RO1 801 8403130273* TOPREP CEN-259 8403050103* 50-318 P 8403050103* 50-318 P 8403050103* 50-318 P 8403050103* 50-318 P 8403050333* 50-382 A 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	BAH-1543 RO2	8403190246*	TOPREP	
CEN-248(B) RO2 CEN-259 CEN-26B CEN-26B CN91-WF-C-01-NP CPL-13-103 RO0 CPC-13-62 EQC-EA-6413 EQC-EA-64	CC-74-133 ROO	B403130106*	50-440 A	
CEN-259 B403020335* 50-382 A CEN-26B CNS1-WF-C-01-NP B401120550* WASTE MOT CPL-13-103 R00 B403070318* 50-225 G DC-1362 B403070375* 50-206 E EG0-EA-6413 B403070375* 50-206 F EG0-EA-6413 B403070375* 50-315 P EQ0-EA-6542 B403070375* 50-315 P EQ0-EA-6542 B403070375* 50-316 P EQ0-EA-6549 R03 B402280725* 50-267 P B403280117 50-388 B EQ0-NTAP-6309 B403280117 50-388 B EC0-8AAM-6381 B403280113 50-313 B EC0-8AAM-6415 B403280112 50-318 B ERCD-693 B8-1000 R8 B403190282* 50-312 G B8-1000 R8 B403190282* 50-312 G B8-1000 R8 B403190282* 50-404 A 43704-2 FAAA-84-2-14 B40329018* 50-244 P GAI 2419 B40329018* 50-244 P GAI 2312 B40329018* 50-244 P ACI 2499 B40329018* 50-244 P ACI 2499 B403290199* 50-244 P ACI 2499 B403290199* 50-244 P ACI 2499 B403290199* 50-244 P ACI 2499 B403290319* TOPREP NEC-10 B403090319* TOPREP NEC-6 B403090319* TOPREP NEC-6 B403090318* TOPREP NEC-7 NEC-9 NED0-30242 B01 NFE-1583.04-1 A01 B403270024* 50-293 P NFD0-30242 B01 RVREQ-0020 V08 N01 B403210080* 50-324 P NUREC-0020 V08 N01 B403200400 NUREC NUREC-00304 V08 N04 B403200400 NUREC	CEN-203-NP ROI SOI	8403130273*	TOPREP	
CEN-26B CN31-MF-C-01-NP CPL-13-103 RO0 DC-1362 EG0-EA-6413 EG0-EA-6413 EG0-EA-6542 EG0-EA-6542 EG0-EA-6593 EG0-SAM-64915 EG0-SAM-6490919 EG0-SAM-64909		8403050103*		
CNST-WF-C-OL-NP	CEN-259	8403020335*	50-382 A	
CPL-13-103 ROO DC-1362 EQ0-EA-6413 B4030703793* 50-205 EQ0-EA-6413 B4030703793* 50-205 EQ0-EA-6542 EQ0-EA-6542 EQ0-EA-6294 RO3 EQ0-HB-6294 RO3 B403280333 B403280725* S0-247 EQ0-NTAP-6309 B403280117 S0-368 EQ0-SAAM-6415 B403280113 S0-313 B403280114 S0-313 BE0-693 B40319018* S0-313 BE0-693 B40319018* S0-324 BE-1000 RB B403190118* S0-340 A 43706-2 BFAAA-84-2-14 B403190118* S0-440 A 43706-2 BFAAA-84-2-14 B403290189* S0-244 P GAI 2512 B403290188* S0-244 P REC-10 B403990315* T0PREP NEC-4 B403990315* T0PREP NEC-6 B403290318* T0PREP NEC-9 RED0-24146A ERR 07 RED0-30242 B403270024* RHED0-30242 B403270024* S0-273 P RED0-30242 B403270024* S0-273 P RHED0-30242 B403270024* S0-273 P RHED0-30244 B4032700401 B40327	CEN-26B	8403140140*	TOPREP	
BC-1362 840350143* 50-206 8 EGQ-EA-6413 8403070375* 50-315 F EGQ-EA-6542 8403260335 50-416 P TAC 54185 EGQ-H8-6294 803 8402280725* 50-267 P EGQ-NTAP-6309 8403280117 50-388 6 EGQ-SAAM-6381 8403280113 50-368 8 EGQ-SAAM-6415 8403280124 50-368 8 ERCD-693 8403190282* 50-312 0 EB-1000 8 8403190182* 50-312 0 EB-1000 8 840319018* 50-440 A 43704-2 FAA-84-2-14 840319018* 50-224 P FME-R-6/7396 GAI 2479 840329018* 50-224 P P GJ-04(83) 8403220025* MASTE MOT P MPR-794 840329018* 50-219 P NEC-10 8403090319* TOPREP P NEC-9 8403090319* TOPREP P				
EGQ-EA-6413 8403070395* 50-315 P EGQ-EA-6542 8403260335 50-416 P TAC 54185 P EGQ-HB-6294 R03 8402280125 50-267 P EQQ-NTAP-6309 8403280117 50-368 S EGQ-SAAN-6391 8403280113 50-313 B EGC-SAAN-6415 8403280124 50-368 S ERCD-693 8403190282* 50-368 S ERCD-693 840319018* 50-340 A 43706-2 S EA-1000 RB 8403130118* 50-440 A 43706-2 S FAAA-84-2-14 8403210446* 50-322 S FME-R-6/7396 S GAI 2499 8403290189* 50-244 P GAI 2512 8403290189* 50-244 P GAI 2512 8403290188* 50-244 P GAI 2612 8403290188* 50-244 P AUGC-6 8403090315* TOPREP NEC-6 8403090315* TOPREP NEC-8 8403090315* TOPREP NEC-8 8403270186* 50-273 P NED0-30242 S01 8403270136* 50-273 P NED0-30242 S01 8403270024* 50-273 P NUREQ-0020 V08 N01 8403150058 NUREO NUREC		8403070316*		
EQO-EA-6542 8403260335 50-416 P TAC 54185 EGO-HB-6294 R03 8402280725* 50-227 P EQO-NTAP-6309 8403280117 50-358 8 EQO-BAAM-6391 8403280113 50-313 8 EGO-BAAM-6415 8403280124 50-368 8 ERCD-693 8403190282* 50-312 0 ER-1000 RB 8403190182* 50-440 A 43706-2 FAAA-84-2-14 840310918* 50-440 P GAI 2499 8403290189* 50-224 P GAI 2512 8403290189* 50-224 P GAI 2512 8403290189* 50-244 P GAI 2512 8403290189* 50-244 P RC-10 840319018* 50-247 P NEC-10 8403990319* TOPREP NEC-8 8403090319* TOPREP NEC-8 8403090316* TOPREP NEC-9 8403270136* 50-273 P NED0-30242 R01 8403270024* 50-273 P NED0-30242 R01 8403210080* 50-324 P NREC-0020 V08 N01 8403210080* 50-324 P NUREC-0020 V08 N01 8403210080 NUREC NUREC-0030 V08 N01 840320040 NUREC				
EGG-H8-6294 RO3 EGG-NTAP-6309 EGG-SAAM-6391 EGG-SAAM-6391 EGG-SAAM-6415 ERCD-693 EB-1000 RB EB-1000	EG9-EA-6413	8403070395*	50-315 P	
EGG-NTAP-6309 EGG-9AAH-6381 EGG-9AAH-6381 EGG-9AAH-6415 BH03280124 S0-368 ERCD-693 EB-1000 RB EB-10				TAC 54185
EGG-SAAM-6415 8403280113 50-313 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8				
ERCD-6493				
ERCD-693				
EB-1000 RB	EG0-8AAM-6415	B403280124	50-36B 8	
FAA-84-2-14 GAI 2497 GAI 2497 GAI 2512 GAJ-04(B3) MPR-794 NEC-10 NEC-6 NEC-6 NEC-7 NEC-9 NEC-0 N				
GAI 2499 GAI 2512 GAI 251				
GAI 2512 8403270188* 50-244 P GJ-04(83) 840322025* 50-219 P NEC-10 8403970319* T0PREP NEC-6 8403970315* T0PREP NEC-6 8403970315* T0PREP NEC-7 8403970315* T0PREP NEG-9 8403970318* T0PREP NED-2024144A ERR 07 8403270318* 50-247 P NEDD-30242 801 8403270022* 50-273 P NEDD-30242 801 8403270024* 50-273 P NEDC-30242 801 8403270024* 50-273 P NEDC-30242 801 8403210080* 50-324 P NUREC-0020 V08 N01 8403150058 NUREC NURE NUREC NUREC NURE NURE NURE NURE NURE NURE NURE NURE				FME-R-6/7396
QJ-04(83) 8403220225 WABTE MOT MPR-794 8403220004* 50-219 P TOPREP TOPREP TOPREP S403090319* TOPREP S403090318* TOPREP TOPREP S403090318* TOPREP S40300000000000000000000000000000000000				
MPR-794 8403220004* 50-219 P NEC-10 8403090319* TOPREP NEC-6 8403090318* TOPREP NEG-8 8403090318* TOPREP NEG-9 8403090318* TOPREP NED0-24146A ERR 07 8403270134* 50-249 P NED0-30242 801 8403270022* 50-273 P NED0-30242 801 8403270024* 50-273 P NPF-1583.04-1 A01 840310080* 50-324 P NUREC-0020 V08 N01 840310008* NUREC NUREC-00304 V08 N04 8403070401 NUREC NUREC-0304 V08 N04 8403070401 NUREC	GAI ESIS	8403270188*	50~244 P	
NEC-10 NEC-10 NEC-20 NEC-3 NEC-3 NEC-3 NEC-9 NEC-9 NECD-24146A ERR 09 NEDD-30242 NEDD-30244 NEDD-30244 NEDD-30244 NEDD-30244 NEDD-30244 NEDD-30244 NEDD-30244 NEDD-30244 NEDD-30244 NUREC-0020 NUREC-0020 NUREC-0020 NUREC-00304 NUREC-00		8403220225		
NEC-5 NEC-8 NEC-9 NED-24144A ERR 07 NEDD-30242 NEDD-3024 NEDD-30242 NEDD-3024				
NEG-8 8403090318* TOPREP NEG-9 NEG0-24146A ERR 07 NED0-30242 NOTE0-0020 NOTE0-0020 NOTE0-0030				
NEG-9 NEDD-204144A ERR 07 NEDD-30242 NEDD-30242 NEDD-30242 NF-1583.04-1 A01 NF-1583.04-1 A01 NUREC-0020 V08 N01 NUREC-0020 V08 N01 NUREC-00304 V08 N04 NUREC-00304 V08				
NEDD-24144A ERR 09 8403270134* 50-249 P 79NED273 NEDD-30242 8403270022* 50-273 P 8403270024* 50-249 P 8403270024* 50-249 P 8403270080* 50-324 P 840321080* 50-249 P 79NED273 P 840321080* 50-249 P 79NED273 P 840321080* 50-249 P	NEG-8	8403070318*	TOPREP	
NEDD-30242 8403270022* 50-273 P NEDD-30242 801 8403270024* 50-273 P NF-1583.04-1 A01 8403210080* 50-324 P NUREO-0020 V08 N01 8403150080 NUREO NUREO-0072 R01 8403020460 NUREO NUREO-0304 V08 N04 8403070401 NUREO				
NEDD-30242 801 8403270024* 50-273 P NF-1583.04-1 A01 840321088* 50-324 P NUREC-0020 V08 N01 8403150058 NUREC NUREC-0072 R01 8403150058 NUREC NUREC-0304 V08 N04 8403070401 NUREC				79NED273
NF-1583.04-1 A01 8403210080* 50-324 P NUREC-0020 V08 N01 8403150058 NUREC				
NUREO-0020 V08 N01 8403150058 NUREO NUREO-0072 R01 8403020460 NUREO NUREO-0304 V08 N04 8403070401 NUREO				
NUREQ-0072 R01 8403020440 NUREC NUREQ-0304 V08 N04 8403070401 NUREO	MF-1083, U4-1 AU1	8903210080 *	DO-984 P	
NUREQ-0304 VOB NO4 8403070401 NUREQ		8403150058	NUREO	
		8403020440	NUREO	
NURED-0430 V04 N01 8403220189 NUREO				
NUREQ-0340 V05 N12 8403260289 NUREQ	NUREG-0540 V05 N12	8403260289	NUREG	

REPORT	ACCESSION	SUBJECT	OTHER REPORT
NUMBER	NUMBER	CATEOURY	NUMBER
NUREO-0606 VO6 NO1	8403230212	NUREG	
NUREO-0675 517	8403070104	50-275 E	
NUREO-0675 522	8403300300	50-275 E	
NUREO-0748 VO4 NO1	8403270269	NUREG	
NUREO-0750 V18 NO4	8403230183	NUREG	
NUREO-0885 103	8403150211	NUREG	
NUREO-0936 VO2 NO4	8403020165	NUREG	
NUREO-0978 FC	8403220326	NUREG	
NUREO-1015	8403230190	NUREG	
NUREO-1015	8403070121	NUREG	
NUREQ-1037	8403070385	NUREG	
NUREQ-1047	8403270267	70-27	
NUREQ-173/022	8403270344*	50-528 D	
NUREQ/DR-0025 V10 N2	8403260280	NUREG	
NUREQ/DR-0031 V05 N3	8403260056	NUREG	
NUREG/BR-0059 R01 ER NUREG/CR-2000 V03 N1 NUREG/CR-2050 NUREG/CR-2015 DRFT NUREG/CR-2896 V01	8403070397 8403070392 8403050029# 8403010041# 8403300261	NUREO NUREO 50-286 P FGIA NUREG	ORNL/NSIC-200 UCRL-53024 BNL-NUREG-51559 ANL-82-25 VO1
NUREO/CR-2876 VO2 NUREO/CR-3067 NUREO/CR-3091 VO3 NUREO/CR-3104 NUREO/CR-3145 VO2	8403300285 8403060533 8403070115 8403230177 8403230131	NUREG HUREG NUREG NUREG NUREG	ANL-82-25 VO2 ENICO-1125 BNL-NUREG-51430 PNL-4583
NUREO/CR-3193	840326028 <i>b</i>	NUREO	ORNL/TM-8653
NUREO/CR-3224	840323021 <i>b</i>	50-537 A	LA-9716-49
NUREO/CR-3279	840330032 <i>5</i>	NUREO	ORNL/TM-8755
NUREO/CR-3309	840330034 <i>2</i>	NUREO	SANDE3-7095
NUREO/CR-3334 VO3	840330031 <i>7</i>	NUREO	ORNL/TM-8787/V3
NUREO/CR-3390 NUREO/CR-3422 VD2 NUREO/CR-3427 VD3	8403230197 8403150219 8403300294	NUREO NUREO NUREO	WWL/TM-1791-1 DRNL/TM-8849/VR
NUREQ/CR-3449	840307011 <i>8</i>	NUREG	ORNL/TH-8694
NUREQ/CR-3501	840320035 <i>8</i>	NUREG	
NUREO/CR-9508	8403190444	NUREG	ORNL/9UB-7576/3
NUREO/CR-9529	8403300306	NUREG	ORNL/TM-8950
NUREO/CR-9529	8403230139	50-313 P	BNL-NURE0-51721
NUREO/CR-9549	8403300318	NUREG	ORNL/TM-8909
NUREO/CR-3540	8403230173	NUREG	PNL-4904
NUREQ/CR-3573 NUREQ/CR-3601 NUREQ/CR-3605 NUREQ/CR-3607	8403170447 8403070107 8403150214 8403070073 8403230200	NUREG NUREG 50-30 % NUREG NUREG	PNL-4923 PNL-4813
NUREO/CR-3622 NUREO/CR-3645 NUREO/CR-3649 NUREO/CR-3661 NUREO/CR-3666	8403230257 8403170055 8403070114 8403230208 8403170437	NUREG NUREG NUREG NUREG NUREG	URNL/TM-8841 PNL-4906 ANL-83-20 EPRI NP-3494
NUREO/CR-3674 NUS-4507 01-0780-1269 RO1 P-281/2 PAD 7394	8403230207 8403260253* 8403200269* 8401240211* 8403140086*	038UN 250-00 A SEP-00 A SEP-00	•

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
PNL-4515	8403140170*	PR	UC-41
PGP-124	8403090199#		NRC/1E-B2/83
GTR 82-003	8403270308*	50-354 A	
GTR-82-010	8403270305*	50~354 A	
R-1208671-001	B403010097#	FOIA	
R-8212	B403090323#	WASTE MOT	UMTRA-DDE/ALD-
R-8215	8403050319#	WASTE MOT	DOE/UNT/0232
R-8216	8403050322*	WASTE MOT	DOE/UNT/0234
R-8217	8403050318*	WASTE MOT	DOE/UNI/0234
R-900-74-2	8403080409*	50-528 A	
RERR-151	8403070241*	50-272 R	RERR-15I
RHO-BW-SA-286 P	8403260347*	WASTE HOT	
R IL-137	B403150175	RE8	
SAI-1-148-08-781	8403050032*	70-697	
BAI-186-028-20	8209030161*	50-280 G	
SANDB2-1457	B4030B0029#	FOIA	
10V SE07-28DNAS	8403080008*	FOIA	CJ905-18E101A2
SANDB2-7032 VO2	8403080017#	FDIA	SAI01381-308LJ
SAND82-7032 VO3	8403080025*	FOIA	SAI01381~295LJ
BAND82-7219 VO1	84030B0010*	FOIA	5A101381-410LJ
SAND82-7219 VO2	B4030B0012#	FOIA	SAI013B1-411LJ
SANDB2-7219 VO3	B403080019*	FOIA	SAI01381-412LJ
SAND82-7220	8403080006#	FOIA	SAI01580-379LJ
SECY-78-569	8403050031*	FOIA	
EECY-82-037	8203050065*	FOIA	
SECY-82-037A	B204160230*	FOIA	
SECY-82-340	B209200364*	FOIA	
SECY-83-034	8403010451	50-204 8	
SECY-83-445	8403090019*	FOIA	
SECY-03-454	8403020074*	FOIA	
SECY-84-067	8402220050	BECY	
SECY-84-067A	8403080434	BECY	
SECY-84-095	84030B0041	SECY	
8MA 13701 05R003 VIO	8403140026*	50-329 A	
SMA 20601 01-R1-0	B403200152*	50-423 A	
85-152	8403060366*	50-302 P	
BWECO 7703	8403160096*	50-412 A	EMTR-801
TER-C5504-425	B403150045*	50-237 P	TAC 49361
UC ID-19130 UMTRA-DDE/AL-0099-F	8403050038*	50-284 P	
	8403060521*	MUSIC IIVI	
UTEC HE 84-0205	8403200293*	50-72 F	
V-PAK-481	8403070014*	50-528 E	
WCAP-10433	8403060326*	50-213 P	
WCAP-10474 HCAP-1048E (NP)	8403090259* 8403190404*	50-349 P 50-413 A	
WCAP-8587 ROESE-47AD WCAP-8587 ROHE-108 D	8403130375* 8403130387*		EGDP-ESE-47A EGDP-HE-109
WCAP-0507 R4ESE-13D	8403130359*		EODP-ESE-13
XN-NF-82-32 (NP) RO2	B4030B0223*	50~316 P	LUDI LOE-13
XN-NF-62-90 (NP) 501	8403150104*	50-316 P	XN-NF-82-90(NP)
XN-NF-83-85	8403000030=	50-314 P	
XN-NF-83-85 RO1 SO1	8403080220* 8403200101*	50-316 P	
XN-NF-83-85 501	8403080210*	50-316 P	
XN-NF-94-14	8403230102*	50-255 P	
XN-NF-84-18	#4010E2E04B	50-255 P	
XN-NF-84-21 (NF)	8403080216*	50-316 P	
XN-NF-84-24	8403230111*	30-255 P	
YAEC-1398	8403080009*	50-29 P	

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

SUR MET

FOTA

CATEODRY

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed Items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

		01.00,04		
7704030135	8403080126	B4/03/01	FOIA	
7906140345	8403010123	B3/12/20	50-312	P
7906140548	8403010123	93/12/20	50-312	P
7906190142	8403050288			
* 100170145	940300U268	84/02/17	50-460	F
7906250470	8403080207	84/01/23	FDIA	
7908010102	8403050268	84/02/17	50-509	Α
7908010232				
	8403050288	84/02/17	50-397	Α
7910260122	8403010123	83/15/50	50-312	P
7911120317	E403010123	83/12/20	50-312	F
7911120366	E403010123	00/40/00	¥0 0.0	_
		83/12/20	50-312	P
7911120370	8403010123	83/12/20	50-312	P
7911120403	8403010123	83/12/20	FOIA	
7911120413	8403010123	83/12/20	50-312	P
7912050523	8403050020	83/12/07	50-284	Ö
8001140316	8403080179	84/02/13	50-440	A
1100721008	6403010123	83/12/20	50-312	P
8003240159	8403010050	84/01/17	50~508	Α
6003240202	8403080179	84/02/13	50-508	Ä
8003240207	8403080179	84/02/13	50-50B	Ä
COMPRADADI	8403080177	94/02/13	20-20B	~
8003240209	8403050299	84/02/17	50-508	Α
8003240217	8403080179	84/02/13	50-50B	Α
B003240222	8403080179	B4/02/13	30-50B	Ä
B003250477	8403080179	84/02/13	50-397	ö
B003270142				
COUNTY	8403080179	84/02/13	50~397	D
8004010752	8403010050	84/01/17	50-50B	Α
B004010759	B403010050	B4/01/17	50-508	Ä
B005010203	B403080016	64/01/11	FOIA	**
8005130793				_
	8403080179	B4/02/13	50-387	E
8005150677	8403080179	84/02/13	FOIA	
E005150483	B4030B0179	84/02/13	FOIA	
8005280995	8403080016	84/01/11	FOIA	
6005280978	84030B0016			
		64/01/11	FOIA	_
8009090737	8403080179	64/02/13	50-344	P
B007110203	8403080179	84/02/13	50-397	U
B009250342	8403010193	83/12/20	50-312	p
B007250345				
	B403010123	83/12/20	20-315	P
8010090260	B4030B0179	B4/02/13	50-460	Α
8010230503	8403080014	E4/01/11	FOIA	
B011070522	B403010117	84/01/25	50-317	P
8011120101	646000000	D . 100	FD14	
	8403050288	84/02/17	FOIA	
8012160551	84030B0179	B4/02/13	50-397	U
8101040747	8403080179	84/02/13	50~397	A
E4001130343	8403080179	84/02/13	50-508	U
8101290708	84030B001A	84/01/11	FOIA	-

8403080126

8403080124 8403080179

840308001A 8403080014

B101300020

8101300025 8102200027 8102240058 8102240064

B4/03/01

84/03/01 84/02/13 84/01/11

FOIA

FOIA 50-466 FOIA

A

ACCESSION NUMBER

ENCLOBURE

7904030132

PRINCIPAL

DOCUMENT

8403080126

DATE

84/03/01

	PRINCIPAL	DATE	SUBJEC.	т
ENCLOSURE	DOCUMENT	IASUED	CATEQUI	
CHPCOSONE				
8103040048	8403050020	83/12/07	50-286	P
8103040052	8403090179	£4/Q2/13	50-397	E
B103050718	8403050020	83/12/07	FOIA	
0103250553	8403010117	84/01/25	FOIA	
8103250430	8403010117	84/01/25	FOIA	
B104210125	8402230207	83/12/02	50~400	0
8104220329	8403000179	84/02/13	50-460	A
8104220881	8403050020	83/12/07	50-286	p
0104300020	8403080179	84/02/13	50-397	A
0105010554	8403080179	84/02/13	50-440	Α
8105140106	B4030B0179	84/02/13	50-460	A
ACF0816018	8403080179	84/02/13	50-440	A
0105210109	8403080179	B4/02/13	50-460	Α
B106170138	8403080179	84/02/13	FOIA	
8106220084	8403080179	84/02/13	うり~50日	a
B1071305B1	8403080179	84/02/13	50-50B	a
8107140185	8403080179	84/02/13	50-508	G.
8107140192	8403080179	84/02/13	50-50B	Œ
8107140213	8403010117	84/01/25	FDIA	
8107160215	8403010117	64/01/25	FDIA	
8107200104	8403200080	01101117	FOIA	
		84/01/17		
8107270274	6403080179	84/02/13	50-50B	Α
8107280171	8403090179	84/02/13	50-460	Α
8108110038	8403080179	B4/02/13	50-460	Α
8108270490	8403080390	B4/02/13	50-528	Ď
GIGORYOTIO	2-0000010	D41 0K1 1D	#0 DEG	
9109180036	8403010117	84/01/25	FOIA	
8110080612	8403080179	B4/02/13	50-460	Α
8110170026	8403080179	84/02/13	50-508	F
8110190051	8403050288	B4/02/17	50-397	Α
8110510314	8403050288	84/02/17	50-460	A
8111020578	B40305028B	84/02/17	50-50B	Α
8111060697	8403080179	84/02/13	50-460	Α
8111120935	8403080179	84/02/13	50-460	E
0111130007	8403080179	84/02/13	50-460	Ā
8111200219	8403080179	84/02/13	50-397	A
8112020204	8403010050	84/01/17	50-412	Α
8112210135	B403010050	84/01/17	50~50B	Α
8112300305	B4030B0179	84/02/13	50~460	A
6201170277	B403080179	84/02/13	50-397	F
9201220170	8403050020	B3/12/07	FOIA	
9201300234	8403050288	B4/02/17	50-397	A
8202120295	8403010117	84/01/25	FOIA	
8202180456	8403080179	84/02/13	50-460	F
				r
8202220056	8403020014	83/12/16	FOIA	_
8202260171	8403080179	84/02/13	50-460	C
8203020139	84030B0179	84/02/13	50-460	F
8203050045	B403090006	84/02/22	FOIA	•
				6
8203100419	B4030B0179	84/02/13	50-460	
8203100570	8403080179	84/02/13	50-397	C
8203120197	B403010117	84/01/25	FOIA	

ACCESSION NUMBER

ACCESS10	N NUMBER				ACCEB910				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJEC		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1880ED	SUBJECT	
8203150028 8203180004 8203180118 8204070077 8204160230	8403080179 8403080179 8403080179 8403080179 8403090006	84/02/13 84/02/13 84/02/13 84/02/13 84/02/22	50-460 50-460 50-508 50-460 FOIA	C A C	8307210078 8307210114 8307210434 8307220297 8307220297	8403050064 8403050064 8403080367 8403050020 8403050064	84/02/07 84/02/07 84/02/28 83/12/07 84/02/07	50-400 50-400 50-322 FDIA 50-400	E
8204290657 8205070088 8205120076 8205270420 8206300082	8403080179 8403080179 8403050064 8403050064 8403080179	84/02/13 84/02/13 84/02/07 84/02/07 84/02/13	50-50B 50-460 50-400 50-400 50-508	A F E A	B309260018 B309260421 B309260412 B309260510 B309290412	8403050064 8403050064 8403050064 8309260515 8403050064	84/02/07 84/02/07 84/02/07 83/09/08 84/02/07	50-400 50-400 50-400 50-311 50-400	REBE
8207140072 8208090297 8208120240 8208120248 8208240003	8403050064 8403050020 8403080177 8403080179 8403050223	84/02/07 83/12/07 84/02/13 84/02/13 84/02/07	50-400 50-286 50-397 50-397 FDIA	E 0 F F	8309290474 831006077 8310060317 8310130378 8310170095	8403050064 8310060076 8402210338 8403050064 8403050064	84/02/07 83/09/21 84/02/10 84/02/07 84/02/07	50-400 MIBC 50-285 50-400 50-400	E 0 E
8209030141 8209200364 8209280165 8210220012 8210220014	8403140179 8403060469 8403080179 8403020014 8403020014	84/02/28 84/02/17 84/02/13 83/12/16 83/12/16	50-280 FOIA 50-460 FOIA FOIA	q q	8310170712 831019067 8310200094 8310280188 8310310445	8403050020 8403050064 8403050064 8310280186 8403050064	83/12/07 84/02/07 84/02/07 83/09/08 84/02/07	50-286 50-400 50-400 50-278 50-400	PE BE
B210220084 B211090008 B211090018 B211090035 B211110461	8403020014 8403050064 8403010050 8403050064 8403050064	83/12/16 84/02/07 84/01/17 84/02/07 84/02/07	FDIA 50-400 50-556 50-400 50-400	E E E	B310310471 B310310475 B311020253 B311100047 B311110263	8403010198 8403010198 8311020249 8403050064 8403050064	83/12/14 83/12/14 83/09/08 84/02/07 84/02/07	50~329 50-329 50-316 50~400 50~400	AASEE
B211160112 B211170249 B211170102 B211170103 B211300017	8403050064 8403050064 8403020014 8403020014 8403050064	84/02/07 84/02/07 83/12/16 83/12/16 84/02/07	50-400 50-400 FOIA FOIA 50-400	E	8311140004 8311140170 8311140248 8311140250 8311150481	8403050064 8307260036 8307260036 8307260036 8403010117	84/02/07 83/07/15 83/07/15 83/07/15 84/01/25	50-400 ACRB ACRS ACRS 50-312	E
8212070382 8212080492 8212100130 8212100130	8403080179 8403020014 8403020014 8403020014 8403020014	84/02/13 83/12/16 83/12/16 83/12/16 83/12/16	50-440 50-267 50-267 FOIA 50-267	A P P	8311160283 8311160367 8311230247 8311290301 8311290302	8403050064 8403050064 8403010100 8403050064 8403050064	84/02/07 84/02/07 83/12/22 64/02/07 84/02/07	50-400 50-400 FOIA 50-400 50-400	E
821216059 8212160163 8212160220 8212300403 8301060211	8403020014 8403050064 8403050064 8403050064	83/12/16 84/02/07 84/02/07 84/02/07 84/02/07	50-267 50-400 50-400 50-400 50-400	P E E E	8312010004 8312020063 8312080628 8312070022 8312070298	8403010198 8403050064 8403010198 8403010198 8403010198	83/12/14 84/02/07 83/12/14 83/12/14 83/12/14	50-329 50-400 50-329 50-329 50-329	AEAAA
B301060420 B301140173 B301140474 B301140486 B301140470	8403010024 8403080375 8403050064 8403020014 8403020014	84/01/18 84/02/17 84/02/07 63/12/16 63/12/16	FOIA FOIA 50-400 50-267 50-267	E. P	8312080134 8312080188 8312120002 8312120004 8312120445	8403010198 8403050064 8403050064 8307260036 8403050064	83/12/14 84/02/07 84/02/07 83/07/15 84/02/07	50-329 50-400 50-400 ACRS 50-400	A E E
8301140494 8301260036 8301280380 8302250083 8303080290	8403020014 8403050044 8403010262 8403010050 8403050020	83/12/14 84/02/07 83/12/20 84/01/17 83/12/07	50-267 50-400 50-382 50-513 50-286	P A A P	8312140347 8312140351 8312140489 8312150232 8312150241	8402090030 8402090030 8403050044 8403280163 8307240034	84/03/02 84/03/02 84/02/07 84/02/17 83/17/15	50-275 50-275 50-400 FOIA ACRS	EEE
8303100474 8303170017 8304040552 8304040577 8304070113	8403080179 8303170014 8403010050 8403080179 8403080179	84/02/13 83/03/02 84/01/17 84/02/13 84/02/13	50-397 50-315 50-397 50-397 50-397	A 0 A A	8312190356 8312230234 8312230241 8312280298 8312280099	8307260036 8403080405 8403080347 8403050064 8402090030	83/07/15 84/03/02 84/03/02 84/02/07 84/03/02	ACRB 50-275 50-334 50-400 50-275	PPEE
8304260013 8305040013 8305040155 8305060342 8305090506	8403020014 8403010024 8305040149 8305060337 8403010050	93/12/16 84/01/18 93/04/19 83/04/23 84/01/17	50-267 FOIA 50-273 50-324 50-509	P 8 8	8312280102 8312280107 8401040010 8401120180 8401120428	8402070030 8402070030 8402070030 8401120171 8401120425	84/03/02 84/03/02 84/03/02 83/09/16 83/12/30	50-275 50-275 50-275 40-3453 50-445	EEA
8305110054 8305170497 8305230119 8305230546 8305270056	8403010014 8305190492 8403050020 8405230539 8305270051	84/01/03 83/04/20 83/12/07 84/03/28 83/04/25	50-289 TOPREP 50-286 50-327 50-338	P P S S	8401120433 8401120437 8401120530 8401120597 8401120600	8401120425 8401120425 8401120525 8401120574 8401120574	83/12/30 83/12/30 83/11/30 83/12/30 83/12/30	50-445 50-445 Waste Mo 50-348 50-348	A A T P
8306220210 8307180403 8307180414 8307290506 8308040003	8403070215 8403080347 8403080347 8403050020 8403050020	84/01/23 84/03/02 84/03/02 83/12/07 83/12/07	50-440 50-344 50-344 50-286 50-286	A P P P	8401230660 8401240211 8401240315 8401240340 8401250456	8401230530 8401240207 8401240304 8401240337 8402270004	83/11/01 84/01/18 84/01/10 84/01/19 84/02/21	50-329 50-352 70-27 70-1100 50-247	8 A P
9308040578 830809070 9308100483 8308150440 8308170191	8307250036 8403080357 8403010050 8403070101 8403010013	83/07/15 84/02/28 84/01/17 84/02/14 84/01/03	ACRS FOIA 50-397 FOIA 50-447	A	8401250468 8401250476 8401250510 8401260167 8402010185	8402290004 8402290004 8402290004 8401260161 8402010178	84/02/21 84/02/21 84/02/21 84/01/18 84/01/25	50-267 50-267 50-267 50-264 GA999	PPF
8307040370 8307120554 8307120400 8307120401 8307200478	84030500A4 8403060091 8403010117 8403010117 84030500A4	84/02/07 84/01/23 84/01/25 84/01/25 84/02/07	50-400 FDIA FDIA FOIA 50-400	E	8402010508 8402020093 8402030344 840203055 8402040421	8402090017 8403120305 8402030338 8403060529 8403060419	84/02/27 84/02/27 84/01/27 84/02/17 84/01/30	50-275 50-293 50-206 MISC 50-302	P F F

ACCESSION	NUMBER				AC CESS I ON				
ENCLOBURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
6402070057 6402070183 6402070184 6402070384	8402070054 8402090003 8402090003 8402090380	84/01/31 83/10/31 83/10/31 84/02/04	50-400 50-352 50-443 50-390	0 A A F	8403010097 8403010098 8403010102 8403010104	B403010092 B403010091 B403010094 B403010100	84/02/09 84/02/14 84/01/03 83/12/22	FOIA CONTRACT FOIA FOIA	
8402130353 8402130353 8402130360 8402130390 8402130392	8402130393 8402130393 8402130393 8402130393	84/02/23 84/01/31 84/01/31 84/01/31	MISC 50-358 50-358 50-358 50-358 50-358	บ บ บ บ บ	8403010108 8403010114 8403010124 8403010127 8403010128	8403010100 8403010113 8403010110 8403010117 8403010110 8403010117	84/02/10 84/02/22 84/02/22 84/01/25 84/02/22 84/01/25	FOIA 50~50B 50~321 FOIA 50~321 50~34B	T P P
8402130399 8402130399 8402130404 8402140022 8402140026 8402140028	8402130373 8402130373 8402130400 8402140018 8402140018	84/01/31 84/01/31 84/02/08 83/12/20 83/12/20 83/12/20	50-358 50-348 50-528 50-528 50-528	U	8403010127 8403010132 8403010132 8403010138 8403010139	8403010117 8403010117 8403010117 8403010117 8403010125	84/01/25 64/01/11 84/01/25 84/01/25 84/01/11	FOIA 50~498 50-348 FOIA 50-498	g P T
8402140031 8402140032 8402140034 8402140037 8402140038	8402140018 8402140018 8402140018 8402140018 8402140018	83/12/20 83/12/20 83/12/20 83/12/20 83/12/20	50~528 50~528 50~528 50~528 50~528	G G G G	8403010141 8403010143 8403010146 8403010147 8403010150	8403010117 8403010136 8403010117 8403010136 8403010123	84/01/25 84/02/21 84/01/25 84/02/21 83/12/20	50-348 50-416 50-348 50-416 50-312	Р Р Р
8402140043 8402140048 8402140052 8402140193 8402140327	8402140018 8402140018 8402140018 8402140189 8402140325	83/12/20 83/12/20 83/12/20 84/01/10 84/02/08	50-528 50-528 50-528 50-261 40-8102	G G G	8403010151 8403010152 8403010153 8403010155 8403010156	8403010117 8403010117 8403010149 8403010134 8403010117	84/01/25 84/01/25 84/01/24 84/02/16 84/01/25	FDIA 50-348 71-511 50-267 50-348	P S P
8402140536 8402150216 8402150226 8402160020 8402170107	8402140527 8402150211 8402150211 8403070103 8402170104	84/01/17 83/12/28 83/12/28 84/02/23 84/02/14	50-331 GA999 GA999 MIBC 50-305	P	8403010159 8403010161 8403010163 8403010164 8403010166	8403010117 8403010117 8403010117 8403010117 8403010162	84/01/25 84/01/25 84/01/25 84/01/25 84/01/24	FDIA FOIA 50-348 FOIA 71-6206	р
8402170166 8402170176 8402210343 8402210348 8402210357	8402170156 8402170156 8402210338 8402210338 8402210338	84/02/14 84/02/14 84/02/10 84/02/10 64/02/10	50-285 50-285 50-285 50-285 50-285	P P G Q Q	8403010167 8403010171 8403010175 8403010177 8403010178	8403010134 8403010140 8403010117 8403010140 8403010117	84/02/14 84/02/22 84/01/25 84/02/22 84/01/25	50-267 50-250 50-344 50-250 FOIA	ե ե
B402220303 B402230226 B402230237 B402230239 B402230242	8402220288 8402230207 8402230207 8402230207 8402230207	84/02/14 83/12/02 83/12/02 83/12/02 83/12/02	50-289 50-400 50-400 50-400 FOIA	U A G A	8403010180 8403010181 8403010184 8403010185 8403010191	8403010173 8403010117 8403010117 8403010117 8403010117	B4/02/23 B4/01/25 B4/01/25 B4/01/25 B4/01/25	50-250 FOIA FOIA FOIA	F
8402230246 8402230248 8402230251 8402240387 8402270314	8402230207 8402230207 8402230207 8403070103 8402270263	83/12/02 83/12/02 83/12/02 84/02/23 84/01/30	50~400 50~400 50~400 MISC 50~321	A A A	B403010193 B403010194 B403010194 B403010199 B403010201	8403010117 8403010186 8403010117 8403010186 8403010117	84/01/25 84/02/21 84/01/25 84/02/21 84/01/25	FDIA 50-247 FOIA 50-247 FOIA	P P
8402280725 8402290440 8403010004 8403010015 8403010020	84031200B1 8403150178 8403010003 8307260034 8403010014	84/03/06 84/02/27 84/01/20 83/07/15 84/01/03	50-267 50-508 CUNTRACT ACR8 50-287	P D	8403010204 8403010205 8403010206 8403010211 8403010214	8403010178 8403010117 8403010117 8403010198 8403010117	83/12/14 84/01/25 84/01/25 83/12/14 84/01/25	50-329 FOIA FOIA 50-329 FOIA	A
8403010022 8403010023 8403010027 8403010029 8403010030	8307260036 8403010014 8403010019 8307260036 8403010014	83/07/15 84/01/03 64/02/22 83/07/15 84/01/03	ACRE 50-287 CONTRACT ACRE 50-287	P	8403010217 8403010222 8403010223 8403010227 8403010227	8403010198 8403010117 8403010198 8403010198 8403010221	83/12/14 84/01/25 83/12/14 83/12/14 84/02/27	50-329 FOIA 50-329 50-329 50-463	A A Q
8403010032 8403010033 8403010035 8403010037 8403010038	8403010016 8307260036 8403010014 8307260036 8403010024	84/01/04 83/07/15 84/01/03 83/07/15 84/01/18	50-334 ACRS 50-289 ACRS FOIA	B	8403010231 8403010233 8403010239 8403010245 8403010252	8403010179 8403010117 8403010117 8403010178 8403010117	83/12/14 84/01/25 84/01/25 83/12/14 84/01/25	50-329 50-312 FOIA 50-329 FOIA	A A
8403010041 8403010042 8403010043 8403010044 8403010045	8403010026 8307260036 8403010014 8403010035 8403010040	84/01/04 83/07/15 84/01/03 84/02/21 84/02/22	FOIA ACRE 50-289 CONTRACT CONTRACT		8403010253 8403010255 8403010257 8403010260 8403010261	8403010248 8403010248 8403010117 8403010248 8403010254	84/01/10 84/01/10 84/01/25 84/01/10 84/02/24	50-142 50-142 FOIA 50-142 50-219	G G G
E403010046 E403010049 E403010054 E403010057 E403010058	8403010024 8403010024 8403010024 8307260036 8403010024	84/01/18 84/01/18 84/01/18 83/07/13 84/01/18	FOIA FOIA FOIA ACRB FOIA		8403010265 8403010266 8403010268 8403010273 8403010274	8403010248 8403010248 8403010262 8403010178 8403010262	94/01/10 84/01/10 89/12/20 89/12/14 83/12/20	50-142 50-142 50-247 50-327 FOIA	Q Q P A
B403010060 B403010061 B403010063 B403010065 B403010067	8403010051 8403010016 8403010024 8307260036 8403010024	84/02/21 84/01/04 84/01/18 83/07/15 84/01/18	CONTRACT 50-334 FOIA ACRB FOIA	S	8403010275 8403010282 8403010283 8403010284 8403010285	8403010271 8403010198 8403010279 8403010117 8403010198	84/02/28 83/12/14 83/12/16 84/01/25 83/12/14	50-352 50-327 FOIA FOIA 50-327	Q A
8403010074 8403010076 8403010078 8403010087 8403010093	8403010024 8403010048 8403010070 8403010083 8403010087	84/01/18 84/01/03 84/02/10 84/02/24 84/02/21	FOIA FOIA CONTRACT 50-454 50-254	Q P	B4030102B7 B403010292 B403010302 B403010303 B403010313	8403010117 8403010117 8403010297 8403010294 8403010306	84/01/25 84/01/25 84/02/24 84/02/27 84/02/22	FDIA FDIA 50-369 50-388 50-259	P E P

ACCESSION NUMBER				ACCESS10				
PRINCIPAL ENGLOSURE DOCUMENT	198UED	SUBJECT	?Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISBUED	CATEGO	
8403010314 840301030 8403010315 840301031 8403010322 840301031 8403010325 840301031 8403010327 840301032	7 B4/02/16 0 B4/02/16 0 B4/02/16 9 B4/02/24	50-352 50-277 50-277 50-424 50-293	0 0 0 X	8403020101 8403020105 8403020107 8403020110 8403020111	8403020011 8403020099 8403020011 8403020011 8403020108	84/02/09 84/02/29 84/02/09 84/02/09 84/02/27	FOIA 50-352 FOIA FOIA 50-331	0
8403010334 840301032 8403010348 840301033 8403010342 840301034 8403010342 840301034 8403010372 840301034	9 84/02/24 6 84/02/28 0 84/02/16 0 84/02/16	REVIEW 6 50-454 70-1100 70-1100 50-255		8403020113 8403020114 8403020115 8403020116 8403020117	8403020011 8403020011 8403020112 8403020011 8402230176	84/02/09 84/02/09 84/02/14 84/02/09 84/02/16	AIOT AIOT AIOT AIOT EE1-OE	c F
8403010373 840301032 8403010377 840301037 8403010378 840301037 8403010382 840301038 8403010390 840301038	4 84/02/22 4 84/02/22 1 84/02/16	50-255 50-312 50-312 50-322 50-322	P P Q G	8403020119 8403020120 8403020124 8403020127 8403020132	8403020011 8403020011 8403020011 8403020011 8403020011	84/02/09 84/02/09 84/02/09 84/02/09 84/02/09	FOIA FOIA FOIA FOIA	
8403010404 840301037 8403010412 840301041 8403010414 840301041 8403010422 840301041 8403010428 840301041	0 83/12/15 0 83/12/15 7 84/02/27	50-213 FOIA FOIA 50-364 50-364	G 5 5	8403020135 8403020136 8403020137 8403020142 8403020144	8403020011 8403020129 8403020011 8403020011 8403020011	84/02/09 84/02/28 84/02/09 84/02/09 84/02/09	FOIA 50-352 FOIA FOIA FOIA	т
8403010430 840301042 8403010437 840301043 8403010446 840301020 8403010456 840301045 8403010462 840301046	5 84/02/24 7 94/02/27 4 84/02/16	50-423 CONTRACT 50-322 XPORTLIC CONTRACT	5	8403020146 8403020147 8403020150 8403020152 8403020152	8403020140 8403020011 8403020011 8403020148 8403020011	84/02/28 84/02/09 84/02/09 84/02/21 84/02/09	50-295 FDIA FOIA 50-445 FDIA	Q A
8403010467 840301046 8403010468 840301046 8403010473 840301047 8403010483 840301047 8403010500 840301047	94/02/10 94/02/10 94/02/16	XFORTLIC XFORTLIC XFORTLIC 40-6920 COMMISSI		8403020146 8403020170 8403020172 8403020175 8403020176	8403020011 8403020011 8403020011 8403020171 8403020011	84/02/09 84/02/09 84/02/09 84/02/21 84/02/09	FOIA FOIA FOIA 50-286 FOIA	F
8403010513 840301050 8403010517 840301051 8403010522 840301052 8403010534 840301052 8403010546 840301052	94/02/10 9 84/02/15 9 84/02/24	40-8027 XPORTLIC 50-275 CONTRACT XPORTLIC	н	8403020177 8403020179 8403020180 8403020183 8403020186	8403020011 8403020011 8403020011 8403020011	84/02/09 84/02/09 84/02/09 84/02/09 84/02/09	FOIA FOIA FOIA FOIA	
8403010550 840301052 8403020016 840302001 8403020018 840302001 8403020021 840302001 8403020023 840302001	84/02/09 B4/02/09 B3/12/16	XPORTLIC FOIA FOIA FOIA FOIA		8403020187 8403020180 8403020191 8403020192 8403020193	8403020011 8403020182 8403020011 8403020182 8403020011	84/02/09 84/02/27 84/02/09 84/02/27 84/02/09	FOIA 50-400 FOIA 50-400 FOIA	0
8403020024 840302001 8403020025 840302001 8403020027 840302001 8403020028 840302001 8403020029 840302001	93/12/16 1 84/02/07 9 93/12/16	XPORTLIC FOIA FOIA FOIA 50-247	P	8403020174 8403020177 8403020200 8403020201 8403020208	8403020011 8403020011 8403020011 8403020011	84/02/09 84/02/09 84/02/09 84/02/09	FDIA FOIA FOIA FOIA	
8403020032 840302001 8403020034 840302001 8403020035 840302001 8403020038 840302001 8403020041 840302001	84/02/07 83/12/16 84/02/07	50-267 FOIA FOIA FOIA 50-267	P P	8403020210 8403020212 8403020215 8403020219 8403020220	8403020011 8403020011 8403020011 8403020011 8403020214	84/02/09 84/02/09 84/02/09 84/02/09 84/02/17	FOIA FOIA FOIA FOIA 50-388	a
8403020043 840302003 8403020045 840302001 8403020046 840302001 8403020048 840302001 8403020049 840302001	83/12/16 83/12/16 83/12/16	50-10 50-267 50-267 50-267 FDIA	P P P	8403020221 8403020224 8403020227 8403020232 8403020237	8403020207 8403020011 8403020011 8403020011 8403020011	84/02/21 84/02/09 84/02/09 84/02/09 84/02/09	50-973 FOIA FOIA FOIA FOIA	F
B403020051 B40302001 B403020052 B40302001 B403020057 B40302005 B403020059 B40302005 B403020059 B40302005	84/02/09 84/02/24	50-537 FOIA FOIA 50-280 50-280	A P R	8403020240 8403020241 8403020243 8403020246 8403020251	8403020011 8403020204 8403020011 8403020011 8403020011	84/02/09 84/01/25 84/02/09 84/02/09 84/02/09	FOIA 50-250 FOIA FOIA	a
8403020060 840302001 8403020061 840302005 8403020060 840302005 8403020066 840302001	84/02/24 84/02/14 84/02/14	FDIA 50-280 50-280 50-280 FOIA	អ ម ម	8403020255 8403020257 8403020264 8403020266 8403020267	8403020011 8403020011 8403020011 8403020257 8403020011	84/02/09 84/02/09 84/02/09 84/02/29 84/02/09	FDIA FDIA FOIA 50~352 FDIA	A
8403020070 840302001 8403020071 840302005 8403020073 840302005 8403020074 840302001 8403020076 840302005	84/02/14 84/02/27 84/02/09	FOIA 50-280 CONTRACT FOIA 50-280	R R	8403020270 8403020272 8403020273 8403020288 8403020290	8403020257 8403020262 8403020257 8403020285 8403020287	84/02/27 84/02/07 84/02/27 84/02/27 84/02/21	50-352 50-293 50-352 50-250 50-322	C G K G E
8403020077 840302006 8403020080 840302001 8403020082 840302001 8403020085 840302001 8403020087 840302001	84/02/09 84/02/09 84/02/14	CONTRACT FOIA FOIA 50-280 FOIA	R	8403020301 8403020305 8403020308 8403020309 8403020321	8403020262 8403020298 8403020282 8403020306 8403020317	84/02/17 84/02/16 84/02/17 84/02/17 84/02/29	50-443 50-54 50-443 50-277 50-369	0 0 0
8403020070 8403020051 8403020071 8403020011 8403020074 8403020011 8403020075 8403020071	84/02/09 84/02/15 84/02/09	FOIA FOIA	Ri P	8403020323 8403020326 8403020328 8403020335 8403020339	8403020318 8403020322 8403020322 8403020333 8403020332	84/02/24 84/02/27 84/02/27 84/02/27 84/02/16	50-320 50-271 50-271 50-382 WASTE MG	P S S A

ACCESSION					ACCESSION	NUMBER			
ENCLOSUME	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEODRY	
8403020342 8403020345 8403020346 8403020347 8403020357	8403020341 8403020343 8403020343 8403020343 8403020353	84/02/17 84/02/29 84/02/29 84/02/29 84/02/21	50-247 50-317 50-317 50-317 50-286		8403050333 8403050335 8403050340 8403050341 8403050345	8403050320 8403050330 8403050338 8403050337 8403050337	84/02/28 84/02/27 84/02/24 84/02/15 84/02/15		P P
8403020399 8403020410 8403020412 8403020423	8403020315 8403020405 8403020406 8403020405 8403020420	84/02/17 84/02/15 84/02/21 84/02/15 84/02/22	50-293 F01A 50-416 F01A 71-9108		8403050364 8403050366 8403050371 8403050373 8403050374	8403050358 8403050358 8403050370 8403050368 8403050368	84/02/28 84/02/28 84/02/29 84/02/28 84/02/28	XPORTLIC XPORYLIC 50-410 XPORTLIC XPORTLIC	A
8403020441 8403020453 8403050006 8403050009 8403050010	8403020435 8403020451 8403050005 8403050007 8403050007	84/02/22 84/02/10 84/02/22 84/02/28 84/02/28	50-440 XPORTLIC 50-155 50-312 50-312		8403040009 8403040012 8403040019 8403040023 8403040029	8403060005 8403060005 8403060008 8403060018 8403060025	84/02/28 84/02/38 84/02/36 84/01/31 84/02/09	50-241 50-204 CONMISSIO	P G IN G
8403050013 8403050015 8403050018 8403050017 8403050023	8403050012 8403050014 8403050016 8403050016 8403050020	84/03/01 84/02/24 84/03/01 84/03/01 83/12/07	50-483 50-483		8403040030 8403040037 8403040044 8403040056 8403040061	8403060018 8403060018 8403060018 8403060053 8403060018	84/01/31 84/01/31 84/01/31 84/02/10 84/01/31	COMMISSIO COMMISSIO COMMISSIO 50-324 COMMISSIO	NC NC P
6403050024 6403050025 8403050027 8403050029	8403050020 8403050020 8403050020 8403050020 8403050020	83/12/07 83/12/07 83/12/07 83/12/07 83/12/07	50-284 50-286		8403060065 8403060071 8403060074 8403060080 8403060095	8403060018 8403060018 8403060018 8403060077 8403060071	84/01/31 84/01/31 84/01/31 84/02/24 84/01/23	COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO	MC
8403050031 8403050032 8403050034 8403050035 8403050037	8403050020 8403020231 8403050020 8403050020 8403050020	83/12/07 84/02/16 83/12/07 83/12/07 83/12/07	50-284		8403040096 8403040098 8403040101 8403040107 8403060114	8403040092 8403040092 8403040092 8403040105 8403040112	84/03/01 84/03/01 84/03/01 84/03/01 84/03/01		g F
B40305003B B403050042 B403050044 B403050049 B403050074	8403050020 8403050020 8403050043 8403050047 8403050072	83/12/07 83/12/07 64/02/24 84/02/29 84/02/29	FOIA 50-10 50-346		8403050117 8403050121 8403050124 8403050125 8403050127	8403060113 8403060113 8403060118 8403060115 8403060113	84/02/07 84/02/07 84/02/29 84/02/29 84/02/07	50-254 40-2061 50-244	R R P R
8403050081 8403050095 8403050100 8403050103 8403050110	8403050078 8403050091 8403050098 8403050098 8403050107	84/03/01 84/02/24 84/02/27 84/02/27 84/03/01	50-278 50-318 50-318		8403050130 8403050142 8403050143 8403050146 8403050147	8403060128 8403060138 8403060131 8403060138 8403060131	84/02/27 84/02/03 84/02/29 84/02/03 84/02/29		P G G G
E403050113 E403050114 E403050118 E403050122 E403050131	8403050111 8403050107 8403050107 8403050114 8403050128	84/02/29 84/03/01 84/03/01 84/03/01	50-346 50-346 50-387	! : :	8403060192 8403060154 8403060161 8403060162 8403060163	8403060148 8403060157 8403060151 8403060151	84/01/17 84/01/17 84/03/01 84/02/21 84/02/28	F01A F01A GA799 50-266 50-259	a F
8403050102 8403050134 8403050143 8403050144 8403050150	8403050127 8403050127 8403050140 8403050136 8403050136	84/02/29 84/02/14 84/03/01 84/02/24 84/02/24	50-458		8403060172 8403060173 8403060176 8403060177 8403060184	8403050165 8403050170 8403050151 8403050170 8403050180	84/02/03 84/03/01 84/02/21 84/03/01 84/02/17	50-113 50-341 50-266 50-341 50-445	0 0 0 0
8403050154 8403050163 8403050171 8403050172 8403050174	8403050136 8403050161 8403050168 8403050148 8403050168	E4/02/24 E4/02/29 E4/02/27 E4/01/31 E4/02/27	50-373	; ; ;	8403040189 8403040172 8403040197 8403040200 8403040202	84030A0147 84030A0188 84030A0191 84030A0195 84030A0188	84/02/28 64/03/01 84/03/01 84/03/01 84/03/01	50-259 50-155 50-314 50-315 50-155	F 0 P P
B403050178 B403050180 B403050182 B403050184 B403050204	8403050177 8403050179 8403050179 8403050179 8403050200	84/03/01 84/02/14 84/02/14 84/02/14 84/02/24	50-413 50-482 50-482 50-482 COMMISSIO		8403060203 8403060205 8403060206 8403060210 8403060214	8403050198 8403050199 8403050147 8403050201 8403050207	84/02/27 84/02/27 84/02/28 84/03/01 84/02/17	50-313 50-313 50-259 40-8830 50-275	Q P F
8403050232 8403050235 8403050237 8403050241 8403050243	8403050223 8403050223 8403050231 8403050223 8403050238	84/02/07 84/02/07 84/02/13 84/02/07 84/02/21	FOIA 50-305 CONTRACT 50-271 50-282	3	84030,60223 84030,60226 84030,60228 84030,60229 84030,60236	8403060207 8403060212 8403060219 8403060222 8403060222	B4/02/17 B4/03/01 B4/02/16 B4/02/17 B4/02/17	50-323 50-322 GA979 50-289 50-289	Q T P P
8403030245 8403030247 8403050250 8403050251 8403050253	8403050223 8403050238 8403050223 8403050248 8403050248	84/02/07 84/02/21 84/02/07 84/01/30 84/01/30	FDIA 50-282 50-312 50-382 50-382	- - -	6403060246 640306025 64306020 64306026 74206086	8403060212 8403060212 8403060254 8403060254 8403060245	84/03/01 84/03/01 84/03/02 84/03/02 84/02/28	50-322 50-322 50-322 50-322 50-454	T T T Q
8403050256 8403050246 8403050270 8403050274 8403050277	8403050223 8403050223 8403050223 8403050223 8403050223	84/02/07 64/02/07 84/02/07 84/02/07 84/02/07	50-255 FOIA FOIA FOIA FOIA	3	8403060270 8403060274 8403060278 8403060277 8403060280	8403060254 8403060264 8403060254 8403060273 8403060275	84/03/02 84/03/01 84/03/02 84/02/28 84/02/29	50-322 50-298 50-322 50-254 50-440	T F T P
8403050318 8403050317 8403050322 8403050323 8403050327	8403050315 8403050315 8403050315 8403050315 8403050320	84/02/08 84/02/08 84/02/08 84/02/08 84/02/28	WABTE MOT WABTE MOT WASTE MOT XPORTLIC		8403060287 8403060275 8403060301 8403060302 8403060303	8403060254 8403060254 8403060254 8403060300 8402070012	84/03/02 84/03/02 84/03/02 84/02/28 84/02/29	50-322 50-322 50-322 50-324 50-275	T T P Q

ACCES910	N NUMBER				ACCEBBI	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	EUBJECT CATEGOR		PAGE SCALES	PRINCIPAL	DATE	SUBJECT	
8403060304	8403060296	84/02/29	50-324	P	ENCLOSURE	DOCUMENT	ISENED	CATEGOR	
8403060307	8403060254	B4/03/02	50-322	т	8403070106 8403070108	8403070101 8403070101	84/02/16 84/02/16	FOIA FOIA	
8403060310 8403060314	8403060254 8403060254	84/03/02 84/03/02	50-322 50-322	T	8403070112 8403070123	8403070107 8403070120	84/02/26 84/03/02	70-824 50-461	Q
8403040315	B403060305	84/03/01	50~315	a	8403070129	8403070125	84/02/24	50-395	a
840304031B 8403060317	8403060254 8403060254	84/03/02 84/03/02	50-322 50-322	T	6403070131 8403070133	8403070125 8403070125	84/02/24 84/02/24	50-375 50-375	Q Q
8403040322 8403040324	8403060254 8403060325	84/03/02 84/02/17	50-322 50-213	T	B403070136	8403070125	84/02/24	50-395	Q
840304032B	8403060327	84/03/03	50-219	P	8403070139 8403070141	8403070135 8403070137	84/03/03 84/02/24	50-250 50-277	P
8403040331	B403060329	84/03/01	70-734		8403070143	8403070135	E4/03/03	50-250	0
8403060344 8403060347	8403050341 8403050345	84/02/07 84/02/28	50-344 50-454	ů E	8403070144 8403070145	8403070137 8403070140	84/02/24 84/02/13	50-277 50-335	D.
8403040352 8403040355	840306034B 840306034B	84/03/02 84/03/02	QA999 QA999		8403070149 8403070150	8403070146 8403070147	84/02/08 84/03/02	70-27	
04C040E0AB	8403040357	84/03/05	50-537					50-322	T
8403060361	8403060348	84/03/02	GA999	A	8403070153 8403070154	8403070146 8403070147	84/02/08 84/03/02	70-27 50-322	т
8403060362 8403060365	8403060359 8403060348	84/02/24 84/03/02	50-302 0A999	P	8403070155 9403070156	8403070151 8403070151	84/02/27 84/02/27	50-327 50-327	Q.
8403060366	6403060359	94/02/24	50-302	P	8403070158	8403070147	84/03/02	50-322	Ť
840306036B	8403060364 8403060348	84/02/24	50-302 0A999	P	8403070157	8403070151	84/02/27	50-327	Q.
8403060369 8403060372	8403060348	84/03/02 84/03/02	9A999		8403070160 8403070161	8403070147 8403070152	84/03/02 84/02/08	50~322 CONTRACT	T
8403060373 8403060374	8403060371 8403060348	84/02/21 84/03/02	50-445 0A999	G	84030701 <i>62</i> 84030701 <i>6</i> 3	8403070157 8403070151	84/02/28	50-324	P
B403060376	840306034B	B4/03/02	GA777			_	84/02/27	50-327	G
8403060379	8403060348	84/03/02	QA999	_	8403070145 8403070147	8403070147 8403070152	84/03/02 84/02/08	50-322 CONTRACT	Т
8403060393 8403060398	8403060392 8403060385	84/03/01 84/03/01	50-276 50-327	Q Q	8403070171 8403070172	8403070147 8403070152	84/03/02 84/02/08	50-322 TOARTAGO	T
8403060406	6403060401	84/02/17	50-312	a	8403070173	8403070168	84/02/22	50-414	a
8403060407 8403060410	8403060385	84/03/01	50-329	Q.	8403070176	8403070168	84/02/22	50-415	a
8403060414	8403060405 8403060402	84/03/01 84/02/29	50-30 50-302	R	840307017B 8403070180	8403070147 8403070168	84/03/02 84/02/22	50-322 50-416	T G
8403050415 8403050420	8493060395 8493060385	84/03/01 84/03/01	50-327 50-327	G G	8403070181 8403070182	8403070177 8403070177	B4/02/29 B4/02/29	50-445 50-445	۵
8403060421	8403060416	84/03/01	70-1257	-					G
B403060423	8403060385	84/03/01	50-329	g .	8403070183 8403070184	8403070147 8403070179	84/03/02 84/02/22	50-322 50-40 <i>0</i>	T Q
8403050427 8403050428	8403060424 8403060385	84/03/02 84/03/01	50-361 50-329	P Qr	8403070184 8403070187	8403070148 8403070148	84/02/22 84/02/22	50-416 50-416	G G
8403060440	8403060436	84/02/21	50-321	P	8403070190	8403070147	84/03/02	50-322	ř
8403050442 8403050444	8403060385 8403060385	84/03/01 84/03/01	50~329 50-329	Q: Q	B403070193	8403070179	84/02/22	50-400	a
E403060445	8403060385	B4/03/01	50-329	G	8403070195 8403070197	8403070147 8403070179	84/03/02 84/02/22	50-322 50-400	T a
8403060447 8403060459	8403060447 8403060454	84/02/21 84/02/16	50-344 50-245	P	8403070178 8403070199	8403070147 8403070179	84/03/02 84/02/22	50-322 50-400	T G
B403040466	8403060462	84/02/23	50-338	F	8403070201	B403070147	84/03/02	20-355	- T
8403060495 8403060499	8403060471 8403060474	84/02/27 84/02/29	CONTRACT REGGD		8403070202	8403070185	84/02/28	50-413	Α
8403040502	8403040500	84/02/27	CONTRACT		8403070204 8403070204	8403070147 8403070168	84/03/02 84/02/22	50-322 50-414	Q.
8403060510	8403060508	B4/02/21	50-261	F	8403070207	8403070147	84/03/02	20-355	т
8403040521 8403060527	8403060519 8403060077	84/02/24 84/02/24	Waste Moi 50-335	P P	9403070208 8403070209	8403070168 8403070168	84/02/22 84/02/22	50-416 50-416	a a
8403040536 8403040554	8402090039 8402090039	84/03/12 84/03/12	50-322	8	8403070210	8403070205	84/02/24	50-413	Q
8403060573	8403060569	84/02/21	XPORTLIC	5	8493070211 8493070214	8403070147 8403070147	84/03/02 84/03/02	50-322 50-322	T T
8403070007	B403070005	84/02/04	CONTRACT		8403070216	8403070168	64/02/22	50-416	a
8403070013 8403070017	8403070007 8403070012	64/02/10 64/02/13	50-395 50-413	a	8403070217 8403070219	8403070147 8403070185	84/03/02 84/02/28		Ţ
8403070017 8403070022	8403070015 8403070020	84/02/28 84/02/29	70-1201 50-443	e e	8403070220	8403070147	84/03/02	50-322	Ť
8403070024	840307001B	B4/02/10	50-424	0	8403070221	8403070215	84/01/23		A
8403070030	8403070027	84/02/27	40~2061	u	8403070222 8403070224	8403070147 8403070218	84/03/02 84/02/23	50-322 50-438	T G
8403070032 8403070037	8403070029 8403070033	84/02/27 84/02/29	CONTRACT 50-413	œ	640307 <u>0</u> 227 6403070231	8403070147 8403070147	84/03/02 84/03/02	50-392	τ̈́
B403070046	8403070039	84/02/27	CONTRACT		8403070234	8403070229	B4/02/23	FOIA	•
8403070058 8403070057	8403070055 8403070055	84/02/28 84/02/28	50~400 50~400	G G	8403070238	8403070234	84/03/02		Q.
8403070060	8403070053	84/02/08	50-289	U	8403070242 8403070244	8403070240 8403070243	84/02/17 84/02/22		G R
8403070067 8403070072	8403070053 8403070067	84/02/08 84/01/11		U Or	B403070246 B40307024B	8403070239 8403070247	83/11/25 84/02/09	50-280	9
8403070073	8409070053	84/02/08	50~289	U	8403070252	8403070251	84/02/29		P
8403070076 8403070079	8403070053 8403070075	84/02/08	50-289	Ď	8403070253	8403070250	84/02/10	50-290	0
8403070083	6403070075	84/02/29 84/02/29	50-275	P	84 030 70257 84 030 70257	8403070255 8403070258	84/02/29 84/02/17	50-244 70-1100	P
84030700RB	8403070085	B4/02/07		a	8403070261	8403070240	84/02/29		R
6403070095 6403070096	8403070094 8403070094	84/02/23 84/02/23		Q G	8403070267 8403070275	9403070264 8403070273	84/02/27 84/03/01	70-474 50-423	c
8403070100 8403070102	8403070094 8403070094	84/02/23	50-400	ē a	8403070281	8403070276	84/02/28	50~352	C G
8403070105	8403070094	84/02/23 84/02/23		G G	8403070287 8403070288	8403070282 8403070284	84/02/21 84/02/29		QI P

ACCESSIO						ON NUMBER			
ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	łΥ	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEOD!	RY
6403070292 8403070302 8403070306 8403070308 8403070310	8403070284 8403070299 8403070301 8403070303 8403070307	84/02/27 84/02/16 84/02/21 84/02/28 84/02/06	50-275 50-423 50-387 50-412 50-324	P A G Q	8403080078 8403080079 8403080082 8403080084 8403080084	8403080027 8403080027 8403080027 8403080027 8403080081	83/12/30 83/12/30 83/12/30 83/12/30 84/03/02	FOIA FOIA FOIA FOIA 50-348	р
8403070318 8403070318 8403070319 8403070322 8403070323	8403070312 8403070315 8403070314 8403070320 8403070321	84/02/23 84/02/27 84/02/22 84/02/22 84/02/23	50-333 50-325 50-352 50-277 50-305	0 0 0	840308007 840308007 840308007 840308007 8403080078	8403080027 8403080027 8403080027 8403080027 8403080068	83/12/30 83/12/30 83/12/30 83/12/30 84/01/17	FOIA FOIA FOIA FOIA	
8403070328 8403070331 8403070334 8403070335 8403070336	8403070327 8403070327 8403070327 8403070327 8403070333	84/02/23 84/02/22 84/02/22 84/02/22 84/02/28	70-27 50-413 50-413 50-413 50-423	a a a	8403080079 840308010 8403080102 8403080103 8403080103	8403080027 8403080014 8403080027 8403080027	83/12/30 84/01/11 83/12/30 84/01/23 83/12/30	FOIA FOIA FOIA 50-275 FOIA	E
6403070338 6403070340 6403070341 6403070343 6403070344	8403070327 8403070229 8403070330 8403070229 8403070342	84/02/22 84/02/23 84/02/28 84/02/23 84/02/29	50-413 50-327 50-273 50-327 50-334	9 9 9	8403080108 8403080109 8403080111 8403080112 8403080113	8403080016 8403080027 8403080027 8403080027 8403080016	84/01/11 83/12/30 83/12/30 83/12/30 84/01/11	FDIA FOIA FOIA FOIA	
8403070345 8403070346 8403070349 8403070351 8403070362	8403070229 8403070339 8403070229 8403070229 8403070360	84/02/23 84/02/10 84/02/23 84/02/23 84/02/27	50-329 CONTRACT 50-329 50-329 50-5	9 9	8403080117 8403080117 8403080120 8403080121 8403080122	8403080027 8403080068 8403080016 8403080027	83/12/30 84/01/17 84/01/11 83/12/30 83/12/30	FOIA FOIA FOIA FOIA	
8403070366 8403070369 8403070373 8403070381 8403070382	8403070269 8403070364 8403070371 8403070377 8403070379	84/02/15 83/06/02 84/02/27 84/02/27 84/02/27	50-334 50-269 CONTRACT XPORTLIC 50-348		8403080123 8403080124 8403080125 8403080127 8403080128	8403080027 8403080027 8403080114 8403080018 8403080068	83/12/30 83/12/30 84/02/23 84/01/11 84/01/17	FOIA FOIA 50-373 FOIA FOIA	œ
B403070383 B403070384 B403070389 B403070390 B403070391	8403070380 8403070379 8403070387 8403190450 8403070387	84/03/01 84/02/29 84/02/27 84/03/05 84/02/27	27-39 50-348 50-334 50-315 50-334	P P P	8403080127 8403080132 8403080134 8403080134 8403080137	8403080027 8403080027 8403080027 8403080027 8403080027	83/12/30 83/12/30 83/12/30 83/12/30	FOIA FOIA FOIA FOIA	
8403070395 8403070398 8403070402 8403070409 8403070414	8403190450 8403070394 8403070394 8402090039 8403070411	84/03/05 64/02/29 84/02/29 84/03/12 84/02/29	50-315 50-247 50-247 50-322 CONTRACT	9 P 8	8403080138 8403080137 8403080144 8403080144 8403080144	8403080048 8403080027 8403080027 8403080048 8403080027	84/01/17 83/12/30 83/12/30 84/01/17 83/12/30	FOIA FOIA FOIA FOIA	
8403070423 8403070425 8403070426 8403080006 8403080008	8402070037 8403070424 8403070424 8403080005 8403080005	84/03/12 84/02/28 84/02/28 84/02/24 84/02/24	50-322 XPORTLIC XPORTLIC FOIA FOIA	8	8403080149 8403080150 8403080151 8403080152 8403080154	8403080125 8403080027 8403080027 8403080145 8403080125	84/03/01 83/12/30 83/12/30 84/02/13 84/03/01	FOIA FOIA FOIA 50-528 FOIA	a
8403080009 8403080010 8403080012 8403080017 8403080019	8403080007 8403080005 8403080005 8403080005 8403080005	84/03/02 84/02/24 84/02/24 84/02/24 84/02/24	50-29 FOIA FOIA FOIA	P	8403080155 8403080155 8403080157 8403080159 8403080160	8403080068 8403080027 8403080027 8403080027 8403080027	84/01/17 83/12/30 83/12/30 83/12/30 83/12/30	FOIA FOIA FOIA FOIA	
8403080025 9403080029 9403080032 9403080033 9403080036	8403080005 8403080005 8403080016 8403080027	84/02/24 84/02/24 83/12/30 84/01/11 83/12/30	FOIA FOIA FOIA FOIA		8403080162 8403080165 8403080165 8403080166 8403080167	8403080016 8403080027 8403080068 8403080027 8403080027	84/01/11 83/12/30 84/01/17 83/12/30 83/12/30	FOIA FOIA FOIA FOIA	
8403080038 8403080040 8403080043 8403080044 8403080045	8403080016 8403080027 8403080016 8403080027	84/01/11 83/12/30 83/12/30 84/01/11 83/12/30	FOIA FOIA FOIA FOIA		84030801AB 8403080170 8403080172 8403080173 8403080173	8403080027 8403080014 8403080027 8403080048 8403080016	83/12/30 84/01/11 83/12/30 84/01/17 84/01/11	FOIA FOIA FOIA FOIA	
8403080046 8403080049 8403080050 8403080051	8403080027 8403080016 8403080027 8403080027 8403080027	83/12/30 84/01/11 83/12/30 83/12/30 83/12/30	FOIA FOIA FOIA FOIA		8403080177 8403080180 8403080181 8403080182 8403080182	8403060027 8403060016 8403060066 8403080027 8403080027	83/12/30 84/01/11 84/01/17 83/12/30 83/12/30	FOIA FOIA FOIA FOIA	
8403080054 8403080055 8403080056 8403080057 8403080058	8403080027 8403080027 8403080027 8403080016 8403080027	83/12/30 83/12/30 83/12/30 84/01/11 83/12/30	FOIA FOIA FOIA FOIA		8403080194 8403080189 8403080189 8403080190 8403080191	8403080016 8403080176 8403080068 8403080027 8403080016	84/01/11 64/02/23 84/01/17 83/12/30 84/01/11	FOIA 50-461 FOIA FOIA FOIA	a
B403080059 B403080060 B403080064 B403080066 B403080069	8403080027 8403080027 8403080027 8403080027 8403080027	83/12/30 83/12/30 83/12/30 83/12/30 83/12/30	FOIA FOIA FOIA FOIA		8403080193 8403080194 8403080195 8403080198 8403080198	8402090022 8403080015 8403080158 8403080016 8402090022	84/03/05 84/01/11 84/03/02 84/01/11 84/03/05	50-275 FOIA 50-348 FOIA 50-275	G P G
E403080070 E403080072 E403080074 E403080075 E403080076	8403080027 8403080027 8403080027 8403080061 8403080027	83/12/30 83/12/30 83/12/30 84/02/21 83/12/30	FDIA FOIA FOIA 50-312 FOIA	Q.	8403080202 8403080204 8403080207 8403080210 8403080211	8403080016 8403080016 8403080016 8403080205 8403080016	84/01/11 84/01/11 84/01/11 84/03/02 84/01/11	FOIA FOIA 50-316 FOIA	P

ACCESS)ON	NUMBER				ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE (SSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	Y
8403080212 8403080214 8403080215 8403080216 8403080217	8403080203 8403080208 8403080016 8403080205 8403080016	84/01/24 84/03/05 84/01/11 84/03/02 84/01/11	50-413 50-315 FDIA 50-316 FDIA	9 9 P	B403090116 B403090135 B403090141 B4030901B3 B403090191	8403070100 8403070133 8403070138 8403070178 8403070185	84/02/29 84/02/27 84/02/27 84/03/02 84/02/15	50-298 CONTRACT CONTRACT PR 50-237	P
8403080218 8403080220 8403080223 8403080225 8403080242	8403080207 8403080205 8403080205 8403080207 8403080238	84/01/23 84/03/02 84/03/02 84/01/23 84/03/05	FDIA 50-316 50-316 FOIA 50-263	P P F	8403090194 8403090194 8403090200 8403090202 8403090202	8403090185 8403090187 8403090198 8403090198 8403090198	84/02/15 84/02/06 84/01/17 84/01/17 84/01/17	50-237 50-321 PT21 PT21 PT21	P
8403080244 8403080253 8403080254 8403080261 8403080263	8403080238 8403080179 8403080251 8403080251 8403080254	84/03/05 84/02/13 84/02/22 84/02/22 84/02/27	50-263 50-508 50-483 50-483 50-528	F A G G	8403070221 8403070227 8403070230 8403070233 8403070238	8403090218 8403090177 8403090177 8403090177 8403090177	84/03/06 84/03/07 84/03/07 84/03/07 84/03/07	50-155 50-361 50-361 50-361 50-361	F P P P
8403080269 8403080269 8403080270 8403080273 840308027 <i>6</i>	8403080245 8403080264 8403080265 8403080265 8403080274	84/03/01 84/03/01 84/02/22 84/03/01 84/02/23	50-298 50-280 50-397 50-298 50-312	F G P Q	8403070237 8403070257 8403070260 8403070277 8403070315	8403070232 8403070255 8403070252 8403070262 8403070314	84/03/06 84/03/01 84/03/02 84/02/29 83/09/30	50-387 50-348 50-324 50-331 TOPREP	8 P P
8403080277 8403080281 8403080283 8403080302 8403080304	8403080274 8402090030 8403080278 8403080299 8403080265	84/02/23 84/03/02 84/02/29 84/02/24 84/03/01	50-312 50-275 50-413 50-315 50-278	C E M G F	8403090316 8403090318 8403090317 8403090321 8403090322	8403090314 8403090314 8403090314 8403090314 8403090314	83/09/30 83/09/30 83/09/30 83/09/30	TOPREP TOPREP TOPREP TOPREP TOPREP	
8403080314 8403080316 8403080327 8403080332 8403080333	8403080312 8402070006 6403080325 8403080325 8403080325	84/03/02 84/02/23 64/01/20 64/01/20 84/01/20	71-6601 50-247 50-445 50-445 50-445	F (1) (2)	8403090323 8403090324 8403090325 8403090327 8403090328	8403070314 8403070314 8403070314 8403070314 8403070314	83/09/30 83/09/30 83/09/30 83/09/30	TOPREP TOPREP TOPREP TOPREP	
8403080335 8403080341 8403080352 8403080360 8403080364	8403080325 8403080339 8403080347 8403080357 8403080357	84/01/20 84/01/20 84/03/02 84/01/17 84/01/17	50-445 50-280 50-336 FOIA FOIA	G G P	8403070327 8403070330 8403070332 8403120005 8403120010	8403090314 8403090314 940309031 8000218048 9000180048	83/09/30 83/09/30 83/09/30 84/03/05 84/03/04	TOPREP TOPREP TOPREP 50-271 50-275	P
8403080346 8403080377 8403080377 8403080381 8403080393	8403080357 8403080372 8403080375 8403080372 8403080375	64/01/17 64/01/31 64/02/17 64/01/31 64/02/17	F01A 50-424 F01A 50-424 F01A	Q Q	8403120012 8403120015 8403120017 8403120018 8403120022	8403120006 8403120006 8403120006 8403120006 8403120006	84/03/06 84/03/06 84/03/06 84/03/06 84/03/06	50-275 50-275 50-275 50-275 50-275	00000
8403080384 8403080375 8403080377 8403080400 6403080406	8403080372 8403080394 8403080397 8403080390 8403080390	84/01/31 84/02/29 84/02/29 84/02/13 84/02/13	50-424 71-6406 71-9001 50-528 50-528	Q C D	8403120023 8403120027 8403120030 8403120050 8403120047	8403120004 8403120004 8403120024 8403120044 8403120065	B4/03/06 84/03/06 84/03/07 84/03/07 84/02/22	50-275 50-275 50-388 50-220 50-458	G G A G
8403080407 8403080407 8403080411 8403080412 8403080414	8403080403 8403080370 8403080405 8403080410 8403080413	84/02/29 84/02/13 84/03/02 84/03/01 84/02/29	50~289 50~528 50~275 50~320 50~275	Q A F P	8403120072 8403120073 8403120077 8403120086 8403120102	8403120065 8403120070 8403120070 8403120081 8403120101	84/02/22 84/02/24 84/02/24 84/03/04 84/03/02	50-458 50-237 50-237 50-247 50-320	0 0 0 P 0
6403080415 6403080417 6403080418 6403080420 6403080421	8403080413 8403080405 8403080416 8403080405 8403080405	84/02/29 84/03/02 84/03/01 84/03/02 84/03/02	50-275 50-275 71-9080 50-275 50-275	۶ ۴ ۶	8403120114 8403120124 8403120125 8403120126 8403120133	8403120108 8403120116 8403120120 8403120122 8403120120	84/03/05 84/02/24 84/02/23 84/03/06 84/02/23	0A999 50~315 50~331 50~440 50~331	0 0 0
8403080422 8403080425 8403080426 8403080431 8403090003	8403080405 8403080393 8403080405 8403080405 8402220291	84/03/02 84/01/27 84/03/02 84/03/02 84/01/31	50-275 50-289 50-275 50-275 50-289	P P E U	8403120137 8403120138 8403120145 8403120156 8403120158	8403120134 8403120135 8403120141 8403120153 8403120153	84/02/23 84/02/28 84/02/23 83/10/28 83/10/28	50-237 50-245 50-263 50-413 50-413	0 R 0 E E
8403070004 8403070005 8403070007 8403070008 8403070007	8402220271 8402220271 8402220271 8402220271	84/01/31 84/01/31 84/01/31 84/01/31 84/01/31	50-289 50-289 50-289 50-289 50-289	0000	8403120141 8403120145 8403120167 8403120172 8403120185	8403120153 8403120164 8403120164 8403120170 8403120184	83/10/28 84/03/08 84/03/08 84/03/05 84/03/06	50-413 50-382 50-382 50-334 50-341	E F F O O
8403090010 8403090011 8403090013 8403090014 8403090019	8402220271 8402220271 8402220271 8403070012 8403070017	84/01/31 84/01/31 84/01/31 84/02/29 84/02/28	50-287 50-287 50-287 50-528 FOIA	U U E	8403120172 8403120175 8403120213 8403120216 8403120217	8403120183 8403120183 8403120210 8403120210 8403120214	84/03/09 84/03/09 84/02/29 84/02/29 84/03/01	50-285 50-285 50-349 50-349 50-335	5666
8403070030 8403070037 8403070043 8403070073 8403070087	8403090032 8403090037 8403090037 8403090070 8403090081	84/03/02 84/02/22 84/02/22 84/03/05 84/02/21	50-382 50-354 50-354 50-219 50-277	A G G	8403120219 8403120226 8403120242 8403120244 8403120252	8403120214 8403120221 8403120234 8403120240 8403120240	84/03/01 84/03/02 84/03/02 84/02/29 84/02/29	50-335 CONTRACT 40-4720 50-335 50-335	g G
8403070092 8403070098 8403090101 8403090108 8403090115	8403090088 8403090095 8403090095 8403090104 8403090112	84/03/05 84/02/28 84/02/28 84/03/05 84/03/06	50-331 50-247 50-247 50-445 50-413	PPTG	8403120308 8403120311 8403120314 8403120342 8403120345	8403120305 8403120305 8403120304 8403120339 8403120340	84/02/27 84/02/27 84/02/28 84/02/21 84/02/22	50~293 50-293 CONTRACT 50-312 CONTRACT	F

ACCEBB10	N NUMBER					N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJE(ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC	
8403120357 8403120388 8403120393 8403130011 8403130014	8403120354 8403120376 8403120376 8403130002 8403130007	84/02/21 84/02/06 84/02/06 84/02/22 84/03/07	50-302 COMMISS COMMISS 50-266 50-354		6403130327 6403130330 6403130330 6403130335 6403130335	8403130317 8403130318 8403130305 8403130326 8403130317	84/03/05 84/03/07 84/03/01 84/03/05 84/03/05	GA999 50-397 50-317 50-409 GA999	P R G
8403130018 8403130021 8403130023 8403130030 8403130036	8403130012 8403130006 8403130002 8403130012 8403130032	84/03/09 84/02/27 84/02/22 84/03/09 84/02/02	50-322 50-220 50-266 50-322 0A999	9	8403130344 8403130345 8403130347 8403130352 8403130352	8403130341 8403130320 8403130340 8403130343 8403130342	84/02/08 84/03/08 84/03/07 84/03/09 84/03/06	50-370 50-462 50-220 50-312 50-462	P Q P Q A
8403130038 8403130041 8403130042 8403130051 8403130052	8403130031 8403130012 8403130032 8403130044 8403130045	84/03/01 84/03/09 84/02/02 84/03/09 84/03/01	50-348 50-322 0A979 50-341 50-34	P Q K P	8403130359 8403130364 8403130372 8403130372 8403130375	8403130348 8403130343 8403130360 8403130355 8403130342	84/03/06 84/03/09 84/02/03 84/03/08 84/03/06	50-373 50-312 50-423 50-354 50-482	0 0 0 0 A
8403130053 8403130058 8403130060 8403130063 8403130064	8403130012 8403130046 8403130044 8403130012 8403130055	84/03/09 84/02/16 84/03/09 84/03/09 84/02/07	50-322 GA779 50-341 50-322 GA779	e K O	8403130376 8403130389 8403130391 8403130399 8403130402	6403130342 6403130342 6403130386 6403130370 8403130375	84/02/03 84/03/06 84/03/08 84/03/08 84/02/16	50-423 50-482 50-220 50-482 50-313	C A P G G
8403130068 8403130073 8403130076 8403130077 8403130082	8403130046 8403130012 8403130046 8403130071 8403130012	84/02/16 84/03/09 84/02/16 84/03/11 84/03/09	0A799 50-322 GA799 50-413 50-322	9	8403130412 8403130414 8403130418 8403130420 8403130421	8403130256 8403130407 8403130410 8403080169 8403130416	84/02/27 83/11/17 84/03/05 84/03/01 84/02/21	50-286 0A999 50-237 50-315 50-461	R P R G
8403130087 8403130087 8403130090 8403130091 8403130094	8403130077 8403130046 8403130012 8403130085 8403130083	84/03/01 84/02/16 84/03/09 84/03/08 84/02/23	50-243 0A797 50-322 50-322 40-3392	R O O	B403130425 8403130430 8403130432 8403130433 8403130433	8403130407 8403130416 8403130268 8403130422 8403130428	83/11/17 84/02/21 84/02/17 84/03/08 84/03/09	GA999 50-461 GA999 40-6329 50-320	Q P
8403130076 8403130077 8403130100 8403130103 8403130106	9403130079 8403130012 8403130089 8403130079 8403130092	84/03/01 84/03/09 84/03/07 84/03/01 84/03/07	50-263 50-322 50-327 50-263 50-440	R G R	8403130444 8403130448 8403130451 8403130453 8403130459	8403130441 8403130438 8403130443 8403130442 8403130447	84/02/17 84/03/08 84/03/08 84/02/22 84/03/09	0A779 50-458 50-289 50-445 50-400	0
8403130109 8403130117 8403130118 8403130119 8403130126	8403130012 8403130101 8403130072 8403130012 8403130116	84/03/09 84/02/27 84/03/07 84/03/09 83/09/13	50-322 40-2061 50-440 50-322 50-445	A O F	8403130460 8403130463 8403130463 8403130471 8403130476	8403130441 8403130455 8403130452 8403130467 8403130472	84/02/17 84/03/01 84/02/29 84/02/27 84/03/07	GA999 50-348 50-325 50-320 70-1100	P D
8403130128 8403130135 8403130136 8403130138 8403130140	8403130092 8403130122 8403130116 8403130092 8403130131	84/03/07 84/01/25 83/09/13 84/03/07 84/01/18	50-440 50-267 50-445 50-440 50-382	A 0	8403130483 6403130487 8403130488 8403130487 6403130495	8403130475 8403130486 8403130478 8403130475 8403130474	84/02/29 84/02/27 84/03/08 84/02/29 84/02/23	50-320 50-458 50-331 50-320 CONTRACT	R F R
8403130142 8403130143 8403130148 8403130149 8403130154	8403130132 8403130133 8403130132 8403130132 8403130133	84/03/02 84/02/28 84/01/25 84/03/02 84/02/28	50-244 50-346 50-267 50-244 50-346	R P Q R P	8403130497 8403140012 8403140023 8403140026 8403140038	8403130498 8403140009 8403140017 8403140021 8403140032	84/02/17 84/03/09 84/03/07 84/03/01 84/03/07	50-312 50-458 50-250 50-329 50-329	0 0 A A
8403130157 8403130164 8403130168 8403130172 8403130178	8403130132 8403130156 8403130153 8403130163 8403130171	84/03/02 84/03/09 84/03/08 84/03/05 84/03/07	50-244 50-400 50-329 50-282 50-272	ROAFF	8403140060 8403140080 8403140086 8403140091 8403140095	8403140057 8403140048 8403140050 8403140048 8403140048	84/03/05 84/03/02 84/03/12 84/03/02 84/03/02	50-441 50-322 50-322 50-322 50-322	9 9 9
8403130176 8403130201 8403130207 8403130207 8403130217	6403130196 6403150283 6403130186 6403130178 6403130183	84/03/07 84/02/27 84/03/07 84/03/05 84/02/28	50-400 27-48 50-400 50-263 50-445	0 F 0	8403140097 8403140107 8403140117 8403140125 8403140140	8403140076 8403140101 8403140113 8403140120 8403140131	84/03/01 84/03/09 84/03/05 84/03/08 84/02/28	50-155 50-423 50-354 50-400 TDPREP	e K A F
8403130220 8403130230 8403130257 8403130258 8403130263	8403130186 8403130186 8403130251 8403130245 8403130251	84/03/07 84/03/07 84/03/02 84/03/01 84/03/02	50-400 50-400 50-267 50-282 50-267	9987	8403140143 8403140163 8403140168 8403140170 8403140178	8403140133 8403140159 8403140159 8403140166 8403140174	84/03/09 84/03/05 84/03/05 84/03/09 84/03/07	50-249 50-400 50-400 PR 50-400	P 0 0
8403130270 8403130272 8403130278 8403130280 8403130281	8403130245 8403130269 8403130245 8403130269 8403130276	84/03/01 84/02/27 84/03/01 84/02/27 84/02/08	50-219 50-219 6A999	R G R G	8403140180 8403140183 8403140184 8403140188 8403140200	8403140175 8403140175 8403140175 8403140133 8403140199	84/03/09 84/03/09 84/03/09 84/03/09 84/02/28	50-373 50-373 50-373 50-249 50-280	F F G
8403130289 8403130291 8403130293 8403130302 8403130308	B403130283 B403130276 B403130277 B403130294 B403130294	84/03/01 84/02/08 84/02/28 84/03/08 84/03/08	50-213 QA999 TOPREP 70-2199 70-2199	R	B403140202 B403140204 B403140205 B403140208 B403140217	8403140177 8403140179 8403140203 8403140206 8403140215	84/02/28 84/02/28 84/02/27 84/03/06 83/12/14	50-280 50-280 50-204 50-382 40-8027	0 0 8 U
8403130312 8403130314 8403130317 8403130322 8403130325	8403130300 8403130305 8403130313 8403130305 8403130307	84/02/23 84/03/01 83/09/13 84/03/01 84/02/16	H1SC 50-317 50-445 50-317 GA999	R F R	B403140238 B403140239 B403140240 B403140256 B403140279	8403140235 8403140236 8403140233 8403140252 8403140272	84/03/05 84/03/05 84/03/05 84/02/22 84/02/22	71-513 50-324 MISC 50-298 50-293	F F

ACCESS10	IN NUMBER				ACCESSION	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUDJECT CATEGORY	E	NCLOSURE	PRINCIPAL DOCUMENT	DATE IBSUED	SUBJECT CATEGOR	
8403140306 8403140308 8403140328 8403150014 8403150017	8403140300 8403140307 8403140325 8403150007 8403150012	84/03/01 84/03/07 84/03/05 84/03/09 84/03/01	50-250 XPORFLIC CONTRACT 50-440 50-219	9 9	3403160202 3403160204 3403160208 3403160210 3403160212	8403140201 8403140203 8403160205 8403140204 8403140204	84/02/14 84/03/12 84/03/07 84/02/21 84/02/23	50-390 50-219 50-219 50-335 50-424	G P G
8403150022 8403150030 8403150034 8403150041 8403150045	8403150027 8403150027 8403150027 8403150037 8403150040	84/03/13 84/02/28 84/02/28 84/02/29 84/03/09	50~354 50~388 50~388 50~313 50~237	9 9	8403160216 8403160220 8403160221 8403160222 8403160223	8403160211 8403160211 8403160211 8403160214 8403160218	84/03/05 84/03/05 84/03/05 84/02/17 84/03/01	50-413 50-413 50-413 50-390 50-259	0 0
8403150060 6403150063 8403150073 8403150078 8403150101	8403150053 8403150054 8403150067 8403150066 8403150096	84/03/09 84/02/29 84/03/01 84/02/28 84/03/01	50-387 50-277 50-273 50-272 50-410	9 8 8	1403160224 1403160225 1403160230 1403160233 1403160233	8403160211 8403160217 8403160218 8403160229 8403160232	84/03/05 84/02/15 84/03/01 84/03/09 84/02/16	50~413 50~327 50~259 50~267 50~259	0 0 0 P 0
8403150104 8403150107 8403150117 8403150117 8403150132	8403150097 8403150097 8403150111 8403150113 8403150125	84/03/13 84/03/09 84/03/09 84/03/09 84/02/28	50~316 50~280 50~293 50~313 50~320	ନ ଫ ଶ	6403160239 6403160240 6403160244 6403160248 6403160260	8403160218 8403160237 8403160218 8403160241 8403160255	84/03/01 84/02/27 84/03/01 84/03/02 84/03/12	50-259 50-390 50-259 50-352 50-298	0 0
8403150135 8403150136 8403150140 8403150142 8403150143	8403150125 8402090032 8403130137 8403150134 8403150137	84/02/28 84/03/13 84/03/07 84/02/28 84/03/07	50-320 (50-275 50-277 (XPORTLIC 50-277 (8: 8:	403160262 403160263 403160265 403160268 403160270	8403160249 8403160256 8403160257 8403160264 8403160258	84/02/29 84/03/14 84/03/05 84/02/24 84/03/07	50-261 50-443 50-348 50-335 70-143	Q Q Q
8403150144 8403150147 8403150152 8403150154 8403150157	8402070032 8403150146 8402070032 8403150133 8402070032	61/60/68 10/60/68 10/60/68 11/60/68 11/60/68	50-275 50-286 50-275 50-206 50-275	8: 8:	403160272 403160274 403160275 403160277 403160277	8403160257 8403160267 8403160249 8403160257 8403160271	84/03/03 84/03/07 84/02/29 84/03/03 84/03/15	50-348 50-261 50-261 50-348 50~390	0 0
8403150162 8403150163 8403150164 8403150166 8403150171	9402070032 8403150161 8403150160 9403150146 8403150168	84/03/13 84/03/09 84/03/02 84/03/01 84/03/07	50-275 1 50-241 F MISC 50-286 (50-298 F	8: 8: 8:	4031 60282 4031 60284 4031 60299 4031 60300 4031 60304	8403160273 8403160257 8403160273 8403160247 8403160277	84/03/08 84/03/05 84/03/08 84/02/29 84/03/07	50~259 50-348 50~413 50~261 50~369	0 0 0
8403150173 8403150183 8403150194 8403150197 8403150203	8403150168 8403150181 8403150194 8403150197 8403150200	84/03/07 84/02/28 84/03/05 84/02/29 84/03/09	50-298 F 50-327 S CONTRACT XPORTLIC 50-315 F	84 84 84	403160307 403160307 403160313 403160314 403160316	8403160273 8403160305 8403160277 8403160293 8403160306	84/03/08 84/02/15 84/03/07 84/03/08 84/02/21	50-413 50-375 50-369 50-413 50-250	0 0
8403150207 8403150209 8403150222 8403150223 8403150246	8403150205 8403150205 8403150221 8403150221 8403150243	84/01/16 84/02/28 84/03/07 84/03/07 84/02/21	40-8781 CONTRACT WASTE MOT WASTE MOT 50-346	8: 8:	4031 60317 4031 60318 4031 60319 4031 60320 4031 60322	8403160297 8403160308 8403160293 8403160315 8403160297	84/03/07 84/03/05 84/03/08 84/03/12 84/03/07	50-369 50-259 50-413 50-302 50-369	G Q Q P Q
8403150250 8403150278 8403150273 8403150275 8403150304	8403150243 8403150270 8403150290 8403150263 8403150270	84/02/21 84/03/07 84/03/06 84/02/27 84/03/07	50-344 F CONTRACT 50-282 F 50-344 F CONTRACT	8: 8: 0:	4031 60328 4031 60327 4031 60331 4031 60332 4031 60337	8403160308 8403160297 8403160327 8403160308 8403160308	84/03/05 84/03/07 84/03/13 84/03/05 84/03/05	50-259 50-349 50-305 50-259 50-259	0 0 0 0
8403150335 8403150340 8403150341 8403150344 8403150343	8403150328 8403150319 8403150336 8403150328 8403150343	84/03/02 83/10/21 84/03/06 84/03/02 84/02/27	50-269 P 40-8829 50-272 U 50-269 P 50-305 F	8: 8: 8:	4031 6034B 4031 60347 4031 60353 4031 60356 4031 60359	8403140340 8403140338 8403140337 8403160343 8403160338	84/03/02 84/03/09 84/02/27 84/02/17 84/03/09	70-1113 50-321 70-143 50-413 50-321	0
8403150347 8403160016 8403160017 8403160021 8403160022	8403150343 8403160008 8403160009 8403160009 8403160006	84/02/29 84/03/13 84/03/12 84/03/12	50-305 F 50-390 G 50-286 P 50-286 F 50-289 P	8: 8:	403160363 403160364 403160365 403160370 403160372	8403160343 8403160350 8403160338 8403160360 8403160338	84/02/17 84/03/03 84/03/09 84/02/24 84/03/09	50-413 50-390 50-321 50-413 50-321	9
8403160049 8403160052 8403160083 8403160092 8403160096	8403160041 8403160048 8403160079 8403160086 8403160090	84/03/02 84/03/14 84/03/08 84/02/27 84/03/09	50-320 F 50-528 A 50-445 A 50-413 0 50-412 A	8: 8:	403160374 403160378 403160380 403160383 403160383	8403160350 8403160350 8403160375 8403160350 8403160382	84/03/05 84/03/05 84/03/02 84/03/05 84/02/17	50-390 50-390 70-1113 50-390 50-261	0
8403140108 8403140111 8403140120 8403140141 8403160146	8403160100 8403160101 8403160110 8403160134 8403160142	84/02/13 84/02/14 84/02/13 84/02/14 84/02/15	50-414 6 50-367 6 50-367 6 50-267 6 50-348 6	84 84 85	4031	6403160377 8403160335 8403160325 8403190010 8403190010	84/03/05 84/03/08 84/02/24 84/03/09 84/03/09	70-143 50~302 70-143 50-142 50-142	000
8403160157 8403160171 8403160173 8403160178 8403160181	8403160152 8403160162 8403160138 8403160162 8403160162	84/03/02 84/02/27 84/02/28 84/02/27 84/02/27	50-272 0 50-259 0 70-143 50-259 0 50-259 0	8/ 8/ 9/	403190016 403190021 403190022 403190023 403190042	8403170011 8403170011 8403170010 8403170018 8403170020	84/03/15 84/03/15 84/03/09 84/03/14 84/03/01	50-275 50-275 50-142 50-317 50-282	G
8403160184 8403160185 8403160187 8403160188 8403160198	8403160169 8403160162 8403160010 8403160010 8403160196	84/02/29 84/02/29 84/03/13 84/03/13 84/02/24	XFORTLIC 50-257 G 50-352 G 50-352 G 50-321 G	84 84 84	4031 90058 4031 90040 4031 90041 4031 90067 4031 90072	8403170053 8403170054 8403170057 8403170045 8403170048	84/03/15 84/03/05 84/03/08 84/03/12 84/03/02	50-400 50-320 50-285 50-400 50-373	Q H G F



ACCESSION NUMBER			ACCESBION NUMBER						
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	CATEG		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 18SUED	SUBJECT CATEOUS	
8403190076 8403190077 8403190082 8403190087 8403190088	8403190048 8403190074 8403190074 8403190083 8403190085	84/03/02 84/03/15 84/03/15 84/03/08 84/03/14	50-373 50-249 50-249 50-267 50-123	0 0 P 0	84031 90373 84031 90381 84031 90381 84031 90385 84031 90385	8403190367 8403190377 8403190379 8402090035 8403190394	84/03/01 84/03/15 84/02/27 84/03/12 84/02/29	50-206 50-338 50-305 50-322 50-413	0 0 5 4
8403170070 8403170073 8403170074 8403170076 8403170102	8403170084 8403170083 8403170085 8403170085 8403170100	84/03/13 84/03/08 84/03/14 84/03/14 84/03/15	50-373 50-267 50-123 50-123 50-275	0 9 0	B403170404 B403170407 B403200035 8403200037 B403200044	8403190394 8403190408 8403200029 8403200031 8403200038	84/02/29 84/03/06 84/03/15 84/03/16 84/03/12	50-413 50-317 50-317 50-322 50-302	A G G P
8403170106 9403170110 8403170113 8403170114 8403170116	8403170100 8403170100 8403170107 8403170100 8403170100	84/03/15 84/03/15 84/03/15 84/03/15 84/03/15	50-275 50-275 50-249 50-275 50-275	0 0 0	8403200052 8403200057 8403200058 8403200062 8403200063	8403200046 8403200053 8403200046 8403200056 8403200046	84/03/15 84/03/15 84/03/15 84/03/14 84/03/15	50-346 50-346 50-346 50-219 50-346	P 0 P
8403170117 8403170122 8403170126 8403170130 8403170134	8403170100 8403170100 8403170100 8403170100 8403170100	84/03/15 84/03/15 84/03/15 84/03/15 84/03/15	50-275 50-275 50-275 50-275 50-275	0 0	84032000A7 8403200074 8403200076 8403200077 8403200082	8403200054 8403200053 8403200072 8403200053 8403200053	84/03/14 84/03/15 84/03/15 84/03/15 84/03/15	50-219 50-361 0A999 50-361 50-361	Q R R
8403190138 8403190141 8403190142 8403190149 8403190155	8403170132 8403170137 8403170132 8403170136 8403170151	84/03/13 84/03/14 84/03/13 84/03/14 84/03/13	50-352 50-400 50-353 50-259 50-213	6 0 0	B4032000B5 B4032000B6 B4032000BB B4032000B9 B4032000871	8403200081 8403200053 8403200053 8403200083 8403200053	84/03/16 84/03/15 84/03/15 84/03/14 84/03/15	50-470 50-361 50-361 40-2061 50-361	K R R
8403190161 8403190172 8403190175 8403190179 8403190185	9403170136 8403170136 8403170170 8403170171 8403170183	84/03/14 84/03/14 84/03/14 84/03/14 84/03/02	50-259 50-259 50-461 50-250 QA999	0 0 0	8403200076 8403200101 8403200108 8403200112 8403200117	8403200094 8403200100 8403200102 8403200109	84/03/15 84/03/16 84/03/16 84/03/16 84/03/06	50-333 50-316 50-354 50-407 50-483	P G F
8403190186 8403190188 8403190187 8403190190 8403190192	8403170180 8403170136 8403170187 8403170183 8403170180	84/03/09 84/03/14 84/03/15 84/03/02 84/03/09	50-329 50-259 50-289 0A999 50-329	A G G	8403200134 8403200130 8403200140 8403200142 8403200143	8403200131 8403200131 8403200131 8403200138 8403070038	84/03/16 84/03/16 84/03/16 84/03/07 84/03/12	50-322 50-322 50-322 6A999 50-322	0 0 0
8403190204 8403190208 8403190210 8403190214 8403190217	8403190201 6403190207 6403190209 8403190209 8403190215	64/03/15 64/03/01 84/02/23 64/02/23 16/02/23	50-337 50-254 GA777 GA777 50-320	о О	8403200145 8403200145 8403200150 8403200151 8403200152	8403200131 8403200131 8403200138 8403200131 8403200149	84/03/15 84/03/15 84/03/07 84/03/14 84/03/13	50-322 50-322 0A999 50-322 50-423	9 9 8 A
8403190220 8403190221 8403190228 8403190229 8403190234	8403190219 8403190218 8403190227 8403190225 8403190231	84/03/16 84/03/24 84/03/13 84/03/13 84/03/09	50-414 0A979 50-389 50-482 70-371	O P A	8403200155 8403200157 840320169 8403200180 8403200181	8403200131 8403200138 8403200131 8403200179 8403200179	84/03/14 84/03/07 84/03/16 84/03/15 84/03/15	50~322 0A999 50~322 50~313	0 0 F F
8403190239 8403190244 8403190246 8403190247 8403190256	8403170236 8403170240 8403170241 8403170240 8403170251	84/03/13 84/03/05 84/03/14 84/03/05 84/01/31	50-331 50-266 TOPREP 50-266 REVIEW 6	0 0 0 8RP	8403200187 8403200193 840320195 8403200196 8403200200	8403200187 8403200190 8403200191 8403200191 8403200191	84/03/14 84/03/16 84/03/19 84/03/19 84/03/19	50~482 50~461 50~289 50~289 50~289	K 0 0
8403190261 8403190265 8403190272 8403190274 8403190278	8403190257 8403190258 8403190271 8403190268 8403190268	84/03/07 84/03/13 84/03/08 84/03/08 84/03/08	50-347 50-284 50-382 50-454 50-454	P G G	8403200205 8403200205 8403200211 8403200214 8403200220	8403200191 8403200201 8403200191 8403200210 8403200218	84/03/19 84/03/15 84/03/19 84/03/15 84/03/12	50~289 50~320 50~289 50~316 50~275	0 Р О Р
8403190281 8403190282 8403190283 8403190288 8403190293	8403170277 8403170275 8403170277 8403170277 8403170270	84/03/13 84/03/19 84/03/08 84/03/08 84/02/29	50-285 50-312 50-313 50-313 50-373	Q Q Q Q	8403200228 8403200240 8403200241 8403200243 8403200248	6403200223 6403200232 8403200234 8403200232 8403200232	84/03/15 84/03/15 84/03/13 84/03/15 84/03/15	50-315 50-410 50-397 50-410 50-410	P A P A
8403170274 8403170277 8403170305 8403170306 8403170313	8403190286 8403190290 8403190297 8403190300 8403190309	84/03/14 84/02/29 84/03/05 84/03/12 84/03/01	50-546 50-373 50-454 50-331 50-341	0 0 0 P 0	8403200251 8403200258 8403200260 8403200263 8403200264	8403200246 8403200246 8403200252 8403200256 8403200264	84/03/14 84/03/14 84/03/14 84/03/13 84/03/14	50-313 50-313 50-482 50-373 50-250	F A Q P
8403170317 8403170321 8403170321 8403170323 8403170324	8403190276 8403190314 8403190314 8403190315 8403190276	84/03/05 84/03/01 84/03/01 84/02/29 84/03/05	50-334 50-275 50-275 50-358 50-334	R G G R	8403200249 8403200270 8403200277 8403200285 8403200288	8403200252 8403200264 8403200274 8403200279 8403200284	84/03/14 84/03/14 84/03/13 84/03/15 84/03/19	50-462 50-250 50-271 50-483 50-29	A P Q Q P
8403170330 8403170333 8403170334 8403170340 8403170347	8403190328 8403190328 8403190314 8403190328 8403190341	84/02/24 84/02/24 84/03/01 84/02/24 84/03/14	GA999 GA999 50-295 GA999 50-346	Q B	8403200290 8403200291 8403200294 8403200294 8403200297	8403200284 8403200287 8403200281 8403200281 8403200295	84/03/17 84/03/04 84/03/14 84/03/14 84/03/06	50-29 50-243 50-72 50-72 50-434	P 0 F 0
8403170351 8403170354 8403170357 8403170357 8403170366	8403170345 8403170348 8403170350 8403170350 8403170360	84/03/14 84/02/28 84/03/06 84/03/06 84/03/13	50-361 50-440 50-267 50-267 50-387	P G P Q	8403200300 8403200301 8403200325 8403200325 8403200335	8403200295 6403140244 8403200323 8403200323 8403200333	84/03/06 84/03/28 84/02/23 84/02/23 84/02/27	50-454 50-275 40-4492 40-4492 40-1341	g 0

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSIO	N NUMBER				ACCE991	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEG		ENCLOBURE	PRINCIPAL DOCUMENT	DATE 185VED	SUBJEC	
8403200374	8403200387	84/02/16	40-8681		8403220266		64/03/12	CONTRAC	
8403210005 8403210010	8403210001 8403210001	84/03/14 84/03/14	40-4920 40-4920		8403220280 8403220293	8403220275	84/03/12 84/03/21	CONTRAC	
840321001 <i>6</i> 8403210020	8403210006 8403210015	84/03/09 84/03/09	50-317 TOPREP	O	8403220294 8403220297	8403220289	84/02/27 84/03/21	XFORTLI 50-322	
8403210054	8403210047	84/03/09	50-320	a	84 03220302		84/03/21	50-322	
8403210055 8403210062	8403210045 8403210057	84/03/16 84/03/18	50-277 50-416	P	8403220305 8403220310	8403220288	B4/03/21	50-322	T
8403210063 8403210064	8403210045 8403210059	84/03/14 84/02/28	50-277 50-320	P	8403220312	8403220307	84/03/21 84/03/08	50-322 CONTRAC	
B403210071	8403210059	84/02/28	50-320	R	100220013		84/03/21	20-355	T
8403210078 8403210077	8403210074 8403210070	84/03/14 84/03/19	50-341 50-245	A	8403220324 8403220324	6403220322	84/03/09 84/03/02	CONTRACT XPORTLI	
8403210080 8403210081	8403210075 8403210072	84/03/15 84/03/09	50-324 50-387	р К	8403220327 8403230007	8403220325 8403230004	84/03/07 84/03/16	CONTRACT 50-331	T P
8403210082	8403210076	B4/03/01	50-289	R	840323002#	8403230018	84/03/14	50-341	A
8403210088	8403210076	B4/03/01	50-289	R	8403230034 8403230037	8403230029 8403230033	84/03/09 84/03/20	50-245 50-423	F
8403210090 8403210091	8403210072 8403210085	84/03/09 84/03/15	50-387 50-373	K	8403230046 8403230052	8403230043 8403230044	84/03/19 84/03/07	50-329 CONTRACT	R
8403210101	8403210099	84/03/14	50-443	A	E403230054	8403230049	84/01/31	50-325	P
8403210105 8403210119	8403210097 8403210114	84/03/09 84/03/16	50-334 50-275	0	8403230067 8403230076	8403230062 8403230071	84/03/20 84/03/05	50-302	P
8403210122 8403210126	8403210115 8403210124	84/01/11 84/03/15	50-416 50-166	Q P	B4032300B1	8403230075	84/03/19	50-373	G
8403210143	8403210135	B4/03/19	50-244	P	8403230087 8403230089	8403230075 8403230084	84/03/19 84/03/20	50-373 50-416	G P
8403210146 8403210156	840321013B 8403210151	84/03/01 84/03/19	50~289 70~143	R	6403230092	8403230094	84/03/20	50-416	Р
8403210173	8403210169	84/03/20 84/03/20	50~289	G	8403230098 8403230100	6403230093 8403230097	84/03/16 84/02/29	50-255 40-3392	Р
8403210181 8403210200	8403210177 8403210197	84/03/07	50-322 50-247	P	8403230102 8403230106	8403230093 8403230093	64/03/16 84/03/16	50-255 50-255	P
8403210206	8403210203	84/03/04	50-338	2	8403230107	B403230088	84/03/20	50-10	a
6403220004 8403220010	8403220002 8403220005	84/03/13 84/03/08	50-219 50-272	P G	8403230111 8403230112	8403230093 8403230110	84/03/16 84/03/16	50~255	P
8403220022 8403220023	8403220013 8403220021	84/03/16 84/03/20	50-329 50-155	R	8403230122 8403230122	8403230119 8403230119	84/02/29	50-219 50-219	R
8403220024	8403220018	84/03/19	50-206	F	8403230126		84/02/29	50-219	R
8403220027 8403220032	8403220018 8403220028	84/03/17 84/03/t6	50~206 50~338	F	8403230128	840323008B 8403230125	B4/03/20 B3/05/24	50-10 50-317	G B
8403220041 8403220042	8403220033 8403220031	84/03/15 84/03/19	50-387 50-298	Q Q	8403230130 840323013B	8403230129 8403230137	84/03/01 64/03/19	CONTRACT	a
8403220044	8403220038	84/03/20	50-349	P	B403230141	8403230137	84/02/29	50-275	R
8403220054 8403220060	8403220045 8403220050	84/02/27 84/03/19	40-4492 50~315	a	8403230150 8403230154	8403230149 8403230152	83/10/07 84/03/12	50-416 CONTRACT	8
8403220062	8403220054	84/03/07	50-309	0	8403230157 8403230160	8403230156 8403230159	84/02/27 84/03/07	40-8745 CONTRACT	
8403220071	8403220068	84/02/28	40-6564	_	B403230164	8403230142	84/03/12	10CFR	
8403220081 8403220085	8403220079 8403220083	84/03/15 84/03/12	50-333 50-277	G G	8403230175 8403230181	8403230171 8403230178	83/05/24 83/05/11	50-317 50-305	S 8
8403220087 8403220087	8403220083 8403220084	84/03/12 84/03/04	50-277 50-354	Q Q	8403230244 8403230246	8403230241 8403230241	84/03/09	70-1359	
8403220091	6403220083	84/03/12	50-277	G	8403240022	8403260018	84/03/09 84/03/05	70-1359 50-454	Α
8403220092 8403220097	8403220090 8403220094	B4/03/09 B4/03/07	40-472 50-454	a	8403260023 8403260026	8403250019	84/03/16	50-346	a
8403220098 8403220099	8403220095 8403220093	84/03/07	50-369 50-266	Q Q	84032&0030	9003260017 8403260027	84/03/21 84/03/05	50-34B XPORTLIC	
8403220103	8403220075	84/03/07	20-309	a	8403260032 8403260040	8403260017 8403260017	84/03/21 84/03/21	50-348 50-348	8 8
8403220110 8403220111	8403220104 8403220109	B4/03/20 B4/03/05	50-275 50-341	9	8403260042	8403260037	84/02/23	XPORTLIC	
8403220114 8403220115	8403220109 8403220105	84/03/05 84/03/06	50-341 50-272	ä	8403260046 8403260048	8403260017 8403260045	84/03/21 84/03/06	50-348 50-321	8 P
8403220124	8403220117	84/02/28	40-8584		84032A0061 B4032A00AB	8403240037 8403240040	84/03/05 84/01/12	50-454 50-458	A
8403220125 8403220127	8403220121 8403220123	84/03/20 84/03/15	50-206 50-373	P	8403260075	8403250072	84/03/19	50~246	8
8403220135	640322012B	E4/03/13	50-387	a	8403260077 8403260080	8403260071 8403260073	84/03/03 84/03/20	50-344 50-413	P A
8403220137 8403220140	8403220131 8403220134	84/03/08 84/03/08	50-412 50-305	G G	8403260081 8403260083	8403260069 8403260071	84/02/28 84/03/03	50~445 50~344	G P
8403220155	6403220152	84/03/13	50-219	P	8403250084	8403240082	84/03/09	70-1257	·
8403220158 8403220160	8403220153 8403220143	84/03/15 84/03/06	50-237 50-322	G.	8403260087 8403260088	8403260078 8403260071	64/02/27 B4/03/03	50-382 50-344	a P
8403220165 8403220167	8403220161 6403220162	84/03/07 84/03/16	50-275 50-246	P	8403260099 8403260107	8403260070 8403260100	84/03/05 84/02/14	50-313 50-247	0
8403220173	8403220170	84/03/15	40-8824		8403260107	8403260102	84/02/22	40-1341	u
8403220187 8403220199	6403220183 6403220172	84/02/27 84/03/19	40~8498 50~309	P	8403260110 8403260111	8403240105 8403240106	84/03/22	50-280	P
8403220212 8403220213	8403220208 8403220208	84/03/06 84/03/06	50~338 50~338	P	8403260112 8403260117	8403260104 8403260113	84/03/09 84/03/15	50-275 50-317	ō N
8403220219	8403220214	84/03/12	CONTRACT		8403260129	B403260113	84/03/20	50-322	F
6403220224 6403220229	6403220220 6403220226	84/01/16 84/03/19	40-1341 50-352	Q	8403260134 8403260135	8403260123	84/03/02 84/03/02	40~1478 40~1478	
8403220234 8403220257	8403220226 8403220254	84/03/19 84/03/01	50-352 50-266	B	8403260141	8403260123 8403260123	84/03/15 84/03/02	40-1478	Α
				•	8403260142	8403260138	84/01/18	40~8102	

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION	NUMBER				VCCERBIU				
	PRINCIPAL	DATE	SUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 196UED	SUBJECT CATEGORY	
ENCLOSURE	DOCUMENT	ISSUED	CATEODR	Y 					-
8403260148 8403260151	8403260123 8403260143	84/03/02 84/02/29	40-1479 50-213	F	8403270252 8403270253	8403270246 8403270249	84/03/22 84/03/19	50~285 0	
8403260153 8403260157	8403260123 8403260051	84/03/02 84/03/16	40~1478 50-313	P	8403270253 8403270260	8403270246 8403270246	84/03/22 84/03/22	30-454	3
8403260158	8403260123	84/03/02	40-1478		8403270263	8403270246	84/03/22	50-454 (3
8403260167 8403260172	8403260161 8403260168	84/02/03 84/01/19	50~267 50~285	G G	840327028 4 8403270290	8403270282 8403270284	84/03/07 84/03/07	CONTRACT	
E403260173	B403260166	84/03/12	50-334	œ œ	8403270306 8403270338	8403270302 8403270333	84/03/07 84/03/23	CONTRACT 50-400 C	•
8403260177 8403260183	8403260174 8403260179	84/03/08 84/03/22	50-267 70-27	u	8403270350	0302020109	83/01/19		3
8403260201	8403240198	B4/03/19	50-244	P	8403270362	8403270360	84/03/09	CONTRACT	
8403260209 8403260211	8403260205 8403260205	84/03/03 84/03/03	50-267 50-267	G G	6403270368 8403260014	8403270365 8403280009	84/03/08 84/02/21	50-416 F	
8403260214 8403260220	8403260206 8403260217	84/02/03 84/02/06	50-445 50-458	G G	6403280018 8403280023	8403280009 8403280009	84/02/21 84/02/21	50-416 F	
8403260232	6403260230	84/03/0B	50-313	a	8403280044	8403280037	B4/03/23	50-348 F	,
8403260234	8403260227	84/03/22	50-348	P	8403280052 8403280054	8403280049 8403280045	84/03/06 84/03/12	CONTRACT 50-341 F	4
8403260237 8403260238	8403240228 8403260235	84/03/21 84/02/17	50-454 50-298	Q Q	8403280055	8403280050	B4/03/13	XPORTLIC 50-83 F	
8403260240	8403260235	84/02/17	50-278	Œ	8403280068	8403280065	B4/03/06		
B403260248	8403260236 8403260245	84/02/27 84/02/14	50-317 50-382	P a	8403280071 8403280079	8403280045 8304270367	84/03/06 83/04/13	50-83 F	
8403260253	8403260249	84/03/22	50-352	E	84032800B1 8403280101	8403280080 8403280090	84/01/17 84/03/12	FO1A 50-295 F	
8403260265 8403260281	8403260261 8403260273	84/02/21 84/03/06	50-321 50-338	F	8403280103	8403280099	83/11/21	40-8586	
8403260304	8403260302	84/03/05	50-344	F	8403280106	9403290090	84/03/12 84/03/12	50-275 F	
8403260307 8403260308	8403260276 8403260302	84/03/08 84/03/05	CONTRACT 50-344	F	8403280108 8403280121	8403280090 8305160260	B3/05/05	50-291 E	
8403260317 8403260322	8403260313 8403260316	84/03/20 84/03/01	50-293 CONTRACT	œ	8403280151 8403280156	8403280147 8403280149	84/03/0B 84/03/07	XPDRTLIC 50~250 F	1
B403260327			50-34B	Р	8403280157	8403280153	84/03/08	COMMISSION	4
B403260336	8403260326 8403260331	84/03/08 84/03/09	71-5450	r	8403280140 8403280170	8403280153 8403280167	84/03/08	50~287 T FOIA	Γ
8403260341 8403260342	8403260323 8403260338	84/03/06 84/03/21	CONTRACT 50-322	٢	B403280174	8403280167	84/02/22	FOIA	
8403260347	8403260344	84/02/27	WARTE MG	T	8403280177	8403280167	84/02/22	FOIA	
8403260350 8403260353	8403260344 8403260344	84/02/27 84/02/27	WASTE MG		8403280182 8403280185	8403280167 8403280167	84/02/22 84/02/22	FOIA FOIA	
B403260354	8403260348	84/03/23	50-400 CONTRACT	G	8403280187 840328018B	8403280186 8403280167	84/03/07 84/02/22	CONTRACT FOIA	
8403260356 8403260367	8403260352 8403260368	84/03/09 84/03/22	50-275	Q	84032B0171	8403280167	B4/02/22	FOIA	
B403240370	8403260363	84/03/08	CONTRACT		8403280197 8403280219	8403280167 8403280214	84/02/22 84/03/14	F01A 71-9036	
8403260379 8403260414	8403260377 8403260411	84/03/22 83/03/23	50-322 50-325	S	8403280225	8403280216	84/03/07	50-482 (
8403270015 8403270022	8403270010 8403270010	84/03/20 84/03/20	50-293 50-293	P	8403280229 8403280235	8403280216 8403280216	84/03/07 84/03/07	50-482 C	
8403270024	8403270010	84/03/20	50-273	P	8403280240	8403280216	84/03/07	50-482	3
8403270032	8403270030	B4/03/16	50-305	þ	8403280263 8403280273	8403280240 8403280270	84/03/09 84/03/07	CONTRACT MISC	
8403270038 8403270048	8403270030 8403270042	84/03/16 84/03/21	50-305 50-352	T	840328027G 8403280282	8403280270 8403280270	84/03/07 84/03/07	MISC MISC	
8403270054	8403270050	84/03/21	GA999					MISC	
8403270057 8403270067	8403270053 8403270064	84/03/21 84/03/08	50-275 50-277	P P	8403280288 8403280274	8403280270 8403280270	84/03/07 84/03/07	MISC	
B403270069	8403270065	84/03/19 84/03/23	50-352 50-458	Q Q	8403280275 8403280301	8403280270 8403280270	84/03/07 84/03/07	M18C	
B403270076 B403270094	8403270070 8403270086	84/03/22	40-8760	u	8403270004	8403270002	84/01/13	50-247 f	7
8403270097	8403270092	84/03/21	QA999	_	8403270006 8403270007	8403290002 8403290002	84/01/13 84/01/13	FOIA FOIA	
8403270113 8403270122	8403270104 8403270119	84/03/22 84/03/15	50-155 50-322	PR	8403270007	6403270002 6403270002	84/01/13 84/01/13	FOIA FOIA	
8403270127 8403270129	8403270123 8403270123	84/03/22 84/03/22	50-320 50-320	P	8403270010 8403270011	8403270002 84032700 02	84/01/13	FOIA	
8403270136	8403270130	84/03/19	50-249	P	8403290012	8403270002	84/01/13	FOIA	
8403270139	8403270135	64/03/22	50-528 50-293	Qi P	8403270014 8403270016	8403270002 8403270002	B4/01/13 B4/01/13	FOIA FOIA	
8403270143 8403270144	8403270055 8403270130	84/03/20 84/03/19	50-249	P	8403270018 8403270020	8403270002 8403270002	84/01/13 84/01/13	FOIA FOIA	
8403270157	8403270132	84/03/23	50-322	s		8403270002	84/01/13	FOIA	
8403270180 8403270181	8403270177 8403270170	84/03/09 84/03/23	50-461 50-282	œ œ	8403270021 8403270022	B403270002	84/01/13	FOIA FOIA	
8403270184 8403270188	8403270178 8403270183	84/03/07 84/03/22	QA999 50-395	P	8403290023 8403290024	8403270002 8403270002	84/01/13 84/01/13	FOIA	
9403270191	8403270189	84/03/14	50-247	P	8403290025	8403270002	B4/01/13	FOIA	
B403270194	8403270189	84/03/14	50-247	P	8403290027 8403290028	8403290019 8403290002	B4/02/29 B4/01/13	50-348 (FDIA	O
8403270212 8403270217	8403270210 8403270214	84/03/22 84/01/14	50-320 70-1257	P	8403290031 8403290034	8403270002 8403270002	84/01/13 84/01/13	FOIA FOIA	
8403270221 8403270225	8403270214 8403270223	B4/01/16 B4/03/22	70-1257 50-395	P	8403290034 8403290035	8403270002	B4/01/13	FOIA	
B403270234	8403270228	84/03/02	QA999		8403290034	8403290002	84/01/13	FOIA	
B40327023B B403270239	8403270233 8403270235	84/03/09 84/03/21	50-409 50-241	Q: P	8403270040 8403270041	8403290002 8403290002	84/01/13 84/01/13	FOIA FOIA	
B403270241	8403270228	B4/03/02	GA797 50-409		840 3 2700 44 840 3 270045	8403270002 8403270002	84/01/13 84/01/13	FOIA 50-266	P
B403270242	8403270233	84/03/09	20-407	Q	2,100-100				

ACCESSION NUMBER

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

ACCESSIU	NUMBER				AGUE	821UN	NONGER			
ENGLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC		ENCLOSU	RC	PRINCIPAL DOCUMENT	DATE 19606D	SUBJECT CATEGOR	
8403270046 8403270048 8403270047 8403270050 8403270051	8403270002 8403270002 8403270002 8403270042 8403270002	84/01/13 84/01/13 84/01/13 84/03/06 84/01/13	FOIA FOIA 50-264 50-390 FOIA	P Q	8403290 8403290 8403290 8403290 8403290	220 234 237 240	8403290178 8403290231 8403290237 8403290250 8403290262	84/03/20 84/02/27 84/03/05 84/03/14 84/03/01	50~259 50~302 50~259 50~338 50~302	9 9
8403270052 8403270054 8403270055 8403270057 8403270058	8403290002 8403290002 8403290002 8403290053 8403290002	84/01/13 84/01/13 84/01/13 84/03/13 84/01/13	FOIA FOIA 50-334 FOIA	a	84 02290 84 03296 84 03296 84 03290 84 03290)273)276)279	8403270250 8403270247 8403270270 8403270267 8403270250	84/03/16 84/03/23 84/03/15 84/03/23 84/03/16	50-338 50-369 50-413 50-369 50-338	0 P Q P
8403270057 8403270061 8403270062 8403270063 8403270063	8403290002 8403290002 8403290053 8403290002 8403290002	84/01/13 84/01/13 84/03/13 84/01/13 84/01/13	FOIA FOIA 50-334 FOIA FOIA	a	8403290 8403290 8403290 8403290 8403290	297 290 291	8403270267 8403270283 8403270275 8403270250 8403270286	84/03/23 64/03/21 64/03/01 64/03/16 64/03/13	50~369 50~409 50~369 50~338 50~29	P G G
8403290056 8403290068 8403290070 8403290071 8403290073	8403290043 8403290002 8403290002 8403290064 8403290002	84/03/15 84/01/13 84/01/13 84/03/13 84/01/13	70-398 FOIA FOIA 50-271 FOIA	G.	8403290 8403290 8403290 6403290 8403290	304 305 308	8403270287 8403270277 8403270302 8403270302 8403270317	84/03/05 84/03/27 84/03/16 84/03/16 84/02/29	50-338 50-250 50-354 50-354 50-335	9 A A
8403270075 8403270082 8403270084 8403270087 8403270070	8403290002 8403290049 8403290078 8403290078 8403290049	84/03/20 84/03/20 84/03/14 84/03/14 84/03/20	FOIA 50-249 50-348 50-249	0 0 0	8403290 8403290 8403290 8403290)343)344)387	8403270338 8403270338 8403270341 8403270385 8403270375	84/03/05 84/03/05 84/02/27 84/03/27 84/03/25	FOIA FOIA 50-328 40-2061 50-352	D O
8403290092 8403290095 8403290096 8403290098 8403290102	8403270086 8403270057 8403270078 8403270073 8403270073	84/03/07 84/03/20 84/03/14 84/03/23 84/03/23	50-324 50-269 50-348 50-461 50-461	G G I I	8403290 8403290 8403300 8403300 8403300	1405 1014 1015	8403290399 8403290404 8403300009 8403300011 8403300017	84/03/28 84/03/08 84/03/29 84/03/26 84/03/13	50-352 XPORTL10 50-352 70-27 50-454	G T
8403290103 8403290104 8403290107 8403290108 8403290113	8403270078 8403270077 8403270073 8403270067 8403270110	84/03/14 84/03/13 84/03/23 84/03/20 84/03/14	50-348 50-219 50-461 50-269 ACRS	0 1 0	8403300 8403300 8403300 8403300 8403300	040 040	8403300017 8403300026 8403300036 8403300041 8403300042	84/03/13 84/03/16 84/03/15 84/02/15 84/03/14	50-454 50-456 50-282 70-27 50-315	G G G
8403290114 8403290119 8403290120 8403290124 8403290126	8403270107 8403270116 8403270116 8403270107 8403270107	84/03/19 84/03/13 84/03/13 84/03/19	50-335 50-387 50-387 50-335 50-335	0 0 0	8403300 8403300 8403300 8403300 8403300	050 051 057	8403300048 8403300046 8403300042 8403300053 8403300063	84/03/28 84/01/31 84/03/14 84/03/15 84/03/21	50-382 50-313 50-315 50-341 50-387	F G G G
8403290132 8403290139 8403290142 8403290146 8403290147	8403270107 8403270135 8403270140 8403270145 8403270143	84/03/19 84/03/22 84/03/14 84/03/19 84/02/28	50~335 50~272 50~387 50~412 50~413	0 0	8403300 8403300 8403300 8403300 8403300	0076 0072 0073	8403300045 8403300072 8403300086 8403300089 8403300098	84/03/23 84/03/16 84/03/23 84/03/20 84/03/16	50-271 50-322 50-245 50-407 50-354	0 0 0 P 0
8403290147 8403290150 8403290154 8403290155 8403290156	8403290140 8403290144 8403290148 8403290140 8403290151	84/03/14 84/03/13 84/03/14 84/03/14	50-387 50-352 50-369 50-387 50-416	0 P 0	840330(840330 840330 840330 840330)116)117)132	8403300111 8403300107 8403300125 8403300125 8403300133	84/03/26 84/03/28 84/03/28 84/03/15 84/03/09	50-302 50-413 50-413 50-498 50-259	S A A A R
8403290162 8403290164 8403290165 8403290166 8403290169	8403290159 8403290148 8403290140 8403290163 8403290163	84/03/22 84/03/16 83/12/21 84/03/20 84/03/20	50-302 50-369 50-322 50-400 50-400	P F G	8403300 8403300 8403300 8403300 8403300)140)146)156	8403300133 8403300137 8403300142 8403300149 8403300149	84/03/09 84/03/27 84/03/23 84/03/22 84/03/22	50-259 70-687 50-271 50-346 50-346	R G P P
8403290171 8403290173 8403290180 8403290183 8403290188	9403270163 8403270163 8403270174 8403270178 8403270185	84/03/20 84/03/20 84/03/20 84/03/26	50-400 50-400 50-235 50-257 50-244	0 0 0 0	8403306 8403306 8403306 8403306 8403306)169)177)183	8403300161 8403300165 8403300171 8403300171 8403300173	84/03/23 84/03/24 84/03/23 84/03/23 84/03/15	50-213 50-223 50-272 50-272 50-250	G G G R
8403290189 8403290190 8403290191 8403290194 8403290195	8403270185 8403270178 8403270186 8403270193 8403270193	84/03/26 84/03/20 84/03/13 84/03/15 84/03/15	50~244 50~259 50~289 50~364 50~364	P G G G	8403300 840330 8403300 8403300 8403300)190)191)193	8403300180 8403300180 8403300189 8403300173 8403300224	84/03/23 84/03/23 84/03/23 84/03/15 84/03/15	50-311 50-311 50-244 50-250 71-9134	G G R
8403270174 8403270177 8403270177 8403270203 8403270204	8403270173 8403270173 8403270178 8403270178 8403270200	84/03/15 84/03/15 84/03/06 84/03/20 84/03/22	50-366 50-366 50-400 50-259 50-412	0 0 0	8403300 8403300 8403300 8403300 8403300)274)277)30 2	8403300235 8403300271 8403300273 8403300278 8403300309	84/03/13 84/03/27 84/03/15 84/03/19 84/03/20	TOPREP 50-352 70-1257 71-9027 CONTRACT	o r
8403270205 8403270207 8403270207 8403270210 8403270211	8403270202 8403270178 8403270201 8403270205 8403270178	B4/03/15 B4/03/20 B4/03/01 B4/03/15 B4/03/20	50-320 50-259 50-390 50-272 50-259	G G G	В403300	327	8403300324	84/03/13	50-241	Œ
8403270212 8403270214 8403270215 8403270216 8403270217	8403270208 8403270178 8403270208 8403270208 8403270208	84/03/19 84/03/20 84/03/19 84/03/19 84/03/19	50-321 50-259 50-321 50-321 50-321	0 0 0 0						

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are

- 1 Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3 Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5 Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR)
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility, not covered by an IE Bulletin.
- 17. Reports of site visits
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- 3 Transmittal and acknowledgement letters
- 4 Certificates of service to the PSAR

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R

- 1. Environmental Report (ER) submitted by the utility
- 2 Amendments and supplements to the ER
- 3 Transmittal and acknowledgement letters
- 4 Information on scheduling of submittal or review of ER
- 5 NRC questions, requests for additional information, and applicant responses.
- 6 Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER
- 8 Meeting announcements or reports of meetings where the primary subject of discussion is the ER

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R

- I Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2 Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4 Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters
- Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9 Site visits to obtain information for DES or FES
- 10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report)
- 2 Supplements to SER
- 3 Correspondence relating to SER
- 4 Federal register notices citing availability of items 1 and 2
- 5 Information on scheduling of SER submittals and review
- 6 Requests for additional information for use in preparing SER, responses to such requests
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8 Transmittal and acknowledgement letters

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded

- 1. Fire Hazard Protection Plan and surveys.
- 2 Plant evacuation correspondence.
- 3 Safeguards Contingency Plans
- 4 Review of Health Physics Program.
- 5 Correspondence relating to aforementioned plans
- 6 Supplements, changes and revisions to plans,

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3 Requests to make appearances at hearings
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5 Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors
- 7 Board orders and decisions.
- 8 Petitions for Commission action.
- 9 Legal filings and Commission orders and decisions resulting from item 8.

H GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license frems that have no substantive technical content or meaning for the status of the license or application are included

- 1 Change of address notifications
- 2. Changes in structure of organization
- 3 Changes in service lists.
- 4 NRC requests to applicant for additional copies of documents.
- 5 Correspondence from the public requesting information about the facility and NRC responses.
- 6 Correspondence on strictly administrative matters.
- 7 Letters of support, concern or opposition to the facility
- 8 Correspondence regarding the Local Public Document Rooms (LPDRs)
- 9 Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties

- 1 Company annual reports
- 2 Separately submitted financial information and related correspondence

J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments
- 2 Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P

- 1 Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report)
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit

- Limited Work Authorizations (LWA) and amendments
- 2 Correspondence pertaining to work performed under LWA's

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review"
- 2 Correspondence where the primary topic of discussion is antitrust matters
- 3 All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS
- 3 Announcement of ACRS meetings
- 4 Transmittal and acknowledgement letters.
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence
- Technical specifications and changes.

- 3 Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2
- 5 Correspondence regarding the Final Safety Analysis Report (FSAR)
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license
- 7 Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license
- 8. Information on the Standard Review Plan (STP)
- 9 Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP)
- 11. Owner's group meeting announcements and reports.
- 12 Quality assurance information.
- 13 Environmental matters (technical).
- 14. Emergency core cooling system documents
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1 Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7 Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (ENs)
- 8 Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature

- Monthly, semiannual, or annual operating reports (other than financial)
- 2 Periodic environmental monitoring, effluent testing, or similar reports
- 3 Periodic personnel exposure reports.
- 4 Operational Logbooks

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets

5 Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNOs. PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes

- All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences)
- 2 Potential or possible reportable deficiency reports and related correspondence
- 3 Personnel exposure reports.
- 4 Construction deficiency reports submitted under 10 CFR 50.55e
- 5 Preliminary Notification of Occurrence (PNOs) and Preliminary Notification of Safeguards Events (PNs)
- 6. Environmental Technical Specifications violation reports and Environmental Event reports
- 7 Part 21 Reports of defects and noncompliance
- 8. Correspondence or other documents relating to items 1-7

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts
- 2. Testimony and statements submitted to ASLB and ASLAB
- 3 Commission meeting transcripts.
- 4. NRC staff briefings to the Commission
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6 Transcripts of utility briefs to NRC staff.
- 7 Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts
- 8. Corrections to above items

U CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category. H

- Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches
- 2 Preparatory and backup documents for item I
- 3 Correspondence to and from NRC Office of Congressional Affairs Congress and the Executive Branch on other than constituent response matters

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1 Operator licenses or administrative information bearing on licensing of operators
- 2. NRC examination results
- 3. Power plant examination summary sheet

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward

- 1. Application for authority to voluntarily surrender license
- 2. Application to dismantle the facility and dispose of component parts.
- Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan Dismantling Plan, Environmental Report on Dismantling Safety Analysis Report on Decommissioning
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items
- 6 All documentation relating to the ongoing operation of the plan, formerly filed in category P.

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

- 1. License applications, licenses, amendments and proposed amendments to possess power reactor spent fuel and other radioactive materials associated with spent storage in an independent spent fuel storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate site.)
- 2. All related correspondence and reports to the above.

APPENDIX R

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It melides

- 1 Sunshine Act Federal Register notices
- 2 Full written explanation of closed meetings
- 3. Certification of General Counsel on closed meetings
- 4 Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings
- 5 Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of IOCFR Part 9 the Sunshine Act, and Commission policies.
- Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence
- Staff requirements memoranda for open meetings, memoranda to record, record of votes of Commissioners on items under consideration at meetings

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation perfaming to the responsibilities of the Advisory Committee on Reactor Saleguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and sufety-related matters
- 2. ACRS meeting announcements description of meeting agendas.
- 3 ACRS-generated reports, memoranda and correspondence that are publicly available
- 4. ACRS consultant reports, comments and related correspondence
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

ADVCM - NRC Advisory Committees

This category contains documentation pertaining to the responsibilities of all NRC advisory committees, other than the Advisory Committee on Reactor Safeguards. The documents in this category are:

- 1. Charters of each advisory committee.
- 2. Verbatim transcripts of committee meetings.

- 3. Meeting announcements; description of meeting agendas.
- 4. Committee generated reports, memoranda, and correspondence that are publicly available.
- 5. Committee related correspondence.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including

- 1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTI: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to ALC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB)
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any,

DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation

- Dealt reports of action plans to accomplish generic tasks in the regulatory program.
- 2 Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues
- 3 Meeting notifications and minutes.
- Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 18.1 Circulars, which describe an event at a licensed facility and are informational in nature.
- 2 I&I Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3 I&I Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event
- 4 Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance
- NOTE I or letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories

MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other non-docketed categories

NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NURLG series code and correspondence pertaining to those reports. NURLG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- These reports are normally final work products and are characterized by the following criteria
 - a They are predecisional documents which present information to be considered in Commission licensing and policy decisions
 - b. They present the results of Commission heensing and policy decisions
 - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3 Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports

ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations, records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development, and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are

- 1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility, e.g., EPA has authority to control all radioactive pollutants emitted into the air
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 3 Correspondence between NRC and the petitioner regarding the status and substance of the petition
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities, and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

I. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
 - 1. Application submitted by the utility.
 - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
 - 3. Applicant's Quality Assurance Manual.
 - 4. Early site review information.
 - 5. Backup technical documents submitted in support of the application.
 - 6. Early site visits.
- B. Utility PSAR and Amendments
 - 1. PSARs submitted by the utility.
 - 2. Amendments and changes to the PSAR.
 - 3. Transmittal letters.
 - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
 - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M Antitrust Correspondence
 - 1. Submittals and related material pertaining to the antitrust review.

O. Inspection Reports

- 1 Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include.

- 1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5 Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports: for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- 3 Pre-test prediction reports.
- 4, "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are

- 1 Agendas for quarterly review group meetings.
- 2 Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3 Research plans and predicted results of major experiments; presentations by research contractors
- 4 Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG - State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include. (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials, (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies, and (3) a wide range of haison and cooperative activities regarding such functions as licensing and siting. It includes

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State haison officers, regarding.
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas
- Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations, i.e. decommissioning and facility siting
- 3. State Legislative Reports.
- 4 Agreement State Licensing Statistics Reports

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria

NOTE For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

- 3 Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are

- License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6 Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8 Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 U.S NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET		NUREG-054					
4 TITLE AND SUBTITLE (Add Volume No , if appropriate)		2 (Leave blank)					
Title List of Documents Made Publicly Availab March 1-31, 1984	3 RECIPIENT'S ACCESSION NO						
7 AUTHOR(S)		5 DATE REPORT	COMPLETED				
		MONTH	YEAR				
9 PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include	le Zip Code)	DATE REPORT	ISSUED				
Division of Technical Information and Documen	it Control	MONTH YEAR 1984					
Office of Administration U.S. Nuclear Regulatory Commission		6 (Leave blank)	1301				
Washington, DC 20555		8 (Leave blank)					
12 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include	le Zip Code)						
Same as 9, above.	•	10 PROJECT/TASK/WORK UNIT NO					
June as 3, above.		11 FIN NO					
		}					
13 TYPE OF REPORT	PERIOD COVERE	D (Inclusive dates)					
Monthly	March 1.	-31, 1984					
15 SUPPLEMENTARY NOTES		14 (Leave blank)					
16 ABSTRACT (200 words or less)							
received and generated by the U.S. NRC. This material associated with civilian nuclear power active materials, and (2) nondocketed material pertinent to its role as a regulatory agency. Personal Author Index, Corporate Source Index, Reference to Principal Documents Index.	er plants and I received ar The followi	l other uses nd generated ng indexes a	of radio- by NRC re included:				
7 KEY WORDS AND DOCUMENT ANALYSIS	174 DESCRIPTORS						
7th IDENTIFIERS. OPEN ENDED TERMS							
8 AVAILABILITY STATEMENT		CLASS (Tois report)	21 NO OF PAGES				
Unlimited	Unclas 20 SECURITY	Sified LLASS (Tyus payur	22 PRICE				
CHELLIDE LLCCL	1 11 11						